DRAKESBORO WORK	ORDER	Work Order #:
DATE: Gas Water	WW _ Acct#:	
NAME:	Meter Nun	nber:
ADDRESS: <u>2258</u> US 4	Awy 43	31
WORK TO BE DONE:	,	
NEW METER#	NEW READING	
TURN ON & READ	OLD READING	
READ and LOCK		
		(SEE BELOW)
READ and LOCK (NON PAYMENT)		
CHECK PRESSURE		
UNLOCK ONLY and READ (DO NOT TURN (	ON)	-
special instructions:  Light pilot Lia	ht on	hot water
neater.		
WORK DONE:		
FLUSHED: Yes No GPM:	How Long:	Water Loss:
WATER LEAK: Yes No GPM:	How Long:	Water Loss:
PARTS USED TO COMPLETE JOB:		:
	****	
	****	
COMMENTS: LitC Pilte, lig	6+	
WORK COMPLETED THE TAIL	· · · · · · · · · · · · · · · · · · ·	A
WORK COMPLETED BY: 3.860~		COMPLETED: 9-4-19
- 11100 C 1 747 ( LV.	_ TIME FINISHED	

DRAKESBORO WORK	ORDER	Work Order #:
DATE: Time: Gas Water	WW _ Acct#:	
	Meter Number	T:
ADDRESS: 1741 SR 70 -		
WORK TO BE DONE:	6	
NEW METER#	NEW READING	
TURN ON & READ)	OLD READING	
	SET METER and LO	OCK
100	LOCATE LINE	
	GET METER NUMB	
	FLUSH LINE	
WORK DONE:		
	How Long:	Water Loss
WATER LEAK: Yes No GPM:	How Long:	Water Loss:
COMMENTS: Almay on	Customer of	
nto owner's na		
NORK COMPLETED BY: 5500	PATE AS	MPLETED: 9-3-19
TOTAL SOME LES DI	DATE CO	MPLEIED: /-/ /7

2 - 4	DRAKESBORO WO	KK UKUEK	work Order #:
DATE: 19	Time: Gas Wate	er WW . Acct#: 2.(	7-29100-2
ADDRESS:	116 Beechmo	nt Drive	er.
•			
	O BE DONE:		
NEW METE	R#	NEW READING _	
TURN ON 8	READ 8192	OLD READING	
READ and	LOCK	SET METER and L	OCK
READING (	ONLY	LOCATE LINE	(SEE BELOW)
READ and	LOCK (NON PAYMENT)	GET METER NUM	BER
CHECK PR	RESSURE	FLUSH LINE	CHECK f. LEAK
	NLY and READ (DO NOT TU		
SPECIAL II	NSTRUCTIONS:		
turn	on oas n	notee and	read please "
WORK D	ONE:	• • • • • • • • • • • • • • • • • • •	
FLUSHE	ED: Yes No GPM:	How Long:	Water Loss:
WATER LE	AK: Yes No GPM:	How Long:	Water Loss:
	ISED TO COMPLETE JO	; '	:
PARISO	SED TO COMPLETE SC	<b></b>	
	/		
•	· · · · · · · · · · · · · · · · · · ·		
	20-		
COMMENT	<u>S:</u>		
	<del></del>		
WORK OO	MPLETED BY: Jishon	W	COMPLETED: 9-3-18
TIME STAF		TIME FINISHED	
	\ I tob' /	inte limbuel	7.

DRAKESBORO WO	RK ORDER	Work Order #:
1 3 1 1	iter WW _ Acct #:	
NAME: Naomi Chumley	Meter Number	er:
ADDRESS: 55 Hwy 7	Ď	
WORK TO BE DONE:	w .	
NEW METER#	NEW READING _	
TURN ON & READ 1835	OLD READING	
READ and LOCK	SET METER and L	OCK
READING ONLY	LOCATE LINE	(SEE BELOW)
READ and LOCK (NON PAYMENT)	GET METER NUMI	BER
CHECK PRESSURE	FLUSH LINE	CHECK f. LEAK
UNLOCK ONLY and READ (DO NOT T	URN ON)	
SPECIAL INSTRUCTIONS:		
turn on gas m	eter and o	set roading:
please.		0
WORK DONE:	• • • • • • • • • • • • • • • • • • •	
FLUSHED: Yes No GPM:	How Long:	Water Loss:
WATER LEAK: Yes No GPM:	How Long:	Water Loss:
PARTS USED TO COMPLETE JO	OR:	<b>:</b>
		·
,		· · · · · · · · · · · · · · · · · · ·
		:
CÓMMENTS:		
	<u> </u>	
·		
WORK COMPLETED BY: 5.540	DATE C	OMPLETED: 9-3-19
TIME STARTED: 8/98	TIME FINISHED	

DRAKESBORO WORK	RDER	Work Order #:
DATE: Time: Gas Water	WW _ Acct #:	10-9390-8
NAME: James MARA	Meter Nu	ımber:
NAME: Jamy Wind ADDRESS: 2258 DS Huy 431, Be	echmint Ku	
WORK TO BE DONE:		
	NEW READING	3
TURN ON & READ		
	SET METER a	
. 4180	<b></b>	(SEE BELOW)
	GET METER N	
CHECK PRESSURE	- _ FLUSH LINE _	CHECK f. LEAK
UNLOCK ONLY and READ (DO NOT TURN (	ON)	
SPECIAL INSTRUCTIONS:		
Service up- needs read	ing chly	
WORK DONE:		
FLUSHED: Yes No GPM: WATER LEAK: Yes No GPM:		
WATER LEAR TES NO GPIN	How Long: _	Water Loss:
PARTS USED TO COMPLETE JOB:	*******	
COMMENTS:	- 10 to 10 t	
	· · · · · · · · · · · · · · · · · · ·	
	<del></del>	
WORK COMPLETED BY: J'Show	DAT	TE COMPLETED: 9-3-/9
TIME STARTED:	TIME FINISH	

DRAKESBORO WORK	ORDER Work Order #:
DATE: Time: Gas Water	WW _ Acct #: 10 - 00500 - 1
NAME: Chris Mefford	Meter Number:
ADDRESS: 471 Hursesve Lunp	Beltin 164
,	270-725-6693
WORK TO BE DONE:	
NEW METER#	NEW READING
TURN ON & READ (338	OLD READING
READ and LOCK	SET METER and LOCK
READING ONLY	LOCATE LINE (SEE BELOW)
READ and LOCK (NON PAYMENT)	GET METER NUMBER
CHECK PRESSURE	FLUSH LINE CHECK f. LEAK
UNLOCK ONLY and READ (DO NOT TURN	ON)
SPECIAL INSTRUCTIONS:	
- reconnect service po	<u>)                                    </u>
WORK DONE:	•
	How Long: Water Loss:
WATER LEAK: Yes No GPM:	How Long: Water Loss:
PARTS USED TO COMPLETE JOB:	
	•
COMMENTS: Went to the or	Sidence, Knocked on every door.
No arriver will to	stdence, Knocked on every door.
	' '
WORK COMPLETED BY: A Shari	DATE COMPLETED:

TIME FINISHED:

TIME STARTED:

DRAKESBORO WORK	ORDER	Work Order #:	
DATE: Time: Gas Water	WW _ Acct #:		
NAME: ERIC NEWMAN	Meter Nu	mber:	
ADDRESS: Love Masonic Dr.	Becchmint K	4 42323	
WORK TO BE DONE:	•		
NEW METER#	NEW READING		<del></del>
TURN ON & READ 6462	OLD READING		
READ and LOCK	SET METER an	d LOCK	
READING ONLY	LOCATE LINE	(SEE BELOW)	
READ and LOCK (NON PAYMENT)	GET METER NU	JMBER	
CHECK PRESSURE	FLUSH LINE _	CHECK f. L	EAK
UNLOCK ONLY and READ (DO NOT TUR!	N ON)		
SPECIAL INSTRUCTIONS:			
New Service			•
<b>V</b>			
			<del></del>
WORK DONE:			
	How Long:	Water Loss:	
WATER LEAK: Yes No GPM:			
	:		•
PARTS USED TO COMPLETE JOB:		·	<del></del>
			<del> </del>
COMMENTS: Trined on ga	s. Belite	hot water	
neater pilot.			
,		·	
., , , ,	· · · · · · · · · · · · · · · · · · ·		
WORK COMPLETED BY:	DAT	E COMPLETED:	30-19

TIME FINISHED:

TIME STARTED:

	•	
DRAKESBORO WOR	RK ORDER	Work Order #:
DATE: Time: Gas Wate	er WW _ Acct#: _	
NAME: Anna Groves	Meter Nu	umber:
ADDRESS: 500 Leslie		
WORK TO BE DONE:	•	
NEW METER#	NEW READING	3
TURN ON & READ	OLD READING	
READ and LOCK	SET METER a	nd LOCK
READING ONLY	LOCATE LINE	(SEE BELOW)
READ and LOCK (NON PAYMENT)	GET METER N	IUMBER
CHECK PRESSURE	FLUSH LINE	CHECK f. LEAK
UNLOCK ONLY and READ (DO NOT TU	IRN ON)	
SPECIAL INSTRUCTIONS:		
look at pipelines t	to see if	She can hook - up
natural gas:		
WORK DONE:		
FLUSHED: Yes No GPM:	How Long:	Water Loss:
WATER LEAK: Yes No GPM:	How Long:	Water Loss:
PARTS USED TO COMPLETE JO	) <u>B:</u>	
,		
COMMENTS: Meter Set	- already a	t her house.

DATE COMPLETED: 8-29-19 WORK COMPLETED BY:

TIME STARTED:

TIME FINISHED:

## DRAKESBORO WORK ORDER Work Order #: Time: (Gas) Water WW - Acct #: 40 - 51250 - 2 NAME: Umarda Mitaheli Meter Number: ADDRESS: 3 Dle Kenned & Jones (Jue (270) 820 - 7610 WORK TO BE DONE: NEW METER # \_\_\_\_\_ NEW READING \_\_\_\_\_ OLD READING TURN ON & READ \_\_\_\_\_ READ and LOCK SET METER and LOCK LOCATE LINE (SEE BELOW) READING ONLY READ and LOCK (NON PAYMENT) GET METER NUMBER CHECK PRESSURE \_\_\_\_\_ FLUSH LINE \_\_\_ CHECK f. LEAK \_\_\_ UNLOCK ONLY and READ (DO NOT TURN ON) SPECIAL INSTRUCTIONS: Gastine not working? Jordan told her it may be clogged & needs brow out ofter work completed lost winter. **WORK DONE:** FLUSHED: Yes No GPM: How Long: Water Loss: WATER LEAK: Yes No GPM: How Long: Water Loss: PARTS USED TO COMPLETE JOB: COMMENTS: Went to resident's had her turn her Purnace on. Furnace had gas and was heating inred on values to fire place, No gas to fire place. Told her to co

WORK COMPLETED BY:

TIME STARTED:

DATE COMPLETED: 8-29-39

TIME FINISHED:

DRAKESBORO WO	IRK ORDE	<b>*</b>	work Order #.
DATE: Gas Wa	iter WW .	Acct #:	
NAME: Carter	••	Meter Number	
NAME: Carter ADDRESS: 82 Weste	r Dr	· · · · · · · · · · · · · · · · · · ·	
WORK TO BE DONE:			
NEW METER#	NEW	READING	
TURN ON & READ			
READ and LOCK	SET	METER and LC	OCK
READING ONLY	LOC	ATE LINE	(SEE BELOW)
READ and LOCK (NON PAYMENT)			
CHECK PRESSURE			
UNLOCK ONLY and READ (DO NOT )			
SPECIAL INSTRUCTIONS:		<b>.</b>	
Reread Jubel	- 388	34	·
Aug			
7	2,990		
WORK DONE:		1	
FLUSHED: Yes No GPM	: Hc	ow Long:	Water Loss:
WATER LEAK: Yes No GPM			
· · · · · · · · · · · · · · · · · · ·			:
PARTS USED TO COMPLETE J	<u>IOB:</u>		
	<del></del>	· · · · · · · · · · · · · · · · · · ·	
	· · · · · · · · · · · · · · · · · · ·		
			0-
COMMENTS: Found hot u	rater neev	ter pap of	of ctive gone bad.
Constantly release			ting, Constantly
Pulling gas. Cus	stomer C	hanged i	op off valle, fixed
Situation.	······································		
WORK COMPLETED BY: Dee S	M5	DATE C	OMPLETED: 8-26-19
TIME STARTED:	· <del>-</del>	IME FINISHED	

Time: Gas Water  ME: Hope 2 all  DRESS: Block Build  DRK TO BE DONE:	Meter Number:
ME: Hope 2 all  DRESS: Block Build	Meter Number:
DRESS: Block Buil	410 00 K
ORK TO BE DONE:	
W METER#	NEW READING
	OLD READING
	SET METER and LOCK
ADING ONLY 3/	_ LOCATE LINE (SEE BELOW)
	GET METER NUMBER
IECK PRESSURE	
ORK DONE:	3
	How Long: Water Loss:
ATER LEAK: Yes No GPM:	
,	:
ARTS USED TO COMPLETE JOB:	
'	
-	
-	
OMMENTS:	
OMMENTS:	
DMMENTS:	