

Preliminary observations

- Low gas pressure that reduced output of Trimble County gas turbines was a historic first since units began operations in 2002
- Low gas pressure that reduced output of Cane Run combined cycle gas was a historic first since unit began operations in 2015
- The Companies are working with Texas Gas Transmission to address event and reduce risk of future occurrence
- Companies are reviewing their own winter operating procedures to reduce risk of equipment failure