

Golden Acres Subd.

AI: 2935

KY0044164

by York, Jessie (EEC)

2/11/20



Influent bar screen



Solids have overflowed
out of the plant.



Plant regularly overflows with heavy rain.

High water line



High water
line



Solids outside
plant



High water
line



Aeration chamber.
Good mixing. Low
MLSS concentration.



Sludge return has low
MLSS concentration.



Aeration chamber



Clarifier



Chlorine tablets



Contact chamber



Solids on the ground



High water
line



Solids on the ground around the plant.



New motor for aeration pump.



Outfall 001 appears clear.



Downstream of
outfall 001



Outfall 001



Downstream of outfall 001