

Year	Pole Number	Owner	Class	Height	Manufacturer	Species	OriginalTreatment	DecayCode	Inspection Code	Rejection Code	Date Inspected
2020	PO7226985929	KU		5	35 BRO	SP	CRE	ED,ID	BD		1/14/2020
2020	PO4706098550	KU		6	30 INP	SP	CCA		V		1/15/2020
2020	PO4627602852	KU		6	30 OTH	SP	CRE	ED,ID	BD		1/16/2020
2020	PO4694098366	KU		4	45 BRN	SP	CCA		V		1/17/2020
2020	PO4739399271	KU		5	30 OTH	SP	CCA		V		1/18/2020
2020	PO4737699207	KU		4	45 BRN	SP	CCA		V		1/19/2020
2020	PO4714199938	KU		5	30 BRN	SP	CRE		V		1/20/2020
2020	PO4703199837	KU		6	30 BRN	SP	CCA		V		1/21/2020
2020	PO4703499909	KU		6	30 BRN	SP	CCA		V		1/22/2020
2020	PO4678200567A	KU		4	40 BRN	SP	CCA		V		1/23/2020
2020	PO4678200567	KU		3	50 BRN	SP	CCA		V		1/24/2020
2020	PO4673400670	KU		5	35 BRN	SP	CCA		V		1/25/2020
2020	PO4662300514	KU		4	40 KOP	SP	CCA		V		1/26/2020
2020	PO4605001349	KU		6	30 KOP	SP	CCA		V		1/27/2020
2020	PO4654602170	KU		4	40 BRN	SP	CCA		V		1/28/2020
2020	PO4673502375	KU		3	50 BRN	SP	CCA		V		1/29/2020
2020	PO4598101826	KU		3	45 BRN	SP	CCA		V		1/30/2020
2020	PO4582401444	KU		6	30 KOP	SP	CRE		V		1/31/2020
2020	PO4579001336	KU		6	30 BRN	SP	CCA		V		2/1/2020
2020	PO4585001864	KU		4	40 BRN	SP	CCA		V		2/2/2020
2020	PO4578202068	KU		3	45 BRN	SP	CCA		V		2/3/2020
2020	PO4497102110	KU		4	45 BRN	SP	CCA		V		2/4/2020
2020	PO4510402153	KU		4	45 BRN	SP	CCA		V		2/5/2020
2020	PO4517302139	KU		4	45 BRN	SP	CCA		V		2/6/2020
2020	PO4580802471	KU		6	30 KOP	SP	CCA		V		2/7/2020
2020	PO4586002912	KU		3	45 BRN	SP	CCA		V		2/8/2020
2020	PO4593803220A	KU		6	30 BRN	SP	CCA		V		2/9/2020
2020	PO4202002507	KU		4	45 BRN	SP	CCA		V		2/10/2020
2020	PO4223202496	KU		4	45 BRN	SP	CCA		V		2/11/2020
2020	PO4208502705	KU		4	45 BRN	SP	CCA		V		2/12/2020
2020	PO4193902914	KU		4	45 BRN	SP	CCA		V		2/13/2020
2020	PO4179603229	KU		4	45 BRN	SP	CCA		V		2/14/2020
2020	PO4176703160	KU		4	45 BRN	SP	CCA		V		2/15/2020
2020	PO4155603216	KU		6	30 BRN	SP	CCA		V		2/16/2020
2020	PO4201902981	KU		4	40 BRN	SP	CCA		V		2/17/2020
2020	PO3762704720	KU		2	50 BRN	SP	CCA		V		2/18/2020
2020	PO8417965953	KU		4	40 BRO	SP	CRE	ED,ID	TD		2/19/2020
2020	PO2921803590	KU		5	35 BRO	SP	CCA		V		2/20/2020
2020	PO3180403544	KU		4	40 BRO	SP	CRE	ID	BD		2/21/2020
2020	PO8513866809	KU		3	45 BRO	SP	CCA		V		2/22/2020
2020	PO8499666647	KU		3	45 BRO	SP	CCA		V		2/23/2020
2020	PO8470266228	KU		3	45 BRO	SP	CCA		V		2/24/2020
2020	PO8460766037	KU		3	45 BRO	SP	CCA		V		2/25/2020
2020	PO3841904137	KU		4	40 XXX	SP	CRE	ED,ID	TD		2/26/2020
2020	PO3854304048	KU		3	40 XXX	SP	CRE	ED,ID	TD		2/27/2020
2020	PO3862903987	KU		4	40 XXX	SP	CCA		V		2/28/2020

2020 PO3852403933	KU	3	40 XXX	SP	P	ID	BD	2/29/2020
2020 PO3850703991	KU	6	30 XXX	SP	CRE	ED,ID	TD	3/1/2020
2020 PO3843603934	KU	6	30 XXX	SP	CRE		B	3/2/2020
2020 PO3832104214	KU	4	45 XXX	SP	CRE	ED,ID	TD	3/3/2020
2020 PO3829704130	KU	5	35 XXX	SP	CRE	ED,ID	TD	3/4/2020
2020 PO6836481988	KU	6	35 BRN	SP	CRE		V	3/5/2020
2020 PO6825481687	KU	4	40 BRN	SP	CRE		V	3/6/2020
2020 PO3618104524	KU	4	40 BRO	SP	CRE	ID	TD	3/7/2020
2020 PO6862682130	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	3/8/2020
2020 PO6844082197	KU	5	20E BRN	SP	CRE	ED,ID,IP	BD	3/9/2020
2020 PO6831882445	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	3/10/2020
2020 PO7211486684	KU	5	35 BRO	SP	CRE	ED,ID	TD	3/11/2020
2020 PO7203686535	KU	4	40 BRO	SP	CRE	ED,ID	BD	3/12/2020
2020 PO7173386369	KU	6	30 BRO	SP	CRE		V	3/13/2020
2020 PO7642672743	KU	4	40 BRO	SP	CRE	ED,ID	BD	3/14/2020
2020 PO7180386476	KU	5	35 BRO	SP	CRE	ED,ID	TD	3/15/2020
2020 PO7185786425	KU	4	40 BRO	SP	S		V	3/16/2020
2020 PO7189986380	KU	6	30 BRO	SP	CRE	ED,ID	TD	3/17/2020
2020 PO7209486318	KU	6	30 BRO	SP	CRE	ED,ID	TD	3/18/2020
2020 PO7253186397	KU	3	50 BRO	SP	CCA		V	3/19/2020
2020 PO7627372805	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/20/2020
2020 PO7631373066	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/21/2020
2020 PO6849682361	KU	3	45 BRN	SP	CCA		V	3/22/2020
2020 PO6850482380	KU	3	45 BRN	SP	CCA		V	3/23/2020
2020 PO7624372900	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/24/2020
2020 PO3816704335	KU	5	35 XXX	SP	CRE	ED,ID	TD	3/25/2020
2020 PO3813404284	KU	5	35 XXX	SP	CCA		V	3/26/2020
2020 PO3810204187	KU	4	40 XXX	SP	CCA		V	3/27/2020
2020 PO7216585845	KU	6	30 BRO	SP	CRE	ED,ID	BD	3/28/2020
2020 PO7208985917	KU	4	45 BRO	SP	CRE	ED,ID	BD	3/29/2020
2020 PO7196485693	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/30/2020
2020 PO7188385523	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/31/2020
2020 PO7188285027	KU	5	35 BRO	SP	CRE	ED,ID	BD	4/1/2020
2020 PO3840104356	KU	4	40 XXX	SP	CRE	ED,ID	TD	4/2/2020
2020 PO3840004285	KU	6	30 XXX	SP	CRE	ED,ID	TD	4/3/2020
2020 PO3865304248	KU	4	35 XXX	SP	P	ED,ID	TD	4/4/2020
2020 PO3859604277	KU	4	35 XXX	SP	P	ED,ID	TD	4/5/2020
2020 PO7638273232	KU	4	40 BRO	SP	CRE	ED,ID	TD	4/6/2020
2020 PO7601272936	KU	4	45 BRO	SP	CRE	ED,ID	TD	4/7/2020
2020 PO3642604517	KU	4	40 BRO	SP	CRE	ID	TD	4/8/2020
2020 PO3662104505	KU	4	45 BRO	SP	CRE	ID	TD	4/9/2020
2020 PO3612105066	KU	4	40 BRO	SP	CRE	ID	TD	4/10/2020
2020 PO7235686384	KU	2	50 BRO	SP	CRE		V	4/11/2020
2020 PO7200286268	KU	4	40 BRO	SP	CRE	ED,ID	TD	4/12/2020
2020 PO7207286292	KU	5	35 BRO	SP	CRE	ED,ID	TD	4/13/2020
2020 PO7218286355	KU	4	45 BRO	SP	CCA	ID	B	4/14/2020
2020 PO6959082412	KU	1	70 BRN	SP	CCA		V	4/15/2020

2020 PO6941282479	KU	2	70 BRN	SP	CRE		V			4/16/2020
2020 PO6920382533	KU	1	70 BRN	SP	CRE		V			4/17/2020
2020 PO6887482641	KU	1	70 BRN	SP	CRE		V			4/18/2020
2020 PO6863382732	KU	1	70 BRN	SP	CRE		V			4/19/2020
2020 PO6736583246-A	KU	2	60 BRN	SP	CRE		V			4/20/2020
2020 PO6737183265	KU	1	70 BRN	SP	CRE		V			4/21/2020
2020 PO6736583246	KU	1	70 BRN	SP	CRE		V			4/22/2020
2020 PO6707783400	KU	1	70 BRN	SP	P		V			4/23/2020
2020 PO6679483538	KU	2	70 BRN	SP	CRE		V			4/24/2020
2020 PO3544904589	KU	4	45 BRO	SP	CRE	ID		TD		4/25/2020
2020 PO3528804507	KU	5	45 BRO	SP	CRE	ID		TD		4/26/2020
2020 PO3530904600	KU	4	40 BRO	SP	CRE	ID		TD		4/27/2020
2020 PO3516404795	KU	4	40 BRO	SP	CRE	ID		TD		4/28/2020
2020 PO3390903566	KU	4	40 BRO	SP	CRE	ID		BD		4/29/2020
2020 PO3417503361	KU	4	40 BRO	SP	CRE	ID		BD		4/30/2020
2020 PO3418603587	KU	5	35 BRO	SP	CRE	ID		TD		5/1/2020
2020 PO3418603758	KU	4	40 BRO	SP	CRE	ID		TD		5/2/2020
2020 PO3428303768	KU	6	30 BRO	SP	CRE	ID		TD		5/3/2020
2020 PO3450404623	KU	4	40 BRO	SP	CRE	ID		TD		5/4/2020
2020 PO3460004406	KU	4	40 BRO	SP	CRE	ID		TD		5/5/2020
2020 PO2614766383	KU	5	35 BRO	SP	CRE	ED,ID		TX	RR	5/6/2020
2020 PO2590766428	KU	5	35 BRO	SP	CRE	ED,HH		TX	RR	5/7/2020
2020 PO2565566467	KU	6	35 BRO	SP	CRE	ED,ID		TD		5/8/2020
2020 PO2537866511	KU	6	35 BRO	SP	CRE			V		5/9/2020
2020 PO2515366546	KU	6	35 BRO	SP	CRE	ED,HH		X	RP2	5/10/2020
2020 PO2502366571	KU	4	40 BRO	SP	CRE	ID		BD		5/11/2020
2020 PO2483966594	KU	4	40 BRO	SP	CCA			V		5/12/2020
2020 PO2480266839	KU	5	35 BRO	SP	CRE	EP,IP		TD		5/13/2020
2020 PO2479367033	KU	5	35 BRO	SP	P	ED		TD		5/14/2020
2020 PO2466866905	F	7 25E	BRO	SP	CRE			V		5/15/2020
2020 PO2469167192	KU	6	30 BRO	SP	CCA			V		5/16/2020
2020 PO2937068087	F	4	40 BRO	SP	P			V		5/17/2020
2020 PO2951468482	F	4	40 BRO	SP	CCA			V		5/18/2020
2020 PO2901867752	F	3 45E	BRO	SP	P			V		5/19/2020
2020 PO2855967540	F	4	40 BRO	SP	P			V		5/20/2020
2020 PO2853067534	F	2	50 BRO	SP	P			V		5/21/2020
2020 PO2837767487	F	2	50 BRO	SP	P			V		5/22/2020
2020 PO2818267404	F	2	50 BRO	SP	P			V		5/23/2020
2020 PO8640989587	KU	5	35 ACE	SP	CRE	ED,EP,HH,ID,IP,RB		BX	RP1	5/24/2020
2020 PO2793167222	F	2	50 BRO	SP	P			V		5/25/2020
2020 PO2784867150	F	2	50 BRO	SP	P			V		5/26/2020
2020 PO2775567062	F	2	50 BRO	SP	P			V		5/27/2020
2020 PO2767866959	F	2	50 BRO	SP	P			V		5/28/2020
2020 PO2761366846	F	2	50 BRO	SP	P			V		5/29/2020
2020 PO2755066694	F	2	50 BRO	SP	P			V		5/30/2020
2020 PO8879591761	F	4	40 ACE	SP	CRE			V		5/31/2020
2020 PO8868291703	KU	4	40 ACE	SP	CRE			V		6/1/2020

2020 PO8886491359	KU	4	40 ACE	SP	CRE	ED,ID	TD		6/2/2020
2020 PO8875291281	KU	4	40 ACE	SP	CRE	ED,ID	BD		6/3/2020
2020 PO8818589452	KU	4	40 ACE	SP	CRE	ED,ID	TD		6/4/2020
2020 PO8756189618	KU	5	35 ACE	SP	CRE	ED,EP,ID,IP	TX	RR	6/5/2020
2020 PO8718289645	KU	5	35 ACE	SP	CRE	ED,EP,ID,IP	TD		6/6/2020
2020 PO8698289745	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		6/7/2020
2020 PO8668689489	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		6/8/2020
2020 PO8643289377	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		6/9/2020
2020 PO8624882717	F	4	40 BRO	SP	CRE		V		6/10/2020
2020 PO8634182630	KU	6	30 BRO	SP	CCA		V		6/11/2020
2020 PO8576981226	KU	4	45 BRO	SP	CCA		V		6/12/2020
2020 PO8575581051	KU	4	45 BRO	SP	CCA		V		6/13/2020
2020 PO8580981466	KU	4	45 BRO	SP	CCA		V		6/14/2020
2020 PO8578881338	KU	4	45 BRO	SP	CCA		V		6/15/2020
2020 PO8437177693	KU	3	45 BRO	SP	CRE	ED,ID	TD		6/16/2020
2020 PO8473477858	F	4	40 BRO	SP	CRE		V		6/17/2020
2020 PO8473177773	F	4	40 BRO	SP	CRE		V		6/18/2020
2020 PO8658982602	KU	6	30 BRO	SP	CRE	ED,ID,SRS	TD		6/19/2020
2020 PO8657282361	KU	6	30 BRO	SP	CRE	ED,ID,SR	TD		6/20/2020
2020 PO8657182160	KU	6	30 BRO	SP	CRE	ED,ID,SRS	TD		6/21/2020
2020 PO8653089362	KU	6	30 ACE	SP	CCA		V		6/22/2020
2020 PO8612788278	KU	5	35 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	RP1	6/23/2020
2020 PO8799087572	KU	4	45 ACE	SP	CCA		V		6/24/2020
2020 PO8813685607	KU	4	45 ACE	SP	CRE		V		6/25/2020
2020 PO8841985808	F	4	40 ACE	SP	CRE		V		6/26/2020
2020 PO8824585867	KU	4	40 ACE	SP	CRE	ED,ID	BD		6/27/2020
2020 PO8842386513	KU	4	40 ACE	SP	CCA		V		6/28/2020
2020 PO8849486807	KU	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	X	RP1	6/29/2020
2020 PO8853586909	KU	3	50 ACE	SP	CCA		V		6/30/2020
2020 PO8870587056	KU	3	45 ACE	SP	CCA		V		7/1/2020
2020 PO8774186206	KU	4	40 ACE	SP	CCA		V		7/2/2020
2020 PO8765186290	KU	6	30 ACE	SP	CCA		V		7/3/2020
2020 PO8789086319	KU	4	40 ACE	SP	CCA		V		7/4/2020
2020 PO8813786521	KU	4	40 ACE	SP	CCA		V		7/5/2020
2020 PO8774887947	KU	6	30 ACE	SP	CRE	ED,ID	TD		7/6/2020
2020 PO8735688237	KU	4	40 ACE	SP	CRE	ED,EP,ID,IP	TX	RR	7/7/2020
2020 PO8656781948	KU	6	30 BRO	SP	CRE	ED,ID,SR	TD		7/8/2020
2020 PO8472777687	F	4	45 BRO	SP	CCA		V		7/9/2020
2020 PO8472477602	F	4	45 BRO	SP	CCA		V		7/10/2020
2020 PO8472177541	F	4	40 BRO	SP	CRE		V		7/11/2020
2020 PO8471977480	F	4	45 BRO	SP	CCA		V		7/12/2020
2020 PO8471677391	F	4	45 BRO	SP	CCA		V		7/13/2020
2020 PO8476577158	KU	5	35 BRO	SP	CRE		B		7/14/2020
2020 PO8489780899	KU	6	30 BRO	SP	CRE	ID,IP	BD		7/15/2020
2020 PO8481881021	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD		7/16/2020
2020 PO8479281061	F	4	40 BRO	SP	CRE		V		7/17/2020
2020 PO8476781115	KU	4	40 BRO	SP	CRE	ED	TD		7/18/2020

2020 PO8480581078	KU	4	40 BRO	SP	P		ED	T		7/19/2020
2020 PO8482381497	F	4	40 BRO	SP	A			V		7/20/2020
2020 PO8489881402	F	4	40 BRO	SP	A			V		7/21/2020
2020 PO8497581306	F	4	40 BRO	SP	A			V		7/22/2020
2020 PO8490081202	F	4	40 BRO	SP	CRE			V		7/23/2020
2020 PO8956690674	F	7	20 ACE	SP	CRE			V		7/24/2020
2020 PO8594482907	KU	4	40 BRO	SP	CRE		ED,ID	TD		7/25/2020
2020 PO8603082999	KU	6	30 BRO	SP	CRE		ID	BD		7/26/2020
2020 PO8589183040	KU	4	40 BRO	SP	CCA			V		7/27/2020
2020 PO8572783059	KU	5	35 BRO	SP	CRE		ID	BD		7/28/2020
2020 PO8630383078	F	4	40 BRO	SP	CRE			V		7/29/2020
2020 PO8628882974	F	4	40 BRO	SP	CRE			V		7/30/2020
2020 PO8637482857	KU	6	30 BRO	SP	CRE		ID,IP	BD		7/31/2020
2020 PO8541181082	KU	3	50 BRO	SP	CCA			V		8/1/2020
2020 PO8558180859	KU	4	45 BRO	SP	CCA			V		8/2/2020
2020 PO8575880850	KU	4	45 BRO	SP	CCA			V		8/3/2020
2020 PO8620382745	KU	5	35 BRO	SP	CRE		ED,ID,SRC	TD		8/4/2020
2020 PO8624682854	KU	5	35 BRO	SP	CCA			V		8/5/2020
2020 PO8627382874	F	4	40 BRO	SP	CRE			V		8/6/2020
2020 PO8621382763	F	4	40 BRO	SP	CRE			V		8/7/2020
2020 PO3823704431	KU	6	30 XXX	SP	CRE		ED,ID,SRC	X	RP3	8/8/2020
2020 PO2635706209	KU	6	30 BRO	SP	CRE			B		8/9/2020
2020 PO2642606203	KU	4	35 BRO	SP	CRE		ID	BD		8/10/2020
2020 PO4330703014	KU	6	30 BRO	SP	CRE		ID	TD		8/11/2020
2020 PO3753204897	KU	5	35 BRO	SP	CRE		ID	BD		8/12/2020
2020 PO3972899870	KU	6	30 XXX	SP	CRE		ED,ID	TD		8/13/2020
2020 PO3961999865	KU	5	30 XXX	SP	CRE		ED,ID	TD		8/14/2020
2020 PO4018502974	KU	6	30 XXX	SP	CRE		ED,ID	TD		8/15/2020
2020 PO7302387111A	KU	5	35 BRO	SP	CCA			V		8/16/2020
2020 PO3945599765	KU	4	45 BRN	SP	CCA			V		8/17/2020
2020 PO3958899703	KU	4	45 BRN	SP	CCA			V		8/18/2020
2020 PO7302387111	KU	3	50 BRO	SP	CRE		ED,ID	BD		8/19/2020
2020 PO3957399810	KU	5	30 XXX	SP	CRE		ED,ID,IP	TD		8/20/2020
2020 PO3948099853	KU	4	40 XXX	SP	CRE		ED,ID,IP	TD		8/21/2020
2020 PO3967201109	KU	4	40 BRN	SP	CRE			V		8/22/2020
2020 PO3970701285	KU	4	40 XXX	SP	CCA			V		8/23/2020
2020 PO3974401435	KU	5	40 XXX	SP	CRE		ED,ID	TD		8/24/2020
2020 PO8477766858	KU	4	40 BRO	SP	CRE		ED,ID,IP	TD		8/25/2020
2020 PO7490186782	KU	4	35 BRO	SP	CCA			V		8/26/2020
2020 PO7507486758	KU	3	35 BRO	SP	A		ED,ID	BD		8/27/2020
2020 PO7101786091	KU	3	40 BRO	SP	CRE		ED,ID	TD		8/28/2020
2020 PO8403266500	KU	4	40 BRO	SP	CRE		ED,ID	TD		8/29/2020
2020 PO8392766340	KU	4	40 BRO	SP	CRE		ED,ID	TD		8/30/2020
2020 PO8382366183	KU	3	40 BRO	SP	CRE		ED,ID	TD		8/31/2020
2020 PO8438766266	KU	4	40 BRO	SP	CRE		ED,ID	TD		9/1/2020
2020 PO2205861042	KU	4	40 BRN	SP	CRE		ED,ID,IP,RB	X	PX	9/2/2020
2020 PO1232061815	F	4	40 BRN	SP	P			V		9/3/2020

2020 PO1220361902	F	4	40 BRN	SP	P		V		9/4/2020
2020 PO1207761997	F	4	40 BRN	SP	CRE		V		9/5/2020
2020 PO1197662067	F	4	40 BRN	SP	P		V		9/6/2020
2020 PO1185962154	F	4	40 BRN	SP	P		V		9/7/2020
2020 PO1175362291	F	6	30E BRN	SP	CRE		V		9/8/2020
2020 PO1172262243	F	4	40 BRN	SP	P		V		9/9/2020
2020 PO1159262326	F	4	40 BRN	SP	A		V		9/10/2020
2020 PO1144062487	F	6	30E BRN	SP	CRE		V		9/11/2020
2020 PO1141562436	F	3	45E BRN	SP	P		V		9/12/2020
2020 PO1131262496	F	4	40 BRN	SP	P		V		9/13/2020
2020 PO1123562538	F	3	45E BRN	SP	A		V		9/14/2020
2020 PO1046862909	F	5	35 BRN	SP	P		V		9/15/2020
2020 PO1019763036	F	3	35E BRN	SP	P		V		9/16/2020
2020 PO1004763110	F	5	35 BRN	SP	CCA		V		9/17/2020
2020 PO0988663200	F	5	35E BRN	SP	P		V		9/18/2020
2020 PO0898863769	F	4	40 BRN	SP	CCA		V		9/19/2020
2020 PO0887863831	KU	2	50 BRN	SP	CRE	ID		BD	9/20/2020
2020 PO0877363904	F	3	45 BRN	SP	P		V		9/21/2020
2020 PO0902363734	KU	5	35 BRN	SP	CCA		V		9/22/2020
2020 PO3915344781	F	4	40 BRN	SP	CRE		V		9/23/2020
2020 PO3925544671	F	4	40 BRN	SP	CRE		V		9/24/2020
2020 PO3939244524	F	4	40 BRN	SP	CRE	ID	VX	RP2	9/25/2020
2020 PO3949344415	F	4	40 BRN	SP	CCA		V		9/26/2020
2020 PO3959644306	F	4	40 BRN	SP	CCA		V		9/27/2020
2020 PO3934644315	KU	5	35 BRN	SP	CRE	ED,ID,IP		TD	9/28/2020
2020 PO3944644204	KU	4	40 BRN	SP	CRE		V		9/29/2020
2020 PO3958744049	KU	4	40 BRN	SP	CRE	ID		BD	9/30/2020
2020 PO3970243923	KU	4	40 BRN	SP	CRE	ED,ID,SRC		TD	10/1/2020
2020 PO3971844174	F	4	40 BRN	SP	CRE		V		10/2/2020
2020 PO3983444050	F	4	40 BRN	SP	CRE		V		10/3/2020
2020 PO3990043979	F	4	40 BRN	SP	CRE		V		10/4/2020
2020 PO3923568939	KU	2	75 BRN	SP	S		V		10/5/2020
2020 PO4018643618	KU	4	45 BRN	SP	CCA		V		10/6/2020
2020 PO4002443567	KU	4	45 BRN	SP	CCA		V		10/7/2020
2020 PO3993743663	KU	4	45 BRN	SP	CCA		V		10/8/2020
2020 PO3998243891	KU	4	40 BRN	SP	A		V		10/9/2020
2020 PO4010543759	F	4	40 BRN	SP	CRE		V		10/10/2020
2020 PO4021343642	F	4	40 BRN	SP	CRE		V		10/11/2020
2020 PO4006843518	KU	4	45 BRN	SP	CCA		V		10/12/2020
2020 PO4002443403	KU	6	30 BRN	SP	CRE	ID		BD	10/13/2020
2020 PO4011843284	KU	6	30 BRN	SP	CRE	ID		BD	10/14/2020
2020 PO4031343531	F	4	40 BRN	SP	CRE		V		10/15/2020
2020 PO3936983040	F	4	40 BRO	SP	P		V		10/16/2020
2020 PO3936683036	F	4	30 BRO	SP	P		V		10/17/2020
2020 PO3935583046	F	4	40 BRO	SP	P		V		10/18/2020
2020 PO4030182799	F	3	45 BRN	SP	A		V		10/19/2020
2020 PO4031582803	F	3	45 BRN	SP	CRE		V		10/20/2020

2020 PO4033182807	F	3	45 BRN	SP	S		V			10/21/2020
2020 PO4029582833	F	4	40 BRN	SP	A		V			10/22/2020
2020 PO4030582836	F	4	40 BRN	SP	CRE		V			10/23/2020
2020 PO3929468931	KU	2	50 XXX	SP	S		V			10/24/2020
2020 PO5911247429	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD			10/25/2020
2020 PO9487174360	KU	4	45 XXX	SP	CRE	ID	TD			10/26/2020
2020 PO3980640382	KU	4	40 BRO	SP	CRE		V			10/27/2020
2020 PO3921668640	KU	3	60 XXX	SP	CRE		V			10/28/2020
2020 PO3919968299	KU	1	75 XXX	SP	CCA		V			10/29/2020
2020 PO4659888460	F	4	40 BRN	SP	CRE		V			10/30/2020
2020 PO4659288469	LGE	4	30 BRN	SP	P	ED,ID	BD			10/31/2020
2020 PO5743047904	KU	4	45 OTH	SP	CRE	ED,EP,ID,IP	X		RP1	11/1/2020
2020 PO4819588395	LGE	4	40 BRO	SP	CRE	ED	BD			11/2/2020
2020 PO3918667996	KU	2	65 XXX	SP	CRE		V			11/3/2020
2020 PO5849847619	KU	4	40 OTH	SP	CRE	ED,SRS	TD			11/4/2020
2020 PO5699248026	KU	3	50 OTH	SP	CRE	ED,SRS	TD			11/5/2020
2020 PO4659888450	LGE	4	30 BRN	SP	A	ED,ID	BD			11/6/2020
2020 PO4660388453	F	3	45 BRN	SP	A		V			11/7/2020
2020 PO4660788448	F	2	45 BRN	SP	CRE		V			11/8/2020
2020 PO4031982838	F	4	40 BRN	SP	A		V			11/9/2020
2020 PO3933683050	F	4	30 BRO	SP	P		V			11/10/2020
2020 PO3933983053	F	4	40 BRO	SP	P		V			11/11/2020
2020 PO3932483060	F	4	40 BRO	SP	P		V			11/12/2020
2020 PO3931183066	F	4	40 BRO	SP	P		V			11/13/2020
2020 PO3929883072	F	4	40 BRO	SP	P		V			11/14/2020
2020 PO3929983067	LGE	4	30 BRO	SP	P	ED,ID,IP	TD			11/15/2020
2020 PO3684846820	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD			11/16/2020
2020 PO3444148331-B	KU	4	40 BRO	SP	CCA		V			11/17/2020
2020 PO3444148331-A	KU	4	40 BRO	SP	CCA		V			11/18/2020
2020 PO2012542834	ODP	4	40 KOP	SP	CRE	ED,ID	TD			11/19/2020
2020 PO2003742983	ODP	4	45 KOP	SP	S		V			11/20/2020
2020 PO1998343309	ODP	5	45 KOP	SP	CRE	ED,ID	TD			11/21/2020
2020 PO4032482898	F	3	40 BRN	SP	A		V			11/22/2020
2020 PO3932083098	F	4	40 BRO	SP	CCA		V			11/23/2020
2020 PO3932183090	LGE	5	30 BRO	SP	CCA		V			11/24/2020
2020 PO3932783094	F	4	40 BRO	SP	P		V			11/25/2020
2020 PO3932983073	LGE	4	30 BRO	SP	CCA		V			11/26/2020
2020 PO3934083087	F	4	40 BRO	SP	P		V			11/27/2020
2020 PO0572332544	ODP	4	45 XXX	SP	CCA		V			11/28/2020
2020 PO3239649958	KU	4	45 ACE	SP	CRE	ED,ID	TD			11/29/2020
2020 PO3896201334	KU	6	30 BRO	SP	CCA		V			11/30/2020
2020 PO3907501300	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			12/1/2020
2020 PO3298450356	KU	3	45 ACE	SP	CCA		V			12/2/2020
2020 PO3326050226	KU	3	45 ACE	SP	CCA		V			12/3/2020
2020 PO3352750100	KU	3	45 ACE	SP	CCA		V			12/4/2020
2020 PO3383249992	KU	3	45 ACE	SP	CCA		V			12/5/2020
2020 PO3316950331	KU	3	45 ACE	SP	CCA		V			12/6/2020

2020 PO3270750486	KU	3	50 ACE	SP	CCA		V	12/7/2020
2020 PO4000701202	F	4	40 BRO	SP	CCA		V	12/8/2020
2020 PO4022801200	F	4	40 BRO	SP	CCA		V	12/9/2020
2020 PO3412949886	KU	3	45 ACE	SP	CCA		V	12/10/2020
2020 PO3952283000	LGE	6	30 BRO	SP	A	ED,ID	TD	12/11/2020
2020 PO4042382553	LGE	4	40 BRN	SP	CRE	ED,ID	TD	12/12/2020
2020 PO7608237310	LGE	3	45 BRN	SP	CCA		V	12/13/2020
2020 PO4041382561	LGE	3	45 BRN	SP	S		V	12/14/2020
2020 PO0548232613	ODP	4	45 XXX	SP	CCA		V	12/15/2020
2020 PO0496232757	ODP	4	45 XXX	SP	CCA		V	12/16/2020
2020 PO0525732699	ODP	4	45 XXX	SP	CCA		V	12/17/2020
2020 PO3951983002	F	3	45 BRO	SP	CCA		V	12/18/2020
2020 PO3951983003	LGE	4	40 BRO	SP	CCA		V	12/19/2020
2020 PO3952483010	F	4	40 BRO	SP	CCA		V	12/20/2020
2020 PO3954083019	F	4	30 BRO	SP	P		V	12/21/2020
2020 PO3953283023	F	3	45 BRO	SP	CCA		V	12/22/2020
2020 PO3952983026	LGE	4	30 BRO	SP	P	ID	BD	12/23/2020
2020 PO3956483022	F	3	45 BRO	SP	CCA		V	12/24/2020
2020 PO3955383028	F	4	40 BRO	SP	P		V	12/25/2020
2020 PO3954083036	F	4	45 BRO	SP	P		V	12/26/2020
2020 PO3954583043	F	4	30 BRO	SP	P		V	12/27/2020
2020 PO3952683044	F	4	40 BRO	SP	P		V	12/28/2020
2020 PO4040382572	LGE	4	35 BRN	SP	CRE	ED,ID	TD	12/29/2020
2020 PO0470032626	ODP	4	40 XXX	SP	CRE	ED,ID	TD	12/30/2020
2020 PO3918382232	LGE	3	50 CAH	SP	A	ED,ID	BD	12/31/2020
2020 PO3919482226	LGE	3	45 CAH	SP	P	ED,ID	TD	1/1/2021
2020 PO3931181990	F	4	40 CAH	SP	P		V	1/2/2021
2020 PO3930781978	F	4	40 CAH	SP	CRE		V	1/3/2021
2020 PO3930281967	F	4	40 CAH	SP	CRE		V	1/4/2021
2020 PO3929781955	F	4	40 CAH	SP	CRE		V	1/5/2021
2020 PO3929281944	F	4	40 CAH	SP	CRE		V	1/6/2021
2020 PO3928781933	F	4	40 CAH	SP	CCA		V	1/7/2021
2020 PO3928281922	F	4	40 CAH	SP	CRE		V	1/8/2021
2020 PO3927781911	F	3	45 CAH	SP	CCA		V	1/9/2021
2020 PO3930581889	F	3	45 CAH	SP	CCA		V	1/10/2021
2020 PO3921281800	LGE	4	40 CAH	SP	CRE	ED,ID	TD	1/11/2021
2020 PO3931781911	F	4	40 CAH	SP	CRE		V	1/12/2021
2020 PO3931681920	F	4	40 CAH	SP	CRE		V	1/13/2021
2020 PV3932181932	F	4	40 CAH	SP	CRE		V	1/14/2021
2020 PO3932581942	F	4	40 CAH	SP	CRE		V	1/15/2021
2020 PO3933081955	F	4	40 CAH	SP	CRE		V	1/16/2021
2020 PO3933581966	F	3	45 CAH	SP	CCA		V	1/17/2021
2020 PO4876586386	LGE	4	40 OTH	SP	P	ED,ID,RB	X PX	1/18/2021
2020 PO3999601805	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	1/19/2021
2020 PO3933981978	F	4	40 CAH	SP	A		V	1/20/2021
2020 PO3922382292	LGE	4	40 CAH	SP	CCA		V	1/21/2021
2020 PO3933881852	F	4	40 CAH	SP	CCA		V	1/22/2021

2020 PO3932881858	F	4	40 CAH	SP	CCA		V	1/23/2021
2020 PO3931881865	F	4	40 CAH	SP	CRE		V	1/24/2021
2020 PO3930881871	F	4	40 CAH	SP	CCA		V	1/25/2021
2020 PO3929781878	F	4	40 CAH	SP	CCA		V	1/26/2021
2020 PO3928781885	F	4	40 CAH	SP	CCA		V	1/27/2021
2020 PO3928081889	F	4	40 CAH	SP	CCA		V	1/28/2021
2020 PO3926181884	F	4	35 CAH	SP	CCA		V	1/29/2021
2020 PO4039782581	LGE	4	35 BRN	SP	CRE	ED,ID	TD	1/30/2021
2020 PO2107323119	ODP	4	40 XXX	SP	CRE	ID	TD	1/31/2021
2020 PO2095323001	ODP	4	40 XXX	SP	CRE	ID	TD	2/1/2021
2020 PO2075923149	ODP	4	40 XXX	SP	CRE	ID	TD	2/2/2021
2020 PO2049723321	ODP	4	40 XXX	SP	CRE	ID	TD	2/3/2021
2020 PO0468832862	ODP	4	45 XXX	SP	CRE	ED,ID	TD	2/4/2021
2020 PO4573536051	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	2/5/2021
2020 PO4577436089	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	2/6/2021
2020 PO4877186397	F	3	50 OTH	UN	CCA		V	2/7/2021
2020 PO4876986390	LGE	4	30 OTH	SP	P	ED,ID,RB	X PX	2/8/2021
2020 PO4875686394	LGE	3	45 OTH	SP	P	ED,ID,SRS	TD	2/9/2021
2020 PO4826187799	LGE	UNK	25E BRO	SP	CCA		V	2/10/2021
2020 PO4871887456	LGE	5	30 KOP	SP	CRE	ED,ID	TD	2/11/2021
2020 PO4872087466	LGE	4	40 XXX	SP	P	ID	BD	2/12/2021
2020 PO4872187460	LGE	3	45 XXX	SP	CCA		V	2/13/2021
2020 PO5842987710	LGE	3	45 XXX	SP	CCA		V	2/14/2021
2020 PO4826287795	LGE	UNK	30E BRO	SP	CRE		V	2/15/2021
2020 PO4821587804	F	4	40 BRO	SP	CCA		V	2/16/2021
2020 PO4801188291	LGE	4	35 BRN	SP	A	ED,ID	BD	2/17/2021
2020 PO4800188303	LGE	4	35 BRN	SP	A	ED,ID	BD	2/18/2021
2020 PO4832886289	LGE	4	30 XXX	SP	CCA		V	2/19/2021
2020 PO5426075759	LGE	3	45 XXX	SP	CCA		V	2/20/2021
2020 PO4829886283	LGE	5	35 XXX	SP	A	ED,ID	TD	2/21/2021
2020 PO4829986294	LGE	4	40 XXX	SP	A	ID	TD	2/22/2021
2020 PO4909687205	LGE	3E	45E OTH	SP	P	ID	BD	2/23/2021
2020 PO3537849707	KU	3	45 ACE	SP	CCA	ED,ID	TD	2/24/2021
2020 PO1833841175	ODP	4	40 KOP	SP	CRE	ED,ID,MD,SRC	BD	2/25/2021
2020 PO1037435816	ODP	4	45 BRN	SP	CCA		V	2/26/2021
2020 PO1040635883	ODP	4	40 BRN	SP	CCA		V	2/27/2021
2020 PO1051435990	ODP	5	35 XXX	SP	CRE	ED,ID	TD	2/28/2021
2020 PO3922283203	F	3	45 BRO	SP	CCA		V	3/1/2021
2020 PO3921983219	F	4	40 BRO	SP	P		V	3/2/2021
2020 PO3921883235	F	4	40 BRO	SP	A	ED,ID,RB	VX RP1	3/3/2021
2020 PO3921683250	F	4	40 BRO	SP	A		V	3/4/2021
2020 PO3921083250	F	5	25 BRO	SP	A		V	3/5/2021
2020 PO3922283250	LGE	5	30 BRO	SP	P	ED,ID	TD	3/6/2021
2020 PO1084635860	ODP	6	30 XXX	SP	CRE		V	3/7/2021
2020 PO1084235783	ODP	5	35 XXX	SP	CRE		V	3/8/2021
2020 PO1071035712	F	7	25 XXX	SP	CRE		V	3/9/2021
2020 PO3245649626	F	4	40 BRO	SP	CRE		V	3/10/2021

2020 PO3258249545	F	4	40 BRO	SP	CRE		V		3/11/2021
2020 PO1084034612	F	4	40 SWP	SP	CRE		V		3/12/2021
2020 PO1065134603	F	3	40 XXX	SP	A		V		3/13/2021
2020 PO1070534853	ODP	4	40 XXX	SP	CRE	ED,ID	TD		3/14/2021
2020 PO1074435098	ODP	4	40 XXX	SP	CRE	ED,ID	TD		3/15/2021
2020 PO1066135187	ODP	5	35 XXX	SP	CRE	ED,ID	TD		3/16/2021
2020 PO1068835360	ODP	4	40 XXX	SP	CRE	ED,ID	TD		3/17/2021
2020 PO3270749462	F	4	40 BRO	SP	CRE		V		3/18/2021
2020 PO3981382703	F	3	45 BRN	SP	A		V		3/19/2021
2020 PO3980982717	F	4	35 BRN	SP	A		V		3/20/2021
2020 PO3981382727	F	4	35 BRN	SP	A		V		3/21/2021
2020 PO3980982732	LGE	4	40 BRN	SP	P	ED,ID	TD		3/22/2021
2020 PO3926483194	F	4	40 BRO	SP	A		V		3/23/2021
2020 PO3925383211	F	4	25 BRO	SP	P		V		3/24/2021
2020 PO3926083211	F	4	40 BRO	SP	CCA		V		3/25/2021
2020 PO3925883225	F	4	40 BRO	SP	P		V		3/26/2021
2020 PO3981182739	F	4	35 BRN	SP	CRE		V		3/27/2021
2020 PO3226049953	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		3/28/2021
2020 PO3287449353	F	4	40 BRO	SP	CRE		V		3/29/2021
2020 PO3262549865	KU	4	40 BRO	SP	CRE	ID,IP	BD		3/30/2021
2020 PO3198050120	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD		3/31/2021
2020 PO3232949707	F	2	45 BRO	SP	CRE		V		4/1/2021
2020 PO3220449790	F	2	45 BRO	SP	CRE		V		4/2/2021
2020 PO3201549916	F	4	40 BRO	SP	CRE		V		4/3/2021
2020 PO3212149845	F	4	40 BRO	SP	CRE		V		4/4/2021
2020 PO3979482746	F	3	45 BRN	DF	CRE		V		4/5/2021
2020 PO3977782738	LGE	4	40 BRN	SP	A	ED,ID	BD		4/6/2021
2020 PO3925783241	F	4	40 BRO	SP	CCA		V		4/7/2021
2020 PO3925683251	F	4	40 BRO	SP	CCA		V		4/8/2021
2020 PO3977582743	F	4	40 BRN	SP	CRE		V		4/9/2021
2020 PO3929783245	F	4	40 BRO	SP	P		V		4/10/2021
2020 PO3929283231	LGE	4	30 BRO	SP	P	ID,RB	BX	RP2	4/11/2021
2020 PO3929683230	F	4	40 BRO	SP	P		V		4/12/2021
2020 PO3929583216	F	4	40 BRO	SP	P		V		4/13/2021
2020 PO3930083199	F	5	30 BRO	SP	P		V		4/14/2021
2020 PO3929383202	F	4	40 BRO	SP	P		V		4/15/2021
2020 PO3928583196	F	4	30 BRO	SP	P		V		4/16/2021
2020 PO3928983196	F	4	40 BRO	SP	P		V		4/17/2021
2020 PO3928183182	F	4	40 BRO	SP	CRE		V		4/18/2021
2020 PO3927083167	F	4	40 BRO	SP	P		V		4/19/2021
2020 PO3925883157	F	4	30 BRO	SP	P		V		4/20/2021
2020 PO3926183154	F	4	40 BRO	SP	P		V		4/21/2021
2020 PO3976282731	LGE	7	25 BRN	SP	CRE	ED,ID	TD		4/22/2021
2020 PO3975782740	F	3	50 BRN	SP	CCA		V		4/23/2021
2020 PO1084435600	ODP	4	40 XXX	SP	CRE	ED,ID	TD		4/24/2021
2020 PO1070235593	F	4	40 XXX	SP	CCA		V		4/25/2021
2020 PO1063635673	ODP	6	30 BRN	SP	CCA		V		4/26/2021

2020 PO1079635359	ODP	4	40 XXX	SP	CRE	ED,ID	TD		4/27/2021
2020 1087235742a	ODP	4	25 XXX	SP	CRE	ID,RB	X	RP1	4/28/2021
2020 PO1087235742	ODP	4	40 BRN	SP	CRE	ED,ID,SRC	TX	RR	4/29/2021
2020 PO3973782740	F	3	50 BRN	SP	S		V		4/30/2021
2020 PO3972582728	LGE	4	30 BRN	SP	A	ED,ID	TD		5/1/2021
2020 PO3973482731	F	4	30 BRN	SP	A		V		5/2/2021
2020 PO3973782739	F	1	50 BRN	SP	S		V		5/3/2021
2020 PO3973382738	F	3	50 BRN	SP	S		V		5/4/2021
2020 PO3972282737	F	3	50 BRN	SP	CCA		V		5/5/2021
2020 PO3971282735	F	3	50 BRN	SP	S		V		5/6/2021
2020 PO3924883143	F	4	30 BRO	SP	P		V		5/7/2021
2020 PO3925383142	F	4	40 BRO	SP	P		V		5/8/2021
2020 PO3925283126	F	5	25 BRO	SP	P		V		5/9/2021
2020 PO3924583130	F	4	40 BRO	SP	A		V		5/10/2021
2020 PO3969482724	F	4	35 BRN	SP	A		V		5/11/2021
2020 PO3968582722	F	4	30 BRN	SP	CRE		V		5/12/2021
2020 PO3969382733	F	3	50 BRN	SP	S		V		5/13/2021
2020 PO3968982732	F	3	50 BRN	SP	S		V		5/14/2021
2020 PO3968782731	F	3	50 BRN	SP	S		V		5/15/2021
2020 PO3968282723	F	4	30 BRN	SP	A		V		5/16/2021
2020 PO3923683117	F	4	40 BRO	SP	A	ED,ID,IP,RB	VX	RP2	5/17/2021
2020 PO3923283118	F	5	35 BRO	SP	P		V		5/18/2021
2020 PO3967682730	F	2	55 BRN	SP	CCA		V		5/19/2021
2020 PO3967282713	LGE	4	40 BRN	SP	CRE		V		5/20/2021
2020 PO6861338920	LGE	4	90 BRN	SP	CRE		V		5/21/2021
2020 PO3967682722	F	4	30 BRN	SP	A		V		5/22/2021
2020 PO3935483081	F	4	40 BRO	SP	P		V		5/23/2021
2020 PO3936583071	F	4	30 BRO	SP	A		V		5/24/2021
2020 PO3936983074	F	4	40 BRO	SP	A		V		5/25/2021
2020 PO4028682910	F	4	40 BRN	SP	CRE		V		5/26/2021
2020 PO4028682910-A	F	4	35 BRN	SP	A		V		5/27/2021
2020 PO4029482877	F	4	40 BRN	SP	CCA		V		5/28/2021
2020 PO4029282892	F	4	40 BRN	SP	A		V		5/29/2021
2020 PO3938383068	F	4	40 BRO	SP	A		V		5/30/2021
2020 PO3939883061	F	4	40 BRO	SP	A		V		5/31/2021
2020 PO0136933581	ODP	4	40 XXX	SP	A	ED,ID	TD		6/1/2021
2020 PO0087033400	ODP	4	40 XXX	SP	A	ED,ID	TD		6/2/2021
2020 PO2117826495	F	4	40 XXX	SP	CRE		V		6/3/2021
2020 PO4974611852	F	3	45 ACE	SP	P		V		6/4/2021
2020 PO6986601217	KU	6	30 KOP	SP	CRE		V		6/5/2021
2020 PO4746988622	LGE	4	35 BRN	SP	CRE	ED,ID,SRC	TX	RR	6/6/2021
2020 6955301358a	KU	6	30 KOP	SP	S		V		6/7/2021
2020 PO6939001368	F	4	40 BRN	SP	CRE		V		6/8/2021
2020 PO6929401423	KU	6	30 BRN	SP	CRE	ED,ID	TD		6/9/2021
2020 PO6941701193	F	6	30 BRN	SP	CRE		V		6/10/2021
2020 PO6925201278	F	5	35 BRN	SP	CRE		V		6/11/2021
2020 PO6940801316	KU	3	45 BRN	SP	CCA		V		6/12/2021

2020 PO3985236232	F	4	40 BRO	SP	CRE		V			6/13/2021
2020 PO4817331365	KU	5	35 BRO	SP	CRE		V			6/14/2021
2020 PO4857331315	F	2	50 BRO	SP	CRE	ED,HH	BX	PX		6/15/2021
2020 PO4764730917	F	3	40 BRO	SP	P		V			6/16/2021
2020 PO7167391129	KU	4	35 BRO	SP	CRE	ED,ID	TD			6/17/2021
2020 PO2778735827	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD			6/18/2021
2020 PO2797035997	KU	4	40 BRN	SP	CCA		V			6/19/2021
2020 PO4746030845	F	2	50 BRO	SP	P		V			6/20/2021
2020 PO4727130779	F	2	55 BRO	SP	P		V			6/21/2021
2020 PO4729030706	F	5	35 BRO	SP	CRE		V			6/22/2021
2020 PO4707430772	F	2	50 BRO	SP	P		V			6/23/2021
2020 PO4194211828	KU	4	40 BRO	SP	CRE	ID	BD			6/24/2021
2020 PO4189611883	KU	4	40 BRO	SP	CRE	ID,IP	BD			6/25/2021
2020 PO4185211926	KU	4	40 BRO	SP	CRE	ID	BD			6/26/2021
2020 PO4175212020	KU	4	40 BRO	SP	CRE	ID	BD			6/27/2021
2020 PO4168811901	KU	4	40 BRO	SP	CRE	ID	BD			6/28/2021
2020 PO4162511749	KU	4	40 BRO	SP	CRE	ID	BD			6/29/2021
2020 PO4157511634	KU	4	40 BRO	SP	CRE	ED,ID	TD			6/30/2021
2020 PO4153311529	KU	4	40 BRO	SP	CRE	ID	BD			7/1/2021
2020 PO4996411988	F	4	40 ACE	SP	P		V			7/2/2021
2020 PO4726289249	F	3	45 BRO	SP	CCA		V			7/3/2021
2020 PO4724789241	F	4	40 BRO	SP	CRE		V			7/4/2021
2020 PO4724489246	F	4	30 BRO	SP	CRE		V			7/5/2021
2020 PO4723389231	F	4	30 BRO	SP	CRE		V			7/6/2021
2020 PO4723089237	F	4	40 BRO	SP	CRE		V			7/7/2021
2020 PO4722589227	F	3	45 BRO	SP	CCA		V			7/8/2021
2020 PO4721889223	F	4	40 BRO	SP	CCA		V			7/9/2021
2020 PO4721189218	F	4	35 BRO	SP	P		V			7/10/2021
2020 PO4721389236	F	4	40 BRO	SP	CRE		V			7/11/2021
2020 PO4690930864	KU	6	30 BRO	SP	CRE		B			7/12/2021
2020 PO4746588830	LGE	4	40 BRN	SP	CRE	ED,HH,ID	BX	RR		7/13/2021
2020 PO4687730818	KU	2	50 BRO	SP	CRE	ID	TD			7/14/2021
2020 PO7412192214	KU	4	40 BRO	SP	CRE	ED,ID,IP	BD			7/15/2021
2020 PO7428892419	KU	4	40 BRO	SP	CRE	ED,ID	BD			7/16/2021
2020 PO2814636160	KU	4	45 BRN	SP	CCA		V			7/17/2021
2020 PO7481392431	KU	6	30 BRO	SP	P	ED,ID	TD			7/18/2021
2020 PO6955495296	KU	4	40 BRN	SP	CRE	ED,ID	TD			7/19/2021
2020 PO6941695278	KU	6	30 BRN	SP	A	ED,ID	BD			7/20/2021
2020 PO7159291184	KU	5	35 BRO	SP	CRE	ED,ID	TD			7/21/2021
2020 PO7156091285	KU	4	40 BRO	SP	CRE	ED,ID	TD			7/22/2021
2020 PO2866536429	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD			7/23/2021
2020 PO2877836397	KU	5	35 BRN	SP	CCA		V			7/24/2021
2020 PO7502392363	KU	6	30 BRO	SP	P	ED,ID	TD			7/25/2021
2020 PO7484092318	KU	6	30 BRO	SP	CRE	ED,ID	TD			7/26/2021
2020 PO6954795148	KU	4	40 BRN	SP	CRE	ED,ID	BD			7/27/2021
2020 PO6887419701	KU	6	30 XXX	SP	CRE		V			7/28/2021
2020 PO6908019757	KU	5	35 XXX	SP	CRE		V			7/29/2021

2020 PO4745688845	LGE	4	40 BRN	SP	A	ED,ID	TD	7/30/2021
2020 PO4746088838	LGE	4	40 BRN	SP	CRE	ED,ID	BD	7/31/2021
2020 PO4620412757	KU	4	40 BRO	SP	CRE	ID,IP	BD	8/1/2021
2020 PO4625212661	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/2/2021
2020 PO4052883053	LGE	4	40 BRO	SP	A	ED,ID	TD	8/3/2021
2020 PO4053283069	LGE	4	40 BRO	SP	CRE	ED,ID	TD	8/4/2021
2020 PO4052783034	LGE	4	40 BRO	SP	A	ED,ID	TD	8/5/2021
2020 PO4052683017	LGE	4	40 BRO	SP	CRE	ED,ID	TD	8/6/2021
2020 PO4053183000	LGE	4	30 BRO	SP	CRE	ED,ID	TD	8/7/2021
2020 PO4052583000	LGE	4	40 BRO	SP	CRE	ED,ID	TD	8/8/2021
2020 PO4546301332	LGE	4	30 BRN	SP	S		V	8/9/2021
2020 PO4744988857	LGE	4	40 BRN	SP	CRE	ED,ID	TD	8/10/2021
2020 PO4644812593	KU	4	40 BRO	SP	CRE	ID	BD	8/11/2021
2020 PO4657712540	KU	4	40 BRO	SP	CRE	ID	BD	8/12/2021
2020 PO4670312488	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/13/2021
2020 PO4734889116	LGE	4	30 BRO	SP	CRE	ED,ID,RB	BX	8/14/2021
2020 PO6878493908	KU	4	40 BRN	SP	CRE	ED,ID	TD	8/15/2021
2020 PO6997301548	KU	4	40 XXX	SP	CRE		V	8/16/2021
2020 PO6971601593	KU	4	40 XXX	SP	CRE		V	8/17/2021
2020 PO6974301567	KU	6	30 XXX	SP	CRE		V	8/18/2021
2020 PO6961001572	KU	4	30 XXX	SP	CRE		V	8/19/2021
2020 PO6978301554	KU	4	40 XXX	SP	CRE	ED,ID	TD	8/20/2021
2020 PO6947801625	KU	6	30 XXX	SP	CRE	ED,ID	TD	8/21/2021
2020 PO6961701416	KU	6	30 KOP	SP	CCA		V	8/22/2021
2020 PO6893493861	KU	6	30 BRN	SP	CRE	ED,ID	TD	8/23/2021
2020 PO6898294021	KU	4	40 BRN	SP	CRE	ED,ID	TD	8/24/2021
2020 PO6919694331	KU	4	40 BRN	SP	CRE	ED,ID	TD	8/25/2021
2020 PO6902094267	KU	6	30 BRN	SP	CCA		V	8/26/2021
2020 PO6888293950	KU	5	35 BRN	SP	CRE	ED,ID	TD	8/27/2021
2020 PO6874194047	KU	6	30 BRN	SP	CCA		V	8/28/2021
2020 PO6847794044	KU	6	30 BRN	SP	A	ED,ID	TD	8/29/2021
2020 PO6856894270	KU	4	40 BRN	SP	CRE	ED,ID	TD	8/30/2021
2020 PO6866594315	KU	5	35 BRN	SP	CRE	ED,ID	BD	8/31/2021
2020 PO6871294252	KU	4	40 BRN	SP	CRE		V	9/1/2021
2020 PO6853094393	KU	6	30 BRN	SP	S		V	9/2/2021
2020 PO6879194304	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/3/2021
2020 PO6889594378	KU	5	35 BRN	SP	CRE	ED,ID	TD	9/4/2021
2020 PO6891694628	KU	6	30 BRN	SP	CRE	ED,ID	TD	9/5/2021
2020 PO4995811257	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	9/6/2021
2020 PO5025711271	F	3	45 ACE	SP	CCA		V	9/7/2021
2020 PO5011011317	F	2	50 ACE	SP	CCA		V	9/8/2021
2020 PO4963110490	F	4	40 ACE	SP	CRE	ED,HH,ID,IP,RB	BX	9/9/2021
2020 PO4738989108	LGE	3	45 BRO	SP	P	ED,ID	TD	9/10/2021
2020 PO4736389114	LGE	3	45 BRO	SP	CRE	ED,ID	BD	9/11/2021
2020 PO4990811142	F	4	40 ACE	SP	P		V	9/12/2021
2020 PO4744388858	LGE	4	30 BRN	SP	A	ED,ID	TD	9/13/2021
2020 PO4985911025	F	4	40 ACE	SP	CRE		V	9/14/2021

2020 PO4980410899	F	4	40 ACE	SP	P		V			9/15/2021
2020 PO4975810792	F	4	40 ACE	SP	P		V			9/16/2021
2020 PO4736689136	F	1	50 BRO	SP	CCA		V			9/17/2021
2020 PO4736389134	LGE	UNK	20 BRO	ST	CRE		V			9/18/2021
2020 PO4737689118	LGE	1	50 BRO	SP	CCA		V			9/19/2021
2020 PO4738289102	LGE	1	50 BRO	SP	CCA		V			9/20/2021
2020 PO4739589104	LGE	1	50 BRO	SP	CCA		V			9/21/2021
2020 PO4744288868	LGE	4	40 BRN	SP	A	ED,ID	TD			9/22/2021
2020 PO4947310807	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	RP1		9/23/2021
2020 PO4965210652	F	4	40 ACE	SP	P		V			9/24/2021
2020 PO4742688858	LGE	3H	45 BRN	SP	A	ED,ID	BD			9/25/2021
2020 PO4511201414	LGE	4	35 BRN	SP	S		V			9/26/2021
2020 PO4952810698	F	4	40 ACE	SP	P		V			9/27/2021
2020 PO4747389118	LGE	4	40 BRO	SP	CRE	ED,ID	BD			9/28/2021
2020 PO4747189124	LGE	3	45 BRO	SP	CCA		V			9/29/2021
2020 PO4748189131	LGE	4	40 BRO	SP	CCA		V			9/30/2021
2020 PO4544103941	LGE	4	30 BRO	SP	CCA		V			10/1/2021
2020 PO4745089120	LGE	1	50 BRO	SP	CCA		V			10/2/2021
2020 PO4756788643	LGE	4	40 BRN	SP	CRE	ED,ID	BD			10/3/2021
2020 PO475788640	LGE	4	40 BRN	SP	S		V			10/4/2021
2020 PO4574888636	LGE	4	35 BRN	SP	CRE	ED,ID	BD			10/5/2021
2020 PO4807116155	F	4	40 BRO	SP	CRE	HH,RB	VX	RP2		10/6/2021
2020 PO4793016201	F	4	40 BRO	SP	CRE		VX	RP2		10/7/2021
2020 PO4809216177	F	4	40 BRO	SP	CRE		V			10/8/2021
2020 PO4803116115	F	4	40 BRO	SP	CRE		V			10/9/2021
2020 PO4779116302	F	4	40 BRO	SP	CRE		V			10/10/2021
2020 PO4804716325	KU	2	40 BRO	SP	CRE	HH,ID,RB	X	PX		10/11/2021
2020 PO4754488635	LGE	4	40 BRN	SP	CRE	ED,ID	BD			10/12/2021
2020 PO4753988642	LGE	4	40 BRN	SP	CRE	ED,ID	TD			10/13/2021
2020 PO4746889130	LGE	1	50 BRO	SP	CCA		V			10/14/2021
2020 PO4573504234	LGE	1	50 BRO	SP	CCA		V			10/15/2021
2020 PO4869111298	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD			10/16/2021
2020 PO4863711216	KU	3	50 ACE	SP	P	ED	T			10/17/2021
2020 PO4034582980	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD			10/18/2021
2020 PO4032183013	LGE	3	45 BRO	SP	CCA		V			10/19/2021
2020 PO4033382978	LGE	4	35 BRO	SP	P	ED,ID	TD			10/20/2021
2020 PO4750189156	F	4	40 BRO	SP	P		V			10/21/2021
2020 PO4750389153	LGE	1	50 BRO	SP	CCA		V			10/22/2021
2020 PO4751689161	LGE	1	50 BRO	SP	CCA		V			10/23/2021
2020 PO4753389171	LGE	1	50 BRO	SP	CCA		V			10/24/2021
2020 PO4754389182	LGE	4	30 BRO	SP	CCA		V			10/25/2021
2020 PO4754589178	LGE	3	50 BRO	SP	CCA		V			10/26/2021
2020 PO4753488650	LGE	4	40 BRN	SP	CRE	ED,ID	BD			10/27/2021
2020 PO4752988659	LGE	4	40 BRN	SP	CRE	ED,ID	TD			10/28/2021
2020 PO1135833587	ODP	4	45 BRN	SP	CCA		V			10/29/2021
2020 PO4752288711	LGE	4	40 BRN	SP	CRE	ED,HH,ID	BX	PX		10/30/2021
2020 PO1126133733	ODP	5	35 US	SP	CRE		V			10/31/2021

2020 PO1130733590	F	3	40 US	SP	CRE		V		11/1/2021
2020 PO1131733749	F	4	40 US	SP	CRE		V		11/2/2021
2020 PO1130933689	ODP	5	35 US	SP	CRE		V		11/3/2021
2020 PO1129833629	F	4	40 US	SP	CRE		V		11/4/2021
2020 PO1123133555	ODP	5	35 US	SP	CRE		V		11/5/2021
2020 PO1122233625	F	4	40 US	SP	CRE		V		11/6/2021
2020 PO1100933662	F	3	45 BRN	SP	CCA		V		11/7/2021
2020 PO1109733487	F	3	50 BRN	SP	CCA		V		11/8/2021
2020 PO1096433514	F	4	40 OTH	SP	CRE	ED	V		11/9/2021
2020 PO3969483104	LGE	4	40 BRO	SP	CRE	ED,ID	TD		11/10/2021
2020 PO3970783106	LGE	4	40 BRO	SP	CRE	ID	BD		11/11/2021
2020 PO6840694407	KU	4	40 BRN	SP	CRE	ED,ID	BD		11/12/2021
2020 PO6860294789	KU	6	30 BRN	SP	CCA		V		11/13/2021
2020 PO6849894979A	KU	4	40 BRN	SP	A	ED,ID	TD		11/14/2021
2020 PO3950482595	LGE	4	40 BRN	SP	CRE	ED,ID	TD		11/15/2021
2020 PO3951482591	F	4	40 BRN	SP	CCA		V		11/16/2021
2020 PO4034582961	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		11/17/2021
2020 PO4031783013	LGE	4	40 BRO	SP	CCA		V		11/18/2021
2020 PO4034782997	LGE	4	40 BRO	SP	P	ED,ID	BD		11/19/2021
2020 PO4871010742	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		11/20/2021
2020 PO4850910825	KU	4	40 ACE	SP	CRE	ED,ID	BD		11/21/2021
2020 PO4751488706	LGE	4	40 BRN	SP	S		V		11/22/2021
2020 PO4033583012	LGE	3	45 BRO	SP	CRE	ED,ID	TD		11/23/2021
2020 PO4034883007	LGE	4	40 BRO	SP	CRE	ED,ID	BD		11/24/2021
2020 PO4034883011	LGE	4	40 BRO	SP	CRE		V		11/25/2021
2020 PO4035383011	LGE	4	40 BRO	SP	A	ED,ID	TD		11/26/2021
2020 PO4034583017	LGE	3	45 BRO	SP	P	ED,ID	BD		11/27/2021
2020 PO4036483012	LGE	4	40 BRO	SP	CRE	ED,ID	BD		11/28/2021
2020 PO4036483017	LGE	4	30 BRO	SP	CCA		V		11/29/2021
2020 PO4747688683	LGE	4	25 BRN	SP	CRE	ED,ID	TD		11/30/2021
2020 PO4217612181	KU	4	40 BRO	SP	CRE	ID	BD		12/1/2021
2020 PO4220212167	KU	4	40 BRO	SP	CRE	ID	BD		12/2/2021
2020 PO4842510669	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD		12/3/2021
2020 PO6847094819	KU	4	40 BRN	SP	CRE	ED,ID	BD		12/4/2021
2020 PO4238511817	KU	4	40 BRO	SP	CRE	HH,ID,RB	BX	PX	12/5/2021
2020 PO4259411992	KU	4	40 BRO	SP	CRE	ID	BD		12/6/2021
2020 PO5030609683	F	5	35 ACE	SP	P		V		12/7/2021
2020 PO5025709575	F	3	45 ACE	SP	P		V		12/8/2021
2020 PO5012309647	F	4	40 ACE	SP	CRE	ED,EP,ID,IP	V		12/9/2021
2020 PO5002309687	F	4	40 ACE	SP	P		V		12/10/2021
2020 PO4748788724	LGE	4	40 BRN	SP	CRE	ED,ID	TD		12/11/2021
2020 PO4733489179	F	3	45 BRO	SP	CCA		V		12/12/2021
2020 PO4748188735	LGE	3	45 BRN	SP	S		V		12/13/2021
2020 PO4422704611	LGE	3	45 BRO	SP	CCA		V		12/14/2021
2020 PO4747888745	LGE	4	35 BRN	SP	CCA		V		12/15/2021
2020 PO4733589164	F	4	40 BRO	SP	CCA		VX	RP2	12/16/2021
2020 PO4733889145	F	UNK	45 BRO	SP	CRE		V		12/17/2021

2020 PO4996909559	F	5	35 ACE	SP	P		V		12/18/2021
2020 PO3949682590	LGE	1	20 BRN	SP	A	ED,ID	BD		12/19/2021
2020 PO3949782592	LGE	1	65 BRN	SP	A		V		12/20/2021
2020 PO6844694689	KU	4	40 BRN	SP	CRE	ED,ID	TD		12/21/2021
2020 PO3868683088	LGE	6	65 BRO	SP	CRE		V		12/22/2021
2020 PO3868983072	LGE	6	40 BRO	SP	CCA		V		12/23/2021
2020 PO3869483071	LGE	4	40 BRO	SP	CCA		V		12/24/2021
2020 PO3950182602	LGE	UNK	100 BRN	AL	CCA		V		12/25/2021
2020 PO3950682615	LGE	1	20 BRN	SP	A	ED,ID	TD		12/26/2021
2020 PO3951182627	LGE	3	20 BRN	SP	A	ED,ID	BD		12/27/2021
2020 PO4977209363	F	5	35 ACE	SP	CRE	ED,EP,HH,ID,IP,MD,RB	BX	PX	12/28/2021
2020 PO3874583073	LGE	4	40 BRO	SP	P	ED,ID,RB	VX	RP1	12/29/2021
2020 PO4985109756	F	4	40 ACE	SP	P		V		12/30/2021
2020 PO4976109792	F	4	40 ACE	SP	P		V		12/31/2021
2020 PO4958709437	F	5	35 ACE	SP	CCA		V		1/1/2022
2020 PO4980109626	F	5	35 ACE	SP	CRE	ED,ID,IP	V		1/2/2022
2020 PO4267612060	KU	4	40 BRO	SP	CRE	ID	BD		1/3/2022
2020 PO4278412159	KU	4	40 BRO	SP	CRE	ID	BD		1/4/2022
2020 PO4282212192	KU	4	40 BRO	SP	CRE	ID	BD		1/5/2022
2020 PO4285512218	KU	4	40 BRO	SP	CRE	ID	BD		1/6/2022
2020 PO4747388747	LGE	4	40 BRN	SP	A	ED,ID	BD		1/7/2022
2020 PO4038582777	F	4	40 BRO	SP	CCA		V		1/8/2022
2020 PV4038582777	F	4	40 BRO	SP	CCA		V		1/9/2022
2020 PO4041182780	F	3	40 BRO	SP	CCA		V		1/10/2022
2020 PO4746788759	LGE	4	40 BRN	SP	CRE	ED,ID	TD		1/11/2022
2020 PO4039982774	LGE	4	40 BRO	SP	CCA		V		1/12/2022
2020 PO4041282775	LGE	4	40 BRO	SP	CCA		V		1/13/2022
2020 PO4042782777	LGE	4	40 BRO	SP	CCA		V		1/14/2022
2020 PO4050782805	LGE	4	40 BRO	SP	CRE	ED,ID	TD		1/15/2022
2020 PO1167933290	F	4	40 OTH	SP	CRE		V		1/16/2022
2020 PO3946982862	LGE	4	45 BRO	SP	CRE	ID	BD		1/17/2022
2020 PO3946482852	LGE	3	45 BRO	SP	A	ID	BD		1/18/2022
2020 PO3945682838	LGE	1	50 BRO	SP	CCA		V		1/19/2022
2020 PO3945682837	LGE	3	50 BRO	SP	P	ED,ID,IP,RB	TX	RR	1/20/2022
2020 PO2124747525	KU	3	40 BRO	SP	CRE	ED,ID,IP	TD		1/21/2022
2020 PO2109647522	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		1/22/2022
2020 PO3996383048	LGE	4	40 BRN	SP	CRE	ED,ID	TD		1/23/2022
2020 PO4085544813	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD		1/24/2022
2020 PO3924382509	LGE	4	35 BRN	SP	CRE	ED,ID	TD		1/25/2022
2020 PO3997383051	LGE	6	25 BRN	SP	CRE	ED	VX	RP3	1/26/2022
2020 PO3996783054	LGE	4	40 BRN	SP	A	ED,ID	TD		1/27/2022
2020 PO3997783066	LGE	4	30 BRN	SP	A	ED,ID	TD		1/28/2022
2020 PO1183333295	ODP	3	50 OTH	SP	CRE	ID,SRS	TD		1/29/2022
2020 PO1180333357	ODP	5	30 OTH	SP	CRE	ID	TD		1/30/2022
2020 PO1139933581	ODP	4	45 OTH	SP	CRE	ID,SRS	TD		1/31/2022
2020 PO4078244659	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD		2/1/2022
2020 PO2110347272	KU	5	30 BRO	SP	CRE	ED,ID,IP	TD		2/2/2022

2020 PO4072744541	KU	4	40 ACE	SP	CCA		V	2/3/2022	
2020 PO2849437647	KU	4	40 BRN	SP	CRE		V	2/4/2022	
2020 PO2857437463	KU	4	40 BRN	SP	CRE		B	2/5/2022	
2020 PO3997183066	LGE	4	40 BRN	SP	CRE	ED,ID	TD	2/6/2022	
2020 9387618048A	KU	6	30 OTH	SP	CRE	ID	TD	2/7/2022	
2020 9380018091A	KU	5	35 OTH	SP	CRE	ID	TD	2/8/2022	
2020 9360018196A	KU	6	30 OTH	SP	CRE	ID	TD	2/9/2022	
2020 PO9370318220	KU	6	30 BRN	SP	CRE	ID	TD	2/10/2022	
2020 PO4801588798	LGE	4	35 BRN	SP	A	ED,ID	TD	2/11/2022	
2020 PO4736489180	F	3	45 ACE	SP	CCA		V	2/12/2022	
2020 PO4736589187	F	3	45 ACE	SP	CCA		V	2/13/2022	
2020 PO4736789198	F	3	45 ACE	SP	CCA		V	2/14/2022	
2020 PO4736789208	F	2	55 ACE	SP	CCA		V	2/15/2022	
2020 PO4736789222	F	3	45 ACE	SP	CCA		V	2/16/2022	
2020 PO4739789202	F	3	45 ACE	SP	CRE		V	2/17/2022	
2020 PO4739589192	F	3	45 ACE	SP	CCA		V	2/18/2022	
2020 PO4739589233	F	3	45 ACE	SP	CCA		V	2/19/2022	
2020 PO4739889215	F	3	45 ACE	SP	CCA		V	2/20/2022	
2020 PO4742589160	F	4	40 ACE	SP	CCA		V	2/21/2022	
2020 PO4742489167	F	3	45 ACE	SP	CCA		V	2/22/2022	
2020 PO4808488824	LGE	4	40 BRN	SP	CRE	ED,HH,ID,RB	VX	PX	2/23/2022
2020 PO3878382775	LGE	4	30 BRO	SP	P	ED,ID,IP	TD		2/24/2022
2020 PO3878582792	LGE	4	30 BRO	SP	P	ED,ID	TD		2/25/2022
2020 PO3878982807	LGE	4	30 BRO	SP	P	ED,ID	TD		2/26/2022
2020 PO3877882779	LGE	1	65 BRO	SP	P		V		2/27/2022
2020 PO3878082787	LGE	4	40 BRO	SP	P	ED,ID	TD		2/28/2022
2020 PO3669642088	KU	5	35 ACE	SP	CRE	ED,ID	BD		3/1/2022
2020 PO3978983093	LGE	6	25 BRN	SP	CRE	ED,ID,RB	TX	RR	3/2/2022
2020 PO2097536422	KU	2	50 BRO	SP	P	ED	T		3/3/2022
2020 PO1115433077	ODP	5	35 XXX	SP	CRE	ED,ID,MD	TD		3/4/2022
2020 PO1075032867	ODP	4	40 XXX	SP	CRE	ID	BD		3/5/2022
2020 PO1054032674	ODP	2	80 XXX	SP	CRE	ED,ID,MD	TD		3/6/2022
2020 PO1121933484	ODP	4	45 XXX	SP	CRE	ED,ID,MD	TD		3/7/2022
2020 PO1150333412	ODP	4	40 XXX	SP	CRE	ED,ID,MD	TD		3/8/2022
2020 PO1139133432	ODP	4	40 XXX	SP	CRE	ED,ID,MD	TD		3/9/2022
2020 PO2148437290	KU	4	40 BRO	SP	P	ED	T		3/10/2022
2020 PO3979883094	LGE	4	40 BRN	SP	CRE	ED,ID	TD		3/11/2022
2020 PO3508842704	KU	4	40 ACE	SP	CRE	ID	BD		3/12/2022
2020 PO3392143324	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD		3/13/2022
2020 PO3979883086	LGE	4	40 BRN	SP	CRE	ED,ID	TD		3/14/2022
2020 PO3879182824	LGE	4	40 BRO	SP	CCA		V		3/15/2022
2020 PO3879382834	LGE	4	30 BRO	SP	P	ED,ID	TD		3/16/2022
2020 PO3879682846	LGE	4	30 BRO	SP	P	ED,ID,IP	TD		3/17/2022
2020 PO3880382875	LGE	4	30 BRO	SP	A	ED,ID,IP	TD		3/18/2022
2020 PO3879882857	LGE	4	30 BRO	SP	P	ED,ID	TD		3/19/2022
2020 PO3880282886	LGE	4	35 BRO	SP	P	ED,ID,IP	TD		3/20/2022
2020 PO3879582887	LGE	4	40 BRO	SP	A	ED,ID	BD		3/21/2022

2020 PO3879482881	LGE	1	65 BRO	SP	P	ED	VX	RP2	3/22/2022
2020 PO3879182858	LGE	1	65 BRO	SP	CRE	ED	VX	RP2	3/23/2022
2020 PO3879082848	LGE	4	40 BRO	SP	P	ED,ID,IP	TD		3/24/2022
2020 PO3878882838	LGE	1	65 BRO	SP	A		V		3/25/2022
2020 PO4809088827	LGE	1	65 BRN	SP	CRE		V		3/26/2022
2020 PO4743489176	F	3	45 ACE	SP	CCA		V		3/27/2022
2020 PO4743689205	F	3	45 ACE	SP	CCA		V		3/28/2022
2020 PO4744689187	F	3	45 ACE	SP	CCA		V		3/29/2022
2020 PO4744189196	F	3	45 ACE	SP	CCA		V		3/30/2022
2020 PO4742389180	F	3	45 ACE	SP	CCA		V		3/31/2022
2020 PO4742989204	F	3	45 ACE	SP	CCA		V		4/1/2022
2020 PO4739789221	F	3	45 ACE	SP	CCA		V		4/2/2022
2020 PO4742289230	F	4	40 ACE	SP	CCA		V		4/3/2022
2020 PO4203913001	KU	2	45 BRO	SP	CRE	ID,IP	BD		4/4/2022
2020 PO4809788829	LGE	4	35 BRN	SP	CRE	ED,ID	TD		4/5/2022
2020 PO4811188830	LGE	4	30 BRN	SP	CCA		V		4/6/2022
2020 PO4810988832	LGE	4	35 BRN	SP	S		V		4/7/2022
2020 PO4810988834	LGE	1	65 BRN	SP	CRE		V		4/8/2022
2020 PO4812088840	LGE	1	70 BRN	SP	CRE		V		4/9/2022
2020 PO4812788843	LGE	1	70 BRN	SP	CRE		V		4/10/2022
2020 PO4813188839	LGE	4	30 BRN	SP	CRE	ED,ID	TD		4/11/2022
2020 PO3978983062	LGE	4	30 BRN	SP	A	ED,ID	TD		4/12/2022
2020 PO3979683059	LGE	4	40 BRN	SP	CRE	ED,ID	TD		4/13/2022
2020 PO2110337613	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD		4/14/2022
2020 PO2139137465	KU	3	45 BRO	SP	CRE	ED,ID,RB	X	RP1	4/15/2022
2020 PO2091237732	KU	4	40 BRO	SP	CRE	ED	TD		4/16/2022
2020 PO2201337340	KU	4	40 BRO	SP	CCA		V		4/17/2022
2020 PO3429439680	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD		4/18/2022
2020 PO3979383048	LGE	4	40 BRN	SP	S		T		4/19/2022
2020 PO3979383037	LGE	4	40 BRN	SP	CRE	ED,ID	TD		4/20/2022
2020 PO3978583037	LGE	4	30 BRN	SP	S	ED,ID	V		4/21/2022
2020 PO3978783024	LGE	6	25 BRN	SP	CRE	ED,ID	TD		4/22/2022
2020 PO3979483025	LGE	4	40 BRN	SP	P	ED,ID	TD		4/23/2022
2020 PO5072811331	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	RP1	4/24/2022
2020 PO4733488458	LGE	4	45 BRN	SP	A	ED,ID	BD		4/25/2022
2020 PO4731888474	LGE	4	40 BRN	SP	A	ED,ID	TD		4/26/2022
2020 PO4734188464	LGE	4	30 BRN	ST	CCA		V		4/27/2022
2020 PO4732288479	LGE	4	30 BRN	ST	CCA		V		4/28/2022
2020 PO4049082906	LGE	4	40 BRO	SP	CCA		V		4/29/2022
2020 PO4050882898	LGE	4	30 BRO	SP	CCA		V		4/30/2022
2020 PO5083411231	F	4	40 ACE	SP	CRE		V		5/1/2022
2020 PO4317611629	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD		5/2/2022
2020 PO5092711163	F	4	40 ACE	SP	CRE		V		5/3/2022
2020 PO4730188487	LGE	3	45 BRN	SP	CCA		V		5/4/2022
2020 PO5101711087	F	4	40 ACE	SP	CRE		V		5/5/2022
2020 PO4729088496	LGE	4	45 BRN	SP	A	ED,ID,IP	TD		5/6/2022
2020 PO4051983001	LGE	4	35 BRO	SP	P	ED,ID	TD		5/7/2022

2020 PO4052083017	LGE	4	30 BRO	SP	A	ED,ID	TD	5/8/2022
2020 PO4052183034	LGE	4	30 BRO	SP	P	ED,ID	BD	5/9/2022
2020 PO4308511551	KU	2	45 BRO	SP	CRE	ED,ID,IP	TD	5/10/2022
2020 PO4720088383	LGE	4	40 ACE	SP	A	ED,ID	VX	5/11/2022
2020 PO4300996733	LGE	4	30 ACE	SP	CCA		V	5/12/2022
2020 PO4329396510	LGE	UNK	70 ACE	SP	P	HH	BX	5/13/2022
2020 PO4723988370	LGE	4	40 ACE	SP	CCA		V	5/14/2022
2020 PO4721088394	LGE	UNK	70 ACE	SP	A		V	5/15/2022
2020 PO4721688401	LGE	4	40 ACE	SP	CRE	ED,ID	BD	5/16/2022
2020 PO4721888403	LGE	4	30 ACE	SP	CRE	ED,ID	BD	5/17/2022
2020 PO4326296555	LGE	4	40 ACE	SP	P	RB	X	5/18/2022
2020 PO4320296639	LGE	UNK	70 ACE	SP	A		V	5/19/2022
2020 PO4812611007	KU	5	35 ACE	SP	CRE	ED,ID	TD	5/20/2022
2020 PO4771088653	F	4	40 BRN	SP	CCA		V	5/21/2022
2020 PO4770988651	F	4	40 BRN	SP	A		V	5/22/2022
2020 PO4770288642	F	1	50 BRN	SP	CCA		V	5/23/2022
2020 PO4771288646	LGE	4	35 BRN	SP	CCA		V	5/24/2022
2020 PO4771188629	LGE	4	35 BRN	SP	S		V	5/25/2022
2020 PO4771588634	F	1	50 BRN	SP	CCA		V	5/26/2022
2020 PO4838410823	KU	2	50 ACE	SP	CRE	ED,ID,IP	TD	5/27/2022
2020 PO5187213015	KU	5	35 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	5/28/2022
2020 PO5538844418	F	4	40 BRN	SP	S		V	5/29/2022
2020 PO5508144658	KU	4	40 BRN	SP	CRE	ED,ID	TD	5/30/2022
2020 PO5540944344	F	4	40 BRN	SP	S		V	5/31/2022
2020 PO5537144311	KU	4	40 BRN	SP	CRE		V	6/1/2022
2020 PO5512544620	F	2	50 BRN	SP	S		V	6/2/2022
2020 PO5533644363	KU	6	30 BRN	SP	CRE	ID	BD	6/3/2022
2020 PO3341052939	KU	4	40 ACE	SP	CRE	ED,HH,ID,IP,RB	BX	6/4/2022
2020 PO3327052860	KU	4	40 ACE	SP	CRE	ED,ID	BD	6/5/2022
2020 PO4313701949	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD	6/6/2022
2020 PO4320002058	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/7/2022
2020 PO4772788804	LGE	4	40 BRN	SP	CRE	ED,ID	TD	6/8/2022
2020 PO4769788790	LGE	4	40 BRN	SP	CRE	ED,ID	TD	6/9/2022
2020 PO5193313123	KU	3	45 ACE	SP	CRE	ED,ID	BD	6/10/2022
2020 PO5151613239	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	6/11/2022
2020 PO4638188186	LGE	4	40 ACE	SP	CCA		V	6/12/2022
2020 PO4638488165	LGE	4	40 ACE	SP	CRE	ED,ID	TD	6/13/2022
2020 PO4638588167	LGE	4	35 ACE	SP	CRE	ED,ID	BD	6/14/2022
2020 PO4331712160	KU	3	40 BRO	SP	CRE		V	6/15/2022
2020 PO4319712059	KU	4	40 BRO	SP	CRE		V	6/16/2022
2020 PO4313412006	KU	4	40 BRO	SP	CRE		V	6/17/2022
2020 PO4299711891	KU	4	40 BRO	SP	CRE		V	6/18/2022
2020 PO4231011913	KU	4	40 BRO	SP	CRE		V	6/19/2022
2020 PO4225311980	KU	4	40 BRO	SP	CRE		V	6/20/2022
2020 PO4220412042	KU	4	40 BRO	SP	CRE		V	6/21/2022
2020 PO4225712189	KU	4	40 BRO	SP	CRE		V	6/22/2022
2020 PO4203712256	KU	4	40 BRO	SP	CRE		V	6/23/2022

2020 PO4772188817	LGE	4	40 BRN	SP	CRE	ED,ID	BD		6/24/2022
2020 PO4766688851	LGE	4	40 BRN	SP	CRE	ED,HH,ID	VX	PX	6/25/2022
2020 PO4766388831	LGE	4	35 BRN	SP	A	ED,ID	TD		6/26/2022
2020 PO4766088838	LGE	4	30 BRN	SP	A	ED,ID	BD		6/27/2022
2020 PO4587312268	KU	1	70 BRO	SP	CRE	ED,ID	BD		6/28/2022
2020 PO4563012891	KU	5	30 BRO	SP	CRE	ED,ID,IP,RB	X	RP2	6/29/2022
2020 PO4838729765	KU	4	40 BRO	SP	CRE		V		6/30/2022
2020 PO4842929845	KU	4	40 BRO	SP	CRE		V		7/1/2022
2020 PO4039082957	LGE	4	40 BRO	SP	CRE	ED,ID	TD		7/2/2022
2020 PO4767088821	LGE	4	30 BRN	SP	CRE	ED,ID	BD		7/3/2022
2020 PO4767788809	LGE	4	30 BRN	SP	CRE	ED,ID	BD		7/4/2022
2020 PO4037882954	LGE	4	40 BRO	SP	P	ED,ID	BD		7/5/2022
2020 PO4041082968	LGE	4	40 BRO	SP	P	ED,ID	TD		7/6/2022
2020 PO4042182974	LGE	4	40 BRO	SP	CRE	ED,ID	TD		7/7/2022
2020 PO4042582988	LGE	4	35 BRO	SP	P	ED,ID	TD		7/8/2022
2020 PO4043082979	LGE	4	40 BRO	SP	P	ED,ID	TD		7/9/2022
2020 PO4043482993	LGE	4	40 BRO	SP	CRE		V		7/10/2022
2020 PO4043882983	LGE	4	30 BRO	SP	P	ED,ID	BD		7/11/2022
2020 PO4686015135	KU	3	45 BRO	SP	CCA		V		7/12/2022
2020 PO4707114804	KU	6	30 BRO	SP	CRE		V		7/13/2022
2020 PO4715214773	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		7/14/2022
2020 PO4712714581	KU	6	30 BRO	SP	CRE	ID,IP	BD		7/15/2022
2020 PO4828115127	KU	6	30 BRO	SP	CRE	ED,ID	TD		7/16/2022
2020 PO4776315029	F	6	35 BRO	SP	CRE		V		7/17/2022
2020 PO4791915075	KU	3	45 BRO	SP	CCA		V		7/18/2022
2020 PO4802015036	F	4	35 BRO	SP	A		V		7/19/2022
2020 PO4801914869	KU	3	45 BRO	SP	CCA		V		7/20/2022
2020 PO4896114916	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		7/21/2022
2020 PO4868414750	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		7/22/2022
2020 PO0719247775	KU	4	40 BRN	SP	CRE	ID,IP	BD		7/23/2022
2020 PO0713347826	KU	4	45 BRN	SP	CRE		V		7/24/2022
2020 PO0728548153	KU	4	40 BRN	SP	CRE	ID,IP	BD		7/25/2022
2020 PO0728548020	KU	5	35 BRN	SP	CRE		V		7/26/2022
2020 PO0743448183	KU	4	45 BRN	SP	CRE		V		7/27/2022
2020 PO0772847996	KU	4	40 BRN	SP	CRE		V		7/28/2022
2020 PO0660548456	KU	4	40 BRN	SP	CRE	ED,ID	TD		7/29/2022
2020 PO0686348314	KU	4	40 BRN	SP	CRE	ID	BD		7/30/2022
2020 PO0700548364	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		7/31/2022
2020 PO0713048567	KU	4	40 BRN	SP	CRE	ED,ID	TD		8/1/2022
2020 PO0732948462	KU	4	40 BRN	SP	CRE	ID	BD		8/2/2022
2020 PO0725448783	KU	4	40 BRN	SP	CRE	ID,IP	BD		8/3/2022
2020 PO0688149092	KU	4	40 BRN	SP	CRE	HH,ID,IP	TD		8/4/2022
2020 PO0708548954	KU	4	40 BRN	SP	CCA		V		8/5/2022
2020 PO3773451384	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD		8/6/2022
2020 PO3788751570	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD		8/7/2022
2020 PO3798251740	KU	2	50E OTH	SP	CRE	HH,ID,SRS	TD		8/8/2022
2020 PO3804851682	KU	4	45 OTH	SP	CRE	ED,ID,SRS	TD		8/9/2022

2020 PO4777288739	LGE	4	40 BRN	SP	P	ED,ID,IP	TD	8/10/2022	
2020 PO1547733512	F	4	40 XXX	SP	A		V	8/11/2022	
2020 PO1549933562	F	4	40 XXX	SP	A		V	8/12/2022	
2020 PO1567533463	ODP	5	35 XXX	SP	CCA		V	8/13/2022	
2020 PO1571933371	ODP	5	35 XXX	SP	CRE	ID	BD	8/14/2022	
2020 PO1575433228	ODP	4	50 XXX	SP	CRE	ID	TD	8/15/2022	
2020 PO1653730921	ODP	5	35 XXX	SP	CCA		V	8/16/2022	
2020 PO1670130883	F	4	40 XXX	SP	A		V	8/17/2022	
2020 PO1683030911	ODP	5	35 XXX	SP	CRE	ID	TD	8/18/2022	
2020 PO1682630398	ODP	6	35 XXX	SP	CRE	ED,ID	TD	8/19/2022	
2020 PO1684930744	ODP	5	35 XXX	SP	CRE	ID	TD	8/20/2022	
2020 PO1703130820	ODP	6	30 XXX	SP	CRE	ID	TD	8/21/2022	
2020 PO1711930858	ODP	4	35 XXX	SP	CRE	ID,IP	TX	RR	8/22/2022
2020 PO3776351830	KU	3	45E OTH	SP	CRE	ED,ID,SRS	TD	8/23/2022	
2020 18525-412038	ODP	5	30 KOP	SP	A		V	8/24/2022	
2020 PO3952881905	LGE	4	35 BRN	SP	A	ED,ID	TD	8/25/2022	
2020 PO3954081904	LGE	4	35 BRN	SP	CRE	ED,ID	TD	8/26/2022	
2020 PO3955381905	LGE	4	35 BRN	SP	P	ED,ID	TD	8/27/2022	
2020 PO3955681897	LGE	4	35 BRN	SP	CCA	ED,ID	BD	8/28/2022	
2020 PO3956081903	LGE	4	40 BRN	SP	CCA		V	8/29/2022	
2020 PO2539027255	ODP	4	40 BRN	SP	CRE	ID	TD	8/30/2022	
2020 PO3870482924	LGE	4	35 BRO	ST	CCA		V	8/31/2022	
2020 PO3870482956	LGE	3	45 BRO	SP	CCA		V	9/1/2022	
2020 PO3870782977	LGE	3	35 BRO	SP	CRE	ED,ID	TD	9/2/2022	
2020 PO3871182956	LGE	2	65 BRO	SP	CCA		V	9/3/2022	
2020 PO3870982966	LGE	4	40 BRO	SP	P		T	9/4/2022	
2020 PO3871382945	LGE	4	40 BRO	SP	A	ED,ID	TD	9/5/2022	
2020 PO3871582933	LGE	2	65 BRO	SP	CRE		V	9/6/2022	
2020 PO3870383000	LGE	2	65 BRO	SP	CCA		V	9/7/2022	
2020 PO3869583040	LGE	2	65 BRO	SP	CCA		V	9/8/2022	
2020 PO3869283055	LGE	2	65 BRO	SP	CCA		V	9/9/2022	
2020 PO3780851935	KU	2	50 OTH	SP	CRE	ID	BD	9/10/2022	
2020 PO3771851924	F	5	35 OTH	SP	CRE	ED,ID	BX	PX	9/11/2022
2020 PO3768851865	F	5	35E OTH	SP	CRE		V	9/12/2022	
2020 PO3703051795	KU	4	40 OTH	SP	CCA		V	9/13/2022	
2020 PO4630911546	KU	4	40 BRO	SP	CRE	ID,IP	BD	9/14/2022	
2020 PO4634488258	LGE	3	45 BRO	SP	CCA		V	9/15/2022	
2020 PO4634588268	LGE	4	40 BRO	SP	CCA		V	9/16/2022	
2020 PO4634688277	LGE	4	40 BRO	SP	CRE	ED,HH,ID,RB	VX	PX	9/17/2022
2020 PO4632288270	LGE	4	40 BRO	SP	CRE	ED,ID	BD	9/18/2022	
2020 PO0379338984	ODP	2	65 XXX	SP	CCA		V	9/19/2022	
2020 PO4777888779	LGE	4	40 BRN	SP	CRE		VX	RP3	9/20/2022
2020 PO4636211381	KU	4	40 BRO	SP	CRE		V	9/21/2022	
2020 PO4654911269	KU	4	40 BRO	SP	CRE		V	9/22/2022	
2020 PO4777588785	LGE	4	40 BRN	SP	A	ED,ID	BD	9/23/2022	
2020 PO6078566313	KU	4	40 OTH	SP	CRE	ID	TD	9/24/2022	
2020 PO6090266335	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	9/25/2022	

2020 PO3727551552	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	9/26/2022
2020 PO3727051476	F	5	35 OTH	SP	P		V	9/27/2022
2020 PO3709051499	KU	3	40 OTH	SP	CRE	ED,ID,SRS	TD	9/28/2022
2020 PO3709751425	F	3	40E OTH	SP	P		V	9/29/2022
2020 PO3713751206	KU	3	40 BRN	SP	CRE	ED,ID,SRS	TD	9/30/2022
2020 PO3700151332	KU	4	35 BRN	SP	CCA	ED,ID,SRS	TD	10/1/2022
2020 PO3697551474	KU	4	40 BRN	DF	CRE	ED,ID,SRS	TD	10/2/2022
2020 PO3693251707	KU	5	35 BRN	DF	CRE	ED,ID,SRS	TD	10/3/2022
2020 PO3679851596	KU	5	35 BRN	SP	CRE	ED,ID,SRS	TD	10/4/2022
2020 PO3697751295	KU	6	30 BRN	SP	CCA		V	10/5/2022
2020 PO3686251261	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD	10/6/2022
2020 PO3681451374	F	5	35 OTH	SP	P		V	10/7/2022
2020 PO3679851447	KU	3	40 OTH	SP	CRE	ED,ID,SRS	TD	10/8/2022
2020 PO3662451429	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	10/9/2022
2020 PO3648951254	KU	6	30 BRN	SP	CCA	ED,SRS	TD	10/10/2022
2020 PO3664651249	KU	5	35 BRN	SP	CRE	ED,ID,SRS	TD	10/11/2022
2020 PO3663051356	KU	5	35 BRN	SP	CCA		V	10/12/2022
2020 PO4625412254	F	4	40 BRO	SP	CRE		V	10/13/2022
2020 PO4616212291	F	4	40 BRO	SP	CRE		V	10/14/2022
2020 PO4611912456	F	4	40 BRO	SP	CRE		V	10/15/2022
2020 PO4604012748	F	4	40 BRO	SP	CRE		V	10/16/2022
2020 PO4639112990	F	4	40 BRO	SP	CRE		V	10/17/2022
2020 PO4604612885	F	4	40 BRO	SP	CRE	HH,RB	VX	RP1 10/18/2022
2020 PO4605613013	F	4	40 BRO	SP	CRE		V	10/19/2022
2020 PO4608513167	F	4	40 BRO	SP	CCA		V	10/20/2022
2020 PO4612513315	F	4	40 BRO	SP	CRE		V	10/21/2022
2020 PO4854586582	LGE	2	50 XXX	SP	P	ID	BD	10/22/2022
2020 PO4854186576	LGE	2	50 XXX	SP	P	ID	BD	10/23/2022
2020 PO4647588995	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TX	RR 10/24/2022
2020 PO5886575953	LGE	1	55 OTH	SP	CCA		V	10/25/2022
2020 PO4874887757	LGE	4	45 XXX	SP	CRE	ID,RB	BX	PX 10/26/2022
2020 PO4874187775	LGE	4	35 XXX	SP	A	ID	BD	10/27/2022
2020 PO4872787787	LGE	4	30 XXX	SP	A	ED,ID	TD	10/28/2022
2020 PO4866287759	F	4	35 XXX	SP	CCA		V	10/29/2022
2020 PO4869587775	LGE	4	35 XXX	SP	CCA		V	10/30/2022
2020 PO4872387770	LGE	1	50 XXX	SP	CCA		V	10/31/2022
2020 PO4871687767	LGE	3	50 XXX	SP	A	ID	BD	11/1/2022
2020 PO4870787765	LGE	1	50 XXX	SP	CCA		V	11/2/2022
2020 PO4937687029	LGE	3	50 OTH	SP	P	ID	BD	11/3/2022
2020 PO4928286903	LGE	4	35 OTH	AL	CCA		V	11/4/2022
2020 PO4926386885	LGE	4	35 OTH	SP	CCA		V	11/5/2022
2020 PO4925286888	LGE	4	30 OTH	AL	CCA		V	11/6/2022
2020 PO4918087096	LGE	3	45 OTH	AL	CCA		V	11/7/2022
2020 PO4877887379	LGE	4	40 XXX	SP	A		V	11/8/2022
2020 PO4850687032	LGE	1	85 XXX	SP	CRE		V	11/9/2022
2020 PO4851887042	LGE	4	30 XXX	SP	CRE	ID	BD	11/10/2022
2020 4850987042a	LGE	5	30 XXX	SP	CCA		V	11/11/2022

2020 PO4850987042	F	1	70 XXX	SP	CCA		V			11/12/2022
2020 PO4851287054	LGE	4	40 XXX	SP	A	ED,ID	TD			11/13/2022
2020 PO4804487866	LGE	4	40 BRN	SP	CRE	ED,HH,ID	BX	RP2		11/14/2022
2020 PO4649488902	LGE	4	40 OTH	SP	P	ED,ID	X	RP3		11/15/2022
2020 PO4661689106	LGE	4	40 KOP	SP	CRE	ED,ID	TD			11/16/2022
2020 PO4662689105	LGE	UNK	25 KOP	SP	CRE	ED,ID	TD			11/17/2022
2020 PO4684789248	LGE	3	50 XXX	SP	CRE	ID	BD			11/18/2022
2020 PO4674089259	LGE	5	35 XXX	SP	A	ID	BD			11/19/2022
2020 PO4650188908	LGE	4	40 OTH	SP	CCA		V			11/20/2022
2020 PO4651088914	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD			11/21/2022
2020 PO4651888920	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD			11/22/2022
2020 PO4684489266	LGE	3	45 BRN	SP	CCA		V			11/23/2022
2020 PO4651488874	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD			11/24/2022
2020 PO4653088886	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD			11/25/2022
2020 PO4649888862	LGE	4	40 OTH	SP	CRE	ID	V			11/26/2022
2020 PO4661089093	LGE	4	30 KOP	SP	CRE	ED,ID	TD			11/27/2022
2020 PO4660689099	LGE	4	35 KOP	SP	CRE	ID	BD			11/28/2022
2020 PO4659989093	LGE	4	40 KOP	SP	S		V			11/29/2022
2020 PO3680703505	LGE	4	30 KOP	SP	CRE	ED,ID	TD			11/30/2022
2020 PO4659189086	LGE	4	35 KOP	SP	CRE	ID	BD			12/1/2022
2020 PO4646188816	LGE	4	35 OTH	SP	CRE	ED,ID,SRS	TD			12/2/2022
2020 PO1779922876	ODP	6	30 XXX	SP	CRE		V			12/3/2022
2020 PO4442038530	KU	4	45 BRO	SP	CRE	ID,IP	BD			12/4/2022
2020 PO2176244019	ODP	4	45 KOP	SP	CRE	ED,ID,IP	TD			12/5/2022
2020 PO2174143833	ODP	5	35 KOP	SP	S		V			12/6/2022
2020 PO2187943721	ODP	6	30 KOP	SP	CRE	ED,ID	TD			12/7/2022
2020 PO2165343904	ODP	4	40 KOP	SP	CRE	ED,ID	TD			12/8/2022
2020 PO2142643638	ODP	5	35 KOP	SP	CRE	ED,ID	TD			12/9/2022
2020 PO2130043491	ODP	4	40 KOP	SP	S		V			12/10/2022
2020 PO2109243321	ODP	4	45 KOP	SP	CRE	ED,ID,IP	TD			12/11/2022
2020 PO3951982499	LGE	5	25 BRN	SP	CRE	ED,ID	TD			12/12/2022
2020 PO3950582467	F	4	30 BRN	SP	CRE		V			12/13/2022
2020 PO3951382468	F	3	45 BRN	SP	CCA		V			12/14/2022
2020 PO3952382475	F	4	35 BRN	SP	A		V			12/15/2022
2020 PO3951982476	LGE	4	40 BRN	SP	S		V			12/16/2022
2020 PO3952582489	F	4	40 BRN	SP	CRE		V			12/17/2022
2020 PO4447138607	KU	4	45 BRO	SP	CRE	ID,IP	BD			12/18/2022
2020 PO3952882496	F	4	40 BRN	SP	CRE		V			12/19/2022
2020 PO3952782514	F	5	25 BRN	SP	A		V			12/20/2022
2020 PO3953482505	F	4	40 BRN	SP	A		V			12/21/2022
2020 PO5640746164	C	6	30 ACE	ST	CCA		V			12/22/2022
2020 PO5823244493	KU	4	45 ACE	ST	CCA		V			12/23/2022
2020 PO5832844640	KU	6	30 ACE	SP	CCA		V			12/24/2022
2020 PO5792746468	KU	4	45 ACE	SP	CRE	ED,ID	BD			12/25/2022
2020 PO9526194172	KU	4	40 ACW	SP	CRE	ED,ID	BD			12/26/2022
2020 PO3953882501	F	4	30 BRN	SP	A		V			12/27/2022
2020 PO3954382519	F	4	30 BRN	SP	CRE		V			12/28/2022

2020 PO2132541921	ODP	4	45 KOP	SP	CRE	ED,ID	TD	12/29/2022
2020 PO2142441838	ODP	6	30 KOP	SP	S		V	12/30/2022
2020 PO3954682510	F	4	40 BRN	SP	A		V	12/31/2022
2020 PO3955282543	F	4	35 BRN	SP	CRE		V	1/1/2023
2020 PO3956082536	LGE	4	40 BRN	SP	S		V	1/2/2023
2020 PO3955782522	F	4	30 BRN	SP	CRE		V	1/3/2023
2020 PO3956182523	F	3	45 BRN	SP	S		V	1/4/2023
2020 PO3957182510	LGE	4	30 BRN	SP	CRE		V	1/5/2023
2020 PO3956382509	F	4	40 BRN	SP	A		V	1/6/2023
2020 PO3957582495	F	4	30 BRN	SP	A		V	1/7/2023
2020 PO3956482495	F	4	40 BRN	SP	CRE		V	1/8/2023
2020 PO4598738940	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	1/9/2023
2020 PO4611238825	KU	4	40 BRO	SP	CRE	ID,IP	BD	1/10/2023
2020 PO1363620427	ODP	5	35 XXX	SP	CRE	ID	TD	1/11/2023
2020 PO1378220245	ODP	5	35 XXX	SP	CRE	ID	TD	1/12/2023
2020 PO1340420451	ODP	6	30 XXX	SP	CRE	ID	TD	1/13/2023
2020 PO9523194165	KU	4	45 ACW	SP	CRE	ED,ID	TD	1/14/2023
2020 PO0514936143	ODP	4	45 BRN	SP	CCA		V	1/15/2023
2020 PO0486236184	ODP	6	30 BRN	SP	CCA		V	1/16/2023
2020 PO0465835527	ODP	6	30 BRN	SP	CCA		V	1/17/2023
2020 PO0436735225	ODP	6	30 BRN	SP	CCA		V	1/18/2023
2020 PO3957182480	F	4	30 BRN	SP	A		V	1/19/2023
2020 PO3956182483	F	4	40 BRN	SP	A		V	1/20/2023
2020 PO3955682483	F	4	30 BRN	SP	CRE		V	1/21/2023
2020 PO3955582470	F	4	40 BRN	SP	A		V	1/22/2023
2020 PO3955082470	F	4	30 BRN	SP	A		V	1/23/2023
2020 PO3955082458	F	3	45 BRN	SP	CCA		V	1/24/2023
2020 PO3954482457	F	4	30 BRN	SP	CRE		V	1/25/2023
2020 PO3955682429	F	6	25 BRN	SP	CRE		V	1/26/2023
2020 PO3955882440	F	4	40 BRN	SP	CRE		V	1/27/2023
2020 PO3954282433	F	6	25 BRN	SP	CRE		V	1/28/2023
2020 PO3954482444	F	4	40 BRN	SP	CRE		V	1/29/2023
2020 PO1680322978	ODP	5	35 XXX	SP	CCA		V	1/30/2023
2020 PO1691023000	ODP	6	30 XXX	SP	CRE	ED,ID,IP	TD	1/31/2023
2020 PO3950882441	LGE	6	30 BRN	SP	CRE	ED,ID	TD	2/1/2023
2020 PO3953182447	F	4	40 BRN	SP	A		V	2/2/2023
2020 PO3951782450	F	4	40 BRN	SP	A		V	2/3/2023
2020 PO3951182451	F	4	40 BRN	SP	A		V	2/4/2023
2020 PO2134441551	ODP	6	30 KOP	SP	S		V	2/5/2023
2020 PO2144241487	F	4	40 KOP	SP	CCA		V	2/6/2023
2020 PO2151841697	F	4	40 KOP	SP	CCA		V	2/7/2023
2020 PO2158641873	ODP	4	45 KOP	SP	A	ID	BD	2/8/2023
2020 PO4790132302	KU	3	45 BRN	SP	CRE	HH,ID,IP,RB	BX	2/9/2023
2020 PO4816132152	KU	4	40 BRN	SP	CRE		V	2/10/2023
2020 PO2535627349	ODP	4	40 BRN	SP	CRE	ID	TD	2/11/2023
2020 PO2619127546	ODP	5	35 BRN	SP	CRE	ID	TD	2/12/2023
2020 PO2666527697	ODP	6	30 BRN	SP	CRE	ID	TD	2/13/2023

Business Use

2020 PO4602930111	KU	4	40 ACE	SP	CRE		V	2/14/2023
2020 PO4803132227	KU	2	50 BRN	SP	CCA		V	2/15/2023
2020 PO4782232035	KU	4	40 BRN	SP	CRE	ID	BD	2/16/2023
2020 PO4618638757	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	2/17/2023
2020 PO3947182469	LGE	5	25 BRN	SP	CRE	ED,ID	TD	2/18/2023
2020 PO3949682461	F	4	30 BRN	SP	CRE		V	2/19/2023
2020 PO3949782455	F	4	40 BRN	SP	CRE		V	2/20/2023
2020 PO9577594140	KU	4	40 ACW	SP	CRE	ED,ID	TD	2/21/2023
2020 PO9544794174	KU	4	30 ACW	SP	CRE	ED,ID	TD	2/22/2023
2020 PO4733722189	KU	3	45 BRO	SP	CCA		V	2/23/2023
2020 PO9550194066	KU	5	45 ACW	SP	CRE	ED,ID	TD	2/24/2023
2020 PO9552494197	KU	4	40 ACW	SP	CRE	ED,EP,ID,RB,SRS	TX RR	2/25/2023
2020 PO9556094107	KU	4	40 ACW	SP	CRE	ED,EP,ID,RB,SR	TX RR	2/26/2023
2020 PO9562393950	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	2/27/2023
2020 PO4709622415	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	2/28/2023
2020 PO4721822236	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	3/1/2023
2020 PO4701122232	C	4	40 BRO	SP	CRE		V	3/2/2023
2020 PO475522098	KU	3	50 BRO	SP	CCA		V	3/3/2023
2020 PO4774422080	KU	2	50 BRO	SP	CCA		V	3/4/2023
2020 PO4747722368	KU	3	45 BRO	SP	CCA		V	3/5/2023
2020 PO3948182450	F	6	30 BRN	SP	CRE		V	3/6/2023
2020 PO3948382458	F	4	40 BRN	SP	S		V	3/7/2023
2020 PO0503536387	ODP	5	30 BRN	SP	CCA		V	3/8/2023
2020 PO0507736334	ODP	4	45 BRN	SP	CCA		V	3/9/2023
2020 PO1711822953	ODP	6	30 XXX	SP	CRE	ID	TD	3/10/2023
2020 PO1712123003	ODP	6	30 XXX	SP	CRE	ID,IP	TD	3/11/2023
2020 PO3946882464	F	6	25 BRN	SP	CRE		V	3/12/2023
2020 PO3947682462	F	4	40 BRN	SP	CRE		V	3/13/2023
2020 PO3948082465	F	4	40 BRN	SP	CRE		V	3/14/2023
2020 PO1349320346	ODP	4	40 XXX	SP	CRE	ID	TD	3/15/2023
2020 PO1332120373	F	4	40 XXX	SP	A		V	3/16/2023
2020 PO1321620120	ODP	4	40 XXX	SP	CRE	ID	TD	3/17/2023
2020 PO1364420123	ODP	6	35 XXX	SP	CRE	ID	TD	3/18/2023
2020 PO1345020084	F	4	40 XXX	SP	A		V	3/19/2023
2020 PO1344519878	ODP	5	35 BRN	SP	CCA		V	3/20/2023
2020 PO1332620560	F	4	40 XXX	SP	CRE	ED	V	3/21/2023
2020 PO1324420482	F	4	40 XXX	SP	A		V	3/22/2023
2020 PO1329520644	ODP	6	30 XXX	SP	CRE	ID	BD	3/23/2023
2020 PO1325720714	ODP	5	30 XXX	SP	CRE	ID	TD	3/24/2023
2020 PO1316120739	ODP	4	45 XXX	SP	CRE	ID	TD	3/25/2023
2020 PO1299320685	ODP	4	40 XXX	SP	CRE	ID	TD	3/26/2023
2020 PO3948682479	F	4	40 BRN	SP	CRE		V	3/27/2023
2020 PO3949182479	F	4	30 BRN	SP	CRE		V	3/28/2023
2020 PO3949682491	F	4	30 BRN	SP	CCA		V	3/29/2023
2020 PO3949282491	F	4	40 BRN	SP	CCA		V	3/30/2023
2020 PO0578336198	ODP	6	30 BRN	SP	CRE	ED,ID	TD	3/31/2023
2020 PO0571936175	ODP	5	35 XXX	SP	CRE	ED,ID	TD	4/1/2023

2020 PO0568636246	ODP	5	35 XXX	SP	CRE	ED,ID	TD	4/2/2023
2020 PO0551036197	F	4	40 XXX	SP	A		V	4/3/2023
2020 PO0558136264	ODP	4	40 XXX	SP	CCA		V	4/4/2023
2020 PO0533536248	F	4	40 XXX	SP	A		V	4/5/2023
2020 PO4546529745	KU	2	50 ACE	SP	CRE	ED,ID	TD	4/6/2023
2020 PO4534229659	KU	3	45 ACE	SP	CRE	ED,ID	TD	4/7/2023
2020 PO3950282504	F	4	30 BRN	SP	CRE		V	4/8/2023
2020 PO3949782504	F	4	40 BRN	SP	CRE		V	4/9/2023
2020 PO4317988162	LGE	2	55 ACW	SP	S		V	4/10/2023
2020 PO4319188161	LGE	2	55 ACW	SP	CRE	ID,IP	BD	4/11/2023
2020 PO3643711263	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/12/2023
2020 PO3626811624	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/13/2023
2020 PO3152036261A	KU	4	45 XXX	SP	P	ID	BD	4/14/2023
2020 PO3151636297	KU	2	55 XXX	SP	CRE	ID	BD	4/15/2023
2020 PO3152036261	KU	2	55 XXX	SP	CRE	ID	BD	4/16/2023
2020 PO3122736341	KU	2	60 XXX	SP	CRE		V	4/17/2023
2020 PO3123036309	KU	2	60 XXX	SP	CRE		V	4/18/2023
2020 PO3094336331	KU	2	60 XXX	SP	CRE	ID	BD	4/19/2023
2020 PO3094736288	KU	3	45 XXX	SP	CRE	ID	BD	4/20/2023
2020 PO3024336378	KU	2	60 XXX	SP	CRE	ID	BD	4/21/2023
2020 PO3024436330	KU	2	60 XXX	SP	CRE	ID	BD	4/22/2023
2020 PO1899631771	KU	2	70 XXX	SP	CRE	ID	BD	4/23/2023
2020 PO3961482440	LGE	4	35 BRN	SP	A	ED,ID	TD	4/24/2023
2020 PO1275730348	ODP	6	30 XXX	SP	CRE	ID,IP	TD	4/25/2023
2020 PO3963082446	LGE	4	40 BRN	SP	CRE	ED,ID	BD	4/26/2023
2020 PO4076483362	LGE	4	40 BRN	SP	CRE	ED,ID	TD	4/27/2023
2020 PO4074983349	LGE	4	40 BRN	SP	CCA		V	4/28/2023
2020 PO4075683382	LGE	4	40 BRN	SP	CRE		V	4/29/2023
2020 PO4078183378	LGE	4	30 BRN	SP	CRE	ED,ID	BD	4/30/2023
2020 PO4077983375	LGE	4	40 BRN	SP	CRE		B	5/1/2023
2020 PO4076583392	LGE	4	40 BRN	SP	CRE	ED,ID	BD	5/2/2023
2020 PO4076883395	LGE	4	30 BRN	SP	P	ED,ID	BD	5/3/2023
2020 PO4075483419	LGE	7	25 BRN	SP	CRE	ED,ID	BD	5/4/2023
2020 PO4074883416	LGE	4	40 BRN	SP	CCA		V	5/5/2023
2020 PO4071883434	LGE	4	40 BRN	SP	CCA		V	5/6/2023
2020 PO3962982473	LGE	4	30 BRN	SP	CRE	ED,ID	TD	5/7/2023
2020 PO3962082452	LGE	4	40 BRN	SP	A	ED,ID	TD	5/8/2023
2020 PO3963282486	LGE	4	35 BRN	SP	S		V	5/9/2023
2020 PO3962682486	F	3	40 BRN	SP	CRE	ED,ID	VX	PX 5/10/2023
2020 PO1216830989	ODP	6	30 XXX	SP	CRE	ID	TD	5/11/2023
2020 PO3961382456	F	3	45 BRN	SP	S		V	5/12/2023
2020 PO3961982470	F	3	45 BRN	SP	S		V	5/13/2023
2020 PO3962282460	F	4	30 BRN	SP	CRE		V	5/14/2023
2020 PO3961682454	F	4	40 BRN	SP	CCA		V	5/15/2023
2020 PO1206030753	ODP	4	40 XXX	SP	CRE	ID,IP	TD	5/16/2023
2020 PO1201130712	ODP	4	45 XXX	SP	CCA		V	5/17/2023
2020 PO1903531724	KU	2	70 XXX	SP	CRE	ID	BD	5/18/2023

2020 PO1959532344	KU	2	55 XXX	SP	CRE	ID	BD	5/19/2023
2020 PO4069983464	LGE	4	30 BRN	SP	A	ED,ID	BD	5/20/2023
2020 PO4070183445	LGE	4	40 BRN	SP	CCA		V	5/21/2023
2020 PO1966932296	KU	2	55 XXX	SP	CRE	ID	BD	5/22/2023
2020 PO1991732675	KU	2	60 XXX	SP	CRE	ID	BD	5/23/2023
2020 PO1999832622	KU	2	60 XXX	SP	CRE	ID	BD	5/24/2023
2020 PO2025732991	KU	2	60 XXX	SP	CRE	ID	BD	5/25/2023
2020 PO2033632937	KU	2	60 XXX	SP	CRE	ID	BD	5/26/2023
2020 PO2053333375	KU	2	65 XXX	SP	CRE	ID	BD	5/27/2023
2020 PO2057333301	KU	2	65 XXX	SP	CRE	ID	BD	5/28/2023
2020 PO2062133213	KU	2	65 XXX	SP	CRE	ID	BD	5/29/2023
2020 PO2159733434	KU	2	60 XXX	SP	CRE	ID	BD	5/30/2023
2020 PO2161233331	KU	2	60 XXX	SP	CRE	ID	BD	5/31/2023
2020 PO2205933497	KU	2	60 XXX	SP	CRE	ID	BD	6/1/2023
2020 PO2206833402	KU	2	60 XXX	SP	CRE	ID	BD	6/2/2023
2020 PO3959782287	LGE	4	40 BRN	SP	CRE	ED,ID	BD	6/3/2023
2020 PO3958882302	LGE	4	40 BRN	SP	CRE	ED,ID	TD	6/4/2023
2020 PO1237030053	ODP	4	40 XXX	SP	CRE	ID	TD	6/5/2023
2020 PO1194030649A	ODP	3	45 XXX	SP	CCA		V	6/6/2023
2020 PO3612011942	KU	4	40 BRO	SP	CRE	ID,IP	BD	6/7/2023
2020 PO3595112305	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/8/2023
2020 PO3959482315	LGE	4	40 BRN	SP	CRE	ED,ID	TD	6/9/2023
2020 PO3959482324	LGE	4	40 BRN	SP	CRE	ED,ID	TD	6/10/2023
2020 PO3578212667	KU	2	40 BRO	SP	CRE	ED,ID,IP	TD	6/11/2023
2020 PO3559712738	KU	4	40 BRO	SP	CRE	ID	BD	6/12/2023
2020 PO3452213114	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/13/2023
2020 PO3491913042	KU	4	40 BRO	SP	CRE	ID,IP	BD	6/14/2023
2020 PO3466713402	KU	4	35 BRO	SP	CRE	ED,ID,IP	TD	6/15/2023
2020 PO3483113813	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/16/2023
2020 PO1067831635	ODP	4	40 XXX	SP	CRE	ID	BD	6/17/2023
2020 PO1067131389	ODP	4	40 XXX	SP	CRE	ID	TD	6/18/2023
2020 PO1106931378	ODP	5	35 XXX	SP	CRE	ID	BD	6/19/2023
2020 PO3960182333	LGE	4	30 BRN	SP	CRE	ED,ID	TD	6/20/2023
2020 PO3959882335	LGE	3	45 BRN	SP	A	ED,ID	TD	6/21/2023
2020 PO2256133665	KU	4	40 XXX	SP	CRE	ID	BD	6/22/2023
2020 PO2256733573	KU	2	55 XXX	SP	CRE	ID	BD	6/23/2023
2020 PO2258333480	KU	2	55 XXX	SP	CRE	ID	BD	6/24/2023
2020 PO2328934044A	KU	2	60 XXX	SP	CRE	ID	BD	6/25/2023
2020 PO2328934044	KU	2	60 XXX	SP	CRE	ID	BD	6/26/2023
2020 PO2331333999	KU	2	60 XXX	SP	CRE	HH,ID,IP	BX	RP3 6/27/2023
2020 PO2370034123	KU	2	65 XXX	SP	CRE	HH,ID,IP	BX	RP3 6/28/2023
2020 PO2368534155	KU	2	65 XXX	SP	CRE	ID	BD	6/29/2023
2020 PO2414334229	KU	2	60 XXX	SP	CRE	ID	BD	6/30/2023
2020 PO2413134265	KU	2	60 XXX	SP	CRE	ID	BD	7/1/2023
2020 PO1512721824	ODP	5	35 XXX	SP	CRE	ID	TD	7/2/2023
2020 PO3961383094	LGE	4	30 BRO	SP	CRE	ED,ID	TD	7/3/2023
2020 PO3959983116	LGE	3	45 BRO	SP	CCA		V	7/4/2023

2020 PO3959383110	LGE	3	45 BRO	SP	CRE	ED,ID	TD	7/5/2023
2020 PO9647138928	F	5	30 XXX	SP	CRE		V	7/6/2023
2020 PO1522321390	ODP	3	45 XXX	SP	CCA		V	7/7/2023
2020 PO1517821053	ODP	4	40 XXX	SP	CRE	ID	TD	7/8/2023
2020 PO1339728917	ODP	5	30 BRN	SP	CRE	ID	TD	7/9/2023
2020 PO2157332128	ODP	6	30 UNK	SP	CRE	ED,ID,SRS	TD	7/10/2023
2020 PO2148432223	ODP	5	35 UNK	SP	CRE	ID	TD	7/11/2023
2020 PO3953283093	LGE	4	35 BRO	SP	A	ED,ID	TD	7/12/2023
2020 PO3959383136	LGE	3	45 BRO	SP	P	ED,ID	TD	7/13/2023
2020 PO6784842995	LGE	3	45 BRO	SP	P	ED,ID	TD	7/14/2023
2020 PO6795642909	LGE	3	45 BRO	SP	P	ED,ID	BD	7/15/2023
2020 PO6804942845	LGE	3	45 BRO	SP	P	ED,ID	BD	7/16/2023
2020 PO3900083116	LGE	3	45 BRO	SP	P	ED,ID	TD	7/17/2023
2020 PO3963483116	F	3	50 BRO	SP	CCA		V	7/18/2023
2020 PO1383625396	ODP	4	45 XXX	SP	CCA	ED,SRS	TD	7/19/2023
2020 PO3953883142	F	5	30 BRO	SP	CCA		V	7/20/2023
2020 PO3953983133	F	4	40 BRO	SP	CCA		V	7/21/2023
2020 PO3952383137	F	4	35 BRO	SP	CCA		V	7/22/2023
2020 PO3952783130	F	4	40 BRO	SP	CCA		V	7/23/2023
2020 PO3951383131	F	4	30 BRO	SP	P		V	7/24/2023
2020 PO3951783124	F	4	40 BRO	SP	P		V	7/25/2023
2020 PO3950283125	F	4	30 BRO	SP	CCA		V	7/26/2023
2020 PO3950683117	F	4	40 BRO	SP	P		V	7/27/2023
2020 PO3949283113	F	5	25 BRO	SP	CCA		V	7/28/2023
2020 PO3949983109	F	3	45 BRO	SP	CCA		V	7/29/2023
2020 PO3948583101	F	5	25 BRO	SP	CCA		V	7/30/2023
2020 PO3949283097	F	4	40 BRO	SP	CCA		V	7/31/2023
2020 PO3948983092	F	4	40 BRO	SP	CCA		V	8/1/2023
2020 PO3948283096	F	5	25 BRO	SP	CCA		V	8/2/2023
2020 PO1837034052	ODP	4	40 BRN	SP	CCA		V	8/3/2023
2020 PO1863733650	ODP	4	45 BRN	SP	CRE		V	8/4/2023
2020 PO3947583066	F	4	40 BRO	SP	CCA	ED,HH,IP	VX	8/5/2023
2020 PO3947583081	F	5	25 BRO	SP	CCA	ED,HH,IP	VX	8/6/2023
2020 PO3948283079	F	4	40 BRO	SP	CCA		V	8/7/2023
2020 PO3948283065	F	4	40 BRO	SP	P		V	8/8/2023
2020 PO3948383051	F	4	40 BRO	SP	CCA		V	8/9/2023
2020 PO3947483055	F	4	40 BRO	SP	CRE		V	8/10/2023
2020 PO3945783062	F	4	40 BRO	SP	CCA		V	8/11/2023
2020 PO2000532636	F	4	40 UNK	SP	CRE		V	8/12/2023
2020 PO2107829282	ODP	5	30 UNK	SP	CRE	ID	TD	8/13/2023
2020 PO2122829436	ODP	4	45 BRN	SP	CRE	ID	TD	8/14/2023
2020 PO2119129313	ODP	4	45 UNK	SP	CRE	ED,ID,SRS	TD	8/15/2023
2020 PO2119129313	ODP	4	45 UNK	SP	CRE	ED,ID,SRS	TD	8/16/2023
2020 PO2116829168	F	4	40 SWP	SP	CRE		V	8/17/2023
2020 PO2126029071	ODP	4	40 BRN	SP	CCA		V	8/18/2023
2020 PO2136128989	ODP	5	35 BRN	SP	CRE	ED,ID,SRS	TD	8/19/2023
2020 PO2141629199	ODP	5	35 BRN	SP	CRE		VX	8/20/2023

2020 PO2146529068	ODP	5	35 BRN	SP	CRE	ED,ID,SRS	TD	8/21/2023
2020 PO2152129011	F	4	40 BRN	SP	CRE		V	8/22/2023
2020 PO2160328935	ODP	4	40 BRN	SP	CRE		V	8/23/2023
2020 PO2167029131	ODP	6	30 CAH	SP	CRE	ID	TD	8/24/2023
2020 PO2177228973	ODP	4	45 BRN	SP	CCA		V	8/25/2023
2020 PO2191829102	ODP	3	40 UNK	SP	CRE	ID	TD	8/26/2023
2020 PO2200528998	ODP	6	30 KOP	SP	CRE	ID	TD	8/27/2023
2020 PO2207229086	ODP	6	30 KOP	SP	CRE	ID	TD	8/28/2023
2020 PO2065429484	ODP	4	40 UNK	SP	CRE	ID	BD	8/29/2023
2020 PO3952183071	F	4	30 BRO	SP	CCA		V	8/30/2023
2020 PO3951583084	F	4	40 BRO	SP	CRE		V	8/31/2023
2020 PO3950283092	F	4	40 BRO	SP	CCA		V	9/1/2023
2020 PO8848731770	ODP	4	40 XXX	SP	CRE	ED,ID	TD	9/2/2023
2020 PO3956283110	F	3	30 BRO	SP	CCA		V	9/3/2023
2020 PO3955383111	F	3	45 BRO	SP	CCA		V	9/4/2023
2020 PO3954983102	F	3	45 BRO	SP	CCA		V	9/5/2023
2020 PO3954183090	F	4	40 BRO	SP	CRE		V	9/6/2023
2020 PO3953783078	F	4	40 BRO	SP	CRE		V	9/7/2023
2020 PO3954883086	F	5	30 BRO	SP	CCA		V	9/8/2023
2020 PO3955683098	F	3	35 BRO	SP	CCA		V	9/9/2023
2020 PO3955283142	F	5	25 BRO	SP	CCA		V	9/10/2023
2020 PO3955283134	F	4	40 BRO	SP	P		V	9/11/2023
2020 PO3955283129	F	4	40 BRO	SP	CCA		V	9/12/2023
2020 PO3956683134	F	4	40 BRO	SP	CCA		V	9/13/2023
2020 PO3958083143	F	5	25 BRO	SP	CCA		V	9/14/2023
2020 PO3958083135	F	4	45 BRO	SP	P		V	9/15/2023
2020 PO2072429605	ODP	5	35 BRN	SP	CCA		V	9/16/2023
2020 PO2072029347	ODP	4	40 UNK	SP	CRE	ID	BD	9/17/2023
2020 PO2067029323	ODP	6	30 UNK	SP	CCA	ID	TD	9/18/2023
2020 PO2084429241	ODP	4	40 BRN	SP	CRE		V	9/19/2023
2020 PO8861331931	ODP	4	40 XXX	SP	CCA	ED	T	9/20/2023
2020 PO8826831913	ODP	6	30 XXX	SP	CRE	ED,ID	TD	9/21/2023
2020 PO8842432168	ODP	4	40 XXX	SP	A	ED,ID	TD	9/22/2023
2020 PO8842432168a	ODP	5	35 XXX	SP	CRE	ED,ID,RB	X	9/23/2023
2020 PO8862332076	ODP	4	40 BRN	SP	A	ED,ID	TD	9/24/2023
2020 PO2086029133	ODP	5	35 CAH	SP	CRE		V	9/25/2023
2020 PO2092729207	ODP	4	40 CAH	SP	CRE	ID	TD	9/26/2023
2020 PO2086829310	ODP	4	40 UNK	SP	CRE	ID	TD	9/27/2023
2020 PO2113529276	ODP	4	45 UNK	SP	CRE	ED,ID,SRS	TD	9/28/2023
2020 PO8881431953	F	4	40 BRN	SP	CRE		V	9/29/2023
2020 PO8898831868	ODP	4	40 BRN	SP	CCA		V	9/30/2023
2020 PO8915432116	ODP	6	30 BRN	SP	CCA		V	10/1/2023
2020 PO8934232114	ODP	6	30 BRN	SP	CCA		V	10/2/2023
2020 PO8945932070	ODP	6	30 BRN	SP	CCA		V	10/3/2023
2020 PO8921531723	F	4	40 XXX	SP	A		V	10/4/2023
2020 PO4048082960	LGE	4	40 BRO	SP	CCA	ED,ID	BD	10/5/2023
2020 PO8921531723a	ODP	6	30 XXX	SP	CRE	ED,ID	TD	10/6/2023

2020 PO8952731551	ODP	5	40 XXX	SP	CCA		V			10/7/2023
2020 PO8943331629	ODP	5	30 XXX	SP	CRE		V			10/8/2023
2020 PO3959483143	F	4	30 BRO	SP	CCA		V			10/9/2023
2020 PO8932231336	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD			10/10/2023
2020 PO8958930980	ODP	4	40 XXX	SP	CCA		V			10/11/2023
2020 PO8968831119	F	4	40 XXX	SP	A		V			10/12/2023
2020 PO8988630904	ODP	4	35 XXX	SP	CRE	ED,ID,RB	X	RP1		10/13/2023
2020 PO8982031314	ODP	4	40 XXX	SP	CRE	ED,ID	TD			10/14/2023
2020 PO8977531184	ODP	4	40 XXX	SP	CRE		V			10/15/2023
2020 PO9064930537a	ODP	4	40 XXX	SP	P		V			10/16/2023
2020 PO9064930537	ODP	4	40 XXX	SP	A	ED,ID	TD			10/17/2023
2020 PO9022631123	ODP	5	40 XXX	SP	CCA		V			10/18/2023
2020 PO9049531044	ODP	4	40 XXX	SP	CCA		V			10/19/2023
2020 PO9078230943	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD			10/20/2023
2020 PO9102930767	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD			10/21/2023
2020 PO9130530570	ODP	5	35 XXX	SP	CRE	ED,ID	TD			10/22/2023
2020 PO0708196097	KU	4	45 ACW	SP	CRE	ED,ID	BD			10/23/2023
2020 PO0709095743	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD			10/24/2023
2020 PO0690196958	KU	4	45 ACW	SP	S		V			10/25/2023
2020 PO0662696615	KU	4	40 ACW	SP	S		V			10/26/2023
2020 PO4567004788	KU	6	30 BRO	SP	CRE	ED,ID	TD			10/27/2023
2020 PO4586304660	KU	4	40 BRO	SP	CRE	ED,ID	TD			10/28/2023
2020 PO4578504806	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			10/29/2023
2020 PO4502804774	KU	4	35 BRO	SP	CRE	ED	T			10/30/2023
2020 PO6402047365	KU	4	40 ACE	SP	CRE	ED,ID	TD			10/31/2023
2020 PO0632396439	KU	3	50 ACW	SP	CRE	ED,ID	TD			11/1/2023
2020 PO0708196209	KU	3	45 ACW	SP	S		V			11/2/2023
2020 PO0675696240	KU	2	55 ACW	SP	CRE	ED,EP,ID,IP,SRC	TX	RR		11/3/2023
2020 PO0739196324	KU	3	45 ACW	SP	S		V			11/4/2023
2020 PO0770096438	KU	3	45 ACW	SP	S		V			11/5/2023
2020 PO0801096553	KU	3	45 ACW	SP	S		V			11/6/2023
2020 PO-5819655453B	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD			11/7/2023
2020 PO-5819655453	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD			11/8/2023
2020 PO4664088364	F	4	40 BRN	SP	CRE		V			11/9/2023
2020 PO4664488357	F	3	45 BRN	SP	S		V			11/10/2023
2020 PO4665388344	F	3	40 BRN	SP	CRE		V			11/11/2023
2020 PO4665688332	LGE	4	30 BRN	SP	A	HH,ID	BD			11/12/2023
2020 PO4666288330	F	4	40 BRN	SP	CRE		V			11/13/2023
2020 PO4666688323	F	4	40 BRN	SP	CCA		V			11/14/2023
2020 PO4667288314	F	4	40 BRN	SP	CRE		V			11/15/2023
2020 PO4668388298	F	4	40 BRN	SP	CRE		V			11/16/2023
2020 PO4667988295	LGE	4	30 BRN	SP	P	ED,ID	TD			11/17/2023
2020 PO2222941792	ODP	5	35 KOP	SP	S		V			11/18/2023
2020 PO2818944006	ODP	4	40 KOP	SP	CRE	ED,ID	TD			11/19/2023
2020 PO2845043938	ODP	4	40 KOP	SP	CRE	ED,ID,IP,SRC	TX	RR		11/20/2023
2020 PO2793543865	ODP	5	35 KOP	SP	CRE	ED,ID	TD			11/21/2023
2020 PO4669188285	F	3	45 BRN	SP	S		V			11/22/2023

2020 PO4669788277	F	4	40 BRN	SP	CRE		V	11/23/2023
2020 PO4669888263	LGE	4	30 BRN	SP	P	ED,ID	TD	11/24/2023
2020 PO4670488266	F	4	35 BRN	SP	CRE		V	11/25/2023
2020 PO4672088264	LGE	4	30 BRN	SP	CRE		V	11/26/2023
2020 PO4671088257	F	3	45 BRN	SP	S		V	11/27/2023
2020 PO4166611012	KU	2	45 BRO	SP	CRE	ED,ID,IP	TD	11/28/2023
2020 PO1720332934	ODP	4	40 BRN	SP	CRE	ID	TD	11/29/2023
2020 PO1815531824	ODP	4	45 BRN	SP	CRE		V	11/30/2023
2020 PO1769431866	ODP	6	30 BRN	SP	CCA		V	12/1/2023
2020 PO1780831876	ODP	4	45 BRN	SP	CRE		V	12/2/2023
2020 PO1879831418	ODP	4	40 BRN	SP	CRE	ID	TD	12/3/2023
2020 PO5689750948	F	4	40 ACE	SP	P		V	12/4/2023
2020 PO5633351304	KU	4	40 ACE	SP	CRE	ED,ID	BD	12/5/2023
2020 PO9599793815	KU	6	30 ACW	SP	S		V	12/6/2023
2020 PO9597993903	KU	6	30 ACW	SP	S		V	12/7/2023
2020 PO9596093991	KU	6	30 ACW	SP	S		V	12/8/2023
2020 PO9608094035	KU	6	30 ACW	SP	S		V	12/9/2023
2020 PO9610794099	KU	6	30 ACW	SP	S		V	12/10/2023
2020 PO5647351166	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	12/11/2023
2020 PO9588094158	KU	4	35 ACW	SP	S		V	12/12/2023
2020 PO9594294170	KU	4	40 ACW	SP	CRE	ED,ID	TD	12/13/2023
2020 PO9608294195	KU	3	45 ACW	SP	CCA		V	12/14/2023
2020 PO9572094261	KU	7	25 ACW	SP	CRE	ED,ID	TD	12/15/2023
2020 PO9571994332	KU	3	45 ACW	SP	CRE		V	12/16/2023
2020 PO5624550438	F	4	40 ACE	SP	P		V	12/17/2023
2020 PO5600750535	F	4	40 ACE	SP	P		V	12/18/2023
2020 PO5671952298a	KU	4	40 ACE	SP	CRE	ED,ID	BD	12/19/2023
2020 PO5671952298	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	12/20/2023
2020 PO4016882806	LGE	4	35 BRO	SP	P		V	12/21/2023
2020 PO4009182761	F	4	40 BRO	SP	CCA		V	12/22/2023
2020 PO4055782642	LGE	4	40 BRO	SP	CCA	ED,ID	BD	12/23/2023
2020 PO1540934539	ODP	5	35 BRN	SP	CCA		V	12/24/2023
2020 PO9604194401	KU	4	40 ACW	SP	CRE	ED,ID	TD	12/25/2023
2020 PO9601194396	KU	4	40 ACW	SP	S		V	12/26/2023
2020 PO9591894375	KU	4	40 ACW	SP	CRE	ED,ID	TD	12/27/2023
2020 PO9579194403	KU	5	30 ACW	SP	CRE	ED,ID	TD	12/28/2023
2020 PO5700051937	KU	4	45 ACE	SP	CRE	ED,ID	BD	12/29/2023
2020 PO5665251168	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD	12/30/2023
2020 PO5682151486	KU	4	40 ACE	SP	CRE	ED,ID	BD	12/31/2023
2020 PO5688751615	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	1/1/2024
2020 PO5708752150	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	1/2/2024
2020 PO5708752150	KU	4	40 ACE	SP	CRE	ED,ID	TD	1/3/2024
2020 PO5717752385	KU	3	50 ACE	SP	CCA		V	1/4/2024
2020 PO5699852382	KU	4	45 ACE	SP	CRE	ED,ID	BD	1/5/2024
2020 PO5680752376	KU	4	40 ACE	SP	CRE	ED,ID	BD	1/6/2024
2020 PO1534534626	ODP	2	50 BRN	SP	CCA		V	1/7/2024
2020 PO4377311278	F	4	40 ACE	SP	CCA		V	1/8/2024

2020 PO4366911352	F	4	40 ACE	SP	CCA		V		1/9/2024
2020 PO4721588590	LGE	4	40 BRN	SP	S		V		1/10/2024
2020 PO4721888618	LGE	4	40 BRN	SP	A	ED,ID	BD		1/11/2024
2020 PO4355211440	F	2	50 ACE	SP	CCA		V		1/12/2024
2020 PO3929382780	F	4	40 BRO	SP	CRE	ED,ID,IP	BX	PX	1/13/2024
2020 PO3502013242	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD		1/14/2024
2020 PO3567913330	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		1/15/2024
2020 PO4744109477	F	4	40 ACE	SP	P		V		1/16/2024
2020 PO4752009364	F	3	45 ACE	SP	CCA		V		1/17/2024
2020 PO4740809128	F	4	40 ACE	SP	CRE		V		1/18/2024
2020 PO4735008920	F	4	40 ACE	SP	CRE		V		1/19/2024
2020 PO4716608865	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX	1/20/2024
2020 PO3956282340	LGE	3	40 BRN	SP	CRE	ED,ID	TD		1/21/2024
2020 PO3956882338	LGE	4	30 BRN	SP	CRE		VX	RP3	1/22/2024
2020 PO3957682371	LGE	4	40 BRN	SP	CRE	ED,ID	TD		1/23/2024
2020 PO4711608754	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX	1/24/2024
2020 PO3544113298	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		1/25/2024
2020 PO3479713213	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		1/26/2024
2020 PO3573112998	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD		1/27/2024
2020 PO3595213366	KU	4	40 BRO	SP	CRE	ID,IP	BD		1/28/2024
2020 PO4729308555	KU	3	45 ACE	SP	CCA		V		1/29/2024
2020 PO4741608506	F	2	50 ACE	SP	CRE		V		1/30/2024
2020 PO4752608762	F	3	45 ACE	SP	CRE		V		1/31/2024
2020 PO4754808810	KU	3	45 ACE	SP	CRE	ED,ID,IP	BD		2/1/2024
2020 PO3958082367	LGE	4	30 BRN	SP	S		V		2/2/2024
2020 PO4709308420	F	4	40 ACE	SP	CRE	ED,ID	V		2/3/2024
2020 PO4716408418	F	4	40 ACE	SP	CRE	ED	V		2/4/2024
2020 PO4726508340	F	3	45 ACE	SP	CRE	ED	V		2/5/2024
2020 PO4733208308	F	3	45 ACE	SP	P		V		2/6/2024
2020 PO4734608251	KU	5	35 ACE	SP	CRE		V		2/7/2024
2020 PO3927782737	F	4	35 BRO	SP	CCA		V		2/8/2024
2020 PO3927482739	F	4	40 BRO	SP	CCA		V		2/9/2024
2020 PO3927082722	F	4	35 BRO	SP	CCA		V		2/10/2024
2020 PO3926682722	F	4	40 BRO	SP	CCA		V		2/11/2024
2020 PO3927882748	LGE	4	40 BRO	SP	P	ED	T		2/12/2024
2020 PO3926982692	F	3	50 BRO	SP	CCA		V		2/13/2024
2020 PO3925682698	F	3	50 BRO	SP	CRE		V		2/14/2024
2020 PO3925882706	F	4	40 BRO	SP	CCA		V		2/15/2024
2020 PO3927082697	F	4	30 BRO	SP	CCA		V		2/16/2024
2020 PO3928582692	F	4	40 BRO	SP	CCA		V		2/17/2024
2020 PO3929282707	F	4	40 BRO	SP	CCA	ED	VX	RP3	2/18/2024
2020 PO3929782717	F	4	40 BRO	SP	CCA		V		2/19/2024
2020 PO3930882739	F	4	40 BRO	SP	CCA		V		2/20/2024
2020 PO3930382728	F	4	40 BRO	SP	CCA		V		2/21/2024
2020 PO3931382749	F	4	40 BRO	SP	CCA		V		2/22/2024
2020 PO3959282393	LGE	4	30 BRN	SP	A	ED,ID	TD		2/23/2024
2020 PO3958682379	LGE	4	30 BRN	SP	S		V		2/24/2024

2020 PO3958282385	LGE	4	40 BRN	SP	CRE	ED,ID	TD	2/25/2024
2020 PO3959882407	LGE	4	30 BRN	SP	A	ED,ID	TD	2/26/2024
2020 PO4506535895	KU	5	35 ACE	SP	CRE		V	2/27/2024
2020 PO3726813543	KU	4	40 BRO	SP	CRE	ID,IP	BD	2/28/2024
2020 PO4863702663	KU	3	45 BRO	SP	CRE	ED,ID	TD	2/29/2024
2020 PO4847902906	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	3/1/2024
2020 PO4882002720	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	3/2/2024
2020 PO3946634015	KU	4	45 ACE	SP	CCA	ED,ID	BD	3/3/2024
2020 PO4849201644	F	4	40 BRO	SP	CCA		V	3/4/2024
2020 PO4850201486	KU	5	30 BRO	SP	CRE	ED,ID,IP	TD	3/5/2024
2020 PO3933434204	KU	6	30 ACE	SP	CCA		V	3/6/2024
2020 PO3946034224	KU	4	45 ACE	SP	CRE	ED,ID	BD	3/7/2024
2020 PO3945534415	KU	4	45 ACE	SP	CCA	ED,ID,IP	BD	3/8/2024
2020 PO3992334447	KU	5	35 ACE	SP	CCA		V	3/9/2024
2020 PO3980634501	KU	4	45 ACE	SP	CCA	ED,ID	TD	3/10/2024
2020 PO5160197869	KU	5	35 BRN	SP	CRE	ID	TD	3/11/2024
2020 PO4948397364	KU	5	35 BRN	SP	CRE		V	3/12/2024
2020 PO4936105278	KU	4	40 BRN	SP	CRE	ED,ID	TD	3/13/2024
2020 PO7502975848	KU	4	45 BRN	SP	CRE	ED,ID	BD	3/14/2024
2020 PO2406659685	KU	4	40 BRN	SP	CRE	ID	TD	3/15/2024
2020 PO2422559908	KU	4	40 BRN	SP	CRE	ID	TD	3/16/2024
2020 PO1060170624	KU	2	50 BRO	SP	CRE	ED,ID,IP	TD	3/17/2024
2020 PO1003468146	KU	2	50 BRO	SP	CRE	ED,ID,IP	TD	3/18/2024
2020 PO1027869602	KU	2	50 BRO	SP	CRE	ED,ID,IP	TD	3/19/2024
2020 PO1022869358	KU	2	50 BRO	SP	CRE	ED,ID,IP	TD	3/20/2024
2020 PO1007568381	KU	2	50 BRO	SP	CRE	ED,ID,IP	TD	3/21/2024
2020 PO1052470388	KU	3	55 BRO	SP	P	ED	T	3/22/2024
2020 PO1046370186	KU	2	50 BRO	SP	CRE	EP,ID,IP	TD	3/23/2024
2020 PO1020769225	KU	2	50 BRO	SP	CRE	ED,ID,IP	TD	3/24/2024
2020 PO1012168653	KU	2	50 BRO	SP	CRE	ED,ID,IP	TD	3/25/2024
2020 PO1039269967	KU	2	55 BRO	SP	CRE	ED,ID,IP	TX	RR 3/26/2024
2020 PO1016368921	KU	2	50 BRO	SP	CRE	ED,ID,IP	TD	3/27/2024
2020 PO0979067395	KU	2	50 BRO	SP	CRE	ED,ID,IP	TD	3/28/2024
2020 PO0970067136	KU	2	50 BRO	SP	CRE	ED,ID,IP	TD	3/29/2024
2020 PO0950866570	KU	3	50 BRO	SP	CCA		V	3/30/2024
2020 PO5534809644	KU	3	45 BRO	SP	CCA		V	3/31/2024
2020 PO7019890259	KU	4	40 BRN	SP	CRE	ED,ID	BD	4/1/2024
2020 PO7026890362	KU	5	35 BRN	SP	CRE	ED,HH,ID,RB	X	PX 4/2/2024
2020 PO7029490475	KU	4	40 BRN	SP	P	ED,ID	BD	4/3/2024
2020 PO7036790481	KU	3	40 BRN	SP	CRE	ED,ID,RB	BX	PX 4/4/2024
2020 PO7041490451	KU	4	40 BRN	SP	CRE	ED,ID,IP	BD	4/5/2024
2020 PO7047290412	KU	5	35 BRN	SP	CRE	ED,ID	BD	4/6/2024
2020 PO7056790364	KU	5	35 BRN	SP	CRE	ED,ID	BD	4/7/2024
2020 PO7079790075	KU	6	30 BRN	SP	CRE	ED,ID	BD	4/8/2024
2020 PO0962266883	KU	2	50 BRO	SP	CRE	ID,IP	BD	4/9/2024
2020 PO7005793775	KU	4	40 BRN	SP	CRE	ED,ID	TD	4/10/2024
2020 PO9134852001	KU	4	40 BRO	SP	CRE	ED,ID,src	TD	4/11/2024

2020 PO9154152107	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD		4/12/2024
2020 PO9172152215	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD		4/13/2024
2020 PO9184452288	KU	4	40 BRO	SP	CCA		V		4/14/2024
2020 PO9198352237	KU	4	40 BRO	SP	CRE		V		4/15/2024
2020 PO3650161418	KU	2	55 ACW	SP	CRE	ED,ID	TD		4/16/2024
2020 PO0649461397	KU	3	45 ACW	SP	CRE	ED,ID	BD		4/17/2024
2020 PO0653161382	F	5	35 ACW	SP	CRE		V		4/18/2024
2020 PO3646061456	KU	2	60 ACW	SP	CRE		V		4/19/2024
2020 PO0647061340	KU	3	45 ACW	SP	CRE	ED,EP,HH,ID,IP,RB	X	RP1	4/20/2024
2020 PO2388259425	KU	4	40 BRN	SP	CRE	ED,ID	TD		4/21/2024
2020 PO2421658952	KU	6	30 BRN	SP	CRE	ID	BD		4/22/2024
2020 PO2398558952	KU	3	45 BRN	SP	CCA		V		4/23/2024
2020 PO2369559154	KU	4	45 BRN	SP	CRE	ED,ID,IP	TX	RR	4/24/2024
2020 PO0642761248	KU	3	45 ACW	SP	CRE	ED,ID,IP	TD		4/25/2024
2020 PO0626361136	KU	4	45 ACW	SP	CRE	ED,ID	TD		4/26/2024
2020 PO6997793664	KU	4	40 BRN	SP	CRE	ED,ID	BD		4/27/2024
2020 PO6991793614	KU	4	40 BRN	SP	CRE	ED,ID	TD		4/28/2024
2020 PO7077190656	KU	5	30 BRN	SP	CRE	ED,ID	BD		4/29/2024
2020 PO7346292736	KU	4	45 BRO	SP	CRE	ED,ID	TD		4/30/2024
2020 PO7347692825	KU	6	30 BRO	SP	CRE	ED,ID,RB	TX	RR	5/1/2024
2020 PO5541909868	KU	4	40 BRO	SP	CRE	ID	TD		5/2/2024
2020 PO5510010461a	KU	5	35 BRO	SP	CRE	ID	TD		5/3/2024
2020 PO5510010461	KU	4	45 BRO	SP	CRE	ID	BD		5/4/2024
2020 PO5532010374	KU	6	30 BRO	SP	CCA		V		5/5/2024
2020 PO5515610298	KU	4	40 BRO	SP	CRE	ID	TD		5/6/2024
2020 PO5520210183	KU	4	40 BRO	SP	CRE	ID	TD		5/7/2024
2020 PO5534310154	KU	6	30 BRO	SP	CRE	ID	TD		5/8/2024
2020 PO5534210238	KU	6	30 BRO	SP	CRE	ID	TD		5/9/2024
2020 PO5510610170	KU	4	40 BRO	SP	CCA		V		5/10/2024
2020 PO7065890289	KU	4	40 BRN	SP	CRE	ED,ID	TD		5/11/2024
2020 PO7445693545	KU	3	45 BRO	SP	CRE	ED,ID	TD		5/12/2024
2020 PO7430993700	KU	4	40 BRO	SP	CRE	ED,ID	TD		5/13/2024
2020 PO5700706508	KU	6	30 BRN	SP	CRE	ED,ID	TD		5/14/2024
2020 PO5704806601	F	3	45 CPT	SP	P		V		5/15/2024
2020 PO5712006631	KU	6	30 BRN	SP	CRE	ED,ID	TD		5/16/2024
2020 PO5702006960	KU	6	30 XXX	SP	CRE	ED,ID	TD		5/17/2024
2020 PO5676307075	KU	5	35 KOP	SP	CRE	ED,ID	TD		5/18/2024
2020 PO5570705880	F	4	40 KOP	SP	CRE		V		5/19/2024
2020 PO5592706173	F	4	40 KOP	SP	CRE		V		5/20/2024
2020 PO5606206418	F	4	40 KOP	SP	CRE		V		5/21/2024
2020 PO5563106645	KU	4	40 XXX	SP	CRE		V		5/22/2024
2020 PO7458393637	KU	4	45 BRO	SP	CRE	ED,ID	TD		5/23/2024
2020 PO7459993855	KU	4	40 BRO	SP	CRE	ED,ID	TD		5/24/2024
2020 PO7470493728	KU	4	45 BRO	SP	CRE	ED,ID	TD		5/25/2024
2020 PO7504793991	KU	4	40 BRO	SP	CRE	ED,ID	TD		5/26/2024
2020 PO7535794223	KU	4	40 BRO	SP	CRE	ED,ID	TD		5/27/2024
2020 PO0637361118	KU	2	45 ACW	SP	CRE	ED,ID,IP	TD		5/28/2024

2020 PO2360759215	KU	5	35 BRN	SP	CRE	ID	TD	5/29/2024
2020 PO9189452018	KU	4	40 BRO	SP	CCA		V	5/30/2024
2020 PO9177851671	KU	4	40 BRO	SP	CCA		V	5/31/2024
2020 PO9172251486	KU	4	40 BRO	SP	CRE	ED,EP,ID	BX	6/1/2024
2020 PO9275052614	KU	4	40 BRO	SP	CRE	EP,HH,ID,RB,SRC	X	6/2/2024
2020 PO9284852641	KU	4	40 BRO	SP	CCA	ED,EP	VX	6/3/2024
2020 PO9312952744	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD	6/4/2024
2020 PO2345859267	KU	3	40 BRN	SP	CRE	ID	BD	6/5/2024
2020 PO2331659354	KU	5	35 BRN	SP	CRE	ID	TD	6/6/2024
2020 PO2326259393	F	7	20E BRN	SP	CRE		V	6/7/2024
2020 PO2307159504	KU	4	40 BRN	SP	CCA		V	6/8/2024
2020 PO0630960969	KU	3	45 ACW	SP	CRE	ED,ID,IP	TD	6/9/2024
2020 PO0626360858	KU	3	45 ACW	SP	CRE	ED,ID,IP	TD	6/10/2024
2020 PO0621460745	KU	3	45 ACW	SP	CRE	ED,ID	TD	6/11/2024
2020 PO2450260516	F	4	40 BRN	SP	P		V	6/12/2024
2020 PO2506361618	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	6/13/2024
2020 PO2447061149	KU	5	35 BRN	SP	CRE	ID,IP	TD	6/14/2024
2020 PO0601860537	KU	6	30 ACW	SP	CRE	ED,ID,IP	TD	6/15/2024
2020 PO0615360600	KU	3	45 ACW	SP	CRE	ED,ID,IP	TD	6/16/2024
2020 PO0612660535	KU	6	30 ACW	SP	CRE	ED,ID	TD	6/17/2024
2020 PO9334052811	KU	4	40 BRO	SP	CRE	ED	T	6/18/2024
2020 PO2492361349	KU	4	40 BRN	SP	P	ED	TD	6/19/2024
2020 PO2480761116	KU	4	40 BRN	SP	CRE	ID	TD	6/20/2024
2020 PO2458860694	KU	4	40 BRN	SP	CRE	HH,RB	X	6/21/2024
2020 PO2425061163	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	6/22/2024
2020 PO2399461077	KU	5	35 BRN	SP	CRE	ID,IP	TD	6/23/2024
2020 PO2368360971	KU	5	35E BRN	SP	CRE	ED,ID	TD	6/24/2024
2020 PO2351860732	KU	4	40 BRN	SP	CCA		V	6/25/2024
2020 PO2339660554	KU	4	40 BRN	SP	CCA		V	6/26/2024
2020 PO9355852884	KU	4	40 BRO	SP	P	ED,SRS	T	6/27/2024
2020 PO9373652949	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD	6/28/2024
2020 PO0609760468	KU	4	45 ACW	SP	CRE	ED,ID	BD	6/29/2024
2020 PO0604560351	KU	3	40 ACW	SP	CRE	ED,ID	TD	6/30/2024
2020 PO0602160292	KU	3	45 ACW	SP	CRE	ED,ID	TD	7/1/2024
2020 PO0950466554	KU	3	50 BRO	SP	CRE	ID	BD	7/2/2024
2020 PO1008663175	KU	4	50 BRO	SP	CRE	ED,ID,IP	TD	7/3/2024
2020 PO0991663270	KU	4	50 BRO	SP	CRE	ED,ID,IP	TD	7/4/2024
2020 PO0974463373	KU	4	50 BRO	SP	CRE	ED,ID,IP	TD	7/5/2024
2020 PO0957363481	KU	4	50 BRO	SP	CRE	ED,ID,IP	TD	7/6/2024
2020 PO0940263591	KU	4	50 BRO	SP	CRE	ED,ID,IP	TD	7/7/2024
2020 PO9394953020	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD	7/8/2024
2020 PO9415353088	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD	7/9/2024
2020 PO9430653139	KU	4	40 BRO	SP	CRE		V	7/10/2024
2020 PO9447453212	KU	4	40 BRO	SP	CRE	ED,ID,IP,SRC	TD	7/11/2024
2020 PO9096954660	KU	4	40 BRO	SP	CRE	ID	BD	7/12/2024
2020 PO0597660185	KU	3	45 ACW	SP	CRE	ED,ID	TD	7/13/2024
2020 PO0592760071	KU	4	40 ACW	SP	CRE	ED,ID	TD	7/14/2024

2020 PO0587560090	F	4	40 ACW	SP	CRE		V	7/15/2024	
2020 PO0586759934a	KU	6	30 ACW	SP	CCA		V	7/16/2024	
2020 PO0586759934	KU	3	45 ACW	SP	CRE	ED,ID	TD	7/17/2024	
2020 PO0580759791	KU	3	45 ACW	SP	CRE	ED,ID	TD	7/18/2024	
2020 PO0594359735	KU	4	45 ACW	SP	CRE	ED,ID	TD	7/19/2024	
2020 PO0612159724	KU	6	30 ACW	SP	CRE	ED,ID,IP	TD	7/20/2024	
2020 PO0602359702	KU	6	30 ACW	SP	CRE	ED,ID,IP	TD	7/21/2024	
2020 PO0596859633	KU	4	40 ACW	SP	CRE	ID	BD	7/22/2024	
2020 PO0592659537	KU	4	40 ACW	SP	CCA		V	7/23/2024	
2020 PO0589459453	KU	4	40 ACW	SP	CRE	ID	BD	7/24/2024	
2020 PO0558059379	F	4	40 ACW	SP	CRE		V	7/25/2024	
2020 PO0923363693	KU	4	50 BRO	SP	CRE	ED,ID,IP	TD	7/26/2024	
2020 PO7387894947	KU	4	40 BRO	SP	CRE		V	7/27/2024	
2020 PO7086894871	KU	2	70 BRN	SP	CRE	ED,ID	TD	7/28/2024	
2020 PO7087694813	KU	4	35 BRN	SP	CRE	ED,ID	TD	7/29/2024	
2020 PO7081694737	KU	4	40 BRN	SP	CRE	ED,ID	TD	7/30/2024	
2020 PO7212290383	KU	6	35 BRO	SP	CCA		V	7/31/2024	
2020 PO7209190382	F	4	40 BRO	SP	CCA		V	8/1/2024	
2020 PO7114989784	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD	8/2/2024	
2020 PO7107689836	KU	5	35 BRN	SP	CRE	ED,ID	BD	8/3/2024	
2020 PO7218890330	KU	6	30 BRO	SP	CCA		V	8/4/2024	
2020 PO7340594441	KU	4	45 BRO	SP	CRE	ED,ID,RB	X	RP1	8/5/2024
2020 PO7229190338	KU	5	35 BRO	SP	P	ED	BD	8/6/2024	
2020 PO7229290383	KU	6	35 BRO	SP	CRE	ED	TD	8/7/2024	
2020 PO7341894343	KU	4	40 BRO	SP	CRE	ED,ID	TD	8/8/2024	
2020 PO7225090409	KU	5	35 BRO	SP	CRE	ED,ID	TD	8/9/2024	
2020 PO7074294644	KU	4	40 BRN	SP	CRE	ED,ID,IP,RB	X	RR	8/10/2024
2020 PO7233890417	KU	4	45 BRO	SP	CRE	ED	TD	8/11/2024	
2020 PO7114889692	KU	6	30 BRN	SP	CRE	ED,ID	BD	8/12/2024	
2020 PO7105289734	KU	4	40 BRN	SP	CRE	ED,ID	TD	8/13/2024	
2020 PO7096889803	KU	6	30 BRN	SP	CRE	ED,ID	BD	8/14/2024	
2020 PO7308294203	KU	4	40 BRO	SP	A	ED,ID	TD	8/15/2024	
2020 PO7343194256	KU	4	40 BRO	SP	CRE	ED,ID	TD	8/16/2024	
2020 PO7344894143	KU	4	40 BRO	SP	CRE	ED,ID	TD	8/17/2024	
2020 PO7200290292	F	4	40 BRO	SP	CCA		V	8/18/2024	
2020 PO7190690227	F	4	40 BRO	SP	CRE		V	8/19/2024	
2020 PO7195890330	F	5	30 BRO	SP	CRE		V	8/20/2024	
2020 PO7204890346	F	5	35 BRO	SP	CRE		V	8/21/2024	
2020 PO7218090455	F	4	40 BRO	SP	CRE		V	8/22/2024	
2020 PO7238490439	F	4	35 BRO	SP	CCA		V	8/23/2024	
2020 PO7324393905	KU	4	40 BRO	SP	CRE	HH,ID	VX	RP1	8/24/2024
2020 PO7073694544	KU	5	30 BRN	SP	CRE	ED,ID	TD	8/25/2024	
2020 PO7068294566	KU	4	40 BRN	SP	CRE	ED,ID	BD	8/26/2024	
2020 PO6725102641	KU	3	50 BRN	SP	CCA		V	8/27/2024	
2020 PO6686802502A	KU	3	40 BRN	SP	CCA		V	8/28/2024	
2020 PO6724002972	KU	5	35 XXX	SP	CRE	ED,ID,IP	TD	8/29/2024	
2020 PO6705703032	KU	4	35 BRN	SP	CRE		V	8/30/2024	

2020 PO6706503052	KU	4	40 BRN	SP	CRE		V		8/31/2024
2020 PO6735903136	KU	4	40 BRN	SP	CCA		V		9/1/2024
2020 PO6717902911	KU	4	45 BRN	SP	CRE	ED,ID	TD		9/2/2024
2020 PO6603903074A	KU	6	30 BRN	SP	CCA		V		9/3/2024
2020 PO6555003411	KU	6	30 BRN	SP	CCA		V		9/4/2024
2020 PO6618903253	F	4	40 XXX	SP	CRE		V		9/5/2024
2020 PO6643103062	F	5	25 BRO	SP	CRE		V		9/6/2024
2020 PO6604303317	F	4	40 KOP	SP	CRE		V		9/7/2024
2020 PO6598603299	F	3	40 XXX	SP	P		V		9/8/2024
2020 PO6691302611	KU	4	40 BRN	SP	CCA		V		9/9/2024
2020 PO6639003005	F	4	40 BRO	SP	P		V		9/10/2024
2020 PO6615703207	F	5	35 XXX	SP	CRE		V		9/11/2024
2020 PO6585103413	F	5	35 KOP	SP	P		V		9/12/2024
2020 PO6220105783	F	5	40 XXX	SP	A	RB	BX	PX	9/13/2024
2020 PO7156390404	KU	4	30 BRN	SP	CRE	ED,ID	TD		9/14/2024
2020 PO7145390202	KU	4	30 BRN	SP	P	ED,ID	TD		9/15/2024
2020 PO2039845583	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		9/16/2024
2020 PO7134790294	F	4	35 BRN	SP	CCA		V		9/17/2024
2020 PO7141390230	KU	5	35 BRN	SP	CRE	ED,ID	BD		9/18/2024
2020 PO2037745374	KU	4	40 ACE	SP	CRE	ED,ID	TD		9/19/2024
2020 PO2043045282	KU	4	40 ACE	SP	CRE	ED,ID	TD		9/20/2024
2020 PO7029095504	KU	6	30 BRN	SP	CRE	ED,ID	TD		9/21/2024
2020 PO7038695465	KU	4	40 BRN	SP	CRE	ED,ID	TD		9/22/2024
2020 PO7051495415	KU	4	35 BRN	SP	P	ED,ID	TD		9/23/2024
2020 PO6765902300	KU	3	45 BRO	SP	CCA		V		9/24/2024
2020 PO6675502656	F	3	45 BRO	SP	CRE		V		9/25/2024
2020 PO6581903352	KU	3	45 BRO	SP	CCA		V		9/26/2024
2020 PO6728202313	KU	3	45 BRO	SP	CCA		V		9/27/2024
2020 PO6532003607	KU	3	45 BRO	SP	CCA		V		9/28/2024
2020 PO7321692314	F	5	35 BRO	SP	CRE	ED,SRC	VX	RP3	9/29/2024
2020 PO7312392225	F	3	45 BRO	SP	CRE		V		9/30/2024
2020 PO5826410993	KU	6	30 BRO	SP	CCA		V		10/1/2024
2020 PO5815810930	KU	5	35 BRO	SP	CRE	ID	TD		10/2/2024
2020 PO7270290771	F	3	40 BRO	SP	CRE		V		10/3/2024
2020 PO7277090690	F	3	40 BRO	SP	CRE		V		10/4/2024
2020 PO7286990583	F	4	40 BRO	SP	CRE		V		10/5/2024
2020 PO7297290479	F	4	40 BRO	SP	CRE		V		10/6/2024
2020 PO7292790460	F	5	30 BRO	SP	CRE	ED	VX	RP1	10/7/2024
2020 PO7302990364	KU	3	45 BRO	SP	CRE	ED,ID	TD		10/8/2024
2020 PO7296390329	KU	5	35 BRO	SP	CCA		V		10/9/2024
2020 PO7293290287	KU	5	30 BRO	SP	CRE	ED,ID	BX	RP3	10/10/2024
2020 PO7289190231	KU	5	30 BRO	SP	CRE	ED,ID	BD		10/11/2024
2020 PO6838317777	KU	6	30 XXX	SP	CRE		V		10/12/2024
2020 PO6838617485	KU	4	40 XXX	SP	CRE	ID	TD		10/13/2024
2020 PO6861318651	KU	5	30 XXX	SP	CRE	ID	TD		10/14/2024
2020 PO7138489387	KU	4	50 BRN	SP	CRE	ED,ID	TD		10/15/2024
2020 PO6510203379	F	4	40 XXX	SP	CRE		V		10/16/2024

2020 PO6504403280	KU	6	30 XXX	SP	CRE	ED,ID	TD	10/17/2024
2020 PO7276688532	KU	4	40 BRO	SP	CCA		V	10/18/2024
2020 PO7267888644	KU	6	30 BRO	SP	CCA		V	10/19/2024
2020 PO7263488601	KU	4	40 BRO	SP	CCA		V	10/20/2024
2020 PO7257288574	KU	6	30 BRO	SP	CCA		V	10/21/2024
2020 PO7251488523	KU	5	35 BRO	SP	CCA		V	10/22/2024
2020 PO7242388441	KU	5	35 BRO	SP	CCA		V	10/23/2024
2020 PO5801210828	KU	4	40 BRO	SP	CRE	ID	TD	10/24/2024
2020 PO5810210633	KU	4	40 BRO	SP	CRE	ID	TD	10/25/2024
2020 PO5794810761	KU	6	30 BRO	SP	CRE	ID	TD	10/26/2024
2020 PO5794710718	KU	6	30 BRO	SP	CRE	ID	TD	10/27/2024
2020 PO5800510672	KU	6	30 BRO	SP	CRE	ID	BD	10/28/2024
2020 PO5785510745	KU	4	40 BRO	SP	CRE	ID	TD	10/29/2024
2020 PO5795610511	KU	4	40 BRO	SP	CRE	ID	TD	10/30/2024
2020 PO7429081990	KU	3	45 BRN	SP	CCA		V	10/31/2024
2020 PO7388481953	KU	4	40 BRN	SP	CRE	ED,ID	TD	11/1/2024
2020 PO7392782005	KU	4	40 BRN	SP	CCA		V	11/2/2024
2020 PO7401882132	KU	4	40 BRN	SP	CRE	ED,ID	TD	11/3/2024
2020 PO7403882206	KU	4	45 BRN	SP	CRE	ED,ID	BD	11/4/2024
2020 PO7418282208	KU	3	50 BRN	SP	CRE	ED,ID	BD	11/5/2024
2020 PO7420582217	KU	2	50 BRN	SP	CRE	ED,ID	BD	11/6/2024
2020 PO7422582218	KU	6	30 BRN	SP	CRE		V	11/7/2024
2020 PO7431182221	KU	2	50 BRN	SP	CCA		V	11/8/2024
2020 PO7458682034	KU	4	40 BRN	SP	CRE	ED,ID	BD	11/9/2024
2020 PO7450582121	KU	5	35 BRN	SP	CRE	ED,ID	BD	11/10/2024
2020 PO7456382196	KU	5	35 BRN	SP	CRE	ED,ID	BD	11/11/2024
2020 PO7446982245	KU	5	35 BRN	SP	CRE	ED,ID	TD	11/12/2024
2020 PO7457282238	KU	4	40 BRN	SP	CRE	ED,ID	TD	11/13/2024
2020 PO7465482244	KU	4	40 BRN	SP	CRE	ED,HH,ID,RB	BX	11/14/2024
2020 PO7574282412	KU	5	35 BRN	SP	CCA		V	11/15/2024
2020 PO7585282424	KU	6	30 BRN	SP	CCA		V	11/16/2024
2020 PO7598882443	KU	5	30 BRN	SP	CRE		V	11/17/2024
2020 PO7654983166	KU	4	40 BRN	SP	CRE	ED,ID	BD	11/18/2024
2020 PO4831187266	LGE	4	35 BRO	SP	CRE	ED	TD	11/19/2024
2020 PO4675788842	LGE	4	40 BRO	SP	A	ED	TD	11/20/2024
2020 PO4802688186	LGE	4	30 BRN	SP	A	ED,ID	BD	11/21/2024
2020 PO4801888171	LGE	4	30 BRN	SP	A	ED,ID	BD	11/22/2024
2020 PO4673688840	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	11/23/2024
2020 PO4802088156	LGE	4	30 BRN	SP	A	ED,ID	BD	11/24/2024
2020 PO4802388139	LGE	4	35 BRN	SP	CCA		BD	11/25/2024
2020 PO4802288136	LGE	4	35 BRN	SP	CCA		V	11/26/2024
2020 PO4801488134	LGE	4	40 BRN	SP	A	ED,ID	BD	11/27/2024
2020 PO4800488132	LGE	4	30 BRN	SP	CRE	ED,ID	BD	11/28/2024
2020 PO4798388126	LGE	4	30 BRN	SP	CCA	ED,ID	BD	11/29/2024
2020 PO4671788818	LGE	4	40 BRO	SP	CCA		V	11/30/2024
2020 PO4674288831	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	12/1/2024
2020 PO4673088822	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	12/2/2024

2020 PO4879286274	LGE	3	45 OTH	SP	P	ID	TD	12/3/2024
2020 PO4879586263	LGE	4	40 OTH	SP	P	ID	TD	12/4/2024
2020 PO4674788797	LGE	4	40 BRO	SP	CCA		V	12/5/2024
2020 PO4673888790	LGE	4	40 BRO	SP	CCA		V	12/6/2024
2020 PO4675888805	LGE	3	45 BRO	SP	CCA		V	12/7/2024
2020 PO4880286240	LGE	4	40 OTH	SP	P	ID	TD	12/8/2024
2020 PO4880686227	LGE	4	40 OTH	SP	P	ID	TD	12/9/2024
2020 PO4881686196	LGE	4	40 OTH	SP	P	ID	TD	12/10/2024
2020 PO4879786245	LGE	4	45 OTH	SP	P	ID	BD	12/11/2024
2020 PO4672788793	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	12/12/2024
2020 PO4673088784	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	12/13/2024
2020 PO4883886162	KU	1	50 OTH	SP	CCA		V	12/14/2024
2020 PO5944775088	LGE	4	40 OTH	SP	CCA		V	12/15/2024
2020 PO4882086184	LGE	3	40 OTH	SP	P	ID	TD	12/16/2024
2020 PO4884586157	LGE	1	45 OTH	UN	S		V	12/17/2024
2020 PO4685988720	LGE	4	40 BRO	SP	A	ID,IP	BD	12/18/2024
2020 PO4905087190	LGE	3	45 OTH	SP	CCA		V	12/19/2024
2020 PO4906687195	LGE	4	40 OTH	SP	CRE	ED,ID,RB	X	RP1 12/20/2024
2020 PO4765287874	LGE	5	70 BRO	SP	CRE		V	12/21/2024
2020 PO4765991580	LGE	3	45 BRO	SP	CCA		V	12/22/2024
2020 PO4768087863	LGE	4	30 BRO	SP	CCA		V	12/23/2024
2020 PO4767987872	LGE	UNK	70 BRO	SP	CRE		V	12/24/2024
2020 PO4771587872	LGE	4	40 BRO	SP	CRE	ED	TD	12/25/2024
2020 PO4771787868	LGE	3	50 BRO	SP	CRE	ED	TD	12/26/2024
2020 PO4772587867	LGE	UNK	70 BRO	SP	CRE		V	12/27/2024
2020 PO4774287865	LGE	UNK	70 BRO	SP	CRE		V	12/28/2024
2020 PO4776187863	LGE	4	65 BRO	SP	CRE		V	12/29/2024
2020 PO4812587756	LGE	4	40 BRN	SP	CRE	ED,ID	BD	12/30/2024
2020 PO4672789176	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	12/31/2024
2020 PO4814287727	LGE	4	40 BRN	SP	CRE	ED,ID	BD	1/1/2025
2020 PO4868386606	LGE	3	45 OTH	SP	P	ED,ID,SRS	TD	1/2/2025
2020 PO4811187749	LGE	4	40 BRN	SP	CRE	ED,ID	BD	1/3/2025
2020 PO4869886608	LGE	1	70 OTH	SP	CCA		V	1/4/2025
2020 PO4870186610	LGE	4	30 OTH	SP	P	ED,SRS	TD	1/5/2025
2020 PO4870586607	LGE	1	55 OTH	SP	CCA		V	1/6/2025
2020 PO4674389150	LGE	4	30 BRO	SP	A	ED	TD	1/7/2025
2020 PO4809687742	LGE	4	40 BRN	SP	CRE	ED,ID	BD	1/8/2025
2020 PO4808187737	LGE	4	40 BRN	SP	CRE	ED,ID	BD	1/9/2025
2020 PO4806987733	LGE	4	45 BRN	SP	A		VX	RP3 1/10/2025
2020 PO4806187747	LGE	4	40 BRN	SP	CRE		V	1/11/2025
2020 PO4676089154	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	1/12/2025
2020 PO4884787478	LGE	4	40 XXX	SP	A	ID	BX	RP2 1/13/2025
2020 PO4870386589	F	1	55 OTH	SP	CCA		V	1/14/2025
2020 PO4869786587	F	4	30 OTH	SP	CCA		V	1/15/2025
2020 PO4871486552	LGE	1	55 OTH	SP	CCA		V	1/16/2025
2020 PO4869586566	F	4	40 OTH	SP	CRE		V	1/17/2025
2020 PO4872086540	LGE	1	55 OTH	SP	CCA		V	1/18/2025

2020 PO4870786564	LGE	4	30 OTH	SP	CCA		V	1/19/2025
2020 PO4871086565	F	1	55 OTH	SP	CCA		V	1/20/2025
2020 PO4871086563	LGE	1	55 OTH	SP	CCA		V	1/21/2025
2020 PO4867586599	LGE	3	45 OTH	SP	P	ED,SRS	TD	1/22/2025
2020 PO4771288090	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	1/23/2025
2020 PO4771788078	LGE	3	45 BRO	SP	CCA		V	1/24/2025
2020 PO4239691900	F	4	40 KOP	SP	CRE		V	1/25/2025
2020 PO4221191911	F	4	40 KOP	SP	CRE		V	1/26/2025
2020 PO4202091919	F	4	40 KOP	SP	CRE		V	1/27/2025
2020 PO4181991931	F	4	40 KOP	DF	CRE		V	1/28/2025
2020 PO3754689513	F	4	40 KOP	DF	CRE		V	1/29/2025
2020 PO3759589524	F	4	40 KOP	SP	CRE		V	1/30/2025
2020 PO4157791943	F	4	40 KOP	SP	P		V	1/31/2025
2020 PO4143191954	KU	3	45 KOP	SP	S		V	2/1/2025
2020 PO4140591955	F	4	40 KOP	SP	CRE		V	2/2/2025
2020 PO4128091958	KU	3	45 KOP	SP	S		V	2/3/2025
2020 PO4111391967	KU	3	45 KOP	SP	S		V	2/4/2025
2020 PO4089091975	F	4	40 KOP	SP	P		V	2/5/2025
2020 PO4157292255	F	4	40 KOP	SP	CRE		V	2/6/2025
2020 PO4137992223	F	4	40 KOP	SP	S		V	2/7/2025
2020 PO4122692188	F	4	40 KOP	SP	CRE		V	2/8/2025
2020 PO4106892155	F	4	45 KOP	SP	S		V	2/9/2025
2020 PO4087792114	F	4	40 KOP	SP	CRE		V	2/10/2025
2020 PO4087792114	KU	5	35 KOP	SP	S		V	2/11/2025
2020 PO4069892068	F	4	40 KOP	SP	CRE		V	2/12/2025
2020 PO4070791977	F	4	40 KOP	SP	CRE		V	2/13/2025
2020 PO4053191985	F	4	40 KOP	SP	CRE		V	2/14/2025
2020 PO4052092030	KU	6	35 KOP	SP	CRE	ED,ID	TD	2/15/2025
2020 PO4045692017	F	4	40 KOP	SP	CRE		V	2/16/2025
2020 PO4036991999	F	4	40 KOP	SP	CRE		V	2/17/2025
2020 PO4029291982	F	4	40 KOP	SP	CRE		V	2/18/2025
2020 PO4017792078	KU	4	40 KOP	SP	CRE	ED,ID	TD	2/19/2025
2020 PO3832190287	KU	6	25 KOP	SP	S		V	2/20/2025
2020 PO3823190118	F	4	40 KOP	SP	CRE		V	2/21/2025
2020 PO3830390175	KU	4	40 KOP	SP	CRE	ID	BD	2/22/2025
2020 PO3837190228	KU	4	40 KOP	SP	CRE	ID	BD	2/23/2025
2020 PO3844490285	KU	4	40 KOP	SP	CRE	ID	BD	2/24/2025
2020 PO4657388609	F	4	40 BRN	SP	CRE		V	2/25/2025
2020 PO4658088599	F	4	40 BRN	SP	CRE		V	2/26/2025
2020 PO4658788589	F	4	40 BRN	SP	CRE		V	2/27/2025
2020 PO4659388583	F	4	40 BRN	SP	CRE		V	2/28/2025
2020 PO4828688034	LGE	4	40 BRO	SP	CRE	ED	V	3/1/2025
2020 PO4829288035	LGE	4	40 BRO	SP	CRE	ED	TD	3/2/2025
2020 PO4653288610	F	4	40 BRN	SP	CCA		V	3/3/2025
2020 PO4654288603	LGE	6	25 BRN	SP	CRE	ED,ID	TD	3/4/2025
2020 PO4654688606	LGE	4	40 BRN	SP	CRE	ED,ID	TD	3/5/2025
2020 PO4655888601	LGE	4	30 BRN	SP	A	ED,ID	BD	3/6/2025

2020 PO4655388597	LGE	4	40 BRN	SP	A	ED,ID	TD	3/7/2025
2020 PO4655088588	LGE	4	30 BRN	SP	A	ED,ID	TD	3/8/2025
2020 PO4830988029	LGE	4	40 BRO	SP	CRE	ED	BD	3/9/2025
2020 PO4832788024	LGE	4	40 BRO	SP	CRE	ED	TD	3/10/2025
2020 PO9272272445	KU	4	40 OTH	SP	CRE	ID	BD	3/11/2025
2020 PO4655988589	LGE	4	40 BRN	SP	A	ED,ID	BD	3/12/2025
2020 PO4656188585	LGE	4	40 BRN	SP	CRE	ED,ID	BD	3/13/2025
2020 PO4823088504-A	LGE	4	30 BRO	SP	CRE	ED	TD	3/14/2025
2020 PO4824933509-A	LGE	3	30 BRO	SP	CRE	ED	TD	3/15/2025
2020 PO4326188497-A	LGE	4	30 BRO	SP	CRE	ED	TD	3/16/2025
2020 PO4655488512	LGE	4	30 BRN	SP	A	ED,ID	TD	3/17/2025
2020 PO4655988516	F	4	35 BRN	SP	CCA		V	3/18/2025
2020 PO4656488518	LGE	4	30 BRN	SP	A	ED,ID,IP	TD	3/19/2025
2020 PO9213872975	KU	6	30 OTH	SP	CCA		V	3/20/2025
2020 PO9199573001	KU	6	30 OTH	SP	CCA		V	3/21/2025
2020 PO9202673110	KU	6	30 OTH	SP	CCA		V	3/22/2025
2020 PO9214973196	KU	6	30 OTH	SP	CCA	ED,SRS	TD	3/23/2025
2020 PO9230773158	KU	5	35 OTH	SP	CCA		V	3/24/2025
2020 PO4824388479	LGE	4	40 BRO	SP	CRE	ED	TD	3/25/2025
2020 PO4822388472	LGE	4	40 BRO	SP	CRE	ED	TD	3/26/2025
2020 PO4657688507	LGE	4	30 BRN	SP	CRE	ED,ID	TD	3/27/2025
2020 PO4658688547	LGE	3	45 BRN	SP	CCA		V	3/28/2025
2020 PO4659188541	LGE	4	35 BRN	SP	A	ED,ID	BD	3/29/2025
2020 PO4659788533	LGE	3	45 BRN	SP	CRE	ED,ID	BD	3/30/2025
2020 PO4660288525	LGE	4	40 BRN	SP	A	ED,ID	BD	3/31/2025
2020 PO4659888522	LGE	4	30 BRN	SP	A	ED,ID	BD	4/1/2025
2020 PO4826388487	LGE	4	40 BRO	SP	CRE	ED	BD	4/2/2025
2020 PO5296297918-A	LGE	3	40 BRO	SP	CRE	ED	TD	4/3/2025
2020 PO4819088492-A	LGE	4	35 BRO	SP	CCA		V	4/4/2025
2020 PO4820788497-A	LGE	4	30 BRO	SP	CCA		V	4/5/2025
2020 PO4823088504-A	LGE	4	30 BRO	SP	CRE	ED	BD	4/6/2025
2020 PO5335597919	LGE	4	35 BRO	SP	CCA		V	4/7/2025
2020 PO5360697871	LGE	3	45 BRO	SP	CRE	ED	BD	4/8/2025
2020 PO9243872870	KU	3	50 OTH	SP	CCA		V	4/9/2025
2020 PO9233672874	KU	5	35 OTH	SP	CCA		V	4/10/2025
2020 PO9239972923	KU	2	50 OTH	SP	CCA		V	4/11/2025
2020 PO9219772536	F	4E	40E OTH	SP	CRE	ED,ID,MD	BX	RP3 4/12/2025
2020 PO9243072685	F	3	45 KOP	SP	P		V	4/13/2025
2020 PO9231472618	F	4E	40E OTH	SP	CRE		V	4/14/2025
2020 PO9208372432	F	3	45 OTH	SP	CCA		V	4/15/2025
2020 PO9194772311	F	2	55 OTH	SP	CCA		V	4/16/2025
2020 PO9191772342	KU	6	30 OTH	SP	CCA		V	4/17/2025
2020 PO9354972938	KU	4	40 OTH	SP	CRE	ED,ID,RB	BX	PX 4/18/2025
2020 PO9348673030	KU	4	40 OTH	SP	CRE	ED,ID	BD	4/19/2025
2020 PO9345573077	KU	4	40 BRN	SP	CRE	ED,ID,MD	BD	4/20/2025
2020 PO9340473154	KU	5	35 BRN	SP	S		B	4/21/2025
2020 PO4660388514	LGE	4	30 BRN	SP	A	ED,ID	BD	4/22/2025

2020 PO4660888517	LGE	4	40 BRN	SP	A	ED,ID	BD	4/23/2025	
2020 PO4661388508	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD	4/24/2025	
2020 PO4829688475	LGE	4	40 BRO	SP	CRE	ED	V	4/25/2025	
2020 PO4660988505	LGE	4	30 BRN	SP	A	ED,ID,IP	BD	4/26/2025	
2020 PO4848588327	LGE	UNK	45 BRO	SP	CRE	ED	BD	4/27/2025	
2020 PO4848888329	LGE	UNK	45 BRO	SP	CRE	ED	BD	4/28/2025	
2020 PO4849188330	LGE	UNK	45 BRO	SP	CRE		BD	4/29/2025	
2020 PO4848987695	LGE	UNK	45 BRO	SP	CCA		V	4/30/2025	
2020 PO4662088499	LGE	4	40 BRN	SP	A	ED,ID	BD	5/1/2025	
2020 PO4661588496	LGE	4	30 BRN	SP	A	ED,ID,IP	TD	5/2/2025	
2020 PO4661888487	LGE	4	30 BRN	SP	CCA		V	5/3/2025	
2020 PO4848787717	LGE	UNK	45 BRO	SP	CRE	ED	BD	5/4/2025	
2020 PO4853287782	LGE	UNK	90 BRO	SP	CRE		V	5/5/2025	
2020 PO4660388462	LGE	4	30 BRN	SP	A	ED,ID	TD	5/6/2025	
2020 PO4660888461	LGE	4	30 BRN	SP	A	ED,ID	TD	5/7/2025	
2020 PO4662788476	LGE	4	30 BRN	SP	A	ED,ID	BD	5/8/2025	
2020 PO4663488479	LGE	4	40 BRN	SP	CRE		V	5/9/2025	
2020 PO4662688492	LGE	4	40 BRN	SP	A	ED,ID	BD	5/10/2025	
2020 PO4850787784	LGE	UNK	90 BRO	ST	CCA		V	5/11/2025	
2020 PO4848387786	LGE	UNK	90 BRO	ST	CRE		V	5/12/2025	
2020 PO4845887787	LGE	UNK	90 BRO	ST	CRE		V	5/13/2025	
2020 PO4845887825	LGE	UNK	45 BRO	SP	CRE		B	5/14/2025	
2020 PO4844787840	LGE	4	40 BRO	SP	CRE	ED	TD	5/15/2025	
2020 PO4664088474	LGE	3	25 BRN	SP	CRE	ED,ID	BD	5/16/2025	
2020 PO3731497443	LGE	4	30 BRN	SP	CCA		V	5/17/2025	
2020 PO4840887876	LGE	UNK	45 BRO	SP	CRE	ED	TD	5/18/2025	
2020 PO4842387858	LGE	4	40 BRO	SP	CRE	ED	BD	5/19/2025	
2020 PO4843287789	LGE	UNK	90 BRO	SP	CRE		V	5/20/2025	
2020 PO4840887791	LGE	UNK	95 BRO	ST	P		V	5/21/2025	
2020 PO4838487794	LGE	UNK	95 BRO	ST	P		V	5/22/2025	
2020 PO4836487796	LGE	UNK	45 BRO	SP	CCA		V	5/23/2025	
2020 PO4836587800	LGE	4	40 BRO	SP	CCA		V	5/24/2025	
2020 PO4839587857	LGE	4	40 BRO	SP	S		V	5/25/2025	
2020 PO4838087837	LGE	4	40 BRO	SP	CRE	ED	TD	5/26/2025	
2020 PO4836687817	LGE	4	40 BRO	SP	CRE	ED	BD	5/27/2025	
2020 PO4836287817	LGE	4	30 BRO	ST	CCA		V	5/28/2025	
2020 PO4813788349	LGE	4	35 BRO	SP	CRE	ID,IP	TX	RR	5/29/2025
2020 PO4663988456	LGE	3	45 BRN	SP	CRE	ED,HH,ID	BX	RP2	5/30/2025
2020 PO4663188450	LGE	1	50 BRN	SP	S		V	5/31/2025	
2020 PO4664788462	LGE	3	45 BRN	SP	S		V	6/1/2025	
2020 PO4664988458	LGE	4	40 BRN	SP	A	ED,ID	TD	6/2/2025	
2020 PO4665188446	LGE	4	30 BRN	SP	CRE	ED,ID	BD	6/3/2025	
2020 PO4665788448	LGE	4	35 BRN	SP	CRE	ED,ID	BD	6/4/2025	
2020 PO3756597017	LGE	4	30 BRN	SP	CCA		V	6/5/2025	
2020 PO4666888431	LGE	4	40 BRN	SP	CRE	ED,ID	TD	6/6/2025	
2020 PO4667488422	LGE	4	35 BRN	SP	A	ED,ID	BD	6/7/2025	
2020 PO4817988322	LGE	4	35 BRO	SP	CRE	ED	TD	6/8/2025	

2020 PO4818988312	LGE	4	30 BRO	SP	CRE	ED	TD	6/9/2025
2020 PO4819588307	LGE	4	30 BRO	SP	CRE	ED	TD	6/10/2025
2020 PO4820988285	LGE	3	45 BRO	SP	CCA		V	6/11/2025
2020 PO4666688413	LGE	4	30 BRN	SP	CCA		V	6/12/2025
2020 PO4815888341	LGE	4	30 BRO	SP	CRE	ED	BD	6/13/2025
2020 PO4815288340	LGE	4	30 BRO	SP	CRE	ED	BD	6/14/2025
2020 PO4814688347	LGE	4	35 BRO	SP	CRE	ED	TD	6/15/2025
2020 PO4813088334	LGE	4	35 BRO	SP	CRE	ED	TD	6/16/2025
2020 PO4810688358	LGE	4	40 BRO	SP	CRE	ED	TD	6/17/2025
2020 PO4810188347	LGE	4	40 BRO	SP	CRE	ED	TD	6/18/2025
2020 PO4692288402	LGE	4	35 BRN	SP	A	ED,ID	BD	6/19/2025
2020 PO4694788417	LGE	4	30 BRN	SP	CCA		V	6/20/2025
2020 PO4692988420	LGE	1	55 BRN	SP	A	ED,ID	BD	6/21/2025
2020 PO4693288414	LGE	1	55 BRN	SP	A	ED,ID	BD	6/22/2025
2020 PO4692988413	LGE	4	40 BRN	SP	A	ED,ID	BD	6/23/2025
2020 PO4693888407	LGE	4	35 BRN	SP	CCA		V	6/24/2025
2020 PO4831988139	F	4	40 BRO	SP	CRE		V	6/25/2025
2020 PO5471294319	LGE	3	45 BRO	SP	CRE	ED	BD	6/26/2025
2020 PO4832388135	LGE	4	30 BRO	SP	CCA		V	6/27/2025
2020 PO4692188429	F	1	55 BRN	SP	A		V	6/28/2025
2020 PO4691488440	F	3	50 BRN	SP	A		V	6/29/2025
2020 PO4023797142	LGE	4	35 BRN	SP	CCA		V	6/30/2025
2020 PO9189972184	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD	7/1/2025
2020 PO4063697122	F	3	45 BRN	SP	CCA		V	7/2/2025
2020 PO4695588452	LGE	3	45 BRN	SP	A	ED,ID	TD	7/3/2025
2020 PO4694588432	LGE	4	35 BRN	SP	CCA		V	7/4/2025
2020 PO4696588435	LGE	3	45 BRN	SP	A	ED,ID	BD	7/5/2025
2020 PO9198072056	KU	4	40 OTH	SP	CRE	ED,ID,SRC	TX	RR 7/6/2025
2020 PO9198772136	F	5	35 OTH	SP	P		V	7/7/2025
2020 PO4701188462	LGE	4	35 BRN	SP	A	ED,ID	TD	7/8/2025
2020 PO4698988447	LGE	4	30 BRN	SP	CRE	ED,ID	TD	7/9/2025
2020 0414178991a	KU	4	45 XXX	SP	CCA		V	7/10/2025
2020 0414178991a	KU	4	45 XXX	SP	CCA		V	7/11/2025
2020 PO0437679127	KU	4	45 XXX	SP	CRE	ID	BD	7/12/2025
2020 PO0414178991	KU	4	45 XXX	SP	CRE	ID	BD	7/13/2025
2020 PO9208972130	KU	4	40 OTH	SP	CCA		V	7/14/2025
2020 PO9221971962	KU	6	30 OTH	SP	CRE	ID	BD	7/15/2025
2020 PO9216072022	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	7/16/2025
2020 PO9206471925A	KU	5	30 OTH	SP	A	ID	BD	7/17/2025
2020 PO9206471925	KU	4	40 OTH	SP	CCA		V	7/18/2025
2020 PO9224571624	KU	4	40 OTH	SP	CCA		V	7/19/2025
2020 PO4845188187	F	4	40 BRO	SP	CRE		V	7/20/2025
2020 PO4847088194	F	4	35 BRO	SP	P		V	7/21/2025
2020 PO4848288198	F	4	40 BRO	SP	P		V	7/22/2025
2020 PO4696588478	LGE	4	35 BRN	SP	A	ED,ID	TD	7/23/2025
2020 PO4695888472	LGE	3	45 BRN	SP	S		V	7/24/2025
2020 PO4060897404	LGE	3	45 BRN	SP	S		V	7/25/2025

2020 PO9060570445	KU	6	30 OTH	SP	CRE	ED,ID,SRS	TD		7/26/2025
2020 PO9040270680A	KU	3	45 OTH	SP	CCA		V		7/27/2025
2020 PO5197112988	KU	6	30 ACE	SP	CRE	ED,ID	TD		7/28/2025
2020 PO4770288778	LGE	4	40 BRN	SP	CRE	ED,ID	TD		7/29/2025
2020 PO4638388284	LGE	4	40 ACE	SP	CRE	ED,EP,ID,IP	TD		7/30/2025
2020 PO4638288278	LGE	4	30 ACE	SP	CRE	ED,ID	TD		7/31/2025
2020 PO4639688261	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD		8/1/2025
2020 PO4639488268	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD		8/2/2025
2020 PO4769088802	LGE	4	40 BRN	SP	CRE	ED,ID	TD		8/3/2025
2020 PO4770288807	LGE	4	40 BRN	SP	CRE	ED,ID	TD		8/4/2025
2020 PO5295212891	KU	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	RP1	8/5/2025
2020 PO5299912875	KU	4	40 ACE	SP	P	ED	T		8/6/2025
2020 PO4757387154	LGE	4	40 BRO	SP	CCA		V		8/7/2025
2020 PO4759187148	LGE	4	40 BRO	SP	CCA		V		8/8/2025
2020 PO4704187710	LGE	3	50 BRO	SP	CCA		V		8/9/2025
2020 PO4702887730	LGE	3	45 BRO	SP	CCA		V		8/10/2025
2020 PO4166989625	LGE	1	50 BRO	SP	CCA		V		8/11/2025
2020 PO4636188110	LGE	4	40 ACE	SP	CRE	ED,ID	TD		8/12/2025
2020 PO4768588813	LGE	4	40 BRN	SP	A	ED,ID	BD		8/13/2025
2020 PO4771588828	LGE	4	40 BRN	SP	CRE	ED,ID	BD		8/14/2025
2020 PO5305312855	KU	3	45 ACE	SP	CRE	ED,ID	BD		8/15/2025
2020 PO4636888126	LGE	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	8/16/2025
2020 PO4636088127	LGE	4	30 ACE	SP	CRE	ED,ID	BD		8/17/2025
2020 PO4637188133	LGE	4	40 ACE	SP	CRE	ED,ID	BD		8/18/2025
2020 PO4636588140	LGE	4	30 ACE	SP	CRE	ED,ID	TD		8/19/2025
2020 PO4637388140	LGE	4	40 ACE	SP	CRE	ED,ID	BD		8/20/2025
2020 PO4637988153	LGE	4	40 ACE	SP	CRE	ED,ID	BD		8/21/2025
2020 PO4636688155	LGE	4	40 ACE	SP	CRE	ED,ID	BD		8/22/2025
2020 PO4635588189	LGE	4	40 ACE	SP	A	ED,ID	TD		8/23/2025
2020 PO4635188192	LGE	3	45 ACE	SP	CCA		V		8/24/2025
2020 PO5253713126	KU	5	35 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	X	RP1	8/25/2025
2020 PO4767988824	LGE	4	40 BRN	SP	A	ED,ID	BD		8/26/2025
2020 PO4770988840	LGE	4	40 BRN	SP	CRE	ED,HH,ID,IP	BX	PX	8/27/2025
2020 PO5242913231	KU	4	40 ACE	SP	CCA		V		8/28/2025
2020 PO4770388851	LGE	4	40 BRN	SP	CRE	ED,ID	BD		8/29/2025
2020 PO4767388856	LGE	4	40 BRN	SP	A	ED,ID	BD		8/30/2025
2020 PO5233213328	KU	4	40 ACE	SP	CRE	ED,ID	BD		8/31/2025
2020 PO5228713371	KU	4	40 ACE	SP	CRE	ED,ID	BD		9/1/2025
2020 PO5221513440	KU	4	40 ACE	SP	CRE	ED,ID	BD		9/2/2025
2020 PO4769688866	LGE	4	40 BRN	SP	CRE	ED,ID	BD		9/3/2025
2020 PO4768988879	LGE	4	40 BRN	SP	S		V		9/4/2025
2020 PO5271611658	KU	5	35 ACE	SP	CCA		V		9/5/2025
2020 PO4701487751	LGE	3	50 BRO	SP	CCA		V		9/6/2025
2020 PO4700487766	LGE	3	45 BRO	SP	CCA		V		9/7/2025
2020 PO4699487781	LGE	3	45 BRO	SP	CCA		V		9/8/2025
2020 PO4698387796	LGE	3	45 BRO	SP	CCA		V		9/9/2025
2020 PO4697487810	LGE	3	45 BRO	SP	CCA		V		9/10/2025

2020 PO4696487825	LGE	3	45 BRO	SP	CCA		V	9/11/2025
2020 PO4768388890	LGE	4	40 BRN	SP	A	ED,ID	BD	9/12/2025
2020 PO4764588893	LGE	4	40 BRN	SP	CRE	ED,ID	BD	9/13/2025
2020 PO4765188881	LGE	4	40 BRN	SP	CRE	ED,ID	BD	9/14/2025
2020 PO4765688869	LGE	4	40 BRN	SP	CCA		V	9/15/2025
2020 PO4768488943	LGE	4	40 BRN	SP	A	ED,ID	BD	9/16/2025
2020 PO9557335085	ODP	6	30 BRN	SP	CRE	ED,ID	TD	9/17/2025
2020 PO9559435175	F	4	40 BRN	SP	A		V	9/18/2025
2020 PO0480944026	ODP	4	40 BRN	SP	CCA		V	9/19/2025
2020 PO0509244136	F	6	30 BRN	SP	CRE		V	9/20/2025
2020 0480944026a	ODP	6	30 BRN	SP	CCA		V	9/21/2025
2020 PO4340512234	KU	2	45 BRO	SP	CRE		V	9/22/2025
2020 PO4660413860	F	4	40 BRO	SP	CRE		V	9/23/2025
2020 PO4648513739	F	4	40 BRO	SP	CRE		V	9/24/2025
2020 PO4698287859	LGE	3	45 BRO	SP	CCA		V	9/25/2025
2020 PO4699887871	LGE	3	45 BRO	SP	CCA		V	9/26/2025
2020 PO4699087865	LGE	3	45 BRO	SP	CCA		V	9/27/2025
2020 PO4696787849	LGE	3	45 BRO	SP	CCA		V	9/28/2025
2020 PO4695487840	LGE	3	50 BRO	SP	CCA		V	9/29/2025
2020 PO4697487854	LGE	3	45 BRO	SP	CCA		V	9/30/2025
2020 PO5273211767	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	10/1/2025
2020 PO5275211891	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	10/2/2025
2020 PO4643913690	F	4	40 BRO	SP	CRE	ID,RB	VX	RP2 10/3/2025
2020 PO4765988938	LGE	4	40 BRN	SP	CCA		V	10/4/2025
2020 PO4764988924	LGE	4	40 BRN	SP	A	ED,ID	BD	10/5/2025
2020 PO5278412004	KU	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX 10/6/2025
2020 PO0475543834	ODP	4	40 BRN	SP	CRE	ID	BD	10/7/2025
2020 PO0472543634	ODP	5	35 XXX	SP	CRE	ED,ID	TD	10/8/2025
2020 PO0487343653	ODP	6	30 XXX	SP	CCA		V	10/9/2025
2020 PO0643144246	ODP	5	35 XXX	SP	CCA		V	10/10/2025
2020 PO0648944066	ODP	4	30 XXX	SP	CRE	ED,ID	TD	10/11/2025
2020 PO0654243861	ODP	5	30 XXX	SP	CRE	ED,ID	TD	10/12/2025
2020 PO0667643467	ODP	5	35 XXX	SP	CRE	ED,ID	TD	10/13/2025
2020 PO0639743365	ODP	5	35 XXX	SP	CRE	ED,ID	TD	10/14/2025
2020 PO4615013520	KU	4	45 BRO	SP	CCA		V	10/15/2025
2020 PO4612713643	KU	4	40 BRO	SP	CCA		V	10/16/2025
2020 PO4633313579	F	4	40 BRO	SP	CRE		V	10/17/2025
2020 PO4607413728	KU	4	40 BRO	SP	CCA		V	10/18/2025
2020 PO5278712134	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	10/19/2025
2020 PO4809309097	KU	1	80 BRO	ST	CCA		V	10/20/2025
2020 PO4847808936	KU	1	75 BRO	ST	CRE		V	10/21/2025
2020 PO4863808873	KU	1	80 BRO	ST	CRE		V	10/22/2025
2020 PO5279312258	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	10/23/2025
2020 PO4888108772	KU	1	80 BRO	ST	CCA		V	10/24/2025
2020 PO4912108673	KU	1	75 BRO	SP	CRE		V	10/25/2025
2020 PO4919108644	KU	3	45 BRO	SP	CCA		V	10/26/2025
2020 PO5284912383	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	10/27/2025

2020 PO5287912502	KU	5	35 ACE	SP	CCA		V			10/28/2025
2020 PO4641188183	LGE	4	40 ACE	SP	CRE		V			10/29/2025
2020 PO4639688195	LGE	3	45 ACE	SP	A	ED,ID	BD			10/30/2025
2020 PO4639288185	LGE	4	40 ACE	SP	A	ED,ID,IP	TD			10/31/2025
2020 PO4638188197	LGE	4	30 ACE	SP	CCA		V			11/1/2025
2020 PO4640188219	LGE	4	40 ACE	SP	CRE	ED,ID,IP,RB	TX	RR		11/2/2025
2020 PO4641388217	LGE	4	40 ACE	SP	CCA		V			11/3/2025
2020 PO4642388225	LGE	4	40 ACE	SP	CRE	ED,ID	BD			11/4/2025
2020 PO4643488232	LGE	4	40 ACE	SP	CRE		V			11/5/2025
2020 PO4636988198	LGE	4	40 ACE	SP	CRE		V			11/6/2025
2020 PO4763988912	LGE	4	40 BRN	SP	A	ED,ID	BD			11/7/2025
2020 PO4763688911	LGE	4	40 BRN	SP	P	ED,ID	BD			11/8/2025
2020 PO4764288898	LGE	4	40 BRN	SP	S		V			11/9/2025
2020 PO4763388899	LGE	4	30 BRN	SP	CRE	ED,ID	BD			11/10/2025
2020 PO4326111699	KU	3	45 BRO	SP	CRE		V			11/11/2025
2020 PO4603611632	KU	1	75 BRO	SP	CRE	ED,ID,IP	TD			11/12/2025
2020 PO4591812096	KU	1	75 BRO	SP	CRE	ED,ID,IP	TD			11/13/2025
2020 PO5284612512	KU	4	40 ACE	SP	CRE	ED,ID	BD			11/14/2025
2020 PO5295212479	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD			11/15/2025
2020 PO5322512406	F	4	40 ACE	SP	P		V			11/16/2025
2020 PO4763788888	LGE	4	30 BRN	SP	CRE	ED,ID	BD			11/17/2025
2020 PO4764388877	LGE	4	30 BRN	SP	CRE	ED,ID	BD			11/18/2025
2020 PO4764888866	LGE	4	30 BRN	SP	P	ED,ID	BD			11/19/2025
2020 PO4039882998	LGE	4	30 BRO	SP	CRE	ED,ID	BD			11/20/2025
2020 PO4039583008	LGE	4	40 BRO	SP	CRE	ED,ID	BD			11/21/2025
2020 PO4039683022	LGE	4	40 BRO	SP	CRE	ED,ID	BD			11/22/2025
2020 PO4038383009	LGE	4	40 BRO	SP	CCA		V			11/23/2025
2020 PO4038283002	LGE	4	40 BRO	SP	CRE	ED,ID	BD			11/24/2025
2020 PO7559241588	LGE	4	30 BRO	SP	CCA		V			11/25/2025
2020 PO4597611873	KU	1	75 BRO	SP	CRE	ED,ID,IP	TD			11/26/2025
2020 PO5318612418	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD			11/27/2025
2020 PO5306612429	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD			11/28/2025
2020 PO5361813502	KU	4	40 ACE	SP	P		V			11/29/2025
2020 PO5365513599	KU	4	40 ACE	SP	P	ID	BD			11/30/2025
2020 PO5367713656	KU	4	40 ACE	SP	P	ID	BD			12/1/2025
2020 PO5368513681	KU	6	30 ACE	SP	CCA		V			12/2/2025
2020 PO4772288738	LGE	4	40 BRN	SP	CRE	HH,ID	TD			12/3/2025
2020 PO0577143025	ODP	5	35 BRN	SP	CRE	ED,ID	TD			12/4/2025
2020 PO0605643184	ODP	5	35 BRN	SP	CRE	ED,ID	TD			12/5/2025
2020 PO0620243262	ODP	5	35 BRN	SP	CRE	ED,ID	TD			12/6/2025
2020 PO0553742911	ODP	4	40 BRN	SP	CCA		V			12/7/2025
2020 PO0539842865	ODP	6	30 BRN	SP	CCA		V			12/8/2025
2020 PO4766288859	LGE	4	40 BRN	SP	CRE	ED,ID	TX	RR		12/9/2025
2020 PO4038082984	LGE	4	35 BRO	SP	CRE	ED,HH,ID,RB	TX	RR		12/10/2025
2020 PO4039882960	LGE	4	40 BRO	SP	A	ED,ID	TD			12/11/2025
2020 PO4188612338	KU	4	40 BRO	SP	CCA		V			12/12/2025
2020 PO4768488799	LGE	4	30 BRN	SP	CRE	ED,ID	TD			12/13/2025

2020 PO4769088786	LGE	4	30 BRN	SP	CRE	ED,ID	TD	12/14/2025
2020 PO4769488774	LGE	4	30 BRN	SP	CRE	ED,ID	BD	12/15/2025
2020 PO4770188763	LGE	4	30 BRN	SP	CRE		V	12/16/2025
2020 PO4335211774	KU	3	45 BRO	SP	CRE		V	12/17/2025
2020 PO4344811854	KU	3	45 BRO	SP	CRE		V	12/18/2025
2020 PO4358111965	KU	2	50 BRO	SP	CRE	ID,IP	BD	12/19/2025
2020 PO4370512067	KU	3	50 BRO	SP	P	ED	T	12/20/2025
2020 PO4350112179	KU	2	45 BRO	SP	CRE	ID,IP	BD	12/21/2025
2020 PO4833629668	KU	4	40 BRO	SP	CRE		V	12/22/2025
2020 PO4047182995	LGE	4	35 BRO	SP	CCA		V	12/23/2025
2020 PO4045582987	LGE	4	35 BRO	SP	P	ED,ID	TD	12/24/2025
2020 PO4770588751	LGE	4	30 BRN	SP	CRE	ED,ID,IP	BD	12/25/2025
2020 PO4839929856	KU	3	45 BRO	SP	CRE		V	12/26/2025
2020 PO4830429781	KU	4	40 BRO	SP	CRE		V	12/27/2025
2020 PO4841829894	KU	2	40 BRO	SP	CRE		V	12/28/2025
2020 PO5062812401	F	4	40E ACE	SP	P		V	12/29/2025
2020 PO5068812462	F	4	40 ACE	SP	P		V	12/30/2025
2020 PO5079212741	F	4	40 ACE	SP	P		V	12/31/2025
2020 PO5062512698	F	4	40 ACE	SP	P		V	1/1/2026
2020 PO4856613408	F	4	40 ACE	SP	P		V	1/2/2026
2020 PO4837913081	F	4	40 ACE	SP	P		V	1/3/2026
2020 PO4850413005	F	4	40 ACE	SP	CRE		V	1/4/2026
2020 PO4842813486	F	4	40 ACE	SP	CRE	ED,ID	V	1/5/2026
2020 PO4738013011	F	4	40 ACE	SP	P		V	1/6/2026
2020 PO4722212656	F	4	40 ACE	SP	CRE	ED,ID	V	1/7/2026
2020 PO4735412596	F	4	40 ACE	SP	CRE	ED,ID	V	1/8/2026
2020 PO4688413356	F	4	40 ACE	SP	CRE		V	1/9/2026
2020 PO4716713694	F	4	40 ACE	SP	P	ED,ID	V	1/10/2026
2020 PO4690013946	F	4	40 ACE	SP	CRE		V	1/11/2026
2020 PO4691314189	F	4	40 ACE	SP	P		V	1/12/2026
2020 PO4694914225	F	4	40 ACE	SP	P		V	1/13/2026
2020 PO4705014335	F	4	40 ACE	SP	CRE		V	1/14/2026
2020 PO4716014449	F	4	40 ACE	SP	P		V	1/15/2026
2020 PO4892114507	KU	6	30 ACE	SP	CCA		V	1/16/2026
2020 PO4843913957	F	4	40 ACE	SP	P		V	1/17/2026
2020 PO4828414003	F	4	40 ACE	SP	P		V	1/18/2026
2020 PO4840413879	F	4	40 ACE	SP	P		V	1/19/2026
2020 PO5069210407	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX PX	1/20/2026
2020 PO5074610540	KU	4	40 ACE	SP	P		V	1/21/2026
2020 PO5044010506	F	3	40 ACE	SP	P		V	1/22/2026
2020 PO5049410643	F	4	40 ACE	SP	P		V	1/23/2026
2020 PO4685088010	LGE	3	45 ACE	SP	CRE	ED,HH,ID,RB	VX PX	1/24/2026
2020 PO4685388046	LGE	4	40 ACE	SP	CRE	ED,ID	TD	1/25/2026
2020 PO4690787950	LGE	1H	75 ACE	SP	CRE		V	1/26/2026
2020 PO4688887952	LGE	UNK	75 ACE	SP	CRE		V	1/27/2026
2020 PO4689387959	LGE	3	45 ACE	SP	A		B	1/28/2026
2020 PO4689487972	LGE	4	40 ACE	SP	CRE		B	1/29/2026

2020 PO4690088000	LGE	UNK	30E	ACE	SP	CRE		V		1/30/2026
2020 PO4634888066	LGE	4	30	ACE	SP	A	ED,ID			1/31/2026
2020 PO4261104944	KU	4	40	BRO	SP	CRE	ED,ID,IP			2/1/2026
2020 PO4321104893	KU	4	40	BRO	SP	CRE	ED,ID,IP			2/2/2026
2020 PO6281446904	KU	4	40	ACE	SP	CRE	ED,ID			2/3/2026
2020 PO9382390199	KU	4	45	XXX	SP	CRE	ED,ID			2/4/2026
2020 PO4227804965	KU	4	40	BRO	SP	CRE	ED,ID,IP			2/5/2026
2020 PO4349505089	KU	4	40	BRO	SP	CRE	ED,ID,IP			2/6/2026
2020 PO6258646688	KU	4	40	ACE	SP	CRE	ED,ID			2/7/2026
2020 PO9391190221	KU	6	30	XXX	SP	CRE			V	2/8/2026
2020 PO6248346584	KU	3	50	ACE	SP	CRE	ED,ID			2/9/2026
2020 PO9379189211	KU	5	35	XXX	SP	CRE	ED,ID			2/10/2026
2020 PO9393289740	KU	5	35	XXX	SP	CRE			V	2/11/2026
2020 PO9378889450	KU	5	35	XXX	SP	CRE	ED,ID			2/12/2026
2020 PO9405688946	KU	5	35	XXX	SP	CRE	ED,ID			2/13/2026
2020 PO9383289729	KU	4	40	XXX	SP	CRE	ED,ID			2/14/2026
2020 PO0457195246	KU	4	40	ACW	SP	CRE	ED,ID			2/15/2026
2020 PO457195246A	KU	5	30	ACW	SP	CRE	ED,ID			2/16/2026
2020 PO6210546375	KU	6	30	ACE	SP	CRE	ED,ID			2/17/2026
2020 PO6221946564	KU	3	45	ACE	SP	CRE	ED,ID			2/18/2026
2020 PO4351004879	KU	4	40	BRO	SP	CRE	ED,ID			2/19/2026
2020 PO4384704874	KU	4	40	BRO	SP	CRE	ED,ID,IP			2/20/2026
2020 PO4345405418	KU	4	40	BRO	SP	CRE	ED,ID,IP			2/21/2026
2020 PO0473095567	KU	3	45	ACW	SP	CRE	ED,ID,IP			2/22/2026
2020 PO0505695047	KU	5	35	ACW	SP	CRE	ED,ID			2/23/2026
2020 PO0517195180	KU	4	45	ACW	SP	CRE	ED,ID			2/24/2026
2020 PO0490796024	KU	4	40	ACW	SP	CRE	ED,ID			2/25/2026
2020 PO0495896144	KU	6	30	ACW	SP	CRE	ED,ID,IP,SRC		TX	2/26/2026
2020 PO0496496193	C	7	20	ACW	SP	S			V	2/27/2026
2020 PO0522295863	KU	6	30	ACW	SP	CRE	ED,ID			2/28/2026
2020 PO0537595914	KU	5	35	ACW	SP	CRE	ED,ID,IP			3/1/2026
2020 PO6190846503	KU	4	40	ACE	SP	CRE	ED,ID,IP			3/2/2026
2020 PO6152346408	KU	4	40	ACE	SP	CRE	ED,ID,IP			3/3/2026
2020 PO9416088636	KU	5	35	XXX	SP	CRE	ID		BD	3/4/2026
2020 PO9428088440	KU	5	35	XXX	SP	CRE	ED,ID			3/5/2026
2020 PO4423804879	KU	4	40	BRO	SP	CRE	ED,ID,IP			3/6/2026
2020 PO9405187467	KU	5	35	XXX	SP	CRE	ED,ID			3/7/2026
2020 PO9420087690	KU	6	35	XXX	SP	CRE	ID		BD	3/8/2026
2020 PO4395405042	KU	4	40	BRO	SP	CRE	HH,RB		X	3/9/2026
2020 PO4440205670	KU	3	40	BRO	SP	CCA			V	3/10/2026
2020 PO4467405576	KU	4	40	BRO	SP	CRE	ED,HH,ID,IP			3/11/2026
2020 PO4411505281	KU	4	40	BRO	SP	CRE	ED,ID			3/12/2026
2020 PO4448605718	KU	5	35	BRO	SP	CCA			V	3/13/2026
2020 PO4456405523	KU	4	40	BRO	SP	CRE	ED,ID,IP			3/14/2026
2020 PO4563404676	KU	5	35	BRO	ST	P			V	3/15/2026
2020 PO6337546963	KU	6	30	ACE	SP	CCA			V	3/16/2026
2020 PO6351347230	KU	4	40	ACE	SP	CRE	ED,ID			3/17/2026

2020 PO6333847103	KU	4	40 ACE	SP	CRE	ED,ID	TD			3/18/2026
2020 PO9367987798	KU	5	30 BRN	SP	P	ED,ID	TD			3/19/2026
2020 PO9312886862	KU	4	40 XXX	SP	CRE	ED,ID	BX		RP1	3/20/2026
2020 PO9368086719	KU	4	40 XXX	SP	CRE	ED,ID	BX		RP1	3/21/2026
2020 PO9339886797	KU	5	35 XXX	SP	CRE	ED,ID	VX		RP2	3/22/2026
2020 PO9316987006	KU	4	40 XXX	SP	CRE	ED,ID	TD			3/23/2026
2020 PO6366647341	KU	4	40 ACE	SP	CRE	ED,ID	TD			3/24/2026
2020 PO6374447457	KU	4	40 ACE	SP	CRE	ED,ID	TD			3/25/2026
2020 PO6381447562	KU	4	40 ACE	SP	CRE	ED,ID	TD			3/26/2026
2020 PO6390847313	KU	5	35 ACE	SP	CRE	ED,ID	TD			3/27/2026
2020 PO4534904853	KU	4	45 BRO	SP	CRE		V			3/28/2026
2020 PO4564404380	F	4	40 BRO	SP	CCA		V			3/29/2026
2020 PO4523304782	KU	3	50 BRO	SP	CCA		V			3/30/2026
2020 PO4552104926	KU	3	40 BRO	SP	CRE	ID,IP	BD			3/31/2026
2020 PO5253639952	F	4	40 ACE	SP	A		V			4/1/2026
2020 PO5252639786	F	4	40 ACE	SP	CCA		V			4/2/2026
2020 PO5230939515	KU	4	40 ACE	SP	CCA		V			4/3/2026
2020 PO4758888642	LGE	1	75 BRN	SP	P		V			4/4/2026
2020 PO4761288650	LGE	1	75 BRN	SP	P		V			4/5/2026
2020 PO4763588658	LGE	1	75 BRN	SP	P		V			4/6/2026
2020 PO5409498758	KU	4	40 BRO	SP	CRE	ID	TD			4/7/2026
2020 PO0724751796	KU	4	45 BRN	SP	CRE	ED,HH,ID	X		RP1	4/8/2026
2020 PO5411798976	KU	4	40 BRO	SP	CRE	ID	TD			4/9/2026
2020 PO5258797352	KU	4	40 BRO	SP	CRE	ID	TD			4/10/2026
2020 PO5279497282	KU	5	35 BRO	SP	CRE	ID	BD			4/11/2026
2020 PO5279497282	KU	4	40 BRO	SP	CRE	ID	TD			4/12/2026
2020 PO5268097268	KU	4	40 BRO	SP	CRE	ID	TD			4/13/2026
2020 PO5267697338	KU	6	30 BRO	SP	CRE	ID	TD			4/14/2026
2020 PO5252797269	KU	6	30 BRO	SP	CCA		V			4/15/2026
2020 PO5240597298	KU	5	30 BRO	SP	CRE	ID	TD			4/16/2026
2020 PO5103197949	KU	6	30 BRO	SP	CRE		V			4/17/2026
2020 PO5181407265	KU	6	30 ACW	SP	CRE	ED,ID	TD			4/18/2026
2020 PO5172207278	KU	6	30 ACW	SP	CRE	ED,ID	TD			4/19/2026
2020 PO5168807275	KU	6	30 XXX	SP	CRE	ED,ID	TD			4/20/2026
2020 PO5178407198	KU	5	35 XXX	SP	CRE	ED,ID	TD			4/21/2026
2020 PO5177307123	KU	4	40 XXX	SP	CRE	ED,ID	TD			4/22/2026
2020 5162106892A	KU	6	30 ACW	SP	CRE	ED,ID	TD			4/23/2026
2020 PO5157806954	KU	5	35 XXX	SP	CRE	ED,ID	TD			4/24/2026
2020 PO1854448580	KU	5	35 BRN	SP	CRE	HH,ID	X		RP2	4/25/2026
2020 PO1820950056	KU	4	45 BRN	SP	CRE	ID,IP	BD			4/26/2026
2020 PO0304362080	KU	4	40 ACW	SP	CRE	ID	BD			4/27/2026
2020 PO0318361920	KU	4	40 ACW	SP	CRE	ED,ID	TD			4/28/2026
2020 PO9945755265	KU	5	35 BRN	SP	CRE	ED,ID,IP,SRC	TD			4/29/2026
2020 PO9934755521	KU	5	35 BRN	SP	CRE	ID	BD			4/30/2026
2020 PO9924255758	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD			5/1/2026
2020 PO4513101240	F	4	40 BRO	SP	CCA		V			5/2/2026
2020 PO4496401389	KU	5	30 BRO	SP	CRE	ID	TD			5/3/2026

2020 PO4487001254	F	4	40 BRO	SP	CRE		V			5/4/2026
2020 PO4493301225	KU	6	30 BRO	SP	CCA		V			5/5/2026
2020 PO4486101310	F	4	40 BRO	SP	CRE		V			5/6/2026
2020 PO4484001407	KU	5	30 BRO	SP	CCA		V			5/7/2026
2020 PO4475101390	KU	5	30 BRO	SP	CRE	ID				5/8/2026
2020 5139099408A	KU	6	30 KOP	SP	CCA		V			5/9/2026
2020 PO6640070667	KU	4	40 BRN	SP	CCA		V			5/10/2026
2020 PO4591602868	KU	4	45 XXX	SP	CRE	ED,ID,IP		TX	RR	5/11/2026
2020 PO7850972304	KU	5	35 BRO	SP	CCA		V			5/12/2026
2020 PO7846572352	KU	4	40 BRO	SP	CRE	ID			BD	5/13/2026
2020 PO7876172392	KU	4	40 BRO	SP	CRE	ED,ID			TD	5/14/2026
2020 PO7858172519	KU	4	40 BRO	SP	CRE	ED,ID			TD	5/15/2026
2020 PO7869672679	KU	4	40 BRO	SP	CRE	ID			BD	5/16/2026
2020 PO7881472843	KU	4	40 BRO	SP	CRE	ED,ID			TD	5/17/2026
2020 PO7894472979	KU	4	40 BRO	SP	CRE	ED,ID			TD	5/18/2026
2020 PO7918472967	KU	4	40 BRO	SP	CRE	ED,ID			TD	5/19/2026
2020 PO7919873026	KU	6	30 BRO	SP	CRE	ID			BD	5/20/2026
2020 PO4685399063	KU	4	40 BRO	SP	CRE	ID			BD	5/21/2026
2020 PO4680498855	KU	4	40 BRO	SP	CRE	ID			TD	5/22/2026
2020 PO4671398851	KU	6	30 BRO	SP	CCA		V			5/23/2026
2020 PO4683399627	KU	4	40 BRO	SP	CRE	ID			TD	5/24/2026
2020 PO4660299574	KU	6	30 BRO	SP	CRE	ID			TD	5/25/2026
2020 PO4762099366	KU	4	40 BRO	SP	CRE	ID			TD	5/26/2026
2020 PO3094967362	KU	6	30 BRN	SP	CRE	IP,RB		X	RP1	5/27/2026
2020 PO4741199517	KU	4	40 BRO	SP	CRE	ID			TD	5/28/2026
2020 PO4616203047	KU	6	30 XXX	SP	CRE	ED,ID			TD	5/29/2026
2020 PO4618102976	KU	5	35 XXX	SP	CRE	ED,ID			TD	5/30/2026
2020 PO4656303037	KU	6	30 XXX	SP	CRE	ED,ID			TD	5/31/2026
2020 PO4702503463	KU	4	40 XXX	SP	CRE	ED,ID			TD	6/1/2026
2020 PO4727003543	KU	3	45 XXX	SP	CRE	ED,ID			TD	6/2/2026
2020 PO4739903697	KU	4	45 XXX	SP	CRE	ED,ID			TD	6/3/2026
2020 PO4745304178	KU	4	40 XXX	SP	CRE	ED,ID			TD	6/4/2026
2020 PO4762903966	KU	5	35 XXX	SP	CRE	ED,ID			TD	6/5/2026
2020 PO4736603792	KU	5	35 BRN	SP	CCA		V			6/6/2026
2020 PO6544670057	KU	5	35 BRN	SP	CRE	ED,ID,IP			TD	6/7/2026
2020 PO6530069225	KU	4	40 BRN	SP	CRE	ED,ID			TD	6/8/2026
2020 PO8090272050	F	3	40 BRO	SP	CRE		V			6/9/2026
2020 PO8083972156	F	4	40 BRO	SP	P		V			6/10/2026
2020 PO3178164949	KU	5	35 BRN	SP	CRE	ID,IP,RB		X	RP1	6/11/2026
2020 PO3204365101	KU	5	35 BRN	SP	CRE	EP,HH,ID,IP,RB		X	RP1	6/12/2026
2020 PO3276564564	KU	4	30 BRN	SP	CRE	ED,HH,ID		X	RP2	6/13/2026
2020 PO3306664100	KU	6	30 BRN	SP	CRE	ED,IP,RB		X	RP2	6/14/2026
2020 PO0548765780	KU	4	40 BRO	SP	CRE	ED,ID,IP			TD	6/15/2026
2020 PO3291864317	KU	5	30 BRN	SP	CRE	ED,ID,IP			TD	6/16/2026
2020 PO3259564813	KU	4	40 BRN	SP	CRE	ID			TD	6/17/2026
2020 PO0594865506	KU	4	40 BRO	SP	CRE	ED,ID,IP			TD	6/18/2026
2020 PO0629965489	KU	4	45 BRO	SP	A	ED,ID,IP			TD	6/19/2026

2020 PO0648965479	KU	3	50 BRO	SP	A	ED,ID,IP	TD		6/20/2026
2020 PO0565265681	KU	3	50 BRO	SP	CCA		V		6/21/2026
2020 PO0545065717	KU	4	45 BRO	SP	CRE		V		6/22/2026
2020 PO0635565662	KU	5	35 BRO	SP	A	ED,ID,IP	TD		6/23/2026
2020 PO0646965885	KU	5	35 BRO	SP	A	RB	X	RP1	6/24/2026
2020 PO0661166288	KU	5	35 BRO	SP	A	ED,ID,IP	X	RP1	6/25/2026
2020 PO8076372274	F	3	40 BRO	SP	CRE		V		6/26/2026
2020 PO8080272876	KU	2	65 BRO	SP	CRE		V		6/27/2026
2020 PO8099072607	KU	2	70 BRO	SP	CRE		V		6/28/2026
2020 PO8070572517	KU	4	40 BRO	SP	CRE	ID	BD		6/29/2026
2020 PO8084172313	KU	6	30 BRO	SP	CRE	ED,ID	TD		6/30/2026
2020 PO8116272360	KU	2	65 BRO	SP	CRE		V		7/1/2026
2020 PO8109572295	KU	6	30 BRO	SP	CRE	ED,ID	TD		7/2/2026
2020 PO8090171750	KU	5	35 BRO	SP	CRE	ED,ID	TD		7/3/2026
2020 PO8078571882	KU	5	35 BRO	SP	CRE		V		7/4/2026
2020 PO8084571862	KU	6	30 BRO	SP	CRE	ID	BD		7/5/2026
2020 PO8090071706	KU	5	35 BRO	SP	CRE	ID	BD		7/6/2026
2020 PO8130172162	KU	2	65 BRO	SP	CRE		V		7/7/2026
2020 PO8117671989	KU	4	40 BRO	SP	CRE	ED,ID	TD		7/8/2026
2020 PO8148371899	KU	2	65 BRO	SP	CRE		V		7/9/2026
2020 PO8164571675	KU	2	65 BRO	SP	CRE		V		7/10/2026
2020 PO8142371656	KU	4	45 BRO	SP	CRE	ED,ID	BD		7/11/2026
2020 PO8130571748	KU	5	35 BRO	SP	CCA		V		7/12/2026
2020 PO7421082696	KU	5	35 BRN	SP	CRE	ED,HH,ID	TX	RR	7/13/2026
2020 PO8142871523	KU	4	45 BRO	SP	CCA		V		7/14/2026
2020 PO6598469143	KU	4	40 BRN	SP	CRE	ED,EP,ID	TD		7/15/2026
2020 PO6572269174	KU	4	40 BRN	SP	CRE	ED,ID	TD		7/16/2026
2020 PO6508469143-A	KU	4	40 BRN	SP	CCA		V		7/17/2026
2020 PO6506968871	KU	4	40 BRN	SP	CCA		V		7/18/2026
2020 PO6511268710	KU	4	45 BRN	SP	CCA		V		7/19/2026
2020 PO6535769592	KU	5	35 BRN	SP	CRE	ED,ID	BD		7/20/2026
2020 PO6534469512	KU	5	35 BRN	SP	CCA		V		7/21/2026
2020 PO6561869517	KU	4	40 BRN	SP	CCA		V		7/22/2026
2020 PO6588869522	KU	4	40 BRN	SP	CCA		V		7/23/2026
2020 PO1748144935	KU	4	45 BRN	SP	P	ED	TD		7/24/2026
2020 PO1731144980	KU	4	40 BRN	SP	CRE	ED,ID	TD		7/25/2026
2020 PO1704045052	KU	4	40 BRN	SP	CRE	ID	TD		7/26/2026
2020 PO1676645125	KU	4	35 BRN	DF	P	ED,ID,IP	TD		7/27/2026
2020 PO1654245186	KU	4	40 BRN	SP	CRE	ID	BD		7/28/2026
2020 PO1631145246	KU	4	40 BRN	SP	CRE	ID	TD		7/29/2026
2020 PO1602545323	KU	4	45 BRN	SP	CRE	ID	TD		7/30/2026
2020 PO7425382565	KU	5	35 BRN	SP	CRE	ED,HH,ID	TX	RR	7/31/2026
2020 PO7413282887	KU	5	35 BRN	SP	CRE	ED,ID	BD		8/1/2026
2020 PO5365807455	KU	3	40 XXX	SP	CRE	ID	BD		8/2/2026
2020 PO5375707360	KU	4	40 XXX	SP	CRE	ID,IP	BD		8/3/2026
2020 PO5379307319	F	5	30 XXX	SP	CRE		V		8/4/2026
2020 PO5386707243	KU	6	30 XXX	SP	CRE	ED,ID	TD		8/5/2026

2020 PO7765477788	KU	6	30 BRO	SP	CRE	ED,ID	TD	8/6/2026	
2020 PO7464982444	KU	4	40 BRN	SP	CRE	ED,ID	BD	8/7/2026	
2020 PO7465082420	KU	5	35 BRN	SP	CRE	ED,ID	BD	8/8/2026	
2020 PO7465382326	KU	2	45 BRN	SP	CRE		V	8/9/2026	
2020 PO7771477757	KU	6	30 BRO	SP	CRE	ED,ID	TD	8/10/2026	
2020 PO5381607430	F	6	30 XXX	SP	CRE		V	8/11/2026	
2020 PO7897576147	KU	5	35 BRO	SP	CRE	ID	BD	8/12/2026	
2020 PO7900176055	KU	5	30 BRO	SP	CRE	ED,ID	TD	8/13/2026	
2020 PO7846676208	KU	5	35 BRO	SP	CRE	HH,RB	VX	PX	8/14/2026
2020 PO1579254472	KU	5	35 BRN	SP	CRE	ID	TD	8/15/2026	
2020 PO2523261951	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD	8/16/2026	
2020 PO2527362057	KU	5	30 BRO	SP	CRE	ED,EP,ID,IP	TD	8/17/2026	
2020 PO1564254563	KU	3	45 BRN	SP	CCA		V	8/18/2026	
2020 PO1610254739	KU	4	40 BRN	SP	CRE	ID	TD	8/19/2026	
2020 PO1609054700	F	6	30E BRN	SP	CRE		V	8/20/2026	
2020 PO1591155162	KU	4	40 BRN	SP	CRE	ID	TD	8/21/2026	
2020 PO0648863056	KU	3	35 BRN	SP	CRE	ED,HH,ID	BX	RP1	8/22/2026
2020 PO0640662999	KU	2	50 BRN	SP	CRE	ID	BD	8/23/2026	
2020 PO0571262084	F	7	30E BRN	SP	CRE		V	8/24/2026	
2020 PO0516862626	KU	3	45 BRN	SP	CCA		V	8/25/2026	
2020 PO0486162394	KU	4	40 BRN	SP	CRE	ED,ID	BD	8/26/2026	
2020 PO0517262441	KU	4	45 BRN	SP	CRE	ED,ID	TD	8/27/2026	
2020 PO0518362183	KU	4	40 BRN	SP	CRE	ED,ID	TD	8/28/2026	
2020 PO0529762188	KU	6	30 BRN	SP	CRE	ED,ID	TD	8/29/2026	
2020 PO0551462199	KU	4	30 BRN	SP	CRE	ED,ID	TD	8/30/2026	
2020 PO0574462070	KU	4	45 BRN	SP	CRE		V	8/31/2026	
2020 PO5372507604	KU	6	30 XXX	SP	CRE	ED,ID	TD	9/1/2026	
2020 PO5376507582	KU	5	35 XXX	SP	CRE	ED,ID	TD	9/2/2026	
2020 PO5372107522	KU	4	40 XXX	SP	CRE	ED,ID	TD	9/3/2026	
2020 PO5375607492	KU	5	30 XXX	SP	CRE	ED,ID	TD	9/4/2026	
2020 PO7442183617	F	4	40 BRN	SP	CRE		V	9/5/2026	
2020 PO7446283784	KU	4	40 BRN	SP	CRE		V	9/6/2026	
2020 PO7445883708	KU	4	45 BRN	SP	CRE		V	9/7/2026	
2020 PO7440483646	F	4	40 BRN	SP	CRE		V	9/8/2026	
2020 PO7526382488	KU	6	30 BRN	SP	CRE	ED,ID	BD	9/9/2026	
2020 PO7556582408	KU	5	35 BRN	SP	CRE	ED,ID	TD	9/10/2026	
2020 PO7560982673	KU	4	40 BRN	SP	CRE	ED,ID	BD	9/11/2026	
2020 PO7563882688	KU	4	40 BRN	SP	CRE	ED,ID	BD	9/12/2026	
2020 PO7573682502	KU	4	40 BRN	SP	CCA		V	9/13/2026	
2020 PO7571182487	KU	6	30 BRN	SP	CRE		V	9/14/2026	
2020 PO7550682527	KU	6	30 BRN	SP	CRE	ED,ID	TD	9/15/2026	
2020 PO7547482603	KU	4	40 BRN	SP	CRE		BD	9/16/2026	
2020 PO0561262191	KU	4	45 BRN	SP	CRE	ED,HH,ID	TX	RR	9/17/2026
2020 PO0586162332	KU	6	30 BRN	SP	CRE	ID	TD	9/18/2026	
2020 PO0581162378	KU	4	40 BRN	SP	CRE	ID	TD	9/19/2026	
2020 PO0571262407	KU	5	30 BRN	SP	CRE	ID	TD	9/20/2026	
2020 PO0568962265	KU	6	30 BRN	SP	CCA		V	9/21/2026	

2020 PO9387688136	KU	4	40 BRO	SP	CCA		V	9/22/2026
2020 PO2011692994	KU	4	40 BRO	SP	CRE	ID	BD	9/23/2026
2020 PO1998293347	KU	4	40 BRO	SP	CCA		V	9/24/2026
2020 PO9495495303	F	4	40 BRO	SP	CRE		V	9/25/2026
2020 PO9788895970	KU	4	45 BRO	SP	CRE	ED,ID	BD	9/26/2026
2020 PO9577195275	KU	4	40 BRO	SP	CRE		B	9/27/2026
2020 PO1945592425	KU	5	45 BRO	SP	CRE		T	9/28/2026
2020 PO0194305765	KU	1	70 BRO	SP	CRE		V	9/29/2026
2020 PO9418695498	KU	4	40 BRO	SP	CCA		V	9/30/2026
2020 PO9413695698	KU	4	40 BRO	SP	CRE		B	10/1/2026
2020 PO1961391966	KU	5	35 BRO	SP	CRE	ID	BD	10/2/2026
2020 PO1921592658	KU	4	40 BRO	SP	CRE	ID	BD	10/3/2026
2020 PO1898392884	KU	4	40 BRO	SP	CRE	ID	BD	10/4/2026
2020 PO1869193167	KU	4	40 BRO	SP	CRE	ID	BD	10/5/2026
2020 PO9420095794	KU	4	40 BRO	SP	CRE	ED,ID	BD	10/6/2026
2020 PO9418896286	KU	4	45 BRO	SP	CRE		B	10/7/2026
2020 PO9435896626	KU	3	50 BRO	SP	CRE		B	10/8/2026
2020 PO9447196822	KU	4	40 BRO	SP	CRE		B	10/9/2026
2020 PO9476996932	KU	3	35 BRO	SP	CRE		B	10/10/2026
2020 PO9508097040	KU	3	50 BRO	SP	CRE		B	10/11/2026
2020 PO9407096032	KU	4	40 BRO	SP	CCA		V	10/12/2026
2020 PO9501096799	KU	4	45 BRO	SP	CCA		V	10/13/2026
2020 PO9509896647	KU	4	40 BRO	SP	CCA		V	10/14/2026
2020 PO9535497127	KU	3	55 BRO	SP	CRE	ID	BD	10/15/2026
2020 PO9667096756a	KU	3	40 BRO	SP	CCA		V	10/16/2026
2020 PO1103698960	F	4	40 BRO	SP	CRE		V	10/17/2026
2020 PO1098698885	F	6	30 BRO	SP	CRE		V	10/18/2026
2020 PO1995592669	KU	5	35 BRO	SP	CRE	ED,ID,SRC	TD	10/19/2026
2020 PO1982792409	KU	5	35 BRO	SP	CRE	ED,ID,SRC	TD	10/20/2026
2020 PO9358056374	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	10/21/2026
2020 PO9347156491	KU	4	40 ACW	SP	CRE	ED,EP,ID,IP	TD	10/22/2026
2020 PO9335556624	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	10/23/2026
2020 PO9322856759	KU	4	40 ACW	SP	CRE	ED,EP,HH,ID,IP,RB	X	RP1 10/24/2026
2020 PO9308856904	KU	4	40 ACW	SP	CRE	ED,ID	TD	10/25/2026
2020 PO1205279818	KU	4	40 BRN	SP	CRE	ID	BD	10/26/2026
2020 PO9286157000a	KU	4	40 ACW	SP	CRE	ED,ID	TD	10/27/2026
2020 PO9286157000	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	10/28/2026
2020 PO1182578490	KU	4	40 BRN	SP	CRE	ID,IP	BD	10/29/2026
2020 PO1154977984	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	10/30/2026
2020 PO1147377845	KU	3	50 BRN	SP	CRE	ED	TD	10/31/2026
2020 PO1183277296	KU	3	50 BRN	SP	CRE	ED	TD	11/1/2026
2020 PO1184677548	KU	4	40 BRN	SP	CCA		V	11/2/2026
2020 PO1142376863	KU	3	50 BRN	SP	CRE	ID	BD	11/3/2026
2020 PO1158477121	KU	3	50 BRN	SP	CRE	ED	TD	11/4/2026
2020 PO0350556667	KU	5	35 BRO	SP	CRE	ED,HH,ID,IP,RB	X	RP2 11/5/2026
2020 PO0200157128	KU	5	35 BRO	SP	CRE	ED,ID,SRC	TD	11/6/2026
2020 PO9250357260	KU	6	30 ACW	SP	CRE	ED,ID,IP	TD	11/7/2026

2020 PO9269857277	KU	5	40 ACW	SP	CRE	ED,ID	TD	11/8/2026
2020 PO9295457220	KU	4	40 ACW	SP	P	ED	T	11/9/2026
2020 PO0294656875	KU	5	35 BRO	SP	CRE	ED,ID,SRC	TD	11/10/2026
2020 PO0322356771	KU	5	35 BRO	SP	CRE	ED,ID,SRC	TD	11/11/2026
2020 PO0231257114	KU	5	35 BRO	SP	CRE	ID,IP	BD	11/12/2026
2020 PO9318757180	KU	4	40 ACW	SP	P	ED	T	11/13/2026
2020 PO9330857514	KU	3	45 ACW	SP	P	ED	T	11/14/2026
2020 PO9346157889	KU	3	45 ACW	SP	P	ED	T	11/15/2026
2020 PO9426360067a	KU	4	40 ACW	SP	CCA		V	11/16/2026
2020 PO9387658900	KU	4	40 ACW	SP	CRE	ED,ID	TD	11/17/2026
2020 PO0138561075	KU	6	30 BRO	SP	CRE		V	11/18/2026
2020 PO0208457201	KU	5	35 BRO	SP	CRE	ID,IP	BD	11/19/2026
2020 PO0196857243	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD	11/20/2026
2020 PO1090974714	KU	4	45 BRN	SP	CCA		V	11/21/2026
2020 PO1074574716	KU	2	60 BRN	SP	CRE	ID	BD	11/22/2026
2020 PO7555083304	KU	4	40 BRN	SP	CRE	ED,ID	TD	11/23/2026
2020 PO7542083235	KU	4	40 BRN	SP	CRE	ED,ID	TD	11/24/2026
2020 PO7387293396	KU	4	40 BRO	SP	CRE	ED,ID	TD	11/25/2026
2020 PO7195491333	KU	4	45 BRN	SP	CRE	ED,ID	BD	11/26/2026
2020 PO7541881664	F	4	45 BRN	SP	CRE		V	11/27/2026
2020 PO7547081565	F	3	45 BRN	SP	CRE		V	11/28/2026
2020 PO7551981467	F	4	45 BRN	SP	CRE		V	11/29/2026
2020 PO7557481361	F	4	45 BRN	SP	CRE		V	11/30/2026
2020 PO7562781258	F	3	50 BRN	SP	CRE		V	12/1/2026
2020 PO7567781160	F	4	45 BRN	SP	CRE		V	12/2/2026
2020 PO4811398547	KU	4	40 BRO	SP	CRE	ID	BD	12/3/2026
2020 PO5384096628	KU	5	35 BRO	SP	CRE	ID	TD	12/4/2026
2020 PO5331497041	KU	4	40 BRO	SP	CRE	ID	BD	12/5/2026
2020 PO5362396659	KU	6	30 BRO	SP	CRE	ID	TD	12/6/2026
2020 PO5384096628A	KU	4	40 BRO	SP	CRE	ID	TD	12/7/2026
2020 PO5361096825	KU	5	35 BRO	SP	CRE	ID	TD	12/8/2026
2020 PO5403396980	KU	5	35 BRO	SP	CRE	ID	TD	12/9/2026
2020 PO5230997447	KU	4	40 BRO	SP	CRE	ID	TD	12/10/2026
2020 PO5206997519	KU	5	35 BRO	SP	CRE	ID	BD	12/11/2026
2020 PO5195197711	KU	4	40 BRO	SP	CRE	ID	TD	12/12/2026
2020 PO5178697626	KU	4	40 BRO	SP	CRE	ID	TD	12/13/2026
2020 PO5107597719	KU	5	35 BRO	SP	CRE	ID	TD	12/14/2026
2020 PO5112697819	KU	4	40 BRO	SP	CRE	ED,ID	TD	12/15/2026
2020 PO9678660649	F	4	40 ACW	SP	CRE		V	12/16/2026
2020 PO9708260540	F	4	40 ACW	SP	P		V	12/17/2026
2020 PO9738160430	F	4	40 ACW	SP	CRE	ED,ID	V	12/18/2026
2020 PO0947872445	KU	3	50 BRO	SP	CRE	ED,ID,IP	TD	12/19/2026
2020 PO0956072685	KU	3	50 BRO	SP	CRE	ED,ID,IP	TD	12/20/2026
2020 PO0996171027	KU	4	40 BRO	SP	CCA		V	12/21/2026
2020 PO0934171617	KU	3	50 BRO	SP	CRE	ED,ID,IP	TD	12/22/2026
2020 PO9946459656	F	4	40 ACW	SP	CRE	ED,ID	V	12/23/2026
2020 PO9960959968	F	4	40 ACW	SP	CRE		V	12/24/2026

2020 PO0027361614	KU	6	30 ACW	SP	CCA		V	12/25/2026	
2020 PO0278451446	KU	6	30 BRO	SP	CRE	ED,ID,SRS	TD	12/26/2026	
2020 PO0023961539	F	4	40 ACW	SP	CRE		V	12/27/2026	
2020 PO0030661501	F	4	40 ACW	SP	P		V	12/28/2026	
2020 PO0039561447	F	4	40 ACW	SP	P		V	12/29/2026	
2020 PO0291151470	KU	4	40 BRO	SP	CRE	ID	BD	12/30/2026	
2020 PO8743124131	KU	4	40 UNK	SP	CRE	ED,ID,SRS	TD	12/31/2026	
2020 PO8732923675	KU	6	30 BRN	SP	CRE	ID	TD	1/1/2027	
2020 PO8723823503	KU	4	40 UNK	SP	CRE	ID	TD	1/2/2027	
2020 PO8688524205	KU	5	35 BRO	SP	CRE	ID	TD	1/3/2027	
2020 PO8825124217	KU	6	30 UNK	SP	CRE	ID	TD	1/4/2027	
2020 PO8741524087	KU	4	40 UNK	SP	CRE	ID	TD	1/5/2027	
2020 PO8721224218	KU	6	30 KOP	SP	CRE	ID	TD	1/6/2027	
2020 PO8697223793	KU	6	30 BRN	SP	CCA		V	1/7/2027	
2020 PO8836824182	KU	5	35 UNK	SP	CRE	ID	TD	1/8/2027	
2020 PO8763323909	KU	5	35 UNK	SP	CRE	ID	TD	1/9/2027	
2020 PO8734623851	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	1/10/2027	
2020 PO8722223958	KU	6	30 BRN	SP	CCA		V	1/11/2027	
2020 PO8799824095	KU	6	30 UNK	SP	CRE	ID	BD	1/12/2027	
2020 PO8804923871	KU	4	40 UNK	SP	CRE	ID	TD	1/13/2027	
2020 PO0313451973	KU	4	40 BRO	SP	CRE	ED,ID,SR	TD	1/14/2027	
2020 PO8748723608	KU	6	30 BRN	SP	CRE	ID	BD	1/15/2027	
2020 PO5303307215	KU	3	40 XXX	SP	CRE	ED,ID	TD	1/16/2027	
2020 PO1101234031	F	4	40 OTH	SP	CRE	ED	V	1/17/2027	
2020 PO5295707382	KU	4	40 XXX	SP	CRE	ED,ID	TD	1/18/2027	
2020 PO5288607528	KU	6	30 XXX	SP	CRE	ED,ID	TD	1/19/2027	
2020 PO5225906957	KU	4	45 BRN	SP	CCA		V	1/20/2027	
2020 5225906957A	KU	5	30 XXX	SP	CRE	ED,ID	TD	1/21/2027	
2020 PO5229806828	KU	6	30 BRN	SP	CRE	ED,ID	TD	1/22/2027	
2020 PO5241206883	KU	4	40 XXX	SP	CRE	ID	BD	1/23/2027	
2020 PO5247106825	KU	4	40 XXX	SP	CRE	ED,ID	TD	1/24/2027	
2020 PO9652653532	KU	6	30 BRN	SP	CRE		V	1/25/2027	
2020 PO9629053637	KU	6	30 BRN	SP	CRE	ED,ID,SR	TD	1/26/2027	
2020 PO1736650098	KU	4	40 BRN	SP	CRE	ID,IP	TD	1/27/2027	
2020 PO1727850072	KU	4	40 BRN	SP	CRE	ED,HH,IP,RB	X	PX	1/28/2027
2020 PO1691950077	KU	4	40 BRN	SP	CRE	ID,IP	TD	1/29/2027	
2020 PO1673050087	KU	4	40 BRN	SP	CRE	ID,IP	BD	1/30/2027	
2020 PO1653450218	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	1/31/2027	
2020 PO1634650484	F	7 25E	BRN	SP	CRE		V	2/1/2027	
2020 PO1628350401	KU	3	45 BRN	SP	CCA		V	2/2/2027	
2020 PO5170307060	KU	5	35 XXX	SP	CRE	ED,ID	TD	2/3/2027	
2020 PO0605061871	F	3	45 BRN	SP	P	ED,ID	VX	PX	2/4/2027
2020 PO5149207059	KU	6	30 ACW	SP	CRE	ED,ID	TD	2/5/2027	
2020 PO5135207017	KU	4	40 XXX	SP	CRE	ED,ID	TD	2/6/2027	
2020 PO5142906845	KU	5	35 XXX	SP	CRE	ED,ID	TD	2/7/2027	
2020 PO5098006775	F	4	40 XXX	SP	CRE		V	2/8/2027	
2020 PO8011173279	KU	6	30 BRO	SP	CRE	ED,ID	TD	2/9/2027	

2020 PO8049973175	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD			2/10/2027
2020 PO8047172868	KU	5	35 BRO	SP	CRE	ED,ID	VX	PX		2/11/2027
2020 PO8064172905	KU	5	35 BRO	SP	CRE	ED	TD			2/12/2027
2020 PO7579075939	KU	3	45 BRO	SP	CRE	ED,ID	BX	PX		2/13/2027
2020 PO7582681805	F	3	45 BRN	SP	CRE		V			2/14/2027
2020 PO7570781789	F	4	40 BRN	SP	CRE		V			2/15/2027
2020 PO7518081361	F	4	40 BRN	SP	CRE		V			2/16/2027
2020 PO7514281414	F	4	40 BRN	SP	CRE		V			2/17/2027
2020 PO0627579160	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD			2/18/2027
2020 PO0611279937	KU	3	40 BRN	SP	CRE		V			2/19/2027
2020 PO0622578982	KU	6	35 BRN	SP	CRE	ID	BD			2/20/2027
2020 PO9209064369	KU	4	40 ACW	SP	CRE	ED,ID	TD			2/21/2027
2020 PO9187763517	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD			2/22/2027
2020 PO9199563970	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD			2/23/2027
2020 PO0615379339	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD			2/24/2027
2020 PO0632879352	KU	4	40 BRN	SP	CRE	ED	TD			2/25/2027
2020 PO0826077719	KU	4	40 BRN	SP	CRE		V			2/26/2027
2020 PO1557470273	KU	5	35 BRN	SP	CRE		V			2/27/2027
2020 PO1526670267	KU	5	35 BRN	SP	CRE		V			2/28/2027
2020 PO1493270261	KU	5	35 BRN	SP	CRE		V			3/1/2027
2020 PO1460270259	KU	5	35 BRN	SP	CRE		V			3/2/2027
2020 PO0628979890	KU	3	40 BRN	SP	CRE	ID	BD			3/3/2027
2020 PO0649479911	KU	3	40 BRN	SP	CRE	ID	BD			3/4/2027
2020 PO0733976273	KU	4	40 BRN	SP	CRE		V			3/5/2027
2020 PO0765576311	KU	4	40 BRN	SP	CRE		V			3/6/2027
2020 PO7544181752	KU	6	30 BRN	SP	P	ED,ID	BD			3/7/2027
2020 PO8047173354	KU	2	65 BRO	SP	CRE		V			3/8/2027
2020 PO1021071678	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD			3/9/2027
2020 PO9247452571	KU	5	35 BRO	SP	CRE	ED,HH,ID,IP,RB	X	RP2		3/10/2027
2020 PO1446244681	KU	4	40 BRN	SP	CRE	ID	TD			3/11/2027
2020 PO9224552460	KU	4	40 BRO	SP	CRE	ID	BD			3/12/2027
2020 PO9194552353	KU	4	40 BRO	SP	CCA		V			3/13/2027
2020 PO9205152257	KU	4	40 BRO	SP	CRE	ED,EP,ID,SRS	TD			3/14/2027
2020 PO0697261899	KU	3	50 ACW	SP	CCA		V			3/15/2027
2020 PO1490045574	KU	6	35 BRN	SP	CRE	HH,RB	X	RP1		3/16/2027
2020 PO0669361855	KU	4	45 ACW	SP	CRE	EP,HH,RB	BX	PX		3/17/2027
2020 PO0664461878	KU	4	40 ACW	SP	CRE		B			3/18/2027
2020 PO0668961985	KU	4	40 ACW	SP	CRE		T			3/19/2027
2020 PO0675261987	KU	4	45 ACW	SP	CRE		B			3/20/2027
2020 PO0679662086	KU	4	45 ACW	SP	CCA		V			3/21/2027
2020 PO0679662086-A	KU	6	30 ACW	SP	CCA		V			3/22/2027
2020 PO0052361375	F	4	40 ACW	SP	P		V			3/23/2027
2020 PO0065961303	F	4	40 ACW	SP	P		V			3/24/2027
2020 PO0084161193	F	4	40 ACW	SP	P		V			3/25/2027
2020 PO0103861243	F	5	35 ACW	SP	CRE		V			3/26/2027
2020 PO0097561113	F	4	40 ACW	SP	CRE		V			3/27/2027
2020 PO0107561055	F	3	40 ACW	SP	P		V			3/28/2027

2020 PO0117960997	F	4	40 ACW	SP	CRE	ED,ID	V	3/29/2027
2020 PO0133760908	F	4	40 ACW	SP	P		V	3/30/2027
2020 PO0155560783	F	4	45 ACW	SP	CRE		V	3/31/2027
2020 PO0171260693	F	4	45 ACW	SP	P		V	4/1/2027
2020 PO0184060617	F	4	40 ACW	SP	CRE		V	4/2/2027
2020 PO0195860560	F	4	40 ACW	SP	CCA		V	4/3/2027
2020 PO0210360621	F	4	40 ACW	SP	CRE		V	4/4/2027
2020 PO0305151801	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD	4/5/2027
2020 PO0278851207	KU	4	45 BRO	SP	CRE	ED,ID,SRC	TD	4/6/2027
2020 PO0219460672	F	4	40 ACW	SP	CRE		V	4/7/2027
2020 PO0226360709	F	4	40 ACW	SP	CRE		V	4/8/2027
2020 PO0239060780	F	4	40 ACW	SP	CRE	ED,ID	V	4/9/2027
2020 PO8712124157	KU	4	40 UNK	SP	CRE	ID	TD	4/10/2027
2020 PO8805824256	KU	4	40 KOP	SP	CCA		V	4/11/2027
2020 PO8698123964	KU	6	30 OTH	SP	CCA		V	4/12/2027
2020 PO8713523922	KU	3	45 BRN	SP	CCA		V	4/13/2027
2020 PO8787823790	KU	2	50 OTH	SP	CRE	ED,ID,SRS	TD	4/14/2027
2020 PO8788224328	KU	4	40 BRN	SP	CCA		V	4/15/2027
2020 PO8717623875	KU	4	45 BRN	SP	CCA		V	4/16/2027
2020 PO8719923704	KU	6	30 BRN	SP	CRE	ID	TD	4/17/2027
2020 PO8852424228	KU	3	45 BRN	SP	CCA		V	4/18/2027
2020 PO8732824101	KU	4	40 UNK	SP	CRE	ID	TD	4/19/2027
2020 PO8778723825	KU	6	30 KOP	SP	CCA		V	4/20/2027
2020 PO3134338394	KU	4	45 BRN	SP	CRE	ID	BD	4/21/2027
2020 PO6994594078	KU	5	35 BRN	SP	CCA		V	4/22/2027
2020 PO7001894015	KU	4	40 BRN	SP	CRE	ED,ID	BD	4/23/2027
2020 PO3133338376	KU	6	30 BRN	SP	CCA		V	4/24/2027
2020 PO0250860761	F	7	20 ACW	SP	CRE		V	4/25/2027
2020 PO8680224430	KU	4	40 BRN	SP	CRE	ED,ID,SRS	TD	4/26/2027
2020 PO0249760841	F	4	40 ACW	SP	P	ED,ID	V	4/27/2027
2020 PO0257960890	F	4	40 ACW	SP	P		V	4/28/2027
2020 PO0278160989	F	4	40 ACW	SP	CRE		V	4/29/2027
2020 PO0289661040	F	4	40 ACW	SP	CRE		V	4/30/2027
2020 PO0301861093	F	4	40 ACW	SP	P	ED,ID	V	5/1/2027
2020 PO0314061145	F	4	40 ACW	SP	CRE	ED,ID	V	5/2/2027
2020 PO0327461204	F	4	40 ACW	SP	CRE	ED,EP,ID	V	5/3/2027
2020 PO0341861267	F	4	40 ACW	SP	P	ED,EP,ID	V	5/4/2027
2020 PO0355661327	F	4	40 ACW	SP	P		V	5/5/2027
2020 PO0366061349	F	4	40 ACW	SP	P		V	5/6/2027
2020 PO0694861109	KU	4	40 ACW	SP	CCA		V	5/7/2027
2020 PO0701561893	KU	5	45 ACW	OT	CRE		V	5/8/2027
2020 PO2513558248	KU	4	40 BRN	SP	CRE	ID	TD	5/9/2027
2020 PO2514058660	KU	4	40 BRN	SP	CRE	ID	TD	5/10/2027
2020 PO2513757824	KU	4	40 BRN	SP	CRE	ID	TD	5/11/2027
2020 PO1508445091	KU	4	40 BRN	SP	CRE	ID	TD	5/12/2027
2020 PO0291851256	KU	5	35 BRO	SP	CRE	ID	BD	5/13/2027
2020 PO8622724328	KU	4	40 INP	SP	CRE	ID	TD	5/14/2027

2020 PO8611524399	KU	4	40 INP	SP	CRE	ID	TD	5/15/2027	
2020 PO8604824477	KU	4	40 OTH	SP	CRE	ID	TD	5/16/2027	
2020 PO8610024575	KU	4	40 OTH	SP	CRE	ID	TD	5/17/2027	
2020 PO8641924801	KU	5	35 BRO	SP	CCA		V	5/18/2027	
2020 PO8639424918	KU	4	45 UNK	SP	CRE	ID	TD	5/19/2027	
2020 PO8657224705	KU	5	35 UNK	SP	CRE	ID	TD	5/20/2027	
2020 PO8652224249	KU	6	30 OTH	SP	CCA		V	5/21/2027	
2020 PO8648124817	KU	4	40 UNK	SP	CRE	ID	TD	5/22/2027	
2020 PO8651024651	KU	6	30 BRO	SP	CCA		V	5/23/2027	
2020 PO8579825140	KU	4	40 OTH	SP	CRE	ID	TD	5/24/2027	
2020 PO8594625112	KU	5	35 OTH	SP	CRE	ID	TD	5/25/2027	
2020 PO8602725091	KU	5	35 OTH	SP	CRE	ID	TD	5/26/2027	
2020 PO8618024825	KU	4	40 INP	SP	CRE	ID	TD	5/27/2027	
2020 PO8621824408	KU	6	30 KOP	SP	CCA		V	5/28/2027	
2020 PO0291751158	KU	4	40 BRO	SP	CCA		V	5/29/2027	
2020 PO6923199330	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD	5/30/2027	
2020 PO0290151220	F	4	40 BRO	SP	CRE		V	5/31/2027	
2020 PO9485753999	KU	4	40 BRO	SP	CRE	ED,ID,IP,RB,SRC	X	PX	6/1/2027
2020 PO0658361600	KU	3	45 ACW	SP	CCA		V	6/2/2027	
2020 PO0652161597	KU	4	45 ACW	SP	P		V	6/3/2027	
2020 PO0653961313	KU	6	30 ACW	SP	CCA		V	6/4/2027	
2020 PO0722761129	KU	4	40 ACW	SP	CRE	ID	BD	6/5/2027	
2020 PO0711361259	KU	4	40 ACW	SP	CRE	ID	BD	6/6/2027	
2020 PO0720161417	KU	3	45 ACW	SP	CCA		V	6/7/2027	
2020 PO0729561398	KU	3	45 ACW	SP	CCA		V	6/8/2027	
2020 PO0791661439	KU	4	40 ACW	SP	CCA		V	6/9/2027	
2020 PO6921599157	F	4	40 XXX	SP	CRE		V	6/10/2027	
2020 PO6930699008	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	6/11/2027	
2020 PO6944698926	KU	6	30 XXX	SP	CRE	ED,ID	TD	6/12/2027	
2020 PO6942398813	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	6/13/2027	
2020 PO7003695217	KU	1	75 BRN	SP	CRE		V	6/14/2027	
2020 PO4333533673	KU	5	35 BRO	SP	CCA		V	6/15/2027	
2020 PO4339433439	KU	2	50 BRO	SP	CCA		V	6/16/2027	
2020 PO4337533229	KU	1	60 BRO	SP	CCA		V	6/17/2027	
2020 PO4349333076	KU	2	55 BRO	SP	CCA		V	6/18/2027	
2020 PO4363032962	KU	2	55 BRO	SP	CCA		V	6/19/2027	
2020 PO4377332843	KU	2	55 BRO	SP	CCA		V	6/20/2027	
2020 PO4393732706	KU	2	50 BRO	SP	CCA		V	6/21/2027	
2020 PO4430432401	KU	3	45 BRO	SP	CCA		V	6/22/2027	
2020 PO6982595382	KU	1	75 BRN	SP	CCA		V	6/23/2027	
2020 PO6977295455	KU	1	75 BRN	SP	CCA		V	6/24/2027	
2020 PO6998395544	KU	6	30 BRN	SP	CRE		VX	RP3	6/25/2027
2020 PO6984295568	KU	4	45 BRN	SP	CRE	ED,ID	TD	6/26/2027	
2020 6274503552a	KU	6	30 XXX	SP	CRE	ED,ID	TD	6/27/2027	
2020 PO4438032336	KU	3	45 BRO	SP	CCA		V	6/28/2027	
2020 PO4445232273	KU	3	45 BRO	SP	P	ED	TD	6/29/2027	
2020 PO4445232273-A	KU	3	45 BRO	SP	CCA		V	6/30/2027	

2020 PO4464432107	KU	2	50 BRO	SP	CCA		V			7/1/2027
2020 PO4464432107	KU	2	50 BRO	SP	CCA		V			7/2/2027
2020 PO4486031919	KU	2	50 BRO	SP	CCA		V			7/3/2027
2020 PO4495531836	KU	2	55 BRO	SP	CCA		V			7/4/2027
2020 PO4504831751	KU	2	55 BRO	SP	CCA		V			7/5/2027
2020 PO4520731648	KU	3	45 BRO	SP	CCA		V			7/6/2027
2020 PO4532131579	KU	2	55 BRO	SP	CCA		V			7/7/2027
2020 PO4541931525	KU	2	55 BRO	SP	CCA		V			7/8/2027
2020 PO4554831457	KU	2	55 BRO	SP	CCA		V			7/9/2027
2020 PO4567131400	KU	2	55 BRO	SP	CCA		V			7/10/2027
2020 PO6274503552	KU	6	30 XXX	SP	CRE	ID	BD			7/11/2027
2020 PO7364891028	KU	4	45 BRO	SP	CCA		V			7/12/2027
2020 PO1791711412	KU	5	30 BRO	SP	CRE	ED,ID,RB	X		RP1	7/13/2027
2020 PO1816011419	KU	3	45 BRO	SP	CCA	ED,ID	TD			7/14/2027
2020 PO1805911519	KU	4	40 BRO	SP	CRE	ED,ID	TD			7/15/2027
2020 PO1830211693	KU	5	30 BRO	SP	CRE		V			7/16/2027
2020 PO1847611898	KU	6	30 BRO	SP	CRE	ED,ID	TD			7/17/2027
2020 PO1841311580	F	4	40 BRO	SP	CRE		V			7/18/2027
2020 PO1842511537	F	5	35 BRO	SP	CCA		V			7/19/2027
2020 PO1853611399	KU	6	30 BRO	SP	CRE	ED,ID	TD			7/20/2027
2020 PO1853211594	KU	6	30 BRO	SP	CRE	ED,ID	TD			7/21/2027
2020 PO1885011903	KU	6	30 BRO	SP	CRE	ED,ID	TD			7/22/2027
2020 PO1868511552	KU	3	45 BRO	SP	CCA		V			7/23/2027
2020 PO1880011446	KU	4	40 BRO	SP	CRE	ED,ID	TD			7/24/2027
2020 PO1892011522	KU	4	40 BRO	SP	CRE	ED,EP,ID	TD			7/25/2027
2020 PO1913811520	KU	4	40 BRO	SP	CRE	ID	BD			7/26/2027
2020 PO1913111437	KU	6	30 BRO	SP	CCA		V			7/27/2027
2020 PO6823020466	KU	4	40 XXX	SP	CRE		V			7/28/2027
2020 PO6940995007	KU	6	30 BRN	SP	A	ED,ID	TD			7/29/2027
2020 PO7400592033	KU	4	45 BRO	SP	CRE		V			7/30/2027
2020 PO8874222879	KU	5	35 UNK	SP	CRE	ED,EP,ID	X		RP2	7/31/2027
2020 PO8917223124	KU	6	30 ACW	SP	CRE	ID	TD			8/1/2027
2020 PO8966222548	KU	5	35 UNK	SP	CRE	ID	TD			8/2/2027
2020 PO8951622780	KU	5	35 UNK	SP	CRE	ID	TD			8/3/2027
2020 PO8896022919	KU	4	40 ACW	SP	CRE	ID	TD			8/4/2027
2020 PO8920822963	KU	4	40 ACW	SP	CRE	ID	TD			8/5/2027
2020 PO8976823059	KU	4	40 UNK	SP	CRE	ID	TD			8/6/2027
2020 PO8942722939	KU	6	30 INP	SP	CRE	ID	TD			8/7/2027
2020 PO7498692200	F	3	40 BRO	SP	CRE		V			8/8/2027
2020 PO7510192130	F	3	40 BRO	SP	CRE		V			8/9/2027
2020 PO7512392138	F	3	40 BRO	SP	CRE		V			8/10/2027
2020 PO7495592543	F	5	35 BRO	SP	CRE		V			8/11/2027
2020 PO7499492653	KU	6	30 BRO	SP	CCA		V			8/12/2027
2020 PO7514092560	KU	6	30 BRO	SP	P	ED,ID	TD			8/13/2027
2020 PO7534292445	KU	5	35 BRO	SP	CRE		V			8/14/2027
2020 PO7544092572	F	4	40 BRO	SP	CRE		V			8/15/2027
2020 PO8090101728	KU	5	35 XXX	SP	CRE	ED,ID,SRC	TX		RR	8/16/2027

2020 PO8078601603	KU	6	30 XXX	SP	CCA		V		8/17/2027
2020 PO8070001781	KU	4	40 XXX	SP	CCA	SRC	T		8/18/2027
2020 PO8094701540	KU	4	40 XXX	SP	CRE	ED,ID	TD		8/19/2027
2020 PO8152301681	KU	6	30 XXX	SP	CCA		V		8/20/2027
2020 PO8177101268	KU	4	40 XXX	SP	CCA		V		8/21/2027
2020 PO8197001193	KU	5	35 XXX	SP	CCA		V		8/22/2027
2020 PO8182201403	KU	5	30 XXX	SP	CCA		V		8/23/2027
2020 PO8229601174	KU	3	45 XXX	SP	CCA		V		8/24/2027
2020 PO8238801161	KU	5	35 XXX	SP	CRE	ED,ID,IP,SRC	TX	RR	8/25/2027
2020 PO9040270680	KU	3	45 OTH	SP	CRE	ED,ID,SRS	TD		8/26/2027
2020 PO0274378005	KU	3	45 XXX	SP	CCA		V		8/27/2027
2020 PO4307888237	LGE	4	40 ACW	SP	S		V		8/28/2027
2020 PO4305588174	LGE	3	45 ACW	SP	S		V		8/29/2027
2020 PO4306888172	LGE	4H	45 ACW	SP	S		V		8/30/2027
2020 PO3939282335	LGE	UNK	100 BRN	SP	CRE		V		8/31/2027
2020 PO4315488183	F	5	25 ACW	SP	CRE	ED,HH,ID,IP,RB	BX	PX	9/1/2027
2020 PO0573636380	ODP	4	40 ACW	SP	CRE	ED,ID	TD		9/2/2027
2020 PO3938882327	LGE	1	75 BRN	SP	CRE	ED,ID	BD		9/3/2027
2020 PO3938082307	LGE	1	80 BRN	SP	CRE	ED,ID	BD		9/4/2027
2020 PO3937682297	LGE	UNK	105 BRN	SP	CRE		V		9/5/2027
2020 PO2223144307	ODP	4	45 KOP	SP	CRE	ED,ID,RB,SRC	X	RP2	9/6/2027
2020 PO2237144402	ODP	4	40 KOP	SP	CRE	ED,EP,ID,RB	X	RP3	9/7/2027
2020 PO2214344360	F	4	40 KOP	DF	CRE		V		9/8/2027
2020 PO3937282288	LGE	1	85 BRN	SP	CRE	ED,ID	BD		9/9/2027
2020 PO3936482268	LGE	1	90 BRN	SP	CCA	ED,ID	BD		9/10/2027
2020 PO2088028210	ODP	4	40 BRN	SP	CCA		V		9/11/2027
2020 PO2080328312	ODP	4	40 BRN	SP	CCA		V		9/12/2027
2020 PO2077928252	F	4	35 BRN	SP	A		V		9/13/2027
2020 PO2073928397	ODP	4	40 BRN	SP	CCA		V		9/14/2027
2020 PO2064928518	ODP	4	40 BRN	SP	CRE	ID	TD		9/15/2027
2020 PO2058628683	F	4	40 BRN	SP	CRE		V		9/16/2027
2020 PO4312888196	F	4	40 ACW	SP	CRE		V		9/17/2027
2020 PO0247394092	LGE	2	55 ACW	SP	S		V		9/18/2027
2020 PO4312888193	LGE	1	55 ACW	SP	S		V		9/19/2027
2020 PO4310188216	LGE	1	70 ACW	SP	A	ED,ID	BD		9/20/2027
2020 PO4310388202	F	4	35 ACW	SP	S		V		9/21/2027
2020 PO4310188180	F	5	35 ACW	SP	S		V		9/22/2027
2020 PO4310988263	LGE	1	55 ACW	ST	CCA		V		9/23/2027
2020 PO4311088267	LGE	4	35 ACW	SP	CCA		V		9/24/2027
2020 PO4312088251	LGE	6	25 ACW	SP	CRE	ID	BD		9/25/2027
2020 PO4322488302	LGE	5	45 ACW	SP	S		V		9/26/2027
2020 PO4321588316	LGE	4	40 ACW	SP	S		V		9/27/2027
2020 PO4321988309	LGE	4	40 ACW	SP	CRE	ED,ID,IP	TD		9/28/2027
2020 PO4327688160	F	5	40 ACW	SP	P		V		9/29/2027
2020 PO4327488171	LGE	2	55 ACW	SP	CRE	ED,ID,IP	BD		9/30/2027
2020 PO4299688276	LGE	5	45 ACW	SP	CRE		V		10/1/2027
2020 PO4298988254	LGE	2	25 ACW	SP	A		V		10/2/2027

2020 PO4293388285	LGE	5	45 ACW	SP	CRE		V	10/3/2027
2020 PO4293988270	LGE	5	45 ACW	SP	CRE		V	10/4/2027
2020 PO1339220988	ODP	6	30 XXX	SP	CCA	ED	TD	10/5/2027
2020 PO3947282140	LGE	4	30 BRN	SP	CRE	ED,ID	TD	10/6/2027
2020 PO1493720956	ODP	6	30 XXX	SP	CRE	ED,ID,IP,SRC	TD	10/7/2027
2020 PO3934682655	LGE	3	55 BRO	SP	CRE	ED,ID	BD	10/8/2027
2020 PO3948382151	LGE	3	45 BRN	SP	S		V	10/9/2027
2020 PO3947682135	LGE	3	45 BRN	SP	S		V	10/10/2027
2020 PO3947082121	LGE	3	45 BRN	SP	S		V	10/11/2027
2020 PO3946382105	LGE	1	55 BRN	SP	S		V	10/12/2027
2020 PO3945782097	F	4	30 BRN	SP	CRE		V	10/13/2027
2020 PO3903282811	F	2	60 BRO	SP	CCA		V	10/14/2027
2020 PO3945782108	F	4	40 BRN	SP	S		V	10/15/2027
2020 PO3944182115	F	3	45 BRN	SP	A		V	10/16/2027
2020 PO1492521170	ODP	5	30 XXX	SP	CCA		V	10/17/2027
2020 PO1488621110	ODP	6	30 XXX	SP	CRE	ID	TD	10/18/2027
2020 PO1489421264	F	4	40 XXX	SP	P		V	10/19/2027
2020 PO147532111-A	ODP	5	35 XXX	SP	P		V	10/20/2027
2020 PO1475321118	F	4	40 XXX	SP	P	ED,MD	V	10/21/2027
2020 PO3942782122	F	3	45 BRN	SP	A		V	10/22/2027
2020 PO3942282118	F	4	30 BRN	SP	A		V	10/23/2027
2020 PO3943482112	F	4	30 BRN	SP	A		V	10/24/2027
2020 PO3932282663	LGE	4	40 BRO	SP	P	ED,ID	TD	10/25/2027
2020 PO3922282714	F	2	50 BRO	SP	CRE		V	10/26/2027
2020 PO3923582708	F	3	50 BRO	SP	CRE		V	10/27/2027
2020 PO3924082713	F	4	30 BRO	SP	CCA		V	10/28/2027
2020 PO3917882746	F	4	30 BRO	SP	CCA		V	10/29/2027
2020 PO3915382745	F	2	50 BRO	SP	P		V	10/30/2027
2020 PO3916482731	LGE	4	25 BRO	SP	CCA		V	10/31/2027
2020 PO3916782739	F	2	50 BRO	SP	CRE		V	11/1/2027
2020 PO3916282745	F	3	45 BRO	SP	CRE		V	11/2/2027
2020 PO3914082751	F	2	50 BRO	SP	CRE		V	11/3/2027
2020 PO3914882756	LGE	4	30 BRO	SP	CRE	ED,ID	TD	11/4/2027
2020 PO3955082182	LGE	4	35 BRN	SP	CCA		V	11/5/2027
2020 PO3953982188	LGE	4	35 BRN	SP	CCA		V	11/6/2027
2020 PO3953682197	LGE	4	35 BRN	SP	A	ED,ID	BD	11/7/2027
2020 PO3952182197	LGE	4	35 BRN	SP	P	ED,ID	TD	11/8/2027
2020 PO1462820973	ODP	5	35 XXX	SP	CCA	ED	V	11/9/2027
2020 PO1479820900	F	4	40 XXX	SP	P	ED	V	11/10/2027
2020 PO1484620680	F	4	40 XXX	SP	P		V	11/11/2027
2020 PO1489620485	F	4	40 XXX	SP	P		V	11/12/2027
2020 PO1500820331	ODP	6	35 XXX	SP	CRE	ID	TD	11/13/2027
2020 PO4617708404	F	4	40 ACE	SP	CRE		V	11/14/2027
2020 PO4629308410	F	4	40 ACE	SP	CRE	ED,ID	V	11/15/2027
2020 PO4608108395	F	4	40 ACE	SP	CRE		V	11/16/2027
2020 PO4648808423	F	4	40 ACE	SP	CRE		V	11/17/2027
2020 PO4577608368	F	4	40 ACE	SP	CRE		V	11/18/2027

2020 PO4564608358	F	4	40 ACE	SP	P		V	11/19/2027
2020 PO4628508531	F	4	40 ACE	SP	P		V	11/20/2027
2020 PO4589508378	F	4	40 ACE	SP	CRE	ED,EP,ID,IP	V	11/21/2027
2020 PO4501308342	KU	3	50 ACE	SP	CCA		V	11/22/2027
2020 PO4554608235	F	5	35 ACE	SP	CRE		V	11/23/2027
2020 PO4573308171	F	5	35 ACE	SP	CRE		V	11/24/2027
2020 PO3948582181	LGE	4	30 BRN	SP	A	ED,ID	TD	11/25/2027
2020 PO3949582179	LGE	3	45 BRN	SP	A	HH,ID	TD	11/26/2027
2020 PO3948982178	LGE	5	30 BRN	SP	CRE		V	11/27/2027
2020 PO3911282765	F	4	50 BRO	SP	CCA		V	11/28/2027
2020 PO3904782795	F	1	70 BRO	SP	CCA		V	11/29/2027
2020 PO3909082775	F	3	50 BRO	SP	CCA		V	11/30/2027
2020 PO3906982784	F	1	60 BRO	SP	CCA		V	12/1/2027
2020 PO3912982763	F	5	25 BRO	SP	CCA		V	12/2/2027
2020 PO3901882829	F	2	50 BRO	SP	A		V	12/3/2027
2020 PO3900382843	F	2	60 BRO	SP	CRE		V	12/4/2027
2020 PO3899482854	F	2	70 BRO	SP	P		V	12/5/2027
2020 PO3896882852	F	4	30 BRO	SP	CCA		V	12/6/2027
2020 PO3918182732	F	4	50 BRO	SP	CRE		V	12/7/2027
2020 PO3919582726	F	3	50 BRO	SP	CCA		V	12/8/2027
2020 PO3920982720	F	4	50 BRO	SP	CRE		V	12/9/2027
2020 PO3921482724	F	4	30 BRO	SP	CRE		V	12/10/2027
2020 PO3920182732	F	3	45 BRO	SP	CCA		V	12/11/2027
2020 PO3920582731	LGE	4	30 BRO	SP	CCA	ED,ID	BX	12/12/2027
2020 PO3921382738	LGE	4	30 BRO	SP	CCA		V	12/13/2027
2020 PO3920982750	F	3	45 BRO	SP	CCA		V	12/14/2027
2020 PO3921382757	LGE	4	30 BRO	SP	P	ED,ID	TD	12/15/2027
2020 PO3921682764	LGE	4	40 BRO	SP	CCA		V	12/16/2027
2020 PO3922382778	F	4	40 BRO	SP	CCA		V	12/17/2027
2020 PO3923582791	F	4	30 BRO	SP	CCA		V	12/18/2027
2020 PO3923082792	F	3	45 BRO	SP	CCA		V	12/19/2027
2020 PO3923482799	F	4	40 BRO	SP	CCA		V	12/20/2027
2020 PO3924582788	LGE	4	35 BRO	SP	CCA		V	12/21/2027
2020 PO3923882798	LGE	5	25 BRO	SP	CCA		V	12/22/2027
2020 PO3923082817	F	3	30 BRO	SP	CCA		V	12/23/2027
2020 PO3923882810	F	3	45 BRO	SP	CCA		V	12/24/2027
2020 PO3924482817	F	4	40 BRO	SP	CCA		V	12/25/2027
2020 PO3924682832	LGE	4	35 BRO	SP	CCA	ED,ID	BD	12/26/2027
2020 PO3925782814	F	3	45 BRO	SP	CCA		V	12/27/2027
2020 PO3898682849	LGE	4	30 BRO	SP	CRE	ED,ID	TD	12/28/2027
2020 PO1503820208	ODP	6	30 XXX	SP	CRE	ED,ID,IP	TD	12/29/2027
2020 PO1461119881	ODP	4	40 XXX	SP	CRE	ID	TD	12/30/2027
2020 PO3950182193	LGE	3	35 BRN	SP	CRE	ED,ID	TD	12/31/2027
2020 PO3949782195	LGE	4	40 BRN	SP	CRE	ED,ID	BD	1/1/2028
2020 PO3626714157	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	1/2/2028
2020 PO3739213582	KU	6	30 BRO	SP	CCA		V	1/3/2028
2020 PO3950982210	LGE	3	45 BRN	SP	S		V	1/4/2028

2020 PO3951182214	LGE	3	45 BRN	SP	S		V	1/5/2028	
2020 PO3952082233	LGE	4	40 BRN	SP	CRE	ED,ID	BD	1/6/2028	
2020 PO3951382234	LGE	4	30 BRN	SP	A	ED,ID	TD	1/7/2028	
2020 PO4593308189	F	5	35 ACE	SP	CRE		V	1/8/2028	
2020 PO4612108255	F	5	35 ACE	SP	CRE		V	1/9/2028	
2020 PO4634208309	F	5	35 ACE	SP	P		V	1/10/2028	
2020 PO4653308339	F	4	40 ACE	SP	CRE		V	1/11/2028	
2020 PO3917082772	F	4	40 BRO	SP	CCA		V	1/12/2028	
2020 PO3917082772	LGE	4	30 BRO	SP	CCA		V	1/13/2028	
2020 PO3917482772A	F	4	35 BRO	SP	A		V	1/14/2028	
2020 PO3917482772	F	3	45 BRO	SP	A		V	1/15/2028	
2020 PO3918582755	F	4	30 BRO	SP	CCA		V	1/16/2028	
2020 PO3919082767	F	4	35 BRO	SP	CCA		V	1/17/2028	
2020 PO3922582720	F	4	40 BRO	SP	CRE		V	1/18/2028	
2020 PO3924082752	F	4	40 BRO	SP	CCA	ED	VX	PX	1/19/2028
2020 PO3927882821	LGE	4	35 BRO	SP	A	ED,ID	TD	1/20/2028	
2020 PO3927382813	F	4	40 BRO	SP	CCA		V	1/21/2028	
2020 PO3952382252	LGE	4	30 BRN	SP	A	ED,ID	TD	1/22/2028	
2020 PO3952082246	LGE	4	30 BRN	SP	A	ED,ID	TD	1/23/2028	
2020 PO3596514402	KU	4	40 BRO	SP	CRE	ID,IP	BD	1/24/2028	
2020 PO3597114583	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	1/25/2028	
2020 PO3952382241-A	LGE	3	45 BRN	SP	A	ED,ID	BD	1/26/2028	
2020 PO4679408450	F	4	40 ACE	SP	CRE		V	1/27/2028	
2020 PO4667608437	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	VX	RP1	1/28/2028
2020 PO4672208352	F	5	35 ACE	SP	P		V	1/29/2028	
2020 PO3952382241	LGE	3	45 BRN	SP	S		V	1/30/2028	
2020 PO3952782265	LGE	4	30 BRN	SP	A	ED,ID	TD	1/31/2028	
2020 PO4696108389	F	4	40 ACE	SP	CCA		V	2/1/2028	
2020 PO4714608322	F	4	40 ACE	SP	CRE		V	2/2/2028	
2020 PO4726608162	F	4	40 ACE	SP	P		V	2/3/2028	
2020 PO4730808264	F	4	40 ACE	SP	CRE		V	2/4/2028	
2020 PO4737609334	F	4	40 ACE	SP	P	ED,ID,IP	V	2/5/2028	
2020 PO3953582259	LGE	3	50 BRN	SP	A	ED,ID	BD	2/6/2028	
2020 PO3609714261	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	2/7/2028	
2020 PO3647813782	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	2/8/2028	
2020 PO3954082278	LGE	3	45 BRN	SP	A	ED,ID	TD	2/9/2028	
2020 PO3953882281	LGE	4	30 BRN	SP	CRE	ED,ID	TD	2/10/2028	
2020 PO3955082282	LGE	4	35 BRN	SP	CRE		V	2/11/2028	
2020 PO3953982288	LGE	4	35 BRN	SP	CCA		V	2/12/2028	
2020 PO3626413407	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	2/13/2028	
2020 PO3562314478	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	2/14/2028	
2020 PO3563014978	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	2/15/2028	
2020 PO3925882789	F	4	40 BRO	SP	CCA		V	2/16/2028	
2020 PO3923382738	F	4	40 BRO	SP	CCA		V	2/17/2028	
2020 PO3924782767	F	4	40 BRO	SP	CCA		V	2/18/2028	
2020 PO3925482781	F	4	40 BRO	SP	CCA		V	2/19/2028	
2020 PO3926882801	F	4	40 BRO	SP	CCA		V	2/20/2028	

2020 PO3928382759	F	4	40 BRO	SP	CRE		V	2/21/2028
2020 PO3929182768	F	4	35 BRO	SP	CRE		V	2/22/2028
2020 PO3928882770	F	4	40 BRO	SP	CRE		V	2/23/2028
2020 PO3957582618	F	4	30 BRN	SP	CRE		V	2/24/2028
2020 PO3958082614	F	4	40 BRN	DF	CRE		V	2/25/2028
2020 PO6194188885	KU	4	40 BRN	SP	CRE		V	2/26/2028
2020 PO6208188787	KU	4	40 BRN	SP	CRE		V	2/27/2028
2020 PO6236788566	KU	4	40 BRN	SP	CRE		V	2/28/2028
2020 PO6219088699	KU	4	40 BRN	SP	CRE		V	2/29/2028
2020 PO4178830614	KU	4	40 BRO	SP	CRE	ID,IP	BD	3/1/2028
2020 PO3957782611	F	4	30 BRN	SP	CCA		V	3/2/2028
2020 PO3958182607	F	4	40 BRN	SP	CCA		V	3/3/2028
2020 PO4522831977	KU	3	45 ACE	SP	CRE	ED,ID	BD	3/4/2028
2020 PO1225420704	ODP	5	35 XXX	SP	CCA		V	3/5/2028
2020 PO1218520160	F	4	40 XXX	SP	CRE		V	3/6/2028
2020 PO1205220630	F	4	40 XXX	SP	A		V	3/7/2028
2020 PO1214320865	F	4	40 XXX	SP	A		V	3/8/2028
2020 PO1228220537	ODP	4	40 BRN	SP	CCA	ED,SRS	TD	3/9/2028
2020 PO1201720823	F	4	40 XXX	SP	A		V	3/10/2028
2020 PO3595633642	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD	3/11/2028
2020 PO3579833341	KU	4	40 BRN	SP	CCA		V	3/12/2028
2020 PO3597333012	KU	4	40 BRN	SP	CRE	ED,ID,MD	TD	3/13/2028
2020 PO3651132027	KU	4	40 BRN	SP	CCA		B	3/14/2028
2020 PO3615332684	KU	5	35 BRN	SP	CRE	ID	BD	3/15/2028
2020 PO3618531899	KU	5	35 BRN	SP	CRE	ED,ID,SRS	TD	3/16/2028
2020 PO3686331378	KU	5	35 BRN	SP	CRE	ED,ID,IP,SRC	TD	3/17/2028
2020 PO3647931265	KU	5	35 BRN	SP	CRE	ED,ID,IP,SRS	TD	3/18/2028
2020 PO3610431159	KU	4	40 BRN	SP	P		T	3/19/2028
2020 PO3597530790	KU	4	40 BRN	SP	CRE	ID	BD	3/20/2028
2020 PO3959382526	F	4	40 BRN	SP	CRE		V	3/21/2028
2020 PO3959882520	LGE	4	30 BRN	SP	CRE	ED,ID	TD	3/22/2028
2020 PO4200530381	KU	4	40 BRO	SP	CRE	ID,IP	BD	3/23/2028
2020 PO4185029995	KU	4	40 BRO	SP	CRE	ID,IP	BD	3/24/2028
2020 PO4208630587	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	3/25/2028
2020 PO4217630830	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	3/26/2028
2020 PO9974633168	ODP	6	30 XXX	SP	CRE		V	3/27/2028
2020 PO0014732976	ODP	4	35 XXX	SP	CCA		V	3/28/2028
2020 PO3959482513	F	4	40 BRN	SP	CRE		V	3/29/2028
2020 PO3959782496	F	4	45 BRN	SP	CRE		V	3/30/2028
2020 PO3959382497	F	4	35 BRN	SP	A		V	3/31/2028
2020 PO3960382474	LGE	6	25 BRN	SP	CRE	ED,ID	TD	4/1/2028
2020 PO0028433556	ODP	4	35 XXX	SP	CRE	ED,ID,IP	TD	4/2/2028
2020 PO0005433683	ODP	4	45 BRN	SP	CCA		V	4/3/2028
2020 PO9987333816	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD	4/4/2028
2020 PO4181031135	KU	3	35 BRO	SP	CRE	ED,ID,IP	TD	4/5/2028
2020 PO4226131047	KU	3	45 BRO	SP	CCA		V	4/6/2028
2020 PO3586947377	F	4	40 BRO	SP	CRE		V	4/7/2028

2020 PO3574947467	F	4	40 BRO	SP	CRE		V			4/8/2028
2020 PO3697846548	F	4	40 BRO	SP	CRE		V			4/9/2028
2020 PO3691446604	F	4	40 BRO	SP	CRE		V			4/10/2028
2020 PO3687746637	F	4	40 BRO	SP	CRE		V			4/11/2028
2020 PO3678046708	F	4	40 BRO	SP	CRE		V			4/12/2028
2020 PO3793345779	F	4	40 BRO	SP	CRE		V			4/13/2028
2020 PO3810545677	F	4	40 BRO	SP	CRE		V			4/14/2028
2020 PO4550631802	KU	6	30 ACE	SP	CRE		V			4/15/2028
2020 PO3958982479	F	4	40 BRN	SP	A		V			4/16/2028
2020 PO3958882464	F	4	40 BRN	SP	CCA		V			4/17/2028
2020 PO3958282451	F	4	40 BRN	SP	CRE		V			4/18/2028
2020 PO3957682438	F	4	40 BRN	SP	CRE		V			4/19/2028
2020 PO3958782433	LGE	6	25 BRN	SP	CRE	ED,ID	BD			4/20/2028
2020 PO2406427771	ODP	4	40 BRN	SP	CRE	ID	TD			4/21/2028
2020 PO2429727756	ODP	4	40 BRN	SP	CCA		V			4/22/2028
2020 Po2429727756a	ODP	4	40 BRN	SP	CCA		V			4/23/2028
2020 PO2414127612	F	5	35 BRN	SP	A		V			4/24/2028
2020 PO2468627729	ODP	5	35 BRN	SP	CRE	ID	TD			4/25/2028
2020 PO1155221192A	ODP	4	40 KOP	SP	CCA	ED,SRS	TD			4/26/2028
2020 PO1172921434	ODP	4	40 BRN	SP	CRE	HH,ID	X		PX	4/27/2028
2020 PO3956982422	F	4	40 BRN	SP	CRE		V			4/28/2028
2020 PO9933334109	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD			4/29/2028
2020 PO9913634131	ODP	6	30 BRN	SP	CCA		V			4/30/2028
2020 PO3956982406	LGE	4	30 BRN	SP	A	ED,ID	BD			5/1/2028
2020 PO3956282408	F	4	40 BRN	SP	CRE		V			5/2/2028
2020 PO2482327730	F	4	40 BRN	SP	A		V			5/3/2028
2020 PO2500927716	ODP	4	40 BRN	SP	CRE	ID	TD			5/4/2028
2020 PO2508027832	F	5	35 BRN	SP	CRE		V			5/5/2028
2020 PO2511927967	ODP	6	30 BRN	SP	CRE		V			5/6/2028
2020 PO4294702212	KU	6	30 BRO	SP	CCA		V			5/7/2028
2020 PO4283902213	F	4	40 BRO	SP	CCA		V			5/8/2028
2020 PO3231351081	KU	4	40 ACE	SP	CRE	ED,ID	TD			5/9/2028
2020 PO3225950985	KU	6	30 ACE	SP	CCA		V			5/10/2028
2020 PO3900982512	F	3	45 BRO	SP	CCA		V			5/11/2028
2020 PO3899282519	LGE	4	35 BRO	SP	A	ED,ID	TD			5/12/2028
2020 PO3900382503	LGE	4	40 BRO	SP	P	ED,HH,ID,RB	X		RP2	5/13/2028
2020 PO2703927505	ODP	4	40 BRN	SP	CRE	ID	TD			5/14/2028
2020 PO3975682733	LGE	4	35 BRN	SP	CRE		V			5/15/2028
2020 PO3975782730	F	3	45 BRN	SP	S		V			5/16/2028
2020 PO3975882717	F	4	45 BRN	SP	CRE		V			5/17/2028
2020 PO3975982703	F	3	45 BRN	SP	S		V			5/18/2028
2020 PO3976582692	F	6	30 BRN	SP	CRE		V			5/19/2028
2020 PO3976082690	F	4	40 BRN	SP	A		V			5/20/2028
2020 PO3976582680	F	4	30 BRN	SP	CCA		V			5/21/2028
2020 PO3976182677	F	6	40 BRN	SP	CRE		V			5/22/2028
2020 PO3976782666	F	4	30 BRN	SP	A		V			5/23/2028
2020 PO3976282665	F	4	40 BRN	SP	A		V			5/24/2028

2020 PO3976782654	F	4	30 BRN	SP	A		V			5/25/2028
2020 PO3976382651	F	4	40 BRN	SP	A		V			5/26/2028
2020 PO3976882641	F	4	30 BRN	SP	A		V			5/27/2028
2020 PO3976482637	F	4	40 BRN	SP	CRE		V			5/28/2028
2020 PO3878882654	LGE	4	40 BRO	SP	P	ED,HH,ID,SRS	TX		RR	5/29/2028
2020 PO3976982627	F	4	30 BRN	SP	CRE		V			5/30/2028
2020 PO3976582623	F	4	40 BRN	SP	CCA		V			5/31/2028
2020 PO3878382649	LGE	4	30 BRO	SP	A	ED,ID,IP,RB,SRC	TX		RR	6/1/2028
2020 PO3977082614	F	4	30 BRN	SP	CCA		V			6/2/2028
2020 PO3091950810	KU	4	40 BRO	SP	CRE	ED,ID	TD			6/3/2028
2020 KU	LGE	2	50 BRN	SP	CRE	ED,ID	TD			6/4/2028
2020 PO3913282169	LGE	3	50 BRN	SP	CCA		V			6/5/2028
2020 PO3913882185	LGE	3	45 BRN	SP	CRE	ED,ID	TD			6/6/2028
2020 PO3976582609	F	4	40 BRN	SP	CRE		V			6/7/2028
2020 PO3977182601	F	7	30 BRN	SP	CRE		V			6/8/2028
2020 PO3976782594	F	3	45 BRN	SP	S		V			6/9/2028
2020 PO3915782221	LGE	2	60 BRN	SP	CRE	ED,ID	BD			6/10/2028
2020 PO4559135718	KU	4	45 ACE	SP	CCA		V			6/11/2028
2020 PO4551435828	KU	4	45 ACE	SP	CCA		V			6/12/2028
2020 PO4546335779	KU	3	45 ACE	SP	CCA		V			6/13/2028
2020 PO2309627226	ODP	4	40 XXX	SP	CRE	ID	TD			6/14/2028
2020 PO2154021984	ODP	4	40 XXX	SP	CCA		V			6/15/2028
2020 PO2134522148	ODP	4	40 XXX	SP	CCA		V			6/16/2028
2020 PO2239624129	F	4	40 XXX	SP	CRE		V			6/17/2028
2020 PO1281123207	ODP	4	40 XXX	SP	CCA		V			6/18/2028
2020 PO1261623383	ODP	4	40 XXX	SP	CCA	ED	T			6/19/2028
2020 PO1277223564	ODP	4	40 XXX	SP	CRE	ID	TD			6/20/2028
2020 PO1264823638	ODP	6	30 XXX	SP	CRE	HH,ID	TX		RR	6/21/2028
2020 PO1317223629	ODP	4	40 XXX	SP	CRE	ID	TD			6/22/2028
2020 PO1949322406	ODP	4	45 XXX	SP	CRE		V			6/23/2028
2020 PO6168766401	KU	3	40 OTH	SP	CRE	ID	TD			6/24/2028
2020 PO6221066912	KU	4	40 OTH	SP	CRE	ID	TD			6/25/2028
2020 PO6198266565	KU	5	40 OTH	SP	CRE	ID	TD			6/26/2028
2020 PO4777088878	LGE	4	40 BRN	SP	CRE	ED,ID	TD			6/27/2028
2020 PO4768588527	LGE	3	50 BRO	SP	CCA	ED,ID	BD			6/28/2028
2020 PO4767388509	LGE	3	45 BRO	SP	CCA		V			6/29/2028
2020 PO4768188503	LGE	4	40 BRO	SP	CCA		V			6/30/2028
2020 PO4536735675	KU	3	50 ACE	SP	CCA		V			7/1/2028
2020 PO4776688807	LGE	4	40 BRN	SP	CRE	ED,ID	TD			7/2/2028
2020 PO3279151740	KU	4	40 ACE	SP	CCA		V			7/3/2028
2020 PO4525935564	KU	3	50 ACE	SP	CCA		V			7/4/2028
2020 PO4515635459	KU	3	50 ACE	SP	CCA		V			7/5/2028
2020 PO1329538122	ODP	4	45 BRN	SP	CCA		V			7/6/2028
2020 PO1315638373	F	4	45 BRN	SP	CRE		V			7/7/2028
2020 PO1270439347	ODP	4	45 BRN	SP	CCA		V			7/8/2028
2020 PO3997882777	LGE	4	30 BRN	SP	CRE	ED,ID	TD			7/9/2028
2020 PO3997482785	LGE	3	45 BRN	SP	S		V			7/10/2028

2020 PO3916882244	LGE	1H		70 BRN	SP	CRE		ED,ID		BD		7/11/2028
2020 PO6368534232	LGE		4	40 BRN	SP	CCA				V		7/12/2028
2020 PO3919482299	LGE	1H		80 BRN	SP	CRE		ED,ID		BD		7/13/2028
2020 PO3918082270	LGE	1H		80 BRN	SP	CRE		ED,ID		BD		7/14/2028
2020 PO1289238785	ODP		4	40 BRN	SP	CCA				V		7/15/2028
2020 PO1278638940	ODP		4	45 BRN	SP	CRE				V		7/16/2028
2020 PO1307638533	ODP		4	45 BRN	SP	CCA				V		7/17/2028
2020 PO1396535843	ODP		4	40 KOP	SP	CRE		ED,ID,MD		TD		7/18/2028
2020 PO1414635619	ODP		2	50 KOP	SP	S				V		7/19/2028
2020 PO1427035416	ODP		3	50 KOP	SP	S				V		7/20/2028
2020 PO4731288314	LGE		4	30 BRO	SP	CCA		ED,ID		BD		7/21/2028
2020 PO4731688318	LGE		4	40 BRO	SP	CCA				V		7/22/2028
2020 PO4779788822	LGE		4	40 BRN	SP	CRE		ED,ID		TD		7/23/2028
2020 PO4619187918	F		4	40 BRO	SP	A				V		7/24/2028
2020 PO4618387930	F		4	40 BRO	SP	A				V		7/25/2028
2020 PO4617587942	F		4	40 BRO	SP	A				V		7/26/2028
2020 PO4621487941	F		4	40 BRO	SP	CRE				V		7/27/2028
2020 PO4620787952	F		3	45 BRO	SP	CCA				V		7/28/2028
2020 PO4616787955	F		4	40 BRO	SP	A				V		7/29/2028
2020 PO4757087882	LGE		1	70 BRO	SP	CCA		ED,ID		BD		7/30/2028
2020 PO4761587878	LGE		1	65 BRO	SP	CCA		ED,HH,ID		BX	RR	7/31/2028
2020 PO4778388815	LGE		4	40 BRN	SP	CRE		ED,ID		TD		8/1/2028
2020 PO4779788815	LGE		4	40 BRN	SP	CCA				V		8/2/2028
2020 PO4780388814	LGE		4	40 BRN	SP	CRE		ED,ID		BD		8/3/2028
2020 PO4777988790	LGE		4	30 BRN	SP	CRE		HH,ID		BD		8/4/2028
2020 PO4777988790-A	LGE		5	30 BRN	SP	S				V		8/5/2028
2020 PO4616087966	F		3	45 BRO	SP	CCA				V		8/6/2028
2020 PO1461534931	ODP		4	45 KOP	SP	S				V		8/7/2028
2020 PO4783688756	LGE		4	40 BRN	SP	CRE		ED,ID		BD		8/8/2028
2020 PO1222739629	ODP		4	45 UNK	SP	CRE		ED,ID		TD		8/9/2028
2020 PO1234839621	ODP		6	30 UNK	SP	CRE		ED,ID		TD		8/10/2028
2020 1113939452A	ODP		6	30 CAH	SP	CRE				V		8/11/2028
2020 PO1110539613	ODP		4	40 BRN	SP	CRE		ED,ID		TD		8/12/2028
2020 PO1117339976	ODP		6	30 BRN	SP	CCA		ED,SR		T		8/13/2028
2020 PO1103339787	ODP		4	35 BRN	SP	CCA				V		8/14/2028
2020 PO1140539927	ODP		4	40 BRN	SP	CRE		ED,ID		TD		8/15/2028
2020 PO1133439939	ODP		4	40 BRN	SP	CRE		ED,ID,IP		TD		8/16/2028
2020 PO3923082341	F		4	30 BRN	SP	CRE				V		8/17/2028
2020 PO3920082312	LGE	1H		75 BRN	SP	CRE		ED,ID		TD		8/18/2028
2020 PO3921082334	LGE	1H		65 BRN	SP	CRE		ED,ID		BD		8/19/2028
2020 PO3923182365	LGE		3	50 BRN	SP	CRE				V		8/20/2028
2020 PO3921582346	LGE		1	50 BRN	SP	A		ED,ID		BD		8/21/2028
2020 PO6416335014	LGE		1	50 BRN	SP	CCA				V		8/22/2028
2020 PO3923582374	LGE		3	50 BRN	SP	CRE		ED,ID		TD		8/23/2028
2020 PO3923882382	LGE		4	40 BRN	SP	CRE		ED,ID		TD		8/24/2028
2020 PO3909782142	LGE		4	30 BRN	SP	P		ED,ID		TD		8/25/2028
2020 PO4783688756-A	LGE		4	30 BRN	SP	A		ED,ID		TD		8/26/2028

2020 PO4622287930	F	3	45 BRO	SP	CCA		V	8/27/2028
2020 PO4623087918	F	3	45 BRO	SP	CCA		V	8/28/2028
2020 PO4623887906	F	4	40 BRO	SP	CRE		V	8/29/2028
2020 PO4624187901	F	4	40 BRO	SP	CRE		V	8/30/2028
2020 PO4784088749	LGE	4	40 BRN	SP	CRE	ED,ID	TD	8/31/2028
2020 PO6022867371	KU	3	50 OTH	SP	CRE	ID	TD	9/1/2028
2020 PO6014167544	KU	4	40 OTH	SP	CRE	ID	TD	9/2/2028
2020 PO5946267096	KU	4	40 OTH	SP	CRE	ID	TD	9/3/2028
2020 PO4785088752	LGE	4	40 BRN	SP	CRE	ED,ID	TD	9/4/2028
2020 PO4784888758	LGE	4	40 BRN	SP	CRE	ED,ID	BD	9/5/2028
2020 PO6099667173	F	4	40 OTH	SP	P	ED	V	9/6/2028
2020 PO6133267579	KU	4	40 OTH	SP	S		V	9/7/2028
2020 PO6124767503	KU	4	45 OTH	SP	S		V	9/8/2028
2020 PO6147167703	KU	4	40 OTH	SP	S		V	9/9/2028
2020 PO5986167154	KU	4	40 OTH	SP	CRE	ID	TD	9/10/2028
2020 PO4287702310	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	9/11/2028
2020 PO4293702364	KU	6	30 BRO	SP	CRE	ID	BD	9/12/2028
2020 PO3188852111	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	9/13/2028
2020 PO5567045439	F	4	40 XXX	SP	CRE		V	9/14/2028
2020 PO5571545524	F	4	40 XXX	SP	CRE		V	9/15/2028
2020 PO5561045355	F	4	40 XXX	SP	CRE		V	9/16/2028
2020 PO5573945628	F	4	40 XXX	SP	CRE		V	9/17/2028
2020 PO5578045679	F	4	40 XXX	SP	CRE		V	9/18/2028
2020 PO5497444631	KU	6	30 BRN	SP	CCA		V	9/19/2028
2020 PO5553745283	F	4	40 XXX	SP	CRE		V	9/20/2028
2020 PO3175252202	KU	6	30 ACE	SP	CRE	ED,ID	TD	9/21/2028
2020 PO4320201914	F	4	40 BRO	SP	CRE		V	9/22/2028
2020 PO4298801693	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	9/23/2028
2020 PO3315652210	KU	6	30 ACE	SP	CCA		V	9/24/2028
2020 PO3317752280	KU	4	40 ACE	SP	CRE	ED,ID	BD	9/25/2028
2020 PO4306401830	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/26/2028
2020 PO5637543751A	KU	3	45 BRN	SP	S		V	9/27/2028
2020 PO3995682777	LGE	4	30 BRN	SP	CRE	ED,ID	BD	9/28/2028
2020 PO3995682784	LGE	3	45 BRN	SP	S		V	9/29/2028
2020 PO1273639139	F	3	45 XXX	SP	P		V	9/30/2028
2020 PO1242139355	ODP	4	45 BRN	SP	CRE		V	10/1/2028
2020 PO3993782775	LGE	4	30 BRN	SP	CRE	ED,ID	TD	10/2/2028
2020 PO1481334848	ODP	4	45 KOP	SP	S		V	10/3/2028
2020 14894-35097A	ODP	4	40 KOP	SP	CRE		V	10/4/2028
2020 14790-34961A	ODP	6	25 KOP	SP	CRE		V	10/5/2028
2020 PO1470935685	ODP	5	35 KOP	SP	S		V	10/6/2028
2020 PO1479034961	ODP	4	45 KOP	SP	A	ID	BD	10/7/2028
2020 PO1489435097	ODP	6	30 KOP	SP	A	ED,ID	TD	10/8/2028
2020 PO1486834987	ODP	4	45 KOP	SP	S		V	10/9/2028
2020 14615-34931A	ODP	6	25 KOP	SP	A		V	10/10/2028
2020 PO3993682782	LGE	4	40 BRN	SP	CRE	ED,ID	TD	10/11/2028
2020 PO1228839684	ODP	4	20 BRN	SP	CRE		V	10/12/2028

2020 PO3880282647	LGE	4	40 BRO	SP	A	ED,ID	TD	10/13/2028
2020 PO3877582660	LGE	3	45 BRO	SP	CCA		V	10/14/2028
2020 PO1181939572	ODP	4	45 BRN	SP	CCA		V	10/15/2028
2020 PO3992182780	LGE	4	40 BRN	SP	A	ED,ID	TD	10/16/2028
2020 PO1166939447	ODP	3	45 BRN	SP	CCA		V	10/17/2028
2020 PO2722027396	F	4	40 BRN	SP	A		V	10/18/2028
2020 PO2737027314	ODP	4	40 BRN	SP	CRE		V	10/19/2028
2020 PO2762727173	ODP	4	45 BRN	SP	CRE	ID	TD	10/20/2028
2020 PO2721527230	ODP	4	40 BRN	SP	CRE	ID	BD	10/21/2028
2020 PO1148339300	ODP	3	45 BRN	SP	CCA		V	10/22/2028
2020 PO1127939463	F	3	45 XXX	SP	P		V	10/23/2028
2020 PO1136137930	ODP	4	45 BRN	SP	CRE		V	10/24/2028
2020 PO3909982147	F	4	40 BRN	SP	CRE		V	10/25/2028
2020 PO3908782148	F	4	30 BRN	SP	P		V	10/26/2028
2020 PO3908982151	F	4	40 BRN	SP	CRE		V	10/27/2028
2020 PO3907782156	F	4	35 BRN	SP	CRE		V	10/28/2028
2020 PO3907182158	F	6	25 BRN	SP	CRE		V	10/29/2028
2020 PO3989482777	LGE	4	40 BRN	SP	CRE	ED,ID,IP	BD	10/30/2028
2020 PO3990482779	LGE	4	45 BRN	SP	CRE	ED,ID	BD	10/31/2028
2020 PO3060651017	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	11/1/2028
2020 PO1193437039	ODP	5	35 BRN	SP	CRE	ED,ID	TD	11/2/2028
2020 PO3476438811	KU	4	40 ACE	SP	CCA		V	11/3/2028
2020 PO3501138161	F	4	40 ACE	SP	CRE		V	11/4/2028
2020 PO3481038164	KU	5	35 ACE	SP	CCA		V	11/5/2028
2020 PO3500138384	F	4	40 ACE	SP	CRE		V	11/6/2028
2020 PO3500838575	F	4	40 ACE	SP	CRE		V	11/7/2028
2020 PO3501438811	F	4	40 ACE	SP	CCA		V	11/8/2028
2020 PO3502139063	F	4	40 ACE	SP	CRE		V	11/9/2028
2020 PO4320302176	KU	6	30 BRO	SP	CCA	ED	T	11/10/2028
2020 PO4321802276	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD	11/11/2028
2020 PO4325902440	F	4	40 BRO	SP	CCA		V	11/12/2028
2020 PO3502839328	F	4	40 ACE	SP	CRE		V	11/13/2028
2020 PO3503039457	F	4	40 ACE	SP	CRE	ED,ID	V	11/14/2028
2020 PO3522739453	F	4	40 ACE	SP	CRE	ED,ID	V	11/15/2028
2020 PO3541739448	F	4	40 ACE	SP	CRE	ED,EP,ID,MD	V	11/16/2028
2020 PO3559039444	F	4	40 ACE	SP	CRE		V	11/17/2028
2020 PO3564339370	KU	4	45 ACE	SP	CCA	ED,ID	BD	11/18/2028
2020 PO4351502532	F	4	40 BRO	SP	CCA		V	11/19/2028
2020 PO4361902568	F	4	40 BRO	SP	CRE		V	11/20/2028
2020 PO4286301526	KU	4	40 BRO	SP	CRE	ED,ID	TD	11/21/2028
2020 PO3624751397	KU	3	50E BRN	SP	CRE	ED,ID,SRS	TD	11/22/2028
2020 PO3611151515	KU	6	30 BRN	SP	CRE	ED,ID,SRS	TD	11/23/2028
2020 PO3616551342	KU	3	50E BRN	SP	CRE	ED,ID,SRS	TD	11/24/2028
2020 PO5079113741	KU	4	40 BRO	SP	CCA		V	11/25/2028
2020 PO5084913853	KU	3	50 BRO	SP	CCA		V	11/26/2028
2020 PO5103213641	KU	4	40 BRO	SP	CRE	ID,IP	BD	11/27/2028
2020 PO5111513607	KU	4	40 BRO	SP	CRE	ED,ID	BD	11/28/2028

2020 PO5067513785	KU	4	40 BRO	SP	CRE		V		11/29/2028
2020 PO4771988894	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD		11/30/2028
2020 PO4751488241	LGE	3	45 BRO	SP	CCA	ED,ID	BD		12/1/2028
2020 PO4771488904	LGE	4	40 BRN	SP	S		V		12/2/2028
2020 PO4774688928	LGE	4	40 BRN	SP	A	ED,ID,IP	BD		12/3/2028
2020 PO4774888922	LGE	4	40 BRN	SP	CRE	ED,ID	TD		12/4/2028
2020 PO3602951384	F	4	40 BRN	SP	P		V		12/5/2028
2020 PO3594651431	F	4	40E BRN	SP	P		V		12/6/2028
2020 PO3593051441	KU	4	40 BRN	SP	CCA		V		12/7/2028
2020 PO4781788938	LGE	4	30 BRN	SP	A	ED,ID	TD		12/8/2028
2020 PO4616288057	LGE	3	45 BRO	SP	CCA		V		12/9/2028
2020 PO4618388057	LGE	4	40 BRO	SP	CRE	ED,ID	TD		12/10/2028
2020 PO4619488054	LGE	4	35 BRO	SP	CRE	ED,ID	BD		12/11/2028
2020 PO4754988576	LGE	4	30 BRO	SP	P	ED,ID,IP	BD		12/12/2028
2020 PO4754888584	F	4	40 BRO	SP	CCA	ED,ID	VX	PX	12/13/2028
2020 PO4764988586	F	4	40 BRO	SP	CCA		V		12/14/2028
2020 PO4763388568	F	3	40 BRO	SP	CCA		V		12/15/2028
2020 PO4621088052	LGE	4	40 BRO	SP	CRE	ED,ID	BD		12/16/2028
2020 PO4622388051	LGE	4	40 BRO	SP	CRE	ED,ID	BD		12/17/2028
2020 PO4623588050	LGE	4	40 BRO	SP	CRE	ED,ID	BD		12/18/2028
2020 PO4564015387	F	4	40 ACE	SP	CRE		V		12/19/2028
2020 PO4572815387	F	4	40 ACE	SP	CRE		V		12/20/2028
2020 PO4582615536	F	4	40 ACE	SP	CRE		V		12/21/2028
2020 PO4779888934	LGE	4	40 BRN	SP	A	ED,HH,ID,IP	BX	RR	12/22/2028
2020 PO4625088048	LGE	4	35 BRO	SP	A	ED,ID	BD		12/23/2028
2020 PO4625788044	LGE	3	45 BRO	SP	A	ED,ID	BD		12/24/2028
2020 PO4625888047	LGE	3	45 BRO	SP	A	ED,ID	BD		12/25/2028
2020 PO8934726655A	F	4	40 XXX	SP	A	RB	VX	RP2	12/26/2028
2020 PO8898926647A	ODP	4	40 XXX	SP	A	ED,ID	TD		12/27/2028
2020 PO8898926647	ODP	5	35 XXX	SP	CRE	ID	TD		12/28/2028
2020 PO4643388344	LGE	4	40 BRO	SP	CRE	ED,HH,ID,RB	BX	PX	12/29/2028
2020 PO4642288340	LGE	4	40 BRO	SP	CCA		V		12/30/2028
2020 PO4641088336	LGE	4	40 BRO	SP	CRE	ED,HH,ID,RB	BX	PX	12/31/2028
2020 PO4639788331	LGE	4	40 BRO	SP	CRE	ED,ID	BD		1/1/2029
2020 PO4638488327	LGE	4	40 BRO	SP	CRE	ED,HH,ID,RB	BX	PX	1/2/2029
2020 PO4760988611	F	4	40 BRO	SP	CCA		V		1/3/2029
2020 PO4760888617	F	4	40 BRO	SP	CCA		V		1/4/2029
2020 PO4760988632	F	4	40 BRO	SP	CCA		V		1/5/2029
2020 PO4759688620	F	4	40 BRO	SP	CCA		V		1/6/2029
2020 PO4758688627	F	3	45 BRO	SP	CCA		V		1/7/2029
2020 PO4759788628	LGE	4	30 BRO	SP	CCA		V		1/8/2029
2020 PO4637088322	LGE	4	40 BRO	SP	P	ED	T		1/9/2029
2020 PO4637188319	LGE	4	40 BRO	SP	CRE	ED,ID	TD		1/10/2029
2020 PO4767288606	F	4	40 BRO	SP	CCA		V		1/11/2029
2020 PO3817852375	KU	4	40 BRN	SP	CRE	ED,HH,ID,RB	X	RP2	1/12/2029
2020 PO4772187471	LGE	4	40 BRO	SP	CCA	ED,ID,IP	BD		1/13/2029
2020 PO4774187456	LGE	4	40 BRO	SP	CCA	ED,ID	BD		1/14/2029

2020 PO0117232856	ODP	4	35 BRN	SP	CRE	ED,ID	TD		1/15/2029
2020 0155832963a	ODP	6	30 BRN	SP	CRE	RB	X	RP1	1/16/2029
2020 PO0155832963	ODP	4	40 BRN	SP	CRE	ED,ID	TD		1/17/2029
2020 PO3942783157	F	4	40 BRO	SP	P		V		1/18/2029
2020 PO3942783149	F	5	25 BRO	SP	A		V		1/19/2029
2020 PO4009882505	LGE	4	40 BRN	SP	CRE	ED,ID,SRC	TX	RR	1/20/2029
2020 PO3944483158	F	4	40 BRO	SP	A		V		1/21/2029
2020 PO3945183158	F	6	25 BRO	SP	A		V		1/22/2029
2020 PO2046342528	ODP	4	40 KOP	SP	CRE	ED,ID,MD	TD		1/23/2029
2020 PO2033542660	ODP	5	45 KOP	SP	CRE	ED,EP,ID,MD	TD		1/24/2029
2020 PO2279946023	KU	4	40 BRN	SP	CCA		V		1/25/2029
2020 PO4577338262	KU	5	35 BRO	SP	CRE	ID,IP	BD		1/26/2029
2020 PO4560138402	KU	4	40 BRO	SP	CRE	ID,IP	BD		1/27/2029
2020 PO1283579483	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		1/28/2029
2020 PO3944783067	F	4	40 BRO	SP	A	RB	VX	RP2	1/29/2029
2020 PO1136075201	KU	3	50 BRN	SP	CRE	ID	BD		1/30/2029
2020 PO1141575299	KU	3	50 BRN	SP	CRE	ED	TD		1/31/2029
2020 PO1141675380	KU	3	50 BRN	SP	CRE	ED,ID,IP	TD		2/1/2029
2020 PO9101257746	KU	4	40 BRN	SP	P	ED	TD		2/2/2029
2020 PO9101257746-A	KU	4	40 BRN	SP	P	ED	TD		2/3/2029
2020 PO1282379211	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		2/4/2029
2020 PO1250379295	KU	4	40 BRN	SP	CRE	ED	TD		2/5/2029
2020 PO1205479417	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		2/6/2029
2020 PO1181879467	KU	4	40 BRN	SP	CRE	ED	TD		2/7/2029
2020 PO9081358155	KU	4	40 BRN	SP	P	ED	TD		2/8/2029
2020 PO9052358784	KU	4	40 BRN	SP	P	ED	TD		2/9/2029
2020 PO9052358784-A	KU	4	40 BRN	SP	P	ED	TD		2/10/2029
2020 PO9020859482	KU	4	40 BRN	SP	P	ED	TD		2/11/2029
2020 PO9037559096	KU	4	40 BRN	SP	P	ED	TD		2/12/2029
2020 PO9224957179	KU	5	35 BRO	SP	CRE	ED,ID,SRC	TD		2/13/2029
2020 9020859482-A	KU	4	40 BRN	SP	P	ED	TD		2/14/2029
2020 PO9210857169	KU	5	35 BRO	SP	CRE	ED,ID,SRC	TD		2/15/2029
2020 PO3944183069	F	4	40 BRO	SP	A		V		2/16/2029
2020 PO3945283048	F	5	25 BRO	SP	A		V		2/17/2029
2020 PO3944483051	F	4	40 BRO	SP	CCA		V		2/18/2029
2020 PO3944083043	F	4	40 BRO	SP	P		V		2/19/2029
2020 PO3944883040	F	5	25 BRO	SP	A		V		2/20/2029
2020 PO3943383029	F	4	40 BRO	SP	A		V		2/21/2029
2020 PO3942583014	F	4	40 BRO	SP	A		V		2/22/2029
2020 PO3942183007	F	4	40 BRO	SP	A		V		2/23/2029
2020 PO3941682998	F	4	40 BRO	SP	P		V		2/24/2029
2020 PO4007682522	LGE	6	30 BRN	SP	CCA		V		2/25/2029
2020 PO4007082520	LGE	4	40 BRN	SP	A	ED,ID	TD		2/26/2029
2020 PO4005582528	LGE	4	40 BRN	SP	CRE	ED,ID	BD		2/27/2029
2020 PO3457548179	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		2/28/2029
2020 PO3455048260	F	4	40 BRO	SP	CRE		V		3/1/2029
2020 PO0195132881	ODP	5	40 XXX	SP	CRE	ED,ID	TD		3/2/2029

2020 PO0185633080	ODP	4	35 XXX	SP	CRE	ED,ID	TD	3/3/2029
2020 PO0251632986	ODP	5	35 XXX	SP	CRE	ED,ID	TD	3/4/2029
2020 PO9197157151	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD	3/5/2029
2020 PO9208257023	KU	5	35 BRO	SP	CCA		V	3/6/2029
2020 PO9205756842	KU	4	40 BRO	SP	CRE	ID	BD	3/7/2029
2020 PO9210357283	KU	6	30 BRO	SP	CCA		V	3/8/2029
2020 PO9187657119	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD	3/9/2029
2020 PO9168357260	KU	4	40 BRO	SP	CRE		V	3/10/2029
2020 PO9174457126	KU	4	40 BRO	SP	CRE		V	3/11/2029
2020 PO9138256561	KU	5	35 BRO	SP	CRE		V	3/12/2029
2020 PO9368558439	KU	4	40 BRO	SP	CRE	ID	BD	3/13/2029
2020 PO9062759647	F	7	30E BRO	SP	CRE		V	3/14/2029
2020 PO9158557002	KU	4	40 BRO	SP	CRE	ID	BD	3/15/2029
2020 PO9126756726	KU	3	45 BRO	SP	CRE		V	3/16/2029
2020 PO9143056866	KU	5	35 BRO	SP	CRE		V	3/17/2029
2020 PO9158556308	KU	4	40 BRO	SP	CCA		V	3/18/2029
2020 PO9039160268	KU	6	30 BRN	SP	P	ED	TD	3/19/2029
2020 PO9062259751	KU	4	40 BRN	SP	CRE	ED	TD	3/20/2029
2020 PO9032959960	KU	4	40 BRN	SP	P	ED	TD	3/21/2029
2020 PO9062060003	KU	4	45 BRN	SP	CCA		V	3/22/2029
2020 PO9061760256	KU	4	45 BRN	SP	CCA		V	3/23/2029
2020 PO9261357098	KU	4	40 ACW	SP	CRE	ED,ID	BD	3/24/2029
2020 PO9415959830	KU	4	40 ACW	SP	CCA		V	3/25/2029
2020 PO9198862582	KU	4	40 ACW	SP	CCA		V	3/26/2029
2020 PO9202362547	KU	4	40 ACW	SP	CRE	ED,ID	BD	3/27/2029
2020 PO1166479429	KU	3	50 BRN	SP	P	ED	T	3/28/2029
2020 PO1175179616	KU	3	50 BRN	SP	P	ED	T	3/29/2029
2020 PO1182379800	KU	3	50 BRN	SP	P	ED	T	3/30/2029
2020 PO5593410495	KU	6	30 BRO	SP	CRE	ID	TD	3/31/2029
2020 PO7257590443	KU	6	30 BRO	SP	CRE	ED,ID	TD	4/1/2029
2020 PO7447594330	KU	6	30 BRO	SP	CRE	ED,ID	TD	4/2/2029
2020 PO7264990576	KU	6	30 BRO	SP	CRE	ED,ID	TD	4/3/2029
2020 PO7256590853	KU	3	40 BRO	SP	CCA		V	4/4/2029
2020 PO7251890898	KU	5	35 BRO	SP	CRE	ED,ID	BD	4/5/2029
2020 PO7256590853	F	4	35 BRO	SP	CRE		V	4/6/2029
2020 PO7236290835	F	4	35 BRO	SP	CCA		V	4/7/2029
2020 PO7143094567	KU	4	40 BRN	SP	CRE	ED,ID	TD	4/8/2029
2020 PO7273192142	KU	4	45 BRN	SP	CRE	ED,ID	TD	4/9/2029
2020 PO7302092363	KU	4	45 BRN	SP	CRE	ED,ID	TD	4/10/2029
2020 PO7129294647	KU	2	70 BRN	SP	CRE	ED,ID	TD	4/11/2029
2020 PO7116294724	KU	4	40 BRN	SP	CRE	ED,ID	BD	4/12/2029
2020 PO7105494850	KU	2	45 BRN	AL	CRE		V	4/13/2029
2020 PO7102794801	KU	2	75 BRN	AL	CCA		V	4/14/2029
2020 PO7073994904	KU	5	35 BRN	SP	CRE	ED,ID	TD	4/15/2029
2020 PO7073294984	KU	4	45 BRN	SP	CCA		V	4/16/2029
2020 PO7450394407	KU	4	40 BRO	SP	CRE	ID	BD	4/17/2029
2020 PO7239491048	KU	4	30 BRO	SP	A	ED,ID	TD	4/18/2029

Business Use

2020 PO7230990632	F	4	40 BRO	SP	CRE		V	4/19/2029
2020 PO7236990685	F	3	40 BRO	SP	CRE		V	4/20/2029
2020 PO7434294724	KU	4	40 BRO	SP	CRE	ED,ID	TD	4/21/2029
2020 PO7429994829	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/22/2029
2020 PO7251090666	F	5	30 BRO	SP	P		V	4/23/2029
2020 PO7246190718	F	4	30 BRO	SP	P		V	4/24/2029
2020 PO7244990752	F	3	45 BRO	SP	CRE		V	4/25/2029
2020 PO7256590853	F	3	45 BRO	SP	CRE		V	4/26/2029
2020 PO7252090290	KU	3	55 BRO	SP	CRE	ED	TD	4/27/2029
2020 PO7121089987	KU	4	45 BRN	SP	CRE	ED,ID	BD	4/28/2029
2020 PO7115889944	KU	5	35 BRN	SP	CRE	ED,ID	TD	4/29/2029
2020 PO7113389914	KU	4	40 BRN	SP	CRE	ED,ID	TD	4/30/2029
2020 PO7282190915	KU	6	30 BRO	SP	CCA		V	5/1/2029
2020 PO7421195015	KU	4	45 BRO	SP	CRE	ED,ID	TD	5/2/2029
2020 PO7348994851	KU	4	40 BRO	SP	CRE	ID	BD	5/3/2029
2020 PO7340794829	KU	4	40 BRO	DF	CRE	ID	BD	5/4/2029
2020 PO7073594925	KU	4	40 BRN	SP	CRE	ED,ID	TD	5/5/2029
2020 PO7368294898	KU	4	45 BRO	SP	CRE	ID	BD	5/6/2029
2020 PO7347793940	KU	4	45 BRO	SP	CRE	ED,ID	TD	5/7/2029
2020 PO3919082647	F	4	40 BRO	SP	CCA	MD	VX	5/8/2029
2020 PO7333393591	KU	4	40 BRO	SP	CCA		V	5/9/2029
2020 PO6341613330	KU	4	40 XXX	SP	CRE	ID	TD	5/10/2029
2020 PO6357013285	KU	4	40 XXX	SP	CRE	ID	TD	5/11/2029
2020 PO6352413151A	KU	5	35 XXX	SP	CRE	ID	TD	5/12/2029
2020 PO6352413151	KU	4	40 XXX	SP	CRE	ID	TD	5/13/2029
2020 PO6366912912	KU	4	40 XXX	SP	CRE	ID	TD	5/14/2029
2020 PO6324013163	KU	4	40 XXX	SP	CCA		V	5/15/2029
2020 PO6325712677	KU	6	30 XXX	SP	CRE	ID	V	5/16/2029
2020 PO6331312955	KU	5	35 XXX	SP	CRE	ID	TD	5/17/2029
2020 PO6338213021	KU	4	40 XXX	SP	CCA		V	5/18/2029
2020 PO6342412979	KU	6	30 XXX	SP	CRE		V	5/19/2029
2020 PO6347712748	KU	5	35 XXX	SP	CRE	ID	TD	5/20/2029
2020 PO6330512703	F	5	30 XXX	SP	CRE		V	5/21/2029
2020 PO6321612811	KU	6	30 XXX	SP	CRE	ID	TD	5/22/2029
2020 PO7347693636	KU	4	40 BRO	SP	CCA		V	5/23/2029
2020 PO7347393750	KU	4	40 BRO	SP	CCA		V	5/24/2029
2020 PO3921182635	F	4	40 BRO	SP	CCA		V	5/25/2029
2020 PO3922182629	F	4	40 BRO	SP	CCA		V	5/26/2029
2020 PO3923182622	F	4	40 BRO	SP	CCA		V	5/27/2029
2020 PO3924182616	F	4	40 BRO	SP	CCA		V	5/28/2029
2020 PO3925082610	F	4	40 BRO	SP	CCA		V	5/29/2029
2020 PO3926182603	F	4	40 BRO	SP	CCA		V	5/30/2029
2020 PO3925582595	F	4	30 BRO	SP	CCA		V	5/31/2029
2020 PO3926982588	F	4	30 BRO	SP	CCA		V	6/1/2029
2020 PO3926982598	F	4	40 BRO	SP	CRE		V	6/2/2029
2020 PO3928582597	F	4	30 BRO	SP	CCA		V	6/3/2029
2020 PO3927782598	LGE	4	30 BRO	SP	A	ED,ID	TD	6/4/2029

2020 PO3927982603	F	4	40 BRO	SP	CCA		V	6/5/2029	
2020 PO3928482615	F	4	40 BRO	SP	CCA		V	6/6/2029	
2020 PO3929082627	F	4	40 BRO	SP	A		V	6/7/2029	
2020 PO3925082662	F	4	40 BRO	SP	CCA		V	6/8/2029	
2020 PO3924082667	F	4	40 BRO	SP	CCA		V	6/9/2029	
2020 PO4015682656	LGE	4	30 BRN	SP	CRE		V	6/10/2029	
2020 PO4036382648	F	5	30 BRN	SP	A		V	6/11/2029	
2020 PO735593774	KU	5	35 BRO	SP	CRE	ED,ID	TD	6/12/2029	
2020 PO3936683132	F	4	40 BRO	SP	A		V	6/13/2029	
2020 PO7363293277	KU	4	40 BRO	SP	CRE	ID	BD	6/14/2029	
2020 PO7348493457	KU	4	40 BRO	SP	CCA		V	6/15/2029	
2020 PO7327192572	KU	5	30 BRN	SP	CRE	ED,ID	TD	6/16/2029	
2020 PO7366993539	KU	5	35 BRO	SP	CRE	ED,ID	TD	6/17/2029	
2020 PO7370093210	KU	4	40 BRO	SP	CRE	ED,ID	TD	6/18/2029	
2020 PO7180789959	KU	6	30 BRO	SP	CCA		V	6/19/2029	
2020 PO7190089941	F	5	30 BRO	SP	CCA		V	6/20/2029	
2020 PO7192289981	KU	5	35 BRO	SP	CRE		V	6/21/2029	
2020 PO7168794352	F	4	40 BRN	SP	A		V	6/22/2029	
2020 PO7381093196	F	3	45 BRO	SP	CRE		V	6/23/2029	
2020 PO7394393105	F	4	40 BRO	ST	CRE		V	6/24/2029	
2020 PO7390993128	F	3	45 BRO	SP	CRE		V	6/25/2029	
2020 PO7132794322	KU	5	35 BRN	SP	CRE	ED,ID	TD	6/26/2029	
2020 PO7150294239	KU	5	35 BRN	SP	CRE		V	6/27/2029	
2020 PO6334412632	KU	4	40 XXX	SP	CRE	ID	TD	6/28/2029	
2020 PO6322312631	KU	4	45 XXX	SP	CCA		V	6/29/2029	
2020 PO6319612466	KU	5	35 XXX	SP	CRE	ID	TD	6/30/2029	
2020 PO6328912442	KU	6	30 XXX	SP	CRE	ID	TD	7/1/2029	
2020 PO6306312577	KU	6	30 XXX	SP	CRE	ID	TD	7/2/2029	
2020 PO6303112506	KU	6	30 XXX	SP	CRE	ID	TD	7/3/2029	
2020 PO6312612487	KU	4	40 XXX	SP	CRE	ID	TD	7/4/2029	
2020 PO6290112208	KU	6	30 XXX	SP	CRE		V	7/5/2029	
2020 PO6289912147	KU	4	50 XXX	SP	CRE	ID	TD	7/6/2029	
2020 PO6289712365	KU	5	35 XXX	SP	CCA		V	7/7/2029	
2020 PO6302012306	KU	4	45 XXX	SP	CRE	ID	TD	7/8/2029	
2020 PO6295312391	KU	5	35 XXX	SP	CRE	ID	TD	7/9/2029	
2020 PO7123194157	KU	6	30 BRN	SP	CRE	ED,ID	TD	7/10/2029	
2020 PO7119394036	KU	5	35 BRN	SP	CRE	ED,ID	BD	7/11/2029	
2020 PO7135893954	KU	5	35 BRN	SP	CRE	ED,HH,ID	VX	PX	7/12/2029
2020 PO5602110097	KU	4	40 BRO	SP	CRE	ID	TD	7/13/2029	
2020 PO3937883145	F	5	25 BRO	SP	P		V	7/14/2029	
2020 PO3937883137	F	4	40 BRO	SP	P		V	7/15/2029	
2020 PO4024082858	F	4	40 BRN	SP	CCA		V	7/16/2029	
2020 PO4022382831	F	4	40 BRN	SP	CRE		V	7/17/2029	
2020 PO4021682819	F	4	40 BRN	SP	CRE		V	7/18/2029	
2020 PO4020682804	F	4	40 BRN	SP	CRE		V	7/19/2029	
2020 PO4600036995	KU	3	45 BRO	SP	CCA		V	7/20/2029	
2020 PO4601937105	KU	3	45 BRO	SP	CCA		V	7/21/2029	

Business Use

2020 PO4587836881	KU	4	45 BRO	SP	CCA		V	7/22/2029	
2020 PO3881544901	KU	4	40 BRN	SP	CRE	ID,IP	BD	7/23/2029	
2020 PO4830431314	KU	4	40 BRO	SP	CCA		V	7/24/2029	
2020 PO4825531325	KU	6	30 BRO	SP	CCA		V	7/25/2029	
2020 PO7097802236	KU	5	35 BRN	SP	CRE		V	7/26/2029	
2020 PO6225106028	KU	6	30 BRN	SP	CRE		V	7/27/2029	
2020 PO7131602009	KU	4	40 BRN	SP	CRE		V	7/28/2029	
2020 PO7110601946	KU	5	35 BRN	SP	CCA		V	7/29/2029	
2020 PO7137301963	KU	4	40 BRN	SP	CCA		V	7/30/2029	
2020 PO7120601870	KU	6	30 BRN	SP	CCA		V	7/31/2029	
2020 PO7138502063	KU	3	45 BRN	SP	CCA		V	8/1/2029	
2020 PO7125901897	KU	4	40 BRN	SP	CCA		V	8/2/2029	
2020 PO7148602028	KU	2	55 BRN	SP	CCA		V	8/3/2029	
2020 PO7202288932	KU	4	40 BRN	SP	CRE		V	8/4/2029	
2020 PO6475703651	KU	5	30 BRN	SP	CRE	RB	X	RP1	8/5/2029
2020 PO6483203603	F	6	30 BRN	SP	CRE		V	8/6/2029	
2020 PO6485703679	KU	4	35 BRN	SP	CRE	ED,ID	TD	8/7/2029	
2020 PO6471803638	KU	6	30 BRN	SP	CRE		V	8/8/2029	
2020 PO6727814154	KU	5	35 XXX	SP	CRE	ID	TD	8/9/2029	
2020 PO0774036740	ODP	3	40 XXX	SP	CRE	ED,ID,RB	X	RP1	8/10/2029
2020 PO6722514025	KU	6	30 XXX	SP	CRE	ID	TD	8/11/2029	
2020 PO6730913889	KU	4	40 XXX	SP	CRE	ID	TD	8/12/2029	
2020 PO6731813717	KU	6	30 XXX	SP	CRE	ID	TD	8/13/2029	
2020 PO6729913811	KU	5	35 XXX	SP	CRE	HH,RB	X	PX	8/14/2029
2020 PO6677514465	KU	6	30 XXX	SP	CRE	ID	TD	8/15/2029	
2020 PO6674614389	KU	6	30 XXX	SP	CRE	ID	TD	8/16/2029	
2020 PO6674414155	KU	6	30 XXX	SP	CRE	ID	TD	8/17/2029	
2020 PO6680414125	KU	6	30 XXX	SP	CRE	ID	TD	8/18/2029	
2020 PO6675413955	KU	5	30 XXX	SP	CRE	ID	TD	8/19/2029	
2020 PO2060846658	KU	6	30 ACE	SP	CRE	ED,ID	TD	8/20/2029	
2020 PO6681613393	KU	4	40 XXX	SP	CCA		V	8/21/2029	
2020 PO6687213299	KU	6	30 XXX	SP	CCA		V	8/22/2029	
2020 PO6691913481	KU	4	40 XXX	SP	CRE	ID	TD	8/23/2029	
2020 PO6711113704	KU	6	30 XXX	SP	CRE	ID	TD	8/24/2029	
2020 PO6702513666	KU	6	30 XXX	SP	CRE	ID	TD	8/25/2029	
2020 PO6320612364	KU	6	30 XXX	SP	CCA		V	8/26/2029	
2020 PO6586514056	KU	4	40 XXX	SP	CRE		V	8/27/2029	
2020 PO6614913367	KU	6	30 XXX	SP	CRE		V	8/28/2029	
2020 PO6581113555	F	4	40 XXX	SP	CRE		V	8/29/2029	
2020 PO7027994671	KU	4	40 BRN	SP	CRE	ED,ID	TD	8/30/2029	
2020 PO7027694716	KU	5	35 BRN	SP	CCA		V	8/31/2029	
2020 PO7032094778	KU	4	40 BRN	SP	CRE	ED,ID	BD	9/1/2029	
2020 PO7034394834	KU	5	35 BRN	SP	S		V	9/2/2029	
2020 PO7040094977	KU	5	35 BRN	SP	CRE	ED,ID	TD	9/3/2029	
2020 PO7042995055	KU	4	45 BRN	SP	CRE	ED,ID	BD	9/4/2029	
2020 PO7026095124	KU	2	70 BRN	SP	CRE	ED	VX	RP2	9/5/2029
2020 PO7031795276	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/6/2029	

2020 PO7054595518	KU	5	35 BRN	SP	CRE	ED,ID	TD	9/7/2029
2020 PO2066446556	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	9/8/2029
2020 PO6806402248	F	4	40 KOP	SP	CRE		V	9/9/2029
2020 PO6572103590	KU	6	30 BRN	SP	CRE		V	9/10/2029
2020 PO6569803535	F	4	40 BRN	SP	CRE		V	9/11/2029
2020 PO6591103461	F	4	40 BRN	SP	CRE		V	9/12/2029
2020 PO6701902671	KU	3	40 BRN	SP	CCA		V	9/13/2029
2020 PO5455411274	KU	6	30 BRO	SP	CRE	ID	TD	9/14/2029
2020 PO5457010982	KU	6	30 BRO	SP	CCA		V	9/15/2029
2020 PO5463411044	KU	4	40 BRO	SP	CRE	ID	TD	9/16/2029
2020 PO5476810962	KU	4	40 BRO	SP	CCA		V	9/17/2029
2020 PO5491110760	KU	4	40 BRO	SP	CRE	ID	TD	9/18/2029
2020 PO5506110602	KU	4	40 BRO	SP	CRE	ID	X	9/19/2029
2020 PO5499610639	KU	4	40 BRO	SP	CRE	ID	BD	9/20/2029
2020 PO5482610600	KU	4	40 BRO	SP	CRE	ID	TD	9/21/2029
2020 PO5466710559	KU	4	40 BRO	SP	CRE	ID	TD	9/22/2029
2020 PO5527810501	KU	5	35 BRO	SP	CCA		V	9/23/2029
2020 PO5513110540	KU	5	35 BRO	SP	CCA		V	9/24/2029
2020 PO8975782972	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	9/25/2029
2020 PO8919981314	F	3	45 BRO	SP	CRE		V	9/26/2029
2020 PO8943481374	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	9/27/2029
2020 PO8948583404	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	9/28/2029
2020 PO8946383559	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	9/29/2029
2020 PO8948983566	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	9/30/2029
2020 PO9024880581	F	6	30 BRO	SP	CCA		V	10/1/2029
2020 PO9013280501	KU	5	35 BRO	SP	CCA		V	10/2/2029
2020 PO9040881203	KU	3	45 BRO	SP	CRE	ID,IP	BD	10/3/2029
2020 PO8866683052	KU	2	65 BRO	SP	CRE		V	10/4/2029
2020 PO8863783401	KU	1	75 BRO	SP	CRE		V	10/5/2029
2020 PO9045781248	KU	3	45 BRO	SP	CRE	ID,IP	TD	10/6/2029
2020 PO8861683648	KU	2	70 BRO	SP	CRE	ED,ID,SR	TD	10/7/2029
2020 PO8860183715	KU	5	35 BRO	SP	CRE	ID	BD	10/8/2029
2020 PO9086380995	KU	3	45 BRO	SP	CRE	ID,IP	BD	10/9/2029
2020 PO9073480899	KU	3	55 BRO	SP	A	ED	TD	10/10/2029
2020 PO9097881081	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	10/11/2029
2020 PO9111481192	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	10/12/2029
2020 PO9054180782	F	4	40 BRO	SP	CCA		V	10/13/2029
2020 PO8787383708	KU	3	45 BRO	SP	CRE	EP,IP,RB	BX	10/14/2029
2020 PO8810183690	KU	4	40 BRO	SP	CCA		V	10/15/2029
2020 PO8742583742	KU	3	35 BRO	SP	CRE	ED,ID,SRS	TD	10/16/2029
2020 PO8761083727	KU	3	40 BRO	SP	CCA		V	10/17/2029
2020 PO8767983723	KU	3	40 BRO	SP	CCA		V	10/18/2029
2020 PO4549502315	KU	2	55 BRO	SP	CRE	ID	TD	10/19/2029
2020 PO4056402549	KU	6	30 BRN	SP	CCA		V	10/20/2029
2020 PO7403578866	KU	3	45 BRN	SP	CCA	ED,ID	BD	10/21/2029
2020 PO7404379019	KU	4	45 BRN	SP	CRE		V	10/22/2029
2020 PO7403278988	KU	6	30 BRN	SP	CRE		V	10/23/2029

2020 PO7415678901	KU	4	40 BRN	SP	CRE	ED,ID	TD		10/24/2029
2020 PO7631781687	KU	5	35 BRO	SP	CRE	ED,ID	BD		10/25/2029
2020 PO7430178945	KU	6	30 BRN	SP	CRE		V		10/26/2029
2020 PO7444578988	KU	6	30 BRN	SP	CRE	ED,ID	TD		10/27/2029
2020 PO7447878889	KU	4	45 BRN	SP	CCA		V		10/28/2029
2020 PO7457178937	KU	6	30 BRN	SP	CRE		V		10/29/2029
2020 PO7382478815	F	3	45 BRN	SP	CRE		V		10/30/2029
2020 PO7378178574	F	3	45 BRN	SP	CRE		V		10/31/2029
2020 PO7374478376	F	2	45 BRN	SP	CRE		V		11/1/2029
2020 PO7633181593	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD		11/2/2029
2020 PO7634681497	KU	4	40 BRO	SP	CRE	ED,ID	BD		11/3/2029
2020 PO8325267160	KU	4	40 BRO	SP	A	ED,ID	BD		11/4/2029
2020 PO8320167214	KU	4	40 BRO	SP	CCA		V		11/5/2029
2020 PO8312567280	KU	4	40 BRO	SP	CRE		V		11/6/2029
2020 PO8299466878	KU	4	45 BRO	SP	CCA		V		11/7/2029
2020 PO8319966952	KU	6	30 BRO	SP	CRE	ED,ID	TD		11/8/2029
2020 PO7633681263	KU	4	40 BRO	SP	CRE		V		11/9/2029
2020 PO7636881117	KU	5	30 BRO	SP	CRE		V		11/10/2029
2020 PO7625181075	KU	5	35 BRO	SP	CCA		V		11/11/2029
2020 PO7633981059	KU	4	40 BRO	SP	CRE	ED,ID	BD		11/12/2029
2020 PO7730781529	KU	6	30 BRO	SP	CRE	ED,ID	TD		11/13/2029
2020 PO7726981627	KU	4	40 BRO	SP	CRE	ED,ID	TD		11/14/2029
2020 PO7722681690	KU	5	30 BRO	SP	CRE	ID	BD		11/15/2029
2020 PO7711381609	KU	5	35 BRO	SP	CRE	ED,ID	TD		11/16/2029
2020 PO8312567020	KU	4	40 BRO	SP	CRE	ED,ID,IP,RB	TX	RR	11/17/2029
2020 PO7696581589	KU	4	40 BRO	SP	CRE	ED,ID	TD		11/18/2029
2020 PO7682881711	KU	7	30 BRO	SP	CRE	ED,ID	TD		11/19/2029
2020 PO8352966822	KU	4	40 BRO	SP	CRE	ED,HH,ID	VX	PX	11/20/2029
2020 PO7710381877	KU	5	35 BRO	SP	CRE	ED,ID	TD		11/21/2029
2020 PO8294966816	KU	5	35 BRO	SP	CCA		V		11/22/2029
2020 PO8283666973	KU	4	45 BRO	SP	CCA		V		11/23/2029
2020 PO8273467036	KU	4	45 BRO	SP	CCA		V		11/24/2029
2020 PO8278567090	KU	5	35 BRO	SP	CCA		V		11/25/2029
2020 PO8403767374	KU	4	40 BRO	SP	CCA		V		11/26/2029
2020 PO8417667519	KU	4	40 BRO	SP	CRE	ED,ID	BD		11/27/2029
2020 PO7701581864	KU	4	40 BRO	SP	CRE	ED,ID	BD		11/28/2029
2020 PO7689481845	KU	4	40 BRO	SP	CRE	ED,ID	TD		11/29/2029
2020 PO7676581824	KU	4	40 BRO	SP	CRE	ED,ID	TD		11/30/2029
2020 PO7662181959	F	2	50 BRO	SP	A		V		12/1/2029
2020 PO7664881770	KU	3	50 BRO	SP	CCA		V		12/2/2029
2020 PO4102702516	KU	6	30 BRN	SP	CCA		V		12/3/2029
2020 PO4092302556	KU	5	30 XXX	SP	CRE	ED,ID	TD		12/4/2029
2020 PO7665281562	KU	4	45 BRO	SP	CRE	ED,ID	TD		12/5/2029
2020 PO7665581427	KU	4	45 BRO	SP	CCA		V		12/6/2029
2020 PO4092402739	KU	5	35 XXX	SP	CRE	ED,ID	TD		12/7/2029
2020 PO4086602826	KU	4	40 XXX	SP	CRE	ED,ID	TD		12/8/2029
2020 PO4057302575	KU	4	40 BRN	SP	CCA		V		12/9/2029

2020 PO4060602726	KU	4	40 BRN	SP	CCA		V	12/10/2029
2020 PO4062702775	KU	5	30 BRN	SP	CCA		V	12/11/2029
2020 PO4071402683	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD	12/12/2029
2020 PO8385967273	KU	6	30 BRO	SP	CRE	ED,ID	TD	12/13/2029
2020 PO8390567233	KU	4	45 BRO	SP	CRE	ED,ID	BD	12/14/2029
2020 PO7294578159	KU	4	45 BRN	SP	CRE	ED,ID	TD	12/15/2029
2020 PO7684879964	KU	4	40 BRO	SP	CRE	ED,ID	BD	12/16/2029
2020 PO7247577735	KU	4	45 BRN	SP	CCA		V	12/17/2029
2020 PO7267877863	KU	4	40 BRN	SP	CCA		V	12/18/2029
2020 PO7258777757	KU	4	45 BRN	SP	CCA		V	12/19/2029
2020 PO7280277945	KU	4	45 BRN	SP	CRE	ED,HH,ID	BX	PX 12/20/2029
2020 PO4053302772	KU	5	30 XXX	SP	CRE	ED,ID	TD	12/21/2029
2020 PO4052402883	KU	6	30 XXX	SP	CRE	ED,ID	TD	12/22/2029
2020 PO4064102896	KU	3	45 BRN	SP	CCA		V	12/23/2029
2020 PO3912203997A	KU	6	30 XXX	SP	CRE	ID	BD	12/24/2029
2020 PO8367867089	KU	6	30 BRO	SP	CRE	ED,ID	BD	12/25/2029
2020 PO8373167041	KU	4	45 BRO	SP	A	ED,ID	BD	12/26/2029
2020 PO8352966957	KU	6	30 BRO	SP	P	ED,ID	TD	12/27/2029
2020 PO7698679966	KU	5	35 BRO	SP	CCA		V	12/28/2029
2020 PO7745380177	KU	5	35 BRO	SP	CCA		V	12/29/2029
2020 PO9037081156	KU	6	30 BRO	SP	CCA		V	12/30/2029
2020 PO9141281096	KU	3	45 BRO	SP	P	ED	T	12/31/2029
2020 PO9088877812	KU	4	40 BRO	SP	CRE	ED	TD	1/1/2030
2020 PO9089977948	KU	3	50 BRO	SP	CRE	ED,ID,IP	TD	1/2/2030
2020 PO9091678121	KU	3	45 BRO	SP	CRE	ED	TD	1/3/2030
2020 PO9093278295	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	1/4/2030
2020 PO9095178482	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	1/5/2030
2020 PO6880577378	KU	4	40 BRN	SP	CRE	ED,ID	TD	1/6/2030
2020 PO6860177102	KU	4	40 BRN	SP	CRE	ED,ID	TD	1/7/2030
2020 PO6844876908	KU	4	45 BRN	SP	CCA		V	1/8/2030
2020 PO6771775421	KU	6	30 BRN	SP	CCA		V	1/9/2030
2020 PO6771275683	KU	4	40 BRN	SP	CRE	ED,ID	BD	1/10/2030
2020 PO6758275787	KU	4	40 BRN	SP	CRE	ED,ID	TD	1/11/2030
2020 PO6720775801	KU	4	40 BRN	SP	CRE	ED,ID	TD	1/12/2030
2020 PO6694475813	KU	4	40 BRN	SP	CRE	ED,ID	TD	1/13/2030
2020 PO8309572180	KU	6	35 BRO	SP	CRE	ED,ID	BD	1/14/2030
2020 PO8335371947	KU	4	45 BRO	SP	CRE	ED,ID	BD	1/15/2030
2020 PO8351471875	KU	4	45 BRO	SP	CRE	ED,ID	TD	1/16/2030
2020 PO0642562588	KU	3	45 BRN	SP	CRE	ED,ID,IP	TX	RR 1/17/2030
2020 PO4410001372	F	4	40 BRO	SP	CRE		V	1/18/2030
2020 PO6825376536	F	3	45 BRN	SP	P		V	1/19/2030
2020 PO6812276382	F	3	45 BRN	SP	P		V	1/20/2030
2020 PO7051488152	KU	2	60 BRO	SP	CRE	ED,ID	BD	1/21/2030
2020 PO7065988347	KU	2	60 BRO	SP	CRE	ED,ID	BD	1/22/2030
2020 PO6721674593	KU	6	30 BRN	SP	CRE	ED,ID	TD	1/23/2030
2020 PO6723374668	KU	5	35 BRN	SP	CRE	ED,ID	TD	1/24/2030
2020 PO6705674873	KU	5	35 BRN	SP	CRE	ED,ID	TD	1/25/2030

2020 PO6669673798	KU	4	45 BRN	SP	CRE	ED,ID	BD		1/26/2030
2020 PO6696673624	KU	4	45 BRN	SP	CRE	ED,ID	BD		1/27/2030
2020 PO4469800699	KU	4	40 BRO	SP	CCA		V		1/28/2030
2020 PO4485500834	KU	5	30 BRO	SP	CCA		V		1/29/2030
2020 PO4469200891	F	4	40 BRO	SP	CRE		V		1/30/2030
2020 PO4483101066	KU	4	30 BRO	SP	CCA		V		1/31/2030
2020 PO4443201045	KU	6	30 BRO	SP	CCA		V		2/1/2030
2020 PO4426501154	KU	6	30 BRO	SP	CRE	ID	TD		2/2/2030
2020 PO4429501209	KU	2	70 BRO	SP	CRE	ID	BD		2/3/2030
2020 PO4440001221	F	4	40 BRO	SP	CRE		V		2/4/2030
2020 PO4440300913	F	4	40 BRO	SP	CRE		V		2/5/2030
2020 PO4451001044	KU	6	30 BRO	SP	CRE	ID	TD		2/6/2030
2020 PO0637662473	KU	4	45 BRN	SP	CRE	ED,ID,IP	BD		2/7/2030
2020 PO0634362395	KU	3	50 BRN	SP	CRE	ED,ID,IP	TX	RR	2/8/2030
2020 PO0626962425	KU	5	35 BRN	SP	CCA		V		2/9/2030
2020 PO0628762263	KU	2	50E BRN	DF	CRE	ED,ID,IP	TD		2/10/2030
2020 PO0627662238	KU	3	45 BRN	SP	CCA		V		2/11/2030
2020 PO0641661839	KU	7	30E BRN	SP	CRE	ID	TD		2/12/2030
2020 PO0647261956	KU	4	40 BRN	SP	CRE	ID	TD		2/13/2030
2020 PO0628462041	KU	4	40 BRN	SP	CRE	ID	TD		2/14/2030
2020 PO0626561991	F	6	30E BRN	SP	CRE		V		2/15/2030
2020 PO0624162004	F	6	30E BRN	SP	CRE		V		2/16/2030
2020 PO0616261972	KU	2	50 BRN	SP	CCA		V		2/17/2030
2020 PO0616261972-A	KU	2	50 BRN	SP	CRE	ID	BD		2/18/2030
2020 PO0573362167	KU	4	45 BRN	SP	CRE	ID,IP	TD		2/19/2030
2020 PO2101389817	KU	5	35 BRO	SP	CRE	ED,EP,HH,ID,RB	BX	RP2	2/20/2030
2020 PO2183189883	KU	4	40 BRO	SP	CCA		V		2/21/2030
2020 PO9244682571	KU	3	45 OTH	SP	CCA		V		2/22/2030
2020 PO9249682619	KU	4	45 OTH	SP	CCA		V		2/23/2030
2020 PO9292580070	KU	4	40 OTH	SP	CRE		V		2/24/2030
2020 PO9245679984	F	4	40 OTH	SP	CCA		V		2/25/2030
2020 PO9237679607	KU	4	40 OTH	SP	CRE	ID,IP	BD		2/26/2030
2020 PO9256879630	KU	4	40 OTH	SP	CRE	ID,IP	BD		2/27/2030
2020 PO9085880171	F	4	40 OTH	SP	CCA		V		2/28/2030
2020 PO9071780220	F	4	40 OTH	SP	CCA		V		3/1/2030
2020 PO9164779952	F	4	40 OTH	SP	A		V		3/2/2030
2020 PO9130880023	F	4	40 OTH	SP	A		V		3/3/2030
2020 PO9122280050	F	4	40 OTH	SP	CCA		V		3/4/2030
2020 PO9198681225	F	3	45 OTH	SP	CRE		V		3/5/2030
2020 PO9196681294	KU	6	30 OTH	SP	CRE	ED,ID,IP	TD		3/6/2030
2020 PO9256182534	F	5	35 OTH	SP	A		V		3/7/2030
2020 PO9259682719	KU	4	40 OTH	SP	CRE	ID,IP	BD		3/8/2030
2020 PO9202582127	KU	4	40 OTH	SP	CRE	ED,ID,IP	TD		3/9/2030
2020 PO4891605331	KU	6	30 XXX	SP	CRE		V		3/10/2030
2020 PO6405083054	KU	4	40 BRN	SP	CRE	ED,HH,ID,RB	X	RP1	3/11/2030
2020 PO6408783008	KU	4	40 BRN	SP	CCA		V		3/12/2030
2020 PO6422882985	KU	5	35 BRN	SP	CCA		V		3/13/2030

2020 PO6385782582	KU	4	45 BRN	SP	CRE	ED,ID	TD	3/14/2030
2020 PO6374682511	KU	4	45 BRN	SP	CRE	ED,ID	BD	3/15/2030
2020 PO6373282264	KU	4	40 BRN	SP	CRE	ED,ID	BD	3/16/2030
2020 PO4967905598	KU	5	30 XXX	SP	CRE	RB	BX	PX 3/17/2030
2020 4961105593A	KU	5	30 XXX	SP	CRE	ED,ID	TD	3/18/2030
2020 PO4977405602	KU	6	30 ACW	SP	CRE	ED,ID	TD	3/19/2030
2020 PO4961105593	KU	6	30 ACW	SP	CRE	ED,ID	TD	3/20/2030
2020 PO4947405567	KU	5	35 XXX	SP	CRE	ED,ID	TD	3/21/2030
2020 PO4935405511	KU	6	30 XXX	SP	CRE	ED,ID	TD	3/22/2030
2020 PO4933005561	KU	5	35 XXX	SP	CRE	ED,ID	TD	3/23/2030
2020 PO4918305550	KU	4	40 ACW	SP	CRE	ED,ID	TD	3/24/2030
2020 PO4892505561	KU	6	30 KOP	SP	CRE	ID	BD	3/25/2030
2020 PO5149397896	KU	4	40 BRN	SP	CRE	ID	TD	3/26/2030
2020 PO6371882039	KU	4	40 BRN	SP	CRE	ED,ID	TD	3/27/2030
2020 PO7501875601	KU	3	50 BRN	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX 3/28/2030
2020 PO4493400994	F	4	40 BRO	SP	CRE		V	3/29/2030
2020 PO8129770145	KU	4	40 BRO	SP	A	ED,ID	BD	3/30/2030
2020 PO8119670325	KU	6	30 BRO	SP	CRE	ED,ID	TD	3/31/2030
2020 PO7483475601	KU	3	50 BRN	SP	CRE	ED,ID	TD	4/1/2030
2020 PO7331576991	KU	5	35 BRN	SP	CCA		V	4/2/2030
2020 PO7388477092	KU	5	35 BRN	SP	CRE	ED,ID	BD	4/3/2030
2020 PO4909105214	KU	6	30 XXX	SP	CRE	ED,ID	TD	4/4/2030
2020 PO4910405287	KU	4	40 BRN	SP	CRE	ED,ID	TD	4/5/2030
2020 PO4895905235	KU	5	35 XXX	SP	CRE	ED,ID	TD	4/6/2030
2020 PO4902705278	KU	6	30 XXX	SP	CRE	ED,ID	TD	4/7/2030
2020 PO4885005260	KU	6	30 XXX	SP	CRE	ED,ID	TD	4/8/2030
2020 PO8034572866	KU	4	40 BRO	SP	CRE	ID	BD	4/9/2030
2020 PO8037272817	KU	5	35 BRO	SP	CRE	ED,ID	TD	4/10/2030
2020 PO8033072723	KU	6	30 BRO	SP	CRE	ED,ID	TD	4/11/2030
2020 PO4877005260	KU	6	30 XXX	SP	CRE	ED,ID	TD	4/12/2030
2020 PO4885005164	KU	4	40 XXX	SP	CRE	ED,ID	TD	4/13/2030
2020 PO7990372627	KU	4	45 BRO	SP	CCA		V	4/14/2030
2020 PO7980772577	KU	4	45 BRO	SP	CRE		V	4/15/2030
2020 PO8364169155	KU	2	70 BRO	SP	CRE		V	4/16/2030
2020 PO8133270390A	KU	4	35 BRO	SP	A	ED,ID	BD	4/17/2030
2020 PO4023906263	KU	4	40 XXX	SP	CRE		V	4/18/2030
2020 PO6716074755	F	4	35 BRN	SP	CCA		V	4/19/2030
2020 PO6537273793	KU	4	40 BRN	SP	CRE	ED,ID	TD	4/20/2030
2020 PO6507973872	KU	4	40 BRN	SP	CRE	ED,ID	BD	4/21/2030
2020 PO6649074055	KU	6	30 BRN	SP	CRE	ED,ID	BD	4/22/2030
2020 PO6662074034	KU	4	40 BRN	SP	CCA		V	4/23/2030
2020 PO6655273852	KU	4	40 BRN	SP	CRE	ED,ID	TD	4/24/2030
2020 PO8290672317	KU	4	45 BRO	SP	CRE	ED,ID	BD	4/25/2030
2020 PO8223772066	KU	3	50 BRO	SP	CRE	ED,ID	BD	4/26/2030
2020 PO8339267301	KU	4	40 BRO	SP	CRE	ED,ID	TD	4/27/2030
2020 PO8387668089	KU	4	40 BRO	SP	CRE	ED,ID	BD	4/28/2030
2020 PO8388767795	KU	4	40 BRO	SP	CRE	ED,ID	BD	4/29/2030

2020 PO4575801542	KU	6	30 BRO	SP	CRE	ID	TD	4/30/2030
2020 PO4566200945	KU	4	40 BRO	SP	CRE	ID	TD	5/1/2030
2020 PO6643073484	KU	3	45 BRN	SP	CCA		V	5/2/2030
2020 PO9330952575	KU	4	40 BRO	SP	P	ED	T	5/3/2030
2020 PO9329152356	KU	5	35 BRO	SP	CRE	ED,ID,SRS	TD	5/4/2030
2020 PO9324352145	KU	5	35 BRO	SP	CRE	ED,ID,SRC	TD	5/5/2030
2020 PO9162451148	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD	5/6/2030
2020 PO9166151280-A	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD	5/7/2030
2020 PO0680961316	KU	6	30 ACW	SP	CRE		T	5/8/2030
2020 PO0685261381	KU	4	45 ACW	SP	CRE		T	5/9/2030
2020 PO0710561504	KU	6	30 ACW	SP	CRE		V	5/10/2030
2020 PO0699261337	KU	3	45 ACW	SP	CCA		V	5/11/2030
2020 PO0707761454	KU	3	45 ACW	SP	CCA		V	5/12/2030
2020 PO0699861452	KU	4	35 ACW	SP	CRE	SRS	T	5/13/2030
2020 PO0926060725	KU	4	35 ACW	SP	CRE	SRS	T	5/14/2030
2020 PO0908960792	KU	4	40 ACW	SP	CRE		T	5/15/2030
2020 PO0812867047	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	5/16/2030
2020 PO0819867190	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	5/17/2030
2020 PO0843567953	KU	4	40 BRO	SP	CRE	ID,IP	BD	5/18/2030
2020 PO0838467708	KU	4	40 BRO	SP	CRE	ID,IP	BD	5/19/2030
2020 PO0836467540	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	5/20/2030
2020 PO4806804581	F	4	40 XXX	SP	CRE		V	5/21/2030
2020 PO4963197577	KU	5	35 BRN	SP	CRE		V	5/22/2030
2020 PO7385377373	KU	4	40 BRN	SP	CRE	ED,ID	BD	5/23/2030
2020 PO7378077690	KU	4	40 BRN	SP	CCA		V	5/24/2030
2020 PO7401279203	KU	6	35 BRN	SP	CRE	ED,ID	TD	5/25/2030
2020 PO7393878326	KU	4	40 BRN	SP	CRE	ED,ID	BD	5/26/2030
2020 PO7385378979	KU	4	40 BRN	SP	CRE	ED,ID	BD	5/27/2030
2020 PO4697599091	KU	5	35 BRN	SP	CRE		V	5/28/2030
2020 PO7389579221	KU	4	40 BRN	SP	CRE	ED,ID	BD	5/29/2030
2020 PO4607102257	KU	4	40 XXX	SP	CRE		V	5/30/2030
2020 PO4835804213	KU	5	35 XXX	SP	CRE	ED,ID	TD	5/31/2030
2020 PO4840904322	KU	4	35 BRN	SP	CRE	ED,ID	TD	6/1/2030
2020 PO4846404354	KU	6	30 XXX	SP	CRE	ED,ID	TD	6/2/2030
2020 PO4693999519	KU	4	40 BRN	SP	CRE	ID	TD	6/3/2030
2020 PO4696299341	KU	4	40 BRN	SP	CRE	ID	TD	6/4/2030
2020 PO6828516710	KU	3	45 XXX	SP	CCA		V	6/5/2030
2020 PO6825216475	KU	4	40 XXX	SP	CRE	ID	TD	6/6/2030
2020 PO6805016500	KU	6	30 XXX	SP	CRE	ID	TD	6/7/2030
2020 PO6821316279	KU	4	40 XXX	SP	CRE		V	6/8/2030
2020 PO6828416257	KU	5	20 XXX	SP	CRE		V	6/9/2030
2020 PO6674114547	KU	6	30 XXX	SP	CRE		V	6/10/2030
2020 PO2222150213	F	4	40 ACE	SP	CRE		V	6/11/2030
2020 PO2174449772	KU	4	40 ACE	SP	CCA		V	6/12/2030
2020 PO2182449432	KU	5	35 ACE	SP	CRE	ED,ID	BD	6/13/2030
2020 PO2180649478	KU	5	30 ACE	SP	CRE	ED,ID	TD	6/14/2030
2020 PO7305790038	KU	6	30 BRO	SP	CRE	ED,ID	TD	6/15/2030

2020 PO7296690033	F	4	40 BRO	SP	CRE		V		6/16/2030
2020 PO7311490265	KU	4	40 BRO	SP	CCA		V		6/17/2030
2020 PO7320990197	KU	3	40 BRO	SP	CRE	ED,ID	TD		6/18/2030
2020 PO3929882790	F	4	40 BRO	SP	CCA		V		6/19/2030
2020 PO3930282800	LGE	4	40 BRO	SP	P	ED,ID	BD		6/20/2030
2020 PO6491139650	LGE	4	30 BRO	SP	CCA	ED,ID	VX	RP2	6/21/2030
2020 PO4732209213	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	VX	PX	6/22/2030
2020 PO4730009164	F	4	40 ACE	SP	P		V		6/23/2030
2020 PO4723009009	F	4	40 ACE	SP	CRE		V		6/24/2030
2020 PO4694408490	F	4	40 ACE	SP	CRE	ED,ID	V		6/25/2030
2020 PO3954782294	LGE	3	45 BRN	SP	S		V		6/26/2030
2020 PO3955582312	LGE	3	40 BRN	SP	CRE	ED,ID	BD		6/27/2030
2020 PO3955782316	LGE	6	25 BRN	SP	CRE	ED,ID	BD		6/28/2030
2020 PO3956282325	LGE	4	30 BRN	SP	CRE	ED,ID	BD		6/29/2030
2020 PO3955682325	LGE	4	40 BRN	SP	CRE	ED,ID	TD		6/30/2030
2020 PO3954682329	LGE	6	25 BRN	SP	CRE	ED,ID	BD		7/1/2030
2020 PO3953982316	LGE	6	25 BRN	SP	CRE	ED,HH,ID	VX	PX	7/2/2030
2020 PO3954982311	LGE	4	30 BRN	SP	CRE	ED,ID	BD		7/3/2030
2020 PO3955582305	LGE	5	25 BRN	SP	CRE		V		7/4/2030
2020 PO7298390167	KU	6	30 BRO	SP	CRE	ID	BD		7/5/2030
2020 PO7337390054	KU	5	35 BRO	SP	CRE	ED,ID,MD	TD		7/6/2030
2020 PO2171249246	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD		7/7/2030
2020 PO2356244174	KU	4	40 BRN	SP	CRE	ED,ID,IP,MD,SRC	TD		7/8/2030
2020 PO2366744107	KU	4	40 BRN	SP	CRE	ED,ID,IP,MD,SRC	TD		7/9/2030
2020 PO7156889551	F	3	35 BRN	SP	CRE		V		7/10/2030
2020 PO7001196985	KU	6	30 BRN	SP	CRE	ED,ID	TD		7/11/2030
2020 PO2177448850	KU	4	40 ACE	SP	CRE	ED,ID	BD		7/12/2030
2020 PO2377144038	KU	4	40 BRN	SP	CRE	ED,ID,IP,MD,SRC	TD		7/13/2030
2020 PO2384344185	KU	4	40 BRN	SP	CRE	ED,ID,IP,MD,SRC	TD		7/14/2030
2020 PO7000196902	KU	5	35 BRN	SP	CRE	ED,ID	BD		7/15/2030
2020 PO6998296799	KU	4	40 BRN	SP	CRE	ED,ID	BD		7/16/2030
2020 PO2135148857	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		7/17/2030
2020 PO7016596776	KU	4	40 BRN	SP	CRE	ED,ID	TD		7/18/2030
2020 PO7024796862	KU	5	30 BRN	SP	CRE	ED,ID	BD		7/19/2030
2020 PO7000096584	KU	6	30 BRN	SP	CRE	ED,ID	BD		7/20/2030
2020 PO2142147656	KU	4	40 ACE	SP	CRE	ED,ID	BD		7/21/2030
2020 PO2387044240	F	4	40 BRN	SP	CRE		V		7/22/2030
2020 PO2314144803	KU	4	40 BRN	SP	CRE	ED,ID,IP,SRC	TD		7/23/2030
2020 PO7339590074	KU	4	40 BRO	SP	A	ED,ID	TD		7/24/2030
2020 PO7328690125	KU	3	40 BRO	SP	CRE	ED,ID	TD		7/25/2030
2020 PO7332590090	KU	3	40 BRO	SP	CRE	ED,ID	TD		7/26/2030
2020 PO7337890087	KU	5	35 BRO	SP	CRE	ED,ID	TD		7/27/2030
2020 PO7008396601	KU	5	30 BRN	SP	CRE	ED,ID	TD		7/28/2030
2020 PO7149889791	KU	4	40 BRN	SP	CRE	ED,ID	TD		7/29/2030
2020 PO7163489753	KU	5	35 BRN	SP	CRE	ED,ID	TD		7/30/2030
2020 PO7160889717	KU	4	40 BRN	SP	CRE	ED,ID	TD		7/31/2030
2020 PO7013596615	KU	4	40 BRN	SP	CRE	ED,ID	TD		8/1/2030

2020 PO7018596570	KU	6	30 BRN	SP	CRE	ED,ID	BD		8/2/2030
2020 PO2195148921	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		8/3/2030
2020 6173004697a	KU	6	30 BRN	SP	CRE	ED,ID	TD		8/4/2030
2020 PO2169749040	KU	4	40 ACE	SP	CRE	ED,ID	TD		8/5/2030
2020 PO7003496472	KU	6	30 BRN	SP	CRE	ED,ID	TD		8/6/2030
2020 PO7011696451	KU	4	40 BRN	SP	CCA		V		8/7/2030
2020 PO7010196315	KU	4	40 BRN	SP	CRE	ED,ID,IP	T		8/8/2030
2020 PO6572903018	KU	6	30 BRN	SP	CRE	ED,ID	TD		8/9/2030
2020 PO6553703015	KU	6	30 BRN	SP	CRE	ED,ID	TD		8/10/2030
2020 PO7147589677	KU	6	30 BRN	SP	CRE	ED,ID	TD		8/11/2030
2020 PO2158848924	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		8/12/2030
2020 PO2164349066	KU	4	40 ACE	SP	CRE	ED,ID	TD		8/13/2030
2020 PO2294544764	KU	4	40 BRN	SP	CRE	ED,ID,SRS	TD		8/14/2030
2020 PO6559203143	KU	5	35 XXX	SP	CRE	ED,ID	TD		8/15/2030
2020 PO6547403234	KU	5	35 XXX	SP	CRE	ED,ID	TD		8/16/2030
2020 PO7154889627	KU	4	40 BRN	SP	CRE	ED,ID	BD		8/17/2030
2020 PO2252445114	KU	4	40 BRN	SP	CRE	ED,HH,ID,IP	X	PX	8/18/2030
2020 PO7141689546	KU	6	30 BRN	SP	CRE	ED,ID	TD		8/19/2030
2020 PO7147189514	KU	4	45 BRN	SP	CRE	ED,ID	TD		8/20/2030
2020 PO2152848787	KU	4	40 ACE	SP	CRE	ED,ID	TD		8/21/2030
2020 PO6524303356	KU	6	30 XXX	SP	CRE	RB	BX	RP1	8/22/2030
2020 PO6530603374	KU	4	40 XXX	SP	CRE	ED,ID	TD		8/23/2030
2020 PO5725206368	F	6	30 XXX	SP	CRE		V		8/24/2030
2020 PO5728406437	F	4	40 XXX	SP	CRE	IP	V		8/25/2030
2020 PO5710806287	F	4	40 APL	SP	CRE		V		8/26/2030
2020 PO5715206513	F	3	45 CPT	SP	P		V		8/27/2030
2020 PO5519710069	KU	6	30 BRO	SP	CCA		V		8/28/2030
2020 PO5507710011	KU	6	30 BRO	SP	CCA		V		8/29/2030
2020 PO5504010119	KU	4	40 BRO	SP	CRE	ID	TD		8/30/2030
2020 PO5534010052	KU	6	30 BRO	SP	CRE	ID	TD		8/31/2030
2020 PO5526809880	KU	4	40 BRO	SP	CRE	ID	TD		9/1/2030
2020 PO5530709954	KU	6	30 BRO	SP	CRE	ID	TD		9/2/2030
2020 PO5522309969	KU	6	35 BRO	SP	CRE	ID	BD		9/3/2030
2020 PO5522509833	KU	3	45 BRO	SP	CCA		V		9/4/2030
2020 PO5518109785	KU	5	35 BRO	SP	CRE	ID	TD		9/5/2030
2020 PO1614149282	ODP	2	50 BRN	SP	CCA		V		9/6/2030
2020 1629350008B	ODP	4	40 UNK	SP	CRE	ED,ID	TD		9/7/2030
2020 PO1642849749	ODP	5	35 BRN	SP	CRE		V		9/8/2030
2020 1629350008A	ODP	4	40 BRN	SP	CRE	ED,ID	TD		9/9/2030
2020 PO1629350008	ODP	4	40 BRN	SP	CRE	ED,ID	TD		9/10/2030
2020 PO1635049916	ODP	6	30 BRN	SP	CCA		V		9/11/2030
2020 PO1640250689	ODP	4	45 BRN	SP	CCA		V		9/12/2030
2020 PO1631750958	ODP	5	35 UNK	SP	CRE	ED,ID	TD		9/13/2030
2020 PO2185712675	KU	5	35 BRO	SP	CRE	ED	TD		9/14/2030
2020 PO2156612391	KU	5	35 XXX	SP	CRE	ED,ID	X	RP3	9/15/2030
2020 PO2131012168	KU	5	35 XXX	SP	CRE	ED	TD		9/16/2030
2020 PO1259210445	KU	4	40 XXX	SP	CRE	ED	TD		9/17/2030

2020 PO1223810652	KU	4	45 XXX	SP	CRE	ED	TD	9/18/2030
2020 PO1223810652A	KU	4	45 XXX	SP	CRE	ED	TD	9/19/2030
2020 PO0087716570	KU	5	35 XXX	SP	CRE	ED	TD	9/20/2030
2020 PO0066816535	KU	5	35 XXX	SP	CRE	ED	TD	9/21/2030
2020 PO5487410138	KU	4	40 BRO	SP	CRE	ID	TD	9/22/2030
2020 PO3922683219	LGE	4	30 BRO	SP	P	ED	VX	9/23/2030
2020 PO5475810161	KU	6	30 BRO	SP	CRE	ID	TD	9/24/2030
2020 PO5482110046	KU	4	40 BRO	SP	CRE	ID	TD	9/25/2030
2020 PO5494809829	KU	5	35 BRO	SP	CRE	ID	TD	9/26/2030
2020 PO5505209660	KU	5	35 BRO	SP	CRE	ID	TD	9/27/2030
2020 PO5494309578	KU	5	35 BRO	SP	CRE	ID	TD	9/28/2030
2020 PO5481809486	KU	4	40 BRO	SP	CRE	ID	TD	9/29/2030
2020 PO5475209577	KU	6	30 BRO	SP	CRE	ID	TD	9/30/2030
2020 PO5475209577a	KU	5	35 BRO	SP	CRE	ID	TD	10/1/2030
2020 PO5846406119	F	4	40 BRO	SP	CCA		V	10/2/2030
2020 PO5842306044	F	4	40 BRO	SP	CCA		V	10/3/2030
2020 PO5839605938	F	4	40 BRO	SP	CRE		V	10/4/2030
2020 PO5871806021	KU	6	30 BRO	SP	CRE	ID	TD	10/5/2030
2020 PO5867606019	KU	6	30 BRO	SP	CRE	ID	TD	10/6/2030
2020 PO5865106081	F	5	35 BRO	SP	CCA		V	10/7/2030
2020 PO5863006173	F	4	40 BRO	SP	CCA		V	10/8/2030
2020 PO5894506029	KU	6	30 BRO	SP	CRE	ID	TD	10/9/2030
2020 PO5890306148	KU	6	30 BRO	SP	CCA		V	10/10/2030
2020 PO3922582969	F	4	40 BRO	SP	A		V	10/11/2030
2020 PO3921782972	F	4	35 BRO	SP	P		V	10/12/2030
2020 PO4001682740	LGE	4	40 BRN	SP	A	ED,ID	TD	10/13/2030
2020 PO3921382959	F	5	25 BRO	SP	P		V	10/14/2030
2020 PO3922182956	F	4	40 BRO	SP	P		V	10/15/2030
2020 PO3942581882	LGE	4	40 BRN	SP	CRE	ED,ID	TD	10/16/2030
2020 PO3941581889	LGE	4	40 BRN	SP	CRE	ED,ID	TD	10/17/2030
2020 PO3940381900	LGE	4	40 BRN	SP	CRE	ED,ID	TD	10/18/2030
2020 PO4002082754	LGE	3	50 BRN	SP	A	ED,ID	BD	10/19/2030
2020 PO4001782742	LGE	4	35 BRN	SP	A	ED,ID	TD	10/20/2030
2020 PO3921082918	F	4	40 BRO	SP	CCA		V	10/21/2030
2020 PO3921982913	F	5	25 BRO	SP	CRE		V	10/22/2030
2020 PO3920482905	F	4	40 BRO	SP	P		V	10/23/2030
2020 PO3919982895	F	4	40 BRO	SP	A		V	10/24/2030
2020 PO3918682886	F	5	25 BRO	SP	P		V	10/25/2030
2020 PO3919482884	F	3	45 BRO	SP	CCA		V	10/26/2030
2020 PO4000882754	LGE	4	40 BRN	SP	CRE	ED,ID	BD	10/27/2030
2020 PO3999282747	F	4	45 BRN	SP	S		V	10/28/2030
2020 PO5889006237	KU	3	45 BRO	SP	A	ID	TD	10/29/2030
2020 PO5876206227A	KU	5	35 BRO	SP	A	ID	BD	10/30/2030
2020 PO5876206227	KU	3	45 BRO	SP	CCA		V	10/31/2030
2020 PO5877406138	KU	6	30 BRO	SP	CCA		V	11/1/2030
2020 PO5881406092	F	4	40 BRO	SP	CRE		V	11/2/2030
2020 PO5892905982	KU	6	30 BRO	SP	CCA		V	11/3/2030

2020 PO3939082097	F	4	40 CAH	SP	CCA		ED,HH,ID,RB	BX	RP2	11/4/2030
2020 PO7199990099A	KU	3	30 BRO	SP	CCA			V		11/5/2030
2020 PO7199990099	F	4	35 BRO	SP	CRE			V		11/6/2030
2020 PO7197390061	F	5	35 BRO	SP	CRE			V		11/7/2030
2020 PO7185789878a	KU	3	30 BRO	SP	CCA			V		11/8/2030
2020 PO7140689855	KU	3	50 BRO	SP	CRE		ED,ID	TD		11/9/2030
2020 PO7396193264	KU	5	35 BRO	SP	CRE		ED,ID	TD		11/10/2030
2020 PO7405793237	KU	4	40 BRO	SP	CRE		ED,ID	TD		11/11/2030
2020 PO5672806815	KU	4	35 XXX	SP	CRE		ID	BD		11/12/2030
2020 PO3939982086	F	6	25 CAH	SP	CRE			V		11/13/2030
2020 PO3939182088	F	4	40 CAH	SP	CRE			V		11/14/2030
2020 PO3939482076	F	6	25 CAH	SP	CCA			V		11/15/2030
2020 PO3938682078	F	4	40 CAH	SP	CRE			V		11/16/2030
2020 PO3937982072	F	4	30 CAH	SP	CRE			V		11/17/2030
2020 PO3938282067	F	4	40 CAH	SP	CRE			V		11/18/2030
2020 PO3937582061	F	4	30 CAH	SP	CRE			V		11/19/2030
2020 PO3937782056	F	4	40 CAH	SP	CRE			V		11/20/2030
2020 PO3937282054	F	4	30 CAH	SP	CRE			V		11/21/2030
2020 PO3937282045	F	4	40 CAH	SP	CRE			V		11/22/2030
2020 PO3936782044	F	4	30 CAH	SP	CRE			V		11/23/2030
2020 PO3936782033	F	4	40 CAH	SP	CRE			V		11/24/2030
2020 PO4024882872	F	3	45 BRN	SP	S			V		11/25/2030
2020 PO7436840464	F	3	45 BRN	SP	CRE			V		11/26/2030
2020 PO4030182850	F	4	40 BRN	SP	CRE			V		11/27/2030
2020 PO4029782864	F	4	40 BRN	SP	CRE			V		11/28/2030
2020 PO4026982839	F	4	40 BRN	SP	A			V		11/29/2030
2020 PO4028682867	F	4	30 BRN	SP	CRE			V		11/30/2030
2020 PO0054031929	ODP	4	40 XXX	SP	CRE		ID,RB	BX	PX	12/1/2030
2020 PO5672306772	F	5	40 XXX	SP	CRE			V		12/2/2030
2020 PO5664306709	KU	6	30 KOP	SP	CCA			V		12/3/2030
2020 PO5692806810	KU	4	40 KOP	SP	CCA			V		12/4/2030
2020 PO5679506812	KU	4	40 KOP	SP	CCA			V		12/5/2030
2020 PO5682106747	F	4	40 XXX	SP	CRE			V		12/6/2030
2020 PO5662406282	F	6	30 BRN	SP	CRE			V		12/7/2030
2020 PO5661406396	KU	4	40 BRN	SP	CRE		ID	TD		12/8/2030
2020 PO5670706664	KU	4	40 ACW	SP	CRE		ED,ID	TD		12/9/2030
2020 PO5668106633	F	6	30 ACW	SP	CRE			V		12/10/2030
2020 PO5673506644	F	4	40 XXX	SP	CRE			V		12/11/2030
2020 PO5687706627	F	4	40 BRN	SP	CRE			V		12/12/2030
2020 PO7410593638	KU	5	35 BRO	SP	CRE		ED,ID,IP	TD		12/13/2030
2020 PO7422993371	KU	4	45 BRO	SP	CRE		ED,ID	TD		12/14/2030
2020 PO7435893467	KU	4	45 BRO	SP	CRE		ED,ID	TD		12/15/2030
2020 PO9952137794	ODP	2	55 BRN	SP	CCA			V		12/16/2030
2020 PO4008282605	F	4	40 BRN	SP	A			V		12/17/2030
2020 PO4007982599	LGE	4	30 BRN	SP	A		ED,ID	TD		12/18/2030
2020 PO9882838224	ODP	4	45 BRN	SP	CCA			V		12/19/2030
2020 PO4009482598	LGE	4	40 BRN	SP	A		ED,ID	TD		12/20/2030

2020 PO9929537941	ODP	2	55 BRN	SP	CCA		V		12/21/2030
2020 PO4562437820	KU	3	45 BRO	SP	CRE	ID		BD	12/22/2030
2020 PO4571237912	KU	3	45 BRO	SP	CRE	ED,ID		BD	12/23/2030
2020 PO4573537944	KU	3	45 BRO	SP	CCA		V		12/24/2030
2020 PO9969337966	ODP	2	50 BRN	SP	CCA		V		12/25/2030
2020 PO4009582582	LGE	4	30 BRN	SP	A	ED,ID		TD	12/26/2030
2020 PO4010082585	LGE	4	40 BRN	SP	CRE	ED,ID		TD	12/27/2030
2020 PO0068932300	ODP	4	45 XXX	SP	CRE	ID		BD	12/28/2030
2020 PO0080432529	ODP	4	45 XXX	SP	CRE	ED,ID		TD	12/29/2030
2020 PO0642278543	KU	3	40 BRN	SP	CRE	ID		BD	12/30/2030
2020 PO0613478663	KU	4	45 BRN	SP	CRE	ED,ID,IP		TD	12/31/2030
2020 PO0641073686-A	KU	4	40 BRN	SP	CCA		V		1/1/2031
2020 PO0344461474	KU	4	40 ACW	SP	CRE	ED,ID,IP		TD	1/2/2031
2020 PO0353361360	KU	4	45 ACW	SP	CRE	ED,ID		TD	1/3/2031
2020 PO9640353793	KU	4	40 BRN	SP	CRE	ID		BD	1/4/2031
2020 PO9564554051	KU	4	40 BRN	SP	CRE	ED,ID,IP,SR		TD	1/5/2031
2020 PO0005759797	KU	4	40 ACW	SP	CRE	ED,ID		TD	1/6/2031
2020 PO0647873838	KU	4	40 BRN	SP	CCA		V		1/7/2031
2020 PO0657874040	KU	4	40 BRN	SP	CRE	ED		TD	1/8/2031
2020 PO0699374290	KU	4	40 BRN	SP	CCA		V		1/9/2031
2020 PO0729274472	KU	4	40 BRN	SP	CRE		V		1/10/2031
2020 PO0588479440	KU	4	40 BRN	SP	CRE	ID,IP		BD	1/11/2031
2020 PO0617978811	KU	4	40 BRN	SP	CRE	ED,ID,IP		TD	1/12/2031
2020 PO0816750114	KU	4	40 BRN	SP	CRE	ID,IP		BD	1/13/2031
2020 PO0785250207	KU	4	40 BRN	SP	CRE	ID		TD	1/14/2031
2020 PO0742450329	KU	4	45 BRN	SP	CRE	ED		TD	1/15/2031
2020 PO0686850496	KU	4	45 BRN	SP	P	ED		TD	1/16/2031
2020 PO0705352083	KU	2	70 BRN	SP	CRE		V		1/17/2031
2020 PO9578554301	KU	4	40 BRN	SP	CRE	ED,ID,IP,RB		X	1/18/2031
2020 PO9241564200	KU	4	40 ACW	SP	CRE	ED,ID,IP		TD	1/19/2031
2020 PO9272864012	KU	4	40 ACW	SP	CRE	ED,ID,IP		TD	1/20/2031
2020 PO9305963810	KU	4	40 ACW	SP	CCA		V		1/21/2031
2020 PO9604554187	KU	4	40 BRN	SP	CRE	ED,ID,SR		TD	1/22/2031
2020 PO9652556945	KU	4	40 BRN	SP	CRE	ED,ID,SR		TD	1/23/2031
2020 PO9156456112	KU	4	40 BRN	SP	CRE		V		1/24/2031
2020 PO0913350725	KU	4	45 BRN	SP	P	ED		TD	1/25/2031
2020 PO0899850415	KU	4	45 BRN	SP	P	ED,ID,IP		TD	1/26/2031
2020 PO9207564792	KU	4	40 ACW	SP	CRE	ED,ID,IP		TD	1/27/2031
2020 PO0934150543	KU	4	40 BRN	SP	CRE	ID,IP		TD	1/28/2031
2020 PO0921650793	KU	4	40 BRN	SP	CRE	ID,IP		TD	1/29/2031
2020 PO9193864499	KU	6	30 ACW	SP	CRE	ID		BD	1/30/2031
2020 PO1145620945	ODP	4	40 KOP	SP	CRE	ID		TD	1/31/2031
2020 PO1152621409	ODP	6	30 BRN	SP	CCA		V		2/1/2031
2020 PO1125821074	ODP	5	35 ESC	SP	CRE	ED,ID,SRS		TD	2/2/2031
2020 PO0368628642	ODP	5	30 ACW	SP	CRE	ED,ID		TD	2/3/2031
2020 PO0366228769	ODP	5	35 ACW	SP	CRE	ED,ID		TD	2/4/2031
2020 PO4570132072	KU	6	30 ACE	SP	CRE	ED,ID		TD	2/5/2031

2020 PO4562432155	KU	6	30 ACE	SP	CRE	ED,ID	TD	2/6/2031
2020 PO0348828819	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD	2/7/2031
2020 P00392329456a	ODP	5	30 XXX	SP	CCA		V	2/8/2031
2020 PO0392329456	ODP	3	45 XXX	SP	CCA		V	2/9/2031
2020 PO0270530337	ODP	5	35 XXX	SP	CRE		V	2/10/2031
2020 PO0309530058	ODP	5	35 XXX	SP	CRE		V	2/11/2031
2020 PO0344129814	ODP	5	35 XXX	SP	CRE		V	2/12/2031
2020 PO9389217820	KU	6	30 UNK	SP	CRE	ID	TD	2/13/2031
2020 PO3413963178	KU	4	40 BRN	SP	CRE	ID	TD	2/14/2031
2020 PO0375561273	KU	4	40 ACW	SP	CRE	ED,ID	BD	2/15/2031
2020 PO0235460619	F	9	20 ACW	SP	CRE		V	2/16/2031
2020 PO3398163292	KU	4	40 BRN	SP	CRE	ID,IP	TD	2/17/2031
2020 PO3379863430	KU	4	40 BRN	SP	CRE	ID,IP	TD	2/18/2031
2020 PO3359663579	KU	4	40 BRN	SP	CRE	ID	TD	2/19/2031
2020 PO3344163689	KU	6	30 BRN	SP	CRE	ED,HH,ID	X	RP2 2/20/2031
2020 PO0275260731	KU	4	40 ACW	SP	CCA		V	2/21/2031
2020 PO0704361134	KU	6	30 ACW	SP	CRE	ED,ID,IP	BD	2/22/2031
2020 PO0705561064	F	6	30 ACW	SP	CRE		V	2/23/2031
2020 PO0657060989	KU	4	40 ACW	SP	CRE	ED,ID	BD	2/24/2031
2020 PO0661661118	KU	4	45 ACW	SP	CCA		V	2/25/2031
2020 PO0645561173	KU	3	35 ACW	SP	CRE	ED,ID	BD	2/26/2031
2020 PO0649660955	KU	6	30 ACW	SP	CRE	ED,ID	BD	2/27/2031
2020 PO0654660934	KU	4	40 ACW	SP	CRE	ED,ID,IP	BD	2/28/2031
2020 PO3439862986	KU	4	40 BRN	SP	CRE	ID	TD	3/1/2031
2020 PO9451418047	KU	5	35 BRN	SP	CCA		V	3/2/2031
2020 PO9439117970	KU	6	30 BRN	SP	CRE	ID	TD	3/3/2031
2020 PO9418017972	KU	5	35 KOP	SP	CRE	ED,ID,SRS	TD	3/4/2031
2020 PO9405818042	KU	3	45 BRN	SP	CCA		V	3/5/2031
2020 PO2112146764	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	3/6/2031
2020 PO4098245084	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	3/7/2031
2020 PO1081833004	ODP	4	40 XXX	SP	CRE	ED,ID	TD	3/8/2031
2020 PO1117532935	ODP	4	45 XXX	SP	CRE	ID	BD	3/9/2031
2020 PO1122632933	ODP	4	45 XXX	SP	CCA		V	3/10/2031
2020 PO1131132919	ODP	3	50 XXX	SP	CRE	ID	BD	3/11/2031
2020 PO1168233325	ODP	4	40 OTH	SP	CRE	ED,HH,ID,IP	BX	RP1 3/12/2031
2020 PO1167633382	ODP	4	45 OTH	SP	CRE	ID	TD	3/13/2031
2020 PO1162333391	ODP	4	45 OTH	SP	CRE	ID,SRS	TD	3/14/2031
2020 PO3923282510	LGE	4	30 BRN	SP	P	ED,ID	TD	3/15/2031
2020 PO3923882512	LGE	4	45 BRN	SP	CRE	ED,ID	TD	3/16/2031
2020 PO4092744967	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	3/17/2031
2020 PO0665860886	KU	4	40 ACW	SP	CRE	ED,ID,IP	BD	3/18/2031
2020 PO9299818412	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD	3/19/2031
2020 PO3462162846	KU	5	35 BRN	SP	CRE	ID,IP	TD	3/20/2031
2020 PO3490963007	KU	5	35 BRN	SP	CRE	ID,IP	BD	3/21/2031
2020 PO0658360579	KU	4	40 ACW	SP	CRE	ED,EP,ID,IP	BX	RR 3/22/2031
2020 PO3508463082	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	3/23/2031
2020 PO9649754315	KU	4	40 BRO	SP	CCA		V	3/24/2031

2020 PO0634060690	KU	4	40 ACW	SP	CRE	ED,ID	BD	3/25/2031
2020 PO0630459904	KU	4	40 ACW	SP	CCA		V	3/26/2031
2020 PO0622559940	KU	4	40 ACW	SP	CRE	ED,ID	BD	3/27/2031
2020 PO3506462596	KU	5	35 BRN	SP	CRE	ID,IP	TD	3/28/2031
2020 PO3453562533	KU	4	40 BRN	SP	P		B	3/29/2031
2020 PO3443162231	KU	5	35 BRN	SP	CRE	ID,IP	BD	3/30/2031
2020 PO0611259991	KU	5	35 ACW	SP	CRE	ED,ID	BD	3/31/2031
2020 PO0605360017	KU	4	40 ACW	SP	CRE	ED,ID,IP	BD	4/1/2031
2020 PO9658054714	KU	3	45 BRO	SP	CCA		V	4/2/2031
2020 PO9636155027	KU	3	45 BRO	SP	CCA		V	4/3/2031
2020 PO9629354079	KU	4	40 BRO	SP	CCA		V	4/4/2031
2020 PO9009860290	KU	4	40 BRO	SP	P	ED	T	4/5/2031
2020 PO9005160152	KU	4	40 BRO	SP	P	ED	T	4/6/2031
2020 PO9007659610	KU	4	40 BRO	SP	P		B	4/7/2031
2020 PO0649465105	KU	2	50 BRO	SP	CRE	ED,ID,IP	TD	4/8/2031
2020 PO0425366230	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/9/2031
2020 PO0458666186	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/10/2031
2020 PO0521266859	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/11/2031
2020 PO0495766590	KU	4	45 BRO	SP	A	ID,IP	BD	4/12/2031
2020 PO0516265986	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/13/2031
2020 PO0528659537	KU	4	40 ACW	SP	CRE	ID	BD	4/14/2031
2020 PO0539259450	KU	4	40 ACW	SP	CRE	ED,ID	BD	4/15/2031
2020 PO3531162468	KU	5	30 BRN	SP	CRE	ED,HH	X	RP2 4/16/2031
2020 PO3538662226	KU	6	30 BRN	SP	CRE	ID	TD	4/17/2031
2020 PO3547062391	KU	5	35 BRN	SP	CRE	ID	BD	4/18/2031
2020 PO0541059953	KU	4	40 ACW	SP	CRE	ED,ID	BD	4/19/2031
2020 PO0568359837	KU	4	45 ACW	SP	CCA		V	4/20/2031
2020 PO0566959457	KU	5	35 ACW	SP	CCA		V	4/21/2031
2020 PO0562859504	KU	4	40 ACW	SP	CRE	ED,ID	BD	4/22/2031
2020 PO0576559646	KU	5	30 ACW	SP	CCA		V	4/23/2031
2020 PO0566659600	KU	5	30 ACW	SP	CCA		V	4/24/2031
2020 PO0569959681	KU	4	45 ACW	SP	CCA		V	4/25/2031
2020 PO0702059827	KU	5	35 ACW	SP	CCA		V	4/26/2031
2020 PO9193118831	KU	4	40 OTH	SP	CRE		V	4/27/2031
2020 PO9360018196	KU	4	40 UNK	SP	CRE	ID	TD	4/28/2031
2020 PO9341518402	KU	6	30 BRN	SP	CCA		V	4/29/2031
2020 PO9234618766	KU	6	30 OTH	SP	CRE	ID	TD	4/30/2031
2020 PO9252918602	KU	5	35 OTH	SP	CRE	ED,HH,ID,SRC	TX	RR 5/1/2031
2020 PO9387618048	KU	4	40 OTH	SP	CRE	ID	TD	5/2/2031
2020 PO9277618582	KU	6	30 BRN	SP	CCA		V	5/3/2031
2020 PO9343318289	KU	4	40 UNK	SP	CRE	ID	TD	5/4/2031
2020 PO9306518419	KU	4	40 OTH	SP	CRE	ID	TD	5/5/2031
2020 PO9281018612	KU	5	35 UNK	SP	CRE	ED,ID,SRS	TD	5/6/2031
2020 PO9380018091	KU	5	35 UNK	SP	CRE	ED,ID,SRS	TD	5/7/2031
2020 PO9259118533	KU	6	30 BRN	SP	CCA		V	5/8/2031
2020 PO9315118352	KU	5	35 OTH	SP	CRE	ID	TD	5/9/2031
2020 PO9378517966	KU	6	30 OTH	SP	CRE	ED,ID,SRS	TD	5/10/2031

2020 PO3916082598	F	3	45 BRN	SP	CCA		V	5/11/2031
2020 PO3917582588	F	3	45 BRN	SP	CCA		V	5/12/2031
2020 PO3918882580	F	4	40 BRN	SP	CCA		V	5/13/2031
2020 PO3920082572	F	4	40 BRN	SP	CRE		V	5/14/2031
2020 PO3921382564	F	4	45 BRN	SP	CRE		V	5/15/2031
2020 PO3922582556	LGE	4	40 BRN	SP	CRE	ED,ID	TD	5/16/2031
2020 PO1127833508	F	4	35 OTH	SP	CRE		V	5/17/2031
2020 PO2870737002	KU	4	40 BRN	SP	CRE	ED,ID	TD	5/18/2031
2020 PO2863037266	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	5/19/2031
2020 PO2877436756	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	5/20/2031
2020 PO3918682509	F	4	40 BRN	SP	CRE		V	5/21/2031
2020 PO1124133620	ODP	4	40 OTH	SP	CRE	ID	TD	5/22/2031
2020 PO2665850423	KU	3	45 BRO	SP	P	ED	T	5/23/2031
2020 PO3923882548	LGE	3	45 BRN	SP	CCA		V	5/24/2031
2020 PO3997483081	LGE	6	25 BRN	SP	CRE	ED,ID	BD	5/25/2031
2020 PO3938582870	LGE	4	35 BRO	SP	CRE		V	5/26/2031
2020 PO3939682864	LGE	4	35 BRO	SP	CRE		V	5/27/2031
2020 PO4344401869	F	3	45 BRO	SP	CCA		V	5/28/2031
2020 PO5551444189	KU	4	40 BRN	SP	CRE		V	5/29/2031
2020 PO5564844062	KU	4	40 BRN	SP	CRE		V	5/30/2031
2020 PO5656843820	KU	3	45 BRN	SP	CRE		V	5/31/2031
2020 PO5637543751	KU	3	55 BRN	SP	CRE		V	6/1/2031
2020 PO5673242968	C	4	40 BRN	ST	CCA		V	6/2/2031
2020 PO5633143321	KU	3	40 BRN	SP	S		V	6/3/2031
2020 PO5670842930	KU	3	45 BRN	SP	CCA		V	6/4/2031
2020 PO5649243138	F	4	40 BRN	SP	S		V	6/5/2031
2020 PO5528542802	KU	4	45 BRN	SP	S		V	6/6/2031
2020 PO5638443258	KU	3	40 BRN	SP	CCA		V	6/7/2031
2020 PO5617242290	KU	3	40 BRN	SP	CCA		V	6/8/2031
2020 PO5588142599	KU	4	40 BRN	SP	CRE	ID	BD	6/9/2031
2020 PO6975889494	KU	4	45 BRN	SP	CRE	ED,ID	BD	6/10/2031
2020 PO6964389431	KU	4	45 BRN	SP	CRE	ED,ID	BD	6/11/2031
2020 PO6960989394	KU	4	45 BRN	SP	CRE	ED,ID,IP	BD	6/12/2031
2020 PO6959489375	KU	4	45 BRN	SP	CRE	ED,ID	BD	6/13/2031
2020 PO6956289349	KU	4	45 BRN	SP	CRE	ED,ID	BD	6/14/2031
2020 PO6949989432	KU	4	45 BRN	SP	CRE	ED,ID	BD	6/15/2031
2020 PO6944689412	KU	3	50 BRN	SP	CRE	ED,ID	TD	6/16/2031
2020 PO6935589477	KU	3	50 BRN	SP	CRE	ED,ID	BD	6/17/2031
2020 PO6941189582	KU	2	65 BRN	SP	CRE	ED,ID	BD	6/18/2031
2020 PO6932489500	KU	4	45 BRN	SP	CCA		V	6/19/2031
2020 PO6936289579	KU	4	45 BRN	SP	CCA		V	6/20/2031
2020 PO6928689430	KU	4	35 BRN	SP	P	ED,ID	BD	6/21/2031
2020 PO5537606861	F	3	50 BRO	SP	P		V	6/22/2031
2020 PO5599906951	F	4	40 XXX	SP	CRE		V	6/23/2031
2020 PO5654407035	F	4	40 XXX	SP	CCA		V	6/24/2031
2020 PO5609006972	F	4	40 BRN	SP	CRE		V	6/25/2031
2020 PO5630007118	KU	6	30 BRN	SP	CCA		V	6/26/2031

2020 PO5628007001	F	4	40 XXX	SP	CRE		V	6/27/2031
2020 PO5639307015	F	4	40 XXX	SP	CCA		V	6/28/2031
2020 PO5668707046	F	4	40 XXX	SP	CCA		V	6/29/2031
2020 PO5543707006	KU	6	30 BRN	SP	CCA		V	6/30/2031
2020 PO5604007170	F	5	35 XXX	SP	CRE		V	7/1/2031
2020 PO5686807014	F	4	40 XXX	SP	CRE		V	7/2/2031
2020 PO5520507195	F	5	35 XXX	SP	CRE		V	7/3/2031
2020 PO5543907032	KU	6	30 BRN	SP	CCA		V	7/4/2031
2020 PO5487006990	KU	5	35 XXX	SP	CCA		V	7/5/2031
2020 PO5558307017	F	4	40 XXX	SP	CRE		V	7/6/2031
2020 PO5509007250	F	5	35 XXX	SP	CRE		V	7/7/2031
2020 PO5509707181	F	4	40 XXX	SP	CRE		V	7/8/2031
2020 PO5612307190	F	5	30 XXX	SP	CRE		V	7/9/2031
2020 PO5575707039	F	4	40 XXX	SP	CRE		V	7/10/2031
2020 PO5570842439	KU	3	40 BRN	SP	S		V	7/11/2031
2020 PO5490406917	F	3	45 XXX	SP	P		V	7/12/2031
2020 PO6364904064	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	7/13/2031
2020 PO5591207096	F	4	40 XXX	SP	CRE		V	7/14/2031
2020 PO5508606888	F	3	45 XXX	SP	P		V	7/15/2031
2020 PO5495307252	F	4	40 XXX	SP	CRE		V	7/16/2031
2020 PO5526407038	KU	6	30 KOP	SP	CCA		V	7/17/2031
2020 PO5521106873	F	3	45 XXX	SP	P		V	7/18/2031
2020 PO5617607237	KU	6	30 BRO	SP	CCA		V	7/19/2031
2020 PO5558407118	KU	6	30 XXX	SP	CCA		V	7/20/2031
2020 PO5477806940	F	3	50 XXX	SP	P		V	7/21/2031
2020 PO5517407140	F	4	40 XXX	SP	CRE		V	7/22/2031
2020 PO5524207106	F	4	40 KOP	SP	CRE		V	7/23/2031
2020 PO5537807042	F	4	40 XXX	SP	S		V	7/24/2031
2020 PO5485307372	F	4	40 XXX	SP	CRE		V	7/25/2031
2020 PO7373094702	KU	4	45 BRO	SP	CRE	ED,ID	TD	7/26/2031
2020 PO7375794619	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/27/2031
2020 PO7066887463	KU	3	55 BRN	SP	CRE	ED,ID	BD	7/28/2031
2020 PO7064487541	KU	4	50 BRN	SP	CCA		V	7/29/2031
2020 PO7049987797	KU	3	50 BRN	SP	CCA		V	7/30/2031
2020 PO6969187886	KU	4	30 BRN	SP	CRE		V	7/31/2031
2020 PO7020288292	KU	5	35 BRN	SP	CRE	ED,ID	BD	8/1/2031
2020 PO7025787843	KU	6	30 BRN	SP	CRE		V	8/2/2031
2020 PO7034587951	KU	6	30 BRN	SP	CRE	ED,ID	BD	8/3/2031
2020 PO7019387985	F	5	35 BRN	SP	CRE		V	8/4/2031
2020 PO5278206784	KU	4	40 XXX	SP	CRE	ED,ID	TD	8/5/2031
2020 PO5261206677	KU	4	40 XXX	SP	CRE	ED,ID	TD	8/6/2031
2020 PO5290606598	KU	4	45 BRN	SP	CCA		V	8/7/2031
2020 PO5293906666	KU	6	30 BRN	SP	CRE	ED,ID	TD	8/8/2031
2020 PO5279606672	KU	6	30 XXX	SP	CCA		V	8/9/2031
2020 PO5285406737	KU	4	40 XXX	SP	CCA		V	8/10/2031
2020 PO7337494619	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD	8/11/2031
2020 PO7330494806	KU	4	40 BRO	SP	CRE	ID	BD	8/12/2031

2020 PO7335594683	KU	4	40 BRO	SP	CRE	ED,ID	TD		8/13/2031
2020 PO7352494653	KU	4	40 BRO	SP	CRE	ID	BD		8/14/2031
2020 PO7302494581	KU	4	40 BRO	SP	CRE	ED,ID	TD		8/15/2031
2020 PO5342406747	KU	6	30 XXX	SP	CRE	ED,ID	TD		8/16/2031
2020 PO5352006737	F	6	30 XXX	SP	CRE		V		8/17/2031
2020 PO5353806802	KU	4	40 KOP	SP	CRE	ED,ID	TD		8/18/2031
2020 PO5363006720	KU	4	40 KOP	SP	CRE	ED,ID	TD		8/19/2031
2020 PO5359406646	KU	6	30 BRN	SP	CRE	RB	X	PX	8/20/2031
2020 PO5377106893	KU	6	30 BRN	SP	CCA		V		8/21/2031
2020 PO5370806883	KU	4	40 XXX	SP	CRE	ED,ID	TD		8/22/2031
2020 PO5358006884	KU	4	40 XXX	SP	CRE	ED,ID	TD		8/23/2031
2020 5343406888a	KU	5	30 KOP	SP	CRE	ED,ID	TD		8/24/2031
2020 PO5324306815	KU	5	30 BRN	SP	CCA		V		8/25/2031
2020 PO5324206914	KU	4	40 XXX	SP	CRE	ED,ID	TD		8/26/2031
2020 PO5343406888	KU	4	40 XXX	SP	CRE	ED,ID	TD		8/27/2031
2020 PO7303194442	KU	4	40 BRO	SP	CRE	ID	BD		8/28/2031
2020 PO7577495480	KU	4	40 BRO	SP	CRE		B		8/29/2031
2020 PO7037488147	KU	5	35 BRN	SP	CRE	ED,ID	TD		8/30/2031
2020 PO7045388093	KU	5	35 BRN	SP	CRE	ED,ID	TD		8/31/2031
2020 PO7048988062	KU	6	30 BRN	SP	CRE	ED,ID	TD		9/1/2031
2020 PO7042188052	KU	6	30 BRN	SP	CRE	ED,ID	TD		9/2/2031
2020 PO7031588052	KU	2	60 BRN	SP	CRE	ED,ID	TD		9/3/2031
2020 PO7038487990	KU	2	60 BRN	SP	CRE	ED,ID	TD		9/4/2031
2020 PO7138088567	KU	6	30 BRN	SP	CRE		V		9/5/2031
2020 PO7098788810	KU	5	35 BRN	SP	CRE	ED,HH,ID,RB	BX	PX	9/6/2031
2020 PO7100988840	KU	2	60 BRN	SP	P	ED,ID	BD		9/7/2031
2020 PO7099788328	KU	4	45 BRN	SP	CCA		B		9/8/2031
2020 PO7118488487	KU	4	40 BRN	SP	CCA		V		9/9/2031
2020 PO7122588407	KU	1	75 BRN	SP	CRE		V		9/10/2031
2020 PO7130388420-A	KU	5	30 BRN	SP	CRE	ED,ID	TD		9/11/2031
2020 PO7160488196	KU	6	30 BRN	SP	CRE		V		9/12/2031
2020 PO7153488157	KU	5	35 BRN	SP	CCA		V		9/13/2031
2020 PO5382507082	KU	6	30 XXX	SP	CRE		VX	RP2	9/14/2031
2020 PO5372007063	KU	6	30 XXX	SP	CCA		V		9/15/2031
2020 PO1591875309	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		9/16/2031
2020 PO9977761241	KU	4	40 ACW	SP	CRE	ED,ID	TD		9/17/2031
2020 PO0525349467	KU	4	40 BRO	SP	CRE	ID	BD		9/18/2031
2020 PO0522349390	KU	3	45 BRO	SP	CCA		V		9/19/2031
2020 PO0515149218	KU	4	40 BRO	SP	CRE	ID,IP	BD		9/20/2031
2020 PO9973461402	KU	5	35 ACW	SP	CRE	ED,ID	BD		9/21/2031
2020 PO1592574851	KU	4	45 BRN	SP	CRE	ED,ID,IP	TD		9/22/2031
2020 PO9920160125	KU	4	40 ACW	SP	CRE	ED,ID	TD		9/23/2031
2020 PO9874860290	KU	4	40 ACW	SP	P	ED	T		9/24/2031
2020 PO0540149862	KU	4	40 BRO	SP	CRE	ID	BD		9/25/2031
2020 PO0196948694	KU	4	40 BRO	SP	CRE		V		9/26/2031
2020 PO0194849412	KU	4	40 BRO	SP	CRE	ID	BD		9/27/2031
2020 PO9865960022	KU	4	40 ACW	SP	CRE	ED,ID	TD		9/28/2031

2020 PO1682471843	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		9/29/2031
2020 PO1680472662	KU	4	40 BRN	SP	CRE	ED	TD		9/30/2031
2020 PO1657273486	KU	4	45 BRN	SP	CRE	ED,ID,IP	TD		10/1/2031
2020 PO1581275622	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		10/2/2031
2020 PO6370003824	F	4	40 INP	SP	CRE		V		10/3/2031
2020 PO6341004640	F	5	35 OTH	SP	CRE		V		10/4/2031
2020 PO6352804731	F	5	35 OTH	SP	CRE		V		10/5/2031
2020 PO6357904160	F	4	40 OTH	SP	CRE		V		10/6/2031
2020 PO6326704587	KU	3	50 BRN	SP	CCA		V		10/7/2031
2020 PO3876882827	LGE	4	40 BRO	SP	CCA	ED,ID	BD		10/8/2031
2020 PO3875182830	LGE	4	40 BRO	SP	CRE	ED,ID	BD		10/9/2031
2020 PO1109134166	ODP	2	55 XXX	SP	CRE	ED,ID	TD		10/10/2031
2020 PO1121934145	ODP	2	60 XXX	SP	CRE	ED,ID	TD		10/11/2031
2020 PO1131934129	ODP	2	65 XXX	SP	CRE	ED,ID,MD	TD		10/12/2031
2020 PO3874982811	LGE	4	45 BRO	SP	CRE	ED,ID	TD		10/13/2031
2020 PO3875282798	LGE	4	45 BRO	SP	P	ED,ID	TD		10/14/2031
2020 PO1132236907	F	4	40 OTH	SP	CRE		V		10/15/2031
2020 PO1123536917	ODP	4	45 OTH	SP	CCA		V		10/16/2031
2020 PO1210133992	ODP	5	35 XXX	SP	CRE	ED,ID,MD	TD		10/17/2031
2020 PO2405153017	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD		10/18/2031
2020 PO1608774515	KU	4	45 BRN	SP	CRE	ED,ID,IP	TD		10/19/2031
2020 PO3977682817	LGE	6	25 BRN	SP	CRE	ED,ID	TX	RR	10/20/2031
2020 PO1676974334	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		10/21/2031
2020 PO1666273293	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		10/22/2031
2020 PO1699271343	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		10/23/2031
2020 PO5908311430	KU	6	30 BRO	SP	CCA		V		10/24/2031
2020 PO5883311259	KU	6	30 BRO	SP	CCA	ID	BD		10/25/2031
2020 PO5919111488	KU	6	30 BRO	SP	CCA		V		10/26/2031
2020 PO5912411473	KU	4	40 BRO	SP	CRE	ID	TD		10/27/2031
2020 Po5912411473b	KU	5	35 BRO	SP	CCA		V		10/28/2031
2020 Po5912411473a	KU	4	40 BRO	SP	CCA		V		10/29/2031
2020 PO5931711883	KU	4	40 BRO	SP	CRE	ID	TD		10/30/2031
2020 PO5954911928	KU	5	35 BRO	SP	CRE	ID	TD		10/31/2031
2020 PO5939712025	KU	6	30 BRO	SP	CRE	ID	TD		11/1/2031
2020 PO5941812223	KU	4	35 BRO	SP	CRE	ID	TD		11/2/2031
2020 PO5949612152	KU	5	35 BRO	SP	CRE	ID	BD		11/3/2031
2020 PO5933112283	KU	4	40 BRO	SP	CRE	ID	BD		11/4/2031
2020 PO5931312241	KU	6	30 BRO	SP	CCA		V		11/5/2031
2020 PO9387693611	KU	4	40 BRN	SP	CRE	ED,ID,RB,Src	TX	RR	11/6/2031
2020 PO9397793672	KU	4	40 BRN	SP	S	ED,ID,Src	TD		11/7/2031
2020 PO5623452853	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD		11/8/2031
2020 PO5703352925	C	6	30 ACE	SP	CRE		V		11/9/2031
2020 PO5622552985a	KU	3	45 ACE	SP	CCA		V		11/10/2031
2020 PO9283994402	KU	4	40 ACW	SP	CRE	ED,ID	TD		11/11/2031
2020 PO9286494347	KU	4	40 ACW	DF	CRE	ED,ID,RB,Src	X	RP1	11/12/2031
2020 PO9282394336	KU	5	35 ACW	SP	S		V		11/13/2031
2020 PO9296294397	KU	4	40 ACW	SP	CRE	ED,ID	TD		11/14/2031

2020 PO9299694420	C	4	40 ACW	SP	CRE		V			11/15/2031
2020 PO5913312043	KU	4	40 BRO	SP	CRE	ID		TD		11/16/2031
2020 PO5925112151	KU	5	30 BRO	SP	CRE	ID		TD		11/17/2031
2020 PO592612051	KU	4	40 BRO	SP	CRE	ID		TD		11/18/2031
2020 PO5427712523	F	5	35 BRO	SP	CRE		V			11/19/2031
2020 PO2395254779	KU	4	40 BRO	SP	CRE	ED,ID,IP		TD		11/20/2031
2020 PO7258288788	KU	6	30 BRO	SP	CRE	ED,ID		TD		11/21/2031
2020 PO2813141789	F	4	40 BRN	SP	CRE	HH,ID,IP,RB	VX		PX	11/22/2031
2020 PO4164834934	KU	3	40 BRO	SP	CCA	ED		BD		11/23/2031
2020 PO4182834760	KU	5	30 BRO	SP	CRE	ED,ID,IP		TD		11/24/2031
2020 PO4192234678	KU	5	30 BRO	SP	CRE	ED,HH	X		PX	11/25/2031
2020 PO3202042182	KU	4	40 ACE	SP	CRE		V			11/26/2031
2020 PO2800041861	F	4	40 BRN	SP	CRE		V			11/27/2031
2020 PO2786841933	F	4	40 BRN	SP	CRE		V			11/28/2031
2020 PO2783641872	KU	4	40 BRN	SP	CRE	ID,IP		BD		11/29/2031
2020 PO2945940953	KU	6	30 ACE	SP	CRE	ED,ID,IP		BD		11/30/2031
2020 PO2950841041	KU	2	55 ACE	SP	CRE	ED,ID,IP		BD		12/1/2031
2020 PO4666088248	LGE	4	35 BRN	SP	CRE	ED,ID,SRC	TX		RR	12/2/2031
2020 PO2928041163	KU	4	45 ACE	SP	CRE	ED,ID		BD		12/3/2031
2020 PO7261688683	F	5	35 BRO	SP	CRE		V			12/4/2031
2020 PO7185789549	KU	6	30 BRO	SP	CRE	ED,ID		TD		12/5/2031
2020 PO2365354890	KU	5	35 BRO	SP	CRE	ED,ID,IP		TD		12/6/2031
2020 PO2390954573	KU	5	35 BRO	SP	P	ED		T		12/7/2031
2020 PO2325852003	F	3	45 BRO	SP	A		V			12/8/2031
2020 PO7162489591	KU	5	35 BRO	SP	CRE			B		12/9/2031
2020 PO7174789561	KU	4	40 BRO	SP	CRE	ED,ID		TD		12/10/2031
2020 PO4337233668	KU	2	45 BRO	SP	CRE	ED,ID,IP		TD		12/11/2031
2020 PO7249488780	LGE	4	35 BRO	SP	A		V			12/12/2031
2020 PO7249188898	KU	5	35 BRO	SP	CCA		V			12/13/2031
2020 PO7253188981	KU	6	30 BRO	SP	CRE		V			12/14/2031
2020 PO7261089073	KU	5	35 BRO	SP	S		V			12/15/2031
2020 PO7174889622	KU	5	35 BRO	SP	CRE	ED,ID		TD		12/16/2031
2020 PO2971440928	KU	3	55 ACE	SP	CCA		V			12/17/2031
2020 PO2770342153	KU	4	40 BRN	SP	CRE	ID,IP		BD		12/18/2031
2020 PO2764842053	F	4	40 BRN	SP	A		V			12/19/2031
2020 PO4051482757	LGE	3	45 BRO	SP	P	ED,ID		TD		12/20/2031
2020 PO4054882735	LGE	3	45 BRO	SP	CRE	ED,ID		TD		12/21/2031
2020 PO4666488263	LGE	4	35 BRN	SP	P	ED,ID		TD		12/22/2031
2020 PO1368024479	ODP	4	40 BRN	SP	CRE	ID,IP		TD		12/23/2031
2020 PO4052782733	LGE	4	40 BRO	SP	P	ED,ID		TD		12/24/2031
2020 PO4056182731	LGE	3	45 BRO	SP	P	ED,ID		TD		12/25/2031
2020 PO4479410416	KU	4	40 ACE	SP	P		V			12/26/2031
2020 PO4483810526	F	4	40 ACE	SP	P		V			12/27/2031
2020 PO4057782738	LGE	3	45 BRO	SP	CRE	ED,ID,IP		BD		12/28/2031
2020 PO4059782792	LGE	3	55 BRO	SP	A	ED,ID	TX		RR	12/29/2031
2020 PO2446646175	ODP	4	40 KOP	SP	CRE	ED,ID	X		PX	12/30/2031
2020 PO2468346080	ODP	5	35 KOP	SP	CCA	ED,ID		TD		12/31/2031

2020 PO2489745377	ODP	4	45 KOP	SP	S		V			1/1/2032
2020 PO2504745467	F	4	40 KOP	SP	CCA		V			1/2/2032
2020 PO2496245612	F	5	35 KOP	SP	CCA		V			1/3/2032
2020 PO2510145971	ODP	4	45 KOP	SP	S		V			1/4/2032
2020 PO9279194376	C	4	40 ACW	SP	CRE		V			1/5/2032
2020 PO4507110188	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX		RP1	1/6/2032
2020 PO3186142021	KU	4	40 ACE	SP	CRE	ED,ID	TD			1/7/2032
2020 PO2749042139	F	4	40 BRN	SP	CCA		V			1/8/2032
2020 PO2753142209	KU	3	45 BRN	SP	CCA		V			1/9/2032
2020 PO2726242400	KU	4	40 BRN	SP	CRE	ED,ID,MD,SRC	TD			1/10/2032
2020 PO3431543129	KU	6	30 ACE	SP	CRE	ED,ID	BD			1/11/2032
2020 PO3374143412	KU	4	40 ACE	SP	CRE	ED,ID	BD			1/12/2032
2020 PO4320333462	KU	3	45 BRO	SP	CRE	ID,IP	BD			1/13/2032
2020 PO4320333462-A	KU	3	45 BRO	SP	CCA		V			1/14/2032
2020 PO4328533561	KU	3	45 BRO	SP	CRE	ID,IP	BD			1/15/2032
2020 PO7321989521	KU	4	40 BRO	SP	CCA		V			1/16/2032
2020 PO7331089600	KU	5	35 BRO	SP	S		V			1/17/2032
2020 PO7293289141	F	4	40 BRO	SP	CRE		V			1/18/2032
2020 PO7299789217	F	6	35 BRO	SP	CRE		V			1/19/2032
2020 PO7312189325	F	5	35 BRO	SP	CRE		V			1/20/2032
2020 PO7323889427	F	5	35 BRO	SP	CRE		V			1/21/2032
2020 PO7254488820	F	4	40 BRO	SP	CRE		V			1/22/2032
2020 PO7263988899	F	4	40 BRO	SP	CCA		V			1/23/2032
2020 PO4518110146	F	4	40 ACE	SP	CRE	ED,HH,ID,IP,RB	BX		PX	1/24/2032
2020 PO4527010330	F	4	40 ACE	SP	CRE		V			1/25/2032
2020 PO4533410476	F	4	40 ACE	SP	P		V			1/26/2032
2020 PO4670588223	LGE	4	35 BRN	SP	CRE	ED,ID	TD			1/27/2032
2020 PO3580608334	KU	4	40 BRO	SP	CRE		V			1/28/2032
2020 PO3610208562	KU	4	40 BRO	SP	CRE	ID,IP	BD			1/29/2032
2020 PO3594308495	KU	4	40 BRO	SP	CRE	ID,IP	BD			1/30/2032
2020 PO3623608603	KU	4	40 BRO	SP	CRE	ID,IP	BD			1/31/2032
2020 PO4051313508	KU	3	45 BRO	SP	CRE	ID,IP	BD			2/1/2032
2020 PO4671088215	LGE	4	40 BRN	SP	CRE	ED,ID	BD			2/2/2032
2020 PO4670588212	LGE	4	30 BRN	SP	CRE	ED,ID	TD			2/3/2032
2020 PO4532610085	F	4	40 ACE	SP	CCA		V			2/4/2032
2020 PO4570710142	F	4	40 ACE	SP	CCA		V			2/5/2032
2020 PO4556909979	F	4	40 ACE	SP	CRE		V			2/6/2032
2020 PO3642608661	KU	4	40 BRO	SP	CRE	ID	BD			2/7/2032
2020 PO1278927819	ODP	5	35 BRN	SP	CRE	ID	TD			2/8/2032
2020 PO1279927980	ODP	4	40 BRN	SP	CRE	ID	BD			2/9/2032
2020 PO9282694370	C	4	40 ACW	SP	CRE		V			2/10/2032
2020 PO9280594332	KU	5	30 ACW	SP	CRE		V			2/11/2032
2020 PO4765429756	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			2/12/2032
2020 PO5618352890	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD			2/13/2032
2020 PO5622552985	KU	3	45 ACE	SP	CCA		V			2/14/2032
2020 PO5623653068	KU	3	45 ACE	SP	CCA		V			2/15/2032
2020 PO5633752935	KU	4	40 ACE	SP	CRE	ED,ID	TD			2/16/2032

2020 PO4796929695	KU	4	45 BRO	SP	CCA		V			2/17/2032
2020 PO4840929741	KU	3	45 BRO	SP	CCA		V			2/18/2032
2020 PO4867629773	KU	3	45 BRO	SP	CCA		V			2/19/2032
2020 PO5643852891a	KU	6	30 ACE	SP	CCA	ED	T			2/20/2032
2020 PO5646552962	KU	5	30 ACE	SP	CRE	ED,ID	BX	RP1		2/21/2032
2020 PO5643852891	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD			2/22/2032
2020 PO5657652828	KU	4	40 ACE	SP	CRE	ED,ID	TD			2/23/2032
2020 PO4869329997	KU	4	40 BRO	SP	A	ED,ID	TD			2/24/2032
2020 PO4864730424	KU	4	40 BRO	SP	CRE	ED,ID	TD			2/25/2032
2020 PO4674388199	LGE	4	30 BRN	SP	A	ED,ID,SRC	TX	RR		2/26/2032
2020 PO9280394499	KU	4	40 ACW	SP	CRE	ED,ID	BD			2/27/2032
2020 PO9272094502	KU	6	30 ACW	SP	CRE	ED,ID,SRC	TX	RR		2/28/2032
2020 PO4891230214	KU	4	40 BRO	SP	CRE	ID,IP	BD			2/29/2032
2020 PO4914029702	KU	3	45 BRO	SP	A	ED,ID	TD			3/1/2032
2020 PO4917629273	KU	3	45 BRO	SP	CCA		V			3/2/2032
2020 PO7272488971	F	5	35 BRO	SP	CRE		V			3/3/2032
2020 PO7280889038	F	5	35 BRO	SP	CRE		V			3/4/2032
2020 PO7300289071	LGE	3	40 BRO	SP	P	ED,ID	TD			3/5/2032
2020 PO7304189070	LGE	3	40 BRO	SP	P	ED,ID	TD			3/6/2032
2020 PO4310933410	KU	3	45 BRO	SP	CCA		V			3/7/2032
2020 PO4296433523	KU	3	45 BRO	SP	CCA		V			3/8/2032
2020 PO4250034070	KU	4	40 BRO	SP	P	ED	TD			3/9/2032
2020 PO2727542257	F	4	40 BRN	SP	CCA		V			3/10/2032
2020 PO2700842429	KU	3	45 BRN	SP	CRE	ID	BD			3/11/2032
2020 PO3493042826	KU	4	40 ACE	SP	CCA		V			3/12/2032
2020 PO4282733638	KU	4	40 BRO	SP	CRE	ID,IP	TD			3/13/2032
2020 PO4262133884	KU	4	40 BRO	SP	CCA		V			3/14/2032
2020 PO3126441244	KU	4	40 ACE	SP	CRE	ED,ID	TD			3/15/2032
2020 PO7201689431	KU	4	40 BRO	SP	CRE	ED,ID,RB	X	RR		3/16/2032
2020 PO7194589494	KU	3	40 BRO	SP	CRE	ED,ID	TD			3/17/2032
2020 PO3110441071	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD			3/18/2032
2020 PO4674188204	LGE	4	30 BRN	SP	A	ED,ID	TD			3/19/2032
2020 PO4049982743	F	4	40 BRO	SP	CCA		V			3/20/2032
2020 PO4050782731	F	3	45 BRO	SP	CRE		V			3/21/2032
2020 PO4051082725	F	3	45 BRO	SP	CCA		V			3/22/2032
2020 PO4051882710	F	4	40 BRO	SP	CCA		V			3/23/2032
2020 PO4053482693	F	4	35 BRO	SP	CCA		V			3/24/2032
2020 PO4052982691	F	4	40 BRO	SP	A		V			3/25/2032
2020 PO4053682667	F	4	40 BRO	SP	CCA		V			3/26/2032
2020 PO4048382746	F	4	40 BRO	SP	CCA		V			3/27/2032
2020 PO4056082623	LGE	3	50 BRO	SP	CCA		V			3/28/2032
2020 PO4056982613	LGE	3	50 BRO	SP	CCA		V			3/29/2032
2020 PO4058182606	LGE	4	30 BRO	SP	CCA		V			3/30/2032
2020 PO4057782603	LGE	3	50 BRO	SP	CCA		V			3/31/2032
2020 PO7736738337	LGE	3	50 BRO	SP	CCA		V			4/1/2032
2020 PO4054182656	F	3	45 BRO	SP	CCA		V			4/2/2032
2020 PO7817639127	LGE	3	45 BRO	SP	P	ED	T			4/3/2032

2020 PO4062982735	LGE	4	40 BRO	SP	CCA		V		4/4/2032
2020 PO4062982734	LGE	4	40 BRO	SP	CCA		V		4/5/2032
2020 PO4915829490	KU	3	45 BRO	SP	CCA		V		4/6/2032
2020 PO4263034251	KU	4	40 BRO	SP	CRE	ID,IP	TD		4/7/2032
2020 PO4242434149	KU	4	40 BRO	SP	CCA		V		4/8/2032
2020 PO4215734425	KU	4	40 BRO	SP	CCA		V		4/9/2032
2020 PO4204334569	KU	5	30 BRO	SP	CRE		V		4/10/2032
2020 PO4198434630	KU	5	30 BRO	SP	CRE	ID,IP	TD		4/11/2032
2020 PO3094540898	KU	4	40 ACE	SP	CRE	ED,ID	TD		4/12/2032
2020 PO3174241762	KU	4	40 ACE	SP	CRE	ED,ID	BD		4/13/2032
2020 PO4209734501	KU	5	35 BRO	SP	P	ED	TD		4/14/2032
2020 PO7288389106	KU	4	45 BRO	SP	A	ED,ID	TD		4/15/2032
2020 PO728839106a	KU	3	35 BRO	SP	CCA		V		4/16/2032
2020 PO3163241643	KU	4	40 ACE	SP	CCA		V		4/17/2032
2020 PO4220434366	KU	5	35 BRO	SP	CRE	ID	BD		4/18/2032
2020 PO4231334255	KU	4	35 BRO	SP	CRE	ID,IP	TD		4/19/2032
2020 PO3142341416	KU	4	40 ACE	SP	CCA		V		4/20/2032
2020 PO3078540726	KU	4	40 ACE	SP	CRE	ED,ID	TD		4/21/2032
2020 PO3076640870	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		4/22/2032
2020 PO2196650620	KU	3	40 BRO	SP	P	ED	T		4/23/2032
2020 PO2325852003-A	KU	3	45 BRO	SP	A		V		4/24/2032
2020 PO6504613343	KU	6	30 XXX	SP	CRE		V		4/25/2032
2020 PO6953794841	KU	4	40 BRN	SP	CRE	ED,ID	TD		4/26/2032
2020 PO6953194678	KU	4	40 BRN	SP	CRE	ED,ID	BD		4/27/2032
2020 PO2987735824	KU	4	40 BRN	SP	CRE	HH,ID,IP	X	RP3	4/28/2032
2020 PO2992135711	KU	6	30 BRN	SP	CRE	ED,EP,ID,IP	X	RP2	4/29/2032
2020 PO3937936630	KU	5	30 ACE	SP	CRE	ED,ID,IP	TD		4/30/2032
2020 PO3948836569	KU	5	30 ACE	SP	CRE	ID,IP	TD		5/1/2032
2020 PO7918703114	KU	4	40 ACW	SP	CRE	ED,ID	TD		5/2/2032
2020 PO8095605695	KU	5	35 BRN	SP	CRE		V		5/3/2032
2020 PO8108605929	KU	5	35 BRN	SP	CRE		V		5/4/2032
2020 PO8112606170	KU	5	35 BRN	SP	CRE		V		5/5/2032
2020 PO8113206573	KU	5	35 BRN	SP	CRE		V		5/6/2032
2020 PO8133506348	KU	5	35 BRN	SP	CRE		V		5/7/2032
2020 PO8159906645	KU	5	35 BRN	SP	CRE		V		5/8/2032
2020 PO8195806753	KU	4	40 BRN	SP	CRE		V		5/9/2032
2020 PO8224606496	KU	4	40 BRN	SP	CRE		V		5/10/2032
2020 PO8257006501	KU	4	40 BRN	SP	CRE		V		5/11/2032
2020 PO8284906618	KU	4	40 BRN	SP	CRE		V		5/12/2032
2020 PO8326506516	KU	4	40 BRN	SP	CRE		V		5/13/2032
2020 PO8011704674	KU	4	40 BRN	SP	CRE		V		5/14/2032
2020 PO3959636505	KU	5	30 ACE	SP	CRE	ED,HH,ID	X	RP1	5/15/2032
2020 PO3970736447	KU	5	30 ACE	SP	CRE	ED,ID,IP	TD		5/16/2032
2020 PO7991302759	KU	4	40 XXX	SP	CRE	ED,ID	TD		5/17/2032
2020 PO7991402704	KU	5	35 XXX	SP	CRE		V		5/18/2032
2020 PO7987302957	KU	4	45 XXX	SP	CRE	ED,ID,IP	TD		5/19/2032
2020 PO7961202834	KU	4	40 XXX	SP	CRE	ED,ID	TD		5/20/2032

2020 PO7993002379	KU	4	40 XXX	SP	CRE	ED,ID	TD		5/21/2032
2020 PO8024202171	KU	4	45 XXX	SP	CRE	ED,ID,IP	TD		5/22/2032
2020 PO8059202116	KU	4	40 XXX	SP	CRE	ED,ID	TD		5/23/2032
2020 PO8085602040	KU	5	35 XXX	SP	CRE	ED,ID	TD		5/24/2032
2020 PO8155501353	KU	4	40 XXX	SP	CRE	ED,ID,IP	BD		5/25/2032
2020 PO8132601397	KU	5	35 XXX	SP	CCA		V		5/26/2032
2020 8152301681A	KU	5	30 XXX	SP	CRE	ED,ID	TD		5/27/2032
2020 PO8312900608	KU	5	35 XXX	SP	CRE	ED,ID	TD		5/28/2032
2020 PO8323100686	KU	4	40 XXX	SP	CRE	ED,ID	TD		5/29/2032
2020 PO6935294742	KU	6	30 BRN	SP	A	ED,ID,RB	TX	RR	5/30/2032
2020 PO7222189307	F	4	45 BRO	SP	CRE		V		5/31/2032
2020 PO7215089212	F	3	40 BRO	SP	CRE		V		6/1/2032
2020 PO7207489136	F	3	40 BRO	SP	CRE		V		6/2/2032
2020 PO7202489078	F	3	40 BRO	SP	CRE		V		6/3/2032
2020 PO3981836390	KU	5	30 BRO	SP	P	ED	TD		6/4/2032
2020 PO3508842439	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		6/5/2032
2020 PO3509142189	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		6/6/2032
2020 PO4002136244	KU	4	35E BRO	SP	CRE	ED,HH,ID	X	RP2	6/7/2032
2020 PO3992136320	KU	5	30 BRO	SP	CRE	ID,IP,RB	X	RP2	6/8/2032
2020 PO7519492717	F	4	40 BRO	SP	CCA		V		6/9/2032
2020 PO7441892720	KU	5	35 BRO	SP	CRE	ED,ID	TD		6/10/2032
2020 PO4031636013	KU	5	30 BRO	SP	CRE	ED,ID,IP	TD		6/11/2032
2020 PO6952594512	KU	4	40 BRN	SP	CRE	ED,ID	TD		6/12/2032
2020 PO6472203468	KU	3	50 BRN	SP	CCA		V		6/13/2032
2020 PO6467803567	KU	3	50 BRN	SP	CCA		V		6/14/2032
2020 PO2974035271	KU	4	45 BRN	SP	CCA		V		6/15/2032
2020 PO2959535067	KU	4	45 BRN	SP	CCA		V		6/16/2032
2020 PO3509641889	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		6/17/2032
2020 PO7413392911	KU	4	40 BRO	SP	CRE		V		6/18/2032
2020 PO6941494515	KU	5	35 BRN	SP	CRE	ED,ID	BD		6/19/2032
2020 PO6941494515A	KU	5	35 BRN	SP	S		V		6/20/2032
2020 PO7406092938	KU	5	35 BRO	SP	CRE	ID	BD		6/21/2032
2020 PO7443192765	F	3	40 BRO	SP	CRE		V		6/22/2032
2020 PO7416092951	F	4	35 BRO	SP	CCA		V		6/23/2032
2020 PO7429992854	F	5	35 BRO	SP	CRE		V		6/24/2032
2020 PO2942734823	KU	4	45 BRN	SP	CCA		V		6/25/2032
2020 PO3199838281	KU	4	40 BRN	SP	CRE	ID	BD		6/26/2032
2020 PO7842502954	KU	6	30 BRN	SP	CRE	ED,ID	TD		6/27/2032
2020 PO7848203001	KU	4	40 BRN	SP	CRE	ED,ID	TD		6/28/2032
2020 PO7861402979	KU	5	35 XXX	SP	CRE	ED,ID	TD		6/29/2032
2020 PO7883902896	KU	5	35 BRN	SP	CRE	ED,ID	TD		6/30/2032
2020 PO7893303133	KU	4	40 XXX	SP	CRE	ED,ID	TD		7/1/2032
2020 PO7884903065	F	6	30 XXX	SP	CRE		V		7/2/2032
2020 PO4436608872	F	4	40 ACE	SP	CRE		V		7/3/2032
2020 PO4731109599	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX	7/4/2032
2020 PO4454908800	F	4	40 ACE	SP	CRE		V		7/5/2032
2020 PO4473208729	F	4	40 ACE	SP	CRE		V		7/6/2032

2020 PO4491808658	F	4	40 ACE	SP	P		V	7/7/2032
2020 PO4510308586	F	4	40 ACE	SP	P		V	7/8/2032
2020 PO4529008514	F	4	40 ACE	SP	P		V	7/9/2032
2020 PO3951082085	LGE	4	30 BRN	SP	A	ED,ID	TD	7/10/2032
2020 PO3951082090	LGE	4	40 BRN	SP	CRE	ED,ID	TD	7/11/2032
2020 PO2131532314	ODP	4	40 BRN	SP	CRE	ID	TD	7/12/2032
2020 PO9465494078	KU	3	50 ACW	SP	S		V	7/13/2032
2020 PO2139132542	ODP	4	40 BRN	SP	CRE	ID	TD	7/14/2032
2020 PO2141832693	ODP	4	40 UNK	SP	CRE	ID	TD	7/15/2032
2020 PO2151432369	ODP	4	45 BRN	SP	CRE	ID	TD	7/16/2032
2020 PO2171032478	ODP	4	45 BRN	SP	CRE	ID	TD	7/17/2032
2020 PO2184833663A	ODP	6	30 BRN	SP	CCA	ED,ID	TD	7/18/2032
2020 PO2194232617	ODP	4	45 KOP	SP	CRE	ID	TD	7/19/2032
2020 PO2146532899B	ODP	6	30 BRN	SP	CRE	ID	TD	7/20/2032
2020 PO1336629040	ODP	3	50 BRN	SP	CRE	ID	TD	7/21/2032
2020 PO1316329255	ODP	5	35 BRN	SP	CRE	ID	BD	7/22/2032
2020 PO1343028732	F	4	45 SWP	SP	P		V	7/23/2032
2020 PO1344528681	F	3	50 BRN	SP	P		V	7/24/2032
2020 PO9694539690	ODP	5	35 XXX	SP	CRE	ED,ID	TD	7/25/2032
2020 PO9722039836	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD	7/26/2032
2020 PO9633939487	ODP	5	30 XXX	SP	CCA		V	7/27/2032
2020 PO9572939467	ODP	3	45 BRN	SP	CCA		V	7/28/2032
2020 PO9586139426	ODP	3	45 BRN	SP	CCA		V	7/29/2032
2020 PO9474894073	KU	6	30 ACW	SP	S		V	7/30/2032
2020 PO9487594002	KU	3	45 ACW	SP	S		V	7/31/2032
2020 PO9488294045	KU	5	35 ACW	DF	CRE	ED,ID,IP	TD	8/1/2032
2020 PO9514294076	KU	6	30 ACW	SP	CRE	ED,ID	TD	8/2/2032
2020 PO9500394010	KU	5	35 ACW	SP	CRE	ED,ID	TD	8/3/2032
2020 PO9508794036	KU	4	40 ACW	SP	CRE	ED,ID	TD	8/4/2032
2020 PO9505794124	KU	3	45 ACW	SP	S		V	8/5/2032
2020 PO9502194215	KU	6	30 ACW	SP	CRE	ED,ID	TD	8/6/2032
2020 PO9397894547	KU	5	35 ACW	SP	CRE		V	8/7/2032
2020 PO9277394265	C	4	40 ACW	SP	CRE		V	8/8/2032
2020 PO9300494314	C	4	40 ACW	SP	CRE		V	8/9/2032
2020 PO9526394539	C	4	40 ACW	SP	CRE		V	8/10/2032
2020 PO9524294498	C	4	40 ACW	SP	CRE		V	8/11/2032
2020 PO4817921816	KU	3	45 BRO	SP	CCA		V	8/12/2032
2020 PO4779121987	KU	3	45 BRO	SP	CCA		V	8/13/2032
2020 PO4835121729	KU	4	45 BRO	SP	CRE	ID,IP	BD	8/14/2032
2020 PO4835621991	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD	8/15/2032
2020 PO9583939593	ODP	3	45 BRN	SP	CCA		V	8/16/2032
2020 PO9603039652	ODP	3	45 BRN	SP	CCA		V	8/17/2032
2020 PO9625439718	ODP	3	45 BRN	SP	CCA		V	8/18/2032
2020 PO9645739560	ODP	3	45 BRN	SP	CCA		V	8/19/2032
2020 PO4183810863	KU	3	45 BRO	SP	CCA		V	8/20/2032
2020 PO4160410952	KU	3	45 BRO	SP	CCA		V	8/21/2032
2020 PO4136511048	KU	3	45 BRO	SP	CRE		V	8/22/2032

2020 PO4204410853	KU	3	45 BRO	SP	CCA		V	8/23/2032
2020 PO4541710501	F	5	35 ACE	SP	P		V	8/24/2032
2020 PO4550710797	F	5	35 ACE	SP	CRE	ED,ID	V	8/25/2032
2020 PO4529310589	F	5	35 ACE	SP	CRE	ED,ID	V	8/26/2032
2020 PO4541810919	F	4	40 ACE	SP	CRE	ED,ID	V	8/27/2032
2020 PO4474511155	F	4	40 ACE	SP	CRE	ED,ID	V	8/28/2032
2020 PO4485511112	F	4	40 ACE	SP	CRE	ED,ID	V	8/29/2032
2020 PO3960783114	LGE	4	30 BRO	SP	P	ED,ID	TD	8/30/2032
2020 PO1362229522	ODP	5	35 BRN	SP	CCA		V	8/31/2032
2020 PO1544720987	F	4	40 XXX	SP	A		V	9/1/2032
2020 PO1554921078	ODP	6	30 XXX	SP	CRE		V	9/2/2032
2020 PO4844422017	KU	4	45 BRO	SP	CCA		V	9/3/2032
2020 PO1526120590A	ODP	6	30 XXX	SP	CRE	ED,ID,SR	TD	9/4/2032
2020 PO3957683030	LGE	4	40 BRO	SP	P	ED,ID	TD	9/5/2032
2020 PO3956983020	LGE	3	45 BRO	SP	CCA		V	9/6/2032
2020 PO3956183007	LGE	4	40 BRO	SP	CCA		V	9/7/2032
2020 PO3954982991	LGE	4	40 BRO	SP	CCA		V	9/8/2032
2020 PO3953082963	LGE	4	40 BRO	SP	CCA		V	9/9/2032
2020 PO3954282981	LGE	3	45 BRO	SP	P	ED,ID	TD	9/10/2032
2020 PO3951282934	LGE	3	45 BRO	SP	CCA	ED,ID	BD	9/11/2032
2020 PO1327329559	ODP	3	50 BRN	SP	CRE	ED,ID	TD	9/12/2032
2020 PO1332029293	ODP	2	55 BRN	SP	CCA		V	9/13/2032
2020 PO4184610936	KU	3	45 BRO	SP	CRE	ID,IP	BD	9/14/2032
2020 PO9650339303	ODP	3	45 XXX	SP	CCA		V	9/15/2032
2020 PO1365031162	ODP	4	40 BRN	SP	CRE	ID	TD	9/16/2032
2020 PO1398231232	ODP	4	45 BRN	SP	CRE	ID	BD	9/17/2032
2020 PO1343930238	ODP	4	45 BRN	SP	CRE	ID	BD	9/18/2032
2020 PO9657939846	ODP	5	35 XXX	SP	CCA		V	9/19/2032
2020 PO9664339724	ODP	4	45 XXX	SP	CCA		V	9/20/2032
2020 PO9653239467	F	4	40 XXX	SP	CRE		V	9/21/2032
2020 PO1551620888	ODP	6	30 XXX	SP	CRE	ID	TD	9/22/2032
2020 PO1551820741	ODP	4	40 XXX	SP	CRE	ID	TD	9/23/2032
2020 PO1540620476	ODP	5	35 XXX	SP	CRE	ID	TD	9/24/2032
2020 PO4222010779	KU	3	45 BRO	SP	CRE	ID,IP	BD	9/25/2032
2020 PO4214910741	KU	2	45 BRO	SP	CCA		V	9/26/2032
2020 PO4193810897	KU	3	45 BRO	SP	CRE	ID,RB	X	9/27/2032
2020 PO4131610923	KU	5	35 BRO	SP	CRE		V	9/28/2032
2020 PO1370230769A	ODP	5	35 BRN	SP	CCA		V	9/29/2032
2020 PO3955483065	F	4	40 BRO	SP	CCA		V	9/30/2032
2020 PO3958283094	F	4	40 BRO	SP	P		V	10/1/2032
2020 PO3957083075	F	4	40 BRO	SP	CCA		V	10/2/2032
2020 PO3959083105	F	4	40 BRO	SP	CCA		V	10/3/2032
2020 PO3959083113	F	4	35 BRO	SP	CCA		V	10/4/2032
2020 PO3957483081	F	4	40 BRO	SP	A		V	10/5/2032
2020 PO3953883071	F	4	40 BRO	SP	CCA		V	10/6/2032
2020 PO9631640149a	ODP	5	30 XXX	SP	CCA		V	10/7/2032
2020 PO9631640149	ODP	4	40 XXX	SP	CRE	ED,ID	TD	10/8/2032

2020 PO9652540038	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD	10/9/2032
2020 PO4858822219	KU	4	45 BRO	SP	CRE	ED,ID	TD	10/10/2032
2020 PO4868922417	KU	4	45 BRO	SP	CRE	ED,ID	TD	10/11/2032
2020 PO4873822614	KU	4	45 BRO	SP	CRE	ED,ID	TD	10/12/2032
2020 PO4877322881	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD	10/13/2032
2020 PO9585295160	KU	5	35 ACW	SP	CRE	ED,ID,IP,MD,SRC	TD	10/14/2032
2020 PO9593895162	KU	6	30 ACW	SP	CRE	ED,ID	TD	10/15/2032
2020 PO9583440347	F	5	30 BRN	SP	A		V	10/16/2032
2020 PO9601140277	ODP	3	45 BRN	SP	CCA		V	10/17/2032
2020 PO4126511092	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	10/18/2032
2020 PO4115511138	KU	4	40 BRO	SP	CRE	ID	BD	10/19/2032
2020 PO1386230507	ODP	5	35 BRN	SP	CCA	ED	T	10/20/2032
2020 PO2081934144	ODP	5	35 BRN	SP	CRE	ED,ID,SRC	TD	10/21/2032
2020 PO2146532899	ODP	4	40 BRN	SP	CRE	ED,ID,SRC	TD	10/22/2032
2020 PO2146532899A	ODP	3	45 BRN	SP	CCA		V	10/23/2032
2020 PO2135633094	F	4	40 UNK	SP	CCA		V	10/24/2032
2020 PO2165433546	ODP	4	40 KOP	SP	CRE	ID	TD	10/25/2032
2020 PO2149333679	F	4	40 UNK	SP	CRE		V	10/26/2032
2020 PO2132933839	ODP	6	30 BRN	SP	CRE	ED,ID,SRC	TD	10/27/2032
2020 PO2123433813	ODP	5	35 BRN	SP	CRE	ED,ID,SRS	TD	10/28/2032
2020 PO2097233889	ODP	5	35 BRN	SP	CRE	ED,ID,SRS	TD	10/29/2032
2020 PO2055234176	ODP	4	45 BRN	SP	CCA		V	10/30/2032
2020 PO2055234176B	ODP	5	35 BRN	SP	CRE	ED,ID,SRS	TD	10/31/2032
2020 PO2055234176A	ODP	5	30 BRN	SP	CRE	ED,EP,ID,SRC	TD	11/1/2032
2020 PO2068633896	ODP	5	35 BRN	SP	CRE	ED,ID,SRS	TD	11/2/2032
2020 PO2058433708	ODP	5	35 BRN	SP	CRE	ED,ID,SRS	TD	11/3/2032
2020 PO2055234176A	ODP	4	40 BRN	SP	CCA		V	11/4/2032
2020 PO2034734369	ODP	4	45 BRN	SP	CCA		V	11/5/2032
2020 PO4481311006	F	4	40 ACE	SP	CRE	ED,ID	V	11/6/2032
2020 PO1559420526	ODP	4	40 XXX	SP	CRE	ID	TD	11/7/2032
2020 PO3951282916	F	3	45 BRO	SP	CCA		V	11/8/2032
2020 PO3964783094	LGE	3	45 BRO	SP	CCA		V	11/9/2032
2020 PO9573835543	ODP	6	30 BRN	SP	CCA		V	11/10/2032
2020 PO1423630644	ODP	5	35 BRN	SP	CCA		V	11/11/2032
2020 PO1451030858	ODP	4	40 BRN	SP	CRE	ID	TD	11/12/2032
2020 PO1390030891	ODP	5	35 BRN	SP	CRE	ID	TD	11/13/2032
2020 PO1370230769A	ODP	4	45 BRN	SP	CCA		V	11/14/2032
2020 PO4453011262a	KU	4	40 ACE	SP	CRE	ED,ID	V	11/15/2032
2020 PO4453011262	KU	5	35 ACE	SP	CCA		V	11/16/2032
2020 PO4462411206	F	4	40 ACE	SP	CRE	ED,ID	V	11/17/2032
2020 PO4039011466	KU	4	40 BRO	SP	CRE	ID,IP	BD	11/18/2032
2020 PO4037311557	KU	3	45 BRO	SP	CRE	ID,IP	BD	11/19/2032
2020 PO9586941195a	ODP	4	45 BRN	SP	CCA		V	11/20/2032
2020 PO9522534833	ODP	2	50 BRN	SP	CCA		V	11/21/2032
2020 PO9518834759	ODP	3	45 BRN	SP	CCA		V	11/22/2032
2020 PO9512834639	ODP	3	45 BRN	SP	CCA		V	11/23/2032
2020 PO9528634851	ODP	4	40 BRN	SP	CRE		V	11/24/2032

2020 PO9550635293	ODP	4	40 BRN	SP	CRE		V		11/25/2032
2020 PO9540035076	ODP	4	40 BRN	SP	CRE		V		11/26/2032
2020 PO9533434936	ODP	4	40 BRN	SP	CRE		V		11/27/2032
2020 PO9599541051	ODP	6	35 BRN	SP	CRE	ED,ID,RB	X	RP1	11/28/2032
2020 PO1526120590	ODP	6	30 XXX	SP	CCA	ED	TD		11/29/2032
2020 PO1515620734	ODP	2	55 XXX	SP	CCA		V		11/30/2032
2020 PO1564020359	ODP	5	35 XXX	SP	CRE	ID	TD		12/1/2032
2020 PO9606641147	F	4	40 BRN	SP	CRE		V		12/2/2032
2020 PO9586941195a	F	5	30 KOP	SP	CRE		V		12/3/2032
2020 PO9586941195	ODP	4	45 XXX	SP	A	ED,ID	TD		12/4/2032
2020 PO4087283128	LGE	4	30 BRN	SP	CRE	ED,ID	TD		12/5/2032
2020 PO9533035007	ODP	3	45 BRN	SP	CCA		V		12/6/2032
2020 PO9544835167	ODP	3	45 BRN	SP	CCA		V		12/7/2032
2020 PO9557235474	ODP	2	55 BRN	SP	CCA		V		12/8/2032
2020 PO9552435894	ODP	2	50 BRN	SP	CCA		V		12/9/2032
2020 PO9546236101	ODP	2	50 BRN	SP	CCA		V		12/10/2032
2020 PO9531536346	ODP	3	45 BRN	SP	CCA		V		12/11/2032
2020 PO9579035710	ODP	4	45 BRN	SP	CRE		V		12/12/2032
2020 PO9563435571	ODP	6	30 BRN	SP	CCA		V		12/13/2032
2020 PO9569635648	ODP	4	45 BRN	SP	CRE		V		12/14/2032
2020 PO9563335525	ODP	4	45 BRN	SP	CRE		V		12/15/2032
2020 PO9570835719	ODP	5	30 BRN	SP	CRE		V		12/16/2032
2020 PO4087183134	LGE	3	45 BRN	SP	S		V		12/17/2032
2020 PO3902411025	KU	3	45 BRO	SP	CCA		V		12/18/2032
2020 PO3899311172	KU	3	45 BRO	SP	CCA		V		12/19/2032
2020 PO4085683134	LGE	3	55 BRN	SP	CRE		V		12/20/2032
2020 PO4086283128	LGE	3	45 BRN	SP	S		V		12/21/2032
2020 PO4442411331	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX	12/22/2032
2020 PO4432311393	F	4	40 ACE	SP	CRE		V		12/23/2032
2020 PO3896311339	KU	3	45 BRO	SP	CCA		V		12/24/2032
2020 PO3899211400	KU	2	45 BRO	SP	CRE	ID,IP	BD		12/25/2032
2020 PO3906311572	KU	4	40 BRO	SP	CRE		V		12/26/2032
2020 PO3914411763	KU	4	40 BRO	SP	CCA		V		12/27/2032
2020 PO4089483135	LGE	3	45 BRN	SP	A	ED,ID	TD		12/28/2032
2020 PO9601341248	F	6	30 XXX	SP	CRE		V		12/29/2032
2020 PO9594741115	ODP	5	30 XXX	SP	CCA		V		12/30/2032
2020 PO9590141319	ODP	6	30 XXX	SP	CRE	ED,ID	TD		12/31/2032
2020 PO4419711396	F	4	40 ACE	SP	CRE	ED,ID	V		1/1/2033
2020 PO4088183135-A	LGE	4	40 BRN	SP	A	ED,ID	BD		1/2/2033
2020 PO4475036017	KU	5	35 ACE	SP	CRE		V		1/3/2033
2020 PO4519909234	F	4	40 ACE	SP	CRE	ED,HH,ID,IP,RB	BX	RP1	1/4/2033
2020 PO4088183135	LGE	3	45 BRN	SP	CCA		V		1/5/2033
2020 PO4089583129	LGE	4	35 BRN	SP	CCA		V		1/6/2033
2020 PO4088683134	LGE	4	40 BRN	SP	S		V		1/7/2033
2020 PO4088783125	LGE	7	25 BRN	SP	CRE		V		1/8/2033
2020 PO4088283126	LGE	3	45 BRN	SP	S		V		1/9/2033
2020 PO1374030973	ODP	4	40 BRN	SP	CRE	ID	TD		1/10/2033

2020 PO1370230769	ODP	4	40 BRN	SP	CRE		V			1/11/2033
2020 PO1371730615	ODP	4	40 BRN	SP	CCA		V			1/12/2033
2020 PO4089383139	LGE	4	40 BRN	SP	S		V			1/13/2033
2020 PO9538036368	ODP	5	35 BRN	SP	CCA		V			1/14/2033
2020 PO9505735899A	ODP	5	35 BRN	SP	CCA		V			1/15/2033
2020 PO9527335996	ODP	4	40 BRN	SP	CCA		V			1/16/2033
2020 PO9497236158	ODP	4	40 BRN	SP	CCA		V			1/17/2033
2020 PO9505735899	ODP	4	40 BRN	SP	CCA		V			1/18/2033
2020 PO1567320208	F	4	40 XXX	SP	A		V			1/19/2033
2020 PO1550920489	F	4	40 XXX	SP	A		V			1/20/2033
2020 PO1548120329	ODP	5	35 XXX	SP	CRE	ED,ID,SRC		TX	RR	1/21/2033
2020 PO1591320055	ODP	5	35 XXX	SP	CCA		V			1/22/2033
2020 PO1608120123	ODP	4	40 XXX	SP	CRE	ID			TD	1/23/2033
2020 PO1575220010	ODP	4	40 XXX	SP	CCA		V			1/24/2033
2020 PO4088783152	LGE	4	35 BRN	SP	CCA		V			1/25/2033
2020 PO4088483158	LGE	4	40 BRN	SP	S		V			1/26/2033
2020 PO1312230467	ODP	4	40 BRN	SP	CRE	ID			TD	1/27/2033
2020 PO1326030381	ODP	5	35 BRN	SP	CRE	ID			TD	1/28/2033
2020 PO9584941695	ODP	4	40 XXX	SP	CCA		V			1/29/2033
2020 PO9580742088	ODP	4	40 XXX	SP	CRE	ED,ID			TD	1/30/2033
2020 PO4675487823	LGE	3	45 BRO	SP	A	ED,ID			BD	1/31/2033
2020 LGE	LGE	2	50 BRO	SP	CCA		V			2/1/2033
2020 PO4663588031	LGE	3	45 BRN	SP	S		V			2/2/2033
2020 PO4665888046	LGE	3	45 BRN	SP	S		V			2/3/2033
2020 PO4675487835	LGE	4	40 BRO	SP	P	ED,ID			BD	2/4/2033
2020 PO4665488055	LGE	4	40 BRN	SP	CRE	ED,ID			BD	2/5/2033
2020 PO4665888058	F	5	35 BRN	SP	CCA		V			2/6/2033
2020 PO4674287855	LGE	3	45 BRO	SP	CRE	ED,ID			BD	2/7/2033
2020 PO4674187857	LGE	3	45 BRO	SP	CRE	ED,ID			BD	2/8/2033
2020 PO4666988055	LGE	4	40 BRN	SP	CRE	ED,ID			BD	2/9/2033
2020 PO4676187842	LGE	4	30 BRO	SP	CRE	ED,ID			TD	2/10/2033
2020 PO4676687823	LGE	4	30 BRO	SP	P	ED,ID			TD	2/11/2033
2020 PO4669588073	LGE	4	40 BRN	SP	CRE	ED,ID			TD	2/12/2033
2020 PO4668388064	LGE	4	40 BRN	SP	A	ED,ID			BD	2/13/2033
2020 PO4667288066	F	4	35 BRN	SP	CRE		V			2/14/2033
2020 PO4667788089	LGE	1	50 BRN	SP	S		V			2/15/2033
2020 PO3779593582	LGE	3	45 BRN	SP	S		V			2/16/2033
2020 PO4668688075	F	4	40 BRN	SP	CRE		V			2/17/2033
2020 PO1912033198	ODP	5	35 UNK	SP	CRE	ED,ID,SRS			TD	2/18/2033
2020 PO4670888082	LGE	4	40 BRN	SP	CRE	ED,ID			BD	2/19/2033
2020 PO4672488072	LGE	3	45 BRN	SP	S		V			2/20/2033
2020 PO4669588100	LGE	4	35 BRN	SP	CRE	ED,ID			BD	2/21/2033
2020 PO4670288091	LGE	4	35 BRN	SP	CRE	ED,ID			TD	2/22/2033
2020 PO2536546250	ODP	4	45 KOP	SP	A	ED,ID			TD	2/23/2033
2020 PO2550946335	ODP	5	35 KOP	DF	CRE	ED,ID,IP			TD	2/24/2033
2020 25694-46392A	ODP	4	45 KOP	SP	S		V			2/25/2033
2020 PO2554246561	ODP	5	35 KOP	SP	CRE	ED,ID			TD	2/26/2033

2020 PO2565246437	F	4	40 KOP	SP	CRE		V	2/27/2033
2020 PO2569446392	ODP	4	40 KOP	SP	CRE	ED,ID	TD	2/28/2033
2020 26404-46665A	ODP	6	30 KOP	SP	S		V	3/1/2033
2020 PO7877440592	LGE	3	45 BRO	SP	P	ED	TD	3/2/2033
2020 PO4672988102	LGE	4	30 BRN	SP	CRE	ED,ID	TD	3/3/2033
2020 PO7927040815	LGE	3	45 BRO	SP	CCA		V	3/4/2033
2020 PO7921140773	LGE	1	50 BRO	SP	CCA		V	3/5/2033
2020 PO7891740701	LGE	1	50 BRO	SP	CCA		V	3/6/2033
2020 PO7861240468	LGE	3	45 BRO	SP	CCA		V	3/7/2033
2020 PO7844940345	LGE	3	45 BRO	SP	CCA		V	3/8/2033
2020 PO7886039986	LGE	4	35 BRO	SP	CCA		V	3/9/2033
2020 PO7933540353	LGE	4	35 BRO	SP	CCA		V	3/10/2033
2020 PO7862339802	LGE	4	35 BRO	SP	CCA		V	3/11/2033
2020 PO7921640261	LGE	4	35 BRO	SP	CCA		V	3/12/2033
2020 PO5835113714	KU	5	40 XXX	SP	CRE	ED,ID	TD	3/13/2033
2020 PO5809814052	KU	4	40 XXX	SP	CRE	ED,ID	TD	3/14/2033
2020 PO5797914232	KU	4	40 XXX	SP	CRE	ED,ID	TD	3/15/2033
2020 PO3592989686	KU	4	40 XXX	SP	CRE	ID	TD	3/16/2033
2020 PO3606489542	F	4	40 XXX	SP	A		V	3/17/2033
2020 PO3595889460	F	4	40 XXX	SP	A		V	3/18/2033
2020 PO3642489811	F	4	40 XXX	SP	A		V	3/19/2033
2020 PO3710590525	F	4	40 XXX	SP	CRE		V	3/20/2033
2020 PO3707690564	F	6	30 XXX	SP	CRE		V	3/21/2033
2020 PO3699490454	KU	4	45 XXX	SP	CRE	ID	BD	3/22/2033
2020 PO4660088105	LGE	4	40 BRN	SP	A	ED,ID	BD	3/23/2033
2020 PO4663188128	LGE	4	40 BRN	SP	CCA		V	3/24/2033
2020 PO4662588124	LGE	6	25 BRN	SP	A	ED,ID	BD	3/25/2033
2020 PO4641789094	LGE	4	40 BRO	SP	CCA		V	3/26/2033
2020 PO4614587872	F	4	40 BRO	SP	CRE		V	3/27/2033
2020 PO7923539600	F	4	40 OTH	SP	CRE		V	3/28/2033
2020 PO7866139661	F	4	40 OTH	SP	CRE		V	3/29/2033
2020 PO7839839694	F	4	40 OTH	SP	CRE	EP,ID,RB	VX	3/30/2033
2020 PO7724239620	F	4	40 OTH	SP	CRE	HH	BD	3/31/2033
2020 PO7953639622	F	4	40 OTH	SP	CRE		V	4/1/2033
2020 PO7895839628	F	4	40 OTH	SP	CRE		V	4/2/2033
2020 PO7810539729	F	4	40 OTH	SP	CRE		V	4/3/2033
2020 PO7972339610	KU	4	40 OTH	SP	CCA		V	4/4/2033
2020 PO4663788108	LGE	6	25 BRN	SP	A	ED,ID	TD	4/5/2033
2020 PO4664288111	LGE	4	35 BRN	SP	A	ED,HH,ID	BX	4/6/2033
2020 PO4663688120	LGE	4	35 BRN	SP	A	ED,ID	BD	4/7/2033
2020 PO4663088116	LGE	6	25 BRN	SP	A	ED,ID	TD	4/8/2033
2020 PO4615387859	F	4	40 BRO	SP	CRE		V	4/9/2033
2020 PO4616187847	F	4	40 BRO	SP	CRE		V	4/10/2033
2020 PO3715090685	KU	6	30 XXX	SP	CRE	ID	TD	4/11/2033
2020 PO3717290623	F	5	35 XXX	SP	A		V	4/12/2033
2020 PO3718790579	KU	4	40 XXX	SP	CRE	ID	TD	4/13/2033
2020 PO4684088683	LGE	4	40 BRO	SP	CCA		V	4/14/2033

2020 PO4616887835	LGE	4	40 BRO	SP	CRE		V	4/15/2033
2020 PO4616987836	F	4	45 BRO	SP	CRE		V	4/16/2033
2020 PO4617787821	LGE	3	45 BRO	SP	A	ED,ID	TD	4/17/2033
2020 PO4603987982	F	4	40 BRO	SP	CRE		V	4/18/2033
2020 PO4604487974	F	3	45 BRO	SP	A		V	4/19/2033
2020 PO4602987965	F	3	45 BRO	SP	A		V	4/20/2033
2020 PO4603287992	F	4	40 BRO	SP	CRE		V	4/21/2033
2020 PO4662288109	LGE	4	25 BRN	SP	A	ED,ID	TD	4/22/2033
2020 PO5780514490	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	4/23/2033
2020 PO4671388962	LGE	4	40 BRO	SP	CCA		V	4/24/2033
2020 PO3725990853	KU	5	35 XXX	SP	CRE	ID	BD	4/25/2033
2020 PO3722790813	F	4	40 XXX	SP	CRE		V	4/26/2033
2020 PO3729790705	F	4	40 XXX	SP	CCA		V	4/27/2033
2020 PO3732290666	F	4	40 XXX	SP	CRE		V	4/28/2033
2020 PO4674488981	LGE	4	30 BRO	SP	CCA		V	4/29/2033
2020 PO4675088985	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/30/2033
2020 7549638791A	KU	6	30 OTH	SP	CRE	ED,ID,SRS	TD	5/1/2033
2020 PO7529438911	F	4	40 OTH	SP	P		V	5/2/2033
2020 PO7549638791	KU	6	30 OTH	SP	CRE	ID	TD	5/3/2033
2020 PO7557938665	KU	4	40 OTH	SP	CRE	ID	TD	5/4/2033
2020 PO7539238812	KU	6	30 OTH	SP	CCA	ED,SRS	TD	5/5/2033
2020 PO7532038707	KU	4	45 OTH	SP	CCA	ED,SRS	TD	5/6/2033
2020 PO3743190675	KU	6	30 XXX	SP	CCA		V	5/7/2033
2020 PO3740290719	KU	4	40 XXX	SP	CRE	ID	TD	5/8/2033
2020 PO3749090777	F	4	40 XXX	SP	CRE		V	5/9/2033
2020 PO3757590835	KU	4	45 XXX	SP	CRE	ID	BD	5/10/2033
2020 PO3762390867	KU	4	45 XXX	SP	CCA		V	5/11/2033
2020 PO3771390926	KU	4	45 XXX	SP	CRE	ID	BD	5/12/2033
2020 PO5767214816	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	5/13/2033
2020 PO4661188101	LGE	4	30 BRN	SP	A	ED,ID	TD	5/14/2033
2020 PO4660688097	LGE	4	35 BRN	SP	A	ED,ID	TD	5/15/2033
2020 PO4661188089	LGE	4	40 BRN	SP	A	ED,ID	TD	5/16/2033
2020 PO9203738567	ODP	5	35 BRO	SP	CRE	ID	BD	5/17/2033
2020 PO4674688991	LGE	4	40 BRO	SP	CCA		V	5/18/2033
2020 PO5753415096	KU	4	40 XXX	SP	CRE	ED,ID	TD	5/19/2033
2020 PO3951401208	LGE	4	30 BRO	SP	CCA		V	5/20/2033
2020 PO4604987965	F	4	40 BRO	SP	CRE		V	5/21/2033
2020 PO4605587956	F	4	40 BRO	SP	CRE		V	5/22/2033
2020 PO4605587981	F	4	35 BRO	SP	CCA		V	5/23/2033
2020 PO4586987989	LGE	3	45 BRO	SP	A	ED,ID	TD	5/24/2033
2020 PO4587487981	LGE	4	40 BRO	SP	CRE	ED,ID	BD	5/25/2033
2020 PO4587987972	LGE	4	40 BRO	SP	A	ED,ID	TD	5/26/2033
2020 PO4589187955	LGE	4	40 BRO	SP	CRE		V	5/27/2033
2020 PO4685788843	LGE	3	45 BRO	SP	P	ED	T	5/28/2033
2020 PO3789190859	KU	5	35 XXX	SP	CCA	ED	T	5/29/2033
2020 PO3796190898	KU	5	35 XXX	SP	CCA	ED	T	5/30/2033
2020 PO3781090988	F	4	40 XXX	SP	CRE		V	5/31/2033

2020 PO3793491071	KU	3	45 XXX	SP	CCA		V		6/1/2033
2020 PO5863313376	KU	6	30 XXX	SP	CCA		V		6/2/2033
2020 PO5882913309	KU	4	40 XXX	SP	CRE	ED,ID	TD		6/3/2033
2020 PO5906013421	KU	5	45 XXX	SP	CRE	ED,ID	TD		6/4/2033
2020 PO7517238923	KU	5	30 OTH	SP	CRE	ED,ID,SRS	TD		6/5/2033
2020 PO5884513532	KU	5	35 XXX	SP	CRE	ED,ID	BX	RP2	6/6/2033
2020 PO7507838990	KU	4	40 OTH	SP	CRE	ID	TD		6/7/2033
2020 PO7512939130	KU	4	40 OTH	SP	CRE	ID	TD		6/8/2033
2020 PO4686788835	LGE	4	30 BRO	SP	CRE	ED,ID,IP,SRS	TD		6/9/2033
2020 PO4686488832	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		6/10/2033
2020 PO4687388819	LGE	3	45 BRO	SP	CCA		V		6/11/2033
2020 PO8605036366	ODP	5	35 BRO	SP	CRE	ID	BD		6/12/2033
2020 PO8605036366	ODP	5	35 BRO	SP	CRE	ID	BD		6/13/2033
2020 PO8582836044	ODP	5	35 BRO	DF	CRE	ID	BD		6/14/2033
2020 PO8591535814	F	4	40 BRO	SP	P		V		6/15/2033
2020 PO8591535814A	ODP	6	30 BRO	SP	P		V		6/16/2033
2020 PO8569935757	ODP	5	35 BRO	DF	CRE	ID	BD		6/17/2033
2020 PO8541435656	ODP	5	30 BRO	SP	S		V		6/18/2033
2020 PO8520135591	ODP	5	35 BRO	DF	CRE	ID	BD		6/19/2033
2020 PO4656688216	LGE	4	30 BRN	SP	S		V		6/20/2033
2020 PO4657988207	LGE	4	40 BRN	SP	CCA		V		6/21/2033
2020 PO4645389204	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		6/22/2033
2020 PO4645189189	LGE	4	35 BRO	SP	A	ED,ID,IP	TD		6/23/2033
2020 PO5728110947	KU	2	50 XXX	SP	CCA		V		6/24/2033
2020 PO5729010964	KU	4	20 XXX	SP	CCA		V		6/25/2033
2020 PO5730210988	KU	2	50 XXX	SP	CCA		V		6/26/2033
2020 PO5745011307	KU	5	45 XXX	SP	CRE	ED,ID	TD		6/27/2033
2020 PO7573038832	KU	4	40 OTH	SP	CRE	ID	TD		6/28/2033
2020 PO7579938620	KU	4	40 OTH	SP	CRE	ID	TD		6/29/2033
2020 PO7568338534	KU	4	40 OTH	SP	CRE	ID	TD		6/30/2033
2020 PO5756011546	KU	5	45 XXX	SP	CRE	ED,ID	TD		7/1/2033
2020 PO5765611765	KU	4	50 XXX	SP	CRE	ED,ID	TD		7/2/2033
2020 PO5765012115	KU	5	35 XXX	SP	CRE	ID,RB	X	RP1	7/3/2033
2020 PO4743887732	LGE	4	40 BRO	SP	A	ED,ID	TD		7/4/2033
2020 PO4743387753	LGE	4	40 BRO	SP	A	ED,ID	TD		7/5/2033
2020 PO4743287760	LGE	4	40 BRO	SP	A	ED,ID	TD		7/6/2033
2020 PO4743487785-A	LGE	4	40 BRO	SP	A	ED,ID	TD		7/7/2033
2020 PO4743487785	LGE	4	40 BRO	SP	CRE	ED,HH,ID,RB	BX	RP2	7/8/2033
2020 PO4743487785a	LGE	4	40 BRO	SP	P	ED,ID	T		7/9/2033
2020 PO4743687812	LGE	4	40 BRO	SP	CRE	ED,ID	BD		7/10/2033
2020 PO4744787885	LGE	4	30 BRO	SP	P	ED,ID	TD		7/11/2033
2020 PO4612387789	F	4	40 BRO	SP	CRE		V		7/12/2033
2020 PO7639337874	KU	5	35 OTH	SP	CRE	ED,EP,ID	X	RP3	7/13/2033
2020 PO7606238293	KU	5	35 OTH	SP	CRE	ID	TD		7/14/2033
2020 PO7586138408	KU	4	40 OTH	SP	CRE	ED,ID,IP	TD		7/15/2033
2020 PO7583038364	KU	6	30 OTH	SP	CRE	ID	TD		7/16/2033
2020 PO7626938174	KU	5	35 OTH	SP	CRE	ID	TD		7/17/2033

2020 PO4657388203	LGE	6	25 BRN	SP	CRE	ED,ID	TD		7/18/2033
2020 PO4654788186	LGE	4	35 BRN	SP	CRE	ED,ID,RB	X	PX	7/19/2033
2020 PO4657988194	LGE	6	25 BRN	SP	CRE	ED,ID,IP	BD		7/20/2033
2020 PO4655388177	LGE	4	40 BRN	SP	CCA		V		7/21/2033
2020 PO4648889197	LGE	3	45 BRO	SP	P	ED	T		7/22/2033
2020 PO4647089186	LGE	3	45 BRO	SP	P	ED	T		7/23/2033
2020 PO5757612047	KU	4	40 XXX	SP	CCA		V		7/24/2033
2020 PO5740012153	KU	4	40 XXX	SP	CCA		V		7/25/2033
2020 PO5722212279	KU	4	40 XXX	SP	CCA		V		7/26/2033
2020 PO5734412494	KU	4	40 XXX	SP	CCA		V		7/27/2033
2020 PO7649038047	KU	4	40 OTH	SP	CRE	ID	TD		7/28/2033
2020 PO7671137924	KU	4	40 OTH	SP	CRE	ID	TD		7/29/2033
2020 PO7694137790	KU	5	35 OTH	SP	CRE	ID	TD		7/30/2033
2020 PO5775311963	KU	4	40 XXX	SP	CRE	ED,ID	TD		7/31/2033
2020 PO5789612199	KU	4	40 XXX	SP	CRE	ED,ID	TD		8/1/2033
2020 PO4644889175	LGE	4	30 BRO	SP	CCA		V		8/2/2033
2020 PO4645389174	LGE	3	45 BRO	SP	P	ED	T		8/3/2033
2020 PO7714337661	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD		8/4/2033
2020 PO7739137520	KU	4	40 OTH	SP	CRE	ID	TD		8/5/2033
2020 PO7695037621	KU	5	35 OTH	SP	CRE	ID	TD		8/6/2033
2020 PO5807112394	KU	4	40 XXX	SP	CRE	ED,ID	TD		8/7/2033
2020 PO5815312489	KU	4	40 XXX	SP	CRE	ED,ID	TD		8/8/2033
2020 PO4641089105	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		8/9/2033
2020 PO4640689102	LGE	5	25 BRO	SP	A	ED,ID,IP	TD		8/10/2033
2020 PO4640889098	F	4	35 BRO	SP	CCA		V		8/11/2033
2020 PO5826512616	KU	4	40 XXX	SP	CRE	ED,ID	TD		8/12/2033
2020 PO5825112742	KU	2	55 XXX	SP	P		V		8/13/2033
2020 PO5828512783	KU	3	50 XXX	SP	CRE		V		8/14/2033
2020 PO5872712308	KU	3	50 XXX	ST	CRE		V		8/15/2033
2020 PO5876512347	KU	3	50 XXX	ST	CRE		V		8/16/2033
2020 PO7767137287	KU	5	35 OTH	SP	CRE	ID	TD		8/17/2033
2020 PO7297038077	KU	6	30 OTH	SP	CCA		V		8/18/2033
2020 PO7297837843	KU	4	40 OTH	SP	CCA		V		8/19/2033
2020 PO7283537805	KU	6	30 OTH	SP	CCA		V		8/20/2033
2020 PO728537903	KU	6	30 OTH	SP	CCA	ED,SRS	TD		8/21/2033
2020 PO4705488278-A	LGE	4	35 BRO	SP	P	ED,ID	TD		8/22/2033
2020 PO4706288257	LGE	H1	70 BRO	ST	CRE		V		8/23/2033
2020 PO4706088262	LGE	3	45 BRO	SP	CCA		V		8/24/2033
2020 PO4161595377	LGE	3	45 BRO	SP	CCA		V		8/25/2033
2020 PO4705888268	LGE	1	70 BRO	SP	CRE		V		8/26/2033
2020 PO4705088275	LGE	3	45 BRO	SP	CCA		V		8/27/2033
2020 PO4704588263	LGE	UNK	35 BRO	SP	CRE		V		8/28/2033
2020 PO4704388270	LGE	UNK	45 BRO	SP	CRE		V		8/29/2033
2020 PO4704488276	LGE	4	35 BRO	SP	CRE		V		8/30/2033
2020 PO4702788255	LGE	3	45 BRO	SP	CRE	ED,ID	TD		8/31/2033
2020 PO4125595312	LGE	3	45 BRO	SP	CCA		V		9/1/2033
2020 PO4672688134	LGE	6	25 BRN	SP	CRE	ED,ID	TD		9/2/2033

2020 PO4747687517	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	9/3/2033
2020 PO4675188143	LGE	4	30 BRN	SP	A	ED,ID	TD	9/4/2033
2020 PO4674288136	LGE	4	35 BRN	SP	A		V	9/5/2033
2020 PO4669488111	LGE	4	30 BRN	SP	A	ED,ID	BD	9/6/2033
2020 PO4650489164	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/7/2033
2020 PO4667788137	LGE	4	30 BRN	SP	A	ED,ID	BD	9/8/2033
2020 PO4670388149	LGE	4	30 BRN	SP	A	ED,HH,ID,RB	BX PX	9/9/2033
2020 PO4666688154	LGE	4	30 BRN	SP	A		V	9/10/2033
2020 PO471208793-A	LGE	4	35 BRO	SP	A	ED,ID	TD	9/11/2033
2020 PO4707987964	LGE	4	40 BRO	SP	A	ED,ID	TD	9/12/2033
2020 PO4709787970	LGE	4	40 BRO	SP	A	ED,ID	TD	9/13/2033
2020 PO4710387974	LGE	UNK	65 BRO	SP	CRE		V	9/14/2033
2020 PO4708787963	LGE	UNK	65 BRO	SP	CRE		V	9/15/2033
2020 PO4707587955	LGE	4	40 BRO	SP	CRE	ED,ID	BD	9/16/2033
2020 PO4706787950	LGE	UNK	70 BRO	SP	CRE		V	9/17/2033
2020 PO4706287946	LGE	3	45 BRO	SP	CRE	ED,ID	TD	9/18/2033
2020 PO4649289155	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/19/2033
2020 PO4666288167	LGE	3	45 BRN	SP	S		V	9/20/2033
2020 PO4667288175	LGE	3	45 BRN	SP	CCA		V	9/21/2033
2020 PO4662388251	LGE	4	35 BRN	SP	CRE	ED,ID	TD	9/22/2033
2020 PO4660188284	LGE	4	35 BRN	SP	CCA		V	9/23/2033
2020 PO4662088362	LGE	4	40 BRN	SP	A	ED,ID	BD	9/24/2033
2020 PO4661088355	LGE	4	40 BRN	SP	A	ED,ID	BD	9/25/2033
2020 PO4660288349	LGE	4	40 BRN	SP	A	ED,ID	TD	9/26/2033
2020 PO4660488345	LGE	4	35 BRN	SP	CCA		V	9/27/2033
2020 PO4654689198	LGE	3	40 BRO	SP	A	ID,IP	BD	9/28/2033
2020 PO4648489149	LGE	3	40 BRO	SP	A	ID,IP	BD	9/29/2033
2020 PO4655488305	LGE	4	30 BRN	SP	S		V	9/30/2033
2020 PO4655988296	LGE	4	30 BRN	SP	S		T	10/1/2033
2020 PO4691587951	LGE	4	40 BRO	SP	P	ED,ID	TD	10/2/2033
2020 PO4656488287	LGE	6	25 BRN	SP	CRE	ED,ID	TD	10/3/2033
2020 PO4657088280	LGE	4	25 BRN	SP	A	ED,ID	BD	10/4/2033
2020 PO4689287943	F	4	40 BRO	SP	CRE		V	10/5/2033
2020 PO4691087941	F	4	40 BRO	SP	CRE		V	10/6/2033
2020 PO4692087940	F	4	35 BRO	ST	CRE		V	10/7/2033
2020 PO4692187948	LGE	2	75 BRO	SP	CRE		V	10/8/2033
2020 PO4692887947	LGE	UNK	55 BRO	SP	CRE	ED,ID	BD	10/9/2033
2020 PO4693287947	LGE	3	55 BRO	SP	CRE	ED,ID	BD	10/10/2033
2020 PO4694187946	LGE	UNK	75 BRO	SP	CRE		V	10/11/2033
2020 PO4695087945	LGE	UNK	55 BRO	SP	CRE	ED,ID	BD	10/12/2033
2020 PO4695887944	LGE	UNK	80 BRO	SP	CRE	ED,ID	BD	10/13/2033
2020 PO4648189137	LGE	4	35 BRO	SP	A	ED	TD	10/14/2033
2020 PO4646189130	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	10/15/2033
2020 PO4646689124	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	10/16/2033
2020 PO3873790611	F	4	40 XXX	SP	CRE		V	10/17/2033
2020 PO3953489533	KU	4	40 XXX	SP	CRE		V	10/18/2033
2020 PO4647689142	LGE	4	40 BRO	SP	A	ID,IP	BD	10/19/2033

2020 PO3851790711	KU	6	30 XXX	SP	CCA		V		10/20/2033
2020 PO4657588271	LGE	6	25 BRN	SP	CRE	ED,ID	BD		10/21/2033
2020 PO4658188263	LGE	4	40 BRN	SP	CCA		V		10/22/2033
2020 PO4658688254	LGE	4	30 BRN	SP	A	ED,ID	TD		10/23/2033
2020 PO3860290916	KU	5	35 XXX	SP	CRE	ID	BD		10/24/2033
2020 PO3838290968	KU	5	35 XXX	SP	CCA		V		10/25/2033
2020 PO3843290846	F	5	30 XXX	SP	A		V		10/26/2033
2020 PO3831690768	F	5	30 XXX	SP	A		V		10/27/2033
2020 PO4695087934	F	3	45 BRO	SP	CRE		V		10/28/2033
2020 PO4696387935	F	3	45 BRO	SP	CRE		V		10/29/2033
2020 PO4697687932	F	3	45 BRO	SP	CRE		V		10/30/2033
2020 PO4698187933	F	3	45 BRO	SP	CRE		V		10/31/2033
2020 PO4703087928	F	3	50 BRO	SP	CRE		V		11/1/2033
2020 PO4701987929	F	4	40 BRO	SP	P		V		11/2/2033
2020 PO4700387931	F	4	40 BRO	SP	P		V		11/3/2033
2020 PO4698887916	LGE	4	35 BRO	SP	CRE	ED,ID,RB	TX	RR	11/4/2033
2020 PO4698987931	F	4	35 BRO	SP	CRE		V		11/5/2033
2020 PO4699087922	LGE	4	40 BRO	SP	CRE	ED,ID	TD		11/6/2033
2020 PO4699987930	LGE	3	45 BRO	SP	A	ED,ID	BD		11/7/2033
2020 PO4659188247	LGE	4	25 BRN	SP	CRE	ED,ID	BD		11/8/2033
2020 PO3822190703	F	5	30 XXX	SP	A		V		11/9/2033
2020 PO3768290120	F	4	40 XXX	SP	CRE		V		11/10/2033
2020 PO3772490056	F	4	40 XXX	SP	CRE		V		11/11/2033
2020 PO4649289091	LGE	4	35 BRO	SP	CCA		V		11/12/2033
2020 PO4648889096	LGE	5	25 BRO	SP	P	ED	T		11/13/2033
2020 PO3782490123	KU	4	45 XXX	SP	CRE	ID	BD		11/14/2033
2020 PO3789790172	KU	4	45 XXX	SP	CRE	ID	BD		11/15/2033
2020 PO3791890186	KU	3	45 BRN	SP	CCA		V		11/16/2033
2020 PO3793590278	KU	5	30 BRN	SP	CCA		V		11/17/2033
2020 PO3796290215	KU	2	50 BRN	SP	CCA		V		11/18/2033
2020 PO4647689078	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		11/19/2033
2020 PO3556903516	LGE	4	35 BRO	SP	P	ED	T		11/20/2033
2020 PO4704111558	KU	4	40 ACE	SP	CRE	ED,ID	TD		11/21/2033
2020 PO4762988792	LGE	4	40 BRN	SP	CRE	ED,ID	TD		11/22/2033
2020 PO5016102199	KU	3	45 BRO	SP	CCA		V		11/23/2033
2020 PO5005602226	KU	6	30 KOP	SP	CRE	ED,ID	TD		11/24/2033
2020 PO3935209705	KU	3	45 BRO	SP	CRE	ID,IP	BD		11/25/2033
2020 PO3928109911	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		11/26/2033
2020 PO4684111381	KU	4	40 ACE	SP	CRE	ED,ID	BD		11/27/2033
2020 PO4760388772	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD		11/28/2033
2020 PO4702211524	F	4	40 ACE	SP	CCA		V		11/29/2033
2020 PO4997702026	KU	4	40 KOP	SP	CRE	ED,ID	TD		11/30/2033
2020 PO3893308849	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD		12/1/2033
2020 PO4638311738	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD		12/2/2033
2020 PO4761688781	LGE	3	45 BRN	SP	CCA		V		12/3/2033
2020 PO4763588782	LGE	4	40 BRN	SP	CRE	ED,ID	TD		12/4/2033
2020 PO4764088772	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD		12/5/2033

2020 PO5010402071	KU	4	40 KOP	SP	CRE	ED,ID	TD		12/6/2033
2020 PO4984601980	KU	4	45 KOP	SP	CRE	ED,ID	TD		12/7/2033
2020 PO4660311500	KU	5	35 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX	12/8/2033
2020 PO4764488763	LGE	4	40 BRN	SP	CRE	ED,ID	TD		12/9/2033
2020 PO4764188755	LGE	4	40 BRN	SP	CRE	ED,ID	TD		12/10/2033
2020 PO4716088985	LGE	3	45 BRO	SP	CRE	ED,ID	TD		12/11/2033
2020 PO2226824398	F	4	40 XXX	SP	A		V		12/12/2033
2020 PO2219724590	F	4	40 XXX	SP	A		V		12/13/2033
2020 PO2216024687	F	4	45 XXX	SP	A		V		12/14/2033
2020 PO2226822406	ODP	4	45 XXX	SP	CCA		V		12/15/2033
2020 PO2193022527	ODP	5	35 XXX	SP	CRE	ID	TD		12/16/2033
2020 PO2211322879	ODP	4	40 XXX	SP	CRE	ID	TD		12/17/2033
2020 PO2232922871	ODP	6	30 XXX	SP	CRE	ID	TD		12/18/2033
2020 PO2235822991	ODP	4	40 XXX	SP	CRE	ID	TD		12/19/2033
2020 PO2241323484	F	4	40 XXX	SP	CRE		V		12/20/2033
2020 PO2244823676	ODP	4	40 XXX	SP	CRE	ID	TD		12/21/2033
2020 PO2254823948	ODP	4	40 XXX	SP	CRE	ID	TD		12/22/2033
2020 PO2272023707	ODP	4	40 XXX	SP	CCA		V		12/23/2033
2020 PO2236923884	ODP	4	45 XXX	SP	CRE	ID	BD		12/24/2033
2020 PO1806922672	ODP	5	35 XXX	SP	CCA		V		12/25/2033
2020 PO4664211460	KU	5	35 ACE	SP	CRE	ED,ID	BD		12/26/2033
2020 PO4662511529	KU	4	40 ACE	SP	CRE	ED,ID	TD		12/27/2033
2020 PO3896508843	KU	4	45 BRO	SP	CRE	ID,IP	BD		12/28/2033
2020 PO4971001933	KU	4	40 KOP	SP	CRE	ED,ID	TD		12/29/2033
2020 PO4966802006	KU	6	30 KOP	SP	CRE	ED,ID	TD		12/30/2033
2020 PO4962202037	KU	4	40 KOP	SP	CCA		V		12/31/2033
2020 PO3903409000	KU	4	40 BRO	SP	CRE	ID,IP	BD		1/1/2034
2020 PO4763288751	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD		1/2/2034
2020 PO4762488752	LGE	4	40 BRN	SP	CRE	ED,ID	TD		1/3/2034
2020 PO4687111436	KU	4	40 ACE	SP	CRE	ED,ID	BD		1/4/2034
2020 PO3911609126	KU	4	40 BRO	SP	CRE	ID,IP	BD		1/5/2034
2020 PO3920209256	KU	4	40 BRO	SP	CRE	ID,IP	BD		1/6/2034
2020 PO3948809406	KU	3	45 BRO	SP	CRE	ID,IP	BD		1/7/2034
2020 PO4761388747	LGE	4	40 BRN	SP	CRE	ED,ID	BD		1/8/2034
2020 PO4759988739	LGE	4	40 BRN	SP	CRE	ED,ID	TD		1/9/2034
2020 PO4774488730	LGE	4	40 BRN	SP	CRE	HH,ID	BD		1/10/2034
2020 PO3940509561	KU	3	45 BRO	SP	CRE	ID,IP	BD		1/11/2034
2020 PO4717588994	LGE	3	45 BRO	SP	P	ED,ID	T		1/12/2034
2020 PO4278602839	LGE	1	50 BRO	SP	CCA		V		1/13/2034
2020 PO4296203048	LGE	4	35 BRO	SP	CCA		V		1/14/2034
2020 PO4295903065	LGE	4	35 BRO	SP	CCA		V		1/15/2034
2020 PO4720189010	LGE	1	50 BRO	SP	CCA		V		1/16/2034
2020 PO4721089015	LGE	3	45 BRO	SP	CRE	ED,ID	BD		1/17/2034
2020 PO4722789026	LGE	3	45 BRO	SP	CRE	ED,ID	BD		1/18/2034
2020 PO4724189034	LGE	3	45 BRO	SP	CRE	ED,ID	TD		1/19/2034
2020 PO4892201450	KU	5	35 KOP	SP	CCA		V		1/20/2034
2020 PO4691111518	KU	4	40 ACE	SP	CRE	ED,ID	TD		1/21/2034

2020 PO3957109264	KU	3	45 BRO	SP	CRE	ID,IP	BD		1/22/2034
2020 PO3965409121	KU	3	45 BRO	SP	CRE	ID,IP	BD		1/23/2034
2020 PO4890601313	KU	5	35 KOP	SP	CCA		V		1/24/2034
2020 PO4886301181	KU	5	35 KOP	SP	CCA		V		1/25/2034
2020 PO4903901269	F	4	40 KOP	SP	P		V		1/26/2034
2020 PO4899101142	F	4	40 KOP	SP	P		V		1/27/2034
2020 PO4666511630	KU	4	40 ACE	SP	CRE	ED,ID	TD		1/28/2034
2020 PO4689911576	KU	4	40 ACE	SP	CRE	ED,ID	BD		1/29/2034
2020 PO4677611625	KU	4	40 ACE	SP	CRE	ED,ID	TD		1/30/2034
2020 PO4674011640	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		1/31/2034
2020 PO4091983153	LGE	3	30 BRO	SP	A	ED,ID,IP	TD		2/1/2034
2020 PO4875301125	KU	5	35 KOP	SP	CCA	ED	TD		2/2/2034
2020 PO4861901195	KU	5	35 KOP	SP	CCA	ED	TD		2/3/2034
2020 PO4847401280	KU	5	35 KOP	SP	CCA	ED	TD		2/4/2034
2020 PO4060809069	KU	3	45 BRO	SP	CCA		V		2/5/2034
2020 PO4003408656	KU	2	60 BRO	SP	CRE	ED,ID,IP	TX	RR	2/6/2034
2020 PO4019408744	KU	3	50 BRO	SP	CRE	ID,IP	BD		2/7/2034
2020 PO4664811678	KU	4	40 ACE	SP	CRE	ED,ID	TD		2/8/2034
2020 PO4657311708	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		2/9/2034
2020 PO4038908884	KU	3	45 BRO	SP	CRE	ID,IP	BD		2/10/2034
2020 PO4768388674	LGE	1	65 BRN	SP	A		V		2/11/2034
2020 PO4770688682	LGE	1	65 BRN	SP	A		V		2/12/2034
2020 PO4091483084	LGE	3	40 BRO	SP	CCA		V		2/13/2034
2020 PO4091383084	LGE	4	40 BRO	SP	CCA		V		2/14/2034
2020 PO4092883103	LGE	3	45 BRO	SP	CCA		V		2/15/2034
2020 PO4768488709	LGE	4	40 BRN	SP	CRE	ED,ID	BD		2/16/2034
2020 PO476888710	LGE	4	40 BRN	SP	CRE	ED,ID	BD		2/17/2034
2020 PO4769388712	LGE	4	40 BRN	SP	CRE	ED,ID	TD		2/18/2034
2020 PO4769688706	LGE	4	30 BRN	SP	P	ED,ID	TD		2/19/2034
2020 PO4770788711	LGE	4	30 BRN	SP	CRE	ED,ID	TD		2/20/2034
2020 PO4770588716	LGE	4	40 BRN	SP	CRE	ED,ID	BD		2/21/2034
2020 PO4642111770	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		2/22/2034
2020 PO4640411821	KU	4	40 ACE	SP	CRE	ED,HH,ID,IP,RB	BX	PX	2/23/2034
2020 PO4645511942	KU	4	40 ACE	SP	P	ED	T		2/24/2034
2020 PO4670911937	KU	5	35 ACE	SP	CRE	ED,ID	TD		2/25/2034
2020 PO4070009514	KU	3	45 BRO	SP	CRE	ID	BD		2/26/2034
2020 PO4074809569	KU	3	45 BRO	SP	CRE	ID,IP	BD		2/27/2034
2020 PO4075909473	KU	3	45 BRO	SP	CRE	ID,IP	BD		2/28/2034
2020 PO4823401673	F	4	40 BRN	SP	CRE		V		3/1/2034
2020 PO4821701448	KU	5	35 BRN	SP	CCA	ED	TD		3/2/2034
2020 PO4827501260	F	4	40 KOP	SP	P		V		3/3/2034
2020 PO4890600923	F	4	40 KOP	SP	P		V		3/4/2034
2020 PO4869501035	F	4	40 KOP	SP	P		V		3/5/2034
2020 PO4852201125	F	4	40 KOP	SP	P		V		3/6/2034
2020 PO4808801355	F	4	45 KOP	SP	CRE		V		3/7/2034
2020 PO4833801345	KU	5	35 KOP	SP	CCA	ED	TD		3/8/2034
2020 PO4816201517	F	4	40 BRN	SP	P		V		3/9/2034

2020 PO4841001186	F	4	40 KOP	SP	P		V		3/10/2034
2020 PO4771688713	LGE	4	30 BRN	SP	CRE	ED,ID	TD		3/11/2034
2020 PO4771488719	LGE	4	40 BRN	SP	CRE	ED,ID	BD		3/12/2034
2020 PO4678412074	KU	4	40 ACE	SP	CRE	ED,ID	BD		3/13/2034
2020 PO4773288726	LGE	4	40 BRN	SP	CRE	ED,ID	BD		3/14/2034
2020 PO4772888725	LGE	4	40 BRN	SP	P	ED,ID	BD		3/15/2034
2020 PO3998582939	LGE	4	35 BRO	SP	CCA		V		3/16/2034
2020 PO3999582948	LGE	4	35 BRO	SP	CCA		V		3/17/2034
2020 PO4000682941	LGE	4	35 BRO	SP	P		V		3/18/2034
2020 PO40017882933	LGE	4	35 BRO	SP	P		V		3/19/2034
2020 PO4002982930	LGE	4	35 BRO	SP	P		V		3/20/2034
2020 PO4002382916	LGE	4	35 BRO	SP	A		V		3/21/2034
2020 PO4001182897	LGE	4	35 BRO	SP	P		V		3/22/2034
2020 PO4002482908	LGE	3	45 BRO	SP	A		V		3/23/2034
2020 PO4001882908	LGE	4	35 BRO	SP	CCA		V		3/24/2034
2020 PO4664212092	KU	4	40 ACE	SP	CRE	ED,ID	TD		3/25/2034
2020 PO4652112104	KU	4	40 ACE	SP	CRE	ED,ID	BD		3/26/2034
2020 PO4689188856	LGE	4	30 BRO	ST	CCA		V		3/27/2034
2020 PO4688188860	LGE	3	45 BRO	SP	CCA		V		3/28/2034
2020 PO4688688853	LGE	3	45 BRO	SP	CCA		V		3/29/2034
2020 PO4689788838	LGE	4	40 BRO	SP	P	ED	T		3/30/2034
2020 PO4690888823	LGE	3	45 BRO	SP	CCA		V		3/31/2034
2020 PO4691888809	LGE	4	40 BRO	SP	CRE	ED,ID	TD		4/1/2034
2020 PO4692988795	LGE	4	40 BRO	SP	CRE	ED,ID	TD		4/2/2034
2020 PO4773588712	LGE	4	40 BRN	SP	CCA		V		4/3/2034
2020 PO4772888698	LGE	4	40 BRN	SP	CCA		V		4/4/2034
2020 PO4098409469	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD		4/5/2034
2020 PO4771588693	LGE	4	40 BRN	SP	CCA		V		4/6/2034
2020 PO4076109345	KU	3	45 BRO	SP	CRE	ID,IP	BD		4/7/2034
2020 PO4811111464	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		4/8/2034
2020 PO4056083002	LGE	4	35 BRO	SP	CCA	ED,ID	VX	RP3	4/9/2034
2020 PO4766488716	LGE	4	35 BRN	SP	A		V		4/10/2034
2020 PO4823611414	KU	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX	4/11/2034
2020 PO4834411371	KU	4	40 ACE	SP	CCA		V		4/12/2034
2020 PO4062609438	KU	3	45 BRO	SP	CCA		V		4/13/2034
2020 PO4062109464	KU	3	45 BRO	SP	CCA		V		4/14/2034
2020 PO4053309344	KU	3	45 BRO	SP	CRE	ID,IP	BD		4/15/2034
2020 PO4051309339	KU	3	45 BRO	SP	CCA		V		4/16/2034
2020 PO4745600186	LGE	4	35 BRN	SP	CCA		V		4/17/2034
2020 PO4731000225	LGE	4	35 BRN	SP	S		V		4/18/2034
2020 PO4762088715	LGE	4	35 BRN	SP	CCA		V		4/19/2034
2020 PO4762288690	LGE	4	40 BRN	SP	CRE	ED,ID	TD		4/20/2034
2020 PO4793711665	KU	5	35 ACE	SP	CRE	ED,ID	BD		4/21/2034
2020 PO4762888680	LGE	4	40 BRN	SP	S		V		4/22/2034
2020 PO4761788698	LGE	3	45 BRN	SP	CCA		V		4/23/2034
2020 PO4709499977	LGE	3	45 BRN	SP	CCA		V		4/24/2034
2020 PO4303412376	KU	4	40 BRO	SP	CRE	ID,IP	BD		4/25/2034

2020 PO4308212417	KU	3	45 BRO	SP	CRE	IP	BD	4/26/2034
2020 PO4760388719	LGE	4	40 BRN	SP	CRE	ED,ID	TD	4/27/2034
2020 PO4695788783	LGE	4	40 BRO	SP	A	ED,ID	TD	4/28/2034
2020 PO4695688785	LGE	4	30 BRO	SP	A	ED,ID	BD	4/29/2034
2020 PO4321212350	KU	3	45 BRO	SP	CRE	ED,ID	TD	4/30/2034
2020 PO4759388734	LGE	4	40 BRN	SP	CRE	ED,ID	TD	5/1/2034
2020 PO4056783011	LGE	4	40 BRO	SP	P	ED,ID	TD	5/2/2034
2020 PO4055983013	LGE	4	30 BRO	SP	S		V	5/3/2034
2020 PO4056283014	LGE	4	30 BRO	SP	S	ED,HH,ID	BX	RP2 5/4/2034
2020 PO4058183009	LGE	4	40 BRO	SP	P	ED,ID	TD	5/5/2034
2020 PO4059683007	LGE	4	40 BRO	SP	P	ED,ID	TD	5/6/2034
2020 PO4056082963	LGE	4	30 BRO	SP	A	ED,ID	TD	5/7/2034
2020 PO4056582962	LGE	4	40 BRO	SP	A	ED,ID	TD	5/8/2034
2020 PO4759688729	LGE	4	40 BRN	SP	S		V	5/9/2034
2020 PO4057182975	LGE	4	35 BRO	SP	P	ED,ID	TD	5/10/2034
2020 PO4056682975	LGE	4	40 BRO	SP	P	ED,ID	TD	5/11/2034
2020 PO5152009358	F	4	40 ACE	SP	CRE		V	5/12/2034
2020 PO5135508907	F	4	40 ACE	SP	P		V	5/13/2034
2020 PO5080210646	F	4	40 ACE	SP	P		V	5/14/2034
2020 PO5072509702	F	4	40 ACE	SP	CRE		V	5/15/2034
2020 PO4363201930	KU	4	40 BRN	SP	CRE	ED,ID,SRS	TD	5/16/2034
2020 PO4372501955	KU	4	45 BRN	SP	CRE	ID	BD	5/17/2034
2020 PO3751209199	KU	4	40 BRO	SP	CRE	ID,IP	BD	5/18/2034
2020 PO3736009155	KU	4	40 BRO	SP	CRE	ID,IP	BD	5/19/2034
2020 PO5057610096	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	RP1 5/20/2034
2020 PO4270211644	KU	4	40 BRO	SP	CRE	ID,IP	BD	5/21/2034
2020 PO4282211766	KU	4	40 BRO	SP	CRE	ID,IP	BD	5/22/2034
2020 PO4386401993	KU	4	40 BRN	SP	CRE	ED,ID	TD	5/23/2034
2020 PO4732089008	F	4	40 BRO	SP	CRE		V	5/24/2034
2020 PO4732688999	F	4	40 BRO	SP	CRE		V	5/25/2034
2020 PO4734489034	F	4	40 BRO	SP	CRE		V	5/26/2034
2020 PO4735189022	F	4	40 BRO	SP	CCA		V	5/27/2034
2020 PO5128210351	F	4	40 ACE	SP	P		V	5/28/2034
2020 PO4395401875	KU	4	40 BRN	SP	CRE	ED,ID,SRS	TD	5/29/2034
2020 PO5131210429	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	RP1 5/30/2034
2020 PO5168810522	F	4	40 ACE	SP	CRE		V	5/31/2034
2020 PO5146610533	F	4	40 ACE	SP	P		V	6/1/2034
2020 PO5156710316	F	4	40 ACE	SP	P		V	6/2/2034
2020 PO5169010439	F	4	40 ACE	SP	P		V	6/3/2034
2020 PO5162110467	F	4	40 ACE	SP	P		V	6/4/2034
2020 PO2114328741	ODP	6	30 XXX	SP	CRE	ID	TD	6/5/2034
2020 PO2102828847	ODP	6	30 XXX	SP	CRE	ID	BD	6/6/2034
2020 PO2099128508	ODP	3	40 XXX	SP	A	ID	TD	6/7/2034
2020 PO2092528592	ODP	4	40 XXX	SP	A	ID	BD	6/8/2034
2020 PO2086028681	ODP	4	40 XXX	SP	CRE	ID	TD	6/9/2034
2020 PO4016082832	F	3	45 BRN	SP	A		V	6/10/2034
2020 PO4016782838	F	4	40 BRN	SP	CCA		V	6/11/2034

2020 PO4017482832	F	4	30 BRN	SP	CCA		V		6/12/2034		
2020 PO4735989010	F	4	40 BRO	SP	CRE		V		6/13/2034		
2020 PO4733288989	F	4	40 BRO	SP	CCA		V		6/14/2034		
2020 PO4736688999	F	4	40 BRO	SP	CRE		V		6/15/2034		
2020 PO4733888981	F	4	40 BRO	SP	CRE		V		6/16/2034		
2020 PO4387501614	KU	5	35 BRN	SP	CCA		V		6/17/2034		
2020 PO4410501652	KU	4	40 BRN	SP	CCA		V		6/18/2034		
2020 PO4388201571	KU	4	40 BRN	SP	CRE	ED,ID		TD	6/19/2034		
2020 PO4370201637	KU	4	40 BRN	SP	CRE	ID		BD	6/20/2034		
2020 PO4374901534	KU	3	45 BRN	SP	CCA		V		6/21/2034		
2020 PO4360001469	KU	4	40 BRN	SP	CRE	ID		BD	6/22/2034		
2020 PO4739788951	F	4	40 BRO	SP	CRE		V		6/23/2034		
2020 PO4289011821	KU	2	40 BRO	SP	CRE	ID,IP		BD	6/24/2034		
2020 PO4393912262	KU	2	50 BRO	SP	CRE	ED,ID,IP		TD	6/25/2034		
2020 PO4738888964	F	4	40 BRO	SP	CRE		V		6/26/2034		
2020 PO4738388972	F	3	45 BRO	SP	CCA		V		6/27/2034		
2020 PO4737588985	F	4	40 BRO	SP	CRE		V		6/28/2034		
2020 PO4737288984	F	4	40 BRO	SP	CCA		V		6/29/2034		
2020 PO4737088966	LGE	4	30 BRO	SP	CRE		V		6/30/2034		
2020 PO4729688942	F	4	40 BRO	SP	A		V		7/1/2034		
2020 PO4728688936	F	4	40 BRO	SP	CRE		V		7/2/2034		
2020 PO4728488935	F	4	40 BRO	SP	CRE		V		7/3/2034		
2020 PO5121109546	F	4	40 ACE	SP	CRE		V		7/4/2034		
2020 PO5120609441	F	4	40 ACE	SP	CRE		V		7/5/2034		
2020 PO5116909248	F	4	40 ACE	SP	CRE		V		7/6/2034		
2020 PO5111409102	F	4	40 ACE	SP	P		V		7/7/2034		
2020 PO5099908803	F	4	40 ACE	SP	P		V		7/8/2034		
2020 PO5189309534	F	4	40 ACE	SP	CRE		V		7/9/2034		
2020 PO5091509414	F	4	40 ACE	SP	CRE		V		7/10/2034		
2020 PO4020282888	F	4	40 BRN	SP	CCA		V		7/11/2034		
2020 PO4019182870	F	4	40 BRN	SP	CCA		V		7/12/2034		
2020 PO4018582873	F	4	30 BRN	SP	CCA		V		7/13/2034		
2020 PO4019682891	F	4	30 BRN	SP	CCA		V		7/14/2034		
2020 PO4020882884	F	4	30 BRN	SP	CCA		V		7/15/2034		
2020 PO4019882866	F	4	30 BRN	SP	CCA		V		7/16/2034		
2020 PO4018182854	F	4	40 BRN	SP	CCA		V		7/17/2034		
2020 PO4017582858	F	4	30 BRN	SP	CCA		V		7/18/2034		
2020 PO4018882851	F	4	30 BRN	SP	CCA		V		7/19/2034		
2020 PO4381401270	KU	4	40 BRN	SP	CRE	ED,HH,ID,IP		TX	RR	7/20/2034	
2020 PO4390601156	KU	4	40 BRN	SP	CRE	ED,ID		TD		7/21/2034	
2020 PO4796400685	KU	4	35 BRN	SP	CRE	ED,ID,RB		X		PX	7/22/2034
2020 PO4820800552	KU	5	35 BRN	SP	CRE	ED,ID,RB		X		RP3	7/23/2034
2020 PO4420200779	KU	4	40 KOP	SP	CRE	ED,EP,HH,ID,RB,SRC		X		PX	7/24/2034
2020 PO4011682894	LGE	4	40 BRN	SP	CCA		V				7/25/2034
2020 PO4023382995	F	3	45 BRN	SP	CCA		V				7/26/2034
2020 PO4021582992	F	4	40 BRN	SP	CCA		V				7/27/2034
2020 PO4019783001	LGE	4	40 BRN	SP	P	ED,ID		BD			7/28/2034

2020 PO4019782995	LGE	4	40 BRN	SP	P	ED,ID	BD	7/29/2034
2020 PO4018183007	LGE	4	40 BRN	SP	CCA		V	7/30/2034
2020 PO4018283006	LGE	4	35 BRN	SP	A	ED,ID	BD	7/31/2034
2020 PO8517878416	F	4	45 BRO	SP	A		V	8/1/2034
2020 PO8516178097	F	3	45 BRO	SP	CRE		V	8/2/2034
2020 PO8515677992	KU	4	45 BRO	SP	CCA		V	8/3/2034
2020 PO8520378036	F	6	30 BRO	SP	CRE		V	8/4/2034
2020 PO8516878217	F	4	40 BRO	SP	A		V	8/5/2034
2020 PO8516878217	KU	4	40 BRO	SP	CCA		V	8/6/2034
2020 PO8515577959	F	3	45 BRO	SP	CCA		V	8/7/2034
2020 PO8640483663	F	4	40 BRO	SP	CRE		V	8/8/2034
2020 PO8643383818	KU	3	50 BRO	SP	CRE	ID	BD	8/9/2034
2020 PO8517478348	F	4	40 BRO	SP	CRE	HH,RB	VX	8/10/2034
2020 PO8640583772	F	3	50 BRO	SP	CRE		V	8/11/2034
2020 PO8685583784	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	8/12/2034
2020 PO8663383801	KU	4	45 BRO	SP	CCA		V	8/13/2034
2020 PO8722783755	KU	4	40 BRO	SP	CRE	ED,ID,SRS	BD	8/14/2034
2020 PO8703683770	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD	8/15/2034
2020 PO8703483868	KU	6	30 BRO	SP	CRE	HH,ID,SRS	TD	8/16/2034
2020 PO8626783953	F	3	50 BRO	SP	CCA		V	8/17/2034
2020 PO8640683958	F	3	55 BRO	SP	A		V	8/18/2034
2020 PO8639284216	F	4	40 BRO	SP	CCA		V	8/19/2034
2020 PO8633984215	F	6	30 BRO	SP	CRE		V	8/20/2034
2020 PO8639184415	F	4	40 BRO	SP	CRE		V	8/21/2034
2020 PO8518578583	F	4	45 BRO	SP	CCA		V	8/22/2034
2020 PO8518978699	F	4	45 BRO	SP	A		V	8/23/2034
2020 PO8515678494	F	5	35 BRO	SP	CCA		V	8/24/2034
2020 PO8509778453	F	4	40 BRO	SP	CRE		V	8/25/2034
2020 PO8500078457	F	4	40 BRO	SP	CRE		V	8/26/2034
2020 PO8489778461	F	4	40 BRO	SP	CRE		V	8/27/2034
2020 PO8478978467	F	4	40 BRO	SP	A		V	8/28/2034
2020 PO8475678554	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	8/29/2034
2020 PO8475478382	F	4	40 BRO	SP	CRE		V	8/30/2034
2020 PO8475678438	F	4	40 BRO	SP	CRE		V	8/31/2034
2020 PO8468178471	F	4	40 BRO	SP	CRE		V	9/1/2034
2020 PO8474878218	F	4	40 BRO	SP	CCA		V	9/2/2034
2020 PO8475178292	F	4	45 BRO	SP	CRE		V	9/3/2034
2020 PO8474478117	F	4	40 BRO	SP	CRE		V	9/4/2034
2020 PO8474178043	F	4	40 BRO	SP	CRE		V	9/5/2034
2020 PO8469778032	KU	5	35 BRO	SP	CCA		V	9/6/2034
2020 PO8468677917	F	4	40 BRO	SP	CRE		V	9/7/2034
2020 PO8473777927	F	3	45 BRO	SP	CRE		V	9/8/2034
2020 PO8479877909	F	4	40 BRO	SP	CCA		V	9/9/2034
2020 PO8490677902	KU	4	40 BRO	SP	CCA		V	9/10/2034
2020 PO8459577923	F	4	40 BRO	SP	CRE		V	9/11/2034
2020 PO8450177931	F	4	40 BRO	SP	A		V	9/12/2034
2020 PO6926686408	KU	4	40 BRO	SP	CRE	ED,ID	TD	9/13/2034

2020 PO6988481325	KU	2	50 BRN	SP	CRE	ED,HH,ID	BX	PX	9/14/2034
2020 PO6989781410	KU	2	50 BRN	SP	CCA		V		9/15/2034
2020 PO6991181495	KU	2	50 BRN	SP	CRE	ED,ID	TD		9/16/2034
2020 PO7654475024	KU	4	40 BRO	SP	CCA		V		9/17/2034
2020 PO6918286526	KU	5	35 BRO	SP	CRE	ED,ID	BD		9/18/2034
2020 PO7052386990A	KU	6	30 BRO	SP	CCA		V		9/19/2034
2020 PO7052386990	KU	4	40 BRO	SP	CRE	ED,ID,IP,RB	TX	RR	9/20/2034
2020 PO7034786946	KU	4	40 BRO	SP	CRE	ED,ID,IP,RB	TX	RR	9/21/2034
2020 PO7632575073	KU	4	45 BRO	SP	CCA		V		9/22/2034
2020 PO7640575426	KU	4	40 BRO	SP	CCA		V		9/23/2034
2020 PO7583575802	KU	4	40 BRO	SP	CRE		V		9/24/2034
2020 PO7059486679	KU	4	40 BRO	SP	S		V		9/25/2034
2020 PO7648275827	KU	4	45 BRO	SP	CCA		V		9/26/2034
2020 PO1298949176	KU	4	40 BRO	SP	CCA		V		9/27/2034
2020 PO1299648974	KU	5	35 BRO	SP	CRE	ID,IP	TD		9/28/2034
2020 PO1300248837	KU	5	35 BRO	SP	CRE	ED,ID	TD		9/29/2034
2020 PO1299048659	KU	4	40 BRO	SP	CRE	ID	BD		9/30/2034
2020 PO1295648556	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD		10/1/2034
2020 PO1234248704	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD		10/2/2034
2020 PO1248548642	KU	4	40 BRO	SP	CCA		V		10/3/2034
2020 PO1263348591	KU	4	40 BRO	SP	CRE	ID,SRS	TD		10/4/2034
2020 PO1235347308	KU	4	40 BRO	SP	CRE	ED,HH,ID	X	RP2	10/5/2034
2020 PO1279247841	KU	4	40 BRO	SP	CRE	ED,HH	X	PX	10/6/2034
2020 PO1283148505	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD		10/7/2034
2020 PO1291448453	KU	4	40 BRO	SP	CRE	ID	TD		10/8/2034
2020 PO1285148305	KU	4	40 BRO	SP	CRE	ID	TD		10/9/2034
2020 PO1278748157	KU	4	40 BRO	SP	CRE	ED,IP	TD		10/10/2034
2020 PO1273848047	KU	4	40 BRO	SP	CCA		V		10/11/2034
2020 PO1251947697	KU	4	40 BRO	SP	CRE	ID,IP	BD		10/12/2034
2020 PO3817504758	KU	6	30 XXX	SP	CRE	ID	TD		10/13/2034
2020 PO6969880072	KU	5	35 BRN	SP	CCA		V		10/14/2034
2020 PO6975780050	KU	4	40 BRN	SP	CRE	ED,ID	BD		10/15/2034
2020 PO7585977425	KU	5	45 BRO	SP	CRE	ED,ID	BD		10/16/2034
2020 PO7586177367	KU	4	45 BRO	SP	CRE	ED,ID	TD		10/17/2034
2020 PO7585477239	KU	4	35 BRO	SP	CRE	ED,ID	BD		10/18/2034
2020 PO6967280044	KU	6	30 BRN	SP	CRE	ED,ID	TD		10/19/2034
2020 PO7001185300	KU	4	40 BRO	SP	CRE	ED,ID	BD		10/20/2034
2020 PO6977280493	KU	4	40 BRN	SP	CRE	ED,ID	TD		10/21/2034
2020 PO6976580425	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD		10/22/2034
2020 PO6983280289	KU	4	40 BRN	SP	CRE	ED,ID	TD		10/23/2034
2020 PO7580077244	KU	4	30 BRO	SP	CRE		V		10/24/2034
2020 PO7571677264	KU	4	40 BRO	SP	CCA		V		10/25/2034
2020 PO7576077256	KU	6	30 BRO	SP	CRE	ED,ID	BD		10/26/2034
2020 PO7569277289	KU	5	35 BRO	SP	P	ED,ID	TD		10/27/2034
2020 PO7566177272	KU	4	30 BRO	SP	CCA		V		10/28/2034
2020 PO7561877283	KU	5	30 BRO	SP	CRE	ED,ID	BD		10/29/2034
2020 PO7678876123	KU	4	45 BRO	SP	CRE	ED,ID	BD		10/30/2034

2020 PO6997585182	KU	6	35 BRO	SP	CRE		V	10/31/2034
2020 PO6988085107	KU	4	45 BRO	SP	CRE	ED,ID	BD	11/1/2034
2020 PO6978684981	KU	4	40 BRO	SP	S		B	11/2/2034
2020 PO6976585004	KU	5	35 BRO	SP	CRE	ED,ID	BD	11/3/2034
2020 PO7047185587	KU	5	35 BRO	SP	S		V	11/4/2034
2020 PO6981285353	KU	4	45 BRO	SP	S		V	11/5/2034
2020 PO6981285353A	KU	5	35 BRO	SP	CCA		V	11/6/2034
2020 PO6972985487	KU	4	45 BRO	SP	S		V	11/7/2034
2020 PO6977085593	KU	5	35 BRO	SP	CCA		V	11/8/2034
2020 PO6968785667	KU	4	45 BRO	SP	CCA		V	11/9/2034
2020 PO6972285821A	KU	5	35 BRO	SP	S		V	11/10/2034
2020 PO6972285821	KU	4	45 BRO	SP	S		V	11/11/2034
2020 PO6985681156	KU	2	50 BRN	SP	CRE	ED,ID	TD	11/12/2034
2020 PO6990780696	KU	4	45 BRN	SP	CRE	ED,ID	TD	11/13/2034
2020 PO6983785921	KU	4	45 BRO	SP	S		V	11/14/2034
2020 PO7007180503	KU	4	40 BRN	SP	CRE	ED,ID,IP	BD	11/15/2034
2020 PO6988280495	KU	4	45 BRN	SP	CRE	ED,ID	BD	11/16/2034
2020 PO6994480938	KU	3	50 BRN	SP	CRE	ED,ID,IP	TD	11/17/2034
2020 PO7047185587A	KU	5	35 BRO	SP	CCA		V	11/18/2034
2020 PO7056285495	KU	4	45 BRO	SP	CCA		V	11/19/2034
2020 PO7037585553	KU	4	45 BRO	SP	CCA		V	11/20/2034
2020 PO7022085590	KU	4	45 BRO	SP	CCA		V	11/21/2034
2020 PO7005985627	KU	4	45 BRO	SP	CCA		V	11/22/2034
2020 PO6992885697	KU	4	45 BRO	SP	CCA		V	11/23/2034
2020 PO6998885840	KU	4	45 BRO	SP	CRE		V	11/24/2034
2020 PO7001586030	KU	4	45 BRO	SP	CCA		B	11/25/2034
2020 PO7004786125	KU	4	40 BRO	SP	CCA		V	11/26/2034
2020 PO6989686221	KU	4	40 BRO	SP	CRE	ED,ID	TD	11/27/2034
2020 PO7707475991	KU	4	40 BRO	SP	CCA		V	11/28/2034
2020 PO7703476135	KU	4	45 BRO	SP	CRE		V	11/29/2034
2020 PO7706675791	KU	4	40 BRO	SP	CCA		V	11/30/2034
2020 PO7705775591	KU	3	45 BRO	SP	CCA		V	12/1/2034
2020 PO6964786287	KU	4	40 BRO	SP	CRE	ED,ID	TD	12/2/2034
2020 PO6952586344	KU	4	40 BRO	SP	CCA		V	12/3/2034
2020 PO7677674972	KU	4	45 BRO	SP	CCA		V	12/4/2034
2020 PO6942086404	KU	4	40 BRO	SP	CRE	ED,ID	BD	12/5/2034
2020 PO7653675664	KU	4	40 BRO	SP	CRE	ED,ID	BD	12/6/2034
2020 PO7645275677	KU	4	45 BRO	SP	CRE	ED,ID,IP	BX	RR 12/7/2034
2020 PO7657275799	KU	4	45 BRO	SP	CCA		V	12/8/2034
2020 PO7648775875	KU	4	45 BRO	SP	CRE	ED,ID	BD	12/9/2034
2020 PO7656875863	KU	4	45 BRO	SP	CCA		V	12/10/2034
2020 PO7651976017	KU	3	45 BRO	SP	CCA		V	12/11/2034
2020 PO3225204535	KU	5	35 BRO	SP	CRE	ID	BD	12/12/2034
2020 PO3207904550	KU	4	40 BRO	SP	CRE	ID	TD	12/13/2034
2020 PO3201304616	KU	4	40 BRO	SP	CCA		V	12/14/2034
2020 PO3196104680	KU	5	35 BRO	SP	CRE	ID	TD	12/15/2034
2020 PO3179604705	KU	4	40 BRO	SP	CRE	ID	BD	12/16/2034

2020 PO3185804658	KU	6	30 BRO	SP	CRE	ID	TD	12/17/2034
2020 PO3191504590	KU	6	30 BRO	SP	CRE	ID	TD	12/18/2034
2020 PO3239404237	KU	5	35 BRO	SP	CRE	ID	TD	12/19/2034
2020 PO3236204186	KU	5	35 BRO	SP	CRE	ID	TD	12/20/2034
2020 PO3233604275	KU	3	50 BRO	SP	CRE	ID	BD	12/21/2034
2020 PO3222304080	KU	2	55 BRO	SP	CRE	ID	TD	12/22/2034
2020 PO3256604006	KU	4	40 BRO	SP	CCA		V	12/23/2034
2020 PO6994381690	KU	2	50 BRN	SP	CRE	ED,ID	TD	12/24/2034
2020 PO7013786885	KU	5	30 BRO	SP	CRE		V	12/25/2034
2020 PO7014586935	KU	4	45 BRO	SP	CCA		V	12/26/2034
2020 PO7029186856	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	12/27/2034
2020 PO6942482135	KU	5	35 BRN	SP	CCA		V	12/28/2034
2020 PO6978381919	KU	4	40 BRN	SP	CCA		V	12/29/2034
2020 PO6952581987	KU	4	45 BRN	SP	CRE	ED,ID	BD	12/30/2034
2020 PO6934182075	KU	4	40 BRN	SP	CRE	ED,ID,IP	BD	12/31/2034
2020 PO6913882171	KU	4	45 BRN	SP	CRE	ED,HH,ID,RB	BX	PX 1/1/2035
2020 PO6885082307	KU	6	30 BRN	SP	CRE	ED,ID	BD	1/2/2035
2020 PO7046086695	KU	6	30 BRO	SP	CRE	ED,HH,ID,IP,RB	TX	RR 1/3/2035
2020 PO3279903964	KU	6	30 BRO	SP	CRE	ID	TD	1/4/2035
2020 PO3278104042	KU	4	40 BRO	SP	CRE	ID	TD	1/5/2035
2020 PO3290704087	KU	4	40 BRO	SP	CRE	ID	TD	1/6/2035
2020 PO3290804167	KU	6	30 BRO	SP	CRE	ID	TD	1/7/2035
2020 PO3301704119	KU	4	40 BRO	SP	CRE	ID	TD	1/8/2035
2020 PO3307204133	KU	4	40 BRO	SP	CCA		V	1/9/2035
2020 PO3332704145	KU	5	35 BRO	SP	CRE	ID	TX	RR 1/10/2035
2020 PO3314104151	KU	4	40 BRO	SP	CRE	ID	TD	1/11/2035
2020 PO3334904229	KU	6	30 BRO	SP	CRE		V	1/12/2035
2020 PO3347604365	KU	5	35 BRO	SP	CRE	ID	TD	1/13/2035
2020 PO3349304210	KU	5	45 BRO	SP	CRE	ID	TD	1/14/2035
2020 PO3358704224	KU	6	30 BRO	SP	CCA		V	1/15/2035
2020 PO3339604046	KU	4	40 BRO	SP	CRE	ID	TD	1/16/2035
2020 PO3321803991	KU	4	40 BRO	SP	CCA		V	1/17/2035
2020 PO3313203962	KU	6	30 BRO	SP	CRE	ID	TD	1/18/2035
2020 PO3301503940	KU	6	30 BRO	SP	CRE	ID	TD	1/19/2035
2020 PO3309003949	KU	4	40 BRO	SP	CRE	ID	TD	1/20/2035
2020 PO7660476541	KU	3	45 BRO	SP	CCA		V	1/21/2035
2020 PO7524775467	KU	5	30 BRO	SP	CCA		V	1/22/2035
2020 PO7089886079	KU	4	45 BRO	SP	CRE	ED,ID	TD	1/23/2035
2020 PO3789904419	KU	6	30 XXX	SP	CRE	ED,ID	TD	1/24/2035
2020 PO3776404226	KU	6	30 XXX	SP	CCA		V	1/25/2035
2020 PO3763404355	KU	6	30 XXX	SP	CRE	ID	TD	1/26/2035
2020 PO7100085975	KU	5	35 BRO	SP	CRE	ED,ID	TD	1/27/2035
2020 PO7649376615	KU	4	45 BRO	SP	CCA		V	1/28/2035
2020 PO7650676473	KU	3	45 BRO	SP	CCA		V	1/29/2035
2020 PO7654076252	KU	4	45 BRO	SP	CCA		V	1/30/2035
2020 PO3826604714	KU	6	30 BRO	SP	CCA		V	1/31/2035
2020 PO3826704671	KU	4	40 XXX	SP	CRE	ED,ID,SRS	TD	2/1/2035

2020 PO7043386653	KU	4	45 BRO	SP	CRE	ED,ID	BD	2/2/2035	
2020 PO7042186737	KU	5	35 BRO	SP	CRE	ED,ID	TD	2/3/2035	
2020 PO7048086771	KU	4	45 BRO	SP	CRE	ED,ID	TD	2/4/2035	
2020 PO7634576233	KU	4	45 BRO	SP	A	ED,ID	TD	2/5/2035	
2020 PO7655176161	KU	4	40 BRO	SP	A	ED,ID	BX	RR	2/6/2035
2020 PO7617576196	KU	3	45 BRO	SP	CCA		V	2/7/2035	
2020 PO7056986522	KU	4	45 BRO	SP	S		V	2/8/2035	
2020 PO3813804670	KU	6	30 XXX	SP	CRE	ID	TD	2/9/2035	
2020 PO7102085973	KU	3	45 BRO	SP	A	ED,ID	TD	2/10/2035	
2020 PO7539474362	KU	4	40 BRO	SP	CRE	ED,ID	BD	2/11/2035	
2020 PO7536674424	KU	4	40 BRO	SP	CRE		V	2/12/2035	
2020 PO3814104520	KU	4	40 XXX	SP	CRE	ID	TD	2/13/2035	
2020 PO3795404530	KU	4	40 BRN	SP	CCA		V	2/14/2035	
2020 PO3806004414	KU	4	45 XXX	SP	CRE	ED,ID,SRS	TD	2/15/2035	
2020 PO3802604370	KU	6	30 XXX	SP	CRE	ED,ID	TD	2/16/2035	
2020 PO3804004238	KU	5	30 XXX	SP	CRE	ID	TD	2/17/2035	
2020 PO7036686262	KU	4	40 BRO	SP	S		V	2/18/2035	
2020 PO7058986335	KU	4	45 BRO	SP	CRE	ED,ID	TD	2/19/2035	
2020 PO7058986335A	KU	6	30 BRO	SP	CRE	ED,ID	TD	2/20/2035	
2020 PO7062586278	KU	4	30 BRO	SP	CRE	ED,ID	BD	2/21/2035	
2020 PO7617276121	KU	3	45 BRO	SP	CCA		V	2/22/2035	
2020 PO7612976345	KU	4	45 BRO	SP	A	ED,ID	TD	2/23/2035	
2020 PO6981082110	KU	4	40 BRN	SP	CRE	ID	BD	2/24/2035	
2020 PO7074186192	KU	4	40 BRO	SP	CRE	ED,ID	BD	2/25/2035	
2020 PO7618376321	KU	3	45 BRO	SP	CCA		V	2/26/2035	
2020 PO6994881992	KU	5	35 BRN	SP	CRE	ED,HH,ID,RB	X	PX	2/27/2035
2020 PO3792104456	KU	4	45 XXX	SP	CRE	ED,ID,SRS	TD	2/28/2035	
2020 PO3790004356	KU	4	40 XXX	SP	CRE	ED,ID,SR	TX	RR	3/1/2035
2020 PO3780604301	KU	4	45 XXX	SP	CRE	ED,ID,SRS	TD	3/2/2035	
2020 PO3753604491	KU	6	30 XXX	SP	CRE	ED,ID,SRS	TD	3/3/2035	
2020 PO7085885584	KU	5	35 BRO	SP	CCA		V	3/4/2035	
2020 PO7541973857	KU	5	35 BRO	SP	CRE	ED,ID	BD	3/5/2035	
2020 PO7585873884	KU	4	40 BRO	SP	CRE	ED,ID	BD	3/6/2035	
2020 PO6974882907	KU	4	45 BRN	SP	CCA		V	3/7/2035	
2020 PO7097085475	KU	3	45 BRO	SP	CRE	ED,ID	BD	3/8/2035	
2020 PO1468647343	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	3/9/2035	
2020 PO1489647251	KU	4	40 BRO	SP	CRE	ID	BD	3/10/2035	
2020 PO1443547440	KU	4	40 BRO	SP	CRE	ID	TD	3/11/2035	
2020 PO1425747503	KU	3	40 BRO	SP	CRE	ID,IP	TD	3/12/2035	
2020 PO1410147521	KU	4	40 BRO	SP	CRE	ID,IP	BD	3/13/2035	
2020 PO1394547539	KU	4	40 BRO	SP	CRE	ID	TD	3/14/2035	
2020 PO1376047618	KU	4	40 BRO	SP	CCA	ED	TD	3/15/2035	
2020 PO1346747693	KU	4	40 BRO	SP	CCA	ED	TD	3/16/2035	
2020 PO1324947751	KU	4	40 BRO	SP	CRE	ID,IP	BD	3/17/2035	
2020 PO1301347823	KU	4	40 BRO	SP	CRE	ID,IP	TD	3/18/2035	
2020 PO1294949711	KU	4	40 BRO	SP	CCA		V	3/19/2035	
2020 PO1297449375	KU	4	40 BRO	SP	CRE	ID,IP	TD	3/20/2035	

2020 PO1216646878	KU	5	35 BRO	SP	CRE	ID,IP	TD	3/21/2035
2020 PO1206646650	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/22/2035
2020 PO8777788228	KU	3	55 ACE	SP	CCA		V	3/23/2035
2020 PO8670188242	KU	4	40 ACE	SP	CCA		V	3/24/2035
2020 PO8612188297	KU	4	40 ACE	SP	CCA		V	3/25/2035
2020 PO7578980971	KU	4	45 BRN	SP	CRE	ED,ID	BD	3/26/2035
2020 PO5082406990	KU	5	30 XXX	SP	CRE	ED,ID	TD	3/27/2035
2020 PO5083107026	KU	5	30 XXX	SP	CRE	ED,ID	TD	3/28/2035
2020 PO5074507028	KU	5	30 XXX	SP	CRE	ED,ID	TD	3/29/2035
2020 PO5070507119	KU	6	30 XXX	SP	CCA		V	3/30/2035
2020 PO7584680991	F	3	40 BRN	SP	CRE	ED,HH,ID,RB	VX PX	3/31/2035
2020 PO7567781160-B	KU	5	35 BRN	SP	P	ED,ID	TD	4/1/2035
2020 PO7567781160-A	F	3	45 BRN	SP	CCA		V	4/2/2035
2020 PO7589380865	F	3	40 BRN	SP	CRE		V	4/3/2035
2020 PO7585280776	KU	4	45 BRN	SP	CRE	ED,ID	BD	4/4/2035
2020 PO6924278386	KU	4	45 BRN	SP	CRE	ED,ID	TD	4/5/2035
2020 PO6913377956	KU	4	40 BRN	SP	CRE	ED,ID	TD	4/6/2035
2020 PO6918378473	KU	4	40 BRN	SP	CRE		V	4/7/2035
2020 PO6928878594	KU	4	45 BRN	SP	CRE	ED,ID	BD	4/8/2035
2020 PO6927978739	KU	4	45 BRN	SP	CRE		V	4/9/2035
2020 PO6938578820	KU	4	40 BRN	SP	CRE	ED,ID	TD	4/10/2035
2020 PO6949179046	KU	4	40 BRN	DF	CRE	ED,ID	BD	4/11/2035
2020 PO6938879087	KU	6	30 BRN	SP	CRE	HH,ID,IP	TD	4/12/2035
2020 PO2399404295	KU	3	40 BRO	SP	CRE		V	4/13/2035
2020 PO7020884736	KU	4	45 BRO	SP	CRE	ED,ID	BD	4/14/2035
2020 PO7655573177	KU	4	40 BRO	SP	CCA		V	4/15/2035
2020 PO6646483463	KU	1	80 BRN	ST	CRE		V	4/16/2035
2020 PO6612883385	KU	2	65 BRN	SP	CRE		V	4/17/2035
2020 PO6580183307	KU	2	70 BRN	SP	A		V	4/18/2035
2020 PO6533283203	KU	2	60 BRN	SP	CCA		V	4/19/2035
2020 PO6556583256	KU	2	60 BRN	SP	P		V	4/20/2035
2020 PO6471683064	KU	1	60 BRN	SP	A		V	4/21/2035
2020 PO6504983140	KU	1	75 BRN	SP	CCA		V	4/22/2035
2020 PO6416382937	KU	2	70 BRN	SP	CRE		V	4/23/2035
2020 PO7268985906	KU	2	45 BRO	SP	CRE	ED,ID	TD	4/24/2035
2020 PO3875704241	KU	6	30 BRO	SP	CCA		V	4/25/2035
2020 PO3864804166	KU	5	30 BRO	SP	CRE	ED,ID	TD	4/26/2035
2020 PO3871004191	KU	6	30 BRO	SP	CRE	ED,ID	TD	4/27/2035
2020 PO3900204311	KU	6	30 BRO	SP	CCA		V	4/28/2035
2020 PO3891504426	KU	6	30 BRO	SP	CCA		V	4/29/2035
2020 PO3877204428	KU	4	40 BRO	SP	CRE	ED,ID	TD	4/30/2035
2020 PO3872604323	KU	4	40 BRO	SP	CCA		V	5/1/2035
2020 PO3870104454	KU	5	35 BRO	SP	CCA		V	5/2/2035
2020 PO3891904547	KU	6	30 BRO	SP	CRE		V	5/3/2035
2020 PO3873205070	KU	4	40 BRO	SP	CRE	ED,ID	TD	5/4/2035
2020 PO3860804959	KU	6	30 BRO	SP	CCA		V	5/5/2035
2020 PO7269985850	KU	6	30 BRO	SP	P	ED,ID	TD	5/6/2035

2020 PO7273485799	KU	2	50 BRO	SP	CRE	ED,ID	BD	5/7/2035
2020 PO7275985747	KU	4 30E	BRO	SP	CCA		V	5/8/2035
2020 PO7275585723	KU	6	30 BRO	SP	CRE		V	5/9/2035
2020 PO7269285625	KU	6	30 BRO	SP	CRE		V	5/10/2035
2020 PO7291885403	KU	2	50 BRO	SP	S		V	5/11/2035
2020 PO7657673596	KU	5	35 BRO	SP	CCA		V	5/12/2035
2020 PO7668373595	KU	5	35 BRO	SP	CCA		V	5/13/2035
2020 PO7617172558	KU	5	35 BRO	SP	CCA		V	5/14/2035
2020 PO7623972722	KU	5	35 BRO	SP	CCA		V	5/15/2035
2020 PO7282585282	KU	4	40 BRO	SP	CRE	ED,ID	BD	5/16/2035
2020 PO7245585593	KU	4	35 BRO	SP	CRE	ED,ID	TD	5/17/2035
2020 PO7250585549	KU	5	35 BRO	SP	CRE	ED,ID	TD	5/18/2035
2020 PO7253685538	KU	5	35 BRO	SP	CRE	ED,ID	TD	5/19/2035
2020 PO7281785614	KU	3	50 BRO	SP	CRE	ED,ID	TD	5/20/2035
2020 PO7260785508	KU	5	35 BRO	SP	CRE	ED,ID	TD	5/21/2035
2020 PO7249985170	KU	4	40 BRO	SP	CCA		V	5/22/2035
2020 PO7255585362	KU	4	40 BRO	SP	CCA		V	5/23/2035
2020 PO7262885415	KU	4	40 BRO	SP	CCA		V	5/24/2035
2020 PO7269485474	KU	3	45 BRO	SP	CRE	ED,ID	TD	5/25/2035
2020 PO7277185560	KU	5	35 BRO	SP	P	ED,ID	TD	5/26/2035
2020 PO7292485799	KU	4	40 BRO	SP	CRE	ED,ID	BD	5/27/2035
2020 PO7022084432	KU	3	45 BRO	SP	CRE	ED,ID	TD	5/28/2035
2020 PO7649572562	KU	5	35 BRO	SP	CCA		V	5/29/2035
2020 PO7665272800	KU	4	40 BRO	SP	CRE	ED,ID	BD	5/30/2035
2020 PO7652772713	KU	4	40 BRO	SP	CRE	ED,ID	BD	5/31/2035
2020 PO7675872714	KU	4	40 BRO	SP	CRE		V	6/1/2035
2020 PO6444683002	KU	2	70 BRN	AL	CRE		V	6/2/2035
2020 PO7013084508	KU	3	45 BRO	SP	CRE	ED,ID	TD	6/3/2035
2020 PO6998284672	KU	4	40 BRO	SP	CRE	ED,ID	TD	6/4/2035
2020 PO2814066121	KU	4	45 BRN	SP	CRE	ID	TD	6/5/2035
2020 PO2852866321	KU	4	40 BRN	SP	CRE	ID	TD	6/6/2035
2020 PO2880966105	KU	4	40 BRN	SP	CRE	ID	TD	6/7/2035
2020 PO2918465872	KU	4	40 BRN	SP	CRE	ID	TD	6/8/2035
2020 PO1588644937	F	4	40 BRO	SP	P		V	6/9/2035
2020 PO2950065676	KU	5	35 BRN	SP	CRE	ID	TD	6/10/2035
2020 PO2980865481	KU	4	40 BRN	SP	CRE	ID	TD	6/11/2035
2020 PO3031265163	KU	4	40 BRO	SP	CRE	ID	TD	6/12/2035
2020 PO2715766231	KU	4	40 BRO	SP	CRE	ID,IP	TD	6/13/2035
2020 PO2704866248	KU	4	40 BRO	SP	CRE		V	6/14/2035
2020 PO2678466288	KU	4	40 BRO	ST	CRE	ED,ID,IP	TD	6/15/2035
2020 PO2651466324	KU	6	35 BRO	SP	CRE	ED,IP	TD	6/16/2035
2020 PO2633567167	KU	4	40 BRO	SP	CCA		V	6/17/2035
2020 PO2624766802	KU	5	35 BRO	SP	CRE	ED,HH	X	PX 6/18/2035
2020 PO2805367315	F	2	50 BRO	SP	P		V	6/19/2035
2020 PO7037584712	KU	4	45 BRO	SP	CRE	ED,ID	TD	6/20/2035
2020 PO3496604389	KU	6	30 BRN	SP	CCA		V	6/21/2035
2020 PO2362559173	F	3 45E	BRN	SP	P		V	6/22/2035

2020 PO2286460526	KU	4	40 BRN	SP	CRE	ID,IP	BD	6/23/2035
2020 PO2242760796	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	6/24/2035
2020 PO2268460641	KU	4	40 BRN	SP	CRE	ED,ID	BD	6/25/2035
2020 PO2326260286	KU	4	40 BRN	SP	CRE	ID,IP	TD	6/26/2035
2020 PO2352560107	KU	4	40 BRN	SP	CRE	ID	TD	6/27/2035
2020 PO2375759956	KU	4	40 BRN	SP	CRE	ID,IP	TD	6/28/2035
2020 PO2399359792	KU	4	40 BRN	SP	CRE	ID	TD	6/29/2035
2020 PO2889267597	KU	5	35 BRN	SP	CRE	ID,IP	TD	6/30/2035
2020 PO2923267581	KU	4	40 BRN	SP	CRE	ID	TD	7/1/2035
2020 PO2902867208	KU	4	40 BRN	SP	P	ED	TD	7/2/2035
2020 PO2899066879	KU	4	40 BRN	SP	CRE	ID	TD	7/3/2035
2020 PO2777466610	KU	5	35 BRN	SP	CRE	ID	BD	7/4/2035
2020 PO2803366509	KU	4	40 BRN	SP	CRE	ID,IP	TD	7/5/2035
2020 PO2820366185	KU	4	40 BRN	SP	CRE	ID	TD	7/6/2035
2020 PO7390086996A	KU	6 25E	BRO	SP	CRE	ED,ID,MD	TD	7/7/2035
2020 PO3589903963	KU	5	35 BRO	SP	CRE	ID	TD	7/8/2035
2020 PO9684993681	KU	4	40 APL	SP	CCA		V	7/9/2035
2020 PO9697493696	KU	4	40 APL	SP	CCA		V	7/10/2035
2020 PO9709993708	KU	4	40 APL	SP	CCA		V	7/11/2035
2020 PO9733993658	KU	4	45 APL	SP	CCA		V	7/12/2035
2020 PO9757793602	KU	4	40 APL	SP	CCA		V	7/13/2035
2020 PO9778793654	KU	6	30 APL	SP	CCA		V	7/14/2035
2020 PO9596592194	KU	4	40 APL	SP	CCA		V	7/15/2035
2020 PO9621592192	KU	4	40 APL	SP	CCA		V	7/16/2035
2020 PO9197796700a	KU	4	40 APL	SP	CCA		V	7/17/2035
2020 PO9197796700	KU	4	45 APL	SP	CCA		V	7/18/2035
2020 PO9188696486	KU	4	45 APL	SP	CCA		V	7/19/2035
2020 PO9194796285	KU	4	45 APL	SP	CCA		V	7/20/2035
2020 PO9197696077	KU	4	40 APL	SP	CCA		V	7/21/2035
2020 PO9208595898	KU	4	40 APL	SP	CCA		V	7/22/2035
2020 PO9225095768	KU	4	40 APL	SP	CCA		V	7/23/2035
2020 PO8930294030	F	4	40 APL	SP	CRE		V	7/24/2035
2020 PO0540961556	F	5 35E	BRN	SP	CRE		V	7/25/2035
2020 PO0536161635	KU	4	40 BRN	SP	CRE	ID	TD	7/26/2035
2020 PO0520661699	KU	4	40 BRN	SP	CRE	ID	TD	7/27/2035
2020 PO0501761778	KU	4	40 BRN	SP	CRE	ID,IP	TD	7/28/2035
2020 PO0543161606	F	4	40 BRN	SP	P		V	7/29/2035
2020 PO0544961655	KU	4	45 BRN	SP	P	ED	TD	7/30/2035
2020 PO0548261722	F	7	30 BRN	SP	CRE		V	7/31/2035
2020 PO0550461627	KU	3	45 BRN	SP	CRE	ED,ID,IP	TD	8/1/2035
2020 PO0555861606	KU	4	40 BRN	SP	CRE	ID	TD	8/2/2035
2020 PO0562761525	F	5	35 BRN	SP	P		V	8/3/2035
2020 PO0566461565	KU	2	45 BRN	SP	CRE	ID	TD	8/4/2035
2020 PO0531161390	KU	4	40 BRN	SP	CRE	ED,HH	TX	RR 8/5/2035
2020 PO9109992966	F	4	40 APL	SP	CRE		V	8/6/2035
2020 PO9226692855	KU	6	30 APL	SP	CRE		V	8/7/2035
2020 PO9234293004	KU	6	30 APL	SP	CRE		V	8/8/2035

2020 PO9226393429	KU	4	35 APL	SP	CCA			V		8/9/2035
2020 PO9053592578	F	4	40 APL	SP	CRE		ED,EP,HH,ID,IP,RB	VX	RP1	8/10/2035
2020 PO8986392030	KU	4	40 APL	SP	CRE		ED,ID	TD		8/11/2035
2020 PO8978192275	KU	4	40 APL	SP	CRE		ED,EP,HH,ID,IP,RB	X	PX	8/12/2035
2020 PO8953992214	KU	5	35 APL	SP	CRE		ED,ID	TD		8/13/2035
2020 PO8970491683	KU	5	35 APL	SP	CRE		ED,ID	TD		8/14/2035
2020 PO8977891550	KU	4	40 APL	SP	CRE		ED,ID	BD		8/15/2035
2020 PO8954592740	KU	6	30 APL	SP	CRE		ED,ID	BD		8/16/2035
2020 PO8941392814	KU	4	40 APL	SP	CRE		ED,ID	BD		8/17/2035
2020 PO0531161453	F	5	35E BRN	SP	CRE			V		8/18/2035
2020 PO0530561325	F	5	35E BRN	SP	CRE			V		8/19/2035
2020 PO0535761441	F	4	40 BRN	SP	P			V		8/20/2035
2020 PO0521561429	KU	4	45 BRN	SP	CCA			V		8/21/2035
2020 PO0508261483	KU	2	55 BRN	SP	CRE		ID	BD		8/22/2035
2020 PO0491961549	KU	2	55 BRN	SP	CRE		ID	TD		8/23/2035
2020 PO0476961608	KU	4	45 BRN	SP	CCA			V		8/24/2035
2020 PO9596893242	KU	4	40 APL	SP	CRE		ED,ID	BD		8/25/2035
2020 PO9595992997	KU	4	40 APL	SP	CRE		ED,ID	TD		8/26/2035
2020 PO9593692677	KU	4	40 APL	SP	CRE		ED,ID	TD		8/27/2035
2020 PO9600792723	KU	6	30 APL	SP	CRE		ED,EP,HH,ID,IP,RB	BX	RP1	8/28/2035
2020 PO9625290200	KU	4	40 APL	SP	CRE		ED,ID,IP	BD		8/29/2035
2020 PO9038092663	KU	4	40 APL	SP	CRE		ED,ID	TD		8/30/2035
2020 PO9047392154	KU	4	40 APL	SP	CRE		ED,ID	TD		8/31/2035
2020 PO9063392021	KU	4	40 APL	SP	CRE		ED,ID	TD		9/1/2035
2020 PO9084292762	F	4	40 APL	SP	CRE			V		9/2/2035
2020 PO8913594738	KU	4	40 APL	SP	CRE			V		9/3/2035
2020 PO9463479611	KU	4	40 BRO	SP	CCA			V		9/4/2035
2020 PO8899580889	KU	6	30 BRO	SP	CRE		ID	BD		9/5/2035
2020 PO9096778670	KU	4	40 BRO	SP	CRE		ED,ID,IP	TD		9/6/2035
2020 PO9098878864	KU	3	50 BRO	SP	CRE		ED,ID,IP	TD		9/7/2035
2020 PO9100479052	KU	3	45 BRO	SP	CRE		ED,ID,IP	TD		9/8/2035
2020 PO8936380541	KU	5	35 BRO	SP	CRE		ED,ID,IP	TD		9/9/2035
2020 PO9102179203	KU	3	45 BRO	SP	CRE		ED,ID,IP	TD		9/10/2035
2020 PO8931681212	F	4	40 BRO	SP	CCA			V		9/11/2035
2020 PO8940181137	F	5	35 BRO	SP	CRE			V		9/12/2035
2020 PO8903480712	KU	6	30 BRO	SP	CRE		ED,ID,IP,SRS	TD		9/13/2035
2020 PO8901780634	KU	6	30 BRO	SP	CRE		ID	BD		9/14/2035
2020 PO8910281214	KU	6	30 BRO	SP	CCA			V		9/15/2035
2020 PO8965581167	KU	5	35 BRO	SP	CRE		ED,ID,SR	TD		9/16/2035
2020 PO8897694665	KU	6	30 APL	SP	CRE		ED,ID	TD		9/17/2035
2020 PO8863593964	KU	4	40 APL	SP	CRE		ED,ID	TD		9/18/2035
2020 PO8859394133	KU	5	30 APL	SP	CRE		ED,ID	TD		9/19/2035
2020 PO9607389706	KU	5	35 APL	SP	CCA			V		9/20/2035
2020 PO9070080930	KU	3	45 BRO	SP	CRE		ED,ID,IP	TD		9/21/2035
2020 PO9190580670	F	4	40 BRO	SP	CRE			V		9/22/2035
2020 PO9220480669	F	4	40 BRO	SP	CRE			V		9/23/2035
2020 PO9234680670	F	4	40 BRO	SP	CRE			V		9/24/2035

2020 PO9244480671	F	4	40 BRO	SP	CRE		V		9/25/2035
2020 PO9202080670	F	4	40 BRO	SP	CRE	HH,RB	VX	PX	9/26/2035
2020 PO9208180670	F	4	40 BRO	SP	CRE		V		9/27/2035
2020 PO9261580668	F	4	40 BRO	SP	CCA		V		9/28/2035
2020 PO9401079672	KU	4	45 BRO	SP	CCA		V		9/29/2035
2020 PO9414779584	KU	4	45 BRO	SP	CRE	ID	BD		9/30/2035
2020 PO9057881035	KU	3	45 BRO	SP	CRE	ID,IP	BD		10/1/2035
2020 PO9463479587	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD		10/2/2035
2020 PO9466079616	KU	4	40 BRO	SP	CRE	ID	BD		10/3/2035
2020 PO8868382838	KU	2	70 BRO	SP	CRE		V		10/4/2035
2020 PO6890076220	KU	4	40 BRN	SP	CRE	ED,ID	TD		10/5/2035
2020 PO7244086999	KU	4	40 BRO	SP	CRE	ED,ID	BD		10/6/2035
2020 PO7247087034	KU	5	35 BRO	SP	CRE		V		10/7/2035
2020 PO6853076762	KU	5	35 BRN	SP	CRE	ED,ID	TD		10/8/2035
2020 PO6856276549	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		10/9/2035
2020 PO7239587037	F	3	40 BRO	SP	CRE		V		10/10/2035
2020 PO7231687085	F	3	40 BRO	SP	CRE		V		10/11/2035
2020 PO7209587255	F	4	40 BRO	SP	CRE	ED,ID,RB	VX	RP2	10/12/2035
2020 PO8366367464	KU	6	30 BRO	SP	CRE	ED,ID	BD		10/13/2035
2020 PO7212487212	F	3	50 BRO	SP	CRE		V		10/14/2035
2020 PO7227387233	F	4	30 BRO	SP	CRE		V		10/15/2035
2020 PO7220487208	KU	5	35 BRO	SP	CRE	ED,ID	BD		10/16/2035
2020 PO7225987300	F	4	40 BRO	SP	CRE		V		10/17/2035
2020 PO7240487340	F	4	40 BRO	SP	CRE		V		10/18/2035
2020 PO6872976400	KU	4	40 BRN	SP	CRE	ED,ID	BD		10/19/2035
2020 PO6919176260	KU	5	35 BRN	SP	CCA		V		10/20/2035
2020 PO6913776353	KU	4	40 BRN	SP	CRE	ED,ID	TD		10/21/2035
2020 PO6936876370	KU	4	40 BRN	SP	CRE	ED,ID	BD		10/22/2035
2020 PO6959876288	KU	4	40 BRN	SP	CRE	ED,ID	BD		10/23/2035
2020 PO6954076369	KU	4	40 BRN	SP	CRE	ED,ID	BD		10/24/2035
2020 PO6962476098	KU	4	40 BRN	SP	CRE	ED,ID	BD		10/25/2035
2020 PO7251287372	F	4	40 BRO	SP	CRE		V		10/26/2035
2020 PO7262487338	KU	5	35 BRO	SP	CRE	ED,ID,IP,RB,SRC	X	RR	10/27/2035
2020 PO7255987596	KU	5	35E BRO	SP	CCA		V		10/28/2035
2020 PO8343167556	KU	5	35 BRO	SP	CRE		V		10/29/2035
2020 PO7260987407	F	3	40 BRO	SP	CRE		V		10/30/2035
2020 PO7271887441	F	3	40 BRO	SP	CRE		V		10/31/2035
2020 PO7283387477	KU	4	45 BRO	SP	CRE	ED,ID	TD		11/1/2035
2020 PO8347767397	KU	4	40 BRO	SP	P	ED,ID	TD		11/2/2035
2020 PO7290787498	KU	5	35 BRO	SP	CRE	ED,ID	BD		11/3/2035
2020 PO7287687362A	KU	4	40 BRO	SP	P	ED,ID,IP	BD		11/4/2035
2020 PO7287687362	KU	4	45 BRO	SP	CRE	ED,ID	TD		11/5/2035
2020 PO7291487248	F	6	30 BRO	SP	CRE		V		11/6/2035
2020 PO8343567190	KU	6	30 BRO	SP	CRE	ED,ID	TD		11/7/2035
2020 PO9329880181	KU	4	40 BRO	SP	CCA		V		11/8/2035
2020 PO9340180106	KU	4	40 BRO	SP	CCA		V		11/9/2035
2020 PO9360779965	KU	4	40 BRO	SP	CRE	ID,IP,RB	BD		11/10/2035

2020 PO9381279815	KU	4	40 BRO	SP	CRE	HH,IP,RB	VX	RP2	11/11/2035
2020 PO9441779625	KU	4	40 BRO	SP	CRE	ID	BD		11/12/2035
2020 PO9182680802	F	4	40 BRO	SP	CRE		VX	RP2	11/13/2035
2020 PO9441279581	KU	6	30 OTH	SP	CCA		V		11/14/2035
2020 PO9022381338	KU	4	45 BRO	SP	CCA		V		11/15/2035
2020 PO9035881216	KU	3	45 BRO	SP	CRE	ED	TD		11/16/2035
2020 PO9035881216-A	KU	3	45 BRO	SP	CCA		V		11/17/2035
2020 PO9046381131	KU	4	45 BRO	SP	P	ED	T		11/18/2035
2020 PO8184071397	KU	2	65 BRO	SP	CRE	ED,ID	BD		11/19/2035
2020 PO4125502688	KU	4	45 XXX	SP	CRE	ED,ID	TD		11/20/2035
2020 PO4133202664	KU	5	35 XXX	SP	CRE	ED,ID	TD		11/21/2035
2020 PO4157002597	KU	4	40 XXX	SP	CRE	ED,ID	TD		11/22/2035
2020 PO4128002548	KU	6	30 BRN	SP	CCA		V		11/23/2035
2020 PO4126202461	KU	6	30 XXX	SP	CRE	ED,ID	TD		11/24/2035
2020 PO3978306202	KU	5	35 XXX	SP	CRE	ED,ID	TD		11/25/2035
2020 PO4007106229	KU	3	40 BRN	SP	CRE	ED,ID	TD		11/26/2035
2020 PO4001706363	KU	5	35 BRN	SP	CRE	ED,ID	TD		11/27/2035
2020 PO3990606134	KU	5	35 BRN	SP	CCA		V		11/28/2035
2020 PO4061806333	KU	4	40 BRN	SP	CRE		V		11/29/2035
2020 PO7038288552	KU	4	40 BRO	SP	S		V		11/30/2035
2020 PO7044488512	KU	5	35 BRO	SP	CRE	ED,ID	BD		12/1/2035
2020 PO7046788509	KU	4	45 BRO	SP	CRE	ED,ID	BD		12/2/2035
2020 PO7051988579	KU	3	45 BRO	SP	S		V		12/3/2035
2020 PO9860038271A	ODP	3	45 BRN	SP	CCA		V		12/4/2035
2020 PO9831738295A	ODP	3	45 BRN	SP	CCA		V		12/5/2035
2020 PO9798538195A	ODP	3	45 BRN	SP	CCA		V		12/6/2035
2020 PO9762038021A	ODP	2	50 BRN	SP	CCA		V		12/7/2035
2020 PO9736538051A	ODP	3	45 BRN	SP	CCA		V		12/8/2035
2020 PO9706137992A	ODP	2	50 BRN	SP	CCA		V		12/9/2035
2020 PO9720637736A	ODP	2	50 BRN	SP	CCA		V		12/10/2035
2020 PO9736137358	ODP	3	40 BRN	SP	CRE		V		12/11/2035
2020 PO9733737210	ODP	2	50 BRN	SP	CCA		V		12/12/2035
2020 PO9840938320	ODP	2	50 BRN	SP	CCA		V		12/13/2035
2020 PO9745037641	ODP	2	55 BRN	SP	CCA		V		12/14/2035
2020 PO9737137427	ODP	2	50 BRN	SP	CCA		V		12/15/2035
2020 PO3944483141	F	4	40 BRO	SP	CCA		V		12/16/2035
2020 PO3944483125	F	4	40 BRO	SP	P		V		12/17/2035
2020 PO3945283126	F	5	30 BRO	SP	A		V		12/18/2035
2020 PO3944583109	F	4	40 BRO	SP	P		V		12/19/2035
2020 PO4008582510	LGE	4	40 BRN	SP	P	ED,ID	TD		12/20/2035
2020 PO2292246321	KU	3	45 BRN	SP	CRE	ID,IP	BD		12/21/2035
2020 PO2305846636	KU	4	40 BRN	SP	CRE	ED,HH,ID,IP	X	RP1	12/22/2035
2020 PO2305846636-A	KU	4	40 BRN	SP	CCA		V		12/23/2035
2020 PO2338047434	KU	4	40 BRN	SP	CRE	ID	BD		12/24/2035
2020 PO2359847966	KU	3	55 BRN	SP	CRE	ED,ID,IP	TD		12/25/2035
2020 PO2361047887	KU	5	35 BRN	SP	CCA		V		12/26/2035
2020 PO2681642976	KU	4	40 BRN	SP	CRE	ED,ID,MD,SRC	TD		12/27/2035

2020 PO2674643290	KU	4	45 BRN	SP	CCA		V		12/28/2035	
2020 PO2650043606	KU	4	40 BRN	SP	CRE	ED,ID,IP,MD	TD		12/29/2035	
2020 PO2625443921	KU	3	45 BRN	SP	CCA		V		12/30/2035	
2020 PO3945283094	F	5	25 BRO	SP	A		V		12/31/2035	
2020 PO3944583093	F	4	40 BRO	SP	A		V		1/1/2036	
2020 PO3944583085	F	3	45 BRO	SP	A		VX	RP1	1/2/2036	
2020 PO4030482779	LGE	4	40 BRN	SP	CCA		V		1/3/2036	
2020 PO4834186409	LGE	4	40 XXX	SP	P	ED,ID	BD		1/4/2036	
2020 PO4031182788	F	4	30 BRN	SP	CCA		V		1/5/2036	
2020 PO4031282783	F	4	40 BRN	SP	CRE		V		1/6/2036	
2020 PO4033382789	F	3	45 BRN	SP	A		V		1/7/2036	
2020 PO0376234337	ODP	4	45 XXX	SP	CRE	ED,ID	TD		1/8/2036	
2020 PO4035282792	F	3	45 BRN	SP	A		V		1/9/2036	
2020 PO4034782812	F	3	45 BRN	SP	S		V		1/10/2036	
2020 PO3943782894	F	4	40 BRO	SP	P		V		1/11/2036	
2020 PO3942582901	F	4	40 BRO	SP	P		V		1/12/2036	
2020 PO0346034814	ODP	4	45 XXX	SP	CCA		V		1/13/2036	
2020 0378834705a	ODP	6	30 XXX	SP	CRE	ID	BD		1/14/2036	
2020 PO0354334505	ODP	5	35 XXX	SP	CRE	ED,ID	TD		1/15/2036	
2020 PO0337734557	ODP	4	40 XXX	SP	CCA		V		1/16/2036	
2020 PO0378834705	ODP	4	40 XXX	SP	CRE	ED,ID	TD		1/17/2036	
2020 PO0381634876	ODP	4	45 XXX	SP	CCA		V		1/18/2036	
2020 PO0385735024	ODP	6	30 XXX	SP	CRE		V		1/19/2036	
2020 PO3941282907	F	4	40 BRO	SP	A		V		1/20/2036	
2020 PO3940882901	F	5	25 BRO	SP	CCA		V		1/21/2036	
2020 PO4833686414	LGE	4	40 XXX	SP	P	ID	BD		1/22/2036	
2020 PO4834686429	LGE	4	35 XXX	SP	CCA		V		1/23/2036	
2020 PO4833786427	LGE	3	45 XXX	ST	CCA		V		1/24/2036	
2020 PO4833986426	LGE	3	45 XXX	SP	CCA	ED	T		1/25/2036	
2020 PO4834086428	LGE	3	45 XXX	SP	CCA	ED	T		1/26/2036	
2020 PO4834086429	LGE	3	45 XXX	SP	P	ID	TD		1/27/2036	
2020 PO4833186432	LGE	4	40 XXX	SP	P	ID	BD		1/28/2036	
2020 PO4831686432	LGE	4	35 XXX	SP	P	ID	TD		1/29/2036	
2020 PO4831486453	LGE	3	50 XXX	SP	CCA		V		1/30/2036	
2020 PO4879487701	LGE	4	35 XXX	SP	P	ED,ID,SR	TD		1/31/2036	
2020 PO4675989076	LGE	4	40 BRO	SP	CCA		V		2/1/2036	
2020 PO4673889058	LGE	4	40 BRO	SP	CCA		V		2/2/2036	
2020 PO4858686728	LGE	4	40 OTH	SP	P	ED,ID,SRS	TD		2/3/2036	
2020 PO4856686723	LGE	4	40 OTH	SP	CRE	ED,SRS	TD		2/4/2036	
2020 PO4808287684	LGE	4	40 BRN	SP	P	ED,ID	TD		2/5/2036	
2020 PO4900987140	LGE	4	40 OTH	AL	CCA		V		2/6/2036	
2020 PO3940082914	F	4	40 BRO	SP	P		V		2/7/2036	
2020 PO4897187175	LGE	4E	40E	OTH	SP	CRE	ED,ID,SR	TX	RR	2/8/2036
2020 PO4667436946	KU	2	45 BRO	SP	CCA		V		2/9/2036	
2020 PO4034282828	F	3	45 BRN	SP	S		V		2/10/2036	
2020 PO4570136395	KU	1	55 BRO	SP	CCA		V		2/11/2036	
2020 PO4558036227	KU	4	45 BRO	SP	CRE		V		2/12/2036	

2020 PO4558036227-B	KU	3	45 BRO	SP	CCA		V		2/13/2036
2020 PO4558036227-A	KU	3	45 BRO	SP	CCA		V		2/14/2036
2020 PO4548136078-A	KU	1	55 BRO	SP	CCA		V		2/15/2036
2020 PO4548136078	KU	4	45 BRO	SP	CCA		V		2/16/2036
2020 PO4547035987	KU	2	45 BRO	SP	CCA		V		2/17/2036
2020 PO4544335958	KU	2	45 BRO	SP	CCA		V		2/18/2036
2020 PO4033882843	F	4	40 BRN	SP	CCA		V		2/19/2036
2020 PO4036182831	LGE	4	45 BRN	SP	S		V		2/20/2036
2020 PO4038482866	LGE	3 45E	BRN	SP	S		V		2/21/2036
2020 PO3937782926	F	4	40 BRO	SP	P		V		2/22/2036
2020 PO3938882920	F	4	40 BRO	SP	A		V		2/23/2036
2020 PO3930482620	LGE	4	40 BRO	SP	CRE	ED,ID	BD		2/24/2036
2020 PV3929982607	LGE	4	40 BRO	SP	P	ED,ID	BD		2/25/2036
2020 PO4901187178	LGE	4	40 OTH	SP	CCA		V		2/26/2036
2020 PO4900887187	LGE	3	45 OTH	SP	P	ED,ID,SRS	TD		2/27/2036
2020 PO4675889089	LGE	4	30 BRO	SP	A	ED,ID,IP	TD		2/28/2036
2020 PO4808687669	LGE	4	40 BRN	SP	CRE	ED,ID	BD		2/29/2036
2020 PO4808487664	LGE	4	35 BRN	SP	CRE	ED,ID	BD		3/1/2036
2020 PO4808687653	LGE	4	30 BRN	SP	CRE	ED,ID	BD		3/2/2036
2020 PO4808887644	LGE	4	30 BRN	SP	CRE	ED,ID,IP	BD		3/3/2036
2020 PO4871886749	F	1	50 OTH	SP	CCA		V		3/4/2036
2020 PO4854786718	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD		3/5/2036
2020 PO4871486763	F	1	50 OTH	SP	CCA		V		3/6/2036
2020 PO4872186736	F	1	50 OTH	SP	CCA		V		3/7/2036
2020 PO4871786737	LGE	4	40 OTH	SP	P	ED,ID,SRS	TD		3/8/2036
2020 PO4872586719	F	1	55 OTH	SP	CCA		V		3/9/2036
2020 4878587643a	F	4	40 KOP	SP	A		V		3/10/2036
2020 PO4880187648	LGE	4	40 XXX	SP	CRE	ID	BD		3/11/2036
2020 PO4880687649	LGE	4	40 XXX	SP	CRE	ED,ID	TD		3/12/2036
2020 PO3930882631	F	4	40 BRO	SP	CCA		V		3/13/2036
2020 PO3931782642	LGE	4	30 BRO	SP	CCA		V		3/14/2036
2020 PO3931682646	LGE	3	35 BRO	SP	CCA		V		3/15/2036
2020 PO3931482643	LGE	3	50 BRO	SP	CRE	ED,ID,IP,RB	X	RP1	3/16/2036
2020 PO3960083240	F	5	40 BRO	SP	P		V		3/17/2036
2020 PO3959283241	F	4	40 BRO	SP	P		V		3/18/2036
2020 PO3929382642	F	4	40 BRO	SP	CCA		V		3/19/2036
2020 PO3928382647	F	4	40 BRO	SP	CCA		V		3/20/2036
2020 PO3927282652	F	4	40 BRO	SP	CCA		V		3/21/2036
2020 PO3926182657	F	3	45 BRO	SP	CCA		V		3/22/2036
2020 PO3922982672	F	4	40 BRO	SP	CCA		V		3/23/2036
2020 PO3921882677	F	4	40 BRO	SP	CCA		V		3/24/2036
2020 PO3918282689	F	4	40 BRO	SP	CCA		V		3/25/2036
2020 PO3918082694	F	4	40 BRO	SP	CCA		V		3/26/2036
2020 PO3919682688	F	4	40 BRO	SP	CCA		V		3/27/2036
2020 PO4537835919	KU	2	45 BRO	SP	CCA		V		3/28/2036
2020 PO4549835814	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		3/29/2036
2020 PO4552935845-A	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD		3/30/2036

2020 PO4552935845	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	3/31/2036
2020 PO4555635872	KU	3	45 BRO	SP	CCA		V	4/1/2036
2020 PO4558935904	KU	3	45 BRO	SP	CCA		V	4/2/2036
2020 PO3958483241	F	4	40 BRO	SP	P		V	4/3/2036
2020 PO3956983242	F	4	40 BRO	SP	P		V	4/4/2036
2020 PO3956483238	F	4	30 BRO	SP	P		V	4/5/2036
2020 PO4033382860	F	3	45 BRN	SP	S		V	4/6/2036
2020 PO4033082871	F	3	45 BRN	SP	S		V	4/7/2036
2020 PO3955883246	LGE	4	30 BRO	SP	A	ED,ID	TD	4/8/2036
2020 PO4032782881	F	3	45 BRN	SP	S		V	4/9/2036
2020 PO4032082913	F	4	40 BRN	SP	A		V	4/10/2036
2020 PO4031682928	F	4	40 BRN	SP	A		V	4/11/2036
2020 PO0389535114	F	4	40 XXX	SP	A		V	4/12/2036
2020 PO0396035060	ODP	6	30 BRN	SP	CCA		V	4/13/2036
2020 PO3955283238	LGE	5	25 BRO	SP	A	ED,ID	TD	4/14/2036
2020 PO3955283243	F	5	35 BRO	SP	A		V	4/15/2036
2020 PO3954883243	F	4	35 BRO	SP	P		V	4/16/2036
2020 PO3954083243	F	4	40 BRO	SP	P		V	4/17/2036
2020 PO4032182945	F	4	40 BRN	SP	S		V	4/18/2036
2020 PO4031382943	F	4	40 BRN	SP	A		V	4/19/2036
2020 PO3952683244	F	4	35 BRO	SP	P		V	4/20/2036
2020 PO3952683241	F	4	30 BRO	SP	P		V	4/21/2036
2020 PO3951183244	F	4	40 BRO	SP	P		V	4/22/2036
2020 PO3951083240	F	4	30 BRO	SP	P		V	4/23/2036
2020 PO3950283245	F	4	40 BRO	SP	P		V	4/24/2036
2020 PO3963283262	F	4	35 BRO	SP	P		V	4/25/2036
2020 PO3963783261	F	5	45 BRO	SP	A		V	4/26/2036
2020 PO4028482930	F	4	40 BRN	SP	CCA		V	4/27/2036
2020 PO4027882921	F	3	40 BRN	SP	A		V	4/28/2036
2020 PO4027282911	F	3	40 BRN	SP	CRE		V	4/29/2036
2020 PO4026482897	F	3	40 BRN	SP	CCA		V	4/30/2036
2020 PO4025682884	F	4	40 BRN	SP	CRE		V	5/1/2036
2020 PO3936083119	F	4	40 BRO	SP	A		V	5/2/2036
2020 PO3939183130	LGE	4	30 BRO	SP	P	ED,ID,IP,RB	TX	RR 5/3/2036
2020 PO3935983135	LGE	5	25 BRO	SP	A		V	5/4/2036
2020 PO3634049339	F	3	45 ACE	SP	CCA		V	5/5/2036
2020 PO4051901203	F	4	40 BRO	SP	CRE		V	5/6/2036
2020 PO4069101137	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	5/7/2036
2020 PO4068901239	F	4	40 BRO	SP	CCA		V	5/8/2036
2020 PO4052102054	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	5/9/2036
2020 PO4048702288	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	5/10/2036
2020 PO3637349511a	KU	3	45 ACE	SP	CCA		V	5/11/2036
2020 PO4640788884	LGE	4	40 BRO	SP	A	ED	TD	5/12/2036
2020 PO4663188527	F	4	40 BRN	SP	CRE		V	5/13/2036
2020 PO4663888517	F	4	40 BRN	SP	CCA		V	5/14/2036
2020 PO4664588506	F	4	40 BRN	SP	CRE		V	5/15/2036
2020 PO4665288496	F	4	40 BRN	SP	CRE		V	5/16/2036

2020 PO4665988481	F	4	40 BRN	SP	CRE		V	5/17/2036	
2020 PO4666888474	F	4	40 BRN	SP	CRE		V	5/18/2036	
2020 PO1584439303	ODP	6	30 BRN	SP	CCA		V	5/19/2036	
2020 PO3591347778	KU	6	30 BRO	SP	P	ED	T	5/20/2036	
2020 PO3943782095	LGE	4	40 BRN	SP	CCA	ED,ID	BD	5/21/2036	
2020 PO4029382945	F	3	45 BRN	SP	CCA		V	5/22/2036	
2020 PO4028582950	LGE	4	30 BRN	SP	CRE	ED,ID	TD	5/23/2036	
2020 PO4027182950	F	1	50 BRN	SP	S		V	5/24/2036	
2020 PO3940982986	F	4	40 BRO	SP	CCA		V	5/25/2036	
2020 PO3941782983	F	5	25 BRO	SP	P		V	5/26/2036	
2020 PO3643647128	KU	5	35 BRO	SP	CRE	ID	TD	5/27/2036	
2020 PO1804241707	ODP	4	40 KOP	SP	CRE	ED,ID,IP	TD	5/28/2036	
2020 PO1801641517	ODP	4	40 KOP	SP	CRE	ED,ID	TD	5/29/2036	
2020 PO3672347347	KU	4	45 BRO	SP	P	ED	T	5/30/2036	
2020 PO3943982084	LGE	4	40 BRN	SP	CRE	ED,ID	TD	5/31/2036	
2020 PO3941982083	LGE	4	40 BRN	SP	CRE	ED,ID	TD	6/1/2036	
2020 PO3941782078	LGE	4	40 BRN	SP	CRE	ED,ID	TD	6/2/2036	
2020 PO3943282080	LGE	4	40 BRN	SP	CRE	ED,ID	TD	6/3/2036	
2020 PO3943582072	LGE	4	40 BRN	SP	CRE	ED,ID	BD	6/4/2036	
2020 PO3674647657	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/5/2036	
2020 PO4254987653	KU	4	40 KOP	DF	CRE	ED,ID,MD,RB,SRC	TX	RR	6/6/2036
2020 PO0230435291	ODP	2	55 XXX	SP	CCA		V	6/7/2036	
2020 PO0208534901	ODP	4	40 XXX	SP	CRE	ED,ID	TD	6/8/2036	
2020 PO0201435061	ODP	2	50 XXX	SP	CCA		V	6/9/2036	
2020 PO0200934770	ODP	2	50 XXX	SP	CCA		V	6/10/2036	
2020 PO4023582880	LGE	4	35 BRN	SP	CRE	ED,ID	TD	6/11/2036	
2020 PO3421440789	KU	5	35 BRN	SP	CRE	ED,ID,MD	TD	6/12/2036	
2020 PO3453340886	KU	6	30 BRN	SP	P	ED	T	6/13/2036	
2020 PO3441540665	KU	6	30 BRN	SP	P	ED	T	6/14/2036	
2020 PO3465041101	KU	2	50 BRN	SP	CCA		B	6/15/2036	
2020 PO3495141621	KU	2	50 BRN	SP	CRE	ID,IP	BX	RP2	6/16/2036
2020 PO3220039519	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD	6/17/2036	
2020 PO2980649026	KU	4	40 BRN	SP	CRE	ID,IP	BD	6/18/2036	
2020 PO4015782794	LGE	1	50 BRN	SP	S		V	6/19/2036	
2020 PO4016282796	LGE	1	50 BRN	SP	S		V	6/20/2036	
2020 PO4017682807	LGE	1	50 BRN	SP	S		V	6/21/2036	
2020 PO4017182792	LGE	4	40 BRN	SP	A	ED,ID	BD	6/22/2036	
2020 PO4257687480	KU	3	45 KOP	SP	S		V	6/23/2036	
2020 PO4233587457	KU	4	40 KOP	SP	CRE	ED,ID	TD	6/24/2036	
2020 PO4226487567	KU	6	30 KOP	SP	S		V	6/25/2036	
2020 PO4168786713	KU	4	45 KOP	SP	CRE	ED,ID	TD	6/26/2036	
2020 PO3949587052	KU	5	30 KOP	SP	CRE		V	6/27/2036	
2020 PO4699888452	LGE	4	40 BRN	SP	CRE	ED,HH,ID,RB	BX	PX	6/28/2036
2020 PO0392378662	KU	1	60 XXX	SP	CCA		V	6/29/2036	
2020 PO0379678590	KU	2	55 XXX	SP	CCA		V	6/30/2036	
2020 PO0371878548	KU	3	55 XXX	SP	CRE	ID	BD	7/1/2036	
2020 PO0357678468	KU	1	60 XXX	SP	CCA		V	7/2/2036	

2020 0336878350a	KU	1	55 XXX	SP	CCA		V	7/3/2036	
2020 PO0336878350	KU	1	55 XXX	SP	CCA		V	7/4/2036	
2020 PO4698888473	LGE	4	35 BRN	SP	CRE	ED,ID	TD	7/5/2036	
2020 PO4698688468	LGE	4	40 BRN	SP	CCA		V	7/6/2036	
2020 PO4016382785	LGE	4	35 BRN	SP	CRE	ED,ID	BD	7/7/2036	
2020 PO9236571711	KU	5E	40E OTH	SP	CRE	ED,ID,SRS	TD	7/8/2036	
2020 PO3943382060	LGE	4	40 BRN	SP	CRE	ED,ID	TD	7/9/2036	
2020 PO3942882037	LGE	4	40 BRN	SP	CRE	ED,ID	TD	7/10/2036	
2020 PO3943182059	LGE	4	40 BRN	SP	P	ED,ID	T	7/11/2036	
2020 PO3940482039	LGE	4	40 BRN	SP	P	ED,ID	TD	7/12/2036	
2020 PO3940582045	LGE	4	40 BRN	SP	CCA		V	7/13/2036	
2020 PO3942282035	LGE	4	40 BRN	SP	CRE	ED,ID,IP,RB	TX	RR	7/14/2036
2020 PO3942582025	LGE	4	40 BRN	SP	CRE	ED,ID	TD	7/15/2036	
2020 PO3942282013	LGE	4	40 BRN	SP	CRE	ED,ID	TD	7/16/2036	
2020 PO0242634915	ODP	5	35 XXX	SP	CRE	ED,ID	TD	7/17/2036	
2020 PO0230634948	ODP	4	35 ACW	SP	CRE	ID,RB	X	RP1	7/18/2036
2020 PO4015182779	LGE	4	35 BRN	SP	A	ED,ID	BD	7/19/2036	
2020 PO4014782789	LGE	4	45 BRN	SP	CRE	ED,ID	TD	7/20/2036	
2020 PO4012782778	LGE	4	40 BRN	SP	CCA	ED,HH,ID	BX	PX	7/21/2036
2020 PO4014282770	LGE	4	40 BRN	SP	CRE	ED,ID	TD	7/22/2036	
2020 PO1831840213	ODP	4	45 KOP	SP	CRE	ED,ID	TD	7/23/2036	
2020 PO1809640122	ODP	4	45 KOP	SP	S		V	7/24/2036	
2020 PO9236571711A	KU	6	30 OTH	SP	CCA		V	7/25/2036	
2020 PO4696788459	LGE	4	40 BRN	SP	CRE	ED,ID	TD	7/26/2036	
2020 PO4838488121A	LGE	4	30 BRO	SP	CCA		V	7/27/2036	
2020 PO4838488121	LGE	4	35 BRO	SP	CRE	ED	TD	7/28/2036	
2020 PO4838488129	LGE	4	30 BRO	SP	CRE	ED,EP	TD	7/29/2036	
2020 PO0316078233	KU	1	55 XXX	SP	CCA		V	7/30/2036	
2020 0295178119a	KU	1	60 XXX	SP	CCA		V	7/31/2036	
2020 PO0295178119	KU	1	55 XXX	SP	CCA		V	8/1/2036	
2020 PO4833388144	F	4	40 BRO	SP	A		V	8/2/2036	
2020 PO4834788150	F	4	40 BRO	SP	A		V	8/3/2036	
2020 PO4836388155	F	4	40 BRO	SP	A		V	8/4/2036	
2020 PO4838288162	F	4	40 BRO	SP	CRE		V	8/5/2036	
2020 PO4839788164	F	4	35 BRO	SP	CRE		V	8/6/2036	
2020 PO4839688167	F	4	40 BRO	SP	P		V	8/7/2036	
2020 PO4841088172	F	4	40 BRO	SP	CRE		V	8/8/2036	
2020 PO4842488178	F	4	40 BRO	SP	CCA		V	8/9/2036	
2020 PO4843488181	F	4	40 BRO	SP	P		V	8/10/2036	
2020 PO3939582991	F	3	45 BRO	SP	CCA		V	8/11/2036	
2020 PO4686888530	LGE	4	40 BRN	SP	A	ED,ID	BX	RR	8/12/2036
2020 PO9671636591	F	4	40 BRO	SP	CRE		V	8/13/2036	
2020 PO4682588072	LGE	4	35 BRN	SP	CRE	ED,ID	BD	8/14/2036	
2020 PO3554589383	KU	4	40 XXX	SP	CRE	ID	TD	8/15/2036	
2020 PO356689303	KU	6	30 XXX	SP	CRE	ID	TD	8/16/2036	
2020 PO3567489276	F	5	35 XXX	SP	P		V	8/17/2036	
2020 PO3564789260	KU	4	40 XXX	SP	CRE	ID	TD	8/18/2036	

2020 PO3569689201	KU	4	40 XXX	SP	CRE	ID	TD		8/19/2036
2020 PO3550789070	KU	4	40 XXX	SP	CRE	ID	TD		8/20/2036
2020 PO7577139799	KU	5	35 OTH	SP	CRE	ID	TD		8/21/2036
2020 PO7521740262	KU	4	45 OTH	SP	CRE	ID	TD		8/22/2036
2020 PO4685688079	LGE	4	35 BRN	SP	CRE	ED,ID,IP	BD		8/23/2036
2020 PO4684588080	LGE	4	35 BRN	SP	CRE	ED,ID	BD		8/24/2036
2020 PO4683888080	LGE	4	35 BRN	SP	CRE	ED,ID,IP	TD		8/25/2036
2020 PO1633219638	F	4	40 BRO	SP	CRE		V		8/26/2036
2020 PO1685819634	ODP	4	40 BRO	SP	CRE	ID	BD		8/27/2036
2020 PO6246218728	KU	4	40 XXX	SP	CRE	ED,ID,RB	X	RP1	8/28/2036
2020 PO4685388113	LGE	4	30 BRN	DF	A	ED,ID	TD		8/29/2036
2020 PO4685988113	LGE	3	45 BRN	SP	S		V		8/30/2036
2020 PO6243619020	KU	4	40 XXX	SP	CRE	ED,ID	TD		8/31/2036
2020 PO6240719416	KU	5	45 XXX	SP	CRE	ID	BD		9/1/2036
2020 PO6241119683	KU	5	40 XXX	SP	CRE	ED,ID	TD		9/2/2036
2020 PO4682788103	LGE	4	40 BRN	SP	A	ED,ID	BD		9/3/2036
2020 PO4683188112	LGE	4	40 BRN	SP	A	ED,ID	BD		9/4/2036
2020 PO7564440189	KU	5	35 OTH	SP	CRE		V		9/5/2036
2020 PO7556040371	KU	4	40 OTH	SP	CCA		V		9/6/2036
2020 PO7570940004	KU	4	40 OTH	SP	CRE	ID	TD		9/7/2036
2020 PO6224319870	KU	4	40 XXX	SP	CRE	ED,ID	TD		9/8/2036
2020 PO1365031162A	ODP	4	40 BRN	SP	CRE	ID	BD		9/9/2036
2020 PO7573440576	F	4	40 OTH	SP	CCA		V		9/10/2036
2020 PO7559140546	F	5	40 OTH	SP	CRE	ED,EP,ID,IP	BX	RP3	9/11/2036
2020 PO7573440467	KU	6	30 OTH	SP	CRE	ID	TD		9/12/2036
2020 PO4675388092	LGE	4	40 BRN	SP	CRE	ED,ID	BD		9/13/2036
2020 PO4677488080	LGE	4	35 BRN	SP	CRE	ED,ID	BX	RR	9/14/2036
2020 PO4673488079	LGE	4	40 BRN	SP	A	ED,ID	BD		9/15/2036
2020 PO4674288084	LGE	3	45 BRN	SP	A	ED,ID	BD		9/16/2036
2020 PO6212920027	KU	5	40 XXX	SP	CRE	ED,ID	TD		9/17/2036
2020 PO6205020105	KU	5	40 XXX	SP	CRE	ED,ID	TD		9/18/2036
2020 PO6192520202	KU	5	40 XXX	SP	CRE	ED,ID,IP,SRC	TD		9/19/2036
2020 PO3531788939	KU	4	40 XXX	SP	CRE	ID	TD		9/20/2036
2020 PO3516088842	KU	4	40 XXX	SP	CCA	ED	T		9/21/2036
2020 PO3480789156	KU	4	40 XXX	SP	CCA		V		9/22/2036
2020 PO8573838700	ODP	6	30 BRO	SP	CRE	ID	BD		9/23/2036
2020 PO8577539209	ODP	5	35 BRO	SP	CRE	ED,ID	TD		9/24/2036
2020 PO8587238944	ODP	4	40 BRO	SP	CRE	ID	BD		9/25/2036
2020 PO4675388058	LGE	4	35 BRN	SP	CCA		V		9/26/2036
2020 PO4665188083	LGE	4	30 BRN	SP	A	ED,ID	TX	RR	9/27/2036
2020 PO4663388056	LGE	4	35 BRN	SP	CRE	ED,ID	BD		9/28/2036
2020 PO3729490964	KU	4	40 XXX	SP	CRE	ID	TD		9/29/2036
2020 PO3717890887	F	4	40 XXX	SP	CRE		V		9/30/2036
2020 PO3686890569	KU	4	40 XXX	SP	CRE	ID	TD		10/1/2036
2020 PO4695588842	LGE	4	40 BRO	SP	CRE	ID,IP	BD		10/2/2036
2020 PO4695888836	LGE	3	45 BRO	SP	CRE	ID	BD		10/3/2036
2020 PO8466235088	ODP	5	30 XXX	SP	CRE		V		10/4/2036

2020 PO8490235335	ODP	6	30 XXX	SP	CRE		V				10/5/2036
2020 PO8505935531	F	4	40 XXX	SP	P		V				10/6/2036
2020 PO8477035761	ODP	5	35 XXX	SP	CRE		V				10/7/2036
2020 PO8461435709	ODP	4	40 XXX	SP	CRE		V				10/8/2036
2020 PO8490435508	F	5	40 XXX	SP	P	ID	V				10/9/2036
2020 PO8439435565	ODP	6	30 XXX	SP	CRE		V				10/10/2036
2020 PO8629836762	ODP	5	35 BRO	SP	S		V				10/11/2036
2020 PO8629936820	ODP	4	40 BRO	SP	S		V				10/12/2036
2020 PO8638737071	ODP	5	35 BRO	DF	CRE	ID	BD				10/13/2036
2020 PO8593436977	ODP	6	30 BRO	SP	CRE	ID	BD				10/14/2036
2020 PO3645189773	KU	3	45 XXX	SP	CRE	ID,IP	TX		RR		10/15/2036
2020 PO3626989635	KU	4	40 XXX	SP	CRE	ID	TD				10/16/2036
2020 PO3609689506	KU	4	45 XXX	SP	CRE	ID	TD				10/17/2036
2020 PO3599689428	KU	3	45 XXX	SP	CRE	ID,IP	TX		RR		10/18/2036
2020 PO3581489459	KU	6	30 XXX	SP	CRE	ID	TD				10/19/2036
2020 PO3585789390	F	5	35 XXX	SP	A		V				10/20/2036
2020 PO3572189439	KU	5	35 XXX	SP	CCA		V				10/21/2036
2020 PO3586489328	F	4	40 XXX	SP	CRE		V				10/22/2036
2020 PO3603889171	KU	5	35 XXX	SP	CCA		V				10/23/2036
2020 PO3594589220	F	4	40 XXX	SP	CRE		V				10/24/2036
2020 PO3638688697	KU	4	40 XXX	SP	CCA		V				10/25/2036
2020 PO3635688813	KU	4	40 XXX	SP	CCA		V				10/26/2036
2020 PO3623288985	KU	4	40 XXX	SP	CCA		V				10/27/2036
2020 PO3613289151	KU	4	40 XXX	SP	CCA		V				10/28/2036
2020 PO4670888879	LGE	4	40 BRO	SP	A	ED	TD				10/29/2036
2020 PO9244530732	ODP	5	30 BRO	SP	CRE		V				10/30/2036
2020 PO3904182614	LGE	4	40 BRO	SP	CRE	ED,ID	TD				10/31/2036
2020 PO3905182627	LGE	3	45 BRO	SP	A	ED,ID	TD				11/1/2036
2020 PO3904482632	LGE	4	30 BRO	SP	A	ED,ID	TD				11/2/2036
2020 PO3903682630	LGE	4	40 BRO	SP	CCA		V				11/3/2036
2020 PO3902582528	F	3	45 BRO	SP	CCA		V				11/4/2036
2020 PO3901782523	F	4	40 BRO	SP	CCA		V				11/5/2036
2020 PO9181245306	ODP	3	45 BRN	SP	CCA		V				11/6/2036
2020 PO9170045596A	ODP	5	35 BRN	SP	CCA		V				11/7/2036
2020 PO9170045596	ODP	3	45 BRN	SP	CCA		V				11/8/2036
2020 PO3035451315	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD				11/9/2036
2020 PO9156845765	ODP	3	45 BRN	SP	CCA		V				11/10/2036
2020 PO9134546055	ODP	3	45 BRN	SP	CCA		V				11/11/2036
2020 PO2394426029	ODP	4	40 BRN	SP	CRE	ID	TD				11/12/2036
2020 PO2472026585	ODP	4	40 BRN	SP	CRE	ID	TD				11/13/2036
2020 PO2497426398	ODP	4	40 BRN	SP	CRE	ID	TD				11/14/2036
2020 PO9106446139	ODP	3	45 BRN	SP	CCA		V				11/15/2036
2020 PO3958382796	LGE	3	50 BRN	SP	CRE	ED,ID	BD				11/16/2036
2020 PO4731588103	F	4	40 BRO	SP	CRE		V				11/17/2036
2020 PO4729388087	F	3	45 BRO	SP	CCA		V				11/18/2036
2020 PO4730588096	F	3	45 BRO	SP	CCA		V				11/19/2036
2020 PO3966890929	KU	2	45 KOP	SP	CRE		V				11/20/2036

2020 PO3984090996	KU	2	45 KOP	SP	CRE		V			11/21/2036
2020 PO3986291055	F	4	40 KOP	SP	CRE		V			11/22/2036
2020 PO39860 91383A	KU	5	35 KOP	SP	S		V			11/23/2036
2020 PO3978891568	F	4	40 KOP	SP	CRE		V			11/24/2036
2020 PO3986091383	F	4	40 KOP	SP	CRE		V			11/25/2036
2020 PO3991491243	F	4	40 KOP	SP	CRE		V			11/26/2036
2020 PO3998791180	F	4	40 KOP	SP	CRE		V			11/27/2036
2020 PO3994791159	F	4	40 KOP	SP	P		V			11/28/2036
2020 PO3998991052	F	4	40 KOP	SP	CRE		V			11/29/2036
2020 PO4000191019	KU	6	30 KOP	SP	S		V			11/30/2036
2020 PO4026091155	F	4	40 KOP	SP	CRE		V			12/1/2036
2020 PO4023591146	KU	4	40 KOP	SP	S		V			12/2/2036
2020 PO4021991173	KU	5	30 KOP	SP	S		V			12/3/2036
2020 PO4030591220	KU	5	30 KOP	SP	CRE		V			12/4/2036
2020 PO3958682805	LGE	1	95 BRN	SP	CRE		V			12/5/2036
2020 PO5699108915	KU	5	40 XXX	SP	CRE	ED,ID,IP	TX		RR	12/6/2036
2020 PO3959182814	LGE	3	50 BRN	SP	A	ED,ID	TD			12/7/2036
2020 PO2959351089	KU	4	40 BRO	SP	CRE	ID,IP	BD			12/8/2036
2020 PO2972651313	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			12/9/2036
2020 PO3953181815	LGE	4	30 BRN	SP	CRE	ED,HH,ID,MD,RB	VX		PX	12/10/2036
2020 PO3952981818	LGE	4	40 BRN	SP	CRE	ED,ID	TD			12/11/2036
2020 PO3952881816	LGE	3	45 BRN	SP	CCA		V			12/12/2036
2020 PO3959882831	LGE	4	50 BRN	SP	CRE	ED,ID	TD			12/13/2036
2020 PO3960282840	LGE	1	90 BRN	SP	CCA		V			12/14/2036
2020 PO2497526607	ODP	4	40 BRN	SP	CRE	ID	TD			12/15/2036
2020 PO2496626892	ODP	4	40 BRN	SP	CRE	ID	TD			12/16/2036
2020 PO2495127243	ODP	4	40 BRN	SP	CRE	ID	TD			12/17/2036
2020 PO1179636398	ODP	5	35 BRN	SP	CRE	ED,ID	TD			12/18/2036
2020 PO1177136312	ODP	5	35 XXX	SP	CRE	ED,ID	TD			12/19/2036
2020 PO1140936417	ODP	6	30 XXX	SP	CRE	ED,ID	TD			12/20/2036
2020 PO1201236478	F	4	40 XXX	SP	A		V			12/21/2036
2020 PO1206436601	F	4	40 KOP	SP	A		V			12/22/2036
2020 PO1204236644	F	4	40 KOP	SP	CRE		V			12/23/2036
2020 PO1212636708	ODP	6	30 BRN	SP	CRE	ED,ID	TD			12/24/2036
2020 PO3960582850	LGE	3	50 BRN	SP	A	ED,ID	TD			12/25/2036
2020 PO6432904111	KU	6	30 UNK	SP	CRE	ID	TD			12/26/2036
2020 PO6451604540	F	6	30 UNK	SP	CCA		V			12/27/2036
2020 PO6407404108	KU	6	30 KOP	SP	CRE	ED,ID,SRS	TD			12/28/2036
2020 PO6426804465	KU	4	40 UNK	SP	CCA		V			12/29/2036
2020 PO6435204220	KU	4	40 UNK	SP	CRE	ID	TD			12/30/2036
2020 PO3039150706	KU	4	40 BRO	SP	P	ED	T			12/31/2036
2020 PO3049550621	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			1/1/2037
2020 PO2976651377	F	3	50 BRO	SP	CRE		V			1/2/2037
2020 PO3008151242	F	4	40 BRO	SP	A		V			1/3/2037
2020 PO3018251184	F	4	40 BRO	SP	CRE		V			1/4/2037
2020 PO3028651109	F	4	40 BRO	SP	A		V			1/5/2037
2020 PO3912482137	LGE	3	50 BRN	SP	CCA		V			1/6/2037

2020 PO3912882153	LGE	3	50 BRN	SP	A		ED,ID	TD		1/7/2037
2020 PO1363736176	ODP	2	50 KOP	SP	S			V		1/8/2037
2020 PO1358636287	ODP	3	50 KOP	SP	CRE			V		1/9/2037
2020 PO1382936082	ODP	3	50 KOP	SP	S			V		1/10/2037
2020 PO1388435933	F	4	40 KOP	SP	S			V		1/11/2037
2020 PO3961382868	LGE	4	50 BRN	SP	CRE		ED,ID	TD		1/12/2037
2020 PO6263904295	KU	6	30 BRN	SP	CRE		ID	TD		1/13/2037
2020 PO7127222402	KU	4	40 BRN	SP	CRE			V		1/14/2037
2020 PO1066036980	ODP	4	40 BRN	SP	CRE			V		1/15/2037
2020 PO3154250222	F	4	40 BRO	SP	CRE			V		1/16/2037
2020 9507417968A	KU	5	35 CAH	SP	CRE		ID	TD		1/17/2037
2020 0558916179A	KU	6	30 INP	SP	CRE		ID	TD		1/18/2037
2020 0628214681A	KU	6	30 KOP	SP	CRE		ID	TD		1/19/2037
2020 PO0667813678	KU	4	45 OTH	SP	CRE		ID	BD		1/20/2037
2020 PO0587815878	KU	4	35 UNK	SP	CRE		ED,ID,SRS	TD		1/21/2037
2020 PO0545716316	KU	5	35 BRN	SP	CRE		ID	TD		1/22/2037
2020 PO0637514573	KU	4	40 BRN	SP	CCA			V		1/23/2037
2020 PO0618514833	KU	4	40 OTH	SP	CRE		ID	TD		1/24/2037
2020 PO4738088336	LGE	4	35 BRO	SP	CRE		ED,ID	BD		1/25/2037
2020 PO3964791823	KU	5	35 KOP	SP	S			V		1/26/2037
2020 PO4028491906	KU	6	30 KOP	SP	S			V		1/27/2037
2020 PO3982391915	KU	6	30 KOP	SP	CRE		ED,ID	TD		1/28/2037
2020 PO3986091826	F	4	40 KOP	SP	CRE			V		1/29/2037
2020 PO3988491784	F	4	40 KOP	SP	CRE			V		1/30/2037
2020 PO3975491766	F	4	40 KOP	DF	CRE			V		1/31/2037
2020 PO3973291705	F	4	40 KOP	SP	CRE			V		2/1/2037
2020 PO3968191681	F	3	45 KOP	SP	S			V		2/2/2037
2020 PO3901191444	F	4	40 KOP	SP	S			V		2/3/2037
2020 PO3919591521	F	5	35 KOP	SP	A			V		2/4/2037
2020 PO3928391558	F	4	40 KOP	SP	P			V		2/5/2037
2020 PO3921391479	F	4	40 KOP	SP	CRE			V		2/6/2037
2020 PO4737588320	LGE	4	35 BRO	SP	CRE		ED,ID,IP	TD		2/7/2037
2020 PO4736888309	LGE	4	35 BRO	SP	CRE		ED,ID,RB	TX	RR	2/8/2037
2020 PO4739788326	LGE	4	40 BRO	SP	CRE		ED,ID	BD		2/9/2037
2020 PO4739188352	LGE	4	40 BRO	SP	P		ED,ID	BD		2/10/2037
2020 PO0616815985	KU	5	35 BRN	SP	CRE			V		2/11/2037
2020 PO3782790695	F	4	40 KOP	SP	CRE		ED,ID,MD,RB	BX	PX	2/12/2037
2020 PO5263331556	KU	4	40 BRO	SP	CRE		ED,ID,IP	TD		2/13/2037
2020 PO5249731703	F	4	40 BRO	SP	CRE			V		2/14/2037
2020 PO4721929533	KU	3	45 BRO	SP	CRE			V		2/15/2037
2020 PO5262531853	F	4	40 BRO	SP	CRE			V		2/16/2037
2020 PO5226831977	F	4	40 BRO	SP	CRE			V		2/17/2037
2020 PO5830847793	C	4	40 ACE	SP	CRE		ED	V		2/18/2037
2020 PO5833347724	KU	4	45 ACE	SP	CRE		ED,ID	TD		2/19/2037
2020 PO5825647630	KU	3	40 ACE	SP	CCA			V		2/20/2037
2020 PO4312928227	KU	4	40 BRO	SP	CRE			V		2/21/2037
2020 PO0595615117	KU	6	30 OTH	SP	CRE		ID	TD		2/22/2037

2020 PO0618115062	KU	4	40 KOP	SP	CRE	ID	TD	2/23/2037	
2020 PO0630015191	KU	2	50 BRN	SP	CRE	ID	TD	2/24/2037	
2020 PO0605614983	KU	4	40 BRN	SP	CRE	ID	TD	2/25/2037	
2020 PO0635314806	KU	6	30 OTH	SP	CRE	ED,ID,SRS	TD	2/26/2037	
2020 PO0619115617	KU	4	40 BRN	SP	CRE		V	2/27/2037	
2020 PO0618315557	KU	2	55 BRN	SP	CRE	ID	TD	2/28/2037	
2020 PO0533416444	KU	5	35 BRN	SP	CRE	ID	TD	3/1/2037	
2020 PO0616615803	KU	4	45 BRN	SP	CRE		V	3/2/2037	
2020 PO0655313549	KU	4	40 KOP	SP	CRE		V	3/3/2037	
2020 PO0657914266	KU	4	40 UNK	SP	CRE	ED,ID,SRS	TD	3/4/2037	
2020 PO0628214681	KU	4	40 INP	SP	CRE	ID	TD	3/5/2037	
2020 PO0630315773	KU	5	35 BRN	SP	CRE		V	3/6/2037	
2020 PO0655414467	KU	6	30 BRN	SP	CCA		V	3/7/2037	
2020 PO0665913795	KU	4	45 BRN	SP	CRE	ID	TD	3/8/2037	
2020 PO0670813948	KU	4	45 BRN	SP	CRE	ID	TD	3/9/2037	
2020 PO0644214468	KU	4	40 INP	SP	CRE	ID	TD	3/10/2037	
2020 PO0647714670	KU	6	30 OTH	SP	CRE	ED,ID,SR	TX	RR	3/11/2037
2020 PO0606715110	KU	6	30 INP	SP	CRE	ID	TD	3/12/2037	
2020 PO0619015357	KU	2	50 BRN	SP	CRE	ID	TD	3/13/2037	
2020 PO0558916179	KU	5	35 UNK	SP	CRE	ID	TD	3/14/2037	
2020 PO7106722261	KU	4	40 BRN	SP	CRE		V	3/15/2037	
2020 PO7115222327	KU	4	40 BRN	SP	CRE		V	3/16/2037	
2020 PO7092622058	KU	4	40 BRN	SP	CRE		V	3/17/2037	
2020 PO7100622165	KU	4	40 BRN	SP	CRE		V	3/18/2037	
2020 PO9440117743	KU	4	35 BRN	SP	CRE	ID	TD	3/19/2037	
2020 PO9207018747	KU	5	35 CAH	SP	CRE	ID	TD	3/20/2037	
2020 PO9482017903	KU	5	35 BRN	SP	CRE		V	3/21/2037	
2020 PO9526517621	KU	4	40 BRN	SP	CCA		V	3/22/2037	
2020 PO9534418068	KU	5	35 BRN	SP	CRE	ID	TD	3/23/2037	
2020 PO9458317810	KU	5	35 INP	SP	CRE	ID	TD	3/24/2037	
2020 PO3770590611	F	4	40 KOP	SP	CRE		V	3/25/2037	
2020 PO3757490525	F	4	40 KOP	SP	CRE		V	3/26/2037	
2020 PO3762790559	F	4	40 KOP	SP	CRE		V	3/27/2037	
2020 PO3759290609	KU	4	45 KOP	SP	CRE	ID	BD	3/28/2037	
2020 PO3754090695	F	4	40 KOP	SP	CRE		V	3/29/2037	
2020 PO4662189196	LGE	4	40 BRO	SP	A	ID,IP	BD	3/30/2037	
2020 PO4667488200	LGE	4	35 BRN	SP	CRE	ED,ID	BD	3/31/2037	
2020 PO4664189211	LGE	4	40 BRO	SP	CCA		V	4/1/2037	
2020 PO5840305228	KU	4	40 XXX	SP	CRE	ED,ID	TD	4/2/2037	
2020 PO5841605124	KU	4	40 XXX	SP	CRE	ED,ID	TD	4/3/2037	
2020 PO5857205142	KU	4	40 XXX	SP	CRE	ED,ID	TD	4/4/2037	
2020 PO5880605173	KU	4	40 XXX	SP	CRE	ID	BD	4/5/2037	
2020 PO4663289203	LGE	4	40 BRO	SP	A	ID,IP	BD	4/6/2037	
2020 PO4666988209	LGE	4	40 BRN	SP	A	ED,ID	BD	4/7/2037	
2020 PO4666388217	LGE	4	40 BRN	SP	CRE	ED,ID	TD	4/8/2037	
2020 PO4653589126	LGE	4	35 BRO	SP	A	ID,IP	BD	4/9/2037	
2020 PO4318028099	KU	2	70 BRO	ST	P		V	4/10/2037	

2020 PO4729629708	KU	5	35 BRO	SP	CRE		V	4/11/2037
2020 PO4708429192	KU	3	45 BRO	SP	CRE		V	4/12/2037
2020 PO4693728876	KU	4	40 BRO	SP	CRE		V	4/13/2037
2020 PO4210028059	KU	4	40 BRO	SP	CRE	ED,ID	TD	4/14/2037
2020 PO4199927998	C	4	40 BRO	SP	CRE		V	4/15/2037
2020 PO4204628244	KU	6	30 BRO	SP	CRE		V	4/16/2037
2020 PO4286128187	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/17/2037
2020 PO4293127936	KU	3	45 BRO	SP	CCA		V	4/18/2037
2020 PO5804147584	KU	4	40 ACE	SP	CRE	ED,ID	TD	4/19/2037
2020 PO5803247643	C	4	40 ACE	SP	CCA		V	4/20/2037
2020 PO5836547646	C	5	35 ACE	SP	P		V	4/21/2037
2020 PO5835647674	F	4	40 ACE	SP	P		V	4/22/2037
2020 PO3928308729	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	4/23/2037
2020 PO5068009570	F	4	40 ACE	SP	CRE	ED,ID	V	4/24/2037
2020 PO4810410534	KU	4	40 ACE	SP	CRE	ED,ID	BD	4/25/2037
2020 PO3947508758	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	4/26/2037
2020 PO4757388827	LGE	4	40 BRN	SP	CRE	ED,ID	TD	4/27/2037
2020 PO4756988827	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD	4/28/2037
2020 PO1959820907	ODP	5	30 XXX	SP	CCA	ED	T	4/29/2037
2020 PO1966020787	ODP	6	30 XXX	SP	CRE	ID	TD	4/30/2037
2020 PO1971221047	F	4	40 XXX	SP	A		V	5/1/2037
2020 PO1994321330	ODP	4	40 XXX	SP	CCA		V	5/2/2037
2020 PO9566290282	KU	3	50 BRN	SP	S		V	5/3/2037
2020 PO9582690472	KU	3	55 BRN	SP	S		V	5/4/2037
2020 PO9707093252	KU	3	50 BRN	SP	S		V	5/5/2037
2020 PO9707292734	KU	3	45 BRN	SP	S		V	5/6/2037
2020 PO9707392475	KU	3	45 BRN	SP	S		V	5/7/2037
2020 PO9707492217	KU	3	45 BRN	SP	S		V	5/8/2037
2020 PO9706291953	KU	3	45 BRN	SP	S		V	5/9/2037
2020 PO9701391694	KU	3	45 BRN	SP	S		V	5/10/2037
2020 PO9674791263	KU	3	45 BRN	SP	S		V	5/11/2037
2020 PO9674791263	KU	3	45 BRN	SP	S		V	5/12/2037
2020 PO9656591074	KU	3	45 BRN	SP	S		V	5/13/2037
2020 PO9633490835	KU	3	45 BRN	SP	S		V	5/14/2037
2020 PO9602890664	KU	3	50 BRN	SP	S		V	5/15/2037
2020 PO9433785225	KU	3	50 BRN	SP	S		V	5/16/2037
2020 PO9421384938	KU	3	50 BRN	SP	S		V	5/17/2037
2020 PO9411284617	KU	3	45 BRN	SP	S		V	5/18/2037
2020 PO9399584308	KU	3	45 BRN	SP	S		V	5/19/2037
2020 PO9397284218	KU	3	50 BRN	SP	S		V	5/20/2037
2020 PO9710293379	KU	5	30 XXX	SP	CRE		V	5/21/2037
2020 PO9708293431	KU	3	50 BRN	SP	CCA		V	5/22/2037
2020 PO4021582923	F	4	30 BRN	SP	CCA		V	5/23/2037
2020 PO4023782932	F	4	30 BRN	SP	CCA		V	5/24/2037
2020 PO4023182936	F	4	40 BRN	SP	CCA		V	5/25/2037
2020 PO4021782900	F	4	30 BRN	SP	P		V	5/26/2037
2020 PO4022582939	F	4	30 BRN	SP	CCA		V	5/27/2037

2020 PO4021082901	F	3	45 BRN	SP	A	ED, RB	VX	PX	5/28/2037
2020 PO4022182919	F	4	40 BRN	SP	CCA		V		5/29/2037
2020 PO4022782915	F	4	30 BRN	SP	CCA		V		5/30/2037
2020 PO4023682956	LGE	4	30 BRN	SP	CCA		V		5/31/2037
2020 PO7424041232	LGE	3	45 BRN	SP	CCA		V		6/1/2037
2020 PO4024282952	LGE	3	45 BRN	SP	CCA		V		6/2/2037
2020 PO4024782949	LGE	4	30 BRN	SP	CCA		V		6/3/2037
2020 PO4025282970	F	3	45 BRN	SP	P		V		6/4/2037
2020 PO4024482972	F	4	30 BRN	SP	CCA		V		6/5/2037
2020 PO4020882907	LGE	4	30 BRN	SP	P	ED, ID	TD		6/6/2037
2020 PO4026482963	F	4	40 BRN	SP	CCA		V		6/7/2037
2020 PO4027582956	F	2	40 BRN	SP	CCA		V		6/8/2037
2020 PO4027582956A	LGE	4	30 BRN	SP	CCA		V		6/9/2037
2020 PO4277911300	KU	3	45 BRO	SP	CRE	ID, IP	BD		6/10/2037
2020 PO4249012748	KU	2	45 BRO	SP	CRE	ID, IP	BD		6/11/2037
2020 PO4234612835	KU	2	45 BRO	SP	CRE	ID, IP	BD		6/12/2037
2020 PO4220412913	KU	2	45 BRO	SP	CRE	ID, IP	BD		6/13/2037
2020 PO4249712796	KU	6	30 BRO	SP	CRE	ID	BD		6/14/2037
2020 PO4027582956A	LGE	4	30 BRN	SP	CCA		V		6/15/2037
2020 PO4029682991	F	4	40 BRN	SP	CCA		V		6/16/2037
2020 PO4030383002	F	4	40 BRN	SP	CCA		V		6/17/2037
2020 PO4030583006	F	5	30 BRN	SP	P		V		6/18/2037
2020 PO4030382987	LGE	4	35 BRN	SP	P	ED, ID	TD		6/19/2037
2020 PO4031682992	F	2	55 BRN	ST	CCA		V		6/20/2037
2020 PO4031882986	F	1	50 BRN	SP	A		V		6/21/2037
2020 PO4031982984	F	1	50 BRN	SP	A		V		6/22/2037
2020 PO4031982981	LGE	2	55 BRN	SP	A	ED, ID	TD		6/23/2037
2020 PO4032582958	F	2	55 BRN	SP	A		V		6/24/2037
2020 PO4032782946	F	1	50 BRN	SP	CCA		V		6/25/2037
2020 PO4033182931	F	3	50 BRN	SP	A		V		6/26/2037
2020 PO4033482917	F	3	35 BRN	SP	A		V		6/27/2037
2020 PO4290012519	KU	2	45 BRO	SP	CRE	ID, IP	BD		6/28/2037
2020 PO4274312605	KU	3	50 BRO	SP	CCA		V		6/29/2037
2020 PO4260512686	KU	3	50 BRO	SP	CRE	ID, IP	BD		6/30/2037
2020 PO4493315586	KU	H4	65 BRO	ST	P		V		7/1/2037
2020 PO4490515627	KU	4	40 BRO	SP	CCA		V		7/2/2037
2020 PO4485315709	KU	1	70 BRO	SP	CRE	ED, ID, IP	TD		7/3/2037
2020 PO4485315709-A	KU	4	40 BRO	SP	CRE	ED	TD		7/4/2037
2020 PO4033882895	LGE	3	50 BRN	SP	A	ED, ID	TD		7/5/2037
2020 PO4033782899	F	3	50 BRN	SP	A		V		7/6/2037
2020 PO4033582906	LGE	3	50 BRN	SP	A	ED, ID, IP	TD		7/7/2037
2020 PO4467915930	KU	4	40 BRO	SP	CRE		V		7/8/2037
2020 PO4464115969	KU	4	40 BRO	SP	CCA		V		7/9/2037
2020 PO4462615987	KU	1	65 BRO	SP	CRE	ID, IP	BD		7/10/2037
2020 PO4509815203	KU	4	40 BRO	SP	CRE	ID	BD		7/11/2037
2020 PO4507015278	KU	1	75 BRO	SP	CRE	ED, ID, IP	TD		7/12/2037
2020 PO4499815488	KU	4	40 BRO	SP	CCA		V		7/13/2037

2020 PO4513815119	KU	1	75 BRO	ST	CRE		V	7/14/2037	
2020 PO4514115094	KU	4	40 BRO	SP	CRE	ID	BD	7/15/2037	
2020 PO4518414951	KU	1	70 BRO	SP	CRE	EP,ID,IP	TD	7/16/2037	
2020 PO4518414951-A	KU	4	40 BRO	SP	CRE	ID	BD	7/17/2037	
2020 PO4521814795	KU	4	60 BRO	SP	CRE		V	7/18/2037	
2020 PO4522014778	KU	H4	65 BRO	ST	P		V	7/19/2037	
2020 PO4522414605	KU	4	40 BRO	SP	CCA		V	7/20/2037	
2020 PO4523214510	KU	1	70 BRO	SP	A	ED,ID,IP	TD	7/21/2037	
2020 PO4524214425	KU	4	40 BRO	SP	CRE		V	7/22/2037	
2020 PO4478112959	KU	2	50 BRO	SP	CRE	ID,IP	BD	7/23/2037	
2020 PO4500313137	KU	3	45 BRO	SP	CRE	ID,IP	BD	7/24/2037	
2020 PO4490413074	KU	3	45 BRO	SP	CCA		V	7/25/2037	
2020 PO4514013253	KU	2	50 BRO	SP	CCA		V	7/26/2037	
2020 PO4522613500	KU	4	40 BRO	SP	CRE	ID,IP	BD	7/27/2037	
2020 PO4528713389	KU	2	55 BRO	SP	CCA		V	7/28/2037	
2020 PO4527413378	KU	1	55 BRO	SP	CCA		V	7/29/2037	
2020 PO4522913322	KU	3	45 BRO	SP	CCA		V	7/30/2037	
2020 PO4521213339	KU	3	45 BRO	SP	CCA		V	7/31/2037	
2020 PO4621537713	KU	1	65 BRO	SP	CCA		V	8/1/2037	
2020 PO4829729907	KU	6	30 BRO	SP	CRE		V	8/2/2037	
2020 PO4637988218	LGE	4	40 ACE	SP	CRE	ED,HH,ID,RB	TX	RR	8/3/2037
2020 PO4638388213	LGE	4	40 ACE	SP	P	ED,ID	TD	8/4/2037	
2020 PO4723488523	LGE	2	60 BRN	SP	A		V	8/5/2037	
2020 PO4744688348	LGE	4	40 BRN	SP	A	ED,ID	BD	8/6/2037	
2020 PO4742988360	LGE	4	40 BRN	SP	P	ED,ID	BD	8/7/2037	
2020 PO4047982907	LGE	4	40 BRO	SP	CRE	ED,ID	BD	8/8/2037	
2020 PO4741588369	LGE	4	40 BRN	SP	CCA		V	8/9/2037	
2020 PO4739988381	LGE	4	40 BRN	SP	CCA		V	8/10/2037	
2020 PO4738388393	LGE	4	40 BRN	SP	A	ED,ID	BD	8/11/2037	
2020 PO4736888404	LGE	4	40 BRN	SP	A	ED,ID	TD	8/12/2037	
2020 PO4633787990	LGE	3	45 ACE	SP	CRE	ED,ID,IP	BD	8/13/2037	
2020 PO4633787992	LGE	3	45 ACE	SP	CRE	ED,ID	TD	8/14/2037	
2020 PO4735688411	LGE	4	40 BRN	SP	A	ED,ID	BD	8/15/2037	
2020 PO4633387954	LGE	4	30 ACE	SP	A	ED,ID	TD	8/16/2037	
2020 PO4633587973	LGE	3	50 ACE	SP	CRE	ED,ID	BD	8/17/2037	
2020 PO4632387972	LGE	4	40 ACE	SP	CRE	ED,ID	TD	8/18/2037	
2020 PO4632287953	LGE	4	40 ACE	SP	CRE		B	8/19/2037	
2020 PO4736688427	LGE	4	30 BRN	SP	A	ED,ID	BD	8/20/2037	
2020 PO4736388422	LGE	4	40 BRN	SP	CCA		V	8/21/2037	
2020 PO4735988425	LGE	4	40 BRN	SP	A	ED,ID	BD	8/22/2037	
2020 PO1272132923	ODP	4	40 XXX	SP	A		V	8/23/2037	
2020 PO5142711430	F	4	40 ACE	SP	P		V	8/24/2037	
2020 PO5064711425	F	4	40 ACE	SP	CRE		V	8/25/2037	
2020 PO0374941875	ODP	5	35 XXX	SP	CRE		V	8/26/2037	
2020 PO0371941585	ODP	5	35 XXX	SP	CRE		V	8/27/2037	
2020 PO0374541321	ODP	5	35 XXX	SP	CRE		V	8/28/2037	
2020 PO0374741051	ODP	4	40 XXX	SP	CRE		V	8/29/2037	

2020 PO0393640631	ODP	5	35 XXX	SP	CRE		V	8/30/2037
2020 PO0399840393	ODP	5	35 XXX	SP	CRE		V	8/31/2037
2020 PO0352438028	ODP	6	30 XXX	SP	CCA		V	9/1/2037
2020 PO0355238229	ODP	6	30 XXX	SP	CCA		V	9/2/2037
2020 PO0458239106	ODP	4	40 XXX	SP	CRE		V	9/3/2037
2020 PO0511041758	ODP	6	30 XXX	SP	CRE		V	9/4/2037
2020 PO0497242494	ODP	6	30 XXX	SP	CRE		V	9/5/2037
2020 PO0498543044	ODP	5	35 XXX	SP	CRE	ED,ID	TD	9/6/2037
2020 PO0489243299	ODP	5	35 XXX	SP	CRE	ED,ID	TD	9/7/2037
2020 PO4734388439	LGE	4	40 BRN	SP	A	ED,ID,IP	BD	9/8/2037
2020 PO4298911473	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	9/9/2037
2020 PO5113511023	F	4	40 ACE	SP	CRE		V	9/10/2037
2020 PO5138110889	F	4	40 ACE	SP	CRE		V	9/11/2037
2020 PO4644488240	LGE	4	40 ACE	SP	CRE	ED,ID	TD	9/12/2037
2020 PO4645488247	LGE	4	40 ACE	SP	CRE	ED,ID	TD	9/13/2037
2020 PO4647488261	LGE	UNK	55 ACE	SP	CRE		V	9/14/2037
2020 PO4646388253	LGE	4	40 ACE	SP	CRE	ED,ID	BD	9/15/2037
2020 PO4646188257	LGE	4	40 ACE	SP	CRE	ED,ID	TD	9/16/2037
2020 PO8894842884	ODP	4	45 BRN	SP	CCA		V	9/17/2037
2020 PO4728488509	LGE	4	30 BRN	SP	P	ED,ID	BD	9/18/2037
2020 PO4727888504	LGE	4	45 BRN	SP	CRE	ED,ID	TD	9/19/2037
2020 PO9119038896	ODP	5	35 BRN	SP	CRE		V	9/20/2037
2020 PO8790644599	ODP	2	50 BRN	SP	CCA		V	9/21/2037
2020 PO5151910816	F	4	40 ACE	SP	P		V	9/22/2037
2020 PO9240334923	ODP	4	45 BRN	SP	CCA		V	9/23/2037
2020 PO9252133429	ODP	4	50 BRN	SP	CRE		V	9/24/2037
2020 PO9267233517	F	4	45 BRN	SP	CCA		V	9/25/2037
2020 PO9241233130	ODP	5	35 BRN	SP	CRE		V	9/26/2037
2020 PO9239032933	ODP	5	35 BRN	SP	CRE		V	9/27/2037
2020 PO4726888495	LGE	4	40 BRN	SP	P	ED,ID	BD	9/28/2037
2020 PO4725888486	LGE	4	40 BRN	SP	A	ED,ID	BD	9/29/2037
2020 PO1310923277A	ODP	4	40 XXX	SP	CRE	ID	TD	9/30/2037
2020 PO1382422791	ODP	5	35 XXX	SP	CRE	ID,RB	BX	10/1/2037
2020 PO1407022781	ODP	4	40 XXX	SP	CRE	ID	TD	10/2/2037
2020 PO1445923561	ODP	2	50 XXX	SP	CCA		V	10/3/2037
2020 PO1502423702	ODP	4	40 XXX	SP	CRE		V	10/4/2037
2020 PO4844029949	KU	2	40 BRO	SP	CRE		V	10/5/2037
2020 PO9807337763	ODP	4	40 BRN	SP	CCA		V	10/6/2037
2020 PO9778037731	ODP	4	40 BRN	SP	CCA		V	10/7/2037
2020 PO9844837815	ODP	4	40 BRN	SP	CCA		V	10/8/2037
2020 PO4294997229	LGE	2	55 BRN	SP	CCA		V	10/9/2037
2020 PO4720588450	LGE	1	55 BRN	SP	CCA		V	10/10/2037
2020 PO4713511307	KU	4	40 ACE	SP	CRE	ED,ID	BD	10/11/2037
2020 PO4722188464	LGE	1	55 BRN	SP	S		V	10/12/2037
2020 PO4723788478	LGE	1	55 BRN	SP	S		V	10/13/2037
2020 PO4723888494	F	4	40 BRN	SP	CCA		V	10/14/2037
2020 PO4722688502	F	4	40 BRN	SP	CCA		V	10/15/2037

Business Use

2020 PO4723088481	LGE	3	25 BRN	SP	CRE		V			10/16/2037
2020 PO4722988479	F	4	35 BRN	SP	A		V			10/17/2037
2020 PO5057131034	KU	3	45 BRO	SP	CCA		V			10/18/2037
2020 0506542776a	ODP	5	30 XXX	SP	CRE	ED,ID	TD			10/19/2037
2020 PO5049730864	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD			10/20/2037
2020 PO4724488484	LGE	1	55 BRN	SP	S		V			10/21/2037
2020 PO4725388491	LGE	1	55 BRN	SP	S		V			10/22/2037
2020 PO4035582920	LGE	4	40 BRO	SP	CRE	ED,HH,ID,RB	X	RP2		10/23/2037
2020 PO4035882917	LGE	4	40 BRO	SP	CCA		V			10/24/2037
2020 PO4035182934	LGE	4	40 BRO	SP	P	ED,ID	TD			10/25/2037
2020 PO7526141228	LGE	4	35 BRO	SP	CCA		V			10/26/2037
2020 PO4034782951	LGE	4	40 BRO	SP	P	ED,ID	BD			10/27/2037
2020 PO4036282805	F	3	45 BRO	SP	A		V			10/28/2037
2020 PO4036482795	F	3	45 BRO	SP	P		V			10/29/2037
2020 PV4036582795	F	4	35 BRO	SP	CCA		V			10/30/2037
2020 PO4040782829	LGE	4	40 BRO	SP	CRE	ED,ID	TD			10/31/2037
2020 PO4365097839	LGE	1	55 BRN	SP	S		V			11/1/2037
2020 PO4727288508	LGE	4	30 BRN	ST	P		V			11/2/2037
2020 PO4732511113	KU	5	35 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	RP1		11/3/2037
2020 PO4739711096	KU	4	40 ACE	SP	CRE	ED,ID	BD			11/4/2037
2020 PO4380297970	LGE	1	55 BRN	SP	S		V			11/5/2037
2020 PO4395398100	LGE	1	55 BRN	SP	S		V			11/6/2037
2020 PO4410598231	LGE	1	55 BRN	SP	S		V			11/7/2037
2020 PO4425698362	LGE	1	55 BRN	SP	S		V			11/8/2037
2020 PO4732788555	LGE	2	80 BRN	SP	P		V			11/9/2037
2020 PO4746311062	KU	5	35 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	RP1		11/10/2037
2020 PO4737988544	LGE	4	40 BRN	SP	CCA		V			11/11/2037
2020 PO4736788552	LGE	4	40 BRN	SP	CCA		V			11/12/2037
2020 PO4736288561	LGE	4	40 BRN	SP	A	ED,ID	BD			11/13/2037
2020 PO4735888558	LGE	4	45 BRN	SP	CRE	ED,ID	BD			11/14/2037
2020 PO4735288563	LGE	1	75 BRN	SP	P		V			11/15/2037
2020 PO4737588570	LGE	1	65 BRN	SP	P		V			11/16/2037
2020 PO4733629282	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD			11/17/2037
2020 PO4735629292	KU	3	50 BRO	SP	CRE	ED,ID,IP	TD			11/18/2037
2020 PO4644988282	LGE	4	40 ACE	SP	CRE	ED,ID	BD			11/19/2037
2020 PO4645388274	LGE	4	40 ACE	SP	CRE	ED,ID	BD			11/20/2037
2020 PO4644488292	LGE	4	40 ACE	SP	CRE	ED,ID	BD			11/21/2037
2020 PO4643888302	LGE	4	40 ACE	SP	CRE	ED,ID,IP	TD			11/22/2037
2020 PO0532842709	ODP	4	45 XXX	SP	CCA		V			11/23/2037
2020 PO0531742768	ODP	3	45 XXX	SP	A	ED,ID	TD			11/24/2037
2020 PO0530642648	ODP	6	30 XXX	SP	CCA		V			11/25/2037
2020 PO0506542776	F	5	40 XXX	SP	CRE		V			11/26/2037
2020 PO0512142591	ODP	4	45 XXX	SP	A	ED,ID	TD			11/27/2037
2020 PO0515042472	ODP	5	35 KOP	SP	CRE	ID	BD			11/28/2037
2020 PO4867430130	F	4	40 BRO	SP	CRE		V			11/29/2037
2020 PO4853830188	F	4	40 BRO	SP	CRE		V			11/30/2037
2020 PO4840530252	F	4	40 BRO	SP	CRE		V			12/1/2037

2020 PO4849430082	F	4	40 BRO	SP	CRE		V	12/2/2037
2020 PO4863830041	F	4	40 BRO	SP	CRE		V	12/3/2037
2020 PO4859530164-A	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	12/4/2037
2020 PO1478124276	F	4	40 XXX	SP	CRE		V	12/5/2037
2020 PO1516124072	ODP	5	35 XXX	SP	CRE	ID	TD	12/6/2037
2020 PO1492024139	ODP	5	35 XXX	SP	CRE	ID	TD	12/7/2037
2020 PO1336327253	ODP	4	40 XXX	SP	CRE	ID	TD	12/8/2037
2020 PO1335127473	ODP	4	40 XXX	SP	CCA	ED	T	12/9/2037
2020 PO1102328023	F	4	40 XXX	SP	CCA		V	12/10/2037
2020 PO1354826522	ODP	4	40 XXX	SP	A	ID	BD	12/11/2037
2020 PO1449624773	ODP	4	45 XXX	SP	CCA		V	12/12/2037
2020 PO1432024298	ODP	4	40 XXX	SP	CRE	ID	TD	12/13/2037
2020 PO1425724665	ODP	4	40 XXX	SP	CRE	ID	BD	12/14/2037
2020 PO1344124084	ODP	4	40 XXX	SP	CRE	ID	TD	12/15/2037
2020 PO1367124221	ODP	4	40 XXX	SP	A	ID	TD	12/16/2037
2020 PO1368024479A	ODP	6	30 XXX	SP	CRE	ID	TD	12/17/2037
2020 PO1587826806	ODP	6	30 XXX	SP	CRE		BD	12/18/2037
2020 PO4859530164	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	12/19/2037
2020 PO4739888578	LGE	1	65 BRN	SP	P		V	12/20/2037
2020 PO4742288586	LGE	1	75 BRN	SP	P		V	12/21/2037
2020 PO4744688594	LGE	1	75 BRN	SP	P		V	12/22/2037
2020 PO4872930130	KU	4	40 BRO	SP	CCA		V	12/23/2037
2020 PO1402033147	ODP	4	45 XXX	SP	CCA		V	12/24/2037
2020 PO4774888764	LGE	4	40 BRN	SP	CRE	ED,ID	BD	12/25/2037
2020 PO4774488770	LGE	4	40 BRN	SP	CRE	ED,ID	BD	12/26/2037
2020 PO4771388755	LGE	4	40 BRN	SP	CRE	ED,ID,IP	BD	12/27/2037
2020 PO4772288758	LGE	4	30 BRN	SP	A	ED,ID	BD	12/28/2037
2020 PO4637588283	LGE	4	30 ACE	SP	P	ED	T	12/29/2037
2020 PO4770888766	LGE	4	40 BRN	SP	S		V	12/30/2037
2020 PO4773388793	LGE	4	40 BRN	SP	S		V	12/31/2037
2020 PO7418194045	KU	5	35 BRO	SP	CRE	ED,ID	TD	1/1/2038
2020 PO5337106510	F	1	20 XXX	SP	A		V	1/2/2038
2020 PO5328006473	KU	6	30 XXX	SP	CRE	ED,ID	TD	1/3/2038
2020 PO5333206486	KU	4	40 XXX	SP	CRE	ED,ID	TD	1/4/2038
2020 PO5341106550	KU	4	45 XXX	SP	CRE	ED,ID	TD	1/5/2038
2020 PO7003189599	F	5	35 BRN	SP	CRE	ED,HH,ID,IP,RB	BX	1/6/2038
2020 PO7020089500	KU	6	35 BRN	SP	CRE	ED,ID,IP	BD	1/7/2038
2020 PO6992689585	F	4	40 BRN	SP	CRE		V	1/8/2038
2020 PO6996189649	KU	3	45 BRN	SP	CRE	ED,ID	BD	1/9/2038
2020 PO7010889551	KU	4	40 BRN	SP	CCA		V	1/10/2038
2020 PO7005789484	KU	5	35 BRN	SP	CRE	ED,ID	BD	1/11/2038
2020 PO7393493835	KU	5	35 BRO	SP	CRE	ID	BD	1/12/2038
2020 PO7401093872	KU	3	45 BRO	SP	P	ED	T	1/13/2038
2020 PO1491726536	F	4	40 MAR	SP	A		V	1/14/2038
2020 PO4863930468	KU	6	30 ACE	SP	CCA		V	1/15/2038
2020 PO3984083068	LGE	4	30 BRN	SP	CCA		V	1/16/2038
2020 PO3983283071	LGE	4	40 BRN	SP	A	ED,ID	TD	1/17/2038

2020 PO1242837229	ODP	5	35 XXX	SP	CRE	ED,ID	TD	1/18/2038
2020 PO1455026431	F	4	40 BRN	SP	CRE		V	1/19/2038
2020 PO1502127019	F	4	40 BRN	SP	CRE		V	1/20/2038
2020 PO1442326884	ODP	4	45 BRN	SP	CCA		V	1/21/2038
2020 PO1435626879	ODP	6	30 BRN	SP	CCA		V	1/22/2038
2020 PO1449826582	F	4	40 KOP	SP	CRE		V	1/23/2038
2020 PO1456526601	F	4	30 BRN	SP	A		V	1/24/2038
2020 PO1223937337	ODP	4	40 XXX	SP	CRE	ED,ID	TD	1/25/2038
2020 PO1433826682	F	4	40 BRN	SP	CRE		V	1/26/2038
2020 PO3983683082	LGE	4	40 BRN	DF	CRE	ED,ID	BD	1/27/2038
2020 PO5280906534	F	6	30 XXX	SP	CRE		V	1/28/2038
2020 PO3984583085	LGE	4	30 BRN	SP	CCA	ED,ID	BD	1/29/2038
2020 PO5282706443	KU	5	35 XXX	SP	CRE	ED,ID	TD	1/30/2038
2020 PO5289806392	KU	6	30 XXX	SP	CRE	ED,ID	TD	1/31/2038
2020 PO5296006406	KU	6	30 XXX	SP	CRE	ED,ID	TD	2/1/2038
2020 PO5293706458	KU	3	40 XXX	SP	CRE	ED,ID	TD	2/2/2038
2020 5313006498a	KU	5	30 XXX	SP	CRE	ED,ID	TD	2/3/2038
2020 PO7397593986	KU	4	40 BRO	SP	CRE	ED,ID,IP	TX	RR 2/4/2038
2020 PO6979389645	KU	4	40 BRN	SP	CRE	ED,ID	BD	2/5/2038
2020 PO6980189828	KU	4	40 BRN	SP	CRE	ED,ID	TD	2/6/2038
2020 PO6988089776	KU	4	45 BRN	SP	CCA		V	2/7/2038
2020 PO7395594040	KU	4	40 BRO	SP	CRE	ED,ID	TD	2/8/2038
2020 PO5297306471	KU	6	30 XXX	SP	CRE	ED,ID	TD	2/9/2038
2020 PO6971489884	KU	3	45 BRN	SP	CRE	ED,ID	TD	2/10/2038
2020 PO6964189920	KU	4	30 BRN	SP	CRE	ED,ID	TD	2/11/2038
2020 PO6962089877	KU	4	45 BRN	SP	CCA		V	2/12/2038
2020 PO6962089914	KU	4	40 BRN	SP	S		V	2/13/2038
2020 PO3983883088	LGE	3	40 BRN	SP	A	ED,ID	TD	2/14/2038
2020 PO3984483102	LGE	4	30 BRN	SP	A	ED,ID	BD	2/15/2038
2020 PO4854730784	KU	5	35 ACE	SP	CRE	ED,ID	TD	2/16/2038
2020 PO4849030749	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	2/17/2038
2020 PO1418326494	F	3	45 BRN	SP	P		V	2/18/2038
2020 PO1422226325	F	4	40 BRN	SP	CRE		V	2/19/2038
2020 PO1426526144	F	4	40 BRN	SP	CRE		V	2/20/2038
2020 PO3902082229	LGE	4	40 BRN	SP	CRE	ED,ID	TD	2/21/2038
2020 PO3901382232	LGE	4	40 BRN	SP	A	ED,ID	TD	2/22/2038
2020 PO3900582234	LGE	4	40 BRN	SP	A	ED,ID	TD	2/23/2038
2020 PO1437534427	ODP	2	50 KOP	SP	CRE	ED,ID,MD	TD	2/24/2038
2020 5203906991A	KU	5	30 XXX	SP	CCA		V	2/25/2038
2020 PO5203906991	KU	6	30 XXX	SP	CCA		V	2/26/2038
2020 PO5209907023	KU	4	45 XXX	SP	CCA		V	2/27/2038
2020 PO5324106983	KU	5	30 XXX	SP	CRE	ED,ID	TD	2/28/2038
2020 PO7562384185	KU	4	45 BRN	SP	CCA		V	3/1/2038
2020 PO7586384317	KU	3	50 BRN	SP	CRE	ED,HH,ID,IP,RB	BX	PX 3/2/2038
2020 PO7601984367	KU	4	40 BRN	SP	CCA		V	3/3/2038
2020 PO7626084323	KU	4	40 BRN	SP	CRE	ED,ID	BD	3/4/2038
2020 PO5455509640	KU	4	40 BRO	SP	CRE	ID	TD	3/5/2038

2020 PO5453209262	KU	4	40 BRO	SP	CRE	ID	TD	3/6/2038	
2020 PO5447709215	KU	6	30 BRO	SP	CRE	ID	TD	3/7/2038	
2020 PO5449409328	KU	5	35 BRO	SP	CRE	ID	TD	3/8/2038	
2020 PO5397809917	KU	5	35 BRO	SP	CRE	ID	TD	3/9/2038	
2020 PO7952874116	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/10/2038	
2020 PO7963174151	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/11/2038	
2020 PO7399184308	KU	4	45 BRN	SP	CRE	ED,ID	TD	3/12/2038	
2020 PO7393084275	KU	6	30 BRN	SP	CRE	ED,ID	TD	3/13/2038	
2020 PO5309006947	KU	6	30 XXX	SP	CRE	ED,ID	TD	3/14/2038	
2020 PO5314306915	KU	5	30 XXX	SP	CRE	ED,ID	TD	3/15/2038	
2020 PO7976673945	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/16/2038	
2020 PO7983673816	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/17/2038	
2020 PO7991373672	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/18/2038	
2020 PO6996921042	KU	6	30 XXX	SP	CRE		V	3/19/2038	
2020 PO6988620915	KU	6	30 XXX	SP	CRE		V	3/20/2038	
2020 PO6954320544	KU	5	35 XXX	SP	CCA		V	3/21/2038	
2020 PO6958220494	KU	4	45 XXX	SP	CRE	ID	TD	3/22/2038	
2020 PO7371084211	KU	5	35 BRN	SP	CRE	ED,ID	BD	3/23/2038	
2020 PO7018320880	KU	5	35 XXX	SP	CRE	HH,ID,RB	BX	3/24/2038	RP2
2020 PO7367084229	KU	4	40 BRN	SP	CCA		V	3/25/2038	
2020 PO7367084084	KU	4	40 BRN	SP	CRE	ED,ID	TD	3/26/2038	
2020 PO7374984021	KU	6	30 BRN	SP	CRE	ED,ID	TD	3/27/2038	
2020 PO7382584281	KU	5	35 BRN	SP	CRE	ED,ID	BD	3/28/2038	
2020 PO7386584217	KU	5	35 BRN	SP	CRE	ED,ID	TD	3/29/2038	
2020 PO5318507087	KU	4	45 XXX	SP	CRE	ED,ID	TD	3/30/2038	
2020 PO8001873951	KU	5	30 BRO	SP	CRE	ED,ID	TD	3/31/2038	
2020 PO5308407115	KU	5	40 XXX	SP	CRE	RB	X	4/1/2038	RP1
2020 PO5309507139	KU	5	30 XXX	SP	CRE	ED,ID	TD	4/2/2038	
2020 PO5301407115	KU	5	35 XXX	SP	CRE	ED,ID	TD	4/3/2038	
2020 PO5283507116	KU	6	30 XXX	SP	CRE	ED,ID	TD	4/4/2038	
2020 PO7392384119	KU	5	35 BRN	SP	CRE	ED,ID	TD	4/5/2038	
2020 PO7418984050	KU	5	35 BRN	SP	CRE	ED,ID	BD	4/6/2038	
2020 PO7388383993	KU	6	30 BRN	SP	CRE	ED,ID	TD	4/7/2038	
2020 PO7396784042	KU	5	35 BRN	SP	CRE	ED,ID	TD	4/8/2038	
2020 PO7000820885	KU	4	40 XXX	SP	CRE	ID	TD	4/9/2038	
2020 PO7002720997	KU	4	40 XXX	SP	CRE	ID	TD	4/10/2038	
2020 PO7096321395	KU	6	30 XXX	DF	CRE		V	4/11/2038	
2020 PO0992233942	ODP	8	30 BRN	ST	CRE		V	4/12/2038	
2020 PO1009334007	ODP	8	30 BRN	ST	CCA		V	4/13/2038	
2020 PO1122233625A	ODP	4	35E BRN	SP	CRE	ID	BD	4/14/2038	
2020 PO1137733998	ODP	2	50 BRN	SP	CCA		V	4/15/2038	
2020 PO1147633917	ODP	6	30 BRN	SP	CCA		V	4/16/2038	
2020 PO1154233926	ODP	4	45 BRN	SP	CCA		V	4/17/2038	
2020 PO1170633910	F	4	40 BRN	SP	CRE	ED	V	4/18/2038	
2020 PO1167933746	ODP	2	50 BRN	SP	CCA		V	4/19/2038	
2020 PO1168333730	ODP	3	45 BRN	SP	CCA		V	4/20/2038	
2020 PO1170233544	ODP	4	45 BRN	SP	CRE		V	4/21/2038	

2020 PO1164933554	ODP	2	55 BRN	SP	CCA		V			4/22/2038
2020 PO1154133573	ODP	4	40 BRN	SP	CCA		V			4/23/2038
2020 PO1148233600	ODP	5	35 BRN	SP	CCA		V			4/24/2038
2020 PO7414884028	KU	H4	95 BRN	SP	CRE	ED,ID	TD			4/25/2038
2020 PO3879083068	LGE	4	35 BRO	SP	P	ED,ID	TD			4/26/2038
2020 PO7391283910	KU	4	45 BRN	SP	CRE	ED,ID	BD			4/27/2038
2020 PO7396483942	KU	3	50 BRN	SP	CRE	ED,ID	BD			4/28/2038
2020 PO5387209939	KU	5	35 BRO	SP	CCA		V			4/29/2038
2020 PO5381809939	KU	6	30 BRO	SP	CRE	ID	TD			4/30/2038
2020 PO5388609829	KU	5	35 BRO	SP	CRE	ID	BD			5/1/2038
2020 PO5399109354	KU	5	35 BRO	SP	CRE	ED,ID	BD			5/2/2038
2020 PO5399109354b	KU	5	30 BRO	SP	CCA		V			5/3/2038
2020 PO5408809167	KU	4	40 BRO	SP	CRE	ID	TX	RR		5/4/2038
2020 PO5380309765	KU	4	40 BRO	SP	CRE	ID	TD			5/5/2038
2020 PO5368709837	KU	6	30 BRO	SP	CRE	ID	TD			5/6/2038
2020 PO5373809708	KU	6	30 BRO	SP	CRE	ID	TD			5/7/2038
2020 PO5387809664	KU	6	30 BRO	SP	CCA	ED	T			5/8/2038
2020 PO5399609431b	KU	5	30 BRO	SP	CRE	ID	BD			5/9/2038
2020 PO5399609431a	KU	5	30 BRO	SP	CRE	ID	BD			5/10/2038
2020 PO5399109354a	KU	5	30 BRO	SP	CCA		V			5/11/2038
2020 PO5399609431	KU	4	45 BRO	SP	CRE	ID	BD			5/12/2038
2020 PO5403809461	KU	4	40 BRO	SP	CRE	ID	BD			5/13/2038
2020 PO5421409261	KU	4	40 BRO	SP	CRE	ID	TD			5/14/2038
2020 PO5416409312	KU	4	40 BRO	SP	CRE	ID	TD			5/15/2038
2020 PO5415809080	KU	4	40 BRO	SP	CRE	ID	TD			5/16/2038
2020 PO5420509024	KU	6	30 BRO	SP	CRE	ID	TD			5/17/2038
2020 PO5402809119	KU	5	35 BRO	SP	CRE	ID	TD			5/18/2038
2020 PO5393109044	KU	6	35 BRO	SP	CRE	ED,ID	TX	RR		5/19/2038
2020 PO5391908906	KU	5	30 BRO	SP	CRE	ID	TD			5/20/2038
2020 PO5396308842	KU	4	40 BRO	SP	CRE	ID	TD			5/21/2038
2020 PO5374608901	KU	4	40 BRO	SP	CRE	ID	TD			5/22/2038
2020 PO5384308976	KU	4	40 BRO	SP	CRE	ID	TD			5/23/2038
2020 PO5380708827	KU	6	30 BRO	SP	CRE	ID	TD			5/24/2038
2020 PO5366108833	KU	4	40 BRO	SP	CRE	ID	TD			5/25/2038
2020 PO5375808499	KU	3	55 BRO	SP	CCA	ED	T			5/26/2038
2020 PO5386708566	KU	6	30 BRO	SP	CCA		V			5/27/2038
2020 PO5335808344	KU	4	40 BRO	SP	CRE		V			5/28/2038
2020 PO6843094531	KU	4	40 BRN	SP	CRE	ED,ID	TD			5/29/2038
2020 PO3951682638	F	UNK	100 BRN	SP	A		V			5/30/2038
2020 PO3967983024	LGE	3	45 BRO	SP	CRE	ED,ID	TD			5/31/2038
2020 PO3968383034	LGE	1	90 BRO	SP	CRE		V			6/1/2038
2020 PO3968783042	LGE	3	45 BRO	SP	CRE	ED,ID,IP,MD	TX	RR		6/2/2038
2020 PO3969583060	LGE	3	45 BRO	SP	CRE	ED,ID,IP,MD	TX	RR		6/3/2038
2020 PO3969883070	LGE	1	90 BRO	SP	CRE		V			6/4/2038
2020 PO3970283079	LGE	4	45 BRO	SP	CRE	ED,ID	TD			6/5/2038
2020 PO3970983097	LGE	3	40 BRO	SP	CRE	ED,ID	TD			6/6/2038
2020 PO3952282652	LGE	2	20 BRN	SP	A	ED,HH,ID,RB	X	PX		6/7/2038

2020 PO3048240511	KU	3	45 ACE	SP	CRE	ED,ID,IP	TD	6/8/2038
2020 PO3953082671	LGE	2	20 BRN	SP	P	ED,ID	TD	6/9/2038
2020 PO3952682662	LGE	3	20 BRN	SP	A	ED,ID	TD	6/10/2038
2020 PO3971283104	LGE	UNK	100 BRO	SP	CRE		V	6/11/2038
2020 PO3972583133	LGE	2	50 BRO	SP	CRE	ED,ID	TD	6/12/2038
2020 PO3971783115	LGE	3	55 BRO	SP	A	ED,ID	TD	6/13/2038
2020 PO4721635183	KU	3	45 ACE	SP	CRE	ED,ID	BD	6/14/2038
2020 PO2849036369	KU	4	40 BRN	SP	CRE	ED,ID,IP,SRC	TD	6/15/2038
2020 PO2834436676	KU	5	35 BRN	SP	CRE	ID,IP	BD	6/16/2038
2020 PO3940782620	LGE	4	35 BRN	SP	P	ED,ID	TD	6/17/2038
2020 PO4732135303	KU	3	45 ACE	SP	CRE	ED,ID,IP	TD	6/18/2038
2020 PO4741135406	KU	3	45 ACE	SP	CCA		V	6/19/2038
2020 PO4729235269	KU	3	45 ACE	SP	CCA		V	6/20/2038
2020 PO3941082627	LGE	3	50 BRN	SP	CRE	ED,ID	TD	6/21/2038
2020 PO0939732353	ODP	5	35 XXX	SP	CRE	ED,ID	TD	6/22/2038
2020 PO0952432524	ODP	5	35 XXX	SP	CRE	ID	TD	6/23/2038
2020 PO3942382621	LGE	3	55 BRN	SP	CRE	ED,ID	BD	6/24/2038
2020 PO3943782615	LGE	1	40 BRN	SP	P	ED,ID	TD	6/25/2038
2020 PO2743651395	KU	3	45 BRO	SP	CCA		V	6/26/2038
2020 PO2820336969	KU	4	40 BRN	SP	CCA		V	6/27/2038
2020 PO2855737002	KU	6	30 BRN	SP	CCA		V	6/28/2038
2020 PO2611037874	KU	5	35 BRN	SP	CRE	ID,IP	BD	6/29/2038
2020 PO2639337909	KU	4	40 BRN	SP	CRE		V	6/30/2038
2020 PO8995259875	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD	7/1/2038
2020 PO8956360039	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD	7/2/2038
2020 PO3037167935	KU	4	40 BRN	SP	CRE	ID,IP	TD	7/3/2038
2020 PO0549760513	F	4	40 ACW	SP	CRE		V	7/4/2038
2020 PO0561860464	KU	6	30 ACW	SP	CRE	ED,ID	BD	7/5/2038
2020 PO0554860492	KU	3	45 ACW	SP	CRE	ED,ID	TD	7/6/2038
2020 PO0559060609	KU	3	45 ACW	SP	CRE	ED,ID	TD	7/7/2038
2020 PO0551560566	F	5	40 ACW	SP	CRE		V	7/8/2038
2020 PO0555360664	F	5	35 ACW	SP	CRE		V	7/9/2038
2020 PO3062868375	KU	4	40 BRN	SP	CRE	ID	TD	7/10/2038
2020 PO3048368456	KU	4	40 BRN	SP	CCA		V	7/11/2038
2020 PO3043668236	KU	4	40 BRN	SP	CCA		V	7/12/2038
2020 PO3021268253	KU	5	35 BRN	SP	CRE		B	7/13/2038
2020 PO3001668277	KU	4	40 BRN	SP	CRE	ID,IP,SRC	TD	7/14/2038
2020 PO2982568355	KU	4	40 BRN	SP	CRE	ED,ID	BD	7/15/2038
2020 PO2961168439	KU	4	40 BRN	SP	CCA		V	7/16/2038
2020 PO8935560132	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD	7/17/2038
2020 PO0536460664	F	6	30 ACW	SP	CCA		V	7/18/2038
2020 PO3877383065	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	7/19/2038
2020 PO4719635352	KU	3	45 ACE	SP	CCA		V	7/20/2038
2020 PO6799392618	KU	5	35 BRN	SP	CRE	ID	BD	7/21/2038
2020 PO6777092679	KU	6	30 BRN	SP	CRE	ED,ID,RB,SRC	X	7/22/2038
2020 PO6341412803	F	4	35 BRN	SP	CRE		V	7/23/2038
2020 PO6686313433	KU	6	30 BRN	SP	CRE		V	7/24/2038

2020 PO6582613318A	ODP	4	40 BRN	SP	CCA		V		7/25/2038
2020 PO4745435454	KU	3	45 ACE	SP	CRE	ED,ID	BD		7/26/2038
2020 PO3945482607	LGE	1	50 BRN	SP	P	ED,ID	BD		7/27/2038
2020 PO3947682805	LGE	3	45 BRO	SP	A	ED,ID	TD		7/28/2038
2020 PO3948382802	LGE	3	45 BRO	SP	CCA		V		7/29/2038
2020 PO3948882800	LGE	3	45 BRO	SP	CCA		V		7/30/2038
2020 PO3949482798	LGE	1	50 BRO	SP	CCA		V		7/31/2038
2020 PO3950182797	LGE	4	35 BRO	SP	P	ED,ID	TD		8/1/2038
2020 PO3950782673	LGE	3	50 BRN	SP	A	ED,ID	BD		8/2/2038
2020 PO0535360634	KU	4	40 ACW	SP	CRE	ED,ID	BD		8/3/2038
2020 PO9132420283	KU	4	45 UNK	SP	CRE	ED,ID,SRS	TD		8/4/2038
2020 PO0532860585	F	4	40 ACW	SP	CRE		V		8/5/2038
2020 PO0522861009	KU	4	40 ACW	SP	CRE	ED,ID	BD		8/6/2038
2020 PO1283946043	KU	4	40 BRN	SP	CRE	ID,IP	TD		8/7/2038
2020 PO9129619715	KU	4	40 OTH	SP	CRE	ID	TD		8/8/2038
2020 PO9147019868	KU	4	40 BRN	SP	CCA		V		8/9/2038
2020 PO9110620439	KU	4	40 UNK	SP	P	ED,SRS	TD		8/10/2038
2020 PO9155119922	KU	6	30 BRN	SP	CCA		V		8/11/2038
2020 PO9078620693	KU	5	35 INP	DF	CRE	ID	TD		8/12/2038
2020 PO9146019389	KU	5	35 UNK	SP	CRE	ID	TD		8/13/2038
2020 PO9148119671	KU	4	40 ACW	SP	CRE	ED,ID,SRS	TD		8/14/2038
2020 PO9131619598	KU	5	35 BRN	SP	CRE	ID	TD		8/15/2038
2020 PO9128819926	KU	4	40 OTH	SP	CRE	ID	TD		8/16/2038
2020 PO9139120033	KU	4	40 ACW	SP	CRE	ED,ID,SRS	TD		8/17/2038
2020 PO9136420097	KU	6	30 BRN	SP	CCA		V		8/18/2038
2020 PO9130619413	KU	3	50 BRN	SP	CCA		V		8/19/2038
2020 PO9105320657	KU	4	40 UNK	SP	CRE		V		8/20/2038
2020 P07588076378	KU	6	30 BRO	SP	A	ED,ID,IP	X	RP2	8/21/2038
2020 PO7703476135	KU	5	30 BRO	SP	A	HH,ID,IP	TX	RR	8/22/2038
2020 PO7655176161A	LGE	6	30 BRO	SP	CCA		V		8/23/2038
2020 PO4766188540	F	3	45 BRO	SP	S		V		8/24/2038
2020 PO9137119801	KU	6	30 OTH	SP	CRE	ID	TD		8/25/2038
2020 PO9122319860	KU	4	40 OTH	SP	CRE	ID	TD		8/26/2038
2020 PO9137020207	KU	6	30 MAR	SP	CRE	ED,ID,SRS	TD		8/27/2038
2020 PO9100120728	KU	4	40 UNK	SP	CRE		V		8/28/2038
2020 PO9092620822	KU	4	40 UNK	SP	CRE	ED,ID,SRC	TD		8/29/2038
2020 PO9082420809	KU	6	30 KOP	SP	CRE	ID	TD		8/30/2038
2020 PO9122719695	KU	5	35 UNK	SP	CRE	ED,ID,SRC	TD		8/31/2038
2020 PO9156920061	KU	6	30 BRN	SP	CCA		V		9/1/2038
2020 PO9157119998	KU	6	30 BRN	SP	CCA		V		9/2/2038
2020 PO9133019503	KU	3	45 BRN	SP	CCA		V		9/3/2038
2020 PO9140319584	KU	4	40 ACW	SP	CRE	ID	TD		9/4/2038
2020 PO9127620058	KU	4	40 UNK	SP	CRE	ID	TD		9/5/2038
2020 PO4773135767	KU	3	45 ACE	SP	CRE	ED,ID,IP	TD		9/6/2038
2020 PO4761835640	KU	3	45 ACE	SP	CRE	ED,ID	BD		9/7/2038
2020 PO0900233553	ODP	4	45 XXX	SP	CCA		V		9/8/2038
2020 PO0885933549	ODP	5	35 XXX	SP	CCA	ED	T		9/9/2038

2020 PO3876083037	LGE	4	35 BRO	SP	P	ED,HH,ID	BX	PX	9/10/2038
2020 PO8595288521	KU	4	45 ACE	SP	CCA		V		9/11/2038
2020 PO8795489676	KU	3	55 ACE	SP	CCA		V		9/12/2038
2020 PO8874590554	KU	3	55 ACE	SP	CCA		V		9/13/2038
2020 PO8884790782	KU	3	55 ACE	SP	CCA		V		9/14/2038
2020 PO8885791077	KU	3	45 ACE	SP	CCA		V		9/15/2038
2020 PO8895491020	KU	3	55 ACE	SP	CCA		V		9/16/2038
2020 PO8966492782	F	4	40 ACE	SP	CRE		V		9/17/2038
2020 PO8949793063	F	4	40 ACE	SP	CRE		V		9/18/2038
2020 PO8968792541	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	VX	RP1	9/19/2038
2020 PO8897194819	F	4	40 ACE	SP	CRE		V		9/20/2038
2020 PO0447823529	KU	5	35 ACE	SP	CCA		V		9/21/2038
2020 PO0451823692	F	7	20 ACE	SP	CRE		V		9/22/2038
2020 PO0808528999	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	VX	RP1	9/23/2038
2020 PO0839829329	F	4	40 ACE	SP	CCA		V		9/24/2038
2020 PO0875729693	F	4	40 ACE	SP	CRE		V		9/25/2038
2020 PO0803110204	KU	4	40 ACE	SP	CRE	ED,ID		TD	9/26/2038
2020 PO4829486427	F	4	45 XXX	SP	A		V		9/27/2038
2020 PO4828886401	LGE	4	35 XXX	SP	A	ED,ID		TD	9/28/2038
2020 PO4829386414	F	4	45 XXX	SP	CRE		V		9/29/2038
2020 PO4829386401	F	4	45 XXX	SP	A		V		9/30/2038
2020 PO4826186421	LGE	4	40 XXX	SP	CCA	ED		T	10/1/2038
2020 PO4827986423	LGE	4	40 XXX	SP	CCA		V		10/2/2038
2020 PO4829386392	LGE	4	45 XXX	SP	CCA		V		10/3/2038
2020 PO4829786381	F	2	25 XXX	SP	A		V		10/4/2038
2020 PO4676388808	LGE	4	35 BRO	SP	A	ED		TD	10/5/2038
2020 PO4829486381	F	4	45 XXX	SP	A		V		10/6/2038
2020 PO4829286364	F	4	40 XXX	SP	CCA		V		10/7/2038
2020 PO0372533124	ODP	4	40 XXX	SP	CRE		V		10/8/2038
2020 PO4829086346	F	4	45 XXX	SP	A		V		10/9/2038
2020 PO0361333186	ODP	5	30 XXX	SP	CCA		V		10/10/2038
2020 PO0385233352	ODP	4	35 XXX	SP	CRE	ED,ID,IP		TD	10/11/2038
2020 PO0400333570	ODP	4	40 XXX	SP	CRE	ED,ID,IP		TD	10/12/2038
2020 PO4037082617	LGE	4	40 BRN	SP	CRE	ED,ID		T	10/13/2038
2020 PO4039382671	F	4	40 BRN	SP	CRE		V		10/14/2038
2020 PO4598036287	KU	3	45 BRO	SP	CRE	ED,ID,IP		TD	10/15/2038
2020 PO4588636109	KU	3	45 BRO	SP	CRE	ID,IP		BD	10/16/2038
2020 PO4575936504	KU	2	45 BRO	SP	CCA		V		10/17/2038
2020 PO4595336262	KU	3	45 BRO	SP	P	ED		T	10/18/2038
2020 PO4613536433	KU	3	45 BRO	SP	CRE	ED		TD	10/19/2038
2020 PO4576136493	KU	2	45 BRO	SP	CCA		V		10/20/2038
2020 PO3943382976	F	5	25 BRO	SP	P		V		10/21/2038
2020 PO3944982987	F	5	40 BRO	SP	P		V		10/22/2038
2020 PO3945082981	F	4	30 BRO	SP	P		V		10/23/2038
2020 PO3944182971	F	4	40 BRO	SP	P		V		10/24/2038
2020 PO4038082659	F	4	40 BRN	SP	CRE		V		10/25/2038
2020 PO2042322300	ODP	4	40 XXX	SP	CRE	ID		TD	10/26/2038

2020 PO4833086354	LGE	4	40 XXX	SP	CCA		V		10/27/2038
2020 PO4830486346	LGE	4	40 XXX	SP	CCA		V		10/28/2038
2020 PO4676888792	LGE	3	45 BRO	SP	P	ED	T		10/29/2038
2020 PO4675888805-A	LGE	5	30 BRO	SP	CRE	ED,ID,IP	TD		10/30/2038
2020 PO4675088818	LGE	4	40 BRO	SP	CCA		V		10/31/2038
2020 PO4806388277	LGE	3	45 BRN	SP	CCA		V		11/1/2038
2020 PO4802288278	LGE	4	40 BRN	SP	CRE		V		11/2/2038
2020 PO5962078203	LGE	1	45 OTH	SP	CCA		V		11/3/2038
2020 PO4872686512	LGE	3	45 OTH	SP	CCA		V		11/4/2038
2020 PO4871486474	LGE	4	40 OTH	SP	CCA		V		11/5/2038
2020 PO4872986496	LGE	3	45 OTH	SP	P	ED,ID,SRS	TD		11/6/2038
2020 PO4872086520	LGE	1	45 OTH	UN	CCA		V		11/7/2038
2020 PO4886086317	LGE	3	50 OTH	SP	CCA		V		11/8/2038
2020 PO5960878243	LGE	3	50 OTH	SP	CCA	ED,SRS	TD		11/9/2038
2020 PO4873286484	F	4	40 OTH	SP	CCA		V		11/10/2038
2020 PO5854678158	LGE	3	45 OTH	SP	CCA		V		11/11/2038
2020 PO4886086306	LGE	3	45 OTH	SP	CCA	ED,SRS	TD		11/12/2038
2020 PO2052922095	ODP	4	40 XXX	SP	CRE	ID	TD		11/13/2038
2020 PO1973022582	ODP	4	40 XXX	SP	CRE	ID	BD		11/14/2038
2020 PO1928222708	ODP	4	40 XXX	SP	CCA		V		11/15/2038
2020 PO1928222708B	ODP	4	40 XXX	SP	CRE	ID	TD		11/16/2038
2020 PO1928222708A	ODP	5	35 XXX	SP	CRE	ID	TD		11/17/2038
2020 PO1945722930	ODP	4	40 XXX	SP	CRE	ID	TD		11/18/2038
2020 PO1939223264	ODP	5	35 XXX	SP	CCA		V		11/19/2038
2020 PO1967522948	ODP	4	40 XXX	SP	CRE	ID	TD		11/20/2038
2020 PO1966122730	ODP	4	40 XXX	SP	CRE	ID	BD		11/21/2038
2020 PO1985322756	ODP	5	35 XXX	SP	CRE	ID	TD		11/22/2038
2020 PO3943582959	F	4	40 BRO	SP	P		V		11/23/2038
2020 PO3942782963	F	5	25 BRO	SP	P		V		11/24/2038
2020 PO3944282944	F	4	40 BRO	SP	P		V		11/25/2038
2020 PO3943482946	F	4	40 BRO	SP	P		V		11/26/2038
2020 PO3943882931	F	5	25 BRO	SP	CCA		V		11/27/2038
2020 PO3943082933	F	4	40 BRO	SP	A		V		11/28/2038
2020 PO3942582921	F	4	40 BRO	SP	A		V		11/29/2038
2020 PO3942382925	LGE	5	30 BRO	SP	CCA		V		11/30/2038
2020 PO0392033844	ODP	4	40 XXX	SP	CRE	ED,ID	TD		12/1/2038
2020 PO4777387998	LGE	4	40 BRO	SP	CRE	ED	TD		12/2/2038
2020 PO0420233887	ODP	4	40 XXX	SP	CRE	ED,ID	TD		12/3/2038
2020 PO0357833691	ODP	4	40 XXX	SP	CRE	ED,ID	TD		12/4/2038
2020 0376234337a	ODP	6	30 XXX	SP	CRE	ED,ID	TD		12/5/2038
2020 PO0390934121	ODP	4	40 XXX	SP	CRE	ED,ID	TD		12/6/2038
2020 PO3925581910	F	4	30 CAH	SP	CCA	ED,ID	VX	RP2	12/7/2038
2020 PO3935781894	F	4	40 CAH	SP	CCA	ED,HH,ID,RB	VX	PX	12/8/2038
2020 PO3935981920	F	4	40 CAH	SP	CRE	ED,ID,IP	VX	PX	12/9/2038
2020 PO3936381944	F	4	40 CAH	SP	CCA		VX	RP3	12/10/2038
2020 PO3937481981	F	4	40 CAH	SP	CCA		VX	RP3	12/11/2038
2020 PO3931982022	LGE	4	30 CAH	SP	CRE	ED,HH,ID,RB	X	PX	12/12/2038

2020 PO3924281928	F	4	40 CAH	SP	CCA	ED,ID	VX	RP3	12/13/2038
2020 PO3926981896	LGE	4	40 CAH	SP	P	ED,ID	TD		12/14/2038
2020 PO3925581906	F	4	40 CAH	SP	CCA		V		12/15/2038
2020 PO3924581912	F	4	40 CAH	SP	CCA		V		12/16/2038
2020 PO3924181921	F	4	40 CAH	SP	CCA		V		12/17/2038
2020 PO3924681939	F	4	40 CAH	SP	CCA		V		12/18/2038
2020 PO3925181950	F	4	40 CAH	SP	CCA		V		12/19/2038
2020 PO3925681962	F	4	40 CAH	SP	CCA		V		12/20/2038
2020 PO3926181973	F	4	40 CAH	SP	CCA		V		12/21/2038
2020 PO3926681954	F	4	40 CAH	SP	CCA		V		12/22/2038
2020 PO3927081995	F	4	40 CAH	SP	CCA		V		12/23/2038
2020 PO3927582005	F	4	40 CAH	SP	CCA		V		12/24/2038
2020 PO3929082014	F	4	40 CAH	SP	CRE		V		12/25/2038
2020 PO3928082016	F	4	40 CAH	SP	CRE		V		12/26/2038
2020 PO3928282024	F	4	40 CAH	SP	CRE		V		12/27/2038
2020 PO3929982015	F	4	40 CAH	SP	CRE		V		12/28/2038
2020 PO3931382009	F	4	40 CAH	SP	CCA		V		12/29/2038
2020 PO3933981996	F	4	40 CAH	SP	CCA		V		12/30/2038
2020 PO3932982001	F	3	45 CAH	SP	CCA		V		12/31/2038
2020 PO3935081991	F	4	40 CAH	SP	CCA		V		1/1/2039
2020 PO3920882682	F	4	40 BRO	SP	CCA		V		1/2/2039
2020 PO3920182641	F	4	40 BRO	SP	A	MD	VX	RP3	1/3/2039
2020 PO4674888711	F	4	40 BRO	SP	A		V		1/4/2039
2020 PO4880986672	F	3	50 OTH	SP	P		V		1/5/2039
2020 PO4876686671	F	3	50 OTH	SP	P		V		1/6/2039
2020 PO4879286665	F	3	50 OTH	SP	P		V		1/7/2039
2020 PO4877986663	F	3	50 OTH	SP	P		V		1/8/2039
2020 PO4633688918	LGE	4	40 BRO	SP	CCA		V		1/9/2039
2020 PO4800987491	LGE	4	35 BRN	SP	CCA	ED,ID	BD		1/10/2039
2020 PO4635088932	LGE	4	40 BRO	SP	CRE	ID,IP	BD		1/11/2039
2020 PO4878086915	LGE	1	25 OTH	ST	CCA		V		1/12/2039
2020 PO4877586916	LGE	3	45 OTH	SP	P	ID	BD		1/13/2039
2020 PO4877286909	LGE	2	60 OTH	SP	P	ID	BD		1/14/2039
2020 PO4778888003	LGE	4	40 BRO	SP	CCA		V		1/15/2039
2020 PO4841786523	LGE	6	30 XXX	SP	P	ID	BD		1/16/2039
2020 PO4841786523	LGE	3	50 XXX	SP	P	ID	BD		1/17/2039
2020 PO4635488934	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		1/18/2039
2020 PO4036682645	F	4	40 BRN	SP	S		V		1/19/2039
2020 PO4802387487	LGE	4	35 BRN	SP	CRE	ED,ID,RB	BX	RR	1/20/2039
2020 PO4035982629	F	4	40 BRN	SP	S		V		1/21/2039
2020 PO4034982640	F	4	40 BRN	SP	A		V		1/22/2039
2020 PO4033982652	F	4	40 BRN	SP	CRE		V		1/23/2039
2020 PO4032982663	F	4	40 BRN	SP	CRE		V		1/24/2039
2020 PO4032082674	F	4	40 BRN	SP	CRE		V		1/25/2039
2020 PO4031082685	F	4	40 BRN	SP	CRE		V		1/26/2039
2020 PO3936281986	F	4	40 CAH	SP	CCA		V		1/27/2039
2020 PO3936581970	F	4	40 CAH	SP	CCA		V		1/28/2039

2020 PO3936681956	F	4	40 CAH	SP	CCA		V	1/29/2039
2020 PO4030182696	F	4	40 BRN	SP	CRE		V	1/30/2039
2020 PO4029282707	F	4	45 BRN	SP	A		V	1/31/2039
2020 PO4028082721	F	4	45 BRN	SP	A		V	2/1/2039
2020 PO4027582732	F	3	45 BRN	SP	A		V	2/2/2039
2020 PO4028182744	F	3	45 BRN	SP	A		V	2/3/2039
2020 PO4028182759	F	4	40 BRN	SP	A		V	2/4/2039
2020 PO3936181931	F	4	40 CAH	SP	CCA		V	2/5/2039
2020 PO3935481920	F	4	30 CAH	SP	CRE		V	2/6/2039
2020 PO3935381908	F	4	40 CAH	SP	CRE		V	2/7/2039
2020 PO4803987484	LGE	4	40 BRN	SP	CCA		V	2/8/2039
2020 PO4633788922	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	2/9/2039
2020 PO4784287930	LGE	4	40 BRO	SP	CRE	ED	BD	2/10/2039
2020 PO4876786688	LGE	3	45 OTH	SP	P	ED,SRS	TD	2/11/2039
2020 PO4875286722	F	3	55 OTH	SP	P		V	2/12/2039
2020 PO4875786705	F	3	50 OTH	SP	P		V	2/13/2039
2020 PO4875186725	F	3	55 OTH	SP	P		V	2/14/2039
2020 PV5898380008	LGE	3	45 OTH	SP	CCA		V	2/15/2039
2020 PO4876286687	F	3	50 OTH	SP	P		V	2/16/2039
2020 PO4781787921	LGE	3	45 BRO	SP	CCA		V	2/17/2039
2020 PO4780887919	LGE	4	40 BRO	SP	CRE	ED	BD	2/18/2039
2020 PO4779087922	LGE	4	40 BRO	SP	CRE	ED	BD	2/19/2039
2020 PO4777787924	LGE	4	40 BRO	SP	CRE	ED	B	2/20/2039
2020 PO4874587777	F	4	45 XXX	SP	A		V	2/21/2039
2020 PO4874287784	F	4	40 XXX	SP	A		V	2/22/2039
2020 PO4842086505A	LGE	5	30 XXX	SP	P	ID	BD	2/23/2039
2020 PO4014201464	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	2/24/2039
2020 PO3934181896	F	4	30 CAH	SP	CRE		V	2/25/2039
2020 PO4882387129	LGE	3	50 OTH	SP	P	ID	BD	2/26/2039
2020 PO4019401286	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	2/27/2039
2020 PO3070739710	F	4	40 ACE	SP	CRE		V	2/28/2039
2020 PO4050602257	F	4	40 BRO	SP	CRE		V	3/1/2039
2020 PO3568349447	KU	3	45 ACE	SP	CRE	ED,ID	BD	3/2/2039
2020 PO3572249550	KU	5	35 ACE	SP	CCA	ED,ID	TD	3/3/2039
2020 PO3572249513	KU	4	45 ACE	SP	CCA	ED,ID	TD	3/4/2039
2020 PO3576949674	KU	3	45 ACE	SP	CCA	ED,ID	BD	3/5/2039
2020 PO3581149694	F	4	35 ACE	SP	CRE	ED,HH,ID,MD,RB	V	3/6/2039
2020 PO3604049500	KU	4	40 ACE	SP	CRE	ED,ID	TD	3/7/2039
2020 PO3591649566	KU	4	40 ACE	SP	CCA	ED,ID	BD	3/8/2039
2020 PO3619049419	KU	3	45 ACE	SP	CCA		V	3/9/2039
2020 PO3933981890	F	4	40 CAH	SP	CRE		V	3/10/2039
2020 PO3935681884	F	4	40 CAH	SP	CRE		V	3/11/2039
2020 PO3935481872	F	4	40 CAH	SP	CRE		V	3/12/2039
2020 PO3935181859	F	3	45 CAH	SP	CCA		V	3/13/2039
2020 PO3934881845	F	4	40 CAH	SP	CRE		V	3/14/2039
2020 PO3935981838	F	4	40 CAH	SP	CRE		V	3/15/2039
2020 PO3937182016	F	3	45 CAH	SP	CCA		V	3/16/2039

2020 PO3934582027	F		4	40 CAH	SP	CRE	ED,ID	V		3/17/2039
2020 PO3935982021	F		4	40 CAH	SP	CRE		V		3/18/2039
2020 PO3932582020	F		4	45 CAH	SP	CCA		V		3/19/2039
2020 PO3933382033	F		4	40 CAH	SP	CRE		V		3/20/2039
2020 PO3932682037	F		4	40 CAH	SP	CRE		V		3/21/2039
2020 PO3933482053	F		4	40 CAH	SP	CCA		V		3/22/2039
2020 PO3933882064	F		4	40 CAH	SP	A		V		3/23/2039
2020 PO3934382076	F		4	40 CAH	SP	P		V		3/24/2039
2020 PO3935282098	F		4	40 CAH	SP	A		V		3/25/2039
2020 PO3934782087	F		3	45 CAH	SP	CCA		V		3/26/2039
2020 PO4029582778	F		4	40 BRN	SP	A		V		3/27/2039
2020 PO4831586462	LGE		4	30 XXX	SP	CRE	HH,ID	X	PX	3/28/2039
2020 PO4832786460	LGE	3H		45 XXX	SP	P	ID	BD		3/29/2039
2020 PO4833986461	LGE		3	45 XXX	SP	P	ID	BD		3/30/2039
2020 PO4648488937	LGE		4	40 BRO	SP	CRE	ED,ID,IP	TD		3/31/2039
2020 PO4883087122	LGE		3	45 OTH	AL	CCA		V		4/1/2039
2020 PO4882887120	LGE		4	40 OTH	SP	CCA		V		4/2/2039
2020 PO4875587746	F		4	40 XXX	SP	A		V		4/3/2039
2020 PO4876087729	F		5	35 KOP	SP	A		V		4/4/2039
2020 PO4654588957	LGE		4	40 BRO	SP	CRE	ED,ID,IP	TD		4/5/2039
2020 PO4883687129	LGE		3	50 OTH	SP	P	ID	BD		4/6/2039
2020 PO4883487148	LGE		4	35 OTH	SP	CCA		V		4/7/2039
2020 PO4755787883	LGE	UNK		45 BRO	SP	CRE	ED	TD		4/8/2039
2020 PO4755687887	F		3	50 BRO	SP	CCA		V		4/9/2039
2020 PO4754687884	LGE	UNK		70 BRO	SP	CRE		V		4/10/2039
2020 PO4868586755	LGE		3	45 OTH	SP	P	ED,SRS	TD		4/11/2039
2020 PO4834186452	LGE		3	50 XXX	SP	P	ID	TD		4/12/2039
2020 PO3949582521	LGE		6	30 BRN	SP	CRE	ED,ID	BD		4/13/2039
2020 PO3950382516	F		4	40 BRN	SP	CRE		V		4/14/2039
2020 PO3950482533	F		6	30 BRN	SP	CRE		V		4/15/2039
2020 PO3951082527	F		4	40 BRN	SP	CRE		V		4/16/2039
2020 PO4798731974	KU		2	40 BRN	SP	CRE	ID	BD		4/17/2039
2020 PO4789332010	KU		4	40 BRN	SP	CRE	ID	BD		4/18/2039
2020 PO3952182535	F		4	40 BRN	SP	CRE		V		4/19/2039
2020 PO3953282544	F		4	40 BRN	SP	CRE		V		4/20/2039
2020 PO3954282554	F		3	45 BRN	SP	S		V		4/21/2039
2020 PO3954882568	F		5	30 BRN	SP	CCA		V		4/22/2039
2020 PO3955382562	F		4	40 BRN	SP	CRE		V		4/23/2039
2020 PO3956182576	F		5	30 BRN	SP	CRE		V		4/24/2039
2020 PO3956382569	F		4	40 BRN	SP	CRE		V		4/25/2039
2020 PO1717422749	ODP		2	50 XXX	SP	CCA		V		4/26/2039
2020 PO1718122876	F		4	40 XXX	SP	A		V		4/27/2039
2020 PO2183841875	ODP		4	45 KOP	SP	A	ED,ID	TD		4/28/2039
2020 PO1724222613	ODP		5	35 XXX	SP	CCA		V		4/29/2039
2020 PO1746022750	ODP		2	50 XXX	SP	CCA		V		4/30/2039
2020 PO1787622210	F		5	35 XXX	SP	CRE		V		5/1/2039
2020 PO1798722260	ODP		4	40 XXX	SP	CRE	HH,ID,RB	BX	RP3	5/2/2039

2020 PO4740722618	KU	3	45 BRO	SP	CCA		V	5/3/2039
2020 PO4733022893	KU	3	45 BRO	SP	CCA		V	5/4/2039
2020 PO5803546498	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD	5/5/2039
2020 PO9624493600	KU	6	30 ACW	SP	S		V	5/6/2039
2020 PO9626493903	KU	6	30 ACW	SP	CRE	ED,ID	BD	5/7/2039
2020 PO9632293883	KU	6	30 ACW	SP	CRE	ED,ID	BD	5/8/2039
2020 PO9637493894	KU	4	45 ACW	SP	CRE	ED,ID	BD	5/9/2039
2020 PO9616693704	KU	3	45 ACW	SP	S		V	5/10/2039
2020 PO9618293799	KU	3	45 ACW	SP	CRE		V	5/11/2039
2020 PO9615593660	KU	6	30 ACW	SP	S		V	5/12/2039
2020 PO9644893585	KU	5	35 ACW	SP	S		V	5/13/2039
2020 PO9633393720	KU	2	40 ACW	SP	CRE		V	5/14/2039
2020 PO9635593719	KU	2	55 ACW	SP	CRE		V	5/15/2039
2020 PO4727023197	KU	3	45 BRO	SP	CCA		V	5/16/2039
2020 PO4720523520	KU	3	45 BRO	SP	CCA		V	5/17/2039
2020 PO4714023844	KU	3	45 BRO	SP	CCA		V	5/18/2039
2020 PO1772122865	ODP	4	45 XXX	SP	CCA		V	5/19/2039
2020 PO2176841760	ODP	5	30 KOP	SP	S		V	5/20/2039
2020 PO4781132123	KU	3	45 BRN	SP	CCA		V	5/21/2039
2020 PO4761931684	KU	4	40 BRN	SP	CRE	ID	BD	5/22/2039
2020 PO4754431498	KU	3	50 BRN	SP	CCA		V	5/23/2039
2020 PO4785831486	KU	6	30 BRN	SP	CCA		V	5/24/2039
2020 PO4773131429	KU	4	40 BRN	SP	CRE	ID,IP	BD	5/25/2039
2020 PO4780431403	KU	4	45 BRN	SP	CRE		V	5/26/2039
2020 PO4792031362	KU	4	40 BRN	SP	CRE		V	5/27/2039
2020 PO3748037463	KU	6	30 BRN	SP	CRE	ED,ID,IP,MD	BD	5/28/2039
2020 PO3974082315	F	4	40 BRN	SP	CCA		V	5/29/2039
2020 PO3972882321	F	4	40 BRN	SP	CRE		V	5/30/2039
2020 PO3973282323	F	4	40 BRN	SP	A		V	5/31/2039
2020 PO3971982330	F	4	30 BRN	SP	S		V	6/1/2039
2020 PO3971582328	F	4	40 BRN	SP	S		V	6/2/2039
2020 PO3970682333	F	4	40 BRN	DF	CRE		V	6/3/2039
2020 PO3970982335	F	5	30 BRN	SP	CRE		V	6/4/2039
2020 PO3970482343	F	4	40 BRN	SP	S		V	6/5/2039
2020 PO4704424170	KU	3	45 BRO	SP	CCA		V	6/6/2039
2020 PO5692353026	KU	3	45 ACE	SP	CCA		V	6/7/2039
2020 PO5711152958	KU	3	45 ACE	SP	CCA		V	6/8/2039
2020 PO5691952976	KU	4	40 ACE	SP	CRE	ED,ID	BD	6/9/2039
2020 PO5687252709	KU	4	40 ACE	SP	CRE	ED,ID	BD	6/10/2039
2020 PO5866153330	KU	6	30 ACE	SP	CCA	ED	T	6/11/2039
2020 PO5008229388	C	4	40 BRO	SP	CRE		V	6/12/2039
2020 PO2319652607	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/13/2039
2020 PO2275155460	KU	4	40 BRO	SP	CCA		V	6/14/2039
2020 A	KU	4	45 UNK	SP	CCA		V	6/15/2039
2020 A	KU	6	30 UNK	SP	CRE	ID	TD	6/16/2039
2020 PO8359425925	F	4	40 UNK	SP	P		B	6/17/2039
2020 PO8415425769	F	4	40 UNK	SP	P		B	6/18/2039

2020 PO8199526298	KU	6	30 UNK	SP	CRE	ID	TD		6/19/2039
2020 PO8202326357	KU	4	40 UNK	SP	CRE	ED,ID,SRS	TD		6/20/2039
2020 PO8392625887	F	4	40 UNK	SP	P		B		6/21/2039
2020 PO8325025949	F	4	40 UNK	SP	CRE		B		6/22/2039
2020 PO8283825992	KU	6	30 UNK	SP	CCA		V		6/23/2039
2020 PO8282726057	KU	6	30 UNK	SP	CCA		V		6/24/2039
2020 PO8304125959	F	4	40 UNK	SP	P		B		6/25/2039
2020 PO8244026107	KU	4	40 UNK	SP	CRE	ID	TD		6/26/2039
2020 PO7322889778	KU	6	30 BRO	SP	CCA		V		6/27/2039
2020 PO4054882637	LGE	2	55 BRO	SP	CCA		VX	RP3	6/28/2039
2020 PO7277289321	KU	6	30 BRO	SP	CCA		V		6/29/2039
2020 PO7261089287	KU	5	35 BRO	SP	CCA		V		6/30/2039
2020 PO3368543488	KU	5	35 ACE	SP	CRE	ED,ID	BD		7/1/2039
2020 PO727888461	KU	4	45 BRO	SP	CRE	ED	X	RR	7/2/2039
2020 PO7298188575	KU	4	45 BRO	SP	CRE	ED,ID	TD		7/3/2039
2020 PO7293788507	KU	5	35 BRO	SP	CRE	ED,ID	TD		7/4/2039
2020 PO7316788707	KU	4	40 BRO	SP	CRE	ED,ID	BD		7/5/2039
2020 PO7334588834	KU	4	40 BRO	SP	CRE	ED,ID	TD		7/6/2039
2020 PO7351488957	KU	4	45 BRO	SP	CRE	ED,ID	BD		7/7/2039
2020 PO7370489093	KU	4	40 BRO	SP	CRE	ED,ID	BD		7/8/2039
2020 PO3397544855	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD		7/9/2039
2020 PO2641742916	KU	5	35 BRN	SP	CRE	ED,ID,MD,SRC	TD		7/10/2039
2020 PO3153741538	KU	4	40 ACE	SP	CCA		V		7/11/2039
2020 PO3353643412	KU	4	40 ACE	SP	CCA		V		7/12/2039
2020 PO2460955732	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		7/13/2039
2020 PO2439655602	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD		7/14/2039
2020 PO4044382909	LGE	4	40 BRO	SP	P	ED,ID	TX	RR	7/15/2039
2020 PO4479712324	F	4	40 ACE	SP	CRE		V		7/16/2039
2020 PO4716388474	LGE	4	40 BRN	SP	A	ED,ID	BD		7/17/2039
2020 PO4716488472	LGE	UNK	70 BRN	SP	A		V		7/18/2039
2020 PO4716688470	LGE	4	40 BRN	SP	A	ED,ID	BD		7/19/2039
2020 PO4720388498	F	UNK	30 BRN	SP	CRE		V		7/20/2039
2020 PO4721488491	F	4	40 BRN	SP	A		V		7/21/2039
2020 PO1007638592	ODP	5	35 XXX	SP	CRE	ID	TD		7/22/2039
2020 PO1086239613	ODP	4	40 XXX	SP	CRE	ID	TD		7/23/2039
2020 PO1055939295	ODP	5	35 XXX	SP	CRE	ID	TD		7/24/2039
2020 PO1044639126	ODP	5	35 XXX	SP	CRE	ID	TD		7/25/2039
2020 PO1031838937	ODP	5	35 XXX	SP	CRE	ID	TD		7/26/2039
2020 PO1020138770	ODP	4	40 XXX	SP	CCA		V		7/27/2039
2020 PO1037138372	ODP	5	35 XXX	SP	CRE	ID	TD		7/28/2039
2020 PO4468412231	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX	7/29/2039
2020 PO2391055267	KU	4	40 BRO	SP	CRE	ID,RB	X	RP1	7/30/2039
2020 PO2348254993	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD		7/31/2039
2020 PO2330955092	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD		8/1/2039
2020 PO2313655194	KU	4	40 BRO	SP	CRE	ED	TD		8/2/2039
2020 PO2322755372	KU	4	40 BRO	SP	CRE	ED	TD		8/3/2039
2020 PO2619943039	KU	4	40 BRN	SP	CRE	ED,ID,IP,MD,SRC	TD		8/4/2039

2020 PO2600343150	KU	5	35 BRN	SP	CRE	ED,ID,MD,SRC	TD	8/5/2039
2020 PO4408334413	KU	4	45 BRO	SP	P	ID	TD	8/6/2039
2020 PO4447134957	KU	2	50 BRO	SP	CRE	ID	TD	8/7/2039
2020 PO3406244740	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	8/8/2039
2020 PO3406244805	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	8/9/2039
2020 PO4367333902	KU	3	45 BRO	SP	CRE	ID	TD	8/10/2039
2020 PO4374533998	KU	3	45 BRO	SP	CCA		V	8/11/2039
2020 PO4386634158	KU	3	45 BRO	SP	CRE	ID	TD	8/12/2039
2020 PO4423634631	KU	3	45 BRO	SP	CCA		V	8/13/2039
2020 PO3354444077	KU	4	40 ACE	SP	CRE	ED,ID	BD	8/14/2039
2020 PO4456612139	F	4	40 ACE	SP	CRE		V	8/15/2039
2020 PO4333711475	F	2	50 ACE	SP	CCA		V	8/16/2039
2020 PO4724588539	LGE	4	35 BRN	SP	S		V	8/17/2039
2020 PO4725388548	LGE	4	30 BRN	SP	S		V	8/18/2039
2020 PO4723588556	LGE	4	40 BRN	SP	CCA	ED,HH,ID,RB	X PX	8/19/2039
2020 PO4721088564	LGE	4	35 BRN	SP	CRE	ED,ID	BD	8/20/2039
2020 PO4046582913	LGE	4	40 BRO	SP	CCA	ED,ID	X RP2	8/21/2039
2020 PO4046282907	LGE	4	40 BRO	SP	P	ED,ID	TD	8/22/2039
2020 PO4078211385	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	8/23/2039
2020 PO4046082902	LGE	4	30 BRO	SP	P	ED,ID	TD	8/24/2039
2020 PO4337111502	F	2	50 ACE	SP	CCA		V	8/25/2039
2020 PO4340211506	F	2	50 ACE	SP	CCA		V	8/26/2039
2020 PO4722588574	LGE	4	40 BRN	SP	CRE	ED,ID	BD	8/27/2039
2020 PO4723188577	LGE	6	25 BRN	SP	CRE	ED,ID	BD	8/28/2039
2020 PO1477634762	ODP	3	55 BRN	SP	CCA		V	8/29/2039
2020 PO1548834334	ODP	6	30 BRN	SP	CCA		V	8/30/2039
2020 PO3360744403	KU	4	40 ACE	SP	CRE	ED,ID	BD	8/31/2039
2020 PO4057882898	LGE	4	40 BRO	SP	P	ED,ID	TX RR	9/1/2039
2020 PO3372744611	KU	3	40 ACE	SP	P		V	9/2/2039
2020 PO3385744836	KU	3	40 ACE	SP	CCA		V	9/3/2039
2020 PO3483444749	KU	5	35 ACE	SP	CCA		V	9/4/2039
2020 PO3458544510	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	9/5/2039
2020 PO4434134781	KU	3	45 BRO	SP	CCA		V	9/6/2039
2020 PO4448834886	KU	5	35 BRO	SP	CCA		V	9/7/2039
2020 PO7234289229	KU	6	30 BRO	SP	CRE	ED,ID,MD	TX RR	9/8/2039
2020 PO2581643256	KU	4	40 BRN	SP	CRE	ED,ID,MD,SRC	TD	9/9/2039
2020 PO2537343508	KU	5	35 BRN	SP	CRE	ED,ID,MD,SRC	TD	9/10/2039
2020 PO2559043385	KU	4	40 BRN	SP	CRE	ID	BD	9/11/2039
2020 PO2660842751	F	4	30 BRN	SP	CRE		V	9/12/2039
2020 PO2519043612	KU	4	40 BRN	SP	CCA		V	9/13/2039
2020 PO4459735048	KU	3	45 BRO	SP	CCA		V	9/14/2039
2020 PO4471235131	KU	3	55 BRO	SP	CCA		V	9/15/2039
2020 PO4499735294-A	KU	2	55 BRO	SP	CCA		V	9/16/2039
2020 PO7333088381	KU	4	40 BRO	SP	CRE	ED,ID	BD	9/17/2039
2020 PO4055982900	LGE	4	40 BRO	SP	P	ED,ID	TD	9/18/2039
2020 PO4719888528	LGE	4	40 BRN	SP	CRE	ED,ID	BD	9/19/2039
2020 PO4719288538	LGE	4	40 BRN	SP	A	ED,ID	TD	9/20/2039

2020 PO4718688548	LGE	4	40 BRN	SP	S		V	9/21/2039
2020 PO4278998382	LGE	4	40 BRN	SP	CCA		V	9/22/2039
2020 PO4108911256	KU	2	45 BRO	SP	CRE	ID,IP	BD	9/23/2039
2020 PO4116311417	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	9/24/2039
2020 PO4121711527	KU	3	45 BRO	SP	CRE	ID,IP	BD	9/25/2039
2020 PO4056611821	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	9/26/2039
2020 PO3886913345	KU	4	45 BRO	SP	CRE	ID	BD	9/27/2039
2020 PO3888913543	KU	4	45 BRO	SP	CRE	ED,ID	TD	9/28/2039
2020 PO3892613732	KU	4	45 BRO	SP	CRE	ID	BD	9/29/2039
2020 PO3896913903	KU	4	45 BRO	SP	CCA		V	9/30/2039
2020 PO4717688565	LGE	4	40 BRN	SP	CCA		V	10/1/2039
2020 PO4717388571	LGE	4	40 BRN	SP	CRE	ED,ID	BD	10/2/2039
2020 PO4716888578	LGE	3	45 BRN	DF	S		V	10/3/2039
2020 PO4716888578-A	LGE	4	40 BRN	SP	S		V	10/4/2039
2020 PO7333188298	KU	6	30 BRO	SP	CRE	ED,ID	BD	10/5/2039
2020 PO7313788436	KU	4	40 BRO	SP	CRE	ED,ID	BD	10/6/2039
2020 PO7318888426	KU	3	30 BRO	SP	CRE	ED	VX	RP2 10/7/2039
2020 PO3486844351	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	10/8/2039
2020 PO3438944851	KU	5	35 ACE	SP	CRE	ED,ID	BD	10/9/2039
2020 PO3456244877	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	10/10/2039
2020 PO3435044643	KU	4	40 ACE	SP	CRE	ED,ID	BD	10/11/2039
2020 PO7201989595	KU	4	40 BRO	SP	CRE	ED,ID	TD	10/12/2039
2020 PO2272650814	KU	3	45 BRO	SP	CCA		V	10/13/2039
2020 PO2301950747	KU	3	45 BRO	SP	CCA		V	10/14/2039
2020 PO2331150681	KU	3	45 BRO	SP	CCA		V	10/15/2039
2020 PO2360450614	KU	3	45 BRO	SP	CCA		V	10/16/2039
2020 PO1730059431	KU	4	40 BRN	SP	CRE	ID,IP	TD	10/17/2039
2020 PO1738859391	KU	4	40 BRN	SP	CRE	ID	BD	10/18/2039
2020 PO3119038633	KU	4	30 BRN	SP	CRE	ED,ID,SRS	TD	10/19/2039
2020 PO3110738535	KU	4	40 BRN	SP	CRE	ID	BD	10/20/2039
2020 PO7010194113	KU	4	40 BRN	SP	CRE	ED,ID	BD	10/21/2039
2020 PO7019394215	KU	4	40 BRN	SP	CRE	ED,ID	TD	10/22/2039
2020 PO3768543273	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	10/23/2039
2020 PO3719142714	KU	5	35 ACE	SP	CRE	ED,ID	TD	10/24/2039
2020 PO7171890582	KU	5	35 BRO	SP	CRE	ED,ID	TD	10/25/2039
2020 PO7177990654	KU	6	30 BRO	SP	CRE	ED,ID	TD	10/26/2039
2020 PO7175490830	KU	4	40 BRO	SP	CRE	ED,ID	TD	10/27/2039
2020 PO6281304771	KU	6	30 XXX	SP	CRE		V	10/28/2039
2020 PO3750042999	KU	4	40 ACE	SP	P	ED	T	10/29/2039
2020 PO6242401313	KU	6	30 XXX	SP	CCA		V	10/30/2039
2020 PO6245201449	KU	4	40 XXX	SP	CCA		V	10/31/2039
2020 PO6243201608	KU	4	40 XXX	SP	CCA		V	11/1/2039
2020 PO6236601763	KU	5	35 XXX	SP	CRE		V	11/2/2039
2020 PO6894801507	KU	5	35 BRN	SP	CRE	ED,ID	TD	11/3/2039
2020 PO7190190728	KU	3	50 BRO	SP	CRE	ED,ID	TD	11/4/2039
2020 PO7186290752	KU	4	40 BRO	SP	CRE	ED,ID	TD	11/5/2039
2020 PO7197090879	KU	5	35 BRO	SP	CRE	ED,ID	TD	11/6/2039

2020 PO7215191101	KU	5	35 BRO	SP	CRE	ED,ID	TD	11/7/2039
2020 PO7266191475	KU	5	35 BRO	SP	CCA		V	11/8/2039
2020 PO7276491401	F	4	40 BRO	SP	P		V	11/9/2039
2020 PO7283891481	F	4	45 BRO	SP	CRE		V	11/10/2039
2020 PO7274791591	F	4	40 BRO	SP	CRE		V	11/11/2039
2020 PO7265791695	F	4	40 BRO	SP	CRE		V	11/12/2039
2020 PO7257891770	F	4	40 BRO	SP	CRE		V	11/13/2039
2020 PO7251891857	F	4	40 BRO	SP	CRE		V	11/14/2039
2020 PO7247591850	F	5	35 BRO	SP	CRE		V	11/15/2039
2020 PO7296391878	F	3	40 BRO	SP	CRE		V	11/16/2039
2020 PO7286891970	F	3	45 BRO	SP	CRE		V	11/17/2039
2020 PO7296892048	KU	5	30 BRO	SP	CCA		V	11/18/2039
2020 PO7284692095	F	4	30 BRO	SP	CRE		V	11/19/2039
2020 PO6877201561	KU	5	35 BRN	SP	CRE	ED,ID,IP	TX	RR 11/20/2039
2020 PO6867501589	KU	6	30 BRN	SP	CRE	ED,ID	TD	11/21/2039
2020 PO6852101570	KU	6	30 BRN	SP	CRE		V	11/22/2039
2020 PO6837001555	KU	4	40 BRN	SP	CCA		V	11/23/2039
2020 PO4431710892	F	4	40 ACE	SP	CRE		V	11/24/2039
2020 PO3146538594	KU	4	45 BRN	SP	CCA		V	11/25/2039
2020 PO4041535936	KU	4	40E BRO	SP	CRE	ID,IP	TD	11/26/2039
2020 PO6268113039	KU	4	40 BRO	SP	CCA		V	11/27/2039
2020 PO6268613242	KU	3	45 BRO	SP	CCA		V	11/28/2039
2020 PO6279813297	KU	4	40 BRO	SP	CCA		V	11/29/2039
2020 PO6288913343	KU	4	40 BRO	SP	CCA		V	11/30/2039
2020 PO6218712973	KU	6	30 BRO	SP	CCA		V	12/1/2039
2020 PO6205712942	KU	6	30 BRO	SP	CCA		V	12/2/2039
2020 PO6195913020	KU	4	40 BRO	SP	CCA		V	12/3/2039
2020 PO6166613115	KU	6	30 BRO	SP	CCA		V	12/4/2039
2020 PO6172112832	KU	4	40 BRO	SP	CCA		V	12/5/2039
2020 PO6173213021	KU	4	40 BRO	SP	CCA		V	12/6/2039
2020 PO6151013057	KU	4	40 BRO	SP	CCA		V	12/7/2039
2020 PO6160313029	KU	4	40 BRO	SP	CCA		V	12/8/2039
2020 PO6145713131	KU	4	40 BRO	SP	CCA		V	12/9/2039
2020 PO6148912334	KU	4	45 BRO	SP	CCA		V	12/10/2039
2020 PO6172212314	KU	4	45 BRO	SP	CCA		V	12/11/2039
2020 PO4438710842	F	4	40 ACE	SP	CRE		V	12/12/2039
2020 PO4410911039	F	4	40 ACE	SP	CRE		V	12/13/2039
2020 PO4420610971	F	4	40 ACE	SP	CRE		V	12/14/2039
2020 PO4400511111	F	4	40 ACE	SP	CRE		V	12/15/2039
2020 PO4390111182	F	4	40 ACE	SP	CRE		V	12/16/2039
2020 PO4042382910	LGE	4	40 BRO	SP	CRE	ED,ID	TD	12/17/2039
2020 PO4043382909	LGE	4	40 BRO	SP	CRE	ED,ID	BD	12/18/2039
2020 PO4042582905	LGE	4	40 BRO	SP	CRE	ED,ID	BD	12/19/2039
2020 PO4041782903	LGE	4	30 BRO	SP	P	ED,ID	BD	12/20/2039
2020 PO4732488561	LGE	4	40 BRN	DF	CRE	ED,ID	BD	12/21/2039
2020 PO4731388558	LGE	3	45 BRN	SP	CRE	ED,ID	BD	12/22/2039
2020 PO4730288547	LGE	1	60 BRN	SP	CRE		V	12/23/2039

2020 PO2698849465	ODP	4	45 KOP	SP	S		V		12/24/2039
2020 PO4730188553	LGE	4	35 BRN	SP	CRE	ED,ID	BD		12/25/2039
2020 PO4726588561	LGE	4	40 BRN	SP	A	ED,ID	BD		12/26/2039
2020 PO4727488549	LGE	4	40 BRN	SP	CCA	ED,ID	BD		12/27/2039
2020 PO4225011667	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		12/28/2039
2020 PO6188312274	KU	4	45 BRO	SP	CCA		V		12/29/2039
2020 8430745402a	ODP	6	30 XXX	SP	CRE	ED,ID,RB	BX	RP1	12/30/2039
2020 PO6186212195	KU	5	35 BRO	SP	CCA		V		12/31/2039
2020 PO6202012140	KU	6	30 BRO	SP	CCA		V		1/1/2040
2020 PO6210412253	KU	4	45 BRO	SP	CCA		V		1/2/2040
2020 PO6174312643	KU	4	45 BRO	SP	CCA		V		1/3/2040
2020 PO4060535663	KU	3	45 BRO	SP	CCA		V		1/4/2040
2020 PO4051435860	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		1/5/2040
2020 PO4087835571	KU	4	35E BRO	SP	CRE	ED,HH,ID,IP	X	RP1	1/6/2040
2020 PO3736343145	KU	4	40 ACE	SP	P	ED	T		1/7/2040
2020 PO3067839049	KU	4	40 BRN	SP	CRE	ID,IP	BD		1/8/2040
2020 PO7026494299	KU	4	40 BRN	SP	CRE	ED,ID,RB,SRC	TX	RR	1/9/2040
2020 PO7033994257	KU	6	30 BRN	SP	CRE	ED,ID	TD		1/10/2040
2020 PO7068094830	KU	4	40 BRN	SP	CRE	ED,ID	TD		1/11/2040
2020 PO3096339031	KU	4	40 BRN	SP	CCA		V		1/12/2040
2020 PO3004138781	KU	4	40 BRN	SP	CRE	ED,ID,IP,MD,SRC	TD		1/13/2040
2020 PO4107435416	KU	5	30 BRO	SP	CRE	ED,ID,IP	TD		1/14/2040
2020 PO4117235339	KU	6	35 BRO	SP	CRE	ED,ID,IP	TD		1/15/2040
2020 PO8363545681	F	5	30 XXX	SP	A		V		1/16/2040
2020 PO8394445668	F	4	40 XXX	SP	A		V		1/17/2040
2020 PO8430745402	F	4	40 XXX	SP	CRE		V		1/18/2040
2020 PO8449345325	F	4	40 XXX	SP	A		V		1/19/2040
2020 PO8463445252	F	4	40 XXX	SP	A		V		1/20/2040
2020 PO8470045180	F	4	40 XXX	SP	A		V		1/21/2040
2020 PO8477045107	F	4	40 XXX	SP	A		V		1/22/2040
2020 PO4939610439	F	4	40 ACE	SP	P		V		1/23/2040
2020 PO4924310132	F	4	40 ACE	SP	P		V		1/24/2040
2020 PO2292742315	F	4	40 KOP	SP	P		V		1/25/2040
2020 PO2331445377	ODP	6	30 KOP	SP	S		V		1/26/2040
2020 PO2369644591	F	4	40 KOP	SP	P		V		1/27/2040
2020 PO2360644853	F	4	40 KOP	SP	P		V		1/28/2040
2020 PO2378145035	F	4	40 KOP	SP	P		V		1/29/2040
2020 PO2364045445	F	4	40 KOP	SP	CRE		V		1/30/2040
2020 PO2371945589	F	4	40 KOP	SP	CRE		V		1/31/2040
2020 PO2088143229	F	4	40 KOP	SP	CRE		V		2/1/2040
2020 PO2086443505	ODP	4	40 KOP	SP	CRE	ED,ID	TD		2/2/2040
2020 PO4173834847	KU	5	30 BRO	SP	CRE	ED,ID,IP	TD		2/3/2040
2020 PO3026439061	KU	4	40 BRN	SP	CRE	ID,IP	BD		2/4/2040
2020 6426703783a	KU	6	30 XXX	SP	CRE	ED,ID	TD		2/5/2040
2020 PO6417103773	KU	6	30 XXX	SP	CRE		V		2/6/2040
2020 PO6414003712	KU	6	30 XXX	SP	CRE	ED,ID	TD		2/7/2040
2020 PO6410003814	F	6	30 XXX	SP	CRE		V		2/8/2040

2020 PO6404903737	F	4	40 XXX	SP	CRE		V		2/9/2040
2020 PO6400803619	KU	3	50 BRN	SP	CRE		V		2/10/2040
2020 PO3715743364	KU	4	40 ACE	SP	CCA		V		2/11/2040
2020 PO3016338934	KU	4	40 BRN	SP	CRE	ID	BD		2/12/2040
2020 PO7279290480	KU	5	35 BRO	SP	CRE	ED,ID	BD		2/13/2040
2020 PO4214330370	KU	2	50 BRO	SP	CCA		V		2/14/2040
2020 PO4852010909	KU	3	45 ACE	SP	P	ED	T		2/15/2040
2020 PO4752488667	LGE	4	40 BRN	SP	S		V		2/16/2040
2020 PO4751388684	LGE	4	40 BRN	SP	CRE	ED,ID	TD		2/17/2040
2020 PO4858111067	KU	3	45 ACE	SP	CCA		V		2/18/2040
2020 PO4751888719	LGE	4	30 BRN	SP	CRE	ED,ID	TD		2/19/2040
2020 PO4756989161	LGE	3	45 BRO	SP	CRE	ED,ID	TD		2/20/2040
2020 PO4757989191	LGE	4	40 BRO	SP	CCA		V		2/21/2040
2020 PO4756189180	LGE	3	50 BRO	SP	CCA		V		2/22/2040
2020 PO4756189178	LGE	2	45 BRO	SP	CRE	ED,ID	BD		2/23/2040
2020 PO4758089156	LGE	4	35 BRO	SP	CRE	ED,ID	BD		2/24/2040
2020 PO4756189189	LGE	3	50 BRO	SP	CCA		V		2/25/2040
2020 PO4757589197	LGE	3	50 BRO	SP	CCA		V		2/26/2040
2020 PO4758589203	F	3	50 BRO	SP	CCA		V		2/27/2040
2020 PO4759289209	F	3	50 BRO	SP	CCA		V		2/28/2040
2020 PO4761289219	F	3	50 BRO	SP	CCA		V		2/29/2040
2020 PO4731589163	F	2	45 BRO	SP	CCA		V		3/1/2040
2020 PO4872110474	KU	5	35 ACE	SP	P	ED	T		3/2/2040
2020 PO4036583029	LGE	4	40 BRO	SP	P	ED,ID	BD		3/3/2040
2020 PO4037483028	LGE	4	35 BRO	SP	CRE	ED,ID	TD		3/4/2040
2020 PO4037083040	LGE	4	35 BRO	SP	P	ED,ID	TD		3/5/2040
2020 PO4036483041	LGE	4	40 BRO	SP	P	ED,ID	BD		3/6/2040
2020 PO5017009146	F	4	40 ACE	SP	CRE	ED,ID	V		3/7/2040
2020 PO4748788690	LGE	4	35 BRN	SP	CRE	ED,ID	BD		3/8/2040
2020 PO4749388688	LGE	4	30 BRN	SP	A	ED,ID	BD		3/9/2040
2020 PO4749588697	LGE	4	40 BRN	SP	S		V		3/10/2040
2020 PO4750388699	LGE	4	40 BRN	SP	CRE	ED,ID	TD		3/11/2040
2020 PO4749588713	LGE	3	45 BRN	SP	CRE	ED,ID	BD		3/12/2040
2020 PO5008809175	F	4	40 ACE	SP	P		V		3/13/2040
2020 PO4994409209	F	4	40 ACE	SP	P		V		3/14/2040
2020 PO4235711753	KU	4	40 BRO	SP	CRE	ID	BD		3/15/2040
2020 PO4246411884	KU	4	40 BRO	SP	CRE	HH,ID,RB	BX	PX	3/16/2040
2020 PO4050082802	LGE	4	40 BRO	SP	CRE	ED,ID	BD		3/17/2040
2020 PO4733889135	F	3	50 BRO	SP	CCA		V		3/18/2040
2020 PO4746888781	LGE	4	40 BRN	SP	CRE	ED,ID	BX	RR	3/19/2040
2020 PO4747588786	LGE	3	45 BRN	SP	S		V		3/20/2040
2020 PO4933608859	KU	3	45 ACE	SP	CRE	ED,ID,IP	TD		3/21/2040
2020 PO4937408925	F	3	45 ACE	SP	CRE		V		3/22/2040
2020 PO4744188764	LGE	4	40 BRN	SP	CRE	ED,ID	TD		3/23/2040
2020 PO4744888769	LGE	4	40 BRN	SP	P	ED,ID	TD		3/24/2040
2020 PO4047082799	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		3/25/2040
2020 PO4048482800	LGE	4	40 BRO	SP	P	ED,ID	TD		3/26/2040

2020 PO4058282872	LGE	4	40 BRO	SP	CRE	ED,ID	TD	3/27/2040
2020 PO4961008831	F	4	40 ACE	SP	CRE		V	3/28/2040
2020 PO4959908807	F	4	40 ACE	SP	P		V	3/29/2040
2020 PO4745788775	LGE	3	45 BRN	SP	S		V	3/30/2040
2020 PO4744688791	LGE	4	40 BRN	SP	CRE	ED,ID	BD	3/31/2040
2020 PO4743888804	LGE	4	40 BRN	SP	CCA		V	4/1/2040
2020 PO4743388813	LGE	4	40 BRN	SP	CRE	ED,ID	TD	4/2/2040
2020 PO4056882869	LGE	4	30 BRO	SP	CCA		V	4/3/2040
2020 PO4053582836	LGE	4	30 BRO	SP	CCA		V	4/4/2040
2020 PO4052082817	LGE	4	40 BRO	SP	CRE	ED,ID	TD	4/5/2040
2020 PO4053782833	LGE	4	40 BRO	SP	CRE	ED,ID	TD	4/6/2040
2020 PO4055282845	LGE	4	40 BRO	SP	CRE	ED,ID	TD	4/7/2040
2020 PO4056782859	LGE	4	40 BRO	SP	CRE	ED,ID	TD	4/8/2040
2020 PO4056282866	LGE	4	35 BRO	SP	P	ED,ID	TD	4/9/2040
2020 PO4742588826	LGE	4	40 BRN	SP	S		V	4/10/2040
2020 PO4741888837	LGE	4	40 BRN	SP	CRE	ED,ID	BD	4/11/2040
2020 PO4741188849	LGE	4	40 BRN	SP	A	ED,ID	TD	4/12/2040
2020 PO4505301370	LGE	4	35 BRN	SP	CCA		V	4/13/2040
2020 PO4739888841	LGE	4	40 BRN	SP	CRE	ED,ID	BD	4/14/2040
2020 PO4499101329	LGE	4	35 BRN	SP	S		V	4/15/2040
2020 PO4494201297	LGE	4	45 BRN	SP	S		V	4/16/2040
2020 PO4052982869	LGE	4	40 BRO	SP	P	ED,ID	TD	4/17/2040
2020 PO4296212317	KU	4	40 BRO	SP	CRE	ID,IP	BD	4/18/2040
2020 PO4694288783	LGE	3	45 BRO	SP	A	ED,ID	BD	4/19/2040
2020 PO4054482947	LGE	4	40 BRO	SP	P	ED,ID	BD	4/20/2040
2020 PO4054582933	LGE	4	35 BRO	SP	P	ED,ID	TD	4/21/2040
2020 PO4054382901	LGE	4	40 BRO	SP	CCA	ED,HH,ID,RB	X	RP2 4/22/2040
2020 PO4768288683	LGE	4	40 BRN	SP	S		V	4/23/2040
2020 PO4767388683	LGE	4	35 BRN	SP	CCA		V	4/24/2040
2020 PO4767388680	LGE	4	40 BRN	SP	S		V	4/25/2040
2020 PO4765888678	LGE	4	35 BRN	SP	CCA		V	4/26/2040
2020 PO4766388676	LGE	3	45 BRN	SP	S		V	4/27/2040
2020 PO4696488753	LGE	4	45 BRO	SP	CRE	ED,ID	BD	4/28/2040
2020 PO4695588765	LGE	4	45 BRO	SP	A	ED,ID	BD	4/29/2040
2020 PO4052882940	LGE	4	40 BRO	SP	CRE	ED,ID	TD	4/30/2040
2020 PO4052882933	LGE	4	35 BRO	SP	P	ED,ID	BD	5/1/2040
2020 PO4697088745	LGE	4	40 BRO	SP	CCA		V	5/2/2040
2020 PO4698088730	LGE	4	40 BRO	SP	CCA		V	5/3/2040
2020 PO4698688723	LGE	3	45 BRO	SP	CCA		V	5/4/2040
2020 PO4765388672	LGE	3	45 BRN	SP	S		V	5/5/2040
2020 PO4762188662	LGE	4	40 BRN	SP	S		V	5/6/2040
2020 PO4763788667	LGE	3	45 BRN	SP	S		V	5/7/2040
2020 PO4763588670	LGE	4	40 BRN	SP	S		V	5/8/2040
2020 PO4699188716	LGE	4	40 BRO	SP	CCA		V	5/9/2040
2020 PO4699788706	LGE	4	40 BRO	SP	CCA		V	5/10/2040
2020 PO4700488711	LGE	4	30 BRO	SP	CRE	ED,ID	TD	5/11/2040
2020 PO4700988691	LGE	3	45 BRO	SP	CCA		V	5/12/2040

2020 PO4701388686	LGE	3	45 BRO	SP	CCA		V		5/13/2040
2020 PO4758488749	LGE	4	40 BRN	SP	CRE	ED,ID	TD		5/14/2040
2020 PO4758188748	LGE	4	40 BRN	SP	CRE	ED,ID	TD		5/15/2040
2020 PO4051682935	LGE	4	40 BRO	SP	A	ED,ID	TD		5/16/2040
2020 PO7694141077	LGE	4	40 BRO	SP	P	ED	T		5/17/2040
2020 PO4051082904	LGE	4	40 BRO	SP	P	ED,ID	BD		5/18/2040
2020 PO4048282921	LGE	4	40 BRO	SP	CRE	ED,ID	TD		5/19/2040
2020 PO4757588762	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD		5/20/2040
2020 PO4702588669	LGE	3	45 BRO	SP	CRE	ED,ID	BD		5/21/2040
2020 PO4704488656	LGE	4	40 BRO	SP	CRE	ED,ID	BD		5/22/2040
2020 PO4703788652	LGE	4	40 BRO	SP	CRE	ED,ID	BD		5/23/2040
2020 PO4703188661	LGE	4	40 BRO	SP	CRE	ED,ID	BD		5/24/2040
2020 PO4049782927	F	4	40 BRO	SP	CCA		V		5/25/2040
2020 PO4756988773	LGE	4	40 BRN	SP	CCA		V		5/26/2040
2020 PO4756388783	LGE	4	40 BRN	SP	CRE	ED,HH,ID,IP	TX	RR	5/27/2040
2020 PO4705688636	LGE	6	25 BRO	SP	CRE	ED,ID	TD		5/28/2040
2020 PO4705188632	LGE	4	40 BRO	SP	CRE	ED,ID	BD		5/29/2040
2020 PO4704588641	LGE	4	40 BRO	SP	CRE	ED,ID	BD		5/30/2040
2020 PO4755688793	LGE	4	35 BRN	SP	CRE	ED,ID,IP	TD		5/31/2040
2020 PO4706688612	LGE	4	40 BRO	SP	P	ED,ID	BD		6/1/2040
2020 PO4705888623	LGE	3	45 BRO	SP	CCA		V		6/2/2040
2020 PO4217698141	LGE	4	40 BRO	SP	S		V		6/3/2040
2020 PO4709988580	LGE	UNK	25 BRO	SP	CRE		V		6/4/2040
2020 PO4202598342	LGE	4	40 BRO	SP	S		V		6/5/2040
2020 PO4708588586	LGE	3	45 BRO	SP	CCA		V		6/6/2040
2020 PO4708788579	LGE	4	40 BRO	SP	CRE	ED	VX	RP3	6/7/2040
2020 PO4709288575	LGE	4	40 BRO	SP	CRE		V		6/8/2040
2020 PO4707588599	LGE	4	40 BRO	SP	CRE	ED,ID	BD		6/9/2040
2020 PO4712588524	LGE	3	45 BRO	SP	CCA		V		6/10/2040
2020 PO4709888564	LGE	3	45 BRO	SP	CCA		V		6/11/2040
2020 PO4713688510	LGE	4	40 BRO	SP	CCA		V		6/12/2040
2020 PO4755088802	LGE	4	40 BRN	SP	CRE	ED,ID	BD		6/13/2040
2020 PO4754488812	LGE	4	40 BRN	SP	A	ED,ID	TD		6/14/2040
2020 PO4753788824	LGE	3	45 BRN	SP	A	ED,ID	TD		6/15/2040
2020 PO4752388847	LGE	3	45 BRN	SP	S		V		6/16/2040
2020 PO4752988844	LGE	4	30 BRN	SP	S		V		6/17/2040
2020 PO4800817031	KU	4	40 BRO	SP	CRE	ID,IP	BD		6/18/2040
2020 PO4788416694	F	4	40 BRO	SP	CRE		V		6/19/2040
2020 PO4783116774	F	4	40 BRO	SP	CRE		V		6/20/2040
2020 PO4779116835	F	4	40 BRO	SP	CRE		V		6/21/2040
2020 PO4767516990	F	4	40 BRO	SP	CRE		V		6/22/2040
2020 PO4752288854	LGE	4	30 BRN	SP	S		V		6/23/2040
2020 PO4751688856	LGE	3	45 BRN	SP	S		V		6/24/2040
2020 PO4751788864	LGE	4	30 BRN	SP	S		V		6/25/2040
2020 PO4857616737	KU	2	50 BRO	SP	CRE	ID,IP	BD		6/26/2040
2020 PO4855416722	KU	2	45 BRO	SP	CRE	ID,IP	BD		6/27/2040
2020 PO4718988437	LGE	3	50 BRO	SP	CRE	ED,ID	BD		6/28/2040

2020 PO1944924053	ODP	4	40 XXX	SP	CRE	ID	TD		6/29/2040
2020 PO1951124106	ODP	6	30 XXX	SP	CCA	ED	T		6/30/2040
2020 PO2064325009	ODP	5	35 XXX	SP	CRE	ID	TD		7/1/2040
2020 PO2037425044	ODP	5	35 XXX	SP	CCA		V		7/2/2040
2020 PO4755988734	LGE	4	40 BRN	SP	CRE	ED,ID	TD		7/3/2040
2020 PO4824617170	KU	2	45 BRO	SP	CRE	ID,IP	BD		7/4/2040
2020 PO4808117415	KU	3	45 BRO	SP	CCA		V		7/5/2040
2020 PO4804417469	KU	5	45 BRO	SP	CRE	ED,ID,IP	TD		7/6/2040
2020 PO4755288746	LGE	4	40 BRN	SP	CRE	ED,ID	BD		7/7/2040
2020 PO4754488759	LGE	4	40 BRN	SP	CRE	ED,HH,ID,IP,SRC	TX	RR	7/8/2040
2020 PO4722588386	LGE	4	35 BRO	SP	CRE	ED,ID	BD		7/9/2040
2020 PO4723488373	LGE	4	40 BRO	SP	CRE	ED,ID	TD		7/10/2040
2020 PO4720488417	LGE	1	50 BRO	SP	CCA		V		7/11/2040
2020 PO4004382910	LGE	4	40 BRO	SP	A	ED,ID	TD		7/12/2040
2020 PO4796717582	KU	3	50 BRO	SP	CRE	ID	BD		7/13/2040
2020 PO4814217706	KU	3	45 BRO	SP	CRE	ID,IP	BD		7/14/2040
2020 PO4805617645	KU	3	45 BRO	SP	CCA		V		7/15/2040
2020 PO4724388367	LGE	4	35 BRO	SP	A	ED,ID	BD		7/16/2040
2020 PO4724788365	LGE	4	30 BRO	SP	CRE	ED,ID	BD		7/17/2040
2020 PO4726088355	LGE	4	30 BRO	SP	CRE	ED,ID	TD		7/18/2040
2020 PO4725188343	LGE	4	35 BRO	SP	CRE		V		7/19/2040
2020 PO4725488358	LGE	4	35 BRO	SP	P		V		7/20/2040
2020 PO2011924355	ODP	6	30 XXX	SP	CCA		V		7/21/2040
2020 PO2008524559	ODP	4	45 XXX	SP	CCA	ED	T		7/22/2040
2020 PO2021924608	ODP	6	30 XXX	SP	CCA		V		7/23/2040
2020 PO2027924795	ODP	5	35 XXX	SP	CRE	ID	TD		7/24/2040
2020 PO4749589167	F	3	45 BRO	SP	CCA		V		7/25/2040
2020 PO4748789179	F	3	45 BRO	SP	CCA		V		7/26/2040
2020 PO4573304590	LGE	4	30 BRO	SP	A	ED,ID	TD		7/27/2040
2020 PO4746589215	F	4	40 BRO	SP	CRE	MD	VX	RP3	7/28/2040
2020 PO4745889226	F	4	40 BRO	SP	CRE		V		7/29/2040
2020 PO4745189238	F	4	40 BRO	SP	CCA		V		7/30/2040
2020 PO4744389250	F	4	40 BRO	SP	CRE		V		7/31/2040
2020 PO2013424857	ODP	6	30 XXX	SP	CCA	ED	T		8/1/2040
2020 PO2008224765	ODP	4	40 XXX	SP	CRE	ID	TD		8/2/2040
2020 PO2076924402	ODP	4	40 XXX	SP	CRE	ID	TD		8/3/2040
2020 PO2089924399	ODP	4	40 XXX	SP	CRE	ID	BD		8/4/2040
2020 PO2089224507	ODP	4	45 XXX	SP	CRE	ID	TD		8/5/2040
2020 PO2039624613	F	4	40 XXX	SP	CRE		V		8/6/2040
2020 PO2048524614	ODP	4	40 XXX	SP	CRE	ID	TD		8/7/2040
2020 PO2069024652	ODP	4	40 XXX	SP	CRE	ID	TD		8/8/2040
2020 PO2083224690	ODP	4	40 XXX	SP	CRE	ID	TD		8/9/2040
2020 PO2081224881	ODP	5	35 XXX	SP	CRE	ID,IP	TX	RR	8/10/2040
2020 PO2045525303	ODP	4	40 XXX	DF	CRE		V		8/11/2040
2020 PO1288632661	ODP	6	30 XXX	SP	CRE		V		8/12/2040
2020 PO4754388771	LGE	4	30 BRN	SP	CRE	HH,ID	BD		8/13/2040
2020 PO4753788770	LGE	4	40 BRN	SP	A	ED,ID	TD		8/14/2040

2020 PO4753288778	LGE	4	40 BRN	SP	S		V	8/15/2040
2020 PO4752788785	LGE	4	40 BRN	SP	CRE	ED,ID,IP	BD	8/16/2040
2020 PO5268501564	F	4	40 ACE	SP	CCA		V	8/17/2040
2020 PO5287901551	F	4	40 ACE	SP	CCA		V	8/18/2040
2020 PO5308701536	F	4	40 ACE	SP	CRE		V	8/19/2040
2020 PO5333601498	F	3	40 ACE	SP	CCA		V	8/20/2040
2020 PO5348701438	F	4	40 ACE	SP	CRE		V	8/21/2040
2020 PO5363501352	F	4	40 ACE	SP	CRE		V	8/22/2040
2020 PO5378901266	F	4	40 ACE	SP	CCA		V	8/23/2040
2020 PO3420440160	F	4	40 ACE	SP	CRE		V	8/24/2040
2020 PO3408039996	F	4	40 ACE	SP	CRE		V	8/25/2040
2020 PO4326041790	F	4	40 ACE	SP	CRE		V	8/26/2040
2020 PO5431301056	F	3	40 ACE	SP	CCA		V	8/27/2040
2020 PO5407001142	F	4	40 ACE	SP	CRE		V	8/28/2040
2020 PO5160401633	F	4	40 ACE	SP	CRE		V	8/29/2040
2020 PO4474409520	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/30/2040
2020 PO9224182972	KU	5	30 BRN	SP	S		V	8/31/2040
2020 PO9220482853	KU	4	45 BRN	SP	CRE	ED,ID	TD	9/1/2040
2020 PO5653845621	KU	3	45 ACE	SP	CRE	ED,ID	BD	9/2/2040
2020 PO9450193378	KU	6	30 ACW	SP	CRE		V	9/3/2040
2020 PO9441593333	KU	4	45 ACW	SP	S		V	9/4/2040
2020 PO9456893353	KU	4	45 ACW	SP	CRE		V	9/5/2040
2020 PO9459093197	KU	4	40 ACW	SP	CRE		V	9/6/2040
2020 PO9334893134	KU	6	30 ACW	SP	CCA		V	9/7/2040
2020 PO9346393063	KU	4	40 ACW	SP	CRE	ED,ID,SRC	TD	9/8/2040
2020 PO9334793069	C	4	40 ACW	SP	CRE		V	9/9/2040
2020 PO9279892875	KU	6	35 ACW	SP	S		V	9/10/2040
2020 PO9269593026	KU	5	35 ACW	SP	S		V	9/11/2040
2020 PO5673545369	KU	3	45 ACE	SP	CRE	ED,ID	BD	9/12/2040
2020 PO5696145101	KU	3	45 ACE	SP	CRE	ED,ID	BD	9/13/2040
2020 PO5717944833	KU	2	50 ACE	SP	CRE	ED,ID	BD	9/14/2040
2020 PO5779444963	KU	4	40 ACE	SP	CRE	ED,ID	BD	9/15/2040
2020 PO4540710382	KU	6	35 BRO	SP	CRE	ED,ID,IP	TD	9/16/2040
2020 PO9207882466	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD	9/17/2040
2020 PO9228682828	KU	6	30 BRN	SP	CCA		V	9/18/2040
2020 PO5761745315	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD	9/19/2040
2020 PO9168982113	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/20/2040
2020 PO9235282376	KU	5	35 BRN	SP	CRE	ED,ID,SRC	TD	9/21/2040
2020 PO4459411697	F	4	40 ACE	SP	CRE		V	9/22/2040
2020 PO4381737583	KU	4	45 BRO	SP	CRE		V	9/23/2040
2020 PO4386137652	KU	4	45 BRO	SP	CCA		V	9/24/2040
2020 PO4385137666	KU	4	45 BRO	SP	CCA		V	9/25/2040
2020 PO4390237718	KU	4	45 BRO	SP	CRE		V	9/26/2040
2020 PO4390737755	KU	4	45 BRO	SP	CCA		V	9/27/2040
2020 PO4622009719	F	4	40 ACE	DF	CRE		V	9/28/2040
2020 PO1395722988	ODP	6	30 XXX	SP	CRE	ID	BD	9/29/2040
2020 PO1391123047	ODP	6	30 XXX	SP	CRE	ID	TD	9/30/2040

2020 PO1399223068	ODP	6	30 XXX	SP	CRE	ID	TD	10/1/2040
2020 PO1403623121	ODP	3	40 XXX	SP	CRE	ID	TD	10/2/2040
2020 PO4638010246	F	5	30 ACE	SP	CRE		V	10/3/2040
2020 PO4631310337	F	4	40 ACE	SP	CRE		V	10/4/2040
2020 PO4617609964	F	4	40 ACE	SP	CRE		V	10/5/2040
2020 PO4621410059	KU	6	30 ACE	SP	CRE	ED,ID	BD	10/6/2040
2020 PO3145240719a	KU	6	30 ACE	SP	P	ED,ID	TD	10/7/2040
2020 PO3174041247	KU	4	40 ACE	SP	CRE	ED,ID	TD	10/8/2040
2020 PO3163241052	KU	4	40 ACE	SP	CRE	ED,ID	TD	10/9/2040
2020 PO3153740878	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	10/10/2040
2020 PO3145240719	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	10/11/2040
2020 PO5284602275	KU	3	40 ACE	SP	CRE	ED,ID,IP	TD	10/12/2040
2020 PO5249902042	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	10/13/2040
2020 PO5242302284	KU	4	45 ACE	SP	CRE	ED,ID,IP	TD	10/14/2040
2020 PO5224902854	KU	4	45 ACE	SP	CRE	ED,ID,IP	TD	10/15/2040
2020 PO5228202990-A	KU	3	40 ACE	SP	CRE	ED,ID,IP	TD	10/16/2040
2020 PO4498243288	F	4	40 ACE	SP	CCA		V	10/17/2040
2020 PO4477643365	F	4	40 ACE	SP	CCA		V	10/18/2040
2020 PO4496643023	KU	4	40 ACE	SP	CRE	ED,ID	TD	10/19/2040
2020 PO4558043357	KU	4	40 ACE	SP	CRE	ED,ID	TD	10/20/2040
2020 PO4462642873	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	10/21/2040
2020 PO4475242970	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	10/22/2040
2020 PO4508443350	KU	4	45 ACE	SP	CCA		V	10/23/2040
2020 PO4508643056	F	3	40 ACE	SP	P		V	10/24/2040
2020 PO5711150838	F	4	40 ACE	SP	P		V	10/25/2040
2020 PO2470546313	F	4	40 KOP	SP	CRE		V	10/26/2040
2020 PO2623747553	ODP	5	35 KOP	DF	CRE	ED,ID	TD	10/27/2040
2020 PO2630747811	ODP	4	40 KOP	SP	CRE	ED,ID	TD	10/28/2040
2020 PO2658147861	ODP	5	35 KOP	SP	CRE	ED,ID	TD	10/29/2040
2020 PO2682147751	ODP	5	35 KOP	DF	CRE	ED,ID	TD	10/30/2040
2020 PO2684847914	ODP	4	40 KOP	SP	CRE	ED,ID	TD	10/31/2040
2020 PO2682448043	ODP	4	40 KOP	SP	CRE	ED,ID	TD	11/1/2040
2020 PO2671448245	F	4	40 KOP	SP	CRE		V	11/2/2040
2020 PO4623910117	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX 11/3/2040
2020 PO4620810212	F	5	35 ACE	SP	CRE		V	11/4/2040
2020 PO4625910170	F	4	40 ACE	SP	CRE		V	11/5/2040
2020 PO4624910437	F	4	40 ACE	SP	P		V	11/6/2040
2020 PO4585210276	F	5	35 ACE	SP	CRE	ED,ID	V	11/7/2040
2020 PO1241624012	ODP	6	30 XXX	SP	CCA		V	11/8/2040
2020 PO1254724150	ODP	6	30 XXX	SP	CCA		V	11/9/2040
2020 PO1267424018	ODP	4	45 XXX	SP	CCA		V	11/10/2040
2020 PO1301723811	ODP	4	45 XXX	SP	CRE	ID	TD	11/11/2040
2020 PO1323423989	ODP	4	40 XXX	SP	CRE	ID	TD	11/12/2040
2020 PO1260224394	ODP	5	35 XXX	SP	CRE		V	11/13/2040
2020 PO1278224463	ODP	4	45 XXX	SP	CCA		V	11/14/2040
2020 PO1296924249	ODP	4	40 BRN	SP	CRE	ID	TD	11/15/2040
2020 PO4593409210	F	5	35 ACE	SP	CRE	ED,ID	V	11/16/2040

2020 PO4252011083	KU	4	40 BRO	SP	CRE	ID,IP	BD		11/17/2040
2020 PO4240010959	KU	4	40 BRO	SP	CRE	ID,IP	BD		11/18/2040
2020 PO4231510882	KU	4	40 BRO	SP	CRE	ED,ID,RB	TX	RR	11/19/2040
2020 PO4568811839	F	4	40 ACE	SP	CRE		V		11/20/2040
2020 PO4560512133	F	4	40 ACE	SP	CRE		V		11/21/2040
2020 PO4565111973	F	4	40 ACE	SP	P		V		11/22/2040
2020 PO4552712232	F	4	40 ACE	SP	CRE		V		11/23/2040
2020 PO4544912330	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX	11/24/2040
2020 PO4258411137	KU	4	40 BRO	SP	CRE	ID,RB	BD		11/25/2040
2020 PO4475799873	LGE	4	35 BRN	SP	A	ED,ID	TD		11/26/2040
2020 PO4735988702	LGE	4	35 BRN	SP	A	ED,ID	TD		11/27/2040
2020 PO4735088698	LGE	4	35 BRN	SP	A	ED,ID	TD		11/28/2040
2020 PO4547012278	KU	6	30 ACE	SP	CCA		V		11/29/2040
2020 PO4539912394	KU	5	35 ACE	SP	CCA		V		11/30/2040
2020 PO1472834561	ODP	4	40 SWP	SP	CRE		V		12/1/2040
2020 PO1489034610	ODP	6	35 SWP	SP	CRE		V		12/2/2040
2020 PO1481034615	ODP	6	35 SWP	SP	CRE		V		12/3/2040
2020 PO4534712461	F	4	40 ACE	SP	CRE	ED,ID	V		12/4/2040
2020 PO4532312491	F	4	40 ACE	SP	CRE		V		12/5/2040
2020 PO4521112627	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,MD	BX	PX	12/6/2040
2020 PO4512912562	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	RP1	12/7/2040
2020 PO4610411020	KU	4	40 ACE	SP	CCA		V		12/8/2040
2020 PO4276611002	F	4	40 ACE	SP	P		V		12/9/2040
2020 PO4264510913	F	4	40 ACE	SP	CCA		V		12/10/2040
2020 PO4253710815	F	4	40 ACE	SP	P		V		12/11/2040
2020 PO4240910691	F	4	40 ACE	SP	P		V		12/12/2040
2020 PO4230810599	F	2	50 ACE	SP	CCA		V		12/13/2040
2020 PO4220510502	F	4	40 ACE	SP	P		V		12/14/2040
2020 PO4210110406	F	4	40 ACE	SP	P		V		12/15/2040
2020 PO4198310298	F	4	40 ACE	SP	P		V		12/16/2040
2020 PO4224811274	KU	4	40 BRO	SP	CRE	ID	BD		12/17/2040
2020 PO4735888685	LGE	4	35 BRN	SP	A	ED,ID	BD		12/18/2040
2020 PO4737688679	LGE	4	35 BRN	SP	A	ED,ID	TD		12/19/2040
2020 PO4212211169	KU	4	40 BRO	SP	CRE	ID,IP	BD		12/20/2040
2020 PO2724547975	ODP	5	35 KOP	SP	CRE	ED,ID	TD		12/21/2040
2020 PO2734148291	ODP	5	35 KOP	DF	CRE	ED,ID	TD		12/22/2040
2020 PO2732748379	ODP	5	30 KOP	SP	CRE	ED,ID	TD		12/23/2040
2020 PO2707748941	ODP	4	40 KOP	SP	CRE	ED,ID	TD		12/24/2040
2020 PO2675748376	ODP	4	45 KOP	SP	CRE	ED,ID	TD		12/25/2040
2020 PO2662748446	F	4	40 KOP	SP	CRE		V		12/26/2040
2020 PO2661248617	F	4	40 KOP	SP	S		V		12/27/2040
2020 PO2620748792	ODP	4	40 KOP	SP	S		V		12/28/2040
2020 PO2678348965	ODP	5	35 KOP	SP	A	ED,ID	TD		12/29/2040
2020 PO2676949104	ODP	6	30 KOP	SP	CRE	ED,ID	TD		12/30/2040
2020 PO2659348753	ODP	3	45 KOP	SP	CCA		V		12/31/2040
2020 PO2670748773	F	4	40 KOP	SP	CCA		V		1/1/2041
2020 PO2657748898	F	4	40 KOP	SP	CRE		V		1/2/2041

2020 PO2652049213	ODP	4	40 KOP	DF	CRE	ED,ID	TD	1/3/2041
2020 PO4760040583	KU	3	45 ACE	SP	CCA		V	1/4/2041
2020 PO4731340383	KU	3	45 ACE	SP	CCA		V	1/5/2041
2020 PO4788740784	KU	3	45 ACE	SP	CCA		V	1/6/2041
2020 PO5123042681	KU	4	45 ACE	SP	CRE	ED,ID,IP	TD	1/7/2041
2020 PO4817440984	KU	3	45 ACE	SP	CCA		V	1/8/2041
2020 PO4845641191	KU	3	45 ACE	SP	CCA		V	1/9/2041
2020 PO4873841398	KU	3	45 ACE	SP	CCA		V	1/10/2041
2020 PO4902141604	KU	3	50 ACE	SP	CCA		V	1/11/2041
2020 PO4128330848	KU	3	45 ACE	SP	CCA		V	1/12/2041
2020 PO4134830938	KU	5	35 ACE	SP	CCA		V	1/13/2041
2020 PO5122243047	KU	4	45 ACE	SP	CCA		V	1/14/2041
2020 PO5122243047-A	KU	3	45 ACE	SP	CCA		V	1/15/2041
2020 PO5122043322	KU	4	45 ACE	SP	CCA		V	1/16/2041
2020 PO5121943534	KU	4	45 ACE	SP	CCA		V	1/17/2041
2020 PO4337842189	KU	3	50 ACE	SP	CCA		V	1/18/2041
2020 PO4336441840	KU	3	50 ACE	SP	CCA		V	1/19/2041
2020 PO4339142433	KU	3	45 ACE	SP	CCA		V	1/20/2041
2020 PO4361142001	KU	3	45 ACE	SP	CCA		V	1/21/2041
2020 PO2675049398	ODP	4	45 KOP	SP	S		V	1/22/2041
2020 PO4736988667	LGE	4	40 BRN	SP	A	ED,ID	BD	1/23/2041
2020 PO4200411069	KU	4	40 BRO	SP	CRE	ID,IP	BD	1/24/2041
2020 PO1339923830	ODP	4	40 BRN	SP	CRE	ID	TD	1/25/2041
2020 PO4737388659	LGE	4	35 BRN	SP	A	ED,ID	TD	1/26/2041
2020 PO4193711029	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	1/27/2041
2020 PO4004482886	LGE	3	45 BRO	SP	A	ED,ID	TD	1/28/2041
2020 PO4736788645	LGE	4	35 BRN	SP	A	ED,ID	BD	1/29/2041
2020 PO4737788641	LGE	4	35 BRN	SP	A	ED,ID	TD	1/30/2041
2020 PO1368523374	ODP	5	35 BRN	SP	CRE	ID	TD	1/31/2041
2020 PO1377423295	ODP	4	40 BRN	SP	CRE	ID	TD	2/1/2041
2020 PO1394823252	ODP	4	40 BRN	SP	CCA		V	2/2/2041
2020 PO1417923365	F	4	40 BRN	SP	A		V	2/3/2041
2020 PO1415523474	ODP	5	30 BRN	SP	CRE	ID	TD	2/4/2041
2020 PO1426023492	ODP	2	55 BRN	SP	CCA		V	2/5/2041
2020 PO1372023606	ODP	6	30 BRN	SP	CRE	ID	TD	2/6/2041
2020 PO1390023582	ODP	4	40 BRN	SP	CRE	ID	TD	2/7/2041
2020 PO1417823626	ODP	4	45 BRN	SP	CRE	ID	BD	2/8/2041
2020 PO1404223862	ODP	4	45 BRN	SP	CRE	ID	TD	2/9/2041
2020 PO1393624102	F	4	40 BRN	SP	P		V	2/10/2041
2020 PO1388824181	F	4	40 BRN	SP	CRE	HH,ID,RB	BX	2/11/2041
2020 PO1360324356	ODP	5	35 BRN	SP	CRE	ID	TD	2/12/2041
2020 PO1070039374	ODP	4	40 BRN	SP	CRE		V	2/13/2041
2020 PO1079339510	ODP	4	40 BRN	SP	CRE		V	2/14/2041
2020 PO4739088648	LGE	4	35 BRN	SP	A	ED,ID	TD	2/15/2041
2020 PO4580338719	KU	5	35 BRO	SP	CRE	ID,IP	TD	2/16/2041
2020 PO4148512176	KU	4	40 BRO	SP	CRE	EP,ID,IP	BD	2/17/2041
2020 PO4141712090	KU	4	40 BRO	SP	CRE	ID,IP	BD	2/18/2041

2020 PO4135811951	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	2/19/2041
2020 PO4129011795	KU	4	40 BRO	SP	CRE	ID,IP	BD	2/20/2041
2020 PO4122411641	KU	3	45 BRO	SP	CRE	HH,ID,IP	BD	2/21/2041
2020 PO4106712159	KU	2	40 BRO	SP	CCA	ID	BD	2/22/2041
2020 PO4102312018	KU	4	40 BRO	SP	CRE		V	2/23/2041
2020 PO4595737943	KU	1	60 BRO	SP	CCA		V	2/24/2041
2020 PO4607137841	KU	1	60 BRO	SP	CCA		V	2/25/2041
2020 PO4576538130	KU	3	45 BRO	SP	CCA		V	2/26/2041
2020 PO4583638208	KU	3	45 BRO	SP	CCA		V	2/27/2041
2020 PO4574138117	KU	1	60 BRO	SP	A		V	2/28/2041
2020 PO4575538104	KU	1	60 BRO	SP	A		V	3/1/2041
2020 PO4578238094	KU	1	60 BRO	SP	A		V	3/2/2041
2020 PO4578338094-A	KU	H2	65 BRO	SP	A		V	3/3/2041
2020 PO4738288627	F	4	30 BRN	SP	CCA		V	3/4/2041
2020 PO4739988631	LGE	4	35 BRN	SP	A	ED,ID	TD	3/5/2041
2020 PO4739888623	LGE	4	35 BRN	SP	P	ED,ID	TD	3/6/2041
2020 PO4738988624	LGE	4	35 BRN	SP	A	ED,ID	TD	3/7/2041
2020 PO4738188632	LGE	4	35 BRN	SP	A	ED,ID	TD	3/8/2041
2020 PO4037882917	LGE	4	40 BRO	SP	CRE	ED,ID	V	3/9/2041
2020 PO9363833372	ODP	3	45 BRN	SP	CCA		V	3/10/2041
2020 PO9397133557	ODP	4	45 KOP	SP	A	ED,ID	TD	3/11/2041
2020 9424033736a	ODP	5	30 XXX	SP	CCA		V	3/12/2041
2020 PO9411633617	ODP	4	45 XXX	SP	CCA		V	3/13/2041
2020 PO9424033736	ODP	4	40 XXX	SP	CCA		V	3/14/2041
2020 PO9432133828	ODP	4	45 XXX	SP	CCA		V	3/15/2041
2020 PO9454234013	ODP	4	45 XXX	SP	CCA		V	3/16/2041
2020 PO4739388615	LGE	4	35 BRN	SP	A	ED,ID	TD	3/17/2041
2020 PO4738388580	LGE	3	45 BRN	SP	S		V	3/18/2041
2020 PO4737088576	LGE	4	40 BRN	SP	S		V	3/19/2041
2020 PO4735888573	LGE	3	45 BRN	SP	S		V	3/20/2041
2020 PO4734688568	LGE	3	50 BRN	SP	CCA		V	3/21/2041
2020 PO4042482935	LGE	4	30 BRO	SP	CRE	ED,ID	TD	3/22/2041
2020 PO4044182932	LGE	4	30 BRO	SP	CCA		V	3/23/2041
2020 PO4734288576	LGE	4	30 BRN	SP	CRE	HH,ID	BD	3/24/2041
2020 PO4734288576	LGE	4	30 BRN	SP	S		V	3/25/2041
2020 PO4733588565	LGE	3	45 BRN	SP	S		V	3/26/2041
2020 PO4171111112	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	3/27/2041
2020 PO4185610184	F	4	40 ACE	SP	CRE		V	3/28/2041
2020 PO4171510040	F	4	40 ACE	SP	CRE		V	3/29/2041
2020 PO4477310735	F	5	35 ACE	SP	CRE	ED,ID	V	3/30/2041
2020 PO4472810609	F	4	40 ACE	SP	CRE	ED,ID,IP	V	3/31/2041
2020 PO4464710664	F	4	40 ACE	SP	CRE	ED,ID	V	4/1/2041
2020 PO4453810745	F	4	40 ACE	SP	CRE		V	4/2/2041
2020 PO4437510822	F	4	40 ACE	SP	P		V	4/3/2041
2020 PO3179840843	KU	4	40 ACE	SP	CRE	ED,ID	BD	4/4/2041
2020 PO5131701690	KU	4	40 ACE	SP	A	ID	BD	4/5/2041
2020 PO5096801726	KU	4	40 ACE	SP	CCA	ED	TD	4/6/2041

2020 PO5092101432	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	4/7/2041
2020 PO3400439840	F	4	40 ACE	SP	CRE		V	4/8/2041
2020 PO3393439676	F	4	40 ACE	SP	CRE		V	4/9/2041
2020 PO3367239676	F	4	40 ACE	SP	CRE		V	4/10/2041
2020 PO3348339681	F	4	40 ACE	SP	CRE		V	4/11/2041
2020 PO3329639689	F	4	40 ACE	SP	CRE		V	4/12/2041
2020 PO3308039706	F	4	40 ACE	SP	CRE	ED,ID	V	4/13/2041
2020 PO4985000762	KU	3	40 ACE	SP	CRE	ED,ID,IP	TD	4/14/2041
2020 PO4979500508	KU	3	40 ACE	SP	CRE	ED,ID,IP	TD	4/15/2041
2020 PO4998001148	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	4/16/2041
2020 PO3292939706	KU	5	35 ACE	SP	CRE	ED,ID	TD	4/17/2041
2020 PO4939401176	KU	3	40 ACE	SP	CRE	ED,ID,IP	TD	4/18/2041
2020 PO3277339715	KU	5	35 ACE	SP	CRE	ED,ID	TD	4/19/2041
2020 PO3160339770	KU	4	40 ACE	SP	CRE	ED,ID	TD	4/20/2041
2020 PO1562122172	ODP	2	50 XXX	SP	CCA	ED	T	4/21/2041
2020 PO1547022354	ODP	4	40 XXX	SP	CRE	ID	TD	4/22/2041
2020 PO1568522334	ODP	5	35 XXX	SP	CRE	ID	TD	4/23/2041
2020 PO1572222223A	ODP	5	35 XXX	SP	CRE	ID	TD	4/24/2041
2020 PO1572222223	ODP	5	35 XXX	SP	CRE	ID	TD	4/25/2041
2020 PO1585622186	ODP	3	50 XXX	SP	CCA	ED	T	4/26/2041
2020 PO1598822459	ODP	4	45 XXX	SP	CCA		V	4/27/2041
2020 PO1601122227	ODP	4	45 XXX	SP	CRE	ID	TD	4/28/2041
2020 PO1617522185	ODP	4	45 XXX	SP	CCA		V	4/29/2041
2020 PO1642822305	ODP	3	50 XXX	SP	CCA	ED	T	4/30/2041
2020 PO1626122438	ODP	4	40 XXX	SP	CRE	ID	TD	5/1/2041
2020 PO1620222261	ODP	4	45 XXX	SP	CRE	ID	TD	5/2/2041
2020 PO3138739778	KU	4	40 ACE	SP	CRE	ED,ID	TD	5/3/2041
2020 PO3118339789	KU	4	40 ACE	SP	CRE	ED,ID	TD	5/4/2041
2020 PO3090339808	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	5/5/2041
2020 PO3074639816	KU	4	40 ACE	SP	CRE	ED,ID	TD	5/6/2041
2020 PO3060239827	KU	4	40 ACE	SP	CRE	ED,ID	TD	5/7/2041
2020 PO3046539806	KU	6	30 ACE	SP	CCA	ED,ID	TD	5/8/2041
2020 PO3058139614	KU	3	45 ACE	SP	CCA		V	5/9/2041
2020 PO3056239402	KU	4	40 ACE	SP	CCA	ED,ID	TD	5/10/2041
2020 PO4766401642	F	4	35 BRO	SP	CCA		V	5/11/2041
2020 PO4752501606	F	4	40 BRO	SP	CRE		V	5/12/2041
2020 PO4738901553	F	4	35 BRO	SP	CCA		V	5/13/2041
2020 PO4719801487	KU	3	45 BRO	SP	CCA		V	5/14/2041
2020 PO4698501448	F	4	40 BRO	SP	CRE		V	5/15/2041
2020 PO4674001417	F	4	40 BRO	SP	CCA		V	5/16/2041
2020 PO4656901394	F	4	35 BRO	SP	CCA		V	5/17/2041
2020 PO4634001353	F	4	40 BRO	SP	CRE		V	5/18/2041
2020 PO4588701285	F	3	40 BRO	SP	CCA		V	5/19/2041
2020 PO4600301302	F	4	40 BRO	SP	CCA		V	5/20/2041
2020 PO6006038084	KU	4	40 BRN	SP	CRE	ID	BD	5/21/2041
2020 PO5507945564	KU	3	50 ACW	SP	CRE	ED,ID	X	RP1 5/22/2041
2020 PO4359811478	KU	2	45 ACE	SP	CCA		V	5/23/2041

2020 PO4367711543	F	2	50 ACE	SP	CCA		V	5/24/2041
2020 PO4379611628	F	4	40 ACE	SP	CCA		V	5/25/2041
2020 PO4064611442	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	5/26/2041
2020 PO4720488608	LGE	4	40 BRN	SP	S		V	5/27/2041
2020 PO4719388627	LGE	4	40 BRN	SP	P	ED,ID	TD	5/28/2041
2020 PO4121612266	KU	4	40 BRO	SP	CCA		V	5/29/2041
2020 PO4105512335	KU	4	40 BRO	SP	CRE	ID,IP	BD	5/30/2041
2020 PO4049611506	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	5/31/2041
2020 PO4084012443	KU	4	40 BRO	SP	CRE	ID,IP	BD	6/1/2041
2020 PO4091312412	KU	4	40 BRO	SP	CRE	ID,IP	BD	6/2/2041
2020 PO4394111799	KU	3	45 ACE	SP	CCA		V	6/3/2041
2020 PO4297699123	LGE	4	35 BRN	SP	S		V	6/4/2041
2020 PO4047682901	LGE	4	30 BRO	SP	P	ED,ID	TD	6/5/2041
2020 PO4049282900	LGE	4	30 BRO	SP	CCA	ED,ID	BD	6/6/2041
2020 PO4719488650	LGE	4	40 BRN	SP	A	ED,ID	TD	6/7/2041
2020 PO4718488642	LGE	4	40 BRN	SP	A	ED,ID	BD	6/8/2041
2020 PO2021622164	ODP	4	40 BRN	SP	CRE	ID	TD	6/9/2041
2020 PO2020922229	ODP	4	40 BRN	SP	CRE	ID	TD	6/10/2041
2020 PO2024022313	ODP	4	40 BRN	SP	CRE	ID	TD	6/11/2041
2020 PO2019522401	ODP	4	40 BRN	SP	CRE	ID	TD	6/12/2041
2020 PO2015722577	ODP	4	40 BRN	SP	CRE	ID	TD	6/13/2041
2020 PO1996122561	ODP	4	40 BRN	SP	CRE	ID	TD	6/14/2041
2020 PO1968922393	ODP	5	35 BRN	SP	CCA		V	6/15/2041
2020 PO4396111762	F	3	45 ACE	SP	CCA		V	6/16/2041
2020 PO1538434712	ODP	4	40 UNK	SP	CRE	ID	TD	6/17/2041
2020 PO1590733757A	ODP	5	35 BRN	SP	CRE	ID	TD	6/18/2041
2020 PO1590733757	ODP	5	35 BRN	SP	CRE	ED,ID,SRC	TD	6/19/2041
2020 PO1593333696	ODP	5	35 UNK	SP	CRE	ID	BD	6/20/2041
2020 PO1597033634	ODP	5	35 UNK	SP	CRE	ED,EP,ID,SRC	TD	6/21/2041
2020 PO1604933449	ODP	5	35 UNK	SP	CRE	ED,ID,SRS	TD	6/22/2041
2020 PO1609833257	ODP	5	35 UNK	SP	CRE	ED,ID,SRS	TD	6/23/2041
2020 PO1612633022	ODP	6	30 UNK	SP	CRE	ED,ID,SRS	TD	6/24/2041
2020 PO1615032805	ODP	5	35 SWP	SP	CRE	ED,ID,SRS	TD	6/25/2041
2020 PO1616632563	ODP	4	40 CAH	SP	CRE	ID	TD	6/26/2041
2020 PO1624232056	ODP	4	40 BRN	SP	CCA		V	6/27/2041
2020 PO4393012008	KU	3	45 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	6/28/2041
2020 PO4408111865	KU	3	45 ACE	SP	CCA		V	6/29/2041
2020 PO4405811849	F	2	50 ACE	SP	CCA		V	6/30/2041
2020 PO4419111953	F	3	45 ACE	SP	CCA		V	7/1/2041
2020 PO4719988665	LGE	4	35 BRN	SP	CRE		V	7/2/2041
2020 PO5674252381	KU	4	40 ACE	SP	CRE	ED,ID	BD	7/3/2041
2020 PO5684652481	KU	4	40 ACE	SP	CRE	ED,ID	BD	7/4/2041
2020 PO4664388808	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	7/5/2041
2020 PO4664988812	LGE	4	30 BRO	SP	CRE	ID,IP	BD	7/6/2041
2020 PO6312445152	KU	4	40 OTH	SP	CRE	ED,SRS	TD	7/7/2041
2020 PO6280745301	KU	4	40 OTH	SP	CRE	ED,SRS	TD	7/8/2041
2020 PO6326945491	KU	4	40 OTH	SP	CRE		B	7/9/2041

2020 PO6345745001	KU	4	45 OTH	SP	CRE	ED,SRS	TD	7/10/2041
2020 PO4814888124	F	4	35 BRO	SP	CCA		V	7/11/2041
2020 PO4824688264	LGE	4	30 BRO	SP	CRE	ED	TD	7/12/2041
2020 PO4824188278	LGE	4	30 BRO	SP	CRE	ED	TD	7/13/2041
2020 PO4823088306	LGE	4	35 BRO	SP	CRE	ED	TD	7/14/2041
2020 PO4668488834	LGE	4	40 BRO	SP	CRE	ID,IP	BD	7/15/2041
2020 PO9494073452	KU	4	40 XXX	SP	CCA		V	7/16/2041
2020 PO9420173852	KU	6	30 XXX	SP	CRE		V	7/17/2041
2020 PO9392373458	KU	6	30 XXX	SP	CRE	ID	TD	7/18/2041
2020 PO9383673577	KU	6	30 XXX	SP	CRE	ID	TD	7/19/2041
2020 PO9386073623	KU	6	30 XXX	SP	CRE	ED,ID	TD	7/20/2041
2020 PO9381073722	KU	4	40 XXX	SP	CRE	ED,ID	TD	7/21/2041
2020 PO9429074207	F	5	35 XXX	SP	A		V	7/22/2041
2020 PO9449374152	KU	4	40 XXX	SP	CRE	ID	TD	7/23/2041
2020 PO9438374091	KU	4	40 XXX	SP	CRE	ID	TD	7/24/2041
2020 PO9427573784	KU	4	40 XXX	SP	CCA		V	7/25/2041
2020 PO9414273906	KU	4	40 XXX	SP	CRE	ID	TD	7/26/2041
2020 PO9407173910	KU	4	40 XXX	SP	CRE	ED,ID	TD	7/27/2041
2020 PO4822588320	LGE	4	35 BRO	SP	CRE	ED	TD	7/28/2041
2020 PO4822188330	LGE	4	35 BRO	SP	CRE	ED	TD	7/29/2041
2020 PO4668688826	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	7/30/2041
2020 PO4791688201	LGE	4	40 BRN	SP	A	ED,ID	BD	7/31/2041
2020 PO4789988194	LGE	4	40 BRN	SP	A	ED,ID,SRS	TX	RR 8/1/2041
2020 PO4670788767	LGE	4	40 BRO	SP	CCA		V	8/2/2041
2020 PO4671988776	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	8/3/2041
2020 PO6215245612	KU	4	45 OTH	SP	CRE	ED,SRS	TD	8/4/2041
2020 PO6247445464	KU	4	45 OTH	SP	CRE	ED,SRS	TD	8/5/2041
2020 PO6201045855	KU	4	45 OTH	SP	CRE	ED,SRS	TD	8/6/2041
2020 PO4821888353	LGE	4	30 BRO	SP	CRE	ED	BD	8/7/2041
2020 PO6085446627	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	8/8/2041
2020 PO6116745700	KU	4	40 OTH	SP	CRE	ID	BD	8/9/2041
2020 PO6100846810	KU	4	40 OTH	SP	CRE	ED,SRS	TD	8/10/2041
2020 PO4124791226	KU	4	40 BRN	SP	CCA		V	8/11/2041
2020 PO4126391171	KU	4	40 BRN	SP	CRE	ID	BD	8/12/2041
2020 PO4783688042	LGE	4	40 BRN	SP	A	ED,ID	BD	8/13/2041
2020 PO4782988063	LGE	4	40 BRN	SP	CCA		V	8/14/2041
2020 PO4669488758	LGE	3	45 BRO	SP	CCA		V	8/15/2041
2020 PO4782188083	LGE	4	40 BRN	SP	A	ED,ID	BD	8/16/2041
2020 PO4668388751	LGE	4	40 BRO	SP	A	ED	TD	8/17/2041
2020 PO7993357871	KU	4	45 XXX	SP	CRE	ED,ID	TD	8/18/2041
2020 PO4667488764	LGE	4	40 BRO	SP	A	ED	TD	8/19/2041
2020 PO4664888798	LGE	4	40 BRO	SP	CCA		V	8/20/2041
2020 PO4780988116	LGE	4	40 BRN	SP	A	ED,ID	BD	8/21/2041
2020 PO4780288137	LGE	4	40 BRN	SP	A	ED,ID	BD	8/22/2041
2020 PO4779688154	LGE	4	40 BRN	SP	A	ED,ID	BD	8/23/2041
2020 PO4779888158	LGE	UNK	45 BRN	SP	A		V	8/24/2041
2020 PO4668088779	LGE	4	40 BRO	SP	A	ID,IP	BD	8/25/2041

2020 PO4666688775	LGE	4	40 BRO	SP	CCA		V	8/26/2041	
2020 PO4819488431	LGE	4	40 BRO	SP	CRE	ED	BD	8/27/2041	
2020 PO4818988446	LGE	4	40 BRO	SP	CRE	ED	TD	8/28/2041	
2020 PO4818488460	LGE	3	50 BRO	SP	CRE	ED	BD	8/29/2041	
2020 PO4817488481	LGE	3	50 BRO	SP	P		T	8/30/2041	
2020 PO4816588505	LGE	3	50 BRO	SP	CCA		V	8/31/2041	
2020 PO4665488785	LGE	4	40 BRO	SP	P	ED	T	9/1/2041	
2020 PO4664788780	LGE	4	40 BRO	SP	A	ID,IP	BD	9/2/2041	
2020 PO6113046950	KU	4	40 OTH	SP	P	ED,SRS	TD	9/3/2041	
2020 PO4664188779	F	4	40 BRO	SP	CRE		V	9/4/2041	
2020 PO4781188162	LGE	4	40 BRN	SP	A	ED,ID	BD	9/5/2041	
2020 PO4684788698	LGE	4	40 BRO	SP	CCA		V	9/6/2041	
2020 PO4856287110	LGE	4	40 XXX	SP	A	ED,ID	TD	9/7/2041	
2020 PO4855087116	LGE	5	35 XXX	SP	CRE	ED,ID	TD	9/8/2041	
2020 PO4854487150	LGE	5	40 XXX	SP	CRE	ED,ID	TD	9/9/2041	
2020 PO4829887058	LGE	4	40 KOP	SP	CRE	ED,ID	BD	9/10/2041	
2020 PO4825687017	LGE	3	45 KOP	SP	S		V	9/11/2041	
2020 PO4821787015	LGE	3	45 KOP	SP	CCA	ED,ID	BD	9/12/2041	
2020 PO4819887014	LGE	4	40 KOP	SP	S		V	9/13/2041	
2020 PO4818087013	LGE	3	45 KOP	SP	S		V	9/14/2041	
2020 PO4844887201	LGE	4	40 KOP	SP	CCA		V	9/15/2041	
2020 PO4842587192	LGE	5	45 KOP	SP	CCA		V	9/16/2041	
2020 PO4840487185	LGE	4	40 KOP	SP	CCA		V	9/17/2041	
2020 PO4851986924	LGE	4	40 KOP	SP	S		V	9/18/2041	
2020 PO5630682286	LGE	3	45 KOP	SP	S		V	9/19/2041	
2020 PO4846186930	F	H1	110 KOP	ST	CCA		V	9/20/2041	
2020 PO4846686942	F	4	40 KOP	SP	A		V	9/21/2041	
2020 PO4849786929	LGE	4	45 KOP	SP	P	ED,ID	BD	9/22/2041	
2020 PO4853387097	LGE	3	45 XXX	SP	CCA		V	9/23/2041	
2020 PO4850487057	LGE	1	70 XXX	SP	CCA		V	9/24/2041	
2020 PO4851287083	LGE	1	60 XXX	SP	CCA		V	9/25/2041	
2020 PO4852087090	LGE	3	45 XXX	SP	CRE	ED,ID	TX	RR	9/26/2041
2020 PO4852487100	LGE	3	45 BRN	SP	CCA		V	9/27/2041	
2020 PO4852787107	LGE	3	45 XXX	SP	CRE	ED,ID,RB	BX	RP1	9/28/2041
2020 PO4853487124	LGE	3	45 XXX	SP	A	ED,ID	TD	9/29/2041	
2020 PO4854187142	LGE	2	45 XXX	SP	CCA		V	9/30/2041	
2020 PO4853787143	LGE	4	40 XXX	SP	CRE	ED,ID	TD	10/1/2041	
2020 PO4851287147	LGE	4	40 XXX	SP	A	ED,ID	TD	10/2/2041	
2020 PO4849887134	LGE	4	45 XXX	SP	CCA		V	10/3/2041	
2020 PO4855387171	LGE	3	50 XXX	SP	A	ID	BD	10/4/2041	
2020 PO4853987177	LGE	4	40 XXX	SP	CCA		V	10/5/2041	
2020 4876787203a	LGE	3	45 XXX	SP	CCA		V	10/6/2041	
2020 PO4857287218	LGE	3	45 XXX	SP	CCA	ED	TD	10/7/2041	
2020 PO4876787203	LGE	3	45 XXX	SP	CCA	ED	T	10/8/2041	
2020 PO4856187190	LGE	3	45 XXX	SP	CCA		V	10/9/2041	
2020 PO4857887232	LGE	5	40 XXX	SP	CRE	ID	BD	10/10/2041	
2020 PO4858587249	LGE	4	40 XXX	SP	CRE	ED,ID	TD	10/11/2041	

2020 PO4833087085	LGE	4	40 KOP	SP	CCA	ED,ID	TD	10/12/2041
2020 PO4831487072	LGE	4	40 KOP	SP	P	ED,ID	TD	10/13/2041
2020 PO4825387017	LGE	4	40 KOP	SP	P	ED,ID	BD	10/14/2041
2020 PO4825187017	LGE	4	40 KOP	SP	P	ED,ID,IP	BD	10/15/2041
2020 PO4823487016	LGE	4	40 KOP	SP	CRE	ED,ID	BD	10/16/2041
2020 PO4817187012	LGE	4	40 KOP	SP	P	ED,ID	TD	10/17/2041
2020 PO4815987012	LGE	3	45 KOP	SP	S		V	10/18/2041
2020 PO7836556455	KU	4	40 XXX	SP	CCA		V	10/19/2041
2020 PO7862956358	KU	4	40 XXX	SP	CRE		V	10/20/2041
2020 PO7878556497	KU	5	35 XXX	SP	CRE		V	10/21/2041
2020 PO7899556635	KU	5	35 XXX	SP	CRE		V	10/22/2041
2020 PO7922156787	KU	5	35 XXX	SP	CRE		V	10/23/2041
2020 PO9668475087	KU	4	40 XXX	SP	CRE	ED,ID	TD	10/24/2041
2020 PO9685675159	KU	4	40 XXX	SP	CRE	ED,ID	TD	10/25/2041
2020 PO9701675227	KU	4	40 XXX	SP	CRE	ID	BD	10/26/2041
2020 7948461259b	KU	5	30 XXX	SP	CCA	ED	T	10/27/2041
2020 PO9230272345	KU	6	35 XXX	SP	CRE	ED,ID	TD	10/28/2041
2020 PO9237872399	KU	5	35 XXX	SP	CRE	ID	BD	10/29/2041
2020 PO9273473056	KU	6	30 XXX	SP	CRE		V	10/30/2041
2020 PO9305273193	KU	5	35 XXX	SP	CRE	ID	BD	10/31/2041
2020 PO9315173260	KU	6	35 XXX	SP	CRE	ID	BD	11/1/2041
2020 PO9285673106	KU	5	30 XXX	SP	CRE	ED,ID	TD	11/2/2041
2020 PO4815787015	LGE	4	35 KOP	SP	CCA	ED,ID,RB,SRC	TX	RR 11/3/2041
2020 PO4813387010	LGE	4	40 KOP	SP	CCA	ED,ID	BD	11/4/2041
2020 PO4811287008	LGE	4	40 KOP	SP	S		V	11/5/2041
2020 PO4808487007	LGE	3	45 KOP	SP	S		V	11/6/2041
2020 PO4805687008	LGE	2	60 KOP	SP	CCA		V	11/7/2041
2020 PO4805587005	LGE	1	60 KOP	SP	S		V	11/8/2041
2020 PO4878487273	F	4	45 XXX	SP	CRE		V	11/9/2041
2020 PO4883187474	F	4	40 XXX	SP	CRE	ID	BX	RP2 11/10/2041
2020 4879387469a	LGE	4	40 XXX	SP	A		V	11/11/2041
2020 PO4881487472	LGE	4	40 XXX	SP	CCA		V	11/12/2041
2020 PO4880487469	F	4	40 XXX	SP	A		V	11/13/2041
2020 PO4879387469	F	4	40 XXX	SP	A		V	11/14/2041
2020 PO4878787466	F	4	40 XXX	SP	A		V	11/15/2041
2020 PO4878087468	F	4	40 XXX	SP	A		V	11/16/2041
2020 4877287467a	LGE	4	35 XXX	SP	A		V	11/17/2041
2020 4878087468	LGE	4	40 XXX	SP	A		V	11/18/2041
2020 PO4877287467	F	4	35 XXX	SP	A		V	11/19/2041
2020 PO4876387463	LGE	4	35 XXX	SP	CCA		V	11/20/2041
2020 PO4874387461	LGE	4	45 XXX	SP	A		V	11/21/2041
2020 PO4875387464	F	4	40 XXX	SP	CCA		V	11/22/2041
2020 PO4874387424	F	3	45 XXX	SP	A		V	11/23/2041
2020 PO4874387409	F	3	45 XXX	SP	A		V	11/24/2041
2020 PO4874787397	LGE	1	50 XXX	SP	CCA		V	11/25/2041
2020 PO4829286279	LGE	4	30 XXX	SP	CCA		V	11/26/2041
2020 PO4803288372	LGE	4	35 BRN	SP	CCA		V	11/27/2041

2020 PO4804788360	LGE	4	35 BRN	SP	A	ED,ID	BD	11/28/2041
2020 PO4803988367	LGE	4	35 BRN	SP	CRE	ED,ID	BD	11/29/2041
2020 PO4804388356	LGE	4	35 BRN	SP	CCA	ED,ID	BD	11/30/2041
2020 PO4803488364	LGE	4	30 BRN	SP	CRE	ED,ID	BD	12/1/2041
2020 PO4801588337	LGE	4	35 BRN	SP	A	ED,ID	BD	12/2/2041
2020 PO4802488329	LGE	4	35 BRN	SP	A	ED,ID	BD	12/3/2041
2020 PO4803188321	LGE	4	35 BRN	SP	A	ED,ID	TD	12/4/2041
2020 PO4740288039	F	4	40 BRO	SP	CRE		V	12/5/2041
2020 PO4740088050	F	3	45 BRO	SP	CCA		V	12/6/2041
2020 PO4739588076	F	4	40 BRO	SP	CRE		V	12/7/2041
2020 PO4739188076	F	3	45 BRO	SP	CCA		V	12/8/2041
2020 PO4736588070	F	3	45 BRO	SP	CRE		V	12/9/2041
2020 PO4737488072	F	4	40 BRO	SP	CRE		V	12/10/2041
2020 PO4739788065	F	3	45 BRO	SP	CCA		V	12/11/2041
2020 PO4739388088	F	4	40 BRO	SP	CCA		V	12/12/2041
2020 PO4735488082	F	4	40 BRO	SP	CRE		V	12/13/2041
2020 PO4805688345	LGE	3H	45 BRN	SP	CRE	ED,ID	BD	12/14/2041
2020 PO4876286448	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	12/15/2041
2020 PO4735388094	F	3	45 BRO	SP	CCA		V	12/16/2041
2020 PO4735588068	F	3	45 BRO	SP	CRE		V	12/17/2041
2020 PO4735388031	F	3	45 BRO	SP	CCA		V	12/18/2041
2020 PO4750387946	F	4	40 BRO	SP	CRE		V	12/19/2041
2020 PO4749987965	F	4	40 BRO	SP	CRE		V	12/20/2041
2020 PO4749587985	F	4	40 BRO	SP	CRE		V	12/21/2041
2020 PO4749188005	F	4	40 BRO	SP	CRE		V	12/22/2041
2020 PO4806688331	LGE	4	35 BRN	SP	CRE	ED,ID	BD	12/23/2041
2020 PO5156696055	LGE	4	30 BRN	SP	A	ED,ID	BD	12/24/2041
2020 PO4878486231	LGE	4	30 OTH	SP	CCA	ED,SRS	TD	12/25/2041
2020 PO4879086231	LGE	4	30 OTH	SP	CCA	ED,SRS	TD	12/26/2041
2020 PO4806888313	LGE	4	40 BRN	SP	CRE	ED,ID	BD	12/27/2041
2020 PO4806088302	LGE	4	40 BRN	SP	A	ED,ID	BD	12/28/2041
2020 PO4676088871	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	12/29/2041
2020 PO4673488860	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	12/30/2041
2020 PO4875186412A	LGE	3	45 OTH	SP	P	ED,SRS	TD	12/31/2041
2020 PO4876386431	LGE	4	40 OTH	SP	CCA		V	1/1/2042
2020 PO4874486422	LGE	4	30 OTH	UN	P		V	1/2/2042
2020 PO4873786465	LGE	3	45 OTH	SP	P	ED,ID,SRS	TD	1/3/2042
2020 PO4874286447	LGE	3	45 OTH	SP	P	ID	TD	1/4/2042
2020 PO4872687407	LGE	3	45 KOP	SP	A	ED,ID	TD	1/5/2042
2020 PO4872787425	LGE	3	45 KOP	SP	A	ED,ID	TD	1/6/2042
2020 PO4803388311	LGE	4	35 BRN	SP	A	ED,ID	BD	1/7/2042
2020 PO4805288291	LGE	4	45 BRN	SP	CCA		V	1/8/2042
2020 PO4804588299	LGE	4	35 BRN	SP	A	ED,ID	TD	1/9/2042
2020 PO4747588086	F	3	45 BRO	SP	CRE		V	1/10/2042
2020 PO4748188087	F	4	30 BRO	SP	CRE		V	1/11/2042
2020 PO4746788124	F	4	40 BRO	SP	CRE		V	1/12/2042
2020 PO4746388124	LGE	4	30 BRO	SP	CRE	ED,EP	TD	1/13/2042

2020 PO4743488117	LGE	4	30 BRO	SP	CRE	ED, SRC	TD	1/14/2042
2020 PO4747188105	F	3	45 BRO	SP	CCA		V	1/15/2042
2020 PO4743288097	F	4	40 BRO	SP	CCA		V	1/16/2042
2020 PO4743688076	F	4	40 BRO	SP	CRE		V	1/17/2042
2020 PO4744088076	F	4	40 BRO	SP	CCA		V	1/18/2042
2020 PO4746788084	LGE	4	35 BRO	SP	CCA		V	1/19/2042
2020 4876586386A	LGE	5	35 OTH	SP	CRE	ED, ID, SRS	TD	1/20/2042
2020 PO4803288265	LGE	4	30 BRN	SP	CRE	ED, ID	BD	1/21/2042
2020 PO4804288275	LGE	4	40 BRN	SP	A	ED, ID	TD	1/22/2042
2020 PO4875186412	LGE	3	45 OTH	SP	P	ED, ID, SRS	TD	1/23/2042
2020 PO4832186300	LGE	4	40 XXX	SP	CCA		V	1/24/2042
2020 PO4829386311	LGE	4	50 XXX	SP	A		V	1/25/2042
2020 PO4824986239	F	1	50 XXX	SP	CCA		V	1/26/2042
2020 PO4826086253	F	4	45 XXX	SP	CRE		V	1/27/2042
2020 PO4826786262	LGE	4	45 XXX	SP	A		V	1/28/2042
2020 PO4827486271	F	3	50 XXX	SP	CCA		V	1/29/2042
2020 PO4828386283	F	1	50 XXX	SP	CCA		V	1/30/2042
2020 PO4828486295	F	1	45 XXX	SP	CCA		V	1/31/2042
2020 PO4828686305	LGE	3	45 XXX	SP	CCA		V	2/1/2042
2020 PO4828686314	F	3	45 XXX	SP	CCA		V	2/2/2042
2020 PO4828886330	F	4	40 XXX	SP	A		V	2/3/2042
2020 PO4673188866	LGE	4	40 BRO	SP	CRE	ED, ID, IP	TD	2/4/2042
2020 PO4672488856	LGE	4	40 BRO	SP	CRE	ED, ID, IP	TD	2/5/2042
2020 PO4797987840	LGE	UNK	45 BRO	SP	CCA		V	2/6/2042
2020 PO4796487841	LGE	UNK	25 BRO	SP	CCA		V	2/7/2042
2020 PO4876186376	LGE	3	45 OTH	SP	P	ED, ID, SRS	TD	2/8/2042
2020 PO4876586373	LGE	3	45 OTH	SP	CCA		V	2/9/2042
2020 PO4816287820	LGE	UNK	45 BRO	SP	CRE	ED	BD	2/10/2042
2020 PO4879586370	LGE	4	35 BRN	SP	CCA		V	2/11/2042
2020 PO5905176207	LGE	3	45 OTH	SP	CCA		V	2/12/2042
2020 PO4876186356	LGE	4	35 OTH	SP	P	ED, ID, SRS	TD	2/13/2042
2020 PO4877086343	LGE	4	40 OTH	SP	P	ED, ID	TD	2/14/2042
2020 PO4878786365	LGE	4	40 OTH	SP	CRE	ED, ID	TD	2/15/2042
2020 PV4879486319	LGE	4	40 OTH	SP	P	ED, SRS	TD	2/16/2042
2020 PO4878286345	LGE	4	40 OTH	SP	CCA		V	2/17/2042
2020 PO4875086375	LGE	4	30 OTH	SP	CCA		V	2/18/2042
2020 PO4876686359	LGE	3	45 OTH	SP	P	ED, ID, SRS	TD	2/19/2042
2020 PO4799288315	LGE	4	35 BRN	SP	CRE	ED, ID	TD	2/20/2042
2020 PO4874787410	LGE	4	30 XXX	SP	A	ED, ID	TD	2/21/2042
2020 PO4820187815	LGE	3	45 BRO	SP	CCA		V	2/22/2042
2020 PO4827987806	LGE	UNK	95 BRO	AL	CCA		V	2/23/2042
2020 PO4826287799	F	4	40 BRO	SP	CRE		V	2/24/2042
2020 PO4825487799	LGE	4	35 BRO	SP	CCA		V	2/25/2042
2020 PO4827887797	F	UNK	45 BRO	SP	S		V	2/26/2042
2020 PO4822987803	F	4	40 BRO	SP	CCA		V	2/27/2042
2020 PO4824487801	F	3	45 BRO	SP	CCA		V	2/28/2042
2020 PO4798988328	LGE	4	35 BRN	SP	A	ED, ID	BD	3/1/2042

2020 PO4820387806	F	4	40 BRO	SP	CCA		V	3/2/2042
2020 PO4820187806	F	4	40 BRO	SP	CCA		V	3/3/2042
2020 PO4819087807	F	4	40 BRO	SP	CCA		V	3/4/2042
2020 PO4875587387	LGE	4	35 XXX	SP	A	ED,ID	TD	3/5/2042
2020 PO4849287099	LGE	4	40 XXX	SP	CCA		V	3/6/2042
2020 PO4848187110	LGE	4	40 XXX	SP	CCA		V	3/7/2042
2020 PO4798488324	LGE	4	35 BRN	SP	A	ED,ID	BD	3/8/2042
2020 PO4798088329	LGE	4	40 BRN	SP	A	ED,ID	BD	3/9/2042
2020 PO4797488324	LGE	4	35 BRN	SP	CRE	ED,ID	BD	3/10/2042
2020 PO4817587809	F	4	40 BRO	SP	CRE		V	3/11/2042
2020 PO4816187811	F	4	40 BRO	SP	CRE		V	3/12/2042
2020 PO4796687832	F	4	30 BRO	SP	CRE		V	3/13/2042
2020 PO4669388926	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	3/14/2042
2020 PO7211493802	KU	2	70 BRN	SP	CRE		V	3/15/2042
2020 PO7464794929	KU	5	35 BRO	SP	CRE	ID	BD	3/16/2042
2020 PO7461195016	KU	5	35 BRO	SP	CRE	ID	BD	3/17/2042
2020 PO7480195148	KU	4	40 BRO	SP	CRE		B	3/18/2042
2020 PO7496495189	KU	4	45 BRO	SP	CRE	ID	BD	3/19/2042
2020 PO3804135323	KU	4	40 BRN	SP	CRE	ED,HH,ID,IP	X	RP2 3/20/2042
2020 PO7194994229	KU	1	80 BRN	SP	CRE	ED,ID	TD	3/21/2042
2020 PO7298091643	F	4	40 BRO	SP	A		V	3/22/2042
2020 PO7293891577	F	4	40 BRO	SP	A		V	3/23/2042
2020 PO7308591759	F	3	45 BRO	SP	CRE		V	3/24/2042
2020 PO7318191665	F	3	40 BRO	SP	CRE		V	3/25/2042
2020 PO7327191578	F	3	40 BRO	SP	A		V	3/26/2042
2020 PO7331991530	F	3	40 BRO	SP	CRE		V	3/27/2042
2020 PO7289892439-A	KU	6	30 BRN	SP	CCA		V	3/28/2042
2020 PO7292392610	KU	5	35 BRN	SP	CRE	ED,ID	TD	3/29/2042
2020 PO7293092493	KU	4	40 BRN	SP	CRE	ED,ID	BD	3/30/2042
2020 PO7289892439	KU	6	30 BRN	SP	CRE	ED,ID	TD	3/31/2042
2020 PO7294292321	KU	4	45 BRN	SP	CCA		V	4/1/2042
2020 PO7310291114	F	3	45 BRO	SP	CRE		V	4/2/2042
2020 PO7281290976	F	4	40 BRO	SP	CRE		V	4/3/2042
2020 PO7153294507	KU	2	70 BRN	SP	CRE		V	4/4/2042
2020 PO7267590930	F	4	45 BRO	SP	CRE		V	4/5/2042
2020 PO3760235142	KU	4	40 BRN	SP	CRE	ED,HH,ID,MD	X	PX 4/6/2042
2020 PO3966182450	F	3	45 BRN	SP	S		V	4/7/2042
2020 PO3966382460	F	5	30 BRN	SP	CRE		V	4/8/2042
2020 PO3966782460	F	4	40 BRN	SP	CRE		V	4/9/2042
2020 PO3967082473	F	4	40 BRN	SP	CRE		V	4/10/2042
2020 PO3966682474	F	5	30 BRN	SP	CRE		V	4/11/2042
2020 PO3966682489	F	5	30 BRN	SP	CRE		V	4/12/2042
2020 PO3967082488	F	4	40 BRN	SP	CRE		V	4/13/2042
2020 P022703-42097A	ODP	6	30 KOP	SP	A	ID	BD	4/14/2042
2020 PO2270342097	ODP	3	50 KOP	SP	CRE	ED,ID	TD	4/15/2042
2020 PO2322142191	ODP	4	45 KOP	SP	CRE	ED,ID	TD	4/16/2042
2020 PO2307642171	ODP	4	40 KOP	SP	CRE	ED,ID	TD	4/17/2042

2020 PO2320142272	ODP	6	30 KOP	SP	CRE	ED,ID	TD	4/18/2042
2020 PO2344742259	ODP	3	50 KOP	SP	CRE	ED,ID	TD	4/19/2042
2020 PO2360242295	ODP	5	35 KOP	SP	CRE	ED,ID	TD	4/20/2042
2020 PO2376542365	ODP	4	45 KOP	SP	CRE	ED,ID	TD	4/21/2042
2020 PO2246041515	ODP	4	40 KOP	SP	CRE	ED,ID	TD	4/22/2042
2020 PO7515695240	KU	4	45 BRO	SP	CRE	ED,ID	TD	4/23/2042
2020 PO3590230569	KU	5	35 BRN	SP	CRE	HH,ID,IP	BX	RP2 4/24/2042
2020 PO0886873591	KU	6	30 BRN	SP	P	ED	T	4/25/2042
2020 PO0715652548	KU	4	40 BRN	SP	CRE	ID,IP	TD	4/26/2042
2020 PO0770952494	KU	5	35 BRN	SP	CRE	ID,IP	TD	4/27/2042
2020 PO0726652189	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	4/28/2042
2020 PO0736552230	KU	2	70 BRN	SP	CRE		V	4/29/2042
2020 PO0770351958	KU	4	40 BRN	SP	P	ED	TD	4/30/2042
2020 PO0748052105	KU	4	40 BRN	SP	CRE	ED,ID	TD	5/1/2042
2020 PO0797351779	KU	4	40 BRN	SP	P	ED	TD	5/2/2042
2020 PO9996050197	KU	4	40 BRN	SP	CRE	ID	BD	5/3/2042
2020 PO9961249875	KU	4	40 BRN	SP	CRE	ID	BD	5/4/2042
2020 PO0744252996	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD	5/5/2042
2020 PO0831951553	KU	4	40 BRN	SP	P	ED	TD	5/6/2042
2020 PO0868851314	KU	4	40 BRN	SP	P	ED	TD	5/7/2042
2020 PO0891751161	KU	4	40 BRN	SP	P	ED	TD	5/8/2042
2020 PO0952151110	KU	4	40 BRN	SP	CRE		V	5/9/2042
2020 PO0928451167	KU	6	30 BRN	SP	CRE		V	5/10/2042
2020 PO3566629824	KU	5	35 BRN	SP	CRE	ED,ID,SRS	TD	5/11/2042
2020 PO3539628939	KU	5	35 BRN	SP	CRE	ED,ID,SRS	TD	5/12/2042
2020 PO3578330206	KU	5	35 BRN	SP	CRE	ID	BD	5/13/2042
2020 PO3958382595	F	4	40 BRN	SP	CRE		V	5/14/2042
2020 PO3958582581	F	4	40 BRN	SP	CRE		V	5/15/2042
2020 PO3959682569	F	6	25 BRN	SP	CRE		V	5/16/2042
2020 PO3958782568	F	4	40 BRN	SP	CRE		V	5/17/2042
2020 PO3958982554	F	4	40 BRN	SP	A		V	5/18/2042
2020 PO1229420483	ODP	6	30 KOP	SP	CRE	ID	TD	5/19/2042
2020 PO1173920874	ODP	4	40 BRN	SP	CRE	ID	TD	5/20/2042
2020 PO1214020323	ODP	4	40 BRN	SP	CRE	ID	TD	5/21/2042
2020 PO1243420592	ODP	4	40 CAH	SP	CRE	ID	TD	5/22/2042
2020 PO1210220479	ODP	4	40 BRN	SP	CCA	ED,SRS	TD	5/23/2042
2020 PO4510731813	KU	3	45 ACE	SP	CRE	ED,ID	TD	5/24/2042
2020 PO3959182540	F	1	50 BRN	SP	S		V	5/25/2042
2020 PO3958682540	LGE	4	30 BRN	SP	CRE		V	5/26/2042
2020 PO0907251057	KU	4	40 BRN	SP	CRE	ED,ID,IP	BD	5/27/2042
2020 PO1171720632	ODP	4	40 KOP	SP	CRE	ID	TD	5/28/2042
2020 PO0032561898	KU	4	40 ACW	SP	P	ED,ID	TD	5/29/2042
2020 PO9990461476	KU	4	40 ACW	SP	CCA		V	5/30/2042
2020 PO0024361692	KU	5	35 ACW	SP	CRE	ED,ID	TD	5/31/2042
2020 PO7082589711	KU	5	35 BRN	SP	CRE	ED,ID	TD	6/1/2042
2020 PO7092289639	KU	4	40 BRN	SP	CRE	ED,ID	BD	6/2/2042
2020 PO7087689675	KU	5	35 BRN	SP	CRE	ED,ID	BD	6/3/2042

2020 PO5399007534	KU	6	30 XXX	SP	CRE	ID	BD	6/4/2042
2020 PO5398107460	F	3	40 XXX	SP	CCA		V	6/5/2042
2020 PO5500607355	KU	6	30 XXX	SP	CRE	ED,ID	TD	6/6/2042
2020 PO5469707544	F	4	40 XXX	SP	CRE		V	6/7/2042
2020 PO5469707464	KU	6	30 BRN	SP	CRE	ED,ID	TD	6/8/2042
2020 PO7033389938	KU	5	35 BRN	SP	CCA		V	6/9/2042
2020 PO7039490026	KU	6	30 BRN	SP	CRE	ED,ID	TD	6/10/2042
2020 PO7037189999	F	5	35 BRN	SP	S		V	6/11/2042
2020 PO7046989932	F	6	25E BRN	SP	CCA		V	6/12/2042
2020 PO7050190053	KU	5	35 BRN	SP	CRE	HH,ID	TD	6/13/2042
2020 PO7056689954	F	4	40 BRN	SP	CRE		V	6/14/2042
2020 PO7067389888	F	6	35 BRN	SP	CRE		V	6/15/2042
2020 PO5925106058	F	4	40 BRO	SP	CRE		V	6/16/2042
2020 PO5925106058a	KU	5	35 BRO	SP	CRE	ID	TD	6/17/2042
2020 909705973a	KU	5	35 BRO	SP	CCA		V	6/18/2042
2020 PO5909506080	KU	6	30 BRO	SP	CCA		V	6/19/2042
2020 PO5914906057	KU	4	40 BRO	SP	CRE	ID	TD	6/20/2042
2020 PO5901106030	F	6	30 BRO	SP	CRE		V	6/21/2042
2020 PO5909705973	F	4	40 BRO	SP	CRE		V	6/22/2042
2020 PO5900805964	KU	6	30 BRO	SP	CRE	ID	BD	6/23/2042
2020 PO5909905880	KU	6	30 BRO	SP	CRE	ID	TD	6/24/2042
2020 PO5903906153	KU	6	30 BRO	SP	CCA		V	6/25/2042
2020 PO5914506211	F	3	50 BRO	SP	CCA		V	6/26/2042
2020 PO5931306170	KU	6	30 BRO	SP	CRE	ID	BD	6/27/2042
2020 PO5924706145	KU	3	50 BRO	SP	CRE	ID	TD	6/28/2042
2020 PO5929806215	F	3	45 BRO	SP	CCA		V	6/29/2042
2020 PO5949306193	F	4	40 BRO	SP	CCA		V	6/30/2042
2020 PO5949906119	F	3	45 BRO	SP	CCA		V	7/1/2042
2020 PO5964006081	F	3	45 BRO	SP	CRE		V	7/2/2042
2020 PO5968906056	KU	5	35 BRO	SP	CCA		V	7/3/2042
2020 PO5961006182	KU	4	40 BRO	SP	CCA		V	7/4/2042
2020 PO6004606151	F	4	40 BRO	SP	A		V	7/5/2042
2020 PO5989906192	F	4	40 BRO	SP	A		V	7/6/2042
2020 PO5997306041	KU	4	40 BRO	SP	CRE	ID	TD	7/7/2042
2020 PO6019106125	F	4	40 BRO	SP	CRE		V	7/8/2042
2020 PO6018406077	KU	5	30 BRO	SP	CRE		V	7/9/2042
2020 PO6054405901	KU	4	30 BRO	SP	CRE		V	7/10/2042
2020 PO6047905867	KU	4	30 BRO	SP	A		V	7/11/2042
2020 PO6031905982	KU	2	50 BRO	SP	CCA		V	7/12/2042
2020 PO6050705804	KU	2	50 BRO	SP	CCA		V	7/13/2042
2020 PO6056305630	KU	4	40 BRO	SP	A		V	7/14/2042
2020 PO6087405717	F	4	40 BRO	SP	CCA		V	7/15/2042
2020 PO5461706960	KU	4	40 XXX	SP	CRE	ED,ID	TD	7/16/2042
2020 PO5517806649	KU	4	45 XXX	SP	CRE	RB	X	RP1 7/17/2042
2020 PO5535206544	KU	3	30 XXX	SP	CRE	RB	X	PX 7/18/2042
2020 PO5540706621	KU	4	45 XXX	SP	CRE	ED,ID	TD	7/19/2042
2020 PO5477006823	KU	4	45 XXX	SP	CRE	ED,ID	TD	7/20/2042

2020 PO7529293744	KU	5	35 BRO	SP	CRE	ID	BD	7/21/2042
2020 PO7520693850	KU	6	30 BRO	SP	CRE	ID	BD	7/22/2042
2020 PO7062989763	KU	4	40 BRN	SP	CRE	ED,ID	TD	7/23/2042
2020 PO7071189620	KU	4	45 BRN	SP	CRE	ED,ID	BD	7/24/2042
2020 PO7064089649	KU	5	35 BRN	SP	CRE	ED,ID	TD	7/25/2042
2020 PO7052789849	KU	5	35 BRN	SP	CRE	ED,EP,HH,ID,IP	VX PX	7/26/2042
2020 PO7054689513	KU	5	35 BRN	SP	CRE	ED,ID	BD	7/27/2042
2020 PO7057289420	KU	4	40 BRN	SP	CRE		VX PX	7/28/2042
2020 PO7063089506	KU	4	40 BRN	SP	CRE	ED,ID	BD	7/29/2042
2020 PO7051289334	KU	3	50 BRN	SP	CRE	ED,ID	BD	7/30/2042
2020 PO7445694107	KU	3	45 BRO	SP	CRE	ID	BD	7/31/2042
2020 PO7447494952	KU	5	30 BRO	SP	P	ED,ID,RB	TX RR	8/1/2042
2020 PO7443095055	KU	4	40 BRO	SP	CRE	ED,ID	TD	8/2/2042
2020 PO5501006592	KU	5	35 KOP	SP	CRE	ED,ID	TD	8/3/2042
2020 PO5491406688	KU	4	45 KOP	SP	CRE	ED,ID	TD	8/4/2042
2020 PO7066789185	KU	2	50 BRN	SP	CRE	ED,ID	BD	8/5/2042
2020 PO4083639057	KU	3	45 ACE	SP	CCA		V	8/6/2042
2020 PO4082538807	F	3	45 ACE	SP	P		V	8/7/2042
2020 PO4081438557	F	3	45 ACE	SP	CCA		V	8/8/2042
2020 PO4097338491	KU	3	45 ACE	SP	P		V	8/9/2042
2020 PO4110538430	F	4	40 ACE	SP	CRE		V	8/10/2042
2020 PO4149239892	F	4	40 ACE	SP	CRE		V	8/11/2042
2020 PO4138939559	F	4	40 ACE	SP	P		V	8/12/2042
2020 PO4361902064	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/13/2042
2020 PO4364302194	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/14/2042
2020 PO4136139879	KU	4	40 ACE	SP	CCA	ID	BD	8/15/2042
2020 PO4172440153	F	4	45 ACE	SP	CCA		V	8/16/2042
2020 PO4186740261	F	4	40 ACE	SP	CRE		V	8/17/2042
2020 PO3215050788	KU	5	45 ACE	SP	CRE		V	8/18/2042
2020 PO4355502190	F	4	40 BRO	SP	CRE		V	8/19/2042
2020 PO4358302287	F	4	40 BRO	SP	CRE		V	8/20/2042
2020 PO4326102848-A	KU	5	35 BRO	SP	CCA		V	8/21/2042
2020 PO7055889177	KU	4	40 BRN	SP	CRE	ED,ID	BD	8/22/2042
2020 PO7520494375	KU	4	45 BRO	SP	CRE	ID	BD	8/23/2042
2020 PO7524794332	KU	5	35 BRO	SP	CRE		B	8/24/2042
2020 PO7536394433	KU	5	30 BRO	SP	CRE	ED,ID	TD	8/25/2042
2020 PO7545694294	KU	4	45 BRO	SP	CRE	ID	BD	8/26/2042
2020 PO7562794427	KU	4	40 BRO	SP	CCA		V	8/27/2042
2020 PO7089089107	KU	4	40 BRN	SP	CRE	ED,ID	BD	8/28/2042
2020 PO7078189042	KU	5	35 BRN	SP	CRE	ED,ID	BD	8/29/2042
2020 PO7072289078	KU	4	40 BRN	SP	CCA		V	8/30/2042
2020 PO7075789116	F	3	35 BRN	SP	CCA		V	8/31/2042
2020 PO7070289156	F	3	35 BRN	SP	P		V	9/1/2042
2020 PO7073989206	F	3	35 BRN	SP	CRE		V	9/2/2042
2020 PO7083289283	KU	4	35 BRN	SP	CRE	ED,ID	BD	9/3/2042
2020 PO7077989264	F	2	50 BRN	SP	CRE		V	9/4/2042
2020 PO5390306645	KU	4	40 XXX	SP	CRE	ED,ID	TD	9/5/2042

2020 PO5391906719	KU	6	30 XXX	SP	CRE	ID	BD	9/6/2042
2020 PO5379406776	KU	4	45 KOP	SP	CCA		V	9/7/2042
2020 PO7531894753	KU	5	35 BRO	SP	P	ED,ID	TD	9/8/2042
2020 PO5396706778	KU	6	30 XXX	SP	CRE	ED,ID	TD	9/9/2042
2020 PO5408106769	KU	6	30 BRN	SP	CCA		V	9/10/2042
2020 PO7503294659	KU	5	30 BRO	DF	CRE	ED,ID	TD	9/11/2042
2020 PO5382406627	KU	4	40 KOP	SP	CCA		V	9/12/2042
2020 PO5374706609	KU	4	40 KOP	SP	CCA		V	9/13/2042
2020 PO5366706551	KU	6	30 KOP	SP	CRE		V	9/14/2042
2020 PO5367306596	KU	4	40 KOP	SP	CRE		V	9/15/2042
2020 PO7476494352A	KU	4	30 BRO	SP	CRE	ED,ID	TD	9/16/2042
2020 PO7458594212A	KU	6	35 BRO	SP	CRE	ED,ID	TD	9/17/2042
2020 PO7092389006	F	3	50 BRN	SP	CRE		V	9/18/2042
2020 PO7099988955	F	4	45 BRN	SP	CRE		V	9/19/2042
2020 PO7098389007	KU	5	35 BRN	SP	CRE		V	9/20/2042
2020 5267806410a	KU	6	30 XXX	SP	CCA		V	9/21/2042
2020 PO5267806410	KU	4	40 XXX	SP	CRE	ED,ID	TD	9/22/2042
2020 PO5249906373	KU	4	45 BRN	SP	CCA		V	9/23/2042
2020 PO5234506555	KU	4	40 BRN	SP	CCA		V	9/24/2042
2020 PO5597510343	F	3	45 BRO	SP	CRE		V	9/25/2042
2020 PO5600410217	F	4	40 BRO	SP	CRE		V	9/26/2042
2020 PO5608210176	F	4	40 BRO	SP	CRE		V	9/27/2042
2020 PO5614810138	KU	5	30 BRO	SP	CRE	ID	TD	9/28/2042
2020 PO5604409979a	KU	5	35 BRO	SP	CRE	ED,ID	X	9/29/2042
2020 PO5604409979	KU	3	50 BRO	SP	CCA		V	9/30/2042
2020 PO5552009745	KU	2	50 BRO	SP	CCA		V	10/1/2042
2020 PO5575909869	KU	3	45 BRO	SP	CCA		V	10/2/2042
2020 PO5594209941	KU	3	45 BRO	SP	CCA		V	10/3/2042
2020 PO5615909959	KU	6	30 BRO	SP	CRE	ID	TD	10/4/2042
2020 PO5598609835	KU	6	30 BRO	SP	CRE	ID	TD	10/5/2042
2020 PO5586109803	KU	6	30 BRO	SP	CRE	ID	TD	10/6/2042
2020 PO5553509685	KU	6	30 BRO	SP	CCA		V	10/7/2042
2020 PO5559009637	KU	6	30 BRO	SP	CRE		V	10/8/2042
2020 PO5426412031	KU	4	40 BRO	SP	CCA		V	10/9/2042
2020 PO5519909525	KU	3	45 BRO	SP	CCA		V	10/10/2042
2020 PO7223590223	KU	4	35 BRO	SP	CRE	ED,ID	TD	10/11/2042
2020 PO7254790326	F	3	50 BRO	SP	CRE		V	10/12/2042
2020 PO7589519801	KU	4	35 BRN	SP	CRE	ED,EP,HH,IP,RB	X	10/13/2042
2020 PO7251190352	F	6	30 BRO	SP	CRE		V	10/14/2042
2020 PO7484193348	KU	4	35 BRO	SP	CRE	ED,ID	TD	10/15/2042
2020 PO7493893417	KU	6	35 BRO	SP	CRE	ID	BD	10/16/2042
2020 PO7245590199	KU	4	45 BRO	SP	CRE	ED,ID	TD	10/17/2042
2020 PO7213190269	KU	4	35 BRO	SP	P	ED,ID	TD	10/18/2042
2020 PO7233290030	KU	4	45 BRO	SP	CRE	ED	BD	10/19/2042
2020 PO7238290098	KU	4	45 BRO	SP	CRE	ED	TD	10/20/2042
2020 PO7246090044	KU	5	35 BRO	SP	CCA		V	10/21/2042
2020 PO7103894107	KU	4	40 BRN	SP	CRE	ED,ID	TD	10/22/2042

Business Use

2020 PO7475593409	KU	5	35 BRO	SP	CRE	ED,ID	TD	10/23/2042	
2020 PO7081189446	KU	4	40 BRN	SP	CRE	ED,ID	BD	10/24/2042	
2020 PO7101389383	F	4	40 BRN	SP	CRE	ED,ID	V	10/25/2042	
2020 PO7097989403	KU	6	30 BRN	SP	CRE	ED,ID	TD	10/26/2042	
2020 PO7117094401	KU	4	40 BRN	SP	S		V	10/27/2042	
2020 PO7109194221	KU	6	30 BRN	SP	CRE	ED,ID	TD	10/28/2042	
2020 PO7088394177	KU	5	35 BRN	SP	CRE	ED,ID	BD	10/29/2042	
2020 PO7464893212	KU	4	40 BRO	SP	CRE	ID	BD	10/30/2042	
2020 PO7468493347	KU	3	45 BRO	SP	CRE	ED,ID	TD	10/31/2042	
2020 PO7473393319	KU	4	40 BRO	SP	CRE	ED,ID	TD	11/1/2042	
2020 PO7082789565	KU	6	30 BRN	SP	CRE	ED,ID	TD	11/2/2042	
2020 PO7091989515	KU	5	35 BRN	SP	CRE	ED,ID	BD	11/3/2042	
2020 PO7086689513	KU	3	40 BRN	SP	CRE	ED,ID	BD	11/4/2042	
2020 PO7093289415	F	4	45 BRN	SP	CRE		V	11/5/2042	
2020 PO7090389422	F	4	45 BRN	SP	CRE		V	11/6/2042	
2020 PO7102194470	KU	4	40 BRN	SP	CRE	ED,ID	BD	11/7/2042	
2020 PO7093294291	KU	6	30 BRN	SP	CRE	ED,ID	TD	11/8/2042	
2020 PO7072494248	KU	4	40 BRN	SP	CCA		V	11/9/2042	
2020 PO0863863984	F	3	45E BRN	SP	P		V	11/10/2042	
2020 PO0857264097	KU	2	50 BRN	SP	CCA		V	11/11/2042	
2020 PO0853864038	KU	2	50 BRN	SP	CCA		V	11/12/2042	
2020 PO0845364085	F	3	45E BRN	SP	P		V	11/13/2042	
2020 PO0855064287	F	5	35 BRN	ST	CCA		V	11/14/2042	
2020 PO0826964168	F	3	45 BRN	SP	P		V	11/15/2042	
2020 PO0808364255	F	3	45 BRN	SP	P		V	11/16/2042	
2020 PO0802664279	KU	3	45 BRN	SP	CCA		V	11/17/2042	
2020 PO0808964426	KU	2	50 BRN	SP	CCA		V	11/18/2042	
2020 PO0792764315	F	3	45 BRN	ST	P		V	11/19/2042	
2020 PO0777564387	F	4	40 BRN	SP	P		V	11/20/2042	
2020 PO0775364406	F	4	40 BRN	ST	CRE		V	11/21/2042	
2020 PO0772364409	F	7	35 BRN	ST	CRE		V	11/22/2042	
2020 PO0751764504	F	4	40 BRN	SP	P		V	11/23/2042	
2020 PO0764464446	F	4	40 BRN	SP	CRE		V	11/24/2042	
2020 PO0736264577	F	4	40 BRN	SP	CRE		V	11/25/2042	
2020 PO0722264638	F	3	45 BRN	SP	P		V	11/26/2042	
2020 PO0702964725	F	3	45 BRN	SP	P		V	11/27/2042	
2020 PO0683764792	F	3	45 BRN	SP	CRE		V	11/28/2042	
2020 PO0669464842	F	2	50 BRN	SP	CRE	HH	BX	PX	11/29/2042
2020 PO0671764944	KU	5	35 BRN	SP	CCA		V	11/30/2042	
2020 PO0663264890	KU	5	35 BRN	SP	CCA		V	12/1/2042	
2020 PO0656364886	F	3	45 BRN	SP	P		V	12/2/2042	
2020 PO0643164941	F	4	40 BRN	SP	CRE		V	12/3/2042	
2020 PO0562865604	F	4	40 BRN	SP	P		V	12/4/2042	
2020 PO0575065520	F	4	40 BRN	SP	P		V	12/5/2042	
2020 PO0583865460	F	4	40 BRN	SP	P		V	12/6/2042	
2020 PO2225060692	KU	5	30 BRN	SP	CRE	ID	BD	12/7/2042	
2020 PO2222660933	KU	4	40 BRN	SP	CRE	ID	BD	12/8/2042	

2020 PO9433488207	KU	5	35 APL	SP	CCA		V	12/9/2042
2020 PO8364971720	KU	4	45 BRO	SP	CRE	ED,ID	BD	12/10/2042
2020 PO6866677018	F	4	35 BRN	SP	CCA		V	12/11/2042
2020 PO6877776865	KU	5	35 BRN	SP	CRE	ED,ID	TD	12/12/2042
2020 PO6942777883	KU	5	35 BRN	SP	CRE	ED,ID	BD	12/13/2042
2020 PO8405171175	KU	4	45 BRO	SP	CRE	ED,ID	BD	12/14/2042
2020 PO6912277309	KU	4	40 BRN	SP	CRE	ED,ID	TD	12/15/2042
2020 PO6896977621	KU	4	40 BRN	SP	CRE	ED,ID	TD	12/16/2042
2020 PO6884077729	KU	6	30 BRN	SP	CRE	ED,ID	BD	12/17/2042
2020 PO6673175819	KU	5	35 BRN	SP	CRE	ED,HH,ID,RB	BX	PX 12/18/2042
2020 PO6652575824	KU	5	35 BRN	SP	CCA		V	12/19/2042
2020 PO8207072302	KU	4	45 BRO	SP	CCA		V	12/20/2042
2020 PO8178272414	KU	4	45 BRO	SP	CCA		V	12/21/2042
2020 PO8249272564	KU	5	35 BRO	SP	CRE	ED,ID	BD	12/22/2042
2020 PO8248872718	KU	4	45 BRO	SP	CRE	ED,ID	BD	12/23/2042
2020 PO8239673090	KU	4	40 BRO	SP	CCA		V	12/24/2042
2020 PO8260073011	KU	4	45 BRO	SP	CRE	ED,ID	BD	12/25/2042
2020 PO7210987844	F	3	45 BRO	SP	CRE	ED,ID,RB	VX	RP2 12/26/2042
2020 PO9318680261	KU	4	40 BRO	SP	CCA		V	12/27/2042
2020 PO8133270390	KU	5	35 BRO	SP	A	ED,ID	BD	12/28/2042
2020 PO8129670459	F	5	35 BRO	SP	CRE		V	12/29/2042
2020 PO8124470243	KU	6	30 BRO	SP	A	ED,ID	TD	12/30/2042
2020 PO8127069898	KU	4	40 BRO	SP	A	ED,ID	BD	12/31/2042
2020 PO8125969646	KU	4	40 BRO	SP	A	ED,ID	BD	1/1/2043
2020 PO4488602592	KU	5	40 XXX	SP	CRE	ED,ID	TD	1/2/2043
2020 PO4507202702	KU	4	45 XXX	SP	CRE	ED,ID	TD	1/3/2043
2020 PO4475702562	KU	4	45 KOP	SP	CRE	ED,ID	TD	1/4/2043
2020 PO4445002665	KU	4	45 KOP	SP	CRE	ED,ID	TD	1/5/2043
2020 PO8143169281	KU	6	30 BRO	SP	CRE	ED,ID	BD	1/6/2043
2020 PO8131269219	KU	6	30 BRO	SP	CRE	ED,ID	TD	1/7/2043
2020 PO8122369231	KU	4	40 BRO	SP	CRE	ED,ID	BD	1/8/2043
2020 PO8116769411	KU	4	40 BRO	SP	CRE	ED,ID	TD	1/9/2043
2020 PO8092069442	KU	4	40 BRO	SP	CRE	ED,ID	TD	1/10/2043
2020 PO8067369474	KU	5	35 BRO	SP	CRE	ED,ID	BD	1/11/2043
2020 PO4564502353	KU	4	40 BRO	SP	CRE	ID	TD	1/12/2043
2020 PO4559802297	KU	6	30 BRO	SP	CRE	ID	TD	1/13/2043
2020 PO4556102399	KU	5	30 BRO	SP	CRE	ID	TD	1/14/2043
2020 PO4576802338	KU	6	30 BRO	SP	CRE	ID	TD	1/15/2043
2020 PO4577602246	KU	5	30 BRO	SP	CRE	ID	TD	1/16/2043
2020 PO4565702269	KU	5	30 BRO	SP	CRE	ID	TD	1/17/2043
2020 PO4551302135	KU	6	30 BRO	SP	CRE	ID	TD	1/18/2043
2020 PO4553702213	KU	4	40 BRO	SP	CRE	ID	TD	1/19/2043
2020 PO4501402033	KU	6	30 BRO	SP	CCA		V	1/20/2043
2020 PO4345102488	KU	3	50 KOP	SP	CRE	ED,ID	TD	1/21/2043
2020 PO4106902743	KU	4	40 XXX	SP	CRE	ED,ID	TD	1/22/2043
2020 PO8156170973	KU	4	40 BRO	SP	CCA		V	1/23/2043
2020 PO8162771134	KU	4	40 BRO	SP	CRE	ED,ID	TD	1/24/2043

2020 PO8174071274	KU	4	40 BRO	SP	CRE	ED,HH	BD	1/25/2043
2020 PO6612673564	KU	5	35 BRN	SP	CRE	ED,ID	TD	1/26/2043
2020 PO5015505575	KU	5	30 XXX	SP	CRE	ED,ID	TD	1/27/2043
2020 PO6628173230	KU	6	30 BRN	SP	CRE	ED,ID	TD	1/28/2043
2020 PO6627773075	KU	4	45 BRN	SP	CCA		V	1/29/2043
2020 PO8340367946	KU	4	40 BRO	SP	CRE	ED,ID	BD	1/30/2043
2020 PO8405667937	KU	4	40 BRO	SP	CRE	ED,ID	TD	1/31/2043
2020 PO8399268007	KU	4	40 BRO	SP	CRE	ED,ID	TD	2/1/2043
2020 PO8483967736	KU	6	30 BRO	SP	CRE		V	2/2/2043
2020 PO4771404664	KU	6	30 XXX	SP	CRE	ED,ID	TD	2/3/2043
2020 PO4766404721	KU	4	40 XXX	SP	CRE	ED,ID	TD	2/4/2043
2020 PO4781704801	KU	4	45 XXX	SP	CRE	ED,ID	TD	2/5/2043
2020 PO4562801121	KU	4	40 BRO	SP	CRE	ID	TD	2/6/2043
2020 PO4561501213	KU	4	40 BRO	SP	CRE	ID	TD	2/7/2043
2020 PO4559001267	KU	6	30 BRO	SP	CCA		V	2/8/2043
2020 PO4574401388	KU	4	40 BRO	SP	CRE	ID	TD	2/9/2043
2020 PO4598501670	KU	4	40 BRO	SP	CRE	ID	TD	2/10/2043
2020 PO4598801532	KU	4	40 BRO	SP	CRE	ID	TD	2/11/2043
2020 PO4600201469	KU	4	40 BRO	SP	CRE	ID	TD	2/12/2043
2020 PO5004105579	F	4	40 XXX	SP	P		V	2/13/2043
2020 PO4995005497	F	4	40 XXX	SP	CRE		V	2/14/2043
2020 PO5009205626	F	4	40 XXX	SP	CCA		V	2/15/2043
2020 PO4985605401	F	4	40 XXX	SP	P		V	2/16/2043
2020 PO4881204813	KU	6	30 XXX	SP	CRE	ED,ID	TD	2/17/2043
2020 PO4987305022	KU	4	40 KOP	SP	CCA		V	2/18/2043
2020 PO4970004981	KU	4	40 XXX	SP	CRE	ED,ID	TD	2/19/2043
2020 PO4931004882	KU	4	45 KOP	SP	CCA		V	2/20/2043
2020 PO4944704930	KU	4	40 KOP	SP	CCA		V	2/21/2043
2020 PO4913204818	KU	4	45 XXX	SP	CRE	ED,ID	TD	2/22/2043
2020 PO0889363923	KU	2	50 BRO	SP	CRE	ED,ID,IP	TD	2/23/2043
2020 PO1939147607	KU	4	40 BRN	SP	CRE	ID	BD	2/24/2043
2020 PO0395761183	KU	4	40 ACW	SP	CRE	ID	BD	2/25/2043
2020 PO0404661208	KU	4	40 ACW	SP	CRE	ED,ID	TD	2/26/2043
2020 PO0397061242	F	5	35 ACW	SP	CRE		V	2/27/2043
2020 PO1902047302	KU	4	40 BRN	SP	CRE	ID,IP	BD	2/28/2043
2020 PO1884447459	KU	3	45 BRN	SP	CCA		V	3/1/2043
2020 PO4609101556	KU	5	35 BRO	SP	CRE	ID	TD	3/2/2043
2020 PO1735846423	KU	5	30E BRN	SP	CRE	ID,RB	X	3/3/2043
2020 PO4610101475	KU	4	40 BRO	SP	CRE	ID	TD	3/4/2043
2020 PO4634001948	KU	4	40 BRO	SP	CRE	ID	TD	3/5/2043
2020 PO4611701720	KU	4	40 BRO	SP	CRE	ID	TD	3/6/2043
2020 PO4604501758	KU	6	30 BRO	SP	CRE	ID	TD	3/7/2043
2020 PO4613001879	KU	4	40 BRO	SP	CRE	ID	TD	3/8/2043
2020 PO4541301213	KU	6	30 BRO	SP	CRE	ID	BD	3/9/2043
2020 PO4531301259	KU	6	30 BRO	SP	CRE	ID	TD	3/10/2043
2020 PO4531101418	KU	4	40 BRO	SP	CRE		V	3/11/2043
2020 PO4536201607	KU	6	30 BRO	SP	CCA		V	3/12/2043

2020 PO4543401570	KU	6	30 BRO	SP	CRE	ID	TD	3/13/2043
2020 PO4502801623	KU	6	30 BRO	SP	CCA		V	3/14/2043
2020 PO6693773539	KU	4	40 BRN	SP	CRE	ED,ID	BD	3/15/2043
2020 PO6723473657	KU	5	30 BRN	SP	CRE	ED,ID	BD	3/16/2043
2020 PO6720273543	KU	4	45 BRN	SP	CRE	ED,ID	BD	3/17/2043
2020 PO6718273453	KU	5	30 BRN	SP	CCA		V	3/18/2043
2020 PO6727273518	KU	4	45 BRN	SP	CCA		V	3/19/2043
2020 PO8493167665	KU	6	30 BRO	SP	CRE	ED,ID	BD	3/20/2043
2020 PO1745746332	KU	4	40 BRN	SP	S	ED	TD	3/21/2043
2020 PO1768346247	KU	4	45 BRN	SP	P		B	3/22/2043
2020 PO0470860918	F	4	40 ACW	SP	P	ED,ID	V	3/23/2043
2020 PO0467760867	KU	4	35 ACW	SP	CRE	ED,ID	BD	3/24/2043
2020 PO0903464385	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	3/25/2043
2020 PO0909664585	KU	2	50 BRO	SP	CRE	ED,ID,IP	TD	3/26/2043
2020 PO9104654793	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD	3/27/2043
2020 PO9822453012	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD	3/28/2043
2020 PO0478060820a	F	5	35 ACW	SP	CRE		V	3/29/2043
2020 PO0478060820	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	3/30/2043
2020 PO0487960842	F	5	35 ACW	SP	CRE	ED,EP,ID,IP	V	3/31/2043
2020 PO0486660783	KU	4	40 ACW	SP	CRE	ED,ID	BD	4/1/2043
2020 PO0489160372	KU	5	35 ACW	SP	CRE	ED,ID	BD	4/2/2043
2020 PO0491960440	KU	4	40 ACW	SP	CRE	ED,ID	BD	4/3/2043
2020 PO0500060478	KU	6	30 ACW	SP	CRE	ED,EP,HH,ID,IP,RB	BX	RP1 4/4/2043
2020 PO8491667744	KU	2	65 BRO	SP	CRE		V	4/5/2043
2020 PO8509767533	KU	2	70 BRO	ST	CRE		V	4/6/2043
2020 PO8530567321	KU	2	65 BRO	SP	CRE		V	4/7/2043
2020 PO8522267292	KU	6	30 BRO	SP	CRE	ED,ID	TD	4/8/2043
2020 PO8552767055	KU	2	45 BRO	SP	CRE		V	4/9/2043
2020 PO8544167180	KU	4	40 BRO	SP	CRE	ED,ID	BD	4/10/2043
2020 PO4809004476	KU	4	40 XXX	SP	CRE	ED,ID	TD	4/11/2043
2020 PO6648572970	KU	5	35 BRN	SP	CRE	ED,ID	TD	4/12/2043
2020 PO4813204490	KU	4	45 XXX	SP	CRE		V	4/13/2043
2020 PO6720775105	KU	3	45 BRN	SP	CCA		V	4/14/2043
2020 PO6727875213	KU	4	40 BRN	SP	CRE	ED,ID	BD	4/15/2043
2020 PO6740075448	KU	4	40 BRN	SP	CCA		V	4/16/2043
2020 PO6748675614	KU	4	45 BRN	SP	CCA		V	4/17/2043
2020 PO6660673381	F	4	45 BRN	SP	CRE		V	4/18/2043
2020 PO4789104324	KU	5	35 XXX	SP	CRE	ED,ID	TD	4/19/2043
2020 PO4796504448	KU	5	40 XXX	SP	CRE	ED,ID	TD	4/20/2043
2020 PO1790246157	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	4/21/2043
2020 PO0481260636	KU	4	40 ACW	SP	CRE	ED,ID	TD	4/22/2043
2020 PO0496560543	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	4/23/2043
2020 PO9813252757	KU	4	40 BRO	SP	CCA		V	4/24/2043
2020 PO9810652529	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD	4/25/2043
2020 PO9803752496	KU	4	40 BRO	SP	CCA		V	4/26/2043
2020 PO0915864797	KU	2	50 BRO	SP	CRE	ED,ID,IP	TD	4/27/2043
2020 PO0921264970	KU	2	50 BRO	SP	CRE	ED,ID,IP	TD	4/28/2043

2020 PO0897264186	KU	2	50 BRO	SP	CRE	ED,ID,IP	TD			4/29/2043
2020 PO0500660725	KU	4	40 ACW	SP	CRE	ED,ID	TD			4/30/2043
2020 PO0509560683	KU	4	40 ACW	SP	CRE	ED,ID	BD			5/1/2043
2020 PO0511360742	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD			5/2/2043
2020 PO0529460794	KU	6	30 ACW	SP	CRE	ED,ID,IP	TD			5/3/2043
2020 PO0499460791	F	5	35 ACW	SP	CRE		V			5/4/2043
2020 PO0523760683	F	5	35 ACW	SP	CRE	ED,ID	V			5/5/2043
2020 PO0520761106	F	5	35 ACW	SP	CRE		V			5/6/2043
2020 PO1815446051	KU	4	35 BRN	SP	CRE	ID,IP	TD			5/7/2043
2020 PO8338169433	KU	2	65 BRO	SP	CRE		V			5/8/2043
2020 PO1865644621	KU	4	40 BRN	SP	CRE	ID,IP,SRS	TX	RR		5/9/2043
2020 PO8329069429	KU	6	30 BRO	SP	CRE	ED,ID	TD			5/10/2043
2020 PO8328569544	KU	5	35 BRO	SP	CRE	ED,ID	TX	RR		5/11/2043
2020 PO8289069084	KU	4	40 BRO	SP	CCA		V			5/12/2043
2020 PO8294668993	KU	4	40 BRO	SP	CRE	ED,ID	TD			5/13/2043
2020 PO8300368909	KU	4	40 BRO	SP	CRE	ED,ID	BD			5/14/2043
2020 PO4802104541	KU	5	40 XXX	SP	CRE	ED,ID	TD			5/15/2043
2020 PO4806904650	KU	4	45 XXX	SP	CRE	ED,ID	TD			5/16/2043
2020 PO4811504762	KU	4	40 XXX	SP	CRE	ED,ID	TD			5/17/2043
2020 PO4745404508	KU	4	45 XXX	SP	CRE	ED,ID	TD			5/18/2043
2020 PO4753804483	KU	6	30 XXX	SP	CRE	ED,ID	TD			5/19/2043
2020 PO4746504393	KU	6	30 BRN	SP	CRE		V			5/20/2043
2020 PO4735804263	KU	4	40 CPT	SP	CRE	ED,ID	TD			5/21/2043
2020 PO4694204649	KU	5	35 ACW	SP	CRE	ED,ID	TD			5/22/2043
2020 PO8366868807	F	3	40 BRO	SP	CRE		V			5/23/2043
2020 PO8355668714	KU	4	40 BRO	SP	CRE	ED,ID	BD			5/24/2043
2020 PO1838844780	F	4	40 BRN	SP	P		V			5/25/2043
2020 PO1836144700	KU	3	45 BRN	SP	S		V			5/26/2043
2020 PO0528461140	KU	3	40 ACW	SP	CRE	ED,ID	TD			5/27/2043
2020 PO0532261223	KU	5	35 ACW	SP	CRE	ED,ID	TD			5/28/2043
2020 PO0534561273	KU	4	35 ACW	SP	CRE	ED,EP,HH,ID,IP,RB	X	PX		5/29/2043
2020 PO0523261162	KU	4	40 ACW	SP	CRE	ED,ID	TD			5/30/2043
2020 PO0515161196	KU	4	40 ACW	SP	CCA		V			5/31/2043
2020 PO0499961260	KU	4	40 ACW	SP	CCA		V			6/1/2043
2020 PO0503361308	F	5	35 ACW	SP	CRE		V			6/2/2043
2020 PO0488261220	KU	5	35 ACW	SP	CRE	ED,ID	BD			6/3/2043
2020 PO0491161297	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD			6/4/2043
2020 PO0490461364	F	5	35 ACW	SP	CRE	ED,ID	V			6/5/2043
2020 PO0473661371	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD			6/6/2043
2020 PO0475461429	F	5	35 ACW	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX		6/7/2043
2020 PO0460161429	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD			6/8/2043
2020 PO0452961460	KU	6	30 ACW	SP	P	ED	TD			6/9/2043
2020 PO0459661493	F	4	40 ACW	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX		6/10/2043
2020 PO1819844744	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD			6/11/2043
2020 PO1800444795	KU	4	40 BRN	SP	CRE	ED,ID,IP,SRC	TX	RR		6/12/2043
2020 PO1780444848	KU	4	40 BRN	SP	CRE	ED,ID	TD			6/13/2043
2020 PO0064052299	KU	2	50 BRO	SP	CCA		V			6/14/2043

2020 PO0007850501	KU	4	45 BRO	SP	CRE	ED,ID,SRS	TD	6/15/2043
2020 PO0015550705	KU	4	45 BRO	SP	CRE	ED,ID,SRS	TD	6/16/2043
2020 PO9999650750	KU	4	40 BRO	SP	CRE	ID	BD	6/17/2043
2020 PO0029851032	KU	4	40 BRO	SP	CRE		V	6/18/2043
2020 PO0044651429	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/19/2043
2020 PO0039951761	KU	4	40 BRO	SP	CRE	ID	BD	6/20/2043
2020 PO0075352405	F	4	40 BRO	SP	CRE		V	6/21/2043
2020 PO1765844887	KU	4	45 BRN	SP	CRE	ID,IP	TD	6/22/2043
2020 PO0423061504	KU	6	30 ACW	SP	CRE	ED,ID	TD	6/23/2043
2020 PO0421361407	KU	6	30 ACW	SP	CRE	ED,EP,HH,ID,IP,RB	X PX	6/24/2043
2020 PO0445961490	F	5	35 ACW	SP	CRE	ED,ID	V	6/25/2043
2020 PO0436361529	F	5	35 ACW	SP	CRE	ED,ID	V	6/26/2043
2020 PO0436261600	F	9	20 ACW	OT	CRE		V	6/27/2043
2020 PO8328268505	KU	5	35 BRO	SP	A	ED,ID	BD	6/28/2043
2020 PO8307168369	KU	4	40 BRO	SP	CRE		V	6/29/2043
2020 PO8150572521	KU	4	45 BRO	SP	CCA		V	6/30/2043
2020 PO8231072264	KU	4	45 BRO	SP	CCA		V	7/1/2043
2020 PO8240072500	KU	4	45 BRO	SP	CRE	ED,ID	BD	7/2/2043
2020 PO8259672169	KU	4	40 BRO	SP	CRE	ED,ID	BD	7/3/2043
2020 PO8262272284	KU	4	45 BRO	SP	CRE	ED,ID	BD	7/4/2043
2020 PO8289072204	KU	4	40 BRO	SP	CRE	ED,ID	BD	7/5/2043
2020 PO8315772243	KU	4	45 BRO	SP	CRE	ED,ID	BD	7/6/2043
2020 PO8336272037	KU	5	45 BRO	SP	CRE	ED,ID	BD	7/7/2043
2020 PO8382271499A	KU	5	35 BRO	SP	CCA		V	7/8/2043
2020 PO8421870926	KU	4	45 BRO	SP	CRE	ED,ID	BD	7/9/2043
2020 PO8382271499	KU	4	45 BRO	SP	CRE	ED,ID	BD	7/10/2043
2020 PO8398271154	KU	4	40 BRO	SP	CRE	ED,ID	BD	7/11/2043
2020 PO8302269533	F	4	35 BRO	SP	CCA		V	7/12/2043
2020 PO4695304829	KU	5	35 BRN	SP	CRE	ED,ID	TD	7/13/2043
2020 PO4713204594	KU	4	40 ACW	SP	CRE	ED,ID	TD	7/14/2043
2020 PO8316369667	KU	2	65 BRO	SP	CRE		V	7/15/2043
2020 PO8243570001	F	4	45 BRO	SP	CCA		V	7/16/2043
2020 PO8249370429	KU	2	65 BRO	SP	CRE		V	7/17/2043
2020 PO8288669967	KU	1	75 BRO	SP	CCA		V	7/18/2043
2020 PO8269670125	KU	2	65 BRO	SP	CRE		V	7/19/2043
2020 PO8301569831	KU	2	70 BRO	SP	CRE		V	7/20/2043
2020 PO7447093092	KU	4	40 BRO	SP	CRE	ID	BD	7/21/2043
2020 PO7435893190	KU	5	35 BRO	SP	CCA		V	7/22/2043
2020 PO7433493090	KU	5	35 BRO	SP	CCA		V	7/23/2043
2020 PO7598320137	KU	4	45 BRN	SP	CRE	ED	TD	7/24/2043
2020 PO7567320497	KU	3	45 BRN	SP	CRE	MD	TD	7/25/2043
2020 PO7578420788	KU	4	45 BRN	SP	CRE	ED	TD	7/26/2043
2020 PO7584420954	KU	4	45 BRN	SP	CRE	ED	TD	7/27/2043
2020 PO7062021325	KU	6	30 BRN	SP	CCA		V	7/28/2043
2020 PO6980201398	KU	6	30 BRN	SP	CRE	ED	TD	7/29/2043
2020 PO3857382137	LGE	4	30 BRO	SP	CCA		V	7/30/2043
2020 PO3855782122	LGE	2	65 BRO	SP	CRE		V	7/31/2043

2020 PO3857082140	LGE	2	65 BRO	SP	CRE		V		8/1/2043
2020 PO3855682151	LGE	4	40 BRO	SP	CCA		VX	PX	8/2/2043
2020 PO3955382725	LGE	3	45 BRN	SP	S		V		8/3/2043
2020 PO3954582707	LGE	3	45 BRN	SP	S		V		8/4/2043
2020 PO3954182698	LGE	1	90 BRN	SP	CRE		V		8/5/2043
2020 PO9486643557	ODP	3	45 BRN	SP	CCA		V		8/6/2043
2020 PO3037851171	KU	4	40 BRO	SP	CRE	ED		TD	8/7/2043
2020 PO9459143607	ODP	4	40 BRN	SP	CCA		V		8/8/2043
2020 PO9456543892A	ODP	4	35 BRN	SP	CCA		V		8/9/2043
2020 PO9456543892	ODP	3	45 BRN	SP	CCA		V		8/10/2043
2020 PO9442844156	ODP	4	40 BRN	SP	CCA		V		8/11/2043
2020 PO5165933481	F	4	40 BRO	SP	CRE		V		8/12/2043
2020 PO1242635275	ODP	6	30 BRN	SP	CCA		V		8/13/2043
2020 PO1231235225	ODP	4	40 BRN	SP	CRE	ED,ID		TD	8/14/2043
2020 PO1230835329	ODP	4	40 BRN	SP	CRE	ED,ID		TD	8/15/2043
2020 PO1241635435	ODP	6	30 BRN	SP	CRE	ED,ID		TD	8/16/2043
2020 PO1222235375	ODP	4	40 BRN	SP	CRE		V		8/17/2043
2020 PO1231035439	ODP	4	40 BRN	SP	CRE	ED,ID		TD	8/18/2043
2020 PO1238835527	ODP	4	40 BRN	SP	CRE	ED,ID		TD	8/19/2043
2020 PO1249135560	ODP	6	30 BRN	SP	CRE	ED,ID		TD	8/20/2043
2020 PO1249935630	ODP	4	40 BRN	SP	CRE	ED,ID		TD	8/21/2043
2020 PO1262435729	ODP	3	55 BRN	SP	CRE	ID		BD	8/22/2043
2020 PO3114950659	KU	4	40 BRO	SP	CRE	ED,ID,IP		TD	8/23/2043
2020 PO9441744523	ODP	4	40 BRN	SP	CCA		V		8/24/2043
2020 PO3940381858	LGE	4	35 BRN	SP	CCA		V		8/25/2043
2020 PO3942481845	LGE	4	35 BRN	SP	A	ED,ID		TD	8/26/2043
2020 PO3941381852	LGE	4	35 BRN	SP	P	ED,ID		TD	8/27/2043
2020 PO3943481838	LGE	4	35 BRN	SP	CRE	ED,ID		TD	8/28/2043
2020 PO3944481831	LGE	4	35 BRN	SP	CRE	ED,ID		TD	8/29/2043
2020 PO3945481825	LGE	4	35 BRN	SP	A	ED,ID		BD	8/30/2043
2020 PO5216433146	F	3	45 BRO	SP	CCA		V		8/31/2043
2020 PO5194433286	F	4	40 BRO	SP	CRE		V		9/1/2043
2020 PO5173933420	KU	3	45 BRO	SP	CCA		V		9/2/2043
2020 PO4799731233	KU	4	35 BRO	SP	CCA		V		9/3/2043
2020 PO5905448416	F	4	40 ACE	SP	CRE		V		9/4/2043
2020 PO5915748519	F	4	40 ACE	SP	CRE		V		9/5/2043
2020 PO5137132311	F	4	40 BRO	SP	CRE		V		9/6/2043
2020 PO5173632176	F	4	40 BRO	SP	CRE		V		9/7/2043
2020 PO5203632065	F	4	40 BRO	SP	CRE		V		9/8/2043
2020 PO5886347878	KU	6	30 ACE	SP	CRE	ED,ID		TD	9/9/2043
2020 PO9559894697	KU	6	35 ACW	SP	CRE	ED,HH,ID,MD,RB	X	PX	9/10/2043
2020 PO9599694804	KU	6	30 ACW	SP	CRE	ED,ID		TD	9/11/2043
2020 PO9574094822	KU	6	30 ACW	SP	CRE	ED,ID		TD	9/12/2043
2020 PO9575194801	C	7	25 ACW	SP	CRE		V		9/13/2043
2020 PO3946481818	LGE	4	35 BRN	SP	A	ED,ID		TD	9/14/2043
2020 PO3947581811	LGE	4	35 BRN	SP	A	ED,ID		TD	9/15/2043
2020 PO3948681804	LGE	4	35 BRN	SP	A	ED,ID		TD	9/16/2043

2020 PO3949681798	LGE	4	35 BRN	SP	A	ED,ID	BD	9/17/2043
2020 PO1404437160	ODP	5	35 KOP	SP	CRE	ED,ID	TD	9/18/2043
2020 PO1402537287	ODP	2	55 KOP	SP	CRE	ID	BD	9/19/2043
2020 14044-37160B	ODP	7	20 KOP	SP	A		V	9/20/2043
2020 PO1408037107	ODP	6	30 KOP	SP	S		V	9/21/2043
2020 14044-37160A	ODP	5	35 KOP	SP	A		V	9/22/2043
2020 13909-37148A	ODP	5	30 KOP	SP	S		V	9/23/2043
2020 PO9435844848	ODP	3	45 BRN	SP	CCA		V	9/24/2043
2020 PO9441744523A	ODP	4	40 BRN	SP	CCA		V	9/25/2043
2020 PO9408344912	ODP	3	45 BRN	SP	CCA		V	9/26/2043
2020 PO9380644854	ODP	3	45 BRN	SP	CCA		V	9/27/2043
2020 PO3957582778	LGE	3	55 BRN	SP	A	ED,ID	TD	9/28/2043
2020 PO9338044782A	ODP	3	45 BRN	SP	CCA		V	9/29/2043
2020 PO9358344810	ODP	3	45 BRN	SP	CCA		V	9/30/2043
2020 PO9308744747	ODP	3	45 BRN	SP	CCA		V	10/1/2043
2020 PO6426804377	KU	6	30 UNK	SP	CCA		V	10/2/2043
2020 PO7385020099	F	4	40 BRN	SP	CRE		V	10/3/2043
2020 PO6910820632	KU	6	30 BRN	SP	CRE	ED,ID,IP	TX RR	10/4/2043
2020 PO7336420839	F	4	40 BRN	SP	CRE		V	10/5/2043
2020 PO7195821066	KU	6	30 BRN	SP	CRE		V	10/6/2043
2020 PO7292320659	KU	1	60 BRN	SP	CCA		V	10/7/2043
2020 PO7603222573	KU	4	40 BRN	SP	CCA		V	10/8/2043
2020 PO7604122988	KU	6	30 BRN	SP	CCA		V	10/9/2043
2020 PO7592622592	KU	6	35 BRN	SP	CRE		V	10/10/2043
2020 PO9338044782	ODP	3	45 BRN	SP	CCA		V	10/11/2043
2020 PO9277844823	ODP	3	45 BRN	SP	CCA		V	10/12/2043
2020 PO9207745006	ODP	2	55 BRN	SP	CCA		V	10/13/2043
2020 PO9245044899	ODP	2	55 BRN	SP	CCA		V	10/14/2043
2020 PO3949181756	LGE	4	35 BRN	SP	CRE	ED,ID	TD	10/15/2043
2020 PO3949781766	LGE	4	40 BRN	SP	CCA		V	10/16/2043
2020 PO3950481776	LGE	4	35 BRN	SP	P	ED,ID	T	10/17/2043
2020 PO3951181786	LGE	4	35 BRN	SP	CRE	ED,ID	TD	10/18/2043
2020 PO5841647820	KU	4	40 ACE	SP	CRE	ED,ID	TD	10/19/2043
2020 PO3951781796	LGE	4	40 BRN	SP	CCA		V	10/20/2043
2020 PO3952981813	LGE	4	30 BRN	SP	CRE	ED,ID	TD	10/21/2043
2020 PO3952281820	LGE	4	30 BRN	SP	P	ED,ID	T	10/22/2043
2020 PO3958182786	LGE	4	40 BRN	SP	A	ED,ID	TD	10/23/2043
2020 Po2475126271a	ODP	5	30 BRN	SP	CCA		V	10/24/2043
2020 PO2391526333	F	4	40 BRN	SP	A		V	10/25/2043
2020 PO2409926230	F	4	40 BRN	SP	A		V	10/26/2043
2020 PO2438926239	F	4	40 BRN	SP	A		V	10/27/2043
2020 PO2475126271	F	4	40 BRN	SP	A		V	10/28/2043
2020 PO2395026140	ODP	4	40 BRN	SP	CRE	ID	BD	10/29/2043
2020 PO1390937148	ODP	4	45 KOP	SP	CRE	ED,ID,MD	TD	10/30/2043
2020 PO1381437021	ODP	4	45 KOP	SP	CRE	ED,ID	TD	10/31/2043
2020 PO1364236774	ODP	4	45 KOP	SP	CRE		V	11/1/2043
2020 PO1357836607	ODP	2	50 KOP	SP	A	ED,ID,MD	TD	11/2/2043

2020 13586-36287A	ODP	2	50 KOP	SP	S		V			11/3/2043
2020 PO3907582667	LGE	4	40 BRO	SP	P	ED,ID,RB	TX	RR		11/4/2043
2020 PO3906082659	LGE	4	25 BRO	SP	CRE	ED,ID	TD			11/5/2043
2020 PO3906282640	LGE	4	40 BRO	SP	CCA		V			11/6/2043
2020 PO3893082602	LGE	4	40 BRO	SP	CCA		V			11/7/2043
2020 PO4728688074	F	4	30 BRO	SP	CCA	MD	VX	RP3		11/8/2043
2020 PO9555286087	KU	4	40 ACW	SP	S		V			11/9/2043
2020 PO9575386048	KU	3	50 ACW	SP	CRE	ED,ID	BD			11/10/2043
2020 PO5973143910	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD			11/11/2043
2020 PO4833012462	F	4	40 BRO	SP	A		V			11/12/2043
2020 PO4870612274	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD			11/13/2043
2020 PO5963643758	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD			11/14/2043
2020 PO4848112095	KU	4	40 BRO	SP	A	ED,ID,IP	TD			11/15/2043
2020 PO9159681874	KU	4	45 BRN	SP	CCA		V			11/16/2043
2020 PO5952043653	F	4	40 ACE	SP	P		V			11/17/2043
2020 PO5990543830	KU	6	30 ACE	SP	CRE	ED,ID	TD			11/18/2043
2020 PO5920543821	KU	3	45 ACE	SP	CCA		V			11/19/2043
2020 PO5929443639	KU	3	45 ACE	SP	CCA		V			11/20/2043
2020 PO5935243642	F	5	35 ACE	SP	CRE		V			11/21/2043
2020 PO1795847646	ODP	3	50 BRN	SP	CRE	ED,ID	TD			11/22/2043
2020 PO1788647571	F	5	35 UNK	SP	CRE		V			11/23/2043
2020 PO1781047508	ODP	5	35 UNK	SP	CRE	ED,ID	TD			11/24/2043
2020 PO1788847292	ODP	4	40 UNK	SP	CRE	ED,ID	TD			11/25/2043
2020 PO1781747209	ODP	6	30 UNK	SP	CRE		V			11/26/2043
2020 PO1759347172	ODP	5	30 UNK	SP	CRE		V			11/27/2043
2020 PO1494845946	ODP	5	35 ACW	SP	CRE		V			11/28/2043
2020 PO1493246439	ODP	5	35 ACW	SP	CRE		V			11/29/2043
2020 PO1551646905	ODP	5	35 ACW	SP	CRE		V			11/30/2043
2020 PO1586247052	ODP	5	35 ACW	SP	CRE		V			12/1/2043
2020 PO1622047078	ODP	5	35 ACW	SP	CRE		V			12/2/2043
2020 PO1640547154	ODP	5	35 ACW	SP	CRE		V			12/3/2043
2020 PO1679847321	ODP	5	35 ACW	SP	CRE		V			12/4/2043
2020 PO1731047215	ODP	5	35 BRN	SP	CRE	ED,ID	TD			12/5/2043
2020 PO1700447364	ODP	4	45 BRN	SP	CCA		V			12/6/2043
2020 PO1658548373	ODP	5	35 BRN	SP	CRE	ED,ID,SRS	TD			12/7/2043
2020 PO1668248208	ODP	5	35 BRN	SP	CRE	ED,EP,HH,ID,IP,MD,RB	VX	PX		12/8/2043
2020 PO1683747777	ODP	4	40 BRN	SP	CRE	ED,ID	TD			12/9/2043
2020 PO1685847654	ODP	4	45 BRN	SP	CCA		V			12/10/2043
2020 PO1709448503	ODP	6	30 BRN	SP	CCA		V			12/11/2043
2020 PO1696448464	ODP	4	45 BRN	SP	CCA		V			12/12/2043
2020 PO1703348626	ODP	6	30 BRN	SP	CCA		V			12/13/2043
2020 PO1691548573	ODP	4	40 BRN	SP	CCA		V			12/14/2043
2020 PO1643648645	ODP	4	45 BRN	SP	CCA		V			12/15/2043
2020 PO1619648816	ODP	4	45 BRN	SP	CCA		V			12/16/2043
2020 PO0016816419	KU	5	35 XXX	SP	CRE	ED	TD			12/17/2043
2020 PO0016816419A	KU	4	40 XXX	SP	S		V			12/18/2043
2020 PO9990016364	KU	5	35 XXX	SP	CRE	ED	TD			12/19/2043

2020 PO9786417618	KU	4	40 XXX	SP	CRE	ED	TD	12/20/2043	
2020 PO9806017481	KU	5	35 XXX	SP	CRE	ED	TD	12/21/2043	
2020 PO9823117382	KU	5	35 XXX	SP	CRE	ED	TD	12/22/2043	
2020 PO9840317273	KU	4	40 XXX	SP	CRE	ED	TD	12/23/2043	
2020 PO7657125594	KU	5	30 XXX	SP	CRE		V	12/24/2043	
2020 PO7667525469	KU	5	30 XXX	SP	CRE		V	12/25/2043	
2020 PO7678925328	KU	5	35 XXX	SP	CRE	ED	TD	12/26/2043	
2020 PO7692325262	KU	5	35 XXX	SP	CRE	ED	TD	12/27/2043	
2020 PO7736825441	KU	5	40 XXX	SP	CRE	ED	TD	12/28/2043	
2020 PO7766925423	KU	6	30 XXX	SP	CRE	ED	TD	12/29/2043	
2020 PO7773825576	KU	4	40 XXX	SP	CRE	ED	TD	12/30/2043	
2020 PO3927883029	F	3	30 BRO	SP	CCA		V	12/31/2043	
2020 PO3927583015	F	4	40 BRO	SP	P		V	1/1/2044	
2020 PO3930383001	F	4	40 BRO	SP	P		V	1/2/2044	
2020 PO3928983008	F	4	40 BRO	SP	A		V	1/3/2044	
2020 PO3931882994	F	4	40 BRO	SP	P		V	1/4/2044	
2020 PO3933082987	F	3	45 BRO	SP	CCA		V	1/5/2044	
2020 PO3934382981	F	4	40 BRO	SP	A		V	1/6/2044	
2020 PO2064942795	ODP	5	35 KOP	SP	CRE	ED,EP,ID,MD,SRC	TD	1/7/2044	
2020 PO2074543057	ODP	4	40 KOP	SP	CRE	ED,ID	TD	1/8/2044	
2020 PO2087943368	ODP	4	40 KOP	SP	CRE	ID	BD	1/9/2044	
2020 PO2041841860	ODP	1	70 KOP	SP	S		V	1/10/2044	
2020 PO2056141751	ODP	2	50 KOP	SP	S		V	1/11/2044	
2020 PO3927882094	LGE	4	35 BRN	SP	CCA	ED,ID	BD	1/12/2044	
2020 PO3926582101	F	4	40 BRN	SP	CRE		V	1/13/2044	
2020 PO3926082090	F	4	40 BRN	SP	CCA		V	1/14/2044	
2020 PO3925382100	LGE	4	30 BRN	SP	CRE		V	1/15/2044	
2020 PO4018482798	F	3	45 BRN	SP	S		V	1/16/2044	
2020 PO3925682089	F	4	40 BRN	SP	CRE		V	1/17/2044	
2020 PO3925682067	LGE	4	30 BRN	SP	P	ED,ID	T	1/18/2044	
2020 PO3925182078	F	4	40 BRN	SP	CRE		V	1/19/2044	
2020 PO3924582055	F	3	45 BRN	SP	CCA		V	1/20/2044	
2020 PO4019682782	F	4	40 BRN	SP	A		V	1/21/2044	
2020 PO3936082982	F	5	25 BRO	SP	P		V	1/22/2044	
2020 PO4654988622	LGE	4	35 BRN	SP	CCA		V	1/23/2044	
2020 PO3935682974	F	4	40 BRO	SP	P		V	1/24/2044	
2020 PO9272472552	KU	5	40 OTH	SP	CRE	ED,ID,SRC	TX	RR	1/25/2044
2020 PO3937482972	F	5	25 BRO	SP	P		V	1/26/2044	
2020 PO3936682966	F	4	40 BRO	SP	P		V	1/27/2044	
2020 PO3999482609	LGE	4	45 BRN	SP	CCA		V	1/28/2044	
2020 PO4000882607	F	4	40 BRN	SP	CRE		V	1/29/2044	
2020 PO4002482604	F	4	40 BRN	SP	A		V	1/30/2044	
2020 PO4003582610	F	3	45 BRN	SP	S		V	1/31/2044	
2020 PO4003282622	F	4	40 BRN	SP	CRE		V	2/1/2044	
2020 PO4003582629	F	4	30 BRN	SP	A		V	2/2/2044	
2020 PO4002982633	F	3	45 BRN	SP	A		V	2/3/2044	
2020 PO3945381983	LGE	4	30 BRN	SP	A	ED,ID	TD	2/4/2044	

2020 PO3938182011	LGE	4	40 BRN	SP	CRE	ED,ID	TD	2/5/2044
2020 PO3934482941	F	4	40 BRO	SP	P		V	2/6/2044
2020 PO3932982949	F	4	40 BRO	SP	P		V	2/7/2044
2020 PO4000182671	F	4	30 BRN	SP	CRE		V	2/8/2044
2020 PO3999882668	F	4	40 BRN	SP	CCA		V	2/9/2044
2020 PO4000882661	F	4	30 BRN	SP	CCA		V	2/10/2044
2020 PO4001082665	F	4	40 BRN	SP	CRE		V	2/11/2044
2020 PO4001782656	F	4	30 BRN	SP	A		V	2/12/2044
2020 PO9267672515A	KU	3	45 OTH	SP	P		V	2/13/2044
2020 PO9267672515	KU	5	40 OTH	SP	CRE	ID	BD	2/14/2044
2020 PO9273772625	KU	6	30 OTH	SP	CCA		V	2/15/2044
2020 PO9260072625	KU	5	45 OTH	SP	CRE	ED,ID	BD	2/16/2044
2020 PO4655988576	LGE	UNK	30 BRN	SP	CRE		V	2/17/2044
2020 PO4655888578	LGE	4	30 BRN	SP	A	ED,ID	BD	2/18/2044
2020 PO4657088572	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD	2/19/2044
2020 PO4658188556	LGE	4	40 BRN	SP	A	ED,ID	BD	2/20/2044
2020 PO4657588564	LGE	3	45 BRN	SP	CCA		V	2/21/2044
2020 PO4655688551	LGE	4	35 BRN	SP	A	ED,ID	BD	2/22/2044
2020 PO4824088519	LGE	4	35 BRO	SP	CCA		V	2/23/2044
2020 PO4822288520	LGE	UNK	60 BRO	SP	CRE		V	2/24/2044
2020 PO4817688497-A	LGE	4	30 BRO	SP	CRE	ED,ID	TD	2/25/2044
2020 PO4821588526	LGE	4	40 BRO	SP	CRE	ED	BD	2/26/2044
2020 PO4820488465	LGE	UNK	45 BRO	SP	CRE	ED	BD	2/27/2044
2020 PO4001982660	F	3	45 BRN	SP	S		V	2/28/2044
2020 PO4003282649	F	4	40 BRN	SP	CRE		V	2/29/2044
2020 PO4003582669	F	6	25 BRN	SP	CRE		V	3/1/2044
2020 PO3932182953	F	4	40 BRO	SP	P		V	3/2/2044
2020 PO3930982959	F	4	40 BRO	SP	P		V	3/3/2044
2020 PO3929882965	F	4	40 BRO	SP	P		V	3/4/2044
2020 PO3540747694	F	4	40 BRO	SP	CRE		V	3/5/2044
2020 PO3939382005	LGE	4	40 BRN	SP	CRE	ED,ID	TD	3/6/2044
2020 PO2061141571	ODP	2	50 KOP	SP	S		V	3/7/2044
2020 PO2058341386	ODP	2	50 KOP	SP	S		V	3/8/2044
2020 PO2048241225	ODP	2	50 KOP	SP	S		V	3/9/2044
2020 PO3928682971	F	4	40 BRO	SP	A		V	3/10/2044
2020 PO3928182980	LGE	4	30 BRO	SP	P	ED,ID	TD	3/11/2044
2020 PO3927582977	F	4	40 BRO	SP	P		V	3/12/2044
2020 PO3926382983	F	4	40 BRO	SP	P		V	3/13/2044
2020 PV3925282989	F	4	40 BRO	SP	P		V	3/14/2044
2020 PO4011782630	LGE	4	40 BRN	SP	CRE	ED,ID	TD	3/15/2044
2020 PO4011482625	LGE	4	30 BRN	SP	CRE	ED,ID	BD	3/16/2044
2020 PO4009782632	F	4	30 BRN	SP	CCA		V	3/17/2044
2020 PO2000341572	ODP	4	45 KOP	SP	CRE	ED,ID,IP	TD	3/18/2044
2020 PO2010341587	ODP	5	35 KOP	SP	S		V	3/19/2044
2020 PO2019941716	ODP	4	45 KOP	SP	S		V	3/20/2044
2020 PO3524647799	F	4	40 BRO	SP	CRE		V	3/21/2044
2020 PO4009982640	F	4	40 BRN	SP	S		V	3/22/2044

2020 PO4008382640	F	4	30 BRN	SP	A		V					3/23/2044
2020 PO4008682648	F	3	40 BRN	SP	CCA		V					3/24/2044
2020 PO4007782645	F	6	30 BRN	SP	A		V					3/25/2044
2020 PO4008082651	F	3	45 BRN	SP	S		V					3/26/2044
2020 PO4006382652	F	4	30 BRN	SP	CRE		V					3/27/2044
2020 PO4006782659	F	4	40 BRN	SP	CCA		V					3/28/2044
2020 PO4004982659	F	4	30 BRN	SP	CRE		V					3/29/2044
2020 PO4004182665	F	4	40 BRN	SP	CCA		V					3/30/2044
2020 PO4004982669	F	4	40 BRN	SP	CRE		V					3/31/2044
2020 PO4004682671	F	4	40 BRN	SP	CCA		V					4/1/2044
2020 PO3508047910	F	4	40 BRO	SP	CRE		V					4/2/2044
2020 PO4004382681	LGE	4	35 BRN	SP	A	ED,ID,RB	TX			RR		4/3/2044
2020 PO4004382679	F	4	30 BRN	SP	CRE		V					4/4/2044
2020 PO4005282682	F	4	40 BRN	SP	A		V					4/5/2044
2020 PO3495447992	F	4	40 BRO	SP	CRE		V					4/6/2044
2020 PO4691988624	LGE	4	35 BRN	SP	A	ED,ID,SRC	TX			RR		4/7/2044
2020 PO3923482950	F	5	25 BRO	SP	A		V					4/8/2044
2020 PO3923782957	F	4	40 BRO	SP	P		V					4/9/2044
2020 PO3924982951	F	4	40 BRO	SP	P		V					4/10/2044
2020 PO3924382959	LGE	4	30 BRO	SP	P	ED,ID	TD					4/11/2044
2020 PO9312094220	KU	3	40 ACW	SP	S		V					4/12/2044
2020 PO9268994520	KU	6	30 ACW	SP	CRE		V					4/13/2044
2020 PO9253194619	KU	6	30 ACW	SP	CRE		V					4/14/2044
2020 PO5747255388	KU	5	35 ACE	SP	CRE	ED,ID	BD					4/15/2044
2020 PO5750055712	KU	4	45 ACE	SP	CRE	ED,ID	BD					4/16/2044
2020 PO9035292244	KU	4	45 XXX	SP	CRE	ID	BD					4/17/2044
2020 PO5741855878	KU	4	40 ACE	SP	CCA		V					4/18/2044
2020 PO5731956077	KU	3	45 ACE	SP	CCA		V					4/19/2044
2020 PO5741856089	KU	5	35 ACE	SP	CRE	ED,ID	TD					4/20/2044
2020 PO5717956225	KU	6	30 ACE	SP	CCA	ED	T					4/21/2044
2020 PO5723656249	KU	4	40 ACE	SP	CRE	ED,ID	TD					4/22/2044
2020 PO5706956348	KU	6	30 ACE	SP	CRE	ED,ID	TD					4/23/2044
2020 PO5716556403	KU	5	35 ACE	SP	CRE	ED,HH,ID	TD					4/24/2044
2020 PO5712856512	KU	5	35 ACE	SP	CRE	ED,ID	TD					4/25/2044
2020 PO5705056643	KU	5	35 ACE	SP	CRE	ED,EP,ID,MD	BX			RP1		4/26/2044
2020 PO5707357135	KU	4	40 ACE	SP	CRE	ED,ID	TD					4/27/2044
2020 PO5672851035	F	3	45 ACE	SP	CCA		V					4/28/2044
2020 PO5795137535	F	4	40 BRO	SP	CRE		V					4/29/2044
2020 PO4737936940	KU	4	45 BRO	SP	CRE	ID	TD					4/30/2044
2020 PO4641436672	F	4	40 BRO	SP	CRE		V					5/1/2044
2020 PO4641236760	KU	3	45 BRO	SP	CCA		V					5/2/2044
2020 PO4698436907	KU	3	45 BRO	SP	CCA		V					5/3/2044
2020 PO4721236847	KU	4	40 BRO	SP	CRE	ID	BD					5/4/2044
2020 PO4746736875	KU	4	45 BRO	SP	CRE	ID	TD					5/5/2044
2020 PO4742836976	F	4	40 BRO	SP	CRE		V					5/6/2044
2020 PO5437445908	KU	6	30 BRO	SP	CRE	ID,IP	TD					5/7/2044
2020 PO5437045982	KU	4	45 BRO	SP	CRE	ID,IP	TD					5/8/2044

2020 PO4778636661	KU	5	35 BRO	SP	CRE	ID	TD	5/9/2044
2020 PO4721736966	KU	3	50 BRO	SP	CCA		V	5/10/2044
2020 PO4768436903	KU	3	50 BRO	SP	CCA		V	5/11/2044
2020 PO4721936926	KU	3	45 BRO	SP	CCA		V	5/12/2044
2020 PO4785237209	KU	4	40 BRO	SP	CRE	ID,IP	TD	5/13/2044
2020 PO5384346134	KU	4	40 BRO	SP	CRE		V	5/14/2044
2020 PO5384646043	KU	2	55 BRO	SP	CRE		V	5/15/2044
2020 PO5399346035	KU	3	45 BRO	SP	CCA		V	5/16/2044
2020 PO5243740514	KU	6	30 ACE	ST	CCA		V	5/17/2044
2020 PO4791337160	F	7 20E	BRO	SP	CRE		V	5/18/2044
2020 PO4781637123	KU	4	40 BRO	SP	CRE	ID	TD	5/19/2044
2020 PO4795537011	F	4	40 BRO	SP	CCA	ID	V	5/20/2044
2020 PO5426245990	KU	6	30 BRO	SP	CCA	SRS	TD	5/21/2044
2020 PO5416645992	KU	3	50 BRO	SP	CCA		V	5/22/2044
2020 PO4795736513	KU	4	40 BRO	SP	CRE	ID	BD	5/23/2044
2020 PO4795536930	KU	2	50 BRO	SP	CRE	HH	X	RP2 5/24/2044
2020 PO4795536839	KU	4	45 BRO	SP	CRE	HH	X	RP2 5/25/2044
2020 PO4795736713	KU	4	40 BRO	SP	CRE	ID	TD	5/26/2044
2020 PO4783036717	KU	6	30 BRO	SP	CCA		V	5/27/2044
2020 PO5185939957	KU	5	35 ACE	SP	CCA	ED	T	5/28/2044
2020 PO5410045730	KU	6	30 BRO	SP	CRE		V	5/29/2044
2020 PO5427845681	KU	4	40 BRO	SP	CRE	ID,IP	TD	5/30/2044
2020 PO5425445548	KU	4	40 BRO	SP	CRE	ID,IP	TD	5/31/2044
2020 PO5397345797	KU	5	35 BRO	SP	CRE	ID	TD	6/1/2044
2020 PO5395945839	KU	4	45 BRO	SP	CRE	ID,IP	TD	6/2/2044
2020 PO5199640129	F	4	40 ACE	SP	CRE		V	6/3/2044
2020 PO5218940081	F	5	35 ACE	SP	CCA		V	6/4/2044
2020 PO5210240126	F	4	40 ACE	SP	CRE		V	6/5/2044
2020 PO5211440259	F	4	40 ACE	SP	CRE		V	6/6/2044
2020 PO4890737414	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	6/7/2044
2020 PO4879537399	KU	4	40 ACE	SP	CRE	ID,IP	BD	6/8/2044
2020 PO4893837049	KU	4	40 ACE	SP	CRE	ID,IP	BD	6/9/2044
2020 PO4891037118	F	4	40 ACE	SP	CCA		V	6/10/2044
2020 PO4936837100	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	6/11/2044
2020 PO4917237153	F	3	45 ACE	SP	CCA		V	6/12/2044
2020 PO4917737077	KU	3	45 ACE	SP	CCA		V	6/13/2044
2020 PO4936837100-A	KU	5	35 ACE	SP	CCA		V	6/14/2044
2020 PO5031237371	KU	4	45 ACE	SP	CRE	ED,ID	TD	6/15/2044
2020 PO5033637432	KU	4	45 ACE	SP	CRE	ID,IP	BD	6/16/2044
2020 PO5017637372	KU	4	45 ACE	SP	CRE	ID,IP	BD	6/17/2044
2020 PO5004937375	KU	4	45 ACE	SP	CRE	ED,ID,IP	TX	RR 6/18/2044
2020 PO5011537665	KU	4	45 ACE	SP	CRE	ID,IP	BD	6/19/2044
2020 PO5015737841	KU	4	45 ACE	SP	CRE	ID,IP	BD	6/20/2044
2020 PO5037137825	KU	4	40 ACE	SP	CRE	ID,IP	BD	6/21/2044
2020 PO5038937937	KU	6	30 ACE	SP	CCA	ED	T	6/22/2044
2020 PO5012338002	KU	4	45 ACE	SP	CRE	ED,ID	TD	6/23/2044
2020 PO5236040435	F	3	45 ACE	SP	CRE		V	6/24/2044

2020 PO5221740445	F	4	40 ACE	SP	CCA		V			6/25/2044
2020 PO5213040402	F	4	40 ACE	SP	CRE		V			6/26/2044
2020 PO5214640507	F	2	50 ACE	SP	CCA		V			6/27/2044
2020 PO5225840569	F	4	40 ACE	SP	CRE		V			6/28/2044
2020 PO5215240637	F	4	40 ACE	SP	CRE		V			6/29/2044
2020 PO5203240663	F	4	40 ACE	SP	CRE		V			6/30/2044
2020 PO9617395235	KU	6	35 ACW	SP	CRE	ED,EP,ID,RB	TX		RR	7/1/2044
2020 PO5327724833	KU	2	45 BRO	SP	CRE	ED,ID,IP	TD			7/2/2044
2020 5312124815-A	KU	3	45 BRO	SP	CRE	ED,ID	TD			7/3/2044
2020 PO5334124653	KU	2	45 BRO	SP	CRE	ED,ID,IP	TD			7/4/2044
2020 PO5376624591	KU	2	45 BRO	SP	CRE	ED,ID,IP	TD			7/5/2044
2020 PO9176292572	KU	5	40 XXX	SP	CRE	ED,ID,RB	X		RP1	7/6/2044
2020 PO9201693017	KU	4	40 BRN	SP	S		V			7/7/2044
2020 PO9097794004	KU	6	30 BRN	SP	S		V			7/8/2044
2020 PO9186392720	KU	4	40 XXX	SP	CRE	ED,ID,RB	X		RP1	7/9/2044
2020 PO9623294760	KU	6	35 ACW	SP	CRE	ED,ID,IP,SRC	TX		RR	7/10/2044
2020 PO9625794709	KU	5	35 ACW	SP	CRE	ED,ID	TD			7/11/2044
2020 PO9617394773	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD			7/12/2044
2020 PO9612994594A	KU	6	30 ACW	SP	CRE	ED,ID	BD			7/13/2044
2020 PO9612994594	C	3	40 ACW	SP	S		V			7/14/2044
2020 PO9619494660	KU	4	40 ACW	SP	CRE	ED,ID	TD			7/15/2044
2020 PO9611994519	KU	3	45 ACW	SP	CCA		V			7/16/2044
2020 PO9625994888	KU	6	30 ACW	SP	CRE	ED,ID	BD			7/17/2044
2020 PO5966148977	KU	4	40 ACE	SP	CRE	ED,ID	TD			7/18/2044
2020 PO9069293821	KU	3	40 BRN	SP	S		V			7/19/2044
2020 PO9142494040	KU	4	45 BRN	SP	CRE	ED,ID	TD			7/20/2044
2020 PO9085693869	KU	3	40 XXX	SP	CRE	ED,ID	TX		RR	7/21/2044
2020 PO5972148941	KU	4	40 ACE	SP	CRE	ED,ID	BD			7/22/2044
2020 PO5986848850	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD			7/23/2044
2020 5430324504-A	KU	4	40 BRO	SP	A	ED,ID,IP	TD			7/24/2044
2020 PO5430324504	KU	2	45 BRO	SP	CRE	ED,ID,IP	TD			7/25/2044
2020 PO5481224427	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD			7/26/2044
2020 PO5521324356	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			7/27/2044
2020 PO5560124070	KU	4	40 BRO	SP	CRE	ED,ID	TD			7/28/2044
2020 PO558824325	KU	2	50 BRO	SP	CRE	ED,ID	TD			7/29/2044
2020 5560124070-B	KU	6	30 BRO	SP	A	ED,ID,IP	TD			7/30/2044
2020 5560124070-A	KU	2	35 BRO	SP	CRE	ED,ID,IP	TD			7/31/2044
2020 5588024333-A	KU	4	40 BRO	SP	A	ED,ID,IP	BD			8/1/2044
2020 PO5588024333	KU	5	35 BRO	SP	A	ED,ID,IP	TD			8/2/2044
2020 PO5624924834	F	3	40 BRO	SP	A		V			8/3/2044
2020 PO5626425035	F	4	40 BRO	SP	CRE		V			8/4/2044
2020 PO5627225195	F	3	40 BRO	SP	CRE		V			8/5/2044
2020 PO5629825400	F	4	40 BRO	SP	CRE		V			8/6/2044
2020 PO5630925592	KU	3	40 BRO	SP	CRE		V			8/7/2044
2020 PO5632925777	F	5	35 BRO	SP	CRE		V			8/8/2044
2020 PO5634025919	KU	4	40 BRO	SP	CRE		V			8/9/2044
2020 PO5635226062	F	4	40 BRO	SP	CRE		V			8/10/2044

2020 PO5641126012	KU	6	30 BRO	SP	A		V	8/11/2044
2020 PO5636526273	F	4	40 BRO	SP	CRE		V	8/12/2044
2020 PO5642826519	F	5	30 BRO	SP	A		V	8/13/2044
2020 PO5636626501	F	4	40 BRO	SP	A		V	8/14/2044
2020 PO5633426752	F	4	40 BRO	SP	A		V	8/15/2044
2020 PO5632526927	F	3	45 BRO	SP	CRE		V	8/16/2044
2020 PO5631627256	F	4	40 BRO	SP	A		V	8/17/2044
2020 PO5631127503	F	4	40 BRO	SP	A		V	8/18/2044
2020 PO5641627694	F	4	40 BRO	SP	A		V	8/19/2044
2020 PO5616827610	F	5	35 BRO	SP	A		V	8/20/2044
2020 PO5654727693	KU	4	35 BRO	SP	A	ED,ID,IP	TD	8/21/2044
2020 PO5648127842	F	4	40 BRO	SP	A		V	8/22/2044
2020 PO5997048636	KU	4	45 ACE	SP	CRE	ED,ID	TD	8/23/2044
2020 PO5992748819	KU	3	45 ACE	SP	CCA		V	8/24/2044
2020 PO9134594015	KU	3	45 BRN	SP	CCA		V	8/25/2044
2020 PO9130394001	KU	4	40 XXX	SP	CRE	ID	BD	8/26/2044
2020 PO6059748318	KU	6	30 ACE	SP	CCA		V	8/27/2044
2020 PO6959748318	KU	6	30 ACE	SP	CCA		V	8/28/2044
2020 PO6059748318	KU	3	45 ACE	SP	CCA		V	8/29/2044
2020 PO5980148702	KU	4	45 ACE	SP	CRE	ED,ID	BD	8/30/2044
2020 PO9614894907	KU	4	40 ACW	SP	CRE	ED,ID	TD	8/31/2044
2020 PO9121293974	KU	4	40 XXX	SP	CRE	ED,ID	TD	9/1/2044
2020 PO9100093911	KU	4	45 XXX	SP	CRE	ED,ID	TD	9/2/2044
2020 PO9083293959	KU	5	45 XXX	SP	CRE	ID	BD	9/3/2044
2020 PO9081294027	C	4	40 XXX	SP	CRE		V	9/4/2044
2020 PO9227092852	C	4	40 XXX	SP	CRE		V	9/5/2044
2020 PO9207392799	KU	4	40 XXX	SP	CRE	ED,ID	BD	9/6/2044
2020 PO9255392979	KU	4	45 BRN	SP	CRE	ED,ID	TD	9/7/2044
2020 PO9199592771	KU	4	40 XXX	SP	CRE	ED,ID	TD	9/8/2044
2020 PO9245792981	C	4	40 BRN	SP	CRE		V	9/9/2044
2020 PO9244592937	KU	4	40 BRN	SP	S		V	9/10/2044
2020 PO9223692864	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/11/2044
2020 PO5934348709	F	3	50 ACE	SP	CCA		V	9/12/2044
2020 PO5924948617	F	3	45 ACE	SP	CCA		V	9/13/2044
2020 PO5944448813	F	4	40 ACE	SP	CRE		V	9/14/2044
2020 PO9559394722	KU	4	40 ACW	SP	CRE	ED,ID	TD	9/15/2044
2020 PO9559394722A	KU	4	40 ACW	SP	CRE	ED,ID	TD	9/16/2044
2020 PO9551794738	KU	6	35 ACW	SP	CRE	ED,ID	TD	9/17/2044
2020 PO9559894697	KU	3	35 ACW	SP	CRE	ED,ID	TD	9/18/2044
2020 PO9264192954	KU	5	35 BRN	SP	CRE	ED,ID	TD	9/19/2044
2020 PO5656027973	F	4	40 BRO	SP	A		V	9/20/2044
2020 PO5692753298	KU	4	40 ACE	SP	CCA		V	9/21/2044
2020 PO4519204597	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/22/2044
2020 PO4510804699	KU	3	45 BRO	SP	CCA		V	9/23/2044
2020 PO4526504643	KU	3	50 BRO	SP	CCA		V	9/24/2044
2020 PO5810546355	KU	4	40 ACE	SP	CRE	ED,ID	TD	9/25/2044
2020 PO5385044239	F	4	40 BRO	SP	CRE		V	9/26/2044

2020 PO4676936883	KU	3	45 BRO	SP	CRE	ID	TD	9/27/2044
2020 PO3954932049	KU	3	45 BRO	SP	CRE	ID,IP	TD	9/28/2044
2020 PO5416743301	KU	4	45 BRO	SP	CRE	ID	TD	9/29/2044
2020 PO5367342498	F	4	40 ACE	SP	CRE		V	9/30/2044
2020 PO4311733564	KU	4	40 BRO	SP	CCA	ED	TD	10/1/2044
2020 PO4340233872	KU	4 35E	BRO	SP	P	ID,IP	BD	10/2/2044
2020 PO5486043542	KU	6	30 BRO	SP	CRE	ED,HH,ID	BX	RP2 10/3/2044
2020 PO5481043810	KU	6	30 BRO	SP	CRE	ID	BD	10/4/2044
2020 PO5531643955	KU	6	30 BRO	SP	CRE	ID	BD	10/5/2044
2020 PO5525443563	KU	6	30 BRO	SP	CRE	ID	BD	10/6/2044
2020 PO5508143295	KU	6	30 BRO	SP	CRE	ID	BD	10/7/2044
2020 PO5483343364	KU	6	30 BRO	SP	CRE	ID	BD	10/8/2044
2020 PO4340233872	KU	4	40 BRO	SP	CRE	ID	TD	10/9/2044
2020 PO5343942755	F	4	40 ACE	SP	CRE		V	10/10/2044
2020 PO4334033988	KU	6	30 BRO	SP	CCA		V	10/11/2044
2020 PO4324334402	KU	6	30 BRO	SP	CCA		V	10/12/2044
2020 PO4357234073	KU	4	40 BRO	SP	CRE	ID,IP	TD	10/13/2044
2020 PO4372334226	KU	4	40 BRO	SP	CRE	ID	TD	10/14/2044
2020 PO4388134381	KU	4	40 BRO	SP	CRE	ID,IP	TD	10/15/2044
2020 PO5432743703	F	4	40 BRO	SP	A		V	10/16/2044
2020 PO5437943768	F	4	40 BRO	SP	CRE		V	10/17/2044
2020 PO5421643840	F	4	40 BRO	SP	A		V	10/18/2044
2020 PO5419343953	F	4	40 BRO	SP	A		V	10/19/2044
2020 PO5418344048	F	4	40 BRO	SP	A		V	10/20/2044
2020 PO5402443988	F	4	40 BRO	SP	A		V	10/21/2044
2020 PO5364842649	F	4	40 ACE	SP	CRE		V	10/22/2044
2020 PO5324042828	KU	4	40 ACE	SP	CCA		V	10/23/2044
2020 PO5324842849	F	4	40 ACE	SP	CRE		V	10/24/2044
2020 PO4345934389	F	3 45E	BRO	SP	CCA		V	10/25/2044
2020 PO4367034389	F	3	40 BRO	SP	P		V	10/26/2044
2020 PO4402234529	KU	4	40 BRO	SP	CRE	ID,IP	TD	10/27/2044
2020 PO4418234697	KU	4 45E	BRO	SP	CRE	ID	TD	10/28/2044
2020 PO5405643727	KU	6	30 BRO	SP	CRE	ID	TD	10/29/2044
2020 PO5400844463	KU	6	30 BRO	SP	CRE	ED,ID	TD	10/30/2044
2020 PO4430634851	KU	4	40 BRO	SP	CRE	ID	TD	10/31/2044
2020 PO4441335006	KU	4	40 BRO	SP	CRE	ED	VX	RP1 11/1/2044
2020 PO5408644533	KU	6	30 BRO	SP	CRE	ID	BD	11/2/2044
2020 PO5214637238	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	11/3/2044
2020 PO4382335542	KU	4	45 BRO	SP	CCA		V	11/4/2044
2020 PO4308035535	F	4	40 BRO	SP	CRE		V	11/5/2044
2020 PO4316435527	KU	4	40 BRO	SP	CRE	IP	TD	11/6/2044
2020 PO5209337306	F	4	40 ACE	SP	CCA		V	11/7/2044
2020 PO5223837493	KU	6	30 ACE	SP	CCA		V	11/8/2044
2020 PO5434844070-A	KU	4	40 BRO	SP	CCA		V	11/9/2044
2020 PO5434844070	KU	4	40 BRO	SP	CRE	ID,IP	TD	11/10/2044
2020 PO5223337355	KU	6	30 ACE	SP	CCA		V	11/11/2044
2020 PO5223437298	F	4	40 ACE	SP	CRE		V	11/12/2044

2020 PO4433435544	KU	4	40 BRO	SP	CRE	ID,IP	BD	11/13/2044
2020 PO5233037274	F	5	30 ACE	SP	CRE		V	11/14/2044
2020 PO5236637254	KU	4	40 ACE	SP	CCA		V	11/15/2044
2020 PO5236737286	F	4	40 ACE	SP	CRE		V	11/16/2044
2020 PO5236737286-A	KU	4	40 ACE	SP	CRE		V	11/17/2044
2020 PO5235337644	F	3	40 ACE	SP	CCA		V	11/18/2044
2020 PO5434044170	KU	4	45 BRO	SP	CRE	ID	BD	11/19/2044
2020 PO5413444298	F	4	40 BRO	SP	CCA		V	11/20/2044
2020 PO5432844285	KU	4	45 BRO	SP	CRE	ID	TD	11/21/2044
2020 PO5407244560	F	3	45 BRO	SP	A		V	11/22/2044
2020 PO4439135325	KU	4	40 BRO	SP	CRE	ID,IP	TD	11/23/2044
2020 PO5216237956	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	11/24/2044
2020 PO5425644537	KU	3	45 BRO	SP	CCA		V	11/25/2044
2020 PO5418644546	F	4	40 BRO	SP	CCA	HH	VX	RP1 11/26/2044
2020 PO5426844800	KU	4	40 BRO	SP	CRE	ID	BD	11/27/2044
2020 PO5420944972	KU	6	30 BRO	SP	CCA		V	11/28/2044
2020 PO5420644787	KU	6	30 BRO	SP	CCA		V	11/29/2044
2020 PO5225837849	KU	4	45 ACE	SP	CRE	ID,IP	BD	11/30/2044
2020 PO5229437899	KU	6	30 ACE	SP	CCA		V	12/1/2044
2020 PO5216637862	F	4	40 ACE	SP	CRE		V	12/2/2044
2020 PO5209437753	F	3	45 ACE	SP	CCA		V	12/3/2044
2020 PO5234437850	F	3	45 ACE	SP	CCA		V	12/4/2044
2020 PO5242237942	F	4	40 ACE	SP	CRE		V	12/5/2044
2020 PO4489334982	KU	4	40 BRO	SP	CRE	ID,IP	TD	12/6/2044
2020 PO6161865849	KU	4	35 OTH	SP	CRE	ID	TD	12/7/2044
2020 PO6165065926	KU	4	35 OTH	SP	CRE	ID	TD	12/8/2044
2020 PO6164966048	KU	4	40 OTH	SP	CRE	ID	TD	12/9/2044
2020 PO4784588808	LGE	4	40 BRN	SP	CRE	ED,ID	TD	12/10/2044
2020 PO4785288798	LGE	4	40 BRN	SP	CRE	ED,ID	TD	12/11/2044
2020 PO3916750870	F	7 25E	OTH	SP	CRE		V	12/12/2044
2020 PO4759388834	LGE	4	40 BRN	SP	CRE	ED,ID	BD	12/13/2044
2020 PO4758288828	LGE	4	40 BRN	SP	P	ED,ID,IP	TD	12/14/2044
2020 PO4048783024	LGE	4	40 BRN	SP	CCA	ED,HH,ID,RB	X	RP2 12/15/2044
2020 PO4044583011	LGE	4	30 BRN	SP	P	ED,ID	TD	12/16/2044
2020 PO4044883051	LGE	4	40 BRN	SP	CCA		V	12/17/2044
2020 PO4044883045	LGE	4	35 BRN	SP	P	ED,ID	TD	12/18/2044
2020 PO4046783044	LGE	4	30 BRN	SP	P	ED,ID	TD	12/19/2044
2020 PO4046883050	LGE	4	40 BRN	SP	P	ED,ID	TD	12/20/2044
2020 PO4716489342	F	3	45 BRO	SP	CCA		V	12/21/2044
2020 PO4715389333	F	4	40 BRO	SP	P		V	12/22/2044
2020 PO4183011437	KU	4	40 BRO	SP	CRE	ID	BD	12/23/2044
2020 PO4177011510	KU	4	40 BRO	SP	CRE	ID	BD	12/24/2044
2020 PO4171911567	KU	4	40 BRO	SP	CRE	ID	BD	12/25/2044
2020 PO4147311389	KU	4	40 BRO	SP	CRE	ID	BD	12/26/2044
2020 PO4788411535	KU	4	40 BRO	SP	CRE	ED,ID	TD	12/27/2044
2020 PO4784811457	KU	5	35 BRO	SP	CRE	ED,ID	TD	12/28/2044
2020 PO4755211623	KU	5	35 BRO	SP	CCA		V	12/29/2044

2020 PO4759911741	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		12/30/2044
2020 PO4756011892	KU	5	30 BRO	SP	CRE	ID,IP	BD		12/31/2044
2020 PO4770612001	KU	4	40 BRO	SP	CRE	HH,ID,RB	X	RP2	1/1/2045
2020 PO4728189212	F	3	45 BRO	SP	CCA		V		1/2/2045
2020 PO4766011887	KU	4	40 BRO	SP	CRE	ED,ID	TD		1/3/2045
2020 PO4729389257	F	3	45 BRO	SP	CCA		V		1/4/2045
2020 PO4729089255	F	3	45 BRO	SP	CCA		V		1/5/2045
2020 PO4727789247	F	3	45 BRO	SP	CCA		V		1/6/2045
2020 PO4726989243	F	3	45 BRO	SP	CCA		V		1/7/2045
2020 PO4725789235	F	3	45 BRO	SP	CCA		V		1/8/2045
2020 PO4727989215	F	4	35 BRO	SP	CCA		V		1/9/2045
2020 PO4726989204	F	4	40 BRO	SP	CCA		V		1/10/2045
2020 PO5077908904	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP	BX	RP1	1/11/2045
2020 PO5047709035	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX	1/12/2045
2020 PO5061808975	F	4	40 ACE	SP	P		V		1/13/2045
2020 PO5034709091	F	4	40 ACE	SP	CRE		V		1/14/2045
2020 PO5021509143	F	4	40 ACE	SP	CRE		V		1/15/2045
2020 PO5028309344	F	4	40 ACE	SP	P		V		1/16/2045
2020 PO4746112085	KU	5	35 BRO	SP	CCA		V		1/17/2045
2020 PO4725789197	F	3	45 BRO	SP	CCA		V		1/18/2045
2020 PO4724589228	F	3	45 BRO	SP	CCA		V		1/19/2045
2020 PO4698212308	KU	5	35 BRO	SP	CRE	HH,ID,IP,RB	BX	PX	1/20/2045
2020 PO4723389220	F	3	45 BRO	SP	CCA		V		1/21/2045
2020 PO4722089213	F	3	45 BRO	SP	CCA		V		1/22/2045
2020 PO4721789210	LGE	4	35 BRO	SP	CRE		V		1/23/2045
2020 PO4720989205	F	4	40 BRO	SP	CCA		V		1/24/2045
2020 PO4719689198	F	4	40 BRO	SP	CCA		V		1/25/2045
2020 PO4721889177	F	4	35 BRO	SP	CCA		V		1/26/2045
2020 PO5034109494	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,MD,RB	BX	RP1	1/27/2045
2020 PO5040009647	F	4	40 ACE	SP	P		V		1/28/2045
2020 PO5046109798	F	4	40 ACE	SP	CRE		V		1/29/2045
2020 PO5047009997	F	4	40 ACE	SP	P		V		1/30/2045
2020 PO5032710056	F	4	40 ACE	SP	P		V		1/31/2045
2020 PO5029109965	F	5	35 ACE	SP	CRE		V		2/1/2045
2020 PO4718589178	F	3	45 BRO	SP	CCA		V		2/2/2045
2020 PO4719489162	F	3	45 BRO	SP	CCA		V		2/3/2045
2020 PO4720289148	F	3	45 BRO	SP	CCA		V		2/4/2045
2020 PO4722089174	F	3	45 BRO	SP	CCA		V		2/5/2045
2020 PO4722589166	F	4	40 BRO	SP	CCA		V		2/6/2045
2020 PO4723489182	F	3	45 BRO	SP	CCA		V		2/7/2045
2020 PO4724689190	F	3	45 BRO	SP	CCA		V		2/8/2045
2020 PO4729289194	F	4	40 BRO	SP	CRE		V		2/9/2045
2020 PO4728689204	F	4	40 BRO	SP	CCA		V		2/10/2045
2020 PO4708489079	LGE	4	40 BRO	SP	CRE	ED,ID	BD		2/11/2045
2020 PO4832111897	KU	6	30 BRO	SP	CRE	ED,ID	TD		2/12/2045
2020 PO4834611775	KU	5	35 BRO	SP	P	ID	BD		2/13/2045
2020 PO5014510130	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,MD,RB	BX	PX	2/14/2045

2020 PO5005809771	F	5	35 ACE	SP	CRE	ED,ID	V			2/15/2045
2020 PO4724912217	KU	5	35 BRO	SP	CRE	HH,ID,IP,RB	X	PX		2/16/2045
2020 PO5010710035	F	4	40 ACE	SP	P		V			2/17/2045
2020 PO4849311412	KU	4	45 BRO	SP	CRE	ID,IP,RB	BX	PX		2/18/2045
2020 PO5003910210	F	4	40 ACE	SP	P		V			2/19/2045
2020 PO5005110168	F	4	40 ACE	SP	P		V			2/20/2045
2020 PO4009882891	LGE	4	40 BRO	SP	CCA		V			2/21/2045
2020 PO4009782915	LGE	4	40 BRO	SP	CCA		V			2/22/2045
2020 PO4010182918	LGE	4	40 BRO	SP	CCA		V			2/23/2045
2020 PO4994910209	F	4	40 ACE	SP	P		V			2/24/2045
2020 PO4986710242	F	4	40 ACE	SP	P		V			2/25/2045
2020 PO4862711561	KU	5	35 BRO	SP	CCA		V			2/26/2045
2020 PO4865711642	KU	4	45 BRO	SP	CRE	ED,ID			TD	2/27/2045
2020 PO4854511544	KU	4	40 BRO	SP	CRE	ID			BD	2/28/2045
2020 PO4710189124	LGE	3	45 BRO	SP	CCA		V			3/1/2045
2020 PO4711089153	LGE	4	30 BRO	SP	CRE	ED,ID			BD	3/2/2045
2020 PO4711389163	LGE	4	30 BRO	SP	CCA		V			3/3/2045
2020 PO4711889156	LGE	3	45 BRO	SP	CCA		V			3/4/2045
2020 PO4714889176	LGE	4	35 BRO	SP	A	RB	X	PX		3/5/2045
2020 PO4717689194	LGE	4	40 BRO	SP	CRE	ED,ID			TD	3/6/2045
2020 PO4719689207	LGE	3	45 BRO	SP	CCA		V			3/7/2045
2020 PO4990110091	F	5	35 ACE	SP	P		V			3/8/2045
2020 PO4976909846	F	5	35 ACE	SP	CRE	ED,ID	V			3/9/2045
2020 PO4010582878	LGE	4	40 BRO	SP	P	ED,ID			TD	3/10/2045
2020 PO4010482881	LGE	4	40 BRO	SP	P	ED,ID			TD	3/11/2045
2020 PO4685409336	KU	4	40 BRO	SP	CRE	ID,IP			BD	3/12/2045
2020 PO4921224359	KU	4	40 BRO	SP	CRE		V			3/13/2045
2020 PO4982325735	KU	2	45 BRO	SP	CRE		V			3/14/2045
2020 PO4987225711	KU	2	45 BRO	SP	CRE		V			3/15/2045
2020 PO4989925916	KU	4	40 BRO	SP	CRE		V			3/16/2045
2020 PO4911924123	KU	4	40 BRO	SP	CRE		V			3/17/2045
2020 PO4885523476	KU	3	45 BRO	SP	CCA		V			3/18/2045
2020 PO4899523830	KU	3	45 BRO	SP	CCA		V			3/19/2045
2020 PO5006202404	KU	4	40 KOP	SP	CRE	ED,ID			BD	3/20/2045
2020 PO4917201627	KU	4	40 KOP	SP	CRE	ED,ID			BD	3/21/2045
2020 PO4931901734	KU	4	45 KOP	SP	CRE	ID			BD	3/22/2045
2020 PO4922101699	KU	4	35 KOP	SP	CRE	ED,ID			TD	3/23/2045
2020 PO4758688797	LGE	4	40 BRN	SP	CRE	ED,ID,IP			TD	3/24/2045
2020 PO4695788891	LGE	4	50 BRO	SP	P	ED,ID			BD	3/25/2045
2020 PO4037001766	LGE	4	35 BRO	SP	P	ED			TD	3/26/2045
2020 PO4695788893	LGE	4	50 BRO	SP	P	ED,ID			BD	3/27/2045
2020 PO4695288905	F	2	60 BRO	SP	CCA		V			3/28/2045
2020 PO4697388914	F	2	50 BRO	SP	CCA		V			3/29/2045
2020 PO4698688918	F	2	50 BRO	SP	CCA		V			3/30/2045
2020 PO4948301853	KU	4	40 KOP	SP	CRE	ID			BD	3/31/2045
2020 PO4759488805	LGE	4	40 BRN	SP	CRE	ED,ID			TD	4/1/2045
2020 PO5023002349	KU	5	35 KOP	SP	CRE	ED,ID			BD	4/2/2045

2020 PO5011302430	KU	1	75 BRO	SP	CRE	ID	BD	4/3/2045
2020 PO4759988808	LGE	4	40 BRN	SP	CRE	ED,ID	TD	4/4/2045
2020 PO4700388923	F	2	50 BRO	SP	CCA		V	4/5/2045
2020 PO4702188932	F	2	50 BRO	SP	CCA		V	4/6/2045
2020 PO4703988937	F	2	50 BRO	SP	CCA		V	4/7/2045
2020 PO2028321261A	ODP	4	40 XXX	SP	CCA	ED	T	4/8/2045
2020 PO2029321159	ODP	6	30 XXX	SP	CCA		V	4/9/2045
2020 PO2028321261	ODP	4	40 XXX	SP	CCA	ED	T	4/10/2045
2020 PO2058221196	ODP	4	40 XXX	SP	CCA	ED	T	4/11/2045
2020 PO3873308882	KU	4	40 BRO	SP	CRE	ID,IP	BD	4/12/2045
2020 PO3839908476	KU	4	45 BRO	SP	CCA		V	4/13/2045
2020 PO4755088831	LGE	4	30 BRN	SP	CRE	HH,ID	TD	4/14/2045
2020 PO4736688927	LGE	4	40 BRO	SP	CRE		B	4/15/2045
2020 PO4755388827	LGE	4	40 BRN	SP	CRE	ED,HH,ID,RB	X	PX 4/16/2045
2020 PO3827808390	KU	4	45 BRO	SP	P	ED	T	4/17/2045
2020 PO4819510752	KU	4	40 ACE	SP	CRE	ED,ID	BD	4/18/2045
2020 PO4819710496	KU	3	45 ACE	SP	CRE	ED,ID	BD	4/19/2045
2020 PO4824910474	KU	3	45 ACE	SP	P	ED	T	4/20/2045
2020 PO4830410709	KU	3	45 ACE	SP	CRE	ED,ID	TD	4/21/2045
2020 PO4830310613	KU	3	45 ACE	SP	CCA		V	4/22/2045
2020 PO4746500949	KU	3	40 BRN	SP	CRE	ED,ID	TD	4/23/2045
2020 PO4752201140	KU	4	40 BRN	SP	CRE	ED,ID,SRS	TD	4/24/2045
2020 PO2078221297	ODP	5	35 XXX	SP	CRE	ID	TD	4/25/2045
2020 PO2063021363	ODP	6	30 XXX	SP	CCA	ED	T	4/26/2045
2020 PO2079621149	ODP	4	40 XXX	SP	CCA		V	4/27/2045
2020 PO2078921096	ODP	6	30 XXX	SP	CCA		V	4/28/2045
2020 PO4707989051	LGE	4	40 BRO	SP	CCA		V	4/29/2045
2020 PO4706489058	LGE	4	40 BRO	SP	P	ED,ID	TD	4/30/2045
2020 PO4831410994	KU	4	40 ACE	SP	CRE	ED,ID	BD	5/1/2045
2020 PO4842810941	KU	3	45 ACE	SP	CCA		V	5/2/2045
2020 PO2082420546	F	4	40 XXX	SP	A		V	5/3/2045
2020 PO2087120744	F	4	40 XXX	SP	A		V	5/4/2045
2020 PO2091820942	F	4	40 XXX	SP	A		V	5/5/2045
2020 PO2101621098	ODP	4	40 XXX	SP	CCA		V	5/6/2045
2020 PO2118621064	F	4	40 XXX	SP	CRE		V	5/7/2045
2020 PO2137121211	ODP	4	45 XXX	SP	CRE	ID	BD	5/8/2045
2020 PO2181820895	ODP	4	40 XXX	SP	CRE	ID	TD	5/9/2045
2020 PO2152220972	ODP	4	40 XXX	SP	CRE	ID	TD	5/10/2045
2020 PO2173021794	ODP	4	45 XXX	SP	CRE	ID	BD	5/11/2045
2020 PO2152821356	ODP	4	45 XXX	SP	CCA		V	5/12/2045
2020 PO2236921771	ODP	4	45 XXX	SP	CRE	ID	TD	5/13/2045
2020 PO2258521755	ODP	4	45 XXX	SP	CRE	ID	TD	5/14/2045
2020 PO2241221857	ODP	4	45 XXX	SP	CRE	ID	TD	5/15/2045
2020 PO2208122414	ODP	4	45 XXX	SP	CCA		V	5/16/2045
2020 PO3795808659	KU	4	40 BRO	SP	CRE	ID,IP	BD	5/17/2045
2020 PO4729000471	KU	6	30 BRN	SP	CCA		V	5/18/2045
2020 PO4833511056	KU	4	40 ACE	SP	CRE	ED,ID	BD	5/19/2045

2020 PO4740300755	KU	4	40 BRN	SP	CRE	ED,ID	TD	5/20/2045
2020 PO4733400511	KU	2	50 BRN	SP	CCA		V	5/21/2045
2020 PO4826411015	KU	2	40 ACE	SP	CRE	ED,ID	TD	5/22/2045
2020 PO4756788841	LGE	4	40 BRN	SP	P	ED,ID	TD	5/23/2045
2020 PO4819911040	KU	5	35 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX PX	5/24/2045
2020 PO4755788847	LGE	4	40 BRN	SP	CRE	ED,ID,SRC	TX RR	5/25/2045
2020 PO4755188857	LGE	4	40 BRN	SP	S		V	5/26/2045
2020 PO4718589093	LGE	4	30 BRO	SP	CRE		V	5/27/2045
2020 PO4713289058	LGE	3	45 BRO	SP	P	ED,ID	TD	5/28/2045
2020 PO4713289073	LGE	4	40 BRO	SP	P	ED,ID	TD	5/29/2045
2020 PO4246603544	LGE	3	45 BRO	SP	CCA		V	5/30/2045
2020 PO4248303555	LGE	3	45 BRO	SP	CCA		V	5/31/2045
2020 PO4690888896	LGE	2	50 BRO	SP	CCA		V	6/1/2045
2020 PO4689288882	LGE	2	50 BRO	SP	CCA		V	6/2/2045
2020 PO4687488870	LGE	3	50 BRO	SP	CCA		V	6/3/2045
2020 PO4781911199	KU	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX PX	6/4/2045
2020 PO3931709429	KU	2	50 BRO	SP	CCA		V	6/5/2045
2020 PO4754988874	LGE	4	40 BRN	SP	S		V	6/6/2045
2020 PO4755988879	LGE	4	40 BRN	SP	S		V	6/7/2045
2020 PO4756988884	LGE	3	45 BRN	SP	S		V	6/8/2045
2020 PO4757788886	LGE	4	40 BRN	SP	S		V	6/9/2045
2020 PO4758388884	LGE	4	40 BRN	SP	CRE	ED,ID,SRC	TX RR	6/10/2045
2020 PO4760288843	LGE	4	40 BRN	SP	P	ED,ID	BD	6/11/2045
2020 PO4760888832	LGE	4	40 BRN	SP	CRE	ED,ID	BD	6/12/2045
2020 PO3934710086	KU	2	45 BRO	SP	CRE	ID	BD	6/13/2045
2020 PO3923610048	KU	3	45 BRO	SP	CRE	ID	BD	6/14/2045
2020 PO4761488821	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD	6/15/2045
2020 PO4709711923	KU	5	35 ACE	SP	CRE	ED,ID	TD	6/16/2045
2020 PO4719211869	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	6/17/2045
2020 PO3982208831	KU	3	45 BRO	SP	CRE	ID,IP	BD	6/18/2045
2020 PO3990708685	KU	3	45 BRO	SP	CRE	ID	BD	6/19/2045
2020 PO4761888812	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD	6/20/2045
2020 PO3973908974	KU	3	45 BRO	SP	CCA		V	6/21/2045
2020 PO4068583090	F	4	40 BRN	SP	CCA		V	6/22/2045
2020 PO4070983098	F	4	40 BRN	SP	CCA		V	6/23/2045
2020 PO4072483103	F	4	40 BRN	SP	CCA		V	6/24/2045
2020 PO4070283095	F	4	40 BRN	SP	CCA		V	6/25/2045
2020 PO4069783118	LGE	3	45 BRN	SP	CCA		V	6/26/2045
2020 PO4070383100	LGE	4	40 BRN	SP	P	ED,ID	TD	6/27/2045
2020 PO4070583122	LGE	4	40 BRN	SP	CCA		V	6/28/2045
2020 PO4072183113	LGE	4	30 BRN	SP	CCA		V	6/29/2045
2020 PO4072783110	LGE	4	30 BRN	SP	CCA		V	6/30/2045
2020 PO3837508940	KU	4	40 BRO	SP	CRE	ID,IP	BD	7/1/2045
2020 PO4911401483	KU	4	40 BRN	SP	CRE	ID	BD	7/2/2045
2020 PO3857308909	KU	4	40 BRO	SP	CRE	ID,IP	BD	7/3/2045
2020 PO3814708977	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	7/4/2045
2020 PO4767788723	LGE	4	40 BRN	SP	CRE	ED,ID	BD	7/5/2045

2020 PO4767788743	LGE	4	30 BRN	SP	CRE	ED,ID	BD	7/6/2045
2020 PO4766988739	LGE	4	40 BRN	SP	P	ED,ID	BD	7/7/2045
2020 PO4903801502	KU	4	40 BRN	SP	CRE	ID	BD	7/8/2045
2020 PO4699988939	LGE	4	40 BRO	SP	CCA		V	7/9/2045
2020 PO4766988753	LGE	4	30 BRN	SP	CRE	ED,ID	BD	7/10/2045
2020 PO4766488751	LGE	4	40 BRN	SP	P	ED,ID	BD	7/11/2045
2020 PO4702588902	LGE	4	40 BRO	SP	CRE	ED,HH,ID,RB	BX PX	7/12/2045
2020 PO4703488893	LGE	3	45 BRO	SP	CCA		V	7/13/2045
2020 PO4705588871	LGE	4	40 BRO	SP	CRE	ED,ID	BD	7/14/2045
2020 PO4707088855	LGE	4	40 BRO	SP	CRE	ED,ID	BD	7/15/2045
2020 PO4708188844	LGE	4	40 BRO	SP	CRE	ED,ID	BD	7/16/2045
2020 PO4766388765	LGE	4	30 BRN	SP	A	ED,ID	BD	7/17/2045
2020 PO4765888763	LGE	4	40 BRN	SP	CRE	ED,ID	BD	7/18/2045
2020 PO3896908268	KU	4	40 BRO	SP	CRE	ID,IP	BD	7/19/2045
2020 PO4074483083	F	4	40 BRN	SP	CCA		V	7/20/2045
2020 PO4075583094	F	4	40 BRN	SP	CCA		V	7/21/2045
2020 PO4074683110	F	4	40 BRN	SP	CCA		V	7/22/2045
2020 PO4074883134	LGE	3	40 BRN	SP	P	ED,ID	V	7/23/2045
2020 PO4074383128	LGE	4	30 BRN	SP	P	ED,ID	BD	7/24/2045
2020 PO4073583131	LGE	3	55 BRN	SP	A	ED,ID	BD	7/25/2045
2020 PO4072383136	LGE	4	40 BRN	SP	P	ED,ID	BD	7/26/2045
2020 PO4071983167	LGE	4	40 BRN	SP	P	ED,ID	BD	7/27/2045
2020 PO4070883153	LGE	4	40 BRN	SP	P	ED,ID	BD	7/28/2045
2020 PO4070883156	LGE	4	30 BRN	SP	P	ED,ID	BD	7/29/2045
2020 PO4070183149	LGE	4	30 BRN	SP	P	ED,ID	BD	7/30/2045
2020 PO4070083200	LGE	4	30 BRN	SP	CRE		V	7/31/2045
2020 PO4070283247	LGE	4	30 BRN	SP	CCA		V	8/1/2045
2020 PO4757500363	KU	4	35 BRN	SP	CRE	ED,ID	TD	8/2/2045
2020 PO4765988778	LGE	4	30 BRN	SP	CRE	ED,ID	BD	8/3/2045
2020 PO4765288775	LGE	4	40 BRN	SP	CCA		V	8/4/2045
2020 PO4843901061	KU	4	40 BRN	SP	CCA		V	8/5/2045
2020 PO4858300625	KU	6	30 BRN	SP	CRE	ED,ID,SRS	TD	8/6/2045
2020 PO4077083117	LGE	3	50 BRN	SP	A	ED,ID,IP	BD	8/7/2045
2020 PO9154682283	KU	4	40 BRN	SP	CRE	ED,ID	TD	8/8/2045
2020 PO5744745314	KU	6	30 ACE	SP	CRE	ED,ID	BD	8/9/2045
2020 PO5725445289	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD	8/10/2045
2020 PO5798945398	KU	4	40 ACE	SP	CRE	ED,ID	BD	8/11/2045
2020 PO5786045477	KU	4	45 ACE	SP	CCA		V	8/12/2045
2020 PO5795145417	KU	4	40 ACE	SP	CRE	ED,ID	BD	8/13/2045
2020 PO5733645456b	KU	6	30 ACE	SP	CCA		V	8/14/2045
2020 PO5797145320	KU	3	45 ACE	SP	CCA		V	8/15/2045
2020 PO5806845438	KU	4	40 ACE	SP	CRE	ED,ID	BD	8/16/2045
2020 PO5817145495	KU	4	40 ACE	SP	CRE	ED,ID	BD	8/17/2045
2020 PO5834645587	KU	4	45 ACE	SP	CRE	ED,ID	BD	8/18/2045
2020 PO4711788965	F	2	50 BRO	SP	CCA		V	8/19/2045
2020 PO4709588958	F	2	50 BRO	SP	CCA		V	8/20/2045
2020 PO4707888951	F	2	50 BRO	SP	CCA		V	8/21/2045

2020 PO4705988944	F	2	50 BRO	SP	CCA		V	8/22/2045	
2020 PO4711888965	LGE	4	40 BRO	SP	CRE	ED,ID	TD	8/23/2045	
2020 PO4712588966	F	3	45 BRO	SP	CRE		V	8/24/2045	
2020 PO4712588968	F	2	50 BRO	SP	CCA		V	8/25/2045	
2020 PO4714488977	LGE	3	50 BRO	SP	CCA		V	8/26/2045	
2020 PO4701311727	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	8/27/2045	
2020 PO4762488802	LGE	4	40 BRN	SP	A	ED,ID,IP	TD	8/28/2045	
2020 PO4711611708	KU	4	40 ACE	SP	CRE	ED,ID	BD	8/29/2045	
2020 PO4987102248	KU	2	40 BRO	SP	CRE	ED,ID	TD	8/30/2045	
2020 PO0959011076	F	4	40 UNK	SP	CRE		V	8/31/2045	
2020 PO1100111361	KU	5	35 UNK	SP	CRE	ED,ID	TD	9/1/2045	
2020 PO0989511247	KU	6	30 BRN	SP	CRE	ED,ID	TD	9/2/2045	
2020 PO0982411156	KU	5	35 BRN	SP	CRE	ED,ID	TD	9/3/2045	
2020 PO1008511052	KU	6	30 BRN	SP	CRE	ED,ID	TD	9/4/2045	
2020 PO3821357230	KU	4	40 BRN	SP	CRE	ID	TD	9/5/2045	
2020 PO1167034531	ODP	4	40 XXX	SP	CRE	ED,ID,IP,SRC	TX	RR	9/6/2045
2020 PO0684459856	KU	5	35 ACW	SP	CRE	ED,ID,IP	TD	9/7/2045	
2020 PO0679059956	KU	4	45 ACW	SP	CRE	ED,ID	TD	9/8/2045	
2020 PO1180834506	ODP	5	35 XXX	SP	CRE	ED,ID	TD	9/9/2045	
2020 PO3976083109	LGE	4	40 BRN	SP	CRE	ED,ID	TD	9/10/2045	
2020 PO3936483286	F	6	25 BRO	SP	CRE		V	9/11/2045	
2020 PO3935983295	F	4	40 BRO	SP	P		V	9/12/2045	
2020 PO3936183315	F	4	40 BRO	SP	CRE		V	9/13/2045	
2020 PO3935983285	F	3	45 BRO	SP	CCA		V	9/14/2045	
2020 PO3936583296	LGE	4	30 BRO	SP	P	ED,ID	TD	9/15/2045	
2020 PO6541644417	LGE	4	30 BRO	SP	CCA		V	9/16/2045	
2020 PO3935883272	F	4	40 BRO	SP	P		V	9/17/2045	
2020 PO3935883263	F	4	40 BRO	SP	P		V	9/18/2045	
2020 PO3936183269	LGE	4	40 BRO	SP	CCA		V	9/19/2045	
2020 PO3976083102	LGE	3	45 BRN	SP	S		V	9/20/2045	
2020 PO4053542719	KU	6	30 ACE	SP	CRE	ED,ID	TD	9/21/2045	
2020 PO3976383081	LGE	4	40 BRN	SP	CRE	ED,ID	TD	9/22/2045	
2020 PO3896982860	F	2	65 BRO	SP	A		V	9/23/2045	
2020 PO1119632886	ODP	4	40 BRN	SP	CRE	ID	BD	9/24/2045	
2020 PO3895882860	F	3	45 BRO	SP	A		V	9/25/2045	
2020 PO7915925753	KU	6	30 ACW	SP	CRE	ED,ID,SRS	TD	9/26/2045	
2020 PO7510293389	F	4	40 BRO	SP	CRE		V	9/27/2045	
2020 PO7522193549	F	3	45 BRO	SP	CRE		V	9/28/2045	
2020 PO7526893615	F	3	50 BRO	SP	CRE		V	9/29/2045	
2020 PO8135535431	KU	4	40 ACW	SP	CRE		V	9/30/2045	
2020 PO8133735123	KU	4	40 ACW	SP	CRE		V	10/1/2045	
2020 PO8131034834	KU	4	40 ACW	SP	CRE		V	10/2/2045	
2020 PO8139335986	KU	4	40 ACW	SP	CRE		V	10/3/2045	
2020 PO8137835716	KU	4	45 ACW	SP	CRE		V	10/4/2045	
2020 PO8140836109	KU	4	40 ACW	SP	CRE		V	10/5/2045	
2020 PO1116132810	ODP	4	40 BRN	SP	CRE		V	10/6/2045	
2020 PO7898125280	KU	6	30 ACW	SP	CRE		V	10/7/2045	

2020 PO7907425355	KU	3	45 ACW	SP	CCA		V		10/8/2045
2020 PO1112332805	ODP	4	40 BRN	SP	CCA		V		10/9/2045
2020 PO4065242618	KU	4	40 ACE	SP	CRE	ED,ID	BD		10/10/2045
2020 PO1173636156A	ODP	5	30 BRN	SP	CRE	ID	TD		10/11/2045
2020 PO3975183080	F	4	40 BRN	SP	CCA		V		10/12/2045
2020 PO3974083079	F	4	40 BRN	SP	CRE		V		10/13/2045
2020 7884625365A	KU	6	30 OTH	SP	CRE	ID	TD		10/14/2045
2020 PO7903025470	KU	3	35 OTH	SP	CRE	ID	TD		10/15/2045
2020 PO7894725458	KU	4	40 ACW	SP	CRE	ID	TD		10/16/2045
2020 PO4360701765	KU	5	30 BRO	SP	CRE	ED,ID,IP	TD		10/17/2045
2020 PO4359301982	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		10/18/2045
2020 PO4350401811	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		10/19/2045
2020 PO3899139725	F	4	40 ACE	SP	CRE		V		10/20/2045
2020 PO3918939714	F	4	40 ACE	SP	CRE		V		10/21/2045
2020 PO3935739603	KU	4	40 ACE	SP	CCA		V		10/22/2045
2020 PO3941539701	F	4	40 ACE	SP	CRE		V		10/23/2045
2020 PO3961239690	F	4	40 ACE	SP	CRE		V		10/24/2045
2020 PO3984839677	F	4	40 ACE	SP	CRE		V		10/25/2045
2020 PO4006339663	F	4	40 ACE	SP	CRE		V		10/26/2045
2020 PO4009140136	F	5	35 ACE	SP	CRE		V		10/27/2045
2020 PO4022039976	F	5	35 ACE	SP	CRE		V		10/28/2045
2020 PO4025739653	F	4	40 ACE	SP	CRE		V		10/29/2045
2020 PO0354647134	KU	4	40 BRO	SP	CRE	ID	BD		10/30/2045
2020 PO0437948395	KU	4	40 BRO	SP	CRE	HH,IP,RB	BX	PX	10/31/2045
2020 PO0175448309	F	4	40 BRO	SP	CRE		V		11/1/2045
2020 PO0355147458	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD		11/2/2045
2020 PO0747859467	KU	4	40 ACW	SP	CRE	ED,ID	TD		11/3/2045
2020 PO0727659655	KU	4	40 ACW	SP	CRE	ED,ID	TD		11/4/2045
2020 PO0731259333	KU	5	35 ACW	SP	CRE	ED,ID	TD		11/5/2045
2020 PO0737759560	KU	4	40 ACW	SP	CRE	ED,ID	TD		11/6/2045
2020 PO0722459670	KU	6	30 ACW	SP	CRE	ED,ID	TD		11/7/2045
2020 PO0773719473	KU	5	35 ESC	SP	CRE	ID	TD		11/8/2045
2020 PO0527217027	KU	5	35 OTH	SP	CRE	ID	TD		11/9/2045
2020 PO0736812865	KU	4	40 KOP	SP	CRE	ID	TD		11/10/2045
2020 PO0748913083	KU	6	30 OTH	SP	CRE	ID	TD		11/11/2045
2020 PO0735713110	KU	4	40 KOP	SP	CRE	ID	TD		11/12/2045
2020 PO0711412933	KU	4	45 OTH	SP	CRE	ID	TD		11/13/2045
2020 PO0671013322	KU	4	45 OTH	SP	CRE		V		11/14/2045
2020 PO0874320149	KU	4	40 BRN	SP	CCA		V		11/15/2045
2020 PO0684613128	KU	4	45 OTH	SP	CRE	ID	TD		11/16/2045
2020 PO0830520467	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD		11/17/2045
2020 PO0857820215	KU	3	45 BRN	SP	CCA		V		11/18/2045
2020 PO0649517668	KU	4	40 BRN	SP	S		V		11/19/2045
2020 PO0654517832	KU	4	40 BRN	SP	CCA		V		11/20/2045
2020 PO0854621174	KU	6	30 OTH	SP	CRE	ID	TD		11/21/2045
2020 PO0806019792	KU	5	35 UNK	SP	CRE	ID	TD		11/22/2045
2020 PO0669318029	KU	6	30 OTH	SP	CCA		V		11/23/2045

2020 PO0044716492	KU	5	35 BRN	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX	11/24/2045
2020 PO3994782876	F	4	40 BRN	SP	CCA		V		11/25/2045
2020 PO3884482628	LGE	4	45 BRO	SP	CRE	ED,ID	TD		11/26/2045
2020 PO3888682609	LGE	4	40 BRO	SP	CRE	ED,ID	BD		11/27/2045
2020 PO3888082612	LGE	4	45 BRO	SP	A	ED,ID	BD		11/28/2045
2020 PO3887182617	LGE	4	45 BRO	SP	CRE	ED,ID	TD		11/29/2045
2020 PO3886282620	LGE	3	45 BRO	SP	CCA		V		11/30/2045
2020 PO3871482677	LGE	4	45 BRO	SP	P	ED,ID	BD		12/1/2045
2020 PO3994982864	F	4	40 BRN	SP	CRE		V		12/2/2045
2020 PO3995082853	F	4	40 BRN	SP	CRE		V		12/3/2045
2020 PO3995182841	F	4	40 BRN	SP	CRE		V		12/4/2045
2020 PO3995282829	F	4	40 BRN	SP	CRE		V		12/5/2045
2020 PO3996282818	F	6	25 BRN	SP	CRE		V		12/6/2045
2020 PO3995482817	F	4	40 BRN	SP	CCA		V		12/7/2045
2020 PO3996382804	F	6	25 BRN	SP	CRE		V		12/8/2045
2020 PO3995482807	F	4	40 BRN	SP	CRE		V		12/9/2045
2020 PO3995282790	F	6	25 BRN	SP	CRE		V		12/10/2045
2020 PO3994782799	F	4	40 BRN	SP	CRE		V		12/11/2045
2020 PO2938735348	KU	4	35 BRN	SP	CRE	ID,IP	BD		12/12/2045
2020 PO3933482545	F	6	35 BRN	SP	CRE	ED,HH,ID	BX	RP2	12/13/2045
2020 PO3933182547	F	6	30 BRN	SP	CRE	ED,ID,RB	VX	PX	12/14/2045
2020 PO3932982555	F	3	45 BRN	SP	CCA		V		12/15/2045
2020 PO2726628166	ODP	6	30 BRO	SP	CCA		V		12/16/2045
2020 PO2756628300	F	4	40 BRO	SP	CRE		V		12/17/2045
2020 PO2786928397	ODP	4	45 BRO	SP	CCA		V		12/18/2045
2020 PO2815528502	ODP	4	40 BRO	SP	CCA		V		12/19/2045
2020 PO4823630208	KU	5	35 ACE	SP	CCA		V		12/20/2045
2020 PO4802230235	KU	3	45 ACE	SP	CCA		V		12/21/2045
2020 PO3985582799	LGE	6	25 BRN	SP	CRE		V		12/22/2045
2020 PO3986582800	F	4	40 BRN	SP	CCA		V		12/23/2045
2020 PO3986482812	F	4	40 BRN	SP	CRE		V		12/24/2045
2020 PO3986282833	F	4	40 BRN	SP	CCA		V		12/25/2045
2020 PO3986182835	F	4	40 BRN	SP	CRE		V		12/26/2045
2020 PO3985682872	F	4	40 BRN	SP	A		V		12/27/2045
2020 PO3985882859	F	4	40 BRN	SP	A		V		12/28/2045
2020 PO2956327423	ODP	4	40 BRO	SP	A		V		12/29/2045
2020 PO2939527536	ODP	4	40 BRO	SP	A	ID	TD		12/30/2045
2020 PO2881027992	F	4	40 BRO	SP	CRE		V		12/31/2045
2020 PO5827341317	KU	4	40 BRN	SP	CRE		V		1/1/2046
2020 PO5843041157	KU	4	40 BRN	SP	CRE	ED,ID	TD		1/2/2046
2020 PO5811141491	KU	4	45 BRN	SP	S		V		1/3/2046
2020 PO5889840674	KU	3	40 BRN	SP	S	ED,ID,MD	BD		1/4/2046
2020 PO5905840507	KU	4	40 BRN	SP	CRE	ED,ID	TD		1/5/2046
2020 PO5920340346	KU	4	40 BRN	SP	CRE	ID	BD		1/6/2046
2020 PO5860240999	KU	4	40 BRN	SP	CRE	ED,ID	TD		1/7/2046
2020 PO4046939641	F	4	40 ACE	SP	CRE		V		1/8/2046
2020 PO4067439630	F	4	40 ACE	SP	CRE		V		1/9/2046

2020 PO4084639621	F	4	40 ACE	SP	CRE		V			1/10/2046
2020 PO4102239610	F	4	40 ACE	SP	CRE		V			1/11/2046
2020 PO4119839598	F	4	40 ACE	SP	CRE		V			1/12/2046
2020 PO4101339459	F	4	40 ACE	SP	CRE	ED,ID,IP	V			1/13/2046
2020 PO4372301992	KU	3	40 BRO	SP	CRE	ED,ID,IP	TD			1/14/2046
2020 PO2272638904	KU	4	40 BRN	SP	CRE	ED,ID,IP,RB	TX		RR	1/15/2046
2020 PO3014727314	ODP	4	40 BRO	SP	CRE	ID	TD			1/16/2046
2020 PO3054427163	ODP	4	40 BRO	SP	CCA		V			1/17/2046
2020 PO3098027000	ODP	5	35 BRO	SP	CCA		V			1/18/2046
2020 PO2854428561	F	4	40 BRO	SP	CRE		V			1/19/2046
2020 PO3985283028	LGE	4	40 BRN	SP	CRE	ED,ID	TD			1/20/2046
2020 PO1231536445	ODP	6	30 BRN	SP	CRE	ED,ID	TD			1/21/2046
2020 PO1234036447	ODP	5	35 XXX	SP	CRE	ID	BX		RP1	1/22/2046
2020 PO1984036558	KU	4	40 BRO	SP	CRE	ED	TD			1/23/2046
2020 PO4722129954	KU	3	45 ACE	SP	CRE	ED,ID	BD			1/24/2046
2020 PO1253236628	ODP	4	40 XXX	SP	CRE	ID	BD			1/25/2046
2020 PO1044734328	ODP	4	45 KOP	SP	CRE	ID	BD			1/26/2046
2020 PO1030634350	ODP	4	45 KOP	SP	CRE	ED,ID	TD			1/27/2046
2020 PO1190136348	ODP	4	40 XXX	SP	A	ED,ID	TD			1/28/2046
2020 PO1990036915	KU	4	45 BRO	SP	CRE	ID	BD			1/29/2046
2020 PO3984383038	LGE	6	25 BRN	SP	CRE	ED,ID	TD			1/30/2046
2020 PO3985283039	LGE	4	40 BRN	SP	CRE	ED,ID	TD			1/31/2046
2020 PO4094639308	F	3	45 ACE	SP	P		V			2/1/2046
2020 PO1110236172	ODP	4	45 XXX	SP	CRE	ED,ID,IP,SRC	TX		RR	2/2/2046
2020 PO1106036229	F	4	40 BRN	SP	A		V			2/3/2046
2020 PO1093034258	ODP	2	55 KOP	SP	CRE	ED,ID	TD			2/4/2046
2020 PO1094134408	ODP	2	60 KOP	SP	CRE	ED,ID,MD	TD			2/5/2046
2020 10941-34408A	ODP	5	30 KOP	SP	A	ED,ID	TD			2/6/2046
2020 PO1113934220	ODP	5	35 KOP	SP	CRE	ED,ID	TD			2/7/2046
2020 PO3865182682	LGE	4	40 BRO	SP	P	ED,ID	TD			2/8/2046
2020 PO3866182699	LGE	3	40 BRO	SP	A	ED,ID	TD			2/9/2046
2020 PO3867982692	LGE	4	45 BRO	SP	P	ED,ID,IP	TD			2/10/2046
2020 PO1095236407	ODP	6	30 BRN	SP	CCA		V			2/11/2046
2020 PO1086536403	ODP	6	30 BRN	SP	CCA		V			2/12/2046
2020 PO1081036461	ODP	6	30 BRN	SP	S	ED	T			2/13/2046
2020 PO1087436463	ODP	6	30 BRN	SP	CRE		V			2/14/2046
2020 PO1094336467	ODP	6	30 BRN	SP	CRE	ED,ID	TD			2/15/2046
2020 PO1097636471	ODP	6	30 BRN	SP	CRE	ED,ID,IP	TD			2/16/2046
2020 PO1101236474	ODP	6	30 BRN	SP	CRE	ED,ID	TD			2/17/2046
2020 PO1106536477	ODP	6	30 BRN	SP	CRE	ED,ID	TD			2/18/2046
2020 PO4171240537	KU	5	35 ACE	SP	CCA	ED	T			2/19/2046
2020 PO4218640474	F	4	40 ACE	SP	CCA		V			2/20/2046
2020 PO4206840181	F	4	40 ACE	SP	CCA		V			2/21/2046
2020 PO4229240720	F	4	40 ACE	SP	CCA		V			2/22/2046
2020 PO4237040907	F	4	40 ACE	SP	P		V			2/23/2046
2020 PO3206750382	KU	3	45 ACE	SP	CCA		V			2/24/2046
2020 PO3199050193	F	4	40 ACE	SP	CRE		V			2/25/2046

2020 PO4326102848	KU	4	45 BRO	SP	CRE	ED,ID	TD	2/26/2046
2020 PO2509972517	KU	3	45 BRO	SP	CCA		V	2/27/2046
2020 PO4425603284	F	4	40 BRO	SP	CRE		V	2/28/2046
2020 PO0964132512	ODP	4	40 XXX	SP	CRE	ID,RB	BX PX	3/1/2046
2020 PO3991782632	F	3	45 BRN	SP	S		V	3/2/2046
2020 PO3918382957	F	4	40 BRO	SP	P		V	3/3/2046
2020 PO3918782966	F	3	45 BRO	SP	CCA		V	3/4/2046
2020 PO3918982981	F	4	40 BRO	SP	A		V	3/5/2046
2020 PO3991882623	F	4	40 BRN	SP	CRE		V	3/6/2046
2020 PO3992182602	F	4	45 BRN	SP	CRE		V	3/7/2046
2020 PO0914433477	ODP	4	45 BRN	SP	CCA		V	3/8/2046
2020 PO3919282995	F	4	40 BRO	SP	A		V	3/9/2046
2020 PO3898382897	LGE	5	80 BRO	SP	A		V	3/10/2046
2020 PO3990782601	F	4	40 BRN	SP	A		V	3/11/2046
2020 PO3989582600	F	4	40 BRN	SP	CCA		V	3/12/2046
2020 PO3919783020	F	4	40 BRO	SP	CCA		V	3/13/2046
2020 PO3919483006	F	4	40 BRO	SP	A		V	3/14/2046
2020 PO6385841823A	F	4	40 BRO	SP	A		V	3/15/2046
2020 PO3920083038A	F	4	40 BRO	SP	A		V	3/16/2046
2020 PO6385841823	LGE	4	30 BRO	SP	CCA		V	3/17/2046
2020 PO3920083038	F	4	40 BRO	SP	P		V	3/18/2046
2020 PO5860346749	F	3	40 ACE	SP	CCA		V	3/19/2046
2020 PO5858546620	F	4	40 ACE	SP	CCA		V	3/20/2046
2020 PO5835046628	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	3/21/2046
2020 PO9606094581	KU	6	30 ACW	SP	S		V	3/22/2046
2020 PO9594094581	KU	6	30 ACW	SP	S		V	3/23/2046
2020 PO9603394657	KU	4	40 ACW	SP	CRE		V	3/24/2046
2020 PO9595194643	KU	3	45 ACW	SP	S		V	3/25/2046
2020 PO9586394623	KU	5	30 ACW	SP	CRE		V	3/26/2046
2020 PO9575194603	C	6	35 ACW	SP	CRE		V	3/27/2046
2020 PO9595194643A	KU	5	35 ACW	SP	CRE	ED,ID	TD	3/28/2046
2020 PO9543594929	C	6	35 ACW	SP	CRE		V	3/29/2046
2020 PO9538894927	KU	6	30 ACW	SP	CRE	ED,ID	BD	3/30/2046
2020 PO9518294407	C	4	40 ACW	SP	CRE		V	3/31/2046
2020 PO9523594449	KU	4	40 ACW	SP	CRE	ED,ID	BD	4/1/2046
2020 PO9517594446	C	5	35 ACW	SP	CRE		V	4/2/2046
2020 PO9496294577	F	5	40 ACW	SP	P		V	4/3/2046
2020 PO3920283049	F	4	40 BRO	SP	P		V	4/4/2046
2020 PO6392342214	LGE	4	30 BRO	SP	CCA		V	4/5/2046
2020 PO3920483061	F	4	40 BRO	SP	A	ED,ID,RB	VX RP1	4/6/2046
2020 PO3919983074	F	5	25 BRO	SP	P		V	4/7/2046
2020 PO3920583073	F	4	40 BRO	SP	CCA		V	4/8/2046
2020 PO3920683087	F	5	25 BRO	SP	P		V	4/9/2046
2020 PO3920783078	F	4	40 BRO	SP	P		V	4/10/2046
2020 PO3921683086	F	5	25 BRO	SP	CCA		V	4/11/2046
2020 PO3921283076	F	4	40 BRO	SP	CCA		V	4/12/2046
2020 PO0930433464	ODP	5	30 BRN	SP	CRE	ED,ID	TD	4/13/2046

Business Use

2020 PO1829640897	ODP	6	30 KOP	SP	CRE	ED,ID	TD		4/14/2046
2020 PO1831540852	ODP	6	30 KOP	SP	CRE	ED,ID,IP	TD		4/15/2046
2020 PO3987982603	LGE	6	25 BRN	SP	A	ED,ID	TD		4/16/2046
2020 PO3987982599	LGE	3	50 BRN	SP	A	ED,ID	BD		4/17/2046
2020 PO1110234731	F	4	40 XXX	SP	CRE		V		4/18/2046
2020 PO1106934689	ODP	6	30 XXX	SP	CRE		V		4/19/2046
2020 PO3987882587	LGE	4	40 BRN	SP	A	ED,ID	TD		4/20/2046
2020 PO1218834601	ODP	5	35 XXX	SP	CRE	ED,ID,RB	X	RP1	4/21/2046
2020 PO5655106237	KU	5	35 KOP	SP	CRE		V		4/22/2046
2020 PO5302306614	KU	6	30 KOP	SP	CCA		V		4/23/2046
2020 PO5381307903	KU	3	35 XXX	SP	CRE	ID	BD		4/24/2046
2020 PO5389007688	KU	4	40 XXX	SP	CRE	ID	BD		4/25/2046
2020 PO5452707379b	KU	5	30 XXX	SP	CRE	ED,ID	TD		4/26/2046
2020 PO5452707379a	KU	5	30 XXX	SP	CRE	ID	BD		4/27/2046
2020 PO5481007194	KU	6	30 BRN	SP	CRE		V		4/28/2046
2020 PO7217690532	KU	4	35 BRO	SP	CRE	ED,ID	BD		4/29/2046
2020 PO7222090556	F	3	45 BRO	SP	CRE		V		4/30/2046
2020 PO7197790672	KU	5	35 BRO	SP	CRE	ED,ID	TD		5/1/2046
2020 PO7204490625	KU	4	40 BRO	SP	CRE	ED,ID	BD		5/2/2046
2020 PO7194890559	KU	4	40 BRO	SP	CRE	ED	TD		5/3/2046
2020 PO7026394028	KU	4	40 BRN	SP	CRE	ED,ID	BD		5/4/2046
2020 PO7015793892	KU	4	40 BRN	SP	CRE	ED,ID	TD		5/5/2046
2020 PO3927483048	F	4	40 BRO	SP	CRE		V		5/6/2046
2020 PO3928083070	F	4	40 BRO	SP	A		V		5/7/2046
2020 PO3989682761	F	3	45 BRN	SP	CRE		V		5/8/2046
2020 PO3988682760	F	3	45 BRN	SP	CCA		V		5/9/2046
2020 PO1220433829	ODP	4	40 XXX	SP	CRE	ED,ID,SRC	TX	RR	5/10/2046
2020 PO2651223300	F	4	40 BRN	SP	A		V		5/11/2046
2020 PO2634323062	ODP	4	40 BRN	SP	A	ID	TD		5/12/2046
2020 PO2609222745	ODP	4	40 BRN	SP	CRE	ID	TD		5/13/2046
2020 PO2592222528	F	4	40 BRN	SP	A		V		5/14/2046
2020 PO2573522450	F	4	40 BRN	SP	A		V		5/15/2046
2020 PO0027637602	ODP	5	35 XXX	SP	CRE	ID	BD		5/16/2046
2020 PO3979082377	F	4	40 BRN	SP	A		V		5/17/2046
2020 PO3978382365	F	4	40 BRN	SP	A		V		5/18/2046
2020 PO4968830283	KU	3	45 BRO	SP	CCA		V		5/19/2046
2020 PO4979130283	KU	3	45 BRO	SP	CCA		V		5/20/2046
2020 PO9642293499	KU	2	45 ACW	SP	CRE	ED,ID	BD		5/21/2046
2020 PO9655193488	KU	2	45 ACW	SP	CRE	ED,ID,IP	TD		5/22/2046
2020 PO9650593493	KU	2	45 ACW	SP	CRE	ED,ID,IP,MD,SRC	TX	RR	5/23/2046
2020 PO9690695344	KU	6	35 ACW	SP	S		V		5/24/2046
2020 PO9719195160	KU	4	40 ACW	SP	CRE	ED,ID	TD		5/25/2046
2020 PO9683095361	C	5	35 ACW	SP	S		V		5/26/2046
2020 PO9682295291	KU	6	30 ACW	SP	S		V		5/27/2046
2020 PO9678795278	KU	4	40 ACW	SP	CCA		V		5/28/2046
2020 PO9685495299	C	6	30 ACW	SP	CRE		V		5/29/2046
2020 PO5956447148	KU	3	45 ACE	SP	CRE	ED,ID,IP	BD		5/30/2046

2020 PO5974547065	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	5/31/2046
2020 PO5974746991	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD	6/1/2046
2020 PO5990246866	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	6/2/2046
2020 PO6002646765	KU	4	45 ACE	SP	CRE	ED,ID	BD	6/3/2046
2020 PO3854129123	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	6/4/2046
2020 PO3885429159	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	6/5/2046
2020 PO3916829193	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	6/6/2046
2020 PO3948129225	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	6/7/2046
2020 PO3977682352	F	4	40 BRN	SP	CRE		V	6/8/2046
2020 PO3977082342	F	3	45 BRN	SP	CRE		V	6/9/2046
2020 PO3976182326	F	3	45 BRN	SP	S		V	6/10/2046
2020 PO3975582314	F	4	40 BRN	SP	CRE		V	6/11/2046
2020 PO3974882301	F	4	40 BRN	SP	S		V	6/12/2046
2020 PO3974582294	LGE	4	40 BRN	SP	A	ED,ID	BD	6/13/2046
2020 PO3974682296	F	4	40 BRN	SP	S		V	6/14/2046
2020 PO4558731153	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	6/15/2046
2020 PO3978429257	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	6/16/2046
2020 PO3982229516	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	6/17/2046
2020 PO4527730971	KU	6	30 ACE	SP	CCA		V	6/18/2046
2020 PO3986129799	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/19/2046
2020 PO4535131293	KU	6	30 ACE	SP	CCA		V	6/20/2046
2020 PO1287420210	ODP	6	30 BRN	SP	CRE	ID	TD	6/21/2046
2020 PO2054828659	ODP	4	40 BRN	SP	A		B	6/22/2046
2020 PO2046228719	ODP	2	45 BRN	SP	CCA		V	6/23/2046
2020 PO2059428835	F	4	40 BRN	SP	CRE		V	6/24/2046
2020 PO2050928945	F	4	40 BRN	SP	CRE		V	6/25/2046
2020 PO2032629250	F	4	40 BRN	SP	CRE		V	6/26/2046
2020 PO2041429102	F	4	40 BRN	SP	CRE		V	6/27/2046
2020 PO2069128911	ODP	4	40 BRN	SP	CRE	ID	BD	6/28/2046
2020 PO2080728756a	ODP	3	35 BRN	SP	CRE	ID	TD	6/29/2046
2020 PO2080728756	ODP	4	40 BRN	SP	A	ID	TD	6/30/2046
2020 PO2077428883	ODP	4	40 BRN	SP	A		V	7/1/2046
2020 PO0614737081	ODP	4	40 ACW	SP	CRE		V	7/2/2046
2020 PO4597331866	KU	3	45 ACE	SP	CRE	ED,ID	TD	7/3/2046
2020 PO4580931495	KU	3	45 ACE	SP	CRE	ED,ID	TD	7/4/2046
2020 PO0564937197	ODP	2	40 ACW	SP	CRE	ED,ID	TD	7/5/2046
2020 PO0564937197a	ODP	2	40 ACW	SP	CRE	ED,ID	TD	7/6/2046
2020 PO0568737048	ODP	5	35 BRN	SP	CRE	ED,ID	TD	7/7/2046
2020 PO0563537489	ODP	4	40 BRN	SP	CCA		V	7/8/2046
2020 PO0565337342	ODP	4	40 BRN	SP	CCA		V	7/9/2046
2020 PO0541837240	ODP	5	35 BRN	SP	CRE	ED,ID	TD	7/10/2046
2020 PO0505137067	ODP	4	40 BRN	SP	CCA		V	7/11/2046
2020 PO0507236973	ODP	6	30 BRN	SP	CCA		V	7/12/2046
2020 PO0520136916	ODP	5	35 BRN	SP	CRE	ED,ID	TD	7/13/2046
2020 PO0539736868	ODP	3	50 BRN	SP	CCA		V	7/14/2046
2020 PO0561836662a	ODP	5	30 BRN	SP	CCA	ED	T	7/15/2046
2020 PO0561836662	ODP	4	45 BRN	SP	CCA		V	7/16/2046

2020 PO0562136453	ODP	4	40 BRN	SP	CCA		V	7/17/2046
2020 PO3953482567	LGE	4	25 BRN	SP	A	ED,ID	TD	7/18/2046
2020 PO4533530031	KU	2	50 ACE	SP	CRE	ID	BD	7/19/2046
2020 PO4559129834	KU	1	60 ACE	SP	CRE	ED,ID	BD	7/20/2046
2020 PO4554029862	KU	3	45 ACE	SP	CRE	ED,ID	TD	7/21/2046
2020 PO3950182589	LGE	4	40 BRN	SP	CCA	ED,ID	BD	7/22/2046
2020 PO2197844150	ODP	4	45 KOP	DF	CRE	ED,ID,IP	TD	7/23/2046
2020 PO3949982582	LGE	4	40 BRN	SP	P	ED,ID	TD	7/24/2046
2020 PO3953382564	F	4	40 BRN	SP	A		V	7/25/2046
2020 PO3951582573	F	4	40 BRN	SP	CRE		V	7/26/2046
2020 PO2745236954	ODP	6	30 UNK	SP	CRE	ED,ID	TD	7/27/2046
2020 PO2756836855	ODP	6	30 UNK	SP	CRE	ED,ID,SRC	TD	7/28/2046
2020 PO2745336768	ODP	6	30 UNK	SP	CRE	ED,ID,SRS	TD	7/29/2046
2020 PO2735036838	ODP	5	30 UNK	SP	CRE	ED,ID	TD	7/30/2046
2020 PO2725336744	ODP	5	35 UNK	SP	CRE	ED,ID	TD	7/31/2046
2020 PO2725336577	ODP	4	40 BRN	SP	CRE	ED,ID	TD	8/1/2046
2020 PO2848648602	ODP	4	40 KOP	SP	CRE	ED,ID	TD	8/2/2046
2020 PO2868449036	ODP	4	40 KOP	SP	CRE	ED,ID	TD	8/3/2046
2020 PO2839348800	ODP	5	35 KOP	SP	CRE	ED,ID	TD	8/4/2046
2020 PO2806948672	ODP	4	40 KOP	SP	CRE	ED,ID	TD	8/5/2046
2020 PO2799548703	ODP	6	30 KOP	SP	S		V	8/6/2046
2020 PO2909048735	ODP	5	35E KOP	SP	CRE	ED,ID	TD	8/7/2046
2020 PO4682336967	KU	2	55 ACE	SP	CCA		V	8/8/2046
2020 PO4693036877	KU	2	55 ACE	SP	CCA		V	8/9/2046
2020 PO4705036776	KU	2	55 ACE	SP	CCA		V	8/10/2046
2020 PO4717736668	KU	2	55 ACE	SP	CCA		V	8/11/2046
2020 PO4729736567	KU	2	55 ACE	SP	CCA		V	8/12/2046
2020 PO4715429817	KU	5	35 ACE	SP	CCA		V	8/13/2046
2020 PO4810130116	KU	6	35 ACE	SP	CRE	ID,IP	BD	8/14/2046
2020 PO4807030000	KU	5	35 ACE	SP	CCA		V	8/15/2046
2020 PO4718329841	KU	3	45 ACE	SP	CRE	ID,IP	BD	8/16/2046
2020 PO4704330099	KU	2	45 ACE	SP	CRE	ID	BD	8/17/2046
2020 PO1467821484	F	5	40 XXX	SP	A		V	8/18/2046
2020 PO1470521360	ODP	4	40 XXX	SP	CRE	ED,ID	TD	8/19/2046
2020 PO1428621524	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD	8/20/2046
2020 PO1434021540	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD	8/21/2046
2020 PO1438621581	ODP	5	35 XXX	SP	CRE	ED,ID	TD	8/22/2046
2020 PO1447221554	ODP	6	30 BRN	SP	CCA	ED	TD	8/23/2046
2020 PO1444021626	ODP	4	45 BRN	SP	CCA	ED	T	8/24/2046
2020 PO1433921735	ODP	5	35 XXX	SP	CRE	ED,ID	TD	8/25/2046
2020 PO2864848500	ODP	4	40 KOP	SP	CRE	ED,ID	TD	8/26/2046
2020 PO2909048735	ODP	5	35 KOP	SP	CRE	ID	BD	8/27/2046
2020 PO2886648905	ODP	4	40 KOP	SP	CRE	ID	BD	8/28/2046
2020 PO2890548779	ODP	5	35 KOP	SP	CRE	ED,ID	TD	8/29/2046
2020 PO4715329749	KU	3	45 ACE	SP	CRE	ID,IP	BD	8/30/2046
2020 PO4706529483	KU	3	45 ACE	SP	CRE	ID,IP	BD	8/31/2046
2020 PO4712129653	KU	3	45 ACE	SP	CRE	ID,IP	BD	9/1/2046

2020 PO1451621688	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD	9/2/2046
2020 PO1460921761	ODP	4	45 BRN	SP	CCA		T	9/3/2046
2020 PO1453321885	ODP	4	40 XXX	SP	CRE	ED,ID	TD	9/4/2046
2020 PO2886348235	ODP	4	40 KOP	DF	CRE	ED,ID,IP	TD	9/5/2046
2020 PO2875347938	ODP	4	40 KOP	DF	CRE	ED,ID	TD	9/6/2046
2020 PO2935347940	ODP	4	40 KOP	SP	CRE	ED,ID	TD	9/7/2046
2020 PO2893348388	ODP	6	30 KOP	SP	CCA	ED,ID	TD	9/8/2046
2020 PO1437021318	F	4	40 XXX	SP	CRE		V	9/9/2046
2020 PO1447521266	ODP	4	40 XXX	SP	CRE	ED,ID	TD	9/10/2046
2020 PO4740536476	KU	2	55 ACE	SP	CCA		V	9/11/2046
2020 PO4742936474	KU	1	60 ACE	SP	CCA		V	9/12/2046
2020 PO4528535739	KU	4	40 ACE	SP	CCA		V	9/13/2046
2020 PO4528735799	KU	4	40 ACE	SP	CCA		V	9/14/2046
2020 PO4795236017	KU	3	45 ACE	SP	CCA		V	9/15/2046
2020 PO4787835934	KU	3	45 ACE	SP	CRE	ED,ID,IP	BD	9/16/2046
2020 PO4828435952	KU	1	60 ACE	SP	CCA		V	9/17/2046
2020 PO4713036856	F	1	20 ACE	SP	CCA		V	9/18/2046
2020 PO1419521267	F	4	40 XXX	SP	CRE		V	9/19/2046
2020 PO1422921182	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD	9/20/2046
2020 PO4688930067	KU	3	45 BRN	SP	CRE	ID	BD	9/21/2046
2020 PO4673330014	KU	3	40 BRN	SP	CRE	ID	BD	9/22/2046
2020 PO1422921182a	ODP	6	30 XXX	SP	CRE	ED,ID	TD	9/23/2046
2020 PO1439820942	ODP	4	40 BRN	SP	CCA	ED	T	9/24/2046
2020 PO1408720872	ODP	4	40 XXX	SP	CRE	ED,ID	TD	9/25/2046
2020 PO1398221076	ODP	4	40 XXX	SP	CCA		V	9/26/2046
2020 PO1393521289	ODP	4	40 XXX	SP	CRE	ED,ID	TD	9/27/2046
2020 PO4664029977	KU	3	45 BRN	SP	CRE	ID,IP	BD	9/28/2046
2020 PO2096328101	ODP	4	40 BRN	SP	CRE		V	9/29/2046
2020 PO1381221168	F	4	40 XXX	SP	A		V	9/30/2046
2020 PO1350421229	ODP	5	35 BRN	SP	CCA	ED	T	10/1/2046
2020 PO4763236478	KU	2	55 ACE	SP	CCA		V	10/2/2046
2020 PO3949482905	LGE	4	40 BRO	SP	P	ED,ID	TD	10/3/2046
2020 PO3948882909	LGE	4	30 BRO	SP	CRE	ED,ID	TD	10/4/2046
2020 PO3958783046	LGE	4	45 BRO	SP	CRE	ED,ID	BD	10/5/2046
2020 PO2168232920	ODP	6	30 BRN	SP	CRE	ED,ID,SRC	TD	10/6/2046
2020 PO3958083049	LGE	4	30 BRO	SP	P	ED,ID	TD	10/7/2046
2020 PO3959283054	LGE	4	40 BRO	SP	CCA		BD	10/8/2046
2020 PO3959783061	LGE	4	40 BRO	SP	CCA		V	10/9/2046
2020 PO3960783076	LGE	4	50 BRO	SP	CRE	HH,ID	TD	10/10/2046
2020 PO3961783091	LGE	4	50 BRO	SP	CRE	ED,ID	TD	10/11/2046
2020 PO1521319103	F	4	40 XXX	SP	CCA		V	10/12/2046
2020 PO2155933123	ODP	4	40 BRN	SP	CRE	ID	TD	10/13/2046
2020 PO2168433302	ODP	4	40 BRN	SP	CRE	ID	TD	10/14/2046
2020 PO2180733209	ODP	5	30 BRN	SP	CRE	ED,ID,SRC	TD	10/15/2046
2020 PO1465419105	F	5	40 XXX	SP	CRE	ED	V	10/16/2046
2020 PO1502619175	F	5	40 XXX	SP	CRE		V	10/17/2046
2020 PO1480719138	F	4	40 XXX	SP	P		V	10/18/2046

2020 PO1451219078	F	4	40 XXX	SP	CRE		V		10/19/2046
2020 PO3976082775	F	4	30 BRN	SP	CCA		V		10/20/2046
2020 PO3968982732	F	3	50 BRN	SP	S		V		10/21/2046
2020 PO3971282735	F	3	50 BRN	SP	S		V		10/22/2046
2020 PO6932639025	LGE	3	50 BRN	SP	CCA		V		10/23/2046
2020 PO1565919510	F	4	40 XXX	SP	CCA		V		10/24/2046
2020 PO1551419587	F	5	40 XXX	SP	CRE	ED	V		10/25/2046
2020 PO1537819558	F	5	35 XXX	SP	CRE	ED,ID	V		10/26/2046
2020 PO1521019520	F	4	45 XXX	SP	CCA		V		10/27/2046
2020 PO3959182710	LGE	4	30 BRN	SP	A	ED,ID	TD		10/28/2046
2020 PO3959982727	F	4	40 BRN	SP	CCA		V		10/29/2046
2020 PO3960982713-B	LGE	7	25 BRN	SP	CCA		V		10/30/2046
2020 PO3960982713-A	LGE	4	35 BRN	SP	A	ED,ID	TD		10/31/2046
2020 PO3960982713	LGE	4	45 BRN	SP	A	ED,ID	BD		11/1/2046
2020 PO3960182713	F	3	45 BRN	SP	CCA		V		11/2/2046
2020 PO1496019559	ODP	6	30 XXX	SP	CRE	ED,ID	TD		11/3/2046
2020 PO1505319481	F	4	40 XXX	SP	CRE		V		11/4/2046
2020 PO1493719452	F	5	40 XXX	SP	CRE	ED,ID	V		11/5/2046
2020 PO1481219409	F	4	40 XXX	SP	A		V		11/6/2046
2020 PO1480519503	ODP	6	30 XXX	SP	CRE	ID	TD		11/7/2046
2020 PO1667319182	ODP	4	40 XXX	SP	CRE	ID	TD		11/8/2046
2020 PO1674619316	ODP	4	45 XXX	SP	CCA	ED	TD		11/9/2046
2020 PO1146028689	ODP	4	45 BRN	SP	CCA		V		11/10/2046
2020 PO3966083139	LGE	3	45 BRO	SP	P	ED,ID	TD		11/11/2046
2020 PO1667822294	ODP	4	40 XXX	SP	CCA		V		11/12/2046
2020 PO2165630813	ODP	4	45 BRN	SP	CCA		V		11/13/2046
2020 PO1653622259	F	4	40 XXX	SP	P		V		11/14/2046
2020 PO1644822226	ODP	4	40 XXX	SP	CCA		V		11/15/2046
2020 PO1668722173	ODP	4	40 XXX	SP	CRE	ID	BD		11/16/2046
2020 PO1605322032	ODP	4	40 XXX	SP	CRE	ED,SRC	TD		11/17/2046
2020 PO1614721816	ODP	5	35 XXX	SP	CRE	ID	TD		11/18/2046
2020 PO1657221409	ODP	5	35 XXX	SP	CRE	ED,EP,ID,IP	TX	RR	11/19/2046
2020 PO2153330354	ODP	4	40 UNK	SP	CRE	ED,ID,SRS	X	PX	11/20/2046
2020 PO3959683043	F	3	30 BRO	SP	CCA		V		11/21/2046
2020 PO1662821612	ODP	4	45 XXX	SP	CRE	ID	BD		11/22/2046
2020 PO1667421585	ODP	4	45 XXX	SP	CRE	ID	TD		11/23/2046
2020 PO3952982941	LGE	4	40 BRO	SP	CCA	ED,ID	BD		11/24/2046
2020 PO3953982902	LGE	3	45 BRO	SP	CCA		V		11/25/2046
2020 PO3951682915	LGE	3	45 BRO	SP	CCA		V		11/26/2046
2020 PO6729440936	LGE	4	40 BRO	SP	CCA		V		11/27/2046
2020 PO3954882929	LGE	3	45 BRO	SP	A	ED,ID	BD		11/28/2046
2020 PO3954682930	LGE	4	40 BRO	SP	A	ED,ID	TD		11/29/2046
2020 PO3969583174	F	4	35 BRO	SP	CRE		V		11/30/2046
2020 PO2141029924	ODP	4	40 UNK	SP	CRE	ID	TD		12/1/2046
2020 PO2147230156	ODP	4	40 UNK	SP	CRE	ID	TD		12/2/2046
2020 PO2132430405	ODP	5	35 UNK	SP	CRE	ED,ID,SRS	TD		12/3/2046
2020 PO2104430455	F	3	45 UNK	SP	CRE		V		12/4/2046

2020 PO9466593365	KU	4	40 ACW	SP	CRE	ED,ID	TD	12/5/2046	
2020 PO9485493390	KU	4	45 ACW	DF	CRE	ED,ID,IP	TD	12/6/2046	
2020 PO9509893414	KU	4	40 ACW	SP	CRE	ED,ID	BD	12/7/2046	
2020 PO9534893375	KU	6	30 ACW	SP	CRE	ED,ID	TD	12/8/2046	
2020 PO2098930607	F	2	45 UNK	SP	CRE		V	12/9/2046	
2020 PO9533893437	KU	4	40 ACW	SP	CRE	ED,ID	TD	12/10/2046	
2020 PO2097230804	F	2	50 UNK	SP	CRE		V	12/11/2046	
2020 PO2095231170	ODP	4	40 UNK	SP	CRE	ED,ID	TD	12/12/2046	
2020 PO2095231170A	ODP	4	40 UNK	SP	CRE	ED,ID	TD	12/13/2046	
2020 PO2109831497	ODP	4	40 UNK	SP	CRE	ID	BD	12/14/2046	
2020 PO2126632111	ODP	4	40 UNK	SP	CRE	ID	TD	12/15/2046	
2020 PO3970783163	LGE	4	35 BRO	SP	CCA		V	12/16/2046	
2020 PO3972883141	LGE	UNK	100 BRO	SP	CRE		V	12/17/2046	
2020 PO1700722028	ODP	3	45 XXX	SP	CCA		V	12/18/2046	
2020 PO1687621997	ODP	4	40 XXX	SP	CRE	ID	TD	12/19/2046	
2020 PO1665221944	ODP	2	55 XXX	SP	CCA		V	12/20/2046	
2020 PO1532221942	ODP	3	50 XXX	SP	CRE		V	12/21/2046	
2020 PO1543121794	ODP	3	50 XXX	SP	CCA		V	12/22/2046	
2020 PO1532321810	ODP	3	45 XXX	SP	CCA		V	12/23/2046	
2020 PO1339828840	ODP	4	45 BRN	SP	CRE	ED,ID	TX	RR	12/24/2046
2020 PO6924743663	LGE	4	35 BRO	SP	CCA		V	12/25/2046	
2020 PO3972783207	LGE	4	35 BRO	SP	CCA		V	12/26/2046	
2020 PO9552593453	KU	4	40 ACW	SP	CRE	ED,ID	TD	12/27/2046	
2020 PO9568293455	KU	4	40 ACW	SP	CRE	ED,ID	TD	12/28/2046	
2020 PO9577993455	KU	4	40 ACW	SP	CRE	ED,ID,MD,SRC	TX	RR	12/29/2046
2020 PO9578193287	KU	4	40 ACW	SP	CRE	ED,ID,IP	BD	12/30/2046	
2020 PO9517793777	KU	4	40 ACW	SP	CRE	ED,ID	TD	12/31/2046	
2020 PO9532393807	KU	6	30 ACW	SP	CRE	ED,ID	TD	1/1/2047	
2020 PO5162836981	C	4	40 BRO	ST	P		V	1/2/2047	
2020 PO4812521476	KU	4	40 BRO	SP	CRE	ED,ID	TD	1/3/2047	
2020 PO4805221521	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	1/4/2047	
2020 PO9542593647	KU	4	40 ACW	DF	CRE	ED,ID,IP	TD	1/5/2047	
2020 PO9563493684	KU	4	45 ACW	SP	CRE	ED,ID	TD	1/6/2047	
2020 PO9577693600	KU	6	30 ACW	SP	CRE	ED,ID	BD	1/7/2047	
2020 PO9577393710	KU	4	40 ACW	SP	CRE	ED,ID	TD	1/8/2047	
2020 PO9592193625	KU	5	35 ACW	SP	CRE		V	1/9/2047	
2020 PO9594093747	KU	4	40 ACW	SP	CRE		V	1/10/2047	
2020 PO3971283187	LGE	4	35 BRO	SP	CCA		V	1/11/2047	
2020 PO3970583202	LGE	4	45 BRO	SP	CRE		V	1/12/2047	
2020 PO3972283179	LGE	4	35 BRO	SP	CCA		V	1/13/2047	
2020 PO1355829522	ODP	5	35 BRN	SP	CRE	ID,IP	TD	1/14/2047	
2020 PO3963783106	LGE	2	55 BRO	SP	CCA		V	1/15/2047	
2020 PO3963683092	LGE	3	50 BRO	SP	CRE	ED,ID	TD	1/16/2047	
2020 PO39363783106-A	LGE	5	30 BRO	SP	CRE	ED,ID	TD	1/17/2047	
2020 PO1507821739	ODP	2	50 XXX	SP	CCA		V	1/18/2047	
2020 PO1908644999	ODP	5	35 UNK	SP	CRE	ED,ID,SRS	TD	1/19/2047	
2020 PO1904544800	ODP	4	40 BRN	SP	CRE	ED,ID	TD	1/20/2047	

2020 PO1918244900	ODP	6	30 BRN	SP	CRE		V	1/21/2047
2020 PO1894244918	ODP	4	40 UNK	SP	CRE	ED,ID	TD	1/22/2047
2020 PO2167041309	ODP	4	40 KOP	SP	A	ID	BD	1/23/2047
2020 PO2175741223	ODP	6	30 KOP	SP	S		V	1/24/2047
2020 PO2176240999	ODP	6	30 KOP	SP	S		V	1/25/2047
2020 PO4045182506	LGE	4	30 BRN	SP	A	ED,ID	TD	1/26/2047
2020 PO4045082504	LGE	4	40 BRN	SP	A	ED,ID	TD	1/27/2047
2020 PO2047623794	ODP	5	35 XXX	SP	CCA		V	1/28/2047
2020 PO2047723631	ODP	4	40 XXX	SP	CRE	ID,IP	TD	1/29/2047
2020 PO2051923863	ODP	6	30 XXX	SP	CRE	ID	TD	1/30/2047
2020 PO4097783128	LGE	4	50 CAH	SP	P	ED,ID	TD	1/31/2047
2020 PO4097083137	LGE	4	40 CAH	SP	P	ED,ID	TD	2/1/2047
2020 PO4096183152	LGE	4	45 CAH	SP	P	ED,ID	TD	2/2/2047
2020 PO4095483161	LGE	4	40 CAH	SP	CCA		V	2/3/2047
2020 PO4094283179	LGE	4	40 CAH	SP	CCA	ED,ID	BD	2/4/2047
2020 PO4613337115	KU	4	45 BRO	SP	CCA		V	2/5/2047
2020 PO4625137222	KU	4	45 BRO	SP	CCA		V	2/6/2047
2020 PO4635537323	KU	3	45 BRO	SP	CCA		V	2/7/2047
2020 PO5228202990	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	2/8/2047
2020 PO3920048236	KU	5	35 ACE	SP	CCA		V	2/9/2047
2020 PO3918247851	F	4	40 ACE	SP	CCA		V	2/10/2047
2020 PO3916347498	F	4	40 ACE	SP	CCA		V	2/11/2047
2020 PO3911246551	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	2/12/2047
2020 PO4806502000	KU	4	40 BRO	SP	CRE	ID,IP	BD	2/13/2047
2020 PO4786401797	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	2/14/2047
2020 PO4582801227	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	2/15/2047
2020 PO3943401206	F	4	40 BRO	SP	CCA		V	2/16/2047
2020 PO3968801204	F	4	40 BRO	SP	CCA		V	2/17/2047
2020 PO3273949062	KU	6	30 ACE	SP	CRE	ED,ID	TD	2/18/2047
2020 PO3197950085	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	2/19/2047
2020 PO3252449916	KU	4	45 ACE	SP	CRE	ED,ID	BD	2/20/2047
2020 PO4635037347	KU	3	50 BRO	SP	CCA		V	2/21/2047
2020 PO4638637349	KU	1	60 BRO	SP	CCA		V	2/22/2047
2020 PO0275432854	ODP	5	35 BRN	SP	CRE	ED,ID	TD	2/23/2047
2020 PO0289732810	ODP	4	40 BRN	SP	CRE	ED,ID	TD	2/24/2047
2020 PO0302732709	ODP	4	45 BRN	SP	CRE	ED,ID	TD	2/25/2047
2020 PO4046782491	LGE	4	40 BRN	SP	CRE	ED,ID	TD	2/26/2047
2020 PO2164540850	ODP	5	35 KOP	SP	CRE	ID	BD	2/27/2047
2020 PO2166141128	ODP	4	40 KOP	SP	A	ED,ID	TD	2/28/2047
2020 PO2187140585	ODP	6	30 KOP	DF	CRE		V	3/1/2047
2020 PO21742-40729A	ODP	5	35 KOP	SP	A	ED,ID	TD	3/2/2047
2020 PO2174540575	ODP	6	30 KOP	SP	S		V	3/3/2047
2020 PO2169040737	ODP	6	30 KOP	SP	CRE	ID	BD	3/4/2047
2020 PO2174240729	ODP	5	35 KOP	SP	A	ID	BD	3/5/2047
2020 PO2015823736	ODP	6	30 XXX	SP	CRE	ID	TD	3/6/2047
2020 PO2031623816	ODP	4	40 XXX	SP	CRE	ID	TD	3/7/2047
2020 PO2029824721A	ODP	5	35 XXX	SP	CRE	ID	TD	3/8/2047

2020 PO4043582485	LGE	4	40 BRN	SP	A	ED,ID	BD	3/9/2047
2020 PO3226850004	KU	4	45 ACE	SP	CRE	ED,ID	BD	3/10/2047
2020 PO4099783128	LGE	4	35 CAH	ST	CCA		V	3/11/2047
2020 PO4101183126	LGE	3	45 CAH	SP	CCA		V	3/12/2047
2020 PO4100383125	LGE	4	45 CAH	SP	CRE	ED,ID	BD	3/13/2047
2020 PO4100183118	LGE	4	30 CAH	SP	CRE		V	3/14/2047
2020 PO4099283101	LGE	4	45 CAH	SP	CRE	ED,ID	BD	3/15/2047
2020 PO4099283113	LGE	4	45 CAH	SP	CRE	ED,ID	TD	3/16/2047
2020 PO4098383123	LGE	2	50 CAH	SP	P	ED,ID	BD	3/17/2047
2020 PO0344332677	ODP	4	45 BRN	SP	CCA		V	3/18/2047
2020 PO3950383008	LGE	4	30 BRO	SP	P	ED,ID,IP	TD	3/19/2047
2020 PO3951183018	F	5	30 BRO	SP	P		V	3/20/2047
2020 PO3950783011	F	4	40 BRO	SP	P		V	3/21/2047
2020 PO3949383017	F	4	40 BRO	SP	P		V	3/22/2047
2020 PO4043782513	LGE	4	40 BRN	SP	CRE	ED,ID	TD	3/23/2047
2020 PO0355932923	ODP	4	40 XXX	SP	CRE	ED,ID	TD	3/24/2047
2020 PO3943382917	F	5	25 BRO	SP	P		V	3/25/2047
2020 PO3946982989	F	5	25 BRO	SP	A		V	3/26/2047
2020 PO3947582986	F	3	40 BRO	SP	P		V	3/27/2047
2020 PO3947782978	LGE	5	30 BRO	SP	P		V	3/28/2047
2020 PO3948782973	F	6	25 BRO	SP	A		V	3/29/2047
2020 PO3948982979	F	4	40 BRO	SP	P		V	3/30/2047
2020 PO3950082977	F	4	40 BRO	SP	P		V	3/31/2047
2020 PO3950782974	F	4	30 BRO	SP	P		V	4/1/2047
2020 PO4042682526	LGE	4	40 BRN	SP	CRE	ED,ID	BD	4/2/2047
2020 PO0333433069	ODP	4	40 XXX	SP	CRE	ED,ID	TD	4/3/2047
2020 PO4041282541	LGE	4	40 BRN	SP	CRE	ED,ID	TD	4/4/2047
2020 PO4040982546	LGE	4	30 BRN	SP	CRE	ED,ID	TD	4/5/2047
2020 PO3950982989	F	4	40 BRO	SP	A		V	4/6/2047
2020 PO2068123677	ODP	5	35 XXX	SP	CRE	ID	TD	4/7/2047
2020 PO2094123392	ODP	3	45 XXX	SP	CCA		V	4/8/2047
2020 PO4648537213	KU	3	45 BRO	SP	CRE	ID	BD	4/9/2047
2020 PO4638736673	KU	3	45 BRO	SP	CRE	ED	TD	4/10/2047
2020 PO0666732351	ODP	4	45 XXX	SP	CCA		V	4/11/2047
2020 PO0642832402	ODP	4	45 XXX	SP	CCA		V	4/12/2047
2020 PO0620032489	ODP	4	45 XXX	SP	CCA		V	4/13/2047
2020 PO0593232408	ODP	4	45 XXX	SP	CCA		V	4/14/2047
2020 PO4070783319	LGE	4	40 CAH	SP	CCA		V	4/15/2047
2020 PO4070183278	LGE	4	40 CAH	SP	CRE	ED,ID	BD	4/16/2047
2020 PO4070783299	LGE	4	35 CAH	SP	A	ED,ID	TD	4/17/2047
2020 PO4071483293	LGE	4	40 CAH	SP	CRE	ED,ID	BD	4/18/2047
2020 PO3851182066	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	4/19/2047
2020 PO3853082055	LGE	2	65 BRO	SP	CRE		V	4/20/2047
2020 PO2227741470	ODP	4	40 KOP	SP	A	ED,ID	TD	4/21/2047
2020 PO23887-42438A	ODP	6	25 KOP	SP	S		V	4/22/2047
2020 PO2388742438	ODP	4	45 KOP	SP	CRE	ED,ID	TD	4/23/2047
2020 PO2396442378	ODP	6	30 KOP	SP	CRE	ED,ID	TD	4/24/2047

2020 PO4039182719	F	4	40 BRN	SP	CRE		V		4/25/2047
2020 PO4040882728	F	4	40 BRN	SP	CRE		V		4/26/2047
2020 PO4041582711	F	4	40 BRN	SP	CRE		V		4/27/2047
2020 PO4041582696	F	4	40 BRN	SP	CRE		V		4/28/2047
2020 PO4040482681	F	4	40 BRN	SP	CCA		V		4/29/2047
2020 PO4015982628	LGE	4	40 BRN	SP	CRE	ED,ID	TD		4/30/2047
2020 PO3852382059	LGE	4	40 BRO	SP	A	ED,ID	TD		5/1/2047
2020 PO3852382037	LGE	2	65 BRO	SP	CRE		V		5/2/2047
2020 PO3852382014	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD		5/3/2047
2020 PO4035882728	F	4	40 BRN	SP	CRE		V		5/4/2047
2020 PO4032882764	LGE	6	30 BRN	SP	CRE	ED,ID	TD		5/5/2047
2020 PO4032682758	F	3	40 BRN	SP	CRE		V		5/6/2047
2020 PO4033282742	F	4	40 BRN	SP	CRE		V		5/7/2047
2020 PO4032682745	F	4	40 BRN	SP	CRE		V		5/8/2047
2020 PO3850682015	LGE	4	30 BRO	SP	P	ED	T		5/9/2047
2020 PO3851682014	LGE	2	65 BRO	SP	CRE		V		5/10/2047
2020 PO3850881996	LGE	2	65 BRO	SP	CRE		V		5/11/2047
2020 PO3850681986	LGE	4	40 BRO	SP	CCA		V		5/12/2047
2020 PO3850181975	LGE	2	65 BRO	AL	CCA		V		5/13/2047
2020 PO3849581990	LGE	4	30 BRO	SP	CRE	ED,ID,MD	X	RP3	5/14/2047
2020 PO3848581945	LGE	4	35 BRO	SP	P	ED,ID	TD		5/15/2047
2020 PO3849281944	LGE	2	65 BRO	SP	A		V		5/16/2047
2020 PO0407732120	ODP	4	45 XXX	SP	CCA		V		5/17/2047
2020 PO0384432020	ODP	3	50 XXX	SP	CCA		V		5/18/2047
2020 PO0406131914	ODP	4	40 XXX	SP	CCA		V		5/19/2047
2020 PO0360931974	ODP	4	45 XXX	SP	CCA		V		5/20/2047
2020 PO0360632126	ODP	4	40 XXX	SP	CRE	ED,ID,IP,SRC	TX	RR	5/21/2047
2020 PO0356932202	ODP	4	35 XXX	SP	CRE	ED,ID	TX	RR	5/22/2047
2020 PO0396432418	ODP	4	40 XXX	SP	CRE	ED,ID	TD		5/23/2047
2020 PO0380132318	ODP	4	45 XXX	SP	CCA		V		5/24/2047
2020 PO0345832375	ODP	4	40 XXX	SP	CRE	ED,ID	TD		5/25/2047
2020 PO0329832597	ODP	4	45 BRN	SP	CCA		V		5/26/2047
2020 PO4033182725	F	4	40 BRN	SP	CRE		V		5/27/2047
2020 PO4033182720	F	4	30 BRN	SP	CRE		V		5/28/2047
2020 PO4031282719	F	4	40 BRN	SP	CRE		V		5/29/2047
2020 PO4030482716	F	4	40 BRN	SP	CRE		V		5/30/2047
2020 PO0297532620	ODP	6	30 BRN	SP	CCA		V		5/31/2047
2020 PO3878582905	LGE	2	50 BRO	SP	CRE		V		6/1/2047
2020 PO3877182909	LGE	2	50 BRO	SP	CRE		V		6/2/2047
2020 PO3875682912	LGE	2	50 BRO	SP	CRE		V		6/3/2047
2020 PO3874382915	LGE	2	60 BRO	SP	CRE		V		6/4/2047
2020 PO3872282916	LGE	4	30 BRO	SP	CCA		V		6/5/2047
2020 PO3872882918	LGE	2	65 BRO	SP	CRE		V		6/6/2047
2020 PO3871982924	LGE	2	65 BRO	SP	CRE		V		6/7/2047
2020 PO3871182916	LGE	4	40 BRO	SP	P	ED,ID,IP	TD		6/8/2047
2020 PO3867883014	LGE	4	40 BRO	SP	CCA		V		6/9/2047
2020 PO3861582438	LGE	3	45 BRO	SP	CCA		V		6/10/2047

2020 PO3858882452	LGE		3	45 BRO	SP	CCA		V	6/11/2047
2020 PO3871382476	LGE	1H		70 BRO	SP	A		V	6/12/2047
2020 PO3870682473	LGE		4	30 BRO	SP	CCA		V	6/13/2047
2020 PO3870882463	LGE	2H		65 BRO	SP	A		V	6/14/2047
2020 PO3870382427	LGE		4	30 BRO	SP	CCA		V	6/15/2047
2020 PO3869582424	LGE		2	65 BRO	SP	CRE		V	6/16/2047
2020 PV3868282350	LGE		3	45 BRO	SP	P	ED,ID,IP	TD	6/17/2047
2020 PO3867482323	LGE		4	30 BRO	SP	CCA		V	6/18/2047
2020 PO3867582399	LGE		4	40 BRO	SP	A	ED,ID	TD	6/19/2047
2020 PO3869082461	LGE		4	30 BRO	SP	CCA		V	6/20/2047
2020 PO3869782455	LGE	4H		45 BRO	SP	A	ED,ID	TD	6/21/2047
2020 PO3870382448	LGE	2H		65 BRO	SP	CCA		V	6/22/2047
2020 PO3871282449	LGE		4	35 BRO	SP	CCA		V	6/23/2047
2020 PO3911882465	F		4	30 BRO	SP	CCA		V	6/24/2047
2020 PO3913282456	F		4	30 BRO	SP	CCA		V	6/25/2047
2020 PO3914482448	F		4	30 BRO	SP	CCA		V	6/26/2047
2020 PO3915982438	F		4	30 BRO	SP	CCA		V	6/27/2047
2020 PO3916882432	F		4	35 BRO	SP	CCA		V	6/28/2047
2020 PO3917782426	F		4	30 BRO	SP	CCA		V	6/29/2047
2020 PO3918382423	F		4	30 BRO	SP	CCA		V	6/30/2047
2020 PO3912682453	F		4	40 BRO	SP	CCA		V	7/1/2047
2020 PO3911382461	F		3	45 BRO	SP	CRE		V	7/2/2047
2020 PO4002182528	LGE		4	30 BRN	SP	CRE	ED,ID	BD	7/3/2047
2020 PO4002482535	LGE		4	40 BRN	SP	CRE	ED,ID	TD	7/4/2047
2020 PO4003282550	LGE		3	45 BRN	SP	S		V	7/5/2047
2020 PO3423148468	F		4	40 BRO	SP	A		V	7/6/2047
2020 PO3433648399	F		4	40 BRO	SP	CRE		V	7/7/2047
2020 PO3941083010	F		5	25 BRO	SP	CCA		V	7/8/2047
2020 PO3942382995	F		5	25 BRO	SP	P		V	7/9/2047
2020 PO4004582561	LGE		6	30 BRN	SP	A	ED,ID	TD	7/10/2047
2020 PO4004082563	LGE		4	40 BRN	SP	A	ED,ID	TD	7/11/2047
2020 PO3433048565	KU		5	35 BRO	SP	CRE	ED,ID,IP	TD	7/12/2047
2020 PO3425148616	F		4	40 BRO	SP	A		V	7/13/2047
2020 PO3442948709	KU		4	40 BRO	SP	CCA		V	7/14/2047
2020 PO3422048368	KU		6	30 BRO	SP	CRE	ED,ID,IP	TD	7/15/2047
2020 PO3424848258	KU		6	30 BRO	SP	CRE	ED,ID,IP	TD	7/16/2047
2020 PO3925682005	LGE		1	95 BRN	SP	CRE		V	7/17/2047
2020 PO3925982012	LGE		1	70 BRN	SP	CRE	ED,ID	BD	7/18/2047
2020 PO3926782029	LGE		1	70 BRN	SP	CRE	ED,ID	BD	7/19/2047
2020 PO3927182041	LGE		1	95 BRN	SP	CRE		V	7/20/2047
2020 PO3927582048	LGE		1	60 BRN	SP	CRE	ED,ID	BD	7/21/2047
2020 PO3928382067	LGE		1	70 BRN	SP	CRE	ED,ID	BD	7/22/2047
2020 PO3928782080	LGE		1	95 BRN	SP	CRE		V	7/23/2047
2020 PO3928982083	LGE		1	55 BRN	SP	CRE	ED,ID	BD	7/24/2047
2020 PO3930382117	LGE	UNK		105 BRN	SP	CRE		V	7/25/2047
2020 PO3929682101	LGE		1	70 BRN	SP	CRE	ED,ID	BD	7/26/2047
2020 PO3930982132	LGE		1	55 BRN	SP	CRE	ED,ID	BD	7/27/2047

2020 PO3931682151	LGE	UNK	115	BRN	AL	CRE		V		7/28/2047
2020 PO4004982575	LGE	3	45	BRN	SP	CRE	ED,ID	TD		7/29/2047
2020 PO4004382595	LGE	3	45	BRN	SP	S		V		7/30/2047
2020 PO4840187109	LGE	1	30	KOP	SP	S		V		7/31/2047
2020 PO4836487170	LGE	4	40	KOP	SP	CRE	ED,ID	BD		8/1/2047
2020 PO4831487345	LGE	3	45	KOP	SP	S		V		8/2/2047
2020 PO4831087305	LGE	3	45	KOP	SP	S		V		8/3/2047
2020 PO4830787321	LGE	3	45	KOP	SP	S		V		8/4/2047
2020 PO4830387337	LGE	3	45	KOP	SP	S		V		8/5/2047
2020 PO4831887268	LGE	4	40	KOP	SP	A	ED,ID	TD		8/6/2047
2020 PO9336973302	KU	6	30	XXX	SP	CRE	ED,ID,RB	X	RP1	8/7/2047
2020 PO9329673413	KU	5	35	XXX	SP	CRE		V		8/8/2047
2020 PO9326073362	KU	5	35	XXX	SP	CRE	ID	BD		8/9/2047
2020 PO4859887282	F	4	40	XXX	SP	CCA		V		8/10/2047
2020 PO4861187286	F	4	40	XXX	SP	CCA		V		8/11/2047
2020 PO4863487286	F	4	40	XXX	SP	CCA		V		8/12/2047
2020 PO4864487285	F	3	45	XXX	SP	CCA		V		8/13/2047
2020 PO4865587284	F	4	40	XXX	SP	CCA		V		8/14/2047
2020 PO4867287256	LGE	4	40	XXX	SP	CCA		V		8/15/2047
2020 PO4867687282	F	4	40	XXX	SP	CCA		V		8/16/2047
2020 PO4869587280	F	4	40	XXX	SP	CCA		V		8/17/2047
2020 PO4875387272	F	4	40	XXX	SP	CCA		V		8/18/2047
2020 PO4684988853	LGE	3	45	BRO	SP	CCA		V		8/19/2047
2020 PO4777387925	LGE	4	40	BRO	SP	CRE	ED	BD		8/20/2047
2020 PO4782787925	LGE	4	40	BRO	SP	CRE	ED	TD		8/21/2047
2020 PO4782687928	LGE	4	40	BRO	SP	CRE	ED	TD		8/22/2047
2020 PO4782087944	LGE	4	40	BRO	SP	CRE	ED	TD		8/23/2047
2020 PO4779887765	F	3	45	BRO	SP	CRE		V		8/24/2047
2020 PO4804587861	LGE	4	40	BRN	SP	CRE	ED,ID	BX	RP2	8/25/2047
2020 PO4804487847	LGE	4	30	BRN	SP	A	ED,ID	BD		8/26/2047
2020 PO4869387763	LGE	3	45	XXX	SP	CCA		V		8/27/2047
2020 PO4867087764	LGE	3	50	XXX	SP	CCA		V		8/28/2047
2020 PO4804987849	LGE	3	45	BRN	SP	CCA		V		8/29/2047
2020 PO4682788763	LGE	4	40	BRO	SP	A	ID,IP	BD		8/30/2047
2020 PO4683488754	LGE	4	40	BRO	SP	CCA		V		8/31/2047
2020 PO4779887777	F	UNK	45	BRO	SP	CRE		V		9/1/2047
2020 PO4779987808	F	UNK	45	BRO	SP	CRE		V		9/2/2047
2020 PO4779887796	F	3	45	BRO	SP	CCA		V		9/3/2047
2020 PO4779987825	F	UNK	45	BRO	SP	CRE		V		9/4/2047
2020 PO2367535898	ODP	4	40	UNK	SP	CRE	ED,ID	TD		9/5/2047
2020 PO2418336174	ODP	4	40	UNK	SP	CRE	ED,ID	TD		9/6/2047
2020 PO1980024833	F	4	40	XXX	SP	CRE		V		9/7/2047
2020 PO1965424816	F	4	40	XXX	SP	A		V		9/8/2047
2020 PO1944024806	F	4	40	XXX	SP	CRE		V		9/9/2047
2020 PO1939324765	F	4	40	XXX	SP	A		V		9/10/2047
2020 PO1917624701	F	4	40	XXX	SP	P		V		9/11/2047
2020 PO1919223172	F	4	40	XXX	SP	P		V		9/12/2047

2020 PO1895823295	F	4	40 XXX	SP	CRE		V	9/13/2047
2020 PO1873023568	F	4	40 XXX	SP	CCA		V	9/14/2047
2020 PO1870023669	ODP	4	45 XXX	SP	CRE	ID	TD	9/15/2047
2020 PO1854323702	F	4	40 XXX	SP	CRE		V	9/16/2047
2020 PO1838023896	F	4	40 XXX	SP	CRE		V	9/17/2047
2020 PO1795223767	F	4	40 XXX	SP	CRE		V	9/18/2047
2020 PO1775024028	F	4	40 XXX	SP	CRE		V	9/19/2047
2020 PO1870624266	ODP	4	40 XXX	SP	CCA		V	9/20/2047
2020 PO1836324304	ODP	6	30 XXX	SP	CCA		V	9/21/2047
2020 PO1855424252	F	4	40 XXX	SP	CRE		V	9/22/2047
2020 PO1849924816	F	4	40 XXX	SP	P		V	9/23/2047
2020 PO1848024604	F	3	45 XXX	SP	P		V	9/24/2047
2020 PO1827524446	F	4	40 XXX	SP	CRE		V	9/25/2047
2020 PO1847324390	ODP	5	35 XXX	SP	CRE	ID	TD	9/26/2047
2020 PO1817524670	F	4	40 XXX	SP	CRE	HH,ID	BX	RP2 9/27/2047
2020 PO1790824459	F	4	40 XXX	SP	CRE		V	9/28/2047
2020 PO4079283358	LGE	4	40 BRN	SP	CRE	ED,ID	BD	9/29/2047
2020 PO4080383342	LGE	4	40 BRN	SP	CRE	ED,ID	BD	9/30/2047
2020 PO3962882414	LGE	3	40 BRN	SP	A	ED,ID	BD	10/1/2047
2020 PO3962782413	LGE	4	40 BRN	SP	CRE	ED,ID	BD	10/2/2047
2020 PO3581111013	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	10/3/2047
2020 PO3604311106	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	10/4/2047
2020 PO3964482405	LGE	4	35 BRN	SP	CRE	ED,ID	BD	10/5/2047
2020 PO3964182410	LGE	3	45 BRN	SP	A	ED,ID	BD	10/6/2047
2020 PO3965082416	LGE	4	30 BRN	SP	A	ED,ID	BD	10/7/2047
2020 PO3965782431	LGE	3	45 BRN	SP	S		V	10/8/2047
2020 PO3965282434	LGE	3	45 BRN	SP	A	ED,ID	TD	10/9/2047
2020 PO3963982441	LGE	3	45 BRN	SP	A	ED,ID	TD	10/10/2047
2020 PO3659913953	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	10/11/2047
2020 PO3694013744	KU	5	35 BRO	SP	CRE	ID,IP	BD	10/12/2047
2020 PO3625211189	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	10/13/2047
2020 PO3964983123	LGE	3	45 BRO	SP	P	ED,ID	TD	10/14/2047
2020 PO3966683147	LGE	3	45 BRO	SP	CRE	ED,ID	TD	10/15/2047
2020 PO3967183155	LGE	4	45 BRO	SP	CRE	ED,ID	TD	10/16/2047
2020 PO6875443523	LGE	3	45 BRO	SP	CCA		V	10/17/2047
2020 PO3960182707	LGE	3	45 BRN	SP	S		V	10/18/2047
2020 PO3960282694	LGE	3	45 BRN	SP	S		V	10/19/2047
2020 PO2178033375	ODP	4	40 BRN	SP	CRE	ID	TD	10/20/2047
2020 PO2184833663	ODP	6	30 BRN	SP	CRE	ID	TD	10/21/2047
2020 PO2210533806	ODP	4	40 BRN	SP	CRE	ID	TD	10/22/2047
2020 PO2210533806A	ODP	6	30 BRN	SP	CCA		V	10/23/2047
2020 PO2234633799	ODP	4	40 BRN	SP	CCA		V	10/24/2047
2020 PO2251733580	ODP	4	45 BRN	SP	CCA		V	10/25/2047
2020 PO2216333643	ODP	5	35 BRN	SP	CCA		V	10/26/2047
2020 PO2221633674	ODP	3	45 BRN	SP	CCA		V	10/27/2047
2020 PO2217333867	ODP	4	40 BRN	SP	CRE	ID	TD	10/28/2047
2020 PO2224633953	ODP	4	40 BRN	SP	CRE	ED,ID,SRS	TD	10/29/2047

2020 PO2215734049	ODP	4	40 ACW	SP	CRE	ED,ID	TD	10/30/2047
2020 PO2208534095	ODP	4	45 BRN	SP	CCA		V	10/31/2047
2020 PO2279534111	ODP	4	40 BRN	SP	CCA		V	11/1/2047
2020 PO2253834303	ODP	4	40 BRN	SP	CRE	ID	TD	11/2/2047
2020 PO2238734122	ODP	4	40 KOP	SP	CRE	ED,ID,SRC	TD	11/3/2047
2020 PO2228834444	ODP	4	40 KOP	SP	CRE	ED,ID	TD	11/4/2047
2020 PO2257134469	ODP	4	40 BRN	SP	CRE	ID	TD	11/5/2047
2020 PO3960682699	F	4	35 BRN	SP	CCA		V	11/6/2047
2020 PO4421208932	F	4	40 ACE	SP	P		V	11/7/2047
2020 PO4642509639	F	4	40 ACE	SP	CRE		V	11/8/2047
2020 PO4654309589	F	4	40 ACE	SP	CCA		V	11/9/2047
2020 PO4651909503	F	4	40 ACE	SP	P		V	11/10/2047
2020 PO4649209413	F	4	40 ACE	SP	CRE		V	11/11/2047
2020 PO4637308948	KU	6	30 ACE	SP	CRE		V	11/12/2047
2020 PO4641409228	F	4	40 ACE	SP	CRE		V	11/13/2047
2020 PO4633609037	F	4	40 ACE	SP	CRE		V	11/14/2047
2020 PO4616408868	F	4	40 ACE	SP	CRE		V	11/15/2047
2020 PO4626108874	F	4	40 ACE	SP	P		V	11/16/2047
2020 PO0766138561	ODP	4	45 BRN	SP	CRE		V	11/17/2047
2020 PO0772138332	ODP	4	45 BRN	SP	CRE		V	11/18/2047
2020 PO0794938118a	ODP	5	30 XXX	SP	CCA		V	11/19/2047
2020 PO0784238242	ODP	4	40 XXX	SP	CCA		V	11/20/2047
2020 PO3960882652	F	3	45 BRN	SP	CRE		V	11/21/2047
2020 PO3961182652	F	4	30 BRN	SP	CRE		V	11/22/2047
2020 PO3961282637	F	4	40 BRN	SP	CCA		V	11/23/2047
2020 PO3960882636	F	3	45 BRN	SP	CRE		V	11/24/2047
2020 PO3960882631	F	4	40 BRN	SP	CCA		V	11/25/2047
2020 PO3959382634	F	4	40 BRN	SP	CRE		V	11/26/2047
2020 PO1116728282	ODP	4	40 BRN	SP	CCA	ED	T	11/27/2047
2020 PO1111428145	ODP	4	45 BRN	SP	CCA	ED	T	11/28/2047
2020 PO1136528840A	ODP	4	45 BRN	SP	CCA		V	11/29/2047
2020 PO1683619403	ODP	4	40 XXX	SP	CRE	ID,IP	TD	11/30/2047
2020 PO1711519389	ODP	4	45 XXX	SP	CRE	ID	TD	12/1/2047
2020 PO0796238246	ODP	4	45 XXX	SP	CCA		V	12/2/2047
2020 PO0814738482	ODP	4	45 XXX	SP	CCA		V	12/3/2047
2020 PO3955182662	LGE	4	45 BRN	SP	CRE	ED,ID	BD	12/4/2047
2020 PO3955082663	LGE	2	45 BRN	SP	CRE	ED,ID	BD	12/5/2047
2020 PO3957682645	F	4	40 BRN	SP	CRE		V	12/6/2047
2020 PO0864435834	ODP	5	35 XXX	SP	CCA		V	12/7/2047
2020 PO0869035975	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD	12/8/2047
2020 PO0883036196	ODP	2	45 XXX	SP	P		V	12/9/2047
2020 PO0880935959	F	3	40 XXX	SP	P		V	12/10/2047
2020 PO0889735990	ODP	6	30 XXX	SP	CRE	ED,ID,IP	TD	12/11/2047
2020 PO3974183254	LGE	3	45 BRO	SP	CRE	ED,ID	TD	12/12/2047
2020 PO3974783262	LGE	2	45 BRO	SP	CCA		V	12/13/2047
2020 PO1116528758A	ODP	4	45 BRN	SP	CCA		V	12/14/2047
2020 PO1186731180	F	4	40 XXX	SP	A		V	12/15/2047

2020 PO3968883180	LGE	3	45 BRO	SP	CRE	ED,ID	TD	12/16/2047
2020 PO3969983196	LGE	2	45 BRO	SP	CRE	ED,ID	TD	12/17/2047
2020 PO3971183211	LGE	2	45 BRO	SP	CRE	ED,ID	TD	12/18/2047
2020 PO3970783206	LGE	3	45 BRO	SP	CRE	ED,ID	TD	12/19/2047
2020 PO3970783205	LGE	4	40 BRO	SP	CRE	ED,ID	BD	12/20/2047
2020 PO3971783219	LGE	3	45 BRO	SP	CCA		V	12/21/2047
2020 PO3973583244	LGE	2	45 BRO	SP	CRE	ED,ID	BD	12/22/2047
2020 PO3972883235	LGE	3	50 BRO	SP	CCA		V	12/23/2047
2020 PO3972283227	LGE	2	45 BRO	SP	CRE	ED,ID,IP	BD	12/24/2047
2020 PO3973583230	LGE	4	30 BRO	SP	P	ED,ID	BD	12/25/2047
2020 PO6928643911	LGE	4	30 BRO	SP	P	ED,ID	BD	12/26/2047
2020 PO3961582615	LGE	4	35 BRN	SP	A	ED,ID	TD	12/27/2047
2020 PO3960982612	F	4	40 BRN	SP	CRE		V	12/28/2047
2020 PO3960982612	F	4	35 BRN	SP	A		V	12/29/2047
2020 PO3964182599	F	5	30 BRN	SP	CRE		V	12/30/2047
2020 PO3961682592	F	4	40 BRN	SP	CRE		V	12/31/2047
2020 PO3961182599	F	4	40 BRN	SP	CRE		V	1/1/2048
2020 PO1588620540	ODP	4	40 XXX	SP	CCA		V	1/2/2048
2020 PO1585620721	ODP	4	40 XXX	SP	CCA		V	1/3/2048
2020 PO1596820823	ODP	5	30 XXX	SP	CCA	ED	TD	1/4/2048
2020 PO1580020963	ODP	4	40 XXX	SP	CRE	ID	TD	1/5/2048
2020 PO1596121024	ODP	6	30 XXX	SP	CRE	ED,SRS	TD	1/6/2048
2020 PO1222331290	ODP	4	40 XXX	SP	CRE	ID	TD	1/7/2048
2020 PO0516635535	ODP	5	35 XXX	SP	CRE	ED,ID	TD	1/8/2048
2020 PO0528835271	ODP	4	40 XXX	SP	CCA		V	1/9/2048
2020 PO0487635238	ODP	5	35 XXX	SP	CRE	ED,ID	TD	1/10/2048
2020 PO0478535211	ODP	4	40 XXX	SP	CCA		V	1/11/2048
2020 PO0492934853	ODP	4	40 XXX	SP	CRE	ID	BD	1/12/2048
2020 PO3961482571	F	4	40 BRN	SP	CRE		V	1/13/2048
2020 PO3961282585	F	4	40 BRN	SP	CCA		V	1/14/2048
2020 PO3962382573	F	4	45 BRN	SP	CRE		V	1/15/2048
2020 PO3962182556	F	4	40 BRN	SP	CRE		V	1/16/2048
2020 PO3961682557	F	4	40 BRN	SP	CRE		V	1/17/2048
2020 PO3961882544	F	4	40 BRN	SP	CRE		V	1/18/2048
2020 PO3962782531	F	4	30 BRN	SP	CRE		V	1/19/2048
2020 PO3975783236	LGE	3	45 BRO	SP	P	ED,ID	TD	1/20/2048
2020 PO6934944121	LGE	4	35 BRO	SP	CCA		V	1/21/2048
2020 PO3962282516	F	4	40 BRN	SP	CRE		V	1/22/2048
2020 PO3962082530	F	4	40 BRN	SP	CRE		V	1/23/2048
2020 PO3963282486	F	4	35 BRN	SP	CCA		V	1/24/2048
2020 PO3962982473	F	4	30 BRN	SP	CRE		V	1/25/2048
2020 PO2255834720	ODP	4	40 BRN	SP	CRE	ID	TD	1/26/2048
2020 PO2242834697	ODP	5	30 BRN	SP	CRE	ED,ID,SRC	TD	1/27/2048
2020 PO2238834656	ODP	5	35 BRN	SP	CCA		V	1/28/2048
2020 PO2215534365	ODP	4	45 BRN	SP	CRE		V	1/29/2048
2020 PO1208931648	ODP	5	35 XXX	SP	CRE	ID	TD	1/30/2048
2020 PO1217631551	ODP	5	35 XXX	SP	CRE	ID	TD	1/31/2048

2020 PO4666408903	F	4	40 ACE	SP	CRE		V	2/1/2048
2020 PO0612735166	ODP	6	30 BRN	SP	CCA		V	2/2/2048
2020 PO0624935179	F	4	40 SWP	SP	P		V	2/3/2048
2020 PO0677635194	F	4	40 SWP	SP	P		V	2/4/2048
2020 PO4645108889	F	4	40 ACE	SP	P		V	2/5/2048
2020 PO4680808913	F	4	40 ACE	SP	P		V	2/6/2048
2020 PO3945882035	LGE	3	45 BRN	SP	CRE		V	2/7/2048
2020 PO3945482020	LGE	3	45 BRN	SP	S		V	2/8/2048
2020 PO3955782015	LGE	4	40 BRN	SP	CRE	ED,ID	BD	2/9/2048
2020 PO3955482040	LGE	3	45 BRN	SP	S		V	2/10/2048
2020 PO1192331767	ODP	4	40 XXX	SP	CRE	ID	BD	2/11/2048
2020 PO1221631765	ODP	5	35 XXX	SP	CCA		V	2/12/2048
2020 PO1275831966	ODP	4	40 XXX	SP	CRE	ID	TD	2/13/2048
2020 PO1243331738	ODP	5	35 XXX	SP	CCA		V	2/14/2048
2020 PO1291931798	ODP	5	35 XXX	SP	CRE	ID	BD	2/15/2048
2020 PO0679135145	ODP	6	30 BRN	SP	CCA		V	2/16/2048
2020 PO3954382044	LGE	3	45 BRN	SP	S		V	2/17/2048
2020 PO3952482050	LGE	4	40 BRN	SP	CRE	ED,ID	TD	2/18/2048
2020 PO4681408802	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	RP1 2/19/2048
2020 PO4687009059	F	4	40 ACE	SP	P		V	2/20/2048
2020 PO4690909153	F	4	40 ACE	SP	P		V	2/21/2048
2020 PO4694709236	F	4	40 ACE	SP	P		V	2/22/2048
2020 PO3950982054	LGE	4	40 BRN	SP	CRE	ED,ID	BD	2/23/2048
2020 PO1654720899	ODP	3	45 XXX	SP	CCA		V	2/24/2048
2020 PO1638720613	ODP	5	35 XXX	SP	CRE	ID	TD	2/25/2048
2020 PO1681920848	ODP	3	45 XXX	SP	CCA		V	2/26/2048
2020 PO1717120310	ODP	4	45 XXX	SP	CCA		V	2/27/2048
2020 PO1708320736	ODP	3	45 XXX	SP	CCA		V	2/28/2048
2020 PO1729320668	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD	2/29/2048
2020 PO1717020643	ODP	6	30 XXX	SP	CCA		V	3/1/2048
2020 PO0575635326	ODP	4	40 XXX	SP	CCA		V	3/2/2048
2020 PO0592435349	ODP	4	40 XXX	SP	CCA		V	3/3/2048
2020 PO0623635385	ODP	4	40 XXX	SP	A	ED,ID	TD	3/4/2048
2020 PO0659535429a	ODP	4	40 XXX	SP	CCA		V	3/5/2048
2020 PO0659535429	ODP	4	35 XXX	SP	CRE	ED,ID	TD	3/6/2048
2020 PO3949482059	LGE	4	40 BRN	SP	CRE	ED,ID	BD	3/7/2048
2020 PO2193534161	ODP	4	45 BRN	SP	CRE		V	3/8/2048
2020 PO2175334145	ODP	6	30 KOP	SP	CRE	ID	TD	3/9/2048
2020 PO2165234123	F	5	30 UNK	SP	CRE		V	3/10/2048
2020 PO2181134311	ODP	4	40 BRN	SP	CRE	ID	TD	3/11/2048
2020 PO2201334858	F	4	40 BRN	SP	CRE		V	3/12/2048
2020 PO2164134908	F	4	40 BRN	SP	P		V	3/13/2048
2020 PO2170734682	ODP	6	30 BRN	SP	CCA		V	3/14/2048
2020 PO2255334877	ODP	4	40 KOP	SP	CRE	ID	TD	3/15/2048
2020 PO2244334827	ODP	6	30 KOP	SP	CCA		V	3/16/2048
2020 PO2325735403	F	4	40 KOP	SP	CRE		V	3/17/2048
2020 PO2284135196	F	3	45 UNK	SP	P		V	3/18/2048

2020 PO3977583254	LGE	4	50 BRO	SP	P	ED,ID	TD	3/19/2048		
2020 PO6949144523	LGE	5	30 BRO	SP	A	ED,ID	BD	3/20/2048		
2020 PO6945144470	LGE	5	30 BRO	SP	P	ED,ID	BD	3/21/2048		
2020 PO6955044552	LGE	5	30 BRO	SP	P	ED,ID	BD	3/22/2048		
2020 PO3947982063	LGE	4	40 BRN	SP	CRE	ED,ID	TD	3/23/2048		
2020 PO3946182051	LGE	4	40 BRN	SP	A	ED,ID	TD	3/24/2048		
2020 PO4698709333	F	4	40 ACE	SP	P		V	3/25/2048		
2020 PO4702409418	F	4	40 ACE	SP	P		V	3/26/2048		
2020 PO4661709761	F	4	40 ACE	SP	CRE		V	3/27/2048		
2020 PO4666510042	F	4	40 ACE	SP	CRE		V	3/28/2048		
2020 PO4660509986	F	4	40 ACE	SP	CCA		V	3/29/2048		
2020 PO1237431415	ODP	6	30 XXX	SP	CCA		V	3/30/2048		
2020 PO1307531605	ODP	4	40 XXX	SP	CRE	ID	BD	3/31/2048		
2020 PO3637349511	F	3	45 ACE	SP	P		V	4/1/2048		
2020 PO3640649683	F	3	45 ACE	SP	P		V	4/2/2048		
2020 PO3650549875	KU	4	45 ACE	SP	CCA		V	4/3/2048		
2020 PO3649950125	KU	4	45 ACE	SP	CCA		V	4/4/2048		
2020 PO3058839273	F	4	40 ACE	SP	CRE		V	4/5/2048		
2020 PO4086501311	F	4	40 BRO	SP	CCA		V	4/6/2048		
2020 PO4106001383	F	4	40 BRO	SP	CCA		V	4/7/2048		
2020 PO4125801459	F	4	40 BRO	SP	CRE		V	4/8/2048		
2020 PO4145001545	F	3	45 BRO	SP	CCA		V	4/9/2048		
2020 PO4918587124	LGE	4E	40E	OTH	SP	CRE	ED,ID,SRC	TX	RR	4/10/2048
2020 PO4919287120	LGE	4	30 OTH	SP	CRE		ED,ID,SRS	TD		4/11/2048
2020 PO4919087105	LGE	4	40 OTH	SP	CRE		ID	BD		4/12/2048
2020 PO4920387090	LGE	4	30 OTH	SP	CRE		ED,ID,RB	X	RP1	4/13/2048
2020 PO4867286511	LGE	4	30 XXX	SP	P		ID	TD		4/14/2048
2020 PO4676988793	LGE	3	45 BRO	SP	CCA			V		4/15/2048
2020 PO4678088803	LGE	3	45 BRO	SP	CCA			V		4/16/2048
2020 PO4679188810	LGE	3H	45 BRO	SP	CCA			V		4/17/2048
2020 PO4680088817	LGE	3	50 BRO	SP	CCA			V		4/18/2048
2020 PO4681788829	LGE	3	45 BRO	SP	CCA			V		4/19/2048
2020 PO4686188862	LGE	3	45 BRO	SP	CCA			V		4/20/2048
2020 PO4683688842	LGE	3	45 BRO	SP	CCA			V		4/21/2048
2020 PO4679988801	LGE	4	40 BRO	SP	CCA			V		4/22/2048
2020 PO4681488782	LGE	4	40 BRO	SP	CCA			V		4/23/2048
2020 PO4863686526	LGE	1	50 XXX	SP	P		ID	BD		4/24/2048
2020 PO4864486528	LGE	1	50 XXX	SP	P		ID	BD		4/25/2048
2020 PO4864786511	LGE	3	45 XXX	SP	P		ID	BD		4/26/2048
2020 PO4876587703	LGE	4	40 XXX	SP	A		ED,ID,SRC	TX	RR	4/27/2048
2020 PO6348482916	LGE	H2	70 OTH	SP	P		ID	BD		4/28/2048
2020 PO4923786961	LGE	1	50 OTH	SP	CCA			V		4/29/2048
2020 PO4924386941	LGE	1	50 OTH	SP	CCA			V		4/30/2048
2020 PO4850686343	LGE	3	45 OTH	SP	P		ED,ID,SRS	TD		5/1/2048
2020 PO4861086503	LGE	4	30 XXX	SP	P		ID	TD		5/2/2048
2020 PO4846386317	LGE	1	45 OTH	SP	P			V		5/3/2048
2020 PO4848186334	LGE	3	45 OTH	SP	CCA		ED,SRS	TD		5/4/2048

2020 PO4848586335	LGE	3	45 OTH	SP	P	ID	BD	5/5/2048
2020 PO4848086340	LGE	5	30 OTH	SP	P	ED,SRS	TD	5/6/2048
2020 PO4927786935	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	5/7/2048
2020 PO4861286511	LGE	2	45 XXX	SP	P	ID	TD	5/8/2048
2020 PO4859086520	LGE	3	45 XXX	SP	P	ID	BD	5/9/2048
2020 PO4853086390	F	3	50 OTH	SP	P		V	5/10/2048
2020 PO4853586375	F	3	50 OTH	SP	P		V	5/11/2048
2020 PO4857886241	F	3	45 OTH	SP	P		V	5/12/2048
2020 PO6369482360	LGE	1	50 OTH	SP	CCA		V	5/13/2048
2020 PO4851386504	LGE	1	50 XXX	SP	CCA	ID	BD	5/14/2048
2020 PO4848786497	LGE	1	55 XXX	SP	CCA		V	5/15/2048
2020 PO4924386793	LGE	4	40 OTH	SP	P	ED,ID,SRS	TD	5/16/2048
2020 PO4870586304	F	3	45 OTH	SP	P		V	5/17/2048
2020 PO4924686810	LGE	4	30 OTH	SP	CRE	ED,ID,SRS	TD	5/18/2048
2020 PO4867486270	LGE	1	50 OTH	SP	P		V	5/19/2048
2020 PO4867286272	F	3	50 OTH	SP	P		V	5/20/2048
2020 PO5812475805	LGE	4	35 OTH	SP	CCA		V	5/21/2048
2020 PO5802476077	LGE	4	35 OTH	SP	CCA		V	5/22/2048
2020 PO5806675933	LGE	4	35 OTH	SP	CCA		V	5/23/2048
2020 PO4869586279	F	1	50 OTH	SP	CCA		V	5/24/2048
2020 PO4867486272	LGE	3	50 OTH	SP	P	ED,SRS	TD	5/25/2048
2020 PO5811376202	LGE	4	35 OTH	SP	CCA		V	5/26/2048
2020 PO4658088950	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	5/27/2048
2020 PO4646988926	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	5/28/2048
2020 PO4925686813	LGE	3	45 OTH	SP	CCA		V	5/29/2048
2020 PO4173901682	F	4	40 BRO	SP	CRE		V	5/30/2048
2020 PO4194401782	F	4	40 BRO	SP	CRE		V	5/31/2048
2020 PO4212601869	F	4	40 BRO	SP	CRE		V	6/1/2048
2020 PO4229101953	F	4	40 BRO	SP	CCA		V	6/2/2048
2020 PO4272001879	F	5	35 BRO	SP	CCA		V	6/3/2048
2020 PO4925886817	LGE	3	45 OTH	SP	P	ID	BD	6/4/2048
2020 PO4926786833	LGE	3	45 OTH	SP	CCA		V	6/5/2048
2020 PO4928886826	LGE	3E	45E OTH	SP	P	ID,IP	BD	6/6/2048
2020 PO4875287745	LGE	4	45 XXX	SP	CRE	ID	BD	6/7/2048
2020 PO5724010981	KU	6	30 BRO	SP	CCA		V	6/8/2048
2020 PO5732611061	KU	4	40 BRO	SP	CCA		V	6/9/2048
2020 PO5764410815	KU	4	40 BRO	SP	CRE	ID	TD	6/10/2048
2020 PO5768310949	KU	6	30 BRO	SP	CCA		V	6/11/2048
2020 PO5763511036	KU	4	35 BRO	SP	CCA		V	6/12/2048
2020 PO5800111107	KU	6	30 BRO	SP	CCA		V	6/13/2048
2020 PO5797310952	KU	4	40 BRO	SP	CRE	ID	TD	6/14/2048
2020 PO5787810954	KU	6	30 BRO	SP	CRE	ID	BD	6/15/2048
2020 PO2495943742	KU	5	35 BRN	SP	CRE	ED,ID,MD,SRC	TD	6/16/2048
2020 PO2476443853	KU	4	40 BRN	SP	CRE	ED,ID,MD,SRC	TD	6/17/2048
2020 PO2454643977	KU	5	35 BRN	SP	CRE	ED,ID,IP,SRC	TD	6/18/2048
2020 PO7302492129	F	5	35 BRO	SP	CRE		V	6/19/2048
2020 PO7302192076	KU	6	30 BRO	SP	CRE	ED,ID	BD	6/20/2048

2020 PO2437244076	KU	4	40 BRN	SP	CRE	ID	BD	6/21/2048
2020 PO3397745044	KU	4	40 ACE	SP	CRE	ED,ID	TD	6/22/2048
2020 PO6664501866	F	4	40 BRO	SP	CRE		V	6/23/2048
2020 PO6663001742	F	5	35 BRO	SP	CRE		V	6/24/2048
2020 PO6666702213	F	4	40 BRO	SP	CRE		V	6/25/2048
2020 PO6646201240	F	4	40 BRO	SP	CRE		V	6/26/2048
2020 PO6656100997	F	4	40 BRO	SP	CRE		V	6/27/2048
2020 PO7510193071	KU	4	40 BRO	SP	CCA		V	6/28/2048
2020 PO7515293034	KU	4	40 BRO	SP	CRE	ED,ID	BD	6/29/2048
2020 PO7520692997	KU	4	40 BRO	SP	CCA		V	6/30/2048
2020 PO7525592963	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/1/2048
2020 PO7503293119	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/2/2048
2020 PO7532192918	KU	4	40 BRO	SP	CCA		V	7/3/2048
2020 PO7220389645	KU	5	35 BRO	SP	CRE	ED,ID,RB	TX	7/4/2048
2020 PO7227089650	KU	6	30 BRO	SP	P		V	7/5/2048
2020 PO6701502297	KU	6	30 BRO	SP	CCA		V	7/6/2048
2020 PO7101101771	KU	6	30 BRO	SP	CRE	ED,ID	TD	7/7/2048
2020 PO3408745234	KU	4	40 ACE	SP	CCA		V	7/8/2048
2020 PO2419844174	KU	4	40 BRN	SP	CRE	ED,EP,ID,IP,SRC	TD	7/9/2048
2020 PO2420443894	KU	5	35 BRN	SP	CRE	ID	BD	7/10/2048
2020 PO7081401669	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/11/2048
2020 PO7070701610	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/12/2048
2020 PO3356645622	KU	3	40 ACE	SP	CRE	ED,ID	TD	7/13/2048
2020 PO3341645625	KU	6	30 ACE	SP	CRE	ED,ID	BD	7/14/2048
2020 PO7057801543	KU	6	30 BRO	SP	CRE	ED,ID	TD	7/15/2048
2020 PO2337745082	KU	4	40 BRN	SP	CCA		V	7/16/2048
2020 PO3394045599	KU	6	30 ACE	SP	CRE	ED,ID	BD	7/17/2048
2020 PO3443445590	F	4	40 ACE	SP	P		V	7/18/2048
2020 PO3429045586	KU	2	50 ACE	SP	P		V	7/19/2048
2020 PO3441745775	KU	2	50 ACE	SP	P		V	7/20/2048
2020 PO6929301687A	KU	6	30 BRO	SP	CRE	ED,ID	TD	7/21/2048
2020 PO6922701743	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD	7/22/2048
2020 PO6929401651	KU	6	30 BRO	SP	CCA		V	7/23/2048
2020 PO6929301687	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/24/2048
2020 PO3628548800	KU	5	30 ACE	SP	CRE	ED,ID	TD	7/25/2048
2020 PO3449645902a	KU	6	30 ACE	SP	CCA		V	7/26/2048
2020 PO7533992906	KU	4	40 BRO	SP	CCA		V	7/27/2048
2020 PO2393455018	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	7/28/2048
2020 PO2267749947	KU	4	40 BRO	SP	CRE	ID	BD	7/29/2048
2020 PO2126650100	KU	4	40 BRO	SP	CRE	ID,IP	BD	7/30/2048
2020 PO2141750001	KU	4	40 BRO	SP	CRE	ID,IP	BD	7/31/2048
2020 PO2158249889	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/1/2048
2020 PO2389650547	KU	3	45 BRO	SP	CCA		V	8/2/2048
2020 PO2395050574	KU	3	45 BRO	SP	CCA		V	8/3/2048
2020 PO3449645902	KU	4	40 ACE	SP	CRE	ED,ID	TD	8/4/2048
2020 PO3417646111	KU	4	45 ACE	SP	CCA		V	8/5/2048
2020 PO3446045967	KU	4	45 ACE	SP	CCA		V	8/6/2048

2020 PO6913901788	KU	5	35 BRO	SP	CRE	ED,ID	TD		8/7/2048
2020 PO7277189519	KU	4	40 BRO	SP	CRE	ED,ID,RB	VX	RP1	8/8/2048
2020 PO3462646116	KU	4	40 ACE	SP	CRE	ED,EP,ID,IP	TD		8/9/2048
2020 PO6784102387	KU	6	30 BRO	SP	CRE	ED,ID	TD		8/10/2048
2020 PO6756402339B	KU	6	30 BRO	SP	CRE	ED,ID	TD		8/11/2048
2020 PO6756402339A	KU	5	35 BRO	SP	CRE	ED,ID	TD		8/12/2048
2020 PO2153150178	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD		8/13/2048
2020 PO2147350090	KU	5	35 BRO	SP	CRE		V		8/14/2048
2020 PO2237749953	KU	3	45 BRO	SP	P	ED	T		8/15/2048
2020 PO2255850370	KU	4	40 BRO	SP	CCA		V		8/16/2048
2020 PO2266650623	KU	3	45 BRO	SP	CCA		V		8/17/2048
2020 PO2270050707	KU	5	35 BRO	SP	CRE	ID,IP	BD		8/18/2048
2020 PO2406950734	KU	3	45 BRO	SP	CCA		V		8/19/2048
2020 PO3477446377	KU	4	40 ACE	SP	CRE	ED,ID	BD		8/20/2048
2020 PO3496246490	KU	4	40 ACE	SP	CRE	ED,ID	BD		8/21/2048
2020 PO3487646549	KU	5	40 ACE	SP	CRE	ED,EP,HH,ID,IP,MD	BX	RP1	8/22/2048
2020 PO2364545399	KU	4	40 BRN	SP	CRE	ED,ID,MD,SRS	TD		8/23/2048
2020 PO6699602576	KU	6	35 BRO	SP	CRE	ED,ID	TD		8/24/2048
2020 PO6707002511	KU	5	35 BRO	SP	CRE	ED,ID	TD		8/25/2048
2020 PO7231789813	F	5	35 BRO	SP	CRE		V		8/26/2048
2020 PO3967583152	LGE	4	35 BRO	SP	CCA	ED,HH,ID	BX	RP2	8/27/2048
2020 PO7250589699	F	3	40 BRO	SP	CRE		V		8/28/2048
2020 PO7270189688	F	6	30 BRO	SP	CRE		V		8/29/2048
2020 PO2324844929	KU	4	40 BRN	SP	CCA		V		8/30/2048
2020 PO3503146818	KU	4	40 ACE	SP	CRE	ED,ID	BD		8/31/2048
2020 PO3491047047	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		9/1/2048
2020 PO6647903152	KU	4	35 BRO	SP	CRE	ED,ID	TD		9/2/2048
2020 PO2348745212	KU	4	40 BRN	SP	CCA		V		9/3/2048
2020 PO2379245576	KU	6	30 BRN	SP	CRE	ID	BD		9/4/2048
2020 PO2420445290	KU	6	30 BRN	SP	CRE	ED,ID,SRC	TD		9/5/2048
2020 PO7256189855	KU	6	30 BRO	SP	CRE	ED,ID	TD		9/6/2048
2020 PO3519946867	KU	4	40 ACE	SP	CRE	ED,ID	TD		9/7/2048
2020 PO3525946973	F	4	45 ACE	SP	P		V		9/8/2048
2020 PO3531347068	KU	3	40 ACE	SP	P		V		9/9/2048
2020 PO3537447174	F	4	40 ACE	SP	P		V		9/10/2048
2020 PO7216489793	KU	4	45 BRO	SP	CRE	ED,ID	TD		9/11/2048
2020 PO7223089886	KU	4	45 BRO	SP	CRE	ED,ID	TD		9/12/2048
2020 PO7219389912	KU	6	30 BRO	SP	CRE	ED,ID	TD		9/13/2048
2020 PO2342344632	KU	4	40 BRN	SP	CRE	ID	BD		9/14/2048
2020 PO6597003435	KU	6	30 BRO	SP	CRE	ED,ID	TD		9/15/2048
2020 PO6631503137	KU	6	30 BRO	SP	CRE	ED,ID	TD		9/16/2048
2020 PO6589103224	KU	5	30 BRO	SP	CRE	ED,EP,HH,ID,IP	BX	PX	9/17/2048
2020 PO6550803514	KU	6	30 BRO	SP	CRE	ED,EP,ID	TX	RR	9/18/2048
2020 PO6603903074	KU	6	30 BRO	SP	CRE	ED,ID,RB	X	RP1	9/19/2048
2020 PO6628403158	KU	4	40 BRO	SP	CRE	ED,ID	TD		9/20/2048
2020 PO6629203242	KU	5	35 BRO	SP	CRE	ED,ID	TD		9/21/2048
2020 PO6564203330	KU	4	40 BRO	SP	CRE	ED,ID	TD		9/22/2048

2020 PO6636403186	F	4	40 BRO	SP	CRE		V		9/23/2048
2020 PO6576003320	KU	5	35 BRO	SP	CRE	ED,ID	TD		9/24/2048
2020 PO3543847284	KU	3	40 ACE	SP	P		V		9/25/2048
2020 PO2372444453	KU	4	30 BRN	SP	CRE	ED,ID,SRC	TD		9/26/2048
2020 PO2391944342	KU	4	40 BRN	SP	CCA		V		9/27/2048
2020 PO3551147415	KU	4	40 ACE	SP	CRE	ED,ID	TD		9/28/2048
2020 PO3560947572	F	4	40 ACE	SP	P		V		9/29/2048
2020 PO6855919533	KU	6	30 XXX	SP	CRE		V		9/30/2048
2020 PO6859219629	KU	4	40 XXX	SP	CRE	ID	TD		10/1/2048
2020 PO6864719685	KU	4	40 XXX	SP	CRE	ID	TD		10/2/2048
2020 PO6872519768	KU	4	40 XXX	SP	CRE	ID	TD		10/3/2048
2020 PO6875619794	KU	6	30 XXX	SP	CRE	ID	TD		10/4/2048
2020 PO6879519838A	KU	6	30 XXX	SP	CRE	HH	X	RP2	10/5/2048
2020 PO6879519838	KU	4	40 XXX	SP	CRE	HH,ID	X	RP2	10/6/2048
2020 PO6880318681	KU	6	30 XXX	SP	CCA		V		10/7/2048
2020 PO6834818725	KU	6	30 XXX	SP	CRE		V		10/8/2048
2020 PO4276631960	KU	2	50 BRO	SP	CCA		V		10/9/2048
2020 PO4282132100	KU	2	50 BRO	SP	CCA		V		10/10/2048
2020 PO4286132211	KU	2	50 BRO	SP	CCA		V		10/11/2048
2020 PO4292532365	KU	2	50 BRO	SP	CCA		V		10/12/2048
2020 PO4297732500	KU	2	50 BRO	SP	CCA		V		10/13/2048
2020 PO4302532625	KU	2	50 BRO	SP	CCA		V		10/14/2048
2020 PO4307932775	KU	2	50 BRO	SP	CCA		V		10/15/2048
2020 PO3790743605	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD		10/16/2048
2020 PO7046094552	KU	4	40 BRN	SP	CRE	ED,ID	TD		10/17/2048
2020 PO7037594435	KU	4	40 BRN	SP	CRE	ED,ID	TD		10/18/2048
2020 PO6974594488	KU	5	35 BRN	SP	CRE	ED,ID	TD		10/19/2048
2020 PO6975494596	KU	4	40 BRN	SP	CRE	ED,ID	TD		10/20/2048
2020 PO7001294689	KU	4	40 BRN	SP	CRE	ED,ID	BD		10/21/2048
2020 PO6992194677	KU	4	45 BRN	SP	CCA		V		10/22/2048
2020 PO2929338415	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		10/23/2048
2020 PO7135491049	F	5	35 BRO	SP	CRE		V		10/24/2048
2020 PO7144991001	KU	4	40 BRO	SP	CRE	ED,ID	TD		10/25/2048
2020 PO7147691054	KU	5	35 BRO	SP	CRE	ED,ID	TD		10/26/2048
2020 PO6366403480	KU	6	30 XXX	SP	CRE	ED,ID	TD		10/27/2048
2020 PO6364703409	KU	4	40 XXX	SP	CRE	ED,ID	TD		10/28/2048
2020 PO6376603322	KU	4	40 XXX	SP	CRE	ED,ID	TD		10/29/2048
2020 PO3809643888	KU	4	40 ACE	SP	CRE	ED,ID	TD		10/30/2048
2020 PO3826344137	KU	4	40 ACE	SP	CRE	ED,ID	TD		10/31/2048
2020 PO4338132759	KU	2	50 BRO	SP	CCA		V		11/1/2048
2020 PO4350932707	KU	2	50 BRO	SP	CCA		V		11/2/2048
2020 PO4354432481	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		11/3/2048
2020 PO4361332613	KU	2	50 BRO	SP	CCA		V		11/4/2048
2020 PO4356032815	KU	2	50 BRO	SP	CCA		V		11/5/2048
2020 PO4357932792	F	3	45 BRO	SP	P		V		11/6/2048
2020 PO4365232720	F	3	50 BRO	SP	P		V		11/7/2048
2020 PO4373232631	F	3	50 BRO	SP	P		V		11/8/2048

2020 PO4395432429	KU	3	50 BRO	SP	P		ED	TD	11/9/2048
2020 PO4407332356	KU	3	45 BRO	SP	P		ED	TD	11/10/2048
2020 PO4428432254	KU	4	40 BRO	SP	CCA			V	11/11/2048
2020 PO2893438198	KU	4	40 BRN	SP	CRE		ED,ID,SRC	TD	11/12/2048
2020 PO6155212746	KU	6	30 BRO	SP	CCA			V	11/13/2048
2020 PO6160912563	KU	4	45 BRO	SP	CCA			V	11/14/2048
2020 PO6154912671	KU	4	40 BRO	SP	CCA			V	11/15/2048
2020 PO6118712674	KU	4	45 BRO	SP	CCA			V	11/16/2048
2020 PO6122112801	KU	4	40 BRO	SP	CCA			V	11/17/2048
2020 PO6110512851	KU	4	40 BRO	SP	CCA			V	11/18/2048
2020 PO6091212919	KU	4	40 BRO	SP	CCA			V	11/19/2048
2020 PO6070412926	KU	4	40 BRO	SP	CCA			V	11/20/2048
2020 PO6047512931	KU	4	40 BRO	SP	CRE		ID	TD	11/21/2048
2020 PO6001312913	KU	6	30 BRO	SP	CRE		ID	TD	11/22/2048
2020 PO6015512894	KU	5	35 BRO	SP	CRE		ID	TD	11/23/2048
2020 PO6021612820	KU	3	45 BRO	SP	CCA			V	11/24/2048
2020 PO6036212909	KU	3	45 BRO	SP	CCA			V	11/25/2048
2020 PO6038712918	KU	3	45 BRO	SP	CCA			V	11/26/2048
2020 PO6043612729	KU	3	50 BRO	SP	CRE		ID	TD	11/27/2048
2020 PO6014912589	KU	4	40 BRO	SP	CRE		ID	BD	11/28/2048
2020 PO6017612407	KU	4	40 BRO	SP	CRE		ID	TD	11/29/2048
2020 PO6021012333	KU	3	50 BRO	SP	CCA			V	11/30/2048
2020 PO6036712436	KU	3	50 BRO	SP	CCA			V	12/1/2048
2020 PO6044512476	KU	3	50 BRO	SP	CCA			V	12/2/2048
2020 PO6058312452	F	2	55 BRO	SP	A			V	12/3/2048
2020 PO5965212253	KU	6	30 BRO	SP	CRE		ID	TD	12/4/2048
2020 PO5954312356	KU	5	35 BRO	SP	CRE		ID	TD	12/5/2048
2020 PO5958012407	F	4	40 BRO	SP	CRE			V	12/6/2048
2020 PO5944512452	KU	5	30 BRO	SP	CRE		ID	TD	12/7/2048
2020 PO5943712330	KU	6	30 BRO	SP	CRE			V	12/8/2048
2020 PO5976912388	KU	5	35 BRO	SP	CRE		ID	TD	12/9/2048
2020 PO5967312513	KU	4	40 BRO	SP	CRE		ID	TD	12/10/2048
2020 PO5990512341	KU	6	30 BRO	SP	CRE		ID	TD	12/11/2048
2020 PO5981412390	F	4	40 BRO	SP	CRE			V	12/12/2048
2020 PO5996812272	KU	6	30 BRO	SP	CRE			V	12/13/2048
2020 PO5988112469	KU	5	30 BRO	SP	CRE		ID	TD	12/14/2048
2020 PO5978612450	KU	6	30 BRO	SP	CRE		ID	TD	12/15/2048
2020 PO5978412498	KU	6	30 BRO	SP	CRE		ID	TD	12/16/2048
2020 PO5973112549	KU	5	30 BRO	SP	CRE			V	12/17/2048
2020 PO5975412620	KU	4	40 BRO	SP	CRE		ID	TD	12/18/2048
2020 PO5969912687	KU	5	30 BRO	SP	CRE		ID	TD	12/19/2048
2020 PO5968312621	KU	6	30 BRO	SP	CRE		ID	TD	12/20/2048
2020 PO7307489895	KU	6	30 BRO	SP	CRE		ED,ID	BD	12/21/2048
2020 PO7272390386	KU	4	40 BRO	SP	CRE			V	12/22/2048
2020 PO6818701479	KU	4	40 XXX	SP	CCA			V	12/23/2048
2020 PO6820301551	F	4	40 XXX	SP	CRE			V	12/24/2048
2020 PO6798401554	F	4	40 XXX	SP	CRE			V	12/25/2048

2020 PO6819701642	KU	5	35 XXX	SP	CRE		V	12/26/2048
2020 PO6394103473	F	6	30 BRN	SP	CRE		V	12/27/2048
2020 PO6394603355	F	6	30 XXX	SP	CRE		V	12/28/2048
2020 PO6397003260	F	6	30 BRO	SP	CRE		V	12/29/2048
2020 PO6408903066	F	4	40 BRO	SP	CRE		V	12/30/2048
2020 PO6421903057	KU	6	30 BRO	SP	CRE	ED,ID	TD	12/31/2048
2020 PO7356391339	KU	4	40 BRO	SP	CRE		V	1/1/2049
2020 PO7346391234	KU	4	40 BRO	SP	CRE		V	1/2/2049
2020 PO7334991120	KU	4	40 BRO	SP	CRE		V	1/3/2049
2020 PO7326391030	KU	4	40 BRO	SP	CRE		V	1/4/2049
2020 PO7316390931	KU	4	40 BRO	SP	CRE		V	1/5/2049
2020 PO6915801304	F	4	40 XXX	SP	CRE		V	1/6/2049
2020 PO6913201121	F	4	40 XXX	SP	CRE		V	1/7/2049
2020 PO6909300810	F	4	40 XXX	SP	CRE		V	1/8/2049
2020 PO6911600684	F	4	40 XXX	SP	CRE		V	1/9/2049
2020 PO6779101558	F	4	40 XXX	SP	CRE		V	1/10/2049
2020 PO6916901402	F	4	40 XXX	SP	CCA		V	1/11/2049
2020 PO6910600586	F	4	40 XXX	SP	CRE		V	1/12/2049
2020 PO7313089445	KU	4	40 BRO	SP	CCA		V	1/13/2049
2020 PO7461092426	F	3	40 BRO	SP	CRE		V	1/14/2049
2020 PO7460992453	F	4	40 BRO	SP	S		V	1/15/2049
2020 PO7485892281	F	3	40 BRO	SP	CRE		V	1/16/2049
2020 PO7472892356	F	3	40 BRO	SP	CRE	ED,ID	VX	1/17/2049
2020 PO7505892796	LGE	3	40 BRO	SP	P	ED,ID	BD	1/18/2049
2020 PO7489092824	F	4	40 BRO	SP	CRE		V	1/19/2049
2020 PO6990094813	KU	6	30 BRN	SP	CRE		V	1/20/2049
2020 PO7013095180	KU	4	40 BRN	SP	CRE	ED,ID	TD	1/21/2049
2020 PO7061794973	KU	3	50 BRN	SP	CCA		V	1/22/2049
2020 PO7058094991	KU	1	80 BRN	SP	CRE		V	1/23/2049
2020 PO2981138672	KU	4	40 BRN	SP	CRE	ID	BD	1/24/2049
2020 PO6231802232	KU	6	30 BRO	SP	CCA		V	1/25/2049
2020 PO6226902217	KU	4	40 BRO	SP	CCA		V	1/26/2049
2020 PO6232102530	KU	4	40 BRO	SP	CCA		V	1/27/2049
2020 PO6237502792	KU	5	35 XXX	SP	CRE		V	1/28/2049
2020 PO3311543383	KU	4	40 ACE	SP	CRE	ED,ID	TD	1/29/2049
2020 PO3329343579	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	1/30/2049
2020 PO3206342031	KU	4	40 ACE	SP	CRE	ED,ID	TD	1/31/2049
2020 PO2952838560	KU	4	40 BRN	SP	CRE	ID	BD	2/1/2049
2020 PO2876538090	KU	4	40 BRN	SP	CRE	ID	BD	2/2/2049
2020 PO7470192574	F	3	40 BRO	SP	CRE		V	2/3/2049
2020 PO7479992698	F	3	40 BRO	SP	CRE		V	2/4/2049
2020 PO7492692878	F	3	40 BRO	SP	CRE		V	2/5/2049
2020 PO7484492927	F	4	40 BRO	SP	CCA		V	2/6/2049
2020 PO2854637969	KU	4	40 BRN	SP	CRE	ID,IP	BD	2/7/2049
2020 PO3028440619	KU	4	35 BRN	SP	CRE	ID,IP	BD	2/8/2049
2020 PO7143391198	KU	5	30 BRO	SP	P	ED,ID	TD	2/9/2049
2020 PO7116591347	KU	5	35 BRO	SP	CRE	ED,ID	TD	2/10/2049

2020 PO7108591383	KU	5	35 BRO	SP	CRE	ED,ID	TD	2/11/2049
2020 PO6245203064	KU	4	40 XXX	SP	CRE	ED,ID	TD	2/12/2049
2020 PO6241603183	KU	4	40 XXX	SP	CRE	ED,ID	TD	2/13/2049
2020 8671624536A	KU	6	30 BRN	SP	CCA		V	2/14/2049
2020 A	KU	5	35 UNK	SP	CCA		V	2/15/2049
2020 PO7601683140-A	KU	6	30 BRN	SP	CRE	ED,ID	BD	2/16/2049
2020 PO7605582574	KU	4	45 BRN	SP	CCA		V	2/17/2049
2020 PO7611082592	KU	4	40 BRN	SP	CRE	ED,ID	BD	2/18/2049
2020 PO7628482413	KU	5	35 BRN	SP	CRE	ED,ID	TD	2/19/2049
2020 PO7633382342	KU	4	40 BRN	SP	CRE	ED,ID	TD	2/20/2049
2020 PO76161823420-A	KU	6	30 BRN	SP	CRE	ED,ID	TD	2/21/2049
2020 PO7616182320	KU	4	40 BRN	SP	CRE	ED,ID	TD	2/22/2049
2020 PO7655282493	KU	5	35 BRN	SP	CCA		V	2/23/2049
2020 PO5534810321	F	6	30 BRO	SP	A		V	2/24/2049
2020 PO2415655438	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	2/25/2049
2020 PO7731782236	KU	3	45 BRN	SP	CCA		V	2/26/2049
2020 PO8028974134	KU	6	30 BRO	SP	CRE	ED,ID	TD	2/27/2049
2020 PO8023874225	KU	4	45 BRO	SP	CRE	ID	BD	2/28/2049
2020 PO8051974375	KU	4	40 BRO	SP	CRE		V	3/1/2049
2020 PO7709282058	KU	6	30 BRN	SP	CRE	ED,ID	TD	3/2/2049
2020 PO7703482075	F	4	45 BRN	SP	CRE		V	3/3/2049
2020 PO7697382435	F	3	45 BRN	SP	CRE		V	3/4/2049
2020 PO7700882229	F	3	45 BRN	SP	CRE		V	3/5/2049
2020 PO5255407317	KU	4	40 BRN	SP	CRE	ED,ID	TD	3/6/2049
2020 PO5271507353	KU	6	30 XXX	SP	CRE	ED,ID	TD	3/7/2049
2020 PO8041774423	KU	6	30 BRO	SP	CRE	ED,ID	TD	3/8/2049
2020 PO8067874460	KU	5	40 BRO	SP	CRE	ID	BD	3/9/2049
2020 PO8072474570	KU	4	45 BRO	SP	CRE		B	3/10/2049
2020 PO7682982234	KU	6	30 BRN	SP	CRE	ED,ID	BD	3/11/2049
2020 PO7684382110	KU	6	30 BRN	SP	CRE	ED,ID	TD	3/12/2049
2020 PO7653481978	KU	4	40 BRN	SP	CRE	ED,ID	BD	3/13/2049
2020 PO5282907260	KU	4	40 XXX	SP	CRE	ED,ID	TD	3/14/2049
2020 PO5431909349	KU	4	40 BRO	SP	CRE	ID	BD	3/15/2049
2020 PO7926174042	KU	4	40 BRO	SP	CRE	ID	BD	3/16/2049
2020 PO7931474071	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/17/2049
2020 PO7942174317	KU	6	30 BRO	SP	CRE		B	3/18/2049
2020 PO7949174186	KU	6	30 BRO	SP	CRE		B	3/19/2049
2020 PO7946274241	KU	4	40 BRO	SP	CRE		B	3/20/2049
2020 PO5253006944	KU	5	35 XXX	SP	CRE		V	3/21/2049
2020 PO5210007000	KU	6	30 XXX	SP	CCA		V	3/22/2049
2020 PO8444367105	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/23/2049
2020 PO8439467144	KU	6	30 BRO	SP	CCA		V	3/24/2049
2020 PO8433466938	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/25/2049
2020 PO8422566774	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/26/2049
2020 PO8413966657	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/27/2049
2020 PO0800061998	KU	4	45 BRN	SP	CRE	ID	TD	3/28/2049
2020 PO0779662099	KU	4	45 BRN	SP	CRE	ID	BD	3/29/2049

2020 PO0773762048	KU	2	50 BRN	SP	CCA		V			3/30/2049
2020 PO0775262121	KU	2	50 BRN	SP	CCA		V			3/31/2049
2020 PO0764662172	KU	3	50 BRN	SP	CCA	ED	BD			4/1/2049
2020 PO0735362316	KU	4	45 BRN	SP	CRE	ID,IP	TD			4/2/2049
2020 PO0707762395	KU	4	45 BRN	SP	CRE	ID,IP	TD			4/3/2049
2020 PO0691762515	KU	4	45 BRN	SP	CRE	ID	TD			4/4/2049
2020 PO0682562587	KU	4	45 BRN	SP	CCA	ED	TD			4/5/2049
2020 PO0672562447	KU	6	30 BRN	SP	CCA		V			4/6/2049
2020 PO0672462661	KU	4	45 BRN	SP	CRE	ID	TD			4/7/2049
2020 PO0741464052	KU	4	40 BRN	SP	CRE	ID,IP	TD			4/8/2049
2020 PO0708464254	KU	6	30 BRN	SP	CRE	ID	TD			4/9/2049
2020 PO0733064085	KU	6	30 BRN	SP	CRE	ID	BD			4/10/2049
2020 PO0704764187	KU	6	30 BRN	SP	CCA		V			4/11/2049
2020 PO7653282374	KU	4	40 BRN	SP	CRE	ED,HH,ID	BX	PX		4/12/2049
2020 PO0710664165	KU	3	45 BRN	SP	CCA		V			4/13/2049
2020 PO0702863982	KU	3	45 BRN	SP	CCA		V			4/14/2049
2020 PO0690663698	KU	4	45 BRN	SP	CRE	ID	TD			4/15/2049
2020 PO0687663627	KU	4	40 BRN	SP	CRE	ID	TD			4/16/2049
2020 PO0700363927	KU	4	45 BRN	SP	CRE	ID	BD			4/17/2049
2020 PO0678663588	KU	5	35 BRN	SP	CCA		V			4/18/2049
2020 PO0683963544	KU	4	40 BRN	SP	CCA		V			4/19/2049
2020 PO0679063435	KU	4	40 BRN	SP	CRE	ID,IP	TD			4/20/2049
2020 PO0674963342	KU	4	40 BRN	SP	CRE	ID	TD			4/21/2049
2020 PO0672863295	KU	4	40 BRN	SP	CRE	ID,IP	TD			4/22/2049
2020 PO0670663241	KU	4	40 BRN	SP	CRE	ID,IP	TD			4/23/2049
2020 PO0663763079	KU	4	45 BRN	SP	CRE	ID	TD			4/24/2049
2020 PO0663763079-A	KU	5 30E	BRN	SP	P	ID	BD			4/25/2049
2020 PO0664563026	KU	5	35 BRN	SP	CRE	ID	TD			4/26/2049
2020 PO0658162961	KU	4	40 BRN	SP	CRE	ID,IP	BD			4/27/2049
2020 PO0668462865	KU	5	35 BRN	SP	CRE	ID	TD			4/28/2049
2020 PO0665562794	KU	5	35 BRN	SP	CRE	ID	TD			4/29/2049
2020 PO7661383075	KU	4	40 BRN	SP	CRE		V			4/30/2049
2020 PO7664583152	KU	4	40 BRN	SP	CRE	ED,ID	BD			5/1/2049
2020 PO7693982991	KU	4	45 BRN	SP	CRE	ED,ID,IP,MD	TD			5/2/2049
2020 PO7717182988	KU	4	45 BRN	SP	CRE		V			5/3/2049
2020 PO7727282797	KU	4	40 BRN	SP	CCA		V			5/4/2049
2020 PO5386508370	KU	3	45 BRO	SP	CRE		V			5/5/2049
2020 PO5393308290	KU	3	45 BRO	SP	CCA		V			5/6/2049
2020 PO5383208122	KU	3	45 BRO	SP	CCA		V			5/7/2049
2020 PO5373008025	F	4	40 BRO	SP	CRE		V			5/8/2049
2020 PO5388808215	KU	5	35 BRO	SP	CRE	ID	TD			5/9/2049
2020 PO5366907982	KU	5	35 BRO	SP	CRE	ID	TD			5/10/2049
2020 PO5369808072	KU	4	40 BRO	SP	CRE	ID	TD			5/11/2049
2020 PO5353008468	KU	6	30 BRO	SP	CRE	ID	TD			5/12/2049
2020 PO5359108517	KU	6	30 BRO	SP	CRE	ID	TD			5/13/2049
2020 PO5355308611	KU	6	30 BRO	SP	CCA		V			5/14/2049
2020 PO5361408674	KU	4	40 BRO	SP	CRE	ID	TD			5/15/2049

2020 PO7729282434	KU	3	45 BRN	SP	CCA		V		5/16/2049
2020 PO0750590027	KU	5	35 BRO	SP	CRE		V		5/17/2049
2020 PO7523882111	F	4	40 BRN	SP	CRE		VX	PX	5/18/2049
2020 PO0777490763	KU	5	35 BRO	SP	CRE		V		5/19/2049
2020 PO0760391054	KU	4	40 BRO	SP	CRE		V		5/20/2049
2020 PO0797191237	KU	4	40 BRO	SP	CRE		V		5/21/2049
2020 PO0811791599	KU	4	40 BRO	SP	CRE		V		5/22/2049
2020 PO0869392310	KU	5	35 BRO	SP	CRE		V		5/23/2049
2020 PO0953792355	KU	5	35 BRO	SP	CRE	ED,ID		TD	5/24/2049
2020 PO9370194792	KU	4	40 BRO	SP	CCA		V		5/25/2049
2020 PO0941890827	KU	4	40 BRO	SP	CRE	ED,ID,SRS		TD	5/26/2049
2020 PO0206906844	F	4	40 BRO	SP	CRE		V		5/27/2049
2020 PO0220006825	F	4	40 BRO	SP	CRE		V		5/28/2049
2020 PO9354295002	KU	6	35 BRO	SP	CRE	ED,ID,IP		TD	5/29/2049
2020 PO9370595009	KU	4	40 BRO	SP	CRE	ED,ID,IP		TD	5/30/2049
2020 PO9367595159	KU	6	30 BRO	SP	CRE	ED,ID,IP		TD	5/31/2049
2020 PO9371395279	KU	4	40 BRO	SP	CRE	ED,ID		TD	6/1/2049
2020 PO0578414860	KU	4	40 BRO	SP	CRE	ED,ID,SRS		TD	6/2/2049
2020 PO0605314913	KU	5	35 BRO	SP	CRE	ED,ID,SRS		TD	6/3/2049
2020 PO7516781708	KU	3	50 BRN	SP	CCA		V		6/4/2049
2020 PO7523781498	KU	6	30 BRN	SP	CRE		V		6/5/2049
2020 PO7504981538	KU	4	45 BRN	SP	CRE		V		6/6/2049
2020 PO7503981366	F	3	55 BRN	SP	CCA		V		6/7/2049
2020 PO7526981296	KU	6	30 BRN	SP	CRE	ED,ID		BD	6/8/2049
2020 PO7521981232	KU	4	45 BRN	SP	CCA		V		6/9/2049
2020 PO7573281599	KU	4	45 BRN	SP	CRE	ED,ID		TD	6/10/2049
2020 PO7570381595	KU	4	45 BRN	SP	CRE	ED,ID		BD	6/11/2049
2020 PO7555981566	KU	4	45 BRN	SP	CCA		V		6/12/2049
2020 PO7597881338	KU	5	35 BRN	SP	CCA		V		6/13/2049
2020 PO7574881324	KU	5	35 BRN	SP	CCA		V		6/14/2049
2020 PO7587981393	KU	5	35 BRN	SP	CCA		V		6/15/2049
2020 PO5177506748	KU	4	40 BRN	SP	CRE	ED,ID		TD	6/16/2049
2020 PO5173706698	KU	4	40 XXX	SP	CRE	ED,ID		TD	6/17/2049
2020 PO5164206715	KU	7	25 XXX	SP	CRE	ED,ID		TD	6/18/2049
2020 PO0642414760	KU	5	35 BRO	SP	CRE	ED,ID,SRS		TD	6/19/2049
2020 PO5146706682	KU	4	35 XXX	SP	CRE	ED,ID		TD	6/20/2049
2020 PO0706815363	KU	6	30 BRO	SP	CRE	ED,ID,SRS		TD	6/21/2049
2020 PO9537494232	F	5	35 BRO	SP	CRE		V		6/22/2049
2020 PO9540894489	KU	6	30 BRO	SP	CRE	ED,ID		TD	6/23/2049
2020 PO9537894123	KU	5	35 BRO	SP	CRE	ED,ID		TD	6/24/2049
2020 PO9555394166	KU	4	40 BRO	SP	CRE	ED,ID		BD	6/25/2049
2020 PO9568694021	KU	4	40 BRO	SP	CRE	ED,ID,IP		TD	6/26/2049
2020 PO9494293436	KU	4	40 BRO	SP	CRE	ED,EP,ID,IP		V	6/27/2049
2020 PO0700615246	F	4	40 BRO	SP	CRE	EP,RB		VX	6/28/2049
2020 PO0727315576	KU	5	35 BRO	SP	CRE	ED,ID,SRS		TD	6/29/2049
2020 PO0805915639	KU	6	30 BRO	SP	CRE	ED,ID,SRS		TD	6/30/2049
2020 PO0775116130	KU	5	45 BRO	SP	CRE	ED,ID,SRS		TD	7/1/2049

2020 PO0793815727	F	4	40 BRO	SP	CRE		V		7/2/2049
2020 PO0757416482	KU	4	40 BRO	SP	CRE	ID	BD		7/3/2049
2020 PO0743915424	F	4	40 BRO	SP	CCA		V		7/4/2049
2020 PO9261381347	KU	4	40 OTH	SP	CRE	ID	BD		7/5/2049
2020 PO9252381499	KU	4	40 OTH	SP	CRE	ED	TD		7/6/2049
2020 PO9267481192	KU	4	40 OTH	SP	CRE	ID	BD		7/7/2049
2020 PO9248781570	KU	4	40 OTH	SP	CRE	ED,ID	TX	RR	7/8/2049
2020 PO9235081578	KU	4	40 OTH	SP	CRE	ED	TD		7/9/2049
2020 PO9217181656	KU	4	40 OTH	SP	CRE	ED,ID,IP	TD		7/10/2049
2020 PO9206681737	KU	4	40 OTH	SP	CRE	ED,ID,IP	TD		7/11/2049
2020 PO9085277449	KU	4	40 OTH	SP	CRE	ED,ID,IP	TD		7/12/2049
2020 PO9123177227	KU	4	45 OTH	SP	CRE	HH,RB	X	RP1	7/13/2049
2020 PO9107077242	KU	4	45 OTH	SP	CRE		T		7/14/2049
2020 PO9087977266	KU	4	45 OTH	SP	CRE		T		7/15/2049
2020 PO9087277651	KU	3	45 OTH	SP	CCA		V		7/16/2049
2020 PO9242677161	KU	4	40 BRO	SP	CRE	ID,IP	BD		7/17/2049
2020 PO9235076916	KU	4	40 BRO	SP	CRE	RB	X	RP1	7/18/2049
2020 PO9122480517	KU	4	40 BRO	SP	CRE	ID,IP	BD		7/19/2049
2020 PO9112480402	KU	4	40 BRO	SP	CRE	ID	BD		7/20/2049
2020 PO9103280482	KU	4	40 BRO	SP	CRE	ID,IP	BD		7/21/2049
2020 PO9125780667	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD		7/22/2049
2020 PO8867882659	KU	3	50 BRO	SP	CRE		V		7/23/2049
2020 PO8883482524	KU	3	45 BRO	SP	CRE		V		7/24/2049
2020 PO8900382378	KU	3	45 BRO	SP	P	ED	T		7/25/2049
2020 PO8932582104	KU	3	45 BRO	SP	CCA		V		7/26/2049
2020 PO8917882230	KU	4	45 BRO	SP	CCA		V		7/27/2049
2020 PO8945981989	KU	3	45 BRO	SP	CRE	ID,IP	BD		7/28/2049
2020 PO8960681862	KU	3	45 BRO	SP	CCA		V		7/29/2049
2020 PO8976381730	KU	3	45 BRO	SP	CRE		V		7/30/2049
2020 PO8992381595	KU	3	45 BRO	SP	CCA		V		7/31/2049
2020 PO9007081472	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD		8/1/2049
2020 PO9882584464	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD		8/2/2049
2020 PO9880484479	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD		8/3/2049
2020 PO9865984573	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD		8/4/2049
2020 PO9848484975	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		8/5/2049
2020 PO5162106892	KU	4	40 XXX	SP	CRE	ED,ID	TD		8/6/2049
2020 PO5117807177	KU	6	30 XXX	SP	CRE	ED,ID	TD		8/7/2049
2020 PO5131407108	KU	4	40 XXX	SP	CRE	ED,ID	TD		8/8/2049
2020 PO5172506953	KU	6	30 XXX	SP	CRE		V		8/9/2049
2020 PO8061775196	KU	4	45 BRO	SP	CRE	ED,ID	TD		8/10/2049
2020 PO8046275297	KU	3	45 BRO	SP	CCA		V		8/11/2049
2020 PO8049775421	KU	3	45 BRO	SP	CCA		V		8/12/2049
2020 PO8036175450	KU	6	30 BRO	SP	CRE	ED,ID	TD		8/13/2049
2020 PO7560781150	KU	6	30 BRN	SP	CCA		V		8/14/2049
2020 PO0224052426	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD		8/15/2049
2020 PO1058571541	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		8/16/2049
2020 PO0940357613	F	4	40 ACW	SP	P		V		8/17/2049

2020 PO0931957743	KU	4	40 ACW	SP	CCA		V		8/18/2049
2020 PO0924657867	F	4	40 ACW	SP	CCA		V		8/19/2049
2020 PO0916457982	F	4	40 ACW	OT	CRE		V		8/20/2049
2020 PO0903858091	F	4	40 ACW	SP	CRE		V		8/21/2049
2020 PO0892258199	F	4	40 ACW	SP	CRE	ED,EP,HH,ID,IP,RB	VX	PX	8/22/2049
2020 PO0888458152	F	5	35 ACW	SP	CRE		V		8/23/2049
2020 PO0877058272	F	5	35 ACW	SP	CRE		V		8/24/2049
2020 PO0880958319	F	4	40 ACW	SP	CRE		V		8/25/2049
2020 PO0871058438	F	4	40 ACW	SP	CRE		V		8/26/2049
2020 PO0860858467	KU	6	30 ACW	SP	CCA		V		8/27/2049
2020 PO0861958562	F	4	40 ACW	SP	CRE		V		8/28/2049
2020 PO0851458672	F	4	40 ACW	SP	CRE		V		8/29/2049
2020 PO0847358628	KU	4	40 ACW	SP	CRE	ED,ID,IP	BD		8/30/2049
2020 PO0862558761	KU	3	45 ACW	SP	CCA		V		8/31/2049
2020 PO0845358726	KU	3	45 ACW	SP	CCA		V		9/1/2049
2020 PO0837658709	KU	6	30 ACW	SP	CCA		V		9/2/2049
2020 PO0826058782	KU	3	45 ACW	SP	CCA		V		9/3/2049
2020 PO0823558800	KU	3	45 ACW	SP	CCA		V		9/4/2049
2020 PO0827058867	KU	3	45 ACW	SP	CCA		V		9/5/2049
2020 PO0798358974	KU	4	40 ACW	SP	CCA		V		9/6/2049
2020 PO0766959280	KU	4	40 ACW	SP	CCA		V		9/7/2049
2020 PO1892258600	KU	6 35E	BRN	SP	CRE	ED,ID,IP	TD		9/8/2049
2020 PO1865358743	KU	5 35E	BRN	SP	CRE	ID,IP	TD		9/9/2049
2020 PO2139457672	KU	6	30 BRN	SP	CRE	ED,HH	X	RP2	9/10/2049
2020 PO0756659097	F	4	40 ACW	SP	CRE		V		9/11/2049
2020 PO0749758963	F	4	40 ACW	SP	P		V		9/12/2049
2020 PO0741358798	F	4	40 ACW	SP	CRE		V		9/13/2049
2020 PO0739358790	F	4	40 ACW	SP	CRE		V		9/14/2049
2020 PO0731358834	F	4	40 ACW	OT	CRE		V		9/15/2049
2020 PO0716858915	F	4	40 ACW	SP	CRE		V		9/16/2049
2020 PO0703158993	F	4	40 ACW	SP	P		V		9/17/2049
2020 PO0691359058	F	4	40 ACW	OT	CRE		V		9/18/2049
2020 PO0678159131	F	4	40 ACW	SP	CRE	ED,ID	V		9/19/2049
2020 PO0225751659	KU	4	40 BRO	SP	CCA		V		9/20/2049
2020 PO0195652222	F	4	40 BRO	SP	CRE		V		9/21/2049
2020 PO0184152176	F	4	40 BRO	SP	CRE		V		9/22/2049
2020 PO0194651949	KU	4	40 BRO	SP	CRE	ID	BD		9/23/2049
2020 PO0174551647	F	5	35 BRO	SP	CRE		V		9/24/2049
2020 PO0669359181	F	4	40 ACW	SP	CRE		V		9/25/2049
2020 PO0662759218	F	4	40 ACW	SP	CRE		V		9/26/2049
2020 PO0661859249	F	4	40 ACW	SP	CRE		V		9/27/2049
2020 PO0666659361	F	4	40 ACW	SP	CRE		V		9/28/2049
2020 PO0243751350	KU	4	40 BRO	SP	CRE	ED,HH,ID,RB	X	RP2	9/29/2049
2020 PO0264751261	KU	4	40 BRO	SP	CRE	ED,ID,src	TD		9/30/2049
2020 PO2294958368	KU	5	35 BRN	SP	CRE	ID,IP	TD		10/1/2049
2020 PO2317058629	KU	4	40 BRN	SP	CCA		V		10/2/2049
2020 PO2371958700	F	4	40 BRN	SP	CRE		V		10/3/2049

2020 PO0975372966	KU	3	50 BRO	SP	CRE	ED,ID	TD	10/4/2049
2020 PO0966972731	KU	3	50 BRO	SP	CRE	ED	TD	10/5/2049
2020 PO9381362315	KU	4	40 ACW	SP	CRE	ED,ID	BD	10/6/2049
2020 PO9381062206	KU	4	45 ACW	SP	CCA		V	10/7/2049
2020 PO9380461824	KU	4	45 ACW	SP	CCA		V	10/8/2049
2020 PO9382761743	F	4	40 ACW	SP	P		V	10/9/2049
2020 PO9417261607	F	4	40 ACW	SP	P		V	10/10/2049
2020 PO9452561525	KU	5	35 ACW	SP	CCA		V	10/11/2049
2020 PO9457061508	F	5	30 ACW	SP	CRE		V	10/12/2049
2020 PO9455161458	F	4	40 ACW	SP	CRE	ED,ID	V	10/13/2049
2020 PO2335258212	KU	7	30 BRN	SP	CRE	ID	TD	10/14/2049
2020 PO9500061279	F	4	40 ACW	SP	CRE		V	10/15/2049
2020 PO9526861190	F	4	40 ACW	SP	CRE		V	10/16/2049
2020 PO9557161087	F	4	40 ACW	SP	P		V	10/17/2049
2020 PO1820946028	KU	3	40 BRN	SP	CCA		V	10/18/2049
2020 PO1840545939	KU	4	40 BRN	SP	CRE	ID,IP	TD	10/19/2049
2020 PO1855346091	KU	5	30 BRN	SP	CRE	ID	TD	10/20/2049
2020 PO1849246120	KU	4	40 BRN	SP	CRE	ED,ID	TD	10/21/2049
2020 PO9794052245	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD	10/22/2049
2020 PO9784651977	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD	10/23/2049
2020 PO9802051898	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD	10/24/2049
2020 PO1873246574	KU	4	40 BRN	SP	CRE	ID,IP	BD	10/25/2049
2020 PO0895064081	KU	2	50 BRO	SP	CCA		V	10/26/2049
2020 PO5097697853	KU	4	45 BRO	SP	CRE	ID	TD	10/27/2049
2020 PO5092497711	KU	6	30 BRO	SP	CCA	ED	T	10/28/2049
2020 PO5102907118	KU	5	30 XXX	SP	CRE	ED,ID,IP	TD	10/29/2049
2020 PO5091407195	KU	6	30 XXX	SP	CRE	ED,ID	TD	10/30/2049
2020 50705007119A	KU	5	35 BRN	SP	CCA		V	10/31/2049
2020 PO5087107117	KU	6	30 BRN	SP	CRE	ED,ID	TD	11/1/2049
2020 PO5090306992	KU	6	30 XXX	SP	CRE	ED,ID	TD	11/2/2049
2020 PO5088407068	KU	4	40 XXX	SP	CRE	RB	X	PX 11/3/2049
2020 PO8125073481	KU	6	35 BRO	SP	CRE	ED	TD	11/4/2049
2020 PO8177973804	KU	6	35 BRO	SP	CRE	ED,ID	TD	11/5/2049
2020 PO8257674107	KU	4	40 BRO	SP	CRE	ID	BD	11/6/2049
2020 PO8247774230	KU	4	40 BRO	SP	CRE	ID	BD	11/7/2049
2020 PO8202873956	KU	4	40 BRO	SP	CRE	ID	BD	11/8/2049
2020 PO8218374051	KU	6	35 BRO	SP	CRE	ED,ID	TD	11/9/2049
2020 PO7663579855	KU	4	40 BRN	SP	CRE	ED,ID	BD	11/10/2049
2020 PO7653679797	KU	4	40 BRN	SP	CRE	ED,ID	BD	11/11/2049
2020 PO7642880180	KU	6	30 BRN	SP	CRE	ED,ID	TD	11/12/2049
2020 PO8280774432	KU	6	35 BRO	SP	CRE	ID	BD	11/13/2049
2020 PO8049872594	KU	4	30 BRO	SP	CRE	ED,ID	TD	11/14/2049
2020 PO8057372461	F	3	45 BRO	SP	CRE		V	11/15/2049
2020 PO8070172222	F	3	45 BRO	SP	CRE		V	11/16/2049
2020 PO8065072106	F	5	35E BRO	SP	A		V	11/17/2049
2020 PO8047172043	F	3	45 BRO	SP	CRE		V	11/18/2049
2020 PO8043371910	F	3	45 BRO	SP	CRE		V	11/19/2049

2020 PO8029372020	F	3	45 BRO	SP	CRE		V	11/20/2049
2020 PO8015772113	F	3	45 BRO	SP	CCA		V	11/21/2049
2020 PO8010672044	F	3	45 BRO	SP	CRE		V	11/22/2049
2020 PO8039571935	F	1E	20E BRO	SP	CCA		V	11/23/2049
2020 PO8021571759	F	3	45 BRO	SP	CRE		V	11/24/2049
2020 PO7997071716	F	3	45 BRO	SP	CRE		V	11/25/2049
2020 PO7976571771	F	3	45 BRO	SP	CRE		V	11/26/2049
2020 PO8003071057	F	3	45 BRO	SP	CRE		V	11/27/2049
2020 PO7990971286	F	3	45 BRO	SP	CRE		V	11/28/2049
2020 PO7955271620	F	3	45 BRO	SP	CRE		V	11/29/2049
2020 PO7986871485	KU	6	30 BRO	SP	CCA		V	11/30/2049
2020 PO7981671502	F	3	40 BRO	SP	CRE		V	12/1/2049
2020 PO8007271164	KU	5	35 BRO	SP	CCA		V	12/2/2049
2020 PO7633580133	KU	4	40 BRN	SP	CRE	ED,ID	BD	12/3/2049
2020 PO7643979951	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	12/4/2049
2020 PO5086597815	KU	6	30 BRO	SP	CRE	ID	TD	12/5/2049
2020 PO5081897886	KU	4	40 BRO	SP	CRE	ID	TD	12/6/2049
2020 PO5061497940	KU	4	40 BRO	SP	CRE	ID	TD	12/7/2049
2020 PO5047197959	KU	4	40 BRO	SP	CRE	ID	TD	12/8/2049
2020 PO5047298062	KU	6	30 BRO	SP	CRE	ID	TD	12/9/2049
2020 PO5030598213	KU	4	40 BRO	SP	CRE	ID	TD	12/10/2049
2020 PO5018498233	KU	6	30 BRO	SP	CRE	ID	TD	12/11/2049
2020 PO5047898136	KU	5	30 BRO	SP	CCA	ED	T	12/12/2049
2020 PO5035097971	KU	4	40 BRO	SP	CRE	ID	TD	12/13/2049
2020 PO5109906534	KU	6	30 XXX	SP	CCA		V	12/14/2049
2020 PO5118106691	KU	6	30 XXX	SP	CRE	ED,ID	TD	12/15/2049
2020 PO5128106747	KU	6	30 XXX	SP	CRE	ED,ID	TD	12/16/2049
2020 PO5125806854	KU	4	40 XXX	SP	CRE	ED,ID	TD	12/17/2049
2020 PO5112106800	KU	4	40 XXX	SP	CRE	ID	BD	12/18/2049
2020 PO5098606755	KU	5	35 XXX	SP	CRE	ED,ID	TD	12/19/2049
2020 PO5085606705	KU	4	40 XXX	SP	CRE	ED,ID	TD	12/20/2049
2020 PO5078606566	KU	6	30 ACW	SP	CRE	ED,ID	TD	12/21/2049
2020 PO5070306585	KU	6	30 ACW	SP	CRE	ID	TD	12/22/2049
2020 PO5071106663	KU	5	40 XXX	SP	CRE	ED,ID	TD	12/23/2049
2020 PO5066106676	KU	6	30 XXX	SP	CRE	ED,ID	TD	12/24/2049
2020 PO5055106605	KU	4	40 XXX	SP	CRE	ID	BD	12/25/2049
2020 PO4964505116	KU	6	30 XXX	SP	CCA		V	12/26/2049
2020 PO2904603923A	KU	3	45 OTH	SP	CCA		V	12/27/2049
2020 PO1478245281	KU	6	35 BRN	SP	CRE	ED,ID,IP	TD	12/28/2049
2020 PO1468845078	KU	5	35 BRN	SP	CRE	ID,IP	TD	12/29/2049
2020 PO0951871533	KU	3	50 BRO	SP	CRE	ED,ID,IP	TD	12/30/2049
2020 PO0978471410	KU	3	50 BRO	SP	CRE	ED,ID,IP	TD	12/31/2049
2020 PO1003871290	KU	3	55 BRO	SP	CRE	ED,ID,IP	TD	1/1/2050
2020 PO1011771465	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD	1/2/2050
2020 PO0848361755	KU	4	45 BRO	SP	CCA		V	1/3/2050
2020 PO0853861752	KU	4	40 BRO	SP	CCA		V	1/4/2050
2020 PO1530046562	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	1/5/2050

2020 PO0694861564	F	4	40 ACW	SP	CRE		V	1/6/2050	
2020 PO0693461689	KU	4	45 ACW	SP	CRE	ED	BD	1/7/2050	
2020 PO0697661572	F	4	40 ACW	SP	CRE		V	1/8/2050	
2020 PO0675361580	KU	3	45 ACW	SP	CCA		V	1/9/2050	
2020 PO0684061546	KU	3	45 ACW	SP	CCA		V	1/10/2050	
2020 PO0693461510	KU	3	45 ACW	SP	CCA		V	1/11/2050	
2020 PO2687361532	KU	4	45 ACW	SP	CRE		B	1/12/2050	
2020 PO0687561597	F	4	40 ACW	SP	A		V	1/13/2050	
2020 PO0863161707	KU	3	50 BRO	SP	CCA		V	1/14/2050	
2020 PO0875461648	KU	3	50 BRO	SP	CCA		V	1/15/2050	
2020 PO1532246288	KU	5	35 BRN	SP	CRE	ED,ID	TD	1/16/2050	
2020 PO1557446076	KU	6	30 BRN	SP	CRE		V	1/17/2050	
2020 PO1533346069	KU	4	40 BRN	SP	CRE	ID,IP	TD	1/18/2050	
2020 PO1490545739	KU	4	40 BRN	SP	CRE	ID	TD	1/19/2050	
2020 PO1509245660	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	1/20/2050	
2020 PO0892461593	KU	3	50 BRO	SP	CCA		V	1/21/2050	
2020 PO0818861908	KU	4	45 BRO	SP	CRE	ID	BD	1/22/2050	
2020 PO0851167061	KU	3	40 BRO	SP	CCA		V	1/23/2050	
2020 PO1502745987	KU	5	35 BRN	SP	CRE	ID,IP	TD	1/24/2050	
2020 PO1517146277	KU	4	35 BRN	SP	CRE	ID,IP	TD	1/25/2050	
2020 PO1541646791	KU	4	40 BRN	SP	CRE	ID	TD	1/26/2050	
2020 PO1526946908	KU	4	40 BRN	SP	CRE	ID	BD	1/27/2050	
2020 PO1508447079	KU	4	40 BRN	SP	CRE	ID	BD	1/28/2050	
2020 PO1080870792	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	1/29/2050	
2020 PO1135970930	KU	4	40 BRO	SP	CCA		V	1/30/2050	
2020 PO1154771026	KU	4	40 BRO	SP	CCA		V	1/31/2050	
2020 PO1173471121	KU	4	40 BRO	SP	CCA		V	2/1/2050	
2020 PO1192171216	KU	4	40 BRO	SP	CCA		V	2/2/2050	
2020 PO0918261016	KU	4	40 ACW	SP	CRE	ED,EP,ID,IP	TX	RR	2/3/2050
2020 PO1206846286	KU	4	40 BRN	SP	CRE	ID	BD	2/4/2050	
2020 PO1209746384	KU	4	40 BRN	SP	CRE	ID,IP	BD	2/5/2050	
2020 PO9166151280	KU	4	40 BRO	SP	CRE	ID	BD	2/6/2050	
2020 PO9004251844-b	KU	6	30 BRO	SP	CRE	ED,EP,ID,IP,SRC	TD	2/7/2050	
2020 PO1294450051	KU	4	45 BRN	SP	CRE	ID	TD	2/8/2050	
2020 PO0887960876	KU	4	40 ACW	SP	CRE	ED,ID	TD	2/9/2050	
2020 PO0874060713	KU	4	40 ACW	SP	CRE	ED,ID	TD	2/10/2050	
2020 PO0861660602	KU	4	40 ACW	SP	CRE	ED,ID	TD	2/11/2050	
2020 PO0826760656	KU	4	40 ACW	SP	CRE	ED,ID	TD	2/12/2050	
2020 PO1298350620	KU	3	50 BRN	SP	CRE	ID	TD	2/13/2050	
2020 PO1155951259	KU	4	40 BRN	SP	CRE	ID	TD	2/14/2050	
2020 PO6781702344	F	5	35 XXX	SP	CRE	ED,HH,ID,RB	BX	PX	2/15/2050
2020 PO1304751015	KU	4	40 BRN	SP	CRE	IP	TD	2/16/2050	
2020 PO1308351288	KU	4	40 BRN	SP	CRE	ED,ID,IP	BD	2/17/2050	
2020 PO1223251396	KU	4	40 BRN	SP	CCA		V	2/18/2050	
2020 PO1191151327	KU	4	35 BRN	SP	CRE	ID,IP	TD	2/19/2050	
2020 PO9004251844-A	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD	2/20/2050	
2020 PO9004251844	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD	2/21/2050	

2020 PO8977151827	KU	4	40 BRO	SP	CRE		V			2/22/2050
2020 PO9005752094	F	4	40 BRO	SP	CRE		V			2/23/2050
2020 PO8984551990	KU	6	30 BRO	SP	CRE		V			2/24/2050
2020 PO8982451877	KU	4	45 BRO	SP	CRE		V			2/25/2050
2020 PO8989551861	KU	4	40 BRO	SP	CRE		V			2/26/2050
2020 PO9011951870	F	4	40 BRO	SP	CRE		V			2/27/2050
2020 PO9018951817	KU	4	40 BRO	SP	CRE	HH,ID,RB	BX	RP2		2/28/2050
2020 PO9036151801	KU	4	40 BRO	SP	CRE	ED,HH,ID,RB	BX	RP2		3/1/2050
2020 PO9036151801-A	KU	4	40 BRO	SP	CRE	ED,ID,SR,SRS	TD			3/2/2050
2020 PO1149350974	KU	4	45 BRN	SP	CRE	ID	TD			3/3/2050
2020 PO1012370929	KU	2	50 BRO	SP	CRE	ED	TD			3/4/2050
2020 PO1013671110	KU	2	50 BRO	SP	CRE	ID	BD			3/5/2050
2020 PO1030370819	KU	2	50 BRO	SP	CRE	ED	TD			3/6/2050
2020 PO1068470066	KU	3	45 BRO	SP	CCA		V			3/7/2050
2020 PO1093070017	KU	3	45 BRO	SP	CCA		V			3/8/2050
2020 PO1117469966	KU	3	45 BRO	SP	CCA		V			3/9/2050
2020 PO1138869836	KU	3	45 BRO	SP	CCA		V			3/10/2050
2020 PO1155169674	KU	2	50 BRO	SP	CCA		V			3/11/2050
2020 PO1157169663	KU	2	50 BRO	SP	CCA		V			3/12/2050
2020 PO1043970115	KU	2	50 BRO	SP	CCA		V			3/13/2050
2020 PO0919068436	KU	4	40 BRO	SP	CRE		V			3/14/2050
2020 PO0952968311	KU	4	40 BRO	SP	CRE		V			3/15/2050
2020 PO0993567870	KU	4	40 BRO	SP	CRE		V			3/16/2050
2020 PO0804460701	KU	4	40 ACW	SP	CRE	ED,ID	TD			3/17/2050
2020 PO0784760745	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD			3/18/2050
2020 PO0769160715	KU	4	45 ACW	SP	CRE	ID	BD			3/19/2050
2020 PO1143850752	KU	4	40 BRN	SP	CRE	ID,IP	TD			3/20/2050
2020 PO1102050814	KU	4	40 BRN	SP	CRE	ID	BD			3/21/2050
2020 PO1057850876	KU	4	40 BRN	SP	CRE	ID	TD			3/22/2050
2020 PO0776360767	KU	4	45 ACW	SP	CRE	ED,ID	TD			3/23/2050
2020 PO0752960750	KU	6	30 ACW	SP	CRE	ED,ID	TD			3/24/2050
2020 PO0764560796	KU	4	40 ACW	SP	CRE	ED,EP,ID,IP	TX	RR		3/25/2050
2020 PO0748560835	KU	4	40 ACW	SP	CRE	ED,ID	TD			3/26/2050
2020 PO0733260818	KU	6	30 ACW	SP	CRE	ED,ID	TD			3/27/2050
2020 PO0985867629	KU	4	40 BRO	SP	CRE		V			3/28/2050
2020 PO0948166497	KU	3	50 BRO	SP	CCA		V			3/29/2050
2020 PO1028869288	F	4	40 BRO	SP	CRE		V			3/30/2050
2020 PO6890201873	F	4	40 XXX	SP	CRE		V			3/31/2050
2020 PO6866501875	KU	6	30 BRN	SP	CCA		V			4/1/2050
2020 PO6900801832	F	2	40 KOP	SP	CRE	ID	V			4/2/2050
2020 PO6869001924	F	6	30 BRN	SP	CRE		V			4/3/2050
2020 PO6876801844	F	6	30 XXX	SP	CRE		V			4/4/2050
2020 PO715798981	KU	4	40 BRN	SP	CRE	ED,ID	TD			4/5/2050
2020 PO7496991751	KU	3	50 BRO	SP	CRE	ED,ID	TD			4/6/2050
2020 PO2092546439	KU	4	40 ACE	SP	CRE	ED,ID	TD			4/7/2050
2020 PO2084746475	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD			4/8/2050
2020 PO7025594603	KU	4	40 BRN	SP	CRE		V			4/9/2050

2020 PO6672702847	KU	4	40 BRN	SP	CRE	ED,ID	TD		4/10/2050
2020 PO6654502960	KU	6	30 XXX	SP	CRE	ID	BD		4/11/2050
2020 PO6792216196	KU	4	40 XXX	SP	CRE	ID	BD		4/12/2050
2020 PO6808615972A	KU	5	35 XXX	SP	CRE	HH,ID,RB	TX	RR	4/13/2050
2020 PO6817916081	KU	5	35 XXX	SP	CRE	HH,ID	TX	RR	4/14/2050
2020 PO6813516200	KU	6	30 XXX	SP	CRE	ID	TD		4/15/2050
2020 PO6798615878	KU	4	40 XXX	SP	CRE	HH,ID,IP	TX	RR	4/16/2050
2020 PO6808615972	KU	5	35 XXX	SP	CRE	ID	TD		4/17/2050
2020 PO6771315654	KU	4	40 XXX	SP	CCA		V		4/18/2050
2020 PO6753515485	KU	5	35 XXX	SP	CRE	ID	TD		4/19/2050
2020 PO6769015441	KU	5	35 XXX	SP	CCA		V		4/20/2050
2020 PO6742715386	KU	4	40 XXX	SP	CRE	ID,IP	TD		4/21/2050
2020 PO6738215187	KU	5	35 XXX	SP	CRE	ID	TD		4/22/2050
2020 PO6733614983	KU	5	35 XXX	SP	CRE	ID	TD		4/23/2050
2020 PO6705614808	KU	4	40 XXX	SP	CCA		V		4/24/2050
2020 PO6717014799	KU	4	40 XXX	SP	CCA		V		4/25/2050
2020 PO6729214790	KU	4	40 XXX	SP	CCA		V		4/26/2050
2020 PO6727114704	KU	4	40 XXX	SP	CRE	ID	TD		4/27/2050
2020 PO6710814684	KU	6	35 XXX	SP	CCA		V		4/28/2050
2020 PO6724114410	KU	5	35 XXX	SP	CRE	ID	TD		4/29/2050
2020 PO6725714282	KU	4	40 XXX	SP	CRE	ID	BD		4/30/2050
2020 PO6731302416	KU	6	30 BRN	SP	P	ID	VX	PX	5/1/2050
2020 PO6745502382A	KU	5	35 BRN	SP	CCA		V		5/2/2050
2020 PO6753403376	KU	4	40 XXX	SP	CRE	ED,ID	TD		5/3/2050
2020 PO6726903547	KU	4	40 XXX	SP	CRE	ED,ID	TD		5/4/2050
2020 PO2052946274	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD		5/5/2050
2020 PO2054746200	KU	4	40 ACE	SP	CRE	ED,ID	BD		5/6/2050
2020 PO2076946182	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		5/7/2050
2020 PO7484691826	F	4	45 BRO	SP	CRE		V		5/8/2050
2020 PO6743602517	KU	6	35 XXX	SP	CRE		V		5/9/2050
2020 PO6769502384	F	4	40 XXX	SP	P		V		5/10/2050
2020 PO7469591912	F	4	45 BRO	SP	CRE		V		5/11/2050
2020 PO6744503245	KU	4	40 XXX	SP	CRE	ED,ID	TD		5/12/2050
2020 PO6735402587	KU	2	50 XXX	SP	CRE		V		5/13/2050
2020 PO2063746155	KU	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	RP1	5/14/2050
2020 PO7478292033	KU	5	30 BRO	SP	CRE	ED,ID,SRC	TD		5/15/2050
2020 PO7155989929	KU	4	40 BRO	SP	CRE	ED,ID	TX	RR	5/16/2050
2020 PO7429192805	KU	4	40 BRO	SP	CRE	EP,ID,IP	BD		5/17/2050
2020 PO7163889062	F	3	45 BRO	SP	CRE		V		5/18/2050
2020 PO7173089192	F	3	40 BRO	SP	CRE		V		5/19/2050
2020 PO7178389241	F	3	40 BRO	SP	CRE		V		5/20/2050
2020 PO7181289308	F	3	40 BRO	SP	CRE		V		5/21/2050
2020 PO7177289668	F	4	40 BRO	SP	CCA		V		5/22/2050
2020 PO7118190120	F	5	30 BRO	SP	A		V		5/23/2050
2020 PO7070791239	F	4	40 BRO	SP	A		V		5/24/2050
2020 PO7095191077	F	4	40 BRO	SP	CCA		V		5/25/2050
2020 PO7110290989	F	4	40 BRO	SP	CRE		V		5/26/2050

2020 PO7132390862	F	4	40 BRO	SP	CRE		V		5/27/2050
2020 PO7143990793	F	4	45 BRO	SP	CRE		V		5/28/2050
2020 PO7119290937	F	4	40 BRO	SP	CRE	ED,ID,RB	VX	RP2	5/29/2050
2020 PO7121290948	KU	4	40 BRO	SP	CRE		V		5/30/2050
2020 PO7207391006	KU	4	35 BRO	SP	CRE	ID	BD		5/31/2050
2020 PO3001835596	KU	6	30 BRN	SP	CRE	ID	BD		6/1/2050
2020 PO4012036168	KU	4	40 BRO	SP	CRE	ID	TD		6/2/2050
2020 PO4021936092	KU	5	35E BRO	SP	CRE	ED,ID,IP	TD		6/3/2050
2020 PO3225238041	KU	4	40 BRN	SP	CRE	ED,EP,ID,IP,RB	BX	PX	6/4/2050
2020 PO7521384519	KU	4	40 BRN	SP	CRE	ED,ID	BD		6/5/2050
2020 PO7469883933	KU	4	40 BRN	SP	CRE		V		6/6/2050
2020 PO7534084476	KU	4	40 BRN	SP	CRE	ED,ID	TD		6/7/2050
2020 PO7539384826-A	KU	3	45 BRN	SP	CCA		V		6/8/2050
2020 PO7539384826	KU	5	35 BRN	SP	CRE	ED,ID	TD		6/9/2050
2020 PO7549184846	F	5	35 BRN	SP	CRE		V		6/10/2050
2020 PO7553084732	KU	3	50 BRN	SP	CRE	ED,ID	TD		6/11/2050
2020 PO7556184759	KU	3	50 BRN	SP	CRE	ED,ID	BD		6/12/2050
2020 PO7485883964	KU	4	40 BRN	SP	CRE	ED,ID	BD		6/13/2050
2020 PO7480683792	KU	3	45 BRN	SP	CCA		V		6/14/2050
2020 PO7492483937	KU	4	40 BRN	SP	CRE	ED,ID	BD		6/15/2050
2020 PO7504184081	KU	4	40 BRN	SP	CRE	ED,ID	BD		6/16/2050
2020 PO7476383473	KU	4	45 BRN	SP	CRE	ED,ID	BD		6/17/2050
2020 PO7781977249	KU	2	60 BRO	SP	CRE		V		6/18/2050
2020 PO7797577059	KU	1	75 BRO	SP	CCA		V		6/19/2050
2020 PO7881076053	KU	2	65 BRO	SP	CRE		V		6/20/2050
2020 PO7862876292	KU	2	65 BRO	SP	CRE		V		6/21/2050
2020 PO7843276519	KU	2	65 BRO	SP	CRE		V		6/22/2050
2020 PO7822276769	KU	2	70 BRO	SP	CRE		V		6/23/2050
2020 PO7833676622	KU	2	65 BRO	SP	CRE		V		6/24/2050
2020 PO7895175880	KU	2	65 BRO	SP	CRE		V		6/25/2050
2020 PO7915975619	KU	2	65 BRO	SP	CRE		V		6/26/2050
2020 PO7936275389	KU	2	65 BRO	SP	CRE		V		6/27/2050
2020 PO7947275178	KU	1	70 BRO	SP	CCA		V		6/28/2050
2020 PO7959974915	KU	2	65 BRO	SP	CCA		V		6/29/2050
2020 PO7973874636	KU	2	65 BRO	SP	CCA		V		6/30/2050
2020 PO7986974365	KU	2	65 BRO	SP	CCA		V		7/1/2050
2020 PO7485983437	KU	6	30 BRN	SP	CRE	ED,ID	BD		7/2/2050
2020 PO7516883707	KU	4	45 BRN	SP	CRE	ED,ID	BD		7/3/2050
2020 PO7521383671	KU	4	40 BRN	SP	CRE	ED,ID	BD		7/4/2050
2020 PO7503383615	KU	4	45 BRN	SP	CCA		V		7/5/2050
2020 PO7495283622	KU	3	50 BRN	SP	CRE	ED,ID	BD		7/6/2050
2020 PO4595310772	F	4	40 ACE	SP	CRE		V		7/7/2050
2020 PO3667308731	KU	4	40 BRO	SP	CRE	ID,IP	BD		7/8/2050
2020 PO3674908797	KU	4	40 BRO	SP	CRE	ID	BD		7/9/2050
2020 PO4670388196	LGE	4	35 BRN	SP	CRE	ED	VX	RP3	7/10/2050
2020 PO3698408998	KU	3	45 BRO	SP	CRE	ID,IP	BD		7/11/2050
2020 PO3707409074	KU	4	40 BRO	SP	CRE	ID,IP	BD		7/12/2050

2020 PO4061182799	LGE	3	50 BRO	SP	A		V		7/13/2050
2020 PO4675688147	LGE	4	40 BRN	SP	CRE	ED,ID	TD		7/14/2050
2020 PO3686308894	KU	4	40 BRO	SP	CRE	ID,IP	BD		7/15/2050
2020 PO4062182711	LGE	3	45 BRO	SP	P	ED,ID,IP	TD		7/16/2050
2020 PO7824240188	LGE	1	50 BRO	SP	A	ED,ID	TD		7/17/2050
2020 PO3846794333	LGE	4	40 BRN	SP	CRE	ED,ID	TD		7/18/2050
2020 PO4062682826	LGE	4	45 BRO	SP	CCA		V		7/19/2050
2020 PO4674188169	LGE	4	40 BRN	SP	CRE	ED,ID	TD		7/20/2050
2020 PO4154113575	KU	3	45 BRO	SP	P	ED	T		7/21/2050
2020 PO4673588177	LGE	4	40 BRN	SP	CRE	ED,ID	TD		7/22/2050
2020 PO4673088185	LGE	3	45 BRN	SP	S		V		7/23/2050
2020 PO4136513472	KU	6	30 BRO	SP	P	ED	T		7/24/2050
2020 PO1308028377	ODP	4	40 BRN	SP	CRE	ID	TD		7/25/2050
2020 PO1342828393	ODP	4	45 BRN	SP	CRE	ID	TD		7/26/2050
2020 PO1309428512	F	5	35 BRN	SP	A		V		7/27/2050
2020 PO1300328432	ODP	5	35 BRN	SP	CRE	ED,ID	TX	RR	7/28/2050
2020 PO1132727704A	ODP	4	40 BRN	SP	CCA	ED	T		7/29/2050
2020 PO1132727704	ODP	4	40 BRN	SP	CRE	ID	TD		7/30/2050
2020 PO1163627564	ODP	4	40 BRN	SP	CCA		V		7/31/2050
2020 PO1165327823	ODP	4	40 BRN	SP	CRE	ID	BD		8/1/2050
2020 PO1171228100	ODP	4	40 BRN	SP	CRE	ID	TD		8/2/2050
2020 PO1340530693	ODP	6	30 BRN	SP	CRE		V		8/3/2050
2020 PO1410330675	ODP	3	50 BRN	SP	CCA		V		8/4/2050
2020 PO1408830903	ODP	5	35 BRN	SP	CCA		V		8/5/2050
2020 PO4672488194	LGE	4	40 BRN	SP	CRE	ED,HH,ID,SRC	TX	RR	8/6/2050
2020 PO4671688205	LGE	4	40 BRN	SP	P	ED,ID	TD		8/7/2050
2020 PO4672388209	LGE	4	35 BRN	SP	CCA		V		8/8/2050
2020 PO4673588217	LGE	3	45 BRN	SP	S		V		8/9/2050
2020 PO4134113562	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD		8/10/2050
2020 PO4104213543	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD		8/11/2050
2020 PO2537446793	ODP	6	30 KOP	SP	CRE	ED,ID,IP	TD		8/12/2050
2020 PO2534346663	ODP	6	30 KOP	SP	S		V		8/13/2050
2020 PO2521346633	ODP	6	30 KOP	SP	S		V		8/14/2050
2020 PO2530346500	ODP	4	40 KOP	DF	CRE	ED,ID	TD		8/15/2050
2020 PO4067913517	KU	3	45 BRO	SP	CRE	ID,IP	BD		8/16/2050
2020 PO4610310947b	KU	3	45 ACE	SP	CCA		V		8/17/2050
2020 PO4610310947a	KU	3	45 ACE	SP	CCA		V		8/18/2050
2020 PO4601810932	F	3	45 ACE	SP	CCA		V		8/19/2050
2020 PO4610310947	KU	2	40 ACE	SP	CCA		V		8/20/2050
2020 PO4077213525	KU	3	45 BRO	SP	CRE	ID,IP	BD		8/21/2050
2020 PO4062413379	KU	6	30 BRO	SP	CRE	ID,IP	BD		8/22/2050
2020 PO4119513553	KU	3	45 BRO	SP	CCA		V		8/23/2050
2020 PO4046082746	F	4	40 BRO	SP	CCA		V		8/24/2050
2020 PO4675888209	LGE	4	40 BRN	SP	A	ED,ID	BD		8/25/2050
2020 PO4674488201	LGE	3	45 BRN	SP	S		V		8/26/2050
2020 PO4063182723	LGE	4	40 BRO	SP	CCA		V		8/27/2050
2020 PO4063682728	LGE	5	25 BRO	SP	CCA		V		8/28/2050

2020 PO7916639890	LGE	3	45 BRO	SP	CCA		V	8/29/2050	
2020 PO7968140287	LGE	3	45 BRO	SP	CCA		V	8/30/2050	
2020 PO7896839738	LGE	3	45 BRO	SP	P	ED	T	8/31/2050	
2020 PO7942840572	LGE	4	35 BRO	SP	CCA		V	9/1/2050	
2020 PO7933640690	LGE	4	35 BRO	SP	CCA		V	9/2/2050	
2020 PO4676588191	LGE	4	35 BRN	SP	A	HH,ID	TD	9/3/2050	
2020 PO7952340165	LGE	3	45 BRO	SP	CCA		V	9/4/2050	
2020 PO7936540043	LGE	3	45 BRO	SP	CCA		V	9/5/2050	
2020 PO7945440444	LGE	4	35 BRO	SP	CCA		V	9/6/2050	
2020 PO4675788184	LGE	3	45 BRN	SP	S		V	9/7/2050	
2020 PO4675388182	LGE	4	30 BRN	SP	S		V	9/8/2050	
2020 PO4676288165	LGE	6	30 BRN	SP	CRE	ED,HH,ID,RB	TX	RR	9/9/2050
2020 PO4169513583	KU	3	45 BRO	SP	CRE	ID,IP	BD	9/10/2050	
2020 PO4178613588	KU	4	40 BRO	SP	CRE	ID,IP	BD	9/11/2050	
2020 PO4677788153	LGE	UNK	45 BRN	SP	S		V	9/12/2050	
2020 PO3871294381	LGE	3	45 BRN	SP	CCA		V	9/13/2050	
2020 PO4676888167	LGE	3	45 BRN	SP	CCA		V	9/14/2050	
2020 PO4256211533	KU	4	40 BRO	SP	CRE	ID,IP	BD	9/15/2050	
2020 PO4249111472	KU	4	40 BRO	SP	CRE	ID	BD	9/16/2050	
2020 PO4236911391	KU	4	40 BRO	SP	CRE	ID,IP	BD	9/17/2050	
2020 PO7837439280	LGE	3	45 BRO	SP	P	ED	T	9/18/2050	
2020 PO7857239432	LGE	3	45 BRO	SP	P	ED	T	9/19/2050	
2020 PO7877039585	LGE	3	45 BRO	SP	P	ED	T	9/20/2050	
2020 PO0548660342	KU	5	45 ACW	SP	CRE	ED,ID,IP	TD	9/21/2050	
2020 PO0471660373	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	9/22/2050	
2020 PO0391360450	KU	4	40 ACW	SP	CRE	ED,ID	TD	9/23/2050	
2020 PO0420660661	KU	4	40 ACW	SP	CRE	ED,ID	TD	9/24/2050	
2020 PO8943893945	KU	4	40 BRN	SP	CRE	ID	BD	9/25/2050	
2020 PO8961993482	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD	9/26/2050	
2020 PO8997192085	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD	9/27/2050	
2020 PO9024792333	KU	5	35 BRN	SP	CRE	ID	BD	9/28/2050	
2020 PO9262595142	KU	4	40 BRN	SP	CRE	ID	BD	9/29/2050	
2020 PO9337694691	KU	4	40 BRN	SP	CRE	ID	BD	9/30/2050	
2020 PO9367294582	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD	10/1/2050	
2020 PO9415595378	KU	6	30 BRN	SP	CRE	ED,ID	TD	10/2/2050	
2020 PO1179524299	ODP	5	30 XXX	SP	CCA	ED	T	10/3/2050	
2020 PO1250024548	ODP	4	45 XXX	SP	CRE	ID	TD	10/4/2050	
2020 PO4497711924	F	2	50 ACE	SP	CCA		V	10/5/2050	
2020 PO4484211980	F	2	50 ACE	SP	CCA		V	10/6/2050	
2020 PO4501711908	F	2	50 ACE	SP	CCA		V	10/7/2050	
2020 PO4513611860	F	2	50 ACE	SP	CCA		V	10/8/2050	
2020 PO1199424400	ODP	4	45 BRN	SP	CCA	ED	T	10/9/2050	
2020 PO4714788499	LGE	2	55 BRN	SP	CCA	ED,ID	BD	10/10/2050	
2020 PO4714588498	LGE	2	55 BRN	SP	S		V	10/11/2050	
2020 PO4523911817	F	1	50 ACE	SP	CCA		V	10/12/2050	
2020 PO4536011768	F	2	50 ACE	SP	CCA		V	10/13/2050	
2020 PO4547611720	F	2	50 ACE	SP	CCA		V	10/14/2050	

2020 PO4561411661	F	2	50 ACE	SP	CCA		V			10/15/2050
2020 PO4570311626	F	2	50 ACE	SP	CCA		V			10/16/2050
2020 PO4716588518	LGE	3	45 BRN	SP	CCA		V			10/17/2050
2020 PO1208024899	F	4	45 BRN	SP	CRE		V			10/18/2050
2020 PO1213824430	F	4	45 BRN	SP	CRE		V			10/19/2050
2020 PO1285724598B	ODP	6	30 BRN	SP	CCA		V			10/20/2050
2020 PO1225424484A	ODP	4	40 BRN	SP	CCA		V			10/21/2050
2020 PO1225424484	ODP	3	50 BRN	SP	CRE		V			10/22/2050
2020 PO2147243732	ODP	4	40 KOP	SP	S		V			10/23/2050
2020 PO2432546438	ODP	4	40 KOP	SP	CRE	ED,ID		TD		10/24/2050
2020 PO2451146272	F	4	40 KOP	SP	P		V			10/25/2050
2020 PO2464646209	F	4	40 KOP	SP	CRE		V			10/26/2050
2020 PO2065042156	ODP	4	40 KOP	SP	S		V			10/27/2050
2020 PO4715688533	LGE	4	40 BRN	SP	CRE	HH,ID		TD		10/28/2050
2020 PO4715988544	LGE	4	35 BRN	SP	CRE		V			10/29/2050
2020 PO4715088544	LGE	3	45 BRN	SP	S		V			10/30/2050
2020 PO4583611559	F	2	50 ACE	SP	CCA		V			10/31/2050
2020 PO4600711483	F	2	50 ACE	SP	CCA		V			11/1/2050
2020 PO4608711353	F	2	50 ACE	SP	CCA		V			11/2/2050
2020 PO4610211157	F	2	50 ACE	SP	CCA		V			11/3/2050
2020 PO4605911036	F	4	40 ACE	SP	CRE		V			11/4/2050
2020 PO4583711145	F	4	40 ACE	SP	CRE		V			11/5/2050
2020 PO4243898293	LGE	4	40 BRN	SP	S		V			11/6/2050
2020 PO4714288557	LGE	4	35 BRN	SP	CRE	ED,ID		TD		11/7/2050
2020 PO4054082631	LGE	4	40 BRO	SP	P	ED,ID		TD		11/8/2050
2020 PO4053082642	LGE	4	40 BRO	SP	P	ED,HH,ID		BD		11/9/2050
2020 PO4713888563	LGE	4	40 BRN	SP	S		V			11/10/2050
2020 PO4713588568	LGE	4	40 BRN	SP	CCA		V			11/11/2050
2020 PO4713288573	LGE	4	35 BRN	SP	CRE	ED,ID		TD		11/12/2050
2020 PO1280124617	ODP	6	30 BRN	SP	CRE	ID		TD		11/13/2050
2020 PO1285724598A	ODP	6	30 BRN	SP	CCA		V			11/14/2050
2020 PO1309324615	ODP	4	40 BRN	SP	CRE	ID		TD		11/15/2050
2020 PO1324324874A	ODP	5	35 BRN	SP	CCA		V			11/16/2050
2020 PO1328224980	ODP	6	30 BRN	SP	CCA		V			11/17/2050
2020 PO1324324874	ODP	4	40 BRN	SP	CCA		V			11/18/2050
2020 PO1354324546	ODP	5	35 BRN	SP	CRE	ID		TD		11/19/2050
2020 PO1359324639	ODP	5	35 BRN	SP	CRE	ID		TX	RR	11/20/2050
2020 PO1377524644	F	4	40 BRN	SP	CRE		V			11/21/2050
2020 PO1369124910	ODP	5	35 BRN	SP	CRE	ID		BD		11/22/2050
2020 PO1231530990	ODP	4	40 BRN	SP	CRE		V			11/23/2050
2020 PO1285724598	ODP	4	40 XXX	SP	CRE	ID		TD		11/24/2050
2020 PO1332324556	ODP	5	35 XXX	SP	CRE	ID		TX	RR	11/25/2050
2020 PO4589508852	F	5	35 ACE	SP	CRE	ED,HH,ID,IP,RB	BX		RP1	11/26/2050
2020 PO4151610089	KU	3	45 BRO	SP	CRE	ED		TD		11/27/2050
2020 PO4168810282	KU	4	40 BRO	SP	CRE	ID		BD		11/28/2050
2020 PO4571708843	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX		PX	11/29/2050
2020 PO4556708895	F	4	40 ACE	SP	CRE		V			11/30/2050

2020 PO4537808972	F	5	35 ACE	SP	CRE		V		12/1/2050
2020 PO4548608928	F	4	40 ACE	SP	P		V		12/2/2050
2020 PO4515209046	F	5	30 ACE	SP	CRE		V		12/3/2050
2020 PO4505809085	F	4	40 ACE	SP	CRE		V		12/4/2050
2020 PO4429909167	F	4	40 ACE	SP	CCA		V		12/5/2050
2020 PO4712788583	LGE	4	40 BRN	SP	CRE	ED,ID	TD		12/6/2050
2020 PO4137809935	KU	2	55 BRO	SP	CRE	ED,ID,IP	TD		12/7/2050
2020 PO4123309772	KU	3	45 BRO	SP	CRE	ID	BD		12/8/2050
2020 PO4223398613	LGE	4	40 BRN	SP	S		V		12/9/2050
2020 PO4712888588	LGE	4	30 BRN	SP	CRE		V		12/10/2050
2020 PO4109309601	KU	3	45 BRO	SP	CRE	ID,IP	BD		12/11/2050
2020 PO4083109761	KU	4	45 BRO	SP	CCA		V		12/12/2050
2020 PO4081509753	KU	4	45 BRO	SP	CCA		V		12/13/2050
2020 PO4109309601-A	KU	2	50 BRO	SP	CCA		V		12/14/2050
2020 PO4659788318	LGE	4	40 BRN	SP	CRE	ED,ID	TD		12/15/2050
2020 PO4659288326	LGE	4	40 BRN	SP	CRE	ED,ID	TD		12/16/2050
2020 PO9414733635	ODP	4	45 XXX	SP	CRE		V		12/17/2050
2020 PO4183810403	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD		12/18/2050
2020 PO4441709225	KU	6	30 ACE	SP	CRE	ED,EP,ID,IP	TD		12/19/2050
2020 PO4197210549	KU	3	45 BRO	SP	CRE	ID,IP	BD		12/20/2050
2020 PO4449609447	KU	6	30 ACE	SP	CRE	ED,ID	TD		12/21/2050
2020 PO4439409403	F	4	40 ACE	SP	P	ED,EP,HH,ID,IP,RB	BX	PX	12/22/2050
2020 PO4446909589	F	4	40 ACE	SP	P	ED,EP,HH,ID,IP,RB	BX	RP1	12/23/2050
2020 PO4658988330	LGE	4	40 BRN	SP	S		V		12/24/2050
2020 PO4615038550	KU	3	45 BRO	SP	CCA		V		12/25/2050
2020 PO4613638552	KU	3	45 BRO	SP	CCA		V		12/26/2050
2020 PO4617838601	KU	3	45 BRO	SP	CCA		V		12/27/2050
2020 PO4620038607	KU	3	45 BRO	SP	CCA		V		12/28/2050
2020 PO4394537787	KU	4	45 BRO	SP	CCA		V		12/29/2050
2020 PO9427987913	KU	4	40 BRN	SP	CRE	ID	BD		12/30/2050
2020 PO9448188241	KU	4	40 BRN	SP	CRE	ED,ID	TD		12/31/2050
2020 PO8916492508	KU	4	40 BRN	SP	CRE	ED,EP,ID,IP,SR	TD		1/1/2051
2020 PO8895093100	KU	4	40 BRN	SP	CRE	ID,IP	BD		1/2/2051
2020 PO8879993509	KU	4	40 BRN	SP	CRE	EP,ID,IP	BD		1/3/2051
2020 PO8925994248	KU	4	40 BRN	SP	CRE	HH,ID,SR	TD		1/4/2051
2020 PO9258293630	KU	4	40 BRN	SP	CRE	ED,ID,RB	TX	RR	1/5/2051
2020 PO9264093866	KU	4	40 BRN	SP	CRE	ED,ID	TD		1/6/2051
2020 PO9251893834	KU	4	40 BRN	SP	CRE	ED,ID	TD		1/7/2051
2020 PO9255693717	KU	4	40 BRN	SP	CRE	ED,ID	TD		1/8/2051
2020 PO9256593674	F	4	40 BRN	SP	CRE		V		1/9/2051
2020 PO9360894816	C	4	40 ACW	SP	CRE		V		1/10/2051
2020 PO9256693956	KU	5	35 BRN	SP	CCA		V		1/11/2051
2020 PO9220294097	C	4	40 BRN	SP	CRE		V		1/12/2051
2020 PO9255394010	F	4	40 BRN	SP	CRE		V		1/13/2051
2020 PO9606393773	KU	4	45 ACW	SP	CRE	ED,ID,IP	TD		1/14/2051
2020 PO9340694510	KU	4	40 ACW	SP	CRE	ED,ID	TD		1/15/2051
2020 PO9334794647	KU	4	40 ACW	SP	CRE	ED,ID	TD		1/16/2051

2020 PO9346694675	KU	5	35 ACW	SP	CRE	ED,ID	TD		1/17/2051
2020 PO9363994718	KU	5	35 ACW	SP	CRE	ED,ID,SRC	TX	RR	1/18/2051
2020 PO5648147618	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		1/19/2051
2020 PO5650747602	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		1/20/2051
2020 PO5664547690	KU	4	45 ACE	SP	CRE	ED,ID,IP	TD		1/21/2051
2020 PO5678947785	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		1/22/2051
2020 PO1256831585	ODP	6	30 XXX	SP	CRE	ID	BD		1/23/2051
2020 PO1326031413	ODP	4	40 XXX	SP	CRE	ID	BD		1/24/2051
2020 PO1303131250	ODP	6	30 XXX	SP	CRE	ID	TD		1/25/2051
2020 PO1344931234	ODP	4	40 XXX	SP	CRE	ID	BD		1/26/2051
2020 PO1313530813	ODP	6	30 XXX	SP	CRE	ID	TD		1/27/2051
2020 PO1267629493	F	4	40 XXX	SP	CRE		V		1/28/2051
2020 PO1284629667	F	4	40 XXX	SP	P	ED	V		1/29/2051
2020 PO3942082743	LGE	4	30 BRO	SP	CRE	ED,ID	TD		1/30/2051
2020 PO3946582067	LGE	4	45 BRN	SP	CRE	ED,ID	TD		1/31/2051
2020 PO1383229341	KU	2	75 XXX	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX	2/1/2051
2020 PO1383129386	KU	2	65 XXX	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX	2/2/2051
2020 PO1383229415	KU	2	75 XXX	SP	CRE	ID	BD		2/3/2051
2020 PO3921982798	LGE	4	30 BRO	SP	P	ED,ID	TD		2/4/2051
2020 PO3928382685	F	4	50 BRO	SP	CRE		V		2/5/2051
2020 PO3928512021	KU	3	45 BRO	SP	CRE	ID,IP	BD		2/6/2051
2020 PO3923411947	KU	2	50 BRO	SP	CCA		V		2/7/2051
2020 PO3921111919	KU	3	45 BRO	SP	CRE	ID	BD		2/8/2051
2020 PO1700720259	F	4	40 XXX	SP	P		V		2/9/2051
2020 PO1686920246	F	4	40 XXX	SP	P		V		2/10/2051
2020 PO1676920288	F	4	40 XXX	SP	P		V		2/11/2051
2020 PO1666920343	F	4	40 XXX	SP	CRE		V		2/12/2051
2020 PO1771219638	F	4	40 XXX	SP	CRE		V		2/13/2051
2020 PO1755419592	F	4	40 XXX	SP	P		V		2/14/2051
2020 PO1727319543	F	4	40 XXX	SP	CRE	ED	V		2/15/2051
2020 PO1756219299	ODP	5	35 XXX	SP	CRE	ID	TD		2/16/2051
2020 PO1776719227	ODP	5	40 XXX	SP	CRE	ED,ID,SRS	TD		2/17/2051
2020 PO1543420055	ODP	4	40 XXX	SP	CRE	ED,ID	TD		2/18/2051
2020 PO3906382306	LGE	4	30 BRO	SP	P	ED,ID	BD		2/19/2051
2020 PO0832835489	ODP	6	35 XXX	SP	CRE		V		2/20/2051
2020 PO0806135537	ODP	5	40 XXX	SP	CRE		V		2/21/2051
2020 PO3906682346	LGE	4	30 BRO	SP	P	ED,ID	TD		2/22/2051
2020 PO0782935578	ODP	4	40 XXX	SP	CRE	ED,ID	TD		2/23/2051
2020 PO806135537A	ODP	4	40 XXX	SP	CCA		V		2/24/2051
2020 PO0763335551	ODP	5	35 XXX	SP	CRE	ED,ID	TD		2/25/2051
2020 PO3947282082	LGE	4	30 BRN	SP	A	ED,ID	TD		2/26/2051
2020 PO3907982429	LGE	4	30 BRO	SP	P	ED,ID	TD		2/27/2051
2020 PO3907582422	LGE	4	30 BRO	SP	P	ED,ID	TD		2/28/2051
2020 PO3918782709	F	4	40 BRO	SP	CCA		V		3/1/2051
2020 PO3918082682	F	4	40 BRO	SP	CCA		V		3/2/2051
2020 PO3929882678	F	3	50 BRO	SP	CRE		V		3/3/2051
2020 PO3930282682	F	4	30 BRO	SP	CCA		V		3/4/2051

2020 PO4670009949	F	4	40 ACE	SP	P		V	3/5/2051
2020 PO4687009882	F	4	40 ACE	SP	CRE		V	3/6/2051
2020 PO3947682081	LGE	4	40 BRN	SP	CRE	ED,ID	TD	3/7/2051
2020 PO0743335529	ODP	5	35 XXX	SP	CRE	ED,ID	TD	3/8/2051
2020 PO0678936525	ODP	6	30 XXX	SP	CRE	ID,RB	X	RP1 3/9/2051
2020 PO3949782089	LGE	4	35 BRN	SP	CCA		V	3/10/2051
2020 PO3949282095	LGE	3	45 BRN	DF	S		V	3/11/2051
2020 PO3948082098	LGE	4	35 BRN	SP	CRE	HH,ID	BD	3/12/2051
2020 PO0761935638	ODP	5	35 BRN	SP	CCA		V	3/13/2051
2020 PO0749635631	ODP	4	40 XXX	SP	CCA		V	3/14/2051
2020 PO4706009805	F	4	40 ACE	SP	CRE		V	3/15/2051
2020 PO4714809756	F	4	40 ACE	SP	CRE		V	3/16/2051
2020 PO1591138612	ODP	2	50 BRN	SP	CCA		V	3/17/2051
2020 PO1610538779	ODP	1	55 BRN	SP	CCA		V	3/18/2051
2020 PO1626738989	ODP	2	60 BRN	SP	CCA		V	3/19/2051
2020 PO1666939146	ODP	2	50 BRN	SP	CCA		V	3/20/2051
2020 PO1646039028	ODP	2	50 BRN	SP	CCA		V	3/21/2051
2020 PO1704739499	ODP	3	45 BRN	SP	CCA		V	3/22/2051
2020 1679739331A	ODP	3	45 BRN	SP	CCA		V	3/23/2051
2020 PO1679739331	ODP	2	50 BRN	SP	CCA		V	3/24/2051
2020 PO1628539044	ODP	4	40 BRN	SP	CRE	ED,ID,SRS	TD	3/25/2051
2020 PO1625139428	ODP	6	30 BRN	SP	CRE	ED,ID	TD	3/26/2051
2020 PO1620639259	ODP	4	45 BRN	SP	CCA		V	3/27/2051
2020 PO1599439237	ODP	4	45 BRN	SP	CCA		V	3/28/2051
2020 PO1581639335	ODP	6	30 BRN	SP	CCA		V	3/29/2051
2020 PO1602639056	ODP	6	30 BRN	SP	CRE	ED,ID	TD	3/30/2051
2020 PO1592739774	ODP	4	45 BRN	SP	CRE		V	3/31/2051
2020 PO1534139812	ODP	4	45 BRN	SP	CRE	ED,ID	TD	4/1/2051
2020 PO1680640750	ODP	6	30 BRN	SP	CRE	ED,ID	TD	4/2/2051
2020 PO1680440565	ODP	6	30 BRN	SP	CCA		V	4/3/2051
2020 PO1680540914	ODP	5	35 BRN	SP	CCA		V	4/4/2051
2020 PO1667340881	ODP	5	35 BRN	SP	CRE	ED,ID	TD	4/5/2051
2020 PO1710841086	ODP	4	45 BRN	SP	CCA		V	4/6/2051
2020 PO3898782849	F	4	40 BRO	SP	A		V	4/7/2051
2020 PO3918882840	F	5	25 BRO	SP	CCA		V	4/8/2051
2020 0975833009a	ODP	6	30 XXX	SP	CRE	ID	BD	4/9/2051
2020 PO0975833009	ODP	4	50 XXX	SP	CRE	ED,ID	TD	4/10/2051
2020 PO3917582844	F	5	25 BRO	SP	CCA		V	4/11/2051
2020 PO3916382858	F	4	40 BRO	SP	A		V	4/12/2051
2020 PO3916082851	F	4	25 BRO	SP	P		V	4/13/2051
2020 PO3946681949	LGE	4	35 BRN	SP	CRE	ED,ID	BD	4/14/2051
2020 PO3947181951	LGE	4	35 BRN	SP	A	ED,ID	TD	4/15/2051
2020 PO3947481964	LGE	4	35 BRN	SP	A	ED,ID	TD	4/16/2051
2020 PO3946981967	LGE	4	35 BRN	SP	A	ED,ID	TD	4/17/2051
2020 PO3945481961	LGE	4	40 BRN	SP	A	ED,ID	TD	4/18/2051
2020 PO3946181959	LGE	3	45 BRN	SP	CCA		V	4/19/2051
2020 PO3944981962	LGE	4	40 BRN	SP	CRE	ED,ID	TD	4/20/2051

2020 PO3943781965	LGE	4	40 BRN	SP	CRE	ED,HH,ID,RB	BX	PX	4/21/2051
2020 PO3942581967	LGE	4	40 BRN	SP	CRE	ED,ID	BD		4/22/2051
2020 PO3940381971	LGE	4	40 BRN	SP	CRE	ED,ID	BD		4/23/2051
2020 PO3940981986	LGE	4	40 BRN	SP	CRE	ED,ID	TD		4/24/2051
2020 PO3941481999	LGE	4	40 BRN	SP	CRE	ED,ID	TD		4/25/2051
2020 PO3943181997	LGE	4	40 BRN	SP	CRE	ED,ID	TD		4/26/2051
2020 PO3944281994	LGE	4	40 BRN	SP	P	ED,ID	T		4/27/2051
2020 PO3945481991	LGE	4	40 BRN	SP	CCA		V		4/28/2051
2020 PO3946382004	LGE	4	40 BRN	SP	CRE	ED,ID	TD		4/29/2051
2020 PO3990782744	LGE	4	30 BRN	SP	CCA		V		4/30/2051
2020 PO3990582737	F	1	50 BRN	SP	S		V		5/1/2051
2020 PO3990182728	F	4	30 BRN	SP	A		V		5/2/2051
2020 PO3990082720	F	4	30 BRN	SP	CCA		V		5/3/2051
2020 PO3990782720	F	4	40 BRN	SP	A		V		5/4/2051
2020 PO3990982706	F	4	40 BRN	SP	CRE		V		5/5/2051
2020 PO3914182846	LGE	5	30 BRO	SP	CCA		V		5/6/2051
2020 PO3915082851	LGE	5	30 BRO	SP	A	ID	BD		5/7/2051
2020 PO3990582691	LGE	4	30 BRN	SP	A	ED,ID,SRC	TX	RR	5/8/2051
2020 18245-41014A	ODP	5	30 KOP	SP	CRE	ED,ID,IP	TD		5/9/2051
2020 PO1813841037	ODP	6	30 KOP	SP	CCA		V		5/10/2051
2020 PO1807240939	F	5	25 KOP	SP	CRE		V		5/11/2051
2020 PO1815640975	ODP	4	45 KOP	SP	S		V		5/12/2051
2020 PO1824541014	F	4	40 KOP	SP	A		V		5/13/2051
2020 PO0963332773	ODP	4	50 XXX	SP	CRE	ID	BD		5/14/2051
2020 PO0958932668	ODP	3	45 XXX	SP	CRE	ED,ID	TD		5/15/2051
2020 PO3914582855	F	3	45 BRO	SP	CCA		V		5/16/2051
2020 PO3914282870	F	6	25 BRO	SP	A		V		5/17/2051
2020 PO3914982867	F	3	45 BRO	SP	CCA		V		5/18/2051
2020 PO3991082690	F	4	40 BRN	SP	A		V		5/19/2051
2020 PO3915582882	F	4	40 BRO	SP	P		V		5/20/2051
2020 PO3916082897	F	4	40 BRO	SP	CCA		V		5/21/2051
2020 PO3897382892	LGE	4	30 BRO	SP	CCA		V		5/22/2051
2020 PO3990682680	F	4	30 BRN	SP	A		V		5/23/2051
2020 PO3991282675	F	4	40 BRN	SP	CRE		V		5/24/2051
2020 PO3990782672	F	4	30 BRN	SP	A		V		5/25/2051
2020 PO0969732886	ODP	4	40 XXX	SP	CRE		V		5/26/2051
2020 PO3991482660	F	4	40 BRN	SP	A		V		5/27/2051
2020 PO3916682911	F	4	40 BRO	SP	P		V		5/28/2051
2020 PO3917182924	F	3	45 BRO	SP	CCA		V		5/29/2051
2020 PO4042743122	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD		5/30/2051
2020 PO3917682937	F	4	40 BRO	SP	P		V		5/31/2051
2020 PO3991682646	F	4	40 BRN	SP	A		V		6/1/2051
2020 PO3917282953	F	5	25 BRO	SP	P		V		6/2/2051
2020 PO3918082950	F	3	45 BRO	SP	CCA		V		6/3/2051
2020 PO3988082575	LGE	4	40 BRN	SP	CRE	ED,ID	BD		6/4/2051
2020 PO3987982572	LGE	4	40 BRN	SP	A	ED,ID	BD		6/5/2051
2020 PO1175735233	ODP	5	35 XXX	SP	CRE		V		6/6/2051

2020 PO1155335399	ODP	4	40 XXX	SP	CRE		V	6/7/2051
2020 PO1125134911	ODP	5	35 XXX	SP	CRE	ED,ID	TD	6/8/2051
2020 PO3922583071	F	4	40 BRO	SP	P		V	6/9/2051
2020 PO3924183074	LGE	4	30 BRO	SP	P		V	6/10/2051
2020 PO3923783065	F	4	40 BRO	SP	P		V	6/11/2051
2020 PO3925483057	F	4	40 BRO	SP	P		V	6/12/2051
2020 PO4036443340	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	6/13/2051
2020 PO1150834868	ODP	5	30 XXX	SP	A		V	6/14/2051
2020 PO1166234860	ODP	6	30 XXX	SP	CCA		V	6/15/2051
2020 PO1157534701	ODP	6	30 XXX	SP	CCA		V	6/16/2051
2020 PO1855940287	ODP	4	45 KOP	SP	S		V	6/17/2051
2020 PO1869940313	ODP	4	45 KOP	SP	S		V	6/18/2051
2020 PO1882740301	ODP	4	45 KOP	SP	S		V	6/19/2051
2020 PO1875640438	ODP	4	45 KOP	SP	S		V	6/20/2051
2020 PO4028943277	KU	4	40 BRO	SP	CRE	ID,IP	BD	6/21/2051
2020 PO4511188012	F	4	40 KOP	SP	CRE	ID,IP,RB	BX	PX 6/22/2051
2020 PO4527188398	F	4	40 KOP	SP	CRE		V	6/23/2051
2020 PO9171971928	KU	5	35 OTH	SP	CCA		V	6/24/2051
2020 PO9178571917	KU	6	30 OTH	SP	CRE	ID	BD	6/25/2051
2020 PO4663388685	LGE	3	50 BRN	SP	CCA		V	6/26/2051
2020 PO3722699620	LGE	3	50 BRN	SP	A	ED,ID	BD	6/27/2051
2020 PO4664788703	LGE	4	35 BRN	SP	CCA	ED,ID	BD	6/28/2051
2020 PO4666288712	F	3	50 BRN	SP	CCA		V	6/29/2051
2020 PO4664588695	LGE	UNK	45 BRN	SP	A		V	6/30/2051
2020 PO4665688708	F	4	40 BRN	SP	CCA		V	7/1/2051
2020 PO9108571482	KU	4	40 OTH	SP	CRE	ID	BD	7/2/2051
2020 PO9078371235	KU	4	40 OTH	SP	CRE	ID	BD	7/3/2051
2020 PO4667888715	LGE	4	40 BRN	SP	CCA		V	7/4/2051
2020 PO4667488724	LGE	3	50 BRN	SP	A	ED,ID	BD	7/5/2051
2020 PO3764399996	LGE	2	55 BRN	SP	CCA		V	7/6/2051
2020 PO4667988727	LGE	4	35 BRN	SP	CCA		V	7/7/2051
2020 PO9194772311A	KU	2	50 OTH	SP	CCA		V	7/8/2051
2020 PO8726665967	KU	4	40 XXX	SP	CRE	ED,ID,RB	X	RP1 7/9/2051
2020 PO8708966248	KU	4	45 XXX	SP	CCA		V	7/10/2051
2020 PO8705866435	KU	4	40 XXX	SP	CRE	ID	BD	7/11/2051
2020 PO8694666434	KU	5	35 XXX	SP	CCA		V	7/12/2051
2020 PO7828360780	KU	4	40 XXX	SP	CRE	ID	BD	7/13/2051
2020 PO7894959611	KU	2	45 XXX	SP	CCA		V	7/14/2051
2020 PO7875059585	KU	3	55 XXX	SP	CCA		V	7/15/2051
2020 PO7892759342	KU	2	50 XXX	SP	CCA		V	7/16/2051
2020 PO7883159477	KU	3	55 XXX	SP	CCA		V	7/17/2051
2020 PO7864259749	KU	3	55 XXX	SP	CCA		V	7/18/2051
2020 PO7860259829	KU	1	55 XXX	SP	CCA		V	7/19/2051
2020 PO7884860087	KU	1	55 XXX	SP	CCA		V	7/20/2051
2020 PO7869960274	KU	1	55 XXX	SP	CCA		V	7/21/2051
2020 PO7857160455	KU	1	55 XXX	SP	CCA		V	7/22/2051
2020 PO7856860761	KU	3	45 XXX	SP	CCA		V	7/23/2051

2020 PO7854060485	KU	2	55 XXX	SP	CCA		V			7/24/2051
2020 PO7843160638	KU	3	45 XXX	SP	CCA		V			7/25/2051
2020 PO4654888728	LGE	4	40 BRN	SP	P	ED,ID,IP	BX	RR		7/26/2051
2020 PO0597964137	KU	5	35 BRN	SP	CRE		V			7/27/2051
2020 PO0596663823	KU	2	45 BRN	SP	CRE		V			7/28/2051
2020 PO0629263895	KU	6	30 BRN	SP	CCA		V			7/29/2051
2020 PO3753246234	KU	4	40 BRO	SP	CRE	ED	TD			7/30/2051
2020 PO3771346077	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD			7/31/2051
2020 PO1886545046	ODP	4	40 SWP	SP	CRE	ID	TD			8/1/2051
2020 PO1851145125	ODP	6	30 SWP	SP	CRE		V			8/2/2051
2020 PO1857245243	ODP	5	35 SWP	SP	CRE		V			8/3/2051
2020 PO1855345572	ODP	4	40 SWP	SP	CRE	ED,ID	TD			8/4/2051
2020 PO1830545573	ODP	4	45 BRN	SP	CCA		V			8/5/2051
2020 PO1841645858	ODP	5	35 SWP	SP	CRE		V			8/6/2051
2020 1861746325A	ODP	4	35 BRN	SP	CRE	ED,ID,SRC	TD			8/7/2051
2020 PO1872946218	ODP	5	35 BRN	SP	CRE	ED,ID	TD			8/8/2051
2020 PO1880346027	ODP	5	35 BRN	SP	CRE	ED,ID	TD			8/9/2051
2020 1823447444A	ODP	4	40 BRN	SP	CRE	ED,ID	TD			8/10/2051
2020 PO1839747156	ODP	3	45 BRN	SP	CCA		V			8/11/2051
2020 PO1834947283	ODP	4	40 BRN	SP	CRE	ED,ID	TD			8/12/2051
2020 1795847646A	ODP	5	30 UNK	SP	CRE	ED,ID,SRS	TD			8/13/2051
2020 PO1823447444	ODP	4	45 UNK	SP	CRE	ED,ID	TD			8/14/2051
2020 PO1805147390	ODP	4	45 UNK	SP	CRE	ED,ID	TD			8/15/2051
2020 PO1812247570	ODP	4	40 ACW	SP	CRE	ED,ID,SRS	TD			8/16/2051
2020 PO1825447717	ODP	4	40 ACW	SP	CRE	ED,ID	TD			8/17/2051
2020 PO1832247796	ODP	6	30 UNK	SP	CRE	ED,ID	TD			8/18/2051
2020 PO1842447869	ODP	4	40 UNK	SP	CRE	ED,ID	TD			8/19/2051
2020 PO1816147742	ODP	5	35 BRN	SP	CRE	ED,ID	TD			8/20/2051
2020 179587646A	ODP	6	30 BRN	SP	CRE	ED,ID	TD			8/21/2051
2020 1832247796A	ODP	6	20 BRN	SP	CRE	ED,ID,RB	VX	RP1		8/22/2051
2020 PO3916982666	F	4	30 BRO	SP	CCA		V			8/23/2051
2020 PO3917982655	F	4	40 BRO	SP	CCA		V			8/24/2051
2020 PO3916882662	F	4	40 BRO	SP	CCA		V			8/25/2051
2020 PO3914482668	F	4	30 BRO	SP	CCA		V			8/26/2051
2020 PO3913482677	F	4	30 BRO	SP	CCA		V			8/27/2051
2020 PO3914882675	F	4	40 BRO	SP	CCA		V			8/28/2051
2020 PO4655188725	LGE	4	40 BRN	SP	CRE	ED,HH,ID,RB	BX	PX		8/29/2051
2020 PO9650574941	KU	4	35 XXX	SP	P	ED	T			8/30/2051
2020 PO9651674861	KU	5	35 XXX	SP	CRE	ID,IP	TD			8/31/2051
2020 PO4821288241	LGE	4	30 BRO	SP	CRE	ED,ID	TD			9/1/2051
2020 PO4656888699	LGE	3	45 BRN	SP	CCA		V			9/2/2051
2020 PO4656088711	LGE	3	45 BRN	SP	CCA		V			9/3/2051
2020 PO4820788242	LGE	4	35 BRO	SP	CRE	ED	TD			9/4/2051
2020 PO9672674914A	KU	6	30 XXX	SP	P	ED	T			9/5/2051
2020 PO9672674914	KU	6	30 XXX	SP	P	ED	T			9/6/2051
2020 PO4661788752	LGE	4	35 BRN	SP	A	ED,ID	BD			9/7/2051
2020 PO4662088736	LGE	4	40 BRN	SP	CRE	ED,HH,ID	BX	PX		9/8/2051

2020 PO3950839225	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/9/2051
2020 PO3960039380	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/10/2051
2020 PO3914082681	F	3	45 BRO	SP	CCA		V	9/11/2051
2020 PO4662588739	LGE	3	45 BRN	SP	CCA		V	9/12/2051
2020 PO3913082688	F	4	30 BRO	SP	CCA		V	9/13/2051
2020 PO3913782688	F	4	40 BRO	SP	CCA		V	9/14/2051
2020 PO3915582662	F	5	25 BRO	SP	CCA		V	9/15/2051
2020 PO3919982665	F	4	40 BRO	SP	CCA		V	9/16/2051
2020 PO3915882668	F	4	40 BRO	SP	CCA		V	9/17/2051
2020 PO3941482734	F	4	35 BRO	SP	CCA		V	9/18/2051
2020 PO3943282726	LGE	3	50 BRO	SP	P	ED,ID,IP	BD	9/19/2051
2020 PO3944582720	LGE	3	45 BRO	SP	P	ED,ID	BD	9/20/2051
2020 PO3945782715	LGE	3	45 BRO	SP	P	ED,ID	BD	9/21/2051
2020 PO3947082709	LGE	3	45 BRO	SP	P	ED,ID	BD	9/22/2051
2020 PO3935782699a	LGE	5	35 BRO	SP	P	ED,ID	TD	9/23/2051
2020 PO3935782699	LGE	4	35 BRO	SP	A	ED,ID	TD	9/24/2051
2020 PO3941383019	F	4	40 BRO	SP	P		V	9/25/2051
2020 PO3734346399	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	9/26/2051
2020 PO4026882825	F	4	40 BRN	SP	CCA		V	9/27/2051
2020 PO4028182829	F	4	40 BRN	SP	A		V	9/28/2051
2020 PO3967239501	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/29/2051
2020 PO4819588252	LGE	4	35 BRO	SP	CRE	ED	TD	9/30/2051
2020 PO4821888253	LGE	4	35 BRO	SP	CRE	ED	TD	10/1/2051
2020 PO4822388239	LGE	4	30 BRO	SP	CRE	ED	TD	10/2/2051
2020 PO4823988245	LGE	4	35 BRO	SP	CRE	ED	TD	10/3/2051
2020 PO4660788727	LGE	4	40 BRN	SP	CRE	ED,HH,ID,RB	BX	PX 10/4/2051
2020 PO9694675115	KU	6	30 XXX	SP	P	ED	T	10/5/2051
2020 PO9691974988	KU	4	40 XXX	SP	P	ED	T	10/6/2051
2020 PO9657874581	KU	5	35 XXX	SP	CRE	HH,ID	BX	RP2 10/7/2051
2020 PO4659988721	LGE	3	45 BRN	SP	A	ED,ID	BD	10/8/2051
2020 PO4659488719	LGE	3	45 BRN	SP	CCA		V	10/9/2051
2020 PO4658188710	LGE	4	40 BRN	SP	CCA		V	10/10/2051
2020 PO4660688710	LGE	4	40 BRN	SP	A	ED,ID	TD	10/11/2051
2020 PO4661488699	LGE	4	40 BRN	SP	A	ED,ID	BD	10/12/2051
2020 PO4662188688	LGE	4	40 BRN	SP	A	ED,ID,IP	BD	10/13/2051
2020 PO4823288209	LGE	4	30 BRO	SP	CRE	ED	BD	10/14/2051
2020 PO3717546592	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	10/15/2051
2020 PO3719346531	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	10/16/2051
2020 PO3704546665	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	10/17/2051
2020 PO7590321099	KU	4	45 BRN	SP	CRE	ED	TD	10/18/2051
2020 PO7597021278	KU	3	50 BRN	SP	CRE	ED	TD	10/19/2051
2020 PO7604621397	KU	3	55 BRN	SP	CCA		V	10/20/2051
2020 PO7623421667	KU	3	55 XXX	SP	CRE	ED	TD	10/21/2051
2020 PO7643121814	KU	4	45 XXX	SP	CRE		V	10/22/2051
2020 PO7628021932	KU	4	40 XXX	SP	CRE	ED	TD	10/23/2051
2020 PO7636922224	KU	4	45 KOP	SP	CRE	ED	TD	10/24/2051
2020 PO7653522805	KU	4	45 BRN	SP	CRE	ED	TD	10/25/2051

2020 PO7644922513	KU	4	45 BRN	SP	CRE	ED	TD	10/26/2051	
2020 PO7662222969	KU	4	45 ACW	SP	CRE	ED	TD	10/27/2051	
2020 PO7672223150	KU	4	45 ACW	SP	CRE	ED	TD	10/28/2051	
2020 PO7694623122	KU	4	45 ACW	SP	CRE		BD	10/29/2051	
2020 PO7709523344	KU	4	40 ACW	SP	CRE	ED	TD	10/30/2051	
2020 PO7722923536	KU	4	40 ACW	SP	CRE	ED	TD	10/31/2051	
2020 PO7739923781	KU	4	40 ACW	SP	CRE	ED	TD	11/1/2051	
2020 PO7753323988	KU	4	40 ACW	SP	CRE	ED,ID	TD	11/2/2051	
2020 PO7764224154	KU	4	40 ACW	SP	CRE	ED,ID	X	RP3	11/3/2051
2020 PO7774524313	KU	4	35 ACW	SP	CRE	ED,ID	TD	11/4/2051	
2020 PO7793924500	KU	5	35 ACW	SP	CCA	ED,ID	TD	11/5/2051	
2020 PO7792324516	KU	4	45 ACW	SP	CRE	ED	TD	11/6/2051	
2020 PO7694924688	F	4	40 ACW	SP	CRE		V	11/7/2051	
2020 PO7702624812	KU	4	40 ACW	SP	CRE		V	11/8/2051	
2020 PO7717624890	KU	4	40 ACW	SP	CRE	ED	TD	11/9/2051	
2020 PO7724725103	KU	4	40 ACW	SP	CRE	ED	TD	11/10/2051	
2020 PO3938282716	LGE	4	35 BRO	SP	CCA		V	11/11/2051	
2020 PO3937382708	LGE	4	35 BRO	SP	P	ED,ID	TD	11/12/2051	
2020 PO3948282703	LGE	3	45 BRO	SP	P	ED,ID	BD	11/13/2051	
2020 PO3949682696	LGE	4	50 BRO	SP	CCA		V	11/14/2051	
2020 PO6688238460	LGE	4	35 BRO	SP	CCA		V	11/15/2051	
2020 PO4028782795	F	4	40 BRN	SP	A		V	11/16/2051	
2020 PO3893644767	KU	4	40 BRN	SP	CRE	ID	BD	11/17/2051	
2020 PO3938483033	F	4	40 BRO	SP	P		V	11/18/2051	
2020 PO3939883026	F	4	40 BRO	SP	P		V	11/19/2051	
2020 PO3938183029	F	4	30 BRO	SP	P		V	11/20/2051	
2020 PO3940983017	LGE	4	30 BRO	SP	P	ED,ID	TD	11/21/2051	
2020 PO3919844478	KU	4	40 BRN	SP	CRE	ID,IP	BD	11/22/2051	
2020 PO3903044912	F	4	40 BRN	SP	CRE		V	11/23/2051	
2020 PO3905044641	KU	4	40 BRN	SP	CRE	ED,ID,IP,RB	X	RP2	11/24/2051
2020 PO8269001241	KU	4	40 XXX	SP	CRE	ED,ID	TD	11/25/2051	
2020 PO8293901266	KU	4	40 XXX	SP	CRE	ED,ID	TD	11/26/2051	
2020 PO7198489524	F	4	40 BRO	SP	CRE		V	11/27/2051	
2020 PO7216189402	F	4	35 BRO	SP	CRE		V	11/28/2051	
2020 PO7206889465	F	4	35 BRO	SP	CRE		V	11/29/2051	
2020 PO8324901228	KU	4	40 XXX	SP	CRE	ED,ID	TD	11/30/2051	
2020 PO8316701184	KU	5	30 XXX	SP	CCA		V	12/1/2051	
2020 PO8351500904	KU	4	40 XXX	SP	CRE	ED,ID	TD	12/2/2051	
2020 PO7270286558	F	4	45 BRN	SP	P		V	12/3/2051	
2020 PO7265886631	F	4	40 BRN	SP	CRE		V	12/4/2051	
2020 PO7265686532	KU	3	55 BRN	SP	CCA		V	12/5/2051	
2020 PO7299885952	KU	4	45 BRN	SP	CRE	ED,ID	BD	12/6/2051	
2020 PO7964774271	F	4	40 BRO	SP	CRE		V	12/7/2051	
2020 PO7900274070	KU	4	40 BRO	SP	CRE		B	12/8/2051	
2020 PO7892474128	KU	4	40 BRO	SP	CRE	ED,ID	TD	12/9/2051	
2020 PO7882274204	KU	4	40 BRO	SP	CCA		V	12/10/2051	
2020 PO7871474283	KU	4	40 BRO	SP	CCA		V	12/11/2051	

2020 PO7882674059	KU	6	30 BRO	SP	CRE	ED,ID	TD	12/12/2051
2020 PO5447509462	KU	4	40 BRO	SP	CRE		V	12/13/2051
2020 PO5407108399	KU	3	45 BRO	SP	CCA		V	12/14/2051
2020 PO5403408472	KU	6	30 BRO	SP	CRE	ID	TD	12/15/2051
2020 PO5398408461	KU	4	40 BRO	SP	CCA		V	12/16/2051
2020 PO5396408446	KU	6	30 BRO	SP	CRE		V	12/17/2051
2020 PO5406808510	KU	4	40 BRO	SP	CCA		V	12/18/2051
2020 PO6849693249	KU	4	40 XXX	SP	CRE	ED,ID	TD	12/19/2051
2020 PO3913182616	LGE	4	40 BRN	SP	P	ED,ID	TD	12/20/2051
2020 9152118432A	KU	5	35 UNK	SP	CRE	ID	TD	12/21/2051
2020 PO9164918472	F	5	40 UNK	SP	CRE	ED,ID	BD	12/22/2051
2020 PO9163718994	KU	3	50 BRN	SP	CCA		V	12/23/2051
2020 PO9152118432	KU	4	40 BRN	SP	CCA		V	12/24/2051
2020 PO9155318541	KU	4	40 UNK	SP	CRE	ED,ID,SRC	TD	12/25/2051
2020 PO9146418258	KU	5	35 UNK	SP	CRE	ED,ID,SRC	TX	RR 12/26/2051
2020 PO9162418747	KU	4	40 OTH	SP	CRE	ID	TD	12/27/2051
2020 PO9130818839	KU	6	30 BRN	SP	CCA		V	12/28/2051
2020 PO9128019082	KU	6	30 KOP	SP	CRE	ED,ID	TD	12/29/2051
2020 PO9133518718	KU	4	40 OTH	SP	CRE	ID	TD	12/30/2051
2020 PO5413408579	KU	6	30 BRO	SP	CRE	ID	TD	12/31/2051
2020 PO9174218924	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	1/1/2052
2020 PO5414108760	KU	6	30 BRO	SP	CCA		V	1/2/2052
2020 PO5415708604	KU	5	30 BRO	SP	CRE	ID	TD	1/3/2052
2020 PO5413208555	KU	6	30 BRO	SP	CRE		V	1/4/2052
2020 PO5421608757	KU	3	45 BRO	SP	CCA		V	1/5/2052
2020 PO5420708808	KU	4	40 BRO	SP	CRE	ID	TD	1/6/2052
2020 PO5427808882	KU	5	35 BRO	SP	CRE		V	1/7/2052
2020 PO5432708849	KU	6	35 BRO	SP	CRE		V	1/8/2052
2020 PO5432008919	KU	4	40 BRO	SP	CRE	ID	TD	1/9/2052
2020 PO5435608875	KU	5	35 BRO	SP	CRE	ID	TD	1/10/2052
2020 PO5438508932	F	4	40 BRO	SP	CRE		V	1/11/2052
2020 PO5444008951	KU	4	45 BRO	SP	CCA	ED	T	1/12/2052
2020 PO5441608994	KU	6	30 BRO	SP	CCA	ED	T	1/13/2052
2020 PO5468609125	KU	4	40 BRO	SP	CCA		V	1/14/2052
2020 PO546860912405a	KU	5	30 BRO	SP	CCA		V	1/15/2052
2020 PO5482309232	KU	4	40 BRO	SP	CRE		V	1/16/2052
2020 PO5489009285	KU	4	40 BRO	SP	CRE	ID	TD	1/17/2052
2020 PO5509009439	KU	4	40 BRO	SP	CRE	ID	TD	1/18/2052
2020 PO9137917940	KU	4	40 INP	SP	CRE	ID	TD	1/19/2052
2020 PO9176118778	KU	4	35 OTH	SP	CCA		V	1/20/2052
2020 PO3945582815	LGE	4	45 BRO	SP	P	ED,ID	TD	1/21/2052
2020 PO3946182813	LGE	4	45 BRO	SP	P	ED,ID	TD	1/22/2052
2020 PO3945382809	LGE	4	40 BRO	SP	P	ED,ID	TD	1/23/2052
2020 PO6637639435	LGE	4	35 BRO	SP	CCA		V	1/24/2052
2020 PO3943982751	LGE	4	30 BRO	SP	A	ED,ID	TD	1/25/2052
2020 PO2718837512	KU	4	40 BRN	SP	P	ED	T	1/26/2052
2020 PO3914482607	LGE	4	40 BRN	SP	CRE	ED,ID	TD	1/27/2052

2020 PO1044832407	ODP	2	70 XXX	SP	CRE	ED,ID	TD	1/28/2052
2020 PO1022732289	ODP	5	35 XXX	SP	CCA	ED	T	1/29/2052
2020 PO1018932428	ODP	4	45 XXX	SP	CRE	ED,ID	TD	1/30/2052
2020 PO1066132406	ODP	5	35 XXX	SP	CCA		V	1/31/2052
2020 PO2743037563	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	2/1/2052
2020 PO2767737602	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	2/2/2052
2020 PO5422909504	KU	4	35 BRO	SP	CCA		V	2/3/2052
2020 PO1556910316	KU	6	30 BRN	SP	CCA		V	2/4/2052
2020 PO5412009689	KU	4	40 BRO	SP	CRE	ID	TD	2/5/2052
2020 PO5406809775	KU	4	40 BRO	SP	CRE	ID	TD	2/6/2052
2020 PO5429009391	F	4	40 BRO	SP	CRE		V	2/7/2052
2020 PO5411010042	KU	6	30 BRO	SP	CCA		V	2/8/2052
2020 PO5409310022	KU	4	40 BRO	SP	CRE	ID	BD	2/9/2052
2020 PO5418810083	KU	5	35 BRO	SP	CRE	ID	TD	2/10/2052
2020 PO5433409876	KU	4	40 BRO	SP	CRE	ID	TD	2/11/2052
2020 PO5418309724	KU	6	30 BRO	SP	CCA		V	2/12/2052
2020 PO5416209761	F	4	40 BRO	SP	CRE		V	2/13/2052
2020 PO5421609808	KU	4	40 BRO	SP	CRE	ID	TD	2/14/2052
2020 PO5424009642	F	4	40 BRO	SP	CRE		V	2/15/2052
2020 PO5433309597	KU	4	40 BRO	SP	CRE	ID	TD	2/16/2052
2020 PO5443309438	KU	5	35 BRO	SP	CRE	ID	TD	2/17/2052
2020 PO5435209437	F	4	40 BRO	SP	CRE		V	2/18/2052
2020 PO5460809312	KU	4	40 BRO	SP	CCA		V	2/19/2052
2020 PO5466309364	KU	3	45 BRO	SP	CCA		V	2/20/2052
2020 PO5461009492	KU	3	45 BRO	SP	CCA		V	2/21/2052
2020 PO1517110223	KU	3	45 BRN	SP	CCA		V	2/22/2052
2020 PO1502209770	KU	4	40 KOP	SP	CRE	ED,ID	TD	2/23/2052
2020 PO1532909717	KU	5	35 UNK	SP	CRE	ED,ID	TD	2/24/2052
2020 PO1520810109	F	3	45 INP	SP	CCA		V	2/25/2052
2020 PO1528710173	KU	4	40 BRN	SP	CRE	ED,ID	TD	2/26/2052
2020 PO1544610257	KU	5	35 BRN	SP	CCA		V	2/27/2052
2020 PO1567510155	KU	6	30 UNK	SP	CRE	ED,ID	TD	2/28/2052
2020 PO1530510314	KU	5	35 UNK	SP	CRE	ED,EP,ID,SRS	TD	2/29/2052
2020 PO1550410448	KU	5	35 UNK	SP	CRE	ED,ID	TD	3/1/2052
2020 PO1562110782	KU	6	30 ACW	SP	CRE	ED,ID,SRS	TD	3/2/2052
2020 PO1586810699	KU	5	35 KOP	SP	CRE		V	3/3/2052
2020 PO1570910446	KU	5	35 KOP	SP	CRE	ED,ID,SRS	TD	3/4/2052
2020 PO1600610336	KU	6	30 KOP	SP	CCA		V	3/5/2052
2020 PO1591810303	KU	6	30 UNK	SP	CRE	ED,ID	TD	3/6/2052
2020 PO1591110425	KU	4	40 UNK	SP	CRE	ED,ID	TD	3/7/2052
2020 PO1615710402	KU	3	45 BRN	SP	CCA		V	3/8/2052
2020 PO7880273989	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/9/2052
2020 PO7005321492	KU	4	40 XXX	SP	CRE	ID	BD	3/10/2052
2020 PO7871074048	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/11/2052
2020 PO7860874126	KU	4	40 BRO	SP	CCA		V	3/12/2052
2020 PO7904073767	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/13/2052
2020 PO7320385605	KU	4	40 BRN	SP	CRE	ED,ID	BD	3/14/2052

2020 PO7316985749	F	4	45 BRN	SP	P		V			3/15/2052
2020 PO7313385811	F	4	40 BRN	SP	CRE		V			3/16/2052
2020 PO7313285726	KU	4	40 BRN	SP	CRE	ED,ID	BD			3/17/2052
2020 PO7305585973	KU	4	45 BRN	SP	P	ED,EP,ID,SRC	TX	RR		3/18/2052
2020 PO7305885850	KU	4	40 BRN	SP	CRE	ED,ID	TD			3/19/2052
2020 PO7293386063	KU	4	45 BRN	SP	CRE	ED,ID	TD			3/20/2052
2020 PO7936373662	KU	4	40 BRO	SP	CRE	ED,ID	TD			3/21/2052
2020 PO7947473450	KU	4	40 BRO	SP	CRE		B			3/22/2052
2020 PO7923773500	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			3/23/2052
2020 PO7917873592	KU	4	40 BRO	SP	CCA		V			3/24/2052
2020 PO7329485459	KU	4	45 BRN	SP	CCA		V			3/25/2052
2020 PO7005321492A	KU	5	30 XXX	SP	CRE	ID	BD			3/26/2052
2020 PO7004221435	KU	6	30 XXX	SP	CCA		V			3/27/2052
2020 PO6985321351	KU	6	30 XXX	SP	CRE	ID	TD			3/28/2052
2020 PO6967121261	KU	6	30 XXX	SP	CCA	ED	T			3/29/2052
2020 PO6975721323	KU	4	40 XXX	SP	CCA		V			3/30/2052
2020 PO6967621398	KU	4	40 XXX	SP	CCA		V			3/31/2052
2020 PO6947421306	KU	4	40 XXX	SP	CCA		V			4/1/2052
2020 PO6948821232	KU	5	30 XXX	SP	CCA		V			4/2/2052
2020 PO6932821349	KU	4	40 XXX	SP	CCA		V			4/3/2052
2020 PO6926221201	KU	4	40 XXX	SP	CCA		V			4/4/2052
2020 PO6920920946	F	3	45 XXX	SP	P		V			4/5/2052
2020 PO6907720729	KU	4	40 XXX	SP	CCA		V			4/6/2052
2020 PO6895220793	KU	6	30 XXX	SP	CCA		V			4/7/2052
2020 PO6892120589	KU	4	35 XXX	SP	CRE	ID	TD			4/8/2052
2020 PO6887219362A	KU	6	30 XXX	SP	CRE	ID	TD			4/9/2052
2020 PO6875619794C	KU	5	35 XXX	SP	P		V			4/10/2052
2020 PO6875619794B	KU	5	35 XXX	SP	P		V			4/11/2052
2020 PO7335785454	F	3	50 BRN	SP	CRE		V			4/12/2052
2020 PO6893420217	KU	4	45 XXX	SP	CRE	ID	TD			4/13/2052
2020 PO7335185375	KU	4	45 BRN	SP	CCA	ED,ID	V			4/14/2052
2020 PO7341185370	F	2	45 BRN	SP	CRE		V			4/15/2052
2020 PO7347885226	F	4	35 BRN	SP	P		V			4/16/2052
2020 PO7341585244	KU	4	40 BRN	SP	CRE	ED,ID	TD			4/17/2052
2020 PO7349585132	KU	4	40 BRN	SP	CRE	ED,ID	TD			4/18/2052
2020 PO7355985114	F	4	40 BRN	SP	CRE		V			4/19/2052
2020 PO7356685014	KU	4	45 BRN	SP	CRE	ED,ID	TD			4/20/2052
2020 PO7913873977	KU	4	45 BRO	SP	CRE	ED,ID	TD			4/21/2052
2020 PO7373484734	KU	4	45 BRN	SP	CRE	ED,ID,IP	TD			4/22/2052
2020 PO7363584900	KU	4	40 BRN	SP	CRE	ED,ID	TD			4/23/2052
2020 PO7369784795	KU	5	45 BRN	SP	CRE	ED,ID	TD			4/24/2052
2020 PO7381984595	KU	4	40 BRN	SP	CRE	ED,ID	TD			4/25/2052
2020 PO7391084446	KU	4	40 BRN	SP	CRE	ED,ID	TD			4/26/2052
2020 PO7362885000	F	5	35 BRN	SP	CCA		V			4/27/2052
2020 PO7374184811	F	2	45 BRN	SP	CRE		V			4/28/2052
2020 PO7379384741	KU	5	35 BRN	SP	CCA		V			4/29/2052
2020 PO6917720340	KU	6	30 XXX	SP	CCA		V			4/30/2052

2020 PO6932120327	KU	4	45 XXX	SP	CRE	ID	BD		5/1/2052
2020 PO6913020203	KU	4	45 XXX	SP	CRE	ID	BD		5/2/2052
2020 PO6876719578	KU	6	30 XXX	SP	CCA		V		5/3/2052
2020 PO6886119574	F	4	40 XXX	SP	CCA		V		5/4/2052
2020 PO7006021124	KU	6	30 XXX	SP	CRE		V		5/5/2052
2020 PO3917482481	F	4	40 BRN	SP	CCA		V		5/6/2052
2020 PO3918682474	F	4	40 BRN	SP	CCA		V		5/7/2052
2020 PO4585434552	KU	3	45 ACE	SP	CRE	ED,ID	BD		5/8/2052
2020 PO2549749901	KU	4	35 BRO	SP	CRE	ED,ID,IP	TD		5/9/2052
2020 PO2651550562	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		5/10/2052
2020 PO3919982465	F	4	40 BRN	SP	CCA		V		5/11/2052
2020 PO7108289534	KU	5	35 BRN	SP	CRE	ED,ID	BD		5/12/2052
2020 PO3921282458	F	4	45 BRN	SP	CRE		VX	PX	5/13/2052
2020 PO3923582479	F	4	35 BRN	SP	P		V		5/14/2052
2020 PO4568934688	KU	2	60 ACE	SP	CRE	ED,ID	BD		5/15/2052
2020 PO7380484706	F	4	35 BRN	SP	CRE		V		5/16/2052
2020 PO4564634724	KU	2	60 ACE	SP	CRE	ED,EP,HH,ID,IP,MD,RB	BX	RP1	5/17/2052
2020 PO7387284595	F	4	40 BRN	SP	CRE	ED,HH,ID,RB	VX	PX	5/18/2052
2020 PO7401984352	F	5	35 BRN	SP	CRE		V		5/19/2052
2020 PO7393784490	F	4	40 BRN	SP	CRE		V		5/20/2052
2020 PO7921873666	KU	6	30 BRO	SP	CCA		V		5/21/2052
2020 PO7911873686	KU	4	40 BRO	SP	CRE	ED,ID	TX	RR	5/22/2052
2020 PO7921573865	KU	4	40 BRO	SP	CRE	ED,ID	TD		5/23/2052
2020 PO7895373876	KU	4	40 BRO	SP	CRE	ED,ID	TD		5/24/2052
2020 PO7901873914	KU	4	40 BRO	SP	CRE	ED,ID	TD		5/25/2052
2020 PO7906673867	KU	6	30 BRO	SP	CRE	ED,ID	TD		5/26/2052
2020 PO5308007196	KU	6	30 XXX	SP	CRE		V		5/27/2052
2020 PO7406084191	F	4	45 BRN	SP	CRE		V		5/28/2052
2020 PO3325263830	KU	4	40 BRN	SP	CRE	ID	TD		5/29/2052
2020 PO3022868077	KU	4	40 BRN	SP	CRE	HH,RB	X	RP1	5/30/2052
2020 PO3922682479	F	4	30 BRN	SP	CRE		V		5/31/2052
2020 PO3922582485	F	3	40 BRN	SP	CCA		V		6/1/2052
2020 PO0992232243	ODP	5	35 XXX	SP	CRE	ED,ID	TD		6/2/2052
2020 PO0993632349	ODP	6	30 XXX	SP	CRE	ED,ID	TD		6/3/2052
2020 PO0985132387	ODP	4	40 XXX	SP	CRE	ED,ID	TD		6/4/2052
2020 PO0992132504	ODP	4	50 XXX	SP	CRE	ED,ID	TD		6/5/2052
2020 PO3921282493	F	4	40 BRN	SP	P		V		6/6/2052
2020 PO7130789521	KU	5	35 BRN	SP	CRE	ED,ID	TD		6/7/2052
2020 PO7123989372	KU	5	35 BRN	SP	CRE	ED,ID	BD		6/8/2052
2020 PO3919982501	F	4	40 BRN	SP	CCA		V		6/9/2052
2020 PO2814737683	KU	4	40 BRN	SP	CRE	ID	BD		6/10/2052
2020 PO2789937641	KU	5	35 BRN	SP	CRE	ID,IP	BD		6/11/2052
2020 PO2830136304	KU	4	45 BRN	SP	CRE	ID,IP	BD		6/12/2052
2020 PO3917482517	F	4	40 BRN	SP	CCA		V		6/13/2052
2020 PO3915682523	F	4	30 BRN	SP	CCA		V		6/14/2052
2020 PO3916182525	F	4	40 BRN	SP	CRE		V		6/15/2052
2020 PO0670366300	KU	4	40 BRO	SP	P	ED	T		6/16/2052

2020 PO3904482597	F	4	40 BRN	SP	CRE	ED,HH,ID,IP,RB	VX	PX	6/17/2052
2020 PO0638766487	KU	5	35 BRO	SP	CRE	ID,IP	BD		6/18/2052
2020 PO0698866535	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD		6/19/2052
2020 PO0697466427	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		6/20/2052
2020 PO0687966360	KU	5	35 BRO	SP	CRE	ED,ID	BD		6/21/2052
2020 PO0706366587	F	4	40 BRO	SP	CRE		V		6/22/2052
2020 PO3241465073	KU	5	30 BRN	SP	CRE	ID,IP	TD		6/23/2052
2020 PO3271765266	KU	6	30 BRN	SP	CCA		V		6/24/2052
2020 PO9516755140	KU	4	40 BRO	SP	CRE		V		6/25/2052
2020 PO9615055401	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD		6/26/2052
2020 PO3285365376	KU	4	40 BRN	SP	CRE	HH,ID	TX	RR	6/27/2052
2020 PO3230165246	KU	4	40 BRN	SP	CRE	ID	TD		6/28/2052
2020 PO9522755222	KU	5	30 BRO	SP	CRE	ED,ID,SRC	TD		6/29/2052
2020 PO9493255345	KU	4	40 BRO	SP	CRE	ID,IP	BD		6/30/2052
2020 PO9435355930	KU	3	45 BRO	SP	P		B		7/1/2052
2020 PO9516755722	KU	4	40 BRO	SP	CRE	ID	BD		7/2/2052
2020 PO0675160034	KU	5	35 ACW	SP	CRE	ED,ID	TD		7/3/2052
2020 PO0671259993	KU	4	45 ACW	SP	CRE	ED,ID	BD		7/4/2052
2020 PO3948382770	LGE	4	40 BRO	SP	P	ID	V		7/5/2052
2020 PO3950082778	LGE	4	40 BRO	SP	CCA		V		7/6/2052
2020 PO3949482778	LGE	3	45 BRO	SP	CCA		V		7/7/2052
2020 PO3949782772	LGE	4	35 BRO	SP	CCA		V		7/8/2052
2020 PO4669134595	KU	3	45 ACE	SP	CRE	ED,ID,IP	BD		7/9/2052
2020 PO3883382953	LGE	4	35 BRO	SP	P	ED,ID	TD		7/10/2052
2020 PO2635250718	KU	4	40 BRO	SP	CRE	ED	TD		7/11/2052
2020 PO2673750346	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD		7/12/2052
2020 9138617651A	KU	6	30 INP	SP	CRE	ID	TD		7/13/2052
2020 9211219995A	KU	3	50 BRN	SP	CCA		V		7/14/2052
2020 9211219995B	KU	3	55 OTH	SP	CCA		V		7/15/2052
2020 9146019389A	KU	6	30 BRN	SP	CRE	ID	TD		7/16/2052
2020 PO9139317402	KU	5	35 OTH	SP	CRE	ED,ID,SRC	TD		7/17/2052
2020 PO3219965460	KU	4	40 BRN	SP	CCA		V		7/18/2052
2020 PO9167619888	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD		7/19/2052
2020 PO0664659904	KU	2	40 ACW	SP	CRE	ED,ID	BD		7/20/2052
2020 PO0667060010	KU	4	45 ACW	SP	CRE	ED,EP,HH,ID,IP,RB	X	RP1	7/21/2052
2020 PO3203965776	KU	4	40 BRN	SP	CRE	ID	BD		7/22/2052
2020 PO0656660054	KU	4	40 ACW	SP	CRE	ED,ID,IP	BD		7/23/2052
2020 PO0642860113	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		7/24/2052
2020 PO0656560117	F	4	40 ACW	SP	CRE		V		7/25/2052
2020 PO3198865885	KU	4	40 BRN	SP	CCA		V		7/26/2052
2020 PO3188366123	KU	4	40 BRN	SP	CRE	ID,IP	TD		7/27/2052
2020 PO0629660173	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		7/28/2052
2020 PO0632360220	F	4	40 ACW	SP	CRE		V		7/29/2052
2020 PO0645160165	F	4	40 ACW	SP	CRE		V		7/30/2052
2020 PO0620760271	F	5	35 ACW	SP	CRE		V		7/31/2052
2020 PO0616260229	KU	4	40 ACW	ST	CRE	ED,ID,IP	BD		8/1/2052
2020 PO0597060313	KU	4	45 ACW	SP	CRE	ED,ID	BD		8/2/2052

2020 PO3177666342	KU	4	40 BRN	SP	CRE	ID,IP	TD		8/3/2052
2020 PO4693199421	KU	6	30 BRN	SP	CRE	ID	TD		8/4/2052
2020 PO4689499376	KU	4	40 BRN	SP	CCA		V		8/5/2052
2020 PO4678799403	KU	6	30 BRN	SP	CRE	ID	TD		8/6/2052
2020 PO4732498707	KU	5	35 BRO	SP	CCA		V		8/7/2052
2020 PO4720798672	KU	5	35 BRO	SP	CRE	ID	TD		8/8/2052
2020 PO4712399335	KU	4	40 BRN	SP	CRE	ID	TD		8/9/2052
2020 PO4731099158	KU	6	30 BRN	SP	CRE	ID	TD		8/10/2052
2020 PO4702499120	KU	4	40 BRO	SP	CRE	ID	TD		8/11/2052
2020 PO4719898867	KU	6	30 BRO	SP	CRE	ID	TD		8/12/2052
2020 PO4729099359	KU	6	30 BRN	SP	CRE	ED,ID	X	RP1	8/13/2052
2020 PO4701898423	KU	4	45 BRO	SP	CRE	ID	TD		8/14/2052
2020 PO4713498652	KU	6	30 BRO	SP	A	ID	TD		8/15/2052
2020 PO4675398269	KU	6	30 BRO	SP	CRE	ID	TD		8/16/2052
2020 PO4664798148	KU	5	35 BRO	SP	CRE	ID	TD		8/17/2052
2020 PO4653497896	KU	5	35 BRO	SP	CRE	ID	TD		8/18/2052
2020 PO1053755955	KU	6	30 ACW	SP	CRE	ED,EP,HH,ID,IP,RB	BX	RP1	8/19/2052
2020 PO4656997568	KU	4	35 BRO	SP	CRE	ID	TD		8/20/2052
2020 PO4652997459	KU	6	30 BRO	SP	CRE	ID	TD		8/21/2052
2020 PO4973498011	KU	4	40 BRO	SP	CCA		V		8/22/2052
2020 PO4963797903	KU	4	40 BRO	SP	CCA		V		8/23/2052
2020 PO4962397839	KU	6	30 BRO	SP	CRE		V		8/24/2052
2020 PO4964197741	KU	4	40 BRO	SP	CCA		V		8/25/2052
2020 PO4960697675	KU	6	30 BRO	SP	CCA		V		8/26/2052
2020 PO7392879411	KU	4	45 BRN	SP	CRE	ED,ID	BD		8/27/2052
2020 PO7415679414	KU	4	45 BRN	SP	CRE	ED,ID	TD		8/28/2052
2020 PO7397979699	F	4	40 BRN	SP	CRE		V		8/29/2052
2020 PO7401079897	F	4	45 BRN	SP	CRE		V		8/30/2052
2020 PO4981505292B	KU	5	35 BRN	SP	CCA		V		8/31/2052
2020 PO4891505292A	KU	3	45 BRN	SP	CCA		V		9/1/2052
2020 PO4981505292	KU	3	50 BRN	SP	CCA		V		9/2/2052
2020 PO4890304751	KU	4	40 BRN	SP	CCA		V		9/3/2052
2020 PO4922804720	KU	5	30 BRN	SP	CRE		V		9/4/2052
2020 PO4951305207	KU	4	40 BRN	SP	CCA		V		9/5/2052
2020 PO4952905363	KU	4	40 BRN	SP	CCA		V		9/6/2052
2020 PO4949205639	KU	6	30 BRN	SP	CCA		V		9/7/2052
2020 PO4959905445	KU	5	35 BRN	SP	CCA		V		9/8/2052
2020 PO4967905401	KU	4	40 BRN	SP	CCA		V		9/9/2052
2020 PO4951005387	KU	6	30 BRN	SP	CCA		V		9/10/2052
2020 PO5003605717	KU	5	35 KOP	SP	CCA		V		9/11/2052
2020 PO4925605498	F	6	30 XXX	SP	CRE		V		9/12/2052
2020 PO4827504070	KU	4	40 BRN	SP	CCA		V		9/13/2052
2020 PO4839104591	KU	3	45 BRN	SP	CCA		V		9/14/2052
2020 PO4774004913	F	3	45 OTH	SP	CCA		V		9/15/2052
2020 PO4603504087	KU	6	30 XXX	SP	CRE	HH,ID	X	RP1	9/16/2052
2020 PO4722104364	F	5 40E	XXX	SP	CCA		V		9/17/2052
2020 PO4629003188	F	4 40E	BRN	SP	CRE		V		9/18/2052

2020 PO4799799077	KU	6	30 BRN	SP	CCA		V		9/19/2052
2020 PO5389596870	F	5	35 XXX	SP	CRE		V		9/20/2052
2020 PO5397396742	F	5	35 INP	SP	CRE		V		9/21/2052
2020 PO5353296708	F	6	30 BRN	SP	CRE		V		9/22/2052
2020 PO5303697150	KU	4	40 XXX	SP	CRE		V		9/23/2052
2020 PO5308597095	F	5 35E	XXX	SP	CRE		V		9/24/2052
2020 PO5313897045	F	4	40 KOP	SP	CRE		V		9/25/2052
2020 PO5292997037	F	4	40 KOP	SP	CRE		V		9/26/2052
2020 PO5279497287A	KU	6	30 KOP	SP	CCA		V		9/27/2052
2020 PO5316298425	KU	5	35 BRN	SP	CCA		V		9/28/2052
2020 PO5350698267	KU	4	40 KOP	SP	CCA		V		9/29/2052
2020 PO5326998260	KU	4	45 KOP	SP	CCA		V		9/30/2052
2020 PO5281498194	F	4 40E	XXX	SP	CRE		V		10/1/2052
2020 PO5264097747	KU	6	30 KOP	SP	CCA		V		10/2/2052
2020 PO5208297590	F	4	35 OTH	SP	CCA		V		10/3/2052
2020 PO5181497689	F	3	40 OTH	SP	A		V		10/4/2052
2020 PO5152198002	F	4	40 BRN	SP	CRE		V		10/5/2052
2020 PO4912698450	KU	4	40 BRN	SP	CCA		V		10/6/2052
2020 PO4972998279	F	5 35E	XXX	SP	CRE		V		10/7/2052
2020 PO4818998650	KU	6	30 KOP	SP	CCA		V		10/8/2052
2020 PO7891471885	KU	4	45 BRO	SP	CRE	ID		BD	10/9/2052
2020 PO7402680174	KU	6	30 BRN	SP	CRE	ED,ID		BD	10/10/2052
2020 PO7406980233	KU	4	40 BRN	SP	CCA		V		10/11/2052
2020 PO7385280537	KU	4	45 BRN	SP	CRE		V		10/12/2052
2020 PO7856871481	KU	5	35 BRO	SP	CRE	ID,IP		BD	10/13/2052
2020 PO7862071450	KU	4	40 BRO	SP	CRE	ID		BD	10/14/2052
2020 PO7855371062	KU	4	40 BRO	SP	CRE	ID		BD	10/15/2052
2020 PO4728004069	KU	4	40 KOP	SP	CCA		V		10/16/2052
2020 PO4711603970	KU	3	45 BRN	SP	CRE	ED,ID		TD	10/17/2052
2020 PO7820771005	KU	4	40 BRO	SP	CRE	ED,ID		TD	10/18/2052
2020 PO7833671138	KU	4	45 BRO	SP	CRE	ID		BD	10/19/2052
2020 PO7828971177	KU	5	35 BRO	SP	CRE	ID		BD	10/20/2052
2020 PO6739774818	KU	5	35 BRN	SP	CRE	ED,ID		TD	10/21/2052
2020 PO6750175184	KU	4	40 BRN	SP	CCA		V		10/22/2052
2020 PO6739175167	F	4	35 BRN	SP	CCA		V		10/23/2052
2020 PO6812475949	KU	4	40 BRN	SP	CRE	ED,HH,ID	X	PX	10/24/2052
2020 PO6957579277	KU	4	40 BRN	SP	CRE		V		10/25/2052
2020 PO6945879203	KU	6	30 BRN	SP	CRE		V		10/26/2052
2020 PO1138756567	KU	6	30 ACW	SP	CRE	ED,ID		BD	10/27/2052
2020 PO8878860165	KU	4	40 BRO	SP	CRE	ED		T	10/28/2052
2020 PO0416657086	KU	4	40 BRO	SP	P			T	10/29/2052
2020 PO8878659787	KU	4	45 BRO	SP	CCA		V		10/30/2052
2020 PO8867659529	KU	3	50 BRO	SP	CCA		V		10/31/2052
2020 PO0408856902	KU	4	40 BRO	SP	CRE	ED,ID,SRC		TD	11/1/2052
2020 PO0401456720	KU	4	40 BRO	SP	CRE	ED,ID,IP,SRC		TD	11/2/2052
2020 PO0383956542	KU	5	35 BRO	SP	CRE	ED,ID,IP,SRC		TD	11/3/2052
2020 PO1150656789	KU	4	40 ACW	SP	CRE	ED,ID		BD	11/4/2052

2020 PO1158354741	KU	4	40 ACW	SP	CRE	ED,EP,ID	BX	RR	11/5/2052
2020 PO1132055025	KU	4	40 ACW	SP	CRE	ED,ID	TD		11/6/2052
2020 PO1110555263	KU	4	40 ACW	SP	CRE	ED,ID,IP	BD		11/7/2052
2020 PO1063255146	KU	4	40 ACW	SP	CRE	ED,ID	TD		11/8/2052
2020 PO1083655254	KU	4	45 ACW	SP	CRE	ED,ID	TD		11/9/2052
2020 PO0395356579	KU	4	40 BRO	SP	CRE	ED,ID,IP,SRC	TD		11/10/2052
2020 PO0387956400	KU	5	35 BRO	SP	CRE	ED,ID,IP,SRC	TD		11/11/2052
2020 PO7845371336	KU	4	30 BRO	SP	CRE	ID	BD		11/12/2052
2020 PO7830671445	KU	4	40 BRO	SP	CRE	ED,ID	TD		11/13/2052
2020 PO7839871293	KU	4	40 BRO	SP	CCA		V		11/14/2052
2020 PO7833871789	KU	5	35 BRO	SP	CRE		B		11/15/2052
2020 PO7816371684	KU	4	40 BRO	SP	CCA		V		11/16/2052
2020 PO7812471658	KU	5	35 BRO	SP	P	ID	BD		11/17/2052
2020 PO4608002822	KU	4	40 XXX	SP	CRE	ED,ID	TD		11/18/2052
2020 PO4591002437	KU	4	45 XXX	SP	CRE	ED,ID	TD		11/19/2052
2020 PO4585302274	KU	4	45 XXX	SP	CRE	ED,ID	TD		11/20/2052
2020 PO4621202378	KU	3	50 XXX	SP	CCA		V		11/21/2052
2020 PO4604802340	KU	3	50 XXX	SP	CCA		V		11/22/2052
2020 PO4602502388	KU	5	35 XXX	SP	CRE	ED,ID	TD		11/23/2052
2020 PO4582002175	KU	4	45 XXX	SP	CRE	ED,ID	TD		11/24/2052
2020 PO4588002348	KU	3	50 XXX	SP	CRE	ED,ID	TD		11/25/2052
2020 PO4595902577	KU	4	45 XXX	SP	CRE	ED,ID	TD		11/26/2052
2020 PO4602202741	KU	4	45 XXX	SP	CRE	ED,EP,ID	TD		11/27/2052
2020 PO6680474413	KU	4	40 BRN	SP	CRE	ED,ID	BD		11/28/2052
2020 PO7797671537	KU	5	35 BRO	SP	A	ED,ID	TD		11/29/2052
2020 PO7783571634	KU	5	35 BRO	SP	CRE	ED,ID	TD		11/30/2052
2020 PO7793571564	KU	3	45 BRO	SP	CRE	ED,ID	TD		12/1/2052
2020 PO7803171706	KU	6	30 BRO	SP	CRE	ED,ID	TD		12/2/2052
2020 PO7810171813	KU	4	45 BRO	SP	CRE	ID	BD		12/3/2052
2020 PO7807471772	KU	5	35 BRO	SP	CRE		V		12/4/2052
2020 PO7823972021	KU	4	40 BRO	SP	CRE	ED,ID	TD		12/5/2052
2020 PO7850172083	KU	5	35 BRO	SP	CRE	ED,ID	TD		12/6/2052
2020 PO7835272189	KU	4	40 BRO	SP	CRE		V		12/7/2052
2020 PO6553273435	KU	5	35 BRN	SP	CRE		V		12/8/2052
2020 PO6577973685	KU	5	35 BRN	SP	CRE	ED,ID	BD		12/9/2052
2020 PO6508971137	KU	6	30 BRN	SP	CCA		V		12/10/2052
2020 PO6522571099	KU	5	35 BRN	SP	CRE	ED,ID	BD		12/11/2052
2020 PO6533671243	KU	4	45 BRN	SP	CCA		V		12/12/2052
2020 PO6553870681	KU	4	40 BRN	SP	CCA		V		12/13/2052
2020 PO6587270674	KU	5	35 BRN	SP	CRE	ED,ID	TD		12/14/2052
2020 PO6616270669	KU	4	40 BRN	SP	CCA		V		12/15/2052
2020 PO7011188082	KU	2	55 BRN	SP	CRE	ED,ID	BD		12/16/2052
2020 PO7570094235	KU	4	45 BRO	SP	CRE	ID	BD		12/17/2052
2020 PO7570094235A	KU	4	40 BRO	SP	CCA		V		12/18/2052
2020 PO7572894503	KU	4	40 BRO	SP	CRE	ED,ID	TD		12/19/2052
2020 PO7032688321	KU	3	45 BRN	SP	CRE	ED,ID	BD		12/20/2052
2020 PO7039888418	KU	3	45 BRN	SP	CRE	ED,ID	BD		12/21/2052

2020 PO7017488171	KU	2	60 BRN	SP	CRE	ED,ID	BD	12/22/2052
2020 PO7040888258	KU	5	35 BRN	SP	CRE	ED,ID	BD	12/23/2052
2020 PO7585494594	KU	4	40 BRO	SP	CRE	ID	BD	12/24/2052
2020 PO7589394624	KU	4	40 BRO	SP	CRE		V	12/25/2052
2020 PO7026588245	KU	3	50 BRN	SP	CRE	ED,ID	TD	12/26/2052
2020 PO7576695202A	KU	3	50 BRO	SP	CCA		V	12/27/2052
2020 PO7585095264	KU	5	35 BRO	SP	CRE		V	12/28/2052
2020 PO7595094668	KU	4	45 BRO	SP	CCA		V	12/29/2052
2020 PO7605694745	KU	4	45 BRO	SP	P		B	12/30/2052
2020 PO7617494831	KU	3	50 BRO	SP	CRE	ID	BD	12/31/2052
2020 PO7969272521	KU	4	40 BRO	SP	CRE	ID	BD	1/1/2053
2020 PO8006772488	KU	6	30 BRO	SP	CRE		V	1/2/2053
2020 PO7996672495	KU	4	40 BRO	SP	CCA		V	1/3/2053
2020 PO7953972409	KU	4	45 BRO	SP	CRE	ED,ID	TD	1/4/2053
2020 PO4872405042	KU	5	35 XXX	SP	CRE	ED,ID,IP	TD	1/5/2053
2020 4879804981A	KU	5	30 XXX	SP	CRE	ED,ID	TD	1/6/2053
2020 PO4879804981	KU	6	30 XXX	SP	CRE	ED,ID	TD	1/7/2053
2020 PO4862204865	KU	5	35 XXX	SP	CRE	ED,ID	TD	1/8/2053
2020 PO4868404680	KU	4	40 XXX	SP	CRE	ED,ID	TD	1/9/2053
2020 PO7967372164	KU	4	40 BRO	SP	CRE	ID	BD	1/10/2053
2020 PO7961172277	KU	4	40 BRO	SP	CRE	ED,ID	TD	1/11/2053
2020 PO7929372583	KU	5	35 BRO	SP	CRE	ID	BD	1/12/2053
2020 PO7912472635	KU	4	45 BRO	SP	CRE	ID	BD	1/13/2053
2020 PO7903272697	KU	4	40 BRO	SP	CRE	ID	BD	1/14/2053
2020 PO7921472470	KU	4	40 BRO	SP	CRE	ED,ID	TD	1/15/2053
2020 PO7932372167	KU	5	35 BRO	SP	CCA		V	1/16/2053
2020 PO7931372276	KU	4	40 BRO	SP	CRE	ED,ID	TD	1/17/2053
2020 PO7222978278	KU	4	40 BRN	SP	CRE	ED,ID	BD	1/18/2053
2020 PO7244578149	KU	4	45 BRN	SP	CCA		V	1/19/2053
2020 PO7006282240	KU	1	75 BRN	SP	CRE		V	1/20/2053
2020 PO6984982314	KU	1	75 BRN	SP	CCA		V	1/21/2053
2020 PO4601002230	KU	4	40 XXX	SP	CCA		V	1/22/2053
2020 PO7915072198	KU	4	40 BRO	SP	CRE	ID	BD	1/23/2053
2020 PO9428894786	KU	4	40 BRO	SP	CRE	ED,ID,IP,RB	BX	1/24/2053
2020 PO9456194878	KU	4	40 BRO	SP	CRE	ED,ID	TD	1/25/2053
2020 PO9399494688	KU	4	40 BRO	SP	CRE	ED,ID	BD	1/26/2053
2020 PO9471095107	KU	4	40 BRO	SP	CRE	ID	BD	1/27/2053
2020 PO9505094706	KU	4	40 BRO	SP	CRE	ID	BD	1/28/2053
2020 PO9486394881	KU	4	45 BRO	SP	CRE		B	1/29/2053
2020 PO9520594535	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD	1/30/2053
2020 PO9528095376	KU	4	35 BRO	SP	CCA		V	1/31/2053
2020 PO9537694357	KU	4	40 BRO	SP	CRE	ED,ID	TD	2/1/2053
2020 PO9298195448	KU	4	40 BRO	SP	CRE	ID	BD	2/2/2053
2020 PO9529695259	KU	4	40 BRO	SP	CRE		V	2/3/2053
2020 PO9404095516	KU	4	40 BRO	SP	CRE	ED,ID	BD	2/4/2053
2020 PO9371295392	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	2/5/2053
2020 PO9372095477	KU	6	30 BRO	SP	CRE	ED,ID	TD	2/6/2053

2020 PO9299994857	KU	4	40 BRO	SP	CRE	ID	BD	2/7/2053
2020 PO9283894966	KU	4	40 BRO	SP	CRE	ID	BD	2/8/2053
2020 PO1997292975	KU	4	45 BRO	SP	CCA		V	2/9/2053
2020 PO7035087353	KU	4	45 BRN	SP	CRE	ED,ID	TD	2/10/2053
2020 PO7058287316	KU	4	40 BRN	SP	CCA		V	2/11/2053
2020 PO7075387299	KU	3	45 BRN	SP	CCA		V	2/12/2053
2020 PO7093087259	KU	4	40 BRN	SP	CRE	ED,ID	BD	2/13/2053
2020 PO7091987296	KU	4	45 BRN	SP	CCA		V	2/14/2053
2020 PO7360995075	KU	6	30 BRO	SP	CRE	ED,ID	TD	2/15/2053
2020 PO7394595158	KU	6	30 BRO	SP	P	ED,ID	TD	2/16/2053
2020 PO7437095260	KU	6	30 BRO	SP	CCA		V	2/17/2053
2020 PO7606379545	KU	4	40 BRN	SP	CRE	ED,ID	TD	2/18/2053
2020 PO7611479268	KU	3	50 BRN	SP	CRE	ED,ID	TD	2/19/2053
2020 PO5028997705	KU	6	30 BRN	SP	CRE	ID	TD	2/20/2053
2020 PO5033397593	KU	5	35 BRN	SP	CRE	ID	TD	2/21/2053
2020 PO5013197772	KU	4	40 BRN	SP	CRE	ID	TD	2/22/2053
2020 PO5234006335	KU	4	40 XXX	SP	CRE	ED,ID	TD	2/23/2053
2020 PO7547579581	KU	4	40 BRN	SP	CRE	ED,ID	TD	2/24/2053
2020 PO7537979350	KU	2	60 BRN	SP	CRE		V	2/25/2053
2020 PO7517679460	KU	2	60 BRN	SP	CRE		V	2/26/2053
2020 PO7267080766	KU	1	80 BRN	SP	CRE		V	2/27/2053
2020 PO7297680631	KU	4	40 BRN	AL	CRE		V	2/28/2053
2020 PO7296880612	KU	4	40 BRN	AL	CRE		V	3/1/2053
2020 PO7329680468	KU	2	60 BRN	SP	CRE		V	3/2/2053
2020 PO7352180359	KU	2	70 BRN	SP	CRE		V	3/3/2053
2020 PO7379980221	KU	2	55 BRN	SP	CCA		V	3/4/2053
2020 PO7491179612	KU	2	65 BRN	SP	CRE		V	3/5/2053
2020 PO7465079759	KU	1	75 BRN	SP	CCA		V	3/6/2053
2020 PO7438679911	KU	2	70 BRN	SP	CRE		V	3/7/2053
2020 PO7405080097	KU	2	70 BRN	SP	A		V	3/8/2053
2020 PO5266506121	KU	6	30 KOP	SP	CCA		V	3/9/2053
2020 PO5700406891	F	5	35 BRO	SP	CRE		V	3/10/2053
2020 PO5277106118	KU	5	30 KOP	SP	CRE	ED,ID	TD	3/11/2053
2020 PO4987497952	KU	4	40 BRN	SP	CRE	ID	TD	3/12/2053
2020 PO4979998311	KU	6	30 BRN	SP	CRE	ID	TD	3/13/2053
2020 PO4963298116	KU	6	30 BRN	SP	CRE	ID	TD	3/14/2053
2020 PO4966798071	KU	4	45 BRN	SP	CRE	ID	TD	3/15/2053
2020 PO4930998134	KU	5	35 BRN	SP	CRE	ID	TD	3/16/2053
2020 PO4897998220	KU	5	35 BRN	SP	CRE	ID	TD	3/17/2053
2020 PO4907698250	KU	6	30 BRN	SP	CRE	ID	TD	3/18/2053
2020 PO4804198704	KU	4	40 BRN	SP	CRE	ID	TD	3/19/2053
2020 PO4801598804	KU	6	30 BRN	SP	CRE	ID	TD	3/20/2053
2020 PO4788498961	KU	4	40 BRN	SP	CRE	ID	TD	3/21/2053
2020 PO4777899126	KU	4	40 BRN	SP	CRE	ID	TD	3/22/2053
2020 PO4883198299	KU	4	40 BRN	SP	CRE	ID	TD	3/23/2053
2020 PO4873498232	KU	4	40 BRN	SP	CRE	ID	TD	3/24/2053
2020 PO4869598113	KU	6	30 BRN	SP	CRE	ID	TD	3/25/2053

2020 PO4887598206	KU	4	40 BRN	SP	CRE	ID	TD		3/26/2053
2020 PO4885297998	KU	6	30 BRN	SP	CRE	ID	TD		3/27/2053
2020 PO5704806781	KU	3	50 BRO	SP	CCA		V		3/28/2053
2020 PO5658306934	KU	4	40 BRO	SP	CCA		V		3/29/2053
2020 PO5646706909	F	5	35 BRO	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX	3/30/2053
2020 PO5625206741	KU	3	45 BRO	SP	CCA		V		3/31/2053
2020 PO5617606753	KU	6	30 BRO	SP	CCA		V		4/1/2053
2020 PO7364494472	KU	4	40 BRO	SP	CRE	ED,ID	TD		4/2/2053
2020 PO7378894527A	KU	4	40 BRO	SP	CRE	ED,ID	TD		4/3/2053
2020 PO7378894527	KU	3	45 BRO	SP	CRE	ED,ID	TD		4/4/2053
2020 PO5616206831	F	5	35 BRO	SP	CRE		V		4/5/2053
2020 PO5580106746	F	5	35 BRO	SP	CRE		V		4/6/2053
2020 PO5300406857	KU	4	40 XXX	SP	CRE	ED,ID	TD		4/7/2053
2020 PO5298406909	KU	6	30 XXX	SP	CRE	RB	X	RP1	4/8/2053
2020 PO5287206808	KU	4	40 XXX	SP	CRE	ED,ID	TD		4/9/2053
2020 PO5285106860	F	6	35 XXX	SP	CRE		V		4/10/2053
2020 PO559906951A	KU	6	30 BRO	SP	CCA		V		4/11/2053
2020 PO5581806901	F	4	40 XXX	SP	CRE		V		4/12/2053
2020 PO4876797830	KU	4	40 BRN	SP	CRE	ID	TD		4/13/2053
2020 PO3975182885	LGE	3	45 BRN	SP	S		V		4/14/2053
2020 PO3129232997	KU	4	40 BRN	SP	CRE	ED,ID,MD	TD		4/15/2053
2020 PO3975382873	F	3	45 BRN	SP	CCA		V		4/16/2053
2020 PO3932883228	F	4	40 BRO	SP	P		V		4/17/2053
2020 PO3932483229	F	4	30 BRO	SP	P		V		4/18/2053
2020 PO3977082862	LGE	6	25 BRN	SP	CRE		VX	RP3	4/19/2053
2020 PO3976882871	LGE	3	45 BRN	SP	CCA		V		4/20/2053
2020 PO3978682864	F	6	25 BRN	SP	CRE		V		4/21/2053
2020 PO3978482873	F	4	40 BRN	SP	CRE		V		4/22/2053
2020 PO3932883242	F	4	40 BRO	SP	A		V		4/23/2053
2020 PO3932583243	F	4	30 BRO	SP	P		V		4/24/2053
2020 PO3933883258	F	5	25 BRO	SP	P		V		4/25/2053
2020 PO3932983258	F	4	40 BRO	SP	P		V		4/26/2053
2020 PO3933083274	F	4	40 BRO	SP	P		V		4/27/2053
2020 PO6345404049	F	4	40 XXX	SP	CRE		V		4/28/2053
2020 PO6353904018	KU	3	40 XXX	SP	CCA		V		4/29/2053
2020 PO8052526810	KU	3	55 KOP	SP	CCA		V		4/30/2053
2020 PO8081426888	KU	1	55 BRN	SP	CCA		V		5/1/2053
2020 PO7959326557	KU	1	55 BRN	SP	CCA		V		5/2/2053
2020 PO7912726226	KU	3	50 BRN	SP	CCA		V		5/3/2053
2020 PO8122026997	KU	1	50 KOP	SP	CCA		V		5/4/2053
2020 PO7896126105	KU	3	50 BRN	SP	CCA		V		5/5/2053
2020 PO7913126219	KU	4	40 BRN	SP	CRE		V		5/6/2053
2020 PO7993126649	KU	2	50 BRN	SP	CCA		V		5/7/2053
2020 PO8026926740	KU	2	50 BRN	SP	CCA		V		5/8/2053
2020 PO3978382890	F	4	40 BRN	SP	CCA		V		5/9/2053
2020 PO3979182891	LGE	6	25 BRN	SP	CRE	ED,HH,ID,IP	BX	RR	5/10/2053
2020 PO3978282906	F	4	40 BRN	SP	CRE		V		5/11/2053

2020 PO3978082923	F	4	40 BRN	SP	CRE	ED	VX	RP2	5/12/2053
2020 PO1173534053	ODP	2	55 XXX	SP	CRE	ID	BD		5/13/2053
2020 PO1149934098	ODP	2	55 XXX	SP	CRE	ED,ID	TD		5/14/2053
2020 PO7438203497	KU	4	40 XXX	SP	CRE		V		5/15/2053
2020 PO7546303843	KU	5	35 XXX	SP	CRE		V		5/16/2053
2020 PO1160034079	ODP	6	35 XXX	SP	CRE	ED,ID	TD		5/17/2053
2020 PO1192534024	ODP	2	55 XXX	SP	CRE	ED,ID,IP	TD		5/18/2053
2020 PO3931683269	F	5	25 BRO	SP	CCA		V		5/19/2053
2020 PO3931583261	F	4	40 BRO	SP	P		V		5/20/2053
2020 PO3929983261	F	4	40 BRO	SP	A		V		5/21/2053
2020 PO3928483262	F	4	40 BRO	SP	P		V		5/22/2053
2020 PO3926883263	F	5	40 BRO	SP	A		V		5/23/2053
2020 PO3925283264	F	4	40 BRO	SP	P		V		5/24/2053
2020 PO3929282498	LGE	3	50 BRN	SP	CCA		V		5/25/2053
2020 PO3929582512	LGE	3	45 BRN	SP	CCA		V		5/26/2053
2020 PO3930282520	LGE	3	45 BRN	SP	CRE	ED,ID	BD		5/27/2053
2020 PO3930682531	LGE	3	45 BRN	SP	CRE	ED,ID	TD		5/28/2053
2020 PO3154532714	KU	4	40 BRN	SP	CRE	ED,ID,MD	TD		5/29/2053
2020 PO2069937864	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		5/30/2053
2020 PO2058038132	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD		5/31/2053
2020 PO2080237974	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		6/1/2053
2020 PO7450503517	KU	4	40 XXX	SP	CRE		V		6/2/2053
2020 PO7450903641	KU	6	30 XXX	SP	CCA		V		6/3/2053
2020 PO7450703598	KU	4	40 XXX	SP	CCA		V		6/4/2053
2020 PO7464003544	KU	4	40 XXX	SP	CRE		V		6/5/2053
2020 PO7490003739	KU	6	30 XXX	SP	CCA		V		6/6/2053
2020 PO7507503641	KU	3	45 XXX	SP	CCA		V		6/7/2053
2020 PO7489203600	KU	4	45 XXX	SP	CRE	RB	X	RP1	6/8/2053
2020 PO7524303580	KU	4	40 XXX	SP	CRE	ED,ID	TD		6/9/2053
2020 PO7574003428	KU	5	35 XXX	SP	CRE	ED,ID	TD		6/10/2053
2020 PO7553303495	KU	4	40 XXX	SP	CRE		V		6/11/2053
2020 PO7538103542	KU	4	45 XXX	SP	CRE	ED,ID	TD		6/12/2053
2020 PO7546103407	KU	6	30 XXX	SP	CCA		V		6/13/2053
2020 PO7534403433	KU	4	40 XXX	SP	CRE	ED,ID	TD		6/14/2053
2020 PO7544703740	KU	4	40 XXX	SP	CCA		V		6/15/2053
2020 PO7532103655	KU	6	30 XXX	SP	CCA		V		6/16/2053
2020 PO7528403528	KU	6	30 XXX	SP	CCA		V		6/17/2053
2020 PO7530903305	KU	4	40 XXX	SP	CRE	ED,ID	TD		6/18/2053
2020 PO7543203247	KU	4	40 XXX	SP	CRE	ED,ID	TD		6/19/2053
2020 PO7550203245	KU	5	35 XXX	SP	CRE	ED,ID	TD		6/20/2053
2020 PO7569303194	KU	5	35 XXX	SP	CRE	ID	BD		6/21/2053
2020 PO7604403140	KU	6	30 XXX	SP	CRE	ED,ID	TD		6/22/2053
2020 PO7615803458	KU	5	35 XXX	SP	CRE	ED,ID	TD		6/23/2053
2020 PO7636903337	KU	6	30 XXX	SP	CRE	ED,ID	TD		6/24/2053
2020 PO7641903474	KU	5	35 XXX	SP	CRE	ED,ID	TD		6/25/2053
2020 PO7651403525	KU	5	35 XXX	SP	CRE	ED,ID	TD		6/26/2053
2020 PO7663803576	KU	5	35 XXX	SP	CRE	ED,ID	TD		6/27/2053

2020 PO7695803415	KU	3	45 XXX	SP	CRE	ED,ID	TD	6/28/2053
2020 PO7696303438	KU	4	40 XXX	SP	CRE	ED,ID	TD	6/29/2053
2020 PO7759703433	KU	4	40 XXX	SP	CRE	ED,ID	TD	6/30/2053
2020 PO7783403380	KU	5	35 XXX	SP	CRE	ED,ID	TD	7/1/2053
2020 PO7760603472	KU	4	45 XXX	SP	CRE	ED,ID	TD	7/2/2053
2020 PO4043443397	F	4	40 ACE	SP	CRE		V	7/3/2053
2020 PO4073743069	KU	6	30 ACE	SP	CRE	ED,ID	TD	7/4/2053
2020 PO4080343028	KU	4	45 ACE	SP	CCA		V	7/5/2053
2020 PO3177532457	KU	4	40 BRN	SP	CRE	ED,ID,MD	TD	7/6/2053
2020 PO3201032191	KU	4	40 BRN	SP	CRE	ID	BD	7/7/2053
2020 PO3212931960	KU	4	40 BRN	SP	CRE	ED,ID	TD	7/8/2053
2020 PO3223331743	KU	4	40 BRN	SP	CRE	ID	BD	7/9/2053
2020 PO2069738168	KU	4	40 BRO	SP	CRE	ID,IP	BD	7/10/2053
2020 PO3977882939	F	1	50 BRN	SP	S		V	7/11/2053
2020 PO3932482620	LGE	4	45 BRN	SP	CRE	ED,ID	BD	7/12/2053
2020 PO8189826717	KU	4	45 BRN	SP	CCA		V	7/13/2053
2020 PO8202026721	KU	4	40 BRN	SP	CCA		V	7/14/2053
2020 PO8205026516	KU	4	40 UNK	SP	CRE	ED,ID,IP	TX	RR 7/15/2053
2020 PO8177826789	KU	4	45 BRN	SP	CCA		V	7/16/2053
2020 PO8188926674	KU	5	35 BRN	SP	CRE	ID	TD	7/17/2053
2020 PO8206626493	KU	5	35 UNK	SP	CRE	ED,ID,SRS	TD	7/18/2053
2020 PO3931682550	LGE	3	45 BRN	SP	CCA		V	7/19/2053
2020 PO3929982569	LGE	4	40 BRN	SP	P	ED,ID	BD	7/20/2053
2020 PO3930982563	LGE	4	40 BRN	SP	P	ED,ID	BD	7/21/2053
2020 PO3932082559	LGE	4	40 BRN	SP	CRE	ED,ID	TD	7/22/2053
2020 PO3932682574	LGE	4	40 BRN	SP	CRE	ED,ID	BD	7/23/2053
2020 PO3933182585	LGE	3	45 BRN	SP	CCA		V	7/24/2053
2020 PO3932982579	LGE	4	40 BRN	SP	CCA		V	7/25/2053
2020 PO3923583265	F	3	45 BRO	SP	CCA		V	7/26/2053
2020 PO3922083274	F	5	25 BRO	SP	CCA		V	7/27/2053
2020 PO4050243323	F	3	45 ACE	SP	P		V	7/28/2053
2020 PO3921983266	F	4	40 BRO	SP	P		V	7/29/2053
2020 PO3920683267	F	4	40 BRO	SP	A		V	7/30/2053
2020 PO3919983267	F	4	40 BRO	SP	A		V	7/31/2053
2020 PO3919483308	F	5	25 BRO	SP	P		V	8/1/2053
2020 PO3919483295	F	4	40 BRO	SP	CCA		V	8/2/2053
2020 PO4212441349	F	2	50 ACE	SP	CRE		V	8/3/2053
2020 PO3977682956	F	3	45 BRN	SP	S		V	8/4/2053
2020 PO3977282953	F	4	30 BRN	SP	A		V	8/5/2053
2020 PO4219541283	F	1	50 ACE	SP	P		V	8/6/2053
2020 PO2369123366	ODP	6	30 XXX	SP	CCA	ED	T	8/7/2053
2020 PO2399623119	ODP	4	40 XXX	SP	CRE	ID	TD	8/8/2053
2020 PO2412922933	ODP	4	40 XXX	SP	CRE	ID	TD	8/9/2053
2020 PO2427922723	ODP	4	40 XXX	SP	CRE	ID	TD	8/10/2053
2020 PO2465422272	F	4	45 XXX	SP	CRE		V	8/11/2053
2020 PO2479622325	F	4	45 XXX	SP	CRE		V	8/12/2053
2020 PO2440022507	ODP	4	40 XXX	SP	CRE	ID	TD	8/13/2053

2020 PO6049212885	KU	2	50 BRO	ST	CRE		V		8/14/2053
2020 PO5593009291	KU	4	40 BRO	SP	CRE	ID	BD		8/15/2053
2020 PO7355789328	F	4	40 BRO	SP	CRE		V		8/16/2053
2020 PO7395489406	KU	4	35 BRO	SP	CRE	ED,HH,ID,MD,RB	X	RP1	8/17/2053
2020 PO7416189236	KU	6	30 BRO	SP	CRE	ED,ID	BD		8/18/2053
2020 PO7411889136	KU	5	35 BRO	SP	CRE	ED,ID	BD		8/19/2053
2020 PO7438189227	KU	5	35 BRO	SP	CRE	ED,ID,IP,MD	BD		8/20/2053
2020 PO7419889310	KU	5	35 BRO	SP	CRE	ED,HH,ID,IP,MD	BD		8/21/2053
2020 PO7369889280	LGE	3	35 BRO	SP	CCA		V		8/22/2053
2020 PO7392291949	KU	1	75 BRO	SP	CRE		V		8/23/2053
2020 PO5581809229	KU	5	35 BRO	SP	CRE	ID	TD		8/24/2053
2020 PO5575609328	KU	5	35 BRO	SP	CRE	ID	TD		8/25/2053
2020 PO5614409363	KU	4	40 BRO	SP	CRE		V		8/26/2053
2020 PO5589709191	KU	4	40 BRO	SP	CCA		V		8/27/2053
2020 PO5596009109	KU	4	40 BRO	SP	CCA	ID	TD		8/28/2053
2020 PO5586009067	KU	4	40 BRO	SP	CCA		V		8/29/2053
2020 PO5580408951	KU	4	40 BRO	SP	CCA		V		8/30/2053
2020 PO5559008081	KU	4	40 BRO	SP	CCA		V		8/31/2053
2020 PO5594608666	KU	4	40 BRO	SP	CCA		V		9/1/2053
2020 PO5613108270	KU	3	45 BRO	SP	CCA		V		9/2/2053
2020 PO5583908248	KU	3	45 BRO	SP	CCA		V		9/3/2053
2020 PO6179312456	KU	3	45 BRO	SP	CCA		V		9/4/2053
2020 PO6180212508	KU	4	40 BRO	SP	CCA		V		9/5/2053
2020 PO6191812471	KU	4	40 BRO	SP	CCA		V		9/6/2053
2020 PO6236512665a	KU	5	35 BRO	SP	CCA		V		9/7/2053
2020 PO6257412705	KU	4	40 BRO	SP	CCA		V		9/8/2053
2020 PO6203712491	KU	4	40 BRO	SP	CCA		V		9/9/2053
2020 PO6236512665	KU	4	40 BRO	SP	CCA		V		9/10/2053
2020 PO6270912736	KU	5	35 BRO	SP	CCA		V		9/11/2053
2020 PO6123112485	KU	4	40 BRO	SP	CRE	ID	TD		9/12/2053
2020 PO6095112568	KU	4	40 BRO	SP	CRE	ID	TD		9/13/2053
2020 PO6066512655	KU	2	50 BRO	SP	CCA		V		9/14/2053
2020 PO4845631792	KU	5	35 BRO	SP	CRE	ID	BD		9/15/2053
2020 PO4851331822	F	4	40 BRO	SP	CRE		V		9/16/2053
2020 PO4543701479	KU	4	40 BRN	SP	CRE	ID,RB	X	RP1	9/17/2053
2020 PO4758988650	LGE	4	40 BRN	SP	CRE	ED,HH,ID	BX	PX	9/18/2053
2020 PO4760588656	LGE	4	40 BRN	SP	S		V		9/19/2053
2020 PO4697599412	LGE	4	40 BRN	SP	S		V		9/20/2053
2020 PO4841911231	KU	4	40 BRO	SP	CRE	ED,ID	TD		9/21/2053
2020 PO4772012036	KU	3	50 BRO	SP	CRE	ED,ID,IP	TD		9/22/2053
2020 PO4536801356	KU	4	40 BRN	SP	CRE	ED,ID	TD		9/23/2053
2020 PO4758088647	LGE	4	40 BRN	SP	CRE	ED,ID	BD		9/24/2053
2020 PO4757788665	LGE	4	40 BRN	SP	CRE		V		9/25/2053
2020 PO4757088662	LGE	3	45 BRN	SP	S		V		9/26/2053
2020 PO4530601246	KU	4	40 BRN	SP	CRE	ED,ID	TD		9/27/2053
2020 PO4529101174	KU	5	35 BRN	SP	CRE	ED,ID	TD		9/28/2053
2020 PO4756588670	LGE	4	40 BRN	SP	A	ED,ID,RB	X	PX	9/29/2053

2020 PO4846611039	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD		9/30/2053
2020 PO4755188684	LGE	4	35 BRN	SP	CRE	ED,ID	BD		10/1/2053
2020 PO4854411268	KU	3	50 ACE	SP	P	ED	T		10/2/2053
2020 PO4844911305	KU	4	45 ACE	SP	CCA		V		10/3/2053
2020 PO9918416948	KU	5	30 BRO	SP	CRE		V		10/4/2053
2020 PO4577800822	KU	4	40 XXX	SP	CRE	ID	BX	RP2	10/5/2053
2020 PO2324242661	KU	5	35 BRO	SP	CRE	ED	TD		10/6/2053
2020 PO9463118109	KU	6	30 SWP	SP	CRE		V		10/7/2053
2020 PO3990482930	F	4	40 BRN	SP	CRE		V		10/8/2053
2020 PO3990782938	F	4	40 BRN	SP	CCA		V		10/9/2053
2020 PO3990582950	F	4	40 BRN	SP	CRE		V		10/10/2053
2020 PO1103735788	ODP	2	55 XXX	SP	CRE	ED,ID,SRC	TX	RR	10/11/2053
2020 PO1104635851	ODP	5	45 XXX	SP	CRE	ED,ID	TD		10/12/2053
2020 PO1101235502	ODP	2	55 XXX	SP	CRE	ED,ID,IP	TX	RR	10/13/2053
2020 PO4107842394	KU	4	35 ACE	SP	CRE	ED,EP,ID,IP	TD		10/14/2053
2020 PO4114742408	F	3	45 ACE	SP	P		V		10/15/2053
2020 PO1279910346	KU	4	45 UNK	SP	CRE	ED,ID	TD		10/16/2053
2020 PO3990482962	F	4	40 BRN	SP	CCA		V		10/17/2053
2020 PO3911282486	F	4	40 BRN	SP	CRE		V		10/18/2053
2020 PO1270610195	KU	6	30 KOP	SP	CRE		V		10/19/2053
2020 PO1282010204	F	3	40 UNK	SP	CRE		V		10/20/2053
2020 PO1284410069	KU	5	35 UNK	SP	CRE	ED,ID	TD		10/21/2053
2020 PO1297510274	KU	4	40 KOP	SP	CRE	ED,ID	TD		10/22/2053
2020 PO4569600674	KU	4	40 XXX	SP	CRE	ID,RB	X	RP1	10/23/2053
2020 PO4562500582	KU	4	40 XXX	SP	CRE	ED,ID	BX	PX	10/24/2053
2020 PO4051682865	LGE	4	40 BRO	SP	P	ED,ID	TD		10/25/2053
2020 PO4049982865	LGE	4	30 BRO	SP	CRE	ED,ID	BD		10/26/2053
2020 PO4047182876	LGE	3	45 BRO	SP	CRE	ED,ID	TD		10/27/2053
2020 PO4048082842	LGE	4	40 BRO	SP	CRE	ED,ID	TD		10/28/2053
2020 PO4047582859	LGE	3	45 BRO	SP	CRE	ED,ID	TD		10/29/2053
2020 PO4050582857	LGE	4	30 BRO	SP	P	ED,ID	TD		10/30/2053
2020 PO4049182867	LGE	4	40 BRO	SP	CRE	ED,ID	TD		10/31/2053
2020 PO4049982860	LGE	4	40 BRO	SP	P	ED,ID	BD		11/1/2053
2020 PO4049482845	LGE	4	30 BRO	SP	P	ED,ID	BD		11/2/2053
2020 PO4049082851	LGE	3	45 BRO	SP	CCA		V		11/3/2053
2020 PO4750488766	LGE	4	40 BRN	SP	CRE	ED,ID	TD		11/4/2053
2020 PO4751288755	LGE	4	40 BRN	SP	CRE	ED,ID	BD		11/5/2053
2020 PO4749888768	LGE	4	30 BRN	SP	S		V		11/6/2053
2020 PO4984413475	KU	5	35 ACE	SP	CRE	ED,ID	TD		11/7/2053
2020 PO1319410193	KU	4	45 BRN	SP	CRE	ED,ID	TD		11/8/2053
2020 PO1306510054	F	3	45 BRN	SP	CRE		V		11/9/2053
2020 PO1341610147	F	3	40 INP	SP	CCA		V		11/10/2053
2020 PO1352610335	KU	5	35 UNK	SP	CRE	ED,ID,SRS	TD		11/11/2053
2020 PO1353210665	KU	5	35 UNK	SP	CRE	ED,ID,SRS	TD		11/12/2053
2020 PO1354110625	KU	5	35 UNK	SP	CRE	ED,ID	TD		11/13/2053
2020 PO1351310952	KU	4	40 KOP	SP	CCA		V		11/14/2053
2020 PO1403110548	KU	4	40 ACW	SP	CRE	ED,ID	TD		11/15/2053

2020 PO1433410397	KU	4	40 ACW	SP	CRE	ED,ID	TD	11/16/2053
2020 PO1462910246	KU	5	35 UNK	SP	CRE	ED,ID	TD	11/17/2053
2020 PO1480310174	KU	5	35 UNK	SP	CRE	ED,ID,SRS	TD	11/18/2053
2020 PO1459210120	KU	6	30 UNK	SP	CRE	ED,ID	TD	11/19/2053
2020 PO1417710346	KU	5	35 KOP	SP	CCA		V	11/20/2053
2020 PO1171533025	ODP	6	30 XXX	SP	CRE		T	11/21/2053
2020 PO3911882500	F	4	40 BRN	SP	CRE		V	11/22/2053
2020 PO5104808552	KU	3	50 ACE	SP	CCA		V	11/23/2053
2020 PO5087908615	KU	3	50 ACE	SP	CCA		V	11/24/2053
2020 PO5071008678	KU	3	50 ACE	SP	CCA		V	11/25/2053
2020 PO5061208521	KU	4	45 ACE	SP	CCA		V	11/26/2053
2020 PO4735389258	F	4	40 BRO	SP	A		V	11/27/2053
2020 PO4734189250	F	4	40 BRO	SP	CRE		V	11/28/2053
2020 PO4732889242	F	4	40 BRO	SP	CRE		V	11/29/2053
2020 PO3992682993	F	4	40 BRN	SP	CRE		V	11/30/2053
2020 PO3991582992	F	4	40 BRN	SP	CRE		V	12/1/2053
2020 PO3915582581	F	3	45 BRN	SP	CCA		V	12/2/2053
2020 PO3916082589	F	4	40 BRN	SP	CRE		V	12/3/2053
2020 PO3916482589	LGE	4	35 BRN	SP	CRE	ED,ID	TD	12/4/2053
2020 PO3990382990	F	4	40 BRN	SP	CRE		V	12/5/2053
2020 PO1293133816	ODP	4	45 BRN	SP	CCA		V	12/6/2053
2020 PO6131505073	KU	2	45 XXX	SP	CRE		V	12/7/2053
2020 PO3989082989	F	4	40 BRN	SP	CRE		V	12/8/2053
2020 PO3987982988	F	4	40 BRN	SP	CRE		V	12/9/2053
2020 PO3986482986	F	4	40 BRN	SP	A		V	12/10/2053
2020 PO4116742242	KU	5	35 ACE	SP	CRE	ED,ID	BD	12/11/2053
2020 PO4122642281	F	2	55 ACE	SP	P		V	12/12/2053
2020 PO9519918356	KU	6	30 ACW	SP	CRE	ID	TD	12/13/2053
2020 PO3916782570	F	7	25 BRN	SP	CRE		V	12/14/2053
2020 PO3986882969	F	3	45 BRN	SP	CCA		V	12/15/2053
2020 PO3954782769	F	4	30 BRO	SP	P		V	12/16/2053
2020 PO3953282776	F	5	30 BRO	SP	P		V	12/17/2053
2020 PO3950382793	F	3	50 BRO	SP	CCA		V	12/18/2053
2020 PO3952082786	F	4	40 BRO	SP	CRE		V	12/19/2053
2020 PO3952882782	F	4	40 BRO	SP	A		V	12/20/2053
2020 PO3953982778	F	4	40 BRO	SP	A		V	12/21/2053
2020 PO3955282772	F	4	40 BRO	SP	P		V	12/22/2053
2020 PO1113534572	ODP	4	45 XXX	SP	CRE	ED,ID	TD	12/23/2053
2020 PO1095134605	ODP	2	60 XXX	SP	CRE	ED,ID,IP	TD	12/24/2053
2020 PO3935883187	LGE	4	30 BRO	SP	A	ED,ID	TD	12/25/2053
2020 PO3935383187	F	4	40 BRO	SP	A		V	12/26/2053
2020 PO3934983171	F	4	40 BRO	SP	A		V	12/27/2053
2020 PO3933983157	F	4	40 BRO	SP	P		V	12/28/2053
2020 PO1260036570	ODP	6	30 KOP	SP	CRE		V	12/29/2053
2020 PO3978383007	LGE	4	30 BRN	SP	CRE	ED,ID	TD	12/30/2053
2020 PO1229836643	F	4	40 KOP	SP	P		V	12/31/2053
2020 PO1241136633	ODP	4	40 BRN	SP	CCA		V	1/1/2054

2020 PO4018042711b	KU	4	40 ACE	SP	CCA		V			1/2/2054
2020 PO1214736462	F	4	40 UNK	SP	CRE		V			1/3/2054
2020 PO1212036393	F	4	40 UNK	SP	CRE		V			1/4/2054
2020 PO4018042711a	KU	4	35 ACE	SP	CRE	ED,ID		TD		1/5/2054
2020 PO4033442968	KU	4	40 ACE	SP	CCA		V			1/6/2054
2020 PO1209136322	F	2	50 UNK	SP	CRE		V			1/7/2054
2020 PO1229036281	ODP	4	40 UNK	SP	CRE	ED		BD		1/8/2054
2020 PO3978482994	LGE	6	30 BRN	SP	CRE	ED,ID		TD		1/9/2054
2020 PO1098034600	ODP	4	40 XXX	SP	CRE	ED,ID		TD		1/10/2054
2020 PO1085234785	ODP	6	30 XXX	SP	CRE		V			1/11/2054
2020 PO1095834745	ODP	4	40 XXX	SP	CCA		V			1/12/2054
2020 PO1096934904	ODP	2	55 XXX	SP	CRE	ED,ID,IP		TD		1/13/2054
2020 PO1098035048	ODP	5	35 XXX	SP	CRE	ED,ID		TD		1/14/2054
2020 PO2239438004	KU	5	35 BRO	SP	CRE	ED,ID,IP		TD		1/15/2054
2020 PO2243238097	KU	4	40 BRO	SP	CRE	HH,ID,RB	X		RP1	1/16/2054
2020 PO2221637976	KU	4	40 BRO	SP	CRE	ID,RB	X		RP1	1/17/2054
2020 PO1254036389	F	4	40 UNK	SP	CRE	ED,ID		V		1/18/2054
2020 PO3925382502	LGE	4	40 BRN	SP	CRE	ED,ID		TD		1/19/2054
2020 PO3922782448	LGE	3	45 BRN	SP	CCA		V			1/20/2054
2020 PO4754688867	LGE	4	40 BRN	SP	A	ED,ID,SRC		TX	RR	1/21/2054
2020 PO3924582487	F	4	40 BRN	SP	CRE		V			1/22/2054
2020 PO3924082476	F	3	45 BRN	SP	CRE		V			1/23/2054
2020 PO3922982462	F	4	30 BRN	SP	P		V			1/24/2054
2020 PO3923382460	LGE	3	45 BRN	SP	CRE	ED,ID		BD		1/25/2054
2020 PO3922782448	LGE	3	45 BRN	SP	CRE	ED,ID		TD		1/26/2054
2020 PO3922282436	F	3	45 BRN	SP	CRE		V			1/27/2054
2020 PO3921582432	F	4	40 BRN	SP	P		V			1/28/2054
2020 PO3921982430	F	4	40 BRN	SP	CRE		V			1/29/2054
2020 PO3921482418	F	4	40 BRN	SP	CRE		V			1/30/2054
2020 PO2518035563	KU	4	40 BRN	SP	CRE	HH,ID,IP,RB		BX	PX	1/31/2054
2020 PO2513535758	KU	4	40 BRN	SP	CRE	ED,ID,IP		TD		2/1/2054
2020 PO2507435974	KU	4	40 BRN	SP	CRE	ED,ID		TD		2/2/2054
2020 PO2501236217	KU	5	35 BRN	SP	CRE	ID,IP		BD		2/3/2054
2020 PO2484236322	KU	4	40 BRN	SP	CRE	ED		T		2/4/2054
2020 PO2432536903	KU	4	40 BRN	SP	CCA		V			2/5/2054
2020 PO2440136740	KU	4	40 BRN	SP	P	ED		T		2/6/2054
2020 PO2447836577	KU	4	40 BRN	SP	P	ED		T		2/7/2054
2020 PO4806611095	KU	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB		BX	PX	2/8/2054
2020 PO4723299250	KU	4	40 BRN	SP	CRE	ID		BD		2/9/2054
2020 PO4714899632	KU	4	40 BRN	SP	CCA		V			2/10/2054
2020 PO4090083051	LGE	3	45 BRO	SP	CCA		V			2/11/2054
2020 PO4695299776	KU	4	45 BRN	SP	CCA		V			2/12/2054
2020 PO4088383058	LGE	3	45 BRO	SP	CCA		V			2/13/2054
2020 PO4088083061	LGE	3	45 BRO	SP	CCA		V			2/14/2054
2020 PO4088283082	LGE	3	45 BRO	SP	CCA		V			2/15/2054
2020 PO4092783048	LGE	3	50 CAH	SP	P	ED		BD		2/16/2054
2020 PO8123442200	LGE	4	45 CAH	SP	CCA	ED,ID		V		2/17/2054

2020 PO4794311146	KU	4	40 ACE	SP	CCA		V		2/18/2054
2020 PO4718900292	KU	4	45 KOP	SP	CRE	ED,ID	TD		2/19/2054
2020 PO4701800023	KU	2	55 BRN	SP	CCA		V		2/20/2054
2020 PO4707199967	KU	2	35 BRN	SP	CRE	ED,ID	TD		2/21/2054
2020 PO8117733120	KU	5	45 OTH	SP	CRE		V		2/22/2054
2020 PO4068383229	LGE	4	30 BRO	SP	P	ED,HH,ID,RB	BX	PX	2/23/2054
2020 PO5530844332	KU	6	35 BRN	SP	CRE	ED,ID,RB	BX	RP2	2/24/2054
2020 PO8124533991	KU	4	40 OTH	SP	CRE		V		2/25/2054
2020 PO8111332789	KU	4	40 OTH	SP	CRE		V		2/26/2054
2020 PO8109532793	KU	4	45 OTH	SP	CRE		V		2/27/2054
2020 PO8127034300	KU	4	40 OTH	SP	CRE		V		2/28/2054
2020 PO8094834676	KU	6	30 OTH	SP	CRE		V		3/1/2054
2020 PO8118333016	KU	4	45 OTH	SP	CRE		V		3/2/2054
2020 PO8118833244	KU	4	40 OTH	SP	CRE		V		3/3/2054
2020 PO8121733678	KU	4	40 OTH	SP	CRE		V		3/4/2054
2020 PO8105734677	KU	3	50 OTH	SP	CRE		V		3/5/2054
2020 PO8116133020	KU	4	45 OTH	SP	CRE		V		3/6/2054
2020 PO8036435535	KU	5	35 OTH	SP	CRE		V		3/7/2054
2020 PO8065634679	KU	5	35 OTH	SP	CRE		V		3/8/2054
2020 PO8129434572	KU	4	40 OTH	SP	CRE		V		3/9/2054
2020 PO8119533367	KU	4	40 OTH	SP	CRE		V		3/10/2054
2020 PO1263636329	F	4	40 UNK	SP	CRE		V		3/11/2054
2020 PO4768011254	KU	4	40 ACE	SP	CRE	ED,EP,ID,IP	TD		3/12/2054
2020 PO3923108994	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD		3/13/2054
2020 PO3923009096	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD		3/14/2054
2020 PO4758688878	LGE	4	40 BRN	SP	CRE	ED,ID	TD		3/15/2054
2020 PO3928909386	KU	4	40 BRO	SP	CRE	ID	BD		3/16/2054
2020 PO4744311352	KU	4	40 ACE	SP	CRE	ED,ID	TD		3/17/2054
2020 PO4755111307	KU	4	40 ACE	SP	CRE	ED,ID	TD		3/18/2054
2020 PO4759188867	LGE	4	40 BRN	SP	CRE	ED,ID	TD		3/19/2054
2020 PO4093583137	LGE	4	40 BRO	SP	A	ED,ID	BD		3/20/2054
2020 PO4090483136	LGE	3	45 BRO	SP	P	ED,ID	TD		3/21/2054
2020 PO4091283136	LGE	3	45 BRO	SP	P	ED,ID	BD		3/22/2054
2020 PO4092283136	LGE	3	45 BRO	SP	A	ED,ID	BD		3/23/2054
2020 PO4759688856	LGE	4	40 BRN	SP	CRE	ED,ID	TD		3/24/2054
2020 PO4729611414	KU	4	40 ACE	SP	CRE	ED,ID	BD		3/25/2054
2020 PO4717811460	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		3/26/2054
2020 PO3954810165	KU	3	45 BRO	SP	CRE	ID	BD		3/27/2054
2020 PO8104132511	KU	4	40 OTH	SP	CRE		V		3/28/2054
2020 PO8104230592	KU	4	40 OTH	SP	CRE		V		3/29/2054
2020 PO8105630184	KU	4	40 KOP	SP	CCA		V		3/30/2054
2020 PO8099731806	KU	4	40 OTH	SP	CRE		V		3/31/2054
2020 PO8097932270	KU	4	40 OTH	SP	CRE		V		4/1/2054
2020 PO8107329298	KU	4	40 BRN	SP	CCA		V		4/2/2054
2020 PO1269235971	F	4	40 BRN	SP	CRE		V		4/3/2054
2020 PO3880682914	LGE	4	40 BRO	SP	P	ED	TD		4/4/2054
2020 PO1256435937	ODP	6	30 BRN	SP	CRE		V		4/5/2054

2020 PO3878182967	LGE	4	35 BRO	SP	P	ED,IP	TD		4/6/2054
2020 PO4057742889	KU	6	30 ACE	SP	CCA		V		4/7/2054
2020 PO4074342913	F	3	45 ACE	SP	P		V		4/8/2054
2020 PO3879882957	LGE	4	40 BRO	SP	CCA		V		4/9/2054
2020 PV3878582985	LGE	4	30 BRO	SP	P	ED,ID,IP	TD		4/10/2054
2020 PO3878382995	LGE	4	35 BRO	SP	P	ED,ID	BD		4/11/2054
2020 PO3981283010	LGE	4	40 BRN	SP	CRE	ED,ID	TD		4/12/2054
2020 PO1231334580	ODP	4	40 BRN	SP	CRE	ID,SRS	TD		4/13/2054
2020 PO1231034719	ODP	6	30 BRN	SP	CRE		V		4/14/2054
2020 PO2226837785	KU	5	35 BRO	SP	CRE	HH,ID,RB	X	RP1	4/15/2054
2020 PO2234837888	KU	4	40 BRO	SP	CCA		V		4/16/2054
2020 PO1228934428	ODP	4	45 KOP	SP	CRE	ID	BD		4/17/2054
2020 PO3879082976	LGE	4	35 BRO	SP	CCA		V		4/18/2054
2020 PO3877682973	LGE	4	35 BRO	SP	P	ED	TD		4/19/2054
2020 PO3876882969	LGE	4	40 BRO	SP	CCA		V		4/20/2054
2020 PO3871583012	LGE	4	35 BRO	SP	P	ED	TD		4/21/2054
2020 PO3874683009	LGE	4	35 BRO	SP	P	ED,ID	TD		4/22/2054
2020 PO1230034482	ODP	6	30 BRN	SP	CCA		V		4/23/2054
2020 PO3982783002	LGE	4	35 BRN	SP	S		V		4/24/2054
2020 PO3982583011	LGE	3	45 BRN	SP	CCA		V		4/25/2054
2020 PO3983983013	LGE	4	40 BRN	SP	CRE	ED,ID	TD		4/26/2054
2020 PO1196134482	ODP	4	40 BRN	SP	CRE	ID	TD		4/27/2054
2020 PO3920082350	LGE	4	30 BRN	SP	CRE		V		4/28/2054
2020 PO3920382353	LGE	4	40 BRN	SP	CRE	ED,ID	TD		4/29/2054
2020 PO3919182358	LGE	4	40 BRN	SP	CRE	ED,ID	BD		4/30/2054
2020 PO3933583142	LGE	5	30 BRO	SP	P	ED,ID	TD		5/1/2054
2020 PO3917582366	LGE	4	40 BRN	SP	CCA		V		5/2/2054
2020 PO3915982373	LGE	4	40 BRN	SP	CCA		V		5/3/2054
2020 PO3933083143	F	4	40 BRO	SP	P		V		5/4/2054
2020 PO3932283130	F	4	40 BRO	SP	P		V		5/5/2054
2020 PO3985483015	LGE	4	40 BRN	SP	CCA		V		5/6/2054
2020 PO3986783017	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD		5/7/2054
2020 PO1203334625	ODP	3	45 BRN	SP	CCA		V		5/8/2054
2020 PO3915282364	LGE	4	35 BRN	SP	P	ED,ID	TD		5/9/2054
2020 PO3917482362	LGE	4	30 BRN	SP	CCA	ED,HH,ID,RB	X	PX	5/10/2054
2020 PO1183534643	ODP	4	40 BRN	SP	CRE	ID	TD		5/11/2054
2020 PO1176634677	ODP	4	45 BRN	SP	CCA		V		5/12/2054
2020 PO4082942940	KU	6	30 ACE	SP	CRE	ED,ID	TD		5/13/2054
2020 PO1059533545	ODP	4	40 BRN	SP	CRE	ED,ID,RB,SRC	TX	RR	5/14/2054
2020 PO3931483118	F	4	40 BRO	SP	A		V		5/15/2054
2020 PO3876283008	LGE	4	35 BRO	SP	P	ED	TD		5/16/2054
2020 PV3930583105	F	4	40 BRO	SP	A		V		5/17/2054
2020 PO3929883093	F	4	40 BRO	SP	CRE		V		5/18/2054
2020 PO3928583078	F	3	45 BRO	SP	CCA		V		5/19/2054
2020 PO3926983085	F	4	40 BRO	SP	P		V		5/20/2054
2020 PO4087442915	KU	6	30 ACE	SP	CRE	ED,ID	TD		5/21/2054
2020 PO3987983019	LGE	4	40 BRN	SP	CRE	ED,ID	TD		5/22/2054

2020 PO2473136039	KU	4	40 BRN	SP	CRE		T			5/23/2054
2020 PO2451736104	KU	4	40 BRN	SP	CRE		V			5/24/2054
2020 PO2420336192	KU	4	40 BRN	SP	CCA		V			5/25/2054
2020 PO2438936310	KU	4	40 BRN	SP	CCA		V			5/26/2054
2020 PO2439536346	KU	4	40 BRN	SP	CRE		V			5/27/2054
2020 PO2455436414	KU	4	40 BRN	SP	CRE	ED	T			5/28/2054
2020 PO3873083011	LGE	4	35 BRO	SP	P	ED	TD			5/29/2054
2020 PO3877683007	LGE	4	35 BRO	SP	P	ED,IP	TD			5/30/2054
2020 PO3925783091	F	4	40 BRO	SP	P		V			5/31/2054
2020 PO3925483088	F	5	25 BRO	SP	P		V			6/1/2054
2020 PO3924983090	LGE	4	30 BRO	SP	P	ED,ID	TD			6/2/2054
2020 PO3923082388	LGE	4	40 BRN	SP	CRE	ED,ID,RB	TX		RR	6/3/2054
2020 PO4082442762	KU	3	45 ACE	SP	CRE	ED,ID,IP	TD			6/4/2054
2020 PO4088242831	F	3	45 ACE	SP	P		V			6/5/2054
2020 PO2296342773	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			6/6/2054
2020 PO2268642889	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD			6/7/2054
2020 PO2261542920	KU	4	40 BRO	SP	CRE	ID	BD			6/8/2054
2020 PO2235042848	KU	4	40 BRO	SP	CRE		V			6/9/2054
2020 PO2243845320	F	4	40 BRO	SP	CRE		V			6/10/2054
2020 PO3922382392	LGE	4	40 BRN	SP	P	ED,ID	TD			6/11/2054
2020 PO1260433332A	ODP	5	35 BRN	SP	CRE	ID	BD			6/12/2054
2020 PO1248433368	ODP	4	45 BRN	SP	CRE	ID	BD			6/13/2054
2020 PO3924183098	F	4	40 BRO	SP	A		V			6/14/2054
2020 PO3923683095	F	5	30 BRO	SP	A		V			6/15/2054
2020 PO3922783105	F	4	40 BRO	SP	CRE		V			6/16/2054
2020 PO3922783100	F	6	25 BRO	SP	CRE	RB	VX		RP1	6/17/2054
2020 PO3921383107	F	4	40 BRO	SP	P		V			6/18/2054
2020 PO3989083020	LGE	4	40 BRN	SP	CRE	ED,ID	TD			6/19/2054
2020 PO1275333466	ODP	5	35 BRN	SP	CRE		BD			6/20/2054
2020 PO1255933492	ODP	4	35 XXX	SP	CCA		V			6/21/2054
2020 PO1275333466	ODP	4	45 BRN	SP	CCA		BD			6/22/2054
2020 PO6406635521	LGE	3	45 BRN	SP	CCA		V			6/23/2054
2020 PO3919582408	F	4	45 BRN	SP	P		V			6/24/2054
2020 PO3920182406	F	4	40 BRN	SP	CRE		V			6/25/2054
2020 PO3920682403	F	4	40 BRN	SP	CRE		V			6/26/2054
2020 PO3920382397	LGE	4	30 BRN	SP	CRE		V			6/27/2054
2020 PO3920083113	F	4	40 BRO	SP	P		V			6/28/2054
2020 PO3919383111	F	1	25 BRO	SP	P		V			6/29/2054
2020 PO3990283022	LGE	4	40 BRN	SP	P	ED,ID	TD			6/30/2054
2020 PO3983682982	F	4	40 BRN	SP	CRE		V			7/1/2054
2020 PO3984882984	F	3	45 BRN	SP	CCA		V			7/2/2054
2020 PO3919983127	F	4	40 BRO	SP	CRE		V			7/3/2054
2020 PO3919883139	F	3	45 BRO	SP	CCA		V			7/4/2054
2020 PO1270433639	ODP	5	35 BRN	SP	CCA		V			7/5/2054
2020 PO1275133680	ODP	5	35 BRN	SP	CRE	ID	BD			7/6/2054
2020 PO3919683156	F	4	40 BRO	SP	A		V			7/7/2054
2020 PO3921083153	LGE	5	30 BRO	SP	A	ID	BD			7/8/2054

2020 PO3919482465	LGE	4	30 BRN	SP	A	ED,ID	TD	7/9/2054
2020 PO4099342654	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	7/10/2054
2020 PO4096142705	F	3	45 ACE	SP	CRE		V	7/11/2054
2020 PO4735488973	F	4	40 BRO	SP	CCA		V	7/12/2054
2020 PO4734588968	F	4	40 BRO	SP	CRE		V	7/13/2054
2020 PO4733588962	F	4	40 BRO	SP	CRE		V	7/14/2054
2020 PO4732388957	F	4	40 BRO	SP	CCA		V	7/15/2054
2020 PO5182010384	F	4	40 ACE	SP	P		V	7/16/2054
2020 PO5197210321	F	4	40 ACE	SP	P		V	7/17/2054
2020 PO2109227774	ODP	5	35 XXX	SP	CRE	ID	TD	7/18/2054
2020 PO2100827788	ODP	5	35 XXX	SP	CRE	ID	TD	7/19/2054
2020 PO2152924811	ODP	4	40 XXX	SP	CRE		V	7/20/2054
2020 PO2147324632	ODP	5	30 XXX	SP	CRE		V	7/21/2054
2020 PO2158324815A	ODP	5	35 XXX	SP	CRE	ID	BD	7/22/2054
2020 PO2158324815	ODP	4	45 XXX	SP	CCA		V	7/23/2054
2020 PO2157924631	ODP	4	40 XXX	SP	CCA	ED	T	7/24/2054
2020 PO2178324557	F	5	35 XXX	SP	CRE		V	7/25/2054
2020 PO4731488952	F	4	40 BRO	SP	CRE		V	7/26/2054
2020 PO4730288932	LGE	4	30 BRO	SP	CRE		V	7/27/2054
2020 PO4730588947	F	4	40 BRO	SP	A		V	7/28/2054
2020 PO7607822775	KU	4	40 XXX	SP	CRE	ID	BD	7/29/2054
2020 PO7602722697	KU	6	30 XXX	SP	CRE	ID	TD	7/30/2054
2020 PO7589222150	KU	6	30 XXX	SP	CCA		V	7/31/2054
2020 PO7604622251	KU	6	30 XXX	SP	CCA		V	8/1/2054
2020 PO7594722203	KU	4	40 XXX	SP	CRE	ID	TD	8/2/2054
2020 PO3980482909	LGE	5	25 BRN	SP	CRE		V	8/3/2054
2020 PO3981682910	F	4	40 BRN	SP	S		V	8/4/2054
2020 PO3981282917	F	4	40 BRN	SP	A		V	8/5/2054
2020 PO2807234381	KU	5	35 BRN	SP	CRE		V	8/6/2054
2020 PO2529834259	KU	4	40 BRN	SP	CRE		V	8/7/2054
2020 PO2907133709	KU	5	35 BRN	SP	CRE	ED,ID,MD	TD	8/8/2054
2020 PO3981082929	F	4	40 BRN	SP	CRE		V	8/9/2054
2020 PO3980982941	F	4	40 BRN	SP	CRE		V	8/10/2054
2020 PO3980782953	F	3	45 BRN	SP	CCA		V	8/11/2054
2020 PO3980682965	F	4	40 BRN	SP	CRE		V	8/12/2054
2020 PO3979882981	LGE	4	30 BRN	SP	CCA	ED,ID	BD	8/13/2054
2020 PO3980782974	F	4	40 BRN	SP	CCA		V	8/14/2054
2020 PO3981382979	F	4	40 BRN	SP	CCA		V	8/15/2054
2020 PO3982482981	F	4	40 BRN	SP	CRE		V	8/16/2054
2020 PO3987583051	LGE	4	40 BRN	SP	CRE	ED,ID	TD	8/17/2054
2020 PO7591922036A	KU	6	30 XXX	SP	CRE	ID,IP	TD	8/18/2054
2020 PO7591922036	KU	4	40 XXX	SP	CRE	ID	TD	8/19/2054
2020 PO7586921878	KU	4	40 XXX	SP	CRE	ID	TD	8/20/2054
2020 PO7573421481	KU	4	40 XXX	SP	CCA		V	8/21/2054
2020 PO7570021152	KU	5	35 XXX	SP	CRE	ID	BD	8/22/2054
2020 PO7570021152A	KU	7	25 XXX	SP	CRE	IP	X	8/23/2054
2020 PO7569121017A	KU	6	30 XXX	SP	CCA		V	8/24/2054

2020 PO7569121017	KU	4	45 XXX	SP	CCA			V		8/25/2054
2020 PO7560520670	KU	4	40 XXX	SP	CRE	ID		TD		8/26/2054
2020 PO7545320507	KU	5	35 XXX	SP	CRE	ID		TD		8/27/2054
2020 PO7546520456	KU	6	30 XXX	SP	CCA			V		8/28/2054
2020 PO7564520908	F	5	35 XXX	SP	CRE			V		8/29/2054
2020 PO7563320853	KU	4	40 XXX	SP	CRE	ID		TD		8/30/2054
2020 PO7162021160	KU	5	35 XXX	SP	CRE			V		8/31/2054
2020 PO3987383043	LGE	4	35 BRN	SP	CCA			V		9/1/2054
2020 PO4042643621	KU	2	50 ACE	SP	CCA			V		9/2/2054
2020 PO4063243562	KU	2	50 ACE	SP	CCA			V		9/3/2054
2020 PO3993983018	LGE	4	30 BRN	SP	CCA			V		9/4/2054
2020 PO2579833939	KU	4	40 BRN	SP	CCA			V		9/5/2054
2020 PO1057832783	ODP	2	80 XXX	SP	CRE		ED,ID,IP	TD		9/6/2054
2020 PO3944582890	F	4	40 BRO	SP	CCA			V		9/7/2054
2020 PO3943882865	F	1	25 BRO	SP	CCA			V		9/8/2054
2020 PO3942482858	F	3	20 BRO	SP	CCA			V		9/9/2054
2020 PO3940882864	F	5	25 BRO	SP	CCA			V		9/10/2054
2020 PO3943182870	F	4	40 BRO	SP	CCA			V		9/11/2054
2020 PO3942282865	F	4	40 BRO	SP	P			V		9/12/2054
2020 PO3995583025	LGE	6	25 BRN	SP	CRE		ED,ID	VX	PX	9/13/2054
2020 PO3995083032	LGE	4	40 BRN	SP	CRE		ED,ID	TD		9/14/2054
2020 PO4093743434	KU	2	50 ACE	SP	CCA			V		9/15/2054
2020 PO1101633045	ODP	5	35 BRN	SP	CCA			V		9/16/2054
2020 PO1100432953	ODP	4	40 XXX	SP	CRE		ED,ID	TD		9/17/2054
2020 PO387782930	LGE	4	35 BRO	SP	P		ED	TD		9/18/2054
2020 PO3876382933	LGE	4	35 BRO	SP	P		ED	TD		9/19/2054
2020 PO3874082948	LGE	4	35 BRO	SP	A		ED,IP	TD		9/20/2054
2020 PO3874482960	LGE	4	30 BRO	SP	P		ED,IP	TD		9/21/2054
2020 PO3874782938	LGE	4	35 BRO	SP	P		ED,ID,IP	TD		9/22/2054
2020 PO3873582977	LGE	4	35 BRO	SP	A		ED,ID	TD		9/23/2054
2020 PO3873682993	LGE	4	35 BRO	SP	P		ED,ID	TD		9/24/2054
2020 PO3876782939	LGE	4	40 BRO	SP	CCA			V		9/25/2054
2020 PO2602234098	KU	4	40 BRN	SP	CRE		ED,ID,SRS	TD		9/26/2054
2020 PO2622134240	KU	4	40 BRN	SP	CRE		ED,ID,IP	TD		9/27/2054
2020 PO2646534423	KU	4	40 BRN	SP	CRE		ED,ID	TD		9/28/2054
2020 PO2678534655	KU	4	40 BRN	SP	CRE		ED,ID,IP	TD		9/29/2054
2020 PO2841037828	KU	4	40 BRN	SP	CRE		ID,IP	BD		9/30/2054
2020 PO3952382810	LGE	4	45 BRO	SP	CRE		ED,ID,RB	TX	RR	10/1/2054
2020 PO3916082557	F	4	30 BRN	SP	CCA			V		10/2/2054
2020 PO3994983041	LGE	4	35 BRN	SP	CCA			V		10/3/2054
2020 PO3916282561	F	3	40 BRN	SP	CCA			V		10/4/2054
2020 PO3917582553	F	3	45 BRN	SP	CRE			V		10/5/2054
2020 PO4123643299	KU	2	50 ACE	SP	CRE			V		10/6/2054
2020 PO1149233237	ODP	4	40 BRN	SP	CRE		ID	TD		10/7/2054
2020 PO1147833291	ODP	4	40 BRN	SP	CRE		ID	BD		10/8/2054
2020 PO3995783038	LGE	3	45 BRN	SP	S			V		10/9/2054
2020 PO4132443249	KU	2	50 ACE	SP	CRE			V		10/10/2054

2020 PO1062532896	ODP	2	55 XXX	SP	CRE	ED,ID	TD	10/11/2054
2020 PO1066233032	ODP	2	55 XXX	SP	CCA		V	10/12/2054
2020 PO1066233176	ODP	4	40 XXX	SP	CRE	ED,ID	TD	10/13/2054
2020 9444518960A	KU	5	35 ACW	SP	CRE	ID	TD	10/14/2054
2020 PO9460619317	KU	5	35 UNK	SP	CRE	ED,ID,SRS	TD	10/15/2054
2020 PO9464019715	KU	5	35 ACW	SP	CRE	ED,ID,SRS	TD	10/16/2054
2020 PO3996283024	LGE	4	30 BRN	SP	CRE	ED,ID	TD	10/17/2054
2020 PO3996783033	LGE	4	40 BRN	SP	CRE	ED,ID	TD	10/18/2054
2020 PO3997583034	LGE	4	40 BRN	SP	CRE	ED,ID	TD	10/19/2054
2020 PO3941082871	F	4	40 BRO	SP	A		V	10/20/2054
2020 PO3939682877	F	4	40 BRO	SP	A		V	10/21/2054
2020 PO3938282884	F	4	40 BRO	SP	P		V	10/22/2054
2020 PO3936482885	F	5	25 BRO	SP	P		V	10/23/2054
2020 PO3936782891	F	4	40 BRO	SP	CRE		V	10/24/2054
2020 PO3935482899	F	4	40 BRO	SP	P		V	10/25/2054
2020 PO3936082901	F	4	30 BRO	SP	P		V	10/26/2054
2020 PO3947582873	LGE	3	45 BRO	SP	CRE	ED,ID	TD	10/27/2054
2020 PO1157133245	ODP	4	40 OTH	SP	CRE	ID,SRS	TD	10/28/2054
2020 PO4131243117	KU	3	45 ACE	SP	CCA		V	10/29/2054
2020 PO4144746071	KU	3	45 ACE	SP	CRE		V	10/30/2054
2020 PO4141146002	KU	3	45 ACE	SP	CCA		V	10/31/2054
2020 PO4139645962	KU	4	40 ACE	SP	CRE		V	11/1/2054
2020 PO4134445853	KU	5	35 ACE	SP	CRE		V	11/2/2054
2020 PO4129345745	KU	5	35 ACE	SP	CRE		V	11/3/2054
2020 PO4124645645	KU	4	40 ACE	SP	CRE		V	11/4/2054
2020 PO4119545537	KU	4	40 ACE	SP	CCA		V	11/5/2054
2020 PO4113645410	KU	4	40 ACE	SP	CCA		V	11/6/2054
2020 PO4108545301	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	11/7/2054
2020 PO3918782545	F	4	45 BRN	SP	P		V	11/8/2054
2020 PO2145346767	KU	4	40 BRO	SP	CRE	ED	TD	11/9/2054
2020 PO2165046611	KU	4	40 BRO	SP	CRE	ID,IP	BD	11/10/2054
2020 PO3919582535	F	4	30 BRN	SP	P		V	11/11/2054
2020 PO3919982537	F	4	40 BRN	SP	P		V	11/12/2054
2020 PO1161133337	ODP	5	35 OTH	SP	CRE	ID,SRS	TD	11/13/2054
2020 PO4103445193	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	11/14/2054
2020 PO3921282529	LGE	4	40 BRN	SP	CRE	ED,ID	TD	11/15/2054
2020 PO3922582520	LGE	4	45 BRN	SP	CRE	ED,ID,RB	X	PX
2020 PO3998083036	LGE	6	25 BRN	SP	CRE	ED,HH,ID	VX	PX
2020 9400117976B	KU	6	30 OTH	SP	CRE	ID	TD	11/18/2054
2020 9400117976A	KU	6	30 INP	SP	CRE	ID	TD	11/19/2054
2020 PO9350518070	KU	4	40 INP	SP	CRE	ID	TD	11/20/2054
2020 PO9400117976	KU	4	40 UNK	SP	CRE	ID	TD	11/21/2054
2020 PO9389517998	KU	6	30 UNK	SP	CRE	ED,ID,SRS	TD	11/22/2054
2020 PO9422917903	KU	6	30 ACW	SP	CRE	ID	TD	11/23/2054
2020 PO4092642634	KU	5	35 ACE	SP	CCA		V	11/24/2054
2020 PO5153008586	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	RP1
2020 PO4105742552	F	4	40 ACE	SP	CRE		V	11/26/2054

2020 PO3920083169	F	5	30 BRO	SP	P		V			11/27/2054
2020 PO3919483171	F	4	40 BRO	SP	P		V			11/28/2054
2020 PO3919283187	F	4	40 BRO	SP	A		V			11/29/2054
2020 PO3917683199	LGE	4	35 BRO	SP	P		V			11/30/2054
2020 PO3919083200	F	4	40 BRO	SP	P		V			12/1/2054
2020 PO3918983214	F	4	40 BRO	SP	CRE		V			12/2/2054
2020 PO3918683231	F	4	40 BRO	SP	CRE		V			12/3/2054
2020 PO3918583246	F	4	40 BRO	SP	P		V			12/4/2054
2020 PO3918383262	F	4	40 BRO	SP	A		V			12/5/2054
2020 PO3918183278	F	4	40 BRO	SP	P		V			12/6/2054
2020 PO3917083292	F	5	25 BRO	SP	P		V			12/7/2054
2020 PO3917983294	F	4	40 BRO	SP	CRE		V			12/8/2054
2020 PO3985982985	F	4	40 BRN	SP	CRE		V			12/9/2054
2020 PO3917883309	F	4	40 BRO	SP	CRE		V			12/10/2054
2020 PO3917683319	F	3	45 BRO	SP	P		V			12/11/2054
2020 PO5139008642	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX		PX	12/12/2054
2020 PO5165609648	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX		PX	12/13/2054
2020 PO4745889140	F	3	45 BRN	SP	S		V			12/14/2054
2020 PO4747089147	F	3	45 BRN	SP	S		V			12/15/2054
2020 PO5042102125	KU	4	40 BRN	SP	CRE	ED,ID	TD			12/16/2054
2020 PO4744389131	F	4	40 BRN	SP	CCA		V			12/17/2054
2020 PO4743689142	F	3	45 BRN	SP	CCA		V			12/18/2054
2020 PO4743189150	F	3	45 BRN	SP	CCA		V			12/19/2054
2020 PO5144509605	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX		PX	12/20/2054
2020 PO1292775473	KU	4	40 BRN	SP	CRE	ID,IP	BD			12/21/2054
2020 PO0997677328	KU	4	40 BRN	SP	A	ED,ID,IP	TD			12/22/2054
2020 PO0931757578	KU	4	40 ACW	SP	CRE	ED,ID	BD			12/23/2054
2020 PO0915557501	KU	4	40 ACW	SP	CRE	ED,ID	BD			12/24/2054
2020 PO0941756907	KU	4	45 ACW	SP	CRE	ED,EP,HH,ID,IP,RB	BX		RP1	12/25/2054
2020 PO0950755955	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD			12/26/2054
2020 PO0964955734	KU	4	40 ACW	SP	CRE	ED,ID	BD			12/27/2054
2020 PO1301976504	KU	4	45 BRN	SP	CRE	ID,IP	BD			12/28/2054
2020 PO0953456248	KU	6	30 ACW	SP	CRE	ED,ID	BD			12/29/2054
2020 PO1301976693	KU	6	30 BRN	SP	CRE	ED	TD			12/30/2054
2020 PO0934056220	KU	4	40 ACW	SP	CRE	ED,ID	BD			12/31/2054
2020 PO0937456566	KU	4	40 ACW	SP	CRE	ED,ID	BD			1/1/2055
2020 PO0902757306	KU	4	40 ACW	SP	CRE	ED,ID	BD			1/2/2055
2020 PO0895457335	KU	6	30 ACW	SP	CRE	ED,ID	BD			1/3/2055
2020 PO0791260274a	KU	4	40 ACW	SP	CRE	ED,ID	BD			1/4/2055
2020 PO0791260274	KU	4	45 ACW	SP	CRE	ED,ID	BD			1/5/2055
2020 PO0815860340	KU	5	35 ACW	SP	CRE	ED,ID,IP	TD			1/6/2055
2020 PO0788060376	KU	4	45 ACW	SP	CRE	ED,EP,ID,IP	TD			1/7/2055
2020 PO0763960527	KU	6	30 ACW	SP	CRE	ED,ID	TD			1/8/2055
2020 PO1221777887	KU	4	40 BRN	SP	CRE	ID,IP	BD			1/9/2055
2020 PO1220277613	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD			1/10/2055
2020 PO1210277088	KU	4	40 BRN	SP	CRE	ID,IP	BD			1/11/2055
2020 PO1177676956	KU	4	40 BRN	SP	CRE	ID,IP	BD			1/12/2055

2020 PO1199676513	KU	4	40 BRN	SP	CRE	ED	T		1/13/2055
2020 PO1232876532	KU	4	40 BRN	SP	CCA		V		1/14/2055
2020 PO1728275771	KU	4	40 BRN	SP	CRE		V		1/15/2055
2020 PO1755275684	KU	4	40 BRN	SP	CRE		V		1/16/2055
2020 PO1734276051	KU	4	40 BRN	SP	CRE		V		1/17/2055
2020 PO1738176237	KU	4	40 BRN	SP	CRE		V		1/18/2055
2020 PO1716876292	KU	5	35 BRN	SP	CCA		V		1/19/2055
2020 PO1751376522	KU	4	40 BRN	SP	CRE		V		1/20/2055
2020 PO1790810687	KU	4	40 BRN	SP	CRE		V		1/21/2055
2020 PO4042782831	LGE	4	40 BRO	SP	P	ED,ID,IP,RB	TX	RR	1/22/2055
2020 PO1797910773	KU	5	35 BRN	SP	CCA		V		1/23/2055
2020 PO1764510719	KU	5	30 KOP	SP	CRE	ED,ID	TD		1/24/2055
2020 PO7203791771	KU	4	40 BRO	SP	CRE	ED,ID	TD		1/25/2055
2020 PO6899794448	KU	4	40 BRN	SP	CRE	ED,HH,ID	X	PX	1/26/2055
2020 PO6882194622	KU	4	40 BRN	SP	CRE	ED,ID	TD		1/27/2055
2020 PO7201291284	KU	4	45 BRO	SP	CCA		V		1/28/2055
2020 PO7205891343	KU	6	30 BRO	SP	CCA		V		1/29/2055
2020 PO7205091524	KU	3	50 BRO	SP	P	ED,ID,IP,RB	TX	RR	1/30/2055
2020 PO7206191506	KU	6	30 BRO	SP	CCA		V		1/31/2055
2020 PO6884194753	KU	5	35 BRN	SP	CRE	ED,ID	BD		2/1/2055
2020 PO5085131777	KU	3	45 BRO	SP	CCA		V		2/2/2055
2020 PO5082631794	KU	3	45 BRO	SP	CCA		V		2/3/2055
2020 PO5070231875	KU	3	45 BRO	SP	CCA		V		2/4/2055
2020 PO5054031974	KU	2	60 BRO	SP	CCA		V		2/5/2055
2020 PO5037532077	KU	3	45 BRO	SP	CCA		V		2/6/2055
2020 PO4730488818	LGE	4	35 BRN	SP	A	ED,ID	TX	RR	2/7/2055
2020 PO4400400640	LGE	3	45 BRN	SP	S		V		2/8/2055
2020 PO4732588799	LGE	4	40 BRN	SP	A	ED,ID	TD		2/9/2055
2020 PO4044982798	LGE	4	40 BRO	SP	P	ED,ID	TD		2/10/2055
2020 PO4044682808	LGE	4	40 BRO	SP	CRE	ED,ID	TD		2/11/2055
2020 PO4481101049	KU	4	40 BRN	SP	CRE	ED,ID	TD		2/12/2055
2020 PO4489801098	KU	4	40 BRN	SP	CRE	ED,ID	TD		2/13/2055
2020 PO4734088773	LGE	4	40 BRN	SP	A	ED,ID	TD		2/14/2055
2020 4495700933a	KU	6	30 BRN	SP	CCA		V		2/15/2055
2020 PO4495700933	KU	4	40 BRN	SP	CRE	ED,ID	TD		2/16/2055
2020 PO4734288770	LGE	5	25 BRN	SP	A	ED,ID	BD		2/17/2055
2020 PO4503100781	KU	4	45 BRN	SP	CRE	ID,RB	X	RP1	2/18/2055
2020 PO4500400819	KU	4	40 BRN	SP	CRE	ED,ID,RB	X	RP1	2/19/2055
2020 PO4734388754	LGE	4	35 BRN	SP	A	ED,ID	TD		2/20/2055
2020 PO4735488760	LGE	4	35 BRN	SP	A	ED,ID	TD		2/21/2055
2020 PO4511800642	KU	4	45 BRN	SP	CRE	ED,ID	TD		2/22/2055
2020 PO5025632157	KU	3	45 BRO	SP	CCA		V		2/23/2055
2020 PO5011532245	KU	3	45 BRO	SP	CCA		V		2/24/2055
2020 PO4996832337	KU	3	45 BRO	SP	CCA		V		2/25/2055
2020 PO5097031692	KU	3	45 BRO	SP	CCA		V		2/26/2055
2020 PO6919494793	KU	5	35 BRN	SP	CRE	ED,ID	TD		2/27/2055
2020 PO6918394689	KU	4	40 BRN	SP	S		V		2/28/2055

2020 PO5021131113	KU	3	45 BRO	SP	CRE		V			3/1/2055
2020 PO5040430806	KU	3	45 BRO	SP	CRE		V			3/2/2055
2020 PO4999731297	KU	3	45 BRO	SP	CCA		V			3/3/2055
2020 PO5049733035	KU	3	45 BRO	SP	CCA		V			3/4/2055
2020 PO4982031448	KU	3	45 BRO	SP	CCA		V			3/5/2055
2020 PO5052833074	KU	3	45 BRO	SP	CCA		V			3/6/2055
2020 PO5057832993	KU	3	50 BRO	SP	CCA		V			3/7/2055
2020 PO6886294900	KU	4	40 BRN	SP	CRE	ED,ID	BD			3/8/2055
2020 PO6920094895	KU	5	35 BRN	SP	CRE	ED,ID	TD			3/9/2055
2020 PO4964331600	KU	3	45 BRO	SP	CCA		V			3/10/2055
2020 PO4948431721	KU	3	45 BRO	SP	CCA		V			3/11/2055
2020 PO4944231760	KU	2	50 BRO	SP	CCA		V			3/12/2055
2020 PO4957531898	KU	2	50 BRO	SP	CCA		V			3/13/2055
2020 PO4970732055	KU	2	50 BRO	SP	CCA		V			3/14/2055
2020 PO4994832379	KU	4	40 BRO	SP	CRE	ID,IP	TD			3/15/2055
2020 PO5007432530	KU	4	40 BRO	SP	CRE	HH,RB	X		PX	3/16/2055
2020 PO5023632724	KU	4	40 BRO	SP	CRE	ID,IP	BD			3/17/2055
2020 PO5039232908	KU	3	45 BRO	SP	CRE	ID,IP	TD			3/18/2055
2020 PO7633903498	KU	5	35 XXX	SP	CRE	ED,ID,IP	TD			3/19/2055
2020 PO7619903735	KU	4	40 XXX	SP	CRE	ED,ID	TD			3/20/2055
2020 PO7621403925	KU	4	40 XXX	SP	CRE	ED,ID	TD			3/21/2055
2020 PO7588303384	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD			3/22/2055
2020 PO7100691161	KU	5	35 BRO	SP	CRE	ED,ID,IP,SRC	TD			3/23/2055
2020 PO6900895039	KU	3	35 BRN	SP	CRE	ED,ID	BD			3/24/2055
2020 PO6888595053	KU	3	35 BRN	SP	S		V			3/25/2055
2020 PO6920895007	KU	4	40 BRN	SP	CRE	ED,ID	TD			3/26/2055
2020 PO6921495108	KU	4	40 BRN	SP	CRE	ED,ID	TD			3/27/2055
2020 PO6890795200	KU	4	45 BRN	SP	CRE	ED,ID	BD			3/28/2055
2020 PO6921995234	KU	4	40 BRN	SP	CRE	ED,ID	TD			3/29/2055
2020 PO6892895333	KU	4	40 BRN	SP	CRE	ED,ID	BD			3/30/2055
2020 PO6923195358	KU	4	40 BRN	SP	CCA		V			3/31/2055
2020 PO7135091408	KU	4	40 BRO	SP	CRE	ED	T			4/1/2055
2020 PO2189145358	KU	4	40 BRN	SP	CRE	ED,ID,IP,SRC	TD			4/2/2055
2020 PO2195645447	KU	4	40 BRN	SP	CCA		V			4/3/2055
2020 PO7602203393	KU	4	40 XXX	SP	CRE	ED,ID	TD			4/4/2055
2020 PO7602203436	KU	4	40 XXX	SP	CRE	ED,ID	TD			4/5/2055
2020 PO7635004099	KU	4	30 XXX	SP	CCA	ED	T			4/6/2055
2020 PO2160045406	KU	3	45 BRN	SP	CRE	ED,ID,IP,SRC	TD			4/7/2055
2020 PO5065233185	KU	2	45 BRO	SP	CRE	ID,SRS	TD			4/8/2055
2020 PO5095333534	KU	2	50 BRO	SP	CCA		V			4/9/2055
2020 PO5073133095	KU	3	45 BRO	SP	CCA		V			4/10/2055
2020 PO5085633218	KU	3	45 BRO	SP	CCA		V			4/11/2055
2020 PO	KU	3	45 BRO	SP	CCA		V			4/12/2055
2020 PO5106533301	KU	3	45 BRO	SP	CCA		V			4/13/2055
2020 PO5127333387	KU	3	45 BRO	SP	CCA		V			4/14/2055
2020 PO7147791332	KU	5	35 BRO	SP	CRE	ID	BD			4/15/2055
2020 PO2113845765	KU	4	40 BRN	SP	CRE	ID	BD			4/16/2055

2020 PO2113945472	KU	4	40 BRN	SP	CRE	ED,EP,ID,IP,RB	X	PX	4/17/2055
2020 PO7121191187	KU	6	30 BRO	SP	CRE	ED,ID	TD		4/18/2055
2020 PO7128491112	KU	4	30 BRO	SP	CRE		V		4/19/2055
2020 PO7167091759	KU	3	40 BRO	SP	CRE	ED,ID,MD,RB	VX	PX	4/20/2055
2020 PO6905595310	KU	6	30 BRN	SP	CRE	ED,ID	BD		4/21/2055
2020 PO6908295591	LGE	4	30 BRN	SP	CCA		V		4/22/2055
2020 PO6907895647	KU	4	40 BRN	SP	CRE	ED,ID	BD		4/23/2055
2020 PO2069745466	F	4	40 BRN	SP	CRE		V		4/24/2055
2020 PO7006620950	KU	4	40 XXX	SP	CRE	ID	TD		4/25/2055
2020 PO6878993849	KU	5	35 BRN	SP	CRE		V		4/26/2055
2020 PO7243288725	F	4	45 BRN	SP	CCA		V		4/27/2055
2020 PO3884983000	LGE	4	35 BRO	SP	P	ED,ID,MD	TD		4/28/2055
2020 PO3883583001	LGE	4	40 BRO	SP	CCA		V		4/29/2055
2020 PO3882083003	LGE	4	35 BRO	SP	P	ED,RB,SRS	TD		4/30/2055
2020 PO3880583004	LGE	4	35 BRO	SP	P	ED,RB,SR	TD		5/1/2055
2020 PO3883282983	LGE	4	35 BRO	SP	P	ED,ID	TD		5/2/2055
2020 PO7216088887	KU	3	30 BRN	SP	CRE		V		5/3/2055
2020 PO7219288949	KU	6	30 BRN	SP	CRE		V		5/4/2055
2020 PO2677537958	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD		5/5/2055
2020 PO2691137811	KU	5	35 BRN	SP	CRE	ED,ID,IP,MD	TD		5/6/2055
2020 PO2704837665	KU	5	35 BRN	SP	CRE	ID,IP	BD		5/7/2055
2020 PO9244515287	KU	5	35 BRN	SP	CRE		V		5/8/2055
2020 PO9209015644	KU	5	35 BRN	SP	CRE		V		5/9/2055
2020 PO9269214897	KU	5	35 BRN	SP	CRE		V		5/10/2055
2020 PO9175316001	KU	5	35 BRN	SP	CRE		V		5/11/2055
2020 PO7247089139	KU	6	30 BRN	SP	CRE	ED,ID	TD		5/12/2055
2020 PO3358148771	KU	6	30 BRO	SP	CRE	ED	TD		5/13/2055
2020 PO3402448569	KU	4	40 BRO	SP	CCA		V		5/14/2055
2020 PO3403448595	F	4	40 BRO	SP	CRE		V		5/15/2055
2020 PO3418148500	F	4	40 BRO	SP	CRE		V		5/16/2055
2020 PO4323540184	KU	2	55 BRO	SP	CCA		V		5/17/2055
2020 PO4310240295	KU	2	55 BRO	SP	CCA		V		5/18/2055
2020 PO4045082579	LGE	4	40 BRN	SP	CRE	ED,ID	TD		5/19/2055
2020 PO4045982587	LGE	4	40 BRN	SP	CRE	ED,ID	BX	PX	5/20/2055
2020 PO1077620085	ODP	4	40 BRN	SP	CCA	ED,SRS	TD		5/21/2055
2020 PO1072820368	ODP	4	40 UNK	SP	CRE	ED,ID,SRS	TD		5/22/2055
2020 PO1061820909	ODP	4	40 UNK	SP	CRE	ED,ID,SRS	TD		5/23/2055
2020 PO1041121230	ODP	6	30 UNK	SP	S		V		5/24/2055
2020 PO2403028303	ODP	4	40 BRN	SP	CRE	ID	TD		5/25/2055
2020 PO2415128567a	ODP	5	35 BRN	SP	CRE	ID	TD		5/26/2055
2020 PO2415128567	ODP	4	40 BRN	SP	CRE	ID	BD		5/27/2055
2020 PO2342727503	ODP	4	40 BRN	SP	CRE	ID	TD		5/28/2055
2020 PO2330827087	ODP	4	40 BRN	SP	CRE	ID	TD		5/29/2055
2020 PO4616531564a	KU	5	35 ACE	SP	CRE	ED,ID	BD		5/30/2055
2020 PO4616531564	KU	3	45 ACE	SP	CRE	ED,ID	TD		5/31/2055
2020 PO4046182599	LGE	4	40 BRN	SP	CRE	HH,ID	TD		6/1/2055
2020 PO4045682604	LGE	4	40 BRN	SP	CRE	HH,ID	TD		6/2/2055

2020 PO4045082604	LGE	4	30 BRN	SP	A	ED,ID	TD	6/3/2055
2020 PO4044782609	LGE	4	40 BRN	SP	CRE	ED,ID	BD	6/4/2055
2020 PO4599431782	KU	5	35 ACE	SP	CRE	ED,ID	TD	6/5/2055
2020 P01071718809C	ODP	5	45 OTH	SP	CRE	ED,ID,SRS	TD	6/6/2055
2020 P01071718809D	ODP	5	45 OTH	SP	CRE	ID	TD	6/7/2055
2020 P01071718809E	ODP	5	45 UNK	SP	CRE	ID	TD	6/8/2055
2020 PO4044382619	LGE	4	40 BRN	SP	CRE	ED,ID	TD	6/9/2055
2020 PO4044582631	LGE	4	40 BRN	SP	A	ED,ID	TD	6/10/2055
2020 PO4044282643	LGE	4	40 BRN	SP	CRE	ED,ID	T	6/11/2055
2020 PO4608531736	KU	4	40 ACE	SP	CCA		V	6/12/2055
2020 PO4622431701	KU	3	40 ACE	SP	CRE	ED,ID,IP	TD	6/13/2055
2020 PO4611731788a	KU	5	35 ACE	SP	P	ED	T	6/14/2055
2020 PO4611731788	KU	5	35 ACE	SP	CRE	ED,ID	TD	6/15/2055
2020 PO9397284218	KU	4	40 BRN	SP	S		V	6/16/2055
2020 PO4044582676	LGE	4	40 BRN	SP	CRE	ED,ID	TD	6/17/2055
2020 PO4045082672	LGE	4	35 BRN	SP	A	ED,ID	TD	6/18/2055
2020 PO7071702107	KU	4	45 BRN	SP	CRE		V	6/19/2055
2020 PO4296440407	KU	2	55 BRO	SP	CCA		V	6/20/2055
2020 PO4278440616	KU	2	55 BRO	SP	CCA		V	6/21/2055
2020 PO4308240586	KU	3	45 BRO	SP	CCA		V	6/22/2055
2020 PO4299240622	KU	4	40 BRO	SP	CCA		V	6/23/2055
2020 PO2063925714	ODP	6	30 XXX	SP	CCA		V	6/24/2055
2020 PO2728937095	ODP	4	40 BRN	SP	CCA		V	6/25/2055
2020 PO2737437413	ODP	4	40 UNK	SP	CRE	ED,ID	TD	6/26/2055
2020 PO2749537305	ODP	4	40 UNK	SP	CRE	ED,ID,SRS	TD	6/27/2055
2020 PO2757937392	ODP	4	40 UNK	SP	CRE	ED,ID,IP	TX	RR 6/28/2055
2020 PO2782237374	ODP	4	40 CAH	SP	CRE	ED,ID	TD	6/29/2055
2020 PO2775837490	ODP	5	35 BRN	SP	CRE		V	6/30/2055
2020 PO4418139339	KU	3	45 BRO	SP	CCA		V	7/1/2055
2020 PO4403139491	KU	3	45 BRO	SP	CCA		V	7/2/2055
2020 PO4421639505	KU	1	60 BRO	SP	CCA		V	7/3/2055
2020 PO4441939320	KU	1	60 BRO	SP	CCA		V	7/4/2055
2020 PO4381139848	KU	1	60 BRO	SP	CCA		V	7/5/2055
2020 PO4390139368	KU	4	40 BRO	SP	CCA		V	7/6/2055
2020 PO4426639444	KU	1	60 BRO	SP	CCA		V	7/7/2055
2020 PO4463939136	KU	1	60 BRO	SP	CCA		V	7/8/2055
2020 PO4477439024	KU	1	65 BRO	SP	CCA		V	7/9/2055
2020 PO4482338971	KU	1	60 BRO	SP	CCA		V	7/10/2055
2020 PO4773636393	KU	2	55 ACE	SP	CCA		V	7/11/2055
2020 PO2467745916	ODP	4	40 KOP	SP	CRE	ED,ID	TD	7/12/2055
2020 PO2434945920	ODP	6	30 KOP	SP	CRE	ED,ID	TD	7/13/2055
2020 PO4706437348	KU	2	50 ACE	SP	CCA		V	7/14/2055
2020 PO4701837258	KU	2	50 ACE	SP	CCA		V	7/15/2055
2020 PO4697337172	KU	3	50 ACE	SP	CCA		V	7/16/2055
2020 PO4693137090	KU	1	55 ACE	SP	CCA		V	7/17/2055
2020 PO4816436040	KU	2	55 ACE	SP	CCA		V	7/18/2055
2020 PO2426945746	ODP	5	35 KOP	SP	CRE	ED,ID	TD	7/19/2055

2020 PO2347645802	ODP	5	35 KOP	SP	S		V		7/20/2055
2020 PO2326645939	ODP	4	40 KOP	SP	CRE	ID	BD		7/21/2055
2020 PO4573432648	KU	3	45 BRN	SP	CRE	ID,IP	BD		7/22/2055
2020 PO0514037024	ODP	4	40 XXX	SP	CRE		V		7/23/2055
2020 PO0555036916	ODP	5	35 XXX	SP	CRE		V		7/24/2055
2020 PO0655036754	ODP	4	40 XXX	SP	CRE		V		7/25/2055
2020 PO0634536647	ODP	4	40 XXX	SP	CRE		V		7/26/2055
2020 PO2368245675	ODP	4	40 KOP	SP	CRE	ED,ID,IP	TD		7/27/2055
2020 PO2062143673	ODP	5	30 KOP	SP	CRE	ED,ID	TD		7/28/2055
2020 PO2051843493	ODP	4	40 KOP	DF	CRE	ED,ID	TD		7/29/2055
2020 PO0794938118a	ODP	5	30 XXX	SP	CCA		V		7/30/2055
2020 PO0794938118	ODP	4	40 XXX	SP	CCA		V		7/31/2055
2020 PO0784937812	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD		8/1/2055
2020 PO0785637617	F	4	40 XXX	SP	P		V		8/2/2055
2020 PO0783937372	ODP	4	35 XXX	SP	CCA		V		8/3/2055
2020 PO0805637228	F	4	40 XXX	SP	CRE		V		8/4/2055
2020 PO0810537232	ODP	3	45 XXX	SP	CCA		V		8/5/2055
2020 PO0846336945	ODP	3	45 XXX	SP	CCA		V		8/6/2055
2020 PO0918536750	ODP	6	30 XXX	SP	CRE	ID	TD		8/7/2055
2020 PO0911136761	ODP	4	40 XXX	SP	CRE		B		8/8/2055
2020 PO4583532785	KU	3	45 BRN	SP	CRE	ED,ID,SRS	TD		8/9/2055
2020 PO4310088175	LGE	5	35 ACW	SP	CRE	ED,HH,ID,RB	BX	RP3	8/10/2055
2020 PO4583932950	KU	3	45 BRN	SP	CRE	ED,ID,SRS	TD		8/11/2055
2020 PO4568433077	KU	3	45 BRN	SP	CRE	ED,ID,SRS	TD		8/12/2055
2020 PO4552933204	KU	3	45 BRN	SP	CRE	ID	BD		8/13/2055
2020 PO4805136133	KU	2	55 ACE	SP	CCA		V		8/14/2055
2020 PO4820936003	KU	2	55 ACE	SP	CCA		V		8/15/2055
2020 PO4788536272	KU	2	55 ACE	SP	CCA		V		8/16/2055
2020 PO2227344649	ODP	4	40 KOP	DF	CRE	ED,ID	TD		8/17/2055
2020 PO2213844713	ODP	5	35 KOP	SP	S		V		8/18/2055
2020 PO2201744673	ODP	4	40 KOP	DF	CRE	ID	BD		8/19/2055
2020 PO0870136807	ODP	3	45 XXX	SP	CCA		V		8/20/2055
2020 PO0882636537	ODP	1	20 XXX	SP	CCA		V		8/21/2055
2020 PO0884736437	ODP	2	65 XXX	SP	CCA		V		8/22/2055
2020 PO0880336587	ODP	2	50 XXX	SP	CCA		V		8/23/2055
2020 PO0867636526	ODP	2	40 XXX	SP	CRE	ED,HH,ID,RB	X	PX	8/24/2055
2020 PO0856436570	ODP	4	45 XXX	SP	CRE	ID	B		8/25/2055
2020 PO2115724742	ODP	4	45 XXX	SP	CCA		V		8/26/2055
2020 PO2182744699	ODP	4	40 KOP	SP	CRE	ED,ID	TD		8/27/2055
2020 PO4309888168	LGE	5	40 ACW	SP	CRE	ID	BD		8/28/2055
2020 PO4310488168	LGE	5	35 ACW	SP	CRE		V		8/29/2055
2020 PO4310588167	LGE	4	45 ACW	SP	S		V		8/30/2055
2020 PO4311188166	LGE	5	35 ACW	SP	CRE		V		8/31/2055
2020 PO4311788166	LGE	5	35 ACW	SP	CCA	ID	BD		9/1/2055
2020 PO4313888163	LGE	5	35 ACW	SP	CRE	ID	BD		9/2/2055
2020 PO4314388163	LGE	5	35 ACW	SP	CRE		V		9/3/2055
2020 PO4310688174	LGE	2	60 ACW	SP	S		V		9/4/2055

2020 PO4311488173	LGE	3	45 ACW	SP	S		V			9/5/2055
2020 PO4312188172	LGE	2	55 ACW	SP	S		V			9/6/2055
2020 PO4312888171	LGE	2	55 ACW	SP	P	ID	BD			9/7/2055
2020 PO4313888169	LGE	2	60 ACW	SP	CRE	ID,IP	BD			9/8/2055
2020 PO4314188169	LGE	2	55 ACW	SP	CRE	ID,IP,MD	BD			9/9/2055
2020 PO4315188168	LGE	3	55 ACW	SP	CRE	ED,HH,ID,RB	BX	PX		9/10/2055
2020 PO4315888169	F	6	30 ACW	SP	CRE		V			9/11/2055
2020 PO0278693698	LGE	1	55 ACW	SP	S		V			9/12/2055
2020 PO4316388165	LGE	3	55 ACW	SP	CRE	ID	BD			9/13/2055
2020 PO2334045189	ODP	5	35 KOP	SP	CRE	ED,ID	TD			9/14/2055
2020 PO2319345079	ODP	5	35 KOP	SP	S		V			9/15/2055
2020 PO2309245002	ODP	5	35 KOP	SP	CRE	ED,ID,IP	TD			9/16/2055
2020 PO2296544901	ODP	5	35 KOP	DF	CRE	ED,EP,ID,IP	TD			9/17/2055
2020 PO4487332965	KU	4	40 BRN	SP	CRE	ID	BD			9/18/2055
2020 PO4481432884	KU	3	45 BRN	SP	CRE		B			9/19/2055
2020 PO4467532667	KU	5	35 BRN	SP	CCA		V			9/20/2055
2020 PO2079425045	ODP	4	40 XXX	SP	CRE	ID	BD			9/21/2055
2020 PO2079625143	ODP	5	35 XXX	SP	CRE	ID	TD			9/22/2055
2020 PO4551232547	KU	3	45 ACE	SP	CRE	ED,ID	BD			9/23/2055
2020 PO0842336600	ODP	4	40 XXX	SP	CRE	ED,ID,RB	X	PX		9/24/2055
2020 PO0827236634	ODP	3	40 XXX	SP	CRE	ED,ID	TD			9/25/2055
2020 PO0780536729	ODP	2	40 XXX	SP	CRE		V			9/26/2055
2020 PO0797436719	ODP	4	40 XXX	SP	CRE		V			9/27/2055
2020 PO0796536695	ODP	4	40 XXX	SP	CRE		V			9/28/2055
2020 PO0813536661	ODP	2	40 XXX	SP	CRE		V			9/29/2055
2020 PO0875236543	ODP	5	35 XXX	SP	CCA		V			9/30/2055
2020 PO0760336770	ODP	2	40 XXX	SP	CRE	ED,ID	TD			10/1/2055
2020 PO4547432305	KU	3	45 ACE	SP	CRE	ED,ID	BD			10/2/2055
2020 PO3948982389	LGE	4	40 BRN	SP	CRE	ED,ID	TD			10/3/2055
2020 PO3946982384	LGE	4	40 BRN	SP	CRE	ED,ID	BD			10/4/2055
2020 PO0749036794	ODP	2	40 XXX	SP	CRE	ED,ID	TD			10/5/2055
2020 PO4530932301	KU	3	45 ACE	SP	CRE	ED,ID	BD			10/6/2055
2020 PO4541432225	KU	3	45 ACE	SP	CCA		V			10/7/2055
2020 PO3947482393	LGE	4	40 BRN	SP	CRE	ED,ID	BD			10/8/2055
2020 PO3948282405	LGE	4	30 BRN	SP	CRE	ED,ID	TD			10/9/2055
2020 PO3947982406	LGE	4	40 BRN	SP	CRE	ED,ID	TD			10/10/2055
2020 PO3946782410	LGE	4	35 BRN	SP	CCA		V			10/11/2055
2020 PO0695836903	ODP	3	40 XXX	SP	CRE	ED,ID,RB	X	RP1		10/12/2055
2020 PO0737536820	ODP	3	40 XXX	SP	CRE	ED,ID	TD			10/13/2055
2020 PO0725736840	ODP	2	40 XXX	SP	CRE		V			10/14/2055
2020 PO0713236853	ODP	4	40 XXX	SP	CRE		V			10/15/2055
2020 PO0713636876	ODP	4	40 XXX	SP	CRE		V			10/16/2055
2020 PO4499133126	KU	3	45 BRN	SP	CRE	ID	BD			10/17/2055
2020 PO4510933288	KU	3	45 BRN	SP	CRE	ED,ID,IP,SRS	TD			10/18/2055
2020 PO4519133386	KU	3	45 BRN	SP	CCA		V			10/19/2055
2020 PO4522733195	KU	4	40 BRN	SP	CRE	ID,IP	BD			10/20/2055
2020 PO4537433330	KU	3	45 BRN	SP	CRE	ED,ID,SRS	TD			10/21/2055

2020 PO4522633450	KU	3	45 BRN	SP	CRE	ED,ID	TD	10/22/2055
2020 PO3947882427	LGE	4	40 BRN	SP	CRE	ED,ID	BD	10/23/2055
2020 PO3949082424	LGE	4	40 BRN	SP	CRE	ED,ID	TD	10/24/2055
2020 PO4535532146	KU	3	45 ACE	SP	CRE	ED,ID	TD	10/25/2055
2020 PO3950182422	LGE	4	40 BRN	SP	CRE	ED,ID	TD	10/26/2055
2020 PO0672336957a	ODP	6	30 XXX	SP	CRE	ED,ID	TD	10/27/2055
2020 PO0672336957	ODP	2	35 XXX	SP	CRE	ED,ID	TD	10/28/2055
2020 PO0682837407	ODP	4	40 XXX	SP	CRE	ED,ID	TD	10/29/2055
2020 PO3951282419	LGE	4	40 BRN	SP	A	ED,ID	TD	10/30/2055
2020 PO2050725291	ODP	4	40 XXX	SP	CCA		V	10/31/2055
2020 PO2063125290	ODP	4	40 XXX	SP	CRE	ID	TD	11/1/2055
2020 PO2052225116	ODP	5	35 XXX	SP	CRE	ID	TD	11/2/2055
2020 PO1954224334	F	3	40 XXX	SP	P		V	11/3/2055
2020 PO2038522609	ODP	4	40 XXX	SP	CRE	ID	BD	11/4/2055
2020 PO2002123931	ODP	4	40 XXX	SP	CRE	ID	TD	11/5/2055
2020 PO2736637916	F	4	40 SWP	SP	CRE		V	11/6/2055
2020 PO2793738000	ODP	4	40 ESC	SP	P	ED,ID	TD	11/7/2055
2020 PO2760937659	F	4	40 SWP	SP	P		V	11/8/2055
2020 PO2824838331C	ODP	6	30 UNK	SP	CRE	ED,ID,SRC	TD	11/9/2055
2020 PO2824838331B	ODP	4	40 UNK	SP	CRE	ED,ID	TD	11/10/2055
2020 PO2824838331A	ODP	4	40 UNK	SP	CRE	ED,ID	TD	11/11/2055
2020 PO2824838331	ODP	5	35 BRN	SP	CRE	ED,ID,SRC	TD	11/12/2055
2020 PO2851938987	ODP	5	35 BRN	SP	CCA		V	11/13/2055
2020 PO2854139119	ODP	6	30 BRN	SP	CCA		V	11/14/2055
2020 PO2858438837	ODP	4	40 BRN	SP	CCA		V	11/15/2055
2020 PO2879039271	ODP	6	30 KOP	SP	CRE	ED,ID	TD	11/16/2055
2020 PO2881539073	ODP	6	35 BRN	SP	CRE	ED,ID	TD	11/17/2055
2020 PO3952482416	LGE	4	40 BRN	SP	CRE	ED,ID	TD	11/18/2055
2020 PO3953682401	LGE	4	35 BRN	SP	CRE	ED,ID	TD	11/19/2055
2020 PO3953682413	LGE	4	40 BRN	SP	CCA		V	11/20/2055
2020 PO3954782411	LGE	4	40 BRN	SP	CRE	ED,ID	TD	11/21/2055
2020 PO4549638917	KU	4	40 BRO	SP	CCA		V	11/22/2055
2020 PO0640637027	ODP	2	35 ACW	SP	CRE	ED,ID	TD	11/23/2055
2020 PO0662537383	ODP	5	35 ACW	SP	CRE	ED,ID	TD	11/24/2055
2020 PO0621836825	ODP	4	40 KOP	SP	A	ED,ID	TD	11/25/2055
2020 PO4557839012	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	11/26/2055
2020 PO4565638767	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	11/27/2055
2020 PO4636532739	KU	4	40 ACE	SP	CRE	ED,ID	TD	11/28/2055
2020 PO2285244881	F	4	40 KOP	DF	CRE		V	11/29/2055
2020 PO2263644744	F	4	40 KOP	DF	CRE		V	11/30/2055
2020 PO2264644658	ODP	5	35 KOP	DF	CRE	ED,ID,SRC	TD	12/1/2055
2020 PO2281844787	ODP	5	35 KOP	SP	A	ED,ID	TD	12/2/2055
2020 PO4583232991	KU	3	45 ACE	SP	CCA		V	12/3/2055
2020 PO4580732966	KU	3	45 ACE	SP	CCA		V	12/4/2055
2020 PO4590333061	KU	3	45 ACE	SP	CCA		V	12/5/2055
2020 PO3945082476	LGE	2	75 BRN	SP	CRE	ED,ID	BD	12/6/2055
2020 PO3944282457	LGE	2	55 BRN	SP	CRE	ED,ID	BD	12/7/2055

2020 PO3943982449	LGE	1	95 BRN	SP	CRE		V	12/8/2055
2020 PO3943482439	LGE	2	70 BRN	SP	CRE	HH,ID	BD	12/9/2055
2020 PO3942782421	LGE	2	70 BRN	SP	CRE	ED,ID	BD	12/10/2055
2020 PO4537338774	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	12/11/2055
2020 PO4543838799	KU	6	30 BRO	SP	CCA		V	12/12/2055
2020 PO0640636770a	ODP	4	40 XXX	SP	CRE	ED,ID	TD	12/13/2055
2020 PO0640636770	ODP	4	40 XXX	SP	CRE	ED,ID	TD	12/14/2055
2020 PO3942382412	LGE	1	95 BRN	SP	CRE		V	12/15/2055
2020 PO3942082404	LGE	2	70 BRN	SP	CRE	ED,ID	BD	12/16/2055
2020 PO3941282385	LGE	1	70 BRN	DF	CRE	ED,ID	BD	12/17/2055
2020 PO3940782374	LGE	1	95 BRN	SP	CRE		V	12/18/2055
2020 PO4516733391	KU	3	45 BRN	SP	CCA		V	12/19/2055
2020 PO4491133449	KU	3	45 BRN	SP	CCA		V	12/20/2055
2020 PO4467633502	KU	3	40 BRN	SP	CCA		V	12/21/2055
2020 PO4440333564	KU	3	45 BRN	SP	CCA		V	12/22/2055
2020 PO4777532052	KU	3	45 BRN	SP	CRE	ID,IP	BD	12/23/2055
2020 PO4444033675	KU	3	45 BRO	SP	CCA		V	12/24/2055
2020 PO4842432181	KU	5	35 BRO	SP	CRE		V	12/25/2055
2020 PO4814832245	KU	3	45 BRO	SP	CRE		V	12/26/2055
2020 PO4324787938	LGE	4	40 ACW	SP	CRE	ED,EP,HH,ID,MD	BX	PX 12/27/2055
2020 PO4819932332	KU	4	40 BRO	SP	A	ID	BD	12/28/2055
2020 PO4793232368	KU	3	45 BRN	SP	CRE	ID,IP,RB	BX	RP2 12/29/2055
2020 PO4779732501	KU	3	45 BRN	SP	CRE	ED,ID	TD	12/30/2055
2020 PO4786032691	KU	2	45 BRN	SP	CRE	ED,ID	TD	12/31/2055
2020 PO3940482366	LGE	1	70 BRN	SP	CRE	ED,ID	BD	1/1/2056
2020 PO2241144541	F	4	40 KOP	SP	CRE		V	1/2/2056
2020 PO2247644499	ODP	4	40 KOP	DF	CRE	ED,ID	TD	1/3/2056
2020 PO2231544434	F	4	40 KOP	DF	CRE		V	1/4/2056
2020 PO2017124099	ODP	4	40 XXX	SP	CRE	ID	BD	1/5/2056
2020 PO1984524092	ODP	5	35 XXX	SP	CRE	ID	TD	1/6/2056
2020 PO1986524387	ODP	5	35 XXX	SP	CRE	ID	TD	1/7/2056
2020 PO4322987912	LGE	4	40 ACW	SP	P	ED,ID	BD	1/8/2056
2020 PO4318087918	LGE	1	55 ACW	SP	P	ED,ID	BD	1/9/2056
2020 PO4321487914	LGE	4	40 ACW	SP	CRE	ED,ID	BD	1/10/2056
2020 PO4318187916	LGE	4	40 ACW	SP	CRE	ED,ID	TD	1/11/2056
2020 PO4308388098	F	4	40 ACW	SP	P		V	1/12/2056
2020 PO4313988266	LGE	6	20 ACW	SP	CRE	ID	BD	1/13/2056
2020 PO4314088264	LGE	4	45 ACW	SP	CRE	ID	BD	1/14/2056
2020 PO4314188255	LGE	5	45 ACW	SP	CRE	ID	BD	1/15/2056
2020 PO4287787992	LGE	1	30 ACW	SP	CCA		V	1/16/2056
2020 PO4291388072	LGE	1	70 ACW	SP	P		V	1/17/2056
2020 PO0162994061	LGE	4	40 ACW	SP	CCA		V	1/18/2056
2020 PO4305088204	LGE	4	40 ACW	SP	CCA		V	1/19/2056
2020 PO4306788224	LGE	4	40 ACW	SP	CCA		V	1/20/2056
2020 PO1242137542	ODP	6	30 XXX	SP	CRE	ED,ID	TD	1/21/2056
2020 PO1249727753	ODP	4	40 OTH	SP	CCA		V	1/22/2056
2020 PO4812430393	F	3	45 ACE	SP	CRE		V	1/23/2056

2020 PO4499735294	KU	2	50 ACE	SP	CCA		V			1/24/2056
2020 PO4504335343	KU	3	50 ACE	SP	CCA		V			1/25/2056
2020 PO4813630417	F	4	40 ACE	SP	CRE		V			1/26/2056
2020 PO4818330481	F	4	40 ACE	SP	P		V			1/27/2056
2020 PO4825630585	F	3	45 ACE	SP	P		V			1/28/2056
2020 PO1249827495	ODP	3	45 OTH	SP	CCA		V			1/29/2056
2020 PO2613526365	ODP	4	40 BRN	DF	CRE	EP,ID	TX		RR	1/30/2056
2020 PO2667327147	ODP	3	45 BRN	SP	CRE	ID	TD			1/31/2056
2020 PO2688127088	ODP	4	40 BRN	SP	CRE	ID	TD			2/1/2056
2020 PO1226027447	ODP	3	50 OTH	SP	CCA		V			2/2/2056
2020 PO1255326210	ODP	4	45 OTH	SP	CCA		V			2/3/2056
2020 PO3050152097	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD			2/4/2056
2020 PO3027651766	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD			2/5/2056
2020 PO3028852227	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD			2/6/2056
2020 PO3902182259	LGE	4	40 BRN	SP	CCA	ED,ID	BD			2/7/2056
2020 PO3902182270	LGE	3	35 BRN	SP	CCA		V			2/8/2056
2020 PO3902182277	LGE	3	45 BRN	SP	CCA		V			2/9/2056
2020 PO3901782245	LGE	3	45 BRN	SP	CCA		V			2/10/2056
2020 PO3902182234	LGE	4	30 BRN	SP	CCA		V			2/11/2056
2020 PO3901582240	LGE	4	40 BRN	SP	CCA		V			2/12/2056
2020 PO3981283052	LGE	4	30 BRN	SP	CCA	ED,ID	BD			2/13/2056
2020 PO3981483053	LGE	6	25 BRN	SP	CRE		V			2/14/2056
2020 PO3982383051	LGE	4	40 BRN	SP	P	ED,ID	TD			2/15/2056
2020 PO3982683062	LGE	4	40 BRN	SP	CRE	ED,ID	TD			2/16/2056
2020 PO1235326622	ODP	2	50 OTH	SP	CCA		V			2/17/2056
2020 PO1241326505	ODP	4	45 OTH	SP	CRE		V			2/18/2056
2020 PO2620726467	ODP	6	30 BRN	SP	CRE	ED,ID	TD			2/19/2056
2020 PO1344526627	F	4	40 BRN	SP	CRE		V			2/20/2056
2020 PO1337626929	F	4	40 BRN	SP	P		V			2/21/2056
2020 PO3894282584	F	4	40 BRO	SP	P		V			2/22/2056
2020 PO3896182571	F	4	40 BRO	SP	P		V			2/23/2056
2020 PO3897882559	F	4	40 BRO	SP	P		V			2/24/2056
2020 PO3898882552	F	4	40 BRO	SP	P		V			2/25/2056
2020 PO3900082544	F	4	40 BRO	SP	P		V			2/26/2056
2020 PO3901382536	F	4	40 BRO	SP	CCA		V			2/27/2056
2020 PO3885582902	LGE	4	40 BRO	SP	P	ED,ID	TD			2/28/2056
2020 PO3885482917	LGE	4	35 BRO	SP	P	ED,ID	TD			2/29/2056
2020 PO3891482596	F	4	40 BRO	SP	CCA		V			3/1/2056
2020 PO4127035261	KU	5	30 BRO	SP	CRE	ED,HH	X		PX	3/2/2056
2020 PO2895652108	KU	5	45 BRO	SP	CRE	ID,IP	BD			3/3/2056
2020 PO2895252700	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			3/4/2056
2020 PO1315826423	ODP	4	45 BRN	SP	CCA		V			3/5/2056
2020 PO3983183108	LGE	4	30 BRN	SP	CCA		V			3/6/2056
2020 PO3983983103	LGE	3	45 BRN	SP	S		V			3/7/2056
2020 PO1672538989	ODP	5	35 BRN	SP	CRE	ED,ID	TD			3/8/2056
2020 PO1685539128	ODP	5	35 BRN	SP	CCA		V			3/9/2056
2020 PO1696239192	ODP	5	35 BRN	SP	CCA		V			3/10/2056

2020 PO1538537812	ODP	4	40 UNK	SP	CRE	ED,ID	TD	3/11/2056	
2020 PO1520737834	ODP	4	45 BRN	SP	CRE	ED,ID	TD	3/12/2056	
2020 1520737834A	ODP	6	30 BRN	SP	CCA		V	3/13/2056	
2020 PO1519037748	ODP	6	30 BRN	SP	CRE	ED,ID,SRS	TD	3/14/2056	
2020 PO1172537911	F	5	35 SWP	SP	A		V	3/15/2056	
2020 PO2872652340	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	3/16/2056	
2020 PO2833452524	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	3/17/2056	
2020 PO2824952581	KU	3	45 BRO	SP	P	ED	T	3/18/2056	
2020 PO3892982277	LGE	4	35 BRN	SP	CRE	ED,ID	TD	3/19/2056	
2020 PO3896082253	LGE	4	40 BRN	SP	CRE	ED,ID	TD	3/20/2056	
2020 PO3896282257	LGE	4	30 BRN	SP	CRE	ED,ID	TD	3/21/2056	
2020 PO1104837343	ODP	4	45 BRN	SP	CCA		V	3/22/2056	
2020 PO1132437343	ODP	3	50 BRN	SP	CCA		V	3/23/2056	
2020 PO1126837570	ODP	4	45 BRN	SP	CCA		V	3/24/2056	
2020 PO1122037763	ODP	4	45 BRN	SP	CCA		V	3/25/2056	
2020 PO2593726527	ODP	4	40 BRO	SP	CRE	ID	TD	3/26/2056	
2020 PO2577526663	ODP	4	40 BRO	SP	CRE	ID	TD	3/27/2056	
2020 PO2564626773	ODP	4	40 BRO	SP	CRE	ID	TD	3/28/2056	
2020 PO2594627074	ODP	4	40 BRO	SP	CRE	ID	TD	3/29/2056	
2020 PO3984183117	LGE	4	30 BRN	SP	P	ED,ID	TD	3/30/2056	
2020 PO3984583111	LGE	4	40 BRN	SP	CRE	ED,ID	TD	3/31/2056	
2020 PO4847030818	KU	3	45 ACE	SP	CCA		V	4/1/2056	
2020 PO4845630697	KU	5	35 ACE	SP	CCA		V	4/2/2056	
2020 PO4860930856	KU	3	50 ACE	SP	CRE	ED,EP,HH,ID,IP,MD,RB	BX	4/3/2056	RP1
2020 PO4858430911	KU	1	50 ACE	SP	CRE	ED,ID	BD	4/4/2056	
2020 PO4875431063	KU	2	55 ACE	SP	CCA		V	4/5/2056	
2020 PO3894282265	LGE	3	45 BRN	SP	CCA		V	4/6/2056	
2020 PO3892782272	LGE	3	45 BRN	SP	CCA		V	4/7/2056	
2020 PO1034134062	ODP	4	45 KOP	SP	CRE	ED,ID	X	4/8/2056	PX
2020 PO3985483122	LGE	5	30 BRN	SP	S		V	4/9/2056	
2020 PO1148837997	ODP	4	40 XXX	SP	CRE	ED,ID	BD	4/10/2056	
2020 PO1133637993	ODP	4	40 XXX	SP	CRE	ED,ID	TD	4/11/2056	
2020 PO3994783126	LGE	4	40 BRN	SP	CRE	ED,ID	TD	4/12/2056	
2020 PO3160049661	KU	4	40 BRO	SP	CRE	ED	TD	4/13/2056	
2020 PO2421653619	KU	4	45 BRO	SP	CRE		V	4/14/2056	
2020 PO2409253488	KU	4	40 BRO	SP	CRE		V	4/15/2056	
2020 PO1928036143	KU	3	45 BRO	SP	CRE		V	4/16/2056	
2020 PO1896336043	KU	4	45 BRO	SP	CCA		V	4/17/2056	
2020 PO1955136727	KU	6	30 BRO	SP	CRE		V	4/18/2056	
2020 PO0711046695	KU	3	50 BRN	SP	CRE	ED,ID,IP	TD	4/19/2056	
2020 PO0681546886	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD	4/20/2056	
2020 PO0652747068	KU	4	45 BRN	SP	CCA		V	4/21/2056	
2020 PO0608747351	KU	4	40 BRN	SP	CRE	ID	BD	4/22/2056	
2020 PO0450348554	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	4/23/2056	
2020 PO0477048432	KU	4	40 BRN	SP	CRE	ID,IP	BD	4/24/2056	
2020 PO0508048269	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	4/25/2056	
2020 PO0532648159	KU	4	40 BRN	SP	CRE	HH,RB	X	4/26/2056	PX

2020 PO0566148023	KU	4	35 BRN	SP	P	ED	T		4/27/2056
2020 PO0672447335	KU	4	45 BRN	SP	CRE	ED,ID,IP	TD		4/28/2056
2020 PO0692247574	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		4/29/2056
2020 PO0732547661	KU	4	40 BRN	SP	CRE	ED,ID,IP,SRC	TD		4/30/2056
2020 PO4712287971	LGE	4	40 BRO	SP	P	ED,HH,ID,RB	X	RP2	5/1/2056
2020 PO4712787951	LGE	4	40 BRO	SP	P	ED,ID	TD		5/2/2056
2020 PO4712887926	LGE	1	75 BRO	SP	A		V		5/3/2056
2020 PO4813088893	LGE	4	40 BRN	SP	CRE	ED,ID	BD		5/4/2056
2020 PO4811888889	LGE	4	40 BRN	SP	CRE	ED,ID	TD		5/5/2056
2020 PO4813588879	LGE	4	40 BRN	SP	CRE	ED,ID	TD		5/6/2056
2020 PO4521557034	KU	4	45 OTH	SP	CCA	ED,SRS	TD		5/7/2056
2020 PO4813988867	LGE	4	40 BRN	SP	CRE	ED,ID	BD		5/8/2056
2020 PO4813088861	LGE	4	40 BRN	SP	CRE	ED,ID	BD		5/9/2056
2020 PO4565156337	KU	4	45 OTH	SP	CRE	ID	TD		5/10/2056
2020 PO4536155503	KU	4	35 OTH	SP	CRE	ID	BD		5/11/2056
2020 PO4560156406	KU	4	45 OTH	SP	CRE	ED,ID,IP	TD		5/12/2056
2020 PO4541056688	KU	4	45 OTH	SP	CRE	ID	TD		5/13/2056
2020 PO4567755642	KU	4	40 OTH	SP	CCA		V		5/14/2056
2020 PO4591456041	KU	4	40 OTH	SP	CRE	ID	TD		5/15/2056
2020 PO4545556917	KU	6	30 OTH	SP	CCA	ED,SRS	TD		5/16/2056
2020 PO4600655777	KU	4	40 OTH	SP	CRE	ID	TD		5/17/2056
2020 PO4811688855	LGE	4	40 BRN	SP	CRE	ED,HH,ID	VX	PX	5/18/2056
2020 PO4810288850	LGE	4	40 BRN	SP	CRE	ED,ID	BD		5/19/2056
2020 PO4810288883	LGE	4	40 BRN	SP	CRE	ED,ID	TD		5/20/2056
2020 PO4438156881	F	4	45 OTH	SP	P		V		5/21/2056
2020 PO4331856220	F	3	45 OTH	SP	P		V		5/22/2056
2020 PO4353756351	F	3	45 OTH	SP	P		V		5/23/2056
2020 PO4402056650	F	3	45 OTH	SP	P		V		5/24/2056
2020 PO3977082969	LGE	4	30 BRN	SP	S		V		5/25/2056
2020 PO3977482973	LGE	4	40 BRN	SP	CCA		V		5/26/2056
2020 PO3920683293	F	4	40 BRO	SP	P		V		5/27/2056
2020 PO6501337612	LGE	4	35 BRN	SP	P	ED,ID	TD		5/28/2056
2020 PO3976982986	LGE	4	30 BRN	SP	A	ED,ID	TD		5/29/2056
2020 PO3922183293	F	4	40 BRO	SP	P		V		5/30/2056
2020 PO3923783292	F	4	40 BRO	SP	CCA		V		5/31/2056
2020 PO4221941338	KU	6	30 ACE	SP	CCA		V		6/1/2056
2020 PO6501337612-A	LGE	4	35 BRN	SP	CCA		V		6/2/2056
2020 PO3931882604	LGE	4	35 BRN	SP	P	ED,ID	TD		6/3/2056
2020 PO3933082599	LGE	4	35 BRN	SP	P	ED,ID	TD		6/4/2056
2020 PO322782446	LGE	3	45 BRN	SP	CCA		V		6/5/2056
2020 PO3933682596	LGE	3	45 BRN	SP	CCA		V		6/6/2056
2020 PO3934482611	LGE	3	45 BRN	SP	CCA		V		6/7/2056
2020 PO3936082648	LGE	3	60 BRN	SP	CRE	ED,ID	BD		6/8/2056
2020 PO3935582637	LGE	4	45 BRN	SP	CRE	ED,ID	BD		6/9/2056
2020 PO3934982623	LGE	4	40 BRN	SP	CRE	ED,ID	TD		6/10/2056
2020 PO3936982645	LGE	3	50 BRN	SP	CRE	ED,ID	BD		6/11/2056
2020 PO4041742867	KU	6	30 ACE	SP	CRE	ED,ID	BD		6/12/2056

2020 PO8154026798	KU	6	30 BRN	SP	CRE	ID	TD	6/13/2056	
2020 PO8106526957	KU	3	55 BRN	SP	CCA		V	6/14/2056	
2020 PO8157026925	KU	3	50 BRN	SP	CCA		V	6/15/2056	
2020 PO3977382990	F	3	40 BRN	SP	S		V	6/16/2056	
2020 PO7476119374	KU	5	35 XXX	SP	CRE	ID	TD	6/17/2056	
2020 PO7410619491B	KU	6	30 XXX	SP	CRE		V	6/18/2056	
2020 PO7410619491A	KU	6	30 XXX	SP	CRE	ID	TD	6/19/2056	
2020 PO7398119591	KU	5	35 XXX	SP	CRE	ID	TD	6/20/2056	
2020 PO7410619491	KU	4	40 XXX	SP	CRE	ID	TD	6/21/2056	
2020 PO7382819709	KU	5	35 XXX	SP	CRE	HH,ID	TX	RR	6/22/2056
2020 PO7369619685	KU	4	40 XXX	SP	CRE	ID	TD	6/23/2056	
2020 PO7389119823	KU	6	30 XXX	SP	CRE	ID	TD	6/24/2056	
2020 PO7370719775	KU	6	30 XXX	SP	CRE	ID	TD	6/25/2056	
2020 PO7358119880	KU	4	40 XXX	SP	CRE	ID	TD	6/26/2056	
2020 PO7350920027	KU	6	30 XXX	SP	CRE	ID	TD	6/27/2056	
2020 PO7372319956	KU	4	40 XXX	SP	CRE	ID	TD	6/28/2056	
2020 PO7366820057	KU	6	35 XXX	SP	CRE	ID,IP	TX	RR	6/29/2056
2020 PO7394219977	KU	4	40 XXX	SP	CRE	ID	TD	6/30/2056	
2020 PO7356520275	KU	6	35 XXX	SP	CRE	ID	TD	7/1/2056	
2020 PO7348920781	KU	6	30 XXX	SP	CRE	ID	BD	7/2/2056	
2020 PO7343920699	F	5	35 XXX	SP	CCA		V	7/3/2056	
2020 PO7334720874	KU	6	35 XXX	SP	CRE	ID	BD	7/4/2056	
2020 PO7338320675	KU	5	35 XXX	SP	CRE	ID	TD	7/5/2056	
2020 PO7346320502	KU	6	35 XXX	SP	CRE	ID	TD	7/6/2056	
2020 PO7346320502B	KU	6	30 XXX	SP	CRE	ID	BD	7/7/2056	
2020 PO7346320502A	KU	5	35 XXX	SP	CRE	HH,RB	X	PX	7/8/2056
2020 PO6866620401	KU	5	35 XXX	SP	CRE		V	7/9/2056	
2020 PO7012521182	KU	6	30 XXX	SP	CRE		V	7/10/2056	
2020 PO3925483291	F	4	40 BRO	SP	A		V	7/11/2056	
2020 PO3977083009	F	3	40 BRN	SP	S		V	7/12/2056	
2020 PO4065343058	F	3	45 ACE	SP	P		V	7/13/2056	
2020 PO3975783021	LGE	6	25 BRN	SP	A	ED,ID	BD	7/14/2056	
2020 PO3976883022	F	3	45 BRN	SP	S		V	7/15/2056	
2020 PO3281952251	KU	4	40 ACE	SP	CRE	ED,EP,ID,IP	TX	RR	7/16/2056
2020 PO4804814872	F	5	35 ACE	SP	P		V	7/17/2056	
2020 PO4810614934	F	4	40 ACE	SP	P		V	7/18/2056	
2020 PO4822914876	F	4	40 ACE	SP	CRE		V	7/19/2056	
2020 PO4834114828	F	4	40 ACE	SP	P		V	7/20/2056	
2020 PO4843414788	F	4	40 ACE	SP	P		V	7/21/2056	
2020 PO4851214754	KU	4	40 ACE	SP	P		V	7/22/2056	
2020 PO4862814707	F	4	40 ACE	SP	P		V	7/23/2056	
2020 PO4874714656	F	4	40 ACE	SP	CRE		V	7/24/2056	
2020 PO4867614498	F	4	40 ACE	SP	CRE		V	7/25/2056	
2020 PO4861614354	F	4	40 ACE	SP	CRE		V	7/26/2056	
2020 PO4855414217	F	4	40 ACE	SP	P		V	7/27/2056	
2020 PO4849614089	F	4	40 ACE	SP	P		V	7/28/2056	
2020 PO5062310591	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	RP1	7/29/2056

Business Use

2020 PO3873382675	LGE	4	35 BRO	SP	CCA		V		7/30/2056
2020 PO3876082667	LGE	1H	75 BRO	SP	CCA		V		7/31/2056
2020 PO3875382668	LGE	4	35 BRO	SP	CCA		V		8/1/2056
2020 PO1557937839	ODP	4	40 BRN	SP	CRE	ED,ID,SRS	TD		8/2/2056
2020 PO1567237735	ODP	4	40 BRN	SP	CRE	ED,ID	TD		8/3/2056
2020 PO1557937706	ODP	6	30 BRN	SP	CRE		V		8/4/2056
2020 PO1563437776	F	4	40 UNK	SP	P		V		8/5/2056
2020 PO1570637670	ODP	4	40 BRN	SP	CRE	ED,ID	TD		8/6/2056
2020 PO3886082615	LGE	4	30 BRO	SP	CCA	ED,ID,IP	X	RP1	8/7/2056
2020 PO3885482616	LGE	4	25 BRO	SP	CCA	ED,ID	X	RP1	8/8/2056
2020 PO3882682628	LGE	4	45 BRO	SP	P	ED,ID,IP	TD		8/9/2056
2020 PO3881582641	LGE	4	40 BRO	SP	CRE	ED,ID	TD		8/10/2056
2020 PO3881082635	LGE	4	35 BRO	SP	P	ED,ID	TD		8/11/2056
2020 PO3882782636	LGE	4	45 BRO	SP	CRE	ED,ID	TD		8/12/2056
2020 PO3891082628	LGE	4	35 BRO	SP	P	ED,ID	TD		8/13/2056
2020 PO3893182589	LGE	4	45 BRO	SP	CRE	ED,ID	BD		8/14/2056
2020 PO3890382602	LGE	4	45 BRO	SP	A	ED,ID	TD		8/15/2056
2020 PO2161732637	KU	4	40 BRN	SP	CRE		V		8/16/2056
2020 PO2149232603	KU	4	40 BRN	SP	CRE		V		8/17/2056
2020 PO3208539356	KU	4	40 BRN	SP	CRE	ID	BD		8/18/2056
2020 PO3929982490-A	LGE	3	45 BRN	SP	CCA		V		8/19/2056
2020 PO0691718377	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD		8/20/2056
2020 PO3993282967	F	4	40 BRN	SP	CRE		V		8/21/2056
2020 PO3993782956	F	4	40 BRN	SP	S		V		8/22/2056
2020 PO4984011419	F	4	40 ACE	SP	P		V		8/23/2056
2020 PO4971011472	F	4	40 ACE	SP	CRE	ED,ID	V		8/24/2056
2020 PO4959411520	F	3	45 ACE	SP	P		V		8/25/2056
2020 PO4946311574	F	3	40 ACE	SP	P		V		8/26/2056
2020 PO4633688039	LGE	5	25 ACE	SP	CRE	ED,ID	TD		8/27/2056
2020 PO4633888053	LGE	3	45 ACE	SP	CRE	ED,ID	BD		8/28/2056
2020 PO4633788052	LGE	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	PX	8/29/2056
2020 PO4634588071	LGE	4	40 ACE	SP	CRE		B		8/30/2056
2020 PO4634288062	LGE	4	45 ACE	SP	CRE		B		8/31/2056
2020 PO4635488092	LGE	4	40 ACE	SP	CRE		B		9/1/2056
2020 PO4635388090	LGE	4	40 ACE	SP	CRE	ED,HH,ID	BX	RP2	9/2/2056
2020 PO4633288039	LGE	3	45 ACE	SP	CRE	ED,ID	TD		9/3/2056
2020 PO5000311361	F	4	40 ACE	SP	P		V		9/4/2056
2020 PO4987511791	F	4	40 ACE	SP	P		V		9/5/2056
2020 PO5000311732	F	4	40 ACE	SP	P		V		9/6/2056
2020 PO5014111669	F	4	40 ACE	SP	P		V		9/7/2056
2020 PO5020311639	F	4	40 ACE	SP	P		V		9/8/2056
2020 PO3993982944	F	4	40 BRN	SP	S		V		9/9/2056
2020 PO4731314501	F	5	35 ACE	SP	CRE		V		9/10/2056
2020 PO3994082933	F	4	40 BRN	SP	S		V		9/11/2056
2020 0680818125A	KU	6	30 OTH	SP	CCA		V		9/12/2056
2020 0734218787A	KU	3	40 CPT	SP	A	ID	TD		9/13/2056
2020 PO3994282921	F	4	40 BRN	SP	CRE	ED,ID,RB	VX	RP2	9/14/2056

2020 PO3180539129	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/15/2056
2020 0773719473A	KU	6	30 BRN	SP	CCA		V	9/16/2056
2020 PO3150238884	KU	4	40 BRN	SP	CRE	ED,ID,IP,SR	TD	9/17/2056
2020 0830520467A	KU	6	30 BRN	SP	CCA		V	9/18/2056
2020 PO0746412904	KU	6	30 BRN	SP	CCA		V	9/19/2056
2020 PO0721018562	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD	9/20/2056
2020 PO0670617612	KU	6	30 OTH	SP	CRE		V	9/21/2056
2020 PO0738712736	KU	6	30 KOP	SP	CRE	ID	TD	9/22/2056
2020 PO0749513141	KU	6	30 OTH	SP	CRE	ED,ID,SRS	TD	9/23/2056
2020 PO0565517042	KU	5	35 OTH	SP	CRE	ID	TD	9/24/2056
2020 PO0808920105	KU	5	35 UNK	SP	CRE	ID	TD	9/25/2056
2020 PO0796419696	KU	3	45 OTH	SP	P		V	9/26/2056
2020 PO0638417586	KU	5	35 OTH	SP	CRE	ID	TD	9/27/2056
2020 PO0840421006	KU	5	35 OTH	SP	CRE	ID	TD	9/28/2056
2020 PO0746619234	KU	5	35 ESC	SP	CRE	ED,ID,SRS	TD	9/29/2056
2020 PO4957810364	F	4	40 ACE	SP	P		V	9/30/2056
2020 PO4961210288	F	5	35 ACE	SP	P		V	10/1/2056
2020 PO4943310355	F	5	35 ACE	SP	P		V	10/2/2056
2020 PO4739189096	LGE	3	45 BRO	SP	CCA		V	10/3/2056
2020 PO4742488884	LGE	4	35 BRN	SP	CRE	ED,ID	TD	10/4/2056
2020 PO4697112378	KU	4	40 BRO	SP	CRE	ED,ID	TD	10/5/2056
2020 PO4709912325	KU	4	40 BRO	SP	CRE	ID	BD	10/6/2056
2020 PO4961511176	F	4	40 ACE	SP	P		V	10/7/2056
2020 PO4053782960	LGE	4	40 BRO	SP	P	ED,ID	TD	10/8/2056
2020 PO7678241810	LGE	4	30 BRO	SP	CRE	ED,ID	BD	10/9/2056
2020 PO4859911670	KU	4	45 BRO	SP	CRE	ED,ID	TD	10/10/2056
2020 PO4852911695	KU	4	40 BRO	SP	CRE	ID	BD	10/11/2056
2020 PO4840911747	KU	4	40 BRO	SP	CRE	ID	BD	10/12/2056
2020 PO4827611803	KU	4	40 BRO	SP	CRE	ID	BD	10/13/2056
2020 PO4813911862	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	10/14/2056
2020 PO4799611921	KU	4	40 BRO	SP	CRE	ID	BD	10/15/2056
2020 PO4785011983	KU	4	40 BRO	SP	CRE	ID	BD	10/16/2056
2020 PO4951710941	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX 10/17/2056
2020 PO4956611060	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,MD,RB	BX	PX 10/18/2056
2020 PO4943210740	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	RP1 10/19/2056
2020 PO4508501439	KU	4	40 BRN	SP	CRE	ED,ID	TD	10/20/2056
2020 PO4497101550	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	10/21/2056
2020 PO4048382829	LGE	4	40 BRO	SP	CRE	ED,ID	TD	10/22/2056
2020 PO4892911625	KU	5	35 ACE	SP	CRE		V	10/23/2056
2020 PO4856711234	KU	6	30 ACE	SP	CCA		V	10/24/2056
2020 PO4754488703	LGE	4	40 BRN	SP	P	ED,ID,IP	TD	10/25/2056
2020 PO4729189166	LGE	4	35 BRO	SP	CRE	ED,ID	BD	10/26/2056
2020 PO4756088677	LGE	3	45 BRN	SP	S		V	10/27/2056
2020 PO4727589171	F	3	45 BRO	SP	CCA		V	10/28/2056
2020 PO4728689177	F	3	45 BRO	SP	CCA		V	10/29/2056
2020 PO4729889185	F	3	45 BRO	SP	CCA		V	10/30/2056
2020 PO4731189194	F	3	45 BRO	SP	CCA		V	10/31/2056

2020 PO4732589203	F	3	45 BRO	SP	CCA		V	11/1/2056
2020 PO4755588687	LGE	3	45 BRN	SP	CCA		V	11/2/2056
2020 PO4755088694	LGE	3	45 BRN	SP	CCA		V	11/3/2056
2020 PO4755188729	LGE	4	40 BRN	SP	CRE	ED,ID	TD	11/4/2056
2020 PO4760612088	KU	3	50 BRO	SP	CRE	ID	BD	11/5/2056
2020 PO4746812148	KU	4	45 BRO	SP	CRE	ID,IP	BD	11/6/2056
2020 PO4734912208	KU	4	45 BRO	SP	P	ED,ID	TD	11/7/2056
2020 PO4721812269	KU	4	45 BRO	SP	CRE	EP,ID,IP	BD	11/8/2056
2020 PO4676812423	KU	5	35 BRO	SP	CRE	ID	BD	11/9/2056
2020 PO4525900958	KU	4	40 BRN	SP	CCA		V	11/10/2056
2020 PO4527001036	KU	4	40 XXX	SP	CRE	ED,ID	TD	11/11/2056
2020 PO4754388724	LGE	4	45 BRN	DF	CRE	ED,ID	TD	11/12/2056
2020 PO4866111403	KU	5	35 ACE	SP	CCA		V	11/13/2056
2020 PO4891911777	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	11/14/2056
2020 PO4879911607	KU	5	35 ACE	SP	CRE	ED,ID	TD	11/15/2056
2020 PO4722089116	LGE	4	35 BRO	SP	CRE		B	11/16/2056
2020 PO4722889110	LGE	4	30 BRO	SP	CRE		B	11/17/2056
2020 PO4721189132	F	3	45 BRO	SP	CCA		V	11/18/2056
2020 PO4721389134	F	3	45 BRO	SP	CCA		V	11/19/2056
2020 PO4721889120	F	4	35 BRO	SP	CRE		V	11/20/2056
2020 PO4315604084	LGE	4	35 BRO	SP	CCA		V	11/21/2056
2020 PO4722489134	F	4	35 BRO	SP	CRE		V	11/22/2056
2020 PO4722489140	F	3	45 BRO	SP	CCA		V	11/23/2056
2020 PO4723589143	LGE	4	35 BRO	SP	CRE		B	11/24/2056
2020 PO4723789148	F	3	45 BRO	SP	CCA		V	11/25/2056
2020 PO4726289163	F	3	45 BRO	SP	CCA		V	11/26/2056
2020 PO4724989155	F	3	45 BRO	SP	CCA		V	11/27/2056
2020 PO4725089149	LGE	4	35 BRO	SP	CRE		B	11/28/2056
2020 PO4725889137	LGE	4	35 BRO	SP	CRE		B	11/29/2056
2020 PO4538001175	KU	4	40 XXX	SP	CRE	ED,ID	TD	11/30/2056
2020 PO4552201048	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	12/1/2056
2020 PO4753488719	LGE	4	40 BRN	SP	A	ED,ID	TD	12/2/2056
2020 PO4877611592	KU	4	40 ACE	SP	CCA		V	12/3/2056
2020 PO4887111527	KU	4	40 ACE	SP	CCA		V	12/4/2056
2020 PO4752688732	LGE	4	40 BRN	SP	CRE	ED,ID	TD	12/5/2056
2020 PO4566800922	KU	4	40 XXX	SP	CRE	ED,ID	TD	12/6/2056
2020 PO4751988743	LGE	4	40 BRN	SP	CRE	ED,ID	TD	12/7/2056
2020 PO4902111939	KU	5	35 ACE	SP	CRE	ED,ID	TD	12/8/2056
2020 PO4905711810	KU	5	35 ACE	SP	CCA		V	12/9/2056
2020 PO4915812229	KU	6	30 ACE	SP	CCA		V	12/10/2056
2020 PO4750888749	LGE	4	30 BRN	SP	A	ED,ID	BD	12/11/2056
2020 PO4750588756	LGE	4	30 BRN	SP	CRE	ED,ID	TD	12/12/2056
2020 PO4977613568	KU	5	35 ACE	SP	P	ED	T	12/13/2056
2020 PO4552100537	KU	6	30 XXX	SP	CRE	ED,ID	TD	12/14/2056
2020 PO4546000709	KU	4	40 XXX	SP	CRE	ED,ID	TD	12/15/2056
2020 PO4544600786	KU	5	35 XXX	SP	CRE	ED,ID	TD	12/16/2056
2020 PO4749788778	LGE	4	40 BRN	SP	CRE	ED,ID	BD	12/17/2056

2020 PO4984713785	KU	5	35 ACE	SP	P	ED	T	12/18/2056
2020 PO4989713951	KU	5	35 ACE	SP	CRE	ED,ID	TD	12/19/2056
2020 PO4988014016	KU	5	35 ACE	SP	P	ED	T	12/20/2056
2020 PO5008511539	KU	2	50 ACE	SP	CCA		V	12/21/2056
2020 PO4749688799	LGE	4	40 BRN	SP	P	ED,ID	TD	12/22/2056
2020 PO4750388804	LGE	3	45 BRN	SP	S		V	12/23/2056
2020 PO4748788793	F	3	45 BRN	SP	A		V	12/24/2056
2020 PO4748088805	LGE	4	40 BRN	SP	CRE	ED,ID	BD	12/25/2056
2020 PO4726489126	F	3	45 BRO	SP	CRE		V	12/26/2056
2020 Tel	F	3	45 BRO	SP	CRE		V	12/27/2056
2020 PO4726689123	F	3	45 BRO	SP	CRE		V	12/28/2056
2020 PO4747088822	LGE	4	40 BRN	SP	CRE	ED,ID	TD	12/29/2056
2020 PO4045982855	LGE	4	40 BRO	SP	P	ED,ID	TD	12/30/2056
2020 PO4733589096	LGE	4	35 BRO	SP	CRE		V	12/31/2056
2020 PO4727589113	F	3	45 BRO	SP	CRE		V	1/1/2057
2020 PO4727289112	LGE	4	35 BRO	SP	CRE		B	1/2/2057
2020 PO4728389109	LGE	4	35 BRO	SP	CRE		B	1/3/2057
2020 PO4727389102	LGE	4	40 BRO	SP	CRE		B	1/4/2057
2020 PO4727389088	LGE	4	40 BRO	SP	A		B	1/5/2057
2020 PO4747588814	LGE	3	45 BRN	SP	S		V	1/6/2057
2020 PO4736289102	LGE	1	55 BRO	SP	CCA		V	1/7/2057
2020 PO4434203864	LGE	1	45 BRO	SP	CRE	ED,ID	BD	1/8/2057
2020 PO5259145098	KU	3	45 ACE	SP	CCA		V	1/9/2057
2020 PO5234044854	KU	3	45 ACE	SP	CCA		V	1/10/2057
2020 PO5209244610	KU	3	45 ACE	SP	CCA		V	1/11/2057
2020 PO5184544359	KU	3	45 ACE	SP	CCA		V	1/12/2057
2020 PO5016538149	KU	4	45 ACE	SP	CRE	ED,ID,IP	TD	1/13/2057
2020 PO5029638138	KU	4	45 ACE	SP	CRE	ED,ID	TD	1/14/2057
2020 PO5043138129	KU	4	45 ACE	SP	CRE	ED,ID,IP	TD	1/15/2057
2020 PO4176833517	KU	4	45 ACE	SP	CCA		V	1/16/2057
2020 PO4124733725	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	1/17/2057
2020 PO4112733461	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	1/18/2057
2020 PO4123433520	KU	4	40 ACE	SP	CCA		V	1/19/2057
2020 PO4966140735	F	3	45 ACE	SP	CRE		V	1/20/2057
2020 PO5005540888	F	4	40 ACE	SP	CRE		V	1/21/2057
2020 PO5195740750	KU	3	35 ACE	ST	P		V	1/22/2057
2020 PO5150040728	F	4	40 ACE	SP	CRE		V	1/23/2057
2020 PO5149340640	F	4	40 ACE	SP	CRE		V	1/24/2057
2020 PO5148340526	F	4	40 ACE	SP	CRE		V	1/25/2057
2020 PO4141633325a	KU	3	45 ACE	SP	CRE	ED,ID	TD	1/26/2057
2020 PO5090340824	F	4	40 ACE	SP	CRE		V	1/27/2057
2020 PO5069440847	F	4	40 ACE	SP	CRE		V	1/28/2057
2020 PO5047440872	F	4	40 ACE	SP	CRE		V	1/29/2057
2020 PO5120140795	F	4	40 ACE	SP	CRE		V	1/30/2057
2020 PO4146533905	KU	4	40 ACE	SP	CCA		V	1/31/2057
2020 PO5113740543	F	4	40 ACE	SP	CRE		V	2/1/2057
2020 PO5116340764	F	4	40 ACE	SP	CRE		V	2/2/2057

2020 PO4141633325	KU	4	40 ACE	SP	CRE	ED,ID	TD	2/3/2057
2020 PO4149033140	KU	4	40 ACE	SP	CRE	ED,ID	TD	2/4/2057
2020 PO5136240464	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	2/5/2057
2020 PO4340641892	KU	4	40 ACE	SP	CRE		V	2/6/2057
2020 PO5130140380	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	2/7/2057
2020 PO5134140566	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	2/8/2057
2020 PO4111032700	KU	6	30 ACE	SP	CCA	ED,ID	TD	2/9/2057
2020 PO4110932827	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	2/10/2057
2020 PO4080832661	KU	3	45 ACE	SP	CCA		V	2/11/2057
2020 PO5135340628	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	2/12/2057
2020 PO5135640781	KU	4	40 ACE	SP	CRE		V	2/13/2057
2020 PO5155840760	F	4	40 ACE	SP	CRE		V	2/14/2057
2020 PO4074132976	KU	5	35 ACE	SP	CCA	ED,ID	TD	2/15/2057
2020 PO4076032878	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	2/16/2057
2020 PO5169840742	F	4	40 ACE	SP	CRE		V	2/17/2057
2020 PO4078532553	KU	6	30 ACE	SP	CRE		V	2/18/2057
2020 PO5153640833	KU	6	30 ACE	SP	CCA		V	2/19/2057
2020 PO4068232808	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	2/20/2057
2020 PO4094832856	KU	5	35 ACE	SP	CRE	ED,ID	TD	2/21/2057
2020 PO4094632742	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	2/22/2057
2020 PO4062432649	KU	6	30 ACE	SP	CCA	ED,ID	BD	2/23/2057
2020 PO4064332572	KU	4	40 ACE	SP	CRE	ED,ID	TD	2/24/2057
2020 PO4057332372	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	2/25/2057
2020 PO4044632472	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	2/26/2057
2020 PO4983941108	F	4	40 ACE	SP	CRE		V	2/27/2057
2020 PO4988541085	KU	5	35 ACE	SP	CCA	ED	TD	2/28/2057
2020 PO4974241190	F	4	40 ACE	SP	CRE		V	3/1/2057
2020 PO4963641532	F	4	40 ACE	SP	CRE		V	3/2/2057
2020 PO4993741391	F	4	40 ACE	SP	CRE		V	3/3/2057
2020 PO5010540986	F	3	40 ACE	SP	CRE		V	3/4/2057
2020 PO5028140908	KU	4	45 ACE	SP	CRE	ED,ID,IP	TD	3/5/2057
2020 PO4058833125	KU	4	40 ACE	SP	CRE	ED,EP,ID,IP	TX	RR 3/6/2057
2020 PO4005833370	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	3/7/2057
2020 PO4039433398	KU	3	45 ACE	SP	CCA		V	3/8/2057
2020 PO5159744112	KU	3	45 ACE	SP	CCA		V	3/9/2057
2020 PO5144543900	KU	3	45 ACE	SP	CCA		V	3/10/2057
2020 PO5131443827	KU	3	45 ACE	SP	CCA		V	3/11/2057
2020 PO4056782996	LGE	3	45 BRO	SP	CCA		V	3/12/2057
2020 PO3906410846	KU	3	45 BRO	SP	CRE		V	3/13/2057
2020 PO3909510700	KU	3	45 BRO	SP	CRE		V	3/14/2057
2020 PO3913010540	KU	3	45 BRO	SP	CRE		V	3/15/2057
2020 PO3916310382	KU	3	45 BRO	SP	CRE		V	3/16/2057
2020 PO4414312461	KU	3	45 BRO	SP	CCA		V	3/17/2057
2020 PO4416012442	KU	2	50 BRO	SP	CRE	ID,IP	BD	3/18/2057
2020 PO4451412779	KU	3	45 BRO	SP	CRE		V	3/19/2057
2020 PO4437812627	KU	3	45 BRO	SP	CCA		V	3/20/2057
2020 PO4454012757	KU	3	45 BRO	SP	CCA		V	3/21/2057

2020 PO4460101305	KU	4	40 BRN	SP	CRE	ID	BD	3/22/2057
2020 PO5214510251	F	4	40 ACE	SP	P		V	3/23/2057
2020 PO5211110117	F	4	40 ACE	SP	P		V	3/24/2057
2020 PO5205609956	F	4	40 ACE	SP	P		V	3/25/2057
2020 PO5200109820	F	4	40 ACE	SP	P		V	3/26/2057
2020 PO5197109740	F	4	40 ACE	SP	P		V	3/27/2057
2020 PO5191509590	F	4	40 ACE	SP	P		V	3/28/2057
2020 PO5186309447	F	4	40 ACE	SP	P		V	3/29/2057
2020 PO5179909267	F	4	40 ACE	SP	CRE		V	3/30/2057
2020 PO5173609095	F	4	40 ACE	SP	CRE		V	3/31/2057
2020 PO5162308793	F	3	40 ACE	SP	P		V	4/1/2057
2020 PO5158808703	F	3	45 ACE	SP	P		V	4/2/2057
2020 PO5154209583	F	4	40 ACE	SP	P		V	4/3/2057
2020 PO5153209478	F	4	40 ACE	SP	P		V	4/4/2057
2020 PO4464101355	KU	4	40 BRN	SP	CRE	ED,ID	TD	4/5/2057
2020 PO4494301182	KU	4	40 BRN	SP	CRE	ED,ID	TD	4/6/2057
2020 PO4501101302	KU	4	40 BRN	SP	CRE	ED,ID	TD	4/7/2057
2020 PO4503701349	KU	4	40 BRN	SP	CRE	ID	BD	4/8/2057
2020 PO4470301435	KU	4	40 BRN	SP	CRE	ED,ID	TD	4/9/2057
2020 PO4477601531	KU	4	40 BRN	SP	CRE	ID	BD	4/10/2057
2020 PO4364902154	KU	6	30 BRN	SP	CRE	ED,ID	TD	4/11/2057
2020 PO4369902198	KU	4	40 BRN	SP	P	ID	BD	4/12/2057
2020 PO2016930176	ODP	5	35 XXX	SP	CRE	ID	TD	4/13/2057
2020 PO2015729938	ODP	4	40 XXX	SP	CCA		V	4/14/2057
2020 PO2015429660	ODP	4	40 XXX	SP	CRE	ID	TD	4/15/2057
2020 PO2024329404	ODP	5	35 XXX	SP	CRE	ID	TD	4/16/2057
2020 PO2080729066	ODP	4	40 XXX	SP	CRE	RB	X	4/17/2057
2020 PO9370588096	KU	4	40 BRN	SP	CCA		V	4/18/2057
2020 PO9367987798	KU	4	40 BRN	SP	CCA		V	4/19/2057
2020 PO9393087599	KU	4	40 XXX	SP	CRE	ED,ID	TD	4/20/2057
2020 PO9386987233	KU	4	40 XXX	SP	CRE	ED,ID	TD	4/21/2057
2020 PO9644893448	KU	3	45 BRN	SP	CRE		V	4/22/2057
2020 PO9287486419	KU	5	35 XXX	SP	CRE	ED,ID	TD	4/23/2057
2020 PO9676593724	KU	6	30 BRN	SP	CRE	ED,ID	BD	4/24/2057
2020 PO9651993448	KU	3	50 BRN	SP	CCA		V	4/25/2057
2020 PO9680793448	KU	3	50 BRN	SP	CCA		V	4/26/2057
2020 PO9673493651	KU	4	40 XXX	SP	CRE	ID	BD	4/27/2057
2020 PO9691693448	KU	3	50 XXX	SP	CCA	ED,ID	TD	4/28/2057
2020 PO9688893624	KU	5	35 BRN	SP	CRE		V	4/29/2057
2020 PO9690493495	KU	6	30 BRN	SP	CRE		V	4/30/2057
2020 PO9439485562	KU	3	45 BRN	SP	S		V	5/1/2057
2020 PO9454685865	KU	3	45 BRN	SP	S		V	5/2/2057
2020 PO9472286121	KU	3	45 BRN	SP	S		V	5/3/2057
2020 PO9487086375	KU	3	45 BRN	SP	S		V	5/4/2057
2020 PO9501886627	KU	3	45 BRN	SP	S		V	5/5/2057
2020 PO9517086899	KU	3	45 BRN	SP	S		V	5/6/2057
2020 PO9525887168	KU	3	45 BRN	SP	S		V	5/7/2057

Business Use

2020 PO9527787456	KU	3	45 BRN	SP	S		V			5/8/2057
2020 PO9526287716	KU	3	45 BRN	SP	S		V			5/9/2057
2020 PO9524288020	KU	3	45 BRN	SP	S		V			5/10/2057
2020 PO9524888318	KU	3	45 BRN	SP	S		V			5/11/2057
2020 PO9524288625	KU	3	45 BRN	SP	S		V			5/12/2057
2020 PO9523488759	KU	3	45 BRN	SP	S		V			5/13/2057
2020 PO9523488909	KU	3	45 BRN	SP	S		V			5/14/2057
2020 PO9522789179	KU	3	45 BRN	SP	S		V			5/15/2057
2020 9525289474	KU	3	45 BRN	SP	S		V			5/16/2057
2020 PO9532889757	KU	3	45 BRN	SP	S		V			5/17/2057
2020 PO9547390088	KU	3	45 BRN	SP	S		V			5/18/2057
2020 PO5781737383	F	5	30 BRO	SP	A		V			5/19/2057
2020 PO5678455208	KU	4	40 ACE	SP	CRE	ED,ID			TD	5/20/2057
2020 PO9386994400	KU	4	40 ACW	SP	CRE	ED,ID			TD	5/21/2057
2020 PO5697355166	KU	4	45 ACE	SP	CRE	ED,ID,IP			BD	5/22/2057
2020 PO5717955123	KU	4	40 ACE	SP	CRE	ED,ID,IP			BD	5/23/2057
2020 PO9364694347	KU	4	40 ACW	SP	CRE	ED,ID		RR	TX	5/24/2057
2020 PO5736655093	KU	4	40 ACE	SP	CRE	ED,ID			TD	5/25/2057
2020 PO9348494308	KU	4	40 ACW	SP	CRE	ED,ID,MD,RB			TX	5/26/2057
2020 PO9178492518	KU	6	30 XXX	SP	CRE	ED,ID			TD	5/27/2057
2020 PO9145492480	KU	4	40 XXX	SP	CRE	ED,ID			TD	5/28/2057
2020 PO9336594280	KU	4	40 ACW	SP	CRE	ED,ID			TD	5/29/2057
2020 PO9323294248	KU	3	40 ACW	SP	S		V			5/30/2057
2020 PO5690855566	KU	4	40 ACE	SP	CRE	ED,ID,IP			BD	5/31/2057
2020 PO5740855225	KU	4	40 ACE	SP	CRE	ED,ID			BD	6/1/2057
2020 PO5739655389	KU	4	40 ACE	SP	CRE	ED,EP,ID,IP			TD	6/2/2057
2020 PO5718755452	KU	4	40 ACE	SP	CRE	ED,ID			BD	6/3/2057
2020 PO9130292588	KU	3	45 BRN	SP	CCA		V			6/4/2057
2020 PO9131992469	KU	3	45 BRN	SP	CCA		V			6/5/2057
2020 PO9077592360	KU	4	40 XXX	SP	CRE	ED,EP,ID			TD	6/6/2057
2020 PO9108092412	KU	4	40 XXX	SP	CRE	ED,ID			TD	6/7/2057
2020 PO9306194261	F	6	30 ACW	SP	CRE		V			6/8/2057
2020 PO9294394177	KU	5	50 ACW	SP	S	ED,ID			TD	6/9/2057
2020 PO5585945039	KU	6	30 ACW	ST	CCA		V			6/10/2057
2020 PO5593245353A	KU	6	30 ACW	ST	S		V			6/11/2057
2020 PO3356852755	KU	4	40 ACE	SP	CRE	ED,ID			TD	6/12/2057
2020 PO3313052446	KU	4	40 ACE	SP	CRE	ED,ID			BD	6/13/2057
2020 PO6014139341	KU	3	45 BRN	SP	CCA		V			6/14/2057
2020 PO5996239541	KU	3	45 BRN	SP	CCA		V			6/15/2057
2020 PO6040339079	KU	3	45 BRN	SP	S		V			6/16/2057
2020 PO6067938802	KU	3	45 BRN	SP	CCA	ED,ID,IP			BD	6/17/2057
2020 PO6055438927	KU	3	45 BRN	SP	S		V			6/18/2057
2020 PO5603644733	F	3	35 ACW	SP	S		V			6/19/2057
2020 PO5581044887	F	3	45 ACW	SP	S		V			6/20/2057
2020 PO5611944826	KU	3	45 ACW	SP	S		V			6/21/2057
2020 PO5588544970	F	4	40 ACW	SP	S		V			6/22/2057
2020 PO5594745037	F	4	40 ACW	SP	P		V			6/23/2057

2020 PO5600045098	F	4	40 ACW	SP	P		V		6/24/2057
2020 PO9214438298	ODP	4	40 XXX	SP	CRE	ED,ID	TD		6/25/2057
2020 PO1480833142	ODP	4	45 XXX	SP	CCA	ED	T		6/26/2057
2020 PO1474233257	ODP	4	45 XXX	SP	CCA	ED	T		6/27/2057
2020 PO1467633372	ODP	4	45 XXX	SP	CCA	ID	T		6/28/2057
2020 PO1469633448	ODP	6	30 XXX	SP	CRE	ID,RB	TX	RR	6/29/2057
2020 PO9223237844	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD		6/30/2057
2020 PO1468033545	ODP	4	40 XXX	SP	CCA	ED	T		7/1/2057
2020 PO1483733630	ODP	4	40 XXX	SP	CRE	ID	TD		7/2/2057
2020 PO1504533629	ODP	4	40 XXX	SP	CRE	ID	BD		7/3/2057
2020 PO1504133573	F	4	40 XXX	SP	CRE		V		7/4/2057
2020 PO1531633511	ODP	6	30 XXX	SP	CRE	ID	TD		7/5/2057
2020 PO1527533601	ODP	4	40 XXX	SP	CRE	ID	TD		7/6/2057
2020 PO1506026594	ODP	4	45 XXX	SP	CCA	ED	T		7/7/2057
2020 PO9225537661	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TX	RR	7/8/2057
2020 PO9236037608	ODP	5	35 XXX	SP	CRE	ED,ID	TD		7/9/2057
2020 PO9263637471	ODP	5	30 XXX	SP	CRE	RB	V		7/10/2057
2020 PO9231037331	ODP	4	50 XXX	SP	CRE	ED,ID,IP	TD		7/11/2057
2020 PO5546645812	F	4	45 ACW	SP	CRE	HH,ID	VX	RP1	7/12/2057
2020 PO5733744867	KU	4	40 ACE	SP	CRE	ED,ID	BD		7/13/2057
2020 PO5752244906	KU	2	45 ACE	SP	CRE	ED,ID	BD		7/14/2057
2020 PO5762644841	KU	6	30 ACE	SP	CRE	ED,ID	BD		7/15/2057
2020 PO5698345567	KU	6	30 ACE	SP	CCA		V		7/16/2057
2020 PO4884519787	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		7/17/2057
2020 PO4861220335	KU	4	40 BRO	SP	A	ED,ID	TD		7/18/2057
2020 PO4851920540	C	4	40 BRO	SP	A		V		7/19/2057
2020 PO4826121475	KU	3	45 BRO	SP	CCA		V		7/20/2057
2020 PO4836521470	KU	4	40 BRO	SP	A	ED,ID	TD		7/21/2057
2020 PO4836021264	KU	4	45 BRO	SP	CCA		V		7/22/2057
2020 PO4835821082	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD		7/23/2057
2020 PO5674245971	KU	6	35 ACE	SP	CRE	ED,ID	BD		7/24/2057
2020 PO5682545638	KU	3	50 ACE	SP	CCA		V		7/25/2057
2020 PO5702245643a	KU	4	40 ACE	SP	CRE	ED,ID	BD		7/26/2057
2020 PO5702245643	KU	4	45 ACE	SP	CRE	ED,ID	BD		7/27/2057
2020 PO5733645456a	KU	6	30 ACE	SP	CCA		V		7/28/2057
2020 PO5733645456	KU	5	35 ACE	SP	CCA		V		7/29/2057
2020 PO5723245651	KU	3	45 ACE	SP	CRE	ED,ID	BD		7/30/2057
2020 PO1282433146	ODP	4	45 XXX	SP	CRE	ID	BD		7/31/2057
2020 PO1272032859	ODP	5	35 XXX	SP	CRE	ID	TD		8/1/2057
2020 PO1272032859A	ODP	4	40 XXX	SP	CRE	ED,ID	TD		8/2/2057
2020 PO1271732426	ODP	4	45 XXX	SP	CRE	ID	BD		8/3/2057
2020 PO1277232573	ODP	4	45 XXX	SP	CRE	ID	BD		8/4/2057
2020 PO1275332829	ODP	3	40 XXX	SP	CRE	ED,ID	TX	RR	8/5/2057
2020 PO1280532709	ODP	4	45 XXX	SP	CRE	ID	TD		8/6/2057
2020 PO1307132697	ODP	6	30 XXX	SP	CRE	ID	TD		8/7/2057
2020 PO1301632816	F	5	35 XXX	SP	A		V		8/8/2057
2020 PO1299032871	ODP	5	30 XXX	SP	CRE	ID	TD		8/9/2057

2020 PO1319632909	ODP	4	40 XXX	SP	CRE	ID	TD	8/10/2057
2020 PO1306832987	ODP	3	45 XXX	SP	CRE	ID	TD	8/11/2057
2020 PO8640045813	ODP	5	45 XXX	SP	CRE		V	8/12/2057
2020 PO8678547015	ODP	6	30 XXX	SP	CRE		V	8/13/2057
2020 PO5735745655	KU	4	45 ACE	SP	CRE	ED,ID	BD	8/14/2057
2020 PO5760345665	KU	4	45 ACE	SP	CRE	ED,ID	BD	8/15/2057
2020 PO5748845660	KU	4	45 ACE	SP	CRE	ED,ID	BD	8/16/2057
2020 PO4835420939	KU	4	40 BRO	SP	A	ED,ID	TD	8/17/2057
2020 PO5776045669	KU	4	45 ACE	SP	CRE	ED,ID	BD	8/18/2057
2020 PO5720145755	KU	3	45 ACE	SP	CCA		V	8/19/2057
2020 PO5732445765	KU	4	45 ACE	SP	CCA		V	8/20/2057
2020 PO4882220626	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/21/2057
2020 PO4844420715	KU	4	40 BRO	SP	A	ED,ID	TD	8/22/2057
2020 PO5971242187a	KU	3	40 ACE	SP	CCA		V	8/23/2057
2020 PO5971242187	F	4	40 ACE	SP	CCA		V	8/24/2057
2020 PO5988442233	KU	4	40 ACE	SP	CCA		V	8/25/2057
2020 PO5956343146a	KU	6	30 ACE	SP	CCA		V	8/26/2057
2020 PO5931543209	F	4	40 ACE	SP	CCA		V	8/27/2057
2020 PO5954143248	F	4	40 ACE	SP	CRE		V	8/28/2057
2020 PO4874920013	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/29/2057
2020 PO4868220151	KU	4	40 BRO	SP	CRE	ED,ID	TD	8/30/2057
2020 PO5956343146	KU	6	30 ACE	SP	CRE	ED,ID	TD	8/31/2057
2020 PO9261536110	ODP	4	45 XXX	SP	CRE		V	9/1/2057
2020 PO9251736411	ODP	4	40 XXX	SP	CRE		V	9/2/2057
2020 PO9270835865	ODP	4	40 XXX	SP	CRE		V	9/3/2057
2020 PO8657646824	ODP	4	40 XXX	SP	CRE		V	9/4/2057
2020 PO8658246662	ODP	4	45 XXX	SP	CRE		V	9/5/2057
2020 PO8659146520	ODP	4	40 XXX	SP	CRE		V	9/6/2057
2020 PO8695546152	ODP	5	45 XXX	SP	CRE		V	9/7/2057
2020 PO9274936220	ODP	6	30 XXX	SP	CCA		V	9/8/2057
2020 PO8340645705	F	4	40 XXX	SP	CRE		V	9/9/2057
2020 PO8861542861	F	4	40 XXX	SP	A		V	9/10/2057
2020 PO8836943229	ODP	4	40 BRN	SP	CCA		V	9/11/2057
2020 PO8822943438	ODP	4	45 BRN	SP	CCA		V	9/12/2057
2020 PO8815443550	ODP	4	40 BRN	SP	CCA		V	9/13/2057
2020 PO8801543758	ODP	4	40 BRN	SP	CCA		V	9/14/2057
2020 PO8787643966	ODP	4	40 BRN	SP	CCA		V	9/15/2057
2020 PO8773744173	ODP	4	40 BRN	SP	CCA		V	9/16/2057
2020 PO8763344401	ODP	4	45 BRN	SP	CCA		V	9/17/2057
2020 PO8785644695	ODP	3	40 XXX	SP	CCA		V	9/18/2057
2020 PO5966443275	F	4	40 ACE	SP	P		V	9/19/2057
2020 PO5968743172	KU	6	30 ACE	SP	CCA	ED	T	9/20/2057
2020 PO5984343206	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	9/21/2057
2020 PO5983243312	F	4	40 ACE	SP	CRE		V	9/22/2057
2020 PO5999243243	KU	6	30 ACE	SP	CCA		V	9/23/2057
2020 PO6011543378	F	4	40 ACE	SP	P		V	9/24/2057
2020 PO5999343346	F	4	40 ACE	SP	P		V	9/25/2057

2020 PO5882146736a	KU	3	40 ACE	SP	CCA		V	9/26/2057
2020 PO4891819629	KU	4	40 BRO	SP	A	ED,ID	TD	9/27/2057
2020 PO5900246879	KU	4	45 ACE	SP	CRE	ED,ID	TD	9/28/2057
2020 PO5907346744	KU	4	45 ACE	SP	CRE	ED,ID	BD	9/29/2057
2020 PO4830713751	KU	5	35 BRO	SP	CRE		V	9/30/2057
2020 PO5882146736	KU	4	40 ACE	SP	CRE	ED,ID	TD	10/1/2057
2020 PO5873146733	KU	4	45 ACE	SP	CCA		V	10/2/2057
2020 PO5766146261	KU	4	45 ACE	SP	CRE	ED,ID	BD	10/3/2057
2020 PO5644550298	KU	4	45 ACE	SP	CRE		V	10/4/2057
2020 PO5552749882	KU	3	45 ACE	SP	CRE	ED,ID,IP	TD	10/5/2057
2020 PO4930119526	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	10/6/2057
2020 PO4912619509	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	10/7/2057
2020 PO8742745007	ODP	2	50 XXX	SP	CCA		V	10/8/2057
2020 PO8764545177	ODP	3	45 XXX	SP	CCA		V	10/9/2057
2020 PO8773145341	ODP	5	35 XXX	SP	CRE	ED,ID	TD	10/10/2057
2020 PO8660245399	ODP	4	40 XXX	SP	CRE		V	10/11/2057
2020 PO5218337333	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	10/12/2057
2020 PO4041482796	LGE	4	40 BRO	SP	A	ED,ID	TD	10/13/2057
2020 PO4043382797	LGE	4	40 BRO	SP	CRE	ED,ID	BD	10/14/2057
2020 PO4041182790	LGE	4	30 BRO	SP	CCA		V	10/15/2057
2020 PO4037582791	LGE	4	40 BRO	SP	CRE	ED,ID	TD	10/16/2057
2020 PO4039782795	LGE	4	40 BRO	SP	CCA		V	10/17/2057
2020 PO4741788616	LGE	4	40 BRN	SP	CCA		V	10/18/2057
2020 PO4741888616	LGE	4	35 BRN	SP	A	ED,ID	BD	10/19/2057
2020 PO4741188615	LGE	4	35 BRN	SP	CRE	ED,ID	TD	10/20/2057
2020 PO4703900950	KU	5	35 BRN	SP	CRE		V	10/21/2057
2020 PO4695400905	KU	5	35 BRN	SP	CRE		V	10/22/2057
2020 PO4679200758	KU	4	40 BRN	SP	CRE		V	10/23/2057
2020 PO4693200697	KU	4	40 BRN	SP	CRE		V	10/24/2057
2020 PO4738588832	LGE	6	25 BRN	SP	CRE	ED,ID	TD	10/25/2057
2020 PO4464601080	LGE	3	45 BRN	SP	S		V	10/26/2057
2020 PO4748988668	LGE	4	35 BRN	SP	CRE	ED,ID	TD	10/27/2057
2020 PO4880209892	KU	6	30 ACE	SP	P		T	10/28/2057
2020 PO4747988684	LGE	4	40 BRN	SP	CRE	ED,ID	TD	10/29/2057
2020 PO4753389010	LGE	4	40 BRO	SP	P	ED,ID	TD	10/30/2057
2020 PO4753789002	LGE	4	40 BRO	SP	A	ED,ID	BD	10/31/2057
2020 PO4754388988	LGE	4	40 BRO	SP	CCA		V	11/1/2057
2020 PO4884509766	KU	6	30 ACE	SP	P	ED	T	11/2/2057
2020 PO4228812512	KU	4	40 BRO	SP	CRE	ID,IP	BD	11/3/2057
2020 PO4221812552	KU	4	40 BRO	SP	CRE	ID	BD	11/4/2057
2020 PO4214912593	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	11/5/2057
2020 PO4852209778	KU	6	30 ACE	SP	P	ED	T	11/6/2057
2020 PO4747288697	LGE	4	40 BRN	SP	CRE	ED,ID	BD	11/7/2057
2020 PO4746288713	LGE	4	40 BRN	SP	A	ED,ID	TD	11/8/2057
2020 PO4745788720	LGE	4	40 BRN	SP	CCA		V	11/9/2057
2020 PO4745888726	LGE	4	30 BRN	SP	CCA		V	11/10/2057
2020 PO4733909619	KU	1	65 ACE	SP	CRE	ED,ID,IP	V	11/11/2057

2020 PO4745288729	LGE	4	40 BRN	SP	P	ED,ID	TD	11/12/2057
2020 PO4766409348	KU	1	75 ACE	SP	CRE	ED,ID	V	11/13/2057
2020 PO4775509278	KU	3	45 ACE	SP	CCA		V	11/14/2057
2020 PO4774209248	F	3	45 ACE	SP	CCA		V	11/15/2057
2020 PO4763709008a	KU	3	45 ACE	SP	P		V	11/16/2057
2020 PO4744388744	LGE	4	40 BRN	SP	A	ED,ID	BD	11/17/2057
2020 PO4763709008	F	3	50 ACE	SP	CRE	ED,ID	V	11/18/2057
2020 PO4206212597	KU	4	40 BRO	SP	CRE	ID,IP	BD	11/19/2057
2020 PO4209312656	KU	4	40 BRO	SP	CRE	ID	BD	11/20/2057
2020 PO4197812727	KU	4	40 BRO	SP	CRE	ID	BD	11/21/2057
2020 PO4743388760	LGE	4	40 BRN	SP	CRE	ED,ID	TD	11/22/2057
2020 PO4742388777	LGE	4	40 BRN	SP	A	ED,HH,ID,RB	X	PX 11/23/2057
2020 PO4526401683	KU	4	40 XXX	SP	CRE	ED,ID,RB	X	RP1 11/24/2057
2020 PO4514601784	KU	4	40 XXX	SP	CRE	ED,ID	TD	11/25/2057
2020 PO4502401885	KU	4	40 XXX	SP	CRE	ED,ID	TD	11/26/2057
2020 PO4741688789	LGE	4	35 BRN	SP	A	ED,ID	TD	11/27/2057
2020 PO4482301685	KU	4	40 XXX	SP	CRE	ED,ID	TD	11/28/2057
2020 PO4486201648	KU	4	40 XXX	SP	CRE	ED,ID	TD	11/29/2057
2020 PO4492201750	KU	4	40 XXX	SP	CRE	ED,ID	TD	11/30/2057
2020 PO1769497967	KU	4	40 UNK	SP	CRE	ID	TD	12/1/2057
2020 PO1764997840	KU	5	35 UNK	SP	CRE		V	12/2/2057
2020 PO5476194352	KU	5	35 BRN	SP	CCA		V	12/3/2057
2020 PO5497294372	KU	4	40 BRN	SP	CCA		V	12/4/2057
2020 PO1762497758	KU	4	40 UNK	SP	CRE	ID	BD	12/5/2057
2020 PO1739597780	F	4	40 UNK	SP	CRE		V	12/6/2057
2020 PO1760497677	KU	4	40 UNK	SP	CRE	ID,IP	TD	12/7/2057
2020 PO1695697484	KU	6	35 UNK	SP	CRE	ID,IP	TD	12/8/2057
2020 PO1699297373	KU	3	45 UNK	SP	CCA		V	12/9/2057
2020 PO4973913436	KU	5	35 ACE	SP	CRE	ED,ID	TD	12/10/2057
2020 PO4754688981	LGE	4	40 BRO	SP	CRE	ED,ID	BD	12/11/2057
2020 PO4755488972	LGE	4	40 BRO	SP	CRE	ED,ID	BD	12/12/2057
2020 PO4740988799	LGE	4	40 BRN	SP	A	ED,ID	TD	12/13/2057
2020 PO4180112824	KU	4	40 BRO	SP	CRE	ID	BD	12/14/2057
2020 PO4172712685	KU	4	40 BRO	SP	CRE	ID	BD	12/15/2057
2020 PO4165212540	KU	4	40 BRO	SP	CRE	ID	BD	12/16/2057
2020 PO4161812473	KU	4	40 BRO	SP	CRE	ID	BD	12/17/2057
2020 PO4176811252	KU	4	40 BRO	SP	CRE	ID	BD	12/18/2057
2020 PO4971913376	KU	5	35 ACE	SP	CRE	ED,ID	BD	12/19/2057
2020 PO4966713337	KU	5	35 ACE	SP	P	ED,ID	BD	12/20/2057
2020 PO4740188812	LGE	4	35 BRN	SP	CRE	ED,ID	TD	12/21/2057
2020 PO4495301947	KU	4	40 XXX	SP	CRE	ED,ID	TD	12/22/2057
2020 PO4474702025	KU	4	40 XXX	SP	CRE	ED,ID	TD	12/23/2057
2020 PO4756088958	LGE	4	40 BRO	SP	CRE	ED,ID	BD	12/24/2057
2020 PO4756388946	LGE	4	40 BRO	SP	CRE	ED,ID	BD	12/25/2057
2020 PO4757188972	LGE	4	40 BRO	SP	CRE	ED,ID	TD	12/26/2057
2020 PO4758688964	LGE	3	45 BRO	SP	CCA		V	12/27/2057
2020 PO4759888964	LGE	3	45 BRO	SP	CCA		V	12/28/2057

2020 PO4739688822	LGE	4	40 BRN	SP	A	ED,ID	TD	12/29/2057
2020 PO4466601913	KU	4	40 XXX	SP	CRE	ED,ID	TD	12/30/2057
2020 PO4952213404	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	12/31/2057
2020 PO4738888835	LGE	1	50 BRN	SP	S		V	1/1/2058
2020 PO4730688824	LGE	4	30 BRN	SP	CCA		V	1/2/2058
2020 PO4460801833	KU	4	40 XXX	SP	CRE	ED,ID	TD	1/3/2058
2020 PO4750488621	LGE	3	45 BRN	SP	S		V	1/4/2058
2020 PO4749388617	LGE	1	50 BRN	SP	S		V	1/5/2058
2020 PO4748288614	LGE	4	40 BRN	SP	A	ED,ID	BD	1/6/2058
2020 PO4943513194	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	1/7/2058
2020 PO4747188610	LGE	4	40 BRN	SP	CRE	ED,ID	BD	1/8/2058
2020 PO4425801661	KU	5	35 XXX	SP	CRE	ED,ID	TD	1/9/2058
2020 PO4452901724	KU	4	40 BRN	SP	CRE	ED,ID	TD	1/10/2058
2020 PO4746088606	LGE	4	35 BRN	SP	CRE	ED,ID	BD	1/11/2058
2020 PO4745088603	LGE	4	40 BRN	SP	S		V	1/12/2058
2020 PO4437401508	KU	4	40 BRN	SP	CRE	ED,ID	TD	1/13/2058
2020 PO4903513605	KU	6	30 ACE	SP	CRE	ED,ID	TD	1/14/2058
2020 PO2139327558	ODP	2	50 XXX	SP	CCA		V	1/15/2058
2020 PO2125727431	ODP	4	40 XXX	SP	CRE	ID	TD	1/16/2058
2020 PO2152927043	ODP	2	50 XXX	SP	CCA		V	1/17/2058
2020 PO2147427048	F	5	35 XXX	SP	A		V	1/18/2058
2020 PO2147626768	F	4	40 XXX	SP	A		V	1/19/2058
2020 PO4190711430	KU	4	40 BRO	SP	CRE	ED,ID,IP	BD	1/20/2058
2020 PO4214211582	KU	4	40 BRO	SP	CRE	ID	BD	1/21/2058
2020 PO4853313826	F	5	35 ACE	SP	P		V	1/22/2058
2020 PO4867913765	F	5	35 ACE	SP	CRE	ED,ID	V	1/23/2058
2020 PO4880613713	F	5	35 ACE	SP	P		V	1/24/2058
2020 PO4892613666	F	4	40 ACE	SP	P		V	1/25/2058
2020 PO4894813716	KU	4	40 ACE	SP	CRE	ED,ID	BD	1/26/2058
2020 PO4896813762	KU	3	45 ACE	SP	CCA		V	1/27/2058
2020 PO4494000760	KU	4	40 BRN	SP	CRE	ID,RB	BX	RP1 1/28/2058
2020 PO4053282872	LGE	4	40 BRO	SP	A	ED,ID	TD	1/29/2058
2020 PO4742889072	LGE	4	40 BRO	SP	CRE	ED,ID	BD	1/30/2058
2020 PO4743989055	LGE	4	35 BRO	SP	CRE		V	1/31/2058
2020 PO4743489063	LGE	4	35 BRO	SP	CRE		V	2/1/2058
2020 PO4742889071	LGE	4	35 BRO	SP	CRE		V	2/2/2058
2020 PO4052582983	LGE	4	40 BRO	SP	A	ED,ID	TD	2/3/2058
2020 PO4049382974	LGE	4	35 BRO	SP	CRE	ED,ID	TD	2/4/2058
2020 PO4049682968	LGE	4	40 BRO	SP	A	ED,ID	TD	2/5/2058
2020 PO4051182976	LGE	4	40 BRO	SP	A	ED,ID,MD	TD	2/6/2058
2020 PO4050982982	LGE	4	35 BRO	SP	P	ED,HH,ID,RB	X	RP1 2/7/2058
2020 PO4744089097	LGE	4	35 BRO	SP	CRE		V	2/8/2058
2020 PO4747989108	LGE	4	35 BRO	SP	CRE		V	2/9/2058
2020 PO4744189107	LGE	4	35 BRO	SP	CRE		V	2/10/2058
2020 PO4738188898	LGE	4	35 BRN	SP	S		V	2/11/2058
2020 PO4743588864	LGE	3H	45 BRN	SP	CCA		V	2/12/2058
2020 PO4742989089	LGE	4	40 BRO	SP	CCA		V	2/13/2058

2020 PO4742889091	LGE	4	40 BRO	SP	CRE		B		2/14/2058
2020 PO4742089001	LGE	3	45 BRO	SP	CCA		V		2/15/2058
2020 PO4751888676	LGE	4	40 BRN	SP	CRE	ED,ID	TD		2/16/2058
2020 PO4857811110	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD		2/17/2058
2020 PO9983976397	KU	4	40 BRN	SP	CCA		V		2/18/2058
2020 PO9965876287	KU	2	50 BRN	SP	CRE	ED,ID,RB	BX	RP1	2/19/2058
2020 PO9957976239	KU	2	40 BRN	SP	CCA		V		2/20/2058
2020 PO9982475876	KU	4	45 XXX	SP	CCA		V		2/21/2058
2020 PO4690788557	LGE	4	35 BRN	SP	A	ED,ID	BD		2/22/2058
2020 PO4689288546	LGE	4	40 BRN	SP	CRE	ED,HH,ID	BX	RR	2/23/2058
2020 PO4687888544	LGE	4	35 BRN	SP	CCA		V		2/24/2058
2020 PO4848187650	LGE	4	40 BRO	SP	CCA		V		2/25/2058
2020 PO4845887644	LGE	UNK	45 BRO	SP	CRE	ED	TD		2/26/2058
2020 PO4823688342	LGE	4	40 BRO	SP	CRE	ED	BD		2/27/2058
2020 PO4824788316	LGE	4	40 BRO	SP	CRE		V		2/28/2058
2020 PO4825688292	LGE	3	50 BRO	SP	CRE	ED	TD		3/1/2058
2020 PO4826288277	LGE	3	50 BRO	SP	CRE	ED	TD		3/2/2058
2020 PO4826888262	LGE	UNK	45 BRO	SP	CRE	ED	BD		3/3/2058
2020 PO4825288250	LGE	4	35 BRO	SP	CRE	ED	TD		3/4/2058
2020 PO4827088258	LGE	UNK	45 BRO	SP	CCA		V		3/5/2058
2020 PO4684888615	LGE	4	35 BRN	SP	CCA		V		3/6/2058
2020 PO4686088624	LGE	4	35 BRN	SP	CCA		V		3/7/2058
2020 PO4687088632	LGE	4	35 BRN	SP	A	ED,ID	TD		3/8/2058
2020 PO4538889927	KU	4	40 KOP	SP	S		V		3/9/2058
2020 PO4537590110	KU	4	40 KOP	SP	S		V		3/10/2058
2020 PO4688288641	LGE	4	35 BRN	SP	A	ED,ID	TD		3/11/2058
2020 PO468888627	LGE	4	40 BRN	SP	A	ED,ID	TD		3/12/2058
2020 PO8778564428	KU	4	40 XXX	SP	CRE	ED,ID	TD		3/13/2058
2020 PO8773764933	KU	4	40 XXX	SP	CRE	ED,ID	TD		3/14/2058
2020 PO8770065137	KU	4	45 XXX	SP	CRE	ED,ID	TD		3/15/2058
2020 PO8766965468	KU	2	65 XXX	SP	CRE		V		3/16/2058
2020 PO8759365574	KU	5	35 XXX	SP	CRE	ED,ID	TD		3/17/2058
2020 PO8738265628	KU	5	35 XXX	SP	CCA	ED	T		3/18/2058
2020 PO8750165716	KU	4	45 XXX	SP	CRE		V		3/19/2058
2020 PO7831460579	KU	4	40 XXX	SP	CCA		V		3/20/2058
2020 PO7837460368	KU	3	45 XXX	SP	CCA		V		3/21/2058
2020 PO7824060326	KU	4	40 XXX	SP	CRE	ID	BD		3/22/2058
2020 PO7819660260	KU	4	40 XXX	SP	CCA		V		3/23/2058
2020 PO7802560156	KU	2	50 XXX	SP	CCA		V		3/24/2058
2020 PO7883660954	KU	4	40 XXX	SP	CRE	ED,ID	TD		3/25/2058
2020 PO7888361359	KU	2	45 XXX	SP	CRE	ED,ID	TD		3/26/2058
2020 PO7908561130	KU	4	40 XXX	SP	CRE	ED,ID	TD		3/27/2058
2020 PO7920761263	KU	4	40 XXX	SP	CRE	ED,ID	TD		3/28/2058
2020 PO7948461259	KU	5	35 XXX	SP	CCA		V		3/29/2058
2020 PO7942761420	KU	4	40 XXX	SP	CRE	ID	BD		3/30/2058
2020 PO7965561578	KU	4	40 BRN	SP	CRE	ID	BD		3/31/2058
2020 PO7964661794	KU	4	45 BRN	SP	CCA		V		4/1/2058

2020 PO7984561713	KU	4	45 BRN	SP	CCA		V	4/2/2058	
2020 PO7982761883	KU	5	35 BRN	SP	CCA		V	4/3/2058	
2020 PO3886969563	KU	4	40 KOP	SP	CRE	ED,ID	TD	4/4/2058	
2020 PO3893969985	KU	4	40 KOP	SP	CRE	ED,ID	TD	4/5/2058	
2020 PO3852267436	KU	6	30 KOP	SP	CRE		V	4/6/2058	
2020 PO3851267579	KU	6	30 KOP	SP	CRE		V	4/7/2058	
2020 PO3853067303	KU	4	40 KOP	SP	A	ED,ID	TD	4/8/2058	
2020 PO3866067408	KU	6	30 KOP	SP	CRE	ED,ID	TD	4/9/2058	
2020 PO3892367420	KU	4	40 KOP	SP	CRE	ID,IP	BD	4/10/2058	
2020 PO3886390497	F	5	30 XXX	SP	A		V	4/11/2058	
2020 PO3886790406	F	4	40 XXX	SP	CRE		V	4/12/2058	
2020 PO3900390193	F	4	40 XXX	SP	CRE		V	4/13/2058	
2020 PO4662688192	LGE	4	30 BRN	SP	CCA		V	4/14/2058	
2020 PO4663788176	LGE	4	30 BRN	SP	CRE	ED,ID	BD	4/15/2058	
2020 PO3742794382	LGE	4	35 BRN	SP	CCA		V	4/16/2058	
2020 PO3909689965	F	4	40 XXX	SP	CRE		V	4/17/2058	
2020 PO3913289985	F	4	40 XXX	SP	CRE		V	4/18/2058	
2020 PO3918489990	F	5	30 XXX	SP	CRE		V	4/19/2058	
2020 PO3921689855	F	4	40 XXX	SP	CRE		V	4/20/2058	
2020 PO3926489780	F	4	40 XXX	SP	CRE		V	4/21/2058	
2020 PO3930489809	KU	4	40 XXX	SP	CRE	ID	BD	4/22/2058	
2020 PO3952289517	KU	4	45 XXX	SP	CRE	ID	BD	4/23/2058	
2020 PO3932089669	F	4	40 XXX	SP	CRE		V	4/24/2058	
2020 PO3924989624	F	4	40 XXX	SP	CRE		V	4/25/2058	
2020 PO4664188152	LGE	4	40 BRN	SP	P	ED,ID	BD	4/26/2058	
2020 PO4665188155	LGE	4	30 BRN	SP	P		T	4/27/2058	
2020 PO4665688146	LGE	6	25 BRN	SP	A	ED,ID,IP	TD	4/28/2058	
2020 PO3917889587	F	4	40 XXX	SP	CRE		V	4/29/2058	
2020 PO3909189540	F	4	40 XXX	SP	CRE		V	4/30/2058	
2020 PO3892289496	F	4	40 XXX	SP	CRE		V	5/1/2058	
2020 PO3878089421	F	5	40 XXX	SP	CRE	ID	B	5/2/2058	
2020 PO3862889334	F	4	40 XXX	SP	CRE		V	5/3/2058	
2020 PO3850189262	F	4	40 XXX	SP	CRE		V	5/4/2058	
2020 PO3842289328	F	4	30 XXX	SP	A		V	5/5/2058	
2020 PO3833589512	F	4	30 XXX	SP	A		V	5/6/2058	
2020 PO4666288138	LGE	6	25 BRN	SP	A	ED,ID,IP	BD	5/7/2058	
2020 PO4666888130	LGE	6	25 BRN	SP	CRE	ED,ID	BD	5/8/2058	
2020 PO4646189066-B	LGE	5	35 BRO	SP	A	ED	T	5/9/2058	
2020 PO4646189066-A	LGE	3	35 BRO	SP	A	ED	T	5/10/2058	
2020 PO4653389031	LGE	4	30 BRO	SP	CRE	ED,EP,ID,IP,RB	X	RR	5/11/2058
2020 PO4667388121	LGE	4	30 BRN	SP	A	ED,ID	TD	5/12/2058	
2020 PO4667888113	LGE	6	25 BRN	SP	CRE	ED,ID	BX	PX	5/13/2058
2020 PO4718787920	LGE	UNK	70 BRO	SP	CRE		V	5/14/2058	
2020 PO4575491651	F	4	35 BRO	SP	CCA		V	5/15/2058	
2020 PO4727687903	F	4	40 BRO	AL	CCA		V	5/16/2058	
2020 PO4722887916	LGE	UNK	70 BRO	SP	CRE		V	5/17/2058	
2020 PO4725287913	LGE	UNK	75 BRO	SP	CRE		V	5/18/2058	

2020 PO4727587911	LGE	UNK	70 BRO	SP	CRE		V	5/19/2058
2020 PO5809405329	KU	4	45 XXX	SP	CCA		V	5/20/2058
2020 PO4651889060	LGE	4	30 BRO	SP	A	ED	T	5/21/2058
2020 PO4652689056	LGE	4	30 BRO	SP	A	ED	T	5/22/2058
2020 PO4652889038-A	LGE	4	35 BRO	SP	A	ED	T	5/23/2058
2020 PO4652889038	LGE	4	40 BRO	SP	CRE	ED,ID	BD	5/24/2058
2020 PO5785705151	KU	4	45 XXX	SP	CCA	ED	T	5/25/2058
2020 PO5762305107	F	4	45 XXX	SP	CRE		V	5/26/2058
2020 PO5766704900	KU	4	45 XXX	SP	CRE	ED,ID	TD	5/27/2058
2020 PO5770004747	KU	4	45 XXX	SP	CRE	ED,ID	TD	5/28/2058
2020 PO5772204630	KU	4	45 XXX	SP	CRE	ED,ID	TD	5/29/2058
2020 PO4666188151	LGE	4	35 BRN	SP	CRE	ED,ID	BD	5/30/2058
2020 PO4666788142	LGE	4	40 BRN	SP	CCA		V	5/31/2058
2020 PO4667388134	LGE	4	40 BRN	SP	A	ED,ID	BD	6/1/2058
2020 PO4667888126	LGE	4	40 BRN	SP	A	ED,ID	BD	6/2/2058
2020 PO4668488118	LGE	4	40 BRN	SP	A	ED,ID	BD	6/3/2058
2020 PO4669088109	LGE	3	45 BRN	SP	CCA		V	6/4/2058
2020 PO4651089071	LGE	4	35 BRO	SP	A	ED	T	6/5/2058
2020 PO4649689065	LGE	4	35 BRO	SP	A	ED	T	6/6/2058
2020 PO4648489074	LGE	4	35 BRO	SP	A	ED	T	6/7/2058
2020 PO4651389025	LGE	4	45 BRO	SP	CRE	ED,ID,IP	TD	6/8/2058
2020 PO4650789028-A	LGE	4	40 BRO	SP	A	ED	TD	6/9/2058
2020 PO4650789028	LGE	4	40 BRO	SP	A	ID,IP	BD	6/10/2058
2020 PO4736789266	F	3	45 BRO	SP	CRE		V	6/11/2058
2020 PO1383724311	F	3	45 BRN	SP	P		V	6/12/2058
2020 PO2201124604	ODP	5	35 XXX	SP	CRE	ID	TD	6/13/2058
2020 PO1315731078	ODP	6	30 BRN	SP	CRE		V	6/14/2058
2020 PO2199722660	ODP	6	30 XXX	SP	CRE		V	6/15/2058
2020 PO2118327643	ODP	5	35 XXX	SP	CRE		V	6/16/2058
2020 PO2465740492	ODP	4	40 ACW	SP	CRE	ED,ID	TD	6/17/2058
2020 PO4650789026	LGE	4	40 BRO	SP	CCA		V	6/18/2058
2020 PO4687788358	LGE	4	25 BRN	SP	A		V	6/19/2058
2020 PO4688388352	LGE	4	40 BRN	SP	A	ED,ID	BD	6/20/2058
2020 PO4689288359	LGE	4	40 BRN	SP	A	ED,ID	BD	6/21/2058
2020 PO4686588391	LGE	3	45 BRN	SP	CCA		V	6/22/2058
2020 PO4688688394	LGE	3	50 BRN	SP	CCA		V	6/23/2058
2020 PO4690788397	LGE	1	50 BRN	SP	A		V	6/24/2058
2020 PO4690688370	LGE	3	45 BRN	SP	CCA		V	6/25/2058
2020 PO4690588371	LGE	4	45 BRN	SP	A	ED,ID	BD	6/26/2058
2020 PO4647089010	F	4	40 BRO	SP	CRE		V	6/27/2058
2020 PO6500115952	KU	6	30 XXX	SP	CRE		V	6/28/2058
2020 PO4029096307	LGE	3	45 BRN	SP	CCA		V	6/29/2058
2020 PO4693188358	LGE	1	50 BRN	SP	CCA		V	6/30/2058
2020 PO4691888375	LGE	1	50 BRN	SP	CCA		V	7/1/2058
2020 PO4691688378	LGE	3	45 BRN	SP	A	ED,ID	BD	7/2/2058
2020 PO4692888388	LGE	4	40 BRN	SP	CRE	ED,EP,ID	BD	7/3/2058
2020 PO4648589003	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	7/4/2058

2020 PO4693688395	LGE	3	45 BRN	SP	A		ED,ID	BD		7/5/2058
2020 PO6571015510	KU	5	35 XXX	SP	CCA			V		7/6/2058
2020 PO6573515602	KU	4	40 XXX	SP	CRE		ED,ID	TD		7/7/2058
2020 PO6542615699	KU	4	40 XXX	SP	CRE		ID,RB	X	RP1	7/8/2058
2020 PO6512315825	KU	4	40 XXX	SP	CRE		ED,ID	TD		7/9/2058
2020 PO4696488379	F	4	40 BRN	SP	CCA			V		7/10/2058
2020 PO4697388367	F	4	40 BRN	SP	CCA			V		7/11/2058
2020 PO4698288356	F	4	40 BRN	SP	CCA			V		7/12/2058
2020 PO4699088345	F	4	40 BRN	SP	CCA			V		7/13/2058
2020 PO4693788399	LGE	4	40 BRN	SP	CCA			V		7/14/2058
2020 PO4698988399	LGE	4	35 BRN	SP	CRE		ED,ID	BD		7/15/2058
2020 PO4699788399	LGE	4	35 BRN	SP	CRE		ED,ID,IP	BD		7/16/2058
2020 PO6483215857	KU	4	40 XXX	SP	CRE		ED,ID	TD		7/17/2058
2020 PO6455515976	KU	4	40 XXX	SP	CRE		ED,ID	TD		7/18/2058
2020 PO6434016060	KU	4	40 XXX	SP	CRE		ED,ID	TD		7/19/2058
2020 PO6404416228	KU	4	40 XXX	SP	CRE		ED,ID	TD		7/20/2058
2020 PO4649089007	LGE	3	45 BRO	SP	CRE		ED,ID,IP	TD		7/21/2058
2020 PO4700688391	LGE	6	25 BRN	SP	CRE		ED,ID	BD		7/22/2058
2020 PO4699188406	LGE	4	40 BRN	SP	CRE		ED,ID	BD		7/23/2058
2020 PO3841090396	KU	4	40 KOP	SP	CRE		ID	BD		7/24/2058
2020 PO3852390354	KU	4	40 KOP	SP	CRE		ED,ID	TD		7/25/2058
2020 PO3855990376	KU	5	35 KOP	SP	CRE		ED,ID	TD		7/26/2058
2020 PO3860590401	KU	5	35 KOP	SP	S			V		7/27/2058
2020 PO4698388417	LGE	4	40 BRN	SP	A		ED,ID	BD		7/28/2058
2020 PO4697888425	LGE	4	45 BRN	SP	A		ED,ID	BD		7/29/2058
2020 PO4695788391-A	LGE	4	30 BRN	SP	S			V		7/30/2058
2020 PO4694888403	F	3	50 BRN	SP	S			V		7/31/2058
2020 PO4695788391	LGE	2	55 BRN	SP	CCA			V		8/1/2058
2020 PO3907189789	KU	6	30 KOP	SP	CRE		ED,ID	TD		8/2/2058
2020 PO3882089662	KU	6	30 KOP	SP	CRE		ED,ID	TD		8/3/2058
2020 PO3872889525	F	4	40 KOP	SP	CRE			V		8/4/2058
2020 PO3885489587	F	4	40 KOP	SP	CRE			V		8/5/2058
2020 PO3898489651	F	4	40 KOP	SP	CRE			V		8/6/2058
2020 PO3910989715	F	4	40 KOP	SP	CRE			V		8/7/2058
2020 PO3921289768	F	4	40 KOP	SP	CRE			V		8/8/2058
2020 PO6377416329	KU	4	40 XXX	SP	CCA			V		8/9/2058
2020 PO6357815985	KU	4	40 XXX	SP	CRE		ED,ID	TD		8/10/2058
2020 PO6361616273	KU	4	40 XXX	SP	CCA			V		8/11/2058
2020 PO6362916450	KU	4	40 XXX	SP	CRE		ED,ID	TD		8/12/2058
2020 PO4649889014	LGE	3	45 BRO	SP	A		ED,ID,IP	TD		8/13/2058
2020 PO4698588376	LGE	4	35 BRN	SP	CRE		ED,ID	BD		8/14/2058
2020 PO4699888387	LGE	4	35 BRN	SP	CRE		ED,ID	BD		8/15/2058
2020 PO4700488389	LGE	4	35 BRN	SP	CRE		ED,ID,RB	BX	PX	8/16/2058
2020 PO4700988382	LGE	4	40 BRN	SP	CRE		ED,ID	BD		8/17/2058
2020 PO6340216645	KU	4	40 XXX	SP	CRE		ED,ID	TD		8/18/2058
2020 PO6325616882	KU	4	40 XXX	SP	CRE		ED,ID	TD		8/19/2058
2020 PO6311917152	KU	4	40 XXX	SP	CRE		ED,ID	TD		8/20/2058

2020 PO4649589001	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TX	RR	8/21/2058
2020 PO4702488361	LGE	4	40 BRN	SP	A	ED,ID	BD		8/22/2058
2020 PO4703088353	LGE	4	35 BRN	SP	CRE	ED,ID	BD		8/23/2058
2020 PO4019991986	KU	5	35 KOP	SP	CRE	ED,ID	TD		8/24/2058
2020 PO4020891961	F	4	40 KOP	SP	P		V		8/25/2058
2020 PO4011391943	F	5	35 KOP	SP	S		V		8/26/2058
2020 PO4006992052	F	4	40 KOP	SP	CRE		V		8/27/2058
2020 PO3999092197	F	4	40 KOP	SP	CRE		V		8/28/2058
2020 PO4007292225	F	4	40 KOP	SP	CRE		V		8/29/2058
2020 PO4032592410	KU	4	40 KOP	SP	CRE	ID	BD		8/30/2058
2020 PO4034192335	KU	6	30 KOP	SP	S		V		8/31/2058
2020 PO4036592277	F	4	40 KOP	SP	CRE		V		9/1/2058
2020 PO4021392306	F	4	40 KOP	SP	CRE		V		9/2/2058
2020 PO4024392262	F	4	40 KOP	SP	S		V		9/3/2058
2020 PO4701988368	LGE	4	35 BRN	SP	CCA		V		9/4/2058
2020 PO4701788375	LGE	6	25 BRN	SP	A	ED,ID	BD		9/5/2058
2020 PO4701588374	LGE	4	40 BRN	SP	A	ED,ID	BD		9/6/2058
2020 PO4701696447	LGE	3	45 BRN	SP	S		V		9/7/2058
2020 PO4700088364-A	LGE	4	25 BRN	SP	A	ED,ID	BD		9/8/2058
2020 PO4651789020	LGE	4	30 BRO	SP	CRE	EP,ID,IP	TD		9/9/2058
2020 PO4699688362	LGE	4	40 BRN	SP	P	ED,ID	BD		9/10/2058
2020 PO4700088364	LGE	3	45 BRN	SP	A	ED,ID	BD		9/11/2058
2020 PO4659389172	LGE	4	35 BRO	SP	CRE	ID,IP	BD		9/12/2058
2020 PO4657189155	LGE	4	30 BRO	SP	CRE	ID,IP	BD		9/13/2058
2020 PO4658189163	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD		9/14/2058
2020 PO4070089443	F	4	40 KOP	SP	CRE		V		9/15/2058
2020 PO4062789581	F	4	40 KOP	SP	CRE		V		9/16/2058
2020 PO4056289707	F	4	40 KOP	SP	CRE		V		9/17/2058
2020 PO4050289678	F	4	40 KOP	SP	CRE		V		9/18/2058
2020 PO4053989347	F	4	40 KOP	SP	CRE		V		9/19/2058
2020 PO4043889496	F	4	40 KOP	SP	CRE		V		9/20/2058
2020 PO3927287680	F	2	45 KOP	SP	P		V		9/21/2058
2020 PO3934087549	F	2	45 KOP	SP	S		V		9/22/2058
2020 PO3928887520	KU	2	45 KOP	SP	S		V		9/23/2058
2020 PO3927688714	F	4	40 KOP	SP	CRE		V		9/24/2058
2020 PO4701188352	LGE	3	45 BRN	SP	CCA		V		9/25/2058
2020 PO6328617244	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD		9/26/2058
2020 PO4661289188	LGE	4	40 BRO	SP	A	ED	TD		9/27/2058
2020 PO4660389181	LGE	4	40 BRO	SP	A	ED	T		9/28/2058
2020 PO6296517438	F	4	40 XXX	SP	CRE		V		9/29/2058
2020 PO3925687894	F	4	40 KOP	SP	P		V		9/30/2058
2020 PO3920987843	F	2	45 KOP	SP	P		V		10/1/2058
2020 PO3910987992	F	4	40 KOP	SP	P		V		10/2/2058
2020 PO3906188085	F	2	45 KOP	SP	P		V		10/3/2058
2020 PO3904688115	F	2	45 KOP	SP	P		V		10/4/2058
2020 PO3896988263	F	2	45 KOP	SP	P		V		10/5/2058
2020 PO6204916561	KU	4	40 XXX	SP	CRE	ED,ID	TD		10/6/2058

2020 PO6217116528	KU	4	40 XXX	SP	CRE	ED,ID	TD	10/7/2058
2020 PO4702288333	LGE	4	40 BRN	SP	A	ED,ID	BD	10/8/2058
2020 PO3889788425	F	4	40 KOP	SP	P		V	10/9/2058
2020 PO3894088449	F	4	40 KOP	SP	P		V	10/10/2058
2020 PO3903588503	F	4	40 KOP	SP	P		V	10/11/2058
2020 PO3915488571	F	4	40 KOP	SP	P		V	10/12/2058
2020 PO3922288609	F	4	40 KOP	SP	P		V	10/13/2058
2020 PO3930888657	F	4	40 KOP	SP	P		V	10/14/2058
2020 PO3944888737	F	4	40 KOP	SP	P		V	10/15/2058
2020 PO3964288846	F	4	40 KOP	SP	P		V	10/16/2058
2020 PO3961388897	KU	6	30 KOP	SP	CRE	ID	BD	10/17/2058
2020 PO3961988938	KU	6	30 KOP	SP	CRE	ID	BD	10/18/2058
2020 PO3978289037	KU	5	30 KOP	SP	CRE	ED,ID	TD	10/19/2058
2020 PO3981189020	F	4	40 KOP	SP	CRE		V	10/20/2058
2020 PO3984288959	F	4	40 KOP	SP	P		V	10/21/2058
2020 PO4004389071	F	4	40 KOP	SP	P		V	10/22/2058
2020 PO4001289139	KU	5	30 KOP	SP	CRE	ED,ID	TD	10/23/2058
2020 PO4016989184	F	4	40 KOP	SP	CRE		V	10/24/2058
2020 PO4046989142	KU	4	40 KOP	SP	CRE	ED,ID	TD	10/25/2058
2020 PO4039389267	F	4	40 KOP	SP	CRE		V	10/26/2058
2020 PO4018789153	F	4	40 KOP	SP	P		V	10/27/2058
2020 40765 89463	KU	6	30 KOP	SP	S		V	10/28/2058
2020 PO1625574144	KU	4	45 BRN	SP	CRE	ED,ID,IP	TD	10/29/2058
2020 PO1680872342	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	10/30/2058
2020 PO1635673938	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	10/31/2058
2020 PO1656574138	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	11/1/2058
2020 PO1629574748	KU	3	40 BRN	SP	CCA		V	11/2/2058
2020 PO1578375161	KU	4	40 BRN	SP	CRE	ID,IP	BD	11/3/2058
2020 PO9880460469	KU	4	40 ACW	SP	P	ED	T	11/4/2058
2020 PO9888060692	KU	4	40 ACW	SP	CRE	ED,ID	TD	11/5/2058
2020 PO9897660954	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	11/6/2058
2020 PO9903261116	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	11/7/2058
2020 PO9908361261	KU	5	35 ACW	SP	CRE	ED,ID,IP	TD	11/8/2058
2020 PO9936661643	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	11/9/2058
2020 PO1701274563	KU	4	40 BRN	SP	CRE	ID,IP	BD	11/10/2058
2020 PO9942061794	KU	5	35 ACW	SP	CRE	ED,ID	TD	11/11/2058
2020 PO397782809	F	4	40 BRN	SP	S		V	11/12/2058
2020 PO1153837032	F	4	40 BRN	SP	P		V	11/13/2058
2020 PO3877082726	LGE	4	50 BRO	SP	CRE	ED,ID	TD	11/14/2058
2020 PO3877482720	LGE	4	40 BRO	SP	P	ED,ID	X	RP1 11/15/2058
2020 PO1166136868	F	4	40 BRN	SP	CRE		V	11/16/2058
2020 PO1150436885	F	4	40 BRN	SP	CRE		V	11/17/2058
2020 PO2519034475	KU	4	40 BRN	SP	CCA		V	11/18/2058
2020 PO2469634298	KU	4	40 BRN	SP	CRE	ID	BD	11/19/2058
2020 PO2491635212	KU	5	35 BRN	SP	CRE	HH,ID,IP	BX	RP3 11/20/2058
2020 PO2455034500	KU	5	35 BRN	SP	CRE	ID,IP	BD	11/21/2058
2020 PO2464834215	KU	6	30 BRN	SP	CRE		V	11/22/2058

2020 PO2467434746	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD		11/23/2058
2020 PO1150836680	F	4	40 BRN	SP	CRE	ED,ID	VX	RP2	11/24/2058
2020 PO1596238039	F	5	35 KOP	SP	CRE		V		11/25/2058
2020 PO1591038165	ODP	4	45 UNK	SP	P	ED,ID	TD		11/26/2058
2020 PO2363629003	KU	4	40 BRN	SP	CRE	HH,ID,IP	BX	RP2	11/27/2058
2020 PO9948661987	KU	4	40 ACW	SP	CRE	ED,ID,IP	BD		11/28/2058
2020 PO9937261521	KU	4	40 ACW	SP	CCA		V		11/29/2058
2020 PO9937961334	KU	4	40 ACW	SP	CCA		V		11/30/2058
2020 PO0226749283	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD		12/1/2058
2020 PO0168048516	KU	4	40 BRO	SP	CRE	ID	BD		12/2/2058
2020 PO0828858826	KU	4	40 ACW	SP	CRE	ED,ID	TD		12/3/2058
2020 PO1701171026	KU	4	40 BRN	SP	CRE	ID,IP	BD		12/4/2058
2020 PO1679373010	KU	4	40 BRN	SP	CRE	ID,IP	BD		12/5/2058
2020 PO0157948324	KU	4	40 BRO	SP	CRE	ED,ID,IP,SRC	TD		12/6/2058
2020 PO0145848264	KU	4	40 BRO	SP	CCA		V		12/7/2058
2020 PO0804658913	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		12/8/2058
2020 PO0790059054	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		12/9/2058
2020 PO0761359333	KU	4	40 ACW	SP	CRE	ED,ID	TD		12/10/2058
2020 PO0527547775	KU	5	35 BRO	SP	CRE	ED,ID,SRC	TD		12/11/2058
2020 PO0254447890	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD		12/12/2058
2020 PO0243747945	KU	5	35 BRO	SP	CRE		B		12/13/2058
2020 PO0297947705	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD		12/14/2058
2020 PO2334829155	KU	4	40 BRN	SP	CCA		V		12/15/2058
2020 PO2325929188	KU	5	35 BRN	SP	CRE		V		12/16/2058
2020 PO2300029115	KU	4	40 BRN	SP	CCA		V		12/17/2058
2020 PO7466483076	KU	4	45 BRN	SP	CRE	ED,ID	TD		12/18/2058
2020 PO7429081825-A	KU	5	35 BRN	SP	CRE	ED,ID	BD		12/19/2058
2020 PO7429081825	KU	5	35 BRN	SP	CRE	ED,ID	BD		12/20/2058
2020 PO7995374189	KU	4	40 BRO	SP	CRE	ED,ID	TD		12/21/2058
2020 PO8014773799	KU	2	70 BRO	SP	CRE		V		12/22/2058
2020 PO8000474100	KU	2	65 BRO	SP	CRE		V		12/23/2058
2020 PO0342255307	KU	4	40 BRO	SP	CCA		V		12/24/2058
2020 PO0332855079	KU	6	35 BRO	SP	CRE	ED	T		12/25/2058
2020 PO0327454946	KU	4	40 BRO	SP	CRE	ED,ID,SRC,SRS	TD		12/26/2058
2020 PO0321954815	KU	4	40 BRO	SP	CRE	ED,ID,SRC,SRS	TD		12/27/2058
2020 PO0316254676	KU	4	40 BRO	SP	CRE	ID	BD		12/28/2058
2020 PO0316254676	KU	4	40 BRO	SP	CRE	ID	BD		12/29/2058
2020 PO0310154533	KU	4	40 BRO	SP	CRE		V		12/30/2058
2020 PO0295454185	KU	4	40 BRO	SP	CRE		V		12/31/2058
2020 PO0286453970	KU	4	40 BRO	SP	CRE	ED,ID,IP,SRC,SRS	TD		1/1/2059
2020 PO0313354283	F	4	40 BRO	SP	CRE		V		1/2/2059
2020 PO0276453726	KU	4	40 BRO	SP	CRE	ED,ID,SRC,SRS	TD		1/3/2059
2020 PO0255853231	KU	4	45 BRO	SP	CRE	ED,ID,SRC,SRS	TD		1/4/2059
2020 PO0907571042	KU	4	40 BRO	SP	CRE	ID,IP	BD		1/5/2059
2020 PO0884571124	KU	4	40 BRO	SP	CRE	ID,IP	BD		1/6/2059
2020 PO1183656834	KU	4	45 ACW	SP	CRE	ED,ID,IP	TD		1/7/2059
2020 PO0265453462	KU	4	40 BRO	SP	CRE	ED,ID,SRC,SRS	TD		1/8/2059

2020 PO1178156715	KU	3	60 ACW	SP	CRE	ED,ID,IP	TD	1/9/2059	
2020 PO1076172232	KU	4	40 BRO	SP	CRE	ID,IP	BD	1/10/2059	
2020 PO0250753254	F	4	40 BRO	SP	CRE		V	1/11/2059	
2020 PO0235652756	KU	4	45 BRO	SP	CRE	ED,ID,SRC	TD	1/12/2059	
2020 PO0244552962	KU	4	45 BRO	SP	CRE	ED,ID,SRC,SRS	TD	1/13/2059	
2020 PO0226752544	KU	3	45 BRO	SP	CRE	ED,ID,SRC	TD	1/14/2059	
2020 PO1070071997	KU	4	40 BRO	SP	CRE	ID,IP	BD	1/15/2059	
2020 PO4752131098	KU	3	40 BRO	SP	CRE	ID	TD	1/16/2059	
2020 PO4752031121	KU	4	40 BRO	SP	CRE	ID,IP	BD	1/17/2059	
2020 PO4766731179	KU	4	40 BRO	SP	CRE	ED,IP	TD	1/18/2059	
2020 PO7401791861	KU	4	40 BRO	SP	CRE	ED,HH,ID,RB	X	PX	1/19/2059
2020 PO7461191305	KU	5	45 BRO	SP	CRE	ED,HH,ID,IP,RB	VX	RP2	1/20/2059
2020 PO7439291123	KU	1	75 BRO	SP	CRE		V		1/21/2059
2020 PO7456991346	KU	1	75 BRO	SP	CCA		V		1/22/2059
2020 PO7441391492	KU	2	65 BRO	SP	CRE		V		1/23/2059
2020 PO7301090721	KU	5	35 BRO	SP	CRE		V		1/24/2059
2020 PO7314590558	KU	5	35 BRO	SP	CCA		V		1/25/2059
2020 A	KU	6	30 INP	SP	CRE	ID	TD		1/26/2059
2020 PO8847824094	KU	6	30 UNK	SP	CRE	ID	TD		1/27/2059
2020 PO8947123890	KU	4	45 UNK	SP	CRE	ID	TD		1/28/2059
2020 PO8919923358	KU	6	30 UNK	SP	CRE	ID	TD		1/29/2059
2020 PO8923623448	KU	6	30 UNK	SP	CRE	ID	TD		1/30/2059
2020 PO1109457077	KU	4	40 ACW	SP	CRE	ED,ID	TD		1/31/2059
2020 PO8833723782	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD		2/1/2059
2020 PO1130556927	KU	4	40 ACW	SP	CRE	ED,ID	TD		2/2/2059
2020 PO1080157284	KU	4	45 ACW	SP	CCA		V		2/3/2059
2020 PO1082357339	F	4	40 ACW	SP	P		V		2/4/2059
2020 PO1066257298	KU	4	40 ACW	SP	CRE	ED,ID	TD		2/5/2059
2020 PO0673461642	KU	3	45 ACW	SP	P	SRS	T		2/6/2059
2020 PO1109270896	KU	4	45 BRO	SP	CRE	ID,IP	TD		2/7/2059
2020 PO1064671786	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		2/8/2059
2020 PO1094071305	F	5	35 BRO	SP	CRE		V		2/9/2059
2020 PO1093671409	KU	6	30 BRO	SP	CRE	ED	TD		2/10/2059
2020 PO1093571627	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD		2/11/2059
2020 PO1087771509	KU	4	40 BRO	SP	CRE	ID,IP	BD		2/12/2059
2020 PO1045657316	KU	4	40 ACW	SP	CRE	ED,ID	TD		2/13/2059
2020 PO1024757336	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		2/14/2059
2020 PO1005657357	KU	4	40 ACW	SP	CRE	ED,ID	TD		2/15/2059
2020 PO0966257397	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		2/16/2059
2020 PO8919124163	KU	5	35 UNK	SP	CRE	ID	TD		2/17/2059
2020 PO8903924031	KU	4	40 KOP	SP	CRE	ID	TD		2/18/2059
2020 PO8880724125	KU	5	35 UNK	SP	CRE	ID	TD		2/19/2059
2020 PO8929524113	KU	4	40 UNK	SP	CRE	ID	TD		2/20/2059
2020 PO8911524025	KU	5	35 UNK	SP	CRE	ID	TD		2/21/2059
2020 PO8915924315	KU	5	30 UNK	SP	CRE	ID	TD		2/22/2059
2020 PO8881424297	KU	4	40 UNK	SP	CRE	ID	TD		2/23/2059
2020 PO8855523833	KU	5	35 OTH	SP	CRE	ED,ID,SRC	TD		2/24/2059

2020 PO8905224188	KU	5	35 UNK	SP	CRE	ID	TD	2/25/2059	
2020 PO8934824051	KU	4	45 INP	SP	CRE	ID	TD	2/26/2059	
2020 PO8853224076	KU	5	35 UNK	SP	CRE	ID	BD	2/27/2059	
2020 PO8873024041	KU	6	30 OTH	SP	CRE	ED,ID,SRS	TD	2/28/2059	
2020 PO4798031044	KU	3	45 BRO	SP	CRE	ID	TD	3/1/2059	
2020 PO6971494306	KU	5	30 BRN	SP	CRE	ED,ID	TD	3/2/2059	
2020 PO6831294713	KU	6	30 BRO	SP	P	ED,ID	TD	3/3/2059	
2020 PO6837095001	KU	6	30 BRO	SP	P	ED,ID	TD	3/4/2059	
2020 PO7162391789	KU	5	35 BRO	SP	CRE	ED	T	3/5/2059	
2020 PO7632504587	KU	6	30 XXX	SP	CCA		V	3/6/2059	
2020 PO7194302481	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD	3/7/2059	
2020 PO7185302467	KU	3	45 XXX	SP	CCA		V	3/8/2059	
2020 PO7195402419	KU	6	30 XXX	SP	CRE		V	3/9/2059	
2020 PO7223002326	KU	5	35 XXX	SP	CCA		V	3/10/2059	
2020 PO7235402345	KU	5	35 XXX	SP	CCA		V	3/11/2059	
2020 PO7203602492	KU	6	30 XXX	SP	CRE		V	3/12/2059	
2020 PO7219302508	KU	5	30 XXX	SP	CRE		V	3/13/2059	
2020 PO3860537040	KU	5	35 BRO	SP	CRE	ED,IP,SRS	TD	3/14/2059	
2020 PO3872436995	KU	6	30 BRO	SP	CRE	ED,IP	TD	3/15/2059	
2020 PO3883336933	KU	6	30 BRO	SP	CRE	ED,ID	TD	3/16/2059	
2020 PO3894136870	KU	6	30 BRO	SP	CRE	ED,ID	TD	3/17/2059	
2020 PO3904936808	KU	5	30 BRO	SP	CRE	ED,ID,IP	TD	3/18/2059	
2020 PO3915836747	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	3/19/2059	
2020 PO6865093913	KU	5	30 BRN	SP	CRE	ED,ID,SR	TX	RR	3/20/2059
2020 PO6867493864	KU	4	40 BRN	SP	CRE	ED,ID	TD	3/21/2059	
2020 PO7219302566	F	4	40 XXX	SP	CRE		V	3/22/2059	
2020 PO7200502564	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD	3/23/2059	
2020 PO7197602517	KU	5	35 BRN	SP	CCA		V	3/24/2059	
2020 PO7190502560	F	4	40 CPT	SP	P		V	3/25/2059	
2020 PO7175702548	F	6	30 BRN	SP	CRE		V	3/26/2059	
2020 7026101658a	KU	4	40 BRN	SP	CRE	RB	X	RP1	3/27/2059
2020 PO7060801845	F	4	40 BRN	SP	CRE		V	3/28/2059	
2020 PO7040901724	KU	4	40 BRN	SP	CRE	ED,ID	TD	3/29/2059	
2020 PO7026101658	F	4	40 BRN	SP	CRE		V	3/30/2059	
2020 PO6839893722	KU	6	30 BRN	SP	A	ED,ID,IP	TD	3/31/2059	
2020 PO6857893741	KU	5	35 BRN	SP	CRE	ED,HH,ID	BX	PX	4/1/2059
2020 PO7022201552	KU	6	30 XXX	SP	CRE		V	4/2/2059	
2020 7006401580a	KU	6	30 XXX	SP	CRE	ED,ID	TD	4/3/2059	
2020 PO7006401580	F	4	40 XXX	SP	CRE	ID	B	4/4/2059	
2020 PO6875593744	KU	6	30 BRN	SP	CRE	ED,ID	BD	4/5/2059	
2020 PO7529893660	F	2	50 BRO	SP	CRE		V	4/6/2059	
2020 PO7871325500	KU	4	45 OTH	SP	CRE	ID	TD	4/7/2059	
2020 PO7540193806	F	3	50 BRO	SP	CCA		V	4/8/2059	
2020 PO7543894057	KU	4	40 BRO	SP	CRE		V	4/9/2059	
2020 PO7545494006	KU	6	30 BRO	SP	CRE		V	4/10/2059	
2020 PO7550893960	F	4	45 BRO	SP	CRE		V	4/11/2059	
2020 PO6975287804	KU	6	30 BRN	SP	CRE		V	4/12/2059	

2020 PO6972287854	KU	2	55 BRN	SP	CCA		V	4/13/2059
2020 PO6998388007	KU	3	55 BRN	SP	CRE		V	4/14/2059
2020 PO6973587912	KU	6	30 BRN	SP	CRE	ED,ID	TD	4/15/2059
2020 PO6983587974	KU	6	30 BRN	SP	CRE	ED,ID	TD	4/16/2059
2020 PO6985687916	KU	3	50 BRN	SP	CCA		V	4/17/2059
2020 PO7559694088	F	4	40 BRO	SP	CRE		V	4/18/2059
2020 PO7569694106	KU	4	30 BRO	SP	CRE	ED,ID	TD	4/19/2059
2020 PO7589494426	F	5	35 BRO	SP	CRE		V	4/20/2059
2020 PO7563894147	F	4	40 BRO	SP	CRE		V	4/21/2059
2020 PO7589194101A	KU	3	45 BRO	SP	CCA		V	4/22/2059
2020 PO7589194101	KU	4	40 BRO	SP	CRE		V	4/23/2059
2020 PO5378407831	KU	4	40 XXX	SP	CRE	ED,ID	TD	4/24/2059
2020 PO5385207791	F	3	40 BRN	SP	P		V	4/25/2059
2020 PO5394707831	KU	5	35 BRN	SP	CCA		V	4/26/2059
2020 PO7602094504	KU	4	45 BRO	SP	P	ID	BD	4/27/2059
2020 PO7611894575	F	3	45 BRO	SP	CRE		V	4/28/2059
2020 PO7615094555	KU	4	40 BRO	SP	CRE		V	4/29/2059
2020 PO5403207891	KU	5	35 BRN	SP	CRE	ED,ID	TD	4/30/2059
2020 PO5409707876	KU	4	45 BRN	SP	CCA		V	5/1/2059
2020 PO5417707809	KU	6	30 BRN	SP	CCA		V	5/2/2059
2020 PO5415307795	KU	3	50 BRN	SP	CCA		V	5/3/2059
2020 PO5413107719	KU	5	35 ACW	SP	CRE	ED,ID	TD	5/4/2059
2020 PO5404607761	KU	4	35 ACW	SP	CRE	ID	BD	5/5/2059
2020 PO5400907704	KU	4	45 BRN	SP	CCA		V	5/6/2059
2020 PO7341586136	KU	4	40 BRN	SP	CRE	ED,ID	BD	5/7/2059
2020 PO7324386348	KU	4	45 BRN	SP	CRE	ED,ID	TD	5/8/2059
2020 PO7315886596	KU	2	55 BRN	SP	CCA		V	5/9/2059
2020 PO7634194498	KU	5	35 BRO	SP	CCA		V	5/10/2059
2020 PO7621994388	KU	4	40 BRO	SP	CRE	ID	BD	5/11/2059
2020 PO7917225572	KU	4	40 ACW	SP	CRE	ID	TD	5/12/2059
2020 PO7900125238	KU	4	40 KOP	SP	CCA		V	5/13/2059
2020 PO7919025469	KU	4	40 ACW	SP	CRE	ID	TD	5/14/2059
2020 PO7884625365	KU	4	40 BRN	SP	CRE	ID	TD	5/15/2059
2020 PO7897725507	KU	6	30 BRN	SP	CCA		V	5/16/2059
2020 PO7917225367	KU	4	40 ACW	SP	CRE	ED,ID,SRS	TD	5/17/2059
2020 PO7895625363	KU	4	40 ACW	SP	CRE	ED,ID,SRS	TD	5/18/2059
2020 PO7871325320	KU	4	40 ACW	SP	CRE	ID	TD	5/19/2059
2020 PO3973983089	F	6	25 BRN	SP	CRE		V	5/20/2059
2020 PO3972683083	LGE	4	25 BRN	SP	S		V	5/21/2059
2020 PO3972883079	F	4	40 BRN	SP	CRE		V	5/22/2059
2020 PO3973083071	F	4	45 BRN	SP	CRE		V	5/23/2059
2020 PO4056842572	KU	5	35 ACE	SP	CRE	ED,ID	BD	5/24/2059
2020 PO4023442786	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	5/25/2059
2020 PO2189737617	KU	4	40 BRO	SP	P	ED	T	5/26/2059
2020 PO2187837663	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	5/27/2059
2020 PO3927482548	LGE	4	40 BRN	SP	CRE	ED,ID	BD	5/28/2059
2020 PO7624094375	KU	4	45 BRO	SP	CRE	ID	BD	5/29/2059

2020 PO7614094034	KU	6	30 BRO	SP	P		B	5/30/2059
2020 PO7627094690	F	4	45 BRO	SP	CRE		V	5/31/2059
2020 PO7634394744	F	4	45 BRO	SP	P		V	6/1/2059
2020 PO7640294788	F	3	45 BRO	SP	CRE		V	6/2/2059
2020 PO7635194323	KU	6	30 BRO	SP	CRE		B	6/3/2059
2020 PO7297586978	KU	6	30 BRN	SP	CRE		V	6/4/2059
2020 PO7652795090	KU	4	45 BRO	SP	P		B	6/5/2059
2020 PO5348207530	KU	5	30 XXX	SP	CRE	ED,ID	TD	6/6/2059
2020 PO5364707735	KU	5	30 KOP	SP	CRE	ED,ID	TD	6/7/2059
2020 PO5354007694	KU	5	30 XXX	SP	CRE	ED,ID	TD	6/8/2059
2020 PO5345007635	KU	4	45 XXX	SP	CRE	ED,ID	TD	6/9/2059
2020 PO5333807543	KU	4	40 XXX	SP	CRE	ED,ID	TD	6/10/2059
2020 PO5322307485	KU	6	30 XXX	SP	CRE	ED,ID	TD	6/11/2059
2020 PO7649995069	KU	4	45 BRO	SP	CRE		B	6/12/2059
2020 PO7637794977	KU	4	45 BRO	SP	CRE	ID	BD	6/13/2059
2020 PO7631694930	KU	4	40 BRO	SP	CRE	ID	BD	6/14/2059
2020 PO7679595296A	KU	4	45 BRO	SP	CCA		V	6/15/2059
2020 PO7307186839	KU	4	45 BRN	SP	CRE	ED,ID,RB	TX	RR 6/16/2059
2020 PO7167288032-A	KU	2	55 BRN	SP	CCA		V	6/17/2059
2020 PO7177888074	KU	2	55 BRN	SP	P		V	6/18/2059
2020 PO7167288032	KU	2	55 BRN	SP	P		V	6/19/2059
2020 PO7679595296	KU	4	45 BRO	SP	CRE		V	6/20/2059
2020 PO7670095226	KU	4	45 BRO	SP	CRE	ID	BD	6/21/2059
2020 PO7651094871	F	3	45 BRO	SP	CRE		V	6/22/2059
2020 PO7681795052	F	4	40 BRO	SP	CRE		V	6/23/2059
2020 PO7668794782	KU	6	30 BRO	SP	CCA		V	6/24/2059
2020 PO7662394883	F	4	45 BRO	SP	CRE		V	6/25/2059
2020 PO0511559460	KU	3	45 ACW	SP	CCA		V	6/26/2059
2020 PO0511159376	KU	4	45 ACW	SP	CCA		V	6/27/2059
2020 PO0482158750	KU	4	40 ACW	SP	CCA		V	6/28/2059
2020 PO0531160058	F	4	35 BRN	SP	A		V	6/29/2059
2020 PO0536660206	F	4	35 BRN	SP	P		V	6/30/2059
2020 PO0541860322	F	4	35E BRN	SP	A		V	7/1/2059
2020 PO0645962742	F	6	30E BRN	SP	P		V	7/2/2059
2020 PO0640362831	F	6	30E BRN	SP	P		V	7/3/2059
2020 PO1277345846	KU	6	35 BRN	SP	CRE	ED,ID	BD	7/4/2059
2020 PO1591345430-A	KU	6	30 BRN	SP	CRE	ID	TD	7/5/2059
2020 PO0411753281	KU	5	35 BRO	SP	CRE	ID	BD	7/6/2059
2020 PO0374351683	KU	4	40 BRO	SP	CCA		V	7/7/2059
2020 PO0335650976	KU	4	40 BRO	SP	CRE	ID	BD	7/8/2059
2020 PO7064188609	KU	3	50 BRO	SP	CRE	ED,ID	BD	7/9/2059
2020 PO7076488523	KU	3	50 BRO	SP	CCA		B	7/10/2059
2020 PO7080888597	KU	5	35 BRO	SP	CRE	ED,ID	BD	7/11/2059
2020 PO8198771594	KU	4	45 BRO	SP	CRE	ED,ID	TD	7/12/2059
2020 PO7070288549	KU	3	50 BRO	SP	CRE	ED,ID	BD	7/13/2059
2020 PO8244371990	KU	4	40 BRO	SP	CRE		V	7/14/2059
2020 PO8216071872	KU	3	45 BRO	SP	CRE	ED,ID	TD	7/15/2059

2020 PO8223371960	KU	3	50 BRO	SP	CRE	ED,ID	BD		7/16/2059
2020 PO4702599765	KU	6	30 BRO	SP	CRE	ED,ID	X	RP1	7/17/2059
2020 PO7059588682	KU	4	40 BRO	SP	CRE		V		7/18/2059
2020 PO7064088745	KU	4	45 BRO	SP	CRE	ED,ID	BD		7/19/2059
2020 PO7067888714	KU	5	35 BRO	SP	CRE	ED,ID	BD		7/20/2059
2020 PO7057588655	KU	2	45 BRO	SP	CRE	ED,ID	BD		7/21/2059
2020 PO4708299531	KU	4	40 BRO	SP	CRE	ID	TD		7/22/2059
2020 PO8417667519	KU	6	30 BRO	SP	CRE	ED,ID	BD		7/23/2059
2020 PO6564770364	KU	6	30 BRN	SP	CRE	ED,ID	TD		7/24/2059
2020 PO6550470380	KU	4	40 BRN	SP	CRE	ED,ID	BD		7/25/2059
2020 PO4698599564	KU	5	35 BRO	SP	CRE	ID	TD		7/26/2059
2020 PO4725799770	KU	5	35 BRO	SP	CRE	ID	BD		7/27/2059
2020 PO4710299706	KU	6	30 BRO	SP	CRE	ID	TD		7/28/2059
2020 PO4697300074	KU	5	35 BRO	SP	CRE	ID	TD		7/29/2059
2020 PO8403767374A	KU	6	30 BRO	SP	A	ED,ID	TD		7/30/2059
2020 PO6475370777	KU	4	40 BRN	SP	CRE	ED,ID	BD		7/31/2059
2020 PO6501470846	KU	4	40 BRN	SP	CRE	ED,ID	BD		8/1/2059
2020 PO6543271345	KU	4	40 BRN	SP	CRE	ED,ID	BD		8/2/2059
2020 PO6523871385	KU	5	35 BRN	SP	CRE	ED,HH,ID	BX	PX	8/3/2059
2020 PO6564171179	KU	4	40 BRN	SP	CRE	ED,ID	TD		8/4/2059
2020 PO4789804258	KU	3	50 XXX	SP	CCA		V		8/5/2059
2020 PO7055688668	KU	4	40 BRO	SP	CRE	ED,ID	BD		8/6/2059
2020 PO0487224331	KU	5	35 BRO	SP	CRE	ED,EP,ID,IP	BX	RP2	8/7/2059
2020 PO7050488755	F	4	40 BRO	SP	CRE		V		8/8/2059
2020 PO7045988719	KU	3	40 BRO	SP	CRE	ED,ID	BD		8/9/2059
2020 PO7046588777	KU	3	50 BRO	SP	CCA		B		8/10/2059
2020 PO7044288838	KU	3	45 BRO	SP	CRE	ED,ID,IP	BD		8/11/2059
2020 PO7038788768	KU	4	35 BRO	SP	CRE	ED,ID	BD		8/12/2059
2020 PO7052588868	KU	5	35 BRO	SP	CCA		V		8/13/2059
2020 PO7039088828	KU	3	50 BRO	SP	CCA		B		8/14/2059
2020 PO7032588872	KU	3	50 BRO	SP	CCA		V		8/15/2059
2020 PO7026388808	KU	4	40 BRO	SP	CRE	ED,ID	BD		8/16/2059
2020 PO7029388852	KU	3	50 BRO	SP	CCA		B		8/17/2059
2020 PO7036488932	KU	5	35 BRO	SP	CRE	ED,ID	BD		8/18/2059
2020 PO7028888956	KU	5	35 BRO	SP	CRE	ED,ID	BD		8/19/2059
2020 PO7025488935	F	5	35 BRO	SP	CRE		V		8/20/2059
2020 PO0612161628	KU	5	35 BRN	SP	CCA		V		8/21/2059
2020 PO0600061756	F	4	40 BRN	SP	P		V		8/22/2059
2020 PO0605061871	F	3	45 BRN	SP	P	ED,ID	V		8/23/2059
2020 PO9518293565	KU	6	30 BRO	SP	CRE	ED,ID	TD		8/24/2059
2020 PO9523193710	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		8/25/2059
2020 PO9526993608	F	9	20 BRO	SP	CRE		V		8/26/2059
2020 PO9560293787	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		8/27/2059
2020 PO9582793812	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		8/28/2059
2020 PO9610293877	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD		8/29/2059
2020 PO9602293648	KU	4	40 BRO	SP	CRE	ED,ID	BD		8/30/2059
2020 PO9597193462	KU	4	40 BRO	SP	CRE	ED,ID	TD		8/31/2059

2020 PO9271780266	KU	4	40 OTH	SP	CRE	ID,IP	BD		9/1/2059
2020 PO9271080595	KU	4	40 OTH	SP	CRE	ID,IP	BD		9/2/2059
2020 PO9271280497	KU	4	40 OTH	SP	CRE	RB	X	RP1	9/3/2059
2020 PO9258580335	KU	4	40 OTH	SP	CRE	RB	X	RP1	9/4/2059
2020 PO9283980507	KU	4	40 OTH	SP	CCA		V		9/5/2059
2020 PO9299880398	KU	4	40 OTH	SP	CCA		V		9/6/2059
2020 PO9268181045	KU	3	45 OTH	SP	CRE		V		9/7/2059
2020 PO9268280990	KU	4	40 OTH	SP	CRE	RB	X	RP1	9/8/2059
2020 PO0603761839	F	4	40 BRN	SP	CRE		V		9/9/2059
2020 PO0596261975	KU	4	40 BRN	SP	CCA		V		9/10/2059
2020 PO0582862034	F	4	40 BRN	SP	CRE		V		9/11/2059
2020 PO0567662025	KU	4	35E BRN	SP	CRE		V		9/12/2059
2020 PO0562161902	KU	3	45 BRN	SP	CCA		V		9/13/2059
2020 PO0559261066	KU	6	30 BRN	SP	CRE	ID,IP	BD		9/14/2059
2020 PO0588760948	KU	4	40 BRN	SP	CRE	ID,IP	TD		9/15/2059
2020 PO0539561940	KU	4	45 BRN	SP	CRE	ID,IP	BD		9/16/2059
2020 PO0608461583	F	5	35 BRN	SP	CRE		V		9/17/2059
2020 PO0547761906	KU	4	45 BRN	SP	CRE	ID	BD		9/18/2059
2020 PO0554261719	KU	4	40 BRN	SP	CRE	ID,IP	TD		9/19/2059
2020 PO0557761800	KU	4	40 BRN	SP	CRE	ID,IP	TD		9/20/2059
2020 PO0584961739	KU	5	35 BRN	SP	CRE	ID,IP	TD		9/21/2059
2020 PO0604561717	KU	3	50 BRN	SP	CRE	ID	BD		9/22/2059
2020 PO0597661563	KU	3	45 BRN	SP	CRE	ID	TD		9/23/2059
2020 PO0587761323	KU	3	45 BRN	SP	CRE	ID	TD		9/24/2059
2020 PO0582561344	KU	6	30 BRN	SP	CRE	ID,IP	TD		9/25/2059
2020 PO0575061019	KU	2	45 BRN	ST	CCA		V		9/26/2059
2020 PO0552361113	KU	3	45 BRN	SP	CCA		V		9/27/2059
2020 PO0564760752	KU	4	45 BRN	SP	CRE	ID	TD		9/28/2059
2020 PO0572560955	KU	3	45 BRN	SP	CRE	ID	TD		9/29/2059
2020 PO0577261072	KU	3	45 BRN	SP	CRE	ID	TD		9/30/2059
2020 PO0610060798	KU	4	40 BRN	SP	CRE	ID,IP	TD		10/1/2059
2020 PO0602960888	KU	5	40 BRN	SP	CRE	ED,IP	TD		10/2/2059
2020 PO0602960888-A	KU	5	35 BRN	SP	P	ED	TD		10/3/2059
2020 PO0569960888	KU	4	45 BRN	SP	CRE	HH,ID,RB	X	RP1	10/4/2059
2020 PO0569561034	F	4	40 BRN	SP	A		V		10/5/2059
2020 PO0567260977	F	5	35 BRN	SP	CRE		V		10/6/2059
2020 PO0562660853	F	5	35E BRN	SP	CRE		V		10/7/2059
2020 PO0558160735	F	5	35E BRN	SP	CRE		V		10/8/2059
2020 PO0621625451	KU	4	45 BRO	SP	CRE	ID	BD		10/9/2059
2020 PO0428426719	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		10/10/2059
2020 PO0410727090	KU	4	40 BRO	SP	CRE	ED,ID	BD		10/11/2059
2020 PO0448927651	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		10/12/2059
2020 PO0466427891	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		10/13/2059
2020 PO0701527394	KU	4	45 BRO	SP	CRE	ED,ID,SRS	TD		10/14/2059
2020 PO0712127331	KU	6	30 BRO	SP	CRE	ED,ID,SRS	TD		10/15/2059
2020 PO0673125883	KU	4	45 BRO	SP	CRE	ID	BD		10/16/2059
2020 PO0730927882	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD		10/17/2059

2020 PO0491528060	KU	4	40 BRO	SP	CRE	ED,ID	BD	10/18/2059
2020 PO0505726215	KU	4	40 BRO	SP	CCA		V	10/19/2059
2020 PO0520026088	KU	4	40 BRO	SP	CCA		V	10/20/2059
2020 PO0756128296	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD	10/21/2059
2020 PO0782428717	KU	4	40 BRO	SP	CRE	ED,EP	BX	10/22/2059
2020 PO0421423946	KU	6	30 BRO	SP	CRE	ED,ID	TD	10/23/2059
2020 PO0440123880	KU	4	40 BRO	SP	CRE	ED,ID	TD	10/24/2059
2020 PO0463923739	KU	4	40 BRO	SP	CRE	ED,ID	TD	10/25/2059
2020 PO0877129912	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD	10/26/2059
2020 PO0875230156	KU	4	40 BRO	SP	CRE	ID	BD	10/27/2059
2020 PO0458223548	KU	4	40 APL	SP	CRE	ED,ID	TD	10/28/2059
2020 PO0447823529a	KU	6	30 APL	SP	CRE	ED,ID	TD	10/29/2059
2020 PO0566925435	F	4	40 BRO	SP	CRE		V	10/30/2059
2020 PO0509925789	KU	4	40 BRO	SP	CCA		V	10/31/2059
2020 PO0525325899	KU	4	40 BRO	SP	CCA		V	11/1/2059
2020 PO0497526240	F	4	40 BRO	SP	CRE		V	11/2/2059
2020 PO0941429147	KU	4	40 BRO	SP	CRE	ED,ID,IP,SRS	TD	11/3/2059
2020 PO0442023470	KU	4	45 APL	SP	CRE	ED,ID	TD	11/4/2059
2020 PO0430423384	KU	4	40 APL	SP	CRE	ED,ID	TD	11/5/2059
2020 PO0422023179	KU	4	40 APL	SP	CRE	ED,ID	TD	11/6/2059
2020 PO9610282527	KU	4	40 BRO	SP	CCA		V	11/7/2059
2020 PO9606783526	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	11/8/2059
2020 PO9606783526	KU	5	35 BRO	SP	CRE	ID,IP	BD	11/9/2059
2020 PO9637083459	KU	5	35 BRO	SP	CRE	ID,IP	BD	11/10/2059
2020 PO9612083757	KU	4	40 BRO	SP	CRE	ID	BD	11/11/2059
2020 PO9635183657	KU	4	40 BRO	SP	CRE	ID	BD	11/12/2059
2020 PO9650883975	KU	4	40 BRO	SP	CRE	ID,IP	BD	11/13/2059
2020 PO9618384041	KU	4	40 BRO	SP	CRE	ED	X	11/14/2059
2020 PO9591684141	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	11/15/2059
2020 PO9594084097	KU	5	35 BRO	SP	CRE	ID,IP	BD	11/16/2059
2020 PO9608284192	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	11/17/2059
2020 PO4699288181	LGE	4	40 BRO	SP	A	ID	BD	11/18/2059
2020 PO4698688177	LGE	4	35 BRO	SP	A	ID	TD	11/19/2059
2020 PO4697388173	LGE	4	35 BRO	SP	A	ID,SRS	TD	11/20/2059
2020 PO9601084260	KU	6	30 BRO	SP	CRE	ID,IP	BD	11/21/2059
2020 PO4696888181	LGE	4	35 BRO	SP	A	ID,SRS	TD	11/22/2059
2020 PO4570801660	F	6	30 KOP	SP	CCA		V	11/23/2059
2020 PO4745798871	F	4	40 XXX	SP	CRE		V	11/24/2059
2020 PO4702498810	KU	6	30 BRN	SP	CCA		V	11/25/2059
2020 PO4712298895	F	4	40E XXX	SP	CRE	ED	V	11/26/2059
2020 PO4678199119	F	4	40E OTH	SP	CRE		V	11/27/2059
2020 PO4685999122	F	4	40 OTH	SP	CRE		V	11/28/2059
2020 PO4709499266	F	4	40E XXX	SP	CRE		V	11/29/2059
2020 PO4728299224	F	5	35E XXX	SP	CRE		V	11/30/2059
2020 PO4673499581	F	4	40 KOP	SP	CRE		V	12/1/2059
2020 PO4679499548	F	6	30 XXX	SP	CRE		V	12/2/2059
2020 PO4698599717	F	6	30 XXX	SP	CRE		V	12/3/2059

2020 PO4690599712	F	4	40 INP	SP	CRE		V		12/4/2059
2020 PO4687799782	F	4	40 XXX	SP	CRE		V		12/5/2059
2020 PO4685799888	F	4	40E XXX	SP	CRE		V		12/6/2059
2020 PO4675899880	F	6	30 OTH	SP	CRE		V		12/7/2059
2020 PO4697888191	LGE	4	35 BRO	SP	A	ID,SRS		TD	12/8/2059
2020 PO4698788197	LGE	4	40 BRO	SP	A	ID,SRS		TD	12/9/2059
2020 PO5662084505	LGE	5	40 UNK	SP	CRE	ID,SRS		TD	12/10/2059
2020 PO4659399658	LGE	3	45 UNK	SP	CCA		V		12/11/2059
2020 PO0185791563	LGE	5	40 UNK	SP	CRE		V		12/12/2059
2020 PO4697699963	F	4	40E XXX	SP	CRE		V		12/13/2059
2020 PO4629599969	F	4	40 BRN	SP	CRE		V		12/14/2059
2020 PO4633400555	F	5	35 INP	SP	CRE		V		12/15/2059
2020 PO4655200788	F	6	30 OTH	SP	CRE		V		12/16/2059
2020 PO4608701661	F	5	35E XXX	SP	CRE	ED,HH,ID,RB		BX	12/17/2059
2020 PO4625201890	F	4	40E INP	SP	CRE		V		12/18/2059
2020 PO4609601818	F	4	40E ESC	SP	CRE		V		12/19/2059
2020 PO4552501542	F	4	40 KOP	SP	CRE		V		12/20/2059
2020 PO4541601330	F	3	40E INP	SP	CRE		V		12/21/2059
2020 PO4585402061	F	6	30E ACW	SP	CRE		V		12/22/2059
2020 PO4541202157	F	6	30 ACW	SP	CRE		V		12/23/2059
2020 PO4494401913A	KU	6	30 KOP	SP	CCA		V		12/24/2059
2020 PO4514401932	F	5	40 KOP	SP	CRE		V		12/25/2059
2020 PO4526102037	F	4	40E OTH	SP	CRE		V		12/26/2059
2020 PO4556502156	F	4	40E OTH	SP	CRE		V		12/27/2059
2020 PO4573102207	F	4	40E OTH	SP	CRE		V		12/28/2059
2020 PO4597202957	F	4	40E OTH	SP	CRE		V		12/29/2059
2020 PO4602203075	F	2	45 OTH	SP	CRE		V		12/30/2059
2020 PO4646403007	F	6	30 OTH	SP	CRE		V		12/31/2059
2020 PO4635802969	F	5	35 OTH	SP	CRE		V		1/1/2060
2020 PO4624002933	F	4	40 OTH	SP	CRE		V		1/2/2060
2020 PO4202002507A	F	4	45 BRN	SP	CRE		V		1/3/2060
2020 PO4430902713	F	3	40 OTH	SP	CRE		V		1/4/2060
2020 PO4416902758	F	3	40 OTH	SP	CRE		V		1/5/2060
2020 PO4401102695	F	3	40 OTH	SP	CRE		V		1/6/2060
2020 PO4390802583	F	4	40 OTH	SP	CRE		V		1/7/2060
2020 PO4383302627	KU	6	30 BRN	SP	CCA		V		1/8/2060
2020 PO4377602687	KU	4	40 BRN	SP	CCA		V		1/9/2060
2020 PO4248902077	F	4	45 BRN	SP	CRE		V		1/10/2060
2020 PO4234902208	F	4	45 BRN	SP	CRE		V		1/11/2060
2020 PO4228801659	F	3	40 BRN	SP	P		V		1/12/2060
2020 PO7896771839	KU	5	35 BRO	SP	CRE	HH,ID		BX	1/13/2060
2020 PO7906671176	KU	5	35 BRO	SP	CRE	ID		BD	1/14/2060
2020 PO7926570985	F	4	40 BRO	SP	CRE		V		1/15/2060
2020 PO7893371561	F	4	40 BRO	SP	CRE		V		1/16/2060
2020 PO7899171461	F	3	45 BRO	SP	CRE		V		1/17/2060
2020 PO7913571210	F	3	45 BRO	SP	CRE		V		1/18/2060
2020 PO7938070782	F	4	40 BRO	SP	CRE		V		1/19/2060

2020 PO7949870576	F	4	40 BRO	SP	CRE		V		1/20/2060
2020 PO7961170381	F	4	40 BRO	SP	CRE		V		1/21/2060
2020 PO7960170282	KU	5	35 BRO	SP	CCA		V		1/22/2060
2020 PO7871471663	KU	4	40 BRO	SP	CRE	ID	BD		1/23/2060
2020 PO4851204414	KU	9	25 XXX	SP	CRE	ED,ID	TD		1/24/2060
2020 PO4852404486	KU	5	30 XXX	SP	CRE	ED,ID	TD		1/25/2060
2020 PO4845704462	KU	5	40 XXX	SP	CRE	ED,ID	TD		1/26/2060
2020 PO4854604633	KU	4	40 XXX	SP	CRE	ED,ID	TD		1/27/2060
2020 PO4802004353	KU	4	40 XXX	SP	CRE	ED,ID	TD		1/28/2060
2020 PO7406880386	KU	4	45 BRN	SP	CCA		V		1/29/2060
2020 PO5080206860	KU	4	40 XXX	SP	CRE	ED,ID	TD		1/30/2060
2020 PO5090106811	KU	6	30 XXX	SP	CRE	ED,ID	TD		1/31/2060
2020 PO5093806910	KU	4	40 XXX	SP	CRE	ED,ID	TD		2/1/2060
2020 PO5110106951	KU	5	35 XXX	SP	CRE	ED,ID	TD		2/2/2060
2020 PO5117806972	KU	5	30 XXX	SP	CRE	ED,ID	TD		2/3/2060
2020 PO7590880568	F	4	45 BRN	SP	CRE		V		2/4/2060
2020 PO7595180580	F	6	30 BRN	SP	CRE		V		2/5/2060
2020 PO7591280538	KU	3	45 BRN	SP	CCA		V		2/6/2060
2020 PO7607280581	KU	3	45 BRN	SP	CCA		V		2/7/2060
2020 PO7616980606	KU	5	35 BRN	SP	CCA		V		2/8/2060
2020 PO7602880011	KU	2	50 BRN	SP	CRE	ED,ID	BD		2/9/2060
2020 PO7612580284	KU	5	35 BRN	SP	CCA		V		2/10/2060
2020 PO7595080270	KU	4	45 BRN	SP	CCA		V		2/11/2060
2020 PO7608080313	KU	4	40 BRN	SP	CRE	ED,ID	BD		2/12/2060
2020 PO7623480089-A	KU	6	30 BRN	SP	CRE	ED,ID	TD		2/13/2060
2020 PO7623480089	KU	6	30 BRN	SP	CRE	ED,ID,IP	BD		2/14/2060
2020 PO7617879887a	KU	4	40 BRN	SP	CRE	ED,EP,ID	TX	RR	2/15/2060
2020 PO7605679916	KU	4	45 BRN	SP	CRE	ED,ID	TD		2/16/2060
2020 PO7646079772	KU	4	45 BRN	SP	CRE		V		2/17/2060
2020 PO7644379730	KU	5	35 BRN	SP	CRE		V		2/18/2060
2020 PO7617879887	KU	3	40 BRN	SP	CRE	ED,HH,ID,RB	VX	PX	2/19/2060
2020 PO7627979850	KU	3	55 BRN	SP	CRE	ED,ID	TD		2/20/2060
2020 PO7632779812	KU	5	35 BRN	SP	CRE		V		2/21/2060
2020 PO7609379775	KU	4	45 BRN	SP	CRE	ED,ID	TD		2/22/2060
2020 PO1071970715	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		2/23/2060
2020 PO9472053726	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD		2/24/2060
2020 PO9460053471	KU	5	35 BRO	SP	CRE	ED,ID,SRC	TX	RR	2/25/2060
2020 PO9063251805	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD		2/26/2060
2020 PO2350558908	KU	4	45E BRN	SP	CRE	ID,IP	BD		2/27/2060
2020 PO2353759058	F	4	40 BRN	SP	P		V		2/28/2060
2020 PO2360959027	KU	3	45 BRN	SP	CRE	IP,RB	BX	RR	2/29/2060
2020 PO9104351817	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD		3/1/2060
2020 PO9085551807	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD		3/2/2060
2020 PO9119751909	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD		3/3/2060
2020 PO2439760171	KU	4	45 BRN	SP	CRE	ID,IP	TD		3/4/2060
2020 PO2445559868	KU	4	40 BRN	SP	CRE		V		3/5/2060
2020 PO2479059800	KU	4	40 BRN	SP	CRE	ID	TD		3/6/2060

2020 PO0771861973	KU	2	50 ACW	SP	CCA		V	3/7/2060
2020 PO0768561865	KU	3	45 ACW	SP	CCA		V	3/8/2060
2020 PO0762961663	KU	3	45 ACW	SP	CCA		V	3/9/2060
2020 PO0747761394	KU	3	45 ACW	SP	CCA		V	3/10/2060
2020 PO0748161359	KU	2	50 ACW	SP	CCA		V	3/11/2060
2020 PO0744261205	KU	4	40 ACW	OT	CRE	ED,ID	BD	3/12/2060
2020 PO0796661440	F	4	40 ACW	SP	CRE		V	3/13/2060
2020 PO0737460977	KU	4	40 ACW	SP	CRE	ED,ID	BD	3/14/2060
2020 PO0736260914	KU	3	50 ACW	SP	CCA		V	3/15/2060
2020 PO0732360784	F	7	20 ACW	SP	CRE		V	3/16/2060
2020 PO0741160857	KU	4	45 ACW	SP	CCA		V	3/17/2060
2020 PO9331218286	KU	4	40 BRN	SP	CCA		V	3/18/2060
2020 PO9294818612	KU	6	30 OTH	SP	CRE	ID	TD	3/19/2060
2020 PO9274618504	KU	3	45 BRN	SP	CCA		V	3/20/2060
2020 PO9287118369	KU	5	35 OTH	SP	CRE		V	3/21/2060
2020 PO9391418080	KU	6	30 INP	SP	CRE	ID	TD	3/22/2060
2020 PO3941082855	LGE	4	35 BRO	SP	CRE		V	3/23/2060
2020 PO3942482848	LGE	4	35 BRO	SP	CRE		V	3/24/2060
2020 PO3942382849	LGE	4	30 BRO	SP	CRE		V	3/25/2060
2020 PO3943682845	LGE	4	35 BRO	SP	CRE		V	3/26/2060
2020 PO3944582835	LGE	4	35 BRO	SP	CRE		V	3/27/2060
2020 PO3942982800	LGE	4	40 BRO	SP	P		V	3/28/2060
2020 PO3943782815	LGE	4	35 BRO	SP	CRE		V	3/29/2060
2020 PO3944482822	LGE	4	35 BRO	SP	CCA		V	3/30/2060
2020 PO3944782820	LGE	2	55 BRO	SP	CCA		V	3/31/2060
2020 PO3996883077	LGE	4	40 BRN	SP	A	ED,ID	TD	4/1/2060
2020 PO3925182540	LGE	4	45 BRN	SP	P	ED,ID	TD	4/2/2060
2020 PO3925282534	LGE	4	35 BRN	SP	CCA		V	4/3/2060
2020 PO2656350294	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/4/2060
2020 PO3995883087	LGE	4	40 BRN	SP	CRE	ED,ID	TD	4/5/2060
2020 PO3997383099	LGE	6	25 BRN	SP	CRE	ED,ID	TD	4/6/2060
2020 PO4067144423	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	4/7/2060
2020 PO4061644306	KU	4	40 ACE	SP	CCA		V	4/8/2060
2020 PO4055744179	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	4/9/2060
2020 PO3927082573	F	6	25 BRN	SP	CRE		V	4/10/2060
2020 PO3926582566	F	4	40 BRN	SP	CRE		V	4/11/2060
2020 PO3925382574	F	4	40 BRN	SP	CRE		V	4/12/2060
2020 PO1149632897	ODP	4	50 XXX	SP	CRE	ED,ID	TD	4/13/2060
2020 PO3924182582	F	4	40 BRN	SP	P		V	4/14/2060
2020 PO3922882590	F	4	40 BRN	SP	CRE		V	4/15/2060
2020 PO1149832782	ODP	4	35 XXX	SP	CRE	ED,ID	TD	4/16/2060
2020 PO3921582598	F	4	40 BRN	SP	P		V	4/17/2060
2020 PO3920482606	LGE	4	40 BRN	SP	CRE	ED,ID	TD	4/18/2060
2020 PO1130534031	ODP	4	30 BRN	SP	CRE	ID,SRS	TD	4/19/2060
2020 PO3944682815	LGE	4	40 BRO	SP	CCA		V	4/20/2060
2020 PO3943982804	LGE	3	50 BRO	SP	CCA		V	4/21/2060
2020 PO3943382791	LGE	3	45 BRO	SP	CCA		V	4/22/2060

2020 PO3942282771	LGE	3	45 BRO	SP	CCA		V		4/23/2060
2020 PO3943382794	LGE	2	45 BRO	SP	CCA		V		4/24/2060
2020 PO3941782761	LGE	3	50 BRO	SP	P	ED,ID	TD		4/25/2060
2020 PO3926482837	LGE	4	35 BRO	SP	P	RB	VX	RP1	4/26/2060
2020 PO2632749971	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		4/27/2060
2020 PO3918982614	LGE	4	40 BRN	SP	CRE	ED,ID	TD		4/28/2060
2020 PO2885036491	KU	4	40 BRN	SP	CRE	ID,IP	BD		4/29/2060
2020 PO2891536307	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		4/30/2060
2020 PO2928335853	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD		5/1/2060
2020 PO1135134288A	ODP	6	30 BRN	SP	CCA		V		5/2/2060
2020 PO1135134288	ODP	4	45 OTH	SP	CRE	ID,SRS	TD		5/3/2060
2020 PO3996583099	LGE	4	40 BRN	SP	A	ED,ID	TD		5/4/2060
2020 PO2616849747	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD		5/5/2060
2020 PO2594749543	KU	4	40 BRO	SP	CRE	ED	TD		5/6/2060
2020 PO1110834434	ODP	6	30 OTH	SP	CRE	ID	TD		5/7/2060
2020 PO3927082867	LGE	5	35 BRO	SP	CCA		VX	RP1	5/8/2060
2020 PO6468740139	LGE	4	35 BRO	SP	CCA		V		5/9/2060
2020 PO3917082626	LGE	4	40 BRN	SP	P	ED,ID	T		5/10/2060
2020 PO3915182633	LGE	4	30 BRN	SP	CRE	ED,ID	BD		5/11/2060
2020 PO4048044016	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD		5/12/2060
2020 PO4042043889	KU	4	45 ACE	SP	CRE	ED,ID,IP	TD		5/13/2060
2020 PO4041543731	KU	3	45 ACE	SP	CCA		V		5/14/2060
2020 PO3915882634	LGE	4	40 BRN	SP	CRE	ED,ID	TD		5/15/2060
2020 PO1124434414	ODP	5	35 OTH	SP	CRE	ID	TD		5/16/2060
2020 PO1169632991	ODP	5	35 XXX	SP	CRE	ED,ID	TD		5/17/2060
2020 PO1169932905	ODP	3	50 XXX	SP	CRE	ID	BD		5/18/2060
2020 PO1187032918	ODP	3	50 XXX	SP	CRE	ID	BD		5/19/2060
2020 PO1186433025	ODP	6	30 XXX	SP	CRE		V		5/20/2060
2020 PO3930182845	LGE	3	45 BRO	SP	CRE		B		5/21/2060
2020 PO6475040097	LGE	4	35 BRO	SP	CCA		V		5/22/2060
2020 PO6488040038	LGE	3	45 BRO	SP	CCA		V		5/23/2060
2020 PO3931782828	LGE	4	40 BRO	SP	CRE		B		5/24/2060
2020 PO3914682642	LGE	4	40 BRN	SP	CRE	ED,ID	TD		5/25/2060
2020 PO1145034346	ODP	5	35 BRN	SP	CCA		V		5/26/2060
2020 PO3996483113	LGE	4	40 BRN	SP	A	ED,ID	TD		5/27/2060
2020 PO1154334310	F	3	45 OTH	SP	CRE		V		5/28/2060
2020 PO2917635748	KU	5	35 BRN	SP	CCA		V		5/29/2060
2020 PO2893536113	KU	4	40 BRN	SP	CRE	ED,ID,SRS	TD		5/30/2060
2020 PO2907836105	KU	4	40 BRN	SP	CRE	ID,IP	BD		5/31/2060
2020 PO3913382651	LGE	4	40 BRN	SP	P	ED,ID	TD		6/1/2060
2020 PO1161734303	ODP	6	30 OTH	SP	CCA		V		6/2/2060
2020 PO1168334289	F	3	45 OTH	SP	CRE		V		6/3/2060
2020 PO1176934275	ODP	4	40 BRN	SP	CRE	ID	TD		6/4/2060
2020 PO1188633163	ODP	3	55 XXX	SP	CRE	ED,ID	TD		6/5/2060
2020 PO1212533017	ODP	4	45 XXX	SP	CRE		BD		6/6/2060
2020 PO1225533240	ODP	4	40 XXX	SP	CRE	ED,ID	TD		6/7/2060
2020 PO1224633195	ODP	4	40 XXX	SP	CRE		V		6/8/2060

2020 PO1244833183	ODP	4	40 XXX	SP	CCA		V	6/9/2060
2020 PO1182334263	F	4	40 BRN	SP	CRE		V	6/10/2060
2020 PO1186734253	F	5	30 BRN	SP	CRE		V	6/11/2060
2020 PO1217134052	ODP	6	30 BRN	SP	CCA	SRS	TD	6/12/2060
2020 PO1191934217	ODP	6	30 BRN	SP	CRE	ID	TD	6/13/2060
2020 PO1195034246	F	4	40 BRN	SP	CRE		V	6/14/2060
2020 PO3995183144	LGE	4	30 BRN	SP	A	ED,ID	TD	6/15/2060
2020 PO1208134223	ODP	4	40 BRN	SP	CRE	ID	BD	6/16/2060
2020 PO3909682675	LGE	4	40 BRN	SP	CRE	ED,ID	TD	6/17/2060
2020 PO3908882679	LGE	4	30 BRN	SP	P	ED,ID	TD	6/18/2060
2020 PO3996283129	LGE	4	40 BRN	SP	A	ED,ID	BD	6/19/2060
2020 PO3996283137	LGE	4	40 BRN	SP	CCA		V	6/20/2060
2020 PO3996283143	LGE	4	40 BRN	SP	A	ED,ID	BD	6/21/2060
2020 PO1218434197	F	7	30 KOP	SP	CRE		V	6/22/2060
2020 PO1225034198	ODP	4	40 BRN	SP	CCA		V	6/23/2060
2020 PO1493110089	KU	3	50 BRN	SP	CCA		V	6/24/2060
2020 PO3982143788	KU	3	45 ACE	SP	CCA		V	6/25/2060
2020 PO3971943695	KU	3	45 ACE	SP	CCA		V	6/26/2060
2020 PO3912182658	LGE	4	40 BRN	SP	CRE	ED,ID	TD	6/27/2060
2020 PO3949943663	KU	4	40 ACE	SP	CCA		V	6/28/2060
2020 PO3957043564	KU	3	45 ACE	SP	CCA		V	6/29/2060
2020 PO1238234185	F	4	40 BRN	SP	CRE		V	6/30/2060
2020 PO6286504294	KU	6	30 XXX	SP	CRE	ED,ID	TD	7/1/2060
2020 PO6296704343	KU	6	30 KOP	SP	CCA		V	7/2/2060
2020 PO6963296407	KU	6	30 BRN	SP	CRE	ED,ID	BD	7/3/2060
2020 PO6973396425	KU	4	40 BRN	SP	CRE	ED,ID	TD	7/4/2060
2020 PO7310189120	LGE	4	45 BRO	SP	P	ED,RB	TD	7/5/2060
2020 PO7319989207	LGE	4	45 BRO	SP	P	ED	BD	7/6/2060
2020 PO2903141298	KU	5	45 BRN	SP	CRE	ED,ID,IP,SRC	TD	7/7/2060
2020 PO2883441406	KU	5	45 BRN	SP	CRE	ED,ID,MD,SRC	TD	7/8/2060
2020 PO2859241538	KU	4	40 BRN	SP	CRE	ED,ID,IP,MD,SRC	TD	7/9/2060
2020 PO6979996507	KU	5	35 BRN	SP	CRE	ED,ID	TD	7/10/2060
2020 PO7331589205	KU	5	35 BRO	SP	CCA		V	7/11/2060
2020 PO7330189129	KU	6	30 BRO	SP	CRE	ED,ID	BD	7/12/2060
2020 PO6974196653	KU	4	40 BRN	SP	CRE	ED,ID	BD	7/13/2060
2020 PO8047172868	KU	5	35 BRO	SP	CRE	ED,ID	TD	7/14/2060
2020 PO6980996755	KU	4	40 BRN	SP	CRE	ED,ID	TD	7/15/2060
2020 PO2395354625	F	4	40 BRO	SP	CCA		V	7/16/2060
2020 PO2322252358	KU	5	35 BRO	SP	A		V	7/17/2060
2020 PO7328789285	LGE	3	40 BRO	SP	P	ED,ID	TD	7/18/2060
2020 PO6780901657	KU	6	30 XXX	SP	CCA	ED,SRS	T	7/19/2060
2020 PO6764001568	KU	5	35 XXX	SP	CRE	ED,ID	TD	7/20/2060
2020 PO6759601711	KU	6	30 XXX	SP	CRE	ED,ID	TD	7/21/2060
2020 PO1222777229	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	7/22/2060
2020 PO1203477248	KU	3	50 BRN	SP	CRE	ED,ID,IP	TD	7/23/2060
2020 PO1196377232	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	7/24/2060
2020 PO1333776447	KU	4	35 BRN	SP	CCA		V	7/25/2060

2020 PO1723675093	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		7/26/2060
2020 PO1695075083	KU	4	40 BRN	SP	CRE	ID,IP	BD		7/27/2060
2020 PO1723275534	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		7/28/2060
2020 PO1732775424	KU	4	40 BRN	SP	CRE	ID,IP	BD		7/29/2060
2020 PO1762776781	KU	4	40 BRN	SP	CCA		V		7/30/2060
2020 PO1322576336	KU	4	40 BRN	SP	CRE	ID	BD		7/31/2060
2020 PO1310975988	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		8/1/2060
2020 PO1682510402	KU	5	35 UNK	SP	CRE	ED,ID,SRS	TD		8/2/2060
2020 PO1681810465	F	4	40 UNK	SP	CRE		V		8/3/2060
2020 PO1703810435	KU	4	40 UNK	SP	CRE	ED,ID,RB	X	RP1	8/4/2060
2020 PO1753710542	KU	3	45 UNK	SP	CCA		V		8/5/2060
2020 PO1730710472	KU	3	45 BRN	SP	CCA		V		8/6/2060
2020 PO1777710701	KU	4	40 UNK	SP	CRE	ED,ID	TD		8/7/2060
2020 PO1761110648	KU	6	30 BRN	SP	CCA		V		8/8/2060
2020 PO1767610395	KU	6	30 UNK	SP	CRE	ED,ID	TD		8/9/2060
2020 PO1757610421	KU	6	30 KOP	SP	CRE		V		8/10/2060
2020 PO1690110276	KU	6	30 BRN	SP	CRE	ED,ID	TD		8/11/2060
2020 PO1797610250	KU	5	35 BRN	SP	CCA		V		8/12/2060
2020 PO1795510442	KU	2	50 BRN	SP	CCA		V		8/13/2060
2020 PO1788910612	KU	2	60 BRN	SP	CRE	ED,ID	TD		8/14/2060
2020 PO2966335864	KU	4	40 BRN	SP	CRE	ID,IP	BD		8/15/2060
2020 PO9122939805a	ODP	4	40 XXX	SP	A		V		8/16/2060
2020 PO9122939805	ODP	5	35 XXX	SP	CRE	ED,ID	TD		8/17/2060
2020 PO9141539686	ODP	4	40 XXX	SP	CRE	ED,ID	TD		8/18/2060
2020 PO1440932778	ODP	6	30 XXX	SP	CRE	ID	TD		8/19/2060
2020 PO1448932691	ODP	4	40 XXX	SP	CCA	ED	TD		8/20/2060
2020 PO1428332915	ODP	5	35 XXX	SP	CRE	ID	TD		8/21/2060
2020 PO9150939727	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD		8/22/2060
2020 PO9163539741	ODP	6	30 BRN	SP	CRE	ED,ID,RB	X	RP1	8/23/2060
2020 PO1357832552	F	4	40 XXX	SP	A		V		8/24/2060
2020 PO1372132698	ODP	4	40 XXX	SP	A	ID	TD		8/25/2060
2020 PO6954294996	KU	4	40 BRN	SP	CRE	ED,ID	BD		8/26/2060
2020 PO9237336967a	ODP	4	35 XXX	SP	CRE	ED,ID,RB	X	PX	8/27/2060
2020 PO1769910914	KU	5	35 BRN	SP	CRE	ED,ID	TD		8/28/2060
2020 PO1783010790	KU	6	30 BRN	SP	CCA		V		8/29/2060
2020 PO1783110864	KU	6	30 KOP	SP	CRE	ED,ID	TD		8/30/2060
2020 PO1786111026	KU	4	40 KOP	SP	CRE	ID	BD		8/31/2060
2020 N	KU	6	30 KOP	SP	CRE	ED,ID	TD		9/1/2060
2020 PO1796411009	KU	5	30 KOP	SP	CRE	ED,ID	TD		9/2/2060
2020 PO1790711158	KU	4	40 KOP	SP	CRE		V		9/3/2060
2020 PO1806511200	KU	5	35 UNK	SP	CRE	ED,ID	TD		9/4/2060
2020 PO1789711315	KU	4	45 BRN	SP	CRE	ED,ID,IP,RB	BX	RP1	9/5/2060
2020 PO1760811142	KU	4	40 BRN	SP	CRE	ED,ID	TD		9/6/2060
2020 PO1752311408	KU	4	30 BRN	SP	CCA	ED,ID	TD		9/7/2060
2020 PO1759111470	KU	5	30 BRN	SP	CRE	ED,ID	TD		9/8/2060
2020 PO1746611665	KU	5	35 KOP	SP	CRE		V		9/9/2060
2020 PO1727111953	KU	5	35 KOP	SP	CRE		V		9/10/2060

2020 PO1704812123	KU	6	30 KOP	SP	CRE		V			9/11/2060
2020 PO1782311496	KU	6	30 KOP	SP	CCA		V			9/12/2060
2020 PO7403592063	F	5	35 BRO	SP	CRE		V			9/13/2060
2020 PO7413792168	F	3	45 BRO	SP	CRE		V			9/14/2060
2020 PO7508692462	F	5	35 BRO	SP	CRE		V			9/15/2060
2020 PO7516592408	F	4	40 BRO	SP	CCA		V			9/16/2060
2020 PO7527092341	F	5	35 BRO	SP	CRE		V			9/17/2060
2020 PO8978422934	F	4	40 UNK	SP	P			B		9/18/2060
2020 PO8965522985	F	6	30 UNK	SP	CRE	ID		BD		9/19/2060
2020 PO8959022666	KU	4	40 UNK	SP	CRE	ID		TD		9/20/2060
2020 PO8967122898	KU	4	40 ACW	SP	CRE	ID		TD		9/21/2060
2020 PO8954523025	KU	4	40 UNK	SP	CRE	ID		TD		9/22/2060
2020 PO8854122821	KU	5	35 UNK	SP	CRE	ID		TD		9/23/2060
2020 PO8942023258	KU	6	30 OTH	SP	CCA		V			9/24/2060
2020 PO8939722854	KU	4	40 ACW	SP	CRE	ID		TD		9/25/2060
2020 PO8955023102	KU	6	30 UNK	SP	CRE	ID		TD		9/26/2060
2020 PO8936022960	KU	6	30 BRN	SP	CCA		V			9/27/2060
2020 PO8981723123	KU	2	65 KOP	SP	CCA		V			9/28/2060
2020 PO9237336967	ODP	5	35 XXX	SP	CRE	ED,ID		TD		9/29/2060
2020 PO9230036860	ODP	6	30 BRN	SP	CCA	ED		T		9/30/2060
2020 PO9248636891	ODP	6	30 BRN	SP	CCA	ED		T		10/1/2060
2020 PO9241336594	ODP	5	35 XXX	SP	CRE	ED,ID,IP		TD		10/2/2060
2020 PO9278635563	ODP	4	40 XXX	SP	CRE	ED,ID		TD		10/3/2060
2020 PO9279635339	ODP	4	40 XXX	SP	CRE	ED,ID		TD		10/4/2060
2020 PO1471126946	ODP	4	40 XXX	SP	CRE	ID		TD		10/5/2060
2020 PO1437026542	ODP	4	40 XXX	SP	CRE	ID		TD		10/6/2060
2020 PO1413526708	ODP	4	40 XXX	SP	CRE	ID		TD		10/7/2060
2020 PO1393626300	ODP	5	35 XXX	SP	CRE	ID,IP		BD		10/8/2060
2020 PO1361926336	ODP	5	35 XXX	SP	CRE	HH	X		RP2	10/9/2060
2020 PO1366426138	ODP	4	40 XXX	SP	CRE	ID		TD		10/10/2060
2020 PO1372425891	ODP	4	40 XXX	SP	CRE	ID		TD		10/11/2060
2020 PO1404526094	ODP	5	35 XXX	SP	CRE	ID		BD		10/12/2060
2020 PO1414125777	ODP	6	35 XXX	SP	CRE	ID		TD		10/13/2060
2020 PO7531892644	F	3	40 BRO	SP	CRE		V			10/14/2060
2020 PO1409625930	ODP	5	35 XXX	SP	CRE	HH,ID	X		RP2	10/15/2060
2020 PO6722021448	KU	5	35 XXX	SP	CCA		V			10/16/2060
2020 PO6725321559	KU	6	30 XXX	SP	CRE	ID		TD		10/17/2060
2020 PO6735321601	KU	5	35 XXX	SP	CRE	ID		TD		10/18/2060
2020 PO6763321413	KU	5	35 XXX	SP	CRE	ID		BD		10/19/2060
2020 PO6800921185A	KU	5	35 XXX	SP	CRE	ID		TD		10/20/2060
2020 PO6800921185	KU	4	40 XXX	SP	CRE	EP,IP	X		RP2	10/21/2060
2020 PO6827620892	KU	4	40 XXX	SP	CRE	ID		TD		10/22/2060
2020 PO6828620605	KU	6	30 XXX	SP	CRE	ID		TD		10/23/2060
2020 PO6838220613	KU	6	30 XXX	SP	CRE	ID		TX	RR	10/24/2060
2020 PO6846820690	KU	4	40 XXX	SP	CRE	ID		TD		10/25/2060
2020 PO6857920516A	KU	6	30 XXX	SP	CRE	ID		BD		10/26/2060
2020 PO6843720521	KU	6	30 XXX	SP	CRE	ID		BD		10/27/2060

2020 PO6857920516	KU	4	40 XXX	SP	CRE	ID	TD	10/28/2060
2020 PO6873820476	KU	6	30 XXX	SP	CRE	ID	BD	10/29/2060
2020 PO6866720376	KU	4	40 XXX	SP	CRE	ID	TD	10/30/2060
2020 PO6864920356	KU	6	30 XXX	SP	CRE	ID	BD	10/31/2060
2020 PO6881020301A	KU	6	30 XXX	SP	CRE	ID	TD	11/1/2060
2020 PO6886520287	KU	6	30 XXX	SP	CRE		V	11/2/2060
2020 PO6881020301	KU	4	40 XXX	SP	CRE	ID	TD	11/3/2060
2020 PO6872020239	KU	4	35 XXX	SP	CRE	ID	BD	11/4/2060
2020 PO6873720185	KU	4	40 XXX	SP	CRE	ID	TD	11/5/2060
2020 PO6863420161	KU	4	40 XXX	SP	CRE	ID	TD	11/6/2060
2020 PO6844120153	KU	6	30 XXX	SP	CRE		V	11/7/2060
2020 PO6832720252A	KU	5	35 XXX	SP	CRE	ID	TD	11/8/2060
2020 PO6832720256	KU	5	35 XXX	SP	CRE	ED,ID	TD	11/9/2060
2020 PO6852820281	KU	4	40 XXX	SP	CRE	ID	TD	11/10/2060
2020 PO6852420380A	KU	5	35 XXX	SP	CRE	ID	TD	11/11/2060
2020 PO6852420380	KU	6	30 XXX	SP	CRE	ID	BD	11/12/2060
2020 PO6818020443	KU	4	40 XXX	SP	CCA		V	11/13/2060
2020 PO6857020004	KU	6	30 XXX	SP	CRE	ID	BD	11/14/2060
2020 PO6853219898	KU	4	40 XXX	SP	CRE	ID	TD	11/15/2060
2020 PO6855619901	F	6	30 XXX	SP	CRE		V	11/16/2060
2020 PO1268022163	F	4	40 XXX	SP	A		V	11/17/2060
2020 PO1243022073	ODP	4	40 XXX	SP	CRE	ID	TD	11/18/2060
2020 PO1113027593	ODP	4	40 XXX	SP	CCA		V	11/19/2060
2020 PO9281835137	ODP	4	45 XXX	SP	CRE	ED,ID	TD	11/20/2060
2020 PO9278334771	ODP	4	40 ACW	SP	CRE	ED,ID	TD	11/21/2060
2020 PO9270234615	ODP	4	40 XXX	SP	CRE	ED,ID	TD	11/22/2060
2020 PO6849019942	KU	4	40 XXX	SP	CRE	ID	TD	11/23/2060
2020 PO5450611838	KU	6	35 BRO	SP	CRE	ID	TD	11/24/2060
2020 PO5448212038	KU	6	30 BRO	SP	CRE	ID	TD	11/25/2060
2020 PO5443212329	KU	5	35 BRO	SP	CCA		V	11/26/2060
2020 PO4541432225a	KU	3	45 ACE	SP	CCA		V	11/27/2060
2020 PO4560332477	KU	3	45 ACE	SP	CRE	ED,ID	BD	11/28/2060
2020 PO4381139848-D	KU	1	60 BRO	SP	CCA		V	11/29/2060
2020 PO4381139848-C	KU	1	60 BRO	SP	A		V	11/30/2060
2020 PO4381139848-B	KU	4	40 BRO	SP	CCA		V	12/1/2060
2020 PO4381139848-A	KU	2	60 BRO	SP	CCA		V	12/2/2060
2020 PO4381139848-A	KU	2	60 BRO	SP	CCA		V	12/3/2060
2020 PO4477439024-A	KU	1	60 BRO	SP	A		V	12/4/2060
2020 PO4463939136-A	KU	1	45 BRO	SP	CCA		V	12/5/2060
2020 PO3951382378	LGE	3	45 BRN	SP	CCA		V	12/6/2060
2020 PO2054425755	ODP	4	40 XXX	SP	CRE	ID	BD	12/7/2060
2020 PO2054425755A	ODP	4	40 XXX	SP	CRE	ID	TD	12/8/2060
2020 PO2042025716	ODP	5	30 XXX	SP	CRE	ID	TD	12/9/2060
2020 PO2059525502	ODP	4	40 XXX	SP	CRE	ID	TD	12/10/2060
2020 PO3950482377	LGE	4	40 BRN	SP	CRE	ED,ID	TD	12/11/2060
2020 PO3950382383	LGE	4	40 BRN	SP	CRE	ED,ID	TD	12/12/2060
2020 PO1981324400	ODP	6	30 XXX	SP	CRE	ED,HH,RB	BX	12/13/2060

Business Use

2020 PO5455312343	F	6	30 BRO	SP	CRE		V	12/14/2060
2020 PO5463411990	F	6	30 BRO	SP	CRE		V	12/15/2060
2020 PO5448212286	KU	4	40 BRO	SP	CRE	ID	TD	12/16/2060
2020 PO5446412485	KU	5	35 BRO	SP	CRE	ID	TD	12/17/2060
2020 PO5456711620	KU	4	40 BRO	SP	CCA		V	12/18/2060
2020 PO5464011530	KU	4	40 BRO	SP	CRE	ID	TD	12/19/2060
2020 PO5464111407	KU	3	45 BRO	SP	CCA		V	12/20/2060
2020 PO5472211169	KU	3	45 BRO	SP	CCA		V	12/21/2060
2020 PO5493511020	KU	4	45 BRO	SP	CRE	ID	TD	12/22/2060
2020 PO5518110853	KU	5	35 BRO	SP	CRE		V	12/23/2060
2020 PO5524610826	KU	3	45 BRO	SP	CCA		V	12/24/2060
2020 PO5525110735	KU	5	35 BRO	SP	CRE	ID	TD	12/25/2060
2020 PO5533010604	KU	4	40 BRO	SP	CRE	ID	TD	12/26/2060
2020 PO5541610467	KU	4	40 BRO	SP	CRE	ID	TD	12/27/2060
2020 PO5548110328	KU	4	40 BRO	SP	CRE	ID	TD	12/28/2060
2020 PO5546710156	KU	5	35 BRO	SP	CRE	ID	TD	12/29/2060
2020 PO7127591034	KU	6	30 BRN	SP	CRE	ED,ID	BD	12/30/2060
2020 PO1967224230	ODP	4	40 XXX	SP	CRE	ID	TD	12/31/2060
2020 PO1680722218	ODP	6	30 XXX	SP	CRE	ID	TD	1/1/2061
2020 PO1685622544	ODP	5	30 XXX	SP	CCA		V	1/2/2061
2020 PO1668422472	ODP	3	50 XXX	SP	CCA		V	1/3/2061
2020 PO1693322645	ODP	4	50 XXX	SP	CRE	ID,IP	BX	1/4/2061
2020 PO1708622621	ODP	6	30 XXX	SP	CRE	ID	TD	1/5/2061
2020 PO1703722723	ODP	2	50 XXX	SP	CCA		V	1/6/2061
2020 PO1699322829	F	4	40 XXX	SP	A		V	1/7/2061
2020 PO1695622891	ODP	4	45 XXX	SP	CRE	ID	TD	1/8/2061
2020 PO1802722821	ODP	6	30 XXX	SP	CRE		V	1/9/2061
2020 PO1796122664	ODP	6	30 XXX	SP	CRE		V	1/10/2061
2020 PO4625132485a	KU	4	40 ACE	SP	CCA		V	1/11/2061
2020 PO4625132485	KU	3	45 ACE	SP	CRE	ED,ID	TD	1/12/2061
2020 PO4611232173	KU	3	45 ACE	SP	CRE	ED,ID	TD	1/13/2061
2020 PO3939682347	LGE	1	70 BRN	SP	CRE	ED,ID	BD	1/14/2061
2020 PO0584136365	ODP	6	30 BRN	SP	CCA	ED	T	1/15/2061
2020 PO0581436324	ODP	6	30 BRN	SP	CRE	ED,ID	TD	1/16/2061
2020 PO4769831868	KU	4	40 BRN	SP	CRE	EP,ID,IP,RB	BX	1/17/2061
2020 PO6342504841	KU	6	30 BRN	SP	CCA		V	1/18/2061
2020 PO6332404793	F	6	30 BRN	SP	CRE		V	1/19/2061
2020 PO6326504759	KU	6	30 BRN	SP	CRE		V	1/20/2061
2020 PO6318604791	KU	3	45 BRN	SP	CCA		V	1/21/2061
2020 PO6324104851	F	5	30 XXX	SP	CRE		V	1/22/2061
2020 PO2050646032	KU	4	40 ACE	SP	CRE	ED,ID	BD	1/23/2061
2020 PO2060945923	KU	4	40 ACE	SP	CRE	ED,ID	TD	1/24/2061
2020 PO7121190574	KU	5	35 BRN	SP	CRE	ED,ID	BD	1/25/2061
2020 6318604791a	KU	3	45 BRN	SP	S		V	1/26/2061
2020 PO7138690723	KU	5	35 BRN	SP	CRE	ED,ID	TD	1/27/2061
2020 PO2050745762	KU	4	40 ACE	SP	CRE	ED,ID,IP,MD	TD	1/28/2061
2020 PO6279506676	KU	4	45 BRN	SP	CCA		V	1/29/2061

2020 PO6249206547	KU	6	20 XXX	SP	CRE	ID	BD	1/30/2061
2020 PO6254006490	KU	4	45 XXX	SP	CRE	ID	BD	1/31/2061
2020 PO6254906354	KU	6	30 XXX	SP	CRE		V	2/1/2061
2020 PO2290229522	KU	5	35 BRN	SP	CRE	ED,ID,IP,MD,SRC	TD	2/2/2061
2020 PO2295429303	KU	5	35 BRN	SP	CRE	ED,ID,IP,MD,SRC	TD	2/3/2061
2020 PO3072240381	KU	2	40 BRN	SP	CRE	ED,ID,IP,MD,SRC	TD	2/4/2061
2020 PO3984282792	F	6	25 BRN	SP	CRE		V	2/5/2061
2020 PO3983382791	F	4	40 BRN	SP	S		V	2/6/2061
2020 PO3983182804	F	3	45 BRN	SP	CCA		V	2/7/2061
2020 PO3983082818	F	4	40 BRN	SP	CCA		V	2/8/2061
2020 PO3539247489	KU	4	40 ACE	SP	CRE	ED,ID	TD	2/9/2061
2020 PO3982482832	F	4	35 BRN	SP	CRE		V	2/10/2061
2020 PO3982882832	F	4	40 BRN	SP	CRE		V	2/11/2061
2020 PO3982682846	F	3	45 BRN	SP	CCA		V	2/12/2061
2020 PO3982582860	F	3	45 BRN	SP	S		V	2/13/2061
2020 PO3982082863	F	6	35 BRN	SP	CRE		V	2/14/2061
2020 PO3982482879	F	4	40 BRN	SP	CRE		V	2/15/2061
2020 PO0347547155	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD	2/16/2061
2020 PO3878282825	LGE	4	40 BRO	SP	CRE	ED,HH,ID,RB	TX	RR 2/17/2061
2020 PO5605542343	KU	4	40 BRN	SP	CRE		V	2/18/2061
2020 PO5598842436	KU	3	45 BRN	SP	CCA		V	2/19/2061
2020 PO5557142601	KU	4	40 BRN	SP	S		V	2/20/2061
2020 PO5542642769	KU	4	40 BRN	SP	S		V	2/21/2061
2020 PO5588442460	KU	4	40 BRN	SP	CRE		V	2/22/2061
2020 PO5572242561	KU	3	45 BRN	SP	CCA		V	2/23/2061
2020 PO5619042245	KU	4	40 BRN	SP	P	ID	BD	2/24/2061
2020 PO5655042114	KU	4	40 BRN	SP	CRE	ED,ID,SRC,SRS	TD	2/25/2061
2020 PO5617242290	KU	4	40 BRN	SP	CRE	ID	BD	2/26/2061
2020 PO5763941997	KU	4	40 BRN	SP	CRE	ED,ID	TD	2/27/2061
2020 PO5666042123	KU	4	40 BRN	SP	CRE	ED,ID,SRC,SRS	TD	2/28/2061
2020 PO4275901404	KU	5	35 BRO	SP	CRE	ID,IP	BD	3/1/2061
2020 PO4300001523	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	3/2/2061
2020 PO4323401349	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	3/3/2061
2020 PO3656739770	KU	4	45 ACE	SP	CRE	ED,ID	TD	3/4/2061
2020 PO4328701438	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	3/5/2061
2020 PO4334901546	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	3/6/2061
2020 PO3878582825	LGE	1	65 BRO	AL	CCA		V	3/7/2061
2020 PO3878382803	LGE	1	65 BRO	SP	CCA		V	3/8/2061
2020 PO3049239937	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	3/9/2061
2020 PO3062640194	KU	4	40 BRN	SP	CRE	ED,ID,MD	TD	3/10/2061
2020 PO3037239707	KU	4	40 BRN	SP	CRE	ED,ID,SRS	TD	3/11/2061
2020 PO3037539297	KU	4	40 BRN	SP	CRE	ED,ID	TD	3/12/2061
2020 PO3037339502	KU	4	40 BRN	SP	CRE	ED,ID,IP	BD	3/13/2061
2020 PO2089736205	KU	4	40 BRO	SP	CCA		V	3/14/2061
2020 PO3978483084	LGE	3	45 BRN	SP	S		V	3/15/2061
2020 PO3981083073	LGE	4	30 BRN	SP	CCA		V	3/16/2061
2020 PO3478340294	KU	4	40 ACE	SP	CRE	ED,ID	TD	3/17/2061

2020 PO3981083073	LGE	4	30 BRN	SP	S		V		3/18/2061
2020 PO3979983072	LGE	4	40 BRN	SP	CRE	ED,ID	TD		3/19/2061
2020 PO3466540265	KU	4	40 ACE	SP	CRE	ED,ID	TD		3/20/2061
2020 PO3443039959	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD		3/21/2061
2020 PO3471640203	KU	6	30 ACE	SP	CRE	ED,ID	BD		3/22/2061
2020 PO3457440243	KU	4	45 ACE	SP	CCA		V		3/23/2061
2020 PO4341501662	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		3/24/2061
2020 PO3656540014	KU	4	40 ACE	SP	CRE	ED,ID	TD		3/25/2061
2020 PO3656340270	KU	4	40 ACE	SP	CRE	ED,ID	TD		3/26/2061
2020 PO3656040592	KU	4	40 ACE	SP	CRE	ED,ID	TD		3/27/2061
2020 PO3655840794	KU	4	40 ACE	SP	CRE	ED,ID	BD		3/28/2061
2020 PO3640940790	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD		3/29/2061
2020 PO3682939309	F	4	40 ACE	SP	CRE		V		3/30/2061
2020 PO4316001355	F	5	35 BRO	SP	CRE		V		3/31/2061
2020 PO4326301543	F	4	40 BRO	SP	A		V		4/1/2061
2020 PO4328301793	KU	5	35 BRO	SP	CRE	ED,ID	TD		4/2/2061
2020 PO3683439114	F	4	40 ACE	SP	CRE		V		4/3/2061
2020 PO3689438926	KU	6	30 ACE	SP	CCA		V		4/4/2061
2020 PO3682639419	F	4	40 ACE	SP	CRE		V		4/5/2061
2020 PO3709939357	F	6	30 ACE	SP	P		V		4/6/2061
2020 PO3791139693	F	4	40 ACE	SP	CRE		V		4/7/2061
2020 PO5779241834	KU	4	45 BRN	SP	CCA	ED,ID	TD		4/8/2061
2020 PO5873840836	KU	4	40 BRN	SP	CRE	ED,ID	TD		4/9/2061
2020 PO3752339575	F	4	40 ACE	SP	CRE		V		4/10/2061
2020 PO3772139637	F	4	40 ACE	SP	CRE		V		4/11/2061
2020 PO3709639413	F	4	40 ACE	SP	CRE		V		4/12/2061
2020 PO3733139507	F	4	40 ACE	SP	CRE		V		4/13/2061
2020 PO3811139766	F	4	40 ACE	SP	CRE		V		4/14/2061
2020 PO4343302055	KU	5	35 BRO	SP	CRE	ED,ID	TD		4/15/2061
2020 PO4336301898	KU	6	30 BRO	SP	CCA		V		4/16/2061
2020 PO4340201937	KU	6	30 BRO	SP	CCA		V		4/17/2061
2020 PO3831239755	F	4	40 ACE	SP	CRE		V		4/18/2061
2020 PO3856939682	KU	4	40 ACE	SP	CCA		V		4/19/2061
2020 PO3855439743	F	4	40 ACE	SP	CRE		V		4/20/2061
2020 PO3876839733	F	4	40 ACE	SP	CRE		V		4/21/2061
2020 PO5253306514	KU	6	35 XXX	SP	CCA		V		4/22/2061
2020 PO5275806359	KU	4	45 XXX	SP	CCA		V		4/23/2061
2020 PO5267606512	KU	4	45 XXX	SP	CRE	ED,ID	TD		4/24/2061
2020 PO5263406614	KU	4	40 XXX	SP	CRE	ED,ID,IP	TX	RR	4/25/2061
2020 PO5251906771	KU	4	45 XXX	SP	CRE	ED,ID	TD		4/26/2061
2020 PO7106088913	KU	3	60 BRN	SP	CRE	ED,ID	BD		4/27/2061
2020 PO7108188823	KU	6	30 BRN	SP	CCA		V		4/28/2061
2020 PO7122588801	F	5	35 BRN	SP	CRE		V		4/29/2061
2020 PO7117988871	KU	5	35 BRN	SP	CRE	ED,ID	TD		4/30/2061
2020 PO7124688830	KU	4	40 BRN	SP	CRE	ED,ID	BD		5/1/2061
2020 PO7449693984	KU	4	45 BRO	SP	CCA		B		5/2/2061
2020 PO7445493971	KU	6	30 BRO	SP	CRE	ED,ID	TD		5/3/2061

2020 PO7443693993	KU	5	35 BRO	SP	CRE	ED,ID	TD	5/4/2061
2020 PO7440694057	KU	4	40 BRO	SP	CRE	ED,ID	TD	5/5/2061
2020 PO7140088812	KU	5	35 BRN	SP	CRE	ED,ID	BD	5/6/2061
2020 PO7150988831	KU	4	40 BRN	SP	CRE	ED,ID	BD	5/7/2061
2020 PO7158588779	KU	5	35 BRN	SP	CRE	ED,ID,RB	TX	5/8/2061
2020 PO7140088734	KU	5	35 BRN	SP	CRE	ED,ID	BD	5/9/2061
2020 PO7151388649	KU	5	35 BRN	SP	CRE	ED,ID	TD	5/10/2061
2020 PO7432094237	KU	4	40 BRO	SP	CRE	ED,ID	TD	5/11/2061
2020 PO7412694362	KU	6	30 BRO	SP	CRE	ID	BD	5/12/2061
2020 PO5275306715	KU	6	30 XXX	SP	CCA		V	5/13/2061
2020 PO7423694419	KU	4	40 BRO	SP	CRE	ED,ID	TD	5/14/2061
2020 PO1195878744	KU	4	40 BRN	SP	CRE	ED,ID	TD	5/15/2061
2020 PO1169578247	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	5/16/2061
2020 PO1159577515	KU	3	50 BRN	SP	CRE	ED	TD	5/17/2061
2020 PO1171177324	KU	3	55 BRN	SP	CRE	ED	TD	5/18/2061
2020 PO9377256171	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	5/19/2061
2020 PO9368956262	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	5/20/2061
2020 PO4178740394	KU	5	35 ACE	SP	CCA	ED	T	5/21/2061
2020 PO0640979639	KU	4	40 BRN	SP	CCA		V	5/22/2061
2020 PO1453475564	KU	4	40 BRN	SP	CCA		V	5/23/2061
2020 PO1128275070	KU	3	50 BRN	SP	CRE	ED,ID,IP	TD	5/24/2061
2020 PO1120274937	KU	3	50 BRN	SP	CRE	ED,ID,IP	TD	5/25/2061
2020 PO1558175232	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	5/26/2061
2020 PO1563475210	F	4	40 BRN	SP	A		V	5/27/2061
2020 PO1111874786	KU	3	50 BRN	SP	CRE	ED,ID,IP	TD	5/28/2061
2020 PO1102974646	KU	2	50 BRN	SP	CRE	ID,IP	BD	5/29/2061
2020 PO1109574627	F	4	40 BRN	SP	CRE		V	5/30/2061
2020 PO9397659150	KU	4	40 ACW	SP	CRE	ED,ID	TD	5/31/2061
2020 PO9409059415	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	6/1/2061
2020 PO0178257307	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD	6/2/2061
2020 PO0152157407	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD	6/3/2061
2020 PO0116357535	KU	4	40 BRO	SP	CRE	ID	BD	6/4/2061
2020 PO0054753478	KU	4	40 BRO	SP	CRE	EP,HH,ID,IP,RB,SRC	TD	6/5/2061
2020 PO9429259829	KU	6	30 ACW	SP	CRE	ED,ID	TD	6/6/2061
2020 PO9401860295	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	6/7/2061
2020 PO9426360067	KU	4	40 ACW	SP	CRE	ED,ID	TD	6/8/2061
2020 PO9416560596	KU	4	45 ACW	SP	P	ED	T	6/9/2061
2020 PO9428660869	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	6/10/2061
2020 PO9441761156	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	6/11/2061
2020 PO0035253792	KU	4	40 BRO	SP	CRE	ID	BD	6/12/2061
2020 PO0217852634	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/13/2061
2020 PO3125750363	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/14/2061
2020 PO1829241358	ODP	4	45 BRN	SP	CCA		V	6/15/2061
2020 PO1830641296	ODP	4	40 BRN	SP	CRE	ED,ID	TD	6/16/2061
2020 PO1819641246	ODP	6	30 BRN	SP	CRE		V	6/17/2061
2020 PO1813941226	ODP	4	35 BRN	SP	CRE	ED,ID,SRS	TD	6/18/2061
2020 PO1804141415	ODP	6	30 BRN	SP	CCA		V	6/19/2061

2020 PO7163091927	KU	6	30 BRN	SP	CRE	ED,ID	TD		6/20/2061
2020 PO1107936046	ODP	4	45 XXX	SP	CRE	IP,RB	BX	RP1	6/21/2061
2020 PO7129891835	KU	4	40 BRN	SP	CRE	ED,ID	BD		6/22/2061
2020 PO7154692006	KU	6	30 BRN	SP	CRE	ED,ID	TD		6/23/2061
2020 PO7142291997	KU	6	30 BRN	SP	CRE	ED,ID	TD		6/24/2061
2020 PO7131391919	KU	6	30 BRN	SP	CRE	ED,ID	TD		6/25/2061
2020 PO7124991764	KU	4	40 BRN	SP	CRE	ED,ID	TD		6/26/2061
2020 PO7115791634	KU	6	35 BRN	SP	CRE	ED,ID	BD		6/27/2061
2020 PO7109591544	KU	5	35 BRN	SP	CRE	ED,ID	TD		6/28/2061
2020 PO7101691440	KU	4	40 BRN	SP	CRE	ED,ID	BD		6/29/2061
2020 PO7093091318	KU	4	40 BRN	SP	CRE	ED,ID	TD		6/30/2061
2020 PO7081691157	F	3	40 BRN	SP	CRE		V		7/1/2061
2020 PO7074591054	KU	3	40 BRN	SP	P		V		7/2/2061
2020 PO7068790970	KU	3	40 BRN	SP	P		V		7/3/2061
2020 PO7060690850	KU	3	40 BRN	SP	P		V		7/4/2061
2020 PO7049890851	KU	5	35 BRN	SP	CRE	ED,ID	BD		7/5/2061
2020 PO7048790760	KU	4	30 BRN	SP	CRE	ED,ID	BD		7/6/2061
2020 PO7051590718	KU	5	35 BRN	SP	CRE	ED,ID	BD		7/7/2061
2020 PO1090935935	ODP	2	40 BRN	SP	CCA		V		7/8/2061
2020 1270935272a	ODP	4	40 BRN	SP	CCA		V		7/9/2061
2020 PO1437837568	ODP	2	55 KOP	SP	A	ID	BD		7/10/2061
2020 PO1377036926	ODP	4	45 KOP	SP	S		V		7/11/2061
2020 PO1450637652	ODP	4	45 KOP	SP	A	ED,ID,MD,SRC	TD		7/12/2061
2020 PO3964382711	LGE	4	30 BRN	SP	CCA	ED,ID	BD		7/13/2061
2020 PO2432426870	ODP	4	40 BRN	SP	CRE	ID	TD		7/14/2061
2020 Po2445827168a	ODP	3	45 BRN	SP	CCA		V		7/15/2061
2020 PO2435627047	ODP	4	40 BRN	SP	CRE	ID	TD		7/16/2061
2020 Po2430026670b	ODP	6	30 BRN	SP	CCA		V		7/17/2061
2020 Po2430026670a	ODP	5	35 BRN	SP	CCA	ED	T		7/18/2061
2020 PO2430026670	ODP	4	40 BRN	SP	CRE	ID	TD		7/19/2061
2020 PO2427426565	ODP	4	40 BRN	SP	CRE	ID	TD		7/20/2061
2020 2390126567a	ODP	4	40 BRN	SP	A	ID	TD		7/21/2061
2020 PO6838038800	LGE	3	45 BRN	SP	CCA		V		7/22/2061
2020 PO3965482717	LGE	4	25 BRN	SP	A	ED,ID	BD		7/23/2061
2020 PO3965682721	LGE	3	45 BRN	SP	CRE	ED,ID	TD		7/24/2061
2020 PO5819906197	F	3	45 MAR	SP	P		V		7/25/2061
2020 PO3908182699	LGE	4	25 BRO	SP	P	ED,HH,ID	X	PX	7/26/2061
2020 PO1258435182	ODP	4	40 BRN	SP	CRE	ED,ID	TD		7/27/2061
2020 PO1255435117	ODP	4	40 BRN	SP	CRE	ED,ID	TD		7/28/2061
2020 PO1255534925	ODP	4	40 BRN	SP	CRE	ED,ID	TD		7/29/2061
2020 PO3146450026	KU	5	35 BRO	SP	CRE	ED,ID,IP	TX	RR	7/30/2061
2020 PO3958782757	LGE	3	40 BRN	SP	A	ED,ID	BD		7/31/2061
2020 PO3957882761	F	3	45 BRN	SP	CCA		V		8/1/2061
2020 PO3958482758	F	6	25 BRN	SP	A		V		8/2/2061
2020 PO3956982765	F	2	55 BRN	SP	CRE		V		8/3/2061
2020 PO3971783106	LGE	4	40 BRO	SP	P	ID	BD		8/4/2061
2020 PO3972683124	LGE	6	30 BRO	SP	CRE		V		8/5/2061

2020 PO3879553410	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD		8/6/2061
2020 PO3903053689	KU	4	40 OTH	SP	CRE	ED,ID,SR	TX	RR	8/7/2061
2020 PO3922053918	KU	4	45 OTH	SP	CCA		V		8/8/2061
2020 PO3942454236	KU	6	30 OTH	SP	CRE	ED,ID,SRS	TD		8/9/2061
2020 PO3950054147	KU	4	40 OTH	SP	CRE	ED,ID,RB	X	RP1	8/10/2061
2020 PO3969254287	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD		8/11/2061
2020 PO3982254372	KU	3	45 OTH	SP	CCA		V		8/12/2061
2020 PO4001454502	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD		8/13/2061
2020 PO3706645612	KU	5	45 OTH	SP	CRE		V		8/14/2061
2020 PO3719545363	KU	4	40 OTH	SP	CCA		V		8/15/2061
2020 PO3720545332	KU	4	40 OTH	SP	CCA		V		8/16/2061
2020 PO3727245172	KU	3	45 OTH	SP	CCA		V		8/17/2061
2020 PO3967451048	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD		8/18/2061
2020 PO3982751088	KU	5	35 OTH	SP	CRE		V		8/19/2061
2020 PO5951865732	F	4	45 OTH	SP	CCA		V		8/20/2061
2020 PO5930965678	F	4	40 OTH	SP	CRE		V		8/21/2061
2020 PO5971165783	F	4	45 OTH	SP	CRE		V		8/22/2061
2020 PO5846265396	F	3	45 OTH	SP	P		V		8/23/2061
2020 PO5903565585	F	3	45 OTH	SP	P		V		8/24/2061
2020 PO5987865826	F	4	40 OTH	SP	P		V		8/25/2061
2020 PO5813665291	F	2	50 OTH	SP	CRE		V		8/26/2061
2020 PO5875765493	F	3	45 OTH	SP	P		V		8/27/2061
2020 PO2271144959	ODP	5	35 ACW	SP	CRE	HH,ID,IP,RB	BX	RP2	8/28/2061
2020 PO2260544380	ODP	5	30 ACW	SP	S		V		8/29/2061
2020 PO2259844192	ODP	4	40 ACW	SP	CRE	ED,ID	TD		8/30/2061
2020 PO2262543935	ODP	6	30 ACW	SP	CRE	ID	BD		8/31/2061
2020 PO2252744315	ODP	4	45 ACW	SP	S		V		9/1/2061
2020 PO0310139978	ODP	4	45 XXX	SP	CCA		V		9/2/2061
2020 PO0337640088	ODP	6	30 XXX	SP	CCA		V		9/3/2061
2020 PO0344340043	ODP	5	35 XXX	SP	CCA		V		9/4/2061
2020 PO0343139978	F	4	40 XXX	SP	CCA		V		9/5/2061
2020 PO0933136330	ODP	3	50 XXX	SP	CCA		V		9/6/2061
2020 PO1028736060	ODP	5	35 XXX	SP	CRE		V		9/7/2061
2020 PO0385339822	F	4	40 XXX	SP	CRE		V		9/8/2061
2020 PO0914636410	ODP	3	45 XXX	SP	CCA		V		9/9/2061
2020 0963436254a	ODP	3	45 XXX	SP	CCA		V		9/10/2061
2020 PO0933736349	ODP	3	45 XXX	SP	CCA		V		9/11/2061
2020 PO4686187946	F	4	35 BRO	SP	CRE		V		9/12/2061
2020 PO4620287989	LGE	UNK	30 BRO	SP	CRE		V		9/13/2061
2020 PO4610288028	LGE	UNK	65 BRO	SP	A	ED,ID,IP	BD		9/14/2061
2020 PO4809088845	LGE	4	40 BRN	SP	CRE	ED,HH,ID	BX	PX	9/15/2061
2020 PO4679487762	LGE	4	40 BRO	SP	CRE	ED,ID	TD		9/16/2061
2020 PO3887190294	LGE	3	45 BRO	SP	P	ED,ID	T		9/17/2061
2020 PO4677387750	LGE	4	40 BRO	SP	CRE	ED,ID	BD		9/18/2061
2020 PO4670287542	LGE	4	40 BRO	SP	CRE		V		9/19/2061
2020 PO4670187601	LGE	4	35 BRO	SP	CCA		V		9/20/2061
2020 PO4734510846	KU	4	40 BRO	SP	CRE	ID,IP	BD		9/21/2061

2020 PO4810189004	LGE	4	40 BRN	SP	CRE	ED,HH,ID	BX	RR	9/22/2061
2020 PO4749110785	KU	4	40 BRO	SP	CRE	ID,IP	BD		9/23/2061
2020 PO4807389000	LGE	4	40 BRN	SP	CRE	ED,ID	BD		9/24/2061
2020 PO4808789002	LGE	4	40 BRN	SP	CRE	ED,ID	BD		9/25/2061
2020 PO4722610896	KU	4	40 BRO	SP	CRE	ID,IP	BD		9/26/2061
2020 PO4911359935	KU	6	35 OTH	SP	CRE	ED,ID	TD		9/27/2061
2020 PO4998358813	KU	4	45 OTH	SP	CRE	ED,ID	TD		9/28/2061
2020 PO4927759724	KU	4	40 OTH	SP	CCA	ED	TD		9/29/2061
2020 PO4979159055	KU	4	40 OTH	SP	CCA		V		9/30/2061
2020 PO5018658547	KU	4	40 OTH	SP	CRE	ID	TD		10/1/2061
2020 PO4743987837	LGE	4	40 BRO	SP	P	ED,HH,ID,RB	BX	RP2	10/2/2061
2020 PO4744087856	LGE	4	40 BRO	SP	P	ED,ID	BD		10/3/2061
2020 PO4700911247	KU	5	35 BRO	SP	CRE	ID	BD		10/4/2061
2020 PO4669987651	LGE	4	35 BRO	SP	A	ED,ID	TD		10/5/2061
2020 PO4669787701	LGE	4	35 BRO	SP	P	ED,ID	BD		10/6/2061
2020 PO4804788997	LGE	4	40 BRN	SP	CRE	ED,ID	BD		10/7/2061
2020 PO4806088999	LGE	4	40 BRN	SP	A	ED,ID	BD		10/8/2061
2020 PO4685111057	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD		10/9/2061
2020 PO4678611156	KU	4	40 BRO	SP	CRE		V		10/10/2061
2020 PO4802188994	LGE	4	40 BRN	SP	CRE	ED,ID	BD		10/11/2061
2020 PO4803388995	LGE	4	40 BRN	SP	CRE	ED,ID	BD		10/12/2061
2020 PO4901412318	F	4	40 BRO	SP	CRE		V		10/13/2061
2020 PO4896612203	F	4	40 BRO	SP	CCA		V		10/14/2061
2020 PO4893212127	F	4	40 BRO	SP	CRE		V		10/15/2061
2020 PO4888212017	F	4	40 BRO	SP	CRE		V		10/16/2061
2020 PO4881711932	F	4	40 BRO	SP	CRE		V		10/17/2061
2020 PO4871011786	F	4	40 BRO	SP	CRE	ID,IP	VX	RP2	10/18/2061
2020 PO1807641367	F	4	40 BRN	SP	CRE		V		10/19/2061
2020 PO9636293835	KU	4	45 ACW	SP	CRE	ED,ID,IP	TD		10/20/2061
2020 PO9638293841	KU	4	45 ACW	SP	CRE	ED,ID	TD		10/21/2061
2020 PO5772846707	KU	4	45 ACE	SP	CCA		V		10/22/2061
2020 PO5770446685	KU	5	45 ACE	SP	CRE	ED,ID,IP	BD		10/23/2061
2020 PO9655394418D	KU	5	35 ACW	SP	S		V		10/24/2061
2020 PO9655394418C	KU	6	35 ACW	SP	CRE	ED,ID	BD		10/25/2061
2020 PO9660094137	KU	6	30 ACW	SP	CRE		V		10/26/2061
2020 PO4743930081	KU	4	40 BRO	SP	CRE		V		10/27/2061
2020 PO5762046774	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD		10/28/2061
2020 PO5750246731	KU	5	35 ACE	SP	CCA		V		10/29/2061
2020 PO4749530234	KU	5	35 BRO	SP	CRE		V		10/30/2061
2020 PO4757330424	KU	5	35 BRO	SP	CRE		V		10/31/2061
2020 PO4763930575	KU	5	35 BRO	SP	CRE		V		11/1/2061
2020 PO4773730763	KU	5	35 BRO	SP	CRE		V		11/2/2061
2020 PO9664594309	KU	6	30 ACW	SP	S		V		11/3/2061
2020 PO1811941510	ODP	6	30 BRN	SP	CCA		V		11/4/2061
2020 PO1802841173	F	4	35 KOP	SP	CRE		V		11/5/2061
2020 PO3883182887	LGE	4	30 BRO	SP	P	ED,ID	TD		11/6/2061
2020 PO3882082889	LGE	4	30 BRO	SP	A	ED,ID	TD		11/7/2061

2020 PO3875282943	LGE	4	30 BRO	SP	P	ED,HH,ID,RB	X	RP2	11/8/2061
2020 PO3874182976	LGE	4	30 BRO	SP	CRE	ED,HH,ID,RB	X	RP1	11/9/2061
2020 PO3901582594	LGE	4	30 BRO	SP	P	ED,ID	TD		11/10/2061
2020 PO3902082590	F	3	45 BRO	SP	CCA		V		11/11/2061
2020 PO3901282580	F	4	40 BRO	SP	CCA		V		11/12/2061
2020 PO3902882565	F	4	40 BRO	SP	CCA		V		11/13/2061
2020 PO1572039830	ODP	4	45 KOP	SP	A	ED,ID	TD		11/14/2061
2020 PO1596339846	ODP	6	30 KOP	SP	CCA		V		11/15/2061
2020 PO1608639832	ODP	6	30 KOP	SP	CRE	ED,ID	TD		11/16/2061
2020 PO1599240101	ODP	4	40 KOP	SP	CCA		V		11/17/2061
2020 15963-39846A	ODP	7	20 KOP	SP	A	ED,ID	TD		11/18/2061
2020 PO3904082557	F	4	40 BRO	SP	P		V		11/19/2061
2020 PO3901182565	F	4	25 BRO	SP	CCA		V		11/20/2061
2020 PO3901782572	F	4	40 BRO	SP	P		V		11/21/2061
2020 PO3900482581	LGE	4	30 BRO	SP	CCA		V		11/22/2061
2020 PO2464227433	ODP	4	40 BRN	SP	CRE	ID	TD		11/23/2061
2020 PO2451827266	ODP	6	30 BRN	SP	CCA	ED	T		11/24/2061
2020 PO2437027357	ODP	4	40 BRN	SP	CRE	ID	TD		11/25/2061
2020 PO2437327495	F	4	40 BRN	SP	CRE		V		11/26/2061
2020 PO2410027339	ODP	4	40 BRN	SP	CCA		V		11/27/2061
2020 PO3912782758	F	3	50 BRO	SP	CCA		V		11/28/2061
2020 PO3912282745	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		11/29/2061
2020 PO3911782735	LGE	4	40 BRO	SP	CRE	ED,ID	TD		11/30/2061
2020 PO1129337222	ODP	4	40 XXX	SP	CRE	ID,RB	X	RP1	12/1/2061
2020 PO1119036666	ODP	4	45 XXX	SP	CRE	ED,ID	TD		12/2/2061
2020 PO1115436453	ODP	4	40 XXX	SP	CRE	ED,ID	TD		12/3/2061
2020 PO2410527476	ODP	6	30 BRN	SP	CRE	ID	BD		12/4/2061
2020 PO2424327538	F	5	35 BRN	SP	A		V		12/5/2061
2020 PO2485927167	ODP	4	40 BRN	SP	CRE	ID	TD		12/6/2061
2020 PO3938681871	LGE	4	40 BRN	SP	CRE	ED,ID	TD		12/7/2061
2020 PO3939381882	LGE	4	40 BRN	SP	CRE	ED,ID	TD		12/8/2061
2020 PO9662694288	KU	5	35 ACW	SP	S		V		12/9/2061
2020 PO3938981864	LGE	4	35 BRN	SP	CRE	ED,ID	TD		12/10/2061
2020 PO3946381807	LGE	4	30 BRN	SP	A	ED,ID	TD		12/11/2061
2020 PO1445237748	F	3	45 UNK	SP	CRE		V		12/12/2061
2020 PO1420638173	ODP	4	40 BRN	SP	CRE	ED,ID	TD		12/13/2061
2020 PO1241034196	ODP	5	35 BRN	SP	CCA		V		12/14/2061
2020 PO3910882667	LGE	4	40 BRN	SP	CRE	ED,ID	TD		12/15/2061
2020 PO3935182785	LGE	4	40 BRO	SP	CCA		V		12/16/2061
2020 PO6562439334	LGE	3	50 BRO	SP	CCA		V		12/17/2061
2020 PO3930143340	KU	3	45 ACE	SP	CCA		V		12/18/2061
2020 PO3943843453	KU	3	45 ACE	SP	CCA		V		12/19/2061
2020 PO3914443194	KU	3	45 ACE	SP	CCA		V		12/20/2061
2020 PO3920343253	KU	3	45 ACE	SP	CCA		V		12/21/2061
2020 PO3907643183	KU	3	45 ACE	SP	CCA		V		12/22/2061
2020 PO1136434360	F	4	40 BRN	SP	CRE	ED	V		12/23/2061
2020 PO1137734420	ODP	4	40 BRN	SP	CCA		V		12/24/2061

2020 PO1145034878	F	3	45 MAR	SP	CRE		V	12/25/2061
2020 PO1121434722	ODP	5	35 KOP	SP	CCA		V	12/26/2061
2020 PO1152134971	F	7	30 KOP	SP	CRE		V	12/27/2061
2020 PO1137134740	F	5	35 KOP	SP	CRE		V	12/28/2061
2020 PO3930582806	F	4	40 BRO	SP	CCA		V	12/29/2061
2020 PO3930982806	F	3	45 BRO	SP	CCA		V	12/30/2061
2020 PO3933282796	LGE	4	40 BRO	SP	CCA		V	12/31/2061
2020 PO3938182774	LGE	3	50 BRO	SP	CCA		V	1/1/2062
2020 PO6573339283	LGE	3	50 BRO	SP	CCA		V	1/2/2062
2020 PO3879882930	LGE	4	35 BRO	SP	CCA		V	1/3/2062
2020 PO1146534634	F	4	40 BRN	SP	CRE		V	1/4/2062
2020 PO3939682771	LGE	4	45 BRO	SP	CCA		V	1/5/2062
2020 PO2791052822	KU	4	40 BRO	SP	CCA		V	1/6/2062
2020 PO2817152461	F	4	40 BRO	SP	A		V	1/7/2062
2020 PO6928398258	KU	4	40 BRN	SP	CRE		V	1/8/2062
2020 PO6925998266	KU	4	40 BRN	SP	CRE		V	1/9/2062
2020 PO8848643054A	ODP	5	35 BRN	SP	CCA		V	1/10/2062
2020 PO8848643054	ODP	4	40 BRN	SP	CCA		V	1/11/2062
2020 PO7867425733	KU	4	40 OTH	SP	CRE	ID	TD	1/12/2062
2020 PO8147136982	KU	4	40 OTH	SP	CRE		V	1/13/2062
2020 PO8138637841	KU	4	40 OTH	SP	CRE		V	1/14/2062
2020 PO8145336695	KU	4	40 OTH	SP	CRE		V	1/15/2062
2020 PO3926483102	F	4	40 BRO	SP	CCA		V	1/16/2062
2020 PO3927483117	F	4	40 BRO	SP	CCA		V	1/17/2062
2020 PO3928283128	F	4	40 BRO	SP	P		V	1/18/2062
2020 PO3929183141	F	4	40 BRO	SP	P		V	1/19/2062
2020 PO3924482395	LGE	4	40 BRN	SP	CCA	ED,ID	BD	1/20/2062
2020 PO3981582878	F	4	40 BRN	SP	A		V	1/21/2062
2020 PO3929983154	F	4	40 BRO	SP	P		V	1/22/2062
2020 PO3929783158	F	4	30 BRO	SP	CCA		V	1/23/2062
2020 PO3930883166	F	5	40 BRO	SP	A		V	1/24/2062
2020 PO3932583178	F	5	25 BRO	SP	A		V	1/25/2062
2020 PO3980282881	F	4	30 BRN	SP	A		V	1/26/2062
2020 PO3925682421	LGE	3	45 BRN	SP	CRE	ED,ID	TD	1/27/2062
2020 PO3925282412	LGE	3	45 BRN	SP	CCA		V	1/28/2062
2020 PO1240437668	F	4	40 KOP	SP	P		V	1/29/2062
2020 PO1222437706	F	4	40 OTH	SP	P		V	1/30/2062
2020 PO1260737652	F	4	40 KOP	SP	CRE		V	1/31/2062
2020 PO3977382850	LGE	4	30 BRN	SP	CCA		V	2/1/2062
2020 PO3977482843	F	4	40 BRN	SP	CRE		V	2/2/2062
2020 PO1264137513	F	4	40 KOP	SP	CRE	ED	V	2/3/2062
2020 PO3975582854	F	4	40 BRN	SP	CCA		V	2/4/2062
2020 PO1141135454	ODP	4	40 XXX	SP	CRE		V	2/5/2062
2020 PO1144835498	ODP	4	40 XXX	SP	S		V	2/6/2062
2020 PO1253337367	ODP	4	40 KOP	SP	CRE		V	2/7/2062
2020 PO2480134993	KU	5	35 BRN	SP	CRE	HH,ID,IP,RB	BX	2/8/2062
2020 PO3974982837	F	4	35 BRN	SP	S		V	2/9/2062

2020 PO1223837297	ODP	6	30 KOP	SP	CRE		V		2/10/2062
2020 PO1213837202	F	4	40 KOP	SP	P	ID,IP	VX	RP3	2/11/2062
2020 PO3975782838	F	3	45 BRN	SP	S		V		2/12/2062
2020 PO2498334749	KU	4	40 BRN	SP	CCA		V		2/13/2062
2020 PO2508134620	KU	3	45 BRN	SP	CCA		V		2/14/2062
2020 PO3975982822	F	3	35 BRN	SP	S		V		2/15/2062
2020 PO3975282805	F	5	30 BRN	SP	S		V		2/16/2062
2020 PO3976182806	F	3	45 BRN	SP	S		V		2/17/2062
2020 PO1118335208	ODP	5	35 XXX	SP	S		V		2/18/2062
2020 PO1053034890	ODP	6	30 BRN	SP	CCA		V		2/19/2062
2020 PO3975582793	LGE	4	30 BRN	SP	CRE		V		2/20/2062
2020 PO1055734813	ODP	4	40 BRN	SP	CCA		V		2/21/2062
2020 PO1054234588	ODP	4	40 BRN	SP	CCA		V		2/22/2062
2020 PO3976382794	F	4	40 BRN	SP	CCA		V		2/23/2062
2020 PO1050434325	ODP	3	45 BRN	SP	CCA		V		2/24/2062
2020 PO1049334195	ODP	3	45 BRN	SP	CCA		V		2/25/2062
2020 PO3976682779	F	3	45 BRN	SP	S		V		2/26/2062
2020 PO3976682779A	LGE	4	30 BRN	SP	S		V		2/27/2062
2020 PO3876582783	LGE	4	35 BRO	SP	P	ED,ID	TD		2/28/2062
2020 PO3877982754	LGE	4	40 BRO	SP	CRE	ED,HH,ID,RB	X	RP1	3/1/2062
2020 PO3878182764	LGE	4	40 BRO	SP	A	ED,ID	TD		3/2/2062
2020 PO3977482766	F	4	35 BRN	SP	S		V		3/3/2062
2020 PO3977482775	F	3	45 BRN	SP	CCA		V		3/4/2062
2020 PO1118035271	ODP	4	40 XXX	SP	CRE	ED,ID	TD		3/5/2062
2020 PO3978882777	F	4	40 BRN	SP	CCA		V		3/6/2062
2020 PO1121135410	ODP	5	35 XXX	SP	S		V		3/7/2062
2020 PO1130835257	ODP	5	35 XXX	SP	A	ED,ID	TD		3/8/2062
2020 PO3979782778	F	4	40 BRN	SP	CRE		V		3/9/2062
2020 PO3979482791	LGE	4	35 BRN	SP	CCA		V		3/10/2062
2020 PO3981082786	F	5	30 BRN	SP	CRE		V		3/11/2062
2020 PO3981282781	F	4	40 BRN	SP	CRE		V		3/12/2062
2020 PO3528647551	KU	4	40 ACE	SP	CRE	ED,ID	TD		3/13/2062
2020 PO3982882774	F	4	30 BRN	SP	CCA		V		3/14/2062
2020 PO3982682782	F	4	40 BRN	SP	S		V		3/15/2062
2020 PO3982382788	F	4	30 BRN	SP	CCA		V		3/16/2062
2020 PO1140835309	ODP	5	35 XXX	SP	CCA	ED,ID	TD		3/17/2062
2020 PO1139835251	ODP	4	45 XXX	SP	CRE	ID	BD		3/18/2062
2020 PO2112136827	KU	3	45 BRO	SP	P	ED	T		3/19/2062
2020 PO2130637255	KU	4	40 BRO	SP	CRE	ED	T		3/20/2062
2020 PO2233440129	KU	4	40 BRO	SP	CRE	ID,IP	BD		3/21/2062
2020 PO2233740629	KU	2	45 BRO	SP	CRE	ED,ID,IP	TD		3/22/2062
2020 PO1147535255	ODP	4	45 XXX	SP	CRE	ID	BD		3/23/2062
2020 PO4798088784	LGE	4	40 BRN	SP	A	ED,ID,IP	BX	RR	3/24/2062
2020 PO1153035277	ODP	4	40 XXX	SP	CRE	ID	BD		3/25/2062
2020 PO1164335262	ODP	4	40 XXX	SP	CRE	ID	BD		3/26/2062
2020 PO1175035185	ODP	4	45 XXX	SP	CRE	ID	BD		3/27/2062
2020 PO3981482894	LGE	4	30 BRN	SP	CRE	ED,ID	BD		3/28/2062

Business Use

2020 PO2295941854	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		3/29/2062
2020 PO3982982897	F	6	25 BRN	SP	CRE		V		3/30/2062
2020 PO2283041481	KU	3	45 BRO	SP	CRE	ID,IP	BD		3/31/2062
2020 PO2349742114	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		4/1/2062
2020 PO2328942139	KU	3	55 BRO	SP	CRE	ED,ID,IP	TD		4/2/2062
2020 PO3982182895	F	3	45 BRN	SP	S		V		4/3/2062
2020 PO3629941313a	KU	4	40 ACE	SP	CCA		V		4/4/2062
2020 PO3629941313	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		4/5/2062
2020 PO3980583114	LGE	3	45 BRN	SP	CRE	ED,ID	TD		4/6/2062
2020 PO3980383101	LGE	4	30 BRN	SP	CRE	ED,ID	TD		4/7/2062
2020 PO3979183106	LGE	6	25 BRN	SP	CRE	ED,ID	TD		4/8/2062
2020 PO3651341732	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD		4/9/2062
2020 PO3979983105	LGE	4	40 BRN	SP	P	ED,ID	TD		4/10/2062
2020 PO4798488784	LGE	3	65 BRN	SP	CRE		V		4/11/2062
2020 PO4799488789	LGE	4	40 BRN	SP	A	ED,ID,IP,SRC	TX	RR	4/12/2062
2020 PO2608953541	KU	3	45 BRO	SP	P	ED	T		4/13/2062
2020 PO2578353754	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD		4/14/2062
2020 PO4800488793	LGE	3	65 BRN	SP	CRE		V		4/15/2062
2020 PO0549928932	ODP	5	35 XXX	SP	CRE		V		4/16/2062
2020 PO0510529441	ODP	5	35 XXX	SP	CRE		V		4/17/2062
2020 PO0493929659	ODP	5	35 XXX	SP	CRE		V		4/18/2062
2020 PO0884450076	KU	4	45 BRN	SP	CCA	ID	BD		4/19/2062
2020 PO9127257612	KU	3	45 BRN	SP	P	ED,SRC	T		4/20/2062
2020 PO9158657462	KU	4	40 BRN	SP	CCA	ID	BD		4/21/2062
2020 PO9166463384	KU	4	40 ACW	SP	CRE	ID	BD		4/22/2062
2020 PO9379460508	KU	4	45 ACW	SP	P	ED	T		4/23/2062
2020 PO9354360749	KU	4	45 ACW	SP	CRE		V		4/24/2062
2020 PO2898239210	ODP	4	40 BRN	SP	CCA		V		4/25/2062
2020 PO2954939118	ODP	5	35 BRN	SP	CRE	ED,ID	TD		4/26/2062
2020 PO2958839271	ODP	4	45 BRN	SP	CCA		V		4/27/2062
2020 PO2993439223	ODP	4	40 BRN	SP	CRE	ED,ID	TD		4/28/2062
2020 PO2971939260	ODP	4	45 BRN	SP	CRE		V		4/29/2062
2020 PO2955039632	ODP	5	35 BRN	SP	CRE	ED,ID	TD		4/30/2062
2020 PO1786222752	ODP	5	35 XXX	SP	CCA		V		5/1/2062
2020 PO3988182223	LGE	4	40 BRN	SP	A	ED,HH,ID,RB	X	PX	5/2/2062
2020 PO3988482229	LGE	5	30 BRN	SP	A	ED,ID	TD		5/3/2062
2020 PO3989982242	LGE	4	30 BRN	SP	CRE	ED,ID	BX	RR	5/4/2062
2020 PO3990582246	LGE	4	40 BRN	SP	A	ED,ID	BD		5/5/2062
2020 PO3990682248	LGE	4	40 BRN	SP	S		V		5/6/2062
2020 PO4554131042	KU	2	45 ACE	SP	CRE	ID	BD		5/7/2062
2020 PO0341536632	ODP	4	45 BRN	SP	CCA		V		5/8/2062
2020 PO0326536345	ODP	4	40 BRN	SP	P		V		5/9/2062
2020 PO0292536387	ODP	2	65 BRN	SP	CCA		V		5/10/2062
2020 PO0312136491	ODP	2	60 BRN	SP	CCA		V		5/11/2062
2020 PO0347837032	ODP	2	50 BRN	SP	CCA		V		5/12/2062
2020 PO0342636837	ODP	2	50 BRN	SP	CCA		V		5/13/2062
2020 PO0330136670	ODP	2	60 BRN	SP	CCA		V		5/14/2062

2020 PO0357437260	ODP	2	50 BRN	SP	CCA		V	5/15/2062
2020 PO0368437475	ODP	2	50 BRN	SP	CCA		V	5/16/2062
2020 PO0384037680	ODP	2	50 BRN	SP	CCA		V	5/17/2062
2020 PO0385938140	ODP	2	50 XXX	SP	CCA		V	5/18/2062
2020 PO4551630982	KU	2	45 ACE	SP	CCA		V	5/19/2062
2020 PO1238521334	ODP	5	35 UNK	SP	CRE	ID	TD	5/20/2062
2020 PO7167688965	KU	4	40 BRN	SP	CRE	ED,ID	TD	5/21/2062
2020 PO7190788943	KU	4	40 BRN	SP	CRE	ED,ID	BD	5/22/2062
2020 PO7110989174	KU	5	35 BRN	SP	CRE	ED,ID	BD	5/23/2062
2020 PO7155389055	KU	6	30 BRN	SP	CRE	ED,ID	TD	5/24/2062
2020 PO7123188971	KU	6	30 BRN	SP	P	ED,ID	TD	5/25/2062
2020 PO7126789235	KU	3	55 BRN	SP	CRE	ED,ID	BD	5/26/2062
2020 PO5445312789	KU	5	35 BRO	SP	CRE		V	5/27/2062
2020 PO5432611644	KU	5	30 BRO	SP	CRE	ID	TD	5/28/2062
2020 PO7427892197	F	4	40 BRO	SP	A		V	5/29/2062
2020 PO7423692170	F	4	40 BRO	SP	CRE		V	5/30/2062
2020 PO7436892094	F	3	40 BRO	SP	CRE		V	5/31/2062
2020 PO7450792022	F	3	35 BRO	SP	CCA		V	6/1/2062
2020 PO7555891757	KU	5	35 BRO	SP	CRE	ED,ID	TD	6/2/2062
2020 PO6976894738	KU	4	40 BRN	SP	CRE	ED,ID	TD	6/3/2062
2020 PO6977794863	KU	4	40 BRN	SP	CRE	ED,ID	TD	6/4/2062
2020 PO7133289310	KU	3	50 BRN	SP	CRE	ED,ID	BD	6/5/2062
2020 PO4546330859	KU	3	45 ACE	SP	CRE	ED,ID	BD	6/6/2062
2020 PO4552230756	KU	3	45 ACE	SP	CCA		V	6/7/2062
2020 PO3980129845	KU	4	40 BRO	SP	CRE	ID,IP	BD	6/8/2062
2020 PO3599147290	F	4	40 BRO	SP	CRE		V	6/9/2062
2020 PO3611647198	F	4	40 BRO	SP	CRE		V	6/10/2062
2020 PO3990982255	LGE	3	45 BRN	SP	A	ED,ID	BD	6/11/2062
2020 PO3990582257	LGE	4	40 BRN	SP	CRE	ED,ID	TD	6/12/2062
2020 PO1799023140	F	4	40 XXX	SP	A		V	6/13/2062
2020 PO1903222912	ODP	4	40 XXX	SP	CRE	ID	TD	6/14/2062
2020 PO1890322879	ODP	5	35 XXX	SP	CRE	ID	TD	6/15/2062
2020 PO1871423044	ODP	4	40 XXX	SP	CRE	ID	TD	6/16/2062
2020 PO1884123068	ODP	5	35 XXX	SP	CRE	ID	TD	6/17/2062
2020 PO1861223344	ODP	4	40 XXX	SP	CRE	ID	TD	6/18/2062
2020 PO1846723482	ODP	4	40 XXX	SP	CCA		V	6/19/2062
2020 PO1918023595	ODP	4	40 XXX	SP	CRE	ID	TD	6/20/2062
2020 PO0371937880	ODP	2	50 XXX	SP	CCA		V	6/21/2062
2020 PO4567730461	KU	3	45 ACE	SP	CRE	ID	BD	6/22/2062
2020 PO7119789113	KU	2	55 BRN	SP	CCA		V	6/23/2062
2020 PO7128389053	F	4	40 BRN	SP	CRE		V	6/24/2062
2020 PO7136389138	KU	4	35 BRN	SP	CRE	ED,ID	BD	6/25/2062
2020 PO6979094990	KU	4	40 BRN	SP	CRE	ED,ID	TD	6/26/2062
2020 PO6980295137	KU	4	40 BRN	SP	CRE	ED,ID	TD	6/27/2062
2020 PO6981395237	KU	4	40 BRN	SP	CCA		V	6/28/2062
2020 PO6981995317	F	2	40 BRN	SP	CCA		V	6/29/2062
2020 PO6295206816	KU	5	35 BRN	SP	CRE		V	6/30/2062

2020 PO7145789152	KU	6	30 BRN	SP	CRE		V		7/1/2062
2020 PO7509291680	KU	4	40 BRO	SP	CRE	ED	VX	RP3	7/2/2062
2020 PO7522591600	KU	5	35 BRO	SP	CRE	ED,ID	BD		7/3/2062
2020 PO7539291679	KU	5	35 BRO	SP	CRE	ID	BD		7/4/2062
2020 PO5457310329	KU	6	30 BRO	SP	CCA		V		7/5/2062
2020 PO5465110298	KU	6	30 BRO	SP	CRE	ID	TD		7/6/2062
2020 PO5471110319	KU	5	35 BRO	SP	CRE	ID	TD		7/7/2062
2020 PO5444610024	KU	4	40 BRO	SP	CRE	ID	TD		7/8/2062
2020 PO5443613065	KU	4	40 BRO	SP	CRE	ID	BD		7/9/2062
2020 PO5455212945	KU	6	30 BRO	SP	CRE	ID	TD		7/10/2062
2020 PO5455812882	KU	4	40 BRO	SP	CRE	ID	TD		7/11/2062
2020 PO5444812933	KU	5	45 BRO	SP	CRE	ID	BD		7/12/2062
2020 PO5445912643	KU	5	30 BRO	SP	CCA		V		7/13/2062
2020 PO5434412284	KU	4	35 BRO	SP	CCA		V		7/14/2062
2020 PO5426412031a	KU	4	40 BRO	SP	CCA		V		7/15/2062
2020 PO5424412137	KU	5	30 BRO	SP	CRE		V		7/16/2062
2020 PO5422712238	KU	5	30 BRO	SP	CRE		V		7/17/2062
2020 PO5428211903	KU	5	30 BRO	SP	CRE	ID	BD		7/18/2062
2020 PO5443311807	KU	6	30 BRO	SP	CCA		V		7/19/2062
2020 PO7151589078	KU	5	30 BRN	SP	CRE	ED,ID	BD		7/20/2062
2020 PO5454711367	KU	5	30 BRO	SP	CRE	ID	TD		7/21/2062
2020 PO7178688952	KU	4	45 BRN	SP	CRE	ED,ID	TD		7/22/2062
2020 PO7022695030	KU	4	45 BRN	SP	CRE	ED,ID	BD		7/23/2062
2020 PO7017494888	KU	4	40 BRN	SP	CCA		V		7/24/2062
2020 PO7011594770	KU	5	35 BRN	SP	CRE	ED,ID	TD		7/25/2062
2020 PO7008794675	KU	4	40 BRN	SP	CRE	ED,ID	TD		7/26/2062
2020 PO3554847480	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		7/27/2062
2020 PO2396344639	KU	4	40 BRN	SP	CRE	ED,EP,ID	BD		7/28/2062
2020 PO2319644592	KU	6	30 BRN	SP	CRE		V		7/29/2062
2020 PO3549647808	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD		7/30/2062
2020 PO3566147695	KU	4	40 ACE	SP	CRE	ED,ID	TD		7/31/2062
2020 PO3575247856	KU	4	45 ACE	SP	CCA		V		8/1/2062
2020 PO7588279093	KU	3	45 BRO	SP	CRE		V		8/2/2062
2020 PO7585779101	KU	3	45 BRO	SP	CRE		V		8/3/2062
2020 PO7598578921	KU	4	45 BRO	SP	CRE	ED,ID	TX	RR	8/4/2062
2020 PO7670179454	KU	3	50 BRO	SP	CRE	ED,ID	TD		8/5/2062
2020 PO6565203501A	KU	6	30 BRO	SP	CRE	ED,ID	TD		8/6/2062
2020 PO6560703456	KU	6	30 BRO	SP	CRE	ED,ID	TD		8/7/2062
2020 PO6578503630	KU	4	40 BRO	SP	CRE	ED,ID	TD		8/8/2062
2020 PO6559503619	KU	6	30 BRO	SP	CRE	ED,ID	TD		8/9/2062
2020 PO3586848055	KU	4	45 ACE	SP	CCA		V		8/10/2062
2020 PO3597748253	KU	4	45 ACE	SP	CCA		V		8/11/2062
2020 PO2345644242	KU	4	35 BRN	SP	CRE	ED,ID,IP,MD,SRC	TD		8/12/2062
2020 PO3968283147	LGE	4	40 BRO	SP	CRE	ED,ID	TD		8/13/2062
2020 PO3971483124	LGE	4	40 BRO	SP	P	ED,ID	BD		8/14/2062
2020 PO3969883136	LGE	4	40 BRO	SP	P	ED,ID	TD		8/15/2062
2020 PO3969683130	LGE	4	30 BRO	SP	P	ED,ID	TD		8/16/2062

2020 PO3950482922	LGE	4	45 BRO	SP	CCA		V	8/17/2062
2020 PO3948482888	LGE	4	45 BRO	SP	CCA		V	8/18/2062
2020 PO9576142529	ODP	5	35 XXX	SP	CRE	ED,ID	TD	8/19/2062
2020 PO9564742522	F	4	40 XXX	SP	P		V	8/20/2062
2020 PO9555142672	ODP	4	40 XXX	SP	CRE	ED,ID	TD	8/21/2062
2020 PO9535042617	ODP	5	35 BRN	SP	CCA		V	8/22/2062
2020 PO9512036457	ODP	3	45 BRN	SP	CRE		V	8/23/2062
2020 PO9521836582	ODP	5	30 BRN	SP	CRE		V	8/24/2062
2020 PO9533936768	ODP	4	45 BRN	SP	CCA		V	8/25/2062
2020 PO1237029905	ODP	4	45 BRN	SP	CCA		V	8/26/2062
2020 PO1262629813	ODP	4	45 BRN	SP	CCA	ID	V	8/27/2062
2020 PO1312230207	ODP	5	35 BRN	SP	CRE	ID	TD	8/28/2062
2020 PO1314629713	ODP	6	30 BRN	SP	CRE	ID	TD	8/29/2062
2020 PO2334944305	KU	4	35 BRN	SP	CRE	HH,ID,IP,MD,SRC	TD	8/30/2062
2020 PO2324344372	KU	4	35 BRN	SP	CRE	ED,ID,MD,SRC	TD	8/31/2062
2020 PO2427444003	F	4	40 BRN	SP	CRE		V	9/1/2062
2020 PO3608848449	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	9/2/2062
2020 PO3628548800	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	9/3/2062
2020 PO3618648626	KU	4	40 ACE	SP	CRE	ED,ID	TD	9/4/2062
2020 PO3641148718	KU	4	40 ACE	SP	CRE	ED,HH,ID,IP,RB	BX	9/5/2062
2020 PO7670179454A	KU	3	50 BRO	SP	CCA		V	9/6/2062
2020 PO7679578922	KU	4	40 BRO	SP	CRE		V	9/7/2062
2020 PO7681878952	KU	5	35 BRO	SP	P	ED,ID	TD	9/8/2062
2020 PO7676878930	KU	4	45 BRO	SP	CRE		V	9/9/2062
2020 PO7682178792	KU	6	30 BRO	SP	CRE	ID	BD	9/10/2062
2020 PO7665078966	KU	4	40 BRO	SP	CRE	ED,ID	B	9/11/2062
2020 PO7649979012	KU	4	40 BRO	SP	CRE		B	9/12/2062
2020 PO0597963773	KU	3	45 BRN	SP	CRE	ED	T	9/13/2062
2020 PO0597963773-A	KU	4	40 BRN	SP	P	ED	T	9/14/2062
2020 PO0603463611	KU	3	50 BRN	SP	P	ED	T	9/15/2062
2020 PO0621263536	KU	3	50 BRN	SP	CCA		V	9/16/2062
2020 PO0625763314	KU	3	50 BRN	SP	P	ED	T	9/17/2062
2020 PO1111176358	KU	4	40 BRN	SP	CRE		V	9/18/2062
2020 PO1091276028	KU	4	40 BRN	SP	CRE		V	9/19/2062
2020 PO1060075550	KU	5	35 BRN	SP	CRE		V	9/20/2062
2020 PO9359094085	F	4	40 ACW	SP	CRE		V	9/21/2062
2020 PO9368394047	KU	6	30 ACW	SP	CRE	ED,ID	TD	9/22/2062
2020 PO9353894200	F	4	40 ACW	SP	CRE		V	9/23/2062
2020 PO9383294121	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	9/24/2062
2020 PO5869711056	KU	5	35 BRO	SP	CCA		V	9/25/2062
2020 PO5970212102	KU	5	35 BRO	SP	CRE	ED,ID	TX	9/26/2062
2020 PO2265413079A	KU	5	35 OTH	SP	CCA		V	9/27/2062
2020 PO2439654637	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	9/28/2062
2020 PO2109611949	KU	4	40 UNK	SP	CRE	ED,ID	TD	9/29/2062
2020 PO2281113219	F	4	40 BRO	SP	CRE		V	9/30/2062
2020 PO2213013021	KU	6	30 BRO	SP	P		V	10/1/2062
2020 PO2199113194	KU	6	35 BRO	SP	CRE	ED,ID	TD	10/2/2062

2020 PO2214312918	KU	4	45 BRO	SP	CRE	ED,ID	TD	10/3/2062
2020 PO2240113213	F	4	40 BRO	SP	CRE		V	10/4/2062
2020 PO2258212993	KU	6	30 BRO	SP	CRE	ED,ID	TD	10/5/2062
2020 PO4704228326	KU	6	30 BRO	SP	CCA		V	10/6/2062
2020 PO2265413079	KU	4	40 BRO	SP	CRE	ED,ID	TD	10/7/2062
2020 PO2274713060	KU	4	35 BRO	SP	CCA		V	10/8/2062
2020 PO2305413326	KU	4	40 BRO	SP	CRE	ED,ID	TD	10/9/2062
2020 PO2287813021	KU	6	30 BRO	SP	CRE	ED,ID	TD	10/10/2062
2020 PO2286713146	KU	4	40 UNK	SP	CRE	ED,ID,SRS	TD	10/11/2062
2020 PO2312713226	KU	4	40 UNK	SP	CRE	ED,ID	TD	10/12/2062
2020 PO2338213441	KU	5	35 UNK	SP	CRE	ED,EP,HH,ID,IP,RB,SRC	X	RP1 10/13/2062
2020 PO2379313594	KU	5	35 UNK	SP	CRE	ED,ID	TD	10/14/2062
2020 PO2490913997	KU	4	40 UNK	SP	CRE	ED,ID	TD	10/15/2062
2020 PO2466213905	KU	4	40 UNK	SP	CRE	ED,ID	TD	10/16/2062
2020 PO2469214050	KU	4	40 UNK	SP	CRE	ED,ID	TD	10/17/2062
2020 PO2446613839	KU	5	35 UNK	SP	CRE	ED,ID	TD	10/18/2062
2020 PO2411813576	KU	6	30 UNK	SP	CRE	ED,ID	TD	10/19/2062
2020 PO6231805194	KU	4	40 XXX	SP	CRE		V	10/20/2062
2020 PO6325207617	KU	5	35 XXX	SP	CRE		V	10/21/2062
2020 PO6335107424	KU	6	30 XXX	SP	CRE		V	10/22/2062
2020 PO6342307207	KU	4	40 XXX	SP	CRE		V	10/23/2062
2020 PO6326807147	KU	4	40 XXX	SP	CRE		V	10/24/2062
2020 PO7242689752	F	4	40 BRO	SP	CRE		V	10/25/2062
2020 PO7236589781	F	3	40 BRO	SP	CRE		V	10/26/2062
2020 PO7245089790	F	4	35 BRO	SP	CCA		V	10/27/2062
2020 PO7252489879	F	4	35 BRO	SP	CCA		V	10/28/2062
2020 PO7260089634	F	4	40 BRO	SP	CRE		V	10/29/2062
2020 PO7269389568	F	3	40 BRO	SP	CRE		V	10/30/2062
2020 PO7268389430	KU	3	40 BRO	SP	CRE	ED,ID	TD	10/31/2062
2020 PO6877493596	KU	3	45 BRN	SP	CCA		V	11/1/2062
2020 PO6885193597	KU	3	45 BRN	SP	CRE		V	11/2/2062
2020 PO6892393605	KU	3	45 BRN	SP	CRE		V	11/3/2062
2020 PO2844341619	KU	4	45 BRN	SP	CRE	ID	BD	11/4/2062
2020 PO4136935184	KU	5	30 BRO	SP	CRE	ED,ID,IP	TD	11/5/2062
2020 PO4097635493	KU	5	30 BRO	SP	CRE	ED,ID,IP	TD	11/6/2062
2020 PO4067035739	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	11/7/2062
2020 A	KU	5	30 UNK	SP	P	ID	TD	11/8/2062
2020 PO8454125924	KU	4	45 UNK	SP	P	ID	TD	11/9/2062
2020 PO8473126289	KU	4	40 UNK	SP	CRE	ID	TD	11/10/2062
2020 PO8535725220	KU	5	35 UNK	SP	CRE	ID	TD	11/11/2062
2020 PO8624225112	F	5	35 UNK	SP	CCA		V	11/12/2062
2020 PO8588325338	KU	4	40 UNK	SP	P	ED,SRS	TD	11/13/2062
2020 PO8617625297	KU	4	45 UNK	SP	P	ID	TD	11/14/2062
2020 PO8524125441	F	4	40 UNK	SP	P		B	11/15/2062
2020 PO8563625197	KU	5	30 UNK	SP	CRE	ID	TD	11/16/2062
2020 PO8570325222	KU	3	45 UNK	SP	CCA		V	11/17/2062
2020 PO8462726109	KU	4	40 UNK	SP	CRE	ID	TD	11/18/2062

2020 PO8495025649	F	4	40 UNK	SP	P		B	11/19/2062
2020 PO8528825315	KU	5	30 UNK	SP	CRE	ID	TD	11/20/2062
2020 PO8446925803	F	2	40 UNK	SP	P		B	11/21/2062
2020 PO8560225379	F	4	40 UNK	SP	P		B	11/22/2062
2020 PO8517525325	KU	5	35 UNK	SP	CRE	ID	TD	11/23/2062
2020 PO8522325236	KU	5	35 UNK	SP	CRE	ID	TD	11/24/2062
2020 PO8628925052	KU	2	50 UNK	SP	CRE	ID	TD	11/25/2062
2020 PO4686127849	KU	4	40 BRO	SP	CCA		V	11/26/2062
2020 PO4663127699	KU	4	40 BRO	SP	CRE	ED,ID	TD	11/27/2062
2020 PO9463893699	C	4	40 XXX	SP	CRE	ED,ID	V	11/28/2062
2020 PO9464493668	C	4	40 XXX	SP	CRE	ED,ID	V	11/29/2062
2020 PO9510394910	KU	6	30 ACW	SP	S		V	11/30/2062
2020 PO9519694884	KU	4	40 ACW	SP	CRE	ED,ID,IP	BD	12/1/2062
2020 PO9492294786	C	4	40 ACW	SP	CRE		V	12/2/2062
2020 PO5629646551	KU	6	30 ACE	SP	CRE	ED,ID	BD	12/3/2062
2020 PO9471993721	KU	4	40 XXX	SP	CRE	ED,ID	TD	12/4/2062
2020 PO9461893707	KU	4	40 XXX	SP	CRE	ED,ID	TD	12/5/2062
2020 PO5655046666	KU	6	30 ACE	SP	CCA	ED	T	12/6/2062
2020 PO9490793704	KU	5	35 KOP	SP	CRE	ED,ID	TD	12/7/2062
2020 PO5703947421	KU	3	45 ACE	SP	CCA		V	12/8/2062
2020 PO9480793681	KU	5	35 KOP	SP	S		V	12/9/2062
2020 PO4792827694	C	4	40 BRO	SP	CRE		V	12/10/2062
2020 PO9493694861	C	4	40 ACW	SP	CRE		V	12/11/2062
2020 PO9471194799	C	4	40 ACW	SP	CRE		V	12/12/2062
2020 PO4078035649	KU	5	35E BRO	SP	CCA		V	12/13/2062
2020 PO7275988913	KU	5	35 BRO	SP	CRE	ED,ID,IP	BD	12/14/2062
2020 PO7290188858	KU	5	35 BRO	SP	CCA		V	12/15/2062
2020 PO7285288808	KU	5	35 BRO	SP	CRE		V	12/16/2062
2020 PO7280688767	KU	5	35 BRO	SP	CRE		V	12/17/2062
2020 PO7275888725	LGE	3	30 BRO	SP	CCA		V	12/18/2062
2020 PO4067035739-A	KU	4	40 BRO	SP	P	ED	TD	12/19/2062
2020 PO2413754712	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	12/20/2062
2020 PO3230742496	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	12/21/2062
2020 PO7209689700	KU	4	45 BRO	SP	CRE	ED,ID	TD	12/22/2062
2020 PO7215489681	KU	5	35 BRO	SP	CRE	ED,ID	TD	12/23/2062
2020 PO7231289564	F	3	40 BRO	SP	CRE		V	12/24/2062
2020 PO5611444482	F	4	40 ACW	SP	P		V	12/25/2062
2020 PO5625144523	F	4	40 ACW	SP	CRE		V	12/26/2062
2020 PO5620544634	F	4	40 ACW	SP	CRE		V	12/27/2062
2020 PO5612544794	F	4	40 ACW	SP	CRE		V	12/28/2062
2020 PO5602744969	F	4	40 ACW	SP	CRE		V	12/29/2062
2020 PO6033238417	KU	4	40 BRN	SP	CRE	ED,ID	TD	12/30/2062
2020 PO5983439677	KU	4	40 BRN	SP	CRE	ED,ID	TD	12/31/2062
2020 PO3585247402	F	4	40 ACE	SP	CRE	ED,ID	V	1/1/2063
2020 PO3563047494	F	4	40 ACE	SP	CRE	ED,ID	V	1/2/2063
2020 PO3536947605	F	4	40 ACE	SP	CRE	ED,ID	V	1/3/2063
2020 PO3337048109	F	4	40 ACE	SP	CRE		V	1/4/2063

2020 PO5841640462	F	3	50 BRN	SP	P		V	1/5/2063
2020 PO3510747703	F	4	40 ACE	SP	CRE	ED,ID	V	1/6/2063
2020 PO5891140259	F	3	50 BRN	SP	P		V	1/7/2063
2020 PO5872940314	F	3	50 BRN	SP	P		V	1/8/2063
2020 PO5853240363	F	3	50 BRN	SP	P		V	1/9/2063
2020 PO5911040197	F	3	50 BRN	SP	P		V	1/10/2063
2020 PO4374702956	F	4	40 BRO	SP	CCA		V	1/11/2063
2020 PO4375402701	KU	3	45 BRO	SP	CCA		V	1/12/2063
2020 PO3483847832	F	4	40 ACE	SP	CCA		V	1/13/2063
2020 PO3455247958	F	4	40 ACE	SP	CRE	ED,ID	V	1/14/2063
2020 PO3426248079	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	VX	RP1 1/15/2063
2020 PO5559044581	F	4	40 ACW	SP	P		V	1/16/2063
2020 PO5551044560	KU	3	45 ACW	SP	S		V	1/17/2063
2020 PO5544144482	F	4	40 ACW	SP	CRE		V	1/18/2063
2020 PO3397848205	F	4	40 ACE	SP	CRE	ED,ID	V	1/19/2063
2020 PO3368448324	F	4	40 ACE	SP	CRE	ED,ID	V	1/20/2063
2020 PO4717511417	KU	4	40 BRO	SP	CRE		V	1/21/2063
2020 PO5179402910	LGE	4	35 BRN	SP	S		V	1/22/2063
2020 PO4711011232	KU	4	40 BRO	SP	CRE	ID,IP	BD	1/23/2063
2020 PO4711011232	KU	4	40 BRO	SP	CRE	ID,IP	BD	1/24/2063
2020 PO4743787825	LGE	4	40 BRO	SP	P	ED,ID	TD	1/25/2063
2020 PO4816612672	F	4	40 BRO	SP	CRE		V	1/26/2063
2020 PO4829912616	F	4	40 BRO	SP	CRE		V	1/27/2063
2020 PO4842512563	F	4	40 BRO	SP	CRE		V	1/28/2063
2020 PO4854812511	F	4	40 BRO	SP	CRE		V	1/29/2063
2020 PO4868212455	F	4	40 BRO	SP	CRE	HH,ID,RB	VX	RP1 1/30/2063
2020 PO4674187959	LGE	UNK	45 BRO	SP	CRE		V	1/31/2063
2020 PO4675487958	F	4	40 BRO	SP	CRE		V	2/1/2063
2020 PO4677187956	F	4	35 BRO	SP	CRE		V	2/2/2063
2020 PO4678587954	F	4	35 BRO	SP	CRE		V	2/3/2063
2020 PO4680187953	F	4	35 BRO	SP	CRE		V	2/4/2063
2020 PO4681587951	F	4	35 BRO	SP	CRE		V	2/5/2063
2020 PO4683087950	F	4	35 BRO	SP	CRE		V	2/6/2063
2020 PO4684487944	LGE	3	45 BRO	SP	A	ED,ID	BD	2/7/2063
2020 PO4857612203	F	4	40 ACE	SP	CRE		V	2/8/2063
2020 PO4800788967	LGE	4	40 BRN	SP	CRE	ED,ID	BD	2/9/2063
2020 PO4826213139	F	4	40 ACE	SP	CRE		V	2/10/2063
2020 PO4810813203	F	4	40 ACE	SP	CRE		V	2/11/2063
2020 PO4813713271	F	4	40 ACE	SP	CRE		V	2/12/2063
2020 PO4795013264	F	4	40 ACE	SP	CRE		V	2/13/2063
2020 PO4778813322	F	4	40 ACE	SP	CRE		V	2/14/2063
2020 PO4762313381	F	4	40 ACE	SP	CRE		V	2/15/2063
2020 PO4750413435	F	4	40 ACE	SP	CRE		V	2/16/2063
2020 PO4737913495	F	4	40 ACE	SP	CRE		V	2/17/2063
2020 PO4801612734	F	4	40 ACE	SP	CRE		V	2/18/2063
2020 PO4711387928	LGE	1	70 BRO	SP	CRE		V	2/19/2063
2020 PO4497202587	KU	4	40 BRO	SP	CRE	ED,ID	TD	2/20/2063

2020 PO9017689663	KU	4	35 ACW	SP	CCA		V			2/21/2063
2020 PO9018289919	KU	4	40 ACW	SP	CRE	ED,ID	TD			2/22/2063
2020 PO9049490240	KU	4	40 ACW	SP	CRE	ED,ID	TD			2/23/2063
2020 PO9077090542	KU	4	40 ACW	SP	CRE	ED,ID	TD			2/24/2063
2020 PO9112790808	KU	4	40 ACW	SP	CRE	ED,ID	TD			2/25/2063
2020 PO9190191288	KU	6	30 ACW	SP	CRE	ED,ID	TD			2/26/2063
2020 PO9158791652	KU	4	40 ACW	SP	CRE	ED,ID	TD			2/27/2063
2020 PO9292290988	KU	4	40 ACW	SP	CRE	ED,ID	TD			2/28/2063
2020 PO9290291078	KU	4	40 ACW	SP	CRE	ID	BD			3/1/2063
2020 PO9250091362	KU	4	40 ACW	SP	CRE	ED,ID,RB	TX	RR		3/2/2063
2020 PO9250891983	KU	5	35 ACW	SP	CRE	ED,ID	TD			3/3/2063
2020 PO9250391655	KU	5	35 ACW	SP	CRE	ED,ID	TD			3/4/2063
2020 PO0013194035	KU	4	50 ACW	SP	CRE	ED,ID	TD			3/5/2063
2020 PO0003894064	KU	5	30 ACW	SP	CRE	ED,ID,IP,SR	TD			3/6/2063
2020 PO5148646965	KU	4	45 ACE	SP	CRE	ED,ID	BD			3/7/2063
2020 PO5119147040	KU	4	45 ACE	SP	CRE	ED,ID	TD			3/8/2063
2020 PO9243192495	KU	5	35 ACW	SP	CRE	ED,ID	TD			3/9/2063
2020 PO5248746718	KU	3	50 ACE	SP	CRE	ED,ID	BD			3/10/2063
2020 PO9243892252	KU	5	30 ACW	SP	CRE	ED,ID	TD			3/11/2063
2020 PO5144746974	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD			3/12/2063
2020 PO9218192237	KU	4	40 ACW	SP	CRE	ED,ID	TX	RR		3/13/2063
2020 PO0142694119	KU	4	40 ACW	SP	CRE	ED,ID	TD			3/14/2063
2020 PO0166094182	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD			3/15/2063
2020 PO9948293528	KU	4	45 ACW	SP	CRE	ID	BD			3/16/2063
2020 PO9196192230	F	4	40 ACW	SP	CRE		V			3/17/2063
2020 PO5174246905	KU	4	45 ACE	SP	CCA		V			3/18/2063
2020 PO5109446565	KU	4	45 ACE	SP	CRE	ED,ID	TD			3/19/2063
2020 PO0215094488	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD			3/20/2063
2020 PO0227494660	KU	4	40 ACW	SP	CRE		V			3/21/2063
2020 PO0230794791	KU	6	30 ACW	SP	CCA		V			3/22/2063
2020 PO0263594944	KU	4	40 ACW	SP	S		V			3/23/2063
2020 PO0278194963	KU	4	40 ACW	SP	S		V			3/24/2063
2020 PO5134647003	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD			3/25/2063
2020 PO5126846788	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD			3/26/2063
2020 PO5280046640	KU	3	50 ACE	SP	CCA		V			3/27/2063
2020 PO4495002824	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			3/28/2063
2020 PO9951293458	KU	4	40 ACW	SP	CRE	ID	TD			3/29/2063
2020 PO4517702934	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			3/30/2063
2020 PO4499903076	KU	6	30 BRO	SP	CRE	ED,ID	TD			3/31/2063
2020 PO5080446987	KU	3	50 ACE	SP	CRE	ED,ID	BD			4/1/2063
2020 PO5104346886	KU	3	55 ACE	SP	CRE	ED,ID	TD			4/2/2063
2020 PO9941393282	KU	4	40 ACW	SP	CRE	ID	BD			4/3/2063
2020 PO9940593193	C	4	40 ACW	SP	CRE		V			4/4/2063
2020 PO0239395076	KU	4	40 ACW	SP	S		V			4/5/2063
2020 PO0249795078	KU	4	40 ACW	SP	S		V			4/6/2063
2020 PO0220295030	KU	4	40 ACW	SP	S		V			4/7/2063
2020 PO9942593147	KU	4	40 ACW	SP	A	ED,ID	TD			4/8/2063

2020 PO5049747124	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	4/9/2063
2020 PO4539103045	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/10/2063
2020 PO9942492913	C	4	40 ACW	SP	CRE		V	4/11/2063
2020 PO9941392997	KU	4	40 ACW	SP	CRE	ED,ID	TD	4/12/2063
2020 PO9607990665	KU	7	25 ACW	AL	CCA		V	4/13/2063
2020 PO9592990734	KU	3	45 ACW	SP	S		V	4/14/2063
2020 PO9607791016	KU	4	40 ACW	SP	CRE	ED,ID	BD	4/15/2063
2020 PO9581891061	KU	3	45 ACW	SP	S		V	4/16/2063
2020 PO9577191393	KU	3	45 ACW	SP	S		V	4/17/2063
2020 PO9582991365	KU	4	40 ACW	SP	CRE		V	4/18/2063
2020 PO9591591277	KU	4	40 ACW	SP	CRE		V	4/19/2063
2020 PO9588091358	C	4	40 ACW	SP	S		V	4/20/2063
2020 PO9638292095	KU	3	45 ACW	SP	S		V	4/21/2063
2020 PO9629592197	KU	5	35 ACW	SP	S		V	4/22/2063
2020 PO5034847180	KU	4	45 ACE	SP	CRE	ED,ID	TD	4/23/2063
2020 PO5022147224	KU	4	40 ACE	SP	CRE	ED,ID	TD	4/24/2063
2020 PO5341047721	KU	6	30 ACE	SP	CRE	ED,ID	TD	4/25/2063
2020 PO4556503135	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	4/26/2063
2020 PO4577403243	KU	4	40 BRO	SP	CRE	ED,ID	TD	4/27/2063
2020 PO4603103412	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	4/28/2063
2020 PO4617103514	KU	5	35 BRO	SP	CRE	ID,IP	BD	4/29/2063
2020 PO4627103590	KU	4	40 BRO	SP	CRE	ID,IP	BD	4/30/2063
2020 PO5062347064	KU	3	55 ACE	SP	CRE	ED,ID,IP	BD	5/1/2063
2020 PO4997247301	F	4	40 ACE	SP	CCA		V	5/2/2063
2020 PO4978247368	F	4	40 ACE	SP	CCA		V	5/3/2063
2020 PO4973247392	KU	3	45 ACE	SP	CCA		V	5/4/2063
2020 PO4974347341	KU	3	45 ACE	SP	CCA		V	5/5/2063
2020 PO4972447249	KU	4	40 ACE	SP	CCA		V	5/6/2063
2020 PO4651503762	KU	3	45 BRO	SP	CCA		V	5/7/2063
2020 PO4663103509	KU	4	40 BRO	SP	CCA	ID	BD	5/8/2063
2020 PO5328647739	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	5/9/2063
2020 PO4455504116	KU	4	40 BRO	SP	CRE	ED,ID	TD	5/10/2063
2020 PO5259747001a	KU	6	30 ACE	SP	CRE	ED,ID	BD	5/11/2063
2020 PO5289546753	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD	5/12/2063
2020 PO5278346869	KU	6	30 ACE	SP	CRE	ED,ID	BD	5/13/2063
2020 PO9593991779	KU	4	40 ACW	SP	CRE	ED,ID	TD	5/14/2063
2020 PO9608891808	KU	5	35 ACW	SP	CRE		V	5/15/2063
2020 PO9593991779A	KU	6	30 ACW	SP	S		V	5/16/2063
2020 PO9620591918	KU	3	45 ACW	SP	S		V	5/17/2063
2020 PO9558191665A	KU	3	45 ACW	SP	S		V	5/18/2063
2020 PO9568991853	KU	6	30 ACW	SP	S		V	5/19/2063
2020 PO9558191665	KU	3	40 ACW	SP	S		V	5/20/2063
2020 PO9541591938	KU	3	45 ACW	SP	S		V	5/21/2063
2020 PO9521492263	KU	3	45 ACW	SP	S		V	5/22/2063
2020 PO0397195538	KU	5	35 ACW	SP	S		V	5/23/2063
2020 PO0404495165	KU	4	40 ACW	SP	CRE	ED,ID	TD	5/24/2063
2020 PO0420195400	KU	5	45 ACW	SP	CRE	ED,ID	TD	5/25/2063

2020 PO0447595472	KU	4	40 ACW	SP	CRE		V	5/26/2063
2020 PO9887293121	KU	4	40 ACW	SP	CRE	ED,ID	TD	5/27/2063
2020 PO4449004273	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	5/28/2063
2020 PO5269746930	KU	6	30 ACE	SP	CRE	ED,ID	BD	5/29/2063
2020 PO5259747001	KU	6	30 ACE	SP	CRE	ED,ID	BD	5/30/2063
2020 PO4438304006	F	4	35 BRO	SP	CCA		V	5/31/2063
2020 PO4442704064	F	5	35 BRO	SP	CRE		V	6/1/2063
2020 PO5241247134	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD	6/2/2063
2020 PO5223647182	KU	2	50 ACE	SP	CRE	ED,ID	T	6/3/2063
2020 PO5238147193	KU	4	45 ACE	SP	CCA		V	6/4/2063
2020 PO5236047163	F	4	40 ACE	SP	CCA		V	6/5/2063
2020 PO4477604131	KU	5	35 BRO	SP	CRE	ED,ID	TD	6/6/2063
2020 PO4465204235	KU	4	40 BRO	SP	CRE	ED,ID	TD	6/7/2063
2020 PO9880892404	KU	4	40 ACW	SP	CRE	ID	BD	6/8/2063
2020 PO9877593519	KU	4	40 ACW	SP	S		V	6/9/2063
2020 PO4467804443	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	6/10/2063
2020 PO4455404568	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/11/2063
2020 PO5205347267	KU	5	35 ACE	SP	CCA	ED	T	6/12/2063
2020 PO5222146967	F	3	45 ACE	SP	CCA		V	6/13/2063
2020 PO5214947086	KU	4	40 ACE	SP	CCA		V	6/14/2063
2020 PO5212547301	KU	2	50 ACE	SP	CRE	ED,ID	TD	6/15/2063
2020 PO5204547538	KU	4	40 ACE	SP	CRE	ED,ID	BD	6/16/2063
2020 PO5185747949	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	6/17/2063
2020 PO9861092491	F	3	40 ACW	SP	S		V	6/18/2063
2020 PO9880292101	F	5	35 ACW	SP	CRE		V	6/19/2063
2020 PO9868792356	F	4	40 ACW	SP	P		V	6/20/2063
2020 PO4453304317	KU	5	35 BRO	SP	CCA		V	6/21/2063
2020 PO4460104278	F	4	40 BRO	SP	CRE		V	6/22/2063
2020 PO4444004470	KU	5	35 BRO	SP	CCA		V	6/23/2063
2020 PO4500604619	KU	4	40 BRO	SP	CCA		V	6/24/2063
2020 PO4467804443-A	KU	3	45 BRO	SP	CCA		V	6/25/2063
2020 PO5187147682	KU	3	45 ACE	SP	CCA		V	6/26/2063
2020 PO5173748122	KU	4	40 ACE	SP	CRE	ED,ID	BD	6/27/2063
2020 PO5167247898	KU	6	30 ACE	SP	CCA		V	6/28/2063
2020 PO4474204320	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/29/2063
2020 PO4493004551	KU	3	45 BRO	SP	CRE		V	6/30/2063
2020 PO4508804327	KU	3	45 BRO	SP	CCA		V	7/1/2063
2020 PO8617436592	F	4	40 BRO	SP	CRE		V	7/2/2063
2020 PO8632337959	F	6	30 BRO	SP	S		V	7/3/2063
2020 PO8593738755	F	4	40 BRO	SP	P		V	7/4/2063
2020 PO8584439326	ODP	6	30 BRO	SP	S		V	7/5/2063
2020 PO8579539425	ODP	5	35 BRO	SP	S		V	7/6/2063
2020 PO8577539209A	ODP	5	30 BRO	SP	CRE	ED,ID	TD	7/7/2063
2020 PO8730035871	F	4	40 XXX	SP	CRE		V	7/8/2063
2020 PO8730235935	F	4	40 XXX	SP	CRE		V	7/9/2063
2020 PO8653135895	ODP	4	40 XXX	SP	CRE	ID	TD	7/10/2063
2020 PO8668335715	ODP	6	30 XXX	SP	CRE	ID	TD	7/11/2063

2020 PO8714236002	ODP	5	35 XXX	SP	CRE	ID	BD			7/12/2063
2020 PO8721335661	ODP	6	30 XXX	SP	CRE	ID	BD			7/13/2063
2020 PO8702535707	ODP	6	30 XXX	SP	CRE	HH,ID	TX	RR		7/14/2063
2020 PO8745735745	ODP	5	35 XXX	SP	CCA		V			7/15/2063
2020 PO8720835900	ODP	5	35 XXX	SP	CCA		V			7/16/2063
2020 PO8730735735	ODP	6	30 XXX	SP	CCA		V			7/17/2063
2020 PO8726035789	F	4	40 XXX	SP	CRE		V			7/18/2063
2020 PO8748935841	ODP	4	40 XXX	SP	CRE	ID	TD			7/19/2063
2020 PO8754935460	ODP	6	30 XXX	SP	CRE	ID	TD			7/20/2063
2020 PO8773135551	ODP	4	40 XXX	SP	CCA		V			7/21/2063
2020 PO8765235117	ODP	6	30 XXX	SP	CCA		V			7/22/2063
2020 PO8787635230	ODP	5	35 XXX	SP	CRE	ID	TD			7/23/2063
2020 PO9039230618	ODP	5	35 XXX	SP	CRE		V			7/24/2063
2020 PO8720533298	ODP	5	35 XXX	SP	CRE		V			7/25/2063
2020 PO4619988207	LGE	4	40 BRO	SP	CRE		V			7/26/2063
2020 PO4620388207	LGE	4	40 BRO	SP	P	ED,ID	TD			7/27/2063
2020 PO4621288206	LGE	4	35 BRO	SP	CRE	ED,ID	BD			7/28/2063
2020 PO4623988204	LGE	4	40 BRO	SP	CRE	ED,ID	TX	RR		7/29/2063
2020 PO4623688204	LGE	4	35 BRO	SP	CRE	ED,ID	TD			7/30/2063
2020 PO4624788203	LGE	4	35 BRO	SP	CRE		V			7/31/2063
2020 PO4622488205	LGE	4	40 BRO	SP	CRE	ED,ID	TD			8/1/2063
2020 PO4620488219	LGE	4	40 BRO	SP	CRE	ED,ID	BD			8/2/2063
2020 PO4620588231	LGE	4	40 BRO	SP	CRE	ED,HH,ID,RB	BX	PX		8/3/2063
2020 PO4624188233	LGE	3	45 BRO	SP	P	ED,ID	T			8/4/2063
2020 PO4624288247	LGE	4	40 BRO	SP	A	ED,ID	TD			8/5/2063
2020 PO4624388257	LGE	4	40 BRO	SP	A	ED,ID	TD			8/6/2063
2020 PO4624488270	LGE	4	40 BRO	SP	CRE	ED,ID	TD			8/7/2063
2020 PO4620688243	LGE	4	40 BRO	SP	CRE	ED,ID	TD			8/8/2063
2020 PO4620788254	LGE	4	40 BRO	SP	CRE	ED,ID	TD			8/9/2063
2020 PO4624588280	LGE	4	40 BRO	SP	CRE	ED,ID	BD			8/10/2063
2020 PO462088267	LGE	4	40 BRO	SP	CRE	ED,ID	BD			8/11/2063
2020 PO8627637937	F	4	40 BRO	SP	P		V			8/12/2063
2020 PO5447691117	KU	4	40 BRN	SP	CRE	ID	TD			8/13/2063
2020 PO5448790931	KU	4	40 BRN	SP	CRE	ID	TD			8/14/2063
2020 PO5447890705	KU	4	40 BRN	SP	CRE	ID	BD			8/15/2063
2020 PO5531695489	KU	3	45 BRN	SP	CCA		V			8/16/2063
2020 PO5545395354	KU	3	45 BRN	SP	CCA		V			8/17/2063
2020 PO1792197383	KU	4	40 UNK	SP	CRE	ID	TD			8/18/2063
2020 PO1863996160	KU	4	40 UNK	SP	CRE	ID	TD			8/19/2063
2020 PO1882895905	KU	4	40 UNK	SP	CRE	ID	BD			8/20/2063
2020 PO1827196730	KU	4	40 UNK	SP	CCA	SRS	TD			8/21/2063
2020 PO5444292237	F	4	40 BRN	SP	CRE		V			8/22/2063
2020 PO5449190508	KU	3	50 BRN	SP	CCA		V			8/23/2063
2020 PO5438090521	KU	3	45 BRN	SP	A		V			8/24/2063
2020 PO5412590679	KU	3	45 BRN	SP	CCA		V			8/25/2063
2020 PO5448789732	KU	4	40 BRN	SP	CRE	ID	TD			8/26/2063
2020 PO1837296328	KU	6	30 UNK	SP	CRE	ID,SRS	TD			8/27/2063

2020 PO1841196479	KU	3	45 UNK	SP	CCA		V	8/28/2063
2020 PO1853296138	KU	6	30 UNK	SP	CCA		V	8/29/2063
2020 PO1886495699	KU	6	30 UNK	SP	CRE	ID	TD	8/30/2063
2020 PO1936798833	KU	4	45 UNK	SP	CRE	ID	BD	8/31/2063
2020 PO5372397338-B	KU	3 35E	BRN	SP	CRE	ID,IP	BD	9/1/2063
2020 PO5372397338-A	KU	4	45 BRN	SP	CRE	ID,IP	TD	9/2/2063
2020 PO5362597156	KU	4	45 BRN	SP	CRE	ID	BD	9/3/2063
2020 PO9292232571a	ODP	4	45 BRN	SP	CCA		V	9/4/2063
2020 PO9326532769	ODP	4	40 BRN	SP	CRE	ED,ID	TD	9/5/2063
2020 PO9311432549	ODP	4	45 BRN	SP	CRE	ED,ID	TD	9/6/2063
2020 PO1377925647	ODP	4	45 XXX	SP	CCA	ED,SRS	TD	9/7/2063
2020 PO1389925135	ODP	4	45 XXX	SP	CCA		V	9/8/2063
2020 PO1404324984	F	4	40 XXX	SP	CRE		V	9/9/2063
2020 PO1394124954	ODP	2	45 XXX	SP	CRE	ID	TD	9/10/2063
2020 PO9292232571	ODP	4	40 BRN	SP	CCA		V	9/11/2063
2020 PO9302332786	ODP	3	45 BRN	SP	CCA		V	9/12/2063
2020 PO9308232893	ODP	4	45 BRN	SP	CCA		V	9/13/2063
2020 PO9314632993	ODP	4	45 XXX	SP	CRE	ED,ID	TD	9/14/2063
2020 PO9302032974	ODP	5	35 XXX	SP	CRE		V	9/15/2063
2020 PO9305232966	ODP	5	35 XXX	SP	CCA		V	9/16/2063
2020 PO1387024643	ODP	4	45 XXX	SP	CRE	ID	TD	9/17/2063
2020 PO1571619740	ODP	4	40 XXX	SP	CRE	ID	TD	9/18/2063
2020 PO1645320308	ODP	4	40 XXX	SP	CRE	ID	TD	9/19/2063
2020 PO9620840156	F	4	40 XXX	SP	CRE		V	9/20/2063
2020 PO9654841099	ODP	4	40 XXX	SP	CRE		V	9/21/2063
2020 PO9651941187	ODP	6	30 XXX	SP	CCA		V	9/22/2063
2020 PO9626441168	ODP	4	40 XXX	SP	CRE		V	9/23/2063
2020 PO9610941311	ODP	4	40 XXX	SP	CCA		V	9/24/2063
2020 PO4046582957	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	9/25/2063
2020 PO4044182939	LGE	4	40 BRO	SP	CRE	ED,ID	TD	9/26/2063
2020 PO4045282950	LGE	4	35 BRO	SP	CRE	ED,ID	TD	9/27/2063
2020 PO4043982943	LGE	4	35 BRO	SP	CRE	ED,ID	TD	9/28/2063
2020 PO4045482946	LGE	4	40 BRO	SP	CRE	ED,ID	TD	9/29/2063
2020 PO4046782953	LGE	4	40 BRO	SP	CRE	ED,ID	TD	9/30/2063
2020 PO6831143027	F	3	45 BRO	SP	CCA		V	10/1/2063
2020 PO3965883152	F	4	30 BRO	SP	CCA		V	10/2/2063
2020 PO3966283158	LGE	4	35 BRO	SP	CCA		V	10/3/2063
2020 PO3967083169	F	4	40 BRO	SP	CCA		V	10/4/2063
2020 PO3965883235	F	4	30 BRO	SP	CCA		V	10/5/2063
2020 PO3966683177	F	3	45 BRO	SP	CCA		V	10/6/2063
2020 PO3965583178	F	4	40 BRO	SP	CCA		V	10/7/2063
2020 PO3963883178	F	4	35 BRO	SP	CCA		V	10/8/2063
2020 PO3962783191	LGE	4	30 BRO	SP	CCA		V	10/9/2063
2020 PO3962483171	LGE	4	40 BRO	SP	CCA		V	10/10/2063
2020 PO3962683179	F	4	40 BRO	SP	CCA		V	10/11/2063
2020 PO3960383180	F	4	40 BRO	SP	CCA		V	10/12/2063
2020 PO3961383176	F	3	35 BRO	SP	CCA		V	10/13/2063

2020 PO3961483180	F	4	35 BRO	SP	CCA		V	10/14/2063
2020 PO3961383189	LGE	4	30 BRO	SP	CCA		V	10/15/2063
2020 PO3959183177	F	4	30 BRO	SP	CCA		V	10/16/2063
2020 PO3959183180	F	4	35 BRO	SP	P		V	10/17/2063
2020 PO3958083181	F	4	40 BRO	SP	CRE		V	10/18/2063
2020 PO3955583174	F	4	30 BRO	SP	CRE		V	10/19/2063
2020 PO3955683182	F	4	40 BRO	SP	CCA		V	10/20/2063
2020 PO3954983181	F	4	35 BRO	SP	CCA		V	10/21/2063
2020 PO3954883172	LGE	4	30 BRO	SP	CCA		V	10/22/2063
2020 PO3953283183	F	4	35 BRO	SP	CCA		V	10/23/2063
2020 PO3951683184	F	4	40 BRO	SP	CCA		V	10/24/2063
2020 PO3951583174	LGE	4	30 BRO	SP	CCA		V	10/25/2063
2020 PO3967583176	F	3	40 BRO	SP	CCA		V	10/26/2063
2020 PO3968083183	F	4	40 BRO	SP	CCA		V	10/27/2063
2020 PO3963383239	F	4	40 BRO	SP	CCA		V	10/28/2063
2020 PO3973183256	F	4	35 BRO	SP	CCA		V	10/29/2063
2020 PO3972383244	F	4	40 BRO	SP	CCA		V	10/30/2063
2020 PO3970383232	LGE	4	40 BRO	SP	A	ED,ID	TD	10/31/2063
2020 PO3970883224	F	4	35 BRO	SP	CCA		V	11/1/2063
2020 PO9464834104	ODP	2	45 XXX	SP	CCA		V	11/2/2063
2020 PO9483234258	ODP	4	45 XXX	SP	A	ED,ID	TD	11/3/2063
2020 PO3968383237	F	3	45 BRO	SP	CCA		V	11/4/2063
2020 PO3968383263	F	4	40 BRO	SP	CCA		V	11/5/2063
2020 PO3968383250	F	4	40 BRO	SP	CCA		V	11/6/2063
2020 PO3968483279	F	4	40 BRO	SP	CCA		V	11/7/2063
2020 PO6868343850	LGE	4	35 BRO	SP	P	ED,ID	TD	11/8/2063
2020 PO3969383202	F	4	40 BRO	SP	CCA		V	11/9/2063
2020 PO6861043742	LGE	4	30 BRO	SP	CCA		V	11/10/2063
2020 PO3969983210	F	4	40 BRO	SP	A		V	11/11/2063
2020 PO3971183236	F	4	40 BRO	SP	CRE		V	11/12/2063
2020 PO9505534526	ODP	3	45 XXX	SP	A	ED,ID	TD	11/13/2063
2020 PO9511334501	ODP	6	30 XXX	SP	CRE	ED,ID	TD	11/14/2063
2020 PO9516934596	ODP	4	40 XXX	SP	CRE	ED,ID	TD	11/15/2063
2020 PO9512634627	ODP	5	35 XXX	SP	CRE	ED,ID	TD	11/16/2063
2020 PO9516534688	ODP	2	40 XXX	SP	CRE	ED,ID	TD	11/17/2063
2020 PO3966483238	F	4	40 BRO	SP	CRE		V	11/18/2063
2020 PO3960683225	LGE	4	35 BRO	SP	A	ED,ID	BD	11/19/2063
2020 PO3961483240	F	4	40 BRO	SP	CCA		V	11/20/2063
2020 PO3961783234	F	4	40 BRO	SP	CCA		V	11/21/2063
2020 PO3963283234	F	4	30 BRO	SP	A		V	11/22/2063
2020 PO3964683238	F	4	40 BRO	SP	CCA		V	11/23/2063
2020 PO3968283232	F	5	25 BRO	SP	A		V	11/24/2063
2020 PO3967683233	LGE	4	30 BRO	SP	CCA		V	11/25/2063
2020 PO3971183230	LGE	4	35 BRO	SP	CRE	ED,ID,IP	BD	11/26/2063
2020 PO3970083236	F	4	40 BRO	SP	CCA		V	11/27/2063
2020 PO3971783235	F	4	40 BRO	SP	CCA		V	11/28/2063
2020 PO3961683210	LGE	4	40 BRO	SP	CRE	ED,ID	TD	11/29/2063

2020 PO3948883079	LGE	4	30 BRO	SP	A	ED,ID	TD	11/30/2063
2020 PO3962883091	LGE	3	50 BRO	SP	CCA		V	12/1/2063
2020 PO3963383081	LGE	4	40 BRO	SP	CCA		V	12/2/2063
2020 PO3961883077	LGE	3	45 BRO	SP	CCA		V	12/3/2063
2020 PO3960183053	F	3	40 BRO	SP	CCA		V	12/4/2063
2020 PO3959383040	LGE	3	45 BRO	SP	A	ED,ID	BD	12/5/2063
2020 PO6676640437	F	3	50 BRO	SP	CCA		V	12/6/2063
2020 PO6691240347	LGE	3	45 BRO	SP	CCA		V	12/7/2063
2020 PO6693540328	LGE	3	45 BRO	SP	CCA		V	12/8/2063
2020 PO3947782828	LGE	3	45 BRO	SP	A	ED,ID	BD	12/9/2063
2020 PO3947382850	F	4	40 BRO	SP	CCA		V	12/10/2063
2020 PO3946882841	F	4	40 BRO	SP	CCA	ED	VX	12/11/2063
2020 PO3946582834	F	4	40 BRO	SP	CCA		V	12/12/2063
2020 PO3946182834	F	4	40 BRO	SP	CCA		V	12/13/2063
2020 PO3945382811	F	4	30 BRO	SP	CCA		V	12/14/2063
2020 PO3944782799	F	4	35 BRO	SP	CCA		V	12/15/2063
2020 PO3944482794	F	3	45 BRO	SP	CCA		V	12/16/2063
2020 PO3944282789	F	3	45 BRO	SP	CCA		V	12/17/2063
2020 PO3942782757	F	3	45 BRO	SP	CCA		V	12/18/2063
2020 PO3961283069	F	3	50 BRO	SP	CCA		V	12/19/2063
2020 PO9482744905	ODP	4	40 XXX	SP	CCA		V	12/20/2063
2020 PO9495844849	ODP	6	30 XXX	SP	CRE	ED,ID	TD	12/21/2063
2020 PO9455444913	ODP	4	40 XXX	SP	A	ED,ID	TD	12/22/2063
2020 PO9637638836	ODP	3	45 XXX	SP	CCA		V	12/23/2063
2020 PO9644138661	ODP	3	45 XXX	SP	CCA		V	12/24/2063
2020 PO9646638553	ODP	4	40 XXX	SP	CCA		V	12/25/2063
2020 PO9653238293	ODP	3	45 XXX	SP	CCA		V	12/26/2063
2020 PO9700837752	ODP	4	40 XXX	SP	CRE	ED,ID	TD	12/27/2063
2020 PO9680137507	ODP	5	35 XXX	SP	CRE	ED,ID	TD	12/28/2063
2020 PO9674737671	ODP	4	40 XXX	SP	CCA		V	12/29/2063
2020 PO9659038127	ODP	3	45 XXX	SP	CCA		V	12/30/2063
2020 PO9717837556	ODP	5	35 XXX	SP	CRE	ED,ID	TD	12/31/2063
2020 PO9741637034	ODP	4	40 XXX	SP	CRE	ED,ID	TD	1/1/2064
2020 PO9719837816	ODP	5	35 XXX	SP	CRE	ED,ID	TD	1/2/2064
2020 PO9738537684	F	2	50 XXX	SP	A		V	1/3/2064
2020 PO9854038299	ODP	4	50 XXX	SP	CRE	ED,ID,RB	X	1/4/2064
2020 PO5350946363	KU	6	30 ACE	SP	CRE		V	1/5/2064
2020 PO5338846330	KU	4	45 ACE	SP	CRE	ED,ID	TD	1/6/2064
2020 PO5352446268	KU	6	30 ACE	SP	CCA		V	1/7/2064
2020 PO5362246361	KU	4	40 ACE	SP	CRE	ED,ID	TD	1/8/2064
2020 PO5375646493	KU	4	40 ACE	SP	CRE	ED,ID	TD	1/9/2064
2020 PO5362746595	KU	6	30 ACE	SP	CRE	ED,ID	TD	1/10/2064
2020 PO5358646561	KU	6	30 ACE	SP	CRE	ED,ID	TD	1/11/2064
2020 PO5353446514	KU	6	30 ACE	SP	CRE	ED,ID	TD	1/12/2064
2020 PO5349446477	KU	6	30 ACE	SP	CRE	ED,ID	TD	1/13/2064
2020 PO5346146492	KU	4	40 ACE	SP	CRE	ED,ID	TD	1/14/2064
2020 PO5363046641	KU	4	40 ACE	SP	CRE	ED,ID	TD	1/15/2064

2020 PO4069304487	KU	3	45 BRO	SP	CCA		V		1/16/2064
2020 PO3260839724	KU	4	35 ACE	SP	CRE	ED,HH,ID,IP,RB	BX	RP1	1/17/2064
2020 PO1382630226	ODP	5	35 BRN	SP	A	ID	TD		1/18/2064
2020 PO1351829957	F	4	40 BRN	SP	A		V		1/19/2064
2020 PO1367530091	F	4	40 BRN	SP	CRE		V		1/20/2064
2020 PO1335729751	ODP	4	50 BRN	SP	CRE	ID	BD		1/21/2064
2020 PO1338529842	ODP	4	45 BRN	SP	CRE	ID	BD		1/22/2064
2020 PO4692588239	F	4	40 BRN	SP	A		V		1/23/2064
2020 PO3952913992	KU	3	45 BRO	SP	CRE	ID,IP	BD		1/24/2064
2020 PO3930714107	KU	2	60 BRO	SP	CRE	ID,IP	BD		1/25/2064
2020 PO3907614227	KU	1	70 BRO	SP	CRE	ID,IP	BD		1/26/2064
2020 PO4693388236	LGE	3	45 BRN	SP	CRE	ED,ID	BD		1/27/2064
2020 PO4693788250	LGE	3	45 BRN	SP	CRE	ED,ID	TD		1/28/2064
2020 PO3982113839	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD		1/29/2064
2020 PO4693888247	F	3	45 BRN	SP	A		V		1/30/2064
2020 PO3995713769	KU	2	60 BRO	SP	P	ED	T		1/31/2064
2020 PO4694688244	LGE	3H	45 BRN	SP	A	ED,ID	BD		2/1/2064
2020 PO2751947616	ODP	5	35 KOP	DF	CRE	ED,ID	TD		2/2/2064
2020 PO2747847534	F	4	40 KOP	SP	CCA		V		2/3/2064
2020 PO2740847530	ODP	6	30 KOP	SP	CRE	ED,ID	TD		2/4/2064
2020 PO2834748548	ODP	5	35 KOP	SP	S		V		2/5/2064
2020 PO1159131467	ODP	4	40 BRN	SP	CRE	ID	TD		2/6/2064
2020 PO1172031332	ODP	4	50 BRN	SP	CRE	ED,ID,RB	TX	RR	2/7/2064
2020 PO1133231788	ODP	4	40 BRN	SP	CRE	ID	BD		2/8/2064
2020 PO1147931729	ODP	4	40 BRN	SP	CRE	ID	TD		2/9/2064
2020 PO1163931798	ODP	5	35 BRN	SP	CRE	ID	BD		2/10/2064
2020 PO1166231743	ODP	4	40 BRN	SP	CRE	ID	TD		2/11/2064
2020 PO1385630712	ODP	5	35 BRN	SP	CCA		V		2/12/2064
2020 PO1393430647	ODP	4	40 BRN	SP	CRE		V		2/13/2064
2020 PO4058882588	LGE	3	50 BRO	SP	CCA		V		2/14/2064
2020 PO4061382555	LGE	3	45 BRO	SP	A	ED,ID	BD		2/15/2064
2020 PO4060582566	LGE	4	40 BRO	SP	A	ED,HH,ID	TX	RR	2/16/2064
2020 PO4059582579	LGE	4	40 BRO	SP	A	ED,ID	BD		2/17/2064
2020 PO4695088261	LGE	4	40 BRN	SP	CRE	ED,ID	TX	RR	2/18/2064
2020 PO4695388259	F	4	40 BRN	SP	CRE		V		2/19/2064
2020 PO4695788253	LGE	4	40 BRN	SP	CRE	ED,ID	BD		2/20/2064
2020 PO4696588258	LGE	4	40 BRN	SP	CRE	ED,ID	BD		2/21/2064
2020 PO4696288282	LGE	4	30 BRN	SP	CRE	ED,ID	BD		2/22/2064
2020 PO4696388265	F	4	40 BRN	SP	CRE		V		2/23/2064
2020 PO4697488265	LGE	4	40 BRN	SP	CRE	ED,ID	BD		2/24/2064
2020 PO4697788275	LGE	4	35 BRN	SP	A	ED,ID	TD		2/25/2064
2020 PO4697588277	F	4	35 BRN	SP	CRE		V		2/26/2064
2020 PO4697088270	F	4	35 BRN	SP	S		V		2/27/2064
2020 PO2819647618	ODP	5	35 KOP	DF	CRE	ED,ID,SRC	TD		2/28/2064
2020 PO2801447826	ODP	4	40 KOP	SP	CRE	ED,ID	TD		2/29/2064
2020 PO2771348107	ODP	5	35 KOP	SP	S		V		3/1/2064
2020 PO2805048340	ODP	5	35 KOP	DF	CRE	ED,ID	TD		3/2/2064

2020 PO2838648731	ODP	5	35 KOP	SP	S		V	3/3/2064
2020 PO2820548690	ODP	5	35 KOP	SP	CRE	ED,ID,SRC	TD	3/4/2064
2020 PO2829648633	ODP	6	30 KOP	SP	CRE	ED,ID,SRC	TD	3/5/2064
2020 PO4698988275	LGE	UNK	45 BRN	SP	CRE	ED,ID	BD	3/6/2064
2020 PO4061582589	LGE	4	40 BRO	SP	P	ED,ID	TD	3/7/2064
2020 PO4062382595	LGE	3	45 BRO	SP	CCA		V	3/8/2064
2020 PO4015082492	F	4	30 BRO	SP	CCA		V	3/9/2064
2020 PO4698688280	F	4	35 BRN	SP	A		V	3/10/2064
2020 PO4699488286	LGE	4	40 BRN	SP	A	ED,ID	TD	3/11/2064
2020 PO4699588285	LGE	3	45 BRN	SP	A	ED,ID	BD	3/12/2064
2020 PO4700188284	LGE	3	45 BRN	SP	CRE	ED,ID	BD	3/13/2064
2020 PO4701488283	LGE	6	30 BRN	SP	CRE	ED,ID	BD	3/14/2064
2020 PO4700388298	LGE	4	35 BRN	SP	CRE	ED,ID	TD	3/15/2064
2020 PO4700488296	LGE	4	35 BRN	SP	CRE	ED,ID	BD	3/16/2064
2020 PO3861812376	KU	4	45 BRO	SP	CCA		V	3/17/2064
2020 PO3873912829	KU	4	45 BRO	SP	CCA		V	3/18/2064
2020 PO3874312670	KU	4	45 BRO	SP	CCA		V	3/19/2064
2020 PO4700988289	LGE	3	45 BRN	SP	S		V	3/20/2064
2020 PO3859512843	KU	2	40 BRO	SP	CRE	ID,IP	BD	3/21/2064
2020 PO3875112501	KU	4	45 BRO	SP	CCA		V	3/22/2064
2020 PO3875912351	KU	4	45 BRO	SP	CCA		V	3/23/2064
2020 PO4701888296	LGE	3	45 BRN	SP	CRE	ED,ID	BD	3/24/2064
2020 PO4702688303	LGE	3	45 BRN	SP	CRE	ED,ID	BD	3/25/2064
2020 PO4703788311	LGE	3	45 BRN	SP	CRE	ED,ID	BD	3/26/2064
2020 PO4703088318	LGE	3	45 BRN	SP	A	ED,ID	BD	3/27/2064
2020 PO4703288319	LGE	3	45 BRN	SP	A	ED,ID	BD	3/28/2064
2020 PO4703788318	LGE	4	25 BRN	SP	A	ED,ID	TD	3/29/2064
2020 PO4703988319	LGE	4	40 BRN	SP	A	ED,ID	BD	3/30/2064
2020 PO4706788340	LGE	4	35 BRN	SP	A	ED,ID	TD	3/31/2064
2020 PO3883211914	KU	4	45 BRO	SP	P	ED	T	4/1/2064
2020 PO3887611721	KU	4	45 BRO	SP	P	ED	T	4/2/2064
2020 PO3892111529	KU	4	45 BRO	SP	P	ED	T	4/3/2064
2020 PO3878712112	KU	4	45 BRO	SP	P	ED	T	4/4/2064
2020 PO3876412269	KU	4	45 BRO	SP	CCA		V	4/5/2064
2020 PO4088483102	LGE	3	45 BRO	SP	CCA		V	4/6/2064
2020 PO4707688335	LGE	1	75 BRN	ST	P		V	4/7/2064
2020 PO4709088346	LGE	UNK	80 BRN	ST	P		V	4/8/2064
2020 PO3849781960	LGE	1	65 BRO	SP	CRE		V	4/9/2064
2020 PO3863282221	LGE	4	30 BRO	SP	CCA		V	4/10/2064
2020 PO3849181962	LGE	4	30 BRO	SP	P	ED,ID	TD	4/11/2064
2020 PO1207862457	KU	5	35 BRN	SP	CRE		V	4/12/2064
2020 PO1216262437	KU	4	40 BRN	SP	CCA		V	4/13/2064
2020 PO1219362597	KU	4	40 BRN	SP	CRE		V	4/14/2064
2020 PO1230262458	KU	6	30 BRN	SP	CRE		V	4/15/2064
2020 PO1221662369	KU	4	40 BRN	SP	CRE		V	4/16/2064
2020 PO1236962851	KU	5	35 BRN	SP	CRE		V	4/17/2064
2020 PO9408895462	KU	6	30 BRN	SP	CRE	ED,ID,SRC	TD	4/18/2064

2020 PO9454595315	KU	4	40 BRN	SP	CRE	ID	BD	4/19/2064	
2020 PO9242393172	KU	5	35 BRN	SP	CRE	ED,ID,SRC	TD	4/20/2064	
2020 PO9265793043	KU	6	35 BRN	SP	CRE	ID	BD	4/21/2064	
2020 PO8938293737	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD	4/22/2064	
2020 PO9851695200	KU	4	40 BRN	SP	CRE	ED,ID,IP	X	RP2	4/23/2064
2020 PO9715896139	KU	4	40 BRN	SP	CRE	ID,IP	BD	4/24/2064	
2020 PO9487695234	KU	4	40 BRO	SP	CRE		V	4/25/2064	
2020 PO9556295460	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/26/2064	
2020 PO8949393677	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/27/2064	
2020 PO9822595639	KU	4	40 BRN	SP	CRE	ED,EP,ID,IP	TD	4/28/2064	
2020 PO4751117248	KU	4	40 BRO	SP	CCA		V	4/29/2064	
2020 PO4768817255	KU	3	45 BRO	SP	CCA		V	4/30/2064	
2020 PO4768917033	KU	3	45 BRO	SP	CCA		V	5/1/2064	
2020 PO4768816655	KU	4	40 BRO	SP	CCA		V	5/2/2064	
2020 PO4768816419	KU	4	40 BRO	SP	CCA		V	5/3/2064	
2020 PO4768716202	KU	3	45 BRO	SP	CCA		V	5/4/2064	
2020 PO4768615909	KU	2	45 BRO	SP	CRE	ED,ID	TD	5/5/2064	
2020 PO4768615909	KU	2	45 BRO	SP	CRE	ED,ID	TD	5/6/2064	
2020 PO4768315680	KU	3	45 BRO	SP	CCA		V	5/7/2064	
2020 PO4772015485	KU	3	45 BRO	SP	CCA		V	5/8/2064	
2020 PO4783015252	KU	4	40 BRO	SP	CCA		V	5/9/2064	
2020 PO4745315270	KU	4	40 BRO	SP	CCA		V	5/10/2064	
2020 PO4840314603	KU	4	45 BRO	SP	CRE	ED,ID	TD	5/11/2064	
2020 PO4816014607	KU	3	45 BRO	SP	CCA		V	5/12/2064	
2020 PO4829014382	KU	4	40 BRO	SP	CCA		V	5/13/2064	
2020 PO4894118657	F	3	45 BRO	SP	A		V	5/14/2064	
2020 PO4846013119	KU	3	40 BRO	SP	CRE		V	5/15/2064	
2020 PO4851513240	KU	3	45 BRO	SP	CCA		V	5/16/2064	
2020 PO4828213193	KU	3	45 BRO	SP	CCA		V	5/17/2064	
2020 PO4828613368	KU	4	40 BRO	SP	CCA		V	5/18/2064	
2020 PO4606099694	KU	4	40 XXX	SP	CRE	ED,ID	TD	5/19/2064	
2020 PO4609899827	KU	6	30 XXX	SP	CRE	ED,ID	TD	5/20/2064	
2020 PO4616499819	KU	4	40 XXX	SP	CRE	ED,ID	TD	5/21/2064	
2020 PO4619099613	KU	5	35 BRN	SP	CCA		V	5/22/2064	
2020 PO4627899703	KU	4	40 BRN	SP	CCA		V	5/23/2064	
2020 PO4627099947	KU	4	45 XXX	SP	CRE	ED,ID	TD	5/24/2064	
2020 PO4642999920	KU	5	35 XXX	SP	CRE	ED,ID	TD	5/25/2064	
2020 PO4633200020	KU	4	40 XXX	SP	CRE	ED,ID	TD	5/26/2064	
2020 PO4643000137	KU	4	40 XXX	SP	CRE	ED,ID	TD	5/27/2064	
2020 PO4652500180	KU	4	40 XXX	SP	CRE	ED,ID	TD	5/28/2064	
2020 PO2264624402	ODP	5	30 XXX	SP	CRE	ID	TD	5/29/2064	
2020 PO2265124346	ODP	4	40 XXX	SP	CCA		V	5/30/2064	
2020 PO2285624355	ODP	4	45 XXX	SP	CCA		V	5/31/2064	
2020 PO4829213543	KU	4	40 BRO	SP	CCA		V	6/1/2064	
2020 PO4854213832	KU	3	45 BRO	SP	CCA		V	6/2/2064	
2020 PO5635950151	KU	3	45 ACE	SP	CRE	ED,ID	TD	6/3/2064	
2020 PO5645650249	C	6	30 ACE	SP	CRE		V	6/4/2064	

2020 PO5597250622	KU	6	30 ACE	SP	CRE		V	6/5/2064
2020 PO5642250307	KU	3	50 ACE	DF	CRE	ED,ID	TD	6/6/2064
2020 PO5641850367	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD	6/7/2064
2020 PO5644150357	KU	4	45 ACE	SP	CRE	ED,ID	TD	6/8/2064
2020 PO4831314274	KU	6	30 BRO	SP	CRE	ED,ID	TD	6/9/2064
2020 PO4859514263	KU	5	35 BRO	SP	CCA		V	6/10/2064
2020 PO4838814210	KU	2	40 BRO	SP	CCA		V	6/11/2064
2020 PO4870118839	KU	3	50 BRO	SP	CCA		V	6/12/2064
2020 PO4854918676	KU	4	45 BRO	SP	CRE	ID	BD	6/13/2064
2020 PO5658850664	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	6/14/2064
2020 PO4825518373	KU	3	45 BRO	SP	CCA		V	6/15/2064
2020 PO4795118116	KU	3	45 BRO	SP	CCA		V	6/16/2064
2020 PO5671751004	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	6/17/2064
2020 PO5669751014	KU	4	40 ACE	SP	CRE	ED,ID	BD	6/18/2064
2020 PO4721318095	KU	4	40 BRO	SP	CRE	ED,ID	TD	6/19/2064
2020 PO4774417243	F	4	40 BRO	SP	CCA		V	6/20/2064
2020 PO5774150650	KU	6	30 ACE	SP	CCA		V	6/21/2064
2020 PO4734988814	LGE	3	45 BRN	SP	S		V	6/22/2064
2020 PO4733988828	LGE	4	35 BRN	SP	A	ED,ID,RB	TX	RR 6/23/2064
2020 PO4034982852	F	4	40 BRO	SP	A		V	6/24/2064
2020 PO4035182848	F	3	50 BRO	SP	P		V	6/25/2064
2020 PO4035482833	F	3	45 BRO	SP	P		V	6/26/2064
2020 PO4035982817	F	2	50 BRO	SP	P		V	6/27/2064
2020 PO4036582820	F	3	45 BRO	SP	P		V	6/28/2064
2020 PO4036782819	LGE	3	45 BRO	SP	CRE	ED,ID	TD	6/29/2064
2020 PO4038582825	LGE	4	40 BRO	SP	P	ED,ID	TD	6/30/2064
2020 PO4038482831	LGE	4	30 BRO	SP	P	ED,ID	TD	7/1/2064
2020 PO4038182833	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	7/2/2064
2020 PO4733788837	LGE	3	45 BRN	SP	A	ED,ID	TD	7/3/2064
2020 PO4732488829	LGE	3	45 BRN	SP	A	ED,ID	TD	7/4/2064
2020 PO4731388821	LGE	4	40 BRN	SP	CCA		V	7/5/2064
2020 PO4731288822	LGE	4	40 BRN	SP	A	ED,ID	TD	7/6/2064
2020 PO4813133198	KU	4	45 BRO	SP	CRE	ED	X	RP2 7/7/2064
2020 PO4521100502	KU	3	45 BRN	SP	CCA		V	7/8/2064
2020 PO2150925766	ODP	6	30 XXX	SP	CRE	ID	BD	7/9/2064
2020 PO2147425713	ODP	6	30 XXX	SP	CRE	ID	TD	7/10/2064
2020 PO4527900397	KU	4	40 BRN	SP	CRE	ED,ID	TD	7/11/2064
2020 PO2150325655	ODP	3	50 XXX	SP	CCA		V	7/12/2064
2020 PO2145925534	ODP	4	40 XXX	SP	CRE	ID	TD	7/13/2064
2020 PO2150325567	F	6	30 XXX	SP	CRE		V	7/14/2064
2020 4556000240a	KU	6	30 BRN	SP	CRE	ED,ID	TD	7/15/2064
2020 PO4536800260	KU	4	40 BRN	SP	CRE	ED,ID	TD	7/16/2064
2020 PO4736788734	LGE	4	35 BRN	SP	A	ED,ID	TD	7/17/2064
2020 PO4737588721	LGE	4	35 BRN	SP	CRE	ED,ID	TD	7/18/2064
2020 PO4544800146	KU	4	40 BRN	SP	CRE	ED,ID	TD	7/19/2064
2020 PO4034682864	LGE	3	50 BRO	SP	A	ED,ID	TD	7/20/2064
2020 PO4034482873	F	4	40 BRO	SP	CCA		V	7/21/2064

2020 PO4037182898	LGE	4	30 BRO	SP	CCA		V							7/22/2064
2020 PO4037482908	LGE	4	35 BRO	SP	CCA		V							7/23/2064
2020 PO4813433052	KU	3	45 BRO	SP	CCA		V							7/24/2064
2020 PO4813932860	KU	3	45 BRO	SP	CCA		V							7/25/2064
2020 PO4813832689	KU	5	35 BRO	SP	CCA		V							7/26/2064
2020 PO4814432442	KU	3	45 BRO	SP	CCA		V							7/27/2064
2020 PO4815132125	KU	5	45 BRO	SP	CRE	ID		TD						7/28/2064
2020 PO4815831794	KU	4	40 BRO	SP	CRE	ID		TD						7/29/2064
2020 PO5126036920	KU	4	40 ACE	SP	CRE	ID		BD						7/30/2064
2020 PO3540348961	KU	4	40 ACE	SP	CRE	ED,ID		TD						7/31/2064
2020 PO3517448806	KU	5	35 ACE	SP	CCA	ED,ID		TD						8/1/2064
2020 PO3537348808	KU	4	40 ACE	SP	CRE	ED,ID		TD						8/2/2064
2020 PO5086637332	KU	4	40 ACE	SP	CRE	ED,ID,IP		TX		RR				8/3/2064
2020 PO5091437114	KU	4	40 ACE	SP	CRE	ED,ID,IP		TD						8/4/2064
2020 PO5077937333	KU	6	30 ACE	SP	CRE	ED,ID		TD						8/5/2064
2020 PO4199832755	KU	4	40 BRO	SP	CCA		V							8/6/2064
2020 PO4190932548	KU	3	45 BRO	SP	CCA		V							8/7/2064
2020 PO4488599935	LGE	4	35 BRN	SP	A	ED,ID		TD						8/8/2064
2020 PO3276751332	KU	5	35 ACE	DF	CRE	ED,HH,ID,RB		BX		RP1				8/9/2064
2020 PO4036882875	LGE	4	35 BRO	SP	CCA		V							8/10/2064
2020 PO4035982850	LGE	4	35 BRO	SP	CCA		V							8/11/2064
2020 PO4735888659	LGE	4	35 BRN	SP	A	ED,ID		TD						8/12/2064
2020 PO4593900525	KU	5	35 BRN	SP	CCA	ED		T						8/13/2064
2020 PO4580900575	KU	4	40 BRN	SP	CRE	ED,ID		TD						8/14/2064
2020 PO4575600395	KU	5	35 BRN	SP	CCA		V							8/15/2064
2020 PO4566000380	KU	4	40 BRN	SP	CRE	ED,ID,IP		TD						8/16/2064
2020 PO4035782865	LGE	4	35 BRO	SP	P		V							8/17/2064
2020 PO7539340461	LGE	4	35 BRO	SP	CCA		V							8/18/2064
2020 PO2152725323	ODP	6	30 XXX	SP	CRE	ID		TD						8/19/2064
2020 PO2160425360	ODP	4	45 XXX	SP	CCA		V							8/20/2064
2020 PO2160125141	ODP	4	45 XXX	SP	CCA		V							8/21/2064
2020 PO2162425157	ODP	4	35 XXX	SP	CRE	ID		TD						8/22/2064
2020 PO4735088673	LGE	4	35 BRN	SP	CCA		V							8/23/2064
2020 PO4735888659	LGE	4	35 BRN	SP	CCA		V							8/24/2064
2020 PO4735988652	LGE	4	40 BRN	SP	CRE	ED,ID		BD						8/25/2064
2020 PO4042882890	LGE	4	40 BRO	SP	A	ED,ID		TD						8/26/2064
2020 PO4039782916	LGE	4	40 BRO	SP	CCA		V							8/27/2064
2020 PO4735488615	LGE	4	35 BRN	SP	A		V							8/28/2064
2020 PO4556000240	KU	4	40 BRN	SP	CRE	ED,ID,IP		TD						8/29/2064
2020 PO4741688591	LGE	4	40 BRN	SP	CRE	ED,ID		BD						8/30/2064
2020 PO4740788588	LGE	4	40 BRN	SP	A	ED,ID		BD						8/31/2064
2020 PO2169825036	ODP	4	40 XXX	SP	CCA		V							9/1/2064
2020 PO2180824938	ODP	5	35 XXX	SP	CRE	ID		TD						9/2/2064
2020 PO2177624876	ODP	4	40 XXX	SP	CRE	ID		TD						9/3/2064
2020 PO2187024799	ODP	4	40 XXX	SP	CRE	ED,EP,ID		TX		RR				9/4/2064
2020 PO2218425232	F	4	40 XXX	SP	CRE		V							9/5/2064
2020 PO2220725130	ODP	4	40 XXX	SP	A	ID		BD						9/6/2064

2020 PO2207625117	ODP	4	40 XXX	SP	CCA		V	9/7/2064
2020 PO2199424849	ODP	2	50 XXX	SP	CCA		V	9/8/2064
2020 PO2206324837	ODP	4	40 XXX	SP	CRE	ID	TD	9/9/2064
2020 PO2207224893	F	4	40 XXX	SP	CRE		V	9/10/2064
2020 PO4739788585	LGE	4	40 BRN	SP	CRE	ED,ID	BD	9/11/2064
2020 PO4616900347	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/12/2064
2020 PO4566500103	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/13/2064
2020 PO4040682833	LGE	3	45 BRO	SP	A	ED,ID	TD	9/14/2064
2020 PO4040482842	LGE	4	40 BRO	SP	A	ED,ID	TD	9/15/2064
2020 PO4038982856	LGE	4	35 BRO	SP	CCA		V	9/16/2064
2020 PO4040082855	LGE	4	35 BRO	SP	CRE	ED,ID	BD	9/17/2064
2020 PO4040082858	LGE	4	40 BRO	SP	CCA		V	9/18/2064
2020 PO4040782887	LGE	4	35 BRO	SP	CCA		V	9/19/2064
2020 PO4043182880	LGE	4	40 BRO	SP	P	ED,ID	BD	9/20/2064
2020 PO4044082849	LGE	4	40 BRO	SP	P	ED,ID,IP	BD	9/21/2064
2020 PO4739388591	LGE	4	40 BRN	SP	CRE	ED,ID	BD	9/22/2064
2020 PO4738488603	LGE	3	45 BRN	SP	A	ED,ID	BD	9/23/2064
2020 PO4612200294	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/24/2064
2020 PO4601800176	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/25/2064
2020 PO4737988611	LGE	4	35 BRN	SP	CRE	ED,ID	BD	9/26/2064
2020 PO4737288621	LGE	4	40 BRN	SP	A	ED,ID	BD	9/27/2064
2020 PO4736788630	LGE	4	40 BRN	SP	A	ED,ID	BD	9/28/2064
2020 PO4591300057	KU	4	45 BRN	SP	CRE	ED,ID	TD	9/29/2064
2020 PO4579999929	KU	4	40 BRN	SP	CRE	ED	T	9/30/2064
2020 PO4735688648	LGE	4	40 BRN	SP	CRE	ED,ID	BD	10/1/2064
2020 PO4044482833	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	10/2/2064
2020 PO4043582868	LGE	3	45 BRO	SP	CRE	ED,ID	TD	10/3/2064
2020 PO4044582822	LGE	4	40 BRO	SP	P		T	10/4/2064
2020 PO4736088641	LGE	3	45 BRN	SP	A	ED,ID	BD	10/5/2064
2020 PO4592299766	KU	4	45 XXX	SP	CRE	ED,ID	TD	10/6/2064
2020 PO4605999588	KU	3	45 BRN	SP	CCA		V	10/7/2064
2020 PO4597599696	KU	4	45 BRN	SP	CCA		V	10/8/2064
2020 PO4611299519	KU	4	40 XXX	SP	CRE	ED,ID	TD	10/9/2064
2020 PO4612499472	KU	6	30 XXX	SP	CRE	ED,ID	TD	10/10/2064
2020 PO2228924767	ODP	4	40 XXX	SP	A	ID	TD	10/11/2064
2020 PO2227524652	ODP	4	40 XXX	SP	CRE	ID	TD	10/12/2064
2020 PO2236224548	ODP	4	40 XXX	SP	CCA		V	10/13/2064
2020 PO2265124346A	ODP	4	40 XXX	SP	CRE	ID	TD	10/14/2064
2020 PO2314124076	ODP	6	30 XXX	SP	CCA	ED	T	10/15/2064
2020 PO2302124095	ODP	4	40 XXX	SP	CRE	ID	TD	10/16/2064
2020 PO2270724111	F	4	40 XXX	SP	CCA		V	10/17/2064
2020 PO2256624123	F	4	40 XXX	SP	A		V	10/18/2064
2020 4661499878a	F	3	45 XXX	SP	CCA		V	10/19/2064
2020 PO4650699757	F	4	40 XXX	SP	A		V	10/20/2064
2020 PO4638899625	F	4	40 XXX	SP	A		V	10/21/2064
2020 PO4628499508	F	4	40 XXX	SP	CRE		V	10/22/2064
2020 PO4620499413	F	4	40 XXX	SP	A		V	10/23/2064

2020 PO4616299365	F	3	45 XXX	SP	P		V		10/24/2064
2020 PO4654000013	KU	5	35 XXX	SP	CCA		V		10/25/2064
2020 PO4658099917	KU	5	35 XXX	SP	CRE	ID,RB	X	RP1	10/26/2064
2020 PO4661499878	KU	4	45 XXX	SP	CRE	ED,ID	TD		10/27/2064
2020 PO4676499931	KU	3	50 XXX	SP	CRE	ED,ID	TD		10/28/2064
2020 PO4672700271	KU	4	40 XXX	SP	CRE	ED,ID	TD		10/29/2064
2020 PO4663400244	KU	5	30 XXX	SP	CRE	ED,ID	TD		10/30/2064
2020 PO4685400160	KU	3	40 XXX	SP	CCA	ED	T		10/31/2064
2020 PO4716800588	KU	4	40 XXX	SP	CRE	ED,ID	TD		11/1/2064
2020 PO4720789246	F	4	40 BRO	SP	CRE		V		11/2/2064
2020 PO4721189252	F	4	30 BRO	SP	CRE		V		11/3/2064
2020 PO4720489259	F	4	40 BRO	SP	CCA		V		11/4/2064
2020 PO4976711927	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD		11/5/2064
2020 PO4976511914	KU	6	30 ACE	SP	CRE	ED,ID	TD		11/6/2064
2020 PO4428601384	KU	4	40 BRN	SP	CRE	ED,ID	TD		11/7/2064
2020 PO4440001194	KU	4	40 BRN	SP	CRE	ED,ID	TD		11/8/2064
2020 PO4745488615	LGE	4	35 BRN	SP	CRE	ED,ID	TD		11/9/2064
2020 PO4744688634	LGE	4	35 BRN	SP	A	ED,ID	TD		11/10/2064
2020 PO2126626393	ODP	5	35 XXX	SP	CRE	ID	TD		11/11/2064
2020 PO2122826143A	ODP	6	30 XXX	SP	CRE	ID	BD		11/12/2064
2020 PO2122826143	ODP	4	40 XXX	SP	CRE	ID	BD		11/13/2064
2020 PO2145825990	ODP	5	35 XXX	SP	CCA		V		11/14/2064
2020 PO2116026129	ODP	5	35 XXX	SP	CRE	ID	BD		11/15/2064
2020 PO2125325998	ODP	4	40 XXX	SP	CRE	ID	TD		11/16/2064
2020 PO2107925915	ODP	5	35 XXX	SP	CCA		V		11/17/2064
2020 PO2114025734	ODP	5	35 XXX	SP	CCA		V		11/18/2064
2020 PO2128525768	ODP	4	45 XXX	SP	CRE	ID	TD		11/19/2064
2020 PO2135825670	ODP	4	40 XXX	SP	CRE	ID	TD		11/20/2064
2020 PO1794322739	ODP	6	30 XXX	SP	CRE		V		11/21/2064
2020 PO4970911953	KU	6	30 ACE	SP	CRE	ED,ID	TD		11/22/2064
2020 PO4744488622	LGE	4	35 BRN	SP	A	ED,ID	TD		11/23/2064
2020 PO4446301087	KU	4	40 BRN	SP	CRE	ED,ID,RB	X	PX	11/24/2064
2020 PO4453100982	KU	4	40 BRN	SP	CRE	ED,ID	TD		11/25/2064
2020 PO4462100832	KU	4	40 BRN	SP	CCA		V		11/26/2064
2020 PO4439401064	KU	4	40 BRN	SP	CRE	ED,ID	TD		11/27/2064
2020 PO4447200912	KU	4	40 BRN	SP	CRE	ED,ID	TD		11/28/2064
2020 PO4966011974	KU	6	30 ACE	SP	CRE	ED,ID	TD		11/29/2064
2020 PO4964112047	KU	6	30 ACE	SP	CRE	ED,ID	BD		11/30/2064
2020 PO4964612096	KU	6	30 ACE	SP	CCA		V		12/1/2064
2020 PO4741888604	LGE	4	35 BRN	SP	A	ED,ID,SR	TX	RR	12/2/2064
2020 PO4733688699	LGE	4	35 BRN	SP	CCA		V		12/3/2064
2020 PO4734388685	LGE	4	35 BRN	SP	CCA		V		12/4/2064
2020 PO4734888670	LGE	4	40 BRN	SP	CRE		V		12/5/2064
2020 PO4734888669	LGE	4	40 BRN	SP	CRE		V		12/6/2064
2020 PO4727289262	F	3	45 BRO	SP	CCA		V		12/7/2064
2020 PO4358705423	LGE	3	45 BRO	SP	CRE		V		12/8/2064
2020 PO4352805517	LGE	3	45 BRO	SP	CCA		V		12/9/2064

2020	PO4726789270	F	3	45 BRO	SP	CCA	V			12/10/2064
2020	PO4724789275	F	3	45 BRO	SP	CCA	V			12/11/2064
2020	PO4723489268	F	3	45 BRO	SP	CCA	V			12/12/2064
2020	PO4722689270	F	4	30 BRO	SP	CRE	V			12/13/2064
2020	PO4723389275	F	4	30 BRO	SP	CRE	V			12/14/2064
2020	PO4344805637	LGE	3	45 BRO	SP	CCA	V			12/15/2064
2020	PO4725889285	F	3	45 BRO	SP	CCA	V			12/16/2064
2020	PO4723689347	F	3	45 BRO	SP	CCA	V			12/17/2064
2020	PO4332105829	LGE	3	45 BRO	SP	CRE	V			12/18/2064
2020	PO4724789301	F	3	45 BRO	SP	CCA	V			12/19/2064
2020	PO4322005981	LGE	3	45 BRO	SP	CRE	V			12/20/2064
2020	PO4723889316	F	3	45 BRO	SP	CCA	V			12/21/2064
2020	PO4722589310	F	3	45 BRO	SP	CCA	V			12/22/2064
2020	PO4721189301	F	4	40 BRO	SP	CRE	V			12/23/2064
2020	PO4971812009	KU	6	30 ACE	SP	CCA	V			12/24/2064
2020	PO4980611971	KU	6	30 ACE	SP	CCA	V			12/25/2064
2020	PO4987211944	KU	6	30 ACE	SP	CCA	V			12/26/2064
2020	PO4727488759	LGE	4	40 BRN	SP	A		ED,ID		TD
2020	PO4459006691	KU	4	40 BRN	SP	CRE		ED,ID		TD
2020	PO4727488769	LGE	3	45 BRN	SP	S				V
2020	PO4371700554	F	4	40 BRN	SP	A				V
2020	PO4719789292	F	4	40 BRO	SP	CRE				V
2020	PO4719189286	F	4	40 BRO	SP	CRE				V
2020	PO4718689276	F	4	40 BRO	SP	CRE				V
2020	PO4721189331	F	4	40 BRO	SP	CRE				V
2020	PO4719789322	F	3	45 BRO	SP	CCA				V
2020	PO4717589296	LGE	3	45 BRO	SP	P		ED,ID		BD
2020	PO4726288804	LGE	4	40 BRN	SP	CRE		ED,ID		BD
2020	PO4722789332	F	4	40 BRO	SP	CRE				V
2020	PO4722389339	F	3	45 BRO	SP	CCA				V
2020	PO4306306213	LGE	3	45 BRO	SP	CRE				V
2020	PO4721789348	F	3	45 BRO	SP	CCA				V
2020	PO4720789364	F	4	40 BRO	SP	CRE				V
2020	PO4720289371	F	4	40 BRO	SP	CRE				V
2020	PO4726588797	LGE	4	40 BRN	SP	CRE		ED,ID		BD
2020	PO4474800634	KU	4	40 BRN	SP	CRE		ED,ID		TD
2020	PO4469900544	KU	4	40 BRN	SP	CRE		ED,ID,IP		TX
2020	PO4477200594	KU	4	40 BRN	SP	CRE		ED,ID		TD
2020	PO4488400704	KU	4	40 BRN	SP	CRE		ED,ID		TD
2020	PO4727088788	LGE	4	40 BRN	SP	A		ED,ID		BD
2020	PO4361000626	LGE	6	25 BRN	SP	CRE		ED,HH,ID,RB		BX
2020	PO4719389361	F	4	40 BRO	SP	CRE				V
2020	PO4717989351	F	4	40 BRO	SP	CRE				V
2020	PO4649613116	F	4	40 BRO	SP	CRE				V
2020	PO4644713198	F	4	40 BRO	SP	CRE				V
2020	PO4659213239	F	4	40 BRO	SP	CRE				V
2020	PO4622413475	F	4	40 BRO	SP	CCA				V

2020 PO4668713362	F	4	40 BRO	SP	CRE		V			1/26/2065
2020 PO4614987924	F	4	40 BRO	SP	CRE	ED,HH,ID,RB	VX	PX		1/27/2065
2020 PO4774888830	LGE	4	40 BRN	SP	P	ED,ID	TD			1/28/2065
2020 PO4775188831	LGE	4	40 BRN	SP	CRE	ED,ID	TD			1/29/2065
2020 PO4614187936	F	4	40 BRO	SP	CCA	ED,HH,ID,RB	VX	PX		1/30/2065
2020 PO4611387978	F	4	40 BRO	SP	CCA		V			1/31/2065
2020 PO4612187966	F	4	40 BRO	SP	CCA		V			2/1/2065
2020 PO4613387948	F	4	40 BRO	SP	CCA		V			2/2/2065
2020 PO4616387901	F	4	40 BRO	SP	CCA		V			2/3/2065
2020 PO4617287888	F	4	40 BRO	SP	CRE		V			2/4/2065
2020 PO5103914207	KU	4	40 BRO	SP	CRE		V			2/5/2065
2020 PO5098214102	KU	4	40 BRO	SP	CRE		V			2/6/2065
2020 PO5104214353	KU	4	40 BRO	SP	CRE		V			2/7/2065
2020 PO4773388823	LGE	4	40 BRN	SP	P	ED,HH,ID,SRS	TX	RR		2/8/2065
2020 PO4774588844	LGE	4	40 BRN	SP	CRE	ED,ID	TD			2/9/2065
2020 PO4759288216	LGE	3	45 BRO	SP	A	ED,ID	TD			2/10/2065
2020 PO4749088223	LGE	4	30 BRO	SP	P	ED,ID	TD			2/11/2065
2020 PO4749688196	F	3	45 BRO	SP	CCA		V			2/12/2065
2020 PO6099966503	KU	5	35 OTH	SP	CRE	ED,EP,HH,ID	VX	RP3		2/13/2065
2020 PO6102066360A	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD			2/14/2065
2020 PO6108666506	F	5	25 OTH	SP	CCA		V			2/15/2065
2020 PO6103066678	F	4	40 OTH	SP	P	ED	V			2/16/2065
2020 PO6111666331	KU	4	45 OTH	SP	CRE	ID	TD			2/17/2065
2020 PO6149166378	KU	3	40 OTH	SP	CRE	ID	TD			2/18/2065
2020 PO6129166352	KU	4	40 OTH	SP	CRE	ID	TD			2/19/2065
2020 PO6151766284	KU	5	35 OTH	SP	CCA		V			2/20/2065
2020 PO6130966250	KU	6	30 OTH	SP	CRE	ID	TD			2/21/2065
2020 PO6145666250	KU	6	30 OTH	SP	CCA		V			2/22/2065
2020 PO6097366684	KU	4	40 OTH	SP	CCA		V			2/23/2065
2020 PO3633951189	KU	6	30 BRN	SP	CCA		V			2/24/2065
2020 PO3634751236	KU	6	30 BRN	SP	CRE	ED,ID,SRC	TD			2/25/2065
2020 PO3635451401	KU	3	45 OTH	SP	CCA	ED	TD			2/26/2065
2020 PO3646951411	KU	4	40E OTH	SP	CRE	ED,ID,SRS	TD			2/27/2065
2020 PO3646151339	F	6	30E OTH	SP	CRE		V			2/28/2065
2020 PO3633451328	F	6	35E OTH	SP	CRE		V			3/1/2065
2020 PO7460437093	KU	4	40 OTH	SP	CRE	ED,HH,ID,RB	X	PX		3/2/2065
2020 PO5685009178	KU	4	40 XXX	SP	CRE	ED,ID	TD			3/3/2065
2020 PO5681809400	KU	4	40 XXX	SP	CRE	ED,ID	TD			3/4/2065
2020 PO4652888215	LGE	4	40 BRN	SP	A	ED,ID	BD			3/5/2065
2020 PO4721888285	LGE	4	40 BRO	SP	CRE	ED,ID	TD			3/6/2065
2020 PO4722888277	LGE	4	40 BRO	SP	CRE	ED,HH,ID,RB	VX	PX		3/7/2065
2020 PO4724088268	LGE	4	40 BRO	SP	CRE	ED,ID	TD			3/8/2065
2020 PO4725288258	LGE	3	45 BRO	SP	P	ED,ID	T			3/9/2065
2020 PO4726588247	LGE	3	45 BRO	SP	CCA		V			3/10/2065
2020 PO4726688266	LGE	4	40 BRO	SP	CRE	ED,ID	BD			3/11/2065
2020 PO4727688281	LGE	4	40 BRO	SP	CRE	ED,ID	BD			3/12/2065
2020 PO4728588299	LGE	4	40 BRO	SP	CRE	ED,ID	BD			3/13/2065

2020 PO4715588141	LGE	3	45 BRO	SP	CCA		V			3/14/2065
2020 PO4260194088	LGE	3	45 BRO	SP	CCA		V			3/15/2065
2020 PO4715888115	LGE	4	30 BRO	SP	CCA		V			3/16/2065
2020 PO4716188115	LGE	3	45 BRO	SP	CCA		V			3/17/2065
2020 PO4716488099	LGE	3	45 BRO	SP	CCA		V			3/18/2065
2020 PO7470537348	KU	4	40 OTH	SP	CRE	ID	TD			3/19/2065
2020 PO4653888258	LGE	6	25 BRN	SP	CRE	ED,ID	BX	PX		3/20/2065
2020 PO4653588257	LGE	4	35 BRN	SP	A	ED,ID	BD			3/21/2065
2020 PO4651788232	LGE	3	45 BRN	SP	CCA		V			3/22/2065
2020 PO4650688248	LGE	4	35 BRN	SP	A	ED,ID	TD			3/23/2065
2020 PO4651288240	LGE	4	35 BRN	SP	CRE	ED,ID	BD			3/24/2065
2020 PO4642789080	LGE	4	30 BRO	SP	CRE	ID,IP	BD			3/25/2065
2020 PO3772189520	KU	6	30 XXX	SP	CCA		V			3/26/2065
2020 PO3784289519	F	4	40 XXX	SP	CRE		V			3/27/2065
2020 PO3775389464	F	4	40 XXX	SP	CRE		V			3/28/2065
2020 PO3778689413	KU	5	35 XXX	SP	CRE	ID	BD			3/29/2065
2020 PO3784089140	F	4	40 XXX	SP	CRE		V			3/30/2065
2020 PO4642189079	F	4	30 BRO	SP	CCA		V			3/31/2065
2020 PO5668609950	KU	4	40 XXX	SP	CCA		V			4/1/2065
2020 PO5687110041	KU	4	40 XXX	SP	CRE	ED,ID	TD			4/2/2065
2020 PO5684710435	KU	4	40 XXX	SP	CRE	ED,ID	TD			4/3/2065
2020 PO4642389058	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD			4/4/2065
2020 PO3798989237	F	4	40 XXX	SP	CRE		V			4/5/2065
2020 PO3809689306	F	4	40 XXX	SP	CRE		V			4/6/2065
2020 PO4654288303	LGE	4	30 BRN	SP	A	ED,ID,SRS	TX	RR		4/7/2065
2020 PO4654088307	LGE	4	40 BRN	SP	A	ED,ID	TD			4/8/2065
2020 PO7352838492	KU	5	35 OTH	SP	CRE	ID	TD			4/9/2065
2020 7352838492A	KU	6	30 OTH	SP	CRE	ID	TD			4/10/2065
2020 PO7389738430	KU	4	40 OTH	SP	CRE	ID	TD			4/11/2065
2020 PO7370638438	KU	4	40 OTH	SP	CRE	ID	TD			4/12/2065
2020 PO7360938319	KU	6	30 OTH	SP	CCA	ED,SRS	TD			4/13/2065
2020 PO7352438446	KU	4	45 OTH	SP	CRE	ID	TD			4/14/2065
2020 PO7381638501	KU	6	30 OTH	SP	CCA		V			4/15/2065
2020 PO5679506840	KU	3	45 XXX	SP	CCA		V			4/16/2065
2020 PO5692206885	KU	4	40 XXX	SP	CCA		V			4/17/2065
2020 PO5709606830	KU	3	45 XXX	SP	CCA		V			4/18/2065
2020 PO5709707206	KU	4	40 XXX	SP	CRE	ED,ID	TD			4/19/2065
2020 PO3746590452	F	3	40 XXX	SP	CCA		V			4/20/2065
2020 PO3742090423	F	4	40 XXX	SP	CCA		V			4/21/2065
2020 PO3727390390	F	5	35 XXX	SP	CCA		V			4/22/2065
2020 PO3722090356	F	5	35 XXX	SP	CRE		V			4/23/2065
2020 PO3733990369	F	4	40 XXX	SP	CRE		V			4/24/2065
2020 PO3872582515	LGE	2	65 BRO	SP	CRE		V			4/25/2065
2020 PO5750747580	F	4	40 ACE	SP	CRE		V			4/26/2065
2020 PO5738647488	F	4	40 ACE	SP	CRE		V			4/27/2065
2020 PO5721947470	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	VX	RP1		4/28/2065
2020 PO5764248013	F	4	40 ACE	SP	CRE		V			4/29/2065

2020 PO5779047846	F	4	40 ACE	SP	CRE		V	4/30/2065	
2020 PO5753747953	F	4	40 ACE	SP	CRE		V	5/1/2065	
2020 PO5738847866	F	4	40 ACE	SP	CCA		V	5/2/2065	
2020 PO5707947696	F	4	40 ACE	SP	CCA		V	5/3/2065	
2020 PO5725047790	F	4	40 ACE	SP	CRE		V	5/4/2065	
2020 PO5785347770	F	4	40 ACE	SP	CRE		V	5/5/2065	
2020 PO5793647560	F	4	40 ACE	SP	CRE		V	5/6/2065	
2020 PO5717047545	KU	6	35 ACE	SP	CRE	ED,ID	TD	5/7/2065	
2020 PO3872182501	LGE	2	65 BRO	SP	CRE		V	5/8/2065	
2020 PO3872882501	LGE	3	30 BRO	SP	CRE		V	5/9/2065	
2020 PO3872882514	LGE	4	35 BRO	SP	P	ED	T	5/10/2065	
2020 PO3880582900	LGE	3	45 BRO	SP	CCA		V	5/11/2065	
2020 PO3882282896	LGE	2	50 BRO	SP	CRE		V	5/12/2065	
2020 PO3943581876	LGE	4	40 BRN	SP	CRE	ED,ID	TD	5/13/2065	
2020 PO1875840972	ODP	4	40 KOP	SP	A	ED,ID	TD	5/14/2065	
2020 PO1875740869	ODP	5	35 KOP	SP	CRE	ED,ID	TD	5/15/2065	
2020 PO3945481860	LGE	4	40 BRN	SP	CRE	ED,ID	TD	5/16/2065	
2020 PO3946481853	LGE	4	40 BRN	SP	CRE	ED,ID	TD	5/17/2065	
2020 PO3947581847	LGE	4	40 BRN	SP	CRE	ED,ID	TD	5/18/2065	
2020 PO3948481845	LGE	4	35 BRN	SP	CCA		V	5/19/2065	
2020 PO3948481840	LGE	3	45 BRN	SP	CCA		V	5/20/2065	
2020 PO3949481833	LGE	3	45 BRN	SP	CCA		V	5/21/2065	
2020 PO3950681825	LGE	3	45 BRN	SP	CCA		V	5/22/2065	
2020 PO3951681818	LGE	3	45 BRN	SP	CCA		V	5/23/2065	
2020 PO3948181748	LGE	3	45 BRN	SP	CCA		V	5/24/2065	
2020 PO3947881741	LGE	4	40 BRN	SP	CCA		V	5/25/2065	
2020 PO3947681744	LGE	4	40 BRN	SP	P	ED,ID	BD	5/26/2065	
2020 PO3949481730	LGE	3	45 BRN	SP	CCA		V	5/27/2065	
2020 PO3947281724	LGE	3	45 BRN	SP	P	ED,ID	BD	5/28/2065	
2020 PO3946281731	LGE	4	45 BRN	SP	CRE	ED,ID	BD	5/29/2065	
2020 PO3945281705	LGE	3	45 BRN	SP	CCA		V	5/30/2065	
2020 PO1876639913	ODP	5	35 KOP	SP	S		V	5/31/2065	
2020 PO1859839903	ODP	4	45 KOP	SP	S		V	6/1/2065	
2020 PO1884740147	ODP	6	30 KOP	SP	S		V	6/2/2065	
2020 PO1221333576	ODP	4	45 BRN	SP	CCA		V	6/3/2065	
2020 PO1216233661	ODP	2	50 BRN	SP	CCA		V	6/4/2065	
2020 PO1209533674	F	4	40 BRN	SP	CRE		V	6/5/2065	
2020 PO5087109309	F	3	40 ACE	SP	P		V	6/6/2065	
2020 PO5082609193	F	4	40 ACE	SP	CRE		V	6/7/2065	
2020 PO5146509208	KU	4	40 ACE	SP	P		V	6/8/2065	
2020 PO5141009058	F	4	40 ACE	SP	CRE		V	6/9/2065	
2020 PO4745489174	F	3	45 BRN	SP	S		V	6/10/2065	
2020 PO4746489157	F	3	45 BRN	SP	CCA		V	6/11/2065	
2020 PO4746189162	F	3	45 BRN	SP	CCA		V	6/12/2065	
2020 PO5077110832	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX	6/13/2065
2020 PO5084410802	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX	6/14/2065
2020 PO5134910583	F	4	40 ACE	SP	P		V	6/15/2065	

Business Use

2020 PO5180310092	F	4	40 ACE	SP	P		V	6/16/2065
2020 PO5173009897	F	4	40 ACE	SP	P		V	6/17/2065
2020 PO5178010033	F	4	40 ACE	SP	P		V	6/18/2065
2020 PO5166510149	F	4	40 ACE	SP	CRE		V	6/19/2065
2020 PO5144610004	F	4	40 ACE	SP	P		V	6/20/2065
2020 PO5146910078	F	4	40 ACE	SP	P		V	6/21/2065
2020 PO5143609866	F	4	40 ACE	SP	P		V	6/22/2065
2020 PO4306502210	LGE	3	45 BRO	SP	P	ED,ID	T	6/23/2065
2020 PO4291602104	LGE	3	45 BRO	SP	P	ED,ID	T	6/24/2065
2020 PO4274602091	LGE	3	45 BRO	SP	P	ED,ID	T	6/25/2065
2020 PO4718288927-A	LGE	4	40E BRO	SP	CRE	ED,ID	BD	6/26/2065
2020 PO4718288927	LGE	3	50 BRO	SP	CCA		V	6/27/2065
2020 PO5125510281	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX PX	6/28/2065
2020 PO5155610174	KU	4	40 ACE	SP	P		V	6/29/2065
2020 PO0755312392	KU	6	30 UNK	SP	CRE	ED,ID	TD	6/30/2065
2020 PO0760812425	KU	4	45 UNK	SP	CRE	ED,ID,SRS	TD	7/1/2065
2020 PO0775312602	KU	6	30 UNK	SP	CRE	ED,ID	TD	7/2/2065
2020 PO0767112292	KU	3	50 BRN	SP	CRE	ED,ID,SRS	TD	7/3/2065
2020 PO0759512249	KU	6	30 BRN	SP	CCA		V	7/4/2065
2020 PO0788412114	KU	4	45 KOP	SP	CRE		V	7/5/2065
2020 PO0801712013	KU	4	45 KOP	SP	CRE	ED,ID	TD	7/6/2065
2020 PO0791411813	KU	4	40 KOP	SP	CRE		V	7/7/2065
2020 PO0807611957	KU	4	40 BRN	SP	CRE	ED,ID	TD	7/8/2065
2020 PO0814611908	KU	4	40 BRN	SP	CRE	ED,ID	TD	7/9/2065
2020 PO0826711915	KU	6	30 BRN	SP	CRE	ED,ID	TD	7/10/2065
2020 PO0833611740	KU	4	40 UNK	SP	CRE	ED,ID	TD	7/11/2065
2020 PO0832611427	KU	6	30 UNK	SP	CRE	ED,ID	TD	7/12/2065
2020 PO0809311632	KU	6	30 BRN	SP	CCA		V	7/13/2065
2020 PO0827411450	KU	6	30 KOP	SP	CCA		V	7/14/2065
2020 PO0825311646	KU	5	35 BRN	SP	CRE		V	7/15/2065
2020 PO0831311559	KU	4	40 BRN	SP	CRE		V	7/16/2065
2020 PO0868611557	KU	6	30 BRN	SP	CCA		V	7/17/2065
2020 PO0882011558	KU	6	30 KOP	SP	CRE		V	7/18/2065
2020 PO0887611628	KU	6	30 BRN	SP	CCA		V	7/19/2065
2020 PO0879911478	KU	6	30 BRN	SP	CCA		V	7/20/2065
2020 PO0888911469	KU	5	35 BRN	SP	CCA		V	7/21/2065
2020 PO0850711591	KU	4	40 KOP	SP	CRE	ED,ID,SRS	TD	7/22/2065
2020 PO0842811567	F	4	40 KOP	SP	CRE		V	7/23/2065
2020 PO0873511411	KU	4	40 BRN	SP	CCA		V	7/24/2065
2020 PO0890311266	KU	5	35 UNK	SP	CRE	ED,ID	TD	7/25/2065
2020 PO0907411075	KU	4	40 UNK	SP	CRE	ED,ID,SRS	TD	7/26/2065
2020 PO2835834179	KU	5	35 BRN	SP	CRE	ED,HH,ID	BX PX	7/27/2065
2020 PO2310131448	KU	4	40 BRN	SP	CRE		V	7/28/2065
2020 PO2166729557	KU	4	40 BRN	SP	CRE	ED,ID,IP,MD	TD	7/29/2065
2020 PO2203929703	KU	4	40 BRN	SP	CRE	ED,ID	TD	7/30/2065
2020 PO3935782618	F	4	35 BRN	SP	CRE		V	7/31/2065
2020 PO3936182626	F	4	40 BRN	SP	CRE		V	8/1/2065

2020 PO0594516856	KU	5	35 BRO	SP	CRE	ID	BD		8/2/2065
2020 PO2242429858	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		8/3/2065
2020 PO2278730003	KU	4	45 BRN	SP	CCA		V		8/4/2065
2020 PO2288230881	KU	4	45 BRN	SP	CCA		V		8/5/2065
2020 PO2277030571	KU	3	50 BRN	SP	CCA		V		8/6/2065
2020 PO2269830373	KU	3	50 BRN	SP	CCA		V		8/7/2065
2020 PO2319932507	KU	5	35 BRN	SP	CRE	ED,HH,ID	X	RP1	8/8/2065
2020 PO2341632357	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		8/9/2065
2020 PO2347432275	KU	4	40 BRN	SP	CRE	ID	BD		8/10/2065
2020 PO2889633806	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD		8/11/2065
2020 PO6411904358	KU	3	50 XXX	SP	CRE	ED,ID	TD		8/12/2065
2020 PO6397604229	KU	5	35 BRN	SP	CRE	ED,ID	TD		8/13/2065
2020 PO6392804163	F	4	40 BRN	SP	CRE		V		8/14/2065
2020 PO6440303771	F	4	40 BRN	SP	CRE		V		8/15/2065
2020 PO6426703783	F	5	40 BRN	SP	CRE		V		8/16/2065
2020 PO3936582635	F	4	40 BRN	SP	P		V		8/17/2065
2020 PO7133502484	KU	4	40 BRN	SP	CRE	ED,ID	TD		8/18/2065
2020 PO7172102729	KU	4	40 BRN	SP	CRE	ED,ID	TD		8/19/2065
2020 PO7201102828	KU	4	40 XXX	SP	CRE	RB	X	RP1	8/20/2065
2020 PO7200702732	KU	4	40 XXX	SP	CRE	RB	X	RP1	8/21/2065
2020 PO7225102910	KU	5	35 XXX	SP	CRE	ED,ID	TD		8/22/2065
2020 PO7267303068	KU	5	35 BRN	SP	CRE	ED,ID	TD		8/23/2065
2020 PO7281303109	KU	5	35 BRN	SP	CRE	ID	BX	RP1	8/24/2065
2020 PO7324303271	KU	4	40 BRN	SP	CRE	ED,ID	TD		8/25/2065
2020 PO7323903291	KU	4	40 BRN	SP	CRE	ED,ID	TD		8/26/2065
2020 PO7338703317	KU	4	40 XXX	SP	CRE	ED,ID	TD		8/27/2065
2020 PO7365803374	KU	4	40 XXX	SP	CRE	ED,ID	TD		8/28/2065
2020 7398103475b	KU	4	40 XXX	SP	CRE	RB	X	RP1	8/29/2065
2020 7398103475a	KU	6	30 XXX	SP	CCA		V		8/30/2065
2020 PO7390403396	KU	6	30 XXX	SP	CCA		V		8/31/2065
2020 PO7398103475	KU	4	40 XXX	SP	CRE	ED,ID	TD		9/1/2065
2020 PO7611122973	KU	4	40 XXX	SP	CRE	ID,IP	BD		9/2/2065
2020 PO1156935212	ODP	4	40 XXX	SP	S		V		9/3/2065
2020 PO3410939576	F	3	45 ACE	SP	P		V		9/4/2065
2020 PO3405939416	KU	5	35 ACE	SP	CCA		V		9/5/2065
2020 PO3432339402	F	5	35 ACE	SP	P	ED,ID	V		9/6/2065
2020 PO3433039473	F	4	40 ACE	SP	CRE	ED,ID	V		9/7/2065
2020 PO3449939467	F	4	40 ACE	SP	CRE	ED,ID	V		9/8/2065
2020 PO3468339464	F	4	40 ACE	SP	CRE	ED,ID,IP	V		9/9/2065
2020 PO4321802276-A	KU	4	35 BRO	SP	CRE	ED,ID,IP	TD		9/10/2065
2020 PO4313702396	F	4	40 BRO	SP	CRE		V		9/11/2065
2020 PO4301102285	F	4	40 BRO	SP	CRE		V		9/12/2065
2020 PO3484139461	F	4	40 ACE	SP	CRE	ED,ID	V		9/13/2065
2020 PO3488738995	KU	5	35 ACE	SP	CCA		V		9/14/2065
2020 PO3451438811	KU	4	40 ACE	SP	CCA		V		9/15/2065
2020 PO3228049819	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		9/16/2065
2020 PO3209149647	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD		9/17/2065

2020 PO3225649742	KU	4	40 ACE	SP	CRE	ED,ID	TD	9/18/2065
2020 PO3221349703	F	4	40 ACE	SP	CRE		V	9/19/2065
2020 PO4067601061	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	9/20/2065
2020 PO3232149644	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	9/21/2065
2020 PO4272701817	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/22/2065
2020 PO3223549383	KU	4	45 ACE	SP	CRE	ED,ID	TD	9/23/2065
2020 PO3240149687	KU	3	45 ACE	SP	CCA		V	9/24/2065
2020 PO4260101740	KU	4	40 BRO	SP	CRE	ID,IP	BD	9/25/2065
2020 PO4249501985	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/26/2065
2020 PO5576145662	KU	3	45 XXX	SP	CCA		V	9/27/2065
2020 PO3189350793	F	3	45 ACE	SP	CCA		V	9/28/2065
2020 PO3242551311	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	9/29/2065
2020 PO4246702039	F	4	40 BRO	SP	CCA		V	9/30/2065
2020 PO4264802126	F	4	40 BRO	SP	CRE		V	10/1/2065
2020 PO7877303161	KU	4	40 XXX	SP	CRE	ED,ID	TD	10/2/2065
2020 PO7960603295	KU	5	35 XXX	SP	CRE	ED,ID	TD	10/3/2065
2020 PO7982803540	KU	5	35 XXX	SP	CRE	ED,ID	TD	10/4/2065
2020 7999903724a	KU	5	30 XXX	SP	CRE	ED,ID	TD	10/5/2065
2020 PO7999903724	KU	5	35 XXX	SP	CRE	ED,ID	TD	10/6/2065
2020 8013704161b	KU	6	30 XXX	SP	CRE	ED,ID	TD	10/7/2065
2020 PO8006603935	KU	4	40 XXX	SP	CRE	ED,ID	TD	10/8/2065
2020 PO8013704161	KU	4	40 XXX	SP	CRE	ED,ID	TD	10/9/2065
2020 8013704161a	KU	6	30 BRN	SP	CRE	ED,ID	TD	10/10/2065
2020 PO8027404233	KU	6	30 BRN	SP	CRE	ED,ID	TD	10/11/2065
2020 PO8028104660	KU	6	30 BRN	SP	CCA		V	10/12/2065
2020 PO8026504539	KU	4	40 BRN	SP	CRE	ED,ID	TD	10/13/2065
2020 PO8035104704	KU	4	40 BRN	SP	CRE	ED,ID	TD	10/14/2065
2020 PO8030904813	KU	6	30 XXX	SP	CRE	ED,ID	TD	10/15/2065
2020 PO8049304900	KU	5	35 XXX	SP	CRE	ED,ID	TD	10/16/2065
2020 PO8066905155	KU	4	40 BRN	SP	CRE	ED,ID	TD	10/17/2065
2020 PO7375392073	KU	1	80 BRO	SP	CRE		V	10/18/2065
2020 PO7368892135	F	4	40 BRO	SP	CRE		V	10/19/2065
2020 PO7361392205	KU	2	70 BRO	SP	CRE		V	10/20/2065
2020 PO7354292217	KU	6	40 BRO	SP	CCA		V	10/21/2065
2020 PO7354492271	F	5	35 BRO	SP	CRE		V	10/22/2065
2020 PO7347192340	F	5	35 BRO	SP	CRE		V	10/23/2065
2020 PO7342592386	KU	2	70 BRO	SP	CRE		V	10/24/2065
2020 PO7338992430	F	3	40 BRO	SP	CRE		V	10/25/2065
2020 PO7338992548	KU	4	40 BRO	SP	CRE	ED,ID,IP,MD	TD	10/26/2065
2020 PO6921994428	KU	6	30 BRN	SP	CRE	ED,ID	TD	10/27/2065
2020 PO3561941596	KU	4	40 ACE	SP	P	ED	T	10/28/2065
2020 PO4785930934	KU	5	35 BRO	SP	CRE	ID,IP	TD	10/29/2065
2020 PO8938623987	KU	4	45 UNK	SP	CRE	ED,ID,SRS	TD	10/30/2065
2020 PO8965923651	KU	6	30 UNK	SP	CRE	ED,ID,SRS	TD	10/31/2065
2020 PO8917523935	KU	4	40 UNK	SP	CRE	ID	TD	11/1/2065
2020 PO8954423775	KU	4	45 UNK	SP	CRE	ID	TD	11/2/2065
2020 PO8963123693	KU	6	30 BRN	SP	CCA		V	11/3/2065

2020 PO8941823510	KU	4	40 UNK	SP	CRE	ID	TD	11/4/2065
2020 PO8930323711	KU	4	40 UNK	SP	CRE	ID	TD	11/5/2065
2020 PO8948223316	KU	4	40 OTH	SP	CRE	ID	TD	11/6/2065
2020 PO8955123376	KU	4	40 OTH	SP	CRE	ID	TD	11/7/2065
2020 PO6938494177	KU	4	40 BRN	SP	CRE	ED,ID	BD	11/8/2065
2020 PO6935094204	KU	4	40 BRN	SP	CRE	ED,ID	BD	11/9/2065
2020 PO6039113224	KU	2	50 BRO	SP	CRE	ID	BD	11/10/2065
2020 PO6942994285	KU	4	40 BRN	SP	CRE	ED,ID	TD	11/11/2065
2020 PO4768331185	KU	3	40 BRO	SP	CRE	ID,IP	TD	11/12/2065
2020 PO4775231156	KU	5	35 BRO	SP	CRE	ID,IP	TD	11/13/2065
2020 PO4782830983-A	KU	5	35 BRO	SP	CRE	ID,IP	TD	11/14/2065
2020 PO6967394388	KU	4	40 BRN	SP	CRE	ED,ID	TD	11/15/2065
2020 PO6954894201	KU	6	30 BRN	SP	A	ED,ID	TD	11/16/2065
2020 PO6946094118	KU	4	40 BRN	SP	CCA		V	11/17/2065
2020 PO7354789787	KU	4	45 BRO	SP	CRE	ED,ID	TD	11/18/2065
2020 PO7365689584	KU	4	40 BRO	SP	CRE		V	11/19/2065
2020 PO7282189264	F	5	35 BRO	SP	CRE		V	11/20/2065
2020 PO7375989388	KU	4	45 BRO	SP	CRE		V	11/21/2065
2020 PO7349190101	KU	3	45 BRO	SP	CRE		V	11/22/2065
2020 PO7345390132	KU	2	65 BRO	SP	CRE		V	11/23/2065
2020 PO7362990308	KU	2	65 BRO	SP	CRE		V	11/24/2065
2020 PO7381090489	KU	2	70 BRO	SP	CRE		V	11/25/2065
2020 PO7399890681	KU	1	80 BRO	SP	CRE		V	11/26/2065
2020 PO7420290910	KU	1	75 BRO	SP	CCA		V	11/27/2065
2020 PO3207437882	KU	4	40 BRN	SP	CRE	ID	BD	11/28/2065
2020 PO7344389981	KU	4	45 BRO	SP	CRE	ED,ID	TD	11/29/2065
2020 PO6956194033	KU	4	40 BRN	SP	CRE	ED,ID	TD	11/30/2065
2020 PO3107438727	KU	5	35 BRN	SP	CRE	ED,ID,MD,SRC	TD	12/1/2065
2020 PO3092338850	KU	5	35 BRN	SP	CRE	ID,IP	BD	12/2/2065
2020 PO4782830983	KU	3	45 BRO	SP	CRE	ID,IP	TD	12/3/2065
2020 PO6980794383	KU	5	35 BRN	SP	CRE	ED,ID	BD	12/4/2065
2020 8879624106A	KU	6	30 UNK	SP	CRE	ED,ID,SRC	TX	RR 12/5/2065
2020 A	KU	6	30 KOP	SP	CCA		V	12/6/2065
2020 PO8886024028	F	4	40 OTH	SP	P	ED	BD	12/7/2065
2020 PO8879624106	KU	5	35 UNK	SP	CRE	ED,ID,SRS	TD	12/8/2065
2020 PO8885123955	KU	5	35 OTH	SP	CRE	ID	TD	12/9/2065
2020 PO8923424022	KU	5	35 UNK	SP	CRE	ID	TD	12/10/2065
2020 PO8897824029	KU	6	30 OTH	SP	CCA		V	12/11/2065
2020 PO8917124067	F	4	35 UNK	SP	P	ED,ID	BD	12/12/2065
2020 PO8891424151	KU	5	35 UNK	SP	CRE	ID	TD	12/13/2065
2020 PO2285924411	ODP	6	35 XXX	SP	CRE	EP,ID,RB	X	RP2 12/14/2065
2020 PO6973794303	KU	5	35 BRN	SP	CRE	ED,ID	BD	12/15/2065
2020 PO3125338093	KU	4	40 BRN	SP	CRE	ID	BD	12/16/2065
2020 PO3156838245	KU	5	45 BRN	SP	CRE	ED,ID,SRC	TD	12/17/2065
2020 PO3203037843	KU	4	40 BRN	SP	CCA		V	12/18/2065
2020 PO4810731093	KU	3	45 BRO	SP	CRE	ID,IP	BD	12/19/2065
2020 PO4834931184	F	2	60 BRO	SP	P		V	12/20/2065

2020 PO4830931268	F	3	45E	BRO	SP	CRE	HH	VX	RP2	12/21/2065
2020 PO4832731313	F	3	45	BRO	SP	P		V		12/22/2065
2020 PO4835731458	KU	3	45	BRO	SP	CCA	IP	BD		12/23/2065
2020 PO6965393956	KU	4	40	BRN	SP	CRE	ED,ID	BD		12/24/2065
2020 PO6983894303	KU	5	35	BRN	SP	CRE	ED,ID	BD		12/25/2065
2020 PO6988394331	KU	5	30	BRN	SP	CRE	ED,HH,ID,RB	X	PX	12/26/2065
2020 PO4838931488	KU	4	45	BRO	SP	CRE	ID	BD		12/27/2065
2020 PO4844531643	KU	3	50	BRO	SP	P	ID	TD		12/28/2065
2020 PO4829631699	KU	5	35	BRO	SP	CRE	ID,IP	BD		12/29/2065
2020 PO4833531865	KU	5	30	BRO	SP	CRE	ID	BD		12/30/2065
2020 PO4839231830	KU	5	35	BRO	SP	CRE	ID,IP	BD		12/31/2065
2020 PO2297724285	ODP	6	35	XXX	SP	CRE	ID	BD		1/1/2066
2020 PO2301924347	F	4	40	XXX	SP	P		V		1/2/2066
2020 PO2301924347A	ODP	6	30	XXX	SP	CRE	ID	BD		1/3/2066
2020 PO2320424258	F	4	40	XXX	SP	A		V		1/4/2066
2020 PO2329024216	ODP	4	40	XXX	SP	CRE	ID	TD		1/5/2066
2020 PO2325724144	ODP	4	45	XXX	SP	CRE	ID	TD		1/6/2066
2020 PO2338124058	ODP	4	40	XXX	SP	CRE	ED,ID	TD		1/7/2066
2020 PO2365723630	ODP	4	40	XXX	SP	CRE	ID	BD		1/8/2066
2020 PO2382823383	ODP	4	45	XXX	SP	CRE	ID	TD		1/9/2066
2020 PO7046721374	KU	4	40	XXX	SP	CRE	ID	TD		1/10/2066
2020 PO7038721410	KU	6	30	XXX	SP	CRE	ID	TD		1/11/2066
2020 PO7041121369	KU	4	40	XXX	SP	CRE	ID	BD		1/12/2066
2020 PO2071645371	KU	4	45	BRN	SP	CCA		V		1/13/2066
2020 PO7063321576	KU	4	40	XXX	SP	CRE	HH,RB	X	PX	1/14/2066
2020 PO2767934658	KU	4	40	BRN	SP	CCA		V		1/15/2066
2020 PO7063321576A	KU	6	30	XXX	SP	CRE	ID	BD		1/16/2066
2020 PO7088121627	KU	6	30	BRN	SP	CRE	ID	TD		1/17/2066
2020 PO7098021603	KU	6	30	BRN	SP	CCA		V		1/18/2066
2020 PO7089721471	KU	5	30	XXX	SP	CRE	ID,IP	TD		1/19/2066
2020 PO7082221459	KU	5	30	XXX	SP	CRE	ID	TD		1/20/2066
2020 PO7083021242	KU	4	35	XXX	SP	CRE	ID	TD		1/21/2066
2020 PO7073321441	KU	4	35	XXX	SP	CRE	ID	TD		1/22/2066
2020 PO7069421366	KU	5	35	XXX	SP	CRE	ID	TD		1/23/2066
2020 PO7058521407	KU	4	40	XXX	SP	CRE	ID	TD		1/24/2066
2020 PO6973620755	KU	6	30	XXX	SP	CCA		V		1/25/2066
2020 PO6839995140	KU	6	30	BRO	SP	P	ED,ID,IP	TD		1/26/2066
2020 PO9088720865	F	4	40	UNK	SP	P		B		1/27/2066
2020 PO9064620807	KU	6	30	BRN	SP	CCA		V		1/28/2066
2020 PO9050121040	KU	6	30	BRN	SP	CCA		V		1/29/2066
2020 PO9025321052	KU	6	30	BRN	SP	CCA		V		1/30/2066
2020 PO9082720922	KU	3	45	BRN	SP	CCA		V		1/31/2066
2020 PO7622604096	KU	5	35	XXX	SP	CRE	ED,ID,IP	TD		2/1/2066
2020 PO7638604325	KU	4	40	XXX	SP	CCA		V		2/2/2066
2020 PO7637604541	KU	4	40	XXX	SP	CCA		V		2/3/2066
2020 PO9036821201	KU	5	35	BRN	SP	CCA		V		2/4/2066
2020 PO9072421028	KU	4	40	UNK	SP	CRE	ID	TD		2/5/2066

2020 PO6895295478	KU	4	45 BRN	SP	CRE	ED,ID	TD	2/6/2066
2020 PO6907295480	KU	6	30 BRN	SP	CRE	ED,ID	TD	2/7/2066
2020 PO6926495628	KU	2	70 BRN	SP	CRE		V	2/8/2066
2020 PO6928195606	KU	5	35 BRN	SP	CRE	ED,ID	BD	2/9/2066
2020 PO6931695623	KU	4	40 BRN	SP	CRE	ED,ID	BD	2/10/2066
2020 PO2710834899	KU	4	40 BRN	SP	CRE	ED,ID,IP,SRS	TD	2/11/2066
2020 PO7174791708	KU	5	30 BRO	SP	CRE	ED,ID	TD	2/12/2066
2020 PO7157991635	KU	5	35 BRO	SP	CRE	ED,ID	TD	2/13/2066
2020 PO9058621179	KU	5	35 UNK	SP	CRE	ID	TD	2/14/2066
2020 PO7223002482	KU	4	40 XXX	SP	CCA		V	2/15/2066
2020 PO7231602412	KU	6	30 XXX	SP	CRE		V	2/16/2066
2020 PO7245902396	KU	6	30 XXX	SP	CCA		V	2/17/2066
2020 7070401901a	KU	5	30 BRN	SP	S		V	2/18/2066
2020 PO7070401901	KU	5	40 XXX	SP	CRE	ED,ID	TD	2/19/2066
2020 PO2712635017	KU	6	30 BRN	SP	CRE		V	2/20/2066
2020 PO2768134813	KU	4	40 BRN	SP	CRE	ID,IP	BD	2/21/2066
2020 PO7236902461	KU	4	40 XXX	SP	CCA		V	2/22/2066
2020 PO7246102279	KU	6	30 XXX	SP	CCA		V	2/23/2066
2020 PO7268402495	KU	4	40 XXX	SP	CCA	ED	T	2/24/2066
2020 PO7247002482	KU	4	40 XXX	SP	CCA		V	2/25/2066
2020 PO7270902433	KU	5	35 XXX	SP	CCA		V	2/26/2066
2020 PO2747335015	KU	5	35 BRN	SP	CRE	ED,ID,IP,MD,SRC	TD	2/27/2066
2020 PO2729235191	KU	4	40 BRN	SP	CRE	ID	BD	2/28/2066
2020 9033521654A	KU	5	35 BRN	SP	CRE	ID	TD	3/1/2066
2020 9033521654B	KU	6	30 BRN	SP	CRE	ID	TD	3/2/2066
2020 PO9027821913	KU	4	40 UNK	SP	CRE	ED,ID,IP	TX	RR 3/3/2066
2020 PO9023622037	KU	4	40 INP	SP	CRE	ID	TD	3/4/2066
2020 PO9056221414	KU	5	35 UNK	SP	CRE	ID	TD	3/5/2066
2020 PO9033521654	KU	4	40 UNK	SP	CRE	ID	TD	3/6/2066
2020 PO9052222261	KU	4	40 BRN	SP	CCA		V	3/7/2066
2020 PO9039921502	KU	4	40 UNK	SP	CRE	ID	TD	3/8/2066
2020 PO9007122246	KU	6	30 UNK	SP	CRE	ID	TD	3/9/2066
2020 PO9051421438	KU	4	40 BRN	SP	CCA		V	3/10/2066
2020 PO9036521834	KU	5	30 UNK	SP	CRE	ID	TD	3/11/2066
2020 PO9021222577	KU	5	35 UNK	SP	CRE	ED,ID,SRS	TD	3/12/2066
2020 PO9026421601	KU	6	30 UNK	SP	CRE	ID	TD	3/13/2066
2020 PO9018722766	KU	4	35 UNK	SP	CRE	ED,ID,SRS	TD	3/14/2066
2020 PO9032622449	KU	5	35 UNK	SP	CRE	ID	TD	3/15/2066
2020 PO9019922158	KU	4	40 UNK	SP	CRE	ID	TD	3/16/2066
2020 PO9040121730	KU	6	30 INP	SP	CRE	ID	TD	3/17/2066
2020 PO9030021808	KU	4	40 UNK	SP	CRE	ID	TD	3/18/2066
2020 PO9021021832	KU	6	30 KOP	SP	CCA		V	3/19/2066
2020 PO9017122278	KU	5	35 UNK	SP	CRE	ED,HH,ID	X	PX 3/20/2066
2020 PO9023322395	KU	4	40 ACW	SP	CRE	ED,ID	TD	3/21/2066
2020 PO6821594193	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	3/22/2066
2020 PO7157702328	KU	6	30 XXX	SP	CCA		V	3/23/2066
2020 PO7149602252	KU	4	40 XXX	SP	CRE	ED,ID	TD	3/24/2066

2020 PO4743988599	LGE	4	35 BRN	SP	CRE	ED,HH,ID	BX	RP2	3/25/2066
2020 PO7192202618	F	6	30 XXX	SP	CRE		V		3/26/2066
2020 PO7192002685	KU	6	30 XXX	SP	CRE	ED,ID	TD		3/27/2066
2020 PO7200002686	KU	6	30 XXX	SP	CRE	ED,ID	TD		3/28/2066
2020 PO7206902741	F	4	40 XXX	SP	CRE		V		3/29/2066
2020 PO6874094525	KU	5	35 BRN	SP	CRE	ED,ID	TD		3/30/2066
2020 PO6863794203	KU	5	35 BRN	SP	CRE	ED,HH,ID	VX	PX	3/31/2066
2020 PO7221802765	F	4	40 XXX	SP	CRE		V		4/1/2066
2020 PO7221002710	F	4	40 BRN	SP	CRE		V		4/2/2066
2020 PO7231702706	F	4	40 BRN	SP	CRE		V		4/3/2066
2020 PO7234702805	F	4	40 BRN	SP	CRE		V		4/4/2066
2020 PO7241502792	KU	4	40 BRN	SP	CRE		V		4/5/2066
2020 PO6849393913	KU	4	40 BRN	SP	CRE	ED,ID,RB	TX	RR	4/6/2066
2020 PO7280902617	KU	5	35 BRN	SP	CCA		V		4/7/2066
2020 PO7270402584	KU	4	40 BRN	SP	CCA		V		4/8/2066
2020 PO7250402606	F	4	40 BRN	SP	CRE		V		4/9/2066
2020 PO7239102584	KU	5	35 XXX	SP	CRE	ED,ID	TD		4/10/2066
2020 PO4941913263	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		4/11/2066
2020 PO4761188969	LGE	4	40 BRO	SP	CRE	ED,ID	TD		4/12/2066
2020 PO4765688990	LGE	4	40 BRO	SP	CRE	ED,ID	BD		4/13/2066
2020 PO4937413466	F	4	40 ACE	SP	P		V		4/14/2066
2020 PO4921913356	KU	3	45 ACE	SP	CCA		V		4/15/2066
2020 PO4927913636	F	6	30 ACE	SP	CRE		V		4/16/2066
2020 PO4917813556	KU	6	30 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	X	RP1	4/17/2066
2020 PO4742888596	LGE	4	40 BRN	SP	CRE	ED,ID	BD		4/18/2066
2020 PO4180511328	KU	4	40 BRO	SP	CRE	ID	BD		4/19/2066
2020 PO4444301605	KU	4	40 BRN	SP	CRE	ED,ID	TD		4/20/2066
2020 PO4762488976	LGE	4	40 BRO	SP	CRE	ED,ID	BD		4/21/2066
2020 PO4763788981	LGE	4	40 BRO	SP	CRE	ED,ID	BD		4/22/2066
2020 PO4765088988	LGE	3	45 BRO	SP	CCA		V		4/23/2066
2020 PO4925113429	F	4	40 ACE	SP	CRE	ED,ID,IP	V		4/24/2066
2020 PO4926013519	F	3	45 ACE	SP	P		V		4/25/2066
2020 PO4915413568	F	3	45 ACE	SP	P		V		4/26/2066
2020 PO4469700712	KU	4	40 BRN	SP	CRE	ED,ID,IP	TX	RR	4/27/2066
2020 PO7161402124	KU	5	45 BRN	SP	CRE	ED,ID	TD		4/28/2066
2020 PO7166702079	KU	6	30 BRN	SP	CCA		V		4/29/2066
2020 PO6816293936	KU	6	30 BRO	SP	P	ED,ID	TD		4/30/2066
2020 PO6941695614	KU	4	45 BRN	SP	CRE	ED,ID	BD		5/1/2066
2020 PO2720035276	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD		5/2/2066
2020 PO2733635408	KU	4	40 BRN	SP	CCA		V		5/3/2066
2020 PO3926836688	KU	4	40 BRO	SP	P	ED	TD		5/4/2066
2020 PO3929336732	KU	4	40 BRO	SP	CCA		V		5/5/2066
2020 PO3937936630-A	KU	5	30E BRO	SP	CRE	ID	TD		5/6/2066
2020 PO6956795613	KU	1	75 BRN	SP	CCA		V		5/7/2066
2020 PO6956595577	KU	4	40 BRN	SP	A	ED,ID	BD		5/8/2066
2020 PO6859895583	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		5/9/2066
2020 PO6861095673	KU	4	45 BRO	SP	CRE	ED,ID	TD		5/10/2066

2020 PO6861595705	KU	2	70 BRO	SP	CRE		V	5/11/2066
2020 PO7299402471	KU	3	45 XXX	SP	CCA		V	5/12/2066
2020 PO7314702455	KU	3	45 XXX	SP	CCA		V	5/13/2066
2020 PO7324702806	KU	4	40 XXX	SP	CCA		V	5/14/2066
2020 PO6959095434	KU	4	40 BRN	SP	CRE	ED,ID	TD	5/15/2066
2020 PO7143101907	KU	3	50 KOP	SP	CRE	ED,ID	TD	5/16/2066
2020 PO2748335544	KU	4	40 BRN	SP	CRE	ED,ID,IP,MD,SRC	TD	5/17/2066
2020 PO2713935342	KU	6	30 BRN	SP	CCA		V	5/18/2066
2020 PO2760035654	KU	4	40 BRN	SP	CRE	ID,IP	TD	5/19/2066
2020 PO4977608801	F	4	40 BRO	SP	CRE		V	5/20/2066
2020 PO7357484400	KU	5	35 BRN	SP	CRE	ED,ID	TD	5/21/2066
2020 PO7346684624	KU	5	35 BRN	SP	CRE	ED,ID	TD	5/22/2066
2020 PO7336584832	KU	4	45 BRN	SP	CRE	ED,ID	TD	5/23/2066
2020 PO7350384399	KU	6	30 BRN	SP	CCA		V	5/24/2066
2020 PO4978508949	KU	6	30 BRO	SP	CRE		V	5/25/2066
2020 PO7341684358	KU	3	50 BRN	SP	CRE		V	5/26/2066
2020 PO7338284346	KU	3	55 BRN	SP	CRE	ED,ID	BD	5/27/2066
2020 PO7327984300	KU	4	45 BRN	SP	CRE	ED,ID	BD	5/28/2066
2020 PO7327984300-A	KU	4	40 BRN	SP	S		V	5/29/2066
2020 PO4953508835	KU	6	30 BRO	SP	CRE		V	5/30/2066
2020 PO4969308841a	KU	5	30 BRO	SP	CCA		V	5/31/2066
2020 PO7320184687	KU	4	45 BRN	SP	CRE		V	6/1/2066
2020 PO7307784586	KU	4	40 BRN	SP	CCA		V	6/2/2066
2020 PO7305184564	KU	5	35 BRN	SP	CRE	ED,ID	TD	6/3/2066
2020 PO7276184649	KU	5	35 BRN	SP	S		V	6/4/2066
2020 PO7289184622	KU	4	40 BRN	SP	CRE	ED,ID	TX	RR 6/5/2066
2020 PO4980508868	KU	5	35 BRO	SP	CRE	ID	TD	6/6/2066
2020 PO4985308775	KU	6	30 BRO	SP	CCA		V	6/7/2066
2020 PO4974808728	KU	5	35 BRO	SP	CRE	ID	TD	6/8/2066
2020 PO4969308841	KU	4	40 BRO	SP	CRE	ID	TD	6/9/2066
2020 PO4964208945	KU	4	40 BRO	SP	CRE	ID	TD	6/10/2066
2020 PO4969709006	KU	6	30 BRO	SP	CCA		V	6/11/2066
2020 PO4948808977	KU	6	30 BRO	SP	CCA		V	6/12/2066
2020 PO4949209191	KU	5	30 BRO	SP	CRE	ID	TD	6/13/2066
2020 PO4948509096	KU	4	40 BRO	SP	CRE	ID	TD	6/14/2066
2020 PO4952109002	KU	4	40 BRO	SP	CRE	ID	TD	6/15/2066
2020 PO3877783035	LGE	4	35 BRO	SP	CRE	ED,ID	TD	6/16/2066
2020 PO3878683034	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/17/2066
2020 PO3884783028	LGE	4	35 BRO	SP	P	ED,ID	TD	6/18/2066
2020 PO2650453742	KU	4	40 BRO	SP	P	ED	T	6/19/2066
2020 PO0900634073	ODP	4	45 XXX	SP	CCA		V	6/20/2066
2020 PO0920134326	ODP	4	45 XXX	SP	CCA		V	6/21/2066
2020 PO0944734409	ODP	4	45 XXX	SP	CCA		V	6/22/2066
2020 PO0941834537	ODP	4	40 XXX	SP	CCA		V	6/23/2066
2020 PO7243991315	F	4	45 BRN	SP	CRE		V	6/24/2066
2020 PO7233991239	F	4	45 BRN	SP	CRE		V	6/25/2066
2020 PO7200491078	F	5	35 BRN	SP	CRE		V	6/26/2066

2020 PO2590737848	KU	4	40 BRN	SP	CRE	ED,ID,IP,SR	TD	6/27/2066
2020 PO2567337818	KU	4	40 BRN	SP	CRE	ED,ID,IP,SRS	TD	6/28/2066
2020 PO2541137785	KU	4	40 BRN	SP	CRE	ID,IP	BD	6/29/2066
2020 PO4946008791	KU	5	35 BRO	SP	CRE	ID	TD	6/30/2066
2020 PO3596841400	KU	6	30 ACE	SP	CRE	ED,EP,HH,ID,IP,MD,RB	X	7/1/2066
2020 PO4934709273	KU	4	40 BRO	SP	CRE	ID	TD	7/2/2066
2020 PO4921309278	KU	6	30 BRO	SP	CCA		V	7/3/2066
2020 PO4929809539	KU	6	30 BRO	SP	CRE	ID	TD	7/4/2066
2020 PO4920309516	KU	4	40 BRO	SP	CRE	ID	TD	7/5/2066
2020 PO4903809530	KU	4	40 BRO	SP	CRE	ID	TD	7/6/2066
2020 PO4862609790	KU	4	40 BRO	SP	CRE	ID	TD	7/7/2066
2020 PO4888509596	KU	6	30 BRO	SP	CRE	ID	TD	7/8/2066
2020 PO4879309541	KU	4	45 BRO	SP	CRE	ID	TD	7/9/2066
2020 PO4850710200	KU	5	35 BRO	SP	CRE	ID	TD	7/10/2066
2020 PO4834310522	KU	4	40 BRO	SP	CRE	ID	TD	7/11/2066
2020 PO4835210348	KU	6	30 BRO	SP	CCA		V	7/12/2066
2020 PO5024807741	KU	6	30 BRO	SP	CCA		V	7/13/2066
2020 PO5007808216	KU	4	40 BRO	SP	CCA		V	7/14/2066
2020 PO5020208204	KU	4	40 BRO	SP	CRE	ID	TD	7/15/2066
2020 PO4995408490	KU	4	40 BRO	SP	CCA		V	7/16/2066
2020 PO5059407815	KU	5	35 BRO	SP	CCA		V	7/17/2066
2020 PO5048707866	KU	4	40 BRO	SP	CRE	ID	TD	7/18/2066
2020 PO3617841283	KU	6	30 ACE	SP	CRE	ED,ID	TD	7/19/2066
2020 PO7195791102	F	4	40 BRN	SP	CRE		V	7/20/2066
2020 PO3948482560	LGE	1	95 BRN	SP	A		V	7/21/2066
2020 PO3948082549	LGE	1	25 BRN	SP	A	ED,ID	BD	7/22/2066
2020 PO7186191182	F	4	35 BRN	SP	CRE		VX	7/23/2066
2020 PO3945482489	LGE	1	95 BRN	SP	A		V	7/24/2066
2020 PO3509439702	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	7/25/2066
2020 PO3945782494	LGE	1	25 BRN	SP	A	ED,ID	BD	7/26/2066
2020 PO1105832427B	ODP	5	35 XXX	SP	CCA		V	7/27/2066
2020 PO1105832427A	ODP	5	35 XXX	SP	CCA		V	7/28/2066
2020 PO1085332419	ODP	5	30 XXX	SP	CCA		V	7/29/2066
2020 PO7131191714	KU	5	35 BRN	SP	CRE	ED,ID	BD	7/30/2066
2020 PO3946582512	LGE	1	25 BRN	SP	A	ED,ID	BD	7/31/2066
2020 PO3881883031	LGE	4	35 BRO	SP	CCA		V	8/1/2066
2020 PO5055607890	KU	4	40 BRO	SP	CCA		V	8/2/2066
2020 PO3880183033	LGE	4	35 BRO	SP	CRE	ED,ID	BX	8/3/2066
2020 PO5055908021	KU	6	30 BRO	SP	CCA		V	8/4/2066
2020 PO5065707858	KU	4	40 BRO	SP	CCA		V	8/5/2066
2020 PO5079107791	KU	4	40 BRO	SP	CCA		V	8/6/2066
2020 PO5067107790	KU	6	30 BRO	SP	CCA		V	8/7/2066
2020 PO5094007828	KU	4	40 BRO	SP	CCA		V	8/8/2066
2020 PO5110407831	KU	6	30 BRO	SP	CCA		V	8/9/2066
2020 PO5054407544	KU	4	30 BRO	SP	CCA		V	8/10/2066
2020 PO5072107601	F	4	40 BRO	SP	CRE		V	8/11/2066
2020 PO5070107340	KU	6	30 BRO	SP	CCA		V	8/12/2066

2020 PO5077307521	KU	3	45 BRO	SP	CRE	ID	TD	8/13/2066	
2020 PO5083907431	F	4	40 BRO	SP	CCA		V	8/14/2066	
2020 PO5087707467	F	3	35 BRO	SP	CRE		V	8/15/2066	
2020 PO5089907548	KU	4	40 BRO	SP	CCA		V	8/16/2066	
2020 PO5098107523	KU	2	50 BRO	SP	CCA		V	8/17/2066	
2020 PO7332783872	KU	4	30 BRN	SP	CRE	ED,ID	TD	8/18/2066	
2020 PO7338983982	KU	4	45 BRN	SP	CRE	ED,ID	BD	8/19/2066	
2020 PO7343283889	KU	4	40 BRN	SP	CRE	ED,ID	BD	8/20/2066	
2020 PO3882883031	LGE	4	40 BRO	SP	CRE	ED,ID	TD	8/21/2066	
2020 PO3882183035	LGE	4	30 BRO	SP	CRE	ED,ID,IP,RB	TD	8/22/2066	
2020 PO3946982523	LGE	1	95 BRN	SP	A		V	8/23/2066	
2020 PO2613753930	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	8/24/2066	
2020 PO2632353836	KU	5	35 BRO	SP	CRE	ED,ID,RB	X	RP1	8/25/2066
2020 PO2622153886	KU	3	45 BRO	SP	P	ED	T	8/26/2066	
2020 PO2600054225	KU	4	40 BRO	SP	CRE	ID,IP,RB	TX	RR	8/27/2066
2020 PO2591454044	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	8/28/2066	
2020 PO2671353699	KU	5	35 BRO	SP	CCA		V	8/29/2066	
2020 PO2658452694	KU	4	40 BRO	SP	CCA		V	8/30/2066	
2020 PO3947382531	LGE	1	25 BRN	SP	A	ED,ID	BD	8/31/2066	
2020 PO6826293648	KU	4	40 BRN	SP	CRE	ED,ID	BD	9/1/2066	
2020 PO6823693520	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	9/2/2066	
2020 PO3500240010	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	9/3/2066	
2020 PO3948982570	LGE	1	25 BRN	SP	A	ED,ID	BD	9/4/2066	
2020 PO7330984147	KU	4	45 BRN	SP	CRE	ED,ID	BD	9/5/2066	
2020 PO6836094167	KU	4	40 BRN	SP	CRE	ED,ID	BD	9/6/2066	
2020 PO7344684221	KU	2	50 BRN	SP	CCA		V	9/7/2066	
2020 PO7352084064	KU	4	40 BRN	SP	CCA		V	9/8/2066	
2020 PO7376983564	KU	4	40 BRN	SP	CRE	ED,ID	BX	RR	9/9/2066
2020 PO7359783900	KU	5	35 BRN	SP	P	ED,ID	TD	9/10/2066	
2020 PO7363983830	KU	5	35 BRN	SP	CRE		V	9/11/2066	
2020 PO7367683748	KU	5	35 BRN	SP	CRE	ED,ID	TD	9/12/2066	
2020 PO7892276390	KU	4	45 BRO	SP	CRE	ID	BD	9/13/2066	
2020 PO5364806951	KU	6	30 BRN	SP	CRE	ED,ID	TD	9/14/2066	
2020 PO5363407028	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/15/2066	
2020 PO7922776478	KU	4	40 BRO	SP	CRE	ID	BD	9/16/2066	
2020 PO7973476627	KU	4	40 BRO	SP	CRE	ED,ID	TD	9/17/2066	
2020 PO7952376564	KU	4	40 BRO	SP	CRE	ID	BD	9/18/2066	
2020 PO7988076962	KU	4	40 BRO	SP	CRE	ED,ID	TD	9/19/2066	
2020 PO5368107349	F	4	40 XXX	SP	CRE		V	9/20/2066	
2020 PO5346906958	KU	4	40 XXX	SP	CCA		V	9/21/2066	
2020 PO1014532115	ODP	4	45 BRN	SP	CRE	ED,ID	TD	9/22/2066	
2020 PO6838594288	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/23/2066	
2020 PO1002332059	ODP	4	45 BRN	SP	CRE	ED,ID	BD	9/24/2066	
2020 PO1016932037	F	4	40 BRN	SP	CRE		V	9/25/2066	
2020 PO6849894979	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/26/2066	
2020 PO3954482791	LGE	4	35 BRO	SP	CRE	ED,ID	TD	9/27/2066	
2020 PO5457207407	KU	6	30 BRO	SP	CRE	ID	TD	9/28/2066	

2020 PO5406408126	KU	5	35 BRO	SP	CRE	ED	X	RP1	9/29/2066
2020 PO5412908043	KU	5	30 BRO	SP	CCA		V		9/30/2066
2020 PO5418707930	KU	5	30 BRO	SP	CRE	ID	TD		10/1/2066
2020 PO5471708903	KU	3	50 BRO	SP	CRE	ID	TD		10/2/2066
2020 PO5439308523a	KU	5	30 BRO	SP	CRE	ID	TD		10/3/2066
2020 PO5444508612	KU	5	30 BRO	SP	CRE		V		10/4/2066
2020 PO5442108561	F	4	40 BRO	SP	CCA		V		10/5/2066
2020 PO5439308523	KU	4	40 BRO	SP	CCA		V		10/6/2066
2020 PO5430908398	F	4	40 BRO	SP	CRE		V		10/7/2066
2020 PO5422908429	KU	3	50 BRO	SP	CRE	ID	TD		10/8/2066
2020 PO7591893609	F	4	40 BRO	SP	CRE		VX	RP1	10/9/2066
2020 PO7600293752	F	4	40 BRO	SP	CRE		V		10/10/2066
2020 PO7596893579	KU	5	30 BRO	SP	CRE	ED,ID	TD		10/11/2066
2020 PO7585593502	F	3	40 BRO	SP	CRE		V		10/12/2066
2020 PO7593693452	KU	5	30 BRO	SP	CRE	ID	BD		10/13/2066
2020 PO7544193272	KU	6	30 BRO	SP	CRE	ID	BD		10/14/2066
2020 PO7578593368	F	2	45 BRO	SP	CRE		V		10/15/2066
2020 PO7567393215	KU	5	35 BRO	SP	CRE	ED,ID	X	RP1	10/16/2066
2020 PO7569793249	F	3	45 BRO	SP	CRE		V		10/17/2066
2020 PO7556693345	F	4	40 BRO	SP	CRE		V		10/18/2066
2020 PO7545593400	F	3	40 BRO	SP	CRE		V		10/19/2066
2020 PO7534993467	F	3	40 BRO	SP	CRE		V		10/20/2066
2020 PO1718070047	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD		10/21/2066
2020 PO1711070300	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		10/22/2066
2020 PO1678570483	KU	6	30 BRN	SP	CRE	EP,ID,IP	TD		10/23/2066
2020 PO1674270294	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		10/24/2066
2020 PO1701270748	KU	4	40 BRN	SP	CRE	RB	X	RP1	10/25/2066
2020 PO1635570287	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		10/26/2066
2020 PO1616670289	KU	4	45 BRN	SP	CRE	ID	BD		10/27/2066
2020 PO0783666315	KU	4	40 BRN	SP	CRE	ID,IP	BD		10/28/2066
2020 PO0777166370	KU	4	40 BRN	SP	CRE	ID,IP	BD		10/29/2066
2020 PO0774666232	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		10/30/2066
2020 PO0780866446	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		10/31/2066
2020 PO0785266531	KU	4	40 BRN	SP	CRE	ID,IP	BD		11/1/2066
2020 PO0793866685	KU	4	40 BRN	SP	CRE	ID,IP	BD		11/2/2066
2020 PO0803466868	KU	4	40 BRN	SP	CRE	ID,IP	BD		11/3/2066
2020 PO0632060527	KU	5	35 ACW	SP	CRE	ED,ID	BD		11/4/2066
2020 PO0648260626	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		11/5/2066
2020 PO0405348553	KU	4	40 BRO	SP	CRE	ID	BD		11/6/2066
2020 PO0364348819	KU	4	45 BRO	SP	CRE	ED,ID,SRC	TD		11/7/2066
2020 PO0308349239	F	4	40 BRO	SP	CRE		V		11/8/2066
2020 PO0322649091	KU	4	45 BRO	SP	CRE	ED,ID,SRC	TD		11/9/2066
2020 PO0469753274	KU	4	40 BRO	SP	CRE	ID	BD		11/10/2066
2020 PO0427353189	KU	4	45 BRO	SP	CRE		B		11/11/2066
2020 PO0697161161	KU	6	30 ACW	SP	CRE	ED,ID	TD		11/12/2066
2020 PO0682860808	KU	4	40 ACW	SP	CRE	ED,ID	TD		11/13/2066
2020 PO0647859972	KU	6	30 ACW	SP	CRE	ED,ID	TD		11/14/2066

2020 PO0642859855	KU	5	35 ACW	SP	CRE	ED,ID,IP	TD		11/15/2066
2020 PO0544059684	KU	6	30 ACW	SP	CRE	ED,ID	TD		11/16/2066
2020 PO0559860038	KU	6	30 ACW	SP	CRE	ED,ID	BD		11/17/2066
2020 PO2924833617	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD		11/18/2066
2020 PO2941633527	KU	5	35 BRN	SP	CRE	HH,ID,RB	X	RP2	11/19/2066
2020 PO2957133446	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		11/20/2066
2020 PO2980933688	KU	4	40 BRN	SP	CRE	ED,ID	TD		11/21/2066
2020 PO2972533362	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD		11/22/2066
2020 PO3988783051	LGE	4	40 BRN	SP	CRE	ED,ID	TD		11/23/2066
2020 PO3988783043	LGE	6	25 BRN	SP	CRE		V		11/24/2066
2020 PO3989883052	LGE	4	40 BRN	SP	CRE	ED,ID	TD		11/25/2066
2020 PO3991083054	LGE	4	40 BRN	SP	CRE	ED,ID,RB	TX	RR	11/26/2066
2020 PO3992383048	LGE	6	25 BRN	SP	CRE	ED,ID	BD		11/27/2066
2020 PO3992283056	LGE	4	40 BRN	SP	CRE	ED,ID,RB	TX	RR	11/28/2066
2020 PO3934582549	LGE	4	40 BRN	SP	P	ED,ID	TD		11/29/2066
2020 PO3934982556	LGE	4	35 BRN	SP	CRE	ED,ID	BD		11/30/2066
2020 7794425226A	KU	5	35 KOP	SP	CCA		V		12/1/2066
2020 PO7825925247	KU	5	30 OTH	SP	CRE	ID	TD		12/2/2066
2020 PO7814425135	KU	6	30 OTH	SP	CRE	ID	TD		12/3/2066
2020 PO0560760153	KU	6	30 ACW	SP	CRE	ED,ID	TD		12/4/2066
2020 PO0534851593	KU	4	40 BRO	SP	CRE	ED,ID,SRC,SRS	TD		12/5/2066
2020 PO0945250319	KU	3	40 BRO	SP	CRE	ID	BD		12/6/2066
2020 PO0541360160	KU	4	40 ACW	SP	CRE	ED,ID	TD		12/7/2066
2020 PO055259907	KU	4	40 ACW	SP	CRE	ED,ID	TD		12/8/2066
2020 PO0536360038	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		12/9/2066
2020 PO0534059982	KU	4	45 ACW	SP	CRE	ED,ID,IP	TD		12/10/2066
2020 PO0528859861a	KU	4	40 ACW	SP	CCA		V		12/11/2066
2020 PO0528859861	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		12/12/2066
2020 PO0523259737	KU	4	40 ACW	SP	CCA		V		12/13/2066
2020 PO0499259158	KU	4	40 ACW	SP	CRE	ED,ID	BD		12/14/2066
2020 PO0948450272	KU	3	45 BRO	SP	P	ED	BD		12/15/2066
2020 PO0708251530	KU	3	45 BRO	SP	CCA		V		12/16/2066
2020 PO0568151424	KU	5	35 BRO	SP	CRE	ED,ID,SRC	TD		12/17/2066
2020 PO0554651359	KU	2	70 BRO	AL	CCA		V		12/18/2066
2020 PO0550551510	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD		12/19/2066
2020 PO0494550839	KU	4	40 BRO	SP	CRE	ID	BD		12/20/2066
2020 PO7796725630	KU	4	40 OTH	SP	CRE	ID	TD		12/21/2066
2020 PO7794425226	KU	4	40 KOP	SP	CCA		V		12/22/2066
2020 PO7795324990	KU	2	50 OTH	SP	CCA		V		12/23/2066
2020 PO7802825318	KU	4	40 OTH	SP	CRE		V		12/24/2066
2020 PO7786525341	KU	4	40 OTH	SP	CRE		V		12/25/2066
2020 PO7795525650	KU	4	40 OTH	SP	CRE	ID	TD		12/26/2066
2020 PO7780525169	KU	6	30 OTH	SP	CRE	ID	TD		12/27/2066
2020 PO7772225260	KU	4	35 OTH	SP	CCA		V		12/28/2066
2020 PO7817225310	KU	5	35 OTH	SP	CCA		V		12/29/2066
2020 PO7795925310	KU	2	50 BRN	SP	CCA		V		12/30/2066
2020 PO7794425674	KU	4	40 OTH	SP	CRE	ID	TD		12/31/2066

2020 PO2981733294	KU	6	30 BRN	SP	CRE		V		1/1/2067
2020 PO2988233168	KU	4	40 BRN	SP	CRE	ED,ID,IP,MD	TD		1/2/2067
2020 PO2910833467	KU	4	40 BRN	SP	CRE	ED,ID	TD		1/3/2067
2020 PO2914933215	KU	4	40 BRN	SP	CRE	ID	BD		1/4/2067
2020 PO3005833942	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		1/5/2067
2020 PO0419450618	F	4	40 BRO	SP	CRE		V		1/6/2067
2020 PO2865033977	KU	5	35 BRN	SP	CRE	ED,HH,ID	BX	RP2	1/7/2067
2020 PO0508659387	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		1/8/2067
2020 PO0518559625	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		1/9/2067
2020 PO0524259577	KU	5	35 ACW	SP	CRE	ED,ID,IP	TD		1/10/2067
2020 PO0523959303	KU	5	35 ACW	SP	CRE	ED,ID,IP	TD		1/11/2067
2020 PO0535159414	KU	5	35 ACW	SP	CRE	ED,ID	TD		1/12/2067
2020 PO0382260778	KU	5	35 ACW	SP	CRE	ED,ID	BD		1/13/2067
2020 PO0380660746	KU	4	40 ACW	SP	CRE	ED,ID	BD		1/14/2067
2020 PO7780925412	F	5	35 OTH	SP	P		V		1/15/2067
2020 PO5897806449	KU	4	35 BRO	SP	CRE		V		1/16/2067
2020 PO5873906503	KU	4	35 BRO	SP	CRE		V		1/17/2067
2020 PO6951489284	KU	5	35 BRN	SP	CRE	ED,ID	BD		1/18/2067
2020 PO6958189215	KU	6	30 BRN	SP	CRE	ED,ID,IP	TX	RR	1/19/2067
2020 PO6966589283	KU	4	40 BRN	SP	CRE	ED,ID,SR	TD		1/20/2067
2020 PO5859706526	KU	4	40 BRO	SP	CRE		V		1/21/2067
2020 PO6002106421a	KU	4	40 BRO	SP	CRE	ED,RB	X	RP1	1/22/2067
2020 PO6002106421	KU	4	45 BRO	SP	CCA		V		1/23/2067
2020 PO6029906584	F	5	35 BRO	SP	CRE		V		1/24/2067
2020 PO5954106528	KU	6	30 BRO	SP	CRE	ID	TD		1/25/2067
2020 PO5954706433	KU	5	30 BRO	SP	CRE	ID	TD		1/26/2067
2020 PO5930206376	KU	4	45 BRO	SP	CRE	ID	BD		1/27/2067
2020 PO8298669859	KU	4	40 BRO	SP	CCA		V		1/28/2067
2020 PO4508401659	KU	6	30 BRO	SP	CCA		V		1/29/2067
2020 PO4509701591	KU	4	40 BRO	SP	CCA		V		1/30/2067
2020 PO4512001488	F	4	40 BRO	SP	CRE		V		1/31/2067
2020 PO4514101395	F	4	40 BRO	SP	CRE		V		2/1/2067
2020 PO2368004484	KU	5	35 BRO	SP	CRE		V		2/2/2067
2020 PO2328303996	KU	5	35 BRO	SP	CRE		V		2/3/2067
2020 PO2288303510	KU	4	40 BRO	SP	CRE		V		2/4/2067
2020 PO2262203191	KU	4	45 BRO	SP	CRE		V		2/5/2067
2020 PO2250103043	KU	4	40 BRO	SP	CRE		V		2/6/2067
2020 PO2233502909	KU	5	35 BRO	SP	CRE		V		2/7/2067
2020 PO4692198226	KU	6	30 INP	SP	CRE		V		2/8/2067
2020 PO7172385291	KU	5	30 BRO	SP	CRE	ED,ID	TD		2/9/2067
2020 PO7167085042	KU	4	40 BRO	SP	CRE	ED,ID	TD		2/10/2067
2020 PO7194786007	KU	5	30 BRO	SP	CRE	ED,ID	TD		2/11/2067
2020 PO7188786082	KU	4	40 BRO	SP	CRE	ED,ID	BD		2/12/2067
2020 PO7182585948A	KU	3	40 BRO	SP	A	ED,ID	BD		2/13/2067
2020 PO7182585948	KU	3	40 BRO	SP	CRE	ED,ID	TD		2/14/2067
2020 PO7636973376	KU	4	40 BRO	SP	CRE		V		2/15/2067
2020 PO7185885813	KU	4	35 BRO	SP	CRE	ED,ID	TD		2/16/2067

2020 PO7176785809	KU	4	40 BRO	SP	CRE	ED,ID	TD	2/17/2067
2020 PO6859687202	KU	1	100 BRO	SP	CRE	ED,ID	TD	2/18/2067
2020 PO6797082974-A	KU	1	70 BRN	SP	CRE		V	2/19/2067
2020 PO6818382927	KU	1	70 BRN	SP	CRE		V	2/20/2067
2020 PO6797082974	KU	1	70 BRN	SP	CRE		V	2/21/2067
2020 PO6760583143-A	KU	2	60 BRN	SP	CCA		V	2/22/2067
2020 PO6760583143	KU	2	60 BRN	SP	P		V	2/23/2067
2020 PO8488381107	F	5	35 BRO	SP	CRE		V	2/24/2067
2020 PO8474581594	F	4	40 BRO	SP	A		V	2/25/2067
2020 PO8506081412	F	4	40 BRO	SP	A		V	2/26/2067
2020 PO8470577214	KU	3	45 BRO	SP	CRE		B	2/27/2067
2020 PO8470677261	KU	3	50 BRO	SP	CCA		V	2/28/2067
2020 PO8470377160	KU	3	45 BRO	SP	CRE	ID	BD	3/1/2067
2020 PO8463877181	KU	4	40 BRO	SP	CRE	ID	BD	3/2/2067
2020 PO8449877124	KU	6	30 BRO	SP	CRE	ID	BD	3/3/2067
2020 PO8453877190	KU	4	40 BRO	SP	CRE	ID	BD	3/4/2067
2020 PO8454377490	F	5	35 BRO	SP	CRE		V	3/5/2067
2020 PO8450477502	F	5	35 BRO	SP	CRE		V	3/6/2067
2020 PO8536281584	KU	5	35 BRO	SP	CRE	ID	BD	3/7/2067
2020 PO2425105175	KU	5	35 BRO	SP	CRE		V	3/8/2067
2020 PO7465175599	KU	4	40 BRN	SP	CRE	ED,ID	TD	3/9/2067
2020 PO7444075599	KU	4	40 BRN	SP	CRE	ED,ID	TD	3/10/2067
2020 PO7419275603	KU	4	40 BRN	SP	CRE	ED,ID	TD	3/11/2067
2020 PO7394475606	KU	4	45 BRN	SP	CRE	ED,ID	TD	3/12/2067
2020 PO7383775608	KU	3	50 BRN	SP	CRE	ED,ID	TD	3/13/2067
2020 PO7378275903	KU	3	45 BRN	SP	CCA		V	3/14/2067
2020 PO7383475965	KU	5	35 BRN	SP	CCA		V	3/15/2067
2020 PO7326875771	KU	2	45 BRN	SP	CRE	ED,ID	TD	3/16/2067
2020 PO7404486971	KU	2	50 BRO	SP	CRE	ID	BD	3/17/2067
2020 PO7430686946	KU	2	50 BRO	SP	CRE	ED,ID	TD	3/18/2067
2020 PO3966200223	KU	6	30 XXX	SP	CCA		V	3/19/2067
2020 PO3965800304	KU	4	40 XXX	SP	CRE	ED,ID	TD	3/20/2067
2020 PO7447286921	KU	2	50 BRO	SP	CRE	ED,ID	TD	3/21/2067
2020 PO3759005355	KU	4	45 BRO	SP	CRE	ID	BD	3/22/2067
2020 PO7315887058	KU	2	45 BRO	SP	CRE	ED,ID	TD	3/23/2067
2020 PO3771504641	KU	3	50 BRO	SP	CRE	ID	TD	3/24/2067
2020 PO3756904774	KU	4	40 BRO	SP	CRE	ED,ID	BX	3/25/2067
2020 PO3742504904	KU	4	45 BRO	SP	CRE	ID	TD	3/26/2067
2020 PO3731904998	KU	4	45 BRO	SP	CRE	ID	TD	3/27/2067
2020 PO3719705107	KU	4	40 BRO	SP	CRE	ID	TD	3/28/2067
2020 PO3566704469	KU	6	30 BRO	SP	CRE	ID	TD	3/29/2067
2020 PO7334387115	KU	3	55 BRO	SP	CRE	ED,ID,IP	BD	3/30/2067
2020 PO7359087033	KU	2	50 BRO	SP	CRE	ED,ID	TD	3/31/2067
2020 PO7357486938	KU	6	30 BRO	SP	CRE	ED,ID	TD	4/1/2067
2020 PO4352802178B	KU	6	30 BRN	SP	CCA		V	4/2/2067
2020 PO4352802178A	KU	6	30 BRN	SP	CCA		V	4/3/2067
2020 PO7383087005	KU	2	50 BRO	SP	CRE	ED,ID	TD	4/4/2067

2020 PO7390086996	KU	2	50 BRO	SP	CRE	ED,ID	TD	4/5/2067	
2020 PO7456786901	KU	3	40 BRO	SP	A	ED,ID	BD	4/6/2067	
2020 PO7456886912	KU	3	30 BRO	SP	CCA		V	4/7/2067	
2020 PO7466386901	KU	3	40 BRO	SP	CRE	ED,ID	BD	4/8/2067	
2020 PO7476686888	KU	4	40 BRO	SP	CCA		V	4/9/2067	
2020 PO7487886870	KU	4	40 BRO	SP	CRE	ED,ID	TD	4/10/2067	
2020 PO3967400474	KU	5	30 XXX	SP	CRE	ED,ID	TD	4/11/2067	
2020 PO3950800517	KU	5	30 BRN	SP	CCA		V	4/12/2067	
2020 PO3966700711	KU	5	35 BRN	SP	CRE	ED,ID	TD	4/13/2067	
2020 PO3958200825	KU	6	30 BRN	SP	CCA		V	4/14/2067	
2020 PO3965400852	KU	4	45 BRN	SP	CCA		V	4/15/2067	
2020 PO3952701069	KU	6	30 BRN	SP	CCA		V	4/16/2067	
2020 PO7182786952	KU	6	30 BRO	SP	CRE	ED,ID	VX	4/17/2067	RP2
2020 PO3941101317	KU	5	35 XXX	SP	CCA		V	4/18/2067	
2020 PO3979501543	KU	4	40 BRN	SP	CCA		V	4/19/2067	
2020 PO3988801739	KU	4	40 XXX	SP	CRE	ED,ID	TD	4/20/2067	
2020 PO8467366701	KU	4	40 BRO	SP	CRE	ED,ID	TD	4/21/2067	
2020 PO4000102001	KU	5	40 XXX	SP	CRE	ED,ID,IP	TX	4/22/2067	RR
2020 PO8439966425	KU	6	40 BRO	SP	CRE	ED,ID	TD	4/23/2067	
2020 PO8417965953	KU	4	40 BRO	SP	A	ED,ID,IP	TD	4/24/2067	
2020 PO7097786115	KU	5	35 BRO	SP	CRE		V	4/25/2067	
2020 PO7112486219	KU	4	40 BRO	SP	CRE	ED,ID	TD	4/26/2067	
2020 PO3276005566	KU	6	30 BRO	SP	CRE	ID	TD	4/27/2067	
2020 PO3254805018	KU	4	40 BRO	SP	CRE	ID	TD	4/28/2067	
2020 PO3582804542	KU	5	35 BRO	SP	CRE	ID	TD	4/29/2067	
2020 PO3599504508	KU	4	40 BRO	SP	CRE		V	4/30/2067	
2020 PO3597804533	KU	4	40 BRO	SP	CRE	ID	TD	5/1/2067	
2020 PO3627604137	KU	5	35 BRO	SP	CRE		V	5/2/2067	
2020 PO3596004052	KU	6	30 BRO	SP	CRE	ID	TD	5/3/2067	
2020 PO8996882482	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	5/4/2067	
2020 PO9059481369	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	5/5/2067	
2020 PO8524479974	F	3	45 BRO	SP	CRE		V	5/6/2067	
2020 PO8525280191	F	3	50 BRO	SP	CRE		V	5/7/2067	
2020 PO8524780059	F	3	50 BRO	SP	CRE		V	5/8/2067	
2020 PO8525880329	F	3	50 BRO	SP	CRE		V	5/9/2067	
2020 PO8526280427	F	3	50 BRO	SP	CRE		V	5/10/2067	
2020 PO8526680506	F	3	50 BRO	SP	CRE		V	5/11/2067	
2020 PO8527280655	F	3	45 BRO	SP	CRE		V	5/12/2067	
2020 PO8527580735	F	3	45 BRO	SP	CRE		V	5/13/2067	
2020 PO8527880790	F	3	50 BRO	SP	CRE		V	5/14/2067	
2020 PO9119681308	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	5/15/2067	
2020 PO9124381339	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	5/16/2067	
2020 PO9091481506	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	5/17/2067	
2020 PO8528280887	F	3	50 BRO	SP	CRE		V	5/18/2067	
2020 PO8528881033	F	3	50 BRO	SP	CRE		V	5/19/2067	
2020 PO8529381136	F	4	40 BRO	SP	CRE		V	5/20/2067	
2020 PO8529881252	F	4	40 BRO	SP	CRE		V	5/21/2067	

2020 PO8530881361	F	4	40 BRO	SP	CRE		V	5/22/2067
2020 PO8533181471	F	3	50 BRO	SP	CRE		V	5/23/2067
2020 PO8587382229	F	5	35 BRO	SP	CCA		V	5/24/2067
2020 PO8580382167	F	3	45 BRO	SP	CCA		V	5/25/2067
2020 PO8573382089	F	3	45 BRO	SP	CCA		V	5/26/2067
2020 PO8564981987	F	4	40 BRO	SP	CCA		V	5/27/2067
2020 PO8555581877	F	4	40 BRO	SP	CRE		V	5/28/2067
2020 PO8562882216	KU	5	35 BRO	SP	CRE	ED,ID,SRS	TD	5/29/2067
2020 PO8556082354	KU	6	30 BRO	SP	CRE	ED,ID,SRC	TD	5/30/2067
2020 PO8549782382	KU	5	35 BRO	SP	CRE	ID	BD	5/31/2067
2020 PO8550282318	KU	6	30 BRO	SP	CRE		V	6/1/2067
2020 PO8622782091	F	4	40 BRO	SP	CRE		V	6/2/2067
2020 PO9018282013	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	6/3/2067
2020 PO9056781813	KU	6	30 BRO	SP	CCA		V	6/4/2067
2020 PO9058781735	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/5/2067
2020 PO8533080868	KU	4	45 BRO	SP	CCA		V	6/6/2067
2020 PO8539580869	KU	4	45 BRO	SP	CCA		V	6/7/2067
2020 PO8533280790	KU	5	35 BRO	SP	CRE	ED	TD	6/8/2067
2020 PO8533580719	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	6/9/2067
2020 PO8608982209	F	4	40 BRO	SP	CRE		V	6/10/2067
2020 PO8598382298	F	4	40 BRO	SP	CRE		V	6/11/2067
2020 PO8596482318	F	3	45 BRO	SP	CCA		V	6/12/2067
2020 PO8595182340	KU	5	35 BRO	SP	CRE	ID	BD	6/13/2067
2020 PO8603282391	F	3	45 BRO	SP	CCA		V	6/14/2067
2020 PO8601582415	KU	5	35 BRO	SP	CRE	ED,ID,SRS	TD	6/15/2067
2020 PO8617682434	KU	5	35 BRO	SP	CRE	ID	BD	6/16/2067
2020 PO8608882507	F	5	35 BRO	SP	CRE		V	6/17/2067
2020 PO8607782518	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD	6/18/2067
2020 PO8615782620	KU	5	35 BRO	SP	CRE		V	6/19/2067
2020 PO8544280725	KU	5	35 BRO	SP	CRE	ID	BD	6/20/2067
2020 PO8548280720	KU	4	40 BRO	SP	CRE	ID,IP	BD	6/21/2067
2020 PO8550780702	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/22/2067
2020 PO8561680706	KU	4	40 BRO	SP	CRE	ID,IP	BD	6/23/2067
2020 PO9744486280	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	6/24/2067
2020 PO8542581334	KU	4	40 BRO	SP	CCA		V	6/25/2067
2020 PO8545681523	KU	4	40 BRO	SP	CCA		V	6/26/2067
2020 PO8602282798	KU	5	35 BRO	SP	CRE	ID	BD	6/27/2067
2020 PO8610482686	KU	5	35 BRO	SP	CRE	ED,ID,SRS	TD	6/28/2067
2020 PO8614482631	F	4	40 BRO	SP	CRE		V	6/29/2067
2020 PO0586361580	KU	5	30 BRN	SP	CRE	ED,ID,IP	X	6/30/2067
2020 PO0579561509	KU	3	45 BRN	SP	CRE	ID	TD	7/1/2067
2020 PO0579161454	F	6	30E BRN	SP	CRE		V	7/2/2067
2020 PO0586861478	KU	4	45 BRN	SP	CRE	ID	TD	7/3/2067
2020 PO0593361454	KU	3	45 BRN	SP	CRE	ID	TD	7/4/2067
2020 PO0600561365	F	6	30 BRN	SP	CRE		V	7/5/2067
2020 PO0605861403	KU	2	50 BRN	SP	CCA		V	7/6/2067
2020 PO0613261286	KU	4	45 BRN	SP	CRE	ED,ID,SRS	TD	7/7/2067

2020 PO0617961351	KU	2	50 BRN	SP	CCA		V	7/8/2067
2020 PO0626561315	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	7/9/2067
2020 PO0627961250	KU	4	35E BRN	SP	CRE	ID	TD	7/10/2067
2020 PO0604661080	KU	5	35 BRN	SP	CRE	ID	TD	7/11/2067
2020 PO0581661180	KU	4	45 BRN	SP	CRE	ID,IP,RB	TX RR	7/12/2067
2020 PO0576761257	KU	4	40 BRN	SP	CRE	ID,IP	TD	7/13/2067
2020 PO0562961316	KU	4	40 BRN	SP	CRE	ID,IP	TD	7/14/2067
2020 PO7671981217	KU	3	40 BRO	SP	CRE		V	7/15/2067
2020 PO7685281239	KU	4	40 BRO	SP	CRE		V	7/16/2067
2020 PO7686081186	KU	6	30 BRO	SP	CCA		V	7/17/2067
2020 PO7699381179	KU	6	30 BRO	SP	CRE	ED,ID	TD	7/18/2067
2020 PO7366878069	F	4	45 BRN	SP	CCA		V	7/19/2067
2020 PO7304478127	KU	4	45 BRN	SP	CCA		V	7/20/2067
2020 PO7315078138	KU	4	45 BRN	SP	CRE	ED,ID	TD	7/21/2067
2020 PO7337878103	KU	4	45 BRN	SP	CRE	ED,ID	BD	7/22/2067
2020 PO7359178072	KU	4	40 BRN	SP	CRE	ED,ID	TD	7/23/2067
2020 PO7366878069-A	KU	6	30 BRN	SP	CRE	ED,ID	TD	7/24/2067
2020 PO7364377782	KU	4	45 BRN	SP	CRE	ED,ID	TD	7/25/2067
2020 PO7359777506	KU	3	50 BRN	SP	CCA		V	7/26/2067
2020 PO7356377312	KU	3	45 BRN	SP	CRE	ED,ID	TD	7/27/2067
2020 PO7351477045	KU	3	50 BRN	SP	CRE		V	7/28/2067
2020 PO4532902265	KU	3	50 BRO	SP	CRE	ID	TD	7/29/2067
2020 PO4526902240	KU	4	40 BRO	SP	CRE	ID	TD	7/30/2067
2020 PO7698181252	KU	4	40 BRO	SP	CRE		V	7/31/2067
2020 PO7713081189	KU	6	30 BRO	SP	CRE	ED,ID	TD	8/1/2067
2020 PO3885204137	KU	4	40 XXX	SP	CRE	ED,ID	TD	8/2/2067
2020 PO3912203997	KU	6	30 XXX	SP	CRE	ED,ID	TD	8/3/2067
2020 PO3915404129	KU	4	40 XXX	SP	CRE	ED,ID	TD	8/4/2067
2020 PO3897104118	KU	4	35 XXX	SP	CRE	ED,ID	TD	8/5/2067
2020 PO3892803983	KU	4	40 XXX	SP	CRE	ED,ID	TD	8/6/2067
2020 PO3879103976	KU	5	35 BRN	SP	CRE	ED,ID	TD	8/7/2067
2020 PO7712381253	KU	4	40 BRO	SP	CRE	ED,ID	BD	8/8/2067
2020 PO7725981311	KU	6	30 BRO	SP	CRE	ED,ID	TD	8/9/2067
2020 PO7726781187	KU	6	30 BRO	SP	CRE	ED,ID	TD	8/10/2067
2020 PO7728681248	KU	4	40 BRO	SP	CRE	ED,ID	BD	8/11/2067
2020 PO7741381246	KU	4	40 BRO	SP	CRE	ED,ID	BD	8/12/2067
2020 PO7743081068	KU	5	30 BRO	SP	CRE	ED,ID	BD	8/13/2067
2020 PO7749381033	KU	4	40 BRO	SP	CRE	ED,ID	TD	8/14/2067
2020 PO8345066890	KU	6	30 BRO	SP	CRE	ED,ID	BD	8/15/2067
2020 PO8334966725	KU	6	30 BRO	SP	CRE	ED,ID	TD	8/16/2067
2020 PO8339866682	KU	4	40 BRO	SP	CRE	ED,ID,RB,SRC	X PX	8/17/2067
2020 PO7754380916	KU	3	45 BRO	SP	CCA		V	8/18/2067
2020 PO4523002243	KU	5	35 BRO	SP	CRE	ID	TX RR	8/19/2067
2020 PO4525102158	KU	4	40 BRO	SP	CRE	ID	X RP2	8/20/2067
2020 PO4517802230	KU	5	35 BRO	SP	CRE	ID	TD	8/21/2067
2020 PO4520702237	KU	5	35 BRO	SP	CRE	ID	TD	8/22/2067
2020 PO4188003688	KU	4	40 BRO	SP	CRE		V	8/23/2067

2020 PO4168103765	KU	4	40 BRO	SP	CRE	ID	TD	8/24/2067
2020 PO4147503844	KU	4	40 BRO	SP	CRE	ID	TD	8/25/2067
2020 PO4132103933	KU	4	40 BRO	SP	CRE	ID	BD	8/26/2067
2020 PO4130404124	KU	5	35 BRO	SP	CRE	ID	TD	8/27/2067
2020 PO4111304054	KU	5	35 BRO	SP	CCA		V	8/28/2067
2020 PO4119604154	KU	6	30 BRO	SP	CCA		V	8/29/2067
2020 PO4114103929	KU	6	30 BRO	SP	CCA		V	8/30/2067
2020 PO4207303612	KU	5	35 BRO	SP	CRE	ID	TD	8/31/2067
2020 PO4227403535	KU	4	40 BRO	SP	CRE	ID	TD	9/1/2067
2020 PO4244003495	KU	4	40 BRO	SP	CRE	ID	TD	9/2/2067
2020 PO4274403437	KU	5	35 BRO	SP	CRE	ID	TD	9/3/2067
2020 PO4290703402	KU	4	40 BRO	SP	CRE	ID	BD	9/4/2067
2020 PO2720606118	KU	4	40 BRO	SP	CRE	ID	BD	9/5/2067
2020 PO7762180720	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/6/2067
2020 PO7771380462	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/7/2067
2020 PO8326666536	KU	4	40 BRO	SP	P	ED,ID	TD	9/8/2067
2020 PO7718880121	KU	4	40 BRO	SP	CRE	ED,ID	BD	9/9/2067
2020 PO7753580281	KU	4	40 BRO	SP	CRE	ED,ID	BD	9/10/2067
2020 PO7742880231	KU	4	40 BRO	SP	CRE	ED,ID	BD	9/11/2067
2020 PO7731380179	KU	4	40 BRO	SP	CRE	ED,ID	BD	9/12/2067
2020 PO7707780070	KU	4	40 BRO	SP	CRE	ED,ID	BD	9/13/2067
2020 PO7696480022	KU	4	40 BRO	SP	CRE	ED,ID	BD	9/14/2067
2020 PO3946799407	KU	5	35 XXX	SP	CRE	ED,ID	TD	9/15/2067
2020 PO3914399638	KU	6	30 BRN	SP	CCA		V	9/16/2067
2020 PO3934299619	KU	6	30 BRN	SP	CCA		V	9/17/2067
2020 PO3947599689	KU	4	40 XXX	SP	CRE	ED,ID	TD	9/18/2067
2020 PO3937399836	KU	6	30 XXX	SP	CCA		V	9/19/2067
2020 PO8437667761	KU	5	35 BRO	SP	CCA		V	9/20/2067
2020 PO8441567715	KU	3	45 BRO	SP	CCA		V	9/21/2067
2020 PO8439067945	KU	5	30 BRO	SP	CRE		V	9/22/2067
2020 PO8441667843	KU	5	30 BRO	SP	CRE		V	9/23/2067
2020 PO8432367659	KU	4	40 BRO	SP	CRE	ED,ID	BD	9/24/2067
2020 PO8424366947	KU	6	30 BRO	SP	CCA		V	9/25/2067
2020 PO6761575512	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/26/2067
2020 PO6832476750	KU	4	45 BRN	SP	CRE	ED,ID	TD	9/27/2067
2020 PO6839276695	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/28/2067
2020 PO6835676254	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/29/2067
2020 PO6823676103	KU	3	40 BRN	SP	CRE	ED,ID	TD	9/30/2067
2020 PO6847976398	KU	4	40 BRN	SP	CRE	ED,ID	TD	10/1/2067
2020 PO6879176105	KU	4	40 BRN	SP	CRE	ED,ID	BD	10/2/2067
2020 PO6873576078	KU	4	40 BRN	SP	CRE	ED,ID	TD	10/3/2067
2020 PO6868475844	KU	5	35 BRN	SP	CRE	ED,ID	TD	10/4/2067
2020 PO6867676049	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	10/5/2067
2020 PO6838875944	KU	4	40 BRN	SP	CRE		V	10/6/2067
2020 PO7245986978	KU	5	35 BRO	SP	CRE	ED,HH,ID,RB	X	10/7/2067
2020 PO6956095465	KU	4	40 BRN	SP	CRE	ED,ID	TD	10/8/2067
2020 PO6940995389	KU	6	30 BRN	SP	CRE	ED,ID	TD	10/9/2067

2020 PO4211334294	KU	4	45 BRO	SP	CCA		V			10/10/2067
2020 PO7294802579	KU	4	40 XXX	SP	CCA		V			10/11/2067
2020 PO7013501206	KU	5	35 XXX	SP	CRE	ED,ID	TD			10/12/2067
2020 PO7012101256	KU	6	30 XXX	SP	CRE	ED,ID	TD			10/13/2067
2020 PO7003201227	KU	6	30 XXX	SP	CRE		V			10/14/2067
2020 PO7001401156	KU	6	30 XXX	SP	CCA		V			10/15/2067
2020 6989601335a	KU	6	30 XXX	SP	CRE	ED,ID	TD			10/16/2067
2020 PO6990301265	KU	6	30 XXX	SP	CRE	ID	BD			10/17/2067
2020 PO6978101289	KU	6	30 XXX	SP	CRE	ED,ID	TD			10/18/2067
2020 PO4425001325	KU	4	40 BRN	SP	CRE	ED,ID,IP	TX		RR	10/19/2067
2020 PO4411801347	KU	4	40 BRN	SP	CRE	ED,ID,IP	TX		RR	10/20/2067
2020 PO4431901197	KU	4	40 BRN	SP	CRE	ED,ID	TD			10/21/2067
2020 PO4418101292	KU	4	40 BRN	SP	CRE	ED,ID,RB	BX		PX	10/22/2067
2020 PO4743688651	LGE	4	35 BRN	SP	A	ED,ID	TX		RR	10/23/2067
2020 PO4921212101	F	4	35 ACE	SP	P		V			10/24/2067
2020 PO4931511965	F	4	40 ACE	SP	P		V			10/25/2067
2020 PO4925412080	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX		PX	10/26/2067
2020 PO4934612034	F	4	40 ACE	SP	P		V			10/27/2067
2020 PO4204911696	KU	4	40 BRO	SP	CRE	ID	BD			10/28/2067
2020 PO4745988642	LGE	4	35 BRN	SP	A	ED,ID	TD			10/29/2067
2020 PO2136926640	ODP	3	50 XXX	SP	CRE	ID	TD			10/30/2067
2020 PO5677237487	F	4	40 BRO	SP	CRE		V			10/31/2067
2020 PO5689437544	F	4	40 BRO	SP	CRE		V			11/1/2067
2020 PO5710737438	KU	4	40 BRO	SP	CRE	ED,ID	TD			11/2/2067
2020 PO5153938760	F	3	55 ACE	SP	CRE		V			11/3/2067
2020 PO5143438870	F	4	40 ACE	SP	CRE		V			11/4/2067
2020 PO5130939009	F	3	40 ACE	SP	CCA		V			11/5/2067
2020 PO5117539018	KU	4	40 ACE	SP	CRE	ID	BD			11/6/2067
2020 PO5103539023	KU	4	40 ACE	SP	CRE	ID,IP	BD			11/7/2067
2020 PO3886031479	KU	4	45 BRO	SP	CRE	ID	TD			11/8/2067
2020 PO3901231618	KU	6	30 BRO	SP	CRE	ED	BX		RP1	11/9/2067
2020 PO3915731743	KU	6	30 BRO	SP	CRE	ID,IP,SRC	TD			11/10/2067
2020 PO3924431667	KU	3	45 BRO	SP	A	ID	TD			11/11/2067
2020 PO3962231969	F	3	45 BRO	SP	A		V			11/12/2067
2020 PO5355843820	F	4	40 BRO	SP	A		V			11/13/2067
2020 PO5356443712	F	4	40 BRO	SP	A		V			11/14/2067
2020 PO5370343472	F	4	40 BRO	SP	A		V			11/15/2067
2020 PO5387643381	F	4	40 BRO	SP	CCA		V			11/16/2067
2020 PO5388143407	F	4	40 BRO	SP	CRE		V			11/17/2067
2020 PO5421443293	F	3	40 BRO	SP	A		V			11/18/2067
2020 PO5406043337	F	4	40 BRO	SP	CCA		V			11/19/2067
2020 PO5393143490	KU	4	40 BRO	SP	CRE	ID	TD			11/20/2067
2020 PO4710940169	KU	4	45 BRO	SP	CCA		V			11/21/2067
2020 PO4709139715	KU	3	45 BRO	SP	CCA		V			11/22/2067
2020 PO4708239425	KU	3	45 BRO	SP	CCA		V			11/23/2067
2020 PO4707439135	KU	3	50 BRO	SP	CCA		V			11/24/2067
2020 PO4710038770	KU	3	50 BRO	SP	CCA		V			11/25/2067

2020 PO4712538414	KU	3	50 BRO	SP	CCA		V	11/26/2067
2020 PO4715338033	KU	3	50 BRO	SP	CCA		V	11/27/2067
2020 PO4717937610	KU	3	50 BRO	SP	CCA		V	11/28/2067
2020 PO4720537196	KU	3	50 BRO	SP	CCA		V	11/29/2067
2020 PO5381842311	KU	3	45 ACE	SP	CRE	ED,ID,IP	TD	11/30/2067
2020 PO5369842330	KU	2	50 ACE	SP	CRE	ID,IP	BD	12/1/2067
2020 PO5408543576	F	4	40 BRO	SP	A		V	12/2/2067
2020 PO5398643651	F	4	40 BRO	SP	CRE		V	12/3/2067
2020 PO5373743662	KU	6	30 BRO	SP	CCA		V	12/4/2067
2020 PO5384543755	F	4	40 BRO	SP	A		V	12/5/2067
2020 PO5378843891	F	3	45 BRO	SP	A		V	12/6/2067
2020 PO5368743954	KU	6	30 BRO	SP	CRE	ID	TD	12/7/2067
2020 PO5374544001	F	4	40 BRO	SP	P		V	12/8/2067
2020 PO5707137921	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	12/9/2067
2020 PO5715837834	F	4	40 BRO	SP	CRE		V	12/10/2067
2020 PO5709837623	F	4	40 BRO	SP	CRE		V	12/11/2067
2020 PO5728037578	F	4	40 BRO	SP	CCA		V	12/12/2067
2020 PO5743737464	F	4	40 BRO	SP	CRE		V	12/13/2067
2020 PO5818253025	KU	4	40 ACE	SP	CRE	ED,ID	TD	12/14/2067
2020 PO5815852934	KU	5	35 ACE	SP	CCA		V	12/15/2067
2020 PO5805652959	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	12/16/2067
2020 PO5789452992	KU	4	40 ACE	SP	CRE	ED,ID	TD	12/17/2067
2020 PO5770853005	KU	4	40 ACE	SP	CCA		V	12/18/2067
2020 PO5764853064	KU	4	40 ACE	SP	CCA		V	12/19/2067
2020 PO5748153052a	KU	4	40 ACE	SP	CCA		V	12/20/2067
2020 PO5748153052	KU	3	45 ACE	SP	CCA		V	12/21/2067
2020 PO5732853134	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	12/22/2067
2020 PO5693053412	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	12/23/2067
2020 PO5355244014	F	4	40 BRO	SP	A		V	12/24/2067
2020 PO5706953562	KU	4	35 ACE	SP	CCA	ED,ID	BD	12/25/2067
2020 PO5693453544	KU	4	40 ACE	SP	CRE	ED,ID	BD	12/26/2067
2020 PO5710953759	KU	6	30 ACE	SP	CRE	ED,ID	TD	12/27/2067
2020 PO5698353781	KU	5	35 ACE	SP	CRE	ED,ID	TD	12/28/2067
2020 PO5690553805	KU	6	30 ACE	SP	CRE	ED,ID	BD	12/29/2067
2020 PO5704953952	KU	4	40 ACE	SP	CRE	ED,ID	TD	12/30/2067
2020 PO5356444153	F	4	40 BRO	SP	A		V	12/31/2067
2020 PO5354844395	F	3	45 BRO	SP	A		V	1/1/2068
2020 PO5352744615	F	3	45 BRO	SP	A		V	1/2/2068
2020 PO5360944608	F	4	40 BRO	SP	CRE		V	1/3/2068
2020 PO5382844590	F	4	40 BRO	SP	A		V	1/4/2068
2020 PO5383344548	F	4	40 BRO	SP	A		V	1/5/2068
2020 PO5373844464	KU	6	30 BRO	SP	CRE	ID	TD	1/6/2068
2020 PO5384044413	F	4	40 BRO	SP	A		V	1/7/2068
2020 PO3934633012	KU	4	40 BRO	SP	CCA		V	1/8/2068
2020 PO3921332877	KU	4	40 BRO	SP	CRE	ID,IP	BD	1/9/2068
2020 PO3928232660	KU	4	40 BRO	SP	CRE	HH,ID,SRC	X	PX 1/10/2068
2020 PO3918932719	KU	5	35 BRO	SP	CCA		V	1/11/2068

2020 PO3910732887	KU	5	35 BRO	SP	CCA		V	1/12/2068	
2020 PO3925332747	KU	4	40 BRO	SP	CCA		B	1/13/2068	
2020 PO3936932383	KU	4	40 BRO	SP	CRE	ID	TD	1/14/2068	
2020 PO3944132187	KU	4	40 BRO	SP	CRE	ID,IP	BD	1/15/2068	
2020 PO5300641377	F	4	40 ACE	SP	CRE		V	1/16/2068	
2020 PO5275041233	F	4	40 ACE	SP	CRE		V	1/17/2068	
2020 PO5258941081	KU	3	40 ACE	SP	CCA		V	1/18/2068	
2020 PO5258540788	KU	5	35 ACE	SP	A	ED,ID,IP	TD	1/19/2068	
2020 PO5245340963	F	2	50 ACE	SP	CRE		V	1/20/2068	
2020 PO5241840750	F	4	40 ACE	SP	CCA		V	1/21/2068	
2020 PO5235040787	F	4	40 ACE	SP	CCA		V	1/22/2068	
2020 PO5225040816	KU	2	45 ACE	SP	CRE		V	1/23/2068	
2020 PO5249339021	F	4	40 ACE	SP	CRE		V	1/24/2068	
2020 PO5219739538	KU	6	30 ACE	SP	CCA		V	1/25/2068	
2020 PO5222339647	KU	6	30 ACE	SP	CRE		V	1/26/2068	
2020 PO5201539868	F	4	40 ACE	SP	CRE		V	1/27/2068	
2020 PO4744387885	LGE	1	50 BRO	SP	CCA		V	1/28/2068	
2020 PO4744087863	LGE	4	40 BRO	SP	A	ED,ID	BD	1/29/2068	
2020 PO4744187861	LGE	4	40 BRO	SP	CCA	ED,ID	BD	1/30/2068	
2020 PO4740087500	LGE	4	40 BRO	SP	CRE	ED,ID	TD	1/31/2068	
2020 PO4737887495	LGE	4	40 BRO	SP	P	ED,ID	TD	2/1/2068	
2020 PO4738087496	LGE	4	40 BRO	SP	P	ED,ID	TD	2/2/2068	
2020 PO5503253926	KU	4	40 OTH	SP	CCA		V	2/3/2068	
2020 PO5489453181	KU	4	40 OTH	SP	CRE	ID	TD	2/4/2068	
2020 PO533355730	KU	4	45 OTH	SP	CRE	ID	TD	2/5/2068	
2020 PO5330053575	KU	4	40 OTH	SP	CRE	ID	TD	2/6/2068	
2020 PO5518954182	KU	4	40 OTH	SP	CCA		V	2/7/2068	
2020 PO5481453340	KU	4	40 OTH	SP	CRE	ID	TD	2/8/2068	
2020 PO5485452800	KU	3	40 OTH	SP	CRE	ID	TD	2/9/2068	
2020 PO5465452669	KU	3	40 OTH	SP	CRE	ED,ID,RB	X	PX	2/10/2068
2020 PO5389552945	KU	3	40 OTH	SP	CRE	ID	TD	2/11/2068	
2020 PO5369653148	KU	4	40 OTH	SP	CRE	ID	TD	2/12/2068	
2020 PO5315853824	KU	4	40 OTH	SP	CRE	ID	TD	2/13/2068	
2020 PO5301454054	KU	4	40 OTH	SP	CRE	ID	TD	2/14/2068	
2020 PO4245232939	KU	4	40 BRO	SP	CRE	ID	TD	2/15/2068	
2020 PO4271832905	KU	5	35 BRO	SP	CRE	ID	BD	2/16/2068	
2020 PO4281033084	KU	5	35 BRO	SP	CRE	ID	BD	2/17/2068	
2020 PO4254033035	KU	4	40 BRO	SP	CRE		V	2/18/2068	
2020 PO5047337139	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	2/19/2068	
2020 PO5040537077	KU	4	40 ACE	SP	CRE	ID,IP	BD	2/20/2068	
2020 PO5029137204	KU	4	45 ACE	SP	CRE	ED,ID,IP	TD	2/21/2068	
2020 PO5026437086	KU	4	45 ACE	SP	CRE	ID,IP	BD	2/22/2068	
2020 PO5015437092	KU	4	40 ACE	SP	CRE	ID,IP	BD	2/23/2068	
2020 PO4998137104	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	2/24/2068	
2020 PO4976737114	KU	4	40 ACE	SP	CRE	ID,IP	BD	2/25/2068	
2020 PO4953137114	KU	2	40 ACE	SP	CRE	ID,IP	BD	2/26/2068	
2020 PO4977337211	F	4	40 ACE	SP	CCA		V	2/27/2068	

2020 PO4956637214	F	4	40 ACE	SP	CRE		V	2/28/2068
2020 PO5536454719	KU	4	40 OTH	SP	CCA	ED,SRS	TD	2/29/2068
2020 PO5505752932	KU	4	40 OTH	SP	CRE	ID	TD	3/1/2068
2020 PO5349655383	KU	5	35 OTH	SP	CRE	ID	TD	3/2/2068
2020 PO5350353351	KU	4	40 OTH	SP	CRE	ID	TD	3/3/2068
2020 PO5560754632	KU	4	40 OTH	SP	CCA		V	3/4/2068
2020 PO5427652551	KU	4	40 OTH	SP	CRE		V	3/5/2068
2020 PO5484753652	KU	3	50 OTH	SP	CCA		V	3/6/2068
2020 PO5408452747	KU	3	40 OTH	SP	CRE	ID	TD	3/7/2068
2020 PO5447852325	KU	4	40 OTH	SP	CRE	ID	TD	3/8/2068
2020 PO5539954947	KU	3	50 OTH	SP	CCA		V	3/9/2068
2020 PO5529154404	KU	4	40 OTH	SP	CRE		V	3/10/2068
2020 PO4662087906	LGE	UNK	30 BRO	SP	CRE		V	3/11/2068
2020 PO4672287973	LGE	UNK	65 BRO	SP	A		V	3/12/2068
2020 PO4670087975	LGE	UNK	65 BRO	ST	CCA		V	3/13/2068
2020 PO4674588341	LGE	4	45 BRN	SP	CRE	ED,ID	TD	3/14/2068
2020 PO4741987504	LGE	4	40 BRO	SP	P	ED,ID	TD	3/15/2068
2020 PO4671987988	LGE	4	30 BRO	SP	A	ED,ID	BD	3/16/2068
2020 PO4672988009	LGE	3	50 BRO	SP	CCA		V	3/17/2068
2020 PO4673287997	LGE	4	30 BRO	SP	CRE		V	3/18/2068
2020 PO4672487997	LGE	3	45 BRO	SP	CCA		V	3/19/2068
2020 PO4672387987	LGE	3	45 BRO	SP	CCA		V	3/20/2068
2020 PO4673787986	LGE	3	45 BRO	SP	CCA		V	3/21/2068
2020 PO4675287984	LGE	4	40 BRO	SP	CCA	ED,ID	BD	3/22/2068
2020 PO4675887966	LGE	1H	70 BRO	SP	A		V	3/23/2068
2020 PO4674987967	LGE	1H	70 BRO	SP	A		V	3/24/2068
2020 PO4765787474	LGE	3	45 BRO	SP	CCA		V	3/25/2068
2020 PO4673688354	LGE	3	45 BRN	SP	CRE	ED,ID	TD	3/26/2068
2020 PO4673088363	LGE	3	45 BRN	SP	A	ED,ID	TD	3/27/2068
2020 PO4672888354	LGE	4	30 BRN	SP	CCA		V	3/28/2068
2020 PO5194111383	F	4	40 BRO	SP	CRE		V	3/29/2068
2020 PO5165211533	F	4	40 BRO	SP	CRE		V	3/30/2068
2020 PO5149611520	F	4	40 BRO	SP	CRE		V	3/31/2068
2020 PO5157011582	F	4	40 BRO	SP	CRE		V	4/1/2068
2020 PO5122611401	F	4	40 BRO	SP	CRE		V	4/2/2068
2020 PO5099113329	F	4	40 BRO	SP	CRE		V	4/3/2068
2020 PO5117311336	F	4	40 BRO	SP	CRE		V	4/4/2068
2020 PO5148613462	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	4/5/2068
2020 PO5064911968	F	4	40 BRO	SP	CRE		V	4/6/2068
2020 PO5073412030	F	4	40 BRO	SP	CRE		V	4/7/2068
2020 PO5121612219	F	4	40 BRO	SP	CRE		V	4/8/2068
2020 PO5090412098	F	4	40 BRO	SP	CCA		V	4/9/2068
2020 PO5101612156	F	4	40 BRO	SP	CRE		V	4/10/2068
2020 PO5110712198	F	4	40 BRO	SP	CRE		V	4/11/2068
2020 PO5137413506	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/12/2068
2020 PO4672488373	LGE	3	45 BRN	SP	CRE	ED,ID	TD	4/13/2068
2020 PO5123413562	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/14/2068

2020 PO5104011582	F	4	40 BRO	SP	CRE		V	4/15/2068
2020 PO5093811684	F	4	40 BRO	SP	CRE		V	4/16/2068
2020 PO5084111777	F	4	40 BRO	SP	CRE		V	4/17/2068
2020 PO5074811871	F	6	30 BRO	SP	CCA		V	4/18/2068
2020 PO5167212369	F	4	40 BRO	SP	CRE		V	4/19/2068
2020 PO5176112485	F	4	40 BRO	SP	CRE		V	4/20/2068
2020 PO5180612543	F	4	40 BRO	SP	CRE		V	4/21/2068
2020 PO5133113145	F	4	40 BRO	SP	CRE		V	4/22/2068
2020 PO5121913201	F	4	40 BRO	SP	CRE		V	4/23/2068
2020 PO5110013261	F	4	40 BRO	SP	CRE		V	4/24/2068
2020 PO5088013384	F	4	40 BRO	SP	CRE		V	4/25/2068
2020 PO5077313439	F	4	40 BRO	SP	CRE		V	4/26/2068
2020 PO5032013635	F	4	40 BRO	SP	CRE		V	4/27/2068
2020 PO5042813592	F	4	40 BRO	SP	CRE		V	4/28/2068
2020 PO5054013547	F	4	40 BRO	SP	CRE		V	4/29/2068
2020 PO4678387963	LGE	UNK	65 BRO	SP	CRE		V	4/30/2068
2020 PO4677687982	LGE	4	40 BRO	SP	A	ED,ID	BD	5/1/2068
2020 PO4680387961	LGE	UNK	70 BRO	SP	CRE		V	5/2/2068
2020 PO4681687977	LGE	3	45 BRO	SP	CCA		V	5/3/2068
2020 PO4684787974-A	LGE	4 30E	BRO	SP	A	ED,ID	BD	5/4/2068
2020 PO4684787974	LGE	3	45 BRO	SP	CCA		V	5/5/2068
2020 PO4682487977	LGE	4	40 BRO	SP	CRE		V	5/6/2068
2020 PO5122812879	F	4	40 BRO	SP	CRE		V	5/7/2068
2020 PO5119012819	F	4	40 BRO	SP	CRE		V	5/8/2068
2020 PO5114412656	F	4	40 BRO	SP	CRE		V	5/9/2068
2020 PO5071312995	KU	4	40 BRO	SP	CRE		V	5/10/2068
2020 PO5084312967	F	4	40 BRO	SP	CRE		V	5/11/2068
2020 PO5077612981	F	4	40 BRO	SP	CRE		V	5/12/2068
2020 PO4676488368	LGE	4	40 BRN	SP	CRE	ED,ID	BD	5/13/2068
2020 PO5089213064	F	4	40 BRO	SP	CRE		V	5/14/2068
2020 PO5063813043	F	4	40 BRO	SP	CRE		V	5/15/2068
2020 PO5056413087	F	4	40 BRO	SP	CRE		V	5/16/2068
2020 PO5049513127	F	4	40 BRO	SP	CRE		V	5/17/2068
2020 PO4989113382	F	4	40 BRO	SP	CRE		V	5/18/2068
2020 PO5002113328	F	4	40 BRO	SP	CRE		V	5/19/2068
2020 PO5015013277	F	4	40 BRO	SP	CRE		V	5/20/2068
2020 PO5074712890	F	4	40 BRO	SP	CRE		V	5/21/2068
2020 PO5026313230	F	4	40 BRO	SP	CRE		V	5/22/2068
2020 PO9171829554	F	4	40 XXX	SP	CRE		V	5/23/2068
2020 PO9175129231	F	4	40 XXX	SP	CRE		V	5/24/2068
2020 PO5020912803	F	4	40 BRO	SP	CRE		V	5/25/2068
2020 PO5015912700	F	4	40 BRO	SP	CRE		V	5/26/2068
2020 PO4993512475	F	4	40 BRO	SP	CRE		V	5/27/2068
2020 PO9215628021	F	4	40 XXX	SP	CRE		V	5/28/2068
2020 PO9190728595	ODP	4	40 XXX	SP	CRE	ID	BD	5/29/2068
2020 PO9194028401	ODP	4	40 XXX	SP	CRE	ID	TD	5/30/2068
2020 PO9205228215	F	4	40 XXX	SP	CRE		V	5/31/2068

2020 PO9173428293	ODP	5	35 XXX	SP	CRE	ID	TD	6/1/2068
2020 PO9151528182	ODP	5	35 XXX	SP	CRE	ID	BD	6/2/2068
2020 PO9227728537	ODP	5	35 XXX	SP	CRE	ID	TD	6/3/2068
2020 PO4980212536	F	4	40 BRO	SP	CRE		V	6/4/2068
2020 PO4762687475	LGE	2	55 BRO	SP	CCA		V	6/5/2068
2020 PO4756987479	LGE	4	40 BRO	SP	CCA	ED,ID	BD	6/6/2068
2020 PO4755387479	LGE	4	40 BRO	SP	CCA	ED,ID	BD	6/7/2068
2020 PO4754887480	LGE	4	40 BRO	SP	CCA	ED,ID	BD	6/8/2068
2020 PO4755187476	LGE	4	30 BRO	SP	A	ED,ID	BD	6/9/2068
2020 PO4753187480	LGE	4	30 BRO	SP	A	ED,ID	BD	6/10/2068
2020 PO4753387483	LGE	4	40 BRO	SP	CCA		V	6/11/2068
2020 PO4751587494	LGE	3	45 BRO	SP	CCA		V	6/12/2068
2020 PO4750387507	LGE	3	45 BRO	SP	CCA		V	6/13/2068
2020 PO4749487521	LGE	3	45 BRO	SP	CCA		V	6/14/2068
2020 PO4748687538	LGE	4	40 BRO	SP	CCA		V	6/15/2068
2020 PO4747887555	LGE	4	40 BRO	SP	CCA		V	6/16/2068
2020 PO4747187571	LGE	4	40 BRO	SP	CCA		V	6/17/2068
2020 PO4746887570	LGE	4	30 BRO	SP	A	ED,ID	BD	6/18/2068
2020 PO4745787585	LGE	4	40 BRO	SP	CCA	ED,ID	BD	6/19/2068
2020 PO4746887585	LGE	4	40 BRO	SP	CCA		V	6/20/2068
2020 PO4776187455	LGE	4	40 BRO	SP	CCA		V	6/21/2068
2020 PO4769987472	LGE	4	40 BRO	SP	CCA		V	6/22/2068
2020 PO4758587477	LGE	3	45 BRO	SP	CCA		V	6/23/2068
2020 PO4966312651	KU	4	40 BRO	SP	CCA		V	6/24/2068
2020 PO4963912612	F	4	40 BRO	SP	CRE		V	6/25/2068
2020 PO4692688267	LGE	4	40 BRN	SP	A		B	6/26/2068
2020 PO4693188259	LGE	4	40 BRN	SP	A		B	6/27/2068
2020 PO4972112741	F	4	40 BRO	SP	CRE		V	6/28/2068
2020 PO4980112866	F	4	40 BRO	SP	CRE		V	6/29/2068
2020 PO4693688304	LGE	4	40 BRN	SP	A	ED,ID	BD	6/30/2068
2020 PO4985012962	F	4	40 BRO	SP	A		V	7/1/2068
2020 PO4989413053	F	4	40 BRO	SP	CRE		V	7/2/2068
2020 PO4692788296	LGE	4	40 BRN	SP	CCA		V	7/3/2068
2020 PO4693588284	LGE	4	40 BRN	SP	CRE	ED,ID	TD	7/4/2068
2020 PO4681488020	LGE	4	35 BRO	SP	P	ED,ID	BD	7/5/2068
2020 PO4681588015	LGE	4	30 BRO	SP	CRE	ED,ID	TD	7/6/2068
2020 PO4681687987	LGE	4	40 BRO	SP	P	ED,ID	BD	7/7/2068
2020 PO4680787978	LGE	4	35 BRO	SP	CRE	ED,ID	TD	7/8/2068
2020 PO4680687987	LGE	7	25 BRO	SP	CRE	ED,ID	TD	7/9/2068
2020 PO4014782550	LGE	3	45 BRN	SP	CRE	ED,ID	BD	7/10/2068
2020 PO4014782554	LGE	4	30 BRN	SP	CRE	ED,ID	BD	7/11/2068
2020 PO4523530272	KU	3	45 ACE	SP	CCA		V	7/12/2068
2020 PO4417838149	KU	4	45 BRO	SP	CCA		V	7/13/2068
2020 PO4422438220	KU	4	45 BRO	SP	CCA		V	7/14/2068
2020 PO4421038243	KU	4	45 BRO	SP	CCA		V	7/15/2068
2020 PO4413638081	KU	4	45 BRO	SP	CCA		V	7/16/2068
2020 PO4409038011	KU	4	45 BRO	SP	CCA		V	7/17/2068

2020 PO4404637940	KU	4	45 BRO	SP	CCA		V	7/18/2068
2020 PO4014382575	LGE	3	45 BRN	SP	CRE	ED,ID	TD	7/19/2068
2020 PO4526530346	KU	3	45 ACE	SP	CCA		V	7/20/2068
2020 PO4016182585	LGE	4	40 BRN	SP	CRE	ED,ID	T	7/21/2068
2020 PO4017882613	LGE	4	40 BRN	SP	CCA		V	7/22/2068
2020 PO4533430514	KU	3	45 ACE	SP	CCA		V	7/23/2068
2020 PO4019182600	LGE	4	40 BRN	SP	A	ED,ID	BD	7/24/2068
2020 PO4019982617	LGE	3	45 BRN	SP	S		V	7/25/2068
2020 PO4537730638	KU	3	45 ACE	SP	P	ED	T	7/26/2068
2020 PO4013682533	F	4	40 BRN	SP	CRE		V	7/27/2068
2020 PO4016282508	LGE	4	40 BRN	SP	CCA	ED,ID	TX	7/28/2068
2020 PO4538430654	KU	3	45 ACE	SP	CRE	ED	T	7/29/2068
2020 PO4592737734	KU	2	45 BRO	SP	CRE	ED,ID,IP	TD	7/30/2068
2020 PO4014782529	F	4	40 BRN	SP	CRE		V	7/31/2068
2020 PO4015082534	F	4	30 BRN	SP	S		V	8/1/2068
2020 PO4610437565	KU	2	45 BRO	SP	CRE	ED,ID,IP	TD	8/2/2068
2020 PO4655438745	KU	2	50 BRO	SP	CCA		V	8/3/2068
2020 PO4648038735	KU	3	50 BRO	SP	CCA		V	8/4/2068
2020 PO4578437870	KU	2	45 BRO	SP	CRE	ID	BD	8/5/2068
2020 PO4015982533	F	4	40 BRN	SP	CRE		V	8/6/2068
2020 PO4016082537	F	4	30 BRN	SP	CCA		V	8/7/2068
2020 PO6823216168	KU	4	40 XXX	SP	CRE		V	8/8/2068
2020 PO6713214246	KU	6	35 XXX	SP	CCA		V	8/9/2068
2020 PO6740614968	KU	6	30 XXX	SP	CRE		V	8/10/2068
2020 PO6960121538	KU	4	40 XXX	DF	CCA		V	8/11/2068
2020 PO6988021573	KU	4	40 XXX	SP	CCA		V	8/12/2068
2020 PO4017182536	F	4	40 BRN	SP	CRE		V	8/13/2068
2020 PO4017182540	F	4	30 BRN	SP	S		V	8/14/2068
2020 PO4539230674	KU	1	45 ACE	SP	CRE	ED,ID	TD	8/15/2068
2020 PO4019682521	LGE	3	45 BRN	SP	CRE	ED,ID	TD	8/16/2068
2020 PO4575737844	KU	4	40 BRO	SP	CCA		V	8/17/2068
2020 PO4621337469	KU	2	50 BRO	SP	CRE	ED,ID,IP	BD	8/18/2068
2020 PO4614937525	KU	3	45 BRO	SP	CCA		V	8/19/2068
2020 PO4018282539	F	4	40 BRN	SP	CRE		V	8/20/2068
2020 PO4540830730	KU	4	45 ACE	SP	P	ED	T	8/21/2068
2020 PO4546330724	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	8/22/2068
2020 PO4542530766	KU	3	45 ACE	SP	CCA		V	8/23/2068
2020 PO4019382545	F	4	40 BRN	SP	CRE		V	8/24/2068
2020 PV4020782552	F	4	40 BRN	SP	CRE		V	8/25/2068
2020 PO4023482514	LGE	4	30 BRN	SP	CCA		V	8/26/2068
2020 PO4023182513	LGE	4	35 BRN	SP	CCA		V	8/27/2068
2020 PO4023182521	LGE	4	40 BRN	SP	A	ED,ID	BD	8/28/2068
2020 PO4021982559	F	4	40 BRN	SP	CRE		V	8/29/2068
2020 PO4023382567	F	3	45 BRN	SP	S		V	8/30/2068
2020 PO4023982561	F	6	25 BRN	SP	CRE		V	8/31/2068
2020 PO4023882580	F	4	40 BRN	SP	CCA		V	9/1/2068
2020 PO4024582583	F	4	35 BRN	SP	A		V	9/2/2068

2020 PO4022982587	F	4	40 BRN	SP	A		V		9/3/2068
2020 PO4022282601	F	4	40 BRN	SP	CCA		V		9/4/2068
2020 PO4021482616	F	3	45 BRN	SP	S		V		9/5/2068
2020 PO4625337434	KU	3	45 BRO	SP	CCA		V		9/6/2068
2020 PO4617936476	KU	2	45 BRO	SP	CCA		V		9/7/2068
2020 PO4620336455	KU	3	45 BRO	SP	CCA		V		9/8/2068
2020 PO4622736437	KU	2	45 BRO	SP	CCA		V		9/9/2068
2020 PO4628736558	KU	6	30 BRO	SP	CRE		V		9/10/2068
2020 PO4633036620	KU	3	45 BRO	SP	CRE		V		9/11/2068
2020 PO4637936629	KU	6	30 BRO	SP	CCA		V		9/12/2068
2020 PO0555045514	KU	4	40 BRN	SP	CCA		V		9/13/2068
2020 PO0559245620	KU	4	40 BRN	SP	CRE	ID	TD		9/14/2068
2020 PO0554245863	KU	4	40 BRN	SP	CRE	ID,IP	TD		9/15/2068
2020 PO1859644215A	ODP	5	30 UNK	SP	CRE		V		9/16/2068
2020 PO1859644215	ODP	5	35 UNK	SP	CRE		V		9/17/2068
2020 PO1904344373	ODP	4	45 UNK	SP	CRE		V		9/18/2068
2020 PO1806346919	ODP	5	30 UNK	SP	CRE		V		9/19/2068
2020 PO1803246878	ODP	5	35 UNK	SP	CRE	ED,ID	TD		9/20/2068
2020 PO3084940350	ODP	5	35 UNK	SP	CRE	ED,ID,SRS	TD		9/21/2068
2020 PO3084540681	ODP	4	40 BRN	SP	CRE		V		9/22/2068
2020 PO3051940963	ODP	4	40 BRN	SP	CRE	ED,ID	TD		9/23/2068
2020 PO2977140107	F	7	20 UNK	SP	CCA		V		9/24/2068
2020 PO2958140162	ODP	6	30 SWP	SP	CRE	ED,ID	TD		9/25/2068
2020 PO2972540191	F	3	40 SWP	SP	CRE		V		9/26/2068
2020 PO2987640322	F	4	40 SWP	SP	CRE		V		9/27/2068
2020 PO3004940416	ODP	6	30 UNK	SP	CRE	ED,HH,ID	TX	RR	9/28/2068
2020 PO3003240464	F	4	40 UNK	SP	CRE		V		9/29/2068
2020 PO1990346272	ODP	5	35 UNK	SP	CRE	ED,ID	TD		9/30/2068
2020 PO2159247812	ODP	5	35 UNK	SP	CRE	ED,ID,SRS	TD		10/1/2068
2020 PO2612027621	ODP	4	40 BRN	SP	CCA		V		10/2/2068
2020 PO1238320167	F	4	40 XXX	SP	CRE		V		10/3/2068
2020 PO1223520074	F	4	40 XXX	SP	A		V		10/4/2068
2020 PO1212220022	F	4	40 XXX	SP	CRE		V		10/5/2068
2020 PO1199619964	F	4	40 XXX	SP	CRE		V		10/6/2068
2020 PO1188519906	F	4	40 XXX	SP	CRE		V		10/7/2068
2020 PO1167519787	F	4	40 XXX	SP	CRE		V		10/8/2068
2020 PO1145919690	F	4	40 US	SP	A		V		10/9/2068
2020 PO1110119708	F	5	40 XXX	SP	A		V		10/10/2068
2020 PO1118319852	F	3	45 XXX	SP	CRE		V		10/11/2068
2020 PO1128219790	F	4	40 US	SP	A		V		10/12/2068
2020 PO1094919987	F	4	40 BRN	SP	A		VX	RP3	10/13/2068
2020 PO3979482514	F	3	45 BRN	SP	CRE		V		10/14/2068
2020 PO6982536782	LGE	3	45 BRN	SP	S		V		10/15/2068
2020 PO3977782512	F	3	40 BRN	SP	A		V		10/16/2068
2020 PO3976382511	F	3	45 BRN	SP	CRE	ED,ID	VX	PX	10/17/2068
2020 PO3974982509	F	3	45 BRN	SP	S		V		10/18/2068
2020 PO3973682493	F	4	40 BRN	SP	CRE		V		10/19/2068

2020 PO3973582508	F	4	40 BRN	SP	S		V		10/20/2068
2020 PO3972282502	F	4	30 BRN	SP	CRE		V		10/21/2068
2020 PO3972182507	F	3	45 BRN	SP	A		V		10/22/2068
2020 PO3970882506	F	3	45 BRN	SP	CCA		V		10/23/2068
2020 PO3969482504	F	3	45 BRN	SP	A		V		10/24/2068
2020 PO3968082503	F	4	40 BRN	SP	A		V		10/25/2068
2020 PO1187020227	ODP	4	40 UNK	SP	CRE	ID	BD		10/26/2068
2020 PO1203021123	ODP	4	40 SWP	SP	P	ED,SRS	TD		10/27/2068
2020 PO1205421373	ODP	4	40 BRN	SP	CRE	ID	TD		10/28/2068
2020 PO3966982502	F	3	45 BRN	SP	A		V		10/29/2068
2020 PO3965682501	F	3	45 BRN	SP	S		V		10/30/2068
2020 PO3964182499	F	3	50 BRN	SP	CCA		V		10/31/2068
2020 PO3962482498	LGE	3	45 BRN	SP	A	ED,ID	TD		11/1/2068
2020 PO1244521392	ODP	6	30 BRN	SP	CRE	ID	TD		11/2/2068
2020 PO1186021106	ODP	4	40 BRN	SP	CRE	ID	TD		11/3/2068
2020 PO0394931133	ODP	6	30 XXX	SP	CRE		V		11/4/2068
2020 PO0374931073	ODP	5	35 XXX	SP	CRE		V		11/5/2068
2020 PO0299531780	ODP	4	45 XXX	SP	CRE		V		11/6/2068
2020 PO3756646028	F	4	40 BRO	SP	CRE		V		11/7/2068
2020 PO3767145935	F	4	40 BRO	SP	CRE		V		11/8/2068
2020 PO3780345855	F	4	40 BRO	SP	CRE		V		11/9/2068
2020 PO3961182497	F	4	40 BRN	SP	CRE		V		11/10/2068
2020 PO3955782616	F	4	40 BRN	SP	CRE		V		11/11/2068
2020 PO3954982617	F	3	45 BRN	SP	S		V		11/12/2068
2020 PO3954282613	F	4	40 BRN	SP	CCA		V		11/13/2068
2020 PO1164621316A	ODP	6	30 BRN	SP	CCA	ED,SRS	TD		11/14/2068
2020 PO1171921233	ODP	4	40 BRN	SP	CRE	ID	TD		11/15/2068
2020 PO1164621316	ODP	4	40 BRN	SP	CRE	ID	TD		11/16/2068
2020 PO3952782616	LGE	4	40 BRN	SP	CRE	ED,ID	TD		11/17/2068
2020 PO0247935874a	ODP	5	30 XXX	SP	CCA		V		11/18/2068
2020 PO3952182614	F	4	40 BRN	SP	CRE		V		11/19/2068
2020 PO3952882630	LGE	3	45 BRN	SP	CRE	ED,ID	TX	RR	11/20/2068
2020 PO0246635648	ODP	5	35 XXX	SP	CRE	ED,ID	TD		11/21/2068
2020 PO0247935874	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD		11/22/2068
2020 PO0261736007	ODP	6	35 XXX	SP	CRE	ED,ID,IP	TD		11/23/2068
2020 PO3716634954	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD		11/24/2068
2020 PO3680034791	KU	4	40 BRN	SP	CRE	ED,ID	TD		11/25/2068
2020 PO3650734518	KU	4	40 BRN	SP	CRE	ED,ID,SRS	TD		11/26/2068
2020 PO3631734299	KU	4	40 BRN	SP	CRE	ID	BD		11/27/2068
2020 PO3611233926	KU	4	40 BRN	SP	CRE	ID	BD		11/28/2068
2020 PO4644632105	KU	4	45 ACE	SP	CCA		V		11/29/2068
2020 PO4655932361	KU	4	45 ACE	SP	CCA		V		11/30/2068
2020 PO4664432560	KU	4	45 ACE	SP	CCA		V		12/1/2068
2020 PO4665132578	KU	4	45 ACE	SP	CCA		V		12/2/2068
2020 PO3969730175	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		12/3/2068
2020 PO3952882636	LGE	3	45 BRN	SP	CRE		V		12/4/2068
2020 PO1200721563	ODP	4	40 BRN	SP	CCA		V		12/5/2068

2020 PO3953982638	F	4	30 BRN	SP	A		V	12/6/2068
2020 PO3953482643	F	4	40 BRN	SP	CCA		V	12/7/2068
2020 PO4148931164	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	12/8/2068
2020 PO4113730955	KU	4	40 BRO	SP	CRE	ID,IP	BD	12/9/2068
2020 PO4137431093	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	12/10/2068
2020 PO3953982656	F	3	45 BRN	SP	CRE		V	12/11/2068
2020 PO3954582671	F	3	45 BRN	SP	S		V	12/12/2068
2020 PO6736438214	LGE	3	45 BRN	SP	CCA		V	12/13/2068
2020 PO0457434408	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD	12/14/2068
2020 PO0437934671	ODP	4	40 XXX	SP	CRE	ED,ID	TD	12/15/2068
2020 PO0425034886	ODP	4	40 XXX	SP	CRE	ED,ID	TD	12/16/2068
2020 PO3955582661	F	3	45 BRN	SP	CRE		V	12/17/2068
2020 PO3956982654	F	3	45 BRN	SP	CRE		V	12/18/2068
2020 PO3957682645	F	4	40 BRN	SP	CRE		V	12/19/2068
2020 PO3957282634	F	5	30 BRN	SP	CCA		V	12/20/2068
2020 PO3957882632	F	1	50 BRN	SP	S		V	12/21/2068
2020 PO2631327690	ODP	5	35 BRN	SP	CRE	ID	BD	12/22/2068
2020 PO2612728255	ODP	4	40 BRN	SP	CRE	ID	TD	12/23/2068
2020 PO2620527956	ODP	4	40 BRN	SP	CRE	ID	TD	12/24/2068
2020 Po2620527956a	ODP	4	40 BRN	SP	CRE	ID	TD	12/25/2068
2020 Po2482327730a	ODP	4	40 BRN	SP	CCA		V	12/26/2068
2020 PO3524549729	KU	3	45 ACE	SP	CCA		V	12/27/2068
2020 PO3481449749	KU	3	45 ACE	SP	CCA	ED,ID	TD	12/28/2068
2020 PO3446849765	KU	3	45 ACE	SP	CCA		V	12/29/2068
2020 PO3480749719	KU	3	45 ACE	SP	CCA		V	12/30/2068
2020 PO3476849710	KU	2	50 ACE	SP	CRE	ED,ID,IP,RB	V	12/31/2068
2020 PO3506049599	KU	5	45 ACE	SP	GALV		V	1/1/2069
2020 PO3531649477	KU	3	45 ACE	SP	CCA		V	1/2/2069
2020 PO4026401708	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	1/3/2069
2020 PO4007501712	KU	4	40 BRO	SP	CRE	ED,ID	TD	1/4/2069
2020 PO4584836012	KU	6	30 BRO	SP	CRE	ED,ID	TD	1/5/2069
2020 PO4582336038	KU	3	45 BRO	SP	CRE	ID,IP	BD	1/6/2069
2020 PO3951583051	F	4	40 BRO	SP	P		V	1/7/2069
2020 PO3952083058	F	5	30 BRO	SP	P		V	1/8/2069
2020 PO3950083065	F	4	35 BRO	SP	A		V	1/9/2069
2020 PO3950083056	F	4	40 BRO	SP	A		V	1/10/2069
2020 PO4038782593	LGE	4	40 BRN	SP	A	ED,ID	TD	1/11/2069
2020 PO4037782606	LGE	4	40 BRN	SP	CRE	ED,ID	TD	1/12/2069
2020 PO4036682594	LGE	4	40 BRN	SP	CRE	ED,ID	BD	1/13/2069
2020 PO4037482620	LGE	6	25 BRN	SP	CRE	ED,ID	TD	1/14/2069
2020 0435332963a	ODP	3	40 XXX	SP	CCA		V	1/15/2069
2020 PO0468833182	ODP	4	40 XXX	SP	CCA		V	1/16/2069
2020 PO4581236126	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	1/17/2069
2020 PO3914445026	KU	3	45 BRN	SP	CRE	ED	B	1/18/2069
2020 PO2151741200	ODP	5	35 KOP	SP	A	ED,ID	TD	1/19/2069
2020 PO2142841109	ODP	5	35 KOP	SP	A	ED,EP,ID	TD	1/20/2069
2020 PO2133841212	ODP	4	40 KOP	DF	A	ED,EP,ID	TD	1/21/2069

2020 PO2124941314	ODP	4	45 KOP	SP	A	ID	BD	1/22/2069	
2020 PO2117541459	ODP	6	30 KOP	SP	CRE		V	1/23/2069	
2020 PO2108341467	ODP	5	35 KOP	SP	CRE	ED,ID	TD	1/24/2069	
2020 PO2158540912	ODP	4	45 KOP	SP	S		V	1/25/2069	
2020 PO2152940990	ODP	2	50 KOP	SP	S		V	1/26/2069	
2020 PO2096041645	ODP	4	40 KOP	SP	S		V	1/27/2069	
2020 PO2081841755	ODP	6	30 KOP	SP	S		V	1/28/2069	
2020 PO3945345095	KU	3	45 BRN	SP	CRE		V	1/29/2069	
2020 PO3976545164	KU	3	45 BRN	SP	CRE		V	1/30/2069	
2020 PO4007245233	KU	3	45 BRN	SP	CRE	ED	T	1/31/2069	
2020 PO4011245047	KU	3	45 BRN	SP	CRE	ED,ID	TD	2/1/2069	
2020 PO4000845219	KU	4	40 BRN	SP	CRE	ED,ID	TD	2/2/2069	
2020 PO4027545127	KU	3	45 BRN	SP	CRE	ID	BD	2/3/2069	
2020 PO4044545210	KU	3	45 BRN	SP	CRE	ID	BD	2/4/2069	
2020 PO3832745678	KU	3	45 BRN	SP	CCA		V	2/5/2069	
2020 PO3831945665	KU	3	45 BRN	SP	CCA		V	2/6/2069	
2020 PO3826845579	F	4	40 BRN	SP	CRE		V	2/7/2069	
2020 PO3865545315	F	4	40 BRN	SP	CRE		V	2/8/2069	
2020 PO4911287210	LGE	3	45 OTH	SP	CCA		V	2/9/2069	
2020 PO4804987802	LGE	3	45 BRN	SP	CRE		V	2/10/2069	
2020 PO4804687816	LGE	4	40 BRN	SP	CCA		V	2/11/2069	
2020 PO4804487824	F	4	45 BRN	SP	CCA		V	2/12/2069	
2020 PO4805587822	F	4	40 BRN	SP	CCA		V	2/13/2069	
2020 PO4677189133	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	2/14/2069	
2020 PO4807687810	LGE	4	35 BRN	SP	CCA		V	2/15/2069	
2020 PO4807787801	LGE	4	35 BRN	SP	CRE	ED,ID	TD	2/16/2069	
2020 PO4808887775	LGE	4	40 BRN	SP	CCA	ED,ID	BD	2/17/2069	
2020 PO4677289124	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TX	RR	2/18/2069
2020 PO4881487475	LGE	7	25 XXX	SP	CRE	ID	BD	2/19/2069	
2020 PO4808687791	LGE	4	40 BRN	SP	CRE	ED,ID	BD	2/20/2069	
2020 PO4770787896	LGE	4	40 BRO	SP	CRE	ED	TD	2/21/2069	
2020 PO4770587923	LGE	4	40 BRO	SP	CRE	ED	TD	2/22/2069	
2020 PO4809787779	LGE	4	40 BRN	SP	CRE	ED,ID	BD	2/23/2069	
2020 PO3841445492	F	4	40 BRN	SP	CCA		V	2/24/2069	
2020 PO4804988230	LGE	4	40 BRN	SP	CRE	ED,ID	BX	RR	2/25/2069
2020 PO3844645284	KU	4	40 BRN	SP	CRE	ID	BD	2/26/2069	
2020 PO3856045203	KU	4	40 BRN	SP	CRE	ED,ID,MD	TD	2/27/2069	
2020 PO3864245146	KU	4	40 BRN	SP	CRE	ED,ID,RB	X	RP2	2/28/2069
2020 PO3870145027	KU	4	40 BRN	SP	CRE	ID	BD	3/1/2069	
2020 PO3858245395	F	4	40 BRN	SP	A		V	3/2/2069	
2020 PO387145190	F	4	40 BRN	SP	A		V	3/3/2069	
2020 PO3890745044	F	4	40 BRN	SP	CRE		V	3/4/2069	
2020 PO6664841988	LGE	4	30 BRO	SP	CCA		V	3/5/2069	
2020 PO3947183027	F	4	40 BRO	SP	A		V	3/6/2069	
2020 PO3946983010	F	4	30 BRO	SP	P		V	3/7/2069	
2020 PO3945683017	LGE	4	30 BRO	SP	P	ED,ID	TD	3/8/2069	
2020 PO3946383012	F	4	40 BRO	SP	P		V	3/9/2069	

2020 PO3947883041	F	3	40 BRO	SP	CCA		V	3/10/2069
2020 PO3945582998	F	3	45 BRO	SP	CCA		V	3/11/2069
2020 PO0435332963	ODP	4	40 XXX	SP	CCA		V	3/12/2069
2020 PO0408732949	ODP	4	40 XXX	SP	CRE	ED,ID	TD	3/13/2069
2020 PO0386933055	ODP	4	40 XXX	SP	CRE	ED,ID	TD	3/14/2069
2020 PO4805988241	LGE	4	40 BRN	SP	CRE	ED,ID	BD	3/15/2069
2020 PO4806488247	LGE	4	40 BRN	SP	CRE	ED,ID	BD	3/16/2069
2020 PO4806088252	LGE	4	30 BRN	SP	CRE	ED	BX	3/17/2069
2020 PO4806488261	LGE	4	40 BRN	SP	CRE	ED,ID	BD	3/18/2069
2020 PO4829486425	F	3	50 XXX	SP	A		V	3/19/2069
2020 PO0072033331	ODP	5	35 XXX	SP	CRE	ED,ID	TD	3/20/2069
2020 PO3868282378	LGE	1	70 BRO	AL	CCA		V	3/21/2069
2020 PO3868782401	LGE	2	65 BRO	SP	CCA		V	3/22/2069
2020 PO3838182404	LGE	4	40 BRO	SP	CCA		V	3/23/2069
2020 PO3866682411	LGE	4	40 BRO	SP	CCA		V	3/24/2069
2020 PO3865782399	LGE	2	90 BRO	SP	CCA		V	3/25/2069
2020 PO3864582438	LGE	4	40 BRO	SP	CCA		V	3/26/2069
2020 PO5819735755	LGE	3	45 BRO	SP	CCA		V	3/27/2069
2020 PO5817335578	LGE	3	45 BRO	SP	CCA		V	3/28/2069
2020 PO5814235327	LGE	3	45 BRO	SP	CCA		V	3/29/2069
2020 PO5811335108	LGE	3	45 BRO	SP	CCA		V	3/30/2069
2020 PO3913582705	F	4	35 BRO	SP	CCA		V	3/31/2069
2020 PO3914282700	F	4	40 BRO	SP	CCA		V	4/1/2069
2020 PO3914782719	F	4	25 BRO	SP	CCA		V	4/2/2069
2020 PO3915082707	F	4	40 BRO	SP	CCA		V	4/3/2069
2020 PO3916382712	F	4	30 BRO	SP	CCA		V	4/4/2069
2020 PO3915982704	F	4	40 BRO	SP	CCA		V	4/5/2069
2020 PO3917082699	F	4	40 BRO	SP	CCA		V	4/6/2069
2020 PO1981843577	ODP	5	35 KOP	SP	CRE	ED,EP,ID,SRC	TD	4/7/2069
2020 PO1961543964	ODP	4	40 KOP	SP	A	ED,ID	TD	4/8/2069
2020 PO3941183055	F	4	40 BRO	SP	A		V	4/9/2069
2020 PO3942783048	F	4	40 BRO	SP	A		V	4/10/2069
2020 PO3931782041	F	4	40 CAH	SP	CRE		V	4/11/2069
2020 PO3943083082	F	5	25 BRO	SP	A		V	4/12/2069
2020 PO3942983089	F	4	40 BRO	SP	A		V	4/13/2069
2020 PO3942983094	F	4	30 BRO	SP	A		V	4/14/2069
2020 PO3930682046	F	4	40 CAH	SP	CRE		V	4/15/2069
2020 PO3929882052	F	4	40 CAH	SP	CCA		V	4/16/2069
2020 PO3929882059	F	4	40 CAH	SP	CRE		V	4/17/2069
2020 PO3941183081	F	5	25 BRO	SP	A		V	4/18/2069
2020 PO3941183088	F	4	40 BRO	SP	P		V	4/19/2069
2020 PO3939583086	F	5	25 BRO	SP	A		V	4/20/2069
2020 PO3930782083	LGE	4	40 CAH	SP	P	ED,ID	T	4/21/2069
2020 PO3930382071	F	4	40 CAH	SP	CRE		V	4/22/2069
2020 PO3931282093	F	4	40 CAH	SP	CCA		V	4/23/2069
2020 PO3931782104	F	4	40 CAH	SP	CCA		V	4/24/2069
2020 PO3932282115	F	4	40 CAH	SP	CCA		V	4/25/2069

2020 PO3932682122	F	4	40 CAH	SP	CRE		V		4/26/2069
2020 PO3933382124	F	4	40 CAH	SP	CRE		V		4/27/2069
2020 PO3934582119	F	4	40 CAH	SP	CCA		V		4/28/2069
2020 PO3937082108	F	4	40 CAH	SP	CCA		V		4/29/2069
2020 PO3938182102	F	4	40 CAH	SP	CCA		V		4/30/2069
2020 PO3938482109	F	4	25 CAH	SP	CRE		V		5/1/2069
2020 PO3939782099	F	4	25 CAH	SP	CRE		V		5/2/2069
2020 PO4026482831	F	4	40 BRN	SP	CRE		V		5/3/2069
2020 PO3939283135	F	4	40 BRO	SP	P		V		5/4/2069
2020 PO3940883131	F	4	40 BRO	SP	A		V		5/5/2069
2020 PO3942083125	LGE	4	35 BRO	SP	CCA		V		5/6/2069
2020 PO3942483129	F	4	40 BRO	SP	P		V		5/7/2069
2020 PO3943483127	F	4	40 BRO	SP	A		V		5/8/2069
2020 PO3942683117	LGE	4	30 BRO	SP	CCA		V		5/9/2069
2020 PO3940383094	F	5	30 BRO	SP	P		V		5/10/2069
2020 PO3939783093	F	4	40 BRO	SP	P		V		5/11/2069
2020 PO3938483099	F	4	40 BRO	SP	P		V		5/12/2069
2020 PO3936983106	F	4	40 BRO	SP	P		V		5/13/2069
2020 PO0029234221	ODP	6	25 XXX	SP	CRE	ED,ID,IP	TD		5/14/2069
2020 PO0042834229	ODP	5	30 XXX	SP	CRE	RB	X	RP1	5/15/2069
2020 PO4025982822	F	4	40 BRN	SP	CRE		V		5/16/2069
2020 PO4023282845	F	4	40 BRN	SP	A		V		5/17/2069
2020 PO1929344642	ODP	4	45 BRN	SP	CRE		V		5/18/2069
2020 PO4021382793	F	4	40 BRN	SP	CRE		V		5/19/2069
2020 PO4022382781	F	4	40 BRN	SP	CRE		V		5/20/2069
2020 PO4022782776	F	4	40 BRN	SP	A		V		5/21/2069
2020 PO9400173096	KU	4	40 XXX	SP	CRE	HH,ID,RB	TX	RR	5/22/2069
2020 PO4575236765	KU	3	45 BRO	SP	CCA		V		5/23/2069
2020 PO4561236642	KU	2	45 BRO	SP	CCA		V		5/24/2069
2020 PO4604337053	KU	3	45 BRO	SP	A		V		5/25/2069
2020 PO3936482128	F	3	45 CAH	SP	CCA		V		5/26/2069
2020 PO0079133751	ODP	6	30 XXX	SP	CCA		V		5/27/2069
2020 PO0063233738	ODP	6	30 XXX	SP	CRE	ED,ID,IP	TD		5/28/2069
2020 PO0053133872	ODP	4	40 XXX	SP	CCA		V		5/29/2069
2020 PO0050033769	ODP	4	40 XXX	SP	CCA		V		5/30/2069
2020 PO0045933625	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD		5/31/2069
2020 PO3939582130	F	6	30 CAH	SP	A		V		6/1/2069
2020 PO3939782135	F	4	40 CAH	SP	CCA		V		6/2/2069
2020 PO3940982124	F	4	30 CAH	SP	CRE		V		6/3/2069
2020 PO3941182128	F	4	40 CAH	SP	CCA		V		6/4/2069
2020 PO3939082144	F	3	45 CAH	SP	CCA		V		6/5/2069
2020 PO3939382152	F	3	45 CAH	SP	CCA		V		6/6/2069
2020 PO3938882139	F	4	40 CAH	SP	A		V		6/7/2069
2020 PO3942682142	F	6	25 CAH	SP	CCA		V		6/8/2069
2020 PO3945082152-A	F	6	30 CAH	SP	CCA		V		6/9/2069
2020 PO3945782149	F	6	25 CAH	SP	CCA		V		6/10/2069
2020 PO3944282137	F	6	25 CAH	SP	CCA		V		6/11/2069

2020 PO3945082152	F	3	45 CAH	SP	CCA		V			6/12/2069
2020 PO3944182145	F	3	45 CAH	SP	CCA		V			6/13/2069
2020 PO3942982149	F	3	45 CAH	SP	CCA		V			6/14/2069
2020 PO3941782159	F	4	30 BRN	SP	CRE		V			6/15/2069
2020 PO3941482155	F	4	40 BRN	SP	CRE		V			6/16/2069
2020 PO3940782173	F	6	25 BRN	SP	CCA		V			6/17/2069
2020 PO3940382166	F	4	30 BRN	SP	CCA		V			6/18/2069
2020 PO3939882163	F	4	40 BRN	SP	CRE		V			6/19/2069
2020 PO3938882172	F	4	30 BRN	SP	CCA		V			6/20/2069
2020 PO3938282171	F	4	40 BRN	SP	CRE		V			6/21/2069
2020 PO6575333445	LGE	4	35 BRN	SP	CRE		V			6/22/2069
2020 PO3936482171	F	6	25 BRN	SP	CCA		V			6/23/2069
2020 PO3936882177	F	3	45 BRN	SP	CCA		V			6/24/2069
2020 PO3937482179	F	4	30 BRN	SP	CCA		V			6/25/2069
2020 PO3934882182	F	4	30 BRN	SP	CCA		V			6/26/2069
2020 PO3935582185	F	4	40 BRN	SP	CCA		V			6/27/2069
2020 PO3934782197	F	6	25 BRN	SP	CCA		V			6/28/2069
2020 PO3935482196	F	4	40 BRN	SP	CRE		V			6/29/2069
2020 PO9409373044	KU	6	30 XXX	SP	P	ED	T			6/30/2069
2020 PO9411172944	KU	4	40 XXX	SP	CRE	ED,ID,RB	TX		RR	7/1/2069
2020 PO3939678665	KU	2	60 KOP	DF	CRE		V			7/2/2069
2020 PO3934579093	KU	6	30 KOP	SP	S		V			7/3/2069
2020 PO3934579093B	KU	H1	70 KOP	ST	S		V			7/4/2069
2020 PO3934579093	KU	H1	70 KOP	ST	S		V			7/5/2069
2020 PO3944978288	KU	2	60 KOP	SP	CRE		V			7/6/2069
2020 PO3945078236	KU	2	60 KOP	SP	CRE		V			7/7/2069
2020 PO3934478328	KU	2	55 KOP	SP	S		V			7/8/2069
2020 PO3928678331	KU	2	65 KOP	ST	CCA		V			7/9/2069
2020 PO4815987751	LGE	4	40 BRO	SP	CRE	ED	BD			7/10/2069
2020 PO4816687738	LGE	4	40 BRO	SP	CRE	ED	TD			7/11/2069
2020 PO4813887791	LGE	4	40 BRO	SP	CCA		V			7/12/2069
2020 PO4814487780	LGE	4	40 BRO	SP	CCA		V			7/13/2069
2020 PO4815287765	LGE	4	40 BRO	SP	CCA		V			7/14/2069
2020 PO4797288232	LGE	4	35 BRN	SP	A	ED,ID	TD			7/15/2069
2020 PO4795888224-A	LGE	4	35 BRN	SP	A	ED,ID	BD			7/16/2069
2020 PO1859046625	ODP	3	45 BRN	SP	CCA		V			7/17/2069
2020 PO4820988351	LGE	4	35 BRO	SP	CRE	ED,HH,ID	BX		RP2	7/18/2069
2020 PO1850446852	ODP	3	45 BRN	SP	CCA		V			7/19/2069
2020 PO1878345202	ODP	4	40 BRN	SP	CCA		V			7/20/2069
2020 PO1875745356	ODP	4	40 BRN	SP	CRE		V			7/21/2069
2020 PO1872045610	ODP	4	40 BRN	SP	CRE		V			7/22/2069
2020 PO1860946449	ODP	5	35 BRN	SP	CCA		V			7/23/2069
2020 PO1873945482	ODP	4	40 BRN	SP	CCA		V			7/24/2069
2020 PO1866446638	ODP	6	30 BRN	SP	CCA		V			7/25/2069
2020 PO1861046876	ODP	5	35 BRN	SP	CCA		V			7/26/2069
2020 PO1877845895	ODP	4	40 BRN	SP	CCA		V			7/27/2069
2020 PO1913744686	ODP	4	45 BRN	SP	CCA		V			7/28/2069

2020 PO1861746325	ODP	3	45 BRN	SP	CCA		V	7/29/2069
2020 PO1970343965	ODP	4	40 KOP	SP	CRE	ED,ID	TD	7/30/2069
2020 PO1980843811	ODP	5	35 KOP	SP	CRE	ED,ID	TD	7/31/2069
2020 PO1988043673	ODP	4	45 KOP	SP	CRE	ED,EP,ID	TD	8/1/2069
2020 PO4592636945	KU	3	45 BRO	SP	P	ED	T	8/2/2069
2020 PO4565336905	KU	3	45 BRO	SP	CCA		V	8/3/2069
2020 PO4561537034	KU	3	45 BRO	SP	CCA		V	8/4/2069
2020 PO4024782814	F	4	40 BRN	SP	CRE		V	8/5/2069
2020 PO4820388361	LGE	4	35 BRO	SP	CRE	ED	BD	8/6/2069
2020 PO4821288365	LGE	4	35 BRO	SP	CRE	ED	BD	8/7/2069
2020 PO4819188355	LGE	4	35 BRO	SP	CCA	ED	V	8/8/2069
2020 PO4788588188	LGE	4	40 BRN	SP	A	ED,ID	BD	8/9/2069
2020 PO4669688783	LGE	4	40 BRO	SP	CRE	ED	TD	8/10/2069
2020 PO4670288763	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/11/2069
2020 PO4785688179	LGE	4	40 BRN	SP	A	ED,ID	BD	8/12/2069
2020 PO4782888168	LGE	4	40 BRN	SP	A	ED,ID	BD	8/13/2069
2020 PO4816788333	LGE	4	30 BRO	SP	CRE	ED	TD	8/14/2069
2020 PO4819988299	LGE	4	30 BRO	SP	CRE	ED	BD	8/15/2069
2020 PO4815588345	LGE	4	30 BRO	SP	CRE	ED	TD	8/16/2069
2020 PO4819588347	LGE	4	30 BRO	SP	CRE		B	8/17/2069
2020 PO4820488337	LGE	4	30 BRO	SP	CRE	ED	BD	8/18/2069
2020 PO4823588293	LGE	4	35 BRO	SP	CRE	ED	BD	8/19/2069
2020 PO6134946292	KU	4	40 OTH	SP	CRE	ED,SRS	TD	8/20/2069
2020 PO6137945908	KU	4	40 OTH	SP	CRE	ED,SRS	TD	8/21/2069
2020 PO6160046122	KU	4	45 OTH	SP	CRE	ED,SRS	TD	8/22/2069
2020 PO4024282781	F	4	40 BRN	SP	CRE		V	8/23/2069
2020 PO4025782786	F	4	40 BRN	SP	A		V	8/24/2069
2020 PO4027082791	F	4	40 BRN	SP	CRE		V	8/25/2069
2020 PO3938382135	LGE	4	30 BRN	SP	CRE	ED,ID	TD	8/26/2069
2020 PO3937482140	LGE	4	35 BRN	SP	CRE	ED,ID	TD	8/27/2069
2020 PO3936882139	F	3	45 BRN	SP	CRE		V	8/28/2069
2020 PO3937282147	F	3	45 BRN	SP	CRE		V	8/29/2069
2020 PO3935782153	F	4	40 BRN	SP	CCA		V	8/30/2069
2020 PO3934282160	F	3	45 BRN	SP	CCA		V	8/31/2069
2020 PO3932982160	F	4	30 BRN	SP	A		V	9/1/2069
2020 PO3934182154	F	4	30 BRN	SP	CRE		V	9/2/2069
2020 PO3935582148	F	4	30 BRN	SP	CCA		V	9/3/2069
2020 PO3931782171	F	4	45 BRN	SP	CCA		V	9/4/2069
2020 PO6499233319	F	4	40 BRN	SP	CRE		V	9/5/2069
2020 PO3921382162	LGE	4	35 BRN	SP	CRE		V	9/6/2069
2020 PO3921782175	LGE	4	35 BRN	SP	CRE		V	9/7/2069
2020 PO3922282077	LGE	4	40 BRN	SP	CRE		V	9/8/2069
2020 PO3923282177	LGE	4	35 BRN	SP	CRE		V	9/9/2069
2020 PO3922882192	LGE	4	35 BRN	SP	A		V	9/10/2069
2020 PO3918782205	F	4	30 BRN	SP	CCA		V	9/11/2069
2020 PO3919182207	LGE	4	35 BRN	SP	P		V	9/12/2069
2020 PO3920482202	LGE	4	35 BRN	SP	A		V	9/13/2069

2020 PO3921382207	LGE	4	35 BRN	SP	CCA		V	9/14/2069
2020 PO3922282199	LGE	4	35 BRN	SP	A		V	9/15/2069
2020 PO6401233765	LGE	4	45 BRN	SP	A	ED,ID	BD	9/16/2069
2020 PO3921282218	F	4	35 BRN	SP	CRE		V	9/17/2069
2020 PO3923182210	F	3	40 BRN	SP	CCA		V	9/18/2069
2020 PO3924982201	F	4	35 BRN	SP	CRE		V	9/19/2069
2020 PO3926682194	F	4	40 BRN	SP	A		V	9/20/2069
2020 PO3928582185	F	4	40 BRN	SP	CRE		V	9/21/2069
2020 PO3929782180	F	4	40 BRN	SP	CRE		V	9/22/2069
2020 PO3929182164	F	3	45 BRN	SP	CCA		V	9/23/2069
2020 PO3928682151	F	4	40 BRN	SP	CCA		V	9/24/2069
2020 PO3927582126	F	4	40 BRN	SP	CCA		V	9/25/2069
2020 PO3928182138	F	4	40 BRN	SP	P		V	9/26/2069
2020 PO4027682772	F	3	45 BRN	SP	CRE		V	9/27/2069
2020 PO0039833394	ODP	6	30 XXX	SP	CRE	ED,ID	TD	9/28/2069
2020 PO0045533282	ODP	5	30 XXX	SP	CCA		V	9/29/2069
2020 PO0055633291	ODP	4	40 XXX	SP	CRE	ED,ID	TD	9/30/2069
2020 PO4026182768	F	4	40 BRN	SP	CRE		V	10/1/2069
2020 PO4025182764	F	4	40 BRN	SP	CRE		V	10/2/2069
2020 PO4023682759	F	3	45 BRN	SP	S		V	10/3/2069
2020 PO4527437289	KU	4	40 BRO	SP	CRE	ED	T	10/4/2069
2020 PO4518937371	KU	4	45 BRO	SP	P	ED	T	10/5/2069
2020 PO4510237281	KU	4	45 BRO	SP	CRE	ED	T	10/6/2069
2020 PO4016782751	F	4	40 BRN	SP	CRE	ED,RB	VX	PX 10/7/2069
2020 PO4015482645	LGE	4	30 BRN	SP	CRE		V	10/8/2069
2020 PO4015382755	LGE	4	40 BRN	SP	A	ED,ID	BD	10/9/2069
2020 PO4016782756	LGE	4	30 BRN	SP	CCA		V	10/10/2069
2020 PO4017282753	F	4	40 BRN	SP	CCA		V	10/11/2069
2020 PO4501737196	KU	4	45 BRO	SP	CCA		V	10/12/2069
2020 PO4504337223	KU	4	45 BRO	SP	CCA		V	10/13/2069
2020 PO4502337166	KU	4	45 BRO	SP	CCA		V	10/14/2069
2020 PO4495237225	KU	4	45 BRO	SP	CCA		V	10/15/2069
2020 9985731048c	ODP	4	45 XXX	SP	CCA		V	10/16/2069
2020 9985731048b	ODP	4	45 XXX	SP	CCA		V	10/17/2069
2020 9985731048a	ODP	4	45 XXX	SP	CCA		V	10/18/2069
2020 PO9990930314	ODP	6	30 XXX	SP	CCA		V	10/19/2069
2020 PO9961130489	ODP	4	45 XXX	SP	CCA		V	10/20/2069
2020 PO9964430968	ODP	4	45 XXX	SP	CCA		V	10/21/2069
2020 PO3935483112	F	4	40 BRO	SP	A		V	10/22/2069
2020 PO3934083119	F	4	40 BRO	SP	P		V	10/23/2069
2020 PO4017882762	LGE	4	30 BRN	SP	A	ED,ID	TD	10/24/2069
2020 PO4018382759	F	4	40 BRN	SP	CRE	RB	VX	PX 10/25/2069
2020 PO4527437289-A	KU	2	45 BRO	SP	CCA		V	10/26/2069
2020 PO9985731048	ODP	3	45 XXX	SP	CCA		V	10/27/2069
2020 PO3933383122	F	4	40 BRO	SP	P		V	10/28/2069
2020 PO3936583168	F	4	40 BRO	SP	P		V	10/29/2069
2020 PO3938283165	F	4	40 BRO	SP	A		V	10/30/2069

2020 PO3939683162	F	4	40 BRO	SP	P		V		10/31/2069
2020 PO3941283160	F	4	40 BRO	SP	CCA		V		11/1/2069
2020 PO4018982768	LGE	4	30 BRN	SP	CRE	ED,ID	TD		11/2/2069
2020 PO4537837564	KU	2	45 BRO	SP	CRE	ED	TD		11/3/2069
2020 PO4541537529	KU	2	45 BRO	SP	CRE	ED,ID,IP	TD		11/4/2069
2020 PO0003731131	ODP	5	35 XXX	SP	CCA		V		11/5/2069
2020 PO0025531250	ODP	4	45 XXX	SP	CRE	ED,ID,RB	X	RP1	11/6/2069
2020 PO0060531518	ODP	4	40 XXX	SP	CRE	ID,RB	X	RP1	11/7/2069
2020 PO4019482765	F	3	45 BRN	SP	S		V		11/8/2069
2020 PO4552937423	KU	2	45 BRO	SP	CRE	ID,IP	BD		11/9/2069
2020 PO4020382771	F	4	40 BRN	SP	A		V		11/10/2069
2020 PO4557537378	KU	2	45 BRO	SP	CCA		V		11/11/2069
2020 PO4020682772	F	4	40 BRN	SP	A		V		11/12/2069
2020 PO2063941838	ODP	4	45 KOP	SP	CRE	ED,ID	TD		11/13/2069
2020 PO2056142005	ODP	2	55 KOP	SP	A	ID	BD		11/14/2069
2020 20565-42356A	ODP	4	40 KOP	SP	A	ED,ID,SRC	TD		11/15/2069
2020 PO2059242547	ODP	5	35 KOP	SP	S		V		11/16/2069
2020 PO2051242433	ODP	3	40 KOP	SP	S		V		11/17/2069
2020 PO4550137693	KU	2	45 BRO	SP	CRE	ED,ID	TD		11/18/2069
2020 PO4527937461	KU	4	45 BRO	SP	P	ED	T		11/19/2069
2020 PO4005782613	LGE	3	45 BRN	SP	S		V		11/20/2069
2020 PO4006982610	LGE	4	40 BRN	SP	S		V		11/21/2069
2020 PO9764337961	ODP	5	35 BRN	SP	CRE		V		11/22/2069
2020 PO4010882539	LGE	4	40 BRN	SP	CRE	ED,ID	TD		11/23/2069
2020 PO4011182523	LGE	4	40 BRN	SP	A	ED,ID	TD		11/24/2069
2020 PO2056542356	ODP	4	40 BRN	SP	CRE	ID	BD		11/25/2069
2020 PO9840938320	ODP	3	45 BRN	SP	CCA		V		11/26/2069
2020 PO9884838205A	ODP	3	45 BRN	SP	CCA		V		11/27/2069
2020 PO4692887569	F	4	40 BRO	SP	CRE		V		11/28/2069
2020 PO4691887583	F	4	40 BRO	SP	CRE		V		11/29/2069
2020 PO4694287550	F	4	40 BRO	SP	CRE		V		11/30/2069
2020 PO4693387544	LGE	4	30 BRO	SP	CRE	ED,ID	TD		12/1/2069
2020 PO4692387537	LGE	4	35 BRO	SP	A	ED,ID	BD		12/2/2069
2020 PO4687887514	LGE	4	40 BRO	SP	CRE	ED,ID	BD		12/3/2069
2020 PO9251927962	ODP	4	40 XXX	SP	CRE	ID	BD		12/4/2069
2020 PO9242327955	ODP	6	30 XXX	SP	CCA		V		12/5/2069
2020 PO9251927962	ODP	4	40 XXX	SP	CRE	ID	TD		12/6/2069
2020 PO9222527903	ODP	4	40 XXX	SP	CRE	ID	BD		12/7/2069
2020 PO9217927755	ODP	4	40 XXX	SP	CRE	ID	TD		12/8/2069
2020 PO9199627617	ODP	5	35 XXX	SP	CRE	ID	TD		12/9/2069
2020 PO2738244409A	ODP	5	35 ACW	SP	CRE	ED,ID	TD		12/10/2069
2020 PO2479440724	ODP	5	35 ACW	SP	CRE	ED,ID	TD		12/11/2069
2020 PO4706788245	LGE	3	45 BRO	SP	CCA		V		12/12/2069
2020 PO4707188234	LGE	1	70 BRO	SP	A		V		12/13/2069
2020 PO4707088231	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD		12/14/2069
2020 PO4709088238	LGE	4	40 BRO	SP	CRE	ED,ID	BD		12/15/2069
2020 PO4710088242	LGE	4	40 BRO	SP	CRE	ED,ID	BD		12/16/2069

2020 PO4710888247	LGE	2	45 BRO	SP	CRE	ED,ID	TD	12/17/2069
2020 PO4711088241	LGE	4	30 BRO	SP	CCA		V	12/18/2069
2020 PO4711188242	LGE	4	35 BRO	SP	P	ED,ID	BD	12/19/2069
2020 PO4709988270	LGE	3	45 BRO	SP	CCA		V	12/20/2069
2020 PO4711188246	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	12/21/2069
2020 PO4741517071	F	4	40 ACE	SP	CRE		V	12/22/2069
2020 PO4750417127	F	4	40 ACE	SP	CRE		V	12/23/2069
2020 PO4757617207	F	4	40 ACE	SP	CRE		V	12/24/2069
2020 PO4720516919	F	4	40 ACE	SP	CRE		V	12/25/2069
2020 PO4729416866	F	4	40 ACE	SP	CRE		V	12/26/2069
2020 PO4644588339	LGE	4	30 BRO	SP	CRE	ED,ID	TD	12/27/2069
2020 PO4644588348	LGE	4	40 BRO	SP	CRE		V	12/28/2069
2020 PO4711988249	LGE	4	40 BRO	SP	CRE	ED,ID	TD	12/29/2069
2020 PO4712988253	LGE	4	40 BRO	SP	A	ED,ID	BD	12/30/2069
2020 PO4712988253a	LGE	4	45 BRO	SP	A	ED,ID	BD	12/31/2069
2020 PO4714788238	LGE	4	40 BRO	SP	A	ED,ID	BD	1/1/2070
2020 PO0513145342	ODP	6	30 XXX	SP	CCA		V	1/2/2070
2020 PO0323038501	ODP	4	40 XXX	SP	CCA		V	1/3/2070
2020 PO8937827230	ODP	5	35 XXX	SP	CRE	ID	TD	1/4/2070
2020 PO8936826903	ODP	5	35 XXX	SP	CRE		V	1/5/2070
2020 PO8934726655	ODP	5	35 XXX	SP	CRE	HH,ID	X PX	1/6/2070
2020 PO9392693496	KU	6	30 BRN	SP	CRE	ED,ID	TD	1/7/2070
2020 PO9385793484	KU	4	40 BRN	SP	CRE	ED,ID	TD	1/8/2070
2020 PO9364393439	KU	4	45 BRN	SP	CRE	ED,ID,IP	TD	1/9/2070
2020 PO9354793357	KU	4	45 BRN	SP	CRE	ED,ID	TD	1/10/2070
2020 PO9230993957	KU	4	40 BRN	SP	CRE	ED,ID,RB	BX PX	1/11/2070
2020 PO9223893707A	KU	5	35E BRN	SP	P	ED,ID	TD	1/12/2070
2020 PO9246593527	KU	4	40 BRN	SP	CCA	ED	TD	1/13/2070
2020 PO9234493538	KU	6	30 BRN	SP	CRE	ED,ID	TD	1/14/2070
2020 PO9262893498	C	4	40 BRN	SP	CRE		V	1/15/2070
2020 PO9278093600	KU	6	30 BRN	SP	CRE	ED,ID	TD	1/16/2070
2020 PO9267693525	KU	4	40 BRN	SP	CRE	ED,ID	TD	1/17/2070
2020 PO9280893539	KU	6	30 BRN	SP	CRE	ED,ID	TD	1/18/2070
2020 PO9285293457	KU	6	30 BRN	SP	CRE	ED,ID	TD	1/19/2070
2020 PO9274193434	KU	4	40 BRN	SP	CRE	ED,ID	TD	1/20/2070
2020 PO9258493410	KU	4	40 BRN	SP	CRE	ED,ID	TD	1/21/2070
2020 PO5329346289	KU	6	35 ACE	SP	CRE		V	1/22/2070
2020 PO5461746745	F	1	20 ACE	SP	A		V	1/23/2070
2020 PO3993006163	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	1/24/2070
2020 PO4008005985	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	1/25/2070
2020 PO4033505624	KU	4	40 BRO	SP	CRE	ED,ID	TD	1/26/2070
2020 PO4081305163	KU	4	40 BRO	SP	CCA		V	1/27/2070
2020 PO5397446883	KU	4	35 ACE	SP	CRE	ED,ID	TD	1/28/2070
2020 PO5399846808	KU	4	45 ACE	SP	CCA		V	1/29/2070
2020 PO9339487697	KU	4	40 XXX	SP	CRE	ED,ID	TD	1/30/2070
2020 PO5423646878	KU	4	40 ACE	SP	CRE	ED,ID	TD	1/31/2070
2020 PO5445346873	KU	4	40 ACE	SP	CRE	ED,ID	TD	2/1/2070

2020 PO5461446796	KU	4	45 ACE	SP	CRE	ED,ID	TD	2/2/2070
2020 PO5460146896	KU	2	60 ACE	SP	CRE		V	2/3/2070
2020 PO5460046877	KU	1	65 ACE	SP	CCA		V	2/4/2070
2020 PO5460246857	KU	1	65 ACE	SP	CRE		V	2/5/2070
2020 PO5493546903	KU	1	60 ACE	SP	CCA		V	2/6/2070
2020 PO5486746714	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	2/7/2070
2020 PO4766688610	F	4	40 BRO	SP	CCA		V	2/8/2070
2020 PO9223893707	KU	5	35 BRN	SP	CRE	ED,ID	TD	2/9/2070
2020 PO4765788615	F	4	40 BRO	SP	CCA		V	2/10/2070
2020 PO4765088655	F	4	40 BRO	SP	CCA		V	2/11/2070
2020 PO4766288647	F	3	45 BRO	SP	CCA		V	2/12/2070
2020 PO4768788630	F	4	40 BRO	SP	CCA		V	2/13/2070
2020 PO4769488624	F	3	45 BRO	SP	A		V	2/14/2070
2020 PO4767488639	F	4	40 BRO	SP	CCA		V	2/15/2070
2020 PO4763988627	F	4	40 BRO	SP	CCA		V	2/16/2070
2020 PO4761988605	F	4	40 BRO	SP	CCA		V	2/17/2070
2020 PO4763888592	F	4	40 BRO	SP	CCA		V	2/18/2070
2020 PO4766388576	F	3	40 BRO	SP	CCA		V	2/19/2070
2020 PO4764688623	F	4	40 BRO	SP	CCA		V	2/20/2070
2020 PO4763988613	F	4	40 BRO	SP	CCA		V	2/21/2070
2020 PO4763188600	F	4	40 BRO	SP	CCA		V	2/22/2070
2020 PO4762988598	F	UNK	35 BRO	SP	CCA		V	2/23/2070
2020 PO4763688488	F	4	30 BRO	SP	CCA		V	2/24/2070
2020 PO4764388499	F	4	30 BRO	SP	CCA		V	2/25/2070
2020 PO4762788477	F	4	30 BRO	SP	CCA		V	2/26/2070
2020 PO4761888465	F	4	30 BRO	SP	CCA		V	2/27/2070
2020 PO4760688457	LGE	4	40 BRO	SP	CCA		V	2/28/2070
2020 PO4761088453	LGE	4	35 BRO	SP	A		V	3/1/2070
2020 PO4759988448	F	4	40 BRO	SP	CCA		V	3/2/2070
2020 PO4759788444	F	4	40 BRO	SP	CCA		V	3/3/2070
2020 PO4758388453	F	4	40 BRO	SP	CCA		V	3/4/2070
2020 PO4637788302	LGE	4	40 BRO	SP	CRE	ED,ID	TD	3/5/2070
2020 PO4635888319	LGE	4	30E BRO	SP	A	ED,ID	TD	3/6/2070
2020 PO4635488317	LGE	4	40 BRO	SP	P	ED,ID	TD	3/7/2070
2020 PO8881326343A	ODP	4	40 XXX	SP	CRE	ID	TD	3/8/2070
2020 PO8830626324	ODP	4	40 XXX	SP	CCA		V	3/9/2070
2020 PO8776826188	ODP	4	40 XXX	SP	CCA		V	3/10/2070
2020 PO8794325710	ODP	4	40 XXX	SP	CCA	ID	V	3/11/2070
2020 PO8780125474	ODP	5	35 XXX	SP	CRE	ID	TD	3/12/2070
2020 PO8780125474A	ODP	5	30 XXX	SP	CRE	ID	TD	3/13/2070
2020 PO8733324643	ODP	5	35 XXX	SP	CRE	ID	TD	3/14/2070
2020 PO8758125079	ODP	5	35 XXX	SP	CRE	ID	TD	3/15/2070
2020 PO8768825278	ODP	5	35 XXX	SP	CRE	HH,IP	X	3/16/2070
2020 PO8881326343	ODP	4	40 XXX	SP	CRE	ID	TD	3/17/2070
2020 PO9189530289	ODP	5	35 XXX	SP	CCA		V	3/18/2070
2020 PO9210530159	ODP	4	45 XXX	SP	CRE	ID	TD	3/19/2070
2020 PO5442461899	F	3	45 OTH	SP	P		V	3/20/2070

Business Use

2020 PO5011261518	F	4	45 OTH	SP	P		V			3/21/2070	
2020 PO4906960917	F	3	45 OTH	SP	P		V			3/22/2070	
2020 PO5367361873	F	4	50 OTH	SP	CRE		V			3/23/2070	
2020 PO5328061868	F	3	45 OTH	SP	CRE		V			3/24/2070	
2020 PO4977861328	F	3	45 OTH	SP	P		V			3/25/2070	
2020 PO5038461678	F	4	45 OTH	SP	P		V			3/26/2070	
2020 PO5253461844	F	3	45 OTH	SP	P		V			3/27/2070	
2020 PO5093061788	F	3	45 OTH	SP	P		V			3/28/2070	
2020 PO5122061797	KU	3	45 BRN	SP	CCA		V			3/29/2070	
2020 PO4871760717	F	3	45 OTH	SP	P		V			3/30/2070	
2020 PO5422361893	F	3	45 OTH	SP	CCA		V			3/31/2070	
2020 PO4931961061	F	4	45 OTH	SP	P		V			4/1/2070	
2020 PO5295361856	F	4	40 OTH	SP	CRE		V			4/2/2070	
2020 PO5182361819	F	3	45 OTH	SP	P		V			4/3/2070	
2020 PO5151261805	F	3	45 OTH	SP	P		V			4/4/2070	
2020 PO5063661758	F	3	45 OTH	SP	P		V			4/5/2070	
2020 PO9265093343	KU	6	30 BRN	SP	CRE	ED,ID			TD	4/6/2070	
2020 PO9284693332	KU	4	40 BRN	SP	S				V	4/7/2070	
2020 PO9208093622	KU	5	30 BRN	SP	CRE	ED,ID			TD	4/8/2070	
2020 PO9201393510	KU	3	50 BRN	SP	CRE	ID			TD	4/9/2070	
2020 PO9195693688	KU	4	45 BRN	SP	CRE	ED,ID,RB,SRC			TX	RR	4/10/2070
2020 PO4955561201	F	4	45 OTH	SP	P		V			4/11/2070	
2020 PO4885060797	F	3	45 OTH	SP	P		V			4/12/2070	
2020 PO5216161830	F	3	45 OTH	SP	P		V			4/13/2070	
2020 PO5396161887	F	3	45 OTH	SP	P		V			4/14/2070	
2020 PO5283361716	KU	6	30 OTH	SP	CRE		V			4/15/2070	
2020 PO5394362335	KU	5	40 OTH	SP	CRE	ED,EP,ID,IP			TX	RR	4/16/2070
2020 PO5421661745	KU	6	30 OTH	SP	CCA		V			4/17/2070	
2020 PO5428662534	KU	4	40 OTH	SP	CCA		V			4/18/2070	
2020 PO5408662618	KU	4	40 OTH	SP	CCA		V			4/19/2070	
2020 PO5375062014	KU	4	45 OTH	SP	CCA		V			4/20/2070	
2020 PO5435762038	KU	4	40 OTH	SP	CRE	ID			BD	4/21/2070	
2020 PO5434162694	KU	4	40 OTH	SP	CCA		V			4/22/2070	
2020 PO4759217060	F	4	40 ACE	SP	CRE		V			4/23/2070	
2020 PO4749388610	LGE	1	75 BRO	SP	P		V			4/24/2070	
2020 PO4766588556	F	4	35 BRO	SP	CCA		V			4/25/2070	
2020 PO4766688513	LGE	3	45 BRO	SP	CCA		V			4/26/2070	
2020 PO4634288313	LGE	4	40 BRO	SP	CRE	ED,ID			TD	4/27/2070	
2020 PO4633188309	LGE	4	40 BRO	SP	A	ED,ID			TD	4/28/2070	
2020 PO4767988566	F	4	40 BRO	SP	CCA		V			4/29/2070	
2020 PO5506547295	KU	4	40 ACE	SP	CCA		V			4/30/2070	
2020 PO5500047088	KU	4	40 ACE	SP	CRE	ED,ID			TD	5/1/2070	
2020 PO5471847098	KU	4	40 ACE	SP	CRE	ED,ID			TD	5/2/2070	
2020 PO5515347416	KU	5	35 ACE	SP	CCA		V			5/3/2070	
2020 PO9211991306A	KU	4	40 XXX	SP	CRE	ED,ID			TD	5/4/2070	
2020 PO9284190900	KU	6	30 XXX	SP	CRE		V			5/5/2070	
2020 PO9211991306	KU	4	40 XXX	SP	CRE	ED,ID			TD	5/6/2070	

2020 PO9259491125	KU	4	40 XXX	SP	CRE	ED,ID	TD	5/7/2070
2020 PO9189591326	KU	4	40 XXX	SP	CRE	ID	BD	5/8/2070
2020 PO4073805083	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD	5/9/2070
2020 PO4073805083-A	KU	5	35 BRO	SP	CRE		V	5/10/2070
2020 PO4063904721-B	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	5/11/2070
2020 PO4063904721-A	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	5/12/2070
2020 PO5594546443	F	4	40 ACE	SP	CRE		V	5/13/2070
2020 PO4767688562	F	3	30 BRO	SP	CCA		V	5/14/2070
2020 PO4768488568	F	4	40 BRO	SP	CCA	HH,MD,RB	VX	RP1 5/15/2070
2020 PO4768888561	F	4	30 BRO	SP	CCA		V	5/16/2070
2020 PO4767488547	F	4	30 BRO	SP	CCA		V	5/17/2070
2020 PO4766788551	F	3	45 BRO	SP	CCA		V	5/18/2070
2020 PO4766888535	F	4	35 BRO	SP	CCA		V	5/19/2070
2020 PO4720516919-A	KU	5	35 ACE	SP	CRE	ID,IP	BD	5/20/2070
2020 PO4801688838	LGE	4	40 BRN	SP	CRE	ED,ID	BD	5/21/2070
2020 PO4801188852	LGE	4	40 BRN	SP	CRE	ED,ID	BD	5/22/2070
2020 PO4803088859	LGE	4	40 BRN	SP	CRE	ED,ID	TD	5/23/2070
2020 PO4631988305	LGE	4	40 BRO	SP	A	ED,ID	TD	5/24/2070
2020 PO4630888301	LGE	4	40 BRO	SP	CRE	ED,HH,ID,RB	BX	PX 5/25/2070
2020 PO4629788298	LGE	4	40 BRO	SP	CCA		V	5/26/2070
2020 PO4628688294	LGE	4	40 BRO	SP	CRE	ED,HH,ID,RB	X	RP2 5/27/2070
2020 PO4627588290	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	5/28/2070
2020 PO4626388286	LGE	4	40 BRO	SP	CRE	ED,ID	BD	5/29/2070
2020 PO4770588614	F	4	40 BRO	SP	CCA		V	5/30/2070
2020 PO6311647019	KU	4	45 ACE	SP	CRE	ED,ID	TD	5/31/2070
2020 PO4770688617	F	4	40 BRO	SP	CCA		V	6/1/2070
2020 PO4770188606	F	4	40 BRO	SP	CCA		V	6/2/2070
2020 PO4769788597	F	3	35 BRO	SP	CCA	ID,MD,RB	VX	RP1 6/3/2070
2020 PO4769388588	F	4	40 BRO	SP	CCA		V	6/4/2070
2020 PO4769588630	F	4	40 BRO	SP	CCA		V	6/5/2070
2020 PO4749488597	F	4	40 BRO	SP	A		V	6/6/2070
2020 PO4745988547	F	4	40 BRO	SP	CCA		V	6/7/2070
2020 PO4746688557	F	3	45 BRO	SP	CCA		V	6/8/2070
2020 PO4748788587	F	4	40 BRO	SP	CCA		V	6/9/2070
2020 PO4747488568	F	4	40 BRO	SP	CRE		V	6/10/2070
2020 PO4748088577	F	4	40 BRO	SP	P		V	6/11/2070
2020 PO3619151230	KU	4	40 BRN	SP	CCA		V	6/12/2070
2020 PO3706051082	KU	4	40 BRN	SP	CRE	ED,ID,SRS	TD	6/13/2070
2020 PO3701651078	KU	4	40 BRN	SP	CRE	ED,ID,SRS	TD	6/14/2070
2020 PO3682051061	KU	4	45 BRN	SP	CRE	ED,ID,SRS	TD	6/15/2070
2020 PO3666951052	KU	5	35E BRN	SP	CRE	ED,ID,SRS	TD	6/16/2070
2020 PO3643751032	KU	5	35 BRN	SP	CRE	ED,ID,SRS	TD	6/17/2070
2020 PO3630851025	KU	5	35E BRN	SP	CRE	ED,ID,SRS	TD	6/18/2070
2020 PO3623251022	KU	4	40 BRN	SP	CRE	ID	BD	6/19/2070
2020 PO4800688867	LGE	4	40 BRN	SP	CCA		V	6/20/2070
2020 PO4800188879	LGE	4	40 BRN	SP	CRE	ED,ID	BD	6/21/2070
2020 PO4799788893	LGE	4	40 BRN	SP	P		T	6/22/2070

2020 PO5498361910	F	4	45 OTH	SP	P		V	6/23/2070	
2020 PO5559261925	F	3	45 OTH	SP	P		V	6/24/2070	
2020 PO5472561905	F	3	45 OTH	SP	CCA		V	6/25/2070	
2020 PO5472262044	F	3	45 OTH	SP	P		V	6/26/2070	
2020 PO5530761914	F	3	45 OTH	SP	P		V	6/27/2070	
2020 PO4809817092	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	6/28/2070	
2020 PO4821417167	KU	4	40 ACE	SP	CRE	ID,IP	BD	6/29/2070	
2020 PO4790817652	KU	4	40 ACE	SP	CRE	ID,IP	BD	6/30/2070	
2020 PO4799288907	LGE	4	40 BRN	SP	CRE	ED,ID	TD	7/1/2070	
2020 PO5576461959	F	4	40 OTH	SP	P		V	7/2/2070	
2020 PO5555762702	KU	4	40 OTH	SP	CRE	ID	TD	7/3/2070	
2020 PO5533662658	KU	3	45 OTH	SP	CCA		V	7/4/2070	
2020 PO5571161805	KU	4	45 OTH	SP	CRE	ID	TD	7/5/2070	
2020 PO5563162018	KU	4	40 OTH	SP	CRE	ID	TD	7/6/2070	
2020 PO5555862194	KU	4	40 OTH	SP	CRE	ID	TD	7/7/2070	
2020 PO5544662422	KU	4	40 OTH	SP	CCA		V	7/8/2070	
2020 PO4798788921	LGE	4	40 BRN	SP	CRE	ED,ID	BD	7/9/2070	
2020 PO4798288935	LGE	4	40 BRN	SP	CRE	ED,ID	BD	7/10/2070	
2020 PO4797888949	LGE	4	40 BRN	SP	CRE	ED,HH,ID,RB	BX	RR	7/11/2070
2020 PO5649762721	KU	4	40 OTH	SP	CCA		V	7/12/2070	
2020 PO5667562787	F	3	45 OTH	SP	CCA		V	7/13/2070	
2020 PO5774864757	F	4	45 OTH	SP	P		V	7/14/2070	
2020 PO5690663024	F	3	45 OTH	SP	P		V	7/15/2070	
2020 PO5637862569	F	3	45 OTH	SP	P		V	7/16/2070	
2020 PO5592062042	F	4	40 OTH	SP	P		V	7/17/2070	
2020 PO5765164618	F	3	45 OTH	SP	P		V	7/18/2070	
2020 PO5756764509	F	3	45 OTH	SP	P		V	7/19/2070	
2020 PO5649762721	F	3	45 OTH	SP	P		V	7/20/2070	
2020 PO5609262173	F	3	45 OTH	SP	P		V	7/21/2070	
2020 PO5645462776	F	4	35 OTH	SP	P		V	7/22/2070	
2020 PO5784264905	F	3	45 OTH	SP	P		V	7/23/2070	
2020 PO5792865049	F	4	40 OTH	SP	P		V	7/24/2070	
2020 PO5586936979	F	5	35 BRO	SP	CRE		V	7/25/2070	
2020 PO5582536893	F	4	40 BRO	SP	CRE		V	7/26/2070	
2020 PO5591136982	F	4	40 BRO	SP	CRE		V	7/27/2070	
2020 PO5597737051	F	4	40 BRO	SP	CRE		V	7/28/2070	
2020 PO5633737288	F	4	40 BRO	SP	CCA		V	7/29/2070	
2020 PO5607237128	F	4	40 BRO	SP	CRE		V	7/30/2070	
2020 PO5620137204	F	3	45 BRO	SP	CCA		V	7/31/2070	
2020 PO5843853187	KU	4	40 ACE	SP	CRE	ED,ID	TD	8/1/2070	
2020 PO5828953098	KU	4	40 ACE	SP	CRE	ED,ID	TD	8/2/2070	
2020 PO5624137446	F	4	40 BRO	SP	CRE		V	8/3/2070	
2020 PO5598437698	KU	6	30 BRO	SP	CCA		V	8/4/2070	
2020 PO5606037633	KU	4	40 BRO	SP	CCA		V	8/5/2070	
2020 PO5662937420	F	4	40 BRO	SP	CRE	HH,ID,RB	VX	RP1	8/6/2070
2020 PO5642037253	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/7/2070	
2020 PO4694388273	LGE	4	40 BRN	SP	CRE	ED,ID	BD	8/8/2070	

2020 PO4638116182	F	4	40 BRO	SP	CRE		V	8/9/2070
2020 PO4644416251	F	4	40 BRO	SP	CRE		V	8/10/2070
2020 PO4652516338	F	4	40 BRO	SP	CRE		V	8/11/2070
2020 PO4660616426	F	4	40 BRO	SP	A		V	8/12/2070
2020 PO4667016052	F	4	40 BRO	SP	A		V	8/13/2070
2020 PO4674916136	F	4	40 BRO	SP	CRE		V	8/14/2070
2020 PO4683716230	F	4	40 BRO	SP	CRE		V	8/15/2070
2020 PO4691716314	F	4	40 BRO	SP	CRE		V	8/16/2070
2020 PO4769816444	F	4	40 BRO	SP	CRE		V	8/17/2070
2020 PO4765716501	F	4	40 BRO	SP	CRE		V	8/18/2070
2020 PO4774616372	F	4	40 BRO	SP	CRE		V	8/19/2070
2020 PO4775716250	F	4	40 BRO	SP	CRE		V	8/20/2070
2020 PO4706888142	LGE	4	40 BRO	SP	A	ED,ID	BD	8/21/2070
2020 PO4707288143	LGE	UNK	30 BRO	SP	CRE		V	8/22/2070
2020 PO5287254291	KU	4	40 OTH	SP	CRE	ID	TD	8/23/2070
2020 PO5273754507	KU	4	40 OTH	SP	CRE	ID	TD	8/24/2070
2020 PO4786588941	LGE	4	30 BRN	SP	CCA		V	8/25/2070
2020 PO4786188940	LGE	3	50 BRN	SP	A	ED,ID	BD	8/26/2070
2020 PO4786788926	LGE	3	50 BRN	SP	A	ED,ID	BD	8/27/2070
2020 PO9592635078	ODP	6	30 BRN	SP	CRE	ED,ID	TD	8/28/2070
2020 PO9588735173	ODP	5	35 BRN	SP	CRE		V	8/29/2070
2020 PO9580735071	ODP	4	40 KOP	SP	CRE	ED,ID	TD	8/30/2070
2020 PO9560635572	ODP	6	30 BRN	SP	CRE		V	8/31/2070
2020 PO9559035865	ODP	3	50 BRN	SP	CRE	ED,ID	TD	9/1/2070
2020 PO4787088921	LGE	3	50 BRN	SP	CRE	ED,ID	BD	9/2/2070
2020 PO4787588910	LGE	3	50 BRN	SP	CCA		V	9/3/2070
2020 PO4787988899	LGE	3	50 BRN	SP	S		V	9/4/2070
2020 PO4790288845	LGE	3	50 BRN	SP	CRE	ED,ID	TD	9/5/2070
2020 PO4790688836	LGE	3	50 BRN	SP	CRE	ED,ID,IP	BD	9/6/2070
2020 PO4791888808	LGE	3	50 BRN	SP	CRE	ED,HH,ID,IP	BX	RR 9/7/2070
2020 PO4744687211	LGE	3	45 BRO	SP	CCA		V	9/8/2070
2020 PO4791488818	LGE	1	50 BRN	SP	S		V	9/9/2070
2020 PO9201693017A	KU	6	30 XXX	SP	CRE	ED,ID	TD	9/10/2070
2020 PO9027693665	KU	4	40 XXX	SP	CRE	ED,ID	TD	9/11/2070
2020 PO5312124815	KU	2	45 BRO	SP	CRE	ED,ID,IP	TD	9/12/2070
2020 PO9617395106	KU	6	35 ACW	SP	CRE	ED,ID	TD	9/13/2070
2020 PO5222524925	KU	3	45 ACE	SP	CRE	ED,ID,IP	TD	9/14/2070
2020 PO5191625062	KU	3	45 ACE	SP	CRE	ED,ID,IP	TD	9/15/2070
2020 PO5068424467	KU	4	40 BRO	SP	CCA		V	9/16/2070
2020 PO5158325207	KU	4	45 ACE	SP	CRE	ED,ID	TD	9/17/2070
2020 PO5141524828	KU	4	40 ACE	SP	CCA		V	9/18/2070
2020 PO5589146768a	KU	6	30 ACE	SP	CCA		V	9/19/2070
2020 PO5113032560	KU	3	45 BRO	SP	CCA		V	9/20/2070
2020 PO5095532571	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/21/2070
2020 PO5108632886	KU	6	30 BRO	SP	CCA		V	9/22/2070
2020 PO9145893926	KU	5	35 BRN	SP	CRE		V	9/23/2070
2020 PO5589146768	F	4	40 ACE	SP	CRE		V	9/24/2070

2020 PO5574947085	F	4	40 ACE	SP	CRE		V			9/25/2070
2020 PO5578747219	F	4	40 ACE	SP	CCA		V			9/26/2070
2020 PO5099832780	KU	6	30 BRO	SP	CCA		V			9/27/2070
2020 PO5115932767	KU	4	40 BRO	SP	CCA		V			9/28/2070
2020 PO5122533393	KU	4	45 BRO	SP	CRE		V			9/29/2070
2020 PO5121633174	KU	3	45 BRO	SP	CCA		V			9/30/2070
2020 PO5122333535	F	3	45 BRO	SP	CCA		V			10/1/2070
2020 PO5122433683	KU	3	45 BRO	SP	CCA		V			10/2/2070
2020 PO5101433683	KU	5	35 BRO	SP	CRE		V			10/3/2070
2020 PO5087333726	KU	4	40 BRO	SP	CCA		V			10/4/2070
2020 PO5595547095a	KU	6	30 ACE	SP	CCA		V			10/5/2070
2020 PO5595547095	KU	6	30 ACE	SP	CRE	ED,ID	TD			10/6/2070
2020 PO5070728566	KU	4	40 BRO	SP	CRE	ED,ID	TD			10/7/2070
2020 PO5224828310	KU	3	45 BRO	SP	CCA		V			10/8/2070
2020 PO5198227174	KU	4	40 BRO	SP	CRE	ED,ID	BD			10/9/2070
2020 PO5203927541	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD			10/10/2070
2020 PO5177727634	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			10/11/2070
2020 PO5636047299	KU	6	30 ACE	SP	CRE	ED,ID	TD			10/12/2070
2020 PO5656747339	KU	3	45 ACE	SP	CCA		V			10/13/2070
2020 PO5649447273	KU	6	30 ACE	SP	CRE	ED,ID	TD			10/14/2070
2020 PO9712895302	KU	6	30 ACW	SP	CRE		V			10/15/2070
2020 PO5106528271	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			10/16/2070
2020 PO6108463029	KU	4	40 OTH	SP	CRE	ED,EP,ID,IP,SRC	TX	RR		10/17/2070
2020 PO3953450917	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD			10/18/2070
2020 PO4776588982	LGE	4	40 BRN	SP	CCA		V			10/19/2070
2020 PO4020250551	KU	6	30 OTH	SP	CRE	ED,ID	BD			10/20/2070
2020 PO3664448970	KU	4	45 OTH	SP	CRE	ID	BD			10/21/2070
2020 PO3655649307	KU	4	40 OTH	SP	CCA		V			10/22/2070
2020 PO3649049579	KU	4	40 OTH	SP	CCA		V			10/23/2070
2020 PO3641949843	KU	4	40 OTH	SP	CCA		V			10/24/2070
2020 PO3633350186	KU	4	40 OTH	SP	CCA		V			10/25/2070
2020 PO3634750385	KU	4	40 OTH	SP	P		V			10/26/2070
2020 PO6049348478	KU	3	45 ACE	SP	CRE		V			10/27/2070
2020 PO6049448437	KU	4	45 ACE	SP	CRE	ED,ID	BD			10/28/2070
2020 PO6028248593	KU	2	50 ACE	SP	CRE	ED,ID	TD			10/29/2070
2020 PO6030248687	KU	4	45 ACE	SP	CRE	ED,ID	BD			10/30/2070
2020 PO9693395270	KU	4	40 ACW	SP	CRE	ED,ID	TD			10/31/2070
2020 PO9681795235	KU	4	40 ACW	SP	CRE	ED,ID	TD			11/1/2070
2020 PO9669895200	KU	5	30 ACW	SP	CRE	ED,ID	TD			11/2/2070
2020 PO9656595157	KU	4	40 ACW	SP	CRE	ED,ID	TD			11/3/2070
2020 PO9629295301	C	5	40 ACW	SP	CRE		V			11/4/2070
2020 PO9640795325	KU	4	40 ACW	SP	CRE	ED,ID	BD			11/5/2070
2020 PO9643195181	KU	5	35 ACW	SP	CRE	ED,ID	TD			11/6/2070
2020 PO9644195118	KU	4	40 ACW	SP	CRE	ED,ID,SRC	TD			11/7/2070
2020 PO5058928661	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			11/8/2070
2020 PO5047128890	KU	4	40 BRO	SP	CRE	ED,ID	TD			11/9/2070
2020 PO5022729181	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			11/10/2070

2020 PO5011729585	KU	4	40 BRO	SP	A		V		11/11/2070
2020 PO4996929698	F	4	40 BRO	SP	CRE		V		11/12/2070
2020 PO3631350589	KU	4	40 OTH	SP	CRE		V		11/13/2070
2020 PO4972929894	KU	4	40 BRO	SP	CRE		V		11/14/2070
2020 PO4948430073	KU	4	40 BRO	SP	CRE		V		11/15/2070
2020 4914330048-A	KU	3	45 BRO	SP	CCA		V		11/16/2070
2020 PO4914330048	KU	4	45 BRO	SP	A	ED,ID	TD		11/17/2070
2020 PO9184194052	KU	4	40 XXX	SP	P	ED,ID	TD		11/18/2070
2020 PO6054048259	KU	4	45 ACE	SP	CRE	ED,ID	BD		11/19/2070
2020 PO5594945531	KU	2	50 ACE	SP	CCA		V		11/20/2070
2020 PO9180194172	KU	4	40 XXX	AL	CCA		V		11/21/2070
2020 PO9185794186	KU	6	30 XXX	SP	CRE	ED,ID	TD		11/22/2070
2020 PO9168194138	KU	4	40 XXX	SP	CRE	ED,ID	TD		11/23/2070
2020 PO5560345773	KU	3	45 ACE	SP	CCA		V		11/24/2070
2020 PO9151994090	KU	4	40 XXX	SP	CRE	ID	BD		11/25/2070
2020 PO9142894071	C	4	40 XXX	OT	CRE		V		11/26/2070
2020 PO9176292572A	F	5	35 XXX	SP	CRE		V		11/27/2070
2020 PO5564445846	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		11/28/2070
2020 PO3627350797	KU	4	40 OTH	SP	CRE		V		11/29/2070
2020 PO3694249221	KU	5	35E OTH	SP	CRE		V		11/30/2070
2020 PO3723049155	KU	5	35 OTH	SP	CRE		V		12/1/2070
2020 PO3750044992	KU	5	30 OTH	SP	CRE	ID	BD		12/2/2070
2020 PO6088065829	KU	4	45 OTH	SP	CRE	ID	TD		12/3/2070
2020 PO6061265804	KU	5	30 OTH	SP	CRE	ID	TD		12/4/2070
2020 PO6064365665	KU	5	35 OTH	SP	CRE	ED,ID,SRC	TD		12/5/2070
2020 PO4779488993	LGE	4	35 BRN	SP	CRE	ED,ID	BD		12/6/2070
2020 PO4778989003	LGE	4	35 BRN	SP	CCA	ED,ID	BD		12/7/2070
2020 PO4763388653	F	4	40 BRO	SP	CCA		V		12/8/2070
2020 PO4765388665	LGE	4	30 BRO	SP	CCA		V		12/9/2070
2020 PO4764288655	F	4	40 BRO	SP	CCA	ED,ID	VX	RP2	12/10/2070
2020 PO4777188970	LGE	4	40 BRN	SP	CRE	ED,ID	BD		12/11/2070
2020 PO4779988982	LGE	4	30 BRN	SP	CCA		V		12/12/2070
2020 PO4777688957	LGE	4	40 BRN	SP	A	ED,ID	TD		12/13/2070
2020 PO4758188630	F	4	40 BRO	SP	CCA		V		12/14/2070
2020 PO5531645918	KU	3	50 ACE	SP	CCA		V		12/15/2070
2020 PO5503045967	KU	3	45 ACE	SP	CCA		V		12/16/2070
2020 5612133827-A	KU	7	35 BRO	SP	CRE		V		12/17/2070
2020 PO5612133827	F	7	35 BRO	SP	CRE		V		12/18/2070
2020 PO5607033923	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		12/19/2070
2020 PO5483045874	KU	4	40 ACE	SP	CCA		V		12/20/2070
2020 PO5483045984	KU	3	45 ACE	SP	CCA		V		12/21/2070
2020 PO5482446032	KU	5	35 ACE	SP	CCA		V		12/22/2070
2020 PO5481946104	F	3	40 ACE	SP	CRE		V		12/23/2070
2020 PO5466845998	KU	3	45 ACE	SP	CCA		V		12/24/2070
2020 PO5452846009	KU	3	45 ACE	SP	CCA		V		12/25/2070
2020 PO5433546035	KU	3	45 ACE	SP	CCA		V		12/26/2070
2020 PO5411046065	KU	3	45 ACE	SP	CCA		V		12/27/2070

2020 PO5398046185	KU	4	40 ACE	SP	CCA		V	12/28/2070
2020 PO9627695067	KU	3	40 ACW	SP	S		V	12/29/2070
2020 PO5098224497	KU	4	40 BRO	SP	CCA		V	12/30/2070
2020 PO5128124526	KU	4	40 BRO	SP	CCA		V	12/31/2070
2020 PO5263724839	KU	4	40 BRO	SP	CCA		V	1/1/2071
2020 PO4757488632	F	4	45 BRO	SP	CCA		V	1/2/2071
2020 PO5278824814	KU	2	45 BRO	SP	CCA		V	1/3/2071
2020 PO5297324797	KU	2	45 BRO	SP	CRE	ED,ID,IP	TD	1/4/2071
2020 PO5710234568	KU	5	30 BRO	SP	CRE		V	1/5/2071
2020 PO9118594053	KU	6 35E	XXX	SP	CRE	ED,ID	TD	1/6/2071
2020 PO5939848404	KU	5	35 ACE	SP	CRE		V	1/7/2071
2020 PO4756088627	F	3	45 BRO	SP	CCA		V	1/8/2071
2020 PO4750188607	F	4	40 BRO	SP	CCA		V	1/9/2071
2020 PO4750688609	F	4	40 BRO	SP	CCA		V	1/10/2071
2020 PO4753188617	F	4	40 BRO	SP	CCA		V	1/11/2071
2020 PO4752088613	F	4	40 BRO	SP	A		V	1/12/2071
2020 PO4754588622	F	4	40 BRO	SP	CCA		V	1/13/2071
2020 PO4778288945	LGE	4	40 BRN	SP	S		V	1/14/2071
2020 PO4684887988	LGE	4	40 BRO	SP	A	ED,ID	BD	1/15/2071
2020 PO4684987999	LGE	4	40 BRO	SP	A	ED,ID	TD	1/16/2071
2020 PO2308240573	ODP	5	35 ACW	SP	S		V	1/17/2071
2020 PO2738244409	ODP	5	35 ACW	SP	CRE	ED,ID	TD	1/18/2071
2020 PO2759244132	ODP	6	35 ACW	SP	CRE	ED,ID	TD	1/19/2071
2020 PO2697044244	ODP	5	35 ACW	DF	CRE	ID	BD	1/20/2071
2020 PO2664944415	ODP	6	35 ACW	DF	CRE	ID	BD	1/21/2071
2020 PO2629744587	ODP	6	35 ACW	SP	CRE	ID	BD	1/22/2071
2020 PO2591844772	ODP	6	35 ACW	DF	CRE	ID	TD	1/23/2071
2020 PO2568344907	ODP	3	45 ACW	DF	CRE	ED,ID,IP	TD	1/24/2071
2020 PO2521145134	F	4	40 ACW	SP	CCA		V	1/25/2071
2020 PO2564345287	ODP	5	35 ACW	SP	CRE	ED,ID	TD	1/26/2071
2020 PO2543045026	ODP	4	40 ACW	DF	CRE	ED,ID	TD	1/27/2071
2020 PO2547045233	ODP	2	50 ACW	SP	CCA		V	1/28/2071
2020 PO2535844818	F	4	40 ACW	SP	CCA		V	1/29/2071
2020 PO2311340209	ODP	5	35 ACW	SP	S		V	1/30/2071
2020 PO1963942046	ODP	4	45 ACW	SP	S		V	1/31/2071
2020 PO1968342212	ODP	4	45 ACW	SP	S		V	2/1/2071
2020 PO1995741822	ODP	5	35 ACW	SP	S		V	2/2/2071
2020 PO1994541909	ODP	4	45 ACW	SP	S		V	2/3/2071
2020 PO1846542282	ODP	4	45 ACW	SP	S		V	2/4/2071
2020 PO1834942156	ODP	4	40 ACW	SP	S		V	2/5/2071
2020 PO1813142142	ODP	5	35 ACW	SP	S		V	2/6/2071
2020 PO2314439902	ODP	5	35 ACW	SP	S		V	2/7/2071
2020 PO4781488970	LGE	4	30 BRN	SP	CRE	ED,ID	BD	2/8/2071
2020 PO4780688966	LGE	4	30 BRN	SP	CRE	ED,ID	BD	2/9/2071
2020 PO4781088934	LGE	4	30 BRN	SP	CRE	ED,ID	TD	2/10/2071
2020 PO4626888046	LGE	4	40 BRO	SP	CRE	ED,ID	BD	2/11/2071
2020 PO4105550341	KU	4	40 OTH	SP	CCA		V	2/12/2071

2020 PO4097250042	KU	4	40 OTH	SP	CRE	ID	BD		2/13/2071
2020 PO4597015773	F	4	40 ACE	SP	CRE		V		2/14/2071
2020 PO4778788932	LGE	4	40 BRN	SP	CCA		V		2/15/2071
2020 PO3981151161	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD		2/16/2071
2020 PO4778088937	LGE	4	40 BRN	SP	CCA		V		2/17/2071
2020 PO4778888921	LGE	4	40 BRN	SP	CRE	ED,ID	TD		2/18/2071
2020 PO4778388933	LGE	4	40 BRN	SP	P		T		2/19/2071
2020 PO3942651361	KU	4	40 OTH	SP	CCA		V		2/20/2071
2020 PO3971451576	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD		2/21/2071
2020 PO3968251699	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD		2/22/2071
2020 PO3940251710	KU	4	40 OTH	SP	CRE	ED,HH,ID,RB	X	PX	2/23/2071
2020 PO3878751843	KU	4	40 OTH	SP	CRE	ID	BD		2/24/2071
2020 PO6105065786	F	4	40 OTH	SP	P		V		2/25/2071
2020 PO6117365679	F	4	40 OTH	SP	CRE	ED	V		2/26/2071
2020 PO6109565857	KU	4	40 OTH	SP	CRE	ID	TD		2/27/2071
2020 PO6111865688	KU	4	40 OTH	SP	CRE	ID	TD		2/28/2071
2020 PO4606087948	F	4	40 BRO	SP	CRE		V		3/1/2071
2020 PO4606587939	F	4	40 BRO	SP	CRE		V		3/2/2071
2020 PO6106665333	KU	4	30 OTH	SP	CRE	ID	TD		3/3/2071
2020 PO6129965623	KU	4	40 OTH	SP	CRE	ID	TD		3/4/2071
2020 PO6113165602	KU	4	40 OTH	SP	CRE	ID	TD		3/5/2071
2020 PO6114365481	KU	4	40 OTH	SP	CRE	ID	TD		3/6/2071
2020 PO4779988898	LGE	4	40 BRN	SP	CRE	ED,ID	TD		3/7/2071
2020 PO4780488890	LGE	4	40 BRN	SP	A	ED,ID	BD		3/8/2071
2020 PO4760988569	F	3	40 BRO	SP	CCA		V		3/9/2071
2020 PO4759788577	F	4	40 BRO	SP	CCA		V		3/10/2071
2020 PO4758788584	F	4	40 BRO	SP	CCA		V		3/11/2071
2020 PO4758088589	F	4	40 BRO	SP	CCA		V		3/12/2071
2020 PO4762688557	F	3	40 BRO	SP	CCA		V		3/13/2071
2020 PO4761988562	F	4	40 BRO	SP	CCA		V		3/14/2071
2020 PO4757288594	F	4	40 BRO	SP	CCA		V		3/15/2071
2020 PO4755488609	LGE	4	35 BRO	SP	CCA	ED,ID	BD		3/16/2071
2020 PO4761388536	F	4	40 BRO	SP	CCA		V		3/17/2071
2020 PO4761988545	F	3	35 BRO	SP	CCA		V		3/18/2071
2020 PO4751488556	F	4	40 BRO	SP	CCA		V		3/19/2071
2020 PO4540915602	KU	3	45 ACE	SP	CRE	ID,IP	BD		3/20/2071
2020 PO4545215628	F	4	40 ACE	SP	CRE	EP,ID,IP	VX	RP2	3/21/2071
2020 PO4780988879	LGE	4	40 BRN	SP	CCA	ED,ID	BX	RR	3/22/2071
2020 PO4610287881	F	4	40 BRO	SP	CRE		V		3/23/2071
2020 PO4607787921	F	4	40 BRO	SP	CRE		V		3/24/2071
2020 PO4608687906	F	4	40 BRO	SP	CRE		V		3/25/2071
2020 PO4609487893	F	4	40 BRO	SP	CRE		V		3/26/2071
2020 PO4610987868	F	4	40 BRO	SP	CRE		V		3/27/2071
2020 PO4612587843	F	4	40 BRO	SP	CRE		V		3/28/2071
2020 PO4611787855	F	4	40 BRO	SP	CRE	ED,HH,ID	VX	RP2	3/29/2071
2020 PO4613387829	F	4	40 BRO	SP	CRE		V		3/30/2071
2020 PO4614187817	F	4	40 BRO	SP	CRE		V		3/31/2071

2020 PO4617987876	F	4	40 BRO	SP	CCA		V	4/1/2071	
2020 PO4614987804	F	4	40 BRO	SP	CRE		V	4/2/2071	
2020 PO3692453710	KU	2	45 OTH	SP	P	ID	BD	4/3/2071	
2020 PO4592115652	F	4	40 ACE	SP	CRE		V	4/4/2071	
2020 PO4781588868	LGE	4	40 BRN	SP	CRE	ED,ID	BD	4/5/2071	
2020 PO6122165338	F	4	40 OTH	SP	CRE	ED	V	4/6/2071	
2020 PO4573415442	F	4	40 ACE	SP	CRE		V	4/7/2071	
2020 PO6120565439	F	5	40 OTH	SP	P	ED	V	4/8/2071	
2020 PO6126765019	F	5	40 OTH	SP	P		V	4/9/2071	
2020 PO6131464716	F	4	40 OTH	SP	CRE		V	4/10/2071	
2020 PO6116864348	KU	5	35 OTH	SP	CRE	ID	TD	4/11/2071	
2020 PO6155463992	KU	5	40 OTH	SP	CRE	ID	TD	4/12/2071	
2020 PO6148064522	KU	4	40 OTH	SP	CCA		V	4/13/2071	
2020 PO6119665123	KU	3	45 OTH	SP	CCA		V	4/14/2071	
2020 PO6125464737	KU	4	45 OTH	SP	CRE	ID	TD	4/15/2071	
2020 PO6128164557	KU	5	35 OTH	SP	CRE	ID	TD	4/16/2071	
2020 PO6143064161	KU	6	30 OTH	SP	CCA		V	4/17/2071	
2020 PO4441235482	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/18/2071	
2020 PO4459836035	KU	2	40 BRO	SP	CRE	ID,IP	BD	4/19/2071	
2020 PO4794088774	LGE	4	30 BRN	SP	A	ED,ID	BD	4/20/2071	
2020 PO4795088772	LGE	4	40 BRN	SP	A	ED,ID,IP,RB	BX	RR	4/21/2071
2020 PO4354837252	KU	2	50 BRO	SP	CCA		V	4/22/2071	
2020 PO4047882968	LGE	4	35 BRO	SP	P	ED,ID	BD	4/23/2071	
2020 PO4336437348	KU	2	50 BRO	SP	CCA		V	4/24/2071	
2020 PO4361737289	KU	4	45 BRO	SP	CCA		V	4/25/2071	
2020 PO4355237189	KU	4	45 BRO	SP	P	ED	T	4/26/2071	
2020 PO4357737225	KU	3	45 BRO	SP	P	ED	T	4/27/2071	
2020 PO4729388920	F	3	45 ACE	SP	CRE		V	4/28/2071	
2020 PO4740088945	LGE	3	45 ACE	SP	A		V	4/29/2071	
2020 PO4742788943	LGE	4	40 ACE	SP	A	ED,ID	BD	4/30/2071	
2020 PO4745488939	LGE	3	45 ACE	SP	P	ED,ID	BD	5/1/2071	
2020 PO4745488952	LGE	UNK	40E	ACE	SP	CRE	V	5/2/2071	
2020 PO4733689047	F	4	40 ACE	SP	CRE		V	5/3/2071	
2020 PO4733489085	LGE	4	35 ACE	SP	CRE		V	5/4/2071	
2020 PO4733289089	LGE	2	60 ACE	ST	CCA		V	5/5/2071	
2020 PO4747989191	F	3	45 ACE	SP	CCA		V	5/6/2071	
2020 PO4558804860	F	3	45 ACE	SP	CCA		V	5/7/2071	
2020 PO4742989217	F	3	45 ACE	SP	CCA		V	5/8/2071	
2020 PO4550438337	KU	1	60 BRO	SP	CCA		V	5/9/2071	
2020 PO4550238362	KU	3	45 BRO	SP	CCA		V	5/10/2071	
2020 PO4555938444	KU	4	40 BRO	SP	CRE		V	5/11/2071	
2020 PO4552638405	KU	4	40 BRO	SP	CRE		V	5/12/2071	
2020 PO4563938211	KU	1	60 BRO	SP	CRE		V	5/13/2071	
2020 PO5678127937	KU	6	30 BRO	SP	A	ED,ID	TD	5/14/2071	
2020 PO9240092850	KU	4	40 BRN	SP	CRE	ED,ID	TD	5/15/2071	
2020 PO9221792769	KU	4	40 BRN	SP	S		B	5/16/2071	
2020 PO9253692908	KU	4	45 BRN	SP	CRE	ED,ID	TD	5/17/2071	

2020 PO9134392801	KU	4	45 BRN	SP	CRE	ID	BD	5/18/2071
2020 PO5673652832	F	4	40 ACE	SP	CRE		V	5/19/2071
2020 PO9519694553	KU	4	40 ACW	SP	CRE	ED,ID	TD	5/20/2071
2020 PO9514594686	KU	5	30 ACW	SP	CRE	ED,ID	TD	5/21/2071
2020 PO9509394701	KU	4	40 ACW	SP	CRE	ED,ID	TD	5/22/2071
2020 PO5805354450	KU	4	45 ACE	SP	CRE	ED,ID	BD	5/23/2071
2020 PO5817054180	KU	4	45 ACE	SP	CRE	ED,HH,ID,IP,RB	BX	RP1 5/24/2071
2020 PO5674927839	F	4	40 BRO	SP	CRE		V	5/25/2071
2020 PO5675228328	F	4	40 BRO	SP	A		V	5/26/2071
2020 PO5685828493	F	4	40 BRO	SP	A		V	5/27/2071
2020 PO4568238582	KU	4	40 BRO	SP	P	ED	T	5/28/2071
2020 PO4576338674	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	5/29/2071
2020 PO4791888750	LGE	4	40 BRN	SP	A	ED,ID	TD	5/30/2071
2020 PO4561238501	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	5/31/2071
2020 PO4573639169	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	6/1/2071
2020 PO4587639041	KU	4	40 BRO	SP	A		V	6/2/2071
2020 PO4588739031	KU	6	30 BRO	SP	CCA		V	6/3/2071
2020 PO4792588741	LGE	4	40 BRN	SP	A	ED,ID,IP	BD	6/4/2071
2020 PO4794088745	LGE	4	40 BRN	SP	A	ED,ID	TD	6/5/2071
2020 PO3311349757	KU	4	40 BRO	SP	CRE	ID,IP	BD	6/6/2071
2020 PO4529238678	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/7/2071
2020 PO4534238631	KU	5	35 BRO	SP	CRE	HH,RB	X	RP1 6/8/2071
2020 PO4795188762	LGE	4	35 BRN	SP	P	ED,ID	TD	6/9/2071
2020 PO4041383121	LGE	4	40 BRN	SP	P	ED,ID	BD	6/10/2071
2020 PO4041483093	LGE	4	40 BRN	SP	P	ED,ID	BD	6/11/2071
2020 PO4041483104	LGE	4	40 BRN	SP	P	ED,ID	BD	6/12/2071
2020 PO5703528672	F	4	40 BRO	SP	A		V	6/13/2071
2020 PO4795988775	LGE	3	65 BRN	SP	A		V	6/14/2071
2020 PO5721728817	F	4	40 BRO	SP	A		V	6/15/2071
2020 PO5737728910	F	3	40 BRO	SP	A		V	6/16/2071
2020 PO5736129163	F	4	40 BRO	SP	A		V	6/17/2071
2020 PO5746029130	KU	4	45 BRO	SP	A	ED,ID	TD	6/18/2071
2020 PO5796629023	KU	4	45 BRO	SP	A	ED	T	6/19/2071
2020 PO5736829398	F	4	40 BRO	SP	A		V	6/20/2071
2020 PO5743629425	KU	4	40 BRO	SP	CCA		V	6/21/2071
2020 PO5738329589	F	4	40 BRO	SP	A		V	6/22/2071
2020 PO5739729775	F	4	40 BRO	SP	A		V	6/23/2071
2020 PO5741029933	F	4	40 BRO	SP	A		V	6/24/2071
2020 PO5743030121	F	4	40 BRO	SP	A		V	6/25/2071
2020 PO5745030309	F	4	40 BRO	SP	CRE		V	6/26/2071
2020 PO5747330503	F	4	40 BRO	SP	CRE		V	6/27/2071
2020 PO5749830699	F	4	40 BRO	SP	CRE		V	6/28/2071
2020 PO5754030990	F	4	40 BRO	SP	A		V	6/29/2071
2020 PO4035883112	F	2	50 BRN	SP	S		V	6/30/2071
2020 PO4035883105	F	2	50 BRN	SP	CRE		V	7/1/2071
2020 PO9494094636	F	4	40 ACW	SP	CRE	ED,ID	V	7/2/2071
2020 PO4034183112	F	5	35 BRN	SP	S		V	7/3/2071

2020 PO4050683081	F	3	45 BRN	SP	A		V	7/4/2071
2020 PO4042183088	F	3	45 BRN	SP	CCA		V	7/5/2071
2020 PO4049483082	F	4	40 BRN	SP	CCA		V	7/6/2071
2020 PO4047683083	F	4	40 BRN	SP	CCA		V	7/7/2071
2020 PO4046283085	F	4	40 BRN	SP	CCA		V	7/8/2071
2020 PO4040783089	F	4	45 BRN	SP	CRE		V	7/9/2071
2020 PO4039783090	F	4	40 BRN	SP	CCA		V	7/10/2071
2020 PO4797288780	LGE	4	40 BRN	SP	P		T	7/11/2071
2020 PO4797688781	LGE	4	40 BRN	SP	A	ED,ID	TD	7/12/2071
2020 PO2590853049	KU	3	45 BRO	SP	CCA		V	7/13/2071
2020 PO2599453284	KU	3	45 BRO	SP	CCA		V	7/14/2071
2020 PO2619153809	KU	3	45 BRO	SP	CCA		V	7/15/2071
2020 PO9498194671	KU	4	40 ACW	SP	CRE	ED,ID	TD	7/16/2071
2020 PO9490794733	KU	4	40 ACW	SP	CRE	ED,ID	TD	7/17/2071
2020 PO9475094614	KU	4	40 ACW	SP	CRE	ED,ID	TD	7/18/2071
2020 PO5692453191	KU	3	40 ACE	SP	CCA		V	7/19/2071
2020 PO5621652661	F	4	40 ACE	SP	CRE		V	7/20/2071
2020 PO5659551573	KU	6	30 ACE	SP	CCA		V	7/21/2071
2020 PO9124093226	C	6	30 BRN	SP	S		V	7/22/2071
2020 PO9122393109	KU	4	45 XXX	SP	CRE	ID	BD	7/23/2071
2020 PO9461494665	KU	6	30 ACW	SP	CRE		V	7/24/2071
2020 PO9455894567B	KU	7	35 ACW	SP	CRE	ED,ID	TD	7/25/2071
2020 PO9455894567A	KU	7	30 ACW	SP	CRE	ED,ID	TD	7/26/2071
2020 PO9455894567	KU	4	40 ACW	SP	CRE	ED,ID	TD	7/27/2071
2020 PO9436794587	KU	4	40 ACW	SP	CRE	ED,ID	TD	7/28/2071
2020 PO9446094542	KU	4	40 ACW	SP	CRE	ED,ID	TD	7/29/2071
2020 PO9435794518	KU	4	45 ACW	SP	S		V	7/30/2071
2020 PO9430194505	KU	4	45 ACW	SP	CRE	ED,ID	TD	7/31/2071
2020 PO9433894406	KU	6	30 ACW	SP	S		V	8/1/2071
2020 PO4802388800	LGE	3	65 BRN	SP	CRE		V	8/2/2071
2020 PO9401994436	KU	3	40 ACW	SP	S		V	8/3/2071
2020 PO9417194473	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	8/4/2071
2020 PO5615055347	KU	4	45 ACE	SP	CRE	ED,ID	TD	8/5/2071
2020 PO9166393271	KU	4	45 XXX	SP	CRE	ED,ID	TD	8/6/2071
2020 PO9147393190	KU	4	45 XXX	SP	CRE	ED,ID	TD	8/7/2071
2020 PO9173393097	KU	4	45 BRN	SP	CRE		B	8/8/2071
2020 PO5596755389	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	8/9/2071
2020 PO5637655297	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	8/10/2071
2020 PO9177492969	KU	4	45 XXX	SP	CRE	ED,ID	TD	8/11/2071
2020 PO9189792624	KU	4	45 XXX	SP	CRE	ED,ID	TD	8/12/2071
2020 PO4802288819	LGE	4	40 BRN	SP	CRE	ED,ID	BD	8/13/2071
2020 PO4802688807	LGE	4	35 BRN	SP	A	ED,ID	TD	8/14/2071
2020 PO4038683120	LGE	4	40 BRN	SP	CCA	ED,ID	VX	8/15/2071
2020 PO4043083087	F	4	40 BRN	SP	CCA		V	8/16/2071
2020 PO4802988802	LGE	4	40 BRN	SP	S		V	8/17/2071
2020 PO5129200856	LGE	3	45 BRN	SP	S		V	8/18/2071
2020 PO4192413216	KU	3	45 BRO	SP	CRE	ID,IP	BD	8/19/2071

2020 PO4804688808	LGE	3	65 BRN	SP	CRE		V		8/20/2071
2020 PO4806088814	LGE	4	40 BRN	SP	CRE	ED,ID,IP,SRC	TX	RR	8/21/2071
2020 PO4192113110	KU	2	50 BRO	SP	CRE	ID,IP	BD		8/22/2071
2020 PO4806688817	LGE	1	65 BRN	SP	CRE		V		8/23/2071
2020 PO4195313052	KU	2	50 BRO	SP	CRE	ED,ID,IP	TD		8/24/2071
2020 PO4809088804	LGE	4	40 BRN	SP	CRE	ED,ID	BD		8/25/2071
2020 PO4808788815	LGE	4	40 BRN	SP	CRE	ED,ID	TD		8/26/2071
2020 PO5777733016	F	3	40 BRO	SP	A		V		8/27/2071
2020 PO4813388846	LGE	1	70 BRN	SP	A		V		8/28/2071
2020 PO4814288843	LGE	4	35 BRN	SP	A	ED,ID	TD		8/29/2071
2020 PO4814488844	LGE	4	30 BRN	SP	CCA		V		8/30/2071
2020 PO4816088835	LGE	4	30 BRN	SP	CCA		V		8/31/2071
2020 PO4379312140	KU	H1	85 BRO	SP	CCA		V		9/1/2071
2020 PO5779533178	F	4	40 BRO	SP	CRE		V		9/2/2071
2020 PO5769933394	F	6	25 BRO	SP	A		V		9/3/2071
2020 PO5781233348	F	4	40 BRO	SP	A		V		9/4/2071
2020 PO5783033536	F	4	40 BRO	SP	A		V		9/5/2071
2020 PO5787834015	F	4	40 BRO	SP	CRE		V		9/6/2071
2020 PO5803833208	KU	4	40 BRO	SP	A	ED,ID	TD		9/7/2071
2020 PO5892533119	KU	4	40 BRO	SP	A	ED,ID	TD		9/8/2071
2020 PO5940633074	KU	4	40 BRO	SP	A	ED,ID	TD		9/9/2071
2020 PO5888334272	KU	3	45 BRO	SP	CCA		V		9/10/2071
2020 PO5870934319	KU	3	45 BRO	SP	CCA		V		9/11/2071
2020 PO5966433046	KU	4	40 BRO	SP	A	ED,ID	TD		9/12/2071
2020 PO5790634287	F	4	40 BRO	SP	A		V		9/13/2071
2020 PO5758037400	F	4	40 BRO	SP	A		V		9/14/2071
2020 PO5754237297	F	5	30 BRO	SP	A		V		9/15/2071
2020 PO5776837479	F	4	40 BRO	SP	A		V		9/16/2071
2020 PO4586188002	LGE	3	45 ACE	SP	A	ED,ID	BD		9/17/2071
2020 PO4585888006	LGE	3	45 ACE	SP	A	ED,ID	BD		9/18/2071
2020 PO4606588005	LGE	4	40 ACE	SP	CRE		V		9/19/2071
2020 PO4607488005	LGE	4	40 ACE	SP	CRE		V		9/20/2071
2020 PO4607588004	LGE	4	40 ACE	SP	CRE	ED,ID	BD		9/21/2071
2020 PO4606588008	LGE	4	35 ACE	SP	P	ED,ID	BD		9/22/2071
2020 PO4773988781	LGE	4	40 BRN	SP	S		V		9/23/2071
2020 PO4775388749	LGE	4	40 BRN	SP	CRE	ED,ID	TD		9/24/2071
2020 PO1929922510	ODP	4	40 XXX	SP	CRE		V		9/25/2071
2020 PO1638622724	ODP	5	35 XXX	SP	CRE		V		9/26/2071
2020 PO1627526961	ODP	4	45 XXX	SP	CCA		V		9/27/2071
2020 PO1339324238	ODP	6	30 XXX	SP	CCA		V		9/28/2071
2020 PO1449531643	ODP	5	35 XXX	SP	CRE		V		9/29/2071
2020 PO1405833091	F	4	40 XXX	SP	A		V		9/30/2071
2020 PO1496130914	ODP	3	45 XXX	SP	CCA		V		10/1/2071
2020 PO1474024036	F	4	40 XXX	SP	A		V		10/2/2071
2020 PO1469330909	ODP	4	45 XXX	SP	CRE	ID	BD		10/3/2071
2020 PO1484731464	ODP	4	40 XXX	SP	CCA		V		10/4/2071
2020 PO1500331103	ODP	3	45 XXX	SP	CCA		V		10/5/2071

2020 PO1516431009	ODP	2	40 XXX	SP	CCA		V	10/6/2071
2020 PO1538230881	ODP	3	45 XXX	SP	CCA		V	10/7/2071
2020 PO1553630788	ODP	4	40 XXX	SP	CCA		V	10/8/2071
2020 PO1553630788A	ODP	4	40 XXX	SP	CCA		V	10/9/2071
2020 PO1573330675	ODP	2	45 XXX	SP	CCA		V	10/10/2071
2020 PO1591430569	ODP	2	40 XXX	SP	CCA		V	10/11/2071
2020 PO1599030557	ODP	2	45 XXX	SP	CCA	ED	T	10/12/2071
2020 PO1615230465	ODP	5	35 XXX	SP	CCA	ED	T	10/13/2071
2020 PO1631030376	ODP	2	40 XXX	SP	CCA		V	10/14/2071
2020 PO1653730242	ODP	4	45 XXX	SP	CCA		V	10/15/2071
2020 PO1685930063	ODP	2	45 XXX	SP	CCA		V	10/16/2071
2020 PO1708929926	ODP	2	40 XXX	SP	CCA		V	10/17/2071
2020 PO1755429676	ODP	2	40 XXX	SP	CRE	ID	BD	10/18/2071
2020 PO1736329781	ODP	2	40 XXX	SP	CRE	ID	BD	10/19/2071
2020 PO5034611621	F	4	40 ACE	SP	P		V	10/20/2071
2020 PO5031112066	F	4	40 ACE	SP	P		V	10/21/2071
2020 PO5051512099	F	4	40 ACE	SP	P		V	10/22/2071
2020 PO5229413195	KU	4	40 ACE	SP	CCA		V	10/23/2071
2020 PO4706687672	LGE	3	45 BRO	SP	CCA		V	10/24/2071
2020 PO4708287650	LGE	3	45 BRO	SP	CCA		V	10/25/2071
2020 PO4709487632	LGE	3	45 BRO	SP	CCA		V	10/26/2071
2020 PO4710487617	LGE	3	45 BRO	SP	CCA		V	10/27/2071
2020 PO4711587600	LGE	3	45 BRO	SP	CCA		V	10/28/2071
2020 PO4712687584	LGE	3	45 BRO	SP	CCA		V	10/29/2071
2020 PO4713887567	LGE	3	45 BRO	SP	CCA		V	10/30/2071
2020 PO4715087551	LGE	3	45 BRO	SP	CCA		V	10/31/2071
2020 PO4716287532	LGE	3	45 BRO	SP	CCA		V	11/1/2071
2020 PO4717287515	LGE	3	45 BRO	SP	CCA		V	11/2/2071
2020 PO4718587497	LGE	3	45 BRO	SP	CCA		V	11/3/2071
2020 PO4719987482	LGE	3	45 BRO	SP	CCA		V	11/4/2071
2020 PO5250813029	KU	5	30 ACE	SP	CRE	ED,ID	BD	11/5/2071
2020 PO4785788963	LGE	4	40 BRN	SP	A	HH,ID	BD	11/6/2071
2020 PO4784788973	LGE	1	50 BRN	SP	CCA		V	11/7/2071
2020 PO4785188964	LGE	3	50 BRN	SP	CCA		V	11/8/2071
2020 PO4785688954	LGE	3	50 BRN	SP	CRE	ED,ID	BD	11/9/2071
2020 PO5239613077	KU	5	30 ACE	SP	CRE	ED,ID,IP	BD	11/10/2071
2020 PO5223512772	KU	4	40 ACE	SP	CRE	ED,ID	BD	11/11/2071
2020 PO5226912880	KU	4	35 ACE	SP	CRE	ED,ID,IP	BD	11/12/2071
2020 PO5225913075	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	11/13/2071
2020 PO4727987391	LGE	3	45 BRO	SP	CCA		V	11/14/2071
2020 PO4729587401	LGE	3	45 BRO	SP	CCA		V	11/15/2071
2020 PO4730987411	LGE	3	45 BRO	SP	CCA		V	11/16/2071
2020 PO4732387393	LGE	3	45 BRO	SP	CCA		V	11/17/2071
2020 PO4733587375	LGE	3	45 BRO	SP	CCA		V	11/18/2071
2020 PO4734787358	LGE	3	45 BRO	SP	CCA		V	11/19/2071
2020 PO4735887341	LGE	3	45 BRO	SP	CCA		V	11/20/2071
2020 PO4736887326	LGE	3	45 BRO	SP	CCA		V	11/21/2071

2020 PO4737987310	LGE	3	45 BRO	SP	CCA		V	11/22/2071
2020 PO4738987295	LGE	3	45 BRO	SP	CCA		V	11/23/2071
2020 PO4739987279	LGE	3	45 BRO	SP	CCA		V	11/24/2071
2020 PO4746587183	LGE	4	35 BRO	SP	CCA		V	11/25/2071
2020 PO4746787179	LGE	4	40 BRO	SP	CCA		V	11/26/2071
2020 PO4747787186	LGE	4	40 BRO	SP	CCA		V	11/27/2071
2020 PO4748287187	LGE	4	40 BRO	SP	CCA		V	11/28/2071
2020 PO4750187180	LGE	4	40 BRO	SP	CCA		V	11/29/2071
2020 PO4751987174	LGE	4	40 BRO	SP	CCA		V	11/30/2071
2020 PO4753787167	LGE	4	40 BRO	SP	CCA		V	12/1/2071
2020 PO4667284485	LGE	4	40 BRO	SP	CCA		V	12/2/2071
2020 PO4720687466	LGE	3	45 BRO	SP	CCA		V	12/3/2071
2020 PO4726587381	LGE	3	50 BRO	SP	CCA		V	12/4/2071
2020 PO4725287398	LGE	3	45 BRO	SP	CCA		V	12/5/2071
2020 PO4724787414	LGE	3	45 BRO	SP	CCA		V	12/6/2071
2020 PO4722387449	LGE	3	45 BRO	SP	CCA		V	12/7/2071
2020 PO4722387441	LGE	3	45 BRO	SP	CCA		V	12/8/2071
2020 PO4723487426	LGE	3	45 BRO	SP	CCA		V	12/9/2071
2020 PO4741187262	LGE	3	45 BRO	SP	CCA		V	12/10/2071
2020 PO4742387246	LGE	3	45 BRO	SP	CCA		V	12/11/2071
2020 PO4743587229	LGE	3	45 BRO	SP	CCA		V	12/12/2071
2020 PO4745887193	LGE	4	40 BRO	SP	CCA		V	12/13/2071
2020 PO5032301633	F	4	40 ACE	SP	CCA		V	12/14/2071
2020 PO5017001634	F	4	40 ACE	SP	A		V	12/15/2071
2020 PO4975801632	F	4	40 ACE	SP	CRE		V	12/16/2071
2020 PO4992601633	F	4	40 ACE	SP	CCA		V	12/17/2071
2020 PO5005801633	F	4	40 ACE	SP	CCA		V	12/18/2071
2020 PO5103501823	F	4	40 ACE	SP	CRE		V	12/19/2071
2020 PO4744088871	LGE	6	25 BRN	SP	CRE	ED,ID	TD	12/20/2071
2020 PO4744388880	LGE	4	30 BRN	SP	A	ED,ID	TD	12/21/2071
2020 PO4970410664	F	4	40 ACE	SP	P		V	12/22/2071
2020 PO4683012435	KU	4	40 BRO	SP	CRE	ID	BD	12/23/2071
2020 PO4504503938	LGE	1	50 BRO	SP	CCA		V	12/24/2071
2020 PO4741789105	LGE	1	50 BRO	SP	CCA		V	12/25/2071
2020 PO4743289112	LGE	1	50 BRO	SP	CCA		V	12/26/2071
2020 PO4784688939	LGE	4	40 BRN	SP	A	ED,ID	BD	12/27/2071
2020 PO6236363663	KU	3	45 OTH	SP	CCA		V	12/28/2071
2020 PO6174064149	KU	4	40 OTH	SP	CCA		V	12/29/2071
2020 PO6176263974	KU	4	40 OTH	SP	CRE	ID	TD	12/30/2071
2020 PO6196863775	KU	3	45 OTH	SP	CCA		V	12/31/2071
2020 PO6216863719	KU	4	40 OTH	SP	CCA		V	1/1/2072
2020 PO4885511535	F	3	45 ACE	SP	CCA		V	1/2/2072
2020 PO4898011480	KU	4	40 BRO	SP	A		V	1/3/2072
2020 PO4918512705	F	4	40 BRO	SP	CRE		V	1/4/2072
2020 PO4916012648	F	4	40 BRO	SP	CRE		V	1/5/2072
2020 PO4758488461	F	4	30 BRO	SP	CCA		V	1/6/2072
2020 PO4760188460	F	4	30 BRO	SP	CCA		V	1/7/2072

2020 PO4761388469	F	4	40 BRO	SP	CCA		V			1/8/2072
2020 PO4762288482	F	4	40 BRO	SP	CCA		V			1/9/2072
2020 PO4761588519	F	3	30 BRO	SP	CCA		V			1/10/2072
2020 PO4762788510	F	4	35 BRO	SP	CCA		V			1/11/2072
2020 PO4763788504	F	4	30 BRO	SP	CCA		V			1/12/2072
2020 PO4765188526	F	3	45 BRO	SP	CCA		V			1/13/2072
2020 PO4764588516	F	4	30 BRO	SP	CCA		V			1/14/2072
2020 PO4907012445	F	4	40 BRO	SP	CRE	HH, RB	VX	RP1		1/15/2072
2020 PO4788488888	LGE	3	50 BRN	SP	CRE	ED, ID, SRS	TX	RR		1/16/2072
2020 PO3736552755	KU	4	40 OTH	SP	CRE	ED, ID, SRS	TD			1/17/2072
2020 PO3744052630	KU	4	40 OTH	SP	CRE	ED, ID, SRS	TD			1/18/2072
2020 PO3758552592	KU	7	30E OTH	SP	CRE	ED, ID, SRS	TD			1/19/2072
2020 PO6159464384	KU	4	40 OTH	SP	CRE	ID	TD			1/20/2072
2020 PO6170964391	KU	5	35 OTH	SP	CRE	ID	TD			1/21/2072
2020 PO4873912589	F	4	40 BRO	SP	CRE	HH, RB	VX	RP1		1/22/2072
2020 PO3747652303	KU	5	35 OTH	SP	CCA		V			1/23/2072
2020 PO3735252509	KU	5	35 OTH	SP	CCA		V			1/24/2072
2020 PO3727852713	KU	5	35 OTH	SP	CCA		V			1/25/2072
2020 PO3706752953	KU	5	35 OTH	SP	CCA		V			1/26/2072
2020 PO3725152934	KU	3	45 OTH	SP	CCA		V			1/27/2072
2020 PO3735452909	F	2	45 OTH	SP	P		V			1/28/2072
2020 PO3749552539	KU	3	40E OTH	SP	CRE	ED, ID, SRS	TD			1/29/2072
2020 PO3758452391	KU	4	40 OTH	SP	CRE	ED, ID, SRS	TD			1/30/2072
2020 PO3769452351	KU	4	40 OTH	SP	CRE	ED, ID, SRS	TD			1/31/2072
2020 PO3774952283	KU	6	40E OTH	SP	CRE	ED, ID, SRS	TD			2/1/2072
2020 PO3772252445	KU	6	30 OTH	SP	CRE	ED, ID, SRS	TD			2/2/2072
2020 PO3783052232	F	4	40E OTH	SP	CRE		B			2/3/2072
2020 PO3791552202	F	3	35E OTH	SP	P		V			2/4/2072
2020 PO3789852120	KU	3	45 OTH	SP	CCA		V			2/5/2072
2020 PO3798752177	KU	4	40E OTH	SP	CRE	ID	BD			2/6/2072
2020 PO6165764811	KU	4	40 OTH	SP	CRE	ID	TD			2/7/2072
2020 PO6167464671	KU	4	40 OTH	SP	CRE	ID	TD			2/8/2072
2020 PO6163564993	KU	4	40 OTH	SP	CRE	ID	TD			2/9/2072
2020 PO6163364581	KU	6	30 OTH	SP	CCA		V			2/10/2072
2020 PO6169564512	KU	4	40 OTH	SP	CCA		V			2/11/2072
2020 PO4886312380	F	4	40 BRO	SP	CRE		V			2/12/2072
2020 PO4865112382	F	4	40 BRO	SP	CRE	HH, RB	VX	RP1		2/13/2072
2020 PO4763612896	F	4	40 BRO	SP	CRE		V			2/14/2072
2020 PO4750312951	F	4	40 BRO	SP	CRE		V			2/15/2072
2020 PO4788988877	LGE	3	50 BRN	SP	CRE	ED, ID, IP	TD			2/16/2072
2020 PO4778012833	F	4	40 BRO	SP	CRE		V			2/17/2072
2020 PO4711313156	F	4	40 BRO	SP	CRE		V			2/18/2072
2020 PO4722213071	F	4	40 BRO	SP	CCA		V			2/19/2072
2020 PO4683712975	F	4	40 BRO	SP	CRE	RB	VX	RP1		2/20/2072
2020 PO4698613155	F	4	40 BRO	SP	CRE		V			2/21/2072
2020 PO4703713223	F	4	40 BRO	SP	CRE		V			2/22/2072
2020 PO4711013319	F	4	40 BRO	SP	CRE		V			2/23/2072

2020 PO6152765521	F	5	35 OTH	SP	CCA		V	2/24/2072
2020 PO6155565209	F	5	40 OTH	SP	CRE	ED	V	2/25/2072
2020 PO6160265264	KU	4	40 OTH	SP	CCA		V	2/26/2072
2020 PO6158065525	KU	4	40 OTH	SP	CCA		V	2/27/2072
2020 PO6158565409	KU	5	35 OTH	SP	CRE	ID	TD	2/28/2072
2020 PO6161665147	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD	2/29/2072
2020 PO4789388866	LGE	3	50 BRN	SP	CRE	ED,ID,IP	TD	3/1/2072
2020 PO4646588076	LGE	3	50 BRO	SP	A	ED,ID	BD	3/2/2072
2020 PO4646288059	LGE	3	50 BRO	SP	A	ED,ID	BD	3/3/2072
2020 PO4645488117	LGE	4	35 BRO	SP	CRE		V	3/4/2072
2020 PO4644688101	LGE	4	35 BRO	SP	CRE		V	3/5/2072
2020 PO4646088104	LGE	4	35 BRO	SP	CRE		V	3/6/2072
2020 PO5062610239	F	4	40 BRO	SP	CRE		V	3/7/2072
2020 PO6158765655	KU	5	35 OTH	SP	CRE	ID	TD	3/8/2072
2020 PO5038410363	F	4	40 BRO	SP	CRE		V	3/9/2072
2020 PO5079509857	F	4	40 BRO	SP	CRE		V	3/10/2072
2020 PO4789888855	LGE	3	50 BRN	SP	A	ED,ID	TD	3/11/2072
2020 PO5113109959	F	4	40 BRO	SP	CRE		V	3/12/2072
2020 PO4749288171	F	4	30 BRO	SP	CCA		V	3/13/2072
2020 PO5119510126	F	4	40 BRO	SP	CRE		V	3/14/2072
2020 PO4714188049	LGE	1	70 BRO	SP	A		V	3/15/2072
2020 PO4713288069	LGE	5	25 BRO	SP	CRE	ED,ID	TD	3/16/2072
2020 PO4709488137	LGE	4	40 BRO	SP	CCA		V	3/17/2072
2020 PO4713788069	LGE	1	65 BRO	SP	CCA		V	3/18/2072
2020 PO4712688085	LGE	4	30 BRO	SP	CRE	ED,ID	TD	3/19/2072
2020 PO4713188087	LGE	1	65 BRO	SP	A		V	3/20/2072
2020 PO4712388108	LGE	1	65 BRO	SP	A		V	3/21/2072
2020 PO4711688125	LGE	1	70 BRO	SP	A		V	3/22/2072
2020 PO4711188129	LGE	5	25 BRO	SP	CRE	ED,ID	TD	3/23/2072
2020 PO4710388121	LGE	4	35 BRO	SP	A	ED,ID	TD	3/24/2072
2020 PO4711088143	F	4	45 BRO	SP	CRE		V	3/25/2072
2020 PO4710288151	LGE	4	40 BRO	SP	CRE	ED,ID,MD	TX	3/26/2072
2020 PO4620888017	LGE	2	50 BRO	SP	CRE	ED,EP,ID	BD	3/27/2072
2020 PO4620188018	LGE	UNK	65 BRO	SP	CRE	ED,ID	BD	3/28/2072
2020 PO4618688019	LGE	3	50 BRO	SP	CRE	ED,ID,IP	BD	3/29/2072
2020 PO4617888020	LGE	2	55 BRO	SP	CRE	ED,ID	TD	3/30/2072
2020 PO4616288022	LGE	UNK	65 BRO	SP	CRE	ED,ID	BD	3/31/2072
2020 PO0963436254	ODP	2	50 XXX	SP	CRE	ED,ID	TD	4/1/2072
2020 PO0990436174	ODP	3	45 XXX	SP	CRE	ED,ID	TD	4/2/2072
2020 PO1010236114	ODP	3	55 XXX	SP	CRE	ED,ID	TD	4/3/2072
2020 PO4710688142	LGE	1	70 BRO	SP	A		V	4/4/2072
2020 PO4709388174	LGE	4	40 BRO	SP	CCA		V	4/5/2072
2020 PO4709888162	LGE	4	30 BRO	SP	CCA		V	4/6/2072
2020 PO4708988185	LGE	1	70 BRO	SP	A		V	4/7/2072
2020 PO4708588196	LGE	4	40 BRO	SP	CRE	ED,ID	BD	4/8/2072
2020 PO4708188206	LGE	1	70 BRO	SP	A		V	4/9/2072
2020 PO4707688220	LGE	4	40 BRO	SP	CRE	ED,ID	BD	4/10/2072

2020 PO0364239900	F	4	40 XXX	SP	CCA		V			4/11/2072
2020 PO4705387934	LGE	1	70 BRO	SP	A		V			4/12/2072
2020 PO4705787946	LGE	4	35 BRO	SP	CCA		V			4/13/2072
2020 PO4806788966	LGE	4	35 BRN	SP	CCA		V			4/14/2072
2020 PO4804288962	LGE	4	40 BRN	SP	A		V			4/15/2072
2020 PO4810188971	LGE	4	40 BRN	SP	CRE		ED,ID		BD	4/16/2072
2020 PO4809788970	LGE	4	30 BRN	SP	CRE		ED,ID		BD	4/17/2072
2020 PO4707087932	LGE	1	70 BRO	SP	A		V			4/18/2072
2020 PO4703987935	LGE	1	70 BRO	SP	A		V			4/19/2072
2020 PO4702387937	LGE	1	75 BRO	SP	A		V			4/20/2072
2020 PO4807388968	LGE	4	40 BRN	SP	P		ED,ID		TD	4/21/2072
2020 PO4807688958	LGE	4	40 BRN	SP	CRE		ED,ID		BD	4/22/2072
2020 PO4700187939	LGE	1	75 BRO	SP	A		V			4/23/2072
2020 PO4698287941	LGE	1	80 BRO	SP	CRE		V			4/24/2072
2020 PO4698587969	LGE	3	45 BRO	SP	A		ED,ID		BD	4/25/2072
2020 PO4698587974	LGE	4	40 BRO	SP	CCA		V			4/26/2072
2020 PO4698487962	LGE	3	45 BRO	SP	A		ED,ID		BD	4/27/2072
2020 PO4091392415	LGE	3	45 BRO	SP	CCA		V			4/28/2072
2020 PO4085692357	LGE	3	45 BRO	SP	CCA		V			4/29/2072
2020 PO4716488015	LGE	4	30 BRO	SP	A		ED,ID		BX	RR 4/30/2072
2020 PO8337062900	ODP	4	40 XXX	SP	CRE		ID		BD	5/1/2072
2020 PO8325062784	ODP	4	40 XXX	SP	CCA		V			5/2/2072
2020 PO6803752940	ODP	4	40 XXX	SP	CRE		V			5/3/2072
2020 PO6852553935	ODP	5	35 XXX	SP	CRE		V			5/4/2072
2020 PO6827653894	ODP	4	40 XXX	SP	CRE		V			5/5/2072
2020 PO6796253945	ODP	4	40 XXX	SP	CRE		V			5/6/2072
2020 PO6805553104	ODP	4	40 XXX	SP	CRE		V			5/7/2072
2020 PO6880553985	ODP	4	35 XXX	SP	CRE		V			5/8/2072
2020 PO6800253920	ODP	4	40 XXX	SP	CRE		V			5/9/2072
2020 PO6784854162	ODP	4	40 XXX	SP	CRE		V			5/10/2072
2020 PO0164852995	ODP	5	35 XXX	SP	CRE		ID		TD	5/11/2072
2020 PO0211752648	ODP	5	35 XXX	SP	CRE		ID		BD	5/12/2072
2020 PO0081551508	ODP	5	35 XXX	SP	CRE		ID		BD	5/13/2072
2020 PO0105451674	ODP	5	35 XXX	SP	CRE		ID		TD	5/14/2072
2020 PO0135751669	ODP	5	35 XXX	SP	CRE		ID		TD	5/15/2072
2020 PO0240651098	ODP	4	40 XXX	SP	CRE		ID		TD	5/16/2072
2020 PO0215452036	ODP	4	45 XXX	SP	CRE		ID		TD	5/17/2072
2020 PO4701388081	F	4	40 BRO	SP	CCA		V			5/18/2072
2020 PO4700688075	F	4	30 BRO	SP	A		V			5/19/2072
2020 PO4701888071	F	4	35 BRO	SP	CCA		V			5/20/2072
2020 PO4701588080	F	3	45 BRO	SP	S		V			5/21/2072
2020 PO4702288085	F	4	40 BRO	SP	A		V			5/22/2072
2020 PO4702988096	F	4	30 BRO	SP	CRE		V			5/23/2072
2020 PO4703288091	F	3	45 BRO	SP	CCA		V			5/24/2072
2020 PO4705088103	F	4	40 BRO	SP	CCA		V			5/25/2072
2020 PO4707088108	LGE	4	35 BRO	SP	A		ED,ID		TD	5/26/2072
2020 PO4680588050	LGE	4	35 BRO	SP	CRE		ED,ID		TD	5/27/2072

Business Use

2020 PO4681088040	LGE	4	40 BRO	SP	CRE	ED,ID	TD	5/28/2072
2020 PO4705788102	F	6	25 BRO	SP	CRE		V	5/29/2072
2020 PO4705888107	F	3	35 BRO	SP	S		V	5/30/2072
2020 PO4705588114	LGE	3	30 BRO	SP	CRE		V	5/31/2072
2020 PO4705488108	F	4	40 BRO	SP	S		V	6/1/2072
2020 PO4704888114	LGE	4	30 BRO	SP	A		BD	6/2/2072
2020 PO4704988120	F	3	45 BRO	SP	S		V	6/3/2072
2020 PO4703688127	LGE	4	30 BRO	SP	A	ED,ID	TD	6/4/2072
2020 PO4704188131	LGE	4	35 BRO	SP	CCA		V	6/5/2072
2020 PO4704588131	F	3	45 BRO	SP	S		V	6/6/2072
2020 PO4704088144	F	3	45 BRO	SP	S		V	6/7/2072
2020 PO4702588140	LGE	4	35 BRO	SP	S		V	6/8/2072
2020 PO4703788153	F	3	45 BRO	SP	CCA		V	6/9/2072
2020 PO4703588158	F	3	45 BRO	SP	S		V	6/10/2072
2020 PO0448846662	ODP	5	35 ACW	SP	CRE	ID	BD	6/11/2072
2020 PO0350446783	ODP	4	40 ACW	SP	CRE	ED,ID	TD	6/12/2072
2020 PO0356546750	ODP	4	40 ACW	SP	CRE	ID	BD	6/13/2072
2020 PO0362846717	ODP	4	40 ACW	SP	CRE	ED,ID	TD	6/14/2072
2020 PO0323046566	ODP	4	40 ACW	DF	CRE	ID	BD	6/15/2072
2020 PO4703088171	LGE	1	50 BRO	SP	S		V	6/16/2072
2020 PO4702588184	F	3	45 BRO	SP	S		V	6/17/2072
2020 PO4698788197	LGE	4	40 BRO	SP	A		B	6/18/2072
2020 PO4697888191	LGE	4	35 BRO	SP	A		B	6/19/2072
2020 PO4696888181	LGE	4	35 BRO	SP	A		B	6/20/2072
2020 PO4697388173	LGE	4	35 BRO	SP	A		V	6/21/2072
2020 PO4698688177	LGE	4	35 BRO	SP	A		V	6/22/2072
2020 PO4699288181	LGE	4	40 BRO	SP	A		B	6/23/2072
2020 PO4700988192	LGE	3	45 BRO	SP	S		V	6/24/2072
2020 PO4676688016	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	6/25/2072
2020 PO4676588006	LGE	4	40 BRO	SP	A	ED,ID	TD	6/26/2072
2020 PO4676487997	LGE	4	40 BRO	SP	CRE	ED,ID	TD	6/27/2072
2020 PO4676387983	LGE	4	40 BRO	SP	P	ED,ID	BD	6/28/2072
2020 PO4703788201	F	4	40 BRO	SP	CRE		V	6/29/2072
2020 PO4703388211	F	4	40 BRO	SP	CCA		V	6/30/2072
2020 PO4703188216	F	4	35 BRO	SP	CRE		V	7/1/2072
2020 PO4701988198	F	3	45 BRO	SP	S		V	7/2/2072
2020 PO4701588209	F	4	40 BRO	SP	CCA		V	7/3/2072
2020 PO4701288209	F	UNK	25 BRO	SP	A		V	7/4/2072
2020 PO4701288218	F	4	40 BRO	SP	CCA		V	7/5/2072
2020 PO4701088214	LGE	4	40 BRO	SP	A	ED,ID	TD	7/6/2072
2020 PO5171210573	F	4	40 BRO	SP	CRE		V	7/7/2072
2020 PO4700788232	F	4	40 BRO	SP	CRE		V	7/8/2072
2020 PO4700288245	F	4	40 BRO	SP	A		V	7/9/2072
2020 PO469988259	F	4	40 BRO	SP	CRE		V	7/10/2072
2020 PO4793416626	F	4	40 BRO	SP	CRE		V	7/11/2072
2020 PO5126010955	F	4	40 BRO	SP	CRE		V	7/12/2072
2020 PO5265511454	F	4	40 BRO	SP	CCA		V	7/13/2072

2020 PO4699788266	F	3	45 BRO	SP	CCA		V	7/14/2072
2020 PO4110696291	LGE	3	45 BRO	SP	CCA		V	7/15/2072
2020 PO5021811891	KU	4	40 BRO	SP	CCA		V	7/16/2072
2020 PO5020111811	F	4	40 BRO	SP	CRE		V	7/17/2072
2020 PO5023311885	F	4	40 BRO	SP	CRE		V	7/18/2072
2020 PO4695888357	LGE	4	30 BRO	SP	P	ED,ID	TD	7/19/2072
2020 PO4695388364	LGE	3	45 BRO	SP	A	ED,ID	BD	7/20/2072
2020 PO8988841603A	ODP	5	35 ACW	SP	CRE	ED,ID	TD	7/21/2072
2020 PO4696488350	LGE	4	35 BRO	SP	CRE	ED,ID	BD	7/22/2072
2020 PO4697088340	LGE	4	40 BRO	SP	A	ED,ID	BX	RR 7/23/2072
2020 PO4689387618	F	3	45 BRO	SP	A		V	7/24/2072
2020 PO4693987548	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	7/25/2072
2020 PO4690687478	LGE	4	40 BRO	SP	CRE	ED,ID	TD	7/26/2072
2020 PO4694087500	LGE	4	40 BRO	SP	P	ED,ID	T	7/27/2072
2020 PO4695888319-B	LGE	4	35 BRO	SP	CCA		V	7/28/2072
2020 PO4695888319-A	LGE	4	35 BRO	SP	CCA		V	7/29/2072
2020 PO5091656822	KU	4	40 OTH	SP	CRE	ID	TD	7/30/2072
2020 PO5073856998	KU	4	40 OTH	SP	CRE	ID	TD	7/31/2072
2020 PO5126556468	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	8/1/2072
2020 PO5013457621	KU	4	40 OTH	SP	CRE	ID	TD	8/2/2072
2020 PO5039357360	KU	4	40 OTH	SP	CRE	ID	TD	8/3/2072
2020 PO5109256639	KU	4	40 OTH	SP	CRE	ID	TD	8/4/2072
2020 PO4943756875	KU	4	45 OTH	SP	CRE	ID	TD	8/5/2072
2020 PO5056257188	KU	4	40 OTH	SP	CRE	ID	TD	8/6/2072
2020 PO4980357260	KU	4	45 OTH	SP	CRE	ID	TD	8/7/2072
2020 PO4695288322	LGE	4	40 BRO	SP	A	ED,ID	BD	8/8/2072
2020 PO4695588317	LGE	4	40 BRO	SP	A	ED,ID	BD	8/9/2072
2020 PO4695888319	LGE	4	40 BRO	SP	CRE	ED,ID	BD	8/10/2072
2020 PO4696088317	LGE	4	35 BRO	SP	A	ED,ID	TD	8/11/2072
2020 PO4479204402	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/12/2072
2020 PO9898093789	KU	4	40 ACW	SP	CRE	ED,ID	TD	8/13/2072
2020 PO9884593646	KU	4	40 ACW	SP	CRE	ED,ID	TD	8/14/2072
2020 PO9820792258	KU	5	35 ACW	SP	S		V	8/15/2072
2020 PO9820592404	KU	4	40 ACW	SP	S		V	8/16/2072
2020 PO9833092571	KU	4	40 ACW	SP	S		V	8/17/2072
2020 PO4695788315	LGE	4	30 BRO	SP	A	ED,ID	BD	8/18/2072
2020 PO9818692723	KU	4	40 ACW	SP	CRE	ED,ID	TD	8/19/2072
2020 PO9840592731	KU	6	30 ACW	SP	CRE	ED,ID	TD	8/20/2072
2020 PO9789792974	KU	5	35 ACW	SP	CCA		V	8/21/2072
2020 PO9824692766	KU	4	40 ACW	SP	CRE	ED,ID	TD	8/22/2072
2020 PO9781192935	KU	6	30 ACW	SP	CCA		V	8/23/2072
2020 PO9734892384	KU	6	30 ACW	SP	CCA		V	8/24/2072
2020 PO9742592063	KU	6	30 ACW	SP	CCA		V	8/25/2072
2020 PO9774793004	KU	6	30 ACW	SP	CCA		V	8/26/2072
2020 PO9752091859	KU	6	30 ACW	SP	CCA		V	8/27/2072
2020 PO9738392353	KU	6	30 ACW	SP	CCA		V	8/28/2072
2020 PO5247047318	F	4	40 ACE	SP	CRE		V	8/29/2072

Business Use

2020 PO9735292253	KU	4	40 ACW	SP	CRE		V	8/30/2072	
2020 PO5241647467	KU	4	40 ACE	SP	CCA		V	8/31/2072	
2020 PO5242547495	KU	1	40 ACE	SP	CCA		V	9/1/2072	
2020 PO9755692210	KU	4	40 ACW	SP	CRE	ED,ID	TD	9/2/2072	
2020 PO4696787517	F	3	45 BRO	SP	CCA		V	9/3/2072	
2020 PO4695787530	F	4	45 BRO	SP	A		V	9/4/2072	
2020 PO4774187470	LGE	4	40 BRO	SP	CCA	ED,ID	BD	9/5/2072	
2020 PO4761087475	LGE	3	45 BRO	SP	A	ED,ID	BD	9/6/2072	
2020 PO4681588029	LGE	4	40 BRO	SP	CRE	ED,ID	BD	9/7/2072	
2020 PO4682088028	LGE	4	35 BRO	SP	CRE	ED,ID	TD	9/8/2072	
2020 PO4685188023	LGE	4	40 BRO	SP	A	ED,ID	BD	9/9/2072	
2020 PO4685288036	LGE	4	40 BRO	SP	P	ED,ID	TD	9/10/2072	
2020 PO4679288073	LGE	3	45 BRO	SP	CCA		V	9/11/2072	
2020 PO4678988333	LGE	4	40 BRN	SP	CRE	ED,ID	BD	9/12/2072	
2020 PO4678488340	LGE	3	45 BRN	SP	CRE	ED,ID,IP	BD	9/13/2072	
2020 PO4677588358	LGE	6	25 BRN	SP	CRE	ED,ID	BD	9/14/2072	
2020 PO4677988347	LGE	3	45 BRN	SP	CRE	ED,ID	TD	9/15/2072	
2020 PO4677288356	LGE	3	45 BRN	SP	CCA		V	9/16/2072	
2020 PO5105212612	F	4	40 BRO	SP	CCA		V	9/17/2072	
2020 PO5096312569	F	4	40 BRO	SP	CRE		V	9/18/2072	
2020 PO5120212739	F	4	40 BRO	SP	A		V	9/19/2072	
2020 PO9182628891	F	4	40 XXX	SP	CRE	HH,ID,RB	BX	RP1	9/20/2072
2020 PO5034213198	F	4	40 BRO	SP	CRE		V	9/21/2072	
2020 PO5026412916	F	4	40 BRO	SP	CRE	ID,IP	VX	RP2	9/22/2072
2020 PO5051312681	F	4	40 BRO	SP	CRE		V	9/23/2072	
2020 PO5085412516	F	4	40 BRO	SP	A		V	9/24/2072	
2020 PO5082212633	F	4	40 BRO	SP	A		V	9/25/2072	
2020 PO5077512489	F	4	40 BRO	SP	CCA		V	9/26/2072	
2020 PO5047412350	F	4	40 BRO	SP	CRE		V	9/27/2072	
2020 PO5053712371	F	4	40 BRO	SP	CRE		V	9/28/2072	
2020 PO4679988063	LGE	4	40 BRO	SP	CRE		V	9/29/2072	
2020 PO5037212221	F	4	40 BRO	SP	CRE		V	9/30/2072	
2020 PO5025712299	F	4	40 BRO	SP	CRE		V	10/1/2072	
2020 PO5015312373	F	4	40 BRO	SP	CRE		V	10/2/2072	
2020 PO5005212421	F	4	40 BRO	SP	CRE		V	10/3/2072	
2020 PO5045112669	F	4	40 BRO	SP	CCA		V	10/4/2072	
2020 PO5038812840	F	4	40 BRO	SP	CRE		V	10/5/2072	
2020 PO5033212735	F	4	40 BRO	SP	CRE		V	10/6/2072	
2020 PO4630688197	LGE	4	40 BRO	SP	CRE	ED,ID,RB	BX	PX	10/7/2072
2020 PO462888199	LGE	3	50 BRO	SP	CCA		V	10/8/2072	
2020 PO5198011830	F	4	40 BRO	SP	CRE		V	10/9/2072	
2020 PO5186611877	F	4	40 BRO	SP	CRE		V	10/10/2072	
2020 PO5174811925	F	4	40 BRO	SP	CRE		V	10/11/2072	
2020 PO5166111961	F	4	40 BRO	SP	CRE		V	10/12/2072	
2020 PO8799334162	ODP	5	35 XXX	SP	CRE	ID	BD	10/13/2072	
2020 PO8799033961	F	4	40 XXX	SP	A		V	10/14/2072	
2020 PO8795533542	F	4	40 XXX	SP	A		V	10/15/2072	

2020 PO8797033787	ODP		5	35 XXX	SP	CRE	ID	BD		10/16/2072
2020 PO8753632953	ODP		6	30 XXX	SP	CRE	ID	TD		10/17/2072
2020 PO8793933265	F		4	40 XXX	SP	P		V		10/18/2072
2020 PO8789232494	ODP		5	35 XXX	SP	CRE	ID	TD		10/19/2072
2020 PO8790532842	F		4	40 XXX	SP	CRE		V		10/20/2072
2020 PO8825432286	ODP		4	45 XXX	SP	CCA		V		10/21/2072
2020 PO8818232473	ODP		4	40 XXX	SP	CCA		V		10/22/2072
2020 PO9245534574	F		4	40 XXX	SP	A		V		10/23/2072
2020 PO9246634329	F		4	40 XXX	SP	CRE		V		10/24/2072
2020 PO9245934052	ODP		4	40 XXX	SP	CRE	ID	TD		10/25/2072
2020 PO3806190538	KU		4	40 XXX	SP	CRE	ID	BX	RP2	10/26/2072
2020 PO3808290608	F		5	30 XXX	SP	A		V		10/27/2072
2020 PO3803090572	F		5	30 XXX	SP	A		V		10/28/2072
2020 PO4659788250	LGE		4	40 BRN	SP	A	ED,ID	BD		10/29/2072
2020 PO4650889103	LGE		4	35 BRO	SP	CRE	ED,ID,IP	TD		10/30/2072
2020 PO3781990426	F		5	30 XXX	SP	A	ED,ID	BX	PX	10/31/2072
2020 PO4650389109	LGE		5	25 BRO	SP	CRE	ED,ID,IP	TD		11/1/2072
2020 PO3795790408	F		5	35 XXX	SP	A		V		11/2/2072
2020 PO3797290474	KU		4	40 XXX	SP	CRE	ID	BD		11/3/2072
2020 PO3788090613	KU		4	40 XXX	SP	CRE	ID	BD		11/4/2072
2020 PO3782090620	F		4	40 XXX	SP	CCA		V		11/5/2072
2020 PO3788990516	F		4	40 XXX	SP	A		V		11/6/2072
2020 PO3773390311	F		3	40 XXX	SP	A	ID,RB	BX	RP1	11/7/2072
2020 PO3780490360	KU		4	40 XXX	SP	CRE	ID	BD		11/8/2072
2020 PO3739690554	F		4	40 XXX	SP	CRE		V		11/9/2072
2020 PO3755490312	F		4	40 XXX	SP	CRE		V		11/10/2072
2020 PO3760990229	F		4	40 XXX	SP	CRE		V		11/11/2072
2020 PO4663188184	LGE		6	25 BRN	SP	CRE	ED,ID,SRS	TX	RR	11/12/2072
2020 PO3853789679	F		4	40 XXX	SP	CRE		V		11/13/2072
2020 PO3861689716	F		4	40 XXX	SP	CRE		V		11/14/2072
2020 PO3873789778	F		4	40 XXX	SP	CRE		V		11/15/2072
2020 PO3886289840	F		4	40 XXX	SP	CRE		V		11/16/2072
2020 PO3901689926	F		4	40 XXX	SP	CRE		V		11/17/2072
2020 PO4708087931	LGE		3	50 BRO	SP	CRE	ED,ID,IP,RB	TX	RR	11/18/2072
2020 PO4706687924	F	UNK		45 BRO	SP	CCA		V		11/19/2072
2020 PO4755887875	F		4	30 BRO	SP	CRE	ED,ID	VX	RP2	11/20/2072
2020 PO4720787910	F		4	35 BRO	SP	CRE	HH,RB	VX	RP2	11/21/2072
2020 PO4709287930	LGE	UNK		75 BRO	SP	CRE	HH,RB	VX	PX	11/22/2072
2020 PO4710387929	LGE		3	50 BRO	SP	CRE	ED,ID	TD		11/23/2072
2020 PO4711287920	LGE		3	45 BRO	SP	CRE	ED,ID,IP	BD		11/24/2072
2020 PO4711387945	LGE	UNK		20 BRO	ST	CRE		V		11/25/2072
2020 PO4727087934	LGE		4	40 BRO	SP	CRE	ED,ID	TD		11/26/2072
2020 PO4727187932	LGE		4	40 BRO	SP	CRE	ED,ID	BD		11/27/2072
2020 PO4726787930	LGE		4	30 BRO	SP	CRE		V		11/28/2072
2020 PO4668388105	LGE		4	25 BRN	SP	A	ED,ID,SRS	TX	RR	11/29/2072
2020 PO4729587909	LGE	UNK		70 BRO	SP	CRE		V		11/30/2072
2020 PO4731387907	LGE		3	50 BRO	SP	CRE	ED,ID	BD		12/1/2072

2020 PO4731587907	LGE	UNK	70 BRO	SP	CRE		V	12/2/2072
2020 PO4731887906	LGE	3	50 BRO	SP	A	ED,ID	TD	12/3/2072
2020 PO4731287897	LGE	3	45 BRO	SP	CCA		V	12/4/2072
2020 PO4733487896	F	3	50 BRO	SP	CRE		V	12/5/2072
2020 PO4736387902	LGE	UNK	65 BRO	SP	CRE		V	12/6/2072
2020 PO4738887899	LGE	UNK	70 BRO	SP	CRE		V	12/7/2072
2020 PO4741487897	LGE	UNK	65 BRO	SP	CRE		V	12/8/2072
2020 PO4744087898	LGE	4	30 BRO	SP	P	ED,ID	TD	12/9/2072
2020 PO4744287894	LGE	UNK	70 BRO	SP	CRE		V	12/10/2072
2020 PO4746887891	LGE	UNK	70 BRO	SP	CRE		V	12/11/2072
2020 PO4749587889	LGE	UNK	70 BRO	SP	CRE		V	12/12/2072
2020 PO4752087887	LGE	UNK	70 BRO	SP	CRE		V	12/13/2072
2020 PO5866605388	KU	4	40 XXX	SP	CRE	ED,ID	TD	12/14/2072
2020 PO5838805345	KU	4	45 XXX	SP	CRE	ED,ID	TD	12/15/2072
2020 PO5814005199	KU	4	45 XXX	SP	CCA		V	12/16/2072
2020 PO9631493825	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	12/17/2072
2020 PO9633993831	KU	4	40 ACW	SP	CRE	ED,ID	TD	12/18/2072
2020 PO3985982755	F	3	45 BRN	SP	CCA		V	12/19/2072
2020 PO4679436992	KU	1	60 BRO	SP	CCA		V	12/20/2072
2020 PO4669336965	KU	2	45 BRO	SP	CCA		V	12/21/2072
2020 PO4670936931	KU	1	50 BRO	SP	CCA		V	12/22/2072
2020 PO4658736839	KU	3	45 BRO	SP	CRE	ED,RB	X	RP1 12/23/2072
2020 PO4669336965-A	KU	3	45 BRO	SP	CCA		V	12/24/2072
2020 PO3982482745	F	4	40 BRN	SP	CCA		V	12/25/2072
2020 PO3982482751	F	1	55 BRN	SP	CCA		V	12/26/2072
2020 PO3983982753	F	1	50 BRN	SP	CCA		V	12/27/2072
2020 PO3984382748	F	4	30 BRN	SP	CCA		V	12/28/2072
2020 PO1079733716	ODP	5	45 XXX	SP	CRE	ED,ID	TD	12/29/2072
2020 PO1088033799	ODP	5	30 XXX	SP	CRE	ED,ID	TD	12/30/2072
2020 PO4654937207	KU	2	55 BRO	SP	CCA		V	12/31/2072
2020 PO4668437101	KU	2	55 BRO	SP	CCA		V	1/1/2073
2020 PO4668137060	KU	3	45 BRO	SP	CCA		V	1/2/2073
2020 PO4636836939	KU	3	45 BRO	SP	CRE	ID,IP	BD	1/3/2073
2020 PO3984082706	LGE	4	35 BRN	SP	A	ED,ID	TD	1/4/2073
2020 PO3923183140	F	4	40 BRO	SP	CCA		V	1/5/2073
2020 PO3922083157	F	5	25 BRO	SP	A		V	1/6/2073
2020 PO3922883157	F	4	40 BRO	SP	P		V	1/7/2073
2020 PO1058933967	ODP	4	45 BRN	SP	CRE		V	1/8/2073
2020 PO1074034029	ODP	3	50 BRN	SP	CRE		V	1/9/2073
2020 PO1088034392	ODP	5	30 BRN	SP	CRE		V	1/10/2073
2020 PO3922583172	F	4	40 BRO	SP	P		V	1/11/2073
2020 PO3922383187	F	4	40 BRO	SP	P	ED,ID,RB	VX	RP2 1/12/2073
2020 PO3982882705	F	4	35 BRN	SP	A		V	1/13/2073
2020 PO3982982685	LGE	3	45 BRN	SP	A	ED,ID	TD	1/14/2073
2020 PO3981982673	LGE	4	35 BRN	SP	CCA		V	1/15/2073
2020 PO3981082685	F	4	40 BRN	SP	CCA		V	1/16/2073
2020 PO3980982706	LGE	3	45 BRN	SP	S		V	1/17/2073

2020 PO1859540623	ODP	4	45 KOP	SP	CRE	ED,ID,MD,SRC	TD	1/18/2073	
2020 PO1846440894	ODP	4	40 KOP	SP	A	ED,ID	TD	1/19/2073	
2020 PO1850940797	F	4	40 KOP	SP	CCA		V	1/20/2073	
2020 PO1851740650	ODP	6	30 KOP	SP	CRE	ED,ID	TD	1/21/2073	
2020 PO1839641079	ODP	2	55 KOP	SP	A	ED,ID	TD	1/22/2073	
2020 PO4376356490	F	3	45 OTH	SP	P		V	1/23/2073	
2020 PO4416956742	F	4	45 OTH	SP	P		V	1/24/2073	
2020 PO4460057020	F	3	45 OTH	SP	P		V	1/25/2073	
2020 PO4505357300	F	3	45 OTH	SP	P		V	1/26/2073	
2020 PO4484457171	F	3	45 OTH	SP	CCA		V	1/27/2073	
2020 PO4343456565	KU	4	40 OTH	SP	CRE	ID	TD	1/28/2073	
2020 PO4376356751	KU	5	40 OTH	SP	CRE	ED,ID	TD	1/29/2073	
2020 PO4717088085	LGE	3	45 BRO	SP	P	ED	T	1/30/2073	
2020 PO4720288094	LGE	4	30 BRO	SP	CCA	ED,ID	BD	1/31/2073	
2020 PO4721888106	LGE	4	35 BRO	SP	CCA	ED,ID	BD	2/1/2073	
2020 PO4723688116	LGE	4	30 BRO	SP	P	ED,ID,IP,MD,RB	BX	2/2/2073	PX
2020 PO4809088879	LGE	4	40 BRN	SP	CRE	ED,ID	TD	2/3/2073	
2020 PO4774112434	F	4	40 ACE	SP	CRE		V	2/4/2073	
2020 PO4807488874	LGE	4	40 BRN	SP	CRE	ED,ID	BD	2/5/2073	
2020 PO4762812480	F	4	40 ACE	SP	CRE		V	2/6/2073	
2020 PO4803088821	LGE	4	40 BRN	SP	CRE	ED,ID	BD	2/7/2073	
2020 PO4804188825	LGE	4	40 BRN	SP	CCA	ED,HH,ID	VX	2/8/2073	PX
2020 PO4694312767	F	4	40 ACE	SP	CRE		V	2/9/2073	
2020 PO4708512709	F	4	40 ACE	SP	CRE		V	2/10/2073	
2020 PO4685212810	F	4	40 ACE	SP	CRE		V	2/11/2073	
2020 PO4283156181	KU	4	45 OTH	SP	CCA		V	2/12/2073	
2020 PO4266155850	KU	5	35 OTH	SP	CRE	ID	TD	2/13/2073	
2020 PO4306456336	KU	2	45 OTH	SP	CCA		V	2/14/2073	
2020 PO4265856060	KU	4	40 OTH	SP	CRE	ID	TD	2/15/2073	
2020 PO4805788831	LGE	4	45 BRN	SP	CRE	ED,ID	BD	2/16/2073	
2020 PO4806788835	LGE	4	40 BRN	SP	CRE	ED,ID	TD	2/17/2073	
2020 PO4807788840	LGE	4	40 BRN	SP	CRE	ED,ID	BD	2/18/2073	
2020 PO4806988889	LGE	4	40 BRN	SP	CRE	ED,HH,ID	BX	2/19/2073	RR
2020 PO4803488894	LGE	4	40 BRN	SP	CRE	ED,ID	BD	2/20/2073	
2020 PO4806488903	LGE	4	40 BRN	SP	CRE	ED,ID,IP	BD	2/21/2073	
2020 PO4726588145	LGE	3	45 BRO	SP	CCA		V	2/22/2073	
2020 PO4727488152	LGE	4	40 BRO	SP	CCA	ED,ID,IP	BD	2/23/2073	
2020 PO4726288169	LGE	4	40 BRO	SP	A	ED,ID	BD	2/24/2073	
2020 PO4727488177	LGE	4	40 BRO	SP	CCA	ED,ID	BD	2/25/2073	
2020 PO4715587915	LGE	4	35 BRO	SP	CCA	ED,ID	BD	2/26/2073	
2020 PO4716387915	LGE	4	35 BRO	SP	CCA		V	2/27/2073	
2020 PO4716887914	F	4	40 BRO	SP	CCA		V	2/28/2073	
2020 PO4715187915	F	4	40 BRO	SP	CCA		V	3/1/2073	
2020 PO4802988908	LGE	4	40 BRN	SP	CRE	ED,ID	BD	3/2/2073	
2020 PO4805988918	LGE	4	40 BRN	SP	CCA		V	3/3/2073	
2020 PO4932712903	F	4	40 ACE	SP	CRE		V	3/4/2073	
2020 PO4233856083	KU	4	40 OTH	SP	CRE	ID	TD	3/5/2073	

2020 PO4245755920	KU	3	45 OTH	SP	CCA		V	3/6/2073
2020 PO4937213177	KU	6	35 ACE	SP	CRE	ED,ID,IP	TD	3/7/2073
2020 PO4853812100	F	4	40 BRO	SP	CRE		V	3/8/2073
2020 PO4838412164	F	4	40 BRO	SP	CRE		V	3/9/2073
2020 PO4667887965	F	UNK	35 BRO	SP	CRE		V	3/10/2073
2020 PO4668687965	LGE	3	50 BRO	ST	CCA		V	3/11/2073
2020 PO4668987942	LGE	4	35 BRO	SP	CRE		V	3/12/2073
2020 PO4825612217	F	4	40 BRO	SP	CRE		V	3/13/2073
2020 PO4813412270	F	4	40 BRO	SP	A		V	3/14/2073
2020 PO4799612327	F	4	40 BRO	SP	CRE		V	3/15/2073
2020 PO4670787961	LGE	3	50 BRO	SP	CRE		V	3/16/2073
2020 PO4670787963	F	4	35 BRO	SP	CRE		V	3/17/2073
2020 PO4672287962	F	4	35 BRO	SP	CRE		V	3/18/2073
2020 PO4673987960	F	4	40 BRO	SP	CRE		V	3/19/2073
2020 PO4670987959	LGE	3	50 BRO	SP	CRE	ED,ID	BD	3/20/2073
2020 PO479988992	LGE	4	40 BRN	SP	CCA	ED,ID	BD	3/21/2073
2020 PO4800188983	LGE	4	40 BRN	SP	CCA	ED,ID	BD	3/22/2073
2020 PO4801288954	LGE	4	40 BRN	SP	CRE	ED,ID	BD	3/23/2073
2020 PO4787312378	F	4	40 BRO	SP	CRE		V	3/24/2073
2020 PO4632688025	LGE	3	50 BRO	SP	CRE	ED,ID,RB	BX	RP3 3/25/2073
2020 PO4632688011	LGE	4	40 BRO	SP	CCA		V	3/26/2073
2020 PO5301454054A	KU	4	40 OTH	SP	CRE	ID	BD	3/27/2073
2020 PO5465952139	KU	4	40 OTH	SP	CCA		V	3/28/2073
2020 PO4736487892	LGE	4	40 BRO	SP	CCA		V	3/29/2073
2020 PO4638588005	F	4	30 BRO	SP	CRE		V	3/30/2073
2020 PO4675888321-A	LGE	4	40 BRN	SP	A	ED,ID	TD	3/31/2073
2020 PO4675988315	LGE	4	30 BRN	SP	A	ED,HH,ID,RB	BX	PX 4/1/2073
2020 PO4675888321	LGE	4	40 BRN	SP	A	ED,ID	TD	4/2/2073
2020 PO4675588325	LGE	4	40 BRN	SP	P		T	4/3/2073
2020 PO4736387890	LGE	4	40 BRO	SP	CRE	ED,ID	BD	4/4/2073
2020 PO4639488004	F	3	50 BRO	SP	CRE		V	4/5/2073
2020 PO4640387994	LGE	1	55 BRO	SP	CCA		V	4/6/2073
2020 PO4640288002	F	UNK	60 BRO	SP	CRE		V	4/7/2073
2020 PO4642288012	LGE	3	45 BRO	SP	CCA		V	4/8/2073
2020 PO4642088000	F	2	55 BRO	SP	CCA		V	4/9/2073
2020 PO4643587999	F	3	50 BRO	SP	CCA		V	4/10/2073
2020 PO4679488018	LGE	4	35 BRO	SP	CCA		V	4/11/2073
2020 PO5019313684	F	4	40 BRO	SP	CRE		V	4/12/2073
2020 PO5007113738	F	4	40 BRO	SP	CRE		V	4/13/2073
2020 PO4671388371	LGE	4	30 BRN	SP	A	ED,ID	TX	RR 4/14/2073
2020 PO5003913751	F	4	40 BRO	SP	A		V	4/15/2073
2020 PO5000713765	F	4	40 BRO	SP	CRE		V	4/16/2073
2020 PO9094740335	F	4	40 ACW	SP	P		V	4/17/2073
2020 PO9075040458	ODP	4	40 ACW	SP	CRE	ED,ID	TD	4/18/2073
2020 PO9048240725	ODP	4	40 ACW	SP	CRE	ED,ID	TD	4/19/2073
2020 PO9029540901B	F	5	30 ACW	SP	CCA		V	4/20/2073
2020 PO9029540901A	F	4	30 ACW	SP	CRE		V	4/21/2073

2020 PO9029540901	ODP	4	40 ACW	SP	CRE	ED,ID	TD	4/22/2073	
2020 PO9003541395	ODP	4	40 ACW	SP	S		V	4/23/2073	
2020 PO8989141435	F	5	35 ACW	SP	P		V	4/24/2073	
2020 PO8988841603	ODP	5	35 ACW	SP	CRE	ED,ID	TD	4/25/2073	
2020 PO4767887473	LGE	4	40 BRO	SP	P	ED,ID	BX	RR	4/26/2073
2020 PO466664	LGE	4	40 BRN	DF	CRE	ED,ID,SRS	TX	RR	4/27/2073
2020 PO4666688034	LGE	3	45 BRN	SP	A	ED,ID	BD	4/28/2073	
2020 PO3766593054	LGE	4	45 BRN	SP	A	ED,ID,SRS	TX	RR	4/29/2073
2020 PO8637137408	ODP	4	35 BRO	DF	A	ID	BD	4/30/2073	
2020 PO8635637542	ODP	4	45 BRO	SP	CRE	ED,ID	TD	5/1/2073	
2020 PO8600438565	ODP	4	40 BRO	SP	CRE	ED,ID	TD	5/2/2073	
2020 PO8631637748	ODP	4	35 BRO	SP	A	ED,ID	TD	5/3/2073	
2020 PO4678688114	LGE	4	40 BRN	SP	A	ED,ID	TD	5/4/2073	
2020 PO4679488120	LGE	4	35 BRN	SP	CRE	ED,ID	BD	5/5/2073	
2020 PO4680288125	LGE	4	35 BRN	SP	A	ED,ID	BD	5/6/2073	
2020 PO4679788134	LGE	3	50 BRN	SP	CCA		V	5/7/2073	
2020 PO6207717315	KU	4	40 XXX	SP	CRE	ED,ID	TD	5/8/2073	
2020 PO4681188131	LGE	4	40 BRN	SP	A	ED,ID	BD	5/9/2073	
2020 PO4681888136	LGE	4	40 BRN	SP	A	ED,ID	BD	5/10/2073	
2020 PO4682788142	LGE	4	35 BRN	SP	CCA		V	5/11/2073	
2020 PO6195417365	KU	5	35 XXX	SP	CRE	ED,ID	TD	5/12/2073	
2020 PO6213517533	KU	4	40 XXX	SP	CRE	ID	BD	5/13/2073	
2020 7576439626	KU	5	40 OTH	SP	CRE	ED,EP,ID,SRC	TX	RR	5/14/2073
2020 PO7576439626	KU	5	35 OTH	SP	CRE	ID	TD	5/15/2073	
2020 PO4680387759	F	4	40 BRO	SP	CRE		V	5/16/2073	
2020 PO4894560150	KU	4	40 OTH	SP	CRE	ID	TD	5/17/2073	
2020 PO4945159502	KU	4	40 OTH	SP	CRE	ED,ID	TD	5/18/2073	
2020 PO4962559275	KU	4	45 OTH	SP	CCA		V	5/19/2073	
2020 PO4877360375	KU	4	40 OTH	SP	CRE	ID	TD	5/20/2073	
2020 PO4849660741	KU	4	40 OTH	SP	CRE	ID	TD	5/21/2073	
2020 PO4713711164	KU	5	35 BRO	SP	CRE		V	5/22/2073	
2020 PO3928750782	F	7	25 OTH	SP	CRE		V	5/23/2073	
2020 PO3931550846	F	2	40 OTH	SP	P		V	5/24/2073	
2020 PO3922750930	F	5	40E OTH	SP	CRE		V	5/25/2073	
2020 PO3913351232	KU	4	40 OTH	SP	CCA		V	5/26/2073	
2020 PO3907751373	F	3	40 OTH	SP	CRE		V	5/27/2073	
2020 PO3893151569	F	6	30 OTH	SP	CCA		V	5/28/2073	
2020 PO3939951606	F	4	40 OTH	SP	CRE		V	5/29/2073	
2020 PO3924516666	KU	4	40 OTH	SP	CRE		B	5/30/2073	
2020 PO3919851565	F	5	35 OTH	SP	CRE		V	5/31/2073	
2020 PO3896951707	F	4	40 OTH	WC	CRE		V	6/1/2073	
2020 PO3900351594	F	4	40 OTH	SP	CCA		V	6/2/2073	
2020 PO3892451588	KU	5	35 OTH	SP	CCA		V	6/3/2073	
2020 PO3892451807	F	4	40 OTH	SP	CRE		V	6/4/2073	
2020 PO3865951962	KU	4	45 OTH	SP	CCA		V	6/5/2073	
2020 PO3931550846A	KU	5	35 XXX	SP	CCA		V	6/6/2073	
2020 PO4040150345	F	4	40 BRN	SP	CRE		V	6/7/2073	

2020 PO4069250117	F	4	40 BRN	SP	CRE		V	6/8/2073
2020 PO4088349990	F	4	40 BRN	SP	CCA		V	6/9/2073
2020 PO3940350794	F	4	40 XXX	SP	P		V	6/10/2073
2020 PO3984150607	F	2	45 XXX	SP	P		V	6/11/2073
2020 PO4028850402	F	4	40 BRN	SP	CRE		V	6/12/2073
2020 PO4047950305	F	4	40 BRN	SP	CRE		V	6/13/2073
2020 PO3970750663	F	4	40 XXX	SP	CRE		V	6/14/2073
2020 PO4074150176	KU	6	30 BRN	SP	CCA		V	6/15/2073
2020 PO4001850532	F	4	40 KOP	SP	CRE		V	6/16/2073
2020 PO4016550464	F	4	40 BRN	SP	CRE		V	6/17/2073
2020 PO4630488174	LGE	4	40 BRO	SP	CRE	ED,ID	BD	6/18/2073
2020 PO4633288130	LGE	4	40 BRO	SP	CRE	ED,ID	BD	6/19/2073
2020 PO4633188121	LGE	4	40 BRO	SP	CRE	ED,ID	BD	6/20/2073
2020 PO4748812539	F	4	40 BRO	SP	CRE		V	6/21/2073
2020 PO4660310839	KU	4	40 BRO	SP	CRE	ED,EP,ID	TD	6/22/2073
2020 PO4657610896	KU	4	40 BRO	SP	CCA		V	6/23/2073
2020 PO4654110965	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/24/2073
2020 PO4785788787	LGE	4	40 BRN	SP	CRE	ED,ID	TD	6/25/2073
2020 PO4670810975	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/26/2073
2020 PO4641011251	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/27/2073
2020 PO4761088435	F	4	40 BRO	SP	CRE		V	6/28/2073
2020 PO4763088447	LGE	4	40 BRO	SP	CCA	ED,ID	BD	6/29/2073
2020 PO4761288434	LGE	4	40 BRO	SP	CRE	ED,ID,IP	BD	6/30/2073
2020 PO4761888430	LGE	3	45 BRO	SP	CCA		V	7/1/2073
2020 PO4762988417	LGE	3	45 BRO	SP	CCA		V	7/2/2073
2020 PO4760588406	LGE	3	45 BRO	SP	A		V	7/3/2073
2020 PO4759888399	LGE	4	30 BRO	SP	CCA	ED,ID	BD	7/4/2073
2020 PO6124265876A	F	3	40 OTH	SP	P		V	7/5/2073
2020 PO6133865829	F	4	40 OTH	SP	P	ED	V	7/6/2073
2020 PO6147765847	F	4	40 OTH	SP	P		V	7/7/2073
2020 PO6152865911	KU	4	40 OTH	SP	CRE	ID	TD	7/8/2073
2020 PO6146365903	KU	4	40 OTH	SP	CRE	ID	TD	7/9/2073
2020 PO6137865894	KU	4	40 OTH	SP	CRE	ID	TD	7/10/2073
2020 PO6124265876	KU	4	40 OTH	SP	CRE	ID	TD	7/11/2073
2020 PO6136765986	KU	4	40 OTH	SP	CRE	ID	TD	7/12/2073
2020 PO6143065814	KU	6	30 OTH	SP	CRE	ID	TD	7/13/2073
2020 PO4632988107	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	7/14/2073
2020 PO4633388143	LGE	4	40 BRO	SP	CRE	ED,ID	BD	7/15/2073
2020 PO4633488158	LGE	4	40 BRO	SP	CRE	ED,ID	BD	7/16/2073
2020 PO4633988206	LGE	4	40 BRO	SP	CRE	ED,ID	BD	7/17/2073
2020 PO2514340630	ODP	5	35 ACW	SP	CRE	ED,ID	TD	7/18/2073
2020 PO2514340630A	ODP	5	35 ACW	SP	CRE	ED,ID	TD	7/19/2073
2020 PO2537140817	ODP	5	35 ACW	SP	CRE	ED,ID	TD	7/20/2073
2020 PO2561640981	ODP	5	35 ACW	DF	CRE	ED,ID	TD	7/21/2073
2020 PO2586341147	ODP	5	35 ACW	DF	CRE	ED,ID	TD	7/22/2073
2020 PO4775888735	LGE	4	40 BRN	SP	A	ED,ID	TD	7/23/2073
2020 PO1928229356	ODP	4	45 XXX	SP	CCA	ED	T	7/24/2073

2020 PO1915529436	ODP	6	30 XXX	SP	CCA	ED	T		7/25/2073
2020 PO1978728869	ODP	4	40 XXX	SP	CRE	ID	TD		7/26/2073
2020 PO4778788744	LGE	4	40 BRN	SP	CRE	ED,ID	TD		7/27/2073
2020 PO3782651861	KU	4	40 OTH	SP	CRE	ID	BD		7/28/2073
2020 PO3782951717	KU	5	40 OTH	SP	CRE	ID	BD		7/29/2073
2020 PO3788951837	KU	5	45 OTH	SP	CRE	ED,ID,SRS	TD		7/30/2073
2020 PO3792451874	KU	5	35 OTH	SP	CRE	ED,ID,IP,SRS	TD		7/31/2073
2020 PO4759788390	LGE	3	45 BRO	SP	CCA		V		8/1/2073
2020 PO4758788373	LGE	3	45 BRO	SP	CCA	ED,ID	BD		8/2/2073
2020 PO4757788354	LGE	3	45 BRO	SP	CCA	ED,ID	BD		8/3/2073
2020 PO4756688335	LGE	3	45 BRO	SP	P	ED,ID	TD		8/4/2073
2020 PO4755388311	LGE	3	45 BRO	SP	CCA	ED,ID,IP	BD		8/5/2073
2020 PO4779588747	LGE	4	40 BRN	SP	CRE	ED,HH,ID,IP,RB	VX	PX	8/6/2073
2020 PO6110866145	F	4	40 OTH	SP	CRE	ED	V		8/7/2073
2020 PO6111466052	F	4	40 OTH	SP	P	ED	V		8/8/2073
2020 PO6120566064	F	4	40 OTH	SP	CRE	ED	V		8/9/2073
2020 PO6135466080	F	5	35 OTH	SP	P		V		8/10/2073
2020 PO6105566134	KU	4	50 OTH	SP	CRE	ED,ID,SRS	TD		8/11/2073
2020 PO6102066360	KU	3	45 OTH	SP	CCA		V		8/12/2073
2020 PO6080666006	KU	4	40 OTH	SP	CRE	ID	BD		8/13/2073
2020 PO6106465931	KU	4	45 OTH	SP	CCA		V		8/14/2073
2020 PO6122166160	KU	6	30 OTH	SP	CCA		V		8/15/2073
2020 PO6107465991	KU	4	40 OTH	SP	CRE	ID	TD		8/16/2073
2020 PO4777188776	LGE	4	35 BRN	SP	A	ED,ID	TD		8/17/2073
2020 PO4634188232	LGE	4	40 BRO	SP	A	ED,ID	BD		8/18/2073
2020 PO4634288245	LGE	4	40 BRO	SP	A	ED,ID	TD		8/19/2073
2020 PO4778788761	LGE	4	40 BRN	SP	A	ED,ID	TD		8/20/2073
2020 PO3748551636	KU	3	45E OTH	SP	CRE	ED,ID,SRS	TD		8/21/2073
2020 PO3756851694	F	5	35E OTH	SP	P		V		8/22/2073
2020 PO3758551614	KU	4	45 OTH	SP	CCA		V		8/23/2073
2020 PO4777088796	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD		8/24/2073
2020 PO4631988197	LGE	4	40 BRO	SP	CRE	ED,ID	TD		8/25/2073
2020 PO4646711116	KU	4	40 BRO	SP	CRE	ID,IP	BD		8/26/2073
2020 PO6061466285	KU	5	40 OTH	SP	CRE	ID	TD		8/27/2073
2020 PO6063366200	KU	6	25 OTH	SP	CRE	ED,EP,ID,IP	X	RP3	8/28/2073
2020 PO6049866265	KU	5	40 OTH	SP	CRE	ID	TD		8/29/2073
2020 PO6039966249	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD		8/30/2073
2020 PO5998966143	KU	3	45 OTH	SP	CCA		V		8/31/2073
2020 PO4633688173	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		9/1/2073
2020 PO4633788181	LGE	4	40 BRO	SP	A	ED,ID	BD		9/2/2073
2020 PO4754088288	LGE	2	45 BRO	SP	P	ED,ID	TD		9/3/2073
2020 PO4752788264	LGE	2	45 BRO	SP	P	ED,ID	TD		9/4/2073
2020 PO4659295946	LGE	3	50 BRO	SP	CCA		V		9/5/2073
2020 PO0212536785	ODP	3	45 XXX	SP	A	ID	BD		9/6/2073
2020 PO0227136620	ODP	3	45 XXX	SP	A	ID	BD		9/7/2073
2020 PO0181837332	ODP	2	50 XXX	SP	CCA		V		9/8/2073
2020 PO0197436978	ODP	4	40 XXX	SP	CCA		V		9/9/2073

2020 PO0358438766	ODP	1	70 XXX	SP	CCA		V			9/10/2073
2020 PO0350938644	ODP	1	65 XXX	SP	CCA		V			9/11/2073
2020 PO0338938474	ODP	2	50 XXX	SP	CCA		V			9/12/2073
2020 PO0330638320	ODP	1	70 XXX	SP	CCA		V			9/13/2073
2020 PO0516045246	ODP	5	35 XXX	SP	CRE	ED,ID	TD			9/14/2073
2020 PO0500845485	ODP	5	35 BRN	SP	CCA		V			9/15/2073
2020 PO0530845469	ODP	5	35 BRN	SP	CCA		V			9/16/2073
2020 PO0520445329	ODP	5	35 XXX	SP	CRE	ED,ID	TD			9/17/2073
2020 PO0507145155	ODP	5	35 XXX	SP	CRE	ED,ID	TD			9/18/2073
2020 PO2607941305	ODP	5	35 ACW	DF	CRE	ED,ID	TD			9/19/2073
2020 PO2624841427	ODP	4	40 ACW	SP	CRE	ED,ID	TD			9/20/2073
2020 PO2633041636	ODP	4	40 ACW	SP	CRE	ID	BD			9/21/2073
2020 PO2208341086	ODP	4	45 ACW	SP	A	ID	BD			9/22/2073
2020 PO2295240923	ODP	4	45 ACW	SP	S		V			9/23/2073
2020 PO3738551590	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD			9/24/2073
2020 PO3737351298	KU	5	30 OTH	SP	CRE		V			9/25/2073
2020 PO3743851380	KU	3	40E OTH	SP	CRE	ID	BD			9/26/2073
2020 PO2913640932	F	5	35 ACW	SP	CCA		V			9/27/2073
2020 PO2902540728	ODP	6	30 KOP	SP	CRE	ED,ID	TD			9/28/2073
2020 PO2892240860	ODP	5	35 KOP	SP	CRE	ED,ID	TD			9/29/2073
2020 PO2923140548	ODP	5	35 KOP	DF	CRE	ED,ID	TD			9/30/2073
2020 PO2937440637	ODP	3	45 KOP	SP	S		V			10/1/2073
2020 PO2960740732	ODP	4	40 KOP	SP	S		V			10/2/2073
2020 PO2958540359	ODP	4	45 KOP	SP	S		V			10/3/2073
2020 PO2718747762	ODP	5	35 KOP	SP	CRE	ED,ID	TD			10/4/2073
2020 PO1683730277	ODP	6	35 XXX	SP	CRE	HH,ID,RB	X	PX		10/5/2073
2020 PO4776388807	LGE	4	40 BRN	SP	CRE	ED,ID	TD			10/6/2073
2020 PO4775788820	LGE	4	40 BRN	SP	CRE	ED,ID	TD			10/7/2073
2020 PO3753251541	F	5	35E OTH	SP	CRE		V			10/8/2073
2020 PO3748551636A	KU	5	35 BRN	SP	CCA		V			10/9/2073
2020 PO3738551590A	F	5	35E OTH	SP	P		V			10/10/2073
2020 PO3739651518	F	5	35 OTH	SP	CRE		V			10/11/2073
2020 PO4653513313	F	4	40 BRO	SP	CCA		V			10/12/2073
2020 PO4676513455-A	KU	3	35 BRO	SP	A	ID,IP	BD			10/13/2073
2020 PO4683513547	F	4	40 BRO	SP	CRE		V			10/14/2073
2020 PO4676513455	F	4	40 BRO	SP	CRE		V			10/15/2073
2020 PO6083666526	F	5	40 OTH	SP	CRE	ED	V			10/16/2073
2020 PO6070266513	F	6	30 OTH	SP	CCA		V			10/17/2073
2020 PO6061766491	F	6	30 OTH	SP	CCA		V			10/18/2073
2020 PO6068566451	KU	4	40 OTH	SP	CCA		V			10/19/2073
2020 PO6037866435	KU	4	40 OTH	SP	CRE	ID	TD			10/20/2073
2020 PO6050466425	KU	4	40 OTH	SP	CRE	ID	TD			10/21/2073
2020 PO6078966468	KU	4	40 OTH	SP	CRE	ID	TD			10/22/2073
2020 PO6059366437	KU	4	40 OTH	SP	CRE	ED,EP,ID	TX	RR		10/23/2073
2020 PO6022566425	KU	5	30 OTH	SP	CRE	ID	TD			10/24/2073
2020 PO4615687912	F	4	40 BRO	SP	CCA		V			10/25/2073
2020 PO6151663909	KU	6	30 OTH	SP	CCA		V			10/26/2073

2020 PO6157263883	KU	4	40 OTH	SP	CRE	ED	TD	10/27/2073
2020 PO6116265351	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	10/28/2073
2020 PO3686753922	KU	2	45 OTH	SP	P	ID	BD	10/29/2073
2020 PO3672254121	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	10/30/2073
2020 PO3682154109	KU	2	45 OTH	SP	CRE	ED,ID,SRS	TD	10/31/2073
2020 PO4568115367	KU	4	40 ACE	SP	CRE		V	11/1/2073
2020 PO3688954324	KU	2	45 OTH	SP	P	ED,ID,SRS	TD	11/2/2073
2020 PO4779588910	LGE	4	40 BRN	SP	CRE	ED,ID,IP	BD	11/3/2073
2020 PO4584115283	F	4	40 ACE	SP	CRE		V	11/4/2073
2020 PO3697554445	F	2	45 OTH	SP	P		V	11/5/2073
2020 PO3713354572	KU	2	45 OTH	SP	P	ED,ID,SRS	TD	11/6/2073
2020 PO3713354572A	KU	2	45 OTH	SP	P	ED,ID,SRS	TD	11/7/2073
2020 PO4781088903	LGE	4	35 BRN	SP	CRE	ED,HH,ID	VX PX	11/8/2073
2020 PO4536715215	F	4	40 ACE	SP	CRE		V	11/9/2073
2020 PO4537715197	F	4	40 ACE	SP	CRE		V	11/10/2073
2020 PO4782588909	LGE	4	30 BRN	SP	CRE	ED,ID	TD	11/11/2073
2020 PO4533615276	KU	3	45 ACE	SP	A		V	11/12/2073
2020 PO4527415388	KU	3	45 ACE	SP	A	ED,ID,IP	TD	11/13/2073
2020 PO3716356062	KU	4	40 OTH	SP	CCA		V	11/14/2073
2020 PO375256076	KU	4	45 OTH	SP	CCA		V	11/15/2073
2020 PO3779556085	KU	2	50 OTH	SP	CCA		V	11/16/2073
2020 PO3794855921	KU	4	40 OTH	SP	CCA		V	11/17/2073
2020 PO3804455752	KU	4	40E OTH	SP	P	ED,ID,SRS	TD	11/18/2073
2020 PO4783988915	LGE	4	30 BRN	SP	CRE	ED,ID	TD	11/19/2073
2020 PO3801955587	KU	4	40 OTH	SP	P	ED,ID,SRS	TD	11/20/2073
2020 PO3800855544	KU	1	115E OTH	AL	S		V	11/21/2073
2020 PO3782155094	KU	4	40 OTH	SP	P	ID	BD	11/22/2073
2020 PO3796855370	KU	4	40 OTH	SP	P	ED,ID,SRS	TD	11/23/2073
2020 PO3790655209	KU	4	40E OTH	SP	P	ED,EP,ID,SRC	TD	11/24/2073
2020 PO3765054880	F	2	45E OTH	SP	P		B	11/25/2073
2020 PO3717654892	F	2	45 OTH	SP	P		V	11/26/2073
2020 PO3756554878	KU	2	50 OTH	SP	CCA		V	11/27/2073
2020 PO4522315491	F	4	40 ACE	SP	A		V	11/28/2073
2020 PO4515615598	F	4	40 ACE	SP	CRE		V	11/29/2073
2020 PO4785388922	LGE	4	30 BRN	SP	CRE	ED,ID	TD	11/30/2073
2020 PO4515615598-A	KU	3	45 ACE	SP	CRE		V	12/1/2073
2020 PO4750988549	F	4	40 BRO	SP	CCA		V	12/2/2073
2020 PO4754688570	F	4	40 BRO	SP	CCA		V	12/3/2073
2020 PO4753888580	F	4	40 BRO	SP	CCA		V	12/4/2073
2020 PO4753188578	F	4	40 BRO	SP	CCA		V	12/5/2073
2020 PO4754288565	F	4	30 BRO	SP	CCA		V	12/6/2073
2020 PO4760688525	F	3	30 BRO	SP	CCA		V	12/7/2073
2020 PO4759788532	F	4	40 BRO	SP	CCA		V	12/8/2073
2020 PO4758788538	F	3	45 BRO	SP	CCA		V	12/9/2073
2020 PO4757788545	F	4	40 BRO	SP	CCA		V	12/10/2073
2020 PO4756788552	F	4	40 BRO	SP	CCA		V	12/11/2073
2020 PO4756188556	F	4	40 BRO	SP	CCA		V	12/12/2073

2020 PO4755388561	F	4	40 BRO	SP	CCA		V	12/13/2073
2020 PO4760088515	F	3	35 BRO	SP	CCA		V	12/14/2073
2020 PO4759388503	F	4	40 BRO	SP	CCA		V	12/15/2073
2020 PO4762888490	F	4	40 BRO	SP	CCA		V	12/16/2073
2020 PO4763088494	F	4	40 BRO	SP	CCA		V	12/17/2073
2020 PO4750488542	F	4	40 BRO	SP	CCA		V	12/18/2073
2020 PO4751788542	F	4	40 BRO	SP	CCA		V	12/19/2073
2020 PO4752288538	F	4	40 BRO	SP	CCA		V	12/20/2073
2020 PO4752888534	F	4	40 BRO	SP	CCA		V	12/21/2073
2020 PO4753788528	F	4	40 BRO	SP	CCA		V	12/22/2073
2020 PO4754888521	F	4	40 BRO	SP	CCA		V	12/23/2073
2020 PO4755788515	F	4	40 BRO	SP	CCA		V	12/24/2073
2020 PO4756788508	F	4	40 BRO	SP	CCA		V	12/25/2073
2020 PO4757788501	F	4	40 BRO	SP	CCA		V	12/26/2073
2020 PO4504815769	F	4	40 ACE	SP	CRE		V	12/27/2073
2020 PO4785188926	LGE	4	40 BRN	SP	A	ED,ID	TD	12/28/2073
2020 PO4497715873	F	4	40 ACE	SP	CRE		V	12/29/2073
2020 PO3712853827	KU	4	40 OTH	SP	CRE	ID	BD	12/30/2073
2020 PO3724253368	KU	2	45 OTH	SP	P	ED,ID,SRS	TD	12/31/2073
2020 PO3724153241	KU	2	45 OTH	SP	P	ID	BD	1/1/2074
2020 PO3724253133	KU	2	45 OTH	SP	CRE	ED,ID,SRS	TD	1/2/2074
2020 PO3692553012	KU	4	40 OTH	SP	CCA		V	1/3/2074
2020 PO3699353044	KU	4	40 OTH	SP	CCA		V	1/4/2074
2020 PO3699453424	KU	2	50 OTH	SP	CCA		V	1/5/2074
2020 PO1605041054	KU	6	30 OTH	SP	CCA		V	1/6/2074
2020 PO3749552151	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD	1/7/2074
2020 PO3757052171	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD	1/8/2074
2020 PO6152363721	F	4	40 OTH	SP	CRE		V	1/9/2074
2020 PO6138063914	KU	5	35 OTH	SP	CRE	ID	TD	1/10/2074
2020 PO6150263803	KU	6	30 OTH	SP	CCA		V	1/11/2074
2020 PO6136463586	KU	4	40 OTH	SP	CCA		V	1/12/2074
2020 PO4701513836	F	4	40 ACE	SP	CRE		V	1/13/2074
2020 PO4710813750	F	4	40 ACE	SP	CRE		V	1/14/2074
2020 PO6149964376	KU	4	40 OTH	SP	CCA		V	1/15/2074
2020 PO6115263217	KU	4	40 OTH	SP	CRE	ID	TD	1/16/2074
2020 PO6124563492	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	1/17/2074
2020 PO4909811656	KU	4	40 ACE	SP	CRE		V	1/18/2074
2020 PO3774352096	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	1/19/2074
2020 PO4890711598	KU	5	35 ACE	SP	CRE	ED	TD	1/20/2074
2020 PO4882511474	KU	5	35 ACE	SP	CRE	ED	TD	1/21/2074
2020 PO6159163784	KU	4	40 OTH	SP	CRE	ID	BD	1/22/2074
2020 PO6167263871	KU	6	30 OTH	SP	CRE	ID	TD	1/23/2074
2020 PO4220230521	KU	2	50 BRO	SP	CCA		V	1/24/2074
2020 PO4226930691	KU	2	50 BRO	SP	CCA		V	1/25/2074
2020 PO4234130876	KU	2	50 BRO	SP	CCA		V	1/26/2074
2020 PO4239331009	KU	2	50 BRO	SP	CCA		V	1/27/2074
2020 PO6400003883	F	6	30 XXX	SP	CRE		V	1/28/2074

2020 PO6391803817	F	4	40 BRN	SP	CRE		V	1/29/2074
2020 PO6381603670	KU	3	45 BRN	SP	CCA		V	1/30/2074
2020 PO7056994691	KU	4	40 BRN	SP	CRE	ED,ID	TD	1/31/2074
2020 PO4245031153	KU	2	50 BRO	SP	CCA		V	2/1/2074
2020 PO4250131284	KU	2	50 BRO	SP	CCA		V	2/2/2074
2020 PO4255031410	KU	2	50 BRO	SP	CCA		V	2/3/2074
2020 PO4260331545	KU	2	50 BRO	SP	CCA		V	2/4/2074
2020 PO4266131692	KU	2	50 BRO	SP	CCA		V	2/5/2074
2020 PO4271831838	KU	2	50 BRO	SP	CCA		V	2/6/2074
2020 PO3010038858	KU	4	40 BRN	SP	CCA		V	2/7/2074
2020 PO2982739085	KU	4	45 BRN	SP	CCA		V	2/8/2074
2020 PO2954539316	KU	4	45 BRN	SP	CCA		V	2/9/2074
2020 PO7012420798	KU	5	35 XXX	SP	CRE	ID	TD	2/10/2074
2020 PO7003420709	KU	5	35 XXX	SP	CRE	ID	BD	2/11/2074
2020 PO6992420687	F	4	40 XXX	SP	CRE		V	2/12/2074
2020 PO6988920741	KU	4	40 XXX	SP	CRE	ID	BD	2/13/2074
2020 PO6951120267	KU	4	40 XXX	SP	CCA		V	2/14/2074
2020 PO6974620717	KU	6	30 XXX	SP	CRE	ID	TD	2/15/2074
2020 PO6979520767	KU	6	30 XXX	SP	CCA		V	2/16/2074
2020 PO6968220679	KU	5	35 XXX	SP	CCA		V	2/17/2074
2020 PO6971120651	KU	5	35 XXX	SP	CCA		V	2/18/2074
2020 PO6973720581	KU	4	45 XXX	SP	CRE	ID	TD	2/19/2074
2020 PO6970920453	KU	5	35 XXX	SP	CRE	ID	TD	2/20/2074
2020 PO6963620442	F	4	40 XXX	SP	CRE		V	2/21/2074
2020 PO6964020404	KU	4	40 XXX	SP	CRE	ID	TD	2/22/2074
2020 PO6936920252	KU	4	40 XXX	SP	CCA		V	2/23/2074
2020 PO6918220152	F	6	30 XXX	SP	CRE		V	2/24/2074
2020 PO6902220114	KU	6	30 XXX	SP	CRE	ID	TD	2/25/2074
2020 PO6906520151	KU	3	50 XXX	SP	CRE	ID	TD	2/26/2074
2020 PO6843919796	F	5	35 XXX	SP	A		V	2/27/2074
2020 PO6838619836	KU	5	35 XXX	SP	CRE	ID	TD	2/28/2074
2020 PO6821919451	KU	4	40 XXX	SP	CCA		V	3/1/2074
2020 PO6833719538	KU	6	30 XXX	SP	CRE	ID	TD	3/2/2074
2020 PO6826319652	KU	4	40 XXX	SP	CRE	ID	TD	3/3/2074
2020 PO6997894375	KU	5	35 BRN	SP	CRE	ED,ID	TD	3/4/2074
2020 PO7184590661	F	4	40 BRO	SP	CRE		V	3/5/2074
2020 PO7195790789	F	3	45 BRO	SP	CRE		V	3/6/2074
2020 PO7200890854	F	3	50 BRO	SP	CRE		V	3/7/2074
2020 PO7205490892	F	3	50 BRO	SP	CRE		V	3/8/2074
2020 PO7208990955	F	4	40 BRO	SP	CRE	RB	VX	3/9/2074
2020 PO7210191189	KU	4	40 BRO	SP	CRE	ID	BD	3/10/2074
2020 PO7213691013	F	3	45 BRO	SP	CRE		V	3/11/2074
2020 PO4853431890	KU	2	50 BRO	SP	CRE	ID,IP	TD	3/12/2074
2020 PO4855231933	KU	2	50 BRO	SP	CRE		B	3/13/2074
2020 PO3191137959	KU	4	40 BRN	SP	CRE	ID	BD	3/14/2074
2020 PO3171137951	KU	4	40 BRN	SP	CRE	EP,HH,ID,IP,RB	BX	3/15/2074
2020 PO3176938096	KU	5	35 BRN	SP	CRE		V	3/16/2074

Business Use

2020 PO2114245554	F	4	40 BRN	SP	CRE		V	3/17/2074
2020 PO7007694348	KU	6	30 BRN	SP	CRE	ED,ID	TD	3/18/2074
2020 PO7009994234	KU	5	35 BRN	SP	CRE	ED,ID	TD	3/19/2074
2020 PO4859632063	KU	3	50 BRO	SP	CRE	ID	BD	3/20/2074
2020 PO4860432087	KU	3	45 BRO	SP	CCA		V	3/21/2074
2020 PO6997894268	KU	6	30 BRN	SP	CRE	ED,ID	TD	3/22/2074
2020 PO6978894022	KU	4	40 BRN	SP	CRE	ED,ID	TD	3/23/2074
2020 PO7339589507	F	5	35 BRO	SP	P		V	3/24/2074
2020 PO7344589455	LGE	4	45 BRO	SP	P	ID	BD	3/25/2074
2020 PO7290289339	KU	5	35 BRO	SP	CRE	ED,ID	TD	3/26/2074
2020 PO7274489193	KU	5	35 BRO	SP	CCA		V	3/27/2074
2020 PO6992993909	KU	4	40 BRN	SP	CRE	ED,ID	BD	3/28/2074
2020 PO6974893878	KU	4	40 BRN	SP	CRE	ED,ID	BD	3/29/2074
2020 PO7284089959	F	4	35 BRO	SP	CCA		V	3/30/2074
2020 PO7288289764	KU	5	35 BRO	SP	CRE	ED,ID	BD	3/31/2074
2020 PO6984193800	KU	4	40 BRN	SP	CRE	ED,ID	BD	4/1/2074
2020 PO7287589934	F	3	40 BRO	SP	CRE		V	4/2/2074
2020 PO7268989873	KU	4	40 BRO	SP	CRE	ED,ID	BD	4/3/2074
2020 PO7279689822	F	4	40 BRO	SP	CCA		V	4/4/2074
2020 PO7220991103	F	4	45 BRO	SP	CRE		V	4/5/2074
2020 PO1940011492	KU	4	40 UNK	SP	CRE	ED,ID	TD	4/6/2074
2020 PO1978511541	KU	4	40 UNK	SP	CRE	ED,ID	TD	4/7/2074
2020 PO2011611566	KU	4	40 UNK	SP	CRE	ED,ID	TD	4/8/2074
2020 PO2029011685	KU	4	50 UNK	SP	CRE	ED,ID	TD	4/9/2074
2020 PO2039811749	KU	4	40 UNK	SP	CRE	ED,ID	TD	4/10/2074
2020 PO2044811723	KU	4	40 UNK	SP	CRE	ED,ID	TD	4/11/2074
2020 PO2053411787	KU	4	45 UNK	SP	P	ED,ID	TD	4/12/2074
2020 PO2070811833	KU	4	40 UNK	SP	CRE	ED,ID	TD	4/13/2074
2020 PO2088511809	KU	4	40 UNK	SP	CRE	ED,ID	TD	4/14/2074
2020 PO2088611972	KU	4	40 UNK	SP	CRE	ED,ID	TD	4/15/2074
2020 PO2105312051	KU	5	35 UNK	SP	CRE	ED,ID	TD	4/16/2074
2020 PO0511977685	KU	4	40 BRN	SP	CCA		V	4/17/2074
2020 PO0597477736	KU	4	45 BRN	SP	CRE	ID	BD	4/18/2074
2020 PO0565077879-A	KU	4	40 BRN	SP	CCA		V	4/19/2074
2020 PO0565077879	KU	4	45 BRN	SP	CRE	ID,IP	BD	4/20/2074
2020 PO0606677955	KU	4	40 BRN	SP	CCA		V	4/21/2074
2020 PO0616378200	KU	4	45 BRN	SP	CRE	ID,IP	BD	4/22/2074
2020 PO1111178144	KU	3	50 BRN	SP	CRE	ED,ID,IP	TD	4/23/2074
2020 PO1083177906	KU	4	40 BRN	SP	CRE	ED	TD	4/24/2074
2020 PO1052177625	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	4/25/2074
2020 PO1283676661	KU	4	45 BRN	SP	CRE	ED,ID,IP	TD	4/26/2074
2020 PO1253176935	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	4/27/2074
2020 PO1301475717	KU	4	40 BRN	SP	CRE	ID,IP	BD	4/28/2074
2020 PO2262145043	KU	6	30 BRN	SP	CRE		V	4/29/2074
2020 PO2270244982	KU	2	45 BRN	SP	P	ED	T	4/30/2074
2020 PO6868202336	KU	4	40 BRO	SP	CRE		V	5/1/2074
2020 PO6974101960	KU	4	40 BRO	SP	CRE		V	5/2/2074

2020 PO6777202634	KU	4	40 BRO	SP	CRE		V	5/3/2074
2020 PO6810902538	KU	4	40 BRO	SP	CRE		V	5/4/2074
2020 PO6991501984	KU	5	35 BRO	SP	CRE		V	5/5/2074
2020 PO6921202144	KU	4	40 BRO	SP	CRE		V	5/6/2074
2020 PO7016802032	KU	5	35 BRO	SP	CRE		V	5/7/2074
2020 PO7048602073	KU	5	35 BRO	SP	CRE		V	5/8/2074
2020 PO6839502421	KU	4	40 BRO	SP	CRE		V	5/9/2074
2020 PO6895302233	KU	5	35 BRO	SP	CRE		V	5/10/2074
2020 PO6946102057	KU	5	35 BRO	SP	CRE		V	5/11/2074
2020 PO6956801269	F	6	25 BRO	SP	CRE		V	5/12/2074
2020 PO6955301358	F	4	40 BRO	SP	CRE		V	5/13/2074
2020 PO5781610568	KU	4	30 BRO	SP	CRE	ID	BD	5/14/2074
2020 PO4704909509	KU	6	30 ACE	SP	CRE	ED,ID	BD	5/15/2074
2020 PO5786310481	KU	6	30 BRO	SP	CRE		V	5/16/2074
2020 PO5773210302	KU	4	30 BRO	SP	CRE	ID	TD	5/17/2074
2020 PO5771410392	KU	6	30 BRO	SP	CCA		V	5/18/2074
2020 PO5774710516	KU	4	40 BRO	SP	CRE	ID	TD	5/19/2074
2020 PO5769110627	KU	4	40 BRO	SP	CRE	ID	TD	5/20/2074
2020 PO5754410477	KU	6	30 BRO	SP	CRE	ID	TD	5/21/2074
2020 PO5753410606	KU	4	40 BRO	SP	CRE	ID	BD	5/22/2074
2020 PO2144848598	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	5/23/2074
2020 PO7023701322	F	4	40 BRO	SP	CRE		V	5/24/2074
2020 PO7002601344	F	4	40 BRO	SP	CRE		V	5/25/2074
2020 PO6974601353	F	4	40 BRO	SP	CRE		V	5/26/2074
2020 PO7056001429	F	4	35 SWP	SP	CRE		V	5/27/2074
2020 PO6989601335	F	4	40 BRO	SP	CRE		V	5/28/2074
2020 PO7013001357	F	4	40 BRO	SP	CRE		V	5/29/2074
2020 PO7040701375	F	4	35 SWP	SP	CRE		V	5/30/2074
2020 PO7009296225	KU	4	40 BRN	SP	CRE	ED,ID	BD	5/31/2074
2020 PO1141328123	ODP	4	45 BRN	SP	CRE	ID	TD	6/1/2074
2020 PO3960482688	F	3	45 BRN	SP	CRE		V	6/2/2074
2020 PO3960582676	F	3	45 BRN	SP	CRE		V	6/3/2074
2020 PO3960882677	F	4	35 BRN	SP	CRE		V	6/4/2074
2020 PO3962182693	LGE	4	35 BRN	SP	A	HH,ID	BD	6/5/2074
2020 PO3962382678	LGE	4	35 BRN	SP	A	ED,ID	TD	6/6/2074
2020 PO3967583161	LGE	2	45 BRO	SP	CRE	ED,ID	TD	6/7/2074
2020 PO3968183170	LGE	3	50 BRO	SP	CCA		V	6/8/2074
2020 PO3968883179	LGE	3	45 BRO	SP	CRE	ED,HH,ID	BX	PX 6/9/2074
2020 PO0768138000	ODP	5	35 XXX	SP	CRE	ED,ID,IP	TD	6/10/2074
2020 PO0751837695	ODP	2	50 BRN	SP	CCA		V	6/11/2074
2020 PO0775937697	ODP	4	45 BRN	SP	CCA		V	6/12/2074
2020 PO1107328010	ODP	3	45 BRN	SP	CCA		V	6/13/2074
2020 PO1113027593	ODP	4	45 BRN	SP	CCA		V	6/14/2074
2020 PO1089927949	ODP	3	45 BRN	SP	CCA		V	6/15/2074
2020 PO1126827599	ODP	3	45 BRN	SP	CCA		V	6/16/2074
2020 PO1087528235	ODP	4	40 BRN	SP	CCA	ED	T	6/17/2074
2020 PO6468203423	KU	4	45 XXX	SP	CRE	ED,ID	TD	6/18/2074

2020 PO0631934898	ODP	4	40 XXX	SP	CRE	ED,ID,IP,SRC	TD	6/19/2074
2020 PO6495603397	KU	4	40 XXX	SP	CRE	ED,ID	TD	6/20/2074
2020 PO2150348549	KU	4	40 ACE	SP	CRE	ED,ID	TD	6/21/2074
2020 PO7207689990	F	5	35 BRO	SP	CRE		V	6/22/2074
2020 PO6473303277	KU	6	30 XXX	SP	CRE	ED,ID	TD	6/23/2074
2020 PO6462603423	KU	4	40 BRN	SP	CRE	ED,ID	TD	6/24/2074
2020 PO7006896029	KU	4	40 BRN	SP	CRE	ED,ID	TD	6/25/2074
2020 PO6997895730	KU	6	30 BRN	SP	CRE	ED,ID	BD	6/26/2074
2020 PO7005195720	KU	4	40 BRN	SP	CRE	ED,ID	TD	6/27/2074
2020 PO7022995682	KU	4	40 BRN	SP	CRE	ED,ID	TD	6/28/2074
2020 PO7044295609	KU	4	40 BRN	SP	CRE	ED,ID	TD	6/29/2074
2020 PO7004595828	KU	4	40 BRN	SP	CRE	ED,ID	TD	6/30/2074
2020 PO7017895791	KU	3	35 BRN	SP	CRE	ED,ID	BD	7/1/2074
2020 PO2168948472	KU	4	40 ACE	SP	CRE	ED,HH,ID,IP,RB	BX	7/2/2074
2020 PO2137548412	KU	5	35 ACE	SP	CRE	ED,ID	TD	7/3/2074
2020 PO2130248226	KU	4	40 ACE	SP	CRE	ED,ID	TD	7/4/2074
2020 PO4811328957	KU	3	45 BRO	SP	CCA		V	7/5/2074
2020 PO6863219109	KU	5	35 XXX	SP	CRE	ID	TD	7/6/2074
2020 PO4803728980	C	4	40 BRO	SP	CRE		V	7/7/2074
2020 PO4785828954	KU	3	45 BRO	SP	CCA		V	7/8/2074
2020 PO4757527972	F	5	35 BRO	SP	A		V	7/9/2074
2020 PO4771028101	F	3	40 BRO	SP	A		V	7/10/2074
2020 PO4771427820	KU	4	40 BRO	SP	CRE	ID	BD	7/11/2074
2020 PO4754327795	KU	5	40 BRO	SP	CRE	ED,ID,IP	TD	7/12/2074
2020 PO4738427809	KU	4	40 BRO	SP	CRE	ID,IP	BD	7/13/2074
2020 PO4705727847	KU	4	40 BRO	SP	A	ED,ID	TD	7/14/2074
2020 PO4700727672	KU	3	50 BRO	SP	CCA		V	7/15/2074
2020 PO4727327345	KU	4	45 BRO	SP	CRE	ID	BD	7/16/2074
2020 PO4712427529	KU	3	45 BRO	SP	A	ID	TD	7/17/2074
2020 PO4712427529-A	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	7/18/2074
2020 PO5716346283	F	6	30 ACE	SP	CCA		V	7/19/2074
2020 PO5669046441	KU	5	35 ACE	SP	CRE	ED,ID	BD	7/20/2074
2020 PO5731846405	F	5	35 ACE	SP	CRE		V	7/21/2074
2020 PO9297994589	KU	6	30 ACW	SP	S		V	7/22/2074
2020 PO6858718907A	KU	5	35 XXX	SP	CCA		V	7/23/2074
2020 PO6866718990	KU	6	30 XXX	SP	CCA		V	7/24/2074
2020 PO6858718907	KU	4	40 XXX	SP	CRE	ID	TD	7/25/2074
2020 PO6846818810	KU	6	30 XXX	SP	CRE	ID	TD	7/26/2074
2020 PO6867318583	KU	4	40 XXX	SP	CRE	ID	BD	7/27/2074
2020 PO6871118651	KU	4	40 XXX	SP	CRE		V	7/28/2074
2020 PO6877918621	KU	5	35 XXX	SP	CRE	ID	TD	7/29/2074
2020 PO2829841698	KU	4	40 BRN	SP	CRE	ID	BD	7/30/2074
2020 PO2827041840	KU	4	40 BRN	SP	CRE	ID	BD	7/31/2074
2020 PO3207142237	KU	4	40 ACE	SP	CRE	ED,ID	TD	8/1/2074
2020 PO4146435104	KU	4	40 BRO	SP	CRE	ED,ID	TD	8/2/2074
2020 PO7338589371	KU	4	40 BRO	SP	P	ED,ID	TD	8/3/2074
2020 PO7345189430	LGE	4	40 BRO	SP	S		V	8/4/2074

2020 PO6653802571	KU	4	35 BRO	SP	CRE		ED,HH,ID,RB	BX	RP2	8/5/2074
2020 PO7300788955	F	4	35 BRO	SP	S			V		8/6/2074
2020 PO6447804140	KU	5	35 OTH	SP	CRE			V		8/7/2074
2020 PO9310994581A	KU	6	35 ACW	SP	CRE		ED,ID	TD		8/8/2074
2020 PO2174950964	KU	3	45 BRO	SP	CCA			V		8/9/2074
2020 PO6464604074	KU	4	40 OTH	SP	CRE			V		8/10/2074
2020 PO6472504058	KU	4	40 OTH	SP	CRE			V		8/11/2074
2020 PO6491304032	KU	4	35 OTH	SP	CRE			V		8/12/2074
2020 PO6508103989	KU	3	50 OTH	SP	CRE			V		8/13/2074
2020 PO6533103931	KU	4	40 OTH	SP	CRE			V		8/14/2074
2020 PO6557703881	KU	5	35 OTH	SP	CRE			V		8/15/2074
2020 PO6584303745	KU	4	40 OTH	SP	CRE			V		8/16/2074
2020 PO6605103640	KU	4	40 OTH	SP	CRE			V		8/17/2074
2020 PO6625203530	KU	4	40 OTH	SP	CRE			V		8/18/2074
2020 PO6645403423	KU	5	35 OTH	SP	CRE			V		8/19/2074
2020 PO6666303338	KU	4	35 OTH	SP	CRE			V		8/20/2074
2020 PO6665303318	KU	4	40 OTH	SP	CRE			V		8/21/2074
2020 PO6468404600	KU	6	30 OTH	SP	CRE			V		8/22/2074
2020 PO6419204456	KU	6	30 OTH	SP	CCA			V		8/23/2074
2020 6279504410a	KU	6	30 XXX	SP	CRE		ED,ID	BD		8/24/2074
2020 PO5834210501	F	2	50 BRO	SP	A			V		8/25/2074
2020 PO5844610345	KU	2	50 BRO	SP	CCA			V		8/26/2074
2020 PO5847910638	KU	3	45 BRO	SP	CCA			V		8/27/2074
2020 PO5862010779	KU	3	45 BRO	SP	CCA			V		8/28/2074
2020 PO5881010995	KU	3	45 BRO	SP	CCA			V		8/29/2074
2020 PO5893911144	KU	3	45 BRO	SP	CCA			V		8/30/2074
2020 PO5913011368	KU	3	45 BRO	SP	CCA			V		8/31/2074
2020 PO5940511377	KU	5	35 BRO	SP	CCA			V		9/1/2074
2020 PO5935011305	KU	4	40 BRO	SP	CRE		ID	TD		9/2/2074
2020 PO5918111428	KU	3	45 BRO	SP	CCA			V		9/3/2074
2020 PO5922411486	KU	3	45 BRO	SP	CCA			V		9/4/2074
2020 PO5932811667	KU	3	45 BRO	SP	CCA			V		9/5/2074
2020 PO5950611878	KU	2	55 BRO	SP	CCA			V		9/6/2074
2020 PO5942811783	KU	3	45 BRO	SP	CCA			V		9/7/2074
2020 PO5973411905	F	3	45 BRO	SP	A			V		9/8/2074
2020 PO5989512005	F	3	45 BRO	SP	A			V		9/9/2074
2020 PO6006812251	KU	3	55 BRO	SP	A			V		9/10/2074
2020 PO6001912301	KU	5	35 BRO	SP	CRE		ID	TD		9/11/2074
2020 PO9310994581	KU	4	40 ACW	SP	CRE		ED,ID	TD		9/12/2074
2020 PO9305794417	KU	6	30 ACW	SP	CRE		ED,ID	TD		9/13/2074
2020 PO9294393691	KU	6	30 ACW	SP	S			V		9/14/2074
2020 PO5687247241	C	4	40 ACE	SP	CRE			V		9/15/2074
2020 PO9311193808	KU	3	50 ACW	SP	CRE		ED,ID	BD		9/16/2074
2020 PO9307393894	KU	3	45 ACW	SP	S			V		9/17/2074
2020 PO9307194122	C	4	40 ACW	SP	CRE			V		9/18/2074
2020 PO9380993763	KU	4	40 BRN	SP	CRE		ED,ID	TD		9/19/2074
2020 PO9384393791	KU	5	35 BRN	SP	CRE		ED,ID	TD		9/20/2074

2020 PO5627852755	KU	6	30 ACE	SP	CRE	ED,ID	TD	9/21/2074	
2020 PO5613952796	KU	4	40 ACE	SP	CRE	ED,ID	TD	9/22/2074	
2020 PO9309994080	KU	5	30 ACW	SP	CRE	ED,ID	TD	9/23/2074	
2020 PO9312194017	KU	6	30 ACW	SP	CRE	ED,ID	TD	9/24/2074	
2020 PO9288593969	KU	6	30 ACW	SP	CRE	ED,ID	TD	9/25/2074	
2020 PO9302094014	KU	4	40 ACW	SP	CRE	ED,ID	TD	9/26/2074	
2020 PO9409493659	KU	5	35 BRN	SP	CRE	ED,ID	TD	9/27/2074	
2020 PO9384393687	KU	4	45 BRN	SP	CRE	ID	BD	9/28/2074	
2020 PO5989412232	KU	4	40 BRO	SP	CRE	ID	TD	9/29/2074	
2020 PO5980712175	KU	5	35 BRO	SP	CRE	ID	TD	9/30/2074	
2020 PO5958711970	KU	5	35 BRO	SP	CRE	ID	TD	10/1/2074	
2020 PO5902111436	KU	5	35 BRO	SP	CRE	ID	TD	10/2/2074	
2020 PO5891711497	KU	5	35 BRO	SP	CRE	ID	TD	10/3/2074	
2020 PO3855582159	LGE	4	30 BRO	SP	CCA		V	10/4/2074	
2020 PO5752432960	LGE	3	45 BRO	SP	CCA		VX	PX	10/5/2074
2020 PO5741232793	LGE	3	45 BRO	SP	CCA		V	10/6/2074	
2020 PO3854082113	LGE	4	30 BRO	SP	CCA	ID	BD	10/7/2074	
2020 PO3854782104	LGE	2	65 BRO	SP	CCA		V	10/8/2074	
2020 PO7438292989	KU	4	40 BRO	SP	CRE	ID	BD	10/9/2074	
2020 PO5726932583	LGE	3	45 BRO	SP	CCA		V	10/10/2074	
2020 PO3854282093	LGE	2	85 BRO	SP	CRE		V	10/11/2074	
2020 PO3854082089	LGE	4	30 BRO	SP	CCA		V	10/12/2074	
2020 PO4014082531	LGE	4	35 BRN	SP	A	ED,ID	BD	10/13/2074	
2020 PO4021082370	F	3	45 BRN	SP	S		V	10/14/2074	
2020 PO4021482363	F	4	30 BRN	SP	CCA		V	10/15/2074	
2020 PO4016982401	F	4	30 BRN	SP	CCA		V	10/16/2074	
2020 PO4017182403	F	1	55 BRN	SP	CCA		V	10/17/2074	
2020 PO4016682419	F	3	45 BRN	SP	A		V	10/18/2074	
2020 PO4015882448	F	4	40 BRN	SP	CRE		V	10/19/2074	
2020 PO4014782490	F	4	40 BRN	SP	S		V	10/20/2074	
2020 PO4014182508	F	4	40 BRN	SP	CCA		V	10/21/2074	
2020 PO2389235762	F	4	40 UNK	SP	CRE		V	10/22/2074	
2020 PO2372935666	F	4	40 UNK	SP	CRE		V	10/23/2074	
2020 PO2379435707	F	4	40 BRN	SP	CRE		V	10/24/2074	
2020 PO2363035795	ODP	6	30 BRN	SP	CCA		V	10/25/2074	
2020 PO2352435548	F	4	40 UNK	SP	CRE		V	10/26/2074	
2020 PO2347435781	F	4	40 UNK	SP	CRE		V	10/27/2074	
2020 PO7434692990	KU	4	40 BRO	SP	CRE	ID	BD	10/28/2074	
2020 PO7427093054	KU	4	40 BRO	SP	CCA		V	10/29/2074	
2020 PO7420593112	KU	4	40 BRO	SP	CRE	ED,ID	TD	10/30/2074	
2020 PO7374292809	KU	4	40 BRO	SP	CRE	ID	BD	10/31/2074	
2020 PO7388192751	KU	4	45 BRO	SP	CRE	ID	BD	11/1/2074	
2020 PO7090894524	KU	4	40 BRN	SP	S		V	11/2/2074	
2020 PO7087994538	KU	4	40 BRN	SP	CRE	ED,ID	TD	11/3/2074	
2020 PO7059494456	KU	4	40 BRN	SP	CRE	ED,ID	TD	11/4/2074	
2020 PO7052894350	KU	4	40 BRN	SP	CRE	ED,ID	TD	11/5/2074	
2020 PO7231090000	F	4	45 BRO	SP	CCA		V	11/6/2074	

2020 PO7013290165	KU	4	40 BRN	SP	CRE	ED,ID	BD	11/7/2074
2020 PO0365331711	ODP	5	35 XXX	SP	CRE	ED,ID	TD	11/8/2074
2020 PO1881165891	KU	4	40 BRO	SP	CRE	ID,IP	TD	11/9/2074
2020 PO0799274562	KU	6	30 BRN	SP	CRE	RB	X	11/10/2074
2020 PO0807474496	KU	4	40 BRN	SP	CRE	ID	BD	11/11/2074
2020 PO1857865815	KU	4	45 BRO	SP	CRE	ID,IP	TD	11/12/2074
2020 PO0849274935	KU	4	40 BRN	SP	CRE	ID,IP	BD	11/13/2074
2020 PO1828865784	KU	4	45 BRO	DF	CRE	ED,ID,IP	TD	11/14/2074
2020 PO1802665757	KU	2	60 BRO	DF	CRE	ED,ID	TD	11/15/2074
2020 PO0929376916	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	11/16/2074
2020 PO0937577199	KU	4	40 BRN	SP	CRE	ED	TD	11/17/2074
2020 PO0863276809	KU	6	35 BRN	SP	CRE	ED,ID,IP	TD	11/18/2074
2020 PO0850076405	KU	4	40 BRN	SP	CRE	ID,IP	BD	11/19/2074
2020 PO0858475966	KU	4	40 BRN	SP	CCA		V	11/20/2074
2020 PO0918876629	KU	5	35 BRN	SP	CRE	ID,IP	BD	11/21/2074
2020 PO0461858267	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	11/22/2074
2020 PO0469158437	KU	4	40 ACW	SP	CRE	ED,ID	TD	11/23/2074
2020 PO0475058579	KU	4	40 ACW	SP	CRE	ED,ID	TD	11/24/2074
2020 PO0486558855	KU	4	40 ACW	SP	CRE	ED,ID	TD	11/25/2074
2020 PO0501859053	KU	6	30 ACW	SP	CRE	ED,ID,IP	TD	11/26/2074
2020 PO0493359016	KU	4	40 ACW	SP	CRE	ED,ID	TD	11/27/2074
2020 PO1182362499	KU	4	40 BRN	SP	CRE	ID,IP	TD	11/28/2074
2020 PO1148962564	KU	4	40 BRN	SP	CRE	ID,IP	TD	11/29/2074
2020 PO0950677146	KU	4	40 BRN	SP	CCA		V	11/30/2074
2020 PO0950677146	KU	4	40 BRN	SP	CRE	ID	BD	12/1/2074
2020 PO0950677146-A	KU	4	40 BRN	SP	CCA		V	12/2/2074
2020 PO1143076571	KU	3	50 BRN	SP	CRE	ED	TD	12/3/2074
2020 PO1160476515	KU	3	50 BRN	SP	CRE	ED	TD	12/4/2074
2020 PO1123176544	KU	6	30 BRN	SP	CRE	ED	TD	12/5/2074
2020 PO1126676623	KU	3	50 BRN	SP	CRE	ED	TD	12/6/2074
2020 PO1107476696	KU	6	30 BRN	SP	CCA		V	12/7/2074
2020 PO1156575713	KU	3	50 BRN	SP	CRE	ID	BD	12/8/2074
2020 PO1343771125	F	4	40 BRN	SP	CCA		V	12/9/2074
2020 PO1191360287	KU	2	50 BRN	SP	CRE	ID	TD	12/10/2074
2020 PO0493958689	KU	6	30 ACW	SP	CRE	ED,ID,IP	TD	12/11/2074
2020 PO0574058544	KU	5	35 ACW	SP	CRE	ED,EP,ID,IP	TX	12/12/2074
2020 PO0560258346	KU	4	40 ACW	SP	CRE	ED,ID	TD	12/13/2074
2020 PO0522058543	KU	4	35 ACW	SP	CCA		V	12/14/2074
2020 PO9469155786	KU	3	45 BRN	SP	CRE	ED,ID,SRS	TD	12/15/2074
2020 PO9487755701	KU	3	45 BRN	SP	CCA		V	12/16/2074
2020 PO9450855859	KU	3	45 BRN	SP	CCA		V	12/17/2074
2020 PO9393456103	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD	12/18/2074
2020 PO9422255982	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD	12/19/2074
2020 PO9309655173	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD	12/20/2074
2020 PO1164561041	KU	2	50 BRN	SP	CRE	ID	TD	12/21/2074
2020 PO1137561522	KU	2	50 BRN	SP	CRE		V	12/22/2074
2020 PO1125961734	KU	3	50 BRN	SP	CRE	ID	TD	12/23/2074

2020 PO1111262020	KU	3	50 BRN	SP	CRE	ID	TD	12/24/2074
2020 PO1113262150	KU	2	50 BRN	SP	CRE	ID	TD	12/25/2074
2020 PO1116362304	KU	2	50 BRN	SP	CRE	ID	TD	12/26/2074
2020 PO1123562538	KU	3	45 BRN	SP	CRE	ID	BD	12/27/2074
2020 PO0585758714	KU	5	35 ACW	SP	CRE	ED,ID,IP	TD	12/28/2074
2020 PO0466559019	KU	4	40 ACW	SP	CCA		V	12/29/2074
2020 PO5826110344	F	3	45 BRO	SP	CCA		V	12/30/2074
2020 PO7376291129	KU	4	45 BRO	SP	CRE	ID	TD	12/31/2074
2020 PO7300890825	KU	5	35 BRO	SP	CRE	ED,ID	TD	1/1/2075
2020 PO7144891703	KU	4	40 BRN	SP	CCA		V	1/2/2075
2020 PO7040201766	KU	3	40 BRN	SP	CCA		V	1/3/2075
2020 PO7008601627	KU	3	40 BRN	SP	CCA		V	1/4/2075
2020 PO6966301645	KU	3	45 BRN	SP	CCA		V	1/5/2075
2020 PO7118402073	KU	3	40 BRN	SP	CCA		V	1/6/2075
2020 PO7106701994	KU	3	45 BRN	SP	CCA		V	1/7/2075
2020 PO6870101913	KU	3	40 BRN	SP	CCA		V	1/8/2075
2020 PO7140102197	KU	6	30 BRN	SP	CCA		V	1/9/2075
2020 PO7089002014	KU	3	40 BRN	SP	CCA		V	1/10/2075
2020 PO6858801950	KU	3	40 BRN	SP	CCA		V	1/11/2075
2020 PO7077101939	KU	3	40 BRN	SP	CCA		V	1/12/2075
2020 PO6904801817	KU	3	40 BRN	SP	CCA		V	1/13/2075
2020 PO7024801690	KU	3	40 BRN	SP	CCA		V	1/14/2075
2020 PO6922601784	KU	3	45 BRN	SP	CCA		V	1/15/2075
2020 PO6959301663	KU	3	45 BRN	SP	CCA		V	1/16/2075
2020 PO6988901596	KU	3	40 BRN	SP	CCA		V	1/17/2075
2020 PO6924201770	KU	3	45 BRN	SP	CCA		V	1/18/2075
2020 PO6886701872	KU	3	40 BRN	SP	CCA		V	1/19/2075
2020 PO5818110297	F	3	45 BRO	SP	A		V	1/20/2075
2020 PO5809010248	F	3	45 BRO	SP	A		V	1/21/2075
2020 PO5801510204	F	3	45 BRO	SP	CCA		V	1/22/2075
2020 PO5774410085a	KU	3	40 BRO	SP	A		V	1/23/2075
2020 PO5774410085	F	3	45 BRO	SP	A		V	1/24/2075
2020 PO5759210001	F	2	50 BRO	SP	A		V	1/25/2075
2020 PO5777409991	F	5	35 BRO	SP	CCA		V	1/26/2075
2020 PO5788010126	F	3	45 BRO	SP	A		V	1/27/2075
2020 PO5737310131	KU	6	30 BRO	SP	CRE		V	1/28/2075
2020 PO5738710230	KU	6	30 BRO	SP	CRE	ID	TD	1/29/2075
2020 PO5720110196	KU	6	30 BRO	SP	CRE	ED,RB	X	RP1 1/30/2075
2020 PO5718510278	KU	6	30 BRO	SP	CRE	ID	TD	1/31/2075
2020 PO5735810331	KU	4	40 BRO	SP	CRE	ID	TD	2/1/2075
2020 PO5725510373	KU	6	30 BRO	SP	CRE	ID	BD	2/2/2075
2020 PO5740610298	KU	3	45 BRO	SP	CCA		V	2/3/2075
2020 PO5746310376	F	4	40 BRO	SP	CRE		V	2/4/2075
2020 PO5739710557	KU	3	50 BRO	SP	CCA		V	2/5/2075
2020 PO5730710463	KU	3	45 BRO	SP	CCA		V	2/6/2075
2020 PO5712610387	KU	3	45 BRO	SP	CCA		V	2/7/2075
2020 PO6571113269	KU	5	20 XXX	SP	CRE	ID	BD	2/8/2075

2020 PO6582613318	KU	2	50 XXX	SP	CRE	ED,ID	TD		2/9/2075
2020 PO1056720105	ODP	4	40 UNK	SP	CRE	ED,ID,SRC	TX	RR	2/10/2075
2020 PO6600713404	KU	4	40 XXX	SP	CRE	ID	TD		2/11/2075
2020 PO6592713455	KU	6	30 XXX	SP	CRE	HH,RB	X	RP1	2/12/2075
2020 PO6572613596	KU	5	35 XXX	SP	CRE	ID	TD		2/13/2075
2020 PO6572613596A	KU	5	30 XXX	SP	CRE	ID	TD		2/14/2075
2020 PO6685213478	KU	5	35 XXX	SP	CCA		V		2/15/2075
2020 PO6682113598	KU	5	30 XXX	SP	CRE	ID	TD		2/16/2075
2020 PO7182391213-A	KU	6	30 BRN	SP	CRE	ED,HH,ID,RB	BX	RP2	2/17/2075
2020 PO7059096721	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		2/18/2075
2020 PO7066596943	KU	6	30 BRN	SP	CRE	ED,ID	TD		2/19/2075
2020 PO7060696935	KU	4	40 BRN	SP	CRE	ED,ID	TD		2/20/2075
2020 PO7059597124	KU	4	40 BRN	SP	CRE	ED,ID	TD		2/21/2075
2020 PO7066697062	KU	6	30 BRN	SP	A	ED,ID	TD		2/22/2075
2020 PO6167705275	KU	4	40 XXX	SP	CRE	ED,ID	TD		2/23/2075
2020 PO6160305238	KU	5	35 XXX	SP	CRE	ED,ID	TD		2/24/2075
2020 PO6165105109	KU	4	40 XXX	SP	CRE	ID	BD		2/25/2075
2020 PO0991220604	ODP	5	35 OTH	SP	CRE	ID	TD		2/26/2075
2020 PO0992320334	ODP	6	30 INP	SP	CRE	ID	TD		2/27/2075
2020 PO1056818697	ODP	6	30 UNK	SP	CRE	ID	TD		2/28/2075
2020 PO0979220623	ODP	5	35 OTH	SP	CRE	ED,ID,SRS	TD		3/1/2075
2020 PO1074619310	ODP	5	35 INP	SP	CRE	ED,ID,SRS	TD		3/2/2075
2020 PO1002120493	ODP	4	40 BRN	SP	CCA	ED,SRS	TD		3/3/2075
2020 PO4043582665	LGE	4	40 BRN	SP	CRE	ED,ID	TD		3/4/2075
2020 PO4042582656	LGE	4	40 BRN	SP	CRE	ED,ID	TD		3/5/2075
2020 PO4041682647	LGE	4	35 BRN	SP	CRE	ED,ID	TD		3/6/2075
2020 PO4040582635	LGE	4	40 BRN	SP	CRE	ED,ID	TD		3/7/2075
2020 PO4040182630	LGE	4	35 BRN	SP	CRE	ED,ID	TD		3/8/2075
2020 PO4041282617	LGE	4	30 BRN	SP	CRE	ED,ID	TD		3/9/2075
2020 PO4042882600	LGE	3	45 BRN	SP	S		V		3/10/2075
2020 PO4041682604	LGE	3	45 BRN	SP	S		V		3/11/2075
2020 PO4040682615	LGE	3	45 BRN	SP	S		V		3/12/2075
2020 PO4038982618	LGE	4	40 BRN	SP	CRE	ED,ID	TD		3/13/2075
2020 PO0583449230	KU	4	40 BRN	SP	CRE		B		3/14/2075
2020 PO0548448973	KU	4	40 BRN	SP	CRE		B		3/15/2075
2020 PO0570248930	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD		3/16/2075
2020 PO0633648560	KU	6	30 BRN	SP	CRE		V		3/17/2075
2020 PO0171550438	KU	4	40 BRN	SP	CRE	ID	BD		3/18/2075
2020 PO0635648594	KU	4	40 BRN	SP	CRE	ID	BD		3/19/2075
2020 PO0222550762	KU	4	40 BRN	SP	CRE	ED,ID,IP,SRC	TD		3/20/2075
2020 PO0569454997	KU	4	35 BRN	SP	CRE	ED,ID	BD		3/21/2075
2020 PO0445555429	KU	4	35 BRN	SP	CRE	ED,ID,IP	TD		3/22/2075
2020 PO0375855679	KU	4	40 BRN	SP	CCA		V		3/23/2075
2020 PO0411555554	KU	4	40 BRN	SP	CCA		V		3/24/2075
2020 PO0540855091	KU	4	35 BRN	SP	CCA	ED,ID	BD		3/25/2075
2020 PO0486554848	KU	4	40 BRN	SP	CRE	ED,ID	TD		3/26/2075
2020 PO0498255242	KU	4	40 BRN	SP	CCA		V		3/27/2075

2020 PO0473854435	KU	4	40 BRN	SP	CRE	ID,IP	TD	3/28/2075
2020 PO0465254150	KU	4	40 BRN	SP	CRE	ID,IP	TD	3/29/2075
2020 PO0908874503	KU	5	35 BRN	SP	CCA		V	3/30/2075
2020 PO0266350415	KU	4	40 BRN	SP	CRE	ID	BD	3/31/2075
2020 PO0708252804	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	4/1/2075
2020 PO0256650384	KU	4	40 BRN	SP	CCA		V	4/2/2075
2020 PO0908874503	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	4/3/2075
2020 PO0611651631	KU	2	70 BRN	ST	CRE		V	4/4/2075
2020 PO0655651842	KU	2	70 BRN	SP	CRE		V	4/5/2075
2020 PO0716752264	KU	4	40 BRN	SP	CRE	ED,ID	TD	4/6/2075
2020 PO0879874124	KU	4	40 BRN	SP	CRE	ID,IP	BD	4/7/2075
2020 PO0246950366	KU	4	40 BRN	SP	CRE	ID	BD	4/8/2075
2020 PO0207350428	KU	4	45 BRN	SP	CCA		V	4/9/2075
2020 PO0229150394	KU	4	40 BRN	SP	CRE	ED,ID,SRS	TD	4/10/2075
2020 PO0420450310	KU	4	40 BRN	SP	CCA		V	4/11/2075
2020 PO0977674669	KU	3	50 BRN	SP	CRE	ID,IP	BD	4/12/2075
2020 PO0961974446	KU	3	50 BRN	SP	CRE	ED	TD	4/13/2075
2020 PO0995974743	KU	3	50 BRN	SP	CRE	ED	TD	4/14/2075
2020 PO1022875048	KU	3	45 BRN	SP	CCA		V	4/15/2075
2020 PO1017575101	KU	3	45 BRN	SP	CCA		V	4/16/2075
2020 PO1015774798	KU	3	45 BRN	SP	CCA		V	4/17/2075
2020 PO1015774798-A	KU	5	35 BRN	SP	CCA		V	4/18/2075
2020 PO1016274733	KU	3	50 BRN	SP	CRE	ED	TD	4/19/2075
2020 PO0411450323	KU	4	40 BRN	SP	CRE	ID	BD	4/20/2075
2020 PO0363949697	KU	6	30 BRN	SP	CRE	ID	BD	4/21/2075
2020 PO0395450022	KU	4	40 BRN	SP	CRE	ID	BD	4/22/2075
2020 PO0369649813	KU	4	45 BRN	SP	CCA		V	4/23/2075
2020 PO0365449673	F	4	40 BRN	SP	CRE		V	4/24/2075
2020 PO9976950202	KU	4	40 BRN	SP	CCA		V	4/25/2075
2020 PO0438558028	KU	4	40 ACW	SP	CRE	ED,ID	BD	4/26/2075
2020 PO0433959023	KU	4	40 ACW	SP	CRE	ED,ID	TD	4/27/2075
2020 PO0632273524	KU	4	40 BRN	SP	CCA		V	4/28/2075
2020 PO0641073686	KU	4	45 BRN	SP	CCA		V	4/29/2075
2020 PO0614873831	KU	4	45 BRN	SP	CCA		V	4/30/2075
2020 PO7320892134	F	4	40 BRO	SP	CRE		V	5/1/2075
2020 PO7323892081	F	4	40 BRO	SP	CRE		V	5/2/2075
2020 PO7329892039	F	4	35 BRO	SP	CCA		V	5/3/2075
2020 PO7335091982	F	4	40 BRO	SP	CRE		V	5/4/2075
2020 PO7345091877	F	4	40 BRO	SP	CRE		V	5/5/2075
2020 PO7353591781	F	4	40 BRO	SP	CRE		V	5/6/2075
2020 PO6850818672	KU	4	40 XXX	SP	CRE	ID	TD	5/7/2075
2020 PO3950582210	LGE	6	25 BRN	SP	CRE	ED,ID,RB	TX	5/8/2075
2020 PO6847718573	KU	6	30 XXX	SP	CRE	ID	TD	5/9/2075
2020 PO6847718573A	KU	6	30 XXX	SP	CRE	ID	TD	5/10/2075
2020 PO6836718454	KU	4	35 XXX	SP	CRE	ID	TD	5/11/2075
2020 PO6862518435	KU	6	30 XXX	SP	CRE	ID	TD	5/12/2075
2020 PO6843118416	KU	4	40 XXX	SP	CRE	ID	TD	5/13/2075

2020 PO6851118300	F	6	30 XXX	SP	CRE		V	5/14/2075
2020 PO6845718353	KU	6	30 XXX	SP	CRE		V	5/15/2075
2020 PO6847918227A	KU	6	30 XXX	SP	CRE	ID	BD	5/16/2075
2020 PO6842718262	KU	4	40 XXX	SP	CRE	ID	TD	5/17/2075
2020 PO6847918227	KU	6	30 XXX	SP	CRE	ID	TD	5/18/2075
2020 PO6846118132	KU	5	35 XXX	SP	CRE	ID	TD	5/19/2075
2020 PO6831018003	KU	4	40 XXX	SP	CRE	ID	TD	5/20/2075
2020 PO6843117974	KU	6	30 XXX	SP	CRE	ID	TD	5/21/2075
2020 PO6859117970	KU	4	40 XXX	SP	CRE	ID	TD	5/22/2075
2020 PO6851917768	KU	4	40 XXX	SP	CRE	ID	TD	5/23/2075
2020 PO6853617656	KU	5	35 XXX	SP	CRE	ID	TD	5/24/2075
2020 PO3951582207	LGE	4	30 BRN	SP	A	ED,ID	TD	5/25/2075
2020 PO0403038924	F	3	45 XXX	SP	P		V	5/26/2075
2020 PO0406938869c	ODP	4	40 XXX	SP	CCA		V	5/27/2075
2020 PO0406938869b	ODP	4	40 XXX	SP	CCA		V	5/28/2075
2020 PO0406938869a	ODP	4	45 XXX	SP	CCA		V	5/29/2075
2020 PO0406938869	ODP	4	45 XXX	SP	CCA		V	5/30/2075
2020 PO0405738795	ODP	2	65 XXX	SP	CCA		V	5/31/2075
2020 PO0407138610	ODP	2	55 XXX	SP	CCA		V	6/1/2075
2020 PO0406138475	ODP	2	50 XXX	SP	CCA		V	6/2/2075
2020 PO0408438316	ODP	4	45 XXX	SP	CCA		V	6/3/2075
2020 PO1165729711	KU	2	55 XXX	SP	CRE	ID	BD	6/4/2075
2020 PO1290529520	KU	2	55 XXX	SP	CRE	ID	BD	6/5/2075
2020 PO1290529485	KU	2	55 XXX	SP	CRE	ID	BD	6/6/2075
2020 PO1165729757	KU	2	55 XXX	SP	CRE	ID	BD	6/7/2075
2020 PO1062829765	KU	2	55 XXX	SP	CRE	ID	BD	6/8/2075
2020 PO1061529740	KU	2	55 XXX	SP	CRE	ID	BD	6/9/2075
2020 PO6833517281	F	4	40 XXX	SP	A		V	6/10/2075
2020 PO6844817482	KU	5	40 XXX	SP	CRE	ID	TD	6/11/2075
2020 PO6842217281	KU	4	45 XXX	SP	CRE	ID	TD	6/12/2075
2020 PO6838116964	KU	5	35 XXX	SP	CRE	ID,IP	TX	RR 6/13/2075
2020 PO2454734350	KU	2	60 XXX	SP	CRE	ID	BD	6/14/2075
2020 PO2455634314	KU	2	60 XXX	SP	CRE	ID	BD	6/15/2075
2020 PO2507934509	KU	2	60 XXX	SP	CRE	ID	BD	6/16/2075
2020 PO3960782356	LGE	4	40 BRN	SP	CRE	ED,ID	TD	6/17/2075
2020 PO1110331284	ODP	6	30 XXX	SP	CRE	ID	TD	6/18/2075
2020 PO1126731338	ODP	5	35 XXX	SP	CRE	ID	TD	6/19/2075
2020 PO1132131192	ODP	6	30 XXX	SP	CCA		V	6/20/2075
2020 PO1146631297	ODP	5	35 XXX	SP	CRE	ID	TD	6/21/2075
2020 PO1163531184	ODP	5	35 XXX	SP	CRE	ID	TD	6/22/2075
2020 PO3961382369	LGE	4	40 BRN	SP	CRE	ED,ID	TD	6/23/2075
2020 PO3961882379	LGE	4	40 BRN	SP	CRE	ED,ID,RB	TX	RR 6/24/2075
2020 PO2510034472	KU	2	60 XXX	SP	CRE	ID	BD	6/25/2075
2020 PO2560434687	KU	2	60 XXX	SP	CRE	ID	BD	6/26/2075
2020 PO2561934640	KU	2	60 XXX	SP	CRE	ID	BD	6/27/2075
2020 PO2602834874	KU	2	60 XXX	SP	CRE	ID	BD	6/28/2075
2020 PO2605734821	KU	2	60 XXX	SP	CRE	ID	BD	6/29/2075

2020 PO2607934786	KU	2	60 XXX	SP	CRE	ID		BD	6/30/2075	
2020 PO3962582381	LGE	4	40 BRN	SP	S			V	7/1/2075	
2020 PO3963482376	LGE	4	40 BRN	SP	CRE		ED,ID	TD	7/2/2075	
2020 PO1174730882	ODP	4	40 XXX	SP	CRE		ID	TD	7/3/2075	
2020 PO1184330762	ODP	4	40 XXX	SP	CRE		ID	TD	7/4/2075	
2020 PO1194030649	ODP	4	40 XXX	SP	CRE		ID	BD	7/5/2075	
2020 PO1133330597	ODP	4	40 XXX	SP	A		ID	BD	7/6/2075	
2020 PO1141530358	ODP	4	40 XXX	SP	A		ID	TD	7/7/2075	
2020 PO1167230501	ODP	4	40 XXX	SP	A		ID	TD	7/8/2075	
2020 PO1246329664	ODP	4	40 XXX	SP	CRE		ID	BD	7/9/2075	
2020 PO3964682370	LGE	4	40 BRN	SP	CRE		ED,ID	TD	7/10/2075	
2020 PO2668035102	KU	2	60 XXX	SP	CRE		ID	BD	7/11/2075	
2020 PO2670935069	KU	2	60 XXX	SP	CRE		ID	BD	7/12/2075	
2020 PO2741435451	KU	2	60 XXX	SP	CRE		ID	BD	7/13/2075	
2020 PO2743235416	KU	2	60 XXX	SP	CRE		ID	BD	7/14/2075	
2020 PO2798235805	KU	2	60 XXX	SP	CRE		ID	BD	7/15/2075	
2020 PO2801635766	KU	2	60 XXX	SP	CRE		ID	BD	7/16/2075	
2020 PO2845936062B	KU	3	45 XXX	SP	CRE		ID	BD	7/17/2075	
2020 PO2848336025A	KU	3	55 XXX	SP	P		ED,HH,ID,IP,RB	X	PX	7/18/2075
2020 PO2845936062A	KU	3	55 XXX	SP	CRE		ID	BD	7/19/2075	
2020 PO2848336025	KU	3	45 XXX	SP	CRE		ID	BD	7/20/2075	
2020 PO2845936062	KU	3	45 XXX	SP	CRE		ID	BD	7/21/2075	
2020 PO2883636221	KU	3	45 XXX	SP	CRE		ID	BD	7/22/2075	
2020 PO2878632312A	KU	3	45 XXX	SP	CCA			V	7/23/2075	
2020 PO2878636312	KU	3	45 XXX	SP	CRE		ID	BD	7/24/2075	
2020 PO2881536254	KU	4	45 XXX	SP	CRE		ID	BD	7/25/2075	
2020 PO2911436137A	KU	4	45 XXX	SP	CCA			V	7/26/2075	
2020 PO2927436497	KU	2	60 XXX	SP	CRE		ID	BD	7/27/2075	
2020 PO2900636373	KU	3	45 XXX	SP	CRE		ID	BD	7/28/2075	
2020 PO2911436137	KU	2	55 XXX	SP	CRE		ID	BD	7/29/2075	
2020 PO2978736369	KU	2	60 XXX	SP	CRE		ID	BD	7/30/2075	
2020 PO2978736416	KU	2	60 XXX	SP	CRE		ID	BX	RP3	7/31/2075
2020 PO3965782364	LGE	4	40 BRN	SP	CRE		ED,ID	BD	8/1/2075	
2020 PO3967682349	LGE	4	40 BRN	SP	CRE		ED,ID	BD	8/2/2075	
2020 PO3966982358	LGE	4	40 BRN	SP	CRE		ED,ID	TD	8/3/2075	
2020 PO3632213561	KU	4	40 BRO	SP	CRE		ED,ID,IP	TD	8/4/2075	
2020 PO3967882353	LGE	4	30 BRN	SP	CRE		ED,ID	BD	8/5/2075	
2020 PO3958582341	LGE	4	40 BRN	SP	CRE		ED,ID	TD	8/6/2075	
2020 PO3958782345	LGE	4	30 BRN	SP	CRE		ED,ID	TD	8/7/2075	
2020 PO5195256455	KU	4	40 BRO	SP	CRE		ED,ID,IP	TD	8/8/2075	
2020 PO4549738492	KU	4	40 BRO	SP	CRE		ID,IP	BD	8/9/2075	
2020 PO4539438434	KU	1	60 BRO	SP	CCA			V	8/10/2075	
2020 PO4531938522	KU	1	60 BRO	SP	CCA			V	8/11/2075	
2020 PO4521638613	KU	1	60 BRO	SP	CCA			V	8/12/2075	
2020 PO4512238678	KU	1	60 BRO	SP	CCA			V	8/13/2075	
2020 PO4511638710	KU	1	60 BRO	SP	CCA			V	8/14/2075	
2020 PO4507438739	KU	1	60 BRO	SP	CCA			V	8/15/2075	

2020 PO4507438739	KU	1	60 BRO	SP	A		V		8/16/2075
2020 PO3956882355	LGE	4	40 BRN	SP	CRE	ED,ID	TD		8/17/2075
2020 PO3161836360	KU	4	40 XXX	SP	P	ED,ID	X	RP3	8/18/2075
2020 PO3199836374	KU	4	40 XXX	SP	CRE	ID	BD		8/19/2075
2020 PO3955282356	LGE	4	40 BRN	SP	CRE	ED,ID	BD		8/20/2075
2020 PO3122336300	KU	2	40 XXX	SP	CRE	ID	BD		8/21/2075
2020 PO3122336348	KU	2	40 XXX	WC	CRE	ID	BD		8/22/2075
2020 PO3199836366	KU	4	40 XXX	SP	CRE	ID	V		8/23/2075
2020 PO3242436389A	KU	5	40 XXX	SP	P	ID	BD		8/24/2075
2020 PO3242436389	KU	4	40 XXX	SP	P	ID	BD		8/25/2075
2020 PO3281836377	KU	4	40 XXX	SP	CCA		V		8/26/2075
2020 PO3191235715	KU	6	30 XXX	SP	CRE		V		8/27/2075
2020 PO3215035801	KU	4	40 XXX	SP	CCA		V		8/28/2075
2020 PO3952482374	LGE	4	40 BRN	SP	CRE	ED,ID	TD		8/29/2075
2020 PO3949982366	LGE	4	40 BRN	SP	A	ED,ID	BD		8/30/2075
2020 PO4501538838	KU	3	45 BRO	SP	CCA		V		8/31/2075
2020 PO1266720862	F	4	40 XXX	SP	CRE		V		9/1/2075
2020 PO1291820873	F	4	40 XXX	SP	CRE		V		9/2/2075
2020 PO1308620910	F	4	45 XXX	SP	CRE		V		9/3/2075
2020 PO1327020959	ODP	5	35 XXX	SP	CRE	ID	TD		9/4/2075
2020 PO1326130791	ODP	5	35 XXX	SP	CRE	ID	TD		9/5/2075
2020 PO1253530971	ODP	5	35 XXX	SP	CRE	ID	TD		9/6/2075
2020 PO1258930929	ODP	4	40 XXX	SP	CCA		V		9/7/2075
2020 PO1266130876	ODP	4	40 XXX	SP	CCA		V		9/8/2075
2020 PO1398231232A	ODP	6	30 XXX	SP	CRE	ID	TD		9/9/2075
2020 PO1317130288	ODP	6	30 XXX	SP	CRE	ID	TD		9/10/2075
2020 PO1292530442	ODP	5	35 XXX	SP	CRE	ID	BD		9/11/2075
2020 PO1347430077	ODP	6	30 XXX	SP	CRE	ID	TD		9/12/2075
2020 PO1332929977	ODP	4	40 XXX	SP	CRE	ID	TD		9/13/2075
2020 PO1255029747	ODP	4	45 XXX	SP	CCA		V		9/14/2075
2020 PO3885014345	KU	2	60 BRO	SP	CRE	ID,IP	BD		9/15/2075
2020 PO3840214579	KU	2	55 BRO	SP	CRE	ID,IP	BD		9/16/2075
2020 PO3862414463	KU	2	60 BRO	SP	CRE	ED,RB	X	RP1	9/17/2075
2020 PO1519120039	ODP	4	40 XXX	SP	CRE	ID	TD		9/18/2075
2020 PO1525220317	ODP	4	40 XXX	SP	CRE	ID	TD		9/19/2075
2020 PO1500621738	ODP	4	40 XXX	SP	CRE	ID	TD		9/20/2075
2020 PO1497821647	ODP	6	30 XXX	SP	CRE	ID	TD		9/21/2075
2020 PO3937782683	LGE	4	45 BRO	SP	CRE	ED,ID	TD		9/22/2075
2020 PO3938282692	LGE	4	45 BRO	SP	P	ED,ID	TD		9/23/2075
2020 PO3938782702	LGE	4	45 BRO	SP	CRE	ED,HH,ID	X	RR	9/24/2075
2020 PO2259035080	F	4	40 UNK	SP	CRE		V		9/25/2075
2020 PO2236034995	F	3	40 KOP	SP	CRE		V		9/26/2075
2020 PO2223335085	ODP	4	40 BRN	SP	CRE	ID	TD		9/27/2075
2020 PO3939582718	LGE	4	45 BRO	SP	P	ED,ID	TD		9/28/2075
2020 PO3940182730	LGE	3	50 BRO	SP	P	ED,ID	BD		9/29/2075
2020 PO3940582737	LGE	2	50 BRO	SP	P	ED,ID	TD		9/30/2075
2020 PO3941482755	LGE	3	50 BRO	SP	CCA		V		10/1/2075

2020 PO3941582757	LGE	3	50 BRO	SP	CCA		V	10/2/2075
2020 PO0690336222	ODP	6	30 XXX	SP	CRE	ED,ID	TD	10/3/2075
2020 PO0665236032	ODP	6	30 XXX	SP	CCA		V	10/4/2075
2020 PO0666935965	ODP	5	40 XXX	SP	CCA		V	10/5/2075
2020 PO0694435973	ODP	5	35 XXX	SP	CRE	ED,ID	TD	10/6/2075
2020 PO0697835726	ODP	4	40 XXX	SP	CRE	ED,ID	TD	10/7/2075
2020 PO0698335705	ODP	6	30 XXX	SP	CRE		V	10/8/2075
2020 PO3952282086	LGE	4	40 BRN	SP	A	ED,ID	TD	10/9/2075
2020 PO3952782080	LGE	4	35 BRN	SP	S		V	10/10/2075
2020 PO3819014690	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	10/11/2075
2020 PO3817214699	KU	2	40 BRO	SP	CRE	ED,ID,IP	TD	10/12/2075
2020 PO3834615005	KU	2	40 BRO	SP	CRE	ID,IP	BD	10/13/2075
2020 PO0700935483	ODP	4	35 XXX	SP	CRE	ED,ID	TD	10/14/2075
2020 PO0702635444	F	4	40 XXX	SP	A		V	10/15/2075
2020 PO0705835261	ODP	6	30 XXX	SP	CCA		V	10/16/2075
2020 PO0851035456	ODP	5	35 XXX	SP	CRE		V	10/17/2075
2020 PO3952982084	LGE	3	45 BRN	SP	S		V	10/18/2075
2020 PO3954682056	LGE	4	40 BRN	SP	P	ED,ID	TD	10/19/2075
2020 PO3952082105	LGE	3	45 BRN	SP	A	ED,ID	TD	10/20/2075
2020 PO3950282114	LGE	4	40 BRN	SP	A	ED,ID	TD	10/21/2075
2020 PO3763212809	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	10/22/2075
2020 PO4547708441	F	4	40 ACE	SP	CRE	ED,ID	V	10/23/2075
2020 PO3952382112	LGE	4	30 BRN	SP	S		V	10/24/2075
2020 PO4500508319	F	4	40 ACE	SP	P		V	10/25/2075
2020 PO3819212140	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	10/26/2075
2020 PO0776977421	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	10/27/2075
2020 PO0771777193	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	10/28/2075
2020 PO0790177481	KU	4	40 BRN	SP	CCA		V	10/29/2075
2020 PO0755977648	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	10/30/2075
2020 PO0796277842	KU	6	35 BRN	SP	CRE	HH,ID,RB	X	10/31/2075
2020 PO1434275087	KU	3	45 BRN	SP	CRE		V	11/1/2075
2020 PO1431875343	KU	4	40 BRN	SP	CRE	ID,IP	BD	11/2/2075
2020 PO1429275639	KU	4	45 BRN	SP	CRE	ID,IP	BD	11/3/2075
2020 PO1435075849	KU	4	40 BRN	SP	CRE	ID,IP	BD	11/4/2075
2020 PO1366475717	KU	4	40 BRN	SP	CRE	ID,IP	BD	11/5/2075
2020 PO1388075767	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	11/6/2075
2020 PO1383375572	F	4	40 BRN	SP	CRE		V	11/7/2075
2020 PO1363275999	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	11/8/2075
2020 PO1372875917	KU	4	40 BRN	SP	CRE	ID	BD	11/9/2075
2020 PO1347276130	KU	4	40 BRN	SP	A	ID,IP	BD	11/10/2075
2020 PO3986932642	KU	6	30 ACE	SP	CRE		V	11/11/2075
2020 PO4282644180	F	5	35 ACE	SP	P		V	11/12/2075
2020 PO4302644125	F	4	40 ACE	SP	CCA		V	11/13/2075
2020 PO3964934541	F	5	35 ACE	SP	CRE		V	11/14/2075
2020 PO4796136328	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	11/15/2075
2020 PO4796336120	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	11/16/2075
2020 PO4796735818	KU	4	45 ACE	SP	CRE	ED,ID	BD	11/17/2075

2020 PO4797335676	KU	4	40 ACE	SP	CRE	ED,ID	BD		11/18/2075
2020 PO4797435511	KU	4	40 ACE	SP	CRE	ED,ID	BD		11/19/2075
2020 PO4797835340	KU	4	45 ACE	SP	CRE	ED,ID	BD		11/20/2075
2020 PO4798535120	KU	4	45 ACE	SP	CRE	ED,ID	BD		11/21/2075
2020 PO4799034877	KU	4	45 ACE	SP	CRE	ED,ID	BD		11/22/2075
2020 PO4799734627	KU	4	45 ACE	SP	CRE	ED,ID	BD		11/23/2075
2020 PO4799634462	KU	3	45 ACE	SP	CCA	ED,ID	BD		11/24/2075
2020 PO4799934338	KU	3	45 ACE	SP	CRE	ED,ID	BD		11/25/2075
2020 PO4800034229	KU	4	45 ACE	SP	CRE	ED,ID	BD		11/26/2075
2020 PO4799734189	KU	3	45 ACE	SP	CCA	ID	BD		11/27/2075
2020 PO4028032472	F	4	40 ACE	SP	P	ED,ID	V		11/28/2075
2020 PO4011032459	F	4	40 ACE	SP	P	ED,ID	V		11/29/2075
2020 PO3990732525	F	4	40 ACE	SP	P		V		11/30/2075
2020 PO3993332693	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		12/1/2075
2020 PO3963933294	KU	4	40 ACE	SP	CCA		V		12/2/2075
2020 PO3981033107	KU	5	35 ACE	SP	CCA		V		12/3/2075
2020 PO3955233702	KU	4	45 ACE	SP	CCA	ED,ID	TD		12/4/2075
2020 PO3951933816	KU	4	45 ACE	SP	CCA	ED,ID	BD		12/5/2075
2020 PO4800101139	F	4	40 BRO	SP	CRE		V		12/6/2075
2020 PO4881801977	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD		12/7/2075
2020 PO4088183169	LGE	3	45 BRN	SP	S		V		12/8/2075
2020 PO5818655162	KU	4	40 ACE	SP	CRE	ED,ID	BD		12/9/2075
2020 PO9295388206	KU	5	35 BRN	SP	CRE	ED,ID	VX	RP2	12/10/2075
2020 PO9228888692	KU	6	30 BRN	SP	CRE	ED,ID	VX	RP2	12/11/2075
2020 PO5867750310	F	4	40 ACE	SP	CRE		V		12/12/2075
2020 PO9254888701	KU	5	35 BRN	SP	CRE	ED,ID,RB	BX	RP1	12/13/2075
2020 PO4649305502	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD		12/14/2075
2020 PO4670905694	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD		12/15/2075
2020 PO4685505842	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		12/16/2075
2020 PO5844550189	KU	4	40 ACE	SP	CRE	ED,ID	TD		12/17/2075
2020 PO5866050271	KU	4	40 ACE	SP	CRE	ED,ID	BD		12/18/2075
2020 PO9707192959	KU	3	45 BRN	SP	S		V		12/19/2075
2020 PO4692406002	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD		12/20/2075
2020 PO9855592594	F	5	35 ACW	SP	CRE		V		12/21/2075
2020 PO9839792846	KU	4	40 ACW	SP	S		V		12/22/2075
2020 PO9857692923	KU	5	30 ACW	SP	CRE	ED,ID,IP	TD		12/23/2075
2020 PO9846392747	KU	4	40 ACW	SP	CRE	ED,ID	TD		12/24/2075
2020 PO9852592769	KU	5	35 ACW	SP	CRE	ED,ID	TD		12/25/2075
2020 PO9862992801	KU	7	30 ACW	DF	CRE	ED,ID,IP,SRC	TX	RR	12/26/2075
2020 PO9386784273	F	4	40 BRN	SP	A		V		12/27/2075
2020 PO9343284265C	KU	3	45 BRN	SP	S		V		12/28/2075
2020 PO9343284265B	KU	3	45 BRN	SP	S		V		12/29/2075
2020 PO9343284265	KU	4	40 BRN	SP	S		V		12/30/2075
2020 PO9922491510	KU	4	40 ACW	SP	CRE	ED,ID	TD		12/31/2075
2020 PO9940191620	KU	4	40 ACW	SP	CRE	ED,ID	TD		1/1/2076
2020 PO9301584513	KU	4	40 BRN	SP	CRE	ED,ID	TD		1/2/2076
2020 PO9343284265	KU	3	45 BRN	SP	CCA		V		1/3/2076

2020 PO9905591740	KU	4	40 ACW	SP	CRE	ED,ID	TD	1/4/2076
2020 PO9914692082	KU	4	40 ACW	SP	CRE	ED,ID	TD	1/5/2076
2020 PO4672926220	KU	4	40 BRO	SP	CCA		V	1/6/2076
2020 PO2553622385	F	4	40 BRN	SP	CCA		V	1/7/2076
2020 Po2526422382	ODP	4	40 BRN	SP	CCA		V	1/8/2076
2020 PO2526422382	ODP	4	40 BRN	SP	CCA		V	1/9/2076
2020 PO2518121863	ODP	4	45 BRN	SP	CCA		V	1/10/2076
2020 PO2570926303	ODP	4	40 BRN	SP	CRE	ID	BD	1/11/2076
2020 PO3977482576	F	6	30 BRN	SP	CCA		V	1/12/2076
2020 PO3977082570	F	3	40 BRN	SP	A		V	1/13/2076
2020 PO3977682558	F	4	40 BRN	SP	S		V	1/14/2076
2020 PO3978382546	F	3	45 BRN	SP	S		V	1/15/2076
2020 PO3979182540	F	4	40 BRN	SP	S		V	1/16/2076
2020 PO4591530037	KU	2	45 ACE	SP	CRE	ED,ID	BD	1/17/2076
2020 PO3979682527	F	4	40 BRN	SP	S		V	1/18/2076
2020 PO3979982513	F	3	45 BRN	SP	CRE		V	1/19/2076
2020 PO2338742343	ODP	5	35 KOP	SP	CRE	ED,ID	TD	1/20/2076
2020 PO23447-42259A	ODP	5	35 KOP	SP	CCA	ED,ID,IP,MD,SRC	TD	1/21/2076
2020 PO4451738676	KU	4	45 BRO	SP	CCA		V	1/22/2076
2020 PO4455938746	KU	4	45 BRO	SP	CRE	ID,IP	BD	1/23/2076
2020 PO4466438900	KU	3	50 BRO	SP	CCA		V	1/24/2076
2020 PO0426935466	ODP	5	35 XXX	SP	CRE	ED,ID	TD	1/25/2076
2020 PO1822322993	ODP	4	40 XXX	SP	CRE	ID	TD	1/26/2076
2020 PO1821523078	ODP	6	30 XXX	SP	CRE	ID	TD	1/27/2076
2020 PO1810123137	ODP	4	40 XXX	SP	CRE	ID	TD	1/28/2076
2020 PO1819923226	ODP	5	35 XXX	SP	CRE	ID	BD	1/29/2076
2020 PO1788723239	ODP	6	30 XXX	SP	CRE	ID	TD	1/30/2076
2020 PO4586130153	KU	2	45 ACE	SP	CRE	ED,ID	BD	1/31/2076
2020 PO4576530304	KU	2	45 ACE	SP	CRE	ED,ID	BD	2/1/2076
2020 PO3979982505	F	3	45E BRN	SP	A		V	2/2/2076
2020 PO3980082482	F	4	40 BRN	SP	S		V	2/3/2076
2020 PO3980282469	F	4	40 BRN	SP	S		V	2/4/2076
2020 PO3979982459	LGE	4	30 BRN	SP	S		V	2/5/2076
2020 PO3980382459	F	3	45 BRN	SP	CRE		V	2/6/2076
2020 P00426935466a	ODP	5	30 XXX	SP	CCA		V	2/7/2076
2020 PO3981682466	LGE	4	40 BRN	SP	S		V	2/8/2076
2020 PO3980482445	F	4	40 BRN	SP	S		V	2/9/2076
2020 PO3980682428	F	3	45 BRN	SP	S		V	2/10/2076
2020 PO3980582413	F	3	45 BRN	SP	S		V	2/11/2076
2020 PO3980282398	F	3	45 BRN	SP	S		V	2/12/2076
2020 PO3979682389	F	4	40 BRN	SP	A		V	2/13/2076
2020 PO2586925822	ODP	4	40 BRN	SP	CRE	ID	BD	2/14/2076
2020 PO2602025161	ODP	4	40 BRN	SP	CRE	ID	BD	2/15/2076
2020 PO2598425489	ODP	4	40 BRN	SP	CRE	ID	BD	2/16/2076
2020 PO2605324494	F	4	40 BRN	SP	A		V	2/17/2076
2020 PO2608024706	F	4	40 BRN	SP	A		V	2/18/2076
2020 PO2621224418	F	4	40 BRN	SP	A		V	2/19/2076

2020 PO2628523998	F	4	40 BRN	SP	A		V		2/20/2076
2020 PO2638623740	F	4	40 BRN	SP	CRE		V		2/21/2076
2020 PO5460343039	KU	3	45 BRO	SP	CCA		V		2/22/2076
2020 PO5456342970	KU	3	45 BRO	SP	CCA		V		2/23/2076
2020 PO4062430700	KU	5	45 BRO	SP	CCA		V		2/24/2076
2020 PO5608145902	KU	3	50 ACE	SP	CRE	ED,ID,IP	BD		2/25/2076
2020 PO4096030769	KU	5	45 BRO	SP	CRE		V		2/26/2076
2020 PO5467442924	KU	6	30 BRO	SP	CCA		V		2/27/2076
2020 PO5468242985	KU	3	45 BRO	SP	CCA		V		2/28/2076
2020 PO5549442632	KU	3	45 BRO	SP	CCA		V		2/29/2076
2020 PO5490042718	KU	3	45 BRO	SP	CCA		V		3/1/2076
2020 PO5501942835	KU	4	45 BRO	SP	CCA		V		3/2/2076
2020 PO5490242850	KU	3	50 BRO	SP	CCA		V		3/3/2076
2020 PO3920230917	KU	4	40 BRO	SP	CRE	HH,ID	X	RP1	3/4/2076
2020 PO3947830832	KU	4	40 BRO	SP	CCA		V		3/5/2076
2020 PO3913130872	KU	6	30 BRO	SP	CRE	ID	TD		3/6/2076
2020 PO3921830838	KU	6	30 BRO	SP	CCA		V		3/7/2076
2020 PO5377241895	F	4	40 ACE	SP	CRE		V		3/8/2076
2020 PO5154338108	F	4	40 ACE	SP	CRE		V		3/9/2076
2020 PO5310444393	F	4	40 BRO	SP	CRE		V		3/10/2076
2020 PO5334344262	KU	3	45 BRO	SP	CCA		V		3/11/2076
2020 PO3840931143	KU	4	45 BRO	SP	CRE		V		3/12/2076
2020 PO3843331518	KU	3	45 BRO	SP	CCA		V		3/13/2076
2020 PO3894830752	KU	3	45 BRO	SP	CCA		V		3/14/2076
2020 PO5615746117	KU	4	45 ACE	SP	CRE	ED,ID	BD		3/15/2076
2020 PO5489837090	F	4	40 BRO	SP	CRE		V		3/16/2076
2020 PO5490837244	F	4	40 BRO	SP	CRE		V		3/17/2076
2020 PO5491737388	F	4	40 BRO	SP	CRE		V		3/18/2076
2020 PO5492337476	F	4	40 BRO	SP	A		V		3/19/2076
2020 PO5493237627	F	4	40 BRO	SP	CRE		V		3/20/2076
2020 PO5494437818	F	4	40 BRO	SP	CRE		V		3/21/2076
2020 PO5494937899	F	5	35 BRO	SP	A		V		3/22/2076
2020 PO5452437071	F	4	40 BRO	SP	CRE		V		3/23/2076
2020 PO5440737284	F	4	40 BRO	SP	CRE		V		3/24/2076
2020 PO5453837264	F	4	40 BRO	SP	CRE		V		3/25/2076
2020 PO5454837403	F	4	40 BRO	SP	CRE		V		3/26/2076
2020 PO5460837321	F	5	35 BRO	SP	A		V		3/27/2076
2020 PO5455637503	KU	1	70 BRO	SP	CRE	ED,ID,IP	TD		3/28/2076
2020 PO5832553401	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		3/29/2076
2020 PO5843753442	KU	4	40 ACE	SP	CRE	ED,ID	TD		3/30/2076
2020 PO5867553532	KU	4	40 ACE	SP	CRE	ED,ID	BD		3/31/2076
2020 PO3898731104	KU	2	50 BRO	SP	CCA		V		4/1/2076
2020 PO3874231114	F	4	45 BRO	SP	CRE		V		4/2/2076
2020 PO3872931403	KU	4	40 BRO	SP	CRE	ID,IP	TD		4/3/2076
2020 PO3867631372	F	4	40 BRO	SP	CRE		V		4/4/2076
2020 PO5275844070	F	6	35 BRO	SP	CRE	HH,ID	VX	PX	4/5/2076
2020 PO5290544200	F	6	30 BRO	SP	CRE		V		4/6/2076

2020 PO5287944302	F	4	40 BRO	SP	CRE		V	4/7/2076
2020 PO5269944145	F	4	40 BRO	SP	CRE		V	4/8/2076
2020 PO5156338513	F	4	40 ACE	SP	A		V	4/9/2076
2020 PO5156438422	F	4	40 ACE	SP	A		V	4/10/2076
2020 PO3934831882	KU	4	40 BRO	SP	CRE	ID,IP	TD	4/11/2076
2020 PO3947031714	KU	4	40 BRO	SP	CRE	ID	TD	4/12/2076
2020 PO5156138344	F	4	40 ACE	SP	CRE		V	4/13/2076
2020 PO5262843818	F	4	40 BRO	SP	CRE		V	4/14/2076
2020 PO5261143709-A	KU	3	45 BRO	SP	CCA		V	4/15/2076
2020 PO5261143709	F	4	40 BRO	SP	A		V	4/16/2076
2020 PO5275343774	KU	6	30 BRO	SP	CRE	ID	TD	4/17/2076
2020 PO5286243624	F	4	40 BRO	SP	CCA		V	4/18/2076
2020 PO5858953383	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	4/19/2076
2020 PO3923431299-A	KU	4	40 BRO	SP	CRE	ID	TD	4/20/2076
2020 PO3923431299	KU	4	40 BRO	SP	CRE	ID,IP,SRS	TD	4/21/2076
2020 PO5155538609	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	4/22/2076
2020 PO5298043826	F	4	40 BRO	SP	CRE		V	4/23/2076
2020 PO5310243894	F	4	40 BRO	SP	A		V	4/24/2076
2020 PO5310943736	F	4	40 BRO	SP	CCA		V	4/25/2076
2020 PO5313743828	F	2	40 BRO	SP	CCA		V	4/26/2076
2020 PO5305343561	F	4	40 BRO	SP	CCA		V	4/27/2076
2020 PO5327143493	F	4	40 BRO	SP	CRE		V	4/28/2076
2020 PO5347143455	F	4	40 BRO	SP	CRE		V	4/29/2076
2020 PO5346143424	F	4	40 BRO	SP	CRE		V	4/30/2076
2020 PO5346143671	F	4	40 BRO	SP	CRE		V	5/1/2076
2020 PO5345543885	F	4	40 BRO	SP	CRE		V	5/2/2076
2020 PO5453137939	F	4	40 BRO	SP	CRE		V	5/3/2076
2020 PO5442037443	F	4	40 BRO	SP	CRE		V	5/4/2076
2020 PO5443637635	F	4	40 BRO	SP	CRE		V	5/5/2076
2020 PO5445037803	F	4	40 BRO	SP	CRE		V	5/6/2076
2020 PO5891253287	KU	4	40 ACE	SP	CRE	ED,ID	TD	5/7/2076
2020 PO5908253201	KU	4	40 ACE	SP	CRE	ED,ID	TD	5/8/2076
2020 PO5457237749	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	5/9/2076
2020 PO5469637940	F	4	40 BRO	SP	CRE		V	5/10/2076
2020 PO5467637711	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	5/11/2076
2020 PO5511436859	F	4	40 BRO	SP	CRE		V	5/12/2076
2020 PO5894252890	KU	4	40 ACE	SP	CRE	ED,ID	TD	5/13/2076
2020 PO5877452994	KU	4	40 ACE	SP	CRE	ED,ID	BD	5/14/2076
2020 PO5860453091	KU	4	45 ACE	SP	CRE	ED,ID	TD	5/15/2076
2020 PO5531636844	F	4	40 BRO	SP	CRE		V	5/16/2076
2020 PO5546436832	F	4	40 BRO	SP	CRE		V	5/17/2076
2020 PO5569036830	F	4	40 BRO	SP	CRE		V	5/18/2076
2020 PO5291747623	KU	3	45 ACE	SP	CCA		V	5/19/2076
2020 PO4501104311	KU	3	45 BRO	SP	CRE	ID,IP	BD	5/20/2076
2020 PO3903007677	F	4	40 BRO	SP	CRE		V	5/21/2076
2020 PO4538004335	KU	5	35 BRO	SP	CCA		V	5/22/2076
2020 PO4516404360	KU	5	30 BRO	SP	CCA		V	5/23/2076

2020 PO3924007888	KU	3	45 BRO	SP	CCA		V	5/24/2076	
2020 PO9844092997	KU	6	30 ACW	SP	CRE	ED,ID	TD	5/25/2076	
2020 PO9827793032	KU	5	35 ACW	SP	CRE	ED,ID	V	5/26/2076	
2020 PO9833592936	KU	4	40 ACW	SP	CRE	ED,ID	TD	5/27/2076	
2020 PO9760593356	KU	3	55 ACW	SP	CCA		V	5/28/2076	
2020 PO9735093393	KU	3	50 ACW	SP	CCA		V	5/29/2076	
2020 PO9812393055	KU	3	50 ACW	SP	CCA		V	5/30/2076	
2020 PO9784293219	KU	3	50 ACW	SP	CCA		V	5/31/2076	
2020 PO9410093089	KU	5	35 ACW	SP	CRE	ED,ID,RB,Src	TX	RR	6/1/2076
2020 PO9799393154	KU	3	50 ACW	SP	CCA		V	6/2/2076	
2020 PO3931807682	KU	4	40 BRO	SP	CRE	ED,ID	TD	6/3/2076	
2020 PO5438946272a	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD	6/4/2076	
2020 PO9096526690	F	4	40 XXX	SP	A		V	6/5/2076	
2020 PO5438946272b	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD	6/6/2076	
2020 PO9078826732	F	4	40 XXX	SP	A		V	6/7/2076	
2020 PO4915810043	F	4	40 BRO	SP	CRE		V	6/8/2076	
2020 PO6847517810	F	5	35 BRN	SP	CRE		V	6/9/2076	
2020 PO4910109907	F	4	40 BRO	SP	CCA		V	6/10/2076	
2020 PO4934611323	KU	4	40 BRO	SP	CCA		V	6/11/2076	
2020 PO4923711371	KU	4	45 BRO	SP	CCA		V	6/12/2076	
2020 PO4911311423	KU	4	40 BRO	SP	CCA		V	6/13/2076	
2020 PO4697688332	LGE	4	40 BRN	SP	CCA		V	6/14/2076	
2020 PO4745787606	LGE	3	30 BRO	SP	CCA		V	6/15/2076	
2020 PO4746787606	LGE	4	40 BRO	SP	CCA		V	6/16/2076	
2020 PO5054308348	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/17/2076	
2020 PO5129208569	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD	6/18/2076	
2020 PO4746687617	LGE	4	35 BRO	SP	CCA		V	6/19/2076	
2020 PO4746887627	LGE	4	40 BRO	SP	CCA		V	6/20/2076	
2020 PO4745087623	LGE	3	45 BRO	SP	CCA		V	6/21/2076	
2020 PO4742387625	LGE	4	45 BRO	SP	CCA	ED,ID	BD	6/22/2076	
2020 PO4977408832	KU	6	30 BRO	SP	CRE		V	6/23/2076	
2020 PO4983908833	KU	6	30 BRO	SP	CCA		V	6/24/2076	
2020 PO5478746571	KU	3	45 ACE	SP	CRE	ED,ID	TD	6/25/2076	
2020 PO5438946272	KU	4	45 ACE	SP	CRE	ED,ID	TD	6/26/2076	
2020 PO5459446264	KU	4	45 ACE	SP	CCA		V	6/27/2076	
2020 PO3953607978	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/28/2076	
2020 PO3947507121	KU	4	40 BRO	SP	A	ID	BD	6/29/2076	
2020 PO5477246244	KU	3	45 ACE	SP	CCA		V	6/30/2076	
2020 PO5482146238	KU	4	45 ACE	SP	CCA		V	7/1/2076	
2020 PO3942107095	KU	4	40 BRO	SP	CCA	ED	T	7/2/2076	
2020 PO3949806938	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	7/3/2076	
2020 PO9592093453	KU	4	40 BRN	SP	CRE	ED,ID	TD	7/4/2076	
2020 PO5420346160	KU	3	50 ACE	SP	CRE	ED,ID,IP	BD	7/5/2076	
2020 PO9604593452	KU	3	45 BRN	SP	CCA		V	7/6/2076	
2020 PO5431346152	KU	4	45 ACE	SP	CRE	ED,ID	TD	7/7/2076	
2020 PO5003808755	KU	4	40 BRO	SP	CRE		V	7/8/2076	
2020 PO4697788321	LGE	4	35 BRN	SP	A	ED,ID	TD	7/9/2076	

2020 PO4698288314	LGE	4	35 BRN	SP	A	ED,ID	TD	7/10/2076
2020 PO4698288319	LGE	4	40 BRN	SP	A	ED,ID	TD	7/11/2076
2020 PO5090258755	KU	4	40 OTH	SP	CCA	ED,SRS	TD	7/12/2076
2020 PO5033058370	KU	4	45 OTH	SP	CRE	ID	TD	7/13/2076
2020 PO5068758699	KU	4	40 OTH	SP	CCA	ED,SRS	TD	7/14/2076
2020 PO5042858628	KU	4	40 OTH	SP	CCA	ED,SRS	TD	7/15/2076
2020 PO5049058152	KU	5	35 OTH	SP	CRE	ID	TD	7/16/2076
2020 PO5141458923	KU	4	45 OTH	SP	CCA	ED,SRS	TD	7/17/2076
2020 PO5113858850	KU	4	40 OTH	SP	CRE	ID	TD	7/18/2076
2020 PO5028457835	KU	3	50 OTH	SP	CRE	ID	TD	7/19/2076
2020 PO5053508550	KU	4	40 BRO	SP	CRE	ID,IP	BD	7/20/2076
2020 PO4944910058	KU	4	40 BRO	SP	CRE		V	7/21/2076
2020 PO4743587623	LGE	3	45 BRO	SP	CCA		V	7/22/2076
2020 PO4741987623	LGE	4	35 BRO	SP	CRE		BD	7/23/2076
2020 PO4742987643	LGE	4	45 BRO	SP	A	ED,ID,IP	BD	7/24/2076
2020 PO9638593802	KU	2	45 BRN	SP	CRE		V	7/25/2076
2020 PO4743487655	LGE	4	40 BRO	SP	CCA	ED,ID	BD	7/26/2076
2020 PO4834909475	KU	6	30 BRO	SP	CRE	ED	TD	7/27/2076
2020 PO4698788311	LGE	4	40 BRN	SP	S		V	7/28/2076
2020 PO4699588309	LGE	4	40 BRN	SP	S		V	7/29/2076
2020 PO4699188315	LGE	4	40 BRN	SP	A	ED,ID,IP	BD	7/30/2076
2020 PO4698188325	LGE	3	45 BRN	SP	S		V	7/31/2076
2020 PO4702188281	LGE	4	40 BRN	SP	CCA		V	8/1/2076
2020 PO4822010408	KU	3	45 BRO	SP	CRE		V	8/2/2076
2020 PO4819810352	KU	4	40 BRO	SP	CRE		V	8/3/2076
2020 PO4811810150	KU	3	45 BRO	SP	CCA		V	8/4/2076
2020 PO4814310213	KU	3	45 BRO	SP	CCA		V	8/5/2076
2020 PO5246657133	KU	4	40 OTH	SP	CCA	ED,SRS	TD	8/6/2076
2020 PO5169557410	KU	4	40 OTH	SP	CCA		V	8/7/2076
2020 PO5261157031	KU	4	40 OTH	SP	CRE	ID	TD	8/8/2076
2020 PO5231857240	KU	6	35 OTH	SP	CRE	ID	TD	8/9/2076
2020 PO5188858899	KU	3	50 OTH	SP	CRE	ED,ID,SRS	TD	8/10/2076
2020 PO5194458444	KU	4	40 OTH	SP	CRE	ID	TD	8/11/2076
2020 PO5192458861	KU	4	35 OTH	SP	CRE	ID	TD	8/12/2076
2020 PO5458846123	KU	4	45 ACE	SP	CRE	ED,ID,IP	TD	8/13/2076
2020 PO5443646129	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	8/14/2076
2020 PO5452946895	KU	1	60E ACE	SP	CRE		V	8/15/2076
2020 PO5451246908	KU	1	60E ACE	SP	CRE		V	8/16/2076
2020 PO5356246300	KU	6	30 ACE	SP	CCA		V	8/17/2076
2020 PO9603994494	KU	5	35 BRN	SP	CRE	ED,ID	TD	8/18/2076
2020 PO9616894554	KU	6	30 BRN	SP	CRE	ED,ID	TD	8/19/2076
2020 PO3934407252	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/20/2076
2020 PO3910907619	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/21/2076
2020 PO9545994335	KU	5	35 BRN	SP	S		V	8/22/2076
2020 PO3904107508	KU	4	40 BRO	SP	CRE	ID,IP	BD	8/23/2076
2020 PO3910907619-A	KU	5	35 BRO	SP	CRE	ED,ID	TD	8/24/2076
2020 PO9525393497	KU	3	45 BRN	SP	S		V	8/25/2076

2020 PO3890507104	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	8/26/2076
2020 PO3906007265	KU	4	45 BRO	SP	CCA		V	8/27/2076
2020 PO5200456984	KU	4	40 OTH	SP	CRE		V	8/28/2076
2020 PO5218057496	KU	4	40 OTH	SP	CCA		V	8/29/2076
2020 PO5265257434	KU	4	45 OTH	SP	CCA		V	8/30/2076
2020 PO5224557383	KU	4	40 OTH	SP	CRE	ID	BD	8/31/2076
2020 PO5204757724	KU	4	45 OTH	SP	CRE	ID	TD	9/1/2076
2020 PO519858115	KU	3	45 OTH	SP	CCA		V	9/2/2076
2020 PO5198858089	KU	3	50 OTH	SP	CCA	ED,SRS	TD	9/3/2076
2020 PO5181059173	KU	4	45 OTH	SP	CRE	ID	TD	9/4/2076
2020 PO4806610019	KU	4	40 BRO	SP	CCA		V	9/5/2076
2020 PO4802609923	KU	3	45 BRO	SP	CCA		V	9/6/2076
2020 PO4798309810	KU	3	45 BRO	SP	CCA		V	9/7/2076
2020 PO4786609521	KU	2	50 BRO	SP	CRE		V	9/8/2076
2020 PO4787909552	KU	3	45 BRO	SP	CRE		V	9/9/2076
2020 PO4793509692	KU	3	45 BRO	SP	CCA		V	9/10/2076
2020 PO4789709597	KU	3	45 BRO	SP	CRE	ID,IP	BD	9/11/2076
2020 PO9557348617	ODP	2	45 BRN	SP	CRE	ID	BD	9/12/2076
2020 PO9559048666	ODP	2	45 BRN	SP	CRE	ID	BD	9/13/2076
2020 PO0170551657	ODP	4	40 BRN	SP	CCA		V	9/14/2076
2020 PO9629248702	ODP	4	40 BRN	SP	CCA	ID	BD	9/15/2076
2020 PO0284247518	ODP	2	50 BRN	SP	CCA		V	9/16/2076
2020 PO0333145931	ODP	3	60 BRN	SP	CCA		V	9/17/2076
2020 PO9950447274	ODP	3	40 BRN	SP	CRE	ID	BD	9/18/2076
2020 PO0428446655	ODP	4	40 BRN	SP	CCA		V	9/19/2076
2020 PO0323146678	ODP	4	40 BRN	SP	CRE		V	9/20/2076
2020 PO0404746671	ODP	4	40 BRN	SP	CCA		V	9/21/2076
2020 PO9558148642	ODP	2	45 BRN	SP	CRE	ID	BD	9/22/2076
2020 PO0204251663	ODP	3	45 BRN	SP	CCA		V	9/23/2076
2020 PO0345346849	ODP	4	40 BRN	SP	CRE		V	9/24/2076
2020 PO4686311043	KU	3	45 BRO	SP	CRE		V	9/25/2076
2020 PO4699010990	KU	4	40 BRO	SP	CRE		V	9/26/2076
2020 PO4710810943	KU	4	40 BRO	SP	CRE		V	9/27/2076
2020 PO4694787701	LGE	4	40 BRO	SP	A	ED,ID	BD	9/28/2076
2020 PO4693387692	LGE	4	40 BRO	SP	A	ED,ID	TD	9/29/2076
2020 PO4691887682	LGE	4	40 BRO	SP	CRE	ED,ID	TD	9/30/2076
2020 PO4690487673	LGE	4	40 BRO	SP	CRE	ED,ID	TD	10/1/2076
2020 PO4688987664	LGE	4	40 BRO	SP	CRE	ED,ID	TD	10/2/2076
2020 PO4687087652	F	4	40 BRO	SP	CRE		V	10/3/2076
2020 PO4684787688	F	4	40 BRO	SP	CRE		V	10/4/2076
2020 PO5100909753	F	4	40 BRO	SP	CRE		V	10/5/2076
2020 PO5118609791	F	4	40 BRO	SP	CRE		V	10/6/2076
2020 PO5108809822	F	4	40 BRO	SP	CRE		V	10/7/2076
2020 PO4797688986	LGE	4	40 BRN	SP	CRE	ED,ID	BD	10/8/2076
2020 PO8979741859	ODP	4	40 ACW	SP	CRE	ED,ID	TD	10/9/2076
2020 PO8978841413	ODP	4	40 ACW	SP	S		V	10/10/2076
2020 PO8975841540	ODP	5	35 ACW	DF	CRE	ED,ID	TD	10/11/2076

2020 P08975841540A	ODP	4	35 ACW	SP	S		V			10/12/2076
2020 P08971241876	F	5	35 ACW	SP	CCA		V			10/13/2076
2020 P08973741930	ODP	6	35 ACW	SP	CRE	ID	BD			10/14/2076
2020 P08917242188	ODP	4	45 ACW	SP	CRE	ED,ID	TD			10/15/2076
2020 P08950842172	ODP	4	40 ACW	SP	CRE	ED,ID	TD			10/16/2076
2020 P08904842891	ODP	4	40 ACW	SP	CRE	ID	BD			10/17/2076
2020 P08936942605	ODP	5	35 ACW	SP	S		V			10/18/2076
2020 P08919342585	ODP	2	50 ACW	SP	S		V			10/19/2076
2020 PO4798788990	LGE	4	40 BRN	SP	CRE	ED,ID	TD			10/20/2076
2020 PO4744887683	LGE	4	40 BRO	SP	CCA		V			10/21/2076
2020 PO4745587694	LGE	4	40 BRO	SP	CCA		V			10/22/2076
2020 PO4746587710	LGE	3	45 BRO	SP	CRE	ED,ID	BD			10/23/2076
2020 PO4746687713	LGE	4	30 BRO	SP	CCA	ED,ID	BD			10/24/2076
2020 PO4745787714	LGE	4	40 BRO	SP	CCA	ED,ID	BD			10/25/2076
2020 PO4744387673	LGE	4	40 BRO	SP	CRE	ED,ID	TD			10/26/2076
2020 PO4745087719	LGE	4	40 BRO	SP	CRE	ED,ID	TD			10/27/2076
2020 PO4744587725	LGE	4	40 BRO	SP	P	ED,ID	TD			10/28/2076
2020 PO4743687738	LGE	4	40 BRO	SP	P	ED,ID	TD			10/29/2076
2020 PO4743387744	LGE	4	40 BRO	SP	CRE	ED,ID	BD			10/30/2076
2020 PO4682287723	F	4	40 BRO	SP	CCA		V			10/31/2076
2020 PO1229933844	F	4	40 XXX	SP	A	ID	BX	RP3		11/1/2076
2020 1220433829b	ODP	6	25 XXX	SP	A	ID	BX	RP2		11/2/2076
2020 1220433829a	ODP	4	40 XXX	SP	CRE		V			11/3/2076
2020 PO1213033828	F	4	40 XXX	SP	CRE		V			11/4/2076
2020 PO3987882739	LGE	4	40 BRN	SP	CRE	ED,ID	TD			11/5/2076
2020 PO3987182757	F	4	40 BRN	SP	CRE		V			11/6/2076
2020 1183233932a	ODP	6	30 XXX	SP	CCA		V			11/7/2076
2020 PO1183233932	F	4	30 XXX	SP	A		V			11/8/2076
2020 PO1187733864	ODP	5	30 XXX	SP	CRE	ED,ID	TD			11/9/2076
2020 PO1175633879	ODP	4	40 BRN	SP	CRE	ED,ID	TD			11/10/2076
2020 PO3985782749	F	4	30 BRN	SP	CRE		V			11/11/2076
2020 PO7186990453	KU	4	40 BRO	SP	CRE	ED	TD			11/12/2076
2020 PO7183490319	KU	6	30 BRO	SP	CRE	ED	TD			11/13/2076
2020 PO7160190270	KU	6	30 BRO	SP	CRE	ED,ID	BD			11/14/2076
2020 PO7355292612	KU	3	50 BRO	SP	CCA		V			11/15/2076
2020 PO7359492868	KU	3	45 BRO	SP	CRE	ED,ID,IP,RB	TX	RR		11/16/2076
2020 PO7350892605	KU	5	35 BRO	SP	CRE	ED,ID	TD			11/17/2076
2020 PO5539609582	KU	6	30 BRO	SP	CRE		V			11/18/2076
2020 PO5538809641	KU	4	40 BRO	SP	CRE	ID	BD			11/19/2076
2020 PO5543209707	KU	3	50 BRO	SP	CCA		V			11/20/2076
2020 PO7076090235	KU	5	35 BRN	SP	CRE	ED,ID	TD			11/21/2076
2020 PO7085190162	KU	5	35 BRN	SP	CRE	ED,ID,IP	BD			11/22/2076
2020 PO7027493823	KU	5	35 BRN	SP	CRE	ED,ID	TD			11/23/2076
2020 PO7338192661	KU	3	40 BRO	SP	CRE	ED,ID	TD			11/24/2076
2020 PO7021993677	KU	6	30 BRN	SP	CRE	ED,ID	BD			11/25/2076
2020 PO7012393785	KU	6	30 BRN	SP	CCA		V			11/26/2076
2020 PO7009393709	KU	5	35 BRN	SP	CRE	ED,ID	BD			11/27/2076

2020 PO7067190311	KU	5	35 BRN	SP	CRE	ED,ID	TD	11/28/2076
2020 PO7079690492	KU	5	35 BRN	SP	CRE	ED,ID	TD	11/29/2076
2020 PO7072290384	KU	5	35 BRN	SP	CRE	ED,ID	TD	11/30/2076
2020 PO7098690586	KU	6	30 BRN	SP	CRE	ED,ID	TD	12/1/2076
2020 PO7086690594	KU	4	40 BRN	SP	CRE	ED,ID	BD	12/2/2076
2020 PO7089790638	KU	4	40 BRN	SP	CRE	ED,ID	BD	12/3/2076
2020 PO7096590745	KU	4	40 BRN	SP	CRE	ED,EP,ID,IP	TD	12/4/2076
2020 PO7165990199	KU	6	30 BRO	SP	CRE	ED,ID	TD	12/5/2076
2020 PO7173290279	KU	4	40 BRO	SP	CRE	ED,ID	TD	12/6/2076
2020 PO7352192945	KU	4	35 BRO	SP	CRE	ED,ID	TD	12/7/2076
2020 PO7366092916	KU	4	45 BRO	SP	CRE	ED,ID	TD	12/8/2076
2020 PO6993593430	KU	5	35 BRN	SP	CCA		V	12/9/2076
2020 PO6983793521	KU	4	40 BRN	SP	CCA		V	12/10/2076
2020 PO6975993429	KU	4	40 BRN	SP	CRE	ED,ID	TD	12/11/2076
2020 PO7173890221	KU	5	35 BRO	SP	CRE	ED,ID	TD	12/12/2076
2020 PO7182190152	KU	4	40 BRO	SP	CCA		V	12/13/2076
2020 PO7176390102	KU	4	40 BRO	SP	CRE	ED,ID	BD	12/14/2076
2020 PO1588549252	ODP	5	35 BRN	SP	CRE	ED,ID,SRS	TD	12/15/2076
2020 PO7172690131	F	4	35 BRO	SP	CCA		V	12/16/2076
2020 PO7376493004	KU	4	45 BRO	SP	CRE	ED,ID	TD	12/17/2076
2020 PO7386093082	KU	3	45 BRO	SP	CCA		V	12/18/2076
2020 PO7377193150	KU	4	40 BRO	SP	CRE	ID	BD	12/19/2076
2020 PO6966493316	KU	4	40 BRN	SP	CRE	ED,ID	TD	12/20/2076
2020 PO7153590103	KU	6	30 BRO	SP	CRE	ED,ID	BD	12/21/2076
2020 PO7165490009	KU	4	40 BRO	SP	CRE	ED,ID	BD	12/22/2076
2020 PO7185789878	KU	5	35 BRO	SP	CRE	ED,ID	TD	12/23/2076
2020 PO6957993220	KU	4	40 BRN	SP	CRE	ED,ID	TD	12/24/2076
2020 PO7376993469	KU	5	35 BRO	SP	CRE	ID	BD	12/25/2076
2020 PO7381593545	KU	6	30 BRO	SP	CRE		B	12/26/2076
2020 PO7386593263	KU	4	40 BRO	SP	CRE	ID	BD	12/27/2076
2020 PO5775306273	KU	6	30 BRN	SP	CCA		V	12/28/2076
2020 PO5788106076	KU	6	30 BRN	SP	CCA		V	12/29/2076
2020 PO5784105989	F	4	40 BRN	SP	CCA		V	12/30/2076
2020 PO5771206157	KU	5	30 BRN	SP	CCA		V	12/31/2076
2020 PO5770606073	F	4	40 XXX	SP	CRE		V	1/1/2077
2020 PO5764806212	KU	6	30 KOP	SP	CCA		V	1/2/2077
2020 PO5748206257	F	4	40 XXX	SP	CRE		V	1/3/2077
2020 PO5737006353	F	4	40 XXX	SP	CRE		V	1/4/2077
2020 PO1454134482	ODP	2	55 KOP	SP	CRE	ED,ID,MD	TD	1/5/2077
2020 PO1466834658	ODP	2	65 KOP	SP	CRE	ED,ID,MD	TD	1/6/2077
2020 PO1464934799	ODP	2	50 KOP	SP	CRE	ED,ID,MD,SRC	TD	1/7/2077
2020 PO1446634449	ODP	2	50 KOP	SP	S		V	1/8/2077
2020 PO6949589871	KU	6	30 BRN	SP	CCA		V	1/9/2077
2020 PO1430025980	F	4	40 BRN	SP	CRE	ED,ID	VX	1/10/2077
2020 PO7024789087	KU	3	55 BRN	SP	CRE	ED,ID	BD	1/11/2077
2020 PO5313006498	KU	4	40 XXX	SP	CRE	ED,ID	TD	1/12/2077
2020 PO5327206526	KU	4	40 XXX	SP	CRE	ED,ID	TD	1/13/2077

2020 PO5325506624	F	6	30 XXX	SP	CRE		V		1/14/2077
2020 PO5317906616	KU	3	45 XXX	SP	CCA		V		1/15/2077
2020 PO7031689350	KU	5	35 BRN	SP	CRE	ED,ID	BD		1/16/2077
2020 PO7044689262	KU	4	40 BRN	SP	S		V		1/17/2077
2020 PO7040989190	KU	4	40 BRN	SP	CRE	ED,ID	BD		1/18/2077
2020 PO7371794179	KU	4	40 BRO	SP	CRE	ID	BD		1/19/2077
2020 PO7374894078	KU	5	35 BRO	SP	CRE	ED,ID	TD		1/20/2077
2020 PO7035389261	KU	3	50 BRN	SP	S		V		1/21/2077
2020 PO7009488870	KU	3	50 BRN	SP	CRE	ED,ID	BD		1/22/2077
2020 5292506552A	KU	5	30 XXX	SP	CRE	RB	X	PX	1/23/2077
2020 PO5292506552	KU	6	30 XXX	SP	CRE	ED,ID	TD		1/24/2077
2020 PO5310606700	KU	5	35 XXX	SP	CRE	ED,ID	TD		1/25/2077
2020 PO3899082239	LGE	4	40 BRN	SP	CCA		V		1/26/2077
2020 PO3892082282	LGE	4	35 BRN	SP	CRE		V		1/27/2077
2020 PO6161133725	LGE	3	45 BRN	SP	CRE		V		1/28/2077
2020 PO3897082227	LGE	3	45 BRN	SP	CCA	ED,ID	BD		1/29/2077
2020 PO3897282236	LGE	4	35 BRN	SP	CRE	ED,ID	TD		1/30/2077
2020 PO3897582245	LGE	4	40 BRN	SP	CRE	ED,ID	TD		1/31/2077
2020 PO3888182315	LGE	4	30 BRN	SP	CRE	ED,ID	TD		2/1/2077
2020 PO3889382298	LGE	4	30 BRN	SP	CRE	ED,ID	BD		2/2/2077
2020 PO3890882288	LGE	4	35 BRN	SP	CRE	ED,ID	TD		2/3/2077
2020 PO3889782315	LGE	4	30 BRN	SP	CRE	ED,ID	TD		2/4/2077
2020 PO3888482308	LGE	4	30 BRN	SP	CRE	ED,ID	TD		2/5/2077
2020 PO1437225994	ODP	5	35 BRN	SP	CCA		V		2/6/2077
2020 PO1191237599	ODP	5	35 XXX	SP	CRE	ED,ID	TD		2/7/2077
2020 PO1181337596	ODP	5	30 XXX	SP	CCA		V		2/8/2077
2020 PO1180037410	ODP	6	30 XXX	SP	CRE	ED,ID	TD		2/9/2077
2020 PO1169937436	ODP	6	30 XXX	SP	CRE	ED,ID	TD		2/10/2077
2020 PO1433725825	F	4	40 BRN	SP	CRE		V		2/11/2077
2020 PO5308906789	KU	6	30 XXX	SP	CRE	ED,ID	TD		2/12/2077
2020 1133637993a	ODP	4	40 XXX	SP	CRE	RB	X	RP1	2/13/2077
2020 PO5299606708	KU	6	30 XXX	SP	CRE		V		2/14/2077
2020 PO5331706890	KU	5	30 XXX	SP	CRE		V		2/15/2077
2020 PO7388894234	KU	4	40 BRO	SP	CRE	ID	BD		2/16/2077
2020 PO7391394161	KU	4	40 BRO	SP	CRE	ED,ID	TD		2/17/2077
2020 PO6976789113	KU	5	35 BRN	SP	CRE	ED,ID	TD		2/18/2077
2020 PO7365894355	KU	6	30 BRO	SP	CRE	ED,ID	TD		2/19/2077
2020 PO7015088950	KU	4	50 BRN	SP	CRE	ED,ID	BD		2/20/2077
2020 PO7008388996	KU	4	50 BRN	SP	CRE	ED,ID	BD		2/21/2077
2020 PO6997589069	KU	4	50 BRN	SP	CRE	ED,ID	BD		2/22/2077
2020 PO6999689098	KU	3	50 BRN	SP	CRE		V		2/23/2077
2020 PO6991589241	KU	5	35 BRN	SP	CRE	ED,ID	BD		2/24/2077
2020 PO6990389405	KU	6	30 BRN	SP	CRE	ED,ID	BD		2/25/2077
2020 PO6986189148	KU	4	45 BRN	SP	CRE	ED,ID	TD		2/26/2077
2020 PO6984789319	KU	5	35 BRN	SP	CRE	ED,ID	BD		2/27/2077
2020 PO6976189216	KU	4	45 BRN	SP	CRE	ED,ID	TD		2/28/2077
2020 PO6978989240	F	4	40 BRN	SP	CRE		V		3/1/2077

2020 PO1143037912	ODP	4	40 XXX	SP	CCA		V			3/2/2077
2020 PO1147437823	ODP	4	45 XXX	SP	CCA		V			3/3/2077
2020 PO1132037900	ODP	5	40 XXX	SP	CRE	ED,ID	TD			3/4/2077
2020 PO1122438025	ODP	6	30 BRN	SP	CRE		V			3/5/2077
2020 PO1116937983	ODP	4	45 BRN	SP	CCA		V			3/6/2077
2020 PO1101738041	ODP	4	45 BRN	SP	CCA		V			3/7/2077
2020 PO1075038119	ODP	4	45 BRN	SP	CCA		V			3/8/2077
2020 PO3985583114	LGE	4	40 BRN	SP	S		V			3/9/2077
2020 PO3891882277	LGE	4	40 BRN	SP	CRE	ED,ID	TD			3/10/2077
2020 PO3890782284	LGE	4	40 BRN	SP	P	ED,ID	TD			3/11/2077
2020 PO3889182292	LGE	4	40 BRN	SP	CRE	ED,ID	TD			3/12/2077
2020 PO3887982298	LGE	4	40 BRN	SP	CRE	ED,ID	TD			3/13/2077
2020 PO3926582417	F	4	35 BRN	SP	CRE	ED,ID	BX	PX		3/14/2077
2020 PO3925482396	F	4	40 BRN	SP	CRE		V			3/15/2077
2020 PO6470835992	F	4	40 BRN	SP	CRE		V			3/16/2077
2020 PO3986783115	LGE	3	45 BRN	SP	S		V			3/17/2077
2020 PO7375894400	KU	5	35 BRO	SP	CRE	ED,ID	TD			3/18/2077
2020 PO3987883117	LGE	4	40 BRN	SP	CRE	ED,HH,ID,RB	X	PX		3/19/2077
2020 PO7382394425	KU	5	45 BRO	SP	CRE	ED,ID	TD			3/20/2077
2020 PO7391994753	KU	4	40 BRO	SP	CRE	ID	BD			3/21/2077
2020 PO1543475705	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD			3/22/2077
2020 PO1554275982	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD			3/23/2077
2020 PO1576076556	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD			3/24/2077
2020 PO1605177322	KU	4	40 BRN	SP	CRE	ID,IP	BD			3/25/2077
2020 PO1587076840	KU	4	40 BRN	SP	CRE	ID,RB	X	RP1		3/26/2077
2020 PO1597477119	KU	4	40 BRN	SP	CRE	ED,ID,IP	TX	RR		3/27/2077
2020 PO1564976282	KU	4	40 BRN	SP	CRE	ID,IP	BD			3/28/2077
2020 PO1127374509	KU	4	40 BRN	SP	CRE	ID,IP	BD			3/29/2077
2020 PO1132474445	KU	4	40 BRN	SP	CRE	ID,IP	BD			3/30/2077
2020 PO0174552748	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD			3/31/2077
2020 PO9153662612	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD			4/1/2077
2020 PO3989083118	LGE	4	40 BRN	SP	CRE	ED,HH,ID,RB	X	PX		4/2/2077
2020 PO3482342760	ODP	4	40 BRO	SP	CRE		V			4/3/2077
2020 PO3485542801	ODP	4	40 BRO	SP	CRE		V			4/4/2077
2020 PO3470242650	ODP	4	40 BRO	SP	CRE	ID	BD			4/5/2077
2020 PO3464242500	ODP	2	55 BRO	SP	CCA		V			4/6/2077
2020 PO2610626943	ODP	4	40 BRO	SP	CRE	ID	TD			4/7/2077
2020 PO2625426819	ODP	4	40 BRO	SP	CRE	ID	TD			4/8/2077
2020 PO2641226688	ODP	5	35 BRO	SP	CRE	ID	TD			4/9/2077
2020 PO2661826507	ODP	4	40 BRO	SP	CRE	ID	TD			4/10/2077
2020 PO2909452887	KU	4	45 BRO	SP	CCA		V			4/11/2077
2020 PO3193049968	F	4	40 BRO	SP	CRE		V			4/12/2077
2020 PO3989983119	LGE	4	40 BRN	SP	CCA		V			4/13/2077
2020 PO3991183121	LGE	4	40 BRN	SP	CRE	ED,ID	TD			4/14/2077
2020 PO3992383123	LGE	4	40 BRN	SP	CRE	ED,ID,IP,RB	TX	RR		4/15/2077
2020 PO0072732752	ODP	5	35 XXX	SP	CRE	ED,ID,RB	X	RP1		4/16/2077
2020 PO1370070258	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD			4/17/2077

2020 PO9271855338	KU	4	45 BRN	SP	CCA		V		4/18/2077
2020 PO1205059654	KU	2	55 BRN	SP	CRE	ID,IP	BD		4/19/2077
2020 PO1237358269	KU	2	50 BRN	SP	CRE		V		4/20/2077
2020 PO1199659867	KU	2	55 BRN	SP	CRE	ID,IP	BD		4/21/2077
2020 PO1216159183	KU	2	50 BRN	SP	CRE	ID	TD		4/22/2077
2020 PO1221158968	KU	2	50 BRN	SP	CRE	ID	TD		4/23/2077
2020 PO1226558718	KU	2	50 BRN	SP	CRE	ED	TD		4/24/2077
2020 PO9239756698	KU	5	35 BRN	SP	CRE	ED,ID,SRC	TD		4/25/2077
2020 PO9232855499	KU	4	40 BRN	SP	CRE	HH,ID,SRC	TD		4/26/2077
2020 PO9194955654	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD		4/27/2077
2020 PO1420770255	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD		4/28/2077
2020 PO1146875511	KU	3	50 BRN	SP	CRE	ED,ID,IP	TD		4/29/2077
2020 PO1354171030	KU	4	40 BRN	SP	P	ED	T		4/30/2077
2020 PO1361870626	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD		5/1/2077
2020 PO1232158469	KU	2	50 BRN	SP	CRE	ID	TD		5/2/2077
2020 PO9990937966	ODP	2	50 BRN	SP	CCA		V		5/3/2077
2020 PO4010282570	LGE	4	40 BRN	SP	CRE	ED,ID	TD		5/4/2077
2020 PO4010182554	LGE	6	30 BRN	SP	P	ED,ID	TD		5/5/2077
2020 PO4010582554	LGE	4	40 BRN	SP	CRE	ED,ID	TD		5/6/2077
2020 PO2410745313	KU	3	45 BRN	SP	CRE	ED,ID,IP	TD		5/7/2077
2020 PO2266645562	KU	4	40 BRN	SP	CCA		V		5/8/2077
2020 PO9841138016	ODP	4	45 BRN	SP	CRE		V		5/9/2077
2020 PO9820538019	ODP	4	45 BRN	SP	CRE		V		5/10/2077
2020 PO9801538024	ODP	4	40 BRN	SP	CRE		V		5/11/2077
2020 PO9833538016	ODP	4	40 BRN	SP	CRE		V		5/12/2077
2020 PO9752337768	ODP	4	45 BRN	SP	CRE		V		5/13/2077
2020 PO9784038024	ODP	4	40 BRN	SP	CRE		V		5/14/2077
2020 PO9793438024	ODP	4	40 BRN	SP	CRE		V		5/15/2077
2020 PO9840938213	ODP	4	45 BRN	SP	CCA		V		5/16/2077
2020 PO9840938162	ODP	2	60 BRN	SP	CRE		V		5/17/2077
2020 PO9748337910	ODP	4	35 BRN	SP	CRE		V		5/18/2077
2020 PO1237358269-A	KU	3	45E BRN	SP	CRE	ID,IP	TD		5/19/2077
2020 PO0117732769	ODP	5	35 XXX	SP	CRE	ED,ID,RB	X	RP1	5/20/2077
2020 PO9329660970	KU	4	45 ACW	SP	P	ED	T		5/21/2077
2020 PO1224958056	KU	4	40 BRN	SP	CRE	HH,RB	X	RP1	5/22/2077
2020 PO1228258039	KU	4	40 BRN	SP	CRE	HH,RB	X	RP1	5/23/2077
2020 PO9155256011	KU	4	40 BRN	SP	CRE		V		5/24/2077
2020 PO9152955831	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD		5/25/2077
2020 PO9149055459	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD		5/26/2077
2020 PO9151155652	KU	4	40 BRN	SP	CCA	ID	B		5/27/2077
2020 PO9146255222	KU	4	40 BRN	SP	CCA	ID	B		5/28/2077
2020 PO9249256561	KU	5	35 BRN	SP	CRE	ED,ID,SRC	TD		5/29/2077
2020 PO9255356854	KU	5	35 BRN	SP	CRE	ED,ID,SRC	TD		5/30/2077
2020 PO9235457192	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		5/31/2077
2020 PO1219957906	KU	4	40 BRN	SP	CRE	ED,EP	TD		6/1/2077
2020 PO1380169719	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD		6/2/2077
2020 PO1279179678	KU	4	40 BRN	SP	CCA		V		6/3/2077

2020 PO1158279245	KU	3	50 BRN	SP	P	ED	T		6/4/2077
2020 PO1215857771	KU	4	45 BRN	SP	P	ED	TD		6/5/2077
2020 PO0097232676	ODP	4	45 XXX	SP	CRE	ED,ID,RB	X	RP1	6/6/2077
2020 PO3925181995	LGE	1	70 BRN	SP	CRE	ED,ID	BD		6/7/2077
2020 PO3924481979	LGE	1	70 BRN	SP	CRE	ED,ID	BD		6/8/2077
2020 PO3924181971	LGE	1	95 BRN	SP	CRE		V		6/9/2077
2020 PO3923781962	LGE	1	70 BRN	SP	CRE	ED,ID	BD		6/10/2077
2020 PO3923181945	LGE	1	80 BRN	SP	CRE	ED,ID	BD		6/11/2077
2020 PO3922681937	LGE	1	95 BRN	SP	CRE		V		6/12/2077
2020 PO3922281926	LGE	1	55 BRN	SP	CRE	ED,ID	BD		6/13/2077
2020 PO3921481907	LGE	1	55 BRN	SP	CRE	ED,ID	BD		6/14/2077
2020 PO3921081899	LGE	1	95 BRN	SP	CRE		V		6/15/2077
2020 PO3919581855	LGE	4	40 BRN	SP	CRE		V		6/16/2077
2020 PO3919281856	LGE	UNK	115 BRN	SP	CRE		V		6/17/2077
2020 PO3919881869	LGE	1	55 BRN	SP	CRE	ED,ID	BD		6/18/2077
2020 PO3920581888	LGE	1	55E BRN	SP	CRE	ED,ID	BD		6/19/2077
2020 PO1207457539	KU	4	45 BRN	SP	P	ED	TD		6/20/2077
2020 PO4011082511	LGE	4	40 BRN	SP	CRE	ED,ID	TD		6/21/2077
2020 PO1199657302	KU	4	45 BRN	SP	CRE	ED,IP	TD		6/22/2077
2020 PO1191457072	KU	4	45 BRN	SP	CRE	ED,ID,RB	TX	RR	6/23/2077
2020 PO9306961191	KU	4	45 ACW	SP	P	ED	T		6/24/2077
2020 PO9288461349	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		6/25/2077
2020 PO1151679095	KU	3	50 BRN	SP	P	ED	T		6/26/2077
2020 PO1145978969	KU	3	50 BRN	SP	P	ED	T		6/27/2077
2020 PO1127378537	KU	3	50 BRN	SP	P	ED	T		6/28/2077
2020 PO9304761647	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		6/29/2077
2020 PO9295961486	KU	4	40 ACW	SP	P	ED	T		6/30/2077
2020 PO9275660935	KU	5	35 ACW	SP	CRE	ED,ID	TD		7/1/2077
2020 PO1208061266	KU	4	40 BRN	SP	CCA		V		7/2/2077
2020 PO1183561367	KU	4	40 BRN	SP	CRE	ED,ID	TD		7/3/2077
2020 PO9250161353	KU	4	40 ACW	SP	P	ED	T		7/4/2077
2020 PO9213061360	KU	4	40 ACW	SP	P	ED	T		7/5/2077
2020 PO9197262174	KU	4	40 ACW	SP	P	ED	T		7/6/2077
2020 PO9189061700	KU	4	40 ACW	SP	CRE	ED	T		7/7/2077
2020 PO9182761359	KU	4	45 ACW	SP	P	ED	T		7/8/2077
2020 PO0132732458	ODP	4	40 BRN	SP	CRE	ED,ID	TD		7/9/2077
2020 PO0157232309	ODP	4	45 BRN	SP	CCA		V		7/10/2077
2020 PO0168732251	ODP	5	30 BRN	SP	CCA		V		7/11/2077
2020 PO1344932682	ODP	5	30 XXX	SP	CRE	ID	TD		7/12/2077
2020 PO1333832636	ODP	4	40 XXX	SP	CRE	ID	BD		7/13/2077
2020 PO1337532568	ODP	4	40 XXX	SP	CRE	ID	TD		7/14/2077
2020 PO1346032410	ODP	4	40 XXX	SP	CRE	ID	TD		7/15/2077
2020 PO1353532258	ODP	4	40 XXX	SP	CRE	ID	TD		7/16/2077
2020 PO1358232169	ODP	5	35 XXX	SP	CRE	ID	TD		7/17/2077
2020 PO1363432075	ODP	4	40 XXX	SP	CRE	ID	TD		7/18/2077
2020 PO1372432042	ODP	6	30 XXX	SP	CRE	ID,IP	TD		7/19/2077
2020 PO1379131784	ODP	4	40 XXX	SP	CRE	ID	TD		7/20/2077

2020 PO1384431764	ODP	4	45 XXX	SP	CRE	ID	TD	7/21/2077
2020 PO1394031871	ODP	5	30 XXX	SP	CRE	ID	TD	7/22/2077
2020 PO1473031264	ODP	4	45 XXX	SP	CRE	ID	TD	7/23/2077
2020 PO8725145321	ODP	4	40 XXX	SP	CRE	ED,ID	TD	7/24/2077
2020 PO8720645523	ODP	4	45 XXX	SP	CRE	ED,ID	TD	7/25/2077
2020 PO1404931706	ODP	4	45 XXX	SP	CCA	ED	T	7/26/2077
2020 PO1428531495	ODP	2	50 XXX	SP	CCA	ED	T	7/27/2077
2020 PO1459231540	ODP	5	30 XXX	SP	CRE	ID	TD	7/28/2077
2020 PO1441031456	ODP	4	45 XXX	SP	CCA		V	7/29/2077
2020 PO1440631709	ODP	4	40 XXX	SP	CRE	ID	TD	7/30/2077
2020 PO1456031750	ODP	4	45 XXX	SP	CCA		V	7/31/2077
2020 PO1459931649	ODP	5	35 XXX	SP	CRE	ID	TD	8/1/2077
2020 PO1464531313	ODP	4	45 XXX	SP	CRE	ID	TD	8/2/2077
2020 PO1477331087A	ODP	4	40 XXX	SP	CCA		V	8/3/2077
2020 PO1477331087	ODP	5	35 XXX	SP	CRE	ID	TD	8/4/2077
2020 PO1482931204	ODP	4	40 XXX	SP	CRE	ID	TD	8/5/2077
2020 PO1497131347	ODP	4	40 XXX	SP	CRE	ID	TD	8/6/2077
2020 PO1489431415	ODP	4	40 XXX	SP	CCA		V	8/7/2077
2020 PO1107328010	ODP	3	45 XXX	SP	CCA		V	8/8/2077
2020 PO8688245503	ODP	4	45 XXX	SP	CRE	ED,ID	TD	8/9/2077
2020 PO8688245503a	ODP	6	30 BRN	SP	CRE	ED,ID	TD	8/10/2077
2020 PO8678044842	F	4	40 BRN	SP	P		V	8/11/2077
2020 PO8649144831	F	4	40 BRN	SP	P		V	8/12/2077
2020 PO8621944692	F	3	45 BRN	SP	CRE		V	8/13/2077
2020 PO8593444563	F	4	40 BRN	SP	P		V	8/14/2077
2020 PO8567844454	F	4	40 BRN	SP	CRE		V	8/15/2077
2020 PO8529344524	F	4	40 BRN	SP	P		V	8/16/2077
2020 PO8548144373	F	4	45 BRN	SP	P		V	8/17/2077
2020 PO8650644490	ODP	4	40 BRN	SP	CRE	ED,ID	TD	8/18/2077
2020 PO8636544441	ODP	5	30 XXX	SP	CRE		V	8/19/2077
2020 PO8513244652	F	2	50 XXX	SP	CRE		V	8/20/2077
2020 PO8498744760	F	3	40 XXX	SP	A		V	8/21/2077
2020 PO3337952666	KU	4	40 ACE	SP	CRE	ED,EP,HH,ID	TX	RR 8/22/2077
2020 PO3293852677	KU	3	45 ACE	SP	CCA		V	8/23/2077
2020 PO3203750289	KU	5	35 ACE	SP	CCA		V	8/24/2077
2020 PO4445803396	KU	4	40 BRO	SP	CRE	ID,IP	BD	8/25/2077
2020 PO4394303305	KU	4	40 BRO	SP	CRE	ED,ID	TD	8/26/2077
2020 PO4404303272	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/27/2077
2020 PO4427803343	KU	4	40 BRO	SP	CRE	ID,IP	BD	8/28/2077
2020 PO4433303840	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/29/2077
2020 PO4421003800	F	5	35 BRO	SP	CCA		V	8/30/2077
2020 PO4441803945	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	8/31/2077
2020 PO3448953091	KU	4	45 ACE	SP	CRE	ED,ID,IP	TD	9/1/2077
2020 PO3430652860	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	9/2/2077
2020 PO3448152845	KU	4	40 ACE	SP	CRE	ED,ID	TD	9/3/2077
2020 PO4454703934	KU	6	30 BRO	SP	A	ED,ID	TD	9/4/2077
2020 PO4449304038	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/5/2077

2020 PO3306252272	KU	3	45 ACE	SP	CCA		V		9/6/2077
2020 PO4104233049	KU	6	30 BRO	SP	CRE	ID	TD		9/7/2077
2020 PO4124332892	KU	5	35 BRO	SP	CRE	ID	BD		9/8/2077
2020 PO4138732961	KU	5	35 BRO	SP	CRE	HH,SRS	X	RP2	9/9/2077
2020 PO4153733033	KU	4	40 BRO	SP	CCA	SRS	TD		9/10/2077
2020 PO4155633100	F	4	40 BRO	SP	CRE		V		9/11/2077
2020 PO4299833439	KU	4	40 BRO	SP	CRE	HH,ID,SRC	X	RP1	9/12/2077
2020 PO4168233057	KU	5	35 BRO	SP	CRE	ED,HH	X	RP1	9/13/2077
2020 PO5067437064	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		9/14/2077
2020 PO4185333047	KU	5	35 BRO	SP	CRE	ID	TD		9/15/2077
2020 PO4198733039	KU	4	40 BRO	SP	CCA	ED	TD		9/16/2077
2020 PO3252650975	KU	4	45 ACE	SP	CRE	ED,ID,IP	TD		9/17/2077
2020 PO3273650852	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		9/18/2077
2020 PO3272450596	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		9/19/2077
2020 PO3242150714	KU	4	45 ACE	SP	CCA	ED,ID	TD		9/20/2077
2020 PO4222432979	KU	4	40 BRO	SP	CRE	ID	TD		9/21/2077
2020 PO9600685252	KU	4	45 ACW	SP	CRE	ED,ID,IP	TD		9/22/2077
2020 PO9590685090	KU	4	45 ACW	SP	CRE	ED,ID	TD		9/23/2077
2020 PO9527485919	KU	3	45 ACW	SP	CCA		V		9/24/2077
2020 PO5865649452	F	4	40 ACE	SP	P		V		9/25/2077
2020 PO5841349647	F	4	40 ACE	DF	P		V		9/26/2077
2020 PO5850549573	F	4	40 ACE	SP	P		V		9/27/2077
2020 PO5101614909	C	4	40 BRO	SP	CRE		V		9/28/2077
2020 PO9582084976	KU	6	30 ACW	SP	CRE	ED,ID	TD		9/29/2077
2020 PO9582084976	KU	4	45 ACW	SP	CRE	ED,ID	TD		9/30/2077
2020 PO9622684967	KU	4	45 ACW	SP	CRE	ED,ID	TD		10/1/2077
2020 PO9530285937	KU	4	40 ACW	SP	S		V		10/2/2077
2020 PO5978147496	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		10/3/2077
2020 PO5964347641	KU	4	40 ACE	SP	CRE	ED,ID	TD		10/4/2077
2020 PO5951547786	KU	4	40 ACE	SP	CRE	ED,ID	TD		10/5/2077
2020 PO5939047921	KU	4	45 ACE	SP	CCA		V		10/6/2077
2020 PO5926948050	KU	4	40 ACE	SP	CCA		V		10/7/2077
2020 PO5142240838	KU	6	30 ACE	SP	CRE		V		10/8/2077
2020 PO5023541849	KU	4	40 ACE	SP	CRE		V		10/9/2077
2020 PO5006341767	KU	5	35 ACE	SP	CCA		V		10/10/2077
2020 PO5008641618	KU	4	40 ACE	SP	CRE	ID,IP	BD		10/11/2077
2020 PO5395546184	KU	5	35 ACE	SP	CCA		V		10/12/2077
2020 PO5283945345	KU	3	45 ACE	SP	CCA		V		10/13/2077
2020 PO5021141816	KU	5	35 ACE	SP	CCA		V		10/14/2077
2020 PO5133040920	KU	3	55 ACE	SP	CRE	ED,ID,IP	TD		10/15/2077
2020 PO5118243755	KU	3	45 ACE	SP	CCA		V		10/16/2077
2020 PO5093843505	KU	3	45 ACE	SP	CCA		V		10/17/2077
2020 PO5069043258a	KU	3	45 ACE	SP	CCA		V		10/18/2077
2020 PO5069043258	KU	3	45 ACE	SP	CCA		V		10/19/2077
2020 PO4969942268a	KU	3	45 ACE	SP	CCA		V		10/20/2077
2020 PO5005714259	KU	5	30 BRO	SP	CRE	ED,ID,IP	TD		10/21/2077
2020 PO5044243010	KU	3	45 ACE	SP	CCA		V		10/22/2077

2020 PO4982714104	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	10/23/2077
2020 PO9539486221	F	4	40 ACW	SP	CRE		V	10/24/2077
2020 PO9534186131	KU	4	40 ACW	SP	CRE	ED,ID	TD	10/25/2077
2020 PO9523386234	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	10/26/2077
2020 PO5915948092	KU	4	40 ACE	SP	CRE	ED,ID	TD	10/27/2077
2020 PO4990713759	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	10/28/2077
2020 PO5909348027	KU	4	40 ACE	SP	CRE	ED,ID	TD	10/29/2077
2020 PO5909748162	KU	4	45 ACE	SP	CRE	ED,ID	TD	10/30/2077
2020 PO5895748318	KU	2	55 ACE	SP	CRE	ED,ID	TD	10/31/2077
2020 PO5890948264	F	4	40 ACE	SP	P		V	11/1/2077
2020 PO5668345637	KU	3	45 ACE	SP	CCA		V	11/2/2077
2020 PO5667445766	KU	6	30 ACE	SP	CCA		V	11/3/2077
2020 PO4985513473	KU	3	45 BRO	SP	CCA		V	11/4/2077
2020 PO4997213399	F	4	40 BRO	SP	A		V	11/5/2077
2020 PO4949013409	KU	3	45 BRO	SP	CCA		V	11/6/2077
2020 PO4916513353	KU	3	45 BRO	SP	CCA		V	11/7/2077
2020 PO4884013296	KU	3	45 BRO	SP	CCA		V	11/8/2077
2020 PO4842713058	KU	6	30 BRO	SP	CCA		V	11/9/2077
2020 PO5679945616	KU	4	40 ACE	SP	CCA		V	11/10/2077
2020 PO5695945644	KU	4	45 ACE	SP	CCA		V	11/11/2077
2020 PO4034083001	LGE	4	35 BRO	SP	P	ED,ID	TD	11/12/2077
2020 PO5019542763	KU	3	45 ACE	SP	CCA		V	11/13/2077
2020 PO4945242021	KU	3	45 ACE	SP	CCA		V	11/14/2077
2020 PO4921141767	KU	3	50 ACE	SP	CCA		V	11/15/2077
2020 PO4994742516	KU	3	45 ACE	SP	CCA		V	11/16/2077
2020 PO4969942268	KU	3	45 ACE	SP	CCA		V	11/17/2077
2020 PO4677240711	KU	4	40 ACE	SP	CRE	ED,ID	TD	11/18/2077
2020 PO5091440903	KU	4	40 ACE	SP	CCA		V	11/19/2077
2020 PO5136241303	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	11/20/2077
2020 PO5135641648	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	11/21/2077
2020 PO5123841973	KU	3	40 ACE	SP	CRE	ED,ID,IP	TD	11/22/2077
2020 PO4657340728	KU	4	40 ACE	SP	CRE	ED,ID	BD	11/23/2077
2020 PO4689840506	KU	3	45 ACE	SP	CCA		V	11/24/2077
2020 PO5123442325	KU	4	40 ACE	SP	CRE	ED,ID	TD	11/25/2077
2020 PO5123142577	KU	3	45 ACE	SP	CRE	ED,ID,IP	TD	11/26/2077
2020 PO4037783073	LGE	4	40 BRO	SP	P	ED,ID	BD	11/27/2077
2020 PO4337543957a	F	4	40 ACE	SP	CCA		V	11/28/2077
2020 PO4337543957b	F	3	35 ACE	SP	P		V	11/29/2077
2020 PO5248001498	F	4	40 ACE	SP	CCA		V	11/30/2077
2020 PO4390642233	KU	4	40 ACE	SP	CRE	ED,HH,ID,IP,RB	X	12/1/2077
2020 PO5160401633	KU	4	40 ACE	SP	CCA		V	12/2/2077
2020 PO5117201634	F	3	40 ACE	SP	CRE		V	12/3/2077
2020 PO5138701634	F	4	40 ACE	SP	CCA		V	12/4/2077
2020 PO4378842096	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	12/5/2077
2020 PO4404142281	KU	6	30 ACE	SP	CCA		V	12/6/2077
2020 PO4402642354	KU	4	40 ACE	SP	CRE	ED,ID	BD	12/7/2077
2020 PO5185401518	F	4	40 ACE	SP	CRE		V	12/8/2077

2020 PO5211201410	F	4	40 ACE	SP	CCA		V	12/9/2077
2020 PO1504122584	ODP	4	45 XXX	SP	CRE		V	12/10/2077
2020 PO1476722533	ODP	6	30 XXX	SP	CRE		V	12/11/2077
2020 PO1512322030	ODP	5	35 XXX	SP	CRE		V	12/12/2077
2020 PO1396021727	F	6	30 XXX	SP	A		V	12/13/2077
2020 PO1353821974	ODP	4	45 XXX	SP	CCA		V	12/14/2077
2020 PO1372021790	F	4	40 XXX	SP	CCA		V	12/15/2077
2020 PO1386821887	F	4	40 XXX	SP	A		V	12/16/2077
2020 PO1393622089	F	4	40 XXX	SP	A		V	12/17/2077
2020 PO1397722183	F	4	40 XXX	SP	A		V	12/18/2077
2020 PO1379222231	F	4	40 XXX	SP	A		V	12/19/2077
2020 PO1358822508	F	4	40 XXX	SP	A		V	12/20/2077
2020 PO1362722656	F	4	40 XXX	SP	A		V	12/21/2077
2020 PO1317622610	F	4	40 XXX	SP	A		V	12/22/2077
2020 PO1351922725	ODP	3	45 XXX	SP	CCA		V	12/23/2077
2020 PO1305022983	ODP	4	45 XXX	SP	CCA		V	12/24/2077
2020 PO1325322763	ODP	4	40 XXX	SP	CCA		V	12/25/2077
2020 PO1381523063	ODP	4	40 XXX	SP	CCA		V	12/26/2077
2020 PO1367822948	ODP	4	40 XXX	SP	CCA		V	12/27/2077
2020 PO1434323367	ODP	2	50 XXX	SP	CCA		V	12/28/2077
2020 PO1427223317	ODP	3	45 XXX	SP	CCA		V	12/29/2077
2020 PO1515522522	ODP	4	45 XXX	SP	CRE	ID	BD	12/30/2077
2020 PO1519822125	ODP	5	35 XXX	SP	CCA		V	12/31/2077
2020 PO1653822754	ODP	3	45 XXX	SP	CCA		V	1/1/2078
2020 PO1655522573	ODP	3	45 XXX	SP	CCA		V	1/2/2078
2020 PO1654522343	ODP	2	55 XXX	SP	CCA		V	1/3/2078
2020 PO1265132843	ODP	4	40 XXX	SP	CRE		V	1/4/2078
2020 PO1268432330	ODP	5	35 XXX	SP	CCA		V	1/5/2078
2020 PO2087727916	ODP	4	45 XXX	SP	CCA		V	1/6/2078
2020 PO2104327989	ODP	4	45 XXX	SP	CCA		V	1/7/2078
2020 PO2041028758	ODP	2	45 XXX	SP	CCA		V	1/8/2078
2020 PO2020528791	ODP	2	45 XXX	SP	CCA		V	1/9/2078
2020 PO2120527776	ODP	2	50 XXX	SP	CCA		V	1/10/2078
2020 PO2104327985A	F	6	30 XXX	SP	CCA		V	1/11/2078
2020 PO2159327321	ODP	2	50 XXX	SP	CCA		V	1/12/2078
2020 PO4654912470	KU	4	40 BRO	SP	CRE	ID	BD	1/13/2078
2020 PO4741789122	LGE	4	35 BRO	SP	CRE	ED,ID	TD	1/14/2078
2020 PO4039383073	LGE	4	30 BRO	SP	P	ED,ID	TD	1/15/2078
2020 PO4037883087	LGE	4	40 BRO	SP	P	ED,ID	BD	1/16/2078
2020 PO4037183087	LGE	4	30 BRO	ST	CCA		V	1/17/2078
2020 PO4037383068	LGE	4	30 BRO	ST	CCA		V	1/18/2078
2020 PO4640412545	KU	5	30 BRO	SP	CRE	ID	BD	1/19/2078
2020 PO4617412689	KU	4	40 BRO	SP	CCA		V	1/20/2078
2020 PO4054183032	LGE	4	30 BRO	SP	P	ED,ID,IP	TX	RR 1/21/2078
2020 PO4741189114	LGE	4	35 BRO	SP	CCA		V	1/22/2078
2020 PO4740889117	LGE	4	35 BRO	SP	CRE	ED,ID	BD	1/23/2078
2020 PO4740089128	LGE	4	40 BRO	SP	CRE	ED,ID	BD	1/24/2078

Business Use

2020 PO4739889132	F	3	45 BRO	SP	CCA		V	1/25/2078
2020 PO4739589136	F	UNK	45 BRO	SP	P		V	1/26/2078
2020 PO4053783035	LGE	4	35 BRO	SP	CCA	ED,HH,ID,RB	X	RP1 1/27/2078
2020 PO4738789148	F	1	50 BRO	SP	CCA		V	1/28/2078
2020 PO4738089144	F	1	50 BRO	SP	CCA		V	1/29/2078
2020 PO4739889166	LGE	4	35 BRO	SP	CRE	ED,ID	TD	1/30/2078
2020 PO4738589164	LGE	4	35 BRO	SP	CRE	ED,ID	TD	1/31/2078
2020 PO5228001420	F	3	40 ACE	SP	CCA		V	2/1/2078
2020 PO4417542516	KU	4	40 ACE	SP	CRE	ED,ID	TD	2/2/2078
2020 PO4437242677	KU	4	40 ACE	SP	CRE	ED,ID	BD	2/3/2078
2020 PO4460543423	F	4	40 ACE	SP	CRE		V	2/4/2078
2020 PO4441643493	F	4	40 ACE	SP	CCA		V	2/5/2078
2020 PO4425043568	F	3	45 ACE	SP	CCA		V	2/6/2078
2020 PO4410743636	F	4	40 ACE	SP	CCA		V	2/7/2078
2020 PO4689843086	F	4	40 ACE	SP	CRE		V	2/8/2078
2020 PO5090901633	F	4	40 ACE	SP	CCA		V	2/9/2078
2020 PO5071801633	F	4	40 ACE	SP	CCA		V	2/10/2078
2020 PO5050101633	F	4	40 ACE	SP	CRE		V	2/11/2078
2020 PO0556493354	KU	5	35 ACW	SP	CRE		BX	RP2 2/12/2078
2020 PO4452702668	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	2/13/2078
2020 PO4453302785	F	3	45 BRO	SP	CRE		V	2/14/2078
2020 PO5244145618	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	2/15/2078
2020 PO5246945518	KU	6	30 ACE	SP	CRE	ED,ID	TD	2/16/2078
2020 PO5249745451	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	2/17/2078
2020 PO5243745530	KU	4	45 ACE	SP	CCA		V	2/18/2078
2020 PO4467402735	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	2/19/2078
2020 PO4474102673	KU	5	35 BRO	SP	CCA		V	2/20/2078
2020 PO5277745883	KU	4	35 ACE	SP	CRE	ED,HH,ID,RB	X	RP1 2/21/2078
2020 PO5296846175	KU	6	30 ACE	SP	CCA		V	2/22/2078
2020 PO5292146086	KU	4	45 ACE	SP	CCA		V	2/23/2078
2020 PO5218646795	KU	4	45 ACE	SP	CRE	ED,ID	TD	2/24/2078
2020 PO4472202920	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD	2/25/2078
2020 PO4482102654	KU	5	35 BRO	SP	CCA		V	2/26/2078
2020 PO4547703090	KU	3	45 BRO	SP	CCA		V	2/27/2078
2020 PO4543803148	KU	3	45 BRO	SP	CCA		V	2/28/2078
2020 PO4535403122	KU	4	40 BRO	ST	P		V	3/1/2078
2020 PO1385532868	ODP	4	40 XXX	SP	CRE	ID,IP	TD	3/2/2078
2020 PO1397932972	ODP	4	40 XXX	SP	CRE	ID	TD	3/3/2078
2020 PO1402633120	ODP	6	35 XXX	SP	CRE	ID,IP	TD	3/4/2078
2020 PO1412533088	F	4	40 XXX	SP	A		V	3/5/2078
2020 PO1416633039	F	4	40 XXX	SP	A		V	3/6/2078
2020 PO9126839344	ODP	4	40 ACW	SP	CRE	ED,ID	TD	3/7/2078
2020 PO9146439325a	ODP	5	40 XXX	SP	CRE	ED,ID	TD	3/8/2078
2020 PO9146439325	ODP	4	40 XXX	SP	CRE	ED,ID	TD	3/9/2078
2020 PO9145839551	ODP	4	40 XXX	SP	CRE		V	3/10/2078
2020 PO9165139502	ODP	5	30 XXX	SP	CRE		V	3/11/2078
2020 PO1429433226	ODP	4	45 XXX	SP	CCA	ED	T	3/12/2078

2020 PO1440833470	ODP	5	35 XXX	SP	CRE	ID	TD		3/13/2078
2020 PO1450333401	ODP	4	45 XXX	SP	CCA	ED	T		3/14/2078
2020 PO1481533476	F	4	40 XXX	SP	CRE		V		3/15/2078
2020 PO9157139034	ODP	3	40 XXX	SP	A	ED,ID	TD		3/16/2078
2020 PO9174639046	ODP	6	30 BRN	SP	CCA	ED	T		3/17/2078
2020 PO9188938931	ODP	4	40 BRN	SP	CCA		V		3/18/2078
2020 PO9209138434	ODP	4	40 BRN	SP	CCA		V		3/19/2078
2020 P05593245353B	KU	6	30 ACW	ST	S		V		3/20/2078
2020 PO5578445077	KU	6	30 ACW	ST	CCA		V		3/21/2078
2020 PO3945234526	KU	3	45 ACE	SP	CCA	ED,ID	TD		3/22/2078
2020 PO3942434657	KU	3	45 ACE	SP	CCA	ED,ID	BD		3/23/2078
2020 PO3888734676	KU	3	45 ACE	SP	CCA	ED,ID	TD		3/24/2078
2020 PO3908634669	KU	3	45 ACE	SP	CCA	ED,ID	BD		3/25/2078
2020 PO3970433371	KU	4	40 ACE	SP	S		V		3/26/2078
2020 PO4804301658	F	4	40 BRO	SP	CRE		V		3/27/2078
2020 PO4825201655	F	4	40 BRO	SP	CRE		V		3/28/2078
2020 PO4817001236	KU	4	40 BRO	SP	CRE	ID,IP	BD		3/29/2078
2020 PO4836501737	KU	3	45 BRO	SP	CCA		V		3/30/2078
2020 PO4786101657	F	4	40 BRO	SP	CRE		V		3/31/2078
2020 PO4573401484	F	3	40 BRO	SP	A		V		4/1/2078
2020 PO4583801344	F	4	40 BRO	SP	CRE		V		4/2/2078
2020 PO3913248138	F	4	40 ACE	SP	CRE		V		4/3/2078
2020 PO3889301201	F	4	40 BRO	SP	CCA		V		4/4/2078
2020 PO3916901205	F	4	40 BRO	SP	CCA		V		4/5/2078
2020 PO3899701396	F	5	30 BRO	SP	CCA		V		4/6/2078
2020 PO9551942658	ODP	3	45 XXX	SP	CCA		V		4/7/2078
2020 PO9528242776	F	5	40 XXX	SP	A		V		4/8/2078
2020 PO9533642833	ODP	5	35 XXX	SP	CRE	ED,ID	TD		4/9/2078
2020 PO4528009321	F	4	40 ACE	SP	CRE	ED,HH,ID,IP,RB	BX	PX	4/10/2078
2020 PO4561509067	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX	4/11/2078
2020 PO3946511945	KU	3	50 BRO	SP	CRE	ID,IP	BD		4/12/2078
2020 PO9651435977	ODP	2	50 BRN	SP	CCA		V		4/13/2078
2020 PO9650836150	ODP	2	50 BRN	SP	CRE		V		4/14/2078
2020 PO1590519919	ODP	4	40 XXX	SP	CRE	ID	TD		4/15/2078
2020 PO4084283267	LGE	4	40 BRN	SP	CRE	ED,ID	TD		4/16/2078
2020 PO3964711867	KU	3	45 BRO	SP	CRE	ID,IP	BD		4/17/2078
2020 PO9503542630	ODP	5	30 XXX	SP	CRE	ED,ID	TD		4/18/2078
2020 PO9493242799	ODP	4	45 XXX	SP	CRE	ED,ID	TD		4/19/2078
2020 PO9517542952	ODP	5	35 XXX	SP	CRE	ED,ID	TD		4/20/2078
2020 PO9713635886	ODP	3	45 BRN	SP	CCA		V		4/21/2078
2020 PO9684735864	ODP	3	45 BRN	SP	CCA		V		4/22/2078
2020 PO9657435857	ODP	2	55 BRN	SP	CCA		V		4/23/2078
2020 PO9654435293	ODP	4	40 BRN	SP	CRE		V		4/24/2078
2020 PO9600635834	ODP	4	45 BRN	SP	CRE		V		4/25/2078
2020 PO9631736022	ODP	4	45 BRN	SP	CRE		V		4/26/2078
2020 PO9676535310	ODP	5	35 BRN	SP	CRE		V		4/27/2078
2020 PO4535909405	F	4	40 ACE	SP	CRE	ED,ID	V		4/28/2078

2020 PO4572109174	F	4	40 ACE	SP	CRE	ED,ID,IP	V	4/29/2078
2020 PO4546509519	F	4	40 ACE	SP	P		V	4/30/2078
2020 PO4555809479	F	5	35 ACE	SP	CRE	ED,ID	V	5/1/2078
2020 PO4579809267	F	4	40 ACE	SP	CRE	ED,ID,IP	V	5/2/2078
2020 PO4553009683	F	4	40 ACE	SP	CRE	ED,HH,ID,IP,RB	BX	5/3/2078
2020 PO4594709416	F	4	40 ACE	SP	CRE	ED,ID	V	5/4/2078
2020 PO4557009778	F	4	40 ACE	SP	CCA		V	5/5/2078
2020 PO4602009588	F	4	40 ACE	SP	CRE	ED,ID,IP	V	5/6/2078
2020 PO4563809952	F	4	40 ACE	SP	CRE	ED,ID	V	5/7/2078
2020 PO4578809892	F	4	40 ACE	SP	CRE	ED,ID	V	5/8/2078
2020 PO4595409826	F	4	40 ACE	SP	P	ED,ID	V	5/9/2078
2020 PO4609509770	F	4	40 ACE	SP	CRE	ED,EP,ID	V	5/10/2078
2020 PO3983311788	KU	3	45 BRO	SP	CRE	ID,IP	BD	5/11/2078
2020 PO3989711944	KU	3	45 BRO	SP	CRE	ID,IP	BD	5/12/2078
2020 PO3995712097	KU	3	45 BRO	SP	CRE	ID,IP	BD	5/13/2078
2020 PO4082583256	LGE	4	40 BRN	SP	CRE	ED,ID	BD	5/14/2078
2020 PO3959782898	LGE	4	40 BRN	SP	CCA		V	5/15/2078
2020 PO1609619424	ODP	6	30 XXX	SP	CRE	ID	TD	5/16/2078
2020 PO1643219429	ODP	5	35 XXX	SP	CRE	ID	TD	5/17/2078
2020 PO1611919459	ODP	4	40 XXX	SP	CRE	ED,ID	T	5/18/2078
2020 PO1601219436	ODP	3	45 XXX	SP	CCA		V	5/19/2078
2020 PO1577619344	F	5	40 XXX	SP	CRE		V	5/20/2078
2020 PO1571419315	F	4	40 XXX	SP	CCA		V	5/21/2078
2020 PO1559419263	F	4	40 XXX	SP	CRE		V	5/22/2078
2020 PO1539319181	F	5	40 XXX	SP	CRE		V	5/23/2078
2020 PO9502943103	ODP	6	30 XXX	SP	CRE	ED,ID	TD	5/24/2078
2020 PO9494443080	ODP	3	45 XXX	SP	CCA		V	5/25/2078
2020 PO9481743064	ODP	5	35 XXX	SP	CRE	ED,ID	TD	5/26/2078
2020 PO9489643134	ODP	5	30 XXX	SP	CRE		V	5/27/2078
2020 PO9626835855	ODP	2	50 BRN	SP	CCA		V	5/28/2078
2020 PO9601435727	ODP	2	55 BRN	SP	CCA		V	5/29/2078
2020 PO9582235509	ODP	2	55 BRN	SP	CCA		V	5/30/2078
2020 PO9574235297	ODP	2	50 BRN	SP	CCA		V	5/31/2078
2020 PO9564134993	ODP	2	50 BRN	SP	CCA		V	6/1/2078
2020 PO9550334755	ODP	2	55 BRN	SP	CCA		V	6/2/2078
2020 PO9564734945	F	4	40 BRN	SP	CRE		V	6/3/2078
2020 PO9569034904	ODP	2	50 BRN	SP	S		V	6/4/2078
2020 PO3967283007	LGE	4	45 BRN	SP	CRE	ED,ID	TD	6/5/2078
2020 PO3966382986	LGE	1	55 BRN	SP	CRE		V	6/6/2078
2020 PO9486643557a	ODP	3	45 XXX	SP	CCA		V	6/7/2078
2020 PO3965582966	LGE	4	45 BRN	SP	CRE	ED,ID	BD	6/8/2078
2020 PO3965082958	LGE	1	90 BRN	SP	CRE		V	6/9/2078
2020 PO3959711798	KU	4	40 BRO	SP	CRE	ID	BD	6/10/2078
2020 PO3977811722	KU	4	40 BRO	SP	CRE		V	6/11/2078
2020 PO3999211633	KU	4	40 BRO	SP	CRE	ID,IP	BD	6/12/2078
2020 PO3999311719	KU	3	45 BRO	SP	CRE	ID,IP	BD	6/13/2078
2020 PO9500843239	ODP	4	45 XXX	SP	CCA		V	6/14/2078

2020 PO9513343387	ODP	5	30 XXX	SP	CRE	ED,ID	TD	6/15/2078
2020 PO9502243444	ODP	5	40 XXX	SP	CRE	ED,ID	TD	6/16/2078
2020 PO3964682946	LGE	4	45 BRN	SP	CRE	ED,ID	BD	6/17/2078
2020 PO3963982928	LGE	4	45 BRN	SP	CRE	ED,ID	BD	6/18/2078
2020 PO3963382916	LGE	1	90 BRN	SP	CRE		V	6/19/2078
2020 PO3962882904	LGE	3	50 BRN	SP	CRE	ED,HH,ID	BX PX	6/20/2078
2020 PO3951582951	LGE	4	30 BRO	SP	P	ED,ID	TD	6/21/2078
2020 PO3952182949	LGE	4	45 BRO	SP	CRE	ED,ID	TD	6/22/2078
2020 PO3947882891	LGE	4	30 BRO	SP	CCA	ED,ID	BD	6/23/2078
2020 PO6808142688	F	4	40 BRO	SP	CCA		V	6/24/2078
2020 PO9502243477	ODP	5	35 XXX	SP	A	ED,ID	TD	6/25/2078
2020 PO9507743671	ODP	5	35 XXX	SP	CRE	ED,ID	TD	6/26/2078
2020 PO9495543915	ODP	4	40 BRN	SP	CCA		V	6/27/2078
2020 PO9513743956	F	4	40 XXX	SP	A		V	6/28/2078
2020 PO3962082885	LGE	3	50 BRN	SP	CRE	ED,ID	BD	6/29/2078
2020 PO3961682878	LGE	1	90 BRN	SP	CRE		V	6/30/2078
2020 PO4013111660	KU	3	45 BRO	SP	CRE	ID,IP	BD	7/1/2078
2020 PO4026811601	KU	4	45 BRO	SP	CCA		V	7/2/2078
2020 PO4491035967	KU	4	40 ACE	SP	CRE		V	7/3/2078
2020 PO4013811572	KU	2	40 BRO	SP	CRE	ID,IP	BD	7/4/2078
2020 PO1248263020	KU	5	35 BRN	SP	CRE		V	7/5/2078
2020 PO1260463203	KU	5	35 BRN	SP	CRE		V	7/6/2078
2020 PO1276563429	KU	5	35 BRN	SP	CRE		V	7/7/2078
2020 PO1311163347	KU	4	40 BRN	SP	CRE		V	7/8/2078
2020 PO1332863289	KU	5	35 BRN	SP	CRE		V	7/9/2078
2020 PO1353863235	KU	5	35 BRN	SP	CRE		V	7/10/2078
2020 PO1377463185	KU	5	35 BRN	SP	CRE		V	7/11/2078
2020 PO1403963118	KU	5	35 BRN	SP	CRE		V	7/12/2078
2020 PO1421663033	KU	4	40 BRN	SP	CRE		V	7/13/2078
2020 PO1440262943	KU	4	40 BRN	SP	CRE		V	7/14/2078
2020 PO1431663553	KU	4	40 BRN	SP	CRE		V	7/15/2078
2020 PO1447263811	KU	4	40 BRN	SP	CRE		V	7/16/2078
2020 PO5645755099	KU	4	40 ACE	SP	CRE	ED,ID	BD	7/17/2078
2020 PO5757831273	F	3	40 BRO	SP	A		V	7/18/2078
2020 PO5769031532	KU	5	35 BRO	SP	CRE	ED,ID	TD	7/19/2078
2020 PO5781131548	KU	4	40 BRO	SP	CRE	ID	BD	7/20/2078
2020 PO5760931527	F	4	40 BRO	SP	A		V	7/21/2078
2020 PO5764931857	F	4	40 BRO	SP	CRE		V	7/22/2078
2020 PO5768132131	F	3	40 BRO	SP	A		V	7/23/2078
2020 PO5659155249	KU	4	40 ACE	SP	CRE	ED,ID	TD	7/24/2078
2020 PO5717832313	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	7/25/2078
2020 5717832313-B	KU	5	40 BRO	SP	CRE	ED,ID	TD	7/26/2078
2020 5717832313-A	KU	5	35 BRO	SP	CRE	ED,ID	TD	7/27/2078
2020 PO5740632328	KU	5	35 BRO	SP	CRE	ED,ID	TD	7/28/2078
2020 PO5778332374	F	5	35 BRO	SP	A		V	7/29/2078
2020 PO5770432348	F	5	40 BRO	SP	A	HH,RB	VX RP1	7/30/2078
2020 PO5774832740	F	4	40 BRO	SP	A		V	7/31/2078

2020 PO5843133166	KU	4	40 BRO	SP	A	ED,ID	TD		8/1/2078
2020 PO4573704413	KU	4	40 BRO	SP	CRE	ED,ID,IP	TX	RR	8/2/2078
2020 PO9613195015	KU	4	40 ACW	SP	CRE	ED,ID	TX	RR	8/3/2078
2020 PO9596495028	KU	7	20 ACW	SP	CRE	ED,ID	TD		8/4/2078
2020 PO5967848661	KU	4	45 ACE	SP	CRE	ED,ID	TD		8/5/2078
2020 PO5712354149	KU	5	35 ACE	SP	CRE	ED,ID	TD		8/6/2078
2020 PO9597994970	KU	4	40 ACW	SP	CRE	ED,ID	X	RP1	8/7/2078
2020 PO9587595043	KU	5	35 ACW	SP	CRE	ED,ID	TD		8/8/2078
2020 PO9585394927	KU	4	40 ACW	SP	CRE	ED,ID	TD		8/9/2078
2020 PO9571094929	KU	6	30 ACW	SP	CRE	ED,ID	TD		8/10/2078
2020 PO9570294879	KU	3	40 ACW	SP	S		V		8/11/2078
2020 PO9061594055	KU	4	40 XXX	SP	CRE	ED,ID	TD		8/12/2078
2020 PO9036093724	KU	3	45 BRN	SP	CCA		V		8/13/2078
2020 PO9262293006	KU	4	45 BRN	SP	CRE	ID	BD		8/14/2078
2020 PO9051993770	KU	4	40 XXX	SP	S	ED,ID	TD		8/15/2078
2020 PO5936548273	KU	5	45 ACE	SP	CRE	ED,ID	BD		8/16/2078
2020 PO5952348517	KU	4	45 ACE	SP	CRE	ED,ID	BD		8/17/2078
2020 PO5954448614	KU	4	45 ACE	SP	CRE	ED,ID	BD		8/18/2078
2020 PO5956348709	KU	5	35 ACE	SP	CCA	ED	T		8/19/2078
2020 PO9236292905	KU	4	40 XXX	SP	CRE	ED,ID	BD		8/20/2078
2020 PO9555994775	KU	6	30 ACW	SP	CRE	ED,EP,ID,IP	X	PX	8/21/2078
2020 PO9555294880	KU	6	30 ACW	SP	CRE	ED,ID	TD		8/22/2078
2020 PO9556494835	KU	4	40 ACW	SP	CRE	ED,ID	TD		8/23/2078
2020 PO9541494787	KU	4	40 ACW	SP	CRE	ED,ID	TD		8/24/2078
2020 PO5945948784	KU	3	45 ACE	SP	CCA		V		8/25/2078
2020 PO5690155058a	KU	6	30 ACE	SP	CCA		V		8/26/2078
2020 PO5690154058	KU	3	40 ACE	SP	CCA		V		8/27/2078
2020 PO5727054566	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		8/28/2078
2020 PO5797554423	KU	5	30 ACE	SP	CRE	ED,ID	BD		8/29/2078
2020 PO5792054664	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		8/30/2078
2020 PO5774854710	KU	4	40 ACE	SP	CRE	ED,ID	BD		8/31/2078
2020 PO5761754748	KU	4	40 ACE	SP	CRE	ED,ID	BD		9/1/2078
2020 PO5735954775	KU	4	40 ACE	SP	CRE	ED,ID	TD		9/2/2078
2020 PO9526394743	KU	4	40 ACW	SP	CRE	ED,ID	TD		9/3/2078
2020 PO5736154910	KU	5	40 ACE	SP	CRE	ED,ID	TD		9/4/2078
2020 PO6003941785	KU	5	35 ACE	SP	CCA		V		9/5/2078
2020 PO5995941759	F	4	40 ACE	SP	CCA		V		9/6/2078
2020 PO1879831418	ODP	6	30 BRN	SP	CRE	ED,ID,SRC	TD		9/7/2078
2020 PO1895831147	ODP	4	40 BRN	SP	CRE		V		9/8/2078
2020 PO1879831419A	ODP	4	40 BRN	SP	CCA		V		9/9/2078
2020 PO1862231627	ODP	4	40 UNK	SP	CRE	ID	TD		9/10/2078
2020 PO1892031604	ODP	6	30 SWP	SP	CRE		V		9/11/2078
2020 PO1862231627A	ODP	4	40 SWP	SP	P	ED,ID,SRS	TD		9/12/2078
2020 PO1842132002	ODP	4	35 UNK	SP	CRE	ED,ID,SRS	TD		9/13/2078
2020 PO1850231772	ODP	4	40 UNK	SP	CRE	ID	TD		9/14/2078
2020 PO1827731411	F	4	40 UNK	SP	CRE		V		9/15/2078
2020 PO1824631727	ODP	5	35 UNK	SP	CRE		V		9/16/2078

2020 PO4454309773	F	4	40 ACE	SP	CRE		V		9/17/2078
2020 PO4491009625	F	4	40 ACE	SP	P		V		9/18/2078
2020 PO4497709708	F	4	40 ACE	SP	P		V		9/19/2078
2020 PO4510409961	F	4	40 ACE	SP	CRE		V		9/20/2078
2020 PO4474910312	F	4	40 ACE	SP	CRE		V		9/21/2078
2020 PO4671488251	F	3	45 BRN	SP	S		V		9/22/2078
2020 PO4672488235	F	4	40 BRN	SP	CRE		V		9/23/2078
2020 PO4669388190	LGE	4	35 BRN	SP	CRE	ED,ID	BD		9/24/2078
2020 PO4668288195	LGE	4	30 BRN	SP	CRE	ED,ID	BD		9/25/2078
2020 PO4667988204	LGE	4	35 BRN	SP	A	ED,ID	BD		9/26/2078
2020 PO2478245942	ODP	4	45 KOP	SP	CRE	ED,EP,ID,IP	X	RP3	9/27/2078
2020 PO2496346193	ODP	4	35 KOP	SP	CCA	ED,ID	TD		9/28/2078
2020 PO2478946190	ODP	4	40 KOP	SP	CRE	ED,ID	TD		9/29/2078
2020 PO4666988221	LGE	4	30 BRN	SP	CRE	ED,ID	BD		9/30/2078
2020 PO4180010956	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD		10/1/2078
2020 PO4502909790	F	4	40 ACE	SP	P		V		10/2/2078
2020 PO4461609969	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	RP1	10/3/2078
2020 PO4468410148	F	4	40 ACE	SP	CRE		V		10/4/2078
2020 PO4665788239	LGE	6	25 BRN	SP	CRE	ED,ID	TD		10/5/2078
2020 PO1385024481	ODP	4	45 BRN	SP	CRE	ID,IP	TD		10/6/2078
2020 PO2523145786	ODP	5	35 KOP	SP	CRE	ED,ID	TD		10/7/2078
2020 PO2502545035	ODP	6	30 KOP	SP	S		V		10/8/2078
2020 PO2514846152	ODP	4	40 KOP	SP	CRE	ED,ID	TD		10/9/2078
2020 PO2496144918	ODP	4	40 KOP	SP	CRE	ED,ID	TD		10/10/2078
2020 PO4489410662	F	4	40 ACE	SP	P		V		10/11/2078
2020 PO4496610684	F	5	35 ACE	SP	P		V		10/12/2078
2020 PO2471546402	F	4	40 KOP	SP	P		V		10/13/2078
2020 PO4668488245	LGE	4	40 BRN	SP	CRE		V		10/14/2078
2020 PO4668988248	LGE	4	40 BRN	SP	CRE	ED,ID	BD		10/15/2078
2020 PO4537409611	F	5	35 ACE	SP	P		V		10/16/2078
2020 PO4518409467	F	4	40 ACE	SP	P		V		10/17/2078
2020 PO4502409367	F	5	35 ACE	SP	CRE		V		10/18/2078
2020 PO4482809268	F	5	35 ACE	SP	CRE		V		10/19/2078
2020 PO4479209495	F	5	35 ACE	SP	CRE		V		10/20/2078
2020 PO3881413185	KU	4	45 BRO	SP	CCA		V		10/21/2078
2020 PO3874113016	KU	4	45 BRO	SP	CCA		V		10/22/2078
2020 PO3758411853	KU	4	40 BRO	SP	CRE		V		10/23/2078
2020 PO4669588239	LGE	4	40 BRN	SP	CRE	ED,ID	BD		10/24/2078
2020 PO4669088236	LGE	4	30 BRN	SP	S		V		10/25/2078
2020 PO3776712045	KU	5	35 BRO	SP	CRE		V		10/26/2078
2020 PO3848012204	KU	2	50 BRO	SP	CRE		V		10/27/2078
2020 PO3769112474	KU	4	40 BRO	SP	CRE		V		10/28/2078
2020 PO3518307606	KU	4	40 BRO	SP	CRE	ID,IP	BD		10/29/2078
2020 PO3532107769	KU	4	40 BRO	SP	CRE	ID	BD		10/30/2078
2020 PO3542407894	KU	4	40 BRO	SP	CRE	ID	BD		10/31/2078
2020 PO3550207981	KU	4	40 BRO	SP	CRE	ID,IP	BD		11/1/2078
2020 PO4669688229	LGE	4	30 BRN	SP	CRE	ED,ID	BD		11/2/2078

2020 PO1338627675	ODP	5	45 BRN	SP	CRE	ID	TD		11/3/2078
2020 PO1266627859	ODP	4	45 BRN	SP	CRE	ID	TD		11/4/2078
2020 PO4485909170	F	4	40 ACE	SP	CRE		V		11/5/2078
2020 PO4468409242	F	5	35 ACE	SP	CRE		V		11/6/2078
2020 PO4060982762	LGE	4	40 BRO	SP	P	ED,ID	TX	RR	11/7/2078
2020 PO4669988232	LGE	4	40 BRN	SP	P	ED,ID	TD		11/8/2078
2020 PO3572408234	KU	4	40 BRO	SP	CRE	ID,IP	BD		11/9/2078
2020 PO3562708122	KU	4	40 BRO	SP	CRE	ID,IP	BD		11/10/2078
2020 PO4486610267	F	4	40 ACE	SP	CRE		V		11/11/2078
2020 PO1304027993	ODP	4	40 BRN	SP	CCA		V		11/12/2078
2020 PO1328128014	ODP	4	40 BRN	SP	CRE	ID	TD		11/13/2078
2020 PO1341027937	ODP	2	50 BRN	SP	CCA		V		11/14/2078
2020 PO1343028164	F	4	40 BRN	SP	A		V		11/15/2078
2020 PO3656408701	KU	4	40 BRO	SP	CRE	ID,IP	BD		11/16/2078
2020 PO4577610350	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	RP1	11/17/2078
2020 PO4582110455	F	4	40 ACE	SP	CRE		V		11/18/2078
2020 PO4586310558	F	4	40 ACE	SP	CRE		V		11/19/2078
2020 PO4591010667	F	4	40 ACE	SP	CCA		V		11/20/2078
2020 PO4556710919	F	4	40 ACE	SP	CRE		V		11/21/2078
2020 PO4572310865	F	4	40 ACE	SP	CRE		V		11/22/2078
2020 PO4602610411	F	4	40 ACE	SP	CRE		V		11/23/2078
2020 PO4596110343	F	4	40 ACE	SP	CRE		V		11/24/2078
2020 PO4617810543	F	4	40 ACE	SP	CRE		V		11/25/2078
2020 PO4610610492	F	4	40 ACE	SP	CRE		V		11/26/2078
2020 PO4613210615	F	4	40 ACE	SP	CRE		V		11/27/2078
2020 PO4604710714	F	4	40 ACE	SP	CRE		V		11/28/2078
2020 PO4600110745	F	4	40 ACE	SP	CRE		V		11/29/2078
2020 PO7451983340	KU	3	55 BRN	SP	CCA		V		11/30/2078
2020 PO7448783493	F	5	35 BRN	SP	CRE		V		12/1/2078
2020 PO7425783018	KU	5	35 BRN	SP	CCA		V		12/2/2078
2020 PO7434883126	KU	5	35 BRN	SP	CCA		V		12/3/2078
2020 PO7441283250	KU	5	35 BRN	SP	CCA		V		12/4/2078
2020 PO7458983373	KU	4	40 BRN	SP	CRE	ED,ID	TD		12/5/2078
2020 PO7445683455	KU	2	70 BRN	SP	CRE	RB	BX	RP2	12/6/2078
2020 PO7470983086	KU	4	40 BRN	SP	CRE	ED,ID	BD		12/7/2078
2020 PO7454881852	KU	4	45 BRN	SP	CRE	ED,ID	BD		12/8/2078
2020 PO7462381703	KU	4	40 BRN	SP	CRE	ED,ID	TD		12/9/2078
2020 PO3218537981	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD		12/10/2078
2020 PO3214737947	KU	4	40 BRN	SP	CRE	ID	BD		12/11/2078
2020 PO3210937913	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD		12/12/2078
2020 PO4841732009	KU	3	45 BRO	SP	CRE	ID	BD		12/13/2078
2020 PO4741531128	KU	6	30 BRO	SP	CRE	ID,IP	BD		12/14/2078
2020 PO3526641794	KU	3	40 ACE	SP	CCA		V		12/15/2078
2020 PO6959694538	KU	6	30 BRN	SP	CRE	ED,ID	TD		12/16/2078
2020 PO6952094392	KU	4	40 BRN	SP	CRE	ED,ID	TD		12/17/2078
2020 PO3544541694	KU	4	40 ACE	SP	CCA		V		12/18/2078
2020 PO4750331114	KU	6	30 BRO	SP	CRE	ID,IP	TD		12/19/2078

2020 PO4768431146	KU	5	35 BRO	SP	P		V		12/20/2078
2020 PO4747131017	KU	6	30 BRO	SP	CRE	ID	BD		12/21/2078
2020 PO3579441498	KU	4	40 ACE	SP	CCA		V		12/22/2078
2020 PO4752331004	KU	2	40 BRO	SP	CRE	ID,IP	BD		12/23/2078
2020 PO4752231016	KU	2	40 BRO	SP	CRE	ED,HH,ID	X	RP2	12/24/2078
2020 PO7462081562	KU	4	45 BRN	SP	CCA		V		12/25/2078
2020 PO7458281492	KU	4	45 BRN	SP	CCA		V		12/26/2078
2020 PO7462583241	F	4	40 BRN	SP	CRE		V		12/27/2078
2020 PO7458583222	KU	4	45 BRN	SP	CCA		V		12/28/2078
2020 PO7474882935	KU	4	45 BRN	SP	CRE	ED,ID	TD		12/29/2078
2020 PO5055006839	KU	6	30 XXX	SP	CRE	ED,ID	TD		12/30/2078
2020 PO5054006760	KU	4	40 XXX	SP	CRE	ED,ID	TD		12/31/2078
2020 PO5066906809	KU	4	40 XXX	SP	CRE	ED,EP,ID	TX	RR	1/1/2079
2020 PO4640400679	KU	4	40 BRO	SP	CRE	ID	TD		1/2/2079
2020 PO4658200192	KU	4	40 BRO	SP	CRE	ID	TD		1/3/2079
2020 PO4632100869	KU	6	30 KOP	SP	CCA		V		1/4/2079
2020 PO6538669745	KU	4	40 BRN	SP	CCA		V		1/5/2079
2020 PO6551069597	KU	6	30 BRN	SP	CCA		V		1/6/2079
2020 PO6541369886	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		1/7/2079
2020 PO6556769849	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD		1/8/2079
2020 PO8196971152	KU	2	70 BRO	SP	CRE		V		1/9/2079
2020 PO8211570892	KU	2	65 BRO	SP	CRE		V		1/10/2079
2020 PO8221170266	F	4	40 BRO	SP	P		V		1/11/2079
2020 PO8233770132	F	4	40 BRO	SP	CRE		V		1/12/2079
2020 PO8399268805	KU	2	65 BRO	SP	CRE		V		1/13/2079
2020 PO8384268952	KU	2	65 BRO	ST	CRE		V		1/14/2079
2020 PO6528670100	KU	4	40 BRN	SP	CRE	ED,ID	TD		1/15/2079
2020 PO4747904727	KU	5	30 XXX	SP	CRE	ED,ID	TD		1/16/2079
2020 PO4753904696	KU	5	30 XXX	SP	CRE	ED,ID	TD		1/17/2079
2020 PO8359666896	KU	4	40 BRO	SP	CRE	ED,ID	BD		1/18/2079
2020 PO6576171308	KU	6	30 BRN	SP	CRE	ED,ID	TD		1/19/2079
2020 PO6566571339	KU	4	40 BRN	SP	CRE	ED,ID	TD		1/20/2079
2020 PO6561271322	F	6	30 BRN	SP	CRE		V		1/21/2079
2020 PO6566671711	KU	6	30 BRN	SP	CRE	ED,ID	TD		1/22/2079
2020 PO6580371665	KU	4	40 BRN	SP	CRE	ED,ID	TD		1/23/2079
2020 PO4682600030	KU	5	35 BRO	SP	CRE	ID	TD		1/24/2079
2020 PO4666600335	KU	6	30 BRO	SP	CRE	ID	TD		1/25/2079
2020 PO4651100376	KU	4	40 BRO	SP	CRE	ID	TD		1/26/2079
2020 PO4639400314	KU	6	30 BRO	SP	CRE	ID	TD		1/27/2079
2020 PO4634600220	KU	4	40 BRO	SP	CRE	ID	TD		1/28/2079
2020 PO4630200451	KU	4	30 BRO	SP	CRE	ID	TD		1/29/2079
2020 PO4639500448	KU	6	30 BRO	SP	CRE	ID	TD		1/30/2079
2020 PO4626000200	KU	6	30 BRO	SP	CCA	ID	TD		1/31/2079
2020 PO4666900770	KU	6	30 BRO	SP	CRE	ID	TD		2/1/2079
2020 PO4993006005	KU	4	40 XXX	SP	CRE	ED,ID	TD		2/2/2079
2020 PO5000906032	KU	4	40 XXX	SP	CRE	ED,ID,IP	TX	RR	2/3/2079
2020 PO5000806020	KU	4	40 XXX	SP	P	ED,ID	TD		2/4/2079

2020 PO5016505994	KU	4	40 XXX	SP	CRE	ED,ID	TX	RR	2/5/2079
2020 5009806162A	KU	4	35 XXX	SP	CRE	ED,ID	TD		2/6/2079
2020 PO4998105963	KU	4	40 XXX	SP	CRE	ID	BD		2/7/2079
2020 PO4604802994	KU	5	35 UNK	SP	CRE	ED,EP,IP,SRC	X	PX	2/8/2079
2020 PO5009806162	KU	4	40 XXX	SP	CRE	ED,ID	TD		2/9/2079
2020 PO5021106196	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD		2/10/2079
2020 PO5038206255	KU	4	40 XXX	SP	CRE	ED,ID	TD		2/11/2079
2020 PO5021405860	KU	5	35 XXX	SP	CRE	ED,ID	TD		2/12/2079
2020 PO5024405803	KU	4	40 XXX	SP	CRE	ED,ID	TD		2/13/2079
2020 PO5000805838	KU	6	30 BRN	SP	CCA		V		2/14/2079
2020 PO5045205901	KU	6	30 XXX	SP	CRE	ED,ID	TD		2/15/2079
2020 PO6562772371	KU	4	40 BRN	SP	CRE	ED,ID	TD		2/16/2079
2020 PO6637572007	KU	4	40 BRN	SP	CCA		V		2/17/2079
2020 PO6592772163	KU	4	40 BRN	SP	CRE	ED,ID	TD		2/18/2079
2020 PO6573372188	KU	4	40 BRN	SP	CRE	ED,ID	TD		2/19/2079
2020 PO6553072203	KU	3	45 BRN	SP	CCA		V		2/20/2079
2020 PO6593471958	KU	4	40 BRN	SP	CRE	ED,ID	BD		2/21/2079
2020 PO6601972408	KU	5	35 BRN	SP	CRE	ED,ID	BD		2/22/2079
2020 PO4765305574	KU	6	30 BRN	SP	CCA		V		2/23/2079
2020 PO4776005513	KU	6	30 KOP	SP	CRE	ED,ID	TD		2/24/2079
2020 PO4772005432	KU	4	40 ACW	SP	CRE	ED,ID	TD		2/25/2079
2020 PO8330267374	KU	6	35 BRO	SP	CRE	ED,ID	TD		2/26/2079
2020 PO8359867526	KU	4	40 BRO	SP	CRE	ED,ID	BD		2/27/2079
2020 PO8299466878A	KU	5	35 BRO	SP	S		V		2/28/2079
2020 PO8124069401	KU	4	45 BRO	SP	CRE	ED,ID	BD		3/1/2079
2020 PO4775605157	KU	4	40 XXX	SP	CRE	ED,ID	TD		3/2/2079
2020 PO6558272593	KU	4	40 BRN	SP	CRE	ED,ID	BD		3/3/2079
2020 PO6562172830	KU	5	35 BRN	SP	CRE	ED,ID	BD		3/4/2079
2020 PO6508372233	KU	4	40 BRN	SP	CRE	ED,ID	TD		3/5/2079
2020 PO4640300965	KU	4	40 BRO	SP	CRE	ID	TD		3/6/2079
2020 PO4611901065	KU	6	30 BRO	SP	CRE	ID	TD		3/7/2079
2020 PO4617701124	KU	4	40 BRO	SP	CRE	ID	TD		3/8/2079
2020 PO4608801253	KU	4	40 BRO	SP	CRE	ID	TD		3/9/2079
2020 PO4611801350	KU	6	30 BRO	SP	CRE	ID	TD		3/10/2079
2020 PO4599501330	KU	4	40 BRO	SP	CRE	ID	TD		3/11/2079
2020 PO4586601284	KU	4	40 BRO	SP	CRE	ID	TD		3/12/2079
2020 PO4597300745	KU	4	40 BRO	SP	CCA		V		3/13/2079
2020 PO4596300644	KU	6	30 BRO	SP	CRE	ID	TD		3/14/2079
2020 PO4593701177	KU	4	40 BRO	SP	CRE	ID	BD		3/15/2079
2020 PO4579401168	KU	6	30 BRO	SP	CCA		V		3/16/2079
2020 PO4582401125	KU	6	30 BRO	SP	CCA		V		3/17/2079
2020 PO4598501069	KU	6	30 BRO	SP	CRE	ID	TD		3/18/2079
2020 PO4581901057	KU	6	30 BRO	SP	CRE		V		3/19/2079
2020 PO4488901178	F	4	40 BRO	SP	CRE		V		3/20/2079
2020 4785605319a	KU	5	30 XXX	SP	CRE	ED,ID	TD		3/21/2079
2020 PO4771905066	KU	6	30 XXX	SP	CRE	ED,ID	TD		3/22/2079
2020 PO4785605273	KU	6	30 XXX	SP	CRE	ED,ID	TD		3/23/2079

2020 PO4785605319	KU	2	50 XXX	SP	CRE	ED,ID	TD		3/24/2079
2020 PO6611372654-A	KU	4	35 BRN	SP	CRE	ED,ID	BD		3/25/2079
2020 PO6624672605	KU	6	30 BRN	SP	CRE	ED,HH,ID	BX	PX	3/26/2079
2020 PO6628172685	KU	6	30 BRN	SP	CRE	ED,ID	TD		3/27/2079
2020 PO6611372654	KU	4	40 BRN	SP	CRE	ED,ID	BD		3/28/2079
2020 PO6590272777	KU	6	30 BRN	SP	CRE	ED,ID	TD		3/29/2079
2020 PO6581772762	KU	4	40 BRN	SP	CRE	ED,ID	BD		3/30/2079
2020 PO8423968529	KU	2	75 BRO	SP	A		V		3/31/2079
2020 PO8423768373	KU	6	30 BRO	SP	CRE	ED,ID	BD		4/1/2079
2020 PO8436168378	KU	2	70 BRO	SP	CRE		V		4/2/2079
2020 PO8429266557	KU	4	40 BRO	SP	CRE	ED,ID	TD		4/3/2079
2020 PO8486766460	KU	3	45 BRO	SP	CCA		V		4/4/2079
2020 PO8451967452	KU	4	40 BRO	SP	CRE	ED,ID	BD		4/5/2079
2020 PO2022892438	KU	5	35 BRO	SP	CCA		V		4/6/2079
2020 PO9718697325	KU	3	50 BRO	SP	CRE	ED,ID	BD		4/7/2079
2020 PO9701097133	KU	3	50 BRO	SP	CRE	ED,ID	TD		4/8/2079
2020 PO9685396959	KU	3	50 BRO	SP	CRE	ED,ID	TD		4/9/2079
2020 PO9667096756	KU	3	50 BRO	SP	CRE	ED,ID	TD		4/10/2079
2020 PO9646596805	KU	3	50 BRO	SP	CRE	ED,ID	TD		4/11/2079
2020 PO9623396876	KU	3	50 BRO	SP	CRE	ED,ID	TD		4/12/2079
2020 PO9600596937	KU	3	50 BRO	SP	CRE	ED,ID	TD		4/13/2079
2020 PO9579396997	KU	3	50 BRO	SP	CRE	ED,ID	TD		4/14/2079
2020 PO1971292175	KU	4	40 BRO	SP	CRE	ID	BD		4/15/2079
2020 PO2133589944	KU	5	35 BRO	SP	CRE	ED,ID,SRC	TD		4/16/2079
2020 PO2196889552	KU	4	40 BRO	SP	CRE		V		4/17/2079
2020 PO2173890101	KU	4	40 BRO	SP	CRE	ED,ID,IP, SRC	TD		4/18/2079
2020 PO2208989244	KU	5	35 BRO	SP	CRE		V		4/19/2079
2020 PO2221688933	KU	4	40 BRO	SP	CRE		V		4/20/2079
2020 PO2201589000	KU	4	40 BRO	SP	CRE		V		4/21/2079
2020 PO9189581995	KU	4	40 OTH	SP	CRE	ID,IP	BD		4/22/2079
2020 PO9284382817	KU	4	40 OTH	SP	CRE	ID,IP	BD		4/23/2079
2020 PO9276282882	KU	4	40 OTH	SP	CRE	ID,IP	BD		4/24/2079
2020 PO9137181475	KU	4	45 OTH	SP	P	ED	T		4/25/2079
2020 PO9144881559	KU	4	45 OTH	SP	CRE	ED,ID,IP	TD		4/26/2079
2020 PO9156981679	KU	5	35 OTH	SP	CRE	ED,ID,IP	TD		4/27/2079
2020 PO9176181861	KU	4	40 OTH	SP	CRE	ED,ID,IP	TD		4/28/2079
2020 PO9176681480	KU	5	35 OTH	SP	CRE	ID,IP	BD		4/29/2079
2020 PO9169781416	KU	3	45 OTH	SP	CRE	ED,ID,IP	TD		4/30/2079
2020 PO9219982302	KU	4	40 OTH	SP	CRE	ED,ID,IP	TD		5/1/2079
2020 PO9231182432	KU	5	35 OTH	SP	CRE	ID,IP	BD		5/2/2079
2020 PO9209382583	KU	4	40 OTH	SP	CRE	ID	BD		5/3/2079
2020 PO9190882716	KU	4	40 OTH	SP	CCA		V		5/4/2079
2020 PO9264083000	KU	6	30 OTH	AL	CRE		V		5/5/2079
2020 PO9151381318	KU	3	45 OTH	SP	CRE		V		5/6/2079
2020 PO9224981021	F	4	40 OTH	SP	CRE		V		5/7/2079
2020 PO9231181105	F	4	40 OTH	SP	CRE		V		5/8/2079
2020 PO9219580949	F	4	40 OTH	SP	CRE		V		5/9/2079

2020 PO9200581210	F	3	45 OTH	SP	CRE		V		5/10/2079
2020 PO9192481169	F	3	45 OTH	SP	CRE	HH,ID,RB	VX	RP1	5/11/2079
2020 PO9185481096	F	3	45 OTH	SP	CRE		V		5/12/2079
2020 PO9100280124	F	4	40 OTH	SP	A		V		5/13/2079
2020 PO9145479976	F	4	40 OTH	SP	A		V		5/14/2079
2020 PO9152079945	F	4	40 OTH	SP	A		V		5/15/2079
2020 PO9179279959	F	4	40 OTH	SP	CRE		V		5/16/2079
2020 PO9194279962	F	4	40 OTH	SP	CCA		V		5/17/2079
2020 PO9227779973	F	4	40 OTH	SP	CCA		V		5/18/2079
2020 PO9258979990	KU	4	40 OTH	SP	A	ID,IP	BD		5/19/2079
2020 PO9271579993	KU	3	45 OTH	SP	CRE	ID,IP	BD		5/20/2079
2020 PO9271980061	KU	4	40 OTH	SP	CRE	HH,RB	X	RP1	5/21/2079
2020 PO7130388420	KU	2	60 BRN	SP	CRE	ED,ID	BD		5/22/2079
2020 PO7135788328	KU	3	55 BRN	SP	A	ED,ID	BD		5/23/2079
2020 PO7142788204	KU	2	50 BRN	SP	A	ED,ID	BD		5/24/2079
2020 PO7142788204-A	KU	3	50 BRN	SP	CCA		V		5/25/2079
2020 PO7758677514	KU	2	70 BRO	SP	CRE		V		5/26/2079
2020 PO5133797755	KU	4	45 BRN	SP	CRE	ID	TD		5/27/2079
2020 PO7559979869	KU	4	40 BRN	SP	CRE	ED,EP,ID,RB	TX	RR	5/28/2079
2020 PO7589478913	KU	4	40 BRN	SP	CRE		V		5/29/2079
2020 PO7576978987	KU	H4	65 BRN	SP	CRE		V		5/30/2079
2020 PO7570279108	KU	4	40 BRN	SP	CRE	ED,ID	TD		5/31/2079
2020 PO7564779205	KU	1	35 BRN	SP	CRE	ED,ID	TD		6/1/2079
2020 PO6658884203	KU	6	30 BRN	SP	CRE	ED,ID	TD		6/2/2079
2020 PO6639383738	KU	5	35 BRN	SP	CCA		V		6/3/2079
2020 PO6658684133	KU	4	40 BRN	SP	CCA		V		6/4/2079
2020 PO6398182665	KU	4	45 BRN	SP	CRE	ED,ID	TD		6/5/2079
2020 PO6663883594	KU	4	40 BRN	SP	CCA		V		6/6/2079
2020 PO6647383477	KU	5	35 BRN	SP	CCA		V		6/7/2079
2020 PO6717382787	KU	5	35 BRN	SP	CCA		V		6/8/2079
2020 PO6676383303	KU	5	35 BRN	SP	CCA		V		6/9/2079
2020 PO6699383036	KU	5	35 BRN	SP	CCA		V		6/10/2079
2020 PO7736777771	KU	2	70 BRO	SP	CRE		V		6/11/2079
2020 PO7713978053	KU	1	75 BRO	SP	CCA		V		6/12/2079
2020 PO7696078268	KU	1	75 BRO	SP	CRE		V		6/13/2079
2020 PO7900175270	KU	5	35 BRO	SP	CRE		V		6/14/2079
2020 PO7149387648	KU	3	45 BRN	SP	CRE	ED,ID	BD		6/15/2079
2020 PO7167187774	KU	3	50 BRN	SP	CCA		V		6/16/2079
2020 PO7168287755	KU	3	45 BRN	SP	CCA		V		6/17/2079
2020 PO7179987663	KU	5	35 BRN	SP	CRE	ED,ID	BD		6/18/2079
2020 PO7188887799	F	3	45 BRN	SP	P		V		6/19/2079
2020 PO7180187779	KU	4	45 BRN	SP	CRE	ED,ID	TD		6/20/2079
2020 PO7639378760	KU	2	70 BRO	SP	CRE		V		6/21/2079
2020 PO7638378742	KU	2	70 BRO	SP	CRE		V		6/22/2079
2020 PO7661678519A	KU	2	60 BRO	ST	CRE		V		6/23/2079
2020 PO7661678599	KU	2	60 BRO	ST	CRE		V		6/24/2079
2020 PO7650978665	KU	2	45 BRO	ST	CRE		V		6/25/2079

2020 PO7652178680	KU	2	45 BRO	ST	CCA		V	6/26/2079	
2020 PO7819275485	KU	4	40 BRO	SP	CRE		B	6/27/2079	
2020 PO6372781754	KU	4	45 BRN	SP	CRE	ED,ID	TD	6/28/2079	
2020 PO6364981479	KU	4	45 BRN	SP	CRE	ED,ID	TD	6/29/2079	
2020 PO6353581222	KU	4	45 BRN	SP	CRE	ED,ID	TD	6/30/2079	
2020 PO4890105498	KU	4	40 BRN	SP	CRE	ED,ID	TD	7/1/2079	
2020 PO4915305399	KU	4	40 BRN	SP	CRE	ED,ID	TD	7/2/2079	
2020 PO4924805301	KU	4	40 XXX	SP	CRE	ED,ID	TD	7/3/2079	
2020 PO7969372747	KU	4	45 BRO	SP	CRE	ID	BD	7/4/2079	
2020 PO7973272761	KU	4	45 BRO	SP	CCA		V	7/5/2079	
2020 PO8017073194	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/6/2079	
2020 PO8020973120	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/7/2079	
2020 PO8024173060	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/8/2079	
2020 PO8027972989	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/9/2079	
2020 PO8017672820	KU	4	40 BRO	SP	CRE		V	7/10/2079	
2020 PO8021172906	KU	6	30 BRO	SP	CCA		V	7/11/2079	
2020 PO8021272796	KU	4	40 BRO	SP	CRE	ID	TD	7/12/2079	
2020 PO8008072723	KU	4	40 BRO	SP	CRE	ID	BD	7/13/2079	
2020 PO7829475514	KU	4	40 BRO	SP	CRE		B	7/14/2079	
2020 PO7833175576	KU	4	40 BRO	SP	CRE		V	7/15/2079	
2020 PO7851075688	KU	4	40 BRO	SP	CRE		B	7/16/2079	
2020 PO7456185336	KU	4	45 BRN	SP	CCA		V	7/17/2079	
2020 PO7437485415	KU	4	45 BRN	SP	CCA		V	7/18/2079	
2020 PO7432885322	KU	4	45 BRN	SP	CCA		V	7/19/2079	
2020 PO7416085199	KU	5	35 BRN	SP	CCA		V	7/20/2079	
2020 PO7434485219	KU	5	35 BRN	SP	CCA		V	7/21/2079	
2020 PO7428585193	KU	4	45 BRN	SP	CCA		V	7/22/2079	
2020 PO7486485162	KU	4	45 BRN	SP	CCA		V	7/23/2079	
2020 PO7474585198	KU	4	45 BRN	SP	CCA		V	7/24/2079	
2020 PO7462185199	KU	4	45 BRN	SP	CCA		V	7/25/2079	
2020 PO7467485021	KU	4	45 BRN	SP	CCA		V	7/26/2079	
2020 PO7464784923	KU	4	45 BRN	SP	CCA		V	7/27/2079	
2020 PO7456584818	KU	4	45 BRN	SP	CCA		V	7/28/2079	
2020 PO7449184727	KU	4	45 BRN	SP	CCA		V	7/29/2079	
2020 PO7001488076	KU	6	30 BRN	SP	CRE	ED,ID	BX	PX	7/30/2079
2020 PO8006673036	KU	6	30 BRO	SP	CCA		V	7/31/2079	
2020 PO8013272999	KU	5	35 BRO	SP	CRE	ID	BD	8/1/2079	
2020 PO8008472976	F	5	35 BRO	SP	A		V	8/2/2079	
2020 PO8001772942	F	5	35 BRO	SP	A		V	8/3/2079	
2020 PO6334780987	KU	4	45 BRN	SP	CRE	ED,ID	TD	8/4/2079	
2020 PO5155198132	KU	4	40 BRN	SP	CRE	ID	TD	8/5/2079	
2020 PO5146697811	KU	4	40 BRN	SP	CRE	ID	TD	8/6/2079	
2020 PO5143097731	KU	3	45 BRN	SP	CRE	ID	TD	8/7/2079	
2020 PO5158697778	KU	5	35 BRN	SP	CRE	ID	TD	8/8/2079	
2020 PO5163197980	KU	5	35 BRN	SP	CRE	ID	TD	8/9/2079	
2020 PO0928765304	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/10/2079	
2020 PO0929065338	KU	3	40 BRO	SP	CCA		V	8/11/2079	

2020 PO0918365358	KU	3	40 BRO	SP	CCA		V	8/12/2079
2020 PO0940265320	KU	3	40 BRO	SP	CCA		V	8/13/2079
2020 PO0921365314	F	4	40 BRO	SP	A		V	8/14/2079
2020 PO0962665296	KU	3	45 BRO	SP	P	ED	T	8/15/2079
2020 PO0987965287	KU	3	50 BRO	SP	CCA		V	8/16/2079
2020 PO2988165326	KU	3	50 BRO	SP	CCA		V	8/17/2079
2020 PO0988165476	KU	3	50 BRO	SP	CCA		V	8/18/2079
2020 PO0988765650	KU	3	50 BRO	SP	P	ED	T	8/19/2079
2020 PO0198352688	KU	4	40 BRO	SP	CRE	ED,EP,ID,IP,RB	X	8/20/2079
2020 PO0989465825	KU	3	50 BRO	SP	CCA		V	8/21/2079
2020 PO0990366064	KU	3	50 BRO	SP	CCA		V	8/22/2079
2020 PO1000166412	KU	3	50 BRO	SP	CCA		V	8/23/2079
2020 PO1000166412-A	KU	3	50 BRO	SP	CCA		V	8/24/2079
2020 PO1888146540	KU	4	35 BRN	SP	P	ID,IP	TD	8/25/2079
2020 PO0525561215	F	5	35 ACW	SP	CRE		V	8/26/2079
2020 PO0520461238	F	5	35 ACW	SP	CRE	ED,ID	V	8/27/2079
2020 PO9819451819	KU	4	40 BRO	SP	CRE	ID	BD	8/28/2079
2020 PO9843452405	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD	8/29/2079
2020 PO9853852417	KU	4	45 BRO	SP	CCA		V	8/30/2079
2020 PO9852452325	F	4	40 BRO	SP	CRE		V	8/31/2079
2020 PO0010252510	KU	3	45 BRO	SP	CCA		V	9/1/2079
2020 PO0516060853	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	9/2/2079
2020 PO0036452409	KU	3	45 BRO	SP	P	ED	T	9/3/2079
2020 PO1862444716	F	6	30 BRN	SP	P		V	9/4/2079
2020 PO0987166445	KU	3	50 BRO	SP	CCA		V	9/5/2079
2020 PO0966966497	KU	3	50 BRO	SP	CCA		V	9/6/2079
2020 POD160552785	KU	4	40 BRO	SP	CRE	ID	BD	9/7/2079
2020 PO9126462724	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	9/8/2079
2020 PO0155152888	KU	6	30 BRO	SP	CRE	ED,ID,SRC	TD	9/9/2079
2020 PO0155352801	KU	4	40 BRO	SP	CCA		V	9/10/2079
2020 POD130852870	KU	5	35 BRO	SP	CRE		V	9/11/2079
2020 PO9181762496	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	9/12/2079
2020 PO0099852957	KU	2	50 BRO	SP	CCA		V	9/13/2079
2020 PO0078652631	KU	4	45 BRO	SP	CCA		V	9/14/2079
2020 PO0092352877	KU	2	50 BRO	SP	CCA		V	9/15/2079
2020 PO0072553183	KU	4	40 BRO	SP	CRE	ID	BD	9/16/2079
2020 PO0524850950	KU	4	40 BRO	SP	CRE	ED,ID,IP,SRC	TD	9/17/2079
2020 PO9625960843	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	9/18/2079
2020 PO0456553025	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD	9/19/2079
2020 PO9670260862	KU	4	40 ACW	SP	P	ED	T	9/20/2079
2020 PO9698061241	KU	4	40 ACW	SP	CCA		V	9/21/2079
2020 PO9722061567	KU	4	40 ACW	SP	P	ED	T	9/22/2079
2020 PO049451093	KU	2	30 BRO	SP	CRE	ED,ID,SRC	TD	9/23/2079
2020 PO7101390053	KU	4	45 BRN	SP	CCA		V	9/24/2079
2020 PO7100590018	KU	3	45 BRN	SP	CRE	ED,ID	TD	9/25/2079
2020 PO7089989892	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/26/2079
2020 PO7081889773	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/27/2079

2020 PO7079389736	KU	4	40 BRN	SP	CRE	ED,ID	BD		9/28/2079
2020 PO5468406715	KU	4	45 XXX	SP	CRE	RB	X	RP1	9/29/2079
2020 PO5445706755	KU	4	40 XXX	SP	CRE	ED,ID	TD		9/30/2079
2020 PO5430406725	KU	4	40 XXX	SP	CRE	ED,ID	TD		10/1/2079
2020 PO5411206692	KU	4	40 XXX	SP	CRE	ED,ID	TD		10/2/2079
2020 PO5400106666	KU	4	50 XXX	SP	CRE	RB	X	RP1	10/3/2079
2020 PO7452594695	KU	5	30 BRO	SP	P	ID	VX	RP1	10/4/2079
2020 PO7485894928	KU	5	35 BRO	SP	CCA	ED	VX	RP1	10/5/2079
2020 PO7518795099	KU	5	35 BRO	SP	CCA		V		10/6/2079
2020 PO7541295156	KU	4	40 BRO	SP	CRE	ED,ID	TD		10/7/2079
2020 PO7458594212	KU	3	45 BRO	SP	CRE	ID	BD		10/8/2079
2020 PO7476494352	KU	4	40 BRO	SP	CRE	ED,ID	TD		10/9/2079
2020 PO7059489291	KU	4	45 BRN	SP	CRE	ED,ID	TD		10/10/2079
2020 PO7069989336	KU	5	35 BRN	SP	CCA		B		10/11/2079
2020 PO7481894393	KU	4	45 BRO	SP	CCA		B		10/12/2079
2020 PO7489994459	KU	3	45 BRO	SP	CRE	ED,ID	TD		10/13/2079
2020 PO7498494527	KU	4	40 BRO	SP	CRE	ID	BD		10/14/2079
2020 PO0262257000	KU	5	35 BRO	SP	CRE	HH,ID,IP,RB	BX	PX	10/15/2079
2020 PO7033290451	F	3	45 BRN	SP	CRE	ED,HH,ID,IP	VX	PX	10/16/2079
2020 PO7045494254	KU	4	40 BRN	SP	CRE	ED,ID	TD		10/17/2079
2020 PO7037594173	KU	4	40 BRN	SP	CRE	ED,ID	TD		10/18/2079
2020 PO7577977219	KU	5	35 BRO	SP	CRE		V		10/19/2079
2020 PO0763274593	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		10/20/2079
2020 PO0420657333	KU	5	35 ACW	SP	CRE	ED,ID,IP	BD		10/21/2079
2020 PO1186760493	KU	2	50 BRN	SP	CRE	ID	BD		10/22/2079
2020 PO1180160767	KU	2	50 BRN	SP	CRE	ID	BD		10/23/2079
2020 PO1150861288	KU	2	50 BRN	SP	CRE	ID	BD		10/24/2079
2020 PO0393657979	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		10/25/2079
2020 PO0793574445	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		10/26/2079
2020 PO0425857309	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		10/27/2079
2020 PO0428657377	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		10/28/2079
2020 PO9677357323	KU	2	40 BRN	SP	CRE	ED,ID,SRC	TD		10/29/2079
2020 PO9700457684	KU	4	40 BRN	SP	CRE	ED,ID	X	RP3	10/30/2079
2020 PO9725458074	KU	4	40 BRN	SP	CRE	ID	BD		10/31/2079
2020 PO9960054951	KU	5	35 BRN	SP	CRE	ID	BD		11/1/2079
2020 PO9647156436	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD		11/2/2079
2020 PO9625856527	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD		11/3/2079
2020 PO9602556166	KU	4	40 BRN	SP	CRE	ED,ID,SRS	TD		11/4/2079
2020 PO0862077557	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		11/5/2079
2020 PO0881877398	KU	5	35 BRN	SP	CRE	ED	TD		11/6/2079
2020 PO0909977293	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		11/7/2079
2020 PO1930866055	KU	4	40 BRO	DF	CRE	ID,IP	TD		11/8/2079
2020 PO1905265974	KU	4	40 BRO	SP	CRE	ID,IP	BX	RP1	11/9/2079
2020 PO0875877199	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD		11/10/2079
2020 PO0434457515	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		11/11/2079
2020 PO0440657662	KU	4	40 ACW	SP	CRE	ED,ID	TD		11/12/2079
2020 PO0446157798	KU	4	40 ACW	SP	CRE	ED,EP,HH,ID,IP,RB	X	RP1	11/13/2079

2020 PO0453158026	KU	4	40 ACW	SP	CRE	ED,ID	TD		11/14/2079
2020 PO0457458160	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		11/15/2079
2020 PO7296290777	KU	5	35 BRO	SP	CRE	HH,ID,RB	VX	PX	11/16/2079
2020 PO5279807218	KU	6	30 XXX	SP	CRE	ED,ID	TD		11/17/2079
2020 PO6279504410	F	5	40 XXX	SP	CRE	RB	BX	RP1	11/18/2079
2020 PO5267407047	KU	4	40 XXX	SP	CRE	ED,ID	TD		11/19/2079
2020 PO5257407169	KU	4	45 BRN	SP	CRE	ID	BD		11/20/2079
2020 PO5265007198	KU	4	40 XXX	SP	CRE	ED,ID	TD		11/21/2079
2020 PO5367608591	KU	3	55 BRO	SP	CCA		V		11/22/2079
2020 PO5373608635	KU	5	35 BRO	SP	CRE	ID	TD		11/23/2079
2020 PO5379808691	KU	5	30 BRO	SP	CCA	ED	T		11/24/2079
2020 PO5365008742	KU	6	30 BRO	SP	CRE	ID	TD		11/25/2079
2020 PO5355208751	KU	4	45 BRO	SP	CRE	ID	TD		11/26/2079
2020 PO5351108799	F	4	40 BRO	SP	A		V		11/27/2079
2020 PO5348508780	KU	6	30 BRO	SP	CCA	ED	T		11/28/2079
2020 PO5343508821	KU	6	30 BRO	SP	CCA		V		11/29/2079
2020 PO5345808884	KU	4	40 BRO	SP	CRE	ID	BD		11/30/2079
2020 PO5346108670	KU	5	35 BRO	SP	CRE	ID	TD		12/1/2079
2020 PO5342708540	KU	4	40 BRO	SP	CRE	ID	TD		12/2/2079
2020 PO5338508577	KU	4	40 BRO	SP	CRE	ID	TD		12/3/2079
2020 PO5332708633	KU	4	40 BRO	SP	CCA		V		12/4/2079
2020 PO5337608471	KU	5	35 BRO	SP	CRE	ID	TD		12/5/2079
2020 PO5334808486a	KU	4	40 BRO	SP	CRE	ID	TD		12/6/2079
2020 PO5334808486	F	7	25E BRO	SP	CRE		V		12/7/2079
2020 PO5329908424	KU	5	35 BRO	SP	CRE	ID	TD		12/8/2079
2020 PO5327408339	F	4	40 BRO	SP	CRE		V		12/9/2079
2020 PO5318508303a	KU	6	30 BRO	SP	CCA		V		12/10/2079
2020 PO5318508303	KU	5	35 BRO	SP	CRE	ID	TD		12/11/2079
2020 PO5356308332	KU	6	30 BRO	SP	CRE	ED,ID	TD		12/12/2079
2020 PO7594581828	F	4	40 BRN	SP	CRE		V		12/13/2079
2020 PO7612881855	KU	4	40 BRN	SP	CRE	ED,ID	TD		12/14/2079
2020 PO7510081316	F	3	45 BRN	SP	CCA		V		12/15/2079
2020 PO7554582088	KU	4	45 BRN	SP	CRE	ED,ID	BD		12/16/2079
2020 PO7531181985	KU	4	40 BRN	SP	CRE	ED,ID	TD		12/17/2079
2020 5257407169A	KU	6	30 XXX	SP	CRE	ED,ID	TD		12/18/2079
2020 PO5253607304	KU	6	30 XXX	SP	CRE	ED,ID	TD		12/19/2079
2020 PO8100474524	KU	5	35 BRO	SP	CRE	ED,ID	TD		12/20/2079
2020 PO8090374662	KU	4	40 BRO	SP	CRE	ID	BD		12/21/2079
2020 PO8075874933	KU	4	45 BRO	SP	CRE	ID	BD		12/22/2079
2020 PO0982273878	KU	3	50 BRO	SP	CRE	ED,ID,IP	TD		12/23/2079
2020 PO0735959268	F	4	40 ACW	SP	CRE	ED,EP,HH,ID,IP,RB	VX	RP1	12/24/2079
2020 PO1933058390	KU	5	45 BRN	SP	CRE	HH,ID,RB	X	RP1	12/25/2079
2020 PO1005773819	KU	3	50 BRO	SP	CRE	ED,ID,IP	TD		12/26/2079
2020 PO0981873145	KU	3	50 BRO	SP	CRE	ED,ID,IP	TD		12/27/2079
2020 PO0922771669	KU	3	50 BRO	SP	CCA		V		12/28/2079
2020 PO0930571900	KU	3	50 BRO	SP	CRE	ED,ID,IP	TD		12/29/2079
2020 PO0940072200	KU	3	50 BRO	SP	CRE	ED,ID,IP	TD		12/30/2079

2020 PO0980173774	KU	4	40 BRO	SP	CRE	ID,IP	BD		12/31/2079
2020 PO0732359197	F	4	40 ACW	SP	CRE	ED,EP,HH,ID,IP,RB	VX	PX	1/1/2080
2020 PO0729359139	F	4	40 ACW	SP	CRE	ED,ID	V		1/2/2080
2020 PO0217452465	F	4	40 BRO	SP	CRE		V		1/3/2080
2020 PO0203752157	KU	2	50 BRO	SP	CRE	ED,ID,IP,SRS	TD		1/4/2080
2020 PO0723459229	F	4	40 ACW	ST	CRE	ED,EP,HH,ID,IP,RB	VX	PX	1/5/2080
2020 PO2001258035	KU	4	45 BRN	SP	P	ED	TD		1/6/2080
2020 PO0709159281	F	4	40 ACW	SP	CRE		V		1/7/2080
2020 PO1970358195	KU	6	35 BRN	SP	CRE	ID,IP	TD		1/8/2080
2020 PO6278304521	KU	5	30 XXX	SP	CRE	ED,ID,RB	X	RP1	1/9/2080
2020 PO6289804453	KU	6	30 XXX	SP	CRE	ED,ID	TD		1/10/2080
2020 PO6283804361	F	4	40 ACW	SP	CRE		V		1/11/2080
2020 PO6283304442	KU	6	30 ACW	SP	CRE	ED,ID	TD		1/12/2080
2020 PO6269604647	KU	6	30 ACW	SP	CRE	ED,ID	TD		1/13/2080
2020 PO6266204706	KU	6	30 ACW	SP	CRE	ED,ID	TD		1/14/2080
2020 PO6287804604	F	6	30 ACW	SP	CRE		V		1/15/2080
2020 PO6280404596	F	4	40 XXX	SP	CRE		V		1/16/2080
2020 PO6281204698	F	4	40 BRN	SP	CRE		V		1/17/2080
2020 PO4155735020	KU	5	30 BRO	SP	CRE	ED,ID,IP	TD		1/18/2080
2020 PO5864811168	KU	6	30 BRO	SP	CRE	ID	TD		1/19/2080
2020 PO5869110882	KU	6	30 BRO	SP	CRE	ID	TD		1/20/2080
2020 PO5848010772	KU	6	30 BRO	SP	CCA		V		1/21/2080
2020 PO5838310717	KU	6	30 BRO	SP	CRE	ID	TD		1/22/2080
2020 PO5816110397	KU	4	40 BRO	SP	CRE	ID	TD		1/23/2080
2020 PO5819810422	KU	5	35 BRO	SP	CRE	ID	TD		1/24/2080
2020 PO0692759340	F	4	40 ACW	SP	CRE		V		1/25/2080
2020 PO8221626245	KU	5	35 UNK	SP	CRE	ED,ID	TD		1/26/2080
2020 PO0697759445	F	4	40 ACW	SP	CRE	ED,ID,IP	V		1/27/2080
2020 PO0702759564	F	4	40 ACW	SP	CRE	ED,ID	V		1/28/2080
2020 PO0707959677	F	4	40 ACW	SP	CRE		V		1/29/2080
2020 PO0711659763	F	4	40 ACW	SP	CRE	ED,ID,IP	V		1/30/2080
2020 PO0209052278	KU	4	45 BRO	SP	CRE	HH,ID,IP,RB	X	PX	1/31/2080
2020 PO0199352055	KU	5	45 BRO	SP	CRE	ID	BD		2/1/2080
2020 PO0187851794	KU	4	40 BRO	SP	CRE		V		2/2/2080
2020 PO0224351433	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD		2/3/2080
2020 PO2029657960	KU	4	40 BRN	SP	CRE	ED	TD		2/4/2080
2020 PO2061257975	KU	3	45 BRN	SP	CCA		V		2/5/2080
2020 PO0682359755	F	4	40 ACW	SP	CRE	ED,ID	V		2/6/2080
2020 PO2080657644	KU	6	30 BRN	SP	CRE	ID	TD		2/7/2080
2020 PO0763559227	F	4	40 ACW	SP	CRE		V		2/8/2080
2020 PO2066557751	KU	4	40 BRN	SP	CRE	ID	TD		2/9/2080
2020 PO2088257812	KU	3	45 BRN	SP	CCA		V		2/10/2080
2020 PO8232926464	KU	4	40 UNK	SP	CCA		V		2/11/2080
2020 PO8278425903	F	4	40 UNK	SP	P		B		2/12/2080
2020 PO8191626144	KU	5	35 ACW	SP	CRE	ID	TD		2/13/2080
2020 PO8262925930	KU	4	45 UNK	SP	CCA		V		2/14/2080
2020 PO8202726078	KU	5	35 UNK	SP	CRE	ID	TD		2/15/2080

2020 PO8261026397	KU	4	40 UNK	SP	CRE	ID	TD	2/16/2080	
2020 PO4353033722	KU	3	45 BRO	SP	CRE	ID,IP	BD	2/17/2080	
2020 PO4361133824	KU	3	45 BRO	SP	CRE	ID,IP	TD	2/18/2080	
2020 PO7322489693	KU	6	35 BRO	SP	S		V	2/19/2080	
2020 PO7206689317	KU	5	35 BRO	SP	CRE	ID	BD	2/20/2080	
2020 PO7214089363	KU	4	40 BRO	SP	CCA		V	2/21/2080	
2020 PO7232889408	KU	4	40 BRO	SP	CRE	ED,ID	TD	2/22/2080	
2020 PO7227689324	KU	4	40 BRO	SP	CRE	ED,ID	TD	2/23/2080	
2020 PO2706442519	KU	5	35 BRN	SP	CRE	ED,ID,IP,MD,SR	TD	2/24/2080	
2020 PO2688542628	KU	5	35 BRN	SP	CRE	ED,ID,IP,MD,SR	TD	2/25/2080	
2020 PO2663042786	KU	5	35 BRN	SP	CCA		V	2/26/2080	
2020 PO0672059501	F	4	40 ACW	SP	CRE		V	2/27/2080	
2020 PO0677159629	F	4	40 ACW	SP	CRE		V	2/28/2080	
2020 PO0687459880	F	4	40 ACW	SP	CRE		V	2/29/2080	
2020 PO2175657577	KU	5	30 BRN	SP	CRE	ID	BD	3/1/2080	
2020 PO0976273506	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	3/2/2080	
2020 PO0997373575	KU	3	50 BRO	SP	CRE	ED,ID,IP	TD	3/3/2080	
2020 PO0989073346	KU	3	50 BRO	SP	CRE	ED,ID,IP	TD	3/4/2080	
2020 PO2226657472	KU	4	40 BRN	SP	CRE	ID	TD	3/5/2080	
2020 PO2253057860	KU	5	40 BRN	SP	CRE	ID,IP	TD	3/6/2080	
2020 PO2275758135	KU	4	40 BRN	SP	P	ED	TD	3/7/2080	
2020 PO0184751721	F	4	40 BRO	SP	CRE		V	3/8/2080	
2020 PO0183051682	KU	5	35 BRO	SP	CRE		V	3/9/2080	
2020 PO0183651556	KU	6	30 BRO	SP	CRE	ID	BD	3/10/2080	
2020 PO0219151279	KU	4	40 BRO	SP	CRE	ED,ID,IP,RB	X	PX	3/11/2080
2020 PO0233751617	KU	4	40 BRO	SP	CRE		T	3/12/2080	
2020 PO0238651112	KU	4	40 BRO	SP	CRE	ID	BD	3/13/2080	
2020 PO0245951424	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD	3/14/2080	
2020 PO0249051539	KU	4	40 BRO	SP	CRE	ID	BD	3/15/2080	
2020 PO9561161132	F	9	20 ACW	SP	CRE		V	3/16/2080	
2020 PO2362358112	KU	4	40 BRN	SP	CRE	ID	TD	3/17/2080	
2020 PO2358158209	F	6	30E BRN	SP	CRE		V	3/18/2080	
2020 PO2349258217	KU	4	40 BRN	SP	CRE	ID	TD	3/19/2080	
2020 PO2337758299	KU	4	35 BRN	SP	CRE	ED,ID,IP	TD	3/20/2080	
2020 PO2337558819	KU	2	50 BRN	SP	CCA		V	3/21/2080	
2020 PO2343858775	KU	3	45 BRN	SP	CCA		V	3/22/2080	
2020 PO2364458660	KU	3	45 BRN	SP	CCA		V	3/23/2080	
2020 PO2373158611	KU	5	30 BRN	SP	CRE	ID	TD	3/24/2080	
2020 PO2379358455	KU	6	30 BRN	SP	CRE	ID	TD	3/25/2080	
2020 PO2390058515	KU	3	45 BRN	SP	CCA		V	3/26/2080	
2020 PO2404658436	KU	3	45 BRN	SP	CCA		V	3/27/2080	
2020 PO2411258458	KU	4	40 BRN	SP	CRE		V	3/28/2080	
2020 PO2440358233	KU	4	40 BRN	SP	CRE	ID	TD	3/29/2080	
2020 PO2412758391	KU	4	40 BRN	SP	CRE	ID	BD	3/30/2080	
2020 PO2456158148	KU	5	35 BRN	SP	CRE	HH,RB	X	RP1	3/31/2080
2020 PO9586660984	F	4	40 ACW	SP	CCA		V	4/1/2080	
2020 PO9659460718	F	4	40 ACW	SP	CRE		V	4/2/2080	

2020 PO6268312874	KU	4	40 BRO	SP	CCA		V	4/3/2080	
2020 PO8249125987	KU	5	35 UNK	SP	CRE		V	4/4/2080	
2020 8787823790A	KU	6	30 OTH	SP	CRE	ID	TD	4/5/2080	
2020 PO8821824030	F	5	35 UNK	SP	P		B	4/6/2080	
2020 PO8703424266	F	5	35 UNK	SP	CCA		V	4/7/2080	
2020 PO8843124054	KU	5	35 UNK	SP	CRE	ED,ID,SRS	TD	4/8/2080	
2020 PO8818624065	KU	4	40 UNK	SP	CCA		V	4/9/2080	
2020 PO8724623602	KU	4	40 UNK	SP	CRE	ID	TD	4/10/2080	
2020 PO8691124298	KU	5	35 UNK	SP	CRE	ED,ID,SRC	TX	RR	4/11/2080
2020 PO8820924241	KU	4	45 UNK	SP	CRE	ID	TD	4/12/2080	
2020 PO8695924244	KU	4	40 INP	SP	CRE	ID	TD	4/13/2080	
2020 PO8806724367	KU	4	40 BRN	SP	CCA		V	4/14/2080	
2020 PO9634560701	KU	4	40 ACW	SP	CRE		V	4/15/2080	
2020 PO8825823989	KU	3	50 KOP	SP	CRE	ED,ID,SRS	TD	4/16/2080	
2020 PO9623960317	KU	4	40 ACW	SP	CRE		V	4/17/2080	
2020 PO9616359997	KU	4	40 ACW	SP	CRE		V	4/18/2080	
2020 PO2522927710	ODP	4	40 BRN	SP	CRE	ID	TD	4/19/2080	
2020 PO2563327815	ODP	4	40 BRN	SP	CRE	ID	TD	4/20/2080	
2020 PO2578327861	ODP	3	35 BRN	SP	CRE		V	4/21/2080	
2020 PO2588427872	ODP	4	40 BRN	SP	CCA		V	4/22/2080	
2020 PO2348628289	ODP	4	40 BRN	SP	CRE	ID	TD	4/23/2080	
2020 PO3955682395	LGE	4	40 BRN	SP	CRE	ED,ID	TD	4/24/2080	
2020 PO4541731707	KU	3	45 ACE	SP	CRE	ED,ID	BD	4/25/2080	
2020 PO0205833705	ODP	4	40 BRN	SP	CRE	ED,ID	TD	4/26/2080	
2020 PO0211333740	ODP	6	30 XXX	SP	CRE	ED,ID	TD	4/27/2080	
2020 PO0383829200	F	4	40 XXX	SP	A		V	4/28/2080	
2020 PO0383829264	F	6	30 XXX	SP	A		B	4/29/2080	
2020 PO3667546785	F	4	40 BRO	SP	CCA		V	4/30/2080	
2020 PO4554431850	KU	6	30 ACE	SP	CCA		V	5/1/2080	
2020 PO3649546798	KU	4	40 BRO	SP	CRE	ID,IP	BD	5/2/2080	
2020 PO4560531940	KU	6	30 ACE	SP	CRE	ED,ID	BD	5/3/2080	
2020 PO3619147310	KU	4	40 BRO	SP	CRE	ID,IP	BD	5/4/2080	
2020 PO4565332005	KU	6	30 ACE	SP	CRE	ED,ID	BD	5/5/2080	
2020 PO3613447665	KU	5	35 BRO	SP	P		T	5/6/2080	
2020 PO3743446143	F	4	40 BRO	SP	CCA		V	5/7/2080	
2020 PO3954782380	LGE	4	40 BRN	SP	CCA		V	5/8/2080	
2020 PO3954782280	LGE	4	40 BRN	SP	CRE	ED,ID	TD	5/9/2080	
2020 PO3954282376	LGE	4	40 BRN	SP	CRE	ED,ID	TD	5/10/2080	
2020 PO1164921050A	ODP	3	45 BRN	SP	CCA		V	5/11/2080	
2020 PO1179820868	ODP	4	40 KOP	SP	CRE	ID	TD	5/12/2080	
2020 PO0477429883	ODP	5	30 XXX	SP	CRE		V	5/13/2080	
2020 PO0448729814	ODP	5	30 XXX	SP	CRE		V	5/14/2080	
2020 PO0402629698	ODP	4	45 XXX	SP	CCA		V	5/15/2080	
2020 PO0398030041	ODP	4	45 XXX	SP	CCA		V	5/16/2080	
2020 PO0384530088	ODP	5	30 XXX	SP	CRE	ED,ID	TD	5/17/2080	
2020 PO0395530253	ODP	5	35 BRN	SP	CRE	ED,ID	TD	5/18/2080	
2020 PO0386630395	ODP	6	30 BRN	SP	CRE	ED,ID	TD	5/19/2080	

2020 PO0376530562	ODP	6	30 BRN	SP	CRE		ED,ID	TD	5/20/2080
2020 PO0381230715	ODP	5	35 XXX	SP	CRE		ED,ID	TD	5/21/2080
2020 PO0253131770	ODP	4	45 BRN	SP	CCA			V	5/22/2080
2020 PO0326331722	ODP	6	30 BRN	SP	CCA		ED	T	5/23/2080
2020 PO0343531716	ODP	4	40 BRN	SP	CCA			V	5/24/2080
2020 PO4550531690	KU	6	30 ACE	SP	CCA			V	5/25/2080
2020 PO4563431623	KU	6	30 ACE	SP	CCA			V	5/26/2080
2020 PO4344140000	KU	2	55 BRO	SP	CCA			V	5/27/2080
2020 PO4342739981	KU	2	55 BRO	SP	CCA			V	5/28/2080
2020 PO4333040099	KU	2	55 BRO	SP	CCA			V	5/29/2080
2020 PO4549939178	KU	4	40 BRO	SP	CRE		ID,IP	BD	5/30/2080
2020 PO2364428000	ODP	4	40 BRN	SP	CRE		ID	TD	5/31/2080
2020 PO2379927793	ODP	5	35 BRN	SP	CRE		ID	TD	6/1/2080
2020 PO4043282562	LGE	4	40 BRN	SP	CRE		ED,ID	TD	6/2/2080
2020 PO4044182570	LGE	4	40 BRN	SP	CRE		ED,ID	TD	6/3/2080
2020 PO4525339133	KU	4	40 BRO	SP	CCA			V	6/4/2080
2020 PO4517038951	KU	5	35 BRO	SP	CCA			V	6/5/2080
2020 PO4415242464	KU	6	30 BRO	SP	CCA			V	6/6/2080
2020 PO4397042216	KU	6	30 BRO	SP	CCA			V	6/7/2080
2020 PO4397842381	KU	6	30 BRO	SP	CCA			V	6/8/2080
2020 PO3306149236	F	4	40 BRO	SP	CRE			V	6/9/2080
2020 PO3317049165	F	4	40 BRO	SP	CRE			V	6/10/2080
2020 PO3329549083	F	4	40 BRO	SP	CRE			V	6/11/2080
2020 PO3336649036	F	4	40 BRO	SP	CRE			V	6/12/2080
2020 PO3349148953	F	4	40 BRO	SP	CRE			V	6/13/2080
2020 PO3378348940	F	4	40 BRO	SP	CRE			V	6/14/2080
2020 PO3369948814	F	4	40 BRO	SP	CRE			V	6/15/2080
2020 PO3388748691	F	4	40 BRO	SP	CRE			V	6/16/2080
2020 PO3297849108	KU	6	30 BRO	SP	CRE		ED,ID,IP	TD	6/17/2080
2020 PO3980082250	LGE	4	40 BRN	SP	A		ED,ID	TD	6/18/2080
2020 PO3980082250-A	LGE	3	45 BRN	SP	S			V	6/19/2080
2020 PO0089238047	ODP	4	45 BRN	SP	CCA			V	6/20/2080
2020 PO0074738086	ODP	4	45 BRN	SP	CCA			V	6/21/2080
2020 PO0064638047	ODP	4	45 BRN	SP	CRE			V	6/22/2080
2020 PO0025838093	ODP	4	45 BRN	SP	CCA			V	6/23/2080
2020 PO0006238547	ODP	4	40 BRN	SP	CCA			V	6/24/2080
2020 PO0015237966	ODP	2	55 BRN	SP	CCA			V	6/25/2080
2020 PO0033537939	ODP	2	50 BRN	SP	CCA			V	6/26/2080
2020 PO0052737898	ODP	2	55 BRN	SP	CCA			V	6/27/2080
2020 PO3979082255	LGE	3	45 BRN	SP	CRE		ED,ID	BD	6/28/2080
2020 PO0050037751	ODP	2	55 BRN	SP	CCA			V	6/29/2080
2020 PO0081737599	ODP	2	50 BRN	SP	CCA			V	6/30/2080
2020 PO0113337448	ODP	2	55 BRN	SP	CCA			V	7/1/2080
2020 PO0163337405	ODP	2	55 BRN	SP	CCA			V	7/2/2080
2020 PO0142437549	ODP	2	60 BRN	SP	CCA			V	7/3/2080
2020 PO3981882243	LGE	4	40 BRN	SP	CRE		ED,ID	BD	7/4/2080
2020 PO4687927253	KU	2	45 BRO	SP	CRE			V	7/5/2080

Business Use

2020 PO4683127002	KU	4	40 BRO	SP	CRE		V			7/6/2080
2020 PO4663727011	KU	3	45 BRO	SP	CCA		V			7/7/2080
2020 PO4642826879	KU	4	40 BRO	SP	CCA		V			7/8/2080
2020 PO4619826304	KU	4	40 BRO	SP	CRE	ED,ID	TD			7/9/2080
2020 PO4621026762	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			7/10/2080
2020 PO4529126601	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD			7/11/2080
2020 PO4568026665	KU	3	45 BRO	SP	CCA		V			7/12/2080
2020 PO4929730427	F	3	50 BRO	SP	CCA		V			7/13/2080
2020 PO6018147058	F	4	40 ACE	SP	CRE		V			7/14/2080
2020 PO6018846913	F	4	40 ACE	SP	P		V			7/15/2080
2020 PO9679893946	KU	6	30 ACW	SP	CCA		V			7/16/2080
2020 PO9653593583	KU	3	45 ACW	SP	CCA		V			7/17/2080
2020 PO9651993679	KU	2	50 ACW	SP	CRE		V			7/18/2080
2020 PO9670893942	F	6	35 ACW	SP	S		V			7/19/2080
2020 PO9649694270	KU	4	45 ACW	SP	CRE		V			7/20/2080
2020 PO9657594282	KU	4	45 ACW	SP	CCA		V			7/21/2080
2020 PO2348942579	ODP	4	45 KOP	SP	S		V			7/22/2080
2020 PO2359142749	ODP	4	45 KOP	SP	S		V			7/23/2080
2020 PO2337642413	ODP	4	40 KOP	SP	S		V			7/24/2080
2020 PO2332942468	ODP	4	40 KOP	SP	S		V			7/25/2080
2020 PO2329542549	ODP	6	30 KOP	SP	CRE	ED,EP,ID	TD			7/26/2080
2020 PO2375742522	ODP	6	30 KOP	SP	S		V			7/27/2080
2020 PO2374842607	ODP	4	40 KOP	SP	S		V			7/28/2080
2020 PO2358042614	ODP	4	40 KOP	SP	S		V			7/29/2080
2020 PO2350642481	ODP	5	35 KOP	SP	CRE	ED,ID	TD			7/30/2080
2020 PO2359642434	ODP	6	30 KOP	SP	A	ED,ID	TD			7/31/2080
2020 PO3982682245	LGE	4	30 BRN	SP	A	ED,HH,ID	X	PX		8/1/2080
2020 PO3958830509	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			8/2/2080
2020 PO3948630799	KU	4	40 BRO	SP	P	ED	T			8/3/2080
2020 PO3950430797	KU	4	40 BRO	SP	CCA		V			8/4/2080
2020 PO3948330901	KU	4	40 BRO	SP	CCA		V			8/5/2080
2020 PO3824029084	KU	4	40 BRO	SP	CRE	ID,IP	BD			8/6/2080
2020 PO1231820328	ODP	4	45 BRN	SP	CCA		V			8/7/2080
2020 PO1800923046	ODP	4	40 XXX	SP	CRE	EP,ID,RB	X	RP2		8/8/2080
2020 PO1805422917	ODP	4	45 XXX	SP	A	ID	TD			8/9/2080
2020 PO9662293994	KU	3	45 ACW	SP	CCA		V			8/10/2080
2020 PO9657193972	KU	4	40 ACW	SP	CRE		V			8/11/2080
2020 PO9681093843	KU	5	35 ACW	SP	S		V			8/12/2080
2020 PO9681093843B	KU	6	35 ACW	SP	S		V			8/13/2080
2020 PO9681093843A	KU	6	35 ACW	SP	S		V			8/14/2080
2020 PO9658693884	KU	2	45 ACW	SP	CRE	ED,ID	BD			8/15/2080
2020 PO9658693884B	KU	5	35 ACW	SP	CRE	ED,ID	BD			8/16/2080
2020 PO9666293837	KU	5	35 ACW	SP	CRE	ED,ID	TD			8/17/2080
2020 PO9658693884A	KU	3	40 ACW	SP	S		V			8/18/2080
2020 PO6030546956	F	4	40 ACE	SP	CRE		V			8/19/2080
2020 PO6019546749	F	4	40 ACE	SP	P		V			8/20/2080
2020 PO6047346818	F	4	40 ACE	SP	P		V			8/21/2080

2020 PO6019446668	F	4	40 ACE	SP	P		V			8/22/2080
2020 PO6030446594	F	4	40 ACE	SP	CRE		V			8/23/2080
2020 PO6043546510	F	4	40 ACE	SP	CRE		V			8/24/2080
2020 PO6059746704	F	4	40 ACE	SP	P		V			8/25/2080
2020 PO6056946420	F	4	40 ACE	SP	P		V			8/26/2080
2020 PO1805722765	F	4	40 XXX	SP	CRE		V			8/27/2080
2020 PO1807522591	ODP	6	30 XXX	SP	CRE		V			8/28/2080
2020 PO1810822268	ODP	3	40 XXX	SP	CCA		V			8/29/2080
2020 PO1811222509	ODP	4	40 XXX	SP	CRE	ID			TD	8/30/2080
2020 PO1821122706	ODP	6	30 XXX	SP	CCA		V			8/31/2080
2020 PO1822622632	ODP	4	35 XXX	SP	CRE	ID			TD	9/1/2080
2020 PO1853522871	ODP	5	35 XXX	SP	CRE	ID,IP			TX RR	9/2/2080
2020 PO1841222777	ODP	4	35 XXX	SP	CRE	ID,IP,RB			TX RR	9/3/2080
2020 PO3984682231	LGE	3	40 BRN	SP	A	HH,ID			TD	9/4/2080
2020 PO3983982234	LGE	4	40 BRN	DF	A	ED,ID			BD	9/5/2080
2020 PO3745037472	KU	4	40 BRN	SP	CRE		V			9/6/2080
2020 PO3760237423	KU	4	40 BRN	SP	CRE		V			9/7/2080
2020 PO3771737371	KU	4	40 BRN	SP	CRE		V			9/8/2080
2020 PO3817937179	KU	6	30 BRN	SP	CRE	ED,ID,IP,MD			TD	9/9/2080
2020 PO3984882236	LGE	4	40 BRN	SP	A	ED,ID			TD	9/10/2080
2020 PO3984982240	LGE	4	30 BRN	SP	A	ED,ID			TD	9/11/2080
2020 PO3986382224	LGE	4	40 BRN	SP	A	HH,ID			BD	9/12/2080
2020 PO3986382230	LGE	4	30 BRN	SP	A	ED,ID			TD	9/13/2080
2020 PO4525531492	F	3	40 ACE	SP	CRE		V			9/14/2080
2020 PO4565831291	KU	3	45 ACE	SP	P	ED			T	9/15/2080
2020 PO1218419822	ODP	6	30 INP	SP	CRE	ID			TD	9/16/2080
2020 PO0180337318	ODP	2	50 BRN	SP	CCA		V			9/17/2080
2020 PO0177737204	ODP	2	65 BRN	SP	CCA		V			9/18/2080
2020 PO0253736460	ODP	2	65 BRN	SP	CCA		V			9/19/2080
2020 PO0270636630	ODP	4	45 BRN	SP	CCA		V			9/20/2080
2020 PO3806337226	KU	4	40 BRN	SP	CRE	ED,ID,MD			TD	9/21/2080
2020 PO3829437130	KU	6	30 BRN	SP	P	ED,ID			TD	9/22/2080
2020 PO3840937081	KU	4	40 BRN	SP	CRE	ID			BD	9/23/2080
2020 PO3811337341	F	4	40 BRN	SP	CRE		V			9/24/2080
2020 PO3841235474	KU	4	45 BRN	SP	P		T			9/25/2080
2020 PO3989782232	LGE	4	40 BRN	SP	A	ED,ID			TD	9/26/2080
2020 PO3988382223	LGE	3	45 BRN	SP	S		V			9/27/2080
2020 PO4560830628	KU	3	45 ACE	SP	CRE	ID			BD	9/28/2080
2020 PO5899947896	KU	4	45 ACE	SP	CRE	ED,ID			BD	9/29/2080
2020 PO3624147106	F	4	40 BRO	SP	CRE		V			9/30/2080
2020 PO3640246988	F	4	40 BRO	SP	CRE		V			10/1/2080
2020 PO3654746881	F	4	40 BRO	SP	CRE		V			10/2/2080
2020 PO3706346470	F	4	40 BRO	SP	CRE		V			10/3/2080
2020 PO3717146374	F	4	40 BRO	SP	CRE		V			10/4/2080
2020 PO3730346259	F	4	40 BRO	SP	CRE		V			10/5/2080
2020 PO0680978141	KU	4	40 BRN	SP	CRE	ED,ID,IP			TD	10/6/2080
2020 PO0555678905	KU	4	40 BRN	SP	CRE	ED,ID,IP			TD	10/7/2080

2020 PO0620977633	KU	4	45 BRN	SP	CRE	ED,ID,IP	TD	10/8/2080
2020 PO0647777612	KU	4	45 BRN	SP	CRE	ED,ID,IP	TD	10/9/2080
2020 PO0663577371	KU	4	40 BRN	SP	P	ED	T	10/10/2080
2020 PO0672877726	KU	4	45 BRN	SP	CRE	ED,ID,IP	TD	10/11/2080
2020 PO0666277600	KU	4	45 BRN	SP	CRE	ED	TD	10/12/2080
2020 PO0692377893	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	10/13/2080
2020 PO0679177613	KU	6	30 BRN	SP	P	ED	T	10/14/2080
2020 PO0672877726-A	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	10/15/2080
2020 PO5890747868	KU	3	45 ACE	SP	CRE	ED,ID,IP	TD	10/16/2080
2020 PO5899447744	KU	4	45 ACE	SP	CRE	ED,ID	BD	10/17/2080
2020 PO5841547434a	KU	6	30 ACE	SP	CCA		V	10/18/2080
2020 PO4841331421	KU	4	40 BRO	SP	CRE	ED,ID	TD	10/19/2080
2020 PO5774247353a	KU	6	35 ACE	SP	CRE	ED,ID	TD	10/20/2080
2020 PO5891648373	KU	4	40 ACE	SP	CRE	ED,ID	BD	10/21/2080
2020 PO4809031390	KU	5	35 BRO	SP	CRE	ED,ID	TD	10/22/2080
2020 PO4751031497	C	5	35 BRO	SP	CRE		V	10/23/2080
2020 PO4760331600	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	10/24/2080
2020 PO4816331540	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD	10/25/2080
2020 PO5766446954	KU	4	40 ACE	SP	P		V	10/26/2080
2020 PO5756146479	KU	3	45 ACE	SP	CRE	ED,ID	BD	10/27/2080
2020 PO5768046661	KU	6	30 ACE	SP	CCA		V	10/28/2080
2020 PO3934182643	LGE	4	40 BRO	SP	P	ED,ID	TD	10/29/2080
2020 PO1290729565	KU	2	65 XXX	SP	CRE	ID	BD	10/30/2080
2020 PO1441329546	KU	2	65 XXX	SP	CRE	ID	BD	10/31/2080
2020 PO2232735488	ODP	4	40 BRN	SP	CRE	ID	TD	11/1/2080
2020 PO2242635923	ODP	5	35 SWP	SP	CRE		V	11/2/2080
2020 PO2248036167	ODP	4	40 SWP	SP	CRE	ID	TD	11/3/2080
2020 PO2259436669	ODP	4	40 SWP	SP	CRE	ID	TD	11/4/2080
2020 PO2296636873	ODP	4	40 SWP	SP	CRE	ED,ID	TD	11/5/2080
2020 PO2322036926	F	4	40 SWP	SP	CRE		V	11/6/2080
2020 PO2345537088	ODP	4	40 UNK	SP	CRE	ID	TD	11/7/2080
2020 PO2306637336	ODP	4	40 CAH	SP	CRE	ID	TD	11/8/2080
2020 PO2367937245	ODP	4	40 SWP	SP	CRE	ID	TD	11/9/2080
2020 PO2286537417	F	4	40 SWP	SP	CRE		V	11/10/2080
2020 PO2297137229	F	4	40 SWP	SP	CRE		V	11/11/2080
2020 PO2364835999	ODP	6	30 BRN	SP	CCA		V	11/12/2080
2020 PO2363035865	ODP	5	30 UNK	SP	CRE	ED,ID	TD	11/13/2080
2020 PO2432035961	ODP	6	30 UNK	SP	CRE	ID	TD	11/14/2080
2020 PO2432935855	F	4	40 UNK	SP	CRE		V	11/15/2080
2020 PO2458235944	F	6	30 UNK	SP	CRE		V	11/16/2080
2020 PO2466735501	ODP	4	40 UNK	SP	CRE	ED,ID	TD	11/17/2080
2020 PO2460435617	ODP	4	45 UNK	SP	CRE	ED,ID,SRC	TD	11/18/2080
2020 PO2465135833	ODP	5	35 UNK	SP	CRE	ID	TD	11/19/2080
2020 PO2497435907	ODP	4	40 UNK	SP	CRE	ED,ID	TD	11/20/2080
2020 PO2555036368	ODP	4	40 CAH	SP	CRE	ID	BD	11/21/2080
2020 PO2569136501	ODP	4	40 BRN	SP	CRE	ID	TD	11/22/2080
2020 PO2590436589	ODP	4	40 KOP	SP	CRE	ID	TD	11/23/2080

2020 PO1627130231	KU	2	75 XXX	SP	CRE	ID	BD	11/24/2080
2020 PO1716630541	KU	2	75 XXX	SP	CRE	ID	BD	11/25/2080
2020 PO1718630495	KU	2	75 XXX	SP	CRE	ID	BD	11/26/2080
2020 PO1628730186	KU	2	75 XXX	SP	CRE	ID	BD	11/27/2080
2020 PO1822130956A	KU	2	60 XXX	SP	CRE	ID	BD	11/28/2080
2020 PO1822130956	KU	2	60 XXX	SP	CRE	ID	BD	11/29/2080
2020 PO1820030914	KU	2	60 XXX	SP	CRE	ID	BD	11/30/2080
2020 PO3958982402	F	4	40 BRN	SP	CRE		V	12/1/2080
2020 PO3959582415	F	4	40 BRN	SP	CRE		V	12/2/2080
2020 PO3960182429	F	4	40 BRN	SP	CRE		V	12/3/2080
2020 PO3960782442	F	4	40 BRN	SP	CRE		V	12/4/2080
2020 PO4083383275	LGE	4	40 BRN	SP	CRE	ED,ID	TD	12/5/2080
2020 PO4083983277	LGE	3	45 BRN	SP	CCA		V	12/6/2080
2020 PO4080383273	LGE	7	30 BRN	SP	CRE	ED,ID	TD	12/7/2080
2020 PO4079983263	LGE	4	40 BRN	SP	CCA		V	12/8/2080
2020 PO4079783270	LGE	4	40 BRN	SP	A	ED,ID	TD	12/9/2080
2020 PO4079183272	LGE	4	30 BRN	SP	CRE	ED,ID	TD	12/10/2080
2020 PO3960982409	LGE	4	35 BRN	SP	A	ED,ID	BD	12/11/2080
2020 PO3932082764	F	4	40 BRO	SP	CCA		V	12/12/2080
2020 PO3932582774	F	4	40 BRO	SP	CRE		V	12/13/2080
2020 PO3933182786	F	4	40 BRO	SP	CRE		V	12/14/2080
2020 PO3937082669	LGE	3	45 BRO	SP	CRE	ED,ID	TD	12/15/2080
2020 PO3962382404	LGE	4	35 BRN	SP	A	ED,ID	BD	12/16/2080
2020 PO3963682398	LGE	4	35 BRN	SP	A	ED,ID	TD	12/17/2080
2020 PO4079383285	LGE	4	40 BRN	SP	A	ED,ID	TD	12/18/2080
2020 PO4079283298	LGE	4	40 BRN	SP	CRE	ED,ID	TD	12/19/2080
2020 PO4079183312	LGE	4	40 BRN	SP	CRE	ED,ID	TD	12/20/2080
2020 PO4082283286	LGE	4	30 BRN	SP	CCA		V	12/21/2080
2020 PO4082883287	LGE	4	35 BRN	SP	CCA		V	12/22/2080
2020 PO4081583315	LGE	4	40 BRN	SP	CCA		V	12/23/2080
2020 PO4082183302	LGE	4	40 BRN	SP	CCA		V	12/24/2080
2020 PO4081683327	LGE	7	25 BRN	SP	CRE	ED,ID	BD	12/25/2080
2020 PO4081183325	LGE	4	40 BRN	SP	CRE	ED,ID	BD	12/26/2080
2020 PO4080683344	LGE	7	25 BRN	SP	CRE	ED,ID	BD	12/27/2080
2020 PO5825847509	F	2	50 ACE	SP	CRE		V	12/28/2080
2020 PO5841547434	F	3	40 ACE	SP	P		V	12/29/2080
2020 PO5854847212	F	3	40 ACE	SP	CRE		V	12/30/2080
2020 PO5858847012	F	3	40 ACE	SP	CCA		V	12/31/2080
2020 PO9500494460	F	5	40 ACW	SP	P		V	1/1/2081
2020 PO9504094358	F	5	35 ACW	SP	CRE		V	1/2/2081
2020 PO5837046741	KU	2	45 ACE	SP	CRE	ED,ID,IP	BD	1/3/2081
2020 PO4523228494	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	1/4/2081
2020 PO4350028116	KU	4	40 BRO	SP	CRE	ED,ID	TD	1/5/2081
2020 PO4383128147	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD	1/6/2081
2020 PO4415728211	KU	4	40 BRO	SP	CCA		V	1/7/2081
2020 PO5824246700	KU	2	45 ACE	SP	CRE	ED,ID	BD	1/8/2081
2020 PO5757547439	KU	6	30 ACE	SP	CRE	ED,ID	TD	1/9/2081

2020 PO5738047227	KU	6	30 ACE	SP	CRE	ED,ID	TD		1/10/2081
2020 PO9489494448	C	5	35 ACW	SP	CRE		V		1/11/2081
2020 PO9491594425	C	4	40 ACW	SP	CRE		V		1/12/2081
2020 PO9466594279	KU	5	30 ACW	SP	CRE	ED,ID	TD		1/13/2081
2020 PO9516117859	KU	4	40 BRN	SP	CCA		V		1/14/2081
2020 PO9224618673	KU	5	35 BRN	SP	CRE	ID	TD		1/15/2081
2020 PO9507417968	KU	5	35 BRN	SP	CRE	ID	TD		1/16/2081
2020 PO3166850140	F	4	40 BRO	SP	A		V		1/17/2081
2020 PO3183450029	F	4	40 BRO	SP	CRE		V		1/18/2081
2020 PO2873052265	KU	4	45 BRO	SP	CRE		V		1/19/2081
2020 PO1235761663	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD		1/20/2081
2020 PO1222761493	KU	4	40 BRN	SP	CRE	ID	BD		1/21/2081
2020 PO1114262659	KU	3	50 BRN	SP	CRE	ED,ID,SRC	TD		1/22/2081
2020 PO1105662700	KU	3	50 BRN	SP	CRE	ED,ID,SRS	TD		1/23/2081
2020 PO1126762864	KU	4	40 BRN	SP	CRE	ID	BD		1/24/2081
2020 PO1142163108	KU	3	45 BRN	SP	P	ED	T		1/25/2081
2020 PO1095962751	KU	3	50 BRN	SP	CRE	ID	BD		1/26/2081
2020 PO1074862853	KU	3	50 BRN	SP	CCA		V		1/27/2081
2020 PO1059762959	KU	4	40 BRN	SP	CCA		V		1/28/2081
2020 PO1024263093	KU	5	35 BRN	SP	CCA		V		1/29/2081
2020 PO1052962952	KU	5	30 BRN	SP	CCA		V		1/30/2081
2020 PO0472649504	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		1/31/2081
2020 PO4707588435	LGE	4	40 BRN	SP	CRE	ED,ID	BX	RR	2/1/2081
2020 PO9462694242	C	4	40 ACW	SP	CRE		V		2/2/2081
2020 PO4708788419	LGE	3	45 BRN	SP	CCA		V		2/3/2081
2020 PO4659788868	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		2/4/2081
2020 PO4659088879	LGE	4	40 BRO	SP	A	ID	BD		2/5/2081
2020 PO4660388859	LGE	3	45 BRO	SP	P	ED	T		2/6/2081
2020 PO4661188866	LGE	4	35 BRO	SP	P	ED	T		2/7/2081
2020 6145914512	KU	6	30 XXX	SP	CRE	ED,ID,IP	TD		2/8/2081
2020 PO4700988439	LGE	4	35 BRN	SP	CCA		V		2/9/2081
2020 PO4702088443	LGE	4	35 BRN	SP	CCA		V		2/10/2081
2020 PO4702688441	LGE	4	40 BRN	SP	A	ED,ID,SRS	TX	RR	2/11/2081
2020 PO4703588429	LGE	4	40 BRN	SP	A	ED,ID	BD		2/12/2081
2020 PO6120714197	KU	4	40 XXX	SP	CRE	ID	BD		2/13/2081
2020 PO6103214182	KU	4	40 XXX	SP	CRE	ED,ID	TD		2/14/2081
2020 PO6082513819	KU	5	40 XXX	SP	CRE	ID,RB	BX	PX	2/15/2081
2020 PO6073813733	KU	6	30 XXX	SP	CRE	ID	BD		2/16/2081
2020 PO4729788335	LGE	4	40 BRO	SP	A	ED,ID	TD		2/17/2081
2020 PO4733088346	LGE	4	40 BRO	SP	CRE		V		2/18/2081
2020 PO9370594837	C	4	40 ACW	SP	CRE		V		2/19/2081
2020 PO9365894826	C	4	40 ACW	SP	CRE		V		2/20/2081
2020 PO9467294319	KU	4	40 ACW	SP	CRE	ED,ID	TD		2/21/2081
2020 PO9461994427	KU	4	40 ACW	SP	CRE	ED,ID	TD		2/22/2081
2020 PO9362794004	KU	6	35 ACW	SP	CRE	ED,ID	TD		2/23/2081
2020 PO4440128243	KU	3	45 BRO	SP	CCA		V		2/24/2081
2020 PO5767447701	KU	6	30 ACE	SP	CRE	ED,ID	BD		2/25/2081

2020 PO4454328261	KU	3	50 BRO	SP	CRE	ID,IP	BD	2/26/2081
2020 PO4479928073	KU	4	40 BRO	SP	CRE	ED,ID	TD	2/27/2081
2020 PO4487128231	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	2/28/2081
2020 PO4458828459	C	4	40 BRO	SP	CRE		V	3/1/2081
2020 PO4464028380	C	4	40 BRO	SP	CRE		V	3/2/2081
2020 PO4471128387	KU	4	40 BRO	SP	CCA	ID	BD	3/3/2081
2020 PO4526628232-A	KU	5	35 BRO	SP	CCA	ED	T	3/4/2081
2020 PO4506328226	KU	3	45 BRO	SP	CCA		V	3/5/2081
2020 PO4526628232	KU	4	40 BRO	SP	CRE	ID,IP	BD	3/6/2081
2020 PO3870083014	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	3/7/2081
2020 PO3947281989	LGE	4	40 BRN	SP	CCA		V	3/8/2081
2020 PO3948681992	LGE	4	40 BRN	SP	CCA		V	3/9/2081
2020 PO3949781989	LGE	3	45 BRN	SP	CCA		V	3/10/2081
2020 PO3949281943	LGE	4	35 BRN	SP	A	ED,ID	TD	3/11/2081
2020 PO3949781942	LGE	4	35 BRN	SP	A	ED,ID	TD	3/12/2081
2020 PO3946081990	LGE	4	35 BRN	SP	A	ED,ID	TD	3/13/2081
2020 PO3950381974	LGE	3	45 BRN	SP	CCA		V	3/14/2081
2020 PO3950181962	LGE	4	35 BRN	SP	A	ED,ID	TD	3/15/2081
2020 PO3949881950	LGE	4	35 BRN	SP	A	ED,ID	TD	3/16/2081
2020 PO3950881987	LGE	4	35 BRN	SP	A	ED,ID	TD	3/17/2081
2020 PO3952081984	LGE	4	35 BRN	SP	CRE	ED,ID	BD	3/18/2081
2020 PO3953281982	LGE	4	35 BRN	SP	A	ED,ID	TD	3/19/2081
2020 PO3955481978	LGE	4	35 BRN	SP	CRE	ED,ID	TD	3/20/2081
2020 PO3954481979	LGE	4	35 BRN	SP	A	ED,ID	TD	3/21/2081
2020 PO3955181971	LGE	4	35 BRN	SP	A	ED,ID	TD	3/22/2081
2020 PO3952681963	LGE	4	35 BRN	SP	CRE	ED,ID	BD	3/23/2081
2020 PO3952481951	LGE	4	35 BRN	SP	CRE	ED,ID	TD	3/24/2081
2020 PO3869883025	LGE	2	65 BRO	SP	CCA		V	3/25/2081
2020 PO3870482990	LGE	4	40 BRO	SP	CRE	ED,ID	BD	3/26/2081
2020 PO3951181892	LGE	4	35 BRN	SP	CRE	ED,ID,MD	TD	3/27/2081
2020 PO3951381899	LGE	4	35 BRN	SP	CRE	ED,ID	BD	3/28/2081
2020 PO3953481880	LGE	4	35 BRN	SP	A	ED,ID	TD	3/29/2081
2020 PO3952881875	LGE	4	35 BRN	SP	A	ED,ID	BD	3/30/2081
2020 PO3953781874	LGE	4	40 BRN	SP	CCA		V	3/31/2081
2020 PO3951481882	LGE	4	35 BRN	SP	CRE	ED,ID	TD	4/1/2081
2020 PO3950881876	LGE	4	40 BRN	SP	CCA		V	4/2/2081
2020 PO3951081863	LGE	4	35 BRN	SP	CRE	ED,ID	BD	4/3/2081
2020 PO3950681853	LGE	4	35 BRN	SP	CRE	ED,ID	TD	4/4/2081
2020 PO3950181844	LGE	4	40 BRN	SP	CRE	ED,ID	TD	4/5/2081
2020 PO3944681871	LGE	4	40 BRN	SP	CRE	ED,ID	TD	4/6/2081
2020 PO3945181879	LGE	4	40 BRN	SP	CCA		V	4/7/2081
2020 PO3948681885	LGE	4	35 BRN	SP	CRE	ED,ID	TD	4/8/2081
2020 PO3945681889	LGE	4	35 BRN	SP	A	ED,ID	TD	4/9/2081
2020 PO4546928092	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	4/10/2081
2020 PO3903782517	F	3	45 BRO	SP	CRE		V	4/11/2081
2020 PO6899316227	KU	4	40 XXX	SP	CRE	ED,ID,IP	TX	RR 4/12/2081
2020 PO4530228636	KU	6	30 BRO	SP	CRE	ID	BD	4/13/2081

2020 PO4527328432	F	5	35 BRO	SP	CCA		V	4/14/2081	
2020 PO4569928594	KU	6	30 BRO	SP	CCA	ED	T	4/15/2081	
2020 PO4545328444	F	4	40 BRO	SP	CRE		V	4/16/2081	
2020 PO4572628462	F	4	40 BRO	SP	CRE		V	4/17/2081	
2020 PO4606728659	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/18/2081	
2020 PO4597828560	KU	4	40 BRO	SP	CCA		V	4/19/2081	
2020 PO4604028479	F	4	40 BRO	SP	CRE		V	4/20/2081	
2020 PO4618428662	KU	4	40 BRO	SP	CCA		V	4/21/2081	
2020 PO4632428493	F	4	40 BRO	SP	CRE		V	4/22/2081	
2020 PO4632928574	F	4	40 BRO	SP	CRE		V	4/23/2081	
2020 PO4644928458	KU	4	40 BRO	SP	CRE	ED,ID	TD	4/24/2081	
2020 PO4686628716	KU	4	40 BRO	SP	CRE		V	4/25/2081	
2020 PO4681728564	KU	5	45 BRO	SP	CRE		V	4/26/2081	
2020 PO3948781893	LGE	4	35 BRN	SP	CRE	ED,ID	TD	4/27/2081	
2020 PO3948281893	LGE	4	40 BRN	SP	CCA		V	4/28/2081	
2020 PO3872582672	LGE	4	40 BRO	SP	P	ED,ID	TD	4/29/2081	
2020 PO3873582668	LGE	4	40 BRO	SP	CCA		V	4/30/2081	
2020 PO1852541203	ODP	3	45 KOP	SP	CRE	ED,ID,MD,SRC	TD	5/1/2081	
2020 18525-41203A	ODP	5	30 KOP	SP	A	ID	BD	5/2/2081	
2020 PO1695640115	ODP	4	40 BRN	SP	CRE	ED,ID,SRS	TD	5/3/2081	
2020 PO1694040419	ODP	2	40 BRN	SP	CRE	ED,ID	TD	5/4/2081	
2020 PO1700740512	F	4	40 BRN	SP	CRE		V	5/5/2081	
2020 PO1707040457	ODP	6	30 BRN	SP	CRE	ID	BD	5/6/2081	
2020 PO1700240591	ODP	4	45 BRN	SP	CCA		V	5/7/2081	
2020 PO1718440574	ODP	4	45 BRN	SP	CCA		V	5/8/2081	
2020 PO1701440742	ODP	2	45 UNK	SP	CRE	ED,ID	TD	5/9/2081	
2020 PO1722740762	ODP	2	40 UNK	SP	CRE	ED,ID	TD	5/10/2081	
2020 PO1717240738	ODP	6	30 UNK	SP	CRE	ED,ID	TD	5/11/2081	
2020 PO1745040726	ODP	6	30 UNK	SP	CRE		V	5/12/2081	
2020 PO1748940788	ODP	5	40 UNK	SP	CRE	ED,ID	TD	5/13/2081	
2020 PO6917116448	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	5/14/2081	
2020 PO4737887495	LGE	4	40 BRO	SP	CRE	ED,ID	BX	PX	5/15/2081
2020 PO5762947671	F	4	40 ACE	SP	CRE		V	5/16/2081	
2020 PO4743887508	LGE	4	40 BRO	SP	CRE	ED,ID	TX	RR	5/17/2081
2020 PO4658388587	LGE	4	35 BRN	SP	CCA		V	5/18/2081	
2020 PO4659988571	F	4	40 BRN	SP	CRE		V	5/19/2081	
2020 PO4662488537	F	4	40 BRN	SP	A		V	5/20/2081	
2020 PO4641988893	LGE	4	40 BRO	SP	P	ED	T	5/21/2081	
2020 PO1445637850	ODP	6	30 BRN	SP	CCA		V	5/22/2081	
2020 PO1435637921	ODP	2	50 BRN	SP	CCA		V	5/23/2081	
2020 PO1439838242	ODP	4	40 UNK	SP	CRE		V	5/24/2081	
2020 PO1456738350	ODP	4	40 UNK	SP	CRE		V	5/25/2081	
2020 PO1467638419	ODP	6	30 UNK	SP	P		V	5/26/2081	
2020 PO1414538362	ODP	5	35 UNK	SP	CRE	ED,ID,SRS	TD	5/27/2081	
2020 PO1414538362A	ODP	6	30 UNK	SP	CCA		V	5/28/2081	
2020 PO1420638173A	ODP	6	30 UNK	SP	P	ED,ID,SRS	TD	5/29/2081	
2020 PO1402438019	ODP	6	30 BRN	SP	CCA		V	5/30/2081	

2020 PO1384537935	ODP	5	35 BRN	SP	CRE	HH,ID,SRC	TD	5/31/2081
2020 PO1378237968	ODP	4	40 BRN	SP	CRE	ED,ID	TD	6/1/2081
2020 PO1388238113	F	4	45 BRN	SP	CRE		V	6/2/2081
2020 PO1380738149	ODP	6	30 BRN	SP	CRE		V	6/3/2081
2020 PO1373937969	ODP	5	35 UNK	SP	CRE	ED,ID	TD	6/4/2081
2020 PO1367938080	ODP	4	40 UNK	SP	CRE	ED,ID	TD	6/5/2081
2020 PO1365237947	ODP	5	35 UNK	SP	CRE	ED,ID	TD	6/6/2081
2020 PO1330538013	ODP	4	45 UNK	SP	CRE	ID	BD	6/7/2081
2020 PO1260039416	ODP	6	30 CAH	SP	CRE	ED,ID	TD	6/8/2081
2020 PO1253839345	ODP	6	30 UNK	SP	CRE	ED,ID,SRS	TD	6/9/2081
2020 PO2445827168	ODP	4	40 BRN	SP	CRE	ID	TD	6/10/2081
2020 PO1098135903	ODP	4	40 XXX	SP	CRE	ED,ID	TD	6/11/2081
2020 PO3911182724	LGE	4	40 BRO	SP	CCA		V	6/12/2081
2020 PO3910682713	LGE	4	40 BRO	SP	CRE	ED,ID	TD	6/13/2081
2020 PO3911882708	LGE	5	25 BRO	SP	CRE	ED,ID	BD	6/14/2081
2020 PO1073935949	ODP	5	35 XXX	SP	CRE		V	6/15/2081
2020 PO1083835964	ODP	5	35 XXX	SP	CCA		V	6/16/2081
2020 PO1087635923	ODP	4	40 XXX	SP	CRE		V	6/17/2081
2020 PO1098436033	ODP	5	35 XXX	SP	CCA		V	6/18/2081
2020 PO3092949953	KU	4	40 BRN	SP	CRE	ED,ID,MD,SRC	TD	6/19/2081
2020 PO3111750187	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/20/2081
2020 PO3002649348	KU	2	45 BRO	SP	CRE	ED,ID,IP	TD	6/21/2081
2020 PO3964282725	LGE	4	40 BRN	SP	CRE	ED,ID	TD	6/22/2081
2020 PO3018049576	KU	4	40 BRN	SP	CRE	ED,ID	TD	6/23/2081
2020 PO3072049685	KU	2	45 BRN	SP	CRE	ED,ID,MD	TD	6/24/2081
2020 PO3049249397	KU	2	60 BRN	SP	CRE	ED,HH,ID,IP,RB	X	PX 6/25/2081
2020 PO3964482719	LGE	4	40 BRN	SP	P	ED,ID	TD	6/26/2081
2020 PO3963182729	F	4	40 BRN	SP	CCA		V	6/27/2081
2020 PO3961982735	F	4	40 BRN	SP	A		V	6/28/2081
2020 PO1280435441	ODP	4	45 BRN	SP	CRE	ED,ID	TD	6/29/2081
2020 PO1270935272	ODP	4	40 BRN	SP	CRE	ID	BD	6/30/2081
2020 PO1265735243	ODP	4	40 BRN	SP	CCA		V	7/1/2081
2020 PO3960782742	F	3	45 BRN	SP	S		V	7/2/2081
2020 PO3959882735	F	3	45 BRN	SP	S		V	7/3/2081
2020 PO3959782748	F	3	45 BRN	SP	A		V	7/4/2081
2020 PO3209251275	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD	7/5/2081
2020 PO3222251158	KU	4	40 BRN	SP	CRE	ED,ID,MD	TD	7/6/2081
2020 PO3212951040	KU	4	40 BRN	SP	CRE	ED,ID,MD	TD	7/7/2081
2020 PO3183050665	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	7/8/2081
2020 PO3160050362	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	7/9/2081
2020 PO3132750392	KU	3	45 BRN	SP	CCA		V	7/10/2081
2020 PO3132950541	KU	3	45 BRN	SP	CRE		V	7/11/2081
2020 PO3059649528	KU	2	55 BRO	SP	CRE	ED,ID,IP	TD	7/12/2081
2020 PO2390126567	ODP	4	40 BRN	SP	CRE	ID	TD	7/13/2081
2020 PO1412637544	ODP	5	35 KOP	SP	S		V	7/14/2081
2020 PO1421537467	ODP	4	40 KOP	SP	CRE	ED,ID,MD,SRC	TD	7/15/2081
2020 PO1412737394	ODP	4	40 KOP	SP	CRE	ED,ID	BD	7/16/2081

2020 PO3959682753	F	3	45 BRN	SP	S		V	7/17/2081
2020 PO3959582753	LGE	3	45 BRN	SP	A		BD	7/18/2081
2020 PO3959082755	F	4	35 BRN	SP	A		V	7/19/2081
2020 PO3911382697	LGE	4	25 BRO	SP	CRE	ED,ID,IP	TD	7/20/2081
2020 PO3910182702	LGE	4	40 BRO	SP	P	ED,ID	TD	7/21/2081
2020 PO3908982694	LGE	4	40 BRO	SP	CCA	ED,ID	BD	7/22/2081
2020 PO3908282682	LGE	4	40 BRO	SP	A	ED,ID	TD	7/23/2081
2020 PO9655394418	KU	3	50 ACW	SP	CRE		V	7/24/2081
2020 PO9655394418B	KU	6	30 ACW	SP	S		V	7/25/2081
2020 PO9655394418	KU	3	40 ACW	SP	S		V	7/26/2081
2020 PO9662894581	KU	5	35 ACW	SP	CRE	ED,ID	BD	7/27/2081
2020 PO9653594528	KU	3	50 ACW	SP	S		V	7/28/2081
2020 PO9654194650	C	4	40 ACW	SP	CRE		V	7/29/2081
2020 PO9645994625	KU	4	45 ACW	SP	CCA		V	7/30/2081
2020 PO9651894638	KU	4	45 ACW	SP	CRE	ED,ID	TD	7/31/2081
2020 PO9650994699	KU	4	40 ACW	SP	CRE	ED,ID	TD	8/1/2081
2020 PO9659194756	KU	6	30 ACW	SP	CRE	ED,ID,IP	TD	8/2/2081
2020 PO9633694770	KU	4	40 ACW	SP	CRE	ED,ID	TD	8/3/2081
2020 PO9633694770	KU	6	35 ACW	SP	CRE	ED,ID	BD	8/4/2081
2020 PO9633494896	KU	6	30 ACW	SP	CRE		V	8/5/2081
2020 PO4735429850	KU	4	40 BRO	SP	CRE		V	8/6/2081
2020 PO4780430904	KU	5	35 BRO	SP	CRE		V	8/7/2081
2020 PO4789931063	KU	4	40 BRO	SP	CRE		V	8/8/2081
2020 PO5751346436	KU	3	45 ACE	SP	CCA		V	8/9/2081
2020 PO5736846499	KU	5	35 ACE	SP	CCA	ED	T	8/10/2081
2020 PO5735346353	KU	4	45 ACE	SP	CCA		V	8/11/2081
2020 PO5748246471	KU	3	45 ACE	SP	CRE		V	8/12/2081
2020 PO5754746533	KU	2	45 ACE	SP	CRE	ED,ID	BD	8/13/2081
2020 PO5751246512	KU	6	30 ACE	SP	CRE	ED,ID	BD	8/14/2081
2020 PO5174134379	KU	3	45 BRO	SP	CCA		V	8/15/2081
2020 PO5167234387	F	4	40 BRO	SP	CRE		V	8/16/2081
2020 PO5141834088	C	4	40 BRO	SP	CRE		V	8/17/2081
2020 PO5141634200	F	4	40 BRO	SP	CRE		V	8/18/2081
2020 PO5165134248	F	4	40 BRO	SP	CRE		V	8/19/2081
2020 PO5171434234	F	4	40 BRO	SP	CRE		V	8/20/2081
2020 PO5156333946	F	3	45 BRO	SP	A		V	8/21/2081
2020 PO5828246546	KU	2	45 ACE	SP	CCA		V	8/22/2081
2020 PO6058948999	KU	3	45 ACE	SP	CCA	ED	T	8/23/2081
2020 PO6057748964	KU	3	45 ACE	SP	CRE		V	8/24/2081
2020 PO5139733334	F	5	40 BRO	SP	A		V	8/25/2081
2020 PO5145133691	F	2	55 BRO	SP	CRE		V	8/26/2081
2020 PO6057748844	KU	6	30 ACE	SP	CCA		V	8/27/2081
2020 PO2394327136	ODP	4	40 BRN	SP	CRE	ID	TD	8/28/2081
2020 PO2416227101	ODP	4	40 BRN	SP	CRE	ID	TD	8/29/2081
2020 Po2409926230a	ODP	6	30 BRN	SP	CCA		V	8/30/2081
2020 PO9564640560	ODP	4	45 BRN	SP	CCA		V	8/31/2081
2020 PO9589540581	ODP	4	45 BRN	SP	CCA		V	9/1/2081

2020 PO9568440966	ODP	4	45 BRN	SP	CCA		V	9/2/2081
2020 PO3956082742	LGE	4	45 BRN	SP	CRE	ED,ID	BD	9/3/2081
2020 PO9560941163	ODP	4	45 BRN	SP	CCA		V	9/4/2081
2020 PO3955682733	LGE	1	95 BRN	SP	CRE		V	9/5/2081
2020 PO9573241064	ODP	4	45 BRN	SP	CCA		V	9/6/2081
2020 PO7348895545	KU	4	40 BRO	SP	CRE		V	9/7/2081
2020 PO4873597783	KU	4	40 BRN	SP	CRE	ID	TD	9/8/2081
2020 PO4849898036	KU	4	30 BRN	SP	CRE	ID	TD	9/9/2081
2020 PO4852498119	KU	6	30 BRN	SP	CRE	ID	TD	9/10/2081
2020 PO4861798247	KU	5	35 BRN	SP	CRE	ID,IP	TD	9/11/2081
2020 PO5218706292	KU	4	40 KOP	SP	CCA		V	9/12/2081
2020 PO5202706262	KU	4	40 KOP	SP	CRE		V	9/13/2081
2020 PO5184106227	KU	4	40 KOP	SP	CCA		V	9/14/2081
2020 PO5172406161	KU	3	40 KOP	SP	CCA		V	9/15/2081
2020 PO5157106079	KU	4	40 KOP	SP	CCA		V	9/16/2081
2020 PO5143905990	KU	4	40 KOP	SP	CCA		V	9/17/2081
2020 PO5130005900	KU	4	35 KOP	SP	CCA		V	9/18/2081
2020 PO5118505827	KU	4	40 KOP	SP	CCA		V	9/19/2081
2020 PO5101005711	KU	4	35 KOP	SP	CCA		V	9/20/2081
2020 PO5090505641	KU	4	40 KOP	SP	CCA		V	9/21/2081
2020 PO5075805549	KU	4	40 KOP	SP	CCA		V	9/22/2081
2020 PO5060305469	KU	4	35 KOP	SP	CCA		V	9/23/2081
2020 PO5042405350	KU	4	40 KOP	SP	CCA		V	9/24/2081
2020 PO7353395390	KU	4	40 BRO	SP	CRE	ID	BD	9/25/2081
2020 PO7320394984	KU	4	40 BRO	SP	CRE	ED,ID	TD	9/26/2081
2020 PO7314095079	KU	4	40 BRO	SP	CRE	ED,ID	TD	9/27/2081
2020 PO7307095279	KU	4	40 BRO	SP	CRE		VX	9/28/2081
2020 PO7339695149	KU	3	50 BRO	SP	CRE	ID	BD	9/29/2081
2020 PO7358695195	KU	4	40 BRO	SP	CRE	ED,ID	TD	9/30/2081
2020 PO5378406999	KU	5	30 XXX	SP	CRE	ED,ID	TD	10/1/2081
2020 PO5383907017	KU	4	45 XXX	SP	CRE	ED,ID	TD	10/2/2081
2020 PO5391406947	KU	6	30 BRN	SP	CCA		V	10/3/2081
2020 PO5408006994	KU	5	30 XXX	SP	CRE	ED,ID	TD	10/4/2081
2020 PO5393407098	KU	4	45 XXX	SP	CRE	ED,ID	TD	10/5/2081
2020 PO5397507328	KU	3	40 BRN	SP	CRE		V	10/6/2081
2020 PO5403407335	KU	4	40 BRN	SP	CRE		V	10/7/2081
2020 PO5406907235	KU	4	45 KOP	SP	CRE	ED,ID	TD	10/8/2081
2020 PO5406507153	KU	6	30 BRN	SP	CRE		V	10/9/2081
2020 PO5411507279	KU	6	30 BRN	SP	CCA		V	10/10/2081
2020 PO7378495245	KU	4	40 BRO	SP	CRE	ID,IP	BX	10/11/2081
2020 PO5035905505	KU	4	40 KOP	SP	CRE		V	10/12/2081
2020 PO5031705277	KU	4	40 XXX	SP	CRE	ED,ID	TD	10/13/2081
2020 PO5016805358	KU	6	30 XXX	SP	CCA		V	10/14/2081
2020 PO7216081012	KU	2	60 BRN	AL	CRE		V	10/15/2081
2020 PO7216881031	KU	2	70 BRN	AL	CRE		V	10/16/2081
2020 PO7188781230	KU	2	65 BRN	AL	CRE		V	10/17/2081
2020 PO7171581367	KU	2	65 BRN	AL	CRE		V	10/18/2081

2020 PO7144581506	KU	2	60 BRN	SP	CCA		V	10/19/2081
2020 PO7118481644	KU	2	60 BRN	SP	CCA		V	10/20/2081
2020 PO7093081777	KU	2	65 BRN	SP	CCA		V	10/21/2081
2020 PO7062281940	KU	1	75 BRN	SP	A		V	10/22/2081
2020 PO7035682079	KU	1	75 BRN	SP	CRE		V	10/23/2081
2020 PO5025405231	KU	4	45 XXX	SP	CCA		V	10/24/2081
2020 PO5005705288	KU	6	30 XXX	SP	CCA		V	10/25/2081
2020 PO5017005173	KU	4	45 XXX	SP	CCA		V	10/26/2081
2020 PO5006105098	KU	4	40 XXX	SP	CRE	ED,ID	TD	10/27/2081
2020 PO7434195381	KU	4	45 BRO	SP	CCA		B	10/28/2081
2020 PO7414695332	KU	4	40 BRO	SP	CRE	ED,ID	TD	10/29/2081
2020 PO7392795280	KU	4	40 BRO	SP	CRE	ID	BD	10/30/2081
2020 PO6939182423	F	6	30 BRN	SP	CRE		V	10/31/2081
2020 PO7453495427	KU	4	45 BRO	SP	CRE	ID	BD	11/1/2081
2020 PO1641375544	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	11/2/2081
2020 PO9946360657	KU	6	30 ACW	SP	CRE	ED,ID	BD	11/3/2081
2020 PO9950760736	KU	4	40 ACW	SP	CCA		V	11/4/2081
2020 PO9963160960	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	11/5/2081
2020 PO0230148909	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD	11/6/2081
2020 PO0454449917	KU	4	40 BRO	SP	CRE	ID	BD	11/7/2081
2020 PO0444949705	KU	4	40 BRO	SP	CRE	ID	BD	11/8/2081
2020 PO9957161290	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	11/9/2081
2020 PO9971261117	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	11/10/2081
2020 PO1658575741	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	11/11/2081
2020 PO0412661109	KU	4	40 ACW	SP	CRE	ID	BD	11/12/2081
2020 PO0426161049	KU	4	40 ACW	SP	CRE	ID	BD	11/13/2081
2020 PO0439561074	KU	5	35 ACW	SP	CCA		V	11/14/2081
2020 PO1849447916	KU	4	40 BRN	SP	CRE	ID	TD	11/15/2081
2020 PO1872547616	KU	4	40 BRN	SP	CRE	ID	TD	11/16/2081
2020 PO0441760980	KU	4	40 ACW	SP	CRE	ED,ID,IP	BD	11/17/2081
2020 PO0453260930	KU	4	40 ACW	SP	CRE	ED,ID	BD	11/18/2081
2020 PO0452360995	KU	6	30 ACW	SP	CCA		V	11/19/2081
2020 PO0038762073	KU	4	40 ACW	SP	CCA		V	11/20/2081
2020 PO1813347366	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	11/21/2081
2020 PO0910263777	KU	4	50 BRO	SP	CRE	ED,ID,IP	TD	11/22/2081
2020 PO0893364043	KU	2	50 BRO	SP	CRE	ED,ID,IP	TD	11/23/2081
2020 PO1833047663	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	11/24/2081
2020 PO0472360971	KU	6	30 ACW	SP	CRE	ED,ID	TD	11/25/2081
2020 PO1792247030	KU	4	35 BRN	SP	CRE	ED,ID,IP	TD	11/26/2081
2020 PO1770446704	KU	4	35 BRN	SP	CRE	ED,IP	TD	11/27/2081
2020 PO5365408415	KU	4	40 BRO	SP	CRE	ID	TD	11/28/2081
2020 7618782149-B	KU	5	35 BRN	SP	P	ED,ID	BD	11/29/2081
2020 7618782149-A	KU	5	35 BRN	SP	P	ED,ID	BD	11/30/2081
2020 PO7618782149	KU	4	45 BRN	SP	CRE	ED,ID	TD	12/1/2081
2020 7622081939	KU	5	35 BRN	SP	CRE	ED,ID	TD	12/2/2081
2020 PO7612781999	KU	5	35 BRN	SP	CRE	ED,ID	TD	12/3/2081
2020 PO7622081939	KU	4	45 BRN	SP	CRE	ED,ID	TD	12/4/2081

2020 PO7528482750	KU	4	40 BRN	SP	CRE	ED,ID	BD	12/5/2081	
2020 PO7552682868	KU	4	45 BRN	SP	CCA	ED,ID	V	12/6/2081	
2020 PO7575082979	KU	4	40 BRN	SP	CRE	ED,ID	BD	12/7/2081	
2020 PO7564883104	KU	4	40 BRN	SP	CRE	ED,ID	BD	12/8/2081	
2020 PO7601683140	KU	4	45 BRN	SP	CRE	ED,ID	BD	12/9/2081	
2020 PO7602683290	KU	5	35 BRN	SP	CRE	ED,ID	BD	12/10/2081	
2020 PO5132907309	KU	6	30 CAH	SP	CRE	ED,ID	TD	12/11/2081	
2020 PO5131707273	KU	6	30 XXX	SP	CRE	ED,ID	TD	12/12/2081	
2020 PO5129007193	KU	4	40 XXX	SP	CRE	ED,ID	TD	12/13/2081	
2020 PO5155207074	KU	6	30 XXX	SP	CRE	ED,ID	TD	12/14/2081	
2020 PO5149907114	KU	6	30 XXX	SP	CRE	ED,ID	TD	12/15/2081	
2020 PO7399491334	KU	4	40 BRO	SP	CRE	ID	VX	RR	12/16/2081
2020 PO7387891232	KU	4	45 BRO	SP	CCA		V		12/17/2081
2020 PO7414491742	KU	2	65 BRO	SP	CRE	IP	VX	PX	12/18/2081
2020 PO7404691438	KU	4	40 BRO	SP	CRE	ID	BD		12/19/2081
2020 PO7134691684	KU	6	30 BRN	SP	CRE	ED,ID	TD		12/20/2081
2020 PO7053896098	KU	4	45 BRN	SP	CRE	ED,ID	TD		12/21/2081
2020 PO7054496278	KU	4	40 BRN	SP	CRE	ED,ID	TD		12/22/2081
2020 PO7154191494	KU	5	35 BRN	SP	CRE	ED,ID	TD		12/23/2081
2020 PO7156691538	KU	4	45 BRN	SP	CRE	ED,ID	TD		12/24/2081
2020 PO7057096468	KU	4	40 BRN	SP	CRE	ED,ID,Src	TX	RR	12/25/2081
2020 PO7057096619	KU	4	40 BRN	SP	CRE	ED,ID	TD		12/26/2081
2020 PO6923301834	KU	6	30 BRN	SP	CCA		V		12/27/2081
2020 PO6199804640	KU	6	30 XXX	SP	CRE		V		12/28/2081
2020 PO7128602140	KU	3	45 BRN	SP	CCA		V		12/29/2081
2020 PO7058401848	KU	3	40 BRN	SP	CCA		V		12/30/2081
2020 PO5151307201	KU	4	40 XXX	SP	CRE	ED,ID	TD		12/31/2081
2020 PO7047390220	KU	6	30 BRN	SP	CRE	MD	VX	PX	1/1/2082
2020 PO5162607200	KU	4	35 XXX	SP	CRE	ED,ID	TD		1/2/2082
2020 5149207059A	KU	6	30 ACW	SP	CRE	ED,ID	TD		1/3/2082
2020 PO7595783254	KU	4	40 BRN	SP	CRE	ED,ID	TD		1/4/2082
2020 PO7579883186	KU	4	40 BRN	SP	CRE	ED,ID	BD		1/5/2082
2020 PO7582283142	KU	4	40 BRN	SP	CRE	ED,ID	TD		1/6/2082
2020 PO7548983019	KU	4	40 BRN	SP	CRE	ED,ID	TD		1/7/2082
2020 PO7531982927	KU	4	40 BRN	SP	CRE	ED,ID	TD		1/8/2082
2020 PO7509982841	KU	4	40 BRN	SP	CRE	ED,ID	TD		1/9/2082
2020 PO7646383398	KU	4	45 BRN	SP	CCA		V		1/10/2082
2020 PO7638983381	KU	5	35 BRN	SP	CCA		V		1/11/2082
2020 PO7628883299	KU	4	40 BRN	SP	CRE		V		1/12/2082
2020 PO5368608343	KU	4	40 BRO	SP	CRE	ID	TD		1/13/2082
2020 PO5372708297	KU	4	40 BRO	SP	CRE	ID	BD		1/14/2082
2020 PO5361408234	KU	3	50 BRO	SP	CRE	ID	BD		1/15/2082
2020 PO5366708131	KU	4	40 BRO	SP	CRE	ID	BD		1/16/2082
2020 PO5336508184	KU	4	45 BRO	SP	CRE	ID	TD		1/17/2082
2020 PO6657013630	KU	5	35 XXX	SP	CRE	ID	TD		1/18/2082
2020 PO6654013477	KU	4	40 XXX	SP	CRE	ID	TD		1/19/2082
2020 PO6642913408	KU	4	40 XXX	SP	CRE	ID	TD		1/20/2082

2020 PO6630713528	KU	4	40	XXX	SP	CRE	ID	TD		1/21/2082
2020 PO6623513725	KU	4	45	XXX	SP	CRE	ID	TD		1/22/2082
2020 PO6563413626	KU	6	30	XXX	SP	CCA		V		1/23/2082
2020 PO65779139477B	KU	4	40	XXX	SP	CRE	ID	TD		1/24/2082
2020 PO6577913947A	KU	5	30	XXX	SP	CCA		V		1/25/2082
2020 PO6576914027	KU	6	30	XXX	SP	CCA		V		1/26/2082
2020 PO6577913947	KU	4	40	XXX	SP	CRE	ID	TD		1/27/2082
2020 PO6594513748	KU	6	30	XXX	SP	CRE	HH,RB	V		1/28/2082
2020 PO6579513741	KU	4	40	XXX	SP	CRE	ID	TD		1/29/2082
2020 PO6589413701	KU	6	30	XXX	SP	CRE	ID	TD		1/30/2082
2020 PO6559513851	KU	4	40	XXX	SP	CCA		V		1/31/2082
2020 PO6557813681	KU	4	40	XXX	SP	CRE	ID	TD		2/1/2082
2020 PO6522913808	KU	4	40	XXX	SP	CCA		V		2/2/2082
2020 PO6542513685	KU	4	40	XXX	SP	CRE	ID	TD		2/3/2082
2020 PO5338008099	KU	4	40	BRO	SP	CRE	ID	TD		2/4/2082
2020 PO7099497130	KU	4	40	BRN	SP	CRE	ED,ID,SRC	TX	RR	2/5/2082
2020 PO5342208014	KU	4	40	BRO	SP	CRE	ID	TD		2/6/2082
2020 PO5331507931	KU	6	30	BRO	SP	CCA	ED	T		2/7/2082
2020 PO5327508024	KU	4	45	BRO	SP	CRE	ID	TD		2/8/2082
2020 PO5336507867	KU	4	40	BRO	SP	CCA		V		2/9/2082
2020 PO5311807916	KU	4	40	BRO	SP	CRE	ED,ID	TD		2/10/2082
2020 PO5288307753a	KU	6	30	BRO	SP	CRE	ID	TD		2/11/2082
2020 PO5314807755	KU	6	30	BRO	SP	CRE	ID	TD		2/12/2082
2020 PO5288307753	KU	4	40	BRO	SP	CRE	ID	TD		2/13/2082
2020 PO5276107655	KU	5	35	BRO	SP	CRE	ID	TD		2/14/2082
2020 PO5268307605	KU	4	40	BRO	SP	CRE	ID	TD		2/15/2082
2020 PO5248397686	KU	6	30	BRO	SP	CRE	ID	TD		2/16/2082
2020 PO7481882950	KU	4	40	BRN	SP	CRE	ED,ID	TD		2/17/2082
2020 PO7514983090	KU	4	40	BRN	SP	CRE	ED,ID	TD		2/18/2082
2020 PO7497283009	KU	4	40	BRN	SP	CRE	ED,ID	TD		2/19/2082
2020 PO7619583385	KU	4	40	BRN	SP	CCA		V		2/20/2082
2020 PO7603683397	KU	4	40	BRN	SP	CRE	ED,ID	TD		2/21/2082
2020 PO7587683410	KU	4	40	BRN	SP	CRE	ED,ID	TD		2/22/2082
2020 PO7569983385	KU	4	40	BRN	SP	CRE	ED,ID	TD		2/23/2082
2020 PO7517383048	KU	6	30	BRN	SP	CRE	ED,ID	BD		2/24/2082
2020 PO7484982746	KU	4	45	BRN	SP	CRE	ED,ID	TD		2/25/2082
2020 PO7494382548	KU	4	45	BRN	SP	CRE	ED,ID,IP	BD		2/26/2082
2020 PO7502482592	KU	4	50	BRN	SP	CRE	ED,ID	TD		2/27/2082
2020 PO7510682355	KU	4	40	BRN	SP	CRE	ED,ID	BD		2/28/2082
2020 PO5230507431	KU	6	30	XXX	SP	CRE	ED,ID	TD		3/1/2082
2020 PO5229707340	F	4	40	XXX	SP	CRE		V		3/2/2082
2020 PO5236307393	F	4	35	XXX	SP	CRE	RB	BX	PX	3/3/2082
2020 PO5223107391	KU	5	35	XXX	SP	CRE	ED,ID	TD		3/4/2082
2020 PO5212507310	KU	6	30	XXX	SP	CRE	RB	X	PX	3/5/2082
2020 PO7501282417	KU	4	45	BRN	SP	CRE	ED,ID	TD		3/6/2082
2020 PO7511382245	KU	4	45	BRN	SP	CRE	ED,ID	TD		3/7/2082
2020 PO7522082048	KU	4	45	BRN	SP	CRE	ED,ID	BD		3/8/2082

2020 PO7523781866	KU	5	35 BRN	SP	CCA		V		3/9/2082
2020 PO7116597171	KU	4	40 BRN	SP	CRE	ED,ID	TD		3/10/2082
2020 PO7132297223	KU	5	35 BRN	SP	CRE	ED,ID	TD		3/11/2082
2020 PO7335192930	KU	2	65 BRN	SP	CRE		V		3/12/2082
2020 PO7066590074	KU	5	35 BRN	SP	CCA		V		3/13/2082
2020 PO7426191633	KU	2	65 BRO	SP	CRE	MD	VX	PX	3/14/2082
2020 PO7444791730	KU	6	30 BRO	SP	CRE		V		3/15/2082
2020 PO7435391786	KU	5	35 BRO	SP	CRE	ED,ID	BD		3/16/2082
2020 6197305447a	KU	4	40 XXX	SP	CCA		V		3/17/2082
2020 PO6206805541	KU	6	30 XXX	SP	CRE	ID,RB	X	RP1	3/18/2082
2020 PO6198105332	KU	6	30 XXX	SP	CRE	ED,ID	TD		3/19/2082
2020 PO6215105185	KU	6	30 XXX	SP	CRE	ED,ID	TD		3/20/2082
2020 PO6214505102	KU	5	40 XXX	SP	CRE	ED,ID	TD		3/21/2082
2020 PO5694510324	KU	3	45 BRO	SP	CCA		V		3/22/2082
2020 PO5667310129	KU	4	30 BRO	SP	CRE	ID	TD		3/23/2082
2020 PO5679710109	KU	4	40 BRO	SP	CRE	ID	TD		3/24/2082
2020 PO5688510107	KU	6	30 BRO	SP	CRE	ID	TD		3/25/2082
2020 PO7529781908	KU	3	45 BRN	SP	CRE	ED,ID	BD		3/26/2082
2020 PO7333991350	F	4	40 BRO	SP	CRE	ED,ID	VX	PX	3/27/2082
2020 PO8024673687	KU	5	35 BRO	SP	CRE	ID	BD		3/28/2082
2020 PO8044473758	KU	6	35 BRO	SP	CRE	ED,ID	TD		3/29/2082
2020 PO8073673856	KU	4	40 BRO	SP	CRE	ED,ID	TD		3/30/2082
2020 PO8096973931	KU	4	40 BRO	SP	CCA		V		3/31/2082
2020 PO8108873945	KU	4	40 BRO	SP	CCA		V		4/1/2082
2020 PO8124274047	KU	4	40 BRO	SP	CCA		V		4/2/2082
2020 PO7997873552	KU	4	40 BRO	SP	CRE	ED,ID	TD		4/3/2082
2020 PO7988573515	KU	5	35 BRO	SP	CRE	ED,ID	TD		4/4/2082
2020 PO8004473425	KU	4	40 BRO	SP	CRE	ED,ID	TD		4/5/2082
2020 PO8013873463	F	4	40 BRO	SP	CRE		V		4/6/2082
2020 PO8034273531	KU	2	65 BRO	SP	CRE		V		4/7/2082
2020 PO5204907310	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		4/8/2082
2020 PO5203607357	KU	6	30 BRN	SP	CCA		V		4/9/2082
2020 PO5185007263	KU	6	30 XXX	SP	CRE	ED,ID	TD		4/10/2082
2020 PO5190707232	KU	4	40 XXX	SP	CRE	ED,ID	TD		4/11/2082
2020 PO5183607174	KU	4	40 BRN	SP	CCA		V		4/12/2082
2020 PO7533881810	KU	4	45 BRN	SP	CRE	ED,ID	TD		4/13/2082
2020 PO7732182030	F	4	40 BRN	SP	P		V		4/14/2082
2020 PO7719982014	F	3	45 BRN	SP	CRE		V		4/15/2082
2020 PO7707281994	F	4	40 BRN	SP	CRE		V		4/16/2082
2020 PO7695781980	F	3	45 BRN	SP	CRE		V		4/17/2082
2020 PO7684481965	F	4	40 BRN	SP	P		V		4/18/2082
2020 PO7654181922	F	3	45 BRN	SP	P		V		4/19/2082
2020 PO7639381897	F	3	40 BRN	SP	CRE		V		4/20/2082
2020 PO7624581873	F	3	45 BRN	SP	CRE		V		4/21/2082
2020 PO7628481878	F	4	40 BRN	SP	CRE		V		4/22/2082
2020 PO5250397523	KU	6	30 BRO	SP	CRE		V		4/23/2082
2020 PO5255997790	KU	4	40 BRO	SP	CRE	ID	TD		4/24/2082

2020 PO5270198023	KU	5	35 BRO	SP	CRE	ID	TD	4/25/2082
2020 PO5306198251	KU	4	40 BRO	SP	CRE	ID	TD	4/26/2082
2020 PO5303698394	KU	4	40 BRO	SP	CRE	ID	TD	4/27/2082
2020 PO5314998662	KU	4	40 BRO	SP	CRE	ID	TD	4/28/2082
2020 PO5322998816	KU	5	35 BRO	SP	CRE	ID	TD	4/29/2082
2020 PO5367098758	KU	4	40 BRO	SP	CRE	ID	TD	4/30/2082
2020 PO7343891450	F	3	45 BRO	SP	CRE		V	5/1/2082
2020 PO7351891534	F	3	45 BRO	SP	CRE		V	5/2/2082
2020 PO7364291663	F	3	45 BRO	SP	CRE		V	5/3/2082
2020 PO7379891822	F	2	50 BRO	SP	CRE		V	5/4/2082
2020 PO6162604972	KU	5	35 BRO	SP	CRE	ED,ID	TD	5/5/2082
2020 PO6154904999	KU	6	30 BRO	SP	CCA		V	5/6/2082
2020 PO6165104701	F	3	45 XXX	SP	CCA		V	5/7/2082
2020 PO6163604638	KU	5	35 XXX	SP	CRE	ED,ID	TD	5/8/2082
2020 PO6155904662	F	6	30 XXX	SP	CRE		V	5/9/2082
2020 PO6140804828	KU	3	50 BRN	SP	CCA		V	5/10/2082
2020 PO6122804755	KU	6	30 BRN	SP	CCA		V	5/11/2082
2020 PO6131504680	KU	4	40 BRN	SP	CCA		V	5/12/2082
2020 PO6125004577	KU	5	35 ACW	SP	CRE	ED,ID	TD	5/13/2082
2020 PO6129104461	KU	5	35 BRN	SP	CCA		V	5/14/2082
2020 PO6138404508	KU	4	40 XXX	SP	CCA		V	5/15/2082
2020 PO6141704669	KU	4	40 XXX	SP	CCA		V	5/16/2082
2020 PO6153104739	KU	3	45 BRO	SP	S		V	5/17/2082
2020 PO9374193040	C	4	40 ACW	SP	CRE		V	5/18/2082
2020 PO9385893066	C	4	40 ACW	SP	CRE		V	5/19/2082
2020 PO9396993088	C	4	40 ACW	SP	CRE		V	5/20/2082
2020 PO9366193040	C	4	40 ACW	SP	CRE		V	5/21/2082
2020 PO9393693059	KU	4	40 ACW	SP	CRE	ED,ID	TD	5/22/2082
2020 PO9368393010	KU	4	40 ACW	SP	CRE	ED,ID	TD	5/23/2082
2020 PO5865945335b	KU	5	35 ACE	SP	P	ED,ID	TD	5/24/2082
2020 PO5865945335a	KU	6	30 ACE	SP	CCA		V	5/25/2082
2020 PO5865945335	KU	4	40 ACE	SP	CRE	ED,ID	BD	5/26/2082
2020 PO5882245603	KU	4	40 ACE	SP	CCA		V	5/27/2082
2020 PO5927345436	KU	4	40 ACE	SP	CRE	ED,ID	BD	5/28/2082
2020 PO5884245430	KU	3	45 ACE	SP	CCA		V	5/29/2082
2020 PO9393293287	C	4	40 ACW	SP	CRE		V	5/30/2082
2020 PO9390293283	KU	4	40 ACW	SP	CRE		V	5/31/2082
2020 PO9385793346	KU	4	40 ACW	SP	CRE	ED,ID	BD	6/1/2082
2020 PO9389193250	KU	4	40 ACW	SP	CRE	ED,ID	TD	6/2/2082
2020 PO5916144237	C	4	40 ACE	SP	CRE		V	6/3/2082
2020 PO4749709847	KU	3	45 BRO	SP	CCA		V	6/4/2082
2020 PO2920082224A	KU	4	40 BRN	SP	S	ED,ID	VX	6/5/2082
2020 PO9200282224	KU	4	40 BRN	SP	CRE	ED,ID	TD	6/6/2082
2020 PO9358293286	KU	4	40 ACW	SP	CRE	ED,ID	BD	6/7/2082
2020 PO9361093230	KU	4	45 ACW	SP	CRE	ED,ID,IP,SRC	TX	6/8/2082
2020 PO9372693212	KU	5	30 ACW	SP	CRE		V	6/9/2082
2020 PO5885445202	F	3	50 ACE	SP	CCA		V	6/10/2082

2020 PO5891044869	F	3	45 ACE	SP	CCA		V	6/11/2082
2020 PO5896844648	F	3	50 ACE	SP	CCA		V	6/12/2082
2020 PO5908144215	F	4	40 ACE	SP	CRE		V	6/13/2082
2020 PO5925544017	KU	4	40 ACE	SP	CCA		V	6/14/2082
2020 PO5914844009	F	3	45 ACE	SP	CCA		V	6/15/2082
2020 PO5946644030	KU	3	45 ACE	SP	CCA		V	6/16/2082
2020 PO5959044039	KU	4	40 ACE	SP	CCA		V	6/17/2082
2020 PO4742309628	KU	3	40 BRO	SP	CRE	ID,IP	BD	6/18/2082
2020 PO9286093007	KU	4	40 ACW	SP	CRE	ED,ID	TD	6/19/2082
2020 PO9297692980	KU	5	35 ACW	SP	CRE	ED,ID,IP	TD	6/20/2082
2020 PO9299993046	KU	4	40 ACW	SP	CRE	ED,ID	BD	6/21/2082
2020 PO9320293101	KU	3	45 ACW	SP	CRE		V	6/22/2082
2020 PO9381593102	KU	5	35 ACW	SP	CRE	ED,ID	TD	6/23/2082
2020 PO9348993165	KU	4	45 ACW	SP	CRE	ED,ID,IP	TD	6/24/2082
2020 PO4744610586	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD	6/25/2082
2020 PO5718754316	KU	2	45 ACE	SP	CRE	ED,ID,IP	TD	6/26/2082
2020 PO5740154243	KU	4	40 ACE	SP	CRE	ED,ID	BD	6/27/2082
2020 PO6359147936	KU	5	35 ACE	SP	CRE		V	6/28/2082
2020 PO6386947288	C	4	40 ACE	SP	CRE		V	6/29/2082
2020 PO6348847948	KU	2	35 ACE	SP	CCA		V	6/30/2082
2020 PO5990744062	KU	4	40 ACE	SP	CCA		V	7/1/2082
2020 PO5906243252	KU	6	30 ACE	SP	CRE		V	7/2/2082
2020 PO4766511260	KU	3	45 BRO	SP	CRE		V	7/3/2082
2020 PO4777211472	KU	4	45 BRO	SP	CCA		V	7/4/2082
2020 PO4785811717	KU	3	50 BRO	SP	CCA		V	7/5/2082
2020 PO4792311895	KU	3	45 BRO	SP	CCA		V	7/6/2082
2020 PO4799712108	KU	4	40 BRO	SP	CRE		V	7/7/2082
2020 PO9187082084	KU	4	40 BRN	SP	S		V	7/8/2082
2020 PO4790312310	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	7/9/2082
2020 PO4805812283	KU	3	45 BRO	SP	CCA		V	7/10/2082
2020 PO4813312526	KU	4	40 BRO	SP	CCA		V	7/11/2082
2020 PO4820212778	KU	4	40 BRO	SP	CCA		V	7/12/2082
2020 PO4825913031	KU	3	45 BRO	SP	CCA		V	7/13/2082
2020 PO9387085155	KU	4	40 BRN	SP	CRE		V	7/14/2082
2020 PO9379384765	KU	4	40 BRN	SP	S		V	7/15/2082
2020 PO9371784513	KU	4	40 BRN	SP	CRE	ED,ID	TD	7/16/2082
2020 PO9468084056	F	5	25 BRN	SP	CRE	ED,ID,RB	V	7/17/2082
2020 PO9457284154	KU	4	40 BRN	SP	CRE	ED,ID	TX	RR 7/18/2082
2020 PO9414684182	KU	4	45 BRN	SP	CRE	ID	BD	7/19/2082
2020 PO9887791992	KU	4	40 ACW	SP	CRE	ED,ID	TD	7/20/2082
2020 PO9563487752	C	4	40 ACW	SP	CRE		V	7/21/2082
2020 PO9585488579	KU	3	45 ACW	SP	S		V	7/22/2082
2020 PO9598088408	KU	4	40 ACW	SP	S		V	7/23/2082
2020 PO9600088199	KU	4	40 ACW	SP	CRE	ED,ID	TD	7/24/2082
2020 PO9592787951	KU	4	40 ACW	SP	S		V	7/25/2082
2020 PO9583488130	KU	4	40 ACW	SP	CRE	ED,ID	TD	7/26/2082
2020 PO9285583969	KU	4	40 BRN	SP	CRE	ED,ID	TD	7/27/2082

2020 PO9595787744	KU	6	30 ACW	SP	CRE	ED,ID	TD	7/28/2082
2020 PO9585887711	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	7/29/2082
2020 PO9575887757	KU	6	30 ACW	SP	CRE	ED,ID	TD	7/30/2082
2020 PO9576187492	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	7/31/2082
2020 PO9278683711	KU	4	40 BRN	SP	CRE	ED,ID	TD	8/1/2082
2020 PO4751527185	KU	3	45 BRO	SP	CRE		V	8/2/2082
2020 PO4776627020	KU	3	45 BRO	SP	CRE		V	8/3/2082
2020 PO4801726856	KU	4	40 BRO	SP	CRE		V	8/4/2082
2020 PO4826626674	KU	4	50 BRO	SP	CRE		V	8/5/2082
2020 PO4846226579	KU	4	40 BRO	SP	CCA		V	8/6/2082
2020 PO4917026251	KU	3	45 BRO	SP	CRE		V	8/7/2082
2020 PO4919626301	KU	4	40 BRO	SP	CRE		V	8/8/2082
2020 PO4992225968	KU	2	45 BRO	SP	CRE		V	8/9/2082
2020 PO4725908584	KU	5	30 BRO	SP	A	ID,IP	BD	8/10/2082
2020 PO4735608433	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/11/2082
2020 PO9542387294	KU	6	30 ACW	SP	S		V	8/12/2082
2020 PO9539786944	KU	6	30 ACW	SP	S		V	8/13/2082
2020 PO9542387194	KU	4	45 ACW	SP	CRE	ED,ID	TD	8/14/2082
2020 PO9559987212	KU	4	45 ACW	SP	CRE	ED,ID	TD	8/15/2082
2020 PO4722408459	KU	4	40 BRO	SP	CRE	ID,IP	BD	8/16/2082
2020 PO4687908694	KU	4	35 BRO	SP	CRE	ED,ID,IP	TD	8/17/2082
2020 PO4722109026	KU	3	45 BRO	SP	CCA		V	8/18/2082
2020 PO4743509103	KU	6	30 BRO	SP	CRE	ID	BD	8/19/2082
2020 PO4747809262	KU	5	35 BRO	SP	CRE	ED,ID	TD	8/20/2082
2020 PO4733809358	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD	8/21/2082
2020 PO9520693971	C	4	40 XXX	SP	CRE		V	8/22/2082
2020 PO9553893915	C	4	40 XXX	SP	CRE		V	8/23/2082
2020 PO9529394109	C	4	40 XXX	SP	CRE		V	8/24/2082
2020 PO9608393522	C	4	40 XXX	SP	CRE		V	8/25/2082
2020 PO9617393525	C	4	40 XXX	SP	CRE		V	8/26/2082
2020 PO9597393532	C	4	40 XXX	SP	CRE		V	8/27/2082
2020 PO9257193455	C	4	40 XXX	SP	CRE		V	8/28/2082
2020 PO9581793238	C	4	40 XXX	SP	CRE		V	8/29/2082
2020 PO9641293825	C	4	40 XXX	SP	CRE		V	8/30/2082
2020 PO9607593708	C	4	40 XXX	SP	CRE		V	8/31/2082
2020 PO9566293564	F	4	40 XXX	SP	S		V	9/1/2082
2020 PO9523693526	C	4	40 XXX	SP	CRE		V	9/2/2082
2020 PO9552593498	C	4	40 XXX	SP	CRE		V	9/3/2082
2020 PO9383289981	C	4	40 BRN	SP	S		V	9/4/2082
2020 PO9343890688	F	4	40 XXX	SP	CRE		V	9/5/2082
2020 PO9391690089	C	4	40 XXX	SP	CRE		V	9/6/2082
2020 PO9394289984	C	4	40 BRN	SP	S		V	9/7/2082
2020 PO9361390585	F	4	40 BRN	SP	CRE		V	9/8/2082
2020 PO9294790825	C	4	40 XXX	SP	CRE		V	9/9/2082
2020 PO9310090890	F	4	40 BRN	SP	S		V	9/10/2082
2020 PO9385590372	F	4	40 BRN	SP	CRE		V	9/11/2082
2020 PO9375590497	F	4	40 BRN	SP	S		V	9/12/2082

2020 PO9326390795	F	4	40 BRN	SP	S		V	9/13/2082
2020 PO9289286613	C	3	40 BRN	SP	S		V	9/14/2082
2020 PO9394289811	C	5	20 XXX	SP	CRE		V	9/15/2082
2020 PO9319985011	KU	5	35 XXX	SP	CRE	ED,ID	TD	9/16/2082
2020 PO4738688932	F	4	40 BRO	SP	A		V	9/17/2082
2020 PO4733788915	LGE	4	35 BRO	SP	CRE		V	9/18/2082
2020 PO4734888923	LGE	4	35 BRO	SP	P		B	9/19/2082
2020 PO4730188907	F	UNK	45 BRO	SP	CRE		V	9/20/2082
2020 PO4730488908	F	4	40 BRO	SP	CRE		V	9/21/2082
2020 PO4731388913	F	4	40 BRO	SP	CCA		V	9/22/2082
2020 PO4732688920	F	4	40 BRO	SP	CRE		V	9/23/2082
2020 PO4733888926	F	4	40 BRO	SP	A		V	9/24/2082
2020 PO4734488930	F	4	40 BRO	SP	P		V	9/25/2082
2020 PO4735588935	F	4	40 BRO	SP	CRE		V	9/26/2082
2020 PO4736788942	F	4	40 BRO	SP	P		V	9/27/2082
2020 PO4737888928	F	4	40 BRO	SP	CCA		V	9/28/2082
2020 PO4737688930	F	4	40 BRO	SP	CCA		V	9/29/2082
2020 PO4764188798	LGE	4	40 BRN	SP	CRE	ED,ID	BD	9/30/2082
2020 PO4764688800	LGE	4	30 BRN	SP	CRE	ED,ID	TD	10/1/2082
2020 PO4039282741	LGE	3	50 BRN	SP	A	ED,ID	TD	10/2/2082
2020 PO4037482761	F	3	45 BRN	SP	A		V	10/3/2082
2020 PO4038082750	F	3	45 BRN	SP	CCA		V	10/4/2082
2020 PO4038982754	F	4	30 BRN	SP	CCA		V	10/5/2082
2020 PO4040482748	LGE	4	40 BRN	SP	P	ED,ID	BD	10/6/2082
2020 PO4043882748	LGE	4	40 BRN	SP	CRE	ED,ID,IP	BD	10/7/2082
2020 PO4042282748	LGE	4	40 BRN	SP	P	ED,ID	BD	10/8/2082
2020 PO4763688809	LGE	3	40 BRN	SP	CRE	ED,ID	BD	10/9/2082
2020 PO4764588812	LGE	4	30 BRN	SP	CRE	ED,ID	BD	10/10/2082
2020 PO4040582747	F	4	40 BRN	SP	CCA		V	10/11/2082
2020 PO4043882740	LGE	4	30 BRN	SP	CCA		V	10/12/2082
2020 PO4763088821	LGE	3	45 BRN	SP	CRE	ED,ID	B	10/13/2082
2020 PO4763688824	LGE	4	30 BRN	SP	CRE	ED,ID	BD	10/14/2082
2020 PO4763388829	LGE	4	30 BRN	SP	CRE	ED,ID	BD	10/15/2082
2020 PO4762188839	LGE	4	40 BRN	SP	CRE	ED,ID,IP	BD	10/16/2082
2020 PO4761888854	LGE	4	30 BRN	SP	CRE	ED,ID	BD	10/17/2082
2020 PO4761488852	LGE	4	40 BRN	SP	CRE	ED,ID	BD	10/18/2082
2020 PO4761388867	LGE	4	30 BRN	SP	CRE	ED,ID	BD	10/19/2082
2020 PO4760888865	LGE	4	40 BRN	SP	CRE	ED,ID	BD	10/20/2082
2020 PO4690188943	LGE	4	40 BRO	SP	P	ED,ID	T	10/21/2082
2020 PO4692288914	LGE	3	45 BRO	SP	CCA		V	10/22/2082
2020 PO4692488908	LGE	2	55 BRO	SP	CCA		V	10/23/2082
2020 PO4694288921	LGE	H1	70 BRO	SP	CCA		V	10/24/2082
2020 PO4696888940	LGE	1	45 BRO	SP	P	ED	BD	10/25/2082
2020 PO4698988949	LGE	6	25 BRO	SP	CRE		V	10/26/2082
2020 PO4698688954	LGE	4	40 BRO	SP	P	ED,ID	TD	10/27/2082
2020 PO4702288980	LGE	UNK	45 BRO	SP	CRE	ED,ID	BD	10/28/2082
2020 PO4706189008	LGE	3	50 BRO	SP	CRE	ED,ID	BD	10/29/2082

2020 PO4042683079	F	4	35 BRN	SP	CCA		V	10/30/2082
2020 PO4040783080	F	4	30 BRN	SP	P		V	10/31/2082
2020 PO4044483077	F	4	30 BRN	SP	CCA		V	11/1/2082
2020 PO4046183076	F	4	35 BRN	SP	CRE		V	11/2/2082
2020 PO4047983075	F	4	30 BRN	SP	P		V	11/3/2082
2020 PO4039783030	LGE	3	45 BRN	SP	P	ED,ID	TD	11/4/2082
2020 PO4047383002	LGE	4	40 BRN	SP	P	ED,ID	TD	11/5/2082
2020 PO4046583003	LGE	4	40 BRN	SP	P	ED,ID	BD	11/6/2082
2020 PO4044683004	LGE	4	40 BRN	SP	P	ED,ID	TD	11/7/2082
2020 PO3863808288	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	11/8/2082
2020 PO3856108441	KU	4	45 BRO	SP	CCA		V	11/9/2082
2020 PO4039783055	LGE	4	40 BRN	SP	CCA	ED,ID	V	11/10/2082
2020 PO4042983046	LGE	4	30 BRN	SP	A	ED,ID,IP	TD	11/11/2082
2020 PO4760688881	LGE	4	30 BRN	SP	CRE	ED,ID	TD	11/12/2082
2020 PO3842208492	KU	4	45 BRO	SP	CCA		V	11/13/2082
2020 PO4042983052	LGE	3	45 BRN	SP	CCA		V	11/14/2082
2020 PO4041483052	LGE	4	40 BRN	SP	P	ED,ID	TD	11/15/2082
2020 PO4041483046	LGE	4	30 BRN	SP	CCA	ED,ID	VX	11/16/2082
2020 PO4042583015	LGE	4	40 BRN	SP	CRE	ED,ID	TD	11/17/2082
2020 PO4760188878	LGE	3	45 BRN	SP	A	ED,ID	BD	11/18/2082
2020 PO1869821785	ODP	6	30 XXX	SP	CRE	ID	TD	11/19/2082
2020 PO1875221672	ODP	4	40 XXX	SP	CRE	ID	TD	11/20/2082
2020 PO1854421625	ODP	4	40 XXX	SP	CCA		V	11/21/2082
2020 PO4049583064	LGE	4	30 BRN	SP	P	ED,ID	TD	11/22/2082
2020 PO4048983064	LGE	4	40 BRN	SP	P	ED,ID	TD	11/23/2082
2020 PO4049083075	LGE	4	40 BRN	SP	P	ED,ID	TD	11/24/2082
2020 PO4048883039	LGE	4	40 BRN	SP	A	ED,ID	TX	11/25/2082
2020 PO3859608405	KU	4	45 BRO	SP	CCA		V	11/26/2082
2020 PO4757888911	LGE	4	30 BRN	SP	A	ED,ID	BD	11/27/2082
2020 PO4758788915	LGE	4	40 BRN	SP	CRE	ED,ID	BD	11/28/2082
2020 PO4758588911	LGE	4	40 BRN	SP	CRE	ED,ID	BD	11/29/2082
2020 PO1869021436	ODP	4	40 XXX	SP	CRE	ID	BD	11/30/2082
2020 PO1839921376	ODP	6	30 XXX	SP	CRE	ID	BD	12/1/2082
2020 PO4759788907	LGE	4	35 BRN	SP	P	ED,ID	BD	12/2/2082
2020 PO3932908686	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	12/3/2082
2020 PO4758988902	LGE	4	40 BRN	SP	CRE	ED,ID	BD	12/4/2082
2020 PO4759588891	LGE	4	40 BRN	SP	CRE	ED,ID	BD	12/5/2082
2020 PO4762088915	LGE	4	35 BRN	SP	S		V	12/6/2082
2020 PO4761788923	LGE	4	40 BRN	SP	CRE	ED,ID	BD	12/7/2082
2020 PO4760688924	LGE	4	45 BRN	SP	A	ED,ID	BD	12/8/2082
2020 PO4048983049	LGE	4	40 BRN	SP	CRE	ED,ID	TD	12/9/2082
2020 PO4042782931	LGE	4	40 BRN	SP	P	ED,ID	BD	12/10/2082
2020 PO4041082928	LGE	4	30 BRN	SP	CRE	ED,ID	TD	12/11/2082
2020 PO4041282924	LGE	4	40 BRN	SP	P	ED,ID	BD	12/12/2082
2020 PO4039582922	LGE	4	30 BRN	SP	P	ED,ID	BD	12/13/2082
2020 PO4048683009	LGE	4	40 BRN	SP	P	ED,ID	TD	12/14/2082
2020 PO1891421146	ODP	4	40 XXX	SP	CCA	ED	T	12/15/2082

2020 PO1910220907	ODP	4	40 XXX	SP	CCA		V		12/16/2082
2020 PO1927420864	ODP	4	40 XXX	SP	CCA	ED	T		12/17/2082
2020 PO1947520826	F	4	40 XXX	SP	A		V		12/18/2082
2020 PO4761288911	LGE	4	30 BRN	DF	CRE	ED,ID	BD		12/19/2082
2020 PO4761588903	LGE	4	30 BRN	SP	P	ED,ID	TD		12/20/2082
2020 PO4710789041	LGE	4	40 BRO	SP	P	ED,ID	TD		12/21/2082
2020 PO4049583049	LGE	4	30 BRN	SP	P	ED,ID	TD		12/22/2082
2020 PO4049383039	LGE	4	30 BRN	SP	P	ED,ID	X	RP2	12/23/2082
2020 PO4046583010	LGE	4	30 BRN	SP	CCA	ED,ID,RB	X	RP2	12/24/2082
2020 PO7610641458	LGE	4	35 BRN	SP	P	ED,ID	TD		12/25/2082
2020 PO4041183007	LGE	4	40 BRN	SP	P	ED,ID	TD		12/26/2082
2020 PO4043383005	LGE	4	40 BRN	SP	CCA		V		12/27/2082
2020 PO4042683006	LGE	4	40 BRN	SP	P	ED,ID	TD		12/28/2082
2020 PO5471845673	KU	4	40 ACW	SP	CRE	ED,ID	TD		12/29/2082
2020 PO6126838735	KU	6	30 ACW	SP	S		V		12/30/2082
2020 PO6100138695	KU	3	45 ACW	SP	S		V		12/31/2082
2020 PO6122338472	KU	3	45 ACW	SP	S		V		1/1/2083
2020 PO6132038374	KU	5	35 ACW	SP	S		V		1/2/2083
2020 PO4400720315	KU	3	45 BRO	SP	CCA		V		1/3/2083
2020 PO4490419704	KU	3	40 BRO	SP	CRE	ED,ID	TD		1/4/2083
2020 PO5543946268a	KU	3	45 ACE	SP	CCA		V		1/5/2083
2020 PO5511945952a	KU	2	50 ACE	SP	CCA		V		1/6/2083
2020 PO5577146342	F	4	45 ACE	SP	P		V		1/7/2083
2020 PO4432720092	KU	3	45 BRO	SP	CRE		V		1/8/2083
2020 PO4466119872	F	4	45 BRO	SP	CCA		V		1/9/2083
2020 PO4584418656	F	4	40 BRO	SP	CRE		V		1/10/2083
2020 PO4678518345	F	4	40 BRO	SP	CCA		V		1/11/2083
2020 PO5536145480	KU	6	30 ACE	SP	CRE	ED,ID	TD		1/12/2083
2020 PO5526945579	KU	4	40 ACE	SP	CRE	ED,ID	TD		1/13/2083
2020 PO4934219608	KU	4	40 BRO	SP	CCA		V		1/14/2083
2020 PO4941819453	C	5	35 BRO	SP	CRE		V		1/15/2083
2020 PO4946619229	KU	4	40 BRO	SP	CCA		V		1/16/2083
2020 PO4959619579	KU	4	40 BRO	SP	CCA		V		1/17/2083
2020 PO4950919399	KU	4	40 BRO	SP	CCA		V		1/18/2083
2020 PO5586249925	KU	4	40 ACE	SP	CRE	ED,ID	TD		1/19/2083
2020 PO4832919805	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		1/20/2083
2020 PO4864719208	KU	5	35 BRO	SP	CRE	HH,ID,RB	X	RP1	1/21/2083
2020 PO5612249994	KU	3	45 ACE	SP	CRE	ED,ID	TD		1/22/2083
2020 PO4896419266	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		1/23/2083
2020 PO4896919505	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD		1/24/2083
2020 PO4894119007	KU	2	50 BRO	SP	CCA		V		1/25/2083
2020 PO3167266555	KU	4	40 BRN	SP	CRE	ID	TD		1/26/2083
2020 PO9211219995	KU	4	40 OTH	SP	CRE	ID	TD		1/27/2083
2020 PO9138617651	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD		1/28/2083
2020 PO9131817437	KU	6	30 OTH	SP	CRE	ID	TD		1/29/2083
2020 PO9138617184	KU	4	40 OTH	SP	CRE	ID,MD	TD		1/30/2083
2020 PO2812952399	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		1/31/2083

2020 PO7125889871	KU	6	30 BRN	SP	CRE	ED,ID	BD	2/1/2083
2020 PO2795052134	KU	4	40 BRO	SP	CRE	ID,IP	BD	2/2/2083
2020 PO0970832340	ODP	4	45 XXX	SP	CRE	ED,ID	TD	2/3/2083
2020 PO0960932153	ODP	5	35 XXX	SP	CRE	ED,ID	TD	2/4/2083
2020 PO0940231970	ODP	4	45 XXX	SP	CRE	ID	BD	2/5/2083
2020 PO2780451931	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	2/6/2083
2020 PO2762251661	KU	4	40 BRO	SP	CRE	ID,IP	BD	2/7/2083
2020 PO2689150574	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	2/8/2083
2020 PO2708650865	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	2/9/2083
2020 PO2725651125	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	2/10/2083
2020 PO3157866742	KU	4	40 BRN	SP	CRE	ID	TD	2/11/2083
2020 PO3939882632	LGE	3	50 BRN	SP	CRE	ED,HH,ID,RB	BX	PX 2/12/2083
2020 PO9532655735	KU	3	45 BRO	SP	CCA		V	2/13/2083
2020 PO9548655746	KU	3	45 BRO	SP	CCA		V	2/14/2083
2020 PO9577255763	KU	4	40 BRO	SP	CRE	ED,ID,IP,SRC	TD	2/15/2083
2020 PO9593656034	KU	3	45 BRO	SP	CCA		V	2/16/2083
2020 PO0590160342	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	2/17/2083
2020 PO0594960382	F	4	35 ACW	SP	CRE		V	2/18/2083
2020 PO9595456042	KU	3	45 BRO	SP	CCA		V	2/19/2083
2020 PO9570355886	KU	3	45 BRO	SP	CCA		V	2/20/2083
2020 PO8977159952	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD	2/21/2083
2020 PO3132966981	KU	4	40 BRN	SP	CRE	ID	TD	2/22/2083
2020 PO3115167166	KU	5	30 BRN	SP	CRE	ID,IP	TD	2/23/2083
2020 PO3076067542	KU	5	35 BRN	SP	CRE	ED,ID	TD	2/24/2083
2020 PO0577560395	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	2/25/2083
2020 PO0579860527	KU	6	30 ACW	SP	CRE	ED,EP,HH,ID,IP,RB	BX	RP1 2/26/2083
2020 PO0577260456	KU	5	35 ACW	SP	CRE	ED,ID,IP	TD	2/27/2083
2020 PO0566160445	KU	4	40 ACW	SP	CRE	ED,ID	TD	2/28/2083
2020 PO3056867735	KU	5	35 BRN	SP	CRE	ID	TD	3/1/2083
2020 PO7148288108	KU	2	50 BRN	SP	CRE	ED,ID	BD	3/2/2083
2020 PO7165587917	KU	5	35 BRN	SP	CRE		V	3/3/2083
2020 PO7155287983	KU	3	50 BRN	SP	CRE	ED,ID	BD	3/4/2083
2020 PO7160587894	KU	3	50 BRN	SP	CRE	ED,ID	BD	3/5/2083
2020 PO7175687495	KU	4	45 BRN	SP	CRE	ED,ID	TD	3/6/2083
2020 PO7170887610	KU	4	45 BRN	SP	CRE	ED,ID	BD	3/7/2083
2020 PO7797171899	KU	6	30 BRO	SP	CRE		V	3/8/2083
2020 PO7678778481	KU	2	65 BRO	SP	CRE		V	3/9/2083
2020 PO7136087585	KU	4	45 BRN	SP	CRE	ED,ID	TD	3/10/2083
2020 PO7121987503	KU	4	45 BRN	SP	CRE	ED,ID	TD	3/11/2083
2020 PO5230006720	KU	4	40 XXX	SP	CRE	ED,ID	TD	3/12/2083
2020 PO5211906643	KU	4	40 XXX	SP	CRE	RB	X	RP1 3/13/2083
2020 PO5205806515	KU	6	30 XXX	SP	CCA		V	3/14/2083
2020 PO5190706587	KU	4	40 XXX	SP	CRE	ED,ID	TD	3/15/2083
2020 PO5229807070	KU	4	45 KOP	SP	CCA		V	3/16/2083
2020 PO5237207135	KU	6	30 XXX	SP	CRE	ED,ID	TD	3/17/2083
2020 PO5243207100	KU	4	40 BRN	SP	CCA		V	3/18/2083
2020 5243207100A	KU	5	30 XXX	SP	P	ED	T	3/19/2083

2020 PO1111434013	F	4	40 OTH	SP	CRE	ED	V			3/20/2083
2020 PO1121433997	F	3	45 OTH	SP	CRE	ED	V			3/21/2083
2020 PO1121433997A	F	4	45 OTH	SP	CRE		V			3/22/2083
2020 PO1121534044	ODP	4	40 OTH	SP	CRE	ID	BD			3/23/2083
2020 PO3953882689	LGE	3	40 BRN	SP	A	ED,ID	BD			3/24/2083
2020 PO3077240479	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD			3/25/2083
2020 PO3097440380	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD			3/26/2083
2020 PO3117640280	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD			3/27/2083
2020 PO3136140280	KU	4	40 ACE	SP	CRE	ED,ID	BD			3/28/2083
2020 PO6875295509	KU	6	30 BRN	SP	CRE	ED,ID	TD			3/29/2083
2020 PO1126132427	ODP	5	35 BRN	SP	CCA		V			3/30/2083
2020 PO1105832427	ODP	5	35 BRN	SP	CRE		V			3/31/2083
2020 PO1095432427	ODP	5	35 BRN	SP	CCA		V			4/1/2083
2020 PO6872895394	KU	6	30 BRN	SP	CRE	ED,ID,SRC	TX	RR		4/2/2083
2020 PO1085332419	ODP	5	35 BRN	SP	CCA	SRC	T			4/3/2083
2020 PO0984132262	ODP	5	30 BRN	SP	CRE	ED,ID	TD			4/4/2083
2020 PO5254107109	KU	6	30 XXX	SP	CRE	ID	BD			4/5/2083
2020 PO0615865382	KU	4	40 BRO	SP	CRE		V			4/6/2083
2020 PO0619266665	KU	5	35 BRO	SP	CCA		V			4/7/2083
2020 PO0626266748	F	4	40 BRO	SP	CRE		V			4/8/2083
2020 PO0670066529	KU	4	45 BRO	SP	CCA		V			4/9/2083
2020 PO0673266644	F	4	40 BRO	SP	CRE		V			4/10/2083
2020 PO8917460214	KU	4	40 BRO	SP	CRE		T			4/11/2083
2020 PO0987057000	KU	4	45 ACW	SP	CRE	ED,ID	BD			4/12/2083
2020 PO0968857314	KU	4	45 ACW	SP	CRE	ED,ID	TD			4/13/2083
2020 PO1003856682	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD			4/14/2083
2020 PO8894960319	KU	4	40 BRO	SP	CRE	ED,SRC	T			4/15/2083
2020 PO8908559756	KU	4	40 BRO	SP	CCA		V			4/16/2083
2020 PO8852259166	KU	4	45 BRO	SP	CRE	ED	T			4/17/2083
2020 PO1026356273	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD			4/18/2083
2020 PO1243246226	KU	4	40 BRN	SP	CRE	ID	TD			4/19/2083
2020 PO1042155988	KU	4	40 ACW	SP	P		T			4/20/2083
2020 PO0380856230	KU	4	40 BRO	SP	CRE	ED,ID,IP,SRC	TD			4/21/2083
2020 PO0373856063	KU	4	35 BRO	SP	CRE	ED,ID,IP,SRC	TD			4/22/2083
2020 PO1057355704	KU	4	45 ACW	SP	P		T			4/23/2083
2020 PO1070654955	F	4	40 ACW	SP	CRE		V			4/24/2083
2020 PO1016655318	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD			4/25/2083
2020 PO0367255910	KU	4	30 BRO	SP	CRE	ED,ID,IP,SRC	TD			4/26/2083
2020 PO0360555743	KU	4	35 BRO	SP	CRE	ED,ID,SRC	TD			4/27/2083
2020 PO0354455597	KU	6	35 BRO	SP	CRE	ED,EP,ID,IP	X	RP2		4/28/2083
2020 PO0348255449	KU	6	35 BRO	SP	CRE	ID,IP,RP	X	RP2		4/29/2083
2020 PO0990755089	KU	4	40 ACW	SP	P		T			4/30/2083
2020 PO0977854856	KU	4	40 ACW	SP	P		T			5/1/2083
2020 PO0963154565	KU	3	40 ACW	SP	P		T			5/2/2083
2020 PO0947654257	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD			5/3/2083
2020 PO5193307642	KU	5	35 BRO	SP	CRE	ID	TD			5/4/2083
2020 PO7384485369	KU	4	45 BRN	SP	CRE	ED,ID	TD			5/5/2083

2020 PO7892675222	KU	5	30 BRO	SP	CRE	ED,ID,IP	TD		5/6/2083
2020 PO9389794138	KU	5	30 ACW	DF	CRE	ED,ID,MD,RB,SRC	X	RP1	5/7/2083
2020 PO7385485162	KU	6	35 BRN	SP	CRE	ED,ID	TD		5/8/2083
2020 PO7360385042	KU	5	35 BRN	SP	CRE		V		5/9/2083
2020 PO7359184917	KU	5	35 BRN	SP	P	ED,ID	BD		5/10/2083
2020 PO7353585314	KU	5	35 BRN	SP	CRE	ED,ID	BD		5/11/2083
2020 PO7339485113	KU	6	30 BRN	SP	CCA		V		5/12/2083
2020 PO7334485197	F	5	35 BRN	SP	CRE		V		5/13/2083
2020 PO7324685128	KU	5	35 BRN	SP	CRE	ED,ID	TD		5/14/2083
2020 PO7913575042	KU	5	35 BRO	SP	CRE	ID	BD		5/15/2083
2020 PO7926274826	KU	5	35 BRO	SP	CRE	ED,ID	TD		5/16/2083
2020 PO5208607662	KU	5	35 BRO	SP	CRE	ID	TD		5/17/2083
2020 PO5226707670	KU	5	35 BRO	SP	CRE	ID	TD		5/18/2083
2020 PO5216207600	KU	5	35 BRO	SP	CCA		V		5/19/2083
2020 PO5238307493	KU	6	30 BRO	SP	CRE	ID	TD		5/20/2083
2020 PO5236307593	KU	5	30 BRO	SP	CRE	ID	TD		5/21/2083
2020 PO5247107695	KU	4	40 BRO	SP	CRE	ID	TD		5/22/2083
2020 PO5402908401	KU	4	40 BRO	SP	CCA		V		5/23/2083
2020 PO9388694267	KU	5	30 ACW	DF	CRE	ED,ID	TD		5/24/2083
2020 PO9382494265	KU	4	40 ACW	SP	CRE		V		5/25/2083
2020 PO9512893921	KU	4	40 XXX	SP	CRE	ED,ID	TD		5/26/2083
2020 PO6021348223	KU	4	40 ACE	SP	CRE	ED,ID	BD		5/27/2083
2020 PO6017848054	KU	4	40 ACE	SP	CRE	ED,ID	BD		5/28/2083
2020 PO9503193892	KU	4	30 XXX	SP	CRE	ED,ID	TD		5/29/2083
2020 PO9453993706	KU	4	40 XXX	SP	CRE	ED,ID	TD		5/30/2083
2020 PO9465494078	KU	4	40 XXX	SP	CRE	ED,ID	TD		5/31/2083
2020 PO9499993582	KU	4	40 XXX	SP	CRE	ED,ID	TD		6/1/2083
2020 PO9468393808	KU	4	40 XXX	SP	CRE	ED,ID	TD		6/2/2083
2020 PO9525993617	KU	4	40 XXX	SP	CRE	ED,ID	TD		6/3/2083
2020 PO9475893802	KU	6	30 XXX	SP	CRE	ED,ID	TD		6/4/2083
2020 PO9487093857	KU	6	30 XXX	SP	CRE	ED,ID	TD		6/5/2083
2020 PO4644527777	C	4	40 BRO	SP	CRE		V		6/6/2083
2020 PO4687728273	KU	4	40 BRO	SP	CRE	ED,ID	TD		6/7/2083
2020 PO5604446786	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD		6/8/2083
2020 PO4663228388	F	4	40 BRO	SP	CRE		V		6/9/2083
2020 PO7334485659	KU	6	30 BRN	SP	CRE	ED,ID	TD		6/10/2083
2020 PO6883494739	KU	3	30 XXX	SP	CRE	RB	BX	PX	6/11/2083
2020 PO7327885564	F	3	50 BRN	SP	CRE		V		6/12/2083
2020 PO7926274826A	KU	4	40 BRO	SP	CCA		V		6/13/2083
2020 PO7914975398	KU	5	35 BRO	SP	CCA		V		6/14/2083
2020 PO7279386322-A	KU	4	40 BRN	SP	CRE	ED,HH,ID,IP,RB	BX	PX	6/15/2083
2020 PO7292686190	F	2	45 BRN	SP	CRE	ED,EP,HH,ID,IP,RB	VX	PX	6/16/2083
2020 PO7288586166	KU	3	45 BRN	SP	CRE	ED,HH,ID,IP,RB	BX	PX	6/17/2083
2020 PO7281286376	F	4	40 BRN	SP	CRE		V		6/18/2083
2020 PO7279386322	KU	3	45 BRN	SP	CCA		V		6/19/2083
2020 PO7275486470	KU	5	35 BRN	SP	CRE	ED,ID	TD		6/20/2083
2020 PO7271286447	KU	3	50 BRN	SP	CCA		V		6/21/2083

2020 PO7922075274	KU	5	35 BRO	SP	CRE		ED,ID	TD		6/22/2083
2020 PO7939475070	KU	6	30 BRO	SP	CRE			B		6/23/2083
2020 PO7938774755	F	4	40 BRO	SP	P			V		6/24/2083
2020 PO7948274812	KU	6	30 BRO	SP	CRE		ED,ID	TD		6/25/2083
2020 PO7933474701	KU	4	40 BRO	SP	CRE		ED,ID	TD		6/26/2083
2020 PO7912474576	KU	5	35 BRO	SP	CRE		ID	BD		6/27/2083
2020 PO5347007046	KU	5	30 XXX	SP	CRE		ID	BD		6/28/2083
2020 PO5354507115	KU	4	40 BRN	SP	CRE		ED,ID,IP	TX	RR	6/29/2083
2020 PO5373707165	KU	5	30 XXX	SP	CRE		ED,ID	TD		6/30/2083
2020 PO5366107242	KU	4	40 KOP	SP	CRE		ID	BD		7/1/2083
2020 PO8002377290	KU	4	40 BRO	SP	CRE		ED,ID	TD		7/2/2083
2020 PO7861276828	KU	6	30 BRO	SP	CCA			V		7/3/2083
2020 PO7448782422	KU	6	30 BRN	SP	CRE		ED,ID	BD		7/4/2083
2020 PO7459282538	KU	4	40 BRN	SP	CCA			V		7/5/2083
2020 PO7452082558	KU	6	30 BRN	SP	CCA			V		7/6/2083
2020 PO7438082553	KU	6	30 BRN	SP	CCA			V		7/7/2083
2020 PO7459382424	KU	5	35 BRN	SP	CRE		ED,ID	TD		7/8/2083
2020 PO7858276843	KU	5	35 BRO	SP	CRE		ED,ID	TD		7/9/2083
2020 PO7428482435	KU	5	35 BRN	SP	CRE		ED,ID	TD		7/10/2083
2020 PO7438982724	KU	4	45 BRN	SP	CCA			V		7/11/2083
2020 PO7559982414	KU	4	40 BRN	SP	CCA			V		7/12/2083
2020 PO7574982494	KU	4	40 BRN	SP	CCA			V		7/13/2083
2020 PO7852976241	F	4	40 BRO	SP	CRE			V		7/14/2083
2020 PO5382607514	KU	3	60 XXX	SP	CRE		ED,ID	TD		7/15/2083
2020 PO7860075971	KU	4	40 BRO	SP	CRE		ED,ID	TD		7/16/2083
2020 PO5395307491	KU	6	30 XXX	SP	CRE		ID	BD		7/17/2083
2020 PO5391707518	KU	4	45 XXX	SP	CRE		ED,ID	TD		7/18/2083
2020 PO5380007622	KU	4	45 XXX	SP	CRE		ID	BD		7/19/2083
2020 PO5375307666	KU	4	40 XXX	SP	CRE		ID	BD		7/20/2083
2020 PO5371807696	KU	3	40 XXX	SP	CRE		ED,ID	TD		7/21/2083
2020 PO5363607605	KU	2	50 XXX	SP	CRE		ED,ID	TD		7/22/2083
2020 PO5356807546	KU	4	40 XXX	SP	CRE		ED,ID	TD		7/23/2083
2020 PO5361507566	KU	6	30 XXX	SP	CRE		ID	BD		7/24/2083
2020 PO5347907427	KU	4	45 XXX	SP	CRE		ED,ID	TD		7/25/2083
2020 PO5336707278	KU	4	45 XXX	SP	CRE		ID	BD		7/26/2083
2020 PO5325407192	KU	4	40 XXX	SP	CRE		ED,ID	TD		7/27/2083
2020 PO7878675643	KU	4	40 BRO	SP	CRE		ED,ID	TD		7/28/2083
2020 PO7870075795	KU	4	45 BRO	SP	CRE		ED,ID	TD		7/29/2083
2020 PO7877975798	F	4	45 BRO	SP	CRE			V		7/30/2083
2020 PO7866075865	KU	4	40 BRO	SP	CRE		ED,ID	TD		7/31/2083
2020 PO7594283859	KU	5	35 BRN	SP	CRE			V		8/1/2083
2020 PO7602283863	KU	3	45 BRN	SP	CCA			V		8/2/2083
2020 PO7589283916	KU	4	45 BRN	SP	P		ED,ID	BD		8/3/2083
2020 PO7526685098	KU	4	40 BRN	SP	CRE		ED,ID	TD		8/4/2083
2020 PO7529185222	KU	4	40 BRN	SP	CRE		ED,ID	TD		8/5/2083
2020 PO7531285344	KU	5	35 BRN	SP	CCA			V		8/6/2083
2020 PO7524484202	KU	5	35 BRN	SP	CCA			V		8/7/2083

2020 PO7515484219	KU	4	45 BRN	SP	CCA		V	8/8/2083	
2020 PO7537783986	KU	4	45 BRN	SP	CRE	ED,ID	BD	8/9/2083	
2020 PO7549284077	KU	4	45 BRN	SP	CCA		V	8/10/2083	
2020 PO7591278939	KU	4	45 BRN	SP	CRE	ED,ID	BD	8/11/2083	
2020 PO7885075531	KU	4	40 BRO	SP	CRE	ID	BD	8/12/2083	
2020 PO9538054476	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD	8/13/2083	
2020 PO0172616807	KU	6	30 BRO	SP	CCA		V	8/14/2083	
2020 PO0632764645	KU	3	50 BRN	SP	CRE	ED,ID,IP	TD	8/15/2083	
2020 PO9537018272	KU	5	35 SWP	SP	CRE	ID	TD	8/16/2083	
2020 PO0401560742	KU	4	40 ACW	SP	CRE	ED,ID	BD	8/17/2083	
2020 PO1685547647	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	8/18/2083	
2020 PO1660147729	KU	4	40 BRN	SP	CRE	ID,IP	BD	8/19/2083	
2020 PO2139756800	KU	4	45 BRN	SP	CCA		V	8/20/2083	
2020 PO2289156748	KU	4	45 BRN	SP	CCA		V	8/21/2083	
2020 PO2267256909	KU	4	45 BRN	SP	CCA		V	8/22/2083	
2020 PO2245357071	KU	4	45 BRN	SP	CCA		V	8/23/2083	
2020 PO2223557233	KU	4	45 BRN	SP	CCA		V	8/24/2083	
2020 PO2230357385	KU	4	40 BRN	SP	CRE	ID	TD	8/25/2083	
2020 PO2207257234	KU	3	45 BRN	SP	CCA		V	8/26/2083	
2020 PO0634264613	KU	5	35 BRN	SP	P	ED	T	8/27/2083	
2020 PO2185257093	KU	4	45 BRN	SP	CRE	ID,IP	TD	8/28/2083	
2020 PO2123956698	KU	5	35 BRN	SP	CRE	ED,ID,RB	TX	RR	8/29/2083
2020 PO0657464798	KU	5	35 BRN	SP	P	ED	T	8/30/2083	
2020 PO0649264704	KU	5	35 BRN	SP	CCA		V	8/31/2083	
2020 PO0749764732	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	9/1/2083	
2020 PO0727464725-A	KU	3	45 BRN	SP	A		V	9/2/2083	
2020 PO0738664796	F	4	40 BRN	SP	A	RB	VX	RP1	9/3/2083
2020 PO0716664798	KU	6	30 BRN	SP	CRE	HH,RB	X	RP1	9/4/2083
2020 PO0727464725	KU	6	30 BRN	SP	CRE	ID	BD	9/5/2083	
2020 PO0702964725-A	KU	5	35 BRN	SP	CCA		V	9/6/2083	
2020 PO0691865001	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/7/2083	
2020 PO0691864954	KU	5	35 BRO	SP	CRE	ED	TD	9/8/2083	
2020 PO3685260524	KU	6	30 BRN	SP	CRE	ED,HH,RB	X	RP2	9/9/2083
2020 PO3688760472	KU	3	50 BRN	SP	CRE	ID,IP	BD	9/10/2083	
2020 PO3427363078	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	9/11/2083	
2020 PO9514254586	KU	2	50 BRO	SP	CCA		V	9/12/2083	
2020 PO9532654638	F	4	40 BRO	SP	CRE		V	9/13/2083	
2020 PO9750153554	KU	4	45 BRO	SP	CRE	ED,ID,SRC	TD	9/14/2083	
2020 PO9778053435	KU	2	40 BRO	SP	CRE	ED,ID,SRC	TD	9/15/2083	
2020 PO9721053680	KU	4	45 BRO	SP	CRE	ED,ID,SRC	TD	9/16/2083	
2020 PO9693753797	KU	4	45 BRO	SP	CRE	ED,ID,SRC	TD	9/17/2083	
2020 PO9666253918	KU	4	40 BRO	SP	CRE	ED,ID,IP,SRC	TD	9/18/2083	
2020 PO3911782517	F	6	25 BRN	SP	CRE		V	9/19/2083	
2020 PO1282633705	ODP	4	45 BRN	SP	CCA		V	9/20/2083	
2020 PO1285833617	ODP	4	45 BRN	SP	CCA		V	9/21/2083	
2020 PO1260433332	ODP	4	45 BRN	SP	CCA		V	9/22/2083	
2020 PO1249233401	ODP	5	35 BRN	SP	CRE		BD	9/23/2083	

2020 PO3990382973	F	3	45 BRN	SP	CCA		V	9/24/2083
2020 PO3912582514	F	4	40 BRN	SP	CRE		V	9/25/2083
2020 PO3995182996	F	4	40 BRN	SP	CRE		V	9/26/2083
2020 PO3913182528	F	4	40 BRN	SP	CCA		V	9/27/2083
2020 PO3914282553	LGE	4	40 BRN	SP	CRE	ID	BD	9/28/2083
2020 PO1100335352	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TD	9/29/2083
2020 PO1099135192	ODP	3	55 XXX	SP	CRE	ED,ID	TD	9/30/2083
2020 PO1102335652	ODP	4	40 XXX	SP	CRE	ED,ID	TD	10/1/2083
2020 PO3993882994	F	4	40 BRN	SP	CCA		V	10/2/2083
2020 PO3914282569	F	6	25 BRN	SP	CRE		V	10/3/2083
2020 PO3914982566	F	4	40 BRN	SP	CRE		V	10/4/2083
2020 PO9643954016	KU	4	40 BRO	SP	CCA		V	10/5/2083
2020 PO3939482987	F	5	25 BRO	SP	P		V	10/6/2083
2020 PO3938382998	F	4	40 BRO	SP	P		V	10/7/2083
2020 PO3937083003	F	4	40 BRO	SP	CCA		V	10/8/2083
2020 PO3936983001	F	5	30 BRO	SP	P		V	10/9/2083
2020 PO3935883009	F	4	40 BRO	SP	A		V	10/10/2083
2020 PO3935683006	F	4	30 BRO	SP	P		V	10/11/2083
2020 PO3934583015	F	4	40 BRO	SP	P		V	10/12/2083
2020 PO3933283021	F	4	40 BRO	SP	P		V	10/13/2083
2020 PO3931783024	F	4	30 BRO	SP	P		V	10/14/2083
2020 PO3931983027	F	4	40 BRO	SP	A		V	10/15/2083
2020 PO3930683033	F	4	40 BRO	SP	P		V	10/16/2083
2020 PO3929483039	F	4	40 BRO	SP	CCA		V	10/17/2083
2020 PO3928083045	LGE	4	40 BRO	SP	CCA		V	10/18/2083
2020 PO0236735287	ODP	4	40 ACW	SP	CRE	ED,ID	TD	10/19/2083
2020 PO0229035290	ODP	4	40 BRN	SP	CRE	ED,ID	TD	10/20/2083
2020 PO1787440040	ODP	5	35 KOP	SP	CRE	ED,ID	TD	10/21/2083
2020 PO1768839912	ODP	5	35 KOP	SP	CRE	ED,ID	TD	10/22/2083
2020 PO1748939773	ODP	5	35 KOP	SP	CRE	ED,ID	TD	10/23/2083
2020 PO4010982797	LGE	4	35 BRN	SP	CRE	ED,ID	TD	10/24/2083
2020 PO4010182785	LGE	4	40 BRN	SP	A	ED,ID	TD	10/25/2083
2020 PO0228535677	ODP	5	40 XXX	SP	CRE	ED,ID	TD	10/26/2083
2020 0214935860a	ODP	4	40 XXX	SP	CRE	ED,ID	TD	10/27/2083
2020 PO4010982763	LGE	4	35 BRN	SP	S		V	10/28/2083
2020 PO4010682768	LGE	4	40 BRN	SP	P	ED,ID	TD	10/29/2083
2020 PO4011482772	LGE	3	50 BRN	SP	CRE	ED,ID	BD	10/30/2083
2020 PO4011582768	F	3	45 BRN	SP	S		V	10/31/2083
2020 PO4008482752	F	3	45 BRN	SP	S		V	11/1/2083
2020 PO0220835548	F	3	45 XXX	SP	P		V	11/2/2083
2020 0220735548a	ODP	2	50 XXX	SP	CCA		V	11/3/2083
2020 0204035453a	ODP	4	40 XXX	SP	CCA		V	11/4/2083
2020 PO0204035453	ODP	2	55 XXX	SP	CCA		V	11/5/2083
2020 PO0190935403	ODP	6	40 XXX	SP	CCA		V	11/6/2083
2020 PO4008482752	F	4	40 BRN	SP	CRE		V	11/7/2083
2020 PO4008282759	LGE	4	35 BRN	SP	S		V	11/8/2083
2020 PO4007782752	F	3	50 BRN	SP	CRE		V	11/9/2083

2020 PO4687688535	LGE	4	35 BRN	SP	CRE	ED,ID	BD		11/10/2083
2020 PO4847687763	LGE	4	40 BRO	SP	CRE	ED	BD		11/11/2083
2020 PO4846787750	LGE	4	40 BRO	SP	CRE	ED	BD		11/12/2083
2020 PO4846687749	LGE	4	40 BRO	SP	CRE	ED	BD		11/13/2083
2020 PO4686188525	LGE	4	40 BRN	SP	A	ED,ID	BD		11/14/2083
2020 PO4687788509	LGE	6	25 BRN	SP	CRE	ED,ID	BD		11/15/2083
2020 PO9381172637	F	5	30 OTH	SP	P		V		11/16/2083
2020 PO9377372610	F	4	40 OTH	SP	P		V		11/17/2083
2020 PO9364672518	F	4	40 OTH	SP	P		V		11/18/2083
2020 PO9361872438	F	4	40 OTH	SP	P		V		11/19/2083
2020 PO9358972475	F	3E	40E OTH	SP	A		V		11/20/2083
2020 PO9350772414	F	4	40 OTH	SP	P		V		11/21/2083
2020 PO7012115487	KU	4	40 XXX	SP	CRE	ID,RB	BX	RP1	11/22/2083
2020 PO4682788599	F	3	45 BRN	SP	A		V		11/23/2083
2020 PO4683388596	LGE	4	40 BRN	SP	A	ED,ID	TD		11/24/2083
2020 PO4683788607	LGE	4	35 BRN	SP	CRE	ED,ID	TD		11/25/2083
2020 PO1397037367	ODP	5	35 KOP	SP	CRE		V		11/26/2083
2020 PO4684688596	LGE	4	35 BRN	SP	CRE	ED,HH,ID,SRS	TX	RR	11/27/2083
2020 PO1390837415	ODP	4	45 KOP	SP	S		V		11/28/2083
2020 PO3926683034	F	4	40 BRO	SP	P		V		11/29/2083
2020 PO3925883023	F	3	45 BRO	SP	P		V		11/30/2083
2020 PO3925083014	F	4	40 BRO	SP	P		V		12/1/2083
2020 PO3924483019	F	5	25 BRO	SP	P		V		12/2/2083
2020 PO3924583073	F	4	40 BRO	SP	P		VX	RP2	12/3/2083
2020 PO3922982999	F	5	35 BRO	SP	P		V		12/4/2083
2020 PO3923782994	F	4	45 BRO	SP	A		V		12/5/2083
2020 PO1383137356	ODP	6	30 KOP	SP	S	ED,MD,SRC	T		12/6/2083
2020 PO3932382168	LGE	1	55 BRN	SP	CRE	ED,ID	BD		12/7/2083
2020 PO3933082183	LGE	UNK	115 BRN	AL	CRE		V		12/8/2083
2020 PO3933582198	LGE	UNK	100 BRN	SP	CRE	ED,ID	BD		12/9/2083
2020 PO3934582221	LGE	1	100E BRN	SP	CRE		V		12/10/2083
2020 PO3934182212	LGE	UNK	50 BRN	SP	CRE	ED,ID	BD		12/11/2083
2020 PO3935682248	LGE	1	50 BRN	SP	CRE	ED,ID	BD		12/12/2083
2020 PO3934982230	LGE	UNK	105 BRN	SP	CRE	ED,ID	BD		12/13/2083
2020 PO3936082258	LGE	UNK	110 BRN	AL	CRE		V		12/14/2083
2020 PO4006082737	LGE	4	35 BRN	SP	A	ED,ID	TD		12/15/2083
2020 PO4006882751	F	1	50 BRN	SP	S		V		12/16/2083
2020 PO4006382751	F	1	50 BRN	SP	S		V		12/17/2083
2020 PO4005282750	F	4	40 BRN	SP	CRE		V		12/18/2083
2020 PO0214935860	ODP	2	50 XXX	SP	A	ED,ID	TD		12/19/2083
2020 0226736065a	ODP	4	40 BRN	SP	CCA		V		12/20/2083
2020 0253736460a	ODP	4	40 XXX	SP	CCA		V		12/21/2083
2020 PO0226736065	ODP	2	50 XXX	SP	A	ED,ID	TD		12/22/2083
2020 PO4004882779	LGE	4	35 BRN	SP	CCA		V		12/23/2083
2020 PO4004182756	F	4	30 BRN	SP	A		V		12/24/2083
2020 PO4004182750	F	3	45 BRN	SP	S		V		12/25/2083
2020 PO4003782744	F	4	35 BRN	SP	A		V		12/26/2083

2020	PO3923082982	F	4	40 BRO	SP	P		V			12/27/2083
2020	PO3922482986	F	5	25 BRO	SP	A		V			12/28/2083
2020	PO6980815384	KU	4	40 XXX	SP	CRE	ID	BD			12/29/2083
2020	PO7431116293	KU	4	40 XXX	SP	CRE	ID	BD			12/30/2083
2020	PO7468616131	KU	4	40 XXX	SP	CCA		V			12/31/2083
2020	PO7503915986	KU	4	40 XXX	SP	CCA		V			1/1/2084
2020	7504215862	F	5	30 XXX	SP	CRE	ID,RB	BX	RP1		1/2/2084
2020	PO7382116506	KU	4	40 XXX	SP	CRE	ID,RB	BX	PX		1/3/2084
2020	PO7344716931	KU	4	40 XXX	SP	CCA		V			1/4/2084
2020	PO7315916804	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD			1/5/2084
2020	PO7314316738	KU	5	35 XXX	SP	CCA		V			1/6/2084
2020	PO7247116522	KU	4	40 XXX	SP	CRE	ID	BD			1/7/2084
2020	PO4820888408	LGE	4	40 BRO	SP	CRE	ED	BD			1/8/2084
2020	PO4821288395	LGE	4	40 BRO	SP	CRE	ED	TD			1/9/2084
2020	PO482188381	LGE	UNK	45 BRO	SP	CRE	ED	TD			1/10/2084
2020	PO4821488342	LGE	4	35 BRO	SP	CRE	ED	BD			1/11/2084
2020	PO4822388344	LGE	4	30 BRO	SP	CRE	ED	BD			1/12/2084
2020	PO4822988362	LGE	4	40 BRO	SP	CCA		V			1/13/2084
2020	PO3999382756	F	4	40 BRN	SP	CRE		V			1/14/2084
2020	PO3919982869	LGE	4	35 BRO	SP	P	ID	BD			1/15/2084
2020	PO3919682873	F	4	40 BRO	SP	CCA		V			1/16/2084
2020	PO3919082869	F	6	25 BRO	SP	A		V			1/17/2084
2020	PO3998082657	F	4	40 BRN	SP	CRE		V			1/18/2084
2020	PO3997182746	F	4	40 BRN	SP	CRE		V			1/19/2084
2020	PO3995082742	F	4	40 BRN	SP	S		V			1/20/2084
2020	PO3995382748	F	3	45 BRN	SP	S		V			1/21/2084
2020	PO3995882759	F	4	40 BRN	SP	A		V			1/22/2084
2020	PO0616864497	KU	3	50 BRN	SP	P	ED	T			1/23/2084
2020	PO0617364237	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD			1/24/2084
2020	PO0602264273	KU	3	50 BRN	SP	CRE	ED,ID,IP	TD			1/25/2084
2020	PO0618064070	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD			1/26/2084
2020	PO0605364336	KU	5	35 BRN	SP	P	ED	T			1/27/2084
2020	PO0600364214	KU	3	50 BRN	SP	P		T			1/28/2084
2020	PO0597064091	KU	3	50 BRN	SP	CRE	ED,ID,IP	TD			1/29/2084
2020	PO0602264034	KU	6	30 BRN	SP	P	ED	T			1/30/2084
2020	PO0601263970-A	KU	5	35 BRN	SP	CRE	ID,RB	X	RP1		1/31/2084
2020	PO0601263970	KU	3	45 BRN	SP	CRE	ED,ID,RB	X	RP1		2/1/2084
2020	PO0595563911	KU	3	45 BRN	SP	CCA		V			2/2/2084
2020	PO0629263835	KU	5	35 BRN	SP	CCA		V			2/3/2084
2020	PO3928884959	KU	4	40 KOP	SP	S		V			2/4/2084
2020	PO3940684813	KU	2	50 KOP	DF	CRE	ED,ID,IP	TD			2/5/2084
2020	PO3943284815	KU	2	45 KOP	SP	CRE	ED,ID	TD			2/6/2084
2020	PO3957584685	KU	5	30 KOP	SP	CRE	ED,ID,IP	TD			2/7/2084
2020	PO3946084227	KU	3	45 KOP	ST	CCA		V			2/8/2084
2020	PO3943884226	KU	3	50 KOP	ST	CCA		V			2/9/2084
2020	PO3947084062	KU	2	55 KOP	ST	S		V			2/10/2084
2020	PO3944384061	KU	2	65 KOP	ST	S		V			2/11/2084

2020 PO3962883463	KU	4	40 KOP	SP	S		V	2/12/2084
2020 PO7805760599	F	4	40 XXX	SP	A		V	2/13/2084
2020 PO7814260475	KU	3	45 XXX	SP	CCA		V	2/14/2084
2020 PO7786660267	KU	4	40 XXX	SP	CRE	ED,ID	TD	2/15/2084
2020 PO7775560245	KU	5	30 XXX	SP	CRE	ED,ID	TD	2/16/2084
2020 PO7762860229	KU	5	35 XXX	SP	CCA		V	2/17/2084
2020 PO7753360364	KU	5	35 XXX	SP	CCA		V	2/18/2084
2020 PO9241071645	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD	2/19/2084
2020 PO9243671478	KU	6	30 OTH	SP	CCA		V	2/20/2084
2020 PO9243271552	KU	6	30 OTH	SP	CRE	ED,ID,SRS	TD	2/21/2084
2020 PO8536166223	KU	4	40 XXX	SP	CCA		V	2/22/2084
2020 PO8555366348	KU	4	40 XXX	SP	CCA		V	2/23/2084
2020 PO8584266590	KU	4	40 XXX	SP	CCA		V	2/24/2084
2020 PO0461779272	KU	4	45 XXX	SP	CRE	ED,ID	TD	2/25/2084
2020 PO0465279291	KU	4	45 XXX	SP	CRE	ED,ID	TD	2/26/2084
2020 PO0494279446	KU	2	55 XXX	SP	CCA		V	2/27/2084
2020 PO0529679382	KU	2	50 XXX	SP	CRE	ED,ID	TD	2/28/2084
2020 PO0545979232	KU	2	50 XXX	SP	CRE	ED,ID	TD	2/29/2084
2020 PO4474388824	KU	4	45 KOP	DF	CRE	ED,ID	TD	3/1/2084
2020 PO4437988606	KU	4	45 KOP	SP	CRE	ID	BD	3/2/2084
2020 PO4443688378	KU	4	40 KOP	SP	CRE	ED,ID	TD	3/3/2084
2020 PO4449488224	KU	3	45 KOP	SP	S		V	3/4/2084
2020 PO4458688025	KU	4	40 KOP	SP	CRE	ED,ID	TD	3/5/2084
2020 PO3897982345	F	3	45 BRO	SP	CCA		V	3/6/2084
2020 PO3898982334	F	4	40 BRO	SP	CRE		V	3/7/2084
2020 PO3899282340	F	4	40 BRO	SP	CRE		V	3/8/2084
2020 PO3933082699	LGE	4	35 BRO	SP	CCA		V	3/9/2084
2020 PO3932382666	F	4	40 BRO	SP	CCA		V	3/10/2084
2020 PO3934382662	F	4	35 BRO	SP	CCA		V	3/11/2084
2020 PO3933082663	F	2	50 BRO	SP	CRE		V	3/12/2084
2020 PO3933182670	F	4	30 BRO	SP	CCA		V	3/13/2084
2020 PO3899982355	F	4	40 BRO	SP	CCA		V	3/14/2084
2020 PO3900882370	F	4	40 BRO	SP	CCA		V	3/15/2084
2020 PO3901682385	F	4	40 BRO	SP	CRE		V	3/16/2084
2020 PO2836350027	ODP	6	35 UNK	SP	CRE	ED,ID	TD	3/17/2084
2020 PO2848450045	F	7	35 UNK	SP	CRE		V	3/18/2084
2020 PO2828850117	ODP	6	30 UNK	SP	CCA	ED,ID	TD	3/19/2084
2020 PO3903282410	F	4	40 BRO	SP	CCA		V	3/20/2084
2020 PO3903982423	F	4	40 BRO	SP	CRE		V	3/21/2084
2020 PO3908082451	F	4	40 BRO	SP	CCA		V	3/22/2084
2020 PO3906782459	F	4	40 BRO	SP	CCA		V	3/23/2084
2020 PO3905382467	F	4	40 BRO	SP	CCA		V	3/24/2084
2020 PO3921182663	LGE	4	30 BRO	SP	CCA		V	3/25/2084
2020 PO3947482723	LGE	4	30 BRO	SP	CRE	ED,ID	TD	3/26/2084
2020 PO3905582448	F	4	40 BRO	SP	CCA		V	3/27/2084
2020 PO3902382396	F	4	40 BRO	SP	CCA		V	3/28/2084
2020 PO3904782435	F	4	40 BRO	SP	CCA		V	3/29/2084

2020 PO3931782669	F	3	50 BRO	SP	CCA		V	3/30/2084
2020 PO3931982676	F	4	40 BRO	SP	CCA		V	3/31/2084
2020 PO3932682691	F	4	40 BRO	SP	CCA		V	4/1/2084
2020 PO3933282702	F	4	40 BRO	SP	CCA		V	4/2/2084
2020 PO3933782713	F	4	40 BRO	SP	CCA		V	4/3/2084
2020 PO3934282724	F	3	45 BRO	SP	CCA		V	4/4/2084
2020 PO3934782734	F	4	40 BRO	SP	CCA		V	4/5/2084
2020 PO3935382747	F	4	40 BRO	SP	CRE		V	4/6/2084
2020 PO3942482751	F	3	45 BRO	SP	CRE		V	4/7/2084
2020 PO4092283060	LGE	3	45 CAH	SP	P	ED,ID	TD	4/8/2084
2020 PO3943482746	LGE	3	45 BRO	SP	CCA		V	4/9/2084
2020 PO3944982740	LGE	3	45 BRO	SP	P	ED	T	4/10/2084
2020 PO3947382729	LGE	3	45 BRO	SP	P		T	4/11/2084
2020 PO3946782732	LGE	3	45 BRO	SP	P		T	4/12/2084
2020 PO3948382724	LGE	3	45 BRO	SP	P	ED,ID	TD	4/13/2084
2020 PO4034982585	F	4	40 BRN	SP	CRE		V	4/14/2084
2020 PO4035882574	F	4	40 BRN	SP	CRE		V	4/15/2084
2020 PO8152442249	LGE	4	35 CAH	SP	CRE	ED,ID	BD	4/16/2084
2020 PO8155742075	LGE	4	35 CAH	SP	CRE	ED,ID	TD	4/17/2084
2020 PO8157741934	LGE	4	35 CAH	SP	CCA		V	4/18/2084
2020 PO4036982569	F	4	40 BRN	SP	CRE		V	4/19/2084
2020 PO4037482559	F	4	40 BRN	SP	CCA		V	4/20/2084
2020 PO4037082551	F	4	40 BRN	SP	CCA		V	4/21/2084
2020 PO4035982542	F	4	40 BRN	SP	CRE		V	4/22/2084
2020 PO4835303142	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/23/2084
2020 PO4032582557	F	4	40 BRN	SP	CRE		V	4/24/2084
2020 PO4091583045	LGE	3	45 CAH	SP	P	ED,ID	TD	4/25/2084
2020 PO4092383047	LGE	3	45 CAH	SP	CCA		V	4/26/2084
2020 PO4092783048	LGE	3	50 CAH	SP	P		V	4/27/2084
2020 PO8138042221	LGE	4	35 CAH	SP	P	ED,ID	BD	4/28/2084
2020 PO8123442200	LGE	4	45 CAH	SP	CRE	ED,ID	BD	4/29/2084
2020 PO4033382553	F	4	40 BRN	SP	CRE		V	4/30/2084
2020 PO4033982542	F	4	40 BRN	SP	CRE		V	5/1/2084
2020 PO2214641414	ODP	4	40 KOP	SP	CRE	ED,ID	TD	5/2/2084
2020 PO2154141456	ODP	6	30 KOP	SP	A	ED,ID	TD	5/3/2084
2020 PO4033282525	LGE	4	30 BRN	SP	A	ED,ID	TD	5/4/2084
2020 PO2189341313	ODP	4	40 KOP	SP	A	ED,ID	TD	5/5/2084
2020 PO2069842406	ODP	6	30 KOP	SP	S		V	5/6/2084
2020 PO2067242514	ODP	4	40 KOP	SP	CRE	ED,ID	TD	5/7/2084
2020 PO2033723488	ODP	4	40 XXX	SP	CRE	ID,IP	TD	5/8/2084
2020 PO4033782522	F	4	40 BRN	SP	CRE		V	5/9/2084
2020 PO2070323428	ODP	4	40 XXX	SP	CRE	ID	TD	5/10/2084
2020 PO4034882531	F	4	40 BRN	SP	CRE		V	5/11/2084
2020 PO4035882521	F	4	40 BRN	SP	CRE		V	5/12/2084
2020 PO8126042057	LGE	4	35 CAH	SP	A	ED,ID	TD	5/13/2084
2020 PO8127741929	LGE	4	45 CAH	SP	P	ED,ID	BD	5/14/2084
2020 PO4036882517	F	4	40 BRN	SP	CRE		V	5/15/2084

Business Use

2020 PO3952182707	LGE	4	40 BRO	SP	CCA		V	5/16/2084
2020 PO3952982704	LGE	3	45 BRO	SP	CCA		V	5/17/2084
2020 PO3953182703	LGE	3	45 BRO	SP	CCA		V	5/18/2084
2020 PO3955182742	LGE	4	30 BRO	SP	CCA		V	5/19/2084
2020 PO3954982736	LGE	3	45 BRO	SP	CCA		V	5/20/2084
2020 PO3954182718	LGE	4	40 BRO	SP	CCA		V	5/21/2084
2020 PO3953482701	LGE	3	45 BRO	SP	CCA	ED	V	5/22/2084
2020 PO3950082738	LGE	4	35 BRO	SP	CCA		V	5/23/2084
2020 PO3938182701	LGE	4	30 BRO	SP	CCA		V	5/24/2084
2020 PO3939682685	LGE	4	30 BRO	SP	CCA		V	5/25/2084
2020 PO3939982704	F	3	45 BRO	SP	P		V	5/26/2084
2020 PO3939282689	F	3	45 BRO	SP	CRE		V	5/27/2084
2020 PO3938482675	F	3	45 BRO	SP	A		V	5/28/2084
2020 PO3937882662	F	4	35 BRO	SP	CCA		V	5/29/2084
2020 PO3940282711	F	3	45 BRO	SP	P		V	5/30/2084
2020 PO3934182658	F	3	50 BRO	SP	CCA		V	5/31/2084
2020 PO4038082521	F	4	40 BRN	SP	CRE		V	6/1/2084
2020 PO4039382526	F	4	40 BRN	SP	CRE		V	6/2/2084
2020 PO4040282532	F	4	40 BRN	SP	CRE		V	6/3/2084
2020 PO1961244111	ODP	4	40 BRN	SP	CRE	ED,ID	TD	6/4/2084
2020 PO1943844456	ODP	4	40 BRN	SP	CRE		V	6/5/2084
2020 PO1956044199	ODP	4	40 BRN	SP	CRE		V	6/6/2084
2020 PO1939344775	ODP	5	35 BRN	SP	CRE	ED,ID	TD	6/7/2084
2020 PO1945644605	ODP	6	30 BRN	SP	CRE	ED,ID,SRS	TD	6/8/2084
2020 PO1947744888	F	4	40 BRN	SP	CCA		V	6/9/2084
2020 PO1944745062	ODP	4	40 UNK	SP	CRE	ED,ID	TD	6/10/2084
2020 PO1963045703	ODP	5	35 UNK	SP	CRE	ED,ID,SRS	TD	6/11/2084
2020 PO1952245342	ODP	3	35 UNK	SP	P		V	6/12/2084
2020 PO1956345085	ODP	6	30 UNK	SP	CRE		V	6/13/2084
2020 PO1968845897	ODP	5	35 UNK	SP	CRE	ED,ID	TD	6/14/2084
2020 PO4080583129	LGE	3	45 BRN	SP	P	ED,ID,IP	BD	6/15/2084
2020 PO4765288789	LGE	4	30 BRN	SP	CRE	ED,ID	BD	6/16/2084
2020 PO4845500418	KU	4	40 BRN	SP	CRE	ED,ID	TD	6/17/2084
2020 PO5108308769	F	4	40 ACE	SP	P		V	6/18/2084
2020 PO3977308559	KU	2	60 BRO	SP	CRE	ID,IP	BD	6/19/2084
2020 PO3963708509	KU	2	50 BRO	SP	CRE	ID,IP	BD	6/20/2084
2020 PO5092409484	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	6/21/2084
2020 PO5058809299	F	3	40 ACE	SP	P		V	6/22/2084
2020 PO5062709430	F	4	40 ACE	SP	P		V	6/23/2084
2020 PO4078483120	LGE	3	50 BRN	SP	A	ED,ID	TD	6/24/2084
2020 PO3961508568	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	6/25/2084
2020 PO3919810211	KU	3	45 BRO	SP	CRE		V	6/26/2084
2020 PO5085010006	F	4	40 ACE	SP	CRE		V	6/27/2084
2020 PO5096410305	F	4	40 ACE	SP	CRE		V	6/28/2084
2020 PO5014210472	F	4	40 ACE	SP	CRE		V	6/29/2084
2020 PO5025810772	F	4	40 ACE	SP	CCA		V	6/30/2084
2020 PO5029310859	F	4	40 ACE	SP	CRE		V	7/1/2084

2020 PO5025610925	F	4	40 ACE	SP	CRE		V			7/2/2084
2020 PO5020610809	F	4	40 ACE	SP	A		V			7/3/2084
2020 PO5015610691	F	4	40 ACE	SP	CRE		V			7/4/2084
2020 PO5010710578	F	4	40 ACE	SP	CRE		V			7/5/2084
2020 PO5004810443	F	4	40 ACE	SP	CRE		V			7/6/2084
2020 PO4998610296	F	4	40 ACE	SP	CRE		V			7/7/2084
2020 PO5033811126	F	4	40 ACE	SP	CCA		V			7/8/2084
2020 PO5035511233	F	4	40 ACE	SP	CRE		V			7/9/2084
2020 PO5090710154	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX		RP1	7/10/2084
2020 PO4223702645	LGE	4	35 BRO	SP	CCA		V			7/11/2084
2020 PO4216002846	F	3	45 BRO	SP	CCA		V			7/12/2084
2020 PO4227602663	F	3	50 BRO	SP	A		V			7/13/2084
2020 PO4205803005	F	3	45 BRO	SP	A		V			7/14/2084
2020 PO4715588960	LGE	4	40 BRO	SP	CRE	ED,ID	TD			7/15/2084
2020 PO4716488941	LGE	4	35 BRO	SP	CCA		V			7/16/2084
2020 PO4740689180	F	3	45 BRO	SP	CCA		V			7/17/2084
2020 PO4739389180	F	3	45 BRO	SP	CCA		V			7/18/2084
2020 PO4736389172	F	3	45 BRO	SP	CCA		V			7/19/2084
2020 PO4737789180	F	3	45 BRO	SP	CCA		V			7/20/2084
2020 PO5101610442	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX		RP1	7/21/2084
2020 PO5090810485	F	4	40 ACE	SP	CRE		V			7/22/2084
2020 PO4738989245	F	3	45 BRO	SP	CCA		V			7/23/2084
2020 PO4736389232	F	3	45 BRO	SP	CCA		V			7/24/2084
2020 PO4737589238	F	4	40 BRO	SP	CCA		V			7/25/2084
2020 PO5043210998	F	4	40 ACE	SP	P		V			7/26/2084
2020 PO5048909879	F	4	40 ACE	SP	CRE		V			7/27/2084
2020 PO5054810026	F	4	40 ACE	SP	CRE		V			7/28/2084
2020 PO5039310070	F	5	35 ACE	SP	P		V			7/29/2084
2020 PO5008910339	F	4	40 ACE	SP	P		V			7/30/2084
2020 PO1447224069	ODP	4	45 XXX	SP	CCA	ED	T			7/31/2084
2020 PO1446623827	ODP	4	45 XXX	SP	CRE	ID	TD			8/1/2084
2020 PO1472223725	F	4	40 XXX	SP	A		V			8/2/2084
2020 PO1308021270	ODP	4	45 XXX	SP	CRE	ID	TD			8/3/2084
2020 PO1300521083	ODP	4	40 XXX	SP	CRE	ID	TD			8/4/2084
2020 PO1289621210	ODP	4	40 XXX	SP	CRE	ID	TD			8/5/2084
2020 PO1276921344	ODP	4	40 XXX	SP	CRE	ID	BD			8/6/2084
2020 PO4734188898	LGE	4	40 BRO	SP	CRE		B			8/7/2084
2020 PO4733388929	LGE	4	30 BRO	SP	CRE	ED,ID	BD			8/8/2084
2020 PO5020010621	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX		PX	8/9/2084
2020 PO5053010956	F	4	40 ACE	SP	P		V			8/10/2084
2020 PO5061510921	F	4	40 ACE	SP	CRE		V			8/11/2084
2020 PO5074110867	F	4	40 ACE	SP	CRE		V			8/12/2084
2020 PO5133910636	F	4	40 ACE	SP	CRE		V			8/13/2084
2020 PO5040711182	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX		PX	8/14/2084
2020 PO5030411037	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX		PX	8/15/2084
2020 PO5091710772	F	4	40 ACE	SP	P		V			8/16/2084
2020 PO5067011013	F	5	35 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX		PX	8/17/2084

2020 PO5106410708	F	4	40 ACE	SP	P		V		8/18/2084
2020 PO5121010644	F	4	40 ACE	SP	P		V		8/19/2084
2020 PO1266221479	ODP	4	40 XXX	SP	CRE	ID	TD		8/20/2084
2020 PO1296922084	F	4	40 XXX	SP	CCA		V		8/21/2084
2020 PO1287421855	ODP	4	40 XXX	SP	CRE		V		8/22/2084
2020 PO1254421678	ODP	4	40 XXX	SP	CCA		T		8/23/2084
2020 PO1309621954	F	4	40 XXX	SP	A		V		8/24/2084
2020 PO1335821491	F	4	40 XXX	SP	A		V		8/25/2084
2020 PO1322021648	ODP	4	40 XXX	SP	CRE	ID	TD		8/26/2084
2020 PO1388921665	ODP	6	30 XXX	SP	CRE		V		8/27/2084
2020 PO1403522001	ODP	5	30 XXX	SP	CRE	ID	TD		8/28/2084
2020 PO1357122363	F	4	40 XXX	SP	A		V		8/29/2084
2020 PO1292223009	ODP	4	45 XXX	SP	CRE		V		8/30/2084
2020 PO1302022722	ODP	4	40 XXX	SP	CRE	HH	X	RP1	8/31/2084
2020 PO1310923277	ODP	4	40 XXX	SP	CRE	ID	BD		9/1/2084
2020 PO4730588966	F	4	40 BRO	SP	CRE		V		9/2/2084
2020 PO4729688979	F	4	40 BRO	SP	CRE		V		9/3/2084
2020 PO4728988991	F	4	40 BRO	SP	CRE		V		9/4/2084
2020 PO4728089003	F	4	40E BRO	SP	CRE		V		9/5/2084
2020 PO4727189020	F	4	40E BRO	SP	A		V		9/6/2084
2020 PO4726589030	F	4	40E BRO	SP	CRE		V		9/7/2084
2020 PO4726589030	F	4	40E BRO	SP	CRE		V		9/8/2084
2020 PO4727489036	F	4	40E BRO	SP	CRE		V		9/9/2084
2020 PO4728689044	F	4	40E BRO	SP	CRE		V		9/10/2084
2020 PO1331823151	ODP	4	40 XXX	SP	CRE	ID	TD		9/11/2084
2020 PO1345622805	ODP	5	35 XXX	SP	CRE		V		9/12/2084
2020 PO1353523134	ODP	4	40 XXX	SP	CRE	ID	TD		9/13/2084
2020 PO1378224119	ODP	4	40 XXX	SP	CRE	ID	BD		9/14/2084
2020 PO1641122493	ODP	5	35 XXX	SP	CRE		V		9/15/2084
2020 PO4729589050	F	3	45E BRO	SP	CCA		V		9/16/2084
2020 PO4732589070	F	4	40 BRO	SP	CCA		V		9/17/2084
2020 PO1308050904	F	3	45 BRO	SP	CCA		V		9/18/2084
2020 PO4731489079	LGE	3	50 BRO	SP	CCA		V		9/19/2084
2020 PO4730289037	F	4	40 BRO	SP	CCA		V		9/20/2084
2020 PO4730689031	F	3	45 BRO	SP	CCA		V		9/21/2084
2020 PO4732889058	F	4	40 BRO	SP	A		V		9/22/2084
2020 PO4731389020	F	4	40 BRO	SP	CCA		V		9/23/2084
2020 PO4736288978	F	4	40 BRO	SP	CRE	ED,HH,ID,RB	VX	PX	9/24/2084
2020 PO5810837597	F	4	40 BRO	SP	CRE		V		9/25/2084
2020 PO5832937669	F	4	40 BRO	SP	CRE		V		9/26/2084
2020 PO5829037537	F	4	40 BRO	SP	CRE		V		9/27/2084
2020 PO5837237512	F	4	40 BRO	SP	A		V		9/28/2084
2020 PO5709256908	KU	3	40 ACE	SP	CCA		V		9/29/2084
2020 PO5647234121	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		9/30/2084
2020 5697334055-A	KU	5	35 BRO	SP	CCA		V		10/1/2084
2020 PO5697334055	KU	4	40 BRO	SP	CRE	ED,ID	TD		10/2/2084
2020 PO5685534304	KU	4	40 BRO	SP	CRE	ED,ID	TD		10/3/2084

2020 PO5699557403	KU	4	40 ACE	SP	CRE	ED,ID	TD	10/4/2084
2020 PO5684934832	F	5	25 BRO	SP	A		V	10/5/2084
2020 PO5691134780	KU	4	40 BRO	SP	A	ED,ID	TD	10/6/2084
2020 PO5693734604	KU	4	40 BRO	SP	A	ED,ID	TD	10/7/2084
2020 PO5732134557	KU	4	40 BRO	SP	CRE	ED,ID	TD	10/8/2084
2020 PO5753334544	KU	4	35 BRO	SP	CRE	ED,ID	TD	10/9/2084
2020 PO5697557468	KU	4	40 ACE	SP	CRE	ED,ID	BD	10/10/2084
2020 PO5689257737	KU	4	40 ACE	SP	CRE	ED,ID	TD	10/11/2084
2020 PO5668158530	F	4	40 ACE	SP	CRE		V	10/12/2084
2020 PO5682957911	KU	4	40 ACE	SP	CRE	ED,ID	BD	10/13/2084
2020 PO5676758038	F	4	40 ACE	SP	CRE		V	10/14/2084
2020 PO5667858231	F	4	40 ACE	SP	CRE		V	10/15/2084
2020 PO5665858305	F	4	40 ACE	SP	CRE		V	10/16/2084
2020 PO5725758191	KU	6	30 ACE	SP	CCA		V	10/17/2084
2020 PO5653158737	F	5	35E ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	RP1 10/18/2084
2020 PO5665058406	F	4	40 ACE	SP	CRE	ED,ID	V	10/19/2084
2020 PO5668158530a	KU	4	40 ACE	SP	CRE	ED,ID	BD	10/20/2084
2020 PO5792934571	F	4	40 BRO	SP	A		V	10/21/2084
2020 PO5799334531	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	10/22/2084
2020 PO5766434536	KU	4	40 BRO	SP	CRE	ED,ID	TD	10/23/2084
2020 PO5826834656	KU	3	45 BRO	SP	CCA		V	10/24/2084
2020 PO5870934569	KU	4	40 BRO	SP	CCA		V	10/25/2084
2020 PO5709358838	F	4	40 ACE	SP	CRE	ED	V	10/26/2084
2020 PO5686058835	F	4	40 ACE	SP	CRE	ED,ID	V	10/27/2084
2020 PO5678058731	KU	4	40 ACE	SP	CCA		B	10/28/2084
2020 PO5673658660	F	3	45 ACE	SP	CCA		V	10/29/2084
2020 PO5796234756	F	4	40 BRO	SP	A		V	10/30/2084
2020 PO5799234964	F	4	40 BRO	SP	A		V	10/31/2084
2020 PO5801835187	F	4	40 BRO	SP	A		V	11/1/2084
2020 PO5804435404	F	3	40 BRO	SP	CRE		V	11/2/2084
2020 PO5807135647	F	4	40 BRO	SP	A		V	11/3/2084
2020 PO5809235839	F	4	40 BRO	SP	A		V	11/4/2084
2020 PO5812036072	F	4	40 BRO	SP	A		V	11/5/2084
2020 PO5814936320	F	4	40 BRO	SP	A		V	11/6/2084
2020 PO5821036825	F	4	40 BRO	SP	A		V	11/7/2084
2020 PO5819636707	F	4	40 BRO	SP	CRE		V	11/8/2084
2020 PO5817836561	F	3	40 BRO	SP	A		V	11/9/2084
2020 PO5831237008	F	4	40 BRO	SP	A		V	11/10/2084
2020 PO5823337011	F	4	40 BRO	SP	A		V	11/11/2084
2020 PO5824637116	F	4	40 BRO	SP	A		V	11/12/2084
2020 PO5826737305	F	4	40 BRO	SP	A		V	11/13/2084
2020 PO5235937129	F	4	40 BRO	SP	CCA		V	11/14/2084
2020 PO4871737020	KU	4	40 ACE	SP	CRE	ED,ID	BD	11/15/2084
2020 PO4876137104	F	2	50 ACE	SP	P		V	11/16/2084
2020 PO4873437291	KU	4	40 ACE	SP	CRE	ED,ID	BD	11/17/2084
2020 PO4870137469	KU	4	40 ACE	SP	CRE	ED,ID	BD	11/18/2084
2020 PO4855337000	KU	4	40 ACE	SP	CRE	ED,ID	TD	11/19/2084

2020 PO5235537036	F	4	40 BRO	SP	A		V			11/20/2084
2020 PO5234936972	KU	4	40 BRO	SP	CRE	ED,ID,IP	BD			11/21/2084
2020 PO4810836950	KU	4	40 ACE	SP	CRE	ED,ID	BD			11/22/2084
2020 PO4831536975	KU	4	40 ACE	SP	CRE	ED,ID	BD			11/23/2084
2020 PO4802736944	KU	3	50 ACE	SP	CCA		V			11/24/2084
2020 PO4698908005	KU	6	30 BRO	SP	CCA		V			11/25/2084
2020 PO9338786041	KU	5	35 XXX	SP	CRE	ED,ID	BX	RP1		11/26/2084
2020 PO5897749189	F	4	40 ACE	SP	P		V			11/27/2084
2020 PO5888849264	F	4	40 ACE	SP	P		V			11/28/2084
2020 PO9318186111	KU	5	35 BRN	SP	CRE	ED,ID	VX	RP2		11/29/2084
2020 PO5914849049	F	4	40 ACE	SP	CRE		V			11/30/2084
2020 PO5938648861	F	3	45 ACE	SP	CRE		V			12/1/2084
2020 PO5958049101	F	4	40 ACE	SP	CRE		V			12/2/2084
2020 PO5947649012	F	3	40 ACE	SP	CRE	ED,ID	V			12/3/2084
2020 PO5966649173	F	4	40 ACE	SP	P		V			12/4/2084
2020 PO5976049271	F	3	40 ACE	SP	P		V			12/5/2084
2020 PO5981249325	F	4	40 ACE	SP	P		V			12/6/2084
2020 PO5970049417	KU	4	40 ACE	SP	CRE	ED,ID	BD			12/7/2084
2020 PO5960549492	KU	4	40 ACE	SP	CRE	ED,ID	BD			12/8/2084
2020 PO5941849094	KU	4	45 ACE	SP	CRE	ED,ID	BD			12/9/2084
2020 PO5906948103	KU	5	35 ACE	SP	CRE		V			12/10/2084
2020 PO4711708703	F	4	40 BRO	SP	CRE		V			12/11/2084
2020 PO4724488997	F	4	40 ACE	SP	CRE		V			12/12/2084
2020 PO4700408339	KU	3	50 BRO	SP	CRE	ED,ID,IP	TD			12/13/2084
2020 PO4724888985	LGE	3	50 ACE	SP	P	ED,ID	BD			12/14/2084
2020 PO4722488972	LGE	UNK	30E ACE	SP	CRE		V			12/15/2084
2020 PO4722989022	F	3	45 ACE	SP	CCA		V			12/16/2084
2020 PO4725288985	F	3	50 ACE	SP	CRE		V			12/17/2084
2020 PO4725988972	LGE	4	40 ACE	SP	CRE	ED,ID	BD			12/18/2084
2020 PO4727588949	F	4	40 ACE	SP	CCA		V			12/19/2084
2020 PO4726888960	F	4	40 ACE	SP	A		V			12/20/2084
2020 PO4783488735	LGE	1	65 BRN	DF	A		V			12/21/2084
2020 PO4784588736	LGE	4	40 BRN	SP	S		V			12/22/2084
2020 PO4787488736	LGE	4	30 BRN	SP	CRE	ED,ID,IP,RB	BD			12/23/2084
2020 PO4014182872	LGE	4	30 BRO	SP	CCA		V			12/24/2084
2020 PO4013782864	F	4	40 BRO	SP	CCA		V			12/25/2084
2020 PO4013682860	LGE	4	40 BRO	SP	CCA		V			12/26/2084
2020 PO4046983097	LGE	4	35 BRN	SP	CCA		V			12/27/2084
2020 PO4015482848	F	4	30 BRN	SP	CCA		V			12/28/2084
2020 PO4015182843	F	4	40 BRN	SP	CCA		V			12/29/2084
2020 PO5774245565	KU	4	40 ACE	SP	CRE		V			12/30/2084
2020 PO4793688738	LGE	4	30 BRN	SP	S		V			12/31/2084
2020 PO4789588737	LGE	4	30 BRN	SP	CCA		V			1/1/2085
2020 PO4785988728	LGE	3	45 BRN	SP	A	ED,ID	BD			1/2/2085
2020 PO4786388740	LGE	4	35 BRN	SP	CRE	ED,ID,IP	TD			1/3/2085
2020 PO4785588735	LGE	4	30 BRN	SP	CCA		V			1/4/2085
2020 PO4785488737	LGE	1	70 BRN	SP	CRE		V			1/5/2085

2020 PO4014382861	F	4	30 BRO	SP	CCA		V	1/6/2085
2020 PO4013882858	F	4	40 BRO	SP	CCA		V	1/7/2085
2020 PO4074383132	LGE	4	30 BRN	SP	A	ED,ID	BD	1/8/2085
2020 PO4068383229	LGE	4	40 BRO	SP	A	ED,ID	TD	1/9/2085
2020 PO4068583238	LGE	4	40 BRO	SP	A	ED,ID	TD	1/10/2085
2020 PO4070583238	LGE	4	30 BRO	SP	A	ED,ID	BD	1/11/2085
2020 PO4787488751	LGE	4	40 BRN	SP	CRE		V	1/12/2085
2020 PO4786288775	LGE	4	40 BRN	SP	P	ED,ID	BD	1/13/2085
2020 PO4786588767	LGE	4	25 BRN	SP	CRE	ED,ID	BD	1/14/2085
2020 PO4786688768	LGE	4	40 BRN	SP	A	ED,ID	BD	1/15/2085
2020 PO4787088759	LGE	4	40 BRN	SP	P	ED,ID,IP,RB	BX	RR 1/16/2085
2020 PO4786588757	LGE	4	40 BRN	SP	CRE	ED,ID	BD	1/17/2085
2020 PO1860928611	ODP	6	30 XXX	SP	CRE		V	1/18/2085
2020 PO1767629605	ODP	2	45 XXX	SP	CCA		V	1/19/2085
2020 PO1794929444	ODP	2	40 XXX	SP	CCA	ED	T	1/20/2085
2020 PO1813229340	ODP	5	35 XXX	SP	CCA		V	1/21/2085
2020 PO1822529287	ODP	2	40 XXX	SP	CCA		V	1/22/2085
2020 PO1917328980	ODP	4	40 XXX	SP	CRE	ID	BD	1/23/2085
2020 PO1896729019	ODP	2	45 XXX	SP	CCA		V	1/24/2085
2020 PO1871029067	ODP	2	45 XXX	SP	CCA		V	1/25/2085
2020 PO1857629091	ODP	2	45 XXX	SP	CCA		V	1/26/2085
2020 PO1835728678	ODP	5	35 XXX	SP	CRE	ID	BD	1/27/2085
2020 PO1577227366	ODP	4	40 XXX	SP	CRE		V	1/28/2085
2020 PO1587927121	ODP	4	40 XXX	SP	CRE	ID	TD	1/29/2085
2020 PO1607226968	ODP	3	45 XXX	SP	CCA		V	1/30/2085
2020 PO1602826882	ODP	4	40 XXX	SP	CRE	ID	BD	1/31/2085
2020 PO1649726408	ODP	5	30 XXX	SP	CRE	ED,ID	TD	2/1/2085
2020 PO1615626604	ODP	4	40 XXX	SP	CRE	ID	TD	2/2/2085
2020 PO1583726632	ODP	5	35 XXX	SP	CRE	ID	TD	2/3/2085
2020 PO1600926871	ODP	3	45 XXX	SP	CCA		V	2/4/2085
2020 PO1534026685	ODP	4	45 XXX	SP	CCA		V	2/5/2085
2020 PO4787488744	LGE	2	65 BRN	SP	A		V	2/6/2085
2020 PO4787788744	LGE	4	40 BRN	SP	A	ED,ID	BD	2/7/2085
2020 PO4788488748	LGE	4	40 BRN	SP	S		V	2/8/2085
2020 PO4787788745	LGE	4	40 BRN	SP	CCA		V	2/9/2085
2020 PO4789788753	LGE	3	65 BRN	SP	CRE		V	2/10/2085
2020 PO4790488756	LGE	4	35 BRN	SP	A	ED,ID	TD	2/11/2085
2020 PO4789888767	LGE	4	30 BRN	SP	CCA		V	2/12/2085
2020 PO4789488781	LGE	4	35 BRN	SP	CCA		V	2/13/2085
2020 PO4788688786	LGE	4	35 BRN	SP	CCA		V	2/14/2085
2020 PO4791488767	LGE	4	30 BRN	SP	A	ED,ID	TD	2/15/2085
2020 PO4791588759	LGE	3	65 BRN	SP	CRE		V	2/16/2085
2020 PO4604638432	KU	3	45 BRO	SP	CCA		V	2/17/2085
2020 PO4792588763	LGE	4	40 BRN	SP	A	ED,ID	TD	2/18/2085
2020 PO4793888765	LGE	4	40 BRN	SP	A	ED,ID	BD	2/19/2085
2020 PO4793788767	LGE	3	70 BRN	SP	CRE		V	2/20/2085
2020 PO4792788790	LGE	3	50 BRN	SP	A	ED,ID,IP	TD	2/21/2085

2020	PO4438535748	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		2/22/2085
2020	PO2714543459	ODP	5	35 ACW	SP	CRE	ED,ID	TD		2/23/2085
2020	PO2706743820	ODP	5	35 ACW	SP	CRE	ID	BD		2/24/2085
2020	PO5251639524	F	3	45 ACE	SP	CCA		V		2/25/2085
2020	PO5231939586	KU	5	35 ACE	SP	CCA		V		2/26/2085
2020	PO5213739524	F	4	40 ACE	SP	CCA		V		2/27/2085
2020	PO5206439517	KU	3	45 ACE	SP	CCA		V		2/28/2085
2020	PO5207339654	F	4	40 ACE	SP	CRE		V		3/1/2085
2020	PO5198839752	F	5	35 ACE	SP	CRE		V		3/2/2085
2020	PO5207939744	F	4	40 ACE	SP	CRE		V		3/3/2085
2020	PO5208739887	F	4	40 ACE	SP	CRE		V		3/4/2085
2020	PO5209540013	F	4	40 ACE	SP	CRE		V		3/5/2085
2020	PO5202740170	F	4	40 ACE	SP	CRE		V		3/6/2085
2020	PO4633888195	LGE	4	40 BRO	SP	CRE		V		3/7/2085
2020	PO4634088219	LGE	4	40 BRO	SP	CRE	ED,ID	BD		3/8/2085
2020	PO4784388981	LGE	3	50 BRN	SP	CRE	ED,ID	VX	RP3	3/9/2085
2020	PO4629488072	LGE	4	40 BRO	SP	CRE	ED,ID	BD		3/10/2085
2020	PO4629588087	LGE	4	40 BRO	SP	P	ED,ID	TD		3/11/2085
2020	PO4629788102	LGE	4	40 BRO	SP	CRE	ED,ID,IP,RB	TX	RR	3/12/2085
2020	PO4629988130	LGE	4	40 BRO	SP	CRE	ED,ID	TD		3/13/2085
2020	PO4629888115	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		3/14/2085
2020	PO4630188144	LGE	4	40 BRO	SP	CRE	ED,ID	BD		3/15/2085
2020	PO4630288160	LGE	4	40 BRO	SP	CRE	ED,ID	BD		3/16/2085
2020	PO4782088858	LGE	3	40 BRN	SP	CRE	ED,ID,IP	TD		3/17/2085
2020	PO4782588848	LGE	4	40 BRN	SP	CCA	ED,ID	BD		3/18/2085
2020	PO4781188828	LGE	6	30 BRN	SP	CRE	ED,ID	TD		3/19/2085
2020	PO4783288835	LGE	4	40 BRN	SP	A	ED,ID	TD		3/20/2085
2020	PO4783888822	LGE	4	40 BRN	SP	CCA	ED,ID	BD		3/21/2085
2020	PO4780988804	LGE	4	40 BRN	SP	CCA		V		3/22/2085
2020	PO6154265661	F	4	40 OTH	SP	CRE		V		3/23/2085
2020	PO6159665723	KU	5	35 OTH	SP	CRE	ID	TD		3/24/2085
2020	PO9202993465	KU	3	50 BRN	SP	CRE	ID	BD		3/25/2085
2020	PO9258193125	KU	4	40 BRN	SP	CRE	ED,ID	TD		3/26/2085
2020	PO9253293293	KU	4	40 BRN	SP	CRE	ED,ID	TD		3/27/2085
2020	PO9250093406	KU	4	40 BRN	SP	CRE	ED,ID	TD		3/28/2085
2020	PO9240993280	KU	4	40 BRN	SP	CRE	ED,ID	TD		3/29/2085
2020	PO9208693285	KU	4	40 BRN	SP	CRE	ED,ID	TD		3/30/2085
2020	PO9235793368	KU	4	45 BRN	SP	CRE	ED,ID	TD		3/31/2085
2020	PO9222593329	KU	4	45 BRN	SP	CRE	ED,ID	TD		4/1/2085
2020	PO9232493228	KU	4	40 BRN	SP	CRE	ED,ID	TD		4/2/2085
2020	9267	KU	5	35 BRN	SP	CRE	ED,ID	TD		4/3/2085
2020	PO9272393732	KU	6	30 BRN	SP	CRE	ED,ID	TD		4/4/2085
2020	PO5665147826	KU	4	40 ACE	SP	CRE	ED,ID	BD		4/5/2085
2020	PO5661147814	F	5	35 ACE	SP	CCA		V		4/6/2085
2020	PO9383094729	KU	6	30 ACW	SP	S		V		4/7/2085
2020	PO9392094709	KU	4	40 ACW	SP	CRE	ED,ID,IP,SR	TX	RR	4/8/2085
2020	PO9384794917	KU	4	40 ACW	SP	CRE		V		4/9/2085

2020 PO9390294822	C	4	40 ACW	SP	CRE		V	4/10/2085
2020 PO9393694877	C	4	40 ACW	SP	CRE		V	4/11/2085
2020 PO9240694138	F	4	40 XXX	SP	CRE		V	4/12/2085
2020 PO9211894047	C	4	40 XXX	SP	CRE		V	4/13/2085
2020 PO9226094100	C	4	40 BRN	SP	CRE		V	4/14/2085
2020 PO9224194163	C	4	40 BRN	SP	S		V	4/15/2085
2020 PO9238794270	KU	6	30 XXX	SP	CRE	ED,ID	TD	4/16/2085
2020 PO9295094290	KU	4	40 XXX	SP	CRE	ED,ID	TD	4/17/2085
2020 PO9453594619	KU	6	30 ACW	SP	CRE		V	4/18/2085
2020 PO9452594687	KU	5	35 ACW	SP	CRE		V	4/19/2085
2020 PO9451294740	C	4	40 ACW	SP	CRE		V	4/20/2085
2020 PO9449394775	C	4	40 ACW	SP	CRE		V	4/21/2085
2020 PO9440194853	C	4	40 ACW	SP	CRE		V	4/22/2085
2020 PO9438594896	C	4	40 ACW	SP	CRE		V	4/23/2085
2020 PO9442994971	C	4	40 ACW	SP	CRE		V	4/24/2085
2020 PO9434294949	KU	4	40 ACW	SP	CRE	ED,ID,IP	BD	4/25/2085
2020 PO9427094829	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	4/26/2085
2020 PO9444194765	KU	5	35 ACW	SP	CRE	ED,ID	TD	4/27/2085
2020 PO9432394697	KU	4	40 ACW	SP	CRE	ED,ID	TD	4/28/2085
2020 PO5678947423	KU	6	30 ACE	SP	CCA		V	4/29/2085
2020 PO5670647441	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	4/30/2085
2020 PO5680647135	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	5/1/2085
2020 PO5685547280	KU	6	30 ACE	SP	CRE	ED,ID	BD	5/2/2085
2020 PO5662847186	F	4	40 ACE	SP	CRE		V	5/3/2085
2020 PO9218394387	KU	6	30 XXX	SP	P	ID	BD	5/4/2085
2020 PO9214094299	KU	6	30 XXX	SP	CCA		V	5/5/2085
2020 PO9206394294	KU	4	40 XXX	SP	CRE	ED,ID	TD	5/6/2085
2020 PO9205694325	F	4	40 XXX	SP	CRE		V	5/7/2085
2020 PO9337793374	F	4	35 ACW	SP	CRE		V	5/8/2085
2020 PO9315693395	KU	6	30 ACW	SP	S		V	5/9/2085
2020 PO9309393569	KU	6	30 ACW	SP	CCA		V	5/10/2085
2020 PO9319493759	KU	3	50 ACW	SP	CRE	ED,ID,IP	TD	5/11/2085
2020 PO9331993673	F	4	40 ACW	SP	S		V	5/12/2085
2020 PO9304993620	KU	6	30 ACW	SP	S		V	5/13/2085
2020 PO9206794247	KU	6	30 BRN	SP	CCA		V	5/14/2085
2020 PO9203794188	KU	4	40 BRN	SP	CRE	ED,ID,RB	TX	5/15/2085
2020 PO5468246027	F	6 30E	ACE	SP	CRE		V	5/16/2085
2020 PO5694647195	KU	4	40 ACE	SP	CRE	ED,ID	TD	5/17/2085
2020 PO9324493643	KU	3	45 ACW	SP	CRE	ED,ID	TD	5/18/2085
2020 PO9338993558	KU	5	35 ACW	SP	CRE	ED,ID	TD	5/19/2085
2020 PO9330593513	KU	3	45 ACW	SP	CRE	ED,ID	TD	5/20/2085
2020 PO9311693461	KU	5	30 ACW	SP	CRE	ED,ID,SR	TD	5/21/2085
2020 PO9309593311C	KU	6	35 ACW	SP	CRE	ED,ID	BD	5/22/2085
2020 PO9309593311B	KU	5	25 ACW	SP	CRE	ED,ID,SR	X	5/23/2085
2020 PO9309593311A	KU	5	30 ACW	SP	CRE	ED,ID	TD	5/24/2085
2020 PO9309593311	KU	5	35 ACW	SP	S		V	5/25/2085
2020 PO6803354092	ODP	4	40 XXX	SP	CRE		V	5/26/2085

2020 PO6818653915	ODP	4	40 XXX	SP	CRE		V		5/27/2085
2020 PO6811853504	ODP	4	40 XXX	SP	CRE		V		5/28/2085
2020 PO4810888954	LGE	4	40 BRN	SP	CCA		V		5/29/2085
2020 PO4808188943	LGE	4	40 BRN	SP	CRE	ED,ID	BD		5/30/2085
2020 PO4811388940	LGE	4	40 BRN	SP	CRE	ED,ID	TD		5/31/2085
2020 PO4808688929	LGE	4	40 BRN	SP	CRE	ED,HH,ID	BX	PX	6/1/2085
2020 PO4716688021	LGE	3	45 BRO	SP	CCA		V		6/2/2085
2020 PO4715388012	LGE	3	45 BRO	SP	CCA		V		6/3/2085
2020 PO4717688029	LGE	3	45 BRO	SP	CCA		V		6/4/2085
2020 PO4718188032	LGE	1	50 BRO	SP	CCA		V		6/5/2085
2020 PO4717588047	LGE	3	45 BRO	SP	CCA		V		6/6/2085
2020 PO4717388057	LGE	3	45 BRO	SP	CCA		V		6/7/2085
2020 PO4717188068	LGE	3	45 BRO	SP	CCA		V		6/8/2085
2020 PO4717088050	LGE	4	35 BRO	SP	A	ED,ID	BD		6/9/2085
2020 PO4717388047	LGE	4	30 BRO	SP	CRE	ED,ID	BD		6/10/2085
2020 PO4716788086	LGE	3	45 BRO	SP	CCA		V		6/11/2085
2020 PO4713988003	LGE	4	40 BRO	SP	CCA		V		6/12/2085
2020 PO4712987996	F	4	40 BRO	SP	CCA		V		6/13/2085
2020 PO4713987999	LGE	4	40 BRO	SP	P	ED,ID	TD		6/14/2085
2020 PO4713287994	LGE	1	70 BRO	SP	A		V		6/15/2085
2020 PO4712087990	LGE	3	45 BRO	SP	CCA		V		6/16/2085
2020 PO4712087986	LGE	2	65 BRO	SP	A		V		6/17/2085
2020 PO4712087983	LGE	4	40 BRO	SP	CCA		V		6/18/2085
2020 PO4811888924	LGE	4	40 BRN	SP	CRE	ED,ID	TD		6/19/2085
2020 PO4809288913	LGE	4	40 BRN	SP	CRE	ED,ID	BD		6/20/2085
2020 PO4812488909	LGE	4	40 BRN	SP	P	ED,ID	TD		6/21/2085
2020 PO4809788898	LGE	4	40 BRN	SP	CRE	ED,ID	TD		6/22/2085
2020 PO4858360625	KU	4	50 OTH	SP	P	ID	TD		6/23/2085
2020 PO4770759820	F	3	45 OTH	SP	P		V		6/24/2085
2020 PO4588757862	F	4	45 OTH	SP	P		V		6/25/2085
2020 PO4685458860	F	5	45 OTH	SP	P		V		6/26/2085
2020 PO4661058624	F	4	45 OTH	SP	P		V		6/27/2085
2020 PO4793160079	F	4	45 OTH	SP	P		V		6/28/2085
2020 PO4802560187	F	3	45 OTH	SP	P		V		6/29/2085
2020 PO4542857529	F	3	45 OTH	SP	CCA		V		6/30/2085
2020 PO4783359961	F	4	40 OTH	SP	P		V		7/1/2085
2020 PO4828160411	F	3	45 OTH	SP	P		V		7/2/2085
2020 PO4750759591	F	3	45 OTH	SP	P		V		7/3/2085
2020 PO4627258254	F	3	45 OTH	SP	P		V		7/4/2085
2020 PO4703359046	F	3	45 OTH	SP	P		V		7/5/2085
2020 PO4813660294	F	3	45 OTH	SP	P		V		7/6/2085
2020 PO4640658398	F	3	45 OTH	SP	P		V		7/7/2085
2020 PO4844360531	F	3	45 OTH	SP	CCA		V		7/8/2085
2020 PO4610358076	F	3	45 OTH	SP	P		V		7/9/2085
2020 PO4526657429	F	4	40 OTH	SP	CCA		V		7/10/2085
2020 PO4719059224	F	3	45 OTH	SP	P		V		7/11/2085
2020 PO4731959381	F	3	45 OTH	SP	P		V		7/12/2085

2020 PO4563757670	F	3	45 OTH	SP	P		V	7/13/2085	
2020 PO4517757331	KU	6	30 OTH	SP	CRE	ID	TD	7/14/2085	
2020 PO4712587961	LGE	4	40 BRO	SP	P	ED,ID,IP	TD	7/15/2085	
2020 PO4805488838	LGE	4	40 BRN	SP	CRE	ED,ID	BD	7/16/2085	
2020 PO4805088851	LGE	4	40 BRN	SP	CRE	ED,ID,SRC	TX	RR	7/17/2085
2020 PO4804588864	LGE	4	40 BRN	SP	CCA	ED,ID	BD	7/18/2085	
2020 PO4674012855	F	4	40 ACE	SP	CRE		V	7/19/2085	
2020 PO4668212775	F	4	40 ACE	SP	CRE		V	7/20/2085	
2020 PO4684687948	LGE	3	45 BRO	SP	CRE		V	7/21/2085	
2020 PO4718588090	LGE	3	45 BRO	SP	CCA		V	7/22/2085	
2020 PO4719988098	LGE	3	45 BRO	SP	CCA		V	7/23/2085	
2020 PO4721588110	LGE	3	45 BRO	SP	CCA		V	7/24/2085	
2020 PO4723288122	LGE	3	45 BRO	SP	CCA		V	7/25/2085	
2020 PO4901612896	F	4	40 ACE	SP	CRE		V	7/26/2085	
2020 PO4897112795	F	4	40 ACE	SP	A		V	7/27/2085	
2020 PO4885612846	F	4	40 ACE	SP	CRE		V	7/28/2085	
2020 PO4725188129	LGE	4	35 BRO	SP	P	ED,HH,ID,RB	BX	RP3	7/29/2085
2020 PO4724988134	LGE	3	45 BRO	SP	CCA		V	7/30/2085	
2020 PO4726888139	LGE	4	30 BRO	SP	P	ED,HH,ID	TX	RR	7/31/2085
2020 PO4872512899	F	4	40 ACE	SP	CRE		V	8/1/2085	
2020 PO4910513098	F	4	40 ACE	SP	CRE		V	8/2/2085	
2020 PO4802488921	LGE	4	40 BRN	SP	CRE	ED,ID	TD	8/3/2085	
2020 PO4805388933	LGE	4	40 BRN	SP	CCA	ED,ID	BD	8/4/2085	
2020 PO4906713010	F	4	40 ACE	SP	CCA		V	8/5/2085	
2020 PO4129655388	KU	4	40 OTH	SP	CCA		V	8/6/2085	
2020 PO4078955041	KU	4	45 OTH	SP	CCA		V	8/7/2085	
2020 PO4129355954	KU	4	40 OTH	SP	CCA		V	8/8/2085	
2020 PO4199756015	KU	4	40 OTH	SP	CRE	ID	TD	8/9/2085	
2020 PO4038654760	KU	5	40 OTH	SP	CRE	ED,ID	TD	8/10/2085	
2020 PO4137355339	KU	4	45 OTH	SP	CRE	ID	TD	8/11/2085	
2020 PO4188855606	KU	3	45 OTH	SP	CCA		V	8/12/2085	
2020 PO4129555674	KU	4	40 OTH	SP	CCA		V	8/13/2085	
2020 PO4236355851	KU	3	45 OTH	SP	CCA		V	8/14/2085	
2020 PO4217855934	KU	4	40 OTH	SP	CRE	ID	TD	8/15/2085	
2020 PO4801588947	LGE	4	40 BRN	SP	CCA	ED,ID	BD	8/16/2085	
2020 PO4801988935	LGE	4	40 BRN	SP	CRE	ED,ID	TD	8/17/2085	
2020 PO4916413232	F	4	40 ACE	SP	CRE		V	8/18/2085	
2020 PO4861612942	F	4	40 ACE	SP	CRE		V	8/19/2085	
2020 PO4909112743	F	4	40 ACE	SP	CRE		V	8/20/2085	
2020 PO4804988945	LGE	4	40 BRN	SP	CRE	ED,ID,IP	BD	8/21/2085	
2020 PO4869913164	F	4	40 ACE	SP	CRE		V	8/22/2085	
2020 PO4876713327	F	4	40 ACE	SP	CRE		V	8/23/2085	
2020 PO4870113353	F	4	40 ACE	SP	CRE		V	8/24/2085	
2020 PO4881613428	F	4	40 ACE	SP	CRE		V	8/25/2085	
2020 PO4885613527	F	4	40 ACE	SP	CRE		V	8/26/2085	
2020 PO4873513451	F	4	40 ACE	SP	CRE		V	8/27/2085	
2020 PO4803088959	LGE	4	30 BRN	SP	CRE	ED,ID	BD	8/28/2085	

2020 PO4870013558	F	4	40 ACE	SP	CRE		V	8/29/2085
2020 PO4834213726	F	4	40 ACE	SP	A		V	8/30/2085
2020 PO4016054606	KU	5	35 OTH	SP	CRE	ED	TD	8/31/2085
2020 PO3968255728	KU	4	40 OTH	SP	CRE	ID	TD	9/1/2085
2020 PO4006754539	KU	4	40 OTH	SP	CRE	ID	TD	9/2/2085
2020 PO3945255934	KU	4	40 OTH	SP	CRE	ID	TD	9/3/2085
2020 PO4010654566	KU	2	50 OTH	SP	CRE		V	9/4/2085
2020 PO4023754658	KU	4	40 OTH	SP	CRE	ID	TD	9/5/2085
2020 PO3993055512	KU	4	40 OTH	SP	CRE	ID	TD	9/6/2085
2020 PO4018154863	KU	4	40 OTH	SP	CRE	ID	TD	9/7/2085
2020 PO3914056172	KU	4	40 OTH	SP	CRE	ID	TD	9/8/2085
2020 PO4006155185	KU	4	40 OTH	SP	CRE	ID	TD	9/9/2085
2020 PO4829913592	F	4	40 ACE	SP	CRE		V	9/10/2085
2020 PO4816413645	F	4	40 ACE	SP	CRE		V	9/11/2085
2020 PO4801813685	F	4	40 ACE	SP	CRE		V	9/12/2085
2020 PO4788313708	F	4	40 ACE	SP	CRE		V	9/13/2085
2020 PO4803988880	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD	9/14/2085
2020 PO4774013775	F	4	40 ACE	SP	CRE		V	9/15/2085
2020 PO4764013824	F	4	40 ACE	SP	CRE	HH,ID,RB	VX	9/16/2085
2020 PO4754413873	F	4	40 ACE	SP	CRE		V	9/17/2085
2020 PO4743513978	F	4	40 ACE	SP	CRE		V	9/18/2085
2020 PO4738714153	F	4	40 ACE	SP	CRE		V	9/19/2085
2020 PO4732514085	F	4	40 ACE	SP	CRE		V	9/20/2085
2020 PO4726814022	F	4	40 ACE	SP	CRE		V	9/21/2085
2020 PO4727013600	F	4	40 ACE	SP	CRE		V	9/22/2085
2020 PO4790712780	F	4	40 ACE	SP	CRE		V	9/23/2085
2020 PO5636446398	F	4	40 ACE	SP	CRE		V	9/24/2085
2020 PO5635246426	F	4	40 ACE	SP	CRE		V	9/25/2085
2020 PO5634746464	F	4	40 ACE	SP	CRE		V	9/26/2085
2020 PO5622746707	F	4	40 ACE	SP	CRE		V	9/27/2085
2020 PO5601546972	KU	6	30 ACE	SP	CRE	ED,ID	BD	9/28/2085
2020 PO5620247030	KU	4	40 ACE	SP	CRE	ED,ID	TD	9/29/2085
2020 PO5609446988	F	4	40 ACE	SP	P		V	9/30/2085
2020 PO5632747079	F	4	40 ACE	SP	P		V	10/1/2085
2020 PO5640847110	F	4	40 ACE	SP	P		V	10/2/2085
2020 PO5612347213	KU	4	40 ACE	SP	CRE	ED,ID	BD	10/3/2085
2020 PO5648047468	KU	4	40 ACE	SP	CRE	ED,ID	BD	10/4/2085
2020 PO5647947336	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD	10/5/2085
2020 PO5443242403	F	4	40 BRO	SP	CRE		V	10/6/2085
2020 PO5396636789	F	4	40 BRO	SP	CRE		V	10/7/2085
2020 PO5395636630	F	4	40 BRO	SP	CRE		V	10/8/2085
2020 PO5394436430	F	4	40 BRO	SP	CRE		V	10/9/2085
2020 PO5393336261	F	4	40 BRO	SP	CRE		V	10/10/2085
2020 PO5392036060	F	4	40 BRO	SP	CRE		V	10/11/2085
2020 PO5400836022	C	5	35 BRO	SP	CCA		V	10/12/2085
2020 PO5654046368	KU	5	35 ACE	SP	CRE	ED,ID	BD	10/13/2085
2020 PO5439336605	F	4	40 BRO	SP	CRE		V	10/14/2085

2020 PO5437436910	F	4	40 BRO	SP	CRE		V	10/15/2085
2020 PO5451336903	F	4	40 BRO	SP	CRE		V	10/16/2085
2020 PO5471636889	F	4	40 BRO	SP	CRE		V	10/17/2085
2020 PO5488336878	F	4	40 BRO	SP	CRE		V	10/18/2085
2020 PO5641546298	KU	4	40 ACE	SP	CRE	ED,ID	BD	10/19/2085
2020 PO5156138229	F	4	40 ACE	SP	CRE		V	10/20/2085
2020 PO5250440905	F	4	40 ACE	SP	CRE		V	10/21/2085
2020 PO5209040778	KU	5	35 ACE	ST	P		V	10/22/2085
2020 PO5377142183	F	5	35 ACE	ST	P		V	10/23/2085
2020 PO5176638337	F	4	40 ACE	SP	CRE		V	10/24/2085
2020 PO5372741834	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	10/25/2085
2020 PO5323341463	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	10/26/2085
2020 PO5425443420	KU	4	45 BRO	SP	CRE	ID	BD	10/27/2085
2020 PO5343641538	KU	3	50 ACE	SP	CCA		V	10/28/2085
2020 PO5428543242	KU	4	45 BRO	SP	CRE	ID	BD	10/29/2085
2020 PO5450843098	KU	4	45 BRO	SP	CRE	ID	BD	10/30/2085
2020 PO4022530616	KU	4	40 BRO	SP	CRE	ID	TD	10/31/2085
2020 PO3973930756	KU	4	40 BRO	SP	CRE	ID	TD	11/1/2085
2020 PO4033830582	F	4	40 BRO	SP	CRE		V	11/2/2085
2020 PO8451568188	KU	2	65 BRO	SP	CRE		V	11/3/2085
2020 PO8461168072	KU	4	40 BRO	SP	CCA		V	11/4/2085
2020 PO8474767918	KU	2	65 BRO	SP	CRE		V	11/5/2085
2020 PO4767305028	KU	5	40 XXX	SP	CRE	ED,ID	TD	11/6/2085
2020 PO4823004956	KU	5	35 ACW	SP	CRE	ED,ID	TD	11/7/2085
2020 PO4796905017	KU	5	30 ACW	SP	CRE	ED,ID	TD	11/8/2085
2020 PO4805605095	KU	4	45 ACW	SP	CRE	ED,ID	TD	11/9/2085
2020 PO4762404969	KU	4	40 ACW	SP	CRE	ED,ID	TD	11/10/2085
2020 PO4762405068	KU	6	30 XXX	SP	CRE	ED,ID	TD	11/11/2085
2020 PO4040506286	KU	4	40 XXX	SP	CRE		V	11/12/2085
2020 PO8457567814	F	4	40 BRO	SP	CRE		V	11/13/2085
2020 PO8448867760	KU	3	45 BRO	SP	CCA		V	11/14/2085
2020 PO8414667844	KU	4	40 BRO	SP	CRE	ED,ID	TD	11/15/2085
2020 PO8347367289	KU	6	30 BRO	SP	P	ED,ID	T	11/16/2085
2020 PO8494167010	KU	4	40 BRO	SP	CRE	ED,ID	TD	11/17/2085
2020 PO6849982784	KU	1	60 BRN	SP	P		V	11/18/2085
2020 PO7216686167	KU	4	40 BRO	SP	CRE	ED,ID	TD	11/19/2085
2020 PO3624204798	KU	4	40 BRO	SP	CRE	ID	TD	11/20/2085
2020 PO3542904738	KU	4	40 BRO	SP	CRE		V	11/21/2085
2020 PO3548704674	KU	6	30 BRO	SP	CCA		V	11/22/2085
2020 PO3556904658	KU	4	40 BRO	SP	CRE	ID	V	11/23/2085
2020 PO3567104761	KU	5	35 BRO	SP	CRE	ID	BD	11/24/2085
2020 PO3567104715	KU	4	40 BRO	SP	CRE	ID	TD	11/25/2085
2020 PO3579704860	KU	5	35 BRO	SP	CRE	ID	TD	11/26/2085
2020 PO3612905124	KU	4	40 BRN	SP	CCA		V	11/27/2085
2020 PO3603404931	KU	5	30 BRO	SP	CRE	ID	BD	11/28/2085
2020 PO3587204995	KU	6	30 BRO	SP	CRE	ID	TD	11/29/2085
2020 PO3596604996	KU	3	40 BRO	SP	CRE	ID	TD	11/30/2085

2020 PO3596105079	KU	4	40 BRO	SP	CRE	ID	TD	12/1/2085
2020 PO3605605162	KU	4	40 BRO	SP	CRE	ID	TD	12/2/2085
2020 PO3510904428	KU	4	40 BRO	SP	CRE	ID	TD	12/3/2085
2020 PO3859804385	KU	4	40 XXX	SP	CRE	ED,ID	TD	12/4/2085
2020 PO3852804613	KU	6	30 XXX	SP	CCA		V	12/5/2085
2020 PO3845504546	KU	4	40 XXX	SP	CRE	ED,ID	TD	12/6/2085
2020 PO3851304756	KU	6	30 XXX	SP	CRE	ED,ID	TD	12/7/2085
2020 3185304756A	KU	6	30 XXX	SP	CRE	ED,ID	TD	12/8/2085
2020 PO7188884922	KU	6	30 BRO	SP	CRE	ED,ID	BD	12/9/2085
2020 PO7190885211	KU	4	40 BRO	SP	CRE	ED,ID	TD	12/10/2085
2020 PO7188785225	KU	3	45 BRO	SP	CCA		V	12/11/2085
2020 PO7178385296	KU	3	40 BRO	SP	CRE	ED,ID	TD	12/12/2085
2020 PO3468504250	KU	4	40 BRO	SP	CRE		B	12/13/2085
2020 PO3490704345	KU	5	35 BRO	SP	CRE	ID	TD	12/14/2085
2020 PO3780704749	KU	4	30 BRN	SP	CRE		V	12/15/2085
2020 PO3782104661	KU	4	40 BRN	SP	CRE		V	12/16/2085
2020 PO3754804679	KU	3	55 BRN	SP	CCA		V	12/17/2085
2020 PO3731204692	KU	3	55 BRN	SP	CCA		V	12/18/2085
2020 PO3699004713	KU	3	50 BRN	SP	CCA		V	12/19/2085
2020 PO3676404719	KU	3	45 BRN	SP	CCA		V	12/20/2085
2020 PO3676404719A	KU	5	35 BRN	SP	CCA		V	12/21/2085
2020 PO3640704574	KU	6	30 BRN	SP	CCA		V	12/22/2085
2020 PO3639604578	KU	6	30 BRN	SP	CCA		V	12/23/2085
2020 PO3616104410	KU	6	30 BRN	SP	CCA		V	12/24/2085
2020 PO3581603683	KU	4	40 BRN	SP	CCA		V	12/25/2085
2020 PO3604203921	KU	4	40 BRN	SP	CCA		V	12/26/2085
2020 PO3587803875	KU	3	45 BRN	SP	CCA		V	12/27/2085
2020 PO3650804741	KU	3	50 BRN	SP	CCA		V	12/28/2085
2020 PO3638705150	KU	5	35 OTH	SP	CCA		V	12/29/2085
2020 PO3616505145	KU	4	35E BRN	SP	CCA		V	12/30/2085
2020 PO3620004742	KU	2	55 BRN	SP	CCA		V	12/31/2085
2020 PO3602304726	KU	3	45 BRN	SP	CCA		V	1/1/2086
2020 PO3583904703	KU	3	45 BRN	SP	CCA		V	1/2/2086
2020 PO3588204572	KU	5	35 OTH	SP	CCA		V	1/3/2086
2020 PO3568404662	KU	3	45 BRN	SP	CCA		V	1/4/2086
2020 PO3567204636	KU	3	50 OTH	WC	CCA		V	1/5/2086
2020 PO3567104547	KU	3	45 OTH	SP	CCA		V	1/6/2086
2020 PO3567704293	KU	6	30 BRN	SP	CCA		V	1/7/2086
2020 PO3545504567	KU	3	45 BRN	SP	CCA		V	1/8/2086
2020 PO3525004466	KU	3	45 BRN	SP	CCA		V	1/9/2086
2020 PO3511504739	KU	5	35 BRN	SP	CCA		V	1/10/2086
2020 PO3510004390A	KU	4	40 BRN	SP	CCA		V	1/11/2086
2020 PO3510004390	KU	3	45 BRN	SP	CCA		V	1/12/2086
2020 PO3513604324	KU	5	35 OTH	SP	CCA		V	1/13/2086
2020 PO7642673646	KU	4	40 BRO	SP	CCA		V	1/14/2086
2020 PO7666273126	KU	3	45 BRO	SP	CCA		V	1/15/2086
2020 PO8540481696	F	2	60 BRO	SP	CCA		V	1/16/2086

2020 PO8545881828	KU	5	35 BRO	SP	CCA		V	1/17/2086
2020 PO8525481857	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	1/18/2086
2020 PO8508681910	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	1/19/2086
2020 PO8512181994	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	1/20/2086
2020 PO8517181563	F	4	40 BRO	SP	A		V	1/21/2086
2020 PO8528081705	F	4	40 BRO	SP	A		V	1/22/2086
2020 PO8367181051	KU	6	30 BRO	SP	CRE		V	1/23/2086
2020 PO8451377618	KU	4	45 BRO	SP	A	ID	BD	1/24/2086
2020 PO8455377611	KU	3	50 BRO	SP	A	ID	BD	1/25/2086
2020 PO8420977706	KU	4	40 BRO	SP	CRE	ED,EP,ID,SRS	TD	1/26/2086
2020 PO8423577705	KU	4	45 BRO	SP	CCA		V	1/27/2086
2020 PO2642006972	KU	6	30 BRO	SP	CRE		V	1/28/2086
2020 PO7346676809	KU	3	50 BRN	SP	CRE	ED,ID	BD	1/29/2086
2020 PO7359576770	KU	4	45 BRN	SP	CRE	ED,ID	BD	1/30/2086
2020 PO7358376707	KU	4	45 BRN	SP	CRE	ED,ID	TD	1/31/2086
2020 PO7335876272	KU	2	50 BRN	SP	CRE	ED,ID	TD	2/1/2086
2020 PO7356076577	KU	4	45 BRN	SP	CRE	ED,ID	BD	2/2/2086
2020 PO7382276475	KU	4	45 BRN	SP	CCA		V	2/3/2086
2020 PO7379376065	KU	5	35 BRN	SP	CCA		V	2/4/2086
2020 PO2635206894	KU	4	40 BRO	SP	CRE		V	2/5/2086
2020 PO2631906801	KU	4	35 BRO	SP	CRE		V	2/6/2086
2020 PO2625206627	KU	4	35 BRO	SP	CCA		V	2/7/2086
2020 PO2634806406	KU	4	35 BRO	SP	CRE		V	2/8/2086
2020 PO2314503831	KU	5	35 BRO	SP	CRE		V	2/9/2086
2020 PO2301403665	KU	4	40 BRO	SP	CRE		V	2/10/2086
2020 PO2432504803	KU	3	40 BRO	SP	CRE		V	2/11/2086
2020 PO2419404636	KU	5	35 BRO	SP	CRE		V	2/12/2086
2020 PO2408104487	KU	5	35 BRO	SP	CRE		V	2/13/2086
2020 PO3965600885	KU	2	35 XXX	SP	CCA		V	2/14/2086
2020 PO3959800921	KU	2	35 XXX	SP	CCA		V	2/15/2086
2020 PO7255887245	KU	4	50 BRO	SP	CRE	ED,ID	BD	2/16/2086
2020 PO7263787189	KU	4	40 BRO	SP	CRE	ED,ID	BD	2/17/2086
2020 PO7272687175	KU	3	45 BRO	SP	A	ED,ID,IP,RB	TD	2/18/2086
2020 PO7291387165	KU	3	45 BRO	SP	CRE	ED,ID	BD	2/19/2086
2020 PO3968100078	KU	6	30 BRN	SP	CCA		V	2/20/2086
2020 PO3956000052	KU	4	40 BRN	SP	CRE		V	2/21/2086
2020 PO4313003226	KU	4	40 BRO	SP	CRE	ID	TD	2/22/2086
2020 PO4325402958	KU	6	35 BRO	SP	CRE	ID	TD	2/23/2086
2020 PO4318803373	KU	6	30 BRO	SP	CRE		V	2/24/2086
2020 PO4372602828	KU	6	30 BRO	SP	A		V	2/25/2086
2020 PO4361402691	KU	6	35 BRO	SP	CRE	ID	TD	2/26/2086
2020 PO4360802740	KU	4	40 BRO	SP	CRE	ID	TD	2/27/2086
2020 PO4335902725	KU	4	40 BRO	SP	CRE	ID	TD	2/28/2086
2020 PO4350502634	KU	6	30 BRO	SP	CRE		V	3/1/2086
2020 PO4342502600	KU	4	40 BRO	SP	CRE	ID	TX	RR 3/2/2086
2020 PO3780204552	KU	3	55 BRO	SP	CRE	ID	TD	3/3/2086
2020 PO2584006269	KU	4	45 BRO	SP	CRE		V	3/4/2086

Business Use

2020 PO2576906185	KU	5	35 BRO	SP	CRE		V		3/5/2086
2020 PO2564106094	KU	5	35 BRO	SP	CRE		V		3/6/2086
2020 PO2541105982	KU	5	35 BRO	SP	CRE		V		3/7/2086
2020 PO2499305691	KU	4	45 BRO	SP	CRE		V		3/8/2086
2020 PO2461705428	KU	5	35 BRO	SP	CRE		V		3/9/2086
2020 PO3614804007	KU	4	40 BRO	SP	CRE		V		3/10/2086
2020 PO3595203841	KU	4	40 BRO	SP	CRE	ID		TD	3/11/2086
2020 PO3591903726	KU	4	40 BRO	SP	CRE	ID		BD	3/12/2086
2020 PO3588003598	KU	4	40 BRO	SP	CRE	ID		BD	3/13/2086
2020 PO3583103328	KU	4	40 BRO	SP	CRE	ID		BD	3/14/2086
2020 PO3584703478	KU	4	40 BRO	SP	CRE	ID		BD	3/15/2086
2020 PO3567504019	KU	5	35 BRO	SP	CRE	ID		TD	3/16/2086
2020 PO3552703941	KU	4	40 BRO	SP	CRE	ID		TD	3/17/2086
2020 PO2406004917	KU	5	35 BRO	SP	CRE		V		3/18/2086
2020 PO2382504622	KU	5	35 BRO	SP	CRE		V		3/19/2086
2020 PO7121686336	KU	4	40 BRO	SP	CCA		V		3/20/2086
2020 PO7129586435	KU	4	40 BRO	SP	CCA		B		3/21/2086
2020 PO7384275765	KU	4	45 BRN	SP	CRE	ED,ID		TD	3/22/2086
2020 PO7346875794	KU	4	45 BRN	SP	CRE	ED,ID		TD	3/23/2086
2020 PO7366775782	KU	4	45 BRN	SP	CRE	ED,ID		TD	3/24/2086
2020 PO4001602291	KU	6	30 XXX	SP	CCA		V		3/25/2086
2020 PO4010702252	KU	5	40 XXX	SP	CRE	ED,ID,IP		TD	3/26/2086
2020 PO7341475829	KU	6	30 BRN	SP	P	ED,ID		T	3/27/2086
2020 PO7331276014	KU	5	45 BRN	SP	CRE	ED,ID		TD	3/28/2086
2020 PO7131986545	KU	4	30 BRO	SP	CRE	ED,ID		TD	3/29/2086
2020 PO7135686514	KU	4	40 BRO	SP	CRE	ED,ID		TD	3/30/2086
2020 PO7137686607	KU	4	30 BRO	SP	CRE	ED,ID		TD	3/31/2086
2020 PO7141086554	KU	4	40 BRO	SP	CRE	ED,ID,IP		TD	4/1/2086
2020 PO7154786614	KU	4	40 BRO	SP	CRE	ED,ID		TD	4/2/2086
2020 PO7174486694	KU	5	35 BRO	SP	CRE	ED,ID,RB	X	PX	4/3/2086
2020 PO7172786737	KU	6	30 BRO	SP	CRE	ED,HH,ID,RB	X	PX	4/4/2086
2020 PO8469467269	KU	4	45 BRO	SP	CRE	ED,ID		TD	4/5/2086
2020 PO7173886815	KU	6	30 BRO	SP	CRE	ED,ID		TD	4/6/2086
2020 PO7176686853	KU	5	35 BRO	SP	CCA		V		4/7/2086
2020 PO7201786876	KU	4	40 BRO	SP	CRE	ED,ID		BD	4/8/2086
2020 PO7175887018	KU	4	35 BRO	SP	A	ED,ID		TD	4/9/2086
2020 PO4015302457	KU	4	40 XXX	SP	CRE	ED,ID		TD	4/10/2086
2020 PO4005002481	KU	6	30 XXX	SP	CRE	ED,ID		TD	4/11/2086
2020 PO4025202451	KU	6	30 XXX	SP	CRE	ED,ID		TD	4/12/2086
2020 PO4021602720	KU	4	40 XXX	SP	CRE	ID		BD	4/13/2086
2020 PO4029602860	KU	5	25 XXX	SP	CRE	ED,ID		TD	4/14/2086
2020 PO7182587102	KU	5	30 BRO	SP	CRE	ED,ID		BD	4/15/2086
2020 PO7189787174	KU	5	35 BRO	SP	CRE	ED,ID		TD	4/16/2086
2020 PO8488367071	KU	4	40 BRO	SP	CRE	ED,ID		TD	4/17/2086
2020 PO7194987218	KU	3	45 BRO	SP	CRE	ED,ID,MD		TD	4/18/2086
2020 PO7204087140	KU	3	45 BRO	SP	CRE	ED,ID		TD	4/19/2086
2020 PO7207687116	KU	3	45 BRO	SP	CRE	ED,ID		TD	4/20/2086

Business Use

2020 PO7220887028	KU	3	45 BRO	SP	CRE	ED,ID	TD	4/21/2086
2020 PO7213486968	KU	3	45 BRO	SP	CRE	ED,ID	TD	4/22/2086
2020 PO1443360453	F	4	40 BRN	SP	P	HH	BX	4/23/2086
2020 PO1430860513	F	4	40 BRN	SP	P		V	4/24/2086
2020 PO1418260572	F	4	40 BRN	SP	CRE		V	4/25/2086
2020 PO1405960634	F	4	40 BRN	SP	CRE		V	4/26/2086
2020 PO1393060697	F	4	40 BRN	SP	CRE		V	4/27/2086
2020 PO1382460754	F	4	40 BRN	SP	CRE		V	4/28/2086
2020 PO1364160848	F	4	40 BRN	SP	A		V	4/29/2086
2020 PO1350660928	F	4	40 BRN	SP	CCA		V	4/30/2086
2020 PO1335261028	F	4	40 BRN	SP	CCA		V	5/1/2086
2020 PO1320661128	F	4	40 BRN	SP	CRE		V	5/2/2086
2020 PO1306161233	F	4	40 BRN	SP	CRE		V	5/3/2086
2020 PO1288761372	F	4	40 BRN	SP	CRE		V	5/4/2086
2020 PO1290961428	KU	4	45 BRN	SP	CCA		V	5/5/2086
2020 PO1276861463	F	4	40 BRN	ST	CRE		V	5/6/2086
2020 PO1265561553	F	4	40 BRN	SP	CRE		V	5/7/2086
2020 PO1252361657	F	4	40 BRN	SP	CRE		V	5/8/2086
2020 PO1241161744	F	4	40 BRN	SP	CRE		V	5/9/2086
2020 PO7191686781	KU	4	40 BRO	SP	CRE	ED,ID	TD	5/10/2086
2020 PO7187686753	KU	4	40 BRO	SP	CRE	ED,ID	TD	5/11/2086
2020 PO7195186643	KU	5	35 BRO	SP	CRE	ED,ID	TD	5/12/2086
2020 PO8448966425	KU	4	40 BRO	SP	CRE	ED,ID	TD	5/13/2086
2020 PO8456966544	KU	4	40 BRO	SP	CRE	ED,ID	TD	5/14/2086
2020 PO4031503001	KU	3	50 XXX	SP	CRE	ED,ID	TD	5/15/2086
2020 PO4036303141	F	6	30 XXX	SP	P		V	5/16/2086
2020 PO7256785997	KU	4	40 BRO	SP	CRE	ED,ID	BD	5/17/2086
2020 PO7237585761	KU	6	30 BRO	SP	CCA		V	5/18/2086
2020 PO7241585740	KU	4	35 BRO	SP	CRE	ED,ID	BD	5/19/2086
2020 PO8474665886	KU	3	45 BRO	SP	CCA		V	5/20/2086
2020 PO7269386203	KU	2	55 BRO	SP	CRE	ED,ID	BD	5/21/2086
2020 PO7262186024	KU	3	40 BRO	SP	CRE	ED,ID	TD	5/22/2086
2020 PO7225186777	KU	5	35 BRO	SP	CRE	ED,ID	TD	5/23/2086
2020 PO2234857349	F	4	40 BRN	SP	P		V	5/24/2086
2020 PO0871864177	F	4	40 BRN	SP	P		V	5/25/2086
2020 PO2139756800	F	3	45 BRN	SP	P		V	5/26/2086
2020 PO1595259419	F	4	40 BRN	SP	A		V	5/27/2086
2020 PO1607859340	F	4	40 BRN	SP	A		V	5/28/2086
2020 PO1586059541	F	2	50 BRN	SP	CCA		V	5/29/2086
2020 PO1576559639	F	4	40 BRN	SP	CRE		V	5/30/2086
2020 PO1564559795	F	3	50 BRN	SP	CCA		V	5/31/2086
2020 PO1552259876	F	2	50 BRN	SP	CRE	ED	V	6/1/2086
2020 PO1542359941	F	4	40 BRN	SP	CRE		V	6/2/2086
2020 PO1545359992	F	3	45E BRN	SP	CRE		V	6/3/2086
2020 PO1532360005	F	4	40 BRN	SP	CRE		V	6/4/2086
2020 PO1522860059	F	4	40 BRN	SP	CRE		V	6/5/2086
2020 PO1512560117	F	4	40 BRN	SP	CRE		V	6/6/2086

2020 PO1503960166	F	4	40 BRN	SP	CRE		V		6/7/2086
2020 PO1494560221	F	4	40 BRN	SP	P		V		6/8/2086
2020 PO1483960277	F	4	40 BRN	SP	CRE		V		6/9/2086
2020 PO1470860334	F	4	40 BRN	SP	CRE		V		6/10/2086
2020 PO1458260388	F	4	40 BRN	SP	CRE		V		6/11/2086
2020 PO2180461111	KU	4	40 BRN	SP	CRE	ID	TD		6/12/2086
2020 PO2147761189	KU	4	40 BRN	SP	CRE	ED,ID	BD		6/13/2086
2020 PO2112561274	KU	4	40 BRN	SP	CRE	ED,ID,IP	BD		6/14/2086
2020 PO2083161338	KU	4	40 BRN	SP	CRE	ED,ID,IP	X	RP2	6/15/2086
2020 PO9771989452	KU	4	45 APL	SP	CCA		V		6/16/2086
2020 PO9746689539	KU	4	45 APL	SP	CCA		V		6/17/2086
2020 PO9725289612	KU	4	45 APL	SP	CCA		V		6/18/2086
2020 PO9693589722	KU	4	45 APL	SP	CCA		V		6/19/2086
2020 PO9606792436	KU	5	35 APL	SP	CRE		V		6/20/2086
2020 PO9557097065	KU	3	50 APL	SP	CCA		V		6/21/2086
2020 PO9564693605	KU	3	45 APL	SP	CCA		V		6/22/2086
2020 PO9586692747	KU	6	30 APL	SP	CCA		V		6/23/2086
2020 PO9668189803	KU	4	45 APL	SP	CCA		V		6/24/2086
2020 PO9645689890	KU	4	45 APL	SP	CRE		V		6/25/2086
2020 PO9621289966	KU	4	45 APL	SP	CCA		V		6/26/2086
2020 PO9425988356	KU	4	40 APL	SP	CCA		V		6/27/2086
2020 PO9403788472	KU	4	40 APL	SP	CCA		V		6/28/2086
2020 PO8920594796	F	4	40 APL	SP	CRE		V		6/29/2086
2020 PO8930192128	KU	4	40 APL	SP	CRE	ED,ID,IP	BD		6/30/2086
2020 PO8953391812	KU	4	40 APL	SP	CRE	ED,ID	BD		7/1/2086
2020 PO8938091707	KU	4	40 APL	SP	CRE	ED,ID	TD		7/2/2086
2020 PO8913291537	KU	4	40 APL	SP	CRE	ED,ID	TD		7/3/2086
2020 PO8950390791	KU	4	40 APL	SP	CRE	ED,ID	BD		7/4/2086
2020 PO8936791191	KU	4	45 APL	SP	CRE	ED,ID	TD		7/5/2086
2020 PO8954591052	KU	4	45 APL	SP	CCA		V		7/6/2086
2020 PO8945691035	KU	4	35 APL	SP	CRE	ED,ID,IP	BD		7/7/2086
2020 PO8839383673	KU	3	40 BRO	SP	CCA		V		7/8/2086
2020 PO9048481268	KU	4	45 BRO	SP	CRE	ID,IP	BD		7/9/2086
2020 PO8847483665	KU	3	40 BRO	SP	CCA		V		7/10/2086
2020 PO8515580649	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD		7/11/2086
2020 PO8529280046	KU	6	30 BRO	SP	CCA		V		7/12/2086
2020 PO8961483284	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD		7/13/2086
2020 8595024315A	KU	6	30 OTH	SP	CCA		V		7/14/2086
2020 8579825140A	KU	6	30 OTH	SP	CCA		V		7/15/2086
2020 PO8664224733	F	5	35 UNK	SP	CRE	ED,ID,RB	BX	PX	7/16/2086
2020 PO8227125976	F	4	40 INP	SP	CRE		V		7/17/2086
2020 PO8688724425	F	5	35 UNK	SP	CRE	ED,ID	BX	RP3	7/18/2086
2020 PO8645724946	F	4	40 UNK	SP	CCA		V		7/19/2086
2020 PO8653024857	F	4	35 UNK	SP	P	ED,ID	BX	RP3	7/20/2086
2020 PO8238426038	F	3	45 INP	SP	P		V		7/21/2086
2020 PO8678824551	F	5	35 OTH	SP	CCA		V		7/22/2086
2020 PO8695424338	F	5	35 UNK	SP	CRE	ED,ID	BX	PX	7/23/2086

2020 PO8646924278	KU	4	40 UNK	SP	CCA		V	7/24/2086
2020 PO8671824412	KU	6	30 BRN	SP	CRE	ID	TD	7/25/2086
2020 PO8581025222	KU	6	30 OTH	SP	CCA		V	7/26/2086
2020 PO8637524404	KU	6	30 KOP	SP	CCA		V	7/27/2086
2020 PO8671624536	KU	4	40 KOP	SP	CCA		V	7/28/2086
2020 PO8612725075	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	7/29/2086
2020 PO8636724294	KU	4	40 UNK	SP	CRE	ID	TD	7/30/2086
2020 PO8595024315	KU	4	40 OTH	SP	CRE	ID	TD	7/31/2086
2020 PO6910300174	F	4	40 XXX	SP	CRE		V	8/1/2086
2020 PO6906799853	F	4	40 XXX	SP	CRE		V	8/2/2086
2020 PO6909199774	F	4	40 XXX	SP	CRE		V	8/3/2086
2020 PO2468354396	F	4	40 BRO	SP	CRE		V	8/4/2086
2020 PO2477154248	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	8/5/2086
2020 PO2479054008	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	8/6/2086
2020 PO6258203383	KU	5	30 XXX	SP	CRE	ED,ID	TD	8/7/2086
2020 PO6253103406	KU	5	35 XXX	SP	CRE	ED,ID	TD	8/8/2086
2020 PO6915199507	F	4	40 XXX	SP	CRE		V	8/9/2086
2020 PO6910199690	KU	4	40 XXX	SP	CRE	ED,ID	TD	8/10/2086
2020 PO6913099375	F	4	40 XXX	SP	CRE		V	8/11/2086
2020 PO7357390964	F	4	40 BRO	SP	CCA		V	8/12/2086
2020 PO7355090790	F	6	30 BRO	SP	CRE		V	8/13/2086
2020 PO7347590877	F	5	35 BRO	SP	CRE		V	8/14/2086
2020 PO7337990787	F	5	35 BRO	SP	CRE		V	8/15/2086
2020 PO7329290710	F	5	35 BRO	SP	CRE		V	8/16/2086
2020 PO7311090603	F	4	40 BRO	SP	CCA		V	8/17/2086
2020 PO7303890551	F	5	35 BRO	SP	CRE		V	8/18/2086
2020 PO6272503642	KU	6	30 XXX	SP	CRE	ED,ID	TD	8/19/2086
2020 PO6264903621	KU	5	40 BRN	SP	CRE	ED,ID	TD	8/20/2086
2020 PO6985495734	KU	4	45 BRN	SP	CRE	ED,ID	T	8/21/2086
2020 PO6977495881	KU	4	40 BRN	SP	CCA		V	8/22/2086
2020 PO3010840714	KU	3	45 BRN	SP	CRE	ED,ID,MD,SRC	TD	8/23/2086
2020 6275203809b	KU	6	30 XXX	SP	CRE	ED,ID	TD	8/24/2086
2020 6275203809a	KU	6	30 XXX	SP	CRE		V	8/25/2086
2020 PO6275203809	KU	4	40 ACW	SP	CRE	ED,ID	TD	8/26/2086
2020 PO2993140807	KU	3	45 BRN	SP	CRE	ED,ID,SRC	TD	8/27/2086
2020 PO3348543790	KU	4	40 ACE	SP	CRE	ED,ID	TD	8/28/2086
2020 PO3298043235	KU	4	40 ACE	SP	CRE	ED,ID	TD	8/29/2086
2020 PO6973896024	KU	4	40 BRN	SP	CRE	ED,ID	BD	8/30/2086
2020 PO7263990270	F	4	40 BRO	SP	CRE		V	8/31/2086
2020 PO7275990181	F	3	45 BRO	SP	CRE		V	9/1/2086
2020 PO7288390094	F	3	40 BRO	SP	CRE		V	9/2/2086
2020 PO7301489945	F	5	35 BRO	SP	CRE		V	9/3/2086
2020 PO7309389947	F	3	40 BRO	SP	CRE		V	9/4/2086
2020 PO4604131297	KU	3	45 BRO	SP	CCA		V	9/5/2086
2020 PO4574931360	KU	1	55 BRO	SP	CCA		V	9/6/2086
2020 PO4587131300	KU	2	55 BRO	SP	CCA		V	9/7/2086
2020 PO4601331228	KU	2	60 BRO	SP	CCA		V	9/8/2086

2020 PO4601331228-A	KU	2	50 BRO	SP	CCA		V	9/9/2086	
2020 PO2462453414	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/10/2086	
2020 PO2456353181	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	9/11/2086	
2020 PO2456353181-B	KU	5	35 BRO	SP	P	ED	T	9/12/2086	
2020 PO2456353181-A	KU	5	35 BRO	SP	P	ED	T	9/13/2086	
2020 PO2496353710	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	9/14/2086	
2020 PO2481353709	KU	4	40 BRO	SP	CRE	ID,IP	BD	9/15/2086	
2020 PO6971296123	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/16/2086	
2020 PO6974196319	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/17/2086	
2020 PO4618131130	KU	2	50 BRO	SP	P	ED	TD	9/18/2086	
2020 PO7366789195	KU	4	30 BRO	SP	CRE	HH,IP	BD	9/19/2086	
2020 PO7373389262	KU	3	50 BRO	SP	CRE	ED,ID	X	PX	9/20/2086
2020 PO7385489201	F	4	35 BRO	SP	CRE		V	9/21/2086	
2020 PO4653530881	KU	2	50 BRO	SP	CCA		V	9/22/2086	
2020 PO4646730893	KU	5	35 BRO	SP	CRE	EP,HH,ID	X	RP1	9/23/2086
2020 PO4651230982	KU	2	50 BRO	SP	CRE	ID,IP	TD	9/24/2086	
2020 PO4654230970	KU	2	50 BRO	SP	CCA		V	9/25/2086	
2020 PO465423090-A	KU	3	50 BRO	SP	CCA		V	9/26/2086	
2020 PO4673730881	KU	3	50 BRO	SP	CCA		V	9/27/2086	
2020 PO3282943069	KU	4	40 ACE	SP	CRE	ED,ID	TD	9/28/2086	
2020 PO3267742903	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	9/29/2086	
2020 PO3250942718	KU	4	40 ACE	SP	CRE	ED,ID	TD	9/30/2086	
2020 PO6274803993	KU	4	40 XXX	SP	CRE	ED,ID	TD	10/1/2086	
2020 PO6282204146	KU	6	30 ACW	SP	CRE	ED,ID	TD	10/2/2086	
2020 PO7027721047	KU	5	35 XXX	SP	CCA		V	10/3/2086	
2020 PO7013121070	KU	6	30 XXX	SP	CRE	ID	TD	10/4/2086	
2020 PO7018421067	KU	4	40 XXX	SP	CRE	ID	BD	10/5/2086	
2020 PO7031221219	KU	4	40 XXX	SP	CCA		V	10/6/2086	
2020 PO7047021075	KU	4	40 XXX	SP	CCA		V	10/7/2086	
2020 PO7047121176	KU	6	30 XXX	SP	CCA	ED	T	10/8/2086	
2020 PO7040721013	KU	6	30 XXX	SP	CCA		V	10/9/2086	
2020 PO7054721193	KU	6	30 XXX	SP	CCA		V	10/10/2086	
2020 PO7052421287	KU	6	30 XXX	SP	CCA		V	10/11/2086	
2020 PO7139790498	KU	4	35 BRN	SP	P	ED,ID	TD	10/12/2086	
2020 PO3950182590	LGE	4	40 BRN	SP	CCA		V	10/13/2086	
2020 PO2175744201	ODP	5	35 KOP	SP	CCA		V	10/14/2086	
2020 PO2177644237	ODP	4	40 KOP	SP	CRE	ED,ID	TD	10/15/2086	
2020 PO2178044135	F	4	40 KOP	SP	CRE		V	10/16/2086	
2020 PO2156843987	F	4	40 KOP	SP	CCA		V	10/17/2086	
2020 PO4433438394	KU	4	45 BRO	SP	CRE		V	10/18/2086	
2020 PO4432038406	KU	4	45 BRO	SP	CCA		V	10/19/2086	
2020 PO4437738459	KU	4	45 BRO	SP	CCA		V	10/20/2086	
2020 PO4436038474	KU	4	45 BRO	SP	CCA		V	10/21/2086	
2020 PO0555778579	KU	4	40 BRN	SP	CRE	ID,IP	BD	10/22/2086	
2020 PO0583978788	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	10/23/2086	
2020 PO0558278379	F	5	30 BRN	SP	CRE	ED,HH,RB	VX	RP3	10/24/2086
2020 PO0674278768	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	10/25/2086	

2020 PO0666578440	KU	4	40 BRN	SP	CRE	ED	TD	10/26/2086	
2020 PO0686678356	KU	4	40 BRN	SP	CRE	ED	TD	10/27/2086	
2020 PO6679302813	KU	6	30 BRO	SP	CRE		V	10/28/2086	
2020 PO0686678356-A	KU	4	40 BRN	SP	A	ED,ID,RB	TX	RR	10/29/2086
2020 PO7152190515	KU	4	35 BRN	SP	CRE	ED,ID	TD	10/30/2086	
2020 PO6224806215	KU	6	30 XXX	SP	CRE	ED,ID	TD	10/31/2086	
2020 PO6242106232	KU	4	40 BRN	SP	CRE	ED,ID	TD	11/1/2086	
2020 PO2030545696	KU	6	30 ACE	SP	CRE	ED,ID	TD	11/2/2086	
2020 PO2024845674	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	11/3/2086	
2020 PO7147390455	F	3	40 BRN	SP	CRE		V	11/4/2086	
2020 PO7144690417	F	3	40 BRN	SP	CRE		V	11/5/2086	
2020 PO6224106158	KU	6	30 BRN	SP	CCA		V	11/6/2086	
2020 PO6231206087	KU	4	40 XXX	SP	CRE	ED,ID,RB	X	RP1	11/7/2086
2020 PO6218905960	KU	6	30 BRN	SP	CCA		V	11/8/2086	
2020 PO6201006442	F	5	35 BRN	SP	CRE		V	11/9/2086	
2020 PO6206306236	F	5	35 BRN	SP	CRE		V	11/10/2086	
2020 PO6207606086	F	4	40 BRN	SP	CRE		V	11/11/2086	
2020 PO6215205916	F	4	40 BRN	SP	CRE		V	11/12/2086	
2020 PO6846101983	KU	3	40 BRO	SP	CCA		V	11/13/2086	
2020 PO6546803631	KU	3	45 BRO	SP	CCA		V	11/14/2086	
2020 PO6664902750	KU	3	45 BRO	SP	CCA		V	11/15/2086	
2020 PO6594403237	KU	4	40 BRO	SP	CRE		V	11/16/2086	
2020 PO6634702953	KU	3	45 BRO	SP	CCA		V	11/17/2086	
2020 PO6556103553	KU	3	45 BRO	SP	CCA		V	11/18/2086	
2020 PO6686802502	KU	3	45 BRO	SP	CCA		V	11/19/2086	
2020 PO6815202150	KU	3	45 BRO	SP	CCA		V	11/20/2086	
2020 PO6803902179	KU	3	45 BRO	SP	CCA		V	11/21/2086	
2020 PO6776802262	KU	3	45 BRO	SP	CCA		V	11/22/2086	
2020 PO6703302352	KU	3	45 BRO	SP	CCA		V	11/23/2086	
2020 PO6592403264	KU	3	45 BRO	SP	CCA		V	11/24/2086	
2020 PO6607103150	KU	3	45 BRO	SP	CCA		V	11/25/2086	
2020 PO6620203056	F	3	45 BRO	SP	CRE		V	11/26/2086	
2020 PO6756402339	KU	3	45 BRO	SP	CCA		V	11/27/2086	
2020 PO6565203501	KU	3	45 BRO	SP	CCA		V	11/28/2086	
2020 PO6745502382	KU	3	45 BRO	SP	CCA		V	11/29/2086	
2020 PO6698102397	KU	3	50 BRO	SP	CCA		V	11/30/2086	
2020 PO6789702225	KU	3	45 BRO	SP	CCA		V	12/1/2086	
2020 PO2532436177	F	4	40 KOP	SP	CRE		V	12/2/2086	
2020 PO2560636293	F	6	35 KOP	SP	CRE		V	12/3/2086	
2020 PO2598336500	F	4	40 UNK	SP	CRE		V	12/4/2086	
2020 PO2628236824	ODP	4	40 BRN	SP	CRE	ED,ID,SRS	TD	12/5/2086	
2020 PO2626336900	F	8	25 BRN	SP	CRE		V	12/6/2086	
2020 PO2670536837	ODP	4	40 BRN	SP	CRE	ED,ID	TD	12/7/2086	
2020 PO2683936785	ODP	4	40 BRN	SP	CRE		V	12/8/2086	
2020 PO2693636933	ODP	4	40 BRN	SP	CRE	ED,ID	TD	12/9/2086	
2020 PO2712937145	ODP	4	40 BRN	SP	CRE	ED,ID	TD	12/10/2086	
2020 PO2719737049	ODP	4	45 BRN	SP	CCA		V	12/11/2086	

2020 PO2758737033	ODP	4	45 BRN	SP	CCA		V			12/12/2086
2020 PO2736237045	ODP	4	45 BRN	SP	CCA		V			12/13/2086
2020 PO6720602319	KU	3	45 BRO	SP	CCA		V			12/14/2086
2020 PO1363321202	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TX		RR	12/15/2086
2020 PO6513303567	KU	3	45 BRO	SP	CCA		V			12/16/2086
2020 PO6487703513	KU	3	50 BRO	SP	CCA		V			12/17/2086
2020 PO6647802859	KU	3	45 BRO	SP	CCA		V			12/18/2086
2020 PO6828202042	KU	3	45 BRO	SP	CCA		V			12/19/2086
2020 PO7133090136	KU	4	35 BRO	SP	P		ED,ID,RB	TX	RR	12/20/2086
2020 PO7126290058	KU	6	30 BRN	SP	CRE	ED,ID		BD		12/21/2086
2020 PO7076190921	KU	6	30 BRN	SP	CRE		V			12/22/2086
2020 PO6201905848	KU	6	30 XXX	SP	CCA		V			12/23/2086
2020 PO6197105734	F	4	40 XXX	SP	CRE		V			12/24/2086
2020 PO7597991299	KU	5	35 BRO	SP	CRE		V			12/25/2086
2020 PO7605891455	KU	5	35 BRO	SP	CRE	RB	X		RP1	12/26/2086
2020 PO7619891410	KU	4	40 BRO	SP	CRE	ED	B			12/27/2086
2020 PO2021445217	KU	4	45 ACE	SP	CRE	ED,ID,IP		TD		12/28/2086
2020 PO2008045352	KU	6	30 ACE	SP	CRE	ED,ID		TD		12/29/2086
2020 PO7070295702	KU	4	40 BRN	SP	CRE	ED,ID		TD		12/30/2086
2020 PO4678129757	KU	3	45 BRN	SP	CRE	ID,IP		BD		12/31/2086
2020 PO4683729919	KU	2	45 BRN	SP	CRE	ID		BD		1/1/2087
2020 PO4675029666	KU	3	45 BRN	SP	CRE	ID		BD		1/2/2087
2020 PO4671629596	KU	3	45 BRN	SP	CRE	ID,IP		BX	RR	1/3/2087
2020 PO1373620869	ODP	6	30 XXX	SP	CRE	ED,ID		TD		1/4/2087
2020 PO1380121000	ODP	4	40 XXX	SP	CRE	ED,ID		TD		1/5/2087
2020 PO1366420942	F	4	40 XXX	SP	CRE		V			1/6/2087
2020 PO4697337172a	KU	5	35 ACE	SP	CCA		V			1/7/2087
2020 PO4701837258a	KU	5	35 ACE	SP	CCA		V			1/8/2087
2020 PO1332520809	ODP	4	45 XXX	SP	CRE	ED,ID		TD		1/9/2087
2020 PO1344520674	F	4	40 XXX	SP	CRE		V			1/10/2087
2020 PO4820936003a	KU	3	45 ACE	SP	CCA		V			1/11/2087
2020 PO4829235964	KU	3	45 ACE	SP	CCA		V			1/12/2087
2020 PO4822035827	KU	2	45 ACE	SP	CRE		V			1/13/2087
2020 PO4802235992	F	4	40 ACE	SP	CRE		V			1/14/2087
2020 PO4752836563	KU	1	60 ACE	SP	CCA		V			1/15/2087
2020 PO7051995907	KU	4	40 BRN	SP	CRE	ED,ID		TD		1/16/2087
2020 6183505836a	KU	5	30 XXX	SP	CRE	RB		BX	PX	1/17/2087
2020 PO6183505836	KU	5	35 XXX	SP	CRE	ED,ID		TD		1/18/2087
2020 PO6183405702	KU	5	30 XXX	SP	CRE	RB	X		RP1	1/19/2087
2020 PO6177305648	KU	4	45 XXX	SP	CRE	ED,ID		TD		1/20/2087
2020 PO6183505191	F	4	40 XXX	SP	CRE		V			1/21/2087
2020 PO6179705160	KU	6	30 XXX	SP	CRE	ID		BD		1/22/2087
2020 PO6180804997	KU	5	35 XXX	SP	CRE	ED,ID		TD		1/23/2087
2020 PO6176005110	F	6	30 XXX	SP	CRE		V			1/24/2087
2020 PO6175105219	F	4	40 BRN	SP	CRE		V			1/25/2087
2020 PO6162405768	KU	3	50 XXX	SP	CRE	ED,ID		TD		1/26/2087
2020 PO6153405405	KU	3	55 XXX	SP	CRE	ED,ID		TD		1/27/2087

2020 PO6214905345	F	4	40 XXX	SP	CRE		V		1/28/2087
2020 PO2202749923	KU	4	40 ACE	SP	CCA		V		1/29/2087
2020 PO7309794629	KU	4	40 BRN	SP	CRE	ED,ID	BD		1/30/2087
2020 PO7320094656	KU	4	40 BRN	SP	CRE	ED,ID	BD		1/31/2087
2020 PO7309394755	KU	4	35 BRN	SP	CCA	ED,ID	BD		2/1/2087
2020 PO7289294961	KU	4	45 BRN	SP	CCA		V		2/2/2087
2020 PO7295894773	KU	4	40 BRN	SP	CRE	ED,ID	TD		2/3/2087
2020 PO7631091224	F	4	35 BRO	SP	A	RB	VX	RP1	2/4/2087
2020 PO7635691362	KU	4	40 BRO	SP	CRE	ED,ID	BD		2/5/2087
2020 PO7649591139	KU	3	30 BRO	SP	CRE	ID	VX	RP3	2/6/2087
2020 PO7056295789	F	5	35 BRN	SP	CRE		V		2/7/2087
2020 PO7050495799	KU	3	45 BRN	SP	S		V		2/8/2087
2020 PO7639391685	KU	4	40 BRO	SP	CCA		V		2/9/2087
2020 PO0551047427	KU	4	40 BRN	SP	CCA		V		2/10/2087
2020 PO0945074009	KU	3	50 BRN	SP	CRE	ED	TD		2/11/2087
2020 PO0543360212	KU	5	35E BRN	SP	CRE	ED,ID,IP	TD		2/12/2087
2020 PO0543847725	KU	4	40 BRN	SP	CRE	ED,ID,IP,SRC	TD		2/13/2087
2020 PO0560047677	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD		2/14/2087
2020 PO0548746194	KU	6	35 BRN	SP	CRE	ED,ID,SRC	TD		2/15/2087
2020 PO0964273945	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		2/16/2087
2020 PO1053974483	KU	3	40 BRN	SP	CRE	ID	BD		2/17/2087
2020 PO0233652373	KU	4	40 BRN	SP	CRE	HH,IP	X	RP1	2/18/2087
2020 PO0267152182	KU	4	40 BRN	SP	CRE	ED,ID	TD		2/19/2087
2020 PO0286452092	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		2/20/2087
2020 PO0286452092-A	KU	4	35 BRN	SP	CRE	ID,IP	BD		2/21/2087
2020 PO0513846193	KU	4	40 BRN	SP	CRE	ID	BD		2/22/2087
2020 PO0646650607	KU	4	45 BRN	SP	P	ED	TD		2/23/2087
2020 PO0597650756	KU	4	45 BRN	SP	CRE	ED,ID,IP	BD		2/24/2087
2020 PO0546650889	KU	4	40 BRN	SP	CRE	ID,IP	TD		2/25/2087
2020 PO0548747120	KU	4	40 BRN	SP	CCA		V		2/26/2087
2020 PO0558847082	KU	5	35 BRN	SP	CCA		V		2/27/2087
2020 PO0728146580	KU	4	40 BRN	SP	CRE	ID	BD		2/28/2087
2020 PO0600347661	KU	4	40 BRN	SP	CRE	ED,ID,IP,RB	X	PX	3/1/2087
2020 PO0580347605	KU	4	40 BRN	SP	CRE	ID	BD		3/2/2087
2020 PO0397451846	KU	4	40 BRN	SP	CRE	ID,IP	TD		3/3/2087
2020 PO0404652070	KU	4	40 BRN	SP	CRE	ED,ID	TD		3/4/2087
2020 PO1064974718	KU	2	60 BRN	SP	CRE	ED,ID,IP	TD		3/5/2087
2020 PO0416152333	KU	4	45 BRN	SP	CRE	ID	BD		3/6/2087
2020 PO0352251785	KU	4	40 BRN	SP	CRE	ED,ID	TD		3/7/2087
2020 PO0325451910	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD		3/8/2087
2020 PO0337852040	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD		3/9/2087
2020 PO0362852389	KU	5	35 BRN	SP	CRE	ED,ID	TD		3/10/2087
2020 PO0375352637	KU	5	35 BRN	SP	CRE	ED,ID	TD		3/11/2087
2020 PO0394152988	KU	5	35 BRN	SP	CRE	ID,IP	TD		3/12/2087
2020 PO0521648603	KU	3	45 BRN	SP	CCA		V		3/13/2087
2020 PO0922374127	KU	4	40 BRN	SP	CRE	ID,IP	BD		3/14/2087
2020 PO0930974059	KU	3	50 BRN	SP	CRE	ED	TD		3/15/2087

2020 PO0946774250	KU	3	50 BRN	SP	CRE	ED	TD		3/16/2087
2020 PO0935974320	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		3/17/2087
2020 PO0971674080	KU	4	40 BRN	SP	CRE	ID,RB	X	RP1	3/18/2087
2020 PO0548448973-A	KU	4	40 BRN	SP	CCA		V		3/19/2087
2020 PO0530349105	KU	4	40 BRN	SP	CRE		T		3/20/2087
2020 PO0576148711	KU	4	40 BRN	SP	CRE	ED,ID,SRS	TD		3/21/2087
2020 PO0569648567	KU	4	40 BRN	SP	CRE	ID	BD		3/22/2087
2020 PO5672352764	KU	4	40 ACE	SP	CRE	ED,ID	TD		3/23/2087
2020 PO7909840169	LGE	4	35 BRO	SP	CCA		V		3/24/2087
2020 PO7897940078	LGE	4	35 BRO	SP	CCA		V		3/25/2087
2020 PO7874239894	LGE	4	35 BRO	SP	CCA		V		3/26/2087
2020 PO4093583137	LGE	4	40 BRO	SP	A	ED,ID	TD		3/27/2087
2020 PO4674288104	LGE	4	40 BRN	SP	CRE	ED,ID	TD		3/28/2087
2020 PO4672388091	LGE	3	45 BRN	SP	S		V		3/29/2087
2020 PO4673688107	F	4	40 BRN	SP	CRE		V		3/30/2087
2020 PO4652087834	LGE	3	55 BRO	SP	A	ED,ID	TD		3/31/2087
2020 PO4653487866	LGE	UNK	40 BRO	SP	CRE		V		4/1/2087
2020 PO4652687857	LGE	1	55 BRO	SP	CCA		V		4/2/2087
2020 PO4652287816	LGE	UNK	40 BRO	SP	CRE		V		4/3/2087
2020 PO4672488098	F	4	30 BRN	SP	CRE		V		4/4/2087
2020 PO1912033198A	ODP	6	30 UNK	SP	CRE	ID	TD		4/5/2087
2020 PO1892733251A	ODP	6	30 UNK	SP	CRE	ED,ID,SRS	TD		4/6/2087
2020 PO1892733251	ODP	4	40 BRN	SP	CRE	ID	TD		4/7/2087
2020 PO1921632716B	ODP	4	40 BRN	SP	CRE	ID	TD		4/8/2087
2020 PO1921632716A	ODP	4	40 BRN	SP	CRE	ID	TD		4/9/2087
2020 PO1948732867	ODP	4	40 KOP	SP	CRE	ED,ID,SRC	TD		4/10/2087
2020 PO1969232785	ODP	4	40 BRN	SP	CRE		V		4/11/2087
2020 PO1957132679	ODP	4	40 BRN	SP	CCA		V		4/12/2087
2020 PO1967832525	ODP	6	30 BRN	SP	CCA		V		4/13/2087
2020 PO1990332907	ODP	4	40 BRN	SP	CRE	ID	TD		4/14/2087
2020 PO2037832547	ODP	5	35 BRN	SP	CRE	ED,ID,SRC	TD		4/15/2087
2020 PO4673388108	LGE	3	45 BRN	SP	S		V		4/16/2087
2020 PO1201428758	ODP	4	40 BRN	SP	CCA	ED	TD		4/17/2087
2020 PO1222527994A	ODP	5	30 BRN	SP	CRE	ID	BD		4/18/2087
2020 PO4675988110	LGE	4	35 BRN	SP	A	ED,ID	BD		4/19/2087
2020 PO4675788114	LGE	3	45 BRN	SP	CRE	ED,ID	BD		4/20/2087
2020 PO4675988123	F	4	35 BRN	SP	A		V		4/21/2087
2020 PO4674888116	F	4	40 BRN	SP	CRE		V		4/22/2087
2020 PO4094483126	LGE	4	40 BRO	SP	A	ED,ID	BD		4/23/2087
2020 PO4097283130	LGE	3	50 BRO	SP	P	ED,ID	BD		4/24/2087
2020 PO4095583133	LGE	3	50 BRO	SP	A	ED,ID	TD		4/25/2087
2020 PO4071583203	LGE	4	40 BRO	SP	CCA		V		4/26/2087
2020 PO4071383226	LGE	3	45 BRO	SP	A		V		4/27/2087
2020 PO4071183240	LGE	4	40 BRO	SP	CCA		V		4/28/2087
2020 PO4070983248	LGE	3	45 BRO	SP	CCA		V		4/29/2087
2020 PO4069883259	LGE	4	30 BRO	SP	P	ED,ID	TD		4/30/2087
2020 PO4677388133	F	4	25 BRN	SP	A		V		5/1/2087

2020 PO4677488126	LGE	4	40 BRN	SP	CRE	ED,ID	TD	5/2/2087
2020 PO3889294118	LGE	3	45 BRN	SP	S		V	5/3/2087
2020 PO4682788162	LGE	4	40 BRN	SP	P	ED,ID	TD	5/4/2087
2020 PO4647887671	LGE	UNK	40 BRO	SP	CRE		V	5/5/2087
2020 PO4642787620	LGE	4	35 BRO	SP	CRE		V	5/6/2087
2020 PO4643887644	LGE	2	60 BRO	SP	CCA		V	5/7/2087
2020 PO4645087667	LGE	UNK	70 BRO	SP	CRE	ED,ID	BD	5/8/2087
2020 PO4680888149	LGE	4	40 BRN	SP	S		V	5/9/2087
2020 PO3917994315	LGE	4	40 BRN	SP	CCA		V	5/10/2087
2020 PO4680488155	F	4	35 BRN	SP	CCA		V	5/11/2087
2020 PO3919594325	LGE	4	40 BRN	SP	S		V	5/12/2087
2020 PO1222527994	ODP	4	45 BRN	SP	CRE	ID	TD	5/13/2087
2020 PO1226128274	ODP	4	45 BRN	SP	CRE	ID	TD	5/14/2087
2020 PO1267828837	ODP	4	45 BRN	SP	CRE	ID	BD	5/15/2087
2020 PO4643487769	LGE	2	55 BRO	SP	A	ED,ID	BD	5/16/2087
2020 PO4643887743	LGE	4	35 BRO	SP	CCA		V	5/17/2087
2020 PO4643587758	LGE	3	55 BRO	SP	A		V	5/18/2087
2020 PO3239139731	KU	4	35 ACE	SP	CRE	ED,HH,ID,IP,RB	BX	RP1 5/19/2087
2020 PO3217339743	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	5/20/2087
2020 PO3199139750	KU	4	40 ACE	SP	CRE	ED,ID	TD	5/21/2087
2020 PO3196139987	KU	4	40 ACE	SP	CRE	ED,ID	TD	5/22/2087
2020 PO3192240336	KU	4	40 ACE	SP	CRE	ED,ID,IP,RB	TX	RR 5/23/2087
2020 PO3189040620	KU	4	40 ACE	SP	CRE	ED,ID	TD	5/24/2087
2020 PO4890401631	F	4	40 BRO	SP	CRE		V	5/25/2087
2020 PO4959201633	F	4	40 BRO	SP	CCA		V	5/26/2087
2020 PO4935101633	F	4	40 BRO	SP	A		V	5/27/2087
2020 PO4911901632	F	4	40 BRO	SP	CRE		V	5/28/2087
2020 PO4869401635	F	4	40 BRO	SP	CRE		V	5/29/2087
2020 PO4880601689	F	4	40 BRO	SP	CRE		V	5/30/2087
2020 PO3178839759	KU	4	40 ACE	SP	CRE	ED,ID	TD	5/31/2087
2020 PO4917302350	KU	4	40 BRO	SP	CCA	ED	TD	6/1/2087
2020 PO4888902226	KU	3	45 BRO	SP	CCA		V	6/2/2087
2020 PO4683588180	LGE	4	35 BRN	SP	P	ED,ID	TD	6/3/2087
2020 PO4684588175	LGE	UNK	45 BRN	SP	CRE	ED,ID	BD	6/4/2087
2020 PO4635187782	LGE	4	40 BRO	SP	CCA		V	6/5/2087
2020 PO2601246522	ODP	4	40 KOP	SP	CRE	ED,ID	TD	6/6/2087
2020 PO2624246623	ODP	4	40 KOP	SP	CRE	ED,ID	TD	6/7/2087
2020 PO2640446665	ODP	4	40 KOP	SP	CRE	ED,ID	TD	6/8/2087
2020 PO2645846679	F	6	30 KOP	SP	S		V	6/9/2087
2020 PO2660646874	F	4	40 KOP	SP	A		V	6/10/2087
2020 PO2658847034	ODP	6	30 KOP	SP	CRE	ED,ID	TD	6/11/2087
2020 PO2674246793	ODP	5	35 KOP	DF	CRE	ED,ID	TD	6/12/2087
2020 PO2688947103	ODP	4	45 KOP	SP	S		V	6/13/2087
2020 PO2700246890	ODP	4	45 KOP	SP	S		V	6/14/2087
2020 PO2722146972	ODP	4	40 KOP	SP	CRE	ED,ID	TD	6/15/2087
2020 PO4640387767	LGE	4	40 BRO	SP	A	ED,ID	BD	6/16/2087
2020 PO4070283262	LGE	3	45 BRO	SP	CCA		V	6/17/2087

2020 PO4069883272	LGE	3	45 BRO	SP	CRE	ED,ID	BD	6/18/2087	
2020 PO4069783273	LGE	4	40 BRO	SP	CCA	ED,ID	BD	6/19/2087	
2020 PO4637787774	LGE	4	40 BRO	SP	CCA		V	6/20/2087	
2020 PO1240729086	ODP	5	35 BRN	SP	CRE	ID	TD	6/21/2087	
2020 PO1330628723	ODP	6	30 BRN	SP	CRE	ID	TD	6/22/2087	
2020 PO4686788185	LGE	3	45 BRN	SP	CRE	ED,ID	BD	6/23/2087	
2020 PO4686688189	LGE	3	45 BRN	SP	A	ED,ID	BD	6/24/2087	
2020 PO4687788196	LGE	4	40 BRN	SP	CRE	ED,ID	TD	6/25/2087	
2020 PO4198313623	KU	3	45 BRO	SP	CCA		V	6/26/2087	
2020 PO4190013594	KU	3	45 BRO	SP	CCA		V	6/27/2087	
2020 PO4642787761	LGE	3	50 BRO	SP	A		V	6/28/2087	
2020 PO4688988198	LGE	4	35 BRN	SP	CRE	ED,HH,ID	TX	RR	6/29/2087
2020 PO3990794718	LGE	3	45 BRN	SP	S		V	6/30/2087	
2020 PO4683888178	F	4	40 BRN	SP	S		V	7/1/2087	
2020 PO4684488182	F	4	35 BRN	SP	CRE		V	7/2/2087	
2020 PO4685788191	F	4	35 BRN	SP	CRE		V	7/3/2087	
2020 PO4687388202	F	4	35 BRN	SP	CRE		V	7/4/2087	
2020 PO4688688203	LGE	4	40 BRN	SP	CRE	HH,ID	BD	7/5/2087	
2020 PO4191513382	KU	3	45 BRO	SP	CCA		V	7/6/2087	
2020 PO4688388208	F	4	35 BRN	SP	CRE		V	7/7/2087	
2020 PO4688888213	F	4	40 BRN	SP	A		V	7/8/2087	
2020 PO4689388216	F	4	30 BRN	SP	CRE		V	7/9/2087	
2020 PO4690888207	LGE	4	35 BRN	SP	CRE	ED,ID	BD	7/10/2087	
2020 PO4690588212	LGE	4	35 BRN	SP	CRE	ED,ID	BD	7/11/2087	
2020 PO4690388215	LGE	3	45 BRN	SP	S		V	7/12/2087	
2020 PO4690588225	F	4	45 BRN	SP	S		V	7/13/2087	
2020 PO4018113598	KU	3	45 BRO	SP	CCA		V	7/14/2087	
2020 PO4034513553	KU	3	45 BRO	SP	CRE	ID,IP	BD	7/15/2087	
2020 PO4011213683	KU	3	45 BRO	SP	CCA		V	7/16/2087	
2020 PO4691688232	F	4	30 BRN	SP	CCA		V	7/17/2087	
2020 PO4692988224	LGE	4	30 BRN	SP	CCA		V	7/18/2087	
2020 PO4691888225	LGE	1	50 BRN	SP	S		V	7/19/2087	
2020 PO4691988245	LGE	4	40 BRN	SP	A	ED,ID	BD	7/20/2087	
2020 PO4693188235	LGE	4	40 BRN	SP	CRE		V	7/21/2087	
2020 PO1455730761	F	4	40 BRN	SP	A		V	7/22/2087	
2020 PO1447530689	ODP	4	40 BRN	SP	A	ID	TD	7/23/2087	
2020 PO1412330496	F	5	45 BRN	SP	A		V	7/24/2087	
2020 PO1398230363	F	5	35 BRN	SP	A		V	7/25/2087	
2020 PO9710095448	KU	6	30 ACW	SP	CRE	ED,ID,SRC	TX	RR	7/26/2087
2020 PO9710095352	KU	4	40 ACW	SP	CRE	ED,ID	TD	7/27/2087	
2020 PO9705595164	KU	3	40 ACW	SP	S		V	7/28/2087	
2020 PO9701795290	KU	4	40 ACW	SP	CRE	ED,ID,SRC	TD	7/29/2087	
2020 PO9701495156	C	2	45 ACW	SP	S		V	7/30/2087	
2020 PO9148493838	KU	5	35 XXX	SP	CRE	ED,ID	TD	7/31/2087	
2020 PO5253728443	KU	3	45 BRO	SP	CCA		V	8/1/2087	
2020 PO5197528187	KU	3	45 BRO	SP	CCA		V	8/2/2087	
2020 PO5170128064	KU	3	45 BRO	SP	CCA		V	8/3/2087	

2020 PO5142327945	KU	4	40 BRO	SP	CRE	ED,ID	TD	8/4/2087
2020 PO9158293737	C	4	40 BRN	SP	CRE		V	8/5/2087
2020 PO9161393874	KU	3	45 BRN	SP	CCA		V	8/6/2087
2020 PO9155993800	KU	5	35 BRN	SP	CCA		V	8/7/2087
2020 PO9232593781	KU	6	30 BRN	SP	CCA		V	8/8/2087
2020 PO9165793756	C	4	40 BRN	SP	CRE		V	8/9/2087
2020 PO9175593830	F	6	30 XXX	SP	CRE		V	8/10/2087
2020 PO6049048705	KU	3	45 ACE	SP	CCA		V	8/11/2087
2020 5106528271	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/12/2087
2020 PO4727618125	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	8/13/2087
2020 PO4703617716-C	KU	5	35 BRO	SP	CRE	ED,ID	TD	8/14/2087
2020 PO4703617716-B	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/15/2087
2020 PO4703617716-A	KU	4	40 BRO	SP	A	HH,RB	X	RP1 8/16/2087
2020 PO4703617716	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/17/2087
2020 PO4757517758	KU	4	40 BRO	SP	A		V	8/18/2087
2020 PO4769517860	KU	4	45 BRO	SP	CCA		V	8/19/2087
2020 PO4768917642	KU	3	45 BRO	SP	CCA		V	8/20/2087
2020 PO4753417478	KU	5	35 BRO	SP	CCA		V	8/21/2087
2020 PO4768817463	KU	3	45 BRO	SP	CRE		V	8/22/2087
2020 PO9744792184	KU	4	40 ACW	SP	CRE	ED,ID,RB	TX	RR 8/23/2087
2020 PO5325046417	KU	4	45 ACE	SP	CRE	ED,ID,IP	TD	8/24/2087
2020 PO9755392410	KU	4	40 ACW	SP	CRE	ED,ID	TD	8/25/2087
2020 PO5307446527	KU	4	45 ACE	SP	CRE	ED,ID,IP	TD	8/26/2087
2020 PO5323146490	KU	6	30 ACE	SP	CRE	ED,ID	TD	8/27/2087
2020 PO4444404682	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/28/2087
2020 PO4431204616	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	8/29/2087
2020 PO9762092598	KU	3	45 ACW	SP	CCA		V	8/30/2087
2020 PO9773492761	KU	3	45 ACW	SP	CCA		V	8/31/2087
2020 PO9761792850	KU	3	45 ACW	SP	CCA		V	9/1/2087
2020 PO4486204478	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/2/2087
2020 PO9761993070	KU	3	45 ACW	SP	CCA		V	9/3/2087
2020 PO5241948493	KU	4	40 ACE	SP	CCA	ED	T	9/4/2087
2020 PO9796593544	KU	4	45 ACW	SP	CRE	ED,ID	TD	9/5/2087
2020 PO9818193667	KU	4	40 ACW	SP	CRE	ED,ID	TD	9/6/2087
2020 PO9793493659	KU	5	35 ACW	SP	CCA		V	9/7/2087
2020 PO5291747623a	KU	3	45 ACE	SP	CCA		V	9/8/2087
2020 PO1664834315	ODP	3	55 BRN	SP	CRE	ID	TD	9/9/2087
2020 PO1631834334	ODP	2	50 BRN	SP	CRE	ED,ID,SRC	TD	9/10/2087
2020 PO2466746280	ODP	6	30 KOP	SP	S		V	9/11/2087
2020 PO2811448234	F	4	40 KOP	SP	CCA		V	9/12/2087
2020 PO2853148550	F	4	40 KOP	SP	CRE		V	9/13/2087
2020 PO2876149211	F	4	40 KOP	SP	CCA		V	9/14/2087
2020 PO4372837451	KU	4	45 BRO	SP	CRE		V	9/15/2087
2020 PO4377237516	KU	4	45 BRO	SP	CRE		V	9/16/2087
2020 PO1589621414	ODP	4	40 XXX	SP	CCA		V	9/17/2087
2020 PO1597021253	ODP	4	40 XXX	SP	CCA		V	9/18/2087
2020 PO2849649771	ODP	4	40 KOP	SP	CRE	ED,ID	TD	9/19/2087

2020 PO1584821542	ODP	4	40 XXX	SP	CRE	ID	TD	9/20/2087	
2020 PO1578721694	ODP	5	35 XXX	SP	CRE	ID	TD	9/21/2087	
2020 PO1572721877	ODP	5	35 XXX	SP	CRE	ID	TD	9/22/2087	
2020 PO1557722026	ODP	6	30 XXX	SP	CCA	ED	T	9/23/2087	
2020 PO1565922094	ODP	5	35 XXX	SP	CRE	ID	TD	9/24/2087	
2020 PO1397923196	ODP	4	45 XXX	SP	CCA		V	9/25/2087	
2020 PO1379036278	ODP	4	45 KOP	SP	CRE	ED,ID	TD	9/26/2087	
2020 PO2465946294	ODP	6	30 KOP	SP	CCA	ED,ID	TD	9/27/2087	
2020 PO1632534366	ODP	2	50 UNK	SP	CRE	ED,ID,SRC	TD	9/28/2087	
2020 PO1726633433	ODP	4	45 BRN	SP	CCA		V	9/29/2087	
2020 PO1707233382	ODP	4	40 BRN	SP	CRE	ID	TD	9/30/2087	
2020 PO1759433511B	ODP	3	45 BRN	SP	CCA		V	10/1/2087	
2020 PO17594	ODP	4	40 BRN	SP	CCA		V	10/2/2087	
2020 PO1782033600	ODP	5	35 KOP	SP	CRE	ED,HH,ID	TX	RR	10/3/2087
2020 PO1767533969	ODP	5	35 KOP	SP	CRE	ID	TD	10/4/2087	
2020 PO1753134345	ODP	5	35 BRN	SP	CRE	ID	TD	10/5/2087	
2020 PO1677934496	ODP	4	45 BRN	SP	CCA		V	10/6/2087	
2020 PO1735234807	ODP	4	40 UNK	SP	CRE	ID	TD	10/7/2087	
2020 PO1734135410	ODP	4	40 BRN	SP	CRE	ID	TD	10/8/2087	
2020 PO1620332306	ODP	4	40 BRN	SP	CRE	ID	TD	10/9/2087	
2020 PO2892948908	F	4	40 KOP	SP	CRE		V	10/10/2087	
2020 PO2862949508	ODP	6	35 KOP	SP	S		V	10/11/2087	
2020 PO4491811539	F	4	40 ACE	SP	CRE		V	10/12/2087	
2020 PO4502611500	F	4	40 ACE	SP	CRE		V	10/13/2087	
2020 PO4516011452	F	4	40 ACE	SP	CRE		V	10/14/2087	
2020 PO5824750384	F	4	40 ACE	SP	CRE		V	10/15/2087	
2020 PO4699106142	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	10/16/2087	
2020 PO4709906359	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	10/17/2087	
2020 PO5787850466	KU	5	35 ACE	SP	CRE	ED,ID	BD	10/18/2087	
2020 PO5781350360	KU	6	30 ACE	SP	CRE	ED,ID	BD	10/19/2087	
2020 PO8069443588	LGE	3	45 BRN	SP	S		V	10/20/2087	
2020 PO4087283190	LGE	3	45 BRN	SP	S		V	10/21/2087	
2020 PO8056343779	LGE	3	45 BRN	SP	S		V	10/22/2087	
2020 PO9507236736	ODP	3	45 BRN	SP	CRE		V	10/23/2087	
2020 PO9522436241	ODP	4	45 BRN	SP	CRE		V	10/24/2087	
2020 PO9532236037	ODP	4	45 BRN	SP	CCA		V	10/25/2087	
2020 PO9496936767	ODP	6	30 BRN	SP	CCA		V	10/26/2087	
2020 PO4086683206	LGE	4	40 BRN	SP	CRE	HH,ID	TD	10/27/2087	
2020 PO4085783228	LGE	4	40 BRN	SP	CRE	ED,ID	TD	10/28/2087	
2020 PO3967283100	LGE	4	40 BRO	SP	A	ED,ID,MD	BD	10/29/2087	
2020 PO3967083087	LGE	4	30 BRO	SP	CRE	ED,ID	TD	10/30/2087	
2020 PO3967283108	LGE	4	35 BRO	SP	CRE	ED,ID	TD	10/31/2087	
2020 PO3967183102	LGE	4	30 BRO	SP	P	ED,ID	TD	11/1/2087	
2020 PO3967683100	LGE	3	45 BRO	SP	CCA		V	11/2/2087	
2020 PO6854342655	LGE	3	45 BRO	SP	CCA		V	11/3/2087	
2020 PO3969683109	LGE	4	30 BRO	SP	A	ED,ID	BD	11/4/2087	
2020 PO1313029813	ODP	4	40 BRN	SP	CRE	ID	TD	11/5/2087	

2020 PO1301229952	ODP	4	40 BRN	SP	CRE	ID	TD	11/6/2087
2020 PO1290130073	ODP	3	45 BRN	SP	P	ID	BD	11/7/2087
2020 PO1217930858	ODP	3	45 BRN	SP	P		V	11/8/2087
2020 PO1242730601	F	4	40 BRN	SP	CRE		V	11/9/2087
2020 PO1236431269	ODP	6	30 BRN	SP	CCA		V	11/10/2087
2020 PO1230431192	ODP	5	35 BRN	SP	CRE	ID	TD	11/11/2087
2020 PO1240031097	ODP	5	35 BRN	SP	CRE	ID	TD	11/12/2087
2020 PO1208130965	F	4	40 BRN	SP	CRE		V	11/13/2087
2020 PO4002012250	KU	3	45 BRO	SP	CRE	ID	BD	11/14/2087
2020 PO4008412404	KU	2	45 BRO	SP	CRE	ID,IP	BD	11/15/2087
2020 PO9543436530	ODP	4	45 BRN	SP	CCA		V	11/16/2087
2020 PO9551136673	ODP	4	45 BRN	SP	CCA		V	11/17/2087
2020 PO4085183241	LGE	3	45 BRN	SP	S		V	11/18/2087
2020 PO4085983246	LGE	3	45 BRN	SP	S		V	11/19/2087
2020 PO4085483254	LGE	4	30 BRN	SP	CRE	ED,ID	BD	11/20/2087
2020 PO4084883253	LGE	4	40 BRN	SP	CRE	ED,ID	BD	11/21/2087
2020 PO2086232428	ODP	4	40 KOP	SP	CRE	ID	TD	11/22/2087
2020 PO2060132491	F	4	35 KOP	SP	CRE		V	11/23/2087
2020 PO2110332372	ODP	4	40 BRN	SP	CRE	ID	TD	11/24/2087
2020 PO2063331226	ODP	5	35 UNK	SP	CRE	ID	TD	11/25/2087
2020 PO2095732164	ODP	4	40 BRN	SP	CRE	ID	BD	11/26/2087
2020 PO2112132232	ODP	4	40 ESC	SP	CRE	ED,ID,SRC	TD	11/27/2087
2020 PO9130630176	ODP	5	35 XXX	SP	CRE	ED,ID	TD	11/28/2087
2020 PO9121930153	ODP	6	30 BRN	SP	CRE	ED,ID,IP	TD	11/29/2087
2020 PO9134030352	ODP	4	40 BRN	SP	CCA	ED	T	11/30/2087
2020 PO9142730557	ODP	4	40 BRN	SP	CRE	ED,ID	TD	12/1/2087
2020 PO3970682356	F	4	40 BRN	SP	CRE		V	12/2/2087
2020 PO3971282372	F	4	40 BRN	SP	CCA		V	12/3/2087
2020 PO3971482385	F	3	45 BRN	SP	CCA		V	12/4/2087
2020 PO3970982399	F	4	40 BRN	SP	CRE		V	12/5/2087
2020 PO3971382404	F	4	30 BRN	SP	CRE		V	12/6/2087
2020 PO2199741951	ODP	4	45 KOP	SP	A	ED,ID	TD	12/7/2087
2020 PO2239642030	ODP	5	35 KOP	SP	CRE	ED,ID	TD	12/8/2087
2020 PO2219041990	ODP	5	35 KOP	SP	CRE	ED,ID	TD	12/9/2087
2020 PO0511736126a	ODP	6	25 BRN	SP	CRE	ED,ID,IP	TD	12/10/2087
2020 PO0511736126	F	4	40 BRN	SP	A		V	12/11/2087
2020 PO4517829544	KU	3	45 ACE	SP	CRE	ED,ID	TD	12/12/2087
2020 PO3970782414	F	4	40 BRN	SP	CRE		V	12/13/2087
2020 PO3970682428	F	4	40 BRN	SP	CRE		V	12/14/2087
2020 PO3970582442	F	4	40 BRN	SP	CRE		V	12/15/2087
2020 PO3971982444	LGE	4	40 BRN	SP	CRE		V	12/16/2087
2020 PO3070539388A	ODP	6	30 BRN	SP	CCA		V	12/17/2087
2020 PO2929239427	ODP	5	35 BRN	SP	CRE	ED,ID	TD	12/18/2087
2020 PO2938239283	F	4	40 BRN	SP	CRE		V	12/19/2087
2020 PO4694024494	KU	3	45 BRO	SP	CCA		V	12/20/2087
2020 PO	KU	3	45 BRO	SP	CCA		V	12/21/2087
2020 PO4681124431	KU	3	45 BRO	SP	CCA		V	12/22/2087

2020 PO5861946429	F	4	40 ACE	SP	CCA		V	12/23/2087
2020 PO5866046202	F	4	40 ACE	SP	CCA		V	12/24/2087
2020 PO5870145966	F	4	40 ACE	SP	CCA		V	12/25/2087
2020 PO5874745579	F	4	40 ACE	SP	CCA		V	12/26/2087
2020 PO5881345440	F	4	40 ACE	SP	CCA		V	12/27/2087
2020 PO5810044582	KU	6	30 ACE	SP	CCA		V	12/28/2087
2020 PO5822544542	KU	3	45 ACE	SP	CCA		V	12/29/2087
2020 PO5795844519	KU	6	30 ACE	SP	CCA		V	12/30/2087
2020 PO5764344459	KU	6	30 ACE	SP	CCA		V	12/31/2087
2020 PO5750044633	KU	6	30 ACE	SP	CCA		V	1/1/2088
2020 PO5775344692	KU	6	30 ACE	DF	CCA		V	1/2/2088
2020 PO2902639584	ODP	3	45 BRN	SP	CCA		V	1/3/2088
2020 PO2917139325	ODP	3	45 BRN	SP	CCA		V	1/4/2088
2020 PO2907639469	ODP	4	40 BRN	SP	CCA		V	1/5/2088
2020 PO2902939581	ODP	4	40 BRN	SP	CCA		V	1/6/2088
2020 PO2992739935	ODP	4	45 BRN	SP	CRE	ED,ID	TD	1/7/2088
2020 PO3020040162	ODP	4	40 BRN	SP	CRE		V	1/8/2088
2020 PO2995840243	ODP	6	30 BRN	SP	CRE	ED,ID	TD	1/9/2088
2020 PO3005739669	F	6	30 BRN	SP	CRE		V	1/10/2088
2020 PO3009339598	ODP	5	35 BRN	SP	CCA		V	1/11/2088
2020 PO3062140514	ODP	4	40 KOP	SP	CRE	ED,ID	TD	1/12/2088
2020 PO3038439925	ODP	4	45 BRN	SP	CCA		V	1/13/2088
2020 PO3070539388	ODP	4	40 BRN	SP	CRE		V	1/14/2088
2020 PO3085439618	ODP	4	45 BRN	SP	CCA		V	1/15/2088
2020 PO3068739710	ODP	4	45 BRN	SP	CCA		V	1/16/2088
2020 PO3094839934	ODP	4	45 BRN	SP	CRE		V	1/17/2088
2020 PO3112540137	ODP	4	45 BRN	SP	CCA		V	1/18/2088
2020 PO3970482455	F	4	40 BRN	SP	CRE		V	1/19/2088
2020 PO3970482468	F	4	40 BRN	SP	CRE		V	1/20/2088
2020 PO3971082474	F	3	45 BRN	SP	S		V	1/21/2088
2020 PO2673227789	ODP	6	35 BRN	SP	CRE	ID	BD	1/22/2088
2020 PO2682527830	ODP	4	40 BRN	SP	CRE	ID	BD	1/23/2088
2020 PO2675227935	F	4	40 BRN	SP	CCA		V	1/24/2088
2020 PO2666128072	ODP	4	40 BRN	SP	CRE	ID	TD	1/25/2088
2020 PO2643528018	ODP	4	40 BRN	SP	CRE	ID	BD	1/26/2088
2020 PO3972382475	F	3	45 BRN	SP	S		V	1/27/2088
2020 PO3973882476	F	4	40 BRN	SP	CRE		V	1/28/2088
2020 PO1786922434A	ODP	6	30 XXX	SP	CCA		V	1/29/2088
2020 PO1786922434	ODP	6	30 XXX	SP	CRE	ID	TD	1/30/2088
2020 PO1784222530	ODP	4	45 XXX	SP	CRE	ID	TD	1/31/2088
2020 PO0493536002a	ODP	6	30 BRN	SP	CCA		V	2/1/2088
2020 PO0493536002	ODP	4	40 BRN	SP	CCA		V	2/2/2088
2020 PO0499135932	ODP	6	30 BRN	SP	CRE	ED,ID	TD	2/3/2088
2020 PO3975182488	F	4	40 BRN	SP	CRE		V	2/4/2088
2020 PO3976582477	F	4	40 BRN	SP	CRE		V	2/5/2088
2020 PO3977182469	F	4	40 BRN	SP	CRE		V	2/6/2088
2020 PO3977282455	F	4	40 BRN	SP	CRE		V	2/7/2088

2020 PO3977382442	F	3	45 BRN	SP	S		V	2/8/2088
2020 PO4507029478	KU	3	45 ACE	SP	CRE	ED,ID	TD	2/9/2088
2020 PO4566430050	KU	3	45 ACE	SP	CCA		V	2/10/2088
2020 PO3977482427	F	4	40 BRN	SP	CRE		V	2/11/2088
2020 PO3977482417	F	4	40 BRN	SP	CRE		V	2/12/2088
2020 PO3976782404	F	4	40 BRN	SP	CRE		V	2/13/2088
2020 PO3975882386	F	4	40 BRN	SP	S		V	2/14/2088
2020 PO3975182374	F	4	40 BRN	SP	CRE		V	2/15/2088
2020 PO3974582361	F	4	40 BRN	SP	S		V	2/16/2088
2020 PO0474535546	ODP	4	40 ACW	SP	CRE	ED,ID	TD	2/17/2088
2020 PO0449935721	ODP	5	35 XXX	SP	CRE	ED,ID	TD	2/18/2088
2020 PO0466735532	ODP	6	30 BRN	SP	CCA		V	2/19/2088
2020 PO3973682355	F	4	40 BRN	SP	CRE		V	2/20/2088
2020 PO4626038693	KU	3	45 BRO	SP	P		T	2/21/2088
2020 PO3972182357	F	4	40 BRN	SP	A		V	2/22/2088
2020 PO3974282393	F	4	40 BRN	SP	CRE		V	2/23/2088
2020 PO4631638714	KU	1	55 BRO	SP	CCA		V	2/24/2088
2020 PO3974082405	F	3	45 BRN	SP	S		V	2/25/2088
2020 PO1255420685	ODP	5	35 XXX	SP	CRE	ED,ID	BD	2/26/2088
2020 PO1256220858	ODP	4	45 XXX	SP	CRE	ID	TD	2/27/2088
2020 PO1243120775	ODP	6	30 XXX	SP	CRE	ID	TD	2/28/2088
2020 PO1250520972	F	4	40 XXX	SP	CRE		V	2/29/2088
2020 PO1243421110	ODP	6	30 XXX	SP	CRE	ID	TD	3/1/2088
2020 PO1232521077	ODP	6	30 BRN	SP	CCA		V	3/2/2088
2020 PO1274620523	ODP	6	30 XXX	SP	CCA		V	3/3/2088
2020 PO1268220516	ODP	6	30 XXX	SP	CCA		V	3/4/2088
2020 PO1266320556	ODP	3	50 XXX	SP	CCA	ED	TD	3/5/2088
2020 PO1273520316	F	4	40 XXX	SP	CRE		V	3/6/2088
2020 PO1270520451	F	7	20 XXX	SP	CCA		V	3/7/2088
2020 PO1261920245	F	4	40 XXX	SP	CRE		V	3/8/2088
2020 PO1251420196	F	4	40 XXX	SP	A		V	3/9/2088
2020 PO1257819690	F	4	40 XXX	SP	A		V	3/10/2088
2020 PO1246519931	F	4	40 XXX	SP	A		V	3/11/2088
2020 PO1286220660	ODP	6	30 BRN	SP	CCA		V	3/12/2088
2020 PO1286420465	ODP	6	30 BRN	SP	CRE	ID	TD	3/13/2088
2020 PO1286220734	ODP	6	30 BRN	SP	CCA		V	3/14/2088
2020 PO1286220699	ODP	6	30 BRN	SP	CCA		V	3/15/2088
2020 PO5823244789	KU	6	30 ACE	SP	CCA		V	3/16/2088
2020 PO4841523158	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	3/17/2088
2020 PO5847744837	KU	6	30 ACE	SP	CCA		V	3/18/2088
2020 PO4840822999	C	4	40 BRO	SP	CRE		V	3/19/2088
2020 PO4906023330	KU	3	45 BRO	SP	CCA		V	3/20/2088
2020 PO4879423224	KU	4	45 BRO	SP	CRE	ED,ID	TD	3/21/2088
2020 PO5871144937	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	3/22/2088
2020 PO5872244886	KU	5	35 ACE	SP	CCA		V	3/23/2088
2020 PO5880444955	KU	3	45 ACE	SP	CCA		V	3/24/2088
2020 PO5931744617	KU	3	45 ACE	SP	CCA		V	3/25/2088

2020 PO5870544572	KU	3	45 ACE	SP	CCA		V	3/26/2088
2020 PO474	KU	4	40 BRO	SP	CCA		V	3/27/2088
2020 PO4706825703	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/28/2088
2020 PO4742825661	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	3/29/2088
2020 PO3973982419	F	4	40 BRN	SP	CRE		V	3/30/2088
2020 PO3974282434	F	4	30 BRN	SP	A		V	3/31/2088
2020 PO3973882433	F	4	40 BRN	SP	CRE		V	4/1/2088
2020 PO3975182448	F	4	30 BRN	SP	A		V	4/2/2088
2020 PO3973682447	F	4	40 BRN	SP	CRE		V	4/3/2088
2020 PO1792822522	ODP	5	35 XXX	SP	CRE	ID	TD	4/4/2088
2020 PO1789522845	ODP	6	30 XXX	SP	CCA		V	4/5/2088
2020 PO1786222941	ODP	4	40 XXX	SP	CRE	ID	BD	4/6/2088
2020 PO1795622926	ODP	6	30 XXX	SP	CCA		V	4/7/2088
2020 PO0452035065	ODP	6	30 XXX	SP	CRE	ID	BD	4/8/2088
2020 PO2432123837	ODP	6	30 BRN	SP	CRE		V	4/9/2088
2020 PO2420123929	ODP	4	40 BRN	SP	CCA		V	4/10/2088
2020 PO2447924052	ODP	4	40 BRN	SP	CCA		V	4/11/2088
2020 PO2463723667	ODP	4	40 BRN	SP	CCA		V	4/12/2088
2020 PO2476723431	ODP	4	40 BRN	SP	CCA		V	4/13/2088
2020 PO2486823172	ODP	4	40 BRN	SP	CCA		V	4/14/2088
2020 PO2498222995	ODP	4	40 BRN	SP	CCA		V	4/15/2088
2020 PO2509622761	ODP	4	40 BRN	SP	CCA		V	4/16/2088
2020 PO4676739062	KU	3	45 BRO	SP	CCA		V	4/17/2088
2020 PO4676839047	KU	3	45 BRO	SP	CCA		V	4/18/2088
2020 PO4671338969	KU	3	45 BRO	SP	CCA		V	4/19/2088
2020 PO4667038908	KU	3	45 BRO	SP	CCA		V	4/20/2088
2020 PO3973582461	F	3	45 BRN	SP	S		V	4/21/2088
2020 PO4558230120	KU	3	55 ACE	SP	CCA		V	4/22/2088
2020 PO0466635018	F	4	40 XXX	SP	CRE		V	4/23/2088
2020 PO0468335159	ODP	4	40 XXX	SP	CRE	ED,ID	TD	4/24/2088
2020 PO0457035160	ODP	2	50 XXX	SP	CRE	ED,ID	TD	4/25/2088
2020 PO0458035011	F	4	40 XXX	SP	CRE		V	4/26/2088
2020 PO0441835381	F	4	40 XXX	SP	A		V	4/27/2088
2020 PO0456635368	ODP	2	50 XXX	SP	CCA		V	4/28/2088
2020 PO3976882587	F	3	45 BRN	SP	S		V	4/29/2088
2020 PO3975282588	F	4	40 BRN	SP	A		V	4/30/2088
2020 PO3973082587	F	4	40 BRN	SP	A		V	5/1/2088
2020 PO3972382584	LGE	3	45 BRN	SP	S		V	5/2/2088
2020 PO3979582590	F	4	40 BRN	SP	A		V	5/3/2088
2020 PO4580829964	KU	1	65 ACE	SP	CRE	ED,ID	BD	5/4/2088
2020 PO2516922603	ODP	4	40 BRN	SP	CCA		V	5/5/2088
2020 PO4684625727	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	5/6/2088
2020 PO5915647576	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD	5/7/2088
2020 PO5929047427	KU	3	45 ACE	SP	CCA		V	5/8/2088
2020 PO5942647281	KU	4	45 ACE	SP	CCA		V	5/9/2088
2020 PO9655595072	C	4	40 ACW	SP	CRE		V	5/10/2088
2020 PO9657395007	C	4	40 ACW	SP	CRE		V	5/11/2088

2020 PO9657994975	C	4	40 ACW	SP	CRE		V		5/12/2088
2020 PO9658594917	C	4	40 ACW	SP	CRE		V		5/13/2088
2020 PO9660294860	C	4	40 ACW	SP	CRE		V		5/14/2088
2020 PO9668294474	C	4	40 ACW	SP	CRE		V		5/15/2088
2020 PO9662794488	C	4	40 ACW	SP	CRE		V		5/16/2088
2020 PO9665194471	C	4	40 ACW	SP	CRE		V		5/17/2088
2020 PO9664694439	KU	5	35 ACW	SP	S		V		5/18/2088
2020 PO9664794412	KU	6	30 ACW	SP	S		V		5/19/2088
2020 PO4643625562	KU	4	40 BRO	SP	CRE	HH, RB	X	RP1	5/20/2088
2020 PO4664325739	KU	3	45 BRO	SP	CCA		V		5/21/2088
2020 PO4701026296-A	KU	3	45 BRO	SP	CCA		V		5/22/2088
2020 PO4677026695	KU	4	40 BRO	SP	CCA		V		5/23/2088
2020 PO9820493006	F	4	40 ACW	SP	P		V		5/24/2088
2020 PO3913782446	F	4	40 BRO	SP	CCA		V		5/25/2088
2020 PO3916082431	F	3	45 BRO	SP	A		V		5/26/2088
2020 PO3917482422	F	4	40 BRO	SP	CCA		V		5/27/2088
2020 PO3918482416	F	3	45 BRO	SP	A		V		5/28/2088
2020 PO3920482409	F	4	30 BRO	SP	CCA		V		5/29/2088
2020 PO3911682424	F	4	30 BRO	SP	CCA		V		5/30/2088
2020 PO3910682466	F	3	45 BRO	SP	A		V		5/31/2088
2020 PO3909982454	F	4	40 BRO	SP	CCA		V		6/1/2088
2020 PO3910282433	F	4	30 BRO	SP	CCA		V		6/2/2088
2020 PO3908982441	F	4	30 BRO	SP	CCA		V		6/3/2088
2020 PO3907782448	F	4	30 BRO	SP	CCA		V		6/4/2088
2020 PO3909282443	F	4	40 BRO	SP	CCA		V		6/5/2088
2020 PO3910782434	F	4	40 BRO	SP	CCA		V		6/6/2088
2020 PO3912082426	F	4	40 BRO	SP	CCA		V		6/7/2088
2020 PO3912782415	F	4	40 BRO	SP	CCA		V		6/8/2088
2020 PO3912682404	F	4	40 BRO	SP	CCA		V		6/9/2088
2020 PO3904382394	F	4	40 BRO	SP	CCA		V		6/10/2088
2020 PO3905882389	F	4	35 BRO	SP	CCA		V		6/11/2088
2020 PO3905682385	F	4	40 BRO	SP	CCA		V		6/12/2088
2020 PO3906882378	F	4	40 BRO	SP	CCA		V		6/13/2088
2020 PO3908182370	F	4	40 BRO	SP	CCA		V		6/14/2088
2020 PO3905882422	F	4	40 BRO	SP	CCA		V		6/15/2088
2020 PO3907282413	F	4	40 BRO	SP	CCA		V		6/16/2088
2020 PO3908582405	F	4	40 BRO	SP	CCA		V		6/17/2088
2020 PO3909982397	F	4	40 BRO	SP	CCA		V		6/18/2088
2020 PO3909382362	F	4	40 BRO	SP	CCA		V		6/19/2088
2020 PO3911182389	F	4	40 BRO	SP	CCA		V		6/20/2088
2020 PO3910782354	F	4	40 BRO	SP	CCA		V		6/21/2088
2020 PO3912482388	F	4	40 BRO	SP	CCA		V		6/22/2088
2020 PO3912282373	F	4	40 BRO	SP	CCA		V		6/23/2088
2020 PO3912082358	F	4	40 BRO	SP	CCA		V		6/24/2088
2020 PO3911882342	F	4	40 BRO	SP	CCA		V		6/25/2088
2020 PO3911782334	F	4	40 BRO	SP	CCA		V		6/26/2088
2020 PO3911382333	F	4	30 BRO	SP	CCA		V		6/27/2088

2020 PO3902682366	F	4	40 BRO	SP	CCA		V	6/28/2088
2020 PO3903982358	F	4	40 BRO	SP	CCA		V	6/29/2088
2020 PO3905282350	F	4	40 BRO	SP	CCA		V	6/30/2088
2020 PO3906582342	F	4	40 BRO	SP	CCA		V	7/1/2088
2020 PO3907782335	F	4	40 BRO	SP	CCA		V	7/2/2088
2020 PO3908982322	F	4	40 BRO	SP	CCA		V	7/3/2088
2020 PO3910282319	F	4	40 BRO	SP	CCA		V	7/4/2088
2020 PO3911782320	F	3	45 BRO	SP	CCA		V	7/5/2088
2020 PO3900382329	F	4	40 BRO	SP	CCA		V	7/6/2088
2020 PO3901782323	F	4	40 BRO	SP	CCA		V	7/7/2088
2020 PO3903082317	F	4	40 BRO	SP	CCA		V	7/8/2088
2020 PO3904482311	F	4	40 BRO	SP	CCA		V	7/9/2088
2020 PO3906082304	F	3	45 BRO	SP	P		V	7/10/2088
2020 PV3867582350	LGE	2	70 BRO	SP	CRE		V	7/11/2088
2020 PO3866782324	LGE	1	80 BRO	SP	A		V	7/12/2088
2020 PO5852134447	LGE	2	60 BRO	SP	CCA		V	7/13/2088
2020 PO5850334349	LGE	2	60 BRO	SP	CCA		V	7/14/2088
2020 PO3856582426	LGE	4	25 BRO	SP	CCA		V	7/15/2088
2020 PO1903723715	ODP	4	45 XXX	SP	CRE	ID	TD	7/16/2088
2020 PO1894123838	ODP	4	40 XXX	SP	CRE	ID,IP	TD	7/17/2088
2020 PO1933423818A	ODP	5	35 XXX	SP	CCA		V	7/18/2088
2020 PO1933423818	ODP	4	40 XXX	SP	P	ID	TD	7/19/2088
2020 PO1948123653	ODP	5	35 XXX	SP	CCA		V	7/20/2088
2020 PO1905323950	ODP	6	35 XXX	SP	CRE	ID	TD	7/21/2088
2020 PO1914424021	ODP	3	45 XXX	SP	CCA		V	7/22/2088
2020 PO1911324065	F	4	40 XXX	SP	P		V	7/23/2088
2020 PO1907724442	ODP	6	30 XXX	SP	CRE	ID	TD	7/24/2088
2020 PO1893624364	ODP	3	45 XXX	SP	CCA		V	7/25/2088
2020 PO3856082425	LGE	4	45 BRO	SP	P	ED,ID	TD	7/26/2088
2020 PO3856882445	LGE	3	45 BRO	SP	CCA		V	7/27/2088
2020 PO1994924461	ODP	5	30 XXX	SP	CRE	ID	TD	7/28/2088
2020 PO1992224536	F	4	40 XXX	SP	CRE		V	7/29/2088
2020 PO1982324524	ODP	4	45 XXX	SP	CRE	ID	TD	7/30/2088
2020 PO1963124483	ODP	4	40 XXX	SP	CCA		V	7/31/2088
2020 PO1956524560	F	4	40 XXX	SP	A		V	8/1/2088
2020 PO1948024659	F	4	40 XXX	SP	CRE		V	8/2/2088
2020 PO1948024659A	ODP	5	35 XXX	SP	CCA		V	8/3/2088
2020 PO1897024627	ODP	5	35 XXX	SP	CRE	ID	TD	8/4/2088
2020 PO1957925012	ODP	6	30 XXX	SP	CRE	ID	TD	8/5/2088
2020 PO1977024921	ODP	6	30 XXX	SP	CRE	ID	TD	8/6/2088
2020 PO1969824674	ODP	6	30 XXX	SP	CRE	ID	TD	8/7/2088
2020 PO1805823882	ODP	6	30 XXX	SP	CCA		V	8/8/2088
2020 PO3853982066	LGE	4	30 BRO	SP	CCA		V	8/9/2088
2020 PO3363648855	F	4	40 BRO	SP	CRE		V	8/10/2088
2020 PO3706989440	F	4	40 XXX	SP	CRE		V	8/11/2088
2020 PO3724889333	KU	5	30 XXX	SP	CCA	ED	T	8/12/2088
2020 PO5545611134	KU	4	40 XXX	SP	CRE	ED,ID	TD	8/13/2088

2020 PO7482138229	KU	4	40 OTH	SP	CRE	ID	TD	8/14/2088	
2020 PO7480638116	KU	4	40 OTH	SP	CRE	ID	TD	8/15/2088	
2020 PO7485638386	KU	4	45 OTH	SP	CRE	ED,EP,ID,IP,SRC	TX	RR	8/16/2088
2020 PO5533910727	KU	5	35 XXX	SP	CRE	ED,ID	TD	8/17/2088	
2020 PO5553510833	KU	4	45 XXX	SP	CRE	ID	BD	8/18/2088	
2020 PO6824554192	ODP	5	35 BRN	SP	CRE	ID	BD	8/19/2088	
2020 PO6801253941	ODP	4	40 XXX	SP	CRE	ID	BD	8/20/2088	
2020 PO6768654220	ODP	5	35 BRN	SP	CRE	ID	BD	8/21/2088	
2020 PO6821254279	ODP	4	40 BRN	SP	CCA		V	8/22/2088	
2020 PO6801753974	ODP	4	45 XXX	SP	CRE	ID	BD	8/23/2088	
2020 PO6804454154	ODP	4	40 BRN	SP	CRE	ID	BD	8/24/2088	
2020 PO6816154165	ODP	4	40 BRN	SP	CRE	ID	BD	8/25/2088	
2020 PO4654988253	LGE	4	40 BRN	SP	CRE	ED,ID	TD	8/26/2088	
2020 PO4655588245	LGE	4	35 BRN	SP	CRE	ED,ID	TD	8/27/2088	
2020 PO4645389204-C	LGE	5	35 BRO	SP	A	ED,ID,IP	TD	8/28/2088	
2020 PO3714189284	KU	6	30 XXX	SP	CRE	ID	TD	8/29/2088	
2020 PO5508710875	KU	4	40 XXX	SP	CRE	ED,ID	TD	8/30/2088	
2020 PO5485210901	KU	4	40 XXX	SP	CRE	ED,ID	TD	8/31/2088	
2020 PO5470710918	KU	4	40 XXX	SP	CRE	ED,ID	TD	9/1/2088	
2020 PO5724210853	KU	4	40 XXX	SP	CRE	ED,ID	TD	9/2/2088	
2020 PO4656088237	LGE	4	40 BRN	SP	CRE	ED,ID	TD	9/3/2088	
2020 PO4656588228	LGE	4	40 BRN	SP	CCA		V	9/4/2088	
2020 PO3750889655	KU	5	35 XXX	SP	CRE	ID	TD	9/5/2088	
2020 PO3738889759	F	6	30 XXX	SP	CRE		V	9/6/2088	
2020 PO3741989794	KU	5	35 XXX	SP	CRE	ED,ID	TX	RR	9/7/2088
2020 PO3725889801	F	4	40 XXX	SP	CRE		V	9/8/2088	
2020 PO3714989809	KU	6	35 XXX	SP	CRE	ID	TD	9/9/2088	
2020 PO3716989749	F	4	40 XXX	SP	CRE		V	9/10/2088	
2020 PO3712889798	F	5	35 XXX	SP	CRE		V	9/11/2088	
2020 PO3709589703	KU	5	35 XXX	SP	CRE	ID	TD	9/12/2088	
2020 PO3697989629	KU	6	30 XXX	SP	CRE	ID	TD	9/13/2088	
2020 PO3736889879	KU	4	40 XXX	SP	CRE	ED,ID	TD	9/14/2088	
2020 PO3751789860	F	5	35 XXX	SP	CRE		V	9/15/2088	
2020 PO3762989993	KU	4	40 XXX	SP	CRE	ID	TD	9/16/2088	
2020 PO3749989905	KU	2	40 XXX	SP	CRE	ID	TD	9/17/2088	
2020 PO3743889886	KU	6	30 XXX	SP	CCA	ED	T	9/18/2088	
2020 PO3753090861	F	5	35 XXX	SP	CCA		V	9/19/2088	
2020 PO3776491015	F	5	35 XXX	SP	A		V	9/20/2088	
2020 PO3801491125	F	4	40 XXX	SP	CRE		V	9/21/2088	
2020 PO3814591212	F	4	40 XXX	SP	CRE		V	9/22/2088	
2020 PO3828191304	F	4	40 XXX	SP	CCA		V	9/23/2088	
2020 PO3840091445	KU	5	35 XXX	SP	CCA		V	9/24/2088	
2020 PO3830991390	KU	5	35 XXX	SP	CCA		V	9/25/2088	
2020 PO3839291382	F	3	45 XXX	SP	CCA		V	9/26/2088	
2020 PO3852791528	F	5	35 XXX	SP	CRE		V	9/27/2088	
2020 PO3849391505	F	5	35 XXX	SP	CRE		V	9/28/2088	
2020 PO3853691478	F	4	40 XXX	SP	P		V	9/29/2088	

2020 PO3872891607	F	4	40 XXX	SP	A		V		9/30/2088
2020 PO3863191542	F	4	40 XXX	SP	P		V		10/1/2088
2020 PO3880991660	F	4	40 XXX	SP	A		V		10/2/2088
2020 PO4645389204-B	LGE	5	35 BRO	SP	A	ED	TD		10/3/2088
2020 PO7485338701	KU	6	30 OTH	SP	CCA	ED,SRS	TD		10/4/2088
2020 PO7501638825	KU	4	40 OTH	SP	CRE	ID	TD		10/5/2088
2020 PO7491238542	KU	4	40 OTH	SP	CRE	ID	TD		10/6/2088
2020 PO7492638866	KU	5	35 OTH	SP	CRE	ID	TD		10/7/2088
2020 PO7496838694	KU	4	40 OTH	SP	CRE	ID	TD		10/8/2088
2020 PO4720188130	LGE	4	40 BRO	SP	A	ED,ID	BD		10/9/2088
2020 PO4719488161	LGE	3	45 BRO	SP	CCA		V		10/10/2088
2020 PO4719888194	LGE	4	30 BRO	SP	CRE		V		10/11/2088
2020 PO4722488186	LGE	4	40 BRO	SP	CRE	ED,ID	TD		10/12/2088
2020 PO4719688187	LGE	3	45 BRO	SP	CCA		V		10/13/2088
2020 PO4717688121	LGE	3	45 BRO	SP	CCA		V		10/14/2088
2020 PO4645389204-A	LGE	5	35 BRO	SP	A	ED	TD		10/15/2088
2020 PO4653988197	LGE	4	35 BRN	SP	CRE	ED,ID	BD		10/16/2088
2020 PO4654988199	LGE	4	30 BRN	SP	A	ED,ID	TD		10/17/2088
2020 PO4656888212	LGE	4	30 BRN	SP	A	ED,ID	TD		10/18/2088
2020 PO4657788219	LGE	4	30 BRN	SP	A	ED,ID	TD		10/19/2088
2020 PO4657188219	LGE	4	40 BRN	SP	A	ED,ID	TD		10/20/2088
2020 PO4658588188	LGE	4	35 BRN	SP	CRE	ED,ID	TD		10/21/2088
2020 PO4656088206	LGE	4	35 BRN	SP	A	ED,ID	TD		10/22/2088
2020 PO3301351863	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		10/23/2088
2020 PO3284852073	KU	4	40 ACE	SP	CRE	ED,HH,ID,IP,RB	X	RP1	10/24/2088
2020 PO3281951896	KU	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	X	RP1	10/25/2088
2020 PO4382002190	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD		10/26/2088
2020 PO4445203332	F	5	35 BRO	SP	A		V		10/27/2088
2020 PO4333202705	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD		10/28/2088
2020 PO4329402558	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD		10/29/2088
2020 PO4394903506	F	4	40 BRO	SP	CCA		V		10/30/2088
2020 PO4400703575	F	4	40 BRO	SP	CCA		V		10/31/2088
2020 PO4388203425-A	KU	6	30 BRO	SP	CRE	ED,ID	TD		11/1/2088
2020 PO3320151859	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		11/2/2088
2020 PO3332951867	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		11/3/2088
2020 PO3350351947	KU	3	45 ACE	SP	CCA		V		11/4/2088
2020 PO4388203425	KU	4	45 BRO	SP	CRE	ED,ID	TD		11/5/2088
2020 PO4397803428	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		11/6/2088
2020 PO4384803511	KU	4	40 BRO	SP	CCA		V		11/7/2088
2020 PO3311252760	KU	4	40 ACE	SP	CCA		V		11/8/2088
2020 PO4404203507	KU	4	45 BRO	SP	CRE	ED,ID	TD		11/9/2088
2020 PO4411603435	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD		11/10/2088
2020 PO3371053011	KU	5	35 ACE	SP	CRE	ED,ID	TD		11/11/2088
2020 PO3385153024	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD		11/12/2088
2020 PO4409103670	F	4	35 BRO	SP	CCA		V		11/13/2088
2020 PO4413503614	KU	4	40 BRO	SP	CRE	ID	BD		11/14/2088
2020 PO4429803826	KU	6	30 BRO	SP	CRE	ED,ID	TD		11/15/2088

2020 PO4421403703	KU	5	35 BRO	SP	CRE	ID,IP	BD		11/16/2088
2020 PO3400953045	KU	5	35 ACE	SP	CRE	ED,ID	TD		11/17/2088
2020 PO3433553074	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD		11/18/2088
2020 PO3419753061	KU	5	35 ACE	SP	CRE	ED,ID	TD		11/19/2088
2020 PO4431703426	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD		11/20/2088
2020 PO4462603433	KU	4	40 BRO	SP	CRE	ED,ID	TD		11/21/2088
2020 PO3482953064	KU	4	40 ACE	SP	CRE	ED,ID	BD		11/22/2088
2020 PO3467053075	KU	4	40 ACE	SP	CRE	ED,ID	BD		11/23/2088
2020 PO4669888175	LGE	4	30 BRN	SP	CRE	ED,ID	TD		11/24/2088
2020 PO4671988191	LGE	4	30 BRN	SP	CRE	ED,ID	TD		11/25/2088
2020 PO4672588181	LGE	4	30 BRN	SP	CCA		V		11/26/2088
2020 PO4672988173	LGE	4	30 BRN	SP	A	ED,ID	TD		11/27/2088
2020 PO4673688166	LGE	4	30 BRN	SP	CRE	ED,HH,ID,RB	BX	PX	11/28/2088
2020 PO4671388149	LGE	4	30 BRN	SP	A	ED,ID	TD		11/29/2088
2020 PO4674188157	LGE	4	30 BRN	SP	CRE	ED,ID	TD		11/30/2088
2020 PO4671988142	LGE	4	30 BRN	SP	CRE	ED,ID	TD		12/1/2088
2020 PO4671388138	LGE	4	40 BRN	SP	A	ED,ID	TD		12/2/2088
2020 PO4745787513	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		12/3/2088
2020 PO5787306385	KU	3	45 XXX	SP	CCA		V		12/4/2088
2020 PO5765006255	KU	3	45 XXX	SP	CRE	ED,ID	TD		12/5/2088
2020 PO5753606129	KU	3	45 XXX	SP	CRE	ED,ID	TD		12/6/2088
2020 PO5757406247	KU	6	35 XXX	SP	CRE	ED,ID	TD		12/7/2088
2020 PO5751206170	KU	3	45 XXX	SP	CCA		V		12/8/2088
2020 PO4672088130	LGE	4	40 BRN	SP	A	ED,ID,SRS	TX	RR	12/9/2088
2020 PO4741488366	LGE	4	35 BRO	SP	CRE	ED,ID	TD		12/10/2088
2020 PO4740588361	LGE	4	40 BRO	SP	CRE	ED,ID	TD		12/11/2088
2020 PO4741088354	LGE	4	30 BRO	SP	CRE	ED,ID	TD		12/12/2088
2020 PO4672588121	LGE	4	40 BRN	SP	P	ED,ID	BD		12/13/2088
2020 PO4670988146	LGE	4	40 BRN	SP	A	ED,ID,IP	TD		12/14/2088
2020 PO4670488156	LGE	4	40 BRN	SP	A	ED,ID,SRS	TX	RR	12/15/2088
2020 PO4669888164	LGE	4	40 BRN	SP	A	ED,ID,SRS	TX	RR	12/16/2088
2020 PO4669388172	LGE	4	40 BRN	SP	A	ED,ID,IP	TD		12/17/2088
2020 PO5741006052	KU	3	45 XXX	SP	CRE	ED,ID	TD		12/18/2088
2020 PO5738606100	KU	3	45 XXX	SP	CRE	ED,ID	TD		12/19/2088
2020 PO5734906139	F	4	40 XXX	SP	A		V		12/20/2088
2020 PO4668588184	LGE	4	45 BRN	SP	A	ED,ID	TD		12/21/2088
2020 PO4666589230	LGE	4	40 BRO	SP	A	ID,IP	BD		12/22/2088
2020 PO4665889224	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		12/23/2088
2020 PO4667988193	LGE	4	35 BRN	SP	CRE	ED,ID	BD		12/24/2088
2020 PO4665989218	LGE	4	30 BRO	SP	A	ED,ID	TD		12/25/2088
2020 PO4745288324	LGE	4	40 BRO	SP	CRE	ED,ID	BD		12/26/2088
2020 PO4747788306	LGE	4	40 BRO	SP	CRE	ED,ID	TD		12/27/2088
2020 PO4748188303	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		12/28/2088
2020 PO4749388311	LGE	4	40 BRO	SP	A	ED,ID	TD		12/29/2088
2020 PO4750688320	LGE	4	40 BRO	SP	A	ED,ID	TD		12/30/2088
2020 PO4751688329	LGE	4	40 BRO	SP	A	ED,ID	TD		12/31/2088
2020 PO3825590981	F	4	40 KOP	SP	CRE		V		1/1/2089

2020 PO3817290925	F	4	40 KOP	SP	CRE	ED,ID,IP,MD	BX	PX	1/2/2089
2020 PO3802490827	F	4	45 KOP	SP	CRE		V		1/3/2089
2020 PO3791490753	F	4	40 KOP	SP	CRE		V		1/4/2089
2020 PO4654389132	LGE	4	40 BRO	SP	CRE	ID,IP	BD		1/5/2089
2020 PO4665788225	LGE	4	35 BRN	SP	A	ED,ID	BD		1/6/2089
2020 PO4665288235	LGE	4	35 BRN	SP	CRE	ED,ID	BD		1/7/2089
2020 PO4664688242	LGE	4	40 BRN	SP	A		B		1/8/2089
2020 PO5879005314	KU	5	30 XXX	SP	CRE	ED,ID	TD		1/9/2089
2020 PO5895005437	KU	4	45 XXX	SP	CRE	ED,ID	TD		1/10/2089
2020 PO5892705604	KU	2	45 XXX	SP	CCA		V		1/11/2089
2020 PO5891005729	KU	4	40 XXX	SP	CRE	ED,ID	TD		1/12/2089
2020 PO4651089160	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD		1/13/2089
2020 PO4664188250	LGE	4	40 BRN	SP	A		B		1/14/2089
2020 PO4752788340	LGE	4	40 BRO	SP	A	ED,ID	TD		1/15/2089
2020 PO4753788350	LGE	4	40 BRO	SP	A	ED,ID	TD		1/16/2089
2020 PO4754888361	LGE	4	40 BRO	SP	A	ED,ID	TD		1/17/2089
2020 PO4755988371	LGE	4	40 BRO	SP	A	ED,ID	TD		1/18/2089
2020 PO4756788384	LGE	4	40 BRO	SP	A	ED,ID	TD		1/19/2089
2020 PO4663588260	LGE	4	40 BRN	SP	A		B		1/20/2089
2020 PO4663088267	LGE	3	45 BRN	SP	CCA		V		1/21/2089
2020 PO4662588277	LGE	4	40 BRN	SP	A		B		1/22/2089
2020 PO4661988285	LGE	4	40 BRN	SP	A		V		1/23/2089
2020 PO4661488293	LGE	4	40 BRN	SP	A		V		1/24/2089
2020 PO4660888301	LGE	4	40 BRN	SP	A	ED,HH,ID	BX	PX	1/25/2089
2020 PO4660388309	LGE	4	40 BRN	SP	A		V		1/26/2089
2020 PO4651889121	LGE	4	30 BRO	SP	CRE	ED	TD		1/27/2089
2020 PO4652389115	LGE	4	35 BRO	SP	CCA		V		1/28/2089
2020 PO4649789149	LGE	4	25 BRO	SP	CRE		BD		1/29/2089
2020 PO3710390351	KU	6	30 KOP	SP	CRE	ED,ID	TD		1/30/2089
2020 PO3814990214	KU	4	40 KOP	SP	CRE	ED,ID	TD		1/31/2089
2020 PO3814489875	KU	6	30 KOP	SP	CRE	ID	BD		2/1/2089
2020 PO3858089576	KU	6	30 KOP	SP	CRE		V		2/2/2089
2020 PO3909690257	KU	6	30 KOP	SP	CRE	ED,ID	TD		2/3/2089
2020 PO3905690667	KU	6	30 KOP	SP	CRE	ED,ID	TD		2/4/2089
2020 PO3902990702	F	4	40 KOP	SP	CRE		V		2/5/2089
2020 PO3872090500	KU	6	30 KOP	SP	CRE	ED,ID	TD		2/6/2089
2020 PO3787190352	KU	5	35 KOP	SP	CRE	ED,ID	TD		2/7/2089
2020 PO3776390422	KU	4	45 KOP	SP	CRE	ED,ID	TD		2/8/2089
2020 PO3810790469	KU	4	40 KOP	SP	CRE	ID	BD		2/9/2089
2020 PO3802490393	KU	4	40 KOP	SP	CRE	ED,ID	TD		2/10/2089
2020 PO3827090499	KU	5	30 KOP	SP	CRE		V		2/11/2089
2020 PO3917689631	KU	5	30 KOP	SP	CRE	ED,ID	TD		2/12/2089
2020 PO3868389235	KU	6	30 KOP	SP	CRE	ED,ID	TD		2/13/2089
2020 PO4745588205	LGE	4	35 BRO	SP	P	ED,ID	TD		2/14/2089
2020 PO4746188207	LGE	3	45 BRO	SP	CCA		V		2/15/2089
2020 PO4747088211	LGE	UNK	45 BRO	SP	CRE	ED,ID	TD		2/16/2089
2020 PO4745288219-A	LGE	4	40 BRO	SP	A	ED,ID	TD		2/17/2089

2020 PO3873988744	F	4	40 KOP	SP	S		V		2/18/2089
2020 PO3880688783	KU	4	40 KOP	DF	CRE	ED,ID	TD		2/19/2089
2020 PO3892088680	KU	4	40 KOP	SP	CRE	ED,ID	TD		2/20/2089
2020 PO4743588193	LGE	4	40 BRO	SP	CRE	ED,ID	TD		2/21/2089
2020 PO4735888220	LGE	4	40 BRO	SP	A	ED,ID	BD		2/22/2089
2020 PO4639188862	LGE	4	40 BRO	SP	CRE	ED,ID,IP,SRC	TD		2/23/2089
2020 PO4638288883	LGE	4	35 BRO	SP	CRE	ED,ID,IP,SRC	TD		2/24/2089
2020 PO4637188856	LGE	4	35 BRO	SP	CRE	ED,ID,IP,SRC	TD		2/25/2089
2020 PO4637588869	LGE	4	40 BRO	SP	P	ED,SRS	T		2/26/2089
2020 PO3873088185	KU	4	40 KOP	SP	CRE	ED,ID	TD		2/27/2089
2020 PO3855987881	KU	4	45 KOP	SP	CRE	ID	BD		2/28/2089
2020 PO3873288010	KU	4	45 KOP	SP	S		V		3/1/2089
2020 PO3887188353	KU	6	30 KOP	SP	CRE	ED,ID	TD		3/2/2089
2020 PO3883988249	KU	4	40 KOP	SP	CRE	ED,ID	TD		3/3/2089
2020 PO4742888210	LGE	4	40 BRO	SP	CRE	ED,ID	TD		3/4/2089
2020 PO4739888198	LGE	4	40 BRO	SP	CRE	HH,RB	VX	PX	3/5/2089
2020 PO4741488204	LGE	4	40 BRO	SP	CRE	ED,HH,ID,RB	BX	PX	3/6/2089
2020 PO4744288215	LGE	4	40 BRO	SP	CRE	ED,ID	TD		3/7/2089
2020 PO4738688193	LGE	4	40 BRO	SP	CRE	ED,ID	TD		3/8/2089
2020 PO4745288219	F	UNK	45 BRO	SP	A		V		3/9/2089
2020 PO4745588220	LGE	4	30 BRO	SP	CRE	ED,ID	BD		3/10/2089
2020 PO4736788186	LGE	4	40 BRO	SP	CRE	ED,ID	BD		3/11/2089
2020 PO4737488189	LGE	4	40 BRO	SP	CRE	ED,ID	TD		3/12/2089
2020 PO3800490091	KU	1	45 KOP	SP	S		V		3/13/2089
2020 PO3803189979	KU	1	45 KOP	SP	S		V		3/14/2089
2020 PO3810789831	KU	1	45 KOP	SP	S		V		3/15/2089
2020 PO3816989706	KU	3	45 KOP	SP	S		V		3/16/2089
2020 PO3823489581	KU	1	45 KOP	SP	S		V		3/17/2089
2020 PO3828689483	KU	1	45 KOP	SP	S		V		3/18/2089
2020 PO3836889328	KU	1	45 KOP	SP	S		V		3/19/2089
2020 PO3843389200	KU	3	45 KOP	SP	S		V		3/20/2089
2020 PO3850289067	KU	3	45 KOP	SP	S		V		3/21/2089
2020 PO3857188933	KU	1	45 KOP	SP	S		V		3/22/2089
2020 PO3868388713	KU	3	45 KOP	SP	S		V		3/23/2089
2020 PO3875088582	KU	1	45 KOP	SP	S		V		3/24/2089
2020 PO3884388406	KU	1	45 KOP	SP	CCA		V		3/25/2089
2020 PO3890488287	KU	3	45 KOP	SP	S		V		3/26/2089
2020 PO3888088130	KU	4	45 KOP	SP	S		V		3/27/2089
2020 PO3900188102	KU	3	45 KOP	SP	S		V		3/28/2089
2020 PO3908087948	KU	3	45 KOP	SP	S		V		3/29/2089
2020 PO3915987795	KU	2	45 KOP	SP	S		V		3/30/2089
2020 PO3920987699	KU	H1	85 KOP	DF	CRE		V		3/31/2089
2020 PO3926287569	KU	4	45 KOP	SP	CRE		V		4/1/2089
2020 PO6928315210	KU	4	40 XXX	SP	CRE		V		4/2/2089
2020 PO6942015019	KU	4	40 XXX	SP	CCA		V		4/3/2089
2020 PO6942014810	KU	4	40 XXX	SP	CCA		V		4/4/2089
2020 PO6941914511	KU	4	40 XXX	SP	CCA		V		4/5/2089

2020 PO6909115154	KU	4	40 XXX	SP	CRE	ED,ID	TD	4/6/2089
2020 PO6871015300	KU	4	40 XXX	SP	CRE	ED,ID	TD	4/7/2089
2020 PO3861590798	KU	4	40 KOP	SP	CRE	ED,ID	TD	4/8/2089
2020 PO3856590875	KU	6	30 KOP	SP	CRE	ED,ID	TD	4/9/2089
2020 PO3836990746	KU	6	30 KOP	SP	CRE	ED,ID	TD	4/10/2089
2020 PO3828590690	KU	4	40 KOP	SP	CRE	ED,ID	TD	4/11/2089
2020 PO3816490607	KU	4	40 KOP	SP	CRE	ED,ID	TD	4/12/2089
2020 PO3824590753	KU	4	40 KOP	SP	CRE	ED,ID	TD	4/13/2089
2020 PO6885015703	KU	4	40 XXX	SP	CCA		V	4/14/2089
2020 PO4656688621	F	4	40 BRN	SP	CRE		V	4/15/2089
2020 PO4533290799	KU	4	40 KOP	SP	CRE	ED,ID	TD	4/16/2089
2020 PO4535790377	KU	4	40 KOP	SP	CRE	ED,ID	TD	4/17/2089
2020 PO4728788038	F	4	40 BRO	SP	CRE	ED	V	4/18/2089
2020 PO4724687983	F	4	40 BRO	SP	CRE		V	4/19/2089
2020 PO4724787992	F	3	45 BRO	SP	CRE		V	4/20/2089
2020 PO0343551144	KU	5	35 BRO	SP	CCA		V	4/21/2089
2020 PO0338551026	F	4	40 BRO	SP	CRE		V	4/22/2089
2020 PO0347250987	F	4	40 BRO	SP	CRE		V	4/23/2089
2020 PO0305251106	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD	4/24/2089
2020 PO1507260215	KU	4	40 BRN	SP	P		B	4/25/2089
2020 PO1719259043	KU	3	45 BRN	SP	CCA		V	4/26/2089
2020 PO0485459016a	KU	4	40 ACW	SP	P		V	4/27/2089
2020 PO0485459016	F	4	40 ACW	SP	P		V	4/28/2089
2020 PO0363760610	KU	4	40 ACW	SP	CRE	ED,ID	BD	4/29/2089
2020 PO0372060310	KU	4	40 ACW	SP	CCA		V	4/30/2089
2020 PO0584358225	KU	5	35 ACW	SP	CRE	ED,ID	BD	5/1/2089
2020 PO3926682530	LGE	3	45 BRN	SP	CRE	ED,ID	BD	5/2/2089
2020 PO3926282521	LGE	4	30 BRN	SP	P	ED,ID	TD	5/3/2089
2020 PO3925882515	LGE	4	40 BRN	SP	P	ED,ID	TD	5/4/2089
2020 PO3973683024	F	4	40 BRN	SP	S		V	5/5/2089
2020 PO3974083024	F	4	30 BRN	SP	CRE		V	5/6/2089
2020 PO3936283250	LGE	4	30 BRO	SP	P	ID	BD	5/7/2089
2020 PO3935783249	F	4	40 BRO	SP	P		V	5/8/2089
2020 PO1249236004	ODP	4	45 KOP	SP	CCA		V	5/9/2089
2020 PO3973783011	F	4	40 BRN	SP	CCA		V	5/10/2089
2020 PO1248636232	F	4	40 KOP	SP	CRE	ED,EP,ID	VX	5/11/2089
2020 PO4027042644	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	5/12/2089
2020 PO3973882993	LGE	1	50 BRN	SP	S		V	5/13/2089
2020 PO3975682995	LGE	4	40 BRN	SP	CRE	ED,ID	TD	5/14/2089
2020 PO3977282997	F	1	50 BRN	SP	CCA		V	5/15/2089
2020 PO1249436548	ODP	6	30 KOP	SP	CRE	ID	TD	5/16/2089
2020 PO2292337606	KU	4	40 BRO	SP	CCA		V	5/17/2089
2020 PO2294237743	KU	4	40 BRO	SP	CRE	ID,IP	BD	5/18/2089
2020 PO0581458161	F	6	30 ACW	SP	CRE		V	5/19/2089
2020 PO3880382944	LGE	4	35 BRO	SP	P	ED,ID,IP,MD	TX	5/20/2089
2020 PO0389160796	KU	4	45 ACW	SP	CCA		V	5/21/2089
2020 PO0361261093	KU	4	40 ACW	SP	CRE	ED,ID	BD	5/22/2089

2020 PO0365160949	KU	4	40 ACW	SP	CRE	ED,ID	BD	5/23/2089
2020 PO0429760610	KU	4	40 ACW	SP	CRE	ED,ID	BD	5/24/2089
2020 PO1870758108	KU	4	40 BRN	SP	CRE	ID	TD	5/25/2089
2020 PO0307751162	F	4	40 BRO	SP	CRE		V	5/26/2089
2020 PO0313651144	KU	4	40 BRO	SP	CRE	ID	BD	5/27/2089
2020 PO9142655035	KU	4	40 BRO	SP	P		B	5/28/2089
2020 PO9138754805	KU	4	40 BRO	SP	CRE		B	5/29/2089
2020 PO9135554638	KU	4	40 BRO	SP	CRE	ID	BD	5/30/2089
2020 PO9596453643	KU	4	40 BRO	SP	CRE		V	5/31/2089
2020 PO9500354299	KU	4	40 BRO	SP	CRE	ID	BD	6/1/2089
2020 PO9501954980	KU	4	45 BRO	SP	CRE	ED,ID,SRC	TD	6/2/2089
2020 PO1778659192	KU	4	40 BRN	SP	CRE	ID	TD	6/3/2089
2020 PO1823758954	KU	4	40 BRN	SP	CCA		V	6/4/2089
2020 PO0436760506	KU	4	40 ACW	SP	CRE	ED,ID	BD	6/5/2089
2020 PO0446560518	KU	4	40 ACW	SP	CRE	ED,ID	BD	6/6/2089
2020 PO0475860494	KU	4	40 ACW	SP	CCA		V	6/7/2089
2020 PO0651761744	KU	5	35 ACW	SP	P	ED,ID	BD	6/8/2089
2020 PO0662661695	KU	3	45 ACW	SP	CCA		V	6/9/2089
2020 PO6567161703	F	4	40 ACW	SP	P	ED,EP,HH,ID,IP,RB	VX	RP1 6/10/2089
2020 PO0664461679	KU	4	40 ACW	SP	P		V	6/11/2089
2020 PO1725347502	F	4	40 BRN	SP	P		V	6/12/2089
2020 PO1709447557	KU	2	45 BRN	SP	CCA		V	6/13/2089
2020 PO1713747263	F	4	40 BRN	SP	CCA		V	6/14/2089
2020 PO1702547031	F	4	40 BRN	SP	P		V	6/15/2089
2020 PO1714746974	KU	4	40 BRN	SP	CCA		V	6/16/2089
2020 PO1573945277	KU	5	35 BRN	SP	CCA		V	6/17/2089
2020 PO1590042483	KU	6	30 BRN	SP	CRE		V	6/18/2089
2020 PO1598542593	KU	5	30 BRN	SP	CRE		V	6/19/2089
2020 PO1608142788	KU	4	40 BRN	SP	P		B	6/20/2089
2020 PO1628443211	KU	4	45 BRN	SP	P		B	6/21/2089
2020 PO1646043388	KU	4	40 BRN	SP	CRE	ID	BD	6/22/2089
2020 PO0258560496	KU	4	35 BRO	SP	CRE		V	6/23/2089
2020 PO3978283002	LGE	4	40 BRN	SP	CRE	ED,ID	TD	6/24/2089
2020 PO3980083007	LGE	4	40 BRN	SP	CRE	ED,ID	TD	6/25/2089
2020 PO1267536078	ODP	1	50 UNK	SP	CRE	ID	BD	6/26/2089
2020 PO4018042711	KU	6	30 ACE	SP	CCA		V	6/27/2089
2020 8107329298A	KU	4	40 KOP	SP	CCA		V	6/28/2089
2020 PO8236531835	KU	5	35 OTH	SP	CRE	ID	TD	6/29/2089
2020 PO8107729115	KU	1	60 BRN	SP	CCA		V	6/30/2089
2020 PO8247731839	KU	6	25 UNK	SP	CCA		V	7/1/2089
2020 PO8148430783	KU	5	35 OTH	SP	CRE	ID	TD	7/2/2089
2020 PO8105230301	KU	4	40 OTH	SP	CRE		V	7/3/2089
2020 PO8102231179	KU	4	40 OTH	SP	CRE		V	7/4/2089
2020 PO8099232010	KU	4	40 OTH	SP	CRE		V	7/5/2089
2020 PO8103729126	KU	4	40 BRN	SP	CCA		V	7/6/2089
2020 PO8107429142	KU	1	60 BRN	SP	CCA		V	7/7/2089
2020 PO8106230007	KU	4	40 BRN	SP	CCA		V	7/8/2089

2020 PO8167431295	KU	5	35 OTH	SP	CRE	ID	TD	7/9/2089	
2020 PO8140330410	KU	5	35 OTH	SP	CRE	ID	TD	7/10/2089	
2020 PO7461695272	KU	5	30 BRO	SP	A	RB	X	RP1	7/11/2089
2020 PO7491995346	KU	5	30 BRO	SP	A	ED,ID	TD	7/12/2089	
2020 PO7472495475	KU	4	40 BRO	SP	CRE	ID	BD	7/13/2089	
2020 PO7488395513	KU	4	45 BRO	SP	CRE	ID	BD	7/14/2089	
2020 PO7509295562	KU	4	40 BRO	SP	CRE	ID	BD	7/15/2089	
2020 PO7536795293	KU	3	45 BRO	SP	CRE	ED,ID	TD	7/16/2089	
2020 PO7531195444	KU	5	30 BRO	SP	A	ED,ID,RB	TX	RR	7/17/2089
2020 PO7528895617	KU	3	45 BRO	SP	CCA		V	7/18/2089	
2020 PO7542895656	KU	4	45 BRO	SP	CCA		B	7/19/2089	
2020 PO7568495450	KU	4	45 BRO	SP	CRE		B	7/20/2089	
2020 PO7565295552	KU	4	45 BRO	SP	CRE		V	7/21/2089	
2020 PO7560995700	KU	3	50 BRO	SP	CRE	ID	BD	7/22/2089	
2020 PO7084387577	KU	4	45 BRN	SP	S		V	7/23/2089	
2020 PO7099887649	F	4	30 BRN	SP	CRE		V	7/24/2089	
2020 PO7103487706	KU	5	35 BRN	SP	CRE	ED,ID	BD	7/25/2089	
2020 PO7107587735	KU	5	35 BRN	SP	CRE	ED,ID	BD	7/26/2089	
2020 PO7148487950	KU	4	45 BRN	SP	CRE		V	7/27/2089	
2020 PO7141287908	KU	4	40 BRN	SP	CRE	ED,ID	BD	7/28/2089	
2020 PO7139387898	KU	4	45 BRN	SP	CRE		V	7/29/2089	
2020 PO7137587888	KU	4	40 BRN	SP	CRE	ED,ID	BD	7/30/2089	
2020 PO7131687852	KU	5	35 BRN	SP	CRE	ED,ID	BD	7/31/2089	
2020 PO7125787818	KU	4	40 BRN	SP	CRE	ED,ID	BD	8/1/2089	
2020 PO6113405943	KU	4	40 BRO	SP	CRE	ID	TD	8/2/2089	
2020 PO7217888319	KU	5	35 BRN	SP	CRE	ED,ID	TD	8/3/2089	
2020 PO7219088387	KU	6	30 BRN	SP	CRE	ED,ID	TD	8/4/2089	
2020 PO7210988292	F	4	40 BRN	SP	CRE		V	8/5/2089	
2020 PO7197288232	F	5	35 BRN	SP	CRE		V	8/6/2089	
2020 PO7186488185	F	4	40 BRN	SP	CRE		V	8/7/2089	
2020 PO6138505809	KU	5	35 BRO	SP	CRE	ID	TD	8/8/2089	
2020 PO6137405880	KU	6	30 BRO	SP	CCA		V	8/9/2089	
2020 PO6132005685	F	4	40 BRO	SP	CRE		V	8/10/2089	
2020 PO6124205663	KU	6	30 BRO	SP	CCA		V	8/11/2089	
2020 PO6132205873	KU	4	40 BRO	SP	CRE	ID	BD	8/12/2089	
2020 PO6142905837	KU	4	40 BRO	SP	CRE	ID	TD	8/13/2089	
2020 PO6152305811	KU	2	50 BRO	SP	CRE	ID	BD	8/14/2089	
2020 PO6158005788	KU	4	45 BRO	SP	CRE	ID	BD	8/15/2089	
2020 PO6147505491	F	4	40 BRO	SP	CRE		V	8/16/2089	
2020 PO6147205424	KU	3	45 BRO	SP	CRE	ID	TD	8/17/2089	
2020 PO5424707703	KU	4	45 BRO	SP	CRE	ID	TD	8/18/2089	
2020 PO5430807633	KU	4	40 BRO	SP	CRE	ID	TD	8/19/2089	
2020 PO5442707534	KU	4	40 BRO	SP	CRE	ID	TD	8/20/2089	
2020 PO5460307378	KU	6	30 BRO	SP	CRE		V	8/21/2089	
2020 PO7182587237	KU	4	40 BRN	SP	CRE		V	8/22/2089	
2020 PO7182787372	KU	4	45 BRN	SP	CRE	ED,ID	BD	8/23/2089	
2020 PO7188587287	KU	4	40 BRN	SP	CRE	ED,ID	BD	8/24/2089	

2020 PO7199287528	KU	4	45 BRN	SP	A	ED,ID	BD	8/25/2089	
2020 PO7222087517	KU	4	45 BRN	SP	CRE	ED,ID	BD	8/26/2089	
2020 PO7225987590	KU	6	30 BRN	SP	A	ED,ID	BD	8/27/2089	
2020 PO7264386760	KU	6	30 BRN	SP	CRE		V	8/28/2089	
2020 PO7259186745	F	4	40 BRN	SP	CRE		V	8/29/2089	
2020 PO7407284260	F	4	40 BRN	SP	CRE		V	8/30/2089	
2020 PO7550995513	KU	4	30 BRO	SP	A	ED,ID	TD	8/31/2089	
2020 PO7316085554	F	6	30 BRN	SP	CRE		V	9/1/2089	
2020 PO7345685516	F	4	40 BRN	SP	CRE		V	9/2/2089	
2020 PO7355285580	F	5	35 BRN	SP	CRE		V	9/3/2089	
2020 PO7369285658	F	5	35 BRN	SP	CRE		V	9/4/2089	
2020 PO7476281570	F	5	35 BRN	SP	CRE		V	9/5/2089	
2020 PO7571495360	KU	4	40 BRO	SP	CRE	ID	BD	9/6/2089	
2020 PO7563395162	KU	6	30 BRO	SP	P	ED	T	9/7/2089	
2020 PO7571295235	KU	4	40 BRO	SP	CRE	ED,ID	TD	9/8/2089	
2020 PO7576695202	KU	4	45 BRO	SP	CRE	ED,ID	TD	9/9/2089	
2020 PO7589494807	KU	4	40 BRO	SP	CRE	ED,ID	TD	9/10/2089	
2020 PO7571794870	KU	5	30 BRO	SP	P	ED,ID	TD	9/11/2089	
2020 PO7582995008	KU	4	40 BRO	SP	CRE	ID	BD	9/12/2089	
2020 PO7585994912	KU	4	40 BRO	SP	CRE	ED,ID	TD	9/13/2089	
2020 PO7502893295	F	4	40 BRO	SP	CRE		V	9/14/2089	
2020 PO5446007446	KU	3	45 BRO	SP	CCA		V	9/15/2089	
2020 PO5452707379	KU	5	35 BRO	SP	CRE		V	9/16/2089	
2020 PO2651127206	ODP	4	40 BRN	SP	A	ID,IP	TX	RR	9/17/2089
2020 PO6070705422	F	4	40 BRO	SP	A		V	9/18/2089	
2020 PO6083305267	F	4	40 BRO	SP	A		V	9/19/2089	
2020 PO6094305130	F	3	45 BRO	SP	CCA		V	9/20/2089	
2020 PO6111004933	F	3	45 BRO	SP	A		V	9/21/2089	
2020 PO7118488603	KU	5	35 BRN	SP	CRE	ED,ID	BD	9/22/2089	
2020 PO7130688789	KU	5	35 BRN	SP	CRE	ED,ID	BD	9/23/2089	
2020 PO7125688706	KU	3	50 BRN	SP	CRE	ED,ID	BD	9/24/2089	
2020 PO7136088866	KU	4	45 BRN	SP	CRE	ED,ID	BD	9/25/2089	
2020 PO7140788935	KU	4	40 BRN	SP	CRE	ED,ID	BD	9/26/2089	
2020 PO7142288956	KU	4	40 BRN	SP	CRE	ED,ID	BD	9/27/2089	
2020 PO7018089643	KU	5	35 BRN	SP	CRE	ED,ID	BD	9/28/2089	
2020 PO7415094603	KU	4	45 BRO	SP	CRE	ED,ID,MD	TD	9/29/2089	
2020 PO5279506627	KU	6	30 XXX	SP	CCA		V	9/30/2089	
2020 PO5349106399	KU	5	35 XXX	SP	CRE	ID	BD	10/1/2089	
2020 5321306343a	KU	5	30 BRN	SP	CCA		V	10/2/2089	
2020 PO7053089571	KU	6	30 BRN	SP	CCA		V	10/3/2089	
2020 PO1225828458	ODP	3	45 BRN	SP	CCA		V	10/4/2089	
2020 PO1233228480	ODP	4	45 BRN	SP	CCA		V	10/5/2089	
2020 PO1251528598	ODP	4	45 BRN	SP	CRE		V	10/6/2089	
2020 PO1282728453	ODP	4	45 BRN	SP	CCA		V	10/7/2089	
2020 PO4498635419	KU	4	45 ACE	SP	CCA		V	10/8/2089	
2020 PO4550235781	KU	3	45 ACE	SP	CRE		V	10/9/2089	
2020 PO1272428469	ODP	4	45 BRN	SP	CCA		V	10/10/2089	

2020 PO3981283040	LGE	4	30 BRN	SP	A	ED,ID	BD		10/11/2089
2020 PO3982283040	LGE	4	40 BRN	SP	CRE	ED,ID,IP,RB	TX	RR	10/12/2089
2020 PO1272728664	ODP	2	50 BRN	SP	CCA		V		10/13/2089
2020 PO1272328705	F	4	40 OTH	SP	P		V		10/14/2089
2020 PO1280728652	ODP	5	35 OTH	SP	CRE		V		10/15/2089
2020 PO1345534191	ODP	2	50 KOP	SP	CRE	ED,ID	TD		10/16/2089
2020 PO1379634316	ODP	2	50 KOP	SP	CRE	ED,ID,MD	TD		10/17/2089
2020 PO1403434343	ODP	2	50 KOP	SP	CRE	ED,ID,MD	TD		10/18/2089
2020 PO1297328775	ODP	2	55 OTH	SP	CRE		V		10/19/2089
2020 PO7037889673	KU	6	30 BRN	SP	CRE	ED,ID	TD		10/20/2089
2020 PO6058305848	KU	4	40 BRO	SP	CRE	ID	BD		10/21/2089
2020 PO6137005155	KU	4	40 BRO	SP	CCA		V		10/22/2089
2020 PO6121405189	KU	4	45 BRO	SP	CCA		V		10/23/2089
2020 PO6135705132	KU	2	45 BRO	SP	CRE	ID	TD		10/24/2089
2020 PO6123505019	KU	2	40 BRO	SP	CCA		V		10/25/2089
2020 PO5956206323	KU	4	50 BRO	SP	CRE	ID	TD		10/26/2089
2020 PO6009206300	KU	6	30 BRO	SP	CRE		V		10/27/2089
2020 PO6023106316	KU	6	30 BRO	SP	CCA		V		10/28/2089
2020 PO6032906263	KU	6	30 BRO	SP	CRE	ID	BD		10/29/2089
2020 PO5985406262	KU	4	40 BRO	SP	CRE	ID	TD		10/30/2089
2020 PO6007206216	KU	4	35 BRO	SP	CRE	ID	BD		10/31/2089
2020 PO6021806183	KU	4	40 BRO	SP	CRE	ID	BD		11/1/2089
2020 PO6021806183a	KU	5	35 BRO	SP	CCA		V		11/2/2089
2020 PO6035106145	KU	4	40 BRO	SP	CCA		V		11/3/2089
2020 PO6042706145	KU	4	40 BRO	SP	CRE	ID	TD		11/4/2089
2020 PO6055106106	KU	4	40 BRO	SP	CRE	ID	TD		11/5/2089
2020 PO6064706064	KU	6	30 BRO	SP	CRE	ID	TD		11/6/2089
2020 PO3889182626	LGE	3	45 BRO	SP	P		V		11/7/2089
2020 PO3889682649	LGE	3	45 BRO	SP	A	ED,ID	BD		11/8/2089
2020 PO3889882652	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD		11/9/2089
2020 PO6040338888	LGE	3	45 BRO	SP	A		V		11/10/2089
2020 PO1283526300	ODP	4	45 OTH	SP	CRE		V		11/11/2089
2020 PO2711627008	ODP	4	40 BRN	SP	CRE	ID	TD		11/12/2089
2020 PO2711826935	ODP	6	30 BRN	SP	CCA		V		11/13/2089
2020 PO2644026084	ODP	4	40 BRN	SP	CCA		V		11/14/2089
2020 PO1385026613	ODP	6	30 OTH	SP	CCA		V		11/15/2089
2020 PO1383126416	ODP	4	40 OTH	SP	CCA		V		11/16/2089
2020 PO1390326414	F	4	40 OTH	SP	CRE	ED,ID	VX	RP3	11/17/2089
2020 PO4838830740	KU	3	45 ACE	SP	CCA		V		11/18/2089
2020 PO4859830342	KU	3	45 ACE	SP	CCA		V		11/19/2089
2020 PO3001051689	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		11/20/2089
2020 PO3019051643	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		11/21/2089
2020 PO3981883064	LGE	4	30 BRN	SP	S		V		11/22/2089
2020 PO6057006046	KU	6	30 BRO	SP	CRE		V		11/23/2089
2020 PO1468826469	F	3	45 MAR	SP	CRE		V		11/24/2089
2020 PO6058605993	KU	4	30 BRO	SP	CRE	ID	TD		11/25/2089
2020 PO6054105991	KU	4	40 BRO	SP	CRE	ID	TD		11/26/2089

2020 PO6063006039	KU	4	40 BRO	SP	CRE	ID	TD			11/27/2089
2020 PO6069105943	KU	6	30 BRO	SP	CRE	ID	TD			11/28/2089
2020 PO6074605984	F	4	40 BRO	SP	CRE		V			11/29/2089
2020 PO6090605883	F	4	40 BRO	SP	CRE		V			11/30/2089
2020 PO6108305727	KU	6	30 BRO	SP	CCA		V			12/1/2089
2020 PO6097505826	KU	6	30 BRO	SP	CCA		V			12/2/2089
2020 PO5910206537	F	4	40 BRO	SP	CRE		V			12/3/2089
2020 PO7410694696	KU	4	45 BRO	SP	CRE	ED,ID	TD			12/4/2089
2020 PO7405994796	KU	4	40 BRO	SP	CRE	ED,ID	TD			12/5/2089
2020 PO7022689832	KU	4	40 BRN	SP	CRE	ED,ID	TD			12/6/2089
2020 PO7022889771	KU	5	35 BRN	SP	CRE	ED,ID	TD			12/7/2089
2020 PO5293306291	KU	5	30 XXX	SP	CRE	ED,ID	TD			12/8/2089
2020 PO5304506303	KU	5	30 XXX	SP	CRE	ED,ID	TD			12/9/2089
2020 PO5305906235	KU	6	30 XXX	SP	CRE	ED,ID	TD			12/10/2089
2020 PO5312706317	KU	6	30 XXX	SP	CRE	ED,ID	TD			12/11/2089
2020 PO7011789898	KU	5	35 BRN	SP	CRE	ED,ID,RB	TX		RR	12/12/2089
2020 PO7004789806	KU	6	30 BRN	SP	CRE	ED,ID	BD			12/13/2089
2020 PO7389094434	KU	4	30 BRO	SP	CRE	ID	BD			12/14/2089
2020 PO7392894348	KU	5	35 BRO	SP	CRE	ED,ID	BD			12/15/2089
2020 PO7406594373	KU	6	30 BRO	SP	CRE	ED,ID	TD			12/16/2089
2020 PO5321306343	KU	4	40 XXX	SP	CCA		V			12/17/2089
2020 PO5379106524	F	4	40 XXX	SP	P		V			12/18/2089
2020 PO5354506524	KU	5	35 XXX	SP	CRE	ED,ID	X		RP1	12/19/2089
2020 PO7045389383	KU	3	50 BRN	SP	CRE	ED,ID	BD			12/20/2089
2020 PO7397994178	KU	5	35 BRO	SP	CRE	ED,ID	TD			12/21/2089
2020 PO7412694220	KU	5	35 BRO	SP	CRE	ID	BD			12/22/2089
2020 PO7025389581	KU	4	40 BRN	SP	CRE	ED,ID	BD			12/23/2089
2020 PO7037289516	KU	6	30 BRN	SP	CRE		V			12/24/2089
2020 PO7040389519	KU	5	35 BRN	SP	CRE	ED,ID	BD			12/25/2089
2020 PO7029489438	F	4	40 BRN	SP	CRE		V			12/26/2089
2020 PO7031489416	KU	3	45 BRN	SP	CCA		V			12/27/2089
2020 PO7033389412	KU	3	45 BRN	SP	CCA		V			12/28/2089
2020 PO7035089401	KU	4	40 BRN	SP	CRE	ED,ID	BD			12/29/2089
2020 PO3926182945	F	4	40 BRO	SP	A		V			12/30/2089
2020 PO3927482938	F	4	40 BRO	SP	P		V			12/31/2089
2020 PO3928682932	F	4	40 BRO	SP	P		V			1/1/2090
2020 PO4005282699	F	4	30 BRN	SP	A		V			1/2/2090
2020 PO4005882696	F	4	40 BRN	SP	CCA		V			1/3/2090
2020 PO4006482709	F	4	40 BRN	SP	CRE		V			1/4/2090
2020 PO4005882716	F	4	30 BRN	SP	A		V			1/5/2090
2020 PO4007182722	F	3	45 BRN	SP	S		V			1/6/2090
2020 PO4006682725	F	4	30 BRN	SP	CCA		V			1/7/2090
2020 PO4007882736	F	4	45 BRN	SP	CRE		V			1/8/2090
2020 PO3956782776	LGE	4	30 BRN	SP	CRE		V			1/9/2090
2020 PO3938781975	LGE	4	30 BRN	SP	CRE	ED,ID	TD			1/10/2090
2020 PO3938881970	LGE	3	45 BRN	SP	CCA		V			1/11/2090
2020 PO4722287976	F	4	40 BRO	SP	CRE		V			1/12/2090

Business Use

2020 PO4723487980	F	3	45 BRO	SP	CCA		V			1/13/2090
2020 PO4720887972	F	3	45 BRO	SP	CCA		V			1/14/2090
2020 PO4721187959	F	3	45 BRO	SP	CCA		V			1/15/2090
2020 PO4604791761	F	4	40 KOP	SP	P		V			1/16/2090
2020 PO4595391764	F	4	40 KOP	SP	CRE		V			1/17/2090
2020 PO4584791770	F	4	40 KOP	SP	CRE		V			1/18/2090
2020 PO4575891774	F	4	40 KOP	SP	CRE		V			1/19/2090
2020 PO4554891784	F	4	40 KOP	SP	CRE		V			1/20/2090
2020 PO4537791790	F	4	40 KOP	SP	S		V			1/21/2090
2020 PO4526191796	F	4	40 KOP	SP	CRE		V			1/22/2090
2020 PO4503991803	F	3	45 KOP	SP	CCA		V			1/23/2090
2020 PO4690288594	LGE	4	35 BRN	SP	CRE	ED,ID		TD		1/24/2090
2020 PO4689388587	LGE	4	40 BRN	SP	A		ED,ID		TD	1/25/2090
2020 PO4688688583	LGE	4	40 BRN	SP	A		ED,ID		BD	1/26/2090
2020 PO4691788604	LGE	4	35 BRN	SP	CRE		ED,ID		TD	1/27/2090
2020 PO4532191515	KU	4	40 KOP	SP	CRE		ID		BD	1/28/2090
2020 PO3936881813	LGE	4	40 BRN	SP	CRE		ED,ID		BD	1/29/2090
2020 PO9283072751	KU	4	40 OTH	SP	CRE		ED,ID,SRS		TD	1/30/2090
2020 PO3937781827	LGE	3	45 BRN	SP	CCA				V	1/31/2090
2020 PO2035741494	ODP	4	40 KOP	SP	CRE		ED,ID		TD	2/1/2090
2020 PO20357-41494A	ODP	6	25 KOP	SP	A		ED,ID		TD	2/2/2090
2020 PO2029841124	ODP	2	50 KOP	SP	S				V	2/3/2090
2020 PO1996741173	ODP	2	50 KOP	SP	S				V	2/4/2090
2020 PO1967141398	ODP	2	50 KOP	SP	S				V	2/5/2090
2020 PO1951541594	ODP	2	50 KOP	SP	S				V	2/6/2090
2020 PO2591744381	KU	4	40 BRN	SP	CRE		ID,IP		BD	2/7/2090
2020 PO2966345872	KU	4	40 BRN	SP	CRE		ID		BX	RP2 2/8/2090
2020 PO2981745465	KU	4	40 BRN	SP	CRE				V	2/9/2090
2020 PO3395640947	KU	6	35 BRN	SP	CRE		ID		BD	2/10/2090
2020 PO3322141384	KU	6	30 BRN	SP	CRE		ED,ID		TD	2/11/2090
2020 PO4012082757	LGE	4	30 BRN	SP	A				V	2/12/2090
2020 PO4012982725	F	4	40 BRN	SP	CCA				V	2/13/2090
2020 PO4012482722	F	4	30 BRN	SP	CRE				V	2/14/2090
2020 PO4013482714	F	4	40 BRN	SP	CRE				V	2/15/2090
2020 PO9306772800	KU	3	40 OTH	SP	CRE		ED,ID,SRC		TX	RR 2/16/2090
2020 PO9312872714	KU	5	35 OTH	SP	CRE		ED,ID,SRC		TX	RR 2/17/2090
2020 PO9319572622	KU	5	35 OTH	SP	CRE		ED,ID,SRS		TD	2/18/2090
2020 PO9323372567	KU	5	35 OTH	SP	CRE		ED,ID,SRS		TD	2/19/2090
2020 PO9304672829	KU	5	35 OTH	SP	CRE		ED		T	2/20/2090
2020 PO9294972793	KU	6	30 OTH	SP	CRE		ED,ID,SRS		TD	2/21/2090
2020 PO9298472740	KU	4	40 OTH	SP	CRE		ED,SRS		T	2/22/2090
2020 PO4692888612	LGE	4	35 BRN	SP	CRE		ED,ID		TD	2/23/2090
2020 PO4725788029	F	4	40 BRO	SP	CRE				V	2/24/2090
2020 PO4727388029	F	4	40 BRO	SP	CRE				V	2/25/2090
2020 PO4729587984	F	3	45 BRO	SP	CCA				V	2/26/2090
2020 PO4729487993	F	4	40 BRO	SP	CRE				V	2/27/2090
2020 PO4728788029	F	4	40 BRO	SP	CRE				V	2/28/2090

2020 PO4729188011	F	4	40 BRO	SP	CRE		V	3/1/2090
2020 PO7281316701	KU	4	40 BRN	SP	CRE		V	3/2/2090
2020 PO4013582706	F	4	40 BRN	SP	A		V	3/3/2090
2020 P04155890421A	KU	6	30 KOP	SP	CRE	ED,ID	TD	3/4/2090
2020 PO4013082696	F	4	40 BRN	SP	CRE		V	3/5/2090
2020 PO4012482683	F	4	40 BRN	SP	CRE		V	3/6/2090
2020 PO3482148080	F	4	40 BRO	SP	CRE		V	3/7/2090
2020 PO4011882668	LGE	4	35 BRN	SP	A	ED,ID	TD	3/8/2090
2020 PO4014082656	LGE	3	45 BRN	SP	S		V	3/9/2090
2020 PO4011982661	F	4	40 BRN	SP	CRE		V	3/10/2090
2020 PO3929882926	F	4	40 BRO	SP	A		V	3/11/2090
2020 PO3930982913	F	5	25 BRO	SP	A		V	3/12/2090
2020 PO3931182920	F	4	40 BRO	SP	P		V	3/13/2090
2020 PO3931982918	F	4	30 BRO	SP	CCA		V	3/14/2090
2020 PO3932982916	F	5	25 BRO	SP	P		V	3/15/2090
2020 PO3932482922	F	4	40 BRO	SP	P		V	3/16/2090
2020 PO3933682929	F	4	40 BRO	SP	CCA		V	3/17/2090
2020 PO4010682669	F	4	40 BRN	SP	CRE		V	3/18/2090
2020 PO4009282677	F	4	40 BRN	SP	CRE		V	3/19/2090
2020 PO4008782684	F	4	40 BRN	SP	CRE		V	3/20/2090
2020 PO4009182695	F	4	40 BRN	SP	CCA		V	3/21/2090
2020 PO4009782708	F	4	40 BRN	SP	CRE		V	3/22/2090
2020 PO4713388494	LGE	4	40 BRN	SP	CCA		V	3/23/2090
2020 PO7215216362	KU	4	40 BRN	SP	CCA		V	3/24/2090
2020 PO7188316222	KU	4	40 XXX	SP	CRE	ID	BD	3/25/2090
2020 PO7149916011	KU	4	40 XXX	SP	CRE	ED,ID	TD	3/26/2090
2020 PO7102615792	KU	4	40 XXX	SP	CRE	ED,ID	TD	3/27/2090
2020 PO3939081896	LGE	3	45 BRN	SP	CCA		V	3/28/2090
2020 PO9323872163	KU	4	40 OTH	SP	CRE	ED,ID,SRS	BD	3/29/2090
2020 PO3939181920	LGE	4	40 BRN	SP	P	ED,ID	TD	3/30/2090
2020 PO3938981908	LGE	4	40 BRN	SP	CRE	ED,ID	TD	3/31/2090
2020 PO3939481932	LGE	4	40 BRN	SP	CRE	ED,ID	TD	4/1/2090
2020 PO3939681943	LGE	4	45 BRN	SP	CCA		V	4/2/2090
2020 PO3939981956	LGE	4	45 BRN	SP	CCA		V	4/3/2090
2020 PO4010482722	F	4	40 BRN	SP	CRE		V	4/4/2090
2020 PO4011282732	F	4	40 BRN	SP	CCA		V	4/5/2090
2020 PO4012682737	F	4	40 BRN	SP	CRE		V	4/6/2090
2020 PO4012482752	F	4	40 BRN	SP	A		V	4/7/2090
2020 PO4013282756	F	4	30 BRN	SP	A		V	4/8/2090
2020 PO4013182761	LGE	4	35 BRN	SP	CRE	ED,ID	BD	4/9/2090
2020 PO4013882758	LGE	4	35 BRN	SP	CRE		V	4/10/2090
2020 PO3668846939	KU	4	45 BRO	SP	CRE	ED	TD	4/11/2090
2020 PO3654447045	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/12/2090
2020 PO3618447014	KU	4	40 BRO	SP	CRE	ID,IP	BD	4/13/2090
2020 PO3935882935	F	4	40 BRO	SP	A		V	4/14/2090
2020 PO3935082938	F	4	40 BRO	SP	A		V	4/15/2090
2020 PO3937382943	F	5	25 BRO	SP	P		V	4/16/2090

2020 PO9320372203	KU	5	35 OTH	SP	CRE	ED,ID,MD,SRC	TX	RR	4/17/2090
2020 PO9320272137	KU	3	45 OTH	SP	CRE	ID	BD		4/18/2090
2020 PO4654288541	LGE	3	45 BRN	SP	CCA		V		4/19/2090
2020 PO4653688536	LGE	4	30 BRN	SP	CRE	ED,ID	BD		4/20/2090
2020 PO4652888530	LGE	3	50 BRN	SP	CCA		V		4/21/2090
2020 PO3616497970	LGE	4	30 BRN	SP	CCA		V		4/22/2090
2020 PO4809288282	LGE	4	40 BRO	SP	CRE	ED	TD		4/23/2090
2020 PO4808288338	LGE	4	40 BRO	SP	CRE	ED	TD		4/24/2090
2020 PO4835587797	LGE	UNK	95 BRO	ST	P		V		4/25/2090
2020 PO4152092512	KU	5	35 KOP	SP	S		V		4/26/2090
2020 PO4157392594	KU	4	40 KOP	SP	S		V		4/27/2090
2020 PO4155192583	KU	3	45 KOP	SP	S		V		4/28/2090
2020 PO4153992699	KU	5	35 KOP	SP	CRE	ED,ID	TD		4/29/2090
2020 PO4152592627	KU	6	30 KOP	SP	S		V		4/30/2090
2020 PO7060115343	KU	4	45 BRN	SP	CCA		VX	RP1	5/1/2090
2020 PO7078015535	KU	4	40 BRN	SP	CCA		V		5/2/2090
2020 PO3936882950	F	4	40 BRO	SP	P		V		5/3/2090
2020 PO3938782952	F	5	25 BRO	SP	P		V		5/4/2090
2020 PO3938182958	F	4	40 BRO	SP	P		V		5/5/2090
2020 PO3939882960	F	5	25 BRO	SP	P		V		5/6/2090
2020 PO3939382966	F	4	40 BRO	SP	P		V		5/7/2090
2020 PO3940882971	F	5	25 BRO	SP	P		V		5/8/2090
2020 PO3940282975	F	4	40 BRO	SP	P		V		5/9/2090
2020 PO1938341754	ODP	2	50 KOP	SP	S		V		5/10/2090
2020 PO1921841942	ODP	2	50 KOP	SP	S		V		5/11/2090
2020 PO1905442118	ODP	2	50 KOP	SP	S		V		5/12/2090
2020 PO1868542037	ODP	2	50 KOP	SP	S		V		5/13/2090
2020 PO1841141977	ODP	2	50 KOP	SP	S		V		5/14/2090
2020 PO1826141717	ODP	2	55 KOP	SP	S		V		5/15/2090
2020 PO3618547400	KU	4	40 BRO	SP	CRE	ID,IP	BD		5/16/2090
2020 PO1697539794	ODP	4	40 BRN	SP	CRE	ED,HH,ID,IP	BX	PX	5/17/2090
2020 PO1530239577	ODP	5	35 BRN	SP	CRE	ED,ID,IP,RB,SRC	X	PX	5/18/2090
2020 PO3598747463	KU	4	40 BRO	SP	CRE	ID,IP	BD		5/19/2090
2020 PO1608839251	F	6	35 KOP	SP	CRE		V		5/20/2090
2020 PO0212733194	ODP	5	35 XXX	SP	CRE	ED,ID	TD		5/21/2090
2020 PO0221433283	ODP	6	30 XXX	SP	CRE	ED,ID	TD		5/22/2090
2020 PO3444148331	F	4	40 BRO	SP	CRE		V		5/23/2090
2020 PO4004382536	LGE	4	40 BRN	SP	CRE	ED,ID	TD		5/24/2090
2020 PO4004582540	LGE	6	30 BRN	SP	A	ED,ID	TD		5/25/2090
2020 PO2052142710	ODP	6	35 KOP	SP	CRE	ED,ID	TD		5/26/2090
2020 PO3471648149	F	4	40 BRO	SP	CRE		V		5/27/2090
2020 PO4002082526	LGE	3	45 BRN	SP	CRE	ED,ID	BD		5/28/2090
2020 PO1197333700	ODP	4	45 BRN	SP	CRE	ED,ID	TD		5/29/2090
2020 PO1884140196	ODP	6	30 KOP	SP	A	ED,ID	TD		5/30/2090
2020 PO3946381771	LGE	4	35 BRN	SP	CRE	ED,ID	TD		5/31/2090
2020 PO3947481765	LGE	4	35 BRN	SP	CRE	ED,ID	TD		6/1/2090
2020 PO3945381778	LGE	4	35 BRN	SP	CRE	ED,ID	TD		6/2/2090

2020 PO3944681789	LGE	4	30 BRN	SP	CRE	ED,ID	TD		6/3/2090
2020 PO3944281785	LGE	4	40 BRN	SP	CCA		V		6/4/2090
2020 PO3943281791	LGE	4	35 BRN	SP	CRE	ED,ID	TD		6/5/2090
2020 PO3942181798	LGE	4	35 BRN	SP	A	ED,ID	TD		6/6/2090
2020 PO3941081806	LGE	4	40 BRN	SP	CCA		V		6/7/2090
2020 PO3939981813	LGE	4	35 BRN	SP	CRE	ED,ID	TD		6/8/2090
2020 PO3938881820	LGE	3	45 BRN	SP	CCA		V		6/9/2090
2020 PO3938881824	LGE	4	30 BRN	SP	CRE	ED,ID	TD		6/10/2090
2020 PO3938681845	LGE	4	40 BRN	SP	P	ED,ID	TD		6/11/2090
2020 PO3938481859	LGE	4	40 BRN	SP	CRE	ED,ID,IP,RB	TX	RR	6/12/2090
2020 PO1875040138	ODP	4	40 KOP	SP	CRE	ED,ID	TD		6/13/2090
2020 PO1850140093	ODP	4	40 KOP	SP	A	ED,ID,MD,RB	X	PX	6/14/2090
2020 PO1598639486	ODP	4	45 KOP	SP	S		V		6/15/2090
2020 PO1173333737	ODP	5	30 BRN	SP	CRE	ED,ID	TD		6/16/2090
2020 PO1182333720	ODP	4	40 BRN	SP	CRE	ED,ID	TD		6/17/2090
2020 PO1159633762	ODP	4	45 BRN	SP	CRE	ED,ID	TD		6/18/2090
2020 PO1150533779	ODP	4	45 BRN	SP	CRE	ED,ID	TD		6/19/2090
2020 PO1142733792	ODP	3	50 BRN	SP	CCA		V		6/20/2090
2020 PO1132433808	ODP	4	40 BRN	SP	CRE	ED,ID	TD		6/21/2090
2020 PO3879782902	LGE	2	65 BRO	SP	CRE		V		6/22/2090
2020 PO2552027226	ODP	4	40 BRN	SP	CRE		V		6/23/2090
2020 PO2573127248	ODP	4	40 BRN	SP	CRE	ID	X	PX	6/24/2090
2020 PO2492027439	ODP	4	40 BRN	SP	CRE		V		6/25/2090
2020 PO2552626874	ODP	3	45 BRN	SP	CCA		V		6/26/2090
2020 PO1127133820	ODP	4	40 BRN	SP	CRE	ED,ID	TD		6/27/2090
2020 PO1117833836	ODP	3	50 BRN	SP	CCA		V		6/28/2090
2020 PO1111133850	ODP	4	40 XXX	SP	CRE	ED,ID	TD		6/29/2090
2020 PO1106333860	ODP	4	40 XXX	SP	CRE	ED,ID	TD		6/30/2090
2020 PO1306834247	ODP	5	35 XXX	SP	CCA		V		7/1/2090
2020 PO2494927341	ODP	4	40 BRN	SP	CRE		V		7/2/2090
2020 PO7608622971	F	6	30 UNK	SP	CRE		V		7/3/2090
2020 PO7598423003	KU	6	30 UNK	SP	CCA		V		7/4/2090
2020 PO7603322949	KU	6	30 UNK	SP	CCA		V		7/5/2090
2020 PO3954881942	LGE	4	35 BRN	SP	A	ED,ID	BD		7/6/2090
2020 PO3953781950	LGE	3	45 BRN	SP	CCA		V		7/7/2090
2020 PO3954981950	LGE	4	35 BRN	SP	A	ED,ID	BD		7/8/2090
2020 PO3952181939	LGE	4	40 BRN	SP	CCA		V		7/9/2090
2020 PV3951881927	LGE	4	40 BRN	SP	CCA		V		7/10/2090
2020 PO3951581912	LGE	4	35 BRN	SP	CCA		V		7/11/2090
2020 PO3950181915	LGE	4	35 BRN	SP	P	ED,ID	TD		7/12/2090
2020 PO3949181922	LGE	4	35 BRN	SP	P	ED,ID	TD		7/13/2090
2020 PO3949081914	LGE	4	35 BRN	SP	A	ED,ID	TD		7/14/2090
2020 PO3948781919	LGE	3	45 BRN	SP	CCA		V		7/15/2090
2020 PO9597986184	KU	4	45 ACW	SP	CRE	ED,ID	BX	RP1	7/16/2090
2020 PO3919982941	F	4	40 BRO	SP	P		V		7/17/2090
2020 PO3991982756	F	4	30 BRN	SP	A		V		7/18/2090
2020 PO3991382760	F	4	40 BRN	SP	CRE		V		7/19/2090

2020 PO3921682932	F	4	40 BRO	SP	A		V		7/20/2090
2020 PO3922882927	F	4	40 BRO	SP	A		V		7/21/2090
2020 PO3997582359	LGE	4	40 BRN	SP	CRE	ED,ID	BD		7/22/2090
2020 PO3924082921	F	4	40 BRO	SP	P	ED,ID,RB	VX	RP1	7/23/2090
2020 PO3924582929	F	5	25 BRO	SP	A		V		7/24/2090
2020 PO3925182915	F	4	40 BRO	SP	A		V		7/25/2090
2020 PO3925882920	F	5	25 BRO	SP	P		V		7/26/2090
2020 PO3926182903	F	5	25 BRO	SP	A		V		7/27/2090
2020 PO3925382906	F	4	40 BRO	SP	P		V		7/28/2090
2020 PO3924582890	F	3	45 BRO	SP	CCA		V		7/29/2090
2020 PO3923882884	F	4	30 BRO	SP	CCA		V		7/30/2090
2020 PO3923982878	F	4	40 BRO	SP	A	ED,ID	VX	PX	7/31/2090
2020 PO3924582873	F	3	25 BRO	SP	A		V		8/1/2090
2020 PO3923582865	F	5	25 BRO	SP	A		V		8/2/2090
2020 PO3923582865A	F	3	45 BRO	SP	P		V		8/3/2090
2020 PO5742747681a	KU	6	30 ACE	SP	CCA		V		8/4/2090
2020 PO5742747681	KU	6	30 ACE	SP	CRE	ED,ID	TD		8/5/2090
2020 PO5760647845	KU	6	30 ACE	SP	CRE	ED,ID	TD		8/6/2090
2020 PO5762347225	F	4	40 ACE	SP	CRE		V		8/7/2090
2020 PO3921982865	F	4	40 BRO	SP	P		V		8/8/2090
2020 PO5742847020	F	4	40 ACE	SP	CRE		V		8/9/2090
2020 PO5784247458	F	4	40 ACE	SP	CRE		V		8/10/2090
2020 PO5752047116	F	4	40 ACE	SP	P		V		8/11/2090
2020 PO5774247353	F	4	40 ACE	SP	P		V		8/12/2090
2020 PO5697147444	KU	6	30 ACE	SP	CRE	ED,ID	TD		8/13/2090
2020 PO5698447506	F	4	40 ACE	SP	CRE		V		8/14/2090
2020 PO5692647595	F	4	40 ACE	SP	CRE		V		8/15/2090
2020 PO5679447541	KU	6	30 ACE	SP	CRE	ED,ID	TD		8/16/2090
2020 PO3921682859	LGE	4	30 BRO	SP	P	ID	BD		8/17/2090
2020 PO3921282853	F	5	30 BRO	SP	CCA		V		8/18/2090
2020 PO3920882859	F	3	45 BRO	SP	CCA		V		8/19/2090
2020 PO3919782853	F	3	45 BRO	SP	CCA		V		8/20/2090
2020 PO3917782852	F	4	40 BRO	SP	A	ED	VX	RP2	8/21/2090
2020 PO3996782381	LGE	4	40 BRN	SP	CRE	ED,ID	BD		8/22/2090
2020 PO3997182376	LGE	4	40 BRN	SP	CCA		V		8/23/2090
2020 PO3997882383	LGE	4	40 BRN	SP	CRE	ED,ID	BD		8/24/2090
2020 PO3999282404	LGE	4	40 BRN	SP	CRE	ED,ID	BD		8/25/2090
2020 PO0949635370	ODP	4	40 XXX	SP	CRE		V		8/26/2090
2020 PO1004435657	ODP	4	40 XXX	SP	CRE		V		8/27/2090
2020 PO1028735680	ODP	5	35 XXX	SP	CRE		V		8/28/2090
2020 PO3942781901	LGE	4	40 BRN	SP	A	ED,ID	TD		8/29/2090
2020 PO4000682421	LGE	4	45 BRN	SP	CRE		V		8/30/2090
2020 PO4000482444	LGE	4	40 BRN	SP	CRE	ED,ID	BD		8/31/2090
2020 PO3943181919	LGE	4	30 BRN	SP	CCA		V		9/1/2090
2020 PO3943081913	LGE	4	40 BRN	SP	CRE	ED,ID	TD		9/2/2090
2020 PO3943281926	LGE	4	40 BRN	SP	A	ED,ID	TD		9/3/2090
2020 PO3943581939	LGE	4	40 BRN	SP	A	ED,ID	TD		9/4/2090

2020 PO3943381952	LGE	4	40 BRN	SP	CRE		ED,ID,RB	VX	PX	9/5/2090
2020 PO1524038123	ODP	2	50 BRN	SP	CCA			V		9/6/2090
2020 PO1547738280	ODP	2	50 BRN	SP	CCA			V		9/7/2090
2020 PO1570538431	ODP	2	50 BRN	SP	CCA			V		9/8/2090
2020 PO4610988011	F	4	40 BRO	SP	CRE			V		9/9/2090
2020 PO4779688767	LGE	4	40 BRN	SP	CRE		ED,ID	TD		9/10/2090
2020 PO4782188782	LGE	4	40 BRN	SP	CRE		ED,ID	BD		9/11/2090
2020 PO6071067037	KU	6	30 OTH	SP	CCA			V		9/12/2090
2020 PO6048167024	KU	4	40 OTH	SP	CCA			V		9/13/2090
2020 PO6047067157	KU	4	45 OTH	SP	CRE		ID	TD		9/14/2090
2020 PO4612888000	F	4	45 BRO	SP	A			V		9/15/2090
2020 PO4612288000	F	3	45 BRO	SP	CCA			V		9/16/2090
2020 PO4611788001	F	4	45 BRO	SP	CRE			V		9/17/2090
2020 PO4611088001	F	4	40 BRO	SP	CRE			V		9/18/2090
2020 PO4695115943	F	3	45 BRO	SP	A			V		9/19/2090
2020 PO4876714648	KU	4	40 BRO	SP	CRE		ED,ID,IP	TD		9/20/2090
2020 PO4609988002	F	3	45 BRO	SP	CCA			V		9/21/2090
2020 PO4610488002	F	3	45 BRO	SP	CCA			V		9/22/2090
2020 PO4610888002	F	3	45 BRO	SP	CCA			V		9/23/2090
2020 PO4780088757	LGE	4	40 BRN	SP	CRE		ED,ID	TD		9/24/2090
2020 PO4780488749	LGE	4	40 BRN	SP	CRE		ED,ID	BD		9/25/2090
2020 PO4781688751	LGE	4	40 BRN	SP	CCA			V		9/26/2090
2020 PO4782188752	LGE	4	40 BRN	SP	CRE		ED,ID	BD		9/27/2090
2020 PO6066867525	KU	4	40 OTH	SP	CRE		ID	TD		9/28/2090
2020 PO6045667343	KU	3	50 OTH	SP	CRE		ID	TD		9/29/2090
2020 PO5929667110	KU	5	35 OTH	SP	CCA			V		9/30/2090
2020 PO6030167221	KU	4	40 OTH	SP	CRE		ID	TD		10/1/2090
2020 PO6095067176	KU	3	45 OTH	SP	CCA			V		10/2/2090
2020 PO4717088420	LGE	4	40 BRO	SP	CRE		ED,ID	BD		10/3/2090
2020 PO4717488416	LGE	UNK	70 BRO	SP	A			V		10/4/2090
2020 PO4718988429	LGE	UNK	75 BRO	SP	A			V		10/5/2090
2020 PO4769388558	LGE	2	55 BRO	SP	CCA			V		10/6/2090
2020 PO4770488584	LGE	3	50 BRO	SP	CCA			V		10/7/2090
2020 PO4769888569	LGE	1	45 BRO	SP	CCA		ED,ID,IP	BD		10/8/2090
2020 PO4772788628	LGE	3	45 BRO	SP	CCA			V		10/9/2090
2020 PO4773488624	LGE	4	40 BRO	AL	CCA			V		10/10/2090
2020 PO4773388621	LGE	UNK	25 BRO	SP	CCA		ED,ID	BD		10/11/2090
2020 PO4673506693	F	6	30 BRO	ST	CCA			V		10/12/2090
2020 PO6099067606	F	4	40 OTH	SP	P			V		10/13/2090
2020 PO6098867487	F	4	40 OTH	SP	S			V		10/14/2090
2020 PO6099067345	F	4	40 OTH	SP	P		ED	V		10/15/2090
2020 PO6099367279	F	4	40 OTH	SP	S		ED	V		10/16/2090
2020 PO6103767838	F	4	40 OTH	SP	P			V		10/17/2090
2020 PO6102767723	F	4	40 OTH	SP	P			V		10/18/2090
2020 PO6055669280	KU	5	35 OTH	SP	CRE		ED,ID,SRS	TD		10/19/2090
2020 PO6112267341	KU	4	45 OTH	SP	CRE		ID	TD		10/20/2090
2020 PO6072369586	KU	4	40 OTH	SP	S			V		10/21/2090

2020 PO6082768050	KU	4	40 OTH	SP	CRE	ID	TD	10/22/2090
2020 PO6085868245	KU	4	40 OTH	SP	CRE	ID	TD	10/23/2090
2020 PO6091267760	KU	3	45 OTH	SP	S		V	10/24/2090
2020 PO6122268722	KU	6	30 OTH	SP	CRE	ID	TD	10/25/2090
2020 PO6108068573	KU	4	40 OTH	SP	CRE	ID	TD	10/26/2090
2020 PO4663610302	F	4	40 BRO	SP	CRE		V	10/27/2090
2020 PO4657910403	F	4	40 BRO	SP	CRE		V	10/28/2090
2020 PO4651510513	F	4	40 BRO	SP	CRE		V	10/29/2090
2020 PO4657810487	KU	1	75 BRO	SP	CRE	ED,ID,IP	TD	10/30/2090
2020 PO4707209853	KU	1	75 BRO	ST	CCA		V	10/31/2090
2020 PO4679210172	KU	1	75 BRO	ST	CCA		V	11/1/2090
2020 PO4647810658	KU	1	75 BRO	SP	CRE	ED,ID,IP	TD	11/2/2090
2020 PO6151468295	KU	4	40 OTH	SP	CRE	ID	TD	11/3/2090
2020 PO6088368509	KU	4	40 OTH	SP	CRE	ID	TD	11/4/2090
2020 PO6151568703	KU	5	35 OTH	SP	CRE	ID	TD	11/5/2090
2020 PO6194168849	KU	4	40 OTH	SP	CRE	ID	TD	11/6/2090
2020 PO4645410616	F	4	40 BRO	SP	CRE		V	11/7/2090
2020 PO4638710727	F	4	40 BRO	SP	CRE		V	11/8/2090
2020 PO4635010784	F	4	40 BRO	SP	CRE		V	11/9/2090
2020 PO4637110835	KU	1	70 BRO	ST	CRE		V	11/10/2090
2020 PO4612711375	KU	1	75 BRO	ST	CRE		V	11/11/2090
2020 PO4620711154	KU	1	65 BRO	ST	CRE		V	11/12/2090
2020 PO6082368633	KU	4	40 OTH	SP	CRE	ID	TD	11/13/2090
2020 PO6060468666	KU	6	30 OTH	SP	CRE	ID	TD	11/14/2090
2020 PO6060369083	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	11/15/2090
2020 PO6077068751	KU	5	35 OTH	SP	CRE	ID	TD	11/16/2090
2020 PO6070468878	KU	4	40 OTH	SP	CRE	ID	TD	11/17/2090
2020 PO4699015886	KU	4	40 BRO	SP	CRE	ID	BD	11/18/2090
2020 PO4725115621	KU	4	40 BRO	SP	CRE	ED	TD	11/19/2090
2020 PO6057669179	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD	11/20/2090
2020 PO4750788233	LGE	2	45 BRO	SP	CCA	ED,ID,IP	BD	11/21/2090
2020 PO0514744806	F	5	30 BRN	SP	A		V	11/22/2090
2020 PO0515044945	F	5	30 XXX	SP	CRE		V	11/23/2090
2020 PO0503144946	ODP	4	40 KOP	SP	CRE	ED,ID	TD	11/24/2090
2020 PO0438545165	ODP	4	40 BRN	SP	CRE	ID	BD	11/25/2090
2020 PO0471444917	ODP	3	40 BRN	SP	A	ED,ID	TD	11/26/2090
2020 PO0482144859	ODP	4	40 BRN	SP	CRE	ID	BD	11/27/2090
2020 PO0499444795	ODP	4	45 BRN	SP	CCA		V	11/28/2090
2020 PO0490444413	ODP	5	35 BRN	SP	CRE	ID	BD	11/29/2090
2020 PO0516144348	ODP	3	45 BRN	SP	CCA		V	11/30/2090
2020 PO0531144374	ODP	3	45 BRN	SP	CCA		V	12/1/2090
2020 PO0546144386	ODP	3	45 BRN	SP	CCA		V	12/2/2090
2020 PO0563044225	ODP	3	45 BRN	SP	CCA		V	12/3/2090
2020 PO0579444076	ODP	3	45 BRN	SP	CCA		V	12/4/2090
2020 PO0571543924	ODP	6	30 BRN	SP	CCA		V	12/5/2090
2020 PO0497944318	ODP	3	45 BRN	SP	CCA		V	12/6/2090
2020 PO6088766485	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	12/7/2090

2020 PO6099966503	KU	4	40 OTH	SP	CRE	ED,ID	BD	12/8/2090
2020 PO4773988855	LGE	3	40 BRN	SP	S		V	12/9/2090
2020 PO4773388866	LGE	4	40 BRN	SP	A	ED,ID	BD	12/10/2090
2020 PO5092613866	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	12/11/2090
2020 PO5089813698	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	12/12/2090
2020 PO5117614283	KU	5	35 BRO	SP	CRE	ID,IP	BD	12/13/2090
2020 PO5092513997	KU	3	50 BRO	SP	CCA		V	12/14/2090
2020 PO1963128896	ODP	2	45 XXX	SP	CRE		V	12/15/2090
2020 PO1950028918	ODP	2	45 XXX	SP	CCA		V	12/16/2090
2020 PO1979128730	ODP	4	40 XXX	SP	CCA	ED	T	12/17/2090
2020 PO1985528628	ODP	5	35 XXX	SP	CCA		V	12/18/2090
2020 PO1990028645	ODP	4	40 XXX	SP	CRE	ID	TD	12/19/2090
2020 PO2137024774	ODP	4	45 XXX	SP	CRE		V	12/20/2090
2020 PO1923624525	F	4	40 XXX	SP	CRE		V	12/21/2090
2020 PO2297122561	ODP	4	35 XXX	SP	CCA		V	12/22/2090
2020 PO2196426756	ODP	5	35 XXX	SP	CRE	ID	TD	12/23/2090
2020 PO4772688881	LGE	4	40 BRN	SP	CRE	ED,ID	TD	12/24/2090
2020 PO3587351474	F	2	40 OTH	SP	P		V	12/25/2090
2020 PO3582851592	KU	5	35 OTH	SP	CRE	ID	BD	12/26/2090
2020 PO3579051522	F	2	45 OTH	SP	P		V	12/27/2090
2020 PO3571051570	F	2	45E BRN	SP	P		V	12/28/2090
2020 PO3566051696	KU	5	25 BRN	SP	CRE	ED,ID,SRS	TD	12/29/2090
2020 PO3562451619	F	5	40E BRN	SP	CRE		V	12/30/2090
2020 PO3555251625	KU	3	40E BRN	SP	CRE	ED,ID,SRS	TD	12/31/2090
2020 PO3552251671	KU	4	40 BRN	SP	CRE		B	1/1/2091
2020 PO3552452038	KU	4	40 BRN	SP	CCA		V	1/2/2091
2020 PO3540851711	KU	4	40E UNK	SP	CRE	ED,ID,SRS	TD	1/3/2091
2020 PO3523951749	KU	3	40E UNK	SP	CRE	ED,ID,SR	TD	1/4/2091
2020 PO3498551312	KU	4	40 UNK	SP	CRE	ED,ID,SRS	TD	1/5/2091
2020 PO4695688309	LGE	4	35 BRO	SP	CRE	ED,ID	TD	1/6/2091
2020 PO4696688322	LGE	4	35 BRO	SP	CRE	ED,ID	BD	1/7/2091
2020 PO5056613827	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	1/8/2091
2020 PO5051513847	KU	6	30 BRO	SP	CRE	ID,IP	BD	1/9/2091
2020 PO5037513922	KU	4	40 BRO	SP	CRE	ID,IP	BD	1/10/2091
2020 PO5025313970	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	1/11/2091
2020 PO4775388912	LGE	4	40 BRN	SP	S		T	1/12/2091
2020 PO5013714017	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	1/13/2091
2020 PO4678614053	F	4	40 BRO	SP	CRE		V	1/14/2091
2020 PO4667713936	F	4	40 BRO	SP	CRE		V	1/15/2091
2020 PO4712588382	LGE	4	40 BRO	SP	P	ED,ID	TD	1/16/2091
2020 PO4713688391	LGE	4	40 BRO	SP	CRE	ED,ID	BD	1/17/2091
2020 PO4714188388	LGE	UNK	65 BRO	SP	A		V	1/18/2091
2020 PO5045013153	F	4	40 BRO	SP	CRE		V	1/19/2091
2020 PO4775988899	LGE	4	40 BRN	SP	CRE	ED,ID,IP	BD	1/20/2091
2020 PO5065413500	F	4	40 BRO	SP	CRE		V	1/21/2091
2020 PO9283694152A	KU	7	35 BRN	SP	CRE	ED,ID	BX	RR 1/22/2091
2020 PO9248193954	KU	4	40 BRN	SP	CRE	ED,ID	TD	1/23/2091

2020 PO9283694152D	KU	7	35 BRN	SP	CRE	ID	BD	1/24/2091
2020 PO9283694152C	KU	7	35 BRN	SP	CRE	ED,ID	TD	1/25/2091
2020 PO9283694152B	KU	7	35 BRN	SP	CRE	ID	BD	1/26/2091
2020 PO9283694152E	KU	6	30 BRN	SP	S		V	1/27/2091
2020 PO9283694152F	KU	7	35 BRN	SP	CRE	ID	TD	1/28/2091
2020 PO9283694152G	KU	5	35 BRN	SP	S	ID	BD	1/29/2091
2020 PO9663994902	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	1/30/2091
2020 PO9660695025	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	1/31/2091
2020 PO5398646082	KU	3	45 ACE	SP	CCA		V	2/1/2091
2020 PO5389546135	KU	2	50 ACE	SP	CCA		V	2/2/2091
2020 PO5632146889	KU	6	30 ACE	SP	CCA		V	2/3/2091
2020 PO5584847010	KU	6	30 ACE	SP	CRE	ED,ID	TD	2/4/2091
2020 PO9639195024	KU	5	35 ACW	SP	S		V	2/5/2091
2020 PO9646095003	KU	4	40 ACW	SP	CCA		V	2/6/2091
2020 PO9647594903	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	2/7/2091
2020 PO9279994247	KU	6	30 BRN	SP	CRE	ED,ID	TD	2/8/2091
2020 PO9283694152	KU	4	40 BRN	SP	CRE		V	2/9/2091
2020 PO9267594110	KU	3	45 BRN	SP	S		V	2/10/2091
2020 PO9252594130	KU	6	30 BRN	SP	CRE	ID	BD	2/11/2091
2020 PO9251494184	KU	3	45 BRN	SP	S		V	2/12/2091
2020 PO9252194070	KU	4	40 XXX	SP	CRE	ED,ID	TD	2/13/2091
2020 PO5608724341	KU	4	40 BRO	SP	CCA		V	2/14/2091
2020 PO5633724357	KU	4	40 BRO	SP	CRE		V	2/15/2091
2020 PO5624324633	F	4	40 BRO	SP	CRE		V	2/16/2091
2020 PO5086732145	KU	5	35 BRO	SP	A	ED,ID	TD	2/17/2091
2020 PO5066632155	KU	5	35 BRO	SP	CRE	ED,ID	TD	2/18/2091
2020 PO5654546992	KU	6	30 ACE	SP	CRE	ED,ID	TD	2/19/2091
2020 PO5639546922	F	4	40 ACE	SP	CRE	ED,HH,RB	BX	RP1 2/20/2091
2020 PO5667147073	F	4	40 ACE	SP	CRE		V	2/21/2091
2020 PO9229294007	KU	4	40 XXX	SP	CRE	ED,ID,RB	TX	RR 2/22/2091
2020 PO9187393946	KU	5	45 XXX	SP	CRE	ED,ID,RB	TX	RR 2/23/2091
2020 PO9174993912	KU	4	40 XXX	SP	CRE	ED,ID,SRC	TX	RR 2/24/2091
2020 PO9244994052	KU	4	40 XXX	SP	CRE	ED,ID	TD	2/25/2091
2020 PO9215293967	KU	4	40 XXX	SP	CRE	ED,ID,SRC	TX	RR 2/26/2091
2020 PO9205893999	KU	4	40 XXX	SP	CRE	ED,ID	TD	2/27/2091
2020 PO9757094759	C	4	40 ACW	SP	CRE		V	2/28/2091
2020 PO9754194758	KU	5	35 ACW	SP	CRE	ED,ID	TD	3/1/2091
2020 PO9761694868	KU	5	20 ACW	DF	CRE	ED,ID	TD	3/2/2091
2020 PO9756094866	KU	3	45 ACW	SP	CRE	ED,ID	TD	3/3/2091
2020 PO9752095029	KU	4	45 ACW	SP	CRE	ED,ID	BD	3/4/2091
2020 PO9756895144	KU	5	35 ACW	SP	CRE	ED,ID	BD	3/5/2091
2020 PO9749195153	KU	4	40 ACW	SP	CRE	ED,ID	TD	3/6/2091
2020 PO9747395360	KU	4	40 ACW	SP	CRE	ED,ID	BD	3/7/2091
2020 PO9728495362	KU	4	40 ACW	SP	CRE	ED,ID	TD	3/8/2091
2020 PO5672646936	F	4	40 ACE	SP	CRE		V	3/9/2091
2020 PO5670646927	F	4	40 ACE	SP	CRE		V	3/10/2091
2020 PO5637546775	F	4	40 ACE	SP	P		V	3/11/2091

2020 PO5644546808	F	4	40 ACE	SP	CRE		V	3/12/2091
2020 PO5655246858	F	4	40 ACE	SP	CRE		V	3/13/2091
2020 PO5708946794	KU	6	30 ACE	SP	CRE	ED,ID	TD	3/14/2091
2020 PO5676946844	F	4	40 ACE	SP	CRE	ED,HH,ID,IP,RB	BX	3/15/2091
2020 PO5619446404	F	4	40 ACE	SP	CRE		V	3/16/2091
2020 PO5604346505	F	4	40 ACE	SP	CRE		V	3/17/2091
2020 PO5107332137	KU	3	45 BRO	SP	CCA		V	3/18/2091
2020 PO5111532293	KU	3	45 BRO	SP	CCA		V	3/19/2091
2020 PO5110432433	KU	4	40 BRO	SP	CCA		V	3/20/2091
2020 PO5580046967	F	4	40 ACE	SP	CRE		V	3/21/2091
2020 PO5597646636	F	4	40 ACE	SP	CRE		V	3/22/2091
2020 PO5241124885	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	3/23/2091
2020 PO9312393256	KU	4	40 ACW	SP	CRE		V	3/24/2091
2020 PO9201594234	KU	4	40 BRN	SP	CRE	ED,ID	TD	3/25/2091
2020 PO5712346929	KU	4	35 ACE	SP	CRE	ED,ID	TD	3/26/2091
2020 PO5698746801	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	3/27/2091
2020 PO5692546921	F	4	40 ACE	SP	CRE		V	3/28/2091
2020 PO5723446801	KU	4	45 ACE	SP	CRE	ED,ID	BD	3/29/2091
2020 PO5518645872	KU	4	40 ACE	SP	CCA		V	3/30/2091
2020 PO4063904721	KU	3	45 BRO	SP	CCA		V	3/31/2091
2020 PO3615747518	KU	4	40 BRN	SP	CCA		V	4/1/2091
2020 PO3627447276	KU	4	40 BRN	SP	CRE		V	4/2/2091
2020 PO3641646977	KU	4	40 BRN	SP	CRE		V	4/3/2091
2020 PO3652046782	KU	4	40 BRN	SP	CCA		V	4/4/2091
2020 PO3670546377	KU	4	40 BRN	SP	CRE		V	4/5/2091
2020 PO3659146624	KU	3	45 BRN	SP	CCA		V	4/6/2091
2020 PO3682746111	KU	4	40 BRN	DF	CRE		V	4/7/2091
2020 PO3694045880	KU	4	40 BRN	SP	CRE		V	4/8/2091
2020 PO3606047699	KU	4	40 BRN	SP	CCA		V	4/9/2091
2020 PO3599647817	KU	4	40 BRN	SP	CCA		V	4/10/2091
2020 PO3593447956	KU	4	40 BRN	SP	CRE		V	4/11/2091
2020 PO3606448140	KU	4	40 BRN	SP	CRE		V	4/12/2091
2020 PO3621848292	KU	4	40 BRN	SP	CRE		V	4/13/2091
2020 PO3636548443	KU	4	40 BRN	SP	CCA		V	4/14/2091
2020 PO3654648629	KU	4	40 BRN	SP	CRE		V	4/15/2091
2020 PO4111304895	KU	6	30 BRO	SP	CCA		V	4/16/2091
2020 PO4113605022	KU	3	40 BRO	SP	CCA		V	4/17/2091
2020 PO5379746750	KU	4	40 ACE	SP	CRE	ED,ID	TD	4/18/2091
2020 PO5406146584	KU	4	35 ACE	SP	CRE	ED,ID	TD	4/19/2091
2020 PO4057205303	KU	3	50 BRO	SP	CCA		V	4/20/2091
2020 PO4038605656	KU	4	40 BRO	SP	CCA		V	4/21/2091
2020 PO4007206097	KU	3	45 BRO	SP	CRE		V	4/22/2091
2020 PO4022305928	KU	5	35 BRO	SP	CRE		V	4/23/2091
2020 PO4157305057	KU	4	40 BRO	ST	P		V	4/24/2091
2020 PO3964206646	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/25/2091
2020 PO5406746470	KU	1	70 ACE	SP	CRE		V	4/26/2091
2020 PO5410846416	KU	1	70 ACE	SP	CRE		V	4/27/2091

2020 PO5409346435	KU	1	70 ACE	SP	CRE		V	4/28/2091
2020 PO5408246454	KU	1	70 ACE	SP	CRE		V	4/29/2091
2020 PO3974506484	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/30/2091
2020 PO3668648778	KU	4	40 BRN	SP	CRE		V	5/1/2091
2020 PO3621651092	KU	4	40 BRN	SP	CRE	ID	BD	5/2/2091
2020 PO2841541772	ODP	4	40 ACW	SP	S		V	5/3/2091
2020 PO2279146166	ODP	6	30 ACW	SP	S		V	5/4/2091
2020 PO2287046168	ODP	4	45 ACW	SP	S		V	5/5/2091
2020 PO2296246131	ODP	4	45 ACW	SP	S		V	5/6/2091
2020 PO2051842581	F	4	40 ACW	SP	P		V	5/7/2091
2020 PO2025042820	ODP	4	45 ACW	SP	CRE	ID	BD	5/8/2091
2020 PO2305646075	ODP	4	45 ACW	SP	S		V	5/9/2091
2020 PO2326645939	ODP	5	35 ACW	SP	S		V	5/10/2091
2020 PO2892441176	F	5	35 ACW	SP	P		V	5/11/2091
2020 PO2868841515	ODP	4	35 ACW	SP	CRE	ID	TD	5/12/2091
2020 PO2850541770	ODP	5	35 ACW	SP	CRE	ED,ID	TD	5/13/2091
2020 PO2832142023	ODP	5	35 ACW	SP	CRE	ED,ID	TD	5/14/2091
2020 PO2808242340	ODP	5	35 ACW	SP	CRE	ID	BD	5/15/2091
2020 PO2791542543	F	4	40 ACW	SP	P		V	5/16/2091
2020 PO2757642851	ODP	5	35 ACW	SP	P	ED,ID	TD	5/17/2091
2020 PO2736243054	ODP	4	40 ACW	SP	CRE	ED,ID	TD	5/18/2091
2020 PO2720343207	ODP	6	35 ACW	SP	CRE	ED,ID	TD	5/19/2091
2020 PO7217888199	F	4	40 BRO	SP	CRE	ED,ID,RB	VX	RP2 5/20/2091
2020 PO7229287983	KU	4	40 BRO	SP	P	ED	TD	5/21/2091
2020 PO7225988046	F	4	40 BRO	SP	CRE		V	5/22/2091
2020 PO7240287734	KU	5	30 BRO	SP	CRE	ED,ID	BD	5/23/2091
2020 PO6895476094	KU	4	40 BRN	SP	CRE	ED,ID	TD	5/24/2091
2020 PO6897075831	KU	4	40 BRN	SP	CRE	ED,ID	BD	5/25/2091
2020 PO7218887868	F	4	45 BRO	SP	CRE		V	5/26/2091
2020 PO7233187910	F	3	45 BRO	SP	CRE		V	5/27/2091
2020 PO7243287941	KU	3	40 BRO	SP	CRE		V	5/28/2091
2020 PO7249887953	KU	3	40 BRO	SP	A	ED,ID,RB,SRC	TX	RR 5/29/2091
2020 PO7244388060	KU	5	35 BRO	SP	CRE	ED,ID	TD	5/30/2091
2020 PO7232388287	KU	5	35 BRO	SP	CRE	ED,ID	TD	5/31/2091
2020 PO6875475545	KU	6	30 BRN	SP	CRE	ED,ID	BD	6/1/2091
2020 PO6875475604	KU	4	40 BRN	SP	CRE	ED,ID	TD	6/2/2091
2020 PO6896675603	KU	4	40 BRN	SP	CCA		V	6/3/2091
2020 PO8380267903	KU	4	40 BRO	SP	CRE	ED,ID	TD	6/4/2091
2020 PO7241288244	KU	5	35 BRO	SP	CCA		V	6/5/2091
2020 PO7238488177	KU	5	35 BRO	SP	CRE	ED,ID	TD	6/6/2091
2020 PO7253787914	F	6	25 BRO	SP	A	ED,ID	VX	RP3 6/7/2091
2020 PO6851775605	KU	4	40 BRN	SP	CRE	ED,ID	BD	6/8/2091
2020 PO6831775606	KU	4	40 BRN	SP	CRE	ED,ID	TD	6/9/2091
2020 PO6849075362	KU	4	40 BRN	SP	CCA		V	6/10/2091
2020 PO6811075349	KU	4	40 BRN	SP	CRE	ED,ID	BD	6/11/2091
2020 PO6830375361	KU	4	40 BRN	SP	CRE	ED,ID	TD	6/12/2091
2020 PO6830075197	KU	4	40 BRN	SP	CCA		V	6/13/2091

2020 PO6830074938	KU	4	40 BRN	SP	CCA		V	6/14/2091
2020 PO6824574963	KU	4	40 BRN	SP	CCA		V	6/15/2091
2020 PO6824574739	KU	4	40 BRN	SP	CCA		V	6/16/2091
2020 PO7262987997	F	4	40 BRO	SP	CRE		V	6/17/2091
2020 PO7271788249	KU	4	45 BRO	SP	CCA		B	6/18/2091
2020 PO7267588044	KU	4	45 BRO	SP	CRE	ED,ID	BD	6/19/2091
2020 PO7239787129	F	3	40 BRO	SP	CRE		V	6/20/2091
2020 PO7246687153	KU	2	50 BRO	SP	A	ED,ID	TD	6/21/2091
2020 PO7265387260	KU	5	30 BRO	SP	CRE	ED,ID	TD	6/22/2091
2020 PO7276087845	F	5	30 BRO	SP	CRE	ED,ID	V	6/23/2091
2020 PO8371268042	KU	4	40 BRO	SP	CRE	ED,ID	TD	6/24/2091
2020 PO8372068243	KU	4	40 BRO	SP	CCA		V	6/25/2091
2020 PO8356667997	KU	4	40 BRO	SP	CRE	ED,ID	TD	6/26/2091
2020 PO8366067813	KU	6	30 BRO	SP	CRE	ED,ID	BD	6/27/2091
2020 PO7270487792	KU	4	45 BRO	SP	CRE	ED,ID	TD	6/28/2091
2020 PO7273787740	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	6/29/2091
2020 PO7278887608	KU	4	45 BRO	SP	CRE	ED,ID	TD	6/30/2091
2020 PO7246686726	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/1/2091
2020 PO8369267736	KU	5	35 BRO	SP	CRE	ED,ID	BD	7/2/2091
2020 PO8374267682	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/3/2091
2020 PO8381367614	KU	6	30 BRO	SP	CRE	ED,ID,RB	X	7/4/2091
2020 PO7242686822	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/5/2091
2020 PO7234086879	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/6/2091
2020 PO7230186969	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/7/2091
2020 PO7252286860	F	2	55 BRO	SP	CRE		V	7/8/2091
2020 PO7261286935	KU	5	35 BRO	SP	CRE	ED,ID	BD	7/9/2091
2020 PO7247486961	F	3	50 BRO	SP	CRE		V	7/10/2091
2020 PO4469101244	F	4	40 BRO	SP	CRE		V	7/11/2091
2020 PO4469501056	F	4	40 BRO	SP	CRE		V	7/12/2091
2020 PO4420000919	KU	6	30 BRO	SP	CCA		V	7/13/2091
2020 PO6799176219	F	3	45 BRN	SP	P		V	7/14/2091
2020 PO6789576085	F	3	45 BRN	SP	P		V	7/15/2091
2020 PO6778275919	F	3	40E BRN	SP	P		V	7/16/2091
2020 PO6774375858	F	3	45 BRN	SP	CRE		V	7/17/2091
2020 PO6757175858	F	3	45 BRN	SP	CCA		V	7/18/2091
2020 PO6730475861	F	3	45 BRN	SP	P		V	7/19/2091
2020 PO6704275863	F	3	40E BRN	SP	P		V	7/20/2091
2020 PO6677775866	F	3	45 BRN	SP	P		V	7/21/2091
2020 PO6651375866	F	3	45 BRN	SP	P		V	7/22/2091
2020 PO6624575872	F	3	45 BRN	SP	P		V	7/23/2091
2020 PO6599975873	F	3	45 BRN	SP	P		V	7/24/2091
2020 PO6779375597	KU	5	35 BRN	SP	CRE	ED,ID	TD	7/25/2091
2020 PO6760375430	KU	6	30 BRN	SP	CRE	ED,ID	TD	7/26/2091
2020 PO0534426517	KU	4	40 BRO	SP	CRE	ID	BX	7/27/2091
2020 PO4573203107	KU	4	40 XXX	SP	CRE		V	7/28/2091
2020 PO8210070552	KU	5	35 BRO	SP	CRE	ED,ID	TD	7/29/2091
2020 PO8213070794	KU	6	30 BRO	SP	CRE	ED,ID	TD	7/30/2091

2020 PO8238771048	KU	5	35 BRO	SP	CRE	ED,ID	TD			7/31/2091
2020 PO8241570716	KU	4	35 BRO	SP	A	ED,ID	TD			8/1/2091
2020 PO8225570733	KU	2	65 BRO	SP	CRE	ED,ID	BD			8/2/2091
2020 PO8242770816	KU	5	35 BRO	SP	CRE	ED,ID	TD			8/3/2091
2020 PO8255870902	KU	5	35 BRO	SP	CRE	ED	TD			8/4/2091
2020 PO8249470819	KU	5	35 BRO	SP	CRE	ED,EP,ID	VX	PX		8/5/2091
2020 PO8260370964	KU	5	35 BRO	SP	CRE		VX	PX		8/6/2091
2020 PO4640203788	KU	5	40 XXX	SP	CRE	ED,ID	TD			8/7/2091
2020 PO4671103715	KU	4	40 XXX	SP	CRE	ED,ID	TD			8/8/2091
2020 PO4654103604	KU	4	45 XXX	SP	CRE	ED,ID	TX	RR		8/9/2091
2020 PO0575726553	KU	4	40 BRO	SP	CRE	ID	BX	RP2		8/10/2091
2020 PO0500926497	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD			8/11/2091
2020 PO0521024551	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			8/12/2091
2020 PO0539924809	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			8/13/2091
2020 PO0570424622	KU	4	40 BRO	SP	CRE	ED,ID	BD			8/14/2091
2020 PO0476626283	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD			8/15/2091
2020 PO0444226418	KU	4	40 BRO	SP	CRE	ID	BD			8/16/2091
2020 PO0446326152	KU	6	30 BRO	SP	CRE	ID	BD			8/17/2091
2020 PO0456626134	KU	4	40 BRO	SP	CRE		V			8/18/2091
2020 PO0552824764	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			8/19/2091
2020 PO0566725069	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			8/20/2091
2020 PO0571725326	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD			8/21/2091
2020 PO0573825241	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			8/22/2091
2020 PO0600125490	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD			8/23/2091
2020 PO0672126940	KU	4	40 BRO	SP	CRE	ID	BD			8/24/2091
2020 PO0587025335	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			8/25/2091
2020 PO8143370807	KU	5	35 BRO	SP	CRE	ED,ID	TD			8/26/2091
2020 PO4659503320	KU	6	30 KOP	SP	CCA		V			8/27/2091
2020 PO4653503297	KU	4	40 XXX	SP	CRE	ED,ID	TD			8/28/2091
2020 PO4637203503	KU	4	40 XXX	SP	CRE	ED,ID	TD			8/29/2091
2020 PO4625403432	KU	4	40 XXX	SP	CRE	ED,ID,IP	TX	RR		8/30/2091
2020 PO4621803480	KU	6	30 BRN	SP	CCA		V			8/31/2091
2020 PO4615503360	KU	4	40 XXX	SP	CRE	ED,ID	TD			9/1/2091
2020 PO4593803220	KU	4	40 XXX	SP	CRE	ED,ID	TD			9/2/2091
2020 PO8133070601	KU	6	30 BRO	SP	CRE	ED,ID	BD			9/3/2091
2020 PO8135670719	KU	4	40 BRO	SP	CRE	ED,ID	TD			9/4/2091
2020 PO4416700934	F	4	40 BRO	SP	CRE		V			9/5/2091
2020 PO4402000947	F	4	40 BRO	SP	CRE		V			9/6/2091
2020 PO4407500886	F	4	40 BRO	SP	CRE		V			9/7/2091
2020 PO4401100790	KU	6	30 BRO	SP	CRE	ID	TD			9/8/2091
2020 PO4417400788	F	4	40 BRO	SP	CRE		V			9/9/2091
2020 PO4410700783	F	4	40 BRO	SP	CRE		V			9/10/2091
2020 PO4420400695	KU	6	30 BRO	SP	CCA		V			9/11/2091
2020 PO4413100577	KU	6	30 BRO	SP	CCA		V			9/12/2091
2020 PO4378001163	KU	4	40 BRO	SP	CRE		V			9/13/2091
2020 PO4386501216	KU	5	35 BRO	SP	CRE		V			9/14/2091
2020 PO4568402192	KU	4	40 BRO	SP	CRE	ID	TD			9/15/2091

2020 PO4559002044	KU	4	40 BRO	SP	CRE	ID	BD	9/16/2091
2020 PO4552302003	KU	4	40 BRO	SP	CRE	ID	TD	9/17/2091
2020 PO4538902050	KU	4	40 BRO	SP	CRE	ID	TD	9/18/2091
2020 PO4503701947	KU	4	40 BRO	SP	CRE	ID	TD	9/19/2091
2020 PO4494401913	KU	6	30 BRO	SP	CRE	ID	TD	9/20/2091
2020 PO4414601199	F	4	40 BRO	SP	CRE		V	9/21/2091
2020 PO4394901197	KU	4	40 BRO	SP	CRE	ID	TD	9/22/2091
2020 PO4366601148	F	4	40 BRO	SP	CRE		V	9/23/2091
2020 PO4360401145	KU	4	40 BRO	SP	CRE	ID	TD	9/24/2091
2020 PO4351701138	F	4	40 BRO	SP	CRE		V	9/25/2091
2020 PO4376801325	F	4	40 BRO	SP	CRE		V	9/26/2091
2020 PO4374101266	F	4	40 BRO	SP	CRE		V	9/27/2091
2020 PO4334001287	KU	6	30 BRO	SP	CRE	ID	TD	9/28/2091
2020 PO4351101314	KU	4	40 BRO	SP	CCA		V	9/29/2091
2020 PO4574602380	KU	4	40 BRO	SP	CRE	ID	TD	9/30/2091
2020 PO4574103093	KU	3	45 XXX	SP	CRE	ED,ID	TD	10/1/2091
2020 PO4475901462	KU	6	30 BRO	SP	CCA		V	10/2/2091
2020 PO4468701302	KU	6	30 BRO	SP	CRE	ID	TD	10/3/2091
2020 PO4467901384	KU	6	30 BRO	SP	CRE	ID	TD	10/4/2091
2020 PO4447401411	KU	5	30 BRO	SP	CRE	ID	TD	10/5/2091
2020 PO4429401429	KU	6	30 BRO	SP	CCA		V	10/6/2091
2020 PO4436301490	KU	4	40 BRO	SP	CRE	ID	TD	10/7/2091
2020 PO4466201523	KU	4	40 BRO	SP	CRE	ID	TD	10/8/2091
2020 PO4409601441	F	4	40 BRO	SP	CRE		V	10/9/2091
2020 PO4716204466	KU	5	35 BRN	SP	CCA		V	10/10/2091
2020 PO4712804453	KU	4	40 XXX	SP	CRE	ED,ID	TD	10/11/2091
2020 PO4597104102	KU	5	30 XXX	SP	CRE	ED,ID	TD	10/12/2091
2020 PO4608604078	KU	4	40 XXX	SP	CRE	ED,ID	TD	10/13/2091
2020 PO4626203976	KU	5	35 XXX	SP	CRE	ED,ID	TD	10/14/2091
2020 PO4695103871	KU	3	50 XXX	SP	CRE	ED,ID	TD	10/15/2091
2020 PO6711174811	F	5	35 BRN	SP	CRE		V	10/16/2091
2020 PO6671173615	KU	4	45 BRN	SP	CRE	ED,ID	TD	10/17/2091
2020 PO8289370241	KU	4	40 BRO	SP	CRE	ED,ID	BD	10/18/2091
2020 PO8304670339	KU	4	45 BRO	SP	CRE	ED,ID	BD	10/19/2091
2020 PO8311970386	KU	4	45 BRO	SP	CCA		V	10/20/2091
2020 PO4674204106	KU	6	30 KOP	SP	CCA		V	10/21/2091
2020 PO4688504056	KU	5	30 XXX	SP	CRE	ID	BD	10/22/2091
2020 PO4677404045	KU	6	30 XXX	SP	CRE	ED,ID	TD	10/23/2091
2020 PO4674803926	KU	6	30 XXX	SP	CRE	ED,ID	TD	10/24/2091
2020 PO4685503905	KU	5	30 XXX	SP	CRE	ED,ID	TD	10/25/2091
2020 PO4183502523	KU	4	40 XXX	SP	CRE		V	10/26/2091
2020 PO8225570733A	KU	4	35 BRO	SP	A	ED,ID	BD	10/27/2091
2020 PO5139099408	F	5 35E	XXX	SP	CRE	ED,ID	B	10/28/2091
2020 PO5150699703	KU	4	40 BRN	SP	CCA		V	10/29/2091
2020 PO5138299873	KU	4	40 BRN	SP	CCA		V	10/30/2091
2020 PO5134698986	F	5 35E	XXX	SP	CRE		V	10/31/2091
2020 PO5129398655	F	5 35E	KOP	SP	CRE		V	11/1/2091

2020 PO5122898321	F	5	35 KOP	SP	CRE		V		11/2/2091
2020 PO5135998040	KU	4	40 KOP	SP	CCA		V		11/3/2091
2020 PO5136298128	KU	6	30 BRN	SP	CCA		V		11/4/2091
2020 5061947940A	KU	5	35 BRN	SP	CCA		V		11/5/2091
2020 PO5029498338	F	5	35 XXX	SP	CRE		V		11/6/2091
2020 PO5026597861	F	4	40 XXX	SP	CRE		V		11/7/2091
2020 PO5018498001	KU	3	50 BRN	SP	CCA		V		11/8/2091
2020 PO5000898122	KU	6	30 KOP	SP	CCA		V		11/9/2091
2020 PO4996798066	KU	4	40 KOP	SP	CCA		V		11/10/2091
2020 PO4935198236	KU	6	30 KOP	SP	CCA		V		11/11/2091
2020 PO4902898309	KU	6	30 BRN	SP	CCA		V		11/12/2091
2020 PO4872197909	KU	7	30 BRN	SP	CCA		V		11/13/2091
2020 PO4871498163	F	6	30 BRN	SP	CRE		V		11/14/2091
2020 PO4865298362	F	3	40 BRN	SP	A		V		11/15/2091
2020 PO4861498174	KU	5	35 BRN	SP	CCA		V		11/16/2091
2020 PO4828498318	KU	4	40 KOP	SP	CCA		V		11/17/2091
2020 PO4846098281	KU	4	40 KOP	SP	CCA		V		11/18/2091
2020 PO4840598016	F	5	35 BRN	SP	CRE		V		11/19/2091
2020 PO4843398159	F	4	40 BRN	SP	CRE		V		11/20/2091
2020 4846098281A	KU	4	40 BRN	SP	CCA		V		11/21/2091
2020 PO4772199228	F	5	35E XXX	SP	CRE		V		11/22/2091
2020 PO4565501029	F	4	40 INP	SP	CRE		V		11/23/2091
2020 PO4592701079	F	5	30 OTH	SP	CCA		V		11/24/2091
2020 PO4587501015	F	6	30 OTH	SP	CRE		V		11/25/2091
2020 PO4580100890	F	6	25 INP	SP	CRE		V		11/26/2091
2020 PO4606900991	F	4	40E INP	SP	CRE		V		11/27/2091
2020 PO4616300815	F	4	40 INP	SP	CRE		V		11/28/2091
2020 PO4623300697	F	5	35E XXX	SP	CRE		V		11/29/2091
2020 PO0619462187	F	4	40 BRN	SP	P		V		11/30/2091
2020 PO0580062147	KU	4	40 BRN	SP	CRE	ID,IP	TD		12/1/2091
2020 PO0594062203	KU	5	30 BRN	SP	P	ED	TD		12/2/2091
2020 PO0620662075	KU	3	45 BRN	SP	CRE	ED,HH,ID	X	RP1	12/3/2091
2020 PO0655062818	KU	4	45 BRN	SP	CRE	ED,ID,IP,SRC	TD		12/4/2091
2020 PO0653362798	KU	3	45 BRN	SP	CCA		V		12/5/2091
2020 PO0648662741	KU	3	45 BRN	SP	CRE	ID	TD		12/6/2091
2020 PO0584162238	KU	6	30 BRN	SP	CRE	ID	TD		12/7/2091
2020 PO0588962116	KU	4	45 BRN	SP	CRE	ID	TD		12/8/2091
2020 PO0602762183	KU	6	30 BRN	SP	CRE	ID	TD		12/9/2091
2020 PO0596962080	KU	4	40 BRN	SP	CRE	ID,IP	TD		12/10/2091
2020 PO0602462050	KU	4	45 BRN	SP	CRE	ID	TD		12/11/2091
2020 PO6100162002	KU	2	50E BRN	SP	P	ID	BD		12/12/2091
2020 PO0611862009	F	3	45E BRN	SP	A		V		12/13/2091
2020 PO0602061814	KU	3	45E BRN	SP	P	ID	BD		12/14/2091
2020 PO0608061799	KU	2	50 BRN	SP	CCA		V		12/15/2091
2020 PO0595161636	F	4	40 BRN	SP	CRE		V		12/16/2091
2020 PO0472424497	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD		12/17/2091
2020 PO0472524054	KU	4	40 BRO	SP	CRE	ID	BD		12/18/2091

Business Use

2020 PO0465624651	KU	4	40 BRO	SP	CRE		V			12/19/2091
2020 PO0493924270	KU	4	40 BRO	SP	CRE	ED,ID	TD			12/20/2091
2020 PO7527183155	KU	4	40 BRN	SP	CRE	ED,HH,ID,RB	BX	PX		12/21/2091
2020 PO0612426579	KU	4	40 BRO	SP	CRE	ED,ID,IP,SRS	TD			12/22/2091
2020 PO0629326034	KU	4	40 BRO	SP	CRE		V			12/23/2091
2020 PO0645326504	KU	4	40 BRO	SP	CCA		V			12/24/2091
2020 PO0616226088	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD			12/25/2091
2020 PO9854285164	KU	2	60 BRO	SP	CRE	ED,ID,IP	TD			12/26/2091
2020 PO9759684981	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			12/27/2091
2020 PO9784484974	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD			12/28/2091
2020 PO9804984986	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD			12/29/2091
2020 PO9840584736	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD			12/30/2091
2020 PO9821484591	KU	5	35 BRO	SP	CRE	ED,ID,IP	TX	RR		12/31/2091
2020 PO9806984487	KU	5	35 BRO	SP	CRE	ID,IP	BD			1/1/2092
2020 PO9570981974	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			1/2/2092
2020 PO9583981945	KU	4	40 BRO	SP	CRE	ID	BD			1/3/2092
2020 PO9576782233	KU	5	35 BRO	SP	CRE	ID,IP	BD			1/4/2092
2020 PO9593282976	KU	5	35 BRO	SP	CRE	ID,IP	TD			1/5/2092
2020 PO9583682550	KU	4	40 BRO	SP	CCA		V			1/6/2092
2020 PO7489482757	F	4	40 BRN	SP	CRE		V			1/7/2092
2020 PO7494382667	F	4	40 BRN	SP	CRE		V			1/8/2092
2020 PO7498382570	F	4	40 BRN	SP	P		V			1/9/2092
2020 PO7502682488	F	4	40 BRN	SP	CRE		V			1/10/2092
2020 PO7515982254	F	4	40 BRN	SP	CRE		V			1/11/2092
2020 PO5099807390	KU	6	30 XXX	SP	CRE	ED,ID	TD			1/12/2092
2020 PO5090507331	F	4	40 XXX	SP	CCA		V			1/13/2092
2020 PO5079207278	KU	6	30 XXX	SP	CRE	ED,ID	TD			1/14/2092
2020 PO8063973108	KU	2	65 BRO	SP	CRE		V			1/15/2092
2020 PO8088773259A	KU	5	35 BRO	SP	P	ED,ID	TD			1/16/2092
2020 PO8088773259	KU	6	35 BRO	SP	CRE	ED,ID	TD			1/17/2092
2020 PO8058073020	KU	5	35 BRO	SP	CRE	ED,ID	TD			1/18/2092
2020 PO7539781818	F	4	40 BRN	SP	CRE		V			1/19/2092
2020 PO7546881758	F	4	45 BRN	SP	CCA		V			1/20/2092
2020 PO7545081728	F	4	45 BRN	SP	CCA		V			1/21/2092
2020 PO9598383218	KU	5	35 BRO	SP	CRE	ED	TD			1/22/2092
2020 PO8223073632	KU	4	40 BRO	SP	CRE	ED,ID	VX	RP1		1/23/2092
2020 PO9623382893	KU	4	40 BRO	SP	CRE	ED	TD			1/24/2092
2020 PO9632383016	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD			1/25/2092
2020 PO9648882446	KU	4	40 BRO	SP	CCA		V			1/26/2092
2020 PO9635682512	KU	4	40 BRO	SP	CCA		V			1/27/2092
2020 PO3956882761	LGE	4	60 BRN	SP	CRE		V			1/28/2092
2020 PO3956682761	LGE	4	35 BRN	SP	CCA		V			1/29/2092
2020 PO9611240409	ODP	4	40 BRN	SP	CRE		V			1/30/2092
2020 PO2389926869	ODP	4	40 BRN	SP	CRE	ID	TD			1/31/2092
2020 PO2388827062	ODP	4	40 BRN	SP	CRE		V			2/1/2092
2020 PO5796906304	F	2	50 MAR	SP	P		V			2/2/2092
2020 PO5774106357	KU	6	30 BRN	SP	CCA		V			2/3/2092

2020 PO5780506331	F	3	45 MAR	SP	P		V	2/4/2092	
2020 PO5836306235	F	5	30 KOP	SP	CRE		V	2/5/2092	
2020 PO5754606378	KU	3	50 KOP	SP	CRE	ED,ID	TD	2/6/2092	
2020 PO5768506362	KU	4	40 XXX	SP	CCA		V	2/7/2092	
2020 PO5770006420	F	3	40 XXX	SP	P		V	2/8/2092	
2020 5796906304A	KU	5	30 ACW	SP	CRE	ED,ID	TD	2/9/2092	
2020 PO5830006172	KU	4	40 XXX	SP	CRE	ED,ID	TD	2/10/2092	
2020 PO5824706072	KU	5	30 XXX	SP	CRE	ED,ID	TD	2/11/2092	
2020 PO3945581898	LGE	4	35 BRN	SP	CRE	ED,ID,RB	TX	RR	2/12/2092
2020 PV3945781908	LGE	4	40 BRN	SP	CCA		V	2/13/2092	
2020 PO3946581928	LGE	4	40 BRN	SP	CCA		V	2/14/2092	
2020 PO3945981930	LGE	4	35 BRN	SP	A	ED,ID	TD	2/15/2092	
2020 PO3945881921	LGE	4	35 BRN	SP	CCA		V	2/16/2092	
2020 PO3947681863	LGE	4	35 BRN	SP	CRE	ED,ID	TD	2/17/2092	
2020 PO3948281873	LGE	4	35 BRN	SP	CRE	ED,ID	TD	2/18/2092	
2020 PO1321934246	ODP	5	35 BRN	SP	CCA		V	2/19/2092	
2020 PO3911082474	F	4	30 BRO	SP	CCA		V	2/20/2092	
2020 PO3909382474	F	4	45 BRO	SP	A		V	2/21/2092	
2020 PO3907982483	F	4	40 BRO	SP	CRE		V	2/22/2092	
2020 PO3909482479	F	4	30 BRO	SP	CCA		V	2/23/2092	
2020 PO3908082489	F	4	30 BRO	SP	CRE		V	2/24/2092	
2020 PO3907382493	F	4	30 BRO	SP	CCA		V	2/25/2092	
2020 PO3906182501	F	4	40 BRO	SP	A		V	2/26/2092	
2020 PO3904782510	F	4	30 BRO	SP	CCA		V	2/27/2092	
2020 PO3905382500	F	4	40 BRO	SP	CRE		V	2/28/2092	
2020 PO3906482492	F	4	40 BRO	SP	CCA		V	2/29/2092	
2020 PO3904482506	F	3	45 BRO	SP	CRE		V	3/1/2092	
2020 PO5794205907	KU	6	30 BRN	SP	CRE	ED,ID	TD	3/2/2092	
2020 PO1746240542	ODP	6	30 UNK	SP	CRE	ID	BD	3/3/2092	
2020 PO5859446910	F	3	40 ACE	SP	CRE	ED,HH,ID,RB	VX	PX	3/4/2092
2020 PO5727306908	KU	3	40 BRN	SP	CRE	ID	BD	3/5/2092	
2020 PO5731906861	KU	6	30 BRN	SP	CRE	ED,ID	TD	3/6/2092	
2020 PO5727806766	KU	6	30 BRN	SP	CCA		V	3/7/2092	
2020 PO5724806768	KU	6	30 BRN	SP	CCA		V	3/8/2092	
2020 PO7182391213	KU	4	40 BRN	SP	CRE	ED,ID	BD	3/9/2092	
2020 PO7191691479	KU	4	45 BRN	SP	CRE	ED,ID	BD	3/10/2092	
2020 PO7186291248	KU	4	40 BRN	SP	CCA		V	3/11/2092	
2020 PO7169891036	KU	4	45 BRN	SP	CCA	HH,ID	V	3/12/2092	
2020 PO7176791132	KU	4	45 BRN	SP	CRE	ED,ID	TD	3/13/2092	
2020 PO5736506742	KU	6	30 XXX	SP	CRE	ED,ID	TD	3/14/2092	
2020 PO5731706707	KU	3	45 XXX	SP	CCA		V	3/15/2092	
2020 PO7385393338	KU	4	35 BRO	SP	CRE	ID	BD	3/16/2092	
2020 PO7323994227	KU	4	40 BRO	SP	CCA		V	3/17/2092	
2020 PO5739206620	KU	5	35 XXX	SP	CRE	ED,ID	TD	3/18/2092	
2020 PO7161690915	KU	3	50 BRN	SP	CRE	ED,ID	BD	3/19/2092	
2020 PO7155390824	KU	4	45 BRN	SP	CRE	ED,ID	TD	3/20/2092	
2020 PO7149190737	KU	4	45 BRN	SP	CRE	ED,ID	BD	3/21/2092	

2020 PO7146190694	KU	4	45 BRN	SP	CRE	ED,ID	TD	3/22/2092
2020 PO7139390595	KU	3	45 BRN	SP	CCA		V	3/23/2092
2020 PO5745006586	KU	5	35 XXX	SP	CRE	ED,ID	TD	3/24/2092
2020 PO7132490499	KU	4	45 BRN	SP	CRE	ED,ID	BD	3/25/2092
2020 PO7126990419	KU	4	45 BRN	SP	CRE	ED,ID	BD	3/26/2092
2020 PO7119590313	KU	4	45 BRN	SP	CRE	ED,ID	TD	3/27/2092
2020 PO7108090275	KU	6	30 BRN	SP	CRE	ED,ID	BD	3/28/2092
2020 PO7114090234	KU	4	45 BRN	SP	CCA		V	3/29/2092
2020 PO7111690051	KU	4	40 BRN	SP	CRE	ED,ID	TD	3/30/2092
2020 PO7422893643	KU	4	40 BRO	SP	CRE	ID	BD	3/31/2092
2020 PO5653106879	KU	6	30 XXX	SP	CRE	ED,ID	TD	4/1/2092
2020 PO5647806776	KU	4	40 XXX	SP	CRE	ED,ID	TD	4/2/2092
2020 PO7449093762	KU	4	35 BRO	SP	CCA		V	4/3/2092
2020 PO7491093884	KU	4	45 BRO	SP	CRE	ID	BD	4/4/2092
2020 PO5596306698	KU	4	40 XXX	SP	CRE	ID	BD	4/5/2092
2020 PO5601006703	KU	4	40 XXX	SP	CRE	ED,ID	TD	4/6/2092
2020 PO5596906740	KU	6	30 XXX	SP	CRE	ED,ID	TD	4/7/2092
2020 PO5557106645	KU	4	45 KOP	SP	CRE		V	4/8/2092
2020 PO5581306676	KU	4	45 BRN	SP	CCA		V	4/9/2092
2020 PO7520694111	KU	4	40 BRO	SP	CRE	ID	BD	4/10/2092
2020 PO7397694971	KU	4	40 BRO	SP	CRE	ED,ID	TD	4/11/2092
2020 PO7403594982	KU	4	40 BRO	SP	CRE	ED,ID	TD	4/12/2092
2020 PO7104590099	KU	3	50 BRN	SP	CRE	ED,ID	BD	4/13/2092
2020 PO5574306935	KU	4	40 BRN	SP	CRE	ED,ID	TD	4/14/2092
2020 PO5388506480	KU	6	30 XXX	SP	CRE		V	4/15/2092
2020 PO1747740364	ODP	6	30 UNK	SP	CRE	ED,ID,SRS	TD	4/16/2092
2020 PO1857341046	ODP	5	35 KOP	SP	S		V	4/17/2092
2020 PO1870741064	ODP	5	35 KOP	SP	CRE	ED,ID	TD	4/18/2092
2020 PO3875682659	LGE	2	45 BRO	SP	P		V	4/19/2092
2020 PO3875882646	LGE	2	65 BRO	SP	CRE		V	4/20/2092
2020 PO3876082629	LGE	4	30 BRO	SP	P	ED,ID	TD	4/21/2092
2020 PO3875282624	LGE	2	65 BRO	SP	CRE		V	4/22/2092
2020 PO3874982605	LGE	2	65 BRO	SP	CRE		V	4/23/2092
2020 PO3875082598	LGE	4	30 BRO	SP	P	ED,ID	TD	4/24/2092
2020 PO3874382583	LGE	2	65 BRO	SP	CRE		V	4/25/2092
2020 PO3875082580	LGE	4	30 BRO	SP	P	ED	T	4/26/2092
2020 PO3873882557	LGE	2	65 BRO	SP	CRE		V	4/27/2092
2020 PO3874482557	LGE	4	30 BRO	SP	P	ED,ID	TD	4/28/2092
2020 PO3872582538A	LGE	5	30 BRO	SP	S		V	4/29/2092
2020 PO3872582538	LGE	4	30 BRO	SP	P	ED,ID	TD	4/30/2092
2020 PO3873682534	LGE	4	35 BRO	SP	CCA		V	5/1/2092
2020 PO3873282534	LGE	2	65 BRO	SP	CRE		V	5/2/2092
2020 PO7245791931	KU	4	45 BRN	SP	CRE	ED,ID	TD	5/3/2092
2020 PO1730939730	ODP	4	45 BRN	SP	CCA		V	5/4/2092
2020 PO1729139665	ODP	4	45 BRN	SP	CCA		V	5/5/2092
2020 PO3994082760	F	4	45 BRN	SP	CRE		V	5/6/2092
2020 PO3993582752	F	4	30 BRN	SP	A		V	5/7/2092

2020 PO3993382739	LGE	4	30 BRN	SP	CRE	ED,ID	TD	5/8/2092	
2020 PO3992382760	F	4	40 BRN	SP	CRE		V	5/9/2092	
2020 PO3918582948	F	4	40 BRO	SP	P		V	5/10/2092	
2020 PO7239391788	KU	4	40 BRN	SP	CRE	ED,ID	BD	5/11/2092	
2020 PO7234891847	KU	3	50 BRN	SP	CRE	ED,ID	BD	5/12/2092	
2020 PO7221691746	KU	3	50 BRN	SP	CRE	ED,ID	TD	5/13/2092	
2020 PO7211791670	KU	3	50 BRN	SP	CCA		V	5/14/2092	
2020 PO7201491592	F	2	50 BRN	SP	CRE		V	5/15/2092	
2020 PO7186191401	KU	4	45 BRN	SP	CCA		V	5/16/2092	
2020 PO6173905057	F	6	30 ACW	SP	CRE		V	5/17/2092	
2020 PO7168491372	KU	4	45 BRN	SP	CRE	ED,ID	TD	5/18/2092	
2020 PO7415591534	KU	4	40 BRO	SP	CRE	RB,SRC	X	RR	5/19/2092
2020 PO6193605027	KU	6	30 ACW	SP	CRE	ID	BD	5/20/2092	
2020 PO6198405093	KU	6	30 ACW	SP	CRE	ED,ID	TD	5/21/2092	
2020 PO7638479069	KU	2	55 BRO	SP	CRE	ID	BD	5/22/2092	
2020 PO6197305447	KU	4	45 XXX	SP	CRE	ED,ID,IP	TD	5/23/2092	
2020 PO6190405586	KU	6	30 BRN	SP	CCA		V	5/24/2092	
2020 PO6188205327	KU	6	30 BRN	SP	CCA		V	5/25/2092	
2020 PO6189305385	KU	6	30 BRN	SP	CCA		V	5/26/2092	
2020 PO7441291857	KU	4	40 BRO	SP	CRE	ED,ID	TD	5/27/2092	
2020 PO6692813745	KU	5	35 XXX	SP	CRE	ID	TD	5/28/2092	
2020 PO6677813704	KU	5	35 XXX	SP	CRE	ID	BD	5/29/2092	
2020 PO7092490177	KU	5	35 BRN	SP	CCA		V	5/30/2092	
2020 PO7041990574	F	4	40 BRN	SP	CRE	ED,ID	V	5/31/2092	
2020 PO6508813551	KU	5	35 XXX	SP	CRE	ID	TD	6/1/2092	
2020 PO6552813393	KU	4	40 XXX	SP	CRE	ID	BD	6/2/2092	
2020 PO6527813562	KU	6	30 XXX	SP	CCA		V	6/3/2092	
2020 PO6529213461	KU	5	35 XXX	SP	CRE	ID	TD	6/4/2092	
2020 PO6483713657	KU	5	35 XXX	SP	CRE	ID	TD	6/5/2092	
2020 PO6462613747	KU	5	35 XXX	SP	CRE	ID	TD	6/6/2092	
2020 PO6452413641	KU	5	35 XXX	SP	CRE	ID	TD	6/7/2092	
2020 PO6424713394	KU	4	40 XXX	SP	CRE	ID	TD	6/8/2092	
2020 PO6397613271	F	4	40 XXX	SP	A		V	6/9/2092	
2020 PO6387813396	KU	5	35 XXX	SP	CRE	ID	BD	6/10/2092	
2020 PO6403513209	KU	4	40 XXX	SP	CRE	ID	TD	6/11/2092	
2020 PO6381413029	KU	5	35 XXX	SP	CRE	ID	BD	6/12/2092	
2020 PO6280912116	KU	5	35 XXX	SP	CRE		V	6/13/2092	
2020 PO6363713370	KU	6	30 XXX	SP	CCA		V	6/14/2092	
2020 PO7081397083	KU	4	40 BRN	SP	CRE	ED,ID	TD	6/15/2092	
2020 PO5681210193	KU	6	30 BRO	SP	CRE	ID	TD	6/16/2092	
2020 PO5676610260	KU	3	45 BRO	SP	CCA		V	6/17/2092	
2020 PO5655710185	KU	3	45 BRO	SP	CCA		V	6/18/2092	
2020 PO5639810128	KU	3	45 BRO	SP	CCA		V	6/19/2092	
2020 PO5625510079	KU	3	45 BRO	SP	CCA		V	6/20/2092	
2020 PO5626510183	KU	5	30 BRO	SP	CRE	ID	TD	6/21/2092	
2020 PO5634910218	KU	6	30 BRO	SP	CCA		V	6/22/2092	
2020 PO5748110746a	KU	4	40 BRO	SP	CCA		V	6/23/2092	

2020 PO5748110746	KU	5	35 BRO	SP	CRE	ID	TD	6/24/2092
2020 PO5742410929	KU	6	30 BRO	SP	CRE	ID	TD	6/25/2092
2020 PO5729210923	KU	6	30 BRO	SP	CRE		V	6/26/2092
2020 PO5743910698	KU	5	30 BRO	SP	CRE		V	6/27/2092
2020 PO5730910718	KU	5	35 BRO	SP	CRE	ID	TD	6/28/2092
2020 PO5722710763	F	4	40 BRO	SP	CCA		V	6/29/2092
2020 PO5715110688	KU	4	40 BRO	SP	CRE	ID	TD	6/30/2092
2020 PO5714810615	KU	6	30 BRO	SP	CRE		V	7/1/2092
2020 PO5695010740	KU	6	30 BRO	SP	CCA		V	7/2/2092
2020 PO5696910646	KU	4	40 BRO	SP	CRE	ID	TD	7/3/2092
2020 PO5699410551	KU	5	30 BRO	SP	CRE	ID	TD	7/4/2092
2020 PO7056590151	KU	6	30 BRN	SP	CRE	ED,ID	BD	7/5/2092
2020 PO5681410605	KU	5	35 BRO	SP	CRE	ID	BD	7/6/2092
2020 PO7055290130	KU	5	35 BRN	SP	CRE	ED,ID	TD	7/7/2092
2020 PO5675010519	KU	6	30 BRO	SP	CRE	ID	TD	7/8/2092
2020 PO5664310554a	KU	5	35 BRO	SP	CCA		V	7/9/2092
2020 PO5658610701	KU	4	40 BRO	SP	CRE	ID	TD	7/10/2092
2020 PO5663110617	F	5 35E	BRO	SP	A		V	7/11/2092
2020 PO5664310554	KU	4	40 BRO	SP	CCA		V	7/12/2092
2020 PO5652810578	KU	6	30 BRO	SP	CRE	ID	TD	7/13/2092
2020 PO5654010514	KU	5	35 BRO	SP	CRE	ID	TD	7/14/2092
2020 PO5627610361	KU	5	30 BRO	SP	CRE	ID	TD	7/15/2092
2020 PO5642710485	KU	4	40 BRO	SP	CRE	ID	TD	7/16/2092
2020 PO5639710575	F	5	35 BRO	SP	A		V	7/17/2092
2020 PO5626410435	KU	5	35 BRO	SP	CRE	ID	BD	7/18/2092
2020 PO5626410288	KU	5	30 BRO	SP	CRE	ID	TD	7/19/2092
2020 PO5611810390	KU	4	40 BRO	SP	CRE	ID	TD	7/20/2092
2020 PO5610210450	F	5	35 BRO	SP	CRE		V	7/21/2092
2020 PO5568110335	KU	5	35 BRO	SP	CRE	ID	TD	7/22/2092
2020 PO5559410391	KU	6	30 BRO	SP	CRE	ID	TD	7/23/2092
2020 PO5554910254	KU	5	35 BRO	SP	CCA		V	7/24/2092
2020 PO7643879331	KU	2	60 BRO	SP	CRE	ID	BD	7/25/2092
2020 PO7630779294	KU	5	35 BRO	SP	CRE	ID	BD	7/26/2092
2020 PO7623479274	KU	2	45 BRO	SP	CRE	ED,ID	TD	7/27/2092
2020 PO7613479233	KU	4	45 BRO	SP	P	ID	BD	7/28/2092
2020 PO7022590518	KU	4	40 BRN	SP	P	ED,ID	BD	7/29/2092
2020 PO7027490220	KU	6	30 BRN	SP	CRE	ED,ID	BD	7/30/2092
2020 PO7004390249	KU	6	30 BRN	SP	CRE	ED,ID	TD	7/31/2092
2020 PO6241904619	KU	6	30 ACW	SP	CRE	ED,ID	TD	8/1/2092
2020 PO6238804739	KU	6	35 ACW	SP	CRE	ID	BD	8/2/2092
2020 PO6229404746	KU	5	35 ACW	SP	CRE	ED,ID	TD	8/3/2092
2020 PO6217704667	KU	6	30 KOP	SP	CRE	ED,ID	TD	8/4/2092
2020 PO6209904731	KU	4	40 KOP	SP	CRE	ED,ID	TD	8/5/2092
2020 PO6208104668	KU	4	40 XXX	SP	CRE	ED,ID	TD	8/6/2092
2020 PO6207104628	KU	3	45 BRO	SP	CCA		V	8/7/2092
2020 PO6193804655	KU	3	45 BRO	SP	CCA		V	8/8/2092
2020 PO6182804676	KU	3	45 BRO	SP	CCA		V	8/9/2092

2020 PO6173004697	F	3	45 BRO	SP	CCA		V		8/10/2092
2020 PO6225204852	F	6	30 BRO	SP	CRE		V		8/11/2092
2020 PO6213604826	F	4	40 BRO	SP	CRE		V		8/12/2092
2020 PO6197604795	F	4	40 BRO	SP	CRE		V		8/13/2092
2020 PO6183404803	F	4	40 BRO	SP	CRE		V		8/14/2092
2020 PO6993390221	KU	6	30 BRN	SP	CRE	ED,ID	BD		8/15/2092
2020 PO6998990299	KU	6	30 BRN	SP	CRE	ED,ID	BD		8/16/2092
2020 PO7319792724	KU	2	60 BRN	SP	CRE		V		8/17/2092
2020 PO7077994352	KU	4	40 BRN	SP	CRE	ED,ID	BD		8/18/2092
2020 PO7506694847	KU	4	45 BRO	SP	CRE	ED,ID,RB	VX	RP1	8/19/2092
2020 PO7323192769	KU	4	40 BRN	SP	CRE		V		8/20/2092
2020 PO7355293194	KU	1	80 BRN	SP	CRE		V		8/21/2092
2020 PO7339993376	KU	2	70 BRN	SP	CRE		V		8/22/2092
2020 PO7325293551	KU	2	70 BRN	AL	CRE		V		8/23/2092
2020 PO7312293709	KU	2	70 BRN	SP	CRE		V		8/24/2092
2020 PO7288893607	KU	2	70 BRN	SP	CRE		V		8/25/2092
2020 PO7263693472	KU	4	40 BRN	SP	CCA		V		8/26/2092
2020 PO7263593497	KU	2	70 BRN	SP	CRE		V		8/27/2092
2020 PO7349691393	F	5	30 BRO	SP	CCA		V		8/28/2092
2020 PO7477394627	KU	4	40 BRO	SP	CRE	ID	BD		8/29/2092
2020 PO7439694598	KU	4	40 BRO	SP	CRE	ED,MD	VX	RP2	8/30/2092
2020 PO7492294759	KU	4	45 BRO	SP	CRE	ID,RB	VX	RP1	8/31/2092
2020 PO7546594966	KU	4	45 BRO	SP	CRE	ED,ID	TD		9/1/2092
2020 PO7525794914	KU	3	45 BRO	SP	CCA		V		9/2/2092
2020 PO7294491055	F	3	45 BRO	SP	CRE	ED,ID	VX	PX	9/3/2092
2020 PO7339091276	F	5	35 BRO	SP	CRE		V		9/4/2092
2020 PO7319391199	F	3	40 BRO	SP	CRE		V		9/5/2092
2020 PO7326291271	F	4	40 BRO	SP	CRE		V		9/6/2092
2020 PO6136704920	KU	3	45 BRO	SP	CRE		V		9/7/2092
2020 6144405100a	KU	4	40 XXX	SP	CRE	ED,ID	TD		9/8/2092
2020 PO6144405100	F	3	45 BRO	SP	CCA		V		9/9/2092
2020 PO6143604883	KU	6	30 BRN	SP	CCA		V		9/10/2092
2020 PO6138905072	KU	2	40 XXX	SP	CRE	ED,ID	TD		9/11/2092
2020 PO6136705082	KU	2	40 XXX	SP	CRE	ED,ID	TD		9/12/2092
2020 PO7208192152	KU	5	35 BRN	SP	CCA		V		9/13/2092
2020 PO7221392007	KU	4	45 BRN	SP	CRE		V		9/14/2092
2020 PO7209692167	KU	5	35 BRN	SP	CCA		V		9/15/2092
2020 PO7201992113	KU	5	35 BRN	SP	CCA		V		9/16/2092
2020 PO4979705340	KU	3	50 BRN	SP	CCA		V		9/17/2092
2020 PO7257092031	KU	4	45 BRN	SP	CCA		V		9/18/2092
2020 PO7259992483	KU	4	45 BRN	SP	CCA		V		9/19/2092
2020 PO7261492464	KU	4	45 BRN	SP	CCA		V		9/20/2092
2020 PO7270292342	KU	4	45 BRN	SP	CCA		V		9/21/2092
2020 PO7279392223	KU	4	45 BRN	SP	CCA		V		9/22/2092
2020 PO7280992204	KU	4	45 BRN	SP	CCA		V		9/23/2092
2020 PO7286592245	KU	3	45 BRN	SP	CCA		V		9/24/2092
2020 PO7315392466	KU	4	40 BRN	SP	CRE	ED,ID	BD		9/25/2092

2020 PO7302691253	KU	6	30 BRO	SP	CRE	ED,ID	TD	9/26/2092
2020 PO7297391238	KU	5	35 BRO	SP	CCA		V	9/27/2092
2020 PO7311091184	KU	5	35 BRO	SP	CCA		V	9/28/2092
2020 PO7240093396	KU	2	70 BRN	SP	CRE		V	9/29/2092
2020 PO7452195106	KU	4	40 BRO	SP	CRE		V	9/30/2092
2020 PO7463695106	KU	4	45 BRO	SP	CRE	ID	BD	10/1/2092
2020 PO7453195100	KU	4	40 BRO	SP	CCA		B	10/2/2092
2020 PO7206993982	KU	1	85 BRN	SP	CRE		V	10/3/2092
2020 PO7225993597	KU	2	70 BRN	SP	CRE		V	10/4/2092
2020 PO7230693399	KU	6	30 BRN	SP	CCA		V	10/5/2092
2020 PO7226993332	KU	4	45 BRN	SP	CCA		V	10/6/2092
2020 PO4017083017	LGE	4	35 BRN	SP	CCA		V	10/7/2092
2020 PO4017183016	LGE	4	35 BRN	SP	A	ED,ID	BD	10/8/2092
2020 PO3772409260	KU	3	45 BRO	SP	CRE	ID,IP	BD	10/9/2092
2020 PO4400501027	KU	4	40 KOP	SP	CRE	ID	BD	10/10/2092
2020 PO4015382951	F	4	30 BRN	SP	CCA		V	10/11/2092
2020 PO4012182879	F	4	40 BRN	SP	CCA		V	10/12/2092
2020 PO4013082893	F	4	40 BRN	SP	CCA		V	10/13/2092
2020 PO4015382851	LGE	3	45 BRN	SP	CCA		V	10/14/2092
2020 PO4013982909	F	4	40 BRN	SP	CCA		V	10/15/2092
2020 PO4014782922	F	4	40 BRN	SP	CCA		V	10/16/2092
2020 PO4018882987	F	4	40 BRN	SP	CCA		V	10/17/2092
2020 PO4018082973	F	4	40 BRN	SP	CCA		V	10/18/2092
2020 PO4017082958	F	4	40 BRN	SP	CCA		V	10/19/2092
2020 PO4016182944	F	4	40 BRN	SP	CCA		V	10/20/2092
2020 PO4015382880	F	4	30 BRN	SP	CCA		V	10/21/2092
2020 PO4014882883	F	3	45 BRN	SP	CCA		V	10/22/2092
2020 PO4016682898	F	4	30 BRN	SP	CCA		V	10/23/2092
2020 PO4015982902	F	3	45 BRN	SP	CCA		V	10/24/2092
2020 PO4021582979	F	4	30 BRN	SP	CCA		V	10/25/2092
2020 PO4020482963	F	4	30 BRN	SP	CCA		V	10/26/2092
2020 PO4019382946	F	4	30 BRN	SP	CCA		V	10/27/2092
2020 PO4018482930	F	4	30 BRN	SP	CCA		V	10/28/2092
2020 PO4020982983	F	4	40 BRN	SP	CCA		V	10/29/2092
2020 PO4019982966	F	4	40 BRN	SP	CCA		V	10/30/2092
2020 PO4018882949	F	3	45 BRN	SP	CCA		V	10/31/2092
2020 PO4017882933	F	4	40 BRN	SP	CCA		V	11/1/2092
2020 PO4010782944	LGE	3	40 BRN	SP	P	ED,ID	TD	11/2/2092
2020 PO4018382911	LGE	4	30 BRN	SP	CCA		V	11/3/2092
2020 PO4017082920	F	4	40 BRN	SP	CCA		V	11/4/2092
2020 PO4017382925	F	4	40 BRN	SP	CCA		V	11/5/2092
2020 PO4031283018	F	2	60 BRN	SP	CCA		V	11/6/2092
2020 PO4032183034	F	2	55 BRN	SP	CCA		V	11/7/2092
2020 PO3782609146	KU	4	40 BRO	SP	CRE	ID,IP	BD	11/8/2092
2020 PO2075123727	ODP	5	35 XXX	SP	CRE	ID	TD	11/9/2092
2020 PO2120023837	ODP	5	35 XXX	SP	CRE	ID	TD	11/10/2092
2020 PO2156323917	ODP	5	35 XXX	SP	CRE	ED,ID	TD	11/11/2092

2020 PO4410300904	KU	4	40 KOP	SP	CRE	ED,ID	TD	11/12/2092
2020 PO4443500524	KU	4	40 KOP	SP	CRE	ED,ID	TD	11/13/2092
2020 PO3794909009	KU	3	45 BRO	SP	CRE	ID	BD	11/14/2092
2020 PO4712188888	F	3	45 BRO	SP	CRE		V	11/15/2092
2020 PO4712488890	F	3	45 BRO	SP	CRE		V	11/16/2092
2020 PO4713188894	F	3	45 BRO	SP	CRE		V	11/17/2092
2020 PO4713888899	F	3	45 BRO	SP	CCA		V	11/18/2092
2020 PO4714988906	F	3	45 BRO	SP	CCA		V	11/19/2092
2020 PO4714688932	F	4	40E BRO	SP	CRE		V	11/20/2092
2020 PO4713688948	F	4	40E BRO	SP	CRE		V	11/21/2092
2020 PO4030983021	F	4	30 BRN	SP	CCA		V	11/22/2092
2020 PO5168008944	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	11/23/2092
2020 PO2178024400	ODP	5	35 XXX	SP	CRE	ID	TD	11/24/2092
2020 PO2197024402	ODP	4	45 XXX	SP	CCA	ED	T	11/25/2092
2020 PO2201424449	ODP	5	30 XXX	SP	CCA		V	11/26/2092
2020 PO2206624489	ODP	6	30 XXX	SP	CCA	ED	T	11/27/2092
2020 PO2029824271	ODP	4	40 XXX	SP	CRE	ID	TD	11/28/2092
2020 PO4422700686	F	4	40 KOP	SP	CCA		V	11/29/2092
2020 PO4434100571	F	4	40 KOP	SP	P		V	11/30/2092
2020 PO4457400454	KU	4	40 BRN	SP	CCA		V	12/1/2092
2020 PO3719609108	KU	4	40 BRO	SP	CRE	ID,IP	BD	12/2/2092
2020 PO3846308056	KU	4	40 BRO	SP	P	ED	T	12/3/2092
2020 PO3868408166	KU	4	40 BRO	SP	P	ED	T	12/4/2092
2020 PO4051683081	F	3	45 BRN	SP	CCA		V	12/5/2092
2020 PO4053583079	F	4	40 BRN	SP	CCA		V	12/6/2092
2020 PO4054983078	F	4	40 BRN	SP	CCA		V	12/7/2092
2020 PO4046683086	LGE	5	25 BRN	SP	CCA		V	12/8/2092
2020 PO4056483076	F	4	40 BRN	SP	CCA		V	12/9/2092
2020 PO4057983075	F	4	40 BRN	SP	CCA		V	12/10/2092
2020 PO1962023376	ODP	4	40 XXX	SP	CRE	ID	TD	12/11/2092
2020 PO1988722968	ODP	4	40 XXX	SP	CRE	ID	TD	12/12/2092
2020 PO1936723006	ODP	5	35 XXX	SP	CRE	ID	BD	12/13/2092
2020 PO1843822058	ODP	5	35 XXX	SP	CRE		V	12/14/2092
2020 PO1855922052	ODP	6	30 XXX	SP	CRE	ID	TD	12/15/2092
2020 PO1882422147	ODP	4	40 XXX	SP	CCA	ED	T	12/16/2092
2020 PO1810821977	ODP	4	40 XXX	SP	CRE	ID	BD	12/17/2092
2020 PO1839321819	ODP	4	40 XXX	SP	CRE	ID	TD	12/18/2092
2020 PO1835621942	ODP	4	40 XXX	SP	CRE	ID	TD	12/19/2092
2020 PO1857422030	ODP	4	40 XXX	SP	CCA		V	12/20/2092
2020 PO1880021294	ODP	4	40 XXX	SP	CCA		V	12/21/2092
2020 PO2213021754	ODP	4	45 XXX	SP	CCA		V	12/22/2092
2020 PO4054983069	F	4	30 BRN	SP	A		V	12/23/2092
2020 PO4056383068	F	4	30 BRN	SP	A		V	12/24/2092
2020 PO4058283066	F	4	30 BRN	SP	A		V	12/25/2092
2020 PO4060283062	F	4	30 BRN	SP	CCA		V	12/26/2092
2020 PO4060283069	F	3	45 BRN	SP	P		V	12/27/2092
2020 PO4059383074	F	4	40 BRN	SP	CCA		V	12/28/2092

2020 PO4062283063	F	4	30 BRN	SP	CCA		V	12/29/2092
2020 PO4062083071	F	4	40 BRN	SP	CCA		V	12/30/2092
2020 PO4062283075	LGE	4	25 BRN	SP	CCA		V	12/31/2092
2020 PO4060183106	LGE	4	40 BRN	SP	CCA		V	1/1/2093
2020 PO4063583074	F	4	40 BRN	SP	CRE		V	1/2/2093
2020 PO4063483081	F	4	30 BRN	SP	CCA		V	1/3/2093
2020 PO4065183080	F	4	40 BRN	SP	CCA		V	1/4/2093
2020 PO4066383074	LGE	4	30 BRN	SP	CCA		V	1/5/2093
2020 PO4065183091	LGE	4	40 BRN	SP	P	ED,ID	BD	1/6/2093
2020 PO4066883085	F	3	50 BRN	SP	CCA		V	1/7/2093
2020 PO4067883088	F	4	40 BRN	SP	CCA		V	1/8/2093
2020 PO4618005984	KU	4	40 BRO	SP	CCA		V	1/9/2093
2020 PO4622205896	KU	4	45 BRO	SP	CRE		V	1/10/2093
2020 PO4594405065	KU	4	40 BRO	SP	CRE		V	1/11/2093
2020 PO6371647303	F	4	40 ACE	SP	CRE		V	1/12/2093
2020 PO0839993018	KU	3	40 ACW	SP	S		V	1/13/2093
2020 PO0831392975	KU	3	45 ACW	ST	S		V	1/14/2093
2020 PO5641645754	KU	6	30 ACE	SP	CRE	ED,ID	BD	1/15/2093
2020 PO0868493168	KU	3	45 ACW	SP	S		V	1/16/2093
2020 PO0906993362	KU	3	45 ACW	SP	CRE	ED,ID	TD	1/17/2093
2020 PO0934293513	KU	4	40 ACW	SP	S		V	1/18/2093
2020 PO5717746396	KU	5	35 ACE	SP	CCA		V	1/19/2093
2020 PO4638005286	KU	3	45 BRO	SP	CCA		V	1/20/2093
2020 PO4613705161	KU	4	40 BRO	SP	CCA		V	1/21/2093
2020 PO4622605850	KU	3	45 BRO	SP	CCA		V	1/22/2093
2020 PO4620905443	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	1/23/2093
2020 PO5773055637a	KU	4	40 ACE	SP	CRE	ED,ID	BD	1/24/2093
2020 PO5773055637	KU	5	45 ACE	SP	CRE	ED,ID	BD	1/25/2093
2020 PO4608605474	KU	4	40 BRO	SP	CCA		V	1/26/2093
2020 PO4594705517	KU	4	45 BRO	SP	CCA		V	1/27/2093
2020 PO0988293783	KU	3	45 ACW	SP	S		V	1/28/2093
2020 PO0975193716	KU	4	40 ACW	SP	S		V	1/29/2093
2020 PO0974793366	KU	4	40 ACW	SP	CRE		V	1/30/2093
2020 PO0974393016	KU	4	40 ACW	SP	S		V	1/31/2093
2020 PO5793155562	KU	3	45 ACE	SP	CRE	ED,ID,IP	BD	2/1/2093
2020 PO4564904953	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	2/2/2093
2020 PO5808355502	KU	3	45 ACE	SP	CRE	ED,ID	BD	2/3/2093
2020 PO4572204972	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD	2/4/2093
2020 PO4581405000	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD	2/5/2093
2020 PO5819655453	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	2/6/2093
2020 PO0502693161	KU	4	40 ACW	SP	CRE	ED,ID,IP	BD	2/7/2093
2020 PO0486392821	KU	3	45 ACW	SP	S		V	2/8/2093
2020 PO0494492581	KU	3	45 ACW	SP	S		V	2/9/2093
2020 PO0494492315	KU	3	45 ACW	SP	S		V	2/10/2093
2020 PO0494492034	KU	3	45 ACW	SP	S		V	2/11/2093
2020 PO9617690289A	KU	3	40 ACW	SP	S		V	2/12/2093
2020 PO9617690289	KU	4	40 ACW	SP	S		V	2/13/2093

2020 PO5819255317	KU	4	40 ACE	SP	CRE	ED,ID	BD	2/14/2093	
2020 PO9072086598	KU	4	40 XXX	SP	CRE	ED,ID	BD	2/15/2093	
2020 PO9121686293	KU	4	40 XXX	SP	CRE	ID	BD	2/16/2093	
2020 PO9647390647	KU	4	40 ACW	SP	CRE	ED,ID	TD	2/17/2093	
2020 PO9628290520	KU	4	40 ACW	SP	S		V	2/18/2093	
2020 PO9659490332	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	2/19/2093	
2020 PO5793950500	KU	6	30 ACE	SP	CRE	ED,ID	TD	2/20/2093	
2020 PO5796250286	KU	5	35 ACE	SP	CRE	ED,EP,ID	TX	RR	2/21/2093
2020 PO5818550393	KU	4	40 ACE	SP	CRE	ED,ID	TD	2/22/2093	
2020 PO9614789957	KU	4	40 ACW	SP	S		V	2/23/2093	
2020 PO9624889921	KU	6	30 ACW	SP	S		V	2/24/2093	
2020 PO9603989698	KU	4	40 ACW	SP	S		V	2/25/2093	
2020 PO4718706520	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	2/26/2093	
2020 PO9170086036	KU	4	40 XXX	SP	CRE	ED,ID	TD	2/27/2093	
2020 PO5812050250	KU	4	45 ACE	SP	CRE	ED,ID	TD	2/28/2093	
2020 PO4717706759	KU	4	45 BRO	SP	CRE	ED,ID	TD	3/1/2093	
2020 PO5806450369	F	4	40 ACE	SP	P		V	3/2/2093	
2020 PO5815650080	F	4	40 ACE	SP	P		V	3/3/2093	
2020 PO5823950111	KU	5	35 ACE	SP	CRE	ED,ID	BD	3/4/2093	
2020 PO5830749796	KU	5	35 ACE	SP	CRE	ED,ID	BD	3/5/2093	
2020 PO9274685628	KU	5	35 XXX	SP	CRE		V	3/6/2093	
2020 PO9202085846	KU	4	45 XXX	SP	CRE	ED,ID	TD	3/7/2093	
2020 PO9586889464	KU	4	40 ACW	SP	CRE	ED,ID	TD	3/8/2093	
2020 PO9572489265	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	3/9/2093	
2020 PO9555789335	KU	3	40 ACW	SP	S		V	3/10/2093	
2020 PO9574088827	KU	4	40 ACW	SP	S		V	3/11/2093	
2020 PO4709807023	KU	3	40 BRO	SP	CCA	ED	T	3/12/2093	
2020 PO5865349678	KU	5	35 ACE	SP	CRE	ED,ID	TD	3/13/2093	
2020 PO9337685473	KU	5	35 XXX	SP	CRE	ED,ID	VX	RP2	3/14/2093
2020 PO9354185991	KU	4	40 XXX	SP	CRE	ED,ID	TD	3/15/2093	
2020 PO5824949782	F	4	40 ACE	SP	P		V	3/16/2093	
2020 PO4700107340	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	3/17/2093	
2020 PO5806049922	KU	5	35 ACE	SP	CRE	ED,ID	TD	3/18/2093	
2020 PO5797250020	F	4	40 ACE	SP	P		V	3/19/2093	
2020 PO5787149968	KU	6	30 ACE	SP	CCA		V	3/20/2093	
2020 PO5789249886	KU	6	30 ACE	SP	CRE	ED,ID	BD	3/21/2093	
2020 PO9597788836	KU	4	40 ACW	SP	CRE	ED,ID	TD	3/22/2093	
2020 PO4751007566	KU	3	40 BRO	SP	CCA		V	3/23/2093	
2020 PO4729007483	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD	3/24/2093	
2020 PO9545488515	KU	5	35 ACW	SP	CRE	ED,ID,IP	TD	3/25/2093	
2020 PO9547788679	KU	4	40 ACW	SP	CRE	ED,ID	TX	RR	3/26/2093
2020 PO9569588662	KU	3	45 ACW	SP	S		V	3/27/2093	
2020 PO9552385908	KU	4	60 ACW	SP	CRE	ED,ID	TD	3/28/2093	
2020 PO5909249142	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	3/29/2093	
2020 PO4692907578	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/30/2093	
2020 PO4690107866	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	3/31/2093	
2020 PO4691908031	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD	4/1/2093	

2020 PO4779588725	LGE	4	40 BRN	SP	S		V	4/2/2093
2020 PO4780888729	LGE	1	70 BRN	SP	A		V	4/3/2093
2020 PO4778488721	LGE	1	65 BRN	SP	A		V	4/4/2093
2020 PO4780188733	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD	4/5/2093
2020 PO4035783116	F	4	35 BRO	SP	CCA		V	4/6/2093
2020 PO4782088732	LGE	1	65 BRN	SP	A		V	4/7/2093
2020 PO4723788827	LGE	UNK	45 ACE	SP	CRE		V	4/8/2093
2020 PO4722488852	LGE	4	45 ACE	SP	CRE	ED,ID	TD	4/9/2093
2020 PO4718988844	F	4	40 ACE	SP	CCA		V	4/10/2093
2020 PO4719488857	F	3	45 ACE	SP	CCA		V	4/11/2093
2020 PO4717488887	F	4	45 ACE	SP	CRE		V	4/12/2093
2020 PO4720213901	F	4	40 ACE	SP	CCA		V	4/13/2093
2020 PO4715988912	F	1	50 ACE	SP	CCA		V	4/14/2093
2020 PO4826930315	KU	3	40 BRO	SP	CRE	ED,IP	TD	4/15/2093
2020 PO4834530704	KU	4	40 BRO	SP	CRE	ED	TD	4/16/2093
2020 PO4747088602	LGE	1	75 BRN	SP	P		V	4/17/2093
2020 PO4749388610	LGE	1	70 BRN	SP	P		V	4/18/2093
2020 PO9185929836A	ODP	3	45 BRN	SP	CCA		V	4/19/2093
2020 PO9217229994	ODP	5	35 BRN	SP	CCA		V	4/20/2093
2020 PO9285832216	F	1	50 XXX	SP	P		V	4/21/2093
2020 PO9269632043	F	1	50 XXX	SP	P		V	4/22/2093
2020 PO9243431742	F	1	50 BRN	SP	P		V	4/23/2093
2020 PO9226331610	ODP	3	50 BRN	SP	CCA		V	4/24/2093
2020 PO9235031557	ODP	2	55 BRN	SP	CCA		V	4/25/2093
2020 PO9224731334	ODP	3	45 BRN	SP	CCA		V	4/26/2093
2020 PO9215131115	ODP	6	30 BRN	SP	CCA		V	4/27/2093
2020 PO9220931028	ODP	3	45 BRN	SP	CCA		V	4/28/2093
2020 PO9216230860A	ODP	3	45 BRN	SP	CCA		V	4/29/2093
2020 PO9216230860	ODP	3	50 BRN	SP	CCA		V	4/30/2093
2020 PO9212330703	ODP	3	50 BRN	SP	CCA		V	5/1/2093
2020 PO9210530537	ODP	3	50 BRN	SP	CCA		V	5/2/2093
2020 PO9217630264	ODP	2	50 BRN	SP	CCA		V	5/3/2093
2020 PO9212930018	ODP	3	45 BRN	SP	CCA		V	5/4/2093
2020 PO9199030029	ODP	3	45 BRN	SP	CCA		V	5/5/2093
2020 PO9199030029A	ODP	3	45 BRN	SP	CCA		V	5/6/2093
2020 PO9241532128	ODP	5	35 BRN	SP	CCA		V	5/7/2093
2020 PO9228231781	ODP	5	35 BRN	SP	CRE		V	5/8/2093
2020 PO9197231075	ODP	4	40 BRN	SP	CRE		V	5/9/2093
2020 PO9220432115	ODP	4	40 BRN	SP	CRE		V	5/10/2093
2020 PO9283031930	ODP	5	35 BRN	SP	CCA		V	5/11/2093
2020 PO9203431422	ODP	4	40 BRN	SP	CRE		V	5/12/2093
2020 PO9161030455	ODP	2	50 BRN	SP	CCA		V	5/13/2093
2020 PO9258332197	ODP	3	45 BRN	SP	CCA		V	5/14/2093
2020 PO9179129702	ODP	6	30 BRN	SP	CCA		V	5/15/2093
2020 PO9185929836	ODP	2	55 BRN	SP	CCA		V	5/16/2093
2020 PO9216730740	ODP	3	45 BRN	SP	CCA		V	5/17/2093
2020 PO9210431564	ODP	4	45 BRN	SP	CCA		V	5/18/2093

2020 PO9207230048	F	4	40 BRN	SP	CRE		V			5/19/2093
2020 PO9200330495	ODP	4	40 BRN	SP	CRE		V			5/20/2093
2020 PO9220931361	ODP	4	40 XXX	SP	CRE		V			5/21/2093
2020 PO9213431013	ODP	6	30 BRN	SP	CCA		V			5/22/2093
2020 PO9192830678	ODP	5	35 BRN	SP	CRE		V			5/23/2093
2020 PO9207031698	ODP	4	40 BRN	SP	CRE		V			5/24/2093
2020 PO4041982863	LGE	4	40 BRO	SP	CRE	ED,ID		BD		5/25/2093
2020 PO4751788618	LGE	1	75 BRN	SP	P		V			5/26/2093
2020 PO4754088625	LGE	1	75 BRN	SP	P		V			5/27/2093
2020 PO4743311195	KU	4	40 ACE	SP	CRE	ED,ID		BD		5/28/2093
2020 PO4756588634	LGE	1	75 BRN	SP	P		V			5/29/2093
2020 PO4080183127	LGE	3	45 BRN	SP	P	ED,ID		TD		5/30/2093
2020 PO4082883148	LGE	4	30 BRN	SP	CCA		V			5/31/2093
2020 PO4082883134	LGE	3	45 BRN	SP	CCA		V			6/1/2093
2020 PO8017043037	LGE	3	45 BRN	SP	CCA		V			6/2/2093
2020 PO8014242941	LGE	4	35 BRN	SP	CCA		V			6/3/2093
2020 PO3920108348	KU	3	45 BRO	SP	CRE	ED,ID,IP		TD		6/4/2093
2020 PO3947808450	KU	3	45 BRO	SP	CRE	ED,ID,IP		TD		6/5/2093
2020 PO4764788787	LGE	4	40 BRN	SP	A	ED,ID		TD		6/6/2093
2020 PO5124008702	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB		BX	PX	6/7/2093
2020 PO5133108842	KU	3	40 ACE	SP	P		V			6/8/2093
2020 PO5120009327	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB		BX	RP1	6/9/2093
2020 PO5070309247	F	4	40 ACE	SP	P		V			6/10/2093
2020 PO5105108942	F	4	40 ACE	SP	CRE		V			6/11/2093
2020 PO4076983113	LGE	4	35 BRN	SP	CCA		V			6/12/2093
2020 PO4078883099	LGE	4	40 BRN	SP	CCA		V			6/13/2093
2020 PO4078583113	LGE	4	40 BRN	SP	CCA		V			6/14/2093
2020 PO4080483122	LGE	4	35 BRN	SP	CCA		V			6/15/2093
2020 PO4079883134	LGE	4	30 BRN	SP	A	ED,ID		BD		6/16/2093
2020 PO4746311276	KU	4	40 ACE	SP	CRE	ED,ID		TD		6/17/2093
2020 PO4767311204	KU	5	35 ACE	SP	CRE	ED,ID,IP		TD		6/18/2093
2020 PO4764211130	KU	5	35 ACE	SP	CRE	ED,EP,HH,ID,IP,RB		BX	RP1	6/19/2093
2020 PO4643288314	LGE	4	40 ACE	SP	CRE	ED,ID		BD		6/20/2093
2020 PO4643788305	LGE	4	40 ACE	SP	CRE	ED,ID		BD		6/21/2093
2020 PO4644188307	LGE	4	30 ACE	SP	CRE	ED,ID		BD		6/22/2093
2020 PO4644888284	LGE	4	40 ACE	SP	CRE	ED,ID		BD		6/23/2093
2020 PO4645488287	LGE	4	30 ACE	SP	CRE	ED,ID		BD		6/24/2093
2020 PO4765988666	LGE	1	70 BRN	SP	P		V			6/25/2093
2020 PO0522042240	F	4	40 KOP	SP	CRE		V			6/26/2093
2020 PO0527941997	ODP	4	40 XXX	SP	A	ED,ID,SRC		TD		6/27/2093
2020 PO0535141818	ODP	4	45 BRN	SP	CCA		V			6/28/2093
2020 PO0508141674	ODP	4	45 BRN	SP	CCA		V			6/29/2093
2020 PO0540241475	ODP	4	45 BRN	SP	CCA		V			6/30/2093
2020 PO0498741373	ODP	4	45 BRN	SP	CCA		V			7/1/2093
2020 PO0517741003	ODP	4	45 BRN	SP	CCA		V			7/2/2093
2020 PO4860230150	KU	5	35 BRO	SP	CRE	ID,IP		BD		7/3/2093
2020 PO4038083107	LGE	4	40 BRO	SP	P	ED,ID		TD		7/4/2093

2020 PO4037083116	LGE	4	35 BRO	SP	P	ED,ID	TD	7/5/2093
2020 PO4035483111	F	4	40 BRN	SP	CCA		V	7/6/2093
2020 PO4034683098	LGE	4	35 BRN	SP	A	ED,ID	TD	7/7/2093
2020 PO4036283101	LGE	4	35 BRN	SP	P	ED,ID	TD	7/8/2093
2020 PO4852230088	KU	5	35 BRO	SP	CRE	ED	TD	7/9/2093
2020 PO4798810581	KU	4	40 ACE	SP	CRE	ED,ID	BD	7/10/2093
2020 PO4036482779	F	3	45 BRO	SP	P		V	7/11/2093
2020 PO4036582758	LGE	4	30 BRO	SP	CCA		V	7/12/2093
2020 PO4031083091	F	4	30 BRO	SP	CCA		V	7/13/2093
2020 PO4031083103	F	4	35 BRO	SP	CCA		V	7/14/2093
2020 PO4031183113	F	4	30 BRO	SP	CCA	ED	VX	RP2 7/15/2093
2020 PO4033983091	F	4	35 BRO	SP	CCA		V	7/16/2093
2020 PO4032683091	F	4	35 BRO	SP	CCA		V	7/17/2093
2020 PO4032683113	F	4	35 BRO	SP	P	ED,ID	VX	PX 7/18/2093
2020 PO4031183002	LGE	4	30 BRO	SP	P	ED,ID	BD	7/19/2093
2020 PO4028582973	F	4	40 BRO	SP	CCA		V	7/20/2093
2020 PO4772088674	LGE	4	35 BRN	SP	A	ED,ID	TD	7/21/2093
2020 PO4922936139	KU	4	40 BRO	SP	CRE	ED	TD	7/22/2093
2020 PO4927436248	KU	4	40 BRO	SP	CRE	ED	TD	7/23/2093
2020 PO4931936357	KU	5	35 BRO	SP	CRE	ED	TD	7/24/2093
2020 PO4786510631	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	7/25/2093
2020 PO4775610675	KU	4	40 ACE	SP	CRE	ED,ID	BD	7/26/2093
2020 PO4773888682	LGE	4	40 BRN	SP	A	ED,ID	BD	7/27/2093
2020 PO4773088691	LGE	1	65 BRN	SP	CRE		V	7/28/2093
2020 PO4772888685	LGE	4	35 BRN	SP	A	ED,ID,RB,SRC	TX	RR 7/29/2093
2020 PO0474540947	ODP	4	45 BRN	SP	CCA		V	7/30/2093
2020 PO0486240658	ODP	4	45 BRN	SP	CCA		V	7/31/2093
2020 PO0452740599	F	3	45 XXX	SP	CRE		V	8/1/2093
2020 PO4762410731	KU	4	40 ACE	SP	CRE	ED,ID	BD	8/2/2093
2020 PO0405540268	F	3	40 XXX	SP	CRE		V	8/3/2093
2020 PO0435940301	F	4	40 XXX	SP	CRE		V	8/4/2093
2020 PO4753210791	KU	5	35 ACE	SP	CCA		V	8/5/2093
2020 PO4755710853	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	8/6/2093
2020 PO4771588681	LGE	4	40 BRN	SP	A	ED,ID	TD	8/7/2093
2020 PO4770188676	LGE	4	35 BRN	SP	A	ED,ID,IP	TD	8/8/2093
2020 PO4774410965	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	8/9/2093
2020 PO0438640202	ODP	4	45 XXX	SP	CCA		V	8/10/2093
2020 PO0440340108	F	4	40 XXX	SP	CRE		V	8/11/2093
2020 PO4289011390	KU	2	45 BRO	SP	CRE	ED,ID,IP	TD	8/12/2093
2020 PO4708335032	KU	3	45 BRO	SP	CRE	ID,IP	BD	8/13/2093
2020 PO4768788671	LGE	4	35 BRN	SP	CCA		V	8/14/2093
2020 PO4768788652	LGE	3	50 BRN	SP	CCA		V	8/15/2093
2020 PO4767699571	LGE	1	50 BRN	SP	S		V	8/16/2093
2020 PO0452339969	ODP	4	40 XXX	SP	CCA		V	8/17/2093
2020 PO0441539973	F	4	40 XXX	SP	CRE		V	8/18/2093
2020 PO0441639808	F	4	40 XXX	SP	CRE		V	8/19/2093
2020 PO0430839810	F	4	35 XXX	SP	CRE		V	8/20/2093

2020 0399740148a	ODP	4	30 XXX	SP	CCA		V		8/21/2093	
2020 PO0399740148	ODP	2	60 BRN	SP	CCA		V		8/22/2093	
2020 PO0398639777	ODP	2	60 XXX	SP	CCA		V		8/23/2093	
2020 PO0441339567	F	4	40 XXX	SP	CRE		V		8/24/2093	
2020 PO0437539200	F	4	40 XXX	SP	CRE		V		8/25/2093	
2020 PO4838310919	KU	4	40 ACE	SP	CRE		ED,ID,IP	TD	8/26/2093	
2020 PO4774188620	LGE	4	40 BRN	SP	A		ED,ID	BD	8/27/2093	
2020 PO4827699202	LGE	1	50 BRN	SP	S		V		8/28/2093	
2020 PO4773388640	LGE	1	50 BRN	SP	CCA		V		8/29/2093	
2020 PO0376238527	F	3	30 XXX	SP	CRE		V		8/30/2093	
2020 PO0389638727	F	3	30 XXX	SP	CRE		V		8/31/2093	
2020 PO0366838354	ODP	2	55 BRN	SP	CCA		V		9/1/2093	
2020 PO0368038083	ODP	2	50 BRN	SP	CCA		V		9/2/2093	
2020 PO9357133112	F	2	50 XXX	SP	A		V		9/3/2093	
2020 PO9365032976	F	4	40 XXX	SP	A		V		9/4/2093	
2020 PO4695134885	KU	3	45 BRO	SP	CRE		ID,IP	BD	9/5/2093	
2020 PO4774188657	LGE	4	40 BRN	SP	CRE		ED,ID	BD	9/6/2093	
2020 PO4774788674	LGE	4	40 BRN	SP	CRE		ED,ID	BD	9/7/2093	
2020 PO4638934261	KU	3	45 BRO	SP	CRE		ED,ID,IP	TD	9/8/2093	
2020 PO4775288681	LGE	4	40 BRN	SP	S		V		9/9/2093	
2020 PO4775888678	LGE	6	25 BRN	SP	CRE		ED,ID	TD	9/10/2093	
2020 PO4776388693	LGE	4	35 BRN	SP	S		V		9/11/2093	
2020 PO4628134217	KU	3	45 BRO	SP	CRE		ED,ID,IP	TD	9/12/2093	
2020 PO4035983095	F	2	55 BRO	SP	A		V		9/13/2093	
2020 PO4035183081	F	2	50 BRO	SP	CCA		V		9/14/2093	
2020 PO4033883060	F	3	45 BRO	SP	S		V		9/15/2093	
2020 PO4033083046	LGE	2	55 BRO	SP	A		V		9/16/2093	
2020 PO4033283050	F	2	50 BRO	SP	P		V		9/17/2093	
2020 PO4033783046	LGE	4	30 BRO	SP	P		ED,ID	TX	RR	9/18/2093
2020 PO4033683049	LGE	4	30 BRO	SP	P		ED,ID	BD		9/19/2093
2020 PO4034783073	F	1	45 BRO	SP	A		V			9/20/2093
2020 PO4775688693	LGE	3	45 BRN	SP	CRE		ED,ID	BD		9/21/2093
2020 PO4615234308	KU	2	50 BRO	SP	CRE		HH,RB	X	RP1	9/22/2093
2020 PO4775588699	LGE	1	65 BRN	ST	P		V			9/23/2093
2020 PO4774288702	LGE	2	50 BRN	SP	CCA		V			9/24/2093
2020 PO4775488706	LGE	1	80 BRN	SP	CRE		V			9/25/2093
2020 PO4775288712	LGE	4	25 BRN	SP	CRE		ED,ID,IP,MD	BD		9/26/2093
2020 PO4777488718	LGE	4	40 BRN	SP	CRE		ED,ID,IP	TD		9/27/2093
2020 PO477910925	KU	4	40 ACE	SP	CRE		ED,ID,IP	BD		9/28/2093
2020 PO4788510880	KU	4	40 ACE	SP	CRE		ED,ID	BD		9/29/2093
2020 PO4796810846	KU	4	40 ACE	SP	CRE		ED,ID	BD		9/30/2093
2020 PO4807510801	KU	4	40 ACE	SP	CRE		ED,ID	TD		10/1/2093
2020 PO4602934409	KU	3	45 BRO	SP	CRE		ID,IP	BD		10/2/2093
2020 PO4522335079	KU	2	55 BRO	SP	CRE		ED,ID,IP	TD		10/3/2093
2020 PO4512435170	KU	3	45 BRO	SP	CRE		ED,ID,IP	TD		10/4/2093
2020 PO4776488714	LGE	1	70 BRN	SP	A		V			10/5/2093
2020 PO4532534991	KU	2	60 BRO	SP	CCA		V			10/6/2093

2020 PO4505035240	KU	3	45 BRO	SP	CCA		V		10/7/2093	
2020 PO4603138432	KU	3	45 BRO	SP	CCA		V		10/8/2093	
2020 PO4593238321	KU	3	45 BRO	SP	CCA		V		10/9/2093	
2020 PO4603338488	KU	4	40 BRO	SP	CRE		V		10/10/2093	
2020 PO4594838321	KU	3	45 BRO	SP	CCA		V		10/11/2093	
2020 PO4595138376	KU	6	30 BRO	SP	CCA		V		10/12/2093	
2020 PO5241238000	F	3	45 ACE	SP	CCA		V		10/13/2093	
2020 PO5242438198	F	3	45 ACE	SP	CCA		V		10/14/2093	
2020 PO5234238526	F	5	35 ACE	SP	CRE		V		10/15/2093	
2020 PO4466135379	KU	3	45 BRO	SP	CRE	ID		TD	10/16/2093	
2020 PO4467935107	KU	3	45 BRO	SP	CCA		V		10/17/2093	
2020 PO4473635336A	KU	4	40 BRO	SP	A	ID		TD	10/18/2093	
2020 PO4473635336	F	6	30E BRO	SP	CRE		V		10/19/2093	
2020 PO5407645288	KU	6	30 BRO	SP	CRE	ID		TD	10/20/2093	
2020 PO5415545083	KU	4	40 BRO	SP	CRE	ID		BD	10/21/2093	
2020 PO5419545273	KU	3	40 BRO	SP	CCA		V		10/22/2093	
2020 PO5421345351	KU	4	40 BRO	SP	CRE	ID,IP		TD	10/23/2093	
2020 PO5438944621	KU	4	45 BRO	SP	CCA		V		10/24/2093	
2020 PO5185938759	F	4	40 ACE	SP	CRE		V		10/25/2093	
2020 PO5185938759-A	KU	5	35 ACE	SP	CRE		V		10/26/2093	
2020 PO4477235546	KU	3	45 BRO	SP	CRE	ID		BD	10/27/2093	
2020 PO4488235719	KU	3	45 BRO	SP	CRE	ID		TD	10/28/2093	
2020 PO5440544536	KU	3	45 BRO	SP	CRE	ID		BD	10/29/2093	
2020 PO5436244692	KU	4	45 BRO	SP	CRE	ID		BD	10/30/2093	
2020 PO4766288493	LGE	4	40 BRO	SP	P	ED,ID,RB		TX	RR	10/31/2093
2020 PO4764988476	LGE	4	40 BRO	SP	P	ED,ID		TD		11/1/2093
2020 PO4764088462	LGE	4	40 BRO	SP	CCA	ED,ID,MD		BX	RP2	11/2/2093
2020 PO4776588889	LGE	4	40 BRN	SP	CRE	ED,ID,IP		BD		11/3/2093
2020 PO2174826689	ODP	4	40 XXX	SP	CRE	EP,HH,RB		X	PX	11/4/2093
2020 PO2213626806	ODP	4	40 XXX	SP	CRE	ID		TD		11/5/2093
2020 PO2251926911	ODP	4	40 XXX	SP	CRE	ID		TD		11/6/2093
2020 PO2292226849	ODP	4	40 XXX	SP	CRE	ID		TD		11/7/2093
2020 PO2281826998	ODP	4	45 XXX	SP	CRE	HH		X	RP2	11/8/2093
2020 PO4769388489	LGE	4	40 BRO	SP	CCA		V			11/9/2093
2020 PO4772188457	LGE	4	40 BRO	SP	CCA		V			11/10/2093
2020 PO4773788441	LGE	3	45 BRO	SP	CCA		V			11/11/2093
2020 PO4771888451	LGE	3	45 BRO	SP	CCA		V			11/12/2093
2020 PO4770488474	LGE	4	40 BRO	SP	CCA	ED,ID,RB		VX	RP1	11/13/2093
2020 PO477588867	LGE	4	40 BRN	SP	CRE	ED,ID		TD		11/14/2093
2020 PO4778188856	LGE	4	40 BRN	SP	CRE	ED,ID		TD		11/15/2093
2020 PO4778688844	LGE	4	40 BRN	SP	CRE	ED,ID		TD		11/16/2093
2020 PO4775788830	LGE	4	30 BRN	SP	CRE	ED,ID,IP		BD		11/17/2093
2020 PO4619887906	F	4	40 BRO	SP	A		V			11/18/2093
2020 PO6180166480	KU	6	30 OTH	SP	CCA		V			11/19/2093
2020 PO6170366303	KU	6	30 OTH	SP	CCA		V			11/20/2093
2020 PO6186966400	KU	6	30 OTH	SP	CRE	ID		TD		11/21/2093
2020 PO6179966416	KU	4	40 OTH	SP	CRE	ID		TD		11/22/2093

2020 PO4620787895	F	4	40 BRO	SP	CRE		V		11/23/2093
2020 PO4776388822	LGE	4	30 BRN	SP	CRE	ED,ID	TD		11/24/2093
2020 PO4779288834	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD		11/25/2093
2020 PO5219838740	KU	6	30 ACE	SP	CCA		V		11/26/2093
2020 PO4469036005	KU	3	45 BRO	SP	CCA		V		11/27/2093
2020 PO4485635934	KU	3	45 BRO	SP	A	ID	TD		11/28/2093
2020 PO4498135877-A	KU	4	45 BRO	SP	CCA		V		11/29/2093
2020 PO4508136034	KU	4	40 BRO	SP	CRE		V		11/30/2093
2020 PO4498135877	KU	3	45 BRO	SP	A	ID	TD		12/1/2093
2020 PO4517336176	KU	4	45 BRO	SP	A	ID	TD		12/2/2093
2020 PO4516236403	KU	4	40 BRO	SP	CRE		V		12/3/2093
2020 PO4527536328	KU	4	40 BRO	SP	CRE		V		12/4/2093
2020 PO4554236560	KU	4	40 BRO	SP	CCA		V		12/5/2093
2020 PO4541536525	KU	2	50 BRO	SP	P		V		12/6/2093
2020 PO4569036597	KU	3	45 BRO	SP	CRE	ID	TD		12/7/2093
2020 PO4581336834	KU	3	45 BRO	SP	CCA		V		12/8/2093
2020 PO4588036454	KU	6	30 BRO	SP	CRE		V		12/9/2093
2020 PO4586536521	F	4	40 BRO	SP	CRE		V		12/10/2093
2020 PO4584736629	KU	3	45 BRO	SP	A	ID	TD		12/11/2093
2020 PO4622736451	KU	3	45 BRO	SP	CCA		V		12/12/2093
2020 PO5432844772	KU	4	40 BRO	SP	CRE	ID,IP	TD		12/13/2093
2020 PO6205666673	KU	4	40 OTH	SP	CRE	ID	TD		12/14/2093
2020 PO4621487878	F	4	40 BRO	SP	CRE	ED,HH,ID,RB	VX	PX	12/15/2093
2020 PO4618787865	F	4	40 BRO	SP	CCA		V		12/16/2093
2020 PO4619587870	F	4	40 BRO	SP	CRE	ED,HH,ID,RB	VX	PX	12/17/2093
2020 PO4621487883	F	4	40 BRO	SP	CRE		V		12/18/2093
2020 PO4622187888	F	4	40 BRO	SP	CRE		V		12/19/2093
2020 PO4625587881	F	4	40 BRO	SP	CCA		V		12/20/2093
2020 PO6280167652	F	6	30 OTH	SP	CRE	ED	V		12/21/2093
2020 PO6265767593	KU	5	35 OTH	SP	CRE	ID	BD		12/22/2093
2020 PO6240567195	KU	4	40 OTH	SP	CRE	ID	TD		12/23/2093
2020 PO6224767203	KU	6	30 OTH	SP	CRE	ID	TD		12/24/2093
2020 PO6274067651	KU	6	30 OTH	SP	CRE	ID	TD		12/25/2093
2020 PO6252567385	KU	4	40 OTH	SP	CRE	ID	TD		12/26/2093
2020 PO4626287870	F	4	40 BRO	SP	CRE	ED,ID,RB	VX	PX	12/27/2093
2020 PO4624687895	F	4	40 BRO	SP	CRE		V		12/28/2093
2020 PO4623587897	F	4	40 BRO	SP	CCA		V		12/29/2093
2020 PO4729588332	LGE	4	40 BRO	SP	A	ED,ID	BD		12/30/2093
2020 PO5244138510	KU	4	40 ACE	SP	CCA		V		12/31/2093
2020 PO5252338634	KU	4	40 ACE	SP	CRE	ED,ID	TD		1/1/2094
2020 PO5426644959	KU	4	40 BRO	SP	CRE	HH,ID	X	PX	1/2/2094
2020 PO5429145073	KU	4	45 BRO	SP	CCA		V		1/3/2094
2020 PO5245238723	F	3	45 ACE	SP	CCA		V		1/4/2094
2020 PO5432545244	KU	3	40 BRO	SP	CRE	ID,IP	TD		1/5/2094
2020 PO5436045258	KU	4	45 BRO	SP	CRE	HH,ID	X	PX	1/6/2094
2020 PO5235438988	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		1/7/2094
2020 PO5225138972	KU	6	30 ACE	SP	CRE	ID	BD		1/8/2094

2020 PO5452745765	KU	4	45 BRO	SP	CRE	ID	BD	1/9/2094
2020 PO5451245313	KU	3	40 BRO	SP	CRE	ID,IP,SRS	TD	1/10/2094
2020 PO5452745816	KU	4	40 BRO	SP	CRE		V	1/11/2094
2020 PO5452745641	KU	4	40 BRO	SP	CCA		V	1/12/2094
2020 PO5452745530	KU	4	45 BRO	SP	CRE	ID	BD	1/13/2094
2020 PO5452545498	KU	4	45 BRO	SP	CRE	ID	BD	1/14/2094
2020 PO5465045962	F	4	30 BRO	SP	A		V	1/15/2094
2020 PO5477745950	F	2	30 BRO	SP	CRE		V	1/16/2094
2020 PO4614287993	F	4	40 BRO	SP	CRE		V	1/17/2094
2020 PO4615687991	F	3	45 BRO	SP	CCA		V	1/18/2094
2020 PO4617187990	F	4	40 BRO	SP	CRE		V	1/19/2094
2020 PO4618187990	F	4	40 BRO	SP	CRE		V	1/20/2094
2020 PO4618987978	F	4	40 BRO	SP	CRE		V	1/21/2094
2020 PO4619987964	F	3	45 BRO	SP	CCA		V	1/22/2094
2020 PO6185566661	F	5	40 OTH	SP	CRE	ED	V	1/23/2094
2020 PO6171866747	KU	5	30 OTH	SP	CRE	ID	TD	1/24/2094
2020 PO4763487876	LGE	1	65 BRO	SP	P	ED,ID,IP,MD	TD	1/25/2094
2020 PO4770187869	LGE	1	70 BRO	SP	P	ED,ID	TD	1/26/2094
2020 PO477687862	LGE	UNK	75 BRO	SP	A	ED,ID,IP	BD	1/27/2094
2020 PO4779587859	LGE	1	75 BRO	SP	CCA	ED,ID	BD	1/28/2094
2020 PO4791488738	LGE	UNK	25 BRO	SP	CCA		V	1/29/2094
2020 PO4778988782	LGE	4	40 BRN	SP	CRE	ED,ID	BD	1/30/2094
2020 PO6124566573	F	5	40 OTH	SP	CRE	ED	V	1/31/2094
2020 PO6140666597	F	4	40 OTH	SP	CRE	ED	V	2/1/2094
2020 PO6154866617	F	4	40 OTH	SP	CRE	ED	V	2/2/2094
2020 PO5452545897	KU	4	40 BRO	SP	CCA		V	2/3/2094
2020 PO5452945971	KU	2	45 BRO	SP	CRE	HH,ID	X	PX 2/4/2094
2020 PO5248138976	F	3	45 ACE	SP	CCA		V	2/5/2094
2020 PO5249239127	F	3	45 ACE	SP	CCA		V	2/6/2094
2020 PO5250339297	F	3	45 ACE	SP	CCA		V	2/7/2094
2020 PO5251639524-A	F	5	35 ACE	SP	CCA		V	2/8/2094
2020 PO4618936693-A	KU	3	45 BRO	SP	CCA		V	2/9/2094
2020 PO6169566639	F	4	40 OTH	SP	CRE	ED	V	2/10/2094
2020 PO4618936693	KU	3	45 BRO	SP	CCA		V	2/11/2094
2020 PO6134966692	KU	5	30 OTH	SP	CRE	ED,ID,SRS	TD	2/12/2094
2020 PO6126666795	KU	5	35 OTH	SP	CCA		V	2/13/2094
2020 PO4781688794	LGE	4	40 BRN	SP	CRE	ED,ID	BD	2/14/2094
2020 PO4782088785	LGE	4	30 BRN	SP	A	ED,ID	BD	2/15/2094
2020 PO6100766783	F	4	40 OTH	SP	CRE	ED	V	2/16/2094
2020 PO6099967031	F	4	40 OTH	SP	P		V	2/17/2094
2020 PO6100466881	F	5	40 OTH	SP	CRE	ED	V	2/18/2094
2020 PO6095866762	KU	5	35 OTH	SP	CCA		V	2/19/2094
2020 PO6145966642	KU	3	45 OTH	SP	CCA		V	2/20/2094
2020 PO6068567015	KU	4	40 OTH	SP	CRE	ID	TD	2/21/2094
2020 PO6114366785	KU	4	45 OTH	SP	CRE	ID	BD	2/22/2094
2020 PO4608888003	F	3	45 BRO	SP	A		V	2/23/2094
2020 PO4614287999	F	4	40E BRO	SP	CRE	ED,HH	VX	RP3 2/24/2094

Business Use

2020 PO3956382767	F	3	50 BRO	SP	CCA		V	2/25/2094
2020 PO3957282770	LGE	UNK	100 BRO	SP	A		V	2/26/2094
2020 PO3958282755	LGE	1	45 BRO	SP	CCA		V	2/27/2094
2020 PO1251033279	ODP	5	35 BRN	SP	CRE	ID	TD	2/28/2094
2020 PO6424303864	KU	6	30 XXX	SP	CRE		V	3/1/2094
2020 PO3987082956	F	4	40 BRN	SP	A		V	3/2/2094
2020 PO3911382532	LGE	7	25 BRN	SP	CRE	ED,ID	TD	3/3/2094
2020 PO3987182944	F	3	45 BRN	SP	CCA		V	3/4/2094
2020 PO4128542187	F	3	45 ACE	SP	CRE		V	3/5/2094
2020 PO3987582936	F	4	40 BRN	SP	CCA		V	3/6/2094
2020 PO3988282930	F	4	40 BRN	SP	CCA		V	3/7/2094
2020 PO3989882918	F	4	40 BRN	SP	CCA		V	3/8/2094
2020 PO4130042039	F	4	40 ACE	SP	CRE	ED,ID	V	3/9/2094
2020 PO4135742072	F	3	45 ACE	SP	P		V	3/10/2094
2020 PO4147641949	F	2	50 ACE	SP	P		V	3/11/2094
2020 PO2453636458	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD	3/12/2094
2020 PO2461136438	KU	4	40 BRN	SP	P	ED	T	3/13/2094
2020 PO2531934304	KU	4	40 BRN	SP	CCA		V	3/14/2094
2020 PO4142741904	F	4	40 ACE	SP	CRE	ED,ID	V	3/15/2094
2020 PO7157320984	KU	5	35 XXX	SP	CRE	ID	TD	3/16/2094
2020 PO7177120914	KU	5	35 XXX	SP	CRE	ID	TD	3/17/2094
2020 PO3990082908	F	3	45 BRN	SP	CCA		V	3/18/2094
2020 PO3905482522	LGE	4	30 BRN	SP	CCA		V	3/19/2094
2020 PO3990282890	F	4	40 BRN	SP	CRE		V	3/20/2094
2020 PO3879083006	LGE	4	35 BRO	SP	P	ED,ID,IP,RR	TX	3/21/2094
2020 PO3883382968	LGE	4	35 BRO	SP	P	ED,ID	TD	3/22/2094
2020 PO1130932857	ODP	5	35 BRN	SP	CCA		V	3/23/2094
2020 PO4155541766	KU	6	30 ACE	SP	CRE	ED,ID	BD	3/24/2094
2020 PO4160841827	F	3	45 ACE	SP	P		V	3/25/2094
2020 PO4134941389	F	4	40 ACE	SP	CRE		V	3/26/2094
2020 PO4144841519	F	6	30 ACE	SP	CRE	ED,ID	V	3/27/2094
2020 PO3905382549	F	4	40 BRN	SP	CRE		V	3/28/2094
2020 PO3906782540	F	4	40 BRN	SP	P		V	3/29/2094
2020 PO3907982532	F	3	45 BRN	SP	CCA		V	3/30/2094
2020 PO9498118283	KU	4	40 UNK	SP	CRE	ED,ID,SRS	TD	3/31/2094
2020 PO3908682517	F	6	25 BRN	SP	CRE		V	4/1/2094
2020 PO3909082525	F	4	40 BRN	SP	P		V	4/2/2094
2020 PO1131933031	ODP	5	35 BRN	SP	CCA		V	4/3/2094
2020 PO3990382877	F	4	40 BRN	SP	CRE		V	4/4/2094
2020 PO3990582865	F	4	40 BRN	SP	CRE		V	4/5/2094
2020 PO3990082860	F	4	30 BRN	SP	CCA		V	4/6/2094
2020 PO3910482518	F	7	25 BRN	SP	CRE		V	4/7/2094
2020 PO3909982524	F	3	45 BRN	SP	CCA		V	4/8/2094
2020 PO1123433036	ODP	4	45 BRN	SP	CCA		V	4/9/2094
2020 PO1118533276A	ODP	3	35E BRN	SP	CRE	ID	BD	4/10/2094
2020 PO3910682536	F	3	45 BRN	SP	CCA		V	4/11/2094
2020 PO3911982566	F	3	45 BRN	SP	CCA		V	4/12/2094

2020 PO3990682853	F	4	40 BRN	SP	CRE		V			4/13/2094
2020 PO4155841662	F	6	30 ACE	SP	CRE	ED,ID	V			4/14/2094
2020 PO3913582576	F	7	25 BRN	SP	CRE		V			4/15/2094
2020 PO3912582578	F	4	40 BRN	SP	CRE		V			4/16/2094
2020 PO3990782841	F	4	40 BRN	SP	A		V			4/17/2094
2020 PO3912982592	F	4	30 BRN	SP	P		V			4/18/2094
2020 PO4012482867	LGE	3	45 BRO	SP	CRE	ED,HH,ID,IP	BX		RR	4/19/2094
2020 PO9467218307	KU	4	40 INP	SP	CRE	ID	TD			4/20/2094
2020 PO9433718451	KU	5	35 ESC	SP	CRE	ED,HH,ID	X		RP3	4/21/2094
2020 PO3990882929	F	3	45 BRN	SP	CCA		V			4/22/2094
2020 PO3912382586	F	4	40 BRN	SP	CRE		V			4/23/2094
2020 6440303771a	KU	6	30 XXX	SP	CRE	RB	X		RP1	4/24/2094
2020 PO6472103714	KU	3	45 XXX	SP	CRE	RB	BX		RP1	4/25/2094
2020 PO6449103715	KU	6	30 KOP	SP	CCA		V			4/26/2094
2020 PO3911082594	F	4	40 BRN	SP	P		V			4/27/2094
2020 PO4169441654	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD			4/28/2094
2020 PO3991982819	F	4	25 BRN	SP	CRE		V			4/29/2094
2020 PO3991082817	F	4	40 BRN	SP	A		V			4/30/2094
2020 PO1020432821	F	4	40 XXX	SP	CRE		V			5/1/2094
2020 PO1045632942	ODP	4	45 XXX	SP	CRE	ID	BD			5/2/2094
2020 PO1038033007	ODP	4	45 XXX	SP	CCA		V			5/3/2094
2020 PO1023732939	ODP	5	35 XXX	SP	CCA		V			5/4/2094
2020 PO1028633056	ODP	1	55 XXX	SP	CRE	ED,ID	TD			5/5/2094
2020 PO4760688658	LGE	4	35 BRN	SP	CRE		V			5/6/2094
2020 PO4759888671	LGE	4	40 BRN	SP	CRE	ED,ID	TD			5/7/2094
2020 PO4759088684	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD			5/8/2094
2020 PO4004882868	LGE	3	45 BRO	SP	A	ED,ID	TD			5/9/2094
2020 PO4004382947	LGE	4	40 BRO	SP	P	ED,ID	BD			5/10/2094
2020 PO4004382929	LGE	4	40 BRO	SP	P	ED,ID,IP	TD			5/11/2094
2020 PO1894621715	ODP	5	35 XXX	SP	CRE	ID	TD			5/12/2094
2020 PO4758588692	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD			5/13/2094
2020 PO4852316768	KU	2	50 BRO	SP	CRE	ED,ID,IP	TD			5/14/2094
2020 PO4715988480	LGE	3	50 BRO	SP	CRE	ED,ID	BD			5/15/2094
2020 PO4716188477	LGE	4	45 BRO	SP	CRE	ED,ID	BD			5/16/2094
2020 PO4716988466	LGE	4	40 BRO	SP	CRE	ED,ID	BD			5/17/2094
2020 PO4716788468	LGE	UNK	70 BRO	SP	CRE		V			5/18/2094
2020 PO4758088701	LGE	4	40 BRN	SP	CRE	ED,ID	TD			5/19/2094
2020 PO1919821775	ODP	4	40 XXX	SP	CRE	ID	TD			5/20/2094
2020 PO1938021767	ODP	5	35 XXX	SP	CRE	ID	TD			5/21/2094
2020 PO1015733110	ODP	4	45 XXX	SP	CRE	ED,ID	TD			5/22/2094
2020 PO1912724218	ODP	6	30 XXX	SP	CRE	HH,ID	VX		RP2	5/23/2094
2020 PO3990682794	F	3	50 BRN	SP	A		V			5/24/2094
2020 PO3986482994	LGE	4	30 BRN	SP	CCA		V			5/25/2094
2020 PO4172541639	KU	3	45 ACE	SP	CCA		V			5/26/2094
2020 PO4174741698	F	3	45 ACE	SP	P		V			5/27/2094
2020 PO2542934058	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD			5/28/2094
2020 PO2588233764	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD			5/29/2094

2020 PO1149833355	ODP	5	35 BRN	SP	CRE		V		5/30/2094
2020 PO1134233384	ODP	5	35 BRN	SP	CRE		V		5/31/2094
2020 PO1121033464	ODP	5	35 BRN	SP	CRE		V		6/1/2094
2020 PO7123721102	KU	5	35 XXX	SP	CRE	ID	BD		6/2/2094
2020 PO7139521048	KU	4	35 XXX	SP	CRE	ID	BD		6/3/2094
2020 PO7228320983	KU	4	40 XXX	SP	CCA		V		6/4/2094
2020 PO7324820270	KU	4	40 XXX	SP	CCA		V		6/5/2094
2020 PO7326920152	KU	4	40 XXX	SP	CCA		V		6/6/2094
2020 PO7328320038	KU	6	30 XXX	SP	CCA		V		6/7/2094
2020 PO7306320093	KU	4	45 XXX	SP	CCA		V		6/8/2094
2020 PO7307020284	KU	4	45 XXX	SP	CCA		V		6/9/2094
2020 PO7322420476	KU	4	40 XXX	SP	CRE	ID	TD		6/10/2094
2020 PO7316520460	KU	4	40 XXX	SP	CCA		V		6/11/2094
2020 PO7308220569	KU	4	45 XXX	SP	CCA		V		6/12/2094
2020 PO7306520790	KU	3	50 XXX	SP	CCA		V		6/13/2094
2020 PO7315620598	KU	4	40 XXX	SP	CCA		V		6/14/2094
2020 PO7306520790A	KU	6	30 XXX	SP	CCA	ED	T		6/15/2094
2020 PO7320920623	KU	6	30 XXX	SP	CCA		V		6/16/2094
2020 PO7319520750	KU	5	30 XXX	SP	CRE	ID	TD		6/17/2094
2020 PO7300920865D	KU	6	30 XXX	SP	CRE	ID	TD		6/18/2094
2020 PO7300920865C	KU	4	40 XXX	SP	CCA		V		6/19/2094
2020 PO7300920865B	KU	6	30 XXX	SP	CCA		V		6/20/2094
2020 PO7300920865A	KU	6	30 XXX	SP	CRE	ID	TD		6/21/2094
2020 PO7300920965	KU	5	35 XXX	SP	CRE	ID	TD		6/22/2094
2020 PO6873917709	KU	3	50 XXX	SP	CCA		V		6/23/2094
2020 PO6868017641	KU	5	35 XXX	SP	CRE	ID	TD		6/24/2094
2020 PO6878917765	KU	6	30 XXX	SP	CRE	ID	TD		6/25/2094
2020 PO6982417469	KU	4	40 XXX	SP	CCA		V		6/26/2094
2020 PO7004117344	KU	4	40 XXX	SP	CCA		V		6/27/2094
2020 PO6968217295	KU	4	40 XXX	SP	CCA		V		6/28/2094
2020 PO6949717285	KU	4	40 XXX	SP	CCA		V		6/29/2094
2020 PO6922317407	KU	4	40 XXX	SP	CCA		V		6/30/2094
2020 PO6923517440	KU	6	30 XXX	SP	CCA		V		7/1/2094
2020 PO6888317511	KU	4	40 XXX	SP	CCA		V		7/2/2094
2020 PO6922021092	KU	5	30 XXX	SP	CRE		V		7/3/2094
2020 PO9416718171	KU	4	40 OTH	SP	CRE	ID	TD		7/4/2094
2020 PO9481718358	KU	4	40 OTH	SP	CRE	ID	TD		7/5/2094
2020 PO9447718210	KU	3	45 BRN	SP	CCA		V		7/6/2094
2020 PO9469018446	KU	6	30 BRO	SP	CCA		V		7/7/2094
2020 PO3991483024	LGE	4	40 BRN	SP	CRE	ED,ID	TD		7/8/2094
2020 PO1118533276	ODP	5	35 BRN	SP	CCA		V		7/9/2094
2020 PO1120333409	ODP	4	40 BRN	SP	CCA		V		7/10/2094
2020 PO4187241581	F	4	40 ACE	SP	P		V		7/11/2094
2020 PO3947182875	F	4	40 BRO	SP	CRE		V		7/12/2094
2020 6485703679b	KU	6	30 KOP	SP	CCA		V		7/13/2094
2020 6485703679b	KU	6	30 KOP	SP	CCA		V		7/14/2094
2020 PO1929224139	ODP	4	40 XXX	SP	CRE	HH,ID,JP	TX	RR	7/15/2094

2020 PO4756988718	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD	7/16/2094
2020 PO4836616994	KU	2	45 BRO	SP	CRE	ID,IP	BD	7/17/2094
2020 PO4717888453	LGE	UNK	70 BRO	SP	CRE		V	7/18/2094
2020 PO4718188449	LGE	3	50 BRO	SP	CRE	ED,ID	BD	7/19/2094
2020 PO4716388481	LGE	4	35 BRO	SP	CRE		V	7/20/2094
2020 PO4718688442	LGE	3	50 BRO	SP	A	ED,ID	TD	7/21/2094
2020 PO3989782704	F	4	40 BRO	SP	CCA		V	7/22/2094
2020 PO3975582755	F	3	25 BRO	SP	CCA		V	7/23/2094
2020 PO3956983182	F	4	40 BRO	SP	CCA		V	7/24/2094
2020 PO3944182154	F	3	35 BRO	SP	CRE		V	7/25/2094
2020 PO4757488710	LGE	4	40 BRN	SP	S		V	7/26/2094
2020 PO4757288743	LGE	4	40 BRN	SP	P	ED,ID	TD	7/27/2094
2020 PO4285297243	LGE	3	50 BRO	SP	CCA		V	7/28/2094
2020 PO4718588434	LGE	4	30 BRO	SP	CRE	ED,ID	BD	7/29/2094
2020 PO4719388432	LGE	UNK	65 BRO	SP	CRE	ED,ID	TD	7/30/2094
2020 PO2462333117	KU	4	40 BRN	SP	CCA		V	7/31/2094
2020 PO4770588690	LGE	4	40 BRN	SP	CRE	ED,ID,MD	VX	RP1 8/1/2094
2020 PO2486133208	KU	5	35 BRN	SP	CRE	ED,ID,IP,MD	TD	8/2/2094
2020 PO2501933331	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	8/3/2094
2020 PO3927083290	F	4	40 BRO	SP	A		V	8/4/2094
2020 PO2541133641	KU	4	40 BRN	SP	CCA		V	8/5/2094
2020 PO2276638382	KU	4	40 BRO	SP	CRE	ID	BD	8/6/2094
2020 PO2264838579	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/7/2094
2020 PO2241738308	KU	4	40 BRO	SP	CCA		V	8/8/2094
2020 PO2247938217	KU	4	40 BRO	SP	CCA		V	8/9/2094
2020 PO2248638233	KU	4	40 BRO	SP	CRE	ID	BD	8/10/2094
2020 PO1142534733	ODP	4	40 XXX	SP	P	ED,ID	TD	8/11/2094
2020 PO1145434516	ODP	5	30 XXX	SP	CRE	ID	BD	8/12/2094
2020 PO3928583290	F	4	40 BRO	SP	P		V	8/13/2094
2020 PO1139434526	ODP	4	40 XXX	SP	CRE	ED,ID,IP	TX	RR 8/14/2094
2020 PO3928483299	LGE	4	30 BRO	SP	CCA		V	8/15/2094
2020 PO3930183289	F	4	40 BRO	SP	P		V	8/16/2094
2020 PO3930283294	LGE	4	30 BRO	SP	P	ED,ID	TD	8/17/2094
2020 PO3931783288	F	4	40 BRO	SP	A		V	8/18/2094
2020 PO4794699768	LGE	4	35 BRN	SP	CRE	ED,ID	BD	8/19/2094
2020 PO4769288693	LGE	4	40 BRN	SP	CRE	ED,ID	TD	8/20/2094
2020 PO4768588693	LGE	4	35 BRN	SP	A		V	8/21/2094
2020 PO4768288708	LGE	4	35 BRN	SP	CCA		V	8/22/2094
2020 PO4767288719	LGE	4	35 BRN	SP	CCA		V	8/23/2094
2020 PO4650212155	KU	5	35 ACE	SP	CRE	ED,ID	BD	8/24/2094
2020 PO4039982775	F	4	40 BRO	SP	CCA		V	8/25/2094
2020 PO4041282776	F	3	40 BRO	SP	CCA		V	8/26/2094
2020 PO4042782778	F	3	40 BRO	SP	CCA		V	8/27/2094
2020 PO4044282779	F	3	40 BRO	SP	CCA		V	8/28/2094
2020 PO4045982781	F	4	40 BRO	SP	CCA		V	8/29/2094
2020 PO4047782783	F	4	40 BRO	SP	CCA		V	8/30/2094
2020 PO4048582785	LGE	4	30 BRO	SP	P	ED,ID	TD	8/31/2094

2020 PO4049482785	F	4	40 BRO	SP	CCA		V	9/1/2094
2020 PO4050482790	F	4	40 BRO	SP	CCA		V	9/2/2094
2020 PO4051882788	F	4	40 BRO	SP	CCA		V	9/3/2094
2020 PO4800811505	KU	4	40 ACE	SP	CRE	ED,ID	TD	9/4/2094
2020 PO4083709292	KU	3	45 BRO	SP	CRE	ID,IP	BD	9/5/2094
2020 PO3933283287	F	4	40 BRO	SP	A		V	9/6/2094
2020 PO3934483286	F	4	40 BRO	SP	CRE		V	9/7/2094
2020 PO4058943227	KU	3	45 ACE	SP	P		V	9/8/2094
2020 PO3976783038	F	4	40 BRN	SP	CRE		V	9/9/2094
2020 PO3976583053	F	4	40 BRN	SP	CRE		V	9/10/2094
2020 PO3976483067	F	3	45 BRN	SP	S		V	9/11/2094
2020 8158527184A	KU	1	60 BRN	SP	CCA		V	9/12/2094
2020 PO8146127896	KU	1	60 BRN	SP	CCA		V	9/13/2094
2020 PO8232331576	KU	5	35 OTH	SP	CRE	ID	TD	9/14/2094
2020 PO8158527184	KU	1	60 BRN	SP	CCA		V	9/15/2094
2020 PO8161327123	KU	1	60 BRN	SP	CCA		V	9/16/2094
2020 PO8138927044	KU	3	55 KOP	SP	CCA		V	9/17/2094
2020 PO8142827890	KU	1	60 BRN	SP	CCA		V	9/18/2094
2020 PO1127034548	ODP	4	40 XXX	SP	CRE	ED,ID	TD	9/19/2094
2020 PO1149734561	ODP	4	40 XXX	SP	CRE	ED,ID	TD	9/20/2094
2020 PO3877683015	LGE	4	30 BRO	SP	A		V	9/21/2094
2020 PO3894682865	F	3	45 BRO	SP	CCA		V	9/22/2094
2020 PO3892182871	F	3	65 BRO	SP	P		V	9/23/2094
2020 PO3889982877	F	6	65 BRO	SP	P		V	9/24/2094
2020 PO3889882872	F	4	35 BRO	SP	P		V	9/25/2094
2020 PO3889582862	F	4	45 BRO	SP	P		V	9/26/2094
2020 PO3887582883	F	6	65 BRO	SP	P		V	9/27/2094
2020 PO3887482888	F	4	40 BRO	SP	CCA		V	9/28/2094
2020 PO3887582898	F	4	40 BRO	SP	CCA		V	9/29/2094
2020 PO3887682914	F	3	45 BRO	SP	CCA		V	9/30/2094
2020 PO3884882889	F	6	65 BRO	SP	CRE		V	10/1/2094
2020 PO3883382893	F	4	35 BRO	SP	CRE		V	10/2/2094
2020 PO3880682929	LGE	4	35 BRO	SP	P	ED	TD	10/3/2094
2020 PO8207431412	KU	5	35 OTH	SP	CRE		V	10/4/2094
2020 PO8142936411	KU	4	45 ACW	SP	CRE		V	10/5/2094
2020 PO8315026651	KU	5	35 ACW	SP	CRE		V	10/6/2094
2020 PO8314626632	KU	4	40 ACW	SP	CRE		V	10/7/2094
2020 PO3927982514	LGE	5	25 BRN	SP	CRE	ED,ID	TD	10/8/2094
2020 PO3927682524	LGE	4	45 BRN	SP	CRE	ED,ID	BD	10/9/2094
2020 PO3927582519	LGE	5	25 BRN	SP	CRE	ED,ID	TD	10/10/2094
2020 PO1122936171	ODP	3	45 BRN	SP	CCA		V	10/11/2094
2020 PO1142136086	ODP	6	30 BRN	SP	CCA		V	10/12/2094
2020 PO3973283058	F	4	40 BRN	SP	CRE		V	10/13/2094
2020 PO1144536167	ODP	3	45 BRN	SP	CCA		V	10/14/2094
2020 PO1160336163	ODP	3	45 BRN	SP	CCA		V	10/15/2094
2020 PO1173636156	ODP	3	45 BRN	SP	CCA		V	10/16/2094
2020 PO3973483039	F	4	40 BRN	SP	CRE		V	10/17/2094

2020 PO3973883039	F	4	30 BRN	SP	CRE		V		10/18/2094
2020 PO1188936182	ODP	4	45 KOP	SP	CRE	ID	BD		10/19/2094
2020 PO3928082544	LGE	4	25 BRN	SP	CRE	ED,ID	TD		10/20/2094
2020 PO2529535557	KU	4	40 BRN	SP	CRE	ID,IP	BD		10/21/2094
2020 PO3972783024	F	4	30 BRN	SP	CRE		V		10/22/2094
2020 PO6470536856	LGE	3	45 BRN	SP	CCA		V		10/23/2094
2020 PO3928382539	LGE	4	40 BRN	SP	CRE	ED,ID	BD		10/24/2094
2020 PO3928482542-A	LGE	4	30 BRN	SP	CCA		V		10/25/2094
2020 PO3928882549	LGE	4	40 BRN	SP	CCA	ED,ID	BD		10/26/2094
2020 PO6480837078	LGE	3	45 BRN	SP	CCA		V		10/27/2094
2020 PO3927682558	LGE	4	40 BRN	SP	CRE	ED,ID	BD		10/28/2094
2020 PO2273537664	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD		10/29/2094
2020 PO4002242686	KU	4	40 ACE	SP	CRE		V		10/30/2094
2020 PO3935683232	F	4	40 BRO	SP	CRE		V		10/31/2094
2020 PO3934783229	LGE	4	40 BRO	SP	CCA		V		11/1/2094
2020 PO3935183223	F	4	40 BRO	SP	CCA		V		11/2/2094
2020 PO3935583218	F	4	40 BRO	SP	CCA		V		11/3/2094
2020 PO3935583202	F	4	40 BRO	SP	CRE		V		11/4/2094
2020 PO7623803236	F	4	40 BRN	SP	CRE		V		11/5/2094
2020 PO7612403349	KU	6	30 BRN	SP	CRE		V		11/6/2094
2020 PO7681403724	KU	4	40 BRN	SP	CCA		B		11/7/2094
2020 PO7193089062	KU	6	30 BRN	SP	CRE	ED,ID	TD		11/8/2094
2020 PO7189689069	F	4	35 BRN	SP	CCA		V		11/9/2094
2020 PO7189389422	KU	3	40 BRN	SP	CRE	ED,ID	BD		11/10/2094
2020 PO3907082656	LGE	4	40 BRN	SP	CRE	ED,ID	BD		11/11/2094
2020 PO9160816285	KU	5	35 BRN	SP	CRE		V		11/12/2094
2020 PO9141116701	KU	4	40 BRN	SP	CRE		V		11/13/2094
2020 PO3908282648	LGE	3	45 BRN	SP	CCA		V		11/14/2094
2020 PO3909482640	LGE	3	45 BRN	SP	CCA		V		11/15/2094
2020 PO3910782632	LGE	3	45 BRN	SP	CCA		V		11/16/2094
2020 PO0976831665	ODP	5	35 XXX	SP	CRE	SRC	V		11/17/2094
2020 PO0971031819	ODP	5	35 XXX	SP	CRE	ED,HH,ID,IP	TX	RR	11/18/2094
2020 PO3911982619	LGE	4	30 BRN	SP	A	ED,ID	TD		11/19/2094
2020 PO3911982624	LGE	4	40 BRN	SP	CRE	ED,ID	TD		11/20/2094
2020 PO3948382840	LGE	4	30 BRO	SP	P	ED,ID,RB	X	PX	11/21/2094
2020 PO4563535636	KU	3	45 ACE	SP	CRE		V		11/22/2094
2020 PO9134319192	KU	3	45 BRN	SP	CCA		V		11/23/2094
2020 PO7168689402	KU	5	35 BRN	SP	CRE	ED,ID	TD		11/24/2094
2020 PO7161589281	F	4	35 BRN	SP	CRE		V		11/25/2094
2020 PO7169489220	F	6	30 BRN	SP	CRE		V		11/26/2094
2020 PO7062589072	F	3	40 BRN	SP	CRE		V		11/27/2094
2020 PO7105689061	KU	6	30 BRN	SP	CRE	ED,ID	BD		11/28/2094
2020 PO6923298276	KU	5	35 BRN	SP	CRE	RB	X	RP1	11/29/2094
2020 PO6923197963	KU	5	35 BRN	SP	CRE	ED,ID	TD		11/30/2094
2020 PO6903097656	KU	4	40 BRN	OT	CRE		V		12/1/2094
2020 PO6899297410	KU	4	40 BRN	SP	CRE	ID	BX	RP2	12/2/2094
2020 PO6893796760	KU	4	40 BRN	SP	CCA		V		12/3/2094

2020 PO6893796441	KU	4	40 BRN	SP	CRE	IP	BX	RP3	12/4/2094
2020 PO6887995532	KU	4	40 BRN	OT	CRE		V		12/5/2094
2020 PO6885895151	KU	5	35 BRN	SP	CCA		V		12/6/2094
2020 PO1629110709	KU	5	35 BRN	SP	CCA		V		12/7/2094
2020 PO1619410703	KU	4	40 BRN	SP	CCA		V		12/8/2094
2020 PO1631510315	KU	6	30 ACW	SP	CRE	ED,ID	TD		12/9/2094
2020 PO1648210343	KU	3	45 BRN	SP	CCA		V		12/10/2094
2020 PO9743417554	KU	5	35 BRO	SP	CRE	ID	X	RP2	12/11/2094
2020 PO9642517655	KU	4	40 BRO	SP	CRE	ID,IP	TX	RR	12/12/2094
2020 PO9554718139	KU	4	40 BRO	SP	CRE	ID,MD	TX	RR	12/13/2094
2020 PO9651917596	KU	6	30 BRO	SP	CRE		V		12/14/2094
2020 PO9856317542	KU	4	40 BRO	SP	CRE	ID	TD		12/15/2094
2020 PO9799517710	KU	6	30 BRO	SP	CRE	ID	TD		12/16/2094
2020 PO9736917222a	KU	6	35 BRO	SP	CRE	ID	TD		12/17/2094
2020 PO9694117475	KU	4	40 BRO	SP	CCA		V		12/18/2094
2020 PO9736917222	KU	4	40 BRO	SP	CCA		V		12/19/2094
2020 PO9745317301	KU	5	35 BRO	SP	CRE	ID	TD		12/20/2094
2020 PO9716617345	KU	6	30 BRO	SP	CRE	ID	TD		12/21/2094
2020 PO9721517521	KU	5	35 BRO	SP	CRE	ID	TD		12/22/2094
2020 PO9686217453	KU	4	40 BRO	SP	CCA		V		12/23/2094
2020 PO9692717391	KU	4	30 BRO	SP	CRE		V		12/24/2094
2020 PO9679017359	KU	4	40 BRO	SP	CRE	ID	TD		12/25/2094
2020 PO9672817398	KU	4	40 BRO	SP	CRE	ID	TD		12/26/2094
2020 PO9678417471	KU	5	35 BRO	SP	CRE		V		12/27/2094
2020 PO9681017495	KU	6	30 BRO	SP	CCA		V		12/28/2094
2020 PO9684017545	KU	5	35 BRO	SP	CRE	ID	TD		12/29/2094
2020 PO9671017647	KU	5	35 BRO	SP	CRE		V		12/30/2094
2020 PO9672017223	KU	5	35 BRO	SP	CRE	ID	BD		12/31/2094
2020 PO9647017320	KU	4	40 BRO	SP	CRE	ID	TD		1/1/2095
2020 PO9629217498	KU	4	40 BRO	SP	CRE	ID	TD		1/2/2095
2020 PO9643317590	KU	6	30 BRO	SP	CCA		V		1/3/2095
2020 PO9653417794	KU	5	35 BRO	SP	CRE	ID	TD		1/4/2095
2020 PO9633117958	KU	5	35 BRO	SP	CRE		V		1/5/2095
2020 PO9616518086	KU	5	35 BRO	SP	CRE	ID	TD		1/6/2095
2020 PO9607118171	KU	4	40 BRO	SP	CCA	ID	TD		1/7/2095
2020 PO9603517924	KU	5	35 BRO	SP	CRE	ID	TD		1/8/2095
2020 PO9593618277a	KU	4	40 BRO	SP	CCA		V		1/9/2095
2020 PO9593618277	KU	4	40 BRO	SP	CCA		V		1/10/2095
2020 PO9592018422	KU	4	40 BRO	SP	CCA		V		1/11/2095
2020 PO4577635738	KU	3	45 ACE	SP	CRE		V		1/12/2095
2020 PO3913782506	F	4	40 BRN	SP	CCA	ED,HH,ID,RB	BX	PX	1/13/2095
2020 PO3914982498	F	3	45 BRN	SP	CCA		V		1/14/2095
2020 PO3916182490	F	4	40 BRN	SP	CRE		V		1/15/2095
2020 PO7094689350	KU	3	35 BRN	SP	CRE	ED,ID	BD		1/16/2095
2020 PO7101089458	KU	6	30 BRN	SP	CRE		V		1/17/2095
2020 PO6874618931	F	4	40 XXX	SP	CRE		V		1/18/2095
2020 PO6759716116A	KU	6	30 XXX	SP	CCA		V		1/19/2095

2020 PO6759716116	KU	4	40 XXX	SP	CRE	ID,IP	TD	1/20/2095
2020 PO6769416411	KU	6	30 XXX	SP	CRE	ID,IP	TD	1/21/2095
2020 PO7060321705	KU	2	50 XXX	SP	CCA		V	1/22/2095
2020 PO6991321787	KU	4	45 XXX	SP	CCA		V	1/23/2095
2020 PO6961621632	KU	4	40 XXX	SP	CCA		V	1/24/2095
2020 PO6988521609	KU	4	45 XXX	SP	CCA		V	1/25/2095
2020 PO7000921666	KU	6	30 XXX	SP	CCA		V	1/26/2095
2020 PO3914982533	F	4	40 BRN	SP	CRE		V	1/27/2095
2020 PO3913782541	F	3	45 BRN	SP	CRE		V	1/28/2095
2020 PO3912682548	F	4	40 BRN	SP	S		V	1/29/2095
2020 PO3911382552	F	3	45 BRN	SP	CCA		V	1/30/2095
2020 PO3910182560	F	3	40 BRN	SP	CCA		V	1/31/2095
2020 PO3909082566	F	4	40 BRN	SP	CRE	HH,RB	VX	2/1/2095
2020 PO7124789478	KU	4	35 BRN	SP	P	ED,ID	TD	2/2/2095
2020 PO7124789478A	KU	6	30 BRN	SP	CRE	ED,ID	BD	2/3/2095
2020 PO7122189273	KU	4	35 BRN	SP	CRE	ED,ID	BD	2/4/2095
2020 PO3949482724	LGE	4	35 BRO	SP	CCA		V	2/5/2095
2020 PO3949682718	LGE	3	45 BRO	SP	P		V	2/6/2095
2020 PO3951082713	LGE	3	45 BRO	SP	CCA		V	2/7/2095
2020 PO3908082573	F	4	40 BRN	SP	CCA		V	2/8/2095
2020 PO4612534626	KU	5	35 ACE	SP	CCA		V	2/9/2095
2020 PO4627934747	KU	5	40 ACE	SP	CCA		V	2/10/2095
2020 PO3907082580	F	4	40 BRN	SP	CRE		V	2/11/2095
2020 PO3905982587	F	4	40 BRN	SP	P		V	2/12/2095
2020 PO3904982593	F	3	40 BRN	SP	CCA		V	2/13/2095
2020 PO4682934748	KU	3	45 ACE	SP	CRE	ED,ID	BD	2/14/2095
2020 PO3950982786	LGE	4	40 BRO	SP	P	ED,ID	TD	2/15/2095
2020 PO3947282750	LGE	4	40 BRO	SP	A	ED,ID	TD	2/16/2095
2020 PO3949082785	LGE	4	40 BRO	SP	P	ED,ID	TD	2/17/2095
2020 PO3949482793	LGE	4	40 BRO	SP	CRE	ED,ID	TD	2/18/2095
2020 PO3948582807	LGE	4	35 BRO	SP	P	ED,ID	TD	2/19/2095
2020 PO7136989990	KU	5	35 BRN	SP	CRE	ED,ID	TD	2/20/2095
2020 PO3883382939	LGE	4	35 BRO	SP	P	ED,ID,MD	TD	2/21/2095
2020 PO3883882913	LGE	4	35 BRO	SP	P	ED,ID,IP	TD	2/22/2095
2020 PO3883482925	LGE	4	35 BRO	SP	P	ED,ID,SRC	TD	2/23/2095
2020 PO3938982637	LGE	3	50 BRN	SP	CRE	ED,ID	BD	2/24/2095
2020 PO7129789929	KU	3	50 BRN	SP	CRE	ED,ID	TD	2/25/2095
2020 PO7108790842	KU	4	40 BRN	SP	CCA		V	2/26/2095
2020 PO7253891605	KU	6	30 BRN	SP	CRE	ED,ID	TD	2/27/2095
2020 PO7271991851	KU	6	30 BRN	SP	CRE	ED,ID	TD	2/28/2095
2020 PO2769652971	KU	5	35 BRO	SP	CRE	ED	TD	3/1/2095
2020 PO2811552680	KU	4	40 BRO	SP	CRE	ID,RB	X	3/2/2095
2020 PO4756535580	KU	3	45 ACE	SP	CRE	ED,ID,IP	BD	3/3/2095
2020 PO6689238183	LGE	3	45 BRN	SP	CCA		V	3/4/2095
2020 PO3949782646	LGE	3	45 BRN	SP	P	ED,ID	BD	3/5/2095
2020 PO3871883061	LGE	4	35 BRO	SP	P	ED,MD	TD	3/6/2095
2020 PO3872183046	LGE	4	35 BRO	SP	P	ED,HH,ID,RB	BX	3/7/2095

2020 PO3872983040	LGE	4	35 BRO	SP	CCA		V			3/8/2095
2020 PO3873583045	LGE	4	30 BRO	SP	P	ED,ID	TD			3/9/2095
2020 PO3874583039	LGE	4	35 BRO	SP	CRE	ED,HH,ID,SRC	TX	RR		3/10/2095
2020 PO0926332271	ODP	5	35 XXX	SP	CRE	ED,ID	TD			3/11/2095
2020 PO0918032466	ODP	4	45 XXX	SP	CRE	ED,ID	TD			3/12/2095
2020 PO3948682621	LGE	3	45 BRN	SP	P	ED,ID	BD			3/13/2095
2020 PO3947782603	LGE	3	45 BRN	SP	P	ED,ID	TD			3/14/2095
2020 PO4783235882	KU	3	45 ACE	SP	CRE	ED,ID	TD			3/15/2095
2020 PO2754053079	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD			3/16/2095
2020 PO0906332703	ODP	4	45 XXX	SP	CRE	ED,ID	TD			3/17/2095
2020 PO0899032830	ODP	4	45 XXX	SP	CRE	ED,ID	TD			3/18/2095
2020 PO0898733190	ODP	4	45 XXX	SP	CCA		V			3/19/2095
2020 PO0875632997	ODP	3	45 XXX	SP	CCA		V			3/20/2095
2020 PO3947282598	LGE	1	30 BRN	SP	A	ED,ID	TD			3/21/2095
2020 PO7191791881	KU	6	30 BRN	SP	CRE		V			3/22/2095
2020 PO7174791902	F	4	40 BRN	SP	CRE		V			3/23/2095
2020 PO7182591807	F	3	45 BRN	SP	CRE		V			3/24/2095
2020 PO7181791545	KU	5	35 BRN	SP	CRE	ED,ID	TD			3/25/2095
2020 PO7194891673	F	3	45 BRN	SP	CRE		V			3/26/2095
2020 PO3948882591	LGE	1	30 BRN	SP	A	ED,ID	BD			3/27/2095
2020 9140319584A	KU	5	30 KOP	SP	P	ED,ID,SRC	TD			3/28/2095
2020 9147019868A	KU	6	30 BRN	SP	CCA		V			3/29/2095
2020 PO9129420157	F	4	40 UNK	SP	P	ED	BD			3/30/2095
2020 PO0928333838	ODP	4	45 XXX	SP	CCA		V			3/31/2095
2020 PO0901933879	ODP	4	45 XXX	SP	CCA		V			4/1/2095
2020 PO2729953168	F	4	40 BRO	SP	CRE		V			4/2/2095
2020 PO3951582793	LGE	4	40 BRO	SP	CRE	ED,ID	TD			4/3/2095
2020 PO3952382803	LGE	4	40 BRO	SP	CRE	ED,ID	TD			4/4/2095
2020 PO6714839786	LGE	3	45 BRO	SP	CCA		B			4/5/2095
2020 PO3954182836A	LGE	4	35 BRO	SP	CRE	ED,ID	TD			4/6/2095
2020 PO3953182824	LGE	4	35 BRO	SP	P	ED	T			4/7/2095
2020 PO6737240004	LGE	4	35 BRO	SP	CCA		V			4/8/2095
2020 PO3954182836	LGE	4	35 BRO	SP	CRE	ED,ID	TD			4/9/2095
2020 PO6738839838	LGE	4	35 BRO	SP	CRE	ED,ID	TD			4/10/2095
2020 PO3954782806	LGE	4	35 BRO	SP	CRE	ID	BD			4/11/2095
2020 PO7221791540	KU	4	40 BRN	SP	CRE	ED,ID	BD			4/12/2095
2020 PO7213891424	F	3	45 BRN	SP	CRE		V			4/13/2095
2020 PO7254791179	F	4	45 BRN	SP	CRE		V			4/14/2095
2020 PO3875883042	LGE	4	30 BRO	SP	P	ED	TD			4/15/2095
2020 PO2520737760	KU	4	40 BRN	SP	CRE	ID	BD			4/16/2095
2020 PO2477537705	KU	4	40 BRN	SP	CCA		V			4/17/2095
2020 PO2461837655	KU	4	40 BRN	SP	CRE	ED,ID,MD,SRC	TD			4/18/2095
2020 PO2444237599	KU	4	40 BRN	SP	CCA		V			4/19/2095
2020 PO2426537543	KU	4	40 BRN	SP	CRE	ED,ID,IP,MD,SRC	TD			4/20/2095
2020 PO2411337495	KU	5	35 BRN	SP	CRE	HH,ID,IP	TD			4/21/2095
2020 PO3949482584	LGE	4	40 BRN	SP	CCA	ED,ID	BD			4/22/2095
2020 PO6828993782	KU	4	40 BRN	SP	CRE	ED,HH,ID	VX	PX		4/23/2095

2020 PO0957831831	ODP	4	40 XXX	SP	CRE	ED,ID	TD	4/24/2095
2020 PO0971331406	F	4	40 XXX	SP	P		V	4/25/2095
2020 PO0992831070	F	4	40 XXX	SP	P		V	4/26/2095
2020 PO0957831831A	KU	4	45 XXX	SP	CRE	ED,ID	TD	4/27/2095
2020 PO6831193900	KU	4	40 BRN	SP	CRE	ED,ID	TD	4/28/2095
2020 PO6833794046	KU	4	40 BRN	SP	CRE	ED,ID	BD	4/29/2095
2020 PO1027311327	KU	6	30 BRN	SP	CRE	ED,ID	TD	4/30/2095
2020 PO1008711184	KU	4	40 BRN	SP	CCA	ED,ID	TD	5/1/2095
2020 PO1029611213	KU	4	40 BRN	SP	CRE		V	5/2/2095
2020 PO1026611100	KU	6	30 BRN	SP	CCA		V	5/3/2095
2020 PO1047311362	KU	5	35 UNK	SP	CRE	ED,ID	TD	5/4/2095
2020 PO1078611363	KU	5	35 UNK	SP	CRE	ED,ID	TD	5/5/2095
2020 PO1104511215	KU	6	30 UNK	SP	CRE	ED,ID	TD	5/6/2095
2020 PO1121811250	KU	4	45 UNK	SP	CRE	ED,ID	TD	5/7/2095
2020 PO1163710972	KU	4	40 BRN	SP	CCA		V	5/8/2095
2020 PO1193410820	KU	5	35 UNK	SP	CRE	ED,ID	TD	5/9/2095
2020 PO3974082980	F	3	45 BRN	SP	S		V	5/10/2095
2020 PO3974882965	LGE	4	35 BRN	SP	CCA		V	5/11/2095
2020 PO3076133596	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	5/12/2095
2020 PO3974282964	LGE	4	40 BRN	SP	CCA		V	5/13/2095
2020 PO3974482949	F	4	40 BRN	SP	CCA		V	5/14/2095
2020 PO3974682932	F	3	45 BRN	SP	S		V	5/15/2095
2020 PO3974882917	F	4	40 BRN	SP	CRE		V	5/16/2095
2020 PO7848425790	KU	4	45 BRN	SP	CCA		V	5/17/2095
2020 PO7845325753	KU	4	40 OTH	SP	CRE	ID	TD	5/18/2095
2020 PO7848325872	KU	3	50 BRN	SP	CCA		V	5/19/2095
2020 PO7843525856	KU	4	45 BRN	SP	CCA		V	5/20/2095
2020 PO7868625947	KU	4	35 OTH	SP	CCA		V	5/21/2095
2020 PO7871925916	KU	3	35 OTH	SP	CRE	ID	TD	5/22/2095
2020 PO7869625933	KU	2	50 BRN	SP	CCA		V	5/23/2095
2020 PO7934226373	KU	2	50 BRN	SP	CCA		V	5/24/2095
2020 Po0405516605b	KU	5	35 BRO	SP	CRE	ID	TD	5/25/2095
2020 Po0405516505a	KU	5	35 BRO	SP	CCA		V	5/26/2095
2020 PO0405516605	KU	5	35 BRO	SP	CRE	ID	TD	5/27/2095
2020 PO0390316541	KU	4	40 BRO	SP	CRE	ID	BD	5/28/2095
2020 PO0391216717	KU	5	35 BRO	SP	CCA		V	5/29/2095
2020 PO0482517090	KU	4	40 BRO	SP	CRE	ED,ID	TD	5/30/2095
2020 PO0438217144	KU	5	35 BRO	SP	CRE	ID	TD	5/31/2095
2020 PO0399617112	KU	5	35 BRO	SP	CRE	ED,ID	TD	6/1/2095
2020 PO0372417102	KU	4	40 BRO	SP	CRE	ID	TD	6/2/2095
2020 PO0369017318	KU	4	40 BRO	SP	CRE	ID	TD	6/3/2095
2020 PO0366617605	KU	4	40 BRO	SP	CRE	ID	TD	6/4/2095
2020 Po0370716643b	KU	5	35 BRO	SP	CRE	ID	BD	6/5/2095
2020 Po0370716643a	KU	5	35 BRO	SP	CRE	ID	TD	6/6/2095
2020 PO0361416740	KU	6	30 BRO	SP	CRE	ID	BD	6/7/2095
2020 PO0370716643	KU	5	35 BRO	SP	CRE	ID	TD	6/8/2095
2020 PO0334616752a	KU	5	35 BRO	SP	CRE	ID	TD	6/9/2095

2020 PO0342616863	KU	6	30 BRO	SP	CCA			V	6/10/2095
2020 PO0334616752	KU	5	35 BRO	SP	CRE	ID		TD	6/11/2095
2020 Po0314716822a	KU	4	40 BRO	SP	CRE	ID		TD	6/12/2095
2020 PO0314716822	KU	4	40 BRO	SP	CRE	ID		TD	6/13/2095
2020 PO0318016672	KU	6	30 BRO	SP	CRE			V	6/14/2095
2020 PO0358416432	KU	4	40 BRO	SP	CRE	ID		TD	6/15/2095
2020 PO0336216473	KU	4	40 BRO	SP	CRE	ID		BD	6/16/2095
2020 PO0318416507	KU	4	40 BRO	SP	CRE	ID		TD	6/17/2095
2020 PO0309716144	KU	6	30 BRO	SP	CCA			V	6/18/2095
2020 PO0305216253	KU	4	45 BRO	SP	CCA			V	6/19/2095
2020 PO0301516361	KU	6	30 BRO	SP	CCA			V	6/20/2095
2020 PO0290416553	KU	4	45 BRO	SP	CCA			V	6/21/2095
2020 PO0267216769	KU	4	40 BRO	SP	CRE	ID		TD	6/22/2095
2020 PO0258116585	KU	4	40 BRO	SP	CCA			V	6/23/2095
2020 PO0236116495	KU	4	40 BRO	SP	CCA			V	6/24/2095
2020 PO0192416947	KU	4	40 BRO	SP	CCA			V	6/25/2095
2020 PO0205816816	KU	3	45 BRO	SP	CCA			V	6/26/2095
2020 PO0204616675	KU	5	30 BRO	SP	CRE	ID		TD	6/27/2095
2020 PO0216516686	KU	4	40 BRO	SP	CRE	ID		TD	6/28/2095
2020 PO0220516560	KU	4	45 BRO	SP	CCA			V	6/29/2095
2020 PO0223516392	KU	4	40 BRO	SP	CRE	ID		TD	6/30/2095
2020 PO0191116378	KU	4	40 BRO	SP	CCA			V	7/1/2095
2020 PO3931883181	F	4	40 BRO	SP	CCA			V	7/2/2095
2020 PO3931683186	F	5	30 BRO	SP	P			V	7/3/2095
2020 PO3974982901	F	3	45 BRN	SP	S			V	7/4/2095
2020 PO3933383193	F	5	25 BRO	SP	A	ED		VX	7/5/2095
2020 PO3932583195	F	4	40 BRO	SP	A			V	7/6/2095
2020 PO3933683213	F	5	26 BRO	SP	A			V	7/7/2095
2020 PO3932783212	F	3	45 BRO	SP	CCA			V	7/8/2095
2020 PO3975682886	F	4	30 BRN	SP	CCA			V	7/9/2095
2020 PO3102633296	KU	4	40 BRN	SP	CRE	ED,ID,MD		TD	7/10/2095
2020 PO3929682506	LGE	4	40 BRN	SP	CRE			V	7/11/2095
2020 PO3927982470	LGE	3	45 BRN	SP	CRE	ED,ID		TD	7/12/2095
2020 PO3928082474	LGE	3	45 BRN	SP	CRE	ED,ID,RB		BX	7/13/2095
2020 PO3928982492	LGE	3	50 BRN	SP	CRE	ED,ID		VX	7/14/2095
2020 PO3929282496	F	3	45 BRN	SP	CRE			V	7/15/2095
2020 PO7240089522	KU	4	40 BRO	SP	CRE			V	7/16/2095
2020 PO7247089466	KU	5	35 BRO	SP	CRE	ED,ID		TD	7/17/2095
2020 PO7256889417	KU	6	30 BRO	SP	CRE	ED,ID		TD	7/18/2095
2020 PO6392404471	KU	4	40 OTH	SP	CRE			V	7/19/2095
2020 PO6376004628	KU	4	40 OTH	SP	CRE			V	7/20/2095
2020 PO9486894846	KU	5	35 ACW	SP	CRE	ED,ID		TD	7/21/2095
2020 PO6361404765	KU	4	40 OTH	SP	CRE			V	7/22/2095
2020 PO6345004920	KU	4	40 OTH	SP	CRE			V	7/23/2095
2020 PO6318104985	KU	4	40 OTH	SP	CRE			V	7/24/2095
2020 PO6282505080	KU	4	40 OTH	SP	CRE			V	7/25/2095
2020 PO6255605144	KU	5	35 OTH	SP	CRE			V	7/26/2095

2020 PO3220642385	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD			7/27/2095
2020 PO6914420125	KU	5	35 XXX	SP	CRE	ID	TD			7/28/2095
2020 PO6902819925	KU	4	40 XXX	SP	CRE	ID	TD			7/29/2095
2020 PO6893919784	F	4	40 XXX	SP	CRE		V			7/30/2095
2020 PO6900619808	KU	4	40 XXX	SP	CRE	ID	TD			7/31/2095
2020 PO6912019554	KU	6	30 XXX	SP	CRE	ID	TD			8/1/2095
2020 PO6892619550	KU	4	40 XXX	SP	CRE	EP,ID	TX	RR		8/2/2095
2020 PO6887219362A	KU	5	30 XXX	SP	CRE	ID	TD			8/3/2095
2020 PO6887219362	KU	4	40 XXX	SP	CRE	ID	TD			8/4/2095
2020 PO6878119114	KU	4	40 XXX	SP	CRE	ID	TD			8/5/2095
2020 PO6881819063	KU	4	40 XXX	SP	CRE	ID	TD			8/6/2095
2020 PO6873618434A	KU	5	30 XXX	SP	CRE	ID	BD			8/7/2095
2020 PO9471494826	KU	6	30 ACW	SP	CRE	ED,ID	TD			8/8/2095
2020 PO9482394975	KU	5	35 ACW	SP	CRE	ED,ID	BD			8/9/2095
2020 PO9350594552	C	4	40 ACW	SP	CRE		V			8/10/2095
2020 PO9344694417	KU	3	45 ACW	SP	CCA		V			8/11/2095
2020 PO9363294441	KU	6	30 ACW	SP	S		V			8/12/2095
2020 PO9329794794	KU	5	35 ACW	SP	CRE		V			8/13/2095
2020 PO9320994609	KU	4	40 ACW	SP	CRE	ED,ID	TD			8/14/2095
2020 PO9362794632	KU	6	30 ACW	SP	S		V			8/15/2095
2020 PO4826727630	C	4	40 BRO	SP	A		V			8/16/2095
2020 PO4812127696	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			8/17/2095
2020 PO4822927843	KU	4	40 BRO	SP	CRE	ED,ID	TD			8/18/2095
2020 PO4824227958	KU	6	30 BRO	SP	CRE		V			8/19/2095
2020 PO4809928210	KU	4	50 BRO	SP	CRE		V			8/20/2095
2020 PO4804127891	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD			8/21/2095
2020 PO4792028238	F	3	45 BRO	SP	A		V			8/22/2095
2020 PO6873618434	KU	4	40 XXX	SP	CRE	ID,IP	TD			8/23/2095
2020 PO6882118393	KU	6	30 XXX	SP	CCA		V			8/24/2095
2020 PO6854118469	KU	6	30 XXX	SP	CRE		V			8/25/2095
2020 PO6866018186	KU	4	40 XXX	SP	CRE	HH,IP	X	RP2		8/26/2095
2020 PO6860918225	KU	6	30 XXX	SP	CRE		V			8/27/2095
2020 PO686891967A	KU	5	40 XXX	SP	CRE	ID	TD			8/28/2095
2020 PO6876019248	KU	6	30 XXX	SP	CRE	HH,ID,IP	TX	RR		8/29/2095
2020 PO6868919167	KU	5	35 XXX	SP	CRE	ID	TD			8/30/2095
2020 PO6869318895	KU	4	40 XXX	SP	CRE	ID	TD			8/31/2095
2020 PO6876218763	KU	4	35 XXX	SP	CRE		V			9/1/2095
2020 PO6842418692	KU	4	45 XXX	SP	CRE		V			9/2/2095
2020 PO6845319052	KU	6	30 XXX	SP	CRE		V			9/3/2095
2020 PO6845418900	KU	4	40 XXX	SP	CRE	ID	TD			9/4/2095
2020 PO6864519279	KU	6	30 XXX	SP	CRE	HH,RB	X	PX		9/5/2095
2020 PO6864019177	KU	5	35 XXX	SP	CRE	ID	TD			9/6/2095
2020 PO6863219109A	KU	5	35 XXX	SP	CCA		V			9/7/2095
2020 PO4803328573	KU	4	40 BRO	SP	A	ED,ID	TD			9/8/2095
2020 PO4813128372	KU	4	40 BRO	SP	A	ED,ID	TD			9/9/2095
2020 PO4813128372-A	KU	4	35 BRO	SP	A	ED,ID	TD			9/10/2095
2020 PO4832628502	KU	4	45 BRO	SP	CRE	ED,ID	TD			9/11/2095

2020 PO4842628385	KU	4	40 BRO	SP	CRE	ID	BD	9/12/2095
2020 PO4832628719	F	4	45 BRO	SP	CCA		V	9/13/2095
2020 PO9474293664	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/14/2095
2020 PO9479293552	KU	5	45 BRN	SP	CRE	ED,ID	TD	9/15/2095
2020 PO5707447366	F	4	40 ACE	SP	CRE		V	9/16/2095
2020 PO5715047253	F	4	40 ACE	SP	P		V	9/17/2095
2020 PO5725547098	F	4	40 ACE	SP	P		V	9/18/2095
2020 PO5735246916	F	4	40 ACE	SP	P		V	9/19/2095
2020 PO9406693807	KU	6	30 BRN	SP	CRE	ED,ID	TD	9/20/2095
2020 PO5689346624	KU	3	45 ACE	SP	CCA		V	9/21/2095
2020 PO5671146628	F	4	40 ACE	SP	CRE		V	9/22/2095
2020 PO9402793879	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/23/2095
2020 PO9398293832	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/24/2095
2020 PO9378693813	KU	4	40 BRN	SP	CRE	ED,ID	TD	9/25/2095
2020 PO5675046553	KU	6	30 ACE	SP	CRE	ED,ID	TD	9/26/2095
2020 PO5682946688	F	4	40 ACE	SP	CRE		V	9/27/2095
2020 PO5681046678	F	4	40 ACE	SP	CRE		V	9/28/2095
2020 PO5704346455	KU	6	30 ACE	SP	CCA		V	9/29/2095
2020 PO5659446572	F	4	40 ACE	SP	CRE		V	9/30/2095
2020 PO5646946519	F	4	40 ACE	SP	CRE		V	10/1/2095
2020 PO5711946246	F	6	30 ACE	SP	P		V	10/2/2095
2020 PO5703246176	F	6	30 ACE	SP	P		V	10/3/2095
2020 PO5692946089	F	6	30 ACE	SP	P		V	10/4/2095
2020 PO4898429577	KU	3	45 BRO	SP	CCA		V	10/5/2095
2020 PO4878629425	KU	3	45 BRO	SP	CCA		V	10/6/2095
2020 PO4848329191	KU	3	45 BRO	SP	CCA		V	10/7/2095
2020 PO6278104217	KU	4	40 XXX	SP	CRE	ED,ID	TD	10/8/2095
2020 PO3953682363	LGE	4	40 BRN	SP	CRE	ED,ID	TD	10/9/2095
2020 PO3953582352	LGE	4	40 BRN	SP	S		V	10/10/2095
2020 PO1160721103	F	4	40 XXX	SP	CRE		V	10/11/2095
2020 PO1063020378	F	4	40 XXX	SP	P		V	10/12/2095
2020 PO1068720544	F	4	40 XXX	SP	A		V	10/13/2095
2020 PO1046420646	F	4	40 XXX	SP	A		V	10/14/2095
2020 PO1050320879	F	4	40 XXX	SP	CRE		V	10/15/2095
2020 PO1044621118	F	4	40 XXX	SP	A		V	10/16/2095
2020 PO1164921050	ODP	4	40 BRN	SP	CCA	ED,SRS	TD	10/17/2095
2020 PO1141721127	ODP	4	40 KOP	SP	CRE	ID	TD	10/18/2095
2020 PO1160421385	ODP	3	45 BRN	SP	CCA		V	10/19/2095
2020 PO1156620972	ODP	4	40 BRN	SP	CCA	ED,SRS	TD	10/20/2095
2020 PO1138221011	ODP	6	30 BRN	SP	CCA	ED,SRS	TD	10/21/2095
2020 PO1155221192	ODP	4	40 UNK	SP	CRE	ID	TD	10/22/2095
2020 PO0876473643	KU	6	30 BRN	SP	P	ED	T	10/23/2095
2020 PO0925373980	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD	10/24/2095
2020 PO0726152990	KU	4	40 BRN	SP	CCA		V	10/25/2095
2020 PO0762152840	KU	4	40 BRN	SP	CCA		V	10/26/2095
2020 PO1781550075	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	10/27/2095
2020 PO1840049219	KU	4	45 BRN	SP	CRE	ID,IP	TD	10/28/2095

2020 PO0782452641	KU	4	40 BRN	SP	CRE	ED,ID,SRC	TD	10/29/2095	
2020 PO0771652735	KU	5	35 BRN	SP	CRE	ED,ID,SRC	TD	10/30/2095	
2020 PO0383961234	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	10/31/2095	
2020 PO1847748892	KU	5	35 BRN	SP	CRE	ID,IP	TD	11/1/2095	
2020 PO1863548150	KU	5	35 BRN	SP	CRE	ID,IP	BD	11/2/2095	
2020 PO0855473802	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	11/3/2095	
2020 PO0841973572	KU	4	40 BRN	SP	CRE	ID,IP	BD	11/4/2095	
2020 PO0315862182	KU	6	30 ACW	SP	CRE	ED,ID	TD	11/5/2095	
2020 PO0875374706	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	11/6/2095	
2020 PO0325861802	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	11/7/2095	
2020 PO1095720962	ODP	5	35 UNK	SP	CRE	ED,ID,IP	TX	RR	11/8/2095
2020 PO3969282588	F	4	35 BRN	SP	CRE		V	11/9/2095	
2020 PO3969082579	F	4	45 BRN	SP	A		V	11/10/2095	
2020 PO4627208738	F	4	40 ACE	SP	CRE		V	11/11/2095	
2020 PO3967082585	LGE	4	35 BRN	SP	S		V	11/12/2095	
2020 PO3967182577	F	4	40 BRN	SP	CRE		V	11/13/2095	
2020 PO1222331290A	ODP	5	35 XXX	SP	CRE	ID,IP	TX	RR	11/14/2095
2020 PO1198031538	ODP	4	40 XXX	SP	CRE	ID	TD	11/15/2095	
2020 PO3964882575	F	4	40 BRN	SP	CRE		V	11/16/2095	
2020 PO1586721233	ODP	4	40 XXX	SP	CRE		V	11/17/2095	
2020 PO1618121193	ODP	4	40 XXX	SP	CRE	ID	TD	11/18/2095	
2020 PO1630821139	ODP	4	40 XXX	SP	CRE	ID	TD	11/19/2095	
2020 PO1639621042	ODP	6	30 XXX	SP	CRE	ID	TD	11/20/2095	
2020 PO1652521136	ODP	4	40 XXX	SP	CCA		V	11/21/2095	
2020 PO4662209466	F	4	40 ACE	SP	P		V	11/22/2095	
2020 PO4672809429	F	4	40 ACE	SP	P		V	11/23/2095	
2020 PO4684509382	F	4	40 ACE	SP	CCA		V	11/24/2095	
2020 PO4678209097	F	4	40 ACE	SP	P		V	11/25/2095	
2020 PO7250688686	F	3	40 BRO	SP	CRE		V	11/26/2095	
2020 PO1376176298	KU	4	40 BRN	SP	CRE	HH,ID,RB	X	RP1	11/27/2095
2020 PO6435903467	KU	4	40 KOP	SP	CRE	ED,ID	TD	11/28/2095	
2020 6425503468a	KU	6	30 KOP	SP	CCA		V	11/29/2095	
2020 PO6425503389	KU	6	30 XXX	SP	CRE	ID	BD	11/30/2095	
2020 PO6425503468	KU	4	40 XXX	SP	CRE	ID	BD	12/1/2095	
2020 PO6415803397	F	4	40 KOP	SP	CRE		V	12/2/2095	
2020 PO6415103494	KU	4	40 XXX	SP	CRE	ID	BD	12/3/2095	
2020 PO6404103506	KU	4	40 KOP	SP	CRE	ED,ID	TD	12/4/2095	
2020 PO6390903535	KU	4	40 XXX	SP	CRE	ED,ID	TD	12/5/2095	
2020 PO6383703437	KU	5	30 XXX	SP	CRE	ED,ID	TD	12/6/2095	
2020 PO6311506998	KU	5	35 BRN	SP	CRE		V	12/7/2095	
2020 PO7125901897A	KU	3	45 BRN	SP	CCA		V	12/8/2095	
2020 PO7074601496	F	4	40 BRN	SP	CRE		V	12/9/2095	
2020 PO7084901616	KU	3	45 BRN	SP	CRE		V	12/10/2095	
2020 PO7091801731	F	4	40 XXX	SP	CCA		V	12/11/2095	
2020 PO7218088922	KU	3	50 BRO	SP	CRE		V	12/12/2095	
2020 PO7221488870	KU	4	40 BRO	SP	CRE	ED,ID	TD	12/13/2095	
2020 PO7227688829	KU	4	40 BRO	SP	CRE	ED,ID	BD	12/14/2095	

Business Use

2020 PO7141489366	KU	4	35 BRN	SP	CCA		BD	12/15/2095
2020 PO2109347722	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	12/16/2095
2020 PO2111346982	KU	4	40 ACE	SP	CCA		V	12/17/2095
2020 PO7371391586	KU	5	35 BRO	SP	CRE	ED	VX	12/18/2095
2020 PO2122648035	KU	4	40 ACE	SP	CCA	MD	V	12/19/2095
2020 PO0741377997	F	4	40 BRN	SP	CRE		V	12/20/2095
2020 PO0738577914	KU	5	35 BRN	SP	CRE		V	12/21/2095
2020 PO0567646690	KU	4	40 BRN	SP	CCA		V	12/22/2095
2020 PO0613148007	KU	4	40 BRN	SP	CRE		V	12/23/2095
2020 PO0703177664	KU	4	45 BRN	SP	P	ED	T	12/24/2095
2020 PO0740077840	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	12/25/2095
2020 PO0593447925	KU	4	40 BRN	SP	CRE	ED,ID,IP,SRC	TD	12/26/2095
2020 PO0569748111	KU	6	30 BRN	SP	CRE	ED,ID,SRC	TD	12/27/2095
2020 PO0577049629	KU	4	40 BRN	SP	CRE	ID	BD	12/28/2095
2020 PO0545649341	KU	4	40 BRN	SP	CRE	ID	BD	12/29/2095
2020 PO0520549980	KU	4	40 BRN	SP	CRE	ID	BD	12/30/2095
2020 PO0567646690-A	KU	4	40 BRN	SP	CCA		V	12/31/2095
2020 PO0769877988	KU	4	40 BRN	SP	CRE	ID,IP	BD	1/1/2096
2020 PO0770378139	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD	1/2/2096
2020 PO0770878209	F	4	40 BRN	SP	CCA		V	1/3/2096
2020 PO0659577035	KU	4	40 BRN	SP	CCA		V	1/4/2096
2020 PO1194776406	KU	3	50 BRN	SP	CRE	ID	BD	1/5/2096
2020 PO1186276237	KU	3	50 BRN	SP	CRE	ID	BD	1/6/2096
2020 PO1206376400	KU	2	50 BRN	SP	CCA		V	1/7/2096
2020 PO1174876037	KU	3	50 BRN	SP	CRE		V	1/8/2096
2020 PO1166675882	KU	3	50 BRN	SP	CRE		V	1/9/2096
2020 PO1056274717	KU	3	50 BRN	SP	CRE	ED	TD	1/10/2096
2020 PO1040174727	KU	3	50 BRN	SP	CRE	ED,ID,IP	TD	1/11/2096
2020 PO1398460735	KU	6	30 BRN	SP	CRE		V	1/12/2096
2020 PO1497660086	KU	4	40 BRN	SP	CRE	ID,IP	BD	1/13/2096
2020 PO1532059728	KU	5	30 BRN	SP	CRE	ED,ID,IP	TD	1/14/2096
2020 PO1591559369	KU	5	35 BRN	SP	A		V	1/15/2096
2020 PO1604759293	KU	6	30 BRN	SP	CRE	ID,IP	BD	1/16/2096
2020 PO1614059742	KU	4	45 BRN	SP	CRE	ED,ID,IP	TD	1/17/2096
2020 PO7421892259	F	4	40 BRO	SP	CRE	ID	VX	1/18/2096
2020 PO7427192324	F	4	40 BRO	SP	CCA		V	1/19/2096
2020 PO7431992385	F	3	45 BRO	SP	CRE		V	1/20/2096
2020 PO7439992469	F	3	45 BRO	SP	CRE		V	1/21/2096
2020 PO7446492575	F	3	45 BRO	SP	CRE		V	1/22/2096
2020 PO7455692693	F	3	45 BRO	SP	CRE		V	1/23/2096
2020 PO7464992811	F	4	40 BRO	SP	CRE		V	1/24/2096
2020 PO7475892926	F	3	45 BRO	SP	CRE		V	1/25/2096
2020 PO7477592968	F	3	45 BRO	SP	CRE		V	1/26/2096
2020 PO7494093181	F	4	40 BRO	SP	CRE		V	1/27/2096
2020 PO7484393057	F	4	40 BRO	SP	CRE	ID	VX	1/28/2096
2020 PO5425512741	KU	6	30 BRO	SP	CCA		V	1/29/2096
2020 Po5430312641a	KU	5	35 BRO	SP	CCA		V	1/30/2096

2020 PO5430912903	KU	5	35 BRO	SP	CRE			V	1/31/2096
2020 PO5430312649	KU	4	40 BRO	SP	CRE	ID		BD	2/1/2096
2020 PO5435313084	KU	4	40 BRO	SP	CRE	ID		TD	2/2/2096
2020 PO1198431049	F	4	40 BRN	SP	A			V	2/3/2096
2020 PO1137728319	ODP	4	45 BRN	SP	CCA			V	2/4/2096
2020 PO1301029814	F	4	40 XXX	SP	P			V	2/5/2096
2020 PO1325229880	F	4	40 XXX	SP	A			V	2/6/2096
2020 PO1779023012	F	4	35 XXX	SP	A			V	2/7/2096
2020 PO1266130346	F	5	35 XXX	SP	CRE			V	2/8/2096
2020 PO5417013016	KU	4	40 BRO	SP	CRE	ID		TD	2/9/2096
2020 PO5411013088	KU	6	30 BRO	SP	CRE	ID		TD	2/10/2096
2020 PO5409613229	KU	4	40 BRO	SP	CCA			V	2/11/2096
2020 PO5408513250	KU	6	30 BRO	SP	CCA			V	2/12/2096
2020 5445413866a	KU	4	40 BRO	SP	CRE	ID		TD	2/13/2096
2020 PO5434513340a	KU	4	40 BRO	SP	CRE	ID		TD	2/14/2096
2020 PO5432113380	KU	5	35 BRO	SP	CRE	ID		TD	2/15/2096
2020 PO5434513340	KU	4	45 BRO	SP	CCA			V	2/16/2096
2020 PO5430413516	KU	6	30 BRO	SP	CCA			V	2/17/2096
2020 PO5435813582	KU	4	35 BRO	SP	CCA			V	2/18/2096
2020 PO5444313588	KU	4	40 BRO	SP	CRE	ID		BD	2/19/2096
2020 PO5443413554	KU	6	30 BRO	SP	CRE	ID		TD	2/20/2096
2020 PO5442613519	KU	6	30 BRO	SP	CRE	ID		TD	2/21/2096
2020 PO5441513427	KU	5	35E BRO	SP	CRE	ID		TD	2/22/2096
2020 PO5445413866	KU	4	40 BRO	SP	CCA			V	2/23/2096
2020 PO5460914123	KU	4	40 BRO	SP	CCA			V	2/24/2096
2020 PO5461814295	KU	4	40 BRO	SP	CCA			V	2/25/2096
2020 PO5474014569	KU	4	40 BRO	SP	CCA			V	2/26/2096
2020 PO5481414533	KU	4	40 BRO	SP	CCA			V	2/27/2096
2020 PO5479414784	KU	4	40 BRO	SP	CCA			V	2/28/2096
2020 PO5491914909	KU	4	40 BRO	SP	CCA			V	2/29/2096
2020 PO5493715021	KU	5	35 BRO	SP	CCA			V	3/1/2096
2020 PO5483415046	KU	4	40 BRO	SP	CCA			V	3/2/2096
2020 PO5489315334	KU	4	45 BRO	SP	CCA			V	3/3/2096
2020 PO5810611177	KU	5	35 BRO	SP	CRE	ID		TD	3/4/2096
2020 PO5819211313	KU	5	35 BRO	SP	CRE	ID		TD	3/5/2096
2020 PO5829411493	KU	5	35 BRO	SP	CRE	ID		TD	3/6/2096
2020 PO5803511424	KU	4	40 BRO	SP	CRE	ID		TD	3/7/2096
2020 PO5795411440	KU	6	30 BRO	SP	CCA			V	3/8/2096
2020 PO5798211538	KU	6	30 BRO	SP	CRE	ID		TD	3/9/2096
2020 PO5783911511	KU	6	30 BRO	SP	CRE	ID		TD	3/10/2096
2020 PO5784711436	KU	6	30 BRO	SP	CRE	ID		TD	3/11/2096
2020 PO5770611468	KU	6	30 BRO	SP	CRE	ID		BD	3/12/2096
2020 PO5770511346	KU	4	40 BRO	SP	CCA			V	3/13/2096
2020 PO5770511346B	KU	4	40 BRO	SP	CCA			V	3/14/2096
2020 PO5770511346a	KU	4	40 BRO	SP	CCA			V	3/15/2096
2020 PO5778411268	KU	4	40 BRO	SP	CRE			V	3/16/2096
2020 PO5773411182	KU	6	30 BRO	SP	CRE			V	3/17/2096

2020 PO5769411063	KU	6	30 BRO	SP	CRE	ID	BD		3/18/2096
2020 PO5751511328	KU	4	40 BRO	SP	CCA		V		3/19/2096
2020 PO5742111345	KU	6	30 BRO	SP	CCA		V		3/20/2096
2020 PO5742211152	KU	4	45 BRO	SP	CRE		V		3/21/2096
2020 PO5739011098	KU	5	35 BRO	SP	CCA		V		3/22/2096
2020 PO5737411285	KU	6	30 BRO	SP	CCA		V		3/23/2096
2020 PO5721011173	KU	6	30 BRO	SP	CCA		V		3/24/2096
2020 PO0599517057	KU	5	35 BRO	SP	CRE	ID	TD		3/25/2096
2020 PO0624817379	KU	4	40 BRO	SP	CCA		V		3/26/2096
2020 PO0609517170	KU	4	40 BRO	SP	CCA		V		3/27/2096
2020 PO0633017276	KU	4	40 BRO	SP	CRE	ID	TD		3/28/2096
2020 PO0639817395	KU	6	30 BRO	SP	CRE	ID	TD		3/29/2096
2020 PO0645117493	KU	6	30 BRO	SP	CCA		V		3/30/2096
2020 PO0536316776	F	4	40 BRO	SP	CCA		V		3/31/2096
2020 PO0533516865	KU	6	30 BRO	SP	CCA		V		4/1/2096
2020 PO0520516560	KU	2	55 BRO	SP	CCA		V		4/2/2096
2020 PO0528616732	KU	4	40 BRO	SP	CRE	ID	TD		4/3/2096
2020 PO0497816548	KU	5	35 BRO	SP	CRE	ID	TD		4/4/2096
2020 PO0516216640	KU	5	35 BRO	SP	CCA		V		4/5/2096
2020 PO0464016620	KU	5	35 BRO	SP	CRE	ID	TD		4/6/2096
2020 PO0471716542	KU	4	40 BRO	SP	CRE	ID	TD		4/7/2096
2020 PO046416558	KU	5	35 BRO	SP	CRE	ID	TD		4/8/2096
2020 PO0428316577	KU	4	40 BRO	SP	CRE	ID	TD		4/9/2096
2020 PO3935482568	LGE	2H	45 BRN	SP	A	ED,ID	TD		4/10/2096
2020 PO3936682560	LGE	4	35 BRN	SP	P	ED,ID	TD		4/11/2096
2020 PO3938982552	LGE	3	35 BRN	SP	CRE		V		4/12/2096
2020 PO3938782552	LGE	2H	45 BRN	SP	P	ED,ID	TD		4/13/2096
2020 PO3938182555	LGE	4	35 BRN	SP	P	ED,ID	TD		4/14/2096
2020 PO3937682546	LGE	2H	45 BRN	SP	P	ED,ID	TD		4/15/2096
2020 PO3993583051	LGE	6	25 BRN	SP	CRE		VX	RP3	4/16/2096
2020 PO3993383059	LGE	4	40 BRN	SP	CRE	ED,ID	BD		4/17/2096
2020 PO3994183065	LGE	4	40 BRN	SP	CRE	ED,ID	TD		4/18/2096
2020 PO3994783061	LGE	4	30 BRN	SP	S		V		4/19/2096
2020 PO3937782536	LGE	4	45 BRN	SP	P	ED,ID	TD		4/20/2096
2020 PO3937482540	LGE	4	35 BRN	SP	P	ED,ID	TD		4/21/2096
2020 PO3936182546	LGE	4	35 BRN	SP	CRE	ED,ID	TD		4/22/2096
2020 PO3935382550	F	4	40 BRN	SP	CRE		V		4/23/2096
2020 PO3995083076	LGE	4	40 BRN	SP	A	ED,ID	TD		4/24/2096
2020 PO4718615056	KU	5	35 BRO	SP	CRE	HH,RB	X	RP1	4/25/2096
2020 6331704449D	KU	3	40 BRN	SP	CCA		V		4/26/2096
2020 6326704587A	KU	3	50 BRN	SP	CCA		V		4/27/2096
2020 PO6322204708	F	4	40 BRN	SP	CRE		V		4/28/2096
2020 PO6296904717	KU	5	35 BRN	SP	CRE		V		4/29/2096
2020 PO3887682920	LGE	4	45 BRO	SP	CRE	ED,HH,ID,RB	BX	RP1	4/30/2096
2020 PO3887082929	LGE	4	35 BRO	SP	CRE	ED,ID,IP,RB	TD		5/1/2096
2020 PO3885982929	LGE	4	35 BRO	SP	P	ED,ID	TD		5/2/2096
2020 PO6365604194	KU	6	30 BRN	SP	CRE		V		5/3/2096

2020 PO1576437895	ODP	6	30 BRN	SP	CRE	ED,ID	TD	5/4/2096	
2020 PO1580637917	F	4	40 KOP	SP	CRE		V	5/5/2096	
2020 PO1584137868	ODP	4	40 KOP	SP	CRE	ED,HH,ID,IP	TX	RR	5/6/2096
2020 PO1601438004	ODP	5	35 UNK	SP	CRE	ED,ID	TD	5/7/2096	
2020 PO1588437977	ODP	6	30 UNK	SP	CRE	ED,ID	TD	5/8/2096	
2020 6353904018A	KU	3	45 BRN	SP	CCA		V	5/9/2096	
2020 6353904018B	KU	3	45 BRN	SP	S		V	5/10/2096	
2020 6331704449B	KU	3	45 BRN	SP	CCA		V	5/11/2096	
2020 6331704449C	KU	3	45 BRN	SP	CCA		V	5/12/2096	
2020 6350004391A	KU	6	30 KOP	SP	CCA		V	5/13/2096	
2020 6331704449A	KU	3	45 BRN	SP	CCA		V	5/14/2096	
2020 6341004640B	KU	6	30 OTH	SP	CRE	ID	TD	5/15/2096	
2020 6341004640A	KU	4	40 UNK	SP	CRE	ED,ID,SRS	TD	5/16/2096	
2020 PO6347704110	KU	3	45 BRN	SP	CCA		V	5/17/2096	
2020 PO6336304739	F	6	30 OTH	SP	CRE		V	5/18/2096	
2020 PO6366304631	KU	6	30 ACW	SP	CRE	ED,ID,SRS	TD	5/19/2096	
2020 PO6362704439	F	4	40 CPT	SP	CRE		V	5/20/2096	
2020 PO6375703875	F	4	40 BRN	SP	S		V	5/21/2096	
2020 PO6350004391	F	4	40 ACW	SP	CRE		V	5/22/2096	
2020 PO6369404462	F	4	40 ACW	SP	CRE		V	5/23/2096	
2020 PO6371703989	F	5	35 OTH	SP	P		V	5/24/2096	
2020 PO6370304244	KU	6	25 OTH	SP	CRE	ED,ID,SRS	TD	5/25/2096	
2020 PO6357104672	F	5	35 KOP	SP	CCA		V	5/26/2096	
2020 PO6331704449	KU	3	45 BRN	SP	S		V	5/27/2096	
2020 PO1192237122	ODP	4	40 OTH	SP	CRE		V	5/28/2096	
2020 PO1185336972	F	4	40 OTH	SP	A		V	5/29/2096	
2020 PO1185236846	F	3	45 OTH	SP	CRE		V	5/30/2096	
2020 PO1183436639	F	3	45 OTH	SP	A		V	5/31/2096	
2020 PO1178736465	F	4	40 OTH	SP	P		V	6/1/2096	
2020 PO3227829227	ODP	4	40 BRO	SP	CRE	ID	BD	6/2/2096	
2020 PO3244529411	ODP	4	40 BRO	SP	CRE	ID	TD	6/3/2096	
2020 PO3263529621	ODP	4	45 BRO	SP	CCA		V	6/4/2096	
2020 PO3284829923	ODP	4	40 BRO	SP	CCA		V	6/5/2096	
2020 PO1148336364	ODP	6	30 OTH	SP	CCA		V	6/6/2096	
2020 PO2372453111	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/7/2096	
2020 PO2442052650	KU	4	40 BRO	SP	P	ED	T	6/8/2096	
2020 PO1222533969	ODP	2	55 XXX	SP	CRE	ED,ID	TD	6/9/2096	
2020 PO1231933949	ODP	4	40 XXX	SP	CRE	ED,ID	TD	6/10/2096	
2020 PO1244533920	ODP	2	65 XXX	SP	CRE	ED,ID	TD	6/11/2096	
2020 PO1255833899	ODP	2	65 XXX	SP	CRE	ED,ID	BD	6/12/2096	
2020 PO1271633941	ODP	2	50 XXX	SP	CRE	ED,ID	TD	6/13/2096	
2020 PO1154036441	F	5	35 OTH	SP	CCA		V	6/14/2096	
2020 PO1161336466	ODP	3	45 OTH	SP	A		V	6/15/2096	
2020 PO3994582895	F	4	40 BRN	SP	CRE		V	6/16/2096	
2020 PO3876082822	LGE	4	35 BRO	SP	CCA		V	6/17/2096	
2020 PO3875282694	LGE	4	40 BRO	SP	CCA		V	6/18/2096	
2020 PO1200637239	F	4	40 BRN	SP	CRE		V	6/19/2096	

2020 PO3978683049	LGE	6	25 BRN	SP	CRE	ED,ID,IP,RB	TX	RR	6/20/2096
2020 PO3993182893	F	4	40 BRN	SP	CRE		V		6/21/2096
2020 PO1186737275	F	4	40 BRN	SP	CRE		V		6/22/2096
2020 PO1174937306	F	4	40 BRN	SP	CRE	ED,ID	VX	RP1	6/23/2096
2020 PO3991882892	F	4	40 BRN	SP	CRE		V		6/24/2096
2020 PO1166637326	F	4	40 BRN	SP	CRE		V		6/25/2096
2020 PO1160037295	F	4	40 BRN	SP	P	ED,ID	VX	RP1	6/26/2096
2020 PO1156437141	F	4	40 BRN	SP	CRE		V		6/27/2096
2020 PO3989382889	F	4	40 BRN	SP	CRE		V		6/28/2096
2020 PO3988182887	F	4	40 BRN	SP	CRE		V		6/29/2096
2020 PO3877182730	LGE	1	65 BRO	SP	A		V		6/30/2096
2020 PO3876882708	LGE	1	65 BRO	SP	A		V		7/1/2096
2020 PO3876682695	LGE	1	50 BRO	SP	A		V		7/2/2096
2020 PO3876882681	LGE	3	45 BRO	SP	CCA		V		7/3/2096
2020 PO3877182700	LGE	4	40 BRO	SP	CRE	ED,HH,ID,RB	X	RP2	7/4/2096
2020 PO3877482753	LGE	1	65 BRO	SP	A	ED	VX	RP2	7/5/2096
2020 PO3876482722	LGE	4	40 BRO	SP	P	ED,ID	BD		7/6/2096
2020 PO3302230124	ODP	4	40 BRO	SP	CCA		V		7/7/2096
2020 PO3320830316	ODP	3	45 BRO	SP	CCA		V		7/8/2096
2020 PO3320530461	ODP	5	35 BRO	SP	CRE	ID	TD		7/9/2096
2020 PO3350630713	ODP	5	35 BRO	SP	CRE	ID	TD		7/10/2096
2020 PO3375630744	F	5	35 BRO	SP	A		V		7/11/2096
2020 PO3309629406	ODP	4	40 BRO	SP	CRE	ID	TD		7/12/2096
2020 PO3331329820	ODP	4	40 BRO	SP	CRE	ID	TD		7/13/2096
2020 PO3986982885	F	4	40 BRN	SP	CRE		V		7/14/2096
2020 PO2460152856	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD		7/15/2096
2020 PO3985582883	F	3	45 BRN	SP	CCA		V		7/16/2096
2020 PV3983882882	F	4	40 BRN	SP	CRE		V		7/17/2096
2020 PO1605738107	F	5	35 KOP	SP	P		V		7/18/2096
2020 PO1608038179	ODP	5	30 BRN	SP	CRE	ED,ID	TD		7/19/2096
2020 PO1611238081	ODP	5	35 BRN	SP	CRE	ED,ID	TD		7/20/2096
2020 PO1630638234	ODP	4	40 BRN	SP	CRE	ED,ID	TX	RR	7/21/2096
2020 PO1619938219	F	4	40 KOP	SP	P	ED,HH,ID	BX	RP1	7/22/2096
2020 PO1627338283	F	5	35 KOP	SP	CRE		V		7/23/2096
2020 PO1639338407	F	5	35 APL	SP	P		V		7/24/2096
2020 PO1656238514	F	5	40 KOP	SP	P		V		7/25/2096
2020 PO1678338623	ODP	6	30 KOP	SP	CRE	ED,ID	TD		7/26/2096
2020 PO1672738579	ODP	4	45 BRN	SP	CCA		V		7/27/2096
2020 PO1663738404	ODP	5	35 BRN	SP	CCA	ED,ID	TD		7/28/2096
2020 PO1644738347	ODP	5	35 BRN	SP	CRE	ED,ID	TD		7/29/2096
2020 PO1630838079	ODP	6	30 BRN	SP	CRE	ED,ID	TD		7/30/2096
2020 PO1637438133	F	4	40 APL	SP	CRE		V		7/31/2096
2020 PO1647737993	F	4	40 APL	SP	CRE		V		8/1/2096
2020 PO1648137885	ODP	4	40 UNK	SP	CRE	ED,ID	TD		8/2/2096
2020 PO1631837884	ODP	4	40 BRN	SP	CCA		V		8/3/2096
2020 PO1636537922	ODP	6	30 UNK	SP	CRE	ED,ID	TD		8/4/2096
2020 PO1664138109	ODP	6	30 KOP	SP	CRE	ED,ID	TD		8/5/2096

2020 PO1657538256	ODP	6	30 UNK	SP	CRE	ED,ID	TD	8/6/2096	
2020 PO1656238127	F	4	40 UNK	SP	CRE		V	8/7/2096	
2020 PO1667838210	ODP	5	35 UNK	SP	CRE	ED,ID,SRC	TD	8/8/2096	
2020 PO1687138176	ODP	6	30 BRN	SP	CRE		V	8/9/2096	
2020 PO1673238249	ODP	5	35 UNK	SP	CRE	ED,ID	TD	8/10/2096	
2020 PO1679738296	ODP	5	35 UNK	SP	CRE	ED,ID	TD	8/11/2096	
2020 PO1163836667	F	4	40 BRN	SP	CRE		V	8/12/2096	
2020 PO3979282811	F	4	40 BRN	SP	A		V	8/13/2096	
2020 PO1164036691	ODP	4	40 BRN	SP	CRE		V	8/14/2096	
2020 PO3980882814	F	4	40 BRN	SP	CRE		V	8/15/2096	
2020 PO3877682736	LGE	4	40 BRO	SP	P	ED,ID	TD	8/16/2096	
2020 PO1043133988	ODP	2	60 BRN	SP	CRE	ED,EP,HH,ID,RB,SRC	X	PX	8/17/2096
2020 PO2425852031	KU	4	40 BRO	SP	CRE	ID,IP	BD	8/18/2096	
2020 PO2448652891	KU	4	40 BRO	SP	CRE	ID,IP	BD	8/19/2096	
2020 PO1256937785	ODP	4	45 KOP	SP	CCA		V	8/20/2096	
2020 PO3980482847	F	4	40 BRN	SP	CCA		V	8/21/2096	
2020 PO3978982845	F	3	45 BRN	SP	S		V	8/22/2096	
2020 PO1202637057	ODP	5	30 XXX	SP	CRE	ED,ID	TD	8/23/2096	
2020 PO1197336648	ODP	5	30 XXX	SP	CRE	ID	BX	RP2	8/24/2096
2020 PO1287433992	ODP	2	55 KOP	SP	CRE	ED,ID	BD	8/25/2096	
2020 PO1307234058	ODP	2	50 KOP	SP	CRE	ED,ID,MD	TD	8/26/2096	
2020 PO3913782185	F	4	40 BRN	SP	CRE		V	8/27/2096	
2020 PO6331333404	LGE	3	45 BRN	SP	CCA		V	8/28/2096	
2020 PO3913282187	F	3	45 BRN	SP	CCA		V	8/29/2096	
2020 PO2852952405	KU	4	45 BRO	SP	CRE		V	8/30/2096	
2020 PO3000951380	KU	3	45 BRO	SP	CRE		V	8/31/2096	
2020 PO3987982776	LGE	4	40 BRN	SP	P	ED,ID	TD	9/1/2096	
2020 PO3911682193	F	4	40 BRN	SP	CRE		V	9/2/2096	
2020 PO3910882196	F	4	40 BRN	SP	CCA		V	9/3/2096	
2020 PO3909182203	LGE	3	45 BRN	SP	CCA		V	9/4/2096	
2020 PO3908782199	F	4	30 BRN	SP	A		V	9/5/2096	
2020 PO3909282208	LGE	3	45 BRN	SP	CCA		V	9/6/2096	
2020 PO3907982213	LGE	4	35 BRN	SP	CCA		V	9/7/2096	
2020 PO3907782209	LGE	4	40 BRN	SP	CCA		V	9/8/2096	
2020 PO3906882217	LGE	4	30 BRN	SP	CRE	ED,ID	BD	9/9/2096	
2020 PO3906582213	LGE	3	45 BRN	SP	CCA		V	9/10/2096	
2020 PO3903582198	F	3	45 BRN	SP	CCA		V	9/11/2096	
2020 PO3902882184	F	4	40 BRN	SP	CCA		V	9/12/2096	
2020 PO3902382172	F	4	40 BRN	SP	CRE		V	9/13/2096	
2020 PO3901782159	F	4	40 BRN	SP	CCA		V	9/14/2096	
2020 PO3903582224	LGE	3	45 BRN	SP	P	ED	T	9/15/2096	
2020 PO3903782229	LGE	4	35 BRN	SP	CRE	ED,ID	TD	9/16/2096	
2020 PO3904882225	LGE	4	30 BRN	SP	A	ED,ID	BD	9/17/2096	
2020 PO3904582220	LGE	4	40 BRN	SP	CRE	ED,ID	TD	9/18/2096	
2020 PO2663627433	ODP	5	35 BRN	SP	CRE	ID	BD	9/19/2096	
2020 PO2684227275	ODP	4	40 BRN	SP	CRE	ID	TD	9/20/2096	
2020 PO2677027358	ODP	4	40 BRN	SP	CRE	ID	TD	9/21/2096	

2020 PO2631427256	ODP	4	40 BRN	SP	CRE	ID	BD	9/22/2096
2020 PO1159240213	ODP	4	40 BRN	SP	CRE	ED,ID	TD	9/23/2096
2020 PO1155940439	ODP	2	50 BRN	SP	CRE		V	9/24/2096
2020 PO1092339687	ODP	4	45 BRN	SP	CCA		V	9/25/2096
2020 PO1095839915	ODP	4	40 BRN	SP	CRE	ED,ID	TD	9/26/2096
2020 PO1459037661	ODP	6	30 BRN	SP	CCA		V	9/27/2096
2020 PO1475437814	ODP	4	45 BRN	SP	CCA		V	9/28/2096
2020 PO1488237897	ODP	4	45 BRN	SP	CCA		V	9/29/2096
2020 PO1506538018	ODP	4	45 BRN	SP	CRE		V	9/30/2096
2020 PO1522838000	ODP	5	35 BRN	SP	CRE		V	10/1/2096
2020 PO1533938149	ODP	1	55 KOP	SP	CRE	ED,EP,ID	TD	10/2/2096
2020 PO1543438180	ODP	5	30 UNK	SP	CRE	ED,ID	TD	10/3/2096
2020 PO1585138355	ODP	5	35 UNK	SP	CRE		V	10/4/2096
2020 PO1591538510	F	4	35 UNK	SP	CRE		V	10/5/2096
2020 PO1614438633	ODP	3	45 BRN	SP	CCA		V	10/6/2096
2020 PO1634038764	F	4	40 UNK	SP	P		V	10/7/2096
2020 PO1655538892	F	4	40 UNK	SP	CRE		V	10/8/2096
2020 PO3986382774	LGE	4	40 BRN	SP	CCA	ED,ID	BD	10/9/2096
2020 PO2924951908	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	10/10/2096
2020 PO2914251982	KU	3	45 BRO	SP	P	ED	T	10/11/2096
2020 PO2945951772	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	10/12/2096
2020 PO3026450770	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	10/13/2096
2020 PO1198637174	ODP	6	30 XXX	SP	CRE	ED,ID	TD	10/14/2096
2020 PO3980782748	F	1	50 BRN	SP	S		V	10/15/2096
2020 PO3980582756	LGE	7	25 BRN	SP	CRE	ED,ID	TD	10/16/2096
2020 PO4309101665	KU	4	40 BRO	SP	CCA	ID	BD	10/17/2096
2020 PO3979082762	LGE	6	25 BRN	SP	CRE		V	10/18/2096
2020 PO3015950838	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	10/19/2096
2020 PO3017251034	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	10/20/2096
2020 PO2984351493	KU	3	45 BRO	SP	CRE	ED	TD	10/21/2096
2020 PO3980082764	LGE	4	40 BRN	SP	S		V	10/22/2096
2020 PO3982283027	LGE	4	40 BRN	SP	A	ED,ID	TD	10/23/2096
2020 PO3981583026	LGE	6	25 BRN	SP	CRE	ED,HH,ID,RB	BX	10/24/2096
2020 PO2964851632	KU	3	45 BRO	SP	CRE	ED,IP	TD	10/25/2096
2020 PO3001051683-A	KU	3	45 BRO	SP	P	ED	T	10/26/2096
2020 PO1261736975	ODP	4	40 XXX	SP	CRE	ED,ID	TD	10/27/2096
2020 PO1236637187	ODP	5	35 BRN	SP	CRE	ED,ID	TD	10/28/2096
2020 PO3882082613	LGE	4	40 BRO	SP	A	ED,ID	TD	10/29/2096
2020 PO3881882591	LGE	4	40 BRO	SP	P	ED,ID	TD	10/30/2096
2020 PO3881282586	LGE	4	35 BRO	SP	P	ED,ID	TD	10/31/2096
2020 PO2611927316	ODP	4	40 BRN	SP	CRE	ID	TD	11/1/2096
2020 PO2587927389	ODP	4	40 BRN	SP	CRE	ID	TD	11/2/2096
2020 PO3578239440	F	4	40 ACE	SP	CRE		V	11/3/2096
2020 PO3594439436	F	4	40 ACE	SP	CRE		V	11/4/2096
2020 PO3611839433	F	4	40 ACE	SP	CRE	ED,ID,IP	V	11/5/2096
2020 PO3633839429	F	4	40 ACE	SP	CRE		V	11/6/2096
2020 PO3656939496	KU	4	40 ACE	SP	CRE	ED,ID	BD	11/7/2096

2020 PO3651939426	F	4	40 ACE	SP	CRE		V	11/8/2096
2020 PO3660539368	KU	4	45 ACE	SP	CRE	ED,ID	BD	11/9/2096
2020 PO3631640954	F	4	40 ACE	SP	CRE		V	11/10/2096
2020 PO4197902067	KU	5	30 BRO	SP	CRE	ED,ID	TD	11/11/2096
2020 PO5674951333	KU	4	40 ACE	SP	CRE		V	11/12/2096
2020 PO5692651694	KU	4	45 ACE	SP	CRE		V	11/13/2096
2020 PO9399193270	KU	4	40 ACW	SP	CRE	ED,ID	BD	11/14/2096
2020 PO9410093288	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	11/15/2096
2020 PO9421493306	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	11/16/2096
2020 PO5769045842a	KU	5	35 ACE	SP	CRE	ED,ID	BD	11/17/2096
2020 PO5769045842	KU	4	45 ACE	SP	CRE	ED,ID	BX	PX 11/18/2096
2020 PO5761046021	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD	11/19/2096
2020 PO5753546192	KU	3	50 ACE	SP	CCA		V	11/20/2096
2020 PO5775450531	KU	4	45 ACE	SP	P		V	11/21/2096
2020 PO9577393832	C	4	40 ACW	SP	CRE		V	11/22/2096
2020 PO9582993903	C	4	40 ACW	SP	CRE		V	11/23/2096
2020 PO9591393871	KU	7	30 ACW	SP	CRE	ED,ID	TD	11/24/2096
2020 PO5728050752	F	4	40 ACE	SP	CCA		V	11/25/2096
2020 PO5742150681	F	4	40 ACE	SP	CCA		V	11/26/2096
2020 PO5800050730	KU	3	50 ACE	SP	CCA		V	11/27/2096
2020 PO5751850630	F	4	40 ACE	SP	P		V	11/28/2096
2020 PO1278337587	ODP	4	40 XXX	SP	A	ED,ID	TD	11/29/2096
2020 PO1297137594	ODP	6	30 XXX	SP	CRE	ED,ID	TD	11/30/2096
2020 PO1292837668	ODP	4	40 XXX	SP	A	ED,ID	TD	12/1/2096
2020 PO1276437769	ODP	4	40 XXX	SP	A	ED,ID	TD	12/2/2096
2020 PO5919806401	KU	4	45 BRO	SP	CRE	ID	TD	12/3/2096
2020 PO6095306078	F	4	40 BRO	SP	CRE		V	12/4/2096
2020 PO6055306408	KU	5	35 BRO	SP	CRE		V	12/5/2096
2020 PO6034006498	KU	4	40 BRO	SP	CRE	ID	TD	12/6/2096
2020 PO6035306341	KU	4	40 BRO	SP	CRE	ID	TD	12/7/2096
2020 PO6045606413	KU	6	30 BRO	SP	CCA		V	12/8/2096
2020 PO6058906310	KU	3	45 BRO	SP	CCA		V	12/9/2096
2020 PO6055506212	KU	5	30 BRO	SP	CRE	ID	TD	12/10/2096
2020 PO6075006291	F	6	30 BRO	SP	CRE		V	12/11/2096
2020 PO6088306206	KU	4	40 BRO	SP	CCA		V	12/12/2096
2020 PO6081806106	F	4	40 BRO	SP	CRE		V	12/13/2096
2020 PO6076106063	KU	4	40 BRO	SP	CRE	ID	TD	12/14/2096
2020 PO6095606233	KU	4	30 BRO	SP	CRE		V	12/15/2096
2020 PO6103906217	KU	4	40 BRO	SP	CCA		V	12/16/2096
2020 PO6112506203	KU	6	30 BRO	SP	CCA		V	12/17/2096
2020 PO6110806124	KU	4	40 BRO	SP	CRE	ID	TD	12/18/2096
2020 PO6094306001	KU	4	40 BRO	SP	CRE	ED,HH,ID	BX	RP2 12/19/2096
2020 PO6095206045	F	4	40 BRO	SP	CRE		V	12/20/2096
2020 PO6108406074	KU	4	35 BRO	SP	CCA		V	12/21/2096
2020 PO6103605975	KU	4	40 BRO	SP	CRE	ID	TD	12/22/2096
2020 PO6120805842	KU	4	40 BRO	SP	CRE		V	12/23/2096
2020 PO6937889525	F	4	45 BRN	SP	CRE		V	12/24/2096

2020 PO0481451150	KU	5	35 BRO	SP	CRE	ED,ID,SRC	TD		12/25/2096
2020 PO4900831254	KU	4	45 ACE	SP	CRE	ED,EP,HH,ID,IP,MD,RB	BX	RP1	12/26/2096
2020 PO4925431497	KU	2	60 ACE	SP	CRE	ED,ID	BD		12/27/2096
2020 PO3927682439	F	4	40 BRN	SP	CRE		V		12/28/2096
2020 PO3927982439	F	4	40 BRN	SP	CRE		V		12/29/2096
2020 PO3928882436	F	4	40 BRN	SP	CRE		V		12/30/2096
2020 PO6493535745	LGE	4	35 BRN	SP	CCA		V		12/31/2096
2020 PO6494935871	LGE	4	35 BRN	SP	CCA		V		1/1/2097
2020 PO6486635910	LGE	4	35 BRN	SP	CCA		V		1/2/2097
2020 PO3936082430	LGE	3	45 BRN	SP	CRE	ED,ID	BD		1/3/2097
2020 PO3937082462	LGE	3	45 BRN	SP	CCA		V		1/4/2097
2020 PO3993583124	LGE	4	40 BRN	SP	CRE	ED,ID,RB	X	PX	1/5/2097
2020 PO2678926368	ODP	4	40 BRO	SP	CRE	ID	TD		1/6/2097
2020 PO1056638231	ODP	4	45 BRN	SP	CRE	ED,ID	TD		1/7/2097
2020 PO4702229357	KU	3	45 ACE	SP	CRE	ED,ID	BD		1/8/2097
2020 PO4701129324	KU	3	45 ACE	SP	CRE	ED,ID	BD		1/9/2097
2020 PO9724361763	KU	4	40 ACW	SP	CRE	ED,EP,ID,IP	TD		1/10/2097
2020 PO9860859850	KU	4	40 ACW	SP	CRE	ED,ID	TD		1/11/2097
2020 PO1534175470	KU	4	40 BRN	SP	CRE	ID,IP	BD		1/12/2097
2020 PO1531275397	KU	4	40 BRN	SP	CRE	ID,IP	BD		1/13/2097
2020 PO1533075311	KU	4	45 BRN	SP	CRE	ID,IP	BD		1/14/2097
2020 PO9727861953	KU	4	40 ACW	SP	CCA		V		1/15/2097
2020 PO9867959706	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		1/16/2097
2020 PO9853659220	KU	4	40 ACW	SP	P	ED	T		1/17/2097
2020 PO1484875463	KU	4	45 BRN	SP	CRE	ID,IP	BD		1/18/2097
2020 PO1624175337	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		1/19/2097
2020 PO1617875148	KU	4	40 BRN	SP	CRE	ID,IP	BD		1/20/2097
2020 PO1599075213	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		1/21/2097
2020 PO1574375030	KU	4	40 BRN	SP	CRE		V		1/22/2097
2020 PO0470551202	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD		1/23/2097
2020 PO0458451260	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD		1/24/2097
2020 PO0446351317	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD		1/25/2097
2020 PO0422351440	KU	5	35 BRO	SP	CRE	ID	BD		1/26/2097
2020 PO0395951572	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD		1/27/2097
2020 PO038951607	KU	4	40 BRO	SP	CRE	ED,HH,ID,IP,RB	X	RP2	1/28/2097
2020 PO0430750927	KU	5	35 BRO	SP	CRE	ED,ID,SRC	TD		1/29/2097
2020 PO0463050119	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD		1/30/2097
2020 PO0008761539	KU	4	40 ACW	SP	CRE	ED,ID	TD		1/31/2097
2020 PO7107787425	KU	3	45 BRN	SP	S		V		2/1/2097
2020 PO7105087320	KU	5	35 BRN	SP	CRE	ED,ID	TD		2/2/2097
2020 PO7101487393	KU	3	50 BRN	SP	CRE	ED,ID	TD		2/3/2097
2020 PO7641878779	KU	4	40 BRO	SP	CRE	ED,ID	TD		2/4/2097
2020 PO7645578873	KU	6	30 BRO	SP	CRE	ID	BD		2/5/2097
2020 PO7654378724	KU	4	40 BRO	SP	CRE	ID	BD		2/6/2097
2020 PO7661378701	KU	4	40 BRO	SP	CRE	ED,ID	TD		2/7/2097
2020 PO7665278787	KU	6	30 BRO	SP	CRE	ED,ID	TD		2/8/2097
2020 PO5420607247	KU	6	30 BRO	SP	CRE		V		2/9/2097

2020 PO5428507556	KU	6	30 BRO	SP	CRE	ID	TD	2/10/2097
2020 PO5425607198	F	4	40 BRO	SP	CRE		V	2/11/2097
2020 PO7812477051	F	3	40 BRO	SP	A		V	2/12/2097
2020 PO7798877175	F	3	45 BRO	SP	CRE		V	2/13/2097
2020 PO7744178083	F	4	40 BRO	SP	CRE		V	2/14/2097
2020 PO7739478164	F	4	40 BRO	SP	CRE		V	2/15/2097
2020 PO7751477958	F	4	50 BRO	SP	CRE		V	2/16/2097
2020 PO7758777833	F	3	40 BRO	SP	A		V	2/17/2097
2020 PO7749378265	KU	5	35 BRO	SP	CRE	ED,ID	TD	2/18/2097
2020 PO7734078257	F	3	40 BRO	SP	A		V	2/19/2097
2020 PO7727678366	F	4	40 BRO	SP	CRE		V	2/20/2097
2020 PO7376885471	KU	4	40 BRN	SP	A	ED,ID	TD	2/21/2097
2020 PO7386385569	KU	6	30 BRN	SP	CRE	ED,ID	TD	2/22/2097
2020 PO7408784402	KU	6	30 BRN	SP	CRE		V	2/23/2097
2020 PO7399184308-A	KU	5	30 BRN	SP	CCA		V	2/24/2097
2020 PO7414784160	F	3	40 BRN	SP	CRE		V	2/25/2097
2020 PO7832877027	KU	4	45 BRO	SP	CRE		V	2/26/2097
2020 PO7844377084	KU	4	40 BRO	SP	CRE		V	2/27/2097
2020 PO7854777131	KU	4	40 BRO	SP	CRE		V	2/28/2097
2020 PO7880577239	KU	4	40 BRO	SP	CRE		V	3/1/2097
2020 PO7384584939	F	4	40 BRN	SP	CRE		V	3/2/2097
2020 PO7401885164	F	4	45 BRN	SP	CCA		V	3/3/2097
2020 PO7398585123	F	4	45 BRN	SP	CRE		V	3/4/2097
2020 PO7393785063	F	3	45 BRN	SP	CRE		V	3/5/2097
2020 PO7852178527	KU	4	40 BRO	SP	CRE		V	3/6/2097
2020 PO7847479022	KU	4	45 BRO	SP	CRE	ED,ID	TD	3/7/2097
2020 PO7863178659	KU	4	45 BRO	SP	CRE	ED,ID	TD	3/8/2097
2020 PO7855178840	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/9/2097
2020 PO7804777258	KU	4	40 BRO	SP	CRE		B	3/10/2097
2020 PO7866378347	KU	4	40 BRO	SP	CRE		V	3/11/2097
2020 PO7835978357	KU	4	40 BRO	SP	CRE		V	3/12/2097
2020 PO7811278242	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	3/13/2097
2020 PO5457708857	KU	5	30 BRO	SP	CCA		V	3/14/2097
2020 PO5455908761	KU	3	50 BRO	SP	CRE		V	3/15/2097
2020 PO5423807062a	KU	5	30 BRO	SP	CRE	ID	TD	3/16/2097
2020 PO5423807062	KU	4	40 BRO	SP	CRE	ID	TD	3/17/2097
2020 PO5417307122	KU	5	35 BRO	SP	CRE	ID	TD	3/18/2097
2020 PO5410307551	KU	4	40 BRO	SP	CRE	ID	BD	3/19/2097
2020 PO5418507626	KU	4	40 BRO	SP	CRE	ID	BD	3/20/2097
2020 PO5461807293	KU	5	35 BRO	SP	CRE	ID	BD	3/21/2097
2020 PO5452507038	F	3	45 BRO	SP	CCA		V	3/22/2097
2020 PO5436907182	KU	4	40 BRO	SP	CCA		V	3/23/2097
2020 PO5428107258	KU	4	45 BRO	SP	CRE	ID	BD	3/24/2097
2020 PO5419307351	KU	4	45 BRO	SP	CRE	ID	BD	3/25/2097
2020 PO5411007426	KU	4	45 BRO	SP	CRE	ID	BD	3/26/2097
2020 PO5403807493	KU	4	45 BRO	SP	CRE	ID	BD	3/27/2097
2020 PO5435307428	KU	6	30 BRO	SP	CRE	ID	TD	3/28/2097

2020 PO5422107389	KU	5	35 BRO	SP	CRE	ID	TD	3/29/2097
2020 PO5452407187	KU	5	35 BRO	SP	CRE	ID	BD	3/30/2097
2020 PO5461307114	KU	5	30 BRO	SP	CRE	ID	TD	3/31/2097
2020 PO5457407077	KU	5	35 BRO	SP	CRE	ID	TD	4/1/2097
2020 PO5477607141	F	4	40 BRO	SP	CRE		V	4/2/2097
2020 PO5492107074	F	4	40 BRO	SP	CRE		V	4/3/2097
2020 PO7790778145	KU	4	40 BRO	SP	CCA		V	4/4/2097
2020 PO7413584834	KU	6	30 BRN	SP	CCA		V	4/5/2097
2020 PO7401784934	F	4	35 BRN	SP	CCA		V	4/6/2097
2020 PO7406984847	F	4	35 BRN	SP	CRE		V	4/7/2097
2020 PO7413584738	F	4	35 BRN	SP	CRE		V	4/8/2097
2020 PO7420184638	F	4	35 BRN	SP	CCA		V	4/9/2097
2020 PO7423884569	F	4	35 BRN	SP	CCA		V	4/10/2097
2020 PO7438484500	KU	5	35 BRN	SP	CRE	ED,ID	BD	4/11/2097
2020 PO7430584451	F	5	35 BRN	SP	CRE		V	4/12/2097
2020 PO7437184359	KU	5	35 BRN	SP	CRE		V	4/13/2097
2020 PO7449984602	KU	6	30 BRN	SP	CRE		V	4/14/2097
2020 PO7769378043	KU	4	40 BRO	SP	CRE	ED,ID	TD	4/15/2097
2020 PO5328007027	KU	4	45 XXX	SP	CRE	ED,ID	TD	4/16/2097
2020 PO5335607136	KU	5	35 XXX	SP	CRE	ID	BD	4/17/2097
2020 PO5342707221	KU	4	40 KOP	SP	CRE	ED,ID	T	4/18/2097
2020 PO5353307276	KU	4	40 XXX	SP	CRE	ED,ID	TD	4/19/2097
2020 PO5355307359	KU	4	40 BRN	SP	CCA		V	4/20/2097
2020 PO7421685408	KU	4	35 BRN	SP	CRE	ED,ID,IP	TD	4/21/2097
2020 PO7420985369	KU	4	45 BRN	SP	CCA		V	4/22/2097
2020 PO7750774789	KU	4	40 BRO	SP	CCA		V	4/23/2097
2020 PO7766174972	KU	4	40 BRO	SP	CCA		V	4/24/2097
2020 PO7775174652	KU	3	45 BRO	SP	CCA		V	4/25/2097
2020 PO7796174279	KU	4	40 BRO	SP	CCA		V	4/26/2097
2020 PO7799174518	KU	4	40 BRO	SP	CCA		V	4/27/2097
2020 PO7776475095	KU	4	40 BRO	SP	CCA		V	4/28/2097
2020 PO7451784657	KU	6	30 BRN	SP	CCA		V	4/29/2097
2020 PO7444384804	KU	4	45 BRN	SP	CCA		V	4/30/2097
2020 PO7436084929	KU	4	45 BRN	SP	CCA		V	5/1/2097
2020 PO7429085055	KU	4	45 BRN	SP	CCA		V	5/2/2097
2020 PO7436185024	KU	5	35 BRN	SP	CCA		V	5/3/2097
2020 PO7518184889	KU	4	40 BRN	SP	CRE		V	5/4/2097
2020 PO7508984672	KU	4	40 BRN	SP	CRE		V	5/5/2097
2020 PO7514884704	KU	5	35 BRN	SP	CRE		V	5/6/2097
2020 PO7520784612	KU	6	30 BRN	SP	CRE		V	5/7/2097
2020 PO7792075277	KU	4	40 BRO	SP	CRE		V	5/8/2097
2020 PO7788175322	KU	4	40 BRO	SP	CRE	ID	BD	5/9/2097
2020 PO7781275439	KU	6	30 BRO	SP	CCA		V	5/10/2097
2020 PO7302885164	F	4	45 BRN	SP	CRE		V	5/11/2097
2020 PO7306385089	KU	4	40 BRN	SP	CCA		V	5/12/2097
2020 PO7311084987	F	4	45 BRN	SP	CRE		V	5/13/2097
2020 PO7317584847	F	4	40 BRN	SP	CRE		V	5/14/2097

2020 PO7323984714	F	3	50 BRN	SP	CRE		V		5/15/2097
2020 PO7330184579	F	3	45 BRN	SP	CRE		V		5/16/2097
2020 PO7404583191	KU	5	35 BRN	SP	CRE		V		5/17/2097
2020 PO7399983156	KU	5	35 BRN	SP	CRE		V		5/18/2097
2020 PO7892276390A	KU	6	35 BRO	SP	CRE	ED,ID	TD		5/19/2097
2020 PO5392107455	KU	6	30 BRN	SP	CRE		V		5/20/2097
2020 PO3627461484	KU	5	35 BRO	SP	CCA		V		5/21/2097
2020 PO0229760585	KU	5	35 BRO	SP	CRE	ED,ID,SRC	TD		5/22/2097
2020 PO3582455794	KU	4	40 BRN	SP	CCA		V		5/23/2097
2020 PO3592255248	KU	5	35 BRN	SP	CRE	ED,ID,IP,SRC	TD		5/24/2097
2020 PO3605955469	KU	3	40 BRN	SP	CRE	ED,ID,IP	BD		5/25/2097
2020 PO3619255681	KU	4	40 BRN	SP	CRE	ID	TD		5/26/2097
2020 PO0766859369	KU	4	40 ACW	SP	CRE	ED,ID	BD		5/27/2097
2020 PO0948257423	KU	3	45 ACW	SP	CCA		V		5/28/2097
2020 PO0735959750	KU	5	30 ACW	SP	CRE	ED,ID	BD		5/29/2097
2020 PO3632455893	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		5/30/2097
2020 PO0226960637	KU	4	40 BRO	SP	CRE	ID	BD		5/31/2097
2020 PO0241660690	KU	6	30 BRO	SP	CRE	ED,ID,SRC	TD		6/1/2097
2020 PO0709359822	KU	4	45 ACW	SP	CRE	ED,ID	TD		6/2/2097
2020 PO3646456118	KU	3	45 BRN	SP	CRE	ID	BD		6/3/2097
2020 PO3653356231	KU	3	45 BRN	SP	P	ED	TD		6/4/2097
2020 PO0711459871	F	5	30 ACW	SP	CRE		V		6/5/2097
2020 PO3659756330	KU	3	45 BRN	SP	CRE	ID	TD		6/6/2097
2020 PO3674256564	KU	4	40 BRN	SP	CRE	ID	TD		6/7/2097
2020 PO0261260439	KU	4	35 BRO	SP	CRE	ED,ID,SRS	TD		6/8/2097
2020 PO0261660346	KU	5	35 BRO	SP	CRE	ED,ID,IP,SRS	TD		6/9/2097
2020 PO0270960398	KU	4	40 BRO	SP	CRE	ID	BD		6/10/2097
2020 PO0776059190	KU	4	40 ACW	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX	6/11/2097
2020 PO3667257084	KU	4	40 BRN	SP	CRE	ID	TD		6/12/2097
2020 PO0747059132	KU	6	30 ACW	SP	CRE	ED,ID	TD		6/13/2097
2020 PO3686256704	KU	4	40 BRN	SP	CRE	ID,IP	TD		6/14/2097
2020 PO3698256614	KU	4	40 BRN	SP	P	ED	BD		6/15/2097
2020 PO0737058946	KU	6	30 ACW	SP	CRE	ED,ID	TD		6/16/2097
2020 PO0284960480	KU	4	40 BRO	SP	CRE	ED,ID,IP,SRS	TD		6/17/2097
2020 PO0722359026	KU	6	30 ACW	SP	CRE	ED,ID	TD		6/18/2097
2020 PO3696056861	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		6/19/2097
2020 PO2073238046	KU	4	40 BRO	SP	CRE	ED,ID	BD		6/20/2097
2020 PO0304816702	KU	6	30 BRO	SP	CRE	HH,ID,RB	X	PX	6/21/2097
2020 PO7443919067	KU	3	50 XXX	SP	CRE	ID	TD		6/22/2097
2020 PO7463719278B	KU	5	35 XXX	SP	CRE	ID	TD		6/23/2097
2020 PO7463719278	KU	5	35 XXX	SP	CRE	ID	TD		6/24/2097
2020 PO7463719287	KU	5	35 XXX	SP	CRE	ID,IP	TD		6/25/2097
2020 PO7474219282	KU	6	30 XXX	SP	CCA		V		6/26/2097
2020 PO3026534152	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD		6/27/2097
2020 PO3049433894	KU	4	40 BRN	SP	CRE	ED,ID,MD	TD		6/28/2097
2020 PO8136237842	KU	4	40 OTH	SP	CRE		V		6/29/2097
2020 PO3926382436	LGE	3	45 BRN	SP	CRE	ED,ID	VX	PX	6/30/2097

2020 PO0700259218	KU	6	30 ACW	SP	CRE	ED,ID	TD		7/1/2097
2020 PO0710759432	KU	6	30 ACW	SP	CRE	ED,ID,IP	BD		7/2/2097
2020 PO3705357010	KU	4	40 BRN	SP	CRE	ID,IP	TD		7/3/2097
2020 PO0277060570	KU	6	30 BRO	SP	CRE	ID	BD		7/4/2097
2020 PO0280360633	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD		7/5/2097
2020 PO0267860867	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD		7/6/2097
2020 PO0267560941	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD		7/7/2097
2020 PO9984152611	KU	5	35 BRO	SP	CRE		B		7/8/2097
2020 PO3723557093	KU	4	40 BRN	SP	CRE	ID,IP	TD		7/9/2097
2020 PO3728357096	KU	6	30 BRN	SP	CRE	ID	TD		7/10/2097
2020 PO0681559335	KU	6	30 ACW	SP	CRE	ED,ID	TD		7/11/2097
2020 PO0692059588	KU	6	30 ACW	SP	CRE	ED,ID	TD		7/12/2097
2020 PO3887156752	KU	4	40 BRO	SP	CRE	ED,ID	BD		7/13/2097
2020 PO3841356734	KU	4	40 BRO	SP	CRE	ED,ID	BD		7/14/2097
2020 PO3800156396	KU	4	40 BRO	SP	CRE	ED,ID	BD		7/15/2097
2020 PO3783056720	KU	5	35 BRN	SP	CRE	ED,ID	TD		7/16/2097
2020 PO9958252703	KU	3	45 BRO	SP	P		B		7/17/2097
2020 PO9929952822	KU	3	45 BRO	SP	P		B		7/18/2097
2020 PO9903352925	KU	3	45 BRO	SP	P		B		7/19/2097
2020 PO9878453021	KU	5	35 BRO	SP	CRE	ED,ID,SRC	TD		7/20/2097
2020 PO3787057944	KU	4	40 BRN	SP	CRE	ED,HH,RB	X	PX	7/21/2097
2020 PO3762356886	KU	5	35 BRN	SP	CRE	HH,RB	X	PX	7/22/2097
2020 PO3763657391	KU	3	45 BRN	SP	CCA		V		7/23/2097
2020 PO0674559610	KU	5	35 ACW	SP	CRE	ED,ID	TD		7/24/2097
2020 PO0678859714	KU	5	35 ACW	SP	CRE	ED,ID	TD		7/25/2097
2020 PO3741557227	KU	5	35 BRN	SP	CRE	ID,IP	TD		7/26/2097
2020 PO3788457575	KU	4	40 BRN	SP	CRE	ID	TD		7/27/2097
2020 PO3791357578	KU	4	40 BRN	SP	CRE	ID	TD		7/28/2097
2020 PO3806357399	KU	4	40 BRN	SP	CRE	ID	TD		7/29/2097
2020 PO9827953226	KU	4	40 BRO	SP	CRE	ED,ID,IP,SRS	TD		7/30/2097
2020 PO9851953123	KU	3	45 BRO	SP	CRE		V		7/31/2097
2020 PO9802953327	KU	3	45 BRO	SP	CRE		V		8/1/2097
2020 PO3927182453	LGE	3	45 BRN	SP	CCA		V		8/2/2097
2020 PO3980182876	F	4	40 BRN	SP	CRE	ED,RB	VX	PX	8/3/2097
2020 PO0910311244	KU	5	35 UNK	SP	CRE	ED,ID	TD		8/4/2097
2020 PO0935311064	F	5	40 UNK	SP	CRE		V		8/5/2097
2020 PO0940711134	F	4	40 UNK	SP	CRE		V		8/6/2097
2020 PO0941011102	KU	5	35 UNK	SP	CRE	ED,ID	TD		8/7/2097
2020 PO0948411201	KU	6	30 UNK	SP	CRE		V		8/8/2097
2020 PO0948111323	KU	6	30 UNK	SP	CRE		V		8/9/2097
2020 PO0951910993	KU	6	30 UNK	SP	CRE	ED,EP,ID,SRC	TD		8/10/2097
2020 PO0958611005	KU	6	30 UNK	SP	CRE	ED,ID	TD		8/11/2097
2020 PO0959211125	KU	5	35 UNK	DF	CRE	ED,ID,SRS	TD		8/12/2097
2020 PO5694852674	KU	6	30 ACE	SP	CRE	ED,ID	TD		8/13/2097
2020 PO5637652740	KU	6	30 ACE	SP	CRE	ED,ID	TD		8/14/2097
2020 PO9435894003	KU	6	30 ACW	DF	CCA		V		8/15/2097
2020 PO9445693984	KU	5	35 ACW	ST	CCA		V		8/16/2097

2020 PO9446693829	KU	4	40 ACW	SP	CRE	ED,ID	TD	8/17/2097
2020 PO9435593849	KU	5	35 ACW	DF	CRE	ED,ID	TD	8/18/2097
2020 PO9432593940	KU	4	40 ACW	SP	CRE	ED,ID	TD	8/19/2097
2020 PO5575552260	KU	4	45 ACE	SP	CRE	ED,ID	TD	8/20/2097
2020 PO5640352809	KU	4	40 ACE	SP	CRE	ED,ID	TD	8/21/2097
2020 PO5651152756	KU	4	40 ACE	SP	CRE	ED,ID	TD	8/22/2097
2020 PO5658152721	KU	4	40 ACE	SP	CRE	ED,ID	BD	8/23/2097
2020 PO9432593940D	KU	6	30 ACW	SP	CRE	ED,ID,IP,MD,SR	TX RR	8/24/2097
2020 PO5647252652	KU	6	30 ACE	SP	CRE	ED,ID	TD	8/25/2097
2020 PO9432593940F	KU	7	30 ACW	SP	CRE	ED,ID	TD	8/26/2097
2020 PO943259340A	KU	6	30 ACW	SP	CRE	ED,ID	TD	8/27/2097
2020 PO4425011873	F	5	35 ACE	SP	P		V	8/28/2097
2020 PO943259340B	KU	6	30 ACW	SP	CRE	ED,ID	TD	8/29/2097
2020 PO4437911977	F	5	35 ACE	SP	P		V	8/30/2097
2020 PO4431412056	F	3	45 ACE	SP	CCA		V	8/31/2097
2020 PO4441412135	F	3	45 ACE	SP	CCA		V	9/1/2097
2020 PO4444112157	F	3	45 ACE	SP	CCA		V	9/2/2097
2020 PO4719088674	LGE	4	40 BRN	SP	CRE	ED,ID	BD	9/3/2097
2020 PO4093811319	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	9/4/2097
2020 PO4135912215	KU	4	40 BRO	SP	CCA		V	9/5/2097
2020 PO4112812306	KU	2	40 BRO	SP	CCA		V	9/6/2097
2020 PO4717288663	LGE	4	40 BRN	SP	A	ED,ID	BD	9/7/2097
2020 PO4716588676	LGE	4	40 BRN	SP	CRE		V	9/8/2097
2020 PO1950222349	ODP	4	40 BRN	SP	CRE	ID,IP	TX RR	9/9/2097
2020 PO1949922218	ODP	4	45 BRN	SP	CCA		V	9/10/2097
2020 PO4723188529	LGE	4	40 BRN	SP	CCA	ED,ID	BD	9/11/2097
2020 PO4722188525	LGE	4	40 BRN	SP	CRE	ED,ID	V	9/12/2097
2020 PO4721388522	LGE	4	40 BRN	SP	CRE	ED,ID	BD	9/13/2097
2020 PO4052782903	LGE	4	40 BRO	SP	P		TD	9/14/2097
2020 PO4052682897	LGE	4	30 BRO	SP	CCA	ED,ID	BD	9/15/2097
2020 PO4720888515	LGE	1	70 BRN	SP	CRE		V	9/16/2097
2020 PO4720388519	LGE	3	50 BRN	SP	CRE	ED,ID	BD	9/17/2097
2020 PO4719488516	LGE	4	35 BRN	SP	CCA		V	9/18/2097
2020 PO4718888514	LGE	3	50 BRN	SP	A	ED,ID	BD	9/19/2097
2020 PO4553511346	KU	6	30 ACE	SP	CRE	ED,ID	TD	9/20/2097
2020 PO4718488505	LGE	1	65 BRN	SP	CRE		V	9/21/2097
2020 PO1950422066	ODP	4	40 BRN	SP	CRE	ID	TD	9/22/2097
2020 PO4089611678	KU	2	40 BRO	SP	CRE	ID	BD	9/23/2097
2020 PO4072411752	KU	4	40 BRO	SP	CRE	ID	BD	9/24/2097
2020 PO4061411799	KU	4	40 BRO	SP	CRE	ID	BD	9/25/2097
2020 PO4105611594	KU	2	40 BRO	SP	CRE	ID	BD	9/26/2097
2020 PO4558211274	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX PX	9/27/2097
2020 PO4541911344	F	4	40 ACE	SP	CRE		V	9/28/2097
2020 PO4054182896	LGE	4	30 BRO	SP	P	ED,ID	TD	9/29/2097
2020 PO1975821855	ODP	4	40 XXX	SP	CRE	ID	TD	9/30/2097
2020 PO2018221861	ODP	4	40 XXX	SP	CRE	ID	TD	10/1/2097
2020 PO2060421884	ODP	4	40 XXX	SP	CRE	ID	TD	10/2/2097

2020 PO1155224263	ODP	4	40 XXX	SP	CRE	ED	T	10/3/2097
2020 PO1178724583	ODP	4	45 XXX	SP	CCA	ED	T	10/4/2097
2020 PO1951021876	ODP	4	40 BRN	SP	CRE	ID	TD	10/5/2097
2020 PO4480611595	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	RP1 10/6/2097
2020 PO1997821852	ODP	4	40 BRN	SP	CRE	ID	TD	10/7/2097
2020 PO2037521865	ODP	4	40 BRN	SP	CRE	ID	TD	10/8/2097
2020 PO1176524384	ODP	4	40 BRN	SP	CCA	ED	T	10/9/2097
2020 PO1217724625	F	4	45 BRN	SP	CRE		V	10/10/2097
2020 PO4528311401	F	4	40 ACE	SP	CRE	ED,ID	V	10/11/2097
2020 PO4470711643	F	4	40 ACE	SP	CRE		V	10/12/2097
2020 PO4116411224	KU	2	45 BRO	SP	CRE	ID,IP	BD	10/13/2097
2020 PO4567411206	F	4	40 ACE	SP	CRE		V	10/14/2097
2020 PO4055682895	LGE	4	30 BRO	SP	P	ED,ID	TD	10/15/2097
2020 PO4716388587	LGE	4	40 BRN	SP	CRE	ED,ID	TD	10/16/2097
2020 PO4460912079	F	2	50 ACE	SP	CCA		V	10/17/2097
2020 PO4471912030	F	2	50 ACE	SP	CCA		V	10/18/2097
2020 PO4070812145	KU	4	40 BRO	SP	CRE	ID,IP	BD	10/19/2097
2020 PO4077212291	KU	4	40 BRO	SP	CRE	ID,IP	BD	10/20/2097
2020 PO4715688599	LGE	3	45 BRN	SP	S		V	10/21/2097
2020 PO4253498758	LGE	3	45 BRN	SP	CRE		V	10/22/2097
2020 PO4715288604	LGE	3	45 BRN	SP	S		V	10/23/2097
2020 PO4064511997	KU	4	40 BRO	SP	CRE	ID,IP	BD	10/24/2097
2020 PO4714888612	LGE	3	45 BRN	SP	S		V	10/25/2097
2020 PO4243898927	LGE	3	45 BRN	SP	CCA		V	10/26/2097
2020 PO4240398985	LGE	3	45 BRN	SP	CCA		V	10/27/2097
2020 PO4059482897	LGE	4	40 BRO	SP	P	ED,ID	TD	10/28/2097
2020 PO4717188508	LGE	4	40 BRN	SP	S		V	10/29/2097
2020 PO4715988496	LGE	1	80 BRN	SP	CRE		V	10/30/2097
2020 PO4715688502	LGE	4	40 BRN	SP	CCA	ED,ID	BD	10/31/2097
2020 PO4715488505	LGE	3	45 BRN	SP	A	ED,ID	BD	11/1/2097
2020 PO4715488491	LGE	UNK	55 BRN	SP	CRE	ED,ID	BD	11/2/2097
2020 P0943259340C	KU	6	30 ACW	SP	CRE	ED,ID	TD	11/3/2097
2020 P09432593940E	KU	6	30 ACW	SP	CRE	ED,ID	TD	11/4/2097
2020 P09443193664	KU	5	35 ACW	SP	CRE	ED,ID	TD	11/5/2097
2020 P09436593495	KU	5	35 ACW	SP	CCA		V	11/6/2097
2020 P05646552552	KU	4	40 ACE	SP	CRE	ED,ID	TD	11/7/2097
2020 P05633252539	KU	4	40 ACE	SP	CRE	ED,ID	TD	11/8/2097
2020 P05622752574	KU	4	40 ACE	SP	CRE	ED,ID	TD	11/9/2097
2020 P05596652405	KU	3	50 ACE	SP	CRE	ED,ID	TD	11/10/2097
2020 P05606552625	KU	4	40 ACE	SP	CRE	ED,ID	TD	11/11/2097
2020 PO4269511230	KU	3	45 BRO	SP	CRE	ED,ID,IP	BD	11/12/2097
2020 PO4728288540	LGE	2	60 BRN	SP	CRE		V	11/13/2097
2020 PO4728988550	LGE	3	45 BRN	SP	S		V	11/14/2097
2020 PO4727888545	LGE	4	40 BRN	SP	S		V	11/15/2097
2020 PO4726788542	LGE	4	40 BRN	SP	S		V	11/16/2097
2020 PO4636137583	KU	1	60 BRO	SP	CCA		V	11/17/2097
2020 PO4645337501	KU	1	60 BRO	SP	CCA		V	11/18/2097

2020 PO4725888531	LGE	1	60 BRN	SP	CRE		V		11/19/2097
2020 PO4725688538	LGE	4	40 BRN	SP	CRE	ED,ID	BD		11/20/2097
2020 PO4649237482	KU	1	60 BRO	SP	CCA		V		11/21/2097
2020 PO4724488533	LGE	4	40 BRN	SP	CCA	ED,ID	BD		11/22/2097
2020 PO4146111099	KU	2	45 BRO	SP	CRE		V		11/23/2097
2020 PO4160711037	KU	2	45 BRO	SP	CRE		V		11/24/2097
2020 PO4130111166	KU	2	45 BRO	SP	CRE		V		11/25/2097
2020 PO4096111869	KU	2	40 BRO	SP	CRE	ID	BD		11/26/2097
2020 PO9254894148	KU	4	40 BRN	SP	P	ED,ID,SRC	TD		11/27/2097
2020 PO4944710418	F	4	40 ACE	SP	P		V		11/28/2097
2020 PO1778832868	F	4	40 BRN	SP	CRE		V		11/29/2097
2020 PO1751032899	ODP	4	40 BRN	SP	CRE	ED,ID,SRC	TD		11/30/2097
2020 PO1790233388	ODP	4	40 UNK	SP	CRE	ID	TD		12/1/2097
2020 PO1759433511	ODP	4	40 UNK	SP	CRE	ED,ID	TD		12/2/2097
2020 PO1500234565	ODP	6	35 SWP	SP	CRE		V		12/3/2097
2020 PO2075142973	F	4	40 KOP	DF	CRE		V		12/4/2097
2020 PO4936910449	F	4	40 ACE	SP	P		V		12/5/2097
2020 PO4929710267	F	4	40 ACE	SP	P		V		12/6/2097
2020 PO4965709829	F	4	40 ACE	SP	CRE	ED,HH,ID,IP,RB	BX	RP1	12/7/2097
2020 PO4959309709	F	5	35 ACE	SP	CRE	ED,ID	V		12/8/2097
2020 PO4940209945	F	4	40 ACE	SP	P		V		12/9/2097
2020 PO4950809888	F	4	40 ACE	SP	P		V		12/10/2097
2020 PO4923010024	F	4	40 ACE	SP	P		V		12/11/2097
2020 PO4920210035	F	4	40 ACE	SP	P		V		12/12/2097
2020 PO4912809826	F	4	40 ACE	SP	P		V		12/13/2097
2020 PO4906509678	F	4	40 ACE	SP	P		V		12/14/2097
2020 PO4953809333	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX	12/15/2097
2020 PO4949809236	F	5	35 ACE	SP	CRE		V		12/16/2097
2020 PO4920809509	KU	4	40 ACE	SP	P		V		12/17/2097
2020 PO4972109260	F	4	40 ACE	SP	CRE	ED,ID	V		12/18/2097
2020 PO4966709171	F	5	35 ACE	SP	CRE		V		12/19/2097
2020 PO4904709552	F	4	40 ACE	SP	CRE		V		12/20/2097
2020 PO4901709565	F	4	40 ACE	SP	CRE		V		12/21/2097
2020 PO4934709432	F	4	40 ACE	SP	CCA		V		12/22/2097
2020 PO4932209309	F	5	35 ACE	SP	CRE		V		12/23/2097
2020 PO2071242840	ODP	5	35 KOP	DF	CRE	ED,ID,RB,SRC	TX	RR	12/24/2097
2020 PO2094842002	ODP	5	35 KOP	SP	S		V		12/25/2097
2020 PO2115641662	ODP	6	30 KOP	SP	S		V		12/26/2097
2020 PO2138841318	ODP	4	35 KOP	SP	S		V		12/27/2097
2020 PO2301542274	F	4	40 KOP	SP	P		V		12/28/2097
2020 PO4894909402	F	4	40 ACE	SP	P		V		12/29/2097
2020 PO4887109218	F	4	40 ACE	SP	P		V		12/30/2097
2020 PO4918109001	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX	12/31/2097
2020 PO4901709066	F	4	40 ACE	SP	P		V		1/1/2098
2020 PO4883909142	F	4	40 ACE	SP	P		V		1/2/2098
2020 PO4821509864	F	4	40 ACE	SP	CRE		V		1/3/2098
2020 PO4839209797	F	4	40 ACE	SP	CRE		V		1/4/2098

2020 PO4831209829	F	4	40 ACE	SP	P		V	1/5/2098
2020 PO4852809744	F	4	40 ACE	SP	P		V	1/6/2098
2020 PO4866809690	F	4	40 ACE	SP	CRE		V	1/7/2098
2020 PO4849109290	F	4	40 ACE	SP	P		V	1/8/2098
2020 PO4868609207	F	4	40 ACE	SP	P		V	1/9/2098
2020 PO4830109359	F	4	40 ACE	SP	CRE	ED,ID	V	1/10/2098
2020 PO2397042596	ODP	6	30 KOP	DF	CRE	ED,ID	TD	1/11/2098
2020 PO2381745793	F	4	40 KOP	SP	P		V	1/12/2098
2020 PO2303945030	F	4	40 KOP	SP	CCA		V	1/13/2098
2020 PO2336344826	ODP	5	35 KOP	SP	S		V	1/14/2098
2020 PO2365645171	F	4	40 KOP	SP	P		V	1/15/2098
2020 PO2378345452	ODP	4	40 KOP	SP	CRE	ED,ID	TD	1/16/2098
2020 PO2367245393	ODP	4	45 KOP	SP	CCA		V	1/17/2098
2020 PO2346745362	F	4	40 KOP	SP	CCA		V	1/18/2098
2020 PO2349545299	ODP	4	40 KOP	SP	S		V	1/19/2098
2020 PO2390246011	F	4	40 KOP	SP	CCA		V	1/20/2098
2020 PO2377346033	ODP	6	30 KOP	SP	S		V	1/21/2098
2020 PO2777043993	ODP	4	40 KOP	SP	CRE	ED,ID	TD	1/22/2098
2020 PO4798909488	F	4	40 ACE	SP	CRE		V	1/23/2098
2020 PO4810309441	F	4	40 ACE	SP	CRE	ED,ID	V	1/24/2098
2020 PO4275410711	KU	4	40 ACE	SP	CRE	ED,ID	TD	1/25/2098
2020 PO4291511128	F	2	55 ACE	SP	CCA		V	1/26/2098
2020 PO4304411235	F	2	50 ACE	SP	CCA		V	1/27/2098
2020 PO4314711319	F	2	50 ACE	SP	CCA		V	1/28/2098
2020 PO4352411418	F	2	50 ACE	SP	CCA		V	1/29/2098
2020 PO4663509930	KU	6	30 ACE	SP	CRE	ED,ID	TD	1/30/2098
2020 PO4530810966	F	4	40 ACE	SP	CRE		V	1/31/2098
2020 PO4508811054	F	4	40 ACE	SP	CRE		V	2/1/2098
2020 PO4519711010	F	4	40 ACE	SP	CRE		V	2/2/2098
2020 PO4498311080	F	4	40 ACE	SP	CRE		V	2/3/2098
2020 PO4500411165	KU	6	30 ACE	SP	CCA		V	2/4/2098
2020 PO4628010234	F	4	40 ACE	SP	P		V	2/5/2098
2020 PO9225934782	ODP	6	30 BRN	SP	CRE		V	2/6/2098
2020 PO1350021810	ODP	5	35 XXX	SP	CCA	ED	T	2/7/2098
2020 PO1355621561	ODP	6	30 XXX	SP	CRE	ID	TD	2/8/2098
2020 PO1356421687	ODP	4	45 XXX	SP	CRE	ID	TD	2/9/2098
2020 PO1363321721	ODP	4	45 XXX	SP	A	ID	TD	2/10/2098
2020 PO1391222512	ODP	5	35 XXX	SP	CRE	ID	BD	2/11/2098
2020 PO1524922499	ODP	5	35 XXX	SP	CRE		V	2/12/2098
2020 PO1411222518	ODP	5	35 XXX	SP	CRE	ID	TD	2/13/2098
2020 PO1447522563A	ODP	4	40 XXX	SP	CRE	ID	TD	2/14/2098
2020 PO1447522563	ODP	4	45 XXX	SP	CRE	ID	TD	2/15/2098
2020 PO1450522395	F	4	40 XXX	SP	A		V	2/16/2098
2020 PO1444822159	ODP	6	30 XXX	SP	CRE		V	2/17/2098
2020 PO1471022147A	ODP	5	35 XXX	SP	CRE	ID	BD	2/18/2098
2020 PO1490922118	ODP	6	30 XXX	SP	CRE	ID	TD	2/19/2098
2020 PO1471022147	ODP	6	30 XXX	SP	CRE	ID	TD	2/20/2098

2020 PO1452422218	ODP	4	40 XXX	SP	CRE	ID	TD	2/21/2098
2020 PO1438122086	ODP	3	40 XXX	SP	CCA		V	2/22/2098
2020 PO1453522094	ODP	4	40 XXX	SP	CCA		V	2/23/2098
2020 PO1441023235	ODP	5	35 XXX	SP	CRE	ID	BD	2/24/2098
2020 PO1435223012	ODP	5	35 XXX	SP	CCA		V	2/25/2098
2020 PO1447823100	ODP	4	45 XXX	SP	CCA		V	2/26/2098
2020 PO1460823042	ODP	3	45 XXX	SP	CCA		V	2/27/2098
2020 PO1455622986	ODP	4	40 XXX	SP	CRE	ID	BD	2/28/2098
2020 PO1462222805	ODP	2	50 XXX	SP	CCA		V	3/1/2098
2020 PO1464522701	ODP	5	35 XXX	SP	CRE	ID	TD	3/2/2098
2020 PO1473722752	ODP	3	50 XXX	SP	CRE	ID	TD	3/3/2098
2020 PO1474122639	ODP	4	40 XXX	SP	CRE	ID	TD	3/4/2098
2020 PO1541522963A	ODP	4	40 XXX	SP	CCA		V	3/5/2098
2020 PO1527222812	ODP	4	40 XXX	SP	CRE		V	3/6/2098
2020 PO1541522963	ODP	4	40 XXX	SP	CRE	ID	TD	3/7/2098
2020 PO1507022980	ODP	4	40 XXX	SP	CRE	ID	BD	3/8/2098
2020 PO1509422775	ODP	4	40 XXX	SP	CRE	ID	TD	3/9/2098
2020 PO1503422670	ODP	4	40 XXX	SP	CRE	ID	TD	3/10/2098
2020 PO1498622610	ODP	3	50 XXX	SP	CRE	ID	TD	3/11/2098
2020 PO1536722108	F	4	40 XXX	SP	A		V	3/12/2098
2020 PO1544321914	ODP	6	30 XXX	SP	CRE	ID	TD	3/13/2098
2020 PO1545922107	ODP	5	35 XXX	SP	CCA	ED	T	3/14/2098
2020 PO1537522227	F	4	40 XXX	SP	CRE		V	3/15/2098
2020 PO1530622246	ODP	4	40 XXX	SP	CCA		V	3/16/2098
2020 PO1537422194	ODP	2	50 XXX	SP	CCA	ED	T	3/17/2098
2020 PO1523522322	ODP	4	40 XXX	SP	CRE	ID	TD	3/18/2098
2020 PO1531522462	F	4	40 XXX	SP	CCA		V	3/19/2098
2020 PO1529922688	ODP	4	40 XXX	SP	CRE	ID	TD	3/20/2098
2020 PO1531322571	ODP	4	40 XXX	SP	CRE	ID	TD	3/21/2098
2020 PO1541822778	ODP	4	40 XXX	SP	CRE	ID,IP	TX	3/22/2098
2020 PO1552022871	ODP	4	45 XXX	SP	CRE	ID	TD	3/23/2098
2020 PO1155427882	ODP	4	40 XXX	SP	CCA		V	3/24/2098
2020 PO1561422277	ODP	4	40 XXX	SP	CCA		V	3/25/2098
2020 PO6004537909	KU	4	40 BRN	SP	CRE	ED,ID	TD	3/26/2098
2020 PO6003037738	KU	4	40 BRN	SP	S		V	3/27/2098
2020 PO5590344921	KU	6	30 ACW	SP	CRE	ED,ID	TD	3/28/2098
2020 PO5584744857	KU	6	30 ACW	SP	CRE	ED,ID	TD	3/29/2098
2020 PO5591444786	KU	6	30 ACW	SP	CRE	ED,ID	TD	3/30/2098
2020 PO4526822284	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	3/31/2098
2020 PO3358852253	F	4	40 ACE	SP	CRE		V	4/1/2098
2020 PO3358352314	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	4/2/2098
2020 PO3447252623	KU	4	40 ACE	SP	CRE	ED,ID	TD	4/3/2098
2020 PO3356152998	KU	4	40 ACE	SP	CRE	ED,ID	TD	4/4/2098
2020 PO6000338612	KU	4	40 BRN	SP	CRE	ED,ID	TD	4/5/2098
2020 PO6009538970	KU	4	45 BRN	SP	CRE	ED,ID	TD	4/6/2098
2020 PO6023039251	KU	3	45 BRN	SP	CCA		V	4/7/2098
2020 PO6022039046	KU	6	30 BRN	SP	CRE	ED,ID	TD	4/8/2098

2020 PO4515922373	KU	4	45 BRO	SP	CCA	ED	T	4/9/2098	
2020 PO4461421853	KU	4	45 BRO	SP	CRE	ED	T	4/10/2098	
2020 PO3356552876	KU	4	40 ACE	SP	CRE	ED,EP,ID,IP	TX	RR	4/11/2098
2020 PO1347833225B	ODP	5	30 XXX	SP	CRE	ID	TD	4/12/2098	
2020 PO134783325	ODP	6	30 XXX	SP	CRE	ID	TD	4/13/2098	
2020 PO1347833225	F	4	40 XXX	SP	CRE		V	4/14/2098	
2020 PO1360733311	F	4	40 XXX	SP	A		V	4/15/2098	
2020 PO1377833404	F	4	40 XXX	SP	A		V	4/16/2098	
2020 PO1356732969	ODP	4	40 XXX	SP	CRE	ID	TD	4/17/2098	
2020 PO1339933015	ODP	6	30 XXX	SP	CCA	ED	T	4/18/2098	
2020 PO1412833383	ODP	6	30 XXX	SP	CCA		V	4/19/2098	
2020 PO1402833262	ODP	4	40 XXX	SP	CRE	ID	TD	4/20/2098	
2020 PO1408733167	ODP	4	45 XXX	SP	CCA		V	4/21/2098	
2020 PO1391733085	F	4	40 XXX	SP	CRE		V	4/22/2098	
2020 PO1807024267	F	4	40 XXX	SP	CRE		V	4/23/2098	
2020 PO1821324059	ODP	5	30 XXX	SP	CRE	ID	TD	4/24/2098	
2020 PO1827824018	F	4	40 XXX	SP	CRE		V	4/25/2098	
2020 PO1977323885	ODP	5	35 XXX	SP	CCA		V	4/26/2098	
2020 PO1982923780	ODP	4	40 XXX	SP	CCA		V	4/27/2098	
2020 PO3861582201	LGE	4	40 BRO	SP	CRE		V	4/28/2098	
2020 PO3861482205	LGE	1	65 BRO	SP	A	ED,ID,IP	TD	4/29/2098	
2020 PO3865182193	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	4/30/2098	
2020 PO3864282199	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	5/1/2098	
2020 PO3863582196	LGE	4	30 BRO	SP	A	ED,ID	BD	5/2/2098	
2020 PO3862782208	LGE	4	40 BRO	SP	P	ED,ID	BD	5/3/2098	
2020 PO3864782275	LGE	1	90 BRO	SP	CRE		V	5/4/2098	
2020 PO3863782250	LGE	1	80 BRO	SP	CRE		V	5/5/2098	
2020 PO3862782225	LGE	1	70 BRO	SP	CRE		V	5/6/2098	
2020 PO5857532494	LGE	3	45 BRO	SP	CCA		V	5/7/2098	
2020 PO5859134096	LGE	3	45 BRO	SP	CCA		V	5/8/2098	
2020 PO5862833981	LGE	3	45 BRO	SP	CCA		V	5/9/2098	
2020 PO3859682177	LGE	1	65 BRO	SP	CRE		V	5/10/2098	
2020 PO3860782193	LGE	1	65 BRO	SP	CRE		V	5/11/2098	
2020 PO3858382159	LGE	1	65 BRO	SP	CRE		V	5/12/2098	
2020 PO0674217975	KU	5	35 BRN	SP	CRE		V	5/13/2098	
2020 PO0680818125	KU	5	35 BRN	SP	CRE		V	5/14/2098	
2020 PO7083521888A	KU	5	35 BRN	SP	CRE	ID	B	5/15/2098	
2020 PO7051921827	KU	5	35 BRN	SP	CRE	ED,EP,HH,ID	X	RP1	5/16/2098
2020 PO7047921952	KU	4	40 BRN	SP	CRE	ID	TD	5/17/2098	
2020 PO7036221854	KU	5	35 BRN	SP	CRE	ID	TD	5/18/2098	
2020 PO7083521888	KU	5	35 BRN	SP	CRE	ID	TD	5/19/2098	
2020 PO6726721660	KU	5	35 BRN	SP	CRE	ED,ID	TD	5/20/2098	
2020 PO6711821991	KU	5	35 BRN	SP	CRE		V	5/21/2098	
2020 PO6695822167	KU	4	40 BRN	SP	CRE	ID	TD	5/22/2098	
2020 PO6698221677A	KU	4	40 BRN	SP	CCA		V	5/23/2098	
2020 PO6712922216	KU	4	45 BRN	SP	CCA		V	5/24/2098	
2020 PO7252920475	KU	4	40 BRN	SP	CRE	ID	TD	5/25/2098	

2020 PO7248620635	KU	4	40 BRN	SP	CRE	ID	TD	5/26/2098
2020 PO7217120757	KU	5	35 BRN	SP	CRE	ID	TD	5/27/2098
2020 PO7194520845	KU	5	35 BRN	SP	CRE	ID	TD	5/28/2098
2020 PO7555720216	KU	3	55 BRN	SP	CRE	ED,HH,ID,IP,MD	BX	5/29/2098
2020 PO7300319756	KU	4	45 BRN	SP	CCA		V	5/30/2098
2020 PO7306619524	KU	4	45 BRN	SP	CCA		V	5/31/2098
2020 PO7316119167	KU	4	45 BRN	SP	CCA		V	6/1/2098
2020 PO7334518989	KU	4	45 BRN	SP	CCA		V	6/2/2098
2020 PO7331018742	KU	4	45 BRN	SP	CCA		V	6/3/2098
2020 PO7353518542	KU	4	40 XXX	SP	CCA		V	6/4/2098
2020 PO7365818475	KU	4	45 XXX	SP	CRE	ED	TD	6/5/2098
2020 PO7423718361	KU	4	45 XXX	SP	CRE	ID	BD	6/6/2098
2020 PO7400018380	KU	4	45 BRN	SP	CRE		V	6/7/2098
2020 PO7434818359	KU	4	40 BRN	SP	CCA		V	6/8/2098
2020 PO7446218394	KU	4	40 BRN	SP	CCA		V	6/9/2098
2020 PO7460018449	KU	4	40 BRN	SP	CRE	ID	BD	6/10/2098
2020 PO7477018521	KU	4	40 BRN	SP	CRE	ID	BD	6/11/2098
2020 PO7492718623	KU	4	40 BRN	SP	CRE	ED	TD	6/12/2098
2020 PO7503018681	KU	4	40 BRN	SP	CRE	ED	TD	6/13/2098
2020 PO7527218833	KU	4	40 BRN	SP	CCA		V	6/14/2098
2020 PO7534418897	KU	4	45 BRN	SP	CCA		V	6/15/2098
2020 PO7557718744	KU	4	40 BRN	SP	CRE	ED	TD	6/16/2098
2020 PO7544518785	KU	4	40 BRN	SP	CRE	ED	TD	6/17/2098
2020 PO7537718797	KU	5	35 BRN	SP	CRE	ID	TD	6/18/2098
2020 PO7589519801A	KU	4	40 BRN	SP	CRE	ED	TD	6/19/2098
2020 PO7577519469	KU	4	35 BRN	SP	CRE	ED	TD	6/20/2098
2020 PO7579519459	KU	4	40 BRN	SP	CRE	ED	TD	6/21/2098
2020 PO2342436013	F	4	40 UNK	SP	CRE		V	6/22/2098
2020 PO2350636217	F	4	40 UNK	SP	CRE		V	6/23/2098
2020 PO2364136309	F	4	40 UNK	SP	CRE		V	6/24/2098
2020 PO2364136309A	F	4	40 UNK	SP	CRE		V	6/25/2098
2020 PO2401636534	F	4	35 UNK	SP	CRE		V	6/26/2098
2020 PO2384936453	F	4	40 UNK	SP	CRE		V	6/27/2098
2020 PO3934582168	F	3	45 CAH	SP	CCA		V	6/28/2098
2020 PO4069483278	LGE	4	40 CAH	SP	CRE	ED,ID	BD	6/29/2098
2020 PO3927082112	F	3	45 BRN	SP	CCA		V	6/30/2098
2020 PO4034182633	LGE	4	30 BRN	SP	CRE		V	7/1/2098
2020 PO4033982674	F	4	40 BRN	SP	CRE		V	7/2/2098
2020 PO4035782682	F	4	30 BRN	SP	CRE		V	7/3/2098
2020 PO4035382687	F	4	40 BRN	SP	CRE		V	7/4/2098
2020 PO4036882699	F	4	40 BRN	SP	CRE		V	7/5/2098
2020 PO4037982709	F	4	40 BRN	SP	CRE		V	7/6/2098
2020 PO3853382070	LGE	2	65 BRO	SP	A		V	7/7/2098
2020 PO4069383332	LGE	4	35 CAH	SP	CRE	ED,ID	BD	7/8/2098
2020 PO4069383343	LGE	4	40 CAH	SP	CRE	ED,ID	TD	7/9/2098
2020 PO4070483334	LGE	4	45 CAH	SP	CRE	ED,ID	BD	7/10/2098
2020 PO5778545366	C	4	40 ACE	SP	CRE		V	7/11/2098

2020 PO9277483240A	KU	5	35 BRN	SP	CRE	ED,ID	TD		7/12/2098
2020 PO9277483240	KU	4	30 BRN	SP	P	ED,ID	TD		7/13/2098
2020 PO9268283600	KU	3	50 BRN	SP	S		V		7/14/2098
2020 PO9272783283	F	4	40 BRN	SP	CRE	ED,ID,RB	BX	RP2	7/15/2098
2020 PO9562093859	C	6	30 ACW	SP	CRE		V		7/16/2098
2020 PO9565693845	C	4	40 ACW	SP	CRE		V		7/17/2098
2020 PO9566993831	F	3	45 ACW	SP	CRE		V		7/18/2098
2020 PO9569693763	F	3	45 ACW	SP	CRE		V		7/19/2098
2020 PO9233383245	KU	4	40 BRN	SP	CRE	ED,ID,RB	TX	RR	7/20/2098
2020 PO9199883429	KU	4	40 BRN	SP	CRE	ID	BD		7/21/2098
2020 PO9230992748	KU	5	35 ACW	SP	CRE	ED,ID,IP,RB,SRC	TD		7/22/2098
2020 PO4567910291	KU	5	35 BRO	SP	CRE	ED,ID,IP,MD	TX	RR	7/23/2098
2020 PO4877086210	LGE	4	40 OTH	SP	CRE	ED,ID,IP,RB	X	PX	7/24/2098
2020 PO4862986809	LGE	4	35 XXX	SP	CRE	ED,ID,RB	X	PX	7/25/2098
2020 PO4864386808	LGE	3	45 XXX	SP	A	ID	BD		7/26/2098
2020 PO5779281148	LGE	3	45 XXX	SP	CCA		V		7/27/2098
2020 PO4864286795	LGE	4	40 XXX	SP	A	ED,ID	TD		7/28/2098
2020 PO4944686823	LGE	4	40 OTH	SP	P	ED,ID,SRC	TD		7/29/2098
2020 PO4945686858	LGE	3	50 OTH	SP	CRE	ED,ID,SRS	TD		7/30/2098
2020 PO4944186803	LGE	4	40 OTH	SP	P	ED,ID,IP,SRS	TD		7/31/2098
2020 PO4936686882	LGE	4	40 OTH	SP	CRE	ED,EP,ID,IP,RB	X	PX	8/1/2098
2020 PO4943386781	LGE	4	40 OTH	SP	P	ED,ID,IP,SRC	TD		8/2/2098
2020 PO4932986868	LGE	4	30 OTH	SP	CRE	ED,HH,ID,IP,SRS	TD		8/3/2098
2020 PO4945086823	LGE	1	20 OTH	UN	P		V		8/4/2098
2020 PO4862186794	LGE	4	40 XXX	SP	A	ED,ID	TD		8/5/2098
2020 PO4860286795	LGE	4	40 XXX	SP	A	ED,ID,SRC	TX	RR	8/6/2098
2020 PO4858686790	LGE	3	45 XXX	SP	A	ED,ID	TD		8/7/2098
2020 PO4931786863	LGE	4	40 OTH	SP	CRE	ED,ID,IP,SRS	TD		8/8/2098
2020 PO4856786785	LGE	3	45 XXX	SP	A	ID	BD		8/9/2098
2020 PO4878887157	LGE	4	30 XXX	SP	CCA		V		8/10/2098
2020 PO4925886725	LGE	4	40 OTH	SP	P	ED,ID,RB	X	PX	8/11/2098
2020 PO1078219776	F	4	40 XXX	SP	CRE		V		8/12/2098
2020 PO1077620085A	ODP	4	40 XXX	SP	A		V		8/13/2098
2020 PO1018920382	F	4	40 XXX	SP	A		V		8/14/2098
2020 PO0998420444	F	4	40 XXX	SP	P		V		8/15/2098
2020 PO0984420493	F	4	40 XXX	SP	CRE		V		8/16/2098
2020 PO1071718809B	ODP	5	35 UNK	SP	CRE	ED,ID,SRS	TD		8/17/2098
2020 PO1071718809A	ODP	4	35 UNK	SP	CRE	ED,ID,SRS	TD		8/18/2098
2020 PO1036819968	ODP	5	35 UNK	SP	CRE	ED,ID,IP	X	RP3	8/19/2098
2020 PO1071718809	ODP	4	40 INP	SP	CRE	ID	TD		8/20/2098
2020 PO1073419023	ODP	4	45 BRN	SP	CCA	ED,SRS	TD		8/21/2098
2020 PO1027220290	ODP	6	30 BRN	SP	CCA	ED,SRS	TD		8/22/2098
2020 PO4876986903	LGE	1	65 XXX	SP	CRE	ED,ID	TD		8/23/2098
2020 PO4875486911	LGE	1	65 XXX	SP	CRE	ED,ID	TD		8/24/2098
2020 PO4927186765	LGE	1	20 OTH	UN	A		V		8/25/2098
2020 PO4927186764	LGE	3	45 OTH	SP	P	ED,SRS	TD		8/26/2098
2020 PO4926786736	LGE	4	40 OTH	SP	P	ED,ID,SRS	TD		8/27/2098

2020 PO4837286725	F	4	40 XXX	SP	CRE	IP	V	8/28/2098
2020 PO4840186793	F	4	35 XXX	SP	CRE		V	8/29/2098
2020 PO4839686777	F	4	40 XXX	SP	CRE		V	8/30/2098
2020 PO4839186763	F	1	55 XXX	SP	CCA		V	8/31/2098
2020 PO4838186740	F	3	50 XXX	SP	CCA		V	9/1/2098
2020 PO4836886718	F	4	40 XXX	SP	CRE		V	9/2/2098
2020 PO4832686768	LGE	3	45 XXX	SP	P	ID	TD	9/3/2098
2020 PO4873386915	LGE	1	65 XXX	SP	CRE	ID	BD	9/4/2098
2020 PO6443279870A	LGE	3	45 OTH	SP	CCA		V	9/5/2098
2020 PO4916086765	LGE	4	35 OTH	SP	CCA		V	9/6/2098
2020 PO4916886768	LGE	4	35 OTH	SP	CCA	ED,SRS	TD	9/7/2098
2020 PO4033682601	F	4	40 BRN	SP	CCA		V	9/8/2098
2020 PO4622231986	KU	4	40 ACE	SP	CRE	ED,ID	TD	9/9/2098
2020 PO4032582614	F	4	40 BRN	SP	CCA		V	9/10/2098
2020 PO4032882618	F	6	25 BRN	SP	CRE		VX	9/11/2098
2020 PO4031582625	F	4	40 BRN	SP	S		V	9/12/2098
2020 PO4030582636	F	4	40 BRN	SP	A		V	9/13/2098
2020 PO4029782646	F	4	40 BRN	SP	CRE		V	9/14/2098
2020 PO4633131935	KU	4	40 ACE	SP	P	ED	T	9/15/2098
2020 PO4629432168	KU	4	45 ACE	SP	CRE	ED,ID	BD	9/16/2098
2020 PO4028782657	F	4	40 BRN	SP	CRE		V	9/17/2098
2020 PO7473238395	LGE	4	35 BRN	SP	CRE	ED,ID	TD	9/18/2098
2020 PO4027882668	F	4	40 BRN	SP	A		V	9/19/2098
2020 PO4027382681	LGE	4	30 BRN	SP	A	ED,ID	TX	9/20/2098
2020 PO4026882679	F	4	40 BRN	SP	A		V	9/21/2098
2020 PO4025982690	F	4	40 BRN	SP	CRE		V	9/22/2098
2020 PO4024982700	F	3	45 BRN	SP	S		V	9/23/2098
2020 PO4024082711	F	4	40 BRN	SP	CRE		V	9/24/2098
2020 PO4024382713	F	4	30 BRN	SP	CRE		V	9/25/2098
2020 PO4023068943	F	4	40 BRN	SP	S		V	9/26/2098
2020 PO4021882760	F	3	45 BRN	SP	S		V	9/27/2098
2020 PO4021882745	F	4	45 BRN	SP	A		V	9/28/2098
2020 PO4021182743	F	6	30 BRN	SP	CRE		V	9/29/2098
2020 PO4021782734	F	3	40 BRN	SP	CRE		V	9/30/2098
2020 PO4353540090	KU	1	60 BRO	SP	CCA		V	10/1/2098
2020 PO4020782725	F	4	40 BRN	SP	CRE		V	10/2/2098
2020 PO4253840905	F	2	45 BRO	SP	CCA		V	10/3/2098
2020 PO4243441048	F	4	40 BRO	SP	CCA		V	10/4/2098
2020 PO4018782723	F	4	30 BRN	SP	S		V	10/5/2098
2020 PO4019482714	F	3	45 BRN	SP	S		V	10/6/2098
2020 PO4020282704	F	3	45 BRN	SP	S		V	10/7/2098
2020 PO4639332081	KU	4	40 ACE	SP	P	ED	T	10/8/2098
2020 PO4021282694	F	4	40 BRN	SP	A		V	10/9/2098
2020 PO4641032120	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	10/10/2098
2020 PO4021282676	LGE	4	35 BRN	SP	P	ED,ID	TD	10/11/2098
2020 PO4022082684	F	4	40 BRN	SP	CRE		V	10/12/2098
2020 PO4022982673	F	3	45 BRN	SP	CCA		V	10/13/2098

2020 PO4505210495	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	10/14/2098	
2020 PO4531309846	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	10/15/2098	
2020 PO4546710006	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	10/16/2098	
2020 PO4446709406	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	10/17/2098	
2020 PO4512609549	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	10/18/2098	
2020 PO4497609602	KU	3	45 BRO	SP	CCA		V	10/19/2098	
2020 PO4517609665	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	10/20/2098	
2020 PO9241092757	KU	5	35 ACW	SP	CRE	ED,ID,IP	TD	10/21/2098	
2020 PO9239092720	KU	6	30 ACW	SP	CRE	ED,ID	BD	10/22/2098	
2020 PO9253692908A	KU	5	35 ACW	SP	CRE	ED,ID	TD	10/23/2098	
2020 PO9260892736	KU	4	40 ACW	SP	CRE	ED,ID	TD	10/24/2098	
2020 PO9407693123	C	5	35 ACW	SP	S		V	10/25/2098	
2020 PO9438093380	C	4	40 ACW	SP	CRE		V	10/26/2098	
2020 PO9445893245	C	4	35 ACW	SP	S		V	10/27/2098	
2020 PO9441893255	KU	5	35 ACW	SP	CRE	ED,ID	TD	10/28/2098	
2020 PO9438193180	KU	5	35 ACW	SP	CRE	ED,ID	TD	10/29/2098	
2020 PO9358993186	KU	4	45 ACW	SP	CRE	ED,ID,MD,SRC	TX	RR	10/30/2098
2020 PO4758610121	KU	3	45 BRO	SP	CRE	ED,ID	TD	10/31/2098	
2020 PO5972144053a	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	11/1/2098	
2020 PO5972144053	KU	4	40 ACE	SP	P	ED,ID	TD	11/2/2098	
2020 PO4771710505	KU	4	45 BRO	SP	CRE	ED,ID	TD	11/3/2098	
2020 PO4765410308	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD	11/4/2098	
2020 PO5906443625	KU	4	45 ACE	SP	CRE	ED,ID	BD	11/5/2098	
2020 PO5925043637	F	3	45 ACE	SP	CCA		V	11/6/2098	
2020 PO5990249310	F	6	30 ACE	SP	P		V	11/7/2098	
2020 PO4777910649	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD	11/8/2098	
2020 PO4786310917	KU	2	60 BRO	SP	CRE	ED,ID,IP	TD	11/9/2098	
2020 PO4792710490	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	11/10/2098	
2020 PO6006949308	KU	5	35 ACE	SP	CRE	ED,ID	BD	11/11/2098	
2020 PO6376147251	F	4	40 ACE	SP	CRE		V	11/12/2098	
2020 PO9184382139	F	4	40 BRN	SP	CRE		V	11/13/2098	
2020 PO5716254822a	KU	5	30 ACE	SP	CCA		V	11/14/2098	
2020 PO5716254822	KU	6	30 ACE	SP	CRE	ED,ID	TD	11/15/2098	
2020 PO5713054677	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	11/16/2098	
2020 PO3865935580	KU	6	30 BRN	SP	CRE	ED,ID,MD	TD	11/17/2098	
2020 PO3858335440	KU	4	40 BRN	SP	CRE	ED,ID,IP,SRC	TD	11/18/2098	
2020 PO3920436552	F	4	35 BRN	SP	CRE		V	11/19/2098	
2020 PO3917935096	KU	5	30 BRN	SP	CRE		V	11/20/2098	
2020 PO3883835368	KU	4	35 BRN	SP	CRE	ED,ID,IP,SRC	TD	11/21/2098	
2020 PO3909035286	KU	4	35 BRN	SP	CRE	ED,ID,SRS	TD	11/22/2098	
2020 PO3923235237	KU	5	35 BRN	SP	CRE	ID	BD	11/23/2098	
2020 PO4024782666	F	4	40 BRN	SP	CCA		V	11/24/2098	
2020 PO4020682633	F	4	40 BRN	SP	CRE		V	11/25/2098	
2020 PO4021982643	F	3	45 BRN	SP	S		V	11/26/2098	
2020 PO4023782648	F	4	35 BRN	SP	CRE		V	11/27/2098	
2020 PO4023282653	F	4	40 BRN	SP	A		V	11/28/2098	
2020 PO4024082661	F	3	40 BRN	SP	CRE		V	11/29/2098	

2020 PO4652232375	KU	5	35 ACE	SP	CRE	ED,ID	TD	11/30/2098
2020 PO4259841001	KU	3	50 BRO	SP	CCA		V	12/1/2098
2020 PO4348039951	F	4	40 BRO	SP	CCA		V	12/2/2098
2020 PO4025482646	F	4	40 BRN	SP	CRE		V	12/3/2098
2020 PO4026382635	F	4	40 BRN	SP	CRE		V	12/4/2098
2020 PO4027282625	F	4	40 BRN	SP	CRE		V	12/5/2098
2020 PO4028282614	F	4	40 BRN	SP	CRE		V	12/6/2098
2020 PO4029282603	F	4	40 BRN	SP	A		V	12/7/2098
2020 PO4030182593	F	4	40 BRN	SP	A		V	12/8/2098
2020 PO4030482595	F	4	40 BRN	SP	CRE		V	12/9/2098
2020 PO4662232603	KU	5	35 ACE	SP	CRE	ED,ID	TD	12/10/2098
2020 PO4651032646	KU	5	35 ACE	SP	CCA		V	12/11/2098
2020 PO4646332664	KU	5	35 ACE	SP	CCA		V	12/12/2098
2020 PO4031482604	F	3	40 BRN	SP	A		V	12/13/2098
2020 PO4234441144	F	2	45 BRO	SP	CRE		V	12/14/2098
2020 PO4261240801	F	2	45 BRO	SP	A		V	12/15/2098
2020 PO4268940728	KU	2	50 BRO	SP	P		T	12/16/2098
2020 PO4288240503	KU	2	55 BRO	SP	CCA		V	12/17/2098
2020 PO3950735020	KU	4	40 BRN	SP	A	ED,ID,SRS	TD	12/18/2098
2020 PO3911234908	KU	5	30 BRN	SP	CRE		V	12/19/2098
2020 PO3939534481	KU	4	40 BRN	SP	A	ED,ID,SRS	TD	12/20/2098
2020 PO3936234314	KU	4	40 BRN	SP	CRE	ED,ID,SRS	TD	12/21/2098
2020 PO3850035654	KU	5	35 BRN	SP	CRE	ED,ID,IP,SRS	TD	12/22/2098
2020 PO3896035995	KU	4	40 BRN	SP	A	ED	T	12/23/2098
2020 PO3874536123	KU	5	35 BRN	SP	CRE	ID	BD	12/24/2098
2020 PO3860435859	KU	5	35 BRN	SP	CRE	ID	BD	12/25/2098
2020 PO3908736331	KU	4	40 BRN	SP	CRE	ED,MD	T	12/26/2098
2020 PO3759145583	KU	6	30 BRN	SP	CRE	ED,ID	TD	12/27/2098
2020 PO3776045655	KU	4	40 BRN	SP	CRE	ED,ID	TD	12/28/2098
2020 PO377445755	KU	4	40 BRN	SP	CRE	ID	BD	12/29/2098
2020 PO3803645571	KU	5	35 BRN	SP	CRE	ID	BD	12/30/2098
2020 PO3824145427	KU	4	40 BRN	SP	CRE		V	12/31/2098
2020 PO3972683122	LGE	4	40 BRO	SP	CRE	ED,ID	TD	1/1/2099
2020 PO2734353216	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	1/2/2099
2020 PO2712953364	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	1/3/2099
2020 PO2705253389	KU	5	35 BRO	SP	CRE	ED	TD	1/4/2099
2020 PO2566054165	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	1/5/2099
2020 PO3062840562	KU	3	45 ACE	SP	CRE	ED,ID	TD	1/6/2099
2020 PO2540054267	KU	6	35 BRO	SP	CRE	ED,ID,IP	TD	1/7/2099
2020 PO2716953035	KU	4	35 BRO	SP	CRE	ED,ID,IP	TD	1/8/2099
2020 PO3877583070	LGE	4	40 BRO	SP	P	ED,ID,IP,RB,SRC	TX	RR 1/9/2099
2020 PO3880583067	LGE	4	35 BRO	SP	P	ED,ID	TD	1/10/2099
2020 PO3882483065	LGE	4	35 BRO	SP	P	ED,ID	TD	1/11/2099
2020 PO1090834032	F	4	40 OTH	SP	CRE	ED	V	1/12/2099
2020 PO1075633467	ODP	4	45 BRN	SP	CCA		V	1/13/2099
2020 PO1077633555	ODP	2	50 BRN	SP	CCA		V	1/14/2099
2020 PO1088333678	ODP	5	35 BRN	SP	CCA		V	1/15/2099

2020 PO3953182675	LGE	1	95 BRN	ST	CCA		V			1/16/2099
2020 PO6852895121	KU	4	40 BRN	SP	S		V			1/17/2099
2020 PO6855195270	KU	4	40 BRN	SP	CRE	ED,ID	BD			1/18/2099
2020 PO6857295420	KU	4	40 BRN	SP	CRE	ED,ID	BD			1/19/2099
2020 PO6895395609	KU	4	45 BRN	SP	CCA		V			1/20/2099
2020 PO6893795658	KU	1	45 BRN	SP	CRE		V			1/21/2099
2020 PO6877795673	KU	4	45 BRN	SP	CRE	ED,ID	BD			1/22/2099
2020 PO6877495618	KU	5	35 BRN	SP	CRE	ED,ID,SR	TD			1/23/2099
2020 PO2690752342	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD			1/24/2099
2020 PO2703552679	KU	4	35 BRO	SP	CRE	ED,ID,IP	TD			1/25/2099
2020 PO2493454451	KU	4	40 BRO	SP	CCA		V			1/26/2099
2020 PO3953582684	LGE	2	40 BRN	SP	CCA	ED,ID	BD			1/27/2099
2020 PO1083533916	F	4	40 OTH	SP	CRE	ID	V			1/28/2099
2020 PO1082334033	F	4	40 OTH	SP	CRE		V			1/29/2099
2020 PO1100934007	F	4	20E OTH	SP	CRE		V			1/30/2099
2020 PO0980532291	ODP	4	45 BRN	SP	CRE	ED,ID	TD			1/31/2099
2020 PO3623941191	KU	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,MD,RB	BX	RP1		2/1/2099
2020 PO3871583076	LGE	4	40 BRO	SP	P	ED,ID,IP,RB,SR	TX	RR		2/2/2099
2020 PO0972232083	ODP	5	35 BRN	SP	CRE	ED,ID	TD			2/3/2099
2020 PO0975332171	ODP	4	40 BRN	SP	CRE	ED,ID	TD			2/4/2099
2020 PO6866695091	KU	6	30 BRN	SP	CCA	ED,ID	BD			2/5/2099
2020 PO3620641122	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD			2/6/2099
2020 PO3609841122	KU	5	35 ACE	SP	CRE	ED,ID	BD			2/7/2099
2020 PO0970231936	ODP	4	45 BRN	SP	CRE	ED,ID	TD			2/8/2099
2020 PO2478654509	KU	4	40 BRO	SP	CRE	ED	TD			2/9/2099
2020 PO2516754359	KU	6	35 BRO	SP	CRE	ED,ID,IP	TD			2/10/2099
2020 PO2461154569	KU	5	30 BRO	SP	CRE	ED,ID,IP	TD			2/11/2099
2020 PO6863694953	KU	6	30 BRN	SP	CRE	ED,ID	TD			2/12/2099
2020 PO3972983109	LGE	4	40 BRO	SP	CCA		V			2/13/2099
2020 PO3963883276	F	4	40 BRO	SP	CRE		V			2/14/2099
2020 PO3960383274	F	4	40 BRO	SP	CRE		V			2/15/2099
2020 PO3963883288	F	4	40 BRO	SP	CRE		V			2/16/2099
2020 PO3961483267	F	4	30 BRO	SP	CRE		V			2/17/2099
2020 PO3961483274	F	4	40 BRO	SP	CCA		V			2/18/2099
2020 PO3963083284	F	4	35 BRO	SP	CRE		V			2/19/2099
2020 PO3962483271	LGE	4	30 BRO	SP	CRE		V			2/20/2099
2020 PO3873583099	LGE	4	35 BRO	SP	P	ED,ID,IP	TD			2/21/2099
2020 PO3871383086	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD			2/22/2099
2020 PO3871183099	LGE	4	35 BRO	SP	P	ED,ID	TD			2/23/2099
2020 PO3871683088	LGE	4	30 BRO	SP	CRE	ED,ID	BD			2/24/2099
2020 PO3974383111	LGE	4	40 BRO	SP	CRE	ED,ID	TD			2/25/2099
2020 PO3975483118	LGE	4	30 BRO	SP	CRE	ED,ID	TD			2/26/2099
2020 PO3976083114	LGE	4	40 BRO	SP	CRE	ED,ID	TD			2/27/2099
2020 PO3977683132	LGE	4	30 BRO	SP	CRE		V			2/28/2099
2020 PO3977783122	LGE	4	30 BRO	SP	CRE	ID	BD			3/1/2099
2020 PO3978383118	LGE	6	25 BRO	SP	CRE	ED,ID	TD			3/2/2099
2020 PO3977483117	LGE	4	30 BRO	SP	CRE	ED,ID	TD			3/3/2099

2020 PO3977583117	LGE	4	40 BRO	SP	CCA		V		3/4/2099
2020 PO3673740957b	KU	5	30 ACE	SP	CRE	ED,ID,IP	TD		3/5/2099
2020 PO3875183098	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD		3/6/2099
2020 PO3673740957a	KU	5	35 ACE	SP	CCA		V		3/7/2099
2020 PO3673740957	KU	4	35 ACE	DF	CRE	ED,ID,IP	TD		3/8/2099
2020 PO3668340870	KU	5	30 ACE	SP	CRE	ED,ID	TD		3/9/2099
2020 PO1006333156	ODP	3	55 BRN	SP	CRE	ED,ID	TD		3/10/2099
2020 PO2696553478	KU	5	35 BRO	SP	CRE	ED	TD		3/11/2099
2020 PO2671453632	KU	4	40 BRO	SP	P	ED	T		3/12/2099
2020 PO3655641042	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		3/13/2099
2020 PO3648740892	KU	5	35 ACE	SP	CRE	ED,ID	TD		3/14/2099
2020 PO1013133324	ODP	3	50 BRN	SP	CRE	ED,ID	TD		3/15/2099
2020 PO1012933300	ODP	2	50 BRN	SP	CCA		V		3/16/2099
2020 PO1011033307	ODP	2	50 BRN	SP	CCA		V		3/17/2099
2020 PO1003033688	ODP	4	45 BRN	SP	CCA		V		3/18/2099
2020 PO1019433494	ODP	3	50 BRN	SP	CRE	ED,ID	TD		3/19/2099
2020 PO1015933404	ODP	4	45 BRN	SP	CCA		V		3/20/2099
2020 PO3868383182	LGE	4	35 BRO	SP	CCA		V		3/21/2099
2020 PO3866983178	LGE	4	35 BRO	SP	CCA	ED,ID	V		3/22/2099
2020 PO3866883163	LGE	4	35 BRO	SP	CCA		V		3/23/2099
2020 PO3866783148	LGE	4	35 BRO	SP	P	ED,ID	TD		3/24/2099
2020 PO3867183143	LGE	4	35 BRO	SP	P	ED,ID	TD		3/25/2099
2020 PO3867183193	LGE	4	35 BRO	SP	CCA		V		3/26/2099
2020 PO2685553965	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD		3/27/2099
2020 PO2698654212	KU	5	35 BRO	SP	CRE	MD,RB	X	RP1	3/28/2099
2020 PO2712754477	KU	4	40 BRO	SP	CRE	ED	TD		3/29/2099
2020 PO2725954724	KU	5	35 BRO	SP	CRE	HH,ID,MD,RB	VX	PX	3/30/2099
2020 PO2734454883	KU	4	40 BRO	SP	CRE	ID,RB	TX	RR	3/31/2099
2020 PO1023333629	ODP	4	40 BRN	SP	CRE	ED,ID	TD		4/1/2099
2020 PO3490840325	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD		4/2/2099
2020 PO3504440592	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		4/3/2099
2020 PO3504440592a	KU	4	40 ACE	SP	CRE	ED,ID	TD		4/4/2099
2020 PO3959383275	F	4	40 BRO	SP	CCA		V		4/5/2099
2020 PO3956283275	F	4	40 BRO	SP	P		V		4/6/2099
2020 PO3958583275	F	4	40 BRO	SP	CRE		V		4/7/2099
2020 PO3957783276	F	4	40 BRO	SP	CCA		V		4/8/2099
2020 PO1027733761	ODP	4	40 BRN	SP	CRE	ED,ID	TD		4/9/2099
2020 PO1030333876	ODP	4	40 BRN	SP	CRE	ED,ID	TD		4/10/2099
2020 PO1029834021	ODP	2	55 BRN	SP	CCA		V		4/11/2099
2020 PO1030434261A	ODP	5	35 BRN	SP	CCA	ED	TD		4/12/2099
2020 PO1030434261	ODP	4	45 BRN	SP	CRE	ED,ID	BD		4/13/2099
2020 PO1032934215	ODP	4	40 BRN	SP	CRE	ED,ID	TD		4/14/2099
2020 PO1029834498A	ODP	4	40 BRN	SP	CRE	ED,ID	TD		4/15/2099
2020 PO1022534745	ODP	4	45 BRN	SP	CCA		V		4/16/2099
2020 PO1032834818	ODP	4	45 BRN	SP	CRE	ED,ID	TD		4/17/2099
2020 PO1029134646	ODP	4	45 BRN	SP	CRE		V		4/18/2099
2020 PO1029834498	ODP	2	50 BRN	SP	CCA	ED	TD		4/19/2099

2020 PO1018334499	ODP	4	45 BRN	SP	CCA	ED	TD	4/20/2099	
2020 PO1016134551	ODP	5	35 BRN	SP	CCA	ED	TD	4/21/2099	
2020 PO3955383280	F	6	40 BRO	SP	CRE		V	4/22/2099	
2020 PO3957283279	LGE	4	40 BRO	SP	CCA		B	4/23/2099	
2020 PO9813517679	KU	6	30 BRO	SP	CCA		V	4/24/2099	
2020 PO2573049712	KU	4	35 BRO	SP	CRE	ED	TD	4/25/2099	
2020 PO2659137934	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	4/26/2099	
2020 PO7585403185	KU	6	30 BRO	SP	CRE		V	4/27/2099	
2020 PO6880694188	KU	4	40 BRN	SP	CRE		V	4/28/2099	
2020 6485703679a	KU	6	30 KOP	SP	CCA		V	4/29/2099	
2020 PO4752288793	LGE	4	40 BRN	SP	CRE	ED,ID,IP,SR	TX	RR	4/30/2099
2020 PO1105533439	ODP	5	35 BRN	SP	CRE	ID	BD	5/1/2099	
2020 PO4200441459a	KU	3	45 ACE	SP	CCA		V	5/2/2099	
2020 PO2336542989	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	5/3/2099	
2020 PO3945582885	F	4	40 BRO	SP	A		V	5/4/2099	
2020 PO4200441459	F	3	45 ACE	SP	CRE		V	5/5/2099	
2020 PO4198441357	KU	3	45 ACE	SP	CCA		V	5/6/2099	
2020 PO4198841376	KU	3	45 ACE	SP	CCA		V	5/7/2099	
2020 PO2571833878	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	5/8/2099	
2020 PO3992783026	LGE	4	40 BRN	SP	CRE	ED,ID	TD	5/9/2099	
2020 PO3873083074	LGE	4	40 BRO	SP	CRE	ED,ID,RB	TD	5/10/2099	
2020 PO3909882601	LGE	4	40 BRN	SP	CRE	ED,ID,IP	TD	5/11/2099	
2020 PO4203741429	F	3	45 ACE	SP	P		V	5/12/2099	
2020 PO3946282961	F	4	40 BRO	SP	P		V	5/13/2099	
2020 PO3947982966	F	6	25 BRO	SP	P		V	5/14/2099	
2020 PO3947482955	F	4	40 BRO	SP	P		V	5/15/2099	
2020 PO3948882950	F	4	25 BRO	SP	A		V	5/16/2099	
2020 PO3948082948	F	4	40 BRO	SP	A		V	5/17/2099	
2020 PO4741389257	F	3	45 BRO	SP	CCA		V	5/18/2099	
2020 PO4740289251	F	3	45 BRO	SP	CCA		V	5/19/2099	
2020 PO4742689263	F	4	40 BRO	SP	CCA		V	5/20/2099	
2020 PO4743389266	F	3	45 BRO	SP	A		V	5/21/2099	
2020 PO4846016707	KU	4	45 BRO	SP	CCA		V	5/22/2099	
2020 PO4842416672	KU	2	45 BRO	SP	CRE	ID,IP	BD	5/23/2099	
2020 PO48424166672-A	KU	5	35 BRO	SP	CRE	ID	BD	5/24/2099	
2020 PO4751588805	LGE	6	25 BRN	SP	CRE	ED,ID,IP	TD	5/25/2099	
2020 PO4752688818	LGE	3	45 BRN	SP	S		V	5/26/2099	
2020 PO4832116441	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	5/27/2099	
2020 PO4813816418	KU	2	45 BRO	SP	CRE	HH,ID,RB	X	RP1	5/28/2099
2020 PO4835216614	KU	3	45 BRO	SP	CRE	ID,IP	BD	5/29/2099	
2020 PO4824716521	KU	3	45 BRO	SP	CRE	ID,IP	BD	5/30/2099	
2020 PO4740389287	F	4	40 BRO	SP	CCA		V	5/31/2099	
2020 PO4741389292	F	4	40 BRO	SP	CRE		V	6/1/2099	
2020 PO4741789292	F	4	40 BRO	SP	CRE		V	6/2/2099	
2020 PO1089733475	ODP	5	35 KOP	SP	CRE	ID	TD	6/3/2099	
2020 PO4739189279	F	4	40 BRO	SP	CRE	ED,ID	VX	RP3	6/4/2099
2020 PO2351943385	KU	3	45 BRO	SP	CRE	ED	TD	6/5/2099	

2020 PO2367943860	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/6/2099
2020 PO2130546675	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	6/7/2099
2020 PO7709403763	KU	4	40 XXX	SP	CRE	ED,ID	TD	6/8/2099
2020 PO7719301922	KU	6	30 XXX	SP	CRE		V	6/9/2099
2020 PO7703101934	KU	4	40 XXX	SP	CRE		V	6/10/2099
2020 PO7696202406	KU	5	35 XXX	SP	CRE		V	6/11/2099
2020 PO7692702649	KU	5	35 XXX	SP	CRE		V	6/12/2099
2020 PO7706402996	KU	6	30 XXX	SP	CRE	ED,ID	TD	6/13/2099
2020 PO7699202870	KU	6	30 XXX	SP	CCA		V	6/14/2099
2020 PO7695402902	KU	4	40 XXX	SP	CRE	ID	BX	6/15/2099
2020 PO7706203249	F	4	40 XXX	SP	P		V	6/16/2099
2020 7719303512a	KU	5	30 XXX	SP	CRE	ED,ID	TD	6/17/2099
2020 PO7701903566	KU	4	40 XXX	SP	CCA		V	6/18/2099
2020 PO7709303532	KU	5	30 XXX	SP	CRE	ID	BD	6/19/2099
2020 PO7719303512	KU	4	40 XXX	SP	CRE	ED,ID	TD	6/20/2099
2020 PO7724403205	KU	6	30 ACW	SP	CRE	ED,ID	TD	6/21/2099
2020 PO7734503283	KU	4	40 XXX	SP	CRE	ED,ID	TD	6/22/2099
2020 PO7760603241	KU	4	40 XXX	SP	CRE	ED,ID	TD	6/23/2099
2020 PO7788503215	KU	5	35 XXX	SP	CRE	ED,ID	TD	6/24/2099
2020 PO7822703291	KU	4	40 XXX	SP	CRE	ED,ID	TD	6/25/2099
2020 PO7850903224	KU	4	40 XXX	SP	CRE	ED,ID	TD	6/26/2099
2020 PO7817203090	KU	6	30 BRN	SP	CCA		V	6/27/2099
2020 PO7819503160	KU	6	30 BRN	SP	CCA		V	6/28/2099
2020 PO8088105500	KU	4	40 BRN	SP	CRE	ED,ID	TD	6/29/2099
2020 PO8079605325	KU	4	40 BRN	SP	CRE	ED,ID	TD	6/30/2099
2020 PO7976703001	KU	5	35 XXX	SP	CRE	ED,ID	TD	7/1/2099
2020 PO7968203038	KU	5	35 XXX	SP	CRE	ED,ID	TD	7/2/2099
2020 PO7956503083	KU	5	35 XXX	SP	CRE	ED,ID	TD	7/3/2099
2020 PO7943403095	KU	4	40 XXX	SP	CRE	ED,ID	TD	7/4/2099
2020 PO7942602971	KU	6	30 BRN	SP	CRE		V	7/5/2099
2020 PO7933902955	KU	4	40 XXX	SP	CRE	ED,ID	TD	7/6/2099
2020 PO7949602785	KU	6	30 BRN	SP	CRE	ED,ID	TD	7/7/2099
2020 PO4737989272	F	4	40 BRO	SP	CRE		V	7/8/2099
2020 PO4751288809	LGE	4	40 BRN	SP	A	ED,ID	TD	7/9/2099
2020 PO4750588822	LGE	4	40 BRN	SP	CRE	ED,ID	TD	7/10/2099
2020 PO4749888832	LGE	4	40 BRN	SP	A	ED,ID	TD	7/11/2099
2020 PO4749088840	LGE	4	40 BRN	SP	A	ED,ID	TD	7/12/2099
2020 PO4749188844	LGE	4	40 BRN	SP	A	ED,ID	TD	7/13/2099
2020 PO4748588852	LGE	3	45 BRN	SP	A	ED,ID	TD	7/14/2099
2020 PO4774516904	F	4	40 BRO	SP	CRE		V	7/15/2099
2020 PO4748088859	LGE	3	45 BRN	SP	A	ED,ID	TD	7/16/2099
2020 PO4747688867	LGE	3	45 BRN	SP	A	ED,ID	TD	7/17/2099
2020 PO0615361851	F	4	40 BRN	SP	CRE		V	7/18/2099
2020 PO7967602930	KU	6	30 BRN	SP	CCA		V	7/19/2099
2020 PO0158316453	KU	4	40 BRO	SP	CRE	HH,ID	X	7/20/2099
2020 PO9926616919	F	4	40 BRO	SP	CRE	ED,ID	BX	7/21/2099
2020 Po0161016806a	KU	4	40 BRO	SP	CRE	ID	TD	7/22/2099

2020 PO0161016806	KU	6	30 BRO	SP	CCA		V	7/23/2099
2020 PO0122016528	KU	5	35 BRO	SP	CCA		V	7/24/2099
2020 PO9942116730	KU	6	30 BRO	SP	CRE	ID	TD	7/25/2099
2020 PO9929316982	KU	5	35 BRO	SP	CRE	ID	TD	7/26/2099
2020 PO9923317021	KU	4	30 BRO	SP	CRE	ID	TD	7/27/2099
2020 PO9974916661	F	4	45 BRO	SP	CRE		V	7/28/2099
2020 PO9981716774	KU	1	60 BRO	SP	CRE	ID	TD	7/29/2099
2020 PO9993116925	KU	4	50 BRO	SP	CRE	ID	BD	7/30/2099
2020 PO9980817021	KU	4	40 BRO	SP	CRE	ID	TD	7/31/2099
2020 PO9964116529	KU	4	40 BRO	SP	CRE	ID	TD	8/1/2099
2020 PO2215945307	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	8/2/2099
2020 PO9951516601	KU	5	35 BRO	SP	CRE	ID	TD	8/3/2099
2020 PO9937316687	KU	5	35 BRO	SP	CRE	ID	TD	8/4/2099
2020 PO2240045207	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	8/5/2099
2020 PO9926616752	KU	5	35 BRO	SP	CRE	ID	TD	8/6/2099
2020 PO9919116799	KU	4	40 BRO	SP	CRE	ID	TD	8/7/2099
2020 PO9904916898	KU	5	35 BRO	SP	CRE	ID	TD	8/8/2099
2020 PO9868617263	KU	5	35 BRO	SP	CRE	ID	TD	8/9/2099
2020 PO9886317375	KU	6	30 BRO	SP	CRE	ID	TD	8/10/2099
2020 PO9895117141a	KU	6	30 BRO	SP	CCA		V	8/11/2099
2020 PO9904517226	KU	6	30 BRO	SP	CRE	ID	TD	8/12/2099
2020 PO9894917317	KU	6	30 BRO	SP	CCA		V	8/13/2099
2020 PO9891117289	KU	4	40 BRO	SP	CRE	ID	TD	8/14/2099
2020 PO9879117164	KU	4	40 BRO	SP	CRE	ID	TD	8/15/2099
2020 PO9895117141	KU	6	30 BRO	SP	CRE	ID	TD	8/16/2099
2020 PO9897517064	KU	6	30 BRO	SP	CRE	ID	TD	8/17/2099
2020 PO9886517021	KU	4	40 BRO	SP	CCA		V	8/18/2099
2020 PO9891716973	KU	6	30 BRO	SP	CRE	ID	TD	8/19/2099
2020 PO9896116960	KU	4	40 BRO	SP	CCA		V	8/20/2099
2020 PO9886616775	KU	6	30 BRO	SP	CRE	ID	TD	8/21/2099
2020 PO3908582610	LGE	4	40 BRN	SP	CRE	ED,ID	TD	8/22/2099
2020 PO3907282618	LGE	3	45 BRN	SP	CCA		V	8/23/2099
2020 PO3907882626	LGE	6	25 BRN	SP	CRE	ED,ID	TD	8/24/2099
2020 PO3907082635	LGE	6	25 BRN	SP	CRE	ED,ID	TD	8/25/2099
2020 PO3948482937	F	6	25 BRO	SP	P		V	8/26/2099
2020 PO3947782940	F	4	40 BRO	SP	A		V	8/27/2099
2020 PO3946982927	F	4	40 BRO	SP	A		V	8/28/2099
2020 PO3946182916	F	4	40 BRO	SP	CRE		V	8/29/2099
2020 PO3945382903	F	4	40 BRO	SP	A		V	8/30/2099
2020 PO3993783027	LGE	4	40 BRN	SP	CRE	ED,ID	TD	8/31/2099
2020 PO3873782963	LGE	4	35 BRO	SP	P	ED	TD	9/1/2099
2020 PO3874083068	LGE	4	30 BRO	SP	P	ED,ID	BD	9/2/2099
2020 PO3875983071	LGE	4	40 BRO	SP	P	ED,HH,ID	TD	9/3/2099
2020 PO3875683067	LGE	4	30 BRO	SP	P	ED,ID	TD	9/4/2099
2020 PO9429218339	KU	4	40 UNK	SP	CRE	ID	TD	9/5/2099
2020 PO1183733512	ODP	5	30 KOP	SP	CRE	ID	TD	9/6/2099
2020 PO9409618577	KU	5	35 UNK	SP	CRE	ID	TD	9/7/2099

2020 PO9408018905	KU	6	30 UNK	SP	CRE	ID	TD	9/8/2099
2020 PO9444518960	KU	4	40 ACW	SP	CRE	ID	TD	9/9/2099
2020 PO4042843543	KU	3	50 ACE	SP	CRE	ED,ID	BD	9/10/2099
2020 PO4555743086	KU	4	40 ACE	SP	CRE	ED,ID	BD	9/11/2099
2020 PO4525343209	KU	4	40 ACE	SP	CRE	ED,ID	TD	9/12/2099
2020 PO4587242963	KU	4	45 ACE	SP	CRE	ED,ID	BD	9/13/2099
2020 PO5441399192	F	4	40 ACE	SP	CCA		V	9/14/2099
2020 PO5435999223	KU	3	40 ACE	SP	CCA		V	9/15/2099
2020 PO4632442783	F	4	40 ACE	SP	CCA		V	9/16/2099
2020 PO4629842804	KU	6	30 ACE	SP	CCA		V	9/17/2099
2020 PO5454999164	KU	5	30 ACE	SP	CRE	ED,ID,IP	TD	9/18/2099
2020 PO5454999164-A	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	9/19/2099
2020 PO5460798954	KU	6	30 ACE	SP	CCA	ED	TD	9/20/2099
2020 PO4625842940	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	9/21/2099
2020 PO4672543423	KU	4	40 ACE	SP	CRE	ED,ID	TD	9/22/2099
2020 PO4668843132	KU	4	40 ACE	SP	CRE	ED,ID	BD	9/23/2099
2020 PO4665842904	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	9/24/2099
2020 PO5420899978	KU	6	30 ACE	SP	CRE	ID,IP	BD	9/25/2099
2020 PO5410799905	KU	3	40 ACE	SP	CCA		V	9/26/2099
2020 PO5423600367	KU	5	35 ACE	SP	CRE	ID,IP	BD	9/27/2099
2020 PO4676443680	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	9/28/2099
2020 PO4683544297	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	9/29/2099
2020 PO4310541331	KU	3	45 ACE	SP	CCA		V	9/30/2099
2020 PO5427600711	KU	4	40 ACE	SP	CRE	ED,ID	TD	10/1/2099
2020 PO5433000532	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	10/2/2099
2020 PO4273441115	KU	4	45 ACE	SP	CRE	ED,ID,IP	BD	10/3/2099
2020 PO4294941227	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	10/4/2099
2020 PO4317541427	F	4	40 ACE	SP	CRE		V	10/5/2099
2020 PO4255341107	F	4	40 ACE	SP	P		V	10/6/2099
2020 PO4262041429	KU	4	40 ACE	SP	CCA		V	10/7/2099
2020 PO4340342661	KU	3	45 ACE	SP	CCA		V	10/8/2099
2020 PO4341943006	KU	4	45 ACE	SP	CCA		V	10/9/2099
2020 PO5469300560	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	10/10/2099
2020 PO5497000618	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	10/11/2099
2020 PO5344901590	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	10/12/2099
2020 PO4342743256	KU	4	45 ACE	SP	CRE	ED,ID,IP	TD	10/13/2099
2020 PO4347943550	KU	3	45 ACE	SP	CCA		V	10/14/2099
2020 PO5351601878	KU	4	40 ACE	SP	CRE	ID,IP	BD	10/15/2099
2020 PO5325702246	KU	4	40 ACE	SP	CRE	ID	BD	10/16/2099
2020 PO5262401656	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	10/17/2099
2020 PO3483847832a	KU	3	45 ACE	SP	CCA		V	10/18/2099
2020 PO3483847832b	KU	3	45 ACE	SP	CCA		V	10/19/2099
2020 PO4357443933	KU	4	40 ACE	SP	CCA		V	10/20/2099
2020 PO4344944006	KU	3	45 ACE	SP	CCA		V	10/21/2099
2020 PO4356543873	F	3	45 ACE	SP	CCA		V	10/22/2099
2020 PO4367643893	KU	5	35 ACE	SP	CCA		V	10/23/2099
2020 PO5258501782	KU	4	40 ACE	SP	CRE	ID,IP	BD	10/24/2099

2020 PO4226044464	KU	5	35 ACE	SP	CRE	ED,ID	TD	10/25/2099
2020 PO4250744075	KU	5	45 ACE	SP	CRE	ED,ID	TD	10/26/2099
2020 PO4320144047	F	2	45E ACE	SP	CRE	ED,HH,ID,RB	VX	RP1 10/27/2099
2020 PO4337543957	F	3	45 ACE	SP	P		V	10/28/2099
2020 PO5235401873	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	10/29/2099
2020 PO5228201871	F	4	40 ACE	SP	CRE		V	10/30/2099
2020 PO4285744230	F	3	45 ACE	SP	CCA		V	10/31/2099
2020 PO4858510520	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	11/1/2099
2020 PO4840110592	KU	2	50 ACE	SP	CCA		V	11/2/2099
2020 PO4733689116	LGE	4	30 BRO	SP	CRE	ED,ID	TD	11/3/2099
2020 PO4733589106	LGE	3	50 BRO	ST	CCA		V	11/4/2099
2020 PO4734389106	LGE	3	50 BRO	SP	CCA		V	11/5/2099
2020 PO4734189117	F	UNK	45 BRO	SP	CRE	ED,ID	BD	11/6/2099
2020 PO4751388630	LGE	4	40 BRN	SP	P	ED,ID	BD	11/7/2099
2020 PO4834810476	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	11/8/2099
2020 PO4832810408	KU	4	40 ACE	SP	CRE	ED,ID	BD	11/9/2099
2020 PO4853510455	KU	6	30 ACE	SP	CRE	ED,ID	TD	11/10/2099
2020 PO4753688632	LGE	4	40 BRN	SP	S		V	11/11/2099
2020 PO4752488628	LGE	4	40 BRN	SP	CRE	ED,ID	BD	11/12/2099
2020 PO4270612273	KU	4	40 BRO	SP	CRE	ID	BD	11/13/2099
2020 PO4751488625	LGE	4	40 BRN	SP	S		V	11/14/2099
2020 PO4750588643	LGE	4	40 BRN	SP	P	ED,ID	TD	11/15/2099
2020 PO4750389099	LGE	4	35 BRO	SP	CCA		V	11/16/2099
2020 PO4749889101	LGE	3	45 BRO	SP	CCA		V	11/17/2099
2020 PO4749789090	LGE	3	45 BRO	SP	CCA		V	11/18/2099
2020 PO4750189077	LGE	3	45 BRO	SP	CCA		V	11/19/2099
2020 PO4750889063	LGE	3	45 BRO	SP	CCA		V	11/20/2099
2020 PO4823210156	KU	4	45 ACE	SP	CCA		V	11/21/2099
2020 PO4749886651	LGE	4	40 BRN	SP	A	ED,ID	BD	11/22/2099
2020 PO4256512357	KU	4	40 BRO	SP	CRE	ID	BD	11/23/2099
2020 PO4749788655	LGE	4	35 BRN	SP	A	ED,ID	BD	11/24/2099
2020 PO4845309951	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD	11/25/2099
2020 PO4749488660	LGE	4	40 BRN	SP	A	ED,ID	BD	11/26/2099
2020 PO4751489050	LGE	4	35 BRO	SP	A	ED,ID	BD	11/27/2099
2020 PO4752089036	LGE	4	35 BRO	SP	CRE	ED,ID	BD	11/28/2099
2020 PO4752789023	LGE	4	35 BRO	SP	CRE	ED,ID	BD	11/29/2099
2020 PO4244212428	KU	4	40 BRO	SP	CRE	ID	BD	11/30/2099
2020 PO9596087073	KU	4	40 ACW	SP	S		V	12/1/2099
2020 PO9604586855	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	12/2/2099
2020 PO5952543837	KU	5	35 ACE	SP	CRE		V	12/3/2099
2020 PO6002944069	KU	4	45 ACE	SP	CCA		V	12/4/2099
2020 PO9615086635A	KU	6	25 ACW	SP	S		V	12/5/2099
2020 PO5983043649	KU	4	40 ACE	SP	CRE	ED,ID	BD	12/6/2099
2020 PO9636286421	KU	5	35 ACW	SP	CRE		V	12/7/2099
2020 PO9643886679	KU	4	40 ACW	SP	CRE		V	12/8/2099
2020 PO5963343660a	KU	6	30 ACE	DF	CRE	ED,ID	TD	12/9/2099
2020 PO5963343660	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	12/10/2099

2020 PO9632686615	KU	4	40 ACW	SP	CRE	ED,ID	TD	12/11/2099
2020 PO9615086635	KU	4	45 ACW	SP	CRE	ED,ID,IP	TD	12/12/2099
2020 PO9610386473	KU	5	30 ACW	SP	CRE	ED,ID,IP	TD	12/13/2099
2020 PO9610286404	KU	4	40 ACW	SP	CRE	ED,ID	TD	12/14/2099
2020 PO9602786274	KU	6	30 ACW	SP	CRE	ED,ID	TD	12/15/2099
2020 PO5927743377	F	4	40 ACE	SP	CCA		V	12/16/2099
2020 PO9127181743B	KU	3	40 BRN	SP	S		V	12/17/2099
2020 PO9127181743A	KU	4	40 BRN	SP	CRE	ED,ID	TD	12/18/2099
2020 PO5024014373	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	12/19/2099
2020 PO5040114471	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	12/20/2099
2020 PO5096414812	KU	4	40 BRO	SP	CRE	ED,ID	TD	12/21/2099
2020 PO5078914709	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	12/22/2099
2020 PO5061314607	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	12/23/2099
2020 PO5907743218	KU	5	35 ACE	SP	CRE	ED,ID	BD	12/24/2099
2020 PO5966543239	KU	4	45 ACE	SP	CCA		V	12/25/2099
2020 PO4840011910	KU	6	30 BRO	SP	CCA	ED	T	12/26/2099
2020 PO4827811954	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	12/27/2099
2020 PO9555185613	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	12/28/2099
2020 PO9551485874	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	12/29/2099
2020 PO9551485874A	KU	3	40 ACW	SP	CRE	ED,ID	TD	12/30/2099
2020 PO5918542965	KU	4	40 ACE	SP	CRE	ED,ID	TD	12/31/2099
2020 PO5932543063	F	4	40 ACE	SP	CCA		V	1/1/2100
2020 PO9127181743	KU	4	40 BRN	SP	CRE	ED,ID	TD	1/2/2100
2020 PO5224713323	KU	4	40 BRO	SP	CRE	ID	BD	1/3/2100
2020 PO5923742905	KU	6	30 ACE	SP	CCA		V	1/4/2100
2020 PO5947342735	KU	4	40 ACE	SP	CCA		V	1/5/2100
2020 PO5954142576	F	4	40 ACE	SP	CCA		V	1/6/2100
2020 PO5922642546	KU	3	45 ACE	SP	CCA		V	1/7/2100
2020 PO5220313619	KU	4	45 BRO	SP	CRE	ID,IP,RB	X	RP1 1/8/2100
2020 PO5203713591	KU	3	45 BRO	SP	CCA		V	1/9/2100
2020 PO5174313547	KU	4	45 BRO	SP	CRE	ID,IP	BD	1/10/2100
2020 PO9122281576	KU	3	45 BRN	SP	CCA		V	1/11/2100
2020 PO9117781391	KU	3	40 BRN	SP	S		V	1/12/2100
2020 PO6357646985	KU	6	30 ACE	SP	CCA		V	1/13/2100
2020 PO5148213502	KU	4	45 BRO	SP	CRE	ID,IP	BD	1/14/2100
2020 PO5113813435	KU	4	45 BRO	SP	CRE	ID,IP	BD	1/15/2100
2020 PO6403647829	KU	6	30 ACE	SP	CCA		V	1/16/2100
2020 PO6396847776	KU	6	30 ACE	SP	CCA		V	1/17/2100
2020 PO6387147789	KU	6	30 ACE	SP	CCA		V	1/18/2100
2020 PO6384747800	KU	3	45 ACE	SP	CCA		V	1/19/2100
2020 PO6378547830	KU	5	35 ACE	SP	CCA		V	1/20/2100
2020 PO6372347883	KU	6	30 ACE	SP	CCA		V	1/21/2100
2020 PO5074413369	KU	4	45 BRO	SP	CRE	ID	BD	1/22/2100
2020 PO5986747307	KU	4	40 ACE	SP	CRE	ED,ID	TD	1/23/2100
2020 PO5037913302	KU	4	45 BRO	SP	CRE	ID,IP	BD	1/24/2100
2020 PO4999613226	KU	4	45 BRO	SP	CRE	ED,ID,IP	TX	RR 1/25/2100
2020 PO5992347392	KU	4	40 ACE	SP	CRE	ED,ID	TD	1/26/2100

2020 PO4985815099	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	1/27/2100
2020 PO4984814676	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	1/28/2100
2020 PO9577185430	KU	4	45 ACW	SP	CRE		V	1/29/2100
2020 PO9595585285	KU	3	45 ACW	SP	CCA		V	1/30/2100
2020 PO9584885363	KU	4	45 ACW	SP	CRE	ED,ID	BD	1/31/2100
2020 PO9567585489	KU	4	45 ACW	SP	CRE	ED,ID,IP,SR	TD	2/1/2100
2020 PO6009047276	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	2/2/2100
2020 PO6002347185	KU	4	40 ACE	SP	CRE	ED,ID	BD	2/3/2100
2020 PO5878849344	F	4	40 ACE	SP	P		V	2/4/2100
2020 PO4734789179	F	4	40 BRO	SP	A		V	2/5/2100
2020 PO5281810271	KU	3	45 ACE	SP	CRE	ED,ID,IP	BD	2/6/2100
2020 PO5281710207	KU	3	45 ACE	SP	CCA		V	2/7/2100
2020 PO5274310234	KU	4	45 ACE	SP	CCA		V	2/8/2100
2020 PO4011582900	LGE	4	40 BRO	SP	P	ED,ID	TD	2/9/2100
2020 PO4012482917	LGE	4	40 BRO	SP	A	ED,ID	TD	2/10/2100
2020 PO4012282920	LGE	4	40 BRO	SP	A	ED,ID	TD	2/11/2100
2020 PO4007282913	LGE	4	40 BRO	SP	CCA		V	2/12/2100
2020 PO4006482901	LGE	4	35 BRO	SP	CCA		V	2/13/2100
2020 PO7254440570	LGE	4	35 BRO	SP	CCA		V	2/14/2100
2020 PO5260210290	KU	4	45 ACE	SP	CCA		V	2/15/2100
2020 PO5264310347	F	6	30 ACE	SP	CRE		V	2/16/2100
2020 PO5257510388	F	5	35 ACE	SP	P	ED,EP,ID,IP	V	2/17/2100
2020 PO5252210320	KU	4	45 ACE	SP	CCA		V	2/18/2100
2020 PO5252510435	KU	4	40 ACE	SP	CRE		V	2/19/2100
2020 PO4028383063	LGE	3	45 BRO	SP	A	ED,ID	TD	2/20/2100
2020 PO4031083048	LGE	2	55 BRO	SP	CRE		V	2/21/2100
2020 PO4029083049	LGE	2	60 BRO	SP	CRE		V	2/22/2100
2020 PO4027083053	LGE	2	75 BRO	SP	CRE		V	2/23/2100
2020 PO4024983056	LGE	2	75 BRO	SP	CRE		V	2/24/2100
2020 PO4021083067	LGE	2	55 BRO	SP	P		V	2/25/2100
2020 PO7394242326	LGE	3	45 BRO	SP	P	ED,ID	BD	2/26/2100
2020 PO4023483058	LGE	2	55 BRO	SP	CRE		V	2/27/2100
2020 PO5241010367	KU	4	40 ACE	SP	CCA		V	2/28/2100
2020 PO5238510465	F	5	35 ACE	SP	P		V	3/1/2100
2020 PO5222310441	F	3	45 ACE	SP	CCA		V	3/2/2100
2020 PO5230310407	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	3/3/2100
2020 PO5219510364	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	3/4/2100
2020 PO5224610188	F	4	40 ACE	SP	P		V	3/5/2100
2020 PO5217810080	F	5	35 ACE	SP	P		V	3/6/2100
2020 PO5215310022	F	5	35E ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	3/7/2100
2020 PO5206409569	KU	6	30 ACE	SP	CRE	ED,ID	BD	3/8/2100
2020 PO5204209593	F	4	40 ACE	SP	CRE		V	3/9/2100
2020 PO5184208907	F	4	40 ACE	SP	CRE		V	3/10/2100
2020 PO5177408928	KU	4	40 ACE	SP	P		V	3/11/2100
2020 PO4962411908	F	4	40 ACE	SP	P		V	3/12/2100
2020 PO4949211970	F	4	40 ACE	SP	P		V	3/13/2100
2020 PO4931911634	F	4	40 ACE	SP	CRE		V	3/14/2100

2020 PO4419904763	LGE	3	45 BRO	SP	CRE		V	3/15/2100
2020 PO4733489194	F	3	45 BRO	SP	CCA		V	3/16/2100
2020 PO4734289214	F	3	45 BRO	SP	CCA		V	3/17/2100
2020 PO4733189206	F	3	45 BRO	SP	A		V	3/18/2100
2020 PO4733689209	F	3	45 BRO	SP	CCA		V	3/19/2100
2020 PO4918711689	F	4	40 ACE	SP	P		V	3/20/2100
2020 PO4923211796	F	5	35 ACE	SP	P		V	3/21/2100
2020 PO4732489218	F	3	45 BRO	SP	CCA		V	3/22/2100
2020 PO4731689231	F	3	45 BRO	SP	CCA		V	3/23/2100
2020 PO4731489234	F	3	45 BRO	SP	CCA		V	3/24/2100
2020 PO4402905103	LGE	3	45 BRO	SP	CRE		V	3/25/2100
2020 PO4399805151	LGE	3	45 BRO	SP	CRE		V	3/26/2100
2020 PO4731289227	F	4	30 BRO	SP	CRE		V	3/27/2100
2020 PO4730989231	F	3	45 BRO	SP	CCA		V	3/28/2100
2020 PO4730489240	F	3	45 BRO	SP	A		V	3/29/2100
2020 PO4730189244	F	3	45 BRO	SP	CCA		V	3/30/2100
2020 PO4411604970	LGE	3	45 BRO	SP	CRE		V	3/31/2100
2020 PO4724789038	LGE	3	45 BRO	SP	CRE	ED,ID	BD	4/1/2100
2020 PO4039483081	F	4	30 BRO	SP	CCA		V	4/2/2100
2020 PO4038183091	F	4	30 BRO	SP	P		V	4/3/2100
2020 PO4037383091	F	2	55 BRO	SP	CCA		V	4/4/2100
2020 PO4036483092	LGE	4	40 BRO	SP	CRE	ED,ID	BD	4/5/2100
2020 PO4904011750	F	4	40 ACE	SP	P		V	4/6/2100
2020 PO4909411579	F	4	40 ACE	SP	CRE		V	4/7/2100
2020 PO4937710480	KU	5	30 ACE	SP	CRE	ED,ID	TD	4/8/2100
2020 PO4930510510	KU	5	30 ACE	SP	CRE	ED,ID	BD	4/9/2100
2020 PO4726089046	LGE	1	50 BRO	SP	CCA		V	4/10/2100
2020 PO4727889068	LGE	4	40 BRO	SP	CCA		V	4/11/2100
2020 PO4729089077	F	3	45 BRO	SP	A		V	4/12/2100
2020 PO4909110680	KU	2	40 ACE	SP	CRE	ED,ID,IP	BD	4/13/2100
2020 PO4729589068	LGE	3	45 BRO	SP	A	ED,ID	BD	4/14/2100
2020 PO4729289064	LGE	4	35 BRO	SP	CCA		V	4/15/2100
2020 PO4729189065	LGE	1	45 BRO	SP	CCA		V	4/16/2100
2020 PO4727189053	LGE	1	50 BRO	SP	CCA		V	4/17/2100
2020 PO4914610813	KU	2	40 ACE	SP	CRE	ED,ID	BD	4/18/2100
2020 PO4036283076	F	3	45 BRO	SP	CCA		V	4/19/2100
2020 PO4920010943	KU	3	45 ACE	SP	CRE	ED,ID,IP	BD	4/20/2100
2020 PO4924211075	KU	3	45 ACE	SP	P	ED,ID	BD	4/21/2100
2020 PO4912311126	KU	2	40 ACE	SP	CRE	ED,ID,IP	BD	4/22/2100
2020 PO4887410964	KU	2	40 ACE	SP	CRE	ED,ID,IP	BD	4/23/2100
2020 PO4728489061	LGE	1	50 BRO	SP	CCA		V	4/24/2100
2020 PO4892111070	KU	2	40 ACE	SP	CRE	ED,ID	BD	4/25/2100
2020 PO4897111186	KU	2	40 ACE	SP	CRE	ED,ID	BD	4/26/2100
2020 PO4872311301	KU	3	45 ACE	SP	CCA		V	4/27/2100
2020 PO4888211225	KU	5	35 ACE	SP	CRE	ED,ID,IP	BD	4/28/2100
2020 PO4061482993	LGE	4	40 BRO	SP	CCA		V	4/29/2100
2020 PO4061482994	LGE	3	50 BRO	SP	A		V	4/30/2100

Business Use

2020 PO4059083000	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	5/1/2100
2020 PO4060282931A	LGE	3	40 BRO	SP	A	ED,ID	TD	5/2/2100
2020 PO4061382972	LGE	4	40 BRO	SP	P	ED,ID	TD	5/3/2100
2020 PO4060482973	LGE	4	35 BRO	SP	CRE	ED,ID	TD	5/4/2100
2020 PO4056582956	LGE	4	40 BRO	SP	CRE	ED,ID	TD	5/5/2100
2020 PO4057082955	LGE	4	30 BRO	SP	P	ED,ID	TD	5/6/2100
2020 PO4061282952	LGE	4	40 BRO	SP	P	ED,ID	TD	5/7/2100
2020 PO4060382952	LGE	4	35 BRO	SP	P	ED,ID	TD	5/8/2100
2020 PO4057782934	LGE	4	40 BRO	SP	P	ED,ID	TD	5/9/2100
2020 PO4060282931	LGE	4	40 BRO	SP	CRE	ED,ID	TD	5/10/2100
2020 PO4693888782	LGE	4	45 BRO	SP	CCA		V	5/11/2100
2020 PO4727388347	LGE	4	30 BRO	SP	CRE	ED,ID,IP	BD	5/12/2100
2020 PO4056382935	LGE	4	40 BRO	SP	S	ED,HH,ID,RB	X	RP2 5/13/2100
2020 PO4694388776	LGE	4	30 BRO	SP	A	ED,ID	TD	5/14/2100
2020 PO4601210184	KU	4	45 BRO	SP	CRE	ID,IP	BD	5/15/2100
2020 PO4641610012	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	5/16/2100
2020 PO4680509843	KU	3	35 BRO	SP	CRE	ED,ID,IP	TD	5/17/2100
2020 PO4713609691	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	5/18/2100
2020 PO4708609633	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD	5/19/2100
2020 PO5869345082	KU	4	45 ACE	SP	CRE	ED,ID	BD	5/20/2100
2020 PO5867345239	KU	4	40 ACE	SP	CRE	ED,ID	BD	5/21/2100
2020 PO0734218787	KU	5	35 OTH	SP	CRE	ID	TD	5/22/2100
2020 PO0748912659	KU	4	40 OTH	SP	CRE	ID	TD	5/23/2100
2020 PO0741013184	KU	6	30 OTH	SP	CRE	ID	TD	5/24/2100
2020 PO3994382909	F	4	40 BRN	SP	S		V	5/25/2100
2020 PO8142025617	ODP	4	45 BRN	SP	CCA		V	5/26/2100
2020 PO8105325832	ODP	4	45 BRN	SP	CCA		V	5/27/2100
2020 PO8152925773	ODP	4	40 BRN	SP	CRE	ID	BD	5/28/2100
2020 PO8163925979	ODP	4	40 BRN	SP	CRE	ID	BD	5/29/2100
2020 PO8179626183	ODP	5	35 BRN	SP	CRE	ID	BD	5/30/2100
2020 PO8173126083	ODP	4	40 BRN	SP	CRE	ID	BD	5/31/2100
2020 PO8163925979	ODP	4	45 BRN	SP	CCA		V	6/1/2100
2020 PO3928682462	F	4	40 BRN	SP	P		V	6/2/2100
2020 PO3928882466	F	4	40 BRN	SP	CRE		V	6/3/2100
2020 PO3929682483	F	3	45 BRN	SP	CCA		V	6/4/2100
2020 PO3929982490	F	3	45 BRN	SP	CCA		V	6/5/2100
2020 PO6490336491	F	3	45 BRN	SP	CCA		V	6/6/2100
2020 PO3993582788	F	6	25 BRN	SP	CRE		V	6/7/2100
2020 PO3993582797	F	4	40 BRN	SP	CRE		V	6/8/2100
2020 PO3992082796	F	4	40 BRN	SP	CRE		V	6/9/2100
2020 PO1340135924	ODP	4	40 BRN	SP	CCA		V	6/10/2100
2020 PO6500136717	LGE	3	45 BRN	SP	CCA		V	6/11/2100
2020 PO6496336630	LGE	3	50 BRN	SP	CCA		V	6/12/2100
2020 PO3931882531	F	4	40 BRN	SP	CRE		V	6/13/2100
2020 PO6512436989	LGE	3	45 BRN	SP	CCA		V	6/14/2100
2020 PO3934482540	LGE	4	30 BRN	SP	CRE	ED,ID	TD	6/15/2100
2020 PO2795327339	ODP	3	45 BRO	SP	CCA		V	6/16/2100

2020 PO2811627142	ODP	3	50 BRO	SP	CCA		V	6/17/2100
2020 PO2846727173	ODP	5	35 BRO	SP	CCA		V	6/18/2100
2020 PO2826927251	ODP	4	40 BRO	SP	CCA		V	6/19/2100
2020 PO2806827309	ODP	3	45 BRO	SP	CCA		V	6/20/2100
2020 PO2716328203	ODP	4	40 BRO	SP	CRE	ID	TD	6/21/2100
2020 PO1317335999	ODP	4	40 BRN	SP	CCA		V	6/22/2100
2020 PO1930437155	KU	5	35 BRO	SP	CRE	ID,IP	BD	6/23/2100
2020 PO2960435590	KU	4	40 BRN	SP	CRE	ID	BD	6/24/2100
2020 PO2966035649	KU	4	45 BRN	SP	CCA		V	6/25/2100
2020 PO2190832714	KU	5	35 BRN	SP	CRE		V	6/26/2100
2020 PO2669734098	KU	5	35 BRN	SP	CRE	HH	BX	RP1 6/27/2100
2020 PO2214932779	KU	5	35 BRN	SP	CRE		V	6/28/2100
2020 PO2247439425	KU	4	40 BRN	SP	CRE	ID,IP	BD	6/29/2100
2020 PO1908537402	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	6/30/2100
2020 PO1892137365	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	7/1/2100
2020 PO1881237466	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	7/2/2100
2020 PO3935482536	LGE	4	30 BRN	SP	CRE	ED,ID	TD	7/3/2100
2020 PO3989282792	F	4	40 BRN	SP	CRE		V	7/4/2100
2020 PO3987982782	F	6	25 BRN	SP	CRE		V	7/5/2100
2020 PO3987982790	F	4	40 BRN	SP	CRE		V	7/6/2100
2020 PO1973036360	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	7/7/2100
2020 PO1977136633	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD	7/8/2100
2020 PO1969436474	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD	7/9/2100
2020 PO4728029808	KU	6	30 ACE	SP	CRE		V	7/10/2100
2020 PO3986382786	LGE	4	25 BRN	SP	S		V	7/11/2100
2020 PO3987082793	F	4	40 BRN	SP	CCA		V	7/12/2100
2020 PO3933482568	F	4	40 BRN	SP	P		V	7/13/2100
2020 PO6525837275	F	4	40 BRN	SP	CRE		V	7/14/2100
2020 PO6530437399	F	3	45 BRN	SP	CCA		V	7/15/2100
2020 PO3934982600	F	4	40 BRN	SP	CCA		V	7/16/2100
2020 PO3936982595	LGE	4	35 BRN	SP	CRE	ED,ID	BD	7/17/2100
2020 PO3934982602	F	4	40 BRN	SP	P		V	7/18/2100
2020 PO3935182606	LGE	3	45 BRN	SP	CCA		V	7/19/2100
2020 PO3935482611	F	4	40 BRN	SP	CCA		V	7/20/2100
2020 PO3939182602	LGE	4	35 BRN	SP	CRE	ED,ID	BD	7/21/2100
2020 PO3937982608	F	4	35 BRN	SP	CRE		V	7/22/2100
2020 PO3936882613	F	4	40 BRN	SP	CCA		V	7/23/2100
2020 PO2888327863	F	4	40 BRO	SP	A		V	7/24/2100
2020 PO2864128362	F	4	40 BRO	SP	CRE		V	7/25/2100
2020 PO2897427689	ODP	4	40 BRO	SP	CRE	ID	TD	7/26/2100
2020 PO4716829309	KU	3	45 ACE	SP	CRE	ED,ID	BD	7/27/2100
2020 PO4744029502	KU	3	45 ACE	SP	CRE	ED,ID	BD	7/28/2100
2020 PO1941836877	KU	4	40 BRO	SP	CRE	ID,IP	BD	7/29/2100
2020 PO3986082848	F	4	40 BRN	SP	CRE		V	7/30/2100
2020 PO1305635908	F	4	45 SWP	SP	A		V	7/31/2100
2020 PO1297836028	F	4	40 SWP	SP	A		V	8/1/2100
2020 PO1280036228	F	4	40 SWP	SP	A		V	8/2/2100

2020 PO1283636092	F	4	40 SWP	SP	A		V			8/3/2100
2020 PO2919727601	ODP	4	40 BRO	SP	CRE	ID	TD			8/4/2100
2020 PO2981327411	F	4	40 BRO	SP	CRE		V			8/5/2100
2020 PO3985482896	F	4	40 BRN	SP	CRE		V			8/6/2100
2020 PO3985782905	F	4	35 BRN	SP	CCA		V			8/7/2100
2020 PO3985382904	F	4	40 BRN	SP	S		V			8/8/2100
2020 PO3984682918	F	4	40 BRN	SP	CRE		V			8/9/2100
2020 PO3984282929	F	3	45 BRN	SP	S		V			8/10/2100
2020 PO3984182941	F	4	40 BRN	SP	S		V			8/11/2100
2020 PO4742814614	F	5	35 ACE	SP	CRE		V			8/12/2100
2020 PO4753514338	F	5	35 ACE	SP	P		V			8/13/2100
2020 PO4804914015	F	5	35 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX		8/14/2100
2020 PO4807714079	F	4	40 ACE	SP	CCA		V			8/15/2100
2020 PO4814114223	F	4	40 ACE	SP	P		V			8/16/2100
2020 PO4646014353	F	4	40 ACE	SP	P		V			8/17/2100
2020 PO4644314370	F	3	40 ACE	SP	P		V			8/18/2100
2020 PO4728914854	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	RP1		8/19/2100
2020 PO4725714893	F	4	40 ACE	SP	CRE		V			8/20/2100
2020 PO4736514673	F	4	40 ACE	SP	CCA		V			8/21/2100
2020 PO4726714567	KU	4	40 ACE	SP	P	ID	BD			8/22/2100
2020 PO4652214141	F	4	40 ACE	SP	CRE		V			8/23/2100
2020 PO4664014191	F	4	40 ACE	SP	P		V			8/24/2100
2020 PO4670814127	F	4	40 ACE	SP	P		V			8/25/2100
2020 PO4695214290	KU	3	45 ACE	SP	CCA		V			8/26/2100
2020 PO2286639218	KU	4	40 BRN	SP	CRE	ED,ID,IP	BD			8/27/2100
2020 PO4824414455	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	PX		8/28/2100
2020 PO3983982953	F	4	40 BRN	SP	A		V			8/29/2100
2020 PO3983882965	F	4	40 BRN	SP	CRE		V			8/30/2100
2020 PO4756429697	KU	6	30 ACE	SP	CRE	ED,ID	BD			8/31/2100
2020 PO4752829720	KU	3	45 ACE	SP	CRE	ED,EP,HH,ID,IP,MD,RB	BX	RP1		9/1/2100
2020 PO4762129838	KU	6	30 ACE	SP	CRE	ED,ID	BD			9/2/2100
2020 PO4758229853	KU	3	45 ACE	SP	CRE	ED,ID	BD			9/3/2100
2020 PO4732529944	KU	6	30 ACE	SP	CRE		V			9/4/2100
2020 PO3981483087	LGE	4	40 BRN	SP	CRE	ED,ID	BD			9/5/2100
2020 PO1260336463	ODP	6	30 BRN	SP	CRE	ED,ID	TD			9/6/2100
2020 PO2260239231	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD			9/7/2100
2020 PO2273439042	KU	5	35 BRN	SP	CRE	ED,ID,SRS	TD			9/8/2100
2020 PO3982483099	LGE	4	30 BRN	SP	S		V			9/9/2100
2020 PO3982683089	LGE	3	45 BRN	SP	A	ED,ID	TD			9/10/2100
2020 PO1242435994	ODP	6	30 BRN	SP	CRE	RB	X	RP1		9/11/2100
2020 PO2282339004	KU	4	40 BRN	SP	CCA		V			9/12/2100
2020 PO4725930080	KU	3	45 ACE	SP	CRE	ED,ID	BD			9/13/2100
2020 PO4727030136	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD			9/14/2100
2020 PO6402804315	KU	3	40 BRN	SP	CCA		V			9/15/2100
2020 PO1217335998	ODP	5	30 XXX	SP	CRE	ED,ID	TD			9/16/2100
2020 PO1211136071	ODP	4	35 XXX	SP	CRE	ED,ID	TD			9/17/2100
2020 PO1203136164	ODP	4	40 XXX	SP	CRE	ED,ID	TD			9/18/2100

2020 PO1202936003	ODP	4	40 XXX	SP	CRE	ED,ID	TD	9/19/2100
2020 PO1199636117	ODP	6	30 XXX	SP	CCA		V	9/20/2100
2020 PO1187436098	ODP	4	40 XXX	SP	CRE	ED,ID	TD	9/21/2100
2020 PO2846128655	F	4	40 BRO	SP	CCA		V	9/22/2100
2020 PO2851928613	ODP	4	40 BRO	SP	CRE	ID	TD	9/23/2100
2020 PO2880028691	ODP	4	40 BRO	SP	A	ID	TD	9/24/2100
2020 PO2903028773	F	4	40 BRO	SP	CCA		V	9/25/2100
2020 PO2950228892	ODP	4	40 BRO	SP	CRE	ID	TD	9/26/2100
2020 PO6402304109	KU	5	30 MAR	SP	CRE		V	9/27/2100
2020 PO6397903988	KU	5	30 MAR	SP	CRE		V	9/28/2100
2020 PO3984583053	LGE	6	25 BRN	SP	CRE	ED,ID	TD	9/29/2100
2020 PO4829614497	F	5	35 ACE	SP	P		V	9/30/2100
2020 PO4759414395	F	4	40 ACE	SP	P		V	10/1/2100
2020 PO4770614296	F	4	40 ACE	SP	P		V	10/2/2100
2020 PO4780014197	KU	4	40 ACE	SP	P		V	10/3/2100
2020 PO4792814134	F	4	40 ACE	SP	CCA		V	10/4/2100
2020 PO4817914306	F	4	40 ACE	SP	P		V	10/5/2100
2020 PO4809114529	F	4	40 ACE	SP	P		V	10/6/2100
2020 PO4796014593	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	BX	RP1 10/7/2100
2020 PO4784414648	F	4	40 ACE	SP	P		V	10/8/2100
2020 PO4788814696	F	5	35 ACE	SP	P		V	10/9/2100
2020 PO3985383051	LGE	4	40 BRN	SP	CRE	ED,ID	TD	10/10/2100
2020 PO2340037468	KU	5	35 BRN	SP	CRE	ID,IP	BD	10/11/2100
2020 PO2238132841	KU	5	30 BRN	SP	CRE		V	10/12/2100
2020 PO2262332906	KU	5	35 BRN	SP	CRE		V	10/13/2100
2020 PO1851837414	KU	4	40 BRN	SP	CRE	ID,IP	BD	10/14/2100
2020 PO1867936941	KU	3	45 BRN	SP	CRE	ID,IP	BD	10/15/2100
2020 PO1889036040	KU	5	35 BRN	SP	CRE		B	10/16/2100
2020 PO6392804163A	KU	6	30 BRN	SP	CCA		V	10/17/2100
2020 PO3892182623	LGE	4	35 BRO	SP	P	ED	X	RP2 10/18/2100
2020 PO3891882611	LGE	4	35 BRO	SP	CCA		V	10/19/2100
2020 PO3891782642	LGE	4	30 BRO	SP	P	ED	TD	10/20/2100
2020 PO3892182652	LGE	4	35 BRO	SP	CCA		V	10/21/2100
2020 PO3892582662	LGE	4	35 BRO	SP	CCA		V	10/22/2100
2020 PO3891382663	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	10/23/2100
2020 PO4749130080	KU	3	45 ACE	SP	CRE	ED,ID	BD	10/24/2100
2020 PO4764630090	KU	3	45 ACE	SP	CRE	ED,ID	TD	10/25/2100
2020 PO4774630096	KU	3	45 ACE	SP	CRE	ED,ID	TD	10/26/2100
2020 PO6262604324	KU	6	30 BRN	SP	CCA		V	10/27/2100
2020 PO3984983066	LGE	6	25 BRN	SP	CRE	ED,ID	TD	10/28/2100
2020 PO6259104397	KU	4	40 BRN	SP	CCA		V	10/29/2100
2020 PO3985783063	LGE	4	40 BRN	SP	CRE	ED,ID	TD	10/30/2100
2020 PO6219404520	KU	4	40 BRN	SP	CCA		V	10/31/2100
2020 PO6197004439	KU	4	45 BRN	SP	CCA		V	11/1/2100
2020 PO6211404340	KU	4	40 BRN	SP	CCA		V	11/2/2100
2020 PO6331104331	KU	4	40 BRN	SP	CCA		V	11/3/2100
2020 PO2070537102	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	11/4/2100

2020 PO2021636802	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	11/5/2100
2020 PO6327104327	KU	6	30 BRN	SP	CCA		V	11/6/2100
2020 PO2037236899	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	11/7/2100
2020 PO6335804215	KU	4	40 BRN	SP	CCA		V	11/8/2100
2020 PO1160736009	ODP	4	40 XXX	SP	CRE	ED,ID	TD	11/9/2100
2020 PO3985383076	LGE	6	25 BRN	SP	CRE		V	11/10/2100
2020 PO3986183074	LGE	4	40 BRN	SP	CRE	ED,ID	TD	11/11/2100
2020 PO7026101658B	KU	6	30 BRN	SP	CRE		V	11/12/2100
2020 PO1121336066	ODP	6	30 XXX	SP	CRE	ED,ID	TD	11/13/2100
2020 PO1124236039	ODP	6	30 XXX	SP	CCA		V	11/14/2100
2020 PO6454503509	KU	3	45 BRN	SP	CCA		V	11/15/2100
2020 PO6450403513	KU	3	50 BRN	SP	CCA		V	11/16/2100
2020 PO3986883081	LGE	4	40 BRN	SP	CCA		V	11/17/2100
2020 PO3986383087	LGE	4	30 BRN	SP	CCA		V	11/18/2100
2020 PO6423603548	KU	3	50 OTH	SP	CCA		V	11/19/2100
2020 PO3987583092	LGE	4	25 BRN	SP	A	ED,ID	TD	11/20/2100
2020 PO2042336930	KU	4	40 BRO	SP	CRE	ID,IP	BD	11/21/2100
2020 PO2967529136	ODP	4	40 BRO	SP	CRE	ID	TD	11/22/2100
2020 PO3012029212	ODP	4	40 BRO	SP	CRE	ID	TD	11/23/2100
2020 PO3045329175	ODP	5	35 BRO	SP	CRE	ED,EP,ID	TD	11/24/2100
2020 PO3987683084	LGE	4	40 BRN	SP	CRE	ED,ID,SRC	TD	11/25/2100
2020 PO1111236747	ODP	4	40 BRN	SP	A	ID	BD	11/26/2100
2020 PO1105536671	ODP	6	30 BRN	SP	CCA		V	11/27/2100
2020 PO1080036843	ODP	6	30 BRN	SP	CCA		V	11/28/2100
2020 PO1086136798	ODP	6	30 BRN	SP	CCA		V	11/29/2100
2020 PO1068936759	ODP	6	30 BRN	SP	CCA		V	11/30/2100
2020 PO1077136738	ODP	6	30 BRN	SP	CCA		V	12/1/2100
2020 PO1072236625	ODP	6	30 BRN	SP	CCA		V	12/2/2100
2020 PO1085636670	ODP	6	30 BRN	SP	CCA		V	12/3/2100
2020 PO1094936673	ODP	6	30 XXX	SP	CRE	ED,ID	TD	12/4/2100
2020 PO1867235845	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	12/5/2100
2020 PO2377837357	KU	5	35 BRN	SP	CRE	ED,ID	TD	12/6/2100
2020 PO2084537306	KU	4	40 BRO	SP	CRE	ID,IP	BD	12/7/2100
2020 PO2089337218	KU	4	40 BRO	SP	CRE	ED	TD	12/8/2100
2020 PO2368737914	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	12/9/2100
2020 PO2359238233	KU	4	40 BRO	SP	CCA		V	12/10/2100
2020 PO6312204592	ODP	3	45 BRN	SP	CCA		V	12/11/2100
2020 PO6302604651	ODP	3	45 BRN	SP	CCA		V	12/12/2100
2020 PO6281304771	ODP	3	45 BRN	SP	CCA		V	12/13/2100
2020 PO6287204714	ODP	3	50 BRN	SP	CCA		V	12/14/2100
2020 PO6276804722	ODP	3	45 BRN	SP	CCA		V	12/15/2100
2020 PO6260104592	ODP	3	40 BRN	SP	CCA		V	12/16/2100
2020 PO398883086	LGE	4	40 BRN	SP	CRE	ED,ID	TD	12/17/2100
2020 PO3989983088	LGE	4	40 BRN	SP	CRE	ED,ID	TD	12/18/2100
2020 PO6246104504	ODP	3	40 BRN	SP	CCA		V	12/19/2100
2020 PO3049829259	ODP	4	40 BRO	SP	CRE	ID	BD	12/20/2100
2020 PO3038229475	ODP	5	35 BRO	SP	CRE	ID	TD	12/21/2100

2020 PO3088829336	ODP	4	40 BRO	SP	CRE	ID	TD	12/22/2100
2020 PO3133329303	ODP	4	40 BRO	SP	CRE	ID	TD	12/23/2100
2020 PO6228604414	ODP	3	45 BRN	SP	CCA		V	12/24/2100
2020 PO3863482712	LGE	1	65 BRO	SP	P		V	12/25/2100
2020 PO2392837361	KU	5	35 BRN	SP	CRE	ED,ID,SRC	TD	12/26/2100
2020 PO2393837435	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	12/27/2100
2020 PO2403737321	KU	4	40 BRN	SP	CRE		V	12/28/2100
2020 PO2229733195	KU	5	35 BRN	SP	CRE		V	12/29/2100
2020 PO2502535420	KU	5	35 BRN	SP	CRE	ID	BD	12/30/2100
2020 PO4773529770	KU	3	45 ACE	SP	CRE	ED,ID	TD	12/31/2100
2020 PO3981283081	LGE	4	40 BRN	SP	CRE	ED,ID	TD	1/1/2101
2020 PO4787630105	KU	2	45 ACE	SP	CRE	ED,ID	TD	1/2/2101
2020 PO4782729990	KU	3	45 ACE	SP	CRE	ED,ID	BD	1/3/2101
2020 PO3991283081	LGE	4	40 BRN	SP	CCA		V	1/4/2101
2020 PO3992283092	LGE	4	40 BRN	SP	CRE	ED,ID	TD	1/5/2101
2020 PO1101534177	ODP	2	55 XXX	SP	CRE	ED,ID,MD	TD	1/6/2101
2020 PO3992883097	LGE	4	30 BRN	SP	CRE	ED,ID	BD	1/7/2101
2020 PO2422353539	KU	5	35 BRO	SP	CCA		V	1/8/2101
2020 PO3993583093	LGE	4	40 BRN	SP	CCA		V	1/9/2101
2020 PO2385852020	F	4	40 BRO	SP	CCA		V	1/10/2101
2020 PO2346852009	F	3	45 BRO	SP	A		V	1/11/2101
2020 PO2306542161	KU	4	40 BRO	SP	CCA		V	1/12/2101
2020 PO2267741062	KU	4	40 BRO	SP	CCA		V	1/13/2101
2020 PO2208040914	KU	3	45 BRO	SP	CRE		V	1/14/2101
2020 PO3994583101	LGE	6	25 BRN	SP	CRE		V	1/15/2101
2020 PO3994583094	LGE	3	45 BRN	SP	S		V	1/16/2101
2020 PO3186729259	ODP	5	35 BRO	SP	CRE	ID	TD	1/17/2101
2020 PO3809552227	KU	4	40 BRN	SP	CRE	ED,ID,SRS	TD	1/18/2101
2020 PO4784288947	LGE	4	30 BRN	SP	CCA	ED,ID	BD	1/19/2101
2020 PO3823252473	KU	4	40 BRN	SP	CRE	ED,ID,SRS	TD	1/20/2101
2020 PO3830952611	KU	4	45 BRN	SP	CRE	ID	BD	1/21/2101
2020 PO4782988976	LGE	4	30 BRN	SP	CRE	ED,ID	BD	1/22/2101
2020 PO4783188972	LGE	4	30 BRN	SP	CRE	ED,ID	TD	1/23/2101
2020 PO4783588964	LGE	4	30 BRN	SP	P		T	1/24/2101
2020 PO4832217022	KU	6	30 ACE	SP	CCA		V	1/25/2101
2020 PO3833352855	KU	6	30 BRN	SP	CRE	ED,ID,SRS	TD	1/26/2101
2020 PO3840352772	KU	4	40 BRN	SP	CCA		V	1/27/2101
2020 PO3850152939	KU	4	40 BRN	SP	CRE		V	1/28/2101
2020 PO3869653283	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	1/29/2101
2020 PO4637188716	LGE	3	45 OTH	SP	CCA		V	1/30/2101
2020 PO4636688717	LGE	3	45 OTH	SP	CCA		V	1/31/2101
2020 PO4635988727	LGE	3	45 OTH	SP	CCA		V	2/1/2101
2020 PO4640688856	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	2/2/2101
2020 PO4655988997	LGE	4	40 ACW	SP	S		V	2/3/2101
2020 PO4655489002	LGE	4	30 ACW	SP	S		V	2/4/2101
2020 PO4660689142	LGE	4	40 ACW	SP	P		V	2/5/2101
2020 PO465888950	LGE	4	40 ACW	SP	CRE	ED,ID,IP	TD	2/6/2101

2020 PO4658988947	LGE	4	40 ACW	SP	CRE	ED,ID,IP	TD	2/7/2101
2020 PO4330888172	LGE	2	50 BRN	SP	CCA		V	2/8/2101
2020 PO4332388195	LGE	3	45 BRN	SP	CCA		V	2/9/2101
2020 PO4658988968	LGE	4	40 ACW	SP	CRE	ID	BD	2/10/2101
2020 PO4658788970	LGE	4	30 ACW	SP	P	ED,ID,IP	TD	2/11/2101
2020 PO3849504874	LGE	4	40 ACW	SP	S		V	2/12/2101
2020 PO4676989214	LGE	4	40 ACW	SP	CRE	ED,ID	TD	2/13/2101
2020 PO4677389216	LGE	4	40 ACW	SP	CRE	ED,ID	TD	2/14/2101
2020 PO4671489150	LGE	4	35 XXX	SP	CRE	ID	BD	2/15/2101
2020 PO4671689068	LGE	4	35 XXX	SP	CRE	ID	BD	2/16/2101
2020 PO4671289126	LGE	4	35 XXX	SP	CRE	ID	BD	2/17/2101
2020 PO4669689112	LGE	4	35 XXX	SP	CRE	ED,ID,IP	TD	2/18/2101
2020 PO4670389103	LGE	4	35 XXX	SP	CRE	ED,ID	TD	2/19/2101
2020 PO4322688156	LGE	3	60 BRN	SP	P	ID	TD	2/20/2101
2020 PO4323588154	LGE	2	60 BRN	SP	CRE	ED,ID,IP	BD	2/21/2101
2020 PO4325388151	LGE	2	55 OTH	SP	CCA		V	2/22/2101
2020 PO4324788152	LGE	2	60 BRN	SP	P	ID	BD	2/23/2101
2020 PO4323988153	LGE	1	60 BRN	UN	CCA		V	2/24/2101
2020 PO4324488152	LGE	2	55 BRN	SP	CCA		V	2/25/2101
2020 PO4671589083	LGE	4	35 XXX	SP	CRE	ID	BD	2/26/2101
2020 PO4672189088	LGE	4	30 XXX	SP	CRE	ED,ID	TD	2/27/2101
2020 PO4671289091	LGE	4	35 XXX	SP	CRE	ID	BD	2/28/2101
2020 PO4327088152	LGE	3	55 OTH	SP	CRE	ID	BD	3/1/2101
2020 PO4326588149	LGE	3	65 OTH	SP	P	ID	BD	3/2/2101
2020 PO4327688148	LGE	2	60 OTH	WC	CRE	ID	BD	3/3/2101
2020 PO4328288147	LGE	3	65 OTH	SP	CCA		V	3/4/2101
2020 PO4330488147	LGE	1	60 OTH	SP	P	ID	BD	3/5/2101
2020 PO4329088145	LGE	2	65 OTH	WC	P	ID	BD	3/6/2101
2020 PO4329788144	LGE	H2	65 OTH	SP	P	ID	BD	3/7/2101
2020 PO4670489120	LGE	4	35 XXX	SP	CCA	ED,ID,IP	TD	3/8/2101
2020 PO4672989124	LGE	4	35 KOP	SP	CRE	ED,ID	TD	3/9/2101
2020 PO4673389109	LGE	4	30 KOP	SP	CRE	ED,ID	TD	3/10/2101
2020 PO0488394816	LGE	1	50 BRO	SP	CCA		V	3/11/2101
2020 PO4338388273	LGE	1	50 BRO	SP	CCA		V	3/12/2101
2020 PO4339788282	LGE	4	40 OTH	SP	CCA		V	3/13/2101
2020 PO4334988233	LGE	3	45 BRO	SP	CCA		V	3/14/2101
2020 PO0489184747	LGE	1	50 BRO	SP	CCA		V	3/15/2101
2020 PO4333388308	LGE	1	20 OTH	SP	S		V	3/16/2101
2020 PV4334288351	LGE	1	35 OTH	UN	S		V	3/17/2101
2020 PO4339188291	LGE	1	20 OTH	UN	S		V	3/18/2101
2020 PO0482494701	LGE	1	50 BRO	SP	CCA		V	3/19/2101
2020 PV4333388358	LGE	1	20 OTH	UN	P		V	3/20/2101
2020 PO4339288278	LGE	3	45 OTH	SP	CCA		V	3/21/2101
2020 PO4337688184	LGE	2	55 OTH	SP	P	ID	BD	3/22/2101
2020 PO0460695727	LGE	1	20 OTH	UN	S		V	3/23/2101
2020 PO4336288337	LGE	1	20 OTH	UN	S		V	3/24/2101
2020 PO4337088324	LGE	1	20 OTH	UN	S		V	3/25/2101

Business Use

2020 PO4337488299	LGE	1	20 OTH	SP	S		V		3/26/2101
2020 PO4334088239	LGE	1	55 BRO	SP	CCA		V		3/27/2101
2020 PO4335488316	LGE	1	20 OTH	SP	S		V		3/28/2101
2020 PO4335688346	LGE	1	20 OTH	UN	CCA		V		3/29/2101
2020 PO433588308	LGE	1	20 OTH	SP	S		V		3/30/2101
2020 PO4334288235	LGE	1	60 BRO	SP	CCA		V		3/31/2101
2020 PO4337788301	LGE	1	20 OTH	SP	P		V		4/1/2101
2020 PO4337188321	LGE	1	20 OTH	UN	S		V		4/2/2101
2020 PO4331288148	F	5	30 OTH	SP	CRE		V		4/3/2101
2020 PO4335088356	LGE	1	20 OTH	UN	CCA		V		4/4/2101
2020 PO4338288305	LGE	1	20 OTH	UN	S		V		4/5/2101
2020 PO4335288220	LGE	1	60 BRO	SP	CCA		V		4/6/2101
2020 PO4337988310	LGE	1	20 OTH	SP	S		V		4/7/2101
2020 PO4673689117	LGE	4	35 KOP	SP	CRE	ED,ID	TD		4/8/2101
2020 PO4297288160	LGE	1	60 ACW	SP	A	ID	BD		4/9/2101
2020 PO0093593575	LGE	1	60 ACW	DF	CRE	ID	BD		4/10/2101
2020 PO4297888172	LGE	1	60 ACW	SP	S		V		4/11/2101
2020 PO4291387992	LGE	1	55 ACW	SP	CRE	ID	BD		4/12/2101
2020 PO4291587992	LGE	1	55 ACW	SP	CRE	ID	BD		4/13/2101
2020 PO4291987991	LGE	4	40 ACW	SP	CRE	ID	BD		4/14/2101
2020 PO4294787988	LGE	3	55 ACW	SP	P	ID	BD		4/15/2101
2020 PO4293787989	LGE	1	55 ACW	SP	CRE	ED,EP,ID,MD	BD		4/16/2101
2020 PO4295287965	LGE	3	50 ACW	SP	S		V		4/17/2101
2020 PO4295287972	LGE	3	50 ACW	SP	S		V		4/18/2101
2020 PO4295187959	LGE	1	50 ACW	SP	CRE	ID	BD		4/19/2101
2020 PO4295087958	LGE	1	50 ACW	SP	A	ID	BD		4/20/2101
2020 PO4294687925	LGE	1	50 ACW	SP	A	ID	BD		4/21/2101
2020 PO429987940	LGE	2	55 ACW	SP	CRE	ID	BD		4/22/2101
2020 PO4294687921	LGE	4	40 ACW	SP	CRE	ID	BD		4/23/2101
2020 PO4299487941	LGE	3	50 ACW	SP	CRE	ID	BD		4/24/2101
2020 PO4301787938	LGE	1	55 ACW	SP	CRE	ID	BD		4/25/2101
2020 PO2741205070	KU	3	45 BRO	SP	CCA		V		4/26/2101
2020 PO6996281832	KU	3	45 BRN	SP	CRE	ED,ID,IP	TD		4/27/2101
2020 PO6999381883	KU	4	40 BRN	SP	CRE		V		4/28/2101
2020 PO6998782630	KU	2	60 BRN	SP	CRE	ED,ID,IP	BD		4/29/2101
2020 PO7002682429	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD		4/30/2101
2020 PO3797204298	KU	3	50 BRN	SP	CCA		V		5/1/2101
2020 PO3786504196	KU	6	30 BRN	SP	CCA		V		5/2/2101
2020 PO3792604218	KU	4	40 BRN	SP	CRE		V		5/3/2101
2020 PO3793804218	KU	3	50 BRN	SP	CCA		V		5/4/2101
2020 PO7564173219	KU	6	30 BRO	SP	CRE	ED,ID	BD		5/5/2101
2020 PO7576073067	KU	4	40 BRO	SP	CRE	ED,ID	TD		5/6/2101
2020 PO7585573475	KU	5	35 BRO	SP	CRE	ED,ID	TD		5/7/2101
2020 PO7092685305	KU	3	45 BRO	SP	CRE	ED,ID	BD		5/8/2101
2020 PO6979682631	KU	4	40 BRN	DF	CCA		V		5/9/2101
2020 PO7563673318	KU	6	30 BRO	SP	CRE	ED,ID	BD		5/10/2101
2020 PO7097985560	KU	3	40 BRO	SP	A	ED,ID	TD		5/11/2101

2020 PO7100685844	KU	3	45 BRO	SP	CRE	ED,ID,IP,MD	BD	5/12/2101	
2020 PO7005982212	KU	4	40 BRN	SP	CRE		V	5/13/2101	
2020 PO7572873478	KU	5	35 BRO	SP	CRE	ED,ID	TD	5/14/2101	
2020 PO7001482012	KU	4	40 BRN	SP	CRE	ED,ID	BD	5/15/2101	
2020 PO7003482142	KU	5	35 BRN	SP	CRE	ED,ID	BD	5/16/2101	
2020 PO2750904925	KU	3	45 BRO	SP	CCA		V	5/17/2101	
2020 PO2771604625	KU	3	50 BRO	SP	CCA		V	5/18/2101	
2020 PO2777104533	KU	3	45 BRO	SP	CCA		V	5/19/2101	
2020 PO2776304336	KU	3	45 BRO	SP	CCA		V	5/20/2101	
2020 PO2807104037	KU	3	45 BRO	SP	CCA		V	5/21/2101	
2020 PO2836803830	KU	3	55 BRO	SP	CCA		V	5/22/2101	
2020 PO2854103861	KU	3	45 BRO	SP	CCA		V	5/23/2101	
2020 PO2868603934	KU	3	45 BRO	SP	CCA		V	5/24/2101	
2020 PO2891703893	KU	3	45 BRO	SP	CCA		V	5/25/2101	
2020 PO3097303236	KU	3	50 BRO	SP	CCA		V	5/26/2101	
2020 PO7102085655	KU	4	40 BRO	SP	A	ED,ID	TD	5/27/2101	
2020 PO7098985652	KU	3	45 BRO	SP	A	ED,ID	BD	5/28/2101	
2020 PO2904603923	KU	3	45 BRO	SP	CCA		V	5/29/2101	
2020 PO2928303978	KU	3	50 BRO	SP	CCA		V	5/30/2101	
2020 PO2951503942	KU	3	50 BRO	SP	CCA		V	5/31/2101	
2020 PO2974903971	KU	3	50 BRO	SP	CCA		V	6/1/2101	
2020 PO2992204031	KU	3	55 BRO	SP	CCA		V	6/2/2101	
2020 PO3038303616	KU	3	45 BRO	SP	CCA		V	6/3/2101	
2020 PO3061803363	KU	3	50 BRO	SP	CCA		V	6/4/2101	
2020 PO3073803167	KU	3	55 BRO	SP	CCA		V	6/5/2101	
2020 PO3109503246	KU	3	50 BRO	SP	CCA		V	6/6/2101	
2020 PO3123003265	KU	3	45 BRO	SP	CCA		V	6/7/2101	
2020 PO3145403308	KU	3	45 BRO	SP	CCA		V	6/8/2101	
2020 PO3164003417	KU	6	30 BRO	SP	CCA		V	6/9/2101	
2020 PO3163703331	KU	3	45 BRO	SP	CCA		V	6/10/2101	
2020 PO3163503473	KU	4	40 BRO	SP	CCA		V	6/11/2101	
2020 PO3786803987	KU	5	35 BRN	OT	CCA		V	6/12/2101	
2020 PO3784603801	KU	4	40 BRN	SP	CRE		V	6/13/2101	
2020 PO3792604158	KU	3	50 BRN	SP	CCA		V	6/14/2101	
2020 PO3791704055	KU	3	50 BRN	SP	CCA		V	6/15/2101	
2020 PO3775504135	KU	6	30 BRN	SP	CCA		V	6/16/2101	
2020 PO3785304087	KU	4	40 BRN	SP	CCA		V	6/17/2101	
2020 PO3785503987	KU	4	45 BRN	SP	CCA		V	6/18/2101	
2020 PO3791303888	KU	3	55 BRN	SP	CCA		V	6/19/2101	
2020 PO3223204226	KU	4	40 BRO	SP	CRE	ID	TX	RR	6/20/2101
2020 PO3987302507	KU	6	30 BRN	SP	CCA		V	6/21/2101	
2020 PO7122485671	KU	5	35 BRO	SP	CRE	ED,ID	BD	6/22/2101	
2020 PO7122085626	KU	4	40 BRO	SP	A	ED,ID	BD	6/23/2101	
2020 PO7036282916	KU	6	30 BRN	SP	CCA		V	6/24/2101	
2020 PO7554372882	KU	5	35 BRO	SP	CRE	ED,ID	BD	6/25/2101	
2020 PO7135085599	KU	4	40 BRO	SP	A	ED,ID	BD	6/26/2101	
2020 PO7147485569	KU	4	40 BRO	SP	CRE	ED,ID	BD	6/27/2101	

2020 PO7161785581	KU	4	40 BRO	SP	A	ED,ID	TD	6/28/2101
2020 PO7566372778	KU	4	40 BRO	SP	CCA		V	6/29/2101
2020 PO7538072756	KU	4	45 BRO	SP	CCA		V	6/30/2101
2020 PO7571672515	KU	4	40 BRO	SP	CCA		V	7/1/2101
2020 PO7591972370	KU	4	40 BRO	SP	CCA		V	7/2/2101
2020 PO3216504163	KU	4	40 BRO	SP	CRE	ID	BD	7/3/2101
2020 PO3214504211	KU	6	30 BRO	SP	CRE	ID	TD	7/4/2101
2020 PO3194304138	KU	5	35 BRO	SP	CRE	ID	TD	7/5/2101
2020 PO3192604094	KU	4	40 BRO	SP	CRE	ID	TD	7/6/2101
2020 PO3239503985	KU	4	40 BRO	SP	CRE	ID	TD	7/7/2101
2020 PO7169285637	KU	3	45 BRO	SP	CRE	ED,ID	TD	7/8/2101
2020 PO7026883001	KU	3	45 BRN	SP	CRE	ED,ID,IP	TD	7/9/2101
2020 PO7018783026	KU	6	30 BRN	SP	CRE	ED,ID	BD	7/10/2101
2020 PO7172285548	KU	5	35 BRO	SP	CRE	ED,ID	TD	7/11/2101
2020 PO7526072876	KU	4	40 BRO	SP	A	ED,ID	TD	7/12/2101
2020 PO7449272508	KU	4	35 BRO	SP	A	ED,ID	TD	7/13/2101
2020 PO7401273030	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/14/2101
2020 PO7426072759	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/15/2101
2020 PO3993702464	KU	4	40 XXX	SP	CRE	ID	TD	7/16/2101
2020 PO7169285592	KU	4	40 BRO	SP	CRE	ED,ID	TD	7/17/2101
2020 PO3980602463	KU	6	30 BRO	SP	CCA		V	7/18/2101
2020 PO3995502714	KU	4	40 XXX	SP	CRE	ID	BD	7/19/2101
2020 PO3986902685	KU	6	30 XXX	SP	CRE	ID	BD	7/20/2101
2020 PO3972002794	KU	4	40 XXX	SP	CRE	ID	TD	7/21/2101
2020 PO7186585597	KU	6	35 BRO	SP	CRE	ED,ID	TD	7/22/2101
2020 PO7131884943	KU	6	30 BRO	SP	CRE	ED,ID	TD	7/23/2101
2020 PO7103484876	KU	3	45 BRO	SP	A	ED,ID	BD	7/24/2101
2020 PO7012283147	KU	5	35 BRN	SP	CCA	ED,ID	T	7/25/2101
2020 PO7032283257	KU	4	40 BRN	SP	CRE	ED,ID,IP	TX	RR 7/26/2101
2020 PO7028383113	KU	4	40 BRN	SP	P	ED,ID	BD	7/27/2101
2020 PO3218103774	KU	4	40 BRO	SP	CRE	ID	TD	7/28/2101
2020 PO3093103667	KU	4	40 BRO	SP	CCA		V	7/29/2101
2020 PO3087203736	KU	6	30 BRO	SP	CCA		V	7/30/2101
2020 PO7093484700	KU	4	40 BRO	SP	CRE	ED,ID	BD	7/31/2101
2020 PO7450872794	KU	4	40 BRO	SP	CRE	ED,ID	TD	8/1/2101
2020 PO7452973112	KU	4	40 BRO	SP	CRE	ED,ID	BD	8/2/2101
2020 PO7482373243	KU	4	40 BRO	SP	A	ED,ID	TD	8/3/2101
2020 PO7092984919	KU	3	45 BRO	SP	A	ED,ID	BD	8/4/2101
2020 PO7141484679	KU	5	30 BRO	SP	CCA		B	8/5/2101
2020 PO7036183393	KU	4	40 BRN	SP	CRE	ED,ID	TD	8/6/2101
2020 PO3965802862	KU	5	30 XXX	SP	CRE	ID	TD	8/7/2101
2020 PO7146384713	KU	3	50 BRO	SP	CRE		V	8/8/2101
2020 PO7126184708	KU	6	30 BRO	SP	CRE	ED,ID	BD	8/9/2101
2020 PO7115084737	KU	6	30 BRO	SP	CRE	ED,ID	TD	8/10/2101
2020 PO3957002819A	KU	6	30 XXX	SP	CRE	ID	TD	8/11/2101
2020 PO7038883732	KU	4	40 BRN	SP	CRE	ED,ID	TD	8/12/2101
2020 PO3976403124	KU	6	30 XXX	SP	CRE	ID	TD	8/13/2101

2020 PO7040783569	KU	3	50 BRN	SP	CRE		B	8/14/2101
2020 PO7044883553	KU	4	40 BRN	SP	CRE		V	8/15/2101
2020 PO7102584653	KU	6	30 BRO	SP	CRE	ED,ID,RB	X	8/16/2101
2020 PO7428174591	KU	4	40 BRN	SP	CRE	ED,ID	TD	8/17/2101
2020 PO7107184757	KU	6	30 BRO	SP	CRE	ED,ID	TD	8/18/2101
2020 PO7112584864	KU	5	30 BRO	SP	CRE	ED,ID	TD	8/19/2101
2020 PO3970003112	KU	6	30 ACW	SP	CRE	ID	TD	8/20/2101
2020 PO3930503157	KU	5	35 XXX	SP	CRE	ED,ID,SRS	TD	8/21/2101
2020 PO3956303126	KU	5	35 XXX	SP	CRE	ED,ID,SRS	TD	8/22/2101
2020 PO3944103034	KU	4	35 XXX	SP	P		V	8/23/2101
2020 PO3931803048	KU	6	30 XXX	SP	CRE		B	8/24/2101
2020 PO3939103138	KU	4	40 XXX	SP	CRE	ID	TD	8/25/2101
2020 PO7086885182	KU	3	45 BRO	SP	CRE	ED,ID	TD	8/26/2101
2020 PO3172403992	KU	4	40 BRO	SP	CRE	ID	TD	8/27/2101
2020 PO3159303994	KU	5	35 BRO	SP	CRE	ID	TD	8/28/2101
2020 PO3918803189	KU	4	40 XXX	SP	CRE	ID	TD	8/29/2101
2020 PO3915403049	KU	6	30 ACW	SP	CRE	ID	TD	8/30/2101
2020 PO3939402553	KU	4	40 INP	SP	CRE	ED,ID,SRS	TD	8/31/2101
2020 PO3950402631	KU	6	30 BRN	SP	CCA		V	9/1/2101
2020 PO3916902727	KU	6	30 BRO	SP	CCA		V	9/2/2101
2020 PO7117384977A	KU	5	35 BRO	SP	CRE	ED,ID	TD	9/3/2101
2020 PO7106985007	KU	5	30 BRO	SP	CRE	ED,ID	TD	9/4/2101
2020 PO7095885034	KU	6	30 BRO	SP	CRE	ED,ID	TD	9/5/2101
2020 PO7460373308	KU	4	40 BRO	SP	CCA		V	9/6/2101
2020 PO7324975661	KU	3	45 BRN	SP	CRE	ED,ID	TD	9/7/2101
2020 PO7316775165	KU	3	55 BRN	SP	CRE	ED,ID	TD	9/8/2101
2020 PO7319675343	KU	3	45 BRN	SP	CRE	ED,ID,IP	TD	9/9/2101
2020 PO7321875546	KU	3	45 BRN	SP	A	ED,ID	TD	9/10/2101
2020 PO7343175574	KU	4	45 BRN	SP	CCA		V	9/11/2101
2020 PO7081984992	KU	4	40 BRO	SP	CRE	ED,ID	TD	9/12/2101
2020 PO7507073170	KU	4	40 BRO	SP	P	ED,ID	TX	9/13/2101
2020 PO3144903903	KU	6	30 BRO	SP	CRE	ID	TD	9/14/2101
2020 PO3141103954	KU	4	40 BRO	SP	CCA		V	9/15/2101
2020 PO3133303938	KU	5	35 BRO	SP	CRE	ID	TD	9/16/2101
2020 PO3082803986	KU	5	30 BRO	SP	CRE	ID	BD	9/17/2101
2020 PO3124903973	KU	4	40 BRO	SP	CRE		V	9/18/2101
2020 PO3121703985	KU	5	35 BRO	SP	CRE	ID	TD	9/19/2101
2020 PO3102903992	KU	5	35 BRO	SP	CRE	ID	TD	9/20/2101
2020 PO3092903989	KU	5	35 BRO	SP	CRE	ID	TD	9/21/2101
2020 PO3121603910	KU	4	40 BRO	SP	CRE	ID	TD	9/22/2101
2020 PO3106603833	KU	6	30 BRO	SP	CRE	ID	TD	9/23/2101
2020 PO3101603887	KU	4	40 BRO	SP	CRE	ID	TD	9/24/2101
2020 PO3089203873	KU	5	35 BRO	SP	CRE	ID	TD	9/25/2101
2020 PO3925802655	KU	6	30 BRO	SP	CCA		V	9/26/2101
2020 PO3902003001	KU	6	30 BRO	SP	CRE	ED,ID	TD	9/27/2101
2020 PO7077085002	KU	3	45 BRO	SP	CRE	ED,ID	TD	9/28/2101
2020 PO7565574012	KU	4	40 BRO	SP	P	ED,ID	TD	9/29/2101

2020 PO3882002933	KU	5	35 XXX	SP	CRE	ED,ID,SRS	TD	9/30/2101
2020 PO7081185068	KU	3	45 BRO	SP	CRE	ED,ID	TD	10/1/2101
2020 PO3888003097	KU	4	40 BRO	SP	CRE	ED,ID	TD	10/2/2101
2020 PO3878802872	KU	6	30 BRO	SP	CCA		V	10/3/2101
2020 PO3884902914	KU	6	30 BRO	SP	CCA		V	10/4/2101
2020 PO3905603236	KU	4	40 XXX	SP	CRE	ID	TD	10/5/2101
2020 PO7084185060	KU	4	35 BRO	SP	CRE	ED,ID	TD	10/6/2101
2020 PO3886303299	KU	5	35 ACW	SP	CRE	ED,ID,SRS	TD	10/7/2101
2020 PO3894303282	KU	4	40 XXX	SP	CRE	ID	TD	10/8/2101
2020 PO3875303461	KU	6	30 XXX	SP	CRE	ID	TD	10/9/2101
2020 PO6121764980	KU	4	40 OTH	SP	CRE	ID	TD	10/10/2101
2020 PO6146264624	KU	4	40 OTH	SP	CCA		V	10/11/2101
2020 PO6131064369	KU	3	45 OTH	SP	CCA		V	10/12/2101
2020 PO6152964177	KU	4	40 OTH	SP	CRE	ID	TD	10/13/2101
2020 PO5725664129	F	3	45 OTH	SP	CCA		V	10/14/2101
2020 PO5746564376	F	3	45 OTH	SP	P		V	10/15/2101
2020 PO5734864241	F	3	45 OTH	SP	P		V	10/16/2101
2020 PO5706863281	F	2	45 OTH	SP	P		V	10/17/2101
2020 PO5713663612	F	3	45 OTH	SP	P		V	10/18/2101
2020 PO5716563950	F	3	45 OTH	SP	P		V	10/19/2101
2020 PO5625062343	F	4	40 OTH	SP	P		V	10/20/2101
2020 PO5839765653	KU	5	35 OTH	SP	CRE	ID	TD	10/21/2101
2020 PO5800665259	KU	4	40 OTH	SP	CCA		V	10/22/2101
2020 PO5834065521	KU	4	40 OTH	SP	CCA		V	10/23/2101
2020 PO3805652703	KU	5	35 BRN	SP	CCA		V	10/24/2101
2020 PO3808452517	KU	4	40 BRN	SP	CCA		V	10/25/2101
2020 PO3794351960	KU	4	45 BRN	SP	CRE	ED,ID,SRS	TD	10/26/2101
2020 PO3801552091	KU	4	40 BRN	SP	CRE	ED,ID,SRS	TD	10/27/2101
2020 PO4797388960	LGE	4	40 BRN	SP	CCA	ED,ID	BD	10/28/2101
2020 PO6336546939	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	10/29/2101
2020 PO6299946779	KU	4	40 ACE	SP	CCA		V	10/30/2101
2020 PO5608845503	KU	4	40 ACE	SP	CCA		V	10/31/2101
2020 PO5398546290	KU	4	40 ACE	SP	CRE		V	11/1/2101
2020 PO4113605022-A	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	11/2/2101
2020 PO4153905002	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	11/3/2101
2020 PO4167605306	KU	4	40 BRO	SP	CRE	ID,IP	BD	11/4/2101
2020 PO4188004985	KU	3	45 BRO	SP	CCA		V	11/5/2101
2020 PO4287704909	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	11/6/2101
2020 PO6238646375	KU	6	30 ACE	SP	CRE		V	11/7/2101
2020 PO4555604498	KU	5	30 BRO	ST	P		V	11/8/2101
2020 PO4561304642	KU	6	35 BRO	ST	CRE		V	11/9/2101
2020 PO5800965195	KU	6	30 OTH	SP	CRE	ID	TD	11/10/2101
2020 PO5829765289	KU	6	30 OTH	SP	CRE	ID	TD	11/11/2101
2020 PO4771615986	F	4	40 ACE	SP	CRE		V	11/12/2101
2020 PO4777815944	F	4	40 ACE	SP	CRE		V	11/13/2101
2020 PO4782915970	F	4	40 ACE	SP	CRE		V	11/14/2101
2020 PO4791115851	KU	2	45 ACE	SP	CCA		V	11/15/2101

2020 PO4796316040	F	4	40 ACE	SP	CRE		V	11/16/2101
2020 PO4784316033	KU	6	30 ACE	SP	CRE	ID,IP	BD	11/17/2101
2020 PO4645687998	LGE	3	55 BRO	SP	CRE	ED,ID	TD	11/18/2101
2020 PO4791916086	KU	6	30 ACE	SP	CRE	ID,IP	BD	11/19/2101
2020 PO4651387992	LGE	2	60 BRO	SP	CRE	ED,ID	BD	11/20/2101
2020 PO4649687994	LGE	3	55 BRO	SP	CRE	ED,ID	TD	11/21/2101
2020 PO4647687996	LGE	3	55 BRO	SP	CRE	ED,ID	TD	11/22/2101
2020 PO4653787992	LGE	UNK	65 BRO	SP	CRE		V	11/23/2101
2020 PO4651487981	LGE	4	35 BRO	SP	CRE		V	11/24/2101
2020 PO4778389017	LGE	4	30 BRN	SP	CRE	ED,ID	BD	11/25/2101
2020 PO4776289016	LGE	4	40 BRN	SP	A	ED,ID	BD	11/26/2101
2020 PO4775389003	LGE	4	40 BRN	SP	P		T	11/27/2101
2020 PO4776188991	LGE	4	40 BRN	SP	P		T	11/28/2101
2020 PO6040265928	F	4	40 OTH	SP	CRE		V	11/29/2101
2020 PO6007965870	F	4	40 OTH	SP	CRE		V	11/30/2101
2020 PO6058666127	KU	4	40 OTH	SP	CCA		V	12/1/2101
2020 PO6089566170	KU	4	40 OTH	SP	CCA		V	12/2/2101
2020 PO6041566113	KU	4	40 OTH	SP	CRE	ID	TD	12/3/2101
2020 PO6075866150	KU	4	40 OTH	SP	CRE	ID	TD	12/4/2101
2020 PO6005365751	KU	5	35 OTH	SP	CRE	ID	BD	12/5/2101
2020 PO4758588491	F	4	30 BRO	SP	CCA		V	12/6/2101
2020 PO4758788495	F	4	40 BRO	SP	CCA		V	12/7/2101
2020 PO4755888470	F	4	40 BRO	SP	CCA		V	12/8/2101
2020 PO4754888476	F	4	40 BRO	SP	A		V	12/9/2101
2020 PO4753888483	F	3	45 BRO	SP	CCA		V	12/10/2101
2020 PO4752888490	F	4	40 BRO	SP	CCA		V	12/11/2101
2020 PO4750888503	F	4	40 BRO	SP	CCA		V	12/12/2101
2020 PO4751888496	F	4	40 BRO	SP	CCA		V	12/13/2101
2020 PO4749988509	F	4	40 BRO	SP	CCA		V	12/14/2101
2020 PO4748888516	F	4	40 BRO	SP	CCA		V	12/15/2101
2020 PO4747888523	F	4	40 BRO	SP	CCA		V	12/16/2101
2020 PO4756888463	F	4	40 BRO	SP	CCA		V	12/17/2101
2020 PO4761988648	F	4	40 BRO	SP	CCA		V	12/18/2101
2020 PO4762916010	KU	4	40 ACE	SP	CRE	ID	BD	12/19/2101
2020 PO9667536361	ODP	4	45 XXX	SP	CRE	ID	BD	12/20/2101
2020 PO9679136528	ODP	4	40 XXX	SP	CRE	ID	BD	12/21/2101
2020 PO9486444137	ODP	4	40 XXX	SP	CRE	ID	TD	12/22/2101
2020 PO9489744323	ODP	4	40 XXX	SP	CCA		V	12/23/2101
2020 PO9487544528	ODP	4	40 XXX	SP	CRE	ID	TD	12/24/2101
2020 PO9689836677	ODP	4	40 XXX	SP	CRE	ID	BD	12/25/2101
2020 PO9470744577	ODP	5	35 XXX	SP	CCA		V	12/26/2101
2020 PO9460544339	ODP	4	40 XXX	SP	CCA		V	12/27/2101
2020 PO9709436937	ODP	3	40 XXX	ST	CRE		V	12/28/2101
2020 PO9721337080	ODP	4	40 XXX	SP	CRE	ID	BD	12/29/2101
2020 PO9780535768	ODP	4	40 XXX	SP	CRE		V	12/30/2101
2020 PO9763035683	ODP	5	35 XXX	SP	CRE	ID	BD	12/31/2101
2020 PO9747535629	ODP	4	40 XXX	SP	CRE	ID	TD	1/1/2102

2020 PO9723135522	ODP	4	45 XXX	SP	CRE	ID	TD	1/2/2102
2020 PO9796135957	ODP	5	35 XXX	SP	CRE	ID	BD	1/3/2102
2020 PO9771636015	ODP	4	45 XXX	SP	CRE	ID	TD	1/4/2102
2020 PO9745236092	ODP	4	45 XXX	SP	CRE	ID	BD	1/5/2102
2020 PO2108627931	ODP	5	35 XXX	SP	CRE		V	1/6/2102
2020 PO2114526040	ODP	6	30 XXX	SP	CCA		V	1/7/2102
2020 PO1821723069	ODP	6	30 XXX	SP	CCA		V	1/8/2102
2020 PO1544733465	ODP	5	30 XXX	SP	CRE		V	1/9/2102
2020 PO4765016032	F	4	40 ACE	SP	CRE		V	1/10/2102
2020 PO4750216137	F	4	40 ACE	SP	CRE	ID,RB	VX	1/11/2102
2020 PO4737616223	F	4	40 ACE	SP	CRE		V	1/12/2102
2020 PO4554315682	F	4	40 ACE	SP	CRE		V	1/13/2102
2020 PO4549615733	F	4	40 ACE	SP	CRE		V	1/14/2102
2020 PO4544815706	F	4	40 ACE	SP	CRE		V	1/15/2102
2020 PO9065826734	ODP	5	35 XXX	SP	CRE	ID	TD	1/16/2102
2020 PO9048826516	F	6	30 XXX	SP	A		V	1/17/2102
2020 PO9046626671	ODP	4	40 XXX	SP	CRE	ID	TD	1/18/2102
2020 PO9041926521	ODP	6	30 XXX	SP	CRE	ID	BD	1/19/2102
2020 PO8998826669	ODP	4	40 XXX	SP	CRE	ID	TD	1/20/2102
2020 PO8964626661	ODP	4	40 XXX	SP	CRE	ED,ID	TD	1/21/2102
2020 PO8892227027	ODP	6	30 XXX	SP	CCA		V	1/22/2102
2020 PO8884627101	ODP	4	40 XXX	SP	CRE	ID	TD	1/23/2102
2020 PO8905727235	ODP	4	40 XXX	SP	CRE	ID	TD	1/24/2102
2020 PO8887227392	ODP	4	40 XXX	SP	CRE	ID	TD	1/25/2102
2020 PO8880527699	ODP	6	30 XXX	SP	CCA		V	1/26/2102
2020 PO8920227238	F	4	40 XXX	SP	A		V	1/27/2102
2020 PO2406345314	ODP	5	35 ACW	SP	S		V	1/28/2102
2020 PO1881432760	ODP	5	35 ACW	SP	S		V	1/29/2102
2020 PO1687233074	ODP	6	30 ACW	SP	CRE	ID	BD	1/30/2102
2020 PO1847032796	F	5	35 ACW	DF	P		V	1/31/2102
2020 PO1797933173	ODP	4	40 ACW	SP	CRE	ED,ID	TD	2/1/2102
2020 PO1701333901	ODP	3	50 ACW	SP	CRE	ID	BD	2/2/2102
2020 PO1692734009	ODP	2	65 ACW	SP	CRE	ID	BD	2/3/2102
2020 PO1714333690	ODP	4	45 ACW	SP	CRE	ID	BD	2/4/2102
2020 PO1921632716	ODP	4	40 ACW	SP	CRE	ID	BD	2/5/2102
2020 PO1810332835	ODP	5	35 ACW	SP	CRE	ID	BD	2/6/2102
2020 PO1822932519	ODP	5	35 ACW	SP	S		V	2/7/2102
2020 PO1680932925	ODP	6	30 ACW	SP	CRE	ID	BD	2/8/2102
2020 PO1676532769	ODP	5	35 ACW	SP	S		V	2/9/2102
2020 PO2422645385	ODP	4	45 ACW	SP	S		V	2/10/2102
2020 PO4634488002	LGE	UNK	65 BRO	SP	A	ED,ID	TD	2/11/2102
2020 PO4634488011	LGE	4	45 BRO	SP	CRE	ED,ID	TD	2/12/2102
2020 PO4637987995	LGE	H2	65 BRO	SP	A	ED,ID	BD	2/13/2102
2020 PO4640387981	LGE	3	50 BRO	SP	CRE	ED,ID,IP	TD	2/14/2102
2020 PO4638887983	LGE	4	35 BRO	SP	CRE	ED,ID,IP	BD	2/15/2102
2020 PO4641887982	LGE	3	45 BRO	SP	CCA		V	2/16/2102
2020 PO4644187986	LGE	2	50 BRO	SP	A	ED,ID,IP	BD	2/17/2102

2020 PO4631988041	LGE	3	45 BRO	SP	CRE	ED,ID	BD	2/18/2102
2020 PO4645087983	LGE	UNK	45 BRO	ST	CCA		V	2/19/2102
2020 PO4645187986	LGE	UNK	45 BRO	ST	CCA		V	2/20/2102
2020 PO4625588021	LGE	2	55 BRO	SP	CRE	ED,ID	BD	2/21/2102
2020 PO4716487923	LGE	1	65 BRO	SP	CCA		V	2/22/2102
2020 PO4715987937	LGE	4	35 BRO	SP	A	ED,ID	TD	2/23/2102
2020 PO4712488148	LGE	3	45 BRO	SP	CCA		V	2/24/2102
2020 PO4712588150	LGE	4	45 BRO	SP	CCA	ED,ID	BD	2/25/2102
2020 PO4716487939	LGE	3	50 BRO	SP	P	ED,ID	TD	2/26/2102
2020 PO4717787941	LGE	4	35 BRO	SP	P	ED,ID	BD	2/27/2102
2020 PO4717087940	LGE	3	25 BRO	ST	CCA		V	2/28/2102
2020 PO4630688006	LGE	2	55 BRO	SP	CRE	ED,ID	BD	3/1/2102
2020 PO4628688008	LGE	2	55 BRO	SP	CCA		V	3/2/2102
2020 PO4626888010	LGE	UNK	65 BRO	SP	CRE	ED,ID	BD	3/3/2102
2020 PO4625488012	LGE	1	60 BRO	SP	CCA		V	3/4/2102
2020 PO4623688013	LGE	UNK	65 BRO	SP	CRE	ED,ID	BD	3/5/2102
2020 PO3326992784	LGE	H1	70 BRO	SP	CCA		V	3/6/2102
2020 PO4715088012	LGE	4	45 BRO	SP	CCA	ED,ID,IP,MD	BD	3/7/2102
2020 PO4715088006	LGE	1	75 BRO	SP	A		V	3/8/2102
2020 PO4715387992	LGE	4	40 BRO	SP	A	ED,ID	TD	3/9/2102
2020 PO4714288025	LGE	4	30 BRO	SP	CCA		V	3/10/2102
2020 PO4715587982	LGE	4	40 BRO	SP	CCA		V	3/11/2102
2020 PO4715787972	LGE	4	40 BRO	SP	CRE	ED,ID	BD	3/12/2102
2020 PO4716887964	LGE	4	35 BRO	SP	P	ED,ID	BD	3/13/2102
2020 PO4716187952	LGE	3	50 BRO	SP	CCA		V	3/14/2102
2020 PO4715987962	LGE	4	45 BRO	SP	CRE	ED,ID	BD	3/15/2102
2020 PO4711988147	LGE	4	40 BRO	SP	CCA	ED,ID	BD	3/16/2102
2020 PO4713888045	LGE	5	25 BRO	SP	CRE	ED,ID,IP	BD	3/17/2102
2020 PO4714688030	LGE	1	70 BRO	SP	A		V	3/18/2102
2020 PO5320644584	KU	6	30 BRO	SP	CRE		V	3/19/2102
2020 PO5331544440	KU	6	30 BRO	SP	CRE		V	3/20/2102
2020 PO5344744289	KU	6	30 BRO	SP	CRE		V	3/21/2102
2020 PO5379742314	KU	4	40 ACE	SP	CRE		V	3/22/2102
2020 PO5377642316	KU	4	40 ACE	SP	CRE		V	3/23/2102
2020 PO5306911735	F	4	40 BRO	SP	CCA		V	3/24/2102
2020 PO5305011617	F	4	40 BRO	SP	CRE		V	3/25/2102
2020 PO5303111496	F	4	40 BRO	SP	CRE		V	3/26/2102
2020 PO5252111071	F	4	40 BRO	SP	CCA		V	3/27/2102
2020 PO5250411101	F	4	40 BRO	SP	CRE		V	3/28/2102
2020 PO5257011224	F	4	40 BRO	SP	CCA		V	3/29/2102
2020 PO5255211219	F	4	40 BRO	SP	CRE		V	3/30/2102
2020 PO5259511334	F	4	40 BRO	SP	CRE		V	3/31/2102
2020 PO5263611446	F	4	40 BRO	SP	CRE		V	4/1/2102
2020 PO5265011484	F	4	40 BRO	SP	CRE		V	4/2/2102
2020 PO5222811422	F	4	40 BRO	SP	CRE		V	4/3/2102
2020 PO5220211349	F	4	40 BRO	SP	CCA		V	4/4/2102
2020 PO5217311272	F	4	40 BRO	SP	CCA		V	4/5/2102

2020 PO5214511196	F	4	40 BRO	SP	CCA		V	4/6/2102
2020 PO4627288177	LGE	1	50 BRO	SP	P	ED,ID	TD	4/7/2102
2020 PO4627188164	LGE	3	45 BRO	SP	CCA		V	4/8/2102
2020 PO4627088153	LGE	4	40 BRO	SP	CRE	ED,ID	BD	4/9/2102
2020 PO4626888141	LGE	3	45 BRO	SP	CCA		V	4/10/2102
2020 PO4626388129	LGE	3	45 BRO	SP	CCA		V	4/11/2102
2020 PO4626688117	LGE	3	45 BRO	SP	A		V	4/12/2102
2020 PO4627888104	LGE	4	40 BRO	SP	P	ED,ID	TD	4/13/2102
2020 PO8778433703	ODP	6	30 XXX	SP	CRE	ID	TD	4/14/2102
2020 PO8884334826	ODP	4	40 XXX	SP	CRE		V	4/15/2102
2020 PO8906335400	ODP	5	35 XXX	SP	CRE		V	4/16/2102
2020 PO8922335798	ODP	4	35 XXX	SP	CCA		V	4/17/2102
2020 PO9327533259	ODP	4	40 BRO	SP	CRE	ID	BD	4/18/2102
2020 PO9322933382	ODP	5	35 BRO	SP	CRE		B	4/19/2102
2020 PO9312633498	ODP	4	40 BRO	SP	CRE	ID	BD	4/20/2102
2020 PO9305733639	ODP	4	40 BRO	SP	CRE	ED,ID	BD	4/21/2102
2020 PO9299833756	ODP	5	35 BRO	SP	CRE	ID	BD	4/22/2102
2020 PO9286534083	ODP	5	35 BRO	SP	CRE	ID	BD	4/23/2102
2020 PO9274034382	ODP	5	35 BRO	SP	CRE	ED,ID	X	4/24/2102
2020 PO9342733274	ODP	4	45 BRO	SP	S		V	4/25/2102
2020 PO4626488105	LGE	3	45 BRO	SP	CRE	ED,ID	TD	4/26/2102
2020 PO4626388094	LGE	4	40 BRO	SP	CCA		V	4/27/2102
2020 PO4626188081	LGE	4	40 BRO	SP	A	ED,ID	TD	4/28/2102
2020 PO4625988055	LGE	4	40 BRO	SP	CCA	ED,ID	BD	4/29/2102
2020 PO4626088067	LGE	3	45 BRO	SP	CCA		V	4/30/2102
2020 PO8928436139	ODP	5	35 XXX	SP	CRE		V	5/1/2102
2020 PO8773134912	ODP	5	35 XXX	SP	CRE	ID	BD	5/2/2102
2020 PO8787635230A	ODP	6	30 XXX	SP	CCA		V	5/3/2102
2020 PO8798835000	F	4	40 XXX	SP	A		V	5/4/2102
2020 PO5212111125	F	4	40 BRO	SP	CCA		V	5/5/2102
2020 PO5234311684	F	4	40 BRO	SP	CRE		V	5/6/2102
2020 PO5242411652	F	4	40 BRO	SP	CRE		V	5/7/2102
2020 PO5599350374	KU	4	40 OTH	SP	CRE	ID	TD	5/8/2102
2020 PO5613449589	KU	4	40 OTH	SP	CRE	ID	TD	5/9/2102
2020 PO5603650151	KU	4	40 OTH	SP	CRE	ID	TD	5/10/2102
2020 PO5594350627	KU	4	40 OTH	SP	CRE	ID	TD	5/11/2102
2020 PO5618049385	KU	4	40 OTH	SP	CRE	ID	TD	5/12/2102
2020 PO5607449946	KU	4	40 OTH	SP	CRE	ID	TD	5/13/2102
2020 PO5623849048	KU	4	40 OTH	SP	CRE	ID	TD	5/14/2102
2020 PO5621449161	KU	4	40 OTH	SP	CRE	ID	TD	5/15/2102
2020 PO5610349790	KU	4	40 OTH	SP	CRE	ID	TD	5/16/2102
2020 PO5245810985	F	4	40 BRO	SP	CRE		V	5/17/2102
2020 PO5241310857	F	4	40 BRO	SP	CRE		V	5/18/2102
2020 PO4627888247	LGE	4	40 BRO	SP	P	ED,ID	TD	5/19/2102
2020 PO4627788235	LGE	4	40 BRO	SP	A	ED,ID	TD	5/20/2102
2020 PO4627688222	LGE	4	40 BRO	SP	CRE	ED,ID	BD	5/21/2102
2020 PO4626088202	LGE	4	40 BRO	SP	CCA		V	5/22/2102

2020 PO4630888222	LGE	3	45 BRO	SP	CCA		V	5/23/2102
2020 PO5238111773	F	4	40 BRO	SP	CRE		V	5/24/2102
2020 PO5264511770	F	4	40 BRO	SP	CRE	ID,IP,RB	VX	5/25/2102
2020 PO5254111607	F	4	40 BRO	SP	CRE		V	5/26/2102
2020 PO5263111692	F	4	40 BRO	SP	CRE		V	5/27/2102
2020 PO5277712519	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	5/28/2102
2020 PO8851934726	ODP	4	40 XXX	SP	CCA		V	5/29/2102
2020 PO8761533303	ODP	5	30 XXX	SP	CCA		V	5/30/2102
2020 PO8932636424	ODP	5	35 XXX	SP	CRE		V	5/31/2102
2020 PO8831534674	ODP	4	40 XXX	SP	CCA		V	6/1/2102
2020 PO8801034825	ODP	4	40 XXX	SP	CRE	ID	TD	6/2/2102
2020 PO8801034825	F	4	40 XXX	SP	A		V	6/3/2102
2020 PO8799334475	F	4	45 XXX	SP	P		V	6/4/2102
2020 PO8801434323	ODP	5	35 XXX	SP	CRE	ID	BD	6/5/2102
2020 PO5269912558	KU	4	40 BRO	SP	CCA		V	6/6/2102
2020 PO5247812643	KU	4	40 BRO	SP	CCA		V	6/7/2102
2020 PO5258612598	KU	4	40 BRO	SP	CRE		V	6/8/2102
2020 PO5258212553	KU	4	40 BRO	SP	CRE		V	6/9/2102
2020 PO5249912564	KU	4	40 BRO	SP	CRE		V	6/10/2102
2020 PO5236712592	KU	4	40 BRO	SP	CRE		V	6/11/2102
2020 PO5234912712	KU	4	40 BRO	SP	CRE		V	6/12/2102
2020 PO4732688134	LGE	3	45 BRO	SP	CCA		V	6/13/2102
2020 PO5283112940	KU	5	35 BRO	SP	CRE		V	6/14/2102
2020 PO5273112971	KU	5	35 BRO	SP	CRE		V	6/15/2102
2020 PO5267612988	KU	5	35 BRO	SP	CRE		V	6/16/2102
2020 PO5261513056	KU	5	35 BRO	SP	CRE		V	6/17/2102
2020 PO5298912811	KU	6	30 BRO	SP	CRE		V	6/18/2102
2020 PO5275912401	F	4	40 BRO	SP	CRE		V	6/19/2102
2020 PO3986703074	KU	6	30 XXX	SP	CRE	ID	TD	6/20/2102
2020 PO7159384865	KU	3	45 BRO	SP	CRE	ED,ID,IP	BD	6/21/2102
2020 PO3177004131	KU	4	35 BRO	SP	CRE	ID	TD	6/22/2102
2020 PO3163404120	KU	5	35 BRO	SP	CRE	ID	BD	6/23/2102
2020 PO3163004221	KU	6	30 BRO	SP	CRE	ID	BD	6/24/2102
2020 PO3156104096	KU	5	35 BRO	SP	CRE	ID	TD	6/25/2102
2020 PO7162384933	KU	7	25 BRO	SP	P	ED,ID	BD	6/26/2102
2020 PO7085384846	KU	6	30 BRO	SP	CRE	ED,ID	TD	6/27/2102
2020 PO7466072180	KU	3	40 BRO	SP	A	ED,ID	BD	6/28/2102
2020 PO7342674722	KU	4	40 BRN	SP	CRE	ED,ID	TD	6/29/2102
2020 PO3811003807	KU	4	45 XXX	SP	CRE	ED,ID	TD	6/30/2102
2020 PO7342774633	KU	6	30 BRN	SP	CRE	ED,ID,IP	TD	7/1/2102
2020 PO7330874751	KU	4	40 BRN	SP	CCA		V	7/2/2102
2020 PO3967902966	KU	6	30 BRN	SP	CCA		V	7/3/2102
2020 PO3983502961	KU	6	30 BRN	SP	CCA		V	7/4/2102
2020 PO4004802887	KU	6	30 BRN	SP	CCA		V	7/5/2102
2020 PO4000703096	KU	4	40 XXX	SP	CRE	ID	TD	7/6/2102
2020 PO3982603155	KU	4	45 XXX	SP	CRE	ID	TD	7/7/2102
2020 PO7075684807	KU	6	30 BRO	SP	CRE	ED,ID	TD	7/8/2102

2020 PO7461272288	KU	4	45 BRO	SP	CRE		B	7/9/2102
2020 PO3152104125	KU	5	35 BRO	SP	CRE	ID	TD	7/10/2102
2020 PO3151704322	KU	6	30 BRO	SP	CRE	ID	TD	7/11/2102
2020 PO3136504132	KU	4	35 BRO	SP	CRE	ID	TD	7/12/2102
2020 PO3138704249	KU	4	40 BRO	SP	CRE	ID	TD	7/13/2102
2020 PO3136504316	KU	6	30 BRO	SP	CRE	ID	BD	7/14/2102
2020 PO3126104354	KU	6	30 BRO	SP	CRE	ID	TD	7/15/2102
2020 PO7064884662	KU	6	30 BRO	SP	CRE	ED,ID	TD	7/16/2102
2020 PO3104504185	KU	5	35 BRO	SP	CRE	ID	TD	7/17/2102
2020 PO3100804296	KU	4	40 BRO	SP	CRE	ID	TD	7/18/2102
2020 PO7077284728	KU	6	30 BRO	SP	CRE	ED,ID	BD	7/19/2102
2020 PO7071584749	KU	6	30 BRO	SP	CRE	ED,ID	TD	7/20/2102
2020 PO7072684628	KU	6	30 BRO	SP	CCA	ED,ID,IP	TD	7/21/2102
2020 PO7566474168	KU	4	40 BRO	SP	CRE	ED	T	7/22/2102
2020 PO7567274334	KU	4	40 BRO	SP	P		B	7/23/2102
2020 PO7597078369	KU	3	45 BRO	SP	P	ED,ID	BD	7/24/2102
2020 PO7066584531	KU	6	30 BRO	SP	CRE	ED,ID	TD	7/25/2102
2020 PO7061184365	KU	6	30 BRO	SP	CRE	ED,ID	TD	7/26/2102
2020 PO3978203296	KU	6	30 XXX	SP	CRE	ID	TD	7/27/2102
2020 PO3971003368	KU	6	30 XXX	SP	CRE	ID	TD	7/28/2102
2020 PO3952103289	KU	4	40 XXX	SP	CRE	ID	TD	7/29/2102
2020 PO3972903194	KU	4	40 XXX	SP	CRE	ID	TD	7/30/2102
2020 PO3945503392	KU	6	30 XXX	SP	CRE	ED,ID	TD	7/31/2102
2020 PO3936403347	KU	4	40 XXX	SP	CRE	ED,ID	TD	8/1/2102
2020 PO3811803673	KU	4	40 KOP	SP	CRE	ID	BD	8/2/2102
2020 PO3815303559	KU	6	30 XXX	SP	CRE	ED,ID	TD	8/3/2102
2020 PO3823103550	KU	5	35 XXX	SP	CRE	ED,ID	TD	8/4/2102
2020 PO3829503491	KU	5	35 CPT	SP	CRE	ED,ID	TD	8/5/2102
2020 PO3839803413	KU	4	40 XXX	SP	CRE	ED,EP,ID,SRC	TX	RR 8/6/2102
2020 PO3835303321	KU	6	30 XXX	SP	CRE	ID	TD	8/7/2102
2020 PO3848903521	KU	4	40 XXX	SP	CRE	ED,ID	TD	8/8/2102
2020 3848903521A	KU	6	30 XXX	SP	CCA		V	8/9/2102
2020 PO3851103613	KU	4	40 XXX	SP	CRE	ED,ID	TD	8/10/2102
2020 PO3878003534	KU	4	40 XXX	SP	CRE	ED,ID	TD	8/11/2102
2020 PO3892003486	KU	3	40 XXX	SP	CRE	ID	TD	8/12/2102
2020 PO3920903396	KU	4	40 XXX	SP	CRE	ED,ID	TD	8/13/2102
2020 PO7557774493	KU	4	45 BRO	SP	CRE	ED,ID	BD	8/14/2102
2020 PO7568174493	KU	5	35 BRO	SP	CRE	ED,ID	TD	8/15/2102
2020 PO7569074643	KU	4	40 BRO	SP	P	ED,ID	TD	8/16/2102
2020 PO7570574935	KU	4	40 BRO	SP	CCA		V	8/17/2102
2020 PO3118504325	KU	6	30 BRO	SP	CRE	ID	TD	8/18/2102
2020 PO3124704263	KU	4	40 BRO	SP	CRE	ID	TD	8/19/2102
2020 PO3123104149	KU	4	40 BRO	SP	CRE	ID	TD	8/20/2102
2020 PO3897103390	KU	4	40 XXX	SP	CRE	ID	TD	8/21/2102
2020 PO7569774787	KU	4	40 BRO	SP	P	ED,ID	TX	RR 8/22/2102
2020 PO7058384210	KU	3	45 BRO	SP	CRE	ED,ID,IP,RB,SRC	TX	RR 8/23/2102
2020 PO3092504204	KU	6	30 BRO	SP	CRE	ID	TD	8/24/2102

2020 PO3084704220	KU	6	30 BRO	SP	CRE		V	8/25/2102
2020 PO3086204303	KU	6	30 BRO	SP	CRE		V	8/26/2102
2020 PO2890305253	KU	5	35 BRO	SP	CRE	ID	BD	8/27/2102
2020 PO7454874322	KU	5	35 BRN	SP	CRE	ED,ID,IP	TD	8/28/2102
2020 PO7456274418	KU	5	35 BRN	SP	CRE	ED,ID	TD	8/29/2102
2020 PO7450474359	KU	6	30 BRN	SP	CCA		V	8/30/2102
2020 PO7325174559	KU	4	40 BRN	SP	CCA		V	8/31/2102
2020 PO7341174534	KU	4	45 BRN	SP	CCA		V	9/1/2102
2020 PO7072484301	KU	3	40 BRO	SP	A	ED,ID	TD	9/2/2102
2020 PO7529174576	KU	5	35 BRO	SP	CRE	ED,ID	TD	9/3/2102
2020 PO7077884406	KU	4	40 BRO	SP	CRE	ED,ID	TD	9/4/2102
2020 PO7091384513	KU	4	30 BRO	SP	CRE	ED,ID	TD	9/5/2102
2020 PO3912503462	KU	6	30 XXX	SP	CRE	ED,ID	TD	9/6/2102
2020 PO3907203429	KU	4	40 XXX	SP	CRE	ED,ID,SRS	TD	9/7/2102
2020 PO3863503572	KU	4	40 XXX	SP	CRE	ED,ID	TD	9/8/2102
2020 PO3840603602	KU	4	40 KOP	SP	CCA		V	9/9/2102
2020 PO3800603787	KU	4	45 BRN	SP	CCA		V	9/10/2102
2020 PO3834503689	KU	4	40 XXX	SP	CRE	ED,ID	TD	9/11/2102
2020 PO7532774784	KU	5	35 BRO	SP	CRE	ED,ID	BD	9/12/2102
2020 PO2924404537	KU	6	30 BRO	SP	CRE	ID	TD	9/13/2102
2020 PO2924104461	KU	6	30 BRO	SP	CRE	ID	TD	9/14/2102
2020 PO2826304224	KU	4	40 BRO	SP	CCA		V	9/15/2102
2020 PO2819004317	KU	4	40 BRO	SP	CCA		V	9/16/2102
2020 PO2795404570	KU	4	45 BRO	SP	CCA		V	9/17/2102
2020 PO2802904488	KU	4	45 BRO	SP	CRE	ID	TD	9/18/2102
2020 PO2791704712	KU	4	40 BRO	SP	CRE		V	9/19/2102
2020 PO4641089088	LGE	3	45 OTH	SP	CCA		V	9/20/2102
2020 PO4640289099	LGE	4	40 OTH	SP	P	ED,ID,SRS	TD	9/21/2102
2020 PO4641789077	LGE	3	45 OTH	SP	CCA		V	9/22/2102
2020 PO4776087656	LGE	4	40 XXX	SP	A	ED,ID	TD	9/23/2102
2020 PO4773787665	LGE	4	40 XXX	SP	A	ID	BD	9/24/2102
2020 PO4639989103	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	9/25/2102
2020 PO4633089199	LGE	4	30 OTH	SP	P	ID	BD	9/26/2102
2020 PO4638989120	LGE	4	40 OTH	SP	P	ED,SRS	TD	9/27/2102
2020 PO4654488801	LGE	3	45 OTH	SP	CCA		V	9/28/2102
2020 PO4655088794	LGE	3	45 OTH	SP	CCA		V	9/29/2102
2020 PO4651188828	LGE	3	45 OTH	SP	CCA		V	9/30/2102
2020 PO4652088835	LGE	3	45 OTH	SP	CCA		V	10/1/2102
2020 PO4649088812	LGE	4	40 OTH	SP	CCA		V	10/2/2102
2020 PO4656288840	LGE	3	45 OTH	SP	CCA		V	10/3/2102
2020 PO4656288814	LGE	4	35 OTH	SP	CCA		V	10/4/2102
2020 PO4655088835	LGE	3	45 OTH	SP	CCA		V	10/5/2102
2020 PO4650688825	LGE	4	30 OTH	SP	CCA		V	10/6/2102
2020 PO4657488823	LGE	3	45 OTH	SP	CCA		V	10/7/2102
2020 PO4649988820	LGE	4	40 OTH	SP	CCA		V	10/8/2102
2020 PO4647988804	LGE	4	40 OTH	SP	CCA		V	10/9/2102
2020 PO4667889140	LGE	4	30 KOP	SP	P	ED,ID	TD	10/10/2102

2020 PO4667489145	LGE	4	40 KOP	SP	CRE	ED,ID	TD		10/11/2102
2020 PO4667289150	LGE	4	30 KOP	SP	P	ED,ID	TD		10/12/2102
2020 PO4668589152	LGE	4	40 KOP	SP	P	ID	BD		10/13/2102
2020 PO4668389178	LGE	4	30 KOP	SP	P	ID	BD		10/14/2102
2020 PO4650688724	LGE	4	40 OTH	SP	CCA		V		10/15/2102
2020 PO4647388774	LGE	4	40 OTH	SP	P	ED,ID,SRS	TD		10/16/2102
2020 PO4651188727	LGE	4	30 OTH	SP	CCA	ID	BD		10/17/2102
2020 PO4646788783	LGE	3	40 OTH	SP	P	ED,ID,SRS	TD		10/18/2102
2020 PO4649688740	LGE	4	40 OTH	SP	CCA	ED,SRS	TD		10/19/2102
2020 PO4648488757	LGE	4	40 OTH	SP	CCA		V		10/20/2102
2020 PO4646388792	LGE	4	40 OTH	SP	CCA		V		10/21/2102
2020 PO4646188791	LGE	3	45 OTH	SP	P	ED,ID,SRS	TD		10/22/2102
2020 PO4666389181	LGE	4	40 KOP	SP	S		V		10/23/2102
2020 PO4662989159	LGE	4	35 KOP	SP	CRE	HH,ID,MD,RB	X	PX	10/24/2102
2020 PO4661889150	LGE	4	40 KOP	SP	S		V		10/25/2102
2020 PO4665388754	LGE	3	45 OTH	SP	CCA		V		10/26/2102
2020 PO4666288741	LGE	3	45 OTH	SP	CCA		V		10/27/2102
2020 PO4654988658	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD		10/28/2102
2020 PO4653388682	LGE	4	40 OTH	SP	CCA		V		10/29/2102
2020 PO4656288650	LGE	4	30 OTH	SP	CRE	ED,ID,SRS	TD		10/30/2102
2020 PO4653188696	LGE	4	30 OTH	SP	CRE	ED,ID,RB	X	PX	10/31/2102
2020 PO4654788673	LGE	4	30 OTH	SP	CRE	ED,ID,SRS	TD		11/1/2102
2020 PO4653988685	LGE	4	30 OTH	SP	CCA	ED,SRS	TD		11/2/2102
2020 PO4655788647	LGE	3	45 OTH	SP	CCA		V		11/3/2102
2020 PO4654188670	LGE	4	40 OTH	SP	CCA	ED,SRS	TD		11/4/2102
2020 PO4652688693	LGE	4	40 OTH	SP	CCA		V		11/5/2102
2020 PO4655488662	LGE	4	30 OTH	SP	CRE	ED,ID,SRS	TD		11/6/2102
2020 PO4682789335	LGE	4	35 XXX	SP	CRE	ID	BD		11/7/2102
2020 PO4682589346	LGE	4	40 BRN	SP	CCA		V		11/8/2102
2020 PO4682289350	LGE	4	40 XXX	SP	A	ED,ID	TD		11/9/2102
2020 PO4789887763	LGE	1	20 XXX	SP	A		V		11/10/2102
2020 PO4660888989	LGE	4	40 KOP	SP	CRE	ID,IP	BD		11/11/2102
2020 PO4660189006	LGE	4	40 KOP	SP	CRE	ED,ID,IP	TD		11/12/2102
2020 PO4676589139	LGE	UNK	45 OTH	UN	P		V		11/13/2102
2020 PO4680189254	LGE	4	40 OTH	SP	P	ED,ID,SRS	TD		11/14/2102
2020 PO4678589257	LGE	4	40 OTH	SP	P	ED,ID,SRS	TD		11/15/2102
2020 PO4679389256	LGE	4	40 OTH	SP	P	ED,ID,SRS	TD		11/16/2102
2020 PO4675789258	LGE	4	40 OTH	SP	CRE	ID	BD		11/17/2102
2020 PO4677289258	LGE	4	40 OTH	SP	P	ED,ID,SRS	TD		11/18/2102
2020 PO4666389043	LGE	4	40 KOP	SP	P	ED,ID	TD		11/19/2102
2020 PO4669289064	LGE	4	40 KOP	SP	P	ED,ID,IP	TD		11/20/2102
2020 PO4673889245	LGE	4	35 OTH	SP	CRE	ED,ID,SRS	TD		11/21/2102
2020 PO4674289235	LGE	4	35 OTH	SP	CRE	ED,ID,SRS	TD		11/22/2102
2020 PO4674589252	LGE	4	40 OTH	SP	P	ED,ID,SRS	TD		11/23/2102
2020 PO4673189218	LGE	3	45 OTH	SP	CCA		V		11/24/2102
2020 PO4674789201	LGE	4	35 OTH	SP	CRE	ID	TD		11/25/2102
2020 PO4672989210	LGE	4	35 OTH	SP	CRE	ID	BD		11/26/2102

2020 PO4673189228	LGE	4	35 OTH	SP	CRE	ED,ID,SRS	TD	11/27/2102
2020 PO4673089240	LGE	4	35 OTH	SP	CRE	ED,ID,SRS	TD	11/28/2102
2020 PO4668189098	LGE	7	25 KOP	SP	CRE	ED,ID,IP	TD	11/29/2102
2020 PO4668589093	LGE	4	35 KOP	SP	CRE	ED,ID	TD	11/30/2102
2020 PO4668389092	LGE	4	40 KOP	SP	P	ID	BD	12/1/2102
2020 PO4680989251	LGE	4	40 XXX	SP	A	ID	BD	12/2/2102
2020 PO4645588920	LGE	4	40 OTH	SP	P	ED,ID,SRS	TD	12/3/2102
2020 PO4667589086	LGE	4	40 KOP	SP	S		V	12/4/2102
2020 PO4667089081	LGE	3	45 KOP	SP	P	ED,ID,IP	TD	12/5/2102
2020 PO4666589087	LGE	4	30 KOP	SP	CRE	ED,ID	TD	12/6/2102
2020 PO4680989259	LGE	4	35 XXX	SP	A	ID	BD	12/7/2102
2020 PO4644388911	LGE	3	45 OTH	SP	CCA		V	12/8/2102
2020 PO4643188902	LGE	3	45 OTH	SP	CRE	ID	BD	12/9/2102
2020 PO4645788911	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	12/10/2102
2020 PO4649588940	LGE	4	40 OTH	SP	P	ED,ID,SRS	TD	12/11/2102
2020 PO4643388893	LGE	3	45 OTH	SP	CRE	ED,ID,SRS	TD	12/12/2102
2020 PO4646988920	LGE	4	40 OTH	SP	P	ED,ID,SRS	TD	12/13/2102
2020 PO4644688903	LGE	4	40 OTH	SP	CRE	RB	X	PX 12/14/2102
2020 PO4647988929	LGE	4	40 OTH	SP	CCA		V	12/15/2102
2020 PO4642088884	LGE	4	40 OTH	SP	P	ED,ID,SRS	TD	12/16/2102
2020 PO4636488802	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	12/17/2102
2020 PO4680989241	LGE	4	40 XXX	SP	A	ID	BD	12/18/2102
2020 PO4680289221	LGE	5	30 XXX	SP	A	ID	BD	12/19/2102
2020 PO4664989075	LGE	5	25 KOP	SP	S		V	12/20/2102
2020 PO4665489070	LGE	4	40 KOP	SP	CRE	ED,ID	TD	12/21/2102
2020 PO4678289220	LGE	4	40 XXX	SP	A	ID	BD	12/22/2102
2020 PO4679289220	LGE	4	40 XXX	SP	A	ID	BD	12/23/2102
2020 PO4679889216	LGE	4	40 XXX	SP	A	ID	BD	12/24/2102
2020 PO4640188794	LGE	3	45 OTH	SP	CCA		V	12/25/2102
2020 PO4636288791	LGE	4	30 OTH	SP	CRE	ED,ID,SR	TD	12/26/2102
2020 PO4663389063	LGE	7	25 KOP	SP	CRE	ED,ID	TD	12/27/2102
2020 PO4663889058	LGE	4	40 KOP	SP	P	ED,ID	TD	12/28/2102
2020 PO4662289045	LGE	4	35 KOP	SP	CRE	ED,ID	BD	12/29/2102
2020 PO4661789051	LGE	4	25 KOP	SP	S	ED	T	12/30/2102
2020 PO4660189040	LGE	UNK	25 KOP	SP	CRE	ED,ID	BD	12/31/2102
2020 PO4634688807	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	1/1/2103
2020 PO4635988787	LGE	3	45 OTH	SP	CCA		V	1/2/2103
2020 PO4637788760	LGE	3	45 OTH	SP	CCA		V	1/3/2103
2020 PO4636988773	LGE	3	45 OTH	SP	CCA		V	1/4/2103
2020 PO4677389202	LGE	4	40 XXX	SP	CRE	ID	BD	1/5/2103
2020 PO4677989188	LGE	4	40 XXX	SP	CRE	ID	BD	1/6/2103
2020 PO4639288804	LGE	4	30 OTH	SP	CRE	ED,ID,SRS	TD	1/7/2103
2020 PO4640588821	LGE	3	45 OTH	SP	CCA		V	1/8/2103
2020 PO4640988781	LGE	3	45 OTH	SP	CCA		V	1/9/2103
2020 PO4640288804	LGE	3	45 OTH	SP	CCA		V	1/10/2103
2020 PO4640488813	LGE	4	40 OTH	SP	CCA		V	1/11/2103
2020 PO4633288839	LGE	3	45 OTH	SP	CCA		V	1/12/2103

2020 PO4639588816	LGE	4	30 OTH	SP	CRE	ID	BD	1/13/2103
2020 PO4639888825	LGE	4	30 OTH	SP	CRE	ED,ID,SRS	TD	1/14/2103
2020 PO4640788833	F	4	35 OTH	SP	CCA		V	1/15/2103
2020 PO4677189185	LGE	5	30 XXX	SP	A	ID	BD	1/16/2103
2020 PO4339287966	LGE	2	60 ACW	SP	S		V	1/17/2103
2020 PO4326687987	LGE	4	35 ACW	SP	CCA		V	1/18/2103
2020 PO4325787984	LGE	4	35 ACW	SP	CCA		V	1/19/2103
2020 PO4325587988	LGE	3	55 ACW	SP	A	ED,ID	BD	1/20/2103
2020 PO4325587991	LGE	2	55 ACW	SP	CRE	ED,ID,IP,MD	BD	1/21/2103
2020 PO4325687995	LGE	1	55 ACW	SP	CRE	ED,ID	BD	1/22/2103
2020 PO4325588003	LGE	2	55 ACW	SP	CRE	ED,ID,IP,MD,RB	BX PX	1/23/2103
2020 PO4325688011	LGE	3	45 ACW	SP	CRE	ED,HH,ID,MD,RB	BX PX	1/24/2103
2020 PO4325187920	F	4	40 ACW	SP	CCA		V	1/25/2103
2020 PO4330587975	F	4	40 ACW	SP	CCA		V	1/26/2103
2020 PO4328387948	LGE	4	40 ACW	SP	CCA		V	1/27/2103
2020 PO4327287935	LGE	2	55 ACW	SP	S		V	1/28/2103
2020 PO4326487927	LGE	4	40 ACW	SP	CRE		V	1/29/2103
2020 PO4326987940	LGE	5	45 ACW	SP	P	ED,ID	BD	1/30/2103
2020 PO4327087940	F	4	40 ACW	SP	CRE		V	1/31/2103
2020 PO4324687923	LGE	4	40 ACW	SP	CRE	ED,ID	BD	2/1/2103
2020 PO4324787926	LGE	2	50 ACW	SP	CRE	ED,ID	BD	2/2/2103
2020 PO4293388262	LGE	4	35 ACW	SP	CCA		V	2/3/2103
2020 PO4299088225	LGE	4	40 ACW	SP	CCA		V	2/4/2103
2020 PO4298088182	F	4	35 ACW	SP	CCA		V	2/5/2103
2020 PO4298488175	F	4	40 ACW	SP	CCA		V	2/6/2103
2020 PO0474597400	LGE	4	40 ACW	SP	CCA		V	2/7/2103
2020 PO0502191223	LGE	5	50 ACW	SP	CCA		V	2/8/2103
2020 PO4326388063	LGE	4	40 ACW	SP	CRE		V	2/9/2103
2020 PO4321488058	LGE	5	55 ACW	SP	CRE		V	2/10/2103
2020 PO4317688056	LGE	4	45 ACW	SP	CRE	ED,ID	BD	2/11/2103
2020 PO4315888010	LGE	4	45 ACW	SP	P	ID	BD	2/12/2103
2020 PO4313788007	LGE	4	40 ACW	SP	CRE	ID	BD	2/13/2103
2020 PO4313788004	LGE	4	45 ACW	SP	P	ED,ID	BD	2/14/2103
2020 PO4295888015	LGE	3	55 ACW	SP	CRE		V	2/15/2103
2020 PO4300888085	LGE	3	50 ACW	SP	S		V	2/16/2103
2020 PO4298988087	LGE	2	50 ACW	SP	S		V	2/17/2103
2020 PO0083192782	LGE	2	55 ACW	SP	S		V	2/18/2103
2020 PO4297088073	LGE	4	40 ACW	SP	CCA		V	2/19/2103
2020 PO0136793362	LGE	4	35 ACW	SP	S		V	2/20/2103
2020 PO4293688157	F	4	40 ACW	SP	CCA		V	2/21/2103
2020 PO4294188166	LGE	4	40 ACW	SP	CRE	ED,ID	BD	2/22/2103
2020 PO0055293760	LGE	3	45 ACW	SP	S		V	2/23/2103
2020 PO4294788166	LGE	4	30 ACW	SP	CCA		V	2/24/2103
2020 PO4295588165	LGE	4	40 ACW	SP	P	ID	BD	2/25/2103
2020 PO4296888164	LGE	3	45 ACW	SP	S		V	2/26/2103
2020 PO4871886610	LGE	1	50 OTH	SP	CCA		V	2/27/2103
2020 PO4672489197	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	2/28/2103

2020 PO4831786584	LGE	4	35 XXX	SP	P	ID	BD	3/1/2103
2020 PO4829886561	F	3	50 XXX	SP	CRE		V	3/2/2103
2020 PO4830186545	F	4	45 XXX	SP	CRE		V	3/3/2103
2020 PO4831286538	LGE	4	40 XXX	SP	CRE	ID	BD	3/4/2103
2020 PO4832786541	LGE	3	45 XXX	SP	CCA		V	3/5/2103
2020 PO4833286543	LGE	4	40 XXX	SP	CRE	ID	BD	3/6/2103
2020 PO5448878637	LGE	3	45 XXX	SP	CCA		V	3/7/2103
2020 PO4831086511	F	3	45 XXX	SP	CCA		V	3/8/2103
2020 PO4830986497	F	4	30 XXX	SP	P	ED	V	3/9/2103
2020 PO4881287390	LGE	4	40 XXX	SP	A	ED,ID	TD	3/10/2103
2020 PO4883587397	LGE	5	40 XXX	SP	A	ID	BD	3/11/2103
2020 PO4884787401	LGE	5	40 XXX	SP	A	ID	BD	3/12/2103
2020 PO4871686616	LGE	4	30 OTH	SP	P	ED,ID,SRS	TD	3/13/2103
2020 PO4871786613	F	4	30 OTH	SP	P		V	3/14/2103
2020 PO5838579156	LGE	1	55 OTH	SP	CCA		V	3/15/2103
2020 PO4870286612	LGE	4	30 OTH	SP	CRE	ED,SRS	TD	3/16/2103
2020 PO4671689168	LGE	4	35 BRO	SP	CCA		V	3/17/2103
2020 PO4759787879	LGE	UNK	70 BRO	SP	CRE		V	3/18/2103
2020 PO4671888180	LGE	3	45 BRO	SP	CCA		V	3/19/2103
2020 PO4902587198	LGE	4	40 OTH	SP	CRE	ED,HH,ID,RB	X	RP2 3/20/2103
2020 PO4902187214	LGE	4	40 OTH	SP	CCA		V	3/21/2103
2020 PO4902787194	LGE	4E	40E OTH	SP	CRE	ED,ID,SRS	TD	3/22/2103
2020 PO4902987187	LGE	3	45 OTH	SP	CCA		V	3/23/2103
2020 PO4903087184	LGE	3	45 OTH	SP	CCA		V	3/24/2103
2020 PO4842086526	LGE	3	30 XXX	ST	CCA		V	3/25/2103
2020 PO5546178323	LGE	4	35 XXX	SP	CCA		V	3/26/2103
2020 PO4653788952	LGE	4	40 BRO	SP	CRE	ED	TD	3/27/2103
2020 PO4802587936	LGE	4	40 BRN	SP	CRE	ED,ID	BD	3/28/2103
2020 PO4801687943	LGE	4	30 BRN	SP	A	ED,ID	BD	3/29/2103
2020 PO4802287948	LGE	4	40 BRN	SP	CRE	ED,ID,IP	BD	3/30/2103
2020 PO4803387968	LGE	4	30 BRN	SP	CRE	ED,HH,ID	BX	PX 3/31/2103
2020 PO4800787961	LGE	4	40 BRN	SP	CRE	ED,HH,ID	BX	RR 4/1/2103
2020 PO4801687942	LGE	4	30 BRN	SP	CCA		V	4/2/2103
2020 PO4799487960	LGE	3	30 BRN	SP	CRE		V	4/3/2103
2020 PO4778587897	LGE	3	45 BRO	SP	CCA		V	4/4/2103
2020 PO4778087906	LGE	UNK	45 BRO	SP	CRE	ED	BD	4/5/2103
2020 PO4809687494	LGE	4	40 BRN	SP	CRE	ED,ID	BD	4/6/2103
2020 PO4810787499	LGE	4	40 BRN	SP	CRE	ED,ID	BD	4/7/2103
2020 PO4861686805	LGE	3	45 XXX	SP	CRE	ED,ID	TD	4/8/2103
2020 PO4862986807	LGE	3	45 XXX	SP	CRE	ED,ID	TD	4/9/2103
2020 PO4846886892	LGE	1	20 XXX	SP	A		V	4/10/2103
2020 PO4954386830	LGE	4	40 OTH	SP	P	ED,ID,IP,SRC	TX	RR 4/11/2103
2020 PO4951386840	LGE	4	35 OTH	SP	P	ED,ID,IP,SRS	TD	4/12/2103
2020 PO4948586851	LGE	4	45 OTH	SP	CRE	ED,ID,SRS	TD	4/13/2103
2020 PO4835886700	F	4	40 XXX	SP	P		V	4/14/2103
2020 PO4832586738	LGE	4	40 XXX	SP	P	ID	BD	4/15/2103
2020 PO4834186724	LGE	4	40 XXX	SP	CRE	HH,ID	X	RP3 4/16/2103

2020 PO4835686711	LGE	4	40 XXX	SP	P	ID	TD	4/17/2103	
2020 PO4836286707	F	3	45 XXX	SP	A		V	4/18/2103	
2020 PO4835686696	LGE	3	45 XXX	SP	P	ID	TD	4/19/2103	
2020 PO4839486659	LGE	4	35 XXX	SP	A	ID	BD	4/20/2103	
2020 PO4839386647	F	3	45 XXX	SP	P		V	4/21/2103	
2020 PO4838486659	F	4	40 XXX	SP	A		V	4/22/2103	
2020 PO4837286674	F	4	35 XXX	SP	CCA		V	4/23/2103	
2020 PO4837486676	F	4	40 XXX	SP	P		V	4/24/2103	
2020 PO4836786686	F	4	40 XXX	SP	A		V	4/25/2103	
2020 PO4836086696	F	4	40 XXX	SP	P		V	4/26/2103	
2020 PO4838186688	LGE	3	50 XXX	SP	P	ID	TD	4/27/2103	
2020 PO4839986687	LGE	3	50 XXX	SP	P	ID	TD	4/28/2103	
2020 PO4841586696	LGE	3	50 XXX	SP	P	ID	TD	4/29/2103	
2020 PO4841586700	LGE	4	30 XXX	SP	P	ED,ID	TD	4/30/2103	
2020 PO4844886637	LGE	3	45 XXX	SP	P	ID	TD	5/1/2103	
2020 PO4844386657	LGE	3	45 XXX	SP	P	ID	TD	5/2/2103	
2020 PO4843486694	LGE	3	50 XXX	SP	P	ID	BD	5/3/2103	
2020 PO4845786695	LGE	2	50 XXX	SP	P	ID	BD	5/4/2103	
2020 PO4847586695	LGE	2	50 XXX	SP	P	ID	BD	5/5/2103	
2020 PO4849186697	LGE	2	50 XXX	SP	P	ID	BD	5/6/2103	
2020 PO4849286700	LGE	3	30 XXX	SP	P		V	5/7/2103	
2020 PO4856886779	LGE	4	45 XXX	SP	A	ID	BD	5/8/2103	
2020 PO4856886778	LGE	3	45 XXX	SP	A	ED,ID	TD	5/9/2103	
2020 PO4943086865	LGE	4	40 OTH	SP	CRE	ED,HH,ID,SRS	TD	5/10/2103	
2020 PO4941186860	LGE	4	35 OTH	SP	P	ED,EP,ID,SRS	TX	RR	5/11/2103
2020 PO4940886870	LGE	4	40 OTH	SP	P	ED,ID,SRS	TD	5/12/2103	
2020 PO4855486782	LGE	3	45 XXX	SP	A	ED,ID	TD	5/13/2103	
2020 PO4939786874	LGE	5	35 OTH	SP	CRE	ED,ID,IP,SRS	TD	5/14/2103	
2020 PO4822687602	LGE	UNK	45 BRO	SP	CRE	ED	TD	5/15/2103	
2020 PO4677188907	LGE	4	40 BRO	SP	CRE	ID,IP	BD	5/16/2103	
2020 PO4680588911	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	5/17/2103	
2020 PO4680788893	LGE	4	30 BRO	SP	P		TD	5/18/2103	
2020 PO4682388886	LGE	4	40 BRO	SP	CRE	ED,ID	TD	5/19/2103	
2020 PO5481076111	LGE	1	50 XXX	SP	CCA		V	5/20/2103	
2020 PO4835886316	LGE	4	45 XXX	SP	A	ID	TD	5/21/2103	
2020 PO4836486316	LGE	4	40 XXX	SP	A	ID	BD	5/22/2103	
2020 PO4838386320	LGE	4	45 XXX	SP	CRE	ID	TD	5/23/2103	
2020 PO4829986325	LGE	4	45 XXX	SP	A	ID	TD	5/24/2103	
2020 PO4829986325	LGE	4	45 XXX	SP	A	ED,ID	X	RP3	5/25/2103
2020 PO4736188143	LGE	4	30 BRO	SP	A	ED,ID	BD	5/26/2103	
2020 PO4798788193	LGE	4	30 BRN	SP	CRE	ED,ID	BD	5/27/2103	
2020 PO4824887510	LGE	4	40 BRO	SP	CRE	ED	TD	5/28/2103	
2020 PO4824487546	LGE	1	50 BRO	SP	CCA		V	5/29/2103	
2020 PO4824987531	LGE	1	50 BRO	SP	CCA		V	5/30/2103	
2020 PO4825387518	LGE	1	50 BRO	SP	CCA		V	5/31/2103	
2020 PO4825687510	LGE	1	50 BRO	SP	CCA		V	6/1/2103	
2020 PO4825887501	LGE	1	50 BRO	SP	CCA	ED	V	6/2/2103	

2020 PO4826387486	LGE	1	50 BRO	SP	CCA		V	6/3/2103
2020 PO4826887472	LGE	1	50 BRO	SP	CCA		V	6/4/2103
2020 PO4827387457	LGE	1	50 BRO	SP	CCA		V	6/5/2103
2020 PO4827887442	LGE	1	50 BRO	SP	CCA		V	6/6/2103
2020 PO4828287427	LGE	1	50 BRO	SP	CCA		V	6/7/2103
2020 PO4798288178	LGE	4	30 BRN	SP	CRE	ED,ID	BD	6/8/2103
2020 PO4797988167	LGE	4	30 BRN	SP	CRE	ED,ID	BX PX	6/9/2103
2020 PO4798088154	LGE	4	30 BRN	SP	CRE	ED,ID	BD	6/10/2103
2020 PO4879186287	LGE	4	40 OTH	SP	P	ED,ID,SRS	TD	6/11/2103
2020 PO4880486291	LGE	4	40 OTH	SP	P	ED,ID,SRS	TD	6/12/2103
2020 PO4878386271	LGE	3	45 OTH	SP	P	ID	TD	6/13/2103
2020 PO4812487504	LGE	4	40 BRN	SP	CCA		V	6/14/2103
2020 PO4814187510	LGE	1	50 BRN	SP	CCA		V	6/15/2103
2020 PO4815887508	LGE	4	40 BRN	SP	CRE	ED,ID	BD	6/16/2103
2020 PO4817487508	LGE	4	45 BRN	SP	CCA		V	6/17/2103
2020 PO4777987922	LGE	4	35 BRO	SP	CRE	ED	TD	6/18/2103
2020 PO4898787144	LGE	4	30 OTH	SP	CCA		V	6/19/2103
2020 PO4823087505	LGE	4	40 BRN	SP	CRE	ED,ID	BD	6/20/2103
2020 PO4821087507	LGE	4	40 BRN	SP	CRE	ED,ID	BD	6/21/2103
2020 PO4819287507	LGE	4	40 BRN	SP	CRE	ED,ID	BD	6/22/2103
2020 PO4777487921	LGE	UNK	45 BRO	SP	CRE	ED	TD	6/23/2103
2020 PO4780287915	LGE	4	35 BRO	SP	CRE	ED	TD	6/24/2103
2020 PO4655788924	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/25/2103
2020 PO4646488932	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/26/2103
2020 PV4884286651	LGE	4	35 OTH	SP	P	ED,ID,SRS	TD	6/27/2103
2020 PO5971279760	LGE	4	40 OTH	SP	CCA	ED,SRS	TD	6/28/2103
2020 PO4876087009	LGE	2	50 OTH	SP	CCA		V	6/29/2103
2020 PO4684888735	LGE	4	40 BRO	SP	CCA		V	6/30/2103
2020 PO4873487762	LGE	4	30 XXX	SP	CCA		V	7/1/2103
2020 PO4869487757	LGE	4	40 XXX	SP	CCA		V	7/2/2103
2020 PO4869387756	F	6	35 XXX	SP	A		V	7/3/2103
2020 PO4870887760	F	6	30 XXX	SP	A		V	7/4/2103
2020 PO4872287765	F	4	45 XXX	SP	A		V	7/5/2103
2020 PO4872987767	F	4	35 XXX	SP	CRE		V	7/6/2103
2020 PO4876986986	LGE	4	35 OTH	SP	P	ID	BD	7/7/2103
2020 PO4876686986	LGE	1	55 OTH	SP	CCA		V	7/8/2103
2020 PO4788687503	LGE	4	40 BRN	SP	CCA		V	7/9/2103
2020 PO4791587507	LGE	4	40 BRN	SP	CRE	ED,ID	BD	7/10/2103
2020 PO4882886687	LGE	3	50 OTH	SP	P	ID	BD	7/11/2103
2020 PO4884086685	LGE	3	50 OTH	SP	CCA		V	7/12/2103
2020 PV4883886678	LGE	5	35 OTH	SP	P	ED,SRS	TD	7/13/2103
2020 PO4883486682	LGE	3	50 OTH	SP	P	ID	BD	7/14/2103
2020 PO4881186701	LGE	1	45 OTH	UN	A		V	7/15/2103
2020 PO4780188008	LGE	4	40 BRO	SP	CRE	ED	BD	7/16/2103
2020 PO4793087502	LGE	4	40 BRN	SP	CRE	ED,ID	BD	7/17/2103
2020 PO4792987509	LGE	4	40 BRN	SP	CCA	ED,ID	BD	7/18/2103
2020 PO5890482755	LGE	3	50 OTH	SP	CCA		V	7/19/2103

2020 PO4877086959	LGE	3	50 OTH	SP	P	ID	BD		7/20/2103
2020 PO4775087987	LGE	4	40 BRO	SP	CCA	ED	BD		7/21/2103
2020 PO4775587991	LGE	4	40 BRO	SP	CRE	ED,HH,IP,RB	X	PX	7/22/2103
2020 PO4796687508	LGE	4	35 BRN	SP	CRE	ED,ID	BD		7/23/2103
2020 PO4794887508	LGE	4	40 BRN	SP	CCA		V		7/24/2103
2020 PO4878186945	LGE	4	35 OTH	SP	P	ED,ID,SRC	X	RR	7/25/2103
2020 PO4878086930	LGE	4	40 OTH	SP	CCA		V		7/26/2103
2020 PO4877286939	LGE	1	60 OTH	SP	CCA		V		7/27/2103
2020 PO4882086717	F	3	45 OTH	SP	P		V		7/28/2103
2020 PO4882286704	LGE	3	45 OTH	SP	P	ED,SRS	TD		7/29/2103
2020 PO4881186725	LGE	3	45 OTH	SP	P	ID	BD		7/30/2103
2020 PO4882786706	F	3	45 OTH	SP	P		V		7/31/2103
2020 PO4798387507	LGE	4	35 BRN	SP	CCA	ED,ID	BD		8/1/2103
2020 PO4799787499	LGE	4	35 BRN	SP	CRE	ED,ID	BD		8/2/2103
2020 PO4842086505	LGE	3	45 XXX	SP	P	ID	BD		8/3/2103
2020 PO4842486507	LGE	2	50 XXX	SP	P	ID	BD		8/4/2103
2020 PO4842986493	LGE	3	50 XXX	SP	P	ID	TD		8/5/2103
2020 PO4734788066	F	4	35 BRO	SP	CRE		V		8/6/2103
2020 PO4873787789	F	5	25 XXX	SP	A		V		8/7/2103
2020 PO4874087789	F	4	40 XXX	SP	A		V		8/8/2103
2020 PO4875787775	LGE	4	45 XXX	SP	CRE	ID	BD		8/9/2103
2020 PO4875087045A	LGE	3	45 OTH	SP	P	ID	BD		8/10/2103
2020 PO4875087045	LGE	H2	50 OTH	SP	CCA		V		8/11/2103
2020 PO4874287071	LGE	3	45 OTH	SP	P	ID	BD		8/12/2103
2020 PO4874886759	F	3	45 OTH	SP	P	MD	V		8/13/2103
2020 PO4874586750	F	3	50 OTH	SP	P		V		8/14/2103
2020 PO4873586784	F	3	50 OTH	SP	P		V		8/15/2103
2020 PO4875086751	F	4	30 OTH	SP	P		V		8/16/2103
2020 PO4874586752	F	3	50 OTH	SP	P		V		8/17/2103
2020 PO5860481037	LGE	1	50 OTH	SP	CCA		V		8/18/2103
2020 PO4874086767	F	3	50 OTH	SP	P		V		8/19/2103
2020 PO4874286748	LGE	4	35 OTH	SP	P	ED,SRS	TD		8/20/2103
2020 PO4776987934	LGE	4	40 BRO	SP	CRE	ED	TD		8/21/2103
2020 PO4807087506	LGE	3	45 BRN	SP	CCA		V		8/22/2103
2020 PO4807287495	LGE	4	40 BRN	SP	A	ED,ID	TD		8/23/2103
2020 PO4875587799	LGE	5	35 XXX	SP	CRE	ED,ID	TD		8/24/2103
2020 PO4873887085	LGE	3	45 OTH	SP	CCA		V		8/25/2103
2020 PO4873487100	LGE	3	45 OTH	SP	P	ID	BD		8/26/2103
2020 PO4845486421	LGE	2	55 XXX	SP	CCA		V		8/27/2103
2020 PO4845286421	LGE	2	55 XXX	SP	P	ID	BD		8/28/2103
2020 PO4776287953	LGE	4	40 BRO	SP	CRE	ED	TD		8/29/2103
2020 PO4775687970	LGE	4	40 BRO	SP	CRE	ED	BD		8/30/2103
2020 PO4872487096	LGE	1	20 OTH	AL	CCA		V		8/31/2103
2020 PO4873087110	LGE	4	35 OTH	SP	CCA		V		9/1/2103
2020 PO4873187099	LGE	4	45 OTH	SP	CCA		V		9/2/2103
2020 PO4871786803	LGE	3	55 OTH	SP	P	ID	BD		9/3/2103
2020 PO4876086801	LGE	3	55 OTH	SP	P	ED,ID,SRS	TD		9/4/2103

2020 PO4877986800	LGE	2	60 OTH	SP	CCA	ED,SRS	TD	9/5/2103	
2020 PO4876886801	LGE	2	55 OTH	SP	P	ED,ID,SRS	TD	9/6/2103	
2020 PO4873386803	LGE	2	55 OTH	SP	P	ED,ID,SRS	TD	9/7/2103	
2020 PO4873486810	LGE	1	55 OTH	SP	CCA		V	9/8/2103	
2020 PO4806887477	LGE	4	40 BRN	SP	A	ED,HH,ID	BX	RR	9/9/2103
2020 PO4635788919	LGE	4	35 BRO	SP	A	ED	TD	9/10/2103	
2020 PO4844486443	LGE	3	50 XXX	SP	A	ED,ID	TD	9/11/2103	
2020 PO4805587480	LGE	4	35 BRN	SP	A	ED,ID	BD	9/12/2103	
2020 PO4748888047	F	4	30 BRO	SP	CRE	ED,EP,ID	VX	RP2	9/13/2103
2020 PO4638888960	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TX	RR	9/14/2103
2020 PO4875787103	LGE	6	25 OTH	SP	CRE	ED,ID,SRS	TD	9/15/2103	
2020 PO4843986461	LGE	3	50 XXX	SP	A	ID	BD	9/16/2103	
2020 PO4843386480	LGE	3	50 XXX	SP	P	ID	BD	9/17/2103	
2020 PO4841386472	LGE	2	50 XXX	SP	P	ID	BD	9/18/2103	
2020 PO4839286465	LGE	3	50 XXX	SP	CCA		V	9/19/2103	
2020 PO4781788014	LGE	UNK	45 BRO	SP	CRE	ED	BD	9/20/2103	
2020 PO4783588021	F	3	45 BRO	SP	CCA		V	9/21/2103	
2020 PO4784388015	F	4	35 BRO	SP	CRE		V	9/22/2103	
2020 PO4785387934	LGE	3	45 BRO	SP	CCA		V	9/23/2103	
2020 PO4807187521	LGE	4	35 BRN	SP	A	ED,ID	BD	9/24/2103	
2020 PO4875787106	LGE	3	45 OTH	SP	CCA		V	9/25/2103	
2020 PO4878387114	LGE	3	45 OTH	SP	CCA		V	9/26/2103	
2020 PO4807587526	LGE	4	35 BRN	SP	CCA		V	9/27/2103	
2020 PO4807587541	LGE	4	35 BRN	SP	A	HH,ID	BD	9/28/2103	
2020 PO4807487551	LGE	4	35 BRN	SP	A	ED,ID	BD	9/29/2103	
2020 PO4807287562	LGE	4	35 BRN	SP	CRE	ED,ID	BD	9/30/2103	
2020 PO4876087776	LGE	3	45 XXX	SP	CCA		V	10/1/2103	
2020 PO4876687778	LGE	1	50 XXX	SP	CCA		V	10/2/2103	
2020 PO4876887750	F	4	40 XXX	SP	A		V	10/3/2103	
2020 PO4876087748	F	4	40 XXX	SP	A		V	10/4/2103	
2020 PO4881487130	LGE	1	25 OTH	ST	S		V	10/5/2103	
2020 PO5926484293	LGE	3	45 OTH	SP	P	ID	BD	10/6/2103	
2020 PO4880687120	LGE	3	45 OTH	SP	P	ID	BD	10/7/2103	
2020 PO4641388953	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	10/8/2103	
2020 PO4869886780	LGE	3	45 OTH	SP	P	ED,SRS	TD	10/9/2103	
2020 PO4867086809	LGE	3	50 OTH	SP	P	ED,ID,SRS	TD	10/10/2103	
2020 PO4867186802	LGE	4	30 OTH	SP	P	ED,ID,SRS	TD	10/11/2103	
2020 PO4869786810	LGE	2	55 OTH	SP	P	ED,ID	BD	10/12/2103	
2020 PO4868286810	LGE	3	50 OTH	SP	P	ED,ID	BD	10/13/2103	
2020 PO4837286458	LGE	3	50 XXX	SP	P	ID	BD	10/14/2103	
2020 PO4835786454	LGE	3	45 XXX	SP	P	ED,ID	TD	10/15/2103	
2020 PO4644788985	LGE	4	35 BRO	SP	CRE	ID,IP	BD	10/16/2103	
2020 PO4752087908	F	3	45 BRO	SP	CCA		V	10/17/2103	
2020 PO4754187906	F	4	40 BRO	SP	CCA		V	10/18/2103	
2020 PO4753987930	LGE	UNK	25 BRO	SP	CRE		V	10/19/2103	
2020 PO4646488953	LGE	4	35 BRO	SP	A	ED,ID,IP	TD	10/20/2103	
2020 PO4882387146	LGE	3	45 OTH	SP	P	ID,IP	BD	10/21/2103	

2020 PO4882887128	LGE	2	55	OTH	SP	P		V	10/22/2103
2020 4877187685a	F	5	35	XXX	SP	A		V	10/23/2103
2020 PO4878187667	F	4	35	XXX	SP	A		V	10/24/2103
2020 PO4877787679	F	3	45	BRN	SP	CCA		V	10/25/2103
2020 PO4877687694	LGE	4	35	XXX	SP	A	ED,ID	TD	10/26/2103
2020 PO4878187706	LGE	4	35	XXX	SP	A	ED,ID	TD	10/27/2103
2020 PO4884887145	LGE	4	30	OTH	SP	CRE	ED,HH,ID,RB	BX PX	10/28/2103
2020 PO4885387135	LGE	3E	45E	OTH	SP	P	ID	BD	10/29/2103
2020 PO4654388944	LGE	4	40	BRO	SP	CRE	ED,ID,IP	TD	10/30/2103
2020 PO48643886744	LGE	4	40	OTH	SP	P	ED,ID,SRC	TX RR	10/31/2103
2020 PO4868986777	LGE	3	45	OTH	SP	P	ED,SRS	TD	11/1/2103
2020 PO4871186775	F	1	50	OTH	SP	CCA		V	11/2/2103
2020 PO4870786792	F	3	45	OTH	SP	P		V	11/3/2103
2020 PO4870786791	LGE	3	45	OTH	SP	CCA		V	11/4/2103
2020 PO4871286773	F	2	55	OTH	SP	CCA		V	11/5/2103
2020 PO4807287723	LGE	4	40	BRN	SP	CRE		V	11/6/2103
2020 PO4296888163	F	4	35	ACW	SP	CCA		V	11/7/2103
2020 PO4695088483	LGE	4	40	BRN	SP	CCA		V	11/8/2103
2020 PO4695388485	LGE	4	30	BRN	SP	CCA		V	11/9/2103
2020 PO4694188495	LGE	4	25	BRN	SP	S		V	11/10/2103
2020 PO4840488130	LGE	4	35	BRO	SP	CRE	ED	TD	11/11/2103
2020 PO4841288133	LGE	4	40	BRO	SP	CRE	ED	TD	11/12/2103
2020 PO025877789	KU	4	45	XXX	SP	CRE	ED,ID	TD	11/13/2103
2020 PO4206687670	KU	6	30	KOP	SP	S		V	11/14/2103
2020 PO4199287402	KU	3	45	KOP	SP	S		V	11/15/2103
2020 PO4198187469	F	4	40	KOP	SP	P		V	11/16/2103
2020 PO4196687668	KU	4	40	KOP	SP	S		V	11/17/2103
2020 PO4196687803	KU	4	40	KOP	SP	S		V	11/18/2103
2020 PO4207087968	KU	4	40	KOP	SP	S		V	11/19/2103
2020 PO4201487266	KU	4	40	KOP	SP	S		V	11/20/2103
2020 PO4214387429	KU	4	40	KOP	SP	CRE	ED,ID	TD	11/21/2103
2020 PO4219687532	KU	4	40	KOP	DF	CRE	ED,ID	TD	11/22/2103
2020 PO4219387636	KU	4	40	KOP	SP	CRE	ED,ID,IP	TD	11/23/2103
2020 PO4693288454	LGE	4	35	BRN	SP	A	ED,HH,ID	BX PX	11/24/2103
2020 PO4693088462	LGE	4	40	BRN	SP	A	ED,ID	B	11/25/2103
2020 PO4692088459-A	LGE	4	30	BRN	SP	A	ED,ID	BD	11/26/2103
2020 PO4691688476	LGE	4	35	BRN	SP	CCA		V	11/27/2103
2020 PO0235877697	KU	4	45	XXX	SP	CCA		V	11/28/2103
2020 PO0219477587	KU	4	45	XXX	SP	CRE	ED,ID	TD	11/29/2103
2020 PO4842288138	LGE	4	40	BRO	SP	CRE	ID,IP,RB	TD	11/30/2103
2020 PO4842688156	LGE	4	40	BRO	SP	CRE	ED	BD	12/1/2103
2020 PO4844488183	LGE	UNK	25	BRO	SP	CRE	ED	B	12/2/2103
2020 PO4830287804	LGE	UNK	95	BRO	ST	P		V	12/3/2103
2020 PO8968770401	F	3E	50E	OTH	SP	CCA		V	12/4/2103
2020 PO8952970270	F	3E	50E	OTH	SP	CCA		V	12/5/2103
2020 PO8937170140	F	3	50E	OTH	SP	CCA		V	12/6/2103
2020 PO8922270011	F	2E	50E	OTH	SP	CCA		V	12/7/2103

2020 PO0197577470	KU	4	45 XXX	SP	CRE	ED,ID	TD	12/8/2103
2020 PO4692088459	LGE	4	40 BRN	SP	CCA		V	12/9/2103
2020 PO4691488455	LGE	4	40 BRN	SP	A	ED,ID	BD	12/10/2103
2020 PO0186277620	KU	4	40 XXX	SP	CCA		V	12/11/2103
2020 0177777354a	KU	4	40 XXX	SP	CRE	ED,ID	TD	12/12/2103
2020 PO8908869859	F	3	55 OTH	SP	CCA		V	12/13/2103
2020 PO8888169702	KU	4	40 OTH	AL	CCA		V	12/14/2103
2020 PO8891769694	F	3	45 OTH	SP	CCA		V	12/15/2103
2020 PO8830069187	F	3	45 OTH	SP	CCA		V	12/16/2103
2020 PO8830069187B	F	3	45 OTH	SP	CCA		V	12/17/2103
2020 PO8830069187A	F	3	45 OTH	SP	CCA		V	12/18/2103
2020 PO8877769622	KU	4	40 OTH	SP	CCA		V	12/19/2103
2020 PO4832987253	LGE	3	45 KOP	SP	S		V	12/20/2103
2020 PO4834087243	LGE	1	50 KOP	SP	S		V	12/21/2103
2020 PO4835487233	LGE	1	50 KOP	SP	S		V	12/22/2103
2020 PO4836787222	LGE	3	45 KOP	SP	S		V	12/23/2103
2020 PO4837387205	LGE	3	45 KOP	SP	S		V	12/24/2103
2020 PO4837887192	LGE	3	45 KOP	SP	S		V	12/25/2103
2020 PO4837787117	LGE	4	30 KOP	SP	CCA		V	12/26/2103
2020 PO4837687131	LGE	4	40 KOP	SP	CRE	ED,ID	TD	12/27/2103
2020 PO4838087125	LGE	5	30 KOP	SP	CRE	HH,ID,IP,RB	BX	12/28/2103
2020 PO4677188957	LGE	4	40 BRO	SP	CRE	ED,ID,IP,SRS	TD	12/29/2103
2020 PO4678188944	LGE	4	40 BRO	SP	CRE	ED,ID,IP,SRS	TD	12/30/2103
2020 PO4677488959	LGE	4	35 BRO	SP	CRE	ED,ID,IP,SRS	TD	12/31/2103
2020 PO9386173958	KU	6	30 XXX	SP	CRE		V	1/1/2104
2020 PO9625874740	KU	6	30 XXX	SP	CRE		V	1/2/2104
2020 PO9658374309	KU	6	30 XXX	SP	CCA		V	1/3/2104
2020 PO9663274309	KU	4	45 XXX	SP	CRE	ID	TD	1/4/2104
2020 PO9265172329	KU	6	30 XXX	SP	CCA		V	1/5/2104
2020 PO8330862872	KU	2	50 BRN	SP	CCA		V	1/6/2104
2020 PO8340062719	KU	2	50 BRN	SP	CCA		V	1/7/2104
2020 PO8352062620	KU	4	40 BRN	SP	CRE		V	1/8/2104
2020 PO8343162550	KU	4	40 BRN	SP	CRE		B	1/9/2104
2020 PO8293363760	KU	4	40 BRN	SP	CRE		V	1/10/2104
2020 PO8295463734	KU	4	40 BRN	AL	CCA		V	1/11/2104
2020 PO8310963543	KU	4	40 BRN	AL	CRE		V	1/12/2104
2020 PO8279063938	KU	3	45 BRN	SP	CCA		V	1/13/2104
2020 PO8301263657	KU	4	40 BRN	SP	CCA		V	1/14/2104
2020 PO8264564069	KU	3	45 BRN	SP	CCA		V	1/15/2104
2020 PO8196863702	KU	5	35 BRN	SP	CCA		V	1/16/2104
2020 PO9266572238	KU	4	40 XXX	SP	CRE	ID	TD	1/17/2104
2020 PO9267072066	KU	6	30 XXX	SP	CRE	ID	TD	1/18/2104
2020 PO9267671911	KU	4	40 XXX	SP	CRE	ED,ID	TX	1/19/2104
2020 PO9274271964	KU	4	40 XXX	SP	CCA		V	1/20/2104
2020 PO9071270186	KU	4	45 OTH	SP	CRE	ID	BD	1/21/2104
2020 PO9056270425	KU	4	45 OTH	SP	CRE	ID	BD	1/22/2104
2020 PO9070868582	KU	2	50 OTH	SP	CCA		V	1/23/2104

2020 PO9091368976	KU	4	45 OTH	SP	CRE	ID	BD	1/24/2104
2020 PO9122469358	KU	4	40 OTH	SP	CRE	ID	BD	1/25/2104
2020 PO9084669973	KU	4	40 OTH	SP	CRE	ID	BD	1/26/2104
2020 PO9097369767	KU	4	40 OTH	SP	CRE	ID	BD	1/27/2104
2020 PO9060768598	KU	4	45 OTH	SP	CRE	ID	BD	1/28/2104
2020 PO9110069565	KU	4	40 OTH	SP	CRE	ID	BD	1/29/2104
2020 PO9107069170	KU	3	50 OTH	SP	CRE	ID	BD	1/30/2104
2020 PO9094568861	KU	3	45 OTH	SP	CCA		V	1/31/2104
2020 PO8309861942	KU	6	30 BRN	SP	CRE	ED,ID	X	RP2 2/1/2104
2020 PO4838387177	LGE	3	45 KOP	SP	S		V	2/2/2104
2020 PO4839187157	LGE	4	40 KOP	SP	S		V	2/3/2104
2020 PO4839787137	LGE	4	40 KOP	SP	CCA	ED,ID,MD	TD	2/4/2104
2020 PO4840187123	LGE	4	40 KOP	SP	S		V	2/5/2104
2020 PO4840687111	LGE	4	40 KOP	SP	S		V	2/6/2104
2020 PO4834587098	LGE	4	40 KOP	SP	CCA	ED,ID,SRC	TD	2/7/2104
2020 PO4836587105	LGE	4	40 KOP	SP	CRE	ED,ID	TD	2/8/2104
2020 PO4838587111	LGE	4	40 KOP	SP	CCA	ED,ID	TD	2/9/2104
2020 PO9285072104	KU	6	30 XXX	SP	CRE	ID	TD	2/10/2104
2020 PO9281272019	KU	4	40 XXX	SP	CRE	ED,ID	TD	2/11/2104
2020 PO9311072964	KU	6	30 XXX	SP	CRE	ID	BD	2/12/2104
2020 PO9317272874	KU	4	45 XXX	SP	CRE	ID	BD	2/13/2104
2020 PO8266362326	KU	4	45 KOP	SP	CRE		V	2/14/2104
2020 PO8281062377	KU	3	45 KOP	SP	CCA		V	2/15/2104
2020 PO8230762198	KU	4	45 KOP	SP	CCA		V	2/16/2104
2020 PO2230262227	KU	3	45 KOP	SP	CCA		V	2/17/2104
2020 PO4681888896	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	2/18/2104
2020 PO4684588856	LGE	4	40 BRO	SP	CRE	ID,IP	BD	2/19/2104
2020 PO4683188904	LGE	4	35 BRO	SP	P	ED	T	2/20/2104
2020 PO8001761814	KU	4	45 KOP	SP	CRE		B	2/21/2104
2020 PO8008161655	KU	4	45 KOP	SP	CRE		B	2/22/2104
2020 PO7948461259A	KU	5	35 KOP	SP	CCA		V	2/23/2104
2020 PO7982860212	KU	4	45 KOP	SP	CRE	ED,EP,HH,ID	X	RP1 2/24/2104
2020 PO8027859573	KU	1	70 KOP	SP	CRE		V	2/25/2104
2020 PO8006259398	KU	1	75 KOP	SP	CCA		V	2/26/2104
2020 PO7975759553	KU	5	35 BRN	SP	CCA		V	2/27/2104
2020 PO9341372974	KU	5	30 XXX	SP	CRE	ID	BD	2/28/2104
2020 PO9340173039	KU	4	45 XXX	SP	CRE	ID,IP	TD	2/29/2104
2020 8137760459a	KU	3	50 BRN	SP	CRE		B	3/1/2104
2020 PO7979160313	KU	5	35 KOP	SP	CCA		V	3/2/2104
2020 PO4679588925	LGE	4	40 BRO	SP	P	ED,ID,IP	TD	3/3/2104
2020 PO8001260212	KU	3	45 KOP	SP	CCA		V	3/4/2104
2020 PO8044859991	KU	3	45 KOP	SP	CCA		V	3/5/2104
2020 PO8034160127	KU	4	45 KOP	SP	CRE		B	3/6/2104
2020 PO9326972946A	KU	6	30 XXX	SP	CRE	ID	TD	3/7/2104
2020 PO9330073016	KU	5	35 XXX	SP	CCA		V	3/8/2104
2020 PO9327773057	KU	6	30 XXX	SP	CRE	ID	TD	3/9/2104
2020 PO9326972946	KU	4	45 XXX	SP	CRE	ID	TD	3/10/2104

2020 PO8025260257	KU	4	45 KOP	SP	CCA		V	3/11/2104
2020 PO8004060516	KU	4	40 KOP	SP	CRE		B	3/12/2104
2020 PO8016660438	KU	4	45 KOP	SP	CCA		V	3/13/2104
2020 PO4825087727	LGE	UNK	25 BRO	SP	CRE	ED	BD	3/14/2104
2020 PO4825687732	LGE	4	40 BRO	SP	CRE	ED	TD	3/15/2104
2020 PO4826087730	F	4	40 BRO	SP	CRE	ED,HH,ID,RB	VX PX	3/16/2104
2020 PO8010360430	KU	4	45 KOP	SP	CRE		V	3/17/2104
2020 PO8014160421	KU	3	45 KOP	SP	CCA		V	3/18/2104
2020 PO8017360357	KU	3	45 KOP	SP	CCA		V	3/19/2104
2020 PO9413872161	KU	4	40 OTH	SP	CRE	ED,SRS	TD	3/20/2104
2020 PO9399372162	KU	5	30 OTH	SP	CRE	ED,SRS	TD	3/21/2104
2020 PO8055459856	KU	4	45 KOP	SP	CCA		V	3/22/2104
2020 PO8060459835	KU	1	70 KOP	SP	CRE		V	3/23/2104
2020 PO8066560283	KU	4	45 KOP	SP	CRE		B	3/24/2104
2020 PO8319462054	KU	4	40 BRN	SP	CRE		B	3/25/2104
2020 PO8081560083	KU	4	45 BRN	SP	CRE		B	3/26/2104
2020 PO8085260034	KU	1	80 BRN	SP	CRE		V	3/27/2104
2020 PO8195760767	KU	2	45 BRN	SP	CCA		V	3/28/2104
2020 PO4839287114	LGE	4	40 KOP	SP	CCA	ED,ID	TD	3/29/2104
2020 PO8104260185	KU	2	65 BRN	SP	CRE		V	3/30/2104
2020 PO8137760459	KU	1	70 BRN	SP	CRE		V	3/31/2104
2020 PO4840387118	LGE	4	40 KOP	SP	CCA	ED,ID	TD	4/1/2104
2020 PO4841187096	LGE	1	55 KOP	SP	CRE		V	4/2/2104
2020 PO4841687082	LGE	1	45 KOP	SP	S		V	4/3/2104
2020 PO5530383897	LGE	1	55 KOP	SP	S		V	4/4/2104
2020 PO4842287061	LGE	4	40 KOP	SP	CCA		V	4/5/2104
2020 PO5530983417	LGE	4	35 KOP	SP	CRE	ID	BD	4/6/2104
2020 PO5564783363	LGE	4	30 KOP	SP	S		V	4/7/2104
2020 PO4842787041	LGE	1	45 KOP	SP	S		V	4/8/2104
2020 PO5564783426	LGE	1	50 KOP	SP	S		V	4/9/2104
2020 PO5583083497	LGE	1	50 KOP	SP	S		V	4/10/2104
2020 PO4848787057	LGE	4	35 KOP	SP	S		V	4/11/2104
2020 PO4848787057	LGE	4	40 KOP	SP	S		V	4/12/2104
2020 PO9450571526	F	5	30 OTH	SP	P		V	4/13/2104
2020 PO9457571569	F	4	40 OTH	SP	CRE		V	4/14/2104
2020 PO9466071391	F	3	45 OTH	SP	P		V	4/15/2104
2020 PO9473171179	F	4	40 OTH	SP	CRE		V	4/16/2104
2020 PO9431071907	KU	5	35 OTH	SP	CRE	ED,SRC	TD	4/17/2104
2020 PO9481971661	KU	5	35 OTH	UN	CRE		V	4/18/2104
2020 PO4875187387	F	3	45 XXX	SP	A		V	4/19/2104
2020 PO4875687373	F	3	45 XXX	SP	A		V	4/20/2104
2020 PO4876287356	F	3	45 XXX	SP	A		V	4/21/2104
2020 PO4876687336	LGE	4	35 XXX	SP	CCA		V	4/22/2104
2020 PO4876887341	F	3	45 XXX	SP	A		V	4/23/2104
2020 PO4877387324	F	3	45 XXX	SP	A		V	4/24/2104
2020 PO5909886315	LGE	3	45 XXX	SP	CCA		V	4/25/2104
2020 PO5895386244	LGE	3	45 XXX	SP	CCA		V	4/26/2104

2020 PO4877887310	F	3	45 XXX	SP	A		V	4/27/2104
2020 PO4878087304	F	3	45 XXX	SP	A		V	4/28/2104
2020 PO4878987276	F	1	50 XXX	SP	A		V	4/29/2104
2020 PO4878587289	F	3	50 BRN	SP	CCA		V	4/30/2104
2020 PO5919985891	LGE	3	45 BRN	SP	CCA		V	5/1/2104
2020 PO5913685873	LGE	3	45 BRN	SP	CCA		V	5/2/2104
2020 PO4877587272	LGE	1	50 BRN	SP	CCA		V	5/3/2104
2020 PO4877187273	F	1	50 XXX	SP	CCA		V	5/4/2104
2020 PO4875887267	F	1	50 XXX	SP	CCA		V	5/5/2104
2020 PO4874487270	F	1	50 XXX	SP	CCA		V	5/6/2104
2020 PO4872087276	F	1	50 XXX	SP	CCA		V	5/7/2104
2020 PO4870787288	F	1	50 XXX	SP	CCA		V	5/8/2104
2020 PO4869087291	F	1	50 XXX	SP	CCA		V	5/9/2104
2020 PO4867387293	F	1	50 XXX	SP	CCA		V	5/10/2104
2020 PO4864487278	LGE	3	45 XXX	SP	CCA		V	5/11/2104
2020 PO4865187298	F	1	50 XXX	SP	CCA		V	5/12/2104
2020 PO4863287302	F	1	50 XXX	SP	CCA		V	5/13/2104
2020 PO4861887298	F	1	50 XXX	SP	CCA		V	5/14/2104
2020 PO4861087290	F	1	50 XXX	SP	CCA		V	5/15/2104
2020 PO4859387270	F	1	50 XXX	SP	CCA		V	5/16/2104
2020 PO4848487137	LGE	4	40 XXX	SP	CCA		V	5/17/2104
2020 PO4842987031	LGE	5	25 XXX	SP	CRE		V	5/18/2104
2020 PO4851287074	LGE	2	60 XXX	SP	CCA		V	5/19/2104
2020 PO4872586520	LGE	2	45 OTH	SP	CCA	ED,SRS	TD	5/20/2104
2020 PO4872286533	LGE	1	50 OTH	SP	CCA		V	5/21/2104
2020 PO4786387875	LGE	4	40 BRO	SP	CRE	ED	TD	5/22/2104
2020 PO4785887866	LGE	4	35 BRO	SP	CRE	HH	TD	5/23/2104
2020 PO4785487872	LGE	4	30 BRO	SP	CRE	ED	BD	5/24/2104
2020 PO4785187870	LGE	4	40 BRO	SP	CRE	ED	TD	5/25/2104
2020 PO4786187868	LGE	4	40 BRO	SP	CRE		V	5/26/2104
2020 PO4784187880	LGE	4	40 BRO	SP	CRE	ED	BD	5/27/2104
2020 PO4783887895	LGE	4	40 BRO	SP	CRE	ED	TD	5/28/2104
2020 PO4784287895	LGE	4	40 BRO	SP	CRE	ED,HH,ID,SRC	TD	5/29/2104
2020 PO4785287902	LGE	UNK	30 BRO	SP	CRE	ED	BD	5/30/2104
2020 PO4783987916	LGE	4	40 BRO	SP	P	ED	TD	5/31/2104
2020 PO4793788352	LGE	4	35 BRN	SP	CRE	ED,ID	BD	6/1/2104
2020 PO4795388355	LGE	4	35 BRN	SP	CRE	ED,ID	BD	6/2/2104
2020 PO4796788358	LGE	4	35 BRN	SP	CCA	ED,ID	BD	6/3/2104
2020 PO4671788851	LGE	4	40 BRO	SP	CCA		V	6/4/2104
2020 PO4671188846	LGE	4	40 BRO	SP	CRE	ID,IP	BD	6/5/2104
2020 PO4798288361	LGE	3	45 BRN	SP	CCA		V	6/6/2104
2020 PO4676988879	LGE	4	40 BRO	SP	A	ID,IP	TD	6/7/2104
2020 PO4801588369	LGE	3	45 BRN	SP	CCA		V	6/8/2104
2020 PO4783687907	LGE	4	40 BRO	SP	CRE	ED	TD	6/9/2104
2020 PO4799688364	LGE	4	35 BRN	SP	CRE	ED,ID	BD	6/10/2104
2020 PO4879087301	LGE	4	30 KOP	SP	CCA		V	6/11/2104
2020 PO4750587909	F	3	45 BRO	SP	CCA		V	6/12/2104

2020 PO4747887912	F	3	45 BRO	SP	CCA		V	6/13/2104	
2020 PO4751987915	LGE	UNK	25 BRO	SP	CRE	ED	TD	6/14/2104	
2020 PO4749288211	LGE	4	40 BRO	SP	CCA		V	6/15/2104	
2020 PO4755387905	F	3	45 BRO	SP	CCA		V	6/16/2104	
2020 PO4754887926	F	4	40 BRO	SP	CRE		V	6/17/2104	
2020 PO4674889072	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	6/18/2104	
2020 PO4836186414	LGE	6	30 XXX	SP	P	ID	BD	6/19/2104	
2020 PO4836186414	LGE	3	45 XXX	SP	P	ID	TD	6/20/2104	
2020 PO4834486415	LGE	3	45 XXX	SP	P	ID	TD	6/21/2104	
2020 PO4833586414	LGE	3	45 XXX	SP	P		V	6/22/2104	
2020 PO4675289068	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TX	RR	6/23/2104
2020 PO4887487141	LGE	3	45 OTH	SP	CCA		V	6/24/2104	
2020 PO4890287148	LGE	3	45 OTH	SP	P	ID	BD	6/25/2104	
2020 PO4805987609	LGE	4	40 BRN	SP	CRE		V	6/26/2104	
2020 PO4805787616	LGE	4	40 BRN	SP	CCA		V	6/27/2104	
2020 PO4805887616	LGE	4	35 BRN	SP	CRE		V	6/28/2104	
2020 PO4805587630	LGE	4	40 BRN	SP	A		V	6/29/2104	
2020 PO4805287643	LGE	4	40 BRN	SP	CRE		V	6/30/2104	
2020 PO4804987656	LGE	4	40 BRN	SP	CRE		V	7/1/2104	
2020 PO4804687672	LGE	4	40 BRN	SP	CRE		V	7/2/2104	
2020 PO4860486734	LGE	4	40 OTH	SP	CRE	ED,SRS	TD	7/3/2104	
2020 PO4870886762	LGE	4	40 OTH	SP	CCA		V	7/4/2104	
2020 PO4892087154	LGE	3	45 OTH	SP	P	ED,ID,SRS	TD	7/5/2104	
2020 PO4746788189	LGE	4	40 BRO	SP	CRE	ED	TD	7/6/2104	
2020 PO4745888187	LGE	4	35 BRO	SP	CRE	ED	TD	7/7/2104	
2020 PO4747688196	F	4	30 BRO	SP	CCA		V	7/8/2104	
2020 PO4747888189	F	3	45 BRO	SP	CCA		V	7/9/2104	
2020 PO4746888185	F	3	45 BRO	SP	CCA		V	7/10/2104	
2020 PO4746288175	F	4	30 BRO	SP	CRE		V	7/11/2104	
2020 PO4745988182	F	4	40 BRO	SP	CRE		V	7/12/2104	
2020 PO4804287689	LGE	4	35 BRN	SP	CRE		V	7/13/2104	
2020 PO4804587692	LGE	4	35 BRN	SP	CCA		V	7/14/2104	
2020 PO4805687694	LGE	4	40 BRN	SP	CCA		V	7/15/2104	
2020 PO4806487696	LGE	4	40 BRN	SP	CRE		V	7/16/2104	
2020 PO4862386739	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	7/17/2104	
2020 PO3808490299	F	3	40 XXX	SP	CRE		V	7/18/2104	
2020 PO3818890368	F	4	40 XXX	SP	CRE		V	7/19/2104	
2020 PO3831590455	F	5	40 XXX	SP	CRE		V	7/20/2104	
2020 PO3839990510	F	4	40 XXX	SP	CRE		V	7/21/2104	
2020 PO3841390639	F	4	40 XXX	SP	CRE		V	7/22/2104	
2020 PO3846390553	F	4	40 XXX	SP	CRE		V	7/23/2104	
2020 PO3853390600	F	4	40 XXX	SP	CRE		V	7/24/2104	
2020 PO3860390646	F	4	40 XXX	SP	CRE		V	7/25/2104	
2020 PO4645789071	LGE	5	25 BRO	SP	CRE	ED,ID,IP	TD	7/26/2104	
2020 PO4646189066	LGE	4	35 BRO	SP	CRE	ID,IP	BD	7/27/2104	
2020 PO3868390697	F	4	40 XXX	SP	CRE		V	7/28/2104	
2020 PO3865890816	F	4	40 XXX	SP	A		V	7/29/2104	

2020 PO3872190722	F	4	40 XXX	SP	A		V			7/30/2104
2020 PO3873790696	F	4	40 XXX	SP	A		V			7/31/2104
2020 PO3906290483	F	4	40 XXX	SP	CRE		V			8/1/2104
2020 PO3924790422	KU	6	30 XXX	SP	CCA		V			8/2/2104
2020 PO3915990326	F	4	40 XXX	SP	CRE		V			8/3/2104
2020 PO3925890172	F	4	40 XXX	SP	CRE		V			8/4/2104
2020 PO3936990246	F	4	40 XXX	SP	CRE	ID	B			8/5/2104
2020 PO3948990324	F	4	40 XXX	SP	CRE		V			8/6/2104
2020 PO3939690466	F	4	40 XXX	SP	CRE		V			8/7/2104
2020 PO4659788239	LGE	4	30 BRN	SP	S		V			8/8/2104
2020 PO4659788232	LGE	4	30 BRN	SP	A	ED,ID	BD			8/9/2104
2020 PO4659188228	LGE	4	35 BRN	SP	CCA		V			8/10/2104
2020 PO4660488224	LGE	6	25 BRN	SP	CRE	ED,ID	BD			8/11/2104
2020 PO4661188217	LGE	6	25 BRN	SP	CRE	ED,ID	TD			8/12/2104
2020 PO4645489059	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD			8/13/2104
2020 PO4644989065	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD			8/14/2104
2020 PO4644189050	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD			8/15/2104
2020 PO3930990603	F	4	40 BRN	SP	CRE	ID,RB	BX	PX		8/16/2104
2020 PO3923590555	KU	6	30 BRN	SP	CCA		V			8/17/2104
2020 PO4661688219	LGE	4	25 BRN	SP	A	ED,ID	BD			8/18/2104
2020 PO4661388194	LGE	UNK	25 BRN	SP	CRE		V			8/19/2104
2020 PO3922490735	F	4	40 XXX	SP	CRE		V			8/20/2104
2020 PO4662188200	LGE	4	25 BRN	SP	CRE	ED,ID,IP	BD			8/21/2104
2020 PO3881890565	F	4	40 XXX	SP	CRE		V			8/22/2104
2020 PO3878190540	F	4	40 XXX	SP	CRE		V			8/23/2104
2020 PO5223255322	KU	4	40 OTH	SP	CRE	ID	TD			8/24/2104
2020 PO5261554696	KU	4	40 OTH	SP	CRE	ID	TD			8/25/2104
2020 PO5247754906	KU	4	40 OTH	SP	CRE	ID	TD			8/26/2104
2020 PO5317654818	KU	4	40 OTH	SP	CRE	ID	TD			8/27/2104
2020 PO5235555112	KU	4	40 OTH	SP	CRE	ID	TD			8/28/2104
2020 PO5208555558	KU	4	40 OTH	SP	CRE	ID	TD			8/29/2104
2020 PO4701888163	LGE	4	40 BRO	SP	CRE	ED,ID	TD			8/30/2104
2020 PO4702688168	LGE	3	45 BRO	SP	S		V			8/31/2104
2020 PO4701088158	LGE	4	40 BRO	SP	A	ED,ID	BD			9/1/2104
2020 PO4103494291	LGE	3	45 BRO	SP	CCA		V			9/2/2104
2020 PO4699388147	LGE	3	45 BRO	SP	CCA		V			9/3/2104
2020 PO4698388140	LGE	4	40 BRO	SP	A	ED,ID	BD			9/4/2104
2020 PO4617793998	LGE	3	45 BRO	SP	S		V			9/5/2104
2020 PO4695588122	LGE	4	35 BRO	SP	CCA		V			9/6/2104
2020 PO4695388125	LGE	UNK	25 BRO	SP	CRE		V			9/7/2104
2020 PO4706116468	F	4	40 BRO	SP	CRE		V			9/8/2104
2020 PO4746016753	F	4	40 BRO	SP	CRE		V			9/9/2104
2020 PO4737316812	F	4	40 BRO	SP	CRE		V			9/10/2104
2020 PO4758116615	F	4	40 BRO	SP	CRE	ID,IP	VX	RP1		9/11/2104
2020 PO4753516687	F	4	40 BRO	SP	CRE		V			9/12/2104
2020 PO4694188113	LGE	4	40 BRO	SP	A	ED,ID	BD			9/13/2104
2020 PO4761216571	F	4	40 BRO	SP	CCA		V			9/14/2104

Business Use

2020 PO4799016543	F	4	40 BRO	SP	CRE		V	9/15/2104
2020 PO4795816470	F	4	40 BRO	SP	CRE		V	9/16/2104
2020 PO4693588122	LGE	4	40 BRO	SP	A	ED,ID	TD	9/17/2104
2020 PO4677488017	LGE	4	40 BRO	SP	CCA		V	9/18/2104
2020 PO4678488017	LGE	4	40 BRO	SP	CCA		V	9/19/2104
2020 PO4680488019	LGE	4	40 BRO	SP	CCA		V	9/20/2104
2020 PO4679687980	LGE	4	35 BRO	SP	P	ED,ID	BX PX	9/21/2104
2020 PO4679587988	LGE	5	25 BRO	SP	CCA		V	9/22/2104
2020 PO4678787981	LGE	3	45 BRO	SP	CCA		V	9/23/2104
2020 PO4677787990	LGE	4	30 BRO	SP	A	ED,ID	BD	9/24/2104
2020 PO4685587975	LGE	4	35 BRO	SP	P	ED,ID	TD	9/25/2104
2020 PO4686087955	LGE	UNK	70 BRO	SP	CRE		V	9/26/2104
2020 PO4684687956	LGE	UNK	70 BRO	SP	CRE		V	9/27/2104
2020 PO4779116302-A	KU	5	35 BRO	SP	CRE	ID,IP	BD	9/28/2104
2020 PO4670316507	F	4	40 BRO	SP	CCA		V	9/29/2104
2020 PO4659915975	F	4	40 BRO	SP	CRE		V	9/30/2104
2020 PO4632116215	F	4	40 BRO	SP	CRE		V	10/1/2104
2020 PO4692888132	LGE	4	40 BRO	SP	CCA		V	10/2/2104
2020 PO4651016041	F	4	40 BRO	SP	CRE		V	10/3/2104
2020 PO4691688138	LGE	4	40 BRO	SP	A	ED,ID	BD	10/4/2104
2020 PO4699616398	F	4	40 BRO	SP	CRE		V	10/5/2104
2020 PO4711816529	F	4	40 BRO	SP	CRE		V	10/6/2104
2020 PO4676116553	F	4	40 BRO	SP	CCA		V	10/7/2104
2020 PO4717116586	F	4	40 BRO	SP	CRE	ID,IP	VX RP1	10/8/2104
2020 PO4692888147	LGE	4	40 BRO	SP	A	ED,ID	BD	10/9/2104
2020 PO4692688146	LGE	4	40 BRO	SP	A	ED,ID,SRS	TX RR	10/10/2104
2020 PO4693588148	LGE	UNK	25 BRO	SP	CRE		V	10/11/2104
2020 PO4692388150	LGE	4	40 BRO	SP	A	ED,ID	BD	10/12/2104
2020 PO4734816454	F	4	40 BRO	SP	CRE		V	10/13/2104
2020 PO4733516368	F	4	40 BRO	SP	CRE		V	10/14/2104
2020 PO4727016294	F	4	40 BRO	SP	CRE		V	10/15/2104
2020 PO4718016193	F	4	40 BRO	SP	CRE		V	10/16/2104
2020 PO4710016106	F	4	40 BRO	SP	CRE		V	10/17/2104
2020 PO4701916018	F	4	40 BRO	SP	CRE		V	10/18/2104
2020 PO5191455847	KU	4	45 OTH	SP	CRE	ID	TD	10/19/2104
2020 PO5322154738	KU	5	30 OTH	SP	CRE	ID	TD	10/20/2104
2020 PO5333655089	KU	4	40 OTH	SP	CRE	ID	TD	10/21/2104
2020 PO5129056247	KU	4	40 OTH	SP	CRE	ID	TD	10/22/2104
2020 PO5190056212	KU	4	40 OTH	SP	CCA	ED,SRS	TD	10/23/2104
2020 PO5140056373	KU	5	30 OTH	SP	CRE	ID	TD	10/24/2104
2020 PO5173256063	KU	4	40 OTH	SP	CCA	ED,SRS	TD	10/25/2104
2020 PO5226255998	KU	4	40 OTH	SP	CCA	ED	TD	10/26/2104
2020 PO5158955903	KU	4	45 OTH	SP	CRE	ID	TD	10/27/2104
2020 PO5334154821	KU	6	30 OTH	SP	CRE	ED,ID,SRS	TD	10/28/2104
2020 PO5256356192	KU	4	40 OTH	SP	CCA	ED,SRS	TD	10/29/2104
2020 PO5132155933	KU	4	45 OTH	SP	CRE	ID	TD	10/30/2104
2020 PO4663515510	KU	3	45 BRO	SP	CCA		V	10/31/2104

2020 PO4662415591	F	4	40 BRO	SP	CRE		V	11/1/2104
2020 PO4691688160	LGE	4	40 BRO	SP	P		T	11/2/2104
2020 PO4691088168	LGE	4	40 BRO	SP	A	ED,ID	BD	11/3/2104
2020 PO4690388179	LGE	4	35 BRO	SP	CRE	ED,ID	TD	11/4/2104
2020 PO4685715842	F	4	40 BRO	SP	CRE		V	11/5/2104
2020 PO4677815754	F	4	40 BRO	SP	CRE		V	11/6/2104
2020 PO4644415746	F	4	40 BRO	SP	CRE		V	11/7/2104
2020 PO4654015664	F	4	40 BRO	SP	CRE		V	11/8/2104
2020 PO4626315902	F	4	40 BRO	SP	CRE		V	11/9/2104
2020 PO4635715822	F	4	40 BRO	SP	CRE		V	11/10/2104
2020 PO4618615967	F	4	40 BRO	SP	CRE		V	11/11/2104
2020 PO4613115961	KU	4	40 BRO	SP	CRE	ID,IP	BD	11/12/2104
2020 PO4610316039	F	4	40 BRO	SP	CCA		V	11/13/2104
2020 PO4542516024	F	4	40 BRO	SP	CRE		V	11/14/2104
2020 PO4531315960	F	4	40 BRO	SP	CRE		V	11/15/2104
2020 PO4689788187	LGE	4	40 BRO	SP	CRE	ED,ID	BD	11/16/2104
2020 PO4581115910	F	4	40 BRO	SP	CRE		V	11/17/2104
2020 PO4573415874	F	4	40 BRO	SP	CRE		V	11/18/2104
2020 PO4563815766	F	4	40 BRO	SP	CRE		V	11/19/2104
2020 PO4574715965	F	4	40 BRO	SP	CRE		V	11/20/2104
2020 PO4555016094	F	4	40 BRO	SP	CRE		V	11/21/2104
2020 PO8958441426	ODP	5	30 ACW	SP	S		V	11/22/2104
2020 PO4565316048	F	4	40 BRO	SP	CRE		V	11/23/2104
2020 PO4552316161	KU	4	40 BRO	SP	CRE		V	11/24/2104
2020 PO4541416257	F	4	40 BRO	SP	A		V	11/25/2104
2020 PO4531516345	KU	4	40 BRO	SP	A		V	11/26/2104
2020 PO4516516233	F	4	40 BRO	SP	CRE		V	11/27/2104
2020 PO4524916401	F	4	40 BRO	SP	CCA		V	11/28/2104
2020 PO4520316574	F	4	40 BRO	SP	CRE		V	11/29/2104
2020 PO4513716497	F	4	40 BRO	SP	CRE		V	11/30/2104
2020 PO4505316518	F	4	40 BRO	SP	CCA		V	12/1/2104
2020 PO4495616445	F	4	40 BRO	SP	A		V	12/2/2104
2020 PO4501216581	F	4	40 BRO	SP	A		V	12/3/2104
2020 PO4682387959	LGE	UNK	70 BRO	SP	CRE		V	12/4/2104
2020 PO4487916678	KU	6	30 BRO	SP	CCA		V	12/5/2104
2020 PO4494516668	F	4	40 BRO	SP	CRE		V	12/6/2104
2020 PO4497116714	F	4	40 BRO	SP	CRE		V	12/7/2104
2020 PO4714787924	LGE	1	70 BRO	SP	A		V	12/8/2104
2020 PO5048811577	F	4	40 BRO	SP	CRE		V	12/9/2104
2020 PO5057011498	F	4	40 BRO	SP	CRE		V	12/10/2104
2020 PO5169810724	F	4	40 BRO	SP	CRE		V	12/11/2104
2020 PO5196810476	F	4	40 BRO	SP	CRE		V	12/12/2104
2020 PO5200910438	F	4	40 BRO	SP	CRE		V	12/13/2104
2020 PO5178210613	F	4	40 BRO	SP	CRE		V	12/14/2104
2020 PO5174410643	F	4	40 BRO	SP	CRE		V	12/15/2104
2020 PO5045611675	F	4	40 BRO	SP	CRE		V	12/16/2104
2020 PO5043211486	F	4	40 BRO	SP	CRE		V	12/17/2104

2020 PO5172111498	F	4	40 BRO	SP	CRE		V	12/18/2104
2020 PO5183811436	F	4	40 BRO	SP	CRE		V	12/19/2104
2020 PO1137434119	F	5	35 BRN	SP	CRE	ED,ID	V	12/20/2104
2020 PO5926613473	KU	5	40 XXX	SP	CRE	ED,ID	TD	12/21/2104
2020 PO5960013522	KU	3	50 XXX	SP	CRE	ED,ID	TD	12/22/2104
2020 PO3813691527	KU	4	40 XXX	SP	CRE	ID	TD	12/23/2104
2020 PO3804691467	KU	5	35 XXX	SP	CCA		V	12/24/2104
2020 PO3795391404	KU	4	40 XXX	SP	CRE	ID	TD	12/25/2104
2020 PO3782091316	KU	4	40 XXX	SP	CRE	ID	BD	12/26/2104
2020 PO3748691021	KU	5	35 XXX	SP	CRE	ID	TD	12/27/2104
2020 PO3742891054	KU	4	40 XXX	SP	CRE	ID	TD	12/28/2104
2020 PO3766391211	F	4	40 XXX	SP	CRE		V	12/29/2104
2020 PO3755291025	F	5	35 XXX	SP	A		V	12/30/2104
2020 PO3754291130	F	4	40 XXX	SP	CRE		V	12/31/2104
2020 PO3746691272	KU	4	40 XXX	SP	CRE	ID	TD	1/1/2105
2020 PO4688388806	LGE	4	35 BRO	SP	CCA		V	1/2/2105
2020 PO4689488792	LGE	3	45 BRO	SP	CCA		V	1/3/2105
2020 PO7518339289	KU	4	45 OTH	SP	CRE	ID	TD	1/4/2105
2020 PO7501539390	KU	4	40 OTH	SP	CCA		V	1/5/2105
2020 PO4690388779	LGE	4	35 BRO	SP	CCA		V	1/6/2105
2020 PO4691388766	LGE	4	35 BRO	SP	P	ED	T	1/7/2105
2020 PO4692388759	LGE	4	35 BRO	SP	CRE	ID,IP	BD	1/8/2105
2020 PO4661688081	LGE	4	40 BRN	SP	A	ED,ID	TD	1/9/2105
2020 PO7533539243	KU	4	40 OTH	SP	CRE	ID	TD	1/10/2105
2020 PO7546839227	KU	4	40 OTH	SP	CRE	ID	TD	1/11/2105
2020 PO7558839268	KU	6	30 OTH	SP	CRE	ID	BD	1/12/2105
2020 PO4662288072	LGE	4	35 BRN	SP	A	ED,ID	BD	1/13/2105
2020 PO4662788064	LGE	4	35 BRN	SP	A	ED,ID	TD	1/14/2105
2020 PO0472137393A	ODP	4	40 BRN	SP	CCA		V	1/15/2105
2020 PO4692888753	LGE	4	35 BRO	SP	A	ID,IP	BD	1/16/2105
2020 PO4663588092	LGE	4	25 BRN	SP	A	ED,ID	TD	1/17/2105
2020 PO4664788094	LGE	4	30 BRN	SP	CRE	ED,ID	BD	1/18/2105
2020 PO6052013890	KU	3	50 XXX	SP	CRE	ED,ID	TD	1/19/2105
2020 PO6005613657	KU	5	45 XXX	SP	CRE	ED,ID	TD	1/20/2105
2020 PO5987613557	KU	4	40 XXX	SP	CRE	ED,ID	TD	1/21/2105
2020 PO0507737743	ODP	4	40 BRN	SP	CCA		V	1/22/2105
2020 PO0492237687	ODP	4	40 BRN	SP	CCA		V	1/23/2105
2020 PO7566739028	KU	4	40 OTH	SP	CRE	RB	X	PX 1/24/2105
2020 PO7573739208	KU	4	40 OTH	SP	CRE	ID	TD	1/25/2105
2020 PO7560639216	KU	4	40 OTH	SP	CRE	ID	TD	1/26/2105
2020 PO4665688077	LGE	4	40 BRN	SP	CCA		V	1/27/2105
2020 PO4664788103	LGE	4	40 BRN	SP	CCA		V	1/28/2105
2020 PO4665388095	LGE	4	35 BRN	SP	A	ED,ID	TD	1/29/2105
2020 PO8653135895A	ODP	6	30 XXX	SP	CRE	ID	BD	1/30/2105
2020 PO0392538011	ODP	4	40 BRN	SP	CCA		V	1/31/2105
2020 PO0406838078	ODP	4	45 BRN	SP	CCA		V	2/1/2105
2020 PO4607087981	LGE	4	40 BRO	SP	A	ED,ID	TD	2/2/2105

2020 PO4588587964	LGE	4	40 BRO	SP	CRE	ED,ID	TD	2/3/2105
2020 PO4666288082	LGE	4	35 BRN	SP	A	ED,ID	BD	2/4/2105
2020 PO4665888087	LGE	4	40 BRN	SP	A	ED,ID	BD	2/5/2105
2020 PO4589687947	LGE	4	40 BRO	SP	P	ED,ID	TD	2/6/2105
2020 PO4610287937	LGE	3	45 BRO	SP	A	ED,ID	TD	2/7/2105
2020 PO4616588061	LGE	4	30 BRO	SP	A	ED,ID	BD	2/8/2105
2020 PO4617588209	LGE	4	35 BRO	SP	CRE	ED,ID	BD	2/9/2105
2020 PO4618888208	LGE	4	35 BRO	SP	CRE	ED,ID	TD	2/10/2105
2020 PO4623988210	LGE	4	40 BRO	SP	CRE	ED,ID	BD	2/11/2105
2020 PO4624088222	LGE	4	40 BRO	SP	CRE	ED,ID	BD	2/12/2105
2020 PO6074114004	KU	5	40 XXX	SP	CRE	ED,ID	TD	2/13/2105
2020 PO4691288748	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	2/14/2105
2020 PO4664787981	LGE	UNK	70 BRN	SP	CCA		V	2/15/2105
2020 PO4666887964	LGE	4	40 BRN	DF	CCA		V	2/16/2105
2020 PO4667287978	LGE	UNK	75 BRN	SP	CRE		V	2/17/2105
2020 PO4667487979	LGE	3	45 BRN	SP	A	ED,ID	BD	2/18/2105
2020 PO4668487977	LGE	UNK	65 BRN	SP	P		V	2/19/2105
2020 PO4668887978	LGE	3	50 BRN	SP	A	ED,ID	BD	2/20/2105
2020 PO3679590380	F	5	35 XXX	SP	CRE		V	2/21/2105
2020 PO3681090334	KU	4	40 XXX	SP	CRE	ID	TD	2/22/2105
2020 PO3684990301	F	5	35 XXX	SP	CRE		V	2/23/2105
2020 PO3675690176	KU	5	35 XXX	SP	CCA		V	2/24/2105
2020 PO3662090209	KU	5	35 XXX	SP	CRE	ID	X	RP1 2/25/2105
2020 PO3667090118	KU	4	40 XXX	SP	CRE	ID	TD	2/26/2105
2020 PO3674789980	F	4	40 XXX	SP	CRE		V	2/27/2105
2020 PO3564689470	KU	4	40 XXX	SP	CRE	ID	BD	2/28/2105
2020 PO7601139254	F	5	40 OTH	SP	P		V	3/1/2105
2020 PO7611039269	F	6	30 OTH	SP	P	ED	BD	3/2/2105
2020 PO7587139199	KU	4	40 OTH	SP	CRE	ID	TD	3/3/2105
2020 PO4673487970	LGE	3	45 BRN	SP	A	ED,ID	BD	3/4/2105
2020 PO6085614251	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	3/5/2105
2020 PO6089814461	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	3/6/2105
2020 PO7636839197	KU	4	40 OTH	SP	CCA	ED,SRS	TD	3/7/2105
2020 PO7611439210	KU	4	40 OTH	SP	CRE	ID	TD	3/8/2105
2020 PO7623339245	KU	4	40 OTH	SP	CRE		V	3/9/2105
2020 PO4690088739	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	3/10/2105
2020 PO4669187996	LGE	3	50 BRN	SP	CRE	ED,ID	TD	3/11/2105
2020 PO4669887999	LGE	6	25 BRN	SP	CRE	ED,ID	TD	3/12/2105
2020 PO7639639350	F	5	35 OTH	SP	P		V	3/13/2105
2020 PO7632339325	F	5	35 OTH	SP	P		V	3/14/2105
2020 PO7636839293	KU	4	40 OTH	SP	CRE	ID	BD	3/15/2105
2020 PO7661239376	KU	4	40 OTH	SP	CRE	ID	TD	3/16/2105
2020 PO7648339331	KU	4	40 OTH	SP	CRE	ID	TD	3/17/2105
2020 PO7600539194	KU	4	40 OTH	SP	CRE	ID	TD	3/18/2105
2020 PO4689488734	LGE	5	25 BRO	SP	CRE	ED,ID,IP	TD	3/19/2105
2020 PO9039627028	ODP	4	40 BRO	SP	CCA		V	3/20/2105
2020 PO6616554606	ODP	5	35 BRO	SP	CRE		V	3/21/2105

2020 PO6098814709	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD			3/22/2105
2020 PO6109814984	KU	4	40 XXX	SP	CRE	ED,ID	TD			3/23/2105
2020 PO4667888016	LGE	3	50 BRN	SP	A	ED,ID,SRS	TX	RR		3/24/2105
2020 PO4667188014	LGE	3	45 BRN	SP	CCA		V			3/25/2105
2020 PO9045627304	ODP	4	40 BRO	SP	CCA		V			3/26/2105
2020 PO3669089911	KU	3	45 XXX	SP	CRE	ID	TD			3/27/2105
2020 PO4846986949	LGE	1	50 BRN	SP	CCA		V			3/28/2105
2020 PO4847386959	LGE	1	50 BRN	SP	CCA		V			3/29/2105
2020 PO4847786966	LGE	1	50 BRN	SP	CCA		V			3/30/2105
2020 PO4848086972	LGE	1	55 BRN	SP	CCA		V			3/31/2105
2020 PO4848686987	LGE	1	65 BRN	SP	CCA		V			4/1/2105
2020 PO4849387002	F	1	75 BRN	SP	CCA		V			4/2/2105
2020 PO4905387321	LGE	4	30 OTH	SP	P	ED,ID,SRC	TX	RR		4/3/2105
2020 PO4833986687	LGE	4	35 XXX	SP	P	ED,ID	TD			4/4/2105
2020 PO4834386676	F	4	40 XXX	SP	CRE		V			4/5/2105
2020 PO4834686610	F	2	45 XXX	SP	P		V			4/6/2105
2020 PO4835586624	F	2	45 XXX	SP	A		V			4/7/2105
2020 PO4833586659	F	4	40 XXX	SP	CCA		V			4/8/2105
2020 PO4832486641	F	3	45 XXX	SP	CCA		V			4/9/2105
2020 PO4831186626	F	4	30 XXX	SP	P		V			4/10/2105
2020 PO4831486624	F	2	45 XXX	SP	CRE		V			4/11/2105
2020 PO4832886621	F	2	45 XXX	SP	P		V			4/12/2105
2020 PO4832886621A	LGE	4	30 XXX	SP	P	ED,ID	X	RP3		4/13/2105
2020 PO4831086611	F	4	40 XXX	SP	CRE		V			4/14/2105
2020 PO4830986599	F	4	40 XXX	SP	CCA		V			4/15/2105
2020 PO4830286583	F	3	50 XXX	SP	CRE		V			4/16/2105
2020 PO4829486600	LGE	4	40 XXX	SP	P	ID	BD			4/17/2105
2020 PO4829886609	LGE	4	40 XXX	SP	P	ID	TD			4/18/2105
2020 PO4870486535	LGE	3	45 XXX	SP	CCA		V			4/19/2105
2020 PO4868586554	LGE	3	45 XXX	SP	P	ID	BD			4/20/2105
2020 PO4869386531	LGE	3	45 XXX	SP	CCA		V			4/21/2105
2020 PO4869086534	LGE	3	45 XXX	SP	P	ID	TD			4/22/2105
2020 PO4868186524	LGE	2	45 XXX	SP	P	ID	TD			4/23/2105
2020 PO4867086519	LGE	2	45 XXX	SP	P	ID	BD			4/24/2105
2020 PO4864986473	LGE	3	45 XXX	SP	CCA	ID	TD			4/25/2105
2020 PO4863486462A	LGE	3	45 XXX	SP	CCA		V			4/26/2105
2020 PO4863786458	LGE	4	30 XXX	SP	P	ID	TD			4/27/2105
2020 PO4863486462	LGE	3	45 XXX	SP	P	ID	BD			4/28/2105
2020 PO4861786453	LGE	4	30 XXX	SP	P	ED,ID	TD			4/29/2105
2020 PO4861686458	LGE	3	45 XXX	SP	P	ID	BD			4/30/2105
2020 PO4846586969	LGE	4	40 XXX	SP	A	ED,ID	TD			5/1/2105
2020 PO4903087386	LGE	4	40 OTH	SP	P	ID	BD			5/2/2105
2020 PO4903987360	LGE	3	50 OTH	SP	P	ED,ID,SRS	TD			5/3/2105
2020 PO4903587355	LGE	3	45 OTH	SP	CCA	ED,SRS	TD			5/4/2105
2020 PO4843786964	LGE	4	45 XXX	SP	A	ED,ID	TD			5/5/2105
2020 PO4843486979	LGE	4	40 XXX	SP	A	ED,ID	TD			5/6/2105
2020 PO4901187440	LGE	4	40 OTH	SP	CCA		V			5/7/2105

2020 PO4901787423	LGE	4	40 OTH	SP	CRE	ED,SRS	TD	5/8/2105
2020 PO4902087430	LGE	4	40 OTH	UN	CCA		V	5/9/2105
2020 PO5562582852	LGE	3	45 XXX	SP	CCA		V	5/10/2105
2020 PO4890987491	LGE	4	40 OTH	SP	CCA		V	5/11/2105
2020 PO4891187490	LGE	4	40 OTH	SP	CCA		V	5/12/2105
2020 PO4887787484	LGE	4	40 OTH	SP	CCA		V	5/13/2105
2020 PO4643988999	LGE	4	40 OTH	SP	CCA		V	5/14/2105
2020 PO4642588988	LGE	3	45 OTH	SP	CCA		V	5/15/2105
2020 PO4641388979	LGE	4	40 OTH	SP	CRE	ED,HH,ID,SRS	TD	5/16/2105
2020 PO4779887720	F	3	45 XXX	SP	A		V	5/17/2105
2020 PO4779987721	LGE	4	40 XXX	SP	A	ID	BD	5/18/2105
2020 PO4779887739	F	3	45 XXX	SP	CRE		V	5/19/2105
2020 PO4779887708	F	3	45 XXX	SP	CCA		V	5/20/2105
2020 PO4779887695	F	3	45 XXX	SP	CRE		V	5/21/2105
2020 PO4779887680	F	1	50 XXX	SP	CCA		V	5/22/2105
2020 PO4644989006	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	5/23/2105
2020 PO4644288960	LGE	4	30 OTH	SP	CCA		V	5/24/2105
2020 PO4645488999	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	5/25/2105
2020 PO4779887629	LGE	2	55 XXX	SP	CCA		V	5/26/2105
2020 PO4779887647	LGE	3	55 XXX	SP	CRE	ID	BD	5/27/2105
2020 PO4779887663	LGE	3	55 XXX	SP	A	ID	BD	5/28/2105
2020 PO4780287662	LGE	3	45 XXX	SP	CCA		V	5/29/2105
2020 PO4639888922	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	5/30/2105
2020 PO4641088931	LGE	4	40 OTH	SP	CRE	ED,ID,IP,SRC	TD	5/31/2105
2020 PO4644588957	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	6/1/2105
2020 PO4642288940	LGE	4	40 OTH	SP	P	ED,ID,SRS	TD	6/2/2105
2020 PO4643488949	LGE	4	40 OTH	SP	CRE	ID	BD	6/3/2105
2020 PO4637988908	LGE	4	40 OTH	SP	CRE	ID	BD	6/4/2105
2020 PO4638588912	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	6/5/2105
2020 PO4645288949	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	6/6/2105
2020 PO4643188928	LGE	4	35 OTH	SP	CRE	ED,ID,SRS	TD	6/7/2105
2020 PO4782387681	LGE	3	45 XXX	SP	CCA		V	6/8/2105
2020 PO4782187665	LGE	1	70 XXX	SP	A		V	6/9/2105
2020 PO4782887666	LGE	4	40 XXX	SP	A	ID	BD	6/10/2105
2020 PO4785087670	LGE	3	45 XXX	SP	A	ED,ID	TD	6/11/2105
2020 PO4786287671	LGE	1	70 XXX	SP	A		V	6/12/2105
2020 PO4787687674	LGE	3	45 XXX	SP	A	ED,ID	BD	6/13/2105
2020 PO4788887675	LGE	3	45 XXX	SP	A	ED,ID	TD	6/14/2105
2020 PO4790087677	LGE	3	50 XXX	SP	A	ID	BD	6/15/2105
2020 PO4790687678	LGE	1	75 XXX	SP	A		V	6/16/2105
2020 PO4792487680	LGE	3	45 XXX	SP	A	ID	BD	6/17/2105
2020 PO4634188908	LGE	4	40 OTH	SP	CRE	ED,EP,RB,SRC	X PX	6/18/2105
2020 PO4635788877	LGE	3	45 OTH	SP	CRE		V	6/19/2105
2020 PO4635688881	LGE	4	40 OTH	SP	CRE	ID	BD	6/20/2105
2020 PO4634988895	LGE	4	40 OTH	SP	CRE	ED,EP,RB	X PX	6/21/2105
2020 PO4629188887	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	6/22/2105
2020 PO4633788880	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	6/23/2105

2020 PO4628388889	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	6/24/2105
2020 PO4625788873	LGE	4	40 OTH	SP	CCA		V	6/25/2105
2020 PO4630788885	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	6/26/2105
2020 PO4632288882	LGE	4	40 OTH	SP	CRE	ED,SRS	TD	6/27/2105
2020 PO4635388877	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	6/28/2105
2020 PO4625188880	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	6/29/2105
2020 PO4790487692	LGE	3	50 XXX	SP	A	ED,ID	TD	6/30/2105
2020 PO4790487708	LGE	3	50 XXX	SP	A	ED,ID	TD	7/1/2105
2020 PO4790487718	LGE	1	70 XXX	SP	A		V	7/2/2105
2020 PO4790487730	LGE	3	45 XXX	SP	CCA		V	7/3/2105
2020 PO4790487745	LGE	3	45 XXX	SP	A	ID	BD	7/4/2105
2020 PO4790487766	LGE	4	40 XXX	SP	A	ID	BD	7/5/2105
2020 PO3581297931	LGE	4	30 XXX	ST	CCA		V	7/6/2105
2020 PO3582097911	LGE	4	40 XXX	SP	CCA		V	7/7/2105
2020 PO3574798282	LGE	1	50 XXX	SP	CCA		V	7/8/2105
2020 PO4684089259	LGE	4	35 XXX	SP	CCA		V	7/9/2105
2020 PO4641688771	LGE	3	45 OTH	SP	CCA		V	7/10/2105
2020 PO4642688758	LGE	4	40 OTH	SP	CCA	ED,SRS	TD	7/11/2105
2020 PO4642888756	LGE	4	45 OTH	SP	P	ED,ID,SRS	TD	7/12/2105
2020 PO4645088771	LGE	4	40 OTH	SP	CCA		V	7/13/2105
2020 PO4643588760	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	7/14/2105
2020 PO4644288765	LGE	4	40 OTH	SP	P	ED,ID,SRS	TD	7/15/2105
2020 PO4667089134	LGE	4	30 KOP	SP	P	ID	BD	7/16/2105
2020 PO4665589130	LGE	4	40 KOP	SP	CCA		V	7/17/2105
2020 PO4664689130	LGE	4	40 KOP	SP	CRE	ED,ID	TD	7/18/2105
2020 PO4663789124	LGE	4	35 KOP	SP	CRE	ID,IP	BD	7/19/2105
2020 PO4664289117	LGE	6	25 KOP	SP	CRE	ED,ID	TD	7/20/2105
2020 PO4663089117	LGE	4	40 KOP	SP	CRE	ED,ID	TD	7/21/2105
2020 PO4663989115	LGE	4	30 KOP	SP	CCA		V	7/22/2105
2020 PO4684689229	LGE	3	45 XXX	SP	CRE	ID	BD	7/23/2105
2020 PO4683889231	LGE	4	30 XXX	SP	A	ID	BD	7/24/2105
2020 PO4642288848	LGE	4	40 OTH	SP	CCA	ED,SRS	TD	7/25/2105
2020 PO4641588852	LGE	4	40 OTH	SP	CRE	ED,ID,RB	X	7/26/2105
2020 PO4644988824	LGE	4	40 OTH	SP	P	ID,SRS	BD	7/27/2105
2020 PO4645388828	LGE	4	40 OTH	SP	P	ED,ID,SRS	TD	7/28/2105
2020 PO4648388850	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	7/29/2105
2020 PO4646688838	LGE	4	40 OTH	SP	CRE	ID	BD	7/30/2105
2020 PO4644188819	LGE	3	45 OTH	SP	P	ED,ID,SRS	TD	7/31/2105
2020 PO4650788849	LGE	4	35 OTH	SP	CCA	ED,SRS	TD	8/1/2105
2020 PO4643788804	LGE	3	45 OTH	SP	CCA		V	8/2/2105
2020 PO4643888799	LGE	4	30 OTH	SP	CRE		V	8/3/2105
2020 PO4647788496	LGE	4	40 BRN	SP	A	ID	BD	8/4/2105
2020 PO3584397931	LGE	4	40 BRN	SP	CCA		V	8/5/2105
2020 PO3585497920	LGE	3	50 BRN	SP	A	ED,ID	TD	8/6/2105
2020 PO4665389136	LGE	4	40 KOP	SP	CRE	ED,ID	TD	8/7/2105
2020 PO4665389130	LGE	4	45 KOP	SP	A	ID	BD	8/8/2105
2020 PO4666589140	LGE	4	40 KOP	SP	CRE	ID	BD	8/9/2105

2020 PO4665989145	LGE	4	30 KOP	SP	P	ED,ID	TD	8/10/2105
2020 PO4646888510	LGE	4	40 BRN	SP	A	ED,ID,SRC	TD	8/11/2105
2020 PO4647088505	LGE	4	40 BRN	SP	CCA		V	8/12/2105
2020 PO4684289282	LGE	4	40 XXX	SP	CRE	ED,ID	TD	8/13/2105
2020 PO4683589282	LGE	5	30 XXX	SP	A	ED,ID	TD	8/14/2105
2020 PO4650288796	LGE	3	45 OTH	SP	CCA		V	8/15/2105
2020 PO4651488780	LGE	3	45 OTH	SP	CCA		V	8/16/2105
2020 PO4653388817	LGE	4	40 OTH	SP	CCA		V	8/17/2105
2020 PO3566697651	LGE	4	40 BRN	SP	CCA		V	8/18/2105
2020 PO4647688498	LGE	3	45 BRN	SP	CCA		V	8/19/2105
2020 PO3575997714	LGE	3	45 BRN	SP	CCA		V	8/20/2105
2020 PO3578997734	LGE	3	50 BRN	SP	CCA		V	8/21/2105
2020 PO3582197758	LGE	3	50 BRN	SP	CCA		V	8/22/2105
2020 PO4683589335	LGE	3	45 BRN	SP	CCA		V	8/23/2105
2020 PO4684089299	LGE	4	40 XXX	SP	CRE	ID	BD	8/24/2105
2020 PO4683789318	LGE	4	40 BRN	SP	CCA		V	8/25/2105
2020 PO4655088794A	LGE	3	40 OTH	SP	P	ED,EP,ID,IP	BX	8/26/2105
2020 PO4650788762	LGE	4	35 OTH	SP	CCA		V	8/27/2105
2020 PO4653488773	LGE	4	30 OTH	SP	CCA		V	8/28/2105
2020 PO4652088771	LGE	4	35 OTH	SP	CCA		V	8/29/2105
2020 PO4653388844	LGE	3	45 OTH	SP	CCA		V	8/30/2105
2020 PO4319988159	LGE	3	60 ACW	SP	CRE	ID,IP	BD	8/31/2105
2020 PO4320788158	LGE	3	60 ACW	SP	CRE	ID	BD	9/1/2105
2020 PO4670988930	LGE	4	30 ACW	SP	P	ED,ID	TD	9/2/2105
2020 PO4671988934	LGE	4	30 ACW	SP	CRE	ED,ID	BD	9/3/2105
2020 PO4670688935	LGE	3	45 ACW	SP	S		V	9/4/2105
2020 PO4671488941	LGE	4	40 ACW	SP	S		V	9/5/2105
2020 PO4672588948	LGE	4	40 ACW	SP	CRE	ED,ID	TD	9/6/2105
2020 PO4673088948	LGE	4	35 ACW	SP	CRE	ED,ID	TD	9/7/2105
2020 PO4671188988	LGE	4	40 ACW	DF	CRE	ED,ID	TD	9/8/2105
2020 PO4670188977	LGE	4	40 ACW	SP	S		V	9/9/2105
2020 PO4669988979	LGE	4	40 ACW	SP	CRE	HH,ID,MD,RB	BX	9/10/2105
2020 PO4668388967	LGE	4	40 ACW	SP	CRE	ED,ID,IP	BD	9/11/2105
2020 PO4667188949	LGE	4	30 ACW	DF	CRE	ED,ID	TD	9/12/2105
2020 PO4666888956	LGE	4	40 ACW	DF	CRE	ED,ID	TD	9/13/2105
2020 PO4665988949	LGE	4	45 ACW	SP	S		V	9/14/2105
2020 PO4667088994	LGE	3	45 ACW	SP	S		V	9/15/2105
2020 PO4668388987	LGE	4	35 ACW	SP	P	ID	TD	9/16/2105
2020 PO4660588960	LGE	4	40 ACW	SP	S		V	9/17/2105
2020 PO4661688972	LGE	4	40 ACW	SP	CRE	ED,ID	TD	9/18/2105
2020 PO4661788969	LGE	4	40 ACW	SP	S		V	9/19/2105
2020 PO4663088978	LGE	4	40 ACW	SP	S		V	9/20/2105
2020 PO4664788991	LGE	4	40 ACW	SP	CRE	ED,ID	TD	9/21/2105
2020 PO4664688994	LGE	4	40 ACW	SP	CRE	ID	BD	9/22/2105
2020 PO4666089009	LGE	4	30 ACW	SP	CRE	ED,ID	TD	9/23/2105
2020 PO4667989015	LGE	5	45 ACW	SP	CRE	ED,ID	TD	9/24/2105
2020 PO4666489002	LGE	UNK	45 ACW	SP	CRE	ED,HH,ID,MD,RB	VX	9/25/2105

2020 PO4669789029	LGE	4	40 ACW	SP	CRE	ED,ID	TD		9/26/2105
2020 PO4673089052	LGE	4	40 ACW	SP	CRE		VX	PX	9/27/2105
2020 PO4671389040	LGE	4	40 ACW	SP	S		V		9/28/2105
2020 PO4657989005	LGE	4	30 ACW	SP	S		V		9/29/2105
2020 PO4652588968	LGE	4	40 ACW	SP	CRE	ED,ID	TD		9/30/2105
2020 PO4652888964	LGE	4	40 ACW	SP	CRE	ED,ID	TD		10/1/2105
2020 PO4656088986	LGE	4	40 ACW	SP	CRE	ED,ID	TD		10/2/2105
2020 PO4665089063	LGE	4	40 ACW	SP	CRE	ED,ID	TD		10/3/2105
2020 PO4665589055	LGE	4	40 ACW	SP	CRE	ID	BD		10/4/2105
2020 PO4668689071	LGE	3	45 ACW	SP	S		V		10/5/2105
2020 PO4668089080	LGE	4	40 ACW	SP	S		V		10/6/2105
2020 PO4306987932	LGE	4	40 ACW	ST	CCA		V		10/7/2105
2020 PO4307087948	LGE	4	40 ACW	SP	P	ED,ID	TD		10/8/2105
2020 PO4304187935	LGE	3	55 ACW	SP	CRE	ID	BD		10/9/2105
2020 PO4304787934	LGE	3	55 ACW	SP	P	ID	BD		10/10/2105
2020 PO4305787933	LGE	3	50 ACW	SP	P	ID	BD		10/11/2105
2020 PO4306787961	LGE	3	45 ACW	SP	S		V		10/12/2105
2020 PO4306587955	F	4	40 ACW	SP	CRE		V		10/13/2105
2020 PO4306587950	LGE	3	45 ACW	SP	S		V		10/14/2105
2020 PO4306587948	LGE	2	45 ACW	DF	CRE	HH,ID,IP,RB	BX	RP3	10/15/2105
2020 PO4306587946	LGE	2	65 ACW	WC	CRE	ID	BD		10/16/2105
2020 PO4306387938	LGE	3	45 ACW	SP	P	ED,ID	TD		10/17/2105
2020 PO4295487985	LGE	2	60 ACW	SP	CRE	ID	BD		10/18/2105
2020 PO4295587993	LGE	3	55 ACW	SP	CRE	ID	BD		10/19/2105
2020 PO4296387991	LGE	4	40 ACW	SP	CRE	ED,ID	TD		10/20/2105
2020 PV0114791946	LGE	5	30 ACW	SP	CRE	ED,ID	TD		10/21/2105
2020 PO4308688108	LGE	1	75 ACW	ST	S		V		10/22/2105
2020 PO4308788110	LGE	3	45 ACW	SP	S		V		10/23/2105
2020 PO4308888117	LGE	4	35 ACW	SP	CRE	ED,ID,IP	BD		10/24/2105
2020 PO0210393179	LGE	3	45 ACW	SP	S		V		10/25/2105
2020 PO4308588096	LGE	1	50 ACW	SP	S		V		10/26/2105
2020 PO0203693019	LGE	2	55 ACW	SP	S		V		10/27/2105
2020 PO0202592927	LGE	3	45 ACW	SP	S		V		10/28/2105
2020 PO4308388081	LGE	1	75 ACW	SP	CRE		V		10/29/2105
2020 PO0211193615	LGE	1	50 ACW	SP	S		V		10/30/2105
2020 PO4309388157	LGE	3	50 ACW	SP	S		V		10/31/2105
2020 PO4309488166	LGE	1	45 ACW	WC	CRE	ID	BD		11/1/2105
2020 PO4309188170	LGE	4	40 ACW	SP	P	ID	BD		11/2/2105
2020 PO4310288195	LGE	2	55 ACW	DF	CRE	ID	BD		11/3/2105
2020 PO4307188206	LGE	3	50 ACW	SP	S		V		11/4/2105
2020 PO4306788201	LGE	1	50 ACW	SP	S		V		11/5/2105
2020 PO4306488202	LGE	4	35 ACW	SP	S		V		11/6/2105
2020 PO4308888203	LGE	4	40 ACW	SP	CRE		V		11/7/2105
2020 PO0216194028	LGE	2	60 ACW	SP	CRE	ID	BX	RP3	11/8/2105
2020 PO4309688186	LGE	2	55 ACW	SP	S		V		11/9/2105
2020 PO4309688181	LGE	2	45 ACW	SP	CRE	ID	BD		11/10/2105
2020 PO4309488176	LGE	3	50 ACW	SP	S		V		11/11/2105

2020 PO4309688178	LGE	1	35 ACW	DF	CRE	ED,ID,IP	BD	11/12/2105
2020 PO4316988164	LGE	3	55 ACW	SP	CRE	ED,ID	BD	11/13/2105
2020 PO9421782279	KU	4	40 BRO	SP	CRE	ID	BD	11/14/2105
2020 PO9465583054	KU	4	40 BRO	SP	CRE	ID	BD	11/15/2105
2020 PO9491982902	KU	4	40 BRO	SP	CRE	ID	BD	11/16/2105
2020 PO9519383646	F	4	40 BRO	SP	CCA		V	11/17/2105
2020 PO9514882127	F	4	40 BRO	SP	A		V	11/18/2105
2020 PO9497783563	F	4	40 BRO	SP	A		V	11/19/2105
2020 PO9438983234	KU	4	40 BRO	SP	CRE	ID	BD	11/20/2105
2020 PO9490483540	KU	6	30 BRO	SP	CRE	ID,IP	BD	11/21/2105
2020 PO9549183756	F	4	40 BRO	SP	A		V	11/22/2105
2020 PO9534883703	F	4	40 BRO	SP	CRE		V	11/23/2105
2020 PO9402883309	F	5	35 BRO	SP	CRE		V	11/24/2105
2020 PO9415583235	F	3	45 BRO	SP	CRE		V	11/25/2105
2020 PO9341283401	KU	5	35 BRO	SP	A		V	11/26/2105
2020 PO9341283401-A	KU	5	35 BRO	SP	A	ED,ID,IP	TD	11/27/2105
2020 PO9362783553	F	4	40 BRO	SP	A		V	11/28/2105
2020 PO9360183723-A	KU	2	50 BRO	SP	CCA		V	11/29/2105
2020 PO9360183723	KU	3	50 BRO	SP	CCA		V	11/30/2105
2020 PO9359683866	F	4	40 BRO	SP	CCA		V	12/1/2105
2020 PO9376583689	F	4	40 BRO	SP	CCA		V	12/2/2105
2020 PO9388081918	KU	4	40 BRO	SP	CRE	ID	BD	12/3/2105
2020 PO9407582128	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD	12/4/2105
2020 PO9498482222	F	4	40 BRO	SP	A		V	12/5/2105
2020 PO4649588945	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	12/6/2105
2020 PO4646588927	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	12/7/2105
2020 PO4674988886	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	12/8/2105
2020 PO4671988893	LGE	4	40 BRO	SP	CRE	ID,IP	BD	12/9/2105
2020 PV4877986314	LGE	3	50 OTH	SP	P	ID	BD	12/10/2105
2020 PO4877586328	LGE	3	45 OTH	SP	P	ED,ID,SRS	TD	12/11/2105
2020 PO4878286311	LGE	2	55 OTH	SP	CCA	ED,SRS	TD	12/12/2105
2020 PO4853587320	LGE	4	40 XXX	SP	P		V	12/13/2105
2020 PO4854387318	LGE	4	40 XXX	SP	CCA		V	12/14/2105
2020 PO5662785999	LGE	4	40 XXX	SP	CCA		V	12/15/2105
2020 PO4855887266	LGE	3	45 XXX	SP	CCA		V	12/16/2105
2020 PO4845387128	LGE	4	35 XXX	SP	CCA		V	12/17/2105
2020 PO4827687390	LGE	4	35 BRO	SP	CRE	ED	BD	12/18/2105
2020 PO4800288239	LGE	4	35 BRN	SP	A		V	12/19/2105
2020 PO4794788320	LGE	4	35 BRN	SP	A	ED,ID	BD	12/20/2105
2020 PO4676188915	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	12/21/2105
2020 PO4826987378	LGE	4	35 BRO	SP	CRE	ED	BD	12/22/2105
2020 PO4826187363	LGE	4	35 BRO	SP	CRE	ED	BD	12/23/2105
2020 PO4825287347	LGE	4	35 BRO	SP	CRE	ED	TD	12/24/2105
2020 PO4828287403	LGE	4	40 BRO	SP	CCA		V	12/25/2105
2020 PO4795588309	LGE	4	40 BRN	SP	CCA		V	12/26/2105
2020 PO4796088303	LGE	4	35 BRN	SP	A	ED,ID	BD	12/27/2105
2020 PO4675088924	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	12/28/2105

2020 PO4796988291	LGE	4	35 BRN	SP	A	ED,ID	BD	12/29/2105
2020 PO4797988279	LGE	4	35 BRN	SP	A	ED,ID	BD	12/30/2105
2020 PO4798988268	LGE	4	35 BRN	SP	A	ED,ID	BD	12/31/2105
2020 PO4802388257	LGE	4	35 BRN	SP	CRE	ED,ID	TD	1/1/2106
2020 PO4799888256	LGE	4	35 BRN	SP	A	ED,ID	BD	1/2/2106
2020 PO4825287716	F	3	45 BRO	SP	CCA		V	1/3/2106
2020 PO4825587722	F	4	40 BRO	SP	CCA		V	1/4/2106
2020 PO4825987720	F	4	40 BRO	SP	CCA		V	1/5/2106
2020 PO4824687705	F	1	50 BRO	SP	CCA		V	1/6/2106
2020 PO4823687689	F	1	50 BRO	SP	CCA		V	1/7/2106
2020 PO4825287706	LGE	4	30 BRO	SP	P	ED	TD	1/8/2106
2020 PO4824487692	LGE	4	30 BRO	SP	CRE	ED	TD	1/9/2106
2020 PO4800888244	LGE	4	35 BRN	SP	CRE	ED,HH,ID,RB	BX PX	1/10/2106
2020 PO4673688905	LGE	4	40 BRO	SP	CRE	ID,IP	BD	1/11/2106
2020 PO4673388903	LGE	4	40 BRO	SP	CRE	ID,IP	BD	1/12/2106
2020 PO4674688896	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	1/13/2106
2020 PO4674488894	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	1/14/2106
2020 PO4822887674	F	1	50 BRO	SP	CCA		V	1/15/2106
2020 PO4822787673	F	1	50 BRO	SP	CCA		V	1/16/2106
2020 PO4821887656	F	UNK	45 BRO	SP	CRE		V	1/17/2106
2020 PO4820887641	LGE	4	30 BRO	SP	CCA		V	1/18/2106
2020 PO4820987639	F	1	50 BRO	SP	CCA		V	1/19/2106
2020 PO4822087648	LGE	4	30 BRO	SP	CRE	ED	TD	1/20/2106
2020 PO4822387655	LGE	4	30 BRO	SP	CCA		V	1/21/2106
2020 PO4826486323	LGE	7	30 XXX	SP	CCA		V	1/22/2106
2020 PO4826886326	LGE	7	30 XXX	ST	CCA		V	1/23/2106
2020 PO4829386323	LGE	1	45 XXX	SP	CCA		V	1/24/2106
2020 PO4832486332	LGE	2	45 XXX	SP	CCA		V	1/25/2106
2020 PO4830986328	LGE	4	45 XXX	SP	A	ID	TD	1/26/2106
2020 PO4829386314	LGE	4	35 XXX	SP	CCA		V	1/27/2106
2020 PO4830786314	LGE	3	45 XXX	SP	CCA		V	1/28/2106
2020 PO4823686314	LGE	3	45 XXX	SP	CCA		V	1/29/2106
2020 PO4832686314	LGE	3	45 XXX	SP	CCA		V	1/30/2106
2020 PO4675588930	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	1/31/2106
2020 PO4821787630	LGE	3	45 BRO	SP	CCA		V	2/1/2106
2020 PO4822287615	LGE	3	45 BRO	SP	CCA		V	2/2/2106
2020 PO4823187586	LGE	1	50 BRO	SP	CCA		V	2/3/2106
2020 PO4823487576	LGE	1	50 BRO	SP	CCA		V	2/4/2106
2020 PO4823987560	LGE	1	50 BRO	SP	CCA		V	2/5/2106
2020 PO3878267846	KU	4	40 KOP	SP	CRE	ED,ID	TD	2/6/2106
2020 PO7921259187	KU	2	65 BRN	SP	CCA		V	2/7/2106
2020 PO7905359170	KU	1	90 BRN	AL	CCA		V	2/8/2106
2020 PO7914459048	KU	4	55 BRN	SP	CCA		V	2/9/2106
2020 PO7932858792	KU	2	60 BRN	SP	CCA		V	2/10/2106
2020 PO7948359255	KU	2	70 BRN	AL	CRE		V	2/11/2106
2020 PO7976259324	KU	2	70 BRN	AL	CCA		V	2/12/2106
2020 PO7968658531	KU	4	45 BRN	SP	CCA		V	2/13/2106

2020 PO7971358256	KU	3	55 BRN	SP	CCA		V	2/14/2106
2020 PO7980758072	KU	3	55 BRN	SP	CCA		V	2/15/2106
2020 PO7987858515	KU	4	45 XXX	SP	CCA		V	2/16/2106
2020 7884859096a	KU	5	30 XXX	SP	CCA		V	2/17/2106
2020 PO7884859096	KU	5	35 XXX	SP	CCA		V	2/18/2106
2020 PO8289564956	KU	6	30 XXX	SP	CCA		V	2/19/2106
2020 PO8273864913	KU	4	40 XXX	SP	CCA		V	2/20/2106
2020 PO8291164800	KU	4	40 XXX	SP	CCA		V	2/21/2106
2020 PO8286164596	KU	4	40 XXX	SP	CCA		V	2/22/2106
2020 8506366028a	KU	3	45 XXX	SP	CCA		V	2/23/2106
2020 PO8494666297	KU	5	30 XXX	SP	CRE	ID	BD	2/24/2106
2020 PO8482766212	KU	3	45 XXX	SP	CCA		V	2/25/2106
2020 PO3885386062	F	4	40 KOP	SP	CRE		V	2/26/2106
2020 PO3860685909	F	4	40 KOP	SP	P		V	2/27/2106
2020 PO3840485826	F	4	40 KOP	SP	A		V	2/28/2106
2020 PO3820785603	F	4	40 KOP	SP	P		V	3/1/2106
2020 PO3805885448	F	4	40 KOP	SP	A		V	3/2/2106
2020 PO379985380	KU	4	40 KOP	SP	S		V	3/3/2106
2020 PO3789885263	F	4	40 KOP	SP	P		V	3/4/2106
2020 PO3785585123	F	4	40 KOP	SP	P		V	3/5/2106
2020 PO3772184971	F	4	40 KOP	SP	P		V	3/6/2106
2020 PO3920085065	KU	4	40 KOP	SP	S		V	3/7/2106
2020 PO3759084846	F	4	40 KOP	SP	P		V	3/8/2106
2020 PO3823785227	F	4	40 KOP	SP	CRE		V	3/9/2106
2020 PO3863885456	KU	4	45 KOP	SP	S		V	3/10/2106
2020 PO3845185685	KU	3	45 KOP	SP	S		V	3/11/2106
2020 PO3847885538	KU	4	45 KOP	SP	S		V	3/12/2106
2020 PO3834285393	KU	4	45 KOP	SP	S		V	3/13/2106
2020 PO3840885014	F	4	40 KOP	SP	P		V	3/14/2106
2020 PO3857984978	F	4	40 KOP	SP	P		V	3/15/2106
2020 PO3859785092	F	4	40 KOP	SP	CRE		V	3/16/2106
2020 PO3881985174	F	4	40 KOP	SP	CRE		V	3/17/2106
2020 PO3879784939	F	4	40 KOP	SP	P		V	3/18/2106
2020 PO0054476560	KU	2	45 XXX	SP	CRE		V	3/19/2106
2020 PO0047776525	KU	2	45 XXX	SP	CRE		V	3/20/2106
2020 PO0036876530	KU	3	45 XXX	SP	CCA		V	3/21/2106
2020 PO0042176457	KU	2	45 XXX	SP	CRE		V	3/22/2106
2020 PO0042476383	KU	2	45 XXX	SP	CRE		V	3/23/2106
2020 PO0027876360	KU	2	45 XXX	SP	CRE		V	3/24/2106
2020 PO0005676305	KU	4	45 XXX	SP	CCA		V	3/25/2106
2020 PO0078977093	KU	4	40 XXX	SP	CRE		V	3/26/2106
2020 PO3888386678	KU	H1	90 XXX	AL	CCA		V	3/27/2106
2020 PO3841386782	KU	5	35 XXX	SP	CRE	ED,ID	TD	3/28/2106
2020 PO3859186992	KU	4	40 XXX	SP	CCA	ED	T	3/29/2106
2020 PO3862287138	KU	1	75 XXX	SP	CRE	ED,ID	TD	3/30/2106
2020 PO3883087248	KU	2	70 XXX	SP	CRE	ED,ID	TD	3/31/2106
2020 PO3931085760	KU	H1	60 XXX	AL	CRE		V	4/1/2106

Business Use

2020 PO3933785783	KU	H1	45	XXX	AL	CRE		V	4/2/2106
2020 PO3928485741	KU	H1	50	XXX	AL	CRE		V	4/3/2106
2020 PO3905886336	KU	H1	85	XXX	SP	CRE		V	4/4/2106
2020 PO3907786346	KU	1	75	XXX	AL	CCA		V	4/5/2106
2020 PO3954187368	F	6	30	XXX	SP	CRE		V	4/6/2106
2020 PO3949187259	F	4	40	XXX	SP	CRE		V	4/7/2106
2020 PO3904487360	KU	3	65	XXX	SP	CRE	ED,ID	TD	4/8/2106
2020 PO3928187458	KU	4	40	XXX	SP	CCA		V	4/9/2106
2020 PO3924987443	KU	1	80	XXX	ST	CRE		V	4/10/2106
2020 8766768472a	KU	4	45	XXX	SP	CCA		V	4/11/2106
2020 PO8766768472	KU	4	45	XXX	SP	CCA		V	4/12/2106
2020 PO8777368378	KU	3	45	XXX	SP	CCA		V	4/13/2106
2020 PO8749968303	KU	4	45	XXX	SP	CCA	ED	T	4/14/2106
2020 PO8803168644	KU	4	40	XXX	SP	CRE		V	4/15/2106
2020 PO8756568174	KU	3	45	XXX	SP	CCA		V	4/16/2106
2020 PO8736967817	KU	4	40	XXX	SP	CCA		V	4/17/2106
2020 PO8732468055	KU	4	40	XXX	SP	CCA		V	4/18/2106
2020 PO8729968113	KU	4	45	XXX	SP	CCA	ED	T	4/19/2106
2020 PO8703967846	KU	4	45	XXX	SP	CCA	ED	T	4/20/2106
2020 PO8720367816	KU	3	45	XXX	SP	CCA		V	4/21/2106
2020 PO8683167642	KU	4	40	XXX	SP	CRE	ED,ID	TD	4/22/2106
2020 8662667235a	KU	5	40	BRN	AL	S		V	4/23/2106
2020 PO8696867582	KU	3	45	BRN	SP	CCA		V	4/24/2106
2020 PO8662667235	KU	3	45	BRN	SP	CCA		V	4/25/2106
2020 PO8657267183	KU	3	45	BRN	SP	CCA		V	4/26/2106
2020 PO8641867228	KU	4	40	BRN	SP	CCA		V	4/27/2106
2020 PO8632167241	KU	3	45	BRN	SP	CCA		V	4/28/2106
2020 PO8620367418	KU	2	50	BRN	SP	CCA		V	4/29/2106
2020 PO8613267524	KU	2	50	BRN	SP	CCA	ED	T	4/30/2106
2020 PO0377278934	KU	4	40	XXX	SP	CRE		V	5/1/2106
2020 PO0384278811	KU	4	40	XXX	SP	CCA		V	5/2/2106
2020 PO0380178786	KU	4	40	XXX	SP	CRE		V	5/3/2106
2020 PO9993576675	KU	4	45	XXX	SP	CCA		V	5/4/2106
2020 PO9992176706	KU	4	45	XXX	SP	CCA		V	5/5/2106
2020 PO9991676620	KU	4	45	XXX	SP	CCA		V	5/6/2106
2020 PO9995276635	KU	4	45	XXX	SP	CCA		V	5/7/2106
2020 PO9628575443	KU	6	30	XXX	SP	P	ED	T	5/8/2106
2020 PO9622875429	KU	3	45	XXX	SP	CCA		V	5/9/2106
2020 PO9762875497	KU	3	45	XXX	SP	CCA		V	5/10/2106
2020 PO9621974533	KU	4	40	XXX	SP	CRE	ID	BD	5/11/2106
2020 PO9616874767	KU	6	30	XXX	SP	P	ED	T	5/12/2106
2020 PO9631574776	KU	4	40	XXX	SP	P	ED	T	5/13/2106
2020 PO3553798224	LGE	1	50	BRN	SP	CCA		V	5/14/2106
2020 PO3556698249	LGE	1	50	BRN	SP	CCA		V	5/15/2106
2020 PO3570498340	LGE	1	55	BRN	SP	CCA		V	5/16/2106
2020 PO4645888564	LGE	1	60	BRN	SP	CRE		V	5/17/2106
2020 PO3576498526	F	3	55	BRN	SP	CCA		V	5/18/2106

2020 PO4648488580	LGE	3	45 BRN	SP	CRE	ED,ID	BD	5/19/2106
2020 PO4654888630	F	3	50 BRN	SP	A		V	5/20/2106
2020 PO4653788620	LGE	2	55 BRN	SP	CCA		V	5/21/2106
2020 PO4650988584	LGE	3	50 BRN	SP	CCA		V	5/22/2106
2020 PO4651888606	LGE	3	45 BRN	SP	CRE	ED,ID	BD	5/23/2106
2020 PO4650288593	LGE	3	45 BRN	SP	CRE	ED,ID	BD	5/24/2106
2020 PO4650288594	LGE	3	45 BRN	SP	CCA		V	5/25/2106
2020 PO4657988645	LGE	3	50 BRN	SP	CCA		V	5/26/2106
2020 PO4659088649	LGE	3	45 BRN	SP	CCA		V	5/27/2106
2020 PO4660588660	LGE	3	45 BRN	SP	CCA		V	5/28/2106
2020 PO3701999339	LGE	3	45 BRN	SP	CCA		V	5/29/2106
2020 PO4662388678	LGE	UNK	45 BRN	SP	CCA		V	5/30/2106
2020 PO4661388670	LGE	3	45 BRN	SP	CCA		V	5/31/2106
2020 PO4653488773	LGE	4	35 BRN	SP	CCA		V	6/1/2106
2020 PO4722987936	F	3	45 BRO	SP	CRE		V	6/2/2106
2020 PO4724587949	F	4	30 BRO	SP	CRE		V	6/3/2106
2020 PO4725387951	F	4	40 BRO	SP	CRE		V	6/4/2106
2020 PO4726887955	F	4	40 BRO	SP	CRE		V	6/5/2106
2020 PO4082837486	KU	4	40 BRO	SP	A	ED,ID,IP	TD	6/6/2106
2020 PO4724087936	F	4	40 BRO	SP	CRE	ED,ID	VX	6/7/2106
2020 PO4723087942	F	4	30 BRO	SP	CRE		V	6/8/2106
2020 PO4721587938	F	3	45 BRO	SP	CCA		V	6/9/2106
2020 PO4721387946	F	4	40 BRO	SP	CRE		V	6/10/2106
2020 PO4080437945	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	6/11/2106
2020 PO4001737982	KU	4	40 BRO	SP	CRE	ED	TD	6/12/2106
2020 PO4657688759	LGE	4	30 BRN	SP	CCA		V	6/13/2106
2020 PO4658788760	LGE	4	35 BRN	SP	A		B	6/14/2106
2020 PO4657288756	LGE	4	35 BRN	SP	A	ED,ID	BD	6/15/2106
2020 PO4732887935	F	4	40 BRO	SP	CRE		V	6/16/2106
2020 PO4731487930	F	4	40 BRO	SP	CCA		V	6/17/2106
2020 PO4731087951	F	3	45 BRO	SP	CRE		V	6/18/2106
2020 PO3977038101	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	6/19/2106
2020 PO4730787965	F	4	40 BRO	SP	CRE	ED,ID	VX	6/20/2106
2020 PO4729987963	F	3	45 BRO	SP	CCA		V	6/21/2106
2020 PO4729887968	F	4	40 BRO	SP	CRE		V	6/22/2106
2020 PO4728487959	F	4	40 BRO	SP	CRE		V	6/23/2106
2020 PO4727387993	F	4	40 BRO	SP	CRE		V	6/24/2106
2020 PO3943938261	KU	4	40 BRO	SP	CRE	ID,IP	BD	6/25/2106
2020 PO6853242625	KU	4	40 OTH	SP	CRE	ED,SRS	TD	6/26/2106
2020 PO4726187992	F	4	40 BRO	SP	CRE		V	6/27/2106
2020 PO4728387993	F	4	40 BRO	SP	CRE		V	6/28/2106
2020 PO6892842232	KU	4	40 OTH	SP	CRE	ED,SRS	TD	6/29/2106
2020 PO6884542471	KU	4	40 OTH	SP	CRE	ED,SRS	TD	6/30/2106
2020 PO6920742262	KU	3	45 OTH	SP	CCA		V	7/1/2106
2020 PO6906341926	KU	4	40 OTH	SP	CRE	ED,SRS	TD	7/2/2106
2020 PO6912941692	KU	4	40 OTH	SP	CRE	ED,SRS	TD	7/3/2106
2020 PO6921841445	KU	4	40 OTH	SP	CRE	ED,SRS	TD	7/4/2106

2020 PO4814888253	LGE	4	40 BRO	SP	CCA		V	7/5/2106
2020 PO4816088243	LGE	3	45 BRO	SP	CCA		V	7/6/2106
2020 PO4816288244	LGE	4	35 BRO	SP	CRE	ED	BD	7/7/2106
2020 PO4817188255	LGE	4	35 BRO	SP	CRE	ED	TD	7/8/2106
2020 PO4660488770	LGE	4	45 BRN	SP	A	ED,ID	BD	7/9/2106
2020 PO4659388762	LGE	4	40 BRN	SP	CCA		V	7/10/2106
2020 PO4658288754	LGE	4	45 BRN	SP	A	ED,ID	BD	7/11/2106
2020 PO3977439672	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	7/12/2106
2020 PO3969939823	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	7/13/2106
2020 PO4813688265	LGE	4	40 BRO	SP	CRE	ED	TD	7/14/2106
2020 PO4812588275	LGE	4	40 BRO	SP	CRE	ED	TD	7/15/2106
2020 PO6930841197	KU	4	40 OTH	SP	CRE	ED,SRS	TD	7/16/2106
2020 PO4657188745	LGE	4	40 BRN	SP	CCA		V	7/17/2106
2020 PO4655988736	LGE	4	40 BRN	SP	CCA		V	7/18/2106
2020 PO6958440437	KU	4	40 OTH	SP	CRE	ED,SRS	TD	7/19/2106
2020 PO6939540963	KU	4	40 OTH	SP	CRE	ED,SRS	TD	7/20/2106
2020 PO6947540738	KU	4	40 OTH	SP	CRE	ED,SRS	TD	7/21/2106
2020 PO6983039750	KU	4	40 OTH	SP	CRE	ED	TD	7/22/2106
2020 PO3655199097	F	3	50 BRN	SP	P		V	7/23/2106
2020 PO4657188648	F	3	50 BRN	SP	CCA		V	7/24/2106
2020 PO4658388856	F	3	50 BRN	SP	A		V	7/25/2106
2020 PO4659288662	F	3	50 BRN	SP	A		V	7/26/2106
2020 PO6974339984	KU	4	45 OTH	SP	CRE	ED,SRS	TD	7/27/2106
2020 PO6966240211	KU	5	35 OTH	SP	CRE	ED,SRS	TD	7/28/2106
2020 PO4813388257	LGE	4	40 BRO	SP	CRE	ED	TD	7/29/2106
2020 PO3816240017	KU	4	40 BRO	SP	CCA		V	7/30/2106
2020 PO3794139882	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	7/31/2106
2020 PO3801540132	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	8/1/2106
2020 PO3795240011	KU	4	40 BRO	SP	CRE	HH,IP,RB	X	RP1 8/2/2106
2020 PO4812788259	LGE	4	30 BRO	SP	CRE	ED	TD	8/3/2106
2020 PO4812088243	LGE	4	40 BRO	SP	CRE	ED	TD	8/4/2106
2020 PO4659188665	LGE	4	40 BRN	SP	S		V	8/5/2106
2020 PO4658388676	LGE	4	40 BRN	SP	S		V	8/6/2106
2020 PO4657688688	LGE	4	40 BRN	SP	CCA		V	8/7/2106
2020 PO6943139284B	KU	4	40 OTH	SP	CCA		V	8/8/2106
2020 PO6943139284A	KU	4	40 OTH	SP	CCA		V	8/9/2106
2020 PO6971039416	KU	4	35 OTH	SP	P	ED,SRS	TD	8/10/2106
2020 PO6943139284	KU	4	35 OTH	SP	CCA		V	8/11/2106
2020 PO6991339507	KU	5	35 OTH	SP	CRE	ED,SRS	TD	8/12/2106
2020 PO6991139386	KU	4	45 OTH	SP	CRE	ED,SRS	TD	8/13/2106
2020 PO4810888230	LGE	4	40 BRO	SP	CRE	ED	BD	8/14/2106
2020 PO4656188695	LGE	4	40 BRN	SP	CRE	ED,ID	TD	8/15/2106
2020 PO0820311037	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	8/16/2106
2020 PO0783311327	KU	5	35 ACE	SP	CRE	ED,ID	TD	8/17/2106
2020 PO0465613164	KU	4	40 ACE	SP	CRE	ED,ID	TD	8/18/2106
2020 PO0782915633	F	7	20 ACE	SP	CRE		V	8/19/2106
2020 PO0792316396	KU	4	45 ACE	SP	CCA		V	8/20/2106

2020 PO0809516662	KU	4	45 ACE	SP	CCA		V	8/21/2106
2020 PO0826716928	KU	4	45 ACE	SP	CCA		V	8/22/2106
2020 PO0819215835	F	4	40 ACE	SP	CRE	ED,EP,ID	V	8/23/2106
2020 PO0825416015	KU	5	35 ACE	SP	CCA		V	8/24/2106
2020 PO0884515405	KU	4	40 ACE	SP	CCA		V	8/25/2106
2020 PO0899015794	KU	4	40 ACE	SP	CCA		V	8/26/2106
2020 PO0817915595	KU	4	40 ACE	SP	CRE	ID	BD	8/27/2106
2020 PO5372397338	KU	4	45E BRN	SP	CRE	ID	BD	8/28/2106
2020 PO5403396923	KU	4	45 BRN	SP	CRE	ID,IP	TD	8/29/2106
2020 PO5419997035A	F	6	30E BRN	SP	CRE		V	8/30/2106
2020 PO5419997035	KU	4	40 BRN	SP	CRE	ID,IP	TD	8/31/2106
2020 PO5413896866	KU	6	30 BRN	SP	CCA		V	9/1/2106
2020 PO5115437039	KU	4	40 BRO	SP	CCA		V	9/2/2106
2020 PO5126037033	KU	4	45 BRO	SP	CCA		V	9/3/2106
2020 PO5126237102	F	4	40 BRO	SP	CCA		V	9/4/2106
2020 PO5114437105	F	4	40 BRO	SP	CRE		V	9/5/2106
2020 PO5179836951	KU	6	30 BRO	SP	CRE		V	9/6/2106
2020 PO5149534854	F	4	40 BRO	SP	CRE		V	9/7/2106
2020 PO5190737103	F	4	40 BRO	SP	CRE		V	9/8/2106
2020 PO4398040862	KU	3	45 BRO	SP	CCA		V	9/9/2106
2020 PO4385841029	KU	4	40 BRO	SP	CRE	ID,IP	BD	9/10/2106
2020 PO4364841161	KU	4	40 BRO	SP	CRE	ID,IP	BD	9/11/2106
2020 PO4336241455	KU	4	40 BRO	SP	CRE		V	9/12/2106
2020 PO4334241596	KU	6	30 BRO	SP	CRE		V	9/13/2106
2020 PO3595649158	KU	3	45 BRO	SP	CCA		V	9/14/2106
2020 PO3622449108	KU	3	45 BRO	SP	CRE	ID,IP	BD	9/15/2106
2020 PO3578349193	KU	3	45 BRO	SP	CCA		V	9/16/2106
2020 PO3559349229	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	9/17/2106
2020 PO3785148735	KU	4	40 BRO	SP	CCA		V	9/18/2106
2020 PO4889837465	F	4	40 BRO	SP	CRE		V	9/19/2106
2020 PO5212337057	F	4	40 BRO	SP	CCA		V	9/20/2106
2020 PO5089337048	KU	4	40 BRO	SP	CCA		V	9/21/2106
2020 PO5040837145	F	4	40 BRO	SP	CCA		V	9/22/2106
2020 PO5092137284	F	4	40 BRO	SP	CRE		V	9/23/2106
2020 PO3428502416	KU	3	45 BRN	SP	CCA		V	9/24/2106
2020 PO3430802198	KU	6	30 BRN	SP	CRE	ID,IP	TD	9/25/2106
2020 PO3424802169	KU	4	40 BRN	SP	CRE	ID,IP	TD	9/26/2106
2020 PO3429502110	KU	4	40 BRN	SP	CRE		V	9/27/2106
2020 PO3432502307	KU	6	30 BRN	SP	CRE	ID,IP	BD	9/28/2106
2020 PO3437102271	KU	4	40 BRN	SP	P	ID,IP	BD	9/29/2106
2020 PO2144800443	F	4	40 UNK	SP	CRE		V	9/30/2106
2020 PO2143800549	KU	3	55 UNK	SP	CCA		V	10/1/2106
2020 PO2146200536	KU	3	55 UNK	SP	CCA		V	10/2/2106
2020 PO5610845197	F	3	40 ACW	SP	S		V	10/3/2106
2020 PO3327452463	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	10/4/2106
2020 PO3340452480	KU	4	40 ACE	SP	CRE	ED,ID,IP	BD	10/5/2106
2020 PO3342252295	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	10/6/2106

2020 PO4438521337	KU	4	40 BRO	SP	A	ED,ID	TD	10/7/2106
2020 PO4415320832	KU	4	40 BRO	SP	CCA	ED	T	10/8/2106
2020 PO6018439550	C	3	45 ACW	SP	CCA		V	10/9/2106
2020 PO3358252444	KU	4	40 ACE	SP	CRE	ED,ID	TD	10/10/2106
2020 PO3373652574	KU	4	40 ACE	SP	CRE	ED,ID	TD	10/11/2106
2020 PO5604245360	KU	4	40 ACW	SP	S		V	10/12/2106
2020 PO5619445209	KU	4	45 ACW	SP	CRE	ED,ID,IP	BD	10/13/2106
2020 PO5599545414	KU	2	50 ACW	SP	S		V	10/14/2106
2020 PO5593245353	KU	4	40 ACW	SP	CRE	ED,ID,RB,SRC	X	RP1 10/15/2106
2020 PO4400720547	KU	4	40 BRO	SP	CRE	ED,ID	TD	10/16/2106
2020 PO3386152582	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	10/17/2106
2020 PO3401252593	KU	4	40 ACE	SP	CRE	ED,ID	TD	10/18/2106
2020 PO3417152604	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	10/19/2106
2020 PO3430052582	KU	4	45 ACE	SP	CRE	ED,ID,IP	TD	10/20/2106
2020 PO3354352557	KU	3	45 ACE	SP	CCA		V	10/21/2106
2020 PO3249251789	F	4	40 ACE	SP	P		V	10/22/2106
2020 PO6012439617	C	3	45 ACW	ST	CCA		V	10/23/2106
2020 PO6018139759	KU	4	40 ACW	SP	CRE	ID	BD	10/24/2106
2020 PO6004839667	C	3	45 ACW	ST	CCA		V	10/25/2106
2020 PO6021239680	C	3	45 ACW	ST	CCA		V	10/26/2106
2020 PO6015239607	KU	4	40 ACW	SP	CRE	ID	BD	10/27/2106
2020 PO5506845901	KU	4	40 ACW	SP	CRE	ED,ID	TD	10/28/2106
2020 PO5549845637	KU	6	30 ACW	SP	CRE	ED,ID	BD	10/29/2106
2020 PO4399120717	F	6	30 BRO	SP	CRE		V	10/30/2106
2020 PO4314221035	KU	4	40 BRO	SP	CRE	ED,ID	TD	10/31/2106
2020 PO4377620511	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	11/1/2106
2020 PO6078038898	KU	4	40 ACW	SP	CRE	ED,ID	TD	11/2/2106
2020 PO6031139435	KU	4	40 ACW	SP	CRE	ED,ID	TD	11/3/2106
2020 PO6057339158	KU	4	40 ACW	SP	CRE	ED,ID	TD	11/4/2106
2020 PO5529245716	KU	6	30 ACW	SP	CRE	ED,ID	TD	11/5/2106
2020 PO5538945801	KU	4	45 ACW	SP	CRE	ED,ID	TD	11/6/2106
2020 PO5524845577	KU	4	45 ACE	SP	CCA	ED	T	11/7/2106
2020 PO5520245562	KU	6	30 ACE	SP	CRE	ED,ID	TD	11/8/2106
2020 PO5541246488	KU	6	30 ACE	SP	CCA		V	11/9/2106
2020 PO5511945952	KU	3	45 ACE	SP	CCA		V	11/10/2106
2020 PO5507845991	KU	5	35 ACE	SP	CCA		V	11/11/2106
2020 PO5510346114	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	11/12/2106
2020 PO5530946150	KU	4	45 ACE	SP	CRE	ED,ID	BD	11/13/2106
2020 PO5512346160	KU	6	30 ACE	SP	CCA		V	11/14/2106
2020 PO5552846186	KU	3	45 ACE	SP	CRE	ED,ID	BD	11/15/2106
2020 PO5543946268	KU	4	45 ACE	SP	CRE	ED,ID	TD	11/16/2106
2020 PO5532346387	KU	3	45 ACE	SP	CCA		V	11/17/2106
2020 PO5554146356	KU	5	35 ACE	SP	CCA		V	11/18/2106
2020 PO5563246524	F	4	45 ACE	SP	P		V	11/19/2106
2020 PO5554746392	F	4	45 ACE	SP	P		V	11/20/2106
2020 PO6121147496	KU	4	40 ACE	SP	CRE	ED,ID	TD	11/21/2106
2020 PO7588339621	KU	6	30 OTH	SP	CRE		V	11/22/2106

2020 PO4666688034-A	LGE	4	35 BRN	SP	A		ED,ID		TD	11/23/2106
2020 PO3574189409	F	4	40 XXX	SP	CRE				V	11/24/2106
2020 PO3565389343	KU	4	40 XXX	SP	CCA				V	11/25/2106
2020 PO4686388161	LGE	3	45 BRN	SP	A		ED,ID		BD	11/26/2106
2020 PO4686188141	LGE	3	45 BRN	SP	A		ED,ID		BD	11/27/2106
2020 PO4686088131	LGE	4	45 BRN	SP	CRE		ED,ID		BD	11/28/2106
2020 PO6204017732	KU	6	30 XXX	SP	CRE		ED,ID		TD	11/29/2106
2020 PO6217517710	KU	5	40 BRN	SP	CRE		ED,ID		TD	11/30/2106
2020 PO4685488128	LGE	6	25 BRN	SP	CRE		ED,ID		TD	12/1/2106
2020 PO4685588068	LGE	4	40 BRN	SP	A		ED,ID		BD	12/2/2106
2020 P086323-37959A	ODP	5	35 BRO	SP	P				V	12/3/2106
2020 PO8596838213	ODP	5	35 BRO	SP	CRE		ED,ID		TD	12/4/2106
2020 PO8620738137	ODP	4	40 BRO	SP	CRE		ED,ID		TD	12/5/2106
2020 PO6224017936	KU	3	50 BRN	SP	CCA				V	12/6/2106
2020 PO6270517600	KU	4	45 KOP	SP	CRE		ED,ID		TD	12/7/2106
2020 PO6244217780	KU	4	45 KOP	SP	CRE		ED,ID		TD	12/8/2106
2020 PO4682488062	LGE	4	40 BRN	SP	CCA				V	12/9/2106
2020 PO6236118993	KU	4	45 BRN	SP	CCA				V	12/10/2106
2020 PO6292418385	KU	4	40 BRN	SP	CCA				V	12/11/2106
2020 6250418220a	KU	3	45 BRN	SP	CCA				V	12/12/2106
2020 6250418220a	KU	3	45 BRN	SP	CCA				V	12/13/2106
2020 PO6250418220	KU	2	50 BRN	SP	CCA				V	12/14/2106
2020 PO6243017700	KU	5	35 XXX	SP	CCA				V	12/15/2106
2020 PO1707219599	ODP	4	45 BRO	SP	CRE		ID		BD	12/16/2106
2020 PO1789819731	ODP	4	40 BRO	SP	CRE				V	12/17/2106
2020 PO1761919913	ODP	2	55 BRO	SP	CCA				V	12/18/2106
2020 PO1744619714	ODP	2	60 BRN	SP	CRE		ID		BD	12/19/2106
2020 PO4682688080	LGE	4	40 BRN	SP	A		ED,ID		BD	12/20/2106
2020 PO4682788092	LGE	4	35 BRN	SP	A		ED,ID		BD	12/21/2106
2020 PO4685788098	LGE	3	45 BRN	SP	CCA				V	12/22/2106
2020 PO1733120184	ODP	4	45 BRN	SP	CCA				V	12/23/2106
2020 PO1761720233	ODP	4	40 BRN	SP	CRE		ID		BD	12/24/2106
2020 PO1781519965	ODP	2	55 BRO	SP	CCA				V	12/25/2106
2020 PO7525440088	KU	4	40 OTH	SP	CRE		ID		TD	12/26/2106
2020 PO6248218419	KU	5	40 XXX	SP	CRE		ED,ID		TD	12/27/2106
2020 PO4676188061	LGE	4	35 BRN	SP	CCA				V	12/28/2106
2020 PO4676988064	LGE	4	40 BRN	SP	A		ED,ID		BD	12/29/2106
2020 PO7525540647	KU	6	30 OTH	SP	CRE		ID		TD	12/30/2106
2020 PO7531240695	KU	4	40 OTH	SP	CRE		ID		TD	12/31/2106
2020 PO4677888067	LGE	4	40 BRN	SP	CRE		ED,HH,ID		BX	1/1/2107
2020 PO4881909916	KU	4	40 BRO	SP	CRE				V	1/2/2107
2020 PO4859010011	KU	4	40 BRO	SP	CRE				V	1/3/2107
2020 PO4846910064	KU	4	40 BRO	SP	CRE				V	1/4/2107
2020 PO4871009960	KU	4	40 BRO	SP	CRE				V	1/5/2107
2020 PO4842010063	KU	6	30 BRO	SP	CRE				V	1/6/2107
2020 PO4852310329	KU	4	40 BRO	SP	CRE				V	1/7/2107
2020 PO4865810271	KU	4	40 BRO	SP	CRE				V	1/8/2107

2020 PO4877310222	KU	4	40 BRO	SP	CRE		V	1/9/2107
2020 PO4887910179	KU	4	40 BRO	SP	CRE		V	1/10/2107
2020 PO4892610298	KU	4	40 BRO	SP	CRE		V	1/11/2107
2020 PO4679188066	LGE	4	35 BRN	SP	CCA		V	1/12/2107
2020 PO3487988903	KU	4	40 XXX	SP	CCA	ED	T	1/13/2107
2020 PO3491488917	KU	4	40 XXX	SP	CRE	ID	TD	1/14/2107
2020 PO3501288752	KU	4	40 XXX	SP	CRE	ID	TD	1/15/2107
2020 PO3485288657	KU	4	40 XXX	SP	CRE	ID	TD	1/16/2107
2020 PO3499788440	KU	4	40 XXX	SP	CRE	ID	TD	1/17/2107
2020 PO3512888244	KU	4	40 XXX	SP	CRE	ID	TD	1/18/2107
2020 PO3476388799	KU	4	40 XXX	SP	CRE	ID	TD	1/19/2107
2020 PO3468888561	KU	4	40 XXX	SP	CCA		V	1/20/2107
2020 PO3464888611	KU	4	40 XXX	SP	CCA		V	1/21/2107
2020 PO4680488080	LGE	4	35 BRN	SP	P	ED,ID	BD	1/22/2107
2020 PO3897193537	LGE	3	45 BRN	SP	CCA		V	1/23/2107
2020 PO4681588080	LGE	4	35 BRN	SP	CCA		V	1/24/2107
2020 PO7504340867	KU	4	40 OTH	SP	CRE	ID	TD	1/25/2107
2020 PO7518540683	KU	4	40 OTH	SP	CRE	ID	TD	1/26/2107
2020 PO4835010111	KU	4	40 BRO	SP	CRE		V	1/27/2107
2020 PO4827510102	KU	6	30 BRO	SP	CRE		V	1/28/2107
2020 PO7514141281	KU	4	40 OTH	SP	CRE		V	1/29/2107
2020 PO7525741229	KU	4	40 OTH	SP	CRE	ID	TD	1/30/2107
2020 PO7512241042	KU	4	45 OTH	SP	CRE	ID	TD	1/31/2107
2020 PO5567643089	F	3	40 ACW	SP	S		V	2/1/2107
2020 PO5582143218	KU	3	45 ACW	SP	CCA		V	2/2/2107
2020 PO5580243203	KU	3	40 ACW	SP	P	ED,ID,IP	BD	2/3/2107
2020 PO5546842934	KU	4	40 ACW	SP	S		V	2/4/2107
2020 PO5541843049	KU	4	45 ACW	SP	S		V	2/5/2107
2020 PO5602843663	KU	2	50 ACW	SP	CRE	ED,ID	TD	2/6/2107
2020 PO5577643942	KU	2	50 ACW	SP	CRE	ED,ID,IP	TD	2/7/2107
2020 PO5577943816	KU	5	35 ACW	SP	S		V	2/8/2107
2020 PO5577643942	KU	4	40 ACW	SP	S		V	2/9/2107
2020 PO5589243809	KU	2	50 ACW	SP	CRE	ED,ID,IP	TD	2/10/2107
2020 PO5519044695	F	4	40 ACW	SP	CRE		V	2/11/2107
2020 PO5510044778	F	4	40 ACW	SP	CRE		V	2/12/2107
2020 PO5520544911	F	4	40 ACW	SP	CRE		V	2/13/2107
2020 PO5513244928	KU	5	30 ACW	SP	S		V	2/14/2107
2020 PO4677288088	LGE	4	40 BRN	SP	CRE	ED,ID	TD	2/15/2107
2020 P5593245353I	KU	6	30 ACW	ST	CCA		V	2/16/2107
2020 PO4677488106	LGE	4	35 BRN	SP	CRE	ED,ID	BD	2/17/2107
2020 PO3856693667	LGE	4	40 BRN	SP	CCA		V	2/18/2107
2020 PO7494441369	KU	4	40 OTH	SP	CRE	ID	TD	2/19/2107
2020 PO7542641441	KU	5	35 OTH	SP	CRE	ID	TD	2/20/2107
2020 PO5357213384	KU	4	40 BRO	SP	A		V	2/21/2107
2020 PO4676588100	LGE	4	40 BRN	SP	CRE	ED,ID,IP	BD	2/22/2107
2020 PO7536641824	F	4	40 OTH	SP	P		V	2/23/2107
2020 PO7536841984	KU	4	40 OTH	SP	CCA		V	2/24/2107

2020 PO7550241625	KU	4	40 OTH	SP	CCA			V		2/25/2107
2020 PO7480341667	KU	5	35 OTH	SP	CRE		ID	BD		2/26/2107
2020 PO7540941750	KU	4	40 OTH	SP	CCA			V		2/27/2107
2020 PO7454141660	KU	4	40 OTH	SP	CCA			V		2/28/2107
2020 PO7486141820	KU	4	40 OTH	SP	CCA			V		3/1/2107
2020 PO7448641772	KU	6	30 OTH	SP	CRE		ID	TD		3/2/2107
2020 PO5354613315	KU	4	40 BRO	SP	CRE			V		3/3/2107
2020 PO5350213204	KU	4	40 BRO	SP	CRE			V		3/4/2107
2020 PO5346213095	KU	3	45 BRO	SP	A			V		3/5/2107
2020 PO5593245353H	KU	6	30 ACW	ST	CCA			V		3/6/2107
2020 PO5574744922	KU	6	30 ACW	SP	CRE		ED,EP,ID,MD,RB	BX	RR	3/7/2107
2020 PO5537645015	KU	5	35 ACW	SP	S			V		3/8/2107
2020 PO5535445101	F	4	40 ACW	SP	CRE			V		3/9/2107
2020 PO5533544600	KU	4	45 ACW	SP	CRE		ED,ID	BD		3/10/2107
2020 PO3914747172	F	3	45 ACE	SP	CCA			V		3/11/2107
2020 PO3912946838	F	4	40 ACE	SP	CCA			V		3/12/2107
2020 PO3918246823	KU	3	45 ACE	SP	CCA			V		3/13/2107
2020 PO3911946333	F	4	40 ACE	SP	CRE		ED,ID	V		3/14/2107
2020 PO3429548154	KU	4	40 ACE	SP	CRE		ED,ID	TD		3/15/2107
2020 PO3442748413	KU	4	40 ACE	SP	CRE		ED,ID,IP	TD		3/16/2107
2020 PO5937540177	KU	4	40 BRN	SP	CRE		ED,ID	TD		3/17/2107
2020 PO5953640014	KU	4	40 BRN	SP	CRE		ED,ID	TD		3/18/2107
2020 PO5977639641	KU	3	45 BRN	SP	CCA			V		3/19/2107
2020 PO6022438202	KU	4	40 BRN	SP	CRE		ED,ID	TD		3/20/2107
2020 PO5969239842	KU	4	40 BRN	SP	CRE		ED,ID	TD		3/21/2107
2020 PO5947738436	KU	3	45 BRN	SP	CRE		ED,ID	TD		3/22/2107
2020 PO5341712977	KU	3	45 BRO	SP	CRE		ID,IP	BD		3/23/2107
2020 PO5940438538	C	4	40 BRN	SP	CRE			V		3/24/2107
2020 PO5945238410	KU	4	40 BRN	SP	CRE		ED,ID	BD		3/25/2107
2020 PO5977438328	KU	4	40 BRN	SP	S			V		3/26/2107
2020 PO6215040239	KU	3	45 BRN	SP	S			V		3/27/2107
2020 PO6058340232	KU	4	45 BRN	SP	CRE		ED,ID	TD		3/28/2107
2020 PO6212041157	KU	3	45 BRN	SP	S			V		3/29/2107
2020 PO6118740224	KU	3	45 BRN	SP	S			V		3/30/2107
2020 PO6165440690	KU	3	45 BRN	SP	S			V		3/31/2107
2020 PO6155840251	KU	3	45 BRN	SP	S			V		4/1/2107
2020 PO6188740924	KU	3	45 BRN	SP	S			V		4/2/2107
2020 PO6075140227	KU	4	45 BRN	SP	CRE		ED,ID	TD		4/3/2107
2020 PO6270240219	KU	3	45 BRN	SP	S			V		4/4/2107
2020 PO6142040457	KU	3	45 BRN	SP	S			V		4/5/2107
2020 PO6186340252	KU	3	45 BRN	SP	S			V		4/6/2107
2020 PO5577644205	F	4	40 ACW	SP	S			V		4/7/2107
2020 PO5580844167	F	4	40 ACW	SP	S			V		4/8/2107
2020 PO5335812821	KU	4	40 BRO	SP	CCA			V		4/9/2107
2020 PO5332212710	KU	4	40 BRO	SP	CRE			V		4/10/2107
2020 PO5329612636	KU	4	40 BRO	SP	A			V		4/11/2107
2020 PO5326012518	F	4	40 BRO	SP	CRE			V		4/12/2107

2020 PO5318812288	F	4	40 BRO	SP	CRE		V		4/13/2107
2020 PO5315312168	F	3	45 BRO	SP	A		V		4/14/2107
2020 PO5312512043	F	4	40 BRO	SP	CRE		V		4/15/2107
2020 PO5596144181	F	4	40 ACW	SP	P		V		4/16/2107
2020 PO5403456477	KU	6	30 OTH	SP	CCA		V		4/17/2107
2020 PO5112811495	F	4	40 BRO	SP	CRE		V		4/18/2107
2020 PO5308811858	F	4	40 BRO	SP	CRE		V		4/19/2107
2020 PO5365555915	KU	4	40 OTH	SP	CRE	ID	TD		4/20/2107
2020 PO5386056430	KU	4	40 OTH	SP	CRE	ID	TD		4/21/2107
2020 PO5372556249	KU	4	40 OTH	SP	CRE	ID	TD		4/22/2107
2020 PO5348557223	KU	4	40 OTH	SP	CCA		V		4/23/2107
2020 PO5330556937	KU	4	40 OTH	SP	CCA		V		4/24/2107
2020 PO5516953485	KU	4	40 OTH	SP	CRE	ID	TD		4/25/2107
2020 PO5313656674	KU	4	40 OTH	SP	CRE	ID	TD		4/26/2107
2020 PO5615044199	F	4	40 ACW	SP	CRE		V		4/27/2107
2020 PO5635844254	F	4	40 ACW	SP	S		V		4/28/2107
2020 PO3458448727	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		4/29/2107
2020 PO5651744577	F	4	40 ACW	SP	CRE		V		4/30/2107
2020 PO5643744732	F	4	40 ACW	SP	CRE		V		5/1/2107
2020 PO5635744888	F	4	40 ACW	SP	CRE		V		5/2/2107
2020 PO5627545049	F	4	40 ACW	SP	CRE		V		5/3/2107
2020 PO3344448145	KU	4	40 ACE	SP	CRE	ED,ID,IP	TX	RR	5/4/2107
2020 PO3341148473	KU	6	30 ACE	SP	CRE	ED,ID	TD		5/5/2107
2020 PO5647144357	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		5/6/2107
2020 PO5655944502	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		5/7/2107
2020 40581 90700	KU	6	30 KOP	SP	S		V		5/8/2107
2020 PO4021189532	KU	5	45 KOP	SP	S		V		5/9/2107
2020 PO4019289558	KU	4	45 KOP	SP	S		V		5/10/2107
2020 PO4732588265	LGE	3	45 BRO	SP	P	ED,ID	BD		5/11/2107
2020 PO4733688276	LGE	4	35 BRO	SP	CCA		V		5/12/2107
2020 PO4025789590	F	4	40 KOP	SP	P		V		5/13/2107
2020 PO4656189157	LGE	5	25 BRO	SP	CRE	ED,ID,IP	TD		5/14/2107
2020 PO4654689144	LGE	5	25 BRO	SP	CRE		V		5/15/2107
2020 PO4702888338	LGE	4	40 BRN	SP	A	ED,ID	BD		5/16/2107
2020 PO4703388340	LGE	4	30 BRN	SP	P	ED,ID	BD		5/17/2107
2020 PO4702688334	LGE	4	35 BRN	SP	CRE	ED,ID	BD		5/18/2107
2020 PO6207315866	KU	4	40 XXX	SP	CRE	ED,ID	TD		5/19/2107
2020 PO6192615865	KU	4	40 BRN	SP	CCA		V		5/20/2107
2020 PO4663288830	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		5/21/2107
2020 PO4662788834	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		5/22/2107
2020 PO4703888371	LGE	4	40 BRN	SP	A	ED,ID	TD		5/23/2107
2020 PO4703388368	LGE	4	40 BRN	SP	A	ED,ID	TD		5/24/2107
2020 PO4704788352	LGE	4	40 BRN	SP	CRE	ED,ID	TD		5/25/2107
2020 PO4660788854	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD		5/26/2107
2020 PO6178115589	KU	4	40 XXX	SP	CRE	ED,ID	TD		5/27/2107
2020 PO6179015420	KU	4	40 XXX	SP	CRE	ED,ID	TD		5/28/2107
2020 PO4659788904	LGE	4	40 BRO	SP	P	ED	T		5/29/2107

2020 PO6125914740	F	4	40 XXX	SP	CRE		V			5/30/2107
2020 PO6144614753	KU	4	40 BRN	SP	CCA		V			5/31/2107
2020 PO6187814767	KU	5	30 XXX	SP	CRE	ID	BX	RP2		6/1/2107
2020 PO6167814674	KU	5	35 XXX	SP	CRE	ED,ID	TD			6/2/2107
2020 PO4731488323	LGE	4	40 BRO	SP	CRE	ED,ID	TD			6/3/2107
2020 PO4731888320	LGE	4	40 BRO	SP	A	ED,ID	TD			6/4/2107
2020 PO4733288306	LGE	4	30 BRO	SP	CRE		V			6/5/2107
2020 PO4733388309	LGE	4	30 BRO	SP	CRE		V			6/6/2107
2020 PO4733388308	LGE	3	45 BRO	SP	CCA		V			6/7/2107
2020 PO4017689736	F	4	40 KOP	SP	P		V			6/8/2107
2020 PO4009189894	F	4	40 KOP	SP	P		V			6/9/2107
2020 PO3998790039	F	4	40 KOP	SP	P		V			6/10/2107
2020 PO4003890265	KU	4	40 KOP	SP	S		V			6/11/2107
2020 PO4021190342	KU	4	40 KOP	SP	CRE	ID	BD			6/12/2107
2020 PO4034290402	KU	4	40 KOP	SP	S		V			6/13/2107
2020 PO3990190200	F	4	40 KOP	SP	P		V			6/14/2107
2020 PO3985390180	F	4	40 KOP	SP	CRE		V			6/15/2107
2020 PO3980890298	KU	6	35 KOP	SP	S		V			6/16/2107
2020 PO3977890372	KU	5	35 KOP	SP	A	ED,ID,SRC	TD			6/17/2107
2020 PO3983090392	F	4	40 KOP	SP	P		V			6/18/2107
2020 PO4043090757	F	4	40 KOP	SP	CRE		V			6/19/2107
2020 PO4017290648	F	4	40 KOP	SP	CRE		V			6/20/2107
2020 PO4704388417	LGE	4	40 BRN	SP	CRE	ED,ID	TD			6/21/2107
2020 PO4705388403	LGE	4	40 BRN	SP	A	ED,ID	TD			6/22/2107
2020 PO5994713020	KU	4	40 XXX	SP	CRE	ED,ID	TD			6/23/2107
2020 PO5977913225	KU	4	40 XXX	SP	CRE	ED,ID	TD			6/24/2107
2020 PO5940013229	KU	4	40 XXX	SP	CRE	ED,ID	TD			6/25/2107
2020 PO5939813368	KU	4	40 XXX	SP	CCA		V			6/26/2107
2020 PO4652388710	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD			6/27/2107
2020 PO4651988704	LGE	4	40 BRO	SP	P	ED	T			6/28/2107
2020 PO4654388724	LGE	4	40 BRO	SP	CRE	ED,EP,IP	TX	RR		6/29/2107
2020 PO4704688384	LGE	4	30 BRN	SP	CRE	ED,ID	BD			6/30/2107
2020 PO4704888379	LGE	4	40 BRN	SP	A	ED,ID	TD			7/1/2107
2020 PO4706088387	LGE	4	40 BRN	SP	A	ED,ID,IP	TD			7/2/2107
2020 PO4709788403	LGE	4	35 BRN	SP	CCA		V			7/3/2107
2020 PO4707688398	LGE	3	45 BRN	SP	CCA		V			7/4/2107
2020 PO3991690539	KU	4	40 KOP	SP	CRE	ED,ID	TD			7/5/2107
2020 PO3985290510	KU	4	40 KOP	SP	CRE	ED,ID	TD			7/6/2107
2020 PO3970690564	F	5	35 KOP	SP	S		V			7/7/2107
2020 PO3975090601	F	4	40 KOP	SP	P		V			7/8/2107
2020 PO4712188490	LGE	4	40 BRN	SP	CCA		V			7/9/2107
2020 PO4711088486	LGE	4	40 BRN	SP	CRE	ED,ID	BD			7/10/2107
2020 PO3948883211	KU	2	55 KOP	SP	CRE		V			7/11/2107
2020 PO3946583209	KU	2	65 KOP	SP	CRE		V			7/12/2107
2020 PO3950082773	KU	3	55 KOP	SP	CRE		V			7/13/2107
2020 PO3947882773	KU	3	65 KOP	SP	P		V			7/14/2107
2020 PO4232585535	KU	4	40 KOP	SP	CRE	ID	BD			7/15/2107

2020 PO7798160777	F	4	40 XXX	SP	A		V			7/16/2107
2020 PO7809460889	F	5	35 XXX	SP	CCA		V			7/17/2107
2020 PO7764961306	KU	3	45 XXX	SP	CCA		V			7/18/2107
2020 PO7793960879	F	1	20 XXX	SP	A		V			7/19/2107
2020 PO7784461078	KU	4	45 XXX	SP	CRE	ED,ID				7/20/2107
2020 PO7795360850	KU	3	45 XXX	SP	CCA		V			7/21/2107
2020 PO7775660695	KU	3	45 XXX	SP	CCA		V			7/22/2107
2020 PO7756060540	KU	3	45 XXX	SP	CCA		V			7/23/2107
2020 PO7736460385	KU	4	45 XXX	SP	CCA		V			7/24/2107
2020 PO7717660237	KU	3	45 XXX	SP	CCA		V			7/25/2107
2020 PO4189389604	KU	6	30 KOP	SP	S		V			7/26/2107
2020 PO4186589575	KU	2	45 KOP	SP	S		V			7/27/2107
2020 PO4183289684	KU	1	65 KOP	SP	CRE		V			7/28/2107
2020 PO4190289404	KU	4	35 KOP	SP	CRE	ED,ID,MD,SRC				7/29/2107
2020 PO4194889227	KU	4	35 KOP	SP	S		V			7/30/2107
2020 PO4199289035	KU	4	35 KOP	SP	S		V			7/31/2107
2020 PO4205788771	KU	3	45 KOP	SP	CRE		V			8/1/2107
2020 PO4212388501	KU	4	40 KOP	SP	S		V			8/2/2107
2020 PO4218988231	KU	3	45 KOP	SP	S		V			8/3/2107
2020 PO4239387873	KU	3	45 KOP	SP	CRE	ED,ID				8/4/2107
2020 PO8135763157	KU	5	35 XXX	SP	CCA		V			8/5/2107
2020 PO8147263250	KU	5	35 XXX	SP	CCA		V			8/6/2107
2020 PO8158763345	KU	5	35 XXX	SP	CCA		V			8/7/2107
2020 PO8171363444	KU	5	35 XXX	SP	CCA		V			8/8/2107
2020 PO8168563483	KU	5	35 XXX	SP	CCA		V			8/9/2107
2020 PO8179863567	KU	5	35 XXX	SP	CCA		V			8/10/2107
2020 PO8191063654	KU	5	35 XXX	SP	CCA		V			8/11/2107
2020 PO9405772280	KU	5	35 OTH	SP	CRE	ID				8/12/2107
2020 PO9395972423	KU	5	35 OTH	SP	CRE	ID				8/13/2107
2020 PO9394272273	KU	6	30 OTH	SP	CCA	ED				8/14/2107
2020 PO9391572397	KU	6	30 OTH	SP	CCA		V			8/15/2107
2020 PO8249364156	KU	3	45 XXX	SP	CCA		V			8/16/2107
2020 PO9211672384	KU	4	40 OTH	SP	CRE	ED,ID,SRC				8/17/2107
2020 PO8302364101	KU	4	40 XXX	SP	CCA		V			8/18/2107
2020 PO8309664175	KU	4	40 XXX	SP	CRE	ED,ID				8/19/2107
2020 PO9230672075	KU	3	45 OTH	SP	CRE	ED,ID,SRS				8/20/2107
2020 PO8288064512	KU	5	40 XXX	SP	CCA		V			8/21/2107
2020 PO9217572291	KU	4	40 OTH	SP	CRE	ED,ID,RB				8/22/2107
2020 PO9250972122	KU	4	40 OTH	SP	CRE	ED,HH,ID,RB				8/23/2107
2020 PO9242972063	KU	4	40 OTH	SP	CRE	ED,ID,SRS				8/24/2107
2020 PO9235172005	KU	5E	40E OTH	SP	CRE	ED,ID,SRC				8/25/2107
2020 PO9240871911	KU	5	35 OTH	SP	CRE	ED,ID,SRC				8/26/2107
2020 PO4274587496	KU	4	40 KOP	SP	CRE	ID				8/27/2107
2020 PO4340887544	KU	4	40 KOP	SP	S		V			8/28/2107
2020 PO4308387500	KU	5	35 KOP	SP	CRE	ED,ID,IP,SRC				8/29/2107
2020 PO8444965603	KU	4	40 XXX	SP	A	ED,ID				8/30/2107
2020 PO8421865404	KU	4	45 XXX	SP	CCA		V			8/31/2107

2020 PO8420265435	KU	4	40 XXX	SP	CCA		V		9/1/2107
2020 PO9251471780	KU	4	40 OTH	SP	CRE	ED,ID,SRC	TX	RR	9/2/2107
2020 PO9248571790	KU	4	40 OTH	SP	CRE	ED,ID,SRC	TX	RR	9/3/2107
2020 PO8465865748	KU	4	45 XXX	SP	CCA		V		9/4/2107
2020 PO8483965875	KU	4	40 XXX	SP	CRE	ED,ID	TD		9/5/2107
2020 PO8506366028	KU	4	45 XXX	SP	CRE	ED,ID	TD		9/6/2107
2020 PO4363987692	F	4	40 KOP	SP	P		V		9/7/2107
2020 PO4366187586	KU	4	45 KOP	SP	CRE	ED,ID	TD		9/8/2107
2020 PO4398387609	KU	4	40 KOP	SP	CRE	ED,ID	TD		9/9/2107
2020 PO4438787665	KU	4	40 KOP	DF	CRE	ED,ID	TD		9/10/2107
2020 PO4438487748	F	4	40 KOP	SP	S		V		9/11/2107
2020 PO4436787975	F	4	40 KOP	SP	CRE		V		9/12/2107
2020 PO9257071902	KU	6	30 OTH	SP	CRE	ED,ID,SRS	TD		9/13/2107
2020 PO9250771755	KU	4	40 OTH	SP	CCA		V		9/14/2107
2020 PO9255571660	F	4	40 OTH	SP	CRE		V		9/15/2107
2020 PO9178072159	F	4	40 OTH	SP	CRE		V		9/16/2107
2020 PO9161072006	F	4	40 OTH	SP	P		V		9/17/2107
2020 PO9148071891	F	3	45 OTH	SP	CRE		V		9/18/2107
2020 PO4669088735	LGE	2	55 BRN	SP	A	ED,ID	BD		9/19/2107
2020 PO4676888744	LGE	2	55 BRN	SP	CRE	ED,ID	BD		9/20/2107
2020 PO3800400075	LGE	4	45 BRN	SP	CCA		V		9/21/2107
2020 PO4463487688	KU	3	50 KOP	SP	CRE	ED,ID,MD,SRC	TX	RR	9/22/2107
2020 PO4494987691	F	4	40 KOP	SP	P		V		9/23/2107
2020 PO4506387697	KU	4	45 KOP	SP	S		V		9/24/2107
2020 PO4539488530	F	4	40 KOP	SP	P		V		9/25/2107
2020 PO4551688635	F	4	40 KOP	DF	CRE		V		9/26/2107
2020 PO4572788542	F	4	40 KOP	SP	CRE		V		9/27/2107
2020 PO4584188732	F	4	40 KOP	SP	A		V		9/28/2107
2020 PO4562388783	F	4	40 KOP	SP	CRE		V		9/29/2107
2020 PO0487180006	KU	4	45 XXX	SP	CRE	ED,ID	TD		9/30/2107
2020 PO0493579848	KU	3	45 XXX	SP	CCA		V		10/1/2107
2020 PO0500779736	KU	3	50 XXX	SP	CRE	ED,ID	TD		10/2/2107
2020 PO0512979546	KU	4	45 XXX	SP	CRE	ED,ID	TD		10/3/2107
2020 PO0130377372	KU	4	40 XXX	SP	CRE		V		10/4/2107
2020 PO91133171747	F	4	40 OTH	SP	CRE		B		10/5/2107
2020 PO9117671621	F	4	40 OTH	SP	CRE		B		10/6/2107
2020 PO9102871498	F	4	40 OTH	SP	CRE		V		10/7/2107
2020 PO9088171379	F	4	40 OTH	SP	CRE		V		10/8/2107
2020 PO9072871259	F	4	40 OTH	SP	CRE		V		10/9/2107
2020 PO9057871137	F	4	40 OTH	SP	CRE		V		10/10/2107
2020 PO9042771014	F	4	40 OTH	SP	CRE		B		10/11/2107
2020 PO4673788772	LGE	4	35 BRN	SP	CCA		V		10/12/2107
2020 PO4673888771	LGE	2	55 BRN	SP	CCA		V		10/13/2107
2020 PO4821887958	LGE	3	50 BRO	SP	CCA		V		10/14/2107
2020 PO0108375650	KU	2	45 XXX	SP	CRE		V		10/15/2107
2020 PO4822687967	LGE	3	50 BRO	SP	CCA		V		10/16/2107
2020 PO3819200133	F	1	50 BRN	SP	CCA		V		10/17/2107

2020 PO4673388731	F		3	45 BRN	SP	CCA		V	10/18/2107
2020 PO4674088721	F		4	40 BRN	SP	A		V	10/19/2107
2020 PO4675588700	F		4	40 BRN	SP	A		V	10/20/2107
2020 PO4676288690	F		4	40 BRN	SP	CCA		V	10/21/2107
2020 PO4677088680	F		4	40 BRN	SP	A		V	10/22/2107
2020 PO4677788669	F		3	45 BRN	SP	A		V	10/23/2107
2020 PO4678588658	F		3	45 BRN	SP	A		V	10/24/2107
2020 PO8968770401	F	2E	60E	OTH	SP	CCA		V	10/25/2107
2020 PO4821387956	F		4	30 BRO	SP	CRE		V	10/26/2107
2020 PO4820787945	LGE		3	50 BRO	SP	CRE	ED	TD	10/27/2107
2020 PO4819187932	F		4	35 BRO	SP	CRE		V	10/28/2107
2020 PO4819987936	LGE		3	50 BRO	SP	CRE	ED	TD	10/29/2107
2020 PO4820387944	F		4	30 BRO	SP	CRE		V	10/30/2107
2020 PO4818987925	LGE		3	50 BRO	SP	CCA		V	10/31/2107
2020 PO4817887912	LGE		3	50 BRO	SP	CRE	ED	TD	11/1/2107
2020 PO4817787917	F		4	35 BRO	SP	CRE		V	11/2/2107
2020 PO4817387911	F		4	30 BRO	SP	CRE		V	11/3/2107
2020 PO4817187904	LGE		3	50 BRO	SP	CRE	ED	BD	11/4/2107
2020 PO4816387895	LGE		3	50 BRO	SP	CCA		V	11/5/2107
2020 PO4816187897	F	UNK		25 BRO	SP	CRE		V	11/6/2107
2020 PO8984970536	F	2E	60E	OTH	SP	CCA		V	11/7/2107
2020 PO8988670568	F		2	60 OTH	SP	CRE		V	11/8/2107
2020 PO9003970698	F		2	60 OTH	SP	CCA		V	11/9/2107
2020 PO4679488646	F		3	50 BRN	SP	CRE		V	11/10/2107
2020 PO4679588645	F		3	50 BRN	SP	CRE		V	11/11/2107
2020 PO9015770793	F		3	50 OTH	SP	CCA		V	11/12/2107
2020 PO9026770886	F		3	45 OTH	SP	CRE		V	11/13/2107
2020 PO4680388633	F		3	45 BRN	SP	A		V	11/14/2107
2020 PO4679888630	LGE		4	40 BRN	SP	A	ED,JD	TD	11/15/2107
2020 PO4680988625	F		3	45 BRN	SP	A		V	11/16/2107
2020 PO4681588615	F		4	40 BRN	SP	CRE		V	11/17/2107
2020 PO4682288606	F		4	40 BRN	SP	CRE		V	11/18/2107
2020 PO4682388597	F		4	40 BRN	SP	A		V	11/19/2107
2020 PO4683588581	F		3	45 BRN	SP	A		V	11/20/2107
2020 PO4683988584	F		4	40 BRN	SP	A		V	11/21/2107
2020 PO4684388576	F		4	40 BRN	SP	A		V	11/22/2107
2020 PO4683888574	F		3	45 BRN	SP	A		V	11/23/2107
2020 PO3937398277	LGE		3	45 BRN	SP	S		V	11/24/2107
2020 PO4684288559	F		3	45 BRN	SP	CCA		V	11/25/2107
2020 PO4801287836	LGE	UNK		95 BRO	ST	P		V	11/26/2107
2020 PO4803287834	LGE	UNK		95 BRO	ST	P		V	11/27/2107
2020 PO4805387832	LGE	UNK		50 BRO	ST	P		V	11/28/2107
2020 PO4807687829	LGE	UNK		95 BRO	ST	CRE		V	11/29/2107
2020 PO4833787783	LGE		4	40 BRO	SP	CCA		V	11/30/2107
2020 PO4833687785	LGE		4	35 BRO	SP	CRE	ED	TD	12/1/2107
2020 PO4833687786	LGE		4	40 BRO	SP	CRE	ED	TD	12/2/2107
2020 PO4833387799	LGE	UNK		95 BRO	ST	P		V	12/3/2107

2020 PO4833487772	LGE	4	35 BRO	SP	CRE	ED	TD	12/4/2107
2020 PO4832587769	LGE	4	35 BRO	SP	CRE	ED	TD	12/5/2107
2020 PO4831587784	LGE	4	35 BRO	SP	CRE	ED	TD	12/6/2107
2020 PO4831687789	LGE	4	35 BRO	SP	CRE	ED	TD	12/7/2107
2020 PO4672988431	F	4	40 BRN	SP	CRE		V	12/8/2107
2020 PO4789987931	F	4	40 BRO	SP	CCA		V	12/9/2107
2020 PO4784188027	LGE	4	40 BRO	SP	CCA		V	12/10/2107
2020 PO4784788025	F	4	40 BRO	SP	CCA		V	12/11/2107
2020 PO4786388031	F	4	40 BRO	SP	CCA		V	12/12/2107
2020 PO4786588026	F	4	40 BRO	SP	CCA		V	12/13/2107
2020 PO6052946834	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	12/14/2107
2020 PO6026247012	KU	3	50 OTH	SP	CRE	ED,SRS	TD	12/15/2107
2020 PO9520674105	KU	6	30 XXX	SP	CCA		V	12/16/2107
2020 PO9512574225	KU	4	40 XXX	SP	CRE	ID	TD	12/17/2107
2020 PO9476374300	KU	4	40 XXX	SP	CRE	ID	TD	12/18/2107
2020 PO5930647397	KU	4	40 OTH	SP	CRE	ED,SRS	TD	12/19/2107
2020 PO4788288038	F	4	40 BRO	SP	CCA		V	12/20/2107
2020 PO4790188022	F	4	40 BRO	SP	CCA		V	12/21/2107
2020 PO4652488577	LGE	4	30 BRN	SP	CRE	ED,ID	TD	12/22/2107
2020 PO4652888567	LGE	4	30 BRN	SP	A	ED,ID	BD	12/23/2107
2020 PO4790788006	F	4	40 BRO	SP	CCA		V	12/24/2107
2020 PO4792987947	F	4	40 BRO	SP	CCA		V	12/25/2107
2020 PO4792487962	F	3	45 BRO	SP	CCA		V	12/26/2107
2020 PO4791887976	F	4	40 BRO	SP	CCA		V	12/27/2107
2020 PO4791287992	F	4	40 BRO	SP	CCA		V	12/28/2107
2020 PO4790387922	F	4	40 BRO	SP	CRE		V	12/29/2107
2020 PO4793687929	F	4	40 BRO	SP	CRE		V	12/30/2107
2020 PO5962447318	KU	5	30 OTH	SP	CRE	ED,ID,SRS	TD	12/31/2107
2020 PO5977747267	KU	5	35 OTH	SP	CRE	ED,SRS	TD	1/1/2108
2020 PO3917267744	KU	2	65 BRN	SP	CRE		V	1/2/2108
2020 PO4657588493	F	4	40 BRN	SP	CRE		V	1/3/2108
2020 PO4658788465	LGE	4	30 BRN	SP	A	ED,ID	TD	1/4/2108
2020 PO4658288483	F	4	40 BRN	SP	CRE		V	1/5/2108
2020 PO4658688476	F	4	40 BRN	SP	A		V	1/6/2108
2020 PO4659188469	F	4	40 BRN	SP	CRE		V	1/7/2108
2020 PO3927770026	KU	1	75 BRN	SP	CRE		V	1/8/2108
2020 PO5878447557	KU	4	40 OTH	SP	CRE	ED,SRS	TD	1/9/2108
2020 PO3932970023	KU	2	65 BRN	SP	CRE		V	1/10/2108
2020 PO3910169994	KU	4	40 BRN	SP	CCA		V	1/11/2108
2020 PO4818188395	LGE	4	40 BRO	SP	CRE	ED	TD	1/12/2108
2020 PO4817588394	LGE	UNK	45 BRO	SP	CRE	ED	TD	1/13/2108
2020 PO5790547775	KU	5	40 OTH	SP	CRE	ED,SRS	TD	1/14/2108
2020 PO5819347688	KU	4	40 OTH	SP	CRE	ED,SRS	TD	1/15/2108
2020 PO4724887999	F	4	40 BRO	SP	CRE		V	1/16/2108
2020 PO4719987969	LGE	3	45 BRO	SP	CRE		BD	1/17/2108
2020 PO4720687984	F	3	45 BRO	SP	CCA		V	1/18/2108
2020 PO4720487996	F	3	45 BRO	SP	CCA		V	1/19/2108

2020 PO4720288006	F		3	45 BRO	SP	CCA			V	1/20/2108	
2020 PO4721788003	F		3	45 BRO	SP	CCA			V	1/21/2108	
2020 PO4723788036	F		4	40 BRO	SP	CRE			V	1/22/2108	
2020 PO4724488034	F		4	40 BRO	SP	CRE			V	1/23/2108	
2020 PO9278972598	KU		5	40 OTH	SP	CRE		ED,ID,SRS	TD	1/24/2108	
2020 PO9288572665	KU	5E	40E	OTH	SP	CRE		ED,ID,SR	TX	RR	1/25/2108
2020 PO7280216999	KU		4	40 BRN	SP	CCA			V	1/26/2108	
2020 PO7275617357	KU		4	40 BRN	SP	CCA			V	1/27/2108	
2020 PO4357892436	KU		5	35 KOP	SP	CRE		ED,ID	TD	1/28/2108	
2020 PO4361192349	KU		4	40 KOP	SP	CRE		ED,ID	TD	1/29/2108	
2020 PO4343292270	KU		5	35 KOP	DF	CRE		ED,ID	TD	1/30/2108	
2020 PO4345092057	KU		4	40 KOP	SP	CRE		ED,ID	TD	1/31/2108	
2020 PO4693088597	LGE		4	35 BRN	SP	A		ED,ID	TD	2/1/2108	
2020 PO4691988587	LGE		4	25 BRN	SP	A		ED,ID,SR	TX	RR	2/2/2108
2020 PO4690788579	LGE		4	25 BRN	SP	A		ED,ID	TD	2/3/2108	
2020 PO4821988082	LGE		4	40 BRO	SP	CRE		ED	TD	2/4/2108	
2020 PO4819588107	LGE		4	40 BRO	SP	CRE		ED	BD	2/5/2108	
2020 PO4818488098	LGE		4	40 BRO	SP	CRE		ED	BD	2/6/2108	
2020 PO4817588108	LGE		3	50 BRO	SP	CRE		ED	BD	2/7/2108	
2020 PO5281093919	LGE		3	45 BRO	SP	CCA			V	2/8/2108	
2020 PO4816188078	F	UNK		45 BRO	SP	CRE			V	2/9/2108	
2020 PO4097591649	KU		4	40 KOP	SP	CRE		ID	BD	2/10/2108	
2020 PO4090491816	F		4	40 KOP	SP	CRE			V	2/11/2108	
2020 PO4116691381	KU		3	45 KOP	SP	CCA			V	2/12/2108	
2020 PO4069790895	KU		4	40 KOP	SP	S			V	2/13/2108	
2020 PO4067590873	KU		4	40 KOP	SP	CRE		ED,ID	TD	2/14/2108	
2020 PO4113091450	KU		4	40 KOP	SP	CRE		ID	BD	2/15/2108	
2020 PO4815088069	F	UNK		25 BRO	SP	A			VX	RP2	2/16/2108
2020 PO3992198422	LGE		4	35 BRN	SP	CCA			V	2/17/2108	
2020 PO3980098334	LGE		4	35 BRN	SP	CCA			V	2/18/2108	
2020 PO4828987990	LGE		4	40 BRO	SP	CRE		ED,ID,IP	TD	2/19/2108	
2020 PO4828387998	LGE		4	40 BRO	SP	CRE		ED	TD	2/20/2108	
2020 PO4687488575	LGE		4	35 BRN	SP	P			T	2/21/2108	
2020 PO4686088566	LGE		4	40 BRN	SP	P			T	2/22/2108	
2020 PO4684988556	LGE		4	40 BRN	SP	A		ED,ID	TD	2/23/2108	
2020 PO4684688543	F		3	45 BRN	SP	CCA			V	2/24/2108	
2020 PO4827588012	LGE		4	40 BRO	SP	CRE		ED	TD	2/25/2108	
2020 PO4827088017	LGE		4	35 BRO	SP	CRE		ED	TD	2/26/2108	
2020 PO4123990107	KU		4	45 KOP	SP	CRE		ED,ID	TD	2/27/2108	
2020 PO4825987851	LGE		4	40 BRO	SP	CCA			V	2/28/2108	
2020 PO4826187866	LGE		4	40 BRO	SP	P		SRC	T	2/29/2108	
2020 PO4826587891	LGE		4	40 BRO	SP	CCA			V	3/1/2108	
2020 PO4826887914	LGE	UNK		45 BRO	SP	CCA			V	3/2/2108	
2020 PO4365602586	KU		4	35 BRO	SP	CCA			V	3/3/2108	
2020 PO4381402949	KU		4	40 BRO	SP	CRE		ID,IP	BD	3/4/2108	
2020 PO4379303161	KU		4	45 BRO	SP	CRE		ED,ID	TD	3/5/2108	
2020 PO5556844358	KU		6	30 ACW	SP	CRE		ED,ID	TD	3/6/2108	

2020 PO5587444563	F	5	40 ACW	SP	P		V	3/7/2108
2020 PO5572144491	KU	6	30 ACW	SP	CRE	ED,ID	TD	3/8/2108
2020 PO5606944585	KU	6	30 ACW	SP	CRE	ED,ID	TD	3/9/2108
2020 PO4378203273	KU	4	40 BRO	SP	CCA		V	3/10/2108
2020 PO3768947147	F	4	40 ACE	SP	CRE	ED,HH,ID,RB	VX	RP1 3/11/2108
2020 PO3750147234	F	4	40 ACE	SP	CRE		V	3/12/2108
2020 PO3728247429	F	4	40 ACE	SP	CRE		V	3/13/2108
2020 PO3723647489	KU	6	30 ACE	SP	CRE	ED,ID,IP	BD	3/14/2108
2020 PO3720747410	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	3/15/2108
2020 PO3728247211	F	4	40 ACE	SP	CRE	ED,ID	V	3/16/2108
2020 PO3707547219	F	4	40 ACE	SP	CRE	ED,ID	V	3/17/2108
2020 PO3671647449	KU	3	45 ACE	SP	CCA		V	3/18/2108
2020 PO3693447370	F	4	40 ACE	SP	CRE		V	3/19/2108
2020 PO3683647289	F	4	40 ACE	SP	CRE	ED,ID	V	3/20/2108
2020 PO3660647329	F	4	40 ACE	SP	CRE	ED,ID	V	3/21/2108
2020 PO4367403619	KU	4	40 BRO	SP	CCA	ED	T	3/22/2108
2020 PO4378602828-A	KU	3	40 BRO	SP	A		V	3/23/2108
2020 PO4378602828-B	KU	3	40 BRO	SP	A		V	3/24/2108
2020 PO4378602828-C	KU	3	40 BRO	SP	A		V	3/25/2108
2020 PO4378602828	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/26/2108
2020 PO4560601648-A	KU	4	40 BRO	SP	CCA		V	3/27/2108
2020 PO4560601648	F	4	40 BRO	SP	CCA		V	3/28/2108
2020 PO4554001755	F	4	40 BRO	SP	CCA		V	3/29/2108
2020 PO4553701847	KU	3	45 BRO	SP	CCA		V	3/30/2108
2020 PO4545001972	F	4	40 BRO	SP	CCA		V	3/31/2108
2020 PO4536102196	F	4	40 BRO	SP	CCA		V	4/1/2108
2020 PO4525102459	F	4	40 BRO	SP	CCA		V	4/2/2108
2020 PO4515802688	F	3	40 BRO	SP	CCA		V	4/3/2108
2020 PO5787941022	F	4	40 BRN	SP	CCA		V	4/4/2108
2020 PO5798140926	F	4	40 BRN	SP	CCA		V	4/5/2108
2020 PO5776041525	F	4	40 BRN	SP	CCA		V	4/6/2108
2020 PO5766441263	F	4	40 BRN	SP	CCA		V	4/7/2108
2020 PO5767641450	F	4	40 BRN	SP	CCA		V	4/8/2108
2020 PO5794841660	KU	4	45 BRN	SP	CCA		V	4/9/2108
2020 PO5784441600	F	4	40 BRN	SP	CCA		V	4/10/2108
2020 PO5759241375	F	4	40 BRN	SP	CCA		V	4/11/2108
2020 PO5772141165	F	4	40 BRN	SP	CCA		V	4/12/2108
2020 PO5779741099	F	4	40 BRN	SP	CCA		V	4/13/2108
2020 PO5791641662	KU	4	40 BRN	SP	CCA	ED,ID	TD	4/14/2108
2020 PO3281352422	KU	3	45 ACE	SP	CCA		V	4/15/2108
2020 PO3280752594	KU	4	40 ACE	SP	CCA		V	4/16/2108
2020 PO4737388280	LGE	4	40 BRO	SP	CCA		V	4/17/2108
2020 PO4733588299	LGE	4	35 BRO	SP	A	ED,ID	TD	4/18/2108
2020 PO4734788290	LGE	4	40 BRO	SP	A	ED,ID	BD	4/19/2108
2020 PO4735288296	LGE	4	40 BRO	SP	CRE	ED,ID	TD	4/20/2108
2020 PO4735288396	LGE	4	40 BRO	SP	A	ED,ID	TD	4/21/2108
2020 PO4737788285	LGE	4	40 BRO	SP	A	ED,ID	TD	4/22/2108

2020 PO4665888479	LGE	4	30 BRN	SP	CRE	ED,ID,IP	TD	4/23/2108
2020 PO4665188489	LGE	4	30 BRN	SP	CRE	ED,ID	TD	4/24/2108
2020 PO4661388543	LGE	4	30 BRN	SP	A	ED,ID	TD	4/25/2108
2020 PO4660788549	LGE	4	30 BRN	SP	A	ED,ID	TD	4/26/2108
2020 PO4737888283	LGE	3	45 BRO	SP	P	ED,ID	TD	4/27/2108
2020 PO4738888270	LGE	3	45 BRO	SP	CRE	ED,ID	BD	4/28/2108
2020 PO4741188254	LGE	3	45 BRO	SP	CCA		V	4/29/2108
2020 PO4742488258	LGE	3	45 BRO	SP	A	ED,ID	TD	4/30/2108
2020 PO4531895457	LGE	1	50 BRO	SP	CCA		V	5/1/2108
2020 PO4744288267	LGE	6	25 BRO	SP	CRE	ED,ID	TD	5/2/2108
2020 PO4743988269	LGE	UNK	55 BRO	SP	A	ED,ID	TD	5/3/2108
2020 PO4531895457-A	LGE	4	30E BRO	SP	A	ED,ID	TD	5/4/2108
2020 PO4746788292	LGE	4	40 BRO	SP	P	ED,ID	BD	5/5/2108
2020 PO4745488282	LGE	4	40 BRO	SP	CRE	MD	VX	5/6/2108
2020 PO4660188559	LGE	4	30 BRN	SP	P	ED,ID	TD	5/7/2108
2020 PO4661488551	F	4	40 BRN	SP	CCA		V	5/8/2108
2020 PO4661788546	F	4	40 BRN	SP	CCA		V	5/9/2108
2020 PO4660788562	F	4	40 BRN	SP	CRE		V	5/10/2108
2020 PO4664288925	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	5/11/2108
2020 PO4665088915	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	5/12/2108
2020 PO4654489050	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	5/13/2108
2020 PO4654889044	LGE	5	25 BRO	SP	CRE	ED,ID,IP	TD	5/14/2108
2020 PO4659288357	LGE	4	40 BRN	SP	A	ED,ID	TD	5/15/2108
2020 PO4658188358	LGE	4	40 BRN	SP	A	ED,ID	BD	5/16/2108
2020 PO4657088357	LGE	4	40 BRN	SP	A	ED,ID,IP	TD	5/17/2108
2020 PO4655888355	LGE	4	40 BRN	SP	A	ED,ID	TD	5/18/2108
2020 P03968691529	KU	5	30 KOP	SP	S		V	5/19/2108
2020 P03958291492	KU	5	35 KOP	SP	S		V	5/20/2108
2020 P03968691529	KU	4	45 KOP	SP	CRE	ED,ID	TD	5/21/2108
2020 P03970891474	F	4	40 KOP	SP	CRE		V	5/22/2108
2020 P03974791368	F	4	40 KOP	SP	CRE		V	5/23/2108
2020 P03979991224	KU	4	45 KOP	SP	CRE	ED,ID	TD	5/24/2108
2020 PO4654988354	LGE	4	40 BRN	SP	A	ED,ID	BD	5/25/2108
2020 PO4654888352	LGE	4	40 BRN	SP	A	ED,ID	TD	5/26/2108
2020 PO4655388344	LGE	4	40 BRN	SP	A	ED,ID	TD	5/27/2108
2020 PO4719988019	F	3	45 BRO	SP	CCA		V	5/28/2108
2020 PO4721488030	F	3	45 BRO	SP	CCA		V	5/29/2108
2020 PO4723988048	F	4	40 BRO	SP	CCA		V	5/30/2108
2020 PO4722888040	F	3	45 BRO	SP	CCA		V	5/31/2108
2020 PO4725488059	F	4	40 BRO	SP	CRE		V	6/1/2108
2020 PO4726688068	F	3	45 BRO	SP	CCA		V	6/2/2108
2020 PO4726888062	F	4	30 BRO	SP	CRE		V	6/3/2108
2020 PO4727488073	F	3	45 BRO	SP	CCA		V	6/4/2108
2020 PO4728288079	F	3	45 BRO	SP	CCA		V	6/5/2108
2020 PO4728188069	F	4	30 BRO	SP	CRE		V	6/6/2108
2020 PO4018391253	KU	5	30 KOP	SP	CRE		V	6/7/2108
2020 PO4656689151	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	6/8/2108

2020 PO4655089139	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/9/2108	
2020 PO4665988904	LGE	4	40 BRO	SP	P	ED	T	6/10/2108	
2020 PO4653188312	LGE	4	40 BRN	SP	A	ED,ID	TD	6/11/2108	
2020 PO5729007223	KU	6	30 XXX	SP	CRE		V	6/12/2108	
2020 PO5734307160	KU	6	30 XXX	SP	CRE		V	6/13/2108	
2020 PO4652688321	LGE	4	40 BRN	SP	A	ED,ID,SRS	TX	RR	6/14/2108
2020 PO4732688111	F	3	45 BRO	SP	CCA		V	6/15/2108	
2020 PO5831011258	KU	4	40 XXX	SP	CCA		V	6/16/2108	
2020 PO5809611335	KU	4	40 XXX	SP	CRE	ED,ID	TD	6/17/2108	
2020 PO5785811417	KU	5	35 XXX	SP	CRE	ED,ID	TD	6/18/2108	
2020 PO5769811472	F	4	40 XXX	SP	CRE		V	6/19/2108	
2020 PO4734088121	F	3	45 BRO	SP	CCA		V	6/20/2108	
2020 PO4737688146	F	3	45 BRO	SP	CRE		V	6/21/2108	
2020 PO4735288129	F	3	45 BRO	SP	CCA		V	6/22/2108	
2020 PO4736488138	F	3	45 BRO	SP	CRE		V	6/23/2108	
2020 PO4735988126	F	4	30 BRO	SP	CRE		V	6/24/2108	
2020 PO4735788133	F	3	45 BRO	SP	CRE		V	6/25/2108	
2020 PO4738488155	F	4	30 BRO	SP	CRE	ED,HH,ID,RB	VX	PX	6/26/2108
2020 PO4738188150	F	4	40 BRO	SP	CRE		V	6/27/2108	
2020 PO4666188902	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/28/2108	
2020 PO4667288912	LGE	4	40 BRO	SP	P	ED	T	6/29/2108	
2020 PO4667888916	LGE	4	40 BRO	SP	CRE	ID,IP	BD	6/30/2108	
2020 PO4020091825	KU	6	30 KOP	SP	CRE	ED,ID	TD	7/1/2108	
2020 PO4018491726	KU	6	30 KOP	SP	CRE	ED,ID	TD	7/2/2108	
2020 PO4015891783	KU	6	30 KOP	SP	CRE	ED,ID	TD	7/3/2108	
2020 PO4013391837	F	4	40 KOP	SP	CRE		V	7/4/2108	
2020 PO4012191860	F	4	40 KOP	SP	CRE		V	7/5/2108	
2020 PO4011291880	F	4	40 KOP	SP	P		V	7/6/2108	
2020 PO3859391115	F	4	40 KOP	SP	CRE		V	7/7/2108	
2020 PO3855891092	F	4	40 KOP	SP	CRE		V	7/8/2108	
2020 PO3847391181	F	4	40 KOP	SP	CRE		V	7/9/2108	
2020 PO3846691253	F	4	40 KOP	SP	CRE		V	7/10/2108	
2020 PO3850591270	KU	6	30 KOP	SP	CCA		V	7/11/2108	
2020 PO3859291280	KU	5	35 KOP	SP	S		V	7/12/2108	
2020 PO4652588355	LGE	4	40 BRN	SP	A	ED,ID	TD	7/13/2108	
2020 PO4652288345	LGE	4	40 BRN	SP	A	ED,ID	TD	7/14/2108	
2020 PO4652788331	LGE	4	40 BRN	SP	A	ED,ID	TD	7/15/2108	
2020 PO4650788330	LGE	4	40 BRN	SP	A	ED,ID	TD	7/16/2108	
2020 PO5737810721	KU	4	45 XXX	SP	CRE	ED,ID	TD	7/17/2108	
2020 PO5740410494	KU	6	30 XXX	SP	CCA		V	7/18/2108	
2020 PO5753110469	KU	4	40 XXX	SP	CRE	ID	BD	7/19/2108	
2020 PO5758110547	KU	4	40 XXX	SP	CCA		V	7/20/2108	
2020 PO5763210625	KU	4	40 XXX	SP	CRE	ED,ID	TD	7/21/2108	
2020 PO5779810543	KU	5	35 XXX	SP	CRE	ED,ID	TD	7/22/2108	
2020 PO4656489057	LGE	5	25 BRO	SP	A	ED	TD	7/23/2108	
2020 PO5795510463	KU	5	40 XXX	SP	CRE	ED,ID	TD	7/24/2108	
2020 PO5798510256	KU	4	40 XXX	SP	CRE	ED,ID	TD	7/25/2108	

2020 PO3888291641	KU	5	35 KOP	SP	S		V	7/26/2108
2020 PO3951591763	F	4	40 KOP	SP	CRE		V	7/27/2108
2020 PO3942091901	F	4	40 KOP	SP	CRE		V	7/28/2108
2020 PO3953191949	F	4	40 KOP	SP	CRE		V	7/29/2108
2020 PO3926491663	KU	4	40 KOP	SP	CRE	ED,ID	TD	7/30/2108
2020 PO3932591677	F	4	40 KOP	SP	CRE		V	7/31/2108
2020 PO3923091816	F	4	40 KOP	SP	CRE		V	8/1/2108
2020 PO3912991770	F	4	40 KOP	SP	S		V	8/2/2108
2020 PO3897491702	F	4	40 KOP	SP	S		V	8/3/2108
2020 PO4656089062	LGE	4	35 BRO	SP	CRE	ID,IP	BD	8/4/2108
2020 PO4655589065	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	8/5/2108
2020 PO4657489073	LGE	4	40 BRO	SP	CRE	ID,IP	BD	8/6/2108
2020 PO4654189083	LGE	4	40 BRO	SP	A	ED	TD	8/7/2108
2020 PO4650288310	LGE	4	40 BRN	SP	A	ED,ID	TD	8/8/2108
2020 PO4649688319	LGE	4	40 BRN	SP	A	ED,ID	TD	8/9/2108
2020 PO5738808881	KU	4	40 XXX	SP	CRE	ED,ID	TD	8/10/2108
2020 PO4649488331	LGE	4	40 BRN	SP	A	ED,ID,IP	TD	8/11/2108
2020 PO4649488343	LGE	4	40 BRN	SP	A	ED,ID,IP	TD	8/12/2108
2020 PO4655089072	LGE	4	40 BRO	SP	A	ED	TD	8/13/2108
2020 PO5707609080	KU	4	40 XXX	SP	CRE	ID	BD	8/14/2108
2020 PO5707908925	KU	1	55 XXX	SP	CRE	ED,ID	TD	8/15/2108
2020 PO4738588343	LGE	4	30 BRO	SP	A	ED,ID	TD	8/16/2108
2020 PO4739788326-A	LGE	5	20E BRO	SP	CRE	ED,ID	BD	8/17/2108
2020 PO4649588353	LGE	4	40 BRN	SP	P	ED,ID,IP	TD	8/18/2108
2020 PO4653389095	LGE	4	40 BRO	SP	A	ID,IP	BD	8/19/2108
2020 PO4652489105	LGE	4	40 BRO	SP	CRE	ID,IP	BD	8/20/2108
2020 PO5711708613	KU	3	50 XXX	SP	CCA		V	8/21/2108
2020 PO3956191628	F	4	40 KOP	SP	S		V	8/22/2108
2020 PO3939291556	F	4	40 KOP	SP	CRE		V	8/23/2108
2020 PO3930391517	F	4	40 KOP	SP	CRE		V	8/24/2108
2020 PO3904191406	F	4	40 KOP	SP	CRE		V	8/25/2108
2020 PO3884391320	F	4	40 KOP	SP	CRE		V	8/26/2108
2020 PO3872891276	F	4	40 KOP	SP	CRE		V	8/27/2108
2020 PO3863091224	F	4	40 KOP	SP	CRE		V	8/28/2108
2020 PO3852091155	F	4	40 KOP	SP	CRE		V	8/29/2108
2020 PO3841891088	F	4	40 KOP	SP	CRE		V	8/30/2108
2020 PO3833791035	F	4	40 KOP	SP	CRE		V	8/31/2108
2020 PO3803690772	KU	6	30 KOP	SP	CRE	ID	BD	9/1/2108
2020 PO3803190944	KU	6	30 KOP	SP	CRE	ED,ID	TD	9/2/2108
2020 PO3808390922	F	4	40 KOP	SP	S		V	9/3/2108
2020 PO3818590989	F	4	40 KOP	SP	S		V	9/4/2108
2020 PO3817591054	KU	6	30 KOP	SP	CRE	ED,ID	TD	9/5/2108
2020 PO3823391083	KU	6	30 KOP	SP	CCA		V	9/6/2108
2020 PO3825891052	KU	5	35 KOP	SP	S		V	9/7/2108
2020 PO5713407831	KU	4	40 XXX	SP	CRE	ED,ID	TD	9/8/2108
2020 PO5754207554	KU	4	40 BRN	SP	CCA		V	9/9/2108
2020 PO5729307545	KU	4	45 BRN	SP	CCA		V	9/10/2108

2020 PO5723907159	KU	4	40 BRN	SP	CCA		V	9/11/2108
2020 PO4652089177	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/12/2108
2020 PO4652489172	LGE	5	25 BRO	SP	CRE	ED,ID,IP	TD	9/13/2108
2020 PO4653689190	LGE	4	35 BRO	SP	CRE		V	9/14/2108
2020 PO4654089184	LGE	4	30 BRO	SP	CRE		V	9/15/2108
2020 PO5772706117	KU	3	45 XXX	SP	CRE	ID	BD	9/16/2108
2020 PO5770506105	KU	3	45 XXX	SP	CRE	ID	BD	9/17/2108
2020 PO5770206162	KU	3	45 XXX	SP	CRE	ID	BD	9/18/2108
2020 PO5767606210	KU	3	45 XXX	SP	CRE	ED,ID	TD	9/19/2108
2020 PO5789906336	KU	3	45 XXX	SP	CCA		V	9/20/2108
2020 PO3962890776	F	4	40 KOP	SP	S		V	9/21/2108
2020 PO3968090793	F	4	40 KOP	SP	P		V	9/22/2108
2020 PO3966590838	KU	3	45 KOP	SP	S		V	9/23/2108
2020 PO3964690883	F	4	40 KOP	SP	S		V	9/24/2108
2020 PO5273812271	F	4	40 BRO	SP	CRE		V	9/25/2108
2020 PO5271912149	F	4	40 BRO	SP	CRE		V	9/26/2108
2020 PO5270012025	F	4	40 BRO	SP	CRE		V	9/27/2108
2020 PO5268011907	F	4	40 BRO	SP	CRE		V	9/28/2108
2020 PO5247012429	KU	4	40 BRO	SP	CRE	ID,IP	BD	9/29/2108
2020 PO5234812065	F	4	40 BRO	SP	CRE		V	9/30/2108
2020 PO5238512118	F	4	40 BRO	SP	CCA		V	10/1/2108
2020 PO5241812261	F	4	40 BRO	SP	CRE		V	10/2/2108
2020 PO5228012262	F	4	40 BRO	SP	CRE		V	10/3/2108
2020 PO5209012644	KU	4	40 BRO	SP	CRE		V	10/4/2108
2020 PO5223512618	KU	4	40 BRO	SP	CCA		V	10/5/2108
2020 PO5212212297	F	4	40 BRO	SP	CRE		V	10/6/2108
2020 PO5548751273	KU	4	40 OTH	SP	CRE	ID	TD	10/7/2108
2020 PO5495351440	KU	5	35 OTH	SP	CRE	ID	TD	10/8/2108
2020 PO5590450840	KU	4	40 OTH	SP	CRE	ID	TD	10/9/2108
2020 PO5507351701	KU	4	40 OTH	SP	CRE	ID	TD	10/10/2108
2020 PO5524951520	KU	4	40 OTH	SP	CRE	ID	TD	10/11/2108
2020 PO5570451053	KU	4	40 OTH	SP	CRE	ID	TD	10/12/2108
2020 PO5483051196	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD	10/13/2108
2020 PO5201912264	F	4	40 BRO	SP	CRE		V	10/14/2108
2020 PO5190912172	F	4	40 BRO	SP	CRE		V	10/15/2108
2020 PO5186511905	F	4	40 BRO	SP	CRE		V	10/16/2108
2020 PO9173527425	ODP	5	35 XXX	SP	CRE	ID	TD	10/17/2108
2020 PO9142227199	ODP	5	35 XXX	SP	CRE	ID	TD	10/18/2108
2020 PO9116126997	ODP	5	45 XXX	SP	CRE	ID	BD	10/19/2108
2020 PO3409040391	KU	4	40 BRO	SP	CCA		V	10/20/2108
2020 PO3391941148A	KU	5	35 BRO	SP	CRE	HH,RB	X	10/21/2108
2020 PO5531342332	KU	6	30 BRO	SP	CCA	ED	T	10/22/2108
2020 PO3399940809	KU	5	35 BRO	SP	CRE	ID	TD	10/23/2108
2020 PO3391941148	KU	4	45 BRO	SP	CCA		V	10/24/2108
2020 PO3357841245	KU	4	45 BRO	SP	CCA		V	10/25/2108
2020 PO3278041305	KU	3	45 BRO	SP	CCA		V	10/26/2108
2020 PO3317941275	KU	3	45 BRO	SP	CCA		V	10/27/2108

2020 PO3317941275-A	KU	3	45 BRO	SP	CCA		V	10/28/2108	
2020 PO3243448469	KU	4	40 ACE	SP	CRE	ED,ID	TD	10/29/2108	
2020 PO5518042282	KU	4	40 BRO	SP	CCA	ED	T	10/30/2108	
2020 PO5509442243	KU	4	40 BRO	SP	CRE	ID,IP	BD	10/31/2108	
2020 PO5426242557	KU	4	40 BRO	SP	CRE	ID	BD	11/1/2108	
2020 PO3275941026	KU	4	40 BRO	SP	CCA		V	11/2/2108	
2020 PO3273940767	KU	3	45 BRO	SP	CCA		V	11/3/2108	
2020 PO3094440777	KU	4	40 BRO	SP	CCA		V	11/4/2108	
2020 PO3094841047	KU	4	40 BRO	SP	CRE	ID	BD	11/5/2108	
2020 PO5413643141	KU	4	45 BRO	SP	CRE	ID	BD	11/6/2108	
2020 PO5448343680	F	4	40 BRO	SP	CRE		V	11/7/2108	
2020 PO2974840845	KU	4	45 BRO	ST	CCA		V	11/8/2108	
2020 PO3030640839	KU	4	45 BRO	SP	CRE	SRS	TD	11/9/2108	
2020 PO3259048713	KU	4	40 ACE	SP	CRE	ED,ID	TD	11/10/2108	
2020 PO5491942224	F	4	40 BRO	SP	CRE		V	11/11/2108	
2020 PO5466042318	F	4	40 BRO	SP	CRE		V	11/12/2108	
2020 PO4879534270	KU	3	45 BRO	SP	CCA		V	11/13/2108	
2020 PO4877534299	KU	3	45 BRO	SP	CRE	ID	BD	11/14/2108	
2020 PO4854134311	KU	3	45 BRO	SP	CRE	ID	TD	11/15/2108	
2020 PO4829334320	KU	3	45 BRO	SP	CRE	ID	TD	11/16/2108	
2020 PO4805834339	KU	3	45 BRO	SP	CCA		V	11/17/2108	
2020 PO4800934116	KU	3	45 BRO	SP	CRE	ID	TD	11/18/2108	
2020 PO4796733770	KU	4	40 BRO	SP	CRE		V	11/19/2108	
2020 PO4805833472	KU	4	40 BRO	SP	CRE	ID	TD	11/20/2108	
2020 PO5460543812	F	4	40 BRO	SP	A		V	11/21/2108	
2020 PO5469343946	F	4	40 BRO	SP	CRE		V	11/22/2108	
2020 PO5204411331	F	4	40 BRO	SP	CRE		V	11/23/2108	
2020 PO4677888284	LGE	4	40 BRN	SP	A	ED,ID	TD	11/24/2108	
2020 PO4608488031	LGE	UNK	65 BRO	SP	CRE	ED,EP,ID,RB	TX	RR	11/25/2108
2020 PO4677188292	LGE	4	40 BRN	SP	CRE	ED,ID	BD	11/26/2108	
2020 PO4676988301	F	4	30 BRN	SP	CCA		V	11/27/2108	
2020 PO4676588300	LGE	4	40 BRN	SP	A	ED,ID	TD	11/28/2108	
2020 PO5481944059	KU	4	45 BRO	SP	CRE	ID	BD	11/29/2108	
2020 PO5541843947	F	4	40 BRO	SP	CRE		V	11/30/2108	
2020 PO5538443751	F	4	40 BRO	SP	CRE		V	12/1/2108	
2020 PO5143537025	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	12/2/2108	
2020 PO5132137029	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	12/3/2108	
2020 PO5535043558	F	4	40 BRO	SP	CRE		V	12/4/2108	
2020 PO5531843360	F	4	40 BRO	SP	CRE		V	12/5/2108	
2020 PO5528843186	F	4	40 BRO	SP	CRE		V	12/6/2108	
2020 PO5528343135	F	6	30 BRO	SP	CRE	HH,ID	VX	RP1	12/7/2108
2020 PO5508343194	F	3	40 BRO	SP	A		V	12/8/2108	
2020 PO5488343204	F	4	40 BRO	SP	CRE		V	12/9/2108	
2020 PO5477843278	F	4	40 BRO	SP	CRE		V	12/10/2108	
2020 PO5461643388	F	4	40 BRO	SP	CRE		V	12/11/2108	
2020 PO5446443492	F	4	40 BRO	SP	CRE		V	12/12/2108	
2020 PO5435243554	F	4	40 BRO	SP	CRE		V	12/13/2108	

2020 PO4290033255	KU	5	35 BRO	SP	CRE	ID	TD	12/14/2108
2020 PO4590058274	KU	4	40 OTH	SP	CRE	ID	TD	12/15/2108
2020 PO4561457939	KU	4	40 OTH	SP	CCA		V	12/16/2108
2020 PO4670558987	KU	4	45 OTH	SP	CRE	ID	TD	12/17/2108
2020 PO4623959311	KU	4	40 OTH	SP	CRE	ID	TD	12/18/2108
2020 PO4644258727	KU	4	40 OTH	SP	CCA	ED,SRS	TD	12/19/2108
2020 PO5166913526	KU	4	40 BRO	SP	A	ED,ID,IP	TD	12/20/2108
2020 PO5201613480	KU	4	45 BRO	SP	CCA		V	12/21/2108
2020 PO4640188250	LGE	4	40 BRO	SP	CRE	ED,ID	BD	12/22/2108
2020 PO4641188257	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	12/23/2108
2020 PO4641988263	LGE	4	40 BRO	SP	P	ED,ID	TD	12/24/2108
2020 PO4642588267	LGE	4	40 BRO	SP	CCA		V	12/25/2108
2020 PO4609388086	LGE	4	35 BRO	SP	CRE		V	12/26/2108
2020 PO4609488102	LGE	4	35 BRO	SP	CRE		V	12/27/2108
2020 PO3186993275	LGE	3	45 BRO	SP	CCA		V	12/28/2108
2020 PV4609088058	LGE	4	40 BRO	SP	CCA		V	12/29/2108
2020 PO4608988048	LGE	4	35 BRO	SP	CRE		V	12/30/2108
2020 PO4609088052	LGE	3	50 BRO	SP	CCA		V	12/31/2108
2020 PO4672888330	LGE	3	45 BRN	SP	A	ED,ID	TD	1/1/2109
2020 PO5199013367	KU	5	35 BRO	SP	CRE	ID,IP	BD	1/2/2109
2020 PO5145113086	KU	4	40 BRO	SP	CRE		V	1/3/2109
2020 PO5142013019	KU	4	40 BRO	SP	CRE		V	1/4/2109
2020 PO5134312925	KU	5	35 BRO	SP	CRE		V	1/5/2109
2020 PO5173912795	F	5	35 BRO	SP	CRE		VX	1/6/2109
2020 PO5183712816	KU	6	30 BRO	SP	CCA		V	1/7/2109
2020 PO5156812529	F	4	40 BRO	SP	CRE		V	1/8/2109
2020 PO4669888308	LGE	3	45 BRN	SP	A	ED,ID	TD	1/9/2109
2020 PO4532057709	KU	3	45 OTH	SP	CCA		V	1/10/2109
2020 PO4459757240	KU	4	40 OTH	SP	P	ID	TD	1/11/2109
2020 PO4497357456	KU	4	45 OTH	SP	CRE	ID	TD	1/12/2109
2020 PO4671388319	LGE	3	45 BRN	SP	CRE	ED,ID	TD	1/13/2109
2020 PO4455357418	KU	4	40 OTH	SP	CCA	ED,SRS	TD	1/14/2109
2020 PO5160212401	F	4	40 BRO	SP	CRE		V	1/15/2109
2020 PO5151612470	F	4	40 BRO	SP	CRE		V	1/16/2109
2020 PO5162712615	F	4	40 BRO	SP	CRE		V	1/17/2109
2020 PO5168012696	F	4	40 BRO	SP	CRE		V	1/18/2109
2020 PO5175112682	KU	6	30 BRO	SP	CRE	ID,IP	BD	1/19/2109
2020 PO4737588169	LGE	3	45 BRO	SP	CCA		V	1/20/2109
2020 PO4738088173	LGE	4	35 BRO	SP	CCA		V	1/21/2109
2020 PO4737588173	LGE	4	40 BRO	SP	A	ED,ID,IP	BD	1/22/2109
2020 PO4733587905	LGE	1	70 BRO	SP	CRE		V	1/23/2109
2020 PO4670588332	LGE	3	45 BRN	SP	A	ED,ID	BD	1/24/2109
2020 PO4669688345	LGE	3	45 BRN	SP	CRE	ED,ID	TD	1/25/2109
2020 PO5130512665	F	4	40 BRO	SP	CRE		V	1/26/2109
2020 PO4669088355	LGE	3	50 BRN	SP	A	ED,ID	TD	1/27/2109
2020 PO4669488361	LGE	4	30 BRN	SP	A	ED,EP,ID	BX	1/28/2109
2020 PO5168511073	F	4	40 BRO	SP	CRE		V	1/29/2109

2020	PO5158411130	F	4	40 BRO	SP	CRE		V		1/30/2109
2020	PO5135611261	F	4	40 BRO	SP	CRE		V		1/31/2109
2020	PO5130411313	F	4	40 BRO	SP	CRE		V		2/1/2109
2020	PO5147411194	F	4	40 BRO	SP	CRE		V		2/2/2109
2020	PO5183335953	F	4	40 ACE	SP	CRE		V		2/3/2109
2020	PO5225536686	F	4	40 BRO	SP	CCA		V		2/4/2109
2020	PO5197337071	F	1	50 BRO	SP	CCA		V		2/5/2109
2020	PO5170435781	F	4	40 ACE	SP	CRE		V		2/6/2109
2020	PO5219837053-A	KU	4	40 BRO	SP	CCA		V		2/7/2109
2020	PO5219837053	F	4	40 BRO	SP	CCA		V		2/8/2109
2020	PO5168435605	F	4	40 ACE	SP	CRE		V		2/9/2109
2020	PO5200336701	KU	4	40 BRO	SP	CRE	ED,ID,IP		TD	2/10/2109
2020	PO5182335812	F	4	40 ACE	SP	CRE		V		2/11/2109
2020	PO5213336693	KU	4	40 BRO	SP	CRE	ED,ID		TD	2/12/2109
2020	PO5181035618	F	4	40 ACE	SP	CRE	ED,ID		V	2/13/2109
2020	PO5180035492	F	3	45 ACE	SP	CCA		V		2/14/2109
2020	PO5178935346a	KU	5	35 ACE	SP	CCA		V		2/15/2109
2020	PO5178935346	F	4	40 ACE	SP	CRE	ED,ID		V	2/16/2109
2020	PO5177435172	F	5	40 ACE	SP	CRE	ED,ID		V	2/17/2109
2020	PO5228036864	F	4	40 BRO	SP	CCA		V		2/18/2109
2020	PO5191835159	F	4	40 ACE	SP	CRE	ED,ID		V	2/19/2109
2020	PO5175235007	F	4	40 ACE	SP	CRE	ED,ID,IP		V	2/20/2109
2020	PO5169734545	F	3	45 ACE	SP	P		V		2/21/2109
2020	PO5173634811	F	3	45 ACE	SP	P		V		2/22/2109
2020	PO5183134802	F	5	35 ACE	SP	CRE		V		2/23/2109
2020	PO5255837022	F	4	40 BRO	SP	CCA		V		2/24/2109
2020	PO5163334506	F	4	40 ACE	SP	CRE		V		2/25/2109
2020	PO5155834476	F	4	40 ACE	SP	CRE		V		2/26/2109
2020	PO5265336937	KU	4	40 BRO	SP	CRE	ID,IP		BD	2/27/2109
2020	PO5262137145	F	4	40 BRO	SP	CRE		V		2/28/2109
2020	PO5274937073	KU	4	40 BRO	SP	CCA		V		3/1/2109
2020	PO5345337494	F	4	40 ACE	SP	CRE		V		3/2/2109
2020	PO5315936980	F	4	40 BRO	SP	CRE		V		3/3/2109
2020	PO5288137002	F	4	40 BRO	SP	CRE		V		3/4/2109
2020	PO5382337473	KU	6	30 ACE	SP	CRE	ED,ID		TD	3/5/2109
2020	PO5307737971	F	4	40 BRO	SP	CRE		V		3/6/2109
2020	PO5315637993	F	4	40 BRO	SP	CRE		V		3/7/2109
2020	PO5369637480	F	4	40 ACE	SP	CRE		V		3/8/2109
2020	PO5369237396	F	4	40 ACE	SP	CRE		V		3/9/2109
2020	PO5307037801	F	4	40 BRO	SP	CRE	ED,ID,IP,RB	VX	RP1	3/10/2109
2020	PO5305837597	F	4	40 BRO	SP	CRE		V		3/11/2109
2020	PO5360537488	F	4	40 ACE	SP	CRE		V		3/12/2109
2020	PO5304537395	F	4	40 BRO	SP	CRE		V		3/13/2109
2020	PO5304137295	F	4	40 BRO	SP	CRE		V		3/14/2109
2020	PO5344637401	F	4	40 BRO	SP	CRE		V		3/15/2109
2020	PO5345937653	F	4	40 ACE	SP	CRE		V		3/16/2109
2020	PO5331237406	KU	6	30 BRO	SP	CRE	ED,ID,IP		TD	3/17/2109

Business Use

2020 PO5367137962	F	4	40 ACE	SP	CRE		V	3/18/2109
2020 PO5370637633	F	4	40 ACE	SP	CRE		V	3/19/2109
2020 PO5333537235	KU	6	30 BRO	SP	CRE	ED,ID	TD	3/20/2109
2020 PO5361337587	F	6	30 ACE	SP	CRE		V	3/21/2109
2020 PO5339737170	F	4	40 BRO	SP	CRE		V	3/22/2109
2020 PO5352937159	F	4	40 BRO	SP	CRE		V	3/23/2109
2020 PO5386237944	F	4	40 ACE	SP	CRE		V	3/24/2109
2020 PO5371536835	KU	6	30 BRO	SP	CRE	ED,ID	TD	3/25/2109
2020 PO5366836841	F	4	40 BRO	SP	CRE		V	3/26/2109
2020 PO5402437457	F	4	40 ACE	SP	CRE		V	3/27/2109
2020 PO5384937772	KU	6	30 ACE	SP	CCA		V	3/28/2109
2020 PO5385337839	KU	6	30 ACE	SP	CCA		V	3/29/2109
2020 PO5405137927	F	4	40 ACE	SP	CRE		V	3/30/2109
2020 PO5403137604	F	4	40 ACE	SP	CRE		V	3/31/2109
2020 PO5404137755	F	3	40 ACE	SP	A		V	4/1/2109
2020 PO5377036943	F	4	40 BRO	SP	CRE		V	4/2/2109
2020 PO5374837031	F	4	40 BRO	SP	CRE		V	4/3/2109
2020 PO5361836953	F	4	40 BRO	SP	CRE		V	4/4/2109
2020 PO5348236962	F	4	40 BRO	SP	CCA		V	4/5/2109
2020 PO5338436968	F	4	40 BRO	SP	CRE		V	4/6/2109
2020 PO5329536974	F	4	40 BRO	SP	CRE		V	4/7/2109
2020 PO5337936773	KU	4	45 BRO	SP	CRE	ID	BD	4/8/2109
2020 PO5413537751	KU	4	40 ACE	SP	CRE	ED,ID	TD	4/9/2109
2020 PO5414637917	F	4	40 ACE	SP	CRE		V	4/10/2109
2020 PO5333236873	KU	4	45 BRO	SP	CRE	ID	BD	4/11/2109
2020 PO5387336936	F	4	40 BRO	SP	CRE		V	4/12/2109
2020 PO5401137262	F	4	40 BRO	SP	CRE		V	4/13/2109
2020 PO5388237076	F	4	40 BRO	SP	CRE		V	4/14/2109
2020 PO5398637066	F	4	40 BRO	SP	CRE		V	4/15/2109
2020 PO5425537708	KU	5	30 ACE	SP	CCA	ED,ID	TD	4/16/2109
2020 PO5397636930	F	4	40 BRO	SP	CRE		V	4/17/2109
2020 PO5409236924	F	4	40 BRO	SP	CRE		V	4/18/2109
2020 PO5412637565	KU	4	40 ACE	SP	CRE	ED,ID	TD	4/19/2109
2020 PO5405737120	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	4/20/2109
2020 PO5411637033	F	4	40 BRO	SP	A		V	4/21/2109
2020 PO5419837065	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/22/2109
2020 PO5418336922	F	4	40 BRO	SP	CRE		V	4/23/2109
2020 PO5423137345	F	4	35 ACE	SP	CCA		V	4/24/2109
2020 PO5421937243	F	4	40 ACE	SP	CRE		V	4/25/2109
2020 PO5400242276	F	4	40 ACE	SP	CRE		V	4/26/2109
2020 PO5396242197	F	4	40 BRO	SP	CRE		V	4/27/2109
2020 PO5409042727	F	4	40 ACE	SP	CRE		V	4/28/2109
2020 PO5412642350	KU	5	35 ACE	SP	CRE	ED,ID	V	4/29/2109
2020 PO5406442421	F	2	50 ACE	SP	P		V	4/30/2109
2020 PO5402042320	F	4	40 ACE	SP	CRE		V	5/1/2109
2020 PO5423642208	KU	5	30 ACE	SP	CCA		V	5/2/2109
2020 PO5408142241	KU	6	30 ACE	SP	CCA		V	5/3/2109

2020 PO5387241953	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	5/4/2109
2020 PO5028837155	F	4	40 BRO	SP	A		V	5/5/2109
2020 PO5293944903	KU	5	35 ACE	SP	CRE		V	5/6/2109
2020 PO5392196837	KU	5	35 BRN	SP	CRE	ID,IP	TD	5/7/2109
2020 PO5394496621	KU	4	40 BRN	SP	CRE	ID,IP	TD	5/8/2109
2020 PO1929099071	KU	4	40 UNK	SP	CRE	ID	TD	5/9/2109
2020 PO5396896412	KU	4	40 BRN	SP	CRE	ID,IP	TD	5/10/2109
2020 PO1916499058	F	4	40 UNK	SP	A		V	5/11/2109
2020 PO5401396131	KU	4	40 BRN	SP	CRE	ID	BD	5/12/2109
2020 PO1897799040	F	4	40 UNK	SP	A		V	5/13/2109
2020 PO5413095368	KU	4	40 BRN	SP	CCA		V	5/14/2109
2020 PO5409395629	KU	5	35 BRN	SP	CRE	EP,ID	TD	5/15/2109
2020 PO5404995887	KU	4	40 BRN	SP	CRE	ID,IP	TD	5/16/2109
2020 PO5424195047	KU	4	40 BRN	SP	CCA		V	5/17/2109
2020 PO5492795339	KU	5	35 BRN	SP	CRE	ID,IP	TD	5/18/2109
2020 PO5459995224	KU	5	35 BRN	SP	CRE	ID,IP	TD	5/19/2109
2020 PO1878898711	KU	4	40 UNK	SP	CRE	ID	TD	5/20/2109
2020 PO5435894734	KU	4	40 BRN	SP	CRE	ID,IP	TD	5/21/2109
2020 PO3422701663	F	4	40 BRN	SP	CRE		V	5/22/2109
2020 PO3424001747	F	4	40 BRN	SP	A		V	5/23/2109
2020 PO3425401845	F	5	35 BRN	SP	CCA		V	5/24/2109
2020 PO3428901980	F	4	40 BRN	SP	CCA		V	5/25/2109
2020 PO5499593079	KU	4	40 BRN	SP	CRE	ID,IP	TD	5/26/2109
2020 PO4545498448	KU	5	35 BRN	SP	CCA		V	5/27/2109
2020 PO4556698507	F	5	35 BRN	SP	A		V	5/28/2109
2020 PO4565098505	F	5	35 BRN	SP	A		V	5/29/2109
2020 PO1865298912	F	4	40 UNK	SP	A		V	5/30/2109
2020 PO1826998602	F	5	30 UNK	SP	CRE		V	5/31/2109
2020 PO1829598744	KU	5	30 UNK	SP	CRE	ID,IP	TD	6/1/2109
2020 PO1831898794	F	4	40 UNK	SP	A		V	6/2/2109
2020 PO1845398813	KU	6	30 UNK	SP	CCA		V	6/3/2109
2020 PO1833498861	KU	6	30 UNK	SP	CCA		V	6/4/2109
2020 PO3878203317	KU	4	40 XXX	SP	CRE	ID	TD	6/5/2109
2020 PO3864703343	KU	4	40 XXX	SP	CRE	ED,ID	TD	6/6/2109
2020 PO7528273860	KU	5	35 BRO	SP	CRE		V	6/7/2109
2020 PO7563673840	KU	4	40 BRO	SP	A	ED,ID	TX	6/8/2109
2020 PO7569073693	KU	6	30 BRO	SP	CRE		V	6/9/2109
2020 PO7562573703	KU	3	40 BRO	SP	CRE		V	6/10/2109
2020 PO7558773491	KU	4	40 BRO	SP	P	ED,ID	TD	6/11/2109
2020 PO7117384977	KU	6	30 BRO	SP	CRE	ED,ID	TD	6/12/2109
2020 PO7404774851	KU	4	40 BRN	SP	CRE	ED,ID	TD	6/13/2109
2020 PO7549973180	KU	4	40 BRO	SP	P	ED,ID,IP	BD	6/14/2109
2020 PO7143884913	KU	4	30 BRO	SP	CRE	ED,ID	TD	6/15/2109
2020 PO7154484886	KU	6	30 BRO	SP	CRE	ED,ID	TD	6/16/2109
2020 PO7378075079	KU	4	45 BRN	SP	CRE	ED,ID	TD	6/17/2109
2020 PO7362774859	KU	4	40 BRN	SP	CRE	ED,ID	BD	6/18/2109
2020 PO7366175044	KU	3	45 BRN	SP	CCA		V	6/19/2109

2020 PO7540673069	KU	4	40 BRO	SP	P	ED,ID	TD		6/20/2109
2020 PO1533445589	KU	4	40 BRO	SP	CRE	ID	TD		6/21/2109
2020 PO3847303391	KU	4	40 XXX	SP	CRE	ED,EP,ID	TX	RR	6/22/2109
2020 PO1565545485	KU	4	40 BRO	SP	CRE	ED,ID	TD		6/23/2109
2020 PO1591345430	KU	3	45E BRO	SP	CRE	ED,ID,IP	TD		6/24/2109
2020 PO1600845600	KU	6	30 BRO	SP	CRE	ID,IP	TD		6/25/2109
2020 PO1597645522	KU	5	30 BRO	SP	CRE	ID,IP	TD		6/26/2109
2020 PO1616645569	KU	4	40 BRO	SP	CRE	ID	TD		6/27/2109
2020 PO1851845703	KU	4	40 BRO	SP	CRE	ID,IP	TD		6/28/2109
2020 PO1868645378	KU	4	40 BRO	SP	CRE	ID	TD		6/29/2109
2020 PO1868645378-A	KU	4	40 BRO	SP	CCA		V		6/30/2109
2020 PO1854345379	KU	6	30 BRO	SP	CRE		B		7/1/2109
2020 PO1856245310	KU	3	45 BRO	SP	CCA		V		7/2/2109
2020 PO1866745119	KU	4	40 BRO	SP	CRE	ID	BD		7/3/2109
2020 PO1871944885	KU	4	40 BRO	SP	CRE	ID,IP	TD		7/4/2109
2020 PO1894444646	KU	4	50 BRO	SP	CRE	ID	BD		7/5/2109
2020 PO0676215702	KU	3	45 ACE	SP	CCA		V		7/6/2109
2020 PO0658315493	KU	3	45 ACE	SP	CCA		V		7/7/2109
2020 PO0660515219	KU	3	45 ACE	SP	CCA		V		7/8/2109
2020 PO0529114839	KU	3	45 ACE	SP	CCA		V		7/9/2109
2020 PO0535215024	KU	3	45 ACE	SP	CCA		V		7/10/2109
2020 PO0541315208	KU	3	45 ACE	SP	CCA		V		7/11/2109
2020 PO0533215338	KU	3	45 ACE	SP	CCA		V		7/12/2109
2020 PO0663015143	F	4	40 ACE	SP	P	ED,ID	V		7/13/2109
2020 PO0635714961	F	4	40 ACE	SP	CRE		V		7/14/2109
2020 PO0806109622	F	4	40 ACE	SP	CRE		V		7/15/2109
2020 PO0793809486	F	7	20 ACE	SP	CRE		V		7/16/2109
2020 PO0796809831	F	4	40 ACE	SP	CRE		V		7/17/2109
2020 PO0793409949	F	7	20 ACE	SP	CRE		V		7/18/2109
2020 PO0836609989	F	4	40 ACE	SP	CRE		V		7/19/2109
2020 PO0897610937	KU	4	40 ACE	SP	CCA		V		7/20/2109
2020 PO0697409852	F	4	40 ACE	SP	CRE	ED,ID	V		7/21/2109
2020 PO0728810123	F	4	40 ACE	SP	CRE	ED,ID	V		7/22/2109
2020 PO0765610454	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	VX	RP1	7/23/2109
2020 PO0819110925	F	4	40 ACE	SP	CRE		V		7/24/2109
2020 PO0856011281	F	4	40 ACE	SP	CRE		V		7/25/2109
2020 PO0941011409	KU	5	35 ACE	SP	CRE	ID	BD		7/26/2109
2020 PO0928611493	F	4	40 ACE	SP	CRE		V		7/27/2109
2020 PO0900911652	F	4	40 ACE	SP	CRE		V		7/28/2109
2020 PO0504816727b	KU	4	40 ACE	SP	CCA		V		7/29/2109
2020 PO0504816727	KU	4	40 ACE	SP	CCA		V		7/30/2109
2020 PO0531916582	KU	4	40 ACE	SP	CCA		V		7/31/2109
2020 PO0916311780	F	4	40 ACE	SP	CRE		V		8/1/2109
2020 PO0940311662	F	4	40 ACE	SP	CRE	ED,ID	V		8/2/2109
2020 PO0931511906	F	4	40 ACE	SP	CRE	ED,ID	V		8/3/2109
2020 PO0963712043	KU	5	35 ACE	SP	CCA		V		8/4/2109
2020 PO0970011980	KU	3	45 ACE	SP	CCA		V		8/5/2109

2020 PO0988512017	F	4	40 ACE	SP	CRE		V	8/6/2109
2020 PO0954112107	F	4	40 ACE	SP	CRE		V	8/7/2109
2020 PO0881411067	KU	4	45 ACE	SP	CCA		V	8/8/2109
2020 PO0497913040	KU	4	40 ACE	SP	CRE	ED,ID	BD	8/9/2109
2020 PO0511312914	KU	3	45 ACE	SP	CCA		V	8/10/2109
2020 PO0504813102	KU	3	45 ACE	SP	CCA		V	8/11/2109
2020 PO0493713300	KU	3	45 ACE	SP	CCA		V	8/12/2109
2020 PO0481813631	KU	3	45 ACE	SP	CCA		V	8/13/2109
2020 PO0494114036	KU	3	45 ACE	SP	CCA		V	8/14/2109
2020 PO0456314067	KU	3	45 ACE	SP	CCA		V	8/15/2109
2020 PO0524314692	KU	3	45 ACE	SP	CCA		V	8/16/2109
2020 PO0457113583	KU	4	40 ACE	SP	CRE	ED,ID	BD	8/17/2109
2020 PO0431613524	KU	4	40 ACE	SP	CRE	ED,ID	BX	RP1 8/18/2109
2020 PO0574116349	KU	3	45 ACE	SP	CCA		V	8/19/2109
2020 PO0723920343	KU	4	40 ACE	SP	CRE	ED,ID	BD	8/20/2109
2020 PO0739920683	KU	4	40 ACE	SP	CRE	ED,ID	BD	8/21/2109
2020 PO0845523660	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	8/22/2109
2020 PO0876823896	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	8/23/2109
2020 PO0866724199	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD	8/24/2109
2020 PO0502027988	KU	4	40 ACE	SP	CRE		V	8/25/2109
2020 PO0518928237	KU	4	40 ACE	SP	CCA		V	8/26/2109
2020 PO0525328420	KU	4	40 ACE	SP	CCA		V	8/27/2109
2020 PO0765023191	KU	4	40 ACE	SP	CRE		V	8/28/2109
2020 PO0794423077	KU	4	40 ACE	SP	CRE		V	8/29/2109
2020 PO8522279471	F	4	40 BRO	SP	CRE		V	8/30/2109
2020 PO4938686877	LGE	3	45 OTH	SP	CCA	ED,SRS	TD	8/31/2109
2020 PO4950586874	LGE	4	40 OTH	SP	CCA	ED,SRS	TD	9/1/2109
2020 PO4852986778	LGE	3	45 XXX	SP	A	ID	BD	9/2/2109
2020 PO4851486775	LGE	3	50 XXX	SP	CCA		V	9/3/2109
2020 PO4856386812	LGE	3	40 XXX	SP	CCA		V	9/4/2109
2020 PO4855786807	LGE	3	45 XXX	SP	CCA		V	9/5/2109
2020 PO4854486803	LGE	4	40 XXX	SP	CRE	ED,ID	TD	9/6/2109
2020 PO4934687021	LGE	3	50 OTH	SP	P	ID	BD	9/7/2109
2020 PO4949486897	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	9/8/2109
2020 PO4855286825	LGE	4	40 BRN	SP	A	ED,ID	TD	9/9/2109
2020 PO4927687023	LGE	3	50 OTH	SP	P	ID	BD	9/10/2109
2020 PO4929687023	LGE	4	40 OTH	SP	P	ID	BD	9/11/2109
2020 PO4924687024	LGE	3	50 OTH	SP	P	ED,SRS	TD	9/12/2109
2020 PO4931687022	LGE	3	50 OTH	SP	P	ID	BD	9/13/2109
2020 PO4854786845	LGE	4	40 BRN	SP	CCA		V	9/14/2109
2020 PO4856086864	LGE	4	40 ACW	SP	CRE	ED,ID	BD	9/15/2109
2020 PO4854586862	LGE	4	45 XXX	SP	A	ED,ID	TD	9/16/2109
2020 PO4855686885	LGE	3	45 XXX	SP	A	ED,ID	TD	9/17/2109
2020 PO4855886896	LGE	3	45 XXX	SP	A	ID	BD	9/18/2109
2020 PO4856186907	LGE	3	45 XXX	SP	A	ED,ID	TD	9/19/2109
2020 PO4848486971	LGE	4	30 XXX	SP	CCA		V	9/20/2109
2020 PO4638389127	LGE	4	45 OTH	SP	P	ED,ID,SRS	TD	9/21/2109

2020 PO4772087672	LGE	4	40 XXX	SP	A	ID	BD	9/22/2109	
2020 PO4771287673	LGE	4	40 XXX	SP	CCA		V	9/23/2109	
2020 PO4770887673	LGE	4	40 XXX	SP	A	ID	BD	9/24/2109	
2020 PO4768987673	LGE	4	40 XXX	SP	A	ED,ID	TD	9/25/2109	
2020 PO4767087674	LGE	4	40 XXX	SP	A	ID	BD	9/26/2109	
2020 PO4766687673	LGE	4	40 XXX	SP	A	ID	BD	9/27/2109	
2020 PO4790487756	LGE	H1	95 XXX	AL	S		V	9/28/2109	
2020 4633889201A	LGE	4	30 OTH	SP	CCA		V	9/29/2109	
2020 PO4637189149	LGE	3	45 OTH	SP	P	ED,ID,SRS	TD	9/30/2109	
2020 PO4638089134	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	10/1/2109	
2020 PO4635289179	LGE	3	50 OTH	SP	P	ED,ID,SRS	TD	10/2/2109	
2020 PO4634589190	LGE	2	50 OTH	SP	CRE	ED,ID,SRS	TD	10/3/2109	
2020 PO4636189164	LGE	3	45 OTH	SP	P	ED,ID,SRS	TD	10/4/2109	
2020 PO4633889201	LGE	2	55 OTH	SP	CRE	ED,ID,SRS	TD	10/5/2109	
2020 PO4836187265	LGE	4	40 KOP	SP	P	ED,ID	TD	10/6/2109	
2020 PO4633489207	LGE	1	55 OTH	SP	CCA		V	10/7/2109	
2020 PO4290488008	LGE	4	35 ACW	SP	CRE		V	10/8/2109	
2020 PO4290688020	LGE	5	35 ACW	SP	CRE		V	10/9/2109	
2020 PO4290788031	LGE	5	35 ACW	SP	CRE		V	10/10/2109	
2020 PO4295688042	LGE	2	55 ACW	SP	CRE	ID,IP	BD	10/11/2109	
2020 PO4295188043	LGE	2	55 ACW	SP	S		V	10/12/2109	
2020 PO4294188044	LGE	1	55 ACW	SP	S		V	10/13/2109	
2020 PO4293888044	LGE	4	45 ACW	SP	CRE	ID	BD	10/14/2109	
2020 PO4293088045	LGE	1	55 ACW	SP	S		V	10/15/2109	
2020 PO4292788056	LGE	4	35 ACW	SP	S		V	10/16/2109	
2020 PO4290888040	LGE	5	35 ACW	SP	CRE		V	10/17/2109	
2020 PO4291188059	LGE	5	30 ACW	SP	CRE		V	10/18/2109	
2020 PO4292188046	LGE	3	45 ACW	SP	S		V	10/19/2109	
2020 PO0028892550	LGE	3	50 ACW	SP	CCA		V	10/20/2109	
2020 PO4290588050	LGE	4	40 ACW	SP	S		V	10/21/2109	
2020 PO4291188048	LGE	1	45 ACW	SP	S		V	10/22/2109	
2020 PO4291088049	LGE	1	50 ACW	SP	S		V	10/23/2109	
2020 PO4286088118	LGE	3	20 ACW	SP	CRE		V	10/24/2109	
2020 PO4285888141	LGE	2	60 ACW	DF	P	ID	BD	10/25/2109	
2020 PO4283188131	LGE	4	35 ACW	SP	P	ID	BD	10/26/2109	
2020 PO4283588128	LGE	4	35 ACW	SP	P	ID	BD	10/27/2109	
2020 PO4284288127	LGE	4	35 ACW	SP	P	ED,ID,SR	TX	RR	10/28/2109
2020 PO4280688135	LGE	5	50 ACW	SP	CRE		V	10/29/2109	
2020 PO4287688103	LGE	5	50 ACW	SP	CRE		V	10/30/2109	
2020 PO4286888104	LGE	5	50 ACW	SP	CRE		V	10/31/2109	
2020 PO4285088106	LGE	5	20 ACW	SP	CRE	ED,HH,ID,IP,MD,RB	BX	PX	11/1/2109
2020 PO4285988107	LGE	5	25 ACW	SP	CRE		V	11/2/2109	
2020 PO4286088105	LGE	4	50 ACW	SP	CRE	ID	BD	11/3/2109	
2020 PO4285888090	LGE	4	30 ACW	SP	S		V	11/4/2109	
2020 PO4285788096	LGE	5	45 ACW	SP	CRE	ID,MD	BD	11/5/2109	
2020 PO4285888098	LGE	4	40 ACW	SP	CCA		V	11/6/2109	
2020 PO4285388097	LGE	4	30 ACW	SP	S		V	11/7/2109	

2020 PO4285288106	LGE	5	45 ACW	SP	CRE	ID	BD	11/8/2109
2020 PO4285488110	LGE	3	55 ACW	SP	CRE	ID	BD	11/9/2109
2020 PO4285588118	LGE	3	55 ACW	SP	P	ID	BD	11/10/2109
2020 PO4285588120	LGE	3	55 ACW	SP	CRE	ID	BD	11/11/2109
2020 PO4350888045	LGE	3	60 ACW	SP	CRE	ID	BD	11/12/2109
2020 PO4349088021	LGE	5	60 ACW	SP	P	ID	BD	11/13/2109
2020 PO4343187992	LGE	2	55 ACW	SP	CRE	ID,IP	BD	11/14/2109
2020 PO4341087996	LGE	6	35 ACW	SP	S		BD	11/15/2109
2020 PO4342787998	LGE	2	45 ACW	SP	A	ED,ID	BD	11/16/2109
2020 PO4342687997	LGE	2	45 ACW	SP	A	ED,ID	TD	11/17/2109
2020 PO4341887983	LGE	2	60 ACW	SP	CRE	ED,ID	BD	11/18/2109
2020 PO4340887979	LGE	4	30 ACW	SP	CRE	ED,ID	TD	11/19/2109
2020 PO4323002485	KU	3	50 XXX	SP	CRE	ED,ID	TD	11/20/2109
2020 PO7587276215	KU	4	45 BRO	SP	CRE		B	11/21/2109
2020 PO7588076378	KU	4	45 BRO	SP	CCA		B	11/22/2109
2020 PO7586576539	KU	4	40 BRO	SP	P	ED,ID	TD	11/23/2109
2020 PO7585376718	KU	4	40 BRO	SP	P	ED,ID	TD	11/24/2109
2020 PO7584976880	KU	4	40 BRO	SP	CCA	ED	T	11/25/2109
2020 PO7591777105	KU	3	45 BRO	SP	A	ED	T	11/26/2109
2020 PO7557777292	KU	4	30 BRO	SP	CRE	ED,HH,ID	BX	11/27/2109
2020 PO7553677300	KU	4	40 BRO	SP	CRE	ED,ID	BD	11/28/2109
2020 PO7599877281	KU	3	45 BRO	SP	CRE	ED,ID	TD	11/29/2109
2020 PO7595977403	KU	6	30 BRO	SP	CRE	ED,ID	TD	11/30/2109
2020 PO7604377396	KU	3	45 BRO	SP	CRE	ED,ID	TD	12/1/2109
2020 PO7613777609	KU	3	45 BRO	SP	CRE	ED,ID	TD	12/2/2109
2020 PO7609277748	KU	3	45 BRO	SP	P	ED,ID	TD	12/3/2109
2020 PO7605177851	KU	3	45 BRO	SP	P	ED,ID	TD	12/4/2109
2020 PO7584677964	KU	4	40 BRO	SP	CCA		V	12/5/2109
2020 PO7599377979	KU	3	45 BRO	SP	P	ED,ID	TD	12/6/2109
2020 PO7604178206	KU	5	35 BRO	SP	CCA		V	12/7/2109
2020 PO7596178124	KU	3	45 BRO	SP	CRE	ED,ID	BD	12/8/2109
2020 PO7599778532	KU	3	40 BRO	SP	P	ED,ID	BD	12/9/2109
2020 PO7603678620	KU	3	45 BRO	SP	CRE	ED,ID	TD	12/10/2109
2020 PO7608778724	KU	3	40 BRO	SP	CCA		V	12/11/2109
2020 PO7602078865	KU	4	45 BRO	SP	CRE	ED,ID	TD	12/12/2109
2020 PO2803504927	KU	4	45 BRO	SP	CRE	ID	BD	12/13/2109
2020 PO2800104957	KU	4	40 BRO	SP	CCA		V	12/14/2109
2020 PO2856105329	KU	6	30 BRO	SP	CCA		V	12/15/2109
2020 PO7294273826	KU	3	50 BRN	SP	CRE		V	12/16/2109
2020 PO7304774435	KU	3	50 BRN	SP	CRE	ED,ID	BD	12/17/2109
2020 PO7300274174	KU	3	50 BRN	SP	CRE	ED,ID	TD	12/18/2109
2020 PO7297273998	KU	3	50 BRN	SP	CRE	ED,ID	BD	12/19/2109
2020 PO7297774094	KU	3	50 BRN	SP	P	ED,ID	TD	12/20/2109
2020 PO7294674103	KU	4	45 BRN	SP	CCA		V	12/21/2109
2020 PO4565702819	KU	4	45 BRN	SP	CRE	ID	TD	12/22/2109
2020 PO6979486571	KU	4	40 BRO	SP	CCA		B	12/23/2109
2020 PO7501373823	KU	5	35 BRN	SP	CCA		V	12/24/2109

2020 PO7480773423A	KU	5	35 BRN	SP	CCA		V			12/25/2109
2020 PO7480773423	KU	5	35 BRN	SP	CCA		V			12/26/2109
2020 PO7459073445	KU	5	35 BRN	SP	CCA		V			12/27/2109
2020 PO7436973510	KU	5	35 BRN	SP	CCA		V			12/28/2109
2020 PO7412473580	KU	5	35 BRN	SP	CCA		V			12/29/2109
2020 PO6974187222	KU	4	40 BRO	SP	CRE	ID		BD		12/30/2109
2020 PO2835505354	KU	4	45 BRO	SP	CRE	ID		TD		12/31/2109
2020 PO2864205419	KU	4	40 BRO	SP	CRE	ID		TD		1/1/2110
2020 PO2870005383	KU	4	40 BRO	SP	CRE	ID		TD		1/2/2110
2020 PO2864005283	KU	4	40 BRO	SP	CCA		V			1/3/2110
2020 PO2873105251	KU	4	40 BRO	SP	CCA		V			1/4/2110
2020 PO2862105082	KU	4	40 BRO	SP	CCA		V			1/5/2110
2020 PO2855305127	KU	6	30 BRO	SP	CCA		V			1/6/2110
2020 PO6973787071	KU	4	40 BRO	SP	CRE	ED,ID		TD		1/7/2110
2020 PO6948586972	KU	3	50 BRO	SP	CRE	ED,ID,IP		BD		1/8/2110
2020 PO6942887145	KU	5	35 BRO	SP	CCA		V			1/9/2110
2020 PO6949587184	KU	5	30 BRO	SP	CRE	ED,ID		BD		1/10/2110
2020 PO6943987156	KU	5	35 BRO	SP	CCA		V			1/11/2110
2020 PO6907287320	KU	3	40 BRO	SP	CRE	ED,ID		TD		1/12/2110
2020 PO4352802178	KU	4	40 BRN	SP	CCA		V			1/13/2110
2020 PO4496902502	KU	5	35 BRN	SP	CRE	ED,ID		TD		1/14/2110
2020 PO6909186603	KU	4	40 BRO	SP	CRE	ED,ID		BD		1/15/2110
2020 PO2734505799	KU	5	35 BRO	SP	CRE	ID		TD		1/16/2110
2020 PO2806704820	KU	6	30 BRO	SP	CCA		V			1/17/2110
2020 PO2839404813	KU	6	30 BRO	SP	CCA		V			1/18/2110
2020 PO2826304914	KU	6	30 BRO	SP	CCA		V			1/19/2110
2020 PO2830804890	KU	6	30 BRO	SP	CCA		V			1/20/2110
2020 PO4484202456	KU	6	30 BRN	SP	CCA		V			1/21/2110
2020 PO4512802570	KU	5	35 BRN	SP	CRE	ED,ID		TD		1/22/2110
2020 PO4516602588	KU	4	45 BRN	SP	CCA		V			1/23/2110
2020 PO6912386636	KU	6	30 BRO	SP	CRE	ED,ID		TD		1/24/2110
2020 PO6913787146	KU	4	40 BRO	SP	CRE	ED,ID		TD		1/25/2110
2020 PO4522002616	KU	5	30 XXX	SP	CRE	ED,ID,SRC		TX	RR	1/26/2110
2020 PO6900286683	KU	4	45 BRO	SP	CRE	ED,ID		BD		1/27/2110
2020 PO2731205326	KU	3	50 UNK	SP	CCA		V			1/28/2110
2020 PO2742805190	KU	4	40 UNK	SP	CRE		V			1/29/2110
2020 PO2756305030	KU	4	45 UNK	SP	CRE		V			1/30/2110
2020 PO2770304858	KU	4	45 UNK	SP	CRE		V			1/31/2110
2020 PO6899687381	KU	1	80 BRO	SP	CRE	HH,ID,IP		BX	RP3	2/1/2110
2020 PO6933886866	KU	4	40 BRO	SP	CRE	ED,ID,RB		BX	RR	2/2/2110
2020 PO6927386990	KU	3	45 BRO	SP	A	ED,HH,ID,RB		X	PX	2/3/2110
2020 PO6927386990A	KU	6	30 BRO	SP	A	ED,ID		TD		2/4/2110
2020 PO6896686887	KU	3	35 BRO	SP	CRE	ED,ID		TD		2/5/2110
2020 PO2836405030	KU	6	30 BRO	SP	CCA		V			2/6/2110
2020 PO2824705121	KU	6	30 BRO	SP	CCA		V			2/7/2110
2020 PO2822105154	KU	4	40 BRO	SP	CRE	ID		BD		2/8/2110
2020 PO2814105246	KU	4	45 BRO	SP	CRE	ID		BD		2/9/2110

2020 PO2822105186	KU	6	30 BRO	SP	CCA		V	2/10/2110	
2020 PO2839005241	KU	4	45 BRO	SP	CCA		V	2/11/2110	
2020 PO2848505522	KU	4	45 BRO	SP	CRE	ID	BD	2/12/2110	
2020 PO4807487715	LGE	4	40 BRN	SP	CRE		V	2/13/2110	
2020 PO4807687707	LGE	4	40 BRN	SP	CRE		V	2/14/2110	
2020 PO4915887200	LGE	3	45 OTH	SP	P	ID	BD	2/15/2110	
2020 PO4915687204	LGE	3	45 OTH	SP	P	ID	BD	2/16/2110	
2020 PO4917187166	LGE	3	45 OTH	SP	P	ID	BD	2/17/2110	
2020 PO4916387183	LGE	3	45 OTH	SP	P	ED,ID,IP,SRC	TD	2/18/2110	
2020 PO4918987068	LGE	3	45 OTH	SP	P	ID	BD	2/19/2110	
2020 PO4919587087	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	2/20/2110	
2020 PO4917287161	LGE	3	45 OTH	SP	P	ED,ID,SRS	TD	2/21/2110	
2020 PO4917287161A	LGE	3	45 OTH	SP	P	ED,ID,SRS	TD	2/22/2110	
2020 PO4915287132	LGE	4	40 OTH	SP	P	ED,ID,SRS	TD	2/23/2110	
2020 PO4918187139	LGE	3	45 OTH	SP	P	ID,IP	BD	2/24/2110	
2020 PO4864986502	LGE	3	45 XXX	SP	P	ED,ID	TD	2/25/2110	
2020 PO4864986494	LGE	3	45 XXX	SP	P	ID	TD	2/26/2110	
2020 PO4919987072	LGE	4	40 OTH	SP	A	ID	BD	2/27/2110	
2020 PO4919687026	LGE	4E	35E OTH	SP	A	ID	BD	2/28/2110	
2020 PO4922486996	LGE	H2	65 OTH	SP	A	ID	BD	3/1/2110	
2020 PO4851486350	LGE	3	45 OTH	SP	P	ID	BD	3/2/2110	
2020 PO4853186356	LGE	3	45 OTH	SP	P	ED,ID,SRC	TD	3/3/2110	
2020 PO4863086509	LGE	2	45 XXX	SP	P	ID	BD	3/4/2110	
2020 PO4863086501	LGE	4	30 XXX	SP	P	ID	TD	3/5/2110	
2020 PO4878587643	LGE	4	40 XXX	SP	A	ED,ID	TD	3/6/2110	
2020 PO4877887663	LGE	5	40 XXX	SP	CRE	ED,ID	TD	3/7/2110	
2020 PO4878387651	LGE	4	40 XXX	SP	CCA		V	3/8/2110	
2020 PO4877587675	LGE	3	45 XXX	SP	CCA		V	3/9/2110	
2020 PO4877187685	LGE	4	40 XXX	SP	P		V	3/10/2110	
2020 PO6368382383	LGE	1	50 OTH	SP	CCA		V	3/11/2110	
2020 PO4925286951	LGE	1	50 OTH	SP	CCA		V	3/12/2110	
2020 PO4924386918	LGE	4	40 OTH	SP	CCA		V	3/13/2110	
2020 PO4926186894	LGE	3	50 OTH	SP	CCA		V	3/14/2110	
2020 PO4927086872	LGE	4	40 OTH	SP	P	ED,ID,SRS	TD	3/15/2110	
2020 PO4927886849	LGE	2E	50E OTH	SP	CRE	ED,HH,ID,MD	BD	3/16/2110	
2020 PO4861786261	LGE	4	35 OTH	SP	CCA		V	3/17/2110	
2020 PO4859486247	F	3	45 OTH	SP	CCA		V	3/18/2110	
2020 PO4865086264	F	3	50 OTH	SP	CCA		V	3/19/2110	
2020 PO4858086235	LGE	4	40 OTH	SP	P	ED,ID,SRC	TX	RR	3/20/2110
2020 PO4861986254	F	1	55 OTH	SP	CCA		V	3/21/2110	
2020 PO4863486260	F	3	45 OTH	SP	CCA		V	3/22/2110	
2020 PO4857686524	LGE	2	50 XXX	SP	P	HH,ID	X	RP2	3/23/2110
2020 PO4855786515A	LGE	5	25 XXX	SP	CCA		V	3/24/2110	
2020 PO4855786515	LGE	1	55 XXX	SP	P	ID	BD	3/25/2110	
2020 PO4686186268	F	3	50 OTH	SP	P		V	3/26/2110	
2020 PO4876287712	LGE	4	40 XXX	SP	A	ID	BD	3/27/2110	
2020 PO4657488937	LGE	4	40 BRO	SP	CRE	ED	TD	3/28/2110	

2020 PO4636488942	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	3/29/2110
2020 PO4646089014	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	3/30/2110
2020 PO4645789012	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	3/31/2110
2020 PO4853686520A	LGE	5	30 XXX	SP	P	ID	TD	4/1/2110
2020 PO4853686520	LGE	4	45 XXX	SP	P	ID	BD	4/2/2110
2020 PO4875887724	LGE	3	45 XXX	SP	A	ED,ID	TD	4/3/2110
2020 PO4875587736	LGE	4	40 XXX	SP	CCA		V	4/4/2110
2020 PO4644889032	LGE	4	40 BRO	SP	CRE	ID,IP	BD	4/5/2110
2020 PO4864686309	LGE	4	30 OTH	SP	P	ED,SRS	TD	4/6/2110
2020 PO4865586284	F	3	45 OTH	SP	P		V	4/7/2110
2020 PO4864986310	LGE	3	45 OTH	SP	P	ED,SRS	TD	4/8/2110
2020 PO4865486286	LGE	3	45 OTH	SP	P	ED,SRS	TD	4/9/2110
2020 PO4853786509	LGE	5	25 XXX	SP	P	ID	BD	4/10/2110
2020 PO4853886512	LGE	2	50 XXX	SP	P	ID	BD	4/11/2110
2020 PO4513886504A	LGE	5	25 XXX	SP	CCA		V	4/12/2110
2020 PO4852386564	LGE	2	50 XXX	SP	CCA		V	4/13/2110
2020 PO4850286565	LGE	2	50 XXX	SP	P	ID	TD	4/14/2110
2020 PO4848186559	LGE	2	50 XXX	SP	P	ID	BD	4/15/2110
2020 PO4847086546	LGE	3	45 XXX	SP	CCA		V	4/16/2110
2020 PO4847886525	LGE	1	50 XXX	SP	CCA	ED	T	4/17/2110
2020 PO4847186545	LGE	3	50 XXX	SP	P	ID	BD	4/18/2110
2020 PO4846686543	LGE	3	50 XXX	SP	CCA		V	4/19/2110
2020 PO4847886525A	LGE	5	30 XXX	SP	CCA	ID	BD	4/20/2110
2020 PO4848286511	LGE	2	50 XXX	SP	P	ID	BD	4/21/2110
2020 PO4847286491	LGE	2	50 XXX	SP	P	ID	BD	4/22/2110
2020 PO4845586486	LGE	2	50 XXX	SP	P	ID	TD	4/23/2110
2020 PO4840886554	LGE	3	50 XXX	SP	P	ID	BD	4/24/2110
2020 PO4841386539	LGE	3	50 XXX	SP	P	ID	BD	4/25/2110
2020 PO4831286469	LGE	4	30 XXX	SP	CCA		V	4/26/2110
2020 PO4646388987	LGE	4	40 BRO	SP	CRE	ID,IP	BD	4/27/2110
2020 PO4646989004	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/28/2110
2020 PO5847775819	LGE	1	50 OTH	SP	CCA		V	4/29/2110
2020 PO4873986288A	LGE	4	30 OTH	SP	CCA	ED,SRS	TD	4/30/2110
2020 PO4873786294	LGE	1	20 OTH	UN	P		V	5/1/2110
2020 PO4873986288	F	2	50 OTH	SP	CCA		V	5/2/2110
2020 PO4871086292	F	3	45 OTH	SP	P		V	5/3/2110
2020 PO4871786282	F	3	50 OTH	SP	P		V	5/4/2110
2020 PO4929686805	F	3	45 OTH	SP	CCA		V	5/5/2110
2020 PO4933586818	F	4	40 OTH	SP	CRE		V	5/6/2110
2020 PO4933286824	LGE	4	40 OTH	SP	CRE	ED,ID,IP,SRS	TD	5/7/2110
2020 PO4935286830	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	5/8/2110
2020 PO4874786311A	F	3	50 OTH	SP	P		V	5/9/2110
2020 PO4874786311	F	3	50 OTH	SP	P		V	5/10/2110
2020 PO4877986299	LGE	3	50 OTH	SP	P	ED,ID	BD	5/11/2110
2020 PO4877986299	LGE	2	55 OTH	SP	CCA	ED,SRS	TD	5/12/2110
2020 PO4878986284	LGE	3	45 OTH	SP	P	ID	TD	5/13/2110
2020 PO4875386298	F	2	50 OTH	SP	P		V	5/14/2110

2020 PO4878486296	LGE	3	50 OTH	SP	CCA		V	5/15/2110
2020 PO4874886309	LGE	3	50 OTH	SP	CCA		V	5/16/2110
2020 PO4648188988	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	5/17/2110
2020 PO4782887967	LGE	4	40 BRO	SP	CRE	ED	TD	5/18/2110
2020 PO4648888980	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	5/19/2110
2020 PO4781787954	LGE	4	40 BRO	SP	P	ED	TD	5/20/2110
2020 PO4779887747	F	UNK	45 BRO	SP	CRE		V	5/21/2110
2020 PO4785187970	LGE	UNK	30 BRO	SP	CRE	ED	BD	5/22/2110
2020 PO4781288000	LGE	4	40 BRO	SP	CRE	ED	BD	5/23/2110
2020 PO4782587990	LGE	4	40 BRO	SP	CRE	ED	B	5/24/2110
2020 PO4783887980	LGE	UNK	45 BRO	SP	CRE	ED	TD	5/25/2110
2020 PO4882286321	LGE	3	50 OTH	SP	CCA	ED,SRS	TD	5/26/2110
2020 PO4880286316	LGE	3	50 OTH	SP	CCA	ED,SRS	TD	5/27/2110
2020 PO4884286326	LGE	3	50 OTH	SP	CCA	ED,SRS	TD	5/28/2110
2020 PO4649288974	LGE	4	40 BRO	SP	CRE	ID,IP	BD	5/29/2110
2020 PO4886586330	LGE	3	50 OTH	SP	CCA	ED,SRS	TD	5/30/2110
2020 PO4887086324	LGE	4	30 OTH	SP	CCA	ED,SRS	TD	5/31/2110
2020 PO4886586332	LGE	2	55 OTH	SP	CCA	ED,SRS	TD	6/1/2110
2020 PO4886586322	LGE	3	50 OTH	SP	CCA	ED,SRS	TD	6/2/2110
2020 PO4885486351	LGE	3	45 OTH	SP	CCA	ED,SRS	TD	6/3/2110
2020 PO4936486834	LGE	5E	40E OTH	SP	CRE	ED,ID,SRS	TD	6/4/2110
2020 PO4802387923	LGE	4	35 BRN	SP	CCA		V	6/5/2110
2020 PO4802987920	LGE	4	40 BRN	SP	CRE	ED,ID	TD	6/6/2110
2020 PO4803287909	LGE	4	40 BRN	SP	P	ED,ID	TD	6/7/2110
2020 PO4803187914	LGE	4	40 BRN	SP	CRE	ED,ID	BD	6/8/2110
2020 PO4802687913	LGE	4	30 BRN	SP	CRE	ED,ID	TD	6/9/2110
2020 PO4779887959	LGE	4	30 BRO	SP	CRE	ED	BD	6/10/2110
2020 PO4780487961	LGE	4	40 BRO	SP	CRE	ED	TD	6/11/2110
2020 PO4779187976	LGE	4	40 BRO	SP	CRE	ED	TD	6/12/2110
2020 PO4893587152	F	1	25E OTH	ST	CCA		V	6/13/2110
2020 PO4803787891	LGE	4	40 BRN	SP	CRE	ED,ID	BD	6/14/2110
2020 PO4803287890	LGE	4	30 BRN	SP	CRE	ED,ID	BD	6/15/2110
2020 PO4803987881	LGE	4	40 BRN	SP	A	ED,ID	BD	6/16/2110
2020 PO4779987835	F	UNK	45 BRO	SP	CRE		V	6/17/2110
2020 PO4779987849	F	3	45 BRO	SP	CCA		V	6/18/2110
2020 PO4884786377	LGE	3	45 OTH	SP	CCA	ED	TD	6/19/2110
2020 PO4779287880	LGE	UNK	45 BRO	SP	CRE	ED	TD	6/20/2110
2020 PO4876187419	LGE	4	40 XXX	SP	A		V	6/21/2110
2020 PO4887086775	LGE	3	45 XXX	SP	A	ID	BD	6/22/2110
2020 PO4885986775	LGE	1	65 XXX	SP	A	ID	BD	6/23/2110
2020 PO4885686775	LGE	1	65 XXX	SP	A	ID	BD	6/24/2110
2020 PO4884386774	LGE	1	65 XXX	SP	CRE	ID	BD	6/25/2110
2020 PO4883586775	LGE	1	65 XXX	DF	A	ID	BD	6/26/2110
2020 PO4881686776	LGE	2	65 XXX	DF	P	ID	BD	6/27/2110
2020 PO4879986785	LGE	1	65 XXX	SP	A	ED,ID	TD	6/28/2110
2020 PO4878886801	LGE	1	65 XXX	SP	CRE	ED,ID	TD	6/29/2110
2020 PO4912486713	LGE	3	50 OTH	SP	P	ID	BD	6/30/2110

2020 PO4912586711	LGE	4	40 OTH	SP	CCA	ED,SRS	TD	7/1/2110
2020 PV4828586255	LGE	2	45 XXX	SP	P	ID	TD	7/2/2110
2020 PO4879586807	LGE	4	35 XXX	SP	A	ID	BD	7/3/2110
2020 PO4829886252	LGE	3	45 XXX	SP	P	ID	TD	7/4/2110
2020 PV4829486248	LGE	4	45 XXX	SP	P	ID	TD	7/5/2110
2020 PO4830086242	LGE	4	40 XXX	SP	P	ID	TD	7/6/2110
2020 PO4911886736	LGE	3	50 OTH	SP	P	ID,IP	BD	7/7/2110
2020 PO4911886734	LGE	3	50 OTH	SP	P	ID	BD	7/8/2110
2020 PO4879286824	LGE	1	65 XXX	SP	CRE	ID,IP	BD	7/9/2110
2020 PO4840286845	LGE	4	40 XXX	SP	CCA		V	7/10/2110
2020 PO4908086750	LGE	4	40 OTH	UN	P		V	7/11/2110
2020 PO6222580783	LGE	3	45 OTH	SP	CCA		V	7/12/2110
2020 PO4879086851	LGE	1	65 XXX	SP	A	ED,ID	TD	7/13/2110
2020 PO4879186855	LGE	1	65 XXX	SP	CRE	ED,ID	TD	7/14/2110
2020 PO4845486915	F	1	55 XXX	SP	P		V	7/15/2110
2020 PO4844686897	F	4	40 XXX	SP	P		V	7/16/2110
2020 PO4903086813	LGE	4	40 OTH	SP	P		V	7/17/2110
2020 PO4901386829	LGE	4	30 OTH	SP	P		V	7/18/2110
2020 PO4901686822	LGE	4	40 OTH	SP	P		V	7/19/2110
2020 PO4906286787	LGE	4	40 OTH	SP	P		V	7/20/2110
2020 PO4843886879	F	3	45 XXX	SP	CCA		V	7/21/2110
2020 PO4843186863	F	4	40 XXX	SP	P		V	7/22/2110
2020 PO4845086868	LGE	2	45 XXX	SP	A	ED,ID	TX	RR 7/23/2110
2020 PO4842786844	LGE	4	25 XXX	SP	P		V	7/24/2110
2020 PO4846686861	LGE	4	40 XXX	SP	A	ID,IP	BD	7/25/2110
2020 PO4922786775	LGE	4	35 OTH	SP	CRE	ED,ID,SRS	TD	7/26/2110
2020 PO4922786775A	LGE	4	40 OTH	SP	P	ED,ID,SRS	TD	7/27/2110
2020 PO4920286744	LGE	3	45 OTH	SP	P	ED,ID,SRS	TD	7/28/2110
2020 PO5549381793	LGE	3	45 XXX	SP	CCA		V	7/29/2110
2020 PO4842586881	LGE	4	40 XXX	SP	P	ID	TD	7/30/2110
2020 PO4841286850	LGE	3	45 XXX	SP	CCA		V	7/31/2110
2020 PO4841586864	LGE	4	40 XXX	SP	A	ED,ID	TX	RR 8/1/2110
2020 PO4842586850	F	1	55 XXX	SP	CCA		V	8/2/2110
2020 PO4842686844	LGE	4	35 XXX	SP	P	ID	TD	8/3/2110
2020 PO4842586818	LGE	4	40 XXX	SP	A	ID	TD	8/4/2110
2020 PO4841586828	F	3	50 XXX	SP	A		V	8/5/2110
2020 PO4840786810	F	3	50 XXX	SP	CRE		V	8/6/2110
2020 PO4839786806	LGE	4	35 XXX	SP	P	ID	TD	8/7/2110
2020 PO4878586881	LGE	1	65 XXX	SP	CRE	ID	BD	8/8/2110
2020 PO5901881996	LGE	H2	65 XXX	SP	P		V	8/9/2110
2020 PO4924586715	LGE	3	50 OTH	SP	P	ED,ID,SRS	TD	8/10/2110
2020 PO6439279859	LGE	3	45 OTH	SP	CCA		V	8/11/2110
2020 PO6443279870	LGE	3	45 OTH	SP	CCA		V	8/12/2110
2020 PO4869786896	LGE	5	30 XXX	SP	A	ID,IP	BD	8/13/2110
2020 PO4871486911a	LGE	3	45 XXX	SP	CCA	ED	T	8/14/2110
2020 PO4871786886	LGE	3	45 XXX	SP	CCA		V	8/15/2110
2020 PO4831386783	LGE	3	50 XXX	SP	P	ID	BD	8/16/2110

2020 PO4835086749	LGE	4	40 XXX	SP	P	ID	BD	8/17/2110
2020 PO4836386738	LGE	3	45 XXX	SP	P	ID	TD	8/18/2110
2020 PO4836686735	LGE	1	50 XXX	SP	CCA		V	8/19/2110
2020 PO4958286832	LGE	4	40 OTH	SP	P	ED,EP,SRC	TX RR	8/20/2110
2020 PO6463580291	LGE	4	40 OTH	SP	P	ED,ID,SRS	TD	8/21/2110
2020 PO4938286744	LGE	4	40 OTH	UN	CCA		V	8/22/2110
2020 PO4871486911	LGE	1	65 XXX	SP	CRE	ED,ID	TD	8/23/2110
2020 PO4961886885	LGE	4	40 OTH	SP	P	ED,EP,ID,SRC	TX RR	8/24/2110
2020 PO4962086859	LGE	4	40 OTH	SP	P	ED,ID,IP,SRS	TD	8/25/2110
2020 PO4962986800	LGE	4	40 OTH	SP	P	ED,ID,SRS	TD	8/26/2110
2020 PO4831186752	LGE	4	40 XXX	SP	P	ID	TD	8/27/2110
2020 PO4831586736	LGE	4	35 XXX	SP	P	ED,ID	TX RR	8/28/2110
2020 PO4830586744	LGE	4	40 XXX	SP	P	ID	TD	8/29/2110
2020 PO4830786723	LGE	4	35 XXX	SP	A	ED,ID	TX RR	8/30/2110
2020 PO4830086710	LGE	4	35 XXX	SP	P	ID	TD	8/31/2110
2020 PO4832086690	LGE	3	45 XXX	SP	CCA		V	9/1/2110
2020 PO4831886699	LGE	4	40 XXX	SP	P	ID	TD	9/2/2110
2020 PO4832486694	LGE	4	40 XXX	SP	CCA	ED	T	9/3/2110
2020 PO4869586904	LGE	1	65 XXX	SP	CRE	ED,ID	TD	9/4/2110
2020 PO4956786821	LGE	4	45 OTH	SP	P	ED,ID,SRS	TD	9/5/2110
2020 PO4956086819	LGE	4	30 OTH	SP	P	ED,ID	BD	9/6/2110
2020 PO4869086931	LGE	3	50 XXX	SP	CCA		V	9/7/2110
2020 PO5808282380A	LGE	1	50 XXX	SP	CCA		V	9/8/2110
2020 PO4865786984	LGE	3	45 XXX	SP	A	ID	BD	9/9/2110
2020 PO4865786970	LGE	3	45 XXX	SP	A	ID	BD	9/10/2110
2020 PO4866086956	LGE	3	45 XXX	SP	CCA		V	9/11/2110
2020 PO4956586817	LGE	4	30 OTH	UN	CCA		V	9/12/2110
2020 PO4866486943	LGE	4	40 XXX	SP	A	ID	BD	9/13/2110
2020 PO4866686934	LGE	4	40 XXX	SP	A	ID	BD	9/14/2110
2020 PO4867086917	LGE	4	40 XXX	SP	A	ID	BD	9/15/2110
2020 PO4867686898	LGE	3	45 XXX	SP	CCA		V	9/16/2110
2020 PO4832686695	LGE	4	35 XXX	SP	A	ED,ID	TX RR	9/17/2110
2020 PO4831386702	LGE	4	35 XXX	SP	A	ID	TD	9/18/2110
2020 PO4840086670	LGE	4	30 XXX	SP	P		V	9/19/2110
2020 PO5519979598	LGE	4	30 XXX	SP	CRE		V	9/20/2110
2020 PO4867686891	LGE	3	50 XXX	SP	A	ID	BD	9/21/2110
2020 PO4866386889	LGE	3	45 XXX	SP	A	ED,ID	TD	9/22/2110
2020 PO4843886940	LGE	H1	105 XXX	AL	A		V	9/23/2110
2020 PO4879987162	LGE	4	40 XXX	SP	CCA		V	9/24/2110
2020 PO4880086900	LGE	1	20 XXX	SP	A		V	9/25/2110
2020 PO4885986827	LGE	4	35 XXX	SP	CCA		V	9/26/2110
2020 PO4868686931	LGE	4	35 XXX	SP	CCA		V	9/27/2110
2020 PO4867086870	LGE	1	20 XXX	SP	A		V	9/28/2110
2020 PO4846186871	LGE	4	35 XXX	SP	CCA		V	9/29/2110
2020 PO4832987229	LGE	4	30 XXX	SP	CCA		V	9/30/2110
2020 PO4834787260	LGE	4	40 XXX	SP	A	ID	BD	10/1/2110
2020 PO4878487254	LGE	3	45 XXX	SP	A	ED,ID	TD	10/2/2110

2020 PO4878987235	LGE	3	45 XXX	SP	CCA		V	10/3/2110
2020 PO4881587164	LGE	3	50 XXX	SP	CCA		V	10/4/2110
2020 PO4879487159	LGE	3	45 XXX	SP	A	ED,ID	TD	10/5/2110
2020 PO4880387208	LGE	3	45 XXX	SP	A	ED,ID,SRC	TX	10/6/2110
2020 PO4879587228	LGE	3	50 XXX	SP	CCA		V	10/7/2110
2020 PO4879687217	LGE	3	45 XXX	SP	A	ID,IP	BD	10/8/2110
2020 PO4880187237	LGE	3	45 XXX	SP	CCA		V	10/9/2110
2020 PO4880587220	LGE	3	45 XXX	SP	CCA		V	10/10/2110
2020 PO4646888974	LGE	4	40 OTH	SP	P	ED,SRS	TD	10/11/2110
2020 PO4646988980	LGE	3	45 OTH	SP	CCA	ED,SRS	TD	10/12/2110
2020 PO4790387787	LGE	4	30 XXX	SP	CCA		V	10/13/2110
2020 PO4637688951	LGE	4	40 OTH	SP	CRE	ED,ID,IP,SRS	TD	10/14/2110
2020 PO4640188970	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	10/15/2110
2020 PO4664488766	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	10/16/2110
2020 PO4798687624	LGE	UNK	45 XXX	SP	A		V	10/17/2110
2020 PO4798887874	LGE	4	40 XXX	SP	CCA		V	10/18/2110
2020 PO4799787873	LGE	4	35 XXX	SP	CCA		V	10/19/2110
2020 PO4800887871	LGE	4	40 XXX	SP	CCA		V	10/20/2110
2020 PO4656289106	LGE	4	35 KOP	SP	A	ID	BD	10/21/2110
2020 PO4663588779	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	10/22/2110
2020 PO4662188799	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	10/23/2110
2020 PO6162115705	KU	5	40 XXX	SP	CRE	ED,ID	TD	10/24/2110
2020 PO6130915293	KU	5	40 XXX	SP	CRE	ED,ID	TD	10/25/2110
2020 PO7675439423	KU	4	40 OTH	SP	CRE	ID	TD	10/26/2110
2020 PO7688639465	KU	4	40 OTH	SP	CRE	ID	TD	10/27/2110
2020 PO6145115484	KU	3	45 XXX	SP	CCA		V	10/28/2110
2020 PO4669088018	LGE	3	45 BRN	SP	A	ED,ID	BD	10/29/2110
2020 PO4671788867	LGE	3	45 BRO	SP	P	ED	T	10/30/2110
2020 PO1581934509	ODP	2	60 BRO	SP	CRE	ID	BD	10/31/2110
2020 PO7570539420	F	4	40 OTH	SP	P		V	11/1/2110
2020 PO7995439583	KU	4	40 OTH	SP	CCA		V	11/2/2110
2020 PO7883339440	KU	4	40 OTH	SP	CCA	ED,SRS	TD	11/3/2110
2020 PO7885639558	KU	4	40 OTH	SP	CRE	ED,ID,IP	TD	11/4/2110
2020 PO4644059182	KU	4	40 OTH	SP	CRE	ID	TD	11/5/2110
2020 PO4619958461	KU	4	40 OTH	SP	CCA		V	11/6/2110
2020 PO4584658547	KU	4	40 OTH	SP	CRE	ID	TD	11/7/2110
2020 PO4591558138	KU	4	45 OTH	SP	CCA		V	11/8/2110
2020 PO7574939419	KU	4	40 OTH	SP	CRE	ID	TD	11/9/2110
2020 PO4665759048	KU	4	40 OTH	SP	CRE	ID	TD	11/10/2110
2020 PO4669688877	LGE	4	40 BRO	SP	CCA		V	11/11/2110
2020 PO4667888864	LGE	4	35 BRO	SP	CCA		V	11/12/2110
2020 PO6163716337	KU	4	40 XXX	SP	CRE	ED,ID	TD	11/13/2110
2020 PO6175016152	KU	5	45 XXX	SP	CRE	ED,ID	TD	11/14/2110
2020 PO3752401241	LGE	3	45 BRO	SP	CCA		V	11/15/2110
2020 PO4665588847	LGE	4	40 BRO	SP	P	ED	TD	11/16/2110
2020 PO6164116674	KU	4	40 XXX	SP	CCA		V	11/17/2110
2020 PO4664888841	LGE	4	40 BRO	SP	CCA		V	11/18/2110

2020 PO6187016585	KU		4	45 XXX	SP	CRE	ED,ID	TD	11/19/2110
2020 PO6195416882	KU		4	40 XXX	SP	CRE	ED,ID	TD	11/20/2110
2020 PO4664588867	LGE		4	40 BRO	SP	A	ID,IP	BD	11/21/2110
2020 PO6201317090	KU		4	40 BRN	SP	CRE	ID	BD	11/22/2110
2020 PO6172717285	KU		4	45 BRN	SP	P		V	11/23/2110
2020 PO6184317224	KU		3	45 BRN	SP	CCA		V	11/24/2110
2020 PO6189417196	KU		3	45 BRN	SP	CCA		V	11/25/2110
2020 PO6204517206	KU		4	40 ACW	SP	CRE	ED,ID	TD	11/26/2110
2020 PO4707188285	LGE		4	30 BRO	SP	P	ED,ID	TD	11/27/2110
2020 PO4705488278	LGE	H1		70 BRO	SP	CRE		V	11/28/2110
2020 PO5683210514	KU		6	30 XXX	SP	CRE		V	11/29/2110
2020 PO4704188301	LGE		4	30 BRO	SP	CRE	ED,ID	BD	11/30/2110
2020 PO4704688299	LGE	UNK		65 BRO	SP	CRE		V	12/1/2110
2020 PO4705088289	LGE		4	40 BRO	SP	CRE	ED,ID	TD	12/2/2110
2020 PO4704488304	LGE	H1		70 BRO	SP	A		V	12/3/2110
2020 PO4704288310	LGE	H1		70 BRO	SP	A		V	12/4/2110
2020 PO4705188301	LGE		4	35 BRO	ST	CCA		V	12/5/2110
2020 PO4706788329	LGE		3	45 BRO	SP	A	ED,ID	TD	12/6/2110
2020 PO4706688327	LGE	H1		65 BRO	SP	CRE		V	12/7/2110
2020 PO4161396119	F		4	35 BRO	SP	CCA		V	12/8/2110
2020 PO4154396066	F		4	35 BRO	SP	CRE		V	12/9/2110
2020 PO4148996025	F		4	35 BRO	SP	CCA		V	12/10/2110
2020 PO4705288317	LGE	H1		65 BRO	SP	CRE		V	12/11/2110
2020 PO4710988370	LGE	3H		45 BRO	SP	CRE	ED,ID	BD	12/12/2110
2020 PO4710088364	LGE		4	30 BRO	SP	CCA		V	12/13/2110
2020 PO4710488356	LGE	UNK		70 BRO	SP	A		V	12/14/2110
2020 PO4708788354	LGE		4	35 BRO	SP	CRE	ED,ID	TD	12/15/2110
2020 PO4708888375	LGE		4	30 BRO	SP	A	ED,ID	TD	12/16/2110
2020 PO4711688365	LGE	UNK		65 BRO	SP	A		V	12/17/2110
2020 PO4713188379	LGE	H1		70 BRO	SP	CCA		V	12/18/2110
2020 PO4712388359	LGE		4	40 BRO	SP	CCA		V	12/19/2110
2020 PO4713588350	LGE		4	40 BRO	SP	CCA		V	12/20/2110
2020 PO4715588408	LGE		4	40 BRO	SP	CRE	ED,ID,RB	X	RP2 12/21/2110
2020 PO4715888403	LGE	UNK		65 BRO	SP	CRE		V	12/22/2110
2020 PO2175647945	ODP		5	35 KOP	SP	CRE	ID	V	12/23/2110
2020 PO2136347631	ODP		4	40 KOP	SP	S		V	12/24/2110
2020 PO2115747355	ODP		5	35 KOP	SP	CRE	ID	V	12/25/2110
2020 PO2101447164	ODP		5	35 KOP	SP	CRE		V	12/26/2110
2020 PO2084546933	ODP		4	40 KOP	SP	CRE	ID	BD	12/27/2110
2020 PO2047146803	ODP		5	35 KOP	SP	CRE	ID	BD	12/28/2110
2020 PO2011846678	ODP		5	35 KOP	SP	CRE	ID	BD	12/29/2110
2020 PO4719588434	LGE		3	45 BRO	SP	CRE	ED,ID	TD	12/30/2110
2020 5760704598a	KU		6	30 XXX	SP	CCA		V	12/31/2110
2020 PO5760704598	KU		3	45 XXX	SP	CCA		V	1/1/2111
2020 PO5754904753	KU		4	40 XXX	SP	CRE	ED,ID	TD	1/2/2111
2020 PO5758004924	KU		4	40 XXX	SP	CRE	ED,ID	TD	1/3/2111
2020 PO5754605088	KU		4	40 XXX	SP	CRE	ED,ID	TD	1/4/2111

2020 PO5740004897	KU	4	45 XXX	SP	CRE	ED,ID	TD	1/5/2111
2020 PO5728704882	KU	4	45 XXX	SP	CRE	ED,ID	TD	1/6/2111
2020 PO5708204928	KU	4	40 XXX	SP	CRE	ID	BD	1/7/2111
2020 PO5700105150	KU	6	30 XXX	SP	CRE	ED,ID	TD	1/8/2111
2020 PO5718905179	KU	6	30 XXX	SP	CRE	ED,ID	TD	1/9/2111
2020 PO7145938638	KU	3	45 OTH	SP	CCA		V	1/10/2111
2020 PO7144738593	KU	6	30 OTH	SP	CRE	ED,ID	BD	1/11/2111
2020 PO7177238544	KU	4	40 OTH	SP	CRE	ID	TD	1/12/2111
2020 PO7258438381	KU	6	40 OTH	SP	CCA	ED,SRS	TD	1/13/2111
2020 PO7262338298	KU	4	45 OTH	SP	CRE	ID	TD	1/14/2111
2020 PO7206638458	KU	4	40 OTH	SP	CRE	ID	TD	1/15/2111
2020 PO7235338358	KU	3	50 OTH	SP	CRE	ID	TD	1/16/2111
2020 PO3793087665	KU	3	45 XXX	SP	CCA		V	1/17/2111
2020 PO3782687850	KU	3	45 XXX	SP	CCA	ED	T	1/18/2111
2020 PO3778787920	KU	4	40 XXX	SP	CCA		V	1/19/2111
2020 PO3698687730	KU	5	35 XXX	SP	CCA		V	1/20/2111
2020 PO5739205212	KU	6	30 XXX	SP	CRE	ED,ID	TD	1/21/2111
2020 PO5748505344	KU	4	45 XXX	SP	CRE	ED,ID	TD	1/22/2111
2020 PO5742105569	KU	4	40 XXX	SP	CRE	ED,ID	TD	1/23/2111
2020 PO5735405771	KU	3	50 XXX	SP	CRE	ED,ID	TD	1/24/2111
2020 7311738388A	KU	4	45 OTH	SP	CRE	ID	TD	1/25/2111
2020 PO7283038188	KU	4	40 OTH	SP	CCA	ED,SRS	TD	1/26/2111
2020 PO7291838320	KU	4	40 OTH	SP	CRE	ID	TD	1/27/2111
2020 PO3753688102	KU	3	45 XXX	SP	CCA	ED	T	1/28/2111
2020 PO3764288189	KU	5	35 XXX	SP	CCA		V	1/29/2111
2020 PO3744688057	KU	3	45 XXX	SP	CCA	ED	T	1/30/2111
2020 PO3724587933	KU	5	35 XXX	SP	CCA		V	1/31/2111
2020 PO4714688384	LGE	3	45 BRO	SP	P	ED,ID	T	2/1/2111
2020 PO4715988374	LGE	4	40 BRO	SP	CRE	ED,ID	BD	2/2/2111
2020 PO4717088365	LGE	4	40 BRO	SP	P	ED,ID	T	2/3/2111
2020 PO4719488347	LGE	4	40 BRO	SP	CRE	ED,ID	TD	2/4/2111
2020 PO4718288346	LGE	4	40 BRO	SP	CCA		V	2/5/2111
2020 PO4721288333	LGE	4	40 BRO	SP	CRE	ED,HH,ID,RB	VX	PX 2/6/2111
2020 PO4720388350	LGE	4	35 BRO	SP	A	ED,ID	TD	2/7/2111
2020 PO5729405961	KU	4	45 XXX	SP	CCA		V	2/8/2111
2020 PO4659188342	LGE	4	40 BRN	SP	A	ED,ID	TD	2/9/2111
2020 PO4658288336	LGE	4	40 BRN	SP	A	ED,ID	TD	2/10/2111
2020 PO3734288004	KU	3	45 XXX	SP	CCA	ED	T	2/11/2111
2020 PO3715787912	KU	3	45 XXX	SP	CCA	ED	T	2/12/2111
2020 PO3694687796	KU	4	40 XXX	SP	CCA	ED	T	2/13/2111
2020 PO3681787719	KU	4	40 XXX	SP	CCA	ED	T	2/14/2111
2020 PO3682187670	KU	4	40 XXX	SP	CCA	ED	T	2/15/2111
2020 PO3690487488	KU	4	40 XXX	SP	CCA		V	2/16/2111
2020 PO7335338432	KU	4	40 OTH	SP	CRE		V	2/17/2111
2020 PO7311738388	KU	4	40 OTH	SP	CRE	ID	TD	2/18/2111
2020 PO5699905861	KU	4	45 XXX	SP	CCA		V	2/19/2111
2020 PO5710206016	KU	4	45 XXX	SP	CCA		V	2/20/2111

2020 PO5725706071	KU	4	45 XXX	SP	CCA		V	2/21/2111
2020 PO5721606180	KU	4	40 XXX	SP	CCA		V	2/22/2111
2020 PO5701906322	KU	4	40 XXX	SP	CRE	ED,ID,IP	TD	2/23/2111
2020 PO5713606370	KU	3	50 XXX	SP	CCA	ED	T	2/24/2111
2020 PO4657288328	LGE	4	40 BRN	SP	A	ED,ID	TD	2/25/2111
2020 PO7307538208	KU	4	40 OTH	SP	CCA	ED,SRS	TD	2/26/2111
2020 PO7304338031	KU	4	40 OTH	SP	CCA		V	2/27/2111
2020 PO4656288322	LGE	4	40 BRN	SP	A	ED,ID	TD	2/28/2111
2020 5638006435a	KU	4	45 XXX	SP	CCA		V	3/1/2111
2020 PO5643506268	KU	4	45 XXX	SP	CCA		V	3/2/2111
2020 PO5638006435	KU	4	45 XXX	SP	CCA		V	3/3/2111
2020 PO3792288253	KU	5	35 XXX	SP	CCA	ED	T	3/4/2111
2020 PO3831588523	KU	5	35 XXX	SP	CCA		V	3/5/2111
2020 PO3865588498	KU	5	35 XXX	SP	CRE	ED,ID	TD	3/6/2111
2020 PO3738990467	F	5	35 XXX	SP	CRE		V	3/7/2111
2020 PO5584806185	KU	3	45 XXX	SP	CCA		V	3/8/2111
2020 PO5580806399	KU	3	45 XXX	SP	CCA		V	3/9/2111
2020 PO5585006587	KU	3	45 XXX	SP	CCA		V	3/10/2111
2020 PO5609106587	KU	3	45 XXX	SP	CCA		V	3/11/2111
2020 PO7301037519	KU	6	30 OTH	SP	CCA		V	3/12/2111
2020 PO7294237673	KU	4	40 OTH	SP	CCA	ED,SRS	TD	3/13/2111
2020 PO7281937460	KU	6	35 OTH	SP	CCA	ED,SRS	TD	3/14/2111
2020 PO7277137166	KU	4	40 OTH	SP	CCA		V	3/15/2111
2020 PO7298337377	KU	6	30 OTH	SP	CCA	ED,SRS	TD	3/16/2111
2020 PO7291437478	KU	4	40 OTH	SP	CCA	ED,SRS	TD	3/17/2111
2020 PO7288537227	KU	4	40 OTH	SP	CCA		V	3/18/2111
2020 PO4655688312	LGE	4	40 BRN	SP	A	ED,ID	TD	3/19/2111
2020 PO5633106587	KU	4	45 XXX	SP	CCA		V	3/20/2111
2020 PO5655706617	KU	2	45 XXX	SP	CCA		V	3/21/2111
2020 PO5681406585	KU	4	45 XXX	SP	CCA		V	3/22/2111
2020 PO5705106571	KU	2	45 XXX	SP	CCA		V	3/23/2111
2020 PO5709006602	KU	3	55 XXX	SP	CRE		V	3/24/2111
2020 PO4655288315	LGE	4	40 BRN	SP	A	ED,ID	TD	3/25/2111
2020 PO5679707190	KU	5	35 XXX	SP	A	ED,ID	TD	3/26/2111
2020 PO5675107088	KU	5	35 XXX	SP	CCA		V	3/27/2111
2020 PO5653407049	KU	5	40 XXX	SP	CRE	ED,ID	TD	3/28/2111
2020 PO5673506955	KU	5	40 XXX	SP	CRE	ED,ID	TD	3/29/2111
2020 PO3725290312	F	3	45 XXX	SP	CCA		V	3/30/2111
2020 PO3712590292	F	4	40 XXX	SP	CRE		V	3/31/2111
2020 PO3716090250	F	4	40 XXX	SP	CRE		V	4/1/2111
2020 PO3701690224	KU	5	35 XXX	SP	CCA		V	4/2/2111
2020 PO3703290169	F	4	40 XXX	SP	CRE		V	4/3/2111
2020 PO3684490107	F	4	40 XXX	SP	CRE		V	4/4/2111
2020 PO3688190071	F	4	40 XXX	SP	CRE		V	4/5/2111
2020 PO4652588296	LGE	4	40 BRN	SP	A	ED,ID	TD	4/6/2111
2020 PO4651588288	LGE	4	40 BRN	SP	P	ED,ID,IP	TD	4/7/2111
2020 PO5705307532	KU	5	45 XXX	SP	CRE	ED,ID	TD	4/8/2111

2020 PO5702307838	KU	4	45 XXX	SP	CRE	ED,ID	TD	4/9/2111
2020 PO4650488281	LGE	4	40 BRN	SP	A	ED,ID,IP	TD	4/10/2111
2020 PO7410338421	KU	4	40 OTH	SP	CRE	ED	TD	4/11/2111
2020 PO7430938413	KU	4	45 OTH	SP	CRE	HH,ID	TD	4/12/2111
2020 PO5670508295	KU	3	45 XXX	SP	CRE	ID	BD	4/13/2111
2020 PO5671508440	KU	4	45 XXX	SP	CRE	ED,ID	TD	4/14/2111
2020 PO7449138405	KU	4	40 OTH	SP	CRE	ID	TD	4/15/2111
2020 PO4670888749	F	4	30 BRO	SP	CCA		V	4/16/2111
2020 PO5699308039	KU	4	40 XXX	SP	CCA		V	4/17/2111
2020 PO5696408284	KU	4	45 XXX	SP	CCA		V	4/18/2111
2020 PO5694008465	KU	4	45 XXX	SP	CCA		V	4/19/2111
2020 PO5692908563	KU	4	45 XXX	SP	CCA		V	4/20/2111
2020 PO5691008720	KU	4	45 XXX	SP	CRE	ED,ID	TD	4/21/2111
2020 PO4671988754	F	2	60 BRO	SP	A		V	4/22/2111
2020 PO3816100417	F	4	40 BRO	SP	A		V	4/23/2111
2020 PO7466938397	KU	4	40 OTH	SP	CRE	ID	TD	4/24/2111
2020 PO4649988278	LGE	4	30 BRN	SP	P		T	4/25/2111
2020 PO4674888779	LGE	3	50 BRO	SP	CCA		V	4/26/2111
2020 PO4675988787	LGE	3	45 BRO	SP	CCA		V	4/27/2111
2020 PO4719088073	LGE	4	30 BRO	SP	CRE	ED,ID	TD	4/28/2111
2020 PO4716088170	LGE	3	45 BRO	SP	CCA		V	4/29/2111
2020 PO4729688120	LGE	4	30 BRO	SP	CRE	ED,ID	TD	4/30/2111
2020 PO4730188140	LGE	4	40 BRO	SP	CCA		V	5/1/2111
2020 PO4730388131	LGE	4	40 BRO	SP	CRE		V	5/2/2111
2020 PO4711388014	LGE	4	40 BRO	SP	CRE	ED,ID	BD	5/3/2111
2020 PO4710588040	LGE	3	45 BRO	SP	CCA		V	5/4/2111
2020 PO4710688048	LGE	3	45 BRO	SP	CCA		V	5/5/2111
2020 PO4709788051	LGE	4	40 BRO	SP	A	ED,ID	TD	5/6/2111
2020 PO4709588067	LGE	4	40 BRO	SP	A	ED,ID	TD	5/7/2111
2020 PO4708588067	LGE	4	40 BRO	SP	P	ED,ID	BD	5/8/2111
2020 PO4709488097	LGE	4	40 BRO	SP	CRE	RB	BX	PX 5/9/2111
2020 PO4707588090	LGE	4	40 BRO	SP	P	ED,ID	BD	5/10/2111
2020 PO4705688081	LGE	4	40 BRO	SP	CRE	ED,ID	BD	5/11/2111
2020 PO4703188065	LGE	4	40 BRO	SP	A	ED,ID	TD	5/12/2111
2020 PO4704088071	LGE	4	40 BRO	SP	CCA		V	5/13/2111
2020 PO4602887942	F	4	35 BRO	SP	CRE		V	5/14/2111
2020 PO4611587801	F	3	45 BRO	SP	CCA		V	5/15/2111
2020 PO4610887813	F	4	40 BRO	SP	CCA		V	5/16/2111
2020 PO4609987826	F	4	40 BRO	SP	P		V	5/17/2111
2020 PO4609187839	F	4	40 BRO	SP	CRE		V	5/18/2111
2020 PO4607587865	F	4	40 BRO	SP	CCA		V	5/19/2111
2020 PO4608387853	F	4	40 BRO	SP	CRE		V	5/20/2111
2020 PO4606887878	F	4	40 BRO	SP	CRE		V	5/21/2111
2020 PO4605987891	F	4	40 BRO	SP	A		V	5/22/2111
2020 PO4603487932	F	4	35 BRO	SP	CRE		V	5/23/2111
2020 PO4604087922	F	4	40 BRO	SP	CCA		V	5/24/2111
2020 PO4602387950	F	4	40 BRO	SP	CRE		V	5/25/2111

2020 PO4601387966	F	4	40 BRO	SP	CRE		V			5/26/2111
2020 PO4601887958	F	3	45 BRO	SP	A		V			5/27/2111
2020 PO4600387983	F	4	40 BRO	SP	CRE		V			5/28/2111
2020 PO4600887975	F	4	35 BRO	SP	CRE		V			5/29/2111
2020 PO4604487915	F	4	40 BRO	SP	CRE		V			5/30/2111
2020 PO3773088020	KU	3	45 XXX	SP	CRE		V			5/31/2111
2020 PO3841387554	KU	4	45 XXX	SP	CCA		V			6/1/2111
2020 PO3830187687	KU	4	45 XXX	SP	CCA		V			6/2/2111
2020 PO3798587548	KU	4	40 XXX	SP	CCA		V			6/3/2111
2020 PO3798587548A	KU	5	35 XXX	SP	CCA		V			6/4/2111
2020 PO2409545897	KU	4	45 BRN	SP	CRE	ED,ID,RB	BX	RP1		6/5/2111
2020 PO4699788435	LGE	4	35 BRN	SP	A		V			6/6/2111
2020 PO4696288414	LGE	4	40 BRN	SP	CCA		V			6/7/2111
2020 PO4683088275	LGE	4	35 BRN	SP	CCA		V			6/8/2111
2020 PO4683388281	LGE	3	45 BRN	SP	P	ED,ID	BD			6/9/2111
2020 PO4683588288	LGE	3	45 BRN	SP	A	ED,ID	BD			6/10/2111
2020 PO4681988309	LGE	6	25 BRN	SP	A		V			6/11/2111
2020 PO4682288308	LGE	6	25 BRN	SP	CRE	ED,ID	BD			6/12/2111
2020 PO4682388304	F	4	40 BRN	SP	CRE		V			6/13/2111
2020 PO4683588313	F	4	40 BRN	SP	A		V			6/14/2111
2020 PO4685188310	LGE	4	35 BRN	SP	CRE	ED,ID	BD			6/15/2111
2020 PO4684988324	F	4	40 BRN	SP	CCA		V			6/16/2111
2020 PO468618834	F	5	40 BRN	SP	CCA		V			6/17/2111
2020 PO4685288342	LGE	4	30 BRN	SP	CCA		V			6/18/2111
2020 PO4686188334	F	4	35 BRN	SP	CCA		V			6/19/2111
2020 PO4687388344	F	4	40 BRN	SP	A		V			6/20/2111
2020 PO4725188129	LGE	4	35 BRO	SP	CRE	ED,ID	TD			6/21/2111
2020 PO4728088346	LGE	4	40 BRO	SP	P	ED,ID	BD			6/22/2111
2020 PO4728488340	LGE	4	35 BRO	SP	P	ED,ID	BD			6/23/2111
2020 PO4729288329	LGE	4	35 BRO	SP	CRE	ED,ID	TD			6/24/2111
2020 PO6882015024	KU	4	40 XXX	SP	CRE	ED,ID	TD			6/25/2111
2020 PO6892014812	KU	5	35 XXX	SP	CRE	ED,ID	TD			6/26/2111
2020 PO4667488464	F	4	40 BRN	SP	CRE		V			6/27/2111
2020 PO4668188455	F	4	40 BRN	SP	CRE		V			6/28/2111
2020 PO4668788446	F	4	40 BRN	SP	CRE		V			6/29/2111
2020 PO4669488436	F	4	40 BRN	SP	CRE		V			6/30/2111
2020 PO4643388856	LGE	3	45 BRO	SP	CCA		V			7/1/2111
2020 PO4670188426	F	4	35 BRN	SP	A		V			7/2/2111
2020 PO4670788418	F	3	45 BRN	SP	A		V			7/3/2111
2020 PO4296988162	LGE	4	30 ACW	SP	P	ID	BD			7/4/2111
2020 PO4296988186	LGE	4	40 ACW	SP	CCA		V			7/5/2111
2020 PO4286088156	F	4	35 ACW	SP	CCA		V			7/6/2111
2020 PO4283088175	LGE	4	30 ACW	SP	CRE	ED,ID	BD			7/7/2111
2020 PO4283188183	F	1	60 ACW	SP	CRE		V			7/8/2111
2020 PO4283588183	F	1	60 ACW	SP	S		V			7/9/2111
2020 PO4286088176	F	3	45 ACW	SP	S		V			7/10/2111
2020 PO4284888185	LGE	4	30 ACW	SP	S		V			7/11/2111

2020 PO4285188179	LGE	3	55 ACW	SP	S		V	7/12/2111
2020 PO4284488181	LGE	1	60 ACW	SP	S		V	7/13/2111
2020 PO4284188181	LGE	4	40 ACW	SP	CCA		V	7/14/2111
2020 PO4282488184	LGE	2	50 ACW	SP	CRE	ED,ID	BD	7/15/2111
2020 PO4282388184	F	3	50 ACW	SP	CRE		V	7/16/2111
2020 PO4282188185	F	2	50 ACW	SP	CRE		V	7/17/2111
2020 PO4281488186	F	2	50 ACW	SP	CRE		V	7/18/2111
2020 PO4280388188	F	2	50 ACW	SP	CRE		V	7/19/2111
2020 PO4282088236	LGE	2	50 ACW	SP	CCA		VX	7/20/2111
2020 PO4283188234	LGE	1	50 ACW	SP	CCA		V	7/21/2111
2020 PO4289288222	LGE	3	45 ACW	SP	P	ED,ID	BD	7/22/2111
2020 PO4286088230	LGE	4	40 ACW	SP	CRE	ED,ID,MD	BD	7/23/2111
2020 PO4287088236	LGE	1	70 ACW	SP	CCA		V	7/24/2111
2020 PO4288588226	LGE	4	40 ACW	SP	S		V	7/25/2111
2020 PO4289388203	LGE	2	50 ACW	SP	P	ED,ID	BD	7/26/2111
2020 PO4287488206	LGE	2	45 ACW	SP	CRE	ED,ID	BD	7/27/2111
2020 PO4288588184	LGE	4	40 ACW	UN	CCA		V	7/28/2111
2020 PO4286388179	LGE	2	60 ACW	SP	P	ED,ID	BD	7/29/2111
2020 PO9979693973	LGE	2	55 ACW	SP	P	ID	BD	7/30/2111
2020 PO4286588194	LGE	2	55 ACW	SP	P	ID	BD	7/31/2111
2020 PO4286588197	LGE	2	55 ACW	SP	P	ID	BD	8/1/2111
2020 PO4286488200	LGE	2	45 ACW	SP	P	ID	BD	8/2/2111
2020 PO4649089007	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	8/3/2111
2020 PO4663289203	LGE	4	40 BRO	SP	A	ID,IP	BD	8/4/2111
2020 PO4660389181	LGE	4	40 BRO	SP	A	ED	T	8/5/2111
2020 PO4659389172	LGE	4	35 BRO	SP	CRE	ID,IP	BD	8/6/2111
2020 PO4645389174	LGE	3	45 BRO	SP	CCA	ED	T	8/7/2111
2020 PO4709088915	LGE	5	35 BRO	SP	A	ED	T	8/8/2111
2020 PO4708388902	LGE	5	35 BRO	SP	A	ED,ID,IP	TD	8/9/2111
2020 PO4709088889	LGE	5	35 BRO	SP	A	ED,ID,IP	TD	8/10/2111
2020 PO4712388873	LGE	5	35 BRO	SP	A	ED	T	8/11/2111
2020 PO4711088865	LGE	5	35 BRO	SP	A	ED	T	8/12/2111
2020 PO4709888876	LGE	5	35 BRO	SP	A	ED	T	8/13/2111
2020 PO4709188938	LGE	5	35 BRO	SP	A	ED,ID	TD	8/14/2111
2020 PO4711588952	LGE	5	35 BRO	SP	A	ED	T	8/15/2111
2020 PO4710488945	LGE	5	35 BRO	SP	A	ED	T	8/16/2111
2020 PO4714688932	F	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/17/2111
2020 PO4713688948	F	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/18/2111
2020 PO4712588966	F	3	45 BRO	SP	CRE	ED,ID,IP	TD	8/19/2111
2020 PO4714988906	F	3	45 BRO	SP	CCA		V	8/20/2111
2020 PO4646988926	LGE	4	40 BRO	SP	CRE		T	8/21/2111
2020 PO4646488932	LGE	4	40 BRO	SP	CCA		TD	8/22/2111
2020 PO4646588927	LGE	4	40 BRO	SP	CRE	ID,IP	TD	8/23/2111
2020 PO4637988908	LGE	4	40 OTH	SP	CRE	ID	BD	8/24/2111
2020 PO9436583319	F	4	40 BRO	SP	CRE		V	8/25/2111
2020 PO9460483413	F	4	40 BRO	SP	A		V	8/26/2111
2020 PO9474383469	F	4	40 BRO	SP	A		V	8/27/2111

2020 PO8383977478	KU	4	40 BRO	SP	CCA		V	8/28/2111
2020 PO8384577569	KU	4	40 BRO	SP	CCA		V	8/29/2111
2020 PO8463179134	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/30/2111
2020 PO8513379224	KU	5	35 BRO	SP	CCA	ED	T	8/31/2111
2020 PO8521379224	F	4	40 BRO	SP	CRE		V	9/1/2111
2020 PO8520879115	F	3	45 BRO	SP	CRE		V	9/2/2111
2020 PO8519578804	F	4	40 BRO	SP	CRE		V	9/3/2111
2020 PO8520178962	F	3	45 BRO	SP	CCA		V	9/4/2111
2020 PO8439677939	F	5	35 BRO	SP	CRE		V	9/5/2111
2020 PO8437477888	F	6	30 BRO	SP	CRE		V	9/6/2111
2020 PO8392677661	KU	6	30 BRO	AL	CCA		V	9/7/2111
2020 PO3892705994	KU	5	30 BRN	SP	CRE	ED,ID	TD	9/8/2111
2020 PO3910606124	F	5	35 XXX	SP	P		V	9/9/2111
2020 PO3917306027	KU	4	40 XXX	SP	CCA		V	9/10/2111
2020 PO3926206082	KU	5	35 XXX	SP	CCA		V	9/11/2111
2020 PO3904605620	KU	3	45 XXX	SP	CCA		V	9/12/2111
2020 PO3266605603	KU	4	40 BRO	SP	CCA		V	9/13/2111
2020 PO3248205682	KU	5	30 BRO	SP	CRE		V	9/14/2111
2020 PO3255305392	KU	5	30 BRO	SP	CRE		V	9/15/2111
2020 PO3250505531	KU	5	30 BRO	SP	CRE	ID	TD	9/16/2111
2020 PO3262605199	KU	6	30 BRO	SP	CCA		V	9/17/2111
2020 PO3253205151	KU	4	40 BRO	SP	CCA		V	9/18/2111
2020 PO3255804888	KU	4	40 BRO	SP	CRE	ID	TD	9/19/2111
2020 PO3259704745	KU	4	40 BRO	SP	CCA		V	9/20/2111
2020 PO3266504757	KU	4	30 BRO	SP	A	ID	TD	9/21/2111
2020 PO2887303794	KU	4	45 BRO	SP	CCA		V	9/22/2111
2020 PO0851215475	KU	4	40 ACE	SP	CCA		V	9/23/2111
2020 PO0832115915	F	7	20 ACE	SP	CRE		V	9/24/2111
2020 PO8630181810	KU	6	30 BRO	SP	CRE	ED,ID	TD	9/25/2111
2020 PO8608481909	KU	6	30 BRO	SP	CCA	ED,ID	TD	9/26/2111
2020 PO8592981958	KU	6	30 BRO	SP	CRE	ED,ID,IP,SRC	TD	9/27/2111
2020 PO8589181743	F	4	40 BRO	SP	CRE		V	9/28/2111
2020 PO8572581863	F	4	40 BRO	SP	CRE		V	9/29/2111
2020 PO8687981868	F	4	40 BRO	SP	CRE		V	9/30/2111
2020 PO8472880943	KU	4	40 BRO	SP	CRE	ED	TD	10/1/2111
2020 PO8474180985	KU	6	30 BRO	SP	CRE	ED	TD	10/2/2111
2020 PO8449081015	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	10/3/2111
2020 PO8433480990	KU	6	30 BRO	SP	CCA	ED	T	10/4/2111
2020 PO8450280970	F	4	40 BRO	SP	A		V	10/5/2111
2020 PO8453980819	F	4	40 BRO	SP	CCA		V	10/6/2111
2020 PO8477880898	KU	6	30 BRO	SP	CRE	ED,EP,ID	TD	10/7/2111
2020 PO8474980794	KU	5	35 BRO	SP	CRE	ID,IP	BD	10/8/2111
2020 PO8479380694	KU	4	40 BRO	SP	CCA		V	10/9/2111
2020 PO8465080916	KU	6	30 BRO	SP	CCA		V	10/10/2111
2020 PO8485480562	F	5	35 BRO	SP	CRE		V	10/11/2111
2020 PO8490980440	F	4	40 BRO	SP	CRE		V	10/12/2111
2020 PO8488880735	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	10/13/2111

2020 PO8523779844	F	3	50 BRO	SP	A		V	10/14/2111
2020 PO8523279710	F	3	45 BRO	SP	CRE		V	10/15/2111
2020 PO8522679557	F	4	40 BRO	SP	CRE		V	10/16/2111
2020 PO8519179802	F	3	45 BRO	SP	A		V	10/17/2111
2020 PO8517279848	F	5	35 BRO	SP	CRE		V	10/18/2111
2020 PO8397780883	KU	4	40 BRO	SP	CCA		V	10/19/2111
2020 PO8406480890	F	4	40 BRO	SP	A		V	10/20/2111
2020 PO8422580867	F	4	40 BRO	SP	A		V	10/21/2111
2020 PO8431680853	F	4	40 BRO	SP	A		V	10/22/2111
2020 PO8688081809	F	4	40 BRO	SP	CRE		V	10/23/2111
2020 PO8688081668	F	4	40 BRO	SP	CRE		V	10/24/2111
2020 PO8706981686	F	4	40 BRO	SP	CRE		V	10/25/2111
2020 PO8721781612	F	4	40 BRO	SP	CRE		V	10/26/2111
2020 PO8737081557	F	4	40 BRO	SP	CRE		V	10/27/2111
2020 PO8752281500	F	4	40 BRO	SP	CRE		V	10/28/2111
2020 PO8775681662	F	4	40 BRO	SP	CCA		V	10/29/2111
2020 PO8768681481	F	4	40 BRO	SP	CCA		V	10/30/2111
2020 PO8767281445	F	4	40 BRO	SP	CRE		V	10/31/2111
2020 PO8782281388	F	4	40 BRO	SP	CRE		V	11/1/2111
2020 PO8712882052	KU	4	40 BRO	SP	CCA		V	11/2/2111
2020 PO8752481908	F	4	40 BRO	SP	CCA		V	11/3/2111
2020 PO8717582034	F	4	40 BRO	SP	CCA		V	11/4/2111
2020 PO8724082012	F	4	40 BRO	SP	CCA		V	11/5/2111
2020 PO8738281960	F	4	40 BRO	SP	CCA		V	11/6/2111
2020 PO8766681856	F	4	40 BRO	SP	CCA		V	11/7/2111
2020 PO8780681802	F	4	45 BRO	SP	CCA		V	11/8/2111
2020 PO8794881751	F	4	40 BRO	SP	CCA		V	11/9/2111
2020 PO8626683246	KU	5	35 BRO	SP	CRE	ED,ID,SRC	TD	11/10/2111
2020 PO8632083197	F	4	40 BRO	SP	CCA		V	11/11/2111
2020 PO8634083334	F	4	40 BRO	SP	CCA		V	11/12/2111
2020 PO3843104646	KU	6	30 BRO	DF	CCA		V	11/13/2111
2020 PO6954079863	KU	5	35 BRN	SP	CRE	ED,ID	TD	11/14/2111
2020 PO6948779726	KU	4	40 BRN	SP	CRE	ED,ID	TD	11/15/2111
2020 PO6996284791	KU	4	40 BRO	SP	CCA		V	11/16/2111
2020 PO7002284894	KU	4	40 BRO	SP	A	ED,ID	TD	11/17/2111
2020 PO7576276840	KU	4	45 BRO	SP	CCA		V	11/18/2111
2020 PO7010385017	KU	5	35 BRO	SP	A	ED,ID	TD	11/19/2111
2020 PO7013284995	KU	4	40 BRO	SP	A	ED,ID	TD	11/20/2111
2020 PO7034484947	KU	4	45 BRO	SP	CRE	ED,ID	BD	11/21/2111
2020 PO7024185065	KU	4	40 BRO	SP	A	ED,ID	TD	11/22/2111
2020 PO6957479775	KU	6	30 BRN	SP	CRE	ED,ID	TD	11/23/2111
2020 PO6959879544	KU	4	40 BRN	SP	CCA		V	11/24/2111
2020 PO6941379569	KU	4	40 BRN	SP	CRE	ED,ID	TD	11/25/2111
2020 PO6933079384	KU	4	40 BRN	SP	CRE	ED,ID	BD	11/26/2111
2020 PO7024184262	KU	6	30 BRO	SP	CRE	ED,ID	BD	11/27/2111
2020 PO7034184281	KU	3	45 BRO	SP	CRE	ED,ID	BD	11/28/2111
2020 PO7041484250	KU	4	45 BRO	SP	CRE	ED,ID	BD	11/29/2111

2020 PO7044484473	KU	6	30 BRO	SP	CRE	ED,ID	TD	11/30/2111
2020 PO7579976824	KU	6	30 BRO	SP	CRE	ED,ID	BD	12/1/2111
2020 PO7580176776	KU	6	30 BRO	SP	CRE	ED,ID	BD	12/2/2111
2020 PO7580576728	KU	6	30 BRO	SP	CRE	ED,ID	BD	12/3/2111
2020 PO7580676675	KU	5	35 BRO	SP	CRE	ED,ID	BD	12/4/2111
2020 PO7050684447	KU	3	45 BRO	SP	CRE	ED,ID	TD	12/5/2111
2020 PO7058384601	KU	4	40 BRO	SP	A	ED,ID	TD	12/6/2111
2020 PO7066084763	KU	3	45 BRO	SP	A	ED,ID	TD	12/7/2111
2020 PO7579576872	KU	6	30 BRO	SP	CRE	ED,ID	BD	12/8/2111
2020 PO7579376921	KU	6	30 BRO	SP	CRE	ED,ID	BD	12/9/2111
2020 PO7005079193	KU	4	40 BRN	SP	CRE	ED,ID,IP	BD	12/10/2111
2020 PO7016879379	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	12/11/2111
2020 PO7039079298	KU	4	40 BRN	SP	CCA		V	12/12/2111
2020 PO7579176970	KU	6	30 BRO	SP	CRE	ED,ID	BD	12/13/2111
2020 PO7578777025	KU	5	35 BRO	SP	CRE	ED,ID	BD	12/14/2111
2020 PO7572577102	KU	4	45 BRO	SP	CCA		V	12/15/2111
2020 PO7069984849	KU	3	40 BRO	SP	A	ED,ID,IP,RR,SRC	TX	12/16/2111
2020 PO6998579440	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	12/17/2111
2020 PO7075684971	KU	4	45 BRO	SP	CCA		V	12/18/2111
2020 PO7071384990	KU	4	30 BRO	SP	CRE	ED,ID	TD	12/19/2111
2020 PO7065685043	KU	3	40 BRO	SP	CRE	ED,ID	TD	12/20/2111
2020 PO7057385184	KU	4	40 BRO	SP	CRE	ED,ID,SRC	TD	12/21/2111
2020 PO7041885228	KU	4	40 BRO	SP	CRE	ED,ID	TD	12/22/2111
2020 PO7035285236	KU	3	40 BRO	SP	CRE	ED,ID	TD	12/23/2111
2020 PO6968579538	KU	4	40 BRN	SP	CCA		V	12/24/2111
2020 PO7559677482	KU	4	40 BRO	SP	CRE	ED,ID	TD	12/25/2111
2020 PO7026085239	KU	4	40 BRO	SP	CRE	ED,ID	TD	12/26/2111
2020 PO6973379798	KU	4	40 BRN	SP	CRE	ED,HH,ID	BX	12/27/2111
2020 PO7025485301	KU	4	35 BRO	SP	A	ED,ID	TD	12/28/2111
2020 PO7002485324	KU	6	30 BRO	SP	CRE	ED,ID	BD	12/29/2111
2020 PO7572377452	KU	4	40 BRO	SP	P	ED,ID	BD	12/30/2111
2020 PO3455104241	KU	4	40 BRO	SP	CCA	ID	TD	12/31/2111
2020 PO3464904661	KU	4	40 BRN	SP	CCA		V	1/1/2112
2020 PO3492604304	KU	3	45 BRN	SP	CCA		V	1/2/2112
2020 PO3475304364	KU	4	40 BRN	SP	CCA		V	1/3/2112
2020 PO3480204266	KU	4	40 BRN	SP	CCA		V	1/4/2112
2020 PO3472804207	KU	3	45 BRN	SP	CCA		V	1/5/2112
2020 PO3453304111	KU	3	45 BRN	SP	CCA		V	1/6/2112
2020 PO3434604023	KU	3	50 BRN	SP	CCA		V	1/7/2112
2020 PO3435403965	KU	4	45 OTH	SP	CCA		V	1/8/2112
2020 PO3426303955	KU	5	35 OTH	SP	CCA		V	1/9/2112
2020 PO3408203795	KU	5	35 BRN	SP	CCA		V	1/10/2112
2020 PO3417303942	KU	4	45 BRN	SP	CCA		V	1/11/2112
2020 PO3421303958	KU	3	50 BRN	SP	CCA		V	1/12/2112
2020 PO3419504192	KU	6	30 KOP	SP	CCA		V	1/13/2112
2020 PO3428404066	KU	4	40 BRN	SP	CCA		V	1/14/2112
2020 PO3403303869	KU	3	45 BRN	SP	CCA		V	1/15/2112

2020 PO3389103822	KU	3	50 BRN	SP	CCA		V	1/16/2112
2020 PO3354403733	KU	3	50 BRN	SP	CCA		V	1/17/2112
2020 PO3336803692	KU	2	50 BRN	SP	CCA		V	1/18/2112
2020 PO3322603660	KU	3	45 BRN	SP	CCA		V	1/19/2112
2020 PO3304603627	KU	3	45 BRN	SP	CCA		V	1/20/2112
2020 PO3282603566	KU	3	45 BRN	SP	CCA		V	1/21/2112
2020 PO3261903527	KU	3	45 BRN	SP	CCA		V	1/22/2112
2020 PO3233503464	KU	2	50 BRN	SP	CCA		V	1/23/2112
2020 PO3200603195	KU	6	30 BRN	SP	CCA		V	1/24/2112
2020 PO3197903445	KU	4	45 OTH	SP	CCA		V	1/25/2112
2020 PO3217103425A	KU	5	35 BRN	SP	CCA		V	1/26/2112
2020 PO3214903551	KU	5	35 OTH	SP	CCA		V	1/27/2112
2020 PO3217103425	KU	2	50 BRN	SP	CCA		V	1/28/2112
2020 PO3215903478	KU	3	45 BRN	SP	CCA		V	1/29/2112
2020 PO3205403574	KU	4	45 OTH	SP	CCA		V	1/30/2112
2020 PO3188203370	KU	2	50 BRN	SP	CCA		V	1/31/2112
2020 PO7414380811	KU	2	60 BRN	SP	CCA		V	2/1/2112
2020 PO7433380946	KU	3	45 BRN	SP	CCA		V	2/2/2112
2020 PO7435080934	KU	3	45 BRN	SP	CCA		V	2/3/2112
2020 PO7418081048	KU	3	45 BRN	SP	CCA		V	2/4/2112
2020 3853205008A	KU	6	30 BRO	SP	CCA		V	2/5/2112
2020 PO3845805079	KU	6	30 XXX	SP	CRE	ED,ID	TD	2/6/2112
2020 PO3445904218	KU	6	30 BRO	SP	CRE		TD	2/7/2112
2020 PO3444604103	KU	4	40 BRO	SP	CCA		V	2/8/2112
2020 PO3429204320	KU	6	30 BRO	SP	CCA		V	2/9/2112
2020 PO3435004376	KU	6	35 BRO	SP	CRE	ID	TD	2/10/2112
2020 PO3427204381	KU	6	30 BRO	SP	CCA	ED	T	2/11/2112
2020 PO3436004580	KU	4	40 BRO	SP	CRE		V	2/12/2112
2020 PO3243704873	KU	4	40 BRO	SP	CCA		V	2/13/2112
2020 PO3235204864	KU	3	35 BRO	SP	CRE	ID	BD	2/14/2112
2020 PO3241004650	KU	5	35 BRO	SP	CRE	ID	TD	2/15/2112
2020 PO3916505811	KU	5	40 XXX	SP	CRE	ED,ID	TD	2/16/2112
2020 PO3948506071	KU	5	35 XXX	SP	CRE	ED,ID	TD	2/17/2112
2020 PO7390981343	KU	3	45 BRN	SP	P	ED,ID	T	2/18/2112
2020 PO7424781299	KU	3	45 BRN	SP	CCA		V	2/19/2112
2020 PO7399481328	KU	3	45 BRN	SP	CCA		V	2/20/2112
2020 PO3926805923	KU	4	40 XXX	SP	CRE	ED,ID	TD	2/21/2112
2020 PO3936505984	KU	5	35 BRN	SP	CRE	ED,ID	TD	2/22/2112
2020 PO3933505799	KU	5	35 BRN	SP	CCA		V	2/23/2112
2020 PO3933005738	KU	4	45 BRN	SP	CCA		V	2/24/2112
2020 PO7393581380	KU	5	35 BRN	SP	CCA		V	2/25/2112
2020 PO7395981173	KU	3	45 BRN	SP	CCA		V	2/26/2112
2020 PO3243504546	KU	4	40 BRO	SP	CRE	ID	TD	2/27/2112
2020 PO3252404642	KU	6	30 BRO	SP	CCA		V	2/28/2112
2020 PO3297204994	KU	6	30 BRO	SP	CRE	ID	TD	2/29/2112
2020 PO3303004930	KU	5	35 BRO	SP	CRE	ID	TD	3/1/2112
2020 PO3872206034	KU	6	30 BRN	SP	CRE	ED,ID	TD	3/2/2112

2020 PO3876405863	KU	6	30 BRN	SP	CRE	ED,ID	TD	3/3/2112
2020 PO3856105789	KU	6	35 BRN	SP	CRE		V	3/4/2112
2020 PO3892605530	KU	4	40 XXX	SP	CRE	ED,ID	TD	3/5/2112
2020 PO3278304484	KU	4	40 BRO	SP	CRE	ID	TD	3/6/2112
2020 PO2638664346	F	2	65 BRO	SP	CRE		V	3/7/2112
2020 PO3863405737	KU	4	40 XXX	SP	CRE	ED,ID	TD	3/8/2112
2020 PO3858305583	KU	4	40 XXX	SP	CRE	ED,ID	TD	3/9/2112
2020 PO3846505537	KU	6	30 XXX	SP	CRE	ED,ID	TD	3/10/2112
2020 PO3833305457	KU	6	30 XXX	SP	CRE	ED,ID	TD	3/11/2112
2020 PO3870205323	KU	6	30 XXX	SP	CRE		V	3/12/2112
2020 PO4866486750	LGE	4	40 OTH	SP	P	ED,SRS	TD	3/13/2112
2020 PO4899687183	LGE	4E	40E OTH	SP	CRE	ED,ID,IP	BD	3/14/2112
2020 PO4807487698	LGE	4	35 BRN	SP	CRE		V	3/15/2112
2020 PO4807987697	LGE	3	45 BRN	SP	CRE		V	3/16/2112
2020 PO4807887665	LGE	4	30 BRN	SP	CRE	ED,ID,IP	BD	3/17/2112
2020 PO4893887158	LGE	3	50 OTH	SP	P	ED,ID,SRS	TD	3/18/2112
2020 PO4895687170	LGE	3	50 OTH	SP	P	ID	BD	3/19/2112
2020 PO4740488160	F	4	40 BRO	SP	CCA		V	3/20/2112
2020 PO4739588154	F	4	40 BRO	SP	CRE		V	3/21/2112
2020 PO4741888166	F	4	40 BRO	SP	CCA		V	3/22/2112
2020 PO4742188162	LGE	UNK	25 BRO	SP	CRE	ED	BD	3/23/2112
2020 PO4833986409	LGE	3	45 XXX	SP	P	ID	TD	3/24/2112
2020 PO4879087639	F	5	35 XXX	SP	CRE		V	3/25/2112
2020 PO4879987615	F	4	35 XXX	SP	A		V	3/26/2112
2020 PO4880687597	F	4	35 XXX	SP	A		V	3/27/2112
2020 PO4880887585	F	4	35 XXX	SP	A		V	3/28/2112
2020 PO4881187577	F	5	40 XXX	SP	CCA		V	3/29/2112
2020 PO4881787563	F	4	35 XXX	SP	A		V	3/30/2112
2020 4882687522a	LGE	4	30 XXX	SP	A	ED,ID	TD	3/31/2112
2020 PO4786787939	LGE	4	40 BRO	SP	CRE	ED	TD	4/1/2112
2020 PO4786487905	LGE	4	40 BRO	SP	CRE	ED	TD	4/2/2112
2020 PO4676389087	LGE	3	45 BRO	SP	CRE	ED	T	4/3/2112
2020 PO4677389086	LGE	4	40 BRO	SP	CCA		V	4/4/2112
2020 PO4681589135	LGE	3	45 BRO	SP	CCA		V	4/5/2112
2020 PO4785487917	LGE	4	40 BRO	SP	CRE	ED	TD	4/6/2112
2020 PO4785787904	LGE	4	40 BRO	SP	CRE	ED	TD	4/7/2112
2020 PO4787887908	LGE	4	40 BRO	SP	CRE	ED	TD	4/8/2112
2020 PO4809087637	LGE	4	30 BRN	SP	CRE	ED,ID	BD	4/9/2112
2020 PO4809987627	LGE	4	30 BRN	SP	CCA		V	4/10/2112
2020 PO4808787621	LGE	4	30 BRN	SP	CRE	ED,ID	BD	4/11/2112
2020 PO4809287628	LGE	4	40 BRN	SP	CCA		V	4/12/2112
2020 PO4861986718	LGE	4	35 OTH	SP	CRE	ED,EP,HH,ID,IP,MD,RB	X PX	4/13/2112
2020 PO4806787577	LGE	4	35 BRN	SP	CRE	ED,ID	BD	4/14/2112
2020 PO4806587587	LGE	4	40 BRN	SP	CCA		V	4/15/2112
2020 PO4832786452	LGE	4	40 XXX	SP	A	ID	BD	4/16/2112
2020 PO4832786452A	LGE	3	45 XXX	SP	P	ID	TD	4/17/2112
2020 PO4830986453	LGE	4	30 XXX	SP	P	ID	BD	4/18/2112

2020 PO4834386598	LGE	4	35 XXX	SP	CCA		V		4/19/2112
2020 PO4921087235	F	4	35 OTH	SP	P		V		4/20/2112
2020 PO4680989116	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		4/21/2112
2020 PO4680789111	LGE	4	40 BRO	SP	A	ED,ID,IP	TD		4/22/2112
2020 PO4783587855	LGE	3	50 BRO	SP	CRE	ID	BD		4/23/2112
2020 PO4785087854	LGE	UNK	70 BRO	SP	CRE		V		4/24/2112
2020 PO4807587581	LGE	4	30 BRN	SP	CCA		V		4/25/2112
2020 PO4780887858	LGE	4	40 BRO	SP	CCA		V		4/26/2112
2020 PO4781987857	LGE	UNK	75 BRO	SP	CRE		V		4/27/2112
2020 PO4786687852	LGE	UNK	70 BRO	SP	CRE		V		4/28/2112
2020 PO4786987852	LGE	3	50 BRO	SP	CRE	ED	TD		4/29/2112
2020 PO4786887854	LGE	4	40 BRO	SP	P	ED	TD		4/30/2112
2020 PO4789387849	LGE	UNK	70 BRO	SP	CRE		V		5/1/2112
2020 PO4784487865	LGE	4	35 BRO	SP	CCA		V		5/2/2112
2020 PO4808787587	LGE	4	30 BRN	SP	CRE	ED,ID	BD		5/3/2112
2020 PO4810187593	LGE	4	30 BRN	SP	CRE	ED,ID	BD		5/4/2112
2020 PO4882287545	F	5	35 XXX	SP	A		V		5/5/2112
2020 PO4811387599	LGE	4	30 BRN	SP	CRE	ED,ID	BD		5/6/2112
2020 PO4877687674	LGE	4	35 XXX	SP	CCA		V		5/7/2112
2020 PO4874887428	LGE	3	45 XXX	SP	CRE		V		5/8/2112
2020 PO4876687402	LGE	4	40 XXX	SP	A	ID	BD		5/9/2112
2020 PO4937687025	LGE	3	50 OTH	SP	P	ED,ID,SRS	TD		5/10/2112
2020 PO4937687020	LGE	9	50 OTH	WC	A		V		5/11/2112
2020 PO4924286911	LGE	4	30 OTH	SP	CCA		V		5/12/2112
2020 PO4875787431	LGE	4	40 XXX	SP	A	ID	BD		5/13/2112
2020 PO4874387771	LGE	1	50 XXX	SP	CCA		V		5/14/2112
2020 PO4865287759	LGE	4	40 XXX	SP	CCA		V		5/15/2112
2020 PO4882087542	LGE	3	45 XXX	SP	CCA		V		5/16/2112
2020 PO4881587559	LGE	4	40 XXX	SP	CCA		V		5/17/2112
2020 PO4880887576	LGE	3	45 XXX	SP	CCA		V		5/18/2112
2020 PO4880187595	LGE	3	45 XXX	SP	CCA		V		5/19/2112
2020 PO4883487502	LGE	4	40 XXX	SP	CCA		V		5/20/2112
2020 PO4883887488	LGE	4	40 XXX	SP	A	ID	BD		5/21/2112
2020 PO4882687522	LGE	5	40 XXX	SP	CRE	ID	BD		5/22/2112
2020 PO4879487615	LGE	3	45 XXX	SP	CCA		V		5/23/2112
2020 PO5683548055	KU	4	40 OTH	SP	CRE	ED,ID	X	RP3	5/24/2112
2020 PO5665848279	KU	5	35 OTH	SP	CRE	ED,SRS	TD		5/25/2112
2020 PO4814988380	LGE	4	30 BRO	SP	CRE	ED	TD		5/26/2112
2020 PO4813688378	LGE	4	30 BRO	SP	CRE	ED	TD		5/27/2112
2020 PO4813688389	LGE	4	40 BRO	SP	CRE	ED	TD		5/28/2112
2020 PO4661788420	LGE	4	30 BRN	SP	CCA		V		5/29/2112
2020 PO4662888428	F	4	30 BRN	SP	CRE	ED	VX	RP2	5/30/2112
2020 PO4662388425	F	4	40 BRN	SP	CRE		V		5/31/2112
2020 PO4661488438	LGE	3	50 BRN	SP	P	ED,ID	TD		6/1/2112
2020 PO4461888432	LGE	3	45 BRN	SP	CCA		V		6/2/2112
2020 PO4812388388	LGE	4	40 BRO	SP	CRE	ED	BD		6/3/2112
2020 PO4811888378	LGE	UNK	45 BRO	SP	CRE	ED	BD		6/4/2112

2020 PO4812288373	LGE	4	30 BRO	SP	CRE			T		6/5/2112	
2020 PO4810688385	LGE	UNK	45 BRO	SP	CRE		ED		BD	6/6/2112	
2020 PO4809388384	LGE	UNK	45 BRO	SP	CRE		ED		TD	6/7/2112	
2020 PO4809388374	LGE	4	30 BRO	SP	CRE		ED		TD	6/8/2112	
2020 PO9609675227	F	4	40 XXX	SP	A				V	6/9/2112	
2020 PO9592375254	KU	6	30 XXX	SP	CCA				V	6/10/2112	
2020 PO9599375304	KU	4	40 XXX	SP	CRE		HH,ID,RB	X	PX	6/11/2112	
2020 PO6560243988	KU	4	40 OTH	SP	CRE		ED,ID,SRS		TD	6/12/2112	
2020 PO5628548810	KU	4	40 OTH	SP	CRE		ED,ID,SR	X	RP3	6/13/2112	
2020 PO5641048869	KU	4	35 OTH	SP	P		ED,SRS		TD	6/14/2112	
2020 PO3906840251	KU	4	40 BRO	SP	CRE		ED,ID,IP		TD	6/15/2112	
2020 PO9635675560	KU	6	30 XXX	SP	CRE		ID		TD	6/16/2112	
2020 PO9647575405	F	4	40 XXX	SP	A				V	6/17/2112	
2020 PO3912040336	KU	4	40 BRO	SP	CRE		ED,ID,IP		TD	6/18/2112	
2020 PO9640875390	F	4	40 XXX	SP	A				V	6/19/2112	
2020 PO9645175345	KU	4	45 XXX	SP	P		ED		T	6/20/2112	
2020 PO9662975576	KU	4	45 XXX	SP	CRE		ID		TD	6/21/2112	
2020 PO3953441013	KU	4	40 BRO	SP	CRE		ED,ID,IP		TD	6/22/2112	
2020 PO4656988501	LGE	4	40 BRN	SP	A		ED,ID		BD	6/23/2112	
2020 PO4655788505	LGE	4	30 BRN	SP	A		ED,ID		BD	6/24/2112	
2020 PO4656388509	LGE	4	40 BRN	SP	A		ED,ID		BD	6/25/2112	
2020 PO3966241223	KU	4	40 BRO	SP	CRE		ED,ID,IP		TD	6/26/2112	
2020 PO4813088317	LGE	4	35 BRO	SP	CRE		ED		TD	6/27/2112	
2020 PO4812588323	LGE	4	40 BRO	SP	CRE		ED		TD	6/28/2112	
2020 PO4654688526	LGE	4	30 BRN	SP	P		ED,ID		TD	6/29/2112	
2020 PO4655188528	F	4	40 BRN	SP	CCA				V	6/30/2112	
2020 PO9660475750	KU	4	45 XXX	SP	CRE		ID		TD	7/1/2112	
2020 PO9673875780	KU	4	45 XXX	SP	CRE		ID		TD	7/2/2112	
2020 PO9676575606	KU	4	45 XXX	SP	CRE		ID		BD	7/3/2112	
2020 PO3968441341	KU	4	40 BRO	SP	CRE		ED,ID,IP		TD	7/4/2112	
2020 PO4650988578	LGE	6	25 BRN	SP	CRE		ED,ID		BD	7/5/2112	
2020 PO4813788309	LGE	4	30 BRO	SP	CRE		ED,ID,IP		TD	7/6/2112	
2020 PO4813488302	LGE	4	30 BRO	SP	CRE		ED,ID		TD	7/7/2112	
2020 PO4813888317	LGE	4	30 BRO	SP	CRE		ED,HH,ID,RB		BX	PX	7/8/2112
2020 PO4653688548	F	4	40 BRN	SP	CCA				V	7/9/2112	
2020 PO4653188545	LGE	4	30 BRN	SP	P		ED,ID		TD	7/10/2112	
2020 PO4652488553	LGE	4	30 BRN	SP	A		ED,ID		TD	7/11/2112	
2020 PO4653488557	F	4	40 BRN	SP	CCA				V	7/12/2112	
2020 PO4652588565	F	4	40 BRN	SP	CCA				V	7/13/2112	
2020 PO4651988561	LGE	4	25 BRN	SP	A		ED,ID		BD	7/14/2112	
2020 PO4651988573	F	4	40 BRN	SP	CCA				V	7/15/2112	
2020 PO6579143900	KU	4	40 OTH	SP	CRE		ED,SRS		TD	7/16/2112	
2020 PO6683344944	KU	4	40 OTH	SP	CRE		ED,SRS		TD	7/17/2112	
2020 PO6636243662	KU	4	40 OTH	SP	CRE		ED,SRS		TD	7/18/2112	
2020 PO6617043740	KU	4	40 OTH	SP	CCA				V	7/19/2112	
2020 PO6598243822	KU	4	40 OTH	SP	CRE		ED,SRS		TD	7/20/2112	
2020 PO4814488302	LGE	4	30 BRO	SP	CRE		ED		TD	7/21/2112	

2020 PO4814888306	LGE	4	30 BRO	SP	CRE	ED	BD	7/22/2112	
2020 PO4815088296	LGE	4	30 BRO	SP	CRE	ED	TD	7/23/2112	
2020 PO4816088286	LGE	4	30 BRO	SP	CRE	ED	TD	7/24/2112	
2020 PO4816888279	LGE	4	30 BRO	SP	CRE	ED	TD	7/25/2112	
2020 PO4817188276	LGE	4	30 BRO	SP	CRE	ED	TD	7/26/2112	
2020 PO4818188266	LGE	4	30 BRO	SP	CRE	ED	TD	7/27/2112	
2020 PO3970241440	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	7/28/2112	
2020 PO4651588570	LGE	4	25 BRN	SP	A	ED,ID	BD	7/29/2112	
2020 PO4651488581	F	3	50 BRN	SP	CCA		V	7/30/2112	
2020 PO4649388571	LGE	4	35 BRN	SP	CCA		V	7/31/2112	
2020 PO3585998134	LGE	1	50 BRN	SP	CCA		V	8/1/2112	
2020 PO9679375617	KU	4	45 XXX	SP	CRE	ID	TD	8/2/2112	
2020 PO9698375630	KU	4	45 XXX	SP	CRE	ID	TD	8/3/2112	
2020 PO9716375640	KU	4	45 XXX	SP	CRE	ID	TD	8/4/2112	
2020 PO9737675621	KU	4	45 XXX	SP	CRE	ID	TD	8/5/2112	
2020 PO3968441341-A	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/6/2112	
2020 PO3358797452	LGE	1	55 BRN	SP	CCA		V	8/7/2112	
2020 PO6638144348	KU	6	30 OTH	SP	CRE	ID	BD	8/8/2112	
2020 PO3376697383	LGE	1	55 BRN	SP	CCA		V	8/9/2112	
2020 PO4804388216	LGE	4	40 BRN	SP	CRE	ED,HH,ID	TX	RR	8/10/2112
2020 PO4803488223	LGE	4	30 BRN	SP	CRE	ED,ID	TD	8/11/2112	
2020 PO4802088211	LGE	4	40 BRN	SP	A	ED,ID	BD	8/12/2112	
2020 PO4800988209	LGE	4	30 BRN	SP	A	ED,ID	TD	8/13/2112	
2020 PO4799088200	LGE	UNK	30 BRN	SP	CRE		V	8/14/2112	
2020 PO4798988202	LGE	4	30 BRN	SP	CRE	ED,ID	BD	8/15/2112	
2020 PO4799388206	LGE	4	35 BRN	SP	A	ED,ID	BD	8/16/2112	
2020 PO4799088217	LGE	4	40 BRN	SP	A	ED,ID	BD	8/17/2112	
2020 PO4798988236	LGE	4	35 BRN	SP	CRE	ED,ID	BD	8/18/2112	
2020 PO4798988254	LGE	4	40 BRN	SP	CCA		V	8/19/2112	
2020 PO4797788269	LGE	4	40 BRN	SP	CCA		V	8/20/2112	
2020 PO4544693372	LGE	4	40 BRO	SP	CRE	ED	BD	8/21/2112	
2020 PO4796788281	LGE	4	35 BRN	SP	A	ED,ID	BD	8/22/2112	
2020 PO4795888292	LGE	4	35 BRN	SP	A	ED,ID	BD	8/23/2112	
2020 PO4794988304	LGE	4	35 BRN	SP	A	ED,ID	BD	8/24/2112	
2020 PO4742987934	LGE	4	30 BRO	SP	CRE	ED	TD	8/25/2112	
2020 PO4742287934	F	3	45 BRO	SP	CRE		V	8/26/2112	
2020 PO9377673678	KU	4	45 XXX	SP	CCA		V	8/27/2112	
2020 PO9384273401	F	5	35 XXX	SP	CCA		V	8/28/2112	
2020 PO4745287997	F	4	40 BRO	SP	CRE		V	8/29/2112	
2020 PO4745687977	F	4	40 BRO	SP	CRE		V	8/30/2112	
2020 PO8311861778	KU	2	45 BRN	SP	CCA		V	8/31/2112	
2020 PO8315961731	KU	2	50 BRN	SP	CCA		V	9/1/2112	
2020 PO8317961745	KU	2	45 BRN	SP	CRE		V	9/2/2112	
2020 PO8337761897	KU	2	50 BRN	SP	CCA		V	9/3/2112	
2020 PO8357362054	KU	2	50 BRN	SP	CCA		V	9/4/2112	
2020 PO8376962209	KU	2	45 BRN	SP	CCA		V	9/5/2112	
2020 PO8396462365	KU	2	45 BRN	SP	CCA		V	9/6/2112	

2020 PO8416062520	KU	2	45 BRN	SP	CCA		V	9/7/2112
2020 PO8435662675	KU	2	45 BRN	SP	CCA		V	9/8/2112
2020 PO8454962834	KU	2	45 BRN	SP	CCA		V	9/9/2112
2020 PO8473762999	KU	2	45 BRN	SP	CCA		V	9/10/2112
2020 PO8492463165	KU	2	45 XXX	SP	CCA		V	9/11/2112
2020 PO8511563327	KU	2	45 XXX	SP	CCA		V	9/12/2112
2020 PO8530163492	KU	2	50 XXX	SP	CCA		V	9/13/2112
2020 PO4746687959	LGE	4	30 BRO	SP	CRE	ED	BD	9/14/2112
2020 PO4794088315	LGE	4	35 BRN	SP	CRE	ED,ID	BD	9/15/2112
2020 PO4793188326	LGE	4	35 BRN	SP	CRE	ED,ID	BD	9/16/2112
2020 PO4747188040	F	4	40 BRO	SP	CRE		V	9/17/2112
2020 PO4748388042	F	3	45 BRO	SP	CCA		V	9/18/2112
2020 PO4747888044	LGE	UNK	25 BRO	SP	CRE	ED,ID	BD	9/19/2112
2020 PO4747988064	F	3	45 BRO	SP	CCA		V	9/20/2112
2020 PO4748788024	F	3	45 BRO	SP	CCA		V	9/21/2112
2020 PO4744588035	F	3	45 BRO	SP	CCA		V	9/22/2112
2020 PO4792288338	LGE	4	40 BRN	SP	A	ED,ID	TD	9/23/2112
2020 PO4792288338-A	LGE	6	30 BRN	SP	A	ED,ID	BD	9/24/2112
2020 PO9404573994	F	4	40 XXX	SP	A		V	9/25/2112
2020 PO9392373852	KU	3	45 XXX	SP	CCA		V	9/26/2112
2020 PO4742587917	F	4	40 BRO	SP	CRE		V	9/27/2112
2020 PO4743687926	LGE	4	35 BRO	SP	CRE	ED	TD	9/28/2112
2020 PO4746087913	F	3	45 BRO	SP	CCA		V	9/29/2112
2020 PO4743787915	LGE	3	25 BRO	SP	CRE	ED	TD	9/30/2112
2020 PO4744187914	LGE	UNK	25 BRO	ST	P		V	10/1/2112
2020 PO4744087915	F	4	40 BRO	SP	CCA		V	10/2/2112
2020 PO9383573848	KU	4	40 XXX	SP	CCA		V	10/3/2112
2020 PO3937874049	KU	5	30 KOP	SP	CRE	ID	BD	10/4/2112
2020 PO3934174378	KU	3	65 KOP	SP	CRE		V	10/5/2112
2020 PO3939974376	KU	2	55 KOP	SP	CRE		V	10/6/2112
2020 PO3963674482	KU	4	40 KOP	SP	CRE	ID	BD	10/7/2112
2020 PO3980774713	KU	4	40 KOP	SP	CRE	ID	BD	10/8/2112
2020 PO3999274963	KU	4	40 KOP	SP	CRE	ID	BD	10/9/2112
2020 PO3932674991	KU	3	45 KOP	SP	S		V	10/10/2112
2020 PO3931875826	KU	2	65 KOP	SP	S		V	10/11/2112
2020 PO3931875826A	KU	2	55 KOP	SP	CRE		V	10/12/2112
2020 PO4791388347	LGE	4	40 BRN	SP	A	ED,ID	BD	10/13/2112
2020 PO4790688345	LGE	4	30 BRN	SP	A	ED,ID	BD	10/14/2112
2020 PO9465771595	KU	6	30 OTH	SP	CRE		V	10/15/2112
2020 PO9440071771	KU	4	40 OTH	SP	CRE	ED,SRS	TD	10/16/2112
2020 PO9422472036	KU	4	40 OTH	SP	CRE	ED,SRS	TD	10/17/2112
2020 PO9354173380	KU	5	35 XXX	SP	CRE	ID,RB	TX	RR 10/18/2112
2020 PO9360773359	KU	6	30 XXX	SP	P	ED	T	10/19/2112
2020 PO8155460625	KU	1	75 BRN	SP	CRE		V	10/20/2112
2020 PO8184760887	KU	1	70 BRN	SP	CCA		V	10/21/2112
2020 PO8197761011	KU	2	70 BRN	SP	CRE		V	10/22/2112
2020 PO8203561056	KU	2	45 BRN	SP	CRE		V	10/23/2112

2020 PO9371873311	KU	4	45 XXX	SP	CRE	ID	TD	10/24/2112
2020 PO8213161052	KU	4	45 BRN	SP	CCA		V	10/25/2112
2020 PO8206361073A	KU	4	40 BRN	SP	CCA		V	10/26/2112
2020 PO8206361073	KU	3	45 BRN	SP	CCA		V	10/27/2112
2020 PO8209861104	KU	4	40 BRN	SP	CCA		V	10/28/2112
2020 PO8208561123	KU	2	50 BRN	SP	CCA		V	10/29/2112
2020 PO8207461143	KU	2	50 BRN	SP	CCA		V	10/30/2112
2020 PO9377473113	KU	4	40 XXX	SP	CRE	ID	BD	10/31/2112
2020 PO9368773244	KU	4	40 XXX	SP	CRE	ID	BD	11/1/2112
2020 PO9356573156	KU	4	40 XXX	SP	CRE	ID	TD	11/2/2112
2020 PO8214261198	KU	2	50 BRN	SP	CCA		V	11/3/2112
2020 PO8222561196	KU	2	45 BRN	SP	CCA		V	11/4/2112
2020 PO8222561196A	KU	4	45 BRN	SP	CCA		V	11/5/2112
2020 PO8241861342	KU	1	75 BRN	ST	CRE		V	11/6/2112
2020 PO8229061186	KU	2	45 BRN	SP	CCA		V	11/7/2112
2020 PO8282161606	KU	2	50 BRN	SP	CCA		V	11/8/2112
2020 PO8262861457	KU	2	50 BRN	SP	CCA		V	11/9/2112
2020 PO8247861335	KU	4	45 BRN	SP	CCA		V	11/10/2112
2020 PO9476771123	KU	5	35 OTH	SP	CRE	ED,SRS	TD	11/11/2112
2020 PO9480771072	KU	4	45 OTH	SP	CCA		V	11/12/2112
2020 PO9486970977	KU	4	45 OTH	SP	CCA		V	11/13/2112
2020 PO8293961695	KU	3	50 BRN	SP	CCA		V	11/14/2112
2020 PO9349373104	KU	4	40 XXX	SP	CRE	ID	TD	11/15/2112
2020 PO9353673050	KU	6	30 XXX	SP	CRE	ID	TD	11/16/2112
2020 PO8308661808	KU	2	50 BRN	SP	CCA		V	11/17/2112
2020 PO8317361881	KU	4	40 BRN	SP	CRE		B	11/18/2112
2020 PO8312561836	KU	4	40 BRN	SP	CCA		V	11/19/2112
2020 PO8303461943	KU	3	45 BRN	SP	CCA		V	11/20/2112
2020 PO9489082279	F	4	40 BRO	SP	A		V	11/21/2112
2020 PO9476482360	F	3	45 BRO	SP	CRE		V	11/22/2112
2020 PO9457982469	F	4	40 BRO	SP	CRE		V	11/23/2112
2020 PO9445982539	F	4	40 BRO	SP	CCA		V	11/24/2112
2020 PO9440782570	F	4	40 BRO	SP	CCA		V	11/25/2112
2020 PO9423582672	F	5	35 BRO	SP	CRE		V	11/26/2112
2020 PO9404382782	F	4	40 BRO	SP	CRE		V	11/27/2112
2020 PO9396983050	F	4	40 BRO	SP	A		V	11/28/2112
2020 PO9388682916	F	4	40 BRO	SP	CRE		V	11/29/2112
2020 PO9386982886	F	3	45 BRO	SP	CRE		V	11/30/2112
2020 PO9357683055	F	3	45 BRO	SP	CRE		V	12/1/2112
2020 PO9342783140	F	3	45 BRO	SP	A		V	12/2/2112
2020 PO9376582944	F	3	45 BRO	SP	CRE		V	12/3/2112
2020 PO9534482012	F	4	40 BRO	SP	A		V	12/4/2112
2020 PO9549881921	F	4	40 BRO	SP	CCA		V	12/5/2112
2020 PO9188780649	F	4	40 BRO	SP	CRE		V	12/6/2112
2020 PO9722084960	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	12/7/2112
2020 PO9736884987	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	12/8/2112
2020 PO9681085882	KU	4	40 BRO	SP	CRE	ID,IP	BD	12/9/2112

Business Use

2020 PO9641685672	KU	4	40 BRO	SP	CCA		V	12/10/2112
2020 PO9602085464	F	4	40 BRO	SP	CRE		V	12/11/2112
2020 PO9602085444	F	5	35 BRO	SP	CRE		V	12/12/2112
2020 PO9601485345	KU	6	30 BRO	SP	CRE	ID,IP	BD	12/13/2112
2020 PO9292283797	KU	3	50 BRO	SP	CCA		V	12/14/2112
2020 PO9284983939	KU	3	55 BRO	SP	CCA		V	12/15/2112
2020 PO9290083017	KU	5	35 BRO	SP	CRE	ID	BD	12/16/2112
2020 PO9327683231	F	3	45 BRO	SP	CRE		V	12/17/2112
2020 PO9280683105	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	12/18/2112
2020 PO9271684197	KU	3	50 BRO	SP	CCA		V	12/19/2112
2020 PO9261984382	KU	4	45 BRO	SP	CCA		V	12/20/2112
2020 PO6989786769	KU	4	40 BRO	SP	CCA		B	12/21/2112
2020 PO6996686892	KU	4	40 BRO	SP	CRE	ED,ID	TD	12/22/2112
2020 PO7273374146	KU	3	45 BRN	SP	CCA		V	12/23/2112
2020 PO7294674103A	KU	4	45 BRN	SP	CCA		V	12/24/2112
2020 PO7267174157	KU	3	45 BRN	SP	CCA		V	12/25/2112
2020 PO7000286957	KU	4	40 BRO	SP	CRE	ED,ID	TD	12/26/2112
2020 PO6988287067	KU	4	40 BRO	SP	CRE	ED,ID	TD	12/27/2112
2020 PO4299602490	KU	4	40 BRN	SP	CRE	ED,SRS	TD	12/28/2112
2020 PO4237402493	KU	4	45 BRN	SP	CCA		V	12/29/2112
2020 PO4248102490	KU	3	45 BRN	SP	CCA		V	12/30/2112
2020 PO4275202487	KU	3	45 BRN	SP	CCA		V	12/31/2112
2020 PO4354102362	KU	4	40 KOP	SP	CCA		V	1/1/2113
2020 PO7401373926	KU	3	45 BRN	SP	CCA		V	1/2/2113
2020 PO7408473912	KU	5	35 BRN	SP	CCA		V	1/3/2113
2020 PO7435073826	KU	5	35 BRN	SP	CCA		V	1/4/2113
2020 PO7459073445A	KU	5	35 BRN	SP	CCA		V	1/5/2113
2020 PO6935287251	KU	4	40 BRO	SP	CRE	ED,ID	BD	1/6/2113
2020 PO6910987424	KU	3	35 BRO	SP	A	ED,ID	BD	1/7/2113
2020 PO6904287399	KU	3	40 BRO	SP	CRE	ED,ID	BD	1/8/2113
2020 PO6899687381A	KU	3	40 BRO	SP	A	ED,ID	BD	1/9/2113
2020 PO6882687308	KU	H1	85 BRO	SP	CRE	ED,ID	BD	1/10/2113
2020 PO2201554589	KU	4	40 BRO	SP	CRE		V	1/11/2113
2020 PO2214054518	KU	4	40 BRO	SP	CCA		V	1/12/2113
2020 PO2224054719	KU	4	40 BRO	SP	CRE		V	1/13/2113
2020 PO2204354326	KU	4	40 BRO	SP	CCA		V	1/14/2113
2020 PO2207354818	KU	4	40 BRO	SP	CCA		V	1/15/2113
2020 PO2210755391	KU	4	40 BRO	SP	CCA		V	1/16/2113
2020 PO2201355143	KU	4	40 BRO	SP	CRE		V	1/17/2113
2020 PO2192654913	KU	4	40 BRO	SP	CCA		V	1/18/2113
2020 PO2173554972	KU	3	45 BRO	SP	CCA		V	1/19/2113
2020 PO2154355031	KU	3	45 BRO	SP	CCA		V	1/20/2113
2020 PO2245555503	F	4	40 BRO	SP	CRE		V	1/21/2113
2020 PO2231755695	F	4	40 BRO	SP	A		V	1/22/2113
2020 PO9247984656	KU	4	40 BRO	SP	CCA	ED	T	1/23/2113
2020 PO9330183214	F	3	45 BRO	SP	CRE		V	1/24/2113
2020 PO9800285111	F	3	45 BRO	SP	CCA		V	1/25/2113

2020 PO9821585201	KU	5	35 BRO	SP	CRE	ID	BD	1/26/2113
2020 PO9839585274	KU	5	35 BRO	SP	CRE	ID,IP	BD	1/27/2113
2020 PO9874085579	KU	4	40 BRO	SP	CRE	ID,IP	BD	1/28/2113
2020 PO9887485793	KU	6	30 BRO	SP	CRE	ID	BD	1/29/2113
2020 PO9896785942	KU	6	30 BRO	SP	CRE	ED,SRC	TD	1/30/2113
2020 PO9840785227	F	5	35 BRO	SP	A		V	1/31/2113
2020 PO9860985362	F	4	45 BRO	SP	CCA		V	2/1/2113
2020 PO9878585484	F	3	55 BRO	SP	CRE		V	2/2/2113
2020 PO9893085607	F	4	40 BRO	SP	A		V	2/3/2113
2020 PO9903485695	F	4	40 BRO	SP	CRE		V	2/4/2113
2020 PO9913185776	F	4	40 BRO	SP	A		V	2/5/2113
2020 PO9300683143	KU	4	45 BRO	SP	CCA		V	2/6/2113
2020 PO9335483572	KU	3	50 BRO	SP	CCA		V	2/7/2113
2020 PO9318083307	KU	3	55 BRO	SP	CCA		V	2/8/2113
2020 PO9305983531	KU	3	50 BRO	SP	CCA		V	2/9/2113
2020 PO7883584473	KU	6	30 BRN	SP	CRE	ED,ID	V	2/10/2113
2020 PO9689674127	KU	2	65 BRN	SP	CRE	ED,ID	TD	2/11/2113
2020 PO2782404689	KU	2	60 BRO	SP	CCA		V	2/12/2113
2020 PO7582675029	KU	5	35 BRO	SP	CCA		V	2/13/2113
2020 PO7571475084	KU	4	40 BRO	SP	P		B	2/14/2113
2020 PO7543375298	KU	5	35 BRO	SP	CCA		V	2/15/2113
2020 PO7572775363	KU	4	35 BRO	SP	P	ED,ID	BD	2/16/2113
2020 PO7556275260	KU	5	35 BRO	SP	CRE	ED,ID	TD	2/17/2113
2020 PO7572375228	KU	5	35 BRO	SP	P		B	2/18/2113
2020 PO7336174926	KU	4	40 BRN	SP	CRE	ED,ID,IP	BD	2/19/2113
2020 PO7345974901	KU	6	30 BRN	SP	CRE	ED,EP,ID	BD	2/20/2113
2020 PO7341474822	KU	5	35 BRN	SP	CRE	ED,ID	TD	2/21/2113
2020 PO7525375625	KU	5	35 BRO	SP	CCA		V	2/22/2113
2020 PO7102684084	KU	4	40 BRO	SP	CRE	ED,ID	BD	2/23/2113
2020 PO1982946166	KU	4	40 BRO	SP	CCA		V	2/24/2113
2020 PO7339574916	KU	6	30 BRN	SP	CRE	ED,ID	BD	2/25/2113
2020 PO7342874908	KU	4	40 BRN	SP	CRE	ED,ID	BD	2/26/2113
2020 PO7313074942	KU	2	60 BRN	SP	CCA		V	2/27/2113
2020 PO7573475493	KU	5	30 BRO	SP	P	ED,ID	TD	2/28/2113
2020 PO7553975398	KU	4	40 BRO	SP	CRE		B	3/1/2113
2020 PO7539075804	KU	5	35 BRO	SP	CCA		V	3/2/2113
2020 PO7113884571	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/3/2113
2020 PO7131884541	KU	4	40 BRO	SP	CRE	ED,ID	BD	3/4/2113
2020 PO7131784424	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/5/2113
2020 PO7133984513	KU	4	45 BRO	SP	CCA		V	3/6/2113
2020 PO7107084487	KU	5	30 BRO	SP	CRE	ED,ID	TD	3/7/2113
2020 PO7099884466	KU	4	40 BRO	SP	CRE	ED,ID	TD	3/8/2113
2020 PO7090584418	KU	6	30 BRO	SP	CRE	ED,ID	TD	3/9/2113
2020 PO7087084459	KU	3	45 BRO	SP	CRE	ED,ID	TD	3/10/2113
2020 PO7553575489	KU	5	35 BRO	SP	CCA		V	3/11/2113
2020 PO7575775636	KU	4	35 BRO	SP	CRE		V	3/12/2113
2020 PO7565575611	KU	4	45 BRO	SP	CCA		V	3/13/2113

2020 PO7554975702	KU	5	35 BRO	SP	CCA		V		3/14/2113
2020 PO7118584116	KU	6	30 BRO	SP	CRE	ED,ID,MD	BX	RP2	3/15/2113
2020 PO7116784300	KU	4	40 BRO	SP	CRE	ED,ID	TD		3/16/2113
2020 PO7309574730	KU	3	55 BRN	SP	CRE	ED,ID	TD		3/17/2113
2020 PO7306674552	KU	3	50 BRN	SP	A	ED,ID	TD		3/18/2113
2020 PO7103684334	KU	3	45 BRO	SP	S		V		3/19/2113
2020 PO7573976113	KU	5	35 BRO	SP	CCA		V		3/20/2113
2020 PO7583876097	KU	3	40 BRO	SP	P	ED,ID	TD		3/21/2113
2020 PO7083984277	KU	3	45 BRO	SP	CRE	ED,ID	TD		3/22/2113
2020 PO7083584138	KU	4	45 BRO	SP	CRE	ED,ID	TD		3/23/2113
2020 PO7593876205	KU	4	40 BRO	SP	P	ED,ID	TD		3/24/2113
2020 PO7574276254	KU	5	35 BRO	SP	CRE		V		3/25/2113
2020 PO7096584243	KU	6	30 BRO	SP	CRE	ED,ID	TD		3/26/2113
2020 PO7107284175	KU	6	30 BRO	SP	CRE	ED,ID	TD		3/27/2113
2020 PO1945445236	KU	6	30 BRO	SP	CRE	ED,IP	TD		3/28/2113
2020 PO1935545157	KU	4	40 BRO	SP	CRE	ED,ID	TD		3/29/2113
2020 PO1932245261	KU	4	40 BRO	SP	CRE	ED,IP	TD		3/30/2113
2020 PO1928245354	KU	4	40 BRO	SP	CRE	ED,ID	TD		3/31/2113
2020 PO1924245481	KU	4	40 BRO	SP	CRE	EP,ID,IP	TD		4/1/2113
2020 PO1930745575	KU	4	40 BRO	SP	CRE	ED,EP,ID	TD		4/2/2113
2020 PO1936045638	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		4/3/2113
2020 PO1968846023	KU	4	40 BRO	SP	CCA	ED	TD		4/4/2113
2020 PO1997146057	KU	6	30 BRO	SP	CCA		V		4/5/2113
2020 PO2002146119	KU	4	40 BRO	SP	CCA		V		4/6/2113
2020 PO1956245902	KU	4	45 BRO	SP	CCA	ED	TD		4/7/2113
2020 PO1958445794	KU	4	40 BRO	SP	CCA	ED	TD		4/8/2113
2020 PO1959845686	KU	4	40 BRO	SP	CRE	ID,IP	TD		4/9/2113
2020 PO1941445496	KU	4	40 BRO	SP	CRE	ID	TD		4/10/2113
2020 PO1950145457	KU	4	40 BRO	SP	CCA		V		4/11/2113
2020 PO1705558557	KU	5	35 BRO	SP	CRE	ID,IP	BD		4/12/2113
2020 PO1696958240	KU	4	40 BRO	SP	CCA		V		4/13/2113
2020 PO1687857925	KU	4	40 BRO	SP	CRE	ED,ID	BD		4/14/2113
2020 PO1659957508	KU	3	40E BRO	SP	CRE	ED,ID,IP,SRC	TD		4/15/2113
2020 PO1661657728	KU	5	35 BRO	SP	CRE	ED,EP	TD		4/16/2113
2020 PO1597157776	KU	4	45 BRO	SP	CRE	ID,IP	TD		4/17/2113
2020 PO1642957582	KU	5	35 BRO	SP	CRE	ED,HH	X	RP2	4/18/2113
2020 PO1597557301	KU	5	35 BRO	SP	CRE	ID	TD		4/19/2113
2020 PO1612356999	F	4	40 BRO	SP	CRE		V		4/20/2113
2020 PO1600856977	KU	4	40 BRO	SP	CRE	ID	TD		4/21/2113
2020 PO0578417502	KU	3	45 ACE	SP	CCA		V		4/22/2113
2020 PO0598217529	KU	3	45 ACE	SP	CCA		V		4/23/2113
2020 PO0618017555	KU	3	45 ACE	SP	CCA		V		4/24/2113
2020 PO0802122271f	KU	3	40 ACE	SP	CCA		V		4/25/2113
2020 PO0802122271e	KU	3	40 ACE	SP	CCA		V		4/26/2113
2020 PO0636918062	KU	3	45 ACE	SP	CCA		V		4/27/2113
2020 PO0641318301	KU	3	45 ACE	SP	CCA		V		4/28/2113
2020 PO0519318114	KU	4	40 ACE	SP	CCA		V		4/29/2113

2020 PO0547318127	KU	4	40 ACE	SP	CCA		V			4/30/2113	
2020 PO0645818540	KU	3	45 ACE	SP	CCA		V			5/1/2113	
2020 PO0778321280	KU	5	30 ACE	SP	CRE		V			5/2/2113	
2020 PO0830315628	F	4	40 ACE	SP	CRE		V			5/3/2113	
2020 PO0840319377	KU	4	45 ACE	SP	CCA		V			5/4/2113	
2020 PO0845219132	KU	4	45 ACE	SP	CCA		V			5/5/2113	
2020 PO0746920904	F	4	40 ACE	SP	CRE		V			5/6/2113	
2020 PO0756321199	F	4	40 ACE	SP	CRE		V			5/7/2113	
2020 PO0766721500	F	4	40 ACE	SP	CRE		ED,ID			5/8/2113	
2020 PO0750821728	KU	4	40 ACE	SP	CRE		ED,ID		TD	5/9/2113	
2020 PO0777121804	F	4	40 ACE	SP	P		ED,EP,HH,ID,IP,RB		VX	RP1	5/10/2113
2020 PO0802122271d	KU	4	40 ACE	SP	CCA				V		5/11/2113
2020 PO0787422337	KU	6	30 ACE	SP	CRE		ED,ID		TD		5/12/2113
2020 PO0802122271c	KU	4	40 ACE	SP	CCA				V		5/13/2113
2020 PO0802122271b	KU	4	40 ACE	SP	CCA				V		5/14/2113
2020 PO0802122271a	KU	4	40 ACE	SP	CCA				V		5/15/2113
2020 PO0802122271	F	4	40 ACE	SP	P				V		5/16/2113
2020 PO0887324250	KU	6	30 ACE	SP	CRE		ED,ID,IP		TD		5/17/2113
2020 PO0841922806	F	4	40 ACE	SP	P		ED,ID		V		5/18/2113
2020 PO0875724889	F	7	20 ACE	SP	CRE		ED,EP,ID		V		5/19/2113
2020 PO0878624787	KU	5	35 ACE	SP	CRE		ED,ID,IP		TD		5/20/2113
2020 PO0912324682	KU	5	35 ACE	SP	CRE		ED,ID,IP		TD		5/21/2113
2020 PO0929624628	KU	6	30 ACE	SP	CRE		ED,ID		TD		5/22/2113
2020 PO0821722769	F	4	40 ACE	SP	P		ED,ID		V		5/23/2113
2020 PO0828422947	F	4	40 ACE	SP	P		ED,ID		V		5/24/2113
2020 PO8433478062	KU	5	35 BRO	SP	CRE		ED,ID,IP		TD		5/25/2113
2020 PO8619385682	KU	6	30 BRO	SP	CRE		ID		BD		5/26/2113
2020 PO8634785170	KU	4	45 BRO	SP	CRE		ED,ID,SRC		TD		5/27/2113
2020 PO8638985381	KU	4	45 BRO	SP	CCA				V		5/28/2113
2020 PO8433477968	KU	5	35 BRO	SP	CRE		ED,ID,IP		TD		5/29/2113
2020 PO8404477824	KU	6	30 BRO	SP	CRE		ID,IP		BD		5/30/2113
2020 PO8430777946	F	5	35 BRO	SP	CRE				V		5/31/2113
2020 PO8391780774	KU	5	35 BRO	SP	CCA		ED		T		6/1/2113
2020 PO8415980643	KU	4	40 BRO	SP	CCA				V		6/2/2113
2020 PO8396480699	KU	4	40 BRO	SP	CCA				V		6/3/2113
2020 PO8400980599	KU	6	30 BRO	SP	CCA				V		6/4/2113
2020 PO8391080590	KU	5	35 BRO	SP	CCA		ED		T		6/5/2113
2020 PO8394880489	KU	4	40 BRO	SP	CCA				V		6/6/2113
2020 PO8389680429	KU	5	35 BRO	SP	CCA		ED		T		6/7/2113
2020 PO8424580424	F	3	50 BRO	SP	CRE		RB		VX	RP1	6/8/2113
2020 PO8402480253	F	3	50 BRO	SP	A				V		6/9/2113
2020 PO8385580409	F	3	50 BRO	SP	CRE				V		6/10/2113
2020 PO8392380356	KU	3	50 BRO	SP	CCA				V		6/11/2113
2020 PO8352178088	KU	4	40 BRO	SP	CCA				V		6/12/2113
2020 PO8363378114	F	6	30 BRO	SP	CRE				V		6/13/2113
2020 PO8375878099	F	5	35 BRO	SP	CRE				V		6/14/2113
2020 PO8467180032	KU	4	40 BRO	SP	A		ED		TD		6/15/2113

Business Use

2020 PO8469780384	KU	4	40 BRO	SP	CRE	ID,IP	BD	6/16/2113
2020 PO8471080308	F	4	45 BRO	SP	A		V	6/17/2113
2020 PO8493780320	F	4	40 BRO	SP	A		V	6/18/2113
2020 PO8643385640	KU	5	35 BRO	SP	CCA	ED,ID,SRC	TD	6/19/2113
2020 PO8632885548	KU	6	30 BRO	SP	CRE	ID,IP	BD	6/20/2113
2020 PO8626185289	F	4	40 BRO	SP	CCA		V	6/21/2113
2020 PO8624485388	F	4	40 BRO	SP	CRE		V	6/22/2113
2020 PO8623785476	F	4	40 BRO	SP	CCA		V	6/23/2113
2020 PO8623985568	F	3	45 BRO	SP	CRE		V	6/24/2113
2020 PO8627985672	F	4	40 BRO	SP	CRE		V	6/25/2113
2020 PO8496680317	F	4	40 BRO	SP	CCA		V	6/26/2113
2020 PO8501080342	F	6	30 BRO	SP	CRE		V	6/27/2113
2020 PO8502480188	F	4	40 BRO	SP	CRE		V	6/28/2113
2020 PO8506780214	F	6	30 BRO	SP	CRE		V	6/29/2113
2020 PO8507380078	F	4	45 BRO	SP	CCA		V	6/30/2113
2020 PO8512679954	F	4	45 BRO	SP	CCA		V	7/1/2113
2020 PO8565478475	F	4	40 BRO	SP	A		V	7/2/2113
2020 PO8582378467	F	4	40 BRO	SP	A		V	7/3/2113
2020 PO8542778486	F	4	40 BRO	SP	A		V	7/4/2113
2020 PO8554378480	F	4	40 BRO	SP	CCA		V	7/5/2113
2020 PO8533878490	F	4	40 BRO	SP	CRE		V	7/6/2113
2020 PO8525178495	F	4	40 BRO	SP	CCA		V	7/7/2113
2020 PO8523178521	F	6	30 BRO	SP	A		V	7/8/2113
2020 PO8594278461	F	4	40 BRO	SP	A		V	7/9/2113
2020 PO8587178409	KU	5	35 BRO	SP	CRE	ID	BD	7/10/2113
2020 PO8392477580	KU	6	30 BRO	AL	CCA		V	7/11/2113
2020 PO8392277516	KU	6	30 BRO	AL	CCA		V	7/12/2113
2020 PO8388078206	F	4	40 BRO	SP	CRE		V	7/13/2113
2020 PO8650283110	KU	4	40 BRO	SP	CRE	ID	BD	7/14/2113
2020 PO8521779336	F	4	40 BRO	SP	CRE		V	7/15/2113
2020 PO8675283066	KU	4	40 BRO	SP	CRE	ID	BD	7/16/2113
2020 PO8608683313	KU	4	40 BRO	SP	CCA		V	7/17/2113
2020 PO8584783333	KU	5	35 BRO	SP	CCA		V	7/18/2113
2020 PO8572283342	KU	5	35 BRO	SP	CCA		V	7/19/2113
2020 PO8636883513	F	4	40 BRO	SP	CCA		V	7/20/2113
2020 PO8644283500	KU	4	40 BRO	SP	CRE	ED,ID,IP	TX	7/21/2113
2020 PO8672183463	KU	5	35 BRO	SP	CRE	ID,IP	BD	7/22/2113
2020 PO8638783657	KU	5	35 BRO	SP	CRE	ED,ID,IP,SRC	TD	7/23/2113
2020 PO8501079478	KU	4	40 BRO	SP	CCA		V	7/24/2113
2020 PO8463180521	KU	4	40 BRO	SP	CRE	ED	TD	7/25/2113
2020 PO8434180510	KU	6	30 BRO	SP	CRE	ED	TD	7/26/2113
2020 PO8451180559	KU	4	40 BRO	SP	CRE	ID,IP	BD	7/27/2113
2020 PO8458880331	F	4	40 BRO	SP	CRE		V	7/28/2113
2020 PO8444280314	F	4	40 BRO	SP	A		V	7/29/2113
2020 PO4809888218	LGE	4	40 BRO	SP	CRE	ED	TD	7/30/2113
2020 PO4809888207	LGE	4	40 BRO	SP	CRE	ED	BD	7/31/2113
2020 PO7005239218	KU	4	40 OTH	SP	P	ED,SRS	TD	8/1/2113

2020 PO4655488692	LGE	4	35 BRN	SP	CRE	ED,ID	TD	8/2/2113
2020 PO3827740182	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	8/3/2113
2020 PO4806488178	LGE	UNK	45 BRO	SP	CRE	ED	BD	8/4/2113
2020 PO4807988196	LGE	UNK	45 BRO	SP	CRE	ED	BD	8/5/2113
2020 PO3874039144	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/6/2113
2020 PO3860739240	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/7/2113
2020 PO3836339362	KU	5	35 BRO	SP	CRE	ID,IP	BD	8/8/2113
2020 PO4823088214	LGE	4	30 BRO	SP	CRE	ED	BD	8/9/2113
2020 PO4825188178	LGE	4	40 BRO	SP	CRE	ED	BD	8/10/2113
2020 PO4825988185	LGE	4	40 BRO	SP	CRE	ED	BD	8/11/2113
2020 PO6982138735	KU	4	40 OTH	SP	P	ED,SRS	TD	8/12/2113
2020 PO6993638953	KU	4	40 OTH	SP	P	ED,SRS	TD	8/13/2113
2020 PO6975838593	KU	6	30 OTH	SP	CCA		V	8/14/2113
2020 PO6980138469	KU	4	40 OTH	SP	P	ED,SRS	TD	8/15/2113
2020 PO4821288201	LGE	4	40 BRO	SP	CCA		V	8/16/2113
2020 PO4821388209	LGE	4	30 BRO	SP	CCA		V	8/17/2113
2020 PO4819588211	LGE	4	40 BRO	SP	CRE	ED	TD	8/18/2113
2020 PO4820688198	LGE	4	40 BRO	SP	CCA		V	8/19/2113
2020 PO4817888226	LGE	4	40 BRO	SP	CRE	ED	BD	8/20/2113
2020 PO9636374306	KU	4	40 XXX	SP	P	ED	T	8/21/2113
2020 PO9713075095	KU	4	40 XXX	SP	CCA		V	8/22/2113
2020 PO9702574791	KU	4	40 XXX	SP	P	ED	T	8/23/2113
2020 PO9694775003	KU	4	40 XXX	SP	P	ED	T	8/24/2113
2020 PO4660388669	F	3	50 BRN	SP	A		V	8/25/2113
2020 PO6969338229	KU	4	40 OTH	SP	P	ED,SRS	TD	8/26/2113
2020 PO6917438095A	KU	4	40 OTH	SP	P	ED,SRS	TD	8/27/2113
2020 PO6944638138	KU	4	40 OTH	SP	P	ED,SRS	TD	8/28/2113
2020 PO4822688185	LGE	4	30 BRO	SP	CRE	ED	TD	8/29/2113
2020 PO4662388686	F	3	50 BRN	SP	A		V	8/30/2113
2020 PO3945738511	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/31/2113
2020 PO4821988186	LGE	4	40 BRO	SP	CRE	ED	TD	9/1/2113
2020 PO4823588168	LGE	4	40 BRO	SP	CRE	ED	TD	9/2/2113
2020 PO6917438095	KU	4	40 OTH	SP	P	ED,SRS	TD	9/3/2113
2020 PO3947538760	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/4/2113
2020 PO6922437609	KU	4	40 OTH	SP	P	ED,SRS	TD	9/5/2113
2020 PO6921337849	KU	4	40 OTH	SP	P	ED,SRS	TD	9/6/2113
2020 PO6895338089	KU	4	40 OTH	SP	P	ED,SRS	TD	9/7/2113
2020 PO4823888168	LGE	3	45 BRO	SP	CCA		V	9/8/2113
2020 PO4826488187	LGE	4	35 BRO	SP	CRE	ED	TD	9/9/2113
2020 PO9743775212	KU	4	40 XXX	SP	P	ED	T	9/10/2113
2020 PO9781875403	KU	3	50 XXX	SP	CCA		V	9/11/2113
2020 PO9769075347	KU	3	45 XXX	SP	CCA		V	9/12/2113
2020 PO3948938960	KU	4	35 BRO	SP	CRE	ED,ID,IP	TD	9/13/2113
2020 PO3948938960-A	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	9/14/2113
2020 PO3948938960-B	KU	5	35 BRO	SP	CRE	ID	BD	9/15/2113
2020 PO4825988232	LGE	4	40 BRO	SP	CRE	ED,ID	BD	9/16/2113
2020 PO4827288187	LGE	4	35 BRO	SP	CRE		V	9/17/2113

2020 PO4826588216	LGE		4	40 BRO	SP	CRE	ED	BD		9/18/2113
2020 PO4826988205	LGE		4	40 BRO	SP	CRE	ED	TD		9/19/2113
2020 PO4827388196	LGE	UNK		45 BRO	SP	CRE	ED	TD		9/20/2113
2020 PO4818087710	LGE		4	40 BRO	SP	CCA		V		9/21/2113
2020 PO7009739307	KU		4	40 OTH	SP	CRE	ED,SRS	TD		9/22/2113
2020 PO7032439214	KU		4	40 OTH	SP	CRE	ED,SRS	TD		9/23/2113
2020 PO7051439138	KU		4	40 OTH	SP	CRE	ED,SRS	TD		9/24/2113
2020 PO7074539046	KU		4	40 OTH	SP	CRE	ED,SRS	TD		9/25/2113
2020 PO3950039109	KU		4	40 BRO	SP	CRE	ED,ID,IP	TD		9/26/2113
2020 PO7096638958	KU		4	40 OTH	SP	CRE	ED,SRS	TD		9/27/2113
2020 PO7110138852	KU		4	40 OTH	SP	CRE	ED,ID,SRS	TD		9/28/2113
2020 PO7126838748	KU		4	40 OTH	SP	CRE	ED,SRS	TD		9/29/2113
2020 PO3949339010	KU		5	35 BRO	SP	CRE	ED,ID,IP	TD		9/30/2113
2020 PO4814687829	LGE	3H		50 BRO	SP	CRE	ED	TD		10/1/2113
2020 PO4813887822	LGE		4	50 BRO	SP	CRE	ED	TD		10/2/2113
2020 PO4814987862	LGE		3	45 BRO	SP	CCA		V		10/3/2113
2020 PO4815187868	LGE	3H		45 BRO	SP	CRE	ED	BD		10/4/2113
2020 PO4815287875	LGE	3H		45 BRO	SP	CRE	ED	TD		10/5/2113
2020 PO4814287873	LGE		4	40 BRO	SP	CCA		V		10/6/2113
2020 PO4814287887	F		4	30 BRO	SP	CRE		VX	RP1	10/7/2113
2020 PO4813987882	F		4	40 BRO	SP	CRE		V		10/8/2113
2020 PO4812887893	F		4	40 BRO	SP	CCA		V		10/9/2113
2020 PO4811587910	F		4	40 BRO	SP	CRE		V		10/10/2113
2020 PO4810687928	F		4	40 BRO	SP	CCA		V		10/11/2113
2020 PO4810587937	F		4	40 BRO	SP	CRE		V		10/12/2113
2020 PO4814487869	LGE		4	35 BRO	SP	CCA		V		10/13/2113
2020 PO4814887821	LGE	UNK		95 BRO	ST	P		V		10/14/2113
2020 PO4814987848	LGE	3H		45 BRO	SP	CCA		V		10/15/2113
2020 PO3895340302	KU		4	35 BRO	SP	CCA		V		10/16/2113
2020 PO4682488386	LGE	UNK		30 BRN	SP	A		V		10/17/2113
2020 PO4705988361	LGE		4	35 BRN	SP	CCA		V		10/18/2113
2020 PO4703788344	LGE	3H		45 BRN	SP	CRE		V		10/19/2113
2020 PO4704288337	LGE		4	40 BRN	SP	CRE		V		10/20/2113
2020 PO4684088486	F		4	35 BRN	SP	CRE		V		10/21/2113
2020 PO4685688498	F		4	35 BRN	SP	CRE		V		10/22/2113
2020 PO4685588520	F		3	45 BRN	SP	A		V		10/23/2113
2020 PO4685088528	F		3	45 BRN	SP	A		V		10/24/2113
2020 PO4685288537	F		4	40 BRN	SP	CCA		V		10/25/2113
2020 PO4683988520	F		4	40 BRN	SP	CRE		V		10/26/2113
2020 PO4682488509	F		4	40 BRN	SP	CRE		V		10/27/2113
2020 PO4680788498	F		4	35 BRN	SP	CRE		V		10/28/2113
2020 PO4682488475	F		4	35 BRN	SP	CRE		V		10/29/2113
2020 PO4679288486	F		4	40 BRN	SP	CRE		V		10/30/2113
2020 PO4680788463	F		4	40 BRN	SP	CRE		V		10/31/2113
2020 PO4679888457	F		4	40 BRN	SP	CRE		V		11/1/2113
2020 PO4678188478	F		4	40 BRN	SP	CRE		V		11/2/2113
2020 PO4676888469	F		4	40 BRN	SP	CRE		V		11/3/2113

2020 PO4678688448	F	4	40 BRN	SP	CCA		V	11/4/2113
2020 PO4675788461	F	4	40 BRN	SP	CRE		V	11/5/2113
2020 PO4677488439	F	4	40 BRN	SP	CRE		V	11/6/2113
2020 PO4674688453	F	4	40 BRN	SP	CRE		V	11/7/2113
2020 PO4676188430	F	4	40 BRN	SP	CRE		V	11/8/2113
2020 PO4675588426	F	4	40 BRN	SP	CRE		V	11/9/2113
2020 PO4791987895	F	4	40 BRO	SP	CCA		V	11/10/2113
2020 PO4791987898	F	4	40 BRO	SP	CCA		V	11/11/2113
2020 PO4790887870	F	4	40 BRO	SP	CRE		V	11/12/2113
2020 PO4791787849	F	3	50 BRO	SP	CCA		V	11/13/2113
2020 PO4791887872	F	4	40 BRO	SP	CRE		V	11/14/2113
2020 PO4794587903	F	4	40 BRO	SP	CCA		V	11/15/2113
2020 PO4792287899	F	4	40 BRO	SP	CRE		V	11/16/2113
2020 PO4792187913	F	UNK	30 BRO	SP	CRE		V	11/17/2113
2020 PO4791987884	F	3	45 BRO	SP	CCA	ED	V	11/18/2113
2020 PO4791287883	F	4	40 BRO	SP	CCA		V	11/19/2113
2020 PO4680788458	LGE	4	30 BRN	SP	CCA		V	11/20/2113
2020 PO4684388454	F	4	40 BRN	SP	CCA		V	11/21/2113
2020 PO4685988465	F	4	40 BRN	SP	CRE		V	11/22/2113
2020 PO4685988460	LGE	3	45 BRN	SP	CCA		V	11/23/2113
2020 PO4682688443	F	4	40 BRN	SP	CRE		V	11/24/2113
2020 PO4681688434	F	4	40 BRN	SP	CRE		V	11/25/2113
2020 PO4680388424	F	4	40 BRN	SP	CRE		V	11/26/2113
2020 PO4679188415	F	4	40 BRN	SP	CRE		V	11/27/2113
2020 PO4787688000	F	4	40 BRO	SP	CCA		V	11/28/2113
2020 PO4787288010	F	4	40 BRO	SP	CCA		V	11/29/2113
2020 PO4786787997	F	4	35 BRO	SP	CCA	ED	V	11/30/2113
2020 PO4788187986	F	4	40 BRO	SP	CCA		V	12/1/2113
2020 PO4788687971	F	4	40 BRO	SP	CCA		V	12/2/2113
2020 PO4788987961	F	4	40 BRO	SP	CCA		V	12/3/2113
2020 PO4789487948	F	4	40 BRO	SP	CCA		V	12/4/2113
2020 PO4789787937	F	4	40 BRO	SP	CCA		V	12/5/2113
2020 PO3865870354	KU	1	40 BRN	SP	CCA		V	12/6/2113
2020 PO5993847236	KU	4	40 OTH	SP	CRE	ID	TD	12/7/2113
2020 PO5983247080	KU	6	30 OTH	SP	CCA		V	12/8/2113
2020 PO4677988407	F	4	40 BRN	SP	CRE		V	12/9/2113
2020 PO4676188407	F	4	40 BRN	SP	CRE		V	12/10/2113
2020 PO4675088402	F	4	40 BRN	SP	CRE		V	12/11/2113
2020 PO4674388411	F	4	40 BRN	SP	CCA		V	12/12/2113
2020 PO4674488418	F	4	40 BRN	SP	CRE		V	12/13/2113
2020 PO4673688421	F	4	40 BRN	SP	CRE		V	12/14/2113
2020 PO4674388434	F	3	45 BRN	SP	S		V	12/15/2113
2020 PO4789188335	LGE	4	40 BRN	SP	CCA		V	12/16/2113
2020 PO9333273480	KU	5	30 OTH	SP	CCA		V	12/17/2113
2020 PO4745987957	F	4	40 BRO	SP	CRE	ED	V	12/18/2113
2020 PO4746187946	F	4	40 BRO	SP	CRE		V	12/19/2113
2020 PO4789588319	LGE	4	40 BRN	SP	A	ED,ID	TD	12/20/2113

2020 PO4790188321	LGE	4	30 BRN	SP	A	ED,ID	TD	12/21/2113
2020 PO4790688302	LGE	4	30 BRN	SP	A	ED,ID	BD	12/22/2113
2020 PO4790188301	LGE	4	40 BRN	SP	A	ED,ID	BD	12/23/2113
2020 PO9374173635	KU	4	40 XXX	SP	CRE		V	12/24/2113
2020 PO9367173558	KU	3	45 XXX	SP	CCA		V	12/25/2113
2020 PO9328173548B	KU	5	35 OTH	SP	CRE	ID	BD	12/26/2113
2020 PO9328873548A	KU	5	35 OTH	SP	CRE	ED,SRS	TD	12/27/2113
2020 PO9375473440	KU	4	40 XXX	SP	CRE	ID,RB	TD	12/28/2113
2020 PO9380473374	KU	3	45 XXX	SP	CCA		V	12/29/2113
2020 PO9337373607	KU	4	45 OTH	SP	CRE	ED,SRS	TD	12/30/2113
2020 PO9328873548	KU	4	40 OTH	SP	CRE	ED,SRS	TD	12/31/2113
2020 PO4676588864	LGE	4	40 BRO	SP	A	ED	TD	1/1/2114
2020 PO4677288855	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	1/2/2114
2020 PO4742488140	F	4	40 BRO	SP	CRE		V	1/3/2114
2020 PO4746388144	F	4	40 BRO	SP	CRE		V	1/4/2114
2020 PO8545963632	KU	2	45 XXX	SP	CCA		V	1/5/2114
2020 PO4683588870	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	1/6/2114
2020 PO9352973561	KU	5	30 OTH	SP	CRE	ED,SRS	TD	1/7/2114
2020 PO4749988174	F	3	45 BRO	SP	CCA		V	1/8/2114
2020 PO4750488153	F	4	40 BRO	SP	CRE		V	1/9/2114
2020 PO4750788133	F	4	40 BRO	SP	CRE		V	1/10/2114
2020 PO4751188113	F	4	40 BRO	SP	CRE		V	1/11/2114
2020 PO4751588094	F	3	45 BRO	SP	CRE		V	1/12/2114
2020 PO4751988073	F	3	45 BRO	SP	CRE		V	1/13/2114
2020 PO4751188048	F	4	40 BRO	SP	CCA		V	1/14/2114
2020 PO4752388050	F	4	40 BRO	SP	CCA		V	1/15/2114
2020 PO4752788033	F	4	40 BRO	SP	CRE		V	1/16/2114
2020 PO4753188013	F	4	40 BRO	SP	CRE		V	1/17/2114
2020 PO4753487994	F	4	40 BRO	SP	CRE		V	1/18/2114
2020 PO4753987974	F	4	40 BRO	SP	CRE		V	1/19/2114
2020 PO4754387951	F	4	40 BRO	SP	CRE		V	1/20/2114
2020 PO4750287953	F	4	40 BRO	SP	CRE		V	1/21/2114
2020 PO8539463716	KU	2	55 XXX	SP	CCA		V	1/22/2114
2020 PO8523663939	KU	2	55 XXX	SP	CCA		V	1/23/2114
2020 PO8509864144	KU	2	50 XXX	SP	CCA		V	1/24/2114
2020 PO8495364350	KU	2	45 XXX	SP	CCA		V	1/25/2114
2020 PO8480964553	KU	2	45 XXX	SP	CCA		V	1/26/2114
2020 PO8466364758	KU	2	45 XXX	SP	CCA		V	1/27/2114
2020 PO8455064924	KU	2	45 XXX	SP	CCA		V	1/28/2114
2020 PO8442365102	KU	2	50 XXX	SP	CCA		V	1/29/2114
2020 PO8450065169	KU	2	55 XXX	SP	CCA		V	1/30/2114
2020 PO8075956336	KU	6	30 XXX	SP	CCA	ED	T	1/31/2114
2020 PO8075856491	KU	4	40 XXX	SP	CRE	ED,ID	TD	2/1/2114
2020 PO8065356628	KU	5	35 XXX	SP	CRE	ED,ID,RB	BX	2/2/2114
2020 PO7945156939	KU	5	35 BRN	SP	CRE	ED,ID	TD	2/3/2114
2020 PO7967357092	KU	4	40 BRN	SP	CCA	ED	T	2/4/2114
2020 PO7986357218	KU	4	40 BRN	SP	CRE	ED,ID	TD	2/5/2114

2020 PO8013159256	KU	2	40 BRN	SP	CCA		V		2/6/2114
2020 PO8062456779	KU	4	40 BRN	SP	CCA	ED	T		2/7/2114
2020 PO8050256977	KU	4	40 BRN	SP	CRE	ED,ID	TD		2/8/2114
2020 PO8037757199	KU	4	40 BRN	SP	CRE	ED,ID	TD		2/9/2114
2020 PO8006057350	KU	4	40 BRN	SP	CCA		V		2/10/2114
2020 PO8021957448	KU	4	40 BRN	SP	CRE	ED,ID	TD		2/11/2114
2020 PO8006457673	KU	4	45 XXX	SP	CRE	ED,ID	TD		2/12/2114
2020 PO9388073269	KU	5	35 XXX	SP	CRE	ID	TD		2/13/2114
2020 PO9394173182A	KU	6	30 XXX	SP	P	ED	T		2/14/2114
2020 PO9394173182	KU	4	40 XXX	SP	CRE	ID	TD		2/15/2114
2020 PO4791988256	LGE	4	40 BRN	SP	CRE	ED,HH,ID	BX	PX	2/16/2114
2020 PO4791188266	LGE	4	40 BRN	SP	CRE	ED,ID,IP	BD		2/17/2114
2020 PO4790688282	LGE	4	40 BRN	SP	CRE	ED,ID	BD		2/18/2114
2020 PO4743288260	F	4	30 BRO	SP	CRE		V		2/19/2114
2020 PO4743888260	F	4	40 BRO	SP	CRE		V		2/20/2114
2020 PO4744588241	F	3	45 BRO	SP	CCA		V		2/21/2114
2020 PO4744888231	F	4	40 BRO	SP	CRE		V		2/22/2114
2020 PO1953885638	KU	4	45 OTH	SP	CCA		V		2/23/2114
2020 PO1934185506	KU	4	40 OTH	SP	CRE	ID,SRS	V		2/24/2114
2020 PO1912285471	KU	4	40 OTH	SP	CRE		V		2/25/2114
2020 PO9405373861	KU	6	30 OTH	SP	CCA		V		2/26/2114
2020 PO9355673722	KU	4	40 OTH	SP	CRE	ED,SRS	TD		2/27/2114
2020 PO9372073842	KU	4	40 OTH	SP	CRE	ED,SRS	TD		2/28/2114
2020 PO9345073666	KU	4	40 OTH	SP	CRE	ED,SRS	TD		3/1/2114
2020 PO4742388239	LGE	4	40 BRO	SP	CRE		B		3/2/2114
2020 PO4740788239	LGE	4	40 BRO	SP	CRE		B		3/3/2114
2020 PO4790988285	LGE	4	40 BRN	SP	A	ED,ID	BD		3/4/2114
2020 PO4791688289	LGE	4	40 BRN	SP	A	ED,ID	BD		3/5/2114
2020 PO4737088223	LGE	4	40 BRO	SP	CCA		V		3/6/2114
2020 PO4738388230	LGE	4	40 BRO	SP	CCA		V		3/7/2114
2020 PO4739588233	LGE	4	30 BRO	SP	CCA		V		3/8/2114
2020 PO4739188237	LGE	3	45 BRO	SP	CCA		V		3/9/2114
2020 PO4738888245	LGE	4	40 BRO	SP	CRE		B		3/10/2114
2020 PO4740288291	LGE	4	40 BRO	SP	CRE	ED	TD		3/11/2114
2020 PO4445196016-A	LGE	4	30 BRO	SP	CCA		V		3/12/2114
2020 PO4732988360	LGE	4	40 BRO	SP	CCA		V		3/13/2114
2020 PO4734688348	LGE	4	40 BRO	SP	CCA		V		3/14/2114
2020 PO4735088336	LGE	4	40 BRO	SP	CCA		V		3/15/2114
2020 PO4792988206	LGE	3	45 BRN	SP	A	ED,ID	TD		3/16/2114
2020 PO4682688863	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		3/17/2114
2020 PO4683188858	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD		3/18/2114
2020 PO4680388863	LGE	4	40 BRO	SP	CRE	ID,IP	BD		3/19/2114
2020 PO9415173185	KU	5	30 XXX	SP	CRE	ID	TD		3/20/2114
2020 PO9415173225	KU	6	30 XXX	SP	CRE		V		3/21/2114
2020 PO4681488853	LGE	4	40 BRO	SP	A	ED	TD		3/22/2114
2020 PO3966475715	KU	4	40 BRN	SP	CCA		V		3/23/2114
2020 PO4731588369	LGE	4	40 BRO	SP	CRE		V		3/24/2114

2020 PO4727588344	LGE	4	35 BRO	SP	CRE	ED	TD	3/25/2114
2020 PO4725588347	LGE	4	40 BRO	SP	CRE		V	3/26/2114
2020 PO4681388847	LGE	4	35 BRO	SP	CRE	ED,ID,IP	TD	3/27/2114
2020 PO4792588221	LGE	4	40 BRN	SP	A	ED,ID	BD	3/28/2114
2020 PO4792188234	LGE	4	40 BRN	SP	A	ED,ID	BD	3/29/2114
2020 PO479988138	LGE	4	30 BRN	SP	CCA		V	3/30/2114
2020 PO4801188157	LGE	4	30 BRN	SP	A	ED,ID	BD	3/31/2114
2020 PO4801088174	LGE	4	30 BRN	SP	CRE	ED,ID	BD	4/1/2114
2020 PO4801988188	LGE	4	30 BRN	SP	CRE	ED,HH,ID	BX PX	4/2/2114
2020 PO4828987406	LGE	3	45 BRO	SP	CCA		V	4/3/2114
2020 PO4829387388	LGE	3	45 BRO	SP	CCA		V	4/4/2114
2020 PO4829587381	LGE	3	45 BRO	SP	CCA		V	4/5/2114
2020 PO4828887375	LGE	4	30 BRO	SP	CRE	ED,EP,IP	TD	4/6/2114
2020 PO4829987355	LGE	3	45 BRO	SP	S		V	4/7/2114
2020 PO4829787368	LGE	3	45 BRO	SP	CCA		V	4/8/2114
2020 PO8445180361	F	4	40 BRO	SP	CCA		V	4/9/2114
2020 PO8471280260	F	5	35 BRO	SP	CRE		V	4/10/2114
2020 PO5576844277	KU	6	30 ACW	SP	CRE	ED,ID	TD	4/11/2114
2020 PO4270244040	KU	3	45 ACE	SP	CCA		V	4/12/2114
2020 PO4270944257	F	4	40 ACE	SP	CCA		V	4/13/2114
2020 PO4257144277	F	4	40 ACE	SP	CCA		V	4/14/2114
2020 PO4224644328	F	4	40 ACE	SP	CCA		V	4/15/2114
2020 PO4205844356	F	4	40 ACE	SP	CRE	ED,ID	V	4/16/2114
2020 PO4377002393	KU	5	30 BRO	SP	CRE	ED,ID,IP	TD	4/17/2114
2020 PO4368502372	KU	4	45 BRO	SP	CRE	ED,ID	TD	4/18/2114
2020 PO4370902472	KU	4	40 BRO	SP	CRE	ED,ID	TD	4/19/2114
2020 PO4188344387	F	3	45 ACE	SP	CRE		V	4/20/2114
2020 PO4166444506	F	3	45 ACE	SP	CCA		V	4/21/2114
2020 PO4143644628	F	4	40 ACE	SP	CRE	ED,ID	V	4/22/2114
2020 PO4113944757	F	4	40 ACE	SP	CRE	ED,ID	V	4/23/2114
2020 PO5631744365	KU	6	30 ACW	SP	CRE	ED,ID,IP	TD	4/24/2114
2020 PO4050944973	F	4	40 ACE	SP	CRE	ED,ID	V	4/25/2114
2020 PO4084944868	F	4	40 ACE	SP	P		V	4/26/2114
2020 PO4019045131	F	4	40 ACE	SP	CRE	ED,ID	V	4/27/2114
2020 PO3995345449	F	4	40 ACE	SP	CRE	ED,ID	V	4/28/2114
2020 PO3972845738	F	4	40 ACE	SP	CRE	ED,ID	V	4/29/2114
2020 PO5630044684	KU	6	30 ACW	SP	CRE	ED,ID	TD	4/30/2114
2020 PO5552844510	KU	4	40 ACW	SP	P	ED,ID	TD	5/1/2114
2020 PO3948046054	F	4	40 ACE	SP	CRE	ED,ID	V	5/2/2114
2020 PO3933146213	F	4	40 ACE	SP	CRE	ED,ID	V	5/3/2114
2020 PO4361502419	F	4	40 BRO	SP	CCA		V	5/4/2114
2020 PO3887646419	F	4	40 ACE	SP	CCA		V	5/5/2114
2020 PO3858146646	KU	4	45 ACE	SP	CCA		V	5/6/2114
2020 PO3850846684a	KU	4	35 ACE	SP	CCA	ED	T	5/7/2114
2020 PO3850846684	F	4	40 ACE	SP	CCA		V	5/8/2114
2020 PO3826546819	F	4	40 ACE	SP	CRE	ED,ID,IP	V	5/9/2114
2020 PO3807946927	F	4	40 ACE	SP	CRE	ED,ID	V	5/10/2114

2020 PO3787147041	F	4	45 ACE	SP	P		V		5/11/2114
2020 PO4372602549	KU	4	45 BRO	SP	CRE		V		5/12/2114
2020 PO5173511971	F	4	40 BRO	SP	CRE		V		5/13/2114
2020 PO5207012153	F	4	40 BRO	SP	CRE		V		5/14/2114
2020 PO5227012093	F	4	40 BRO	SP	CRE	ID,IP,RB	VX	RP2	5/15/2114
2020 PO5229611931	F	4	40 BRO	SP	CRE		V		5/16/2114
2020 PO5218711846	F	4	40 BRO	SP	CRE		V		5/17/2114
2020 PO5214511763	F	4	40 BRO	SP	CRE		V		5/18/2114
2020 PO5224411777	F	4	40 BRO	SP	CRE		V		5/19/2114
2020 PO5222711731	F	4	40 BRO	SP	CRE		V		5/20/2114
2020 PO4627988255	LGE	3	45 BRO	SP	CCA		V		5/21/2114
2020 PO4631288266	LGE	4	40 BRO	SP	CRE	ED,ID	BD		5/22/2114
2020 PO4631188248	LGE	4	40 BRO	SP	CRE	ED,ID	BD		5/23/2114
2020 PO4631088235	LGE	4	40 BRO	SP	CRE	ED,ID	BD		5/24/2114
2020 PO4630788209	LGE	3	45 BRO	SP	CCA		V		5/25/2114
2020 PO4627588211	LGE	3	45 BRO	SP	CCA		V		5/26/2114
2020 PO4627488200	LGE	3	50 BRO	SP	CRE	ED,ID	BD		5/27/2114
2020 PO9259633783	F	4	40 XXX	SP	A		V		5/28/2114
2020 PO9232532434	ODP	5	35 XXX	SP	CRE	ID	TD		5/29/2114
2020 PO9254131487	ODP	4	40 XXX	SP	CRE	ID	BD		5/30/2114
2020 PO9247228306	ODP	6	30 XXX	SP	CRE		V		5/31/2114
2020 PO9225928728	ODP	5	35 XXX	SP	CRE	ID	BD		6/1/2114
2020 PO9247728034	ODP	6	30 XXX	SP	CRE	ID,IP	BX	RP2	6/2/2114
2020 PO5157911995	KU	4	40 BRO	SP	CRE		V		6/3/2114
2020 PO5158712073	F	4	40 BRO	SP	CCA		V		6/4/2114
2020 PO5146112092	F	4	40 BRO	SP	CRE	HH,ID,IP,RB	VX	RP1	6/5/2114
2020 PO5137412089	F	4	40 BRO	SP	CRE		V		6/6/2114
2020 PO5127412166	F	4	40 BRO	SP	CRE		V		6/7/2114
2020 PO5143812051	F	4	40 BRO	SP	A		V		6/8/2114
2020 PO5340849423	KU	5	35 OTH	SP	CCA	ED,SRS	TD		6/9/2114
2020 PO5255150275	KU	3	45 OTH	SP	CCA		V		6/10/2114
2020 PO5300750900	KU	3	45 OTH	SP	CCA		V		6/11/2114
2020 PO5340051415	KU	4	40 OTH	SP	CCA		V		6/12/2114
2020 PO5391052085	KU	4	40 OTH	SP	CCA		V		6/13/2114
2020 PO5306849950	KU	4	40 OTH	SP	CCA		V		6/14/2114
2020 PO5417352205	KU	4	40 OTH	SP	CCA		V		6/15/2114
2020 PO5378051876	KU	4	40 OTH	SP	CCA		V		6/16/2114
2020 PO5333049779	KU	4	40 OTH	SP	CRE	ID	TD		6/17/2114
2020 PO5277050133	KU	4	40 OTH	SP	CRE	ID	BD		6/18/2114
2020 PO5272450511	KU	4	40 OTH	SP	CCA		V		6/19/2114
2020 PO5320351175	KU	4	40 OTH	SP	CCA		V		6/20/2114
2020 PO9209437232	ODP	6	30 BRO	SP	CRE	ED,ID	TD		6/21/2114
2020 PO9131338700	ODP	5	35 BRO	SP	CRE	ED,ID	TD		6/22/2114
2020 PO9042041518	ODP	6	30 BRO	SP	CRE	ID	BD		6/23/2114
2020 PO9179139313	ODP	5	35 BRO	SP	CRE	ID	BD		6/24/2114
2020 PO9131739927	ODP	5	35 BRO	SP	CRE	ED,ID	TD		6/25/2114
2020 PO9133740043	ODP	6	30 BRO	SP	CRE		V		6/26/2114

Business Use

2020 PO9126740147	ODP	3	50 ACW	SP	CRE	ED,ID	TD	6/27/2114
2020 PO9011641828	ODP	4	40 ACW	SP	CRE	ID	BD	6/28/2114
2020 PO9061741226	ODP	5	30 ACW	SP	CRE	ID	BD	6/29/2114
2020 PO5101412450	F	4	40 BRO	SP	CRE		V	6/30/2114
2020 PO5140112347	F	4	40 BRO	SP	CRE		V	7/1/2114
2020 PO5156512230	F	4	40 BRO	SP	A		V	7/2/2114
2020 PO5129312283	F	4	40 BRO	SP	CRE		V	7/3/2114
2020 PO5177112846	KU	4	40 BRO	SP	CCA		V	7/4/2114
2020 PO5180712908	KU	4	40 BRO	SP	CRE		V	7/5/2114
2020 PO5191112879	KU	6	30 BRO	SP	CRE		V	7/6/2114
2020 PO5196413256	KU	5	35 BRO	SP	CRE		V	7/7/2114
2020 PO5197613305	KU	4	40 BRO	SP	CRE		V	7/8/2114
2020 PO5158614060	KU	4	40 BRO	SP	CRE		V	7/9/2114
2020 PO5147714119	KU	5	35 BRO	SP	CRE		V	7/10/2114
2020 PO5132813846	KU	4	40 BRO	SP	CRE		V	7/11/2114
2020 PO5119513900	KU	5	35 BRO	SP	CCA		V	7/12/2114
2020 PO5175511006	KU	5	35 BRO	SP	CCA		V	7/13/2114
2020 PO5200410830	F	4	40 BRO	SP	CRE		V	7/14/2114
2020 PO5211610815	F	4	40 BRO	SP	CRE		V	7/15/2114
2020 PO5223010636	F	4	40 BRO	SP	CRE		V	7/16/2114
2020 PO5207910709	F	4	40 BRO	SP	CRE		V	7/17/2114
2020 PO5199910885	F	4	40 BRO	SP	CRE		V	7/18/2114
2020 PO5189210949	F	4	40 BRO	SP	CRE		V	7/19/2114
2020 PO5179111015	F	4	40 BRO	SP	CRE		V	7/20/2114
2020 PO5223610749	F	4	40 BRO	SP	CRE		V	7/21/2114
2020 PO5234110685	F	4	40 BRO	SP	CRE		V	7/22/2114
2020 PO5232710694	F	4	40 BRO	SP	CRE		V	7/23/2114
2020 PO5163713719	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	7/24/2114
2020 PO5157413739	KU	5	35 BRO	SP	CRE	ID,IP	BD	7/25/2114
2020 PO5149113762	KU	4	40 BRO	SP	CRE	HH,ID,IP,RB	X	RP1 7/26/2114
2020 PO5167714010	KU	4	40 BRO	SP	CRE	ID,IP	BD	7/27/2114
2020 PO5170013850	KU	4	30 BRO	SP	CRE	ID,IP	BD	7/28/2114
2020 PO5134214193	KU	4	40 BRO	SP	CRE		V	7/29/2114
2020 PO5372549527	KU	4	40 OTH	SP	CRE	ID	TD	7/30/2114
2020 PO5176713957	KU	4	40 BRO	SP	CRE	ID,IP,RB	X	RP1 7/31/2114
2020 PO5197213694	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/1/2114
2020 PO5175113881	KU	4	40 BRO	SP	CRE	ID,IP	X	RP1 8/2/2114
2020 PO5187513795	KU	4	40 BRO	SP	CRE	ID	BD	8/3/2114
2020 PO4639388289	LGE	4	40 BRO	SP	CRE		V	8/4/2114
2020 PO4640188293	LGE	4	40 BRO	SP	CRE		V	8/5/2114
2020 PO4641088297	LGE	4	40 BRO	SP	CRE	ED,ID	TD	8/6/2114
2020 PO5210913552	KU	6	30 BRO	SP	CCA		V	8/7/2114
2020 PO4732088130	LGE	3	45 BRO	SP	CCA		V	8/8/2114
2020 PO4730888122	LGE	3	45 BRO	SP	CCA		V	8/9/2114
2020 PO4743887508	LGE	4	40 BRO	SP	P	ED,ID	TD	8/10/2114
2020 PO4718988016	LGE	4	40 BRO	SP	A	ED,HH,ID	BD	8/11/2114
2020 PO4717988014	LGE	4	30 BRO	SP	P	ED,ID	BD	8/12/2114

Business Use

2020 PO4718188003	LGE	4	30 BRO	SP	CCA	ED,ID	BD	8/13/2114	
2020 PO4729888114	LGE	3	45 BRO	SP	CCA		V	8/14/2114	
2020 PO4728988108	LGE	4	40 BRO	SP	CCA		V	8/15/2114	
2020 PO4727588098	LGE	3	45 BRO	SP	CCA		V	8/16/2114	
2020 PO4725788086	LGE	3	45 BRO	SP	CCA		V	8/17/2114	
2020 PO4724188074	LGE	3	45 BRO	SP	CCA		V	8/18/2114	
2020 PO4722488062	LGE	3	45 BRO	SP	CCA		V	8/19/2114	
2020 PO4720888051	LGE	4	40 BRO	SP	CCA		V	8/20/2114	
2020 PO4719788043	LGE	3	45 BRO	SP	CCA		V	8/21/2114	
2020 PO4718488015	LGE	3	45 BRO	SP	CCA		V	8/22/2114	
2020 PO4718788001	LGE	3	45 BRO	SP	CCA		V	8/23/2114	
2020 PO4718487990	LGE	4	30 BRO	SP	CCA	ED,ID	BD	8/24/2114	
2020 PO4719087986	LGE	3	45 BRO	SP	CCA		V	8/25/2114	
2020 PO4719487968	LGE	3	45 BRO	SP	CCA		V	8/26/2114	
2020 PO4719587963	LGE	3	45 BRO	SP	CCA		V	8/27/2114	
2020 PO4675288260	LGE	4	30 BRN	SP	A	ED,ID	T	8/28/2114	
2020 PO4674988265	LGE	4	40 BRN	SP	CRE	ED,ID,SRS	TX	RR	8/29/2114
2020 PO4637388266	LGE	4	40 BRO	SP	CRE	ED,ID	BD	8/30/2114	
2020 PO4636288222	LGE	4	40 BRO	SP	CRE	ED,HH,ID,RB	BX	PX	8/31/2114
2020 PO4637288229	LGE	3	45 BRO	SP	CCA		V	9/1/2114	
2020 PO4638288236	LGE	4	40 BRO	SP	CCA		V	9/2/2114	
2020 PO4639388244	LGE	4	40 BRO	SP	P	ED,ID	TD	9/3/2114	
2020 PO4674388274	LGE	4	45 BRN	SP	A	ED,ID	TD	9/4/2114	
2020 PO470060223	KU	4	40 OTH	SP	CCA		V	9/5/2114	
2020 PO4676359677	KU	4	40 OTH	SP	CCA		V	9/6/2114	
2020 PO4690159904	KU	4	40 OTH	SP	CCA		V	9/7/2114	
2020 PO4665859499	KU	4	40 OTH	SP	CCA		V	9/8/2114	
2020 PO5204713617	KU	4	40 BRO	SP	CRE	ID,IP	BD	9/9/2114	
2020 PO4673888282	LGE	4	40 BRN	SP	CRE	ED,ID	TD	9/10/2114	
2020 PO4673288290	LGE	4	45 BRN	SP	CRE	ED,ID	TD	9/11/2114	
2020 PO5171113706	KU	4	40 BRO	SP	CCA		V	9/12/2114	
2020 PO4719287949	LGE	4	35 BRO	SP	P	ED,ID,IP	BD	9/13/2114	
2020 PO4719887947	LGE	3	45 BRO	SP	CCA		V	9/14/2114	
2020 PO4720387925	LGE	3	45 BRO	SP	CCA		V	9/15/2114	
2020 PO4720487918	LGE	1	65 BRO	SP	CRE		V	9/16/2114	
2020 PO4734388147	LGE	3	45 BRO	SP	CCA		V	9/17/2114	
2020 PO4735988158	LGE	3	45 BRO	SP	CCA		V	9/18/2114	
2020 PO4470094406	LGE	3	45 BRO	SP	CCA		V	9/19/2114	
2020 PO5170713695	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/20/2114	
2020 PO5157713585	KU	4	40 BRO	SP	CRE		V	9/21/2114	
2020 PO5159313421	KU	4	40 BRO	SP	CRE		V	9/22/2114	
2020 PO5164813433	KU	5	35 BRO	SP	CRE		V	9/23/2114	
2020 PO4672788299	LGE	3	40 BRN	SP	A	ED,ID	BD	9/24/2114	
2020 PO4672288307	LGE	4	45 BRN	SP	CRE	ED,ID	TD	9/25/2114	
2020 PO4672588309	LGE	4	30 BRN	SP	A	ED,EP,ID,SRS	TX	RR	9/26/2114
2020 PO5201413542	KU	4	45 BRO	SP	P	ED	T	9/27/2114	
2020 PO7541540513	KU	4	40 OTH	SP	CRE	ID	TD	9/28/2114	

2020 PO4619688137	LGE	4	35 BRO	SP	CRE		V	9/29/2114	
2020 PO4619188083	LGE	4	35 BRO	SP	CRE		V	9/30/2114	
2020 PO4619188090	LGE	4	40 BRO	SP	CRE		V	10/1/2114	
2020 PO4619288100	LGE	4	35 BRO	SP	CRE		V	10/2/2114	
2020 PO4619488113	LGE	4	40 BRO	SP	CRE		V	10/3/2114	
2020 PO4619588124	LGE	4	40 BRO	SP	CRE		V	10/4/2114	
2020 PO4658488186	LGE	6	25 BRN	SP	A	ED,ID,SRS	TX	RR	10/5/2114
2020 PO4619788149	LGE	4	40 BRO	SP	CRE		V	10/6/2114	
2020 PO4619888161	LGE	4	40 BRO	SP	CRE		V	10/7/2114	
2020 PO4619988172	LGE	4	35 BRO	SP	CCA		V	10/8/2114	
2020 PO4620088183	LGE	4	40 BRO	SP	CRE		V	10/9/2114	
2020 PO4623288133	LGE	4	40 BRO	SP	CRE		V	10/10/2114	
2020 PO4624088107	LGE	3	45 BRO	SP	CCA		V	10/11/2114	
2020 PO4622888096	LGE	4	35 BRO	SP	CRE		V	10/12/2114	
2020 PO4655888169	LGE	4	35 BRN	SP	CCA		V	10/13/2114	
2020 PO4657288166	LGE	4	30 BRN	SP	CCA		V	10/14/2114	
2020 PO4656488161	LGE	4	35 BRN	SP	CCA		V	10/15/2114	
2020 PO4659088190	LGE	4	45 BRN	SP	A	ED,ID	BD	10/16/2114	
2020 PO4659688182	LGE	4	35 BRN	SP	S		V	10/17/2114	
2020 PO4659088178	LGE	4	30 BRN	SP	S		V	10/18/2114	
2020 PO4659688170	LGE	6	25 BRN	SP	A	ED,ID	BD	10/19/2114	
2020 PO4656988152	LGE	4	40 BRN	SP	A	ED,ID	BD	10/20/2114	
2020 PO4623688180	LGE	4	40 BRO	SP	CRE		V	10/21/2114	
2020 PO4623588170	LGE	4	40 BRO	SP	CRE		V	10/22/2114	
2020 PO4623488157	LGE	4	40 BRO	SP	CRE		V	10/23/2114	
2020 PO4623388145	LGE	4	40 BRO	SP	CRE		V	10/24/2114	
2020 PO4623088120	LGE	4	35 BRO	SP	CRE		V	10/25/2114	
2020 PO4623088109	LGE	3	45 BRO	SP	CCA		V	10/26/2114	
2020 PO4620488111	LGE	3	45 BRO	SP	CCA		V	10/27/2114	
2020 PO4622788086	LGE	4	40 BRO	SP	CRE		V	10/28/2114	
2020 PO4622688076	LGE	4	40 BRO	SP	CCA		V	10/29/2114	
2020 PO4657588143	LGE	4	35 BRN	SP	A	ED,ID	TD	10/30/2114	
2020 PO4660188161	LGE	6	25 BRN	SP	CRE	ED,ID	TD	10/31/2114	
2020 PO4605287902	LGE	4	40 BRO	SP	CRE	ED,ID	TD	11/1/2114	
2020 PO4660888154	LGE	6	25 BRN	SP	A	ED,HH,ID	BX	RR	11/2/2114
2020 PO4658188135	LGE	4	40 BRN	SP	P	ED,ID	BD	11/3/2114	
2020 PO7780539745	F	4	40 OTH	SP	CRE	HH,ID	BX	RP3	11/4/2114
2020 PO7699939547	F	4	40 OTH	SP	CRE		V	11/5/2114	
2020 PO7751039700	F	4	40 OTH	SP	P		V	11/6/2114	
2020 PO4658688127	LGE	4	40 BRN	SP	CCA		V	11/7/2114	
2020 PO4660688165	LGE	4	35 BRN	SP	A	ED,ID	BD	11/8/2114	
2020 PO4660188174	LGE	4	35 BRN	SP	CCA		V	11/9/2114	
2020 PO4661288157	LGE	4	40 BRN	SP	A	ED,ID	TD	11/10/2114	
2020 PO4617488002	F	4	30 BRO	SP	CRE		V	11/11/2114	
2020 PO4617088010	F	4	40 BRO	SP	CRE		V	11/12/2114	
2020 PO4616588017	F	3	45 BRO	SP	CCA		V	11/13/2114	
2020 PO4604788011	F	4	30 BRO	SP	CRE		V	11/14/2114	

2020 PO4604488017	F	4	35 BRO	SP	A		V	11/15/2114
2020 PO4605188017	F	3	50 BRO	SP	A		V	11/16/2114
2020 PO4604288031	F	3	45 BRO	SP	A		V	11/17/2114
2020 PO4661788149	LGE	4	40 BRN	SP	CCA		V	11/18/2114
2020 PO4661388145	LGE	6	25 BRN	SP	A	ED,ID	BD	11/19/2114
2020 PO0519437414	ODP	5	35 BRN	SP	CRE	ID	BD	11/20/2114
2020 PO0520437283	ODP	2	35 BRN	SP	CRE	ID	BD	11/21/2114
2020 PO5843512813	KU	4	40 XXX	SP	CRE	ED,ID	TD	11/22/2114
2020 PO5860813027	KU	5	40 XXX	SP	CRE	ED,ID	TD	11/23/2114
2020 PO4641289090	F	4	40 BRO	SP	CRE		V	11/24/2114
2020 PO4603988049	LGE	2	45 BRO	SP	CRE	ED,ID	TD	11/25/2114
2020 PV4604488028	F	3	50 BRO	SP	CCA		V	11/26/2114
2020 PO4604788035	LGE	2	55 BRO	SP	P	ED,ID	BD	11/27/2114
2020 PO4611287923	F	4	40 BRO	SP	CRE		V	11/28/2114
2020 PO4612087910	F	4	40 BRO	SP	CRE		V	11/29/2114
2020 PO4612887998	LGE	4	40 BRO	SP	CRE		V	11/30/2114
2020 PO4612987898	F	4	40 BRO	SP	CRE		V	12/1/2114
2020 PO4613687985	LGE	4	40 BRO	SP	CRE		V	12/2/2114
2020 PO4613687885	F	3	45 BRO	SP	A		V	12/3/2114
2020 PO4661188131	LGE	4	40 BRN	SP	A	ED,ID	TD	12/4/2114
2020 PO3715594082	LGE	4	30 BRN	SP	CCA		V	12/5/2114
2020 PO4659288118	LGE	4	40 BRN	SP	A	ED,ID	BD	12/6/2114
2020 PO4661988132	LGE	4	30 BRN	SP	A	ED,ID	TD	12/7/2114
2020 PO4662388140	LGE	4	40 BRN	SP	CCA		V	12/8/2114
2020 PO4660288120	LGE	4	35 BRN	SP	CCA		V	12/9/2114
2020 PO4660388111	LGE	4	30 BRN	SP	A	ED,ID	TD	12/10/2114
2020 PO0397737536A	ODP	4	35 BRN	SP	CRE	ID	BD	12/11/2114
2020 PO0418837515A	ODP	2	35 BRN	SP	CRE	ID	BD	12/12/2114
2020 PO0466337332A	ODP	2	35 BRN	SP	CRE	ID	BD	12/13/2114
2020 PO0407437806	ODP	4	45 BRN	SP	CCA		V	12/14/2114
2020 PO0496337332	ODP	2	35 BRN	SP	CRE	ID	BD	12/15/2114
2020 PO0397737536	ODP	2	50 BRN	SP	CCA		V	12/16/2114
2020 PO0472137393	ODP	2	35 BRN	SP	CRE	ID	BD	12/17/2114
2020 PO0418837515	ODP	2	35 BRN	SP	CRE	ID	BD	12/18/2114
2020 PO5856013452	KU	5	35 XXX	SP	CRE	ED,ID	TD	12/19/2114
2020 PO9468174452	KU	5	35 XXX	SP	CCA		V	12/20/2114
2020 PO9478774611	KU	3	35 XXX	SP	CRE	ID	BD	12/21/2114
2020 PO9470274568	KU	5	35 XXX	SP	CRE	ID,RB	X	12/22/2114
2020 PO3917067498	KU	2	65 XXX	SP	CRE		V	12/23/2114
2020 PO4816788375	LGE	4	30 BRO	SP	CRE	ED,EP,IP	TD	12/24/2114
2020 PO4816088392	LGE	4	40 BRO	SP	CRE	ED,ID	TD	12/25/2114
2020 PO4817088385	LGE	4	40 BRO	SP	CRE	ED	BD	12/26/2114
2020 PO4658388440	LGE	4	40 BRN	SP	CCA		V	12/27/2114
2020 PO4657688449	LGE	UNK	25 BRN	SP	CRE		V	12/28/2114
2020 PO4657588451	LGE	4	40 BRN	SP	A	ED,ID	BD	12/29/2114
2020 PO4660188412	LGE	4	40 BRN	SP	CRE	ED,ID	BD	12/30/2114
2020 PO9484074529	F	4	40 XXX	SP	CRE		V	12/31/2114

2020 PO9500774627	F	4	40 XXX	SP	A		V	1/1/2115	
2020 PO9519074730	F	4	40 XXX	SP	A		V	1/2/2115	
2020 PO9539674840	F	4	40 XXX	SP	A		V	1/3/2115	
2020 PO9562974959	F	4	40 XXX	SP	A		V	1/4/2115	
2020 PO9585575078	F	4	40 XXX	SP	A		V	1/5/2115	
2020 PO5652248435	KU	5	35 OTH	SP	CRE	ED,ID	BD	1/6/2115	
2020 PO4659488424	LGE	3	50 BRN	SP	CRE	ED,ID	BX	RP1	1/7/2115
2020 PO4664088400	LGE	4	40 BRN	SP	CCA		V	1/8/2115	
2020 PO4663188413	F	4	40 BRN	SP	CCA		V	1/9/2115	
2020 PO5718847972	KU	4	40 OTH	SP	CCA		V	1/10/2115	
2020 PO3935572060	KU	2	70 KOP	WC	CRE		V	1/11/2115	
2020 PO3941172062	KU	2	60 KOP	WC	CRE		V	1/12/2115	
2020 PO3932671530	KU	2	70 KOP	SP	CRE		V	1/13/2115	
2020 PO3939471524	KU	2	60 KOP	SP	CRE		V	1/14/2115	
2020 PO3936970869	KU	2	60 KOP	SP	S		V	1/15/2115	
2020 PO3931970871	KU	2	70 KOP	SP	CRE		V	1/16/2115	
2020 PO3917770633	KU	4	40 KOP	SP	S		V	1/17/2115	
2020 PO3929773662	KU	4	45 KOP	SP	CRE	ED,ID	TD	1/18/2115	
2020 PO3904373784	KU	4	45 KOP	SP	CRE	ED,ID	TD	1/19/2115	
2020 PO3943073605	KU	3	70 KOP	SP	CRE		V	1/20/2115	
2020 PO3945772755	KU	2	50 KOP	SP	CRE		V	1/21/2115	
2020 PO3938972757	KU	2	60 KOP	DF	CRE		V	1/22/2115	
2020 PO3940873164	KU	3	70 KOP	SP	CRE		V	1/23/2115	
2020 PO3944772766	KU	4	40 KOP	SP	S		V	1/24/2115	
2020 PO3968672754	KU	4	40 KOP	SP	S		V	1/25/2115	
2020 PO3991372755	KU	4	40 KOP	SP	S		V	1/26/2115	
2020 PO4197986351	KU	4	40 KOP	SP	CRE	ID	BD	1/27/2115	
2020 PO4216085954	KU	4	45 KOP	SP	CRE	ID	BD	1/28/2115	
2020 PO3810886425	KU	4	40 KOP	SP	CRE		V	1/29/2115	
2020 PO3796186254	KU	4	40 KOP	SP	CRE	ID	BD	1/30/2115	
2020 PO4168690193	KU	1	70 KOP	SP	CRE		V	1/31/2115	
2020 PO4174489966	KU	1	70 KOP	SP	CRE		V	2/1/2115	
2020 PO4284389920	KU	6	30 KOP	SP	S		V	2/2/2115	
2020 PO4248891707	KU	2	50 KOP	SP	S		V	2/3/2115	
2020 PO4346591713	F	4	40 KOP	SP	CRE		V	2/4/2115	
2020 PO4575091974	KU	5	35 KOP	SP	S		V	2/5/2115	
2020 PO3926240569	KU	4	35 BRO	SP	CRE	ED,ID,IP	TD	2/6/2115	
2020 PO3933040680	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	2/7/2115	
2020 PO3906840251-A	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD	2/8/2115	
2020 PO4814888391	LGE	4	40 BRO	SP	CRE	ED	TD	2/9/2115	
2020 PO3942840512	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	2/10/2115	
2020 PO3952240480	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	2/11/2115	
2020 PO3962640444	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	2/12/2115	
2020 PO3938240765	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	2/13/2115	
2020 PO3945640885	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	2/14/2115	
2020 PO4825887839	LGE	4	40 BRO	SP	CCA		V	2/15/2115	
2020 PO4825487814	LGE	4	40 BRO	SP	CRE	ED	TD	2/16/2115	

2020 PO4823087812	LGE	UNK	90 BRO	ST	P		V			2/17/2115
2020 PO4825487809	LGE	UNK	95 BRO	ST	P		V			2/18/2115
2020 PO3953298242	LGE		4 35 BRN	SP	P		T			2/19/2115
2020 PO3964998232	LGE		4 35 BRN	SP	P		T			2/20/2115
2020 PO4162790440	KU		1 70 KOP	SP	CRE		V			2/21/2115
2020 PO4108790554	KU		6 30 KOP	SP	S		V			2/22/2115
2020 PO4105190741	KU		4 40 KOP	SP	S		V			2/23/2115
2020 PO4090690797	KU		4 40 KOP	SP	S		V			2/24/2115
2020 PO4085590818	KU		4 40 KOP	SP	CCA	ID	BD			2/25/2115
2020 PO4114990530	KU		4 40 KOP	SP	CRE	ED,ID	TD			2/26/2115
2020 PO4124290324	KU		4 40 KOP	SP	S		V			2/27/2115
2020 PO4155890421	KU		4 40 KOP	SP	S		V			2/28/2115
2020 PO7952558530	KU		2 60 BRN	SP	CCA		V			3/1/2115
2020 PO3401197367	LGE		1 55 BRN	SP	CCA		V			3/2/2115
2020 PO6669444598	KU		4 40 OTH	SP	CRE	ED,HH,SRS	TD			3/3/2115
2020 PO4808088279	LGE		3 45 BRO	SP	CRE	ED,HH,ID,RB	BX	RP2		3/4/2115
2020 PO4634388487	LGE		4 40 BRN	SP	A		V			3/5/2115
2020 PO3421097519	LGE		4 35 BRN	SP	CCA		V			3/6/2115
2020 PO3423397443	LGE		1 55 BRN	SP	CCA		V			3/7/2115
2020 PO3434597469	LGE		1 55 BRN	SP	CCA		V			3/8/2115
2020 PO3451997572	LGE		1 55 BRN	SP	CCA		V			3/9/2115
2020 PO6655344228	KU		4 40 OTH	SP	CRE	ED,SRS	TD			3/10/2115
2020 PO6655343890	KU		4 45 OTH	SP	CRE	ED,SRS	TD			3/11/2115
2020 PO6734643571	KU		4 40 OTH	SP	CRE		V			3/12/2115
2020 PO6697143393	KU		4 40 OTH	SP	CRE	ED,SRS	TD			3/13/2115
2020 PO6674943492	KU		4 45 OTH	SP	CCA		V			3/14/2115
2020 PO6655843568	KU		4 40 OTH	SP	CRE	ED,SRS	TD			3/15/2115
2020 PO9759375601	KU		4 45 XXX	SP	CRE	ID	TD			3/16/2115
2020 PO9778975613	KU		4 45 XXX	SP	CRE	ID	TD			3/17/2115
2020 PO9798775625	KU		4 45 XXX	SP	CRE	ID	TD			3/18/2115
2020 PO9806175646	KU		5 35 XXX	SP	P	ED	T			3/19/2115
2020 PO9626475312	F		4 40 XXX	SP	CCA		V			3/20/2115
2020 PO4641188533	LGE		1 65 BRN	SP	PENTA		V			3/21/2115
2020 PO4639888523	LGE		1 60 BRN	SP	A		V			3/22/2115
2020 PO4638288513	LGE		3 50 BRN	SP	CCA		V			3/23/2115
2020 PO4640488503	LGE		6 25 BRN	SP	CRE		V			3/24/2115
2020 PO4639288494	LGE		4 35 BRN	SP	CCA		V			3/25/2115
2020 PO3499797845	LGE		1 50 BRN	SP	CCA		V			3/26/2115
2020 PO3495398712	LGE		1 50 BRN	SP	CCA		V			3/27/2115
2020 PO3481297732	LGE		1 50 BRN	SP	CCA		V			3/28/2115
2020 PO3987240359	KU		4 35 BRO	SP	CRE	ED,ID,IP	TD			3/29/2115
2020 PO4819188515	LGE		3 45 BRO	SP	CRE	ED	TD			3/30/2115
2020 PO3982240204	KU		4 40 BRO	SP	P	ED	T			3/31/2115
2020 PO4828088232	LGE		3 45 BRO	SP	CCA		V			4/1/2115
2020 PO4829088202	LGE		3 45 BRO	SP	CCA		V			4/2/2115
2020 PO4828788212	LGE		3 45 BRO	SP	CCA		V			4/3/2115
2020 PO4829788180	LGE	UNK	45 BRO	SP	CRE	ED	TD			4/4/2115

2020 PO4830388163	LGE	UNK	60	BRO	SP	CRE	ED	TD	4/5/2115
2020 PO3977640061	KU	4	40	BRO	SP	CRE	ED,ID,IP	TD	4/6/2115
2020 PO3465197621	LGE	1	55	BRN	SP	CCA		V	4/7/2115
2020 PO6719143302	KU	3	45	OTH	SP	CRE	ED,SRS	TD	4/8/2115
2020 PO6827642729	KU	4	40	OTH	SP	CRE	ED,SRS	TD	4/9/2115
2020 PO6741843201	KU	4	40	OTH	SP	CCA		V	4/10/2115
2020 PO6772643073	KU	4	40	OTH	SP	CRE	ED,SRS	TD	4/11/2115
2020 PO6801942952	KU	3	45	OTH	SP	CCA		V	4/12/2115
2020 PO3974539966	KU	4	40	BRO	SP	CRE	ED,ID,IP	TD	4/13/2115
2020 PO3954540030	KU	3	45	BRO	SP	CRE	ED,ID,IP	TD	4/14/2115
2020 PO4831688124	LGE	1	50	BRO	SP	CCA		V	4/15/2115
2020 PO4830588145	LGE	UNK	25	BRO	SP	CRE		V	4/16/2115
2020 PO4831388131	LGE	1	50	BRO	SP	CCA		V	4/17/2115
2020 PO4830888147	LGE	1	55	BRO	SP	CCA		V	4/18/2115
2020 PO4829288135	LGE	4	40	BRO	SP	CRE	ED	TD	4/19/2115
2020 PO4828188150	LGE	4	40	BRO	SP	CRE	ED	BD	4/20/2115
2020 PO4831588066	LGE	3	45	BRO	SP	CRE	ED	TD	4/21/2115
2020 PO4832288063	LGE	4	30	BRO	SP	CRE	ED	TD	4/22/2115
2020 PO4830088050	LGE	3	45	BRO	SP	CCA		V	4/23/2115
2020 PO4832288106	LGE	3	45	BRO	SP	CCA		V	4/24/2115
2020 PO4833088082	LGE	1	55	BRO	SP	CCA		V	4/25/2115
2020 PO5431693810	LGE	1	50	BRO	SP	CCA		V	4/26/2115
2020 PO3935739883	KU	4	40	BRO	SP	CRE	ED,ID,IP	TD	4/27/2115
2020 PO3943140066	KU	4	40	BRO	SP	CCA		V	4/28/2115
2020 PO4791588252	LGE	4	40	BRN	SP	A	ED,ID	BD	4/29/2115
2020 PO3985175860	KU	3	45	BRN	SP	CCA		V	4/30/2115
2020 PO3934876511	KU	2	50	KOP	SP	CRE		V	5/1/2115
2020 PO3930176508	KU	2	60	KOP	ST	CRE		V	5/2/2115
2020 PO3930177106	KU	2	65	KOP	DF	CRE		V	5/3/2115
2020 PO3935077105	KU	2	55	KOP	SP	CRE		V	5/4/2115
2020 PO3929177698	KU	2	55	KOP	SP	CRE		V	5/5/2115
2020 PO3934777700	KU	2	55	KOP	DF	CRE		V	5/6/2115
2020 PO4038478297	KU	4	40	KOP	SP	CRE		V	5/7/2115
2020 PO4038878247	KU	4	40	KOP	SP	CRE		V	5/8/2115
2020 PO4027678142	KU	4	40	KOP	SP	CRE		V	5/9/2115
2020 PO4028178095	KU	4	40	KOP	SP	CRE		V	5/10/2115
2020 PO3956678087	KU	H1	85	KOP	SP	CRE		V	5/11/2115
2020 PO3956478150	KU	H1	85	KOP	SP	CRE		V	5/12/2115
2020 PO3934078664	KU	2	70	KOP	SP	CRE		V	5/13/2115
2020 PO3977875728	KU	4	40	BRN	SP	CCA		V	5/14/2115
2020 PO4830287794	F	4	35	BRO	SP	CCA		V	5/15/2115
2020 PO3953875722	KU	4	40	BRN	SP	CCA		V	5/16/2115
2020 PO3936475828	KU	2	55	BRN	SP	CRE		V	5/17/2115
2020 PO3941075730	KU	4	40	BRN	SP	CCA		V	5/18/2115
2020 PO3936475828	KU	2	50E	BRN	SP	CRE		V	5/19/2115
2020 PO3931875826	KU	2	65	BRN	SP	CCA		V	5/20/2115
2020 PO4793488269	LGE	4	40	BRN	SP	CRE	ED,ID	BD	5/21/2115

2020 PO4795088248	LGE	4	30 BRN	SP	A	ED,ID	BD	5/22/2115
2020 PO4795288242	LGE	4	30 BRN	SP	CRE	ED,ID	BD	5/23/2115
2020 PO1978186669	KU	4	40 OTH	SP	CRE	ED,SRS	TD	5/24/2115
2020 PO1991286678	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	5/25/2115
2020 PO1995386683	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	5/26/2115
2020 PO1978886523	KU	4	40 OTH	SP	CRE	ED,SRS	TD	5/27/2115
2020 PO4678688836	LGE	4	40 BRO	SP	CRE	ID,IP	BD	5/28/2115
2020 PO4679888821	LGE	4	40 BRO	SP	CRE	ID,IP	BD	5/29/2115
2020 PO4654888918	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	5/30/2115
2020 PO4817187707	LGE	4	30 BRO	SP	CRE	ED	BD	5/31/2115
2020 PO9398372961	KU	4	40 XXX	SP	CRE	ID	TD	6/1/2115
2020 PO4795888224	LGE	4	30 BRN	SP	A	ED,ID	TD	6/2/2115
2020 PO4795788230	LGE	4	35 BRN	SP	A	ED,ID	BD	6/3/2115
2020 PO4795588206	LGE	4	30 BRN	SP	A	ED,ID	BD	6/4/2115
2020 PO4817487721	LGE	4	40 BRO	SP	CCA		V	6/5/2115
2020 PO290057979-A	F	4	45 OTH	SP	CRE		V	6/6/2115
2020 PO1967785736	KU	3	45 OTH	SP	P	ED,SRS	TD	6/7/2115
2020 PO1980486297	KU	2	50 OTH	SP	CRE	ED,ID,IP	TD	6/8/2115
2020 PO1983685915	KU	4	45 OTH	SP	CRE	ED,SRS	TD	6/9/2115
2020 PO4814987812	F	3	50 BRO	SP	CRE		V	6/10/2115
2020 PO4813487795	LGE	4	40 BRO	SP	CCA		V	6/11/2115
2020 PO4813687813	F	3	50 BRO	SP	CRE		V	6/12/2115
2020 PO4810387818	F	3	50 BRO	SP	CRE	ED	V	6/13/2115
2020 PO4808387820	F	4	30 BRO	SP	CRE		V	6/14/2115
2020 PO4812487795	LGE	UNK	45 BRO	SP	CRE		V	6/15/2115
2020 PO4811587810	LGE	3	45 BRO	SP	CCA		V	6/16/2115
2020 PO4811987816	F	3	50 BRO	SP	CCA		V	6/17/2115
2020 PO8205063929	KU	5	35 BRN	SP	CRE		V	6/18/2115
2020 PO8212163990	KU	5	35 BRN	SP	CRE		V	6/19/2115
2020 PO4659588940	LGE	4	40 BRO	SP	CCA		V	6/20/2115
2020 PO4794988189	LGE	4	35 BRN	SP	A	ED,ID	BD	6/21/2115
2020 PO4657288885	LGE	4	40 BRO	SP	CCA		V	6/22/2115
2020 PO4658288890	LGE	4	40 BRO	SP	A	ID	BD	6/23/2115
2020 PO4658188892	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	6/24/2115
2020 PO9409772786	KU	4	40 XXX	SP	CRE	ID	TD	6/25/2115
2020 PO4800887827	LGE	3	50 BRO	SP	CCA		V	6/26/2115
2020 PO9418572770	KU	6	30 XXX	SP	CRE	ID	TD	6/27/2115
2020 PO4000882417	KU	4	40 KOP	SP	CRE		B	6/28/2115
2020 PO3970782341	KU	4	40 KOP	SP	CRE	ID	BD	6/29/2115
2020 PO3936779729	KU	2	70 KOP	ST	CRE		V	6/30/2115
2020 PO3940579730	KU	2	60 KOP	ST	CCA		V	7/1/2115
2020 PO3937880025	KU	2	65 KOP	SP	CRE		V	7/2/2115
2020 PO3939180360	KU	3	70 KOP	SP	CRE		V	7/3/2115
2020 PO3941280796	KU	2	65 KOP	SP	CRE		V	7/4/2115
2020 PO3943181229	KU	3	60 KOP	SP	CRE		V	7/5/2115
2020 PO3945581656	KU	3	60 KOP	SP	CRE		V	7/6/2115
2020 PO3948382233	KU	3	55 KOP	SP	CRE		V	7/7/2115

2020 PO3952082235	KU		3	45 KOP	SP	CRE		V	7/8/2115	
2020 PO41957 90845	KU		3	45 KOP	SP	S		V	7/9/2115	
2020 PO4139890824	KU		4	40 KOP	SP	CRE	ID	BD	7/10/2115	
2020 PO4178490534	KU		4	40 KOP	SP	S		V	7/11/2115	
2020 PO4161390492	KU		2	45 KOP	SP	CRE		V	7/12/2115	
2020 PO4794187843	LGE	UNK		60 BRO	SP	CRE	ED,EP	BD	7/13/2115	
2020 PO4793887844	LGE	UNK		20 BRO	SP	CRE	ED	V	7/14/2115	
2020 PO4656888881	F		4	40 BRO	SP	CCA		V	7/15/2115	
2020 PO9420972866	KU		3	45 XXX	SP	CCA		V	7/16/2115	
2020 PO9425072800	KU		6	30 XXX	SP	CRE	ID	TD	7/17/2115	
2020 PO9468072997A	KU		6	30 XXX	SP	CCA		V	7/18/2115	
2020 PO4653988923	F		4	30 BRO	SP	A		V	7/19/2115	
2020 PV4653288931	F		4	40 BRO	SP	A		V	7/20/2115	
2020 PO4791087809	LGE	UNK		45 BRO	SP	CRE	ED	BD	7/21/2115	
2020 PO4791087804	LGE	UNK		95 BRO	SP	CRE		V	7/22/2115	
2020 PO4654488915	F		4	40 BRO	SP	CCA		V	7/23/2115	
2020 PO6374744850	KU		4	45 OTH	SP	CRE	ED,SRS	TD	7/24/2115	
2020 PO6501744252	KU		4	40 OTH	SP	CRE	ED,SRS	TD	7/25/2115	
2020 PO6469544402	KU		4	40 OTH	SP	CRE	ED,SRS	TD	7/26/2115	
2020 PO6406344701	KU		5	35 OTH	SP	CRE	ED,SRS	TD	7/27/2115	
2020 PO6533144112	KU		4	40 OTH	SP	CRE	ED,ID,IP,SRC	TD	7/28/2115	
2020 PO6438244547	KU		4	40 OTH	SP	CRE	ED,SRS	TD	7/29/2115	
2020 PO4793687835	F		4	35 BRO	SP	CRE		V	7/30/2115	
2020 PO4792987836	F		3	45 BRO	SP	CRE		V	7/31/2115	
2020 PO4792587836	F		4	40 BRO	SP	CCA		V	8/1/2115	
2020 PO4790687847	LGE		3	50 BRO	SP	CRE	ED	TX	RR	8/2/2115
2020 PO4790287839	LGE		3	50 BRO	SP	CRE	ED	TD		8/3/2115
2020 PO4789087841	F		3	50 BRO	SP	CRE		V		8/4/2115
2020 PO4787887842	F	UNK		45 BRO	SP	CRE		V		8/5/2115
2020 PO4791887837	F	UNK		45 BRO	SP	CCA		V		8/6/2115
2020 PO4655888902	LGE		4	35 BRO	SP	CRE	ED,ID,IP	TD		8/7/2115
2020 PO9460272963	KU		4	40 XXX	SP	CRE	ID	TD		8/8/2115
2020 PO9468072997	KU		5	30 XXX	SP	CRE	ID	TD		8/9/2115
2020 PO4657688914	LGE		4	35 BRO	SP	CCA		V		8/10/2115
2020 PO9435372974	KU		4	45 XXX	SP	CRE	ID	TD		8/11/2115
2020 PO9453273104	KU		4	45 XXX	SP	CRE	ID	TD		8/12/2115
2020 PO9473973308	F		4	40 XXX	SP	A		V		8/13/2115
2020 PO9457573192	F		4	40 XXX	SP	A		V		8/14/2115
2020 PO4784687846	F		3	45 BRO	SP	CRE		V		8/15/2115
2020 PO4786587844	F		3	45 BRO	SP	CCA		V		8/16/2115
2020 PO4783187848	F		3	45 BRO	SP	CRE		V		8/17/2115
2020 PO4782187849	F		3	50 BRO	SP	CCA		V		8/18/2115
2020 PO4782987848	F		4	35 BRO	SP	CRE		V		8/19/2115
2020 PO4782887848	F	UNK		20 BRO	SP	CRE		V		8/20/2115
2020 PO4927691328	LGE		4	35 BRO	SP	CCA		V		8/21/2115
2020 PO4782087834	LGE		4	35 BRO	SP	CCA		V		8/22/2115
2020 PO4794688177	LGE		4	35 BRN	SP	A	ED,ID,SRC	TX	RR	8/23/2115

2020 PO4794388169	LGE	4	35 BRN	SP	A	ED,ID	BD	8/24/2115
2020 PO4794088168	LGE	4	40 BRN	SP	CRE	ED,ID	TD	8/25/2115
2020 PO4793588187	LGE	4	45 BRN	SP	A	ED,ID	BD	8/26/2115
2020 PO4669288798	LGE	4	40 BRO	SP	CCA		V	8/27/2115
2020 PO4668888815	LGE	4	40 BRO	SP	CCA		V	8/28/2115
2020 PO4666488803	LGE	4	40 BRO	SP	CCA		V	8/29/2115
2020 PO3956791088	F	4	40 KOP	SP	CRE		V	8/30/2115
2020 PO3952791047	KU	5	35 KOP	SP	S		V	8/31/2115
2020 PO3941791057	F	4	40 KOP	SP	CRE		V	9/1/2115
2020 PO3942491468	F	4	40 KOP	SP	CRE		V	9/2/2115
2020 PO5875412972	F	4	40 XXX	SP	CRE		V	9/3/2115
2020 PO5826012232	KU	5	40 XXX	SP	CRE	ID	BD	9/4/2115
2020 PO6223819079	KU	3	50 XXX	SP	CCA		V	9/5/2115
2020 PO6213219399	KU	4	45 XXX	SP	CRE	ED,ID	TD	9/6/2115
2020 PO6196519821	KU	4	40 XXX	SP	CRE	ED,ID	TD	9/7/2115
2020 PO6163419765	KU	4	40 XXX	SP	CCA		V	9/8/2115
2020 PO6176419986	KU	2	40 XXX	SP	CRE	ED,ID	TD	9/9/2115
2020 PO4706388389	LGE	4	40 BRN	SP	CRE	ED,ID	BD	9/10/2115
2020 PO4707088379	LGE	3	45 BRN	SP	A	ED,ID	BD	9/11/2115
2020 PO4707688371	LGE	4	40 BRN	SP	CRE	ED,ID	BD	9/12/2115
2020 PO3938191450	F	4	40 KOP	SP	CRE		VX	9/13/2115
2020 PO4663788883	LGE	4	40 BRO	SP	P	ED	T	9/14/2115
2020 PO4663988879	LGE	4	40 BRO	SP	A	ED	TD	9/15/2115
2020 PO4661288914	LGE	4	40 BRO	SP	CRE	ID,IP	BD	9/16/2115
2020 PO4662888926	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/17/2115
2020 PO4665288895	LGE	4	40 BRO	SP	P	ED	T	9/18/2115
2020 PO4644089042	LGE	4	40 BRO	SP	A		V	9/19/2115
2020 PO4684188585	LGE	4	40 BRN	SP	CCA		V	9/20/2115
2020 PO4685188592	LGE	4	35 BRN	SP	CRE	ED,ID	BD	9/21/2115
2020 PO4686188599	LGE	4	35 BRN	SP	CCA		V	9/22/2115
2020 PO4687888595	LGE	4	35 BRN	SP	CRE	ED,ID	TD	9/23/2115
2020 PO4687088606	LGE	4	40 BRN	SP	CRE	ED,ID	BD	9/24/2115
2020 PO9311772388	KU	5	35 OTH	SP	CRE	ED,ID,SRS	TD	9/25/2115
2020 PO9318572291	KU	5	40 OTH	SP	CRE	ED,ID,IP,SRC	TD	9/26/2115
2020 PO9300672484	KU	3	40 OTH	SP	CRE	ED,EP,ID,IP,SRC	TD	9/27/2115
2020 PO4687488610	LGE	4	45 BRN	SP	CRE	ED,ID	BD	9/28/2115
2020 PO4688588617	LGE	4	35 BRN	SP	CRE	ED,ID	BD	9/29/2115
2020 PO4689788626	LGE	4	35 BRN	SP	A	ED,ID	BD	9/30/2115
2020 PO4690888635	LGE	4	35 BRN	SP	A	ED,ID	BD	10/1/2115
2020 PO4535991158	KU	4	40 KOP	SP	CRE	ED,ID	TD	10/2/2115
2020 PO4709988482	LGE	4	40 BRN	SP	A	ED,ID	BD	10/3/2115
2020 PO4708888478	LGE	3	45 BRN	SP	CCA		V	10/4/2115
2020 PO4708088475	LGE	3	45 BRN	SP	CCA		V	10/5/2115
2020 PO4706788470	LGE	3	45 BRN	SP	CCA		V	10/6/2115
2020 PO4705788467	LGE	3	50 CAH	SP	CRE	ED,ID	BD	10/7/2115
2020 PO4704688462	LGE	3	50 CAH	SP	CCA		V	10/8/2115
2020 PO4703488458	LGE	3	50 CAH	SP	CRE	ED,ID	BD	10/9/2115

2020 PO4702388454	LGE	2	55 CAH	SP	CCA		V	10/10/2115
2020 PO4704688468	LGE	4	30 CAH	SP	CCA		V	10/11/2115
2020 PO9339472583	KU	5E	40E	OTH	SP	CRE	ED,ID,IP,SRS	TD
2020 PO9327872500	KU	4	40 OTH	SP	CRE		ED,ID,SRS	TD
2020 PO9339872333	KU	3	45 OTH	SP	CCA		V	10/14/2115
2020 PO9342372295	KU	4	40 OTH	SP	CRE		ED,ID,SR	TX
2020 PO9334572240	KU	3	35 OTH	SP	CRE		ED,ID,SR	TX
2020 PO4804588203	LGE	UNK	45 BRO	SP	CRE		ED	TD
2020 PO4804088189	LGE	4	35 BRO	SP	CRE		ED	BD
2020 PO4805888213	LGE	4	40 BRO	SP	CRE		ED	TD
2020 PO4806688223	LGE	4	40 BRO	SP	CRE		ED	T
2020 PO4701088450	LGE	3	55 CAH	SP	CRE		ED,ID	BD
2020 PO4700288446	LGE	3	55 BRN	SP	CRE		ED,ID	BD
2020 PO4699388443	LGE	3	55 BRN	SP	CCA		V	10/23/2115
2020 PO4178890496	KU	4	40 KOP	SP	S		V	10/24/2115
2020 PO4187590519	KU	1	70 KOP	SP	CRE		V	10/25/2115
2020 PO4232490644	KU	1	70 KOP	SP	CRE		V	10/26/2115
2020 PO4211290590	KU	1	70 KOP	SP	CRE		V	10/27/2115
2020 PO4223190888	KU	1	70 KOP	SP	CRE		V	10/28/2115
2020 PO4210191193	KU	1	70 KOP	SP	CRE		V	10/29/2115
2020 PO4215491070	KU	1	70 KOP	SP	CRE		V	10/30/2115
2020 PO4200391449	KU	1	70 KOP	SP	CRE		V	10/31/2115
2020 PO4189591713	KU	1	70 KOP	SP	CRE		V	11/1/2115
2020 PO4184991826	KU	1	70 KOP	SP	CRE		V	11/2/2115
2020 PO4181992113	KU	4	25 KOP	SP	S		V	11/3/2115
2020 PO4169592167	KU	5	35 KOP	SP	S		V	11/4/2115
2020 PO4182092178	KU	3	45 KOP	SP	S		V	11/5/2115
2020 PO4175292355	KU	3	50 KOP	SP	S		V	11/6/2115
2020 PO4168692184	KU	3	45 KOP	SP	S		V	11/7/2115
2020 PO4164392237	KU	3	45 KOP	SP	S		V	11/8/2115
2020 PO4161292315	KU	3	45 KOP	SP	S		V	11/9/2115
2020 PO4807188230	LGE	4	40 BRO	SP	CRE		ED	TD
2020 PO4807688236	LGE	4	40 BRO	SP	CRE		ED,ID,IP	TD
2020 PO4808688248	LGE	4	40 BRO	SP	CRE		ED	V
2020 PO4698388439	LGE	3	50 BRN	SP	CCA		V	11/13/2115
2020 PO4697188435	LGE	3	50 BRN	SP	CRE		ED,ID	BD
2020 PO4696088431	LGE	3	50 BRN	SP	CCA		V	11/15/2115
2020 PO4694988427	LGE	3	50 BRN	SP	CRE		ED,ID	BD
2020 PO4809588258	LGE	4	40 BRO	SP	CRE		ED	TD
2020 PO4809488271	LGE	4	40 BRO	SP	CRE		ED	TD
2020 PO4811188279	LGE	4	40 BRO	SP	CRE		ED	TD
2020 PO7087515815	KU	5	30 XXX	SP	CRE		ED,ID	TD
2020 PO7084915716	KU	4	40 BRN	SP	CRE		ED,ID	TD
2020 PO7071215143	KU	4	40 BRN	SP	CCA		V	11/22/2115
2020 PO7072314897	KU	4	40 BRN	SP	CCA		V	11/23/2115
2020 PO7072414715	KU	4	40 BRN	SP	CCA		V	11/24/2115
2020 PO7045515588	KU	4	40 XXX	SP	CRE		ED,ID	TD

2020 PO3596297994	LGE	1	50 BRN	SP	CCA			V				11/26/2115	
2020 PO4650388530	LGE	3	50 BRN	SP	CCA			V				11/27/2115	
2020 PO4651488536	LGE	3	50 BRN	SP	CCA			V				11/28/2115	
2020 PO4650988532	LGE	3	50 BRN	SP	CCA			V				11/29/2115	
2020 PO4144292398	KU	6	25 KOP	SP	CRE				ED,ID			11/30/2115	
2020 PO4138492401	KU	4	40 KOP	SP	CRE				ED,ID			12/1/2115	
2020 PO4145892515	F	4	40 KOP	SP	CRE			V				12/2/2115	
2020 PO4135192511	F	4	40 KOP	SP	CRE			V				12/3/2115	
2020 PO4118792455	F	4	40 KOP	DF	CRE			V				12/4/2115	
2020 PO4099492412	F	4	40 KOP	SP	CRE			V				12/5/2115	
2020 PO4810288313	LGE	4	30 BRO	SP	CRE				ED			12/6/2115	
2020 PO3761497052	LGE	4	40 BRN	SP	CCA			V				12/7/2115	
2020 PO4809288296	LGE	4	40 BRO	SP	CRE				ED			12/8/2115	
2020 PO4807788309	LGE	4	40 BRO	SP	CRE				ED			12/9/2115	
2020 PO4809288312	LGE	3	45 BRO	SP	CCA			V				12/10/2115	
2020 PO4082192378	F	4	40 KOP	SP	CRE			V				12/11/2115	
2020 PO4088792481	KU	5	35 KOP	SP	S			V				12/12/2115	
2020 PO4081592525	F	4	40 KOP	DF	CRE			V				12/13/2115	
2020 PO4063892340	F	4	40 KOP	DF	CRE			V				12/14/2115	
2020 PO4049492307	F	4	40 KOP	DF	CRE				RB		BX	PX	12/15/2115
2020 PO4056392318	KU	5	35 KOP	SP	S			V					12/16/2115
2020 PO4060292410	KU	6	30 KOP	SP	S			V					12/17/2115
2020 PO4084592263	KU	4	45 KOP	SP	S			V					12/18/2115
2020 PO4085292224	F	4	40 KOP	SP	CRE			V					12/19/2115
2020 PO4081092146	F	5	25 KOP	SP	A			V					12/20/2115
2020 PO4656488630	LGE	3	45 BRN	SP	P							T	12/21/2115
2020 PO4808088316	LGE	4	35 BRO	SP	CRE				ED			TD	12/22/2115
2020 PO4808988326	LGE	4	40 BRO	SP	CRE				ED			TD	12/23/2115
2020 PO4810188333	LGE	4	30 BRO	SP	CRE				ED			TD	12/24/2115
2020 PO4656388625	LGE	3	45 BRN	SP	P							T	12/25/2115
2020 PO4809488335	LGE	4	40 BRO	SP	CRE				ED			TD	12/26/2115
2020 PO4807488352	LGE	4	40 BRO	SP	CRE				ED			TD	12/27/2115
2020 PO4808088353	LGE	4	30 BRO	SP	CRE				ED			TD	12/28/2115
2020 PO4835587997	LGE	4	40 BRO	SP	CRE				ED			BD	12/29/2115
2020 PO4834888017	LGE	4	40 BRO	SP	CRE				ED			TD	12/30/2115
2020 PO4835188013	LGE	4	40 BRO	SP	CRE				ED			BD	12/31/2115
2020 PO4827888035	F	4	30 BRO	SP	CRE			V					1/1/2116
2020 PO4828688032	LGE	4	35 BRO	SP	CCA			V					1/2/2116
2020 PO4828088033	F	4	30 BRO	SP	CRE			V					1/3/2116
2020 PO8867569534	KU	4	40 OTH	SP	CCA			V					1/4/2116
2020 PO8860869479	KU	4	40 OTH	SP	CCA			V					1/5/2116
2020 PO8876569571	F	3	45 OTH	SP	CCA			V					1/6/2116
2020 PO8861169451	F	3	45 OTH	SP	CCA			V					1/7/2116
2020 PO8848369352	F	3	45 OTH	SP	CCA			V					1/8/2116
2020 PO8834269133	KU	1	20 OTH	AL	A			V					1/9/2116
2020 PO8810869053	KU	3	45 OTH	SP	CCA			V					1/10/2116
2020 PO8800968953	KU	3	50 OTH	SP	CCA			V					1/11/2116

2020 PO9301972007	KU	5	35 OTH	SP	CRE	ED,ID,SRC	TX	RR	1/12/2116
2020 PO4689088486	LGE	4	30 BRN	SP	CRE	ED,ID	BD		1/13/2116
2020 PO4688688485	F	3	45 BRN	SP	A		V		1/14/2116
2020 PO4182187370	KU	4	40 KOP	DF	CRE	ED,ID	TD		1/15/2116
2020 PO4160087397	KU	6	30 KOP	SP	CRE	ED,ID	TD		1/16/2116
2020 PO4163987079	KU	4	45 KOP	SP	CRE	ED,ID	TD		1/17/2116
2020 PO4687488493	LGE	3	45 BRN	SP	CCA		V		1/18/2116
2020 PO4688388480	F	3	45 BRN	SP	A		V		1/19/2116
2020 PO4688288482	F	3	45 BRN	SP	A		V		1/20/2116
2020 PO017777354	KU	4	45 XXX	SP	CRE	ED,ID	TD		1/21/2116
2020 PO4687688478	F	4	40 BRN	SP	CRE		V		1/22/2116
2020 PO4689388475	LGE	4	30 BRN	DF	A	ED,ID	TD		1/23/2116
2020 PO4689188474	F	3	45 BRN	SP	A		V		1/24/2116
2020 PO4689888462	F	3	50 BRN	SP	A		V		1/25/2116
2020 PO4690688467	LGE	4	35 BRN	SP	CCA		V		1/26/2116
2020 PO3999297410	LGE	3	45 BRN	SP	CCA		V		1/27/2116
2020 PO4690188464	LGE	4	40 BRN	SP	A	ED,ID	BD		1/28/2116
2020 0166877294a	KU	4	40 XXX	SP	CCA		V		1/29/2116
2020 PO4823987992	LGE	4	30 BRO	SP	CRE	EP	TD		1/30/2116
2020 PO4824287988	LGE	4	40 BRO	SP	CRE	EP,HH	TD		1/31/2116
2020 PO4824487987	LGE	3	50 BRO	SP	CRE	ED	TD		2/1/2116
2020 PO4824787978	LGE	4	35 BRO	SP	CRE	ED	BD		2/2/2116
2020 PO4826288001	LGE	4	30 BRO	SP	CRE	ED,EP,ID	TD		2/3/2116
2020 PO4825888003	LGE	1	50 BRO	SP	CCA		V		2/4/2116
2020 PO4824388015	LGE	4	35 BRO	SP	P	HH,IP	TD		2/5/2116
2020 PO4821487985	LGE	4	40 BRO	SP	CRE	ED	BD		2/6/2116
2020 PO4823087971	LGE	3	50 BRO	SP	CRE	ED,EP	BD		2/7/2116
2020 PO4821787983	LGE	4	40 BRO	SP	CRE	ED	TD		2/8/2116
2020 PO4812487824	LGE	UNK	95 BRO	ST	P		V		2/9/2116
2020 PO4816687819	LGE	UNK	95 BRO	ST	CRE		V		2/10/2116
2020 PO4818887817	LGE	UNK	95 BRO	ST	P		V		2/11/2116
2020 PO4820987814	LGE	UNK	95 BRO	ST	P		V		2/12/2116
2020 PO4690788449	F	3	50 BRN	SP	A		V		2/13/2116
2020 PO4160987333	KU	4	40 KOP	DF	CRE	ED,ID,IP	TD		2/14/2116
2020 PO4128187286	KU	4	45 KOP	SP	CRE	ED,ID	TD		2/15/2116
2020 PO4097887233	KU	3	45 KOP	SP	S		V		2/16/2116
2020 PO4096287298	F	4	40 KOP	DF	P		V		2/17/2116
2020 PO4688588439	LGE	3	50 BRN	SP	A	ED,ID	BD		2/18/2116
2020 PO4689188440	LGE	3	50 BRN	SP	A	ED,ID	BD		2/19/2116
2020 PO3978997056	LGE	1	50 BRN	SP	S		V		2/20/2116
2020 PO4687488429	LGE	3	50 BRN	SP	A	ED,ID	BD		2/21/2116
2020 PO4686188429	LGE	3	50 BRN	SP	A	ED,ID	BD		2/22/2116
2020 PO4685988424	LGE	UNK	30 BRN	SP	CRE		V		2/23/2116
2020 0166877294a	KU	1	50 XXX	SP	CCA		V		2/24/2116
2020 0166877294a	KU	3	45 XXX	SP	CCA		V		2/25/2116
2020 PO0166877294	KU	3	45 XXX	SP	CCA		V		2/26/2116
2020 PO0167277293	KU	3	45 XXX	SP	CCA		V		2/27/2116

2020 PO4064387140	KU	4	45 KOP	SP	CRE	ED,ID	TD	2/28/2116	
2020 PO4066587054	KU	3	40 KOP	SP	CRE	ED,ID	TD	2/29/2116	
2020 PO0110277033	KU	1	70 XXX	SP	CCA		V	3/1/2116	
2020 0086776949a	KU	1	70 XXX	SP	CCA		V	3/2/2116	
2020 0048876768a	KU	1	60 XXX	SP	CCA		V	3/3/2116	
2020 PO0086776949	KU	1	70 XXX	SP	CCA		V	3/4/2116	
2020 PO0156477233	KU	2	50 XXX	SP	CCA		V	3/5/2116	
2020 PO9288472208	KU	6	30 OTH	SP	CCA		V	3/6/2116	
2020 PO9294372121	KU	5	40 OTH	SP	CRE	ED,ID,SRC	TX	RR	3/7/2116
2020 PO0048876758	KU	1	65 XXX	SP	CCA		V	3/8/2116	
2020 PO4050687092	KU	4	45 KOP	SP	S		V	3/9/2116	
2020 PO4039287052	KU	4	40 KOP	SP	CRE	ED,ID,IP,MD,SRC	TD	3/10/2116	
2020 PO4020686994	KU	4	40 KOP	DF	CRE	ED,ID	TD	3/11/2116	
2020 PO4003886960	KU	4	40 KOP	SP	CRE	ED,ID	TD	3/12/2116	
2020 PO3989286909	KU	4	40 KOP	DF	CRE	ID	BD	3/13/2116	
2020 PO0051275548	KU	3	45 XXX	SP	CCA		V	3/14/2116	
2020 PO0065175637	KU	5	35 XXX	SP	CCA		V	3/15/2116	
2020 PO0071175671	KU	5	35 XXX	SP	CCA		V	3/16/2116	
2020 PO0089475797	KU	5	35 XXX	SP	CCA		V	3/17/2116	
2020 PO9288472208	KU	4	40 OTH	SP	CRE	ED,ID,RB	X	RP1	3/18/2116
2020 PO9281472311	KU	5	40E OTH	SP	CRE	ED,ID,SRS	TD	3/19/2116	
2020 PO9276072391	KU	4	40 OTH	SP	CRE	ED,ID,SRS	TD	3/20/2116	
2020 PO9331972983	KU	4	45 OTH	SP	CCA		V	3/21/2116	
2020 PO9322173017	F	4	40 OTH	SP	P		V	3/22/2116	
2020 PO9331072885	F	5	35 OTH	SP	P		V	3/23/2116	
2020 PO9339572765	F	6E	35E OTH	SP	P		V	3/24/2116	
2020 PO9347772642	F	4	40 OTH	SP	CRE		V	3/25/2116	
2020 PO9354172546	F	5	35 OTH	SP	P		V	3/26/2116	
2020 0096075860a	KU	3	45 XXX	SP	CCA		V	3/27/2116	
2020 PO0106475688	KU	2	45 XXX	SP	CCA		V	3/28/2116	
2020 PO0096075860	KU	3	45 XXX	SP	CCA		V	3/29/2116	
2020 PO0086776184	KU	1	30 XXX	SP	CRE	ED,ID	TD	3/30/2116	
2020 PO0059875922	KU	3	45 XXX	SP	CCA		V	3/31/2116	
2020 PO0082076036	KU	3	45 XXX	SP	CCA		V	4/1/2116	
2020 PO0082076095	KU	4	45 XXX	SP	CRE		V	4/2/2116	
2020 PO4841187572	LGE	UNK	45 BRO	SP	CCA		V	4/3/2116	
2020 PO4842187581	LGE	4	40 BRO	SP	CRE	MD	BD	4/4/2116	
2020 PO4843187589	LGE	UNK	45 BRO	SP	CCA		V	4/5/2116	
2020 PO4843387615	LGE	4	40 BRO	SP	CRE	ED	BD	4/6/2116	
2020 PO4843587635	LGE	UNK	45 BRO	SP	CRE	ED	TD	4/7/2116	
2020 PO4843587638	LGE	UNK	45 BRO	SP	CRE	ED	BD	4/8/2116	
2020 PO0073276245	KU	2	45 XXX	SP	CRE	ID	BD	4/9/2116	
2020 0044576576b	KU	2	55 BRN	SP	CCA		V	4/10/2116	
2020 0044576576a	KU	3	50 BRN	SP	CCA		V	4/11/2116	
2020 PO0044576576	KU	2	50 BRN	SP	CCA		V	4/12/2116	
2020 PO0029476694	KU	2	50 BRN	SP	CCA		V	4/13/2116	
2020 PO0017576588	KU	4	45 BRN	SP	CRE		V	4/14/2116	

2020 PO4684888425	LGE	3	50 BRN	SP	A	ED,ID	BD	4/15/2116
2020 PO4681888413	LGE	3	50 BRN	SP	A	ED,ID	BD	4/16/2116
2020 PO4849987655	LGE	3	45 BRO	SP	CRE	ED	TD	4/17/2116
2020 PO4850187662	LGE	4	40 BRO	SP	CRE	ED,EP,HH,ID	BD	4/18/2116
2020 PO4849587673	LGE	UNK	45 BRO	SP	CRE	ED	TD	4/19/2116
2020 PO9994476553	KU	4	45 BRN	SP	CCA		V	4/20/2116
2020 PO9997676480	KU	4	45 BRN	SP	CCA		V	4/21/2116
2020 PO9995276470	KU	4	40 BRN	SP	CCA		V	4/22/2116
2020 PO3959886796	KU	6	30 KOP	SP	S		V	4/23/2116
2020 PO3993286392	KU	6 25E	KOP	SP	CRE		V	4/24/2116
2020 PO3993286392	KU	4	40 KOP	SP	CRE	ID	BD	4/25/2116
2020 PO3980786812	KU	6	30 KOP	SP	CCA		V	4/26/2116
2020 PO3978286871	KU	4	45 KOP	SP	CRE	ED,ID	TD	4/27/2116
2020 PO3973286806	KU	4	40 KOP	DF	CRE	ED,ID	TD	4/28/2116
2020 PO3970186849	F	5	35 KOP	SP	S		V	4/29/2116
2020 PO3960687075	KU	4	40 KOP	DF	CRE	ED,ID	TD	4/30/2116
2020 PO3945287180	KU	6	35 KOP	DF	CRE	ED,ID	TD	5/1/2116
2020 PO3931187475	KU	5	35 KOP	SP	CRE	ED,ID	TD	5/2/2116
2020 PO4686088514	LGE	4	35 BRN	SP	A	ED,ID	BD	5/3/2116
2020 PO4686088513	F	3	45 BRN	SP	CCA		V	5/4/2116
2020 PO4686688505	F	3	45 BRN	SP	A		V	5/5/2116
2020 PO4687388496	LGE	4	35 BRN	SP	CCA		V	5/6/2116
2020 PO4687688491	F	3	45 BRN	SP	A		V	5/7/2116
2020 9983976397	KU	4	40 BRN	SP	CCA		V	5/8/2116
2020 PO5450994327	KU	4	40 BRN	SP	CRE	HH,ID,IP,RB	X	PX 5/9/2116
2020 PO1797098033	KU	4	40 UNK	SP	CRE	ED,ID	X	RP2 5/10/2116
2020 PO5465993925	KU	4	40 BRN	SP	CCA		V	5/11/2116
2020 PO5480293559	KU	4	40 BRN	SP	CRE	ID,IP,SRS	TD	5/12/2116
2020 PO5489393290	KU	3	45 BRN	SP	CCA		V	5/13/2116
2020 PO5484293127	KU	4	40 BRN	SP	CCA		V	5/14/2116
2020 PO1774498075	F	6	30 UNK	SP	CRE		V	5/15/2116
2020 PO1705497395	KU	4	40 UNK	SP	CRE	ED,HH,ID	X	RP2 5/16/2116
2020 PO1713497228	KU	4	40 UNK	SP	CRE	ID	BD	5/17/2116
2020 PO1730097411	KU	4	40 UNK	SP	CCA		V	5/18/2116
2020 PO1731697490	KU	4	40 UNK	SP	CRE	HH,ID	BX	RP2 5/19/2116
2020 PO5518992487	KU	4	40 BRN	SP	CRE	ID	BD	5/20/2116
2020 PO5474592742	KU	4	40 BRN	SP	CRE	ID	BD	5/21/2116
2020 PO5512492656	KU	4	40 BRN	SP	CRE		B	5/22/2116
2020 PO5468192555	KU	4	40 BRN	SP	CCA		V	5/23/2116
2020 PO1745097140	KU	4	40 UNK	SP	CCA		V	5/24/2116
2020 PO1760096869	KU	4	40 UNK	SP	CCA		V	5/25/2116
2020 PO1767097612	KU	4	40 UNK	SP	CRE	ID	BD	5/26/2116
2020 PO1780197492	F	4	40 UNK	SP	CRE		V	5/27/2116
2020 PO5546793862	KU	4	40 BRN	SP	CRE		V	5/28/2116
2020 PO5460692280	KU	4	45 BRN	SP	CRE		B	5/29/2116
2020 PO5447791788	KU	4	40 BRN	SP	CRE	ID	TD	5/30/2116
2020 PO5461892710	F	4	40 BRN	SP	CRE		V	5/31/2116

2020 PO5447791609	KU	4	40 BRN	SP	CRE	ID	TD		6/1/2116
2020 PO5448391364	KU	4	40 BRN	SP	CRE	ID	TD		6/2/2116
2020 PO0607796303	KU	4	40 ACW	SP	CRE		V		6/3/2116
2020 PO0466495310	KU	4	40 ACW	SP	CRE		B		6/4/2116
2020 PO9958993623	KU	5	35 ACW	SP	CRE	ED,ID	BD		6/5/2116
2020 PO9972193745	KU	5	35 ACW	SP	CRE	ED,ID	BD		6/6/2116
2020 PO0581194568	KU	6	30 ACW	SP	CRE	ED,ID	BX	RP2	6/7/2116
2020 PO0214193761	KU	3	45 ACW	SP	CRE	ED,ID	TD		6/8/2116
2020 PO0016693833	KU	4	40 ACW	SP	CRE	ED,ID,IP,SRC	TD		6/9/2116
2020 PO0069493941	KU	5	35 ACW	SP	CRE	ED,HH,ID,RB	X	RP1	6/10/2116
2020 PO0123494047	KU	4	45 ACW	SP	CRE	ED,ID,IP	TD		6/11/2116
2020 PO4513019537	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		6/12/2116
2020 PO0661494583	KU	3	45 ACW	SP	S		V		6/13/2116
2020 PO0570095177	KU	4	40 ACW	SP	CRE	ID	BD		6/14/2116
2020 PO4522619730	KU	4	40 BRO	SP	CRE	ED,ID	TD		6/15/2116
2020 PO4552019268	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		6/16/2116
2020 PO4595518934	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		6/17/2116
2020 PO4634818660	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD		6/18/2116
2020 PO4384902834	KU	4	35 BRO	SP	CRE	ED,ID	TD		6/19/2116
2020 PO5643349017	KU	2	50 ACE	SP	CRE	ED,ID	TD		6/20/2116
2020 PO0622394212	KU	4	40 ACW	SP	CRE		B		6/21/2116
2020 PO0644094343	KU	4	40 ACW	SP	CRE	ED,ID	TD		6/22/2116
2020 PO0544294884	KU	6	30 ACW	SP	CRE	ID	BD		6/23/2116
2020 PO0494195369	KU	4	45 ACW	SP	CRE	ID	BD		6/24/2116
2020 PO5283345031	KU	6	30 ACE	SP	CRE		V		6/25/2116
2020 PO5642249252	KU	4	35 ACE	SP	CRE	ED,ID,IP	BD		6/26/2116
2020 PO9016889441	KU	6	30 ACW	SP	CRE	ED,ID	TD		6/27/2116
2020 PO9152191078	KU	4	40 ACW	SP	CRE	ED,ID	TD		6/28/2116
2020 PO4367402688	F	3	40 BRO	SP	A		V		6/29/2116
2020 PO4375402701-A	KU	5	35 BRO	SP	A	ED,ID,IP	TD		6/30/2116
2020 PO5643848823	KU	3	55 ACE	SP	CRE		V		7/1/2116
2020 PO5645048804	KU	3	55 ACE	SP	CRE		V		7/2/2116
2020 PO5647448509	KU	3	40 ACE	SP	CRE	ED,ID,IP	BD		7/3/2116
2020 PO5647448199	KU	4	45 ACE	SP	CCA		V		7/4/2116
2020 PO4385002770	KU	4	35 BRO	SP	CCA	ED,ID,IP	TD		7/5/2116
2020 PO0295092778	KU	5	35 ACW	SP	CRE	ED,ID	TD		7/6/2116
2020 PO0313192583	F	3	40 ACW	SP	A		V		7/7/2116
2020 PO5647448082	KU	3	40 ACE	SP	CRE	ED,ID	TD		7/8/2116
2020 PO4380002569	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		7/9/2116
2020 PO0230993411	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD		7/10/2116
2020 PO0255593152	KU	6	30 ACW	SP	P	ED,ID	TD		7/11/2116
2020 PO0278192944	KU	5	35 ACW	SP	P	ED,ID	TD		7/12/2116
2020 PO0430693623	C	6	30 ACW	SP	CRE		V		7/13/2116
2020 PO6118647720	KU	2	55 ACE	SP	CRE	ED,ID	BD		7/14/2116
2020 PO5274345140	KU	6	30 ACE	SP	CRE		V		7/15/2116
2020 PO5266645242	KU	1	60 ACE	SP	CRE		V		7/16/2116
2020 PO4394802565	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD		7/17/2116

2020 PO4390702596	KU	3	45 BRO	SP	CRE	ED,ID,IP	TD	7/18/2116
2020 PO4400602624	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	7/19/2116
2020 PO4415302767	KU	6	30 BRO	SP	CRE	ED,ID	TD	7/20/2116
2020 PO4410002719	KU	5	35 BRO	SP	CRE	ED,ID	TD	7/21/2116
2020 PO4417502715	F	4	35 BRO	SP	A		V	7/22/2116
2020 PO0675193757	KU	4	40 ACW	SP	CRE	ED,ID	TD	7/23/2116
2020 PO0723793113	KU	4	40 ACW	SP	CRE	ED,ID	TD	7/24/2116
2020 PO0757992832	KU	6	30 ACW	SP	CRE	ID	BD	7/25/2116
2020 PO0239594345	KU	4	45 ACW	SP	CRE	ED,ID	TD	7/26/2116
2020 PO0215294279	KU	4	40 ACW	SP	CRE	ED,ID,SRC	TD	7/27/2116
2020 PO0190594251	KU	4	40 ACW	SP	CRE	ED,ID	TD	7/28/2116
2020 PO4413102648	KU	3	40 BRO	SP	CRE	ED,ID,IP	TD	7/29/2116
2020 PO4430202668-A	KU	4	35 BRO	SP	CRE		V	7/30/2116
2020 PO4430202668	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	7/31/2116
2020 PO0760392612	KU	4	45 ACW	SP	CRE	ID	BD	8/1/2116
2020 PO5259145342	KU	6	30 ACE	SP	CRE		V	8/2/2116
2020 PO0792492767	KU	4	40 ACW	SP	CRE	ID	BD	8/3/2116
2020 PO0827692702	KU	4	45 ACW	SP	CRE		V	8/4/2116
2020 PO0822392251	KU	4	45 ACW	ST	CRE		V	8/5/2116
2020 PO5228646409	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD	8/6/2116
2020 PO0828991747	KU	3	45 ACW	SP	S		V	8/7/2116
2020 PO0828991747	KU	3	45 ACW	SP	S		V	8/8/2116
2020 PO0834891778	KU	4	45 ACW	ST	CRE		V	8/9/2116
2020 PO0585693451	KU	4	45 ACW	SP	CRE	ED,ID	TD	8/10/2116
2020 PO0259694613	KU	4	40 ACW	SP	CRE	ED,ID	TD	8/11/2116
2020 PO4442002644	KU	4	40 BRO	SP	CRE	ED,ID	TD	8/12/2116
2020 PO4441402491	KU	4	40 BRO	SP	CRE	ED,ID	TD	8/13/2116
2020 PO4431902482	KU	4	35 BRO	SP	CCA		V	8/14/2116
2020 PO4440702362	KU	3	45 BRO	SP	CCA		V	8/15/2116
2020 PO4429602729	F	3	45 BRO	SP	CCA		V	8/16/2116
2020 PO4441602758	F	6	35 BRO	SP	A		V	8/17/2116
2020 PO4456402942	KU	3	45 BRO	SP	CCA		V	8/18/2116
2020 PO5239445602	KU	4	40 ACE	SP	CRE	ED,HH,ID,RB	BX	8/19/2116
2020 PO0529893268	KU	4	40 ACW	SP	S		V	8/20/2116
2020 PO5256545849	KU	4	40 ACE	SP	CCA		V	8/21/2116
2020 PO5225046090	KU	4	40 ACE	SP	CRE	ED,ID	TD	8/22/2116
2020 PO5232945811	KU	4	40 ACE	SP	CRE	ED,ID	TD	8/23/2116
2020 PO0304094813	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	8/24/2116
2020 PO0357095084	KU	2	55 ACW	SP	CRE	ED,ID	TD	8/25/2116
2020 PO0687195905	KU	6	30 ACW	SP	S		V	8/26/2116
2020 PO3773248817	KU	4	40 BRO	SP	CRE	ID,IP	BD	8/27/2116
2020 PO5207035800	F	4	40 ACE	SP	CRE		V	8/28/2116
2020 PO5205236030	F	4	40 ACE	SP	CRE		V	8/29/2116
2020 PO3563248993	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/30/2116
2020 PO5218236442	F	4	40 ACE	SP	CRE		V	8/31/2116
2020 PO5187836658	F	4	40 ACE	SP	CRE		V	9/1/2116
2020 PO3797148652	KU	3	40 BRO	SP	CRE	ED,ID,IP	TD	9/2/2116

2020 PO3864949086	KU	3	40 BRO	SP	CRE	ID,IP	BD	9/3/2116
2020 PO3872749388	KU	3	45 BRO	SP	CCA		V	9/4/2116
2020 PO3890749341	KU	4	40 BRO	SP	CRE	ID,IP	BD	9/5/2116
2020 PO3881949638	KU	4	40 ACE	SP	CRE	ED,ID	TD	9/6/2116
2020 PO3858148693	F	3	45 BRO	SP	CCA		V	9/7/2116
2020 PO3816548886	KU	3	45 BRO	SP	CCA		V	9/8/2116
2020 PO3828848826	KU	4	40 ACE	SP	CCA		V	9/9/2116
2020 PO3874448680	KU	3	45 ACE	SP	CCA		V	9/10/2116
2020 PO3891248560	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/11/2116
2020 PO3904348591	KU	5	35 ACE	SP	CCA		V	9/12/2116
2020 PO3906248208	KU	4	40 ACE	SP	CRE		V	9/13/2116
2020 PO3686446551	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/14/2116
2020 PO3667644655	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/15/2116
2020 PO3656744725	KU	6	30 ACE	SP	CRE	ED,ID	TD	9/16/2116
2020 PO3670744893	KU	3	45 ACE	SP	CCA		V	9/17/2116
2020 PO3675745456	KU	3	45 BRO	SP	A	ED	T	9/18/2116
2020 PO3674045144	KU	3	45 ACE	SP	CCA		V	9/19/2116
2020 PO3680545984	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	9/20/2116
2020 PO5387146119	KU	5	35 ACE	SP	CCA		V	9/21/2116
2020 PO5312445625	KU	3	45 ACE	SP	CCA		V	9/22/2116
2020 PO5093635393	KU	4	40 ACE	SP	CRE	ED,ID	TD	9/23/2116
2020 PO5101335435	KU	6	30 ACE	SP	CRE	ED,ID	TD	9/24/2116
2020 PO5094235229	KU	4	40 BRO	SP	CRE	ID,IP	BD	9/25/2116
2020 PO5094435045	KU	4	40 BRO	SP	CRE	ID,IP	BD	9/26/2116
2020 PO5209135590	F	4	40 ACE	SP	CRE		V	9/27/2116
2020 PO5124234197	F	4	40 BRO	SP	CRE		V	9/28/2116
2020 PO5124333945	KU	4	40 BRO	SP	CCA		V	9/29/2116
2020 PO5122234451	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/30/2116
2020 PO5151034909	KU	5	35 BRO	SP	CRE	ED,ID	TD	10/1/2116
2020 PO5155135612	KU	6	30 ACE	SP	CRE	ED,ID	TD	10/2/2116
2020 PO5184736137	F	4	40 ACE	SP	CRE		V	10/3/2116
2020 PO5157034602	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	10/4/2116
2020 PO5185736294	F	4	40 ACE	SP	CRE		V	10/5/2116
2020 PO5176436601	KU	6	30 BRO	SP	CRE	ED,ID	TD	10/6/2116
2020 PO5187436595	F	4	40 ACE	SP	CRE		V	10/7/2116
2020 PO5174936093	KU	5	35 BRO	SP	CRE	ED,ID	TD	10/8/2116
2020 PO5188836818	F	4	40 ACE	SP	CRE		V	10/9/2116
2020 PO5194136547	KU	6	30 ACE	SP	CCA		V	10/10/2116
2020 PO5195136597	F	6	35 ACE	SP	CRE		V	10/11/2116
2020 PO5186536475	F	4	40 ACE	SP	CRE		V	10/12/2116
2020 PO5170437583	KU	4	40 BRO	SP	CRE	ID,IP	BD	10/13/2116
2020 PO5189836952	F	3	45 ACE	SP	CCA		V	10/14/2116
2020 PO5168837425	KU	4	40 BRO	SP	CRE	ED,ID,IP,RB	X	10/15/2116
2020 PO5164937019	KU	4	45 ACE	SP	CRE	ED,ID,IP	TD	10/16/2116
2020 PO5165937093	F	4	40 ACE	SP	CRE		V	10/17/2116
2020 PO5167837296	KU	3	40 BRO	SP	CRE	ED,ID,IP	TD	10/18/2116
2020 PO5186337056	KU	3	40 BRO	SP	CCA		V	10/19/2116

2020 PO5144237023	KU	3	45 ACE	SP	CCA	ED,ID	TD			10/20/2116
2020 PO5166437150	KU	4	45 BRO	SP	CRE	ED,ID,IP	TD			10/21/2116
2020 PO5171537172	KU	5	35 BRO	SP	CCA		V			10/22/2116
2020 PO5210835441	F	4	40 ACE	SP	CRE		V			10/23/2116
2020 PO5192535400	F	4	45 ACE	SP	CRE		V			10/24/2116
2020 PO5384641951	KU	4	40 BRO	SP	CRE		V			10/25/2116
2020 PO5346937794	F	4	40 ACE	SP	CRE		V			10/26/2116
2020 PO5347937976	F	4	40 ACE	SP	CRE		V			10/27/2116
2020 PO5172635952	F	4	40 ACE	SP	CRE		V			10/28/2116
2020 PO5386242019	F	4	40 BRO	ST	P		V			10/29/2116
2020 PO2075800004	KU	4	45 UNK	SP	CRE	HH,ID	X		RP1	10/30/2116
2020 PO2076799959	KU	4	45 UNK	SP	CRE	HH,ID,SRS	TX		RR	10/31/2116
2020 PO2125899707	KU	4	40 UNK	SP	CRE	ID,IP	TD			11/1/2116
2020 PO3410001781	KU	4	40 BRN	SP	CRE	ID	TD			11/2/2116
2020 PO2039900081	KU	4	40 UNK	SP	CRE		V			11/3/2116
2020 PO2040000029	KU	4	40 UNK	SP	CRE		V			11/4/2116
2020 PO3380801834	KU	5	35 BRN	SP	CCA		V			11/5/2116
2020 PO3408601709	KU	4	40 BRN	SP	CRE	ID,IP	TD			11/6/2116
2020 PO3400501727	KU	5	35 BRN	SP	CRE	ID,IP	BD			11/7/2116
2020 PO3406201604	KU	4	40 BRN	SP	CRE	ID	TD			11/8/2116
2020 PO3398501565	F	4	40 BRN	SP	CRE		V			11/9/2116
2020 PO3414201465	KU	4	40 BRN	SP	CRE	ID,IP	TD			11/10/2116
2020 PO3403301453	F	6	30E BRN	SP	CRE		V			11/11/2116
2020 PO2071400202	KU	3	45 UNK	SP	CCA		V			11/12/2116
2020 PO5061097704	KU	4	40 BRN	SP	CRE	ID,IP	TD			11/13/2116
2020 PO5070897556	KU	4	40 BRN	SP	CRE	ID,IP	TD			11/14/2116
2020 PO2004999345	KU	4	40 UNK	SP	CRE	ID	TD			11/15/2116
2020 PO2002699367	KU	4	40 UNK	SP	CRE	ID,IP	BD			11/16/2116
2020 PO5099797499	KU	4	40 BRN	SP	CRE	ID,IP	TD			11/17/2116
2020 PO5126997431	KU	4	40 BRN	SP	CRE	ID,IP	TD			11/18/2116
2020 PO2053299760	KU	3	45 UNK	SP	CCA		V			11/19/2116
2020 PO2049899775	KU	3	45 UNK	SP	CCA		V			11/20/2116
2020 PO2037399830	KU	4	40 UNK	SP	CRE	ED,ID,IP	BD			11/21/2116
2020 PO2018999922	KU	4	45 UNK	SP	CRE	ID	TD			11/22/2116
2020 PO1790597659	KU	2	60 UNK	SP	CRE	HH,ID	X		RP3	11/23/2116
2020 PO1787897687	KU	1	65 UNK	SP	CRE	ID,IP	BD			11/24/2116
2020 PO1786597710	KU	1	65 UNK	SP	CRE	ID,IP	BD			11/25/2116
2020 PO5325196997	KU	5	35 BRN	SP	CRE	ID,IP	BD			11/26/2116
2020 PO5304697049	KU	5	35 BRN	SP	CRE	ID,IP	BD			11/27/2116
2020 PO5282097095	KU	5	35 BRN	SP	CRE	ID	TD			11/28/2116
2020 PO5233797200	KU	4	40 BRN	SP	CRE	ID,IP	TD			11/29/2116
2020 PO1890298550	KU	4	45 UNK	SP	CRE	ID,IP	TD			11/30/2116
2020 PO1891898527	KU	4	45 UNK	SP	CRE	ID,IP	TD			12/1/2116
2020 PO5168997340	KU	4	45 BRN	SP	CCA		V			12/2/2116
2020 PO5150997381	KU	3	45E BRN	SP	CRE	ID,IP	TD			12/3/2116
2020 PO5147397573	KU	4	40 BRN	SP	CRE	ID	TD			12/4/2116
2020 PO1971499104	KU	3	40 UNK	SP	CRE	ID	TD			12/5/2116

2020 PO1973799084	KU	4	45 UNK	SP	CRE	ID,IP	TD	12/6/2116
2020 PO1983998972	KU	4	40 UNK	SP	CRE	ID,IP,SRS	TD	12/7/2116
2020 PO1935998863	KU	4	45 UNK	SP	CRE	ED,ID	BX	RP2 12/8/2116
2020 PO3424802169-A	KU	3	45 BRN	SP	CRE	ID,IP	BD	12/9/2116
2020 PO3411502040	KU	7 30E	BRN	SP	CRE	ID,IP	TD	12/10/2116
2020 PO3416902096	KU	6	30 BRN	SP	CRE	ED,ID	BX	RP2 12/11/2116
2020 PO3411502040	KU	4	35 BRN	SP	CRE	ID,IP	TD	12/12/2116
2020 PO3415502028	KU	4	40 BRN	SP	CRE	ID	TD	12/13/2116
2020 PO3406701997	F	4	40 BRN	SP	A		V	12/14/2116
2020 PO3379802085	KU	4	40 BRN	SP	CRE	ID,IP	TD	12/15/2116
2020 PO3373702139	F	4	40 BRN	SP	CRE		V	12/16/2116
2020 PO3374102105	F	6 30E	BRN	SP	P		V	12/17/2116
2020 PO3380802038	KU	6	30 BRN	SP	CRE	ID	TD	12/18/2116
2020 PO3392502044	KU	4	40 BRN	SP	CRE	ID	TD	12/19/2116
2020 PO3397202168	KU	4	45 BRN	SP	CRE	ID,IP	TD	12/20/2116
2020 PO3406102401	KU	4	45 BRN	SP	CRE	ID,IP	TD	12/21/2116
2020 PO4796597556	KU	5	35 BRN	SP	CRE	ID	TD	12/22/2116
2020 PO4939397847	KU	4	40 BRN	SP	CRE	ID,IP	BD	12/23/2116
2020 PO2153600422	KU	4	40 UNK	SP	CRE	ID	TD	12/24/2116
2020 PO2175200241	KU	4	40 UNK	SP	CRE	ID	TD	12/25/2116
2020 PO5030697652-A	KU	4	40 BRN	SP	CRE	ID,IP	TD	12/26/2116
2020 PO5030697652	KU	4	40 BRN	SP	CRE	ID,IP	BD	12/27/2116
2020 PO4790998079	KU	3	55 BRN	SP	CRE	ID	BD	12/28/2116
2020 PO2196400003	KU	4	40 UNK	SP	CRE	ID	TD	12/29/2116
2020 PO2189700238	KU	6	30 UNK	SP	CCA		V	12/30/2116
2020 PO4883697973	KU	5	45 BRN	SP	CRE	ID,IP	TD	12/31/2116
2020 PO4905597915	KU	4	40 BRN	SP	CRE	ID,IP	BD	1/1/2117
2020 PO2217299996	KU	4	40 UNK	SP	CCA		V	1/2/2117
2020 PO2259499734	F	6	30 UNK	SP	CRE		V	1/3/2117
2020 PO2276199415	KU	6	30 UNK	SP	CRE	ID,IP	TD	1/4/2117
2020 PO2250099681	KU	5	35 UNK	SP	CRE	ID,IP,SRS	TD	1/5/2117
2020 PO4992997735	KU	4	40 BRN	SP	CRE	ID,IP	TD	1/6/2117
2020 PO2080300351	KU	4	40 UNK	SP	CRE	ID	TD	1/7/2117
2020 PO2096199959	KU	1	65 UNK	WC	A		V	1/8/2117
2020 PO2096299923	KU	1	65 UNK	WC	A		V	1/9/2117
2020 PO4928398133	F	4	40 BRN	SP	CCA	ID	V	1/10/2117
2020 PO4903198076	KU	4	40 BRN	SP	CRE	ID	TD	1/11/2117
2020 PO5574144451	F	3	40 ACW	SP	P		V	1/12/2117
2020 PO5589144462	F	4	40 ACW	SP	P		V	1/13/2117
2020 PO5598244469	F	4	40 ACW	SP	P		V	1/14/2117
2020 PO3407348228	F	5 35E	ACE	SP	CRE	ED,ID	V	1/15/2117
2020 PO3608347419	F	4	40 ACE	SP	CCA		V	1/16/2117
2020 PO4671388409	F	4	40 BRN	SP	CRE		V	1/17/2117
2020 PO4671788397	F	4	40 BRN	SP	A		V	1/18/2117
2020 PO6900414614	KU	4	45 XXX	SP	CCA		V	1/19/2117
2020 PO4644688866	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TX	RR 1/20/2117
2020 PO6842614984	KU	4	40 XXX	SP	CRE	ED,ID	TD	1/21/2117

2020 PO6809714956	KU	4	40 XXX	SP	CRE	ED,ID	TD	1/22/2117	
2020 PO6775414921	KU	4	40 XXX	SP	CRE	ED,ID	TD	1/23/2117	
2020 PO4646888883	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	1/24/2117	
2020 PO4646288878	LGE	4	40 BRO	SP	CCA		V	1/25/2117	
2020 PO4678788275	LGE	4	40 BRN	SP	CRE	ED,ID	BD	1/26/2117	
2020 PO4678088270	F	4	40 BRN	SP	CCA		V	1/27/2117	
2020 PO4680388297	LGE	4	40 BRN	SP	CRE	ED,ID	BD	1/28/2117	
2020 PO4679188278	F	4	40 BRN	SP	CRE	ED,HH,ID	VX	PX	1/29/2117
2020 PO4647988890	LGE	4	40 BRO	SP	P	ED,ID,IP	TD	1/30/2117	
2020 PO6750514951	KU	4	40 XXX	SP	CCA		V	1/31/2117	
2020 PO4649088874	LGE	4	35 BRO	SP	CRE	ID,IP	BD	2/1/2117	
2020 PO6718014978	KU	4	40 XXX	SP	CRE	ID	BD	2/2/2117	
2020 PO6677815174	KU	4	40 XXX	SP	CRE	ED,ID	TD	2/3/2117	
2020 PO6653615345	KU	4	40 XXX	SP	CCA		V	2/4/2117	
2020 PO6626315434	KU	4	40 XXX	SP	CRE	ID	BD	2/5/2117	
2020 PO6594915441	F	5	30 XXX	SP	CRE		V	2/6/2117	
2020 PO6598615518	KU	3	45 XXX	SP	CCA		V	2/7/2117	
2020 PO4681188294	F	4	40 BRN	SP	CCA		V	2/8/2117	
2020 PO4662189111	F	3	45 BRO	SP	CCA		V	2/9/2117	
2020 PO4099891806	F	4	40 KOP	SP	S		V	2/10/2117	
2020 PO4095091815	KU	5	30 KOP	SP	CRE	ID	BD	2/11/2117	
2020 PO4079191553	KU	4	40 KOP	SP	S		V	2/12/2117	
2020 PO4080691575	KU	4	40 KOP	SP	S		V	2/13/2117	
2020 PO4093891788	KU	4	40 KOP	SP	CRE	ED,ID	TD	2/14/2117	
2020 PO4086191667	KU	4	45 KOP	SP	CRE	ED,ID	TD	2/15/2117	
2020 PO4077791826	KU	4	45 KOP	SP	S		V	2/16/2117	
2020 PO4060891573	KU	3	45 KOP	SP	CRE	ED,ID	TD	2/17/2117	
2020 PO4063291521	KU	6	35 KOP	SP	CRE	ED,ID	TD	2/18/2117	
2020 PO4069891489	KU	4	45 KOP	DF	CRE	ED,ID	TD	2/19/2117	
2020 PO4478891806	F	4	40 KOP	SP	S		V	2/20/2117	
2020 PO4449891811	F	4	40 KOP	SP	CRE		V	2/21/2117	
2020 PO4397091824	F	3	45 KOP	SP	CRE		V	2/22/2117	
2020 PO4374091836	F	4	40 KOP	SP	S		V	2/23/2117	
2020 PO4347391845	F	4	40 KOP	DF	CRE		V	2/24/2117	
2020 PO4327491859	F	4	40 KOP	SP	CRE		V	2/25/2117	
2020 PO4272491882	F	4	40 KOP	SP	CRE		V	2/26/2117	
2020 PO4258391888	F	4	40 KOP	SP	CRE		V	2/27/2117	
2020 PO3349348424	F	4	40 ACE	SP	CRE	ED,ID	V	2/28/2117	
2020 PO5556044614	F	3	40 ACW	SP	S		V	3/1/2117	
2020 PO5553844592	F	4	40 ACW	SP	CRE		V	3/2/2117	
2020 PO3324548594	F	4	40 ACE	SP	CRE	ED,ID,IP	V	3/3/2117	
2020 PO3270849016	F	4	40 ACE	SP	CRE	ED,ID	V	3/4/2117	
2020 PO3248649188	F	4	40 ACE	SP	CRE	ED,ID	V	3/5/2117	
2020 PO3302548785	F	3	45 ACE	SP	CCA		V	3/6/2117	
2020 PO5605444755	F	3	45 ACW	SP	S		V	3/7/2117	
2020 PO5549744743	KU	6	30 ACW	SP	CRE	ED,ID	BD	3/8/2117	
2020 PO5556644679A	KU	6	30 ACW	SP	CRE	ED,ID	TD	3/9/2117	

2020 PO5556644679	KU	3	45 ACW	SP	CRE	ED,ID	TD	3/10/2117
2020 PO5990040179	KU	4	40 BRN	SP	CRE	ED,ID	TD	3/11/2117
2020 PO6008441495	F	3	45 BRN	SP	CCA		V	3/12/2117
2020 PO6054040819A	KU	5	35 BRN	SP	S		V	3/13/2117
2020 PO6054040819	KU	4	40 BRN	SP	CCA		V	3/14/2117
2020 PO6019540856	F	4	40 BRN	SP	CRE		V	3/15/2117
2020 PO6019540491	F	4	40 BRN	SP	S		V	3/16/2117
2020 PO6015341208	F	4	40 BRN	SP	S		V	3/17/2117
2020 PO3300350144	KU	6	30 ACE	SP	CCA		V	3/18/2117
2020 PO3264250100	KU	3	45 ACE	SP	CCA	ED	T	3/19/2117
2020 PO3257950268	F	4	40 ACE	SP	CRE		V	3/20/2117
2020 PO3264950301	F	3	45 ACE	SP	CCA		V	3/21/2117
2020 PO5582745144	KU	6	30 ACW	ST	CCA		V	3/22/2117
2020 PO5591645096	KU	6	30 ACW	SP	S		V	3/23/2117
2020 PO6009340313	KU	4	40 BRN	SP	CRE		V	3/24/2117
2020 PO6024640210	KU	3	45 BRN	SP	CCA		V	3/25/2117
2020 PO5565344648	KU	6	30 ACW	SP	CRE	ED,ID,IP	TD	3/26/2117
2020 PO5571644718	KU	6	30 ACW	SP	CRE	ED,ID,IP	TD	3/27/2117
2020 PO5577944786	F	6	30 ACW	SP	CRE		V	3/28/2117
2020 PO6017840086	F	4	40 BRN	SP	P		V	3/29/2117
2020 PO6074438404	KU	6	30 BRN	SP	CCA		V	3/30/2117
2020 PO6018940177	C	4	40 BRN	SP	CRE		V	3/31/2117
2020 PO6020839990	KU	4	45 BRN	SP	CCA		V	4/1/2117
2020 PO4452622967	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/2/2117
2020 PO4472722782	KU	4	35 BRO	SP	CRE	ED,ID,IP	TD	4/3/2117
2020 PO6013238286	F	4	40 BRN	SP	S		V	4/4/2117
2020 PO6029337893	C	4	40 BRN	SP	CRE		V	4/5/2117
2020 PO6014937723	KU	6	30 BRN	SP	CRE		V	4/6/2117
2020 PO5593245353G	KU	6	30 ACW	ST	CCA		V	4/7/2117
2020 PO5593245353F	KU	6	30 ACW	ST	CCA		V	4/8/2117
2020 PO5593245353E	KU	6	30 ACW	ST	CCA		V	4/9/2117
2020 PO5593245353D	KU	6	30 ACW	SP	S		V	4/10/2117
2020 PO5593245353C	KU	6	30 ACW	ST	CCA		V	4/11/2117
2020 PO5998138265	KU	4	40 BRN	SP	CRE	ED,ID	TD	4/12/2117
2020 PO4491422601	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD	4/13/2117
2020 PO5613543538	KU	4	40 ACW	SP	S		V	4/14/2117
2020 PO5593943328	KU	4	40 ACW	SP	S		V	4/15/2117
2020 PO5593943328	KU	3	40 ACW	SP	S		V	4/16/2117
2020 PO5559043320	KU	3	45 ACW	SP	S		V	4/17/2117
2020 PO5555843221	KU	4	45 ACW	SP	S		V	4/18/2117
2020 PO5537143192	KU	3	45 ACW	SP	S		V	4/19/2117
2020 PO5728642091H	KU	6	30 ACW	ST	CCA		V	4/20/2117
2020 PO5728642091G	KU	6	30 ACW	ST	CCA		V	4/21/2117
2020 PO5728642091F	KU	6	30 ACW	ST	S		V	4/22/2117
2020 PO5728642091E	KU	6	30 ACW	ST	CCA		V	4/23/2117
2020 PO5728642091	KU	6	30 ACW	ST	CCA		V	4/24/2117
2020 PO5728642091C	KU	6	30 ACW	ST	CCA		V	4/25/2117

2020	PO5728642091	KU	6	30 ACW	ST	CCA		V	4/26/2117
2020	PO5728642091A	KU	6	30 ACW	ST	CCA		V	4/27/2117
2020	PO5689042748	KU	2	50 ACW	SP	S		V	4/28/2117
2020	PO5723942396	KU	4	40 ACW	SP	CRE	ED,ID	TD	4/29/2117
2020	PO5706242574	KU	4	40 ACW	SP	CRE	ED,ID,IP	TD	4/30/2117
2020	PO5766842240	KU	4	45 ACW	SP	S		V	5/1/2117
2020	PO5754242382	KU	4	45 ACW	SP	S		V	5/2/2117
2020	PO5767042581	KU	3	45 ACW	SP	S		V	5/3/2117
2020	PO5750142426	KU	3	45 ACW	SP	S		V	5/4/2117
2020	PO5740442535	KU	4	45 ACW	SP	S		V	5/5/2117
2020	PO5742042882	KU	4	45 ACW	SP	S		V	5/6/2117
2020	PO5733842804	KU	3	45 ACW	SP	S		V	5/7/2117
2020	PO5724442713	KU	4	45 ACW	SP	S		V	5/8/2117
2020	PO5710342813	KU	5	35 ACW	SP	S		V	5/9/2117
2020	PO5710342950	KU	5	35 ACW	SP	S		V	5/10/2117
2020	PO5728642091	KU	4	40 ACW	SP	S		V	5/11/2117
2020	PO5722341903	KU	3	45 ACW	SP	S		V	5/12/2117
2020	PO5759442009	KU	4	40 ACW	SP	S		V	5/13/2117
2020	PO5748142163	KU	4	40 ACW	SP	S		V	5/14/2117
2020	PO5736842258	KU	4	40 ACW	SP	S		V	5/15/2117
2020	PO5755242022	KU	3	45 ACW	SP	CCA		V	5/16/2117
2020	PO4665488162	LGE	3	45 BRN	SP	A	ED,ID	TD	5/17/2117
2020	PO4664888171	LGE	4	40 BRN	SP	CRE	ED,ID	TD	5/18/2117
2020	PO4664388179	LGE	4	40 BRN	SP	CRE	ED,ID	TD	5/19/2117
2020	PO4663788188	LGE	4	40 BRN	SP	CRE	ED,ID	BD	5/20/2117
2020	PO4663288196	LGE	4	40 BRN	SP	CRE	ED,HH,ID	BX	PX 5/21/2117
2020	PO4662688204	LGE	4	40 BRN	SP	A	ED,ID	TD	5/22/2117
2020	PO4662188212	LGE	4	40 BRN	SP	CRE	ED,ID	TD	5/23/2117
2020	PO4661588221	LGE	4	40 BRN	SP	A	ED,ID	BD	5/24/2117
2020	PO4661088229	LGE	4	40 BRN	SP	CRE	ED,ID	BD	5/25/2117
2020	PO4645089112	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	5/26/2117
2020	PO4644689117	LGE	4	40 BRO	SP	A	ED,ID	TD	5/27/2117
2020	PO4656488299	LGE	4	40 BRN	SP	CRE	ED,ID	BD	5/28/2117
2020	PO4658688266	LGE	4	40 BRN	SP	CRE	ED,ID,RB	BX	PX 5/29/2117
2020	PO4660288241	LGE	4	40 BRN	SP	CCA		V	5/30/2117
2020	PO4643589099	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	5/31/2117
2020	PO4724488296	LGE	4	35 BRO	SP	A	ED,ID	TD	6/1/2117
2020	PO4725088281	LGE	UNK	25 BRO	SP	CCA		V	6/2/2117
2020	PO4659188258	LGE	3	45 BRN	SP	CCA		V	6/3/2117
2020	PO4722388269	LGE	4	30 BRO	SP	P	ED,ID	TD	6/4/2117
2020	PO4724388287	LGE	4	40 BRO	SP	CRE	ED,ID	BD	6/5/2117
2020	PO4714188345	LGE	3	45 BRO	SP	P		T	6/6/2117
2020	PO4715288337	LGE	4	40 BRO	SP	CRE	ED,ID	TD	6/7/2117
2020	PO4716388328	LGE	4	40 BRO	SP	CRE	ED,ID	TD	6/8/2117
2020	PO4658088275	LGE	4	40 BRN	SP	P	ED,ID	TD	6/9/2117
2020	PO4657588283	LGE	4	40 BRN	SP	CRE	ED,ID,SRS	TD	6/10/2117
2020	PO4656988291	LGE	4	40 BRN	SP	CRE	ED,ID	BD	6/11/2117

2020 PO3540489271	KU	4	40 XXX	SP	CRE	ID	TD	6/12/2117
2020 PO4655988309	LGE	4	40 BRN	SP	CRE	ED,ID	TD	6/13/2117
2020 PO4643089105	LGE	4	40 BRO	SP	A	ID,IP	BD	6/14/2117
2020 PO4717488320	LGE	4	40 BRO	SP	CRE	ED,ID	TD	6/15/2117
2020 PO4718588311	LGE	4	40 BRO	SP	CRE	ED,ID	TD	6/16/2117
2020 PO2277140840	F	4	40 KOP	SP	CRE	ED,ID	VX	6/17/2117
2020 PO7449438463	KU	6	30 OTH	SP	CRE	ID	TD	6/18/2117
2020 PO2409440660	ODP	4	40 KOP	SP	CRE	ID	BD	6/19/2117
2020 PO2361140625	ODP	4	40 KOP	SP	CRE	ID	BD	6/20/2117
2020 PO2221740668	ODP	5	35 KOP	SP	CRE	ID	BD	6/21/2117
2020 PO2266340614	ODP	5	35 KOP	SP	CRE	ID	BD	6/22/2117
2020 PO2450944418	ODP	4	40 KOP	SP	S		V	6/23/2117
2020 PO2408244423	ODP	4	40 KOP	SP	S		V	6/24/2117
2020 PO2373944460	F	4	40 KOP	SP	P		V	6/25/2117
2020 PO4719688302	LGE	4	40 BRO	SP	CRE	ED,ID	TD	6/26/2117
2020 PO4720688294	LGE	4	40 BRO	SP	CRE	ED,ID	TD	6/27/2117
2020 PO4653488206-A	LGE	4	30 BRN	SP	A	ED,ID	BD	6/28/2117
2020 PO4656088224	LGE	6	25 BRN	SP	CRE	ED,HH,ID	BX	6/29/2117
2020 PO4655588233	LGE	4	25 BRN	SP	A	ED,ID	TD	6/30/2117
2020 PO5676008867	KU	6	30 XXX	SP	CRE	ED,ID	TD	7/1/2117
2020 PO5688408898	KU	4	45 XXX	SP	CRE	ED,ID	TD	7/2/2117
2020 PO4653888215	LGE	4	30 BRN	SP	A	ED,ID	BD	7/3/2117
2020 PO7448738656	KU	4	40 OTH	SP	CCA	ED,SRS	TD	7/4/2117
2020 PO7433838662	KU	4	40 OTH	SP	CCA		V	7/5/2117
2020 PO4653488206	LGE	4	40 BRN	SP	CCA		V	7/6/2117
2020 PO7476237717	KU	4	40 OTH	SP	CRE	ID	TD	7/7/2117
2020 PO7465237211	KU	4	40 OTH	SP	CRE	ID	TD	7/8/2117
2020 PO7473637523	KU	4	40 OTH	SP	CRE	ID	TD	7/9/2117
2020 PO3787889742	KU	5	30 XXX	SP	CRE	ID	TD	7/10/2117
2020 PO3776789926	F	4	40 XXX	SP	CRE		V	7/11/2117
2020 PO3782989822	F	4	40 XXX	SP	CRE		V	7/12/2117
2020 PO3791689871	KU	6	30 XXX	SP	CCA		V	7/13/2117
2020 PO4652388223	LGE	4	35 BRN	SP	A	ED,ID	BD	7/14/2117
2020 PO5680809646	KU	4	40 XXX	SP	CRE	ED,ID	TD	7/15/2117
2020 PO5682709862	KU	4	40 XXX	SP	CRE	ED,ID	TD	7/16/2117
2020 PO4654588249	LGE	6	25 BRN	SP	CRE	ED,ID	BD	7/17/2117
2020 PO4655088241	LGE	4	35 BRN	SP	CCA		V	7/18/2117
2020 PO3794989729	F	4	40 XXX	SP	CRE		V	7/19/2117
2020 PO3800489620	F	4	40 XXX	SP	CRE		V	7/20/2117
2020 PO3809889680	KU	4	40 XXX	SP	CRE	ID	TD	7/21/2117
2020 PO3797189280	F	6	30 XXX	SP	CRE		V	7/22/2117
2020 PO3814489336	F	4	40 XXX	SP	CCA		V	7/23/2117
2020 PO3818989366	F	4	40 XXX	SP	CRE		V	7/24/2117
2020 PO3818689267	KU	6	30 XXX	SP	CRE	ID	TD	7/25/2117
2020 PO3762389003	F	4	40 XXX	SP	CRE		V	7/26/2117
2020 PO3753388945	F	4	40 XXX	SP	CRE		V	7/27/2117
2020 PO3743588886	F	4	40 XXX	SP	CRE		V	7/28/2117

2020 PO4653388266	LGE	4	30 BRN	SP	CCA		V	7/29/2117
2020 PO4652888275	LGE	4	30 BRN	SP	S		V	7/30/2117
2020 PO5701310400	KU	4	45 XXX	SP	CRE	ED,ID	TD	7/31/2117
2020 PO7473737906	F	6	35 OTH	SP	CRE	ED,ID	V	8/1/2117
2020 PO7473137989	F	6	30 OTH	SP	CRE	ED,ID	BX	8/2/2117
2020 PO7473037833	F	6	30 OTH	SP	CRE	ED,ID	V	8/3/2117
2020 PO7477537842	KU	4	40 OTH	SP	CRE	ID	TD	8/4/2117
2020 PO7464538048	KU	6	30 OTH	SP	CRE	ID	TD	8/5/2117
2020 PO7479037976	KU	4	40 OTH	SP	CRE	ID	TD	8/6/2117
2020 PO4639189035	LGE	4	40 BRO	SP	P	ED	T	8/7/2117
2020 PO4637389020	LGE	4	40 BRO	SP	A	ED,ID,IP	TD	8/8/2117
2020 PO4650188257	LGE	4	40 BRN	SP	A	ED,ID	TD	8/9/2117
2020 PO4649588265	LGE	4	35 BRN	SP	CRE	ED,ID	TD	8/10/2117
2020 PO4649188273	LGE	4	55 BRN	SP	CRE	ED,ID,IP	BD	8/11/2117
2020 PO5708510533	KU	4	40 XXX	SP	CRE	ED,ID	TD	8/12/2117
2020 PO5713310671	KU	5	45 XXX	SP	CRE	ED,ID	TD	8/13/2117
2020 PO3765289091	KU	6	30 XXX	SP	CRE	ID	TD	8/14/2117
2020 PO3771389062	F	4	40 XXX	SP	CRE		V	8/15/2117
2020 PO3779889114	KU	4	40 XXX	SP	CCA		V	8/16/2117
2020 PO3785289038	KU	6	30 XXX	SP	CCA		V	8/17/2117
2020 PO5681810703	KU	4	40 XXX	SP	CRE	ED,ID	TD	8/18/2117
2020 PO5709210748	F	4	40 XXX	SP	CRE		V	8/19/2117
2020 PO5682210786	F	5	30 XXX	SP	CRE		V	8/20/2117
2020 PO4636389012	LGE	4	40 BRO	SP	CRE	ID,IP	BD	8/21/2117
2020 PO4616689004	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/22/2117
2020 PO2003742983	ODP	4	45 KOP	SP	CRE	ID	BD	8/23/2117
2020 PO2003742983A	ODP	4	45 BRO	SP	CRE	ID	BD	8/24/2117
2020 PO1547934624	ODP	2	65 BRO	SP	CRE	ID	BD	8/25/2117
2020 PO1580934474	ODP	2	60 BRO	SP	CRE	ID	BD	8/26/2117
2020 PO1547334599	ODP	2	60 BRO	SP	CRE	ID	BD	8/27/2117
2020 PO3772489317	KU	2	40 XXX	SP	CRE	ID	TD	8/28/2117
2020 PO3766889411	F	4	40 XXX	SP	CRE		V	8/29/2117
2020 PO3762389383	KU	3	45 XXX	SP	P		V	8/30/2117
2020 PO5661310715	KU	4	40 XXX	SP	CRE	ID	BX	8/31/2117
2020 PO5647410732	KU	4	40 XXX	SP	CRE	ED,ID	TD	9/1/2117
2020 PO4641389147	LGE	3	45 BRO	SP	A	ED	TD	9/2/2117
2020 PO4638889131	LGE	3	45 BRO	SP	A	ED	TD	9/3/2117
2020 PO2525446329	F	4	40 XXX	SP	CRE		V	9/4/2117
2020 PO3749990211	F	5	35 XXX	SP	CRE		V	9/5/2117
2020 PO3744990018	KU	6	30 XXX	SP	CCA		V	9/6/2117
2020 PO3751390164	KU	4	45 XXX	SP	CRE	ID	BD	9/7/2117
2020 PO3738990078	KU	4	45 XXX	SP	CRE	ID	TD	9/8/2117
2020 PO3720790046	F	6	30 XXX	SP	CRE		V	9/9/2117
2020 PO3728590009	KU	3	45 XXX	SP	CCA		V	9/10/2117
2020 PO3757489295	KU	6	30 XXX	SP	CCA		V	9/11/2117
2020 PO3752489318	KU	4	40 XXX	SP	CCA		V	9/12/2117
2020 PO3737689196	F	4	40 XXX	SP	CRE		V	9/13/2117

2020 PO3724489073	F	4	40 XXX	SP	CRE		V	9/14/2117
2020 PO4643689164	LGE	3	45 BRO	SP	A	ID,IP	BD	9/15/2117
2020 PO5592211119	KU	4	40 XXX	SP	CRE	ED,ID	TD	9/16/2117
2020 PO5590810871	F	5	40 XXX	SP	A		V	9/17/2117
2020 PO5630010751	KU	4	40 XXX	SP	CCA		V	9/18/2117
2020 PO5587410794	KU	4	40 XXX	SP	CCA		V	9/19/2117
2020 PO4652388284	LGE	4	25 BRN	SP	CRE	ED,ID	BD	9/20/2117
2020 PO4652788287	LGE	4	40 BRN	SP	CCA		V	9/21/2117
2020 PO4653388278	LGE	4	40 BRN	SP	CCA		V	9/22/2117
2020 PO4653888270	LGE	4	35 BRN	SP	CRE	ED,ID	BD	9/23/2117
2020 PO4654488262	LGE	4	35 BRN	SP	CRE	ED,ID	BD	9/24/2117
2020 PO3731189583	F	4	40 XXX	SP	CRE		V	9/25/2117
2020 PO3719589518	F	4	40 XXX	SP	CRE		V	9/26/2117
2020 PO4663188785	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	9/27/2117
2020 PO4657889085	LGE	4	35 KOP	SP	A	ED,ID	TD	9/28/2117
2020 PO4658389079	LGE	4	40 KOP	SP	S		V	9/29/2117
2020 PO4657189095	LGE	4	35 KOP	SP	A	ED,ID,IP	TD	9/30/2117
2020 PO4657389115	LGE	4	30 KOP	SP	S		V	10/1/2117
2020 PO4658589124	LGE	3	45 KOP	SP	S		V	10/2/2117
2020 PO4659689133	LGE	4	35 KOP	SP	A	ED,ID,IP	TD	10/3/2117
2020 PO4802487868	LGE	4	40 XXX	SP	CCA		V	10/4/2117
2020 PO4665889179	LGE	4	40 KOP	SP	P	ID	BD	10/5/2117
2020 PO4665289177	LGE	4	40 KOP	SP	A	ED,ID	TD	10/6/2117
2020 PO4664389171	LGE	4	40 KOP	DF	P	ED,ID	TD	10/7/2117
2020 PO4661388818	F	4	35 OTH	SP	P		V	10/8/2117
2020 PO4662388805	F	4	35 OTH	SP	CRE		V	10/9/2117
2020 PO4660788819	LGE	3	45 OTH	SP	CRE	ED,ID,SRS	TD	10/10/2117
2020 PO4661188813	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	10/11/2117
2020 PO4659688812	LGE	7	25 OTH	SP	CRE	ED,SRS	TD	10/12/2117
2020 PO5126591528	LGE	4	30 XXX	SP	CCA		V	10/13/2117
2020 PO4795588114	LGE	4	45 XXX	SP	A		V	10/14/2117
2020 PO4781588100	LGE	4	40 XXX	SP	CCA		V	10/15/2117
2020 PO4667089184	LGE	4	40 KOP	SP	CCA	ED,ID	TD	10/16/2117
2020 PO4666789190	LGE	4	30 KOP	SP	P	ID	BD	10/17/2117
2020 PO4668189191	LGE	4	30 KOP	SP	P	ED,ID	TD	10/18/2117
2020 PO4668289185	LGE	4	40 KOP	SP	CCA	ED,ID	TD	10/19/2117
2020 PO4669489185	LGE	4	40 KOP	SP	P	ID	BD	10/20/2117
2020 PO4656488879	LGE	3	45 BRO	SP	CCA		V	10/21/2117
2020 PO4657488865	LGE	3	45 BRO	SP	CCA		V	10/22/2117
2020 PO4659288828	LGE	4	35 OTH	SP	CRE	ED,HH,ID,SRS	TD	10/23/2117
2020 PO4658388840	LGE	4	30 OTH	SP	P	ED,SRS	TD	10/24/2117
2020 PO4660688829	F	4	35 OTH	SP	CRE		V	10/25/2117
2020 PO4658988845	LGE	3	45 BRO	SP	CRE	ID	BD	10/26/2117
2020 PO4659888832	LGE	3	45 OTH	SP	P	ED,ID,SRS	TD	10/27/2117
2020 PO4656688869	LGE	3	45 BRO	SP	CCA		V	10/28/2117
2020 PO4656988871	LGE	3	45 BRO	SP	CCA		V	10/29/2117
2020 PO4804487919	LGE	4	40 XXX	SP	A	ID	BD	10/30/2117

2020 PO4799087838	LGE	H1	95	XXX	AL	S		V		10/31/2117
2020 PO4654688898	LGE		45	45 BRO	SP	CRE	ED,ID,SRS	TD		11/1/2117
2020 PO4651888942	LGE		3	45 BRO	SP	CCA		V		11/2/2117
2020 PO4652988928	LGE		4	40 BRO	SP	CRE	ID,RB	BX	PX	11/3/2117
2020 PO4655288896	LGE		4	40 BRO	SP	CCA		V		11/4/2117
2020 PV4654088912	LGE		4	40 BRO	SP	P	ED,ID,SRS	TD		11/5/2117
2020 PO4655888888	LGE		4	40 BRO	SP	CRE	ED,ID,IP,SRS	TD		11/6/2117
2020 PO5171075750	LGE		4	35 KOP	SP	S		V		11/7/2117
2020 PO5185875774	LGE		4	35 KOP	SP	S		V		11/8/2117
2020 PO5200375812	LGE		4	35 KOP	SP	S		V		11/9/2117
2020 PO5156075738	LGE		4	35 KOP	SP	S		V		11/10/2117
2020 PO5142175793	LGE		4	35 KOP	SP	S		V		11/11/2117
2020 PO5112475816	LGE		4	35 KOP	SP	S		V		11/12/2117
2020 PO5127475822	LGE		4	35 KOP	SP	S		V		11/13/2117
2020 PO5083275766	LGE		4	35 KOP	SP	S		V		11/14/2117
2020 PO5097475815	LGE		4	35 KOP	SP	S		V		11/15/2117
2020 PO4766987673	LGE		4	40 XXX	SP	CCA		V		11/16/2117
2020 PO4778287739	F		5	30 XXX	SP	CRE		V		11/17/2117
2020 PO4785187669	LGE	UNK		45 XXX	SP	A		V		11/18/2117
2020 PO4778187669	LGE		3	45 XXX	SP	A	ID	BD		11/19/2117
2020 PO4778187701	F		4	40 XXX	SP	CCA		V		11/20/2117
2020 PO4778187659	LGE	H1		100 XXX	AL	S		V		11/21/2117
2020 PO4650688949	LGE		3	40 BRO	SP	CRE	ED,ID,SRS	TD		11/22/2117
2020 PO4651488963	LGE		3	45 BRO	SP	CRE	ED,ID,IP,SRS	TD		11/23/2117
2020 PO4650688957	LGE		4	40 BRO	SP	CRE	ED,ID,SRS	TD		11/24/2117
2020 PO4649788942	LGE		3	45 BRO	SP	CCA		V		11/25/2117
2020 PO4649088951	LGE		4	40 OTH	SP	CRE	ID	BD		11/26/2117
2020 PO4651088952	LGE		4	40 BRO	SP	CCA	ED,SRS	TD		11/27/2117
2020 PO4649288957	LGE		4	40 OTH	SP	CRE	ED,ID,SRS	TD		11/28/2117
2020 PO4778287575	LGE		1	45 XXX	SP	CCA		V		11/29/2117
2020 PO4778287580	LGE		4	45 XXX	SP	A	ID	BD		11/30/2117
2020 PO4778287591	LGE		3	45 XXX	SP	CRE	ID	BD		12/1/2117
2020 PO4778287617	LGE		1	70 XXX	SP	A		V		12/2/2117
2020 PO4778187643	LGE		4	50 XXX	SP	A	ID	BD		12/3/2117
2020 PO4854887383	LGE		4	45 KOP	SP	P	ID	BD		12/4/2117
2020 PO4853287379	LGE		4	40 KOP	SP	P	ED,ID	TD		12/5/2117
2020 PO4851587374	LGE		4	40 KOP	SP	S		V		12/6/2117
2020 PO4849787361	LGE		4	40 KOP	SP	P	ID	BD		12/7/2117
2020 PO4848187350	LGE		4	40 KOP	SP	S		V		12/8/2117
2020 PO4846387337	LGE		4	40 KOP	SP	P	ED,ID	TD		12/9/2117
2020 PO4844787326	LGE		4	40 KOP	SP	S		V		12/10/2117
2020 PO4843287315	LGE		4	40 KOP	SP	S		V		12/11/2117
2020 PO4841287301	LGE		4	40 KOP	SP	S		V		12/12/2117
2020 PO4839487289	LGE		4	40 KOP	SP	CCA	ID	BD		12/13/2117
2020 PO4837387274	LGE		4	40 KOP	SP	P	ID	BD		12/14/2117
2020 PO4642789062	LGE		4	40 OTH	SP	P	ED,ID,SRS	TD		12/15/2117
2020 PO4642389067	LGE		4	40 OTH	SP	CRE	ED,SRS	TD		12/16/2117

2020 PO4643389052	LGE	5	40 OTH	SP	CRE	ED,ID,SRS	TD	12/17/2117
2020 PO5901589244	LGE	3	45 XXX	SP	CCA		V	12/18/2117
2020 PO4878887634	LGE	4	40 XXX	SP	A	ED,ID	TD	12/19/2117
2020 PO4869286454	LGE	1	45 OTH	UN	P		V	12/20/2117
2020 PO4838086266	F	3	45 OTH	SP	P		V	12/21/2117
2020 PO4833786252	F	3	45 OTH	SP	P	ED	BD	12/22/2117
2020 PO4835686258	F	3	45 OTH	SP	P		V	12/23/2117
2020 PO4830886234	LGE	3	45 OTH	SP	P	ED,SRS	TD	12/24/2117
2020 PO4835186267	LGE	3	45 OTH	SP	P	ID	BD	12/25/2117
2020 PO4831886245	F	3	45 OTH	SP	P		V	12/26/2117
2020 PO4831786226	LGE	3	45 OTH	SP	CCA		V	12/27/2117
2020 PO5439775349	LGE	3	45 OTH	SP	CCA		V	12/28/2117
2020 PO4830986232	LGE	4	40 OTH	SP	P	ED,ID,SRS	TD	12/29/2117
2020 PO5460475070	LGE	1	50 OTH	SP	CCA		V	12/30/2117
2020 PO4830986234	LGE	3	45 OTH	SP	P	ED,ID,SRS	TD	12/31/2117
2020 PO4831186233	LGE	4	45 OTH	SP	P	ED,ID,SRS	TD	1/1/2118
2020 PO4836686234	LGE	1	20 OTH	UN	P		V	1/2/2118
2020 PO4834086145	LGE	4	40 OTH	UN	CCA		V	1/3/2118
2020 PO4833286211	LGE	3	50 OTH	SP	P	ED,ID,SRS	TD	1/4/2118
2020 PV4836086185	LGE	3	45 OTH	SP	P	ED,ID,SRS	TD	1/5/2118
2020 PO4859286454	LGE	3	45 XXX	SP	P	ID	BD	1/6/2118
2020 PO4857686451	LGE	3	45 XXX	SP	P	ID	BD	1/7/2118
2020 PO4856386447	LGE	3	45 XXX	SP	CCA		V	1/8/2118
2020 PO4856286447	LGE	2	45 XXX	SP	P	ID	BD	1/9/2118
2020 PO4854886442	LGE	2	45 XXX	SP	P	ID	BD	1/10/2118
2020 PO4853486436	LGE	3	45 XXX	SP	CCA	ED	T	1/11/2118
2020 PO4851686431	LGE	2	45 XXX	SP	P	ID	BD	1/12/2118
2020 PO4837186176	LGE	4	40 OTH	SP	P	ED,SRS	TD	1/13/2118
2020 PO4837986162	LGE	4	40 OTH	SP	P	ED,SRS	TD	1/14/2118
2020 PO4838786162	LGE	1	20 OTH	UN	P		V	1/15/2118
2020 PO4851686456	LGE	4	40 XXX	SP	P	ID	BD	1/16/2118
2020 PO4850986452	LGE	2	50 XXX	SP	P	ED,ID	TX	1/17/2118
2020 PO5636877576	LGE	1	50 XXX	SP	CCA		V	1/18/2118
2020 PO5636877576A	LGE	5	25 XXX	SP	P	ID	TD	1/19/2118
2020 PO563507736	LGE	3	45 XXX	SP	CCA	ED	T	1/20/2118
2020 PO563507736A	LGE	4	30 XXX	SP	P	ID	TD	1/21/2118
2020 PO4849186476	LGE	1	55 XXX	SP	CCA		V	1/22/2118
2020 PO4849986463	LGE	1	55 XXX	SP	CCA		V	1/23/2118
2020 PO4836786194A	LGE	4	30 OTH	SP	P	ID	BD	1/24/2118
2020 PO4838886190A	LGE	4	30 OTH	SP	P	ID,SRS	BD	1/25/2118
2020 PO4838886190	F	2	55 OTH	SP	P		V	1/26/2118
2020 PO4836786194	F	2	55 OTH	SP	P		V	1/27/2118
2020 PO4835486206	F	3	50 OTH	SP	P		V	1/28/2118
2020 PO4843786195A	LGE	1	50 OTH	SP	CCA		V	1/29/2118
2020 PO4841186196	F	4	40 OTH	SP	P		V	1/30/2118
2020 PO4843786195	F	3	50 OTH	SP	P		V	1/31/2118
2020 PO4821686080	LGE	4	40 OTH	SP	P	ID	BD	2/1/2118

2020 PO4841386190	F	3	55 OTH	SP	P		V	2/2/2118
2020 PO4845686209	LGE	3	45 OTH	SP	CCA		V	2/3/2118
2020 PO4843886213	LGE	1	20 OTH	UN	S		V	2/4/2118
2020 PO4848086209	F	4	40 OTH	SP	P		V	2/5/2118
2020 PO4845886202	F	4	40 OTH	SP	P		V	2/6/2118
2020 PO4849986215	F	4	40 OTH	SP	P		V	2/7/2118
2020 PO4846186194	LGE	4	40 OTH	SP	P	ED,SRS	TD	2/8/2118
2020 PO4854686239	LGE	4	30 OTH	UN	CCA		V	2/9/2118
2020 PO4853986228	F	4	40 OTH	SP	P		V	2/10/2118
2020 PO4855886235	F	3	45 OTH	SP	CCA		V	2/11/2118
2020 PO4854786260	LGE	3	50 OTH	UN	CCA		V	2/12/2118
2020 PO4857086288	F	3	50 OTH	SP	P		V	2/13/2118
2020 PO4857786267	F	3	50 OTH	SP	P		V	2/14/2118
2020 PO4851986222	F	3	45 OTH	SP	P		V	2/15/2118
2020 PO4856286214	F	3	50 OTH	UN	CCA		V	2/16/2118
2020 PO4855386241	LGE	3	50 OTH	SP	CCA		V	2/17/2118
2020 PO4854186229	F	3	45 OTH	SP	P		V	2/18/2118
2020 PO4852286223	F	3	45 OTH	SP	P		V	2/19/2118
2020 PO4822286370	LGE	4	40 XXX	SP	P	ID	BD	2/20/2118
2020 PO4822286394	LGE	4	40 XXX	SP	P	ID	BD	2/21/2118
2020 PO4822286383	LGE	4	40 XXX	SP	P	ID	TD	2/22/2118
2020 PO4825786370	LGE	3	45 XXX	SP	CCA		V	2/23/2118
2020 PO4827586376	LGE	4	45 XXX	SP	CRE	ID	BD	2/24/2118
2020 PO4856086318	LGE	1	55 OTH	SP	CCA		V	2/25/2118
2020 PO5689676052	LGE	1	50 OTH	SP	CCA		V	2/26/2118
2020 PO4854686360	LGE	3	50 OTH	SP	P	ED,EP,ID,IP,SRC	X	RP3 2/27/2118
2020 PO4854686339	F	3	45 OTH	SP	P		V	2/28/2118
2020 PO5683776472	LGE	4	35 OTH	SP	CCA	ED,SRS	TD	3/1/2118
2020 PO4855586311	LGE	1	50 OTH	SP	CCA		V	3/2/2118
2020 PO4855186362	LGE	4	30 OTH	SP	P	ED,SRS	TD	3/3/2118
2020 PO4855386341	LGE	3	50 OTH	SP	P	ED,ID,SRS	TD	3/4/2118
2020 PO4824586417	LGE	4	40 XXX	SP	P	ID	TD	3/5/2118
2020 PO4823386414	LGE	4	40 XXX	SP	P	ID	TD	3/6/2118
2020 PO4822386407	LGE	4	40 XXX	SP	P	ID	TD	3/7/2118
2020 PO4825386380	LGE	4	40 XXX	SP	P	ID	TD	3/8/2118
2020 PO4823586369	LGE	4	40 XXX	SP	P	ID	TD	3/9/2118
2020 PO4824786371	LGE	4	40 XXX	SP	P	ID	TD	3/10/2118
2020 PO4826886375	LGE	4	40 XXX	SP	P	ID	TD	3/11/2118
2020 PO4828086378	LGE	4	40 XXX	SP	P	ID	TD	3/12/2118
2020 PO4832986409	LGE	4	45 XXX	SP	CCA		V	3/13/2118
2020 PO4827986323	LGE	2	45 XXX	SP	CCA		V	3/14/2118
2020 PO4889587489	LGE	4	40 OTH	SP	CCA		V	3/15/2118
2020 PO4896587486	LGE	3	45 BRO	SP	CCA		V	3/16/2118
2020 PO4899787480	LGE	4	40 OTH	SP	P	ED,ID,SRS	TD	3/17/2118
2020 PO4900187466	LGE	4	40 OTH	SP	P	ED,SRS	TD	3/18/2118
2020 PO4897987490	LGE	3	45 BRO	SP	CCA		V	3/19/2118
2020 PO4891887473	LGE	3	45 OTH	SP	CCA		V	3/20/2118

2020 PO4900587457	LGE	3	45 OTH	SP	CCA		V	3/21/2118
2020 PO4895187482	LGE	3	45 OTH	SP	CCA		V	3/22/2118
2020 PO4898887492	LGE	3	45 BRO	SP	CCA		V	3/23/2118
2020 PO4893187476	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	3/24/2118
2020 PO4899387490	LGE	3	45 BRO	SP	P	ED,ID,SRS	TD	3/25/2118
2020 PO4852286711	LGE	4	30 OTH	SP	CCA	ED,SRS	BD	3/26/2118
2020 PO4872886208	LGE	4	40 OTH	SP	CCA		V	3/27/2118
2020 PO4852786712	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	3/28/2118
2020 PO4873086169	LGE	4	40 OTH	SP	CRE	ED,ID,SRS	TD	3/29/2118
2020 PO4846686892	LGE	H1	100 XXX	AL	S		V	3/30/2118
2020 PO4863486892	LGE	1	50 XXX	SP	CCA		V	3/31/2118
2020 PO4865086889	LGE	3	45 XXX	SP	A	ID	BD	4/1/2118
2020 PO4865586896	LGE	4	40 XXX	SP	A	ED,ID	TD	4/2/2118
2020 PO4861486910	LGE	5	35 BRN	SP	CCA		V	4/3/2118
2020 PO4861686903	LGE	1	50 BRN	SP	CCA		V	4/4/2118
2020 PO4860786906	LGE	3	45 XXX	SP	A	ID	BD	4/5/2118
2020 PO4859386799	LGE	3	45 XXX	SP	CRE	ED,ID,IP	TD	4/6/2118
2020 PO4859786810	LGE	4	40 XXX	SP	A	ID	BD	4/7/2118
2020 PO4881087204	LGE	3	45 XXX	SP	A	ID	BD	4/8/2118
2020 PO4881187202	LGE	3	45 XXX	SP	A	ED,ID	TD	4/9/2118
2020 PO4882687164	LGE	3	45 XXX	SP	A	ID	BD	4/10/2118
2020 PO4884886855	LGE	4	45 XXX	SP	A	ID	BD	4/11/2118
2020 PO4885786825	LGE	5	30 XXX	SP	CCA		V	4/12/2118
2020 PO4885086823	LGE	3	45 XXX	SP	CCA		V	4/13/2118
2020 PO4885086806	LGE	3	45 XXX	SP	A	ED,ID,SRC	TX	RR 4/14/2118
2020 PO4885386794	LGE	3	45 XXX	SP	A	ID	BD	4/15/2118
2020 PO4884486794	LGE	5	30 XXX	SP	A	ED,ID,IP	TD	4/16/2118
2020 PO4878286833	LGE	5	40 XXX	SP	A	ID	BD	4/17/2118
2020 PO4875686886	LGE	3	50 XXX	SP	CCA		V	4/18/2118
2020 PO4847886858	LGE	4	35 XXX	SP	CCA		V	4/19/2118
2020 PO4841586796	LGE	4	30E XXX	SP	P		V	4/20/2118
2020 PO4678189177	LGE	5	30 XXX	SP	A	ED,ID	TD	4/21/2118
2020 PO4678689185	LGE	4	40 XXX	SP	A	ID	BD	4/22/2118
2020 PO4636988837	LGE	3	45 OTH	SP	CCA		V	4/23/2118
2020 PO4632288829	LGE	3	45 OTH	SP	CCA		V	4/24/2118
2020 PO4634888829	LGE	3	45 OTH	SP	CCA		V	4/25/2118
2020 PO4637588803	LGE	4	35 OTH	SP	CCA		V	4/26/2118
2020 PO4636188821	LGE	3	45 OTH	SP	CCA		V	4/27/2118
2020 PO4632088846	LGE	3	45 OTH	SP	CCA		V	4/28/2118
2020 PO4631688842	LGE	4	30 OTH	SP	CCA		V	4/29/2118
2020 PO4630588855	LGE	3	45 OTH	SP	CCA		V	4/30/2118
2020 PO4635188801	LGE	3	45 OTH	SP	CCA		V	5/1/2118
2020 PO4633988851	LGE	3	45 OTH	SP	CCA		V	5/2/2118
2020 PO4660789034	LGE	4	40 KOP	SP	S		V	5/3/2118
2020 PO4659089022	LGE	4	35 KOP	SP	CRE	ED,ID,IP	TD	5/4/2118
2020 PO4658689027	LGE	UNK	25 KOP	SP	S	ED	T	5/5/2118
2020 PO4657089015	LGE	UNK	25 KOP	SP	S		V	5/6/2118

2020 PO4657489010	LGE	4	40 KOP	SP	S		V	5/7/2118	
2020 PO4655188991	LGE	4	40 KOP	SP	CRE	ED,ID,IP	TD	5/8/2118	
2020 PO4653888992	LGE	4	30 KOP	SP	S		V	5/9/2118	
2020 PO4654388985	LGE	4	40 KOP	SP	CRE	ID	BD	5/10/2118	
2020 PO4652188980	LGE	4	30 KOP	SP	P	ED,ID	TD	5/11/2118	
2020 PO4679589180	LGE	4	40 XXX	SP	CRE	ID	BD	5/12/2118	
2020 PO4680689173	LGE	4	40 XXX	SP	A	ID	BD	5/13/2118	
2020 PO4681389179	LGE	4	40 XXX	SP	A	ED,ID	TD	5/14/2118	
2020 PO4627688846	LGE	3	45 OTH	SP	CCA		V	5/15/2118	
2020 PO4629588819	LGE	3	45 OTH	SP	CCA		V	5/16/2118	
2020 PO4627888867	LGE	4	35 OTH	SP	CCA		V	5/17/2118	
2020 PO4626788859	LGE	3	45 OTH	SP	CCA		V	5/18/2118	
2020 PO4631588823	LGE	4	35 OTH	SP	CCA		V	5/19/2118	
2020 PO4628688832	LGE	3	45 OTH	SP	CCA		V	5/20/2118	
2020 PO4630588804	LGE	3	45 OTH	SP	CCA		V	5/21/2118	
2020 PO4682489187	LGE	4	40 XXX	SP	A	ID	BD	5/22/2118	
2020 PO4683589196	LGE	4	40 XXX	SP	CRE	ID	BD	5/23/2118	
2020 PO4682989199	LGE	5	30 XXX	SP	A	ED,ID	TD	5/24/2118	
2020 PO4684089212	LGE	5	40 XXX	SP	CRE	ID	BD	5/25/2118	
2020 PO4683189216	LGE	5	30 XXX	SP	A	ED,ID	TD	5/26/2118	
2020 PO4634288753	LGE	3	45 OTH	SP	CCA		V	5/27/2118	
2020 PO4633288766	LGE	3	45 OTH	SP	CCA		V	5/28/2118	
2020 PO4631388793	LGE	3	45 OTH	SP	CCA		V	5/29/2118	
2020 PO4632288780	LGE	3	45 OTH	SP	CCA		V	5/30/2118	
2020 PO4652688972	LGE	4	40 KOP	SP	CRE	ED,ID	TD	5/31/2118	
2020 PO4635088741	LGE	3	45 OTH	SP	CCA		V	6/1/2118	
2020 PO4638588726	LGE	3	45 OTH	SP	CCA		V	6/2/2118	
2020 PO4635288742	LGE	3	45 OTH	SP	CCA		V	6/3/2118	
2020 PO4636588752	LGE	3	45 OTH	SP	CCA		V	6/4/2118	
2020 PO4641388746	LGE	3	45 OTH	SP	CCA		V	6/5/2118	
2020 PO4640188737	LGE	3	45 OTH	SP	CCA		V	6/6/2118	
2020 PO7351473819	KU	5	35 BRN	SP	CCA		V	6/7/2118	
2020 PO7348473780	KU	3	45 BRN	SP	CCA		V	6/8/2118	
2020 PO7356373730	KU	3	45 BRN	SP	CCA		V	6/9/2118	
2020 PO7366873700	KU	3	45 BRN	SP	CCA		V	6/10/2118	
2020 PO7379173665	KU	3	45 BRN	SP	CCA		V	6/11/2118	
2020 PO7388073637	KU	3	45 BRN	SP	CCA		V	6/12/2118	
2020 PO7381673820	KU	3	45 BRN	SP	CCA		V	6/13/2118	
2020 PO7386573953	KU	3	45 BRN	SP	CCA		V	6/14/2118	
2020 PO7389874131	KU	3	45 BRN	SP	CCA		V	6/15/2118	
2020 PO4529602688	KU	6	30 BRN	SP	CRE	ED,ID	TD	6/16/2118	
2020 PO4538102684	KU	4	45 BRN	SP	CRE	ED,ID	TD	6/17/2118	
2020 PO4551202746	KU	4	40 BRN	SP	CRE	ED,ID	TD	6/18/2118	
2020 PO4556802822	KU	6	30 BRN	SP	CCA		V	6/19/2118	
2020 PO4522202787	KU	2	55 BRN	SP	CRE	ED,EP,ID	TX	RR	6/20/2118
2020 PO4561302843	KU	6	30 XXX	SP	CRE		V	6/21/2118	
2020 PO4583202780	KU	6	30 XXX	SP	CRE	ID	TD	6/22/2118	

2020 PO7352874130	KU	4	45 BRN	SP	CRE		V	6/23/2118
2020 PO7355073978	KU	4	45 BRN	SP	CRE		V	6/24/2118
2020 PO7320373802	KU	4	45 BRN	SP	CCA		V	6/25/2118
2020 PO7327973963	KU	4	45 BRN	SP	CRE		V	6/26/2118
2020 PO7330474105	KU	4	45 BRN	SP	CCA		V	6/27/2118
2020 PO7332774239	KU	4	45 BRN	SP	CRE		V	6/28/2118
2020 PO7316674414	KU	4	45 BRN	SP	CCA		V	6/29/2118
2020 PO2828705657	KU	3	50 BRO	SP	CCA		V	6/30/2118
2020 PO2762306002	KU	5	35 BRO	SP	CRE	ID	TD	7/1/2118
2020 PO2809705780	KU	3	50 BRO	SP	CCA		V	7/2/2118
2020 PO2737605700	KU	6	30 BRO	SP	CRE		V	7/3/2118
2020 PO7506374070	KU	5	35 BRN	SP	CCA		V	7/4/2118
2020 PO7482674110	KU	5	35 BRN	SP	CCA		V	7/5/2118
2020 PO7463374143	KU	5	35 BRN	SP	CCA		V	7/6/2118
2020 PO7437674187	KU	5	35 BRN	SP	CCA		V	7/7/2118
2020 PO7414374227	KU	5	35 BRN	SP	CCA		V	7/8/2118
2020 PO7409274257	KU	3	45 BRN	SP	CCA		V	7/9/2118
2020 PO7399874264	KU	3	45 BRN	SP	CCA		V	7/10/2118
2020 PO7387774292	KU	4	45 BRN	SP	CCA		V	7/11/2118
2020 PO7374574313	KU	4	45 BRN	SP	CCA		V	7/12/2118
2020 PO7346174360	KU	4	45 BRN	SP	CCA		V	7/13/2118
2020 PO7359874335	KU	4	45 BRN	SP	CCA		V	7/14/2118
2020 PO7332374385	KU	4	45 BRN	SP	CCA		V	7/15/2118
2020 PO4587302662	KU	4	40 XXX	SP	CRE	ED,ID,SRS	TD	7/16/2118
2020 PO4572102616	KU	4	40 XXX	SP	CRE	ED,ID	TD	7/17/2118
2020 PO4556902565	KU	4	40 XXX	SP	CRE	ED,ID	TD	7/18/2118
2020 PO4508002420	KU	4	40 XXX	SP	CRE	ED,ID	TD	7/19/2118
2020 PO4527502475	KU	4	40 XXX	SP	CRE	ED,ID	TD	7/20/2118
2020 PO4525002373	KU	9	30 XXX	SP	CRE	ID	BD	7/21/2118
2020 PO4498002401	KU	6	30 XXX	SP	CRE	ID	BD	7/22/2118
2020 PO4543202522	KU	4	45 XXX	SP	CRE	ED,ID	TD	7/23/2118
2020 PO4545802447	KU	4	45 XXX	SP	CRE	ED,ID	TD	7/24/2118
2020 PO4537002335	KU	5	35 XXX	SP	CRE	ED,ID	TD	7/25/2118
2020 PO4527602312	KU	5	30 XXX	SP	CRE	ED,ID	TD	7/26/2118
2020 PO4515702224	KU	2	65 XXX	SP	CRE	ED,ID	TD	7/27/2118
2020 PO2731105677	KU	6	30 BRO	SP	CRE		V	7/28/2118
2020 PO2712905799	KU	5	35 BRO	SP	CRE	ID	TD	7/29/2118
2020 PO2745805841	KU	5	35 BRO	SP	CRE	ID	TD	7/30/2118
2020 PO2751505732	KU	4	40 BRO	SP	CRE	ID	TD	7/31/2118
2020 PO2755005660	KU	6	30 BRO	SP	CRE	ID	TD	8/1/2118
2020 PO6885886892	KU	5	30 BRO	SP	CRE	ED,ID	BD	8/2/2118
2020 PO6885886892	KU	5	35 BRO	SP	CRE	ID	BD	8/3/2118
2020 PO6891186953	KU	4	40 BRO	SP	A	ED,ID	BD	8/4/2118
2020 PO6884687186	KU	6	30 BRO	SP	CCA	ED	TD	8/5/2118
2020 PO6901987076	KU	4	40 BRO	SP	A	ED,ID	BD	8/6/2118
2020 PO2238555713	KU	4	45 BRO	SP	CCA		V	8/7/2118
2020 PO2281655533	KU	4	40 BRO	SP	CCA		V	8/8/2118

2020 PO2290455638	KU	5	35 BRO	SP	CCA		V		8/9/2118
2020 PO2254255600-A	KU	4	40 BRO	SP	CCA		V		8/10/2118
2020 PO2254255600	KU	4	40 BRO	SP	CCA		V		8/11/2118
2020 PO2220855785	F	4	40 BRO	SP	A		V		8/12/2118
2020 PO2170555403	F	4	45 BRO	SP	CCA		V		8/13/2118
2020 PO2180855670	F	4	45 BRO	SP	CCA		V		8/14/2118
2020 PO2207455892	F	4	40 BRO	SP	P		V		8/15/2118
2020 PO2200955891	F	3	40 BRO	SP	P		V		8/16/2118
2020 PO2196356027	F	4	40 BRO	SP	CRE		V		8/17/2118
2020 PO2192655983	F	3	45 BRO	SP	P		V		8/18/2118
2020 PO2182656285	KU	3	45 BRO	SP	CCA		V		8/19/2118
2020 PO2176756183	KU	3	45 BRO	SP	CCA		V		8/20/2118
2020 PO2179856065	F	4	40 BRO	SP	P		V		8/21/2118
2020 PO2183756106	F	4	40 BRO	SP	CRE		V		8/22/2118
2020 PO2169656196	F	4	40 BRO	SP	P		V		8/23/2118
2020 PO2166056153	F	4	40 BRO	SP	CCA		V		8/24/2118
2020 PO2155756217	F	4	40 BRO	SP	P		V		8/25/2118
2020 PO2089656290	KU	5	35 BRO	SP	CRE	ED,HH,ID	X	RP3	8/26/2118
2020 PO2106956292	KU	6	30 BRO	SP	CRE	EP	TD		8/27/2118
2020 PO2144756287	F	2	50 BRO	SP	P		V		8/28/2118
2020 PO2136156343	F	5	35E BRO	SP	CRE	ED,HH,ID	VX	RP2	8/29/2118
2020 PO2128356394	F	4	40 BRO	SP	CRE		V		8/30/2118
2020 PO2116656470	KU	2	50 BRO	SP	P		V		8/31/2118
2020 PO2099856182	KU	5	35 BRO	SP	CRE	ED,ID	TD		9/1/2118
2020 PO2128156082	KU	4	40 BRO	SP	CCA		V		9/2/2118
2020 PO2114355856	KU	4	40 BRO	SP	CCA		V		9/3/2118
2020 PO2139656696	KU	4	40 BRO	SP	CCA		V		9/4/2118
2020 PO2139456267	KU	4	40 BRO	SP	CCA		V		9/5/2118
2020 PO2102456564	F	4	50 BRO	SP	A		V		9/6/2118
2020 PO2094356616	F	2	50 BRO	SP	A		V		9/7/2118
2020 PO2084556679	F	2	50 BRO	SP	P		V		9/8/2118
2020 PO2069956771	F	2	50 BRO	SP	P		V		9/9/2118
2020 PO2051856886	F	2	50 BRO	SP	P		V		9/10/2118
2020 PO2037456975	F	2	50 BRO	SP	A		V		9/11/2118
2020 PO2023857061	F	2	50 BRO	SP	A		V		9/12/2118
2020 PO2009657152	F	2	50 BRO	SP	A		V		9/13/2118
2020 PO1951356932	KU	4	40 BRO	SP	CCA	ED	TD		9/14/2118
2020 PO1963157130	KU	4	40 BRO	SP	CCA	ED	TD		9/15/2118
2020 PO1997057235	F	4	40 BRO	SP	A		V		9/16/2118
2020 PO1979357346	F	2	50 BRO	SP	A		V		9/17/2118
2020 PO1974557319	KU	4	40 BRO	SP	CCA	ED	TD		9/18/2118
2020 PO1967357423	F	2	50 BRO	SP	A		V		9/19/2118
2020 PO1954857501	F	2	50 BRO	SP	CRE		V		9/20/2118
2020 PO1942057581	F	2	50 BRO	SP	A		V		9/21/2118
2020 PO1942057581-A	KU	2	50 BRO	SP	A		V		9/22/2118
2020 PO1902957646	KU	3	45 BRO	SP	CCA	ED	TD		9/23/2118
2020 PO1872857593	KU	4	40 BRO	SP	CRE		V		9/24/2118

2020 PO1868757400	KU	4	45 BRO	SP	CCA		V	9/25/2118
2020 PO1880457708	KU	4	40 BRO	SP	CCA		V	9/26/2118
2020 PO1898257571	KU	4	40 BRO	SP	CCA		B	9/27/2118
2020 PO1906957708	KU	4	45 BRO	SP	CCA	ED	TD	9/28/2118
2020 PO1929357664	F	3	45E BRO	SP	A		V	9/29/2118
2020 PO1916057750	F	3	40 BRO	SP	A		V	9/30/2118
2020 PO1901257845	F	4	40 BRO	SP	A		V	10/1/2118
2020 PO1888557918	F	4	40 BRO	SP	A		V	10/2/2118
2020 PO1875757988	F	4	40 BRO	SP	A		V	10/3/2118
2020 PO1863358054	F	4	40 BRO	SP	A		V	10/4/2118
2020 PO1781358029	KU	6	30 BRO	SP	CCA		V	10/5/2118
2020 PO1849758120	F	4	40 BRO	SP	A		V	10/6/2118
2020 PO1853258194	F	5	30 BRO	SP	A		V	10/7/2118
2020 PO1794558346	F	3	40 BRO	SP	A		V	10/8/2118
2020 PO1819858242	F	4	40 BRO	SP	CRE		V	10/9/2118
2020 PO1779358413	F	3	40 BRO	SP	A		V	10/10/2118
2020 PO1760058497	F	3	45E BRO	SP	A		V	10/11/2118
2020 PO1711558745	F	3	45E BRO	SP	A		V	10/12/2118
2020 PO0907024390	KU	3	45 ACE	SP	CCA		V	10/13/2118
2020 PO0927924385	KU	3	45 ACE	SP	CCA		V	10/14/2118
2020 PO0883824340	F	4	40 ACE	SP	CRE	ED,ID	V	10/15/2118
2020 PO0890224573	F	4	40 ACE	SP	CRE	ED,ID	V	10/16/2118
2020 PO0942725325	KU	4	45 ACE	SP	CCA		V	10/17/2118
2020 PO0912525203	F	4	40 ACE	SP	P		V	10/18/2118
2020 PO0851123534	F	4	40 ACE	SP	P		V	10/19/2118
2020 PO0861723800	F	4	40 ACE	SP	CRE		V	10/20/2118
2020 PO0933625728	F	4	40 ACE	SP	P		V	10/21/2118
2020 PO0952126184	F	4	40 ACE	SP	P		V	10/22/2118
2020 PO0886124419	KU	3	45 ACE	SP	CCA		V	10/23/2118
2020 PO0902124915	F	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	VX	10/24/2118
2020 PO0963926433	F	4	40 ACE	SP	P		V	10/25/2118
2020 PO0973326664	F	4	40 ACE	SP	CRE	ID	V	10/26/2118
2020 PO0989327055	F	4	40 ACE	SP	CRE		V	10/27/2118
2020 PO0989227243	F	4	40 ACE	SP	P		V	10/28/2118
2020 PO0989327433	F	4	40 ACE	SP	P		V	10/29/2118
2020 PO1028327456	F	4	40 ACE	SP	P		V	10/30/2118
2020 PO1068027475	F	4	40 ACE	SP	P		V	10/31/2118
2020 PO1091027480	F	4	40 ACE	SP	P		V	11/1/2118
2020 PO1035828030	KU	4	45 ACE	SP	CCA		V	11/2/2118
2020 PO1023628203	KU	4	45 ACE	SP	CCA		V	11/3/2118
2020 PO0998228155a	KU	4	40 ACE	SP	CCA		V	11/4/2118
2020 PO0998228155	KU	5	35 ACE	SP	CCA		V	11/5/2118
2020 PO1051228194	KU	4	40 ACE	SP	CRE		V	11/6/2118
2020 PO1066028682	KU	4	40 ACE	SP	CRE	ID	BD	11/7/2118
2020 PO1035528635	KU	4	40 ACE	SP	CRE	ED,ID	TD	11/8/2118
2020 PO1089528820	KU	4	40 ACE	SP	CRE	ID	BD	11/9/2118
2020 PO0988727831	F	4	40 ACE	SP	CRE	ED,ID	V	11/10/2118

2020 PO0989328263	F	4	40 ACE	SP	CCA		V	11/11/2118
2020 PO0991928734	F	4	40 ACE	SP	P		V	11/12/2118
2020 PO0998429133	F	4	40 ACE	SP	P		V	11/13/2118
2020 PO1008029704	F	4	40 ACE	SP	P		V	11/14/2118
2020 PO1016030177	F	4	40 ACE	SP	P		V	11/15/2118
2020 PO1022630292	F	4	35 ACE	SP	P		V	11/16/2118
2020 PO1042430203	KU	4	40 ACE	SP	CRE	ED,ID	TD	11/17/2118
2020 PO8643285563	KU	3	55 BRO	SP	CCA		V	11/18/2118
2020 PO8668986259	KU	4	45 BRO	SP	CCA		V	11/19/2118
2020 PO8678886456	KU	4	45 BRO	SP	CCA		V	11/20/2118
2020 PO8634385769	KU	5	35 BRO	SP	P	ID	BD	11/21/2118
2020 PO8656786016	KU	3	50 BRO	SP	P	ID	BD	11/22/2118
2020 PO8644085771	KU	3	45 BRO	SP	CCA		V	11/23/2118
2020 PO8656785712	KU	3	45 BRO	SP	CCA		V	11/24/2118
2020 PO8387478110	F	5	35 BRO	SP	A		V	11/25/2118
2020 PO8386777986	F	5	35 BRO	SP	A		V	11/26/2118
2020 PO8389077975	F	5	35 BRO	SP	CRE		V	11/27/2118
2020 PO8369477950	F	5	35 BRO	SP	CCA		V	11/28/2118
2020 PO8381977929	KU	5	35 BRO	SP	CRE	ID	BD	11/29/2118
2020 PO8386377918	F	4	40 BRO	SP	CCA		V	11/30/2118
2020 PO8385877829	F	4	40 BRO	SP	A		V	12/1/2118
2020 PO8381377804	KU	6	30 BRO	SP	CRE	ID	BD	12/2/2118
2020 PO8371177806	KU	6	30 BRO	SP	CRE	ID	BD	12/3/2118
2020 PO8385377725	KU	5	35 BRO	SP	CRE	ID	BD	12/4/2118
2020 PO8378677675	F	6	30 BRO	SP	CCA		V	12/5/2118
2020 PO8384877624	KU	5	35 BRO	SP	CRE	ID,IP	BD	12/6/2118
2020 PO7535374933	KU	6	30 BRO	SP	CRE	ED,ID	TD	12/7/2118
2020 PO7089184592	KU	4	45 BRO	SP	CCA	ED	B	12/8/2118
2020 PO7096784579	KU	3	45 BRO	SP	CCA		V	12/9/2118
2020 PO3207204831	KU	4	40 BRO	SP	CRE		V	12/10/2118
2020 PO3148204789	KU	4	40 BRO	SP	CRE		V	12/11/2118
2020 PO3131404784	KU	5	35 BRO	SP	CRE		V	12/12/2118
2020 PO3097804773	KU	5	35 BRO	SP	CRE		V	12/13/2118
2020 PO3060004794	KU	5	35 BRO	SP	CRE		V	12/14/2118
2020 PO3049604813	KU	5	35 BRO	SP	CRE		V	12/15/2118
2020 PO3027504844	KU	5	35 BRO	SP	CRE		V	12/16/2118
2020 PO3018304855	KU	4	40 BRO	SP	CRE		V	12/17/2118
2020 PO2905405154	KU	4	45 BRO	SP	CRE	ID	BD	12/18/2118
2020 PO2923305063	KU	3	55 BRO	SP	CRE	ID	BD	12/19/2118
2020 PO2942305017	KU	4	40 BRO	SP	CRE		V	12/20/2118
2020 PO2938204719	KU	4	40 BRO	SP	CRE	ID	TD	12/21/2118
2020 PO2933604673	KU	4	35 BRO	SP	CRE	ID	TD	12/22/2118
2020 PO2924504615	KU	4	40 BRO	SP	CRE	ID	TD	12/23/2118
2020 PO8419277954	F	4	40 BRO	SP	CRE		V	12/24/2118
2020 PO8410777960	F	5	35 BRO	SP	CRE		V	12/25/2118
2020 PO8403177965	F	4	40 BRO	SP	CRE		V	12/26/2118
2020 PO8639184608	F	4	40 BRO	SP	CRE		V	12/27/2118

2020 PO8633684391	KU	5	35 BRO	SP	CRE	ED,ID	TD	12/28/2118	
2020 PO8633884506	KU	5	35 BRO	SP	CCA	ED,ID	TD	12/29/2118	
2020 PO8639184790	F	4	45 BRO	SP	CCA		V	12/30/2118	
2020 PO8633684972	KU	3	55 BRO	SP	CCA		V	12/31/2118	
2020 PO8633784626	KU	5	35 BRO	SP	CRE	ED,ID	TD	1/1/2119	
2020 PO8633884810	KU	5	35 BRO	SP	CRE	ED,ID,IP,SRS	TD	1/2/2119	
2020 PO8627885196	F	3	45 BRO	SP	CRE		V	1/3/2119	
2020 PO8620085009	KU	4	40 BRO	SP	P	ID	BD	1/4/2119	
2020 PO8609285016	KU	4	40 BRO	SP	CRE	ID	BD	1/5/2119	
2020 PO8598585023	KU	6	30 BRO	SP	CCA	ED	V	1/6/2119	
2020 PO8614485288	F	4	40 BRO	SP	CRE		V	1/7/2119	
2020 PO8614785486	F	4	40 BRO	SP	A		V	1/8/2119	
2020 PO3221803952	KU	2	50 BRO	SP	CRE	ID	TD	1/9/2119	
2020 PO3204303866	KU	4	40 BRO	SP	CRE	ID	TD	1/10/2119	
2020 PO3086603813	KU	6	30 BRO	SP	CCA		V	1/11/2119	
2020 PO3180803991	KU	6	30 BRO	SP	CRE	ID	TD	1/12/2119	
2020 PO3991302783	KU	4	40 XXX	SP	CRE	ID	TD	1/13/2119	
2020 PO3957002819	KU	7	30 XXX	SP	CRE	ED,ID,SRS	TD	1/14/2119	
2020 PO3173703725	KU	6	30 BRO	SP	CCA		V	1/15/2119	
2020 PO3193203775	KU	4	45 BRO	SP	CRE	ID	TD	1/16/2119	
2020 PO3179903773	KU	4	40 BRO	SP	CRE	ID	TD	1/17/2119	
2020 PO3165203758	KU	4	40 BRO	SP	CRE	ID	TD	1/18/2119	
2020 PO3151103742	KU	4	40 BRO	SP	CRE	ID	TD	1/19/2119	
2020 PO3139303724	KU	4	40 BRO	SP	CRE	ID	TD	1/20/2119	
2020 PO3115703823	F	4	40 BRO	SP	CRE		V	1/21/2119	
2020 PO3124303705	KU	4	40 BRO	SP	CRE	ID	TD	1/22/2119	
2020 PO3123203809	KU	4	40 BRO	SP	CCA		V	1/23/2119	
2020 PO3110803689	KU	4	40 BRO	SP	CRE	ID	TD	1/24/2119	
2020 PO3107103738	KU	6	30 BRO	SP	CRE	ID	TD	1/25/2119	
2020 PO1911844855	KU	4	45 BRO	SP	CRE	HH,RB	X	PX	1/26/2119
2020 PO1926545031	KU	4	45 BRO	SP	CRE	ID	TD	1/27/2119	
2020 PO1948044921	F	4	40 BRO	SP	CRE		V	1/28/2119	
2020 PO1973645051	KU	6	40 BRO	SP	CRE	ID	TD	1/29/2119	
2020 PO1980344920	KU	4	45 BRO	SP	CRE	ID	TD	1/30/2119	
2020 PO1993445210	KU	4	45 BRO	SP	CRE	ID,IP	BD	1/31/2119	
2020 PO1966045203	KU	3	45 BRO	SP	CRE	ED,HH,ID	X	RP1	2/1/2119
2020 PO1944245117	KU	4	45 BRO	SP	CRE	ID	TD	2/2/2119	
2020 PO1905945627	KU	3	45 BRO	SP	CCA	ED	TD	2/3/2119	
2020 PO1920345792	KU	3	45 BRO	SP	CCA	ED	TD	2/4/2119	
2020 PO1913045713	KU	3	45 BRO	SP	CCA	ED	TD	2/5/2119	
2020 PO1927645872	KU	3	45 BRO	SP	CCA	ED	TD	2/6/2119	
2020 PO2223455412	KU	4	40 BRO	SP	CRE	ID,IP	TX	RR	2/7/2119
2020 PO2213555685	KU	4	40 BRO	SP	CRE	ID	BD	2/8/2119	
2020 PO0707015443	F	7	20 ACE	SP	CRE		V	2/9/2119	
2020 PO0694015911	KU	3	45 ACE	SP	CCA		V	2/10/2119	
2020 PO7530972931	KU	4	40 BRO	SP	P		B	2/11/2119	
2020 PO7121484428	KU	5	30 BRO	SP	CRE	ED,ID	TD	2/12/2119	

Business Use

2020 PO7353074883	KU	4	40 BRN	SP	CRE	ED,ID,IP	TD	2/13/2119	
2020 PO4003303246	KU	6	30 XXX	SP	CRE	ID	TD	2/14/2119	
2020 PO9277372818	KU	4	40 OTH	SP	CRE	ID	BD	2/15/2119	
2020 PO9317473092	KU	4	40 OTH	SP	CRE	ED,SRS	TD	2/16/2119	
2020 PO9481970752	KU	4	45 OTH	SP	CCA		V	2/17/2119	
2020 PO9465170728	KU	4	40 OTH	SP	CCA		V	2/18/2119	
2020 PO9490970808	KU	4	45 OTH	SP	CCA		V	2/19/2119	
2020 PO9456670724	KU	4	40 OTH	SP	CCA		V	2/20/2119	
2020 PO9496270843	KU	4	45 OTH	SP	CCA		V	2/21/2119	
2020 PO9300372971	KU	5	35 OTH	SP	P	ED,SRS	TD	2/22/2119	
2020 PO9275672864	KU	5	35 OTH	SP	CRE	ED,ID,RB	X	PX	2/23/2119
2020 PO9364272884	KU	5	30 XXX	SP	CRE	ED,ID	TD	2/24/2119	
2020 PO9351672770	KU	6	30 XXX	SP	CRE	ED,ID,RB	TX	RR	2/25/2119
2020 PO8314862138	KU	4	45 BRN	SP	CRE		B	2/26/2119	
2020 PO8306862265	KU	4	45 BRN	SP	CRE		B	2/27/2119	
2020 PO8327262424	KU	4	40 BRN	SP	CRE		B	2/28/2119	
2020 PO8292362411	KU	4	45 BRN	SP	CCA		V	3/1/2119	
2020 PO9361972835	KU	5	35 XXX	SP	CRE	ED,ID	TD	3/2/2119	
2020 PO8292362411A	KU	3	45 BRN	SP	CCA		V	3/3/2119	
2020 PO8283562582	KU	4	45 BRN	SP	CRE		V	3/4/2119	
2020 PO8228463281	KU	3	45 BRN	SP	CCA		V	3/5/2119	
2020 PO8230263323	KU	4	45 BRN	SP	CCA		V	3/6/2119	
2020 PO8232063298	KU	4	45 BRN	SP	CCA		V	3/7/2119	
2020 PO8241263135	KU	4	45 BRN	SP	CRE		V	3/8/2119	
2020 PO9355072650	KU	6	35 XXX	SP	CRE	ID	TD	3/9/2119	
2020 PO8243763134	KU	4	45 BRN	SP	CRE		V	3/10/2119	
2020 PO8234862821	KU	4	45 BRN	SP	CRE		B	3/11/2119	
2020 PO8252262953	KU	3	45 BRN	SP	CCA		V	3/12/2119	
2020 PO8264062853	KU	4	45 BRN	SP	CRE		B	3/13/2119	
2020 PO8270962867	KU	5	35 BRN	SP	CRE		B	3/14/2119	
2020 PO8268862789	KU	4	45 BRN	SP	CCA		V	3/15/2119	
2020 PO8273762724	KU	4	45 BRN	SP	CRE		B	3/16/2119	
2020 PO8246063684	KU	5	35 BRN	SP	CCA		V	3/17/2119	
2020 PO4675988973	LGE	4	40 BRO	SP	CRE	ID,IP	BD	3/18/2119	
2020 PO9252272738	KU	5	40 OTH	SP	CRE	ED,SRS	TD	3/19/2119	
2020 PO9378372817	KU	5	35 XXX	SP	CRE	ID	TD	3/20/2119	
2020 PO9367472739	KU	5	35 XXX	SP	CRE	ID	TD	3/21/2119	
2020 PO9378372817A	KU	5	35 XXX	SP	P	ED	T	3/22/2119	
2020 PO8269863869	KU	4	40 BRN	SP	CRE		B	3/23/2119	
2020 PO8261763804	KU	4	40 BRN	SP	CRE		B	3/24/2119	
2020 PO8255463716	KU	4	45 BRN	SP	CRE	ED,ID	BD	3/25/2119	
2020 PO8238263790	KU	5	35 BRN	SP	CCA		V	3/26/2119	
2020 PO4801887963	LGE	3	45 BRN	SP	CCA		V	3/27/2119	
2020 PO4801687972	LGE	4	40 BRN	SP	A	ED,ID	TD	3/28/2119	
2020 PO9254473024	KU	4	40 OTH	SP	CRE	ID	BD	3/29/2119	
2020 PO4678588966	LGE	4	35 BRO	SP	CRE	ID,IP	BD	3/30/2119	
2020 PO9275173114	KU	6	30 OTH	SP	P	ED,SRS	TD	3/31/2119	

2020 PO9267473117	KU	4	35 OTH	SP	CRE	ED,SRS	TD	4/1/2119
2020 PO4678288973	LGE	4	30 BRO	SP	CRE	ED,ID,IP	TD	4/2/2119
2020 PO8232664012	KU	3	45 BRN	SP	CCA		V	4/3/2119
2020 PO8232763866	KU	5	35 BRN	SP	CRE		V	4/4/2119
2020 PO8209963855A	KU	3	45 BRN	SP	CCA		V	4/5/2119
2020 PO8209963855	KU	5	35 BRN	SP	CCA		V	4/6/2119
2020 PO8209063605	KU	3	45 BRN	SP	CCA		V	4/7/2119
2020 PO8206363583	KU	3	45 BRN	SP	CCA		V	4/8/2119
2020 PO4801387982	LGE	4	40 BRN	SP	CRE	ED,ID	BD	4/9/2119
2020 PO4801887985	LGE	4	30 BRN	SP	S		V	4/10/2119
2020 PO4801087994	LGE	4	40 BRN	SP	A	ED,ID	BD	4/11/2119
2020 PO4800488012	LGE	3	45 BRN	SP	A	ED,ID	BD	4/12/2119
2020 PO9374472951	KU	5	30 XXX	SP	CRE	ID	TD	4/13/2119
2020 PO9391572912	KU	4	40 XXX	SP	CRE	ID,IP	BX	4/14/2119
2020 PO9385073005	KU	5	35 XXX	SP	CRE	ID	TD	4/15/2119
2020 PO9396372842	KU	5	35 XXX	SP	CRE	ID	BD	4/16/2119
2020 PO9405072682	KU	6	30 BRN	SP	P	ED	T	4/17/2119
2020 PO9401972730	KU	4	40 XXX	SP	CRE	ED,ID	TD	4/18/2119
2020 PO9390272507	KU	4	40 XXX	SP	CRE	ED,ID	TD	4/19/2119
2020 PO9405472495	KU	6	30 XXX	SP	P	ED	T	4/20/2119
2020 PO9383772600	KU	4	35 XXX	SP	CRE	ID	TD	4/21/2119
2020 PO9388772636	KU	4	35 XXX	SP	CRE	ID	TD	4/22/2119
2020 PO8218963478	KU	4	45 BRN	SP	CRE	ID	BD	4/23/2119
2020 PO9309373411	F	4	40 OTH	SP	CRE		V	4/24/2119
2020 PO9279573201	KU	4	40 OTH	SP	CRE	ED,SRS	TD	4/25/2119
2020 PO9284673382	KU	6	30 OTH	SP	P	ED,SRS	TD	4/26/2119
2020 PO9290973281	KU	4	40 OTH	SP	P	ED,SRS	TD	4/27/2119
2020 PO9318373472	KU	5	35 OTH	SP	CRE	ED,SRS	TD	4/28/2119
2020 PO9300473348	KU	4	40 OTH	SP	CRE	ED,SRS	TD	4/29/2119
2020 PO9277173343	KU	6	30 OTH	SP	CCA		V	4/30/2119
2020 PO4796288013	LGE	4	35 BRN	SP	CCA		V	5/1/2119
2020 PO4684488912	LGE	4	35 BRO	SP	A	ED	TD	5/2/2119
2020 PO8216163452	KU	3	45 BRN	SP	CCA		V	5/3/2119
2020 PO4797588031	LGE	4	35 BRN	SP	A	ED,ID	BD	5/4/2119
2020 PO4801088043	LGE	4	40 BRN	SP	A	ED,ID	BD	5/5/2119
2020 PO4799588044	F	3	45 BRN	SP	A		V	5/6/2119
2020 PO4799088039	LGE	3	45 BRN	SP	S		V	5/7/2119
2020 PO4823787745	LGE	4	40 BRO	SP	CRE	ED	BD	5/8/2119
2020 PO4823687746	LGE	4	40 BRO	SP	CRE	ED	BD	5/9/2119
2020 PO3946702294	LGE	4	40 BRO	SP	CCA		V	5/10/2119
2020 PO4800988071	LGE	4	30 BRN	SP	CRE	ED,ID	BD	5/11/2119
2020 PO4685188947	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	5/12/2119
2020 PO4808388055	LGE	4	40 BRN	SP	CCA		V	5/13/2119
2020 PO4829787795	F	2	55 BRO	SP	CCA		V	5/14/2119
2020 PO4829587792	F	3	50 BRO	SP	CRE		V	5/15/2119
2020 PO4828887780	F	3	50 BRO	SP	CCA		V	5/16/2119
2020 PO4827887763	F	UNK	45 BRO	SP	CRE	ED,ID	VX	5/17/2119

Business Use

2020 PO4828187768	F	UNK	45	BRO	SP	CRE	ED,ID	VX	RP3	5/18/2119
2020 PO4827087747	F	4	40	BRO	SP	CCA		V		5/19/2119
2020 PO4808288085	LGE	4	40	BRN	DF	A	ED,ID	BD		5/20/2119
2020 PO4806088079	LGE	4	45	BRN	SP	CCA		V		5/21/2119
2020 PO4803888077	LGE	4	30	BRN	SP	A	HH,ID	BD		5/22/2119
2020 PO4803988073	LGE	3H	45	BRN	SP	CCA		V		5/23/2119
2020 PO4829387779	LGE	4	40	BRO	SP	CRE	ED	TD		5/24/2119
2020 PO4801588065	LGE	3H	45	BRN	SP	CCA		V		5/25/2119
2020 PO4799488059	LGE	3H	45	BRN	SP	CCA		V		5/26/2119
2020 PO4798688057	LGE	4	40	BRN	SP	P	ED,ID,IP	BD		5/27/2119
2020 PO4829287763	LGE	4	40	BRO	SP	CRE	ED	TD		5/28/2119
2020 PO4829487777	LGE	4	30	BRO	SP	CRE	ED	TD		5/29/2119
2020 PO5406490918	LGE	4	35	BRO	SP	CCA		V		5/30/2119
2020 PO4829087773	LGE	4	35	BRO	SP	CRE	ED	TD		5/31/2119
2020 PO4685888922	LGE	4	40	BRO	SP	A	ED	TD		6/1/2119
2020 PO4798188074	LGE	4	40	BRN	SP	A	ED,ID	TD		6/2/2119
2020 PO4797788087	LGE	3	45	BRN	SP	CCA		V		6/3/2119
2020 PO4829287763-A	LGE	4	30	BRO	SP	CRE	ED	TD		6/4/2119
2020 PO4686688917	LGE	4	30	BRO	SP	A	ED	TD		6/5/2119
2020 PO4798688092	LGE	4	30	BRN	SP	CRE	ED,HH,ID	BX	RR	6/6/2119
2020 PO4797288104	LGE	4	40	BRN	SP	CRE	ED,ID	BD		6/7/2119
2020 PO4796888117	LGE	3	45	BRN	SP	CCA		V		6/8/2119
2020 PO4797388123	LGE	4	35	BRN	SP	A	ED,ID	BD		6/9/2119
2020 PO4796788124	LGE	4	35	BRN	SP	S		V		6/10/2119
2020 PO4833387949	LGE	4	35	BRO	SP	CRE	ED	BD		6/11/2119
2020 PO4833187945	LGE	UNK	45	BRO	SP	CRE	ED	BD		6/12/2119
2020 PO4833087943	LGE	UNK	45	BRO	SP	CRE	ED	TD		6/13/2119
2020 PO4681488898	LGE	4	40	BRO	SP	CRE	ED,ID,IP	TD		6/14/2119
2020 PO4794688147	LGE	4	45	BRN	SP	CRE	ED,ID	BD		6/15/2119
2020 PO4830987862	LGE	4	40	BRO	SP	CRE	ED	TD		6/16/2119
2020 PO4832187914	LGE	4	40	BRO	SP	CRE	ED	BD		6/17/2119
2020 PO5418391914-A	LGE	4	30	BRO	SP	CCA		V		6/18/2119
2020 PO4830887888	LGE	4	30	BRO	SP	CCA		V		6/19/2119
2020 PO4831387887	LGE	4	40	BRO	SP	CCA		VX	RP1	6/20/2119
2020 PO4795188131	LGE	3	45	BRN	SP	CCA		V		6/21/2119
2020 PO4830587831	LGE	3	45	BRO	SP	CCA		V		6/22/2119
2020 PO4810487826	LGE	UNK	95	BRO	SP	P		V		6/23/2119
2020 PO4743088170	F	4	40	BRO	SP	CCA		V		6/24/2119
2020 PO4744488176	F	4	40	BRO	SP	A		V		6/25/2119
2020 PO4812887606	LGE	4	35	BRN	SP	CRE	ED,ID	BD		6/26/2119
2020 PO4814487614	LGE	4	30	BRN	SP	CRE	ED,ID	BD		6/27/2119
2020 PO4828086328	LGE	4	30	XXX	SP	CCA		V		6/28/2119
2020 PO4829786455	F	4	45	XXX	SP	CCA		V		6/29/2119
2020 PO4815687620	LGE	4	30	BRN	SP	CRE	ED,ID	BD		6/30/2119
2020 PO4817087627	LGE	4	30	BRN	SP	CRE	ED,ID	BD		7/1/2119
2020 PO4818687635	LGE	4	30	BRN	SP	CRE	ED,ID	BD		7/2/2119
2020 PO4818787641	LGE	4	30	BRN	SP	CCA		V		7/3/2119

2020 PO4818187652	LGE	4	35 BRN	SP	A	ED,ID	BD	7/4/2119	
2020 PO4742988116	F	4	40 BRO	SP	CRE		V	7/5/2119	
2020 PO4739288108	LGE	4	30 BRO	SP	CRE	ED	TD	7/6/2119	
2020 PO4738788118	F	4	40 BRO	SP	CCA		V	7/7/2119	
2020 PO4739088105	F	3	45 BRO	SP	CCA		V	7/8/2119	
2020 PO4738488133	F	4	40 BRO	SP	CRE		V	7/9/2119	
2020 PO4813287645	LGE	4	30 BRN	SP	CRE	ED,ID	BD	7/10/2119	
2020 PO4812487641	LGE	4	40 BRN	SP	A	ED,ID	BD	7/11/2119	
2020 PO4812187646	LGE	4	30 BRN	SP	CRE	ED,HH,ID	BX	RR	7/12/2119
2020 PO4872886696	LGE	4	40 OTH	SP	P	ED,SRS	TD	7/13/2119	
2020 PO4862486711	LGE	3	45 OTH	SP	P	ED,ID,SRS	TD	7/14/2119	
2020 PO4863786690	LGE	6	25 OTH	SP	CRE	ED,ID,SRS	TD	7/15/2119	
2020 PO4861786707	LGE	4	35 OTH	SP	P	ED,ID,SRS	TD	7/16/2119	
2020 PO4744888016	F	4	40 BRO	SP	CCA		V	7/17/2119	
2020 PO4814287650	LGE	4	30 BRN	SP	CRE	ED,ID	BD	7/18/2119	
2020 PO4815187655	LGE	4	30 BRN	SP	CRE	ED,ID	BD	7/19/2119	
2020 PO4739888038	F	3	45 BRO	SP	CCA		V	7/20/2119	
2020 PO4738688005-A	LGE	5	30 BRO	SP	CRE		V	7/21/2119	
2020 PO4738688005	LGE	4	30 BRO	SP	CRE	ED,ID	BD	7/22/2119	
2020 PO4919687230	F	4	35 OTH	SP	P		V	7/23/2119	
2020 PO4738288036	F	4	40 BRO	SP	CRE		V	7/24/2119	
2020 PO4736388033	F	4	40 BRO	SP	CRE		V	7/25/2119	
2020 PO4740588026	F	3	45 BRO	SP	CCA		V	7/26/2119	
2020 PO4817587665	LGE	4	35 BRN	SP	CRE	ED,ID	BD	7/27/2119	
2020 PO4817287664	LGE	4	30 BRN	SP	CRE	ED,ID	BD	7/28/2119	
2020 PO4816187659	LGE	4	30 BRN	SP	CRE	ED,ID	BD	7/29/2119	
2020 PO4901587234	LGE	4	40 OTH	SP	CRE	ED,ID,SR	TX	RR	7/30/2119
2020 PO4817087675	LGE	1	35 BRN	SP	CCA		V	7/31/2119	
2020 PO4863486695	LGE	3	40 OTH	SP	P	ED,ID,SRS	TD	8/1/2119	
2020 PO4867686696	LGE	5	35 OTH	SP	CRE	ED,SRS	TD	8/2/2119	
2020 PO4816487687	LGE	4	30 BRN	SP	CRE	ED,ID	BD	8/3/2119	
2020 PO4680189119	LGE	4	30 BRO	SP	A	ED	TD	8/4/2119	
2020 PO4678589111	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	8/5/2119	
2020 PO4731488059	F	4	35 BRO	SP	CRE		V	8/6/2119	
2020 PO4731988060	F	4	40 BRO	SP	CRE		V	8/7/2119	
2020 PO4732288029	F	4	40 BRO	SP	CRE		V	8/8/2119	
2020 PO4732088073	F	4	40 BRO	SP	CRE		V	8/9/2119	
2020 PO4731988053	F	4	40 BRO	SP	CRE		V	8/10/2119	
2020 PO4732088088	F	4	40 BRO	SP	CRE		V	8/11/2119	
2020 PO4732088040	F	4	40 BRO	SP	CRE		V	8/12/2119	
2020 PO4732488015	F	4	40 BRO	SP	CRE		V	8/13/2119	
2020 PO4732788000	F	4	40 BRO	SP	CRE		VX	RP2	8/14/2119
2020 PO4732987990	F	4	40 BRO	SP	CCA		V	8/15/2119	
2020 PO4740987918	F	4	40 BRO	SP	CRE		V	8/16/2119	
2020 PO4733987974	F	4	40 BRO	SP	CRE		V	8/17/2119	
2020 PO4734887958	F	4	40 BRO	SP	CRE		V	8/18/2119	
2020 PO4735787923	F	4	40 BRO	SP	CRE		V	8/19/2119	

2020 PO4735887943	F	4	30 BRO	SP	CRE		V	8/20/2119	
2020 PO4735287942	F	4	40 BRO	SP	CCA		V	8/21/2119	
2020 PO4738287921	F	4	40 BRO	SP	CCA		V	8/22/2119	
2020 PO4736987922	F	4	40 BRO	SP	CRE		V	8/23/2119	
2020 PO4739387920	F	3	45 BRO	SP	CRE		V	8/24/2119	
2020 PO4741587969	F	3	45 BRO	SP	CCA		V	8/25/2119	
2020 PO4740888009	F	3	45 BRO	SP	CCA		V	8/26/2119	
2020 PO4740988000	F	4	40 BRO	SP	CCA		V	8/27/2119	
2020 PO4741287988	F	4	40 BRO	SP	CCA		V	8/28/2119	
2020 PO4741887955	F	3	45 BRO	SP	CCA		V	8/29/2119	
2020 PO4742087942	F	3	45 BRO	SP	CCA		V	8/30/2119	
2020 PO4741287939	F	4	30 BRO	SP	CRE		V	8/31/2119	
2020 PO4682189151	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	9/1/2119	
2020 PO4738887940	F	4	40 BRO	SP	CCA		V	9/2/2119	
2020 PO4738587953	F	4	40 BRO	SP	CCA		V	9/3/2119	
2020 PO4738087970	F	4	40 BRO	SP	CRE		V	9/4/2119	
2020 PO4737787978	F	4	40 BRO	SP	CRE		V	9/5/2119	
2020 PO4737587987	F	4	40 BRO	SP	CRE		V	9/6/2119	
2020 PO4737287999	F	4	40 BRO	SP	CRE		V	9/7/2119	
2020 PO4901187245	LGE	2E	50E	OTH	SP	CRE	ID	BD	9/8/2119
2020 PO4815687694	LGE	4	40 BRN	SP	CRE	ED,ID	BD	9/9/2119	
2020 PO4814587689	LGE	4	40 BRN	SP	CRE	ED,ID	BD	9/10/2119	
2020 PO4813887686	LGE	4	35 BRN	SP	A	ED,HH,ID	BX	RP3	9/11/2119
2020 PO4813887686	LGE	4	40 BRN	SP	CRE	ED,ID	BD	9/12/2119	
2020 PO4899687240	LGE	4	40 OTH	SP	P	ED,ID,RB	X	RP3	9/13/2119
2020 PO4872787446	LGE	4	40 XXX	SP	CCA		V	9/14/2119	
2020 PO4877287382	LGE	4	40 XXX	SP	A	ID	BD	9/15/2119	
2020 PO4898487237	LGE	4	40 OTH	SP	P	ID	BD	9/16/2119	
2020 PO4898187239	LGE	4	40 OTH	SP	CCA		V	9/17/2119	
2020 PO4897687252	LGE	3	45 OTH	SP	CCA		V	9/18/2119	
2020 PO4811587675	LGE	4	40 BRN	SP	CRE	ED,ID	BD	9/19/2119	
2020 PO4810387672	LGE	4	40 BRN	SP	CRE	ED,ID	TD	9/20/2119	
2020 PO4831086578	LGE	4	30 XXX	SP	CCA		V	9/21/2119	
2020 PO4829086591	LGE	4	40 XXX	SP	P	ID	TD	9/22/2119	
2020 PO4873186697	F	1	50 OTH	SP	CCA		V	9/23/2119	
2020 PO4870986665	LGE	5	30 OTH	SP	CRE	ED,ID	BD	9/24/2119	
2020 PO4873486685	F	1	50 OTH	SP	CCA		V	9/25/2119	
2020 PO4872886671	LGE	4	30 OTH	SP	CRE	ED,ID,SRS	TD	9/26/2119	
2020 PO4874486648	F	1	50 OTH	SP	CCA		V	9/27/2119	
2020 PO4874086660	F	1	50 OTH	SP	CCA		V	9/28/2119	
2020 PO4873786673	F	2	55 OTH	SP	CCA		V	9/29/2119	
2020 PO4874786633	F	1	55 OTH	SP	CCA		V	9/30/2119	
2020 PO4895487322	LGE	4	40 OTH	SP	CCA		V	10/1/2119	
2020 PO6062186338	LGE	4	40 OTH	SP	P	ID	BD	10/2/2119	
2020 PO4895987307	LGE	4	40 OTH	SP	CRE	ID,IP	BD	10/3/2119	
2020 PO4896587286	LGE	4	40 OTH	SP	CRE	ID	BD	10/4/2119	
2020 PO4897187268	LGE	3	45 OTH	SP	CCA		V	10/5/2119	

2020 PO4676989102	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	10/6/2119	
2020 PO4679589163	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	10/7/2119	
2020 PO4674889156	LGE	4	40 BRO	SP	CRE	ID,IP	BD	10/8/2119	
2020 PO4673889166	LGE	4	40 BRO	SP	CRE	ID,IP	BD	10/9/2119	
2020 PO4677289111	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	10/10/2119	
2020 PO4677789137	LGE	4	30 BRO	SP	A	ED	TD	10/11/2119	
2020 PO4677189133	LGE	3	45 BRO	SP	CRE	ED,ID,IP	TD	10/12/2119	
2020 PO4808187697	LGE	4	40 BRN	SP	CRE	ED,ID	BD	10/13/2119	
2020 PO4675689148	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD	10/14/2119	
2020 PO4678089150	LGE	4	40 BRO	SP	P	ED	T	10/15/2119	
2020 PO4833086583	LGE	1	55 XXX	SP	P	ID	BD	10/16/2119	
2020 PO4809587704	LGE	4	40 BRN	SP	CRE	ED,ID	TD	10/17/2119	
2020 PO4812987720	LGE	4	40 BRN	SP	CRE	ED,ID	BD	10/18/2119	
2020 PO4811687714	LGE	4	40 BRN	SP	CRE	ED,ID	BD	10/19/2119	
2020 PO4810487708	LGE	4	40 BRN	SP	CRE	ED,ID,IP	BD	10/20/2119	
2020 PO4879487383	LGE	4	40 XXX	SP	A		V	10/21/2119	
2020 PO4875186618	LGE	1	60 OTH	SP	CCA		V	10/22/2119	
2020 PO4873186613	LGE	1	50 OTH	SP	CCA		V	10/23/2119	
2020 PO4874486617	LGE	1	55 OTH	SP	CCA		V	10/24/2119	
2020 PO4874386621	LGE	4	35 OTH	SP	CCA	ED,SRS	TD	10/25/2119	
2020 PO2895303734	KU	5	35 BRO	SP	CRE	ID	TD	10/26/2119	
2020 PO2931903626	KU	6	30 BRO	SP	CRE	ID	TD	10/27/2119	
2020 PO3335404581	KU	6	30 BRO	SP	CRE	ID	TD	10/28/2119	
2020 PO3878305431	KU	4	40 XXX	SP	CRE	ED,ID,IP,SRC	TX	RR	10/29/2119
2020 PO3864705334	KU	4	40 XXX	SP	CRE	ED,ID	TD	10/30/2119	
2020 PO3325004589	KU	6	30 BRO	SP	CRE	ID	TD	10/31/2119	
2020 PO3303604585	KU	5	35 BRO	SP	CRE	ID	TD	11/1/2119	
2020 PO3290804647	KU	6	30 BRO	SP	CRE		V	11/2/2119	
2020 PO3270304678	KU	6	30 BRO	SP	CRE	ID	TD	11/3/2119	
2020 PO3270304452	KU	4	40 BRO	SP	A	ID	TD	11/4/2119	
2020 PO3266804317	KU	6	30 BRO	SP	CRE	ID	TD	11/5/2119	
2020 PO3259304459	KU	6	30 BRO	SP	CRE		V	11/6/2119	
2020 PO3261404383	KU	4	40 BRO	SP	CRE	ID	TD	11/7/2119	
2020 PO3247504416	KU	6	30 BRO	SP	CRE	ID	BD	11/8/2119	
2020 PO3249904314	KU	4	40 BRO	SP	CRE	ID	TD	11/9/2119	
2020 PO3258004144	KU	4	45 BRO	SP	CCA		V	11/10/2119	
2020 PO3272004266	KU	4	45 BRO	SP	CCA		V	11/11/2119	
2020 PO3851105123	KU	5	30 XXX	SP	CRE	ED,ID,IP	TD	11/12/2119	
2020 PO3853205008	KU	4	45 XXX	SP	CRE	ED,ID	TD	11/13/2119	
2020 PO3852204905	KU	6	30 XXX	SP	CCA		V	11/14/2119	
2020 PO3832504944	KU	5	30 XXX	SP	CRE	ED,ID	TD	11/15/2119	
2020 PO3835004771	KU	5	35 XXX	SP	CRE	ED,ID	TD	11/16/2119	
2020 PO3841704842	KU	4	40 XXX	SP	CRE	ED,ID	TD	11/17/2119	
2020 PO2746466471	F	2	50 BRO	SP	P		V	11/18/2119	
2020 PO2741166324	F	2	50 BRO	SP	P		V	11/19/2119	
2020 PO2655064781	F	2	60E BRO	SP	CRE		V	11/20/2119	
2020 PO2670665172	F	2	55E BRO	SP	CRE		V	11/21/2119	

2020 PO2685665568	F	2	50 BRO	DF	A		V	11/22/2119
2020 2685665568-A	F	5	35 BRO	SP	CCA		V	11/23/2119
2020 PO2702465936	F	2	50 BRO	SP	P		V	11/24/2119
2020 PO2710166079	F	2	50 BRO	SP	P		V	11/25/2119
2020 PO2718866218	F	2	50 BRO	SP	A		V	11/26/2119
2020 PO2743166740	F	4	40 BRO	SP	A		V	11/27/2119
2020 PO2770467196	F	3	35 BRO	SP	P		V	11/28/2119
2020 PO2764567173	F	5	35 BRO	SP	P		V	11/29/2119
2020 PO2782767345	F	5	35E BRO	SP	P		V	11/30/2119
2020 PO2807667702	F	6	30 BRO	SP	CRE		V	12/1/2119
2020 PO2805667651	KU	5	35E BRO	SP	CRE	ID	TD	12/2/2119
2020 PO2806967580	F	2	50 BRO	SP	P		V	12/3/2119
2020 PO2832167629	KU	4	40 BRO	SP	CCA		V	12/4/2119
2020 PO2867667750	F	2	50 BRO	SP	P		V	12/5/2119
2020 PO2868767761	F	2	50 BRO	SP	P		V	12/6/2119
2020 PO2879467821	F	2	50 BRO	SP	P		V	12/7/2119
2020 PO2888467885	F	2	50 BRO	SP	P		V	12/8/2119
2020 PO2895967986	F	3	50 BRO	SP	P		V	12/9/2119
2020 PO2905168113	F	3	50 BRO	SP	P		V	12/10/2119
2020 PO2911668226	F	2	50 BRO	SP	P		V	12/11/2119
2020 PO2906068426	KU	4	40 BRO	SP	CCA		V	12/12/2119
2020 PO2919568389	F	3	45 BRO	SP	P		V	12/13/2119
2020 PO2926568576	F	3	45 BRO	SP	P	IP	V	12/14/2119
2020 PO2932868728	F	3	45 BRO	SP	P		V	12/15/2119
2020 PO8862290281	KU	2	60 ACE	SP	CCA		V	12/16/2119
2020 PO8850790253	KU	2	60 ACE	SP	CCA		V	12/17/2119
2020 PO8794390509	KU	4	40 ACE	SP	CCA		V	12/18/2119
2020 PO8821590382	KU	2	60 ACE	SP	CCA		V	12/19/2119
2020 PO8802189898	KU	3	55 ACE	SP	CCA		V	12/20/2119
2020 PO8797085263	KU	4	45 ACE	SP	CRE		V	12/21/2119
2020 PO8776888034	KU	3	55 ACE	SP	CCA		V	12/22/2119
2020 PO8765887888	KU	5	35 ACE	SP	CCA		V	12/23/2119
2020 PO8776087840	KU	2	60 ACE	SP	CCA		V	12/24/2119
2020 PO8319791393	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	12/25/2119
2020 PO8265791765	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD	12/26/2119
2020 PO8648082647	F	4	40 BRO	SP	CRE		V	12/27/2119
2020 PO8535479704	F	6	30 BRO	SP	A		V	12/28/2119
2020 PO8743887612	KU	4	45 ACE	SP	CCA		V	12/29/2119
2020 PO8733887612	KU	5	35 ACE	SP	CCA		V	12/30/2119
2020 PO8784289017	KU	3	55 ACE	SP	CCA		V	12/31/2119
2020 PO8790589451	KU	3	55 ACE	SP	CCA		V	1/1/2120
2020 PO8780288519	KU	3	55 ACE	SP	CCA		V	1/2/2120
2020 PO8782788809	KU	3	55 ACE	SP	CCA		V	1/3/2120
2020 PO8782884948	KU	4	45 ACE	SP	CRE		V	1/4/2120
2020 PO8593389578	KU	4	40 ACE	SP	CRE	ED,ID	TD	1/5/2120
2020 PO8491889434	KU	4	40 ACE	SP	CRE	ED,ID	BD	1/6/2120
2020 PO8494789681	KU	4	35 ACE	SP	CRE	ED,ID	BD	1/7/2120

2020 PO8532889995	KU	4	40 ACE	SP	CCA		V		1/8/2120
2020 PO8467890180	KU	6	30 ACE	SP	CRE	ED,ID,IP	TD		1/9/2120
2020 PO8480290327	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD		1/10/2120
2020 PO8369391055	KU	4	40 ACE	SP	CRE	ED,ID,IP	TD		1/11/2120
2020 PO8344591226	KU	5	35 ACE	SP	CRE	ED,ID,IP	TD		1/12/2120
2020 PO8445890555	KU	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	X	PX	1/13/2120
2020 PO8406790810	KU	4	40 ACE	SP	CRE	ED,EP,HH,ID,IP,RB	X	RP1	1/14/2120
2020 PO8293591568	KU	4	40 ACE	SP	CRE	ED,EP,ID	X	RP1	1/15/2120
2020 PO9753886197	KU	5	35 BRO	SP	CRE	ED,ID,IP	TD		1/16/2120
2020 PO8640082457	F	4	40 BRO	SP	CRE		V		1/17/2120
2020 PO8635482358	F	4	40 BRO	SP	CRE		V		1/18/2120
2020 PO8634982157	F	4	40 BRO	SP	CRE		V		1/19/2120
2020 PO8634981972	F	4	40 BRO	SP	CRE		V		1/20/2120
2020 PO8655681893	F	4	40 BRO	SP	CRE		VX	RP2	1/21/2120
2020 PO9763085946	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		1/22/2120
2020 PO9773885687	KU	4	40 BRO	SP	CRE	ED,ID	TD		1/23/2120
2020 PO9785385415	KU	4	40 BRO	SP	CRE	ED,ID,IP	TD		1/24/2120
2020 PO8536479509	KU	5	35 BRO	SP	CRE	EP,ID,IP	TD		1/25/2120
2020 PO8533979406	KU	6	30 BRO	SP	CRE	ED	TD		1/26/2120
2020 PO8550879696	F	5	35 BRO	SP	CRE		V		1/27/2120
2020 PO8554279827	KU	6	30 BRO	SP	CRE	ID	BD		1/28/2120
2020 PO8554979863	KU	6	30 BRO	SP	CCA		V		1/29/2120
2020 PO8687882068	F	4	40 BRO	SP	CRE		V		1/30/2120
2020 PO8687782258	F	4	40 BRO	SP	CRE		V		1/31/2120
2020 PO8687582456	F	4	40 BRO	SP	A		V		2/1/2120
2020 PO8687782535	F	4	40 BRO	SP	A		V		2/2/2120
2020 PO8663481864	F	4	40 BRO	SP	CRE		V		2/3/2120
2020 PO8755581120	KU	4	40 BRO	SP	CRE	ED,ID,IP,SRC,SRS	TD		2/4/2120
2020 PO8530279434	KU	5	35 BRO	SP	CCA		V		2/5/2120
2020 PO8372380823	KU	6	30 BRO	SP	CCA		V		2/6/2120
2020 PO8364380973	KU	3	45 BRO	SP	CRE	ID,IP	BD		2/7/2120
2020 PO8363080781	KU	3	45 BRO	SP	CRE	HH,RB	X	RP1	2/8/2120
2020 PO8362180663	F	3	45 BRO	SP	CRE		V		2/9/2120
2020 PO8369780613	KU	6	30 BRO	SP	CCA		V		2/10/2120
2020 PO8360880483	F	3	50 BRO	SP	CRE		V		2/11/2120
2020 PO8396881078	KU	6	30 BRO	SP	P		T		2/12/2120
2020 PO8445181172	F	4	40 BRO	SP	CCA		V		2/13/2120
2020 PO8454281164	F	4	40 BRO	SP	A		V		2/14/2120
2020 PO8465381233	F	4	40 BRO	SP	A		V		2/15/2120
2020 PO8709881277	KU	4	40 BRO	SP	CRE	ED,ID,SRS	TD		2/16/2120
2020 PO8694581334	KU	4	40 BRO	SP	CRE	ED,ID,RB,SRC	TD		2/17/2120
2020 PO8770781067	KU	4	40 BRO	SP	CRE	ID	BD		2/18/2120
2020 PO8740381169	KU	4	40 BRO	SP	CRE		BD		2/19/2120
2020 PO8725081222	KU	4	40 BRO	SP	CRE	ID	BD		2/20/2120
2020 PO8678481387	F	4	40 BRO	SP	CRE		V		2/21/2120
2020 PO8444281450	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD		2/22/2120
2020 PO8402381503	F	4	40 BRO	SP	CRE		V		2/23/2120

2020 PO8403081573	F	5	35 BRO	SP	CRE		V	2/24/2120	
2020 PO8407481500	KU	6	30 BRO	SP	CRE	EP	TD	2/25/2120	
2020 PO8421481372	KU	5	35 BRO	SP	P	ED	T	2/26/2120	
2020 PO8429881189	F	4	40 BRO	SP	CRE		V	2/27/2120	
2020 PO8414881207	F	4	40 BRO	SP	CRE		V	2/28/2120	
2020 PO8413281059	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	2/29/2120	
2020 PO8665181647	KU	6	30 BRO	SP	CRE	ED,ID,SRS	TD	3/1/2120	
2020 PO8646381711	KU	6	30 BRO	SP	CRE	ED,ID,IP	TD	3/2/2120	
2020 PO8658481456	F	4	40 BRO	SP	CRE		V	3/3/2120	
2020 PO8603581637	F	4	40 BRO	SP	CRE		V	3/4/2120	
2020 PO8640381514	F	3	45 BRO	SP	CRE		V	3/5/2120	
2020 PO8621281578	F	4	40 BRO	SP	CRE		V	3/6/2120	
2020 PO4772388062	LGE	UNK	45 BRO	SP	CRE	ED,ID,IP	BD	3/7/2120	
2020 PO4772988045	LGE	UNK	45 BRO	SP	CRE	ED	BD	3/8/2120	
2020 PO4774388008	LGE	UNK	45 BRO	SP	CRE	ED	BD	3/9/2120	
2020 PO4773688027	LGE	UNK	45 BRO	SP	CRE	ED	BD	3/10/2120	
2020 PO4807287768	LGE	4	40 BRN	SP	CRE	ED,ID	TD	3/11/2120	
2020 PO4830386530	F	3	45 XXX	SP	CRE		V	3/12/2120	
2020 PO5431878261	LGE	3	45 XXX	SP	CCA		V	3/13/2120	
2020 PO4830586511	F	3	45 XXX	SP	CRE		V	3/14/2120	
2020 PO4829886499	LGE	4	30 XXX	SP	CRE	ID	TD	3/15/2120	
2020 PO4830186498	F	3	45 XXX	SP	P		V	3/16/2120	
2020 PO4830086492	LGE	3	45 XXX	SP	P		T	3/17/2120	
2020 PO4829986483	F	3	45 XXX	SP	P		V	3/18/2120	
2020 PO4829486464	F	2	50 XXX	SP	P		V	3/19/2120	
2020 PO4826286466	LGE	4	30 XXX	SP	A	ED,ID	T	3/20/2120	
2020 PO4827986472	LGE	3	45 XXX	SP	CCA		V	3/21/2120	
2020 PO4677189143	LGE	4	30 BRO	SP	A	ED,ID,IP	TD	3/22/2120	
2020 PO4883987474	LGE	4	35 XXX	SP	A	ED,ID	TD	3/23/2120	
2020 PO4886487481	LGE	3	45 XXX	SP	CRE	ED,ID	TD	3/24/2120	
2020 PO4805887761	LGE	3	45 BRN	SP	CCA		V	3/25/2120	
2020 PO4806387794	LGE	4	35 BRN	SP	A		V	3/26/2120	
2020 PO4805787771	LGE	3	45 BRN	SP	CCA		V	3/27/2120	
2020 PO4805687777	LGE	4	40 BRN	SP	A		V	3/28/2120	
2020 PO4805287791	LGE	4	40 BRN	SP	CRE		V	3/29/2120	
2020 PO4908287205	LGE	3	45 OTH	SP	P	ED,ID,SRS	TD	3/30/2120	
2020 PO4915187247	LGE	4	30 BRN	SP	CRE	ED,ID,SRC	TX	RR	3/31/2120
2020 PO4908387199	LGE	4	40 OTH	SP	P	ED,ID,SRC	TX	RR	4/1/2120
2020 PO4908487194	LGE	4	30 OTH	SP	P	ED,ID,SRS	TD	4/2/2120	
2020 PO6199685190	LGE	3	45 OTH	SP	CCA		V	4/3/2120	
2020 PO5950777352	LGE	1	50 OTH	SP	CCA		V	4/4/2120	
2020 PO5925277310	LGE	1	50 OTH	SP	CCA		V	4/5/2120	
2020 PO5929077147	LGE	1	50 OTH	SP	CCA		V	4/6/2120	
2020 PO5939376945	LGE	1	50 OTH	SP	CCA		V	4/7/2120	
2020 PO5940476736	LGE	1	50 OTH	SP	CCA		V	4/8/2120	
2020 PO5941376728	LGE	1	50 OTH	SP	CCA		V	4/9/2120	
2020 PO5956076775	LGE	1	50 OTH	SP	CCA		V	4/10/2120	

2020 PO5958377111	LGE	4	35 OTH	SP	CCA		V	4/11/2120
2020 PO5960777017	LGE	4	35 OTH	SP	CCA		V	4/12/2120
2020 PO5972076944	LGE	4	35 OTH	SP	CCA		V	4/13/2120
2020 PO4810387775	LGE	4	30 BRN	SP	CRE	ED,ID	BD	4/14/2120
2020 PO4810787778	LGE	4	30 BRN	SP	CRE	ED,ID	BD	4/15/2120
2020 PO4879787464	LGE	5	30 XXX	SP	A	ED,ID	TD	4/16/2120
2020 PO4770387927	LGE	4	40 BRO	SP	CRE	ED	BD	4/17/2120
2020 PO4769487951	LGE	4	40 BRO	SP	CRE	ED	TD	4/18/2120
2020 PO4885086379	LGE	3	45 OTH	SP	CCA	ED,SRS	TD	4/19/2120
2020 PO4826186459	LGE	3	45 XXX	SP	CCA		V	4/20/2120
2020 PO4827786456	LGE	4	45 XXX	SP	CRE	ID,IP	BD	4/21/2120
2020 PO4829486455	F	1	55 XXX	SP	P		V	4/22/2120
2020 PO4829486447	F	3	50 XXX	SP	A		V	4/23/2120
2020 PO4829186441	LGE	4	30 XXX	ST	CCA		V	4/24/2120
2020 PO4832186366	LGE	4	35 XXX	SP	P	ED	T	4/25/2120
2020 PO4831886384	LGE	4	35 XXX	SP	P	ID	BD	4/26/2120
2020 PO4830486382	LGE	4	40 XXX	SP	CRE	ID	BD	4/27/2120
2020 PO4886386382	LGE	3	45 OTH	SP	CCA	ED,SRS	TD	4/28/2120
2020 PO4875386472	LGE	4	30 OTH	SP	CRE	ED,ID,SRS	TD	4/29/2120
2020 PO4912287228	LGE	4	30 OTH	SP	P	ID	BD	4/30/2120
2020 PO6240385310	LGE	3	45 OTH	SP	CCA		V	5/1/2120
2020 PO4913787212	LGE	4E	40E OTH	SP	CRE	ED,ID,SRS	TD	5/2/2120
2020 PO4917287225	F	4	35 OTH	SP	P		V	5/3/2120
2020 PO4915387221	F	5	35 OTH	SP	P		V	5/4/2120
2020 PO4915187222	LGE	1	50 BRN	SP	CCA		V	5/5/2120
2020 PO4913987219@	LGE	4	30 BRN	SP	CCA		V	5/6/2120
2020 PO4913987219	LGE	3	45 BRN	SP	CCA		V	5/7/2120
2020 PO4914487250	LGE	3	45 BRN	SP	CCA		V	5/8/2120
2020 PO4675089112	LGE	4	40 BRO	SP	CRE	ID,IP	BD	5/9/2120
2020 PO4675689112	LGE	4	40 BRO	SP	A	ID,IP	BD	5/10/2120
2020 PO4874487436	LGE	3	40 XXX	SP	P		V	5/11/2120
2020 PO4768587976	LGE	4	40 BRO	SP	CRE	ED	BD	5/12/2120
2020 PO4767588004	LGE	4	40 BRO	SP	CRE	ED	BD	5/13/2120
2020 PO4770993056	LGE	3	45 BRO	SP	CCA		V	5/14/2120
2020 PO4763593244	LGE	3	45 BRO	SP	CCA		V	5/15/2120
2020 PO4766488035	LGE	4	40 BRO	SP	CCA		V	5/16/2120
2020 PO4765488063	LGE	4	40 BRO	SP	CRE	ED	TD	5/17/2120
2020 PO4765388065	LGE	4	40 BRO	SP	CRE	ED	TD	5/18/2120
2020 PO4765388065-A	LGE	4	30E BRO	SP	CRE	ED	TD	5/19/2120
2020 PO4786087890	LGE	UNK	45 BRO	SP	CRE	ED	TD	5/20/2120
2020 PO4783587868	LGE	4	35 BRO	SP	CRE	ED	V	5/21/2120
2020 PO4874487428	LGE	3	45 XXX	SP	A		V	5/22/2120
2020 PO5980177399	LGE	1	50 OTH	SP	CCA		V	5/23/2120
2020 PO4886086307	LGE	3	45 OTH	SP	CCA		V	5/24/2120
2020 PO4885686378	LGE	3	45 OTH	SP	CCA		V	5/25/2120
2020 PO4885786356	LGE	3	50 OTH	SP	CCA		V	5/26/2120
2020 PO4876086295	LGE	4	40 OTH	SP	CCA	ED,SRS	TD	5/27/2120

2020 PO4885586300	LGE	3	45 OTH	SP	CCA	ED	TD		5/28/2120
2020 PO4876186477	LGE	4	30 OTH	SP	CRE	ED,SRS	TD		5/29/2120
2020 PO4878787370	LGE	5	40 BRN	SP	CRE	ED,ID	TD		5/30/2120
2020 PO4877687354	LGE	4	35 BRN	SP	CCA		V		5/31/2120
2020 PO4873287432	LGE	4	40 XXX	SP	CCA		V		6/1/2120
2020 PO4876787298	LGE	4	40 XXX	SP	A	ED,ID,SRS	TD		6/2/2120
2020 PO4877187285	LGE	5	35 XXX	SP	A	ED,ID,SRS	TD		6/3/2120
2020 PO4853087321	LGE	5	35 XXX	SP	A	ID,RB	X	RP1	6/4/2120
2020 PO5853087796	LGE	3	45 BRN	SP	CCA		V		6/5/2120
2020 PO4875887293	LGE	5	35 XXX	SP	CRE	ID	BD		6/6/2120
2020 PO4663789012	LGE	4	40 BRO	SP	CRE	ED,ID,IP	TD		6/7/2120
2020 PO4663089026	LGE	4	40 BRO	SP	CRE	ID,IP	BD		6/8/2120
2020 PO4804388235	LGE	4	30 BRN	SP	CRE	ED,ID	BD		6/9/2120
2020 PO4805488246	LGE	4	30 BRN	SP	CRE	ED,ID	BD		6/10/2120
2020 PO4886086329	LGE	3	50 OTH	SP	CCA	ED,SRS	TD		6/11/2120
2020 PO4859786907	LGE	4	45 XXX	SP	A	ED,ID	TD		6/12/2120
2020 PO4857786911	LGE	4	45 XXX	SP	A	ID	BD		6/13/2120
2020 PO4856286915	LGE	4	45 XXX	SP	A	ED,ID	TD		6/14/2120
2020 PO4856286920	LGE	4	40 XXX	SP	A	ED,ID	BD		6/15/2120
2020 PO4853886920a	LGE	3	45 XXX	SP	A	ID	BD		6/16/2120
2020 PO4853886920	LGE	3	45 XXX	SP	A	ID	BD		6/17/2120
2020 PO4846886872	LGE	4	40 XXX	SP	A	ID	BD		6/18/2120
2020 PO4848086925	LGE	4	40 XXX	SP	A	ED,ID	TD		6/19/2120
2020 PO4921687025	LGE	2	55 OTH	SP	CRE	ED,ID,SRS	TD		6/20/2120
2020 PO4920687052	LGE	4	40 OTH	SP	CRE	ED,ID,IP,SRS	TD		6/21/2120
2020 PO4834286684	LGE	4	40 XXX	SP	P	ID	TD		6/22/2120
2020 PO4843886676	LGE	3	45 XXX	SP	CCA		V		6/23/2120
2020 PO4836286607	LGE	4	30 XXX	SP	P		V		6/24/2120
2020 PO4835386691	F	3	45 XXX	SP	CCA		V		6/25/2120
2020 PO4846386913	LGE	4	40 XXX	SP	A	ED,ID	TD		6/26/2120
2020 PO4847186928	LGE	3	50 BRN	SP	A	ED,ID	TD		6/27/2120
2020 PO4906287267	LGE	4	40 OTH	SP	P	ED,EP,ID,IP,RB	X	PX	6/28/2120
2020 PO4907687223	LGE	4	40 OTH	SP	CCA		V		6/29/2120
2020 PO4906987246	LGE	3	45 OTH	SP	CCA		V		6/30/2120
2020 PO4905387295	LGE	4	40 OTH	SP	CCA		V		7/1/2120
2020 PO4904987310	LGE	4	40 OTH	SP	CCA		V		7/2/2120
2020 PO4905787282	LGE	4	45 OTH	SP	P	ED,ID,IP,SRS	TD		7/3/2120
2020 PO4904287334	LGE	4	40 OTH	SP	CCA		V		7/4/2120