

①

RECEIVED

MAR 28 2024

To Whom It may Concern

PUBLIC SERVICE
COMMISSION

Public Service Commission

Case # 2023-00384

I don't feel responsible for this repair bill for the following prima facie case

① This meter base has been in the ground for approx 50 years none of the lines which consist of plastic copper etc, last for ever clamps Deteritate (rot) has not been in service for at least 15 years. I have a 2013 Dodge 3500 Diesel truck I bought new has 8000 mile on it never set outside I raised the hood last year the clamp on Breather Box had broke for no reason Its still like it was (come and look at it) your meter box was outside a fence in which I WAS approx. 3 feet away from never touched the meter base I knew exactly where the base was as there was no growth

2

Look at
pictures

on or around base had been mowed and cleaned for at least $1\frac{1}{2}$ years before I dug. If I'm guilty for Digging in my yard 3 feet away from meter base in my yard inside fence then all water companies should have advised all Private party homeowners to did next to meter & cut supply like before digging. again look at pictures there is no growth nowhere near base I knew exactly where it was it was in the Drive way partly. Mail carrier run over it Daily. Sure grass & growth grew over it for at least 15 years but I mowed it $1\frac{1}{2}$ years ago. Check the statues & see how long it should be before line setter or meter be updated. Because this was 50 or so years old the repair men called & asked if they wanted to go ahead & up date connection to main line was told not now maybe because I wasn't going to hook up now. This dispute has nothing to ~~do~~ about charges for or related to Duncan's water

3

Service over which the Commission has jurisdiction, this dispute relates to a claim for unliquidated damages arising from tortious damage to property over which Commission would not have jurisdiction because I had nor have had any service from DAW Co Water at this location.

DAW Co Water has not established that there was not a faulty clamp, hose, or mechanism, line or something happened with a 50 year old equipment. This is a prima facie case that does not prove to me that there may not been a faultier is a line or setter or something went wrong since I didn't touch the meter base I never even dug under the fence because when I dig around it meter base I always dig at least good distance from base. Its absurd that you base any claim that I didn't know where the base was Again look AT Pictures. In part of the bill I received from DAW Co Water

④

I believe I was charged for a new line setter which would have been replaced (no doubt) their not going to hook up new service on a 50 year old line setter when I call for a water service. Sorry I don't & can't quote regulation numbers & letters & sections. Also I don't understand reject Dav. Co water on ground on page 4 of last correspondence (see bottom page 4 last paragraph). I think this commission should find probable cause that I not pay for this you have had four months ~~to~~ come up with this and you give me 20 days to respond. This is very disturbing to me feeling not responsible, you don't know for positive that you have jurisdiction I don't know what happened you don't know but I do know if I dug into their line I would be responsible but I was 3 feet away from a 50 year old service, the water leaked from back of base of water meter because a black line was disconnected. They charged it off replaced old line setter I don't know what a 50 year old

3

line setter look like. I'm sure they have changed a lot. I feel like they have somewhat tried to get me to pay without too much investigation, beginning with the incident with a lady named Ros-marry who said she was the investigator I hope these callings were recorded I'd like to listen to them because I feel I way very very respectable. If not I'll come and appolige for it I don't sleep at night over this. I'm sure this commission has legal council but I ask you to weigh in on all sides I haven't sought any legal council. Cl-ope I don't this is a lot of money for me but I really don't feel responsible. I hope this answers your question & establishes a prima facie case

Sincerely Rick Duran
Any discussion feel free to
call I be the only one to
answer 270 316 8477 24-7

Case# 2023-00384



Andy Beshear
Governor

Rebecca W. Goodman
Secretary
Energy and Environment Cabinet

Commonwealth of Kentucky
Public Service Commission
211 Sower Blvd.
P.O. Box 615
Frankfort, Kentucky 40602-0615
Telephone: (502) 564-3940
Fax: (502) 564-3460
psc.ky.gov

Kent A. Chandler
Chairman

Angie Hatton
Vice Chairman

Mary Pat Regan
Commissioner

January 23, 2024

PARTIES OF RECORD

Re: Case No. 2023-00384

Notice is given to all parties that the attached 811 Line Locator Request has been filed into the record of this proceeding.

If you have any comments you would like to make regarding the contents of the document, please do so within five days of receipt of this letter. If you have any questions, please contact Jessica Norris-Canfield, Staff Attorney, at jnorriscanfield@ky.gov.

Sincerely,

A handwritten signature in cursive script that reads "Linda C. Bridwell".

Linda C. Bridwell, PE
Executive Director

Attachment: Document

Kentucky 811

Ticket no 232222200 **Type** NORMAL CALL
Request date 08/10/23 04:44 pm
Start date 08/15/23 08:00 am
Expiration date 08/31/23 11:59 pm

Excavator information

Excavator name RICK DUNCAN
Address 8931 AUBREY RD
MACEO,
Company phone [REDACTED]
Requested by RICK DUNCAN
On-site name RICK DUNCAN
Contact email

Phone [REDACTED]
On-site phone [REDACTED]

Excavation information

Type of work INSTALL WATER SERVICE, INSTALL PORCH, INSTALL POST
Depth (ft) 4 **Explosives** N
Area marked N
Job name/number
Work done for RICK DUNCAN

Location information

County DAVIESS **City** MACEO
Address/street 8931 AUBREY RD
Nearest intersecting street AUBREY RD
Location of work MARK FRONT OF PROPERTY.

Comments

Map Coord

NW Lat 37.8614212 **Lon** -86.9993597 **SE Lat** 37.8604908 **Lon** -86.9979834

Members notified

Company name	District	Type	Status
ATMOS ENERGY	0132	PIPELINE	Marked - The approximate location has been marked. File a 2ND NOTICE with KY811 if marks are not complete and accurate.
AT&T DISTRIBUTION	0139	COMMUNICATIONS	Marked - The approximate location has been marked. File a 2ND NOTICE with KY811 if marks are not complete and

accurate. (2023/08/16 10:54
AT&T paint and flagged)


No Conflict - The KY811
member has no facilities in the
area of excavation described
(2023/08/16 10:54 AT&T paint
and flagged)

KENERGY CORPORATION

0195

E

Map



Rick Duncan
8853 Hwy 2830
Macedo Kentucky 42355



Public Service Commission
211 Sower Blvd.
P.O. Box 615
Frankfort, Kentucky 40602-0615

Att. Commissioners