COMMONWEALTH OF KENTUCKY BEFORE THE PUBLIC SERVICE COMMISSION

In the Matter of:		
DANIEL CLYMER)))	CASE NO.
ALLEGED VIOLATION OF UNDERGROUND FACILITY DAMAGE PREVENTION ACT)))	2021-00161

OPENING ORDER

Daniel Clymer (Mr. Clymer) has been named as a party to an investigation before the Kentucky Public Service Commission (Commission) for allegedly violating the Kentucky Underground Facility Damage Prevention Act (Act).¹

Pursuant to KRS 278.495(2), the Commission has jurisdiction to regulate the safety of natural gas facilities in Kentucky and to enforce minimum federal pipeline safety standards. Under the Act, the Commission has authority to investigate and assess civil penalties for any violation of the Act that results in excavation damage to an underground facility used to transport natural gas or hazardous liquid subject to federal pipeline safety laws, 49 U.S.C. § 60101, et seq. Any person who violates any provision of the Act is subject to assessment of a civil penalty in the amount of \$250 for the first offense, no more than \$1,000 for the second offense within one year, and no more than \$3,000 for the third and any subsequent offense. Additionally, any person whose violation of the Act results in damage to an underground facility containing any flammable, toxic, corrosive,

¹ KRS 367.4901 through KRS 367.4917.

or hazardous material or results in the release of any flammable, toxic, corrosive, or hazardous material is subject to an additional penalty of up to \$1,000.

Following receipt of a report of excavation damage to its underground gas pipeline from an operator, Commission Staff (Staff) conducted an investigation and prepared an Incident Report, a copy of which is attached to this Order as an Appendix. In its Incident Report, Staff cites Mr. Clymer for violation of the following provision of the Act:

KRS 367.4911(1)(b) – An excavator may commence work before the two (2) full working days provided for in paragraph (a) of this subsection have elapsed if all affected operators have notified the person that the location of all the affected operators' facilities have been marked or that they have no facilities in the area of the proposed excavation, demolitions, or timber harvesting.

Based on its review of the Incident Report and being otherwise sufficiently advised, the Commission finds prima facie evidence that Mr. Clymer violated the Underground Facility Damage Prevention Act. The Commission further finds that a formal investigation into the excavation damage incident should be conducted.

This proceeding was established on April 12, 2021 with the issuance of an Opening Order. The attempt to perfect service of process for the previously issued Opening Order was unsuccessful. The Opening Order is now being reissued with the intent to perfect service of process on Mr. Clymer.

IT IS THEREFORE ORDERED that:

1. Mr. Clymer shall submit to the Commission, via email sent to PSCED@ky.gov with the case number of this proceeding in the subject line of the

message, a written response to the allegations contained in the Staff Incident Report within 20 days of receipt of this Order.

- 2. Any partnership, corporation, or business entity (including a limited liability company) must be represented by an attorney licensed to practice law in Kentucky, and such representation includes the filing of papers with and appearances at hearings before the Commission.
- 3. An individual may submit a response to the allegations contained in the Staff Incident Report without the representation of an attorney.
- 4. The Staff Incident Report 32234 in the Appendix to this Order is made a part of the record in this case.
- 5. Please note that notice of a hearing to be held in this matter will be mailed to Mr. Clymer once proof of service is received by the Commission. Parties who fail to appear after service will be subject to entry of a default judgment against them.

[REMAINDER OF PAGE INTENTIONALLY LEFT BLANK]

By the Commission

ENTERED

SEP 29 2021 rcs

KENTUCKY PUBLIC SERVICE COMMISSION

ATTEST:

Executive Director

APPENDIX

APPENDIX TO AN ORDER OF THE KENTUCKY PUBLIC SERVICE COMMISSION IN CASE NO. 2021-00161 DATED SEP 29 2021

NINE PAGES TO FOLLOW

PIPELINE DAMAGE INVESTIGATION REPORT

Investigation Information

KY PSC Investigator(s) Eric V. Tout Incident ID 32234

Incident Date 10/24/2019 3:00:00 PM Report Submitted 11/12/2019 3:08:37 PM

OPERATOR INFORMATION

OperatorCarrollton UtilitiesReportPhone502-732-1218Email

Incident Location 38.681690, -85.176152 701 Highland Ave Carrollton, KY 41008 Carroll Reported By Kaleb Nab
Email knab@cuky.us

Locate Ticket Number 1910231674

EXCAVATOR INFORMATION

Name of Excavator Clymer, Daniel Organization ID

Phone 502-655-0638 Email

Excavator Address 701 Highland Ave Carrollton, KY 41008 **Locate Ticket Number**

INCIDENT

The Operator reports that the Excavator/Homeowner damaged a ¾ inch steel gas service pipe coating, bent pipe, with mechanized equipment. No release of gas occurred. More specifically the Operator was responding to a locate request when it was discovered excavation occurred prior to the locate request. The Operator indicates that the homeowner/excavator was not present and he was unable to make contact at the time of the event.

The Damage Report is include as Attachment 1.

Excavation Summary

Excavation Within 18" (Approximate Location)	Type Of Equipment Used	Cost of Damage (Per Operator)	Amount Billed (Excavator)
No call to 811	Mechanized / Not specified	\$350.00	\$350.00

Locate Ticket (LT) Summary

Ticket #	Valid	Initial Date	Expiration Date (21 calendar days from Initial date)	Incident Date	# of Days Expired	Within Scope of Excavation
1910231674	Did not wait 2 working days	10/23/19	N/A	10/24/19	0	Yes

The Locate Ticket(s) is/are include as Attachment 2.

INVESTIGATION

On 07/22/20 the Operator, Carrollton Utilities' Kaleb Nab (502-525-9064), provided a paid invoice from the Excavator. The invoice is included as Attachment 3.

On 07/23/20 Mr. Nab stated that gas was in the line at the time of the damage.

On 07/23/20 the Excavator/Homeowner, Daniel Clymer, stated that he did not wait the two working days before excavating. Mr. Clymer was receptive to attending the Damage Prevention Course and paying the reduced penalty of \$100.00.

VIOLATION KRS 367,4911

(1) (b) An excavator may commence work before the two (2) full working days provided for in paragraph (a) of this subsection have e if all affected operators have notified the person that the location of all the affected operators' facilities have been marked or th have no facilities in the area of the proposed excavation, demolition, or timber harvesting.

of Offences

Excavator Last Offence Incident #		Last Offence Incident Date	Last Offence Resolved Date
1 st	N/A	N/A	N/A



Gas Excavation Damage Report

Carrollton Utilities Submitted 2/7/2020 Incident ID 32234 Set back to Edit Staff Edit Print (PDFForm.aspx?Rpt=GasInvestigation&IG=32234) Reported By: Kaleb Nab Name Phone 502-732-1218 Email knab@cuky.us Gas Line Incident Occured: 10/24/2019 Date 3:00 PM Time Details: 11/12/2019 3:08 PM Reported Date Incident Location Address: 38.681690, -85.176152 Location Address 701 Highland Ave City Carrollton State ΚY County Carroll 41008 Zip Confirm Code **Number of Customers out** Was gas or hazardous liquids contained in the underground facility? Was gas or hazardous liquids released into the 3/2020 atmosphere? Locate Request Ticket No. 1910231674 Excavator Home Owner **Excavator Address:** First Name Daniel **Last Name** Clymer 502-655-0638 Phone Email

701 Highland Ave

Carrollton

Address

City

ΚY State Zip 41008 Confirm Code

Excavation Damage

One Call notification practices not

At 3:00 PM on Thursday Oct. 24th, a Carrollton Utilities Service Man responded to a One Call ticket that was called in at 4:00 PM Wednesday Oct 23rd. The service man came to the area indicated the work would be done and found that excavation work had already been done. No one was in the area and there was no longer any excavation equipment. The service man found a hole approximately 4ft deep with 5 ft of a 3/4" steel natural gas service line exposed. The service man then checked the area for leaking gas with a GMI Description of Incident and found there to be no leaks. He found that there was some damage to the coating of the pipe and that the pipe had been bent in two areas from a machine pulling on it. The service man called the General Manager of Carrollton Utilities and briefed him about the damage. The service man took pictures of the site and then proceeded to apply mastic to the pipe where the coating had been damaged. He then locate the line in the areas needed per the ticket and left the scene. The homeowner/excavator were never present

Summary Information

2/7/2020

cause

Extent of the damage Cost of the damage Steps taken to prevent re-occurance Amount billed to

excavator

Full details such as the lines in the area of construction. Utilities 48 hours to locate the gas lines in the area of construction. For more details see "Description of

Pipe coating was damaged as well as the pipe was bent in two places. \$100.00

and were not able to be contacted at the time of the event.

Customer was billed \$100 for repairs and \$300 for the serviceman's time.

\$400.00



NORMAL NOTICE

Ticket: 1910231674 Date: 10/23/2019 Time: 16:04 Oper: KUPIANONYMOUS Chan:000

State: KY Cnty: CARROLL City: CARROLLTON

Subdivision:

Address : 701

Street : HIGHLAND AVE

Location: NORTH SIDE OF LOT

:

Boundary: n 38.682137 s 38.680793 w -85.177078 e -85.172062

Work type : BASEMENT ACCESS Done for : DANIEL CLYMER

Start date: 10/25/2019 Time: 16:30 Hours notice: 48/48 Priority: NORM

Ug/Oh/Both: U Blasting: NO Emergency: N

Duration: N/A Depth: 3 FT

Company : DANIEL CLYMER Type: HOME

Co addr : 701 HIGHLAND AVE

City : CARROLLTON State: KY Zip: 41008
Caller : DANIEL CLYMER Phone: (502)655-0638

Contact : DANIEL Phone:
Mobile : (502)655-0638

Email : CARROLLTONSHEETMETAL@YAHOO.COM

Submitted date: 10/23/2019 Time: 16:04

Members: 0030 0139 WINKY



Carrollton Utilities

P O Box 269

Carrollton, KY 41008 (502) 732-7055 fax (502) 732-7058 www.carrolltonutilities.com

TO

Heather Clymer 701 Highland Ave Carrollton, KY 41008 INVOICE NO.

GAS LINE REPAIR

DATE

October 30, 2019

ACCOUNT # 200180.0081

PAID

NOV 15 2019

TOTAL \$

350.00

CARROLLTON UTILITIES

DATE COMPLETED	JOB	PAYMENT TERMS	DUE DATE
10/24/2019	701 Highland Ave	DUE UPON RECEIPT	

QUANTITY	DESCRIPTION	UNIT PRICE	LINE TOTAL	
1.00	GAS LINE REPAIR	\$ 350.00	\$	350.00
			\$	-
				
	 		ļ	
				······································
				. *
		SUBTOTAL	Ś	350.00
		SALES TAX		

Make all checks payable to: CARROLLTON UTILITIES

(4)(3)(4) X View | Edit \$390.45 \$390.91 \$406.10 \$351.37 5351.97 \$372.13 \$421.52 \$417.37 \$0,00 \$0.00 o 1 0 Total Usage ន 表表 Search... ψ F Ref 4685 2737 2737 13556 13646 2778 2778 Amount \$15.42 \$421.52 \$350.00 \$18.32 \$0.46 \$15.19 \$20.16 \$0.60 50.71 Gas Line Rpr/Min Rate Code: RA1 Rate Code: R01 Rate Code: RA1 Rate Code: 01 Rate Code: Rate Code: CITY READ CITY READ CITY READ CITY READ Rate Code: OLBP MC OLBP ACH Utility Management - Account Console Attachments Payment Arrangements Contacts Meter No 67558884 67558884 67558884 67558884 147039 147039 147039 avascriptRadGridNamespaceAsyncRequestCttl00SContentPlaceHolder1SHistoyGridSctl03Sctl01Sctl063;","ctl00_ContentPlaceHolder1_HistoyGrid; event) 9599 5072,0000 1780.0000 4841,0000 1748,0000 Reading 🏤 🗷 BIU4Pay 3.0 Login 🖹 EAGLE 🕒 LOGICS 🗿 PHONE SYSTEM 🛃 ONLINE ACCOUNTS 😁 AR BOX 🎆 Perform Home Account into History Deposits Services Location Service Orders Mapping Comments Help Code **8** 8 ₹ **は 38 12 8 2** 12 8 2 88 X E Budgel Bang Reports Billing Delaits Open tlems 10/21/2019 11/07/2019 11/07/2019 11/19/2019 10/23/22/01 10/21/2019 11/01/2019 11/07/2019 11/02/2018 11/07/2019 11/07/2019 11/15/2019 11/19/2019 12/06/2019 Adjustments Readings G Arrangements G III. (E) (E) http://db-2019/esgle/UB_Account_Locator.aspx ΠĄ READING READING PAYMENT PAYMENT READING READING ADJUST BILLING BILLING BILLING BRIDG BILLING BILLING BILLING Type Calendar Customers Assets Collections O File Edit View Favorites Tools Help counts 12 | Svc Apps 15 | Service Orders 02 R S165.00 \$66.92 07/24/2020 ACTIVE 04/09/2018 Manage Manage Account Information 28233 200180.00 31 CLYMER, HEATHER 701 HIGHLAND AVENUE CARROLLTON, KY Status Billing UP Balance:
Due Date:
Budget Bill Date:
Cycle:
Rev-Class:
Deposits: GS SW TC WA Trans From: Trans To: (E) Account Console Status: Activity: Start: Cut-0ff: Manage (KOO) Tools View Recent

٢.

.

Ľ

Ē.

•

ll land

iū

H O Type here to search

Daniel Clymer 701 Highland Ave Carrollton, KENTUCKY 41008

*Daniel Clymer 915 Polk Street Carrollton, KENTUCKY 41008