COMMONWEALTH OF KENTUCKY

BEFORE THE PUBLIC SERVICE COMMISSION

In the Matter of:

ALLEGED FAILURE TO COMPLY WITH COMMISSION REGULATIONS) }	
BALLARD RURAL TELEPHONE COOPERATIVE CORPORATION, INC.) CASE NO.	10323
AND)	
JACKSON PURCHASE ELECTRIC COOPERATIVE CORPORATION, INC.))	

AMENDED ORDER

On July 21, 1988, this Commission issued an Order to Show Cause to Jackson Purchase Electric Cooperative Corporation, Inc. ("Jackson Purchase"), and Ballard Rural Telephone Cooperative Corporation, Inc. ("Ballard"), as a result of allegations made by the Commission Staff in an Electrical Utility Accident Investigation Report on the fatal accident of Wilbur Nall III. A copy of this report was to have been attached to that Order and made a part of the record of this case. This Commission has subsequently discovered that a different report was inadvertently attached to its Order instead.

IT IS THEREFORE ORDERED that this Commission's Order of July 21, 1988 be amended as follows:

1. The Electrical Utility Accident Investigation Report on the fatal accident of Wilbur Nall III, a copy of which is attached

hereto, shall be, and it hereby is, substituted for the Report attached to our previous Order and made part of the record of this case.

2. Jackson Purchase and Ballard shall each submit to this Commission a written response to the allegations contained in the Electrical Utility Accident Investigation Report no later than August 22, 1988.

IT IS FURTHER ORDERED that all other provisions of this Commission's Order of July 21, 1988 shall remain in effect.

Done at Frankfort, Kentucky, this 3rd day of August, 1988.

PUBLIC SERVICE COMMISSION

Chairman

Robert M. Deus

Vice Chairman

Complete Milliains

ATTEST:

Executive Director

MEMORANDUM

TO:

Claude G. Rhorer, Jr., Director

Division of Engineering and Services

THRU:

J. Wayne Bates, Manager 303

Communications and Electric Branch

FROM:

John W. Land

Utility Investigator, Sr.

Electric Branch

DATE:

June 28, 1988

SUBJECT:

Investigation Involving Jackson Accident

Electric Distribution System

Attached please find the Report on the investigation of the accident in which Mr. Wilbur Nall III was fatally injured.

JWL: jsb

Attachment: A.

- Persons Asisting In Investigation
- в. P.S.C. Accident and Trouble Report
- C. Jackson Purchase Accident Report
- McCracken County Sheriff's Investigation Report McCracken County Coroner's Investigation Report D. Ε.
- F. System Inspection Map of Accident Site
- Sketch of Accident Site G.
- Work Orders Showing Line Correction and Construction Dates
- Pictures of Accident Site
- I. J. Ballard Rural Telephone Accident Report
- Κ. Newspaper Articles on Accident
- Ballard's work sketch showing line corrections.

ELECTRICAL UTILITY ACCIDENT INVESTIGATION

DATE OF THIS REPOR	r 6/28/88 SUBM	TTED BY John W. L	and
NAME OF UTILITY	ackson Purchase Electric	Cooperative Corpor	ation
ACCIDENT REPORTED	BY David Stiles General	Manager	
DATE & TIME UTILIT	y Learned of Accident 4/	/21/88 (10:35 A.M.)	
DATE . TIME ACCIDE	NT REPORTED 4/21/88 (3:2	29 P.M.)	
DATE AND TIME ACCI	DENT OCCURRED 4/21/88 (9	9:40 A.M.)	
DATE OF ACCIDENT I	NVESTIGATION 4/22/88	anthornament and another articles are also as a superior and a superior and a superior and a superior and a su	
DATE SUMMARY WRITT	en report was received p	ROM UTILITY 4/22/8	18
PERSONS ASSISTING	IN THE INVESTIGATION Sec	e Attachment A	
			·····
NAME OF VICTIM(S)	1. Wilbur Nall III	sexm	AGE 28
PATAL X	NAME OF EMPLOYER: Man	ning Auto Salvage	
Injuries	option to the contract of the		
	2.		
	HAME OF EMPLOYER:		
INJURIES			
	3.	SRI	AGR
21017			
	name of employer:		
INJUKIES			

ELECTRICAL UTILITY ACCIDENT INVESTIGATION (Continued)

LOCATION OF ACCIDENT SITE Manning's Auto Salvage -Kingsway Drive
off US 60 about 1 1/2 miles East of Kevil, Kentucky.
DESCRIPTION OF ACCIDENT Mr. Nall was standing on a pile of crushed
auto's loaded on a transport truck leaving Manning's Auto Salvage
yard when accident occurred. Mr. Nall was holding up the utility
lines as the truck passed under them, when he apparently came into
contact with a 7,200 volt overhead line with his head and thereby
suffered a fatal electrical shock. (See Jackson Purchase Electric
Cooperative's accident report)
SOURCE OF INFORMATION On site investigation, reports from personnel
assisting in the investigation (Attachment A) and accident report
submitted by Jackson Purchase Electric Cooperative.
VIOLATIONS OF COMMISSION REGULATIONS 1. Jackson Purchase single phase
line was in violation of 807 KAR 5:041, Section 3(1) NESC Table
232-1. 2. (See line clearances of this report) 2. Ballard Rural
Telephone Cooperative service wires were in violation of 807 KAR
5:061, Section 2(1) NESC Table 232-1 2. (See line clearances of this
report)
RECOMMENDATIONS 1. It is recommended that Jackson Purchase and
Ballard Rural Telephone review their system inspection procedures and
make necessary changes if needed. 2. It is recommended that Ballard
Telephone personnel be made aware of National Electric Safety Code
clearance requirements and report them to proper company personnel.
3. It is also recommended that the Commission consider action in
accordance with KRS 278.990 due to line clearance violations by Jack-
son Purchase RECC and Ballard Rural Telephone Company required by
807 KAR 5:041, Section 3(1) and 807 KAR 5:061, Section 2(1); NESC Table
232-1. 2.

CORRECTIVE ACTION Jackson Purchase Electric Cooperative set a 35°,
class 5 pole in mid-span to raise conductors to code height per Stak-
ing Sheet Work Order \$8-04-706-1E2 dated 4-26-88. Measurements were
taken by Jackson Purchase personnel after completion of work order
#8-04-706-1E2 and are given on bottom section of the above mentioned
Work Order.
Ballard Rural Telephone Company relocated its two service drops to
new poles set by Jackson Purchase Electric Cooperative on May 10,
1988. (Re: Letter dated June 24, 1988 and work sketch.) Drops mea-
sure 18'-8" and 19'-2" and are in compliance with Commission regula-
tions.

LINE CLEARANCES

		As Heasured	Minimum Allowed by MESC 1981 Edition
A.	AT POINT OF ACCIDENT		
	Phase conductor to ground elevation:	17'-4"	21.1'
	Neutral conductor to ground elevation:	14'-1"	19.1'
	Communication conductor to ground elevation:	13'-3" 12'-11"	19.1' 19.1'
	Phase conductor to structure:	N/A	N/A
	Neutral conductor to structure:	N/A	N/A
	Communication conductor to structure:	N/A	<u> </u>
в.	AT LOWEST POINT OF SPAN		
	Phase conductor to ground elevation:	17'-4"	21.1'
	Neutral conductor to ground elevation:	14*-1*	19.1'
	Communication conductor to ground elevation:	13'-3"	19.1'
c.	SPAN LENGTH 362		
Da	te the line or facilities were co	nstructed: 10/2	20/82
Ut:	llity: Jackson Purchase Electri	c Cooperative Co	orporation
		ise 3:22 P.H.(1	
λp	proximate temperature: 76 degre	es (National Wes	ather Service)
Ne	asurements made by: Rick Irby 1	st class journe	y-man lineman and
<u>b</u>	ucket truck operator, Greq Simmor	s Field Enginee	r of Jackson County
E	lectric Cooperative and witnessed	by John W.Land	of PSC statt.
		Submitted by:	John Kond

SOURCE OF INFORMATION:

Persons Assisting In The Investigation Jackson Purchase RECC Personnel

David Stiles - General Manager

Don Schaefer - Manager Engineering

Donnie Lanier - Manager of Operations

Sam Adams - Sub. Foreman


Rick Irby - Journey-man Lineman

Greg Simmons - Field Engineer

Jeff Wigand - (Claims Adjuster-Crawford Insurance Co.)

ACCIDENT AND TROUBLE REPORT FORM

TODAY'S DATE 4-21-88			_ TIME _3	:29
COMPANY JACKSON PURCH. PER	د			•
PERSON REPORTING INCIDENT: NAME: 2	AVID .	STILE	<u> </u>	
CONTROL DAVID SILES TITLE: G	EN.M	5 p.	•	
TO REPRISE VISITE ADDRESS:				· · · · · · · · · · · · · · · · · · ·
7. RPRAISE PHONE NO:		•	2_1	
ACCIDENT DESCRIPTION: MAN COM	183.76D	CHO	200 V.L	125
ACCIDENT DESCRIPTION:	11.0100	<i>D.</i> K. 1		• • • • • • • • • • • • • • • • • • • •
victims names:	SEX	AGE	DEATH V	INJURY
				_injury
	•••			_INJURY_
LOCATION OF ACCIDENT:		^	VERAIT	
DOURTED OF ROOLDENS!				
TIME OF OCCURRENCE:				·
THE OF OCCURAENCE:				
<i>f</i> .				
TROUBLE DESCRIPTION: No aut	<u> </u>			············
	•			
TIME OF OCCURRENCE:				
TIME OF RESUMPTION OF NORMAL SERVI	CE:			
NUMBER OF CUSTOMERS AFFECTED:			. ^	
	SIGNE	m	Hus	hen
	DATE		7	
·	aura "			



Jackson Purchase Electric Cooperative Corporation

2900 Irvin Cobb Drive P.O. Box 3188 Paducah, Kentucky 42002-3188 Telephone 442-7321

April 27, 1988

Ky. Public Service Commission 730 Schenkle Lane P. O. Box 615 Frankfort, KY 40602

Attn: John Land

Dear John:

Please find attached the PSC Report for the Wilbur Nail III fatality. We will be sending a sketch of the area and the accident scene at a later date. Also enclosed is a copy of the sheriff's report and coroner's report.

If you need further information, please call.

Sincerely yours,

JACKSON PURCHASE E C C

Donald R. Schaefer, P.E. Manager of Engineering

Enclosure

DRS/bjs



P.S.C. EMERGENCY REPORT FORM

ATE APRIL 20, 1988		T	IME	:00 P.M.		
OMPANY JACKSON PURCHASE EL	ECIRIC COOF	PERATIVE C	ORPORATIO	N		
ERSON MAKING CALL:		EMERGENCY				
	TITLE					
OCATION OF OCCURRENCE						
		Kingswood	Drive			
		Kevil, Ky	42053			
TIME OF OCCURRENCE		9:35 A.M.	April	21st, 1988		
ESCRIPTION OF OCCURREN	CE: DEA	THS:	YES	x	мо _	
						Х
				DAMAGE		
to raise the lines by hand wires and raised into the p						the bottom
EFFECTS ON NORMAL SERVI	CE	NONE				
		٠,				
A. A. A.	· .	·				
CORRECTIVE ACTIONS TAKE	N We se	t a 35 ft.	, Class	pole in mi	d-spen to	raise
conductors to Code height.						
TIME OF RESUMPTION OF I	NORMAL SE	RVICE				
		SI	GNED	Onses	I Set	afu.
				ANALYZ OF	_	
				pril 27	-	♂

McCR. KEN COUNTY SHERIFF DEPA MENT
County Court House
Paducah, Kentucky 42001
(502) 444-4719
HOWARD WALKER, JR. - Sheriff

10	O RE LILLED OUT	BY OFFICE					
Incident No.:0444-88 Offen	ise No.:		Case No.: _	DEATH FIL	E		
Title of Investigation:Death_Report	Statute:	KRS					
Status of Investigation:CLOSED,							
тс	BE FILLED OUT	BY OFFICER					
Time Notified: 09:51 .m. Time	Arrived:10:0	<u>.m.</u>	Time Com	pleted:11	:00		.m.
Orl. No.: KY0730000 Date: 4-21	19 <u>88</u>	_ Day of Week:]	hursday	Unit No.: _	_10		
Location of Event: Manning Auto Salvage Rose	Rt. 1 Box 187 i	Kingsway Dr.		Kevil.	1	(Y	
Event Reported By: Billy Brooks							
Type Event Reported: Death Report	Date	of Event: 4-21		19 <u>88</u> Ti	ime: 9:4	2_	Am.
Victim's Name(s)		Address		Phone No.			Race
Wilbur J. Nall III	8020 01d Cai		443-7180	3-9-60	М	W	
)				<u> </u>	
Make Year Model	VEHICLE INV		ensė No.	Sta	ë 1	ōŵé	d .
	DETAILS OF	EVENT					
Received call of 10-07 body at Mar	ining Auto Salv	<u>age. Upon arr</u>	ival, fo	und Wilbur	- J. Nal	1 1	11
lying on top of semi-trailer, look	ked to have bee	n electrocuted	. Coron	er was ca	lled and		
Det. Mike Kaufman. Truck was 71	ft. from origin	al point of in	pact. T	ruck was	14' 2" F	igh	
on right side and 14' 7" high on	left side. Pri	mary wire was	17' 8",	neutral w	ire 14'5	·" .	
Telephone wires (1) 13'5" (2) 13'	4" from ground.	Body was tak	en by Ar	ngel of Men	rcy to		
Western Baptist Morgue.							
							, <u>.</u>
					-		
			(Over) Use	additional s	heets as r		-

MCCRACKEN COUNTY CORUNER'S INVESTIGATION REPORT, MCCRACKEN COUNTY, KENTUCKY


NAME OF DECEDENT:		WILBUR J. NA	ALL III 40	06-02-3894		
NAME OF DECEDENT:	(First)	4)	tiddle)	(Las	t)	
ADDRESS:	8020 OLD CAIRO	ROAD PADUCAL	K, KY.	···		
AGE: 28 Da	te of Birth:	03-09-1960	Sex: MALE	Race:	CAUCASIAN	
DATE and TIME of	DEATH: APRIL	21ST, 1988	9:35 A.M. Pro	onounced:	10:30 A.M.	وسوانت النار
DATE and TIME of	INCIDENT:A	PRIL 21ST, 19	88 9:35 A.M	·		
PLACE of INCIDENT	8.6 MILES	WEST OF PADUC	AH, GRAVEL	ROAD OFF KIN	GSWAY ROAD	
PLACE of DEATH:	SAME AS	ABOVE	· 	···		
MANNER of DEATH:	Natural	Accident	XX Homicid	• su	icide	-
FUNERAL BOME:	LINDSEY FUNE	RAL HOME				
RELEASED BY:					Phone:	43-7180
LAST SEEN ALIVE						
WHERE & DATE:						
FOUND DEAD BY OR	REPORTED BY:	ANGEL OF MEI	RCY AMBULANCE	SERVICE PHO	ONE:	529
PERSONAL PHYSICI						
B.A. OR URINE TA					W.B.K.	MORGUE
AUTOPSY NO	_ PATHOLOGIST:_	EXAMINED BY	DR. E. W. YLI	TALO		
POLICE AGENCY AN		DEPUTY SHE	RIFF FRANKIL	. AUGUSTUS	PBONE: 444-4	719
PROTOS TAKEN:						
SUSPECTED CAUSE				IY SIMS OF TH	E AMBULANCE	SERVICE
SUSPECTED MANNE	R OF DEATH:	ACCIDENTAL				
HISTORY: THIS I WAS INFORMED TH ANGEL OF MERCY WA SEE THE REPORTS	AS ALSO DISPATCH	COUNTY AMBULAN ED WHEN IT WAS	CE WAS FIRST OF LEARNED IT W	CALLED AT 9:2 AS INSIDE THE	E McCRACKEN C	HEN THE OUNTY LINE.
OFF THE HIGHWAY	50 AND PROCEEDED	APPROX. 2 BLO	OCKS TO A GRAV	EL ROADWAY WI	HICH LEADS TO	A CRUSHING
AUTO COMPANY WHICE GO BY THE NAME TO SEMI-TRAILER TRUCE BODIES OF 16 CRUSTOP OF THE FIRST RESCUE SQUAD NOTHE WAS LAYING OVER THE WAS LAYING OVER THE WHITE PERSONNERS OF THE W	RISTATE COMPANY CK IS SITTING ON SHED CARS IN STA STACK BEHIND TH ED NO LIFE SIGNS ER THE SIDE ON THE HOLD HIM ON THE	THE GRAVEL RECKS OF EIGHT OF THE CAB OF THE ON THE BODY. THE RIGHT SIDE CARS BY ARRI	ACKEN FIRE AND OAD HEADED NOR ONE BEHIND THE TRUCK AND WITH THE BODY WAS OF THE TRAILE VING E.M.T.'S	RESCUE HAS TH AND LOADE OTHER. I C THE AIDE OF LAYING ON T OR IN A FACE THIS MAN WA	A UNIT ON THE DON'THE TRAILIMBED A LADIDARRY GILL (OP OF THE CRUUP POSITION. S BURNED ACU	E SCENE. A ILER IS THE DER TO THE DEF THE USHED CAR. THE LEGS TELY AND I
- Investigating		JERRY W. BEYE			History Over	
					-	


DEATH INVESTIGATION WILBUR NALL III

I NOTE THAT LATER I REMOVED SOME KEYS AND TWO POCKET KNIVES AND A SMALL AMOUNT OF CHANGE AND THE SISTER, LORI NALL, PICKED THESE UP AT MY OFFICE. THERE WAS ALSO A BIC LIGHTER IN THE RIGHT FRONT POCKET BUT IS WAS BURNED AND I DESTROYED IT. AT THE MORGUE WITH DR. E.W. YLITALO PRESENT I REMOVED BOTH URINE AND BLOOD FROM THE BODY. THE BODY WAS EXAMINED AND I NOTE A OVERWEIGHT WHITE MALE WITH WHAT APPEARS TO BE BLOND SHOULDER LENGTH HAIR WHICH HAS BEEN SINGED THERE IS A SEVERE WHITE PURGE FROTHY FROM THE NOSTRILS OR NASAL NARES. HE HAS A BLOND UPPER MUSTACHE BUT THE BEARD WHICH HE APPEARS TO HAVE HAS BEEN BURNED OFF. THE CHEST HAIR. PUBIC HAIR AND THE HAIR UNDER THE ARMS HAS ALSO BEEN BURNED OFF. ANY AREA WHERE METAL TOUCHED THE SKIN CAUSED SEVERE 2ND AND 3R DEGREE BURNS SUCH AS WHERE THE BELT BUCKLE AND THE POCKET KNIVES AND KEYS TOUCHED THE BODY. THE LEFT ANKLE HAD A BURN AREA THE BLUE JEANS ARE BLOWN APART IN THIS AREA. THE SHIRT HAS BURNED OFF THE BODY AND THIS CAUSED 2ND DEGREE BURNS OVER THE ANTERIOR AND POSTERIOR OF THE THORACIC AND ABDOMINAL CAVITIES. THE BUTTOCK ON THE LEFT SIDE HAVE SEVERE 3RD DEGREE BURNS, AS IF HE WAS GROUNDED IN THIS AREA. THE ZIPPER OF THE BLUE JEANS IS BURNED. THE BOOTS DO NOT HAVE INDICATION OF ANY EXIT AREAS. I NOTE THE HEAD HAIR TO BE SINGED OFF. THERE IS A TATTO ON THE LEFT SHOULDER OF A FLYING DRAGON AND SKULL. IN THE AREA OF THE NECK POSTERIORLY IS A DEEP 3RD DEGREE BURN DIRECTLY BELOW THE HAIR LINE AND THIS INJURY IS DEEP AND SEVERE IN NATURE AND WOULD APPEAR TO BE WHERE HE STRUCK THE HOT LINE AS HE RAISED UP. THIS INJURY HAS FLESH MISSING AND HAIR LENGTH IS SHORTER IN THIS AREA AND WOULD BE CONSISTENT WITH THE FLESH AND HAIR FOUND ON THE HOT WIRE. THE LEFT GLOVE IS A BROWN COTTON TYPE MATERIAL AND THE FINGERS ARE TIGHT IN A FIST WITH A TYPE OF TRAUMA RIGOR AND WHEN I PULL THEM APART I NOTE A BURN DEEP INTO THE INSIDE THE FINGERS, INDICATING THIS HAND WAS TOUCHING THE GROUND OR NEUTRAL WIRE. THE RIGHT HAND ALSO HAS A GLOVE BUT IT IS NOT DAMAGED BUT THE RIGHT WRIST DOES HAVE A BLACK 2ND DEGREE TYPE BURN WHICH MIGHT INDICATE THE 2ND AREA WHERE HE WAS TOUCHING THE GROUND WIRE. AGAIN BACK TO THE SCENE I DID NOT SEE ANY INDICATION WHERE THIS MAN MIGHT HAVE BEEN GROUNDED TO THE CARS BUT THERE WAS BURNED CLOTH FROM THE SHIRT ON THE METAL AND THIS MAY HAVE COVERED ANY GROUNDING. I AGAIN NOTE THAT THE CAP WAS NOT DAMAGED BUT THE MATERIAL ON THE TOP LINE MAY HAVE BEEN FROM THE SHIRT BUT I COULD NOT DETERMINE THIS. DEPUTY FRANKIE AUGUSTUS TOOK THE WEDGE SHAPED STICK WITH HIM TO KEEP IN THE EVIDENCE LOCKER. SEE ALL NOTES AND ACCIDENT REPORT OF DEPUTY AUGUSTUS.

THIS WRITER LEARNED THAT THE NEW CODE FOR NATIONAL ELECTRICAL SAFETY CODE CALLS FOR WIRES OVER A ROADWAY TO BE AT LEAST 18 FEET FROM THE GROUND.

K.R.S. 189.222 STATES HEIGHT OF SEMI CAN'T BE HIGHER THAT 13 FEET 6 INCHES.....





Jackson Purchase Electric Cooperative Corporation

2900 Irvin Cobb Drive P.O. Box 3188 Paducah, Kentucky 42002-3188 Telephone 442-7321

May 10, 1988

Mr. John Land Kentucky Public Service Commission 730 Schenkle Lane P.O. Box 615 Frankfort, Ky. 40602 RECEIVED

1 - 13 122.

DIVICION OF UTILITY ENGINEERING & SERVICES

Dear John:

Re: Wilbur Nall III Accident

Attached is the master map for Line Patrols in 1988. The accident scene is in block 27. Inspection was completed February 4th, 1988. Also included are the Line Patrol Inspection Instructions which are given to our personnel. A trouble ticket was not turned in for the location where the accident occurred.

If you need any additional assistance please let me know. The sketch of the scene will follow very soon.

Yours truly,


JACKSON PURCHASE ECC


Donald R. Schaefer, P.E. Manager of Engineering

DRS/jf

الأراب والمتكافئة والراباء والمتعط فأنكر والراباء والمالية

CC: David Stiles





Jackson Purchase Electric Cooperative Corporation

2900 Irvin Cobb Drive P.O. Box 3188 Paducah, Kentucky 42002-3188 Telephone 442-7321

LINE PATROL


WHAT TO LOOK FOR


- 1. Busted insulators
- 2. Stranded wires
- 3. Any dangerous condition
- 4. Wires over houses, swimming pools, ect.
- 5. Signs, grains bins, ect. --- close to phase
- 6. Low wires
- 7. Broke poles



Dates In Block Insicate.

Date Block Completed





Jackson Purchasa Electric Cooperative Corporation

2900 Irvin Cobb Drive P.O. Box 3188 Paducah, Kentucky 42002-3188 Telephone 442-7321

May 17, 1988

RECEIVED

Mr. John Land Kentucky Public Service Commission 730 Schenkle Lane P.O. Box 615 Frankfort, Ky. 40602

17 19 19 10

DIVISION OF UTILITY ENGINEERING & SERVICES

Dear John:

Re: Wilbur Nall III Fatality

Please find attached the sketch of the accident location in Kevil, Ky. If you need any additional information please advise.

Yours truly,

Don Schan


JACKSON PURCHASE ECC

Donald R. Schaefer, P.E. Manager of Engineering


DRS/Jf

CC: David Stiles
Donnle Lanier







PROFILE UNDER LINE



ACCIDE	NT - WILBUF	R NALL 1	
ACCOL	NT # 27-98	-57 NON	DRAWN BY M.T.
LOCATIO	N - MANNING A	UTO PAR	TS, KEVIL, KY.
DATE	APPROVED BY		DRAWING NO.
5-11-88	Lon Schan	<u></u>	



CROSS SECTION OF ROAD BED AT ACCIDENT LOCATION



Number poles on sketch at tap, corners, transformers and desdends. Include retired units with 💥 . Replaced units with 🔘 MANNING AUTO SALVAGE ž Clearance Problem SKETCH OF WORK 4-26-88 WAY DRIVE Add 2 Add 3 Add Ex 2 EXI 27-88-57 190 180 360 HOLES 35-5 6 35-5 A 35-5 HISC. A MISC. Pri. V When: 2 Sine \boldsymbol{z} N Ŋ CLEARAGE Map Reference STAKING SHEET 2nd Spon 10-25 10-10 McCracken County Span System Decignation Ky 20 Mc Cracken X 27 3-10 3-10 1-2 ACSA 23' 6 3" Neutral 23' & 3' !! 1-2 7 1-2 i BUILD ONLY 27' & 4 & " SECONDARY 27'69" HO. LORK Ruling Span -NO. OF MEMBERS SERVICE DROP PRIMARY LINE SECONDARY BARE TOTAL DYDEMBUILD COVERED š * MAN HON : Staked (S)
Checked
Released for Const. LOOP METER Sheet No. _ ENGINEER METER . . Work Order No. 7.04 - 706 -162 3 Acct.# Acct# 100 0 8167 BELLANKS HISC. 2 . 4-26-88 27-88-57 27-88-15

Number poles on sketch Reset meters and transformers with FORM \$1939 (\$3000 |-41) 1000ECLEGE PREES INC., MATURALLE, INC. 27-86-56 MANNING AUTO PARTS SERVICE (100A)
SKETCH OF WORK 53. 36 TAP ¥ 6 The stay S 20-7 H & C Pri. Vaire: 2 Size S Z : H TO Map Reference STAKING SHEET E ST "G" M'CRACKEN CO A E G System Designation KY 20 - MSCARCKEN 75 ĕ 7 -ig Sec LEAD 27/-2 U þ 4 ONDER. SECONDARY SEC 4 160 NO.LOR 110 NO OF MEMBERS 8772 SERVICE DROP SECONDARY PRIMARY LINE COVERED UNDERBUILD BARE ğ ,728: NAM × SEASON OF THE PROPERTY OF THE ľ 1 14/12 £007 Released for Const. Sheet No. METER # 0 P Staked D.C. ENGINEER WELLE STA Work Order No. 2-10-114-1 000 O BAO READE MISC. Pre 80 0-186 :

TOTAL RETIRED								RETIRED	TOTAL ADDED						x	ž	ş			Ź											ADDED			
ETIRED	T	T	T						0300					T	2019	RE	प्रकृ भ	4605	SS	1	2002	£ (768	AL 0	3 6	\$7.05	1355	1350	1135	1130	TYPE	* O	CONS	-
		1											1		-	160	724	-		F			T	Т	T	- 1/1	7		_	-	NUMBER	UNITS	RUCTION	-
																3	to L			3						1					RIGHT OF V		T	
																									T	T					ANCHOR G	UY		
	T	T							Γ					T	T												T				CROSSARM		1	i
																															35' & UND	ER	3	
																															40' 4 45'			
	اً																														20. # OAE	R		
\int																																		
																								\int							GROUND			
	\perp																														INSULATOR	•		
																															ARRESTER			ê
																															CUTOUT			ISB 3V
																																		CONVERSION TO RECORD
																																		RICO
\dashv	+	╁	-	-	\vdash	-	-		_	-	\vdash	+	+	+	+	\vdash	H			\dashv	+	\dashv	+	+	+	+	+	-	_	H			3	D UNI
	\perp	_			_								_	\bot	_	L				\Box	1	\downarrow	\downarrow	1	1	1	_	L	_			UDHO		15 02
																								1								CTOR		PROPE
1	1	1	1										\dagger	十	+	T				7	+	+	7	+	+	+	1					IZE AI	365	PTV
_	4	4	-			_							4	1	1	<u> </u>				_	4	4	4	4	4	1	\perp	<u> </u>	_			141 00	į	
1																				- {		1										ň		ĺ
1	+	+											\dagger	+	†	İ				1	7	7	7	1	+	1	1	 					ì	
-	+	+	-	-	-		-					\vdash	+	+	+	-				-	+	+	+	+	+	+	+-	-	_			4	_	
+	+	+	+	-	-		-						+	+	+	-				1	+	\dashv	+	+	+	+	+	-	-		ARRESTER		368	
+	+	+	\vdash	-	-	_	-						+	+	+	\vdash				-	+	\dashv	+	+	+	+	+	-	-				5	
+	+	+	+	-	-	-	-					-	+	+	+	\vdash				-	+	\dashv	\dashv	+	+	+	+	-	-	Н			-	
1	\dagger	+	\dagger	+	-	-	-		-				+	+	+	\vdash				ا ا	<u> </u>	_ <u>-</u> -	+	- -	_ 		۔. د ا) }	 				:	İ
1	1	+	+	T	1		1	1					+	\dagger	+	T			H	7	1	1	+	+	+	+	+						5	
7	+	†	+	+	1	1	1		-				+	+	+	1					1	1	+	1	+	1	1	1			SERVICE			
1	T	T	Ī	T	T								1	+	1	1				j	1	+	1	7	十	1	1	-			METERS	à.	-+	
	1	T	1	T	1		1						1	1	1	T					1	1	1	1	T	T	1	T	1		TRANSFOR	MERS	5	MEMO ONLY
		I	I																							T	Ţ				O C R' S			ONLY
T	T	T	T	T	1								T	T	T	I				i	1	Ī			T	T	T	I			SECTIONAL	IZER		

corners, transformers and deadends. Include retired units with ... Replaced units with ... Reset meters and transformers with channing Auto SERVICE (100A)
SKETCH OF WORK 10-20-82 A A 9 E Map Relarance
Pri / Wire: 2 Size 4 STAKING SHEET A System Designation KV 20 - MSCAACKE Ĕ 1/-227/-2 22-227/-2 7 ACS 27/25/25 6 4 NO LOW D COVERED UNDERBUILD NO OF MEMBERS **** B SECONDARY PRIMART LINE TOTAL BARE ĕ 28.77 177 Drud .. 58K/ × 12/2 ë Staked D.B.
Checked
Released for Const. LOOP METER 2.5 Sheet No. ENGINEER METER Work Order No. 2-10-119-1 11: \$ B 103 HEMARKS MUSIC. .. 10-186 20 7018



BALLARD RURAL TELEPHONE COOPERATIVE CORPORATION. INC.

502-665-5186

P.O. BOX 295

LA CENTER. KENTUCKY 42056 - 0295

April 26, 1988

"Owned by those we serve"

FILED

Mr. Forest Skaggs, Executive Director Public Service Commission 730 Schenkel Lane P. O. Box 615 Frankfort, KY 40619 MAY 0 2 1988

PUBLIC SERVICE COMMISSION

Re: 807 KAR 5:006 Section 24 Reporting of Accidents

Dear Mr. Skaggs:

This is to confirm the report of an accident which occurred in our serving area in McCracken County at the end of Kingsway Drive off U.S. Highway 60 east of Kevil, Kentucky, on Thursday, April 21, 1988, at approximately 9:30 A.M. We were not notified in our office until 3:00 P.M. Thursday afternoon by David Stiles, Manager of Jackson Purchase Electric Cooperative.

At that time my Plant Manager, Durwood Whipple, was out of town and so was I. On Friday, April 22, I returned around 3:00 P.M. and at that time I tried to reach the Public Service Commission to report the accident, but could not get an answer.

On Monday, April 25, I talked to Mr. John Land with the Public Service Commission and reported the accident. At that time he said he had been notified by Jackson Purchase Electric Cooperative and that he had already visited the site of the accident and took measurements of electric and telephone lines.

Mr. Land suggested that I call Wayne Bates on Tuesday and see if he still wanted us to send in a report of the accident. After talking to Mr. Bates he suggested I go ahead and send in a report telling what I knew about the accident.

After I visited the site, we had two service drops built under Jackson Purchase Electric. At the low spot in the road our bottom wire was 12' 11½" and our top wire was 13' 3". The electric cooperative's neutral wire was 14' 1".

We were told by the Jackson Purchase Insurance Adjuster that Mr. Manning had told him that our wires had been torn down several times, but after our Plant Department ran our Trouble Log, we found that we had only had one trouble report related to the service wires. We went back to January, 1986. On June 24, 1986, we had this one report to raise our lines, that loads were going out that were taller than our lines. At that time the serviceman raised the drops as close to the neutral wire of the electric cooperative as possible. Since that time we have not had any more complaints.

If you have any questions, please advise.


Very truly yours,

BALLARD RURAL TELEPHONE COOPERATIVE CORPORATION, INC.

Harlon E. Parker, Manager

HEP:bjr

152 12 tal Accubert Not 15 Kon 1, Ky (26 hun, NAII III)





MANING ACCIDENT 4/21/38 (Willow NAH III) TATAI NEAR KENIL









int in Thin than Tatal Accident 4/21/88 NEAL KELT, Ky (W. Hai AAH III)







Regional Edition

The Poducah Sun

Thursday, April 21, 900

Paducahan electrocuted near Kevil

KEVIL, Ky. — Paducahan Wilbur Nall, M, was accidentally electrocuted this morning near

Nall, a Cairo Road resident, was killed as his heed struck a highvoltage power line across the gravel extension of Kingsway Drive off U.S. 60, about 1½-miles east of Kevil, said Jerry Beyer,

McCracken County coroner.

Nall was standing on a pile of crushed autos, loaded on a trans-

crushed aixos, losoed on a transport truck owned by Glasgow Scrap Iron and Metals Co., Bardwell Rt.

1. Nall worked for Glasgow.

Beyer said the truck was leaving Manning's Auto Salvage at the end of Kingsway Drive when the accident occurred. Nall was holding up to the property of the low-hanging telephone wires to make way for the truck.

When he stood up, his head touched the high-voltage wire above telephone wires.

Paducahan electrocuted near Kevil

KEVIL, Ky. — Paducahan. Wilbur Nall III, 28, was accidentally electrocuted this morning near Kevil.

Nall, of 8020 Cairo Road, was killed as his head struck a high-voltage power line across the gravel extension of Kingsway Drive off U.S. 60, about 11/2-colles cent of Kevil, said Jerry Beyer, McCrechen County coroner.

Nail was standing on a pile of crushed autos, loaded on a trus-port truck owned by Glasgow Scrap-iron and Metala Co., Bardwell Rt. 1. Nall worked for Glasgog.

Beyer said the truck was leave Manning's Auto Salvage at the end of Kingsway Drive when the accident occurred. Nail was slightly bent over, holding up two lowbanging telephone wires and a neutral electrical wire to make way for the truck, he said.

Beyer said Glasgest defrer William Lindner of Patricah yelled at Nall to release the power line. In response, Nall stood up, causing his head to hit a higher, positive elec-trical wire as he held the other lines.

The regult was a fatal shock of

about 7,000 volts, he said.


Beyer said he would interview officials of the salvage company and Jackson Purchase Electric Cooperative Corp., which maintains the power lines, to determine if the truck load and wires met height regulations.

Glasgow is owned by Billy Brooks of Paducah, he said.

Eight crushed cars were stacked in two piles on the truck bed to a height exceeding 14 feet, he said. The lowest phone line was 13 feet 5 inches and the lowest power line, 14 feet 5 inches, Beyer said.

He said the positive wire was 17

feet & inches.



BALLARD RURAL TELEPHONE COOPERATIVE CORPORATION, INC.

502-665-5186

P.O. BOX 295

LA CENTER, KENTUCKY 42056-0295

"Owned by those we serve"

June 24, 1988

RECEIVED

Hr. John Land
Public Service Commission
730 Schenkel Lane

P. O. Box 615 Frankfort, KY 40619

Dear Mr. Land:

DIVISION OF UTILITY ENGINEERING & SERVICES

In reference to our phone conversation of June 24, 1988, please find enclosed a copy of the work sketch. These two service drops were relocated to the new poles set by Jackson Purchase Electric Cooperative on May 10, 1988.

See the measurements from the work sketch at the pole, the 21'2" is the distance from road level to our attachment. I think the rest of the measurements are explanatory.

If you have any questions, please advise.

Very truly yours,

BALLARD RURAL TELEPHONE) COOPERATIVE CORPORATION, INC.

Harlon E. Parker, Manager

HEP:bjr

Enclosure

WORK SKETCH

TOW ISSUEDAN