Meadowbrook

APRIL 2009

Rm 29th Diffusers Back on line - January - added 1 Skid
Decklon - chlorine Tabs Good - Flow
4 6pm Effluent Clear - (Good)

Rm 30th Diffusers off line Due To Rain in Area
no Decklon needed - chlorine Tabs (Good)
Flow 3 6pm Effluent clear (Good)

MAY 2009

Diffusers (offline)

Fri 2nd — Major Rain Fall in Area - no Dechlon needed or added - chlorine TABS (Good) Flow 8-10 gpm Effluent clear (Good)

4th — Plant Activated Trickle on at 11:00 am, Chl box Secure Add chlor & Dechl, SR & Scum & Debris, Wet Plant down. Effl Chly & 3.

Diffusers online - (working properly)

Fri 5th — 1 sleeve Dechlon added - chlorine TABS - (Good) Flow 4 gpm ~~Effluent~~ - clear (Good) no problems

6th — Trickle Plant Activated off at 10:45 am, 8 gpm Add Chlorine & Dechl.

Fri 7th — no Dechlon TABS (needed) on added chlorine TABS - (Good) Diffusers - online working Properly - Flow 5 gpm Effluent clear - (Good)

Fri 9th — 1 sleeve Dechlon added - chlorine TABS (Good) Diffusers online - working Properly Flow 3 6pm - Effluent clear - no solids clear - (Good)

Fri 11th — 1 sleeve Dechlon added - chlorine TABS (Good) Diffusers online working Properly Flow 4 gpm Effluent clear (Good)

MAY 2009

Rm 12th — 1 sleeve Decthlon ADDED - chlorine TABS (Good) Diffusers online - working Properly - (Good) Flow 4 6pm Effluent clear - (Good) -

13th — Check Plant all equipment working OK, Plant EFFLN = Clear 3pm

14th — Chk bar Screen, Scrpt Hippo, SR and Dsbn Hopper - OK, Plt Effln = Clear 3pm

Rm 15th — Decthlon ADDED (1 sleeve) chlorine TABS (Good) - Diffusers online working Properly - Flow 3 6pm Effluent clear (Good)

18th — Chk bar Screen, SR, Dsbn, Chk Wpas Chk Sludge Fm chlorine Contact Tank, ALL Chks = Dsbl. ALL Chk to Aeration Fm Effluent Cont. Effln = Clear 3pm

Rm 19th — chlorine TABS (Good) - ADD - 1 sleeve Decthlon - Diffusers - Tested - working Properly no RAIN - In Area Flow 2 6pm Effluent clear (Good)

20th NO Dechlon needed or added. Chlorine
RM Tabs (Good) - Diffusers on line and working
Properly - No Rain - In Area Flow - 2 to 3 gpm
Effluent clean (Good) - no solids

21st Pumped out Cl2 Contact Tank, Cl2 box
Serviced & Work, Wet Plant down, refill Chlorine & Dechlor
All equipment working, Plant Effluent @ Chlorine 3 gpm

RM 23rd 1 sleeve Dechlon added - Chlorine Tabs -
(Good) Condition - Diffuser - Tested on line -
(no Rain) Flow 3 gpm - Effluent clean -
(Good) - no solids - or Debris -

25th Plant Tank off 4:30pm Chlorine - 8 gpm

26th Plant Aeration Tank back on at 11:00am Cl2 box
Serviced, Serviced Hopper, Cl2 Water, SRT Sampled Down
Harmony, Plant Effluent @ 8 gpm Chlorine & Dechlor

RM 27th Filled - Dechlon - Tube - 1 Sleeve
Chlorine Tabs (Good) Diffusers on line
Tested - Working (Good) - Rain In Area
No Impact Flow - 2 gpm - Effluent
Clear - (Good) - (no solids)

May 2019 Cont'd

[illegible] Club Low Sensor, Size Drum, and Chlorine & Dilution Pot Effluent to Clarifier

Jun 30th - 1 Sleeve Decliner ADDED - Chlorine Tabs (Low) - But Still (Good) - Reset Timers - Polymers Tested - Working Properly online - Effluent Clear - Good for Solids

June 2009

1st Chl bar Screen, SIR-1 Diberry, Add chlorine Dechlor, Lubricate Equip, Wet Plat down Effluent = Clear 1.5gpm

2nd Chlorine TABS (Good) - ADDED 1 sleeve Dechlor - To Dispensers - Diffusers - online working Properly - (Good) - Flow 2 gpm Effluent clear - (Good)

3rd Chlorine TABS (Good) - Dechlor - OK - Diffusers online - working Properly - (Good) - Flow 3 gpm Effluent - Clear - (Good)

4th Chl bar Screen, Add chlorine + Dechlor, All equipment working, WET PLT Effluent = Clear 1.5gpm

6th Chlorine TABS (Good) - 1 sleeve Dechlor ADDED TO Dispenser - Diffusers (Tested) working Properly - (Good) - Flow 3 gpm Effluent (clear)

8th Chl bar Screen, Rinse Screen + Deck, Hose unit Add chlorine + Dech, Wet PLT during PLT Effluent = Clear 2 gpm

9th Chlorine TABS (Good) - 1 sleeve Dechlor ADDED Diffusers - online working Properly - Timers set - Effluent clear - (Good) Wasp nests - Flow 1 gpm

June 2009

Fri 10th Decthlon - Good - Chlorine Tabs (Good)
Diffusers Tested - working Properly
Flow .5 gpm Effluent clear - (Good)
Plant Turned off at 3:00pm

11th Skid Drums, All Chlorine Decthlon Plant
and Skid Turned off due To Rain Event

12th

13th Chlorine Tabs (Good) added / Sleeve
Decthlon - Diffusers Tested - working
Properly - (Good) - Flow 5 gpm - Effluent
slight - cloudy - in color - No - Solids -

June 2004

15th Pumped & Hauled 3000 gals of Sludge From Plant, Cl'd box Screw, SR'd Decon Treatment, All Chlon & Dechlon. No Effl.

16th NO Dechlon needed - ON ADDED - Chlonne TABS Good - Diffusers (OFFline Brown) - Tested Working Properly - Effluent Clean - Good No Solids - Flow 3 Gpm

Jun 17th Dechlon ADDED - 1 Sleeve - Chlonne TABS (Good) - Diffusers (OFFline Due To Rain) - Tested - working Properly - Effluent - Clean (Good) - no Solids Flow 4 Gpm

18th Rain Event Turn Aerators off

19th Turn Aerators back on, Cl'd box Screw SR'd Decon, All Chlon & Dechlon, Hose Plate down, Effl to Chlor & Dech

Jun 20th Dechlon 1 sleeve - Chlonne TABS (Good) Diffusers (On-Line) - Tested - (Good) Effluent Clean - (Good) no Solids

June 2009 Cont'd

22nd Addl chlorine + Dechlor, SR and Dbr thickener, Chl bar Screen, All equipt working OK, Plt Effl w/ Chlor & 1.5 gpm

Tue 23RD Chlorine Tabs (Good) Dechlor ADDED Diffusers Tested - working Properly - Flow 1.0 6pm Effluent clean-(Good) no solids

Tue 24TH Chlorine Tabs (Good) Dechlor ADDED 1 Sleeve Diffusers Tested - working (Good) - Flow 2 6pm Effluent clean- (Good) (no-solids)

26th Chl bar Screen + Weir, SR and Dbr thickener, Wet Plt down, Addl chlor + Dechl, Plt Effl w/ Chlor & 2 gpm

Mon 27TH Flow 4 6pm - Chlorine (Good) - 1/2 sleeve Dechlor ADDED - Diffusers - online working - (Good) Effluent clean-(Good) - no-solids

29th Wet Plant down, SR and Dbr thickener, Chl Bar Screen + Weir Screen Hopper, Addl Chlor + Dechlor Tablets. Treated Act. Slg with Powd Chlor as Effluent is coming back In crease Act Tm.

Tue 30TH Chlorine - Good - Dechlor - Good - OK Flow 3 6pm Diffusers Tested - online working (Good.) Effluent - Good. no solids

July 2009

1st — Cl2 Unit + bar Screen, Add Chlor + Dechl. Hand Plot down + SRT Down, Effl Clear + Dye

2nd — Chlorine (Good) - no Dechlon needed - OK. Diffusers Tested - Working (Good) - Flow 4 6pm · Effluent clear - (Good)

3rd — Chlorine (Good) · 1 sleeve Dechlon ADDED - Diffusers on line - working (Good) Flow 3 6pm Effluent (Good) - no solids

6th — Cl2 bar Screen, Scrap Hopper, Cl2 Unit, Hand Plot down, SRT Down, Add Chlor + Dechl. Add Chlorine mix To Aeration, All equipt working OK, Pond Aeration Time, Plot Flow 1pc

7th — Chlorine (Good) Dechlon (Good) - Diffusers Tested - Working - Properly - Flow 26pm - Effluent Clear - no - solids

9th — ~~Chlorine TABS (Good)~~ - Dechlon - 1 sleeve added (Good) - Diffusers - Tested - working (Good) Flow 3 6pm - Effluent - Clear - no - solids

July 2009

9th Chl bw Screen & Weir, Added Tablets, SRA Drive Thru out, Swept Happy, Wet Scrubbed baffle, Added Chlorine mix to Aeration, Plt Effluent is Clear & Good

Fri 10th Chlorine - Dechlor Good - Diffusers Tested working Properly - Flow 2.0 Gpm - Effluent Clear Good -

Fri 11th Chlorine - Good - 1/2 sleeve Dechlor Added. Diffusers online - working (Good) - 3.0 Gpm Effluent (Good) - no - Solids Visible

13th Mixt on Wheels - Sprayed Algae - Hosed Plant - Cleaned Bar Screen - Added Cl2 & Dechlor - Sprayed Foam w/ Cl2 - Epk 15 Clear @ 1" Gpm

Fri 14th No Dechlor needed - (Good) Chlorine Tabs (Good) - Diffusers Tested - (Good) - 2.0 Gpm Flow - Effluent - Clear - no - Solids

Wed 15th 1/2 sleeve Dechlor - Added - Good - Chlorine Tabs - Good - Diffusers online - working Properly - Flow 1.5 Gpm - Effluent - Clear no - Solids - Visible

JULY 2009

16th Thu — MAINT ON WWTP - CLEANED BARSCREEN - HOSED PLANT - SCRAPED HOPPER - ADDED Cl_2 & DOCTOR - SPRAYED FOAM W/ Cl_2 SOLUTION. GFF IS A LITTLE CLOUDY @ ABOUT 2 GPM NO SOLIDS VISIBLE

Fri 17th — CHlorine - GOOD - DechLor - GOOD - Diffusers on line. working Properly - Flow 1.5 GPM Effluent - clear - O/K - NO SOLIDS

20th Mon — MAINT ON WWTP - SCRAPED HOPPER HOSED PLANT - ADDED Cl_2 & DOCTOR SPRAYED FOAM W/ Cl_2 - CLEANED BARSCREEN - GFF CLEAN @ 1 GPM

Tue 21st — DechLor - GOOD - NO ADDS MADE - CHlorine TABS GOOD - Diffusers on line working (GOOD) Flow 2.0 GPM - Effluent clear NO SOLIDS - (GOOD)

Wed 22nd — Diffusers off Line - Rain Event - CHlorine TABS - GOOD - DechLor - GOOD - Flow 8-12 GPM - Effluent Clear - GOOD - NO SOLIDS

July 2009

24th — MAINT ON WWTP - TURNOS

TUE — PLANT BACK ON @ 1:00 PM
OFF IS CLOUDY @ 2 GPM
ADDED Cl_2 & DECHLOR

RM 25 7/4 — CHLORINE TABS (GOOD) - DECHLOR - (GOOD)
NO ADDS NEEDED - FLOW 1 GPM - DIFFUSERS
TESTED - WORKING PROPERLY - EFFLUENT (GOOD)
NO SOLIDS - CLEAR -

TUE — MAINT ON WWTP - SCREEN HOPPER
ADDED Cl_2 & DECHLOR - CLEANED BAR SCREEN
RESET PLANT - OFF IS A CLOUDY -
MISS DACK - PUT ON HAND

RM 28 7/14 — CHLORINE - (GOOD) - DECHLOR - GOOD) DIFFUSERS
TESTED - WORKING PROPERLY - FLOW 3 GPM
EFFLUENT - (GOOD) - NO SOLIDS - CLEAR
TWL PLANT AUTO OFF AT 9:00 PM

RM 29 7/14 — CHLORINE - (GOOD) - DECHLOR - (GOOD) DIFFUSERS
OFFLINE DUE TO RAW EVENT - FLOW 4 GPM
EFFLUENT - CLEAR - (GOOD)

30th TWL PLT AUTO BACK ON AT 12:30PM, CHL BY SCRN,
WET PLT DRY ADD CHLOR & DECHL, PLT FLOW
IS 5GPM & CLR

AUGUST 2009

Rm 1st Chlorine - (Good) - Decthlon - (Good) Diffusers online working Properly - (Good - Distribution) - Flow 6gpm - Effluent Clear - (Good) - no - solids

3rd Hand Plate down, SRM Debris, Clubbar Screw, ADD Chlor & Dechl, Effluent is Cloudy & 2.5gpm

Rm 4th Chlorine - Good - Decthlon - Good Diffuser Tested working Properly - Flow (2.0) 6gpm Effluent - Clear - (Good)

Rm 5th Chlorine Good - Decthlon - ADDED 1 sleeve To Dispenser (Good) - Diffusers Offline - Due To Rain Event - Flow 6 6pm Effluent - Still - Good - no - Solids -

6th Club bar Screw, Club Wing, SRM & Screw & Diffuser Hand - dry, ADD Chlor & Dechlor, Effluent is Clear & 2gpm

Rm 8th ADDED 1 sleeve Decthlon - Chlorine TABS Good! Diffusers Tested - working & Good Flow 2.0 6pm - Effluent Clear (Good)

Aug 2009

10th Cld bar Screen, Scraped Wiper, SR and Screen Dubrin Hum over, Aer Cl low + Double PLT Effl is Clear + 1.5 ppm

Rm 11th CHlorine TABS (GOOD) - DecHlon - (GOOD) NO-ADDS- needed -> Diffusers - Tested working - Properly - Flow - 3 6pm - Effluent Clear - (GOOD) - no-Odor - no-SOLIDS

Rm 12th CHlorine - GOOD - ADDED 1 sleeve DecHlon Diffusers - Tested - working - (GOOD) Flow 1 6pm - Effluent - clear - (GOOD) no-SOLIDS - no-odor

13th Cld bar Screen, SCR Dubrin Hum over, EFFLR is Clear + 1 ppm

Rm 14 CAP ON DecHlon - Does NOT Need To Be Hammered - ON 'GD CHlorine TABS - GOOD - DecHlon 2 sleeves ADDED - Diffusers (GOOD) - online - Flow - 2 6pm - Effluent - CLEAR - GOOD

Aug. 2009

17th Cl-1 bar Screen, All chlor + Dechlor Sample Hopper, Cl-1 Wash, SRV Disinfectant, Wash Plate down, Plate Effl. to Clear + Dye

Mon 18th chlorine - (Good). 1 sleeve Dechlor added - Diffusers Tested - working Properly - Flow 1.8gpm Effluent clear - Good - no solids - no odor -

Tue 19th chlorine (Good) · Dechlor - (Good) Diffusers online · working (Good) - Flow 1 gpm Effluent - (Good) - clear no odor

20th Cl-1 bar Screen, Sample Hopper, Cl-1 Wash SRV beam + Disinfectant, Plate Effl. to Clear + Dye

Wed 22nd chlorine TABS (Good) - Added - 2 sleeves Dechlor - (Good) - Diffuser - Tested - working Properly - Flow 1 gpm Effluent clear - (Good) no odor - no solids

August 2009

24th Chl box Server, SR w/ Debris Thrown out, All equipt working OK, All Chlorine & Dechlor, & Effl is Clear & Tan

Fri 25th Chlorine & Dechlor - (Good) - Diffusers Tested - working Properly. Flow 1 1/2 gpm - Effluent Clean (Good) no - Excessive - Odor - no - Solids

Mon 28th Chlorine Tabs (Good) - 1 sleeve Dechlor Added - (Good) - Diffusers Tested - working Properly - Flow 1 gpm Effluent Clean - (Good) - no - Solids -

28th Chl box Server & Weir, SR w/ Debris Thrown out All Chl & Dechl All equipt working OK, Plt Effl is Clear & Tan

Tue 29th Chlorine Tabs (Good) - Dechlor - Added 1 Sleeve To Diffusers - Diffusers - Tested working (Good) - Flow 2 gpm Effluent clear - (Good) - no solids - no odor

31st Chl box Server & Weir, Scraped Nipps, SR w/ Debris Thrown out, Weed Plnts down, Added Dechlor & Chlorine, Effl is Clear & Tan

September 2009

1st	Everything look good. Little odor if any. Eff. look good. No chl. or dechl. needed today.
9-2	Everything look good. Hosed down walls added Dechl. and chl. granules. 13 blower working properly.
9-3	chl bar Screen, chl Wash, Scrpd. Hopper, SRA Dibrie treatment, added chlor + Dechl, Eff left w Clear + 1gpm
9-5	Everything looks fine. little or no odor blower working O.K. Plenty of chl. and dechl.
9-7	5 C.P.M. Everything working properly. Bit of a washout with heavy rain.
9-8	chl bar Screen + Wash, Scrpd Hopper, Wet Plant down, SRA Dibr- Treatment, Eff left w Clear + 1.5 gpm, added chlor + Dechl.

9-10-09	Everything working properly. Added dechl. Little or no odor. Hosed down plant.
9-12-09	Chl bar Screen, SR, Drum, Add Chlor & Dechlor. Effl to Chan ± 1.5 gpm
9-12-09	Everything working properly. Little or no odor. Plenty of chl. and dechl.
9-14-09	Everything working properly. Very little odor. added dechl. Hosed down plant. 1 GAL PER MIN.
9-16-09	1 GAL PER MIN. Everything working O.K. Little or no odor
9-17-09	Check bar Screen, Scrpt Hopper, Chl Water Wash Screen behind baffle, SR, Drum thoroughly. Effluent to Chan ± 1 gpm Add Chlor + Dechlor
9-19-09	Everything working O.K. ~~Added~~ added a few tablets of dechl.
9-20-09	Rain Event Alarm Turned off at 1:00 PM
9-21-09	SR, Drum, Add Chlor + Dechlor, Plant Effl to Chan ± 1 gpm

9-22-09 Everything look good, working properly Eff. look good.

9-23-09 Everything look good and working properly. Turned ~~DO~~ Skimmer on, added dechl. Hoed down plant. Plant turned OFF at 11:00 AM. Turned back ~~on~~ OFF at 5:30 PM

9-24-09 Heavy rain expected Blower off. ~~added~~ added Dechl.

9-25-09 AM Chlor & Dechlor, Plant Aeration Turned off due To rain event, Effl Cloudy & 14 gpm

9-28-09 Aeration System Turned back on AT 11:00 a.m., Chl box Secured, SRA Inverted Doors, Wash Plant down, Chl Wash

9-29-09 Everything look fine and working properly added dechl. ~~Eff.~~ Effl clear

9-30-09 Everything look good and working properly. added 2 Tabs. of dechl. Effl look good.

Oct. 2009

1st Lubricated Equipment Wash Plant down, SRA Doors & Gears, Chl box Secured and Wash, AM Chlor & Dechlor Effl Clear

Paint a Tank Today!

10-3-09 Eff. look good Everything working properly
4 GPM. added dechl.

10-5-09 Chl bw Screen, SRL Scr + Dchlr Thru out;
All chlr + Dchlr, All pumps work, OR, Effl
Chlr 1 ppm

10-6-09 It osyl down plant bar screen ECI. Everything
working properly Eff. look great.

10-7-09 Eff. look great. Everything working properly
added a little chl. and dechl.

10-8 Had Scr + Dchlr + SRL off, All chlr +
Dchlr, Chl bw Screen, Plt is Wash, very wet,
Cover Low. Gal Plt Effl is Chlr 3 ppm

10-10-09 Started plant up. Added a little chl. and
dechl. Everything working properly

10-12-09 Chl bw Screen, SRL Chlr + Scr, All Chlr +
Dchlr, Had Plt down Effl is Chlr 1.5 ppm

10-13-09 Everything looks good and working properly
Eff. look excellent.

10-14-09 Everything working properly. Added chl. and dechl. SHUT PLANT. RAIN!

10-15-09 Plant Water System slug down due to low Ewtr, added Dechl & Chlor

10-17-09 added chl. and dechl. Everything working properly. Plant up and running at 11:00 AM

10-19-09 Chl bac Screen, Wash Plant down, Surge Hopper Chl Well, Strained leaves & Debris thru - out AM Chlor & Dechl. Effluent @ Chlor 1.5 ppm

10-20-09 Plenty of chl and dechl. Everything working properly.

10-21-09 Everything working properly. Added dechl. Hosed down plant. Eff. looks great.

10-22-09 Chl bac Screen, Surge Hopper, Strained Debris, Strained leaves from Chlorine Contact Tank, Effluent @ Chlorine 1.5 ppm

10-24-09 Everything working properly. added dechl. Started plant.

Oct. 2009 Cont"

26th Chl bw Scrns, SRA Dubw, Well Pl wr dwn, DAM Tabl, Effl & Clw

+1.5 ppm

10-27-09 Everything looks good. Eff. looks great. added deckl. and a little chl.

10-28-09 Turned plant off at about noon yesterday (rain) Started plant up. Added deckl and chl.

10-29 DAM chl & Deckl. Chl bw Scrns, SRA Iron & Dubw thru out, Effl & Clear Typo

10-31-09 added deckl & gravity plant off because of high flow

November 2009

2nd Upright Sludge Ramp, DAM Chl & Deckl Chl bw Scrns, SRA Dubw & Iron, Effl & Clw.

3RD Everything working properly. added deckl. Hosed down plant.

11-4-09 Everything working properly. added deckl.

11-5-09 Clr bar Screen, Rmv leaves & Debris thru-out, Swept Hopper. Clr Weir, Hot Plate down, Labrynth Equipmt, All clear & Drills, Effluent w. Clear

11-7-09 Everything working properly. Eff. look good. added deckl. Hosed down plant.

11-9-09 Clr bar Screen, SRA leaves, Heat Plate down, Clr Weir & Chlorine Contact Tank, All equipmt works, added Chlorine & Drills, Effluent w. Clear 1.5 gpm

11-10-09 Eff. look real good. Everything working properly. Hosed down plant

11-11-09 Everything working properly. Eff look good. added deckl.

11-12-09 Heat Plate down, SRA Screen & Leaves From bar bar Eff., SR and leaves thru-out, Heat Plate down Clr bar Screen, All Chlorine & Drills, Effluent Clear 1.5 gpm

11-13-09	Everything working properly. added sludge. Eff. looks good.
11-15-09	Everything working properly. added sludge.
11-16-09	Cl2 box Screws, SRA Lower & Drive Housing Rod Lower from bulk baffle, add Chlorine Pellets to Chlor & 1.5 gr
11-17-09	Everything look good. added sludge. Shut Down plant (Rain expected.)
11-18-09	Everything looks good. Leaving plant off because of rain.
11-19-09	Started plant. Everything working properly. added sludge.
11-20-09	Everything working OK. added cl2. and sludge. Closed down plant. Eff. look fair.
11-22-09	Everything working properly. added Sludge. Eff. look good.

Nov. 2009

23rd Chl ba. Screen, SRT Debr. Thru out, Wet Plant down, Chl ba Screen, All Chlors & Dechlor Wet 1-Load of Sludg Pmpd & Wet. Effluent had som. Turbidity & 1.5 ppm. Add Chlor To Sludg. at Filtration to back

24TH Everything working properly. Plenty of chl. and dechl. Eff. look good.

26TH Everything look good and working properly.

28TH added dechl. tabs. Everything working properly. Eff. look good.

30th Wet Plant down, Chl ba Screen & Wash SRT Lasers & Debris Thru out, All Chlors & Dechlor Plant Effluent is a little Turbid & 5 ppm From Rinse Cycle.

12-1-09 Everything working properly. Plenty of chl. and dechl. Eff. look good.

12-2 Shut down plant. added dechl. Everything OK.

Dec. 2009

3rd Clr bar Screen, Scrap Hopper, SRS Lines + Debris, ALM chlor + Dechlor, Trail Plat Auto back on at 11:00 am, Effluent = Cloudy + Yes

5th Everything working properly. added dechl. Eff. look real good.

7th Clr bar Screen, Wet Plat dirty, SRS Lines + Debris. ALM chlor + Dechlor, Effluent = Clear. CV

8th Everything working properly Plenty of chl and dechl. Eff. look ~~good~~ great. Shut down plant. Rain

9th Plant still down. ~~added~~ added dechl. Cleaned bar screen. Everything look fair.

10th Clr bar Screen, Wet Scr + SRS off, ALM Chlor + Dechl. Effluent = Cloudy + Yes

12th added dechl. Everything working properly Eff. look real good.

Dec. 2009

14th Cl2 bw. Screen & Weir, SRA Down & Scum Thru-out Scrap Hopper, Add Chlor & Dechlor, Effl to Chlor @ 3 gpm

15th Eff. look great. Everything working properly. added dechl.

16th Everything working properly. Added dechl. Eff. look great. Mtl Order

17th Cl2 bw. Screen & Weir, Scrap Hopper. Main Plt down, SRA Debris thru-out, Add Chlor & Dechl, Effl Chlor @ 1.5 gpm, Add chlor To Aer Tank To Kill off Filiments

19th Everything working properly. added dechl. Eff. look pretty good

20th Quick look, Everything OK. (Summit)

21st Everything working properly. Eff. look good. added dechl.

12-22-09 Plant being cleaned today. Everything working properly.

Dec. 2009

23rd Chl. b.w. Screw, Wt Plt down, all chl.t Dechlor. SRS Dobie Thru-out, Effl. to Chl. + 3 yr

24th Shut plant down, rain coming today. Everything look good and working properly.

26th Quick check, everything fine.

27th added shell. Started plant. Everything working properly.

28th Ck. look good. Everything working properly chl. and shell good.

29th Everything working properly. added shell. Cleaned plant.

30th Chl. b.w. Screw, Wt Plt down, AMA chl.ed Dechlor, Chl. Wtr, SRS Dobie Thru-out. Effl. to Chl. + 3 yr

31ST	Everything look good. Light rain today but not enough to shut down plant. Everything working ~~properly~~ properly.
1-2-09	Everything working properly. added shell. 2 CP's.
1-4-10	Old ban Seven, SR-1 Dehumidifier, Sewage Wagon. All equipment working. Equipt Lubricated & Effluent Clear & dye
1-5-10	Everything working properly. Plenty of shell and shell. Eff. look good.
1-6-10	Everything working properly. Eff look good. Plenty of shell and shell.
1-8-10	Church Plant all equipment working OK Plenty shell & Shell. Effluent Clear & dye. Very Cold Weather
1-9-10	Plenty of shell and shell. Everything look good and working properly

Jan. 2010

1/1	Chl. bar Screen, SR-1 Disc. chl. Well #1
	Plant drop. NaH Drill & chlor. Effluent to Clar
1-12-10	Everything working properly. Plenty of chl. and dechl. Eff. look good.
1-13-10	Everything working properly. added dechl. Cleaned bar Screen. Eff. look good.
1-14-10	Sample Hopper, Chl. Well & bar Screen, Wet Plant down NaH, Tablets, Effluent to Chlor & Sump
1-16-10	Everything working properly. added dechl. Cleaned bar screen. Eff. look great.
1-17-10	Plant Ant. in Test off at 9:30 am due Tues to ice Eval
1-18-10	NaH Chlor & Drilling Pumped 1000 gal of Sludge from Plant. No Drainage.
1-19-10	Still a lot of flow. Plenty of chl. and dechl. Eff look pretty good.
1-20-10	Plant down rain. Everything look pretty good added dechl. Need not to get trash out.

Jan

225 Rain Event

1-23-10 Plant still down, too much flow. More rain expected. Added dechl. Cleaned bar screen

1-25-10 Started plant, cleaned up some. Everything working. added dechl.

1-26-10 Cl2 bar Screw, Chk'd Equipt OK, All Chlor + Dechl. Effluent OK.

1-27-10 Everything looking good and working O.K. Plenty of Cl2 and dechl. Eff. look good.

1-28-10 Cl2 bar Screw + Wash, All equipt working OK, All Chlor + Dechl, Effluent + Chlor + Eye.

1-30-10 Eff. look good. Everything working O.K. Added dechl.

Feb. 2010

1st Chk bar Screw & Weir, Rub Ice, AMM Chlor & Bubb., All equipt working or, Effluent Chlor & Ls ok

2-2-10 Everything working OK Ph. looks great Cleaned up plant some, Plenty of Cl. added Cl. ~~added~~ added Cl.

2-3-10 Everything working OK. Ph. looks great Cleaned up plant Plenty of Cl. added Cl.

2-4-10 Chk bar Screw & Weir, All equipt working OK, AMM chlor & Bubb, Effluent Chlor & Ls ok

2-6-10 Plant Down. Too much flow. added Cl.

2-8-10 Turn Plant backwards on AMM Chlor & Bubbler all equipt working OK, Effluent Chlor & Ls ok

2-9-10 Start down plant. ~~Flow picking up~~ Flow picking up and will continue to. added Cl.

2-10-10	Started pool. Everything working OK added shock.
2-11-10	Cl. bar Scum, SRed. Dolw. N.W. Chlor + Dechl. Algae work on Eff. & Clean 3.
2-12-10	Eff. look good. Everything working properly added shock.
2-14-10	~~Good~~ Everything working properly. Eff. look Great. Added shock.
2-16-10	Maint Pool Scrub tapper, Skim Top add Tablets Eff Clean
2-17-10	Eff. look good. Everything working OK. Plenty of chl. added shock.
2-18-10	Test Pool Alkan. System OFF at 1:00 p.m down To Spa wall. Cl. bar Scrub SRed Dolw, Vac Pool down, Add Chlor + Dechlor, Eff. bar with Tablets, Flow is 10 gpm

2-20-10 Plant still down, too much flow

2-22-10 Turn Plt back on at 2:30 p.m., chk bin Screw SKid Debris, AAU chk & Drill, Eff Lvl = Clr, grd 3 yr

2-23-10 Everything look good and working properly. added feed. Cleaned up plant.

2-24-10 Everything working properly. Clr. look good. added feed.

2-25-10 Chk'd Plt all equip working OK, AAU chk & Drill, Eff Lvl = Clr, ~1.5 yr

2-27-10 Clr. look great. Plenty of feed. Everything working properly. Added feed.

March 2010

1st chk bin Screw & Wash SKimmer Debris thru out Lubricate Equip, AAU chk & Drain, Wash Plant down, Eff Lvl = Clr, 1 yr

2nd Clr. look great, Everything working properly. Cleaned up the plant

3RD	Eff. look great Everything working properly. Cleaned bar screen. Plenty of chl. added dechl.
4TH	Chl bar Screw SRW Down, All equipment W.R. OK, All Chlorine Dosing Eff. Flow. Clear & Dry
6TH	Everything look good and working properly. Plenty of chl. added dechl.
8TH	Eff. look great. Everything look good and working properly. Plenty of chl. added dechl.
9TH	Everything look good and working properly. added dechl. Cleaned Sep plant.
11TH	Everything look good and working properly. added chl. and dechl. Cleaned bar ~~to~~ screen.
12TH	Everything working properly and looks good. Heavy rain expected today. Shut down plant at 12:00

14th	Turned on plant. Everything working properly. added chl. and dechl.
15th	Check Plant, Effl. Cloudy since it was Turned off
16th	Inspect aeration Tank, Check bar Screen, added Chlorine Dechlor, Effl. Cloudy & light
18th	Eff. is clear. Everything working properly. Plenty of chl. added dechl. Cleaned up plant.
19th	Hard Plant down, Check Weir & bar Screen, Screen Hopper, Rinse Screen from bucket before, Added Chlorine & Dechlor, Effl. is Clear & Light
20th	Eff. look good. added dechl. Plenty of chl. Chemical bar screen. Everything working properly
22nd	Check bar Screen, Added Chlorine + Dechlor, Effl. is Clear & Light

23RD ~~Started~~ Started plant. Everything look good and working properly. Cleaned bar screen. Plenty of chl. and dechl

24TH Off. Look good. Everything working properly. Added dechl. Cleaned plant up some.

25TH Pumped out Well 1000 gals of Sludge From Plant Chl bar Screen, all chlor + Dechlor Scrubber Hoppers, NO pumps work OR EFFLUENT. Cleaned Sys

27TH ML a little dark, but coming around Plant was down about 24 due to rain. Back on 28TH about noon. Everything working properly added chl. Cleaned bar screen.

27TH Shut plant down (rain)

29TH Started plant. Everything working O.K. ~~Plant~~ Plenty of chl. and dechl. Cleaned bar screen.

March 2010

30th Cl bar Screw, Rod Scr Fr Cl nozzle, ANN Tubing, Wt Plt dump Inspect Auto Trans on Plt Auto Trans has been Turned off quite a bit. Effl is Clear + 1.5

31st Plant looking a lot better. Eff. look good. Everything working properly. Cleaned up plant. Added Shell.

April 2010

1st Cl bar Screw, SRA Debris Hum-a-nay, ANN Zahm & Denbury Scrpt Happy All equipt working OK, ANN Zahm Parts To Austin For Testing Filtration

3RD Eff look good. Everything working properly. Added Shl., plenty of shell. Cleaned bar screen.

5th Hand Plant down, Rod Scr & Debris, Cl bar Screw Scrpt Hopper Cl Wire, ANN Tubing. Effluent is OK again

6th Eff. look good. Everything working OK. Plenty of Mix shell. Cleaned up plant.

7TH Everything look great and working properly. Plenty of chl. added daily. Turned PLR off at 8:00p

8th Chl bar Screen, SRM Debris, AM Tablets, Turned Plnt over to back up. PLR Flow: 5gpm

10TH Eff. look good. Everything working properly. Plenty of chl & daily. Cleaned bar screen.

12th Chl bar Screen, Rmvd Scum & Debris from Surface, Wash Platforms, Add Chlorine & Dry Ice, Chlorine Analysis as 1 bar Fibersphere, Effluent & Clarifier 5gpm

13TH Everything working properly. Eff. look good. Plenty of chl. added daily. Cleaned up. plant.

14TH Everything look great and working properly. Cleaned bar screen, added daily.

4-15-10 *Eff. look real good. Everything working properly. Plenty of dil. added drill. Cleaned up plant.

4-16-10 Scrapt Hopper, Cl'd bin Screw, Skid Debris Add. Decklr. & cables, Eff'd's & cleaned up Cables-Trays, Alarms for Fabrications

4-17-10 Shut down plant 6PM 16TH. Started (RAM) ~~back~~ back up 9:00AM 17TH. Added drill. Everything working properly. Cleaned box screen

4-19-10 Chuck, can you get me a ~~pump~~ High pressure nozzle for hose I lost mine. Everything working properly Eff. look good. added dil. and drill.

4-20-10 Cl'd bin Screw & Wire Belt Plant down, Rmvd Screw Debris, Scrapt Hopper, Add Cables & Decklr. Eff's & Cleaned up

4-22-10 Scrapt Hopper, Rmvd Screw, Add Trolley, Eff's & Cleaned up

4-24-10 Shut down plant. Heavy rain expected next 2 days. Everything working properly. Added lime. Plenty of Cl2.

4-26-10 Cl2 ban Screw, Scrub Debris, Start Plant Aeros add Chlor + Bullion, Plant Trail back up at 2:00pm Effl Cl2 4 5ppm

4-27-10 Plant Trail off at 9:30am

4-28-10 Plant Trail back on at 11:30am, Cl2 ban Screw, Trail Screw + Debris, Scrub Hopper-Clar well, add Tablets, Effl Cl2 + Pos-4 2ppm

4-29-10 Effl. looks good Everything working properly Cleaned bar screen.

4-30-10 Everything working O.K. and look good. added lime. Shut down plant. Heavy rain expected

May 2010

3rd	Chl bar Screen, add Chlorine & Dechlor, SR in Drum, Lubricate Equipt, Plant Secure. Still Treating due to Rain Event, 10 gpm
4th	Started plant. ML is slack, adjusted timer. Return lines were not pumping. Got them going. added dechl. Plenty of chl.
5th	Everything working properly. Chl. look good. Set timer back to normal. Added dechl. Cleaned bar screen
6th	Add Chlorine & Dechlor, Shut Plant down, Chl bar Screen Scrapl Happy, Chl Wash, Effluent is Clear & 3 gpm
7th	Everything look great and working properly. Added dechl. SHUT DOWN PLANT 7pm
8th	Started plant up Everything look good, working properly. Cleaned bar screen.
10th	Chl Bar Screen, SR in Screen & Drum Hose out, Shut Plant down, Cleaned wash, Screen Scrapl Happy, Add Tablets Effluent is Clear & 3 gpm

11TH Everything working properly. Plenty of oil and fuel. Let plant run about an hour, shut back down. Rain expected

12TH Turned plant on at 2:00 pm Everything look good and working properly. Slight chance of rain later. Added fuel.

13TH Add Chlorine Bottle, Wet Plant down, START Ozone, Check for Sewer & Water, Effluent is Clear & Typ

15TH Everything look good and working O.K. Eff. look real good. Added fuel. Cleaned for rain.

17TH Wet Plant down, Add Chlorine Bottle. Turn Plant Ozone back on. Effluent Cloudy & Typ

19TH Everything look good and working properly. added fuel. Cleaned up plant.

20TH — Shut down plant 4:00 PM Rain starting now. Everything look good and working O.K. added cl2 and sodd.

21ST — Turn Plant Aeration on at 11:00 PM, Cl2 bar Screen Nat Plt down SRA Dchm Thru comp, Add Tablets Effluent 1.4 Cl2 1.5 ppm

22ND — Plant flooded last night adjusted timers to keep plant off during the day today. added sodd.

24TH — Cl2 bar Screen, Add Tablets Nat Plt down SRA Dchm Effluent Cl2 2 ppm

25TH — Everything look great and working properly. Plenty of cl2 and sodd. Cleaned up plant.

26TH — Plt. look great. Everything working properly. Added sodd. Cleaned bar screen.

May 2010

28th	Cl'd bar Screen & Wet Well Screen & Debris from out Aer Clean & Debris, Wash Plant down, Maintenance work on Excel & Clean 2 gas
29th	Everything working properly. Ff. look real good. added sludd. Cleaned bar screen.
31st	Everything look fine and is working properly. added sludd. Cleaned up plant.

June 2010

1st	Cl'd bar Screen, Wash Plant down, Small Debris, Aer Diffusers Clean, Plant Effluent to Clean & 2 gas
2nd	Everything look great and working properly. Empty ff. and sludd. Cleaned bar screen.
3rd	Everything look great and working properly. added sludd. and ff. Hosed down plant.

June 2011

4th Cl bar Screen, SRM Debris, Add Chem & Debris, Sept Hopper Effl. & Clay

7th Cl bar Screen, SRM Debris Hum-vac, Sept Hopper, Hyd Pkg drawer, Add Chem and Debris Ipcmd Aer. Tank to Effluent to Filter Clay.

8th Everything look good and working properly Plenty of Al. and Acid. Cleaned bar screen.

9th Heavy rain shut down plant 6:30 PM

10th Started plant 9:00 AM ML. up little graph, but will come back quick Everything working properly. Cleaned up plant. Added Acid.

11th Cl bar Screen, SRM Debris Hum-vac Add Chem & Debris, Ipcmd Aer. Tank to Effluent to Stn Clay.

15th M.L. a little ~~d~~ dark. Ff. still look good. added alcl. Cleaned bar screen Everything working OK. Shut down plant 7:00 pm (rain)

16th Started plant 3:30 pm added alc. and alcl. cleaned bar screen. Everything working OK.

17th Everything look pretty good and working properly. Added alcl. Cleaned up plant.

18th Chl bar Screen & Weir Wash Plant down, SRA Screw & Drive, Aer Clean & Drain, Effluent & Clean 1.5 Jr

21st Everything look good and working OK. Cleaned bar screen. added alcl.

22nd Chl bar Screw & Weir, SRA Drive thru out Surge Hopper, Effluent & Chamber

24th — Everything look good and working O.K. Eff. look real good. Plenty of ice and slack. Cleaned bar screen.

25th — Cln bar screen, Scrap Hopper, Cln Wire, Hand Pkt down, add Cleaned Peeler, Eff Low Clean & Dip.

26th — Everything look great and working properly. Plenty of slack and ice. Cleaned bar screen.

28th — Cln bar Screen, Sized Drum, Add Chlor & Drum, Eff Lt to Clean & Dip.

29th — Everything look great and working properly. Plenty of ice and slack. Cleaned bar screen.

30th — Everything look real good and working O.K. Cleaned bar screen, added slack.

July 2014

2nd Chk bar Screens, Chk Water Tank, Wash Plant down, Lubricate Equipt, All equipment work OK, Effluent to Clarifier, added Chlorine & Dechlor

3RD Everything look great and working properly. Added dechl. and shaked down plant. Took flow the nozzle.

6th Chk bar Screen & Water, Wash Plant down, All equipment work OK, added Chlorine & Dechlorine Effluent in Clarifier 1-5 ppm

7th Everything look great and working properly, Cleaned of chl. and dechl. Cleaned bar Screen

8th Everything look great and working fine. Added dechl. cleaned up plant. Shut down plant around 5:30 pm (rain coming.)

10th | Started plant. Everything look good and working fine. Added DEF and ULSD. Cleaned bar screen

11th | Chk box Survey Chk Wire SPL Sand Drains, Add Chk + Dubbing Eff Lift Chk + 2yr

13th | Shut down plant (Storm) Everything look good and working fine

~~14th~~

14th | Everything look ~~good~~ great and working fine. added ULSD and DEF. Cleaned up plant. Started plant back up last night 7:00 PM

15th | Everything look great and working O.K. added ULSD and DEF. Heated down plant

16th | Everything is fine.

17th | Shut down plant. Too much flow from rain

19th Everything look good and working fine. Added deckl. Cleaned up plant. Started plant 9:05 AM Tuesday. Shut down plant about 7:00 PM rain coming.

20th Started plant around 11:00 AM Everything look good and working fine. Added chl. and deckl. Cleaned up.

21st Shut down plant 8:00 AM Rain

22nd Stopped up plant 9:00 AM M.L. a little dark but not bad. Added chl. and deckl. Cleaned up plant. Everything working.

23rd Everything look good.

24th Everything working now. Had an airline broken fixed it. M.L. a little ~~dark~~ dark, but coming back. Added chl. and deckl.

26th	Everything look great air leak leaking OK. Cleaned up plant added diesel.
27th	Everything look real good. added diesel. Cleaned up plant. air leak is not leaking.
	1-Lady in Study Employment
28th	Everything look great. Eff. is glass clear. Everything working fine. Added diesel. cleaned up plant.
	Shut down plant. 6:00 PM (rain)
29th	Started plant 9:30 AM Everything look good and working OK added oil. and diesel. Cleaned up plant.
31st	Everything look great and working properly. Plenty of oil, added diesel. Cleaned up plant.

August 2010

8-2-10 Everything look great and working fine. ~~Called~~ added shell. Cleaned up plant.

8-3-10 Chl bar Screen SRW Drb motor went, Scrapl Wapper, Wtl Plt down, Lubricated Equipt, still Drbln & Chlorine Effluent is Clear 1 ppm

8-4-10 Everything look great. added shell. Plenty of chlg Hosed down plant. Everything working properly.

8-5-10 W.W Plt down, Chl bar Screen & Wtr, SRW Drbm Thru-out, still Chlor Dosing Effl is Clear & 1.5 ppm

8-7-10 Everything look great and working properly. Added shell and cleaned up plant.

8-9-10 Shut bar Screen, 1 Wtr Scrapl Wapper, still Tablets, Wtl Plt down, SRW Drbing Effl is Clear 1.5 ppm

8-10-10	Everything look real good and working properly. Added shell. Cleaned up plant.
8-11-10	Everything look good and working O.K added shell and shl. Cleaned up plant.
8-12-10	Everything look great and working O.K. Added shl. and shell. Cleaned up plant.
8-13-10	Hard Plant down, SRM Debris, Add Chlorine Building Effluent to Clow & 1.5 yp
8-16-10	Inspected Chestnut Trail, Add Chlorine Dublin Club bar Screen, SRM Debris, Plant Effluent to pool & 1.5 yp
8-17-10	Like the new hose. Everything look pretty Rain M.G. is a little low. Put Tarp on shl. and shell. Everything working OK. Cleaned up plant.

8-18-10 Everything looks good and working fine. Plenty of oil and deisel. Cleaned up plant.

8-19-10 Oil in Screw, Unit Plant down, SRU Down Thermocouple working on, added Oil and Diesel, Effl. to Clean 1/2 gr

8-21-10 Everything looks fine, Eff. clear and working fine. Cleaned up ~~plant~~ plant. added oil and deisel.

8-23-10 Oil in Screw, SRU Down Thermocouple, Unit Plant down, Added Oil and Diesel, Effl. to Clean 1/2 gr

8-24-10 Everything looks good and working fine. Plenty of oil and deisel. Cleaned up plant.

8-25-10 Everything looks fine and working O.K. added deisel, cleaned up plant.

8-26 Changed Bio-Screw and Motor, SRU Down Unit Plant down, Added Oil and Diesel, Effl. to Clean 1/2 gr

8-28-10 Everything look great and working fine. Added shell. Cleaned up plant. Plenty of ml.

8-30-10 Chk bow Screen - Working Sample Water, Wet Plat & Screen Down, SRT Drive belt Chk bow & Drive, Effluent - Clear 1 gpm

8-31-10 Everything look good and working OK. Plenty of ml and shell. Cleaned up.

Sept 2010

9-1-10 Everything look great, and working fine. Added ml and shell. Cleaned up plant.

9-3-10 Chk bow Screen, Wet Plat down, belt Tight, Influent Equipt, Effluent - Clear 1.5 gpm

9-4-10 Everything look good and working OK. Plenty of ml and shell. Cleaned up plant.

Sept. 2020 Cont'd

7th Chl bar Screen, Add Decht. + Chlorine, Wet Plant down, SR moved Debris, Plant Effluent is Clear + 1.5 ppm

8th Everything look pretty good and working O.K. added chl and decht. Cleaned up plant.

9th Add chlorine Decht. chl bar Screen, All equipment working OK, Effluent is Clear

Pumped & chl chlorine Tanks, Pumped down to Sludge from Plant

11th Everything look great. Plenty of chl. added decht. Cleaned up plant.

13th Chl bar Screen, SR'd bar + Debris Chl Weir, Wet Plant down, Add chlorine D.H. Effluent is Clear + 0.5 ppm

14th Everything look pretty good, and working O.K. Plenty of chl. and decht. Cleaned up plant.

15th — Everything look good and working fine added deck, cleaned up plant

16th — Cl'd bow Screw W.A Plant down SCW D'bris thru out, ADD Tables, Effl'n Clear 1 ppm

18th — Everything look real good and working O.K. Added Cl. plenty of deck. Cleaned up.

20th — Cl'd bow Screw & Wash Screw & Wipper SCW Debris thru-out, ADD Chlor & Dechlor, W.A Plant down, Effl'n Clear 0.5 ppm

21st — Everything look good and working O.K Plenty of Cl. and deck. Cleaned up

22nd — Everything look real good and working O.K. Added Cl. and deck. Cleaned up ~~plant~~ plant.

23rd — W.A Plant down, Cl'd bow Screw RW Screw Thru out, No equipt working only ADD Chlor Dechlor Effl'n Clear 1 ppm

25th Everything look good and working OK. Added sludge ~~clean~~ cleaned up plant. Plenty of sludge.

28th Everything look good and working O.K. Plenty of sludge and sludge. Cleaned up.

29th Everything looks good and working fine. Plenty of sludge and sludge. Cleaned up plant and good while it was here.

Pump in Well 1 Load of Sludge from Plant

3rd Cl Bar Screen, Wet Pit down, Cl Wet Well Cl Blower & Drive, Screw & Drive. Effluent Cl Meter

10-2-11 Everything look good and working fine. Added sludge. Cleaned up.

Oct- 2010

4th — Cleaned bar Screens, Weed Screen behind baffle, Skimmer Arm & Debris Thrown out, Added Chlorine & Dechlor, Inspected Equipment, Effluent is Clear & Iyer

5th — Everything looks fine and working OK ~~Plant~~ Plenty of Chl. added Dechl. Cleaned up plant.

6th — Everything looks good and working fine. added Dechl. and cleaned up plant.

8th — Cleaned bar Screens, SKIM Debris From Clarifier, Added Chlorine & Dechlor, Effluent is Clear & Iyer

9th — Everything looks good and working fine. Eff. looks great. Added dechl. Cleaned up.

11th — Cleaned bar Screens, Weed Screen SKIM Debris from Plant dump Screens Wiped Chl Wires, Added Chlorine Dechlor, Effluent is Clear & Iyer

10-12-10 Everything look real good and working O.K. Added dechl. cleaned up plant.

10-13-10 Everything look good and working O.K added dechl. and cleaned up plant

10-14-10 Chl bm Scum, SRT Iron & Dobay, AWJ Chlorine Dechl, Effl Clarifier

10-16-10 Everything look good and working O.K. Added chl. and dechl. Cleaned up plant.

10-18-10 Plant Sludge bm Developed Filamentous Trouble with Chlorine & Austin Scum Clarifier Scum & Weir Had Plant down SRT Iron & Dobay treatment Effl in Clarifier

10-19-10 Everything look good and working Rec. Plenty of chl. added dechl Cleaned up plant.

10-20-16 Everything look good and working O.K. added bckt. Cleaned up plant

10-21 Plant Sludge has Filamentous, Treating with Chlor, Chl box Screw, SRT Lower & Divert, All Chlor & Drilling, Effl w. Cloudy

10-23-16 Everything look good and working fine. Plenty of chl. added bckt. Cleaned up.

10-25-16 Chl box Screw, Had Plot down, Rot-Lower From Plot, Scrap Wiper, Chl Wire rand Stuff From Clarifier Tank, All Chlor & Drilling, Plot has Filament Rolling, Tan chlorine Stuff, Effl Cloudy & Crud & Jar

2016 SHUT DOWN PLANT (RAIN)

2714 Started plant, added bckt. and chl. Cleaned up plant.

Oct. 2016

28th Rain heavy, still Dosing, All equipment working OK, Effluent is Clear & Tasteless

29th Chlorine bar Screen, Wash Fan & SR all heavy Dosing, Chlorine Analyser Study, Wash Platform Rain heavy Fan Clarifier & Chlorine Tank, All Chlorine & Dosing Effluent bar Screen Turbidity Analyser Fluorine

30th Everything look OK. and working fine. Added Alum. Plenty of alum. Cleaned up room.

November 2016

1st Wash Screen down & SR all heavy, Chlorine Screen, still Chlorine & Dosing, Inhibitor Equipment Effluent is Clear & Tasteless

2nd Sludge level is high, 1 Load 3000 gals of Sludge Pumped & Wash Fan Plant.

3rd Everything look fair, and working OK. Added Alum. Cleaned up plant.

6th Plant look better today, everything working O.K. Cleaned bar screen, added chl. added.

8th Add chlorine & Dechlor. Had Plant down, Cl bar Screen, Had Screen & SKL Debris, Effluent is clear & typ. We are Testing Filtration in Accordance with chlor

9th Cl. look real good. Everything working O.K. Plenty of chl. and bell. Cleaned up plant.

10th Everything look pretty good and working O.K. added chl. and bell. Cleaned up plant.

11th Cl bar Screen & Weir, Had Plant down SKL Debris, Add chlorine Dechlor

Nov. 2010

15th CW bar Screw, Wet Plt down SRA Lines & Dubs. Hammer, All Chlr & D.W. Effl to Clr #2 Sys

~~16th~~

16th Added shell, Everything o.k. Plant down plant

17th Started plant, everything look pretty good. Added chl. and shell. Cleaned up plant

18th CW bar Screen, SRA lines off Plt, All Chlr & Dubs Effl to Clr #2 Sys

19th Everything look good and working O.K Plenty of chl. and shell.

22nd CW bar Screen, Wet Plt down, Wet Fine & Screen & SRA bar, All Chlr & Dubs, Effl to Clr #2 Sys

24 SHUT DOWN RAIN

26th Started plant, added chl. shell

Nov. 2010

Sun. 28th	Everything look better and working O.K. added shell, chl. to ML. Cleaned up plant.
3rd	Took Plant down at 7:30 pm Rain Env Chl to Serv, Well Plant down, SRU Low & Up Low, All Chlor & Bubbles, Eff Lt with Club & Jyr

Dec. 2010

12-1-10	Started plant.
12-2-10	Everything looks fine and working OK added shell Tabs
12-4-10	Snowing. added chl. and shell. tabs Everything ~~work~~ working OK and looks pretty good
12-6-10	Well Plt down, chl to Serv, SRU Low Hum-vey, All Chlor Bubbles, Eff Lt, Club & Jyr

12-7 Everything [illegible] good, including eff, and working fine. Plenty of MO and deebl.

12-8 Everything look good and working O.K. added deebl. Cleaned up plant Done.

12-9 Chl bar Screen, Wet Pit down, Strl Down Hammermill, Inf, Aft Chlor Dosing Eff Pit & Chlor Bypass

12-10 Everything look good and working OK added deebl. Cleaned up plant. Shut down plant! Pain expected Today

12-11 Started plant

13th Everything look good and working O.K. added deebl. ~~Cleaned~~ Cleaned bar Screen

14th Wet Pit down, Strl Down Screen, Hammermill Chl Wet Pit Bar Screen, Aft Chlor & Dosing Eff Pit & Chlor 1.5 gpm

December 2010

16th Shut down blower at 1:00 pm as we are having heavy flow, still adding Del-Floc

18th Started plant. Some odor, but not bad. added alk. and del-floc. Cleaned bar screen

20th Cln bar Screen & Wash SRwl Grnd. & Debris Hopper, Scrngd Hopper, Wash Plant down, shut blower & Drill. Eff Flow to Clarifier

21st Shut down plant - 11:15 AM

22nd Started plant - 11:00 AM Everything look good and working OK added alk. and del-floc tabs. Cleaned up around.

24th Everything look good and working O.K. Plenty of alk. added del-floc

26th Everything look good and working OK added del-floc.

Dec. 2010

27th Chl bar Sump, All equipt work OR, All Chlor + Dublr, Eff Cl was 1.5 ppm

28th Everything look good and working fine. Added chl.

29th Everything look good and working fine. Added chl. Cleaned up plant. Shut down plant. Rain coming.

30th Rain Event, Flow to heavy, T. Twnl on Auto, All Chlor + Dublr, Had Scm off Channel, Chl bar Scm.

31ST Added chl. Way too ~~much~~ much flow to start. More rain coming.

AERATION BASIN

Utility: Meadowbrook S.D. Inspected by: Richter Inv.

Month: Dec. Year: 2010

Day	Even air distribution (any dead spots?)			Diffusers?				Air leaks around base and fittings of blower?			Blower belts wear and tension?				Unusual noises or vibration?		
	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs Maintenance	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs Maintenance	Yes	No	Needs Maintenance
1																	
2		✓		✓					✓			✓				✓	
3																	
4		✓	✓						✓			✓				✓	
5																	
6		✓		✓					✓			✓				✓	
7		✓		✓					✓			✓				✓	
8		✓		✓					✓			✓				✓	
9		✓		✓					✓			✓				✓	
10		✓		✓					✓			✓				✓	
11																	
12																	
13		✓		✓					✓			✓				✓	
14		✓		✓					✓			✓				✓	
15																	
16		✓		✓					✓			✓				✓	
17																	
18		✓		✓					✓			✓				✓	
19																	
20		✓		✓					✓			✓				✓	
21		✓		✓					✓			✓				✓	
22		✓		✓					✓			✓				✓	
23																	
24		✓		✓					✓			✓				✓	
25																	
26		✓		✓					✓			✓				✓	
27		✓		✓					✓			✓				✓	
28		✓		✓					✓			✓				✓	
29		✓	✓						✓			✓				✓	
30		✓		✓					✓			✓				✓	
31		✓		✓					✓			✓				✓	

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CLARIFIER

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

Day	Sludge blanket depth					Sludge collection arm turning					Any floating material on top of clarifier?				Sludge recirculation system?					Scum recirculation system?				
	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Yes	No	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance
1																								
2	✓						✓				✓				✓						✓			
3																								
4	✓						✓				✓				✓						✓			
5																								
6	✓						✓				✓				✓						✓			
7	✓						✓				✓				✓						✓			
8	✓						✓				✓				✓						✓			
9	✓						✓				✓				✓						✓			
10	✓						✓				✓				✓						✓			
11																								
12																								
13	✓						✓				✓				✓						✓			
14	✓						✓				✓				✓						✓			
15																								
16	✓						✓				✓				✓						✓			
17																								
18	✓						✓				✓				✓						✓			
19																								
20	✓										✓				✓						✓			
21	✓						✓				✓				✓						✓			
22	✓						✓				✓				✓						✓			
23																								
24	✓						✓				✓				✓						✓			
25																								
26	✓						✓				✓				✓						✓			
27	✓										✓				✓						✓			
28	✓										✓				✓						✓			
29	✓										✓				✓						✓			
30	✓										✓				✓						✓			
31	✓										✓				✓						✓			

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CONTROL SYSTEM

Utility:_____ Inspected by:_____

Month:_____ Year:_____

	Timers?				Electrical controls?				Control housing?				Unprotected electrical connections?			
Day	Good	Fair	Poor	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Number	Maintenance Needs
1																
2																
3																
4																
5																
6	✓				✓					✓				✓		
7																
8																
9	✓				✓					✓				✓		
10																
11																
12																
13																
14	✓				✓					✓				✓		
15																
16	✓				✓					✓				✓		
17																
18																
19																
20	✓				✓					✓				✓		
21																
22																
23																
24																
25																
26																
27	✓				✓					✓				✓		
28																
29																
30	✓				✓					✓				✓		
31																

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CHLORINE CONTACT TANK

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

	Any floating material?			Any sludge?			Baffles placement to insure proper chlorine contact time			
Day	Yes	No	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs
1										
2										
3										
4										
5										
6		✓			✓		✓			
7										
8										
9		✓			✓		✓			
10										
11										
12										
13										
14		✓			✓		✓			
15										
16		✓			✓		✓			
17										
18										
19										
20		✓			✓		✓			
21										
22										
23										
24										
25										
26										
27		✓			✓		✓			
28										
29										
30		✓			✓		✓			
31										

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

AERATION BASIN

Utility: Meadowbrook Sch Inspected by: Ridg. Lee Investment

Month: November Year: 2016

Day	Even air distribution (any dead spots?)			Diffusers?				Air leaks around base and fittings of blower?			Blower belts wear and tension?				Unusual noises or vibration?		
	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs Maintenance	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs Maintenance	Yes	No	Needs Maintenance
1	✓				✓				✓		✓					✓	
2																	
3	✓				✓				✓		✓					✓	
4																	
5																	
6					✓				✓		✓					✓	
7																	
8	✓				✓				✓		✓					✓	
9	✓				✓				✓		✓					✓	
10	✓				✓				✓		✓					✓	
11	✓				✓				✓		✓					✓	
12																	
13																	
14																	
15	✓				✓				✓		✓					✓	
16	✓				✓				✓		✓					✓	
17	✓				✓				✓		✓					✓	
18	✓				✓				✓		✓					✓	
19	✓				✓				✓		✓					✓	
20																	
21																	
22	✓				✓				✓		✓					✓	
23																	
24	–				–				–		–					–	
25																	
26	✓				✓				✓		✓					✓	
27																	
28	✓				✓				–		✓					✓	
29																	
30																	
31																	

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CLARIFIER

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

Day	Sludge blanket depth					Sludge collection arm turning					Any floating material on top of clarifier?				Sludge recirculation system?					Scum recirculation system?				
	Good	Fair	Poor	Needs Maintenance		Good	Fair	Poor	Needs Maintenance		Yes	No	Needs Maintenance		Good	Fair	Poor	Needs Maintenance		Good	Fair	Poor	Needs Maintenance	
1			✓								✓				✓					✓				
2																								
3			✓								✓			✓						✓				
4																								
5																								
6			✓								✓				✓					✓				
7																								
8	✓										✓				✓					✓				
9	✓										✓				✓					✓				
10	✓										✓				✓					✓				
11	✓										✓				✓					✓				
12																								
13																								
14																								
15	✓										✓				✓					✓				
16	✓										✓				✓					✓				
17	✓										✓				✓					✓				
18																								
19	✓										✓				✓					✓				
20																								
21																								
22	✓										✓				✓					✓				
23																								
24	✓										✓				✓					✓				
25																								
26	✓										✓				✓					✓				
27																								
28	✓										✓				✓					✓				
29																								
30																								
31																								

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CONTROL SYSTEM

Utility: _____ Inspected by: _____

Month: _____ Year: _____

	Timers?				Electrical controls?				Control housing?				Unprotected electrical connections?			
Day	Good	Fair	Poor	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Number	Maintenance Needs
1	✓					✓				✓				✓		
2																
3																
4																
5																
6																
7																
8	✓					✓				✓				✓		
9																
10																
11	✓					✓				✓				✓		
12																
13																
14																
15	✓					✓				✓				✓		
16																
17																
18																
19	✓					✓				✓				✓		
20																
21																
22	✓					✓				✓				✓		
23																
24																
25																
26																
27																
28																
29																
30																
31																

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CHLORINE CONTACT TANK

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

	Any floating material?			Any sludge?			Baffles placement to insure proper chlorine contact time			
Day	Yes	No	Needs Maintenance	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs Maintenance
1	✓			✓			✓			
2										
3										
4										
5										
6										
7										
8	✓	✓			✓		✓			
9										
10										
11		✓			✓		✓			
12										
13										
14										
15		✓			✓		✓			
16										
17										
18	✓				✓		✓			
19										
20										
21										
22	✓				✓		✓			
23										
24										
25										
26										
27										
28										
29										
30										
31										

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

AERATION BASIN

Utility: Manchester STP Inspected by: Rodgers

Month: OCT. Year: 2016

Day	Even air distribution (any dead spots?)			Diffusers?				Air leaks around base and fittings of blower?			Blower belts wear and tension?				Unusual noises or vibration?		
	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs Maintenance	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs Maintenance	Yes	No	Needs Maintenance
1																	
2	✓			✓					✓		✓					✓	
3																	
4	✓			✓					✓		✓					✓	
5	✓			✓					✓		✓					✓	
6	✓			✓					✓		✓					✓	
7																	
8	✓			✓					✓		✓					✓	
9	✓			✓					✓							—	
10																	
11	✓			✓					✓		✓					✓	
12	✓			✓					✓		✓					✓	
13	✓			✓					✓		✓					✓	
14	✓			✓					✓		✓					✓	
15																	
16	—			—					—		—					✓	
17																	
18	✓			✓					✓		✓					✓	
19	✓			✓					✓		✓					✓	
20	✓			✓					✓		✓					✓	
21	✓			✓					✓		✓					✓	
22																	
23	✓			✓					✓		✓					✓	
24																	
25	✓			✓					✓		✓					✓	
26	—			—					—		—					—	
27	—			—					—		—					—	
28	✓			✓					✓		✓					✓	
29	✓			✓					✓		✓					✓	
30	✓			✓					—		✓					—	
31	—			—					—		—					—	

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CLARIFIER

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

Day	Sludge blanket depth				Sludge collection arm turning				Any floating material on top of clarifier?			Sludge recirculation system?				Scum recirculation system?			
	Good	Fair	Poor	Needs Maintenance	Good	Fair	Poor	Needs Maintenance	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs Maintenance	Good	Fair	Poor	Needs Maintenance
1									✓			✓				✓			
2	✓																		
3																			
4	✓								✓			✓				✓			
5	✓								✓			✓				✓			
6	✓								✓			✓				✓			
7																			
8	✓								✓			✓				✓			
9	✓								✓			✓				✓			
10																			
11	✓								✓			✓				✓			
12	✓								✓			✓				✓			
13	✓								✓			✓				✓			
14	✓								✓			✓							
15																			
16	✓								✓			✓				✓			
17																			
18		✓							✓			✓				✓			
19		✓							✓			✓				✓			
20		✓														✓			
21		✓							✓			✓				✓			
22																			
23		✓							✓			✓				✓			
24																			
25		✓							✓			✓				✓			
26		✓							✓			✓				✓			
27		✓							✓			✓				✓			
28																			
29		✓							✓			✓				✓			
30		✓							✓										
31		✓							✓			✓				✓			

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CONTROL SYSTEM

Utility:_____ **Inspected by:**_____

Month:_____ **Year:** _____

	Timers?				Electrical controls?				Control housing?				Unprotected electrical connections?			
Day	Good	Fair	Poor	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Number	Maintenance Needs
1																
2	✓				✓				✓					✓		
3																
4	✓				✓				✓					✓		
5																
6																
7																
8	✓				✓				✓					✓		
9																
10																
11	✓				✓				✓					✓		
12																
13																
14	✓				✓				✓					✓		
15																
16																
17																
18	✓				✓				✓					✓		
19																
20																
21	✓				✓				✓					✓		
22																
23																
24																
25																
26																
27																
28	✓				✓				✓					✓		
29																
30																
31																

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CHLORINE CONTACT TANK

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

Day	Any floating material?			Any sludge?			Baffles placement to insure proper chlorine contact time			
	Yes	No	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs
1										
2	√				√		√			
3										
4		√			√		√			
5										
6										
7										
8	√	√			√		√			
9										
10										
11		√			√		√			
12										
13										
14		√			√		√			
15										
16										
17										
18	√			√			√			
19										
20										
21	√			√			√			
22										
23										
24										
25	√			√			√			
26										
27										
28										
29	√			√			√			
30										
31										

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments: Plot has filtration, chlorination, Chlorine Tank

CONTROL SYSTEM

Utility: Meadowbrook S.D.

Month: Sept

Inspected by:

Year: 2010

Day	Timers?				Electrical controls?				Control housing?				Unprotected electrical connections?			
	Good	Fair	Poor	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Number	Maintenance Needs
1	✓				✓					✓				✓		
2	✓				✓					✓				✓		
3					✓					✓				✓		
4	✓													✓		
5					✓									✓		
6										✓						
7	✓													✓		
8	✓			✓												
9	✓			✓						✓						
10				✓						✓				✓		
11	✓									✓				✓		
12				✓										✓		
13	✓									✓						
14	✓			✓										✓		
15	✓			✓						✓						
16	✓			✓						✓				✓		
17	✓			✓						✓				✓		
18										✓				✓		
19	✓			✓										✓		
20	✓									✓						
21	✓			✓										✓		
22	✓			✓						✓						
23	✓			✓						✓				✓		
24				✓						✓				✓		
25										✓				✓		
26														✓		
27																
28	✓															
29				✓												
30	✓			✓				✓				✓				
31				✓				✓				✓				

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments: Pump and Haul Sludge

9-29-10

Utility: _____

AERATION BASIN

Inspected by: _____

Month: _____

Year: _____

Day	Even air distribution (any dead spots?)			Diffusers?				Air leaks around base and fittings of blower?			Blower belts wear and tension?				Unusual noises or vibration?			
	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs Maintenance	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs Maintenance	Yes	No	Needs Maintenance	
1	✓				✓				✓		✓					✓		
2	✓				✓											✓		
3					✓				✓		✓					✓		
4	✓				✓				✓							✓		
5									✓		✓					✓		
6																✓		
7	✓				✓				✓		✓							
8	✓				✓				✓		✓					✓		
9	✓				✓				✓		✓					✓		
10					✓				✓		✓					✓		
11	✓								✓		✓					✓		
12					✓				✓							✓		
13									✓		✓					✓		
14	✓				✓				✓		✓							
15	✓				✓				✓		✓					✓		
16	✓				✓				✓		✓					✓		
17	✓				✓				✓		✓					✓		
18									✓		✓					✓		
19	✓				✓				✓		✓					✓		
20	✓								✓		✓					✓		
21	✓				✓				✓		✓							
22	✓				✓				✓		✓					✓		
23	✓				✓				✓		✓					✓		
24					✓				✓		✓					✓		
25									✓		✓					✓		
26																		
27																		
28	✓																	
29	✓				✓													
30	✓				✓				✓		✓					✓		
31					✓				✓		✓					✓		

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CLARIFIER

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

Day	Sludge blanket depth					Sludge collection arm turning					Any floating material on top of clarifier?			Sludge recirculation system?					Scum recirculation system?				
	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Yes	No	Needs	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance
1																							
2		✓																					
3											✓			✓									
4																			✓				
5																							
6																							
7		✓																					
8											✓			✓									
9		✓																	✓				
10											✓			✓									
11														✓					✓				
12																							
13		✓																					
14											✓												
15														✓					✓				
16		✓																					
17											✓												
18														✓					✓				
19																							
20		✓																					
21											✓												
22														✓					✓				
23	✓																						
24											✓												
25														✓					✓				
26																							
27																							
28																							
29																							
30	✓	✓																					
31									✓					✓					✓				

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CHLORINE CONTACT TANK

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

Day	Any floating material?			Any sludge?			Baffles placement to insure proper chlorine contact time			
	Yes	No	Needs Maintenance	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs Maintenance
1										
2		✓								
3					✓		✓			
4										
5										
6										
7		✓								
8					✓		✓			
9		✓								
10					✓		✓			
11										
12										
13										
14		✓								
15					✓		✓			
16										
17		✓								
18					✓		✓			
19										
20										
21		✓								
22					✓		✓			
23										
24		✓			✓					
25							✓			
26										
27										
28										
29										
30										
31		✓			✓		✓			

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, e that support maintenance action taken.)

Additional Comments:

CONTROL SYSTEM

Utility: Marlborough Sub'n Inspected by: [illegible]

Month: August Year: 2010

Day	Timers?					Electrical controls?					Control housing?					Unprotected electrical connections?				
	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Yes	No	Number	Needs	Maintenance
1																				
2	✓					✓						✓					✓			
3	✓					✓						✓					✓			
4	✓					✓						✓					✓			
5	✓					✓						✓					✓			
6																				
7	✓					✓						✓					✓			
8																				
9	✓					✓						✓					✓			
10	✓					✓						✓					✓			
11	✓					✓						✓					✓			
12	✓					✓						✓					✓			
13	✓					✓						✓					✓			
14																				
15																				
16	✓					✓						✓					✓			
17	✓					✓						✓					✓			
18	✓					✓						✓					✓			
19	✓					✓						✓					✓			
20																				
21	✓					✓						✓					✓			
22																				
23	✓					✓						✓					✓			
24	✓					✓						✓					✓			
25	✓					✓						✓					✓			
26	✓					✓						✓					✓			
27																				
28	✓					✓						✓					✓			
29																				
30	✓					✓						✓					✓			
31	✓					✓						✓					✓			

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

AERATION BASIN

Inspected by: A J

Year: 2110

Day	Even air distribution (any dead spots?)			Diffusers?				Air leaks around base and fittings of blower?			Blower belts wear and tension?				Unusual noises or vibration?		
	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs Maintenance	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs Maintenance	Yes	No	Needs Maintenance
1																	
2	✓				✓				✓		✓					✓	
3																	
4	✓				✓				✓		✓					✓	
5	✓				✓				✓		✓					✓	
6									✓		✓					✓	
7	✓				✓												
8									✓		✓					✓	
9	✓				✓												
10	✓				✓				✓		✓					✓	
11	✓				✓				✓		✓					✓	
12	✓				✓				✓		✓					✓	
13	✓				✓				✓		✓					✓	
14					✓												
15									✓		✓					✓	
16	✓				✓												
17	✓				✓				✓		✓					✓	
18	✓				✓				✓		✓					✓	
19	✓				✓				✓		✓					✓	
20					✓												
21	✓				✓				✓		✓					✓	
22					✓				✓		✓					✓	
23	✓				✓												
24	✓				✓				✓		✓					✓	
25	✓				✓				✓		✓					✓	
26	✓				✓				✓		✓					✓	
27					✓												
28	✓				✓				✓		✓					✓	
29																	
30	✓				✓				✓		✓					✓	
31	✓				✓				✓		✓					✓	

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CLARIFIER

ity: _____ Inspected by: _____

ıonth: _____ Year: _____

Day	Sludge blanket depth					Sludge collection arm turning					Any floating material on top of clarifier?				Sludge recirculation system?					Scum recirculation system?				
	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Yes	No	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance
1																								
2	✓																							
3											✓				✓									
4																				✓				
5	✓																							
6											✓				✓									
7																				✓				
8																								
9	✓																							
10											✓				✓									
11																				✓				
12																								
13	✓																							
14											✓				✓									
15																				✓				
16	✓																							
17											✓				✓									
18																				✓				
19	✓																							
20											✓				✓									
21																				✓				
22																								
23	✓																							
24											✓				✓									
25																				✓				
26	✓																							
27											✓				✓									
28																				✓				
29																								
30	✓																							
31											✓				✓					✓				

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CHLORINE CONTACT TANK

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

	Any floating material?			Any sludge?			Baffles placement to insure proper chlorine contact time			
Day	Yes	No	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs
1										
2		✓			✓		✓			
3										
4										
5		✓			✓		✓			
6										
7										
8										
9		✓			✓		✓			
10										
11										
12										
13		✓			✓		✓			
14										
15										
16		✓			✓		✓			
17										
18										
19		✓			✓		✓			
20										
21										
22										
23		✓			✓		✓			
24										
25										
26		✓			✓		✓			
27										
28										
29										
30		✓			✓		✓			
31										

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CONTROL SYSTEM

Utility: Meadowbrook S.D.A. Inspected by: Participant

Month: July 2016 Year: 2016

Day	Timers?					Electrical controls?					Control housing?					Unprotected electrical connections?				
	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Yes	No	Number	Needs	Maintenance
1																				
2	✓					✓	✓					✓					✓			
3	✓						✓					✓					✓			
4																				
5																				
6	✓						✓					✓								
7	✓						✓					✓					✓			
8	✓						✓					✓					✓			
9																				
10	✓						✓					✓					✓			
11																				
12	✓						✓					✓					✓			
13	✓						✓					✓					✓			
14	✓						✓					✓					✓			
15	✓						✓					✓					✓			
16	✓						✓					✓					✓			
17	✓						✓					✓					✓			
18																				
19	✓						✓					✓					✓			
20	✓						✓					✓					✓			
21	✓						✓					✓					✓			
22	✓						✓					✓					✓			
23	✓						✓					✓					✓			
24	✓						✓					✓					✓			
25																				
26	✓						✓					✓					✓			
27	✓						✓					✓					✓			
28	✓						✓					✓					✓			
29	✓						✓					✓					✓			
30																				
31	✓						✓					✓					✓			

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

8-2-16

AERATION BASIN

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

Day	Even air distribution (any dead spots?)			Diffusers?				Air leaks around base and fittings of blower?			Blower belts wear and tension?				Unusual noises or vibration?		
	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs Maintenance	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs Maintenance	Yes	No	Needs Maintenance
1																	
2	√				√				√		√					√	
3	√				√				√		√					√	
4																	
5																	
6	√				√				√		√					√	
7	√				√				√		√					√	
8	√				√				√		√					√	
9																	
10	√				√				√		√					√	
11																	
12	√				√				√		/					√	
13	√				√				√		√					√	
14	√				√				√		√					√	
15	√				√				√		√					√	
16	√				√				√		√					√	
17	√				√				√		√					√	
18																	
19	√				√				√		√					√	
20	√				√				√		√					√	
21	√				√				√		√					√	
22	√				√				√		√					√	
23	√				√				√		√					√	
24	√				√				√		√					√	
25																	
26	√				√				√		√					√	
27	√				√				√		√					√	
28	√				√				√		√					√	
29	√				√				√		√					√	
30																	
31	√				√				√		√					√	

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

8-2-16

CLARIFIER

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

	Sludge blanket depth					Sludge collection arm turning					Any floating material on top of clarifier?			Sludge recirculation system?					Scum recirculation system?				
Day	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance
1																							
2	✓											✓		✓					✓				
3																							
4																							
5																							
6	✓											✓		✓					✓				
7																							
8																							
9																							
10																							
11																							
12	✓											✓		✓					✓				
13																							
14																							
15																							
16																							
17																							
18																							
19																							
20																							
21																							
22																							
23																							
24																							
25																							
26																							
27																							
28																							
29																							
30																							
31																							

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CHLORINE CONTACT TANK

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

	Any floating material?			Any sludge?			Baffles placement to insure proper chlorine contact time			
Day	Yes	No	Needs Maintenance	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs Maintenance
1										
2		✓			✓		✓			
3										
4										
5										
6		✓			✓		✓			
7										
8										
9										
10										
11										
12		✓			✓		✓			
13										
14										
15										
16										
17										
18										
19										
20										
21										
22										
23										
24										
25										
26										
27										
28										
29										
30										
31										

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CONTROL SYSTEM

Utility: Meadowbrook S-h-N Inspected by: _____

Month: June Year: 2018

Day	Timers?					Electrical controls?					Control housing?					Unprotected electrical connections?				
	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Yes	No	Number	Needs	Maintenance
1	✓						✓					✓					✓			
2	✓						✓					✓					✓			
3	✓						✓					✓					✓			
4	✓						✓										✓			
5																				
6																				
7	✓						✓					✓					✓			
8	✓						✓					✓					✓			
9	✓						✓					✓					✓			
10	✓						✓					✓					✓			
11	✓						✓					✓					✓			
12																				
13																				
14																				
15	✓							✓				✓					✓			
16	✓							✓				✓					✓			
17	✓							✓				✓					✓			
18	✓																			
19								✓				✓					✓			
20																				
21	✓							✓				✓					✓			
22	✓							✓				✓					✓			
23																				
24	✓							✓				✓					✓			
25	✓							✓				✓					✓			
26	✓							✓				✓					✓			
27																				
28	✓							✓				✓					✓			
29	✓							✓				✓					✓			
30	✓							✓				✓					✓			
31																				

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

AERATION BASIN

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

Day	Even air distribution (any dead spots?)			Diffusers?				Air leaks around base and fittings of blower?			Blower belts wear and tension?				Unusual noises or vibration?		
	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Maintenance Needs
1	✓			✓					✓		✓					✓	
2	✓			✓					✓		✓					✓	
3	✓			✓					✓		✓					✓	
4	✓			✓					✓		✓					✓	
5																	
6																	
7	✓			✓					✓		✓					✓	
8	✓			✓					✓		✓					✓	
9	✓			✓					✓		✓					✓	
10	✓			✓					✓		✓					✓	
11	✓			✓					✓		✓					✓	
12																	
13																	
14																	
15	✓			✓					✓		✓					✓	
16	✓			✓					✓		✓					✓	
17	✓			✓					✓		✓					✓	
18	✓			✓					✓		✓					✓	
19																	
20																	
21	✓			✓					✓		✓					✓	
22	✓			✓					✓		✓					✓	
23																	
24	✓			✓					✓		✓					✓	
25	✓			✓					✓		✓					✓	
26	✓			✓					✓		✓					✓	
27																	
28	✓			✓					✓		✓					✓	
29	✓			✓					✓		✓					✓	
30	✓			✓					✓		✓					✓	
31																	

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CLARIFIER

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

	Sludge blanket depth					Sludge collection arm turning					Any floating material on top of clarifier?				Sludge recirculation system?					Scum recirculation system?				
Day	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Yes	No	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance
1	✓										✓				✓					✓				
2																								
3																								
4	✓										✓				✓					✓				
5																								
6																								
7	✓										✓				✓					✓				
8																								
9																								
10																								
11	✓										✓				✓					✓				
12																								
13																								
14																								
15																								
16																								
17																								
18	✓										✓				✓					✓				
19																								
20																								
21																								
22	✓										✓				✓					✓				
23																								
24																								
25	✓										✓				✓					✓				
26																								
27																								
28	✓										✓				✓					✓				
29																								
30																								
31																								

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

	Any floating material?			Any sludge?			Baffles placement to insure proper chlorine contact time			
Day	Yes	No	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs
1		✓			✓		✓			
2										
3										
4		✓			✓		✓			
5										
6										
7		✓			✓		✓			
8										
9										
10										
11		✓			✓		✓			
12										
13										
14										
15										
16										
17										
18		✓			✓		✓			
19										
20										
21										
22		✓			✓		✓			
23										
24										
25										
26										
27										
28		✓			✓		✓			
29										
30										
31										

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CONTROL SYSTEM

Utility: [illegible]

Inspected by: _____

Month: May

Year: _____

	Timers?				Electrical controls?				Control housing?				Unprotected electrical connections?			
Day	Good	Fair	Poor	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Number	Maintenance Needs
1																
2						✓				✓				✓		
3	✓					✓				✓				✓		
4	✓					✓				✓				✓		
5	✓					✓				✓				✓		
6	✓					✓				✓				✓		
7	✓					✓				✓						
8	✓									✓				✓		
9						✓				✓				✓		
10	✓					✓				✓				✓		
11	✓					✓										
12	✓															
13										✓				✓		
14						✓										
15	✓									✓				✓		
16						✓										
17	✓									✓				✓		
18						✓				✓				✓		
19	✓					✓				✓				✓		
20	✓					✓				✓				✓		
21	✓					✓										
22	✓															
23						✓				✓				✓		
24	✓					✓				✓				✓		
25	✓					✓										
26	✓									✓				✓		
27						✓				✓						
28	✓					✓										
29	✓															
30						✓				✓				✓		
31	✓															

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

AERATION BASIN

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

Day	Even air distribution (any dead spots?)			Diffusers?				Air leaks around base and fittings of blower?			Blower belts wear and tension?				Unusual noises or vibration?		
	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Maintenance Needs
1																	
2																	
3	✓			✓					✓		✓					✓	
4	✓			✓					✓		✓					✓	
5	✓			✓					✓		✓					✓	
6	✓			✓					✓		✓					✓	
7	✓			✓					✓		✓					✓	
8	✓			✓					✓		✓					✓	
9																	
10	✓			✓					✓		✓					✓	
11	✓			✓					✓		✓					✓	
12	✓			✓					✓		✓					✓	
13																	
14																	
15	✓			✓					✓		✓					✓	
16																	
17	✓			✓					✓		✓					✓	
18																	
19	✓			✓					✓		✓					✓	
20	✓			✓					✓		✓					✓	
21	✓			✓					✓		✓					✓	
22	✓			✓					✓		✓					✓	
23																	
24	✓			✓					✓		✓					✓	
25	✓			✓					✓		✓					✓	
26	✓			✓					✓		✓					✓	
27																	
28	✓			✓					✓		✓					✓	
29	✓			✓					✓		✓					✓	
30																	
31	✓			✓					✓		✓					✓	

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CLARIFIER

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

	Sludge blanket depth					Sludge collection arm turning					Any floating material on top of clarifier?				Sludge recirculation system?					Scum recirculation system?				
Day	Good	Fair	Poor	Needs Maintenance		Good	Fair	Poor	Needs Maintenance		Yes	No	Needs Maintenance		Good	Fair	Poor	Needs Maintenance		Good	Fair	Poor	Needs Maintenance	
1																								
2																								
3	✓											✓			✓					✓				
4																								
5																								
6	✓											✓			✓					✓				
7																								
8																								
9																								
10	✓										✓				✓					✓				
11																								
12																								
13																								
14																								
15																								
16																								
17	✓										✓				✓					✓				
18																								
19																								
20																								
21	✓											✓			✓					✓				
22																								
23																								
24	✓										✓	✓			✓					✓				
25																								
26																								
27																								
28	✓										✓				✓					✓				
29																								
30																								
31																								

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CHLORINE CONTACT TANK

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

	Any floating material?			Any sludge?			Baffles placement to insure proper chlorine contact time			
Day	Yes	No	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs
1										
2										
3		✓			✓		✓			
4										
5										
6		✓			✓		✓			
7										
8										
9										
10		✓			✓		✓			
11										
12										
13										
14										
15										
16										
17		✓			✓		✓			
18										
19										
20										
21		✓			✓		✓			
22										
23										
24		✓			✓		✓			
25										
26										
27										
28		✓			✓		✓			
29										
30										
31										

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CONTROL SYSTEM

Utility: _____ Inspected by: _____

Month: _____ Year: _____

	Timers?				Electrical controls?				Control housing?				Unprotected electrical connections?			
Day	Good	Fair	Poor	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Number	Maintenance Needs
1																
2																
3																
4																
5																
6																
7																
8																
9																
10																
11																
12																
13																
14																
15																
16																
17																
18																
19																
20																
21																
22																
23																
24																
25																
26																
27																
28																
29																
30																
31																

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

AERATION BASIN

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

Day	Even air distribution (any dead spots?)				Diffusers?				Air leaks around base and fittings of blower?			Blower belts wear and tension?				Unusual noises or vibration?			
	Yes	No	Needs	Maintenance	Good	Fair	Poor	Needs Maintenance	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs Maintenance	Yes	No	Needs	Maintenance
1	✓				✓					✓		✓					✓		
2																			
3	✓				✓					✓		✓					✓		
4																			
5	✓				✓					✓		✓					✓		
6	✓				✓					✓		✓					✓		
7	✓				✓					✓		✓					✓		
8	✓				✓					✓		✓					✓		
9																			
10	✓				✓					✓		✓					✓		
11																			
12	✓				✓					✓		✓					✓		
13	✓				✓					✓		✓					✓		
14	✓				✓					✓		✓					✓		
15	✓				✓					✓		✓					✓		
16	✓				✓					✓		✓					✓		
17	✓				✓					✓		✓					✓		
18																			
19	✓				✓					✓		✓					✓		
20																			
21	✓																		
22	✓				✓					✓		✓					✓		
23																			
24	✓				✓					✓		✓					✓		
25																			
26	✓				✓					✓		✓					✓		
27																			
28	✓				✓					✓		✓					✓		
29	✓				✓					✓		✓					✓		
30	✓				✓					✓		✓					✓		
31																			

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CLARIFIER

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

Day	Sludge blanket depth					Sludge collection arm turning					Any floating material on top of clarifier?				Sludge recirculation system?					Scum recirculation system?				
	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Yes	No	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance
1	✓										✓				✓					✓				
2																								
3																								
4																								
5	✓										✓				✓					✓				
6																								
7																								
8	✓										✓				✓					✓				
9																								
10																								
11																								
12	✓										✓				✓					✓				
13																								
14																								
15																								
16	✓										✓				✓					✓				
17																								
18																								
19																								
20																								
21																								
22	✓										✓				✓					✓				
23																								
24																								
25																								
26	✓										✓				✓					✓				
27																								
28	✓										✓				✓					✓				
29																								
30																								
31																								

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CHLORINE CONTACT TANK

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

	Any floating material?			Any sludge?			Baffles placement to insure proper chlorine contact time			
Day	Yes	No	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs
1		√			√		√			
2										
3										
4										
5		√			√		√			
6										
7										
8		√			√		√			
9										
10										
11										
12		√			√		√			
13										
14										
15										
16		√			√		√			
17										
18										
19										
20										
21										
22		√			√					
23										
24										
25										
26		√			√		√			
27										
28		√			√		√			
29										
30										
31										

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CONTROL SYSTEM

Utility: Mendenhall Inspected by: _____

Month: March Year: 2016

Day	Timers?				Electrical controls?				Control housing?				Unprotected electrical connections?			
	Good	Fair	Poor	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Number	Maintenance Needs
1	✓				✓					✓				✓		
2	✓				✓					✓				✓		
3	✓				✓					✓				✓		
4	✓				✓					✓				✓		
5																
6	✓				✓					✓				✓		
7																
8	✓				✓					✓				✓		
9	✓				✓					✓				✓		
10																
11	✓				✓					✓				✓		
12	✓				✓					✓				✓		
13																
14	✓				✓					✓				✓		
15																
16	✓				✓					✓				✓		
17																
18	✓				✓					✓				✓		
19	✓				✓					✓				✓		
20	✓				✓					✓				✓		
21																
22	✓				✓					✓				✓		
23	✓				✓					✓				✓		
24	✓				✓					✓				✓		
25	✓				✓					✓						
26																
27	✓				✓					✓				✓		
28																
29	✓				✓					✓				✓		
30	✓				✓					✓				✓		
31	✓				✓					✓				✓		

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

3-22-16 - Pumped out Chl Chlor Tank, Pumped 500 gals of Sludge from Plant.

AERATION BASIN

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

Day	Even air distribution (any dead spots?)			Diffusers?				Air leaks around base and fittings of blower?			Blower belts wear and tension?				Unusual noises or vibration?		
	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Maintenance Needs
1	✓			✓					✓		✓					✓	
2	✓			✓					✓		✓					✓	
3	✓			✓					✓		✓					✓	
4	✓			✓					✓		✓					✓	
5																	
6	✓			✓					✓		✓					✓	
7																	
8	✓			✓					✓		✓					✓	
9	✓			✓					✓		✓					✓	
10																	
11	✓			✓					✓		✓					✓	
12	✓			✓					✓		✓					✓	
13																	
14	✓			✓					✓		✓					✓	
15																	
16	✓			✓					✓		✓					✓	
17																	
18	✓			✓					✓		✓					✓	
19	✓			✓					✓		✓					✓	
20	✓			✓					✓		✓					✓	
21																	
22	✓			✓					✓		✓					✓	
23	✓			✓					✓		✓					✓	
24	✓			✓					✓		✓					✓	
25	✓			✓					✓		✓					✓	
26																	
27	✓			✓					✓		✓					✓	
28																	
29	✓			✓					✓		✓					✓	
30	✓			✓					✓		✓					✓	
31	✓			✓					✓		✓					✓	

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CLARIFIER

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

	Sludge blanket depth					Sludge collection arm turning					Any floating material on top of clarifier?			Sludge recirculation system?					Scum recirculation system?				
Day	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance
1	✓										✓			✓					✓				
2																							
3																							
4	✓										✓			✓					✓				
5																							
6																							
7																							
8																							
9																							
10																							
11																							
12																							
13																							
14																							
15																							
16	✓										✓			✓					✓				
17																							
18																							
19	✓										✓			✓					✓				
20																							
21																							
22		✓									✓			✓					✓				
23																							
24																							
25	✓										✓			✓					✓				
26																							
27																							
28																							
29																							
30	✓										✓			✓					✓				
31																							

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CHLORINE CONTACT TANK

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

	Any floating material?			Any sludge?			Baffles placement to insure proper chlorine contact time			
Day	Yes	No	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs
1		✓			✓		✓			
2										
3										
4		✓			✓		✓			
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
16		✓			✓		✓			
17										
18										
19		✓			✓		✓			
20										
21										
22		✓			✓		✓			
23										
24										
25		✓			✓		✓			
26										
27										✓
28										
29										
30		✓			✓		✓			
31										

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CONTROL SYSTEM

Utility: [illegible] Inspected by: _____

Month: Feb. Year: 2010

	Timers?					Electrical controls?					Control housing?					Unprotected electrical connections?				
Day	Good	Fair	Poor	Needs Maintenance		Good	Fair	Poor	Needs Maintenance		Good	Fair	Poor	Needs Maintenance		Yes	No	Number	Needs Maintenance	
1		✓					✓					✓					✓			
2		✓					✓					✓					✓			
3		✓					✓					✓					✓			
4		✓					✓					✓					✓			
5																				
6		✓					✓					✓					✓			
7																				
8		✓					✓					✓					✓			
9		✓					✓					✓					✓			
10		✓					✓					✓					✓			
11		✓					✓					✓					✓			
12		✓					✓					✓					✓			
13																				
14																				
15																				
16		✓					✓					✓					✓			
17		✓					✓					✓					✓			
18		✓					✓					✓					✓			
19																				
20		✓					✓					✓								
21		✗																		
22		✓					✓					✓								
23		✓					✓					✓					✓			
24		✓					✓					✓					✓			
25		✓					✓					✓					✓			
26																				
27		✓					✓					✓					✓			
28																				
29																				
30																				
31																				

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

AERATION BASIN

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

	Even air distribution (any dead spots?)			Diffusers?				Air leaks around base and fittings of blower?			Blower belts wear and tension?				Unusual noises or vibration?		
Day	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Maintenance Needs
1	✓				✓				✓		✓					✓	
2	✓				✓				✓		✓					✓	
3	✓				✓				✓		✓					✓	
4	✓				✓				✓		✓					✓	
5																	
6	✓				✓				✓		✓					✓	
7																	
8																	
9	✓				✓				✓		✓					✓	
10	✓				✓				✓		✓					✓	
11	✓				✓				✓		✓					✓	
12	✓				✓				✓		✓					✓	
13																	
14	✓				✓				✓		✓					✓	
15																	
16																	
17	✓				✓				✓		✓					✓	
18	✓				✓				✓		✓					✓	
19																	
20	✓				✓				✓		✓					✓	
21																	
22	✓				✓				✓		✓					✓	
23	✓				✓				✓		✓					✓	
24	✓				✓				✓		✓					✓	
25																	
26																	
27	✓				✓				✓		✓					✓	
28																	
29																	
30																	
31																	

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CLARIFIER

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

	Sludge blanket depth					Sludge collection arm turning					Any floating material on top of clarifier?			Sludge recirculation system?					Scum recirculation system?				
Day	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance
1	✓											✓		✓					✓				
2																							
3																							
4	✓											✓		✓					✓				
5																							
6																							
7																							
8	✓											✓		✓					✓				
9																							
10																							
11	✓											✓		✓					✓				
12	✓											✓		✓					✓				
13																							
14	✓											✓		✓					✓				
15																							
16																							
17																							
18	✓											✓		✓					✓				
19																							
20																							
21																							
22	✓											✓		✓					✓				
23																							
24																							
25																							
26																							
27																							
28																							
29																							
30																							
31																							

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CHLORINE CONTACT TANK

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

	Any floating material?			Any sludge?			Baffles placement to insure proper chlorine contact time			
Day	Yes	No	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs
1		✓			✓		✓			
2										
3										
4		✓			✓		✓			
5										
6										
7										
8		✓			✓		✓			
9										
10										
11		✓			✓		✓			
12										
13										
14										
15										
16										
17										
18		✓			✓		✓			
19										
20										
21										
22		✓			✓		✓			
23										
24										
25										
26										
27										
28										
29										
30										
31										

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CONTROL SYSTEM

Utility: Municipal S.A.

Inspected by:

Month: Jan.

Year: 2010

Day	Timers?					Electrical controls?					Control housing?					Unprotected electrical connections?				
	Good	Fair	Poor	Needs Maintenance		Good	Fair	Poor	Needs Maintenance		Good	Fair	Poor	Needs Maintenance		Yes	No	Number	Needs Maintenance	
1																				
2																				
3																				
4	✓						✓				✓	✓					✓			
5	✓						✓				✓	✓					✓			
6							✓				✓	✓					✓			
7																				
8																				
9	✓						✓				✓						✓			
10	✓						✓				✓						✓			
11																				
12	✓						✓				✓						✓			
13	✓						✓				✓						✓			
14	✓						✓				✓						✓			
15	✓						✓				✓						✓			
16	✓						✓				✓						✓			
17							✓				✓						✓			
18	✓						✓				✓						✓			
19	✓						✓				✓						✓			
20	✓						✓				✓						✓			
21											✓						✓			
22																				
23	✓																			
24							✓				✓						✓			
25	✓																			
26	✓						✓				✓						✓			
27	✓						✓				✓						✓			
28	✓						✓				✓						✓			
29							✓				✓						✓			
30																				
31							✓													

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

AERATION BASIN

Utility: Muskegon Inspected by:

Month: Jan Year: 2016

Day	Even air distribution (any dead spots?)			Diffusers?				Air leaks around base and fittings of blower?			Blower belts wear and tension?				Unusual noises or vibration?		
	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Maintenance Needs
1																	
2																	
3																	
4	✓			✓					✓		✓					✓	
5	″			″					″		—					″	
6																	
7																	
8	✓			✓					✓		✓					✓	
9	″			″					″		″					″	
10																	
11	✓			✓					✓		✓					✓	
12	″			″					″		″					″	
13	″			″					″		″					″	
14	✓			✓					✓		✓					✓	
15																	
16	″			″					″		″					″	
17																	
18																	
19	″	~~✓~~		—					″		″					″	
20	✓			″					″		″					″	
21																	
22																	
23	″			″					—		″					—	
24																	
25	″			″					″		—					″	
26	″			″					″		″					″	
27	″			—					″		″					—	
28	″			✓					✓		✓					✓	
29																	
30	″			—					—		″					—	
31																	

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CLARIFIER

Utility: _____ Inspected by: _____

Month: _____ Year: _____

	Sludge blanket depth					Sludge collection arm turning					Any floating material on top of clarifier?				Sludge recirculation system?					Scum recirculation system?				
Day	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Yes	No	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance
1																								
2																								
3																								
4	✓										✓				✓					✓				
5																								
6																								
7																								
8	✓										✓				✓					✓				
9																								
10																								
11	✓										✓				✓					✓				
12																								
13																								
14	✓										✓				✓					✓				
15																								
16																								
17																								
18																								
19																								
20																								
21	✓										✓				✓					✓				
22																								
23																								
24																								
25																								
26	✓											✓			✓					✓				
27																								
28	✓											✓			✓					✓				
29																								
30																								
31																								

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CHLORINE CONTACT TANK

Utility: _____ Inspected by: _____

Month: _____ Year: _____

	Any floating material?			Any sludge?			Baffles placement to insure proper chlorine contact time			
Day	Yes	No	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs
1										
2										
3										
4		✓			✓		✓			
5										
6										
7										
8		✓			✓		✓			
9										
10										
11		✓			✓		✓			
12										
13										
14		✓			✓		✓			
15										
16										
17										
18										
19										
20										
21		✓			✓		✓			
22										
23										
24										
25										
26		✓			✓		✓			
27										
28		✓			✓		✓			
29										
30										
31										

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CONTROL SYSTEM

Utility: Manchester Inspected by: _____

Month: Dec. Year: 2009

Day	Timers?					Electrical controls?					Control housing?					Unprotected electrical connections?				
	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Yes	No	Number	Needs	Maintenance
1	✓					✓					✓						✓			
2	✓					✓					✓						✓			
3	✓					✓					✓						✓			
4																				
5	✓					✓					✓						✓			
6																				
7	✓					✓					✓						✓			
8	✓					✓					✓						✓			
9	✓					✓					✓						✓			
10	✓					✓					✓						✓			
11																				
12	✓					✓					✓						✓			
13																				
14	✓					✓					✓						✓			
15	✓					✓					✓						✓			
16	✓					✓					✓						✓			
17	✓					✓					✓						✓			
18																				
19	✓					✓					✓						✓			
20																				
21	✓					✓					✓						✓			
22	✓					✓					✓						✓			
23	✓					✓					✓						✓			
24	✓					✓					✓						✓			
25	✓					✓											✓			
26																				
27	✓					✓					✓						✓			
28	✓					✓					✓						✓			
29	✓					✓					✓						✓			
30	✓					✓					✓						✓			
31	✓					✓					✓						✓			

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments: Manchester Sewer Line at 149 Main

AERATION BASIN

Utility: _____ Inspected by: _____

Month: _____ Year: _____

	Even air distribution (any dead spots?)			Diffusers?				Air leaks around base and fittings of blower?			Blower belts wear and tension?				Unusual noises or vibration?		
Day	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Maintenance Needs
1	✓			✓					✓		✓					✓	
2	✓			✓					✓		✓					✓	
3	✓			✓					✓		✓					✓	
4																	
5	✓			✓					✓		✓					✓	
6																	
7	✓			✓					✓		✓					✓	
8	✓			✓					✓		✓					✓	
9	✓			✓					✓		✓					✓	
10	✓			✓					✓		✓					✓	
11																	
12	✓			✓					✓		✓					✓	
13																	
14	✓			✓					✓		✓					✓	
15	✓			✓					✓		✓					✓	
16	✓			✓					✓		✓					✓	
17	✓			✓					✓		✓					✓	
18																	
19	✓			✓					✓		✓					✓	
20																	
21	✓			✓					✓		✓					✓	
22	✓			✓					✓		✓					✓	
23	✓			✓					✓		✓					✓	
24	✓			✓					✓		✓					✓	
25	✓			✓					✓		✓					✓	
26																	
27	✓			✓					✓		✓					✓	
28	✓			✓					✓		✓					✓	
29	✓			✓					✓		✓					✓	
30	✓			✓					✓		✓					✓	
31	✓			✓					✓		✓					✓	

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CLARIFIER

Utility: _____ Inspected by: _____

Month: _____ Year: _____

Day	Sludge blanket depth					Sludge collection arm turning					Any floating material on top of clarifier?			Sludge recirculation system?					Scum recirculation system?				
	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance
1																							
2																							
3	✓										✓			✓					✓				
4																							
5																							
6																							
7	✓										✓			✓					✓				
8																							
9																							
10	✓										✓			✓					✓				
11																							
12																							
13																							
14	✓										✓			✓					✓				
15																							
16																							
17	✓										✓			✓					✓				
18																							
19																							
20																							
21																							
22																							
23	✓										✓			✓					✓				
24																							
25																							
26																							
27																							
28																							
29																							
30	✓										✓			✓					✓				
31																							

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CHLORINE CONTACT TANK

Utility: _____ Inspected by: _____

Month: _____ Year: _____

Day	Any floating material?			Any sludge?			Baffles placement to insure proper chlorine contact time			
	Yes	No	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs
1										
2										
3		✓			✓		✓			
4										
5										
6										
7		✓		✓			✓			
8										
9										
10	✓				✓		✓			
11										
12										
13										
14	✓	✓		✓	✓		✓			
15										
16										
17		✓		✓			✓			
18										
19										
20										
21										
22										
23		✓			✓		✓			
24										
25										
26										
27										
28										
29										
30		✓			✓		✓			
31										

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments: 12. 21.09 Pumped 1-Load of Slug. From Chlor. Contact Tank to Pl...

CONTROL SYS

Utility: Meadowbrook Sub

Inspected by: _____

Year: 2009

Month: November

Day	Timers?				Electrical controls?				Control housing?				Unprotected electrical connections?			
	Good	Fair	Poor	Maintenance Needed	Good	Fair	Poor	Maintenance Needed	Good	Fair	Poor	Maintenance Needed	Yes	No	Number	Maintenance Needed
1					✓					✓				✓		
2	✓															
3																
4					✓											
5	✓									✓				✓		
6					✓											
7	✓									✓				✓		
8	✓				✓					✓				✓		
9					✓					✓				✓		
10	✓				✓					✓				✓		
11	✓				✓					✓				✓		
12	✓															
13										✓				✓		
14					✓					✓				✓		
15	✓				✓					✓				✓		
16	✓									✓				✓		
17	✓									✓				✓		
18	✓									✓				✓		
19	✓				✓											
20	✓									✓				✓		
21					✓					✓				✓		
22	✓				✓					✓				✓		
23	✓															
24	✓									✓				✓		
25					✓											
26	✓									✓						
27					✓											
28	✓									✓				✓		
29																
30	✓				✓											
31																

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

23.1 Upright Sample line in front of Plt

23.1 - Lost of Sky Pmpl + Wtk 20

AERATION BASIN

Utility: _____ Inspected by: _____

Month: _____ Year: _____

Day	Even air distribution (any dead spots?)				Diffusers?				Air leaks around base and fittings of blower?			Blower belts wear and tension?				Unusual noises or vibration?		
	Yes	No	Needs	Maintenance	Good	Fair	Poor	Needs Maintenance	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs Maintenance	Yes	No	Needs Maintenance
1																		
2																		
3																		
4																		
5																		
6																		
7																		
8																		
9																		
10																		
11																		
12																		
13																		
14																		
15																		
16																		
17																		
18																		
19																		
20																		
21																		
22																		
23																		
24																		
25																		
26																		
27																		
28																		
29																		
30																		
31																		

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CLARIFIER

Utility: _____ Inspected by: _____

Month. _____ Year: _____

	Sludge blanket depth				Sludge collection arm turning				Any floating material on top of clarifier?			Sludge recirculation system?				Scum recirculation system?			
Day	Good	Fair	Poor	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Good	Fair	Poor	Maintenance Needs
1																			
2	✓								✓			✓				✓			
3																			
4																			
5	✓								✓			✓				✓			
6																			
7																			
8																			
9	✓								✓			✓				✓			
10																			
11																			
12	✓								✓			✓				✓			
13																			
14																			
15																			
16	✓								✓			✓				✓			
17																			
18																			
19																			
20																			
21																			
22																			
23	✓								✓			✓				✓			
24																			
25																			
26																			
27																			
28																			
29																			
30		✓							✓			✓				✓			
31																			

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CHLORINE CONTACT TANK

Utility: _____ Inspected by: _____

Month: _____ Year: _____

	Any floating material?			Any sludge?			Baffles placement to insure proper chlorine contact time			
Day	Yes	No	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs
1										
2		✓			✓		✓			
3										
4										
5		✓			✓		✓			
6										
7										
8										
9		✓			✓		✓			
10										
11										
12		✓		✓			✓			
13										
14										
15										
16		✓		✓			✓			
17										
18										
19										
20										
21										
22										
23		✓		✓			✓			
24										
25										
26										
27										
28										
29										
30		✓		✓			✓			
31										

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.) 1212 Pump Station Chlor Tank

Additional Comments:

CONTROL SYSTEM

Utility: Mendenhall Sub's

Inspected by:

Month: Oct

Year: 2009

Day	Timers?					Electrical controls?					Control housing?					Unprotected electrical connections?				
	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Yes	No	Number	Needs	Maintenance
1	✓					✓						✓					✓			
2																				
3	✓					✓						✓					✓			
4																				
5	✓					✓						✓					✓			
6	✓					✓						✓					✓			
7	✓					✓						✓					✓			
8	✓					✓						✓					✓			
9																				
10	✓					✓						✓					✓			
11																				
12	✓					✓						✓					✓			
13	✓					✓						✓					✓			
14	✓					✓						✓					✓			
15	✓					✓						✓					✓			
16																				
17	✓					✓						✓					✓			
18																				
19	✓					✓						✓					✓			
20	✓					✓						✓					✓			
21	✓					✓						✓					✓			
22	✓					✓						✓					✓			
23																				
24	✓					✓						✓					✓			
25																				
26	✓					✓						✓					✓			
27	✓					✓						✓					✓			
28	✓					✓						✓					✓			
29	✓					✓						✓					✓			
30																				
31	✓					✓						✓					✓			

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments: 10-3-09 Painted Tank!

AERATION BASIN

Utility: _____ Inspected by: _____

Month: _____ Year: _____

Day	Even air distribution (any dead spots?)				Diffusers?					Air leaks around base and fittings of blower?				Blower belts wear and tension?					Unusual noises or vibration?			
	Yes	No	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Yes	No	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Yes	No	Needs	Maintenance
1	✓					✓					✓			✓						✓		
2																						
3	✓					✓								✓						✓		
4																						
5	✓					✓								✓						✓		
6	✓					✓								✓						✓		
7	✓					✓								✓						✓		
8	✓					✓								✓						✓		
9																						
10	✓					✓								✓						✓		
11																						
12	✓					✓								✓						✓		
13	✓					✓								✓						✓		
14	✓					✓								✓						✓		
15	✓					✓								✓						✓		
16																						
17	✓					✓								✓						✓		
18																						
19	✓					✓								✓						✓		
20	✓					✓								✓						✓		
21	✓					✓								✓						✓		
22	✓					✓								✓						✓		
23																						
24	✓					✓								✓						✓		
25																						
26	✓					✓								✓						✓		
27	✓					✓								✓						✓		
28	✓					✓								✓						✓		
29	✓					✓								✓						✓		
30																						
31	✓					✓								✓						✓		

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CLARIFIER

Utility: _____ Inspected by: _____

Month: _____ Year: _____

	Sludge blanket depth					Sludge collection arm turning					Any floating material on top of clarifier?			Sludge recirculation system?					Scum recirculation system?				
Day	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance
1	✓										✓			✓					✓				
2																							
3																							
4																							
5	✓										✓								✓				
6																							
7																							
8	✓										✓								✓				
9																							
10	✓										✓								✓				
11																							
12																							
13																							
14	✓										✓								✓				
15																							
16																							
17																							
18																							
19	✓										✓								✓				
20																							
21																							
22	✓										✓								✓				
23																							
24																							
25																							
26	✓										✓								✓				
27																							
28																							
29	✓										✓								✓				
30																							
31																							

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CHLORINE CONTACT TANK

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

	Any floating material?			Any sludge?			Baffles placement to insure proper chlorine contact time			
Day	Yes	No	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs
1		✓			✓		✓			
2										
3										
4										
5		✓			✓		✓			
6										
7										
8		✓			✓		✓			
9										
10										
11										
12		✓			✓		✓			
13										
14		✓			✓		✓			
15										
16										
17										
18										
19		✓			✓		✓			
20										
21										
22		✓			✓		✓			
23										
24										
25										
26		✓			✓		✓			
27										
28										
29		✓			✓					
30										
31										

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CONTROL SYSTEM

Utility: Meadowville S-b'k Inspected by: _____

Month: Sept Year: 2009

Day	Timers?					Electrical controls?					Control housing?					Unprotected electrical connections?				
	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Yes	No	Number	Needs	Maintenance
1	✓					✓						✓					✓			
2	✓					✓						✓					✓			
3	✓					✓						✓					✓			
4																				
5	✓					✓						✓					✓			
6																				
7	✓					✓						✓					✓			
8	✓					✓						✓					✓			
9																				
10	✓					✓						✓					✓			
11	✓					✓						✓					✓			
12	✓					✓						✓			✓		✓			
13																				
14	✓					✓						✓					✓			
15	✓					✓						✓					✓			
16	✓					✓						✓					✓			
17	✓					✓						✓					✓			
18																				
19	✓					✓						✓					✓			
20																				
21	✓					✓						✓					✓			
22	✓					✓						✓					✓			
23	✓					✓						✓					✓			
24	✓					✓						✓					✓			
25	✓					✓						✓					✓			
26																				
27																				
28	✓					✓						✓					✓			
29																				
30																				
31																				

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

AERATION BASIN

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

	Even air distribution (any dead spots?)			Diffusers?				Air leaks around base and fittings of blower?			Blower belts wear and tension?				Unusual noises or vibration?		
Day	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Maintenance Needs
1		✓			✓				✓		✓					✓	
2		✓			✓				✓		✓					✓	
3		✓			✓				✓		✓					✓	
4																	
5		✓			✓				✓		✓					✓	
6																	
7		✓			✓				✓		✓					✓	
8		✓			✓				✓		✓					✓	
9																	
10		✓			✓				✓		✓					✓	
11		✓			✓				✓		✓					✓	
12		✓			✓				✓		✓					✓	
13																	
14		✓			✓				✓		✓					✓	
15		✓			✓				✓		✓					✓	
16		✓			✓				✓		✓					✓	
17		✓			✓				✓		✓					✓	
18																	
19		✓			✓				✓		✓					✓	
20																	
21		✓			✓				✓		✓					✓	
22		✓			✓				✓		✓					✓	
23		✓			✓				✓		✓					✓	
24		✓			✓				✓		✓					✓	
25		✓			✓				✓		✓					✓	
26																	
27																	
28		✓			✓				✓		✓					✓	
29																	
30																	
31																	

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CLARIFIER

Utility: _____ Inspected by: _____

Month: _____ Year: _____

	Sludge blanket depth					Sludge collection arm turning					Any floating material on top of clarifier?				Sludge recirculation system?					Scum recirculation system?				
Day	Good	Fair	Poor	Needs Maintenance		Good	Fair	Poor	Needs Maintenance		Yes	No	Needs Maintenance		Good	Fair	Poor	Needs Maintenance		Good	Fair	Poor	Needs Maintenance	
1																								
2																								
3	✓										✓				✓					✓				
4																								
5																								
6																								
7																								
8	✓										✓				✓					✓				
9																								
10																								
11																								
12																								
13																								
14																								
15	✓										✓				✓					✓				
16																								
17	✓										✓				✓					✓				
18																								
19																								
20																								
21	✓										✓				✓					✓				
22																								
23																								
24																								
25	✓											✓			✓					✓				
26																								
27																								
28	✓											✓			✓					✓				
29																								
30																								
31																								

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments: 9-2. Pump & Motor 3 000 gph. 05 SH

CHLORINE CONTACT TANK

Utility: _____ Inspected by: _____

Month: _____ Year: _____

	Any floating material?			Any sludge?			Baffles placement to insure proper chlorine contact time			
Day	Yes	No	Needs Maintenance	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs Maintenance
1										
2										
3		✓			✓		✓			
4										
5										
6										
7										
8		✓			✓		✓			
9										
10										
11										
12										
13										
14		✓			✓		✓			
15										
16										
17		✓			✓		✓			
18										
19										
20										
21		✓			✓		✓			
22										
23										
24										
25		✓			✓		✓			
26										
27										
28		✓			✓		✓			
29										
30										
31										

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CONTROL SYSTEM

Utility: Mushmouth Sub'n Inspected by: _____

Month: Aug. 2009 Year: 2009

Day	Timers?				Electrical controls?				Control housing?				Unprotected electrical connections?			
	Good	Fair	Poor	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Number	Maintenance Needs
Rm 1	✓				✓											
2																
3	✓				✓					✓				✓		
Rm 4	✓				✓											
Rm 5	✓				✓											
6	✓				✓					✓				✓		
7																
Rm 8	✓				✓											
9																
10	✓				✓					✓				✓		
Rm 11	✓				✓											
Rm 12	✓				✓											
13	✓				✓					✓				✓		
Rm 14	✓				✓											
15																
16																
17	✓				✓					✓				✓		
Rm 18	✓				✓											
Rm 19	✓				✓											
20	✓				✓					✓				✓		
21																
Rm 22	✓				✓											
23																
24	✓				✓					✓				✓		
Rm 25	✓				✓											
Rm 26	✓				✓											
27																
28	✓				✓					✓				✓		
Rm 29	✓				✓											
30																
31	✓				✓					✓				✓		

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

AERATION BASIN

Utility: _____ Inspected by: _____

Month: _____ Year: _____

Day	Even air distribution (any dead spots?)			Diffusers?				Air leaks around base and fittings of blower?			Blower belts wear and tension?				Unusual noises or vibration?		
	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Maintenance Needs
Rm 1	✓			✓													
2																	
3	✓			✓					✓		✓					✓	
Rm 4	✓			✓													
Rm 5	✓			✓													
6	✓			✓					✓		✓					✓	
7																	
Rm 8	✓			✓													
9																	
10	✓			✓					✓		✓					✓	
Rm 11	✓			✓													
Rm 12	✓			✓													
13	✓			✓					✓		✓					✓	
Rm 14	✓			✓													
15																	
16																	
17	✓			✓					✓		✓					✓	
Rm 18	✓			✓													
Rm 19	✓			✓													
20	✓			✓					✓		✓					✓	
21																	
Rm 22	✓			✓													
23																	
24	✓			✓					✓		✓					✓	
Rm 25	✓			✓													
Rm 26	✓			✓													
27																	
28	✓			✓					✓		✓					✓	
Rm 29	✓			✓													
30																	
31	✓			✓					✓		✓					✓	

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CLARIFIER

Utility: _____ Inspected by: _____

Month: _____ Year: _____

	Sludge blanket depth					Sludge collection arm turning					Any floating material on top of clarifier?			Sludge recirculation system?					Scum recirculation system?				
Day	Good	Fair	Poor	Needs Maintenance		Good	Fair	Poor	Needs Maintenance		Yes	No	Needs Maintenance	Good	Fair	Poor	Needs Maintenance		Good	Fair	Poor	Needs Maintenance	
1																							
2																							
3	✓											✓		✓					✓				
4																							
5																							
6	✓											✓		✓					✓				
7																							
8																							
9																							
10	✓										✓			✓					✓				
11																							
12																							
13	✓										✓			✓					✓				
14																							
15																							
16																							
17	✓										✓			✓					✓				
18																							
19																							
20	✓										✓			✓					✓				
21																							
22																							
23																							
24	✓										✓			✓					✓				
25																							
26																							
27																							
28	✓										✓			✓					✓				
29																							
30																							
31	✓										✓			✓					✓				

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CHLORINE CONTACT TANK

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

	Any floating material?			Any sludge?			Baffles placement to insure proper chlorine contact time			
Day	Yes	No	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs
1										
2										
3		✓			✓		✓			
4										
5										
6		✓			✓		✓			
7										
8										
9										
10		✓			✓		✓			
11										
12										
13		✓			✓		✓			
14										
15										
16										
17		✓			✓		✓			
18										
19										
20		✓			✓		✓			
21										
22										
23										
24		✓			✓		✓			
25										
26										
27										
28		✓			✓		✓			
29										
30										
31		✓			✓		✓			

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CONTROL SYSTEM

Utility: Meadowood Sub A Inspected by: R. Taylor

Month: July Year: 2009

Day	Timers?					Electrical controls?					Control housing?					Unprotected electrical connections?				
	Good	Fair	Poor	Needs Maintenance		Good	Fair	Poor	Needs Maintenance		Good	Fair	Poor	Needs Maintenance		Yes	No	Number	Needs Maintenance	
1	✓					✓						✓					✓			
Rm 2	✓					✓														
Rm 3	✓					✓														
4																				
5																				
6	✓					✓						✓					✓			
Rm 7	✓					✓														
Rm 8	✓					✓														
9	✓					✓						✓					✓			
Rm 10	✓					✓														
Rm 11	✓					✓														
12																				
TLH 13	✓					✓						✓					✓			
Rm 14	✓					✓														
Rm 15	✓					✓														
TLH 16	✓					✓						✓					✓			
Rm 17	✓					✓														
18																				
19																				
TLH 20	✓					✓						✓					✓			
Rm 21	✓					✓														
Rm 22	✓					✓														
23																				
TLH 24	✓					✓						✓					✓			
Rm 25	✓					✓														
26																				
TLH 27	✓					✓						✓					✓			
Rm 28	✓					✓														
Rm 29	✓					✓														
30	✓					✓						✓					✓			
31																				

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

AERATION BASIN

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

Day	Even air distribution (any dead spots?)				Diffusers?				Air leaks around base and fittings of blower?				Blower belts wear and tension?				Unusual noises or vibration?			
	Yes	No	Needs	Maintenance	Good	Fair	Poor	Needs Maintenance	Yes	No	Needs	Maintenance	Good	Fair	Poor	Needs Maintenance	Yes	No	Needs	Maintenance
1	✓				✓					✓			✓					✓		
2	✓				✓															
3	✓				✓															
4																				
5																				
6	✓				✓					✓			✓					✓		
7	✓				✓															
8	✓				✓															
9	✓				✓					✓			✓					✓		
10	✓				✓															
11	✓				✓															
12																				
13	✓				✓					✓			✓					✓		
14	✓				✓															
15																				
16	✓				✓					✓			✓							
17	✓				✓															
18																				
19																				
20	✓				✓					✓			✓					✓		
21	✓				✓															
22	✓				✓															
23																				
24	✓				✓					✓			✓					✓		
25	✓				✓															
26																				
27	✓				✓					✓			✓					✓		
28	✓				✓															
29	✓				✓															
30	✓				✓					✓			✓					✓		
31																				

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CLARIFIER

Utility: _____ Inspected by: _____

Month: _____ Year: _____

Day	Sludge blanket depth					Sludge collection arm turning					Any floating material on top of clarifier?			Sludge recirculation system?					Scum recirculation system?				
	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance
1	✓										✓			✓					✓				
2																							
3																							
4																							
5																							
6	✓										✓			✓					✓				
7																							
8																							
9	✓										✓			✓					✓				
10																							
11																							
12																							
T/H 13	✓										✓			✓					✓				
14																							
15																							
16	✓										✓			✓					✓				
17																							
18																							
19	✓																						
20	✓										✓			✓					✓				
21																							
22																							
23	✓																						
24	✓										✓			✓					✓				
25																							
26																							
27	✓										✓			✓					✓				
28																							
29																							
30	✓										✓			✓					✓				
31																							

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CHLORINE CONTACT TANK

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

	Any floating material?			Any sludge?			Baffles placement to insure proper chlorine contact time			
Day	Yes	No	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs
1		✓			✓		✓			
2										
3										
4										
5										
6		✓			✓		✓			
7										
8										
9		✓			✓		✓			
10										
11										
12										
13		✓			✓		✓			
14										
15										
16		✓			✓		✓			
17										
18										
19										
20										
21										
22										
23										
24		✓			✓		✓			
25										
26										
27		✓		✓	pumps & clean					
28										
29										
30		✓		✓			✓			
31										

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CONTROL SYSTEM

Utility: Mendocino Sub'n Inspected by: Rm & Chuck

Month: June Year: 2009

Day	Timers?					Electrical controls?					Control housing?					Unprotected electrical connections?				
	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Yes	No	Number	Needs	Maintenance
1	✓					✓						✓					✓			
Rm 2	✓					✓														
Rm 3	✓					✓						✓					✓			
4	✓					✓														
5																				
Rm 6	✓					✓														
7												✓					✓			
8	✓					✓														
Rm 9	✓					✓														
Rm 10	✓					✓						✓					✓			
11	✓					✓														
12	✓					✓														
Rm 13	✓					✓						✓					✓			
14	✓					✓														
15	✓					✓														
Rm 16	✓					✓														
Rm 17	✓					✓														
18																				
19	✓					✓						✓					✓			
Rm 20	✓					✓														
21																				
22	✓					✓						✓					✓			
Rm 23	✓					✓														
Rm 24	✓					✓														
25												✓					✓			
26	✓					✓														
Rm 27	✓					✓														
28												✓					✓			
29	✓					✓														
Rm 30	✓					✓														
31																				

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments: Sub Panel Heat ON Rm 15&2 on June

AERATION BASIN

Utility:_____ Inspected by:_____

Month:_____ Year:_____

Day	Even air distribution (any dead spots?)			Diffusers?				Air leaks around base and fittings of blower?			Blower belts wear and tension?				Unusual noises or vibration?			
	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Maintenance Needs	
1	✓				✓				✓		✓				✓			
Rm 2	✓				✓													
Rm 3	✓				✓													
4	✓				✓				✓		✓				✓			
5																		
Rm 6	✓				✓													
7																		
8	✓				✓				✓		✓				✓			
Rm 9	✓				✓													
Rm 10	✓				✓													
11	✓				✓													
12	✓				✓													
Rm 13	✓				✓													
14																		
15	✓				✓				✓		✓				✓			
Rm 16	✓				✓													
Rm 17	✓				✓													
18																		
19	✓				✓				✓		✓				✓			
Rm 20	✓				✓													
21																		
22	✓				✓				✓		✓				✓			
Rm 23	✓				✓													
Rm 24	✓				✓													
25																		
26	✓				✓				✓		✓				✓			
Rm 27	✓				✓													
28																		
29	✓				✓				✓		✓				✓			
Rm 30	✓				✓													
31																		

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CLARIFIER

Utility: _____ Inspected by: _____

Month: _____ Year: _____

	Sludge blanket depth				Sludge collection arm turning				Any floating material on top of clarifier?			Sludge recirculation system?				Scum recirculation system?			
Day	Good	Fair	Poor	Needs Maintenance	Good	Fair	Poor	Needs Maintenance	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs Maintenance	Good	Fair	Poor	Needs Maintenance
1	✓								✓			✓				✓			
2																			
3																			
4	✓								✓			✓				✓			
5																			
6																			
7																			
8		✓							✓			✓				✓			
9																			
10																			
11																			
12																			
13		✓							✓			✓				✓			
14																			
15	✓									✓		✓				✓			
16																			
17																			
18																			
19	✓								✓			✓				✓			
20																			
21																			
22	✓								✓			✓				✓			
23																			
24																			
25																			
26	✓								✓			✓				✓			
27																			
28																			
29	✓								✓			✓				✓			
30																			
31																			

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CHLORINE CONTACT TANK

Utility: _____ Inspected by: _____

Month: _____ Year: _____

	Any floating material?			Any sludge?			Baffles placement to insure proper chlorine contact time			
Day	Yes	No	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs
1		✓			✓		✓			
2										
3										
4		✓			✓		✓			
5										
6										
7										
8		✓			✓		✓			
9										
10										
11										
12										
13		✓		✓			✓			
14										
15		✓			✓		✓			
16										
17										
18										
19		✓			✓		✓			
20										
21										
22		✓			✓		✓			
23										
24										
25										
26		✓			✓		✓			
27										
28										
29		✓			✓		✓			
30										
31										

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

Utility: Marlborough Sub Inspected by: Robert Bartlett

Month: May Year: 2009

Day	Timers?				Electrical controls?				Control housing?				Unprotected electrical connections?			
	Good	Fair	Poor	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Number	Maintenance Needs
1																
RM 2	✓				✓											
3	✓				✓					✓				✓		
4																
RM 5	✓				✓											
6	✓				✓					✓				✓		
RM 7	✓				✓											
8																
RM 9	✓				✓											
10																
RM 11	✓				✓											
RM 12	✓				✓											
13	✓				✓					✓				✓		
14	✓				✓					✓				✓		
RM 15	✓				✓											
16																
17																
18	✓				✓					✓				✓		
RM 19	✓				✓											
RM 20	✓				✓											
21	✓				✓					✓				✓		
22																
RM 23	✓				✓											
24																
25																
26	✓															
RM 27	✓				✓					✓				✓		
RM 28	✓				✓					✓				✓		
29																
RM 30	✓				✓											
31																

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

AERATION BASIN

Utility:_____ Inspected by:_____

Month:_____ Year:_____

Day	Even air distribution (any dead spots?)			Diffusers?				Air leaks around base and fittings of blower?			Blower belts wear and tension?				Unusual noises or vibration?		
	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs Maintenance	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs Maintenance	Yes	No	Needs Maintenance
1																	
2	✓			✓													
3																	
4	✓				✓				✓		✓					✓	
5	✓			✓													
6																	
7	✓			✓													
8																	
9	✓			✓													
10																	
11	✓			✓													
12	✓			✓													
13																	
14	✓			✓					✓		✓					✓	
15	✓			✓													
16																	
17																	
18	✓			✓					✓		✓					✓	
19	✓			✓													
20	✓			✓													
21	✓			✓					✓		✓					✓	
22																	
23	✓			✓													
24																	
25																	
26	✓			✓					✓		✓					✓	
27	✓			✓													
28	✓			✓					✓		✓					✓	
29																	
30	✓			✓													
31																	

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CLARIFIER

Utility: _____ Inspected by: _____

Month: _____ Year: _____

Day	Sludge blanket depth					Sludge collection arm turning					Any floating material on top of clarifier?				Sludge recirculation system?					Scum recirculation system?				
	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Yes	No	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance
1																								
2																								
3																								
4	✓										✓				✓					✓				
5																								
6																								
7																								
8																								
9																								
10																								
11																								
12																								
13																								
14		✓									✓				✓					✓				
15																								
16																								
17																								
18		✓									✓				✓					✓				
19																								
20																								
21		✓									✓				✓					✓				
22																								
23																								
24																								
25																								
26		✓									✓				✓					✓				
27																								
28		✓									✓				✓					✓				
29																								
30																								
31																								

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CHLORINE CONTACT TANK

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

	Any floating material?			Any sludge?			Baffles placement to insure proper chlorine contact time			
Day	Yes	No	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs
1										
2										
3										
4		✓			✓		✓			
5										
6										
7										
8										
9										
10										
11										
12										
13										
14		✓			✓		✓			
15										
16										
17										
18		✓		✓			✓			
19										
20										
21	✓			✓			✓			
22										
23										
24										
25										
26	✓				✓		✓			
27										
28		✓			✓		✓			
29										
30										
31										

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

18th Pump & Clean
21st Pump & Clean

LAGOON

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

	Any buildup of scum on pond surface and discharge outlet boxes?			Signs of burrowing animals?			Anaerobic conditions noted by odor and/or black color?			Water grown weeds?			Dike leakage?			Fence damage?			Ice buildup in winter?			Evidence of short circuiting?		
Day	Yes	No	Maintenance Needs	Yes	No	Maintenance Needs	Yes	No	Maintenance Needs	Yes	No	Maintenance Needs	Yes	No	Maintenance Needs	Yes	No	Maintenance Needs	Yes	No	Maintenance Needs	Yes	No	Maintenance Needs
1																								
2																								
3																								
4																								
5																								
6																								
7																								
8																								
9																								
10																								
11																								
12																								
13																								
14																								
15																								
16																								
17																								
18																								
19																								
20																								
21																								
22																								
23																								
24																								
25																								
26																								
27																								
28																								
29																								
30																								
31																								

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

Utility: Manitowoc Sub 1 Inspected by:

Month: May Year: 2009

Day	Timers?					Electrical controls?					Control housing?					Unprotected electrical connections?				
	Good	Fair	Poor	Needs Maintenance		Good	Fair	Poor	Needs Maintenance		Good	Fair	Poor	Needs Maintenance		Yes	No	Number	Needs Maintenance	
Rm 1	✓					✓														
2	✓					✓						✓					✓			
Rm 3	✓					✓														
4												✓								
5																				
6	✓					✓						✓					✓			
7	✓					✓														
8	✓					✓														
9	✓					✓						✓					✓			
10																				
11																				
12																				
13	✓					✓						✓					✓			
Rm 14	✓					✓														
15	✓					✓						✓								
16	✓					✓						✓								
17																				
Rm 18	✓					✓														
19																				
20	✓					✓						✓					✓			
Rm 21	✓					✓														
Rm 22	✓					✓														
23	✓					✓						✓					✓			
24																				
Rm 25	✓					✓														
26																				
27	✓					✓						✓					✓			
Rm 28	✓					✓														
Rm 29	✓					✓														
Rm 30	✓					✓														
31																				

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

May

Rm. 2nd ✓ ✓

AERATION BASIN

Utility: _____ Inspected by: _____

Month: _____ Year: _____

Day	Even air distribution (any dead spots?)			Diffusers?				Air leaks around base and fittings of blower?			Blower belts wear and tension?				Unusual noises or vibration?		
	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Maintenance Needs
1	✓				✓												
2	✓				✓	✓			✓		✓					✓	
3	✓				✓												
4																	
5																	
6	✓				✓				✓		✓					✓	
7																	
8																	
9	✓				✓				✓		✓					✓	
10																	
11																	
12																	
13	✓				✓				✓		✓					✓	
14	✓				✓												
15																	
16																	
17																	
18	✓				✓												
19																	
20	✓				✓				✓		✓					✓	
21	✓				✓												
22	✓				✓												
23	✓				✓				✓		✓					✓	
24																	
25	✓				✓												
26																	
27	✓				✓				✓		✓					✓	
28	✓				✓												
29	✓				✓												
30	✓				✓												
31																	

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

✓ ✓

RM

CLARIFIER

Utility: _____ Inspected by: _____

Month: _____ Year: _____

	Sludge blanket depth					Sludge collection arm turning					Any floating material on top of clarifier?				Sludge recirculation system?					Scum recirculation system?				
Day	Good	Fair	Poor	Needs Maintenance		Good	Fair	Poor	Needs Maintenance		Yes	No	Needs Maintenance		Good	Fair	Poor	Needs Maintenance		Good	Fair	Poor	Needs Maintenance	
1																								
2	✓										✓				✓					✓				
3																								
4																								
5																								
6	✓										✓				✓					✓				
7																								
8																								
9	✓										✓				✓					✓				
10																								
11																								
12																								
13	✓										✓				✓					✓				
14																								
15																								
16																								
17																								
18																								
19																								
20	✓										✓				✓					✓				
21																								
22																								
23	✓										✓				✓					✓				
24																								
25																								
26																								
27	✓										✓				✓					✓				
28																								
29																								
30																								
31																								

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CHLORINE CONTACT TANK

Utility: _____ Inspected by: _____

Month: _____ Year: _____

Day	Any floating material?			Any sludge?			Baffles placement to insure proper chlorine contact time			
	Yes	No	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs
1										
2		✓		✓			✓			
3										
4										
5										
6		✓			✓		✓			
7										
8										
9		✓			✓		✓			
10										
11										
12										
13		✓			✓		✓			
14										
15										
16										
17										
18										
19										
20		✓		✓			✓			
21										
22										
23		✓		✓			✓			
24										
25										
26										
27		✓		✓			✓			
28										
29										
30										
31										

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

4.2.09 Purge Sludge out of Chlorine Contact Tank

4.2.09 Purge Sludge from Chlorine Tank

AERATION BASIN

Utility: Meadow Brook Sub'd **Inspected by:** Rehmann Investments

Month: [redacted] March **Year:** 2009

Day	Even air distribution (any dead spots?)			Diffusers?				Air leaks around base and fittings of blower?			Blower belts wear and tension?				Unusual noises or vibration?		
	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Maintenance Needs
1	✓																
2	✓																
2.11 3	✓				✓				✓		✓					✓	
4	✓																
5	✓																
6	✓																
7	✓																
2.11 8	✓				✓				✓		✓					✓	
9	✓				✓												✓
10	✓				✓				✓		✓					✓	
11	✓																
12	✓																
13	✓																
14	✓				✓				✓		✓					✓	✓
15																✓	
16	✓																✓
17	✓				✓				✓		✓					✓	
18	✓																
19	✓																
20	✓																✓
21	✓				✓				✓		✓					✓	
22	✓																
23	✓																
24	✓				✓				✓		✓					✓	
25	✓																
26	✓																
27	✓																
28	✓				✓				✓		✓					✓	
29	✓																
30	✓																
31	✓				✓				✓		✓					✓	

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CLARIFIER

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

	Sludge blanket depth					Sludge collection arm turning					Any floating material on top of clarifier?				Sludge recirculation system?					Scum recirculation system?				
Day	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Yes	No	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance
1	✓																							
2	✓																							
3	✓										✓				✓					✓				
4	✓																							
5	✓																							
6	✓																							
7	✓																							
8	✓										✓				✓					✓				
9	✓										✓				✓						✓			
10	✓										✓				✓						✓			
11																								
12																								
13	✓		✓								✓			✓	✓						✓			
14	✓		✓								✓		✓		✓						✓			
15																								
16	✓										✓	✓			✓						✓			
17	✓										✓	✓			✓						✓			
18	✓																							
19	✓																							
20	✓										✓				✓						✓			
21	✓										✓	⊗			✓						✓			
22	✓																							
23	✓																							
24	✓										✓				✓						✓			
25	✓																							
26	✓																							
27	✓																							
28	✓										✓				✓						✓			
29	✓																							
30	✓																							
31	✓										✓				✓						✓			

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CONTROL SYSTEM

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

	Timers?				Electrical controls?				Control housing?				Unprotected electrical connections?			
Day	Good	Fair	Poor	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Number	Maintenance Needs
1																
2																
3	✓				✓					✓				✓		
4																
5																
6																
7																
8	✓				✓					✓				✓		
9	✓				✓					✓				✓		
10	✓				✓					✓				✓		
11																
12																
13	✓				✓					✓				✓		
14	✓				✓					✓				✓		
15																
16	✓				✓					✓				✓		
17	✓				✓					✓				✓		
18																
19																
20																
21																
22																
23																
24	✓				✓					✓				✓		
25																
26																
27																
28	✓				✓					✓				✓		
29																
30																
31	✓				✓					✓				✓		

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CHLORINE CONTACT TANK

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

	Any floating material?			Any sludge?			Baffles placement to insure proper chlorine contact time			
Day	Yes	No	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs
1										
2										
3		✓		✓			✓			
4										
5										
6										
7										
8		✓		✓			✓			
9		✓		✓			✓			
10		✓		✓			✓			
11										
12										
13										
14		✓		✓			✓			
15										
16		✓			✓		✓			
17		✓		✓	✓		✓			
18										
19										
20		✓			✓		✓			
21		✓			✓		✓			
22										
23										
24		✓			✓		✓			
25										
26										
27										
28		✓			✓		✓			
29										
30										
31		✓		✓			✓			

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments: _____

CONTROL SYSTEM

Utility: [illegible] S.A. Inspected by: _____

Month: Feb. 2009 Year: 2009

Day	Timers?					Electrical controls?					Control housing?					Unprotected electrical connections?				
	Good	Fair	Poor	Needs Maintenance		Good	Fair	Poor	Needs Maintenance		Good	Fair	Poor	Needs Maintenance		Yes	No	Number	Needs Maintenance	
1																				
2	✓					✓						✓					✓			
3																				
4																				
5	✓					✓						✓					✓			
6																				
7	✓					✓						✓					✓			
8																				
9	✓					✓						✓					✓			
10																				
11																				
12	✓					✓						✓					✓			
13	✓					✓														
14																				
15																				
16																				
17	✓					✓						✓					✓			
18	✓					✓														
19 2.4	✓					✓						✓					✓			
20																				
21	✓					✓						✓					✓			
22																				
23	✓					✓						✓					✓			
24																				
25																				
26	✓					✓						✓					✓			
27																				
28																				
29																				
30																				
31																				

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

AERATION BASIN

Utility: _____ Inspected by: _____

Month: _____ Year: _____

Day	Even air distribution (any dead spots?)			Diffusers?				Air leaks around base and fittings of blower?			Blower belts wear and tension?				Unusual noises or vibration?		
	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs	Yes	No	Maintenance Needs
1																	
2		✓			✓				✓		✓					✓	
3																	
4		✓			✓				✓		✓					✓	
5		✓			✓				✓		✓					✓	
6																	
7		✓			✓				✓		✓					✓	
8																	
9	✓				✓				✓		✓					✓	
10																	
11																	
12	✓				✓				✓		✓					✓	
13	✓				✓				✓		✓					✓	
14																	
15																	
16																	
17	✓				✓				✓		✓					✓	
18																	
19	✓				✓				✓		✓					✓	
20																	
21	✓				✓				✓		✓					✓	
22																	
23	✓				✓				✓		✓					✓	
24																	
25																	
26	✓				✓				✓		✓					✓	
27																	
28																	
29																	
30																	
31																	

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CLARIFIER

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

	Sludge blanket depth					Sludge collection arm turning					Any floating material on top of clarifier?			Sludge recirculation system?					Scum recirculation system?				
Day	Good	Fair	Poor	Needs Maintenance		Good	Fair	Poor	Needs Maintenance		Yes	No	Needs Maintenance	Good	Fair	Poor	Needs Maintenance		Good	Fair	Poor	Needs Maintenance	
1																							
2	✓											✓		✓					✓				
3																							
4	✓											✓		✓					✓				
5	✓											✓		✓					✓				
6																							
7	✓											✓		✓					✓				
8																							
9	✓											✓		✓					✓				
10																							
11																							
12	✓											✓		✓					✓				
13	✓											✓		✓					✓				
14																							
15																							
16																							
17	✓										✓			✓					✓				
18																							
19	✓										✓			✓					✓				
20																							
21	✓										✓			✓					✓				
22																							
23	✓										✓			✓					✓				
24											✓			✓					✓				
25																							
26	✓										✓			✓					✓				
27																							
28																							
29																							
30																							
31																							

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CHLORINE CONTACT TANK

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

	Any floating material?			Any sludge?			Baffles placement to insure proper chlorine contact time			
Day	Yes	No	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs
1										
2		✓			✓		✓			
3										
4										
5		✓			✓		✓			
6										
7										
8										
9		✓			✓		✓			
10										
11										
12		✓			✓		✓			
13										
14										
15										
16										
17		✓			✓		✓			
18										
19										
20										
21										
22										
23		✓			✓		✓			
24										
25										
26		✓			✓		✓			
27										
28										
29										
30										
31										

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CONTROL SYSTEM

Utility: Mendocino Sub 1 Inspected by: Chuck Hughes

Month: JAN. Year: 2009

	Timers?					Electrical controls?					Control housing?					Unprotected electrical connections?				
Day	Good	Fair	Poor	Needs Maintenance		Good	Fair	Poor	Needs Maintenance		Good	Fair	Poor	Needs Maintenance		Yes	No	Number	Needs Maintenance	
1																				
2	✓						✓					✓					✓			
3																				
4																				
5																				
6																				
7																				
8	✓						✓					✓					✓			
9																				
10																				
11																				
12	✓						✓					✓					✓			
13	✓						✓					✓					✓			
14																				
15	✓						✓					✓					✓			
16																				
17																				
18																				
19	✓						✓					✓					✓			
20	✓						✓					✓					✓			
21																				
22	✓						✓					✓					✓			
23																				
24																				
25																				
26	✓						✓					✓					✓			
27																				
28																				
29																				
30																				
31																				

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

AERATION BASIN

Utility: _____ Inspected by: _____

Month: _____ Year: _____

	Even air distribution (any dead spots?)			Diffusers?				Air leaks around base and fittings of blower?			Blower belts wear and tension?				Unusual noises or vibration?		
Day	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs Maintenance	Yes	No	Needs Maintenance	Good	Fair	Poor	Needs Maintenance	Yes	No	Needs Maintenance
1																	
2	✓				✓				✓		✓					✓	
3																	
4																	
5																	
6																	
7																	
8	✓				✓				✓		✓					✓	
9																	
10																	
11																	
12	✓				✓				✓		✓					✓	
13	✓				✓				✓		✓					✓	
14																	
15	✓				✓				✓		✓					✓	
16																	
17																	
18																	
19	✓				✓				✓		✓					✓	
20	✓				✓				✓		✓					✓	
21																	
22	✓				✓				✓		✓					✓	
23																	
24																	
25																	
26	✓				✓				✓		✓					✓	
27																	
28																	
29																	
30																	
31																	

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CLARIFIER

Utility: _____ Inspected by: _____

Month: _____ Year: _____

Day	Sludge blanket depth					Sludge collection arm turning					Any floating material on top of clarifier?				Sludge recirculation system?					Scum recirculation system?				
	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Yes	No	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance	Good	Fair	Poor	Needs	Maintenance
1																								
2	✓										✓				✓					✓				
3																								
4																								
5																								
6																								
7																								
8	✓										✓				✓					✓				
9																								
10																								
11																								
12	✓																							
13											✓				✓					✓				
14																								
15		✓									✓				✓					✓				
16																								
17																								
18																								
19		✓									✓				✓					✓				
20		✓									✓				✓					✓				
21																								
22		✓									✓				✓					✓				
23																								
24																								
25																								
26		✓									✓				✓					✓				
27																								
28																								
29																								
30																								
31																								

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments:

CHLORINE CONTACT TANK

Utility: _____ **Inspected by:** _____

Month: _____ **Year:** _____

Day	Any floating material?			Any sludge?			Baffles placement to insure proper chlorine contact time			
	Yes	No	Maintenance Needs	Yes	No	Maintenance Needs	Good	Fair	Poor	Maintenance Needs
1										
2		✓			✓		✓			
3										
4										
5										
6										
7										
8		✓			✓		✓			
9										
10										
11										
12		✓			✓		✓			
13		✓		✓			✓			
14										
15		✓		✓			✓			
16										
17										
18										
19		✓		✓			✓			
20		✓		✓			✓			
21										
22		✓		✓			✓			
23										
24										
25										
26		✓		✓			✓			
27										
28										
29										
30										
31										

(If any inspected element is in need of maintenance, attach documents [such as bids, invoices, etc.] that support maintenance action taken.)

Additional Comments: Need to clean Chlorine Tank