

BRIAN CUMBO

ATTORNEY AT LAW

86 W. Main St., Suite 100 P.O. Box 1844 Inez, KY 41224 (606) 298-0428 FAX: (606) 298-0316 cumbolaw@cumbolaw.com

ADMITTED IN KY AND WV

RECEIVED

MAY 12 2016

Public Service Commission

Aaron Greenwell, Acting Executive Director Public Service Commission P.O. Box 615

RE: Martin County Water District PSC Case No. 2016-00142

Dear Mr. Greenwell:

Frankfort, KY 40602

May 10, 2016

Enclosed please find an original and one (1) copy of Motion for Confidentiality and the redacted Martin County Water District's Response to information requested in Appendix H of the Public Service Commission's Order entered April 11, 2016 regarding the above matter.

Thank you for your attention to this matter.

Very truly yours,

BRIAN CUMBO

BC/ld Enclosure

cc: Martin County Water District

COMMONWEALTH OF KENTUCKY

BEFORE THE PUBLIC SERVICE COMMISSION	N	
In the Matter of:		
INVESTIGATION OF THE OPERATING CAPACITY OF MARTIN COUNTY WATER DISTRICT PURSUANT TO KRS 278.280)	CASE NO. 2016-00142 RECEIVE
		MAY 12 2016
		Public Service Commission

MARTIN COUNTY WATER DISTRICT'S RESPONSE TO INFORMATION REQUESTED IN APPENDIX H OF THE PUBLIC SERVICE COMMISSIONER'S ORDER ENTERED APRIL 11, 2016

CERTIFICATE OF SERVICE

I hereby certify that service was made as required by the April 11, 2016 Order of the Public Service Commission, the original and one true and correct copy of the Martin County Water District's Response to information requested in Appendix H of said Order, to the following on May 5, 2016 via overnight delivery and the redacted Response on May 10, 2016: Aaron D. Greenwell, Acting Executive Director, Public Service Commission, 211 Sower Boulevard, P.O. Box 615, Frankfort, KY 40602

HON. BRIAN CUMBO

ATTORNEY FOR MARTIN COUNTY

WATER DISTRICT

PO BOX 1844

INEZ, KY 41224

TELEPHONE (606) 298-0428

FACSIMILE (6060) 298-0316

EMAIL: cumbolaw@cumbolaw.com

TABLE OF CONTENTS

MARTIN COUNTY WATER DISTRICT'S RESPONSE	1-8
VERIFICATION OF PREPARER	9
EXHIBIT #1 – CURRENT LIST OF WORK ORDERS	
EXHIBIT #2 – NUMBER OF TAPS REQUESTED	
EXHIBIT #3 – NUMBER OF TAPS REQUEST PENDING	
EXHIBIT #4 – NUMBER OF TURN-OFFS	
EXHIBIT #5 – COMPARISON OF ELECTRICITY COST	
EXHIBIT #6 – WATER LOSS AND LEAK DETECTION PROGRAM	
EXHIBIT #7 – UPDATED CAPITAL IMPROVEMENT PLAN	
EXHIBIT #8 – PENDING DISCONNECTS	
EXHIBIT #9 – BUSINESS MANAGER'S JOB DUTIES	
EXHIBIT #10 – WRITTEN COMPLAINTS	
EXHIBIT #11 – TELEMENTRY PRESSURE CHARTS	
EXHIBIT #12 – PUBLIC NOTIFICATION	
EXHIBIT #13 – DIVISION OF WATER	

Martin County Water District Before the Public Service Commission

Martin County Water District ("Martin District"), a water district organized pursuant to KRS Chapter 74, owns and operates facilities that treat and distribute water to approximately 3,533 customers in Martin County, Kentucky.

Joe Hammond
Jhammond58@bellsouth.net

PSC Data Request Response Case No. 2016-00142

Questions 1-17 are related to ongoing Management Audit recommendations steps.

- 1. Refer to the 2007 Management Audit Action Plan, Recommendation 11-1
 - Step 3. Provide a current list of work orders for leak repairs, meter sets, meter rereads, meter pulls, low pressure, meter reads (in and out), tap relocates, and similar distribution work, and explain how Martin District addresses these work orders.
 - a. Exhibit #1
- 2. Refer to the 2007 Management Audit Action Plan, Recommendation 11-1
 - Step 4. Provide the following:
 - A. The number of tap requests processed and completed since October 6, 2015 (the date the new NRC tariff was issued).
 - a. Exhibit #2
 - b. 5 Tap request
 - B. The number of tap request pending as of November 13, 2015.
 - c. Exhibit #3
 - d. No tap request pending
 - C. An estimate of when Martin District expects to complete the taps outstanding as of November 13, 2015.
 - e. No taps outstanding
- 3. Refer to the 2007 Management Audit Action Plan, Recommendation 11-1
 - Step 5. Provide the following:
 - A. The number of turn-offs performed since October 6, 2015.
 - a. Exhibit #4
 - B. The number of outstanding or past-due accounts.
 - b. 137 Customers 30-60-90 days
- 4. Refer to the 2007 Management Audit Action Plan, Recommendation 11-1

Step 7. Provide the following:

- A. Identify the number and location of additional pumps Martin District plans to install to allow pumping at night. For each, provide an estimate of when Martin District plans to install the pumps.
 - a. None at this time
- B. A comparison of electricity costs for each month for the past two years.
 - b. Electricity comparison for 2014 2015
 - c. Exhibit #5
- 5. Refer to the 2007 Management Audit Action Plan, Recommendation 11-1
 - Step 9. Provide the following:
 - A. Explain whether or not Martin District will reach the goal of five treatment plant operators.
 - a. At present the District has two (2) part-time and two (2) full-time operators.
 - b. The District has one employee full-time training for his class II operator license. He will be testing in July 2016. Hopefully by January 2017, he will be ready for his class III.
 - c. As everyone knows, treatment operators are difficult to find and to hire. In-house training is a must and that is the District's goal.
- 6. Refer to the 2007 Management Audit Action Plan, Recommendation 11-2
 - Step 1. Provide the following:
 - A. The amount and percentage of line loss on each system (A and B) through December 31, 2015.
 - a. Amount of water loss = 393.097 million gallons
 - b. Percentage = 62%
 - B. The amount and percentage of line loss for calendar years 2014, 2013, and 2012.
 - a. Amount of water loss 2012 = 370.087 million gallons =56% Loss

- b. Amount of water loss 2013 = 399.816 million gallons = 61% Loss
- c. Amount of water loss 2014 = 376.606 million gallons = 52%
- 7. Refer to the 2007 Management Audit Action Plan, Recommendation 11-1

Step 2 and 3. Provide the following:

- A. Identify known leaks and prioritize the mains and services for replacement or repair based on volumes.
 - a. Pigeon Roost under railroad tracks casing broke and broke a 4" line. Repaired March 2016. Leak detection assisted by KRWA and District personnel.
 - b. Little Peter Cave, Wolf Creek Area, estimated 2 to 3 million a month. Repaired April 2016. Leak detection assisted by KRWA and District personnel.
 - c. Elk Creek, Beauty KY, estimated 3 to 3.5 million a month. Repaired March 2016. Leak detection assisted by KRWA and District personnel.
- B. An estimate of when replacement or repair will be undertaken.
 - a. This will be an ongoing process until water loss is under control.
 - b. Replacement of old water lines will be determined when funding is in place.
 - c. Repairs to line breaks will be taken care of ASAP.
- 8. Refer to the 2007 Management Audit Action Plan, Recommendation 11-2
 - Step 4. Other than identification (of cheater bars) when reading meters, explain how Martin District is addressing this recommendation.
 - a. Since August 2015, found 2 cheater bars and turned over to the County Attorney for prosecution.
 - b. One customer is now paying his bill due to the County Attorney's action.
 - c. No update on the other one.

- 9. Refer to the 2007 Management Audit Action Plan, Recommendation 11-2
 - Step 5. Provide an update of Martin District's progress in replacing or repairing all excessively leaking mains and services as outlined in Step 5. Identify any decreases in water loss resulting from it efforts.
 - a. Reference Step 2 and 3 above. The leaks mention above have been repaired. Our storage tanks in these areas are maintained at the appropriate levels. Water loss in these areas will be determined at the end of the month.
- 10. Refer to the 2007 Management Audit Action Plan, Recommendation 11-3
 - Steps 1-4. Provide Martin District's formal, written preventive maintenance program.
 - a. The District has a Water Loss and Leak Detection Program for Preventive Maintenance.
 - b. Exhibit #6
 - c. The District will begin to prepare a complete Preventive Maintenance Plan for all assets in the District.
- 11. Refer to the 2007 Management Audit Action Plan, Recommendation 11-5
 - a. After consulting with the Health Inspector, concerning the water shed, he is aware of the situation and monitors the area where residents live. No complaints at this time.
- 12. Refer to the 2007 Management Audit Action Plan, Recommendation 11-6
 - Steps 1, 2, 3, and 6. Other than working with the electric providers to reduce power outages, explain how Martin District is addressing this recommendation.
 - a. The District has purchased a 300kw mobile generator that can run the plant or any other pump station in the system. The District has spent approximately \$23000.00 for the generator. This has and will continue to assist the District in covering our power outages.
 - b. Also, the power company has been clearing trees from overhead power lines.
- 13. Refer to the 2007 Management Audit Action Plan, Recommendation 111-1

Other than working with the Big Sandy ADD, explain what internal or other external steps Martin District is taking to address this recommendation.

- a. Continue to meet with BSADD, KRWA, PSC, and Division of Water planning and prioritizing our system to comply with the rules and regulation set forth for the District.
- b. The District will evaluate the upgrades made to the Capital Improvement Plan of 2003 and improve the Plan to current needs of the system. Plans updated (03/08/2016).
- c. Exhibit #7
- 14. Refer to the 2007 Management Audit Action Plan, Recommendation 111-2

Steps 1 and 2. Provide the following:

- A. Identify the water loss reduction related construction projects undertaken in the past year and identify those planned for the next six months.
 - a. The District is replacing old service lines and as funding permits, replacing old main lines.
 - b. Training and assistance from KRWA pertaining to the proper technique in locating hard to find leaks and to maintain proper records to ascertain when a leak occurs and repair and track the amount of water loss. This process will continue throughout the daily process of the District.
 - c. Replacing 100 Radio Read meters in the Wolf Creek Area. If funding becomes available, the District plans are to continue replacing all manual read meters. This will help with water loss and theft of services.
 - d. The District believes that each project identified above will contribute to less water loss.
- 15. Refer to the 2007 Management Audit Action Plan, Recommendation IV-3

Provide a report of pending disconnects for 30-60-90 days, for the most recent date, available at the time of your response.

- a. Exhibit #8
- 16. Refer to the 2007 Management Audit Action Plan, Recommendation V-4

Steps 1, 2, 3 and 4. Provide the following:

A. External audit reports for years 2013, 2014, and 2015 when completed.

- a. The audit firm of White and Associates, PSC, Richmond, KY has been engaged to complete audits for the years in question. The projected completion dates are early summer 2016. Copies will be forwarded upon receipt.
- B. If any of these reports are complete, provide an estimate of when each audit will be completed.
 - b. No audits are complete at this time.
- 17. Refer to the 2007 Management Audit Action Plan, Recommendation V-5

Steps 1 and 2: Provide a description of the duties of the Business Manager position.

- a. Exhibit #9
- 18. Refer to the 2007 Management Audit Action Plan, Recommendation V-5
 - A. Provide a copy of each written complaint or electronic mail message containing a complaint concerning water service received by Martin District during the period January 1, 2013 to the present. Include with the response a copy of Martin District's response to the complaint. If Martin District has not retained documentation of the complaints, explain why each document has not been retained.
 - a. 2013 2016 Exhibit #10
- 19. Provide a schedule that contains the date, time, and duration of each event in which Martin District was not in compliance with 807 KAR 5:066, Section 5(1). During the period January 1, 2013, to present.
 - The District uses our Telementry system to monitor the pressure (both Suction and Discharge) throughout our system.
 - a. Exhibit #11
 - b. Beginning this month, (April 2016) a pressure recording device will be installed in different areas of the system and charts maintained.
- 20. Provide a copy of each public notification that Martin District has been required to provide to its customers pursuant to federal or state drinking water regulations during the period January 1, 2013, to present.
 - a. Exhibit #12
- 21. Provide a copy of all communication between Martin District and the Kentucky Division of Water, including its regional offices, during the period January 1, 2013, to present.

- a. Researching files to completely comply with this request.
- b. Exhibit #13
- 22. Refer to the Public Service Commission's Utility Inspection Report for Martin District dated December 23, 2014. Provide the following:
 - A. Explain why Martin District failed to produce pressure surveys that showed a continuous 24-hour pressure recording for a minimum of one week per month as required by 807 KAR 5:066, Section 5(2).
 - a. Ongoing research as to the fail process of the pressure surveys required by 807 KAR 5:066, Section 5(2).
 - b. Policies have been implemented effective April 1, 2016 to be fully compliant.
 - B. Explain Martin District's procedure for monitoring and documenting withdrawals from Martin District by fire departments.
 - c. Reports have been presented to the Fire Departments to complete the withdrawals from the Martin District's system, however, no cooperation.
 - C. For each fire department that made a withdrawal from the Martin District system for the purpose of extinguishing fires or training purposes during the period January 1, 2013, to present, provide a copy of the fire department's estimate of the withdrawal.
 - d. Estimates were made by the District's Office since no reports were present for withdrawals and placed on the water loss report as estimates.
 - D. For any instance in which a fire department failed to provide an estimate of a withdrawal during the period January 1, 2013, to present, state the actions that Martin District took concerning the failure.
 - e. A meeting was held with the County Judge Executive the Chairman of the Board and Business Manager, concerning the lack of water withdrawal reports from the Fire Departments and was informed that the Judge Executive would withhold funds from the Fire Departments.
 - E. Provide a copy of each record kept by Martin District pursuant to 807 KAR 5:006, Section 26(3), for the period January 1, 2015, to date.
 - f. The District will be presented with a Utility Inspection Checklist for approval at the next meeting on May 24, 2016. The Inspection Checklist will then be sent to the Commission for review.

- 23. Identify each contract that Martin District has with another water system for the purchase or sale of water. For each contract, state the date the contract was filed with the Commission.
 - a. Mountain Water District (04/16/1992)
 - b. Paintsville Utilities (05/01/2013)
 - c. Prestonsburg Utilities (Agreement (01/15/1998)
- 24. Confirm whether Martin District is currently providing water service to the United States Penitentiary, Big Sandy, and if not, explain why Martin District is unable to provide water service to the federal prison.
 - a. The District supplies water to the Honey Branch Tank and that water pumped is metered at the pump station, located at the entrance to the Honey Branch Industrial Park. Martin County customers or businesses located on the Industrial Site and on New Route 3, Davella Road, Brookview Apartments, and Holding Hills Trailer Park are supplied by the Honey Branch Tank. The water supplied to District's customers is metered by the outgoing meter at the pump station. The difference in water going to the Honey Branch Tank and water supplied to the Martin County customers is purchased by Prestonsburg Utilities at \$3.05 per thousand. If we do not pump sufficient amount of water to supply our businesses and customers mention, we must pay Prestonsburg Utilities \$3.05 per thousand. Prestonsburg Utilities has the Contract with the United States Prison

VERIFICATION

I, Joe Hammond, of the Martin County Water District, hereby verify that the responses and exhibits attached hereto are true and correct to the best of my knowledge.

Joe Hammond

STATE OF KENTUCKY)

COUNTY OF MARTIN)

SUBSCRIBED, SWORN and ACKNOWLEDGED before me by Joe Hammond this 9th day of May, 2016.

My Commission Expires: 9-18-18

Lislie a Dempsie NOTARY PUBLIC, STATE AT LARGE

Exhibit #1 Current List of Work Orders

Martin County Water District 387 East Main St., Suite 140 Inez, KY 41224

(606) 298-3885

Service Orders Dated Between 4/1/2016 And 4/29/2016

Type of Work	Service Order Count	'Closed Order Count	Open Order Count	
Change Out	28	14	14	
Cheater Bar Investigation	2	1	1	
Complaints	6	3	3	
Leak	28	20	8	
Line Locate	2	1	1	
Meter Puli Non-Pay	16	10	6	
Meter Set	32	31	1	
MISC.	32	20	12	
Pull - Customer Request	21	16	5	
Pull - MCWD Request	2	2	0	
Read IN	13	11	2	
Read Out	13	11	2	
Replace shut off	4	2	2	
Re-Read	1	1	0	
Тар	5	1	4	
Verify Meter Number And Re	16	15	1	
Tota	ls: 221	159	62	

Exhibit #2 Number of Taps Requested

Martin County Water ∟istrict

387 East Main St., Suite 140 Inez, KY 41224 (606) 298-3885

Service Orders Dated Between 10/6/2015 And 4/29/2018

Type of Work	Service Order Gount	Closed Order Count	Open Order Count	
Тар	14	10	4	
	Totals: 14	10	4	

#Error

Exhibit #3 Number of Taps Request Pending

Martin County Water District 387 East Main St., Suite 140 Inez, KY 41224 (606) 298-3885

Service Orders Dated Between 10/6/2015 And 11/13/2015

Type of Work	Service Order Count	Clased Order Count	Open Order Count	many of the second seco
Тар	5	5	0	
	Totals: 5	5	0	

#Error

Exhibit #4 Number of Turn-offs

Martin County Water Listrict

387 East Main St., Suite 140 Inez, KY 41224 (606) 298-3885

Service Orders Dated Between 10/6/2015 And 4/29/2016

Type of Work	Service Order Count	Closed Order Count	Open Order Count	
Meter Pull Non-Pay	143	137	6	
Pull - Customer Request	117	111	6	
Pull - MCWD Request	3	3	0	
	Totals: 263	251	12	

Exhibit #5 Comparison of Electricity Cost

MARTIN COUNTY WATER DISTRICT

Purchased Power: 2015	Purchased Power	r: 2014	
Jan 2015	25,804.90	Jan 2014	30,264.06
Feb 2015	24,920.52	Feb 2014	21,212.23
March 2015	33,022.57	March 2014	20,753.67
April 2015	18,694.78	April 2014	13,010.71
May 2015	16,534.37	May 2014	22,947.20
June 2015	21,505.77	June 2014	22,637.44
July 2015	25,425.76	July 2014	27,219.42
Aug 2015	23,221.15	Aug 2014	33,597.27
Sept 2015	25,847.90	Sept 2014	32,347.95
Oct 2015	35,897.10	Oct 2014	29,940.51
Nov 2015	31,206.11	Nov 2014	29,764.02
Dec 2015	32,613.03	Dec 2014	24,272.98
	314,693.96		307,967.46

Exhibit #6 Water Loss and Leak Detection Program

Martin County Water District Water Loss Plan February 2016

Steps to follow:

- Read the master meters daily and at the same time each day. At a minimum, they should be read Monday through Friday. This will minimize water loss due to a large leak that can go undetected for a week or month.
- Divide the distribution system into zones or subsections where possible and calculate water loss for each zone. This will allow for the prioritizing of work based upon the severity of the problem in a particular zone.
- Utilize computer billing software to generate water loss reports for sections or zones as well as to generate an overall water loss report.
- Install bypass monitor meters as needed to isolate lines with potential leaks. A 5/8- x 3/4- inch meter will suffice for each 100 customer section of line.
- Install a 2 inch bypass monitor meter at water storage tanks to isolate sections of the line with potential leaks during the night (1:00 a.m. to 4:00 a.m.)
- Utilize pressure recordings to detect fluctuating pressures and abnormally low or high pressures in distribution systems lines.
- Test and change-out all meters according to Kentucky Public Service Commission (PSC) regulations. PSC regulations require residential meters to be tested and changed-out in 10-year intervals. Four-inch and larger meters are to be tested annually.

- It may be feasible to hire a part-time operator to utilize leak detection equipment to search for leaks. A portion of the distribution system could be covered each month.
- Identify sections of pipe in the distribution system with the most frequent line breaks. Budgeting for infrastructure replacement is imperative in any water utility.
- Having a main transmission line from the master meter to a water storage tank will reduce pressure fluctuations in the distribution system and result in fewer line breaks.
- Provide the necessary resources for manpower and equipment to properly maintain the distribution system appurtenances such as gate valves, pressure reducing valves, and hydrants.

COMPONENTS OF A WATER LOSS PREVENTION PLAN

How do the terms "water loss" and "weight gain" relate? Can it be that apathy, procrastination, or plain idleness might apply to both situations? Definitely, good intentions abound with either problem. No one wants to be overweight, just as no one who is responsible for the management and operation of a water utility wants to have excessive water loss. How do we attack these problems? In either case, we must identify the root of the problem, focus on a solution and stick with it! How many times have we heard the phrase, "If you fail to plan, you plan to fail." A good plan is the key to any long-term solution.

A person's physical and psychological make-up has a huge impact when attempting to solve the weight problem. Heredity affects us in many ways, but especially in regards to our ability to lose weight. What about the person who accepted the position of manager and soon learned that they had inherited an inadequately operated water system?

Age is another common factor in both problems. A water distribution system that was installed in the WPA days of the 1930's will most likely experience problems that newly installed water lines will not possess. The older that I get, the harder it is to keep the weight off! We can list other analogies such as our body shapes and sizes compared to the geographical terrain of our utilities and our distribution system sizes. However, let's get going with a proactive approach to the problem of water loss.

Accurate records are vital to any water loss prevention plan. How do we know the status of our water loss if we do not keep records? There is a water loss template that is available for download from the Kentucky Rural Water Association website

(<u>www.krwa.org</u>). This Excel spreadsheet, or a similar record keeping system, can be utilized in a preliminary water audit. The initial step in water loss prevention is the water loss calculation. Secondly we must locate and eliminate all water leaks. Sounds easy, doesn't it?

The following steps can be utilized to prevent or reduce water loss and should be incorporated into a water loss prevention plan:

- Read the master meters daily and at the same time each day. At a minimum, they should be read Monday through Friday. This will minimize water loss due to a large leak that can go undetected for a week or month.
- 2. Read all meters in the distribution system within a 3-to 5-day window. When the meters are read over a

- 2-week period, this will cause fluctuations of monthly water loss numbers. However, these numbers will average out over a year's period of time.
- Divide the distribution system into zones or subsections where possible and calculate water loss for each zone. This will allow for the prioritizing of work based upon the severity of the problem in a particular zone.
- Utilize computer billing software to generate water loss reports for sections or zones as well as to generate an overall water loss report.
- Install bypass monitor meters as needed to isolate lines with potential leaks. A 5/8- x 3/4-inch meter will suffice for each 100-customer section of line.
- Install a 2-inch bypass monitor meter at water storage tanks to isolate sections of the line with potential leaks during the night (1:00 a.m. to 4:00 a.m.)
- Utilize pressure recordings to detect fluctuating pressures and abnormally low or high pressures in distribution system lines.
- Test and change-out all meters according to Kentucky Public Service Commission (PSC) regulations. PSC regulations require residential meters to be tested and changed-out in 10-year intervals. Four-inch and larger meters are to be tested annually.
- It may be feasible to hire a part-time operator to utilize leak detection equipment to search for leaks. A portion of the distribution system could be covered each month.
- Identify sections of pipe in the distribution system with the most frequent line breaks. Budgeting for infrastructure replacement is imperative in any water utility.
- Having a main transmission line from the master meter to a water storage tank will reduce pressure fluctuations in the distribution system and result in fewer line breaks.
- 12. Provide the necessary resources for manpower and equipment to properly maintain the distribution system appurtenances such as gate valves, pressure reducing valves, and hydrants.

Today's advanced technology can certainly enhance our water loss prevention plan. Computers not only utilize software for spreadsheets to calculate water loss expediently, but can be used in a variety of ways to identify areas of the distribution system with potential leaks. Both master meters and customer meters can be read by satellites or other automated meter reading mechanisms.

Telemetry/SCADA systems operated with computers can produce trend charts for water flows, water pressures, and water levels in storage tanks. This kind of data is valuable in determining where leaks are or are not prevalent. Computers analyze hydraulic data to determine if theoretical and actual water flows and water pressures in the distribution system match. Computerized maps with GPS and GIS data are beneficial when used properly. A water utility's budget is the major limiting factor as to why technology is not used more frequently.

By industry standards, more than 15 percent water loss in a rural system in unacceptable. Probably, no one realizes this more than the managers of water districts, water associations, and investor-owned utilities under the jurisdiction of the Kentucky Public Service Commission. Just as we should be concerned with our health due to being overweight, the PSC is concerned with the financial health and well-being of water utilities under their jurisdiction in Kentucky. PSC inspectors routinely discuss water loss during their inspections. When a water system exceeds 15 percent water loss on their annual report to the PSC, a deficiency is issued. Numerous water systems' response to the PSC's Deficiency Tracking Reports (DTR) has been deemed unacceptable by PSC. A common request from PSC to the water system with a deficiency due to water loss is for a water loss control plan. A good water loss control plan should include the above-mentioned components with a time frame to implement the improvements and follow-up evaluations to measure the success of the plan.

Whether we are weighing in or wading in, we should always do so with a goal in mind. We cannot continue to ignore our problem and hope it resolves itself. Just as there are various diets to control an individual's weight, there are various methods for controlling water loss.

Let's start implementing all of our good intentions!

Exhibit #7 Updated Capital Improvement Plan



Preliminary Project Cost Estimate

Project: Water Treatment Plant Improvements

Date:

Job No.:

Revised: 03/08/16

Est. By:

BKL

panel.	latings.	neviseu.	03/00/10	usa by.	DICE	
ITEM	SUMMARY OF:	QUANTITY	,			TOTAL
NO.		NO. OF UNITS	UNIT MEAS.	COST PER UNIT		COST
_1	Electrical System Improvements	1	LS	\$ 280,000.00	s	280,000.00
2	Mechanical Renovations (Operations Building	1	LS	S 196,000,00	<u>\$</u>	196,000.00
3	Structural Renovations (Operations Building)	1	LS	\$ 216,000.00	\$	216,000.00
4	Architectural Renovations (Operations Building)	1	LS	\$ 425,000.00	s	425,000.00
5	Process Improvements and Expansion	1	LS	\$ 3,430,000.00		3,430,000.00
	Subtota	1			S	4,547,000.00
	Contractors OH&P (10%)			\$	454,700.00
•	Subtota					5,001,7 <u>00.00</u>
Mo	bilization, Bonds, and General Conditions (10%	3			<u> </u>	500,170.00
	Subtota				\$	5,501,870.00
	Contingency @ 10%	6			s	550,187.00
	Tota	ß -			\$	6,052,057.00
	TOTAL AMOUNT - CONSTRU	CTION COST			\$	6,052,057.00
		RING DESIGN	6.64%	·	\$	402,150,00
-	RESIDEN' LEGAL AND ADM	r inspection inistration	3.31%		\$	200,600.00
	TOTAL ESTIMATED PROJECT	T COST		<u> </u>	\$	6.654.807.00




Exhibit #8
Pending Disconnects

		1.0	.00 D	04 29		T-4-I Dua
Text44	>	*		i	90 Days	Total Due
KY	41224	\$57.33	1	\$75,91	\$0.00	\$231.92
KY	41224	\$57,33	•		\$115.86	\$248.43
KY	41267	\$86,31	\$45.21	\$9.63	\$0.00	\$141.15
KY	41267	\$57.33	;	!	\$0.00	\$184 .16
KY	-41231	\$34.20	\$0,00	\$0.00	\$325.40	\$359.60
KY	-41267	\$102.87	\$105.94			\$358.96
KY	-41224	\$318.17	\$166.66	\$166.66	\$834.34	\$1,485.83
KY	-41267	\$157.38	\$105.94	\$23.76	\$0.00	\$287.08
KY	41267	\$57.33	\$37.62	\$0.54	\$0.00	\$95.49
KY	41224	\$64.23	\$45.21	\$104.92	\$0.00	\$214.36
KY	-41224	\$85.62	\$57.97	\$37.62	\$27.70	\$208.91
KY	41231	\$61.80	\$0.00	\$0.00	\$206.73	\$268.53
KY	-41231	\$57.33	\$30.03	\$4.60	\$0.00	\$91:96
KY	41231	\$52,61	\$0.00	\$0.00	\$171.04	\$223.65
KY	41231	\$71.82	\$37.62	\$3.78	\$0.00	\$113:22
KY	41231	\$57.33	\$45.21	\$6.93	\$0.00	\$109.47
KY	41231	\$57.33	\$30.03	\$2.06	\$0.00	\$89.42
KY	41231	\$100.11	\$67.98	\$0.31	\$0.00	\$168.40
ΚY	41224	\$79,41	\$75.57	\$37.62	\$0.00	\$192.60
KY	-41250	\$30.03	\$30.03	\$45.21	\$231.66	\$336.93
KY	-41250	\$30.03	\$30.03	\$10.15	\$0.00	\$70.21
KY	-41250	\$37.62	\$37.62	\$5.49	\$0.00	\$80.73
KY	-41250	\$67.98	\$189.44	\$30,03	\$302.74	\$590.19
Ку	-41250	\$0.00	\$0.00	\$0.00	\$229.46	\$229:46
KY	-41250	\$0.00	\$0.00	\$0.00	\$241.55	\$241,55
KY	-41250	\$0.00	\$0.00	\$0.00	\$67.95	\$67.95
KY	-41250	\$0.00	\$0.00	\$59.61	\$109.31	\$168.92
KY	-41224	\$0.00	\$0.00	\$74.03	\$0,00	\$74.03
KY	41224	\$30.03	\$30,03	\$30.03	\$0.00	\$90.09
KY	-41250	\$57.33	· · · · · · · · · · · · · · · · · · ·	3	\$39.29	\$164:27
KY	-41267	\$262.97	1	\$0,00	\$163.66	\$512.93
KY	-41267	\$93.21	\$52.80	\$37.62	\$8.15	\$191.78
KY	41231	\$64.23	\$30.03	\$5,42	\$0.00	\$99.68
KY	-41231	\$100.11	\$0.00	\$0,00	į.	1
KY	41231	\$71.13	\$52.80	\$23,66	\$134.86	\$282.45
KY "	-41231	\$149.79	\$90.75	\$50,97	\$0.00	\$291.51
Ку	-41231	\$57.33	\$30.03	\$20.06	\$0,00	/\$107.42
Ку	41514	\$89.03	\$37.62	\$30.03	\$3,46	\$160.14
KY	-41514	\$64.23	s. \$30.03	\$30.03	\$4.06	\$128.35
KY	41203	\$115.29	\$83.16	\$9.78	\$0.00	\$208.23
KY	41203	\$61.80	\$0 .00	\$0.00	\$157,14	\$218.94
ку	41203	\$57.33	\$30.03	\$8.06	\$39.96	\$135.38
KY	-41203	\$64.23	\$52.80	\$13.86	\$0.00	\$130.89
KY	41231	\$57.33	\$30.03	\$30.03	\$0,00	\$117,39
KY	41203	\$57.33	\$37.62	\$23.16	\$0.00	\$118.11

				U4 Z3	2010	
KY	41203	\$130.47	\$83.16	\$67.98	\$173.86	<u>\$4</u> 55.47
KY	41203	\$93,90	\$52.80	\$27,18	\$29.65	\$203.53
KY	-41203	\$57.33	\$45.21	\$7.59	\$0.00	\$110.13
KY	41567	\$57.33	\$37.62	\$10.60	\$0.00	\$105.55
Ку	-41224	\$129.09	\$45.21	\$67.98	\$153.23	\$395.51
KY	-41224	\$78.72	\$30.03	\$19.29	\$0.00	\$128.04
ΚY	-41224	\$64.92	\$30.03	\$46,60	\$126.18	\$267.73
KY	41224	\$71.82	\$37.62	\$12.01	\$0.00	\$121.45
KY	-41224	\$57.33 [‡]	\$0.00	\$0.00	\$62.98	\$120.31
Ку	-41224	\$78.72 _\	\$37.62	\$45.21	\$6.70	\$168.25
KY	41224	\$41.10	\$0.00	\$2.13	\$224.58	\$267.81
KY	41224	\$57.33	\$30.03	\$3.42	\$0.00	\$90.78
KY	41224	\$115.29	\$52.80	\$39.12	\$0.00	\$207.21
KY	41224	\$100.11	\$30.03	\$11.27	\$0.00	\$141.41
KY	-41224	\$131.85	\$143,89	\$8.36	\$0,00	\$284.10
KY	41224	\$107.62	\$0.00	\$0.70	\$0.00	\$108.32
KY	41224	\$406.10	\$401.30	\$6.89	\$0.00	\$814,29
KΥ	-41224	\$79.41	\$37.62	\$40.63	\$0. 0 0	\$157.66
KY	-41224	\$108.39	\$83.16	\$68.42	\$0,00	\$259.97
Ку	-41230	\$64.23	\$52.80	\$30.03	\$115.32	\$262,38
KY	41224	\$57.33	\$30.03	\$2.73	\$0,00	\$90.09
KY	41224]	\$41.10	\$0 .00	\$0.00	\$132,87	\$173.97
KY	41224]	\$57.33	\$48.62	\$30.03	\$0.00	\$135.98
KY	-41224	\$172.52	\$52,80	\$30.03	\$239.38	\$494.73
KY	-41224	\$115.98	\$52.80	\$12.82	\$0.00	\$181.60
KY	-41224	\$93.21	\$52.80	\$37.62	\$21.54	\$205.17
KY	-41224	\$57.33	\$190.63	\$9.33	\$0.00	\$257.29
KY	-41224	\$78.72	\$52.80	\$4.11	\$0.00	\$135.63
Ку	-41224	\$86.31	\$30.03	\$83.16	\$0.00	\$199.50
KY	-41224	\$54,90	\$0.00	\$0.00	\$96.31	\$151.21
KY	-41224	\$64.92	\$30.03	\$32.28	\$0.49	\$127.72
KY	41230	\$71.82	\$0.00	\$44,41	\$87.04	
KY	41224-09	\$100,80	\$52.80	\$14.29	j	g Driggaran and
KY	41224	\$93.90	\$67.98		\$285.51	\$477.42
KY	41224	\$130,47	\$75.57			
KY	41224	\$79,41	\$37.62	\$45.21	\$91.28	, , , , , , , , , , , , , , , , , , , ,
KY	-41224	\$71.82	\$30.03	\$45.21	\$193.18	\$340.24
Ку	-41224	\$100.11	\$37.62	\$52.80	\$455.23	\$645.76
ΚY	41224	\$172.5 6	\$83.16	. \$8.94	\$0.00	
KY	-41224	\$107.70	\$75.57	\$10.39	\$0.00	\$193.66
KY	-41224	\$78 .72	\$30.03		i	1
KY	-41224	\$79,41	\$37.62	\$5.21		<u> </u>
KY	-41214	\$86.31	\$60.39	\$15.99		!
KY	-41224	\$95.28	\$0.00		1	
KY	-41214	\$79.41	\$60.39	f (pre.) per	f 1 7 7 7	-
KY	-41214	\$163.91	\$0,00	\$0.00	\$200,00	\$363.91

				04 29 20	10	-
KY	41214	\$71.82 _;	\$30.03 أ _.	\$15.42	\$0.00	\$117.27
KY	-41214	\$34.20	\$0.00	\$0.00	\$1.00	\$35.20
KY	-41224	\$41.10	\$0.00 [‡]	\$0.00	\$68.67	\$109.77
KY	41214	\$78.03	\$30.03	\$0.06	\$0.00	\$108.12
Ку	-41214	\$57.33	\$37.62	\$2.73	\$0.00	\$97.68
KY	-41224	\$71.82	\$52.80	\$11.14	\$0.00	\$135.76
KY	41224	\$57.33	\$30.03	\$37.62	\$25.30	\$150.28
KY	41224]	\$64.23	\$15.97	\$0.00	\$16,20	\$96.40
KY	-41224	\$57.33	\$30.03	\$0.03	\$0.00	\$87.39
KY	41224	\$27,30	\$0.00	\$0.00	\$57.31	\$84.61
KY	-41230	\$57.33	\$0.00	\$0.00	\$895.27	\$952.60
Ку	-41224	\$34.20	\$7.33	\$37.62	\$74.60	\$153.75
Ку	-41230	\$108.39	\$60.39	\$4.80	\$0.00	\$173.58
KY	41230	\$100.80	\$45.21	\$52.80	\$303.05	\$501.86
KY	41230	\$122.88	\$30.03	\$90.75	\$137.92	\$381.58
KY	-41230	\$114.60	\$52.80	\$83.16	\$54.87	\$305.43
KY	-41230 i	\$86.31	\$37.62	\$47.25	\$0.00	\$171.18
KY	41224	\$57.33	\$30,03	\$2.73	\$0.00	\$90.09
KY	41224]	\$100.80	\$52.80	\$2.29	\$0.00	\$155.89
KY	-41224	\$174.64	\$107.30	\$53.30	\$0.00	\$335.24
KY	-41224	\$64.92	\$30.03	\$3,03	\$0.00	\$97.98
Ку	41224	\$61.80	\$97.11	\$124.80	\$0.00	\$283.71
KY	41224	\$57.33	\$30.03	\$0.27	\$0.00	\$87.63
KY	;41224 ;	\$100.80	\$60.39	\$25.57	\$0.00	\$186.76
KY	41224	\$27.30	\$0.00	\$0.00	\$129.63	\$156.93
KY	41224	\$497.60	\$166.66	\$227.39	\$2,191,41	\$3,083.06
ΚY	41224	\$57.33	\$30.03	\$30.03	\$30.03	\$147.42
Ку	-41262	\$78.72	\$37.62	\$2.11	\$0.00	<u>\$118.45</u>
KY	41262	\$57.33	\$30.03	\$5.63	\$0.00	\$92.99
ΚY	41262	\$64.23	\$45,21	\$23,22	\$0.00	\$132.66
KY	-41262	\$54.90	\$0.00	\$0.00	\$146.69	\$201.59
ΚY	-41262	\$64.92	\$30.03	\$3.42	\$0.00	\$98.37
KY	41224	\$54.90	\$0.00	\$0.00	\$215.66	\$270.56
KY	41224	\$64. 2 3	\$37.62	\$37.62	\$199.73	\$339.20
KΥ	41224	\$209.15	\$121,12	\$16.49	\$0.00	\$346.76
Κ̈́Υ	-41224	\$71.82	\$45.21	\$3,08	\$0.00	\$120.11
KY	41262	\$64.23	\$30.03	\$30.03	\$38.06	\$162.35
KY	41262	\$64.23	\$30.03	\$29.61	\$0.00	\$123.87
Ку	-41262	\$100.80	\$45.21 į	\$0,21	\$0.00	\$146.22
KY	-41262	\$57.33	\$30.03	\$0.03	\$0,00	\$87.39
KY	41262	\$71.82	\$37.62	\$2.89	\$0.00	\$112 <u>.3</u> 3
KY	-41262	\$71.82	\$30.03	\$31.98	\$0.00	\$133.83
KY	41262	\$100.11	\$52.80	\$2.80	\$0.00	\$155.71
KY	41224	\$78.72	\$121.12	\$75.57	\$76.88	\$352.29
Ку	41262	\$57.33	\$30.03	\$5.67	\$0.00	\$93.03
KY	41267	\$60.67	\$31.78	\$31,78	\$8,414.59	\$8,538.82

137 CUSTOMER \$11,488.65 \$6,278.54 \$3,521.94 \$19,996.57 \$41,285.70

Exhibit #9 Business Manager's Job Duties

Position Responsibilities

Business Mgr.

- Responsible for Financial and legal issues
- Policy enforcement
- Safety Training and reviews
- Handle PSC issues (forms, regulations, etc.)
- Control legal documents and correspondence
- Maintain personnel records
- Develop Inventory controls
- Develop purchase order protocol and controls
- Solid waste (garbage) accounts?
- Budget controls
- Quotes and bids as requested by Operations Mgr.
- Develop training programs
- Maintain office systems (hardware and software)
- Continuous system upgrades and improvements
- Equipment maintenance (office related equipment, etc.)
- Provide a safe and clean working environment
- Interface with contractors
- Report to Board

Exhibit #10 Written Complaints

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER



	Time Started		Work Complete		
Loc#	and interface to the same of t		Master Meter #		
Dat 1/29/2	2013	Account#	SEQ # 479		
Name: K	elly Maynard		Phone #		
Address:	and \$4° as a \$4 base of more of the control of the		Carrier Land 16000 and		
	nez, KY 41224				
Ţ	HICKETY FORK				
Type of Wo	rk: Complaints				
Material Us	ed:	((3v9		
Customer L	ine Inspection		5-/		
≱ -	no water for three days	1 1			
Cı	urrent System Information:	A Arrivan Wales and a collection of a security with very security or an extension of the security of the secur	New Information:		
Meter#1:	29934541		Meter # 1:		
Meter#2: (Radio		Meter# 2: Radio		
MXU #:	<u> </u>		MXU #:		
Current Rea	ading 12/20/2012 362		Current Reading 0		
Type of Met	ter: Badger		Type of Meter:		
Year MFG:	2004		Year MFG:		
GPS - Long	itude		GPS - Latitude		
Employee S	signature(s): \sum $$		Date Completed 1-29-13		

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Employee Signature(s):

130100197



Work Complete Time Started Master Meter # Loc# Date 1/28/2013 Account # SEQ # 123 Mark & Donna Howard Phone # Name: Address: Louisa, Ky 41230 Location: Blankenship Hlw Rd Type of Work: Complaints Material Used: Customer Line Inspection |) | 00 Comments: Air in lines; says everyone up hollow has a lot of air in lines too New Information: **Current System Information:** Meter#1: Meter#1: 29935136 Meter # 2: Radio Meter # 2: Radio 29935136 MXU#: MXU #: Current Reading 0 Current Reading 12/20/2012 112 Type of Meter: Type of Meter: Badger 2004 Year MFG: Year MFG: GPS - Longitude GPS - Latitude Date Completed 1-29

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

130100132

WO#



Work Complete Time Started Loc# Master Meter # Date 1/18/2013 SEQ# Account # Fioretta Coleman Name: Phone # Address: Location: Newberry Ln Type of Work: Complaints Material Used: Customer Line Inspection Comments: pot holes from previous work done by MCWD g a g and a gradual and a grad **Current System Information: New Information:** Meter # 1: Meter # 1: Meter # 2: Radio Meter # 2: Radio MXU#: MXU#: we are a second consequence of the Current Reading 0 Current Reading 0 Type of Meter: Type of Meter: Year MFG: Year MFG: GPS - Latitude GPS - Longitude

Employee Signature(s): <u>5</u>

Date Completed [-22-3]

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 121200166



Time Started		***********************	Work Complete		
Loc#	AN ANNA DE LA CASA DEL CASA DE LA CASA DEL CASA DE LA C	Master N	Master Meter #		
Dat 12/28/201	2	Account #	SEQ # 42		
	an Jude		Phone #		
Address: P.O. 8	Зох		Employee Kyle Sammons		
Lovel	y, KY 41231	and the second s			
Location E Main St, Inez, last house past pawn shop, white w/green shutters, next to empty lot					
	: Main St				
Type of Work:	Complaints				
Material Used:			(cice)		
Customer Line I	nspection				
Comments ext	remely low water pressu	re High Dress	are at Box butrealy low from		
	nt System Information:	V	New Information:		
Meter # 1:	70616368		Meter # 1:		
Meter#2: Radio	70616368		Meter # 2: Radio		
MXU#:	14440339	and the second s	MXU #:		
Current Reading	12/20/2012 3	manadharado e e e estado e que democramore	Current Reading 0		
Type of Meter:			Type of Meter:		
Year MFG:			Year MFG:		
GPS - Longitude		**************************************	GPS - Latitude		
Employee Signa	iture(s): \(\)		Date Completed 1-17-13		

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO # .

121200072



Time Started Work Complete Yes Master Meter # Loc# Dat 12/18/2012 Account # SEQ # 256 William Maynard Name: Phone # Employee Josh Williams Address: Lovely, KY 41231 Location 2nd driveway before Big Branch, Maynard Flat, white trailer w/black shutters Connt. Type of Work: Complaints Material Used: Looked good Customer Line Inspection Comments needs more gravel where contractors put in line around driveway **Current System Information: New Information:** Meter # 1: Meter # 1: Meter # 2: Rádio Meter # 2: Radio MXU#: MXU #: Current Reading 0 Current Reading 0 Type of Meter: Type of Meter: Year MFG: Year MFG: GPS - Longitude GPS - Latitude **Date Completed** Employee Signature(s):

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

130100111



Time Started Work Complete Master Meter # Date 1/10/2013 Account # SEQ # 175 BARBARA MARCUM Name: Phone # (Address: PO BOX , KY 41203 BEAUTY Big Elk Crk up Big Elk Creek road (from rt 40) before Gospel Light, red brick house on left across Location: from big black barn. Type of Work: Complaints Material Used: Customer Line Inspection 55-Paul ATTE- Paul STATION Comments: complaints of too much pressure New Information: **Current System Information:** 29541976 Meter#1: Meter#1: ______ Meter # 2: Radio Meter # 2: Radio MXU#: MXU#: Current Reading 12/20/2012 503 Current Reading 0 Type of Meter: ______ Type of Meter: Badger Year MFG: 2004 Year MFG:

Employee Signature(s) 15-15-65-71

GPS - Longitude 0

Date Completed | - //- /3

GPS - Latitude

387 East Main St., Suite 140 Inez, KY 41224



WORK ORDER

	WO#	13020010	0
Tir	ne Started	Work	Complete
Loc#	(Master Meter	
Date 2/6/2013		Account#	SEQ # 437
Name: MELVI	N HOWARD	de die g. man mare de Miller ook group – "gr g skondelsbeker gelande die die be	Phone #
Address: P.O.BO	ox.		
INEZ	, KY 41224	and the state of t	Andrew 4
Location: Eg	den Ln, ON RIGHT ACROS	S FROM PUMP STATI	ON, grey/white single-white
			Andrews and the second state of the second s
645-S	AW MILL RD		
Type of Work: C	omplaints	(9)	
Material Used:	/		
Customer Line Ir		,	
Comments: box	is too deep in the box to rea	ach, customer would lik	e it fixed put a bil riser
Curren	t System Information:	general and the second	New Information:
Meter#1:	98343293	M	eter # 1:
Meter#2: Radio		M6	eter#2: Radio
MXU #:	ور المراجع الم	M	KU #:
Current Reading	1/20/2013 708	Cu	rrent Reading 0
Type of Meter:	Badger	Ту	pe of Meter:
Year MFG:	1998	Ye	ear MFG:
GPS - Longitude	0.	G	PS - Latitude 0
Employee Signat	cure(s): J.S.	Attacher a poor thyreig (magnetic property)	Date Completed 2 - 11 - 13

Martin County Water District 387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 130200095



Т	ime Started	· · · ·	Work Complete	
Loc#	,	Master	Meter #	
Date 2/6/2013		Account #	SEQ:	# 199
Name: ROBE	ERT & KIMBERLY SMITH		Phone #	
Address: P.O. I	вох			
INEZ	, KY 41224			
Location:				and according to the second of
COLE	DWATER RD.		(2)	and the second s
			7	The second description of the second
Material Used:				. se
Customer Line	Inspection			CESS W.
Comments: ext	tremely low pressure	195 about	44 pound's	At box.
	nt System Information:	and the second s	•	nformation:
Meter#1:	19447503		Meter#1:	و د ومساور میبان اسانیسسسسسسس
Meter#2: Radio	1	4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.	Meter#2: Radio	The same was a supplemental and the same and
MXU#:		************	MXU #:	And the state of t
Current Reading	g 1/20/2013 852	in the second control of the second control of the second	Current Reading	0
Type of Meter:	Badger		Type of Meter:	
Year MFG:	2003		Year MFG:	aalestiin käyteenin yuu – säjä (v. 1900-julkijustin muunin aan – diin turus vyst must 1900
GPS - Longitud	e 0 [!]		GPS - Latitude 0	annesses a proposed a size waters and see the see
Employee Signa	ature(s): TS	AND THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUM	Date Completed	2-7-13

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

130100235

Tim	ne Started		Work Complete	е			
Loc#		Master	Meter#	- manufacture commendation of many			
Dat 1/31/2013	and the second of the second o	Account #	- :	SEQ# 461			
Name: Sue Du	tton	annoque, qu'entre (\$200 millionne, presidente		Phone #			
Address:	omahawk Rd.	and the second s	manga	Employee Josh Williams			
TOMAH	AWK , KY 41262	an yek-mani v m stark a an					
Location:	Location: **omahawk Rd, end of line on Rt 40, single-wide on right						
	E 40 WEST	(The second desirables in second the Campbeller with			
Type of Work: Co	ompiaints) ovel)				
Material Used:		- Co	/ /				
Customer Line Ins	spection 30/bs	/ search	iter bit.	showed 7516s			
Comments: comp	plaints of extremely low pres	CLIFA					
Gurrent	System Information:		agi, Balifin Balifin an restriction of the State of the S	New Information:			
Meter # 1:	97094028		Meter#1:				
Meter # 2: Radio			Meter#2: R	adio			
MXU#:			MXU#:	Antibertugger or open allocated antibergalists of the open parts and a commence of the reference or comment to			
Current Reading	1/20/2013 444		Current Rea	ding 0			
Type of Meter:	Badger		Type of Met	er:			
Year MFG:	1997		Year MFG:				
GPS - Longitude	0	ranjaganis 40 4 500	GPS - Latitu	de <u>0</u>			
Employee Signatu	re(s): .))(Z	Date C	Completed 2-1-13			

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 130300126



	Time Started		rk Complete		
Loc#			Master Meter #		
Dat <u>3/19</u>	9/2013			‡ <u>16</u>	
Name:	DARRELL HARMON		Phone# (
Address:	Big Branch			Josh Williams	
	LOVELY , KY 4123	1			
Location	3ig Br, 1/2 mile up Big B	Br, 3rd bridge on right, white	house w green shutte	ers.	
	DIC BRANCU			Annual of the second se	
	BIG BRANCH	Done		and an appropriately plants of streams at a statement to	
Type of W	/ork: Complaints	Done			
Material U	Jsed:				
	Line Inspection				
	s has had no water since Fri	iday.	THE STATE OF THE S		
	Current System Information	1:		formation:	
Meter#1:	74846443	M	leter#1:		
Meter#2:	Radio 74846443	_·M	eter#2: Radio	and the second section of the section of the second section of the section of the second section of the section of th	
MXU #:	14992020	M	XU #:		
	eading 3/15/2013 0		urrent Reading		
Type of Me	eter:	т	ype of Meter:		
Year MFG		Y	ear MFG:		
GPS - Lon	gitude	G	PS - Latitude		
Employee	Signature(s):		. Date Completed	3-19-13	

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO # 130300210



Time Started	Work Complete	en u trade lander to deligation prince plane apply approximation of his new
Loc#	Master Meter #	e e e e e e e e e e e e e e e e e e e
Date 3/27/2013	Account #	SEQ# 369
Name: Darlene Crum		Phone #
Address:		
Inez, Ky 41224	anis and a super-section with the section of the section with the section of the	ž.
		ight. Greyish trailer next to old store.
ohnson Btm	k restriction of the second of	The second of th
Type of Work: Complaints		
•	ind in the state of the state o	and the second s
/laterial Used:	• • • of managers or page 1 (a) of a supply of the supply	A to have the auditorian elementary of K. M. M. University. In . Willy 17 West.
Customer Line Inspection	. We will be seen to see the seen proper recent	o na
Comments: Redo TAP		
1 CTL U want to be followed as the second		
Current System Information:		New Information:
Neter#1:	Meter # 1:	Branchine and the control of the con
Neter#2: Radio	Meter # 2: Rad	dlo
1XU#:	MXU#:	. The second sec
Current Reading 0	Current Read	ling 0
ype of Meter:		
	Type of Meter	r:
/ear MFG:	Type of Meter	C
'ear MFG:	Year MFG:	
rear MFG:	Year MFG:	

Martin County Water District 387 East Main St., Suite 140

Inez, KY 41224

WORK ORDER

	WO #	140500167	• • • • • • • • • • • • • • • • • • •
Ti	me Started	Work (Complete
Loc#		Master Meter #	
Date <u>5/22/2014</u>	- AA	Account #	SEQ# 227
Name: Lorett	a Moore		Phone #
Address: P	igeon Roost Rd		
Pilgrin	n, Ky 41250		
	igeon Roost Rd. 2nd house		
Р	igeon Roost Rd		annessenting to proportion to the second
Type of Work: C	Complaints	- (Done)	
Material Used:			
Customer Line II	nspection		
			e made / Put grave) in hole
Curren	t System Information:		New Information:
Meter # 1:	97176588	Mete	er#1:
Meter # 2: Radio	97176588	Mete	er#2: Radio
MXU #:		IXIXI	
Current Reading	4/20/2014 311	Curr	rent Reading 0
Type of Meter:	Badger		e of Meter:
Year MFG:	1997	Year	r MFG:
GPS - Longitude		GPS	S - Latitude
Employee Signat	rure(s): TH, GS, J	5	Date Completed 5-23-14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

		WO#	140500166		
	Time Started	ng Pig Milang Salika niy man nara-birananan nagbur	Work Complete		
Loc#			64	And the state of t	······································
Date 5/2	2/2014	Acc	ount#	SEQ# 310	
Name:	ROBERT FRALEY	·	Pho	one#) "Whitehproblekin s.), arm
Address:	Halls Br				
	TOMAHAWK , KY	41262	7,000,000,000,000,000,000,000,000,000,0		
Location:	Halls Br				
					
	HALL BRANCH ROAD	•			Page and the second sec
Type of V	Vork: Complaints			aya kangan sa kila ay	
Material (Jsed:				
	Line Inspection		(
Comment	ts: very low water pressure	lesk	on mcw D & xx	t box	
	Current System Informati	on:	and the state of t	New Information:	
Meter#1	96130886		Meter # 1:		
Meter # 2:	Radio	······································	Meter#2: Radio		
MXU #:	And the second s		MXU #:		
Current R	eading 4/20/2014 1219	·	Current Reading	g <u> </u>	
Type of M	eter: Badger	· · · · · · · · · · · · · · · · · · ·	Type of Meter:	\$.	
Year MFG	s: 1996		Year MFG:		
GPS - Lor	ngitude 0		GPS - Latitude	0	

Date Completed 5-22

Employee Signature(s):

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO #	140500161	File and American Control of the Con
Time Started		Work	Complete
Loc#			
Date 5/22/2014		Account #	
Name: Recy	cling Solutions Tech.		Phone #
Address: PO	Pov		
Allen	KV 41601		
Location: Right	side, go thru gate, meter se		pors, in front of boiler
	n County Coal Hill		
Type of Work:	Complaints		
	Inspection		
	remely low pressure, Paul Ai		3
Curre	nt System Information:	and the second s	New Information:
Meter # 1:	70025360	Met	er#1:
Meter#2: Radio	70025360	Met	er#2: Radio
MXU #:	14640449	MXU	J #:
Current Reading	4/20/2014 1293		rent Reading0
Type of Meter:			e of Meter:
Year MFG:		Yea	r MFG:
GPS - Longitude	·	GPS	S - Latitude
Employee Signa	iture(s): ΛV		Date Completed 5-22-14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	AAC	7405	UU154	
	Time Started		Work Complete	
Loc#			Meter#	
Date 5/21/	2014	Account #	SE	Q# <u>381</u>
Name: J	ames McGinnis			
Address:	McGinnis Br			
Ī	Debord, Ky 41214			
Location: <u>C</u>	Grey doublewide before Walke			
	Aiddlefork			
Type of Wo	ork: Complaints			
Material Us				
Customer L	ine Inspection			
Comments	: low pressure / /oo	BIRE	αΧ	
C	urrent System Information:	Mins & Activities & State of the State of th		Information:
vleter#1:	29541627		Meter#1:	,
Meter#2: i	Radio		Meter#2: Radio	
/IXU #:			MXU #:	
Current Rea	ading 4/20/2014 221	***************************************	Current Reading	0
Type of Met	ter: Badger		Type of Meter:	(
ear MFG:	2004		Year MFG:	
3PS - Long	itude 0		GPS - Latitude 0	
Employee S	Signature(s): \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	5/65	Date Complete	a 5-21.14

Martin County Water District 387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 140500099

	Time Started	17-148-144-1-1	Work Complete
Loc#			Meter#
Dat 5/14	1/2014	Account#	SEQ# 372
Name:	Carey Dindai	W W 100	
Address:	Davalla Pd		Employee Jason W
	Debord , Ky 41214	and the state of t	**************************************
Location		ella Rd	
	Davella Rd	A STATE OF THE STA	
Type of V	Vork: Complaints		
Material l			
Custome	r Line Inspection		
	ts low pressure since last nigh	nt	
	Current System Information:		New Information:
Meter#1	: 19408276		Meter # 1:
Meter#2		,	Meter # 2: Radi
MXU#:			MXU #:
Current R	leading 4/20/2014 1234	er Berkhallerdau er i Françoiskoski gan vestellerist	Current Reading 0
Type of M	leter: Badger	-	Type of Meter:
Year MF0	S: <u>2003</u>		Year MFG:
GPS - Lo	ngitude 0		GPS - Latitude 0
Employee	Signature(s):		Date Completed 5-15-14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 140500105

	Time Started	V	Work Complete			
Loc#	The state of the s		eter#			
Dat 5/14	/2014		SEQ # 442			
Name:	Recycling Solutions Tech.		Phone #			
Address:	PO Box		Employee Jason W.			
	Allen, KY 41601		e Translation and the state of			
Location			age doors, in front of boiler			
		- '				
Type of W	/ork: Complaints	the specific feeling for the specific s				
Material U	Jsed					
Customer	Line Inspection					
Comment						
		مى سەرىكىنىڭ ھەلەر ئىنىڭ يەرىكىنىڭ ئالىرىكىنىڭ ئالىرىكىنىڭ ئىلىنىڭ ئالىرىكىنىڭ ئالىرىكىنىڭ ئالىرىكىنىڭ ئالىرىك ئالىرىكىنىڭ ئالىرىكىنىڭ ئالىرىكىنىڭ ئالىرىكىنىڭ ئالىرىكىنىڭ ئالىرىكىنىڭ ئالىرىكىنىڭ ئالىرىكىنىڭ ئالىرىكىنىڭ ئا				
Meter # 1:	70025360	and the second s	Meter # 1:			
Meter # 2:	Radi 70025360		Meter # 2: Radi			
MXU#:	14640449	, and the same	MXU#:			
Current R	ading 4/20/2014 1293	· · · · · · · · · · · · · · · · · · ·	Current Reading 0			
Type of M	eter:	Melitid dik , rinkunangkan philim serenta Militi.	Type of Meter:			
Year MFG	f		Year MFG:			
GPS - Lon	gitude	· ·	GPS - Latitude			
Employee	Signature(s):		Date Completed 5-15-14			

Martin County Water District 387 East Main St., Sulte 140 Inez, KY 41224

WORK ORDER

	WO#	140500076	n natural desiration de consideration
	Time Started	Work (Complete
Loc# Ma			
Date <u>5/7/</u>	2014	Account#	
Name:	Wanda Jude		Phone #
Address:	Pigeon Roost Rd		
	Pilgrim, Ky 41250		
Location:			an/brown double-wide.
	ligeon Roost Rd	WAR AND A WAR AN	
Type of V	Vork: Complaints		
	Jsed:r Line Inspection	1 + 112 >1/4	od)
Commen	ts: milky water, lines need flushed		
	Current System Information:		New Information:
Meter#1	67012626	Mete	er#1:
Meter#2	Radio 67012626	Mete	er#2: Radio
MXU#:	· · · · · · · · · · · · · · · · · · ·	MXL	J#:
Current R	eading 4/20/2014 362	Curr	ent Reading 0
Type of M	leter: Sensus	Туре	of Meter:
Year MFG	3: 2006	Yea	MFG:
GPS - Loi	ngitude	GP8	3 - Latitude

Employee Signature(s): \(\subseteq \subseteq \)

Date Completed 5-8-14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 140500098

Time Start	ted	Work Complete			
Loc#		Master Met	Jt		
Dat 5/14/2014	A	ecount#		SEQ#	382
Name: JAY ROWE	a segund som on opposite the second s	annan san san san san san san san san sa		Phone# (_	
Address: Hillcrest Dr		**************************************	THE RESERVE OF THE PERSON OF T	Employee J	ason W.
DEBORD,	, KY 41214		Approximation support space 4		
Location Hillcrest Dr		hill.brown.			
MCGINNIS BR	,	<u> </u>			
Type of Work: Complain	its C	hecked	and	has	120165
Material Used	box.				APPLICATION OF THE PROPERTY OF
Customer Line Inspectio	n				
Comments check press	sure, complaints of low	pressure, said the			
Current Syste	m Information:	A PARTICULAR OF THE PARTICULAR	and an any graph and an array of the second	New Info	ormation:
Meter # 1: 937492	223		Meter#1:	,	
Meter # 2: Radi			Meter#2: F	Radi	
MY11#			MXU#:		
Current Reading 4/20/20	-		Current Rea	ading	
Type of Meter: Badge		·	Type of Met	er:	
Year MFG: 1993		·	Year MFG:		
GPS - Longitude 0		······································	GPS - Latitu	ıde <u>0</u>	
Employee Signature(s):	CH JM		Date C	Completed	5-14-14

Martin County Water District 387 East Main St., Suite 140

Inez, KY 41224

WORK ORDER

WO #

Employee Signature(s): 55,54

130600159

COMPLETE

Time Started		w	ork Complete	
Loc#		Master Me	tor#	
Date <u>6/20/2013</u>	· · · · · · · · · · · · · · · · · · ·	Account#	s	EQ# 140
Name: Johnn	y Marcum		Phone	#
Address: F	Poplar Frk			
Beaut	y, Ky 41203			
	Poplar Fork. On right be			
	Poplar Fork			
Type of Work: C	complaints	(Yixed)		and the second s
Material Used:				
Customer Line II	Λ	Rhall Has	Λ.	
Comments: cust	tomer tried to turn on w	ater, nothing is coming th	ru meter	
Curren	it System Information		Ne	w Information:
Meter#1:	12760362		Meter # 1:	
Meter # 2: Radio	12760362		Meter # 2: Radlo	
MXU #:			MXU #:	
Current Reading	5/30/2013 19		Current Reading _	0
Type of Meter:	Hersey	• <	Type of Meter:	
Year MFG:	2012		Year MFG:	
GPS - Longitude			GPS - Latitude	
Employee Signat	ture(s): 55,5 4		Date Comple	ted 6-21-13

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

130600179

COMPLETE

Time Started Work Complete Master Meter # Loc# _____ Date 6/24/2013 Account# SEQ # 227 Phone# Russel Maynard Name: Address: P.O. Box Inez, KY 41224 Peter Cave Br. On left down over hill almost to the end before you get to Lum Porters. Cream Location: Old Rt 3 Type of Work: Complaints 5re Material Used: Customer Line Inspection Comments: customer has had little water pressure after meter was reinstalled, now they have no water New Information: **Current System Information:** Meter # 1: Meter # 1: Meter# 2: Redio Meter # 2: Radio MXU#: MXU#: Current Reading 0 Current Reading 0 Type of Meter: Type of Meter: Year MFG: Year MFG: GPS - Latitude GPS - Longitude

Date Completed____

Employee Signature(s): <

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER



WO # 130600128 Time Started Work Complete Master Meter # Loc# Account # SEQ # 89 Date 6/17/2013 Phone # () Jack Small Name: Address: | Buck Branch Lovely , KY 41231 Location: Buck Cranch - House Type of Work: Complaints Material Used: Customer Line Inspection Comments: customer is complaining of muddy water **Current System Information:** New Information: Meter # 1: Meter#1: 74604131 Meter # 2: Radio Meter# 2: Radio 74604131 14992781 MXU#: MXU #: Current Reading 0 Current Reading 5/20/2013 12 Type of Meter: Type of Meter: Year MFG: Year MFG: GPS - Latitude GPS - Longitude Employee Signature(s):

Date Completed 4 - 18

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

130500005



τ	ime Started	Wor	rk Complete
Loc#	a various same summan start	Master Mete	er#
Dat 5/1/2013	The second section (section (s	Account #	SEQ # 543
Name: Chest	ter Johnson Jr.	Campy many my comments of the first of	Phone #
Address: Bo	yd Ward Rd	SEAR SHARING ASSESSED & ME	Employee Josh Williams
	hawk KY 41262	· max of transmission of the contract of	Tony
Location Bo		miles, 3rd house past I	Davis Port Church, cedar house, across crk
30	yd Ward Rd		The state of the second
Type of Work: 9	Complaints	agan , ammagan sakkatatatatatataga gayatagang na sakkatanya ing sakkata y	y 22 - magin jak - manamanan 17 k - manaman dan 19 k manaman da 18 k manaman ang manaman da manaman sa manaman
Material Used:	and the second s	The state of the s	
Customer Line I	Inspection		Next farmane to discounts administrate and the second of t
			sure
	nt System Information:	and the state of t	New Information:
Meter # 1:	19713241	N	leter # 1:
Meter # 2: Radio	19713241	N	leter#2: Radio
MXU#:	- management of security and security promition of the security of the securit		IXU#:
Current Reading	4/20/2013 1177	C	urrent Reading 0
Type of Meter:	Badger		ype of Meter:
Year MFG:	2003		ear MFG:
GPS - Longitude	And And Andrews Cip S 1974	G	SPS - Latitude
Employee Signa	ature(s):	and a second of allocation by American School Schoo	Date Completed

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO # 130700002



Time Started			Work Complete			
Loc#		Master	Meter#			
Date 7/1/2013		Account #	SEQ#	178		
Name: JEFF	HINKLE		Phone #			
Address: P.O. B	ox		-			
INEZ,	, KY 41224		-			
Location: U	nion Rd					
TURK	EY ROAD					
Type of Work: C	omplaints					
Material Used: _	fixed check	Value	()ove			
Customer Line II	nspection		10000			
Comments: no v	vater					
Curren	t System Information:		New Info	rmation:		
Meter# 1:	70616457		Meter # 1:			
Meter# 2: Radio	70616457	···	Meter # 2: Radio			
MXU #:	13152697		MXU #:	The state of the s		
Current Reading	6/20/2013 158		Current Reading	0		
Type of Meter:			Type of Meter:			
Year MFG:			Year MFG:			
GPS - Longitude			GPS - Latitude			
Employee Signat	ture(s): JW		Date Completed_	7-1-13		

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO#	13070	0168		
	Time Started	e congression	Work Complete		
Loc#		Master N	fleter#		
Date 7/18	3/2013	Account#		SEQ# 21	
Name:	People's Market		Phon	ne# <u>()</u>	
Address:	P.O.BOX				
	INEZ , KY 41224]				
Location:	Old Middlefork Behind court house				
	MIDDLEFORK RD.				A STATE OF THE STA
Type of V	Vork: Complaints	***************************************			the second secon
Material L	Jsed: TIXCO				
Customer	r Line Inspection				
Commen	ts: ditch line on left just before Eclip	se driveway need	ds dug deeper, runs	across the roa	d to this customer's
or up up your to the thirty and the	Current System Information:		N	lew informatio	n:
Meter#1	70840736		Meter # 1:		
Meter # 2	Radio		Meter # 2: Radio		
MXU#:	· Company of the comp		MXU #:	,	
Current R	leading 6/20/2013 152	······································	Current Reading		
Type of M	leter: Sensus		Type of Meter:	and the state of t	
Year MFG	3: 2009	· · · · · · · · · · · · · · · · · · · ·	Year MFG:		
GPS - Lo	ngitude 0		GPS - Latitude	0	

Employee Signature(s): 18-15-65-17

Date Completed 8-30-13

Ma. lin County Water Distrut

387 East Main St., Suite 140 Inez. KY 41224

WORK ORDER

WO # 130900145 Work Complete Time Started Master Meter # Loc# SEQ # 175 Date 9/18/2013 Account # Phone # ROGER CASTLE Name: Address: Dean Castle Br. INEZ , KY 41224] Location; CASTLE BRANCH RD Type of Work: Complaints Material Used: Zi WT A? Customer Line Inspection Comments: customer had no water Last night and this morning **Current System Information:** New Information: Meter # 1: Meter#1: 99691594 Meter # 2: Radio Meter # 2: Radio MXU#: MXU#: Current Reading 8/20/2013 776 Current Reading 0 Type of Meter: Badger Type of Meter: Year MFG: 1999 Year MFG: GPS - Latitude 0 GPS - Longitude 0

Employee Signature(s): $\sqrt{5-15-65-61}$

Date Completed 9-19-13

. 387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

130800101

Tir	me Started	W	Vork Complete
Loc#		Master Me	eter#
Dat 8/6/2013		Account#	SEQ# 158
Address: P.O.Bo	N'S BP DX		Phone # Employee Clyde Stanley
Location: ROUT	E 1884/645 BY PASS		· · · · · · · · · · · · · · · · · · ·
Customer Line In	cPlasEcd Li	ηe	vn
Curren	t System Information:		New Information:
Meter # 1:	29934478		Meter # 1:
Meter # 2: Radio MXU #:	29934478		Meter # 2: Radio MXU #:
Current Reading	7/20/2013 200	. 65	Current Reading 0
	Badger		Type of Meter:
Year MFG:	2004	and wy topology	Year MFG:
GPS - Longitude	0	••	GPS - Latitude 0
Employee Signat	ure(s): /3-JS-GS-N	-	Date Completed 9-5-13

367 East Main St., Suite 140 Inez, KY 41224

WORK ORDER



WO # 131000178 Time Started Work Complete Loc# Master Meter # Account# SEQ# 36 Date 10/18/2013 Name: Clifford Endicott Phone # Address: PO Box Lovely , KY 41231 Location: Last house on left - gray Type of Work: Complaints Material Used: ____ Customer Line Inspection Comments: has extremely low pressure New Information: Current System Information: Meter#1: Meter# 1: 74846474 Meter# 2: Radio 74846474 Meter # 2: Radio MXU#: MXU#: 14993070 Current Reading 9/20/2013 15 Current Reading 0 Type of Meter: Type of Meter: Year MFG: Year MFG: GPS - Latitude GPS - Longitude

Employee Signature(s): 0 Date Completed 0 $-\lambda$ $-\beta$

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO #

131000147



Time Started Work Complete				of a term of a t
Loc#				And the second s
Date 10/14/2013 Acco		Account #		SEQ# 152
Name: Kirk M	emorial Church		Phon	e#
Address: PO Bo	×			
lnez, K	Y 41224	THE RESERVE TO SERVE THE S		
Location: Big Lic		ive on the right, meter		n gravel drive that turns left
RT 3				
Type of Work: C	omplaints			· · · · · · · · · · · · · · · · · · ·
Material Used:	l à sur ser l'amount de la company de Agrilla de que a contra de Agrilla de A	11 / Jac	}	
Customer Line Ir	spection		<u> </u>	
Comments: cust	omer is complaining of	extremely low pressure	/ 100 lb.	\$
Curren	t System Information:		N	ew Information:
Meter # 1:	99691417	- Share bear assessment	Meter#1:	A CONTRACTOR OF THE CONTRACTOR
Meter # 2: Radio			Meter # 2: Radio	
MXÙ #:		<u>.</u>	MXU #:	
Current Reading	9/20/2013 37	w w w w w w w w w w w w w w w w w w w	Current Reading	0
Type of Meter:	Badger		Type of Meter:	
Year MFG:	1999		Year MFG:	
GPS - Longitude			GPS - Latitude	
Employee Signat	ure(s): VV J	RJ	Date Comp	leted 10-15-13

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

Ti	me Started	Work Cor	mplete	de construir de la construir d
Loc #		Master Meter #		NOTES AND
Date 9/27/2013		Account #	SEQ# 29	1
Name: Wilma	Ball		Phone #	ĵ
Address:	Riverfront Rd	AND		
Belfry	KY 41514			
_ocation:	Riverfront Rd Next to the c	hruch, doublewide trailor		
LITTE	· ·		4	
HOM				
Type of Work: (
Type of Work: C	Complaints		_	
Type of Work: Contact Material Used: Contact Line I	complaints Inspection Replaced Storner said yard and gravel	genuel & rake was a mess	_	
Type of Work: O Material Used: Cusamer Line I Comments: cus	complaints Inspection Replaced	genuel & rake was a mess	d Aren	
Type of Work: Comments: cus	complaints Inspection Replaced Storner said yard and gravely Int System Information:	giavel 4 rake was a mess	New Inform	
Type of Work: Control Cusamer Line I Comments: cus Curren Meter # 1;	nspection Replaced	grave C & rake was a mess Meter:	New Inform	nation:
Type of Work: Control Cusamer Line I Comments: cus Curren Meter # 1;	complaints Inspection Replaced Storner said yard and gravel vertex said yard and gravel yard yard yard yard yard yard yard yard	Meter:	New Inform # 1: # 2: Radio	nation:
Type of Work: Control Used: Cusamer Line I Comments: cus Current Meter # 1: Meter # 2: Radio MXU #:	complaints Inspection Replaced Itemer said yard and gravel vertex said yard yard yard yard yard yard yard yar	Meter:	New Inform # 1: # 2: Radio	nation:
Type of Work: Control Used: Cusamer Line I Comments: cus Current Meter # 1: Meter # 2: Radio MXU #:	complaints Inspection Replaced Itemer said yard and gravely Int System Information: 29934881	Meter: MXU #	New Inform # 1: # 2: Radio : t Reading	nation:
Type of Work: O Material Used: Cusamer Line I Comments: cus Currer Meter # 1; Meter # 2: Radio MXU #; Current Reading	nspection Replaced eterner said yard and gravel vertex sai	Meter: MXU #	New Inform # 1: # 2: Radio : t Reading f Meter:	nation:

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO #	1311000	17	
Ti	me Started	Wo	rk Complete	
Date 11/4/2013		Account #,	SEC	Q# <u>470</u>
Name: Christ	opher Chapman		Phone #	_
Address: PO Bo	X			
lnez, l	KY 41224		in - speaning)	
				/stone garage
wy 40 4 · **** · ****	A CONTRACTOR OF THE PROPERTY O			
Ma	adison Sarah Ln.			
Type of Work: C	Complaints			
_				
Customer Line I	nspection			
Comments: extr	emely low pressure since la	st week, customer ha	s 12 lbs at box	
Currer	nt System Information:		New	Information:
Meter # 1:	29935332		1eter # 1:	
Meter#2: Radio	29935332	٨	leter#2: Radio	
MXU #:	~ * * * * * * * * * * * * * * * * * * *	<u> </u>	(XU#:	
Current Reading	10/20/2013 389		Surrent Reading	0
Type of Meter:	Badger		ype of Meter:	
Year MFG:	2004	Y	ear MFG:	
GPS - Longitude	:		SPS - Latitude	
Employee Signal	ture(s): JB-VS-TR-R		Date Completed	11-6-13

Martin County Water Distinct 387 East Main St., Suite 140

WORK ORDER

WO # 131100083

Tiı	me Started	Work C	Complete	property and the second
Loc#		Master Meter #	V-20	
Date 11/7/2013		Account#	SEQ # 18	6
Name: CLAU	DE MILLS		Phone #	week to an address and a subsets
Address: P.O.B	<u>ox</u>		generate.	
BEAU	TY , KY 41203			
Location: 7193 I	Beauty Rd brown trailer o	n the left past Tommy's Au	to Sales	

				•
Type of Work: C	Complaints		\mathbb{R}^{2}	
Material Hsed:			1	
Customer Line I	nspection	V	045 11	
Comments: extr	emely low water pressure	since leak was fixed	3 PST_A+	100 K
Currer	nt System Information:		New Inform	nation:
Meter# 1:	29934843	Mete	er#1:	
Meter # 2: Radio		Met	er#2: Radio	
MXU #:	Angeles very make and a second very make a second very mak	MXU	J#:	
Current Reading	10/20/2013 121	Curi	rent Reading	0
Type of Meter:	Badger	Тур	e of Meter:	najvas sajvasuur viina kastuluun sistemaan saanaan kan maanaan ka
Year MFG:		Yea	г MFG:	
GPS - Longitude	0			
Employee Signa	ture(s): VS		Date Completed	1-12-13

387 East Mein St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

130500216



Time Started Loc # Date 5/30/2013		Work Complete Master Meter #			
					Account#
		Name: JOY	CE DIALS		Phone #
Address: PO	вох				
LOV	/ELY , KY 41231				
	sk block		es past Lovely Post Office on left raised house w	nite	
Type of Work:	Complaints	A Territoria			
Material Used:	Fixed:				
			and grass seed spread New information:		
Curr Meter#1:	ent System Information 74846427	•	Meter # 1:	•	
					
		· · · · · · · · · · · · · · · · · · ·			
MXU #:	14991359		MXU #:		
Current Readi	ng 5/20/2013 9		Current Reading 0	<u> </u>	
Type of Meter:			Type of Meter:		
Year MFG:			Year MFG:		
GPS - Longitu	de	<u>. </u>	GPS - Latitude		
Employee Sign	nature(s):).'\(\begin{array}{c} \) - (\(\delta \sum \sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sq}}}}}}}}}}}}}} \end{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sq}\sq}}}}}}\end{\sqit{\sq}\sq}\sqrt{\sq}\sq}\sqrt{\sq}\sq}\sqrt{\sqrt{\sq}\sq}}}}}}}}}}}}}	-JE 6J	Date Completed 5-31-13	,	

Martin County Water District 387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO#	130400187		
	Time Started	Work Co	mplete	
Loc#		Master Meter#		
Date 4/18/2	013	Account#	SE	Q# <u>71</u>
Name: F	ILGRIM POST OFFICE		Phone #	¥
Address: P	O BOX			
P	ILGRIM , KY 41250			
Location:				
. 				
		round around tap box, can	- -,	
Ct	urrent System Information:		New	v Information:
Meter#1:	23864805	Meter	# 1: <u> </u>	
Meter#2: F	tadio	Meter	#2: Radlo	
MXU#:		MXU #	# ;	
Current Res	iding 3/20/2013 107	Currer	nt Reading _	0
Type of Met	er: Sensus	Туре	of Meter:	
Year MFG:	1974	Year N	MFG: _	
GPS - Long	itude 0	GPS -	Latitude 0	
Employee S	ignature(s) IS-II-G5	-16-61	Date Complete	ed 5-31-13

badger-

387 East Main St., Suite 140 Inez, KY 41224

130500005

WORK ORDER

Work Complete Loc# Master Meter # SEQ# 539 Account # Date 5/1/2013 Phone # ---Name: Chester Johnson Jr. Address: Boyd Ward Rd Tomahawk, KY 41262 Location: Boyd Ward Rd, Rockhouse 3 miles, 3rd house past Davis Port Church, cedar house, across crk Boyd Ward Rd Type of Work: Complaints Material Used: 150 - Fool of 4 1-4 TEE Customer Line Inspection Comments: customer is complaining of extremely low water pressure New Information: Current System Information: Meter # 1: Meter # 1: 19713241 Meter# 2: Radio Meter # 2: Radio 19713241 MXU#: MXU#: Current Reading 4/20/2013 1177 Current Reading Type of Meter: Badger Type of Meter: , Year MFG: 2003 Year MFG: GPS - Latitude GPS - Longitude

> 32.885989 085.49447W

Employee Signature(s): 18-65-35-17-16

Date Completed 5-30

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO # _____

130500106



Time Started		Work Complete	
Loc#	Master	Meter#	
Date 5/9/2013	Account #	SEQ #	452
Name: Junior Hunt		Phone #	
Address: Little Rockcastle Rd			
Inez, KY 41224			New Year
Location: Little Rockcaste Rd, a right over the bank Little Rockcastle Rd	bout 3m, up 2032, acro	oss mountain, grey double v	vide w/black shutters on the
Type of Work: Complaints			
Material Used:		100	
Customer Line Inspection		<u> </u>	
Comments: need gravel in driveway.	There are sink holes le	ft after leak was fixed.	
Current System Informatio	n:	New in	formation:
Meter # 1:		Meter# 1:	
Meter # 2: Radio	<u> </u>	Meter#2: Radio	
MXU #:	<u> </u>	MXU #:	
Current Reading 0	•	Current Reading	0
Type of Meter:	·	Type of Meter:	
Year MFG:	•	Year MFG:	
GPS - Longitude	· · · · · · · · · · · · · · · · · · ·	GPS - Latitude	
Employee Signature(s):		Date Completed	5-20-13

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO #	13050		
	Time Started		Work Complete	
Loc#				
Date <u>5/1</u>	5/2013	Account #		SEQ# 352
Name:	ELMER DIALS		Pho	ne# (;
Address:	lackburn & Dials Rd			
	TOMAHAWK , KY 41262			
Location:				
	ROUTE 40 WEST		· · · · · · · · · · · · · · · · · · ·	
Type of V	Work: Complaints			
Material 1				
Custome	er Line Inspection			
Commer				
	Current System Information:		<u> </u>	New Information:
Meter#1	<u></u>		Meter#1:	
Meter#2	2: Radio	·	Meter # 2: Redio	
MXU#:		<u>.</u>	MXU#:	
Current F	Reading 0		Current Reading	0
Type of N	Meter:		Type of Meter:	*
Year MF	G:		Year MFG:	
ĠPS - Lo	ongitude	<u>.</u>	GPS - Latitude	

Employee Signature(s): $\sqrt{5-15-15-15-65-16-17}$ Date Completed $\sqrt{5-22-12}$

Martin County Water District 387 East Main St., Sulte 140 Inez, KY 41224

WORK ORDER



WO#

130300215

Time Started		od o o o o o o o o o o o o o o o o o o	Work Complete		
Loc#	· a se e settemble	Master	Meter#	, , , , , , , , , , , , , , , , , , ,	
Date 3/28/2013	e. 	Account #	SEQ #	‡ <u>22</u>	\$
Name: RUSS	ELL STEPP		Phone #		
Address: PO BC	X.				
LOVE	LY , , KY	41231	a ao		Segretaria de la composición del composición de la composición de
Location: Bruce	St Lovely, 292 &	1714 Intersection, right on	1714, 1st brick house on the	e left	ų <i>4</i>
· · · · · · · · · · · · · · · · · · ·		and the country and the state of the state o	afa and taxis in the second	enement vide zwe Szienne i de Pierre i de e nome voer alle de 1830 - 4	\$ \$44 70 \$ \display 30
	υ		Dove		
Type of Work: C	omplaints				a a vidas de desenvas esta esta esta esta esta esta esta es
Material Used:	1- 6" Met	er Box Riser +	- 1-3" Meter P	lox Riser	- an experience and anomaly second
Customer Line Ir	nspection	· · · · · · · · · · · · · · · · · · ·	The second secon	المعاصدة فالمعالمة المعاملة عاديان إرباء الوموس	magan, un den der en gebende den
Comments: nee	ds boxes raised/	he has two boxes/		and the property of the accuracy	. The state of the
Curren	t System Inform	ation:	New In	formation:	
Meter#1:	72918851	•	Meter # 1:		
Meter # 2: Radio	72918851	on y visus - chini-massals amps from motions true.	Meter # 2: Radio	the state of the s	
MXU#:	14755871	n o a y deconstructure de la capación de Astración	MXU#:		\$ 5 :
Current Reading	3/20/2013 4	e geographics — in this time displaying	Current Reading	O Majorina digiti samajana	mana mana ana ana ana ana ana ana ana an
Type of Meter:	ma jenari en a	no monor — manus menonomis districtà :	Type of Meter:	telapananining otoslapa napa 1868.	⊋, ω και
Year MFG:	,	ত ভূতনাত কর্মান পুরু	Year MFG:	e veed and extensive recommendate to the first party of	غيون پهيدون
GPS - Longitude	•	· (· vers · ho see the see of the	GPS - Latitude	aning property of the transfer	in sometime to great
,	. VZ	y o, f. g. marapara sa dis distribution de	man de manuer a fin a servició de la respector de la servició (ED). Las la compressiones des la grade manuer por	60-1	<u> </u>
Employee Signat	ure(s): 1	and the same and an experience of the same and the same of the sam	Date Completed_	7-01	

4. " -1. /

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO # 130500009



Time Started	Wo	rk Complete
Loc#	Master Mete	er#
Date 5/2/2013	Account#	SEQ#
Name: Kenneth Berry		Phone # '
Address: D.O. Boy		
Lovely, KY 41231		-
Location: Dogwood DR, 2nd tr	ailor on right	<u> </u>
Type of Work: Complaints Material Used: Customer Line Inspection Comments: customer has no pres	1000	up w/water/Co/psoblem
Current System Inform	atlon:	New Information:
Meter # 1:	<u> </u>	Meter # 1:
Meter # 2: Radio		Meter# 2: Radio
MXU#:		MXU #:
Current Reading 0	(Current Reading 0
Type of Meter:		Type of Meter:
Year MFG:		Year MFG:
GPS - Longitude		SPS - Latitude
Employee Signature(s):		Date Completed 5 - 3 - 13

Martin County Water District 387 East Main St., Suite 140

WORK ORDER

WO# 140600171

Tir	ne Started	W	ork Complete	
Loc#	And the second s	Master Me	eter#	
Date 6/23/2014		Account#	SEQ#	224
Name: Norma	МсСоу		Phone #	gge-, was now a great and
Address:	Meathouse Rd			
Pilgrim	, KY 41250	consideration of the second	and disease the second state of the second	
Location:		-		
MEAT	HOUSE			. A second secon
Type of Work: C	omplaints	*		
Material Used:				
Customer Line Ir	nspection:			
Curren	t System Information:		New In	formation:
Meter#1:	29934888		Meter # 1:	
Meter # 2: Radio	29934888		Meter # 2: Radio	<u></u>
MXU#;			MXU#:	
Current Reading	5/20/2014 529	*	Current Reading	0
Type of Meter:	Badger		Type of Meter:	A CONTRACTOR OF THE CONTRACTOR
Year MFG:	2004		Year.MFG:	
GPS - Longitude			GPS - Latitude	* ***
Employee Signat	ure(s): 174, C.S	and the second	Date Completed	6-23-14

387 East Main St., Suite 140 (nez, KY 41224

WORK ORDER

WO# 131000143

ד	Time Started	Work Cor	mplete
Loc#	***************************************	Master Meter #	
Date 10/11/20	13	Account #	SEQ# 101
Name: MAR	Y STANLEY		Phone# ()
Address: PO E	Box		
WAF	RFIELD , KY 41267		
Location: 84 S	tanley Dr		
COL	LINS CREEK	;	
Type of Work:	Complaints	at M. A Rad	fix a less
Material Used:	Chech and	hed 28 #	fix a lech + Presoure
Customer Line	Inspection		
Comments: ex	.	•	
Curre	ent System Information:		New Information:
Meter#1:	70616608	Meter #	‡ 1:
Meter#2: Radio)	Meter #	‡ 2: Radio
MXU #:	13154928	MXU#	
Current Readin	g 9/20/2013 273	Curren	t Reading 0
Type of Meter:	· · · · · · · · · · · · · · · · · · ·	Туре о	f Meter:
Year MFG:	and the second s	Year M	IFG:
GPS - Longitud	le	GPS -	Latitude
Employee Sign	ature(s): <u>C.S.</u>)	ht o	ate Completed 10-38-13

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

140600182 WO# Time Started Work Complete Master Meter # Loc# Date 6/25/2014 Account # SEQ # 297 Name: SAMUEL JUDE Employee Jason W. Address: Pigeon Roost Rd PILGRIM , KY 41250 Location: igeon Roost Rd, 1 3/4 miles up at he mouth of Hale Br in a brown brick house Type of Work: Complaints ·Material Used: Customer Line Inspection Comments: too much air in lines, needs flushed New Information: Current System Information: Meter #1: Meter#1: 97728674 Meter#2: Radio ___ Meter # 2: Radio MXU#: Current Reading 0 Current Reading 5/20/2014 850 Type of Meter: Badger ____ Type of Meter. Year MFG: Year MFG: 1997 GPS - Longitude 0 GPS - Latitude 0

Date Completed

Employee Signature(s):

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 140600211 Time Started Work Complete Master Meter # Loc# Account# SEQ# 224 Date 6/27/2014 Phone # (Name: Norma McCoy Employee Justin Scott Meathouse Rd Address: Pilgrim, KY 41250 Meathouse Rd, turn right @ 1439 4 or 5 miles on right grey trailer on hill Location: MEATHOUSE Type of Work: Complaints Material Used: Customer Line Inspection Comments: nothing but air in lines New Information: **Current System Information:** Meter#1: Meter # 1: Meter # 2: Radio Meter # 2: Radio MXU #: MXU#: Current Reading 0 Current Reading 0 Type of Meter: Type of Meter: Year MFG: Year MFG: GPS - Longitude GPS - Latitude

Employee Signature(s):

Date Completed L-27-14

Martin County Water Distorct 387 East Main St., Suite 140

WORK ORDER

WO# 140600150

Time Started	Work Co	mplete
Loc#	Master Meter #	
Date 6/17/2014	Account #	SEQ# 184
Name: Jason Robinson		Phone #
Address: Meathouse Rd		
PILGRIM , KY 41250		
Meathouse Rd	in more as recommon many recordances for an order of the contract of the contr	den ere å nakkensensensen ere meld en ere til
Type of Work: Complaints		<u> </u>
Material Used:	(Dave	<u>/</u>
Customer Line Inspection:		
Comments: no water	got water	
Current System Information		New Information:
Meter # 1: 47824008	Meter	# 1:
Meter#2: Radio 47824008	Meter:	# 2: Radio
MXU #:	MXU #	<u> </u>
Current Reading 5/20/2014 853	Currer	nt Reading 0
Type of Meter: Sensus	Туре с	of Meter:
Year MFG: 1993	Year N	MFG:
GPS - Longitude 0	GPS -	Latitude 0
Employee Signature(s):	CS I	Date Completed 10-19-11

Wartin County Water District 387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	AAO :	# 1400001	74U		
Tia	ne Started	W	ork Complete		
Loc#		Master Met	ter#		<u> </u>
Date 6/4/2014		Account#	SE	Q# <u>357</u>	,
Name: Betty I			Phone #	#	
Address: P.O. B	ox				
lnez, l	(y 41224				
Location: ie	lds Traile Ct. Tomahawk:	2nd trailer (white camp	er) on right.		
Fie	lds Trailer Ctl		<u></u>		
Type of Work: C	omplaints	Lane	/		
Material Used: _		100			
Customer Line II	nspection				
Comments: no v	vater / Checked	1 por Baterier	box had	80psi	
Curren	t System Information:	<u> </u>	New	Information:	*
Meter#1:	16721822		Meter#1:		
Meter#2: Radio	16721822		Meter#2: Redlo		
MXU#:			MXU #:		
Current Reading	5/20/2014 343		Current Reading	0	
Type of Meter:	Badger		Type of Meter:		
Year MFG:	2000	·	Year MFG:		
GPS - Longitude			GPS - Latitude		
Eleve - Siev	hum(a): TH GC	C.C	Date Complete	n 10-5-12	

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 140700258 Time Started Work Complete Master Meter# SEQ # 492 Date 7/29/2014 Account# ROGER SPENCE Phone # Name: Employee Rainbo Address: P.O. Box TOMAHAWK , KY 41262 Location: Orville Rd 3rd house on left.white 1 story ORVILLE ROAD Type of Work: Complaints Material Used: Customer Line Inspection: Comments: extremely low pressure New Information: **Current System Information:** Meter#1: 19408808 Meter #1: Meter#2: Radio 19408808 Meter # 2: Radio MXU#: MXU#: Current Reading 0 Current Reading 7/20/2014 246 Type of Meter: Badger . Type of Meter: Year MFG: Year MFG: GPS - Latitude 0

Date Completed Period 7-31-14

GPS - Longitude 0

Employee Signature(s): \\S

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

		WO #	140700199		
	Time Started		Work Com	plete	
Ĺoç#	*		Master Meter#		
Date 7/23	3/2014	Acc	count #	SEQ# 221	WARRANTO CONTRACTOR OF THE STATE OF THE STAT
Name:	Tina Ward			Phone # '^	
Address:	PO Box	~		Employee Justin Scott	·
	Inez, KY 41224				
Location:	Spence Branch, 19 T	ina Ln, app 1/2 m	ile on right in beige traile	or	
	MILO				
Type of V	Vork: Complaints		1)	* **	
Material (Jsed:	11181	ed)	3.5	
Custome	r Line Inspection:	9 1000			
Commen	ts: water has a stale o	odor, has been like	this for a few days. So	does father next door.	
The second secon	Current System Info	rmation:		New Information:	

	_		
t System Information:		Ne	ew Information:
29935324	North Christian and Space (Christian	Meter # 1:	.5
		Meter # 2: Radio	
	·	MXU#:	
6/20/2014 398		Current Reading	0
Badger	· · · · · · · · · · · · · · · · · · ·	Type of Meter:	
2004		Year MFG:	
*		GPS - Latitude	
	6/20/2014 398 Badger	29935324 6/20/2014 398 Badger 2004	29935324 Meter # 1: Meter # 2: Radio MXU #: 6/20/2014 398 Current Reading Badger Type of Meter: 2004 Year MFG:

Employee Signature(s):

Date Completed

7-24-11

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO#	140700175	
	Time Started	Work Complete	
Loc#		Master Meter #	<u></u>
Date 7/2	1/2014 Accou	int# SEQ# <u>165</u>	
Name:	Mill 9 Chang blowgome	Phone#	
Address:	PO Roy	Employee Justin Scott	
	WARFIELD , KY 41267	•	
Location:	77 Hode Rd, on the right side of T&D har	dware nursery lot, grey raised house	
	HODE		
Type of V	Nork: Complaints		
Material I	Used:	Jane	
	r Line Inspection		
Commen	nts: very low water pressue	165 PSI	
	Current System Information:	New Information:	
Meter#1	: 70616551	Meter # 1:	
Meter#2	2: Redlo 70616551	Meter#2: Radio	
MXU#:	13136511	MXU #:	
Current F	Reading 6/20/2014 205	Current Reading 0	
Type of N	Meter:	Type of Meter:	
Year MF0	G:	Year MFG:	
GPS - Lo	ongitude	GPS - Latitude	
Employee	e Signature(s):	ユー クリー	14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 140700087 Work Complete Time Started Loc# Master Meter# Account# SEQ# 818 Date 7/8/2014 Phone # () CHESTER GARTIN JR Name: Address: \ Hode Rd. Employee Rainbo WARFIELD , KY 41267 Hode Rd, 6 miles from T&D Hardware on Warfield side, across from Alonzo Alley, grey double wide Location: wigazebo & chain link fence. Type of Work: Complaints Material Used: Showed 100 psi at box Customer Line Inspection: Comments: low pressure for a week; call before going, has 6 dogs New Information: **Current System Information:** Meter#1: Meter#1: 47823903 Meter#2: Radio ____ Meter#2: Radio MXU#: MXU#: Current Reading 0 Current Reading 6/20/2014 811 Type of Meter: Sensus Type of Meter: 1993 Year MEG: Year MFG: GPS - Longitude 0 GPS - Latitude

Employee Signature(s): LU15 m

Date Completed 7/14/14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

140700170 WO# Time Started Work Complete Master Meter # Loc# Account# SEQ# 33 Date 7/18/2014 Phone # James R. Shepherd Name: Employee Rainbo Address: P.O.BOX INEZ , KY 41224] Location: 88 Nichols Street.Last house on right.Across from Henry Ward. **NICHOLS STREET** Type of Work: Complaints Material Used: all osher series is sport up Customer Line Inspection Weterin flacting though Comments: no water New Information: **Current System Information:** Meter # 1: 70840668 Meter # 1: Meter # 2: Redio Meter # 2: Radio 70840668 MXU#: MXU#: Current Reading 0_____ Current Reading 6/20/2014 159 Type of Meter: Type of Meter: Sensus Year MFG: Year MFG: 2012 GPS - Latitude 0 GPS - Longitude 0

Employee Signature(s):

Date Completed 7-/8-/4

Martin County Water District 387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

140700026

Time Started			Work Complete
Loc#		Master	Meter#
Date 7/7/2014		Account #	SEQ# 224
Name: Norma	МсСоу		Phone # (
Address:	Meathouse Rd		Employee Rainbo
Pilgrim	n, KY 41250		
Location: 3	Meathouse Rd, turn rig	ght @ 1439 4 or 5 mile	es on right grey trailer on hill
MEAT	HOUSE		
Type of Work: C	omplaints		
Material Used:	90.	ster ues	lose
_			
Customer Line I	ispection:		
Comments: no v	vater		
Currer	t System Information	1:	New Information:
Meter # 1:	29934888		Meter # 1:
Meter # 2: Radio	29934888		Meter # 2: Radio
MXU#:			MXU #:
Current Reading	6/20/2014 532		Current Reading 0
Type of Meter:	Badger	4	Type of Meter:
Year MFG:	2004		Year MFG:
GPS - Longitude			GPS - Latitude
Employee Signa	ture(s): B,J,		Date Completed 7-7-14

Martin County Water District V 387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO#	140700018	
	Time Started	Work Cor	mplete
Loc#		Master Meter #	
Date 7/3/2014		Account#	SEQ# 172
Name: John	n Moore		Phone#
Address:	In atherina Del	7	Employee Rainbo
Pilgi	rim , KY 41250		
Location:	, Meathouse Rd Below Leann		rallor
Wol	f Creek		
Type of Work:	Complaints		
Material Used:	<u>:</u>		
Customer Line	e Inspection: <u>alla</u>	to lear of	
	xtremely low water pressure		
Curr	ent System Information:	, , , , , , , , , , , , , , , , , , ,	New Information:
Meter # 1:	47823969	Meter	# 1:
Meter#2: Red	io	Meter a	# 2: Radio
MXU#:		MXU#	k
Current Readi	ng <u>6/20/2014</u> 581	Curren	it Reading 0
Type of Meter:	Sensus	Туре о	of Meter:
Year MFG:	1993	Year M	MFG:
GPS - Longitu	de <u>0</u>	GPS-	Latitude 0
Employee Sign	nature(s): RJ		Date Completed 7-11-14

387 East Main St., Sulte 140 Inez, KY 41224

WORK ORDER

140700031 **WO#** Time Started Work Complete Loc# Master Meter # Account # SEQ # 123 Date 7/7/2014 Phone# (George Spence Name: Employee Clyde Stanley Address: P.O. Box Inez, KY 41224 Location: 148 Mckinney Rd.Mudfork Rd., across from Milo Bridge, 1/2mile up Mudfork stay left, blacktop hill 2nd drive on left, meter is @ bottom of hill 148 Mckinney Dr Type of Work: Complaints Material Used: Customer Line Inspection act water Comments: no water **Current System Information:** New Information: Meter # 1: 12760367 Meter#1: Meter # 2: Radio 12760367 Meter # 2: Radio MXU #: MXU#; Current Reading 0 Current Reading 6/20/2014 49 Type of Meter: Hersey Type of Meter: Year MFG: 2012 Year MFG: GPS - Longitude GPS - Latitude

Employee Signature(s): TH, CS

Date Completed 7:-8-14

Martin County Water District 387 East Mein St., Sulte 140 Inez, KY 41224

WORK ORDER

	WO #	140700	113	
	Time Started	W	ork Complete	
Loc#			t4	
Date 7/1	1/2014	Account#		SEQ# 106
Name:	MARY STANLEY		Phone	e# <u>(</u>
Address:	DO Pay 1		Emplo	oyee Kyle Sammons
	WARFIELD , KY 41267			
Location:	84 Stanley Dr			
		•		
Type of V	Vork: Complaints			
Material (Used:			
Custome	r Line Inspection			
Commen	ts: no water / Controcto	urs forgot	5. two V	alve pook en
	Current System Information:		No	ew Information:
Meter#1	: 70816608		Meter # 1:	
Meter#2	: Radio		Meter#2: Redio	
MXU#:	13154928		MXU#:	
Current R	Reading 6/20/2014 283		Current Reading	0
Type of M	feter:		Type of Meter:	
Year MF0	3 :		Year MFG:	
GPS-Lo	ngitude		GPS - Latitude	

Employee Signature(s): 55

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

			WO #	14070	00106		
	Tir	ne Started	Property of the state of the st		Work Complete	· ·	
Loc#				Master	Meter#		<u>.</u>
Date 7/10)/2014		 .	Account#		SEQ# 184	
Name:	Jason	Robinson			Phor	ne# !	
Address:	N	leathouse F	₹d	,	Emp	loyee Rainbo	
	PILGR	ım ,	KY 41250		· · · · · · · · · · · · · · · · · · ·		•
Location:	. <u>N</u>	Meathouse F	Rd, beside LeAn	na Church, brick	house		
	9006 N	leathouse F	 {{d}				
Type of V	Vork: C	omplaints				<u> </u>	
Material L	Jsed:	they	Rosel	the s	eason go	tolod	PR.S
Customer	Line Ir	spection:	····-				
Comment	ts: <u>low</u>	pressure					· · · · · · · · · · · · · · · · · · ·
(Curren	t System In	formation:		N	lew information:	
Meter # 1:	:	47824008			Meter # 1:		
Meter # 2:	Radio	47824008			Meter#2: Radio		
MXU#;			- Indiana		MXU #:		
Current R	eading	6/20/2014	857		Current Reading	0	
Type of M	eter:	Sensus			Type of Meter:		
Year MFG	3 :	1993			Year MFG:		
GPS - Lor	ngitude	0		<u></u>	GPS - Latitude	<u>o</u> ·	

Date Completed___

Employee Signature(s): 85,

Martin County Water District 387 East Main St., Sulte 140 Inez, KY 41224

WORK ORDER

	WO#	140700108	
	Time Started	Work Com	plete
Loc#		Master Meter#	
Date 7/10	0/2014	Account#	SEQ# 142
Name:	HENRY JUDE		Phone #
Address:	North Wolf Creek		Employee Rainbo
	LOVELY , KY 41231		
		green trim on hill; Ralf Mayna	rd is nearest neighbor
Type of V	Vork: Complaints	η ,	a (à
Material U	Jsed: Line bra	he in Wall	relet
Custome	r Line Inspection:		
Commen	ts: no water		
	Current System Information:		New Information:
Meter#1	74846459	Meter#	1:
Meter#2	: Radio 74846459	Meter#	2: Radio
MXU#:	14991931	MXU#:	
Current R	leading 6/20/2014 42	Current	Reading 0
Type of M	leter:	Type of	Meter:
Year MFG	3:	Year MF	FG:
GPS - Loi	ngitude	GPS - L	atitude

Employee Signature(s): RJ

Date Completed 7-10-14

Martin County Water District 387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO #	140700011	
	Time Started	Work Co	omplete
Loc#			
Date 7/1/2	2014	Account#	SEQ# 163
Name:	Forest Fitch		Phone# (
Address:	P.O. Box	***	Employee John Mills
	In 107 44004		_
Location:	łuckleberry Ridge Brown bric		
,			
Type of W	ork: Complaints		
Material U	sed:		
	Line Inspection		
	s: no water, check Otto Brown pun		; electrical issues
C	Current System Information:		New Information:
Meter#1:	63860615	Meter	#1:
Meter # 2:	Radio 63860615	Meter	# 2: Radio
MXU#:	13155594	MXU;	#:
Current Re	eading 6/20/2014 463	Curre	nt Reading 0
Type of Me	eter:	Туре	of Meter:
Year MFG:		Year i	MFG:
GPS - Lon	gitude	GPS-	Latitude

Date Completed


Employee Signature(s):

M... tin County Water Distinct 387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

COMPLETED

•	WO #	130800177	
Til	me Started	Work Co	omplete
Loc#		Master Meter#	
Date 8/20/2013		Account#	SEQ # 260
Name: STER	LING MARCUM		Phone #
Address:			-
LOUIS	SA , KY 41230]		_
- 15 -	Rockcastle Rd, 1st white how the Drive War	xit will be	Side of Sox
Type of Work: C	Complaints	-	
Material Used:			
	nspection		
Comments: say	s water is foamy and has di	rt in it	
Curre	nt System Information:		New Information:
Meter # 1:	47823998	Mete	r#1:
Meter # 2: Radio	47823998	Mete	r#2: Radio
MXU #:		MXU	#:
Current Reading	7/20/2013 456	Curre	ent Reading 0
Type of Meter:	Sensus	Туре	of Meter.
Year MFG:	1993	Year	MFG:
GPS - Longitude	e <u>0</u>	GPS	- Latitude 0
Employee Signa	ature(s):		Date Completed 8-21-13



387 East Main St., Suite 140

WORK ORDER

130800168

COMPLETE

WO# Time Started Work Complete Master Meter # Loc# Account# SEQ # 834 Date 8/16/2013 Phone # Thomas & Diana Thompson Address: hompson Lane Inez, ky 41224 Location: .. Thompson Ln Turkey, past fire dept., 2nd house past new Nazarene Church, tan w/green roof 292 Type of Work: Complaints Material Used: Customer Line Inspection told customer to check Comments: customer has had low water pressure for at least 2 months. New information: **Current System Information:** Meter#1: Meter#1: Meter#2: Radio Meter# 2: Radio MXU#: MXU#: Current Reading 0 Current Reading 0 Type of Meter: Type of Meter: Year MFG: Year MFG: GPS - Latitude GPS - Longitude

Employee Signature(s):

Date Completed

M...tin County Water Dist...t

387 East Main St., Suite 140

WORK ORDER



WO#

130600152

Time Started		<u> </u>	Work Complete	
Loc#	E-	Master Meter #		
Date <u>6/19</u>	9/2013	Account#	SEQ# 393	
Name:	DONALD HINKLE		Phone#	
Address:	P.O.BOX			
	INEZ , KY 41224]			
Location:	Resevoir Rd. 2nd driveway.			_
	LICKBRANCH RD.			
Type of V	Vork: Complaints			
Material I	1 /			-
Custome				
Commen	ts: leak across the road from his	s house.		
	Current System Information:		New Information:	
Meter#1	: 70616419		Meter # 1:	
Meter#2	Radio	<u> </u>	Meter# 2: Radio	
MXU#:	13150995		MXU #:	
Current F	Reading 5/20/2013 183	<u></u>	Current Reading 0	
Type of N	Meter:	*	Type of Meter:	<u>.</u>
Year MF0	3 :		Year MFG:	•
GPS - Lo	ngitude		GPS - Latitude	-
Employee	e Signature(s): 18-75-65-7	G-N	Date Completed 8-1-13	

Martin County Water Distract 387 East Main St., Suite 140

WORK ORDER



WO#

130800013

	Time Started	VVOIK	Work Complete		
Loc#		Master Meter	#		
Date 8/2/	2013 A	Account#	SEQ#	179	
Name:	JEFF HINKLE		Phone # (
Address:	P.O. BOX				
	INEZ, , KY 41224		· ·		
Location:	109 Union Rd				
	** * **				
Type of V	Vork: Complaints				
Material l	Jsed:				
	r Line Inspection No leak four	nd () one		
Commen	ts: high bill				
	Current System Information:	and an experience the control of the	New Inf	formation:	
Meter#1	70616457	Me	eter#1:		
Meter#2	: Radio 70616457	Me	eter#2: Radio	1	
MXU#:	13152697	M×	(U #:		
Current R	eading 7/20/2013 169	Cu	rrent Reading	0	
Type of №	leter:	Туг	pe of Meter.		
Year MFC	3: 	, Ye	ar MFG:		
GPS - Lo	ngitude	GP.	S - Latitude	and the state of t	
Employee	Signature(s): \\		Date Completed	8-5-13	

Iviartin County Water District J

WO#

WORK ORDER

130800110

COMPLETE

Ti	me Started	Work Complete
Loc#	, <u> </u>	Master Meter #
Dat 8/8/2013	Account	# SEQ# 178
Name: KARE	N MARCUM	Phone #
Address: PO BO)X	Employee Kyle Sammons
BEAU	TY , KY 41203	
Location Bi	g Elk Rd. 1 mile up Big Elk Rd on right	t, beside Black barn w/sign that says "Buck Creek Scooter"
يها يحفظ المحادث المحا		
Type of Work: C	omplaints	
Material Used:	The second section of the section of the second section of the section of the second section of the sect	
Widterial Oscu	.) santa ya) (W)
Customer Line Ir	nspection	
Comments no v	vater is coming from meter, please-sto	p by Karen's house (white w/black fence)
Curren	t System Information:	New Information:
Meter # 1:	29934697	Meter # 1:
Meter#2: Radio	29934697	Meter # 2: Radio
MXU#:	A. A. C.	MXU #:
Current Reading	7/20/2013 876	Current Reading 0
Type of Meter:	Badger	Type of Meter:
Year MFG:	2004	Year MFG:
GPS - Longitude	0	GPS - Latitude 0
Employee Signat	ure(s): U	Date Completed 8-8-13

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

140800265 WO# Work Complete Time Started Master Meter# Loc#_____ Date 8/25/2014 Account # SEQ # 101 Phone # LEE SUMPTER Name: Employee Clyde Stanley Address: P.O.BOX , KY 41224 INEZ, Location: Blackburn Ln on Blacklog; trailor on right **ROUTE 40 EAST** Type of Work: Complaints Material Used: 3016 of grass seed, and 4 bail of strawle Customer Line Inspection: Comments: property behind Johhny Stacy's need repaired New Information: **Current System Information:** Meter #1: 29935408 Meter#1: Meter # 2: Radio Meter # 2: Radio MXU#: MXU#: Current Reading 0 Current Reading 7/20/2014 301 Type of Meter: Type of Meter: Badger Year MFG: Year MFG: 2004 GPS - Latitude GPS - Longitude 0

Employee Signature(s):

Date Completed 8-25-14

367 East Main St., Suite 140 (nez, KY 41224

WORK ORDER

140800268 WO# Time Started Work Complete Master Meter# Loc# SEQ# 126 Date 8/25/2014 Account # Phone # "~ Name: George Spence Employee Rainbo Address: P.O. Box Inez, KY 41224 Ackinney Rd.Mudfork Rd., across from Milo Bridge, 1/2mile up Mudfork stay left, blacktop hill 2nd Location: drive on left, meter is @ bottom of hill ickinney Dr Type of Work: Complaints Material Used: Comments: low pressure all day, neighbors are having same issue New Information: **Current System Information:** Meter # 1: Meter#1: Meter # 2: Radio Meter # 2: Radio MXU#: MXU #: 0 Current Reading Current Reading Type of Meter: Type of Meter: Year MFG: Year MFG: GPS - Longitude GPS - Latitude

Date Completed

Employee Signature(s)

387 East Main St., Suite 140 inez, KY 41224

WORK ORDER

	WO#	140800250	
	Time Started	Work Con	nplete
Loc#	-	Master Meter #	
Date 8/20	0/2014	Account#	SEQ# 400
Name:	Helen MILLS		Phone #
Address:	P.O. BOY		Employee Troy Horn
	INEZ , KY 41224]		
Location:	71 Helen Mills Rd, white house		<u> </u>
	TURKEY ROAD	DOV	
Type of V	Vork: Complaints	US	
Material (Used:		
	r Line Inspection: ts: customer has had low pressure		. 180 %
	Current System Information:		New Information:
Meter#1	: 70616398	Meter #	‡ 1:
Meter#2			# 2: Redio
MXU#:	13152700	#	•
Current R	Reading 7/20/2014 222	Curren	t Reading 0
Type of M	Neter:	Туре о	f Meter:
Year MF0	G:	Year M	IFG:
GPS - Lo	ngitude	GPS -	Latitude
Employee	Signature(s): TH, CS	D	rate Completed 8- 25-14

Employee Signature(s): TH, C 5

Martin County Water District 387 East Mein St., Suite 140

tnez, KY 41224

WORK ORDER

	W0 #	140800	016 ·	
	Time Started	W	ork Complete	
Loc#			ter#	
Date 8/4	/2014	Account #	SE	Q # <u>268</u>
Name:	LILLIAN STACY		Phone a	¥
Address:	РО ВОХ.		Employ	ee Justin Scott
	LOVELY , KY 41231			
Location:	Himmlerville Rd, on left, Yellow h			
•				
Type of \	Work: Complaints			
Material	Used:			
	1 / 1	1.6 600	\	
	er Line Inspection:	(N) VEL		
Commer	nts: complaints of water smelling b	ad		
	Current System Information:		Ne	v Information:
Meter#	1: 29934938		Meter#1:	
Meter#2	2: Radio		Meter#2: Radio _	
MXU#:		·	MXU #:	
Current l	Reading 7/20/2014 245		Current Reading	0
Type of f	Meter: Badger	······	Type of Meter:	**************************************
Year MF	હ·		Year MFG:	

Employee Signature(s): Justin Set Soft Date Completed 8-4-14

GPS - Longitude 0

GPS - Latitude 0_

wartin County Water Disc. 1ct

WORK ORDER

	W	/O#140800	017			
Time Started			/ork Complete			
Loc#						
Date 8/4/2014 Accord		Account#		SEQ# 462		
Name: Penny	Todd	A.F.C.	Phone	*		
Address: PO Bo	1		Emnlo	oyee Justin Scott		
lnez, k	(Y 41224					
Location: Davis Cemetery Rd 1st house on right past Ooten, Grey in color, Church of Christ in front of house						
Type of Work: Complaints Material Used: Customer Line Inspection Comments: foul odor since low water pressure last week, lines may need flushed						
Current System Information:		1:	New Information:			
Meter # 1:	67012673		Meter#1:			
Meter # 2: Redio	<u> </u>		Meter#2: Radio			
MXU#:		-	MXU#:			
Current Reading	7/20/2014 137		Current Reading	0		
Type of Meter:	Sensus	, 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 	Type of Meter:			
Year MFG:	2006	<u> </u>	Year MFG:			
GPS - Longitude	<u>0</u> .		GPS - Latitude	0 .		
Employee Signature(s): Date Completed 8-4-14						

linartin County Water Dis act

387 East Main St., Suite 140 Inez. KY 41224

WORK ORDER

WO# 140800123 Work Complete Time Started Master Meter# Loc#_____ SEQ# 24 Account# Date 8/11/2014 Phone # ARNOLD MURPHY Name: Employee Justin Scott Address: Hewitt Ave LOVELY , KY 41231 Location: Hewitt Ave, 1st house on left, beige 2-story house 9015; at box Type of Work: Complaints Material Used: Customer Line Inspection: Comments: low pressure New Information: **Current System Information:** Meter # 1: Meter # 1: 99459379 Meter # 2: Radio Meter # 2: Radio 99459379 MXU#: MXU#: Current Reading 7/20/2014 678 Current Reading 0 Type of Meter: Type of Meter: Badger Year MFG: 1999 Year MFG:

Employee Signature(s): C 1-5M

GPS - Longitude 0

Date Completed 8-12-14

GPS - Latitude

Niartin County Water Dist 1 1 1

WORK ORDER

	• WO#	140800145					
Time Started		Work Co	Work Complete				
Loc#		Master Meter #					
Date 8/13	3/2014	Account# 47	SEQ# 82				
Name:	EDDIE HINKLE		Phone # ()				
Address:	P.O.BOX		Employee Rainbo				
	BEAUTY , KY 41203		_				
Location:	Bone Holw 2031.Lower Popla	ar.Bone Hollow.1st trailer o	n right at top of hill.Grev & white.				
Type of V	Work: Flush Line	Dane					
Material Used: Flush live 8-13-14							
Customer Line Inspection							
Comments: water still has odor and low pressure							
	Current System Information:		New Information:				
Meter#1	97728662	Mete	er#1:				
Meter#2	2: Redio	Mete	r#2: Radio				
MXU#:		MXU	l#:				
Current F	Reading 7/20/2014 794	Curr	ent Reading 0				
Type of N	Weter: Badger	Туре	e of Meter:				
Year MF	G: 1997	Year	MFG:				
GPS - Lo	ongitude 0	GPS	i - Latitude 0				

Employee Signature(s):___

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

140800092 WO # Work Complete Time Started Master Meter # Loc# _____ SEQ # 224 Account # Date 8/6/2014 Phone # (Norma McCoy Name: Employee Rainbo Address: Veathouse Rd Pilgrim, KY 41250 Location: Meathouse Rd, turn right @ 1439 4 or 5 miles on right grey trailer on hill MEATHOUSE Type of Work: Complaints Material Used: Customer Line Inspection: break /repaired Comments: no water New Information: **Current System Information:** Meter #1: 29934888 Meter # 1: Meter#2: Radio Meter # 2: Redio 29934888 MXU#: Current Reading 0 Current Reading 7/20/2014 536 Type of Meter: Type of Meter: Badger 2004 Year MFG: Year MFG: GPS - Latitude GPS - Longitude

Employee Signature(s):

Date Completed

Martin County Water District 387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO #	140500138	
	Time Started	Work	Complete
Loc#			#
Date 5/1	9/2014	Account #	SEQ # 63
Name:	EDANK DAI DDIDGE		Phone # ()
Address:	P.O.BOX		
	INEZ , KY 41224]		
Location:	RIGHT SIDE 133 Haney Pl .		
	HANEY PLACE		
Type of \	Work: Complaints		
	•		
Commer	nts: driveway has been destroyed s	ince line was repaced la	st year.
<u></u>	Current System Information:		New Information:
Meter#1	1: 98003195	Me	ter#1:
Meter#2	2: Radio	Me	ter#2: Radio
MXU #:		M×	(U #:
Current F	Reading 4/20/2014 774	Cu	rrent Reading 0
Type of I	Meter: Badger	Ту	pe of Meter:
Year MF	G: <u>1998</u>	Ye	ar MFG:
GPS - Lo	ongitude 0	GP	PS - Latitude 0
Employe	e Signature(s):	•	Date Completed 8/26/14

Employee Signature(s):_

Martin County Water District V 387 East Main St., Suite 140 Inez, KY 41224

	WO #	140800	076
	Time Started	W	/ork Complete
Loc#			eter#
Date 8/5/2	2014	Account #	SEQ# 35
	OLEN DIEVINE		Phone# (
Address:	DO Boy		Employee Justin Scott
	INEZ , KY 41224]		
Location:	131 Blevins Ln		
	MIDDLEFORK RD.		
Type of V	Vork: Complaints		
	Jsed: r Line Inspection:	Dan	
	ts: musty smell with greasy textur	e/Tan is	Toyoly to fix it
	Current System Information:	4/0/	New Information:
Meter#1	29213201		Meter#1:
Meter#2	: Radio		Meter#2: Radio
MXU#:			MXU #:
Current R	Reading 7/20/2014 757		Current Reading 0
Type of M	fleter: Badger		Type of Meter:
Year MFC	G: <u>2004</u>		Year MFG:
GPS - Lo	ngitude 0		GPS - Latitude 0
Employee	e Signature(s):	SAA	Date Completed 8-6-14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 140900215

Time Started		Work Complete		
Loc#	Master	Meter#		
Date 9/26/2014	Account#	SEQ# 221		
Name: LON CRUM		Phone # (_)		
Address: P.O. Box.		Employee Troy Horn		
lnez , KY 412	24			
Location: 81 Guyton Rd, Little Lich	k Br, top of hi∥ last house @	top of hill, red		
GUYTON RD	1100			
Type of Work: Complaints				
Material Used:		200 - Common of the common of		
Customer Line Inspection				
Comments: very low water pressu	ire/Said it	t come back up		
Current System Inform	ation:	New Information:		
Meter # 1:		Meter # 1:		
Meter # 2: Radio		Meter # 2: Radio		
MXU #:		MXU #:		
Current Reading 0		Current Reading 0		
Type of Meter:		Type of Meter:		
Year MFG:	·	Year MFG:		
GPS - Longitude	·	GPS - Latitude		
Employee Signature(s): CS	TS, TH	Date Completed 9-26-18		

Martin County Water District 387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	'	NO#	140900003	
	Time Started		Work Complete	
Loc#_			Master Meter#	
Date 9/2/2	2014	Account	t# ⁻	SEQ# 218
Name:	JAMES HOWELL		Pł	one #
Address:	P.O.BOX 1		Er	nployee Troy Hom
	INEZ , KY 41224			•
Location:	37 James Howell Dr Left F	ork		,
	LITTLE LICK BRANCH		veine)	
	Jsed:			
Customer	Line Inspection			and the second s
Comment	s: low water pressure all w	eekend / had	d 30psiat	bax
	Current System Informati			New Information:
Meter#1:			Meter#1:	and the process of the Contract of the Contrac
Meter#2:	Radio	,	Meter#2: Rac	do
MXU#:	-		MXU#:	
Current R	eading 8/20/2014 1326		Current Read	ing 0
Type of M	leter: Badger	,	Type of Meter	
Year MFG	6: <u>1994</u>	<u>.</u>	Year MFG:	
GPS - Lor	ngitude <u>0</u>		GPS - Latitud	e <u>0 </u>

Employee Signature(s): TH, CS

Date Completed 9-12-14

Martin County Water District 387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

•	WO# 140900	090	•	•
Time Started	w	ork Complete		
Loc#	Master Me	ter#		agyapanga sa mana da ang aka a
Date 9/4/2014	Account #	SEQ	#	materials - 198 Favorance are dated to see
Name: Ashley Tiller	·	Phone #		
Address:		Employee	Rainbo	
1				
Location: mouth of Setser Br, Det	oord. Wants locking lid for pit.		a d vis a 1 mars	
A CONTRACTOR OF THE CONTRACTOR		1		manage of the first course had been been been been been been been bee
)		
Type of Work: Complaints	(Done)	/		emment are self-ten stay agrees? . 4. 19.5 meters
Material Used:			epin a	ong ang ang di ping dipungan kanangan
Customer Line Inspection				,*
Comments: Put Led av	d Flaged it of	<u>C</u>		
Current System Inform			nformation:	
Meter # 1:		Meter # 1:		
Meter # 2: Radio		Meter # 2: Redio		of the Minimum Street
MXU#:	· · · · · · · · · · · · · · · · · · ·	MXU #:	*	
Current Reading 0		Current Reading	0	ngar barrier (v. d. d.) – mojši k trijetik
: Type of Meter:	<u> </u>	Type of Meter:	, _p , _{communic}	nazo pede inci e
Year MFG:		Year MFG:		namentus (1883), se e a deservición
GPS - Longitude	and the state of t	GPS - Latitude		- / san s
· ;				

Date Completed 9-11-

387 East Main St., Suite 140 Inez, KY 41224

	WO	# 1409000	3Q
	Time Started	Wor	k Complete
Loc#	F 128 and 1		
Date 9/5/	2014	Account# -	SEQ # 270
Name:	Edna Daniel		Phone #
Address:	PO Box	,	Employee Justin Scott
	lnez , KY 41224		
Location:	the left.		een two brick houses, go up the hill, 1st place on
Type of V	Vork: Complaints		And the second s
Material l			
	r Line Inspection: ts: this customer and her neight	bor are experiencing no/lo	
***	Current System Information:		New Information:
Meter # 1	: 29935126	M	Meter # 1:
Meter#2	: Radio	M	Neter#2: Radio
MXU#:	-a	M	1XU #:
Current R	teading 8/20/2014 421	C	current Reading 0
Type of M	leter: Badger	T	ype of Meter:
Year MFC	G: 2004	Υ	ear MFG:
GPS - Lo	ngitude 0	G	SPS - Latitude 0
Employee	e Signature(s):		Date Completed 9-5-/4

387 East Main St., Suite 140 Inez, KY 41224

	WO:	# 14	0800118		
Time S	tarted	······································	Work Complete		
Loc#	·	Mas	ter Meter#		
Date 8/8/2014		Account #		SEQ	# <u>137</u>
Name: MARK HOV	WARD		Pł	none#	
Address: P.O.BOX			E *		Clyde Stanley
Inez, KY 4	1224		<u></u>		
ocation: Hinkle	Valley, turn left after	crossing bridge	, white doublewide		
	04 140 0				
ROUTE 18	84 MILO				
Type of Work: Comp	laints		. la line		
Type of Work: Comp	laints		, b'line		
Type of Work: Comp	laints	en stap	y b' line upon aux	منقده	
Type of Work: Comp Material Used:	laints Let ce sette	- ·	od on		
Type of Work: Comp Material Used: Customer Line Inspect Comments: extremel	laints Let ce sette	- ·	od on		
Type of Work: Comp Material Used: Customer Line Inspect Comments: extremel Current Sy:	laints Let ce sette ction: Sere use y low pressure since	- ·	od on	New i	
Type of Work: Comp Material Used:	laints Let be settle ction: Since we y low pressure since stem Information:	leak was worke	ed on.	New II	nformation:
Type of Work: Comp Material Used:	laints Let be settle ction: Since substance y low pressure since stem information: 67271	leak was worke	ed on. Meter # 1:	New II	nformation: 993457
Type of Work: Comp Material Used:	laints Let a sette ction: Serve sette y low pressure since stem information: 67271	leak was worke	Meter # 1: Meter # 2: Rad MXU #:	New II	nformation: 993457
Type of Work: Comp Material Used:	laints Let be setter ction: Since let y low pressure since stem Information: 67271	leak was worke	Meter # 1: Meter # 2: Rad MXU #:	New II	nformation: 993457
Type of Work: Comp Material Used:	laints Let be settle ction: Serve use y low pressure since stem Information: 67271	leak was worke	Meter # 1: Meter # 2: Rad MXU #: Current Readi	New II	nformation: 993457

387 East Main St., Suite 140 Inez, KY 41224

Time Started	W	ork Complete	
Loc#	Master Me	eter#	
Date 10/23/2014	Account #	SEQ	# 158
Name: RICKY HORN	<u> </u>	Phone #	
Address: Mountain View		Employee	e Clyde Stanley
INEZ, , KY 41224			
Location: Mountain View			
CALF CREEK			
Type of Work: Complaints			
	I	3 1	
Material Used	1100		
Material Used:		У	
Material Used:		У	
Customer Line Inspection:	atel cone	back on	
Customer Line Inspection:	atel cone	back on	
Comments: complaints of no water	atel cone	Sack CM.	
Customer Line Inspection: Comments: complaints of no water Current System Information Weter # 1: 99691124	atel cone	New Meter # 1:	Information:
Comments: complaints of no water Current System Information:	abe Cone	New Meter # 1: Meter # 2: Radio	Information:
Customer Line Inspection: Comments: complaints of no water Current System Information: Vieter # 1: 99691124 Vieter # 2: Radio	abe Cone	New Meter # 1: Meter # 2: Radio MXU #:	Information:
Customer Line Inspection: Comments: complaints of no water Current System Information: Weter # 1: 99691124 Meter # 2: Radio	abe Cone	New Meter # 1: Meter # 2: Radio MXU #:	Information:
Customer Line Inspection: Comments: complaints of no water Current System Information: Weter # 1: 99691124 Meter # 2: Radio MXU #: Current Reading 9/20/2014 645	abe Cone	New Meter # 1: Meter # 2: Radio MXU #: Current Reading	Information:
Customer Line Inspection: Comments: complaints of no water Current System Information: Meter # 1: 99691124 Meter # 2: Radio MXU #: Current Reading 9/20/2014 645 Type of Meter: Badger	abe Cone	New Meter # 1: Meter # 2: Radio MXU #: Current Reading Type of Meter:	Information:

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

		WO #	1410002	31	
	Time Started		Wo	rk Complete	
Loc#					
Date 10/2	27/2014		Account#		SEQ# 107
Name:	ERVIN STEPP			Phon	e# <u> , </u>
Address:	Collins Crk			Emp	loyee Rainbo
	WARFIELD	, KY 41267			
Location:	Collins Crk M	ain end of Coll	ins Creek.Meter box o	on right	
			1		
Type of V	Work: Complaints			·	
Material I	Used:				
Custome	er Line Inspection:	blaw	rece.		ened tu Williag
	Current System In	formation:			New Information:
Meter # 1	-		1	Vieter#1:	
Meter # 2	2: Radio 16151170			Meter#2: Radio	
MXU#:			1	MXU #:	
Current F	Reading 10/20/2014			Current Reading	0
Type of N	Meter. Badger		- 	Type of Meter:	Approjekt deman sind with a strong a sample amount of the sample and sample a
Year MF	G: <u>2000</u>			Year MFG:	All and the second of the seco
GPS - Lo	ongitude <u>-82.42864</u>			GPS - Latitude	37.83200
Employee	e Signature(s):	35.		Date Comp	oleted 16-26-14

387 East Main St., Suite 140 Inez, KY 41224

141000142

WORK ORDER

WO#

Ti	me Started	W	Work Complete		
Loc#		Master Me	ter#		
Date 10/15/2014		Account # 111		SEQ# 9	
Name: DORC	THY FARRA		Phor	ne#	
Address: P.O.B	ox		Emp	oloyee Corey Hill	
WARF	FIELD , KY 41267				
Location:	Riverfront Rd				
LOVE	LY (
Type of Work: O	complaints \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	one)			
Material Used:					
Customer Line In	nspection:	1			
Comments: chec	ck water meter to see if it is	s busted / groo	nd water	in look of down leaft o	
Curren	t System Information:			lew Information:	
Meter#1:	97728665		Meter#1:		
Meter # 2: Radio			Meter#2: Radio		
MXU#:			MXU#:		
Current Reading	9/20/2014 495		Current Reading	0	
Type of Meter:	Badger		Type of Meter:		
Year MFG:	1997		Year MFG:		
GPS - Longitude	0		GPS - Latitude	0	
Employee Signat	ure(s)(1))	Date Comp	leted 10 IS I Y	

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

141100140 WO# Time Started Work Complete Master Meter # Loc# Account # _____ SEQ # 223 Date 11/24/2014 Phone # _ TIM MCCOY #2 Name: Employee Troy Horn Beauty Rd Address: BEAUTY , KY 41203 Location: Beauty Rd Type of Work: Complaints Material Used: Customer Line Inspection: Fulsh Dd Comments: air in lines; blowing his service lines apart New Information: **Current System Information:** Meter#1: 16368696 Meter # 1: Meter # 2: Radio 16368696 Meter # 2: Radio MXU#: MXU#: Current Reading 0 Current Reading 11/20/2014 429 Type of Meter: Badger Type of Meter: Year MFG: Year MFG: 2000 GPS - Latitude 0 GPS - Longitude 0 Date Completed 11-24-14

Employee Signature(s): \$\frac{1}{5}, \frac{1}{5}\$

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 141100088 Time Started Work Complete Loc# Master Meter # Account # SEQ # 226 Date 11/13/2014 Name: LON CRUM Phone # () Employee Justin Scott Address: P.O. Box Inez , KY 41224 Location: Guyton Rd, Little Lick Br, top of hill last house @ top of hill, red **GUYTON RD** Type of Work: Complaints 2 leaks Has wader now Material Used: Customer Line Inspection: Comments: customer has no water New Information: **Current System Information:** Meter # 1: Meter # 1: 29935077 Meter # 2: Redio 29935077 Meter # 2: Radio MXU#: MXU#: Current Reading 0 Current Reading 10/20/2014 610 Type of Meter: Type of Meter. Badger Year MFG: 2004 Year MFG: GPS - Latitude 0 GPS - Longitude 0

Employee Signature(s): (5, 15, T/F

Date Completed / 1 - 25 - 14

. 387 East Main St., Suite 140 tnez, KY 41224

WORK ORDER

141100110 WO# Work Complete Time Started Master Meter # SEQ# 27 Date 11/18/2014 Account # Phone# Carol Stevens Name: Employee Rainbo Address: Long Br. Lovely, Ky 41230 Location: Long Br, new white home on the right, less than 1/2 mile to next rd 292 Type of Work: Complaints it was air ir line whal ever was Customer Line Inspection: Dreeting it affer an. Comments: water is milky white since last night, check for problems New Information: Current System Information: Meter #1: 29934536 Meter # 1: Meter # 2: Radio Meter#2: Radio MXU#: MXU#: Current Reading 0 Current Reading 10/20/2014 534 Type of Meter: Type of Meter: Badger Year MFG: Year MFG: 2004 GPS - Latitude GPS - Longitude Date Completed 11-20-14 Employee Signature(s): RJ

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO#	140900237	_
	Time Started	Work Comp	lete
Loc#		Master Meter#	
Date <u>9/2</u>	9/2014	Account #	SEQ# 66
Name:	FRANK BALDRIDGE		Phone# (
Address:	P.O.BOX		Employee John Mills
, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	INEZ , KY 41224]	•	
Location	: Haney Pl, last house, green h	nouse;	
	HANEY PLACE	6	
Type of '	Work: Complaints) me /
Material	Used:	<u>·</u>	
Custome	er Line Inspection:		
Comme	nts: driveway has been destroyed s	since line was repaced last ye	ar, needs blacktop
	Current System Information:		New Information:
Meter#	1: 98003195	Meter#	1:
Meter#	2: Radio	Meter#	2: Radio
MXU#:		MXU #:	
Current	Reading 9/20/2014 792	Current	Reading0
Type of	Meter: Badger	Type of	Meter:
Year MI	FG: <u>1998</u>	Year M	FG:
GPS - L	ongitude 0	GPS - I	atitude 0
1			

Employee Signature(s): Him Wes Black Supplies

Date Completed 17-24-14

WORK ORDER

	WO #	141000176	<u></u>
÷.	Time Started	Work	Complete
Loc#		Master Meter	
Date 10/2	21/2014	Account#	SEQ#
Name:	Maggie Collins		Phone #
Address:			Employee Clyde Stanley
,	inez KY 41224		
Location:	2 driveways past Frog Pond; Mag driveway rough, needs repaired.	gie Collins; driveway up	p hill, recent work by MCWD has left her
• •	Vork: Complaints	FIX	
Material l	Jsed: Level aut t	he rough	opat
Custome	r Line Inspection;		
Commen	ts: Still Need	d a drain	Pipe
	Current System Information:		New Information:
Meter#1	:	Me	eter # 1:
Meter # 2	: Radio		eter # 2: Radio
MXU#:			
Current R	teading 0	. Cu	urrent Reading 0
Type of N	fleter:	Ту	rpe of Meter:
Year MF0	G:	Ye	ear MFG:
GPS - Lo	ngitude	GF	PS - Latitude
			to.

Date Completed 12-36 - 14

Employee Signature(s): JS, RJ, TR

Martin County Water District 387 East Main St., Suite 140

Inez, KY 41224

WORK ORDER

WO# 140100432

Time Started Work Complete			k Complete		
Loc #		Master Meter #			
Dat 1/31/2014		Account #	SEQ # 14		
Name: MARIE	and the second s				
Address: S. PILGR	Wolf Creek Rd. KY 41250	4 440; - / - 10 minute at a second at a se	Employee Rainbo		
Location: Wolf	creek past miners in betwee	n garbage dump and i	martin co freewill baptist		
<u>-</u>		\sim			
Type of Work: C	complaints (1) one			
Material Used:					
Customer Line In	·				
Comments: no v	vater toak one	ter boose of	malester was gaing though		
Curren	t System Information:		New Information:		
Meter#1:	96130852	M	leter # 1:		
Meter # 2: Radio		M	leter#2: Radio		
MXU#:	and administrative parameters of the contract	N	XU #:		
Current Reading	1/20/2014 718	- California - col colorate (se sen)	urrent Reading 0		
Type of Meter:	Badger	т	ype of Meter:		
Year MFG:	1996	Υ	ear MFG:		
GPS - Longitude	0	G	PS ~ Latitude 0		
Employee Signat	ure(s): В. J.		Date Completed 1-30-14		

387 East Main St., Sulte 140 Inez, KY 41224

WORK ORDER

	WO	# 14010	0058		
	Time Started	·	Work Complete	the contract of the contract o	
Loc#	, , , , , , , , , , , , , , , , , , ,	Master M	/leter#	<i>s</i>	
Date 1/7/2	014	Account #		SEQ# 212	
Name: L	ON CRUM		Phor	e# ()	
Address: F	P.O. Box		Market and the second s		
į	nez , KY 41224				
Location:	Guyton Rd, Little Lick Br, top	of hill last house @	top of hill, red		
· _	GUYTON RD				
Type of Wo	ork: Complaints		0		
Material I Is	sed: WATCO PCS	C1110 = 1 =	and a		
			V		
Customer I	Line Inspection				
Comments	: low water pressure				The same of the sa
C	urrent System Information:		N	lew Information:	
Meter#1:	29935077		Meter # 1:		
Meter # 2:	Radio 29935077		Meter#2: Radio		
MXU #:			MXU#;		
Current Re	ading 12/20/2013 575	Annady, magazina kapina kapina kapina	Current Reading	O	
Type of Me	ter: Badger		Type of Meter:		
Voor MEC:	2004		Year MFG:		

Employee Signature(s): 18-65-75 Date Completed 1-15-14

GPS - Longitude 0

GPS - Latitude 0

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

140100222 WO# Time Started Work Complete Master Meter # Loc# SEQ# 144 Account # Dat 1/10/2014 Phone # Name: Kathy Jude Address: Calf Crk Rd Employee Tony Blevins Inez, Ky 41224 Calf Crk Rd. Brick house at the forks of the road, meter is by the wellhouse,nearest neighbor is Location: Dennis Hinkle. 24 Calf Crk Rd Type of Work: Complaints Material Used: Customer Line Inspection Stored At 100 PSI Comments: water pressure comes and goes after they changed meter out . **Current System Information:** New Information: Meter # 1: Meter#1: 29802064 Meter # 2: Radio 29802064 Meter # 2: Redio MXU#: MXU#: Current Reading 0 Current Reading 12/20/2013 828 Type of Meter: Badger Type of Meter: 2004 Year MFG: Year MFG: GPS - Longitude GPS - Latitude

Employee Signature(s):

Date Completed | - 16 - 14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 140100234

	Time Started	v	Vork Complete
Loc#		Master M	eter#
Dat 1/13	3/2014	Account #	SEQ# 104
Name:	NORMA SLONE	an	Phone #
Address:	P.O.BOX \		Employee Jason W.
	INEZ, , KY 41224	Part of the state	nomen a remova de la company.
Location			ouse w/screened in front porch and green roof.
	CAMP BRANCH		
Type of V	Vork: Complaints		
Material l	Jsed:	-DON	
Custome	r Line Inspection		
Commen	ts low pressure (S. D.S.)	= A box	
ىمىدىنىنى ئىلىقىيەچىچىۋە - يىدردىدە يور. _ي ورىي	Current System Information:	Andrew States Commission of the Commission of th	New Information:
Meter#1	99085893		Meter # 1:
Meter#2	Radio		Meter # 2: Radio
MXU#:			MXU#:
Current R	eading 12/20/2013 443	e againm and a distribution of Artifaction of Artifaction (Artifaction of Artifaction of Artifac	Current Reading 0
Type of M	leter: Badger	married Married Street, Street	Type of Meter:
Year MFG	S: 1999		Year MFG:
GPS - Lo	ngitude 0		GPS - Latitude 0
Employee	Signature(s): 55/		Date Completed 1 - 15 - 1 4

387 East Main St., Sulte 140 Inez, KY 41224

WORK ORDER

WO #	140100202	a.
Time Started	Work Complete	9
Loc#		
Date 1/10/2014		
Name: ALBERT SMITH		Phone #
Address: P.O.BOX		
INEZ , KY 41224		
Location:		
J CASSADY BR.		
Type of Work: Complaints	t	
Material Used:		
Customer Line Inspection		
O for O days		
Current System Information:		New Information:
Meter # 1: 97354363	Meter # 1:	
Meter# 2: Radio	Meter # 2: R	adio
MXU #:	MXU #:	
Current Reading 12/20/2013 836	Current Rea	ding 0
Type of Meter: Badger	Type of Met	9F;
Year MFG: <u>1997</u>	Year MFG:	
GPS - Longitude 0	GPS - Latitu	de <u>0</u>

Employee Signature(s): John Mills

Date Completed ///3/14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO #	1401002	20	
Ł	Time Started	Wo	ork Complete	
Loc#	and the second control of the second control	Mactor Mat		
Dat 1/10	0/2014	Account#	<u></u>	SEQ # 102
Name:	MARY STANLEY		Phone	e# ()
Address:	PO Box 1		Emplo	oyee Jason W.
	WARFIELD , KY 41267			
Location:	84 Stanley Dr			
		3		
Type of V	Vork: Complaints			
	Jsed:	•		· · · · · · · · · · · · · · · · · · ·
Custome	r Line Inspection			
Commen	ts: has had low water pressure fo	r days so has neighbo	rs at bottom of hill	1535 PSI Atb
	Current System Information:	kantan na salah 1937 mendebutan mendebutan penganjah mendebutan dalam di Persandah dalam di Persandah dalam di		ew Information:
Meter#1	: 70616608		Vleter#1:	
Meter # 2	: Radio		Meter # 2: Radio	
MXU #:	13154928		VIXU #:	
Current R	Reading 12/20/2013 273	n veget and the state of the st	Ourrent Reading	0
Type of M	Aeter:	B. Cong. and Boy. on Address to Manager	Type of Meter:	Among the state of
Year MF0	3 :		Year MFG:	
GPS - Lo	ngitude	promotions () to make.	GPS - Latitude	

Employee Signature(s):

Date Completed 1-13-14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO # 140100209 Time Started Work Complete Master Meter # Loc# SEQ # 452 Date 1/10/2014 Account # Robert Nichols #3 Phone # Name: Address: PO Box Inez, KY 41224 Location: Middlle Fork, last railer on right, greyish tan in color 308 Holden Hills 308 Holden Hills Type of Work: Complaints Material Used: Customer Line Inspection Comments: no water Has water Model New Information: **Current System Information:** 70616589 Meter # 1: Meter # 1: Meter # 2: Radio 70616589 Meter # 2: Radio MXU #: MXU#: 13154916 Current Reading 0 Current Reading 12/20/2013 183 Type of Meter: Type of Meter: Year MFG: Year MFG: GPS - Latitude GPS - Longitude

Employee Signature(s): 5/6 Date Completed 1-14-14

387 East Main St., Sulte 140

		WO #	140	200265	_		
	Time Started	and the state of t	ander#4	Work Comple	ete		
Loc#	April 1 and			r Meter#			
Date 2/1	1/2014	· · · · · · · · · · · · · · · · · · ·	Account#	·	SEQ#	103	
Name:	MARY STANLEY		and analysis are an analysis and an analysis are an analysis and an analysis are an analysis and an analysis and an analysis are an analysis are an analysis and an analysis are an analysis a		Phone # ()	
	PO Box :						
	WARFIELD	, KY 41267					
Location:	84 Stanley Dr						
	COLLINS CREEK						
Type of V	Work: Complaints						n var ann an ann ann ann ann an agus aine an ann an ann an an an an an an an an a
Material (Used: 5h Q	LAN	WATE	<u>er</u>		ente de como anticipatado de la como de la c	manus and the State of the Stat
Custome	r Line Inspection						
Commen	its: customer has no	water	14 - 100 1 100 1 100 1				
	Current System In	formation:			New Inf	formation:	
Meter#1	70616608			Meter#1:			
Meter#2	Radio		_ 	Meter # 2:	Radio		
MXU #:	13154928	age of the section game and the section and th		MXU #:			
Current F	Reading 1/20/2014	273		Current Re	eading	0	
Type of M	Meter:		 	Type of Me	eter:		
Year MF0	G:			Year MFG			*·.
GPS - Lo	ngitude			GPS - Lati	tude	<u>-</u>	
Employee	e Signature(s):	5-G5-1	<u> </u>	. Date	Completed	2-12-	-14

Martin County Water District 387 East Main St., Suite 140

WORK ORDER

WO# 140200249

Time Started	Work Complete			
Loc#	Master Meter #			
Dat 2/11/2014 Acc	ount# SEQ# 234			
Name: JEAN COPELAND	Phone # /			
Address: Jean Copeland Ln	Employee Justin Scott			
TOMAHAWK, KY 41262				
Location Jean Copeland Ln on Milo, grey hou	se by road			
ROUTE 1884 MILO				
Type of Work: Complaints	K-Jul.			
Material Used:				
Customer Line Inspection				
	PSI At box			
Current System Information:	New Information:			
Meter # 1:	Meter # 1:			
Meter # 2: Radio	Meter # 2: Radio			
MXU #:	MXII#			
Current Reading 0	Current Reading 0			
Type of Meter:	Type of Meter:			
Year MFG:	Year MFG:			
GPS - Longitude	GPS - Latitude			
Employee Signature(s): 55	Date Completed 2 - 12 - 14			

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO #	1402001	72		
	Time Started	W	ork Complete	· · · · · · · · · · · · · · · · · · ·	
Loc#		Master Me	er#		
Dat 2/4/	/2014	Account#		SEQ# 109	
Name:	Matthew Preece		Phor	ne# (
Address:	P.O. Box		Emp	loyee Justin Scott	**************************************
	Inez, KY 41224				
Location	•	· · · · · · · · · · · · · · · · · · ·			
Type of V	Vork: Complaints			and the state of t	
Material (Jsed: INAWED		garaya <u>ayan ayan ya aranga kanan kanan ayan</u> an	Val	
Custome	r Line Inspection				
Commen	ts customer has not had water in	over a week, check f	or problems		
- 1- 10/01/2009/0	Current System Information:	- Comment of Comments of Comme	ħ	lew Information:	
Meter#1	29934714	·	Meter#1:		and toplants between
Meter # 2	Radlo 29934714		Meter#2: Redio		
MXU#:	Norman Market Constitution of Market		MXU#;		
Current R	eading 1/20/2014 502	hill-science ,	Current Reading	0	
Type of M	eter: Badger		Type of Meter:		100000
Year MFG	3: 2004	_	Year MFG:		
GPS - Lor	ngitude 0	 	GPS - Latitude	0	

Date Completed 2 1 - 14

Employee Signature(s): 13-65-1H-J5

Martin County Water District 387 East Main St., Suite 140

Inez, KY 41224

WORK ORDER

WO# 140200198 Work Complete Time Started

Loc#	Master Meter #					
Date 2/6/2	2014 Acc	ount# SEQ# 58				
Name:	Mel Markin	Phone # (606)				
Address:	Russell Workman Rd					
	Lovely, KY 41231	And the second of the second o				
Location:	cation: Lovely, Long BR, 2 m, on right yellow house					
	ł Russell Workman Rd					
Type of W	ork: Complaints					
Material U	sed:					
Customer	Line Inspection					
Comment	s: water is going on and off	is Good . I worked on Regulator				
— weathern Versions have a second	Current System Information:	New Information:				
Meter# 1:	94788708	Meter # 1:				
Meter # 2:	Radio 94788708	Meter#2: Radio				
MXU#:	والمنافذة والمنا	MXU #:				
Current Re	eading 1/20/2014 180	Current Reading 0				
Type of M	eter: Badger	Type of Meter:				
Year MFG	: 1994	Year MFG:				
GPS - Lon	gitude	GPS - Latitude				

Employee Signature(s): プレ パゴ Date Completed ラ/10/12

Martin County Water District 387 East Main St., Suite 140

Inez, KY 41224

WORK ORDER

WO# 140200185

T	me Started	* >?****** N	/ork Complete
Loc#		Master Me	eter#
Dat 2/5/2014		Account# -	SEQ# 62
Name: RUSS	SELL WORKMAN		Phone # (
Address: R	ussell Workman Rd	(Long Blanch)	
	LY , KY 41231		
Location:			
Type of Work: 0	Complaints		
Material Used:			
Customer Line I	nspection		
Comments: no	water water is	Good 1.	Wolked on Regulator
Currer	nt System Information:		New Information:
Meter # 1:	47823828		Meter # 1:
Meter # 2: Radio		····	Meter # 2: Radio
MXU #:			MXU#:
Current Reading	1/20/2014 727		Current Reading 0
Type of Meter:	Sensus		Type of Meter:
Year MFG:	1993		Year MFG:
GPS - Longitude	0		GPS - Latitude 0
Employee Signa	ture(s): ゴン Rゴ		Date Completed a / 10 / 13

387 East Main St., Suite 140

WORK ORDER

WO# 140200194 Time Started Work Complete Master Meter # Loc# Account # SEQ# 321 Dat 2/5/2014 Heather Harrison Phone # Name: Employee Tony Blevins Address: ! Mullett Br INEZ , KY 41224 Location: Mullett Br. Coldwater.Last house on the right, white house on hill, stone bottom Mullett Br Type of Work: Complaints Material Used: Customer Line Inspection 20 PSI A+ 60X Comments: extremely low water pressure New Information: **Current System Information:** Meter#1: Meter # 1: 92701651 Meter # 2: Radio Meter # 2: Radio 92701651 MXU#: MXU #: Current Reading 0 Current Reading 1/20/2014 959 Type of Meter: Type of Meter: Badger 1992 Year MFG: Year MFG: GPS - Longitude 0 GPS - Latitude Employee Signature(s): 55, C (+ Date Completed 2 - 6 - 14

Martin County Water Dist. Lt / 387 East Main St., Suite 140

Inez, KY 41224

	WO #	140200202	
Tir	me Started	Work C	omplete
Date 2/6/2014		Account #	SEQ# 59
Name: DAVID	MILLS		Phone # ^
Address: P.O.BO	 ∩X		_
INEZ,	, KY 41224		,
Location:	urkey Rd.1st driveway on k	eft past Resevoir Rd.	
TURK	EY ROAD		
Type of Work: C	omplaints (Dane	
Material Used:			
	nspection toush on thaugh on n't had water in 2 weeks	reter sect an	chech wirter was gaing
	t System Information:		New Information:
Meter # 1:	70616474	Mete	r#1:
Meter # 2: Radio	70616474	Mete	r#2: Radio
MXU#:	14440372	MXU	#:
Current Reading	1/20/2014 35	Curre	ent Reading 0
Type of Meter:		Туре	of Meter:
Year MFG:		Year	MFG:
GPS - Longitude		GPS	- Latitude
Employee Signat	ure(s): JW, RJ,		Date Completed 2-6-14

387 East Main St., Sulte 140 Inez, KY 41224

WORK ORDER

WO # 140200204 Work Complete Time Started Master Meter # Loc# Account # SEQ # 214 Date 2/6/2014 Phone # Name: Dahryi Keller Address: Setser Br Inez, Ky 41224 Location: Setser Br. Wood sided house @ end of road Setser Br Type of Work: Complaints Material Used: Customer Line Inspection Comments: extremely low pressure 2 weeks problem Fixed | kocked on Cold Water master met New Information: Current System Information: Meter # 1: 33076067 Meter # 1: Meter # 2: Radio Meter # 2: Radio 33076067 MXU#: MXU#: Current Reading 1/20/2014 249 Current Reading 0 Type of Meter: Badger Type of Meter:

Employee Signature(s): TR, TH, GS, CS

Date Completed > /6/14

Year MFG:

GPS - Latitude

2006

GPS - Longitude

Year MFG:

387 East Main St., Suite 140

WORK ORDER

WO# 140200164 Work Complete Time Started Master Meter # Loc# SEQ# 248 Dat 2/4/2014 Account # Phone # Ronald D. & Evelyn Preece Name: Employee Clyde Stanley Address: P.O. Box INEZ , KY 41224 Location Muddy Br. Coldwater. Last cream double-wide on left. " Muddy Br Type of Work: Complaints Material Used: Customer Line Inspection Problem Fixed ! worked on Gold water master mater Comments extremely low water pressure, cannot even flush toilet New Information: **Current System Information:** Meter # 1: Meter#1: 97176433 Meter#2: Radio Meter # 2: Radio 97176433 MXU#: MXU#: Current Reading 12/20/2013 923 Current Reading 0 Type of Meter: Badger Type of Meter: . Year MFG: 1997 Year MFG: GPS - Longitude 0 GPS - Latitude 0

Employee Signature(s): TB, TH, GS, CS

Date Completed 2/6/14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Employee Signature(s): TB, GS, TH, CS

140200163

			mailing town and amountments of managed a minimal		
T	ime Started	Work Complete			
Loc#			in the second se		
Dat 2/4/2014		Account #	2	SEQ # 114	
Name: ROGE	ER SMITH		Phor	ne#	
Address: PO Bo	OX ·		Emp	loyee Tony Blevins	
INEZ	, KY 41224	and the state of t			
Location	Camp Br Rd				
CAME	BRANCH	and Australia and Constitutional Anni Market State (Constitution Constitution Const			
Type of Work: Q	Complaints				
Material Used:					
Customer Line I				water master meter	
Comments extr				at bas	
Currer	nt System Information:	N 1990 or an annual transition of the development of the second second and the community of the second seco	<u>namago may ayali da u marananda kapamanana a aya akina na uu uu</u>	lew Information:	
Meter # 1:	19629183	TO A A A MENTAL PROPERTY AND A MENTAL AND A MANAGEMENT	Meter # 1:		
Meter#2: Radio			Meter # 2: Radio		
MXU#;			MXU #:	4a-canada and AMANA BANANA Andreas	
Current Reading	12/20/2013 782		Current Reading	0	
Type of Meter:	Badger		Type of Meter:	water and the second se	
Year MFG:	2003		Year MFG:		
GPS - Longitude	O	The Market constraints from the contract of th	GPS - Latitude	0	

Date Completed 3 / 6 / 14

Ivrartin County Water Discret /

WORK ORDER

WO# 140100407

Time Started		Work	Work Complete			
Loc#		Master Meter	Master Meter#			
Dat <u>1/30/2014</u>		Account#	SI	EQ# 32	1	
Name: Heath	er Harrison		Phone	#		manadadar ay May. had
Address:	lullett Br		Employ	yee <u>Cly</u> c	de Stanley	
INEZ	, KY 41224					
Location:N	Jullett Br. Coldwater.Last	house on the right, white h	ouse on hill, sto	ne bottor	<u>n</u>	
2 M	fullett Br			•	-	
Type of Work: 0	Complaints					
Material Used:		Jul]				-
Customer Line I	nspection					
Comments: extr	emely low pressure		****			
Curren	nt System Information:		Ne	w inform	nation:	***************************************
Meter#1:	92701651	Me	ter#1:		ne e e e	
Meter#2: Radio	92701651	Me	ter#2: Radio			
MXU #:		MX	(U #:			
Current Reading	12/20/2013 951	Cu	rrent Reading _		0	
Type of Meter:	Badger	Тур	oe of Meter:			
Year MFG:	1992	Yea	ar MFG:		- 5-2	
GPS - Longitude	0	GP	S - Latitude <u>C</u>)		<u>. </u>
Employee Signat	ure(s):	,	Date Comple	ted 🔆	1.6.14	

Iviartin County Water District 387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO # 140100404

Time Started		Work Complete		
Loc#		Master Meter #		
Dat 1/30/2014		Account#	SEQ# 109	
Name: Allen I	Bowen		Phone #	
Address: P.O. E	BOX		Employee Justin Scott	ugh yiraddida Alda yan di Salaurunna
Inez	, Ky 41224	of the state of th		
	amp Br, White Doublew		and the second s	
	Branch			
Type of Work: 0	Complaints			annanda edda an dan er de Araghy V Militaria
Material Used: _	· /	Done		
Customer Line I	nspection	+ •		
Comments cus	tomer has extremely low	/ pressure	- 10 10 10 10 10 10 10 10 10 10 10 10 10	
Curren	nt System Information:		New Information:	
Meter#1:	96646016		Meter # 1:	······································
Meter # 2: Radio			Meter # 2; Redio	
MXU #:			MXU #:	
Current Reading	12/20/2013 1542		Current Reading 0	
Type of Meter:	Badger		Type of Meter:	- Alberton
Year MFG:	1996		Year MFG:	ablanca a su de la constantina della constantina
GPS - Longitude	0		GPS - Latitude 0	
Employee Signal	ture(s):///		Date Completed 2.6./4/	

heartin County Water Dist...ct

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	Wo	# 1402	200008	
	Time Started	No. 1487-1-1-1-1-1-1-1-1	Work Complete	
Loc#	AND THE RESIDENCE OF THE PROPERTY OF THE PROPE	Master	Meter #	
Dat 2/3/2	2014	Account#	SEQ# 260	
Name:	LORRAINE JUDE		Phone #	and the second s
Address:	Duncest Rd		Employee Justin Sco	ott
	Lake Worth, FI 33467			
Location:				
	DAVIS BRANCH			
Type of W	/ork: Complaints	appears , was some one of the same and the s		
Material U	and the second s			
Customer	Line Inspection		Adams of the second	
	s: Gary Jude-former owner of p			
C	Current System Information:		New Information	
Meter#1:	46220019		Meter # 1:	A Street Annual Conference of
Meter # 2:	Redio		Meter # 2: Radio	
MXU#:			MXU #:	<u> </u>
Current Re	eading 1/20/2014 1034		Current Reading 0	
Type of Me	eter: Sensus		Type of Meter:	
Year MFG:	: 1992		Year MFG:	
GPS - Long	gitude 0		GPS - Latitude 0	

Employee Signature(s): 18-65-75-11

Date Completed 2 - 14 - 14

Martin County Water Dist. at

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

|--|

Time Started	Time Started Work Complete		
Loc#	Master Meter #		
Dat 2/3/2014	Account#	SEC	2# 204
Name: EXCEL MINING CO., L	LC	Phone #	
Address: 3t Hwy 194 West	War and the second seco	Employe	e Justin Scott
Pikeville, KY 41501	restriction to the second seco		
	eter is beside main road by g		
		•	
	d meter		n para managan nganggan ng mara manggan par mara mara di mining manggan nganggan di di sa di sa di sa di sa di
Current System Informa	ation:	New	Information:
Meter # 1:		Meter#1:	10788513
Meter # 2: Radio	di ny ro ana ny maganaga ana ani an'	Meter # 2: Radio	Market of the same
MXU #:		MXU #:	And the second s
Current Reading 0		Current Reading	\$ 000
Type of Meter:		Type of Meter:	ABB (3 In)
Year MFG:	Markage or company or a street deliverable for every	Year MFG:	
GPS - Longitude		GPS - Latitude	
Employee Signature(s): 15-33	5-65-TH	Date Complete	02-5-14

387 East Main St., Suite 140 Inez. KY 41224

WORK ORDER

WO# 140200181 Time Started Work Complete Master Meter # Loc# SEQ # 83 Dat 2/5/2014 Account# .. Phone # (ARLEN COOK Name: Address: PO BOX Employee Jason W. BEAUTY , KY 41203 Location: Bone Hollow Rd Type of Work: Complaints Material Used: Qol WATER Customer Line Inspection Comments: water went off around 10 pm last night Roset Puers Sine wind 2 New Information: **Current System Information:** 19713222 Meter#1: Meter # 1: Meter # 2: Radio Meter # 2: Redio MXU#: MXU #: Current Reading 1/20/2014 732 Current Reading 0 Type of Meter: Badger Type of Meter:

Employee Signature(s): 5 0 AF 18-55-65-114 Date Completed 2-5-14

Year MFG:

GPS - Latitude 0

Year MFG:

2003

GPS - Longitude 0

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO#	140200184	,
	Time Started	Work Co	mplete
Lac #		Master Meter#	
Dat 2/5/201	14	Account #	SEQ# 84
Name: FR	REDDIE & CAROL CHAFFINS		Phone # (
Address: PC	BOX		Employee Jason W.
BE	EAUTY , KY 41203		
Location:			
Material Use	d: 98 DATER		
Comments: 1	no water since last night /	each Premp	sond unet 2
Cui	rrent System Information:		New Information:
Meter # 1:	72305550	Meter	# 1:
Meter#2: Ra	dio 72305550	Meter	# 2: Radio
MXU #:	· · · · · · · · · · · · · · · · · · ·	MXU #	‡ :
Current Read	ding 1/20/2014 83	Сипег	nt Reading 0
Type of Mete	r: Sensus	Туре с	of Meter:
Year MFG:	2010	Year N	AFG:
GPS - Longitı	ude <u>0</u>	GPS -	Latitude 0

Employee Signature(s): THE RT 18 GS-V5-TH Date Completed 2-5-14

387 East Main St., Suite 140

WORK ORDER

WO # 140200182 Work Complete Time Started Master Meter# Loc# SEQ # 82 Account # Dat 2/5/2014 Name: MAGGIA HINKLE Phone # (Address: PO BOX Employee Jason W. BEAUTY KY 41203 Bone Hollow on 2031, 1/4 of a mile on Poplar Fork on left, 2nd single wide on left Location: Type of Work: Complaints Material Used: GOT DATER Customer Line Inspection Comments: no water since about 10:30 last night Reset Pump seed with 2 **Current System Information:** New Information: Meter # 1: Meter#1: 99085837 Meter # 2: Radio 99085837 Meter # 2: Radio MXU#: MXU#: Current Reading 1/20/2014 584 Current Reading 0 Type of Meter: Badger Type of Meter: 1999 Year MFG: Year MFG: GPS - Latitude 0 GPS - Longitude 0

Employee Signature(s): 5-0 RT 13-15-14-CS Date Completed 2-5-14

Wartin County Water District / 387 East Main St., Suite 140

Inez, KY 41224

WORK ORDER

Time Started		W	Work Complete		
Loc#		Master Me	eter#		
Dat 1/31/2014	4	Account#			
Name: GAR	Y CHAPMAN		Phone # (
Address: P.O.	вох		Employee Rainbo		
INEZ	, KY 41224				
Location:	Coldwater Rd				
COL	DWATER RD.				
Type of Work:	Complaints	(2)			
Material Used:		100			
Customer Line	Inspection				
Comments: no	water Has w	xter toda	//		
Curre	nt System Information:		New Information:		
Meter # 1:	93144891		Meter # 1:		
Meter#2: Radio			Meter # 2: Radlo		
MXU #:			MXU #:		
Current Reading	g 12/20/2013 837		Current Reading 0		
Type of Meter:	Badger	A A A A A A A A A A A A A A A A A A A	Type of Meter:		
Year MFG:	1993		Year MFG:		
GPS - Longitud	e <u>0</u>		GPS - Latitude 0		
Employee Signa	ature(s): \(\sum_{\subset} \)		Date Completed 2-3-1		

387 East Main St., Suite 140 fnez. KY 41224

WORK ORDER

140100465 **WO#** Work Complete Loc# Master Meter # Dat 1/31/2014 Account# -SEQ# 117 Janice Blackburn Name: Employee Justin Scott Address: __ Camp Branch Inez, KY 41224 ¹ Camp Br, last house in hollow, green double wide Location: Coldwater Type of Work: Complaints Material Used: Customer Line Inspection had about Comments: Extremely low pressure **Current System Information: New Information:** 29935159 Meter # 1: Meter#1: Meter # 2: Radio 29935159 Meter # 2: Radio MXU#: MXU #: Current Reading 0 Current Reading 12/20/2013 309 Type of Meter: Badger Type of Meter: 2004 Year MFG: Year MFG: GPS - Longitude GPS - Latitude

Employee Signature(s): <u>JS</u>

Date Completed 2-2-14

Iviartin County Water District 387 East Main St., Sulte 140

WORK ORDER

Time Started Work Complete		
Loc#		eter#
Dat 1/31/2014	Account#	SEQ# 298
Name: TRACY BUTCHER		Phone #
Address: Coldwater Rd		Employee Tony Blevins
INEZ , KY 41224		
Location: around Pleasant Valley		
		
COLDWATER RD.	and the state of the state and a se	
Type of Work: Complaints	Service Control of the Control of th	
Material Used:		
Customer Line Inspection		
Comments: Russia		9 %
Current System Information:		New Information:
Meter # 1: 99691581		Meter # 1:
Meter # 2: Radio	room maner till hid had goggamengen	Meter # 2: Radio
MXU #:		MXU #:
Current Reading 12/20/2013 646		Current Reading 0
Type of Meter: Badger	The control of the same of the	Type of Meter:
Year MFG: 1999	Marie and Marie	Year MFG:
GPS - Longitude 0		GPS - Latitude 0
Employee Signature(s):		Date Completed

WORK ORDER

Ti	ime Started	Maked Ingress - Maked resident and the No. 10	Work Complete		
Loc#		Master	Meter #	alle de la company de la compa	
Dat 1/31/2014	and the same of th	Account#	SEQ# 222		
Name: Tomn	ny Allen		Phone #		
Address:	eekwood Estates		Employee Tony Blevins	namer een ername spinsk	
lnez,	KY 41224				
	eekwood Estaates, 1st ho	ouse on right, new co			
Coldw				alan — Tarathan nagalandan Aldillana Quana	
Type of Work: 0	Complaints				
•		(love			
Customer Line I	nspection			.91	
Comments: Ext	remély low préssure	Pressure Is	·····		
Currer	it System Information:		New Information:		
Meter # 1:	29934735		Meter # 1:	· · · · A· · · · · ·	
Meter#2: Radio	V	Marcollope (175) glave de general estados de la constante de l	Meter # 2: Redio		
MXU #:			MXU #:		
Current Reading	12/20/2013 1127	n valanta ara ang a ra ang a	Current Reading 0		
Type of Meter:	Badger	**************************************	Type of Meter:		
Year MFG:	2004	·	Year MFG:		
GPS - Longitude		make any opposition of management the same to	GPS - Latitude	1 1 1	
Employee Signat	ture(s):		Date Completed 3.714		

WORK ORDER

	WO #	140100457	According to the second
т	ime Started	Work Com	plete
Loc#	. 100		
Dat 1/31/2014		Account #	
Name: Laray	a Fields		Phone # (
Address: P.O.E	BOX	rooff water was trong to transport year to be a great to the control of the contr	Employee Tony Blevins
INEZ	, KY 41224	And the state of t	
Location 1/4 m	ile on left.1st white double-w	ide on left.	
COL			
Type of Work: 0	Complaints,		
Material Used:	· ·	Die)	
Customer Line I	nspection		
Comments ext	remely low pressure	Phessure Better	
Currei	nt System Information:	and an agree of the contract o	New Information:
Meter # 1:	93749257	Meter#	1:
Meter # 2: Radio		Meter#	2: Radio
MXU #:	·	MXU#:	yelen regions and the particular and the second
Current Reading	12/20/2013 1153	Current	Reading 0
Type of Meter:	Badger	Type of	
Year MFG:	1993	Year Mf	FG:
GPS - Longitude	0	GPS - L	atitude 0
Employee Signa	ture(s):	Da	ate Completed 2.3.14

Wartin County Water District 387 East Main St., Suite 140

Inez, KY 41224

WORK ORDER

, Τ.	ime Started	Work Complete		
Loc#			ter#	
Dat 1/31/2014	and the state of t	Account#	SEQ# 198	
Name: Arlena	a Evans	ua a a. o. o. a. o.	Phone # /	
Address: P.O. I	The state of the s	12.00	Employee Tony Blevins	
	, KY 41224 Coldwater Rd. 3.2 miles on		riveway. Brown house w/brown tin roof.	
Type of Work: Continued of Work: Continued of Work Continued of Wo	nspection			
Currer	nt System Information:		New Information:	
Meter # 1:	33076070		Meter # 1:	
Meter # 2: Radio	33076070		Meter # 2: Radio	
MXU #:	A STATE OF THE THE PROPERTY OF THE		MXU #:	
Current Reading	12/20/2013 853	AN TERMEDAL PROPERTY.	Current Reading0	
Type of Meter:	Badger	ANNE CORNECTION AND COMPANY	Type of Meter:	
Year MFG:	2006		Year MFG:	
GPS - Longitude	0		GPS - Latitude 0	
Employee Signal	ture(s): KJ		Date Completed 2-3-14	

Maitin County Water Dist. Ct 387 East Main St., Suite 140

inez, KY 41224

WORK ORDER

Time Started		Wo	Work Complete		
Loc#	and a second	Master Meter #			
Dat 1/31/2014	and the state of t	Account#	SEQ# 271		
Name: ALBE	RT SMITH		Phone #		
Address: P.O.B	BOX		Employee Tony Blevins		
INEZ	, KY 41224		·		
Accessive	SSADY BR.	Dane			
Material Used:					
Customer Line	Inspection				
Comments: no	water pressure but	better nou	<u></u>		
Curre	nt System Information:		New Information:		
Meter # 1:	97354363		Meter # 1:		
Meter#2: Radio			Meter#2: Radio		
MXU #:			MXU#:		
Current Reading	12/20/2013 836		Current Reading 0		
Type of Meter:	Badger	ennellatura a Santa Santa	Type of Meter:		
Year MFG:	1997	**************************************	Year MFG:		
GPS - Longitude	0		GPS - Latitude 0		
Employee Signa	uture(s): RJ		Date Completed 2-3-14		

Ivertin County Water Dist. St

387 East Main St., Suite 140

WORK ORDER

WO # 140100443 Work Complete _____ Master Meter # Loc# SEQ # 110 Dat 1/31/2014 Account # Phone # i Jimmy Hensley Name: Address: Camp Br Employee Tony Blevins INEZ, , KY 41224 Location: Camp Br. Tan two tone trailer on the right. Camp Br Type of Work: Complaints: Material Used; Customer Line Inspection Comments: extremely low pressure a little better new **Current System Information:** New Information: Meter # 1: 47823736 Meter # 1: Meter # 2: Radio 47823736 Meter # 2: Radio MXU#: Current Reading 12/20/2013 405 Current Reading 0 Type of Meter: Sensus Type of Meter: 1993 Year MFG: Year MFG: GPS - Longitude 0 GPS - Latitude

Date Completed 2-3-14

Employee Signature(s): RJ

Neartin County Water Dist. 387 East Main St., Suite 140

WORK ORDER

Time Started		Work Complete
Loc#		ter Meter#
Dat 1/31/2014	Account#	SEQ# 115
Name: Paul Hensle	y	Phone #
Address: Camp	Branch	Employee Tony Blevins
inez, KY 41	224	
Location: Coldwater, (Camp Branch, about 1 on left, 2 tone	
Coldwater		
Type of Work: Comple	aints (1) an	
Material Used:		
Customer Line Inspec	tion	
Comments: extremely	1 44 10	n'ayas
Current Sys	tem Information:	New Information:
Meter # 1: 6701	2625	Meter # 1:
Meter # 2: Radio		Meter # 2: Radio
MXU #:		MXU #:
Current Reading 12/20	0/2013 186	Current Reading 0
Type of Meter: Sens	us	Type of Meter:
Year MFG: 2006		Year MFG:
GPS - Longitude		GPS - Latitude
Employee Signature(s)	· RJ	Date Completed 2-3-14

Inex, KY 41224

WORK ORDER

Time Started	Time Started Work Complete			
Loc#	Master Meter #			
Dat 1/31/2014		SEQ# 307		
Name: Aaron & Jackie Gauze		Phone #		
Address: P.O. Box		Employee Clyde Stanley		
INEZ, , KY 41224				
Location: 'Coldwater Rd				
Coldwater Rd				
Type of Work: Complaints				
Material Used:		re)		
Customer Line Inspection	4			
Comments: very low water pressure	Has go	sod paressure now		
Current System Information:		New Information:		
Meter # 1: 98604665		Meter # 1:		
Meter # 2: Radio 98604665		Meter # 2: Radio		
MXU #:		MXU #:		
Current Reading 12/20/2013 662		Current Reading 0		
Type of Meter: Badger		Type of Meter:		
Year MFG: 1998		Year MFG:		
GPS - Longitude 0		GPS - Latitude 0		
Employee Signature(s): 5		Date Completed 2 - 3 - 1 4		

Inartin County Water Dist...t

387 East Main St., Suite 140 Inez. KY 41224

WORK ORDER

WO # 140100451 Time Started Work Complete Loc# Master Meter # Dat 1/31/2014 Account # SEQ# 285 Name: ALBERT SMITH Jr. Phone # Address: COLDWATER RD Employee Tony Blevins INEZ, , KY 41224 Location: _____ Soldwater Rd COLDWATER RD. Type of Work: Complaints Material Used: Customer Line Inspection Comments: no water Customer has water tra to holese **Current System Information: New Information:** Meter # 1: 98985892 Meter#1: Meter # 2: Radio Meter # 2: Redio MXU#: MXU #: Current Reading 12/20/2013 199 Current Reading 0 Type of Meter: Badger Type of Meter: 1998 Year MFG: Year MFG: GPS - Longitude 0 GPS - Latitude 0 Employee Signature(s): 1.31.11 Date Completed 2-3-14

Iviartin County Water District 387 East Main St., Suite 140

Inez, KY 41224

WORK ORDER

140200101

		WO#	14020010	<u>1</u>	
	Time Started	*	Worl	Complete	
Loc#	Company and the same and the sa			#	
Dat 2/4	/2014	Acco	ount#	SEQ# 469	
Name:	TIM SIZEMORE			Phone#	
Address:	Tomahawk Rd.	,		Employee Justin	n Scott
	TOMAHAWK ,	KY 41262		···	
Location					
	ROUTE 40 WEST		.,		
Type of V	Work: Complaints				
Material I	Used:				
	r Line Inspection	_	($\overline{}$	
	its no water	/ (Y	plated		in caused pros
	Current System Infor	mation:	•	New Inform	ation:
Meter#1	98607414		M	eter # 1:	
Meter#2	: Radio		_ M	eter#2: Radio	
MXU#:			ħπ	XU#:	
Current R	Reading 12/20/2013 6	00	. C	urrent Reading	<u>o´`</u>
Type of M	leter: Badger		T	ype of Meter:	
Year MFC	S: 1998		_ Yo	ear MFG:	
GPS - Lo	ngitude 0		_ G	PS - Latitude 0	
	Signatura(s):	\mathcal{N}		Date Completed 2	14/14

Wartin County Water District 387 East Main St., Suite 140

Inez, KY 41224

WORK ORDER

W O #	140100488	o galanga mananananan
Time Started	Work Co	primplete
Loc#	Master Meter #	A Section of the sect
Dat 1/31/2014	Account#	SEQ# 319
Name: JOE STATON		Phone #
A. J. January B. Avilland Phys	. p	Employee Tony Blevins
MOLLETT BRANCH		
Type of Work: Complaints		ruy disaminahan angal da sana angal da sana angal da sana da sana da sana angal da sana da sana da sana da sana
Material Used:	T	•.
Customer Line Inspection	1)Over	
Comments: extremely low pressure	tas 40 751	- At box
Current System Information:	99 <u>99999999999999999999999999999999999</u>	New Information:
Meter # 1: 97354329	Meter	#1:
Meter # 2: Radio		# 2: Redio
MXU#:	<u></u>	#:
Current Reading 12/20/2013 1058		nt Reading 0
Type of Meter: Badger	Туре	of Meter:
Year MFG: 1997	Year	MFG:
GPS - Longitude 0	GPS -	- Latitude 0
Employee Signature(s):		Date Completed 2 - 4 - 14

N.L. tin County Water Dist. Lt

387 East Main St., Suite 140 inez. KY 41224

WORK ORDER

	Time Started	v	Vork Complete	
Loc #		Master M	eter#	
Date 2/12/20	14	Account #	SEC	Q# <u>474</u>
Name: Joi	nn Curtis Kirk		Phone #	
Address: P.0	D. Box			
Ine	z, Ky 41224			
Location:	: Eden West, Last residence	e on hill.		
	· Eden West		(n)	
Type of Worl	c: Complaints		Vone	
Material Use	d. Pulphone	grand	-	7 1:1
Customer Lir	ne Inspection	also	ready had	grand put dans
Comments:	customer needs gravel put c	down, they were remov	red when tap was put i	n
Cui	rent System Information:	entered to block of a control of the	New	Information:
Meter# _. 1:	98003080		Meter # 1:	Man and the same of the same o
Meter # 2: Ra	dio 98003080		Meter # 2: Radio	
MXU#:			MXU #:	
Current Read	ling 1/20/2014 334		Current Reading	0
Type of Mete	r: Badger	the state of the s	Type of Meter:	
Year MFG:	1998	<u>-</u>	Year MFG:	
GPS - Longite	ude <u>'</u>	and an analysis of Ass.	GPS - Latitude	
Employee Sig	gnature(s): 55, RJ	_	Date Complete	d 3-24-14

Martin County Water Dist...t

387 East Main St., Suite 140 (nez, KY 41224

WORK ORDER

140300177 WO# Time Started Work Complete Master Meter# Loc# SEQ # 288 Date 3/24/2014 Account # Phone # Niki J. Boyes Name: Buffalo Horn Address: Louisa, Ky 41230 Location Buffalo Horn Rd. About 1 mile on left. White trailer down over hill after you pass small graveyard. ਰuffalo Horn Rd Type of Work: Complaints Material Used: Customer Line Inspection how after he calle back on about Comments: NO WATER / **Current System Information:** New Information: Meter#1: 70840680 Meter#1: Meter # 2: Radio 70840680 Meter # 2: Radio MXU #: MXU#: ______ Current Reading 2/20/2014 153 Current Reading 0 Type of Meter: Sensus The second secon Type of Meter: 2012 Year MFG: Year MFG: GPS - Longitude _____ GPS - Latitude

Date Completed 3-26-

Employee Signature(s):

Iviartin County Water Dis ct

WORK ORDER

Ti	Time Started Work Complete		Work Complete		
Loc#	and the state of t		Master Meter #		
Dat 3/14/2014		Account#	SEQ# 158		
Name: NOAH	I WEBB		Phone# (
Address: PO Bo	XC		Employee Jason W.		
LOVE	LY KY 41231				
Location	N Wolf Crk Lovely 1714. F	irst house on left on	Webbville.White 2-story. N. Wolf Creek		
Type of Work: O	nspection	Flushe			
,	nplaints of air in line, need	s flushed			
	nt System Information: 74604138		New Information: Meter # 1:		
Meter#1: Meter#2: Radlo	and the second s				
MXU#:	1/002318		Meter # 2: Radio MXU #:		
	2/20/2014 38		Current Reading 0		
Type of Meter:			Type of Meter:		
Year MFG:			Year MFG:		
GPS - Longitude			GPS - Latitude		
	R.T		7 - 14m W		

Imartin County Water Dis...ct

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO #



Time Started Work Complete			no compagnion may	
Loc#		Master Meter #		
Dat 3/14/201	14	Account #	SEQ#	158
Name: NO	AH WEBB) (
Address: PO	BOX.	y gamadannangariya laidahaliya anna yandid	Employee Ja	ason W.
LO\	VELY , KY 412	231	The part of the state of the st	
Location:			on Webbville.White 2-story.	
Type of Work				
Material Used				
Comments: c	omplaints of air in line,	needs flushed		<u> </u>
	rent System Informati		New Info	
Meter#1:	74604138		Meter#1:	
Meter # 2: Rad	ю 74604138		Meter#2: Radio	
	14002218		MXU #:	
Current Readi	ng 2/20/2014 38		Current Reading	0
Type of Meter			Type of Meter:	
Year MFG:			Year MFG:	
GPS - Longitu	de	Market State Control of the State St	GPS - Latitude	
Employee Sig	nature(s):		Date Completed 3	-19-14

WORK ORDER

Time Started	V	Work Complete		
Loc#	Master M	Master Meter #		
Date 3/10/2014	Account #	SEC	2# 48	
Name: Landon Jude		Phone #		
Address: P.O. Box				
Inez, KY 41224		markets a state of the Control of th		
Location: E Main St, Inez, last	house past pawn shop, whit	te w/green shutters, ne	ext to empty lot	
₃ E Main St				
Type of Work: Complaints				
Material Used:				
Customer Line InspectionComments: complaints of extreme		• • • • • • • • • • • • • • • • • • • •		
Current System Informa	ation:	New	Information:	
Meter # 1: 70616368		Meter#1:	and the second s	
Meter # 2: Radio 70616368		Meter # 2: Radio		
, MXU #: 14440339		MXU#:		
Current Reading 2/20/2014 23	- A SE TRANSPORT OF THE SECOND STATE OF THE SE	Current Reading	0	
Type of Meter:		Type of Meter:		
Year MFG:	, <u> </u>	Year MFG:		
GPS - Longitude		GPS - Latitude		
Employee Signature/s)		Date Complete	a 3 1714	

WORK ORDER

WO # 150700198

Ti	ne Started Work Complete					
Loc#			Master Mete	er#	9 7 4	. 3
Date 7/28/2015		Accou	ınt#	SE	Q# 202	.
Name: Steph	anie Tackett		t district s	Phone #		j ve
Address: N	Wolf Crk Rd			Employe	e Justin Scott	
Pilgrir	n, Ky 41250		in count of many			
Location: N	Wolf Crk Rd.	1/4 mile from Pigeon	Roost comm	unity center. White h	nouse on the left wi	th green
IUU) o	shutters	25 m 2 24 2 4 m		•••		ing proper proves
. N	Wolf Creek F	RD.				
Type of Work: 0	Complaints	49 N AAA N			* * * *	, , , e e e
Material Used:			•	w 1	.	* ** 4
Customer Line I	$\tilde{\mathcal{Q}}$	stopped uf	> 8/ C	Lustman's	sole	
Curre	nt System Inf	ormation:		New	Information:	
Meter # 1:	96982418	e a su prima	ľ	Vieter # 1:	t 1	; •
Meter # 2: Radio	96982418		ſ	Meter#2: Radio		
MXU #:	د ۾ دم	•	1	MXU#:		
Current Reading	6/20/2015	1168	(Current Reading	, o	
Type of Meter:	Badger	я	-	Type of Meter:		
Year MFG:	1996	•	•	Year MFG:		
GPS - Longitude	:		(GPS - Latitude	,	,
Employee Signa	ature(s): $\mathcal K$	ゴ ブ		Date Complete	ed 9 -2	9-15

WORK ORDER

WO #

time Started		vvork Complete	ALC SWEE BOARD
Loc#	Maste	r Meter#	- v. v.
Date 7/28/2015	Account# -	SEQ:	# 397
Name: PAUL MORRISON	e	Phone #	<u> </u>
Address: PO BOX		Employee	Troy Horn
INEZ , KY 41224	a marana any	2000 200 20	**** • /• · ·
Location: Across from Venters Branch.Little	grey house on l	eft. 3428 New Rt 3	
		w w t investigation or	
NEW RT 3	poli em ve	and particularly and the second	
Type of Work: Complaints	t w we produce.	ayunninganiya a A. M. B. M. ESS - KD 20	i vy y gyman za za za za z
Material Used:		*** * *********************************	
Customer Line Inspection			
Comments: air in the lines	Blew o	FF lim	1
Current System Information:	ئاد ئىلىدىدى بىرىكىدى ئادى ئادى ئادى ئادى ئادى ئادى ئادى ئ	New In	formation:
Meter # 1: 29934564	im > +	Meter # 1:	v, v
Meter # 2: Radio		Meter#2: Radio	
MXU#:		MXU #:	
Current Reading 6/20/2015 495	•	Current Reading	,0
Type of Meter: Badger		Type of Meter:	
Year MFG: 2004		Year MFG:	
GPS - Longitude 0		GPS - Latitude 0	
Employee Signature(s):	, ,,,,	Date Completed	7-2815

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO #

150700144

Time Started

Year MFG:

GPS - Longitude

2006

Employee Signature(s): (5

Work Complete

Year MFG:

GPS - Latitude

Date Completed 7-27-15

Loc# Master Meter # Date 7/20/2015 Account # ^ *** SEQ # 237 Name: Dahryl Keller Phone # 🛴 Address: . Setser Br Employee Troy Horn Inez, Ky 41224 Location: Setser Br. Wood sided house @ end of road Setser Br Type of Work: Complaints Material Used: **Customer Line Inspection** Comments: as extremely low water pressure **Current System Information:** New Information: Meter#1: 33076067 Meter # 1: Meter # 2: Radio 33076067 Meter#2: Radio MXU#: MXU#: Current Reading 6/20/2015 311 **Current Reading** Type of Meter: Badger Type of Meter:

Martin County Water District 387 East Main St., Suite 140

Inez, KY 41224

WORK ORDER

WO #

Time Started Work Complete		and a s	
Loc#	Master	Meter#	, where , has
Date 7/1/2015	Account #	SEQ # 12	1
Name: Charles Tipton	and the second s	Phone # (нарыят разу
Address: P.O. Box	s supplying on the state	Employee Raj	nbo
INEZ , KY 41	224]	•	
Location: Boone Br of Eli Rd	; last house in hollow; box is	on BANK IN FRONT	
management and a set for the set of Administration		Andrew Communication and the communication of the c	المراجعة في مستخدم المراجعة المستخدمين
BOONE BR.		•	•
Type of Work: Complaints	and a supplementary of the same of the stages of the same, and the same of the same of the same of the same of	na managanan salaman managangan managan salah	۱۹۸۸ و د ده که این میرود انستومو موسودونو
Material Used:	(D)		والمعود الإنجار المستحدد والشيار والشراء والشراء
Customer Line Inspection:	0014		
Comments: had extremely low p	ressure for a week	apsI At 6	· a.X.
Current System Infor	nation:	New Infor	nation:
Meter # 1: 99691122	ma ^{rt} eg any annue gap Webbe au e é é vivale à de	Meter#1:	e angles a la l
Meter # 2: Radio	. See a ware	Meter # 2: Radio	e consegue see pant é T 24 Metros s
MXU #:	2	MXU #:	was sample and the same of the
Current Reading 6/20/2015 52	20	Current Reading	
Type of Meter: Badger	garage also	Type of Meter:	g maritis made and des
		Year MFG:	and the second of the second o
GPS - Longitude 0		GPS - Latitude 0	
Employee Signature(s):	, g up e peradukana men	Date Completed	2-23-195

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 150700	037
Time Started W	/ork Complete
Loc# Master Me	eter#
Date 7/6/2015 Account #	SEQ # 117
Name: James Williamson	Phone #
Address: Poplar Frk Rd	Employee Rainbo
BEAUTY KY 41203	
Location: Lower Poplar Frk, top of hill, 2nd drive on right,	green double wide
	the state of the s
ELK CREEK	`
Type of Work: Complaints	
Material Used: Irad a line inter an	I the tank went Empty.
Customer Line Inspection Still be got west	I sow we fix the
Comments: no water line ser Sunda	Y
Current System Information:	New Information:
Meter # 1: 47823585	Meter # 1:
Meter # 2: Radio	Meter # 2: Redio
MXU #:	MXU #:
Current Reading 6/20/2015 719	Current Reading 0
Type of Meter: Sensus	Type of Meter:
Year MFG: 1993	Year MFG:
GPS - Longitude 0	GPS - Latitude 0
Employee Signature(s): J5, C5, RJ.	Date Completed 7-6-15

Inez, KY 41224

WORK ORDER

WO#

Time Started	· ·	Work Complete
Loc#	Master M	leter#
Date 7/9/2015	Account #	SEQ # 107
Name: Kirby PREECE	و پرسر	Phone #
Address: PO BOX		Employee Rainbo
INEZ , KY 41224		·
Location: Howard Spence Rd, Afte	r crossing Inez hill,1st di	rive on left up on hill.Tan trailer
ROUTE 40 WEST		the second of th
Type of Work: Complaints	2 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	· Administration of the state o
Material Used:	,	يونوائه من يرينه بمواق يدين و يرويا سيست
Customer Line Inspection: \(\sum_{\alpha \in S} \)	water now	manana and a same and
Comments: customer has no water	u wa din kwamina Wijel Ang	
Current System Information		New Information:
Meter # 1: 90819244		Meter # 1:
Meter # 2: Radio	· · · · · · · · · · · · · · · · · · ·	Meter # 2: Radio
MXU #:	···· ,	MXU#:
Current Reading 6/20/2015 1536	• •	Current Reading 0
Type of Meter: Badger		Type of Meter:
Year MFG: 1990	••	Year MFG:
GPS - Longitude 0	* 54	GPS - Latitude 0
	- 90	
Employee Signature(s):	,	Date Completed

WORK ORDER

Time Starte	d	Work Complete		
Loc#	. Master	Meter#	p. A19	; more discount
Date 7/13/2015	Account#	SEQ#	108	••
Name: MARY STANLE Address: PO Box WARFIELD	p and k understand the second of the second	Phone # (Employee T		ar arch
Location: Stanley Dr		Windows 2 pay on Man South	*****	••
Type of Work: Complaint	S	eg ve macesmen en mangement des	·	◆····turify) Min.
Material Used:	entral and proper statements		_	, an
Customer Line Inspection Comments: no water	was pumping into	Elle Creek a it to	ok their pres	sure down
Current System		New Info	ormation:	
Meter # 1: 706166	08	Meter # 1:	.,	iv:
Meter # 2: Radio	an on a suppose say well be to	Meter#2: Radio		·
MXU#: 131549	28	MXU #:	y a ga ga ga ga a ga a ga a ga a ga a g	للا معلومة أحوا
Current Reading 6/20/20	15 353	Current Reading	0	3 ,1 ≥ 9
Type of Meter:	No. A region of the control of the c	Type of Meter:	•••	
Year MFG:	The specific to the specific to	Year MFG:		
GPS - Longitude	ty a comment to the comment	GPS - Latitude		
Employee Signature(s):	TH	Date Completed	7-13-15	e o e

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Tin	ne Started		Work Complet	le	
Loc#	1.4.5.5 = 25 4.5.5	Maste	er Meter#	No. of Charles decreases in	graph and the second
Date 7/2/2015	e annual term and the first	Account#	فمستفسد منجوية الكاسي	SEQ# 96	a p a ac comment
4		and the second s	v mi - to m	Phone # Employee Rainbo	and the second s
	ELL BRANCH	gy ignispries in NE		,	edistración (n. 1) 1 a militario (n. 1) 2 a militario (n. 1)
Type of Work: C	complaints	Da	L		e wilderending some a
Material Used:	*** ****** * *	g a semanamente a a e e		, b. document the	mana a compositivo de la Prima de la Pr
Customer Line In Comments: no V		ressure	uco a	F#153	
Currer	nt System Information:	ngung ng ng gan adahalana nnunun sus	in the community decision of A	New Information	1:
Meter # 1:	29541979	4 - a washing wood	Meter#1:	ignorum di Mark di Noru	
Meter#2: Radio	29541979	alam de production managed (p. 1.5.5)	Meter # 2:	Radio	Make Box 18 4 Add No. or
MXU #:	ساماة وتتعطيبية		MXU #:	ar sewe we were a second	a and a second
Current Reading	6/20/2015 457		Current Re	eading 0	and the second of
Type of Meter:	Badger	₩ ₩7.25.	Type of Me	eter:	
Year MFG:	2004	a y a y waarinaa	Year MFG		g g wage and also
GPS - Longitude	e 0		GPS - Lati	tude 0	na managa ya na
	iture(s): R.T	والمستعددة والم	 Date	Completed 7	2-15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

Time Started	George George China State	Work Complete	ရှ အစု အ <u>စိုး မှတ်၏။ မ</u>	
Loc#	Master .	Meter#	EA PAR MARKETER VEV VIEV 1	an a scoren
Date 8/19/2015	Account#	SEC	2#7	adh F N
Name: William Scott	» دوم الله الله المستعدد عارضا	Phone #	1	المراجعة
Address: P.O. Box	nay managaman kalaban din 43 No. 190 Mary 1975 - 1975	Employe	e Justin Scott	54.5
Inez, KY 41224	is any anyony specific any any single and any any	i de la		
Location: Newberry Ln. Inez. S	late colored house on the I	eft.	unau jai paparijanar tyder	ne programa de la compaña de l
ewberry Ln		man and a second	Anazaki ing Pang 1446 - 1	grane westing
Type of Work: Complaints	ma sampan managan naga sampan naga sam	The second section is a second	No approximate (ψεταράθει και ² εκ	i. Lemma dishing St. 2-26.
Material Used:	1.01		ayunan angsi sa - sy is - sesampi a amasa a	த 631 காலில் கள்
Customer Line Inspection	147 necx 1		agadan hangandan ing dia 1901 tini dia mangan	mand and the Comment
Comments: customer said water	stank	معلست مستسفده سيستان مديده والمراجع والموسية	15 (× 900000) promote site of 0	s. del signistiques s's res ; mis
Current System Inform	ation:	New	Information:	g 2 south of 2 south of 4
Meter # 1:	ala san san dala dalaman ya panangia dalamada	Meter # 1:	randonto no francisco amendo de la constante d	James of prints of the second
Meter # 2: Radio	was all the second seco	Meter # 2: Radio	nag a Southern nagylynnodding (Southern nagynnag Ed	- in a separate of
MXU#:	pr og grape determinetalentering	MXU #:	and the second s	g sammand different
Current Reading 0	 iii. The second statement and the control of the cont	Current Reading	O	www.noojen.n
Type of Meter:	www.www.www.www.ww.co.co.co.co.co.co.co.co.co.co.co.co.co.	Type of Meter:	, ya yangid kana mua a A	\$ 4 4 W W
Year MFG:	denial simulation interview of	Year MFG:	a in Section Administration is should be \$2.00.	and a separate
GPS - Longitude	The second secon	GPS - Latitude	, ann gamanan ar A − A − Ψ S	रज्ञकारक संभागी का
Employee Signature(s): 15	, grae	Date Complete	ed 8-25	<u> </u>

WORK ORDER

WO#

Time Started	Work Comple	te
Loc#	Master Meter #	100 m to 100 m
Date 8/11/2015	Account #	SEQ# 82
Name: John Glass	ال هميك علا مود	Phone #
Address: P.O. Box Nagatuck, WV 25685	n tittleftengum nave en sin. 8	Employee Justin Scott
Location: Maple Dr. 1st house on left.	Brown double-wide w/chain link fe	ence.
Maple Dr	a disease a second process of the second pro	A strongenium to the transfer of the transfer
Type of Work: Complaints	in the second second	g nyamitan on also k - go kong ne promi r - r N - A 187922 Y
Material Used: Customer Line Inspection	Stall)	A summanarian or summanarian 6 - 5
Comments: water is milky white	(1) 400	and engineery was a specimen of the contract o
Current System Information:	de placellose mensione e odo o regionalis de odo	New Information:
Meter # 1: 94261289	Meter # 1:	्रे प्रमुख्यासम्बद्धाः । । । । । । । । । । । । । । । । । । ।
Meter # 2: Radio 94261289	Meter # 2	Radio
MXU#:	MXU #:	inggi glida san sa
Current Reading 7/20/2015 2260	Current R	eading 0
Type of Meter: Badger	Type of M	leter:
Year MFG: 1994	Year MFG	d company physiques that their their
GPS - Longitude	GPS - La	titude , , , , , , , , , , , , , , , , , , ,
A	Se No. 100 No. 100 P	491 - 611 (694
Employee Signature(s): 55	Date	Completed 8 20-25

387 East Main St., Suite 140 inez, KY 41224

WORK ORDER

WO#

Tir	me Started	Work Complete			
Loc#		Master M	eter#		(of 120ds sometimes
Date 8/19/2015	are comment of the dead of	Account #	خاصفات خاصمات	SEQ# 242	
Name: Billy Ha	ammond	, sianga mpandanan mas	Phor	ne#	Secretaria de la Caración de la Cara
Address: PO Bo))		Emp	loyee Justin Scott	
Warfie	ld, KY 41267	w	# 18* * * * * * * * * * * * * * * * * * *		
Location: App. 1	mile, blue house on hill.	Sheppard Ln			 ,
SPEN	CE BR	000			400,000
Type of Work: C					s oo :
Material Used:	23"slip,	5 ft of.	31'Line		e spakate
Customer Line Ir	' /		1		
Comments: cust	omer reported Sheppard	Lane is without water	State bro	oke Main while c	peavina
Curren	t System Information:	v shin krahov ^o i žu <u>i žu į unimoves di pa v</u> —	A AMERICAN (CONTRACTOR CONTRACTOR)	lew Information:	;
Meter # 1:	29934524	AT	Meter # 1:	and the second s	4
Meter#2: Radio			Meter # 2: Radio	a constitution of the constitution of	e wh
MXU#:			MXU#:	and the second second	40
Current Reading	7/20/2015 884		Current Reading	0	*
Type of Meter:	Badger	w . we	Type of Meter:	g angalist is an amanan an a	com (by m
Year MFG:	2004	May dan sh	Year MFG:	and the second s	
GPS - Longitude	<u>0</u>	····• (GPS - Latitude	<u> </u>	i
Employee Signat	ture(s): TH, C5,	TM	Date Comp	oleted &-26-15	,

WORK ORDER

WO#

Lir	ne Started	, W	ork Complete	annual aire e un un un
Loc#	No. 1995 W. Stagest	Master Me	eter#	
Date 8/11/2015		Account #		SEQ # 234
Name: Billy G	reer		Pho	ne#
Address: P.O. B Lovely	ox - KY 41231	pite display to the same security	Emp	oloyee Troy Horn
y mangaman in a sa	Riverfront Rd. Past Jackie & A	Alice Scott.	e mineral de l'Alberta e la seconda de l'Alberta e la seconda de l'Alberta de l'Alb	g adapt for the first transfer to the first transfer transfer to the first transfer tr
Type of Work: C	complaints			and the second second and the second
Material Used: Customer Line In	water of the formation of the second of the	,,;		e a manuar de la m
Comments: low	pressure for over a week	· Zo pert.	14-6-15	i u projementa sija menden sija mojeka e as
Curren	it System Information:	## hamman		New Information:
Meter#1:	33001041	A A V Sades	Meter # 1:	e
Meter # 2: Radio	33001041	· ••••	Meter # 2: Radio	way a samual solid and the second second second and the second se
MXU#:	A manner of an commentation of successions	▼ m·y	MXU#:	Openium (C. 1940 - L. A. physiological generality of the conference of the
Current Reading	7/20/2015 183	ւարում և առաջան գո	Current Reading	0
Type of Meter:	Badger	r umimm	Type of Meter:	may what the second proportion of the second
Year MFG:	2006		Year MFG:	المستعدد الم
GPS - Langitude	r part of subspace to a suppose the suppose		GPS - Latitude	TO PICE OF MALE IN THE WAY OF THE COMMISSION OF THE SECURITY SECUR
Employee Signa	ture(s):	manuse and a first formation of the second	Date Comp	oleted O

WORK ORDER

WO # 150800085

I line Started V	vork Complete
Loc# Master M	eter#
Date 8/6/2015 Account #	SEQ # 595
Name: Maurice & Rita Milis	Phone #
Address: 3 Rockhouse Road	Employee Justin Scott
Tomahawk , Ky 41262	* AA 1
Location: Mills Lane, 1st house, meter on right of driveway, bes	ide fence 3 Rockhouse Road
A 15 to a continue of the cont	and the second of the second o
Rockhouse	A STATE OF THE STA
Type of Wark: Complaints	orkganan k hilk ot by galandamanan han magi yapı onk hamin k ni'n bi olu olu
Material Used:	en e
Customer Line Inspection:	الما المحادث المحادث المادين والمستسود واستوري الم
Comments: requested a flush, water stinks //4 5hcc/	L'ne
Current System Information:	New Information:
Meter # 1: 96725763	Meter # 1:
Meter # 2: Radio	Meter#2: Radio
MXU #:	MXU#:
Current Reading 7/20/2015 1550	Current Reading 0
Type of Meter: Badger	Type of Meter:
Year MFG: 1996	Year MFG:
GPS - Longitude 0	GPS - Latitude 0
Employee Signature(s):	Date Completed 8-11-15

WORK ORDER

WO # 150700200

Time Started	. Wo	ork Complete
Loc#	Master Met	er#
Date 7/28/2015	Account #	SEQ # 158
Name: DAVID MARCUM		Phone # 1
Address: Calf Crk	ja va juandus	Employee Justin Scott
Inez, Ky 41224	. I nd ddearmini e n	and a second
Location: Calf Crk, 1st house on k	eft, white w/black shutters	used to be there now going to be putting a
CALF CRREK	A spine trade (1)	
Type of Work: Complaints	i partife or every many on a non-	many distinguish as the second of the second
Material Used:		
Customer Line Inspection	Checked	Pressure, Read over 100gs;
Comments: pressure is low and very n	nilky Checked for	L. Pressure, Read over 100gs; x. Milky. water, more visible at
Current System Information	1:	New Information:
Meter # ,1:		Meter # 1:
Meter # 2: Radio		Meter # 2: Radio
MXU #:		MXU #:
Current Reading 0	,	Current Reading 0
Type of Meter:		Type of Meter:
Year MFG:		Year MFG:
GPS - Longitude		GPS - Latitude
Employee Signature(s):	· . TS	Date Completed 8/3//5

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

150700185

	WO #	7 150700	J.102		
Tim	ne Started	V	Vork Comple	ite	
Loc#		Master M	eter#		• w a -
Date 7/27/2015	,	Account #		SEQ#	98
Name: HAROL	D GOBLE			Phone #	
Address: P.O.BO	X , KY 41224		A.V.	Employee	Justin Scott
- -	li Rd .EFORK RD.			,	
Type of Work: C	omplaints	er Alexand	րայաց *մ	.du	
Material Used: Customer Line Ir Comments: very	nspection 74 (1) low water pressure	psIAf	604		
Curren	t System Information:) v v	io g	New Inf	ormation:
Meter#1:	92701640	,	Meter#1:		* · · · · · · · · · · · · · · · · · · ·
Meter # 2: Radio	₩.	.*	Meter # 2:	Radio 🔻	 -
MXU #:	• -		MXÙ #:		
Current Reading	6/20/2015 1420		Current Re	eading	0
Type of Meter:	Badger		Type of Me	eter:	
Year MFG:	1992		Year MFG	:	
GPS - Longitude	· 0		GPS - Lati	tude 0	•

Employee Signature(s): 55

Date Completed 8-3-15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

₩O#

150700188

Time Started	Work Complete		
Loc#	Master M	eter#	_ •
Date 7/27/2015	Account#	09.40× man.8×	SEQ# 20
Name: Sherry Moore		F	Phone #
Address: P.O. Box Lovely, KY 41231	e a manage	egilar in A went dan sek	Employee Justin Scott
Location: Locust Crt. 1st house of	on the right.	Lander was	· -
Locust Crt	and a second of the second of	atribación acusa es se una acidique se sere se	· · · · · · · · · · · · · · · · · · ·
Type of Work: Complaints	ngar yi Sa kilaman	نستخبر خ تعد ■	egas
Material Used:	na way wide sa e s = s	• v≥+ov o · · · · · · ·	و و و د د م
Customer Line Inspection	Gara y we be see as	i an E. Saparate	×eαφim− ↓× ·
Comments: has bad odor to water	Re doing a	11/4.	line on bay star
Current System Informat	Argenny on the dear of the section	До финульской рук, — Горония	New Information:
Meter#1:	الإخراج مواد يوسع	Meter # 1:	s Santa
Meter#2: Radio	e di Andro di	Meter # 2: Ra	adio
MXU#:	- 4 · · -	MXU#:	mark of the growth
Current Reading 0	W - K/W -	Current Read	ding 0
Type of Meter:		Type of Mete	er:
Year MFG:	er er	Year MFG:	,
GPS - Longitude		GPS - Latitud	de ,

Employee Signature(s): JS/TH-CS/AS/55 Date Completed 8-3-65

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Tir	me Started	ν,	Vork Complete	
Loc#	and the second of the second o	Master M	eter#	e er om brom swaan
Date 8/5/2015	-	Account#	SEQ# 473	es par e a moneral
Name: Mary N	M FITCH	composers produce a produce a	Phone # (- arommor shor
Address: C k	bb's Lane	a gradiomica ils sur to dispose	Employee Justin	Scott
INEZ	KY 41224]		، بالمنت	
Location: A	bs Ln LEFT FORK.4th ho	use.White w/blue sh	utters.	•
	but a harmonia . A mapped and		n m. Asia bara aman b. Conta pandamin a Albania.	e a summer is Augmanusement
ABBS	LANE	reported the Carter Schools (1999) and in July and	en e	angere e en
Type of Work: C	complaints			
Material Used:	- company and a summer			er k vasamet menerel jag bendande
Customer Line Ir	nspection:	VOI		
Comments: extra	emely low pressure 7	3 + 78 p	SI At box	
Curren	t System Information:	,	New Informa	tion:
Meter # 1:	94056605		Meter # 1:	and the same
Meter # 2: Radio	de und al delivery of Administration in the contract of the co	programs =	Meter # 2: Radio	I daniminate a mannana muni
MXU#:	age as we a secure of the secu	et market de la constant de la const	MXU#;	والمعتقد المستدين والمستدان والمستدا
Current Reading	7/20/2015 849		Current Reading	0
Type of Meter:	Badger	yourne w.Y. Ch. oph	Type of Meter:	ner d'un gagenne y gentre de vener
Year MFG:	1994	· way hotel	Year MFG:	and the second
GPS - Longitude			GPS - Latitude 0	e a managaman a a a a sun a a a a a a a a a a a a a a a a a a a
Employee Signat	rure(s) 5		Date Completed &-	5-15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

AAO

WO# 150800088

Loc# Master Meter # Date 8/6/2015 Account # SEQ # 218 Name: Miranda McCoy Phone # (Address: P.O. Box Employee Rainbo Beauty, KY 41203 Location: Big Elk Rd. Across from Water Tower, grey trailer	
Name: Miranda McCoy Phone # (Address: P.O. Box Employee Rainbo Beauty, KY 41203	
Address: P.O. Box Beauty, KY 41203	
Beauty, KY 41203	
A CONTRACTOR OF THE PROPERTY O	
I costion: Big Elle Del Apropa from Metas Toures, growtesiles	
Location: Big Elk Rd. Across from Water Tower, grey trailer	
1) and	•
Big Elk Rd	
Type of Work: Complaints tack 2 case of gal. = 8 gall	
Material Used:	··· -^
Customer Line Inspection:	
Comments: customer has no water Reds water	i som
Current System Information: New Information:	s Zger ♥
Meter # 1: 29935189 Meter # 1:	ła;
Meter # 2: Radio 29935189 Meter # 2: Radio	min.
MXU#: MXU#:	4
Current Reading 7/20/2015 397 Current Reading 0	
Type of Meter: Badger Type of Meter:	
Year MFG: 2004 Year MFG:	graer-
GPS - Longitude GPS - Latitude	at he
Employee Signature(s): RT	-

Martin County Water District 387 East Máin St., Suite 140 Inez, KY 41224

WORK ORDER

WO # 150800093

Time Started	Work Complete
Loc#	Master Meter #
Date 8/7/2015 A	ccount# SEQ# 99
Name: Ronnie Mills	Phone # \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
Address: PO Box Inez, KY 41224	Employee Rainbo
Location: 5.8 miles up Turkey, turn left at Fire I house TURKEY	Dept, appr. 1 mile on right, 2nd house on Meadow Lark Lanee, fan
Type of Work: Complaints	، معقود د معمومسرهم بعد و موجه سا و دده مرسههای سووانشت
Material Used:	Announcements are majory a references and the second secon
Customer Line Inspection \\ \OO \(\text{PSi} \) Comments: no water	@ look ; issue on costomer's side
Current System Information:	New Information:
Meter # 1: 99691595	Meter # 1:
Meter # 2: Radio	Meter# 2: Radio
MXU #:	MXU #:
Current Reading 7/20/2015 401	Current Reading 0
Type of Meter: Badger	Type of Meter:
Year MFG: 1999	Year MFG:
GPS - Longitude	GPS - Latitude
Employee Signature(s): TS TS	Date Completed 8/7/\S

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

150200011

WO#

COMPLETE

Time Started		Work Complete		
Loc#		Master Meter#		
Date 2/3/2015		Account#	SEQ #	‡ 400
Name: JIM W	нгт		Phone #	
Address: P.O.BO	OX	•	Employee	Clyde Stanley
TOMA	HAWK , KY 41262		merchanovský	
Location: Sh	irley Moore Ln			
ROUT	E 40 WEST			
Type of Work: C	complaints	$(J)O\lambda$	3.e.	
Material Used:				
Customer Line I				
Comments: cus	그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그			e/Drain Looke
-FIAC			<u></u>	nformation:
	nt System Information:	Nac	eter#1:	
Meter # 1:	29935046			A. 450 9 10 10 10 10 10 10 10 10 10 10 10 10 10
Meter#2: Radio		Me	eter#2: Radio	
MXU#:			(U #:	
Current Reading	1/20/2015 291	Cı	rrent Reading	0
Type of Meter:	Badger	Ту	pe of Meter:	*
Year MFG:	2004	Ye	ar MFG: .	·
GPS - Longitude	e <u>0</u>	G	PS - Latitude 0	
Employee Signa	ature(s): 55, T/4,	000	Date Completed	9-25-15

Martin County Water District 387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#



Time Started	work Co	Work Complete			
Loc#	Master Meter #	والمستورة والمراجع والمراجع والمراجع والمراجع والمراجع			
Date 9/18/2015	Account #	SEQ# 69			
Name: DEBBIE DIALS	g a se table - management - with the	Phone # (
Address: Russell Workman Rd	مدالات المستقد	Employee Rainbo			
LOVELY KY 412	231				
Location. Russell Workman Rd	of 292.Long Branch.Russell Work	man Rd.Go right up on hill.Last house.			
The foregoing area of the second of the seco	where me we adoption to the file Specime among the file is	and an area of the second of t			
e e e e e e e e e e e e e e e e e e e	ne en a a a a a a a a a a a a a a a a a	100 110 110 110 110 110 110 110 110 110			
Type of Work: Complaints	A Court)			
		= 1.0			
Material Used: Not	ar in le	he blow it aff			
Customer Line Inspection:	و کا دید معقصد مشار در کا دید و در در دارد در د	orași argument proposationi de compressioni de			
Comments: no water	, market (1)	je i kanadanim po po po 1995. godina 1995. g			
w. se side S	ما في الله الله المستحد الله الله الله الله الله الله الله الل				
Current System Informat		r#1:			
Meter # 1: 19667238	angunggapan an an pulabara Tipiga j	de su destruit de C.C. W			
Meter # 2: Radio	. " "	r#2: Radio			
MXU #:	The state of the s	#: nation in a proportion of a last			
Current Reading 8/20/2015 611	Curre	ent Reading 0			
Type of Meter: Sensus	Type	of Meter:			
Year MFG: 1966	Year	MFG:			
GPS - Longitude 0	GPS	- Latitude 0			
	egintagende e egint mende men ≠	9 18 10			
Employee Signature(s): //	_	Date Completed 9-18-15			

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#



Time Started	Wor	Work Complete			
Loc#	Master Mete	Master Meter #			
Date 9/15/2015	Account #	SEQ # 220			
Name: Miranda McCoy	and the second s	Phone #			
Address: P.O. Box	and the second s	Employee Justin Scott			
Beauty, KY 41203	a have been seen to be a seen and the seen as the seen				
		Samuranan managanan yan orak esan 1883 - 1807 yan sebingi meni seperangan meningi.			
manadadaminintatatata ya mata waka waka waka waka waka waka waka w	man and a very and a very and a very	The sign constraints and the second constraints are second constraints.			
_ Big Elk Rd	· · · · · · · · · · · · · · · · · · ·				
Type of Work: Complaints	rija - ar , numanik minimi mimimimimikokokok dirista ahdid Tilgil (1870).	and the second of the second o			
Material Used:	New you the second-language of wave were not to the second-language of the second-language	anniannianniannianniannian paine. Zak il e e kie zazana zie za ko e pope e e elektroko e mannian filosofi.			
Customer Line Inspection					
Comments: no water Rain &	a is loomly Asif	~ has water now			
Current System Informa	tion:	New Information:			
Meter#1:	N	Meter # 1:			
Meter # 2: Radio	<u> </u>	Meter # 2: Radio			
MXU#:	A A AND AND AND AND AND AND AND AND AND A	MXU #:			
Current Reading 0		Current Reading 0			
Type of Meter:		Type of Meter:			
Year MFG:	manaman A ass too 1975	Year MFG:			
GPS - Longitude		GPS - Latitude			
Constant Circulate Constant	na speciment e space al pha e en la manación de la c elesción de la celesción de la celesció	Data Camplated AFITTI			

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 150900003

COMPLETED

Time Started	Work	Work Complete			
Loc#	Master Meter	# was an analysis of the same			
Date 9/1/2015	Account#	SEQ# 30			
Name: WENDELL STEPP	g garage and a second second second second	Phone # (
Address: BO Box	and the second s	Employee Justin Scott			
INEZ, , KY 41		• •			
Location: Twin Oak Dr., red CASSADY AVE.	brick home	eng mananan ang ang ang ang ang ang ang ang a			
Type of Work: Complaints	, pagamakan har (). pagaman manang manang (ومود ده و محدد د يه دهود			
Material Used:	معالصة فعاست والروار والروار والروار	in the same of the			
Customer Line Inspection:	and the second of the second o	and the second second and the second			
Comments: low pressure 1000	Possible leak	on service line Top at Borton of drive			
. Current System Inforr		New information:			
Meter # 1: 70616430	Λ	Meter # 1:			
Meter # 2: Radio 70616430	N	Meter#2: Radio			
MXU #: 13155681	<u> </u>	лхи #:			
Current Reading 8/20/2015 19	2	Current Reading 0			
Type of Meter:	•	Type of Meter:			
Year MFG:	<i>b</i>	Year MFG:			
GPS - Longitude	(GPS - Latitude			
Finding Circuture(a): IF	· 1 <i>M</i> S	Date Completed 9/3/15			

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#



Time Started		Work Complete			
Loc#			Master	Meter#	
Date 9/4/2	2015	Α	account#	SEQ	# 69
Name:	DEBBIE DIALS	3	£ + x + y = x + x + y + y + y + x + x + x + x + x +	Phone #	
Address:	Russell W	orkman Rd	ad Konstantin a	Employee	Rainbo
	LOVELY	KY 41231	2 () 32 a year	in the second distribution of the second distrib	
Location:	Russell W	orkman Rd of 292.Lo	ng Branch.Rus	sell Workman Rd.Go righ	t up on hill.Last house.
		a sy sy an a a minimizen endem			enter processor contrate a contrate of the con
Material C	Jsed:	nassannya,≖warawi ∿ Craff par I b I	Pressur		A STATE OF THE STA
uvu e e	Current Syste	m Information:	- Andrew Spanish designed and the con-	New I	nformation:
Meter # 1	-			Meter#1:	and the second s
Meter # 2	:: Radio	so existing \$40 mills and a second se		Meter # 2: Radio	
MXU#:				MXU #:	n and the second
Current R	Reading 8/20/2	015 611		Current Reading	0
Type of M	Meter: Sensu	S		Type of Meter:	- and the state of
Year MF0		4		Year MFG:	and the second sections of the second sections of the second section section sections and the second sections of the second section section sections and the second section sections are sections as the second section sectio
GPS - Lo	ngitude 0	VIII 43 JANUARY COMMISSION CO.		GPS - Latitude 0	
Employee	e Signature(s):	RS	engaging graph and a second se	Date Complete	9/4/15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 150800266

	WO#	1508	00266	AAMAI FURA
Time	e Started	obe v	Work Complete	
Loc#	လေးကို ရေ (၈၉၄) ရှိက နေဆန် <i>ဆ</i> ေန အေ ။ ကိုကာည်းအေတတ်	Master	Meter#	
Date 8/28/2015	ine in in all fine a second contractions and the second contraction and the	Account#	الم المادية المعارض ويعارض المعارض الم	SEQ # 125
Name: Charles	Tipton	down to grand hydric in. I'm him him was to	Pho	ne# (
Address: P.O. Box	X	er nama sekara kan dan menangan p	Emį	ployee Justin Scott
	, KY 41224]	alian di Santa Santanana ang Santanan di Bandanan di Santanan di Santanan di Santanan di Santanan di Santanan	nada masa it sala nas genera antisonominos	
Location: Boo	one Br of Eli Rd; last house	e in hollow; box is	on BANK IN FRO	NT
- Mari	as for 2 of 3 dr show when a	was an orient very second series.	Sila and received a residence of the	e agreed to grow and a
BOONE	BR.	nur strait	`	is an about it as a second of the second of
Type of Work: Co	mplaints	—n- «m» · · · /	70.00	n nane v s s s s s s s s s s s s s s s s s s
Material Used:		3 at 1 a Sanit rando	Done)	and a second of the second
Customer Line Ins	spection:			والمعتقدة المنطقة مستحدة المستحدة الأراد الألام الماراد الذار الذار الذارات الماراد الذارات الماراد الذارات الماراد الماراد الذارات الماراد ال
Comments: VER	Y LOW WATER PRESSU	RE ? /	Veeds Hook	ed up to main
Current	System Information:	S 1997 A 416 Few Youlder But Arrive at	ज्ञानसम्बद्धका १९७८ वर्ष होन्द्रोभरतामा १४८ द्वाराष्ट्रभ - भर इ. ज्ञानसम्बद्ध	New Information:
Meter#1:	99691122	چې د مهر وي مم	Meter # 1:	The source is not depositely to the contract of the contract o
Meter # 2: Radio	g - Ağıkı və səlisifi ərə və	decompletes constructed to	Meter # 2: Radio	
MXU#:	C. C. Calabara, A. Carlos and and an action of the contraction of the	e olympia i Karanania	MXU#:	KO 1997 Y. S. N. II. massing-identocode block
Current Reading	7/20/2015 524	erma, K. be	Current Readin	g O O on the North Programme of the Control of the
Type of Meter:	Badger .	the constant that constant the start of	Type of Meter:	jaga dan menanggi menghiging georopi di Salah di di 18 di
Year MFG:	1999	e _s ton y	Year MFG:	waata y a
GPS - Longitude	0 3 000,000	x erenic	GPS - Latitude	O , , , , , , , , , , , , , , , , , , ,
wy grown y was a gray at	alter - silve en le che en	and the second s	and the second s	a class
Employee Signatu	ıre(s): しり		Date Con	pleted 9/9//

Martin County Water District 387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO # 151000218

Time Started		Work Complete				
Loc#	g Ar market to a type do 2	Master Me	eter#			
Date 10/23/2015		Account #	SEQ#	177		
Name: Jimmie	Slone	n ili si kingd nama dibi sa ninkdamandibi sa ninka k	Phone #	e hays and		
Address: P.O. Bo	ox -	erre e e e e e e e e e e e e e e e e e	Employee .	Justin Scott		
lnez, K	Y 41224	z, I a suscende parameterismon –				
			Blue-grey house on hill.	***		
				,		
Sp	lit Rock Hiw					
Type of Work: C	omplaints	gyanga an b - b- annound (& b) announce and the	navina (b.c.) de minima en estatumina e	ya (a same a masan a saa		
			Name where to remain			
Customer Line In						
Comments: water			r yesterday			
Curren	t System Information:	Appendix of Professional States (1984)	New Info	ormation:		
Meter#1:	94788708		Meter # 1:			
Meter#2: Radio	94788708		Meter # 2: Radio	and the first of the second se		
MXU#:	The second secon	<u> </u>	MXU #:			
Current Reading	9/11/2015 254	www.marac.eq. p	Current Reading	0		
Type of Meter:	Badger		Type of Meter:	وولوافقة ومستمسية الحالية المسامة والأرام الارام المهيية والا		
Year MFG:	1994	ggart og Vålgruppin	Year MFG:			
GPS - Longitude			GPS - Latitude	,		
Employee Signat	ure(s)		Date Completed	10/23/15		

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO #	151000	190		*
Time	Started	W	ork Complete	and the second second	
Loc#	معج به مستسببت سوال کا کیوا	Master Me	ter#	, , ,	
Date 10/21/2015	t week an e e me t	Account #	S	EQ# 821	
Name: Pauline H	layes		Phone	# !	er e
Address: Wend	y St		Emplo	yee Justin Scott	general control of the control of th
Warfield,	KY 41267		But word fire		
Location: Wend	ly St 5 mi from Warfield,	on right, Wendy St, 2	2nd trailer on right,	white & brown	
Type of Work: Cor	nplaints	mining some shakenan is a confin	AN IN MADE OF FEBRUARY	a ay langa - milalah sadah yan wasan mana	en was intograme something to
Material Used: Customer Line Ins	1 Tim	(red)			
and the property of the same and the same and				ew Information:	<u> </u>
	System Information:			ew information:	
Meter # 1: 2	29935240	enderson E. A. gar glicanists	Meter # 1:	·	e su suma partir de la compansión de la co
Meter # 2: Radio 2	29935240		Meter # 2: Radio		ا من من من من
MXU#:		-	MXU#:		عدو ميد ديد ته مده همد
Current Reading 9	9/20/2015 247	A remark Manage was do order	Current Reading	<u> </u>	
Type of Meter:	Badger	en normanno de constitución de la constitución de l	Type of Meter:	end subselv allimos kompsumskin i k. k. se	, was no w one the person
Year MFG:	2004	og gradoMeno etn 4a	Year MFG:	-6, 44 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	and the state of t
GPS - Longitude			GPS - Latitude		· (a)

Employee Signature(s)

Date Completed 10



WORK ORDER

WO#

Tir	ne Started	Wo	rk Complete	y or a Nanomere	
Loc#		Master Mete	er# <u>.</u>		
Date 10/21/2015	·	Account #	SEC	Q# <u>1</u> 78	
Name: EDGA	R SLONE	ndd en ha wa punis	Phone #	(6(
Address: PO BC	X		Constant	e Justin Scott	
INEZ					
Location: Sp	olit Rock Holw				
	e a respector to the second	e an aureanance e eau s arinamen ge van		1	
MOOF	RE BRANCH		ရေး (၁) ၂ ပေးကောင်းမှ မေး	and the second s	
Type of Work: C	complaints /		/		
Material Used: _					
Customer Line In	nspection		, summer summer flutters of the second	galamanan da da da sa	
Comments: has	low water pressure	24 PS/	At be	<u> </u>	
Curren	t System Information:	and the second s	New	Information:	•
Meter # 1:	89107955		/leter # 1:	«در مصممممه» در به از برای و در و در و در مینیوشانشدینیا و در از	
Meter#2: Radio	e yan amangan kebapatan segi iku terpengan magapa		Neter#2: Redio		
MXU #:	Management of the propagation of		/IXU #:		
Current Reading	9/20/2015 1699	The second secon	Current Reading	0	
Type of Meter:	Badger	· oper combination with the	ype of Meter:	aus ys I samman gamen nich weit blad ist von de som de sommen en	
Year MFG:	1989		ear MFG:	a was an american and a second respective to	
GPS - Longitude	0		SPS - Latitude 0_		
Employee Signa	ture(s):	-17. 414	Date Complete	ed (0-22-15	_

Martin County Water District 387 East Main St., Suite 140

Inez, KY 41224

WORK ORDER

WO # 150900253

Time Started		Vork Complete	S. A. Shakemer & S.
Loc#	Master M	eter#	makka pining gariga - k t - s epini namangang mangang kanagania
Date 9/29/2015	Account#	SE	Q#
Name: Thomas Delong reported	a way of compact of the sample with sample with samples and samples with samples and samples with samples and samples with samples and samples and samples are samples and samples and samples are samples are samples and samples are sam	Phone #	ر بر چې د درې الها دود اله
Address:	angan sangan angan a	Employe	ee Clyde Stanley
1 (b. 3) —) Endinger-specialistic (5)	17 Sha X Willesharde Chapters are esti-	■ P projection project	
Location: at the mouth of Big Branch; rough and washed out and	Water Dept cut across roneeds repaired	oad a few years ago to	
The second	A A SQUARE SAME OF THE SAME SAME OF THE SAME SAME SAME SAME SAME SAME SAME SAM		and the second s
Type of Work: Complaints		- A A A . S	a and an artificial and a sound of the same and a second of the supplement of the supplement of the supplement
Material Used:	ana a Marinista janguaranan baga pa A. 1888 1987 (Arthur & 1997)	. Lynn yy moe Me ware harmonia ————————————————————————————————————	
Customer Line Inspection:	ر ما در		as as the same a first same and a superior of the same states of the same same same same same same same sam
Comments: newls black to	<i>[</i> '		Albert M. Greensbrok of the Market M. 20 (82) c.
Current System Informatio	,	Nev	v Information:
Meter # 1:	Address de la company de la co	Meter # 1:	The second secon
Meter # 2: Radio	maje s mane ja ete k k k k k k k k k k k k k k k k k k	Meter # 2: Radio	ann an shipping and strain aquight is a common shipping of
MXU#:		MXU#:	- in the second section of the second section is the second section of the second section of the second section section section sections.
Current Reading 0	with major and the state of the	Current Reading	O
Type of Meter:	or surprises surficiented in processing.	Type of Meter:	and the second
Year MFG:	e segurum, no jugas intos nees assistantin	Year MFG:	ျော် ရှိသော်သို့ရေးလည်းသည်။ မိုးသို့ဆိုခဲ့ခဲ့ခဲ့ခဲ့ခဲ့ခဲ့ခဲ့ခဲ့ခဲ့ခဲ့ခဲ့ခဲ့ခဲ့ခ
GPS - Longitude	a	GPS - Latitude	and the Charles of the same that I have the
Employee Signature(s): \$	nam markan makan makan dan kanan sa najirah ji kata mata na maha dahan yabirah sa na na	Date Complet	ted /0-22~/5

Martin County Water District \checkmark

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 151000136

Tim	e Started	AMERICA, ANAGO SERAGA ,	Work Complete	Agricultura in a significant and the significa
Loc#	ر رينيد د مويندي د ما	Master	Meter#	
Date 10/9/2015		Account #		SEQ# 377
Name: JERRY	MAYNARD	annonness or a granges size over the ex-	Pho	one # (
Address: \(^\text{Vontg}	omery Lane		En	pployee Rainbo
Belfry, F	(Y 41514	m programming specific page 197	The state of the s	
	omery Lane, Two story			ine
		To be a parameter of the state	gram, garangan ay . S. a sangagannan ay	y composition of the second of
Type of Work: Co	implaints Put &	Drawas 10	wit mit	Shaw A 100 PS1
	at the Bex.	The second secon	omana A - g Basil a m	State Summer residence and ever a fine process of the control of
Material Used:				
Customer Line Ins	spection:	_Oorl		
Comments: low p	ressure			anne anne o companya de la la companya de la compa
A der prompt of the state of th	to the appropriate sensitive of the sensitive supplies and the	· · · · · · · · · · · · · · · · · ·	To a principle of managements of \$ 10.50 are independent on the principle of the principle	and the second s
	System Information:		B 4 - 4 4 4 .	New Information:
	47823709		Meter#1:	· je · godina do do com atale bala a gelen geriere ale i
Meter # 2: Radio			Meter#2: Radi	•
MXU#:	gan gang and an an an an an an an an	ra mandimonomer	MXU #:	and the same of th
Current Reading	9/20/2015 1631		Current Readir	ng 0
Type of Meter:	Sensus	and we may be becomed	Type of Meter:	where he is a superior of the property of the second of th
	1993		Year MFG:	
	0		GPS - Latitude	0
Employee Signatu	ure(s): RT	e pagamagatu au wa w	Date Cor	mpleted 16-12-15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO # ___

Time Started		Work Complete				
Loc#	Master M	eter#				
Date 10/12/2015	Account#	SEQ# 118				
Name: James Williamson	who common copy (S)	Phone # (*				
Address: Poplar Frk Rd	த சந்த கூறாமுல். எக் க	Employee Rainbo				
BEAUTY , KY 41203		w: •				
Location: Lower Poplar Frk, top c	f hill, 2nd drive on right	, green double wide	,			
	****	garzetranjon arvair son terptite				
ELK CREEK	(Das)	g and management by a simply-construction of the second	·			
Type of Work: Complaints audi	i um trol	an queloal dat les	מי			
	WANG AND	well descent ser you ourse	e s 20054 185			
Material Used:	an a spring transmission of the co	vi a high paper in the second of the second				
Customer Line Inspection:	an ersen skap verse til	والمرافع في المنظم المرافعين المستعلق				
Comments: no water			6 6 M B			
and the second section of the section of the second section of the section of the second section of the section of th	er + research réduit à la la la de	***				
Current System Information	:	New Information				
Meter # 1: 47823585	of your thinks	Meter # 1:	,, .			
Meter # 2: Radio		Meter # 2: Radio	1.0 WALL 100 B 70			
MXU#:	an ing yang galaba ni d	MXU#:	4 3 89 till 4 F			
Current Reading 9/20/2015 732	n	Current Reading 0	· · · · · ·			
Type of Meter: Sensus		Type of Meter:	*******			
Year MFG: 1993	. ======	Year MFG:	\$ 16 the first own			
GPS - Longitude 0	······································	GPS - Latitude 0				
Employee Signature(s): R.5	and the second section of the section of t	Date Completed 1/0-1	J-15			

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 151000030

Work Complete

Time Started	VVOIR O	a. mee v v · · · · · · · · · · · · · · · · ·
Loc#	Master Meter #	to a company of the confine form of the designation of the state of th
Date 10/5/2015	Account#	SEQ#
Name: Ed Pack		Phone # (6
Address: Tomahawk Rd	gy pa. 30a (maganing alang y dy't lety's lethic dather the	Employee Troy Horn
Tomahawk, Ky 41262	American de la companya de la compa	vva
Location: Tomahawk Rd,		
y i a managamananahan ni siyi serjemba de hisan		
1 to 2 to 200 to majore and well and the	A three sections and the section of	
Type of Work: Complaints		manamananan mang bi and nampangangan na panang na pandanahandalahan egip sabalahan na
and have separate to the state of the separate to the separate		
Customer Line Inspection		and the second s
shallow in the internal strength of the control of		, and prompty that
Current System Information:	The second secon	New Information:
Meter # 1:	Mete	er#1:
Meter#2: Radio	Mete	er#2: Radio
MXU#:	MXU	J#
Current Reading 0	_	rent Reading 0
Type of Meter:	Type	e of Meter:
Year MFG:	Yea	r MFG:
GPS - Longitude	GPS	S - Latitude
		The second of th
Employee Signature(s): 1/4 = £ 2		Date Completed 10/12/15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO:	# 15080	00215			
Tin	ne Started	कर्षन केंग	Work Comple	ete	• •	
Loc#	e de description	Master I	Vieter#		ona p _e nggaga v ne v v v v v v v v v v v v v v v v v	m e v salekowskys
Date 8/25/2015	Å 90mm,	Account#	n war er 1723	SEQ#!	96	· • •
Address: PO BO	HEDGES X Y , KY 41231	allen en la	, , , ,	Phone #	roy Horn	मुंक प्राच्या व्हा प्राप्तह कुर
	Riverfront Rd of Lovely; 3rd garage	d driveway on right		Bridge, white b	ouse w/red shutte	ers and
Type of Work: C	به بدائدة شده رد و ۱	(n Ngyaran		ngg fasion y massarana .	> one Majo
Material Used:	30 ft of 4	1 Sewer	Pipes 6) 40in (Couple's,	> 678
Customer Line In		Summanum in a state of the control of the state of the st	w water on	selinounik yu w 5:	Control of the second of the	e 744 s.··
Comments: cove	ered customer's drain whi	le fixing leak	pr 364	متعرومه و الدي	مستود سوليديو الله	s % :44
Curren	t System Information:	vo g⊬drýguk ček		New Info	rmation:	* 5/ *
Meter#1:	95748911	elder er og stilsperk	Meter # 1:		Sudjandon see Françaises (F. Gra	: • ·
Meter#2: Radio	9.g	magama c.s: era	Meter # 2:	Radio	K2 X X Y 6	
MXU#:		· · · · · · · · · · · · · · · · · · ·	MXU#:	÷	su colonia e e e	,
Current Reading	7/20/2015 711	common so spains	Current Re	eading	<u>, 0</u>	a ny
Type of Meter:	Badger	commo egovose	Type of M	eter:		
Year MFG:	1995	v. Mar de prodropostall	Year MFG): , ,	v	¥
GPS - Longitude	0	¥ , v	GPS - Lat	itude 0	u balante Mi	
Employee Signat	ture(s): TH.CS.RT	156516	Date	Completed	0-1-15	, *-

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Time Started	×	Work Complete
Loc#	Master	Meter#
Date 10/5/2015	Account#	SEQ # 146
Name: GARY HUNT	34, f. ex. "o — weak down consistent we wanted resonance	Phone # (
Address: - Hunt Place		
INEZ, , KY 41224		
32 ma sperme, and a side state of the special special contraction of the special speci	- wy referency yn y gant agant hannen annann mar ar gere a fe	and a second the second to the
ROUTE 2032	*: × **********************************	<u> </u>
Type of Work: Complaints		
Type of Work. Complaints	and the second s	and is and a supplied to the supplied of the s
Material Used:	man amanani arta ini si kanta Asangan, amana a	the second secon
Customer Line Inspection		- A
Comments: no water	Power	issue
Current System Information:	and the state of t	New Information:
Meter # 1: 29935364	un nec'h, ni dennezek	Meter # 1:
Meter # 2: Radio		Meter # 2: Radio
MXU#:	nd new wind Microsco.	MXU#:
Current Reading 9/20/2015 473		Current Reading 0
Type of Meter: Badger		Type of Meter:
Year MFG: 2004		Year MFG:
GPS - Longitude 0		GPS - Latitude 0
Employee Signature(s): 85	Ar annuis 24	Date Completed 10 .5 .1 S

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

151000122 WO# Work Complete Master Meter # Loc# SEQ# 679 Date 10/8/2015 Account # ____ Phone# 12-Phyllis Lowe Name: Employee Justin Scott Address: P.O. Box Tomahawk, Ky 41262 Rockhouse Rd. Tomahawk. 5 4/10 mile from bridge. Grey & white trailer on the right on a bank. Location: Has blacktop driveway. Rockhouse Rd Type of Work: Complaints Customer Line Inspection (USD Mer Side Comments: no water New Information: Current System Information: Meter # 1: Meter # 1: 29934859 Meter # 2: Radio 29934859 Meter # 2: Radio MXU#: MXU#: Current Reading 9/20/2015 626 Current Reading 0 Type of Meter: Type of Meter: Badger Year MFG: Year MFG: GPS - Latitude GPS - Longitude

Employee Signature(s):

Date Completed 10 - 9 - 15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO #151	100181
Time Started	Work Complete
Loc# Maste	er Meter#
Date 11/25/2015 Account #	SEQ # 110
Name: MARY STANLEY	Phone #
Address: PO Box	Employee Justin Scott
WARFIELD , KY 41267 Location: Stanley Dr COLLINS CREEK	
Type of Work: Complaints	e definition for the first (1975) (1) (1) (2) (2) (3) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4
Material Used: Dater Pressure with Customer Line Inspection Pan @ EIF Creek	low due to pamp being
	water \$ \$ \$ \$ And the first tensor and the second of the s
Current System Information:	New Information:
Meter # 1: 70616608	Meter # 1:
Meter # 2: Radio	Meter # 2: Radio
MXU#: 13154928	MXU#.
Current Reading 11/20/2015 371	Current Reading 0
Type of Meter:	Type of Meter:
· Vear MEG:	Year MFG:

Employee Signature(s): // TC / TC / J

GPS - Longitude

Date Completed 11/25/15

GPS - Latitude

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

		WO#	151100	168		
Tir	ne Started		v	Vork Complete	е це семгуу. Закамыр ць эко эко оролцег иштог	
Loc#						······································
Date 11/24/2015) 	Acc	count #		SEQ# 295	······································
Name: Ronnie	& Marcella Cook	· · · · · · · · · · · · · · · · · · ·		P	hone# (
Address: Cr	um Br		copyrights find for a first gar years	<u> </u>	mployee Rainbo	and a second
Debore	d, Ky 41214					
C	rum Br				14 * **	
Type of Work: C	Complaints				,	The same of the sa
) DNO)	
Customer Line I	41 housespeed 4.4	Flad	teak	Vad.	50 25Z	ALLOX
Currer	nt System Informa	tion:			New Information:	
Meter#1:	47823639		•••	Meter # 1:		<u></u>
Meter#2: Radio	47823639		······································	Meter#2: Re	idlo	and the second section of the second
MXU#:				MXU#:		
Current Reading	10/20/2015 1135			Current Read	ding <u>0</u>	
Type of Meter:	Sensus			Type of Mete	or:	
Year MFG:	1993		_	Year MFG:		
GPS - Longitude				GPS - Latitud	de	
<u> </u>						

Date Completed

Employee Signature(s):

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 151100136 Time Started Work Complete Master Meter # Loc# Date 11/13/2015 Account # SEQ # 40 Name: Connie Mills Phone # Address: P.O. Box 4 Employee Troy Horn Warfield, Ky 41267 Location: Lower Carter Br. Type of Work: Complaints Material Used: 200- 1th Couplers , 287-1" Line Customer Line Inspection Comments: Low water pressue. Said there is a leak at Lower Carter Br in the blacktop. **Current System Information:** New Information: Meter # 1: 33001035 Meter # 1: Meter # 2: Radio 33001035 Meter#2: Radio MXU#: MXU#: Current Reading 10/20/2015 483 Current Reading 0 Type of Meter: Badger Type of Meter: 2006 Year MFG: Year MFG: GPS - Longitude GPS - Latitude

Employee Signature(s):

Date Completed ///12//3-

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

I ime Started	. VVC	ork Complete
Loc#	Master Met	er#
Date 11/18/2015	Account#	SEQ# 161
Name: RICKY HORN		Phone #
Address: Mountain View	- Area and a series of the ser	en transfer
INEZ, , KY 4122	4	*****
Location: Mountain View		
	The same of the sa	
CALF CREEK	volume etc. Newtons	and the second section of the second
Type of Work: Complaints		and the second of the second o
Customer Line Inspection:	γ	
Comments: customer has no water	/fluching lin	
Current System Information	ilon:	New Information:
Meter # 1: 99691124		Meter # 1:
Meter # 2: Radio		Meter # 2: Radio
MXU #:		MXU #:
Current Reading 10/20/2015 691	- Surging transmission	Current Reading0
Type of Meter: Badger	minum grass organization minimization	Type of Meter:
Year MFG: 1999		Year MFG:
GPS - Longitude 0		GPS - Latitude 0
Employee Signature/s): PT		Data Completed 1815

Martin County Water District 387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Time Started	VVO	rk Complete	AND THE PROPERTY OF THE PERSON	
Loc#	Master Met	er#	rrunda mana sa a sa a sa a sa a sa a sa a sa	
Date 11/16/2015	Account#	SEQ#	427	
Name: TRUMAN HORN	One desirence was also see the con-	Phone # (þ.
Address: P.O.BOX	ستاه فنست وونوستا الشلوب والدردان ال الا الواجان الدران	Employee	Clyde Stanley	•
INEZ , KY 412	24]	†		
Location: \ Hom Br	114 · Aud 12 at 14			
2 11 20 11 11	y dia and seed the control of the co			- .
LICKBRANCH RD.			A servedor per A .	
Type of Work: Complaints	(V) can	·		
	\			
Material Used: Putz Q	one grovel in	Surrellay		
Current System Inform		- (+ p.) 2 40 md - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100	formation:	
Meter#1		Meter#1:		
34-t#3:				
MXU #:	The state of the s	MXU#:		
Current Reading 0		Current Reading	<u> </u>	
Type of Meter:		Type of Meter:	National Control of the Control of t	
Year MFG:		Year MFG:		_
GPS - Longitude		GPS - Latitude		
Employee Signature(s): R T		Date Completed	11-18-15	=

367 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 151100134

Time Started	*** *** * * *	Work Complete	
Loc#	Master	Meter#	
Date 11/13/2015	Account #	SEQ#	
Name: Charlie Mills	'41) 44 shife salada sada sanasanayan asradahidi say' sayada sasa sa sasa	Phone #	war of warehouse
Addross:		Employee Rainho	and deprosps.
Location: Riverfront Rd, new			
Type of Work: Complaints	and the second s		the first size of the contract of production of
Material Used:			
Customer Line Inspection custom	er has leak	The state of the s	
Comments: no water			
Current System Inform	ation:	New Information:	
Meter # 1:		Meter#1:	
Meter # 2: Radio	and a second condition of	Meter#2: Radio	
MXU #:		MXU #:	
Current Reading 0		Current Reading 0	
Type of Meter:	and the second s	Type of Meter:	arry gartywae e c
Year MFG:	· 	Year MFG:	
GPS - Longitude		GPS - Latitude	
Employee Signature(s):	RS	Date Completed 1/-/3-/5	

Martin County Water District V 387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 151100123

Ter	ne Started	Work C	Complete Yes
Loc#	a e es	Master Meter #	; - company comment of the delta company and the delta company and the company
Date 11/11/2015		Account#	SEQ# 20
Name: Sherry	Moore	· · · · · · · · · · · · · · · · · · ·	Di # **
Address: P.O. B	ov		Employee Poinho
Lovely	, KY 41231		·
Location: Loc		ne right.	agamata ya kangan da oo ya caa dadama mara mada da Shandi Shandi amaan waxay waxay da ah dadama
Loc		The first of the f	
Type of Work: C	omplaints		SANGAR (1995) THE ROLL IN LANGE A SANGER AND
Material Used:	· · · · · · · · · · · · · · · · · · ·		
	nspection problem on c		
Comments: low	pressure		
Curren	t System Information:	The second secon	New Information:
Meter#1:	70840490	Mete	er#1: <u></u>
Meter#2: Radio	70840490	Mete	er#2: Radio
MXU#:		MXU	J#:
Current Reading	10/20/2015 630	Curr	rent Reading 0
Type of Meter:	Sensus	Туре	e of Meter:
Year MFG:	2012	V	r MFG:
GPS - Longitude	Alde // I de decido la	GPS	S - Latitude
Employee Signat	ure(s):		Date Completed 11-11-15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO# 15110	UU15
Time Started	, 1000 ·	Work Complete
Loc#	Master M	
Date 11/2/2015	Account #	SEQ # 449
Name: James McGinnis		Phone #
Address: McGinnis Br Debord, Ky 41214	and the second s	Employee Justin Scott
Location: HillCrest Dr; ac	ross the bridge by Bud's Bike Shop	o; turn left and it is the 1st white single-wide on hill
Middlefork		
Type of Work: Complaints		
Material Used:		
Customer Line Inspection		The state of the s
Comments: milky water		
Current System In	oformation:	New Information:
Meter # 1: 29541627	·	Meter # 1:
Meter # 2: Radio	and construction to the construction of the co	Meter # 2: Radio
MXU #:	••	MXU #:
Current Reading 10/20/2015	255	Current Reading 0
Type of Meter: Badger	entation to proceed the control of t	Type of Meter:
Veer MEG: 2004	Company of the Compan	Year MFG:
GPS - Longitude 0	www.mananananananananananananananananananan	GPS - Latitude 0

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO # 151200064

Time Started	Work Complete
Loc#	Master Meter #
ate 12/14/2015	Account # SEQ # 417
lame: ELMER DIALS	Phone# ()
Address: Blackburn & Dials Ro	d Employee Troy Horn
TOMAHAWK , KY	Y 41262
driveway on right fork	Rd on Tomawk Just past romanawk Freewill Babtist wooden bridge on left.
ROUTE 40 WEST	
Type of Work: Complaints	1 1-111 30 01 33/11-1011
Type of Work: Complaints Material Used: ユールークリー・ Material Used: ユールークリー・ Customer Line Inspection:	
Type of Work: Complaints Material Used: ユールークリー・ Material Used: ユーター・ Material Used: ユーター・ Customer Line Inspection:	e; possibly creek crossing
Fype of Work: Complaints Material Used: 13/4 COUP Customer Line Inspection: Comments: extremely low pressure Current System Information Meter # 1: 93534937	e; possibly creek crossing
Fype of Work: Complaints Material Used: 3/4 COUP Customer Line Inspection: Comments: extremely low pressur Current System Information Meter # 1: 93534937	re; possibly creek crossing ation: New Information: Meter # 1:
Naterial Used: 13/4 COUP Customer Line Inspection: Comments: extremely low pressur Current System Informa Meter # 1: 93534937 Meter # 2: Radio	re; possibly creek crossing ation: New Information: Meter # 1:
Fype of Work: Complaints Material Used: 34 Coup Customer Line Inspection: Comments: extremely low pressure Current System Information Meter # 1: 93534937 Meter # 2: Radio MXU #:	re; possibly creek crossing Ration: New Information: Meter # 1: Meter # 2: Radio MXU #:
Fype of Work: Complaints Material Used: 3/4 COUP Sustomer Line Inspection: Comments: extremely low pressure Current System Information Meter # 1: 93534937 Meter # 2: Radio MXU #: Current Reading 11/20/2015 1093	re; possibly creek crossing Ration: New Information: Meter # 1: Meter # 2: Radio MXU #: Current Reading 0
Type of Work: Complaints Material Used: 13/4 COUP Customer Line Inspection: Comments: extremely low pressure Current System Information Meter # 1: 93534937 Meter # 2: Radio MXU #: Current Reading 11/20/2015 109:	re; possibly creek crossing Ation: New Information: Meter # 1: Meter # 2: Radio MXU #: 3 Current Reading 0 Type of Meter:

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WC	# 15	1200088	
Tin	ne Started		Work Complete	management in the School School Spirit
Loc#	/ M is provided that solve the late of the	Mas	ter Meter#	and the state of t
Date 12/21/2015		Account#	ng of Alley St	SEQ# 244
Name: LON C	RUM		Phor	ne# (` -
Address: P.O. Bo	OX			loyee Troy Horn
lnez	, KY 41224			
	rton Rd, Little Lick Br, to	p of hill last hous	se @ top of hill, red	
Type of Work: C	omplaints		Done)
Customer Line Ir	nspection		Now.	
Curren	t System Information:		N	lew Information:
Meter # 1:	29935077		Meter # 1:	27 - 8 - 8 - 8 - 8 - 8 - 8 - 8 - 8 - 8 -
Meter#2: Radio	29935077		Meter#2: Radio	
MXU#:			MXU #:	
Current Reading	11/20/2015 650	unana nauna na resaltivé	Current Reading	0
Type of Meter:	Badger		Type of Meter:	
Year MFG:	2004		Year MFG:	make an annual to be given, so the nor significant to the second of the
GPS - Longitude	0		GPS - Latitude	0
Employee Signat	ture(s): TH, C	.5,	Date Comp	oleted 12-23-15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Ti	me Started	Wo	rk Complete	· B. Jappa, vjetnov niembov. s
Loc#	· 1990 · Ola Westername Department	Master Mete	er#	gramma about the form of the transfer of the t
Date 8/11/2015	· · · · · · · · · · · · · · · · · · ·	Account#	SEQ#	49
Name: Alway	s Perfect Floral	FIRST SEC. A SECRETARY OF SECRETARY		The state of the s
Address: Flu	ty Lick Rd	2 Monthson from A XAA Samoon parameter 1900	Employee	Troy Horn
Louisa	a, KY 41230	Annual S Ann	amany 1.	
		ide Shop Rite. Across roa		
· ·		, , , , , , , , , , , , , , , , , , , ,		
	Beauty Rd			
Type of Work: C	Complaints Palche	el the bad S	ant in anchie	3-20 t
Material Used:		_		
				in 1966, it is provided and the second of th
Customer Line I	·			
				garantan da angan kalaman kaman kaman na da kalaman kaman na da kalaman
	nt System Information			formation:
Meter#1:	29934563		Meter#1:	and the second s
Meter # 2: Radio	29934563		Meter#2: Radio	AND
MXU #:			MXU #:	A readon annical designation of the St. St. and St. A. St.
Current Reading	7/20/2015 651	(Current Reading	0
Type of Meter:	Badger	, , , , , , , , , , , , , , , , , , ,	Type of Meter:	the section of the se
Year MFG:			Year MFG:	
GPS - Longitude	e <u>-82.25144</u>		GPS - Latitude 37.50	562
			g g gam i dans g grannet g drigter y	and a second arrows the state of the
Employee Signa	iture(s): To To an	r /c TU	Date Completed	12/12/10

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Time Started	,	Nork Complete	
Loc#	Master M	leter#	
Date 9/1/2015	Account#	SEQ# 54	
Name: WARFIELD SHC Áddress: PO BOX	PRITE	Phone #	
	Y 41224	A market in the fact of the fa	
Location: ! Beauty Rd			
Type of Work: Complaints	Patched .	the bad Spot in Packing 20	+
Material Used:			
Customer Line Inspection:	, thus the second	The second secon	
Comments: parking lot nee	ds repaired	the contract of the contract o	
Current System I	nformation:	New Information:	;
Meter # 1: 37229319	CONTRACTOR NO. 10 CT 1 CT 2	Meter # 1:	
Meter # 2: Radio	·	Meter # 2: Radio	
MXU #:	و و و و و منسخسین کی و	MXU#:	
Current Reading 8/20/2015	8029	Current Reading 0	
Type of Meter: Sensus	, , , , , , , , , , , , , , , , , , ,	Type of Meter:	
Year MFG: 1986	par effects	Year MFG:	
GPS - Longitude 0	and the second of the second o	GPS - Latitude 0	
Employee Signature(s): ~~	TO OT CO TH	Date Completed	

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

150900059 WO# Time Started Work Complete Loc# Master Meter # SEQ # 39 Date 9/8/2015 Account # DARRELL CLARK Phone # Name: Employee Rainbo Address: Collins Crk Warfield, KY 41267 Location: Collins Creek. 1/2 miles up. Brown brick house on left. Type of Work: Complaints Material Used: Customer Line Inspection: Comments: repair blacktop **Current System Information:** New Information: 70616376 Meter # 1: Meter#1: Meter # 2: Radio Meter # 2: Radio MXU#: MXU #: 13151496 Current Reading 8/20/2015 215 Current Reading 0 Type of Meter: Type of Meter: Year MFG: Year MFG: GPS - Longitude GPS - Latitude

Employee Signature(s): 55, 55, TH, CS Date Completed

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO # 151200045

Tin	me Started	, W	/ork Complete
Loc#	over the second second	Master Me	eter#
Date 12/10/2015	The second secon	Account#	SEQ# 30
Name: WEND	ELL STEPP	n an g ar Maria na a a an a	Phone # /
Address: P.O. B	n otto ammero, il minimissimi giprimi i ini gi gaga	k in spiling management and a spiling	Employee Justin Scott
INEZ,	, KY 41224	es a santinari da di ili manda anda e sa	
Location: ?Tv	vin Oak Dr., red brick home	e de la companione de l	
CASSA	ADY AVE.		
Type of Work: C	omplaints		promoundations with the contract was the second to the contract of the contrac
Material Used:		(S)	<u></u>
Customer Line In	spection	Ugae!	
Comments:	Land decor	2 3/4	Captines about 4 of 3/4/1/he
Curren	t System Information:	vd 4 3/4	14 Sur 1/S New Information:
Meter#1:	70616430	er + maan v	Meter # 1:
Meter#2: Redio	70616430		Meter # 2: Radio
MXU #:	13155681	M	MXU #:
Current Reading	11/20/2015 197	செல் ல ஆர் 1949.	Current Reading 0
Type of Meter:	-mar-main mr. m. 69 . m Arr h. a.a.mialibus, bliad fi soud a m am. las s	To a Management of	Type of Meter:
Year MFG:	a is about their an is	www.d.soda	Year MFG:
GPS - Longitude	· —— · —— · —— · —— · — · · · · · · · ·		GPS - Latitude
Employee Signat	ure(s):	, TH, CS	Date Completed Q - 65 - 15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Time Started	. Work Co	mplete	
Loc#	Master Meter #		
Date 11/30/2015	Account#	SEQ # 328	
Name: Earyetta GILLMAN		Phone #	- • · · ·
Address: Riverfront Rd Belfry, KY 41514	No article (see Section 2011)	Employee Rainbo	
Location: Riverfront Rd.2nd drive	eway past Gospel Revelation.Bl	ack & white double-wide on hill.	er er er
Type of Work: Complaints	Dow	Andrew Control of the	المردة في الأكام طو عنها . ا
		one absolute had 90H	
Customer Line Inspection: Lolch Ju	r to get some one	to chade or her side	for sent
Comments: extremely low pressure pl	ease let customer throu	oif issocis on her side	Ovnet)
Current System Information	1:	New Information:	`.\ <u>.</u> .
Meter # 1: 29935301	Meter	#1:	
Meter # 2: Radio	Meter	# 2: Redio	- 16 1 7
MXU#:	MXU;	#:	e oma laj livi
Current Reading 11/20/2015 301	Curre	nt Reading 0	5 5 mine 10 min a
Type of Meter: Sensus	Type	of Meter:	•
Year MFG: 1980	Year I	MFG:	right from all t
GPS - Longitude 0	GPS -	- Latitude 0	es la
Employee Signature(s): 12CBX	25	Date Completed 12-4-15	

387 East Main St., Suite 140 Inez, KY 41224

	WO #	151200018	
Tin	ne Started	Work Complete	
Loc#	A. A	Master Meter #	to the state of th
Date 12/4/2015		Account#	SEQ # 135
Name: GARL	AND SPENCE	Ph	one# (
Address: Gar	land Spence Dr		ployee Justin Scott
INEZ	, KY 41224		
		,	white house on hill w/railing on
Type of Work: Co	is an age at announcemental single single and a second single sin	DONY) 434 incerts 104.	tos 341:ne, 34 wra
Customer Line In	spection		,
Commants	**************************************		
Current	System information:		New Information:
Meter#1:	98604648	Meter # 1:	
Makes 44 Oc			755-7-16
MXU#;		MXU #:	
Current Reading	11/20/2015 1687	Current Readin	· *
Type of Meter:	Badger	Type of Meter:	The second secon
Year MFG:	1998	Year MFG:	
GPS - Longitude	0	GPS - Latitude	0
Employee Signatu	re(s): TH, C5	Date Com	pleted /1-54-15

WORK ORDER

41	WO #	14120009	12	
	Time Started	Wor	k Complete	***
Loc#	Control of the Contro	Master Meter	r#	
Date 12/	12/2014	Account#		SEQ # 226
Name:	ELMER FITCH		Phone	e# (
Address:	P.O.BOX			oyee Troy Horn
	Inez, KY 41224			
Location:	Guyton Rd, 2nd driveway on le	eft up Little Lick; 2nd dr	veway, white do	puble-wide
	GUYTON RD	5		
Type of V	Vork: Complaints	Done		*
Material (Jsed:			^
Custome	r Line Inspection:			
Commen	ts: got water		· · · · · · · · · · · · · · · · · · ·	
	Current System Information:		N	ew Information:
Meter#1	29934978	M	eter # 1:	
Meter # 2	: Radlo	M	eter#2: Radio	
MXU#:		M	XU #:	
Current R	reading 11/20/2014 389	C	urrent Reading	0 .
Type of M	leter: Badger	т:	ype of Meter:	
Year MFG	S: <u>2004</u>	· Y	ear MFG:	
GPS - Loi	ngitude 0	G	PS - Latitude	0

Date Completed 1-5-15

Employee Signature(s): The CS

WORK ORDER

WO # 150200238



			4 4 200
	Time Started	Work Compl	lete
Loc#		Master Meter#	
Date 2/24	1/2015	Account# '	SEQ# 220
Name:	Eric Copeland		Phone #
Address:	PO Box		Employee Rainbo
	Lovely , KY 41231		
Location:	3 Riverfront Rd		
	292		
Type of W	Vork; Complaints	Dal	
Material U	Jsed:		
Customer Comment	r Line Inspection La Localities: no water coming thru meter	the now put & c water son had good one one will from Bile i found it	lach it near to begge Pressure in I left it son
	Current System Information:	more se factor of	New Information:
Meter#1:	98655397	Meter # 1:	
Meter # 2:	Radio	Meter # 2:	Radio
MXU#:		MXU #:	
Current R	eading 1/20/2015 997	Current Re	eading 0
Type of M	eter: Badger	Type of M	eter:
Year MFG	G: 1998	Year MFG	:
GPS - Lor	ngitude 0	GPS - Lati	ltude 0
Type of M Year MFG GPS - Lor	G: 1998	Year MFG	:

声.

Martin County Water District 387 East Main St., Suite 140

lnez, KY 41224

WORK ORDER

	WO #	150200236	·····
Tia	me Started	Work Con	plete
Loc#	a a		* Details and the second secon
Date <u>2/24/2015</u>	44.	Account#	SEQ# 484
Name: Recyc	oling Solutions Tech.		Phone # (
Address: PO Bo	***	AAN AA SAA	Employee Troy Horn
Allen,	KY 41601	•	·
Location: Right:	side, go thru gate, meter se	ets to the left of garage doors	, in front of boiler
Type of Work: C	complaints		
	·	and there is no water coming	to it either.
Curren	t System Information:		New Information:
Meter # 1:	70025360	Meter#	1:
Meter#2: Radio	70025360	Meter#	2: Radio
MXU #:	14640449	MXU #:	
Current Reading	1/20/2015 1961	Current	Reading 0
Type of Meter:		Type of	Meter:
Year MFG:		Year Mi	FG:
GPS - Longitude	· · · · · · · · · · · · · · · · · · ·	GPS - L	atitude
Employee Signat	ure(s): <u>CS</u>	J. De	ite Completed 2 – 29 – 15

WORK ORDER

	WO#	150200	227	
	Time Started	. v	ork Complete	
Loc#	• • • • • • • • • • • • • • • • • • • •	Master Me	المحملا	- Marian and the state of the s
Date 2/24/2	2015	Account#	· · · · · · · · · · · · · · · · · · ·	SEQ# 183
Name: P	ATRICIA MAYNARD		Phon	ne#
Address:	Everett Rd		Empl	loyee Justin Scott
E	BEAUTY , KY 41203		······································	
Location:	Everette Rd, 2nd house on left,			
 E	EVERETT LANE			
Type of Wo	ork: Complaints			l pa quantum manga man makanka kilak k
Material Us	sed:			
Customer l	ine Inspection:			
Comments	: no water	+ heir	5. Le	
·c	urrent System Information:		N	lew Information:
Meter # 1:	29934968		Meter#1:	
Meter # 2:	Radio		Meter # 2: Radio	
MXU#:			MXU#:	
Current Rea	ading <u>1/20/2015</u> 756	omore de	Current Reading	0
Type of Me	ter: Badger	AAA TOO AAAA AAAA AAAA AAAAA AAAAA AAAAA AAAAA AAAA	Type of Meter:	
Year MFG:			Year MFG:	
GPS - Long	gitude 0		GPS - Latitude	0

Employee Signature(s):_

Date Completed 2-24-15

Martin County Water District 387 East Main St., Suite 140

Inez, KY 41224

WO #	150200225	_
Time Started	Work Complet	9
Loc#	Master Meter #	
Date 2/24/2015	Account #	SEQ# 384
Name: WANDA Maynard		Phone # ();
Address: Honeysuckle Ln		Employee Justin Scott
Debord, KY 41214		
Location: Honeysuckle Ln, 90 Babe Dek	ong Rd	
BABE DELONG RD	Done	
Type of Work: Complaints	LY87	en on servide
Material Used: 41.10 cupplers Lin wrap Customer Line Inspection:	8 1:1 incerts, 10	
Comments: NO WATER		
Current System Information:	Le Company Com	New Information:
Meter # 1: 29935196	Meter # 1:	
Meter # 2: Radio	annua manua ma	adio
MXU #:		- A de anno montre de la companya del la companya de la companya d
Current Reading 1/20/2015 594		ding0
Type of Meter: Badger	Type of Mete	
Year MFG: 2004	Year MFG:	The state of the s
GPS - Longitude 0	GPS - Latitu	de <u>0</u>
Employee Signature(s):	Date C	ompleted

Martin County Water District 387 East Main St., Suite 140

Inez, KY 41224

WORK ORDER

	WO #	15020021	8	
Tir	me Started	Work	Complete	
	- to a constant of the constan			** ** ** ** ** ** ** ** ** ** ** ** **
Date 2/23/2015		Account#	SEC	Q# <u>525</u>
Name: Jonath	an Johnson		Phone #	Paragram finale resilientis finishina (1905 to 6 Sanaka arang makka mang dipulipulik dipulik dipulik dipulik d
Address: E	llockhern: Pd			e Clyde Stanley
Debor	d, KY 41214			
	Blackberry Rd. New Rt 3. Tu	ım left by Fast Lane.Gr	ey double-wide on	
at Allerday Lotter (In Allerda Albania	Blackberry Rd	and the second s	***************************************	
Type of Work: C	omplaints			
Material Used:				1 *10 - 10 - 10 - 10 - 10 - 10 - 10 - 10
Customer Line In			_	
Comments: cust	omer has not had water sind			
Curren	t System Information:	***************************************	New	Information:
Meter#1:	94261254	Me	eter#1:	
Meter#2: Radio	94261254	Me	eter#2: Radio	
MXU#:		FA)	(U #:	
Current Reading	1/20/2015 513	Cu	rrent Reading	0
Type of Meter:	Badger	Ту	pe of Meter:	
Year MFG:	1994	Ye	ar MFG;	
GPS - Longitude		GF	S - Latitude	

Employee Signature(s):

Date Completed 2-24-15

WO #	150200202	desida quanta quanta de la companio
Time Started	Work Go	mplete
Loc#		
Date 2/23/2015	Account #	SEQ# 525
Name: Jonathan Johnson		Phone#
Address: Blackhorn, Pd		Employee Justin Coett
Debord, KY 41214		
Location: Blackberry Rd. New Rt 3. To	·	louble-wide on left.
* · · · · · · · ·	•	Managanagan and American Ameri
Customer Line Inspection Comments: no water		
Current System Information:		New Information:
Meter # 1: 1896 3034	Meter	# 1:
Meter#2: Radio	Meter	# 2: Radio
MXU #:	MXU #	* :
Current Reading	Currer	nt Reading 0
Type of Meter: Badge	Туре с	of Meter:
Year MFG:	Year M	AFG:
GPS - Longitude	GPS -	Latitude
Employee Signature(s):	······································	Date Completed 2 - 24 C

		WO#	150200	175		
	Time Started	A , 3 No.	W	ork Complete	\	
Loc#			Master Me	in H	·	
Date <u>2/18</u>	/2015	Α	.ccount#		SEQ# 214	
Name:	Miranda McCoy			Pho	ne# *	
Address:	P.O. Box			Em	ployee Justin Scott	
	Beauty, KY 41203	*******				
Location:) Big Elk Rd. Acro	oss from Water	Tower, grey trail	<u> </u>	· • • • • • • • • • • • • • • • • • • •	
	Big Elk Rd /ork: Complaints		0			
Customer	Line Inspection:				_	
Comment	s: possibly frozen at r	neter / ħq	d water	going	hourgh:	the meter
	Current System Info	rmation:			New Information:	
Meter#1:	29935189	·		Meter#1:		
Meter # 2:	Radio 29935189	······		Meter#2: Radio		
MXU #:				MXU#:		
Current R	eading 1/20/2015 3	74		Current Reading		-
Type of M	eter: Badger		···········	Type of Meter:	ده چې سيمېر د است چې د د د د د د د د د د د د د د د د د د	ar 1 - \$ 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1
Year MFG	G: <u>2004</u>			Year MFG:		
GPS - Lor	ngitude		 -	GPS - Latitude		
Employee	Signature(s):	-H, RJ		Date Com	pleted <u> </u>	1-15

Martin County Water District 387 East Main St., Suite 140

Inez, KY 41224

	W0 #	150200169	
	Time Started	Work Con	pplete
Loc#	- ** -		and higher and higher
Date 2/18	//2015	Account#	SEQ# 142
Name:	EARL ALLEY		Phone #
Address:	_ Poplar Fork		Employee Troy Horn
	BEAUTY , KY 41203		
Location:			
Material U	Jsed:	weeno Bood	Ametor
		program a transfer de la companya de	No. 1. f. wood fare
Meter#1:	Current System Information: 98607413	Meter#	New Information:
Meter # 2	and the state of t		2: Radio
MXU#:	Radio	MX11#	
Current R	eading 1/20/2015 734		Reading 0
Type of M	leter: Badger	Type of	Meter:
Year MFG	6: <u>1998</u>	Year M	FG:
GPS - Loi	ngitude 0	GPS - I	_atitude 0
Employee	e Signature(s):	D	ate Completed 2 8 5

	WO#	150200171	and the latest and the
	Time Started	Work Com	plete
Loc#			and the state of t
Date 2/18/20	015	Account #	
Name: B.	ARANAS		Phone # (_)
Address: P.	O. BOX		Employee Troy Horn
В	EAUTY , KY 41203		
Location: be	eauty, Beside Nazarene church.	Pink house right side	
B	EAUTY		
Type of Wor	k: Complaints		
		.	
Material Use	ed:		<u> </u>
Customer Li	ne Inspection: 1/ Witer	Almond at mete	r., problemison customas s
	customer thinks meter is frozen	U	. ·
Cu	rrent System Information:	·	New Information:
Meter#1:	96130786	Meter #	1:
Meter#2: R	adio	Meter#	2: Radio
MXU#:		MXU#:	
Current Rea	ding 1/20/2015 1343	Current	Reading 0
Type of Mete	er; Badger	Type of	
Year MFG:	1996	Year MF	FG:
GPS - Longi	tude 0	GPS - L	atitude 0
Employee Si	ignature(s):	₩ Da	te Completed 2/8/15

WORK ORDER

	WO#	15020016	<u></u>	
Time	Started	Wor	k Complete	
Loc#		11 4 - 14-1-		·
Date 2/18/2015	The of the spherous services	Account#	SEQ# 538	
Name: Ivalean H	lager		Phone#	part or a special section of the sec
Address: PO Box			Employee Rainbo	
Inez	, Ky 41224-0295			
Location:) Hage	er Hill Dr. single wide at b			
Skyview			<u> </u>	
Type of Work: Con	nplaints	10 - 10 - 10 - 10 - 10 - 10 - 10 - 10 -		· · · · · · · · · · · · · · · · · · ·
Material Used:				
Customer Line Inst	pection: <u>Costome</u> r	- had wa	to at long	in Article Principle
		TOOK WO	da ex loc	
Comments: no wat	er			-
Current S	System Information:		New Information:	
Meter # 1: 9	5748781	M	leter#1:	
Meter#2: Radio _	<u> </u>	M	leter#2: Radio	
MXU#:		M	XU#:	
Current Reading 1	/20/2015 1773	с	urrent Reading 0	·
Type of Meter: B	adger	T;	ype of Meter:	
Year MFG: 1	995	Ye	ear MFG:	
GPS - Longitude 0		G	PS - Latitude 0	

Date Completed

Employee Signature(s):

WO#	15030020	05
Time Started	Work Complete	
Loc#	*	r#
Date 3/25/2015	Account #	SEQ# 98
Name: GARY & Trish HUNT		Dhono # /
Address: PO ROY		Employee Justin Scott
INEZ , KY 41224		······································
Location: Cassell Br. Brown 16X80 tra		,
CASSELL BRANCH	-	
Type of Work: Complaints		
Customer Line Inspection:		
Comments: no water Dung Va	, Jour)
Current System Information:	* · · · · · · · · · · · · · · · · · · ·	New Information:
Meter # 1: 29935252		Леter # 1:
Meter#2: Radio		Neter#2: Radio
MXU #:	<u> </u>	AXU#:
Current Reading 3/20/2015 961	(Current Reading 0
Type of Meter: Badger	***************************************	Type of Meter:
Year MFG: 2004		/ear MFG:
GPS - Llougilude 10		GRS Lautude 0
		7-2
Employee Signature(s):	-daria: x	Date Completed
The state of the s	•	785°

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO # 150300144 Time Started Work Complete Master Meter # Date 3/18/2015 Account # SEQ # 174 Phone # Name: Judy Harmon Employee Justin Scott Address: PO BOX LOVELY , KY 41231 Location: ... N Wolf Creek Type of Work: Complaints Material Used: Customer Line Inspection: Comments: complains of white, murky water; please flush lines/cont flush lines Have to Save **Current System Information:** New Information: Meter#1: Meter#1: 74604140 Meter # 2: Redlo Meter # 2: Radio 74604140 MXU #: 14992935 MXU#: Current Reading 0 Current Reading 2/20/2015 13 Type of Meter: Type of Meter: Year MFG: Year MFG: GPS - Latitude GPS - Longitude

Date Completed 3-19

Employee Signature(s):

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

150300112 **WO#** Time Started Work Complete Master Meter# Loc# SEQ #· 121 Date 3/12/2015 Account # Mary V Moore Name: Phone # (. Address: Yellow Crk Rd Employee Justin Scott LOUISA , KY 41230 Location:) Yellow Crk, 4th house on right, white LOWER FLUTY LICK Type of Work: Complaints Material Used: , Customer Line Inspection: Comments: low pressure **Current System Information:** New Information: Meter#1: 330010033 Meter # 1: Meter # 2: Radio 330010033 Meter#2: Radio MXU #: MXU#. Current Reading 2/20/2015 293 Current Reading

Employee Signature(s):

Type of Meter: Badger

GRS-Longitude 0

Year MFG:



Date Completed

GPS - Latitude → 0 →

Type of Meter:

Year MFG:

Martin County Water District \checkmark

387 East Main St., Suite 140 Inez, KY 41224

WO#	150300117	and the later of t
Time Started	Work Complete	
Loc#	Master Meter#	
Date 3/13/2015	Account #	SEQ# 295
Name: Justin Pinson	-	Phone # (f
Address: Music Lp	•	Employee Rainbo
Inex Ky 41224		-
Location: Music Ln. 1st driveay across b	mage, brown nouse. 1st t	oridge on the right after Ok Corral.
Type of Work: Complaints		
Material Used:		
Customer Line Inspection		1. 1
Comments: very low water pressure for day	15/ 100 DZI	At box loft sill
Current System Information:		New Information:
Meter # 1: 70472562	Met	er#1:
Meter # 2: Radio 70472562	Met	er#2: Radio
MXU #:	MX	U#:
Current Reading 2/20/2015 194	Cur	rent Reading 0
Type of Meter: Sensus	Тур	ee of Meter:
Year MFG: 2010	Yea	nr MFG:
GPS - Longitude	GP	S - Latitude
	-2	
Employee Signature(s):	<u> </u>	Date Completed 5 /6 - /5

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO # 150300098 Time Started Work Complete Master Meter # Loc# Account # SEQ # 524 Date 3/10/2015 Phone # \ Name: Kayla Hall Employee Rainbo Address: Tomahawk Rd Tomahawk, Ky 41262 Location: 3 Tomahawk Rd. Tan house beside Phillip Cove Church , Tomahawk Rd Type of Work: Complaints Material Used: Customer Line Inspection Blowed hydrant at Spicy Mountain., Comments: milky water New Information: **Current System Information:** Meter # 1: 47823902 Meter # 1: Meter # 2: Radio 47823902 Meter # 2: Radlo MXU#: MXU #: Current Reading 0 Current Reading 2/20/2015 418 Type of Meter: Sensus Type of Meter: Year MFG: 1993 Year MFG: GPS - Latitude GPS - Longitude at Against a

Date Completed 3-11-15

Employee Signature(s): 57, CH, K5

WORK ORDER

VV	O# 150300	7115	
Time Started	V	Vork Complete	
Loc#			
Date 3/13/2015	Account#	SEQ#	118
Name: RONDA CRUM			
Address: .! Blacklog Rd			Clyde Stanley
Inez, KY 41224		,	
Location: ? Blacklog Rd Blacklog,	1st house on the right pa	st Preece Hollow	
BLACKLOG			
Type of Work: Complaints		leak on custo	mers Side
Material Used:			
Customer Line Inspection:			
Comments: check meter to see if it but	sted or a leak on custom	er's side	
Current System Information	ion: New Information:		formation:
Meter#1: 90770481		Meter # 1:	· · · · · · · · · · · · · · · · · · ·
Meter#2: Radio		Meter#2: Radio	
MXU #:		MXU #:	
Current Reading <u>2/20/2015</u> 1487	, , , , , , , , , , , , , , , , , , ,	Current Reading	0
Type of Meter. Badger	_	Type of Meter:	
Year MFG:	·	Year MFG:	
GPS - Longitude 0		GPS - Latitude 0	

Date Completed_

Employee Signature(s):_

387 East Main St., Sulte 140 Inez, KY 41224

WORK ORDER

	WO #	150300114	
	Time Started	Work Co	omplete
Loc#		Master Meter #	
Date 3/13/2	015	Account#	SEQ# 162
Name: Di	inah Ratliff		Phone # (
Address:	Oakie Drive		Employee Clyde Stanley
in	ez, KY 41224		· -
Location: C	alf Creek Oakie Dr. stav stra	ight, last house, beige 2st	огу
		V	
Type of Wo	rk: Complaints		
Material Use	ed:		
	ina Inapaction:		
Comments:		on custome	
	700001110	OII COSTOING	7_S 0(SAC
Cı	urrent System Information:		New Information:
Meter#1:	99459123	Meter	r#1:
Meter#2: F	Radio 99459123	Meter	# 2: Radio
MXU #:		MXU	#:
Current Rea	ading <u>2/20/2015</u> 1247	Curre	ent Reading 0
Type of Met	er: Badger	Туре	of Meter:
Year MFG:	1999	Year	MFG:
GPS - Long	itude	GPS	- Latitude
	The state of the s		Law -
Employee S	Signature(s): 3S		Date Completed 3/3/5

WORK ORDER

	WO#	150300100	
Time Started		Work C	complete
Loc#		Master Meter #	
Date 3/11	1/2015	Account #	SEQ# 229
Name:	Norma McCoy		Phone# (
Address:	5 Meathouse Rd		Employee Rainbo
	Pilgrim, KY 41250		ement.
Location:	3 Meathouse Rd, turn right @) 1439 4 or 5 miles on rig	ht grey trailer on hill
	MEATHOUSE		
Type of V	Vork: Complaints		
Material (Jsed:	-	
Custome	r Line Inspection		
Commen			-
	Current System Information:		New Information:
Meter # 1	71799523	Mete	er#1:
Meter#2	2. Radio 71799523	Mete	er#2: Radio
MXU#:	The state of the s	MXL	J#:
Current F	Reading 2/20/2015 140	Curr	rent Reading 0
Type of M	Meter: Sensus	Туре	e of Meter:
Year MF	G: <u>2012</u>	Year .	r MFG:
GPS-Lo	noitude	GP\$	S - Latitude

Employee Signature(s):

Date Completed

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO # 150300039 Time Started Work Complete Master Meter # Loc# Account # 1 SEQ # 177 Date 3/6/2015 Phone # 1 John Moore Name: Address: Meathouse Rd Employee Rainbo Pilgrim , KY 41250 Meathouse Rd Below Leanna Church, 1st Drive, Grey Trailor Location: Wolf Creek Type of Work: Complaints Material Used: Customer Line Inspection Comments: low pressure / had water **Current System Information: New Information:** 47823969 Meter # 1: Meter # 1: Meter # 2: Radio Meter # 2: Radio MXU #: MXU #: Current Reading 0 Current Reading 2/20/2015 582 Type of Meter: Sensus Type of Meter: 1993 Year MFG: Year MFG:

Employee Signature(s): TH, CS Date Completed 3-10-15

GPS - Latitude 0

GPS - Longitude 0

	WO #	150300052	
Tir	me Started	Work Cor	mplete
Loc#		Master Meter#	
Date 3/9/2015		Account#	SEQ# 224
Name: JAMES	MOLLETT		Phone #
Address: 4 B	ig Elk Road		Employee Rainbo
INEZ	, KY 41224		
Location: : E	Big Elk Rd		
Type of Work: C Material Used: Customer Line In Comments: no w	nspection:	Dong	
Curren	t System Information:		New Information:
Meter#1:	98985758	Meter	#1:
Meter # 2: Radio		Meter:	# 2: Radio
MXU #:		MXU #	<u> </u>
Current Reading	2/20/2015 700	Curren	nt Reading 0
Type of Meter:	Badger	Туре с	of Meter:
Year MFG:	1998	Year N	MFG:
GPS - Longitude	0	GPS -	Latitude 0
Employee Signat	ure(s): <u>TH, CS</u>		Date Completed 3-10-15

WO #	150300036		, .* !!!
Time Started	Work Co	omplete Yes	,
Loc#	Master Meter #		
Date 3/6/2015	Account# ^	SEQ# 262	
Name: EUGENE MAYNARD	· .	Phone #	
Address: Debord Rd		Employee Rainbo	
DEBORD , KY 41214]		-	
Location: Debord Rd. On the hill on the	e left past post office. 2nd o	śriveway	
DEBOARD RD			
Type of Work: Complaints	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
Customer Line Inspection:			
Current System Information:	<u></u>	New Information	1:
Meter # 1: 92701760	Meter	r # 1 :	
Meter # 2: Radio 92701760	Mete	r#2: Radio	
MXU #:	MXU	#:	
Current Reading 2/20/2015 1507	Curre	ent Reading 0	
Type of Meter: Badger	Туре	of Meter:	
Year MFG: 1992	Year	MFG:	
GRS - Longitude 0	GPS	- Latitude 0	

Employee Signature(s):	Date Complete	مر کر ہ	26-15
		•• -	·•

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 150300065 Work Complete Time Started Master Meter # Loc# Account # ' _____ SEQ # 154 Date 3/10/2015 Phone # / Name: JOE HACKNEY Employee Justin Scott Address: PO BOX : LOVELY , KY 41231 Location: Stepp Br STEPP BRANCH Type of Work: Complaints Kyle tak him water Material Used: Customer Line Inspection Comments: no water for days New Information: **Current System Information:** Meter#1: Meter # 1: 19906223 Meter # 2: Radio Meter # 2: Radio 19906223 MXU #: MXU#: Current Reading 0 Current Reading 2/20/2015 380 Type of Meter: Type of Meter: Sensus 1967 Year MFG: Year MFG: GPS - Latitude 0 GPS - Longitude 0

Employee Signature(s):

Date Completed 3-10-15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 150300049 Time Started Work Complete Master Meter # Loc# Account # SEQ # 331 Date 3/9/2015 William Chapman Phone# Name: Address: : Nolan St Employee Rainbo Williamson, WV 25661 Chapman Farm Rd of Riverfront, 1 mile from county line, Spring Br, right side of rd, beige double Location: RIVERFRONT Type of Work: Complaints to Will to curanter Material Used: Customer Line Inspection: Comments: havent had water since Tuesday, neighbors are having no pressure New Information: **Current System Information:** Meter # 1: 29934670 Meter # 1: Meter # 2: Radio Meter # 2: Radio MXU#: MXU#: Current Reading 0 Current Reading 2/20/2015 334 Type of Meter: Badger Type of Meter: Year MFG: 2004 Year MFG: GPS - Latitude GPS - Longitude

Employee Signature(s):

Date Completed 3-9-1

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

150300040 WO# Time Started Work Complete Master Meter # Account # SEQ # 203 Date 3/6/2015 Phone # (Name: CLIFFORD KEENER Address: . Riverfront Rd Employee Rainbo LOVELY , KY 41231 Location: Riverfront Rd. Type of Work: Complaints Value shut of tank low Material Used: Customer Line Inspection: Comments: water had low pressure, now has none New Information: **Current System Information:** Meter # 1: 25088029 Meter#1: Meter # 2: Radio Meter#2: Radio MXU#: MXU#: Current Reading 0 Current Reading 2/20/2015 710 Type of Meter: Type of Meter: Sensus 1976 Year MFG: Year MFG: GPS - Longitude 0 GPS - Latitude 0

Employee Signature(s):

Date Completed 3-1-15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

150400180

Time Started

Work Complete

Loc#

Master Meter #

Date 4/23/2015

Account#

SEQ # 382

Name: SD & MARY MOORE

Phone # (1

Address: P.O.BOX

Employee Troy Horn

INEZ

, KY 41224]

Location:

¹ Rockcastle Crk

ROUTE 3 NORTH

Type of Work: Complaints

Material Used:

Material Used:

Customer Line Inspection:

Comments: fence was tore down Friday by MCWD

Put

Fence was tore down Friday by MCWD

New Information:

Current System Information:

15094918

Meter#1:

Meter # 2: Radio

Meter#1:

Meter # 2: Radio

MXU #:

MXU#:

Current Reading 3/20/2015 1464

Current Reading

0

Type of Meter:

Badger

Type of Meter:

Year MFG:

1982

Year MFG:

GPS - Longitude 0

GPS - Latitude 0

Employee Signature(s):

Date Completed 4-275

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO #

150400202

Time Started

Work Complete

Loc#

Master Meter #

Date 4/24/2015

Account#

SEQ # 282

Name: Eva Spence

Phone # (6

Address: PO Box 1

Employee Troy Horn

Inez, KY 41224

Location:

3 Rockcastle Rd Old Rt 3, Past Ratlifftown on hill on the right, brick house, beside Rocky Top Hill.

Old Rt 3

Type of Work: Complaints

Material Used:

Customer Line Inspection:

Comments: customer wants dirt filled and grass sown on bank where water dept had worked put DN hack Current System Information:

New Information:

Meter#1:

29934897

Meter # 1:

Meter # 2: Radio 29934897

Meter # 2: Radio

MXU#:

MXU#:

Current Reading 4/20/2015 394

Type of Meter:

Badger

Type of Meter:

Current Reading

Year MFG:

2004

Year MFG:

GPS - Longitude

GPS - Latitude

Employee Signature(s):

Date Completed 4-27-/5

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

150500078

Time Started

Work Complete

Loc#

Master Meter #

Date 5/7/2015

Account#

SEQ # 303

Name:

PAUL ENDICOTT

Phone #

Address:

2 Buffalo Horn Rd.

LOUISA

, KY 41230

Employee Justin Scott

Location:

2 Buffalo Horn Rd 1st white house on the left past Burkes Body Shop. Wood fence around yard.

BUFFALO HORN

Type of Work: Complaints

Material Used:

Customer Line Inspection:

Comments: extremely low pressure / had good pressure

Current System Information:

New Information:

Meter # 1:

92917046

Meter # 1:

Meter # 2: Radio

Meter # 2: Radio

MXU#;

MXU#:

Current Reading 4/20/2015

Current Reading

0

Type of Meter:

Badger

1992

Type of Meter:

Year MFG:

Year MFG:

GPS - Longitude 0

GPS - Latitude 0

Employee Signature(s): 7 # , C 5

Date Completed 5-8-15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

150500096

Time Started

Work Complete

Loc#

Master Meter#

Date 5/11/2015

Account #

SEQ# 117

Name: Linda Smith

Phone # (f

Address:

_ Camp Branch

Employee Justin Scott

Inez, KY 41224

Location: (

Camp Br, 1/2 m on left, brick split level

Coldwater

Type of Work: Complaints

Material Used:

Customer Line Inspection:

Comments: very low pressure; water is cloudy

New Information:

Current System Information: Meter#1:

70840768

Meter # 1:

Meter # 2: Radio

Meter # 2: Radio

MXU#:

MXU#:

Current Reading 4/20/2015 190

Current Reading

0

Type of Meter:

Sensus

Type of Meter:

Year MFG:

2009

Year MFG:

GPS - Longitude

GPS - Latitude

Employee Signature(s):

Date Completed 5-12-5

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

150500101

Time Started

Work Complete

Loc#

Master Meter #

Date 5/11/2015

Account# ~

SEQ# 293

Name: STERLING MARCUM

Phone # (I

Address: RT 5 BOX

Employee Justin Scott

LOUISA

, KY 41230]

Location:

Rockcastle Rd, 1st white house on the right past Friendship Church

ROUTE 3 NORTH

Type of Work: Complaints

Material Used:

Customer Line Inspection:

Comments: extremely low pressure

New Information:

Current System Information:

Meter # 1:

47823998

Meter # 2: Radio 47823998

MXU#:

Current Reading 4/20/2015 530

Type of Meter:

Sensus

Year MFG:

1993

GPS - Longitude 0

Meter#1:

Meter#2: Radio

MXU #:

Current Reading

Type of Meter:

Year MFG:

GPS - Latitude 0

Employee Signature(s):

35

Date Completed 6-16-5

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

150500087

Time Started

Work Complete

Loc#

Master Meter #

Date 5/8/2015

Account# .

SEQ # 352

Name: Heather Harrison

Phone # (, __. _ ...

Address:

Mullett Br

Employee Justin Scott

INEZ

, KY 41224

Location:

! Mullett Br. Coldwater.Last house on the right, white house on hill, stone bottom

Mullett Br

Type of Work: Complaints

Material Used:

Customer Line Inspection:

Comments: low pressuree - 40 PSI A+ 60%

New Information:

Meter # 1:

29934533

Current System Information:

Meter # 1:

MXU#:

Meter # 2: Radio 29934533

Meter # 2: Radio

MXU#:

Current Reading 4/20/2015 447

Current Reading

Type of Meter:

0

Type of Meter: Badger

Year MFG:

2004

Year MFG:

GPS - Longitude 0

GPS - Latitude 0

Employee Signature(s):

Date Completed 3-11-15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO #

150400151

Time Started

Work Complete

Loc#

Master Meter #

Date 4/16/2015

Account# ^ -

SEQ # 352

Name: Heather Harrison

Phone # (:

Address: Mullett Br

Employee Troy Horn

INEZ

, KY 41224

Location:

Mullett Br. Coldwater.Last house on the right, white house on hill, stone bottom

_ Mullett Br

Type of Work: Complaints

Material Used:

Customer Line Inspection:

40 PSI At box

Comments: extremely low pressure

Current System Information:

New Information:

Meter # 1:

29934533

Meter # 1:

MXU#:

Meter # 2: Radio 29934533

Meter # 2: Radio

MXU#:

Current Reading 3/20/2015 443

Current Reading

Type of Meter:

Badger .

Type of Meter.

Year MFG:

2004

Year MFG:

GPS - Longitude 0

GPS - Latitude 0

Employee Signature(s):

Date Completed 5-4-15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

150500071

Time Started

Work Complete

Loc#

Master Meter #

Date 5/7/2015

Account #

SEQ# 85

Name: DICIE CHARLES

Phone #

Address: PO BOX

Employee Rainbo

LOVELY

, KY 41231

Location: 4 Vaple St 3rd house down, red & white.

MAPLE STREET

Type of Work: Complaints Pull networn A seen the be an Material Used:

Lithing she has a lad Regulata as she Customer Line Inspection

Customer Line Inspection

Comments: very low water pressure

Current System Information:

New Information:

Meter # 1:

47823885

Meter #1:

Meter # 2: Radio

Meter # 2: Radio

MXU#:

MXU#:

Current Reading 4/20/2015

Current Reading

0

Type of Meter:

Sensus

Type of Meter:

Year MFG:

1993

Year MFG:

GPS - Longitude 0

GPS - Latitude 0

Employee Signature(s): \mathcal{B}, \mathcal{J}

Date Completed 5-7-15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

150600053

Time Started

Work Complete

Loc#

Master Meter#

Date 6/8/2015

Account#

SEQ # 105

Name:

HERMAN ENDICOTT

Phone# ()

Address:

Tug River Rd.

Employee Troy Horn

INEZ

, KY 41224]

Location:

. Tug River Rd, 1 mile up Tug River, green roof w.grey siding

TURKEY ROAD

Type of Work: Complaints

Material Used:

Customer Line Inspection:

Comments: customer thinks driveway is damaged due to water meter busting - Did not See way thing was

Current System Information:

New Information:

Meter # 1:

96646084

Meter # 1:

Meter # 2: Radio 96646084

Meter # 2: Radio

MXU#:

MXU#:

Current Reading 5/20/2015

1050

Current Reading

Type of Meter:

Badger

Type of Meter:

Year MFG:

1996

Year MFG:

GPS - Longitude 0

GPS - Latitude 0

Employee Signature(s):

Date Completed 6-8-15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

150600124

Time Started

Work Complete

Loc#

Master Meter #

Date 6/16/2015

Account#

SEQ # 95

FRANK STACY Name:

Phone # 11

Address: PO BOX

Employee Rainbo

INEZ

, KY 41224

Location:

i Frank Stacy Ln blacktop hill goes right-handed white house all the way to end of road.

CASSELL BRANCH

Type of Work: Complaints

Material Used:

Customer Line Inspection

Comments: no water / gct water NOW

New Information:

Current System Information: Meter # 1:

33001067

Meter # 1:

Meter#2: Radio

Meter # 2: Radio

MXU#:

MXU#:

Current Reading 5/20/2015 642

Current Reading

Type of Meter:

Badger

Type of Meter:

Year MFG:

2006

Year MFG:

GPS - Longitude 0

GPS - Latitude 0

Employee Signature(s):

Date Completed

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

150600101

Time Started

Work Complete

Loc#

Master Meter #

Date 6/11/2015

Account#

SEQ # 120

Name:

R&J Development

Phone #

Address: P.O. Box

Employee Justin Scott

Warfield, Ky 41267

Location: W Main St Suite 110. Beside Melissa's House of Style

.V Main St Suite 110

Type of Work: Complaints

Material Used:

Customer Line Inspection:

Comments: customer stated water had odor

Current System Information:

New Information:

Meter # 1:

72136096

Meter#1:

Meter # 2: Radio 72136096

Meter # 2: Radio

MXU#:

14639897

MXU#:

Current Reading 5/20/2015 43

Current Reading

Type of Meter:

Type of Meter:

Year MFG:

Year MFG:

GPS - Longitude

GPS - Latitude

Employee Signature(s): 5

Date Completed 6 -/5 -6

367 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

150600218

Time Started		Work Complete	racione ad an	
Loc#	Master I	Meter#		•
Date 6/29/2015	Account#		SEQ# 231	
Name: LON CRUM Address: P.O. Box Inez , KY 41224	e e e e e e e e e e e e e e e e e e e	*	ne # () loyee Justin Scott	
Location: Guyton Rd, Little Lick Br	top of hill last house @	top of hill, red	with the territory of	• •
GUYTON RD	- 			
Type of Work: Complaints	idan ku ku ku ku ku	***	a topologia a majerak Pak	
Material Used:	-managan	· 40 5 15 4 5 5 76		·* * * * * * * * * * * * * * * * * * *
Customer Line Inspection:		ore the con-	t king a commonly w	*· ·
Comments: low pressure	if for a loa	k	a madaa kaasaa kee ee	
Current System Information)n:	, procession de	New Information:	in the second of
Meter # 1: 29935077	or and the second of the second of	Meter # 1:	and the second s	454 4 4 APA //
Meter # 2: Radio 29935077		Meter # 2: Radio		·~) ··· • · · · · · · · · · · · · · · · ·
MXU #:	a become street.	MXU#:		
Current Reading 5/20/2015 632	. ·•	Current Reading	0	
Type of Meter: Badger		Type of Meter:	ومع و ما	• •
Year MFG: 2004		Year MFG:	s 4.84 4 19 FF	p. 6/81
GPS - Longitude 0		GPS - Latitude	0	
Employee Signature(s): RJ+	ZS	Date Com	pleted 629	

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

		WO #	160100234	,	
Time Started		Work Co	mplete	gan manusungan spirar a App de App and 1 - a	
Loc#	W 7 V		Master Meter #		and the control of th
Date 1/2	6/2016	Ac	count#	SEQ	# 408
Name:	Haskel Mills		No par camphinate in the camph	Phone #	(€
Address:			the state of the s	Employee	Rainbo
	Inez, KY 41224				
Location					
) Union Rd	100 march 2 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
Type of '	Work: Complaints			· · · · · · · · · · · · · · · · · · ·	
Material	Used:		na juga na mangana angana		
Custome	er Line Inspection:				
Comme	nts: extremely	shops u	KUD KES	aleak	but can not the
angungan kanasakin angun Igilika Pasaran sa	Current System Infor	nation:		New	Information:
Meter#	1: 70616597		Mete	r#1:	
Meter#	2: Radio 70616597		Mete	r#2: Radio	
MXU#:	13155911		MXU	#: 	
Current	Reading 12/20/2015 28	35	Curre	ent Reading	0
Type of	Meter:		Турє	of Meter:	
Year MF	FG:		Year	MFG:	
GPS-L	ongitude		GPS	- Latitude	· · · · · · · · · · · · · · · · · · ·

Employee Signature(s):

Date Completed / - 28-///

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 160100234

Tir	ne Started	Work Complete			
		Montos Motos 4			nggan sa gada ini. Inini supundanén
Date 1/26/2016	,	Account#	-	SEQ# 408	
Name: Haske	I Mills	No	maria b Aim	one# (************************************	ar - 25 day 1,50 day lang
Address: PO Bo	The second secon	Annual Control of the Control o		ployee Rainbo	and the second s
	(Y 41224 Union Rd, clay house on hill			,	
	Jnion Rd	· ·			***
Type of Work: C	complaints <i>Ull</i> Ju	rd a leag	on ('opy	
Material Used:	alle fins	it so.	therey.	Starded	ggalaggagaaninasaananga waa d da garid dibidhid
Customer Line In	nspection: Rave	ellate ne	all.		and the second second
Comments: extr	emely	*			
Сиггел	t System Information:	AND ALMON AND AND AND AND AND AND AND AND AND AN	urka samurh applessyon, frag sylf yearsprone er samuran seledi ill samuya	New Information	- na mana, da qui ammir - u - P p q Agripulturaju ur remeder - l
Meter # 1:	70616597	num met 14 mannasik	Meter#1:	, and a second s	
Meter#2: Radio	70616597		Meter#2: Radio		
MXU#:	13155911	ik name the serverhooderlike Villedikit	MXU#:		-
Current Reading	12/20/2015 285	assambles & Monte William	Current Readir	ng 0	Annual Control of the
Type of Meter:			Type of Meter:		th which have the second of th
Year MFG:		qua querrana à	Year MFG:		NAME OF STREET
GPS - Longitude	***************************************	and the state of t	GPS - Latitude		A harmony Widow # *
Employee Signa	ture(s): R,\mathcal{I}	I N. Was the second district.	Date Con	npleted /-	18-16

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO #	1601	JU275	
Time Started		****	Work Complete	man an angatherroannean go an annannin k
Loc#	,	Master	Meter#	
			SEQ	# 245
Name: LON C	RUM		Phone #	(
)X .			Troy Horn
	, KY 41224 .			
∟ocation: Guy	ton Rd, Little Lick Br, top	of hill last house (top of hill, red	
GUYTO	ON RD			
Type of Work: Co	omplaints		an Market	annual of the second of the se
Material Used:		$\langle \rangle$		
	1 (Jaco /		
	any water tru	ed from d	eepr -	Kit 15 Cage Chest
Curren	t System Information:	<i>V</i> .	New	Information:
Neter#1:	29935077		Meter # 1:	
Vieter#2: Radio	29935077		Meter#2: Radio	
MXU #:	No.		MXU #:	
Current Reading	12/20/2015 653	gaggi yaanin anabin qabiniyaa	Current Reading	0
Type of Meter:	Badger	n mananagan na na na akaba	Type of Meter:	na ngayan kanga tanà kaona dia kanana dia kanga dia na dia na mandaha dia dia na mangana kangana dia na mangana
Year MFG:	2004		Year MFG:	
GPS - Longitude	0		GPS - Latitude 0	
				d (2076

Employee Signature(s): 35

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

Wo	# 160100	071			
Time Started	, v	ork Complete	Ar an array constitution M.		
Loc#	Master Me	Master Meter #			
Date 1/6/2016	Account#	SEC	Q# 219		
Name: Charlie Jude		Phone #	<u></u>		
Address: 3 Coldwater Rd		Employe	e Justin Scott		
Inez, Ky 41224	,		,		
Location: Spence Br. Milo. 1/4 mile o	n left. 3rd driveway up	Double-wide.			
Spence Br					
Type of Work: Complaints			and the second s		
Material Used: 2 3/4/1 Ca Customer Line Inspection: Re Jan	pres dasa	+ 30' of 3	5/4 liken 2 Joints a		
Customer Line Inspection: Re	e Cheek C	1050hp	l" Condude		
Comments: creek crossing is uncovered;	possibly froze off	creed C109	stipneds to be Rech		
Current System Information:			Information:		
Meter # 1: 47823965		Meter # 1:			
Meter # 2: Radio 47823965	·	Meter # 2: Radlo			
MXU #:		MXU #:	- The state of the		
Current Reading 12/20/2015 1113		Current Reading	0		
Type of Meter: Sensus		Type of Meter:			
Year MFG: 1993		Year MFG:			
GPS - Longitude		GPS - Latitude			
Employee Signature(s):	C3, TH	Date Complete	ed /- 19-18		

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO #	160100206	•
Time Started		Work Con	nplete
Loc#			
Date 1/2	0/2016	Account #	SEQ# 143
Name;	WILBERT WEBB		Phone # (
Address:	PO BOX:		Employee Rainbo
	LOVELY , KY 41231		
Location			
Type of \	Work: Complaints	and the second s	
Material	Used:		The second secon
	er Line Inspection:		
	nts: all immediate neighbors are o	/	7
	Current System Information:	* A * * * * * * * * * * * * * * * * * *	New Information:
Meter#	1; 99085874	Meter	# 1:
Meter#	2: Radio	Meter	# 2: Radio
MXU#:		MXU #	
Current	Reading 12/20/2015 1169	Currer	nt Reading 0
Type of	Meter: Badger	Туре	of Meter:
Year MF	G: <u>1999</u>	Year N	AFG:
GPS - Lo	ongitude 0	GPS -	Latitude 0

Employee Signature(s):

Date Completed 1 - 20 -/6

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 160100203 Time Started Work Complete Loc# Master Meter # Date 1/16/2016 _____ Account # _____ SEQ # 106 Name: GARY & Trish HUNT Phone # (Address: PO BOX Employee Justin Scott INEZ , KY 41224 Location: Cassell Br. Brown 16X80 trailer at head of hollow **CASSELL BRANCH** Type of Work: Complaints Material Used: Customer Line Inspection: + Urned Pump Station back on Comments: no water New Information: Current System Information: 29935252 Meter # 1: Meter # 1: Meter # 2: Radio Meter # 2: Radio MXU#: MXU#: Current Reading 12/20/2015 1087 Current Reading 0 Type of Meter: Badger Type of Meter: Year MFG: 2004 Year MFG:

GPS - Latitude

GPS - Longitude 0

Employee Signature(s): 5S Date Completed

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 160100190

Time Started	Work Complete				
Loc#	Master Meter #				
Date 1/19/2016	Account#	SEQ# 44	\$10 vi di vive muses distribution (dis		
Name: GLADYS STACY		Phone #,			
Address: P.O.BOX INEZ , KY 41224]		Employee Justin Scott	ex considerate Medical (Mg) (
Location: Aaron St		The second secon	A A STREET, THE STREET, AS A ST		
ROUTE 40 EAST					
Type of Work: Complaints		And the second s			
Material Used:	A	<u></u>			
Customer Line Inspection	1200	A min some	***************************************		
Comments: low water pressue	d 75-i	DST At look			
Current System Information:	Service and the service of the servi	New Information:			
Meter # 1: 29934551		Meter # 1:			
Meter # 2: Radio	Yourselfon	Meter # 2: Redio	manuscom spanness (sp. 174 p. 164 p. 1849).		
MXU #:	,	MXU#:	and a second sec		
Current Reading 12/20/2015 609	agrij Ammana	Current Reading 0	y y administrativi transmini.		
Type of Meter: Badger	Angliang Assessed	Type of Meter:	P 24-4		
Year MFG: 2004	d. aboutedays #4	Year MFG:			
GPS - Longitude 0	<u></u>	GPS - Latitude 0	, up i gyngungamman ble N-Mel er B		
Employee Signature(s):		Date Completed / -/9	16		

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO#	1601	00171	
	Time Started	nam gan ya	Work Complete	management of the Angel Control of the Angel Contro
Loc#				
Date 1/15	5/2016	Account #	S	EQ# 47
Name:	William Davis	with a special and the special		:#
Address:	Po Box		Emplo	yee Justin Scott
	Inez , Ky 41224			
Location:	Behind Farm Bureau			
	Blacklog	•		
Type of V	Vork: Complaints			p. alleman - de formation de la formation de l
	Jsed:			
Custome	r Line Inspection froze on custome	er side		and a grading and a second that the second and a second and
Commen				10, 200
and the second s	Current System Information:			ew Information:
Meter#1	: 18576453		Meter#1:	
Meter # 2	: Radio	радитуруу түр ай оролого оролог	Meter#2: Radio	
MXU#:			MXU #:	
Current F	Reading 12/20/2015 257		Current Reading	0
Type of N	Meter: Badger	<u> </u>	Type of Meter:	
Year MF	G: <u>2002</u>		Year MFG:	
GPS - Lo	ongitude 0		GPS - Latitude	0

Employee Signature(s): 5 Date Completed 1-/5-16

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO # 151200130

Time Started	ed Work Complete		
Loc#	Master Meter #		
Date 12/30/2015	Account #	SEQ# 170	A CONTRACTOR OF THE PARTY OF TH
Name: Elsie Jarvis		Phone # 6	
Address: PO Box		Employee Justin Scott	· ·
lnez , KY 41224	//		-
Happy Hollow			
Type of Work: Complaints			
Material Used:			
Customer Line Inspection Comments: very low water pressure		and it up on!	1 11/14
Comments, very low water pressure /	Meinto Fu	na it up on	<u> </u>
Current System Information:		New Information:	
Meter # 1:		Meter # 1:	
Meter # 2: Radio		Meter#2: Radio	
MXU #:		MXU #:	_
Current Reading 0		Current Reading 0	
Type of Meter:		Type of Meter:	
Year MFG:		Year MFG:	
GPS - Longitude	(GPS - Latitude	
Employee Signature(s):		Date Completed / '/	-15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO #

151100139

Time Started	Work Complete Yes
Loc#	Master Meter #
Date 11/13/2015	Account # SEQ # 31
Name: WENDELL STEPP	Phone #
Address: P.O. Box t	Employee John Stafford
INEZ, , KY 41224	
Location: Twin Oak Dr., red brick home	and the second of the second o
	s there is a second of the sec
CASSADY AVE.	
Type of Work: Complaints	A construction of the cons
Material Used:	and the second s
Customer Line Inspection: fixed leak	plant a material of the control of t
Comments: extremely low pressure	and the second of the second o
Current System Information:	New Information:
Meter # 1: 70616430	Meter#1:
Meter # 2: Radio 70616430	Meter # 2: Radio
MXU #: 13155681	MXU #:
Current Reading 10/20/2015 195	Current Reading 0
Type of Meter:	Type of Meter:
: Year MFG:	Year MFG:
GPS - Longitude	GPS - Latitude
Employee Signature(s): 7R, JS, 3	Date Completed //6/16

Martin County Water District 387 East Main St., Suite 140

387 East Main St., Suite 140 (nez, KY 41224

WORK ORDER

WO#

160200213

Time Started Work Complete					
Loc#	equal termination of the second	Master Meter #			
Date 2/22/2016	made or a constant of the American Income	Account #	and the state of t	SEQ # 163	d s page despense
Name: MIKE	IORN	at a Managangan		Phone # (
Address: Dak	tie Drive KY 41224			Employee Troy Horn	• • •
Location: Jal	cie Dr of Calf Creek, 5th di	riveway on right.wh		Action for a proceeding survey group;	man way as pily one
Material Used:	So F ₁ - <u>1"Linc</u> ispection:		The state of the s		
Curren	t System Information:	Andrew specific processing to the specific terms of the specific t	****	New Information:	
Meter#1:	29935042	manager of the second s	Meter # 1:	~	
Meter # 2: Radio	29935042	NSS THE CONTRACTOR	Meter#2: R	adio .	d Sheery or say destroys
MXU#:			MXU#:	and the same of th	and the state of t
Current Reading	1/20/2016 200		Current Read	ding O	پېسىن. «ئېمان سىد، مېنىدى <u>نى د د د د</u>
Type of Meter:	Badger	des (an de aquante en un particular un s	Type of Mete	er:	· company on the first VIII confirm
Year MFG:	2004	-	Year MFG:	المنافعة الم	
GPS - Longitude	0 .	der der eigen de	GPS - Latitu	de 0,	
Employee Signa	ture(s): // / =	 T<	Date C	ompleted Alas	16

and the second of the second

a Variety

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

160200193 WO# Time Started Work Complete Master Meter # Loc# SEQ# 802 Date 2/18/2016 Account # 1 Phone # Name: CLYDE WALLER Employee Rainbo Address: Hode Rd WARFIELD , KY 41267 Location: 5 Hode Rd Type of Work: Complaints Material Used: Customer Line Inspection Problem on Customers 5, de Comments: no water **Current System Information:** New Information: Meter # 1: 29935145 Meter#1: Meter # 2: Radio Meter # 2: Radio فالمستعملة فمستعب الموافكة المعارض الدارات الأراسات الوارا أتدران إيا للممهور ومهسست MXU#: MXU#; Current Reading 0 Current Reading 1/20/2016 445 Type of Meter: Type of Meter: Badger and the second s 2004 Year MFG: Year MFG: GPS - Longitude 0 GPS - Latitude 0

Employee Signature(s):

Date Completed 2-18-/6

Martin County Water District 387 East Main St., Suite 140

Inez, KY 41224

WORK ORDER

	WO#	160200	0184			
Tir	Vork Complete					
. "						
Date 2/16/2016		Account#	SEQ# 494			
Name: MARK	FITCH		Phone # (
Address:W	eeping Cherry Ln	Accommendated Secretal Accommendates the Control of	Employee Troy Horn			
INEZ	, KY 41224]	They they recommended to the second to the s	* * -			
Location: W	eeping Cherry Ln	Managan ta masa Managan ta ka ka ta ka	No Alexandra Control of the Control			
Amenican et a 2 head from						
ABBS	LANE					
Type of Work: C	complaints					
Material Used:						
- Customer Line I	concediani COO 1	, a 111 to	of 3/4" line; 3/4 to 1" starblate 3/4 in line across bridges			
		state is	79 in line actions budge			
Comments: no v	water					
Currer	nt System Information:	***************************************	New Information:			
Meter#1:	29934818		Meter # 1:			
Meter#2: Radio			Meter # 2: Radio			
MXU #:			MXU #:			
Current Reading	1/20/2016 1072		Current Reading 0			
Type of Meter:	Badger		Type of Meter:			
Year MFG:	2004		Year MFG:			
GPS - Longitude	0		GPS - Latitude 0			
Employee Signa	ture(s): JS,CS,T	H	Date Completed 2/7/16			

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

160200190 WO# Work Complete Time Started Master Meter # Loc# Date 2/17/2016 Account # SEQ # 82 Phone # DIANA SLONE Name: Employee Rainbo Address: ___ Phoebe Trace Rd. BEAUTY , KY 41203 Location: Pheobe Trce PHOEBE TRACE Type of Work: Complaints Material Used: Comments: customer and neighbors have nothing but air in lines New Information: **Current System Information:** 29934831 Meter # 1: Meter # 1: Meter # 2: Radio Meter # 2: Radio MXU#: MXU#: Current Reading 0 Current Reading 1/20/2016 280 Badger Type of Meter: Type of Meter: Year MFG: Year MFG: GPS - Latitude 0 GPS - Longitude 0

Date Completed

Employee Signature(s):

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

160200025 Loc# « Master Meter# Date 2/3/2016 Account# Name: HELEN MCGINNIS Phone.# (Address: __ Tomahawk Road Employee Justin Scott TOMAHAWK, . KY 41262 Location: Tomahawk Rd; Donna Jude **ROUTE 40 WEST** Type of Work: Complaints Material Used: Changed out 8 an Softer ad Relatour Customer Line Inspection She Said Hut Comments: low pressure; check for problems **Current System Information:** New Information: Meter # 1: 94261251 Meter #1: Meter # 2: Radio Meter # 2: Radio MXU#: MXU#: Current Reading 1/20/2016 615 Current Reading 0 Badger Type of Meter: Type of Meter: 1994 Year MFG: Year MFG: GPS - Longitude 0 GPS - Latitude

Date Completed 2 - 9 - 16

Employee Signature(s): \(\int \)

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO #	16030	0204	
Time	e Started	,	Work Complete	and the same of th
Loc#	managa gamagang sing attig di 15 dan ja 18 dan dereng den an antibio di	Master N	latar #	
Date 3/23/2016	magar by m (m) by Mar	Account#	a manga manga at a man man man and a same a	SEQ# 276
Name: ILENE	HARDIN		Phor	ne# (
Address: 3 No	orth Milo Rd.	maring and the same of the same of		loyee Troy Horn
TOMAH	IAWK , KY 41262	ه چوه در	and the second s	
Location: No	orth Milo Rd.On the right a	ifter Pack Bottom o	hurch.Grey house	w/red roof and shutters.
	e alexandra e a accidente		manananan kananan kana Lamanan kananan kanana	
ROUTE	1884 MILO			
Type of Work: Co	mplaints		n garan sakhadding si diank jiyo saya way waxanay kananay kananay ka sayan wa sa sa sa sa sa	and the second control of the second control
Material Used:	and the same and t	(n)	1	and the state of t
Customer Line Ins		(Hore	{ \	
Comments: low y	vater pressure since last n	ight Orbote	loops 1	Lt hox
[,	System Information:		<u> </u>	New Information:
Meter#1:	70472580	···································	Meter # 1:	٠, ١٠٠٠ منظم مستحد الدارية المتوسوبة ليدعو
Meter # 2: Radio	ha an amining of him superior of day for foreigness the antimetrate at more than	onnounced by the	Meter#2: Radio	- man a contract of the contra
MXU #:	:	r manuscop, as d	MXU #:	nga danamakan basasa nus li widil wisibanan santw
Current Reading	2/20/2016 309	- Januarian Addin Alago	Current Reading	0
: Type of Meter:	Sensus	n i i i i i i i i i i i i i i i i i i i	Type of Meter:	THE STREET AND DESCRIPTIONS AND ADDRESS OF STREET
;	2009		Year MFG:	The state of the s
GPS - Longitude	0 ,	or waters and the	GPS - Latitude	0

Employee Signature(s):

Date Completed

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

160300161 \

Time Started

Work Complete L

Loc#

Master Meter#

Date 3/16/2016

Account#

SEQ # 154

Name: Willie Mollette Jr.

Phone #

Address:

Emily Crk

Employee Troy Horn

Pilgrim, KY 41250

Location: 4 Emily Crk, White house with green roof above Terry Harmon on right

Emily

Type of Work: Complaints

Material Used: Spoke with Customer Has wester. Good pressure in Camade + Bath tube Just law pressure in Kirchen sink, Customer Line Inspection: Problem with Customer.

Comments: meter was relocated; now customer has no water

Current System Information:

New Information:

Meter # 1:

70840680

Meter # 1:

Meter # 2: Radio 70840680

Meter#2: Radio

MXU#:

MXU#:

Current Reading 2/20/2016 235

Current Reading

Type of Meter:

0

Type of Meter: Sensus

Year MFG:

Year MFG:

GPS - Longitude 0

GPS - Latitude 0

Employee Signature(s): 28/Tz/Js

Date Completed 3/22//6

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

160300208

Time Started

Work Complete

Loc#

Master Meter #

Date 3/24/2016

Account#

SEQ# 185

Name: Gracie Reed

Phone# (,.

Address: PO Box

Employee Rainbo

Beauty, KY 41203

Location: Cliffside Dr, Moore's Trailer Prk, Last trailer on the right on the bank, brown

: I Cliffside Dr

Type of Work: Complaints

Material Used:

Customer Line Inspection

Comments: 626-6846

no water pressure

Pumps of

New Information:

Current System Information:

Meter#1:

Meter # 1:

16721209

Meter # 2: Radio

MXU#:

MXU#:

Current Reading 2/20/2016 761

Meter # 2: Radio 16721209

Current Reading

0

Type of Meter: Badger

Type of Meter:

Year MFG:

2000

Year MFG:

GPS - Longitude 0

GPS - Latitude 0

Employee Signature(s):

Date Completed

3-24-16

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

160200212 WO# Time Started Work Complete Master Meter # Date 2/19/2016 Account # 1 ___ . SEQ # 84 Phone # () Name: EDDIE HINKLE Address: P.O.BOX (_ Employee Rainbo BEAUTY , KY 41203 Bone Holw 2031.Lower Poplar.Bone Hollow.1st trailer on right at top of hill.Grey & white. Location: Type of Work: Complaints Material Used: Customer Line Inspection new pump Comments: wants to know why the water is so nasty. New Information: **Current System Information:** Meter #1: 97728662 Meter # 1: Meter#2: Radio Meter # 2: Radio MXU#: MXU #: Current Reading 0 Current Reading 1/20/2016 853 Type of Meter: Badger Type of Meter: 1997 Year MFG: Year MFG: GPS - Latitude 0 GPS - Longitude 0

Date Completed

Employee Signature(s): RT

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

160200221

Time Started		garangen selapantha negapin plateting	Work Complete		
Loc#	man reproduktivatelytek e sam		Master Meter	#	
Date 2/22/20	16	Accound	l# 1		SEQ # 85
Name: MA	GGIA HINKLE	A company of the second district control of the Action of		Phon	e# (
Address: PO	вох	Some section will be sectioned and section of the s		Empl	oyee Rainbo
BE	AUTY , K	Y 41203			
Location:	.' Bone Hollow on	2031, 1/4 of a mile on	Poplar Fork (on left, 1st singl	le wide on left
,A.			*******	er og som mendelsminket et er er	
مناب عو بو	. i i	As a play assumed that the second sec	, is pulled annual ways and	Annual An	ik is is dig 2 of 5 Wiley . Journal R. p. Westmensch is Meistensch Kart Gebergeberger
Type of Work	c: Complaints			¥	
Material Used					
	ne Inspection:				
Comments: 1	ow pressure	/ installed	New Por	mp	58 psi @lox
Си	rrent System Info	ormation:		N	lew Information:
Meter#1:	99085837		M	leter#1:	
Meter#2: Ra	odio 99085837		N	leter#2: Radio	quantity and a management of the same of t
MXU #:			N	1XU #:	
Current Read	ding 1/20/2016	623	c	turrent Reading	0
Type of Mete	r; Badger		T	ype of Meter:	
Year MFG:	1999			ear MFG:	
GPS - Longit	F To makes on which the said statement			SPS - Latitude	0
and the same of th					711
Employee Si	gnature(s):	KZ		Date Comp	pleted 22/16

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

160300142

Time Started

Work Complete

Loc#

Master Meter #

Date 3/14/2016

Account# 4

tightered fitting

SEQ # 56

Name: Dick Young

Phone # (

Address:

Flat Hollow

Employee Rainbo

Inez, KY 41224

Location: Flat Hollow, Last house

Flat Hollow

Type of Work: Complaints

Material Used:

Customer Line Inspection

Comments: no water

New Information:

Meter # 1:

95748912

Current System Information:

Meter#1:

Meter # 2: Radio 95748912

Meter # 2: Radio

MXU#:

MXU #:

* Current Reading 2/20/2016 952

Current Reading

Type of Meter: Badger

Type of Meter:

Year MFG:

1995

Year MFG:

GPS - Longitude

GPS - Latitude

Employee Signature(s):

Date Completed 3/14/16

, 0

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 160200226 Time Started Work Complete Master Meter # Loc# SEQ # 347 Account # Date 2/23/2016 Phone # (6 Marcia Mills Name: Address: PO Box 7 Employee Troy Horn , KY1 41224 Inez Location: Tug River Rd, Trailor past Holbert Mills house on left Type of Work: Complaints Material Used: Customer Line Inspection: Lecked Drg. not Crushed, Cleared for him.

Comments: MCWD unloaded equipment and crushed drain pipe; needs repaired and gravel needs put down **Current System Information:** New Information: 70616407 Meter # 1: Meter # 1: Meter # 2: Radio 70616407 Meter # 2: Radio 13153136 MXU#: MXU#: Current Reading 1/20/2016 262 Current Reading 0 Type of Meter: Type of Meter: and the second s Year MFG: Year MFG: GPS - Longitude GPS - Latitude

Employee Signature(s):

Date Completed 3 11/16

Ř

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

160300156

Time Started

Work Complete

Loc#

Master Meter #

Date 3/16/2016

Account #

SEQ # 130

Name: Kenneth Aldrich

Phone# (***

Address: Jollins Crk

Employee Justin Scott

Warfield, KY 41267

Location: Yellow Crk Rd. White trailer on the left.

Yellow Crk Rd

Type of Work: Complaints

Material Used:

Customer Line Inspection

Comments: water stinks

all the wax up Blanken Ship

New Information:

Current System Information:

47823868 Meter # 1:

Meter #1:

Meter # 2: Radio 47823868

Meter # 2: Radio

MXU#:

Current Reading 2/20/2016 486

Current Reading

MXU#:

0

Type of Meter:

Sensus

Type of Meter:

Year MFG:

1993

Year MFG:

GPS - Longitude 0

GPS - Latitude 0

Employee Signature(s):

Date Completed 3 - /2 -/6

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

160200254

Time Started		Work Complete			
Loc#		Master Meter	#		
Date 2/24/2016		Account #	SEQ# 510		
Name: SHON	NIE PAULEY	V-1100	Phone # (C		
Address: P.O.BO	OX ,		Employee Rainbo		
Pilgrim	, KY 41250				
Location:L	ittle Rockcastle Rd just as	you start up 2032 hill,tu	ırn right at Jude's feed store,house up on the hill		
Type of Work: C	omplaints	- NOTE STORMS BUILDING			
Material Used:	menne, en en e	and a county Shade (a). Sadder control control of the control of t	were against \hat{W} , we have an interesting an interesting \hat{W} , which is the state of \hat{W}		
Customer Line Ir	nspection:				
Comments: Low	Pressure				
Curren	t System Information:	k MA idea discourse in the second sec	New Information:		
Meter # 1:	29934956	M	eter # 1:		
Meter # 2: Radio	The second secon	М	eter # 2: Radio		
MXU #:	t ist judica Production community adolphic to the time seems.	M	XU#:		
Current Reading	1/20/2016 404	C	urrent Reading 0		
Type of Meter:	Badger	T	ype of Meter:		
Year MFG:	2004	Y	ear MFG:		
GPS - Longitude	0		PS - Latitude 0		
Employee Signal	iure(s):	eratt säägymin olisen) säännin en ja erakkii er	Date Completed		

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

		WO #	16020021	7		
	Time Started	t and the second	Work	Complete	guit agu air simpleochaid fhain is shife suid.	
Loc#	and the second s	• ••••	Master Meter	#	we will be a beautiful and the second	nagami na ya nagangandanani
Date 2/22/20	16	Accou	unt#	· · · · · · · · · · · · · · · · · · ·	SEQ # 4	and the second
Name: BE	CKY GRIFFITH			Phor	ne# (60(
Address: PO	вох		WAY MAR PAR PROPERTY AND ADMINISTRATION AND ADMINISTRATION OF THE PARTY AND ADMINISTRATION OF	Emn	loyee Justin Scott	
INE						
Location:	E Main St, across fr	om Pizza Stop	44 A 15 M V VICE TO VI			
Material Used Customer Lin Comments:	c: Complaints d: ne Inspection: ow pressure; check p	ba il-			-60X	
Cur	rent System Inform	ation:			New Information:	
Meter # 1:	19667728		Me	eter # 1:		
Meter # 2: Ra	dlo		Me	eter#2: Radio		
MXU #:	alle alle alle and a second and	# 5 12	M	KU #:	- Vigoriania de la produción de la Milla de Milla de la Cambrida d	
Current Read	ling 1/20/2016 434		Cı	irrent Reading	00	···
Type of Mete	r: Badger		Ту	pe of Meter:		
Year MFG:	2003	om anna alamateria ntiya 114 - 14 ja 1400 magga	Ye	ear MFG:		
GPS - Longite	ude 0		G	PS - Latitude	0	

Employee Signature(s): 3

Date Completed 5

Martin County Water District 387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO #	160300030	
Time Started	Work Co	omplete
Loc#		
Date 3/3/2016	Account # {	SEQ# 128
Name: Vina Sue PREECE		Phone #
Address: Blacklog Rd		Employee Rainbo
INEZ, , KY 41224		_
Location: Preece Hill on Blacklog; Tri-le	vel house.3rd driveway.	·
ROUTE 40 EAST		The!
Type of Work: Complaints		
Customer Line Inspection: Comments: now water		
Current System Information:	A STATE OF THE STA	New Information:
Meter # 1: 29935412	Meter	r#1:
Meter # 2: Radio	Meter	r#2: Radio
MXU #:	MXU	#:
Current Reading 2/20/2016 450	Curre	ent Reading 0
Type of Meter: Badger		of Meter:
Year MFG: 2004	Year	MFG:
GPS - Longitude 0	GPS	- Latitude 0
Employee Signature(s): // / / K		Date Completed 3/7//

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO # 160200266

Tid	me Started	N	/ork Complete	
Loc#	mental agramment of an	Master Me	eter#	
Date 2/26/2016	g and the second	Account #	SEQ # 11	one est describe
Name: Denzil	Marcum	ad a part of the property of the company of the com	Phone #	gampaga alba san aran di sebita sa di dikaba
Address: PO Bo	×(.		Employee Rainbo	de Landon West State State
Lovely	, KY 41231		W	
Location: L 'Vir	ginia St, 2nd on right, beig	e house w/maroon sh	nutters	
GASC	DLINE ALLEY			Lating in principles and the second s
Type of Work: C	Complaints			manuscrup ord Alleit & Pilyttist (A. et sjeld
Material Used:		de		nagana ang pangaban sa nagantan 48
Customer Line I	nspection	(A)		man grider on hitty dr
Comments: has	low pressure / Tal	ked to Co	Stores Ed Hall gr See H-1/e Had-a-legk New Information:	sod phero
Curren	nt System Information:		New Information:	
Meter # 1:	98604661		Meter # 1:	
Meter#2: Radio			Meter # 2: Radio	,
MXU#:	and the second of the second contract of the	inne garage and provide delivers	MXU #:	- an may on 4 som of or
Current Reading	2/20/2016 486	-g-0-0-0	Current Reading 0	4,000,000
Type of Meter:	Badger	****	Type of Meter:	
Year MFG:	1998	nema daugas - edit - edit	Year MFG:	o year and a second second second
GPS - Longitude	9 0	· danggi na nama	GPS - Latitude 0	
Employee Signa	nture(s):	and the state of t	Date Completed 3-8-	16

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 160400211

Time Started	Work Complete
Loc#	Master Meter #
Date 4/22/2016	Account# SEQ # 223
Name: Miranda McCoy	Phone # (
Address: P.O. Box	Employee Rainbo
Beauty, KY 41203	. .
Location: Big Elk Rd. Across from War	ter Tower, grey trailer
	The second of th
· Big Elk Rd	
Type of Work: Complaints	s ann sand lany
Material Used:	
Customer Line Inspection 65 168	PSI @ boox
Comments: no water	and the second s
Current System Information:	New Information:
Meter # 1: 29935189	Meter # 1:
Meter # 2: Radio 29935189	Meter # 2: Radio
. MXU #:	MXU #:
Current Reading 4/20/2016 426	Current Reading 0
Type of Meter: Badger	Type of Meter:
Year MFG: 2004	Year MFG:
GPS - Longitude	GPS - Latitude
Employee Signature(s):	Date Completed 4/22/10

387 East Main St., Suite 140 Inex, KY 41224

WORK ORDER

WO#

160400195

Time Started

Work Complete

GPS - Latitude

Date Completed 4-21-16

Loc#

GPS - Longitude

Employee Signature(s): RJ

Master Meter #

Date 4/20/2016	Account #	SEC)# 49 6
Name: Charlene Daniels		Phone #	(*
Address: Wooten Rd		Employe	e Justin Scott
Tomahawk, KY 412	62		
Location: Wooten, 7th double	wide on left, grey w/blue shutter	rs. Wooten Rd	
Tomahawk		and a set of any own of	
Type of Work: Complaints	Hod 90 Fat	box I to	ld her
Material Used: It Prol	aley was the	P.R.V stage	UPD:
Customer Line Inspection:			y Ni american en en en
Comments: LOW WATER PR	ESSURE (V) OL		
Current System Info	ormation:	New	Information:
Meter # 1: 17762829		Meter # 1:	
Meter # 2: Radio		Meter # 2: Radio	
MXU#:	•	MXU #:	,
Current Reading 3/20/2016	442	Current Reading	
Type of Meter: Badger		Type of Meter:	
; Year MFG: 2002		Year MFG:	

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO #

160400121

Time Started

Work Complete

Loc#

Master Meter #

Date 4/11/2016

Account# 1

SEQ# 253

Name: Rowdy Kinser

Phone # (

Address: PO Box

Employee John Mills

Lovely, KY 41231

Location: 2, Riverfront Rd, 3rd blacktop drive on right past Riverfront Store

RIVERFRONT

Type of Work: Complaints

Put in a Preserve Chart 1-74 tee 3- 1 Niegele

Material Used:

Customer Line Inspection:

Comments: low pressure

Showing 100 PSI

Install a Chart for I day to Chart austr Preson & flagor of electe

Current System Information:

New Information:

Meter # 1:

70750157

Meter # 1:

Meter # 2: Radio

Meter#2: Radio

MXU#:

MXU#:

Current Reading 3/20/2016 242

Current Reading

Type of Meter: Sensus

Type of Meter:

Year MFG:

2009

Year MFG:

· GPS - Longitude

GPS - Latitude

Employee Signature(s): JS, TR, CS, RJ.

Date Completed 4-//-//

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO #

Time Started

Customer Line Inspection: Shat off

160300242

Work Complete

Comments: hissing noise and water is coming from box even though meter has been pulled; land owner reported

Current System Information:		New Inf	New Information:		
Meter # 1:		Meter#1:			
Meter#2: Radio		Meter#2: Radio			
MXU #:		MXU #:			
Current Reading	0	Current Reading	0		
Type of Meter:		Type of Meter:			
Year MFG:		Year MFG:	•		
GPS - Longitude		GPS - Latitude			
Employee Signature(s):	75	Date Completed	4-1-16		

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

160300208

Time Started

Work Complete Yes

Loc#

Master Meter #

Date 3/24/2016

Account # 1

SEQ # 185

Name: Gracie Reed

Address: PO Box 1

Phone # (

Beauty, KY 41203

Employee Rainbo

Location: '

Cliffside Dr, Moore's Trailer Prk, Last trailer on the right on the bank, brown

3 Cliffside Dr

Type of Work: Complaints

Material Used:

Still has same issue

Customer Line Inspection: pump is on

Comments: 626-6846

no water pressure

Current System Information:

New Information:

0

Meter # 1:

16721209

Meter # 1:

Meter # 2: Radio 16721209

Meter # 2: Radio

MXU#:

MXU#:

Current Reading 2/20/2016 761

Current Reading Type of Meter:

Type of Meter. Badger

Year MFG:

2000

Year MFG:

GPS - Longitude 0

GPS - Latitude 0

Employee Signature(s):

Date Completed

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO #

160300208

Time Started

Work Complete Yes

Loc#

Master Meter #

Date 3/24/2016

Account #

SEQ# 186

Name:

Gracie Reed

Phone # 🔩

Address: PO Box : .

Employee Rainbo

Beauty, KY 41203

Location:

o Cliffside Dr. Moore's Trailer Prk, Last trailer on the right on the bank, brown

· Cliffside Dr

Type of Work: Complaints

Customer Line Inspection: purnp is on

ut asual that was on was out Kernit

the purp was out no water pressure

Comments: 626-6846

Current System Information:

New Information:

Meter # 1:

16721209

Meter #1:

Meter # 2: Radio 16721209

Meter#2: Radio

MXU#:

MXU#:

Current Reading 2/20/2016

Current Reading

! Type of Meter: Badger

Type of Meter:

Year MFG:

2000

Year MFG:


GPS - Longitude 0


GPS - Latitude 0


Employee Signature(s): RT


Date Completed


Exhibit #11 Telementry Pressure Charts














Exhibit #12
Public Notification

ur water system recently violated a drinking water standard. Althout appened and what we did (are doing) to correct this situation. fe routinely monitor for the presence of drinking water contaminants. Testing results from 1/1/2013 through 3/31/2013 show that our system exceeds the andard, or maximum conteminant level (MCL), for trihelomethanes (THM) and heloscotic acids (HAA). The standard for THM is 0.080 mg/L and the andard for HAA is 0.060 mg/L. These are determined by averaging all samples collected by our system for the last 12 months. The level of THM average our system for 1/1/2013 to 3/31/2013 was 0.083 mg/L and HAA was 0.086 mg/L.,

- There is nothing you need to do. You do not need to boil your water or take other corrective actions. If a situation arises where the water is no longer safe to drink, you will be notified within 24 hours. If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek advice from your health care providers about drinking this water,

ome people who drink water containing Inhalomethanes in excess of the MCL over many years may experience problems with their liver, kidneys, or central reaus system, and may have an increased risk of gelling cancer. Some people who ddnk water containing haloacolic acids in excess of the MCL over any years may have an increased risk of gelling cancer.

ris is not an emergency. If it had been an emergency, you would have been notified within 24 hours.

To are working to minimize the formation of trihatemothenes and halcacetic acids white ensuring we maintain an adequate level of disinfectant. We have ken additional steps to change disinfectant types/levels, remove natural organic matter, and increased flushing of water fines to determine if our efforts have son effective. We are also maniforing water storage tank levels and water flow patterns within the distribution system, We anticipate resolving the problem

n, please contact John Mills at (606) 296-3885 or 387 E Main St. Suite 140, Inez, KY 41224

ease share this information with all the other people who drink this water, especially those who may not have received this natice directly (for exemple, ropia in apartments, nursing homes, achoots, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

In 2012, Martin County Water District detected 13 contaminants in the drinking water and none of them were above the EPA accepted level for drinking water. Please go to www.krwa.org/2012cc/martincounty.pdf to view your 2012 annual water quality report and learn more about your drinking water. This report contains important information about the source and quality of your drinking water. To speak with someone about the report, please call (606) 298-3885. If you would like a paper copy of the 2012 Annual Water Quality Report mailed to your home please check the paper copy box and mail back with your payment or call (606) 298-3885, Mail a copy 🗖

Notice by Martin County Water Diatrict — System ID#: KY0890273 ur water system recently violated a drinking water standard, Although this incident was not an emergency, as our customers, you have a right to know what appends and what we did (are doing) to correct this situation.

'e routinely monitor for the presence of drinking water contentinants, Testing results from 1/1/2013 through 3/31/2013 show that our system exceeds the anderd, or maximum conteminant level (MCL), for trihelomethanes (THM) and haloacetic acids (HAA). The standard for THM is 0,090 mg/L and the anderd for HAA is 0.060 mg/L. These are determined by averaging all samples collected by our system for the last 12 months, The level of THM averaged our system for 1/1/2013 to 3/31/2013 was 0,083 mg/L and HAA was 0.058 mg/L.

- There is nothing you need to do, You do not need to boil your water or take other corrective actions, if a situation erises where the water is no longer safe to drink, you will be notified within 24 hours.
 If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek advice from your health care providers about drinking this water.

amo people who drink water containing trinalomethanes in excess of the MCL over many years may experience problems with their liver, kidneys, c arrous system, and may have an increased risk of getting cancer. Some people who drink water containing heloecetic acids in excess of the MCL o any years may have an increased risk of getting cancer.

nie is not an emergancy. If it had been an emergancy, you would have been notified within 24 hours.

The are working to minimize the formation of trihalomethanes and haloscatic acids white onsuring we maintain an adequate level of disinfectant. We have ken additional steps to change disinfectant types/levels, remove natural organic matter, and increased flushing of water lines to determine if our efforts have no effective. We are also monitoring water storage tank lovels and water flow patterns within the distribution system, We anticipate resolving the problem thin the rest quarter.

or more information, please contact John Mills at (606) 298-3885 or 387 E Main St. Suite 140, Inez, KY 41224

ease share this information with all the other people who drink this water, especially those who may not have received this notice directly (for exemple, topie in epartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

In 2012, Martin County Water District detected 13 contaminants in the drinking water and none of them were above the EPA accepted level for drinking water. Please go to www.krwa.org/2012ccr/martincounty.pdf to view your 2012 annual water quality report and learn more about your drinking water. This report contains important information about the source and quality of your drinking water. To speak with someone about the report, please call (606) 298-3885. If you would like a paper copy of the 2012 Annual Water Quality Report

mailed to your home please check the paper copy box and mail back with your payment or call (606) 298-7439. Mail a copy 🗖

THM & HAA Stage I DBPR Template 2-18

Insert water system name and IDS in header, Insert compliance period begin date, and date, and average level. Remove brackets.

Do not modify mandatory

Replace explanation language with your own to explain what happened, what is being done and date that compliance is anticipated

Insert contact information,

No text below this point,

Copy and paste notice. Prior to paste make sure that the cursor is at the highest point In the text box.

Notice by Martin County Water District - System ID#: KY0800273

Our water system recently violated a drinking water standard. Although this incident was not an emergency, as our customers, you have a right to know what happened and what we did (are doing) to correct this situation.

We are required to monitor your drinking water for specific contaminants on a regular basis. Results of regular monitoring are an indicator of whether or not our drinking water meets health standards. During 2/1/2013 – 2/28/2013, we did not complete all monitoring or testing for chlorine and turbidity, and therefore cannot be sure of the quality of your drinking water during that time.

There is nothing you need to do at this time. You may continue to drink the water. If a situation arises where the water is no longer safe to drink, you will be notified within 24 hours.

By the 10th of each month we must submit a Monthly Operation Report (MOR) to the Division of Water. The MOR for February 2013 did not arrive by the required deadline and this caused three violations. One violation for not submitting the MOR by the required deadline, another for not submitting daily chlorine results, and another for failing to submit the daily turbidity readings. (The chlorine results and turbidity readings are contained within the MOR.) We have modified our procedures to assure that the MOR arrives by the required deadline.

For more information, please contact John Mills at (606) 298-3885 or 387 E Main St. Suite 140, Inez, KY 41224

Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

Notice by Martin County District — System ID#: KY0800273

Dur water system recently violated a drinking water standard. Almough this incident was not an emergency, as our customers, you have a right to know what happened and what we did (are doing) to correct this situation.

We are required to monitor your drinking water for specific contaminants on a regular basis. Results of regular monitoring are an indicator of whether or not our drinking water meets health standards. During 2/1/2013 – 2/28/2013, we did not complete all monitoring or testing for chlorine and turbidity, and therefore cannot be sure of the quality of your drinking water during that time.*

There is nothing you need to do at this time. You may continue to drink the water. If a situation arises where the water is no longer safe to drink, you will be notified within 24 hours.

By the 10th of each month we must submit a Monthly Operation Report (MOR) to the Division of Water. The MOR for February 2013 did not arrive by the required deadline and this caused three violations. One violation for not submitting the MOR by the required deadline, another for not submitting daily chlorine results, and another for failing to submit the daily turbidity readings. (The chlorine results and turbidity readings are contained within the MOR.) We have modified our procedures to assure that the MOR arrives by the

For more information, please contact John Mills at (606) 298-3885 or 387 E Main St. Suite 140, Inez, KY 41224

Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

Notice by Martin County Water District – System ID#: KY0800273
Our water system recently violated a drinking water standard. Although this incident was not an emergency, as our customers, you have a right to know what happened and what we did (are doing) to correct this situation.

We are required to monitor your drinking water for specific contaminants on a regular basis. Results of regular monitoring are an indicator of whether or not our drinking water meets health standards. During 2/1/2013 - 2/28/2013, we did not complete all monitoring or testing for chlorine and turbidity, and therefore cannot be sure of the quality of your drinking water during that time.

There is nothing you need to do at this time. You may continue to drink the water. If a situation arises where the water is no longer safe to drink, you will be notified within 24 hours.

By the 10th of each month we must submit a Monthly Operation Report (MOR) to the Division of Water. The MOR for February 2013 did not arrive by the required deadline and this caused three violations. One violation for not submitting the MOR by the required deadline, another for not submitting daily chlorine results, and another for failing to submit the daily turbidity readings. (The chlorine results and turbidity readings are contained within the MOR.) We have modified our procedures to assure that the MOR arrives by the required deadline.

For more information, please contact John Mills at (806) 298-3885 or 387 E Main St. Suite 140, Inez, KY 41224

Elease share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

Template 3-2 Manitoring

Do not modify mandatory

No text below this point,

Copy and paste notices. Prior to paste make aure that the cursor is at the highest point in the text box.

Notice by Martin Coun: Spatrat - System ID#: KY0800273

Our water system recently violated a drinking water requirement. Atthough this was not an emergency, as our customers, you have a right to move what happened, what you should do, and what we did (are doing) to correct this situation.

We routinely monitor your water for turbidity (cloudiness). This tells us whether we are effectively filtering the water supply. Water samples for lanuary 2014 showed that 5.4 percent of turbidity measurements were over 0.3 turbidity units — the standard is that no more than 5 percent of samples may exceed 0.3 turbidity units per month. The turbidity levels are relatively low. However, their persistence is a concern. Normal surbidity levels at our plant are 0.1 units. This is not an emergency. If it had been, you would have been notified within 24 hours.

- There is nothing you need to do. You do not need to boil your water or take other actions. We do not know of any contamination, and none of our testing has shown disease-causing organisms in the drinking water.
 If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek advice from your health care providers about drinking this water. General guidelines on ways to lessen the risk of infaction by microbes are available from EPA's Safe Drinking Water Hotline at 1-800-425-4791.

Turbidity has no health effects. However, turbidity can interfere with disinfection and provide a medium for microbial growth. Turbidity may indicate the presence of disease causing organisms. These organisms include bacteria, viruses, and parasites which can cause symptoms such as nausea, cramps, diarrhea, and associated headeches. These symptoms are not caused only by organisms in drinking water. If you experience any of these symptoms and they persist, you may want to seek medical advice.

We made repairs to our equipment. We inspected and cleaned the filters. The problem is resolved. For more information, please contact John Mills at (608) 298-3885 or 387 E Main St. Suite 140, Inez, KY 41224.

"Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, people in apertments, nursing homes, schools, and businesses). You can do this by posting this notice in a public piece or distributing copies by hand or mail.*

Notice by Martin County Water District – System ID#: KY0800273

Our water system recently violated a drinking water requirement. Although this was not an emergency, as our customers, you have a right to know what happened, what you should do, and what we did (are doing) to correct this situation.

We routinely monitor your water for turbidity (cloudiness). This tells us whether we are effectively filtering the water supply. Water samples for January 2014 showed that 5.4 percent of turbidity measurements were over 0.3 turbidity units – the standard is that no more than 5 percent of samples may exceed 0.3 turbidity units per month. The turbidity levels are relatively low. However, their persistence is a concern. Normal turbidity levels at our plant are 0.1 units. This is not an emergency, if it had been, you would have been notified within 24 hours.

- There is nothing you need to do. You do not need to boil your water or take other actions. We do not know of any contamination, and none of our testing has shown disease-causing organisms in the drinking water.

 If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek advice from your health care providers about drinking this water. General guidelines on ways to lessen the risk of infection by microbes are available from EPA's Safe Drinking Water Hotline at 1-800-426-4791.

*Turbidity has no health effects. However, turbidity can interfere with distriction and provide a medium for microbial growth. Turbidity may indicate the prosence of disease causing organisms. These organisms include bactoria, viruses, and parasites which can cause symptoms such as nausea, cramps, diamhea, and associated headaches. These symptoms are not caused only by organisms in drinking water, if you experience any of these symptoms and they persist, you may want to seek medical advice.

We made repairs to our equipment. We inspected and cleaned the filters. The problem is resolved. For more information, please contact John Mills at (605) 298-3885 or 387 E Main St. Suite 140, Inez, KY 41224.

Please share this information with all the office people who drink this water, especially those who may not have received this notice directly (for example; people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

Template 2-6 Turbidity

Do not modify mandatory

No text below this point

Copy and paste notice. Prior to paste make are that the cursor is at the highest point in the text box.

Notice by Martin County Water District - System ID#: KY0800273

Our water system recently violated a drinking water standard. Although this incident was not an emergency, as our customers, you have a right to know what happened and what we did (are doing) to correct this situation.

We routinely monitor for the presence of drinking water contaminants. Testing results from 7/1/2014 through 9/30/2014 show that our system exceeds the standard, or maximum contaminant level (MCL), for trihalomethanes (THM) and haloacetic acids (HAA). The standard for THM is 0.080 mg/L and the standard for HAA is 0.060 mg/L. These are determined by averaging all samples collected at each sampling location for the last 12 months. The level of THM averaged at one of our system's locations for 7/1/2014 to 9/30/2014 was 0.101 mg/L and HAA was 0.081 mg/L.

- There is nothing you need to do. You do not need to boil your water or take other corrective actions. If a situation arises where the water is no longer safe to drink, you will be notified within 24 hours.
- If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek advice from your health care providers about drinking this water.

Some people who drink water containing trihalomethanes in excess of the MCL over many years may experience problems with their liver, kidneys, or central nervous system, and may have an increased risk of getting cancer. Some people who drink water containing haloacetic acids in excess of the MCL over many years may have an increased risk of getting cancer.

This is not an emergency. If it had been an emergency, you would have been notified within 24 hours.

We are working to minimize the formation of trihalomethanes and haloacetic acids while ensuring we maintain an adequate level of disinfectant. We have taken additional steps to change disinfectant levels, remove natural organic matter, and increased flushing of water lines to determine if our efforts have been effective. We are also monitoring water storage tank levels and water flow patterns within the distribution system. We anticipate resolving the problem within the next quarter but the compliance calculation is based upon annual averages and it may be several quarters before compliance is achieved.

For more information, please contact John Mills at 606-298-3885 or 387 E Main St. Suite 140, Inez, KY 41224.

Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

பகபான – aystem ruw; காமலம்273 எ cident was not an emergency, as our customers, you have a right to k ைட்ர்

אינטונט שין אומדונה שטינט אינטונט שין אומדונה שטינט אינטונט שין אומדונה שטינה: water system recently violated a dirinking water standard. Althour, sened and what we did (ere doing) to correct this situation. fe routinely monitor for the presence of drinking water conteminants. Testing results from 7/1/2014 through 9/30/2014 show that our system exceeds the andard, or maximum conteminant level (MCL), for irrinelometranes (THM) and haloacetic acids (HAA). The standard for THM is 0,080 mg/L and the andard for HAA is 0,060 mg/L. These are determined by averaging all samples collected at each sampling location for the last 12 months. The level of THM reraged at one of our system's locations for 7/1/2014 to 9/30/2014 was 0,101 mg/L and HAA was 0,081 mg/L.

- ere is nothing you need to do. You do not need to boil your water or take other corrective actions. If a situation arises where the water is no
- In you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek advice from your health care providers about drinking this water,

te people who drink water containing tritalomethanes in excess of the MCL over many years may experience problems with their liver, kidneys, or central ous system, and may have an increased risk of getting cancer. Some people who drink water containing haloacetic acids in excess of the MCL over by years may have an increased risk of getting cancer.

its is not an emergency, if it had been an emergency, you would have been notified within 24 hours.
To are working to minimize the formation of trihatomethanes and haloacetic acids white ensuring we maintain an adequate level of disinfectant. We have ken additional steps to change disinfectant levels, remove natural organic matter, and increased flushing of water lines to determine if our offorts have been factive. We are also monitoring water storage tank levels and water flow patterns within the distribution system. We anticipate resolving the problem within a next quarter but the compliance calculation is based upon annual averages and it may be several quarters before compliance is achieved.

or more information, please contact John Mills at 606-298-3685 or 387 E Main St. Suite 140, Inez, KY 41224:

'ease share this information with all the other people who drink this water, especially those who may not have received this incide directly (for example, apple in apartments, hursing homes, schools, and businesses). You can do this by posting this notice in a public place or distilluting copies by hand or mail.

Notice by Martin County Water District – System ID#: KY8809273 ur water system recently violated a drinking water standard. Although this incident was not an emergency, as our appened and what we did (are doing) to correct this situation. ency, as our customers, you have a right to know what

to routinely monitor for this presence of drinking water contaminants. Testing results from 7/1/2014 through 9/30/2014 show that our system exceeds the andard, or maximum contaminant level (MCL), for trihafornitizanes (THM) and haloecolic acids (HAA), The standard for THM is 0.080 mg/L and the andard for HAA is 0.030 mg/L. These are determined by averaging all semples collected at each sampling location for the last 12 months. The level of THM reraged at one of our system's locations for 7/1/2014 to 9/30/2014 was 0.101 mg/L and HAA was 0.081 mg/L.

- There is nothing you need to do. You do not need to boil your water or take other corrective actions. If a situation arises where the water is no longer safe to drink, you will be notified within 24 hours.
 If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek advice from your health care providers about drinking this water.

Imo people who drink water containing tributomethanes in excess of the MCL over many years may experience problems with their liver, kidneys, or central avoids system, and may have an increased risk of getting cancer. Some people who drink water containing haloacetic acids in excess of the MCL over any years may have an increased risk of getting cancer.

is is not an emergency. If it had been an emergency, you would have been notified within 24 hours.

The are working to minimize the formation of inhelomethanes and haloacotic acids within ensuring we maintain an adequate level of distinctions. We have ken additional steps to printing distinctional levels, remove natural organic matter, and introduced flushing of water lines to determine if our efforts have been focuse. We are also monitoring water storage tank levels and water flow patterns within the distribution system. We anticipate reaching the problem within a next quarter but the compliance calculation is based upon annual averages and it may be several quarters before compliance is achieved.

or more information, please contact John Mills at 608-298-3885 or 387 E Main St. Suite 140, Inex, KY 41224.

'éosé share this information with all the other people who clink this water, especially those who may not have received this notice circetly (for example, tople in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

THM & HAA Stage 2 DBPR Template 2-19

Insert water system name and ID# in header: Insert and 10% in header; insert compliance period begin date, end date, and average level. Remove brackets. Do not medify mandatory

Printing Instructions

This template is designed to print the notice on the back of the water bill sheets prior to printing the water bills using procedures the same as

After the notice has been printed to all sheets place the stack of sheets upside down on a flat aurifice and place a

When the stack of sheets have cooled and straightened print the water bills as usual.

No text below this point.

Copy and paste notice, Prior to paste make sore that the cursor is at the highest point in ibe test box.

Notice by Martin County Water District - System ID#: KY0800273

Our water system recently violated a drinking water standard. Although this incident was not an emergency, as our customers, you have a right to know what happened and what we did (are doing) to correct this situation.

We routinely monitor for the presence of drinking water contaminants. Testing results from 10/1/2014 through 12/31/2014 show that our system exceeds the standard, or maximum contaminant level (MCL), for trihalomethanes (THM) and haloacetic acids (HAA). The standard for THM is 0.080 mg/L and the standard for HAA is 0.060 mg/L. These are determined by averaging all samples collected at each sampling location for the last 12 months. The level of THM averaged at one of our system's locations for 10/1/2014 to 12/31/2014 was 0.096 mg/L and HAA was 0.105 mg/L.

- There is nothing you need to do. You do not need to boil your water or take other corrective actions. If a situation arises where the water is no longer safe to drink, you will be notified within 24 hours.
- If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek advice from your health care providers about drinking this water.

Some people who drink water containing trihalomethanes in excess of the MCL over many years may experience problems with their liver, kidneys, or central nervous system, and may have an increased risk of getting cancer. Some people who drink water containing haloacetic acids in excess of the MCL over many years may have an increased risk of getting cancer.

This is not an emergency. If it had been an emergency, you would have been notified within 24 hours.

We are working to minimize the formation of trihalomethanes and haloacetic acids while ensuring we maintain an adequate level of disinfectant. We have taken additional steps to change disinfectant levels, remove natural organic matter, and increased flushing of water lines to determine if our efforts have been effective. We are also monitoring water storage tank levels and water flow patterns within the distribution system. We anticipate resolving the problem within the next quarter but the compliance calculation is based upon annual averages and it may be several quarters before compliance is achieved.

For more information, please contact John Mills at 606-298-3885 or 387 E Main St. Suite 140, Inez, KY 41224.

Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

wower by martin county institute - System recently violated a drinking water standard, Although _ _ institute - System recently violated a drinking water standard, Although _ institute was not an emergency; as our customers, you have a right to knoppened and what we did (are doing) to correct this situation.

'e routinely monitor for the presence of crinking water contaminants. Testing results from 10/1/2014 through 12/31/2014 show that our system exceeds the andard, or maximum contaminant level (MCL), for trinsformations (THM) and haloacetic acids (HAA). The standard for THM is 0,080 mg/L and the andard for HAA is 0,060 mg/L. These ere determined by averaging all samples collected at each sampling location for the last 12 months. The level of THM reraged at one of our system's locations for 10/1/2014 to 12/31/2014 was 0,096 mg/L and HAA was 0,105 mg/L.

- There is nothing you need to do. You do not need to boil your water or take other corrective actions. If a situation enters where the water is no longer safe to drink, you will be notified within 24 hours.

 If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek advice from your health care providers about drinking this water,

ome people who drink water containing trihelomethanes in excess of the MCL over many years may experience problems with their liver, kidneys, or central propus system, and may have an increased risk of getting cancer. Some people who drink water containing haloscetic soids in excess of the MCL over any years may have an increased risk of getting cancer.

is is not an emergency. If it had been an emergency, you would have been notified within 24 hours, to are working to minimize the formation of tribalomethanes and haloacetic acids white ensuring we maintain an adequate level of disinfectant. We have ken additional steps to change disinfectant levels, remove natural organic matter, and increased flushing of water lines to determine if our efforts have been fective. We are also monitoring water storage tank levels and water flow patterns within the distribution system. We anticipate resolving the problem within a next quarter but the compliance calculation is based upon annual averages and it may be several quarters before compliance is achieved.

or more information, please contact John Milis at 606-298-3885 or 387 E Main St. Suite 140, Inez, KY 41224,

ease share this information with all the other people who drink this water, aspecially those who may not have received this notice directly (for example, social in apartments, nursing homes, schools, and businesses), you can do this by posting this notice in a public place or distributing captes by hand or mail.

Notice by Martin County Water District – System 10#: KY9800273 ur water system recently violated a drinking water standard, Although this incident was not an emergency, as our appened and what we did (are doing) to correct this situation. our oustomers, you have a right to know what

utinely monitor for this presence of drinking water conteminants. Testing results from 10/1/2014 through 12/31/2014 show that our system exceeds the strd or maximum conteminant level (MCL); for tribelemontanes (THM) and helpacelic ecids (HAA). The standard for THM is 0,080 mg/L and the strd for HAA is 0,060 mg/L. These are determined by everaging all samples collected at each sampling location for the last 12 months. The level of THM ged at one of our system's locations for 10/1/2014 to 12/31/2014 was 0.096 mg/L and HAA was 0,105 mg/L.

- There is nothing you need to do. You do not need to boil your water or take other corrective actions. If a situation arises where the water is no longer safe to drink, you will be notified within 24 hours.
 If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek advice from your health care providers about drinking this water.

ame people who didnk water containing tribalomethanes in excess of the MCL over mady years may experience problems with their twer, kidneys, or central irvous system, and may have an increased risk of getting cancer. Some people who drink water containing haloscotic acids in excess of the MCL over any years may have an increased risk of getting cancer.

tis is not an emergency. If it had been an emergency, you would have been notified within 24 hours. The are working to minimize the formation of trihalomatisanes and haloscotic acids white ansuring we maintain an adequate level of disinfectant. We have feen additional steps to change disinfectant levels, remove natural organic matter, and increased furshing of water tines to determine it our efforts have been focultive. We are also monitoring water storage tank fevols and water flow patterns within the distribution system. We anticipate resolving the problem within a next quarter but the compliance calculation is based upon annual everages and it may be several quarters before compliance is achieved.

or more information, please contact John Mills at 606-298-3985 or 387 E Main St, Suite 140, Inex, KY 41224.

'ease share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, topic in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

THM & HAA Stage 2 DBPR Template 2-19

insert water system name and ID# in header. Insert and 109 in neater. Insert compliance period begin date, end date, end average level, Remove brackets. modify mandatory language!

Printing Instructions

This template is designed to print the notice on the back of the water bill sheets prior to printing the water bills using procedures the same as printing a letter.

After the notice has been printed to all sheets place the stock of sheets upside down on a flat surface and place a weight on the stock to remove the curl.

When the stack of sheets have cooled and straightened print the water bills as usual.

No text below this point,

Copy and paste notice. Prior to paste make sure that the cursor is at the highest point in the text box.

Notice by Martin County Water District - System ID#: KY0800273

Our water system recently violated a drinking water requirement. Although this was not an emergency you have a right to know what happened. We routinely monitor your water for turbidity (cloudiness). This tells us whether we are effectively filtering the water supply. On 2/23/2015 we had a turbidity result of 1.195 NTU. This was above the standard of 1.0 NTU. Water samples for February 2015 showed that 6.58 percent of turbidity measurements were over 0.3 turbidity units – the standard is that no more than 5 percent of samples may exceed 0.3 turbidity units per month. The turbidity levels are relatively low. However, their persistence is a concern. Normal turbidity levels at our plant are 0.12 units. This is not an emergency. If it had been, you would have been notified within 24 hours.

- There is nothing you need to do. You do not need to boil your water or take other
 actions. We do not know of any contamination, and none of our testing has
 shown disease-causing organisms in the drinking water.
- If you have a severely compromised immune system, have an infant, are
 pregnant, or are elderly, you may be at increased risk and should seek advice
 from your health care providers about drinking this water. General guidelines on
 ways to lessen the risk of infection by microbes are available from EPA's Safe
 Drinking Water Hotline at 1-800-426-4791.

Turbidity has no health effects. However, turbidity can interfere with disinfection and provide a medium for microbial growth. Turbidity may indicate the presence of disease causing organisms. These organisms include bacteria, viruses, and parasites which can cause symptoms such as nausea, cramps, diarrhea, and associated headaches.

These symptoms are not caused only by organisms in drinking water. If you experience any of these symptoms and they persist, you may want to seek medical advice.

High turbidity on top of the filters occurred when a rake motor failed and due to high demand we had to continue operations. The problem was resolved within three days. For more information, please contact John Mills at (606) 298-3885 or 387 E Main St. Suite 140, Inez, KY 41224.

Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

Notice by Martin Coun r District - System ID#: KY0800273

Notice by Martin Coun r District – System ID#: KY0800273

If water system recently violated a drinking water requirement. Although this was not an emergency you have a right to know what happened. It routinely monitor your water for turbidity (cloudiness). This tells us whether we are effectively filtering the water supply. On 2/23/2015 we had turbidity result of 1.195 NTU. This was above the standard of 1.0 NTU. Water samples for February 2015 showed that 6.58 percent of turbidity easurements were over 0.3 turbidity units – the standard is that no more than 5 percent of samples may exceed 0.3 turbidity units per month, be turbidity levels are relatively low. However, their persistence is a concern. Normal turbidity levels at our plant are 0.12 units. This is not an nergency. If it had been, you would have been notified within 24 hours.

- There is nothing you need to do. You do not need to boll your water or take other actions. We do not know of any contamination, and none of our testing has shown disease-causing organisms in the drinking water.

 If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek advice from your health care providers about drinking this water. General guidelines on ways to lessen the risk of infection by microbes are available from EPA's Safe Drinking Water Hotline at 1-800-426-4791.

Turbidity has no health effects. However, turbidity can interfere with disinfection and provide a medium for microbial growth. Turbidity may dicate the presence of disease causing organisms. These organisms include bacteria, viruses, and parasites which can cause symptoms such singular new parasites which can cause symptoms such singular new parasites and characterial provides and only by organisms in drinking water, if you operience any of these symptoms and they parsist, you may want to seek medical advice.

igh turbidity on top of the filters occurred when a rake motor falled and due to high demand we had to continue operations. The problem was isolved within three days. For more information, please contact John Mills at (606) 298-3885 or 387 E Main St. Suite 140, finez, KY 41224.

Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for cample, people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing sples by hand or mail.*

2014 Martin County Water District annual water quality report is available. This report contains important information about your drinking water. Please go to http://www.krwa.org/2014ccr/martincounty.pdf to view your 2014 annual water quality report or to request a paper copy call (606) 298-3885.

Notice by Martin County Water District – System ID#: KY0800273 ur water system recently violated a drinking water requirement. Although this was not an emergency you have a right to know what happened. It routinely monitor your water for turbidity (cloudiness). This tells us whether we are effectively filtering the water supply. On 2/23/2015 we had turbidity result of 1.195 NTU. This was above the standard of 1.0 NTU. Water samples for February 2015 showed that 6,58 percent of turbidity easurements were over 0.3 turbidity units – the standard is that no more than 5 percent of samples may exceed 0.3 turbidity units per month, ne turbidity levels are relatively low. However, their persistence is a concern. Normal turbidity levels at our plant are 0.12 units. This is not an nergency. If it had been, you would have been notified within 24 hours.

- There is nothing you need to do. You do not need to boil your water or take other actions. We do not know of any contamination, and none of our testing has shown disease-causing organisms in the drinking water. If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek advice from your health care providers about drinking this water. General guidelines on ways to lessen the risk of infection by microbes are available from EPA's Safe Drinking Water Hotline at 1-800-426-4791.

Furbidity has no health effects. However, turbidity cen Interfere with disinfection and provide a medium for microbial growth. Turbidity may dicate the presence of disease causing organisms. These organisms include bacteria, viruses, and parasites which can cause symptoms such an associated headaches.* These symptoms are not caused only by organisms in drinking water. If you operience any of these symptoms and they persist, you may want to seek medical advice.

igh turbidity on top of the filters occurred when a rake motor falled and due to high demand we had to continue operations. The problem was solved within three days, For more information, please contact John Mills at (606) 298-3865 or 387 E Main St. Suite 140, Inez, KY 41224.

Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for cample, people in epartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing spies by hand or mail.*

2014 Martin County Water District annual water quality report is available. This report contains important information about your drinking water. Please go to http://www.krwa.org/2014ccr/martincounty.pdf to view your 2014 annual water quality report or to request a paper copy call (606) 298-3885.

No text below this point.

Notice by Martin County Water District – System ID#: KY0800273

Our water system recently violated a drinking water standard. Although this incident was not an emergency, as our customers, you have a right to know what happened and what we did (are doing) to correct this situation.

We routinely monitor for the presence of drinking water contaminants. Testing results from 4/1/2015 through 6/30/2015 show that our system exceeds the standard, or maximum contaminant level (MCL), for trihalomethanes (THM) and haloacetic acids (HAA). The standard for THM is 0.080 mg/L and the standard for HAA is 0.060 mg/L. These are determined by averaging all samples collected at each sampling location for the last 12 months. The level of THM averaged at one of our system's locations for 4/1/2015 to 6/30/2015 was 0.088 mg/L and HAA was 0.077 mg/L.

- There is nothing you need to do. You do not need to boil your water or take other corrective actions. If a situation arises where the water is no longer safe to drink, you will be notified within 24 hours.
- If you have a severely compromised immune system, have an infant, are
 pregnant, or are elderly, you may be at increased risk and should seek advice
 from your health care providers about drinking this water.

Some people who drink water containing trihalomethanes in excess of the MCL over many years may experience problems with their liver, kidneys, or central nervous system, and may have an increased risk of getting cancer. Some people who drink water containing haloacetic acids in excess of the MCL over many years may have an increased risk of getting cancer.

This is not an emergency. If it had been an emergency, you would have been notified within 24 hours.

We are working to minimize the formation of trihalomethanes and haloacetic acids while ensuring we maintain an adequate level of disinfectant. We have taken additional steps to change disinfectant levels, remove natural organic matter, and increased flushing of water lines to determine if our efforts have been effective. We are also monitoring water storage tank levels and water flow patterns within the distribution system. We anticipate resolving the problem within the next quarter but the compliance calculation is based upon annual averages and it may be several quarters before compliance is achieved.

For more information, please contact John Mills at 606-298-3885 or 387 E Main St. Suite 140, Inez, KY 41224.

Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

tr water system recently violated a drinking water standard. Althout incident was not an omergency, as our customers, you have a right to k appened and what we did (are doing) to correct this situation.

te routinely monitor for the presence of drinking water contaminants. Testing results from 4/1/2015 through 5/30/2015 show that our system exceeds the andard, or maximum contaminant level (MCL), for trihelomethenes (THM) and haloacetic acids (HAA). The standard for THM is 0.080 mg/L, and the andard for HAA is 0.060 mg/L. These are determined by averaging all samples collected at each sampling location for the last 12 months. The level of THM reraged at one of our system's locations for 4/1/2015 to 6/30/2015 was 0.088 mg/L and HAA was 0.077 mg/L.

- There is nothing you need to do. You do not need to bail your water or take other corrective actions. If a situation arises where the water is no longer safe to drink, you will be notified within 24 hours.
 If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek advice from your health care providers about drinking this water.

ome people who dilink water containing tribelomethenes in excess of the MCL over many years may experience problems with their liver, kidneys, or central twous system, and may have an increased risk of getting cancer. Some people who drink water containing haloacetic ecids in excess of the MCL over any years may have an increased risk of getting cancer.

his is not an emergency. If it had been an emergency, you would have been notified within 24 hours,
to are working to minimize the formation of trihelomethanes and haloacetic acids white ensuring we maintain an adequate level of disinfectant. We have
ken additional steps to change disinfectant levels, remove natural organic matter, and increased flushing of water lines to determine if our efforts have been
fective. We are also monitoring water storage tank levels and water flow patterns within the distribution system. We compliance calculation is based upon annual averages and it may be several quarters before compliance is achieved.

e information, please contect John Mills at 606-298-3685 or 387 E Main St. Suite 140, Inez, KY 41224.

ease share this information with all the other peopla who drink this water, especially those who may not have received this notice directly (for example, sople in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

Notice by Martin County Water District – System ID#: KY0800273 ur water system recently violated a drinking water standard. Although this incident was not an emergency, as our customers, you have a right to know what appened and what we did (are doing) to correct this situation.

fe routinely mainter for the presence of drinking water contaminants. Testing results from 4/1/2015 through 6/30/2015 show that our system exceeds the andard, or maximum contaminant level (MCL), for trinsformalitanes (THM) and haloacotic acids (HAA). The standard for THM is 0.080 mg/L and the andard for HAA is 0.060 mg/L. These are determined by averaging all samples collected at sech sampling location for the last 12 months. The level of THM refeged at one of our system's locations for 4/1/2015 to 6/30/2015 was 0.088 mg/L and HAA was 0,077 mg/L.

- There is nothing you need to do. You do not need to boil your water or take other corrective actions. If a situation arises where the water is no longer safe to drink, you will be notified within 24 hours.

 If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek advice from your health care providers about drinking this water.

e people who drink water containing trihalomethanes in excess of the MCL over many years may experience problems with their liver, kidneys, or central ous system, and may have an increased risk of getting cencer. Some people who drink water containing haloacetic acids in excess of the MCL over y years may have an increased risk of getting cencer.

ris is not an emergency. If it had been an emergency, you would have been notified within 24 hours
fo are working to minimize the formation of trihatomethanes and heleocotic acids white ensuring we maintain an adequate level of disinfectant. We have ken additional steps to change disinfectant levels, remove natural organic matter, and increased flushing of water lines to determine if our efforts have been factive. We are also emoilicing water storage task fevels and water flow patterns within the distribution system. We anticipate resolving the problem within e next quarter but the compliance calculation is based upon annual averages and it may be several quarters before compliance is achieved.

er more information, please contact John Mills at 606-298-3885 or 387 E Main St. Suite 140, tnez, KY 41224,

'ease share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, topic in apartments, nutsing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

THM & HAA Singe 2 DBPR Template 2-19

Insert water system name and ID# in header, insert compliance period begin date, end date, and average level. Remove brackets Do not modify mandatory language!

Printing Instructions

This template is designed to print the notice on the back of the water bill sheets prior to printing the water bills using procedures the same as

After the notice has been printed to all sheets place the stack of sheets upside down on a flat surface and place a weight on the stack to remove the curl.

When the stock of sheeta have cooled and straightened print the water bills as usual.

No text below this point.

Copy and paste notice. Prior to paste make sure that the cursor is at the highest point in the text box.

Notice by Martin County Water District - System ID#: KY0800273

Our water system recently violated a drinking water standard. Although this incident was not an emergency, as our customers, you have a right to know what happened and what we did (are doing) to correct this situation.

We routinely monitor for the presence of drinking water contaminants. Testing results from 7/1/2015 through 9/30/2015 and 10/1/2015 through 12/31/2015 show that our system exceeds the standard, or maximum contaminant level (MCL), for trihalomethanes (THM) and haloacetic acids (HAA). The standard for THM is 0.080 mg/L and the standard for HAA is 0.060 mg/L. These are determined by averaging all samples collected at each sampling location for the last 12 months. The level of THM averaged at one of our system's locations for 7/1/2015 to 9/30/2015 was 0.081 mg/L and HAA was 0.070 mg/L. The level of THM for 10/1/2015 to 12/31/2015 was 0.100 mg/L

- There is nothing you need to do. You do not need to boil your water or take other corrective actions. If a situation arises where the water is no longer safe to drink, you will be notified within 24 hours.
- If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek advice from your health care providers about drinking this water.

Some people who drink water containing trihalomethanes in excess of the MCL over many years may experience problems with their liver, kidneys, or central nervous system, and may have an increased risk of getting cancer. Some people who drink water containing haloacetic acids in excess of the MCL over many years may have an increased risk of getting cancer.

This is not an emergency. If it had been an emergency, you would have been notified within 24 hours.

We are working to minimize the formation of disinfection by-products while ensuring we maintain an adequate level of disinfectant. We have taken steps to change disinfectant levels, remove natural organic matter, and increased flushing of water lines. We anticipate resolving the problem within the next six months.

For more information, please contact John Mills at 606-298-3885 or 387 E Main St. Suite 140, Inez, KY 41224.

Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

) unduct— system tue. A two variation customers, you have a right to $k_{\rm k}^{\rm f}$

ur water system recently violated a drinking water standard. Althoug-typened and what we did (are doing) to correct this situation,

Ve routinely monitor for the presence of drinking water contaminants. Testing results from 7/1/2015 through 9/30/2015 and 10/1/2015 through 12/31/2015 tow that our system exceeds the standard or maximum contaminant level (MCL), for trihalomethanes (THM) and haloacetic acids (HAA). The standard for Mis 0,080 mg/L and the standard for HAA is 0,060 mg/L. These are determined by averaging all samples collected at each sampling location for the fast 1 months. The level of THM averaged at one of our system's locations for 7/1/2015 to 9/30/2015 was 0,081 mg/L and HAA was 0,070 mg/L. The level of HM for 10/1/2015 to 12/31/2015 was 0,100 mg/L.

There is nothing you need to do, You do not need to boil your water or take other corrective actions. If a situation arises where the water is no longer safe to drink, you will be notified within 24 hours.

If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek advice from your health care providers about drinking this water.

ome people who drink water containing trihelomethenes in excess of the MCL over many years may experience problems with their liver, kidneys, or central arrous system, and may have an increased risk of getting cancer. Some people who drink water containing haloacetic acids in excess of the MCL over eny years may have an increased risk of getting cancer.

ris is not an emergency. If it had been an emergency, you would have been notified within 24 hours

le are working to minimize the formation of disinfection by-products while ensuring we maintain an adequate level of disinfectant. We have taken steps to range disinfectant levels, remove natural organic matter, and increased flushing of water fines. We anticipate resolving the problem within the next six onths:

or more information, please contact John Mills at 606-298-3885 or 387 E Main St. Suite 140, Inex, KY 41224,

ease share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, sople in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

Notice by Martin County Water District – System ID#; KY0808273 ur water system recently violeted a drinking water standard. Although this incident was not an emergency, as our customers, you have a right to know what appened and what we did (are doing) to correct this situation.

for routinely monitor for the presence of drinking water conterminants. Testing results from 7/1/2016 through 9/30/2015 and 10/1/2015 through 12/31/2015 tow that our system exceeds the standard, or maximum conteminant level (MCL), for trinatementenes (THM) and haloacetic acids (HAA). The standard for Mis is 0.050 mg/L. and the standard for HAA is 0.050 mg/L. These are determined by averaging all samples collected at each sampling location for the last 2 months. The level of THM averaged at one of our system's locations for 7/1/2015 to 9/30/2015 was 0.081 mg/L and HAA was 0,079 mg/L. The level of HM for 10/1/2015 to 12/31/2015 was 0.100 mg/L.

• There is nothing you need to do. You do not need to bail your water or take other corrective actions; If a situation arises where the water is no longer safe to dirik, you will be notified within 24 hours.

• If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek advice from your health care providers about drinking this water.

ome people who drink water containing tritialomethanes in excess of the MCL over many years may experience problems with their liver, kidneys, or or servous system, and may have an increased risk of getting cancer. Some people who drink water containing haloacetic acids in excess of the MCL over any years may have an increased risk of getting cancer.

nis is not an emergency. If it had been an emergency, you would have been notified within 24 hours.

te are working to minimize the formation of disinfection by-products while ensuring we maintain an adequate level of disinfectant. We have taken steps to range disinfectant levels, remove natural organic matter, and increased flushing of water lines. We anticipate resolving the problem within the next six

ore information, please contact John Mills at 606-298-3885 or 367 E Main St. Suite 140, Inez. KY 41224.

ese share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, ple in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

THM & HAA Stage 2 DBPR Tempiate 2-19

Insert water system name and ID# in header, insert compliance period begin date, end date, and average level. Remove brackets, Do not modify mandatory language!

Printing Instructions

This template is designed to print the notice on the back of the water bill sheets prior to printing the water bills using proce

After the notice has been printed to all sheets place the stock of sheets upside down on a flat surface and place a weight on the stock to remove the curf.

When the stack of sheets have confed and straightened print the water bills as usual.

No text below this point.

Copy and paste notice Prior to paste make sure that the cursor is at the highest point in the text box.

Exhibit #13
Division of Water

MATTHEW G. BEVIN GOVERNOR



CHARLES G. SNAVELY SECRETARY

ENERGY AND ENVIRONMENT CABINET

DEPARTMENT FOR ENVIRONMENTAL PROTECTION

Division of Water 233 Birch St Hazard, KY 417012115 www.kentucky.gov

March 14, 2016

Martin Co Water District 14 Flat Hollow Inez, Kentucky 41224

RE: Mai

Martin Co Water District -- 2987

Permit No.: KY0800273 Martin County, Kentucky Activity ID: CIN20160002

Dear Martin Co Water Dist:

Attached for your information and records is a copy of the DW Comp-Surface performed at Martin Co Water District on February 22, 2016.

The system should continue efforts to leak detect the distribution system and repair any issues as they are found. Measure should be taken to perform a full system flush twice per year while flushing dead ends as often as needed.

If you have any questions or comments concerning this inspection, please contact the Hazard Regional Office at: (606) 435-6022.

Sincerely,

Robert Back Environmental Inspector Hazard Regional Office Division of Water

RB Enclosure:

Kentuckij

An Equal Opportunity Employer M/F/D

KentuckyUnbridledSpirit.com

ENERGY AND ENVIRONMENT CABINET KENTUCKY DEPARTMENT FOR ENVIRONMENTAL PROTECTION **DIVISION OF WATER**

Routine Surface Inspection

Site/Permit ID: 0800273	0273 Division: Water		Regional Office: Hazard	
Site Name: MARTIN CO. WATER DISTRICT		Program: D r	Program: Drinking Water	
Site Address: HC69 Box 875				
City: INEZ	State: KY	Zip: 41224	County: Martin	
Inspection Type: Routine Surface		ose: Comprehens	ve AI #: 2987	
Inspection Date: 2/22/16		Time: Start 9.55 AM End 1.10 PM		
Latitude: 37 52 20.3		Longitude: 82 31 09.8		
Coordinate Collection Method	l: G40-Handheld receiv	er er	Revision Code: 112108	
	Drinkin	g Water Data		
Plant Name: MARTIN CO.	Contact Name: Tom	Alley		
WATER DISTRICT	una-a-a-a-a-a-a-a-a-a-a-a-a-a-a-a-a-a-a-	-		
Phone No.: 606-298-3885	Fax No:		Email Address:	

I. Administrative Requirements

Comments:

I. Compliance Status - Not Evaluated

II. Operator Certification/Accreditation Requirements

Operator in Charge or on duty.

Plant Certification # Distribution Certification

Operator Name	Plant Certification #	#
Tom Alley	17562	
Mike Sartin	21944	
Tim Reed/ Elbert Osborne	24590	27800

Comments:

II. Compliance Status - Not Evaluated

III. Record Keeping Requirements

Comments:

III. Compliance Status - No violations observed Comments: Wolf creek, Coldwater, Inez 1&2 tanks are not in service. The system does not use these tanks at this time. The System has switched from gas chlorine to liquid bleach disinfectant. The system is using a Thornsorb activated carbon system. The water treatment plant has a 100,000 gallon clearwell at the plant and two 500,000 gallon clearwell tanks on the hill above the plant.

The system needs to perform a complete system flush however approximately 50% water loss and low storage due to distribution leaks in the Warfield area make it difficult. Failure to properly flush the system will make meeting future DBP limits a difficult task.

V. Compliance Status - No violations obs-but impending viol trends obs

Inspector: Robert D. Back

VI. Discharge/Emission Compliance Comments: Compliance Status - No violations observed VII. Monitoring/Analyses Evaluation Comments: The system has multiple violations for disinfection by-products from the 2015 year. The Division of Enforcement is addressing these violations. VII. Compliance Status - Out of Compliance- No action taken VIII. Environmental /Health Impact □ REVIEWED Work Site Hazard Assessment: Comments: VIII. Compliance Status – No violations observed IX. Documentation Samples taken by DEP Samples taken by outside source Instrument readings taken by DEP regional office Photographs obtained by DEP Copies of records obtained by DEP Other documentation

Title: Environmental Inspector III

Date: 2/22/16



ENERGY AND ENVIRONMENT CABINET

Matthew G Bevin Governor

Department for Environmental Protection
Division of Water
200 Fair Oaks Lane
4 Floor
Frankforl. Kentucky 40601
Phone: (502) 564-341 0
Fax: (502) 564-2741

Charles G Snavely Secretary

> R. Bruce Scott Commissioner

March 9, 2016

www.water.ky.gov

CERTIFIED MAIL: 70 15 3430 0000 4915 032 PRETURN RECEIPT REQUESTED
JOHN MILLS
MARTIN CO WATER DISTRICT #1
287 E MAIN ST SUITE 140
INEZ, KY 41224

Re: NOTICE OF VIOLATION Al ID: 2987

PWSID: KY0800273

PWS NAME: MARTIN CO WATER DISTRICT #1

COUNTY: MARTIN

Dear Mr. Mills:

The Kentucky Department for Environmental Protection (DEP) has issued the enclosed Notice of Violation for violations discovered at your facility. Please review this Notice of Violation carefully to ensure that all remedial measures are completed by the specified deadlines.

Failure to comply with all remedial measures could result in enforcement action and the assessment of penalties. Your cooperation and attention to this matter is appreciated. If you have any questions, please contact Kellee Husband at (502)564-3410 ext. 4986 or email at kelteem.husband@ky.gov.

Sincerely, Bin_M. Chitti

Brian Chitti
Drinking Water CTAB Supervisor
Compliance & Technical Assistance Branch
Division of Water

C: Drinking Water Program files Enclosure

COMMONWEALTH OF KENTUCKY

ENERGY & ENVIRONMENT CABINET DEPARTMENT FOR ENVIRONNIENTAL PROTECTION Division of Water

NOTICE OF VIOLATION

MARTIN CO WATER DISTRICT #1 287 E MAIN ST SUITE 140 INEZ, KY 41224

PWSID: KY0800273

PWS Name: MARTIN CO WATER DISTRICT Al ID: 2987

County: MARTIN

Violation Number: 2016 - 9951 175
Determination Date: 02/10/2016

Compliance Period: 10/01/2015 - 12/31/2015 Violation Type: 02 MCL, LRAA Tier Level: 2

PWS Facility: IDSE9999 IDSE - MARTN CO WATER DIST Contaminant:

2950 TTHM

Public Water Systems are subject to the requirements of 401 KAR Chapter 8. [401 KAR 8:020 Section 1] This is to advise that you are in violation of the provision(s) cited below:

Description of Non Compliance:

401 KAR 8:510 mHM The public water system exceeded the MCL for locational running annual average (LRAA) of samples for the specific contaminant in compliance period 10/01/2015 - 12/31/2015. The reported result of .123 mg/l exceeded the MCL of 0.080 mg/l,

The remedial measure(s) and date(s) to be completed by are as follows: Begin or continue quarterly monitoring for TTHM

Pertorm public notification for the above-mentioned violation in accordance with 401 KAR 8:070. The public notification must not contain language that contradicts or detracts from the standard mandatory language or the purpose of the notice. Submit proof of public notification and its certification within ten (10) days of executing public notification. [401 KAR 8:070] The specific public notification activilies to be performed are listed below.

PW S must give notice to consumers, including other water systems you may provide water to, about a violation by mail delivery or hand delivery. The notice must be executed within thirty (30) days following receipt by the PWS of this Notice of Violation.

If not all consumers can be notified by mail or hand delivery then the PWS must give notice to consumers about a violation by t) publication in a newspaper of general circulation in the area served by the PWS or 2) by continuous posting in conspicuous places within the area served by the PW S. The notice must be executed within thirty (30) days following receipt by the PWS of this Notice of Violation.

Submit proof of public notification and its certification within ten (10) days of executing public notification.

Violations of the above cited statutes and/or regulations are subject to a civil penalty. Violations carry civil penalties of up to \$25,000 per day per violation depending on the statutes/regulations violated. In addition, violations may be concurrently enjoined. Compliance with remedial measures and their deadlines does not provide exemption from liability for violations during the period of remediation, nor prevent additional remedial measures from being required.

Detailed information about your water system's violations & monitoring requirements can be easily accessed on Kentucky Drinking Water Watch at http://dep.gateway.ky.gov/DWW/

If you have questions or need further information, write or call Kellee Husband at (502)564-3410 ext 4986 or email at kelleem.husband@kv.gov.

ALL DOCUMENTATION MUST BE SUBMITIED TO:

Drinking Water Compliance & Technical Assistance Division of Water, Department tor Environmental Protection 200 Fair Oaks Lane, 4th Floor Frankfort, KY 40601

Bin m. Chitti

Issued By:

Brian Chitti Drinking Water CTAB Supervisor

Compliance & Technical Assistance Branch Division of Water

Date: March 9, 2016

How Delivered: Certified/Registered #7015 3430 0000 4915 0.321

in water system recently violated a drinking water standard, Althoppened and what we did (are doing) to correct this situation.

in chang - oystein iow, necouders is incident was not an emergency, as our customers, you have a right to

e routinely monitor for the presence of drinking water contaminants. Testing results from 7/1/2015 through 9/30/2015 and 10/1/2015 through 12/31/2015 ow that our system exceeds the standard or maximum contaminant level (MCL), for trihalomethanes (THM) and heleacetic acids (HAA). The standard for Mis 0.030 mg/L and the standard for HAA is 0.060 mg/L. These are determined by averaging all samples collected at each sampling location for the last 1 months. The level of THM averaged at one of our system's locations for 7/1/2015 to 9/30/2015 was 0.081 mg/L and HAA was 0.070 mg/L. The level of M for 10/1/2015 to 12/31/2015 was 0.100 mg/L.

There is nothing you need to do. You do not need to boil your water or take other corrective actions. If a situation arises where the water is no longer safe to drink, you will be notified within 24 hours.

If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek advice from your health care providers about drinking this water.

me people who drink water containing trihalomethanes in excess of the MCL over many years may experience problems with their liver, kidneys, or central vivous system, and may have an increased risk of getting cancer. Some people who drink water containing haloscetic soids in excess of the MCL over any years may have an increased risk of getting cancer.

is is not an emergency. If it had been an emergency, you would have been notified within 24 hours.

e are working to minimize the formation of disinfection by-products while ensuring we maintain an adequate level of disinfectant. We have taken steps to ange disinfectant levels, remove natural organic matter, and increased flushing of water lines. We anticipate resolving the problem within the next six antitis.

r more information, please contact John Milis at 606-298-3895 or 387 E Main St. Suite 140, Inex, KY 41224.

ease share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, tople in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

Notice by Martin County Water District — System ID#: KY0800273 # water system recently violated a drinking water standard. Although this incident was not an emergency, as our ppened and what we did (are doing) to correct this situation. our customers, you have a right to know what

e routinely monitor for the presence of drinking water contaminants. Testing results from 7/1/2015 through 9/30/2015 and 10/1/2015 through 12/31/2015 through 9/30/2015 and 10/1/2015 through 12/31/2015 tow that our system exceeds the standard or maximum contaminant level (MCL), for trihelomethanes (THM) and heloacetic acids (HAA). The standard for 1M is 0,080 mg/L, and the standard for 1M is 0,080 mg/L and the standard for 1M is 0,080 mg/L and 1M averaged at one of our system's locations for 7/1/2015 to 9/30/2015 was 0,081 mg/L and HAA was 0,070 mg/L. The level of 1M for 10/1/2015 to 12/31/2015 was 0,100 mg/L.

There is nothing you need to do. You do not need to boil your water or take other corrective actions, if a situation erises where the water is no longer safe to drink, you will be notified within 24 hours.

If you have a severely compromised immune system, have an infant, are pregnant, or are alderly, you may be at increased risk and should seek advice from your health care providers about drinking this water.

me poople who drink water containing trihalomathanes in excess of the MCL over many years may experience problems with their fiver, kidneys, or central arous system, and may have an increased risk of gelling cancer. Some people who drink water containing haloacetic acids in excess of the MCL over any years may have an increased risk of gelling cancer.

tis is not an emergency. If it had been an emergency, you would have been notified within 24 hours;

e are working to minimize the formation of disinfection by-products white ensuring we maintain an adequate level of disinfectant. We have taken steps to enga disinfectant levels, remove natural organic matter, and increased flushing of water lines. We anticipate resolving the problem within the next six onths.

or more information, please contact John Mills at 605-298-3885 or 387 E Main St. Suite 140, Inex, KY 41224.

ease share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, sople in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mall,

THM & HAA Stage 2 DBPR Template 2-19

Insert water system name and ID# in header, insert compliance period begin date, end date, and average ievei, Remove brackets.
Do not modify mandatory

Printing Instructions

This template is designed to print the notice on the back of the water bill sheets prior to printing the water bills using procedures the same as printing a letter

After the notice has been printed to all sheets place the stack of sheets upside down on a flat surface and place a weight on the stack to remove the curl.

When the stack of sheets have cooled and straightened print the water bills as usual

No text below this point

Copy and paste notice. Prior to paste make sure that the cursor is at the highest point in the text box.



ENERGY AND ENVIRONMENT CABINET

Matthew G Bevin Governor

Department for Environmental Protection
Division of Water
200 Fair Oaks Lane, 4th Floor
Frankfort, Kentucky 40601
Phone: (502) 564-3410
Fax: (502) 564-2741
water.ky.gov

Charles G. Snavely Secretary

> R. Bruce Scott Commissioner

December 22, 2015

Earl Alley Martin County Water District #1 387 East Main St Suite 140 Inez, KY 41224 Re: Repeat Public Notice Extension

AI ID: 2987

PWSID: KY0800273

PWS NAME: Martin County Water District #1

COUNTY: Greenup

Dear Mr. Alley,

The Division of Water has considered your request and will grant an extension to the required repeat public notice for the ongoing disinfection byproduct MCL exceedance or a reduction in frequency of the repeat public notice. This will depend on the Locational Running Annual Average that is calculated for the 4th quarter of 2015.

If the water system continues to exceed the MCL for disinfection byproducts for the 4th quarter, the water system will use the 4th quarter results in the repeat public notice. If the water system comes back into compliance in the 4th quarter, the water system will be required to perform a public notice using the 3rd quarter results.

The public notice shall be performed no later than February 10th, 2016.

It is not required for the water system to receive a 4th quarter Notice of Violation before issuing the public notice. The water system may issue the notice as soon as they receive 4th quarter TTHM analysis results and can make a determination whether or not they are in compliance for the 4th quarter.

Please note all violations shall be listed in the 2015 Consumer Confidence Report.

If you have any questions or concerns, please contact Brook Overbay at (502) 564-3410, extension 4958. Or ashlee.overbay@ky.gov

Sincerely.

Brook Overbay Compliance Section Division of Water

C: Drinking Water Files

KentuckyUnbridledSpirit.com



An Equal Opportunity Employer M/F/D



PAID

DEC 28 2015

MARTIN CO. WATER

Matthew G. Bevin Governor **ENERGY AND ENVIRONMENT CABINET**

Department for Environmental Protection
Division of Water
200 Fair Oaks Lane, 4th Floor
Frankfort, Kentucky 40601
Phone: (502) 564-3410
Fax: (502) 564-2741
www.water.ky.gov

Charles G, Snavely Secretary

> R. Bruce Scott Commissioner

December 14, 2015

To Whom It May Concern:

The Kentucky Department for Environmental Protection (DEP) has enclosed multiple notices for violations discovered at your facility. Please review each notice of violation carefully to ensure that all remedial measures are completed by the specified deadlines.

.. If you have questions regarding any of the violations, please call or write the contact identified on each of the violations.

Sincerely,

Bian M. Chitti

Brian Chitti
Drinking Water CTAB Supervisor
Compliance & Technical Assistance Branch
Division of Water

Enclosures

KentuckyUnbridledSpirit.com



An Equal Opportunity Employer M/F/D



ENERGY AND ENVIRONMENT CABINET

Matthew G. Bevin Governor

Department for Environmental Protection
Division of Water
200 Fair Oaks Lane
4th Floor
Frankfort, Kentucky 40601
Phone: (502) 564-3410
Fax: (502) 564-2741

Charles G. Snavely Secretary

> R. Bruce Scott Commissioner

www.water.ky.gov

December 11, 2015

CERTIFIED MAIL: 7015 0640 0005 6317 6221 RETURN RECEIPT REQUESTED

JOHN MILLS
MARTIN CO WATER DISTRICT #1 .
287 E MAIN ST SUITE 140
INEZ, KY 41224

Re: NOTICE OF VIOLATION

AI ID: 2987

PWSID: KY0800273

PWS NAME: MARTIN CO WATER DISTRICT #1

COUNTY: MARTIN

Dear Mr. Mills:

The Kentucky Department for Environmental Protection (DEP) has issued the enclosed Notice of Violation for violations discovered at your facility. Please review this Notice of Violation carefully to ensure that all remedial measures are completed by the specified deadlines.

Failure to comply with all remedial measures could result in enforcement action and the assessment of penalties. Your cooperation and attention to this matter is appreciated. If you have any questions, please contact Kellee Husband at (502)564-3410 ext. 4986 or email at kelleem.husband@ky.gov.

Sincerely,

Bin M. Chitti

Brian Chitti
Drinking Water CTAB Supervisor
Compliance & Technical Assistance Branch
Division of Water

C: Drinking Water Program files Enclosure

COMMONWEALTH OF KENTUCKY ENERGY & ENVIRONMENT CABINET DEPARTMENT FOR ENVIRONMENTAL PROTECTION Division of Water

NOTICE OF VIOLATION

To:

MARTIN CO WATER DISTRICT #1 287 E MAIN ST SUITE 140 INEZ, KY 41224

PWSID: KY0800273

PWS Name: MARTIN CO WATER DISTRICT #1 AI ID: 2987

County: MARTIN

Violation Number: 2016 - 9951173 Determination Date: 11/09/2015

Compliance Period: 07/01/2015 - 09/30/2015 Violation Type: 02 MCL, LRAA Tier Level: 2

PWS Facility: IDSE9999 IDSE - MARTN CO WATER DIST Contaminant: 2456 TOTAL HALOACETIC ACIDS (HAA5)

Public Water Systems are subject to the requirements of 401 KAR Chapter 8. [401 KAR 8:020 Section 1] This is to advise that you are in violation of the provision(s) cited below:

Description of Non Compliance:

401 KAR 8:510 TOTAL HALOACETIC ACIDS (HAA5) The public water system exceeded the MCL for locational running annual average (LRAA) of samples for the specific contaminant in compliance period 07/01/2015 - 09/30/2015. The reported result of .07 mg/l exceeded the MCL of 0.060 mg/l.

The remedial measure(s) and date(s) to be completed by are as follows:

Begin or continue quarterly monitoring for TOTAL HALOACETIC ACIDS (HAA5)

Perform public notification for the above-mentioned violation in accordance with 401 KAR 8:070. The public notification must not contain language that contradicts or detracts from the standard mandatory language or the purpose of the notice. Submit proof of public notification and its certification within ten (10) days of executing public notification. [401 KAR 8:070] The specific public notification activities to be performed are listed below.

PWS must give notice to consumers, including other water systems you may provide water to, about a violation by mail delivery or hand delivery. The notice must be executed within thirty (30) days following receipt by the PWS of this Notice of Violation.

If not all consumers can be notified by mail or hand delivery then the PWS must give notice to consumers about a violation by 1) publication in a newspaper of general circulation in the area served by the PWS or 2) by continuous posting in conspicuous places within the area served by the PWS. The notice must be executed within thirty (30) days following receipt by the PWS of this Notice of Violation.

Submit proof of public notification and its certification within ten (10) days of executing public notification.

Violations of the above cited statutes and/or regulations are subject to a civil penalty. Violations carry civil penalties of up to \$25,000 per day per violation depending on the statutes/regulations violated. In addition, violations may be concurrently enjoined. Compliance with remedial measures and their deadlines does not provide exemption from liability for violations during the period of remediation, nor prevent additional remedial measures from being required.

Detailed information about your water system's violations & monitoring requirements can be easily accessed on Kentucky Drinking Water Watch at http://depigateway.ky.gov/DWW/

If you have questions or need further information, write or call Kellee Husband at (502)564-3410 ext 4986 or email at kelleem husband @ky.gov.

ALL DOCUMENTATION MUST BE SUBMITTED TO:

Drinking Water Compliance & Technical Assistance Division of Water, Department for Environmental Protection 200 Fair Oaks Lune, 4th Floor Frankfort, KY 40601

Issued By:

Brian Chitti

Drinking Water CTAB Supervisor

Compliance & Technical Assistance Branch

Division of Water

Bin M. Chitti

Date: December 11, 2015

How Delivered: Certified/Registered #7015 0640 0005 6317 6221



ENERGY AND ENVIRONMENT CABINET

Matthew G. Bevin Governor

Department for Environmental Protection
Division of Water
200 Fair Oaks Lane
4th Floor
Frankfort, Kentucky 40601
Phone: (502) 564-3410

Phone: (502) 564-3410 Fax: (502) 564-2741 www.water.ky.gov

December 11, 2015

Charles G. Snavely Secretary

> R. Bruce Scott Commissioner

CERTIFIED MAIL: 7015 0640 0005 6317 6221 RETURN RECEIPT REQUESTED

JOHN MILLS MARTIN CO WATER DISTRICT #1 287 E MAIN ST SUITE 140 INEZ, KY 41224 Re: NOTICE OF VIOLATION

AI ID: 2987

PWSID: KY0800273

PWS NAME: MARTIN CO WATER DISTRICT #1

COUNTY: MARTIN

Dear Mr. Mills:

The Kentucky Department for Environmental Protection (DEP) has issued the enclosed Notice of Violation for violations discovered at your facility. Please review this Notice of Violation carefully to ensure that all remedial measures are completed by the specified deadlines.

Failure to comply with all remedial measures could result in enforcement action and the assessment of penalties. Your cooperation and attention to this matter is appreciated. If you have any questions, please contact Kellee Husband at (502)564-3410 ext. 4986 or email at kelleem.husband@ky.gov.

Sincerely,

Bin M. Chitti

Brian Chitti
Drinking Water CTAB Supervisor
Compliance & Technical Assistance Branch
Division of Water

C: Drinking Water Program files Enclosure

COMMONWEALTH OF KENTUCKY ENERGY & ENVIRONMENT CABINET DEPARTMENT FOR ENVIRONMENTAL PROTECTION Division of Water

NOTICE OF VIOLATION

To: MARTIN CO WATER DISTRICT #1 287 E MAIN ST SUITE 140 INEZ, KY 41224

PWSID: KY0800273

PWS Name: MARTIN CO WATER DISTRICT #1 AI ID: 2987

County: MARTIN

Violation Number: 2016 - 9951174 Determination Date: 11/09/2015

Compliance Period: 07/01/2015 - 09/30/2015 Violation Type: 02 MCL. LRAA Tier Level: 2

PWS Facility: IDSE9999 IDSE - MARTN CO WATER DIST

Contaminant: 2950 TTHM

Public Water Systems are subject to the requirements of 401 KAR Chapter 8. [401 KAR 8:020 Section 1] This is to advise that you are in violation of the provision(s) cited below:

Description of Non Compliance:

401 KAR 8:510 TTHM The public water system exceeded the MCL for locational running annual average (LRAA) of samples for the specific contaminant in compliance period 07/01/2015 - 09/30/2015. The reported result of .081 mg/l exceeded the MCL of 0.080 mg/l.

The remedial measure(s) and date(s) to be completed by are as follows:

Begin or continue quarterly monitoring for TTHM

Perform public notification for the above-mentioned violation in accordance with 401 KAR 8:070. The public notification must not contain language that contradicts or detracts from the standard mandatory language or the purpose of the notice. Submit proof of public notification and its certification within ten (10) days of executing public notification. [401 KAR 8:070] The specific public notification activities to be performed are listed below.

PWS must give notice to consumers, including other water systems you may provide water to, about a violation by mail delivery or hand delivery. The notice must be executed within thirty (30) days following receipt by the PWS of this Notice of Violation.

If not all consumers can be notified by mail or hand delivery then the PWS must give notice to consumers about a violation by 1) publication in a newspaper of general circulation in the area served by the PWS or 2) by continuous posting in conspicuous places within the area served by the PWS. The notice must be executed within thirty (30) days following receipt by the PWS of this Notice of Violation.

Submit proof of public notification and its certification within ten (10) days of executing public notification.

Violations of the above cited statutes and/or regulations are subject to a civil penalty. Violations carry civil penalties of up to \$25,000 per day per violation depending on the statutes/regulations violated. In addition, violations may be concurrently enjoined. Compliance with remedial measures and their deadlines does not provide exemption from liability for violations during the period of remediation, nor prevent additional remedial measures from being required.

Detailed information about your water system's violations & monitoring requirements can be easily accessed on Kentucky Drinking Water Watch at http://dep.gateway.ky.gov/DWW/.

If you have questions or need further information, write or call Kellee Husband at (502)564-3410 ext 4986 or email at <u>Kelleem, husband@kÿ.gov</u>.

ALL DOCUMENTATION MUST BE SUBMITTED TO:

Drinking Water Compliance & Technical Assistance
Division of Water, Department for Environmental Protection
(200) Fair Oaks Lane, 4th Floor
Frankfort, KY 40601

Issued By:

Brian Chitti

Drinking Water CTAB Supervisor

Compliance & Technical Assistance Branch

Division of Water

Bin M. Chitti

Date: December 11, 2015

How Delivered: Certified/Registered #7015 0640 0005 6317 6221