COMMONWEALTH OF KENTUCKY

BEFORE THE PUBLIC SERVICE COMMISSION	N	
In the Matter of:		
INVESTIGATION OF THE OPERATING CAPACITY OF MARTIN COUNTY WATER DISTRICT PURSUANT TO KRS 278.280))	CASE NO. 2016-00142 RECEIVE
		MAY 12 2016
		Public Service

MARTIN COUNTY WATER DISTRICT'S RESPONSE TO INFORMATION REQUESTED IN APPENDIX H OF THE PUBLIC SERVICE COMMISSIONER'S ORDER ENTERED APRIL 11, 2016

CERTIFICATE OF SERVICE

I hereby certify that service was made as required by the April 11, 2016 Order of the Public Service Commission, the original and one true and correct copy of the Martin County Water District's Response to information requested in Appendix H of said Order, to the following on May 5, 2016 via overnight delivery and the redacted Response on May 10, 2016: Aaron D. Greenwell, Acting Executive Director, Public Service Commission, 211 Sower Boulevard, P.O. Box 615, Frankfort, KY 40602

HON. BRIAN CUMBO

ATTORNEY FOR MARTIN COUNTY

Commission

WATER DISTRICT

PO BOX 1844

INEZ, KY 41224

TELEPHONE (606) 298-0428

FACSIMILE (6060) 298-0316

EMAIL: cumbolaw@cumbolaw.com

TABLE OF CONTENTS

MARTIN COUNTY WATER DISTRICT'S RESPONSE	1-8
VERIFICATION OF PREPARER.	9
EXHIBIT #1 – CURRENT LIST OF WORK ORDERS	
EXHIBIT #2 – NUMBER OF TAPS REQUESTED	
EXHIBIT #3 – NUMBER OF TAPS REQUEST PENDING	
EXHIBIT #4 – NUMBER OF TURN-OFFS	
EXHIBIT #5 – COMPARISON OF ELECTRICITY COST	
EXHIBIT #6 – WATER LOSS AND LEAK DETECTION PROGRAM	
EXHIBIT #7 – UPDATED CAPITAL IMPROVEMENT PLAN	
EXHIBIT #8 – PENDING DISCONNECTS	
EXHIBIT #9 – BUSINESS MANAGER'S JOB DUTIES	
EXHIBIT #10 – WRITTEN COMPLAINTS	
EXHIBIT #11 – TELEMENTRY PRESSURE CHARTS	
EXHIBIT #12 – PUBLIC NOTIFICATION	
EXHIBIT #13 – DIVISION OF WATER	

Martin County Water District Before the Public Service Commission

Martin County Water District ("Martin District"), a water district organized pursuant to KRS Chapter 74, owns and operates facilities that treat and distribute water to approximately 3,533 customers in Martin County, Kentucky.

Joe Hammond

Jhammond58@bellsouth.net

PSC Data Request Response Case No. 2016-00142

Questions 1-17 are related to ongoing Management Audit recommendations steps.

- 1. Refer to the 2007 Management Audit Action Plan, Recommendation 11-1
 - Step 3. Provide a current list of work orders for leak repairs, meter sets, meter rereads, meter pulls, low pressure, meter reads (in and out), tap relocates, and similar distribution work, and explain how Martin District addresses these work orders.
 - a. Exhibit #1
- 2. Refer to the 2007 Management Audit Action Plan, Recommendation 11-1
 - Step 4. Provide the following:
 - A. The number of tap requests processed and completed since October 6, 2015 (the date the new NRC tariff was issued).
 - a. Exhibit #2
 - b. 5 Tap request
 - B. The number of tap request pending as of November 13, 2015.
 - c. Exhibit #3
 - d. No tap request pending
 - C. An estimate of when Martin District expects to complete the taps outstanding as of November 13, 2015.
 - e. No taps outstanding
- 3. Refer to the 2007 Management Audit Action Plan, Recommendation 11-1
 - Step 5. Provide the following:
 - A. The number of turn-offs performed since October 6, 2015.
 - a. Exhibit #4
 - B. The number of outstanding or past-due accounts.
 - b. 137 Customers 30-60-90 days
- 4. Refer to the 2007 Management Audit Action Plan, Recommendation 11-1

Step 7. Provide the following:

- A. Identify the number and location of additional pumps Martin District plans to install to allow pumping at night. For each, provide an estimate of when Martin District plans to install the pumps.
 - a. None at this time
- B. A comparison of electricity costs for each month for the past two years.
 - b. Electricity comparison for 2014 2015
 - c. Exhibit #5
- 5. Refer to the 2007 Management Audit Action Plan, Recommendation 11-1
 - Step 9. Provide the following:
 - A. Explain whether or not Martin District will reach the goal of five treatment plant operators.
 - a. At present the District has two (2) part-time and two (2) full-time operators.
 - b. The District has one employee full-time training for his class II operator license. He will be testing in July 2016. Hopefully by January 2017, he will be ready for his class III.
 - c. As everyone knows, treatment operators are difficult to find and to hire. In-house training is a must and that is the District's goal.
- 6. Refer to the 2007 Management Audit Action Plan, Recommendation 11-2
 - Step 1. Provide the following:
 - A. The amount and percentage of line loss on each system (A and B) through December 31, 2015.
 - a. Amount of water loss = 393.097 million gallons
 - b. Percentage = 62%
 - B. The amount and percentage of line loss for calendar years 2014, 2013, and 2012.
 - a. Amount of water loss 2012 = 370.087 million gallons = 56% Loss

- b. Amount of water loss 2013 = 399.816 million gallons = 61% Loss
- c. Amount of water loss 2014 = 376.606 million gallons = 52%
- 7. Refer to the 2007 Management Audit Action Plan, Recommendation 11-1

Step 2 and 3. Provide the following:

- A. Identify known leaks and prioritize the mains and services for replacement or repair based on volumes.
 - a. Pigeon Roost under railroad tracks casing broke and broke a 4" line. Repaired March 2016. Leak detection assisted by KRWA and District personnel.
 - b. Little Peter Cave, Wolf Creek Area, estimated 2 to 3 million a month. Repaired April 2016. Leak detection assisted by KRWA and District personnel.
 - c. Elk Creek, Beauty KY, estimated 3 to 3.5 million a month. Repaired March 2016. Leak detection assisted by KRWA and District personnel.
- B. An estimate of when replacement or repair will be undertaken.
 - a. This will be an ongoing process until water loss is under control.
 - b. Replacement of old water lines will be determined when funding is in place.
 - c. Repairs to line breaks will be taken care of ASAP.
- 8. Refer to the 2007 Management Audit Action Plan, Recommendation 11-2
 - Step 4. Other than identification (of cheater bars) when reading meters, explain how Martin District is addressing this recommendation.
 - a. Since August 2015, found 2 cheater bars and turned over to the County Attorney for prosecution.
 - b. One customer is now paying his bill due to the County Attorney's action.
 - c. No update on the other one.

9. Refer to the 2007 Management Audit Action Plan, Recommendation 11-2

Step 5. Provide an update of Martin District's progress in replacing or repairing all excessively leaking mains and services as outlined in Step 5. Identify any decreases in water loss resulting from it efforts.

- a. Reference Step 2 and 3 above. The leaks mention above have been repaired. Our storage tanks in these areas are maintained at the appropriate levels. Water loss in these areas will be determined at the end of the month.
- 10. Refer to the 2007 Management Audit Action Plan, Recommendation 11-3

Steps 1-4. Provide Martin District's formal, written preventive maintenance program.

- a. The District has a Water Loss and Leak Detection Program for Preventive Maintenance.
- b. Exhibit #6
- c. The District will begin to prepare a complete Preventive Maintenance Plan for all assets in the District.
- 11. Refer to the 2007 Management Audit Action Plan, Recommendation 11-5
 - a. After consulting with the Health Inspector, concerning the water shed, he is aware of the situation and monitors the area where residents live. No complaints at this time.
- 12. Refer to the 2007 Management Audit Action Plan, Recommendation 11-6

Steps 1, 2, 3, and 6. Other than working with the electric providers to reduce power outages, explain how Martin District is addressing this recommendation.

- a. The District has purchased a 300kw mobile generator that can run the plant or any other pump station in the system. The District has spent approximately \$23000.00 for the generator. This has and will continue to assist the District in covering our power outages.
- b. Also, the power company has been clearing trees from overhead power lines.
- 13. Refer to the 2007 Management Audit Action Plan, Recommendation 111-1

Other than working with the Big Sandy ADD, explain what internal or other external steps Martin District is taking to address this recommendation.

- a. Continue to meet with BSADD, KRWA, PSC, and Division of Water planning and prioritizing our system to comply with the rules and regulation set forth for the District.
- b. The District will evaluate the upgrades made to the Capital Improvement Plan of 2003 and improve the Plan to current needs of the system. Plans updated (03/08/2016).
- c. Exhibit #7
- 14. Refer to the 2007 Management Audit Action Plan, Recommendation 111-2

Steps 1 and 2. Provide the following:

- A. Identify the water loss reduction related construction projects undertaken in the past year and identify those planned for the next six months.
 - a. The District is replacing old service lines and as funding permits, replacing old main lines.
 - b. Training and assistance from KRWA pertaining to the proper technique in locating hard to find leaks and to maintain proper records to ascertain when a leak occurs and repair and track the amount of water loss. This process will continue throughout the daily process of the District.
 - c. Replacing 100 Radio Read meters in the Wolf Creek Area. If funding becomes available, the District plans are to continue replacing all manual read meters. This will help with water loss and theft of services.
 - d. The District believes that each project identified above will contribute to less water loss.
- 15. Refer to the 2007 Management Audit Action Plan, Recommendation IV-3

Provide a report of pending disconnects for 30-60-90 days, for the most recent date, available at the time of your response.

- a. Exhibit #8
- 16. Refer to the 2007 Management Audit Action Plan, Recommendation V-4

Steps 1, 2, 3 and 4. Provide the following:

A. External audit reports for years 2013, 2014, and 2015 when completed.

- a. The audit firm of White and Associates, PSC, Richmond, KY has been engaged to complete audits for the years in question. The projected completion dates are early summer 2016. Copies will be forwarded upon receipt.
- B. If any of these reports are complete, provide an estimate of when each audit will be completed.
 - b. No audits are complete at this time.
- 17. Refer to the 2007 Management Audit Action Plan, Recommendation V-5

Steps 1 and 2: Provide a description of the duties of the Business Manager position.

- a. Exhibit #9
- 18. Refer to the 2007 Management Audit Action Plan, Recommendation V-5
 - A. Provide a copy of each written complaint or electronic mail message containing a complaint concerning water service received by Martin District during the period January 1, 2013 to the present. Include with the response a copy of Martin District's response to the complaint. If Martin District has not retained documentation of the complaints, explain why each document has not been retained.
 - a. 2013 2016 Exhibit #10
- 19. Provide a schedule that contains the date, time, and duration of each event in which Martin District was not in compliance with 807 KAR 5:066, Section 5(1). During the period January 1, 2013, to present.
 - a. The District uses our Telementry system to monitor the pressure (both Suction and Discharge) throughout our system.
 - a. Exhibit #11
 - b. Beginning this month, (April 2016) a pressure recording device will be installed in different areas of the system and charts maintained.
- 20. Provide a copy of each public notification that Martin District has been required to provide to its customers pursuant to federal or state drinking water regulations during the period January 1, 2013, to present.
 - a. Exhibit #12
- 21. Provide a copy of all communication between Martin District and the Kentucky Division of Water, including its regional offices, during the period January 1, 2013, to present.

- a. Researching files to completely comply with this request.
- b. Exhibit #13
- 22. Refer to the Public Service Commission's Utility Inspection Report for Martin District dated December 23, 2014. Provide the following:
 - A. Explain why Martin District failed to produce pressure surveys that showed a continuous 24-hour pressure recording for a minimum of one week per month as required by 807 KAR 5:066, Section 5(2).
 - a. Ongoing research as to the fail process of the pressure surveys required by 807 KAR 5:066, Section 5(2).
 - b. Policies have been implemented effective April 1, 2016 to be fully compliant.
 - B. Explain Martin District's procedure for monitoring and documenting withdrawals from Martin District by fire departments.
 - c. Reports have been presented to the Fire Departments to complete the withdrawals from the Martin District's system, however, no cooperation.
 - C. For each fire department that made a withdrawal from the Martin District system for the purpose of extinguishing fires or training purposes during the period January 1, 2013, to present, provide a copy of the fire department's estimate of the withdrawal.
 - d. Estimates were made by the District's Office since no reports were present for withdrawals and placed on the water loss report as estimates.
 - D. For any instance in which a fire department failed to provide an estimate of a withdrawal during the period January 1, 2013, to present, state the actions that Martin District took concerning the failure.
 - e. A meeting was held with the County Judge Executive the Chairman of the Board and Business Manager, concerning the lack of water withdrawal reports from the Fire Departments and was informed that the Judge Executive would withhold funds from the Fire Departments.
 - E. Provide a copy of each record kept by Martin District pursuant to 807 KAR 5:006, Section 26(3), for the period January 1, 2015, to date.
 - f. The District will be presented with a Utility Inspection Checklist for approval at the next meeting on May 24, 2016. The Inspection Checklist will then be sent to the Commission for review.

- 23. Identify each contract that Martin District has with another water system for the purchase or sale of water. For each contract, state the date the contract was filed with the Commission.
 - a. Mountain Water District (04/16/1992)
 - b. Paintsville Utilities (05/01/2013)
 - c. Prestonsburg Utilities (Agreement (01/15/1998)
- 24. Confirm whether Martin District is currently providing water service to the United States Penitentiary, Big Sandy, and if not, explain why Martin District is unable to provide water service to the federal prison.
 - a. The District supplies water to the Honey Branch Tank and that water pumped is metered at the pump station, located at the entrance to the Honey Branch Industrial Park. Martin County customers or businesses located on the Industrial Site and on New Route 3, Davella Road, Brookview Apartments, and Holding Hills Trailer Park are supplied by the Honey Branch Tank. The water supplied to District's customers is metered by the outgoing meter at the pump station. The difference in water going to the Honey Branch Tank and water supplied to the Martin County customers is purchased by Prestonsburg Utilities at \$3.05 per thousand. If we do not pump sufficient amount of water to supply our businesses and customers mention, we must pay Prestonsburg Utilities \$3.05 per thousand. Prestonsburg Utilities has the Contract with the United States Prison

VERIFICATION

I, Joe Hammond, of the Martin County Water District, hereby verify that the responses and exhibits attached hereto are true and correct to the best of my knowledge.

Joe Hammond

STATE OF KENTUCKY)

COUNTY OF MARTIN)

SUBSCRIBED, SWORN and ACKNOWLEDGED before me by Joe Hammond this _9th day of May, 2016.

My Commission Expires: 9-18-18

NOTARY PUBLIC, STATE AT LARGE

Exhibit #1 Current List of Work Orders

Martin County Water Listrict

387 East Main St., Suite 140 Inez, KY 41224 (606) 298-3885

Service Orders Dated Between 4/1/2016 And 4/29/2016

Type of Work	Sen	ice Order Count	Closed Order Count	Open Order Count	
Change Out		28	14	14	
Cheater Bar Investigation		2	1	1	
Complaints		6	3	3	
Leak		28	20	8	
Line Locate		2	1	1	
Meter Pull Non-Pay		16	10	6	
Meter Set		32	31	1	
MISC.		32	20	12	
Pull - Customer Request		21	16	5	
Pull - MCWD Request		2	2	0	
Read IN		13	11	2	
Read Out		13	11	2	
Replace shut off		4	2	2	
Re-Read		1	1	0	
Тар		5	1	4	
Verify Meter Number And	Re	16	15	1	
	Totals:	221	159	62	

Exhibit #2 Number of Taps Requested

Martin County Water Listrict

387 East Main St., Suite 140 Inez, KY 41224 (606) 298-3885

Service Orders Dated Between 10/6/2015 And 4/29/2016

Tyrie of Work	Service Order Count	Closed Order Count	Open Order Count	ada adamin a sa sa atau a a a a a a a a a a a a a a a a a
Тар	14	10	4	
т.	otals: 14	10	4	

Exhibit #3 Number of Taps Request Pending

Martin County Water District

387 East Main St., Suite 140 Inez, KY 41224 (606) 298-3885

Service Orders Dated Between 10/6/2015 And 11/13/2015

Type of Work	Service Order Count	Closed Order Count		
Тар	5	5	0	
То	tals: 5	5	0	

Exhibit #4 Number of Turn-offs

Martin County Water Listrict

387 East Main St., Suite 140 Inez, KY 41224 (606) 298-3885

Service Orders Dated Between 10/6/2015 And 4/29/2016

Type of Work	Service Order Count	Closed Order Count	Open Order Count	
Meter Pull Non-Pay	143	137	6	
Pull - Customer Request	117	111	6	
Pull - MCWD Request	3	3	0	
т	otals: 263	251	12	

Exhibit #5 Comparison of Electricity Cost

MARTIN COUNTY WATER DISTRICT

Purchased Power: 2015		Purchased Power: 2014			
Jan 2015	25,804.90	Jan 2014	30,264.06		
Feb 2015	24,920.52	Feb 2014	21,212.23		
March 2015	33,022.57	March 2014	20,753.67		
April 2015	18,694.78	April 2014	13,010.71		
May 2015	16,534.37	May 2014	22,947.20		
June 2015	21,505.77	June 2014	22,637.44		
July 2015	25,425.76	July 2014	27,219.42		
Aug 2015	23,221.15	Aug 2014	33,597.27		
Sept 2015	25,847.90	Sept 2014	32,347.95		
Oct 2015	35,897.10	Oct 2014	29,940.51		
Nov 2015	31,206.11	Nov 2014	29,764.02		
Dec 2015	32,613.03	Dec 2014	24,272.98		
	314,693.96		307,967.46		

Exhibit #6 Water Loss and Leak Detection Program

Martin County Water District Water Loss Plan February 2016

Steps to follow:

- Read the master meters daily and at the same time each day. At a minimum, they should be read Monday through Friday. This will minimize water loss due to a large leak that can go undetected for a week or month.
- Divide the distribution system into zones or subsections where
 possible and calculate water loss for each zone. This will allow for
 the prioritizing of work based upon the severity of the problem in a
 particular zone.
- Utilize computer billing software to generate water loss reports for sections or zones as well as to generate an overall water loss report.
- Install bypass monitor meters as needed to isolate lines with potential leaks. A 5/8- x 3/4- inch meter will suffice for each 100 customer section of line.
- Install a 2 inch bypass monitor meter at water storage tanks to isolate sections of the line with potential leaks during the night (1:00 a.m. to 4:00 a.m.)
- Utilize pressure recordings to detect fluctuating pressures and abnormally low or high pressures in distribution systems lines.
- Test and change-out all meters according to Kentucky Public Service Commission (PSC) regulations. PSC regulations require residential meters to be tested and changed-out in 10-year intervals. Four-inch and larger meters are to be tested annually.

- It may be feasible to hire a part-time operator to utilize leak detection equipment to search for leaks. A portion of the distribution system could be covered each month.
- Identify sections of pipe in the distribution system with the most frequent line breaks. Budgeting for infrastructure replacement is imperative in any water utility.
- Having a main transmission line from the master meter to a water storage tank will reduce pressure fluctuations in the distribution system and result in fewer line breaks.
- Provide the necessary resources for manpower and equipment to properly maintain the distribution system appurtenances such as gate valves, pressure reducing valves, and hydrants.

COMPONENTS OF A WATER LOSS PREVENTION PLAN

How do the terms "water loss" and "weight gain" relate? Can it be that apathy, procrastination, or plain idleness might apply to both situations? Definitely, good intentions abound with either problem. No one wants to be overweight, just as no one who is responsible for the management and operation of a water utility wants to have excessive water loss. How do we attack these problems? In either case, we must identify the root of the problem, focus on a solution and stick with it! How many times have we heard the phrase, "If you fail to plan, you plan to fail." A good plan is the key to any long-term solution.

A person's physical and psychological make-up has a huge impact when attempting to solve the weight problem. Heredity affects us in many ways, but especially in regards to our ability to lose weight. What about the person who accepted the position of manager and soon learned that they had inherited an inadequately operated water system?

Age is another common factor in both problems. A water distribution system that was installed in the WPA days of the 1930's will most likely experience problems that newly installed water lines will not possess. The older that I get, the harder it is to keep the weight off! We can list other analogies such as our body shapes and sizes compared to the geographical terrain of our utilities and our distribution system sizes. However, let's get going with a proactive approach to the problem of water loss.

Accurate records are vital to any water loss prevention plan. How do we know the status of our water loss if we do not keep records? There is a water loss template that is available for download from the Kentucky Rural Water Association website

(www.krwa.org). This Excel spreadsheet, or a similar record keeping system, can be utilized in a preliminary water audit. The initial step in water loss prevention is the water loss calculation. Secondly we must locate and eliminate all water leaks. Sounds easy, doesn't it?

The following steps can be utilized to prevent or reduce water loss and should be incorporated into a water loss prevention plan:

- Read the master meters daily and at the same time each day. At a minimum, they should be read Monday through Friday. This will minimize water loss due to a large leak that can go undetected for a week or month.
- 2. Read all meters in the distribution system within a 3-to 5-day window. When the meters are read over a

- 2-week period, this will cause fluctuations of monthly water loss numbers. However, these numbers will average out over a year's period of time.
- Divide the distribution system into zones or subsections where possible and calculate water loss for each zone. This will allow for the prioritizing of work based upon the severity of the problem in a particular zone.
- 4. Utilize computer billing software to generate water loss reports for sections or zones as well as to generate an overall water loss report.
- 5. Install bypass monitor meters as needed to isolate lines with potential leaks. A 5/8- x 3/4-inch meter will suffice for each 100-customer section of line.
- 6. Install a 2-inch bypass monitor meter at water storage tanks to isolate sections of the line with potential leaks during the night (1:00 a.m. to 4:00 a.m.)
- 7. Utilize pressure recordings to detect fluctuating pressures and abnormally low or high pressures in distribution system lines.
- Test and change-out all meters according to Kentucky Public Service Commission (PSC) regulations. PSC regulations require residential meters to be tested and changed-out in 10-year intervals. Four-inch and larger meters are to be tested annually.
- 9. It may be feasible to hire a part-time operator to utilize leak detection equipment to search for leaks. A portion of the distribution system could be covered each month.
- Identify sections of pipe in the distribution system with the most frequent line breaks. Budgeting for infrastructure replacement is imperative in any water utility.
- Having a main transmission line from the master meter to a water storage tank will reduce pressure fluctuations in the distribution system and result in fewer line breaks.
- 12. Provide the necessary resources for manpower and equipment to properly maintain the distribution system appurtenances such as gate valves, pressure reducing valves, and hydrants.

Today's advanced technology can certainly enhance our water loss prevention plan. Computers not only utilize software for spreadsheets to calculate water loss expediently, but can be used in a variety of ways to identify areas of the distribution system with potential leaks. Both master meters and customer meters can be read by satellites or other automated meter reading mechanisms.

Telemetry/SCADA systems operated with computers can produce trend charts for water flows, water pressures, and water levels in storage tanks. This kind of data is valuable in determining where leaks are or are not prevalent. Computers analyze hydraulic data to determine if theoretical and actual water flows and water pressures in the distribution system match. Computerized maps with GPS and GIS data are beneficial when used properly. A water utility's budget is the major limiting factor as to why technology is not used more frequently.

By industry standards, more than 15 percent water loss in a rural system in unacceptable. Probably, no one realizes this more than the managers of water districts, water associations, and investor-owned utilities under the jurisdiction of the Kentucky Public Service Commission. Just as we should be concerned with our health due to being overweight, the PSC is concerned with the financial health and well-being of water utilities under their PSC inspectors routinely jurisdiction in Kentucky. discuss water loss during their inspections. When a water system exceeds 15 percent water loss on their annual report to the PSC, a deficiency is issued. Numerous water systems' response to the PSC's Deficiency Tracking Reports (DTR) has been deemed unacceptable by PSC. A common request from PSC to the water system with a deficiency due to water loss is for a water loss control plan. A good water loss control plan should include the above-mentioned components with a time frame to implement the improvements and follow-up evaluations to measure the success of the plan.

Whether we are weighing in or wading in, we should always do so with a goal in mind. We cannot continue to ignore our problem and hope it resolves itself. Just as there are various diets to control an individual's weight, there are various methods for controlling water loss.

Let's start implementing all of our good intentions!

Exhibit #7 Updated Capital Improvement Plan



Preliminary Project Cost Estimate

Project: Water Treatment Plant Improvements

Date:

Job No. :

Revised:

03/08/16

Est. By:

BKL

\au		Revised:	03/08/16	Est. By:	BKL	
ITEM	SUMMARY OF:	QUANTITY		apr		TOTAL
NO.		NO. OF UNITS	UNIT MEAS.	COST PER UNIT		COST
1	Electrical System Improvements	1	. LS	\$ 280,000.00		\$ 280,000.00
2	Mechanical Renovations (Operations Building)	1	LS	\$ 196,000.00	<i></i>	\$ 196,000.00
3	Structural Renovations (Operations Building)	1	LS	S 216,000.00		\$ 216,000.00
	Architectural Renovations (Operations Building)	1	LS	\$ 425,000.00		\$ 425,000.00
5	Process Improvements and Expansion	<u> 1</u>	LS	\$ 3,430,000.00	· · · · · · · · · · · · · · · · · · ·	\$. 3,430,000.00
	Subtotal					\$ 4,547,000.00
	Contractors OH&P (10%)	· · · · · · · · · · · · · · · · · · ·				\$ 454,700.00
	Subtotal	1				\$ 5,001,700.00
Mob	ilization, Bonds, and General Conditions (10%)	: :			· 	\$ 500,170.00
	Subtotal	: :				\$ 5,501,870.00
r.	Contingency @ 10%	: 		:	,,, ;	\$ 550,187.00
	Total	:				\$ 6,052,057.00
			4			
	TOTAL AMOUNT - CONSTRUC	TION COST			:	\$ 6,052,057.00
		ING DESIGN	6.64%			\$ 402,150.00
	RESIDENT LEGAL AND ADMIN	INSPECTION VISTRATION	3.31%			\$ 200,600.00
	TOTAL ESTIMATED PROJECT	COST			· · · · · · · · · · · · · · · · · · ·	\$ 6,654,807.00




Exhibit #8
Pending Disconnects

Martin County Water
Past Due
04 29 2016

Text44	Text46	Current	30 Days		90 Days	Total Due
KY	41224	\$57.33	\$98.68	-	\$0.00	\$231.92
KY	41224	\$57.33	\$37.62	***	\$115.86	\$248.43
KY	41267	\$86.31°	\$45.21	\$9.63	\$0.00	\$141.15
KY	41267	\$57.33	\$30.03	\$96.80	\$0.00	\$184.16
KY	-41231	\$34.20	\$0.00	\$0.00	\$325.40	\$359.60
KY	,-41267	\$102.87	\$105.94	\$30.03	\$120.12	\$358.96
KY	-41224	\$318.17	\$166,66	\$166.66	\$834.34	\$1,485.83
KY	-41267	\$157.38	\$105.94	\$23.76	\$0.00	\$287.08
KY	41267	\$57.33	\$37.62	\$0.54	\$0.00	\$95.49
ΚY	41224	\$64.23	\$45.21	\$104.92	\$0.00	\$214.36
KY	-41224	\$85.62	\$57.97	\$37.62	\$27.70	\$208.91
KY	41231	\$61.80	\$0,00	\$0.00	\$206.73	\$268.53
KY	-41231	\$57.33	\$30.03	\$4.60	\$0.00	\$91:96
KY	41231	\$52,61	\$0.00	\$0.00	\$171.04	\$223.65
KY	41231	\$71.82	\$37.62	\$3.78	\$0.00	\$113.22
KY	41231	\$57.33	\$45.21	\$6.93	\$0.00	\$109.47
KY	41231	\$57.33	\$30.03	\$2.06	\$0.00	\$89.42
KY	41231	\$100.11	\$67.98	\$0.31	\$0.00	\$168.40
KY	41224	\$79,41	\$75.57	\$37.62	\$0.00	\$192.60
KY	-41250	\$30.03	\$30.03	\$45.21	\$231.66	\$336.93
KY	-41250	⁴ \$30.03	\$30.03	\$10.15	\$0.00	\$70.21
KY	-41250	\$37.62	\$37.62	\$5.49	\$0.00	\$80.73
KY	-41250	\$67.98	\$189,44	\$30,03	\$302.74	\$590.19
Ку	-41250	\$0.00	\$0.00	\$0.00	\$229.46	\$229,46
KY	-41250	\$0.00	\$0.00	\$0.00	\$241.55	\$241.55
KY	-41250	\$0.00	\$0.00	\$0.00	\$67.95	\$67.95
KY	-41250	\$0.00	\$0.00	\$59.61	\$109.31	\$168.92
KY	-41224	\$0.00	\$0.00	\$74.03	\$0.00	general area of the second
KY	41224	\$30.03	\$30,03	\$30.03	\$0.00	\$90.09
KY	-41250	\$57.33	\$30.03	\$37.62	\$39.29	
KY	-41267	\$262.97	\$86.30	\$0,00	\$163.66	\$512.93
KY	-41267	\$93.21	\$52.80	\$37.62	§	300 10000000000000000000000000000000000
KY	41231	\$64.23	\$30.03	\$5.42		·
KY	-41231	\$100.11	,	\$*	*	35
KY	41231	\$71.13	\$52.80	\$23.66		
KY	-41231	\$149.79	7	1	300000000000000000000000000000000000000	li ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '
Ку	-41231	\$57.33			1	
Ку	41514	\$89.03	4	1	,	
KY	-41514	\$64.23		. } ~ ~	Ton	
KY	41203	\$115.29		*		unit or and all Administration of
KY	41203	\$61.80	4	- B RAMMANIANA A. A. A		3
KY	41203	\$57.33				1 11111
KY	-41203	\$64.23	7	J	-3	
KY	41231	\$57.33	· č. · · · · · · ·	`		.,,
KY	41203	\$57.33	3 \$37,62	\$23.16	\$0.00): \$118.11

Martin County Water Past Due

04 29 2016

					. ~	
KY	41203	\$130.47	\$83.16	\$67.98	\$173,86 [‡]	\$455.47
KY	41203	\$93,90	\$52.80	\$27,18	\$29.65	\$203.53
KY	-41203	\$57,33	\$45.21	\$7.59	\$0.00	\$110.13
KY	41567	\$57.33	\$37.62	\$10.60	\$0.00	\$105,55
Ку	-41224	\$129:09	\$45.21	\$67.98	\$153.23 [°]	\$395.51
KY	-41224 :	\$78.72	\$30.03	\$19.29 ⁵	\$0.00	\$128.04
KY	-41224	\$64.92;	\$30.03	\$46.60	\$126.18	\$267.73
KY	41224	\$71.82	\$37.62	\$12.01	\$0.00	\$121.45
KY	-41224	\$57.33.	\$0.00	\$0.00	\$62.98	\$120.31
Ку	-41224	\$78.72	\$37.62	\$45.21	\$6.70	\$168.25
ΚY	41224	\$41.10	\$0.00	\$2.13	\$224.58	\$267.81
KY	'41224	\$57.33	\$30.03	\$3.42	\$0.00	\$90.78
KY	41224	\$115.29	\$52,80	\$39.12	\$0.00	\$207.21
KY	41224	\$100.11	\$30.03	\$11.27	\$0.00	\$141.41
KY	-41224	\$131.85	\$143.89	\$8.36	\$0,00	\$284.10
KY	41224	\$107.62 ¹	\$0,00	\$0.70	\$0.00	\$108.32
KY	41224	\$406.10	\$401.30	\$6.89	\$0.00	\$814:29
KY	-41224	\$79.41	\$37.62	\$40.63	\$0.00	\$157,66
KY	-41224	\$108.39	\$83.16	\$68,42	\$0.00	\$259.97
Ку	-41230	\$64.23	\$52.80	\$30.03	\$115.32	\$262.38
KY	41224	\$57.33	\$30.03	\$2.73	\$0.00	\$90.09
KY	41224]	\$41.10	\$0.00	\$0.00	\$132.87	\$173.97
KY	.41224]	\$57.33	\$48.62	\$30.03	\$0.00	\$135.98
KY	-41224	\$172.52	\$52.80	\$30.03	\$239.38	\$494.73
KY	-41224	\$115.98	\$52.80	\$12.82	\$0.00	\$181.60
KY	-41224	\$93.21	\$52.80	\$37.62	\$21.54	\$205.17
KY	-41224	\$57.33	\$190.63	\$9.33	\$0.00	\$257.29
KY	-41224	\$78.72	\$52.80	\$4.11 ²	\$0.00	\$135.63
Ку	-41224	\$86.31	\$30.03	\$83.16	\$0.00	\$199.50
KY	-41224	\$54,90	\$0.00	\$0.00	\$96.31	\$151.21
KY	-41224	\$64.92	\$30.03	\$32.28	\$0,49	\$127.72
KY	-41230	\$71,82	\$0.00	\$44.41	\$87.04	\$203.27
KY	41224-093	\$100.80	\$52.80	\$14.29	\$0.00	\$167.89
KY	41224	\$93,90	\$67.98	\$30.03	\$285.51	\$477.42
KY	41224	\$130,47	\$75.57	\$52.80	\$264.83	\$523.67
ĶΥ	41224	\$79.41	\$37.62	\$45.21	\$91.28	\$253.52
KY	-41224	\$71.82	\$30.03	\$45.21	\$193.18	\$340.24
Ку	-41224	\$100.11	\$37.62	\$52.80	\$455.23	\$645.76
ΚY	41224	\$172.56	\$83.16	\$8.94	\$0.00	\$264.66
KY	-41224	\$107.70	\$75.57	\$10.39	\$0.00	\$193.66
KY	-41224	\$78,72	\$30.03	\$10.36	\$0.00	\$119.11
KY	-41224	\$79.41	\$37.62	\$5.21	\$0.00	\$122:24
KY	-41214	\$86.31	\$60.39	\$15.99	\$0.00	\$162.69
KY	-41224	\$95.28	\$0.00	\$0.00	\$172.47	\$267.75
KY	-41214	\$79.41	\$60.39	\$60.21	\$62.25	\$262.26
KY	-41214	\$163.91	\$0,00}	\$0.00	\$200:00	\$363.91

Martin County Water Past Due 04 29 2016

P				07 20 20	,,,,	
KY	41214	\$71.82	\$30.03	\$15.42	\$0.00	\$117.27
KY	-41214	\$34.20;	\$0.00	\$0.00	\$1.00	\$35.20
KY	-41224	\$41.10 [;]	\$0.00	\$0.00	\$68,67	\$109.77
KY	41214	\$78.03	\$30.03	\$0.06	\$0.00	\$108.12
Ку	-41214	\$57.33	\$37.62	\$2.73	\$0.00	\$97,68
KY	-41224	\$71.82	\$52.80	\$11.14	\$0.00	\$135.76
KY	41224	\$57,33	\$30.03	\$37.62	\$25.30	\$150:28
KY	41224]	\$64.23	\$15.97	\$0.00	\$16.20	\$96:40
KY	-41224	\$57.33	\$30,03	\$0.03	\$0.00	\$87.39
KY	41224	\$27,30	\$0.00	\$0.00	\$57.31	\$84.61
KY	-41230	\$57.33	\$0.00	\$0.00	\$895.27	\$952;60
Ку	-41224	\$34.20	\$7,33	\$37.62	\$74.60	\$153,75
Ку	-41230	\$108.39°	\$60.39	\$4.80	\$0.00	\$173.58
KY	41230	\$100.80	\$45.21	\$52.80	\$303.05	\$501.86
KY	-41230	\$122.88	\$30.03 [§]	\$90.75	\$137.92	\$381.58
KY	-41230	\$114.60;	\$52.80	\$83.16	\$54.87	\$305.43
KY	-41230	\$86.31	\$37.62	\$47.25	\$0.00	\$171.18
KY	41224	\$57.33	\$30,03	\$2.73	\$0.00	\$90.09
KY	41224]	\$100.80	\$52.80	\$2.29	\$0.00	\$155.89
KY	-41224	\$174.64	\$107.30	\$53,30	\$0.00	\$335.24
KY	-41224	\$64,92	\$30,03	\$3.03	\$0.00	\$97.98
Ку	41224	\$61.80	\$97.11	\$124.80	\$0.00	\$283.71
KY	41224	\$57.33	\$30.03	\$0.27	\$0.00	\$87.63
KY	41224	\$100.80	\$60,39	\$25.57	\$0.00	\$186.76
KY	41224	\$27,30	\$0.00	\$0.00	\$129.63	\$156.93
KY	41224	\$497.60	\$166.66	\$227.39	\$2,191.41	\$3,083.06
KY	41224	\$57.33	\$30.03	\$30.03	\$30.03	\$147.42
Ку	-41262	\$78.72	\$37.62	\$2.11	\$0.00	\$118.45
KY	41262	\$57.33	\$30.03	\$5.63	\$0.00	\$92.99
KY	41262	\$64.23	\$45,21	\$23,22	\$0.00	\$132.66
KY	-41262	\$54.90 [°]	\$0.00	\$0.00	\$146.69	\$201.59
KY	-41262	\$64.92	\$30.03	\$3,42	\$0.00	\$98.37
KY	41224	\$54.90	\$0,00	\$0.00	\$215.66	\$270.56
KY	41224	\$64.23	\$37.62	\$37.62	\$199.73	\$339.20
KY	41224	\$209.15	\$121,12	\$16.49	\$0.00	\$346.76
KY	-41224	\$71.82	\$45.21	\$3,08	\$0.00	\$120.11
KY	41262	\$64.23	\$30.03	\$30.03	\$38.06	\$162.35
KY	41262	\$64.23	\$30.03	\$29.61	\$0.00	\$123.87
Ку	-41262	\$100.80	\$45.21	\$0.21	\$0.00	\$146.22
KY	-41262	\$57.33	\$30.03	\$0.03	\$0.00	\$87.39
KY	-41262	\$71.82	\$37.62	\$2.89	\$0.00	\$112,33
KY	-41262	\$71.82	\$30.03	\$31.98	\$0.00	\$133.83
ΚY	41262	\$100,11	\$52.80	\$2.80	\$0.00	\$155.71
KY	41224	\$78.72	\$121.12	\$75.57	\$76.88	\$352.29
Ку	41262	\$57.33	\$30.03	\$5.67	\$0.00	\$93.03
kv	41267	\$60.67	\$3 1. 78}	\$31.78	\$8,414.59	\$8,538.82
KY	TIAU1	, \$UU,UT;	يا الداردي	, 901,701	Ψυ, - 1-1.00	40,000.0Z

Martin County Water Past Due 04 29 2016

137 CUSTOMER \$11,488,65 \$41,285.70 \$6,278.54 \$3,521.94 \$19,996.57

Exhibit #9 Business Manager's Job Duties

Position Responsibilities

Business Mgr.

- Responsible for Financial and legal issues
- Policy enforcement
- Safety Training and reviews
- Handle PSC issues (forms, regulations, etc.)
- Control legal documents and correspondence
- Maintain personnel records
- Develop Inventory controls
- Develop purchase order protocol and controls
- Solid waste (garbage) accounts?
- Budget controls
- Quotes and bids as requested by Operations Mgr.
- Develop training programs
- Maintain office systems (hardware and software)
- Continuous system upgrades and improvements
- Equipment maintenance (office related equipment, etc.)
- Provide a safe and clean working environment
- Interface with contractors
- Report to Board

Exhibit #10 Written Complaints

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO #



Time Started Loc#		Work Complete			
		Master Meter #			
Dat 1/29	9/2013	Account #	SEQ# 479	a ***	
,	Kally Maymard	No November gas dimensiones in accommon accommon accommon .	Phone #	····· / ··· *	
Address:	***************************************		Employee Josh Williams		
. •	Inez, KY 41224		* v /halace ti x		
		<u> </u>		> 44 &	
	THICKETY FORK		A STATE OF THE PROPERTY OF THE	* *** *	
Type of W	/ork: Complaints				
Material U	Jsed:		and an area of the same of the	uur shekka 2 Na s 2	
Customer	Line Inspection)*	يمر شدر	
	s: no water for three days	1 1	A commence of the commence of	ngruserer ş. N.ng	
	Current System Information:	y die widdende wysger – generalisty ag morania de de maria in the second de	New Information:	Se una manuera e dine desc	
Meter#1:	29934541	noncommunity of the state of th	Meter # 1:	n nager tray my trabben	
Meter # 2:	Radio	7000000-000000000000000000000000000000	Meter # 2: Radio	tour Military	
MXU#:		······································	MXU #:	************	
Current Re	eading 12/20/2012 362		Current Reading 0		
Type of M	eter: Badger	nonna and denother Medicades	Type of Meter:		
Year MFG	2004		Year MFG:	co-ime	
GPS - Lon	ngitude	-	GPS - Latitude	en internet	
Employee	Signature(s):		Date Completed 1-29-13		

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#



Tii	Time Started		Work Complete		
Loc#	nde nye Kalana, i yan y. 30, 35 k 25 aktor aktor aktor aktor aktor an	Master Met	ter#		
Date 1/28/2013	ye dissipaninke siyi da giriraya yaya iya ii ye sidayi 8.90 - 100 yanan	Account #	SEQ # 123		
	& Donna Howard	A likeliharan da arang a	Phone #	hand the street	
			november		
Louisa	a, Ky 41230		<u>`</u>		
			"		
Programme de la companya de la compa		·	20 miles and a second a second and a second	mandamini ang mang pinan	
B	lankenship Hlw Rd	(c)			
Type of Work: C	Complaints		The second secon	and the same of th	
Material Used;)one)		
 Customer Line l	D.I.	1 aft			
	A Mark Economic Company of the Compa	<u> </u>		26 / This was a sine on year and	
			in lines too		
	nt System Information		New Information:		
			IAGAA HIIOHIINMOII.		
Meter#1:	29935136		Meter # 1:	v *	
	29935136 29935136	myreemen	Meter # 1:		
Meter#2: Radio	and the second s	in promised of the set No.	Meter # 2: Posto		
Meter#2: Radio	29935136		Meter # 1: Meter # 2: Radio		
Meter # 2: Radio MXU #: Current Reading	29935136 12/20/2012 112		Meter # 1: Meter # 2: Radio MXU #:		
MXU #:	29935136 12/20/2012 112		Meter # 1: Meter # 2: Radio MXU #: Current Reading 0		
Meter # 2: Radio MXU #: Current Reading Type of Meter:	29935136 12/20/2012 112 Badger 2004		Meter # 1: Meter # 2: Radio MXU #: Current Reading 0 Type of Meter:		

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER



WO #

Time Started	Work Complete
Loc#	Master Meter #
Date 1/18/2013 Accoun	sEQ#
Name: Floretta Coleman	Phone #
Address:	
For the second s	T 200 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Location: Newberry Ln	inagarammashan maga i sandhi kandhan kang sandi kanghal ya wa kamanina iya hii ya kandha papama manga mana maga mana i disha kila ili ili ili ili ili ili ili ili ili
Type of Work: Complaints	
Material Used:	
Customer Line Inspection	
Comments: pot holes from previous work done by M	CWD
Current System Information:	New Information:
Meter # 1:	Meter # 1:
Meter # 2: Radio	Meter # 2: Radio
MXU #:	MXU#;
Current Reading 0	Current Reading 0
Type of Meter:	Type of Meter:
Year MFG:	Year MFG:
GPS - Longitude	GPS - Latitude
Employee Signature(s): $\sum 5$	Date Completed [-22-[3

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO #



Tir	me Started	Work Complete	
Loc#	recommendations for \$ 1 as any conditioning \$ 1. Let a vincounced sometime where the	Master Meter #	Section 18 Commission of the C
Dat 12/28/2012	Ac		SEQ # 42
Name: Lando	n Jude	Phone	
Address: P.O. B	and the second s	***************************************	oyee Kyle Sammons
Lovely	, KY 41231	in the state of the control of the c	
Location E		awn shop, white w/green shutters,	
. <u> </u>	Main St		. The same of the
Type of Work: C	omplaints		,
Material Used:		() (eved)	
Customer Line In	spection		8
	emely low water pressure	Sypresure oit Box	battealy low from
Curren	t System Information:	Ne	w Information:
Meter # 1:	70616368	Meter # 1:	The state of the s
Meter # 2: Radio	70616368	Meter # 2: Radio	and the same of th
MXU#:	14440339	MXU#:	ментова и что том на потовно и при при потовно по потовно по потовно по потовно по потовно по по по по по по п
Current Reading	12/20/2012 3	Current Reading	0
Type of Meter:	The state of the s	Tuno of Motor:	
Year MFG:	Annahim and the second of the	Year MFG:	
GPS - Longitude		GPS - Latitude	No. 1 No. 1 Garage
Employee Signat	ure(s): ()\	Date Comple	eted - 7 - 3

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER



		WO #	121200	072	
	Time Started	a year construint of the second	٧	/ork Complete Ye	S &
Loc#	an annual and the second and the sec	The state of the s	Master Me		en e
Dat 12/	18/2012	Acc	ount#	and the same of th	SEQ # 256
Name:	William Maynard			Phon	e#
Address:				Empl	oyee Josh Williams
	Lovely, KY 41231			one of the state o	entra Angel 1980 et a mark demonstration con co.
Location	2nd driveway before Bi	g Branch, Mayna	ırd Flat, white	trailer w/black shu	tters
	A Commence of the Commence of	and the second s	PRO Service and Association of Contraction		and a superior of the superior
Type of V	Vork: Complaints	· · · · · · · · · · · · · · · · · · ·	asasini iya	County	3021 need gravel
Material l	Jsed: Looked good			Jan. 100 100 100 100 100 100 100 100 100 10	The second secon
, Custome	r Line Inspection		10/	annum a gramma an aranno della	
Commen	ts needs more gravel w		put in line arc	und driveway	Joe Fold Mayraid
	Current System Inform			N	ew Information:
Meter#1	• • • • • • • • • • • • • • • • • • •			Meter # 1:	North and the state of the stat
Meter#2	Radlo	and a supplement to the supplement of the supple		Meter # 2: Radio	non transference and transference and transference and the second and the second and the second and the second
MXU#:	Salahanan aran aran salahan dari dari da Aran			MXU #:	**************************************
Current R	eading 0	Charles and the same and the sa		Current Reading	<u>0</u>
Type of M	leter:			Type of Meter:	gen ^l an y <mark>magning</mark> en o o mag age saganggang ang saganggan ang sagang a saganggan sagang a saganggan sagang ang saganggan sa
Year MFG	5 :			Year MFG:	
GPS - Lor	ngitude			GPS - Latitude	and the second s

29934504 Stadelas

Employee Signature(s):

70750162 Variety -130

Date Completed

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER



WO#

	Time Started		Work Complete	
Loc#	· · · · · · · · · · · · · · · · · · ·	Master	Meter#	production of the control of the con
Date 1/10/201	3	Account #		SEQ# 175
Name: BAR	RBARA MARCUM		Pho	ne# (
Address: PO	вох		·	
BEA	UTY , KY 41203	es wermanness. Chian Propo, ayona a summonamananananin va	PROVINCE ♥ ₹ .com .color-sica relacionalescensors.	
Location: from	hig black barn	, , , , , , , , , , , , , , , , , , , ,	before Gospel Light	, red brick house on left across
Type of Work:	Complaints		The second secon	
Material Used:				
Customer Line	Inspection 83-904	AS ATT	C 0.0	JATON
	omplaints of too much pres			
Curr	ent System Information:			New Information:
Meter # 1:	20541976		Meter#1:	was distinct and the desired and the second second and the second
Meter#2: Radi	0		Meter # 2: Radio	Por Parker and districtions are properly a gramma management on the contract of the contract o
MXU#:	· · · · · · · · · · · · · · · · · · ·	i ya danamanan nakan kabu.	MXU#:	Style tide and a temption to the second temption to the second temption of the second tempt
Current Readir	ng 12/20/2012 503	incident the historical definition to proof of the physiology	Current Reading	O Company Comp
Type of Meter:	Badger		Type of Meter:	Characters and Control to Annual States of States and States and Annual States and Annual States and Annual States
Year MFG:	2004	nomina memorana salah kan salah s	Year MFG:	was a state of the
GPS - Longitud	de <u>0</u>		GPS - Latitude	0
Employee Sigr	nature(s) \\S - \TS - C_S	-11	Date Com	pleted - //- 13

387 East Main St., Suite 140 . Inez, KY 41224



WORK ORDER

WO#

Ti	ime Started	Work Complete		
Loc#		Master Meter #		
Date 2/6/2013		Account #	SEQ # 437	
Name: MELV	IN HOWARD	i siyo wakan gi iiin kin 30 3005 2006 5 yaanoo 2 65 c waxaanoo kaanoo kaanoo kaa ka	Phone #	
Address: P.O.B	ΟX	in the second se		
INEZ	, KY 41224	ng rang ng managang ana sa sa manak sa marana ma ma mma sa managan ka sa		
Location:E	den Ln, ON RIGHT ACRO	OSS FROM PUMP STATION,	grey/white single-white	
645-S	AW MILL RD		and a single-state of the second seco	
Type of Work: C	Complaints		and the state of t	
Material Used:	ranga sagan et an an an		·····	
Customer Line I	2012 En 2014 En 1914		· · · · · · · · · · · · · · · · · · ·	
Comments: box	is too deep in the box to	reach, customer would like it	fixed put a 6 riser	
Currer	nt System Information:	grap graphic spaces and the property of the community of the property of the second spaces of	New Information:	
Meter # 1:	98343293	Meter	# 1:	
Meter # 2: Radio	is No manus of morning a physical with about manuscription and second se	Meter	# 2: Radio	
MXU #:	Control of the control of the specific and the specific of the	MXU #	te	
Current Reading	1/20/2013 708	Currer	at Reading	
Type of Meter:	Badger	Туре с	of Meter:	
Year MFG:	1998	Year N	AFG:	
GPS - Longitude	Distriction of the state of the	GPS -	Latitude 0	
Employee Signa	ture(s): TC		Date Completed 2 - 11 - 13	

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#



	Time Started	1	Work Complete	e med term	
Loc#	and adjusted to the surface who are only appropriate the surface and the surfa	Master M	fleter#	· · · · · · · · · · · · · · · · · · ·	
Date 2/6/201	13	Account #	S	EQ# 199	io vid anii min maaseesee s
Name: RC	DBERT & KIMBERLY SMITH		. Phone	#	oogogog n. a. a. viicoobana kiil a sh
Address: P.C	O. BOX				
<u>IN</u>	EZ , KY 41224	· · · · · · · · · · · · · · · · · · ·			
Location:	end war. Smithigh the state of the high place being the second of the state of the second of the sec			The second secon	, ab. so .
interior (in the contract of t	2.9.300 menye ya ya mana da kanan danan kanan kana Menyeri ini mini kanan kan			e processes and the second of	and the second of the second of
CC	OLDWATER RD.		1 lln		
Type of Worl	k: Complaints			min immenserative in the second contribution to the second contribution of	under management of the
Material Use	d:	100	\		y, uping varancamen
Customer Lir	ne Inspection			Tress were	
Comments:	ne Inspection extremely low pressure / / / / / rrent System Information:	5 about	44 pound	3 At box	
Cui	rrent System Information:	to the weight with and the way of a property of the first	Ne	w Information:	* * * * * *
Meter#1:	19447503	· · · · · · · · · · · · · · · · · · ·	Meter # 1:	a vallent to a secondario and a secondario to the secondario	بيور خانيات
Meter#2: Ra	adio		Meter # 2: Radio	a tanan and a managaman and a same	om vytuna mile sklet
MXU#:		*******************************	MXU #:	And the second s	
Current Read	ding 1/20/2013 852	menodospone 4.1 , 3º C	Current Reading	0	**************************************
Type of Mete	er: Badger	manina systelliterskeitere	Type of Meter:	and a subject of the	groupes "societies as a complete of the
Year MFG:	2003		Year MFG:	man a saya kapanggangganggan sagaran sagaran sagar a sa sa sa sanan mahatayan a	a u de a magail mariant de sous
GPS - Longit	ude 0		GPS - Latitude)	ka wa Mariji wa wa naji
Employee Sig	gnature(s): <u>J</u>		Date Comple	sted $2-7-1$	3

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Ti	me Started	Work Comple	Work Complete			
Loc#						
Dat <u>1/31/2013</u>		Account#	SEQ# 461			
Name: Sue D	eutton	and the same of the commence of the property o	Phone #			
Address:	omahawk Rd.	. Employee Josh Williams				
TOMA	HAWK , KY 41262	ar resource and a separate from the department of the Separate Sep				
Location:	omahawk Rd, end of line or	7 to 5 to 100 to	was an			
ROUT	E 40 WEST					
Type of Work: C	Complaints					
Material Used:		(a) over				
Customer Line I	nspection 30 lbs	Legilator Dif	showed 75lbs			
Comments: com	plaints of extremely low pres	SSURE	appear and the second of the s			
*	t System Information:		New Information:			
Meter # 1:	97094028	Meter # 1:	Approximation and the contraction of the contractio			
Meter # 2: Radio	Name of the second seco	Meter # 2:	Radio			
MXU #:		MXU #:	Appropriate of the contraction o			
Current Reading	1/20/2013 444	Current Re	ading 0			
Type of Meter:	Badger	Type of Me	ter:			
Year MFG:	.1997	Year MFG:				
GPS - Longitude	0	GPS - Latit	ude 0			
Employee Signat	:ure(s): \ / 2 \ \ \ \ / 2 \ \ \ \ \ \ \ \ \ \ \	Date (Completed 2-1-/3			

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#



	Time Started	V	Work Complete		
Loc#			Master Meter #		
Dat 3/19/201	3	Account #	SEQ	# 16	
Name: DAR	RRELL HARMON			()	
Address:	Big Branch	Statement Assaultaneous announce consideration and so see the solution of the	Employee	Josh Williams	
	/ELY , KY 41231	· · · · · · · · · · · · · · · · · · ·			
Location	3ig Br, 1/2 mile up Big Br, 3	rd bridge on right, whi	te house w green shut	ers.	
			1		
BIG	BRANCH	Done			
Type of Work:	Complaints	Voice			
Material Used:			en and grown entangence and a substitution of the A.A.Win a A.A.Wi	n and a proposal and a proposal and a second and a second a second a second and a second and a second and a second a sec	
Customer Line	Inspection				
	as had no water since Friday				
•			The state of the s	uuun muun kuutunka ja makka ta eesta ta eesta ta eesta ta ka eesta ta ka eesta ta eesta ta eesta ta eesta ta e	
	ent System Information: 74846443		Meter # 1:	nformation:	
	74846443		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	and the second s	
	43-11-11-11-11-11-11-11-11-11-11-11-11-11		VALATINI LII LII LII LII LII LII LII LII LII		
MXU #:	14992020	•	MXU #:	and the second s	
Current Readin	ng 3/15/2013 0	construction of the state of th		0	
Type of Meter:		•	Type of Meter:	AND THE STREET OF THE STREET O	
Year MFG:		· · · · · · · · · · · · · · · · · · ·	Year MFG:	appendix Al-Propaga constitution of the second seco	
GPS - Longitud	le	in die volle vir de verge, de designe der	GPS - Latitude	· · · · · · · · · · · · · · · · · · ·	
Employee Sign	ature(s): KS		Date Completed	3-19-13	

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO #



Time Started	Work Comp	plete		
Loc.#	Master Meter #	ner som såmline i i en ø sem såmlenne menne) men men menne åmlen film i energe som sim i men sjæmlinge (en s		
Date 3/27/2013	Account #	SEQ# 369		
Name: Darlene Crum	mil saamuun oo ahussaulikun saamuu maanuu yuunnanannammii aanassa n	Phone #		
Address:	and the second s			
Inez, Ky 41224	m marina Marina na m	•		
ocation: Johnson Btm. Old Rt 3. Johns	on Btm. After crossing bridge,	go right. Greyish trailer next to old store		
		A AN TO BE A PROMOTOR WITH THE PROPERTY OF THE		
ohnson Btm				
Type of Work: Complaints		and a second party of the content of		
Naterial Used:		A PERSON WEEK ME THOM PAPER MINEROMENT & WITHOUT BOTH TO THE WAS A SHEET		
nateriai Oseq.	Bondon and the state of the sta	wige a constant and migration appropriate to the first of the constant of the		
Customer Line Inspection	e company or years to sum	gar in a lawa seebaa seemanii qii qaabayiga hiin waxa maa hii hii see hii		
Comments: Redo TAD	gan diang gamen di Maganan akanka mag af ak sang Pada kababa 2004 sa manang paganangan manangan panganan sa ak			
Current System Information:	anna sang anag mata a ana managa anag ang ang ang ang ang ang ang a	New Information:		
Neter#1:	Meter # 1			
leter#2: Radio	Meter # 2	2: Radlo		
XU #:	MXII#			
urrent Reading 0				
ype of Meter:	Type of N	Aeter:		
ear MFG:	Year MF6	G:		
PS - Longitude	GPS - La	GPS - Latitude		
go y a sa s	ก ค. ค.ก	A superior and the supe		
imployee Signature(s): Tim	Dat	e Completed 3/22//3		

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO #	140500167	P	
T	ime Started	Work	Complete	
Loc#		Master Meter	#	
Date 5/22/2014	and the second s	Account #	SEQ#	227
Name: Lorett	a Moore		Phone #	aanuumunastanastanastanastanastanastanastanast
Address: P	igeon Roost Rd		w., ***	,
Pilgrir	n, Ky 41250	announcement of the second control of the se		
* h	igeon Roost Rd. 2nd house		nd Max Hale.	
· · · · · · · · · · · · · · · · · · ·	igeon Roost Rd			
Type of Work: 0	Complaints	Done		
Material Used:				
Customer Line I	nspection	- Company of the Comp		
Comments: con	nplaining that driveway is too	rough after repairs were	e made / put @	ravel in hole
Currer	nt System Information:	r	New Info	ormation:
Meter # 1:	97176588	Met	er#1:	
Meter # 2: Radio	97176588	Met	er#2: Radio	
MXU#:		MX	J #:	
Current Reading	4/20/2014 311	Cur	rent Reading	0
Type of Meter:	Badger	Тур	e of Meter:	* restricts to the control of the co
Year MFG:	1997	Yea	r MFG:	The second secon

Date Completed 5-23-14 Employee Signature(s): TH, GS, JS

GPS - Latitude

GPS - Longitude

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

140500166

Time Started				Work Complete			
Date 5/22	2/2014	Arr Arrival da gradital di altragi. Malatina di Albano della consociale consociale		**************************************			
Name:	ROBERT FRALE			P	none#	3 / / / / / / / / / / / / / / / / / / /	
Address:	Halls Rr						
	TOMAHAWK	, KY 41262	and the same of th	and the second s			
Location:							
	Vork: Complaints Jsed:				and the second section with the second		
Customer	Line Inspection			2 7	and annual section of the section of		
Comment	s: very low water p	ressure	leak on	mcwo sid	e Albox		
	Current System In		the Market Commission of the state of the st	and the second s	New Information);	
Vieter#1:	96130886	ggrafin gerf ein um meldkerweis zuer Velkenspielendbenschlich	trobumen managamen (MERRIGIA)	Meter # 1:	Account of the second of the s		
Vieter # 2:		· ·		Meter#2: Radi			
MXU #:	Security on the Control of the Contr	Augustus (Marie and a second and	·	MXU #:		manufarra d'al VIII de se al lagra qui algunda constitue a calendariste papa es	
Current Ro	eading 4/20/2014	1219		Current Readir	ng 0	WAR THE	
Type of M	eter: Badger			Type of Meter		\$	

Employee Signature(s):

1996

Year MFG:

GPS - Longitude 0

Date Completed

Year MFG:

GPS - Latitude

5-22-14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	# Ow	140	DUUTOI	
	Time Started		Work Complete	
Loc#	and the second s		Meter#	
•			SEQ # 442	
	ecycling Solutions Tech.		Phone #	-
Address: PC				
Alle	en, KY 41601			
			arage doors, in front of boiler	
	***************************************	***************************************	arage doors, in nork or boiler	
wishermone				
Ivia	rtin County Coal Hill			
Type of Work	: Complaints			-
Customer Lin	e inspection	haqisaga oʻlgishlardi sasiyasili sililisiddi dalidi di daliddi daliddi sasasa sabii qaraaqayba		onenngaggudille Makkinska saka sasanggag, *
			226-5554 / Tixed Valve 165	Imag ?!
Cur	rent System Information:	dan marin daga garan dan dan dan dan dan dan dan dan dan d	New Information:	
vleter#1:	70025360		Meter # 1:	
Vieter#2: Rad	tio 70025360		Meter# 2: Radio	
ΛXU #:	14640449		MXU #:	
Current Read	ing 4/20/2014 1293	e Mohambaran da kirikakisissa	Current Reading 0	
Type of Meter			Type of Meter:	
ear MFG:	•	······································	Year MFG:	
∋PS - Longitu	ide		GPS - Latitude	
	•	•		

Employee Signature(s):

Date Completed 5-22-14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO #	140500154	
	Time Started	Work (Complete
Loc#		Master Meter #	
Date 5/2	1/2014	Account #	SEQ# 381
Name:	James McGinnis		Phone #
Address:	McGinnis Br		
	Debord, Ky 41214		namente
Location:	Grey doublewide before Walker Pro	eece. McGinnis Br	
	Middlefork	The second secon	
Type of V	Vork: Complaints	······································	
Material l	Jsed:		
	- lina Inanadian		
Commen	ts: low pressure / /06 P		and the second s
*	Current System Information:	a. a.a. taga and an all and a figure a series arrive and a first an arrive and a figure and a fi	New Information:
Meter#1	29541627	Mete	er#1:
Meter#2	Radio	Mete	er#2: Radio
MXU #:		MAVI) #:
Current R	eading 4/20/2014 221	Curr	ent Reading 0
Type of M	eter: Badger		e of Meter:
Year MFG	2004	Year Year	MFG:
GPS - Lor	ngitude 0	GPS	- Latitude 0
Employee	Signature(s): TH / (5	165	Date Completed 5-21,14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Time Started	varriamentelekkensen e nord	Work Complete
Loc#	Maste	r Meter#
Dat 5/14/2014	Account #	SEQ# 372
Name: Carey Dindal	addition through the complete plants that the companion of 18 to 19 th the companion of 18 to 18 th the companion of 18 th the companion	Phone# (
Address: Davella Rd		Employee Jason W
Debord , Ky 4121	4	
Location Blue house on left, C	oavella Rd	
Davella Rd		
Type of Work: Complaints		
Material Used	ik V Arrov sis s s <i>ention american</i> approximate (common video mension de desprésage entre	
Comments low pressure since last	night	
Current System Informati		New Information:
Meter # 1: 19408276		Meter # 1:
Meter#2: Radi		Meter # 2: Radi
MXU#:		MXU#:
Current Reading 4/20/2014 1234		Current Reading 0
Time of Motor: Padger	,	Type of Meter:
Year MFG: 2003	2 2 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	Year MFG:
GPS - Longitude 0	in procession and his supply process on	GPS - Latitude 0
Employon Signatura(s):	VII	Date Completed 5-15-14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

VO	#		140500105
		mc 1	**************************************

Time Sta	irted	Work Complete		
Loc#	M			
Dat 5/14/2014			SEQ# 442	
Name: Recycling So	olutions Tech.	Phon	e#	
Address: PO Box	THE RESIDENCE THE TAXABLE AND THE PROPERTY OF	Empl	oyee Jason W.	
Allen, KY 41	601	essaulius a quahyisys Missamatuuunannasis k"s	· ·	
		•	of boiler	
Anger and the state of the stat	and the second s		and the second s	
Martin Count	y Coal Hill	CONTRACTOR THE RESIDENCE AND ASSESSMENT OF THE SECOND ASSESSMENT OF THE	annenda (v. 1910. 1.) C. Linguissi, dindrin and deva designe volgens (desemble designation) designation of the	
Гуре of Work: Complai	ínts			
Salata a salata a salata a			o manus - 1,5 mans 1 s cuando manus acumento acumento acumento acumento e e est escriber e e escriber e e e e e e e e e e e e e e e e e e	
Material Used			MARINE MARINE / MARINE / A OFFICE MARINE MAR	
Customer Line Inspecti	on			
	R FOR DAYS			
Current Syste	em Information:	Ne	ew Information:	
fleter # 1: 70025	5360	Meter # 1:		
Meter # 2: Radi 70025	360	Meter#2: Radi		
1XU#: 14640	1449	MXU #:		
current Reading 4/20/2	014 1293	Current Reading	0	
ype of Meter:		Type of Meter:		
ear MFG;		Year MFG:	umannonana da kanggapa da angananana kanananan X. Angan sa sa manananana a sa sa s	
		GPS - Latitude		
imployoo Signatura(s):		Data Camal	eted 5-18-18	

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Meter # 2: Radio 67012626

140500076

Time Started Loc#		Work Comple	ete	
		Master Meter #		etrophological company and the Company of the Compa
Date 5/7	/2014		SEQ# 270	
Name:	Wanda Jude		Phone #	
Address:	Pigeon Roost Rd			,
	Pilarim, Kv 41250			
	'igeon Roost Rd			
Type of V	Vork: Complaints			
Material I	(1 .	Children Charles		I'm de Albander de dAlband amazzende am A
Custome	r Line Inspection	T the swe w		territorio accentratater accentratatente de la constanta de la constanta de la constanta de la constanta de la
Commen	ts: milky water, lines need flus			
The second secon	Current System Information	, que y 164 m = 6 m = 4	New Information:	
Meter#1	: 67012626	Meter # 1:		

MXU#:	* was a contract of the second	MXU#:
Current Reading	4/20/2014 362	Current Reading 0
Type of Meter:	Sensus	Type of Meter:
Year MFG:	2006	Year MFG:
GPS - Longitude		GPS - Latitude
Employee Signat	ure(s): J S / R J	Date Completed 5-8-14

Meter # 2: Radio

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Time Started	en e a managament en	Work Complete			
Loc#	Master	r Meter#			
Dat 5/14/2014	Account #	SEQ# 382			
Name: JAY ROWE	encontroller of the second	Phone # (;			
	The second secon	•			
DEBORD, , KY 4	1214	manuscommunication (manufacture of the manufacture) and manufacture of the manufacture of			
•					
MCGINNIS BRANCH	4				
Type of Work: Complaints	Checked	and has 120165			
Material Used A+ box					
Customer Line Inspection					
Comments check pressure, complete	aints of low pressure, said	d they read 10 lbs at box			
Current System Informat	ion:	New Information:			
Meter # 1: 93749223		Meter # 1:			
Meter#2: Radi		Meter # 2: Radi			
MXU #:	•	MXU #:			
Current Reading 4/20/2014 1182		Current Reading 0			
Type of Meter: Badger	in to summand with the summer	Type of Meter:			
Year MFG: 1993		Year MFG:			
GPS - Longitude 0		GPS - Latitude 0			
Employee Signature(s):	JM	Date Completed 5 - 14 - 14			

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

/O # 130600159



Т	ime Started	meth dyselled one has a release d	Work Complete	е		·
Loc#		Maste	r Meter#			
Date 6/20/2013	, , , , , , , , ,		ž	• •	# 140	
Name: John	ny Marcum	The second second second	i	Phone#		
Address:	Poplar Frk				and the second s	> A - A - A - A - A - A - A - A - A - A
Beau	ty, Ky 41203	-				
Location:	Poplar Fork. On right bet	fore Jake's Place.				and the state of t
, it is market securious	Poplar Fork				· cosse day, ,, ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ;	and a manufacture of the first factorial declaration of the second secon
Type of Work:	Complaints	16:4)	•		W W W W W W W W W W W W W W W W W W W
Type of Work.		(I I DECI)	la consequencia de la consequencia della consequencia de la consequencia della della consequencia de la cons		******************	WANA AMANA MANAGE A MANGEMBER 1990 - 1990 - 1990 - 1990
		(1700)	* *	•		
Material Used		saft this	WA	www.augus san jarance incorrer or a	Tananani wa kata ka danakaina wa kata ka	yana ya marani wa ma
Material Used: Customer Line Comments: cus	Inspection	saft this	WA		Tananani wa kata ka danakaliwa M	
Material Used: Customer Line Comments: cus	Inspection stomer tried to turn on wa nt System Information: 12760362	saft this	WA			
Material Used: Customer Line Comments: cus Curre	Inspection stomer tried to turn on wa nt System Information: 12760362	ater, nothing is comi	ng thru meter	New In		
Material Used: Customer Line Comments: cus Curre Meter # 1: Meter # 2: Radio	Inspection stomer tried to turn on wa nt System Information: 12760362	ater, nothing is coming	ng thru meter Meter # 1:	New In	nformation	
Material Used: Customer Line Comments: cus Curre Meter # 1: Meter # 2: Radio MXU #:	Inspection Stomer tried to turn on was nt System Information: 12760362 12760362	ater, nothing is coming	Meter # 1:	New In	nformation	
Material Used: Customer Line Comments: cus Curre Meter # 1: Meter # 2: Radio MXU #: Current Reading	Inspection stomer tried to turn on wa nt System Information: 12760362 12760362	ater, nothing is coming	Meter # 1: Meter # 2: Ra MXU #:	New In	nformation	1:
Material Used: Customer Line Comments: cus Curre Meter # 1: Meter # 2: Radio MXU #:	Inspection stomer tried to turn on wa nt System Information: 12760362 12760362 5/30/2013 19	ater, nothing is coming	Meter # 1: Meter # 2: Ra MXU #: Current Reac	New In	nformation	1:

387 East Main St., Suite 140 Inez. KY 41224

WORK ORDER

WO#

130600179



Time Started Work Complete Loc# ____ Master Meter # Account# SEQ# 227 Date 6/24/2013 Name: Russel Maynard Phone # Address: P.O. Box Inez, KY 41224 Peter Cave Br. On left down over hill almost to the end before you get to Lum Porters. Cream Location: double-wide. Old Rt 3 Type of Work: Complaints Material Used: Customer Line Inspection Comments: customer has had little water pressure after meter was reinstalled, now they have no water

Current System Information:		New Inf	ormation:
Meter # 1:	The state of the s	Meter # 1:	Same the second
Meter# 2: Radio		Meter # 2: Radio	
MXU #:	·	MXU #:	
Current Reading	0	Current Reading	. 0
Type of Meter:	nested from the section of the security of the section of the sect	Type of Meter:	
Year MFG:	and the same of th	Year MFG:	The second secon
GPS - Longitude		GPS - Latitude	's

Employee Signature(s): <

Date Completed

New Information:

387 East Main St., Suite 140 Inez. KY 41224

WORK ORDER

WO#

Type of Meter:

GPS - Longitude

Year MFG:

Current Reading 5/20/2013 12

130600128

	Time Sta	ırted	·	Work Complete	-
Loc#_	c# Master Me			Meter#	
Date 6/17/	/2013	· · · · · · · · · · · · · · · · · · ·	Account #	SEQ# 8	9
Name:	Jack Small	•		Phone # ()	
Address:	I Buck Bra	anch			
	Lovely	, KY 41231		-	
Location:					
	Buck Cranch	- House			
Type of W	ork: Compla	ints			
Material U	sed:		· · · · · · ·	() fro	
Customer	Line Inspect	on W	lushed L	inc	yyen araa syna istoolee (31.0 -4 shakkiiladkiila shaananiniil 9787988
Comments	s: customer i	s complaining of r	nuddy water		
C	Current Syst	em Information:	-	New Infor	mation:
Meter#1:	74604	1131		Meter # 1:	s .
Meter#2:	Radio 74604	1131	·	Meter# 2: Radio	
MXU #:	14992	2781		MXU #:	

Date Completed Employee Signature(s):

Current Reading 0

Type of Meter:

GPS - Latitude

Year MFG:

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#



	Time Started	Work C	Complete
Loc#	the second of th	Master Meter #	n to commence come a contract of the contract
Dat 5/1/201	13 C. Samera del del constitue	Account #	SEQ # 543
Name: Ch	ester Johnson Jr.	A CHIEF PARAMETER IN MINING IN SHIP & C. T. T.	Phone #
Address:		A Section of the sect	Employee Josh Williams
To	mahawk, KY 41262	ANAL COMMENT COMMENT OF MANNEY	Tony
Location	, , , , , , , , , , , , , , , , , , , ,		is Port Church, cedar house, across crk
**	Boyd Ward Rd	•	The second control of the second seco
Type of Worl	k: Complainta		
Material Use	٨.		Summer and an annual control of the
Customer Lir	ne Inspection	CONTRACTOR	Annual Control of the
Comments		extremely low water pressure	
Cur	rent System Information:	···	New Information:
Meter # 1:	19713241	Mete	r#1:
Meter # 2: Ra	dio 19713241	Mete	r#2: Radio
MXU#:	. Make the second property of the state of t	MXU	#:
Current Read	ling 4/20/2013 1177	Curr	ent Reading 0
Type of Mete	r: Badger	Туре	of Meter:
Year MFG:	2003	Year	MFG:
GPS - Longito	ude	GPS	- Latitude
Employee Sig	gnature(s):		Date Completed

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO #



Time Started		habblusidessmant*	Work Complete
Loc#		Master	Meter#
Date 7/1/2013		Account #	SEQ# 178
	HINKLE		Phone #
Address: P.O. B	• • •		
INEZ,	, KY 41224		supplementary of the second se
Location: U	nion Rd		
TURK	EY ROAD		
Type of Work: C	omplaints	,, ,, q.,,,,,,,,,,,,,,,,,,,,,,,,,	
•	fixed check	value	()one
Customer Line Ir	espection	# (A. # 60) 5 6 mm or 1 mm or 2 mm or)0'
Comments: no v	vater		
Curren	t System Information:	entered to the second of the s	New Information:
Meter#1:	70616457		Meter # 1:
Meter#2: Radio	70616457	Market Street Control of the Control	Meter#2: Radio
MXU #:	13152697	management of the control of the con	MXU#:
Current Reading	6/20/2013 158	Annual Annual Services (Spine)	Current Reading 0
Type of Meter:		gan a new diguello constitution in the	Type of Meter:
Year MFG:			Year MFG:
GPS - Longitude		·	GPS - Latitude
Employee Signat	ure(s): JU		Date Completed 7-1-13

387 East Main St., Sulte 140 Inez, KY 41224

WORK ORDER

WO#

	Aller Analysis representation	***************************************		
Time Starte	ed	Work Co	mplete	and the second s
Loc#	, pp. , to different tolerance			and the second s
Date 7/18/2013	Accour			
Name: People's Mark	et		Phone # (
Address: P.O.BOX	Annual Annua			
INEZ	, KY 41224]	- And the state of		
Location: Old Middlefork.	Behind court house.			, , , , , , , , , , , , , , , , , , , ,
Autorian Administration of Autorian Conference of the Conference o				
MIDDLEFORK				
Type of Work: Complaint	S N			A superior and in an entrange way appropriate the contraction and the or is a contraction to the
Type of Work: Complaint Material Used: X	S	Martin survey of the task to the survey of t	And the second s	A COMMISSION OF THE PARTY OF TH
	bs			
Material Used: \\ \frac{1}{1}X				Annual of the second of the se
Material Used: \(\sum_{\text{\tint{\text{\tint{\text{\tint{\text{\text{\text{\text{\text{\text{\text{\tint{\text{\tin}\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\texi}\text{\text{\text{\tex{\text{\texi{\text{\texi{\text{\texi{\texi{\texi\texi{\texit{\text{\text{\text{\texi{\texi{\texi{\texi{\texi{\texi}\text{\	left just before Eclipse drive	eway needs dug de	eper, runs across	
Material Used: \(\sum_{\text{\tint{\text{\tint{\text{\tint{\text{\text{\text{\text{\text{\text{\text{\tint{\text{\tin}\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\texi}\text{\text{\text{\tex{\text{\texi{\text{\texi{\text{\texi{\texi{\texi\texi{\texit{\text{\text{\text{\texi{\texi{\texi{\texi{\texi{\texi}\text{\	left just before Eclipse drive	eway needs dug de	eper, runs across	
Material Used: \(\sum \) \(\sum	left just before Eclipse drive	eway needs dug de	eper, runs across New Info	the road to this custome
Material Used: \(\sum \) \(\sum	left just before Eclipse drive	eway needs dug de Meter	eper, runs across New Info	the road to this custome
Material Used: \(\sum \) \(\sum	left just before Eclipse driven Information:	eway needs dug de Meter	eper, runs across New Info # 1: # 2: Radio	the road to this custome
Material Used: \(\sum \sum \cdot \c	left just before Eclipse driven Information:	eway needs dug de Meter Meter MXU #	eper, runs across New Info # 1: # 2: Radio	the road to this custome
Material Used: \(\sum \) \(\sum \) \(\sum \) Customer Line Inspection Comments: ditch line on Current System Meter # 1: 708407 Meter # 2: Radlo MXU #: Current Reading 6/20/20	left just before Eclipse driven Information: 36	eway needs dug de Meter Meter MXU # Currer	Peper, runs across New Info # 1: # 2: Radio	the road to this custome
Material Used: \(\sum \) \(\sum	left just before Eclipse driven Information: 36	eway needs dug de Meter Meter MXU # Currer	New Info # 1: # 2: Radio #: nt Reading	the road to this custome

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO #

Ti	me Started		Work Complete
Loc#		Master M	Neter#
Date 9/18/2013		Account #	SEQ# 175
Name: ROGE	R CASTLE		Phone #
Address: De	an Castle Br.		·
INEZ	, KY 41224]	455 \$2 600 000 000 000 000 000 000 000 000 00	· · · · · · · · · · · · · · · · · · ·
nin demandra vanoritri		<u> </u>	
	LE BRANCH RD	· · · · · · · · · · · · · · · · · · ·	
Type of Work: C	Complaints		
Material Used:	SU WAR		The second secon
Customer Line II			
Comments: cust	tomer had no water Last nig	ht and this morning	9
	t System Information:	mayanangagaa yasannaan	New Information:
Meter#1:	99691594	n ng gradinin ng dag	Meter # 1:
Meter # 2: Radio		·	Meter# 2: Radio
MXU#:	* * A A A A A A A A A A A A A A A A A A		MXU #:
Current Reading	8/20/2013 776	ru-u-upgymm ^r grouper	Current Reading 0
Type of Meter:	Badger		Type of Meter:
Year MFG:	1999	·**	Year MFG:
GPS - Longitude	0	gang sekilikan sekarangan ,	GPS - Latitude 0
Employee Signat	:ure(s): 15-15-65-	17	Date Completed 9-19-13

. 387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

т	ime Started	Wo	rk Complete
Loc#	water	Master Mete	er#
Dat 8/6/2013		Account #	SEQ# 158
Name: HOR	N'S BP	y to me Succ	Phone #
Address: P.O.B	BOX	•	Employee Clyde Stanley
INEZ	, KY 41224	, -	
Location:	· Mark Programme we		
diagn of a	ere of the second secon	لا ف ا ستن فضي	
	TE 1884/645 BY PASS		
Type of Work: (An arrangement of the company of the a	e e e e e e e e e e e e e e e e e e e	and the second s
Material Used: y	cePlasted L	ine	a so was a second white
Customer Line I	Inspection		e e e e e e e e e e e e e e e e e e e
	k is showing 80 lbs of press		•
			and the state of t
Curre	nt System Information:		New Information:
Meter # 1:	29934478	, ,	Лeter # 1:
Meter # 2: Redio	29934478	1	Meter#2: Redio
MXU#:	model action of many of the first control of the		MXU#:
Current Reading	7/20/2013 200	3 444	Current Reading 0
Type of Meter:	Badger		Type of Meter:
Year MFG:	2004		ear MFG:
GPS - Longitude	9 0		SPS - Latitude 0
garganin ng masa ataba - da	e en manuel e e e e e e e e e e e e e e e e e e	ک بانور با بسمه هم او	g or a consequence and commercially the control of
Employee Signa	nture(s): バルゴム・65~1	N	Date Completed 9-5-13

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER



WO#

	Time Started		Work Complete	
Loc#		Master N	fleter#	the of multiple continuous continuous and continuou
Date 10/18/20	013	Account#	SI	EQ# 36
Name: Cliff	ord Endicott		Phone	#
Address: PO		> > > > > > > > > > > > > > > > > > >	r.	
Lov	ely , KY 41231			
Location: Las	t house on left - gray		Section 1 and 1 an	
Cha	ipman Bottom			
Type of Work:	Complaints			ur v y (ugunny jazzak zwieniuminimininka administrative vyznymini) będo obniej obniej (obniej obniej obniej
				en de la companya de la constitución de la companya
Comments: h	as extremely low pressure			
Curr	ent System Information:		Ne	w Information:
Meter# 1:	74846474	, and a second community of the second community of th	Meter#1:	and a second side contains the contains the contains and
Meter # 2: Radi	o 74846474		Meter # 2: Radio	u ungaganggan panahan panahan na ang kanahan na ang
MXU#:	14993070	** ** was some appearance all Villagement .	MXU #:	anganina s in s constitutus manganingan dahinda manahan kalangan kandan kandan da Mandanist R
Current Readi	ng 9/20/2013 15		Current Reading _	0
Type of Meter:			Type of Meter:	
Year MFG:			Year MFG:	
GPS - Longitu	de	· · · · · · · · · · · · · · · · · · ·	GPS - Latitude	
Employee Sigr	nature(s):		Date Comple	ted 10-21-13

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

131000147

COMPLETED

	Time Started		Work Complete	no terrori assenzazione di sur qua relatificazioni e degli caratte.
Loc#		Master N	/leter#	
Date 10/14/20	013	Account #	SE	Q# 152
Name: Kirl	Memorial Church		Phone #	#
Address: PO	Вох			•
Inez	z, KY 41224		•	
	Lick, Sansom Drive, 1st driv	e on the right, meter	on right across from g	gravel drive that turns left
RT	3			
Type of Work:	Complaints		in free commercial and internalistics and internalistic control	entropy and the second
Material Used	Manager accounts of Manager at the contract of		2	
Customer Line	e Inspection		<u> </u>	
Comments: c	ustomer is complaining of ex	dremely low pressur	e/100 lbs	the state of the s
,	ent System Information:		New	v Information:
Meter # 1:	99691417	<u> </u>	Meter # 1:	er 2012 - William die der Wester Wester Voor voor de Berker voor de Berker voor de Verschaanske de Verschaansk
Meter # 2: Rad			Meter#2: Radio	
MXÚ #:	anno ang at a ang ang ang ang ang ang ang ang ang a		MXU#:	
Current Readi	ng 9/20/2013 37	o on a manage of management of the same	Current Reading	0
Type of Meter:	Badger	and the latter of the appropriate and the latter of the la	Type of Meter:	
Year MFG:	1999	· " .	Year MFG:	
GPS - Longitu	de		GPS - Latitude	
	and it was the second s	Action of the same	* * * * * * * * * * * * * * * * * * *	

Employee Signature(s):

Date Completed 15-13

387 East Main St., Suite 140 inez, KY 41224

WORK ORDER

••	WO #	130900	0207	
Tir	ne Started	V	Vork Complete	
				M2337 1200-2700-1000000-370-2
Date 9/27/2013		Account #	SEQ# 291	
Name: Wilma	Ball	▼ ************************************	Phone #	<u>)</u>
Address:	Riverfront Rd	V 1000 To 4 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5		
Belfry,	KY 41514		and the same of white the same \$	
Location: 3	Riverfront Rd Next to the c	hruch, doublewide t	railor	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	NA W. I. F.			
HUNII	YVILLE			
Type of Work: C	omplaints			THE PARTY OF THE P
Material Used:	,		Commence and a second commence of the second commence of the second commence and a second commence of the second c	
	omer said yard and gravel		raked Area	
Curren	t System Information:		New Information:	
Meter#1:	29934881	1999 8 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	Meter # 1:	······································
Meter#2: Radio	29934881	,	Meter # 2: Radio	
MXU#:	<u> </u>	·•	MXU #:	
Current Reading	9/20/2013 355	omicouis, incommune -	Current Reading 0	····
Type of Meter:	Badger	ordered and an analysis and an analysis and a second and a	Type of Meter:	······································
Year MFG:	2004	manufacture of the second of t	Year MFG:	
GPS - Longitude	0	annone and a second	GPS - Latitude 0	**************************************
* v voltamen managen se me en	ure(s):		Date Completed 1/2/27/	/13

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

	Time Started	orania and an analogo and an and	Work Cor	mplete
Loc#	ev o o o o o o o o o o o o o o o o o o o	Mast	er Meter#	
Date 11/4/20	13	Account #		SEQ# 470
Name: Chr	istopher Chapman			Phone #
Address: PO	Box	enganian and an analysis and a	t general de l'accommendate of facts and a secondate of the secondate of the secondate of the secondate of the	•
lne	z, KY 41224			
		s from Eden Eleme	ntary, beige/s	stone siding w/stone garage
	Madison Sarah Ln.			
Type of Work	: Complaints	v vuli minimususus ususus alla s. e.		
Material Used	: IX = sharkb	Itc.		
Customer Line				· ·
	WAR A COMPANY OF THE PROPERTY			os at box
	Atternety low pressure sin			33 41 50 1
Curi	rent System Information	:		New Information:
Meter # 1:	29935332	*	Meter #	* 1 :
	lio 29935332		Meter#	# 2: Radio
MXU#	i in signification in the second control of the second second second second second second second second second	Particular and State of the Sta	MXU#	groups a suckey and an announce and an announce of the section of
Current Readi	ng 10/20/2013 389	u	Curren	t Reading 0
Type of Meter	: Badger		Type of	f Meter:
Year MFG:	2004	and the second section of the section of the second section of the section of the second section of the section of th	Year M	FG:
GPS - Longitu	de ,	nethran va va valana ir natanosteno ingrana va hanang	GPS -	Latitude
Employee Sign	nature(s): JII-JS-TR		D	ate Completed 11-6-13

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	VAC	1311		
	Time Started	makes and to make the same of	Work Complete	
Loc#		Master	Meter #	and the second s
Date 11/7	7/2013	Account #	SEQ# 186	
Name:	CLAUDE MILLS		Dhono #	
Address:	P.O.BOX			
	BEAUTY , KY 41203			
Location:	7193 Beauty Rd brown trailer	on the left past Tom	my's Auto Sales	e and the second
		· 		
Type of V	Vork: Complaints		- PD)	
Material U	Jsed:			1.
Customer	Line Inspection			**************************************
Comment	ts: extremely low water pressur	e since leak was fix	ed 80 PST At box	
	Current System Information:	A	New Information:	
Meter#1	29934843	and the second second second second	Meter # 1:	CONTRACTOR OF THE STATE OF THE
Meter # 2	Radjo	- And the first of	Meter # 2: Radio	
MXU#:	Book Sand Sand Sand Sand Sand Sand Sand Sand	ng namunka kananananananananananan	MXU #:	
Current R	eading 10/20/2013 121		Current Reading 0	
Type of M	eter: Badger		Type of Meter:	
Year MFG):	angeriga di Nagata angeria	Year MFG:	a management of the territory
GPS - Loi	ngitude 0		GPS - Latitude 0	

Employee Signature(s):

Date Completed_

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#



Ti	ime Started		Work Complete	· · · · · · · · · · · · · · · · · · ·
Loc#		Master M	Neter#	
Date 5/30/2013		Account #		SEQ# 164
Name: JOYC	E DIALS	TO ANTHONY THE TOTAL PARTY OF TH	Phon	e#
Address: PO Bo	OX			
LOVE	LY , KY 41231			
Location: 3835 /black	hlack			
Type of Work: (Complaints		and the second s	
Material Used:	Fixed			
Customer Line I				
	nts mess in yard from cor			and
***************************************	nts mess in yard from con			· · · · · · · · · · · · · · · · · · ·
	nt System Information:			lew Information:
Vieter#1:	74846427		Meter # 1:	
Vieter#2: Radio	74846427		Meter # 2: Radio	***************************************
/IXU #:	14991359		MXU #:	
Current Reading	5/20/2013 9		Current Reading	0 .
Гуре of Meter:			Type of Meter:	
Year MFG:		in the second	Year MFG:	:
GPS - Longitude)	·	GPS - Latitude	
Employee Signa	ature(s):):P-(65√5"	J617	Date Comp	leted 5-51-15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

		WO #	1304001		
	Time Start	ed	· ·	ork Complete	
Loc#		Marie 4-96 Marie de la Porte de Marie de Marie (Marie 1990) (Marie 199	Master Met	er#	
Date 4/1	8/2013		Account#	, , S	EQ# 71
Name:	PILGRIM POS	ST OFFICE	Fax: 6	Phone	#
Address:	РО ВОХ				
	PILGRIM	, KY 41250			
Location:					
Material I	Nork: Complain	1			
	·	eft rock & unlevel g	ground around tap bo	k, cannot mow aro	und.
Commen	its: contractors	eft rock & unlevel g		k, cannot mow aro	und
Commen	contractors	eft rock & unlevel g	ground around tap bo	k, cannot mow aro	und.
Commen	Current System: 238648	eft rock & unlevel g	ground around tap bo	x, cannot mow aro	und.
Commen Meter # 1 Meter # 2	Current System: 238648	eft rock & unlevel g	ground around tap bo	x, cannot mow aro Ne Meter # 1:	und. w Information:
Commen Meter # 1 Meter # 2 MXU #:	Current System: 238648	eft rock & unlevel g m Information:	ground around tap bo	Neter # 2: Radio	und. w Information:
Commen Meter # 1 Meter # 2 MXU #: Current R	Current System 238648 Radio Reading 3/20/20	eft rock & unlevel g in Information: 105	ground around tap bo	Neter # 2: Radio	und. w Information:
Commen Meter # 1 Meter # 2 MXU #:	Current System 238648 Reading 3/20/20 Meter: Sensus	eft rock & unlevel g in Information: 105	ground around tap bo	Neter # 1: Meter # 2: Radio MXU #: Current Reading	und. w Information:

4860464T

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

130500005

	Time Started	Work Complete				
Loc#		Master Meter #				
Date <u>5/1/201</u>	3	Account #	SEQ# 539	orten magnigue.		
Name: Ch	ester Johnson Jr.		Phone #			
Address:	Boyd Ward Rd		•			
To	mahawk, KY 41262	,				
Location:	Boyd Ward Rd, Rockhouse 3	miles, 3rd house past Davis Por	t Church, cedar house, across crk			
<u></u>	⊰oyd Ward Rd					
Type of Work	c: Complaints	· · · · · · · · · · · · · · · · · · ·				
Material Use	# 150-FOOTOF#	1-4 TEE				
Customer Lir	ne Inspection	· · · · · · · · · · · · · · · · · · ·				
Comments: 0	customer is complaining of ex	remely low water pressure	and the contract of the contra			
Cui	rent System Information:		New Information:			
Meter#1:	19713241	Meter # 1:	See assessing to the second of			
Meter#2: Ra	dio 19713241	Meter # 2:	Radio			
MXU#:		MXU #:	and the state of t			
Current Read	ling 4/20/2013 1177	Current R	eading 0			
Type of Mete	r: Badger	Type of M	eter:			
Year MFG:	2003	Year MFG				
GPS - Longit	ude	GPS - Lat	itude			
		• ·				

Employee Signature(s): 18-GS-TS-TT-TG

Date Completed 5-30-13

37-38-598-W 08-49-4-WW

For all

387 East Main St., Suite 140 inez, KY 41224

WORK ORDER

WO# 130500106

VV W	1000010	A 17 - Ab - W LF Cu ' Th		
Time Started	Work Complete			
Loc#		#		
Date 5/9/2013		•		
Name: Junior Hunt		Phone # -		
Address: Little Rockcastle Rd				
4,				
right over the bank	m, up 2032, across mo	untain, grey double wide w/black shutters on the		
Little Rockcastle Rd		,		
Type of Work: Complaints		,		
Material Used:				
Customer Line Inspection	0			
		leak was fixed.		
Current System Information:		New Information:		
Meter # 1:	Me	eter # 1:		
Vieter # 2: Radio	Me	eter#2: Radio		
MXU#:		KU #:		
Current Reading0	Cu	rrent Reading 0		
Type of Meter:	Ty _!	pe of Meter:		
fear MFG:	·	ar MFG:		
GPS - Longitude	GF	PS - Latitude		
_				

Date Completed

Employee Signature(s):

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

130500132



Time Started		Work Complete				
Loc#		Maste	r Meter#			
Date 5/15	5/2013	Account #	SEQ	# 352		
Name:	ELMER DIALS		Phone #			
Address:	lackburn & Dials Rd					
	TOMAHAWK , KY 4126	2	and the state of t			
Location:			Damage was done last yea	ar when water line was		
	ROUTE 40 WEST					
Material (Jsed: Fixed					
	Current System Information:			eformation:		
Meter # 1 Meter # 2						

MXU#:	randing 0		***************************************	0		
	eading 0					
Type of M		· · · · · · · · · · · · · · · · · · ·		<u> </u>		
Year MFC	1311,000 000	*				
GPS - Lo	ngitude .		GPS - Latitude			

Employee Signature(s): 15-15-15-65-16-17 Date Completed 5-22-13

387 East Main St., Sulte 140 Inez. KY 41224

WORK ORDER



WO#

130300215

		* * *	Work Complete			
Loc#	an e e e e e e e e e e e e e e e e e e e	Master Meter #	; ; ;			
Date 3/28/2013	Ac	count #	SEQ# 22			
Name: RUSSEI	Ĺ STEPP	Pho	ne#			
Address: PO BOX			3			
LOVELY	, KY 41231	man, do so de lates de la augus à la grand confincie de la				
Location: Bruce S	t Lovely, 292 & 1714 Intersect	tion, right on 1714, 1st brick house	e on the left			
« »	s SV T A SEWA . W		And remainded and an arrange of the second s			
	*** *** *** *** *** *** *** *** *** **	Maine	Andrew Control of the			
ype of Work: Co	A CONTRACTOR OF THE STATE OF TH	itali dessitas siristamanjamaineme es saineide, ma memo nemograpuitatidade.	and a party of a section of the sect			
Material Head:	- 6" Meter Box R	iser + 1-3" Met	an Roy Riser			
Customer Line Ins	pection	and the second second in the second s	andangangang na mangar san san san san dan dahiri san in dahari Salahar Salahar Salahar Salahar Salahar Salahar			
	pection s boxes raised/ he has two box	xes/	and any angular parameter of the second seco			
Comments: needs	" Tar", a a sur o a Cumana amadaning gani manini		New Information:			
Current	s boxes raised/ he has two box					
Current Meter # 1:	System Information:					
Current Weter # 1: 7	System Information:	Meter # 1:				
Current Weter # 1: 7 Weter # 2: Radio 7	Spokes raised/ he has two box System Information: 72918851 72918851	Meter # 1: Meter # 2: Radio MXU #: Current Reading	New Information:			
Current Weter # 1: 7 Weter # 2: Radio 7 WXU #: 1	Spokes raised/ he has two box System Information: 72918851 72918851	Meter # 1: Meter # 2: Radio MXU #:	New Information:			
Current Meter # 1: 7	Spokes raised/ he has two box System Information: 72918851 72918851	Meter # 1: Meter # 2: Radio MXU #: Current Reading	New Information:			
Current Meter # 1: 7 Meter # 2: Radio 7 MXU #: 1 Current Reading 3	Spokes raised/ he has two box System Information: 72918851 72918851	Meter # 1: Meter # 2: Radio MXU #: Current Reading Type of Meter:	New Information:			
Current Meter # 1: 7 Meter # 2: Radio 7 MXU #: 1 Current Reading 3 Type of Meter: Year MFG:	Spokes raised/ he has two box System Information: 72918851 72918851	Meter # 1: Meter # 2: Radio MXU #: Current Reading Type of Meter: Year MFG:	New Information:			

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

130500009 WO#

e di		AND THE REAL PROPERTY.	N. A.		
R. B.	and a	E	磨圆	ij.	

Time Started	V	Vork Complete
Loc#	Master M	eter#
Date 5/2/2013	Account#	SEQ#
Name: Kenneth Berry		Phone #
Address: P.O. Box		
Lovely, KY 41231		· · · · · · · · · · · · · · · · · · ·
Location: Dogwood DR, 2nd trailor on		
Material Used: Customer Line Inspection Comments: customer has no pressure sir	nce the set, box is filli	
Current System Information:		New Information:
Meter # 1:	n com escrecialistation	Meter # 1:
Meter # 2: Radio		Meter # 2: Radio
MXU#:		MXU #:
Current Reading 0	- datasaga resonance	Current Reading 0
Type of Meter:		Type of Meter:
Year MFG:		Year MFG:
GPS - Longitude		GPS - Latitude
	_	K-3-13

Employee Signature(s):

Date Completed

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 140600171

,	Time Started	Wo	rk Complete	war war and the same of the sa
Loc#		Master Met	er#	
Date 6/23/20	014	Account #	SEQ#	‡ <u>224</u>
Name: No	orma McCoy		Phone #	Mary the second
Address:	Meathouse Rd			
Pi	lgrim, KY 41250		non a rest and	
Location:	Meathouse Rd, turn right	@ 1439 4 or 5 miles or	n right grey trailer on h	ill
. M	EATHOUSE			
Type of Wor	k: Complaints	· · · · · · · · · · · · · · · · · · ·		to a second seco
Material Use	•			
Customer Li	ine Inspection:			
Cu	ırrent System Information:	.	New In	formation:
Meter# 1:	29934888		Meter # 1:	
Meter # 2: R	adlo 29934888		Meter # 2: Radio	
MXU#:			MXU #:	
Current Rea	ding 5/20/2014 529	·	Current Reading	0
Type of Met	er: Badger			
Year MFG:	2004	•	Year.MFG:	
GPS - Longi	itude		GPS - Latitude	<i>*</i>
Employee S	ignature(s): TH, CS		Date Completed	1:07-1/1

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

		WO#	131000143	**************************************
	Time Started		Work Comple	lete
Loc#	S. S		Master Meter#	
Date 10/	11/2013	Acco	unt#	SEQ# 101
Name:	MARY STANLEY			Phone # ()
Address:	PO Box			
	WARFIELD , KY	41267		
Location:	84 Stanley Dr			
	COLLINS CREEK		è	
Type of V	Nork: Complaints	D	all of Roel for	in a lest
Material	Used: <u>Chack</u>	and he	3d 28 #	Lix a lest
Custome	r Line Inspection		gaggya. Ji kaminimistan erri siin nimbinda kabinimininga olda siin. 🕠 middilasi	
Commen	its: extremely low pressure		, and the second	AND
, ,	Current System Informa	tion:	######################################	New Information:
Meter#1	: 70616608	and the second s	Meter # 1:	
Meter # 2	: Radio		Meter # 2:	Radio
MXU#:	13154928		MXU#:	
Current F	Reading 9/20/2013 273		Current Re	eading 0
Type of N	Neter:		Type of Me	leter:
Year MF0	3 :	and the state of t	Year MFG	3:
GPS - Lo	ngitude	****	GPS - Lati	titude

Date Completed 10-88-13

Employee Signature(s): C5, 115, 45

387 East Main St., Suite 140 Inez, KY 41224

	WO	# 14060018	32
т	ime Started	Wor	k Complete
Loc#			
Date 6/25/2014		Account#	SEQ# 297
Name: SAMI	JEL JUDE		Phone #
Address:	Pigeon Roost Rd		
PILG	RIM , KY 41250		
Location:	√igeon Roost Rd, 1 3/4 m	illes up at he mouth of Ha	ale Br in a brown brick house
			•
di antiantinantinantinantinantina			
Type of Work: (Complaints		
Material Head:		1	
Customer Line I		12 las	red
••	,		
Comments: too	much air in lines, needs f	lushed	,
Curre	nt System Information:		New Information:
Meter # 1:	97728674	N	leter # 1:
Meter#2: Radio	•		leter#2: Radio
MXU #:			IXU #:
Current Reading	5/20/2014 850		urrent Reading 0
Type of Meter:	Badger	T	ype of Meter:
Year MFG:	1997	Y	ear MFG:
GPS - Longitude	9 0	G	PS - Latitude 0
	-511		1 0/11
Employee Signa	ture(s):	www.	Date Completed 6-619

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	N	/O#	140600)211		
	Time Started		V	Vork Complete		and the second s
Loc#	A minimum and the second secon	out to the control of	Master M			
Date 6/2	7/2014	Ac	count#		SEQ# 224	
Name:	Norma McCoy			Pho	ne# (
Address:			· ·		loyee Justin	Scott
	Pilgrim, KY 41250					
Location:	Vleathouse Rd, turn r					
Type of V	Work: Complaints				17	
Material i	Used:		44			
Custome	r Line Inspection					
Commen	its: nothing but air in lines				·	
· .	Current System Information	n:		1	New Informat	tion:
Meter # 1			<u> </u>	Meter#1:	****	
Meter#2	2: Radio	<u> </u>		Meter # 2: Radio		
MXU#:	* grandersogggerendenheiden kan deutschaften er og eine de helde			MXU#:	A	
Current F	Reading 0	· · · · · · · · · · · · · · · · · · ·	·····	Current Reading		0
Type of N	Meter:			Type of Meter:	-	- The contract of the contract
Year MF	G:	**************************************		Year MFG:		
GPS - Lo	ngitude			GPS - Latitude	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	***

Employee Signature(s):

Date Completed 6-27-14

387 East Main St., Suite 140 Inez, KY 41224

	# Ow	1400UV10U
Time Started	we was accepted to a second of the property of	Work Comple

	I me Started		vvork Complete	: .
Loc#	variable and the state of the s	Master N	fleter#	***
Date 6/17/201	4	Account #	SEQ# 184	
Name: Jaso	n Robinson		Phone #	
Address:	Meathouse Rd		<u> </u>	
PILO	SRIM , KY 41250		no sòn s'air a m' sermer	
Location:	Meathouse Rd, beside I	LeAnna Church, brick h	ouse	parameters and alternate frames to be set to the space of principles in the second as a second
ALE - 1 - 100			e en	
	Meathouse Rd	na Transc viz anaminina potez ana sea deser 111 an cen	WAS many pain) as a referring the angles of the community pain believed that and the community of the commu	· · · · · · · · · · · · · · · · · · ·
Type of Work:	Complaints			na a anggangaga na na na na na naga na
Material Hood		7	.0	
Material Used:		- (DO		
Customer Line	Inspection:	- Williams		
Comments: no	water /	jot water		
Curre	ent System Information		New Information	on:
Meter#1:	47824008		Meter # 1:	· · · · · · · · · · · · · · · · · · ·
Meter#2: Radk	47824008	n na pagana ang kanana ang kananang ang kananang ang kananang ang kananang ang kananang ang kananang ang kanan	Meter # 2: Radio	
MXU#:	,		MXU #:	
Current Readir	ng 5/20/2014 853	•	Current Reading ()
Type of Meter:	Sensus	 	Type of Meter:	
Year MFG:	1993		Year MFG:	
GPS - Longitud	de O		GPS - Latitude 0	
Employee Sign	satura(s):	<u>۲</u>	Date Completed n = 1	9-14

Martin County Water Dist :: 1

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO #	140600040	-	
Time Started	Work	Complete	
parameters and the second seco	Master Meter #	į.	
2014	Account#	SEQ#	357
Betty Lopez		Phone #	
P.O. Box	-		
Inez, Ky 41224			
ields Traile Ct. Tomahawk. 2n	d trailer (white camper)	on right.	
Fields Trailer Ctl)	· · · · · · · · · · · · · · · · · · ·
Vork: Complaints	600/		***
Used:			
r Line Inspection			
ts: no water / Checked	poesburees be	ox had 80) psi
Current System Information:		New Info	rmation:
: 16721822	Met	er#1:	· · · · · · · · · · · · · · · · · · ·
: Radio 16721822	Met	er#2: Radio	and the second s
ny paritaminin'i mananananana mandrimanana kaominina di Missi di di di Missi di Missi di di Missi di M	MXI	J#:	And the second contract of the second contrac
teading 5/20/2014 343	Cur	rent Reading	0
fleter: Badger	Тур	e of Meter:	
3: 2000	Yea	r MFG:	
ngitude	GP\$	S - Latitude	in the state of th
	Time Started 2014 Betty Lopez P.O. Box Inez, Ky 41224 lelds Traile Ct. Tomahawk. 2n Fields Trailer Ctl Vork: Complaints Jsed: r Line Inspection ts: no water / Circked Current System Information: : 16721822 : Radio 16721822 deading 5/20/2014 343 Reter: Badger S: 2000	Time Started Work of Master Meter # 2014 Account # Betty Lopez P.O. Box Inez, Ky 41224 ields Traile Ct. Tomahawk. 2nd trailer (white camper) Fields Trailer Ctl Vork: Complaints Jsed: r Line Inspection ts: no water / Checked for Solvenes body Current System Information: : 16721822 Meter ieading 5/20/2014 343 Current System Information: Iteleer: Badger Type Signature Account #	Time Started Work Complete Master Meter # 2014 Account # SEQ # Betty Lopez Phone # P.O. Box Inez, Ky 41224 ields Traile Ct. Tomahawk 2nd trailer (white camper) on right. Fields Trailer Ctl Vork: Complaints Jsed: r Line Inspection ts: no water / Checked Complaints Current System Information: Rew Info Reading 5/20/2014 343 Current Reading MXU #: Reading 5/20/2014 343 Current Reading Inter: Badger Type of Meter: Year MFG:

Date Completed

Employee Signature(s):

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

•	WO #	1407002	258
Ti	me Started	We	ork Complete
Loc#		84484-4	
Date 7/29/2014		Account#	SEQ# 492
Name: ROGE	ER SPENCE		Phone #
Address: P.O. E	Roy		Employee Rainho
TOM	AHAWK , KY 41262		and the Community of th
Location: C	Prville Rd 3rd house on left.w		
ORVI	LLE ROAD	سنبند	
Type of Work: (Complaints		
Material Used:			
Customer Line I Comments: ext	remely low pressure	RVPT	is being the Adjusted
Curre	nt System Information:		New Information:
Meter # 1:	19408808	hanna ann an a	Meter # 1:
Meter#2: Redio	19408808		Meter # 2: Radio
MXU #:	. 1800-1800-1800-1800-1800-1800-1800-1800	ggedrommon and the	MXU#:
Current Reading	7/20/2014 246		Current Reading 0
Type of Meter:	Badger .		Type of Meter:
Year MFG:	2003	·	Year MFG:
GPS - Longitude	0	 :	GPS - Latitude 0

Employee Signature(s):

Date Completed Peace 7-31-14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#	140700199	nonemator vi
Time Started	Work Comp	lete
Loc#	Master Meter #	
Date 7/23/2014	Account #	SEQ# 221
Name: Tina Ward		Phone #
Address: BO Poy		Employee Justin Scott
Inez, KY 41224		
Location: Spence Branch, 19 Tina Ln, app 1/2	2 mile on right in beige trailer	
		1,23
MILO		
Type of Work: Complaints		z.
Material Used: Customer Line Inspection:	ted)	
Comments: water has a stale odor, has been	like this for a few days. So d	oes father next door.
Current System Information:		New Information:
Meter # 1: 29935324	Meter # 1	*
Meter # 2: Radio	Meter # 2	: Radio
MXU #:	MXU #:	3
Current Reading 6/20/2014 398		eading 0
Type of Meter: Badger	Type of M	leter:

Employee Signature(s):

Badger

2004

Type of Meter:

GPS - Longitude

Year MFG:

Date Completed

Year MFG:

GPS - Latitude

387 East Main St., Suite 140 Inez, KY 41224

wo #	740/0	<u>U175</u>	
Time Started		Work Complete	
Loc#	Master M	fleter#	
Date 7/21/2014	Account#	SEQ# 165	
Name: Will & Shana Newsome		Phone #	
Address: PO Box		Employee Justin	Scott
WARFIELD , KY 41267		· :	
Location: 77 Hode Rd, on the right side of 7	「&D hardware nurs	ery lot, grey raised house	
HODE	- Andrews		
Type of Work: Complaints			
Material Used:	NB		
Customer Line Inspection			
Comments: very low water pressue	65	PSI	··
Current System Information:	***************************************	New Information	tion:
Meter # 1: 70616551		Meter#1:	
,Meter # 2: Redlo 70616551		Meter#2: Radio	
MXU#: 13136511	u mas mandinada e	MXU #:	
Current Reading 6/20/2014 205		Current Reading	0
Type of Meter:	**************************************	Type of Meter:	
Year MFG:		Year MFG:	
GPS - Longitude		GPS - Latitude	:
Employee Signature(s):		Date Completed 7	24-14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO #	140/0	10081	
Time	Started		Work Complete	
Loc#	•			·
Date 7/8/2014		Account#		SEQ# 818
Name: CHESTER	R GARTIN JR		Phon	ne# <u>()</u>
Address: \ Hode	o Dal		Empl	loyee Rainbo
WARFIEL	D 107 44007			
Type of Work: Composite Material Used: Customer Line Inspec	plaints	051 at b	0 Y	
٠,				
_	stem information:	15	Meter # 1:	lew information:
		, .	Meter # 2: Radio	
		······································	MXU #:	
**************************************	0/2014 811		Current Reading	0
	nsus		Type of Meter:	QA - Marika and a
•	93		Year MFG:	
	···		GPS - Latitude	0.

Employee Signature(s): LU15 m

Date Completed 7/14/14

Martin County Water District 387 East Main St., Suite 140

Inez, KY 41224

WORK ORDER

	WO #	1407001	70	
Tir	ne Started	Wo	rk Complete	and the same of th
Loc#		Master Mete	er#	
Date 7/18/2014	· · · · · · · · · · · · · · · · · · ·	Account#		SEQ# 33
Name: James	R. Shepherd		Phor	ne#
Address: P.O.Bo				loyee Rainbo
INEZ	, KY 41224]			
			y Ward.	
Type of Work: C				The state of the s
Material Used:	all osher.	screen in	sport	-up
Customer Line I	nspection Weter	is flacus	ry the	eyha wot
Comments: no v	vater Drøse;			
Curren	t System Information:	h. Address)	lew Information:
Meter#1:	70840668	·	Neter#1:	
Meter # 2: Radio	70840668	ľ	Meter#2: Redio	No. of the Control of
MXU#:			ИXU #:	
Current Reading	6/20/2014 159	·	Current Reading	0
Type of Meter:	Sensus	•	Type of Meter:	
Year MFG:	2012	The control of the co	rear MFG:	
GPS - Longitude	0		3PS - Latitude	0

Employee Signature(s):___

Date Completed 7

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	W	U# 1701'	<i>)</i> 0026	
Т	ime Started		Work Complete	and the same of th
Loc#		Master I	Meter#	
Date <u>7/7/2014</u>		Account #	SEQ#	± 224
		,	Phone # (
Address:	Meathouse Rd		Employee	Rainbo
Pilgri	m, KY 41250			
Location:	3 Meathouse Rd, turn rig		s on right grey trailer on h	
MEA	THOUSE	•		
		·		
Type of Work:	Complaints	4		
MEA	Complaints	ster veca	lase	
Type of Work:	Complaints W.			, ,
Type of Work: Material Used: Customer Line	Complaints U Inspection:		lose	
Type of Work: Material Used: Customer Line Comments: no	Complaints U Inspection:			
Type of Work: Material Used: Customer Line Comments: no	Complaints OU 2 Inspection: water		New In	
Type of Work: Material Used: Customer Line Comments: no Curre	Inspection: water 29934888	:	New In Meter # 1:	formation:
Type of Work: Material Used: Customer Line Comments: no Curre Meter # 1:	Inspection: water 129934888 29934888		New In Meter # 1: Meter # 2: Radio	formation:
Type of Work: Material Used: Customer Line Comments: no Curre Meter # 1: Meter # 2: Radio MXU #:	Inspection: water 129934888 29934888	•	New In Meter # 1: Meter # 2: Radio	formation:
Type of Work: Material Used: Customer Line Comments: no Curre Weter # 1: Meter # 2: Radio MXU #: Current Reading	Inspection: water 29934888 29934888	•	New In Meter # 1: Meter # 2: Radlo MXU #:	formation:
Type of Work: Material Used: Customer Line Comments: no Curre Meter # 1: Meter # 2: Radio MXU #:	Complaints U. 2 Inspection: water nt System Information: 29934888 29934888	•	New In Meter # 1: Meter # 2: Radio MXU #: Current Reading	formation:

Employee Signature(s):___

Date Completed 7-

387 East Main St., Suite 140 Inez, KY 41224

	WO #	140700018	
Ti	me Started	Work C	complete
Loc#		• •	
Date 7/3/2014		Account #	
Name: John I	Moore		Phone#
	leathouse Rd		Employee Rainbo
	n , KY 41250		• • • • •
Location:	Meathouse Rd Below Lean	na Church, 1st Drive, Grey	Trailor
Wolf (400		
Type of Work: 0	Complaints		
			1
	-11	<i>T.</i>	All I
Customer Line I	nspection: <u>Alla</u>	W lelas .	ary -
Comments: ext	remely low water pressure		, ,
Curre	nt System Information:	And the second s	New Information:
Vleter # 1:	47823969	Mete	er#1:
Vieter#2: Radio		Mata	er#2: Radio
VIXU #:	**************************************	BAY!!	
Current Reading	6/20/2014 581	• •	ent Reading 0
Type of Meter:	Sensus	Туре	e of Meter:
Year MFG:	1993	Year	MFG:
GPS - Longitude	0		- Latitude 0
Employee Signa	0 5		Date Completed 7-11-14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO#	140700031		
Ti	me Started	Work (Complete	
Loc#	• •	Master Meter #		
Date 7/7/2014	000 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	Account #	SEQ# 123	
Name: Georg	e Spence		Phone # (0	
Address: P.O. E	Box _	4	Employee Clyde Stanle	<u>y</u>
lnez, l	KY 41224		TOTALISM.	
drive o	on left, meter is @ bottom of	4-31	2mile up Mudfork stay left, black	
148 M Type of Work: C	Complaints	Done		
Material Used:				
Customer Line I	nspection			
Comments: no v				
	nt System Information:		New Information:	
/leter # 1:	12760367	Met	er#1:	The second secon
/leter#2: Radio	12760367	Met	er#2: Radio	
/IXU #:		MXI	J#:	
Current Reading	6/20/2014 49	Cur	rent Reading 0	***************************************
Type of Meter:	Hersey	Тур	e of Meter:	
Year MFG:	2012	Yea	r MFG:	All the second s
3PS - Longitude		GP8	S - Latitude	
Employee Signal	ture(s): TH, CS		Date Completed 7-8	14

387 East Mein St., Suite 140 Inez, KY 41224

WORK ORDER

WO #

140700113

	Time Started	w	ork Complete	
Loc#		Master Me	ter#	
Date 7/11/2	2014	Account #	SEQ# 106	
Name: M	IADV OTANI EV	<u></u>	Phone # (
Address: P	O Pay		Employee Kyle Sammons	***************************************
V	VARFIELD , KY 41267		· ·	
_ 	COLLINS CREEK			
		•		
Material Us	ed:			
			<u> </u>	
Comments	no water / Controct	ors tergot	5 turn Value book	2M
C	urrent System Information:	4	New Information:	
Meter#1:	70616608		Meter # 1:	
Meter # 2:			Meter # 2: Redio	*
MXU#:	13154928		MXU #:	
Current Rea	ading 6/20/2014 283		Current Reading 0	
Type of Me	ter:		Type of Meter:	
Year MFG:			Year MFG:	
GPS - Long	itude		GPS - Latitude	and the second s
Employee S	Signature(s): KS S S		Date Completed	

387 East Main St., Suite 140 Inez, KY 41224

	WO #	1407	00106
Ti	me Started	Work Complete	
Loc#	and the second s	Master	Meter #
Date 7/10/2014		Account #	SEQ# 184
Name: Jason	Robinson		Phone #
Address:	Meathouse Rd		
	RIM , KY 41250		
Location:	Meathouse Rd, beside LeAn	,	house
9006 1			
Type of Work: C	Complaints		
Material Used:	they know	the so	conson got selod RRS
	nspection:		· <i>U</i> .
Comments: low			
Currer	nt System Information:		New Information:
Meter # 1:	47824008		Meter # 1:
Meter # 2: Radio	47824008		Meter # 2: Radio
MXU #:	A SAME OF THE SAME	regionage to collection during the collection and the	MXU #:
Current Reading	6/20/2014 857	·····	Current Reading 0
Type of Meter:	Sensus		Type of Meter:
Year MFG:	1993		Year MFG:
GPS - Longitude			GPS - Latitude 0
Employee Signá	ture(s): BJ,	-	Date Completed 7-10-14

Martin County Water District 387 East Main St., Sulte 140

Inez, KY 41224

WORK ORDER

	WO#	140700108	unuminuje,
,	Time Started	Work Com	nplete
Loc#		Master Meter #	
Date 7/10/2	2014	Account#	SEQ# 142
Name: <u>H</u>	IENRY JUDE		Phone #
Address:	North Wolf Creek		Employee Rainbo
Ī	OVELY , KY 41231		
Location:			ard is nearest neighbor
Material Us	Line Inspection:		Leelel
······································			
Meter # 1:	74846459	Meter#	
Meter # 2:	Radio 74846459		2: Radlo
MXU#:	14991931	MXU#:	
Current Re	ading 6/20/2014 42	Current	Reading 0
Type of Me	ter:	Type of	Meter:
Year MFG:	Noncommunication and control of the	Year M	FG:
GDS - Lond	nitude.	GPS-I	atitude

Employee Signature(s):_ Date Completed

387 East Main St., Suite 140 Inez, KY 41224

	WO#	140	0700011
	Time Started		Work Complete
Loc#		Mast	er Meter #
Date 7/1/	/2014		
Name:	Forest Fitch		Dhono # /
Address:	P.O. Box		Employee John Mills
	Inez , KY 41224		
Location:	luckleberry Ridge Brown brid	ck house on lef	<u>t </u>
	łuckleberry Ridge		
Type of V	Vork: Complaints	^	
Material I	Used:		
Custome	r Line Inspection		
Commen	ts: no water, check Otto Brown pur	np station	Done " electrical issues
	Current System Information:		New Information:
Meter#1	: 63860615		Meter # 1:
Meter # 2	: Radio 63860615		Meter # 2: Radio
	13155594		MXU #:
Current R	Reading 6/20/2014 463	***	Current Reading 0
Type of M	feter:	School Control Control Control	Type of Meter:
Year MFG	3:		Year MFG:
GPS - Loi	ngitude		GPS - Latitude
Employee	Signature(s):	· · · · · · · · · · · · · · · · · · ·	Date Completed 1/1/

M...tin County Water Distr t

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

130800177



Time Started		Work Complete	and the state of t
Loc#		Master Meter #	
Date 8/20	/2013	Account #	SEQ # 260
Name:	STERLING MARCUM	·	one #
Address:		· · · · · · · · · · · · · · · · · · ·	
	1 OLUGA LOV 419301	airs qui	
	ROUTE 3 NORTH Side Wa	ouse on the right past Friendship Chi Act of Nix + 16 + 16 X + 10 11 6	House of the truck
Type of W	/ork: Complaints		
	Jsed:		
	s: says water is foamy and has c		
	Current System Information:		New Information:
Meter#1:	47823998	Meter # 1:	
Meter # 2:	Radio 47823998	Meter # 2: Radi	0
MXU #:	· Address of the second of the	MXU #:	
Current R	eading 7/20/2013 456	Current Readi	ng <u>0</u>
Type of M	eter: Sensus	Type of Meter	and the same of th
Year MFG	i: 1993	Year MFG:	
GPS - Lor	ngitude 0	GPS - Latitude	0
Employee	Signature(s): 5	Date Co.	mpleted 8-21-13



387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Type of Meter:

GPS - Longitude

Year MFG:

130800168

COMPLETE

-			Mark O seedlets		
	Time Started		Work Complete	- And the state of	
Loc#		Master	Meter#		
Date <u>8/10</u>	6/2013	Account#	and the second s	SEQ# 834	
Name:	Thomas & Diana Thompson		Phor	ne#	
Address:	hompson Lane				
	I Inc. 44004				
Location:	Thompson Ln Turkey, past	fire dept., 2nd hous	se past new Nazarene	Church, tan w/green roof	
	292	C			
Type of V	Work: Complaints				
Material	Used:		ONE		
Custome	er Line Inspection +old Cu	<u> </u>	theck reogn	lator	
Commer	nts: customer has had low water	pressure for at lea	st 2 months.	over 100165 of psi	
	Current System Information:			New Information:	
Meter#1	1:		Meter # 1:		
Meter#2			Meter#2: Radio		
MXU#:		oglessa galla linguago de que escalara su comerce	MXU#:	A STATE OF THE STA	
Current F	Reading 0		Current Reading	0	

Employee Signature(s): JW Date Completed 8-26-13

Type of Meter:

GPS - Latitude

Year MFG:

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER



WO#

130600152

Time Started		no en	Work Complete		
Loc#	2	Master Meter #			
Date 6/19/201	13	Account#	SEQ# 393		
Name: DOI	NALD HINKLE		Phone #		
Address: P.O	BOY		•		
INE	Z , KY 41224]				
ocation: Res	sevoir Rd. 2nd driveway.				
Lic	KBRANCH RD.				
Type of Work:	7,	*			
	eak across the road from h	nis house,	New Information:		
Cu rı //eter # 1:	rent System Information: 70616419	•	Na_t 44 d.		
neter#1. Neter#2: Rad	And the second s		Meter # 1:		
AXU#:	40450005		MXU #:		
current Readi	ng 5/20/2013 183		Current Reading 0		
ype of Meter			Type of Meter:		
ear MFG:			Year MFG:		
3PS - Longitu	de	A constitution of the cons	GPS - Latitude		
Employee Sig	nature(s): 18-15-65-	16-N	Date Completed 8-1-13		

387 East Main St., Suite 140 Inez. KY 41224

WORK ORDER



130800013 WO # Work Complete Time Started Loc# Master Meter # SEQ# 179 Account # Date 8/2/2013 Phone # (JEFF HINKLE Name: Address: P.O. BOX , KY 41224 INEZ, Location: 109 Union Rd TURKEY ROAD Type of Work: Complaints Material Used: Customer Line Inspection No leak tourch Comments: high bill New Information: **Current System Information:** Meter#1: Meter # 1: 70616457 Meter # 2: Radio 70616457 Meter # 2: Radio MXU #: MXU#: 13152697 Current Reading 7/20/2013 169 Current Reading 0 Type of Meter. Type of Meter: Year MFG: Year MFG: GPS - Longitude GPS - Latitude

Employee Signature(s): U Date Completed 8-5-13

Inartin County Water Disurct

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

130800110

COMPLETE

Time Started		p grammanamentermenter entre c > 5 h min 445	Work Complete		
		or and			
Loc#	· ▼ • • • • • • • • • • • • • • • • • •	Master	Master Meter #		
Dat 8/8/2013	Company of a marriage attacher or over the a a a a a a a a a a a a a a a a a a a	Account#	SE	EQ# 178	
Name: KARE	N MARCUM	· Www. gr. p. commonstrate and analysis and gr. c.	Phone	#	
Address: PO BC	DX	المراجع والمستشكرة فعيلكم المسام	Employ	vee Kyle Sammons	
BEAU	TY , KY 41203	3 xw 38700 973 322222222222222222222222222222222222	A)		
Location Bi	ig Elk Rd. 1 mile up Big	Elk Rd on right, besid	de Black barn w/sign th	at says "Buck Creek Scooter"	
, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	and the second s	A Section of the Sect	ا ما المستقدم المستق	14 18 4 manual and a second se	
Comments no w		neter, please stop by K	aren's house (white w/	black fence)	
	t System Information			v Information:	
ieter#1:	29934697	mananan ilahumpa kan p man	Meter#1:	and the second s	
/leter#2: Radio	29934697	and a description of the control of	Meter # 2: Radio	Landing Control of the Control of th	
1XU#:			MXU #:	and the second secretary and the second seco	
Current Reading	7/20/2013 876		Current Reading	O Samuel	
ype of Meter:	Badger	n Vic valenteetile are topy occuminates in para as	Type of Meter:		
ear MFG:	2004		Year MFG:	minerajus, vinda raman minerajum minerajum kan dir saya da da pa da	
			000 1-66-4- 0		
PS - Longitude	<u>0</u>		GPS - Latitude 0	errene di branchimeriore ecos ecos prominente di constitución de la co	

387 East Main St., Suite 140 Inez, KY 41224

WO:	# 140800265	and almost and
Time Started	Work Co	mplete
Loc#	4.0 4 B.0 - 4 Ll	
Date 8/25/2014	Account #	SEQ# 101
Name: LEE SUMPTER		Phone#
Address D.O.BOV		Employee Clyde Stanley
INEZ, , KY 41224	And the state of t	
Location: Blackbum Ln on Blacklog; to	ailor on right	
)
ROUTE 40 EAST	Done	
Tura at Marky Complaints		
Type of Work: Complaints		1
Material Used: 301.6 05 aras	5 seed, and 4	bail of Strawle
Customer Line Inspection: Comments: property behind Johnny Stace		
Current System Information:		New Information:
Meter # 1: 29935408	Meter	#1:
Meter # 2: Radio		#2: Radio
MXU #:	MXU	# :
Current Reading 7/20/2014 301	Curre	nt Reading 0
Type of Meter: Badger	Туре	of Meter:
Year MFG: 2004	Year I	MFG:
GPS - Longitude 0	GPS -	Latitude 0
5 :		
Employee Signature(s): TH, S		Date Completed 8-25-14

387 East Main St., Suite 140 Inez, KY 41224

	W	O# 1408	00268	
Time Started		·····	Work Complete	
Loc#		Master	Meter#	
Date 8/2	5/2014	Account#	SEC	Q# <u>126</u>
Name:	George Spence		Phone #	
Address:	P.O. Box		Employe	e Rainbo
	Inez, KY 41224		Management of the control of the con	
Location:	/lckinney Rd Mudfork R drive on left, meter is @ botto	om of hill		k stay left, blacktop hill 2nd
Type of V	ickinney Dr Vork: Complaints		·	
Material I	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX		*	
	r Line Inspection: 3/4	1	issue	
	Current System Information			Information:
Meter#1	• • • • • • • • • • • • • • • • • • •		Meter#1:	
Meter # 2	Radio	Annual of the Annual	Meter # 2: Radlo	
MXU #:		·	MXU#:	A CAMPAGE AND A
Current R	Reading 0		Current Reading	0
Type of M	fleter:	description of the second of t	Type of Meter:	•
Year MF0	3 :	and the second s	Year MFG:	
GPS - Lo	ngitude	**************************************	GPS - Latitude	
Employee	e Signature(s)	ZORIZA	Date Complete	8-25-19

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO#	14080025	<u> </u>
Time Started		Work	Complete
Loc#			
Date 8/20)/2014	Account#	SEQ# 400
Name:	Helen MILLS		Phone #
Address:	D O DOV		Employee Troy Horn
	INEZ , KY 41224]		
Location:	71 Helen Mills Rd, white house TURKEY ROAD	Dove	
Type of W	/ork: Complaints		
Material U	ised:	-	
	Line Inspection: s: customer has had low pressure		, POOD
· ·	Current System Information:	•	New Information:
Meter # 1:	70616398	M	eter # 1:
Meter # 2:	Radlo	Me	eter#2: Radio
MXU#:	13152700		XU #:
	eading 7/20/2014 222	-	urrent Reading 0
Type of M	eter:	Ту	pe of Meter:
Year MFG	:	Ye	ear MFG:
GPS - Lon	gitude	<u>-</u>	PS - Latitude
Employee	Signature(s): TH, C C	and the second s	Date Completed 8- 25-14

Employee Signature(s):

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	# OW	140800	10716	
Time Starte	ed	.	ork Complete	
		Master Me	eter#	
				SEQ # 268
LILLIAN STAC	Υ		Phone	* #
PO BOX .			Emplo	oyee Justin Scott
LOVELY	, KY 41231		*	
Himmlerville Ro	d, on left, Yellow ho	ouse w/brown trim		
Vork: Complain	s			
Jsed: r Line Inspection	n:	ushed)	*
ts: complaints o	of water smelling ba	ad		
Current Syster	n Information:		N	ew Information:
: 299349	38		Meter#1:	
Radio			Meter # 2: Radio	
-			MXU#:	
Reading 7/20/20	14 245		Current Reading	. 0
Meter: Badger		······	Type of Meter:	
3:			Year MFG:	
	LILLIAN STACY PO BOX: LOVELY Himmlerville Ro Vork: Complaint Jsed: r Line Inspection ts: complaints of Current System : 299349 : Radio	Time Started 2014 LILLIAN STACY PO BOX: LOVELY , KY 41231 Himmlerville Rd, on left, Yellow he Work: Complaints Jsed: r Line Inspection: ts: complaints of water smelling be Current System Information: : 29934938 : Radio Reading 7/20/2014 245 Meter: Badger	Master Me 2014 Account # LILLIAN STACY PO BOX: LOVELY , KY 41231 Himmlerville Rd, on left, Yellow house w/brown trim Vork: Complaints Jsed: r Line Inspection: ts: complaints of water smelling bad Current System Information: : 29934938 : Radlo Reading 7/20/2014 245 Reter: Badger	Time Started Work Complete Master Meter # 2014 Account # EILLIAN STACY Phone PO BOX: Emplo LOVELY , KY 41231 Himmlerville Rd, on left, Yellow house w/brown trim Vork: Complaints Jsed: r Line Inspection: ts: complaints of water smelling bad Current System Information: 129934938 Meter # 1: Meter # 2: Radio MXU #: Reading 7/20/2014 245 Current Reading Type of Meter: Badger Type of Meter:

Employee Signature(s): Justin Betscoff Date Completed 8-4-14

GPS - Longitude 0

GPS - Latitude

Employee Signature(s)

wartin County Water District

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO# 1408	00017
Time Started		Work Complete
Loc#	Master	Meter#
Date 8/4/2014	Account#	SEQ# 462
Name: Penny Todd		Phone #
Address: PO Box		Employee Justin Scott
Inez, KY 41224		
Location: Davis Cemete	ery Rd 1st house on right past Oot	en, Grey in color, Church of Christ in front of house
STAFFORD		
Type of Work: Complaints		
Material Used:	Plaste	
Customer Line Inspection		
Comments: foul odor since	low water pressure last week, line	es may need flushed
Current System I	information:	New Information:
Meter # 1: 67012673		Meter # 1:
Meter # 2: Redio	distance in the second	Meter#2: Radio
MXU#:	reconstruction of the second contract of the	MXU#:
Current Reading 7/20/2014	137	Current Reading 0
Type of Meter: Sensus	and the second superior and the second superior and the second superior and the second superior and the second	Type of Meter:
Year MFG: 2006		Year MFG:
GPS - Longitude 0		GPS - Latitude 0


Date Completed

Wartin County Water Disact

387 East Main St., Suite 140 Inez, KY 41224

	WO #	140800123
ima Startad		Mark Complet

Time Started		Work Complete		
Loc#		Master Me	eter#	
Date 8/11/	/2014	Account #	SEQ# 24	
Name:	ARNOLD MURPHY		Phone #	
Address:	Hewitt Ave			
e, ,	LOVELY , KY 41231		·	
Location:	Hewitt Ave, 1st house on left,	beige 2-story house		
		v = 100000000000000000000000000000000000		
Type of W	ork: Complaints		9015, at box	
Material U	sed:			
Customer	Line Inspection:			
Comments	s: low pressure			
(Current System Information:		New Information:	
Meter # 1:	99459379	Managa yana sa mana sa	Meter # 1:	
Meter#2:	Radio 99459379		Meter # 2: Radio	
MXU#:	y		MXU#:	
Current Re	eading 7/20/2014 678	Market Copie and Anna Agentic Administration (Assert Copies and Assert Copies and As	Current Reading 0	
Type of Me	eter: Badger		Type of Meter:	
Year MFG	: 1999	·	Year MFG:	
GPS - Lon	gitude 0		GPS - Latitude 0	
Employee	Signature(s): CH-JM		Date Completed 8-12-14	



387 East Main St., Suite 140 Inez, KY 41224

WO#	140800145

	Time Started	Work (Work Complete		
Loc#	and the second s	Master Meter #	Master Meter #		
Date 8/13/2014 Ad		Account # 47	SEQ# 82		
Name: ED	DIE HINKLE		Phone # ()		
Address: P.C	D.BOX	,	Employee Rainbo		
BE			_		
Location:	Bone Holw 2031.Lower Po	olar.Bone Hollow.1st trailer	on right at top of hill.Grey & white.		
Type of Work	c: Flush Line	Dane	w. f		
Material Used	t: Flush	lin 8-	13-14		
	ne Inspection				
Current System Information:		and the second s	New Information:		
Meter # 1:	97728662	Met	ter#1:		
Meter#2: Ra	dio	· Met	ter#2: Radio		
MXU #:		A/X	U#:		
Current Read	ling 7/20/2014 794	Cur	rent Reading 0		
Type of Mete	r: Badger	Тур	pe of Meter:		
Year MFG:	1997	Yes	ar MFG:		
GPS - Longito	ude 0	GP.	S - Latitude 0		
Employee Sig	gnature(s): RJ	· · · · · · · · · · · · · · · · · · ·	Date Completed 8 - 13 - 14		

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

140800092

T	me Started		Work Complete Master Meter #		
Loc#	The second secon	Master			
Date 8/6/2014		Account #	SE	SEQ# 224	
Name: Norma	a McCoy		Phone #	(
Address: Vleathouse Rd			Employe	e Rainbo	
Pilgrin	m, KY 41250				
Location: :	Meathouse Rd, turn ri	ght @ 1439 4 or 5 mil	es on right grey traller or	n hill	
MEAT	THOUSE				
Type of Work:	Complaints	•		-	
Material Used:	· · · · · · · · · · · · · · · · · · ·				······································
Customer Line I	Inspection:				
Comments: no	water / Tep	rived brea			
Current System Information:		1:	New	Information:	
Meter # 1:	29934888	ne en e	Meter # 1:		
Meter # 2: Radio	29934888	an and a supplied to the suppl	Meter#2: Radio		
MXU#:			MXU #:		
Current Reading	7/20/2014 536		Current Reading	0	
Type of Meter:	Badger		Type of Meter:		
Year MFG:	2004	and the second s	Year MFG:		
GPS - Longitude	9		GPS - Latitude		Managagana arikatik dagan
Employee Signa	ature(s):		Date Complete	ed 90/4	

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#		14050013	
	Time Started	Work	k Complete
Loc#_		Master Meter	#
Date 5/19	/2014	Account#	SEQ # 63
Name:	FRANK BALDRIDGE		Phone# ()
Address:			
	INEZ , KY 41224]	, ,	
Location:	RIGHT SIDE 133 Haney PI		
	•••••••••••••••••••••••••••••••••••••••		
Type of W	/ork: Complaints		
	Line Inspections: driveway has been destroyed s		ast year.
	Current System Information:	Ad	New Information:
Meter # 1:	98003195	. IVI	leter # 1:
Meter # 2:	Radio	nagadar naknya narona Saurda	eter#2: Radio
MXU#:	Anna barrer de la companya della companya della companya de la companya della com	** ***********************************	XU #:
Current R	eading 4/20/2014 774	- 	urrent Reading 0
Type of M	eter: Badger		ype of Meter:
Year MFG	1998	Y	ear MFG:
GPS - Lor	ngitude 0	G.	PS - Latitude 0
Employee	Signature(s): JM	\$	Date Completed 8/20/14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO #	140800076	and the second section of the section of t
	Time Started	Work C	Complete
Loc#		Master Meter #	
Date 8/5/2	2014	Account#	SEQ# 35
	0/ EN DI E //NO		Phone # (3
			Employee Justin Scott
	INEZ , KY 41224]		
Location:	131 Blevins Ln		
	MIDDLEFORK RD.		
Type of W	Vork: Complaints		
Material L	Jsed:		
	Line Inspection:		· · · · · · · · · · · · · · · · · · ·
	ts: musty smell with greasy texture		July to fix it
	Current System Information:		New Information:
Meter#1	29213201	Mete	er#1:
Meter#2	Radio		er#2: Radlo
MXU#:		MXI	J #:
Current R	eading 7/20/2014 757	Cum	ent Reading 0
Type of M	leter. Badger	Туре	e of Meter:
Year MFG	9: 2004	Year	r MFG:
GPS - Loi	ngitude 0	GPS	S - Latitude 0
Employee	Signature(s):		Date Completed \$ -6-14

Employee Signature(s):

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO #	1409002	15
	Time Started	Wo	rk Complete
Loc#	The second secon	Master Mete	er#
Date 9/2	6/2014	Account#	SEQ# 221
Name:	LON CRUM		Phone # ()
Address:	P.O. Box		Employee Troy Horn
	Inez , KY 41224		
Location:	81 Guyton Rd, Little Lick Br, top o	f hill last house @ top	
	GUYTON RD	**************************************	
Type of \	Work: Complaints		
Material	Used:		
Custome	er Line Inspection		
Commen	nts: very low water pressure	and it	come back up
	Current System Information:		New Information:
Meter#1	l:		Neter # 1:
Meter # 2	2: Radio		Neter # 2: Radio
MXU#:		<u> </u>	/IXU #:
Current F	Reading 0		Current Reading 0
Type of N	Meter:		ype of Meter:
Year MF	G:	<u> </u>	/ear MFG:
GPS - Lo	ongitude :	(GPS - Latitude

Employee Signature(s): CS JS J

Date Completed 9-26-19

Martin County Water District 387 East Main St., Suite 140

WORK ORDER

	WO#	1409000	003		
	Time Started	W	ork Complete		
Loc#		Master Me	ter#	un ausbruck der gestellt der gest	
Date 9/2/	2014	Account#	(SEQ# 218	
Name:	JAMES HOWELL		Phone	e#	Manager - Barry A. Astronomy Manager (1997)
Address:	P.O.BOX		Empl	oyee Troy Hom	
	INEZ , KY 41224				
Location:	37 James Howell Dr Left Fork	~.			
Material (LITTLE LICK BRANCH Vork: Complaints Used:	Done			
	r Line Inspection	1 had 30	psiat	box	
	Current System Information:	,, ,	N	lew Information:	
Meter#1	: 94261366	······································	Meter#1:		
Meter # 2		TOTAL STATE OF THE	Meter#2: Radio		
MXU#:	· And the second		MXU#:		
Current F	Reading 8/20/2014 1326	and the second s	Current Reading	0	
Type of N	Meter: Badger		Type of Meter:		
Year MF	G: <u>1994</u>	·	Year MFG:		
GPS - La	ongitude 0	i	GPS - Latitude	0	Andrew discount of the same

Employee Signature(s): TH, CS

Date Completed 9-12-14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

140900090 WO# Work Complete Time Started Master Meter # SEQ# Account # Date 9/4/2014 Phone # Name: Ashley Tiller Employee Rainbo Address: Location: mouth of Setser Br, Debord. Wants locking lid for pit. Type of Work: Complaints Material Used: Customer Line Inspection New Information: **Current System Information:** Meter # 1: Meter#1: Meter # 2: Radio Meter # 2: Radio MXU#: MXU#: Current Reading 0 **Current Reading** Type of Meter: Type of Meter: Year MFG: Year MFG: **GPS - Latitude** GPS - Longitude

Date Completed Q

Martin County Water District 387 East Main St., Suite 140

Inez, KY 41224

WORK ORDER

WO#	140900086			
	*******************	* A .m' (mm x .m.		

Time Started		No. of the state o	Work Complete
Loc#	and a supplication of the	Master M	leter#
Date 9/5/2014	inimas kunummasimasimasimasimasi (ze s 4 gg v v - f s ec 201 ; r)) jų	Account#	SEQ# 270
Name: Edna	Daniel	A4 WWW	Phone #
Address: PO B	lox		Employee Justin Scott
Inez	, KY 41224	· · · · · · · · · · · · · · · · · · ·	·
the le	Rocky Top, Past Ratliff To	own, road turns right be	etween two brick houses, go up the hill, 1st place on
Old F		nd vid e variat e <mark>eaglid</mark> a _a e n realization en	and the same of th
Type of Work:	Complaints	es promi quanti que en cara de la propria de	and the first of t
Material Used:	سه کرت در ۱۰۰ مستخدست در سید در در در در مستخدم در سید می در		The state of the s
Customer Line	Inspection:	Had 305	RSI At boy
Comments: this	s customer and her neigh		
Curre	ent System Information:	and the state of t	New Information:
Meter # 1:	29935126	mana and and and and and and and and and	Meter # 1:
Meter#2: Radio	magama s. ps. 1727 say agraedymodymodymodymod box - 475 - 47 h history		Meter # 2: Radio
MXU#:	The second secon	a was a surrounding of make	MXU #:
Current Readin	g 8/20/2014 421	* *	Current Reading 0
Type of Meter:	Badger	A Co. description of the contraction of the contrac	Type of Meter:
Year MFG:	2004	***************************************	Year MFG:
GPS - Longitud	le 0	به ارسوس و العمل بدر المعالم بدر المعالم بدر المعالم بدر المعالم بدر المعالم بدرا المعالم بدرا المعالم بدرا المعا	GPS - Latitude 0
	ature(s):		Date Completed 9-5-/4

387 East Main St., Suite 140 inez, KY 41224

WORK ORDER

	WO #	140800118	· Annual ·
Ti	ime Started	Work Comple	ete
Loc#		Master Meter#	
Date 8/8/2014	-	Account #	SEQ# 137
Name: MARK	(HOWARD		Phone #
Address: P.O.B	OX		Employee Clyde Stanley
Inez,	I/V 4400.4		
ROUT	ΓΕ 1884 MILO Complaints		
Customer Line I	nspection: Since Lucius	e Stap up an au ak was worked on.	u side
Currei	nt System Information:	And the state of t	New Information:
Meter # 1:	19667271	Meter # 1:	29934572
Meter # 2: Radio	\$ 111111911791179179797979797979797979797	Meter # 2:	Radio
MXU#:		MXU #:	Manager 11
Current Reading	7/20/2014 809	Current Re	eading \$960
Type of Meter:	Badger	Type of Mo	eter: Budge
Year MFG:	2003	Year MFG	
GPS - Longitude	0	GPS - Lati	tude 0

Employee Signature(s): TB, JR, RJ

Date Completed 9-8-14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WC	# 141000231	er vogsteren og en
Time Started	Work (Complete
Loc#		E
Date 10/27/2014	~	SEQ# 107
Name: ERVIN STEPP		Phone #
Address: Collins Crk		Employee Rainbo
WARFIELD , KY 4126	7	
Type of Work: Complaints		
Material Used:		
Customer Line Inspection:	ir ein at li	re Deened tu Mething
Current System Information:		New Information:
Meter # 1: 16151170	Met	ter#1:
Meter # 2: Radio 16151170	Mel	er#2: Redio
MXU #:	MX	U #:
Current Reading 10/20/2014 1041	Cur	rrent Reading0
Type of Meter: Badger	Тур	e of Meter:
Year MFG: 2000	Yea	ar MFG:
GPS - Longitude <u>-82.42864</u>	GP:	S - Latitude 37.83200
Employee Signature(s): RJ_		Date Completed 15-26-14

Employee Signature(s): 85-

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO #	141000142	<u></u>
Ti	me Started	Work Complet	e
Loc#	and an arrange of the second s	Master Meter #	
Date 10/15/2014	4	Account# 11 -	SEQ# 9
Name: DORO	OTHY FARRA		Phone # '^
Address: P.O.B	ΛΥ		Employee Corey Hill
WAR			
Location:	Riverfront Rd		
•			
LOVE	LY		;
Type of Work: C	Complaints (M)	ve)	
Material Used:			
Customer Line I	nspection:	<u> </u>	
•	ck water meter to see if it is I	toci broage between	et in look of down least or
	it System Information:		New Information:
Meter # 1:	97728665	Meter # 1:	
Meter # 2: Radio		Meter # 2: F	Radio 'c
MXU#:		MXU #:	
Current Reading	9/20/2014 495	Current Rea	ding
Type of Meter:	Badger	Type of Met	
Year MFG:	1997	Year MFG:	
GPS - Longitude	•	GPS - Latitu	de <u>0</u>
Employee Signat	ure(s)CH, TM	Date C	completed

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

141100140

			•	***			
	Time Started		V	ork Complete			
Loc#			Master Meter #				
Date 11/2	24/2014		Account #		SEQ#	223	
Name:	TIM MCCOY #2			P			
Address:	Beauty Rd	•		E	mployee	Troy Horn	
	BEAUTY						
Location:			, .				
Type of V	Work: Complaints						
Material I	Used: er Line Inspection:		3 1 1	de)).	•	`
		owing his service I	ines apart				
	Current System				New In	formation:	
Meter#1	1: 1636869	6		Meter#1:		· · · · · · · · · · · · · · · · · · ·	

	· /		• •
Meter # 2: Radio	16368696	Meter # 2: Radio	
MXU#:		MXU#:	
Current Reading	11/20/2014 429	Current Reading	<u> </u>
Type of Meter:	Badger	Type of Meter:	
Year MFG:	2000	Year MFG:	****
GPS - Longitude	0	GPS - Latitude	0
			and the second s

Employee Signature(s): \$\frac{1}{5} \frac{1}{5}

Date Completed 11-24-14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

Employee Signature(s):

		WO #	141100	0088
	Tim	e Started	V	Vork Complete
Loc#			Master M	leter#
Date 11/	13/2014	***************************************	Account #	SEQ# 226
Name:	LON CI	RUM		Phone # ()
Address:	P.O. Bo	X	· · :	Employee Justin Scott
	Inez	, KY 41224	<u></u>	
Location:	GUYTO		f hill last house @	top of hill, red
Type of V	7	^ F	s leaks	Has insider now
Custome	r Line In	spection:		<u> </u>
Commen	its: <u>custo</u>	omer has no water	(10	
······································	Current	System Information:		New Information:
Meter#1	i:	29935077		Meter # 1:
Meter#2	2: Radio	29935077		Meter # 2: Radio
MXU#:				MXU #:
Current F	Reading	10/20/2014 610	*	Current Reading 0
Type of N	/leter:	Badger	* ***	Type of Meter:
Year MF	G:	2004		Year MFG:
GPS - Lo	ngitude	0		GPS - Latitude 0

Date Completed /1-25-14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Time Started		Wo	Work Complete		
Loc#	40-40-40-40-40-40-40-40-40-40-40-40-40-4	Master Mete	er#		
Date <u>11/18/201</u>	14	Account#	SEQ# 27		
Name: Caro	l Stevens		Phone #		
Address:					
	ly, Ky 41230				
Location:	Long Br, new white home	e on the right, less than 1/2	2 mile to next rd		
292	• •				
Type of Work:	Complaints				
Material Used:	I was	eir ir le	il what we was		
Customer Line	Inspection: Drette	in it affer	· Low.		
Comments: wa	ater is milky white since	ast night, check for proble	ems		
Curr	ent System Information	1:	New Information:		
Meter # 1:	29934536		Meter # 1:		
Meter # 2: Radi	lo		Meter # 2: Radio		
MXU#:	·		MXU #:		
Current Readi	ng 10/20/2014 534		Current Reading 0		
Type of Meter:	: Badger		Type of Meter:		
Year MFG:	2004	_ 	Year MFG:		
GPS - Longitu	de	•	GPS - Latitude		
Employee Sign	nature(s): RJ		Date Completed 11-20-14		

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO #	140900237	nga ambandan tanang (199
	Time Started	Work Co	omplete
Loc#		Master Meter #	
Date 9/29	9/2014	Account #	SEQ# 66
Name:	FRANK BALDRIDGE		Phone # (`
Address:	P.O.BOX		Employee John Mills
	INEZ , KY 41224]		
Location:	Haney Pl, last house, green h	iouse;2	
Time of M	HANEY PLACE	C.	1
Type of V	Vork: Complaints		
Material l	Jsed:		
Custome	r Line Inspection:	- Anna Carlotte Carlo	
	ts: driveway has been destroyed s		
	Current System Information:		New Information:
Meter#1	98003195	Mete	er#1:
Meter # 2	2: Radio	Mete	er#2: Radio
MXU #:		MXU	J#:
Current F	Reading 9/20/2014 792	Curr	ent Reading 0
Type of N	Meter: Badger	Туре	e of Meter:
Year MF	G: 1998	Year	r MFG:
GPS - Lo	ongitude 0	GPS	S - Latitude 0

Hinkles Blackspains

Employee Signature(s):

Date Completed 179414

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO #	141000176	4
Time Started	Work C	Complete
Loc#		
Date 10/21/2014	Account #	SEQ#
Name: Maggie Collins		Phone #
Address:		Employee Clyde Stanley
Inez, KY 41224		
Type of Work: Complaints	FIV	
		i i i i i i i i i i i i i i i i i i i
Material Used: Level aut t	the Raugh D	pat
Customer Line Inspection:		
Comments: Still Mees	d ordrain	Pipe
Current System Information:		New Information:
Meter # 1:	Met	ter#1:
Meter # 2: Redio	Met	ter#2: Radio
MXU #:	MX	ù#:
Current Reading 0	Cur	rrent Reading 0
Type of Meter:	Тур	pe of Meter:
Year MFG:	Yea	ar MFG:
GPS - Longitude		S - Latitude

Date Completed 1230 - 14

Henry Dept.

Employee Signature(s):

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

140100432

Tir	me Started	₩.	ork Complete	and the state of t
Loc#	Supposition to provide the contraction of the contr	Master Me	ter#	on the space of the state of th
Dat 1/31/2014		Account #	- van v	SEQ# 14
Name: MARIE	LOWE	and the same of th		ne# (
Address: S.	Wolf Creek Rd		Emn	loyee Rainbo
PILGF	IM KV 41250			
Location: Wolf o	creek past miners in between	garbage dump and	i martin co freew	ill baptist
Type of Work: C	omplaints	Done		
Comments: no v	1	The President	,	was view Thattach
moter	with how on the	Their	Decle	was given though
Curren	t System Information:		h	lew Information:
Meter # 1:	96130852		Meter#1:	were a second and the
Meter # 2: Radio	- ab a surroy. At a same and space a	······································	Meter#2: Radio	- Andrews
MXU#:	ge	7	MXU #:	ARAMON ARAM STATE OF THE STATE
Current Reading	1/20/2014 718	and the desire of the	Current Reading	0
Type of Meter:	Badger		Type of Meter:	30 services on a color of a consequent service of a consequence of a consequence of a consequence of a color o
Year MFG:	1996	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	Year MFG:	an annual and a state of the st
GPS - Longitude			GPS - Latitude	0
and an angular to the second of the second 				1

Employee Signature(s): K, J, Date Completed $\frac{1-30-14}{}$

387 East Main St., Sulte 140 Inez, KY 41224

WORK ORDER

	WO #	140	100006	
	Time Started		Work Complete	to a transitivistic consider entertrinoment intermental and the second
Loc#		-		£
Date 1/7/2	2014			SEQ# 212
Name:	LON CRUM		Ph	none# ()
Address:	P.O. Box			
	Inez , KY 41224			
Location:		f hill last house	@ top of hill, red	
• .	GUYTON RD			
Type of W	ork: Complaints		\mathcal{O}	
Material U	sed: WATER Press:	urc is	0000	
	Line Inspection		-,0	
	s: low water pressure	NC 11/2 1/2 1/2 1/2 1/2 1/2 1/2 1/2 1/2 1/		·
,	Current System Information:		The second secon	New Information:
Meter#1:		oooooooooooooooooooooooooooooooooooooo	Meter # 1:	
Meter # 2:	Radio 29935077	·	Meter # 2: Radi	io
MXU #:			MXU#:	Management of Apparent source on all the second supplications and the second source of the API
Current Re	eading 12/20/2013 575	payaban managaming managaming managaming managaming managaming managaming managaming managaming managaming mana	Current Readi	ng <u> </u>
Type of Me	eter: Badger		Type of Meter:	yes ,
Year MFG	2004		Year MFG:	destinante de s istema e de constante de constante de constante de constante de constante de constante de constante
GPS - Lon			GPS - Latitude	9 0
	λ.			

Date Completed 1-15-14

Employee Signature(s): 18-65-75-7

Martin County Water District 387 East Main St., Suite 140

Inez, KY 41224

WORK ORDER

		WO#	140100222	
	Time Started	and a second	Work Complete	BO Subari
Loc#	inalitationina in a sum on a sumply. Summy the analysis of the sum	,	Master Meter#	austrius es s'assacres des
Dat 1/10/2	014	Account	#	SEQ# 144
	ethy Jude		Phon	e#
Address:	Calf Crk Rd		Empl	oyee Tony Blevins
Ir	nez, Ky 41224		ngaranananananananananananananananananan	
Location:		se at the forks of ti		
Type of Wo	4 Calf Crk Rd rk: Complaints ed:			
Comments:	water pressure comes	and goes after they	changed meter out	Stated At 100 PSI
	urrent System Informat		N	ew Information:
Meter#1:	29802064		Meter # 1:	See the second s
Meter#2: r	Radio 29802064		Meter # 2: Radio	
,MXU #:	* AANGOO OO OO OO		MXU #:	
Current Rea	ading 12/20/2013 828		Current Reading	0
Type of Met	er: Badger	and the second s	Type of Meter:	
Year MFG:	2004		Year MFG:	
GPS - Long	itudę	:	GPS - Latitude	::•
	-9.			,

Employee Signature(s):

Date Completed ___

387 East Main St., Sulte 140 Inez, KY 41224

WORK ORDER

WO#

140100234

Work Complete Time Started Master Meter # Loc# SEQ # 104 Dat 1/13/2014 Account # Phone # NORMA SLONE Employee Jason W. Address: P.O.BOX \ INEZ, , KY 41224 Location 19 Hill Vw on Camp Br, 1/3 of a mile on left, white house w/screened in front porch and green roof. CAMP BRANCH Type of Work: Complaints Material Used: Customer Line Inspection Comments low pressure/

Current System Information:			New Information:
Meter#1:	99085893	Meter # 1:	· · · · · · · · · · · · · · · · · · ·
Meter#2: Radio	NATE OF PROPERTY AND ADMINISTRATION OF THE PROPERTY OF THE PRO	Meter # 2: Radio	Was and demonstrated and the second of
MXU#:	AND THE RESIDENCE OF THE PROPERTY OF THE PROPE	MXU#:	
Current Reading	12/20/2013 443	Current Reading	0
Type of Meter:	Badger	Type of Meter.	and the second s
Year MFG:	1999	Year MFG:	
GPS - Longitude	0	GPS - Latitude	0
r.			

Employee Signature(s): 55/

Name:

Date Completed 1 - 15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	A			.54
٠,	ıv	u	8	ж

Ti	me Started	ne na hakun	Work Complete
Loc#		Master	Meter#
Date 1/10/2014		Account #	SEQ# 271
Name: ALBEI	RT SMITH		Phone #
Address: P.O.B			
INEZ	, KY 41224		······································
Location:		was a superior of the superior	
J CAS	SADY BR.		
Type of Work; C	complaints	i.	
	•		
	water pressure for 2 days		
Currer	nt System Information:		New Information:
vleter # 1:	97354363		Meter # 1:
Meter#2: Radio			Meter # 2: Radio
ΛΙΧU #:		The management of the state of	MXU #:
Current Reading	12/20/2013 836	· Carana and an annual and an annual and an	Current Reading 0
Type of Meter:	Badger	aland - to and the contribution to the contribution of the contrib	Type of Meter:
rear MFG:	1997	uar kuun ei rin ein hallandingagaan de menjuar	Year MFG:
GPS - Longitude	0	de de succession Court Verlandeschaum.	GPS - Latitude 0
	turo(s): Tahi Mill		Date Completed 1/12/19

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO#	140100220	our manufacture and the second	
Time Started		Work	Complete	
Loc#	and the state of t	544 94.4 <i>1</i>		
Dat 1/10/	2014	Account #	SEQ # 102	
Name: N	MARY STANLEY		Phone # ()	
Address: F	PO Boy		Employee Jason W.	
<u></u>	WARFIELD , KY 41267			
	84 Stanley Dr			
 (COLLINS CREEK	ga ugu a samu a samunga samung		
Type of Wo	ork: Complaints	and the second s		
Material Us	sed:	<u> </u>	The second case and the second	
Customer l	Line Inspection			
	: has had low water pressure for	days so has neighbors a	at bottom of hill, 35 PST 44	į
<u></u>	urrent System Information:		New Information:	:
Meter#1:	70616608	Met	ter#1:	
Meter # 2:	Radio	Met	er#2: Radio	
MXU #:	13154928	MX	U#:	
Current Re	ading 12/20/2013 273	Cur	rent Reading 0	
Type of Me			e of Meter:	
Year MFG:		Yea	ar MFG:	
GPS - Long	gitude	GPS	S - Latitude	-
Employee	Signature(s): Sycc	and any or a "automore" and any or any	Date Completed \-\3-\2	

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO #

Time Started		Work	Complete		
Loc#		Master Meter	Master Meter #		
Date 1/10/2014	erstammatik store traduksia men V.A. sin erstakka menensi erstamma erstamma	Account #	SEQ #	# 452	
Name: Rober	t Nichols #3		Phone #	The state of the s	
Address: PO Bo	<u> </u>	and the second s			
inez, i	KY 41224	And the state of t			
Location: Middle	e Fork, last railer on rigl	nt, greyish tan in color 308	Holden Hills	· · · · · · · · · · · · · · · · · · ·	
3 - 11 d a a a a a a a a a a a a a a a a a	(, , , ,) years to San , , , , , , , , , , , , , , , , , , ,				
308 H	olden Hills	and the second s	•		
Type of Work: C	Complaints		3	and the second s	
Material Used:	hannessen, e ser esse Assessed e en se especiales en fort hannessen	T 1811 1		anna propagation de la manage de la manage de la compagation de la compagation de la compagation de la compaga	
Customer Line I		J 51			
Comments: no	water H w	safer wait	······································		
Currer	nt System Information			formation:	
Meter # 1:	70616589	Me	eter # 1:		
Meter # 2: Radio	70616589	Me	eter#2: Radio		
MXU#:	13154916	M	ΚU # :	and the second s	
Current Reading	12/20/2013 183	Cu	rrent Reading	0	
Type of Meter:	A Distriction of the Control of the	Ту	pe of Meter:		
Year MFG:	Alter an incommendation and the control of the cont	Ye	ar MFG:	A A A BELLOTTE AND A STATE OF THE STATE OF T	
GPS - Longitude		GI	PS - Latitude		
Employee Signal	ture(s):		Date Completed	1-14-14	

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

140200265	WO#	
Work Complete	In AAAMA, AAAMAA, aaaaaaaaaaaaaaaaaaaaaaaa	Time Started
Master Meter #		

Loc#			Mast	er Meter#	· · · · · · · · · · · · · · · · · · ·		· works
Date 2/11/2014	1		Account #		SEQ#	103	anna ann an a
Name: MAR	Y STANLEY				Phone # (_)	
Address: PO B	gox ,						
WAR	RFIELD	KY 41267		anganagala a r A anno anno anno anno anno anno anno ann			
Location: 84 St		•		www.mar. 25		•	
COLI	LINS CREEK					_	
Type of Work:	Complaints						manual and the second s
	< \ .	1. 63	سينسره ي	<i>~</i>			
viaterial Used:	3NG	WHZ_	TACI	C11,			ether who is a second with
				CN,			
Customer Line	Inspection	o water					
Customer Line	Inspection	o water					
Customer Line Comments: cus	Inspection stomer has no nt System In	o water			New Info		
Customer Line Comments: cus Curre Teter # 1:	Inspection stomer has no nt System In 70616608	o water			New Info	ormation:	
Customer Line Comments: cus Curre Meter # 1: Meter # 2: Radio	Inspection stomer has no nt System In 70616608	o water formation:		Meter#1:	New Info	ormation:	
Customer Line Comments: cus Curre Meter # 1: Meter # 2: Radio	Inspection stomer has no nt System in 70616608	o water formation:		Meter # 1: Meter # 2: MXU #:	New Info	ormation:	
Customer Line Comments: cus Curre Meter # 1: Meter # 2: Radio MXU #: Current Reading	Inspection stomer has no nt System In 70616608 13154928 g 1/20/2014	o water formation:		Meter # 1: Meter # 2: MXU #:	New Info	ormation:	
Customer Line Comments: cus	Inspection stomer has no nt System in 70616608 13154928 g 1/20/2014	o water formation:		Meter # 1: Meter # 2: MXU #: Current Re	New Info	ormation:	

Employee Signature(s): 13-65-114 Date Completed 2-12-14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Time Started	Work Complete
Loc#	
Dat 2/11/2014	Account# SEQ# 234
Name: JEAN COPELAND	Phone # /
Address: Jean Copeland Ln	Employee Justin Scott
TOMAHAWK, KY 41262	·-
	y house by road
ROUTE 1884 MILO	
Type of Work: Complaints	
Material Used:	
Customer Line Inspection	
Comments low water pressure	· · · · · · · · · · · · · · · · · · ·
Current System Information:	New Information:
Meter # 1:	Meter # 1:
Meter # 2: Radlo	Meter # 2: Radio
MXU #:	MXU #:
Current Reading 0	Current Reading 0
Type of Meter:	Type of Meter:
Year MFG:	Year MFG:
GPS - Longitude	GPS - Latitude
Employee Signature(s): J.S	Date Completed 2 - 12 - 14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO i	¥ 14020	U172	
7	Fime Started		Work Complete	
,	content manage of particular and a state of the state of		leter#	
Dat 2/4/2014		Account#	SE(2# 109
Name: Matti	new Preece	The state of the s	Phone #	
Address: P.O.	Boy	VI. 1 A. 1	Employe	e Justin Scott
inez,	KY 41224	and the second s		
Location sof the				
.,	Smith Rd	neren na generalistika kantan kan	· · · · · · · · · · · · · · · · · · ·	
Type of Work:	Complaints			
Material Used:	in the second se			
	Increation		,	· · · · · · · · · · · · · · · · · · ·
Customer Line	And word the second Annies and a second and		and the second s	The state of the s
A vage out	stomer has not had water in	au maint a marana a mainte a marana a mainte a		
	nt System Information:	mananananananananananananananananananan	The state of the s	Information:
Meter # 1:	29934714	······································	Meter#1:	
Meter # 2: Radio	29934714	***************************************	Meter#2: Radio	
MXU #:	4) For many	and the same of the same	MXU#;	
Current Reading	1/20/2014 502	·	Current Reading	0
Type of Meter:	Badger	*	Type of Meter:	
Year MFG:	2004		Year MFG:	

Employee Signature(s): 13-6-1H-35

GPS - Longitude 0

Date Completed

GPS - Latitude

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO#	140200198	Material Company of the Company of t	
	Time Started	Work Con	nplete	
Loc#		Master Meter #	and the second s	
Date 2/6/20	14	Account#	SEQ # 58	***
Name: Me	el Markin		Phone # (606)	
Address:	Russell Workman Rd	*		
Lo	ovely, KY 41231			
Location: Lo	ovely, Long BR, 2 m, on right yel		***	
- contribution				
Type of Wor	k: Complaints	**		
Material Use				
Customer Li	ne Inspection		· · · · · · · · · · · · · · · · · · ·	
		ster is Good I	worked on Regulato	
Сп	rrent System Information:	V 4 dda, F	New Information:	***************************************
Meter # 1:	94788708	Meter#	· 1:	
Meter#2: R	adio 94788708	Meter#	2: Radio	mannen en
MXU#:	* w year ************************************	MXU #:	m one visua annocation interior () () anno 1 marie annocation annocation annocation and annoca	
Current Read	ding 1/20/2014 180	Current	Reading 0	

Employee Signature(s): プレ アゴ Date Completed ラ/10/12

Type of Meter:

GPS - Longitude

Year MFG:

Badger

1994

Type of Meter:

GPS - Latitude

Year MFG:

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Ţ	Fime Started	W	fork Complete
Loc#	and a province of the second s	Master Me	eter#
Dat 2/5/2014	ng paramatanan and kalakan demokratikan andara andara	Account #	SEQ# 62
Name: RUS	SELL WORKMAN		
	Russell Workman Rd		
	ELY , KY 41231	~	
Location:			
* 1991 AN ANNIMAN			
Type of Work:	Complaints	* ************************************	and the second s
Customer Line	B		
Comments: no	water water is	Good 1	Wolfsed on Regulater
	nt System Information:		New Information:
Meter#1:	47823828		Meter # 1:
Meter # 2: Radio		and the second second	Meter # 2: Radio
MXU#:	Au-A	rea _{nning} , ann de feindeit.	MXU #:
Current Reading	g 1/20/2014 727		Current Reading 0
Type of Meter:	Sensus	man and a second	Type of Meter:
Year MFG:	1993	, 	Year MFG:
GPS - Longitude	9 0	Harandara de la companya de la comp	GPS - Latitude 0
Employee Signa	ature(s): J.W., R.J.		Date Completed 2/10/12

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Ti	me Started	Wo	rk Complete	
Loc#	·	84		
Dat 2/5/2014	No. consistent of the state of	Account #	SEQ# 321	
Name: Heath	er Harrison		Phone #	may are also man also produce and are also and are also and also are also and also are also and also are also and also are also also are also also also also also also also also
Address: ! M		arran umahan unuga sanannin makan halaga halaga halaga kalaga kalaga kalaga kalaga kalaga kalaga kalaga kalaga	Employee Tony Blevins	
INEZ	, KY 41224		•	
Location: M	ullett Br. Coldwater.Last h	ouse on the right, white	house on hill, stone bottom	
Name of the Control o		· · · · · · · · · · · · · · · · · · ·		
М	ullett Br			•
Type of Work: C	complaints		·	
Material Used:	was a second and a second a second and a second a second and a second a second and a second and a second and	(/)		
	nspection			
		/ 20 psi	PA+ box	
Curren	t System Information:	2 22 24 24 24 24 24 24 24 24 24 24 24 24	New Information:	
Meter # 1:	92701651		Meter # 1:	·
Meter # 2: Radio	92701651		Meter#2: Radio	
MXU #:			MXU #:	MANAGE NO
Current Reading	1/20/2014 959		Current Reading 0	and the supplemental supplement of the supplemental supplement of the supplemental
Type of Meter:	Badger		Type of Meter:	
Year MFG:	1992	Name of the Control o	/ear MFG;	
GPS - Longitude	0		GPS - Latitude 0	
Employee Signat	ure(s): 55, CH		Date Completed 2 - 6 - 14	(.

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Ti	me Started	Work Co	mplete
Loc#	· ognum umuma aka o · · · · · · · · · · · · · · · · · · ·		
Date 2/6/2014		Account #	SEQ# 59
Name: DAVID	MILLS		Phone #
Address: P.O.B	OX ·		
INEZ,	, KY 41224	. A	
Location:	Turkey Rd.1st driveway	on left past Resevoir Rd.	
TURK	EY ROAD		
Type of Work: C		(Dane	
Material Used:			
	nspection Lach a shall s	OFFICERE	chech wirtu wer garing
Curren	t System Information:	Nordige (Pr.) A comment of the comme	New Information:
Meter # 1:	70616474	Meter	# 1:
Meter # 2: Radio	70616474	Meter 1	# 2: Radio
MXU#:	14440372	MXU #	
Current Reading	1/20/2014 35	Curren	t Reading 0
Type of Meter:		Туре о	of Meter:
Year MFG:	-	Year M	
GPS - Longitude		GPS -	Latitude
Employee Signat	hura(s): \\\ \T10\} \n \\\ \T		Nata Completed 2-6-14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO #	140200204
Time Started		Work Comple


Т	ime Started		Work Complete
Loc#		Master M	Meter#
Date 2/6/2014		Account # ^	SEQ# 214
Name: Dahry	/i Keller		Phone #
Address: S	otoor Dr		
Inez,	Ky 41224		
agg to many controlled	Setser Br		
Type of Work: (Complaints	rationalists, organismus and sales appropriate and organization of the sales and sales are sales are sales and sales are sales are sales and sales are sales	
Customer Line !	Inspection		
Comments: ext	remely low pressure 2 v	veeks problem	Fixed ! Nocked on Cold Nater master of
Currei	nt System Information		New Information:
Meter # 1:	33076067	- Annual Company of the Company of t	Meter # 1:
Meter # 2: Radio	33076067		Meter# 2: Radio
MXU#:	,		MXU #:
Current Reading	1/20/2014 249		Current Reading 0
Type of Meter:	Badger	The same of the sa	Type of Meter:
Year MFG:	2006		Year MFG:
GPS - Longitude) <u></u>		GPS - Latitude
Employee Signa	ature(s): TR, TH,	65, CS	Date Completed > / 6 / 14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	# OW	140200104
Time Started	Signification of the contraction	Work Complet

Loc#	ANY CONTRACTOR OF THE CONTRACT	Master Meter#	
Dat 2/4/2014	v o promos promostania (1977). Alletti v iliteriliikin oosa - Alge P. Alletti v ingas	Account #	SEQ# 248
Name: Rona	ald D. & Evelyn Preece		Phone #
Address: P.O.	Box		Employee Clyde Stanley
INEZ	. , KY 41224		
Location 1	Muddy Br. Coldwater. Last o	cream double-wide on left.	
4 3 mg/g/mmmm	Muddy Br		
Type of Work:	Complaints	MA A CONTRACTOR OF CONTRACTOR	
Material Used: Customer Line	Inspection Probles	m fixed! wol	
Material Used: Customer Line Comments ex	Inspection Probles tremely low water pressure,	m fixed! wol	
Material Used: Customer Line Comments ex	Inspection Probles tremely low water pressure, nt System Information:	cannot even flush toilet	New Information:
Material Used: Customer Line Comments ex Curre	Inspection Probles tremely low water pressure, nt System Information: 97176433	cannot even flush toilet	New Information:
Material Used: Customer Line Comments ex Curre Meter # 1:	Inspection Proble tremely low water pressure, nt System Information: 97176433	cannot even flush toilet Meter # 1 Meter # 2	New Information:
Material Used: Customer Line Comments ex Curre Meter # 1: Meter # 2: Radio MXU #:	Inspection Probles tremely low water pressure, nt System Information: 97176433	m Fixed ! wood, cannot even flush toilet Meter # 1 Meter # 2 MXU #:	New Information:
Material Used: Customer Line Comments ex Curre Meter # 1: Meter # 2: Radio MXU #: Current Reading	Inspection Proble tremely low water pressure, nt System Information: 97176433	m Fixed Wood, cannot even flush toilet Meter # 1 Meter # 2 MXU #: Current F	New Information: 1: 2: Radio Reading 0
Material Used: Customer Line Comments ex Curre Meter # 1: Meter # 2: Radio MXU #: Current Reading	Inspection Proble tremely low water pressure, nt System Information: 97176433 97176433	m Fixed Weak cannot even flush toilet Meter # 1 Meter # 2 MXU #: Current F	New Information: 1: 2: Radio Reading 0



387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO	# 140	200163	denotes termina	,
	Time Started	**************************************	Work Com	plete	
	er ver i trans and a degree designed a suit en			The second secon	
				SEQ# 114	
	GER SMITH			Phone #	
Address: PO	вох	<u> </u>		Employee Tony Ble	•
INE	7 KV 11991	······································			
Location	Camp Br Rd				
· · · · · · ·	IP BRANCH				The state of the s
Type of Work:	Complaints	, , , , , , , , , , , , , , , , , , ,		Annual annua	Berger Control of the
Material Used:	No. Assessed to the second				
	Inspection				
			,		
	ktremely low pressure			· *	
Curre	ent System Information:			New Information):
Meter # 1:	19629183	to his work thereon the second	Meter#	1:	
Meter#2: Radio			Meter#	2: Radio	n ,,,,, . Conjunction and the conjunction of the co
MXU #:		and and and and and and and and and and 	MXU#:	Az	· ·
Current Readir	ng 12/20/2013 782		Current	Reading0	and the state of t
Type of Meter:	Badger		Type of	Meter:	annum va e e e e e e e e e e e e e e e e e e
Year MFG:	2003	SSMO vir verinimassianimas "	Year MF	'G:	. 25. \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
GPS - Longitude 0 GPS - Latitude 0		atitude 0	Control of the Contro		
report of comparing and assume approximation		TO WANTE TO THE TOTAL OF THE			

Employee Signature(s): TB, GS, TH, CS

Date Completed 3/6/14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO#	140100407	marginal 1800 (con recognización con con conse	
Ti	me Started	Work C	Complete	
Loc#		Master Meter #		
Dat 1/30/2014	AND THE STREET S	Account#	SEQ# 321	nte analysisch der von alle Stages von St. F. der St. Stages von Stages (S. S. S
Name: Heath	er Harrison		Phone #	
Address:	ullo# Dr		Employee Clyde Sta	
a watch conferential and	, KY 41224			water the second of the second
Location:M		se on the right, white ho	use on hill, stone bottom	
2 M	ullett Br			•
Type of Work: C	Complaints			
Material Used:		Je)		
Comments: extr			· · · · · · · · · · · · · · · · · · ·	
Curren	t System Information:		New Information	E -> ;
Meter # 1:	92701651	Mete	er#1:	· · · · · · · · · · · · · · · · · · ·
Meter#2: Radio	92701651		er#2: Radio	·
MXU#:	Application of the second of t	MXL	J#: <u></u>	
Current Reading	12/20/2013 951	Curr	rent Reading 0	
Type of Meter:	Badger	Туре	e of Meter:	
Year MFG:	1992	Yea	r MFG:	- Andrew Control of the Control of t
GPS - Longitude	0	GPS	S - Latitude 0	

Employee Signature(s):

Date Completed 2.6.14

387 East Main St., Suite 140 fnez, KY 41224

WORK ORDER

WO#

Time Started Work Complete			/ork Complete		
Loc#	Market 18 1 minimum and a second		Master Meter #		
		Account #	SEQ# 109	Market Market State Control of the C	
Name: Allen B	owen	-	Phono #		
Address: P.O. BO	and M				
lnez	, Ky 41224	· manner 2			
Camp I		The state of the s			
Type of Work: Co	omplaints			·	
Material Used:		Dre	_)		
Customer Line Ins	spection	4		······································	
Comments custo	omer has extremely low		and the second of the second o		
Current	System Information:		New Information:		
Meter # 1:	96646016		Meter # 1:		
Meter # 2: Radio			Meter # 2: Radio		
MXU #:			MXU #:		
	12/20/2013 1542	· · ·	Current Reading0		
Type of Meter:	Badger		Type of Meter:	and the second s	
Year MFG:	1996		Year MFG:		
GPS - Longitude	0 //		GPS - Latitude 0		
Employee Signatu	re(s):///		Date Completed 2.6./	4	

lmartin County Water Dis...ct

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO#	1402	80000	
	Time Started	* *********	Work Complete	
Loc#	THE STATE OF THE S	Master	Meter #	
Dat 2/3/201	4	Account#	SE(Q# <u>260</u>
Name: LO	RRAINE JUDE		Phone #	
Address:	Duncost Dd	~~ ~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	Employe	e Justin Scott
Lal	ke Worth, FI 33467	-	***************************************	
Location:	UDans Br			
DA	VIS BRANCH			
Type of Work	: Complaints		na mettavitavita va tujuvatataka karista karista karista karista karista karista karista karista karista karis	
Material Used	: THAwed	*		
	e Inspection			
	Sary Jude-former owner of prop			
Curi	rent System Information:		New	Information:
Meter#1:	46220019	Ndd Fallania Antonomia Ant	Meter # 1:	engangan ang ang ang ang ang ang ang ang ang ang
Meter # 2: Rad	llo		Meter # 2: Radio	
MXU#:	general and a second	·	MXU#:	negative contracts. With City out, N
Current Readi	ng 1/20/2014 1034		Current Reading	0
Type of Meter	: Sensus	handyn gegrap gefatt romger	Type of Meter:	
Year MFG:	1992		Year MFG:	
GPS - Longitu	de 0	······································	GPS - Latitude 0	
Employee Sigi	nature(s): 18 ~ 65 ~ 5 ~ 5	14	Date Complete	d 2-64-14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

140200006

	Time Started	Control of the September of the Control of the Cont	Work Complete			
Loc#	Loc # Master Meter #					
			SE	EQ# 204		
Name:	EXCEL MINING CO., LLC		Phone :	#		
Address:	ेर Hwy 194 West	· ***	Employ	ee Justin Scott		
	Pikeville, KY 41501	· M · M · M · M · M · M · M · M · M · M				
Location:				entermination of the second		
	What is seen a second s					
Customer	Used: Changed r Line Inspection ts: has no water at box,	Meler				
(Current System Information:		Nev	New Information:		
Meter#1:	Sometimes and the supported by the contract of	Produce Street S	Meter#1:	10788513		
/leter # 2:	Radio		Meter # 2: Radio			
/IXU#:	· · · · · · · · · · · · · · · · · · ·		MXU#:	ta a sa a		
Current R	eading 0	and the second second	Current Reading	ø 000		
Type of M	eter:	n - in marine	Type of Meter:	ABB (27m)		
ear MFG):	Managara (A), sin amenocile accompanyones.	Year MFG:			
GPS - Lor	ngitude		GPS - Latitude			

Employee Signature(s): 115-55-65-114 Date Completed 2-5-14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO #	14020	00181	
	Time Started	a say sha same	Work Complete	righter minimum v. o virginis de
Loc#	alimana manaminan () () and t o a comp many many manaminan () and manaminan		Meter#	man managaman a man . Ampanganan man Taraga matatiba man da baran
Dat 2/5/	2014	Account #	- SEQ#	83
Name:	ARLEN COOK			·
Address:	PO BOX	han ganjaarah 1986 aan ah sakarah habibah oo ka 100 km/de, saabbah 118	Employee	Jason W.
	BEAUTY , KY 41203			
Location:	Bone Hollow Rd		A	
		and the second s		
	Vork: Complaints	To the act a local designation of the second		Accordance and accordance with the property of the contract of
Material U	Jsed: GOT WATE		ang tinang ang ang ang ang ang ang ang ang ang	
	Line Increation	and the second of the second o		and the second s
Comment	ts: water went off around 10 pm la	ast night R	aset Pump 1	Sine unt 2
	Current System Information:	e economica quantitativa de proprio de la companio del la companio de la companio del la companio de la companio del la companio de la compan	New Int	formation:
Meter#1	19713222	- water - on- on- mountain trans	Meter#1:	anne ann an an ann ann ann an an an an an an
Meter # 2:		and a second	Meter # 2: Radio	na paga na an
MXU #:		ADDITION to de not definicable	MXU #:	
Current R	eading 1/20/2014 732	angan produceron i seguir i consissionistica	Current Reading	0
Type of M	eter: Badger	· Mandala Maria	Type of Meter:	
Year MFG		· · · reconstructive (All College Coll	Year MFG:	
GPS - Lor	ngitude 0	and the company of the state of	GPS - Latitude 0	

Employee Signature(s): 5 0 AF 13-55-65-114 Date Completed 2-5-19

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO #	1402001	34		
	Time Started	Wo	k Complete	naturajan (minimum minimum min	
Loc#	naghinggaring		sr#		
Dat 2/5/2		Account #	or management and	SEQ# 84	
Name:	FREDDIE & CAROL CHAFFINS		Pho	ne# (
Address:	PO BOX		Emr	oloyee Jason W.	
,	BEAUTY , KY 41203		-		••
Location:	Dana Mallaus				
	na na Anadrik kalifantinanya di sa Ada Naudusia samananya njigajahan na sarasana ta samana sambili dak san	ausstalens ta <u>mpila</u> aussen i dadatus pataman 1999 daganis dag	W	and the second	And the state of t
∵ Type of W	ork: Complaints				
Customer	sed: 98 DATER Line Inspection	Designation of the control of the co			
Comments	s: no water since last night R	seen & conf	v Dosel	une a	
C	Current System Information:		ı	New Information	;
Meter#1:	72305550		leter#1:	garwan , sayanan anganimina	
Meter # 2:	Radio 72305550	N	leter#2: Radio		
MXU#:	ju 1973 <u>juni kan</u> alangkalangkalangkala, 1970 1971 1971 1971 1971 1971 1971 1971		1XU #:	TO NOT THE PROPERTY IN A SHARE WAS DOOD TO THE PROPERTY OF THE	, cyto
Current Re	eading 1/20/2014 83		urrent Reading	0	
Type of Me	eter: Sensus	Т	ype of Meter:		
rear MFG:	2010	Y	ear MFG:	All control of the second of t	
GPS - Long	gitude 0		SPS - Latitude	0	

Employee Signature(s): JUBST 18 65-114

Date Completed 2-5-14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

140200182

WO#

Time Started		Work Co	mplete
Loc#	rider som game aven bornstrøde væderner en sed a dens mend væderskrevereren en en en	R4	poliumarijumikalians , se aussamas se sonom su sonom <mark>anijumikana kanandindahan maka ana ana ana an</mark> an sanoma san
Dat 2/5/2014		Account#	SEQ# 82
Name: MAGC	GIA HINKLE	·	Phone # (
Address: PO BO	OX	and the course of a second contract of the se	Employee Jason W.
BEAU	TY , KY 41203		
Location: B	one Hollow on 2031, 1/4 of	a mile on Poplar Fork on le	ft, 2nd single wide on left
Sourcestant Arrest A	CANCELLO TO A SE AMERICAN MENTAL MENTAL MENTAL SE L'ANNO MA		
, on spanowa	1 TAN 10 - Non-market and section of the section of	•	
Type of Work: Ć	Complaints		·
Material Used: 3		· ·	
``			-
Customer Line II	water and a second seco	0 .1 5	
Comments: no v	water since about 10:30 las	tnight Report Pu	mp soul unit 2
Curren	t System Information:		New Information:
Meter # 1:	99085837	Meter	# 1:
Meter # 2: Radio	99085837	Meter	# 2: Radio
MXU #:	Santa a La Canada de la Manda de Canada de Can	MXU #	:
Current Reading	1/20/2014 584	Currer	nt Reading 0
Type of Meter:	Badger	Туре с	of Meter:
	1999		/IFG:
	0		Latitude 0
		و و معمولین هو	

Employee Signature(s): 50 AT 13-15-14-65 Date Completed 2-5-14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO	#	1401	0043

Time Started		Wor	Work Complete		
Loc#	iniquation and the second seco		41	- service and a service of the servi	
Dat 1/31/2014	n den de en	Account #	SEC	Q# 244	
Name: GARY	CHAPMAN		Phone #		
Address: P.O.B	OX			e Rainbo	
INEZ	, KY 41224				
Location:	Coldwater Rd	-			
COLD	WATER RD.			·	
Type of Work: C	omplaints	10			
Material Used:		11)01			
Customer Line In	nspection				
Comments: no v	vater Has w	cter today	<i>!</i> ·		
Curren	t System Information:		New	Information:	
Meter # 1:	93144891		Meter # 1:		
Meter # 2: Radio	Widow springers and the spring		feter#2: Radlo	Andrew - Marion - Angres - Ang	
MXU #:		N	1XU #:		
Current Reading	12/20/2013 837		Current Reading	0	
Type of Meter:	Badger	T	ype of Meter:	ann de marine de marine de la compansa de la compa	
Year MFG:	1993	Y	ear MFG:	and the same of th	
GPS - Longitude	0	,,	GPS - Latitude 0	· ·	
Employee Signat	ure(s):		Date Complete	od 2-3-14	

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO #	140100465	MARIANI WALLEST STATE OF THE ST
	Time Started	Work C	Complete
Loc#	меченен разделина (ж. 100 г.). А сектронично поменено и поменено и поменено и поменено и поменено и поменено и		
Dat 1/31/2	ς.	Account #	SEQ# 117
Name: J	anice Blackburn		Phone #
Address:	Camp Branch		Employee Justin Scott
11	nez, KY 41224		
Location:		w, green double wide	
	Coldwater		
Type of Wo	ork: Complaints		
Material Us	Appril 1 at the second	nell	
Customer L	ine Inspection		
Comments:	Extremely low pressure	ad about 5	2 PSI At box
Cı	urrent System Information:		New Information:
Vieter#1:	29935159	Mete	er # 1:
Meter#2: F	Radio 29935159	Mete	er#2: Radio
VIXU#:	gran natural ann ann an Art Geoldon	MXU	#:
Current Rea	ading 12/20/2013 309	Curre	ent Reading 0
Гуре of Met	er: Badger	Туре	of Meter:
rear MFG:	2004	Year	MFG:

Employee Signature(s): 55

Date Completed 2-2-14

GPS - Latitude

GPS - Longitude

387 East Main St., Sulte 140 Inez, KY 41224

WORK ORDER

WO# 140100450

Time Started		W	ork Complete	# TV (1870-1871-18-1-18-1-18-1-18-1-18-1-18-1-	
Loc#			Master Meter#		
Dat 1/31/2014		Account#	Ś	EQ# 298	
Name: TRAC	Y BUTCHER		Phone	#	
Address:	Coldwater Rd		Emplo	yee Tony Blevins	
INEZ	, KY 41224				
Location: around	d Pleasant Valley	,	,		
	W MAN ALL ALL OF MAN THE PROPERTY OF THE PARTY OF THE PAR	in insumination in a single contract of the s			
·	WATER RD.				
Type of Work: C	complaints	And the second s			
)	A CONTRACTOR OF THE CONTRACTOR	
Material Used:	<u> </u>	1 date		The state of the s	
Customer Line In	nspection	The second secon	and the second s		
Comments:	Qe				
Curren	t System Information:	· mann yg-by-graden and an ann an ann an ann an ann an ann an		w Information:	
Meter # 1:	99691581	and the second	Meter # 1:		
			Meter # 2: Radio	eret (MA) ANNONEMENTAL MAN AND AND AND AND AND AND AND AND AND A	
MXU#:			MXU #:	<u></u>	
Current Reading	12/20/2013 646	·	Current Reading _	0	
Type of Meter:	Badger		Type of Meter:		
Year MFG:	1999		Year MFG:	and the state of t	
GPS - Longitude	0 	eastan aan amerika oo	GPS - Latitude	0	
Employee Signat	ure(s):		Date Comple	eted 23.14	

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

140100447	A. (1997)
Work 0	Complete
Master Meter #	
Account#	SEQ# 222
	Phone #
The second secon	Employee Tony Blevins
ann a thaille ann an t-aireann an tha ann an Art an teach all ann an deann an teachailte ann an teachailte an t	notes
on right, new construct	ion
1 1	and the second s
love)	
respue no kinc	
	New Information:
Mete	er#1:
	er#2: Radio
	J#:
Curr	rent Reading 0
Тур	e of Meter:
Yea	r MFG:
, OD6	
GPS	S - Latitude
GPS	3 - Latitude
	Master Meter # Account # on right, new construct Dessure Is Fine Mete Mate MXI Curr Type Yea

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO #	140100457	MA SOURS V-COMMEN
	Time Started	Work Con	nplete
Loc#	The state of the s	Master Meter #	
Dat 1/3	1/2014	Account #	SEQ # 52
Name:	Laraya Fields		Phone # (
Address:	P.O.BOX		Employee Tony Blevins
	INEZ , KY 41224		and the first terminal fields and parties to the terminal and the terminal and the terminal and
Location		•	
	COLDWATER RD.		
Type of V	Vork: Complaints		
	Used:)	
		Done/	
Custome	r Line Inspection		Control of the Contro
Commen	ts extremely low pressure γ	nessure Better	there is a second to the secon
	Current System Information:	ri Azura, dam an dadan m uja dikaman da Nagri Angri (100 ming pandinggan dan dan kangan dalamin v	New Information:
Meter#1	: 93749257	Meter#	£1:
Meter # 2	: Radio	Meter #	2: Radio
MXU#:	Sea - Seminarity of Adolescop - Seminarity over 1 months and produce of the seminarity of the seminari	MXU#:	Approximately and the second s
Current R	leading 12/20/2013 1153	Current	Reading 0
Type of M	leter: Badger	Type of	Meter:
Year MFG	9: 1993 <u> </u>	Year M	FG:
GPS - Loi	ngitude 0	GPS - I	_atitude 0
Emolovee	Signature(s):	Di	ate Completed 2.3.14/

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

•	WO #	140100468	-
, τ	ime Started	Work Co	emplete
	and the state of t		
Dat 1/31/2014			SEQ# 198
Name: Arlena	a Evans		Phone # /
Address: P.O. I	Зох		Employee Tony Blevins
	, KY 41224		
			y. Brown house w/brown tin roof.
	Coldwater Rd Complaints	Done	
Material Used:			
Customer Line I	nspection		
Comments:			
Currer	nt System Information:	1 m 1 m 1 m 1 m 1 m 1 m 1 m 1 m 1 m 1 m	New Information:
Meter # 1:	33076070	Meter	#1:
Meter # 2: Radio	33076070	Meter	#2: Radio
MXU#:		MXII	
Current Reading	12/20/2013 853	Curre	nt Reading 0
Type of Meter:	Badger	Type o	of Meter:

Employee Signature(s): 15 Date Completed 2-3-14

Year MFG:

GPS - Latitude

2006

Year MFG:

GPS - Longitude 0

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO #	140100452	n an tentanti 4	
Tin	ne Started	Work Con	nplete	·
	William Andrews Commission of the Commission of			
Dat 1/31/2014	aliai aanaan ingunamanakankankankankankankankankankankankank	Account #	SEQ # 27	many di mandi in ang kalan ang
Name: ALBER	ТЅМІТН		Phone #	No. of the state o
Address: P.O.BC	\v	* ** ** ******************************		/ Blevins
INEZ	, KY 41224	•		
Location: Jac	ck Cassady Br			and the second s
J CASS	SADY BR. pmplaints	Dane		
Material Used:				
Customer Line In				
	ater pressure but b			
Current	System Information:		New Inform	ation:
Meter # 1:	97354363	Meter#	1:	
Meter # 2: Radio	personal control of the control of t	Meter#	2: Radio	
MXU#:		MXU #:	A MAR OF STANDS AND	and the second s
Current Reading	12/20/2013 836	Current	Reading	0
Type of Meter:	Badger	Type of	Meter:	
Year MFG:	1997	Year M	FG:	
GPS - Longitude	0	GPS - I	_atitude 0	and the second s
		, , , , , , , , , , , , , , , , , , , ,		

Date Completed_

Employee Signature(s): BJ

Martin County Water Dist. ot /


387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO #	1401004	43		
Ti	me Started	Wo	rk Complete		
Loc#	and the second s	Master Met	er#	er anne i dei	- Villegaline
Dat 1/31/2014		Account #		SEQ# 110	N
Name: Jimmy	/ Hensley		Phor	ne#	i
Address:	Camp Br		Emp	loyee Tony Blevins	
	KY 41224			-	
Location:	Camp Br. Tan two tone traile	r on the right.			
	Camp Br				, an anamar ex-s-s -maniferin
Type of Work: C	Complaints	Dione			
Material Used:				accoming accoming	
Customer Line II	nspection	and the second s		The witness of the second seco	
Comments: extr	emely low pressure al	ittle better	now		
Curren	t System Information:	2-	N	lew Information:	
Meter # 1:	47823736		Meter # 1:		
Meter # 2: Radio	47823736	<u></u>	Meter#2: Radio	NAMES AND ASSESS OF THE PARTY O	
MXU#:		M	MXU #:	p	
Current Reading	12/20/2013 405		Current Reading	<u> </u>	
Type of Meter:	Sensus	-	Type of Meter:	***************************************	
Year MFG:	1993		ear MFG:	water and the second of the se	
GPS - Longitude	0	(GPS - Latitude	0	

Date Completed 2-3-14

Employee Signature(s): RJ



387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 140100444

Time Started		Work C	Work Complete			
Loc#	Designation of the second seco	Master Meter #	Master Meter #			
Dat 1/31	/2014	Account#	SEQ# 115			
Name:	Paul Hensley		"			
Address:	Camp Branch		Employee Tony Blevins	S		
	Inez, KY 41224		name a			
Location:	•		ise .			
	Coldwater /ork: Complaints	Dane		residential and the second		
Material U	sed:	9.20				
Customer	Line Inspection	>	· · · · · · · · · · · · · · · · · · ·			
Comment	s: extremely low pressure	better than auc	بره			
(Current System Information:	And the second s	New Information:			
Meter # 1:	67012625	Mete	r#1:			
Meter # 2:	Radio	Mete	r#2: Radio			
MXU#:		M XU) #: 	/1. <u>************************************</u>		
Current Re	eading 12/20/2013 186	Curre	ent Reading 0	> - > Access - vices requirements designated		
Type of Me	eter: Sensus	Туре	of Meter.			
Year MFG			MFG:	entralina en la companya en la comp		
GPS - Lon	gitude	GPS	- Latitude			
Employee	Signature(s): <i>R</i> チ		Date Completed 2-3	-14		



387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Time Started		Work Complete			
Loc#			er#		
Dat 1/31/2014	Non-recognition is the second and		SEQ# 307		
Name: Aaron	& Jackie Gauze		Phone #		
Address: P.O. B	ox	**************************************	Employee Clyde Stanley		
INEZ,	, KY 41224		and the second s		
Location:	Coldwater Rd				
	Coldwater Rd				
Type of Work: C	omplaints				
Material Used:					
Customer Line Ir	nspection	4			
Comments: very	,	Has got	d paressure nou		
200 271 1 700 27	t System Information:	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	New Information:		
Meter # 1:	98604665	hootohoogaan	Meter # 1:		
Meter # 2: Radio	98604665	•	Meter # 2; Radio		
MXU #:	2-2		MXU #.		
Current Reading	12/20/2013 662	www.manner.	Current Reading 0		
Type of Meter:	Badger	***************************************	Type of Meter:		
Year MFG:	1998		Year MFG:		
GPS - Longitude	0	distance on the second	GPS - Latitude 0		
Employee Signate	ure(s): 5		Date Completed 2 - 3 - 1 9		

Martin County Water Dist. St

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

		WO #	14010045	1	
	Time Started		Work	Complete	
Loc#	resentante de la company de la	**************************************	Master Meter	#	na nataonina,, etc.,
Dat 1/31	/2014	Acc	ount#	·	SEQ# 285
Name:	ALBERT SMITH Jr.			Phon	e#
Address:	COLDWATER RD			Emp	loyee Tony Blevins
	INEZ, , KY 41224		**************************************		-
Location:					and the state of t
``.	COLDWATER RD.				
Type of W	ork: Complaints		and the same of th		- International Control of the Contr
Material U	sed:	- production			
Customer	Line Inspection	(10	INP.		
Comments	ino water Custoo	mer h	as water	tool	form but not
Ċ	urrent System Information	on:	· Standard	N	ew Information:
Meter#1:	98985892		Me	ter # 1:	A S. Sundanian and M. S. Sandanian and M. Sandanian and M. S. Sandanian and M. Sandanian
Meter # 2:	Radio		Me	ter#2: Radio	\ <u></u>
MXU#:		VII	ΚM	(U #:	Address Colonia Coloni
Current Re	ading 12/20/2013 199		Cu	rrent Reading	0
Type of Me	ter: Badger			oe of Meter:	
Year MFG:	1998	·	Ye	ar MFG:	And the second s
GPS - Long	itude 0		GP	S - Latitude	0

Employee Signature(s): 1.31.11

TW, RJ,

Date Completed

2-3-14

Martin County Water District \(\square \)

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO	# 14020	90101
Т	ime Started		Work Complete
			Meter#
		Account #	
Name: TIM S	SIZEMORE	www.www.co.co.co.co.co.co.co.co.co.co.co.co.co.	Phone #
Address:	Tomahawk Rd.		Employee Justin Scott
	AHAWK , KY 4126		
Location			
	- Syr		
ROU	TE 40 WEST		
Type of Work:	Complaints		
¥			
Customer Line	; (Lamplat	Place of main caused P
Curre	nt System Information:		New Information:
Meter#1:	98607414		Meter # 1:
	V 20 20 No. American American States (AMA) American States (Amarican State		Meter # 2: Radio
MXU#:		MANAGONA 1999 - ANGELIA ANGELIA ANGELIA ANGELIA	MXU #:
Current Reading	12/20/2013 600	reduceran and confirm all annuals as	Current Reading 0
Type of Meter:	Badger		Type of Meter:
Year MFG:	1998	k von der energen einer energen einer en	Year MFG:
GPS - Longitude	0		GPS - Latitude 0
Employee Signa	iture(s):		Date Completed 2/4/13

Employee Signature(s):

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO#	1401004	488	
Time Started			ork Complete	
Loc#			ter#	
Dat 1/31/2014		Account #		9
Name: JOES	TATON		Phone #	
Address: M	ullett Br		Employee Tor	ny Blevins
INEZ	, KY 41224 .	NV housewoods vary for the contract of the con	Carried Substance	
Location:	Mullett Br		CONTRACTOR AND	
Annual section and the training to the	AND BOOK OF THE PROPERTY OF TH		The state of the s	A STATE OF THE STA
MOLL	ETT BRANCH			
Type of Work: C	complaints			
Material Used:				·
Customer Line In	./	7)04		<u></u>
Comments: extr	emely low pressure	tas 40 q	ISI At box	
Curren	t System Information:		New Infor	mation:
Meter # 1:	97354329	and the second	Meter # 1:	and the second s
Meter # 2: Radio	, ,		Meter # 2: Redio	agency of the second se
MXU#:		innered the second of the seco	MXU #:	
Current Reading	12/20/2013 1058	· · · · · · · · · · · · · · · · · · ·	Current Reading	0
Type of Meter:	Badger	Name of the State	Type of Meter:	
Year MFG:	1997		Year MFG:	
GPS - Longitude	O Marie Company of the Company of th	and the state of t	GPS - Latitude 0	The second of th
Employee Signat	ure(s): JS		Date Completed	1-4-14

Martin County Water Dist. Lt

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Time Started		Work	Complete
Loc#	WWW.	Master Meter	#
Date 2/12/2014		Account #	SEQ# 474
Name: John C	Curtis Kirk		Phone #
Address: P.O. B	Jox		
inez, l	(y 41224		
E	den West		
Type of Work: Ç	omplaints:		1 one
Material Used.	Out down	- A	
Material Caca.	TWO PARTY I		101.01
Customer Line In	nspection	Obrea	dy had grand put das
	**************************************	down, they were removed w	when tap was put in
	t System Information:		New Information:
Meter # 1:	98003080	Me	eter # 1:
Meter # 2: Radio	98003080		eter # 2: Radio
MXU#:	k	M	(U #:
Current Reading	1/20/2014 334	Cu	rrent Reading 0
Type of Meter:	Badger	Ty	pe of Meter:
Year MFG:	1998	Ye	ar MFG:
GPS - Longitude	t.	GF	PS - Latitude
Employee Signat	ure(s): <u>55,</u> <i>R</i> J		Date Completed 3-24-14

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	AAO #	140300177		
	Time Started	Work Co	omplete	· ·····
Loc#		Master Meter #		and the second s
Date 3/24	3/2014	Account #	SEQ # 288	3
Name:	Niki J. Boyes		Phone #	
Address:	Ruffelo Horn			. '
	Louisa Kv 41230		•	
Location	,	le on left. White trailer dow		
	Buffalo Horn Rd			
Type of V	Vork: Complaints			
Material L	Jsed:	() 01	e $) $ $-$	
Customer	Line Inspection			
Comment	ts: NO WATER / Care	back on	about an	hour ofthe he calle
	Current System Information:		New Inform	ation:
Meter # 1:	70840680	Meter	# 1:	name to the state of the state
Meter # 2:	Redio 70840680	Meter	# 2: Radio	
MXU#:	and the second s	MXU	#:	
Current R	eading 2/20/2014 153	Curre	nt Reading	0
Type of M	leter: Sensus	Type	of Meter:	- Annual Control of the Control of t
Year MFG			VIFG:	
ĜPS - Lor		GDS.	- Latitude	

Employee Signature(s):

3-26-14

Date Completed

Water Dispoct

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Time Started		\	Work Complete		
Loc#			Master Meter #		
Dat 3/14/2014		Account #	SEQ# 158	\$ -\(\text{\tin}\text{\tett{\text{\tetx}\\ \text{\text{\text{\text{\texitt{\text{\text{\text{\text{\text{\text{\text{\text{\text{\texi}\text{\text{\texi}\text{\text{\text{\texi}\text{\text{\text{\texi}\text{\text{\texit{\text{\teti}\titt{\text{\texi}\tittt{\texitit}\\ \tittt{\text{\texi}	
Name: NOAH	WEBB	instr <u>usionalistania anno anno 1</u> 000 de mandre	Phone # /		
Address: PO BC)X	andanina	Employee Jason W.		
LOVE	LY , KY 41231		· · · · · · · · · · · · · · · · · · ·		
Location 1	N Wolf Crk Lovely.1714. F	First house on left on	Webbville White 2-story. N. Wolf C	reek.	
Angular with district to the		was a summary of the same of t		and the second	

Type of Work: C	complainte				
Type of Work.	omplains	e de la companya del companya de la companya del companya de la companya del la companya de la c			
Material Used:					
Customer Line I	nspection (7/22h0	JK.		
***************************************	plaints of air in line, nesd	s ilusped		***************************************	
	t System Information:		New Information:	-	
Meter # 1:	74604138		Meter # 1:	and the second s	
Meter#2: Radio	74604138	gyrnus reasong and de	Meter#2: Radlo	gyraannaa waana waanaannaa aa aa	
MXU#:	14992318	generospontacións canniquiaco a 161, 16	MXU #:		
Current Reading	2/20/2014 38	dense var vijt av hiller om jaret om j	Current Reading 0		
Type of Meter:	**************************************	And Annual Annua	Type of Meter:	un	
Year MFG:		and Proposition as a 1990 to Springer with	Year MFG:		
GPS - Longitude	Andrewson and anti-		GPS - Latitude	00	
	á:-		and the state of t		
Employee Signat	ure/e) KIT		Date Completed 3 - 14	-14	

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#



Time Started		na and analysis warm	Work Complete		
Loc#	, «могумен» «««««»» «««»» ««»» ««»» ««»» ««»» ««	Master	Master Meter #		
	PF - 445-07 2 M2 MARIEMENE PER PER PER PER PER PER PER PER PER PE	Account #		158	
Name: NOAl	H WEBB	**************************************	Phone # ().¢	
Address: POB	OX	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Employee	Jason W.	
LOVE	LY , KY 41231	at or analysis	* William to the stands are also are the stands of	4	
Location:		and the second s	n Webbville.White 2-story.		
Type of Work:	Complaints	e net sammenamente e se manuscriptures es manuscriptures es manuscriptures es manuscriptures es manuscriptures	- Andrews		
Material Used:					
Customer Line	Inspection			•	
	mplaints of air in line, need	de fluehad			
	nt System Information:		New In	formation;	
Vieter#1:	74604138		Meter#1:		
Meter#2: Radio	74604138		Meter # 2: Radio		
	14992318		MXU #:		
Current Reading	2/20/2014 38	and the second s		0	
Type of Meter:	Accounts and the second	· ann open and a state of the s	Type of Meter:	and the second s	
Year MFG:	National Control of the Control of t	- nonnumbili substanti di Supstanti di Supst	Year MFG:		
GPS - Longitude	Section of the sectio		GPS - Latitude		
Employee Signa	ature(s):		Date Completed	3-19-14	

Martin County Water Dist. ...t

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Time Started		V	Work Complete		
Loc#		Master Me	Master Meter #		
Date 3/10/20	14	Account#	SEQ#	‡ <u>48</u>	
Name: Lar	ndon Jude	· · · · · · · · · · · · · · · · · · ·	Phone #	en e	
Address: P.C). Box				
ine	z, KY 41224		······································		
Location:	E Main St, Inez, last house	e past pawn shop, whit	e w/green shutters, next	to empty lot	
······					
	E Main St			•	
Type of Work	c: Complaints	M			
Material Used	4.				
			eri d		
Customer Lin	ne Inspection	water pressure, going	BI RBW	chine, has reported several ti	
Customer Lin	ne Inspection	water pressure, going	to burn up his wash mad		
Customer Lin Comments: c	complaints of extremely low	water pressure, going	to burn up his wash mad	chine, has reported several ti	
Customer Lin Comments: c Cur Meter # 1:	ne Inspection	water pressure, going	to burn up his wash mad New In Meter # 1:	chine, has reported several ti	
Customer Lin Comments: C Cur Meter # 1: Meter # 2: Rad	rent System Information:	water pressure, going	New In Meter # 1: Meter # 2: Radio	chine, has reported several ti	
Customer Lin Comments: c Cur Meter # 1: Meter # 2: Ra MXU #:	rent System Information: 70616368	water pressure, going	New In Meter # 1: Meter # 2: Radio	chine, has reported several ti	
Customer Lin Comments: c Cur Meter # 1: Meter # 2: Rad MXU #: Current Read	rent System Information: 70616368 dio 70616368 14440339 ling 2/20/2014 23	water pressure, going	New In Meter # 1: Meter # 2: Radio MXU #: Current Reading	chine, has reported several ti	
Customer Lin Comments: C Cur Meter # 1: Meter # 2: Ra MXU #: Current Read Type of Meter	rent System Information: 70616368 dio 70616368 14440339	water pressure, going	New In Meter # 1: Meter # 2: Radio MXU #: Current Reading	chine, has reported several ti	
Customer Lin Comments: C Cur Meter # 1: Meter # 2: Ra MXU #:	rent System Information: 70616368 dio 70616368 14440339 ling 2/20/2014 23	water pressure, going	New In Neter # 1: Meter # 2: Radio MXU #: Current Reading Type of Meter:	chine, has reported several ti	

Martin County Water District 387 East Main St., Suite 140

Inez, KY 41224

WORK ORDER

WO#

Ti	me Started	Work Co			
Loc#	ender in the second of the second	Master Meter #		7 ° C C 2 5	v ,¢:
Date 7/28/2015	,	Account#	SEQ# 2	.02	Re go
Name: Stepha	anie Tackett	at explants (diameters	Phone #		- ; w
Address: N	Wolf Crk Rd	the second to th	Employee Ju	stin Scott	
Pilgrin	n, Ky 41250	معشر مصيحين ها			
		m Pigeon Roost community c	enter. White house	on the left with	green
roof &	shutters		wave gaze 1	, ,	· · · · · · · · · · · · · · · · · · ·
, . N	Wolf Creek RD	gyah ing pangang Kabupangang	\$ / \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		1 3 M 1 5 T.
Type of Work: O	Complaints	, and a state of the state of t	areas, s. x br	v ,	
Material Used:	an harast of the second	grande grande og de skrivet i de skrivet skrivet skrivet skrivet skrivet skrivet skrivet skrivet skrivet skriv	v. v	# × · · · · · · · · · · · · · · · · · ·	<i>187.</i> 2
Customer Line I	water 1 Toppo	Ly M. Cuc	ternors s	de	•
Currei	nt System Information:	•	New Infor	mation:	
Meter#1:	96982418	Meter	# 1:	4 те у е	. .
Meter # 2: Radio	96982418	Meter	# 2: Radio	% of v	*
MXU#:	ا سو مردد د د د	MXU #	;	•	-
Current Reading	6/20/2015 1168	Currer	nt Reading	0	
Type of Meter:	Badger	Туре	of Meter:	*	
Year MFG:	1996	Year N	//IFG:	4	
GPS - Longitude	•	GPS -	Latitude	•	
	 0 		um de ser es		. ,
Employee Signa	iture(s):	Ε	Date Completed 🥣	9 - 29	-15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Time Started	Work Complete				
Loc#	Master Meter #	2 3 % WILLIAM 32% 37%	et mensk		
Date 7/28/2015	Account#	SEQ# 397	ب م		
Name: PAUL MORRISON	v even engantament is a	Phone # (;			
Address: PO BOX	a a complex a commence of	Employee Troy Horn			
INEZ , KY 41224	e series of the				
Location: Across from Venters Branch.L	ittle grey house on left. 3428 No	ew Rt 3			
e c	to a minimum mental and a constraint and a	e A September 2000 A Se			
NEW RT 3	ina	, , , , , , , , , , , , , , , , , , ,			
Type of Work: Complaints	. a " had haassen it	-\$ in the country to the second of the country of t	·> * 4 *		
Material Used:	to a account the state of the summer of the second of the	4 504 %) */·×·		
Customer Line Inspection	n e li i maran n ka ki i nagandanganak kilo ee	a programa de de C. S. F. S.	\$ e .		
Comments: air in the lines	Blew off In	egge vig me di amerimmen g			
Current System Information:	ila ya kataba animani ya ee ee ee ee kataba anii ka	New Information:	9		
Meter # 1: 29934564	Meter	‡1: ., ,	• • •		
Meter # 2: Radio	Meter	2: Radio			
MXU #:	. MXU#		·		
Current Reading 6/20/2015 495	Curren	t Reading 0	* *		
Type of Meter: Badger	Туре о	f Meter:			
Year MFG: 2004	Year M	IFG:	-w w 70% >		
GPS - Longitude 0	GPS-	Latitude 0	٠		
- 1,00 €	ita kan ni na manangga e gan a s	*	· · · · · · · · · · · · · · · · · · ·		
Employee Signature(s);	}	ate Completed 7-28 1	5		

387 East Main St., Suite 140 inez, KY 41224

WORK ORDER

WO#

150700144

Time Started

Work Complete

Loc#

Master Meter #

Date 7/20/2015

Account #

SEQ # 237

Name:

Dahryl Keller

Phone #

Address:

Setser Br

Employee Troy Horn

Inez, Ky 41224

Location:

Setser Br. Wood sided house @ end of road

Setser Br

Type of Work: Complaints

Material Used:

Customer Line Inspection

Comments: as extremely low water pressure

Current System Information:

New Information:

Meter # 1:

33076067

Meter # 1:

Meter # 2: Radio 33076067

Meter # 2: Radio

MXU#:

MXU#:

Current Reading 6/20/2015

Current Reading

Type of Meter:

Type of Meter:

Year MFG:

Badger 2006

Year MFG:

GPS - Longitude

GPS - Latitude

Employee Signature(s): (

Date Completed 7-27-15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Tim	ne Started	Work Complete	angagar . 13 ga asa saba da Nadiji Afradi Ar Na
Loc#	a parte nya harang s	Master Meter #	uju ja
Date 7/1/2015	Account	#SI	EQ# 121
Name: Charles Address: P.O. Bo	s Tipton ox (KY 41224]		# (
Location: Boon	y y to the same same same and the same of	v; box is on BANK IN FRONT	
Type of Work: Co	omplaints	in the first safetimes made making when requiremental productions are appropriate and the second safetimes and	enecenantia finan universida situata fo com tanuata e pipina
Material Used: Customer Line In	spection:	one)	in particular many according to the very
	extremely low pressure for a week	=90psI A+	box
	t System Information:	Ne	w Information:
Meter # 1:	99691122	Meter # 1:	nyuunuunaanannuunaanannan oo
Meter # 2: Radio	a s dana si sada wang sana sa a sa Si Sada sayo normorin	Meter # 2: Radio	any manager of a great manager language and a fine surprise to
MXU#:	to a final control of the control of	MXU#:	mangan maga maga ngananganan digi a sa sahan sa
Current Reading	6/20/2015 520	Current Reading	<u> </u>
Type of Meter:	Badger	Type of Meter:	in any or an order of the state
Year MFG:	1999	Year MFG:	The second of th
GPS - Longitude	O manufacture of the second of	•	O and the second of the second
Employee Signat		Date Comple	eted $7 - 23 - 195$

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 150700037

Time	Started	Work Comple	te
Loc#	e sign of the confession of the sign of	Master Meter #	e significant proportion of the second state of the second
Date 7/6/2015	gam van colum 4 sams so so so so	Account #	SEQ # 117
Name: James Wi	allegant and a contrapant to a reason from	d frame, N. c	Phone #
	lar Frk Rd , KY 41203		Employee Rainbo
,,,,,		and drive on right, green doubl	e wide
ELK CRE	na esta anno esta esta esta esta esta esta esta esta		in a section of the s
Type of Work: Com	Fix " " 1 100 men 5.2 4		engan in the common desired to the common de
Material Used:	Grad a line	entee an the	tank went Empty.
Customer Line Insp	ection but he g	at meeter rou	rue fix the
Comments: no water	er line en	Sunday	Salamatika ya mara a maja sa m
Current S	ystem Information:	n Kir Samman ang Kiri, ang mga mananan mangan ang mangan ang mga Tanaharangan	New Information:
Meter # 1: 47	7823585	Meter # 1:	yy y har y di Toury e di soondeyn'i 12 may, 'y hêmmê diy, reke €2 . der rek
Meter#2: Radio	aya - waxayaa dana waxaya ka aa aa aa aa waxaa waxa	Meter # 2:	Radio
MXU#:	and any angle of the comment of the comment	MXU #:	para manganananananan sa
Current Reading 6/	20/2015 719	Current Re	eading 0
Type of Meter: Se	ensus	Type of Me	eter:
Year MFG: 19	993	Year MFG	- Annual constitution and annual and annual and annual ann
GPS - Longitude 0	فستسميس دوم ودفوده مريهاي	GPS - Lati	tude O
Employee Signature		R T Date	Completed 7-6-15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Time Started	W	Work Complete			
Loc#	Master Me	ter#			
Date 7/9/2015	Account #	SEQ # 107			
Name: Kirby PREECE	g y www.	Phone #			
Address: PO BOX	e and 3 Key 1999	Employee Rainbo			
INEZ , KY 41224	, 5	en e			
Location: Howard Spence Rd, Af	ter crossing Inez hill,1st dri	e on left up on hill.Tan trailer			
	, in the second of the second	The second of th			
ROUTE 40 WEST	మీ	,			
Type of Work: Complaints		Suit the approximate of the state of the sta			
Material Used:	د مشاهد پیشرورست	in the second of			
Customer Line Inspection:	S water now	and the second of the second o			
Comments: customer has no water	* ** ***	and the second of the second of the second			
O Oversom Informati	_	New Information:			
Current System Informat	ion:	Blacker dt 4.			
Meter # 1: 90819244	w is the				
Meter # 2: Radio	<i>्र</i> ्क व्यक्तित	Meter # 2: Radio			
MXU #:	, , , * *	MXU#:			
Current Reading 6/20/2015 1536		Current Reading 0			
Type of Meter: Badger		Type of Meter:			
Year MFG: 1990	_ 233	Year MFG:			
GPS - Longitude 0	e See	GPS - Latitude 0			
e	v ye	and the second of the second o			
Employee Signature(s):		Date Completed			

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO #

Time Started Vi	vork Complete
Loc# Master Me	eter#
Date 7/13/2015 Account #	SEQ # 108
Name: MARY STANLEY	Phone # ()
Address: PO Box WARFIELD , KY 41267	Employee Troy Horn
	ا الله الله الله الله الله الله الله ال
Type of Work: Complaints	are conserved to a constitution to the contract of the contrac
Material Used:	and the second of the second o
Customer Line Inspection: Was pumping into E	IK Creek 4 it took their pressure down
Comments: no water	
Current System Information:	New Information:
Meter # 1: 70616608	Meter # 1:
Meter # 2: Radio	Meter # 2: Radio
MXU #: 13154928	MXU #:
Current Reading 6/20/2015 353	Current Reading 0
Type of Meter:	Type of Meter:
Year MFG:	Year MFG:
GPS - Longitude	GPS - Latitude
in the second of	المراجع المحاجب والمراجع المحاجب والمحاجب والمتجاجع
Employee Signature(s):	Date Completed 7-13-15

Martin County Water District 387 East Main St., Suite 140

Inez, KY 41224

WORK ORDER

Time Started	Work Complete
Loc#	Master Meter #
Date 7/2/2015	Account# SEQ# 96
Name: JASON MAYNARD Address: Cassell Br INEZ , KY 41224	Phone # Employee Rainbo
Location: Cassell Br CASSELL BRANCH	
Type of Work: Complaints	Digital and a second of the se
Material Used:	and the second s
· '	Pressure was #153
Current System Informati	on: New Information:
Meter # 1: 29541979	Meter # 1:
Meter # 2: Radio 29541979	Meter # 2: Radio
MXU#:	MXU#:
Current Reading 6/20/2015 457	_
Type of Meter: Badger	Type of Meter:
Year MFG: 2004	Year MFG:
GPS - Longitude 0	GPS - Latitude 0
Employee Signature(s): R.J	Date Completed 7 -2

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 150800183

Time Started	Work	Complete
Loc#	Master Meter	# 10 C 25 C CONTROL CO
Date 8/19/2015	Account#	SEQ#7
Name: William Scott		Phone # / 222
Address: P.O. Box		Employee Justin Scott
Inez, KY 41224	a graph and a graph and a graph of the first	em Cv
Location: Newberry Ln. Inez. Slate of	colored house on the left.	and an analysis of the second
ewberry Ln		and the contraction of the contr
Type of Work: Complaints		and the control of th
Material Used: Customer Line Inspection	shecl)	
Comments: customer said water stack	The state of the s	and the second supplication of the second se
Current System Information	na esta en la	New Information:
Meter # 1:	Me	ster#1:
Meter # 2: Radio	Me	eter # 2: Radio
MXU#:	M>	(U #:
Current Reading 0	Cu	rrent Reading
Type of Meter:	Туј	pe of Meter:
Year MFG:	Ye	ar MFG:
GPS - Longitude	GF	PS - Latitude
Employee Signature(s):	u v v s vecta agripovamente e qui spillabel la 7 v v le discende seanne	Date Completed 8-25-6

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

150800117

Time Started

Work Complete

Loc#	y was a summary of the second	Master Meter #	w. w	· zh·v
Date 8/11/2015		Account #	SEQ # 82	"z se
Name: John G	ر ع∈ متناه المستقد بين الم	مسورتاتشد د د بدر بروار و	Phone #	Scott
Address: P.O. Bo	ick, WV 25685	eletarium (m. sterim see	Linployee Justin O	e vig es
Location: Mar		rown double-wide w/chain li	nk fence.	
Мар	ole Dr	A service conduction of the service	Siring and Albert State of Sta	e main e
Type of Work: C	omplaints	in the second se	May Me you was care and a service of the service of	A A SAN TONING CO. C. C.
Material Used:		A)	ang tanan and an and an and an an and an	ه ۱۰ با سامود مشد .
Customer Line Ir	nspection I AG	Shed for		ya, e waa da
Comments: water	er is milky white		porter à la questife de la Palaciente de Contra de	parameter in the second
Curren	t System Information:	plater in an anti-	New Information	on:
Meter # 1:	94261289	Meter	# 1:	
Meter # 2: Radio	94261289	Meter	# 2: Radio	مديسفه موادر ر
MXU #:	سندي در د	MXU	#:	the things of the second
Current Reading	7/20/2015 2260	Curre	nt Reading	0
Type of Meter:	Badger	Туре	of Meter:	
Year MFG:	1994	Year	MFG:	يود عدد المراجع والمحافظ والم
GPS - Longitude	· , , , , , , , , , , , , , , , , , , ,	GPS -	- Latitude	e e e e e e e e e e e e e e e e e e e
	* * * * * * * * * * * * * * * * * * * *	e se generalismo e l	y Tydy sy bi c	iin.
Employee Signa	ture(s): 55	ene u de es áse.	Date Completed	20-15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Time Started	nondor. Compilipper v. 1,5	Work Complete	
Loc#	Master .	Meter #	
Date 8/19/2015	Account#	SEQ# 242	was Vy
Address: PO Box	andra see an emperiment of groups and	Phone # Employee Justin Scott	
Warfield, KY 41267 Location: App. 1 mile, blue ho	ouse on hill. Sheppard Ln		r ya, ángry
Type of Work: Complaints	Slip, 3 ft of	3(Line)	grans. +\$44-der
Customer Line Inspection:	and the state of t	o na man ag 🌓 - 3 - 3 an commercial - 4 conference a commence of the conference of	,. •
Comments: customer reporte	d Sheppard Lane is without wa	ner State broke main while clear	ญี่เก๋
Current System Inf	-	New Information:	æ;
Meter # 1: 29934524	, instancemental part of second \$0 .	Meter # 1:	; ;
Meter # 2: Radio	anne de la compansa d	Meter # 2: Radio	۰,
MXU#:		MXU#:	······································
Current Reading 7/20/2015	* *	Current Reading 0	,
	magnetic for the first terms of	Type of Meter:	
Year MFG: 2004		Year MFG:	
GPS - Longitude 0	an opposite a series and an experience of the	GPS - Latitude 0	.54
Employee Signature(s):	405 2M	Date Completed U-26-15	*. *.



387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Time Sta	arted	Work Complete
Loc#	Maste	r Meter#
Date 8/11/2015	Account #	SEQ # 234
Name: Billy Greer	Mandress Street War & S. J. J. S. S. S. C. Consenting	Phone #
Address: P.O. Box Lovely, KY 4	11231	
	ont Rd. Past Jackie & Alice Scott.	and the state of t
Type of Work: Compla	ints	المنطقة والمراد المستشف والمساورة والمستولة
	• •	مند المستقدة المستقدة المستومة المستقدة المستقد
Cuctomor Emo mopoca	å, a d 1920 kikanjelje – a – monten a a <u>"merer föllimin mi</u> teret semme	له ماه سداده در داه استجوالو در در در در استسبور برد و مستورین در مستود در در مستود در
Comments: low pressu	re for over a week - 70 pg	I. Bt billion and a second
. Current Syst	em Information:	New Information:
Meter # 1: 3300	1041 	Meter # 1:
Meter # 2: Radio 3300	1041	Meter # 2: Radio
MXU#;	nominable () on Crawd Virgo (insumpress of some	MXU#:
Current Reading 7/20/2	2015 183	Current Reading 0
Type of Meter: Badg	er	Type of Meter:
Year MFG: 2006	to a classification of the state of the control of the state of the st	Year MFG:
	S. a strange of S. as to protect the second of the second and the second of the second	GPS - Latitude
Employee Signeture(s)		Date Completed &



Inez, KY 41224

WORK ORDER

WO#

Time S	Started	V	Vork Complete	No Mark Contract Cont
Loc#	* Ang , r a a s	. Master M	eter#	ولا منصم
Date 8/6/2015	ers et what a Typica	Account #	enter , stop galactic () at the	SEQ # 595
Name: Maurice &	Rita Milis	and the second of the second o	Pho	ne#
Address: 3 Rock	thouse Road		Emp	ployee Justin Scott
	k , Ky 41262	Soften in the same	3 ¥ma	
Location: Mills Lane,	, 1st house, meter on ri	ght of driveway, bes	side fence 3 F	lockhouse Road
es so wish s	a se change of the second second	• •	ac er in enemaña ao ar e emicomendario.	
Rockhouse		er og prængre e grænere avon	k sekarahan e ^d — e anaman an metek	g and the state the state of th
Type of Work: Comp	olaints			in a fact that the second of t
Material Used:		1)200}	g han an as " San sounda" as an seriender en an	mages of the graph and phonomenous of the same of the
Customer Line Inspe	ection:			a glass open of the months of months of the contract of
Comments: requeste	ed a flush, water stinks	The Shed	€ 38.	ومنائد المكامد المسامرة في ويرسو
Current Sy	stem Information:	A A A A A A A A A A A A A A A A A A A	ng k na [®] nada ada her adan d a banda da banda da ba nda da banda	New Information:
Meter # 1: 967	725763	man range (°).	Meter#1:	e. Se winds & paramin republic to the text
Meter # 2: Radio	y sisa y in insu	*	Meter#2: Radio	غ م م م مسلمانسد قالمين :
MXU#:			MXU#:	garan garan dan kanan dan dan dan dan dan dan dan dan dan
Current Reading 7/2	0/2015 1550	a a bangir mm	Current Reading	0
Type of Meter: Bac	dger	The first of the second	Type of Meter:	°ì ∨e
Year MFG: 199	96	Journey .	Year MFG:	
GPS - Longitude 0	w	*** **	GPS - Latitude	0
*			ve 19 3	v ve
Employee Signature((s) full -		Date Com	pleted 8-11-15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

ang ning terminang ning ning ning ning ning ning ning
Work Complete
Master Meter #
Account # SEQ # 158
Phone # 1
Employee Justin Scott
and the state of t
hite w/black shutters used to be there now going to be putting a
as and the contract of the con
The second of th
e anner y se estatal annario arrelà distribit e e e e e e e e e e e e e e e e e e e
Checked Pressure, Read over 100ps;
Checked Pressure, Read over 100gs; Checked for Milky water, more visible at
New Information:
Meter # 1:
Meter # 2: Radio
MXU#:
Current Reading 0
Type of Meter:
Type of Meter: Year MFG:
•

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

150700185

Time Started

Work Complete

Loc#

Master Meter #

Date 7/27/2015

Account #

SEQ # 98

Name:

HAROLD GOBLE

Phone #

Address: P.O.BOX

Employee Justin Scott

INEZ

, KY 41224

Location:

/ Eli Rd

MIDDLEFORK RD.

Type of Work: Complaints

Material Used:

Customer Line Inspection 7

1 ps

At 604

Comments: very low water pressure

Current System Information:

Meter # 1:

92701640

Meter # 2: Radio

MXU#:

Current Reading 6/20/2015

1420

Type of Meter:

Badger

Year MFG:

1992

GPS - Longitude 0

New Information:

Meter#19

Meter#2: Radio

MXÛ#:

Current Reading

0

Type of Meter:

Year MFG:

GPS - Latitude 0

Employee Signature(s):

July 1

Date Completed 8-3-15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

150700188

Time Started

Work Complete

Loc #	Master N	/leter#	:	
Date 7/27/2015	Account #	SEC	Q# 20	
Name: Sherry Moore		Phone #	•	`
Address: P.O. Box		Employe	e Justin Scott	
Lovely, KY 41231	And the second second	general con-		
Location: Locust Crt. 1st house o	on the right.			
	namenta de de la composición de la	A ABANAMA SA	· ·	
Locust Crt	the same of the same of	www.es.ye s	pates.	
Type of Work: Complaints	· · · · · · · · · · · · · · · · · · ·	nora w be 64 towe		
Material Used:				
Customer Line Inspection		·		. ,
Comments: has bad odor to water	Re doing a	211 the w	re en loca	STCH
Current System Informati	وها المراج ما المراجعين	السابق يعابدية معامدة	Information:	*
Meter # 1:	a siring air in	Meter # 1:	· · · · · · · · · · · · · · · · · · ·	
Meter # 2: Radio	ža vištam la	Meter#2: Radio		
MXU#:	. <u> </u>	MXU#:	am a sa s	*
Current Reading 0	2 4 8 4 AN	Current Reading	0	7° ,
Type of Meter:		Type of Meter:		-
Year MFG:	,.	Year MFG:		
GPS - Longitude	••	GPS - Latitude	<u>.</u> »	*
,		er ses s		
Employee Signature(s):	H CS, Wi	5 Date Complete	d 8-37	5

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Tir	ne Started	Work Comple	ite
Loc#	where strains who we we control	Master Meter #	and the second s
Date 8/5/2015	The state of the s	Account #	SEQ # 473
, -x	1 FITCH	· processor o sector of the se	Phone # (
Address: (b		erannen pa. Er er aug ry pag va	Employee Justin Scott
INEZ	[KY 41224]	in the second se	
Location: At	bs Ln LEFT FORK.4th house	. White w/blue shutters.	annin i militar i Sandardo de deservició de la composició
ABBS	LANE	e granden er men en e	Angermannia (angermannia) Angermannia (angermannia) Angermannia (angermannia) (angermannia) (angermannia) (ang
Type of Work: C	omplaints		r janana a jamangu jalaya sak apangu am kenyu benjabbi,
Material Used:	· · · · · · · · · · · · · · · · · · ·		and the second section of the second section of the second section of the second section secti
Customer Line In	spection	Comments of the second of the	العادوة والمعنو الإستراديات فللمسترد المستند
Comments: extre	emely low pressure ラブ	+78 PSI	At book
Curren	t System Information:	emilje s trouwermen ven tie is vietnemen in it worde seems of the seems of the seems of the seems of the seems	New Information:
Meter # 1:	94056605	Meter # 1:	e analos salos sum a plación se estato como construir se estatorios se
Meter # 2: Radio	no residente de la compansión de consciente en la la consciente en la la consciente en la c	Meter # 2:	Radio
MXU#:	The A second accordance to the second accordan	MXU#:	o tomonomic och to commente o etter och och och och
Current Reading	7/20/2015 849	Current Rea	ading 0
Type of Meter:	Badger	Type of Me	ter:
Year MFG:	1994	Year MFG:	و ده د د دود ۱۹۰۶ مغلف میدسود بیشود میشود
GPS - Longitude	0	GPS - Latitu	ude 0
Employee Signat	ure(s) 5	Date (Completed 8-5-15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Time	Started	, V	Vork Complete	8 M	
Loc#	n ye was s sugar s ye yearen	Master M	eter#	regitad bankyoon was n	of govern
Date 8/6/2015	Sangar Si were sac	ccount#		SEQ # 218	9 <u>u</u> v
Name: Miranda I	McCoy		Phone	e# (
Address: P.O. Box Beauty, J	Y 41203	ancomo (2) (2) (2) (2) (2) (2) (2) (2) (2) (2)	Emplo	oyee Rainbo	,
end and	Elk Rd. Across from Water	Tower, grey trail	er	and the second of the second o	e de la companya de l
Type of Work: Con	nplaints tack	2 case	of gal.	= 8gall	
Material Used:	ر و الإستنسلومون و ما ماه العالم العالم الماه الما	an demokratik sa sa sadanda sa sa sa	manimina skiringa ka	e same access of the graph of the second	an english
Customer Line Insp	pection:		A SHAMMAN PARKET TO THE	. ,	
Comments: custon	ner has no water \(\int \hat{\lambda} \)	ceds wo	1	company of the company of	synnes of the gathere
Current S	System Information:	adalan samutuk an 30 - an an anna an Arriz 3 - an an		ew Information:	grand in complete
	9935189	tandara ar	Meter # 1:	was a straigh of the care of the contract of t	a pra boadrongsjaja
Meter # 2: Radio 25	9935189	• "	Meter#2: Radio	الما و يا تعلق معملوه در و الاستأنيس بريان	پېسىدخۇنۇر ئىق
MXU#:	hit k to see a garanama o salah	-	MXU#:	العدم معامل المعامل ال	ay as a crisis
Current Reading 7/	20/2015 397		Current Reading		Car Shape + C
Type of Meter: B	adger	wty w	Type of Meter:	e and the second of the second	4 65 66 4
Year MFG: 20	004 		Year MFG:	maineus nasāmi sas	olina come
GPS - Longitude	· Bout of the second of the se		GPS - Latitude		2. 2°24
Employee Signature	e(s): RJ	The second se	Date Comple	eted 8-6-/	5

Martin County Water District 387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Time	e Started V	Vork Complete
Loc#	Master Me	eter#
Date 8/7/2015	Account #	SEQ#99
Name: Ronnie	Mills	Phone # V. Marine & M
Address: PO Box Inez, KY		Employee Rainbo
Location: 5.8 miles	and analysis that the state of	e on right, 2nd house on Meadow Lark Lanee, tan
TURKE	Y	
Type of Work: Co	mplaints oby some the someoning classical expenses of a con-	enegan takka tengan ngapatay ngapan ngapan na enemata ngapan
Material Used:	Anna Comment of the C	January - John Washings
Customer Line Ins	pection 100 PS; @ loo	K ; issue on costomer's side
Comments: no wa	iter 	· Societable chains describe to the second of a
Current	System Information:	New Information:
Meter # 1:	99691595	Meter # 1:
Meter # 2: Radio	types of the state	Meter # 2: Radio
MXU #:	Amin's a construction of properties.	MXU#:
Current Reading 7		Current Reading 0
Type of Meter: E	Badger	Type of Meter:
	1999	Year MFG:
GPS - Longitude	the second secon	GPS - Latitude
Employee Signatu	re(s): \(\bar{\sigma} \bar{\sigma} \), \(\bar{\sigma} \bar{\sigma} \)	Date Completed 8 7 \S

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER



Date Completed 9-28

		WO#	15020	0011	A: Reset in	Man in 48	
Tia	me Started			Work Complete			
Loc#			Master N	/leter#			
Date 2/3/2015			Account #		SEQ# 40	0	
Name: JIM W	НІТТ			Pho	ne#		
Address: P.O.B			·		ployee Clyo	de Stanley	
TOMA	HAWK ,	KY 41262					
Location: St	nirley Moore Ln						<u></u>
*							
ROUT	E 40 WEST		$\left(\begin{array}{c} 1 \\ 1 \end{array} \right)$	one			
Material Used:					7.		·
Customer Line I				•			
Comments: cus	1. 1			ed up while installii		Drain	Looke
Fine							
	nt System Infor			4	New Inform	nation:	
Meter # 1:	29935046			Meter#1:	<u></u>		
Meter # 2: Radio	·			Meter#2: Radio	· <u></u>	<u>. </u>	
MXU #:			negovingor more amenine miritale	MXU#:	·		
Current Reading	1/20/2015 2	91	-	Current Readin	g <u> </u>	0	
Type of Meter:	Badger			Type of Meter:			
Year MFG:	2004			Year MFG:			
GPS - Longitude	e 0	s		GPS - Latitude	0		<u></u>

Employee Signature(s): 35

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#



Tim	ne Started	Work Complete			
Loc#	تكديدة مسودو ماسادي	Master Me	iter#		
Date 9/18/2015	*** ****	Account#	SEQ # 69		
Address: lu	E DIALS ssell Workman Rd	a falt a seasonning time	Phone # (Employee Rainbo		
	· , , , , , , , , , , , , , , , , , , ,	ه ده اهممستاندهای مورد اید بریستاندین به	Workman Rd.Go right up on hill.Last house.		
Type of Work: Co	Irod a	2 Dane	tine blaw it aff		
Comments: no w	, ~ ~ ~ , , ~	- services and services are services as	و چې ترکیم د د میکاند د د د د د د د د د د د د د د د د د د		
Curren	t System Information:	ganing dangga taluk a ganininggat na	New Information:		
Meter # 1:	19667238	munt to v	Meter # 1:		
Meter#2: Radio	e A wheregov **	u spic appe	Meter#2: Radio		
MXU #:		- a regery pa , Noti Weer Y	MXU#:		
Current Reading	8/20/2015 611		Current Reading 0		
Type of Meter:	Sensus		Type of Meter:		
Year MFG:	1966	ari ka	Year MFG:		
GPS - Longitude	4 13 4 14 34	13- # ABV	GPS - Latitude 0		
Employee Signat	10 -	The control of the co	Date Completed 9-18-15		

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#




	Time Started		Complete
Loc#	and the second of the second o	Master Meter	# Administrações de la companiente del companiente de la companiente del companiente de la companiente
Date 9/15/	/2015	Account#	SEQ# 220
	Miranda McCoy	g garante e series e	Phone #
Address:		eespax n , s n h n n n n n n n n n n n n n n n n n	Employee Justin Scott
Location:	1 Big Elk Rd. Across from Wate	er Tower, grey trailer	ومقسمه سادونو وسافتتكو مذورها الاسترامية مديناه والانتجاز الأميل الانتظام كالمستسك سيست
Type of W	ork: Complaints	ommonomic 200, C 000 gg 8 on 60 th sign # 150 th 150	and the second s
	Line Inspection	o.cg · manage water. Were the commencer to the commencer	
Comment	s: no water Rain to 15	looking Afif	has water now
	Current System Information:		New Information:
Meter # 1:	in "ours, in 8 a.s.s. roughes were laborate and transformation for graduate the \$100.0000000000000000000000000000000000	Me	eter # 1:
Meter#2:	Radio	Me	eter#2: Radio
MXU #:	manuschina and and solve on the first control and the first	(M	(U # :
Current Ro	eading 0	Cu	irrent Reading 0
Type of M	eter:	Ţ	pe of Meter:
Year MFG	The state of the s	Ye	ear MFG:
GPS - Lor		Gr	PS - Latitude
Employee	Signature(s):	ado e pada de cos que representamente esta en elemente en el compresentamente en el compresentamente en el comp Agreco resulte a commercia de san el por energista e	Date Completed 9-15-16

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#



Time	e Started	Work Complete	****
Loc#	N	laster Meter #	wayaannaan a markan di sa j
Date 9/1/2015	Account #	£	SEQ# 30
Name: WENDE	LL STEPP	Phone	e# (
Address: P.O. Bo	X	Emplo	byee Justin Scott
,	n Oak Dr., red brick home DY AVE.	are was an are a great of the	and the same of th
Type of Work: Co	mplaints	Company (Section 4) See Company (Section 4)	g garage
Material Used:	g magains see a facilities see a se	and the constraint of the transfer of the constraint of the constr	was a done or a new orking, a series
	ressure Mari Passible Edge of	leak on se Black Top at	Bottom of drive
	System Information:		ew Information:
	70616430 70616430	Meter # 1: Meter # 2: Radio	The second secon
	13155681	MXU#:	was program in the same and an asset of the
	8/20/2015 191 / /92	Current Reading	0
Tunn of Motor	, a pro-sur's someone we	Type of Meter:	with the control of the control of
Year MFG:	The state of the s	Year MFG:	5,
GPS - Longitude	ه المنظم المعارم إليان المنظم المعارم المنظم المعارم المنظم المعارم المنظم المنظم المنظم المنظم المنظم المنظم	GPS - Latitude	e graphers
Employee Signat	ure(s): JS J	Date Comp	oleted 9/3/17

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#



Time Started	, ,	Work Complete			
Loc#	Master	Meter#	man and a second se		
Date 9/4/2015	Account #	SEQ	# 69		
Name: DEBBIE DIALS	2000 se s s s s s s s s s s s s s s s s s	Phone #	<u>(</u>		
Address: Russell Workman F	Rd		Rainbo		
LOVELY	11231	Principles of the Secretarian Association of Association (Control of the Secretarian Control of the Se			
Location: Russell Workman	Rd of 292 Long Branch Rus	ssell Workman Rd.Go:rigt	it up on hill Last house.		
ا وها الله الله الله الله الله الله الله	A A C	ust a son num y qui mininapiminapimini. Amerikansk si ngtoga ergtoga ergen usyund	Professional and the second se		
merce of the state of the green making of a		andre a commence and the grown announce and consequently on a square to the offer of	and a second		
Torres of Marchy Complaints					
Type of Work: Complaints	the discussion in a way or profes and accommodate to built at the discussion of the	A Company of the state of the s	idanian in international game and specific parametrization of the Same Section 18		
Material Used:	موسيسه سدي ي د د د د د د د د د د د د د د د د د		such what can be a second to the second to t		
Customer Line Inspection +	ned Oreant	e look is P	eren St. L. Gallahara		
Comments: no water	Janes Janes				
Comments, no water	C. Land Communication of the C	and the second s	anagarigaan ka rammama ee sen oo		
Current System Inforn	nation:	New	Information:		
Meter # 1: 19667238	Track & data of American Control of Control	Meter # 1:	ang kangalan finanganan ang kananan ang kananan kananan ng kananan ng kananan ng kananan ng kananan ng kananan		
Meter # 2: Radio	ou suigh community communities strangers communities c	Meter # 2: Radio	There in the tenth of the second section of the second second		
MXU #:	and a familiar and a	MXU#:	Se any manifestation and the second s		
Current Reading 8/20/2015 61	1	Current Reading	——————————————————————————————————————		
Type of Meter: Sensus	Minganian kana and a Min - 1 d - 2 c	Type of Meter:	الرواية المراجع والمماهية المستعدم المستعددة المستعدد المستعددة المستعددة المستعددة المستعددة المستعددة المستعددة المستعددة المستعدد المستعدد المستعدد المستعدد المستعدد المستعددة المستعدد المستعدد المستعدد المستعدد المستعددة المستعدد المستعدد المستعدد المستعدد المستعدد المستعدد المستعدد المستعدد المستعدد		
Year MFG: 1966		Year MFG:	i go November (a) — way a — wax yake yayan aka een hii hay o 18		
GPS - Longitude 0	No. 1. February	GPS - Latitude 0	Stabilization of the second than the second		
ا د دورو دولو اها اهوا این استانه دارد دوروستیست پردو این این این این این این این این این این	A company magnification of 644	way and the same of the same o	* 4 9 1 - · · · · · · · · · · · · · · · · · ·		
Employee Signature(s):		Date Complete	a 114115		

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 150800266

		WO#,	150800266	**	PARE	A Pepa
Tir	ne Started	way we have a manager of the second	Work Cor	mplete	LANI	
Loc#	uu jaan wa i u galigana u jiga wa wa	and a market of the state of th	Master Meter #	; ·	N	: ,
Date 8/28/2015	سيدو المعادة المداد	Accor	unt#	SE	EQ# 125	e salahan N
Name: Charle	s Tipton	. ya a ruun kan joonaaning Kananina	i a si	Phone :	# (, () AV) M
			on a sulace of me to his min the in .		ee Justin Scott	
INEZ	, KY 41	224]				
Location: Bo	oone Br of Eli Rd	ast house in hol	low, box is on BANK	IN FRONT	y grawy d	5 / · V · / · · · · · · · · · · · · · · ·
/ .as/ 1	** * ** ** **	i a tan-en le more mon	n eren hannandischlich at en neue e rece v	3 · · · ·	e expert & t g	· . p · seep · Anderson Anderson
BOON	E BR.	si is was a war.	76 m² u		4.64° MAN, MA	s to the second
Type of Work: C	omplaints	All the second s		~	w speck s	a e vara v jaktis
Material Used:		· · · · · · · · · · · · · · · · · · ·	() On	ne)	, and the minimum as the	ali, y E. Salahyo e e sysaye elempooni
Customer Line In	nspection:	N. 10. / N.	The Control of the Co	.,	المراقع	ga yan isin dalamar in kan dalambara bandamining redigi
Comments: VEF	RY LOW WATER	PRESSURE	? Needs	Hooked	Up 10	maio
, , , , , , , , , , , , , , , , , , ,		مه د خو خموان و	en e dem y almente entre entre Antonio (Nel estre estre en 18 milles est	* - *	w Information:	ويور فالأعوام - أو ويألمُلُوا وفي تستيب الريف وي أن
Meter # 1:	99691122	adianapotong u s n · · · · · · · · · · · · · · · · · ·	Meter	# 1:	. SKYLI IS LABANGASLI M.	a sancon e che è monte depet
Meter # 2: Radio	S. S. Salama an allegations	and a second and a second as a second and a	Meter	# 2: Radio	and to be alphaness, by a manner of the states	Signal Street St
MXU#:	or the continue of	Same and a substitution of the substitution of	MXU #	# : ::	· lase of the second	51 Speed regions demande de 1
Current Reading	7/20/2015 52	4	Currer	nt Reading	· · · · · · · · · · · · · · · · · · ·	. v v
Type of Meter:	Badger	> > Section with the section of the	Туре	of Meter:	skramen an majetin britain in	. Á is e s scrábas
Year MFG:	1999	e constate a manage a militaria.	Year N	/IFG:	sa a di a a a a a a a a a a a a a a a a a	sa, al sulpage o or general actions
GPS - Longitude	. 0	Chamberdan Information	GPS -	Latitude 0	to save .	against a section of the section
a source of	ماسد است	the transmission of the second second second			د ۶ خو مي و. ه	E grady step triv
England Ciana	·····(a).		T	Joto Comple	tod 9/4	1.1

Martin County Water District 387 East Main St., Suite 140

Inez, KY 41224

WORK ORDER

WO#

Tir	me Started	Wo	Work Complete				
Loc#	es e Maria de agraça e e	Master Met	er#	يعاد معيدمة			
Date 10/23/2015	Comment of Section .	Account #		177			
Name: Jimmie	e Slone	er er er endem anderen er	Phone #	in the state of the			
Address: P.O. B	OV .	the plant of the control of the second of th	Employee I	ustin Scott			
inez, k	Y 41224	· · · · · · · · · · · · · · · · · · ·	nate A				
		vater. Off Moore Branch. B		د د سرو			
	is rates companied to papers seems	g galamania o punuma vara or o spanii dangaya ja a a a	and the second control of the second	· · · · · · · · · · · · · · · · · · ·			
	olit Rock Hlw	war in and the foreign and the same and the	THE PROPERTY OF THE PROPERTY O				
Type of Work: C	omplaints	Non-marine of the comments of the confirmation	isada (district) og delementy er skriptmæser dele	e e e e e e e e e e e e e e e e e e e			
Material Used:	gramma. en qui menting que	i e Aminimistra pro Communicatore e dispussamento de co	disalina anagan sa ara matanin pandipena a ya ka sa matanin a sama a sa sa sa sa	indig days which diddig of y decimal production con-			
Customer Line Ir	nspection:						
Comments: water		1CWD checked his meter	vesterday	شخب الخاشية			
Curren	t System Information		New Info	•			
Meter#1:	94788708	<u></u>	Meter # 1:	we will supplied the second second the second second the second s			
Meter # 2: Radio	94788708	***	Vieter # 2: Radio	gagi - a ga a da			
MXU #:	Samery of a viving more of the Street Systems of the same of the s	communication .	MXU #:	and the second s			
Current Reading	9/11/2015 254	communications consists of the first of the	Current Reading	o comment of the comm			
Type of Meter:	Badger		Type of Meter:	and the second s			
Year MFG:	1994	Name and the few sections	Year MFG:	in the second contract of the second stable of the second			
GPS - Longitude	- market in the second of the		GPS - Latitude	A Land			
Employee Signat	ture(s)	ander er er en gegenge ommer en er	Date Completed	1923/5			

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 151000190

Time S	tarted	Work Complete				
Loc#	was en som ommenten en ste me	Master	Meter#	e e e e e e e e e e e e e e e e e e e	What so an rough like's the hour	
Date 10/21/2015	3v \ 2.6 . y min si	Account #	,	SEQ# 821		
Name: Pauline Ha	yes .	gree systems and an approximate the state of	Phor	ne# .;	e opiajoras en en	
Address: Wendy	St		Emp	loyee Justin So	ott	
Warfield, K	Y 41267	many landage to say in succession and the successio	minner y > quy diporterio			
- was a series of the month any	en e	d, on right, Wendy S	St, 2nd trailer on righ	t, white & brown	t de la companya de l	
Type of Work: Comp		annual states for the states of the states	and the second second	ann à my anne a conspiração sacabemble e m	man mining a state of the second of the seco	
Material Used:				المداد مستست النواد المواشي الأراد والراد والم	anne gy y sen's de depot de verseemen V y de v	
Customer Line Inspe	1	Thed)		مستخدم میدود کار در	al San	
Current Sy	stem information:			New Informatio	n:	
Meter # 1: 29	935240	naganadaya in gotz maga kwasi w	Meter # 1:	* *****	e especiminar per ancie e v. c. met.	
Meter # 2: Radio 29	935240		Meter#2: Radio	Andrew morning of the forest of the sec	margine yila sab han v	
MXU#:			MXU #:	jumaniani, minen mijeri, m	grang against a sour ye is a distributed.	
Current Reading 9/2	20/2015 247	coloquia 5 anno monerom to const	Current Reading	,	THE OF THE MENTION AND A SALE CONTINUES	
Type of Meter: Ba	dger		Type of Meter:	مالاستدر فأنوقا مجتلأكات كأدبعت ألحث	مدين يدور ي د د د د د د د د د د د د د د د د د د	
Year MFG: 20	04	the second secon	Year MFG:	s opening a state of the state	an en sentre sentre ser sentre contra d'antique y y l'estrante e s'entre que se altra entre entre e	
GPS - Longitude	arrayor ago of f Scottly - months indicate a second analysis of the second and th	and the same of th	GPS - Latitude	annatas pria Naibaki di	y symposition a real management	
Employee Signature	(a): (5)		Date Com	pleted 10	-21-15	



387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Tin	ne Started	Work Complete	, , , , , , , , , , , , , , , , , , ,
Loc#	, , , , , , , , , , , , , , , , , , ,	aster Meter #	y w warman on a same of the second of the se
Date 10/21/2015	Account #	The same which have the same with the same	SEQ# 178
Address: PO BO	. KY 41224	And the commence of the party of the commence of	ne # (60 loyee Justin Scott
signe go	elit Rock Holw	Santa Camidy — all transmission provincy — — — — — — — — — — — — — — — — — — —	A THE SECRET SECRETARY SEC
Type of Work: C	omplaints		and promonents of a Section management of the section of the section of
Material Used: Customer Line In Comments: has	spection low water pressure 24 D	9)) STA+	
Curren	t System Information:		lew Information:
Meter # 1: Meter # 2: Radio MXU #:	89107955	Meter # 1: Meter # 2: Radio MXU #:	
Current Reading	9/20/2015 1699	Current Reading	The second section of the second second section is a second section of the second section of the second section sectio
Type of Meter:	Badger	Type of Meter:	entrine en 17 de se de manuel entre des la
Year MFG:	1989	Year MFG:	anger 1 state de maintenance de la secono de la compositione de la com
GPS - Longitude	0	GPS - Latitude	0
Employee Signat	rure(s):		oleted (0-22-/5

Martin County Water District 387 East Main St., Suite 140

Inez, KY 41224

WORK ORDER

WO#

Time Started	v ^4 ·	Work Complete			
Loc#	Master I	aster Meter #			
Date 9/29/2015	Account #	SEQ#	t agama, y Jos glanfifi. Adam a schringenig in is		
Name: Thomas Delong repor	ted	Phone #	a a sua a sua a sua sua sua sua sua sua		
Address:	" M. S. L. 40 (MOS). The second and analytic finance	Employee Cly	de Stanley		
Location: at the mouth of Big Br	anch; Water Dept cut across and needs repaired	road a few years ago to exten	d water line, it is now		
Type of Work: Complaints	anne e e e e e e e e e e e e e e e e e e	and the second s	lady and government and another military of the programme		
Material Used:	oo ahaa soo ka aa a saama saashahaa saashaha saa soo ka saashaan a saadhaa	and the second s	and the second s		
Customer Line Inspection: Comments: need 5 blace	k toped		agenering out and a pinka of the and a time. He is given a time.		
Current System Infor		New Infor			
Meter # 1:	on de men (ils menumente propriete p	Meter # 1:	manus anglides an amit districts out to North anneas mission or ann		
Meter # 2: Radio	a to see may to min months of the contributions	Meter # 2: Radio	ng stone was sine is in the state of		
MXU#:	Communication in Special Schools and Communication Schools and Communication Schools and Communication Schools	MXU #:	and the second s		
Current Reading0	y y' wy na y nadeolionad demande	Current Reading	0		
Type of Meter:	and the side of the second	Type of Meter:	and the second s		
Year MFG:	NOTE IN THE CONTRACT AND THE CONTRACT OF THE C	Year MFG:	kanangaranga di salah garaji kalaman da salah		
GPS - Longitude	Service Sections (Section)	GPS - Latitude	العائم محمد في الساح مسلم يما له المسلم بالساء		
Employee Signature(s):	and you have a second and a second a second and a second	Date Completed /	6-21-18		

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Time Started		Work Complete			
Loc#	on the same of	Master Meter	#		
Date 10/9/2015	er of the control of	Account #	SEQ# 377		
Address: Vioni	Y MAYNARD tgomery Lane KY 41514	A see since the contraction of t	Phone # (Employee Rainbo		
		A which is a second to the sec	e y la del Amerikando - la Servicio en en el el elegistra amazando el el actuarizando el el el el el el el el e En el		
Material Used:	omplaints but a some suit as a some		towit Shaw H 100Ps1		
	pressure		in the second se		
	t System Information:	Telegraphic Schools and during the control of the c	New Information:		
Meter # 1: Meter # 2: Radio MXU #:	47823709	Me	eter # 1: eter # 2: Radio		
Current Reading	9/20/2015 1631	Cı	irrent Reading 0		
Type of Meter:	Sensus		pe of Meter:		
Year MFG:	1993	Y e	ear MFG:		
GPS - Longitude	O	G	PS - Latitude 0		
Employee Signat	ture(s): RJ	S SEE SEE SEE SEE SEE SEE SEE SEE SEE S	Date Completed 16-12-15		

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO # 151000149

Time Started	Work Complete	
Loc#	Master Meter#	
Date 10/12/2015	Account # ' SEQ # 118	, ,
Name: James Williamson	Phone # (
Address: Poplar Frk Rd	Employee Rainbo	
BEAUTY , KY 41203	-1 3	
Location: Lower Poplar Frk, top of h	nill, 2nd drive on right, green double wide	
<i>2</i> = <u>-</u> 4	and the second s	
ELK CREEK	Das	
Type of Work: Complaints autatus	un lock an que all got their	*** *>>>
Material Used:	and the second s	ه
Customer Line Inspection:	. and the second of the second	13
	, commence of the second of th	
Current System Information:	New Information:	
Meter # 1: 47823585	Meter # 1:	
Meter # 2: Radio	Meter # 2: Radio	**
MXU #;	MXU #:	
Current Reading 9/20/2015 732	Current Reading 0	
Type of Meter: Sensus	Type of Meter:	•
Year MFG: 1993	Year MFG:	-Symin
GPS - Longitude 0		٠
Employee Signature(s):	Date Completed 10-13-15	911 to* 9

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Time Started		Work Complete			
Loc#		er#			
Date 10/5/2015	Account#	SEQ#			
Name: Ed Pack	a na namaya namanang ng la pala ka na a namaka maka na saka sa na sa	Phone # (6			
Address:Tomahawk Rd					
T	op annum general see to be common and the see				
Location: Tomahawk Rd,	washer 2000 - O commence and a commence of the				
ا در در میداند. و در در میده میداند میداند. و در این از این از این	The second second to the same second to the second second to the second	na a kan ing na kanamanananananan magaman ing manaman manaman na an a			
magazi pad ja manao					
Type of Work: Complaints	รร รู วันเจ้าของเหมือนุ่น ก.ก. ชุ . 250 ของพากแปกก ค.อ.พร ชุ (2)	Commence programme to the commence of the comm			
Material Used:	ili sandinini yillili wa yaya ili ili ili ili ili ili ili ili ili il	and the second s			
Customer Line Inspection	and a second	alima siele (r. 1918m.) see makke pin reconstructionel (3), do fan 'n monormanismisse, (3), (3), (4), (4), (4), (4), (4), (4), (4), (4			
Comments: need to repair driveway date	maged when fixing leak	and the second s			
Current System Information		New Information:			
Meter # 1:	(Nation references and a second	Meter # 1:			
Meter # 2: Radio	, * 2 ··································	Meter # 2: Radio			
MXU #:	A shadden and market A	MXU#: #: ################################			
Current Reading 0	and the statement of th	Current Reading 0			
Type of Meter:	the and a second control of the first of the second control of the	Type of Meter:			
Year MFG:	e especialistic est un est	Year MFG:			
GPS - Longitude	A district manager of the c	GPS - Latitude			
and the second	وه که همه پیشه بهای دی در در در مه چون روه که دومی دو				
Employee Signature(s): 2	سهدد دی رپوینی که عرکه س	Date Completed 10/2//S			

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO # 150800215

Time Started	Work Complete			
Loc#	Master	Meter#	. An inapper with the two decreases departmentages	
Date 8/25/2015	Account #	SEQ:	# 96	
Name: LLOYD HEDGES	ni o sa kikili	Phone #	rang an tanàna na ang ang abawang abbandan anakan	
Address: PO BOX	e van e ten andere andere andere	Employee	Troy Horn	
LOVELY , KY 41231	the region of the second secon		•	
Location: Riverfront Rd of Lovely;		past Railroad Bridge, whit	e house w/red shutters and	
Type of Work: Complaints	100			
Material Used: 30 ft of	111 Sewers	pipe, 240in	Couplers,	
Customer Line Inspection:		1 1 2 1 2 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1	and the state of t	
Comments: covered customer's drain w	hile fixing leak	. yu 3 8 89 4 6 38 66 66 6 1	a spilipania Turana a sa sa sa	
Current System Information:	ا کین دید ده ده متین	New Ir	iformation:	
Meter # 1: 95748911		Meter # 1:	A someone and other and respectable for the second	
Meter # 2: Radio	36 pt. c 3 / 3 value	Meter # 2: Radio	man na sanar Selar	
MXU #:		MXU#:		
Current Reading 7/20/2015 711	American State of A	Current Reading	0	
Type of Meter: Badger	With the second	Type of Meter:	, , , , , , , , , , , , , , , , , ,	
Year MFG: 1995	is commercial address.	Year MFG:		
3 april 5 a.v.	C WAS TABLES	GPS - Latitude 0	•	
GPS - Longitude 0	97 · V	Gro-Lauluue V		
Employee Signature(s): TH, CS, R	J,J5,JL5	Date Completed	10-1-15	

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Time Started	Work Complete				
Loc# Mas		er Meter#			
Date 10/5/2015	Account #	SEQ # 146			
Name: GARY HUNT	I 300 2 000 GARAGA GAMANA AMATE VANNON	Phone # (
Address: Junt Place		Employee Rainbo			
INEZ, KY 41224		·			
LOCATION. 1 TURN FT	and for a superior management of the V	and a survey of the second of			
A man, 4 A Sop v. E. France was among the amount of a separation of the second of the					
ROUTE 2032					
Type of Work: Complaints	A SA A MANAGEMENT OF THE SAME AS A SAME A SAME AS A SAME A SAME A SAME A SAME A SAME A SAME AS A SAME A S	manus para series de la granda de la companie de la			
Material Used:	1 1 2 2 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	The second secon			
2 - 4 - 4 - 4 - 4 - 4 - 4 - 4 - 4 - 4 -	و مستنسبت المستنسبة المنهور و المن	Desperation to a substitution to approximate the same and the second section of the second se			
Comments: no water	. Doner	I'SSKE			
Current System Information:	e sin si ilan saama ahaa ahaa ahaa ahaa ahaa ahaa aha	New Information:			
Meter # 1: 29935364		Meter # 1:			
Meter#2: Radio		Meter # 2: Radio			
MXU #:	N. Marinet M. Marinet and	MXU#:			
Current Reading 9/20/2015 473		Current Reading 0			
Type of Meter: Badger	no _{grafi} a objekt og	Type of Meter:			
Year MFG: 2004		Year MFG:			
GPS - Longitude 0		GPS - Latitude 0			
in Tage of a succession is a different in the supplier of the	Ar Arm Erth	BY C BY C BY CONTRACTOR OF THE STATE OF CONTRACTOR OF CONTRACTOR OF THE STATE OF TH			
Employee Signature(s): RS	-	Date Completed 10 .5 .1 .5			

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO #

	Time Started		/ork Complete
Loc#	o de la sue de communia, la lactica de constituir de la c		
Date 10/8/20	15	Account#	SEQ# 679
Name: Phy	rllis Lowe	was visioner in the first	Phone # ""
Address: P.C	D	The state of the s	Employee Justin Scott
Tor	nahawk, Ky 41262		
	Rockhouse Rd. Tomaha s blacktop driveway. Rockhouse Rd	5 garage algorithms and the rest of the second	idge. Grey & white trailer on the right on a bank.
Type of Work	:: Complaints	g og skinnersom sommer som fra prik y	gy a la la company de la compa
Material Used	d:	>	and the second s
Customer Lin		3	ide
Comments: r			granification and artificial community control of the second of the seco
 Cur	rrent System Information:	e e e e e e e e e e e e e e e e e e e	New Information:
Meter # 1:	29934859		Meter # 1:
Meter#2: Ra	idio 29934859	regulation symmetric confidence of the second secon	Meter # 2: Radio
MXU #:	e de la composición dela composición de la composición de la composición de la composición dela composición dela composición dela composición de la composición dela composición de la composición de la composición dela	undante lightice of the thick of the	MXU#:
Current Read	ding 9/20/2015 626		Current Reading
Type of Mete	r: Badger	, . Pau	Type of Meter:
Year MFG:	2004		Year MFG:
GPS - Longit		•••	GPS - Latitude
۲,	• • • • • • • • • • • • • • • • • • •	apoju v nasu seni	and the second s
Employee Cir	anatura(a):		Date Completed 10 - 8 -1 5

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Time Started	Work Complete
Loc# Maste	er Meter #
Date 11/25/2015 Account #	SEQ # 110
Name: MARY STANLEY	Phone #
Address: PO Box	Employee Justin Scott
WARFIELD , KY 41267 Location: Stanley Dr COLLINS CREEK	
Type of Work: Complaints	en demonstrative territorio (200). Il de la colorida especiale especiale de la colorida del colorida de la colorida del colorida de la colorida del la colorida de la colorida del la colorida de la colorida de la colorida del la colorida de la colorida del l
Material Used: Later Pressure was	low due to pump being
Customer Line Inspection Pan (a) EIK Creek	Sandamara da esta esta esta de la como de la compansa de la compansa de la compansa de la compansa de la compa
Comments: no water	and the second of the second s
Current System Information:	New Information:
Meter # 1: 70616608	Meter # 1:
Meter # 2: Radio	Meter # 2: Radio
MXU#: 13154928	MXU #:
Current Reading 11/20/2015 371	Current Reading 0
Type of Meter:	Type of Meter:
Year MFG:	Year MFG:
GPS - Longitude	GPS - Latitude
Employee Signature(s): # 170 TC TC TC TC TC TC TC T	Date Completed 11/25/15



387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

		WO # 1511	00168
	Time Started		Work Complete
Loc#	and a second demand demand to the assessment of their con-	Master	Meter #
Date 11/24/2	2015	Account #	SEQ# 295
Name: Ro	onnie & Marcella Cook	1.0	Phone # (
Address:	Crum Br		Employee Rainbo
De	ebord, Ky 41214	· · · · · · · · · · · · · · · · · · ·	
Location:			
and an investment			
	Crum Br		
Type of Wor	k: Complaints		
Material Use	ed:		
Customer Li	ne Inspection	Dorc	in the second se
Comments:	could not	that teak	led 500 SI At box
Cu	rrent System Informa	ition:	New Information:
Meter # 1:	47823639	more production of the contract of the contrac	Meter # 1:
Meter#2: R	adio 47823639	antinana di	Meter # 2: Radlo
MXU#:			MXU #:
Current Rea	ding 10/20/2015 113	5	Current Reading 0
Type of Mete	er: Sensus	A grante de salante de la companya d	Type of Meter:
Year MFG:	1993		Year MFG:
GPS - Longi	itude .		GPS - Latitude
<u> </u>			

Date Completed

Employee Signature(s):

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

		WO #	1511	00136	•
	Time Started	arried 3 - C + may described a constant from the first from the fi		Work Complete	9
Loc#	1888 Communication of Transmission		Master	Matan	entremontes productiva de la compression della c
Date 11/	13/2015	Acc	ount#		SEQ # 40
Name:	Connie Mills		*** **********************************		Phone #
Address:	P.O. Box 4				Employee Troy Horn
	Warfield, Ky 41267	***			, , , , , , , , , , , , , , , , , , ,
Location:	Lower Carter Br.	ng than salam and salam termina to the salam and salam a		······································	
	Lower Carter Br				Y
Type of V	Vork: Complaints				and der stand in well der kommenden der den der soller (1900) in der kommende helde der der der der der der de Ten der
Material I					<u>ale</u>
		•	•		
Custome	r Line Inspection				to the state about the second state of the sec
Commen	ts: Low water pressue.	Said there is a le	ak at Lowe	r Carter Br in the	blacktop.
·	Current System Infor	nation:		سسسسسسسنسنسنسنسنسنسنسن	New Information:
Meter # 1	-			Meter # 1:	The state of the s
Meter#2	2: Radio 33001035	★ Management of the control of t	••	Meter#2: R	
MXU#:		***** **** * * - ** ****		MXU #:	
Current R	Reading 10/20/2015 48	33	····•	Current Rea	ding 0
Type of M	Meter: Badger	· » - o la compania de la compania del compania della compania del	·····	Type of Mete	
Year MF0	3: 2006	· p	··•4	Year MFG:	
GPS - Lo	ngitude			GPS - Latitu	de

Employee Signature(s): 5 / JF / J) Date Completed 11/12/15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Time Started		, sw	. Work Complete			
Loc#	· sampanga w or upowermaning y	Master I	Neter#	in the second se		
Date 11/18/2015	Polit d to a describe describer of the	Account #	SE	Q# 161		
Name: RICKY	'HORN	er e k. h. d	Phone #			
Address:V	ountain View	e en esta esta esta esta esta esta esta esta	Employe	e Troy Horn		
INEZ,	, KY 41224					
\$. * * * * * * * * * * * * * * * * * *	nistina dan e din manimina em ceja,	New Asp Sec. of security Asp Assessment substitution	matanistis suranimamanistis variatis (siriatis and siria	a se se estados de estados estados estados en estados en entre en entre en entre en entre entre entre entre en		
Type of Work: C	omplaints		oursessession for the test of the power and the second			
Material Used:	manna kystorinna kansat — pianakangganianna mangkan, pafersian	o mangang pundangan manamatah anink sepangan ya sepangan manaman	- The second contraction of the second contr	o a management paragraphic page ()) Super-control page ()		
Customer Line Ir	nspection:	, -, , , -, -, -, -, -, -, -, -, -, -, -	ine			
Curren	t System Information:		New	Information:		
Meter # 1:	99691124	minina managa juga saasa s	Meter # 1:	man bull a state to the same of the same to the same and		
Meter # 2: Radio	so co ntravanto la combi	<u></u>	Meter # 2: Radio	and the continuous management the continue of the continue of		
MXU#		distriction of the factor of t	MXU#:	payy The second		
Current Reading	10/20/2015 691	Control and annual control and the control and	Current Reading	0		
Type of Meter:	Badger	was the season amount	Type of Meter:	and the state of t		
Year MFG:	1999		Year MFG:	inamina bir simmingan handing gap in = − ma a ir a vormah s. V C b , Francia and garancia virial nib		
GPS - Longitude	O harre the first and information and an angular		GPS - Latitude 0	The state of the s		
Employee Signat	ture(s): R5	Rep 137. Cd	Date Complete	14/8//5		

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Time Started	VVOI	Work Complete			
Loc#	Master Mete	Master Meter #			
Date 11/16/2015	Account #	SEQ # 427			
Name: TRUMAN HORN	we consider to make on the control of the control o	Phone # (_)			
Address: P.O.BOX	Apart & Mark Land Compagner of the Compa	Employee Clyde Stanley			
INEZ , KY 412	24]	· · · · · · · · · · · · · · · · · · ·			
Location: Hom Br	s - yse c - 3se games juiciliuminene amene en	ne po de de la companya del companya de la companya del companya de la companya d			
ક. મે કેટોએ પસંદે કેસ	ميدة مستور مستسسسسسسسسسسسسسسسسسسسسسسسسسسسسسسسسسسس	A STATE OF THE STA			
LICKBRANCH RD.	در منیانگیاندونشستیستیستی میگر پشاری و ایکانگارونگار میزاد در	and the second s			
Type of Work: Complaints	(Dar	t same men production of the same of the s			
Complete state of the state of		Participation of			
Material Used: Puls D	one grove in.	laineway			
Customer Line Inspection:	The state of the s	and the second s			
Comments: MCWD left a mess at	the end of her driveway on RT	908			
Ourself Sustain Inform	The state of the s	New Information:			
Current System Inform Meter # 1:		Neter # 1:			
, 5 × min an in transportation commission	•••	The state of the s			
Meter # 2: Radio	A	Actor # 21 and			
	anima tali in Tamanan tanaman a ya afin da daman	Meter#2: Radio			
MXU #:	anima tali in Tamanan tanaman a ya afin da daman	MXU #:			
¥	·	VAII #-			
MXU #:	, , , , , , , , , , , , , , , , , , ,	AXU#:			
MXU #: Current Reading 0		AXU #: Current Reading 0			
MXU #: Current Reading 0 Type of Meter:		MXU #: Current Reading 0 Type of Meter:			

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#


Time Started	ATO AC F CO No. 1 5	Work Complete
Loc#	544 5	
Date 11/13/2015	Account #	SEQ#
Name: Charlie Mills	d For the 100 calculations and consequences according to the consequences of the conse	Phone #
A didroco:		Employee Painho
American construction of the second	. N. S. g. subaran da managaran managaran sa managaran sa managaran sa managaran sa managaran sa managaran sa m	
Location: Riverfront Rd, n	ew meter set	A STATE OF THE PROPERTY OF THE
manus de ma		
Type of Work: Complaints		
Material Used:	C S ARRIVE COME S CONTRACTOR CONT	
iviacci iai Ooca.	ang ayang ayan mangang arang ang ananan ang ang ang ang ang ang a	Sandrik samun dib. B. S. S. Salaman in C. Spanish da Malika and Albania and Albania
Customer Line Inspection custo	mer has leak	and the second s
Comments: no water	and the state of the second state of the second sec	and the second s
Current System Infor	mation:	New Information:
Meter # 1:	mation.	Meter # 1:
Meter # 2: Radio		Meter # 2: Radio
NAVII #-		MXU#:
Current Reading 0	A CONTRACTOR OF THE PROPERTY O	Current Reading 0
No. Show with 1.5. 4 . while replace (of Show temperatures		
	Shina Amanan marik mari salambanda tana Gharathayan mari	Type of Meter:
Year MFG:	and the state of t	Year MFG:
GPS - Longitude	ne santraganggapan makalana dan santragan mananan mananan mananan mananan mananan mananan mananan mananan manan	GPS - Latitude
Annual	O-	11 10 12
Employee Signature(s):	_XZ	Date Completed //-/5-/5

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Time Started Work Complete Yes			Complete Yes		
Loc#	Loc#		Master Meter #		
Date 11/11/2015	- Comment of the second	Account #	SEQ # 20		
Name: Sherry	Moore	and the statement of the second secon			
Address: P.O. B	^~	AAP COO SE	Employee Dainha		
Lovely	KV 41221	وسائليو سنستسم مستساسد الإدار و الاراد المستد			
Location: Loc	ust Crt. 1st house on th	ne r iaht .	garaganija siš negga — — 6 s 55 sija klālāmikaris akana a sagran is amasamina ritur		
- v 4	The second secon	entre deservation de la company de la compan	The second section of the second section is a second secon		
Loc	eust Crt	et a utumindakintinda dana sebi utu eta yum se utu	ugi kana ana ang auti ay ili u ili ay ay ang		
Type of Work: C	omnlaints				
	omplaints	O 4 V 2 V WHITEVER WARRENCE WARRANT WARRANT TO THE PARTY OF THE PARTY	sandaning salah sanca da sanca da a a a a a a a anandra makan sa da da a a anang anang anang anang anang anang		
Type of Work: C	r until be gib i summi mennin mi semini sumpelembe ay	· · · · · · · · · · · · · · · · · · ·			
Material Used:	r until be gib i summi mennin mi semini sumpelembe ay	ustomor oldo			
Material Used:	nspection problem on c	ustomer side			
Material Used; Customer Line Ir Comments: low	nspection problem on co	ustomer side			
Material Used: Customer Line Ir Comments: low Curren	nspection problem on co pressure t System information:	ustomer side	New Information:		
Material Used: Customer Line Ir Comments: low Curren Meter # 1:	pressure t System information:	ustomer side	New Information:		
Material Used; Customer Line Ir Comments: low Curren Meter # 1: Meter # 2: Radio	pressure t System information:	ustomer side	New Information: eter # 1:		
Material Used; Customer Line Ir Comments: low Curren Meter # 1: Meter # 2: Radio MXU #:	pressure t System information: 70840490	ustomer side Me Me	New Information: eter # 1: eter # 2: Radio		
Material Used: Customer Line Ir Comments: low Curren Meter # 1: Meter # 2: Radio MXU #: Current Reading	pressure t System information: 70840490	ustomer side Me Me	New Information: eter # 1: eter # 2: Radio		
Material Used: Customer Line Ir Comments: low Curren Meter # 1: Meter # 2: Radio MXU #: Current Reading	pressure t System information: 70840490 10/20/2015 630	ustomer side Me Mo Mo Cu	New Information: eter # 1: eter # 2: Radio		
Material Used; Customer Line Ir Comments: low Curren Meter # 1: Meter # 2: Radio MXU #:	pressure t System information: 70840490 10/20/2015 630	ustomer side Me Mo Cu	New Information: eter # 1: eter # 2: Radio KU #: errent Reading 0		



387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Time Started Work Complete				
Loc#	ring and water, or a record to see market	Master	Master Meter #	
Date 11/2/2015	a v ražio provincia sika	Account #	· vormilariye que · · · · · · · · · · · · · · · · · · ·	SEQ# 449
Name: James	s McGinnis	***************************************	P	hone#
Address: M	cGinnis Br		E	mployee Justin Scott
Debor	d, Ky 41214	The second secon	Contract of the Contract of th	
Location: Hill	Crest Dr; across the br	idge by Bud's Bike Sh	op; turn left and i	t is the 1st white single-wide on hill
90) s. y - no - n- n	The state of the contraction of	***************************************	·	managuras and amin'ny site and any a special and the second and th
Middle	•	and the second of the second o	e militar of managements. The layer of a summit	ا يونها السيادي المستوفد في المستوفد (١٠٥٥ - المستوفد المستوفد المستوفد المستوفد المستوفد المستوفد المستوفد ال المستوفد المستوفد الم
Tuna of Modes C	Samuelainte			
Type of Work: C	ompiaints /			enter des des un service des est est ser service différent des menters de la communité de la communité de la c
Material Used:	The local state of the local sta	Zalla za je za kon za	casa wasay see ya	Op sin magnetis de son stelleren sammen der Gels soller men Adries som son steller.
Customer Line I	nspection \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	hee		
		And the second s		international and the second s
Comments: milk	ky water			and the second s
Currer	nt System Information		tra remainmenten eta eritat eta terita eta terra eta en pera espera eta esta eta en pera espera eta esta esta e	New Information:
Meter#1:	29541627		Meter # 1:	
Meter # 2: Radio	***		Meter#2: Rad	dio
MXU#:			MXU #:	Santanana (
: Current Reading	10/20/2015 255		Current Read	
Type of Meter:	Badger		Type of Meter	
Year MFG:	2004		Year MFG:	
GPS - Longitude			GPS - Latitud	
diname de l'interde les desertes l'entre etne et	. Seaja – Kalada da karan sangat wangan da magan	and the state of t		ominimina and the second section of the second section of the second second section of the second section of the second section section section sections section secti
Employee Signat	ture(s):		Date Co	moleted //- < -/

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO #

Time Started Work Complete		w anny samuniahanan anno samesw	
Loc#	Ma	ster Meter#	
Date 12/14/2015	Account #	- Carty distribution of the second of the se	SEQ# 417
Name: ELMER DI	ALS	Phon	e# <u>()</u>
Address: Blackt	ourn & Dials Rd	Empl	oyee Troy Horn
TOMAHA	VK , KY 41262	CONTRACTOR OF THE PROPERTY OF	
ROUTE 40 Type of Work: Comp Material Used:	Plaints June 11 de 19 11 de 19 19 19 19 19 19 19 19 19 19 19 19 19	3/4 coupler) -	3 3/4 incects 11" inc
	stem Information:		ew Information:
	534937	Meter # 1:	agrangina arraman ang mang sa dipagdis madalamina disaman arrama.
Meter#2: Radio	, si e e e e e e e e e e e e e e e e e e	Meter # 2: Radio	and the state of t
MXU #:	$\mathcal{L}_{p}=48$ $_{p}$, ϕ ψ $_{23}$ $_{p}$ $_{p}$ $_{p}$ $_{q}$ $_{p}$ $_{q}$ $_{p}$ $_{q}$ $_{p}$	MXU#:	and the second s
Current Reading 11	20/2015 1093	Current Reading	<u> </u>
Type of Meter: Ba	dger .	Type of Meter:	a constraint standard of conference of the confe
Year MFG: 19	93 	Year MFG:	makana iyo ar yasaar ya araba da sabya ga sa amahar waxaan
•	en description and final final homeomore was a society remains as to be a super-blooding to	GPS - Latitude	
		The state of the s	aaran saligaan aa'aayiin ahiyay oo bir galaana ga ahiya is is salaada salaa salaa salaa salaa salaa salaa sala

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

W	O	#
88	~	w

Tin	ne Started	Work Complete		geren og kommer Fraggings med i skr
Loc#	and the second s	Master Me	eter#	The state of the continuous and
Date 12/21/2015	· · · · · · · · · · · · · · · · · · ·	Account#		EQ# 244
Name: LON C	RUM	annotation and the same and the	Phone	# (, -
Address: P.O. Bo	سىسىسىمىنى ئايدۇرۇرىلىدى سىسىسىسىشىمە ھەۋدىرۇ د	And the second s	Employ	yee Troy Horn
	, KY 41224 rton Rd, Little Lick Br, top o		op of hill, red	
GUYT	ON RD			
Type of Work: C	omplaints		ne /	amin waxaa na a salamin dhalamin waxaa waxaa a waxaa waxaa baa sa s
Material Used:	and the second s	$\left(\right)^{c}$	24	and the state of t
Customer Line Ir	nspection	conformation with a majorate with the control of th		and the second s
Comments: low	water pressure / a a+	water n	<u>yow</u>	A ve succession
Curren	t System Information:	and the state of t		w Information:
Meter # 1:	29935077	nergenin objektor an	Meter # 1:	g v 19 osno v po po minimum managa ann managay. Amai 1870 dij
Meter # 2: Radio	29935077	antenno de la constanta de la	Meter # 2: Radio	
MXU#:	· Mariana and and and and and and and and and 		MXU#:	e make an elik sirk on somethi disan sammanda and kanada jihan Tarihi jimmamada danas
Current Reading	11/20/2015 650		Current Reading	O
Type of Meter:	Badger	· ·	Type of Meter:	
Year MFG:	2004	······································	Year MFG:	mana mana 25 km da da es destamana mana mana de
GPS - Longitude	0	r etgista an ata antitara	GPS - Latitude	
Employee Signa	ture(s): THC5	The state of the s	Date Comple	sted 12-23-15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

l ir	ne Started	ng south an attraction of	Work Complete	of our power was to approximate the state of
Loc#	N The War & SIA saless communication is a region	Master	Meter#	mari v stavetima males sa a manifes a timo e vidando
Date 8/11/2015	Šina Nimir — A - 5 A namaganijanaks (5 - 5 -	Account#		SEQ # 49
Name: Alway	s Perfect Floral	· · · · · · · · · · · · · · · · · · ·	Phon	e# (**
Address: Flut	ty Lick Rd		Empl	oyee Troy Horn
Louisa	LV 41220	moutherness during a strain of management is a strain		
Location: 3 E	Beauty Rd. Building bo	•	road from Rite Aid.	men 11 M de management et s'amb de mande et s'amb de mande et s'amb de mande et s'amb de mande et s'amb de mand Man 11 M de management et s'amb de mande
E	Beauty Rd	some stammers of the gramman some some	neguunasinegine	u waaniiniiniinii ja yanaaniineen ee ey ee
Type of Work: C	complaints (2)		<i>a</i>	ا و ا
			•	acking 20+
Material Used:		California del contra de la California de la contra del contra de la contra del la contra de la contra del la cont	an eyn dan dan endine ee e e . E k k ee	manananan () , n a star se parada hafa a seka seka seka se mananan menembanan menembanan seka seka seka seka s
Customer Line In	nspection:			· Anna · · · · · · · · · · · · · · · · · ·
				e service succession and the service service succession and the service service service service services.
**************************************		angan paga paga padamangan andan sanaman angan paga paga paga paga paga paga p		alan and and an alan and an and an and an
Curren	it System Informatio	n:	N	lew Information:
Meter#1:	29934563	national and as well as I the enterior of	Meter # 1:	5 And communication of the property of the pro
Meter # 2: Redio	29934563	The Art of Artificial Annual A	Meter # 2: Radio	a su accompanya da sa
MXU #:	· «,		MXU #:	
Current Reading	7/20/2015 651	nas maana maanamanan	Current Reading	
Type of Meter:	Badger	As the second se	Type of Meter:	A) applicately deconvolutions on X 0.4. 40 to p. 4.48 at an analysis and an in-
Year MFG:	2004		Year MFG:	Managanamana massa (s. Tagana samunjanamananan dina 1. M. 1. 17.2
GPS - Longitude	-82.25144		GPS - Latitude	37.50562
	ture(s): Js Js R		Date Comp	leted 12/10/15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Time Starte	ed V	Vork Complete	. y - 2 mar.
Loc#	Master M	eter#	***
Date 9/1/2015	Account #		SEQ # 54
Name: WARFIELD SI Address: PO BOX INEZ	HOPRITE	Empl	oyee Troy Horn
Location: Beauty R	d companies of the comp	ing a second of the second of	
Type of Work: Complaint	s	the bad.	Spot in Packing Lot
Material Used:			
Customer Line Inspection): 	e marketing the man and and and	man in the state of the state o
Comments: parking lot n	eeds repaired	a e g de se emperor	in in the second of the second
Current System	معرسمة سركك ما مورشة كمعاديد	7 77. 7	ew Information:
Meter # 1: 372293	19	Meter # 1:	ayan wa 1 3 saya da a na stanar at atas
Meter # 2: Radio		Meter#2: Radio	From the man to district the second of the s
MXU #:	is no thing of his him him for the property of	MXU#:	www.placowwe.ukg+1 W wangepri-arecepe
Current Reading 8/20/20	15 8029	Current Reading	
Type of Meter: Sensus	g y s seemen • e	Type of Meter:	excesses the second of the sec
Year MFG: 1986	gai, was a	Year MFG:	t pay we want to the district of the
GPS - Longitude 0	. 3	GPS - Latitude	O
	e a grandia e quanquare de de la		
Employee Signature(s):	TS, JS, RJ, CS, TH	Date Compl	leted 12 /16 /15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO # 150900059

Time Started Work Complete			mmoney is a collection of a	
Loc#	V	Master Me		
Date 9/8/201	5	Account #	SEC	1# 39
Name: DA	ARRELL CLARK	vs. — Santinanous view	Phone #	a commence of the second secon
Address:	· · · · · · · · · · · · · · · · · · ·		Employee	Rainbo
VV.	arfield, KY 41267			
Location:	Collins Creek. 1/2 miles u	p. Brown brick house or		and the state of t
Type of Wor	k: Complaints		grander van Van Kaalan kommune sommervaar en de stedenbege	
	k: Complaints			
Material Use	e y a gamma wanisha an	and the second s		
	ne Inspection:			
Comments:	repair blacktop	20		
Cu	rrent System Information:		New	Information:
Meter#1:	70616376		Meter # 1:	A RESTAURANT AND
Meter#2: R	adlo	3 75 6 2 70 10 1000	Meter # 2: Radlo	
MXU#:	13151496		MXU#:	
Current Rea	ding 8/20/2015 215			0
Type of Mete	PF:	and the second s	Type of Meter:	
Year MFG:	- ar yelf-y Montaning against a second of \$ \$300 Comment and 3 millions	endana, en gen den generalisa	Year MFG:	manus quidifing ann a sa a 1511 a 15 an agus an amainn ann an an
GPS - Longit	tude	CON. TO A CONTRACTOR	GPS - Latitude	on from the state of the suppression of the state of the
Employee Si	gnature(s): 55,59	S,TH,CS	Date Completed	i slilis

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Tin	me Started	, W	/ork Complete
Loc#	n care of the section of the contraction of the con	Master Me	eter#
Date 12/10/2015	e de la la grandera l'impire e l'impire ponde le galegia de l'anciente de l'impire de l'im	Account#	SEQ# 30
Name: WEND	ELL STEPP	·········	Phone # /
Address: P.O. Bo	, KY 41224		Employee Justin Scott
Location: !Tw	vin Oak Dr., red brick home		and the control of th
Type of Work: Co	omplaints		A STATE OF THE STA
Material Used:			A second of the
Customer Line In	Speciion Light Attack	23/4	cupline abou 4 of 3/4/1/the
Current	t System Information:	ad 4 3/4	M Sur 1/8 New Information:
Meter#1:	70616430	The second secon	Meter # 1:
Meter # 2: Radio	70616430	Year On State Season & Mills and	Meter # 2: Radio
MXU#	13155681	nga Annakananan ya u	MXU #:
Current Reading	11/20/2015 197		Current Reading 0
Type of Meter:	manima menerala a a cara sa na maneralaka mena na urusa na na	v 6 ; » budaumana v.a.	Type of Meter:
Year MFG:	g systempherene i i i i i menor lagina e seni - se	S do W A o cert W	Year MFG:
GPS - Longitude	general construction of the construction of th		GPS - Latitude
Employee Cianet	TO ST	· TH, C	Poto Completed () = (5)

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Tim	e Started	W	ork Complete	a salah garan anan ali ya maray	
Loc#	g Anne de communication	Master Me	ter#	e gy e i sam sam mang	
Date 11/30/2015	c and mornion at the c	Account #	S	EQ# 328	
Name: Earyetta	GILLMAN	strives estroyom, one or exemperation	Phone	# C	
	Riverfront Rd	g witer we confullate many or so the	Emplo	yee Rainbo	
Location:	Riverfront Rd.2nd driveway	past Gospel Revela	tion.Black & white	double-wide on hill.	
Type of Work: Co	mplaints	000		manus da spaning i s s o o o o o o o o o o o o o o o o o	₁₉₈ 6
Material Used:	Pulled the me	towarch.	Prosence about	ave had 904 att	Box
Customer Line In:	spection: tald I was t	to get some	notee dre	De or Der side for	5000
		•		e is on her side	serreel.
Current	System Information:		Ne	w Information:	
Meter # 1:	29935301	againer on a monosporare	Meter # 1:	a siles e de commencia esta commencia esta commencia esta commencia esta compensa de constante e que esta de c	1 1
Meter#2: Radio	amanaramman aras, no series manaramman and a series and a	ranta'uma	Meter # 2: Radio	amananin wayana a a a a a a a a a a a a a a a a a	*
MXU#:	e and a state and a state a sta	,	MXU#:	andre and and another and a special control of the second and a second and a second and a second and a second	
Current Reading	11/20/2015 301	Si sagawa,	Current Reading	0	**
Type of Meter:	Sensus	a one-province-source-source	Type of Meter:		•
Year MFG:	1980	o o po o significante o	Year MFG:	» закашницью антаминация при стантор — 9 аго 23 аго пр. Синтипицьов так достуг то до 18 д	
GPS - Longitude	0		GPS - Latitude	D	
Employee Signatu	ure(s): 1ACBRT	ang mga kata kata kata kata kata kata kata ka	Date Comple	eted $12 - 4 - 15$	

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO #	151200018	·
Time Started		Work Complete	
Loc#			ا من المعالم ا
Date 12/4/2015	Construence and the state of th	Account#	
	AND SPENCE	No.	Phone # (
Address: Ga	rland Spence Dr		Employee Justin Scott
INEZ	, KY 41224	o tal asymmetric property of the second	
		*	go left white house on hill w/railing on
Type of Work: Commer Line In	2 3/4 Couplers,	- Control of the Cont	0ftof341:ne, 34 wrg
Current System Information:		The state of the s	New Information:
Meter # 1:	98604648	Meter #	1:
Meter#2: Radio	Comments of the Sale of Sales of the Sales o		
AXU#: MXU#:			
Current Reading	11/20/2015 1687	Current	Reading 0
Type of Meter:	Badger	Type of	Meter:
Year MFG:	1998	Year MF	G:
GPS - Longitude	.0	GPS - La	atitude 0
Employee Signat	ure(s): TH, C5	Da	te Completed 12-04-15

387 East Main St., Suite 140 Inez, KY 41224

, Q.

WORK ORDER

• 2	WO #	141200	092		
	Time Started	W	ork Complete		
Loc#	popuji mini a sa shakana ka	Master Me	ter#		
Date 12/12/2	2014	Account #		SEQ# 226	·
Name: EL	MER FITCH		Phon	ne# (
Address: P.0	OROV		Empl	loyee Troy Ho	rn <u> </u>
Ine	ez, KY 41224		'		•
	Guyton Rd, 2nd driveway on let			ouble-wide	
Gl	JYTON RD				
	,.	Jan J			y
type of wor	k: Complaints	Doll	gggggggggggggggggggggggggggggggggggggg		· · · · · · · · · · · · · · · · · · ·
Material Use	d:				· ·
Customer Lir	ne Inspection;				
Comments:	· · · · · · · · · · · · · · · · · · ·	4 444444			
Cui	ment System Information:		N	lew Information	n:
Meter # 1:	29934978	ngorale growing and the control of t	Meter#1:	· · · · · · · · · · · · · · · · · · ·	
Meter # 2: Ra	ndlo	1	Meter # 2: Radio	Volumentary and the second	
MXU#:	:-	······································	MXU#:		
Current Read	ling 11/20/2014 389	market side of the	Current Reading		4
Type of Mete	r: Badger	h annonnamentalan	Type of Meter:	•	
Year MFG:	2004	, , , , , , , , , , , , , , , , , , ,	Year MFG:		
GPS - Longite	ude 0 .		GPS - Latitude		
·					

Date Completed__

Employee Signature(s): The CS

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO# 150200238



Tir	me Started	Work C	Complete	
Loc#		Master Meter #		
Date 2/24/2015	***	Account# /	SEQ# 220	••••
Name: Eric Co	opeland		Phone #	; -
Address: PO Bo	x		Employee Rainbo	
Lovely	, KY 41231	The Samuel Control of the Control of	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
Location: 3 F	Divortent Pd			
292		A1 >		-
Type of Work: C	omplaints	Dal		
Material Used:			··· · · · · · · · · · · · · · · · · ·	
Customer Line Ir		water son Ired are		YCZQ
Curren	t System Information:		New Information:	
Meter#1:	98655397	Mete	er#1:	
Meter # 2: Radio	<u> </u>	Mete	er#2: Radio	
MXU #:		MXU	J#:	
Current Reading	1/20/2015 997	Curre	ent Reading 0	
Type of Meter:	Badger	Туре	of Meter:	
Year MFG:	1998	Year	MFG:	<u></u>
GPS - Longitude	0	GPS	S - Latitude 0	
Employee Signat	ure(s): RJ		Date Completed 2-26-15	

دمیر در

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO#	150200236	
	Time Started	Work Co	mplete
Loc#		Master Meter #	
Date 2/24	1/2015	Account #	SEQ# 484
Name:	Recycling Solutions Tech.		Phone # ()
Address:	PO Box		Employee Troy Horn
	Allen, KY 41601		
Location:		s to the left of garage door	s, in front of boiler
Type of W	Vork: Complaints		
• Antonial I			***************************************
Material L	Jsea:	JANGJ	
Customer	Line Inspection Hada a	vote off the	
			g to it either.
	Current System Information:	and the same of th	New Information:
Meter # 1:		Meter i	# 1.
	Radio 70025360	Motors	# 2: Radio
	14640449	MXU#	
Current R	eading 1/20/2015 1961	Curren	t Reading 0
Type of M	eter:	T	f Meter:
Year MFG	:	Year M	IFG:
GPS - Lor	ngitude	GPS-	Latitude
Employee	Signature(s):	<i>H</i>	Pate Completed 2 - 29 - 15

Employee Signature(s):

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO #	‡ 1502 <u>0</u> 0)227	
Time Started	V	Vork Complete	·
Loc#		ata a M	
Date 2/24/2015	Account #	SE	Q# 183
Name: PATRICIA MAYNARD		Phone #	.
4.11			ee Justin Scott
BEAUTY , KY 41203			
Location: Everette Rd, 2nd house on lei	ft, white single-wide		
EVERETT LANE	tadh di dan an i dhaga dha tha tha tha tha tha tha tha tha tha t		
	•		
Type of Work: Complaints	THE RESERVE AND ASSESSED ASSESSED.	o	
Material Used:	**************************************	and the second s	and the second s
Customer Line Inspection:			
Comments: no water			
Current System Information:	70	New	Information:
Meter # 1: 29934968	maniference maintain	Meter # 1:	vident fortier
Meter # 2: Radio		Meter # 2: Radio	
MXU#:	The state of the 	MXU #:	
Current Reading 1/20/2015 756		Current Reading	0
Type of Meter: Badger		Type of Meter:	
Year MFG:	**************************************	Year MFG:	
GPS - Longitude 0	"Terak mandan saka dap	GPS - Latitude 0	

Employee Signature(s):

Date Completed 2-24-6

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO#	150200225	
Ti	me Started	Work Cor	mplete
Loc#	· ·	Master Meter #	
Date 2/24/2015	The state of the s	Account#	SEQ# 384
Name: WAN	DA Maynard		Phone # ();
Address: Ho	neysuckle Ln		Employee Justin Scott
Debor	d, KY 41214		The state of the s
Location: Ho	neysuckle Ln, 90 Babe Delo	ong Rd	
Type of Work: C	11:11 cupplers,	Dong 8 1:n incerts,	rozen on serside 100ft of ElinLine,
Comments: NO	WATER	and the second s	
Curren	t System Information:	<u> </u>	New Information:
Meter#1:	29935196	Meter #	£ 1:
Meter # 2: Radio	***	Meter #	2: Radio
MXU#:			The state of the s
Current Reading	1/20/2015 594	Current	t Reading 0
Type of Meter:	Badger	Type of	Meter:
Year MFG:	2004	Year M	FG:
GPS - Longitude	0	GPS - L	_atitude 0

Employee Signature(s):

Date Completed 2-24-15

387 East Main St., Suite 140 Inez, KY 41224

	WO #	1502	00218	
Tir	ne Started	******************************	Work Complete	manufacture of a grant of the
			Nector #	
Date 2/23/2015	AND THE RESIDENCE OF THE SECOND SECON	Account #		SEQ# 525
Name: Jonath	an Johnson	Nid	Ph	one #
Address: B	lackberry Rd			ployee Clyde Stanley
Deboro	i, KY 41214			
				de on left.
ype of Work: C	omplaints	Walleting of the state of the s		Manager of the state of the sta
Naterial Used:				and the second s
 Customer Line In				- Company
	omer has not had water si	•		
	t System Information;	**************************************		New Information:
Neter#1:	94261254		Meter # 1:	* Consideration of the second
Meter#2: Radio	94261254	······································	Meter # 2: Radio	
fXU#;			MXU#:	
Current Reading	1/20/2015 513	kalikunggang laing ana ng nganatikhankan	Current Readir	ng0
ype of Meter:	Badger		Type of Meter:	
ear MFG:	1994		Year MFG:	
GPS - Longitude			GPS - Latitude	
Employee Signat	ure(s): <u> </u>	3 .	Date Con	npleted 2-24-15

387 East Main St., Suite 140 Inez, KY 41224

	WO #18	50200202	
Time Started	÷ 3	Work Complete	
Loc#	Mas	ster Meter #	
Date 2/23/2015	Account #	SEQ# 525	one of the same
Name: Jonathan Johnson		Phone #	
Address: Rischberg Pd		Employee Luckin Coast	
Debord, KY 41214	•	marks, sty, vs.	
		t Lane.Grey double-wide on left.	
Blackberry Rd			a Simulation
Type of Work: Complaints		***	
Material Used:			·
Customer Line Inspection			· · · · · · · · · · · · · · · · · · ·
Comments: no water	n their	Sible	
Current System Inform		New Information:	* 4
Meter # 1: /8963	034	Meter # 1:	***************************************
Meter # 2: Radio		Meter#2: Radio	
MXU #:		MXU#;	
Current Reading	321	Current Reading 0	······································
Type of Meter: Bade	geV	Type of Meter:	·
Year MFG:		Year MFG:	
GPS - Longitude		GPS - Latitude	000 THE T-000 THE T-
	2 •	· 3	7.
Employee Signature(s):	1/4	Date Completed 2	11210

387 East Main St., Suite 140 inez, KY 41224

		WO#	15020017	5	
Tir	me Started	÷	Work	Complete	<u> </u>
Loc#		· 	Master Meter	#	
Date <u>2/18/2015</u>		Accc	ount#		SEQ# 214
Name: Mirano	la McCoy			Phone	e# __ ′^
Address: P.O. B	ox			Emplo	oyee Justin Scott
Beauty	/, KY 41203		hirotores est es es est		,
Location: 18	Big Elk Rd. Across	from Water To	wer, grey trailer		191) 43-44-4
	-			Manian and the late of the lat	
	Big Elk Rd				
Type of Work: C	- complaints	1		(2)	
******			10t		
Material Used:	and the second s				, III
Customer Line In	rspection:				
Comments: pos	sibly frozen at met	er / had	water c	T philo	hourgh the Me
	it System Informa				ew Information:
Meter#1:	29935189		Me	eter # 1:	and the second s
Meter # 2: Radio	29935189		. Me	eter#2; Radio	A Samuel Company of the Company of t
MXU#:	ya		M	XU#:	
Current Reading	1/20/2015 374		Cı	irrent Reading	0
Type of Meter:	Badger			pe of Meter:	
Year MFG:	2004		Ye	ear MFG:	
GPS - Longitude			. G	PS - Latitude	
Employee Signa	ture(s):	, RJ		Date Compl	eted 1 -19-15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#	150200169
Time Started	Work Complete
Loc#	Master Meter #
Date 2/18/2015 Accou	sEQ# 142
Name: EARL ALLEY	Phone #
Address: Poplar Fork	Employee Troy Horn
BEAUTY , KY 41203	
· · · · · · · · · · · · · · · · · · ·	
Customer Line Inspection: Wother Pross	Tietom to book onus
Current System Information:	New Information:
Meter # 1: 98607413	Meter # 1:
Meter # 2: Radio	Meter # 2: Radio
MXU #:	MXU #:
Current Reading 1/20/2015 734	Current Reading 0
Type of Meter: Badger	Type of Meter:
Year MFG: 1998	Year MFG:
GPS - Longitude 0	GPS - Latitude 0


Date Completed

Employee Signature(s):

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO # 15020	A A A A A A A A A A A A A A A A A A A
Time Started		Work Complete
Loc#		Neter#
Date 2/18/2015		SEQ# 380
Name: B. ARANAS	announce ()	Phone # () · · ·
Address: P.O. BOX		Employee Troy Horn
BEAUTY , K	Y 41203	
ocation: beauty, Beside Naza	rene church. Pink house right si	ide
BEAUTY		
Type of Work: Complaints		
ypo or tronc complainte		
		meter: problemison customé
Customer Line Inspection: 1)	eter is flusing at	meter; proldemison austomé
Current System Info	eter is frozen	meter; problemison customé
Current System Info	iter is flooring at leter is frozen	meter; problemison custome
Current System Into Meter # 1: 96130786	eter is frozen	meter; problemison custome
Customer Line Inspection: Comments: customer thinks m Current System Info Meter # 1: 96130786 Meter # 2: Radio	eter is frozen	Meter , Proldemison Custome New Information: Meter # 1:
Customer Line Inspection: Comments: customer thinks m Current System Info Meter # 1: 96130786 Meter # 2: Radio	eter is frozen	Meter # 2: Redio
Customer Line Inspection: Comments: customer thinks m Current System Info Meter # 1: 96130786 Meter # 2: Radio MXU #: Current Reading 1/20/2015	eter is frozen	New Information: Meter # 1: Meter # 2: Radio MXU #:
Customer Line Inspection: Comments: Customer thinks m Current System Info Meter # 1: 96130786 Meter # 2: Radio MXU #: Current Reading 1/20/2015	eter is frozen	New Information: New Information: Meter # 1: Meter # 2: Radio MXU #: Current Reading 0
Customer Line Inspection: Comments: customer thinks m Current System Info Meter # 1: 96130786 Meter # 2: Radio MXU #: Current Reading 1/20/2015 Type of Meter: Badger Year MFG: 1996	eter is frozen	New Information: Meter # 1: Meter # 2: Radio MXU #: Current Reading 0 Type of Meter:



387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO # 150200168

Ti	me Started		Work Complete
Loc#	·		Meter#
Date 2/18/2015		Account#	SEQ# 538
Name: <u>Ivalea</u>	n Hager		Phone #
Address: PO Bo	N7.	# * M	Familiana Deleka
Inez	, Ky 41224-029	5	
Skyvi	ew Drive		
Type of Work: 0	Complaints		
			vode to robou
Comments: no	water		<u> </u>
Curre	nt System Information:		New Information:
Meter # 1:	95748781	and the same of th	Meter # 1:
Meter # 2: Radio		***************************************	Meter # 2: Radio
MXU#:		Mineral Control of the Control of th	MXU #:
Current Reading	1/20/2015 1773		Current Reading 0
Type of Meter:	Badger	- <u></u>	Type of Meter:
Year MFG:	1995	· · · · · · · · · · · · · · · · · · ·	Year MFG:
GPS - Longitude	0	and the same the construction of the same	GPS - Latitude 0
Employee Signs	ature(s): RS		Date Completed 2/17/15

Martin County Water District 387 East Main St., Suite 140

Inez, KY 41224

WORK ORDER

- 1	 * 5		~

150300205

Time Started	Work Complete
Loc# Mast	ter Meter#
Date 3/25/2015 Account #	SEQ# 98
Name: GARY & Trish HUNT	Phone # (
Address: PO BOX	Employee Justin Scott
INEZ , KY 41224	
Location: Cassell Br. Brown 16X80 trailer at head of	hollow
CASSELL BRANCH	
Type of Work: Complaints	
	36N
Current System Information:	New Information:
Meter # 1: 29935252	Meter # 1:
Meter # 2: Radio	Meter # 2: Radio
MXU #:	MXU #:
Current Reading 3/20/2015 961	Current Reading 0
Type of Meter: Badger	Type of Meter:
Year MFG: 2004	Year MFG:
GPS Longitude 0	GRS 4 litude 0
Employee Signature(s):	Date Completed 3 - 25 - 15
A Company of the Comp	



387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

WO#

Employee Signature(s):

150300144

Į II	me Started	****	Work Complete	Control of the Contro
Loc#				
Date 3/18/2015	annika aryandan annihili ayang da annihili ayan ka annihili a	Account #	SE	Q# <u>174</u>
Name: Judy H	Harmon		Phone #	
Address: PO BO	OX.	•	Employe	ee Justin Scott
LOVE	LY , KY 41231			
Location:	N Wolf Creek			
	•			
Type of Work: (Complaints			
7,7				
Material Used:		· · · ·	· · · · · · · · · · · · · · · · · · ·	
Material Used:				
Customer Line I Comments: con	nspection:			
Customer Line I Comments: con	nspection:	er; please flush li	nes/cont flash	lônes Have to
Customer Line I	nspection: nplains of white, murky wat	er; please flush li	nes/cont_flash New	
Customer Line I	nspection:nplains of white, murky wat	er; please flush li	nes/Cont Flash	lônes Have to
Customer Line I Comments: con Currer Meter # 1:	nspection: nplains of white, murky watent System Information:	er; please flush li	nes/ Cont Flash New Meter # 1:	lones Have to
Customer Line I Comments: con Currer Meter # 1:	nspection: nplains of white, murky wat nt System Information: 74604140	er; please flush li	New Meter # 1: Meter # 2: Redlo	lones Have to
Customer Line I Comments: con Currer Meter # 1: Meter # 2: Radio MXU #:	nspection: nplains of white, murky wate nt System Information: 74604140 74604140	er; please flush li	New Meter # 1: Meter # 2: Radio MXU #:	icnes Have to Information:
Customer Line I Comments: con Currer Meter # 1: Meter # 2: Radio MXU #:	nspection: nplains of white, murky wat nt System Information: 74604140 74604140 14992935	er; please flush li	New Meter # 1: Meter # 2: Radio MXU #: Current Reading	lones Have to
Customer Line I Comments: con Currer Meter # 1: Meter # 2: Radio MXU #: Current Reading	nspection: nplains of white, murky wat nt System Information: 74604140 74604140 14992935	er; please flush li	New Meter # 1: Meter # 2: Radio MXU #: Current Reading	Iches Hace to Information:
Customer Line I Comments: con Currer Meter # 1: Meter # 2: Radio MXU #: Current Reading Type of Meter:	nspection: nplains of white, murky water nt System Information: 74604140 74604140 14992935 12/20/2015 13	er; please flush li	New Meter # 1: Meter # 2: Radio MXU #: Current Reading Type of Meter:	Iches Hace to Information:

Inez, KY 41224

WORK ORDER

	WO#	15030	0112	
Ti	me Started	\	Vork Complete	
Loc#		Master M	eter#	
Date 3/12/2015		Account #	SI	EQ#- 121
Name: Mary	√ Moore		Phone	# (
Address:	Yellow Crk Rd	·	Employ	ree Justin Scott
LOUIS	SA , KY 41230		aggorian con consequent and an arrangement	** And
Location:) Yellow Crk, 4th house on i	right udita		3*
Location.				
New				
LOWE	ER FLUTY LICK		¢	
Type of Work: C	Complaints			
Material Used:	, x	· ·	ent of the contract of the con	
Customer Line I	nspection:			
Comments: low	/	IA	box	
Currer	nt System Information:	s	Nev	v Information:
Meter#1:	330010033	25	Meter # 1:	
Meter # 2: Radio	330010033		Meter # 2: Radio	
MXU#:	***************************************		MXU#:	remonante que en esta e
Current Reading	2/20/2015 293	^	Current Reading _	0
Type of Meter:	Badger	^	Type of Meter:	
Year MFG:			Year MFG:	
GPS-Longitude	0		GPS - Latitude 0	

Date Completed

Employee Signature(s):

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	W	O# 1503	300117		
-	Time Started		Work Complete		no.es com
Loc#	an mangan samananan mananan mananan dalah samanan mananan mananan dalah samanan menengan menengan menengan men	Master	Meter#		
Date 3/13/201	5	Account #		SEQ# 295	
Name: Just	in Pinson	· · · · · · · · · · · · · · · · · · ·	Phon	e# (f	- *
Address: M			F1		
Inez	, Ky 41224		·		
Location: N	flusic Ln. 1st driveay acr	oss bridge, brown hou			and the second s
N	/lusic Ln		and the state of t	1900 M. C.	
Type of Work:	Complaints				
Material Head					
Iviaterial Oseu.					\$
Customer Line	Inspection				
Comments: ve	ery low water pressure for	or days / 100 p	ZI At	box-	1. K- Sal
Curr	ent System Informatio	n:	N	ew Information	on:
Meter # 1:	70472562		Meter # 1:	***************************************	The state of the s
Meter # 2: Rad	70472562	and the second s	Meter # 2: Radio		**************************************
MXU #:		THEN TO THE	MXU #:		
Current Readi	ng 2/20/2015 194		Current Reading	***************************************	D
Type of Meter	Sensus		Type of Meter:		
Year MFG:	2010	,	Year MFG:		
GPS - Longitu	<u> </u>	4 94	GPS - Latitude		
				2. 624 6 2	**************************************

Date Completed

Employee Signature(s):

387 East Main St., Suite 140 Inez, KY 41224

	WO#	150300098	***************************************
Ti	me Started	Work Comp	lete
Loc#		Master Meter #	
Date 3/10/2015	****	Account #	SEQ# 524
Name: Kayla	Hali		Phone # (
Address:	Tomahawk Rd	·	Employee Rainbo
Toma	hawk, Ky 41262		·
Location: 3			
	Tomahawk Rd		
Type of Work: O	Complaints		
Material Used:			
Customer Line I	nspection Dor	e/	
Comments: mill	ky water	Blowed hyd	rant at Spicy Mountain.,
	-4 C		New Information:
Meter # 1:	nt System Information: 47823902	Meter # 1	
		A Agent riggs of the Trade Management	
Meter # 2: Radio	47823902	Meter # 2	2: Radio
MXU #:		MXU #:	
Current Reading	2/20/2015 418	Current F	Reading 0
Type of Meter:	Sensus	Type of I	Meter:
Year MFG:	1993	Year MF	G :
GPS - Longitude		GPS - La	atitude
Employee Signa	ture(s): 57/CH/K5	Dat	te Completed 3-11-15

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO #	15030	0115	
	Time Started	V	Vork Complete	
Loc#		Master M	eter#	
Date 3/13	3/2015	Account #	SEQ	# 118
Name:	RONDA CRUM		Phone #	
Address:	! Blacklog Rd		-	Clyde Stanley
	Inex KV 41224			
Location:	2 Blacklog Rd Blacklog, 1st h			
Type of W	BLACKLOG	\	leak on cut	±
••	Jsed:			
	r Line Inspection:			
	ts: check meter to see if it busted			
	Current System Information:		New (ı	nformation:
Meter#1	90770481		Meter#1:	
Meter#2			Meter#2: Radio	
MXU #:	The state of the s	***************************************	MXU #:	
Current R	Reading <u>2/20/2015</u> 1487	designation of the contract	Current Reading	0
Type of M	leter: Badger		Type of Meter:	

100	- ^	 white s. "	, , , ,	つた	
Employee Signature(s)	ET:	Date	Completed	713	.
	, .	 	***************************************	7	

Year MFG:

GPS - Longitude 0

Year MFG:

GPS - Latitude

387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO #	150300114	
Tir	me Started	Work Com	plete
Loc#		Master Meter #	
Date 3/13/2015		Account#	SEQ# 162
Name: Dinah	Ratliff		Phone # (
Address: Oal	rie Drive		Employee Clyde Stanley
lnez, k	√ 41224		
Location: Calf C	reek, . Oakie Dr. stay strai	ght, last house, beige 2ston	<u>/</u>

Anni in anni anni anni anni anni anni an			
Type of Work: C	complaints		
		*	
Material Used:			
Customer Line In	nspection:		
Comments:	. 4:	on costomer	
Curren	t System Information:		New Information:
Meter#1:	99459123	Meter#	1:
Meter#2: Radio	99459123	Meter#	2: Radio
MXU#:		MXU#:	Notes that the second s
Current Reading	2/20/2015 1247	Current	Reading 0
Type of Meter:	Badger	Type of	Meter:
Year MFG:	1999	Year MF	FG:
 GPS - Longitude	יי יין יין יין יין יין יין יין יין יין	GPS - L	atitude
_	estate the second of the secon	. >>	3 2 2 3 4
Employee Signat	ture(s): TS	Da	ite Completed 3/3/5

Martin County Water District 387 East Main St., Suite 140

Inez, KY 41224

WORK ORDER

	WO:	# 150	0300100		
	Time Started	Work Complete			
Loc#		Mas	ter Meter#		
Date 3/1	1/2015	Account #	SEC	Q# <u>229</u>	······································
Name:	Norma McCoy		Phone #		
Address:	6 Meathouse Rd		Employe	e Rainbo	
	Pilgrim, KY 41250				
Location:			miles on right grey trailer on		
Type of V	Vork: Complaints				
Material (Used:				
Custome	r Line Inspection				
Commen	its: no water pumb	LJQS"	att		
	Current System Information:		New	Information:	
Meter # 1	71799523	and the same of th	Meter#1:		
Meter # 2	2: Radio 71799523		Meter # 2: Radio		
MXU#:			MXU #:		
Current F	Reading 2/20/2015 140		Current Reading	0	
Type of N	Meter: Sensus		Type of Meter:		
Year MF	G: 2012		Year MFG:	The second secon	
GPS - Lo	ngitude	- >1	GPS - Latitude	Asymptotic by the second	

Employee Signature(s):

Date Completed

Martin County Water District 387 East Main St., Suite 140


Inez, KY 41224

WORK ORDER

WO#	150300039	***
Time Started	Work Comple	te
Loc#		···
Date 3/6/2015	Account# 1	SEQ# 177
Name: John Moore		Phone # \
Address: Meathouse Pd		Employee Rainbo
Pilarim KV 41250		
Wolf Creek		
		~
Type of Work: Complaints)
Material Used:	-1000	<u>/ </u>
Customer Line Inspection		
Comments: low pressure / had we	7+e1	
Current System Information:	and the state of t	New Information:
Meter # 1: 47823969	Meter # 1:	
Meter # 2: Radio	Meter # 2:	Radio
MXU#:	MXII#	
Current Reading 2/20/2015 582	Current Re	eading 0
Type of Meter: Sensus	Type of Me	eter:
Year MFG: 1993	Year MFG	
GPS - Longitude 0	GPS - Lati	tude ` <u>0</u>

Employee Signature(s):

Date Completed



387 East Main St., Suite 140 Inez, KY 41224

WORK ORDER

	WO #	1503000	J5∠		
Tir	me Started	Wo	rk Complete		
Loc#		Master Met	er#		Source of the state of the stat
Date 3/9/2015		Account#		SEQ# <u>224</u>	
Name: JAMES	S MOLLETT		Phon	e#	
Address: 4 E	Big Elk Road		Empl	oyee Rainbo	
INEZ	, KY 41224				-
Location: : E	Big Elk Rd				
Type of Work: C Material Used: Customer Line In Comments: no w	nspection:	Done			
Curren	t System Information:		N	ew Information:	:
Meter # 1:	98985758	Commenced common age of commenced co	Vieter # 1:	*	·
Meter # 2: Radio			Meter # 2: Radio	<u></u>	
·MXU #:		einne in en	MXU #:		·
Current Reading	2/20/2015 700	······································	Current Reading	. 0	and the state of t
Type of Meter:	Badger	·	Type of Meter:	· · · · · · · · · · · · · · · · · · ·	
Year MFG:	1998		Year MFG:		······································
GPS - Longitude	0	· ·	GPS - Latitude	0	*
	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	······································	······		

Employee Signature(s): TH, CS

Date Completed 3-10-15

387 East Main St., Suite 140 Inez, KY 41224

#### WORK ORDER

WO#	150300036	**
Time Started	Work Complete Yes	, , , , , , , , , , , , , , , , , , ,
Loc#	Master Meter #	<u></u>
Date 3/6/2015	Account # ^	SEQ# 262
Name: EUGENE MAYNARD	Phon	e#
Address: Debord Rd	Empl	oyee Rainbo
		Sales and the sales and the sales are sales and the sales are sales are sales and the sales are
	e left past post office. 2nd driveway	
DEBOARD RD		
Type of Work: Complaints		
Material Used:		
Customer Line Inspection:		
Comments: water is milky 14 S	hed line	
Current System Information:		lew Information:
Meter # 1: 92701760	Meter # 1:	A
Meter # 2: Radio 92701760	Meter # 2: Radio	
MXU #:	MXU #:	
Current Reading 2/20/2015 1507	Current Reading	
Type of Meter: Badger	Type of Meter:	
Year MFG: 1992	Year MFG:	
GPS - Longitude 0	GPS - Latitude	0 .

Employee Signature(s):

15,06

Date Completed

3-26-15

387 East Main St., Suite 140 Inez, KY 41224

### WORK ORDER

		WO #	150300065		
Time Started			Work Complete		
Loc#	···	·			
Date 3/10	0/2015	Acc			154
Name:				Phone # /	
Address:	** **		<u> </u>		ustin Scott
	LOVELY , KY				
Location:	Stepp Br				
	STEPP BRANCH  Vork: Complaints  Used:				
Custome	r Line Inspection				
Commen	nts: no water for days		- North Address of the Control of th		
-	Current System Info	•			ormation:
Meter#1	I: 19906223		Mete	er#1:	
Meter # 2	2: Radio 19906223		Mete	er#2: Radio ,	
MXU #:	<b>4</b> 4		MXU	J#;	
Current F	Reading <u>2/20/2015</u>	380	Curr	ent Reading	0
Type of N	Meter: Sensus	, , , , , , , , , , , , , , , , , , , ,	Туре	e of Meter:	
Year MF	G: 1967		Year	r MFG:	
GPS - Lo	ongitude 0		GPS	3 - Latitude 0	

Employee Signature(s):

Date Completed

387 East Main St., Suite 140 Inez, KY 41224

#### **WORK ORDER**

	-	
w	J( }	33

150300049

Time Started		Wo	Work Complete			
Loc#		Master Mete	Master Meter #			
Date 3/9/2015		Account #	SI	EQ# 331		
Name: William	n Chapman		Phone	# '		
Address: N	olan St		Employ	yee Rainbo		
William	nson, WV 25661					
Location: Chapman Farm Rd of Riverfront, 1 mile from county line, Spring Br, right side of rd, beige double wide,						
RIVER	FRONT					
Type of Mark: C	omplaints	Lock water +	x Auchan	<u></u>		
<u></u>		The state of the s		·		
Material Used: _						
Customer Line Ir	spection:					
			_			
Curren	t System Information:		Ne	ew Information:		
Meter # 1:	29934670		Meter#1:			
Meter # 2: Radio			Meter#2: Radio			
MXU#:		· · · · · · · · · · · · · · · · · · ·	MXU#:	·		
Current Reading	2/20/2015 334		Current Reading	0		
Type of Meter:	Badger	nga ana ana ana ana ana ana ana ana ana	Type of Meter:			
Year MFG:	2004	·	Year MFG:			
GPS - Longitude			GPS - Latitude			
Employee Signa	ture(s):		Date Comple	eted 3-9-15		



387 East Main St., Suite 140 Inez, KY 41224

#### **WORK ORDER**

	WO:	# 150300040	Military and Administration			
	Time Started	Work Co	omplete			
Loc# Master Meter#						
Date 3/6/2	015	Account#	SEQ# 203			
Name: 0	CLIFFORD KEENER		Phone # (			
Address:	Riverfront Rd		Employee Rainbo			
<u></u>	LOVELY , KY 41231		_			
-						
Type of Work: Complaints  Walk Shut off tank  Material Used:  Customer Line Inspection:  Comments: water had low pressure, now has none						
·	Current System Information:	e and	New Information:			
Meter # 1:	25088029	Mete	r#1:			
Meter#2:		18-1-	r#2: Radio			
MXU#:	N. 44	MXU	#:			
Current Re	eading 2/20/2015 710	Curre	ent Reading0			
Type of Me	eter: Sensus	Туре	of Meter:			
Year MFG	: 1976	Year	MFG:			
GPS - Lon	gitude 0	GPS	- Latitude 0			

Employee Signature(s)

Date Completed

387 East Main St., Suite 140 Inez. KY 41224

#### **WORK ORDER**

WO#

150400180

Time Started

Work Complete

Loc#

Master Meter #

Date 4/23/2015

Account #

SEQ # 382

Name:

**SD & MARY MOORE** 

Phone # (*

Address: P.O.BOX

Employee Troy Horn

**INEZ** 

. KY 412241

Location:

Rockcastle Crk

**ROUTE 3 NORTH** 

Type of Work: Complaints

Material Used:

**Customer Line Inspection:** 

Comments: fence was tore down Friday by MCWD

put fence back 40

New Information:

**Current System Information:** 

Meter # 1:

Meter # 2: Radio

15094918

Meter # 2: Radio

Meter # 1:

MXU#:

MXU#:

Current Reading 3/20/2015

Type of Meter:

**Current Reading** Type of Meter:

Badger

Year MFG:

1982

Year MFG:

GPS - Longitude 0

GPS - Latitude 0

Employee Signature(s):

Date Completed 4-27-5

387 East Main St., Suite 140 Inez. KY 41224

#### **WORK ORDER**

WO#

150400202

Time Started

Work Complete

Loc#

Master Meter #

Date 4/24/2015

Account #

SEQ # 282

Name:

Eva Spence

Phone # (6

Address: PO Box

Employee Troy Horn

Inez, KY 41224

Location:

3 Rockcastle Rd Old Rt 3, Past Ratlifftown on hill on the right, brick house, beside Rocky Top Hill.

Old Rt 3

Type of Work: Complaints

Material Used:

**Customer Line Inspection:** 

Comments: customer wants dirt filled and grass sown on bank where water dept had worked

**New Information:** 

Meter # 1:

29934897

Meter # 1:

Meter # 2: Radio 29934897

Meter # 2: Radio

MXU#:

MXU #:

Current Reading 4/20/2015

Current Reading

put Dit back

Type of Meter:

Badger

Type of Meter:

Year MFG:

2004

Year MFG:

GPS - Longitude

GPS - Latitude

Employee Signature(s):

Date Completed 4-27-5

387 East Main St., Suite 140 Inez, KY 41224

#### **WORK ORDER**

WO#

150500078

Time Started

Work Complete

Loc#

Master Meter #

Date 5/7/2015

Account #

SEQ # 303

Employee Justin Scott

Name:

PAUL ENDICOTT

Phone #

Address:

2 Buffalo Horn Rd.

LOUISA

, KY 41230

Location:

? Buffalo Horn Rd 1st white house on the left past Burkes Body Shop. Wood fence around yard.

**BUFFALO HORN** 

Type of Work: Complaints

Material Used:

Customer Line Inspection:

Comments: extremely low pressure / had good pressure

**Current System Information:** 

New Information:

Meter # 1:

92917046

Meter # 1:

Meter # 2: Radio

Meter # 2: Radio

MXU#:

MXU#:

Current Reading 4/20/2015 920

**Current Reading** 

Type of Meter:

Badger

Year MFG:

1992

Year MFG:

Type of Meter:

GPS - Longitude 0

GPS - Latitude 0

Employee Signature(s):

Date Completed 5-8-15

387 East Main St., Suite 140 Inez, KY 41224

#### **WORK ORDER**

**WO#** 

150500096

Time Started

Work Complete

Loc#

Master Meter #

Date 5/11/2015

Account #

SEQ# 117

Name:

Linda Smith

Phone # (f

Address:

_ Camp Branch

Employee Justin Scott

Inez, KY 41224

Location: (

Camp Br, 1/2 m on left, brick split level

Coldwater

Type of Work: Complaints

Material Used:

Customer Line Inspection:

Comments: very low pressure; water is cloudy

**Current System Information:** 

**New Information:** 

Meter # 1:

70840768

Meter # 1:

Meter # 2: Radio

Meter # 2: Radio

MXU#:

MXU#:

Current Reading 4/20/2015

**Current Reading** 

Type of Meter:

Sensus

Type of Meter:

Year MFG:

2009

Year MFG:

GPS - Longitude

GPS - Latitude

Employee Signature(s):

Date Completed 5 - 12 - 5

387 East Main St., Suite 140 Inez, KY 41224

#### **WORK ORDER**

WO#

150500101

Time Started

Work Complete

Loc#

Master Meter #

Date 5/11/2015

Account # 1

SEQ # 293

Employee Justin Scott

Name:

STERLING MARCUM .

Phone # (1

Address: RT 5 BOX

LOUISA

, KY 41230]

Location:

Rockcastle Rd, 1st white house on the right past Friendship Church

**ROUTE 3 NORTH** 

Type of Work: Complaints

Material Used:

**Customer Line Inspection:** 

Comments: extremely low pressure

**Current System Information:** 

Meter # 1:

47823998

Meter # 2: Radio 47823998

MXU#:

Current Reading 4/20/2015

Type of Meter:

Sensus

Year MFG:

1993

GPS - Longitude 0

Meter # 1:

Meter # 2: Radio

MXU #:

**Current Reading** 

0

**New Information:** 

Type of Meter:

Year MFG:

GPS - Latitude 0

Employee Signature(s):

35

Date Completed 6-16-5

29934796 428

387 East Main St., Suite 140 Inez. KY 41224

#### **WORK ORDER**

WO#

150500087

Time Started

Work Complete

Loc#

Master Meter#

Date 5/8/2015

Account #

SEQ # 352

Name:

Heather Harrison

Address:

Mullett Br

Employee Justin Scott

**INEZ** 

, KY 41224

! Mullett Br. Coldwater.Last house on the right, white house on hill, stone bottom

Mullett Br

Type of Work: Complaints

Material Used:

Customer Line Inspection:

Comments: low pressuree - 40 PBSI A+ 60%

**Current System Information:** 

**New Information:** 

Meter # 1:

29934533

Meter # 1:

Meter # 2: Radio 29934533

Meter # 2: Radio

MXU#:

MXU#:

Current Reading 4/20/2015 447

**Current Reading** 

0

Type of Meter:

Badger

Type of Meter:

Year MFG:

2004

Year MFG:

GPS - Longitude 0

GPS - Latitude 0

Employee Signature(s):

Date Completed 5-11-15

387 East Main St., Suite 140 Inez, KY 41224

#### **WORK ORDER**

**WO#** 

150400151

Time Started

Work Complete

Loc#

Master Meter #

Date 4/16/2015

Account # ^ *

SEQ # 352

Name:

Heather Harrison

Phone # (:

Address: Mullett Br

Employee Troy Horn

INEZ

, KY 41224

Location: -

Mullett Br. Coldwater.Last house on the right, white house on hill, stone bottom

_ Mullett Br

Type of Work: Complaints

Material Used:

Customer Line Inspection:

40 PSI At box

Comments: extremely low pressure

#### **Current System Information:**

**New Information:** 

Meter # 1:

29934533

Meter # 1:

Meter # 2: Radio 29934533

Meter # 2: Radio

MXU#:

MXU#:

Current Reading 3/20/2015

**Current Reading** 

Type of Meter:

Badger .

Type of Meter:

Year MFG:

2004

Year MFG:

GPS - Longitude 0

GPS - Latitude 0

Employee Signature(s):

Date Completed 5-4-15

387 East Main St., Suite 140 Inez. KY 41224

#### **WORK ORDER**

WO#

150500071

Time Started

Work Complete

Loc#

Master Meter #

Date 5/7/2015

Account #

SEQ# 85

Name:

DICIE CHARLES

Phone #

Address: PO BOX

Employee Rainbo

LOVELY

, KY 41231

MAPLE STREET

Type of Work: Complaints

Material Used:

Customer Line Inspection

Comments: very low water pressure

**Current System Information:** 

Meter # 1: 47823885

Meter # 2: Radio

MXU#:

Current Reading 4/20/2015

Type of Meter:

Year MFG:

1993

Sensus

GPS - Longitude 0

ints Pull neter on it seem to be oh I think she has a lod Regulhta on she on said ser

**New Information:** 

Meter # 1:

Meter # 2: Radio

MXU#:

**Current Reading** 

Type of Meter:

Year MFG:

GPS - Latitude 0

Date Completed

5-7-15

Employee Signature(s):

387 East Main St., Suite 140 Inez. KY 41224

#### **WORK ORDER**

WO#

150600053

Time Started

Work Complete

Loc#

Master Meter #

Date 6/8/2015

Account # .

SEQ # 105

Name:

HERMAN ENDICOTT

Phone # ( )

Address:

Tug River Rd.

Employee Troy Horn

**INEZ** 

, KY 412241

Tug River Rd, 1 mile up Tug River, green roof w.grey siding

**TURKEY ROAD** 

Type of Work: Complaints

Material Used:

Comments: customer thinks driveway is damaged due to water meter busting — Did not See was thing which some

**Current System Information:** 

New Information:

Meter # 1:

96646084

Meter # 1:

Meter # 2: Radio

96646084

Meter # 2: Radio

MXU#:

MXU #:

Current Reading 5/20/2015 1050

**Current Reading** 

0

Type of Meter:

Badger

Type of Meter:

Year MFG:

1996

Year MFG:

GPS - Longitude 0

GPS - Latitude

Employee Signature(s):

Date Completed 6 - 8 - 15

387 East Main St., Suite 140 Inez. KY 41224

#### **WORK ORDER**

WO#

150600124

Time Started

Work Complete

Loc#

Master Meter #

Date 6/16/2015

Account#

SEQ# 95

Name:

FRANK STACY

Phone #

Address: PO BOX

Employee Rainbo

INEZ

, KY 41224

Location:

Frank Stacy Ln blacktop hill goes right-handed.white house all the way to end of road.

**CASSELL BRANCH** 

Type of Work: Complaints

Material Used:

Customer Line Inspection

Comments: no water / got water NOW

**Current System Information:** 

**New Information:** 

Meter # 1:

33001067

Meter # 1:

Meter # 2: Radio

Meter # 2: Radio

MXU#:

MXU#:

Current Reading 5/20/2015 642

Current Reading

Type of Meter:

0

Type of Meter:

.

Year MFG:

Badger

2006

Year MFG:

GPS - Longitude 0

GPS - Latitude 0

Employee Signature(s):

Date Completed

6-17-15

387 East Main St., Suite 140 Inez, KY 41224

#### **WORK ORDER**

**WO#** 

150600101

Time Started

Work Complete

Loc#

Master Meter #

Date 6/11/2015

Account #

SEQ # 120

Name:

**R&J Development** 

Phone #

Address: P.O. Box

Employee Justin Scott

Warfield, Ky 41267

Location: W Main St Suite 110. Beside Melissa's House of Style

.V Main St Suite 110

Type of Work: Complaints

Material Used:

Customer Line Inspection:

Comments: customer stated water had odor

**Current System Information:** 

**New Information:** 

Meter # 1:

72136096

Meter # 1:

Meter # 2: Radio

72136096

Meter # 2: Radio

MXU#:

14639897

MXU#:

Current Reading 5/20/2015 43

**Current Reading** 

Type of Meter:

Type of Meter:

Year MFG:

Year MFG:

GPS - Longitude

**GPS - Latitude** 

Employee Signature(s): (

Date Completed 6 -/5 -5

387 East Main St., Suite 140 Inez, KY 41224

### **WORK ORDER**

WO#

Time Started	Work Comple	ete
Loc#	Master Meter #	en manere en
Date 6/29/2015	Account#	SEQ# 231
Name: LON CRUM	14.7. NA	Phone # ( )
Address: P.O. Box	g	Employee Justin Scott
Location: Guyton Rd, Little Lick Br, top		id.
GUYTON RD		in a manufacture of the second
Type of Work: Complaints	e de la compansión de l	a and the second control of the second contr
Material Used:	Bungan Bangan ayan ayan sanar bir sistera	to a constant
		. Philipsychology with the methodology of the second secon
Comments: low pressure	for a lak	Shapping and the state of the s
Current System Information:	gard the free and the second of the second order of the	New Information:
Meter # 1: 29935077	Meter # 1:	m es human sans s
Meter # 2: Radio 29935077	Meter # 2:	Radio
MXU#:	MXU#:	e i a manage energy and another the
Current Reading 5/20/2015 632		eading 0
Type of Meter: Badger	Type of M	eter:
Year MFG: 2004	Year MFG	<b>3:</b>
GPS - Longitude 0	GPS - Lat	itude 0
Employee Signature(s): R5+ T	SS. Date	e Completed 6 29

387 East Main St., Suite 140 Inez, KY 41224

### **WORK ORDER**

WO#

Time	e Started	a rincinantessagian	Work Complete	Company of the second of the s
Loc#	and the second s	Master	Meter#	and an annual company and an
Date 1/26/2016	manus annomonostro sures	Account #	SI	EQ# 408
Name: Haskel	Mills		Phone	# (6
Address: PO Box		sugar - co especial action and an artist and an artist and a sugar action acti		yee Rainbo
Inez, KY	<u>41224</u>	Marker 186 obsessed versus marketing and advantagement of the	transmissional visity / man	
Location: 4 Ur	nion Rd, clay house on	hill with green roof	- The Windows	A A A A A A A A A A A A A A A A A A A
	nion Rd		The state of the s	e egy per - Sangalingda samanamanamanamanaman p 8 9 - 440 4,98880000000000000000000000000000000000
Type of Work: Co	mplaints	A AMERICAN AND AND AND AND AND AND AND AND AND A	AND THE RESIDENCE OF THE PARTY	energy was a financial property of the property of the second second second second second second second second
				and the second s
Customer Line Ins		, <del>,,,</del>		
Comments: extre	The second secon	& MCOD	145 alea	k link com Not
Current	System Information:	na - vyronina rode pri internacioni i internacioni i internacioni i internacioni i internacioni i internacioni	Ne	w Information:
Meter # 1:	70616597		Meter # 1:	and the second s
Meter # 2: Radio	70616597		Meter # 2: Radio	
MXU#:	13155911	•	MXU#:	-
Current Reading	12/20/2015 285	The state of the s	Current Reading	0
Type of Meter:		november de la la companya de la com	Type of Meter:	Andrews and the second
Year MFG:	paramikaninananinan wasan 11 w wasa samansaanananananananananan	en grannen anna an anna anna anna anna anna	Year MFG:	
GPS - Longitude			GPS - Latitude	
Employee Signatu	(150(c): 7=	. ************************************	Date Comple	sted 1-20/11

387 East Main St., Suite 140 Inez, KY 41224

#### WORK ORDER

WO#

Time Started		<b>V</b>	Vork Complete	un commitmentation was sure s A , , , )
Loc#	Sp. Age 1, Sp. 1, Sp. 1	Master M	eter#	
Date 1/26/2016	легия и выи и игр шистр че в . Этомунийнического	Account #	SE	Q# 408
Name: Haske	I Mills	s 100 s hanne standardens person	Phone #	£ (
Address: PO Bo	<b>)X</b>		Employe	ee Rainbo
Inez, I	Y 41224	ees x - x - x - x - x - x - y - moon of an outer manner man a name	······································	
	Union Rd, clay house on hi			The state of the s
1 8000 4 800000	Jnion Rd		Action of the second of the se	The state of the s
	Complaints QUL Ju			Py
Material Used:	alle fin	it so	they sh	ald.
Customer Line I	110		well.	
Comments: extr	emely	* * * * * * * * * * * * * * * * * * *		and the state of t
Currer	nt System Information:	and a second consideration of the second	Nev	v Information:
Meter # 1:	70616597	and the same of th	Meter # 1:	Administration by accompanying particularly designed that the same state of the same is a second of th
Meter # 2: Radio	70616597	1.00 \$ 100 An applicamental property.	Meter # 2: Radio	and the second s
MXU #:	13155911	ar sa jana <del>jana jana jana jana jana jana ja</del>	MXU #:	Annual framework of the state o
Current Reading	12/20/2015 285	a magaza de a januaria	Current Reading	0
Type of Meter:		·· >	Type of Meter:	for the first section of the section
Year MFG:	• incommunication and income we designed to a second of 20 to	and sometiment	Year MFG:	N. A. MARKAMAN MARKAMA
GPS - Longitude	Commence of the contract of th	and a succession of a successi	GPS - Latitude	
Employee Signa	iture(s): B, T	igo a h. d s.j., normanna nakanaman kanamanna nakanamanna nakanamanna nakanamanna nakanamanna nakanamanna naka	Date Complet	ed 1-28-16

387 East Main St., Suite 140 Inez, KY 41224

### **WORK ORDER**

	WO #	1601002	215	
	Time Started	. W	ork Complete	
Loc#	umbra grunga, g distanta go alla distanta distantina di sanganta si sanganta sa	Master Me	ter#	
Date 1/20	/2016	Account #		SEQ # 245
Name:	LON CRUM		Phon	e# ( ` ^
Address:	P.O. Box		Empl	oyee Troy Horn
	Inez , KY 41224	v • 5	desk to	
Location:	Guyton Rd, Little Lick Br, top o	f hill last house @ to	pp of hill, red	
Type of W	/ork: Complaints	w will be substituted and the substituted and		The state of the s
	Ised:	00)	Ac . Monocontrol Company	
15	s: no water   Has water   Land	part low	jungsu j	hhkit 15 case cuery on lew Information:
Meter#1		·-	Meter # 1:	
Meter # 2:	Radio 29935077	man van dar van van van de kant de jare de	Meter # 2: Radio	
MXU #:	A commence the designation of the second	general and a second	MXU#:	
Current R	eading 12/20/2015 653	n paga sa <del>gla saglamadhinadh.</del>	Current Reading	0
Type of M	eter: Badger	nack and a second a	Type of Meter:	
Year MFG	S: 2004	······································	Year MFG:	
GPS - Loi	ngitude 0	www.www.cophys ² -mare resemb	GPS - Latitude	0

Employee Signature(s): 35

Date Completed ( 25 76



387 East Main St., Suite 140 Inez, KY 41224

### **WORK ORDER**

N	0	#	•

Tin	Time Started Work Complete			na je na razio Brig. Se		
Loc#	Master Meter #					
Date 1/6/2016		Account#	SEQ# 2	19		
Name: Charlie	Jude	~440, \$ 1.440.00 mm m	Phone # (C	and a management of the state o		
Address: 8 C	oldwater Rd	. <u>2 - 4 - 4 - 4 - 4 - 4 - 4 - 4 - 4 - 4 - </u>		stin Scott		
lnez, K	W 44004		alphanisauri va			
Location: 1 Sp	ence Br. Milo. 1/4 mile on lef			and the second s		
Sp	ence Br		·	and an angle of the second		
Type of Work: Co	omplaints		and the second s	aggregorium anno anno anno anno anno anno anno ann		
Material Used:	2 3/4" Care	es daset	38 of 5/4	11 likes 2 South to al		
Customer Line In	espection: Re Jac	Chex Clo	Solp	11 likes 2 South of		
Comments; cree	k crossing is uncovered; pos	sibly froze off	reed Clossic	reals to be Rectag		
Curren	t System Information:		New Infor	mation:		
Meter#1:	47823965		eter # 1:			
Meter # 2: Radio	47823965	M	eter#2: Radio	And the constraints of the constraints addinguistic the constraints.		
MXU #:	4400	M	XU #:	the second secon		
Current Reading	12/20/2015 1113	Cu	urrent Reading	0		
Type of Meter:	Sensus	Ty	pe of Meter:	A open		
Year MFG:	1993		ear MFG:	- In the second water and the second		
GPS - Longitude	washining and a state of the st	<b>.</b>	PS - Latitude			
Employee Signat	cure(s): 35,55,0	SIK	Date Completed /	-19-18		

387 East Main St., Suite 140 Inez, KY 41224

### **WORK ORDER**

**WO#** 

Employee Signature(s):

Tir	ne Started	······	/ork Complete	
Loc#	man a serience de la companya de la			
Date <u>1/20/2016</u>	Someting all all the state of t	Account #	SEQ# 143	
Name: WILBE	RT WEBB	AND MAIN AND THE PARTY OF THE P	Phone # {	
Address: PO BC	V.		Employee Rainho	
LOVE	Y , KY 41231		•	
Location: F			i house	
Type of Work: C	complaints	1000000 and 1000000000000000000000000000000000000	auch den voordensteren verschoolster werden versche ve	
Material Used:				
Comments: all in	mmediate neighbors are o	. /,		
Currer	nt System Information:		New Information:	
Meter # 1:	99085874	and the second s	Meter # 1:	
Meter # 2: Radio	and the second s	The second secon	Meter # 2: Radio	
MXU#:		o o oppor agrana administrativa	MXU #:	
Current Reading	12/20/2015 1169		Current Reading 0	
Type of Meter:	Badger	And the second of the second o	Type of Meter:	
Year MFG:	1999	0000000000000000 of a full file to the f	Year MFG:	
GPS - Longitude	) O		GPS - Latitude 0	
Employee Signa	iture(s):	and the second s	Date Completed 1-20-16	

387 East Main St., Suite 140 Inez, KY 41224

### **WORK ORDER**

WO # 160100203

Time Started V			Work Complete		
Loc#	ny				
Date 1/16/2016	THE RESIDENCE AND AND EXCHANGES AND THE PROPERTY OF THE PROPER	Account #	SEQ# 106		
Name: GARY	& Trish HUNT		Phone # (		
Address: PO BO	X		Employee Justin Scott		
INEZ	, KY 41224		***************************************		
Location: C			The second secon		
CASSI			And the second s		
Type of Work: C	omplaints	mannagipumman anjara manan ayin assam x mmanan a			
Material Used:					
********	4 7	1	1		
Customer Line In	spection: Turned	Pump Sta	ution back on		
Comments: no w	rater	•			
	t System Information:	MALINA MALAKA A P V Proprincipal malina mali	New Information:		
Meter#1:	29935252	<u></u>	Neter # 1:		
Meter # 2: Radio			Neter#2: Radio		
MXU #:			ΛXU#:		
Current Reading	12/20/2015 1087		Current Reading 0		
Type of Meter:	Badger		Type of Meter:		
Year MFG:	2004		Year MFG:		
GPS - Longitude		(			
	0	der aller Aller against and a Apple	GPS - Latitude 0		



Inez, KY 41224

### **WORK ORDER**

WO#

Time Started		Work Complete	
Loc#	Master N	Meter#	E
Date 1/19/2016	Account #	SEQ# 44	3+ 74-4-1-1-1
Name: GLADYS STACY	· / A Thrown or Assessment and Asses	Phone #,	, to A TO THE A STATE OF THE A
Address: P.O.BOX	vice sick file at a residence stranger and administration of the second	Employee Justin Scott	
INEZ , KY 41224]	W. 2 4 400-14 400000000000000000000000000000	·	
Location: Aaron St	Section and the section of the secti	management with the second of the second	Andrewson Go. and control &
ا معدد المعدد المعدد المعدد المعدد	** ***********************************	you can write out to the second	*
ROUTE 40 EAST	and despending street or the street of the s		
Type of Work: Complaints		The same of the sa	A, Sociausia Novi Associator State Astronologo A,
Material Used:		in the second second	2 - 4
Customer Line Inspection	(7)00		41 mass Washington
Comments: low water pressue	ad 75	PST At loox	
Current System Information:		New Information:	
Meter # 1: 29934551	o and a state of the state of t	Meter # 1:	3 × ·····
Meter # 2: Radio	No. Britan.	Meter # 2: Radio	
MXU #:	филоментом	MXU #:	سه منافع د پیدارستان و دی
Current Reading 12/20/2015 609	with armount.	Current Reading 0	to an amount and the good of a summan.
Type of Meter: Badger	a de granda de	Type of Meter:	V. 2
Year MFG: 2004	n andriving in	Year MFG:	100 J. C. S. S. STANSON STANSO
GPS - Longitude 0	ar <del>ini</del> .	GPS - Latitude 0	t var god variable variable in
Frankling Signatura(s): (TC	M/ workersteller on the relative section was included to	Date Completed 1 - / 9 - /	s presidenti e sominimo en Vilia



387 East Main St., Suite 140 Inez, KY 41224

### WORK ORDER

WO #	160100171	terry an administr
Time Started	Work C	omplete
Loc#		Summing and the second
Date 1/15/2016	Account#	SEQ # 47
Name: William Davis		Phono #
Address De Day		Familiary Luction Conff
lnez , Ky 41224		
		and the second s
	en anno anno anno anno anno anno anno an	and the second s
Blacklog	and the second	
Type of Work: Complaints	and the second s	A STATE OF THE STA
		and the second s
	1-1-	
Customer Line Inspection froze on custome	rside	
		The second secon
Current System Information:	COLORO CE	New Information:
Meter # 1: 18576453	Mete	r#1:
Meter#2: Radio	Mete	r#2: Radio
MXU#:	MXU	#:
Current Reading 12/20/2015 257	Curre	ent Reading 0
Type of Meter: Badger	Туре	of Meter:
Year MFG: 2002	Year	MFG:
GPS - Longitude 0	GPS	- Latitude 0
E .		

Employee Signature(s):

Date Completed___

387 East Main St., Suite 140 Inez, KY 41224

#### **WORK ORDER**

	WO #	151200130	_ ~~~
	Time Started	Work Com	plete
Loc#		** * ** * **	and the state of t
Date 12/2	30/2015	Account #	SEQ# 170
Name:	Elsie Jarvis		Phone # 6
Address:	PO Box		Employee Justin Scott
	Inez . KY 41224	······································	
Location:			
•	Happy Hollow		
Type of V	Vork: Complaints		<del>\</del>
Material (	gan agan gan agan gan agan ga gan kadan an a		
	r Line Inspection	Kainto Fuendi	+ up on the 4.14
	Current System Information:		New Information:
Meter # 1		Meter#	1:
Meter # 2	Radlo	Meter # 2	2: Radio
MXU#:	SURCESSARIAN DE DE PROPERTO PERO PORTE - S ADMINISTRA DE PROPERTO PORTE - S	MXU #:	
Current F	Reading 0	Current F	Reading 0
Type of M	Meter:	Type of I	Meter:
Year MF0	<b>G</b> :	Year MF	G:
GPS - Lo	ngitude	GPS - La	atitude
Employee	e Signature(s):	Dat	te Completed 1 - 4 - 15

387 East Main St., Suite 140 Inez, KY 41224

#### **WORK ORDER**

**WO#** 

Employee Signature(s): 7K, TS, 3S

151100139

Time Started Work Complete Yes Master Meter# Loc# Account# SEQ # 31 Date 11/13/2015 Phone # WENDELL STEPP Name: Employee John Stafford Address: P.O. Box ( INEZ, , KY 41224 Location: __ Twin Oak Dr., red brick home CASSADY AVE. Type of Work: Complaints Material Used: Customer Line Inspection: fixed leak Comments: extremely low pressure **New Information: Current System Information:** 70616430 Meter # 1: Meter # 1: Meter # 2: Radio Meter # 2: Radio 70616430 MXU#: 13155681 MXU #: **Current Reading** Current Reading 10/20/2015 195 Type of Meter: Type of Meter: Year MFG: Year MFG: GPS - Latitude GPS - Longitude

**Date Completed** 

387 East Main St., Suite 140 Inez, KY 41224

#### **WORK ORDER**

WO#

160200213

Tin	ne Started	· .	Work Complete			
Loc#	ans & constant answers and an entitle control between a	Master N	Meter#	emmanyany with wast T	C NO SAKE SERVICEMENT OF THE C	
Date 2/22/2016	ounders — you or have the great of the contraction	Account #	s .	SEQ # 163	or a samon summe	
Name: MIKE	IORN	and a section of a section of the se	Phon	e# (	у : / т	
Address: Dak	tie Drive		Empl	oyee Troy Horn	e la Monta	
INEZ, I	KY 41224	and the second s	openium () (d) (d)	,		
	kie Dr of Calf Creek, 5tl			- man analysis of the second	s y a service construction of a manifest and continues to the continues of	
egyssalannichtergene v com	manus as sudaranamando describir par sa su es			a salah bada a salah s	and the second second second	
CALF	CREEK		( )N	e	,	
Type of Work: C	omplaints		N. C.			
AA-tt-I Handy	.,			13 - 6	_	
	50 Ft - 1" Line				en ( V ) and the day of the second second	
Customer Line Ir	nspection:	an financia de la companya del companya de la companya del companya de la company	managa managa sana asakas as	ree e ver	\$ \$ \$ #\psi = \text{manages }	
Comments: no w	vater	A CONTRACT STATES OF THE STATE	add was in the think of the sense of the sen	entering the second	e e e e e e e e e e e e e e e e e e e	
	t System Information		<u> </u>	lew Information:	of manufacture follows in injurience of 1980 to 1 1981, in	
Meter # 1:	29935042		Meter # 1:		walker and the control of the contro	
Meter#2: Radio	29935042	e the graph has space assumption	Meter # 2: Radio	San		
MXU #:		a decima and the state of the decimal of the	MXU #:	was a series of the second of the series of	against français ann ann an ann an ann an ann an an an a	
Current Reading	1/20/2016 200		Current Reading		management of the second of th	
Type of Meter:	Badger	on duas, dudhaga duscordar registarione	Type of Meter:	- Agus ang ang animona a sa a sa a sa m	and the second s	
Year MFG:	2004		Year MFG:	ma ckamatyrak histori	S & desiles and the desiremental section with the second	
GPS - Longitude	0		GPS - Latitude	0	· · · · · · · · · · · · · · · · · · ·	
and the second s	humatali N	<u> </u>	Pate Comr	Neted 2/25/	. Same is standard the management about a symmetry	

The Something and the

387 East Main St., Suite 140 Inez, KY 41224

### **WORK ORDER**

WO#

Tim	ne Started		Work Complete	
Loc#	Frankansan renimentah His minimen a. n. n. n. 1 paddididigan - menin	Maste	er Meter #	y egye ya ya gamana ya gaya e e e uz
Date 2/18/2016	Accoun		SEO # 902	
Name: CLYDE	WALLER		Phone #	والمرافق المرافق المرا
Address: H	ode Rd		Employee Rainbo	
	FID KY 41267		Furthermodage to Acc.	
Location: 5 H	ode Rd		annonnamente manere manifestature o o o o o o o o o o o o o o o o o o o	,
	and a street state of a superior and a state of the state			and the second
·				
Type of Work: Co	omplaints	January & 4 (1948) 1878) 1879	ING BOAK COMMONTORS ENGINEERING AND AND CONTROL AND	ne amenimenta que somera a como y
Material Used:	anna anna de del antamanta d'alta del pubble de la companio de la companio de la companio de la companio de la	يمسي شيودي	adambanan guydimma ag mam yyd gyrri gyrrinian araba manan manag Arig V. Argyr. — mirribyrrinna 190 yr i 111 Fr	per transcription of the Control of
Customer Line In:	spection Droblem C	۱۸ ۱	customors side	
Comments: no w	•		and the second section of the section of the second section of the section of the second section of the section of th	WWW. Commencement and 113 Trape, 15
		Artematica and Artematica	and the second s	The state of the s
Current	System Information:		New Information:	
Meter # 1:	29935145		Meter # 1:	and the second power of the second se
Meter # 2: Radio	an promoved among the first of the second of the second order of		Meter # 2: Radio	where is a magnitude of the second desirable and a second d
MXU#:	interference of the commence of the confidence o		MXU #:	:
Current Reading	1/20/2016 445		Current Reading 0	yanna sain, a sa manan
Type of Meter:	Badger		Type of Meter:	To annual and the state of the
Year MFG:	2004		Year MFG:	nessados e mineral presenta de la compansa de la co
GPS - Longitude	0		GPS - Latitude 0	entropy and process of parts of the self o
Employee Signate	ure(s):		Date Completed $2 - 18$	-/6

387 East Main St., Suite 140 Inez, KY 41224

### **WORK ORDER**

WO #

	V	<i>1</i> 0 # 160	200184	
Tin	me Started	15 Tp2000 MINISTER	Work Complete	
	anna ar o granderska kalendar ve je – v Cras cer den			minimum minimum manifed (a. v. v. v.) appears resourcement (v.)
Date 2/16/2016		Account #	Try - man-relational from territoria	SEQ# 494
Name: MARK	FITCH		Phon	e# (
	eeping Cherry Ln		Empl	oyee Troy Horn
INEZ	, KY 41224]			****
				an ritteraturus variationassa antanta e de de destita esta d'entre d'entre d'entre d'entre d'entre d'entre d'e
- annum en e à sud nom	This production the state of th	* 99 00 000 000 000 000 000 000 000 000		Ka
ABBS				and the second s
Type of Work: C	complaints	AN ANNOUNCE CONTROL OF THE STATE OF THE STAT		
Material I lead:				. 3/, 10 1" dal 1 f
Material Oscu.	it coups	$\frac{20}{1}$	T of 14 aun	e; 3/4 to 1" staublist
Customer Line In	nspection: <u>ran</u>	temp !"	to sty my	ine across bridge
Comments: no v	vater		his is also the same of the same and the sam	and the second s
Curren	nt System Informatio	n:	N	ew Information:
Meter#1:	29934818		Meter # 1:	
Meter # 2: Radio	TO CONTROL OF THE CON	información e a militario de mi	Meter # 2: Radio	
MXU#:			MXU#:	
Current Reading	1/20/2016 1072		Current Reading	0
Type of Meter:	Badger	nadione of the contract of the	Type of Meter:	
Year MFG:	2004	any demonstration was an appropriate trans	Year MFG:	
GPS - Longitude	0	non-religional desiration of the state of th	GPS - Latitude	0
Employee Signa	ture(s): JS,OS	,TH	Date Compl	leted 2/17/16

387 East Main St., Suite 140 Inez, KY 41224

### **WORK ORDER**

	WO #	160200190
Time Sta	arted	Work Complete
Loc#	<u> </u>	Master Meter #
Date 2/17/2016	Account	# SEQ# 82
Name: DIANA SLON		Phone #
Address: Phoebe		<b>5</b>
BEAUTY	, KY 41203	An and the second secon
Location: Pheobe	Troc	
PHOEBE TR	resonance resonance from a popular contract of the second advantage and a second contract of the second contract o	
Type of Work: Compla	ints	
Customer Line Inspect	ion: <u>CUSTONOT NO</u>	o worker @ box
	em Information:	New Information:
Meter # 1: 2993		Meter # 1:
Meter # 2: Radio	akatatuurin ( - akatatatun ka arring yoro er ah aring ( xiri). Mah akriminin ka arring ( xiri) arring arring a	Meter # 2: Radio
MXU#:		MXU#:
Current Reading 1/20/	2016 280	Current Reading 0
Type of Meter: Badg		Type of Meter:
Year MFG:	radium vo co k y v se seguio ser ine in morte prominimo interiorità di morte della constanti	Year MFG:
GPS - Longitude 0	namenana amerikanski sakoli (2. d. k.) v. v. v. sako (2. s. sakoli kanana amerikanski alikularak alikularak k	GPS - Latitude 0
Employee Signature(s)	. RJ	Date Completed 2/7/16

Employee Signature(s):

387 East Main St., Suite 140 Inez. KY 41224

### **WORK ORDER**

	W <i>W</i> # 1602	00025	
Time	Started	Work Complete	
Loc#	Master	Matar #	
meg nu e un	- A Committee of A Committee of the Comm	Weder #	and the state of t
Date 2/3/2016	Account #	SEQ# 316	*
Name: HELEN M	ICGINNIS	Phone.# (	
Address:Tom	nahawk Road	Employee Justin Scott	
TOMAHA	WK, , KY 41262		
Location: Tom	nahawk Rd; Donna Jude	manus (manus (manus manus ( Kunika ) K m 197 paga ( manus manus ( manus )	**************************************
38 X. VALLE	and comments of the same of th		ا بالمركزة عاسد
ROUTE 4	0 WEST		and a represent to the second of the
Type of Work: Com	plaints	DO	er saansterier in 1886 by a dear assist
Material Used:	rayed out Dan	F tar Soffer ad	Relatour
Customer Line Inspe	ection She Said Hut	It Is a lot Get	hr Pressy
Comments: low pres	ssure; check for problems	5I At box now	
Current Sy	stem Information:	New Information:	pure a separation of the separ
Meter # 1: 942	261251	Meter # 1:	3
Meter # 2: Radio	The second secon	Meter # 2: Radio	and the state of t
MXU#:	the second secon	MXU #:	* ************************************
Current Reading 1/2	20/2016 615	Current Reading 0	· Communication of the second
Type of Meter: Bac	dger	Type of Meter:	All services and the services of the services
Year MFG: 199	94 	Year MFG:	Anna Anna I anna I
GPS - Longitude 0	of the second	GPS - Latitude 0	f.

Date Completed 2 - 9 - 16

Employee Signature(s):

387 East Main St., Suite 140 Inez, KY 41224

### WORK ORDER

**WO** #

Time Starte	ed	Work Complete	
Loc#	Mas	ster Meter #	a dan wakananan manangkan - para sa minangka
Date 3/23/2016	Account #	SEQ # 276	e a families of the second way
Name: ILENE HARDIN	N	Phone # (	a summing any and the second section of the
Address: 3 North Mile	a		e coming grower or soon the
TOMAHAWK	, KY 41262	nommunitatus 1900 - Sumus 1900 olima	
Location: North Mil		om church.Grey house w/red roof and shu	itters.
	and the confidence of the supplier of animal of the rational analysis and the same	25 ประชาการแบบแบบแบบเกรียร์ (2 2 รุงเพราะ) สำหัก - จะ จะรับ (2 รุงเหม ) 2 เพราะ เพลาะละคุณสมเดิมและการสะ เกิดแบบ ความ ละละสมัยส์ สำหรับสามารถ 2 ระวาว (2 รุงเหม ) เกิดเกราะ เกิดเกราะละครามและสมเดิมและสมเดิมและสามารถ	entre est en son de la companya del la companya de
ROUTE 1884 I	MILO		
Type of Work: Complain	ts	Andrew Seas to versus management and so I am 2 . I see symmetic management the management of the season of the sea	way or supression and the supression of the supr
Material Used:	the committee of the contract	minute mystyle - to me can be suite minute as on a minute service and any and any	agang hijin saan dad 2 saan deriftoo dii jidhil da deeringa dhe sa dhe h
Customer Line Inspection	n \to	2 1	and an opin and appears of expression of the contract of the c
Comments: low water pr		and loops. It have	т ду кашдара ардан төс гүшчүн түр мэрү
Current System	m Information:	New Information:	and a new season of the season
Meter # 1: 704725	580	Meter # 1:	ioni trivi est, e en nom estate in inc.
Meter # 2: Radio	nick demonster der des der einer Sp. seppendigklicht, is gedeutschaften und der de de de	Meter # 2: Radio	المراجعة المراجعة والمراجعة المراجعة المراجعة المراجعة المراجعة المراجعة المراجعة المراجعة المراجعة المراجعة ا
MXU#:		MXU #:	A SE MINDS MA SENDER WE WAY
Current Reading 2/20/20	016 309	Current Reading 0	يىنىدۇرىدىن ئىلىدىنىدىنىدىنىدىن دىنىدۇرىدىنىدىنىدىنىدىنىدىنىدىنىدىنىدىنىدىنىدى
Type of Meter: Sensus	S	Type of Meter:	La partition of the property of the second o
Year MFG: 2009	to the second of	Year MFG:	en de la company
GPS - Longitude 0	N. N. N. S. A. S.	GPS - Latitude 0	nd material and make the second of a second
Employee Signature(s):	JS JS	Date Completed	3.46

387 East Main St., Suite 140 Inez, KY 41224

#### **WORK ORDER**

**WO#** 

160300161

Time Started

Work Complete (

Loc#

Master Meter #

Date 3/16/2016

Account #

SEQ# 154

Name:

Willie Mollette Jr.

Phone #

Address:

Emily Crk

Employee Troy Horn

Pilgrim, KY 41250

4 Emily Crk, White house with green roof above Terry Harmon on right

**Emily** 

Type of Work: Complaints

Material Used: Spoke with Customer Has wester, Good prossure in Commende + Both tube Just law prossure in Kitchen sink.

Customer Line Inspection: Problem with Customer.

Comments: meter was relocated; now customer has no water

#### **Current System Information:**

New Information:

Meter #1:

70840680

Meter # 1:

Meter # 2: Radio 70840680

Sensus

Meter # 2: Radio

MXU#:

MXU#:

Current Reading 2/20/2016

Type of Meter:

Type of Meter:

**Current Reading** 

Year MFG:

Year MFG:

GPS - Longitude 0

GPS - Latitude

Employee Signature(s):

8/Te/Js

Date Completed 3/22//6

387 East Main St., Suite 140 Inez, KY 41224

#### WORK ORDER

WO#

160300208

Time Started

Work Complete

Loc#

Master Meter #

Date 3/24/2016

Account#

SEQ # 185

Name:

Phone # ( ., .. ....

Address: PO Box

Employee Rainbo

Beauty, KY 41203

Gracie Reed

Location:

Cliffside Dr, Moore's Trailer Prk, Last trailer on the right on the bank, brown

1 Cliffside Dr

Type of Work: Complaints

Material Used:

**Customer Line Inspection** 

Comments: 626-6846

no water pressure

40 egmpc

**Current System Information:** 

Meter # 1: 16721209

Meter # 2: Radio 16721209

MXU#:

Current Reading 2/20/2016 761

Type of Meter:

Badger

Year MFG:

2000

GPS - Longitude 0

New Information:

Meter # 1:

Meter # 2: Radio

MXU #:

**Current Reading** 

0

Type of Meter:

Year MFG:

GPS - Latitude 0

Employee Signature(s)::

KS

**Date Completed** 

3-24-16

387 East Main St., Suite 140 Inez, KY 41224

### **WORK ORDER**

WO#	,	1602002	12

Time Started Work Complete			eige.	
Loc#	immegalahan salah salahan salah s	Master Meter #	S. WWW. P. MINISTER CO. C.	
Date 2/19/2016	employment of a colonic day of the analysis of the colonic col	Account # 1	SEQ# 84	to live of the section of the sectio
Name: EDDIE	HINKLE		Phone# ()	- was the first the state of th
Address: P.O.BO	DX (	and the second s	Employee Rainb	)
BEAU	ΓΥ , KY 41203	· ·		
Location: Bo	one Holw 2031.Lower Popla	r.Bone Hollow.1st trailer on r	ight at top of hill Grey	& white.
, , and , a				% -2x6+2 - wij ve v v sagarana maniferia angan ann
Type of Work: C	omplaints	de while the state of the design and the state of the sta	notice the second secon	. Annual productive and the second se
Material Used:	va, s valgation manner and an annual annual and an annual annual and an annual and an annual and an annual annual and an annual and an annual annual and an annual		nos	
Customer Line Ir	nspection			
Comments: wan	ts to know why the water is	so nasty. / installe	•	np.
Curren	t System Information:		New Informat	lion:
Meter # 1:	97728662	Meter #	1:	COMMANDA AND AND AND AND AND AND AND AND AND
Meter # 2: Radio	44 C	Meter#	2: Radio	
MXU#:	. N warner, and war was the analysis of the property of the contract of t	MXU #:	å ännannannen en	
Current Reading	1/20/2016 853	Current	Reading	0
Type of Meter:	Badger	Type of	Meter:	
Year MFG:	1997	Year M	FG:	
GPS - Longitude	0	GPS - L	atitude 0	
Employee Signa	ture(s): RJ	Da	ate Completed 3	19/18

387 East Main St., Suite 140 Inez, KY 41224

### **WORK ORDER**

WU #		10	ひとし	JUZZI		
	*********		,			
					_	

Tir	ne Started	M	Work Complete	چ <del>انجان المار</del> مرجاج فيد المار الم	
Loc#	ngine	Ma	aster Meter #	Control of the contro	
Date 2/22/2016	- 100000 p 1000 10 pp 100 10 pp 100 p	Account #	1	SEQ# 85	
Name: MAGG	IA HINKLE	N A in a final and adoption of the field and the second of t	Phor	ne# (	
Address: PO BO	ıx İ	1 1 2 1 1 2 2 mm s du l'anna di mana d	Emp	loyee Rainbo	
BEAU [*]	ΓΥ .	KY 41203	MMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMMM		
Location:' Bo	one Hollow o	n 2031, 1/4 of a mile on Po	pplar Fork on left, 1st sing	le wide on left	
gar a 1 / a de territorio	7			The state of the s	
				·	
Type of Work: C	omplaints	The state of the s	**************************************		
Material Used:				. Lange of the state of the sta	
Customer Line Ir	nspection:	;	nass fluguespanie work province were no see see seemanne	g pp. w. p. 10. pp. 100 g g g w 10 pp. 100	
Comments: low	pressure	/installed n	en brub	58 psi @ box	
Curren	t System In	formation:	I American Anna de marcil i guirran magar can caparague en agé civité c	New Information:	
Meter#1:	99085837	**************************************	Meter # 1:	to superior as an anamona and an anamona and a superior and a supe	
Meter#2: Radio	99085837	· · · · · · · · · · · · · · · · · · ·	Meter # 2: Radio	And the second s	
MXU #:	,	5-m5-y/2020 tage - No-2 - W	MXU#:	decreases the second of the se	
Current Reading	1/20/2016	623	Current Reading	0	:
Type of Meter:	Badger	· · · · · · · · · · · · · · · · · · ·	Type of Meter:	September 1 million and the september 1 miles and the september 1 mile	
Year MFG:	1999		Year MFG:	Zikanithaniya mininkara mininkara kalani	
GPS - Longitude	0		GPS - Latitude	0	
Employee Signat	ture(s):	R5	Date Comp	pleted 2/22/16	

387 East Main St., Suite 140 Inez. KY 41224

#### WORK ORDER

WO#

160300142

Time Started

Work Complete

Loc#

Master Meter #

Date 3/14/2016

Account# 4 ^

SEQ # 56

Name:

Phone # (

Address:

Flat Hollow

Employee Rainbo

Inez, KY 41224

Dick Young

Location: Flat Hollow, Last house

Flat Hollow

Type of Work: Complaints

Material Used:

**Customer Line Inspection** 

Comments: no water

**New Information:** 

Meter#1:

95748912

**Current System Information:** 

Meter#1:

Meter # 2: Radio 95748912

Meter # 2: Radio

MXU#:

MXU#:

Current Reading 2/20/2016 952

tightered fitting

**Current Reading** 

0

Type of Meter:

Type of Meter:

Year MFG:

Badger 1995

Year MFG:

GPS - Longitude

GPS - Latitude

Employee Signature(s):

**Date Completed** 

387 East Main St., Suite 140 Inez, KY 41224

#### **WORK ORDER**

160200226 WO# Work Complete Time Started Master Meter # SEQ # 347 Account # Date 2/23/2016 Name: Marcia Mills Phone # (6 Employee Troy Horn Address: PO Box 7 Inez , KY1 41224 Location: Tug River Rd, Trailor past Holbert Mills house on left Type of Work: Complaints Material Used: Customer Line Inspection: Checked Drain not Crushed, Classed up alteh Comments: MCWD unloaded equipment and crushed drain pipe; needs repaired and gravel needs put down **Current System Information: New Information:** Meter # 1: Meter#1: 70616407 Meter # 2: Radio 70616407 Meter # 2: Radio MXU #: 13153136 MXU#: Current Reading 0 Current Reading 1/20/2016 262 Type of Meter: Type of Meter: Year MFG: Year MFG:

Employee Signature(s): A / JK Date Completed 3 /11/16

GPS - Longitude

GPS - Latitude

387 East Main St., Suite 140 Inez, KY 41224

#### WORK ORDER

WO#

160300156

Time Started

Work Complete

Loc#

Master Meter #

Date 3/16/2016

Account #

SEQ # 130

Name:

Kenneth Aldrich

Phone # (****

Address:

Jollins Crk

Employee Justin Scott

Warfield, KY 41267

Location: ____ Yellow Crk Rd. White trailer on the left.

Yellow Crk Rd

Type of Work: Complaints

Material Used:

**Customer Line Inspection** 

Comments: water stinks

all the wax up Blanken Ship

**Current System Information:** 

Meter # 1:

47823868

Meter # 1:

Meter # 2: Radio 47823868

Meter # 2: Radio

MXU#:

MXU#:

Current Reading 2/20/2016

**Current Reading** 

0

**New Information:** 

Type of Meter:

Sensus

Type of Meter:

Year MFG:

1993

Year MFG:

GPS - Longitude 0

GPS - Latitude

Employee Signature(s):

Date Completed 3-/2-/6

387 East Main St., Suite 140 Inez, KY 41224

### **WORK ORDER**

WO #

Time St	arted	· · ·	Work Complete			
Loc#	سيرم سنسير در ۱۳۵۰ مستوده الا	Master Meter #		Constitution of the Consti		
Date 2/24/2016	ي نيست پر مستومت مه امي	Account #	e same viria menimina in	SEQ# 510	e to be associated	
Name: SHONNIE F	AULEY	· · · · · · · · · · · · · · · · · · ·	Pho	ne# <u>(</u> [[-	n observe these substances and the	
Address: P.O.BOX	on the same plants of the same and a same and		Emr	oloyee Rainbo		
Pilgrim	, KY 41250	maniference & St	rankfireksyrrer er remnend 300.			
Location: Little I	Rockcastle Rd just as	you start up 2032 l	hill,turn right at Jud	e's feed store,house	up on the hill	
San				on annual transcription of the second		
		•				
Type of Work: Compl	aints					
6#_4:_1 111.				and the same of	A selection and an annual selection and a sele	
A FAC .	An historia gradina de de la companio de la compani	A. A AND 30 - AND 50 - AN	minimum markete e v v via a visit e v v via a viva e viva e viva e v viva e	no mana a provincia a mana	a Tan was compared an annique game.	
Customer Line Inspec	tion:	gyzonie g www.wysminio gram	anglingman at my J. L. glimin't senson, bearanness one	modernijsvensjet end og i sam	Control of the second disconnection of the second disconne	
Comments: Low Pres	sure		announce to the second	and the company of the self-to-the test of the test of	graphone agraph Announce to the 1 th	
	tem Information:	randi k drafinov a kara wanne e <del>anakan ama karana awa</del>	The section of the se	New Information:	and the second s	
Meter # 1: 2993	84956	Control of the contro	Meter # 1:	man organis y man y agains organis Manth at the service of the ser	to the state souther commence the state of t	
Meter # 2: Radio	an de san a san an a		Meter # 2: Radio	were the second	e commence and environmental environment	
MXU#:	ie was kan was was san sa	erk meges je	MXU#:	name namenomous statistic de la construcción y estas en un	and the company of th	
Current Reading 1/20	/2016 404	ere ( ) and	Current Reading	0	No. 40 1 % About the second incommentation of	
Type of Meter: Bad			Type of Meter:	Volume and the annual and the second of the	k o go Sensa - sensana mana ammanana mana managa na managa	
Year MFG: 2004			Year MFG:	mana a risam yaga a a e e a a a e y a	* * * * * * * * * * * * * * * * * * * *	
GPS - Longitude 0	on the state of th		GPS - Latitude	0	with petining an evaluation of them to be	
), yaya, ayar yaya, ay wa wanananana namanananan namanananan na ay a a a a a a a a a a a a a	og og geng å men nye en menenske i skrivenske i skrive gjeler.	an gantang a na namana ang ang ang ang ang ang ang ang ang		Zanamanininana in Siritinos automaga er go 🤭 esagye		

387 East Main St., Suite 140 Inez, KY 41224

### **WORK ORDER**

160200217

WO#

	m managamananan ang 1 10 - Januaran	manufacture - 1, and the property of the contract of the contr		
Time Started Work Complete				
Loc# Master Meter#				
Date 2/22/2016	Account#	SEQ # 4		
Name: BECKY GRIFFITH	man v * * * * * * * * * * * * * * * * * *	Phone # (60)		
Address: PO BOX		Employee Justin Scott		
INEZ KY 41224	annan antan in 19 maa aa ah ah aa ah a	₹ -unda Wentermore		
Location: E Main St, across from	Pizza Stop	annocumento Espetinte - su, alla constanta e 159 - 5 e 3 e 3 e sumo manocumento e quanto monte e a a a a a a a		
The state of the s				
Type of Work: Complaints  Material Used:  Customer Line Inspection: Comments: low pressure; check pressure	sure at the box	Timber 600 X		
Current System Informatio	n:	New Information:		
Meter # 1: 19667728		Meter # 1:		
Meter#2: Radio	The second control of the Second Control	Meter # 2: Radio		
MXU#:		MXU #:		
Current Reading 1/20/2016 434	is and a state of the state of	Current Reading 0		
Type of Meter: Badger	responsive management and constructive devictors and constructive devictors.	Type of Meter:		
Year MFG: 2003	innerine un a sa caire de l'inné.	Year MFG:		
GPS - Longitude 0	Haman of Samuel or Calendary or Calend	GPS - Latitude 0		
Employee Signature(s):		Date Completed 3-7-/6		

387 East Main St., Suite 140 Inez, KY 41224

### **WORK ORDER**

	WO #	160300030	········
	Time Started	Wark Con	nplete
Loc#		Master Meter #	·
	/2016	Account #	SEQ# 128
	Vina Sue DREECE		Phone # (
Address:	_ Blacklog Rd	-	Employee Rainbo
	INEZ, , KY 41224		•
Location	: Rreece Hill on Blacklog; Tri-le	vel house.3rd driveway.	
	A STATE OF THE STA	-	
	ROUTE 40 EAST	16	
Type of I	Work: Complaints		
•.			
Material	Used: 100 - 3/4 Couplier,	3/4 insect , 8/	1-41 (jac
Custome	er Line Inspection:		
COMMINE	110. 110W WOLCO		
	<b>Current System Information:</b>		New Information:
Meter#	1: 29935412	Metera	<b># 1</b> :
Meter#	2: Radio	Meter	# 2: Radio
MXU#:	According to the second	MXU#	
Current	Reading 2/20/2016 450	•	t Reading 0
Type of	Meter: Badger	Туре с	of Meter:
Year MF	FG: 2004	Year N	/IFG:
GPS - L	ongitude 0	GPS -	Latitude 0
Employe	ee Signature(s):		Date Completed 3/7//

387 East Main St., Suite 140 Inez, KY 41224

#### **WORK ORDER**

WO # 160200266

Т	ime Started	Work	c Complete
Loc#	ingi, mar a arabi a ahi . v . a . b'iza . r	Master Meter	#
Date 2/26/2016		Account #	SEQ # 11
Name: Denz	il Marcum		Phone #
Address: PO B	<b>ox</b> {	A GASTA A TANKA	Employee Rainbo
Lovel	ly, KY 41231	\$	nuce states.
Location: UVi	rginia St, 2nd on right, b	eige house w/maroon shutte	ers
GAS	OLINE ALLEY		And the state of t
Type of Work:	Complaints	African I response a more many mark	
Material Used:		Dee	
Customer Line	Inspection		
Comments: has	s low pressure	Elked to CLS	House It of Hall good Meson e Hall a leck New Information:
Curre	nt System Information	1:	New Information:
Meter # 1:	98604661	Me	eter # 1:
Meter # 2: Radio	e e e e e e e e e e e e e e e e e e e	Mo	eter#2: Radio
MXU#;	al a like a leasure of the longer transfer of the longer transfer of the life	Salu III in the second constraint	XU#:
Current Readin	g 2/20/2016 486	Cl	urrent Reading 0
Type of Meter:	Badger	Ty	/pe of Meter:
Year MFG:	1998		ear MFG:
GPS - Longitud	e 0	G	PS - Latitude Ö
Employee Signa	ature(s). T	and the second section of the second section of the second second second second section second section section second section second section s	Date Completed 3-8-16

387 East Main St., Suite 140 Inez, KY 41224

### **WORK ORDER**

WO#

Time Started	Work Complete			
Loc#	Master Me	eter#		
Date 4/22/2016	Account# '	SEQ# 223		
Name: Miranda McCoy	) ). W '	Phone # (		
Address: P.O. Box :		Employee Rainbo		
Beauty, KY 41203		e e e e e e e e e e e e e e e e e e e		
Location: Big Elk Rd. Across from V	Vater Tower, grey trail	er :		
•	X **	The state of the s		
Big Elk Rd	V F W W gr W	and the second s		
Type of Work: Complaints		and the second s		
Material Used:	a say .	المرابع والمعارض والمعارض والمرابع والمرابع والمعارض والم		
Customer Line Inspection 65 16	s PSI @	2 look		
Comments: no water	كالما درومة ويمرا	g ng gangrasa di ki ki kinanganan nyangganangsawa ni mbana ban		
Current System Information:	**************************************	New Information:		
Meter # 1: 29935189		Meter # 1:		
Meter#2: Radio 29935189	,	Meter # 2: Radio		
. MXU #:		MXU #:		
Current Reading 4/20/2016 426		Current Reading 0		
Type of Meter: Badger	<b>5</b>	Type of Meter:		
Year MFG: 2004		Year MFG:		
GPS - Longitude		GPS - Latitude		
Employee Signature(s):	/ en	Date Completed 122 11 a		

387 East Main St., Suite 140 Inez, KY 41224

### **WORK ORDER**

WO#

GPS - Longitude

Employee Signature(s):

160400195

	Work Complete		
Master M	eter#		
Account#	SE	Q # 496	
	Phone #	<b># (</b> (	
a	Employ	ee Justin Scott	
grey w/blue shutters	s. Wooten Rd		
	Committee of the commit		
90 tat	box I to	old her	
une the	P.R.V stoye	ungo:	
		A SAN A SECURIT SAME OF THE SAME OF	
Done			
	Nev	v Information:	
	Meter # 1:	C C Sp. C At	
** *	Meter # 2: Radio		
	MXU#:	· · · · · · ·	
	Current Reading		
· ·	Type of Meter:	,,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,,	
	Year MFG:	g the forest to the second	
	Master M Account # grey w/blue shutters	Master Meter #  Account #  Phone is Employ  grey w/blue shutters. Wooten Rd  Out the P.R.V staye  New Meter # 1:  Meter # 2: Radlo  MXU #:  Current Reading  Type of Meter:	

GPS - Latitude

Date Completed 4-21-16

387 East Main St., Suite 140 Inez, KY 41224

### **WORK ORDER**

WO#

160400121

		•			
Time Started			Work Complete		
	Loc#	Ma	ster Meter #		•
	Date 4/11/2016	Account #	SE	Q# 253	
	Name: Rowdy Kinser		Phone #	<i>‡</i> (	
	Address: PO Box Lovely, KY 41231		Employ	ee John Mills	
	Location: 2, Riverfront Rd	, 3rd blacktop drive on right	past Riverfront Store	·	
	RIVERFRONT		:		, .
	Type of Work: Complaints	Oa	ne 1% phatoff.	1-3/4 tee 3/4 N	peele
	Material Used: Put	in a Preseure	ne Bur shet off , chart 1-12 a	mici an	y
	Customer Line Inspection:			a cont for 700 austra Preson of	
	Comments: low pressure	Showing 100	PSI trached	austr Pieson J.f.	afe wite
	Current System In	iformation:	Nev	v Information:	
:	Meter # 1: 70750157	476 F. W	Meter # 1:	· v · vvv · ,	; ; ;
	Meter # 2: Radio		Meter#2: Radio		
	MXU#:	^* < ·	MXU#:	,	mes w jogment
	Current Reading 3/20/2016	242	Current Reading	. 0	9. Websel
	Type of Meter: Sensus	.s. w	Type of Meter:		en a company
	Year MFG: 2009		Year MFG:		A0040-0129 and **
	GPS Longitude		GPS - Latitude		,

Employee Signature(s): J5, TR, C5, RJ.

Date Completed 4-//-//6

387 East Main St., Suite 140 Inez, KY 41224

### WORK ORDER

**WO**#

Time Started	Work Comple	ete			
Loc#	Master Meter #				
Date 3/28/2016	Account #	SEQ # 233			
Name: Lydia Perry		Phone # (6 .,			
Address: PO Box (		Employee Justin Scott			
INEZ , KY 41224	. du v				
Location: Little Lick. Right fork of Little Lick Rd. Last house on hill. Brown					
	1	A service of the serv			
Little Lick					
Type of Work: Complaints					
Material Used:	and the second s	N. p. N. MANAGER MAY COMP. My 1.5 M.			
Customer Line Inspection: 3hat	off needs to	be church			
Comments: hissing noise and water is	Comments: hissing noise and water is coming from box even though meter has been pulled; land owner reported				
		e es ale			

New Information:
Meter # 1:
Meter # 2: Radio
MXU #:
Current Reading 0
Type of Meter:
Year MFG:
GPS - Latitude
And the second s
Date Completed 4-/-/6

387 East Main St., Suite 140 Inez, KY 41224

#### **WORK ORDER**

**WO#** 

160300208

Time Started

Work Complete Yes

Loc#

Master Meter #

Date 3/24/2016

Account # 1

SEQ # 185

Name:

Gracie Reed

Phone # 1

Address: PO Box '

Employee Rainbo

Beauty, KY 41203

Location: 1

Cliffside Dr, Moore's Trailer Prk, Last trailer on the right on the bank, brown

3 Cliffside Dr

Type of Work: Complaints

Material Used:

Customer Line Inspection: pump is on

Comments: 626-6846

no water pressure

New Information:

Meter # 1:

16721209

**Current System Information:** 

Meter # 1:

I has some issue

Meter # 2: Radio 16721209

Meter # 2: Radio

MXU#:

MXU#:

Current Reading 2/20/2016

**Current Reading** 

Type of Meter:

Type of Meter:

Year MFG:

Badger 2000

Year MFG:

GPS - Longitude 0

GPS - Latitude 0

Employee Signature(s):

Date Completed

387 East Main St., Suite 140 Inez, KY 41224


#### **WORK ORDER**


Employee Signature(s): RJ

Date Completed

		ORK ORDER	$\triangle$	
	WO#	160300208		
Time Started		Work Com	olete Yes	'AL
Loc#		Master Meter #		
Date 3/24/2016	Acc	ount#	SEQ# 186	\$ <b>4 4 4 1 1 1 1 1 1 1 1 1 1</b>
Name: Gracie Reed		4 3 3	Phone # ( , _ ;	. ,
Address: PO Box : _ Beauty, KY 41203	,	14 TO 15 TO	Employee Rainbo	
Location: J Cliffside Dr. Moor	re's Trailer Pṛḳ, La	st tr <u>ailer on</u> the <u>righ</u> t on	the bank, brown	
Cliffside Dr  Type of Work: Complaints  Material Used: Put guid  Customer Line Inspection: purns  Comments: 626-6846		one ) it do it he was on use the pump i		
Current System Infor	mation:		New Information	on:
Meter # 1: 16721209		Meter#	1:	2
Meter # 2: Radio 16721209	, ,	Meter#2	2: Radio	as a section
* MXU #:	···	MXU #:	*	· ·
Current Reading 2/20/2016 7	61	Current I	Reading (	;
Type of Meter: Badger		Type of i	Meter:	
Year MFG: 2000		Year MF	G:	
GPS - Longitude 0		GPS - La	titude 0	


Exhibit #11
Telementry Pressure Charts






Month July 102.67 95.33 36.67 51.33 58,67 14.67 29.33 73,33 7.33 22.0 0.33 88.0 44.0 0.0 14
Day
Day
18 ← 201

A Suction Pressure N Type |7Day 4  $\infty$ 햐 1 4 4 23 OI 2 1 5 a e N 9 ಕ 23 36 0








Exhibit #12
Public Notification

## עושְּׁמִינִין – שׁׁיְשִׁנְּשִׁוֹן וְנִשְּׁיִלְיִוֹ

ur water system recently violated a drinking water standard, Althour appened and what we did (are doing) to correct this situation.

alicident was not an emergency, as our customers, you have a right to kill

te routinally monitor for the presence of drinking water contaminants. Testing results from 1/1/2013 through 3/31/2013 show that our system exceeds the andard, or maximum contaminant level (MCL), for trihatomethanes (THM) and halogoetic acids (HAA). The standard for THM is 0.080 mg/L and the anderd for HAA is 0.060 mg/L. These are determined by everaging all samples collected by our system for the last 12 months. The level of THM everaged our system for 1/1/2013 to 3/31/2013 was 0.093 mg/L and HAA was 0.068 mg/L.

- There is nothing you need to do. You do not need to boil your water or take other corrective actions, if a situation arises where the water is no longer safe to drink, you will be notified within 24 hours.
- If you have a severely compromised immune system, have an infant, are pregnant, or are alderly, you may be at increased risk and should seek advice from your health care providers about drinking this water.

ome people who drink water containing trhatomethanes in excess of the MCL over many years may experience problems with their liver, kidneys, or central arrous system, and may have an increased risk of getting cancer. Some people who drink water containing haloacotic acids in excess of the MCL over any years may have an increased risk of getting cancer.

his is not an emergency. If it had been an emergency, you would have been notified within 24 hours.

'e are working to minimize the formation of trihelomethanes and haloacetic acids white ensuring we maintain an adequate level of disinfectant. We have ken additional steps to change disinfectant types/levels, remove natural organic matter, and increased flushing of water lines to determine it our efforts have sen effective. We are also monitoring water storage tank levels and water flow patterns within the distribution system. We anticipate resolving the problem thin the next quarter.

or more information, please contact John Mills at (606) 298-3885 or 387 E Main St, Suite 140, Inez, KY 41224

'ease share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, apple in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail

In 2012, Martin County Water District detected 13 contaminants in the drinking water and none of them were above the EPA accepted level for drinking water. Please go to www.ktwa.org/2012cc/martincounty.pdf to view your 2012 annual water quality report and learn more about your drinking water. This report contains important information about the source and quality of your drinking water. To speak with someone about the report, please call (606) 298-3885. If you would like a paper copy of the 2012 Annual Water Quality Report mailed to your home please check the paper copy box and mail back with your payment or call (606) 298-3885. Mail a copy 🗖

Notice by Martin County Water District - System ID#: KY0800273 ur water system recently violated a drinking water standard, Although this incident was not an emergency, as our customers, you have a right to know what appened and what we did (are doing) to correct this situation.

re routinely monitor for the presence of drinking water conteminants, Testing results from 1/1/2013 through 3/31/2013 show that our system exceeds the andard, or maximum conteminant level (MCL), for trihalomethanes (THM) and haloacetic acids (HAA); The standard for THM is 0.080 mg/L. and the andard for HAA is 0.080 mg/L. These are determined by averaging all samples collected by our system for the last 12 months. The level of THM averaged our system for 1/1/2013 to 3/31/2013 was 0.083 mg/L and HAA was 0.083 mg/L.

- There is nothing you need to do. You do not need to boil your water or take other corrective actions. If a situation erises where the water is no larger safe to drink, you will be notified within 24 hours,
- If you have a severally compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek advice from your health care providers about drinking this water.

ome people who drink water containing trinalomethanes in excess of the MCL over many years may experience problems with their liver, kidneys, or central arrous system, and may have an increased risk of getting cancer. Some people who drink water containing haloacetic acids in excess of the MCL over any years may have an increased risk of getting cancer.

his is not an emergency, if it had been an emergency, you would have been notified within 24 hours.

's are working to minimize the formation of trihalomethanes and haloacetic acids while ensuring we maintain an adequate level of disinfectant. We have ken additional stops to change disinfectant types/levels, remove natural organic matter, and increased flushing of water lines to determine if our efforts have en effective. We are also monitoring water storage tank levels and water flow patterns within the distribution system. We anlicipate resolving the problem thin the next queder

or more information, please contact John Milts at (606) 298-3885 or 387 E Main St. Suite 140, Inez, KY 41224

'ease share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, tople in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or moit.

In 2012, Martin County Water District detected 13 contaminants in the drinking water and none of them were above the EPA accepted level for drinking water. Please go to www.krwa.org/2012ccr/martincounty.pdf to view your 2012 annual water quality report and learn more about your drinking water. This report contains important information about the source and quality of your drinking water. To speak with someone about the report, please call (606) 298-3885. If you would like a paper copy of the 2012 Annual Water Quality Report

mailed to your home please check the paper copy box and mail back with your payment or call (606) 298-7439. Mail a copy 🗖

THM & HAA Stage ! DBPR Template 2-18

Insert water system name and ID# in header, Insert compliance period begin date, end date, and average level. Remove brackers.

Do not modify mandatory language!

Replace explanation language with your own to explain what happened, what is being done and date that compliance is anticipated

Insert contact information

No text below this point

Copy and paste notice. Prior to paste make sure that the cursor is at the highest point in the text box.

No text below this point,

# Notice by Martin County Water District - System ID#: KY0800273

Our water system recently violated a drinking water standard. Although this incident was not an emergency, as our customers, you have a right to know what happened and what we did (are doing) to correct this situation.

*We are required to monitor your drinking water for specific contaminants on a regular basis. Results of regular monitoring are an indicator of whether or not our drinking water meets health standards. During 2/1/2013 – 2/28/2013, we did not complete all monitoring or testing for chlorine and turbidity, and therefore cannot be sure of the quality of your drinking water during that time.*

There is nothing you need to do at this time. You may continue to drink the water. If a situation arises where the water is no longer safe to drink, you will be notified within 24 hours.

By the 10th of each month we must submit a Monthly Operation Report (MOR) to the Division of Water. The MOR for February 2013 did not arrive by the required deadline and this caused three violations. One violation for not submitting the MOR by the required deadline, another for not submitting daily chlorine results, and another for failing to submit the daily turbidity readings. (The chlorine results and turbidity readings are contained within the MOR.) We have modified our procedures to assure that the MOR arrives by the required deadline.

For more information, please contact John Mills at (606) 298-3885 or 387 E Main St. Suite 140, Inez, KY 41224

Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

Notice by Martin County District - System ID#: KY0800273

Our water system recently violated a drinking water standard. Although this incident was not an emergency, as our customers, you have a right to know what happened and what we did (are doing) to correct this situation.

*We are required to monitor your drinking water for specific contaminants on a regular basis. Results of regular monitoring are an indicator of whether or not our drinking water meets health standards. During 2/1/2013 – 2/28/2013, we did not complete all monitoring or testing for chlorine and furbidity, and therefore cannot be sure of the quality of your drinking water during that time.*

There is nothing you need to do at this time. You may continue to drink the water. If a situation arises where the water is no longer safe to drink, you will be notified within 24 hours.

By the 10th of each month we must submit a Monthly Operation Report (MOR) to the Division of Water. The MOR for February 2013 did not arrive by the required deadline and this caused three violations. One violation for not submitting daily chlorine results, and enother for failing to submit the daily turbidity readings. (The chlorine results and turbidity readings are contained within the MOR.) We have modified our procedures to assure that the MOR arrives by the required deadline.

For more information, please contact John Mills at (606) 298-3885 or 387 E Main St. Suite 140, Inez, KY 41224

Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

# Notice by Martin County Water District - System ID#: KY0800273

Our water system recently violated a drinking water standard. Although this incident was not an emergency, as our customers, you have a right to know what happened and what we did (are doing) to correct this situation.

*We are required to monitor your drinking water for specific contaminants on a regular basis. Results of regular monitoring are an indicator of whether or not our drinking water meets health standards. During 2/1/2013 – 2/28/2013, we did not complete all monitoring or testing for chlorine and turbidity, and therefore cannot be sure of the quality of your drinking water during that time.*

There is nothing you need to do at this time. You may continue to drink the water. If a situation arises where the water is no longer safe to drink, you will be notified within 24 hours.

By the 10th of each month we must submit a Monthly Operation Report (MOR) to the Division of Water. The MOR for February 2013 did not arrive by the required deadline and this caused three violations. One violation for not submitting the MOR by the required deadline, another for not submitting daily chlorine results, and another for failing to submit the daily turbidity readings. (The chlorine results and turbidity readings are contained within the MOR.) We have modified our procedures to assure that the MOR arrives by the required deadline.

For more information, please contact John Mills at (606) 298-3885 or 387 E Main St. Suite 140, Inez, KY 41224

Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, people in apartments; nursing nomes, schools, and businesses). You can do this by posting this police in a public place or distributing copies by hand or mail.

Do not modify mandatory language!

Copy and paste notice. Prior to paste make sure that the cursor is at the highest point in the text box.



Notice by Martin Count of District - System ID#: KY0800273

Dur water system recently violated a drinking water requirement, Although this was not an emergency, as our customers, you have a right to (now what happened, what you should do, and what we did (are doing) to correct this situation. We routinely monitor your water for turbidity (cloudiness). This tells us whether we are effectively filtering the water supply. Water samples for January 2014 showed that 5.4 percent of turbidity measurements were over 0.3 turbidity units - the standard is that no more than 5 percent of samples may exceed 0.3 turbidity units per month. The turbidity levels are relatively low. However, their persistence is a concern. Normal urbidity levels at our plant are 0.1 units. This is not an emergency. If it had been, you would have been notified within 24 hours.

There is nothing you need to do. You do not need to boil your water or take other actions. We do not know of any contamination, and none of our testing has shown disease-causing organisms in the drinking water.

If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and

should seek advice from your health care providers about drinking this water. General guidelines on ways to lessen the risk of infection by microbes are available from EPA's Safe Drinking Water Hotline at 1-800-426-4791.

*Turbidity has no health effects. However, turbidity can interfere with disinfection and provide a medium for microbial growth. Turbidity may indicate the presence of disease causing organisms. These organisms include bacteria, viruses, and parasites which can cause symptoms such as nausea, cramps, diarrhea, and associated headaches.* These symptoms are not caused only by organisms in drinking water. If you experience any of these symptoms and they persist, you may want to seek medical advice.

We made repairs to our equipment. We inspected and cleaned the filters. The problem is resolved: For more information, please contact John Viills at (606) 298-3885 or 387 E Main St. Suite 140, Inez, KY 41224.

*Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

## Notice by Martin County Water District - System ID#: KY0800273

Our water system recently violated a drinking water requirement. Although this was not an emergency, as our customers, you have a right to know what happened, what you should do, and what we did (are doing) to correct this situation. know what happened, what you should do, and what we did (are doing) to correct this situation.

We routinely monitor your water for turbidity (cloudiness). This tells us whether we are effectively filtering the water supply. Water samples for January 2014 showed that 5.4 percent of turbidity measurements were over 0.3 turbidity units – the standard is that no more than 5 percent of samples may exceed 0.3 turbidity units per month, The turbidity levels are relatively low. However, their persistence is a concern. Normal turbidity levels at our plant are 0.1 units. This is not an emergency. If it had been, you would have been notified within 24 hours.

- There is nothing you need to do. You do not need to boil your water or take other actions. We do not know of any contamination,
- and none of our testing has shown disease-causing organisms in the drinking where.

  If you have a severely compromised immune system, have an Infant, are pregnant, or are elderly, you may be at increased risk and should seek advice from your health care providers about drinking this water. General guidelines on ways to lessen the risk of infection by microbes are available from EPA's Safe Drinking Water Hotline at 1-800-426-4791.

*Turbidity has no health effects. However, turbidity can interfere with disinfection and provide a medium for microbial growth. Turbidity may indicate the presence of disease causing organisms. These organisms include bactorie, viruses, and parasites which can cause symptoms such as neusee, cramps, diamnes, and associated headaches.* These symptoms are not caused only by organisms in drinking water if you experience any of these symptoms and they persist, you may want to seek medical advice.

We made repairs to our equipment. We inspected and cleaned the filters. The problem is resolved. For more information, please contact John Mills at (606) 298-3885 or 387 E Main St. Suite 140, Inez, KY 41224.

Pléasa share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, people in spattments, nursing homes, schools, and businesses), You can go this by posting this notice in a public place or distributing. copies by hand or mail."

Template 2-6 Turbidity

De not modify mandatory language!

No text below this point

Copy and paste notice, Prior to paste make sure that the cursor is at the bighest point in the text box.

No text below this point.

# Notice by Martin County Water District – System ID#: KY0800273

Our water system recently violated a drinking water standard. Although this incident was not an emergency, as our customers, you have a right to know what happened and what we did (are doing) to correct this situation.

We routinely monitor for the presence of drinking water contaminants. Testing results from 7/1/2014 through 9/30/2014 show that our system exceeds the standard, or maximum contaminant level (MCL), for trihalomethanes (THM) and haloacetic acids (HAA). The standard for THM is 0.080 mg/L and the standard for HAA is 0.060 mg/L. These are determined by averaging all samples collected at each sampling location for the last 12 months. The level of THM averaged at one of our system's locations for 7/1/2014 to 9/30/2014 was 0.101 mg/L and HAA was 0.081 mg/L.

- There is nothing you need to do. You do not need to boil your water or take other corrective actions. If a situation arises where the water is no longer safe to drink, you will be notified within 24 hours.
- If you have a severely compromised immune system, have an infant, are
  pregnant, or are elderly, you may be at increased risk and should seek advice
  from your health care providers about drinking this water.

Some people who drink water containing trihalomethanes in excess of the MCL over many years may experience problems with their liver, kidneys, or central nervous system, and may have an increased risk of getting cancer. Some people who drink water containing haloacetic acids in excess of the MCL over many years may have an increased risk of getting cancer.

This is not an emergency. If it had been an emergency, you would have been notified within 24 hours.

We are working to minimize the formation of trihalomethanes and haloacetic acids while ensuring we maintain an adequate level of disinfectant. We have taken additional steps to change disinfectant levels, remove natural organic matter, and increased flushing of water lines to determine if our efforts have been effective. We are also monitoring water storage tank levels and water flow patterns within the distribution system. We anticipate resolving the problem within the next quarter but the compliance calculation is based upon annual averages and it may be several quarters before compliance is achieved.

For more information, please contact John Mills at 606-298-3885 or 387 E Main St. Suite 140, Inez, KY 41224.

Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

NORCH DV WATER GOOD

DISCICL - SYSTEM ID#: P. 10000213

noident was not an emergency, as our customers, you have a right to kits

ur water system recently violated a drinking water standard. Although appened and what we did (are doing) to correct this situation.

'e routinely monitor for the presence of drinking water contaminants. Testing results from 7/1/2014 through 9/30/2014 show that our system exceeds the andard, or maximum contaminant level (MCL), for trihatomethanes (THM) and haloacetic acids (HAA). The standard for THM is 0,080 mg/L and the andard for HAA is 0,060 mg/L. These are determined by averaging all samples collected at each sampling location for the last 12 months. The level of THM reraged at one of our system's locations for 7/1/2014 to 9/30/2014 was 0.101 mg/L and HAA was 0.081 mg/L.

- There is nothing you need to do. You do not need to bail your water or take other corrective actions. If a situation arises where the water is no longer safe to drink, you will be notified within 24 hours.
- If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek edvice from your health care providers about drinking this water,

ome people who drink water containing trihalomethanes in excess of the MCL over many years may experience problems with their liver, kidneys, or central arous system, and may have an increased risk of getting cancer. Some people who drink water containing haloacetic acids in excess of the MCL over any years may have an increased risk of getting cancer.

his is not an emergency. If it had been an emergency, you would have been notified within 24 hours.

To are working to minimize the formation of trihatomethanes and hatoacetic acids white ensuring we maintain an adequate level of disinfectant. We have the art working to hit missing the transport of the admission and the second flushing of water lines to determine if our efforts have been fective. We are also monitoring water storage tank levels and water flow patterns within the distribution system. We anticipate resolving the problem within e next quarter but the compliance calculation is based upon annual everages and it may be several quarters before compliance is achieved.

or more information, please contact John Mills at 606-298-3685 or 387 E Main St., Suite 140, inez, KY 41224.

lease shere this information with all the other people who drink this water, especially those who may not have received this indice directly (for example, rople in apartments, hursing homes, schools, and businesses). You can do this by posting this notice in a public place of distributing copies by hand or mail.

## Notice by Martin County Water District - System ID#: KY0800273

ur water system recently violated a drinking water standard. Although this incident was not an emergency, as our customers, you have a right to know what appened and what we did (are doing) to correct this situation.

To routinely monitor for this presence of drinking water contaminants. Testing results from 7/1/2014 through 9/30/2014 show that our system exceeds the anderd, or maximum contaminant level (MCL), for trihalonightanes (THM) and haloacetic acids (HAA). The standard for THM is 0.060 mg/L and the anderd for HAA is 0.060 mg/L. These are determined by averaging all samples collected at each sampling location for the last 12 months. The level of THM reraged at one of our system's locations for 7/1/2014 to 9/30/2014 was 0.101 mg/L and HAA was 0.081 mg/L,

- There is nothing you need to do. You do not need to boil your water or take other corrective actions, If a situation arises where the water is no
- longer safe to drink, you will be notified within 24 hours,
  If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seak advice from your health care providers about drinking this water.

mino people who drink water containing tribulomethanes in excess of the MCL over many years mey experience problems with their tiver, kidneys, or central Probles system, and may have an increased risk of pelling cancer. Some people who drink water containing haloacetic acids in excess of the MCL over any years may have an increased risk of getting cancer.

ls is not an emergency, if it had been an emergency, you would have been notified within 24 hours.
The pre-working to minimize the formation of inhelomethanes and haloscotic acids white emergency we maintain an adequate tovel of disinfectant. We have been excited a support of the support of e next quarter but the compliance calculation is based upon annual averages and it may be several quarters before compliance is achieved

or more information, please contact John Mills at 606-298-3585 or 387 E Main St. Suite 140, Inex, KY 41224.

'éase share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, sopie in apartments, norsing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

### THM & HAA Stage 2 DBPR Template 2-19

Insert water system name and IDe in header, insert compliance period begin date, end date, and average level. Remove brackets. Do not medify mandatory language!

## Printing Instructions

This template is designed to print the notice on the back of the water bill sheets prior to printing the water bills using procedures the same as printing a letter.

After the notice has been printed to all sheets place the stack of sheets unside down on a flat surface and place a weight on the stack to remove the curl.

When the stack of sheets have cooled and straightened print the water bills as usual.

No text below this point.

Copy and paste notice. Prior to paste make sure that the cursor is at the highest point in the text box

No text below this point,

# Notice by Martin County Water District – System ID#: KY0800273

Our water system recently violated a drinking water standard. Although this incident was not an emergency, as our customers, you have a right to know what happened and what we did (are doing) to correct this situation.

We routinely monitor for the presence of drinking water contaminants. Testing results from 10/1/2014 through 12/31/2014 show that our system exceeds the standard, or maximum contaminant level (MCL), for trihalomethanes (THM) and haloacetic acids (HAA). The standard for THM is 0.080 mg/L and the standard for HAA is 0.060 mg/L. These are determined by averaging all samples collected at each sampling location for the last 12 months. The level of THM averaged at one of our system's locations for 10/1/2014 to 12/31/2014 was 0.096 mg/L and HAA was 0.105 mg/L.

- There is nothing you need to do. You do not need to boil your water or take other corrective actions. If a situation arises where the water is no longer safe to drink, you will be notified within 24 hours.
- If you have a severely compromised immune system, have an infant, are
  pregnant, or are elderly, you may be at increased risk and should seek advice
  from your health care providers about drinking this water.

Some people who drink water containing trihalomethanes in excess of the MCL over many years may experience problems with their liver, kidneys, or central nervous system, and may have an increased risk of getting cancer. Some people who drink water containing haloacetic acids in excess of the MCL over many years may have an increased risk of getting cancer.

This is not an emergency. If it had been an emergency, you would have been notified within 24 hours.

We are working to minimize the formation of trihalomethanes and haloacetic acids while ensuring we maintain an adequate level of disinfectant. We have taken additional steps to change disinfectant levels, remove natural organic matter, and increased flushing of water lines to determine if our efforts have been effective. We are also monitoring water storage tank levels and water flow patterns within the distribution system. We anticipate resolving the problem within the next quarter but the compliance calculation is based upon annual averages and it may be several quarters before compliance is achieved.

For more information, please contact John Mills at 606-298-3885 or 387 E Main St. Suite 140, Inez, KY 41224.

Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

NORCE BY MAILIN COMING

LIISHIUL - SYBWIN ILIE: ATUQUUZIS

ur water system recently violated a drinking water standard, Although appened and what we did (are doing) to correct this situation. dicident was not an emergency, as our customers, you have a right to kr

'e routinely monitor for the presence of drinking water contaminants. Testing results from 10/1/2014 through 12/31/2014 show that our system exceeds the andard, or maximum contaminant level (MCL), for trithelomethanes (THM) and haloscelic acids (HAA). The standard for THM is 0.080 mg/L and the andard for HAA is 0.060 mg/L. These ere determined by sveraging all samples collected at each sampling location for the last 12 months. The level of THM rereged at one of our system's locations for 10/1/2014 to 12/31/2014 was 0.096 mg/L and HAA was 0.105 mg/L.

- There is nothing you need to do, You do not need to boil your water or take other corrective actions. If a situation enses where the water is no
- longer safe to drink, you will be notified within 24 hours.

  If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek advice from your health care providers about drinking this water,

ome people who drink water containing triheformethanes in excess of the MCL over many years may experience problems with their liver, kidneys, or central propuls system, and may have an increased risk of getting cancer. Some people who drink water containing halpacetic acids in excess of the MCL over any years may have an increased risk of gelting cancer.

his is not an emergency. If it had been an emergency, you would have been notified within 24 hours, le are working to minimize the formation of trihatomethanes and haloacetic acids white ensuring we maintain an adequate level of disinfectant. We have ken additional steps to change disinfectant levels, remove natural organic matter, and increased flushing of water lines to determine if our efforts have been fective. We are also monitoring water storage tank levels and water flow patterns within the distribution system. We anticipate resolving the problem within e next quarter but the compliance calculation is based upon annual averages and it may be several quarters before compliance is achieved.

or more information, please contact John Mills at 605-298-3885 or 387 E Main St, Suite 140, Inez, KY 41224,

ease share this information with all the other people who drink this water, especially those who may not have received this police directly (for example,

## Notice by Martin County Water District - System 10#: KY0800273

ur water system recently violated a drinking water standard. Although this incident was not an emergency, as our customers, you have a right to know what appened and what we did (are doing) to correct this situation,

the routinely monitor for this presence of driving water contaminants. Tasting results from 10/1/2014 through 12/31/2014 show that our system exceeds the sancted or maximum contaminant level (MCL), for trihalomethanes (THM) and haloacetic acids (HAA). The standard for THM is 0.080 mg/L, and the andard for HAA is 0.060 mg/L. These are determined by averaging all samples collected at each sampling location for the last 12 months. The level of THM reraged at one of our system's locations for 10/1/2014 to 12/31/2014 was 0.096 mg/L and HAA was 0.105 mg/L.

- There is nothing you need to do. You do not need to boil your water or take other corrective actions. If a situation arises where the water is no
- longer safe to drink, you will be notified within 24 hours.
  If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek advice from your health cere providers about drinking this water,

ame people who think water containing tringfornally ares in excess of the MCL over injuly years may experience problems with their kyer, kidneys, or centrel strong system, and may have at increased risk of golling carber. Some people who drink water containing halogoetic acids in excess of the MCL over any years may have an increased risk of getting cancer.

his is not an emergency. If it had been an emergency, you would have been notified within 24 hours.
The are working to minimize the formation of trihalomethenes and haloscotic acids while ensuring you maintain an adequate level of distributions. We have for a working to minimize the formation of trihalometheness and haloscotic acids while ensuring you maintain an adequate level of distributions to determine it our efforts have been focitive. We are also monitoring water storage tank fevels and water flow patterns within the distribution system. We anticipate resolving the problem within e next quarter but the compliance calculation is based upon annual averages and it may be several quarters before compliance is achieved.

or more Information, please contact John Mills at 606-298-3865 or 387 E Main St. Suite 140, Inex, KY 41224.

'ease share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, sople in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

#### THM & HAA Stage 2 DBPR Template 2-19

insert water system name and ID# in header, Insert compliance period begin date, end date, and average level. Remove brackets. Do not modify mandatory language!

## Printing Instructions

This template is designed to print the notice on the back of the water bill sheets prior to printing the water bills using procedures the same as printing a letter.

After the notice has been printed to all sheets place the stack of sheets upside down on a flat surface end place a weight on the stack to remove the curl-

When the stack of sheets have cooled and straightened print the water bills as usual.

No text below this point.

Copy and paste notice. Prior to paste make sure that the cursor is at the highest point in the text box.

No text below this point,

# Notice by Martin County Water District - System ID#: KY0800273

Our water system recently violated a drinking water requirement. Although this was not an emergency you have a right to know what happened.

We routinely monitor your water for turbidity (cloudiness). This tells us whether we are effectively filtering the water supply. On 2/23/2015 we had a turbidity result of 1.195 NTU. This was above the standard of 1.0 NTU. Water samples for February 2015 showed that 6.58 percent of turbidity measurements were over 0.3 turbidity units – the standard is that no more than 5 percent of samples may exceed 0.3 turbidity units per month. The turbidity levels are relatively low. However, their persistence is a concern. Normal turbidity levels at our plant are 0.12 units. This is not an emergency. If it had been, you would have been notified within 24 hours.

- There is nothing you need to do. You do not need to boil your water or take other
  actions. We do not know of any contamination, and none of our testing has
  shown disease-causing organisms in the drinking water.
- If you have a severely compromised immune system, have an infant, are
  pregnant, or are elderly, you may be at increased risk and should seek advice
  from your health care providers about drinking this water. General guidelines on
  ways to lessen the risk of infection by microbes are available from EPA's Safe
  Drinking Water Hotline at 1-800-426-4791.

*Turbidity has no health effects. However, turbidity can interfere with disinfection and provide a medium for microbial growth. Turbidity may indicate the presence of disease causing organisms. These organisms include bacteria, viruses, and parasites which can cause symptoms such as nausea, cramps, diarrhea, and associated headaches.*

These symptoms are not caused only by organisms in drinking water. If you experience any of these symptoms and they persist, you may want to seek medical advice.

High turbidity on top of the filters occurred when a rake motor failed and due to high demand we had to continue operations. The problem was resolved within three days. For more information, please contact John Mills at (606) 298-3885 or 387 E Main St. Suite 140, Inez, KY 41224.

*Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.*

CCR Availability Notice

ur water system recently violated a drinking water requirement. Although this was not an emergency you have a right to know what happened. It routinely monitor your water for turbidity (cloudiness). This tells us whether we are effectively filtering the water supply. On 2/23/2015 we had turbidity result of 1.195 NTU. This was above the standard of 1.0 NTU. Water samples for February 2015 showed that 6.58 percent of turbidity easurements were over 0.3 turbidity units – the standard is that no more than 5 percent of samples may exceed 0.3 turbidity units per month, the turbidity levels are relatively low. However, their persistence is a concern. Normal turbidity levels at our plant are 0.12 units. This is not an mergency. If it had been, you would have been notified within 24 hours.

- There is nothing you need to do. You do not need to boil your water or take other actions. We do not know of any contamination, and none of our testing has shown disease-causing organisms in the drinking water.
- If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek advice from your health care providers about drinking this water. General guidelines on ways to lessen the risk of infection by microbes are available from EPA's Safe Drinking Water Hotline at 1-800-426-4791.

"urbidity has no health effects. However, turbidity can interfere with disinfection and provide a medium for microbial growth. Turbidity may dicate the presence of disease causing organisms. These organisms include bacteria, viruses, and parasites which can cause symptoms such a nausee, cramps, diernhee, and associated headaches.* These symptoms are not caused only by organisms in drinking water, if you operience any of these symptoms and they persist, you may want to seek medical advice.

igh turbidity on top of the filters occurred when a rake motor falled and due to high demand we had to continue operations. The problem was solved within three days. For more information, please contact John Mills at (606) 298-3885 or 387 E Main St. Suite 140, Inez, KY 41224.

Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for cample, people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing poles by hand or mail.

2014 Martin County Water District annual water quality report is available. This report contains important information about your drinking water. Please go to http://www.krwa.org/2014ccr/martincounty.pdf to view your 2014 annual water quality report or to request a paper copy call (606) 298-3885.

Notice by Martin County Water District - System ID#: KY0800273

ur water system recently violated a drinking water requirement. Although this was not an emergency you have a right to know what happened. It routinely monitor your water for turbidity (cloudiness). This tells us whether we are effectively filtering the water supply. On 2/23/2015 we had turbidity result of 1.195 NTU. This was above the standard of 1.0 NTU. Water samples for February 2015 showed that 6.58 percent of turbidity easurements were over 0.3 turbidity units – the standard is that no more than 5 percent of samples may exceed 0.3 turbidity units per month. et turbidity levels are relatively low. However, their persistence is a concern. Normal turbidity levels at our plant ere 0.12 units. This is not an mergency. If it had been, you would have been notified within 24 hours.

- There is nothing you need to do. You do not need to boil your water or take other actions. We do not know of any contamination, and none of our testing has shown disease-causing organisms in the drinking water.
- If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek advice from your health care providers about drinking this water. General guidelines on ways to lessen the risk of infection by microbes are available from EPA's Safe Drinking Water Hotline at 1-800-426-4791.

*rurbidity has no health effects. However, turbidity can Interfere with disinfection and provide a medium for microbial growth. Turbidity may dicate the presence of disease causing organisms. These organisms include bacteria, viruses, and parasites which can cause symptoms such a nausea, cramps, diarrhea, and associated headaches.* These symptoms are not caused only by organisms in drinking water. If you sperience any of these symptoms and they persist, you may want to seek medical advice.

igh turbidity on top of the filters occurred when a rake motor falled and due to high demand we had to continue operations. The problem was solved within three days. For more information, please contact John Mills at (606) 298-3885 or 387 E Main St. Suite 140, Inez, KY 41224.

Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for cample, people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing pies by hand or mail.*

2014 Martin County Water District annual water quality report is available. This report contains important information about your drinking water. Please go to http://www.krwa.org/2014ccr/martincounty.pdf to view your 2014 annual water quality report or to request a paper copy call (606) 298-3885.

No text below this point

No text below this point

# Notice by Martin County Water District - System ID#: KY0800273

Our water system recently violated a drinking water standard. Although this incident was not an emergency, as our customers, you have a right to know what happened and what we did (are doing) to correct this situation.

We routinely monitor for the presence of drinking water contaminants. Testing results from 4/1/2015 through 6/30/2015 show that our system exceeds the standard, or maximum contaminant level (MCL), for trihalomethanes (THM) and haloacetic acids (HAA). The standard for THM is 0.080 mg/L and the standard for HAA is 0.060 mg/L. These are determined by averaging all samples collected at each sampling location for the last 12 months. The level of THM averaged at one of our system's locations for 4/1/2015 to 6/30/2015 was 0.088 mg/L and HAA was 0.077 mg/L.

- There is nothing you need to do. You do not need to boil your water or take other corrective actions. If a situation arises where the water is no longer safe to drink, you will be notified within 24 hours.
- If you have a severely compromised immune system, have an infant, are
  pregnant, or are elderly, you may be at increased risk and should seek advice
  from your health care providers about drinking this water.

Some people who drink water containing trihalomethanes in excess of the MCL over many years may experience problems with their liver, kidneys, or central nervous system, and may have an increased risk of getting cancer. Some people who drink water containing haloacetic acids in excess of the MCL over many years may have an increased risk of getting cancer.

This is not an emergency. If it had been an emergency, you would have been notified within 24 hours.

We are working to minimize the formation of trihalomethanes and haloacetic acids while ensuring we maintain an adequate level of disinfectant. We have taken additional steps to change disinfectant levels, remove natural organic matter, and increased flushing of water lines to determine if our efforts have been effective. We are also monitoring water storage tank levels and water flow patterns within the distribution system. We anticipate resolving the problem within the next quarter but the compliance calculation is based upon annual averages and it may be several quarters before compliance is achieved.

For more information, please contact John Mills at 606-298-3885 or 387 E Main St. Suite 140, Inez, KY 41224.

Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

## NUMBER DV Martin Comin

າ ນາຣິທີເບີ່ - ວຸຈຸຣັເຫກີ ເນົ້າເ ກ ເບີດເບເລີ້ ວັ

ur water system recently violated a drinking water standard, Althous appened and what we did (are doing) to correct this situation.

incident was not an emergency, as our customers, you have a right to

THM & HAA Stage 2 DBPR Template 2-19

> Insert water system same and ID# in header, insert compliance period begin date, end date, and average level. Remove brackets. Do not modify mandatory Innousse!

#### Printing Instructions

This template is designed to print the notice on the back of the water bill sheets prior to printing the water bills using procedures the same as printing a letter.

After the notice has been printed to all sheets place the stack of sheets upside down on a flat surface and place a weight on the stack to remove the curl.

When the stack of sheets have cooled and straightened print the water bills as usual.

No text below this point,

Copy and paste notice. Prior to paste make sure that the cursor is at the highest point in the text box,

andard, or maximum contaminant level (MCL), for trihalomethanes (THM) and haloacetic acids (HAA). The standard for THM is 0,080 mg/L and the andard for HAA is 0.060 mg/L, These are determined by averaging all samples collected at each sampling location for the last 12 months. The level of THM reraged at one of our system's locations for 4/1/2015 to 6/30/2015 was 0.080 mg/L and HAA was 0 0.77 mg/L, There is nothing you need to do, You do not need to boil your water or take other corrective actions, if a situation arises where the water is no

fe routinely monitor for the presence of drinking water contaminants. Testing results from 4/1/2015 through 6/30/2015 show that our system exceeds the

longer safe to drink, you will be notified within 24 hours

If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek advice from your health care providers about drinking this water.

ome people who drink water containing trihalomethenes in excess of the MCL over many years may experience problems with their liver, kidneys, or central pryous system, and may have an increased risk of getting cancer. Some people who drink water containing haloacetic acids in excess of the MCL over any years may have an increased risk of getting cancer.

his is not an emergency. If it had been an emergency, you would have been notified within 24 hours.

'e are working to minimize the formation of trihelomethanes and haloacetic acids white ensuring we maintain an adequate level of disinfectant. We have two additional steps to change disinfectant levels, remove natural organic matter, and increased flushing of water lines to determine if our efforts have been fective. We are also nonlitoring water storage tank levels and water flow patterns within the distribution system. We anticipate resolving the problem within e next quarter but the compliance calculation is based upon annual averages and it may be several quarters before compliance is achieved

or more information, please contact John Mills at 606-298-3885 or 387 E Main St. Suite 140, Inex, KY 41224.

'ease shere this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, eople in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public piece or distributing copies by hand or mail.

## Notice by Martin County Water District - System ID#: KY0800273

ur water system recently violated a drinking water standard. Although this incident was not an emergency, as our customers, you have a right to know what appened and what we did (are doing) to correct this situation.

fe routinely monitor for the presence of drinking water contaminents. Testing results from 4/1/2015 through 6/30/2015 show that our system exceeds the andard, or maximum contaminant level (MCL), for trihatomethanes (THM) and haloscotic acids (HAA). The standard for THM is 0.080 mg/L and the andard for HAA is 0.060 mg/L. These are determined by averaging all samples collected at each sampling location for the last 12 months. The level of THM reraged at one of our system's locations for 4/1/2015 to 6/30/2015 was 0.088 mg/L and HAA was 0.077 mg/L.

- There is nothing you need to do. You do not need to boll your water or take other corrective actions, if a situation arises where the water is no
- ionger safe to drink, you will be notified within 24 hours.

  If you have a severely compromised immune system, have en infant, are pregnant, or are elderly, you may be at increased risk and should seek advice from your health care providers about drinking this water.

ome people who drink water containing trihalomethanes in excess of the MCL over many years may experience problems with their liver, kidneys, or central arrows system, and may have an increased risk of getting cencer. Some people who drink water containing haloacetic acids in excess of the MCL over any years may have an increased risk of getting car

nis is not an emergency. If it had been an emergency, you would have been notified within 24 hours.
The are working to minimize the formation of trihalomethanes and heloacotic acids white ensuring we maintain an adequate level of disinfectant. We have ken additional steps to change distributions are remove natural organic matter, and increased flushing of water lines to determine if our efforts have been fective. We are also monitoring water storage tank levels and water flow patterns within the distribution system, We anticipate resolving the problem within e next quarter but the compliance calculation is based upon annual averages and it may be several quarters before compliance is achieved.

or more information, please contact John Mills at 606-298-3885 or 387 E Main St. Suite 140, Inex, KY 41224.

'ease share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, apple in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mall,

No text below this point.

# Notice by Martin County Water District - System ID#: KY0800273

Our water system recently violated a drinking water standard. Although this incident was not an emergency, as our customers, you have a right to know what happened and what we did (are doing) to correct this situation.

We routinely monitor for the presence of drinking water contaminants. Testing results from 7/1/2015 through 9/30/2015 and 10/1/2015 through 12/31/2015 show that our system exceeds the standard, or maximum contaminant level (MCL), for trihalomethanes (THM) and haloacetic acids (HAA). The standard for THM is 0.080 mg/L and the standard for HAA is 0.060 mg/L. These are determined by averaging all samples collected at each sampling location for the last 12 months. The level of THM averaged at one of our system's locations for 7/1/2015 to 9/30/2015 was 0.081 mg/L and HAA was 0.070 mg/L. The level of THM for 10/1/2015 to 12/31/2015 was 0.100 mg/L

- There is nothing you need to do. You do not need to boil your water or take other corrective actions. If a situation arises where the water is no longer safe to drink, you will be notified within 24 hours.
- If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek advice from your health care providers about drinking this water.

Some people who drink water containing trihalomethanes in excess of the MCL over many years may experience problems with their liver, kidneys, or central nervous system, and may have an increased risk of getting cancer. Some people who drink water containing haloacetic acids in excess of the MCL over many years may have an increased risk of getting cancer.

This is not an emergency. If it had been an emergency, you would have been notified within 24 hours.

We are working to minimize the formation of disinfection by-products while ensuring we maintain an adequate level of disinfectant. We have taken steps to change disinfectant levels, remove natural organic matter, and increased flushing of water lines. We anticipate resolving the problem within the next six months.

For more information, please contact John Mills at 606-298-3885 or 387 E Main St. Suite 140, Inez, KY 41224.

Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

NORCE DY MAIRIL CODIG ur water system recently violated a drinking water standard. Although

appened and what we did (are doing) to correct this situation.

DIBUICE - System ILH. ISTUODUZTS acident was not an emergency, as our customers, you have a right to ke

te routinely monitor for the presence of drinking water contaminants. Testing results from 7/1/2015 through 9/30/2015 and 10/1/2015 through 12/31/2015 now that our system exceeds the standard, or maximum contaminant level (MCL), for trihalomethanes (THM) and haloacotic acids (HAA). The standard for AM is 0,009 mg/L and the standard for HAA is 0,009 mg/L. These are determined by averaging all samples collected at each sampling location for the last 2 months, The level of THM everaged at one of our system's locations for 7/1/2015 to 9/30/2015 was 0,081 mg/L and HAA was 0,070 mg/L. The level of HM for 10/1/2015 to 12/31/2015 was 0,100 mg/L.

- There is nothing you need to do. You do not need to boil your water or take other corrective actions, if a situation arises where the water is no lenger safe to drink, you will be notified within 24 hours.
  If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek
- advice from your health care providers about drinking this water,

ome people who drink water containing tribalomethanes in excess of the MCL over many years may experience problems with their liver, kidneys, or central property and may have an increased risk of getting cancer. Some people who drink water containing haloacetic acids in excess of the MCL over any years may have an increased risk of getting cancer

his is not an emergency. If it had been an emergency, you would have been notified within 24-hours,.

lange disinfectant levels, remove natural organic matter, and increased flushing of water lines. We anticipate resolving the problem within the next six online: le are working to minimize the formation of disinfection by-products while ensuring we meintain an adoquate level of disinfectant. We have taken steps to

or more information, please contact John Mills at 606-298-3885 or 387 E Main St. Suite 140, Inez, KY 41224,

'ease share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, pople in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

## Notice by Martin County Water District - System ID#; KY0800273

ur water system recently violated a drinking water standard, Although this incident was not an emergency, as our customers, you have a right to know what appened and what we did (are doing) to correct this situation.

/e routinely monitor for the presence of drinking water contaminants. Testing results from 7/1/2015 through 9/30/2015 and 10/1/2015 through 12/31/2015 to the control of the presence of unitarity was contained as a testing results in the present of the control of 2 months. The level of THM averaged at one of our system's locations for 7/1/2015 to 9/30/2015 was 0.081 mg/L and HAA was 0.070 mg/L. The level of -IM for 1C11/2015 to 12/31/2015 was 0.100 mg/L.

There is nothing you need to do: You do not need to boil your water or take other corrective actions; If a situation arises where the water is no

- longer safe to drink, you will be notified within 24 hours.
  If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek
- advice from your health care providers about drinking this water...

ome people who drink water containing trihalomethanes in excess of the MCL over many years may experience problems with their liver, kidneys, or central arous system, and may have an increased risk of getting cancer. Some people who drink water containing haloacetic acids in excess of the MCL over any years may have an increased risk of getting cancer.

his is not an emergency. If it had been an emergency, you would have been notified within 24 hours.

le are working to minimize the formation of disinfection by-products while ensuring we maintain an adequate level of disinfectant, We have taken steps to range disinfectant levels, remove natural organic matter, and increased flushing of water lines. We anticipate resolving the problem within the next six

or more information, please contact John Mills at 606-298-3885 or 387 E Main St. Suite 140, Inex. KY 41224.

'ease share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, sople in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

THM & HAA Stage 2 DBPR Template 2-19

Insert water system name and ID# in header, insert compliance period begin date, end date, and average level. Remove brackets. De not modify mandatory Innguage!

#### Printing Instructions

This template is designed to print the notice on the back of the water bill sheets prior to printing the water bills using procedures the same as printing a letter.

After the notice has been printed to all sheets place the stack of sheets upside down on a flat surface and place a remove the curl

When the stack of sheets have cooled and straightened print the water hills as usual:

No text below this point

Copy and paste notice Prior to paste make cure that the cursor is at the highest point in the text box

No text below this point

Exhibit #13 Division of Water

# MATTHEW G. BEVIN GOVERNOR



CHARLES G. SNAVELY SECRETARY

# **ENERGY AND ENVIRONMENT CABINET**

DEPARTMENT FOR ENVIRONMENTAL PROTECTION

Division of Water 233 Birch St Hazard, KY 417012115 www.kentucky.gov

March 14, 2016

Martin Co Water District 14 Flat Hollow Inez, Kentucky 41224

RE:

Martin Co Water District -- 2987

Permit No.: KY0800273 Martin County, Kentucky Activity ID: CIN20160002

Dear Martin Co Water Dist:

Attached for your information and records is a copy of the DW Comp-Surface performed at Martin Co Water District on February 22, 2016.

The system should continue efforts to leak detect the distribution system and repair any issues as they are found. Measure should be taken to perform a full system flush twice per year while flushing dead ends as often as needed.

If you have any questions or comments concerning this inspection, please contact the Hazard Regional Office at: (606) 435-6022.

Sincerely,

Robert Back Environmental Inspector Hazard Regional Office

Division of Water

RB Enclosure:



# ENERGY AND ENVIRONMENT CABINET KENTUCKY DEPARTMENT FOR ENVIRONMENTAL PROTECTION DIVISION OF WATER Routine Surface Inspection

Site/Permit ID: 0800273	Division: Wat	er	Regional Office: Hazard				
Site Name: MARTIN CO. WATER DISTRICT.		Program	Program: Drinking Water				
Site Address: HC69 Box 875		· .	14 A				
City: INEZ	State: KY	Zip: 412:	24 Cour	nty: Martin			
Inspection Type: Routine Surface		rpose: Comprel	nensive	nsive AI #: 2987			
Inspection Date: 2/22/16 Ti		Γime: Start 9.55 AM End 1.10 PM					
Latitude: 37 52 20.3	Longitude: 82 31 09.8						
Coordinate Collection Method: G40-Handheld receiver			Revision Code: 112108				
Drinking Water Data							
Plant Name: MARTIN CO.	Contact Name: Ton	Alley					
WATER DISTRICT							
Phone No.: 606-298-3885	Fax No:		Email A	ddress:			

# I. Administrative Requirements

# Comments:

I. Compliance Status - Not Evaluated

# II. Operator Certification/Accreditation Requirements

Operator in Charge or on duty.

Operator Name	Plant Certification #	Distribution Certification #
Tom Alley	17562	
Mike Sartin	21944	
Tim Reed/ Elbert Osborne	24590	27800

# Comments:

II. Compliance Status - Not Evaluated

# III. Record Keeping Requirements

# Comments:

III. Compliance Status - No violations observed

Comments: Wolf creek, Coldwater, Inez 1&2 tanks are not in service. The system does not use these tanks at this time. The System has switched from gas chlorine to liquid bleach disinfectant. The system is using a Thornsorb activated carbon system. The water treatment plant has a 100,000 gallon clearwell at the plant and two 500,000 gallon clearwell tanks on the hill above the plant.

The system needs to perform a complete system flush however approximately 50% water loss and low storage due to distribution leaks in the Warfield area make it difficult. Failure to properly flush the system will make meeting future DBP limits a difficult task.

V. Compliance Status - No violations obs-but impending viol trends obs

	·	
VI. Discharge/Emission Compliance		
Comments:		
VI. Compliance Status - No violations obse	erved	
VII. Monitoring/Analyses Evaluation		
Comments: The system has multiple violatic Division of Enforcement is addressing th VII. Compliance Status - Out of Compliance	iese violations.	n the 2015 year. The
VIII. Environmental /Health Impact		
Work Site Hazard Assessment:		⊠ REVIEWED
Comments:		
VIII. Compliance Status - No violations obs	served	
IX. Documentation		
☐ Samples taken by DEP ☐ Samples taken by outside source ☐ Instrument readings taken by DEP reg ☐ Photographs obtained by DEP ☐ Copies of records obtained by DEP ☐ Other documentation		
Towns of the Donale Title	Environmental Ingrestor III	Data: 2/22/16



# **ENERGY AND ENVIRONMENT CABINET**

Matthew G Bevin Governor

Department for Environmental Protection
Division of Water
200 Fair Oaks Lane
4 Floor
Frankforl, Kentucky 40601

Phone: (502) 564-341 0 Fax: (502) 564-2741 www.water.ky.gov

March 9, 2016

Charles G Snavely Secretary

R. Bruce Scott Commissioner

CERTIFIED MAIL: 70 15 3430 0000 4915 0321

RETURN RECEIPT REQUESTED

JOHN MILLS MARTIN CO WATER DISTRICT #1 287 E MAIN ST SUITE 140

INEZ, KY 41224

Re: NOTICE OF VIOLATION

A1 ID: 2987

PWSID: KY0800273

PWS NAME: MARTIN CO WATER DISTRICT #1

COUNTY: MARTIN

Dear Mr. Mills:

The Kentucky Department for Environmental Protection (DEP) has issued the enclosed Notice of Violation for violations discovered at your facility. Please review this Notice of Violation carefully to ensure that all remedial measures are completed by the specified deadlines.

Failure to comply with all remedial measures could result in enforcement action and the assessment of penalties. Your cooperation and attention to this matter is appreciated. If you have any questions, please contact Kellee Husband at (502)564-3410 ext. 4986 or email at kelteem.husband@ky.gov.

Sincerely, Bin M. Chitti

Brian Chitti

Drinking Water CTAB Supervisor

Compliance & Technical Assistance Branch

Division of Water

C: Drinking Water Program files Enclosure

COMMONWEALTH OF KENTUCKY

# ENERGY & ENVIRONMENT CABINET DEPARTMENT FOR ENVIRONNIENTAL PROTECTION Division of Water

# NOTICE OF VIOLATION

MARTIN CO WATER DISTRICT #1 287 E MAIN ST SUITE 140 INEZ, KY 41224

PWSID: KY0800273

PWS Name: MARTIN CO WATER DISTRICT Al ID: 2987

County: MARTIN

Violation Number: 2016 - 9951 175 Determination Date: 02/10/2016

Compliance Period: 10/01/2015 - 12/31/2015 Violation Type: 02 MCL, LRAA Tier Level: 2

PWS Facility: IDSE9999 IDSE - MARTN CO WATER DIST Contaminant:

2950 TTHM

Public Water Systems are subject to the requirements of 401 KAR Chapter 8. [401 KAR 8:020 Section 1] This is to advise that you are in violation of the provision(s) cited below:

Description of Non Compliance:

401 KAR 8:510 mHM The public water system exceeded the MCL for locational running annual average (LRAA) of samples for the specific contaminant in compliance period 10/01/2015 - 12/31/2015. The reported result of .123 mg/l exceeded the MCL of 0.080 mg/l,

The remedial measure(s) and date(s) to be completed by are as follows: Begin or continue quarterly monitoring for TTHM

Pertorm public notification for the above-mentioned violation in accordance with 401 KAR 8:070. The public notification must not contain language that contradicts or detracts from the standard mandatory language or the purpose of the notice. Submit proof of public notification and its certification within ten (10) days of executing public notification. [401 KAR 8:070] The specific public notification activilies to be performed are listed below.

PW S must give notice to consumers, including other water systems you may provide water to, about a violation by mail delivery or hand delivery. The notice must be executed within thirty (30) days following receipt by the PWS of this Notice of Violation.

If not all consumers can be notified by mail or hand delivery then the PWS must give notice to consumers about a violation by t) publication in a newspaper of general circulation in the area served by the PWS or 2) by continuous posting in conspicuous places within the area served by the PW S. The notice must be executed within thirty (30) days following receipt by the PWS of this Notice of Violation.

Submit proof of public notification and its certification within ten (10) days of executing public notification.

Violations of the above cited statutes and/or regulations are subject to a civil penalty. Violations carry civil penalties of up to \$25,000 per day per violation depending on the statutes/regulations violated. In addition, violations may be concurrently enjoined. Compliance with remedial measures and their deadlines does not provide exemption from liability for violations during the period of remediation, nor prevent additional remedial measures from being required.

Detailed information about your water system's violations & monitoring requirements can be easily accessed on Kentucky Drinking Water Watch at http://dep.gateway.ky.gov/DWW/

If you have questions or need further information, write or call Kellee Husband at (502)564-3410 ext 4986 or email at kelleem.husband@kv.gov.

## ALL DOCUMENTATION MUST BE SUBMITIED TO:

Drinking Water Compliance & Technical Assistance
Division of Water, Department tor Environmental Protection
200 Fair Oaks Lane, 4th Floor Frankfort,
KY 40601

Bin m. Clitti

Issued By:

Brian Chitti

Drinking Water CTAB Supervisor

Compliance & Technical Assistance Branch

Division of Water

Date: March 9, 2016

How Delivered: Certified/Registered #7015 3430 0000 4915 0.321

WEREST OF STREET COL

THE DISTRICT - OVSTORE INFO A LUGUULIO

incident was not an emergency, as our customers, you have a right to

ar water system recently violated a drinking water standard, Altho ippened and what we did (are doing) to correct this situation

e routinely monitor for the presence of drinking water contaminants. Testing results from 7/1/2015 through 9/30/2015 and 10/1/2015 through 12/31/2015 ow that our system exceeds the standard, or maximum contaminant level (MCL), for trihalomethanes (THM) and haloacelic acids (HAA). The standard for IM is 0.080 mg/L, and the standard for HAA is 0,060 mg/L. These are determined by everaging all samples collected at each sampling location for the last months. The level of THM averaged at one of our system's locations for 7/1/2015 to 9/30/2015 was 0,081 mg/L and HAA was 0,070 mg/L. The level of 4M for 10/1/2015 to 12/31/2015 was 0.100 mg/L.

There is nothing you need to do, You do not need to boil your water or take other corrective actions. If a situation arises where the water is no

- longer safe to drink, you will be notified within 24 hours.
- If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek advice from your health care providers about drinking this water.

me people who drink water containing trihalomethanes in excess of the MCL over many years may experience problems with their liver, kidneys, or central vivous system, and may have an increased risk of getting cancer. Some people who drink water containing haloacetic acids in excess of the MCL over any years may have an increased risk of getting cancer.

its is not an emergency. If it had been an emergency, you would have been notified within 24 hours.

e are working to minimize the formation of disinfection by-products while ensuring we maintein an adequate level of disinfectant. We have taken steps to ango disinfectant levels, remove natural organic matter, and increased flushing of water lines. We anticipate resolving the problem within the next six

ir more information, please contact John Mills at 606-298-3885 or 387 E Main St. Suite 140, Inex, KY 41224.

sase share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, tople in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

Notice by Martin County Water District – System ID#; KY0800273 ar water system recently violated a drinking water standard. Although this incident was not an emergency, as our customers, you have a right to know what appened and what we did (are doing) to correct this situation,

e routinely monitor for the presence of drinking water conteminants; Testing results from 7/1/2015 through 9/30/2015 and 10/1/2015 through 12/31/2015 tow that our system exceeds the standard, or maximum conteminant level (MCL), for trihsiomethanes (THM) and heloacelic acids (HAA). The standard for HM is 0.080 mg/L and the standard for HAA is 0.060 mg/L. These are determined by averaging all samples collected at each sampling location for the last monitor. The level of THM averaged at one of our system's locations for 7/1/2015 to 9/30/2015 was 0.081 mg/L and HAA was 0.070 mg/L. The level of HAA is 0.0400 mg/L. IM for 10/1/2015 to 12/31/2015 was 0.100 mg/L;

- There is nothing you need to do. You do not need to boil your water or take other corrective actions; If a situation erises where the water is no longer safe to drink, you will be notified within 24 hours.
- If you have a severely compromised immune system, have an infant, are pregnent, or are elderly, you may be at increased risk and should seek advice from your health care providers about drinking this water.

ame people who drink water containing trihalomethanes in excess of the MCL over many years may experience problems with their liver, kidneys, or central rvous system, and may have an increased risk of gelling cancer. Some people who drink water containing haloacetic acids in excess of the MCL over any years may have an increased risk of gelting cancer.

is is not an emergency, If it had been an emergency, you would have been notified within 24 hours,

e are working to minimize the formation of disinfection by-products while ensuring we maintain an adequate level of disinfectant. We have taken steps to enge disinfectant levels, remove natural organic matter, and increased flushing of water lines. We anticipate resolving the problem within the next six

or more information, please contact John Mills at 606-298-3885 or 387 E Main St. Suite 140, Inex, KY 41224.

ease share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, sople in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

THM & HAA Stage 2 DBPR Template 2-19

Insert water system name and IDS in header, Insert compliance period begin date, end date, and average icvei, Remove brackets, Do not modify mandatory language!

### Printing Instructions

This template is designed to print the notice on the back of the water bill sheets prior to printing the water bills ing procedures the same as printing a letter.

After the notice has been printed to all sheets place the stack of sheets upside down on a flat surface and place a weight on the stack to remove the curl.

When the stack of sheets have cooled and straightened print the water bills as usual.

No text below this point

Copy and paste notice Prior to paste make suce that the cursor is at the highest point in the text box.

No text below this point.



## **ENERGY AND ENVIRONMENT CABINET**

Matthew G Bevin Governor

Department for Environmental Protection
Division of Water
200 Fair Oaks Lane, 4th Floor
Frankfort, Kentucky 40601
Phone: (502) 564-3410
Fax: (502) 564-2741
water.ky.gov

Charles G. Snavely Secretary

> R. Bruce Scott Commissioner

December 22, 2015

Earl Alley Martin County Water District #1 387 East Main St Suite 140 Inez, KY 41224 Re: Repeat Public Notice Extension

AI ID: 2987

PWSID: KY0800273

PWS NAME; Martin County Water District #1

COUNTY: Greenup

Dear Mr. Alley,

The Division of Water has considered your request and will grant an extension to the required repeat public notice for the ongoing disinfection byproduct MCL exceedance *or* a reduction in frequency of the repeat public notice. This will depend on the Locational Running Annual Average that is calculated for the 4th quarter of 2015.

If the water system continues to exceed the MCL for disinfection byproducts for the 4th quarter, the water system will use the 4th quarter results in the repeat public notice. If the water system comes back into compliance in the 4th quarter, the water system will be required to perform a public notice using the 3rd quarter results.

The public notice shall be performed no later than February 10th, 2016.

It is not required for the water system to receive a 4th quarter Notice of Violation before issuing the public notice. The water system may issue the notice as soon as they receive 4th quarter TTHM analysis results and can make a determination whether or not they are in compliance for the 4th quarter.

Please note all violations shall be listed in the 2015 Consumer Confidence Report.

If you have any questions or concerns, please contact Brook Overbay at (502) 564–3410, extension 4958. Or ashlee.overbay@ky.gov

Sincerely,

Brook Overbay Compliance Section Division of Water

C: Drinking Water Files





PAID

DEC 28 2015

MARTIN CO. WATER

Matthew G. Bevin Governor

# **ENERGY AND ENVIRONMENT CABINET**

Department for Environmental Protection
Division of Water
200 Fair Oaks Lane, 4th Floor
Frankfort, Kentucky 40601
Phone: (502) 564-3410
Fax: (502) 564-2741
www.water.ky.gov

Charles G, Snavely Secretary

> R. Bruce Scott Commissioner

December 14, 2015

To Whom It May Concern:

The Kentucky Department for Environmental Protection (DEP) has enclosed multiple notices for violations discovered at your facility. Please review each notice of violation carefully to ensure that all remedial measures are completed by the specified deadlines.

If you have questions regarding any of the violations, please call or write the contact identified on each of the violations.

Sincerely,

Bin m. Chitti

Brian Chitti
Drinking Water CTAB Supervisor
Compliance & Technical Assistance Branch
Division of Water

Enclosures





# **ENERGY AND ENVIRONMENT CABINET**

Matthew G. Bevin
Governor

Department for Environmental Protection
Division of Water
200 Fair Oaks Lane
4th Floor
Frankfort, Kentucky 40601
Phone: (502) 564-3410
Fax: (502) 564-2741
www.water.ky.gov

Charles G. Snavely
Secretary

R. Bruce Scott Commissioner

December 11, 2015

CERTIFIED MAIL: 7015 0640 0005 6317 6221 RETURN RECEIPT REQUESTED

JOHN MILLS MARTIN CO WATER DISTRICT #1 287 E MAIN ST SUITE 140 INEZ, KY 41224 Re: NOTICE OF VIOLATION

AI ID: 2987

PWSID: KY0800273

PWS NAME: MARTIN CO WATER DISTRICT #1

COUNTY: MARTIN

Dear Mr. Mills:

The Kentucky Department for Environmental Protection (DEP) has issued the enclosed Notice of Violation for violations discovered at your facility. Please review this Notice of Violation carefully to ensure that all remedial measures are completed by the specified deadlines.

Failure to comply with all remedial measures could result in enforcement action and the assessment of penalties. Your cooperation and attention to this matter is appreciated. If you have any questions, please contact Kellee Husband at (502)564-3410 ext. 4986 or email at kelleem.husband@ky.gov.

Sincerely,

Brian Chitti

Drinking Water CTAB Supervisor

Compliance & Technical Assistance Branch

Division of Water

C: Drinking Water Program files Enclosure

# COMMONWEALTH OF KENTUCKY ENERGY & ENVIRONMENT CABINET DEPARTMENT FOR ENVIRONMENTAL PROTECTION Division of Water

## NOTICE OF VIOLATION

To:

MARTIN CO WATER DISTRICT #1 287 E MAIN ST SUITE 140 INEZ, KY 41224

PWSID: KY0800273

PWS Name: MARTIN CO WATER DISTRICT #1 AI ID: 2987

County: MARTIN

Violation Number: 2016 - 9951173 Determination Date: 11/09/2015

Compliance Period: 07/01/2015 - 09/30/2015 Violation Type: 02 MCL, LRAA Tier Level: 2

PWS Facility: IDSE9999 IDSE - MARTN CO WATER DIST Contaminant: 2456 TOTAL HALOACETIC ACIDS (HAA5)

Public Water Systems are subject to the requirements of 401 KAR Chapter 8. [401 KAR 8:020 Section 1] This is to advise that you are in violation of the provision(s) cited below:

**Description of Non Compliance:** 

401 KAR 8:510 TOTAL HALOACETIC ACIDS (HAA5) The public water system exceeded the MCL for locational running annual average (LRAA) of samples for the specific contaminant in compliance period 07/01/2015 - 09/30/2015. The reported result of .07 mg/l exceeded the MCL of 0.060 mg/l.

# The remedial measure(s) and date(s) to be completed by are as follows:

Begin or continue quarterly monitoring for TOTAL HALOACETIC ACIDS (HAA5)

Perform public notification for the above-mentioned violation in accordance with 401 KAR 8:070. The public notification must not contain language that contradicts or detracts from the standard mandatory language or the purpose of the notice. Submit proof of public notification and its certification within ten (10) days of executing public notification. [401 KAR 8:070] The specific public notification activities to be performed are listed below.

PWS must give notice to consumers, including other water systems you may provide water to, about a violation by mail delivery or hand delivery. The notice must be executed within thirty (30) days following receipt by the PWS of this Notice of Violation.

If not all consumers can be notified by mail or hand delivery then the PWS must give notice to consumers about a violation by 1) publication in a newspaper of general circulation in the area served by the PWS or 2) by continuous posting in conspicuous places within the area served by the PWS. The notice must be executed within thirty (30) days following receipt by the PWS of this Notice of Violation.

Submit proof of public notification and its certification within ten (10) days of executing public notification.

Violations of the above cited statutes and/or regulations are subject to a civil penalty. Violations carry civil penalties of up to \$25,000 per day per violation depending on the statutes/regulations violated. In addition, violations may be concurrently enjoined. Compliance with remedial measures and their deadlines does not provide exemption from liability for violations during the period of remediation, nor prevent additional remedial measures from being required.

Detailed information about your water system's violations & monitoring requirements can be easily accessed on Kentucky Drinking Water Watch at <a href="http://dep.gateway.ky.gov/DWW/">http://dep.gateway.ky.gov/DWW/</a>

If you have questions or need further information, write or call Kellee Husband at (502)564-3410 ext 4986 or email at kelleem husband @ky.gov.

## ALL DOCUMENTATION MUST BE SUBMITTED TO:

Drinking Water Compliance & Technical Assistance
Division of Water, Department for Environmental Protection
200 Fair Oaks Lane, 4th Floor
Frankfort, KY 40601

Issued By:

Brian Chitti

Drinking Water CTAB Supervisor

Compliance & Technical Assistance Branch

Division of Water

Brian M. Chitti

Date: December 11, 2015

How Delivered: Certified/Registered #7015 0640 0005 6317 6221



# ENERGY AND ENVIRONMENT CABINET

Matthew G. Bevin Governor

Department for Environmental Protection
Division of Water
200 Fair Oaks Lane
4th Floor
Frankfort, Kentucky 40601
Phone: (502) 564-3410
Fax: (502) 564-2741

Charles G. Snavely Secretary

> R. Bruce Scott Commissioner

December 11, 2015

www.water,ky.gov

CERTIFIED MAIL: 7015 0640 0005 6317 6221

RETURN RECEIPT REQUESTED

JOHN MILLS MARTIN CO WATER DISTRICT #1 287 E MAIN ST SUITE 140 INEZ, KY 41224 Re: NOTICE OF VIOLATION

AI ID: 2987

PWSID: KY0800273

PWS NAME: MARTIN CO WATER DISTRICT #1

COUNTY: MARTIN

Dear Mr. Mills:

The Kentucky Department for Environmental Protection (DEP) has issued the enclosed Notice of Violation for violations discovered at your facility. Please review this Notice of Violation carefully to ensure that all remedial measures are completed by the specified deadlines.

Failure to comply with all remedial measures could result in enforcement action and the assessment of penalties. Your cooperation and attention to this matter is appreciated. If you have any questions, please contact Kellee Husband at (502)564-3410 ext. 4986 or email at kelleem.husband@ky.gov.

Sincerely,

Brian M. Chitti

Brian Chitti
Drinking Water CTAB Supervisor
Compliance & Technical Assistance Branch
Division of Water

C: Drinking Water Program files Enclosure

# COMMONWEALTH OF KENTUCKY ENERGY & ENVIRONMENT CABINET DEPARTMENT FOR ENVIRONMENTAL PROTECTION Division of Water

## NOTICE OF VIOLATION

To:

MARTIN CO WATER DISTRICT #1 287 E MAIN ST SUITE 140 INEZ, KY 41224

PWSID: KY0800273

PWS Name: MARTIN CO WATER DISTRICT #1 AI ID: 2987

County: MARTIN

Violation Number: 2016 - 9951174 Determination Date: 11/09/2015

Compliance Period: 07/01/2015 - 09/30/2015 Violation Type: 02 MCL, LRAA Tier Level: 2

PWS Facility: IDSE9999 IDSE - MARTN CO WATER DIST

Contaminant: 2950 TTHM

Public Water Systems are subject to the requirements of 401 KAR Chapter 8. [401 KAR 8:020 Section 1] This is to advise that you are in violation of the provision(s) cited below:

**Description of Non Compliance:** 

401 KAR 8:510 TTHM The public water system exceeded the MCL for locational running annual average (LRAA) of samples for the specific contaminant in compliance period 07/01/2015 - 09/30/2015. The reported result of .081 mg/l exceeded the MCL of 0.080 mg/l.

# The remedial measure(s) and date(s) to be completed by are as follows:

Begin or continue quarterly monitoring for TTHM

Perform public notification for the above-mentioned violation in accordance with 401 KAR 8:070. The public notification must not contain language that contradicts or detracts from the standard mandatory language or the purpose of the notice. Submit proof of public notification and its certification within ten (10) days of executing public notification. [401 KAR 8:070] The specific public notification activities to be performed are listed below.

PWS must give notice to consumers, including other water systems you may provide water to, about a violation by mail delivery or hand delivery. The notice must be executed within thirty (30) days following receipt by the PWS of this Notice of Violation.

If not all consumers can be notified by mail or hand delivery then the PWS must give notice to consumers about a violation by 1) publication in a newspaper of general circulation in the area served by the PWS or 2) by continuous posting in conspicuous places within the area served by the PWS. The notice must be executed within thirty (30) days following receipt by the PWS of this Notice of Violation.

Submit proof of public notification and its certification within ten (10) days of executing public notification.

Violations of the above cited statutes and/or regulations are subject to a civil penalty. Violations carry civil penalties of up to \$25,000 per day per violation depending on the statutes/regulations violated. In addition, violations may be concurrently enjoined. Compliance with remedial measures and their deadlines does not provide exemption from liability for violations during the period of remediation, nor prevent additional remedial measures from being required.

Detailed information about your water system's violations & monitoring requirements can be easily accessed on Kentucky Drinking Water Watch at http://dep.gateway.ky.gov/DWW/

If you have questions or need further information, write or call Kellee Husband at (502)564-3410 ext 4986 or email at kelleem, husband @ky.gov.

## ALL DOCUMENTATION MUST BE SUBMITTED TO:

Drinking Water Compliance & Technical Assistance
Division of Water Department for Environmental Protection
200 Fair Oaks Lane, 4th Floor
Frankfort, KY 40601

Issued By:

Bian M. Chitti

issued by

Brian Chitti

Drinking Water CTAB Supervisor

Compliance & Technical Assistance Branch

Division of Water

Date: December 11, 2015

How Delivered: Certified/Registered #7015 0640 0005 6317 6221