

City of Liberty

P.O. Box 127 • Liberty, KY 42539

RECEIVED

AUG 16 2021

PUBLIC SERVICE
COMMISSION

August 10, 2021

Kentucky Public Service Commission
211 Sower Boulevard
P.O. Box 615
Frankfort, KY 40602

Re: Case No. 2017-00053

Dear Commission,

The gas leakage survey for the Liberty Gas System was completed by Heath Consultants in July 2021. During the survey, two (2) grade 2 under ground leaks were discovered in Liberty's gas system.

The grade 2 leaks will be inspected routinely and repairs are on schedule to be made within the allotted time frame. Repair reports will be sent to the Commission as soon as they are repaired.

Please contact me at 606-787-9973 or libertybb@windstream.net for any questions or concerns.

Sincerely,



Bridgett Blake, City Clerk
City of Liberty, Kentucky



City Hall
(606) 787-9973

Utilities
(606) 787-6691

Fax (606) 787-7992

TDD # 1-800-247-2510




Leak Survey Report

CITY OF LIBERTY GAS DEPARTMENT

LIBERTY, KY.

Heath Consultants





Heath Consultants Incorporated

8-6-2021

Bridgett Blake
City of Liberty Gas Dept.
51 Jockey St.
Liberty, KY. 42539

Ms. Blake,

This is your final report of the results obtained during the recently completed gas leakage control survey.

The summary page following will give you further details concerning your survey. Should you have any questions or comments regarding the survey or this report, please contact us at 615.361.8306.

We appreciate this opportunity to be of service to you and look forward to serving you again in the near future.

Sincerely,

A handwritten signature in black ink, appearing to read "Shawn Baumgardner".

Shawn Baumgardner
Director of Operations
Heath Consultants Incorporated



SUMMARY OF

Gas Leak Survey

LEAKAGE CONTROL SURVEY

City of Liberty Gas Dept.
Client

Liberty, KY
City and State

40
District or Division

Conducted by our Consultant(s)

Marty Bryan

Date Start 7/27/2021

Date Completed 7/29/2021 **Total Day** 3

Number of Hours 24

Miles of Main Surveyed 32

Number of Services Inspected 453

Number of Leak Indications 2

| Under Ground Classification* | | |
|------------------------------|------|------|
| GR-1 | GR-2 | GR-3 |
| 0 | 2 | 0 |

| Above Ground Classification* | | |
|------------------------------|------|------|
| GR-1 | GR-2 | GR-3 |
| 0 | 0 | 0 |

Key Map Symbols

- x Indicates Leak Indication
- //// Estimated Area Affected
- Δ Catch Basin
- * Tree
- [] House & Building
- Indicates the Main
- ___Represents curbe line or edge of road unless designated as property line.

Leak Indication Classification*

- Grade 1- Schedule for Immediate Repair
- Grade 2- Schedule for Repair after Grade 1 indications are completed. Recheck mandatory if leak cannot be repaired within six months or before frost.
- Grade 3- Repair as work scheduled permit if indications cannot be repaired within one year, indication should be checked.

Special Cases

Contact HEATH CONSULTANTS INCORPORATED for further information regarding any Special Cases such as analysis, sample collecting, investigation, verification, survey recheck, etc. Our Consultant will be available on 24-hour notice to assist you.

*Leak indication is not an exact science in spite of use of the most modern instruments plus complete training and experience by the Consultant it is impossible to determine the exact condition of underground piping and equipment without actually exposing same. In view of this limitation our Consultant is intended as an aid in scheduling repairs based upon the information available, the Consultants judgment and and site conditions at the time the report is prepared. Variable factors beyond our control may alter this Classification at any time. Main and service line leak indications are classified individually. Classifications for buildings where leakage is found refer to the situation as it applies to the entire building. Individual building leaks are not classified.



CONSULTANT'S WEEKLY RESUME

ORDER NO.: _____

CLIENT: City of Liberty

WEEK ENDING: 07/31/21

LOCATION: Liberty Kentucky

DAYS TO COMPLETE SURVEY: _____

| Date | Town | Miles | Critical services | Services Surveyed | UNDERGROUND LEAKS | | | | ABOVE GROUND LEAKS | | | | | | | BILLABLE HOURS | | | |
|-----------------------------|---------|-------|-------------------|-------------------|-------------------|--------|--------|---------|--------------------|----------|----------|--------|--------|--------|-------|----------------|---------|---|----|
| | | | | | 1 or A | 2 or B | 3 or C | Reports | Buildings | Negative | Positive | 1 or A | 2 or B | 3 or C | Leaks | | Reports | | |
| 7/25 | | | | | | | | | | | | | | | | | | | |
| 7/26 | Liberty | | | | | | | | | | | | | | | | | | |
| 7/27 | Liberty | | | 225 | | 2 | | 2 | | | | | | | | | | 8 | |
| 7/28 | Liberty | | | 131 | | | | | | | | | | | | | | 8 | |
| 7/29 | Liberty | | | 97 | | | | | | | | | | | | | | 8 | |
| 7/30 | | | | | | | | | | | | | | | | | | | |
| 7/31 | | | | | | | | | | | | | | | | | | | |
| TOTAL FOR WEEK | | 0 | 0 | 453 | 0 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 24 |
| TOTAL THRU LAST WEEK | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| TOTAL TO DATE | | 0 | 0 | 453 | 0 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 24 |

| Day | DPIR PPM | DPIR Alarm | Passed Test? | RMLD PPM-M | RMLD Alarm | Passed Test? | OMD PPM | OMD Alarm | Passed Test? |
|-----------|----------|------------|--------------|------------|------------|--------------|---------|-----------|--------------|
| Sunday | | | | | | | | | |
| Monday | | | | | | | | | |
| Tuesday | | | | | | | | | |
| Wednesday | | | | | | | | | |
| Thursday | | | | | | | | | |
| Friday | | | | | | | | | |
| Saturday | | | | | | | | | |

Calibration Verified: (delete one Yes or No) S/N

RMLD _____

DPIR _____

OMD _____

FI _____

CGI _____

Marty C Bryan
Consultant



Heath Consultants Incorporated
 9030 Monroe Road, Houston, TX 77061

Date 7-27-2021

Status (Circle Status) Pos Neg.

Leak Indication Classification (Circle Leak Indication)
 1 2 3

TIME REPORTED _____

1 LEAK ONLY

LEAKAGE CONTROL REPORT

FIELD SURVEY

Company City of Liberty District Annual Survey

City Liberty State KY

Nearest Street Address

454 Whipp Ave

| TYPE OF GAS | |
|-------------|-------------------------------------|
| Natural | <input checked="" type="checkbox"/> |
| Manuf. | <input type="checkbox"/> |
| L.P. | <input type="checkbox"/> |
| Other | <input type="checkbox"/> |

| LEAK INDICATION FIRST DETECTED (AT) (IN) (BY) | | |
|---|-------------------------------------|--|
| Atmosphere | <input checked="" type="checkbox"/> | |
| Bar Hole Test | <input type="checkbox"/> | |
| Man Hole | <input type="checkbox"/> | |
| Pit (Reg. or Meter) | <input type="checkbox"/> | |
| Valve Box | <input type="checkbox"/> | |
| Main Valve | <input type="checkbox"/> | |
| Curb Valve | <input type="checkbox"/> | |
| Meter Box | <input type="checkbox"/> | |
| Underground Fuel Tank | <input type="checkbox"/> | |
| Selected Test | <input type="checkbox"/> | |


| METHOD OF SURVEY | |
|------------------|-------------------------------------|
| Vegetation | <input type="checkbox"/> |
| Portable F I | <input type="checkbox"/> |
| Mobile F I | <input type="checkbox"/> |
| Bar Hole | <input type="checkbox"/> |
| Other | <input checked="" type="checkbox"/> |

| LEAK INDICATION APPEARS TO BE AT: | |
|-----------------------------------|-------------------------------------|
| Main | <input checked="" type="checkbox"/> |
| Service | <input type="checkbox"/> |
| Service Tap | <input type="checkbox"/> |
| Main At Tie In | <input type="checkbox"/> |
| Drip | <input type="checkbox"/> |
| Meter | <input type="checkbox"/> |
| Curb Valve | <input type="checkbox"/> |
| Main Valve | <input type="checkbox"/> |
| Other | <input type="checkbox"/> |

| PIPE DESIGNATION | |
|------------------|-------------------------------------|
| Distribution | <input checked="" type="checkbox"/> |
| Transmission | <input type="checkbox"/> |
| Gathering | <input type="checkbox"/> |
| Other | <input type="checkbox"/> |

| PRESSURE | |
|--------------|--------------------------|
| High | <input type="checkbox"/> |
| Intermediate | <input type="checkbox"/> |
| Low | <input type="checkbox"/> |

| CGI TEST | |
|---------------------|-------------------------------------|
| Positive <u>88%</u> | <input checked="" type="checkbox"/> |
| Negative | <input type="checkbox"/> |



| LEAK INDICATION (Vegetation Only) | |
|-----------------------------------|--------------------------|
| Trees | <input type="checkbox"/> |
| Shrubs | <input type="checkbox"/> |
| Grass <u>N/A</u> | <input type="checkbox"/> |
| Lawn | <input type="checkbox"/> |
| Weeds | <input type="checkbox"/> |
| Odor | <input type="checkbox"/> |
| Other | <input type="checkbox"/> |

| LOCATION OF PIPE | |
|------------------------|-------------------------------------|
| Street | <input type="checkbox"/> |
| Between St. & Sidewalk | <input checked="" type="checkbox"/> |
| Under Sidewalk | <input type="checkbox"/> |
| Lawn | <input type="checkbox"/> |
| Easement | <input type="checkbox"/> |
| R.O.W. | <input type="checkbox"/> |
| Other | <input type="checkbox"/> |

Remarks Leak appears to be on Main

| COVER | |
|----------|-------------------------------------|
| Concrete | <input type="checkbox"/> |
| Asphalt | <input type="checkbox"/> |
| Brick | <input type="checkbox"/> |
| Gravel | <input type="checkbox"/> |
| Soil | <input checked="" type="checkbox"/> |
| Other | <input type="checkbox"/> |

Client Representative _____ Heath Consultant Matt C. By



Heath Consultants Incorporated

9030 Monroe Road, Houston, TX 77061

Date 7-27-2021

Status (Circle Status) Pos. Neg.

Leak Indication Classification (Circle Leak Indication)
1 2 3

TIME REPORTED _____

1 LEAK ONLY

LEAKAGE CONTROL REPORT

FIELD SURVEY

Company City of Liberty District Annual Survey

City Liberty State KY

Nearest Street Address

124 KY 49

| TYPE OF GAS | |
|-------------|-------------------------------------|
| Natural | <input checked="" type="checkbox"/> |
| Manuf. | <input type="checkbox"/> |
| L.P. | <input type="checkbox"/> |
| Other | <input type="checkbox"/> |

| LEAK INDICATION FIRST DETECTED (AT) (IN) (BY) | |
|---|-------------------------------------|
| Atmosphere | <input checked="" type="checkbox"/> |
| Bar Hole Test | <input type="checkbox"/> |
| Man Hole | <input type="checkbox"/> |
| Pit (Reg. or Meter) | <input type="checkbox"/> |
| Valve Box | <input type="checkbox"/> |
| Main Valve | <input type="checkbox"/> |
| Curb Valve | <input type="checkbox"/> |
| Meter Box | <input type="checkbox"/> |
| Underground Fuel Tank | <input type="checkbox"/> |
| Selected Test | <input type="checkbox"/> |


| METHOD OF SURVEY | |
|------------------|-------------------------------------|
| Vegetation | <input type="checkbox"/> |
| Portable F I | <input type="checkbox"/> |
| Mobile F I | <input type="checkbox"/> |
| Bar Hole | <input type="checkbox"/> |
| Other | <input checked="" type="checkbox"/> |

| LEAK INDICATION APPEARS TO BE AT: | |
|-----------------------------------|-------------------------------------|
| Main | <input checked="" type="checkbox"/> |
| Service | <input checked="" type="checkbox"/> |
| Service Tap | <input type="checkbox"/> |
| Main At Tie In | <input type="checkbox"/> |
| Drip | <input type="checkbox"/> |
| Meter | <input type="checkbox"/> |
| Curb Valve | <input type="checkbox"/> |
| Main Valve | <input type="checkbox"/> |
| Other | <input type="checkbox"/> |

| PIPE DESIGNATION | |
|------------------|-------------------------------------|
| Distribution | <input checked="" type="checkbox"/> |
| Transmission | <input type="checkbox"/> |
| Gathering | <input type="checkbox"/> |
| Other | <input type="checkbox"/> |

| PRESSURE | |
|--------------|-------------------------------------|
| High | <input type="checkbox"/> |
| Intermediate | <input checked="" type="checkbox"/> |
| Low | <input type="checkbox"/> |

| CGI TEST | |
|----------|--|
| Positive | <u>39%</u> <input checked="" type="checkbox"/> |
| Negative | <input type="checkbox"/> |



| LEAK INDICATION (Vegetation Only) | |
|-----------------------------------|--------------------------|
| Trees | <input type="checkbox"/> |
| Shrubs | <input type="checkbox"/> |
| Grass | <input type="checkbox"/> |
| Lawn | <u>N/A</u> |
| Weeds | <input type="checkbox"/> |
| Odor | <input type="checkbox"/> |
| Other | <input type="checkbox"/> |

| LOCATION OF PIPE | |
|------------------------|-------------------------------------|
| Street | <input type="checkbox"/> |
| Between St. & Sidewalk | <input checked="" type="checkbox"/> |
| Under Sidewalk | <input type="checkbox"/> |
| Lawn | <input type="checkbox"/> |
| Easement | <input type="checkbox"/> |
| R.O.W. | <input type="checkbox"/> |
| Other | <input type="checkbox"/> |

Remarks Leak appears to be on main

| COVER | |
|----------|-------------------------------------|
| Concrete | <input type="checkbox"/> |
| Asphalt | <input type="checkbox"/> |
| Brick | <input type="checkbox"/> |
| Gravel | <input type="checkbox"/> |
| Soil | <input checked="" type="checkbox"/> |
| Other | <input type="checkbox"/> |

Client Representative _____
 Health Consultant Marty C. By

Leak Survey 2021



COMPANY: Liberty Utilities, Liberty KY

LEGEND: AC Atmospheric Corrosion

TECHNICIAN: Marty C. Bryan

NP- Needs Paints

PAGE: 1

| DATE | ROUTE | HOUSE# | ADDRESS | AC | POS | NEG |
|-----------|-------|--------|----------------|----|-----|-----|
| 7/27/2021 | 102 | 539 | Allen St | OK | | X |
| 7/27/2021 | 102 | 411 | Hustonville St | OK | | X |
| 7/27/2021 | 102 | 587 | Allen St | OK | | X |
| 7/27/2021 | 102 | 109 | Wall St | OK | | X |
| 7/27/2021 | 102 | 147 | Wall St | OK | | X |
| 7/27/2021 | 102 | 167 | Wall St | OK | | x |
| 7/27/2021 | 102 | 241 | Phillips St | OK | | X |
| 7/27/2021 | 102 | 232 | Phillips St | OK | | X |
| 7/27/2021 | 102 | 225 | Phillips St | OK | | X |
| 7/27/2021 | 102 | 189 | Phillips St | OK | | X |
| 7/27/2021 | 102 | 161 | Phillips St | OK | | X |
| 7/27/2021 | 102 | 141 | Phillips St | OK | | X |
| 7/27/2021 | 102 | 540 | Hustonville St | OK | | x |
| 7/27/2021 | 102 | 549 | Hustonville St | OK | | x |
| 7/27/2021 | 102 | 476 | Carmicle St | OK | | x |
| 7/27/2021 | 102 | 463 | Carmicle St | OK | | x |
| 7/27/2021 | 102 | 470 | Carmicle St | OK | | x |
| 7/27/2021 | 102 | 453 | Carmicle St | OK | | x |
| 7/27/2021 | 102 | 440 | Carmicle St | OK | | x |
| 7/27/2021 | 102 | 430 | Carmicle St | OK | | x |
| 7/27/2021 | 102 | 427 | Carmicle St | OK | | x |
| 7/27/2021 | 102 | 417 | Carmicle St | OK | | x |
| 7/27/2021 | 102 | 360 | Carmicle St | OK | | x |
| 7/27/2021 | 102 | 410 | Phillips St | OK | | x |
| 7/27/2021 | 102 | 425 | Phillips St | OK | | x |
| 7/27/2021 | 102 | 740 | Hustonville St | OK | | x |
| 7/27/2021 | 102 | 450 | Popplewell St | OK | | x |
| 7/27/2021 | 102 | 435 | Popplewell St | OK | | x |
| 7/27/2021 | 102 | 369 | Popplewell St | OK | | x |
| 7/27/2021 | 102 | 651 | Whipp Av | OK | | x |
| 7/27/2021 | 102 | 671 | Wolford Av | OK | | x |
| 7/27/2021 | 102 | 578 | Whipp Av | OK | | x |
| 7/27/2021 | 102 | 521 | Whipp Av | OK | | X |
| 7/27/2021 | 102 | 510 | Whipp Av | OK | | x |
| 7/27/2021 | 102 | 338 | Trammell St | OK | | x |
| 7/27/2021 | 102 | 341 | Trammell St | OK | | x |
| 7/27/2021 | 102 | 377 | Trammell St | OK | | x |

Leak Survey 2021



COMPANY: Liberty Utilities, Liberty KY

LEGEND: AC Atmospheric Corrosion

TECHNICIAN: Marty C. Bryan

NP- Needs Paints

PAGE: 2

| DATE | ROUTE | HOUSE# | ADDRESS | AC | POS | NEG |
|-----------|-------|--------|-------------|----|------|-----|
| 7/27/2021 | 102 | 426 | Trammell St | OK | | x |
| 7/27/2021 | 102 | 438 | Trammell St | OK | | x |
| 7/27/2021 | 102 | 411 | Trammell St | OK | | x |
| 7/27/2021 | 102 | 434 | Weddle St | OK | | x |
| 7/27/2021 | 102 | 353 | Fair St | OK | | x |
| 7/27/2021 | 102 | 454 | Whipp Av | OK | xGR2 | |
| 7/27/2021 | 102 | 240 | Trammell St | OK | | x |
| 7/27/2021 | 102 | | Adams St | OK | | x |
| 7/27/2021 | 102 | 241 | Trammell St | OK | | x |
| 7/27/2021 | 102 | 378 | Wolford Av | OK | | x |
| 7/27/2021 | 102 | 109 | Fair St | OK | | x |
| 7/27/2021 | 102 | 357 | Wolford Av | OK | | x |
| 7/27/2021 | 102 | 339 | Wolford Av | OK | | x |
| 7/27/2021 | 102 | 323 | Wolford Av | OK | | x |
| 7/27/2021 | 102 | 320 | Wolford Av | OK | | x |
| 7/27/2021 | 102 | 112 | Allen St | OK | | x |
| 7/27/2021 | 103 | 340 | Whipp Av | OK | | x |
| 7/27/2021 | 103 | 356 | Allen St | OK | | x |
| 7/27/2021 | 103 | 418 | Allen St | OK | | x |
| 7/27/2021 | 103 | 452 | Allen St | OK | | x |
| 7/27/2021 | 103 | 455 | Allen St | OK | | x |
| 7/27/2021 | 103 | 397 | Beldon St | OK | | x |
| 7/27/2021 | 103 | 384 | Beldon St | OK | | x |
| 7/27/2021 | 103 | 364 | Beldon St | OK | | x |
| 7/27/2021 | 103 | 321 | Beldon St | OK | | x |
| 7/27/2021 | 103 | 314 | Beldon St | OK | | x |
| 7/27/2021 | 103 | 280 | Beldon St | OK | | x |
| 7/27/2021 | 103 | 250 | Beldon St | OK | | x |
| 7/27/2021 | 103 | 241 | Beldon St | OK | | x |
| 7/27/2021 | 103 | 107 | Beldon St | OK | | x |
| 7/27/2021 | 103 | 36 | Beldon St | OK | | x |
| 7/27/2021 | 103 | 58 | Beldon St | OK | | x |
| 7/27/2021 | 103 | 72 | Beldon St | OK | | x |
| 7/27/2021 | 103 | 88 | Beldon St | OK | | x |
| 7/27/2021 | 103 | 116 | Beldon St | OK | | x |
| 7/27/2021 | 103 | 451 | Montgomery | OK | | x |
| 7/27/2021 | 103 | 444 | Montgomery | OK | | x |

Leak Survey 2021



COMPANY: Liberty Utilities, Liberty KY

LEGEND: AC Atmospheric Corrosion

TECHNICIAN: Marty C. Bryan

NP- Needs Paints

PAGE: 3

| DATE | ROUTE | HOUSE# | ADDRESS | AC | POS | NEG |
|-----------|-------|--------|------------|----|-----|-----|
| 7/27/2021 | 103 | 425 | Montgomery | OK | | x |
| 7/27/2021 | 103 | 334 | Montgomery | OK | | x |
| 7/27/2021 | 103 | 362 | Montgomery | OK | | x |
| 7/27/2021 | 103 | 108 | Taylor St | OK | | x |
| 7/27/2021 | 103 | 410 | Montgomery | OK | | x |
| 7/27/2021 | 103 | 136 | Taylor St | OK | | x |
| 7/27/2021 | 103 | 164 | Taylor St | OK | | x |
| 7/27/2021 | 103 | 176 | Taylor St | OK | | x |
| 7/27/2021 | 103 | 205 | Taylor St | OK | | x |
| 7/27/2021 | 103 | 237 | Taylor St | OK | | x |
| 7/27/2021 | 103 | 244 | Taylor St | OK | | x |
| 7/27/2021 | 103 | 253 | Taylor St | OK | | x |
| 7/27/2021 | 103 | 271 | Taylor St | OK | | x |
| 7/27/2021 | 103 | 369 | Allen St | OK | | x |
| 7/27/2021 | 103 | 351 | Allen St | OK | | x |
| 7/27/2021 | 103 | 331 | Allen St | OK | | x |
| 7/27/2021 | 103 | 292 | Whipp Av | OK | | x |
| 7/27/2021 | 103 | 274 | Whipp Av | OK | | x |
| 7/27/2021 | 103 | 275 | Whipp Av | OK | | x |
| 7/27/2021 | 103 | 264 | Whipp Av | OK | | x |
| 7/27/2021 | 103 | 252 | Whipp Av | OK | | x |
| 7/27/2021 | 103 | 236 | Whipp Av | OK | | x |
| 7/27/2021 | 103 | 245 | Whipp Av | OK | | x |
| 7/27/2021 | 103 | 231 | Whipp Av | OK | | x |
| 7/27/2021 | 103 | 217 | Whipp Av | OK | | x |
| 7/27/2021 | 103 | 199 | Whipp Av | OK | | x |
| 7/27/2021 | 103 | 218 | Whipp Av | OK | | x |
| 7/27/2021 | 103 | 198 | Whipp Av | OK | | x |
| 7/27/2021 | 103 | 190 | Whipp Av | OK | | x |
| 7/27/2021 | 103 | 189 | Whipp Av | OK | | x |
| 7/27/2021 | 103 | 178 | Whipp Av | OK | | x |
| 7/27/2021 | 103 | 166 | Whipp Av | OK | | x |
| 7/27/2021 | 103 | 139 | Whipp Av | OK | | x |
| 7/27/2021 | 103 | 111 | Whipp Av | OK | | x |
| 7/27/2021 | 103 | 315 | Montgomery | OK | | x |
| 7/27/2021 | 103 | 276 | Montgomery | OK | | x |
| 7/27/2021 | 103 | | Sanders | OK | | x |

Leak Survey 2021



COMPANY: Liberty Utilities, Liberty KY

LEGEND: AC Atmospheric Corrosion

TECHNICIAN: Marty C. Bryan

NP- Needs Paints

PAGE: 4

| DATE | ROUTE | HOUSE# | ADDRESS | AC | POS | NEG |
|-----------|-------|--------|---------------------|----|-----|-----|
| 7/27/2021 | 103 | 199 | Sanders | OK | | x |
| 7/27/2021 | 103 | 75 | College St | OK | | x |
| 7/27/2021 | 103 | 98 | College St | OK | | x |
| 7/27/2021 | 103 | 58 | College St | OK | | x |
| 7/27/2021 | 103 | 80 | College St | OK | | x |
| 7/27/2021 | 103 | 116 | Montgomery | OK | | x |
| 7/27/2021 | 103 | | Montgomery | OK | | x |
| 7/27/2021 | 103 | 230 | Wolford Av | OK | | x |
| 7/27/2021 | 103 | 244 | Wolford Av | OK | | x |
| 7/27/2021 | 103 | 241 | Wolford Av | OK | | x |
| 7/27/2021 | 103 | 244 | Adams St | OK | | x |
| 7/27/2021 | 103 | 251 | Adams St | OK | | x |
| 7/27/2021 | 103 | 237 | Adams St | OK | | x |
| 7/27/2021 | 103 | 211 | Adams St | OK | | x |
| 7/27/2021 | 103 | 134 | Griffin St | OK | | x |
| 7/27/2021 | 103 | 176 | Wolford Av | OK | | x |
| 7/27/2021 | 103 | 52 | Montgomery | OK | | x |
| 7/27/2021 | 103 | 105 | Montgomery | OK | | x |
| 7/27/2021 | 103 | 53 | Montgomery | OK | | x |
| 7/27/2021 | 103 | 31 | Montgomery | OK | | x |
| 7/27/2021 | 103 | 14 | Montgomery | OK | | x |
| 7/27/2021 | 103 | 150 | Foster St | OK | | x |
| 7/27/2021 | 103 | 150 | Foster St | OK | | x |
| 7/27/2021 | 103 | 99 | Wallace | OK | | x |
| 7/27/2021 | 103 | 150 | Foster St | OK | | x |
| 7/27/2021 | 103 | 150 | Foster St | OK | | x |
| 7/27/2021 | 103 | 115 | N Wallace Wilkerson | OK | | x |
| 7/27/2021 | 103 | 115 | N Wallace Wilkerson | OK | | x |
| 7/27/2021 | 103 | 14 | Foster St | OK | | x |
| 7/27/2021 | 103 | 271 | Wolford Av | OK | | x |
| 7/27/2021 | 103 | 222 | Allen St | OK | | x |
| 7/27/2021 | 103 | 239 | Allen St | OK | | x |
| 7/27/2021 | 103 | 223 | Allen St | Ok | | x |
| 7/27/2021 | 103 | 269 | Allen St | OK | | x |
| 7/27/2021 | 103 | 312 | Allen St | OK | | x |
| 7/27/2021 | 103 | 328 | Allen St | OK | | x |
| 7/27/2021 | 103 | 351 | Allen St | OK | | x |

Leak Survey 2021



COMPANY: Liberty Utilities, Liberty KY

LEGEND: AC Atmospheric Corrosion

TECHNICIAN: Marty C. Bryan

NP- Needs Paints

PAGE: 5

| DATE | ROUTE | HOUSE# | ADDRESS | AC | POS | NEG |
|-----------|-------|--------|-------------------|----|-----|-----|
| 7/27/2021 | 103 | 351 | Adams St | OK | | x |
| 7/27/2021 | 103 | 356 | Adams St | OK | | x |
| 7/27/2021 | 103 | 139 | Fair St | OK | | x |
| 7/27/2021 | 103 | 242 | Fair St | OK | | x |
| 7/27/2021 | 103 | 256 | Fair St | OK | | x |
| 7/27/2021 | 103 | 280 | Fair St | OK | | x |
| 7/27/2021 | 103 | 340 | Whipp Av | OK | | x |
| 7/27/2021 | 103 | 356 | Allen St | OK | | x |
| 7/27/2021 | 103 | 418 | Allen St | OK | | x |
| 7/27/2021 | 103 | 452 | Allen St | OK | | x |
| 7/27/2021 | 101 | 625 | Campbellsville St | OK | | x |
| 7/27/2021 | 101 | 231 | Courthouse square | OK | | x |
| 7/27/2021 | 101 | 169 | Courthouse square | OK | | x |
| 7/27/2021 | 101 | 169 | Courthouse square | OK | | x |
| 7/27/2021 | 101 | 763 | Campbellsville St | OK | | x |
| 7/27/2021 | 101 | 913 | Campbellsville St | OK | | x |
| 7/27/2021 | 101 | 932 | Campbellsville St | OK | | x |
| 7/27/2021 | 101 | 966 | Campbellsville St | OK | | x |
| 7/27/2021 | 101 | 959 | Campbellsville St | OK | | x |
| 7/27/2021 | 101 | 1019 | Campbellsville St | OK | | x |
| 7/27/2021 | 101 | 1109 | Campbellsville St | OK | | x |
| 7/27/2021 | 101 | 1139 | Campbellsville St | OK | | x |
| 7/27/2021 | 101 | 1139 | Campbellsville St | OK | | x |
| 7/27/2021 | 101 | 1171 | Campbellsville St | OK | | x |
| 7/27/2021 | 101 | 770 | Campbellsville St | OK | | x |
| 7/27/2021 | 101 | 752 | Campbellsville St | OK | | x |
| 7/27/2021 | 101 | 718 | Campbellsville St | OK | | x |
| 7/27/2021 | 101 | 770 | Campbellsville St | OK | | x |
| 7/27/2021 | 101 | | Gosser St | OK | | x |
| 7/27/2021 | 101 | 668 | Campbellsville St | OK | | x |
| 7/27/2021 | 101 | 664 | Campbellsville St | OK | | x |
| 7/27/2021 | 101 | 654 | Campbellsville St | OK | | x |
| 7/27/2021 | 101 | 634 | Campbellsville St | OK | | x |
| 7/27/2021 | 101 | 630 | Campbellsville St | OK | | x |
| 7/27/2021 | 101 | 628 | Campbellsville St | OK | | x |
| 7/27/2021 | 101 | 628 | Campbellsville St | OK | | x |
| 7/27/2021 | 101 | 626 | Campbellsville St | OK | | x |

Leak Survey 2021



COMPANY: Liberty Utilities, Liberty KY

LEGEND: AC Atmospheric Corrosion

TECHNICIAN: Marty C. Bryan

NP- Needs Paints

PAGE: 6

| DATE | ROUTE | HOUSE# | ADDRESS | AC | POS | NEG |
|-----------|-------|--------|-------------------|----|------|-----|
| 7/27/2021 | 101 | 26 | Campbellsville St | OK | | x |
| 7/27/2021 | 101 | 33 | Hustonville St | OK | | x |
| 7/27/2021 | 101 | 33 | Hustonville St | OK | | x |
| 7/27/2021 | 101 | 58 | Hustonville St | OK | | x |
| 7/27/2021 | 101 | 58 | Hustonville St | ok | | x |
| 7/27/2021 | 101 | 56 | Hustonville St | OK | | x |
| 7/27/2021 | 101 | 36 | Hustonville St | OK | | x |
| 7/27/2021 | 101 | 546 | Middleburg St | OK | | x |
| 7/27/2021 | 101 | 546 | Middleburg St | OK | | x |
| 7/27/2021 | 101 | 14 | Hustonville St | OK | | x |
| 7/27/2021 | 101 | 108 | Hustonville St | OK | | x |
| 7/27/2021 | 101 | 132 | Hustonville St | OK | | x |
| 7/27/2021 | 101 | 11 | KY 49 | OK | | x |
| 7/27/2021 | 101 | 30 | Brown Ct | OK | | x |
| 7/27/2021 | 101 | 54 | Brown Ct | OK | | x |
| 7/27/2021 | 101 | 75 | Brown Ct | OK | | x |
| 7/27/2021 | 101 | 82 | Brown Ct | OK | | x |
| 7/27/2021 | 101 | 67 | Brown Ct | OK | | x |
| 7/27/2021 | 101 | 163 | Hustonville St | OK | | x |
| 7/27/2021 | 101 | 95 | KY 49 | OK | | x |
| 7/27/2021 | 101 | 119 | KY 49 | OK | | x |
| 7/27/2021 | 101 | 124 | KY 49 | OK | Xgr2 | |
| 7/27/2021 | 101 | 142 | KY 49 | OK | | x |
| 7/27/2021 | 101 | 142 | KY 49 | OK | | x |
| 7/27/2021 | 101 | 158 | KY 49 | OK | | x |
| 7/27/2021 | 101 | 43 | Bartle Heights | OK | | x |
| 7/27/2021 | 101 | 216 | KY 49 | OK | | x |
| 7/27/2021 | 101 | 230 | KY 49 | OK | | x |
| 7/27/2021 | 101 | 250 | KY 49 | OK | | x |
| 7/27/2021 | 101 | 279 | KY 49 | OK | | x |
| 7/27/2021 | 101 | 391 | KY 49 | OK | | x |
| 7/27/2021 | 101 | 454 | KY 49 | OK | | x |
| 7/27/2021 | 101 | 501 | KY 49 | OK | | x |
| 7/27/2021 | 101 | 625 | KY 49 | OK | | x |
| 7/27/2021 | 101 | 693 | KY 49 | OK | | x |
| 7/27/2021 | 101 | 817 | KY 49 | OK | | x |
| 7/27/2021 | 101 | 219 | Hustonville St | OK | | x |

Leak Survey 2021



COMPANY: Liberty Utilities, Liberty KY

LEGEND: AC Atmospheric Corrosion

TECHNICIAN: Marty C. Bryan

NP- Needs Paints

PAGE: 7

| DATE | ROUTE | HOUSE# | ADDRESS | AC | POS | NEG |
|-----------|-------|--------|----------------|----|-----|-----|
| 7/27/2021 | 101 | 246 | Hustonville St | OK | | x |
| 7/27/2021 | 101 | 327 | Hustonville St | OK | | x |
| 7/27/2021 | 101 | 367 | Hustonville St | OK | | x |
| 7/28/2021 | 104 | 57 | Middleburg St | OK | | x |
| 7/28/2021 | 104 | 58 | Middleburg St | OK | | x |
| 7/28/2021 | 104 | 74 | Middleburg St | OK | | x |
| 7/28/2021 | 104 | 94 | Middleburg St | OK | | x |
| 7/28/2021 | 104 | 89 | Middleburg St | OK | | x |
| 7/28/2021 | 104 | 115 | Middleburg St | OK | | x |
| 7/28/2021 | 104 | 106 | Middleburg St | OK | | x |
| 7/28/2021 | 104 | 118 | Middleburg St | OK | | x |
| 7/28/2021 | 104 | 138 | Middleburg St | OK | | x |
| 7/28/2021 | 104 | 173 | Middleburg St | OK | | x |
| 7/28/2021 | 104 | 38 | Conner St | OK | | x |
| 7/28/2021 | 104 | 62 | Conner St | OK | | x |
| 7/28/2021 | 104 | 79 | Conner St | OK | | x |
| 7/28/2021 | 104 | 238 | Middleburg St | OK | | x |
| 7/28/2021 | 104 | 248 | Middleburg St | OK | | x |
| 7/28/2021 | 104 | 253 | Middleburg St | OK | | x |
| 7/28/2021 | 104 | 44 | Maple | OK | | x |
| 7/28/2021 | 104 | 57 | Maple | OK | | x |
| 7/28/2021 | 104 | 71 | Maple | OK | | x |
| 7/28/2021 | 104 | 58 | Maple | OK | | x |
| 7/28/2021 | 104 | 80 | Maple | OK | | x |
| 7/28/2021 | 104 | 77 | Northcut St | OK | | x |
| 7/28/2021 | 104 | 323 | Middleburg St | OK | | x |
| 7/28/2021 | 104 | 417 | Middleburg St | OK | | x |
| 7/28/2021 | 104 | 414 | Middleburg St | OK | | x |
| 7/28/2021 | 104 | 438 | Middleburg St | OK | | x |
| 7/28/2021 | 104 | 14 | Beldon St | OK | | x |
| 7/28/2021 | 104 | 532 | Middleburg St | OK | | x |
| 7/28/2021 | 104 | 511 | Middleburg St | OK | | x |
| 7/28/2021 | 104 | 523 | Middleburg St | OK | | x |
| 7/28/2021 | 104 | 529 | Middleburg St | OK | | x |
| 7/28/2021 | 104 | | Middleburg St | OK | | x |
| 7/28/2021 | 104 | 113 | Courthouse SQ | OK | | x |
| 7/28/2021 | 104 | 133 | Courthouse SQ | OK | | x |

Leak Survey 2021



COMPANY: Liberty Utilities, Liberty KY

LEGEND: AC Atmospheric Corrosion

TECHNICIAN: Marty C. Bryan

NP- Needs Paints

PAGE: 8

| DATE | ROUTE | HOUSE# | ADDRESS | AC | POS | NEG |
|-----------|-------|--------|--------------------------|----|-----|-----|
| 7/28/2021 | 104 | 21 | S wilkerson Blvd | OK | | x |
| 7/28/2021 | 104 | 92 | N Wilkinson Blvd | OK | | x |
| 7/28/2021 | 104 | 130 | N Wilkinson Blvd | OK | | x |
| 7/28/2021 | 104 | 130 | N Wilkinson Blvd | OK | | x |
| 7/28/2021 | 104 | 206 | N Wilkinson Blvd | OK | | x |
| 7/28/2021 | 104 | 224 | N Wilkinson Blvd | OK | | x |
| 7/28/2021 | 104 | 262 | N Wallace wilkinson Blvd | OK | | x |
| 7/28/2021 | 104 | 255 | N Wallace wilkinson Blvd | OK | | x |
| 7/28/2021 | 104 | 261 | N Wallace wilkinson Blvd | OK | | x |
| 7/28/2021 | 104 | 245 | N Wallace wilkinson Blvd | OK | | x |
| 7/28/2021 | 104 | 245 | N Wallace wilkinson Blvd | OK | | x |
| 7/28/2021 | 104 | 223 | N Wilkinson Blvd | OK | | x |
| 7/28/2021 | 104 | 245 | N Wilkinson Blvd | OK | | x |
| 7/28/2021 | 104 | | N Wilkinson Blvd | OK | | x |
| 7/28/2021 | 104 | 343 | N Wilkinson Blvd | OK | | x |
| 7/28/2021 | 104 | 371 | N Wilkinson Blvd | OK | | x |
| 7/28/2021 | 104 | 397 | N Wallace wilkinson Blvd | OK | | x |
| 7/28/2021 | 104 | 410 | N Wallace wilkinson Blvd | ok | | x |
| 7/28/2021 | 104 | 100 | Liberty sq | OK | | x |
| 7/28/2021 | 104 | 112 | Liberty sq | OK | | x |
| 7/28/2021 | 104 | 112 | Liberty sq | OK | | x |
| 7/28/2021 | 104 | 122 | Liberty sq | OK | | x |
| 7/28/2021 | 104 | 140 | Liberty sq | OK | | x |
| 7/28/2021 | 104 | 150 | Liberty sq | OK | | x |
| 7/28/2021 | 104 | 49 | Scanlon Dr | OK | | x |
| 7/28/2021 | 104 | 49 | Scanlon Dr | ok | | x |
| 7/28/2021 | 104 | 472 | Wallace Wilkinson | OK | | x |
| 7/28/2021 | 104 | 543 | N Wilkinson Blvd | OK | | x |
| 7/28/2021 | 104 | 579 | Wallace Wilkinson | OK | | x |
| 7/28/2021 | 104 | 112 | Dillon St | OK | | x |
| 7/28/2021 | 104 | 112 | Dillon St | OK | | x |
| 7/28/2021 | 104 | 130 | Dillon St | OK | | x |
| 7/28/2021 | 104 | 130 | Dillon St | OK | | x |
| 7/28/2021 | 104 | 150 | Dillon St | OK | | x |
| 7/28/2021 | 104 | 150 | Dillon St | OK | | x |
| 7/28/2021 | 104 | 180 | Dillon St | OK | | x |
| 7/28/2021 | 104 | 180 | Dillon St | OK | | x |

Leak Survey 2021



COMPANY: Liberty Utilities, Liberty KY

LEGEND: AC Atmospheric Corrosion

TECHNICIAN: Marty C. Bryan

NP- Needs Paints

PAGE: 9

| DATE | ROUTE | HOUSE# | ADDRESS | AC | POS | NEG |
|-----------|-------|--------|--------------|----|-----|-----|
| 7/28/2021 | 104 | 705 | N Wilkinson | OK | | X |
| 7/28/2021 | 104 | 260 | Dillion St | OK | | x |
| 7/28/2021 | 104 | 260 | Dillion St | OK | | x |
| 7/28/2021 | 104 | 230 | Dillion St | OK | | x |
| 7/28/2021 | 104 | 212 | Dillion St | OK | | x |
| 7/28/2021 | 104 | 15 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 35 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 19 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 19 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 19 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 700 | N Wilkinson | OK | | x |
| 7/28/2021 | 104 | 19 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 29 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 25 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 25 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 25 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 20 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 20 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 20 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 20 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 20 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 750 | N Wilkinson | OK | | x |
| 7/28/2021 | 104 | | Dillion St | OK | | x |
| 7/28/2021 | 104 | 85 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 85 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 85 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 85 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 50 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 50 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 50 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 50 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 100 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 100 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 100 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 100 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 90 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 90 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 90 | Riverdale Dr | OK | | x |

Leak Survey 2021



COMPANY: Liberty Utilities, Liberty KY

LEGEND: AC Atmospheric Corrosion

TECHNICIAN: Marty C. Bryan

NP- Needs Paints

PAGE: 10

| DATE | ROUTE | HOUSE# | ADDRESS | AC | POS | NEG |
|-----------|-------|--------|-------------------|----|-----|-----|
| 7/28/2021 | 104 | 50 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 100 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 100 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 100 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 100 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 90 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 90 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 90 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 90 | Riverdale Dr | OK | | x |
| 7/28/2021 | 104 | 735 | N Wilkinson Blvd | OK | | x |
| 7/28/2021 | 104 | 938 | N Wilkinson Blvd | OK | | x |
| 7/28/2021 | 104 | 775 | N Wilkinson Blvd | OK | | x |
| 7/28/2021 | 104 | 1200 | Wallace Wilkinson | OK | | x |
| 7/28/2021 | 104 | 750 | Wallace Wilkinson | OK | | x |
| 7/28/2021 | 104 | | N Hwy 127 | OK | | x |
| 7/28/2021 | 104 | 815 | Wallace Wilkinson | OK | | x |
| 7/28/2021 | 104 | 46 | Farmers Bank Dr | OK | | x |
| 7/28/2021 | 104 | 46 | Farmers Bank Dr | OK | | x |
| 7/28/2021 | 104 | 1124 | Hustonville St | OK | | x |
| 7/28/2021 | 104 | 1031 | Hustonville St | OK | | x |
| 7/28/2021 | 104 | 1031 | Hustonville St | OK | | x |
| 7/28/2021 | 104 | 1024 | Hustonville St | OK | | x |
| 7/28/2021 | 104 | 1004 | Hustonville St | OK | | x |
| 7/29/2021 | 105 | 107 | Woodrum Ridge | OK | | x |
| 7/29/2021 | 105 | 107 | Woodrum Ridge | OK | | x |
| 7/29/2021 | 105 | 909 | Hustonville St | OK | | x |
| 7/29/2021 | 105 | 221 | Napier St | OK | | x |
| 7/29/2021 | 105 | 100 | Napier St | OK | | x |
| 7/29/2021 | 105 | 465 | Woodrum Ridge | OK | | x |
| 7/29/2021 | 105 | 187 | Woodrum Ridge | OK | | x |
| 7/29/2021 | 105 | 186 | Woodrum Ridge | OK | | x |
| 7/29/2021 | 105 | 256 | Sweeney St | OK | | x |
| 7/29/2021 | 105 | 774 | E KY 70 | OK | | x |
| 7/29/2021 | 105 | 1168 | E KY 70 | OK | | x |
| 7/29/2021 | 105 | 1190 | E KY 70 | OK | | x |
| 7/29/2021 | 105 | 1305 | E KY 70 | OK | | x |
| 7/29/2021 | 105 | 1377 | E KY 70 | OK | | x |

Leak Survey 2021



COMPANY: Liberty Utilities, Liberty KY

LEGEND: AC Atmospheric Corrosion

TECHNICIAN: Marty C. Bryan

NP- Needs Paints

PAGE: 11

| DATE | ROUTE | HOUSE# | ADDRESS | AC | POS | NEG |
|-----------|-------|--------|--------------|----|-----|-----|
| 7/29/2021 | 105 | 1397 | E KY 70 | OK | | x |
| 7/29/2021 | 105 | 1423 | E KY 70 | OK | | x |
| 7/29/2021 | 105 | 1533 | E KY 70 | OK | | x |
| 7/29/2021 | 105 | 1520 | E KY 70 | OK | | x |
| 7/29/2021 | 105 | 1563 | E KY 70 | OK | | x |
| 7/29/2021 | 105 | 1611 | E KY 70 | OK | | x |
| 7/29/2021 | 105 | 1841 | E KY 70 | OK | | x |
| 7/29/2021 | 105 | 1723 | E KY 70 | OK | | x |
| 7/29/2021 | 105 | 1841 | E KY 70 | OK | | x |
| 7/29/2021 | 105 | 1841 | E KY 70 | OK | | x |
| 7/29/2021 | 105 | 1841 | E KY 70 | OK | | x |
| 7/29/2021 | 105 | 1983 | E KY 70 | OK | | x |
| 7/29/2021 | 105 | 1983 | E KY 70 | OK | | x |
| 7/29/2021 | 105 | 1983 | E KY 70 | OK | | x |
| 7/29/2021 | 105 | 1820 | E KY 70 | OK | | x |
| 7/29/2021 | 105 | 289 | W Wilkinson | OK | | x |
| 7/29/2021 | 105 | 289 | W Wilkinson | OK | | x |
| 7/29/2021 | 105 | 581 | W Wilkinson | OK | | x |
| 7/29/2021 | 105 | 126 | Sharp Hollow | OK | | x |
| 7/29/2021 | 105 | 54 | Sharp Hollow | OK | | x |
| 7/29/2021 | 105 | 611 | S Wilkinson | OK | | x |
| 7/29/2021 | 105 | 54 | Sharp Hollow | OK | | x |
| 7/29/2021 | 105 | 616 | S Wilkinson | OK | | x |
| 7/29/2021 | 105 | 690 | S Wilkinson | OK | | x |
| 7/29/2021 | 105 | 713 | S Wilkinson | OK | | x |
| 7/29/2021 | 105 | 876 | S Wilkinson | OK | | x |
| 7/29/2021 | 105 | 83 | Believers Ln | OK | | x |
| 7/29/2021 | 105 | 67 | Believers Ln | OK | | x |
| 7/29/2021 | 105 | 1074 | S Wilkinson | OK | | x |
| 7/29/2021 | 105 | 1173 | S Wilkinson | OK | | x |
| 7/29/2021 | 105 | 1214 | S Wilkinson | OK | | x |
| 7/29/2021 | 105 | 1498 | S Wilkinson | OK | | x |
| 7/29/2021 | 105 | 1500 | S Wilkinson | OK | | x |
| 7/29/2021 | 105 | 1517 | S Wilkinson | OK | | x |
| 7/29/2021 | 105 | 1678 | S Wilkinson | OK | | x |
| 7/29/2021 | 105 | 98 | Hilltop Dr | OK | | x |
| 7/29/2021 | 105 | 1713 | KY 49 | OK | | x |

Leak Survey 2021



COMPANY: Liberty Utilities, Liberty KY

LEGEND: AC Atmospheric Corrosion

TECHNICIAN: Marty C. Bryan

NP- Needs Paints

PAGE: 12

| DATE | ROUTE | HOUSE# | ADDRESS | AC | POS | NEG |
|-----------|-------|--------|---------------|----|-----|-----|
| 7/29/2021 | 105 | 1705 | KY 49 | OK | | X |
| 7/29/2021 | 105 | 1714 | KY 49 | OK | | x |
| 7/29/2021 | 105 | 1870 | KY 49 | OK | | x |
| 7/29/2021 | 105 | 1830 | KY 49 | OK | | x |
| 7/29/2021 | 105 | 1976 | KY 49 | OK | | x |
| 7/29/2021 | 105 | 2059 | KY 49 | OK | | x |
| 7/29/2021 | 105 | 2063 | KY 49 | OK | | x |
| 7/29/2021 | 105 | 2411 | KY 49 | OK | | x |
| 7/29/2021 | 105 | 3265 | KY 49 | OK | | x |
| 7/29/2021 | 105 | 3804 | KY 49 | OK | | x |
| 7/29/2021 | 105 | 2804 | KY 49 | OK | | x |
| 7/29/2021 | 105 | 5727 | KY 49 | OK | | x |
| 7/29/2021 | 105 | 5717 | KY 49 | OK | | x |
| 7/29/2021 | 105 | 6290 | KY 49 | OK | | x |
| 7/29/2021 | 105 | 7009 | KY 49 | OK | | x |
| 7/29/2021 | 105 | 4399 | Caney Fork Ln | OK | | x |
| 7/29/2021 | 105 | 7293 | KY 49 | OK | | x |
| 7/29/2021 | 105 | 7274 | KY 49 | OK | | x |
| 7/29/2021 | 105 | 7806 | KY 49 | OK | | x |
| 7/29/2021 | 105 | 11669 | KY 1547 | OK | | x |
| 7/29/2021 | 105 | 11168 | KY 1547 | OK | | x |
| 7/29/2021 | 105 | 165 | Button Knob | OK | | x |
| 7/29/2021 | 105 | 10963 | KY 1547 | OK | | x |
| 7/29/2021 | 105 | 11138 | KY 1547 | OK | | x |
| 7/29/2021 | 105 | 10887 | KY 1547 | OK | | x |
| 7/29/2021 | 105 | 361 | Button Knob | OK | | x |
| 7/29/2021 | 105 | 653 | Button Knob | OK | | x |
| 7/29/2021 | 105 | 10520 | KY 1547 | OK | | x |
| 7/29/2021 | 105 | 10523 | KY 1547 | OK | | x |
| 7/29/2021 | 105 | 10167 | KY 1547 | OK | | x |
| 7/29/2021 | 105 | 10045 | KY 1547 | OK | | x |
| 7/29/2021 | 105 | 10006 | KY 1547 | OK | | x |
| 7/29/2021 | 105 | 9972k | KY 1547 | OK | | x |
| 7/29/2021 | 105 | 14 | Sheepskin Rd | OK | | x |
| 7/29/2021 | 105 | 9758 | KY 1547 | ok | | x |
| 7/29/2021 | 105 | 9745 | KY 1547 | OK | | x |
| 7/29/2021 | 105 | 9717 | KY 1547 | OK | | x |

Leak Survey 2021



COMPANY: Liberty Utilities, Liberty KY

TECHNICIAN: Marty C. Bryan

PAGE: 13

LEGEND: AC Atmospheric Corrosion

NP- Needs Paints

| DATE | ROUTE | HOUSE# | ADDRESS | AC | POS | NEG |
|-----------|-------|--------|---------------|----|-----|-----|
| 7/29/2021 | 105 | 9653 | KY 1547 | OK | | x |
| 7/29/2021 | 105 | 356 | Bartle Dr | OK | | x |
| 7/29/2021 | 105 | 1166 | Woodrum Ridge | OK | | x |
| 7/29/2021 | 105 | 1106 | Woodrum Ridge | OK | | x |
| 7/29/2021 | 105 | 1256 | Woodrum Ridge | OK | | x |
| 7/29/2021 | 105 | 139 | Viewpoint Dt | OK | | x |
| 7/29/2021 | 105 | 1494 | Woodrum Ridge | OK | | x |
| 7/29/2021 | 105 | 224 | Viewpoint Dt | OK | | x |
| 7/29/2021 | 105 | 1817 | Woodrum Ridge | OK | | x |