SME: 15030

SPECIFICATIONS AND CONTRACT DOCUMENTS BIG SANDY WATER DISTRICT, BOYD COUNTY, KENTUCKY

WATER TANK PAINTING & REPAIRS CONTRACT F-1

BID OPENING: THURSDAY JUNE 13, 2019, 12:00 NOON LOCAL TIME

ADDENDUM NO. 1

June 10, 2019

SPECIFICATIONS

Section 5 – Technical Specifications

The following questions have arisen, and our responses are attached as follows:

- 1. For the "misc. repairs" the Bid schedule says to "See Liquid Engineering Report...". Does the list of repairs include everything listed under "Reservoir Inspection Condition Supplemental?" On some of the repairs there are notes in handwritten are those the only repairs? Some are not marked up and wanted to verify. Those are my hand notes and are reflected in BID ITEMS.
- 2. On the bid schedule there are 5 gallons of pit filler listed "as needed for Rush Hill Tank". On page 09900-3 (Part 3 Execution 3.1 Field Inspection A.) it states "Examine all surfaces to be coated. All skip weld seams, roof lap plate seams not welded and gouges in plate steel shall be caulked after priming with Tnemec Series 63-1500 Filler and Surfacer." Is the 5 gallons on the bid schedule including the amount needed for the Field Inspection or is that just for the Rush Hill Tank? This is primarily for Rush Hill tank but will establish a unit price, if our Painting Inspector determines a need otherwise in other tanks.
- 3. Also, Pit Filler Tnemec 63-1500 has been discontinued and has been replaced with Tnemec 215. We agree! Use Tnemec 215.

Bidders for this Contract must acknowledge this Addendum No. 1 on the bid documents.

Joseph F. Sisler, P.E., P.L.S., President

Maggard Engineering, PLL