

COMMONWEALTH OF KENTUCKY  
BEFORE THE PUBLIC SERVICE COMMISSION

In the Matter of:

KENTUCKY FRONTIER GAS, LLC )  
)  
\_\_\_\_\_ )

ALLEGED VIOLATION OF UNDERGROUND )  
FACILITY DAMAGE PREVENTION ACT )

CASE NO.  
2019-00322

NOTICE OF FILING

Notice is given to all parties that the Gas Excavation Damage Report for Incident 31468 has been filed into the record for this proceeding.



Gwen R. Pinson  
Executive Director  
Public Service Commission  
P.O. Box 615  
Frankfort, KY 40602

DATED OCT 31 2019

cc: Parties of Record

# Gas Excavation Damage Report

## Kentucky Frontier Gas, LLC

Submitted 4/12/2019 Incident ID: 31468

[Set back to Edit](#)

[Staff Edit](#)

[Print](#)

Reported By:

Name:

Heather Music

Phone:

606-886-2431 ext 100

Email:

hmusic@kyfrontiergas.com

Gas Line Incident Occured:

Date:

3/20/2019

Time:

3:12 PM

Details:

Reported Date: 4/12/2019 12:06 PM

Incident Location Address:

Location:

37.44471 -82.80593

Address:

Curt Tuft Road

City:

Wayland

State:

KY

County:

Floyd

Zip:

41666

Confirm Code:

<b>Address</b>	<b>City</b>	<b>State</b>	
<b>ZipCode</b>	<b>County</b>	<b>State</b>	

Number of Customers out: 14

Locate Request Ticket No.: NA

**Excavator:** Contractor

Organization ID	Company	Status	Company Type
-----------------	---------	--------	--------------

Excavator Address:

First Name:

Elvis

Last Name:

Keathley

Organization ID:

Company:

T and N Concrete Construction

Phone:

606-791-4118

Email:

Address:

PO Box 411

City:

Betsy Layne

State:

KY

Zip:

41605

Confirm Code:

Y

Address	City	State
ZipCode	County	State

Excavation Damage: No notification made to the One Call Center

**Description of Incident** Contractor was digging a ditch for a storm drain and broke a 2" main line with a excavator.

Summary Information 4/12/2019

**Full details such as the cause** Contractor was digging a storm drain ditch and broke a 2" main PE with a excavator. KFG construction crew has leak controlled within 45 minutes by squeeze off which resulted in the loss of 14 customers gas service. The

crew replaced the area of the break with pretested 2" PE and EF couplings. Field technicians then went around and restored service to affected customers or left door tags if they were not home. T and N construction crew did not call 811 for this area but was aware that there were lines in the general area of the dig.

<b>Extent of the damage</b>	Minimal
<b>Cost of the damage</b>	\$350.00
<b>Steps taken to prevent re-occurrence</b>	Discussed the 811 dig laws with crew supervisor
<b>Amount billed to excavator</b>	\$0.00

CT Corporation System Register Agent  
306 W Main Street, Suite 512  
Frankfort, KENTUCKY 40601

\*Honorable John N Hughes  
Attorney at Law  
124 West Todd Street  
Frankfort, KENTUCKY 40601

\*Kentucky Frontier Gas, LLC  
4891 Independence Street, Suite 200  
Wheat Ridge, CO 80033

\*Kentucky Frontier Gas, LLC  
Kentucky Frontier Gas, LLC  
4891 Independence Street, Suite 200  
Wheat Ridge, CO 80033