

COMMONWEALTH OF KENTUCKY
BEFORE THE PUBLIC SERVICE COMMISSION

In the Matter of:

KENTUCKY FRONTIER GAS, LLC

ALLEGED VIOLATION OF UNDERGROUND
FACILITY DAMAGE PREVENTION ACT

)
)
)
)
)
)

CASE NO.
2019-00324

NOTICE OF FILING

Notice is given to all parties that the Gas Excavation Damage Report for Incident 31517 has been filed into the record for this proceeding.



Gwen R. Pinson
Executive Director
Public Service Commission
P.O. Box 615
Frankfort, KY 40602

DATED OCT 31 2019

cc: Parties of Record

Gas Excavation Damage Report

Kentucky Frontier Gas, LLC

Submitted 4/26/2019 Incident ID: 31517

[Set back to Edit](#)

[Staff Edit](#)

[Print](#)

Reported By:

Name:

Heather Music

Phone:

606-886-2431 ext 100

Email:

hmusic@kyfrontiergas.com

Gas Line Incident Occured:

Date:

3/28/2019

Time:

12:00 AM

Details:

Reported Date: 4/25/2019 2:00 PM

Incident Location Address:

Location:

37.76405 -83.08822

Address:

625 Elk Crk

City:

Salyersville

State:

KY

County:

Magoffin

Zip:

41465

Confirm Code:

Y

Address	City	State	
ZipCode	County	State	

Number of Customers out: 1

Locate Request Ticket No.: 1903180293

Excavator: Contractor

Organization ID	Company	Status	Company Type
-----------------	---------	--------	--------------

Excavator Address:

First Name:

Bret

Last Name:

Conley

Organization ID:

Company:

L&L Excavating

Phone:

606-349-1933

Email:

bconley1963@gmail.com

Address:

111 Brad Dr

City:

Salyersville

State:

KY

Zip:

41465

Confirm Code:

Y

Address	City	State
ZipCode	County	State

Excavation Damage: Failure to use hand tools where required

Description of Incident During a sewer drain installation, the contractor hit a 1" PE service line going to one customer.

Summary Information 4/26/2019

Full details such as the cause

Extent of the damage

Cost of the damage

Steps taken to prevent re-occurrence

Amount billed to excavator

During excavation for a ongoing job alongside this roadway, the contractor broke a 1" PE service line leading to one customer. When the field technician arrived, the pipe was bent over and he proceeded to squeeze it

off. The construction crew arrived and did the repair, pressure tested the line and restored service to the customer. The contractor then broke the same line while backfilling the ditch. KFG field technician was in the area and squeezed it off within 10 minutes of the call. KFG construction crew repaired the line, did a pressure test, then restored gas to the customer.

Both hits resulted in a complete break of the line, gas loss was minimal

\$600.00

KFG technicians remained in the area until the job was done and requested communication when the contractor would be doing any continuing area of work near the gas lines.

\$0.00

CT Corporation System Register Agent
306 W Main Street, Suite 512
Frankfort, KENTUCKY 40601

*Honorable John N Hughes
Attorney at Law
124 West Todd Street
Frankfort, KENTUCKY 40601

*Kentucky Frontier Gas, LLC
4891 Independence Street, Suite 200
Wheat Ridge, CO 80033

*Kentucky Frontier Gas, LLC
Kentucky Frontier Gas, LLC
4891 Independence Street, Suite 200
Wheat Ridge, CO 80033