

COMMONWEALTH OF KENTUCKY
BEFORE THE PUBLIC SERVICE COMMISSION

In the Matter of:

SCHROEDER CONSTRUCTION INCORPORATED)	
_____)	
ALLEGED VIOLATION OF UNDERGROUND)	CASE NO.
FACILITY DAMAGE PREVENTION ACT)	2021-00032
)	
)	

NOTICE OF FILING


Notice is given to all parties that the following materials have been filed into the record of this proceeding:

- The digital video recording of the evidentiary hearing conducted on April 23, 2021 in this proceeding;
- Certification of the accuracy and correctness of the digital video recording;
- All exhibits introduced at the evidentiary hearing conducted on April 23, 2021 in this proceeding;
- A written log listing, inter alia, the date and time of where each witness' testimony begins and ends on the digital video recording of the evidentiary hearing conducted on April 23, 2021.

A copy of this Notice, the certification of the digital video record, and hearing log have been served upon all persons listed at the end of this Notice. Parties desiring to view the digital video recording of the hearing may do so at <https://youtu.be/Pg4CSqbu52A>.

Parties wishing an annotated digital video recording may submit a written request by electronic mail to pscfilings@ky.gov. A minimal fee will be assessed for a copy of this recording.

Done at Frankfort, Kentucky, this 6th day of May 2021.



Linda C. Bridwell
Executive Director
Public Service Commission of Kentucky

COMMONWEALTH OF KENTUCKY
BEFORE THE PUBLIC SERVICE COMMISSION

In the Matter of:


SCHROEDER CONSTRUCTION)	
INCORPORATED –)	CASE NO.
ALLEGED VIOLATION OF UNDERGROUND)	2021-00032
FACILITY DAMAGE PREVENTION ACT)	

CERTIFICATION

I, Candace H. Sacre, hereby certify that:

1. The attached flash drive contains a digital recording of the Formal Hearing conducted in the above-styled proceeding on April 23, 2021. The Formal Hearing Log, Exhibit List, and Exhibits are included with the recording on April 23, 2021;
2. I am responsible for the preparation of the digital recording;
3. The digital recording accurately and correctly depicts the Formal Hearing of April 23, 2021; and
4. The Formal Hearing Log attached to this Certificate accurately and correctly states the events that occurred at the Formal Hearing of April 23, 2021, and the time at which each occurred.

Signed this 25th day of April, 2021.



Candace H. Sacre
Administrative Specialist III



Stephanie Schweighardt
Notary Public State at Large
Commission Expires: January 14, 2023
ID#: 614400



Session Report - Detail

2021-00032 23Apr2021

Schroeder Construction Incorporated (Schroeder)

Date:	Type:	Location:	Department:
4/23/2021	Public Hearing\Public Comments	Hearing Room 1	Hearing Room 1 (HR 1)

Witness: Eric Tout
 Judge: Kent Chandler; Talina Mathews; Michael Schmitt
 Clerk: Candace Sacre

Event Time	Log Event
10:29:04 AM	Session Started
10:29:09 AM	Chairman Schmitt Note: Sacre, Candace
	Back on record, 2021-00032, Schroeder Construction Incorporated, alleged violation KRS 367.4911(1)(a), reading. (Click on link for further comments.)
10:30:07 AM	Chairman Schmitt Note: Sacre, Candace
	Anyone present on behalf of Schroeder?
10:30:15 AM	Chairman Schmitt Note: Sacre, Candace
	Does not appear anyone present.
10:30:25 AM	Chairman Schmitt Note: Sacre, Candace
	Counsel for DOI identify herself and witness?
10:30:35 AM	Staff Atty Frederick PSC Note: Sacre, Candace
	Tina Frederick, call Eric Tout.
10:30:45 AM	Chairman Schmitt Note: Sacre, Candace
	Confirm Schroeder served?
10:31:03 AM	Staff Atty Frederick PSC Note: Sacre, Candace
	Yes, served Feb 4 2021, and filed.
10:31:11 AM	Chairman Schmitt Note: Sacre, Candace
	Witness sworn.
10:31:23 AM	Staff Atty Frederick PSC - witness Tout Note: Sacre, Candace
	Direct Examination. Name?
10:31:26 AM	Staff Atty Frederick PSC - witness Tout Note: Sacre, Candace
	Where employed?
10:31:29 AM	Staff Atty Frederick PSC - witness Tout Note: Sacre, Candace
	Job duties?
10:31:36 AM	Staff Atty Frederick PSC - witness Tout Note: Sacre, Candace
	Familiar with damage natural gas facility on Aug 21 2019 at 124 Ditto Lane, Vine Grove, Kentucky?
10:31:51 AM	Staff Atty Frederick PSC - witness Tout Note: Sacre, Candace
	Investigate?
10:31:57 AM	Staff Atty Frederick PSC - witness Tout Note: Sacre, Candace
	Investigation Report 31996, 39-page document, appear true copy of report?
10:32:39 AM	Staff Atty Frederick PSC - witness Tout Note: Sacre, Candace
	Describe contents of report?
10:33:26 AM	Staff Atty Frederick PSC - witness Tout Note: Sacre, Candace
	First involving Schroeder?
10:33:48 AM	Staff Atty Frederick PSC - witness Tout Note: Sacre, Candace
	How investigation resolved?
10:33:49 AM	DIVISION OF INSPECTION EXHIBIT 1 Note: Sacre, Candace
	INVESTIGATION REPORT 31996

	Note: Sacre, Candace	STAFF ATTY FREDERICK PSC - WITNESS TOUT
10:34:10 AM	Staff Atty Frederick PSC - witness	Tout
	Note: Sacre, Candace	Describe investigation and results?
10:34:26 AM	Staff Atty Frederick PSC - witness	Tout
	Note: Sacre, Candace	Facility contain natural gas?
10:34:35 AM	Staff Atty Frederick PSC - witness	Tout
	Note: Sacre, Candace	Pg 33 of report, how obtain document?
10:34:58 AM	Staff Atty Frederick PSC - witness	Tout
	Note: Sacre, Candace	What is document?
10:35:10 AM	Staff Atty Frederick PSC - witness	Tout
	Note: Sacre, Candace	Damage location incident date and address?
10:35:38 AM	Staff Atty Frederick PSC - witness	Tout
	Note: Sacre, Candace	Damage date on invoice?
10:35:45 AM	Staff Atty Frederick PSC - witness	Tout
	Note: Sacre, Candace	Does appear to be nvoice for damage investigated?
10:35:51 AM	Staff Atty Frederick PSC - witness	Tout
	Note: Sacre, Candace	Pg 39, how obtained?
10:36:10 AM	Staff Atty Frederick PSC - witness	Tout
	Note: Sacre, Candace	What is document?
10:36:32 AM	Staff Atty Frederick PSC - witness	Tout
	Note: Sacre, Candace	Appear be invoice number on invoice previously viewed?
10:36:39 AM	Staff Atty Frederick PSC - witness	Tout
	Note: Sacre, Candace	Demand letter?
10:36:44 AM	Staff Atty Frederick PSC - witness	Tout
	Note: Sacre, Candace	Result?
10:36:49 AM	Staff Atty Frederick PSC - witness	Tout
	Note: Sacre, Candace	Type of equipment?
10:37:33 AM	Staff Atty Frederick PSC - witness	Tout
	Note: Sacre, Candace	Locate ticket obtained by Schroeder?
10:38:05 AM	Staff Atty Frederick PSC - witness	Tout
	Note: Sacre, Candace	When obtained?
10:38:16 AM	Staff Atty Frederick PSC - witness	Tout
	Note: Sacre, Candace	Expired when?
10:38:23 AM	Staff Atty Frederick PSC - witness	Tout
	Note: Sacre, Candace	How many days expired?
10:38:29 AM	Staff Atty Frederick PSC - witness	Tout
	Note: Sacre, Candace	Ticket ends in 1318, when obtained?
10:38:46 AM	Staff Atty Frederick PSC	
	Note: Sacre, Candace	No further.
10:38:50 AM	Chairman Schmitt	
	Note: Sacre, Candace	Questions?
10:39:01 AM	Chairman Schmitt	
	Note: Sacre, Candace	No questions, but confirm Schroeder had one previous violation, attended training, paid reduced penalty?
10:39:24 AM	Chairman Schmitt	
	Note: Sacre, Candace	Second violation?
10:39:31 AM	Chairman Schmitt	
	Note: Sacre, Candace	Anyone present on behalf of Schroeder?
10:39:38 AM	Chairman Schmitt	
	Note: Sacre, Candace	Not appeared, so order drafted, fine/civil penalty \$2,000.
10:39:59 AM	Chairman Schmitt	
	Note: Sacre, Candace	Hearing adjourned.
10:40:31 AM	Session Ended	



Exhibit List Report

2021-00032 23Apr2021

Schroeder Construction
Incorporated (Schroeder)

Name:**Description:**

Division of Inspections Exhibit 1 Investigative Report 31996

PIPELINE DAMAGE INVESTIGATION REPORT

Investigation Information

KY PSC Investigator(s) Eric V. Tout Incident Date 8/21/2019 11:10:00 AM	Incident ID 31996 Report Submitted 9/11/2019 4:02:49 PM
--	--

OPERATOR INFORMATION

Operator Louisville Gas and Electric Company (LG&E) Phone (502) 364-8281 Incident Location 124 Ditto Ln Vine Grove, KY 40175 Hardin	Reported By Mike Jones Email Mike.Jones@lge-KU.com Locate Ticket Number 1906201196
---	---

EXCAVATOR INFORMATION

Name of Excavator Schroeder, Jacob Phone 270-312-7904 Excavator Address Schroeder Construction Incorporated 589 Franklin Ln Elizabethtown, KY 42701	Organization ID 0186382 Email Locate Ticket Number
---	---

INCIDENT

The Operator reports that the Excavator damaged a 2" gas service with no valid Locate Ticket (LT).
The Damage Report is include as Attachment 1.

Excavation Summary

Excavation Within 18" (Approximate Location)	Type Of Equipment Used	Cost of Damage (Per Operator)	Amount Billed (Excavator)
No valid LT	Not Specified	\$651.00	\$0.00

LT Summary

Ticket #	Valid	Initial Date	Expiration Date (21 calendar days from Initial date)	Incident Date	# of Days Expired	Within Scope of Excavation
1906201196	No	06/20/19	07/10/19	08/21/19	42	Yes
1906191318	No	06/19/19	07/09/19		43	Yes

The Locate Ticket(s) is/are include as Attachment 2.

INVESTIGATION

Note: A review of LT...1196 revealed that on 06/20/19 Schroeder Construction obtained the LT to install a water line, the LT expired on 07/10/19, the damage occurred on 08/21/19, indicating the LT expired 42 days before the Incident Date. (See Attachment 1 and LT Summary above)

On 05/04/20 the Operator, LG&E's Mike Jones provided a Dig Tix Facts-Based Investigation with photographs indicating Schroeder Construction caused the damage.

Dig Tix Facts-Based Investigation w/Photographs are include as Attachment 3.

On 05/06/20 Mr. Jones provided a LG&E Field Investigative Report.

- LG&E Field Investigative Report: Indicates that Schroeder Construction caused the damage, they were still on site, Jacob Schroeder was in charge and Schroeder Construction returned to the job to repair a water leak. The report indicates that LT 1906191318 was obtained, the facilities were not marked, the Excavator agreed the facilities were not marked, the flags were outside the dig area, the LT was expired and no new LT was submitted.

LG&E Field Investigative Report is include as Attachment 4.

Note: A review of LT...1318 revealed that on 06/19/19 Schroeder Construction obtained the LT to install a water line, the LT expired on 07/09/19, the damage occurred on 08/21/19, indicating the LT expired 43 days before the Incident Date. (See Attachment 1 and LT Summary above)

On 05/08/20 Mr. Jones provide photographs and invoice.

- 15 Photographs: Depicting the damage and vehicles at the incident location all with LG&E logos.
- Invoice: Indicating Schroeder Construction was billed \$651.13 for the damage and Mr. Jones stated Schroeder Construction paid for the damages in September 2019 but provided no receipt of payment.

Photographs and invoice are included as Attachment 5.

On 05/15/20 Mr. Schroder stated, via email (scijacob@gmail.com), that he was unable to find photographs of this incident. Mr. Schroder stated that he recalls the line was marked, it was broken one time prior and when it was repaired it veered off center approximately two feet. Mr. Schroder stated that they were digging off the marks resulting in the damage. Mr. Schroder was informed without a valid LT a Demand Letter will be sent assessing a penalty of \$2,000.00 and as of today's date Mr. Schroder has provided no valid LT.

Mr. Schroder's email is include as Attachment 6.

On 05/20/20 Mr. Jones provided a copy of a check from Schroder Construction to LG&E indicating Schroder Construction paid for the damage.

Check copy is include as Attachment 7.

VIOLATION

KRS 367.4911(1)(a) Each excavator, or person responsible for an excavation, planning excavation or demolition work shall, not less than two (2) full working days nor more than ten (10) full working days prior to commencing work, notify each affected operator of the excavator's intended work and work schedule. Contacting the applicable protection notification centers shall satisfy this requirement.

(8) The excavator shall contact the protection notification center to request remarking two (2) working days in advance of the expiration of each twenty-one (21) day period while excavation or demolition continues or if.

of Offences

(Including this incident)

Excavator	Last Offence Incident #	Last Offence Incident Date	Last Offence Resolved Date
2 nd	31761	6/19/2019	3/3/2020

Attachment 1

Gas Excavation Damage Report

Louisville Gas and Electric Company

Submitted 9/11/2019 Incident ID: 31996

[Set back to Edit](#) [Staff Edit](#)[Print \(PDFForm.aspx?Rpt=GasInvestigation&IG=31996\)](#)**Reported By:**

Name: Mike Jones
Phone: (502) 364-8281
Email: Mike.Jones@lge-KU.com

Gas Line Incident Occured:

Date: 8/21/2019
Time: 11:10 AM

Details:

Reported Date: 9/11/2019 4:02 PM

Incident Location Address:

Location:
Address: 124 Ditto Ln
City: Vine Grove
State: KY
County: Hardin
Zip: 40175
Confirm Code: Y

Number of Customers out: 1

Was gas or hazardous liquids contained in the underground facility?

Was gas or hazardous liquids released into the atmosphere?

3/2020

Locate Request Ticket No.: 1906201196

Excavator: Contractor

Excavator Address:

First Name: Jacob
Last Name: Schroeder
Organization ID:
Company: Schroeder Construction
Phone: 270-312-7904
Email:

Address: 589 Franklin Ln
 City: Elizabethtown
 State: KY
 Zip: 42701
 Confirm Code: Y

Excavation Damage: Failure to maintain marks

Description of Incident Excavator damaged 2" plastic service.

Summary Information

9/11/2019

Full details such as the cause	Excavator did not have a valid locate request. The request listed in association with this activity expired 5-6 weeks prior to incident, was from a previous activity, and did not include this dig area in the scope. Locates had been completed in June and in July after Miller Pipeline worked on the unlocatable facility but there was not an active request for this area.
Extent of the damage	Broken 2" service
Cost of the damage	\$651.00
Steps taken to prevent re-occurrence	Contractor not on site at time of my investigation. I left a Know Whats Below Brochure on one of their vacant company trucks on-site. On 8-26 I left a message with Jacob Schroeder explaining my findings. I let him know the ticket was 2 months old and markings appeared to have been accurate for that locate request. I told him I left a Know Whats Below Brochure on one of their vehicles. I asked him to call me with any further questions regarding this damage or KY Dig Law.
Amount billed to excavator	\$0.00

Attachment 2

NORMAL NOTICE

Ticket : 1906201196 Date: 06/20/2019 Time: 13:43 Oper: JGREEN Chan:000

State: KY Cnty: HARDIN City: VINE GROVE
Subdivision:

Address :

Street : VINE GROVE RD

Cross 1 : DITTO LN

Location: STARTING AT THE COUNTY LINE WHICH IS APPROX 180 FEET NORTH OF DITTO
LANE LOCATE THE NORTHSIDE OF VINE GROVE ROAD GOING SOUTH 2000 FEET TO INCLUDE
EXTENDING NORTH OFF THE ROAD FOR 150 FEET FORTHE DISTANCE OF THE LOCATE

:

Boundary: n 37.818579 s 37.814945 w -86.007508 e -86.000833

Work type : INSTALL WATER LINE

Done for : HARDIN COUNTY WATER DISTRICT 1

Start date: 06/24/2019 Time: 14:00 Hours notice: 96/48 Priority: NORM

Ug/Oh/Both: U Blasting: NO

Emergency: N

Duration : N/A

Depth: 20 FEET

Company : SCHROEDER CONSTRUCTION INC Type: CONT

Co addr : 589 FRANKLIN LN

City : ELIZABETHTOWN State: KY Zip: 42701

Caller : JACOB SCHROEDER Phone: (270)737-7717

Contact : JACOB SCHROEDER - CELL Phone:

Mobile : (270)312-7904

Fax : (866)892-1965

Email : SCIJACOB@GMAIL.COM

Submitted date: 06/20/2019 Time: 13:43

Members: 0002 0069 0072 0205 0227 0267 0358

NORMAL NOTICE

Ticket : 1906191318 Date: 06/19/2019 Time: 13:41 Oper: DFASEHUN Chan:000

State: KY Cnty: HARDIN City: VINE GROVE
Subdivision:

Address :

Street : VINE GROVE RD

Cross 1 : DITTO LN

Location: STARTING AT THE COUNTY LINE WHICH IS APPROX 180 FEET NORTH OF DITTO
LANE LOCATE BOTH SIDES OF VINE GROVE ROAD GOING SOUTH 2000 FEET

:

Boundary: n 37.818579 s 37.814945 w -86.007508 e -86.000833

Work type : INSTALL WATER LINE

Done for : HARDIN COUNTY WATER DISTRICT 1

Start date: 06/21/2019 Time: 14:00 Hours notice: 48/48 Priority: NORM

Ug/Oh/Both: U Blasting: NO

Emergency: N

Duration : N/A

Depth: 20 FEET

Company : SCHROEDER CONSTRUCTION INC Type: CONT

Co addr : 589 FRANKLIN LN

City : ELIZABETHTOWN State: KY Zip: 42701

Caller : JACOB SCHROEDER Phone: (270)737-7717

Contact : JACOB SCHROEDER - CELL Phone:

Mobile : (270)312-7904

Fax : (866)892-1965

Email : SCIJACOB@GMAIL.COM

Submitted date: 06/19/2019 Time: 13:41

Members: 0002 0069 0072 0205 0227 0267 0358

Attachment 3



Facts-Based Investigation

Internal Claim #: INC-20190821-001 Customer Claim #: _____

Site Investigator: Tracy Reesor Date Notified: 08/21/19 12:43:00

Notified By: (Name & #) Gas Operations Dispatch 5025891444

Damage Location: 124 Ditto Ln Vine Grove KY 40175

Date of damage: 08/21/19 11:15:00

Original Ticket #: 1906201196 Locator: ELM Locating

Due Date: 06/24/19 13:46:37 Date Located: 06/21/19 10:30:04

Photos taken before damage? N

Photos taken of damage site? Y

Type and size of damaged utility: Service/Drop 2

Depth: 18" to < 36" (0.5 to < 1m)

Description and extent of damage: Contractor damaged 2" pl customer service to a church digging on a ticket that is two months old. Some flags remain on the service but I could not determine if they were in line with the service. Per post-locate photo on 6/24 the service was accurately marked and locator, Howard Warren, told me he potholed, which is evident in that photo.

Equipment used: _____

Damaging Company Name: SCHROEDER CONSTRUCTION INC

Company Address: 589 FRANKLIN LN ELIZABETHTOWN, KY 42701

Telephone #: (270)737-7717 Contact name: JACOB SCHROEDER

Working for: HARDIN COUNTY WATER DISTRICT 1

Contractor assisting in the repair of damaged facility: LG&E

Personal Injury: N 3rd Party Property Damage: N Evacuations: N Other: Y

Explain: Service to church, no activity at the church today

Was Locate requested?: Y Facilities located?: Y

Locate accurate (Within tolerance zone)?: N If No, Distance markings off?: 18'

Were marks visible at time of damage: N

Were damaged facilities within scope of ticket?: N



Facts-Based Investigation

Name of util. Mgr/Rpr Tech on site: Luke Druen Tel. #: _____

Comments: _____

Witness: _____ Tel. #: _____

Comments: _____

Witness: _____ Tel. #: _____

Comments: _____

Investigator Findings: _____

Name the responsible party: Schroeder Construction

Give reasons why this party is responsible: Ticket is two months old.

Date of Investigation: 08/21/19 Total Investigation Time (Hours): _____

Site Investigator's Name: Tracy Reesor Phone: _____

Site Investigator's Signature: Tracy Reesor Date: 08/26/2019

(OFFICE USE ONLY)

DOCUMENTS ENCLOSED

Other: _____ Other: _____

Damage Status: Excavation Issue Cause Code: Excavator dug after valid ticket expired

Damage Claims Manager: _____



Facts-Based Investigation





Facts-Based Investigation



NOTE: Only 12 most recent photos shown. To view all 16 attachments, please view the ticket within DigTix.

Attachment 4

**LOUISVILLE GAS & ELECTRIC COMPANY
INCIDENT FIELD INVESTIGATION REPORT**

DAMAGE REPORT NO. 2019082314
PROJECT NO./TASK OMDIST47 / OF
RESP. CTR. 4470 GSMS NO. G000813456

DAMAGE TO LG&E FACILITIES

DATE OF INCIDENT Aug-21-2019 TIME 11:10 AM PM
ADDRESS/LOCATION OF DAMAGE 124 Birtto Lane One Grove Ky 40175
SUBDIVISION NAME _____
TIME DISPATCHED 11:20 AM PM TIME OF COMPLETION _____ AM/PM
WHO CAUSED DAMAGE? Schroeder Construction
(NAME OF CONTRACTOR, UTILITY, INDIVIDUAL, ETC.)
ADDRESS OF PARTY CAUSING DAMAGE 589 Franklin Lane Elizabethtown Ky 42701
(STREET) (CITY) (STATE) (ZIP CODE)
PHONE NUMBER OF PARTY CAUSING DAMAGE (703) 312-7904
WAS PARTY CAUSING DAMAGE STILL ON THE JOB? YES / NO
IF YES, WHO WAS IN CHARGE? Jacob Schroeder
IF NO HOW DID YOU OBTAIN NAME OF PARTY CAUSING DAMAGE? _____
WHAT WAS DAMAGED? (CIRCLE) - COMPANY MAIN - COMPANY SERVICE - CUSTOMER SERVICE
OTHER _____
WHAT TYPE OF WORK WAS BEING PERFORMED? laying water line
PARTY'S EXPLANATION FOR DAMAGE Returned to job to repair leak on main
WHAT REPAIRS WERE MADE? Repaired with PL service
ANY ADDITIONAL WORK TO BE PERFORMED? YES / NO
IF YES, BY WHOM? _____

POSSIBLE DAMAGE TO OTHERS

DATE OF INCIDENT _____ TIME _____ AM/PM
LOCATION OF INCIDENT _____
WHAT WAS DAMAGED? _____
WHAT WAS LG&E DOING AT THIS LOCATION? N/A
DESCRIPTION OF DAMAGE _____
OWNER OF PROPERTY _____ PHONE # _____
OWNER'S ADDRESS _____
(STREET) (CITY) (STATE) (ZIP CODE)
WHO WAS DAMAGE REPORTED TO? _____
WERE THERE ANY INJURIES? YES / NO IF YES, NAME OF INJURED PARTY _____
WERE THERE ANY WITNESSES TO INCIDENT? YES / NO
NAME _____ ADDRESS _____ PHONE _____

BUD INFORMATION

BUD NUMBER AND REQUESTING PARTY'S NAME 1906191318
WERE FACILITIES MARKED? YES / NO DID EXCAVATOR AGREE? YES / NO
IF YES, WERE FACILITIES PROPERLY MARKED? YES / NO DID EXCAVATOR AGREE? YES / NO
IF NO, HOW WERE THEY MISMARKED? (BE SPECIFIC) _____
Flags outside dig area, Bud expired on original ticket, new ticket not submitted
WAS LINE LOCATING CONTRACTOR ON THE JOB? YES / NO

Aug-21-2019
DATE OF REPORT

[Signature]
SIGNATURE OF EMPLOYEE

EMP. NO


APPROVED _____

DATE _____

While excavating to repair leak on watermain, contractor broke 10 cust. 1" PL-CTS service

CREW PERSONNEL	EMPLOYEE #	HOURS	TRUCK #	EQUIPMENT#	STALL #
DALE DOBSON	2730	1	8074		
LUKE DRUEN	28524	4	8102	Excavator - Trailer	
LUCAS BALANTINE	27226	4	4930	70-N 13-0	

PLEASE PROVIDE A SKETCH OF THE DAMAGE LOCATION INCLUDING ANY LOCATE MARKINGS



MATERIAL USED

	MATERIAL	IIN#		MATERIAL	IIN#
	FT PIPE PE 2406, 1/2 IN. IPS	1170051			
3-	FT PIPE PE 2406, 1 IN. CTS	1170078			
	FT PIPE PE 2406, 1 1/2" IPS	0434843			
	FT PIPE PE 2406, 2 IN IPS	0459060			
	FT PIPE PE 2406, 4 IN. IPS	0395160			
	FT PIPE PE 2406, 6 IN. IPS	0445394			
	EA 1/2" IPS PERMASERT COUPLING	0394943			
2	EA 1" CTS PERMASERT COUPLING	0394935			
	EA 1/2" IPS SOC WELD COUPLING	0394986			
	EA 1" CTS SOC WELD COUPLING	0427051			
	EA 1 1/2" IPS SOC WELD COUPLING	0427043			
	EA 2" IPS SOC WELD COUPLING	1166651			
	EA 2" IPS ELECTROFUSION CPL	0394894			
	EA 4" IPS ELECTROFUSION CPL	0394901			
	EA 6" IPS ELECTROFUSION CPL	0443586			
	EA 2" TAPE COAT	1172227			
	EA 4" TAPE COAT	1172235			
	EA CURB BOX WHITE LID	0418986			
	EA CUB BOX YELLOW LID	1164851			

Attachment 5




2018-09-11 12:46:04




2019-08-21 12:48:08



2819-86-21 123 517 47




2019-08-24 12:52:13



2019-06-24 14:02:37



2019-08-21 12:53:09



2019-08-21 12:53:17

Schroeder Construction Inc. Judith Schroeder
128 Bewley Hollow Rd
Elizabethtown, KENTUCKY 42701

Schroeder Construction Inc.
589 Franklin Ln
Elizabethtown, KENTUCKY 42701