# COMMONWEALTH OF KENTUCKY BEFORE THE PUBLIC SERVICE COMMISSION

In the Matter of:		
DRILLTEK LLC	)	CASE NO.
ALLEGED VIOLATION OF UNDERGROUND FACILITY DAMAGE PREVENTION ACT	) ) )	2022-00075

#### OPENING ORDER

DrillTek LLC (DrillTek) has been named as a party to an investigation before the Kentucky Public Service Commission (Commission) for allegedly violating the Kentucky Underground Facility Damage Prevention Act (Act).<sup>1</sup>

Pursuant to KRS 278.495(2), the Commission has jurisdiction to regulate the safety of natural gas facilities in Kentucky and to enforce minimum federal pipeline safety standards. Under the Act, the Commission has authority to investigate and assess civil penalties for any violation of the Act that results in excavation damage to an underground facility used to transport natural gas or hazardous liquid subject to federal pipeline safety laws, 49 U.S.C. § 60101, *et seq.* Any person who violates any provision of the Act is subject to assessment of a civil penalty in the amount of \$250 for the first offense, no more than \$1,000 for the second offense within one year, and no more than \$3,000 for the third and any subsequent offense. Additionally, any person whose violation of the Act results in damage to an underground facility containing any flammable, toxic, corrosive,

<sup>&</sup>lt;sup>1</sup> KRS 367.4901 through KRS 367.4917.

or hazardous material or results in the release of any flammable, toxic, corrosive, or hazardous material is subject to an additional penalty of up to \$1,000.

Following receipt of a report of excavation damage to its underground gas pipeline from an operator, Commission Staff (Staff) conducted an investigation and prepared an Incident Report, a copy of which is attached to this Order as an Appendix. In its Incident Report, Staff cites DrillTek for violation of the following provision of the Act:

KRS 367.4911(10) – When excavation or demolition is necessary within the approximate location of the underground facility, the excavator shall hand-dig or use nonintrusive means to avoid damage to the underground facility.

Based on its review of the Incident Report and being otherwise sufficiently advised, the Commission finds prima facie evidence that DrillTek violated the Underground Facility Damage Prevention Act. The Commission further finds that a formal investigation into the excavation damage incident should be conducted.

#### IT IS THEREFORE ORDERED that:

- 1. DrillTek shall submit to the Commission, via email sent to <a href="PSCED@ky.gov">PSCED@ky.gov</a> with the case number of this proceeding in the subject line of the message, a written response to the allegations contained in the Staff Incident Report within 20 days of receipt of this Order.
- 2. Any partnership, corporation, or business entity (including a limited liability company) must be represented by an attorney licensed to practice law in Kentucky, and such representation includes the filing of papers with and appearances at hearings before the Commission.
- 3. An individual may submit a response to the allegations contained in the Staff Incident Report without the representation of an attorney.

4. The Staff Incident Report 42792 in the Appendix to this Order is made a part of the record in this case.

5. Please note that notice of a hearing to be held in this matter will be mailed to DrillTek once proof of service is received by the Commission. Parties who fail to appear after service will be subject to entry of a default judgment against them.

[REMAINDER OF PAGE INTENTIONALLY LEFT BLANK]

PUBLIC SERVICE COMMISSION

Chairman

Vice Chairman

Commissioner

**ENTERED** 

MAR 24 2022 rcs

KENTUCKY PUBLIC SERVICE COMMISSION

ATTEST:

**Executive Director** 

## **APPENDIX**

# APPENDIX TO AN ORDER OF THE KENTUCKY PUBLIC SERVICE COMMISSION IN CASE NO. 2022-00075 DATED MAR 24 2022

9 PAGES TO FOLLOW

#### PIPELINE DAMAGE INVESTIGATION REPORT

**Investigation Information** 

KY PSC Investigator(s) John E. Gowins	Incident ID 42792
Incident Date 6/25/2020 1:43:00 PM	Report Submitted 7/14/2020 12:00:00 AM

#### **OPERATOR INFORMATION**

	0		
Operator	Louisville Gas and Electric Company	Reported By	Mike Jones
Phone	(502) 364-8281	Email	Mike.Jones@lge-KU.com
Incident Loca Intersection of KY 40004	<b>tion</b> Remington Dr. and Christie Ct. Bardstown,	Locate Ticke	et Number 2006091200
Nelson			

### **EXCAVATOR INFORMATION**

Name of Excavator	Sachleben, Roy	Organization ID	0899196
Phone	502-403-8340	Email	
Excavator Address DrillTek LLC 6915 Enterprise Dr Louisville, KY 40214		Locate Ticket Num	ber

# INCIDENT

Locate Ticket Summary						
Ticket # Valid Initial Date (21 calendar days from Initial date )		Incident Date	# of Days Expired	Within Scope of Excavation		
2006091200	Yes	6/9/20	6/30/20	6/25/20	N/A	Yes

Excavation Summary				
Excavation Within Tolerance Zone	Type Of Equipment Used	Cost of Damage	Amount Billed	
Zone	Useu	(Per Operator)	(Excavator)	
Yes	Mechanized	\$1767.00	\$0.00	

The operator reports that DRILLTEK was boring SE on Remington Dr on the west side of the road to install fiber optics for Star Construction. Drilltek did not have their own 811 locate request number. DRILLTEK started boring just north of Christine Ct on Remington Dr when they stated

that their boring head hit something solid so they pulled the bit back and almost immediately damaged the 2" MP PI G/M. The pothole that DRILLTEK made to spot the 2" PL Gm was not exactly in-line with their cross bore. The 2" PL G/M (main #438352) depth changed between where Drilltek potholed the line and where they actually crossed the PL G/M. Post damage photos show that Drilltek was not aware of the exact location of their boring head as well. The gas main was accurately marked by URG for Star Construction prior to DRILLTEK damaging the 2"PL G/M.

#### **INVESTIGATION**

This will be the company's fourth violation. Previous incidents are: 21064,31489, and 31913.

Previous contact was made with Jim Painter at 502.643.5422. This number was verified online.

Online address for corporate office is 2400 Ampere Dr., Louisville, KY 40299.

March 16, 2021

- Called 502.643.5422, went to v.m. for Jim with JP Construction, left a message.
- Received a call from Mr. Painter, no longer w/company, need to contact Josh Heberle 502.851.5977.

March 23, 2021

• Called Josh Heberle at 502.851.5977, left a v.m.

April 9, 2021

- Called 502.851.5977, left Mr. Heberle a second v.m.
- Received a v.m. from Mr. Heberle.

April 12, 2021

• Called Mr. Heberle back, left a v.m.

April 20, 2021

Called 502.851.5977, left a message that a demand letter was coming.

#### **VIOLATION**

KRS 367.4911 (10) When excavation or demolition is necessary within the approximate location of the underground facility, the excavator shall hand-dig or use nonintrusive means to avoid damage to the underground facility.

# Gas Excavation Damage Report

# Louisville Gas and Electric Company

Submitted 7/14/2020 Incident ID: 42792

Set back to Edit | Staff Edit |

Print (PDFForm.aspx?Rpt=GasInvestigation&IG=42792) Reported By: Name: Mike Jones (502) 364-8281 Phone: Email: Mike.Jones@lge-KU.com Gas Line Incident Occured: Date: 6/25/2020 Time: 1:43 PM Details: Reported Date: 7/14/2020 8:55 AM **Incident Location Address:** Location: Intersection of Remington Dr. and Christie Ct. Address: City: Bardstown State:  $\mathsf{K}\mathsf{Y}$ County: Nelson 40004 Zip: Confirm Code: Number of Customers out: Was gas or hazardous liquids contained in the underground facility? Was gas or hazardous liquids released into the 3/2020 atmosphere? Locate Request Ticket No.: 2006091200 Excavator: Contractor **Excavator Address:** Roy First Name: Last Name: Sachleben Organization ID: Company: Drill Tek Phone: 502-403-8340 Email:

Address: 6915 Enterprise Dr

City: Louisville

State: ΚY

Zip: 40214

Confirm Code:

**Excavation Damage:** No notification made to the One

Call Center

Description of Incident Excavator damaged gas main while working without valid locate request.

#### **Summary Information**

7/14/2020

DRILLTEK was boring SE on Remington Dr on the west side of the road to install fiber optics for Star Construction. Drilltek did not have their own 811 locate request number. DRILLTEK started boring just north of Christine Ct on Remington Dr when they stated that their boring head hit something solid so they pulled the bit back and almost immediately damaged the 2" MP PI

cause

Full details such as the G/M. The pothole that DRILLTEK made to spot the 2" PL Gm was not exactly in-line with their cross bore. The 2" PL G/M (main #438352) depth changed between where Drilltek potholed the line and where they actually crossed the PL G/M. Post damage photos show that Drilltek was not aware of the exact location of their boring head as well. The gas main was accurately marked by URG for Star Construction prior to DRILLTEK damaging the 2"PL G/M.

Extent of the damage Cost of the damage

2" plastic gas main

\$1,767.00

When I arrived Roy Sachleben (502-966-7690) with Star Construction was the only person on site, after LG&E gas crew dug up the damaged G/M a representative from DRILLTEK came and took pictures. Talked to Joshua with Drilltek and reiterated they MUST have their OWN ticket regardless of who they are doing the work for. Spoke with the Star Construction supervisor Steps taken to prevent and reiterated that all their subcontractors must have their OWN ticket. Steve Delap left messages for DRILLTEK general manager Jim Painter on 6/25/20

re-occurance

informing him that DRILLTEK should NOT do any excavation until they call in a valid 811 locate request and wait the required time for the ticket to be located. Steve Delap also stressed to the crew leader on site that all boring crews should only cross bore in the exact location the utility is potholed due to possible sudden depth changes.

Amount billed to

excavator

\$0.00

#### NORMAL NOTICE REMARK

Ticket: 2006091200 Date: 06/09/2020 Time: 12:41 Oper: ROY.SACHLEBEN.KY Chan:000 Old Tkt: 2005260834 Date: 05/26/2020 Time: 10:12 Oper: ROY.SACHLEBEN.KY Rev: 00A

State: KY Cnty: NELSON City: BARDSTOWN

Subdivision:

Address :

Street : REMINGTON DR Cross 1 : MAYWOOD AVE

Location: LOCATE 50 FOOT RADIUS OF THE INTERSECTION IN ALL DIRECTIONS. CONTINUE LOCATING WEST ALONG THE NORTH SIDE OF REMINGTON DR FOR APP 600 FT (STOPPING AT

BETHANY CT)

:

Boundary: n 37.791807 s 37.789814 w -85.432957 e -85.429274

Work type : PLACE DUCT AND HANDHOLDS

Done for : ATT

Start date: 06/11/2020 Time: 13:00 Hours notice: 48/48 Priority: NORM

Uq/Oh/Both: U Blasting: NO Emergency: N

Duration: N/A Depth: 10 FEET

Company : STAR CONSTRUCTION Type: CONT

Co addr : 6915 ENTERPRISE DRIVE

City : LOUISVILLE State: KY Zip: 40214
Caller : ROY SACHLEBEN Phone: (502)361-9772

Contact : ROY SACHLEBEN Phone:

Mobile : (502)966-7690 Fax : (502)361-9773

Email : ROY.SACHLEBEN@STAR-LLC.NET

Submitted date: 06/09/2020 Time: 12:41

Members: 0002 0139 0141





# Kentucky Secretary of State Michael G. Adams

# **DrillTek LLC**

File Annual Report File Statement of Change of Principal Office

File Statement of Change of registered Agent / Registered Address

Printable Forms Additional Services Certificates

#### **General Information**

**Organization Number** 0899196

**Company Type** KLC - Kentucky Limited Liability Company

StatusA - ActiveStandingG - Good

State KY

File Date 10/9/2014 10:03:00 AM Organization Date 10/9/2014 10:03:00 AM

Last Annual Report 2/18/2020

**Principal Office** 102 Wendover Ct.

Vine Grove, KY 40175

Managed By Managers

**Registered Agent** Joshua Michael Heberle

102 Wendover Ct. Vine Grove, KY 40175

#### **Current Officers**

**Manager** Joshua Michael Heberle

#### Individuals / Entities listed at time of formation

**Organizer** JOSHUA MICHAEL HEBERLE

# Images available online

Documents filed with the Office of the Secretary of State on September 15, 2004 or thereafter are available as scanned images or PDF documents. Documents filed prior to September 15, 2004 will become available as the images are created.

Annual Report	2/18/2020	1 page	PDF
Annual Report	7/10/2019	1 page	PDF
Annual Report	6/29/2018	1 page	PDF
Annual Report	9/13/2017	1 page	PDF
Annual Report	6/30/2016	1 page	PDF
Annual Report	8/17/2015	1 page	PDF
Articles of Organization	10/9/2014 10:03:	00 AM 1 page	PDF

#### **Assumed Names**

## **Activity History**

Filing	File Date	Effective Date	Org. Referenced
Appual report	2/18/2020	2/18/2020	
Annual report	12:18:47 AM	12:18:47 AM	
Appual report	7/10/2019 5:01:57	7/10/2019 5:01:57	
Annual report	PM	PM	
Appual report	6/29/2018	6/29/2018	
Annual report	12:48:22 PM	12:48:22 PM	
Appual report	9/13/2017 9:29:37	9/13/2017 9:29:37	
Annual report	AM	AM	
Appual report	6/30/2016 5:01:40	6/30/2016 5:01:40	
Annual report	PM	PM	
A	8/17/2015 3:22:15	8/17/2015 3:22:15	
Annual report	PM	PM	
Add	10/9/2014	10/9/2014	
Auu	10:03:00 AM	10:03:00 AM	

# **Microfilmed Images**

Contact	Site Map				
Privacy	Security	Disclaimer	Accessibility		

© Commonwealth of Kentucky All rights reserved.

Kentucky Unbridled Spirit

DrillTek LLC 102 Wendover Ct. Vine Grove, KENTUCKY 40175

DrillTek LLC 6915 Enterprise Dr. Louisville, KENTUCKY 40214