



a PPL company

Mr. Jeff DeRouen,
Executive Director
Kentucky Public Service Commission
211 Sower Boulevard
Frankfort, KY 40601

March 1, 2013

RE: *In the matter of Louisville Gas and Electric Company Alleged Failure
to Comply with KRS 278.495*
Case No. 2012-00239

Dear Mr. DeRouen:

Enclosed please find Louisville Gas and Electric Company's monthly status report pursuant to the February 5, 2013 Order in the above referenced proceeding.

Should you require anything further, please contact me at your convenience.

Sincerely,

Rick Lovekamp

Enclosures

RECEIVED
MAR 1 2013
PUBLIC SERVICE
COMMISSION

**Louisville Gas and Electric
Company**

State Regulation and Rates
220 W. Main Street
PO Box 32010
Louisville, Kentucky 40232
www.lge-ku.com

Rick Lovekamp
Manager, Regulatory Affairs
T 502-627-3780
F 502-627-3213
Rick.Lovekamp@lge-ku.com

KPSC Status Report

LG&E Project - Resetting Gas Regulator Facility Operating Pressures (As of February 26, 2013)

February – Work Completed

Resetting operating pressures of gas regulator facilities supplying LG&E's various single feed distribution systems was continued in February with the operating pressures reset on 91 separate facilities during February.

March – Work Planned

In March gas regulation technicians are scheduled to continue resetting operating pressures at gas regulator facilities supplying single feed distribution systems and starting the resetting of operating pressures on gas regulator facilities supplying LG&E's 35 psig gas distribution systems.

Project Status Summary

Provided below is a table providing the status of resetting operating pressures of LG&E's gas regulator facilities. Gas regulator facilities are broken down by pressure class and by the single feed distribution systems. The following data is provided for each pressure class: total customer count, total number of gas regulator facilities, number of gas regulator facilities that operating pressure has been reset, and percent complete for each pressure class. As of February 28th, 2013 the operating pressures have been reset on 41.3% of the gas regulator facilities.

Systems Pressure Class (psig)	No. Customers	Regulator Facilities		
		Total	Resets Completed	Percent Completed
60	53,120	15	15	100.0%
50	58,364	27	27	100.0%
35	149,103	97	0	0.0%
30	1,589	3	0	0.0%
20	14,684	10	0	0.0%
15	399	2	0	0.0%
Single feed ¹	12,058	175	94	53.7%
Totals	289,317	329	136	41.3%

¹ Single fed single gas regulator facilities supply a single distribution system and operate at various pressures