


## LICKING VALLEY-

## RURAL ELECTRIC COOPERATIVE CORPORATION

P. O. Box 605 • 271 Main Street West Liberty, KY 41472-0605 (606) 743-3179



KERRY K. HOWARD General Manager/CEO

January 04, 2013

RECEIVED

JAN 8 2013

PUBLIC SERVICE COMMISSION

Mr. Jeff Derouen
Executive Director
Kentucky Public Service Commission
211 Sower Boulevard
Post Office Box 615
Frankfort, Kentucky 40602-0615

RE: Case Number 2012-00372

Alleged Failure To Comply With 807 KAR 5:006

Dear Mr. Derouen:

In response to the Public Service Commission's Order in the above referenced Case dated December 14, 2012, please find enclosed Licking Valley Rural Electric Cooperative Corporation's 2012 System Line Inspection Update including dates each circuit was inspected including the inspector. Due to streamlining our line patrol methods, we should have no problem completing the entire system by June 01<sup>st</sup> or before, which you will be provided with a complete Line Inspection Update at that time.

A Cashier's Check for the assessed civil penalty of \$2,500 is also enclosed. If additional information is needed or required at this time, please let us know.

Sincerely,

Kerry K. Howard

General Manager/CEO

KKH:slv

**Enclosures** 

## LICKING VALLEY RURAL ELECTRIC COOPERATIVE CORPORATION PSC Case Number 2012-00372

**Line Inspection Update 2012 Substations and Circuits Completed** 

Substation / Circuit	Substation / Circuit		
Number	Location	Started Date	Completed Date
Substation # 1	ZACHARIAH	10/17/2012	11/06/2012
Substation # 1 / Circuit # 1	Lee County	10/31/2012	11/06/2012
Substation # 1 / Circuit # 2	Pine Ridge	10/17/2012	10/31/2012
Substation # 2	OAKDALE	11/09/2012	12/12/2012
Substation # 2 / Circuit # 1	Athol	11/09/2012	11/15/2012
Substation # 2 / Circuit # 2	Highland	11/14/2012	11/21/2012
Substation # 2 / Circuit # 3	Elkatawa	12/04/2012	12/06/2012
Substation # 2 / Circuit # 4	War Creek	12/11/2012	12/12/2012
Substation # 4	HOT MIX	08/29/2012	09/25/2012
Substation # 4 / Circuit # 1	Elkfork	09/21/2012	09/25/2012
Substation # 4 / Circuit # 2	Liberty Road	09/20/2012	09/20/2012
Substation #4 / Circuit #4	519	08/29/2012	09/14/2012
Substation # 4 / Circuit # 5	Wrigley	09/14/2012	09/20/2012
Substation # 6	SUBLETT	Not Completed	Not Completed
Substation # 6 / Circuit # 3	Gunlock	12/13/2012	12/19/2012
Substation # 6 / Circuit # 4	Gun Creek	12/28/2012	12/28/2012
Substation # 7	CAMPTON	06/26/2012	07/27/2012
Substation # 7 / Circuit # 1	Pine Ridge	07/24/2012	07/27/2012
Substation #7 / Circuit #2	Stillwater	07/11/2012	07/24/2012
Substation #7 / Circuit #3	Vortex	06/26/2012	07/03/2012
Substation # 8	INDEX	01/24/2012	06/07/2012
Substation #8 / Circuit #1	Caney	01/24/2012	06/07/2012
Substation #8 / Circuit #2	Index	02/17/2012	02/28/2012
Substation #8 / Circuit #3	Mize	02/28/2012	06/06/2012
Substation #8 / Circuit #4	Prison	06/07/2012	06/07/2012
Substation #8 / Circuit #5	School	02/17/2012	02/17/2012
Substation # 9	MAYTOWN	08/01/2012	08/29/2012
Substation #9 / Circuit #1	Ezel	08/15/2012	08/29/2012
Substation #9 / Circuit #2	Hazel Green	08/07/2012	08/10/2012
Substation #9 / Circuit #3	Pomeroyton	08/01/2012	08/07/2012
Substation # 10	CROCKETT	09/25/2012	10/16/2012
Substation # 10 / Circuit # 1	Lenox	10/10/2012	10/16/2012
Substation # 10 / Circuit # 2	Williams Creek	09/25/2012	10/02/2012
Substation # 10 / Circuit # 3	Crockett	10/02/2012	10/10/2012
Substation # 10 / Circuit # 4	School	10/10/2012	10/10/2012

Comments: At this time we have ten (10) Substations total and have completed seven (7) Substations.

We have thirty-seven (37) Circuits total and have completed twenty-eight (28) Circuits.

Inspected by: Arthur Patterson

LICKING VALLEY RECCLINE PATROL & LINE INSPECTION MONTH 07 Day 05 Year 2012 Inspected BY: Arthur Patterson

Substation (ampten	Prole	ð	Circuit 2000	Insulators	Guy	Ravels	Right of Way	Comments	Report	Confesso
	Good / Bad		Wire							4.000
	)						ナンプ			2.5.0
20,27-18		1						35.445-61.269.60	1	
44	٠,	7						Newtral thely have		11.00
20.36.9-2	)							Triplex 164.03 to 300		
20.47.33	)									
								1.54 A. 4. 9. 9.	)	5.5.72
20.25.4	257150	7						11. 4 0.4 69.15	7	21.01
76.29.1		7							)	2.1.2
	-					Free 58				75:37:07
	>							30.6 KMC1.	۱	
20.45.6b		7						Bad KUM Arrastal		7,9.11.2
20.55-1	7									
									<b></b>	4
							4.			τ
									-	<del>- 1</del> -
										<del></del>
										<b>Sep</b> Processed Pro
										T
									_	
			<del></del>							