

COMMONWEALTH OF KENTUCKY  
BEFORE THE PUBLIC SERVICE COMMISSION

In the Matter of:

WATSON FARMS LLC	)	
	)	
_____	)	CASE NO.
	)	2022-00017
ALLEGED VIOLATION OF UNDERGROUND	)	
FACILITY DAMAGE PREVENTION ACT	)	

OPENING ORDER

Watson Farms LLC (Watson Farms) has been named as a party to an investigation before the Kentucky Public Service Commission (Commission) for allegedly violating the Kentucky Underground Facility Damage Prevention Act (Act).<sup>1</sup>

Pursuant to KRS 278.495(2), the Commission has jurisdiction to regulate the safety of natural gas facilities in Kentucky and to enforce minimum federal pipeline safety standards. Under the Act, the Commission has authority to investigate and assess civil penalties for any violation of the Act that results in excavation damage to an underground facility used to transport natural gas or hazardous liquid subject to federal pipeline safety laws, 49 U.S.C. § 60101, *et seq.* Any person who violates any provision of the Act is subject to assessment of a civil penalty in the amount of \$250 for the first offense, no more than \$1,000 for the second offense within one year, and no more than \$3,000 for the third and any subsequent offense. Additionally, any person whose violation of the Act results in damage to an underground facility containing any flammable, toxic, corrosive,

---

<sup>1</sup> KRS 367.4901 through KRS 367.4917.

or hazardous material or results in the release of any flammable, toxic, corrosive, or hazardous material is subject to an additional penalty of up to \$1,000.

Following receipt of a report of excavation damage to its underground gas pipeline from an operator, Commission Staff (Staff) conducted an investigation and prepared an Incident Report, a copy of which is attached to this Order as an Appendix. In its Incident Report, Staff cites Watson Farms for violation of the following provision of the Act:

KRS 367.4911(1)(a) – Each excavator, or person responsible for an excavation, planning excavation or demolition work shall, not less than two (2) full working days nor more than ten (10) full working days prior to commencing work, notify each affected operator of the excavator's intended work and work schedule. Contacting the applicable protection notification centers shall satisfy this requirement.

Based on its review of the Incident Report and being otherwise sufficiently advised, the Commission finds *prima facie* evidence that Watson Farms violated the Underground Facility Damage Prevention Act. The Commission further finds that a formal investigation into the excavation damage incident should be conducted.

IT IS THEREFORE ORDERED that:

1. Watson Farms shall submit to the Commission, via email sent to [PSCED@ky.gov](mailto:PSCED@ky.gov) with the case number of this proceeding in the subject line of the message, a written response to the allegations contained in the Staff Incident Report within 20 days of receipt of this Order.

2. **Any partnership, corporation, or business entity (including a limited liability company) must be represented by an attorney licensed to practice law in Kentucky, and such representation includes the filing of papers with and appearances at hearings before the Commission.**

3. An individual may submit a response to the allegations contained in the Staff Incident Report without the representation of an attorney.

4. The Staff Incident Report 43112 in the Appendix to this Order is made a part of the record in this case.

**5. Please note that notice of a hearing to be held in this matter will be mailed to Watson Farms once proof of service is received by the Commission. Parties who fail to appear after service will be subject to entry of a default judgment against them.**

By the Commission

ENTERED  
FEB 23 2022 <sup>rCS</sup>  
KENTUCKY PUBLIC  
SERVICE COMMISSION

ATTEST:

  
Executive Director

Case No. 2022-00017

APPENDIX

APPENDIX TO AN ORDER OF THE KENTUCKY PUBLIC SERVICE  
COMMISSION IN CASE NO. 2022-00017 FEB 23 2022

TWENTY PAGES TO FOLLOW

# PIPELINE DAMAGE INVESTIGATION REPORT

## Investigation Information

**Investigator** Eric Tout **Incident ID** 43112 **Investigation** 8059  
**Incident Date** 10/13/2020 1:45:00 PM **Report Submitted** 11/4/2020

## Operator Information

**Operator** Atmos Energy Corporation **Reported By** Anthony Stallins  
**Phone** (270) 779-4849 **Email** anthony.stallins@atmosenergy.com

**Incident Location** 723 S Main St **Locate Ticket Number** N/A  
 Marion KY 42064  
 723 S. MAIN ST, Marion/Princeton  
**County** Crittenden

## Excavator Information

**Excavator** Jeff Watson **Organization ID** 0610656  
 Watson Farms, LLC  
**Phone** 270-625-2521 **Email**  
**Address** 444 Grooms Ln **Locate Ticket Number** N/A  
 Princeton KY 42445

## Damage Report (DR) Summary

Excavation Within 18" (Approximate Location)	Gas Or Hazardous Liquids		Type Of Equipment Used	Cost of Damage	Amount Billed
	Contained	Released			
No call to 811	Yes	Yes	Mechanized/Track Hoe	\$764.00	\$764.00

The Operator reports that the Excavator damaged a below ground riser, demolishing a home, with a track hoe, the roof and wall fell on the riser and the Excavator failed to contact the KY Contact Center (811).

**The DR is included as Attachment 1.**

## INVESTIGATION

On 10/12/21:

An attempt to contact the Excavator at 270-625-2521 resulted in speaking to an individual indicating that he was with Watson Farms and demolition occur on the incident date at the incident location. He stated that he had no idea if a call was made to 811 prior to the excavation and research was warranted. When inquiring how long it would take, he stated, "a month or so". Staff informed the individual that this was insufficient and a week would be sufficient and the conversation ended before inquires could be made as to whom was speaking. A call back to obtain a name resulted in no answer. *Note:* A reverse look up of 270-625-2521 revealed the number is assigned to Jason Emery.

A web search for Watson Farms provided a telephone number for Charles A Watson Farm / Watson Excavating, 270-365-2358 address 444 Grooms Ln., Princeton, KY 42445, wherein Charlie Watson was contacted. Mr. Watson stated that he was contracted for payment to demolish church property and the pastor indicated to him all utilities were shut off. Mr. Watson stated that no call was made to 811 and there was no need due to no excavation occurring. Staff informed Mr. Watson of KRS 367.4911(1) (a) and the need to call 811 prior to all demolitions. Mr. Watson stated that he has been doing demolition for 50+ yrs. (approximately 1,000 demolitions) and he has, "never heard of such", felt the state was over regulating and wanting money. Mr. Watson was informed of his options and never indicated which he would take, therefore Staff informed Mr. Watson a Demand Letter offering the Damage Prevention Course to receive the reduced penalty of \$250.00 would be forthcoming.

# PIPELINE DAMAGE INVESTIGATION REPORT

## VIOLATIONS

**KRS 367.4911(1)(a)** Each excavator, or person responsible for an excavation, planning excavation or demolition work shall, not less than two (2) full working days nor more than ten (10) full working days prior to commencing work, notify each affected operator of the excavator's intended work and work schedule. Contacting the applicable protection notification centers shall satisfy this requirement.

### # of Offences

(Including this incident)

<b>Excavator</b>	<b>Last Offence Incident #</b>	<b>Last Offence Incident Date</b>	<b>Revert to 1<sup>st</sup> Offence Date</b> (Last Offence Date +365 Days)
1 <sup>st</sup>	N/A	N/A	N/A

# Attachment 1

# Gas Excavation Damage Report

## Atmos Energy Corporation

Submitted 11/4/2020 Incident ID: 43112

[Set back to Edit](#)[Staff Edit](#)[Print \(PDFForm.aspx?Rpt=GasInvestigation&IG=43112\)](#)

### Reported By:

**Name:** Anthony Stallins  
**Phone:** (270) 779-4849  
**Email:** anthony.stallins@atmosenergy.com

### Gas Line Incident Occured:

**Date:** 10/13/2020  
**Time:** 1:45 PM

### Details:

**Reported Date:** 10/20/2020 8:12 AM

### Incident Location Address:

**Location:** 723 S. MAIN ST, MARION/PRINCETON  
**Address:** 723 S Main St  
**City:** Marion  
**State:** KY  
**County:** Crittenden  
**Zip:** 42064  
**Confirm Code:** Y

**Number of Customers out:** 0

**Was gas or hazardous liquids contained in the underground facility?**

**Was gas or hazardous liquids released into the atmosphere?**  \*

3/2020

**Locate Request Ticket No.:** N/A

**Excavator:** Contractor

### Excavator Address:

**First Name:** Jeff  
**Last Name:** Watson  
**Organization ID:** 0610656  
**Company:** WATSON FARMS, LLC  
**Phone:** 270-625-2521  
**Email:**

**Address:** 444 Grooms Ln  
**City:** Princeton  
**State:** KY  
**Zip:** 42445  
**Confirm Code:** Y  
**Excavation Damage:** No notification made to the One Call Center

**Description of Incident** Damaged riser below ground. No locate ticket. No customers off. No injuries.

Summary Information

---

11/4/2020

**Full details such as the cause** Watson Farms, demo house with a track hoe, damaged a riser below ground when the roof and wall fell over on the riser and broke the riser below ground. Watson Farms did not have a locate ticket for the demo of the house.  
**Extent of the damage** Service was retired.  
**Cost of the damage** \$764.00  
**Steps taken to prevent re-occurrence** Watson Farms advised of the need to call KY 811 before starting any demo or excavation project.  
**Amount billed to excavator** \$764.00

# SUPPLEMENTAL PIPELINE DAMAGE INVESTIGATION REPORT

## Investigation Information

**Investigator** Eric Tout **Incident ID** 43112 **Investigation** 8059  
**Incident Date** 10/13/2020 1:45:00 PM **Report Submitted** 11/4/2020

## Operator Information

**Operator** Atmos Energy Corporation **Reported By** Anthony Stallins  
**Phone** (270) 779-4849 **Email** anthony.stallins@atmosenergy.com

**Incident Location** 723 S Main St **Locate Ticket Number** N/A  
Marion KY 42064  
723 S. MAIN ST, Marion/Princeton  
**County** Crittenden

## Excavator Information

**Excavator** Jeff Watson **Organization ID** 0610656  
Watson Farms, LLC  
**Phone** 270-625-2521 **Email**  
**Address** 444 Grooms Ln **Locate Ticket Number** N/A  
Princeton KY 42445

## SUPPLEMENTAL INVESTIGATION

On 11/23/21 a No Attendance Remedial Measure/Training letter was sent to the Excavator indicating the reduced penalty of \$250.00 has been paid, but no representative has attended the Damage Prevention Course.

**The No Attendance Remedial Measure/Training letter is include as Attachment 2.**

On 01/10/22 the Operator, Atmos's Anthony Stallins, stated no photographs were available and provided the following documentation:

- Show Compliance/Construction Order Details: Indicating during demolition the roof hit the riser and broke it off underground.

**Amos's report is included as Attachment 3.**

On 01/12/22 Mr. Stallins, via email, stated the Excavator was invoiced \$764.13 for the damage, the Excavator paid \$350.00 and the reaming balance was turned over to collections.

**Mr. Stallins's email is included as Attachment 4.**

# Attachment 2



Andy Beshear  
Governor

Rebecca W. Goodman  
Secretary  
Energy and Environment Cabinet

Commonwealth of Kentucky  
**Public Service Commission**  
211 Sower Blvd.  
P.O. Box 615  
Frankfort, Kentucky 40602-0615  
Telephone: (502) 564-3940  
Fax: (502) 564-3460  
psc.ky.gov

Kent A. Chandler  
Chairman

Amy D. Cabbage  
Vice Chairman

Marianne Butler  
Commissioner

November 23, 2021

Charles A Watson  
Watson Farms, LLC  
444 Grooms Ln  
Princeton, KY 42445

Re: Violation of Kentucky Underground Facility Damage Prevention Act  
Incident Number: 43112

### No Attendance Remedial Measure/Training

Dear Mr. Watson:

Attached is the demand letter and investigation report for the above Incident. Our records indicate that a reduced penalty of \$250.00 has been paid, but no representative has attended the Remedial Measure/Training to receive this reduced penalty. Attendance is required for the penalty reduction to apply.

### REMEDIAL MEASURE/TRAINING

A representative of Watson Farms shall participate in a Damage Prevention training course. The Kentucky Public Service Commission will hold these classes online. Class dates have a limited capacity available on a first come-first served basis. To sign up for the class, go to <https://psc.ky.gov/classSignUp>. You will need your incident number, **43112** and this key **8059** to sign-up for one of the available training dates. **Please understand that this training will be required as a contingency for the reduced penalty amount.**

If we do not hear from you within 10 days from the date of this letter this matter will be referred to the Commission for an Administrative Hearing to be held at the Commission's offices.

Once a referral to the Commission is made, any partnership, corporation, or business entity (including a limited liability company) must be represented by an attorney licensed to practice law in Kentucky. Thank you for your prompt attention to this matter.

If you have any questions regarding this notice or if you find that these requirements have been met, please contact Ashley Rhodes, Division of Inspections at 502-782-2578.

Sincerely,

Nancy J. Vinsel  
General Counsel

# Attachment 3

## Tout, Eric V (PSC)

---

**From:** Stallins, Anthony A <Anthony.Stallins@atmosenergy.com>  
**Sent:** Monday, January 10, 2022 3:44 PM  
**To:** Tout, Eric V (PSC)  
**Cc:** Coleman, Mike D; House, Alex R; Tucker, Mariam L; Bledsoe, Jonathon T; Stanley, Bill E; Sanders, Jack; Stallins, Anthony A  
**Subject:** PSC ID: 43112; Leak Asset 709833; 723 S Main St., Marion, Watson Farms  
**Attachments:** 723 S Main St, Marion (Watson Farms).pdf

---

**\*\*CAUTION\*\* PDF attachments may contain links to malicious sites. Please contact the COT Service Desk [ServiceCorrespondence@ky.gov](mailto:ServiceCorrespondence@ky.gov) for any assistance.**

---

Good afternoon Eric,

The report for the damage at 723 S Main St, Marion.  
I could find no pictures of the damage, (contractor did not have a locate ticket).  
We are checking on whether the invoice was paid and will get back with you.

Thanks, Anthony

---

**From:** Tout, Eric V (PSC) <ericv.tout@ky.gov>  
**Sent:** Monday, January 10, 2022 4:46 AM  
**To:** Stallins, Anthony A <Anthony.Stallins@atmosenergy.com>  
**Subject:** [EXT] 43112, 10/13/2020, 723 S Main St., Marion, Watson Farms

**CAUTION: Don't be quick to click. This e-mail originated from outside of Atmos Energy. Do not click links or open attachments unless you recognize the sender and know the content is safe.**

Hello Anthony,

Please send reports, photos, invoices and payment info (copy of check) if paid on this one he has paid, but not attended the class gearing up for a hearing.

*Thanks,  
Eric V. Tout*

*Kentucky Public Services Commission  
Division of Inspections / Damage Prevention  
211 Sower Blvd., Frankfort, KY 40601  
Office: 502-782-2622  
Fax: 502-564-1582*

**Atmos Energy Corporation - Show Compliance/Construction Order Details**

Business: 3404  
40  
Ky - eAM

Asset:  
LEAK709833

Order# - Done - Status - Type:  
19033811 - 10/13/2020 - C - LKRP

Job Code:  
LKRP

Display Normal Display Debug ReSet

Run Time: 01/10/2022 14:20

**Job Details**

Status Complete      Office: PRINCETON      Done: 10/13/2020      Source: Qk  
Type:      SubRegion: Central Ky      District: Madisonville      In MA:  
Region: NORTHERN

**Schedule Data**

Start 10/14/2020      Base Date:      Interval: 0      Printed:      Print Date:  
Date:

**Asset**

Description LEAKS      Asset#: LEAK709833      Parent Asset#: LKS (2635)  
Group:      Asset: 723 S. S. MAIN ST. 5003400 MARION      Activity: LEAK REPAIR 1 2635  
Description:      Owing WA2635      Child Assets:      Status: InActive  
Department:

**Location**

Physical Information      GPS 37.32264      GPS Longitude: -88.08278      GPS Altitude: 0  
Latitude:      Address: 723 S. S. MAIN ST.      State: KY  
Town/City: 5003400 MARION      Time Zone:      DST:  
In/Outside INSIDE      Cross Street: Chapel Hill Rd.  
City Limits:      Other      Class Location: 3  
Location Information:      Map      Control Code:  
Number:      County: 21055 CRITTENDEN  
Property 90701 CRITTENDEN,MARION,MARION CTY & COM SCH  
Tax Code:      School      Certificate of Occupancy Required:  
District:      Land  
Description:      City  
Inspection Required:

**Location Additional Information**

WorkArea/SubArea: KYOWNB\_C      PipeLine #:      Read Sequence:  
Station Number:      Corrosion Section:  
System Number:      Printer Name: noprint      Project Number:  
Pipeline Balance      Code:      Task Number:  
Operation Area: KYMAD      Rate Division: 009      Facilities Classification: DIST  
Retirement Unit Non Unitized Retirement Unit      Zip:  
Name:  
Related SAP SO 100018335969  
Number:

**Leak Data**

Date 2020/10/13 13:45      Time Classified: 13:48:05      Leak Grade: 1  
Found:      Grade 2 Interval:      CGI Reading: 100  
Leak Grade 19038 Purdy, Dan      By:      Unit of Measure: % GAS  
Apparent SERVICE      Population Density: COMMERCIAL  
Location:      Ft To 5      Surface Type: DIRT  
Building:      Leak N/A      Leak Repaired: N      Leak Located (LKFD - 2): 2 - Below Ground  
Location:  
Comments: company demo house with no BUD call. Roof hit riser and broke it off under ground.

(LKRP) Leak Repair

Atmos Energy Corporation - Show Compliance/Construction Order Details

Business: 3404  
40  
Ky - eAM

Asset:  
LEAK709833

Order# - Done - Status - Type:  
19033811 - 10/13/2020 - C - LKRP

Job Code:  
LKRP

Display Normal Display Debug ReSet

Run Time: 01/10/2022 14:20

Completion Data

Leak Found (Yes/No): Reason Not Repaired: Initial Cause: EXCAVATION GROUP Ferc Acct: 8740 Condition of FAIR Wall Thickness: 0 External Corrosion: LOCALIZED Coating: Corrosion 0 Internal Corrosion: NA PS Reading: -1.56 Pit Depth (in): Coating Type: HOT COATED Test Pressure: 45 Test Duration: Repaired Date: 10/13/2020 Soap Test (Y/N/A): Y Info Chg Req: N Residual Gas: N Test Medium: OTHER Addit. Maint. Req: N Follow-Up: Welder ID: Welding Performed:

Installed	Length Units:	Task:	Size:	Type:
1				
Removed 1	Length Units:	Task:	Size: 0	Type:
Installed 2	Length Units:	Task:	Size:	Type:
Removed 2	Length Units:	Task:	Size: 0	Type:

Leak Located: Above\* Cause Code: 22 - Other Third Party Excavators Repair Method: 3 - Encapsulation Other Leak Cause: Fitting Type: Astm Code: Pipe Size: 3rd Party Y Pipe Mfg Code: Joint Type: Other Mfg: Damage: Compr Coupling Data: N

(LK3P) Leak 3rd Party Data

Completion Data Activity: LEAK REPAIR 1 2635 Asset Num: Task ID: Damage Date: 2020/10/13 Leak Area Sq. IN: 0 Locate ID #: N 3rd Party Name: Watson farms Locate Ticket #: 3rd Party Address: 444 Grooms Ln. Leak Duration Minutes: 0 Located By: Injuries or Deaths OnSite: 0 Damage to Property: Y Date Located2: Locate Mark within State Law: N Repair Total: 3rd Party Phone #: 2706252521 Reason Damage Occurred: NOLOCATEREQ Type of 3rd Party Work: SITEDEVEL Date Locate Requested: Locate Priority: Ferc Acct: 8740 Equipment Causing Damage: BACKHOE Date Located: Date Locate Requested: 2018/04/12 3rd Party Contact: Jeff Watson Ins Agent: Agent Phone: Company: Type CONTRACTOR Damage Where: City: Princeton Excavator: Facility DISTRIBUTION Num Cust Affected: 0 State: KY

Atmos Energy Corporation - Show Compliance/Construction Order Details

Business: 3404  
40  
Ky - eAM

Asset:  
LEAK709833

Order# - Done - Status - Type:  
19033811 - 10/13/2020 - C - LKRP

Job Code:  
LKRP

Display Normal Display Debug ReSet

Run Time: 01/10/2022 14:20

Involved:	Billed:	Zip: 42445
Time Located:	Damage By: THIRDPY	Title 16: N
Damage Location:	FAC Release Plan: Y	One Call Code:
FAC Material BODYOFPIPE	FAC Locate Code: INTRA	FAC Pipe Diameter: 0
Damage: FAC 911 N	Excavator Ticket:	Excavator Notify Oper: N
Damage Call:	Excavator Ticket:	Excavator Notify Oper: N
Excavator Call: N	Pipeline Material: COATSTEEL	Pipeline Year:
Pipeline IS: ACTIVE	Fire Comments:	Type of Injury:
Prod Trans Code:	Mark 2nd Call Rsn:	Mark 2nd Call Oth:
Mark :: Positive Response:	Mark 2nd Call Date:	Mark 2nd Call Resp:
Mark 2nd Call Ticket:	Mark Why and Rsn:	Mark Why Other:
Mark :: Positive Response:	Locator Other Explain:	
Mark 0 Variance Inches:	Incident Address: 723 S. S. Main St.	Incident Time: 1:3PM
SubDivision:	Latitude: 37.32264	Longitude: -88.08278
Lat Long DECIMAL		
LkUp:		

(LK3P) RRC Leak 3rd Party

<b>Data Completion Data</b>		
Date of 2020/10/13	Excavator Name: Watson farms	Excavator Address: 444 Grooms Ln.
Damage:	Excavator State: KY	Excavator Zip: 42445
Excavator City: Princeton	Excavator Phone: 2706252521	Excavator Fax:
Excavator Contact Name: Jeff Watson	Excavator Type Code: CONTRACTOR	Excavation Type: BACKHOE
Excavator EMail:	Excavator Depth Ft: 0	Excavator Depth In: 0
Work SITEDLEVEL	Incident NO:	Country: US
Performed Code:	City: marion	Address: 723S. S. Main St.
Was Called: N	RightOfWay Type: PRVEAS	Fac Damaged Code:
State: KY	Fac Damaged Depth Ft: 1	Fac Damaged Depth In: 0
Intersection: Chapel Hill Rd.	OneCall Member: Y	Locate Request: N
Fac Affected Code: DISTRIBUTION	OneCall Ticket#:	OneCall Ctr Notified Date: 2018/04/12
Joint N	Locator Name:	Fac Marks Visible: N
Trench:	Marked Variance Ft: 0	Marked on Time:
OneCall Center Code:	Marked Loc. Meth Oth:	Marked by Paint:
Locate Org Code:	Marked by Other: N	Marked by Other Comnt:
Fac Marks Correct:	Marked Spec Instruction:	Marked Using Maps:
Marked Locate Method:	Marked Loc Met with Exc:	Marked Reps OnSite:
Marked by Flags:	Marked Procedure Used:	Marked Positive Response:
Marked By White Lining:	Excavator Down Time: 1	Excavator Down Cost: -1
Marked 48 HR Notice:		
Marked Second Call:		
Excavator Y Down:		

Atmos Energy Corporation - Show Compliance/Construction Order Details

Business: 3404  
40  
Ky - eAM

Asset: LEAK709833

Order# - Done - Status - Type:  
19033811 - 10/13/2020 - C - LKRP

Job Code:  
LKRP

Display Normal Display Debug ReSet

Run Time: 01/10/2022 14:20

Was Fac Damaged: Y	Service Interruption: N	Outage Hours: 0
Customers Affected: 0	Restoral Cost: 0	Number People Injured: 0
Number Fatalities: 0	Impact Fire Occurr: N	Impact Evac: N
Impact Evac No People: 0	Impact Evac Comnt:	Impact Media Covrg: N
Impact Media Covrg Comnt:	Impact Street: N	Impact Street Comnt:
Impact Explosion: N	Impact Explosion Comnt:	Impact Other: N
Impact Other Explanation: Damage	Impact No addl:	Damage Cause Code: NOLOCATEREQ
Other Desc:		

Comments & Labor

Comments: company demo house with no bud call, roof fell on riser and broke it under ground.  
Tech: 27619 Copeland, Shawn

Travel: .03

OnSite: 10.15

Data Entry Stats

Order# 19033811

Asset Created:	10/13/2020	By: 8247	EAMADMIN
Order Created:	10/13/2020	By: 8247	EAMADMIN
Q. Results Entered:	10/13/2020	By: 8247	EAMADMIN

ET .117 Minutes RECORD Count

0

# Attachment 4

## Tout, Eric V (PSC)

---

**From:** Stallins, Anthony A <Anthony.Stallins@atmosenergy.com>  
**Sent:** Wednesday, January 12, 2022 1:39 PM  
**To:** Tout, Eric V (PSC)  
**Cc:** Kirkham, Nicole A; Whitney, Lisa S; Coleman, Mike D; House, Alex R; Tucker, Mariam L; Owen, Tim D; Stallins, Anthony A; Sanders, Jack  
**Subject:** FW: PSC ID: 43112; Leak Asset 709833; 723 S Main St., Marion, Watson Farms

Good afternoon Eric,

Watson Farms was invoiced \$764.13 for the damage. The bill was not paid, written off and turned over to collections. It appears after Watson Farms was contacted by the collection agency, they paid \$350.00.

Thanks, Anthony

---

**From:** Kirkham, Nicole A <Nicole.Kirkham@atmosenergy.com>  
**Sent:** Monday, January 10, 2022 4:12 PM  
**To:** Stallins, Anthony A <Anthony.Stallins@atmosenergy.com>  
**Cc:** Whitney, Lisa S <Lisa.Whitney@atmosenergy.com>  
**Subject:** Re: PSC ID: 43112; Leak Asset 709833; 723 S Main St., Marion, Watson Farms

Invoice No	Inv Amt	Inv.Status	Cncl Reas	Claim Re...	Outst Bal	Claim Disp
299503	764.13	Closed			.00	NO

Payment History

Ta...	Invoice No	Payor	Doc No	Doc A...	Doc Date	Inv Act Date	Invoice Activity	Inv Act Reason
4	299503		304895	764.13	03/08/2021	03/08/2021	CREDIT MEMO	PA_WRITE_OFF
3	299503				01/29/2021	01/29/2021	COLECTION AGENCY UP...	PFC
2	299503				12/28/2020	12/28/2020	50 DAY LETTER UPDATE	
1	299503				12/07/2020	12/07/2020	30 DAY LETTER UPDATE	

Invoice History

Invoice No	Inv Amt	Inv.Status	Cncl Reas	Claim Re...	Outst Bal	Claim Disp
305254	350.00	Closed			.00	NO

Payment History

Ta...	Invoice No	Payor	Doc No	Doc A...	Doc Date	Inv Act Date	Inv Act	Inv Act Re
1	305254	WATSON FARMS	JC031821M3	350	03/19/2021	03/18/2021	RECEIPT	

Looks like the larger amount was written off.

Thanks

**Nicole Kirkham**

Operations Assistant  
3510 Coleman Rd  
Paducah, KY 42001  
(270)702-6591



---

**From:** Stallins, Anthony A <[Anthony.Stallins@atmosenergy.com](mailto:Anthony.Stallins@atmosenergy.com)>  
**Sent:** Monday, January 10, 2022 2:15 PM  
**To:** Kirkham, Nicole A <[Nicole.Kirkham@atmosenergy.com](mailto:Nicole.Kirkham@atmosenergy.com)>  
**Cc:** Coleman, Mike D <[Michael.Coleman@atmosenergy.com](mailto:Michael.Coleman@atmosenergy.com)>; House, Alex R <[Alex.House@atmosenergy.com](mailto:Alex.House@atmosenergy.com)>; Bledsoe, Jonathon T <[Jonathon.Bledsoe@atmosenergy.com](mailto:Jonathon.Bledsoe@atmosenergy.com)>; Stanley, Bill E <[Bill.Stanley@atmosenergy.com](mailto:Bill.Stanley@atmosenergy.com)>; Stallins, Anthony A <[Anthony.Stallins@atmosenergy.com](mailto:Anthony.Stallins@atmosenergy.com)>; Tucker, Mariam L <[Mariam.Tucker@atmosenergy.com](mailto:Mariam.Tucker@atmosenergy.com)>  
**Subject:** PSC ID: 43112; Leak Asset 709833; 723 S Main St., Marion, Watson Farms

Good afternoon Nicole,

Would you please check on this invoice as to whether it was paid or not.  
Looks like we had 2 invoices, the original was \$764.13. The second one was for \$350.00.  
Maybe Mike or Alex can remember the reason of the two.

Thanks, Anthony

---

**From:** Tout, Eric V (PSC) <[ericv.tout@ky.gov](mailto:ericv.tout@ky.gov)>  
**Sent:** Monday, January 10, 2022 4:46 AM  
**To:** Stallins, Anthony A <[Anthony.Stallins@atmosenergy.com](mailto:Anthony.Stallins@atmosenergy.com)>  
**Subject:** [EXT] 43112, 10/13/2020, 723 S Main St., Marion, Watson Farms

**CAUTION: Don't be quick to click. This e-mail originated from outside of Atmos Energy. Do not click links or open attachments unless you recognize the sender and know the content is safe.**

Hello Anthony,

Please send reports, photos, invoices and payment info (copy of check) if paid on this one he has paid, but not attended the class gearing up for a hearing.

*Thanks,  
Eric V. Tout  
Kentucky Public Services Commission  
Division of Inspections / Damage Prevention  
211 Sower Blvd., Frankfort, KY 40601  
Office: 502-782-2622  
Fax: 502-564-1582*

Watson Farms LLC  
444 Grooms Ln  
Princeton, KENTUCKY 42445