

COMMONWEALTH OF KENTUCKY
BEFORE THE PUBLIC SERVICE COMMISSION

In the Matter of:

HOSLER EXCAVATING, INC)	
)	
_____)	CASE NO.
)	2022-00171
ALLEGED VIOLATION OF UNDERGROUND)	
FACILITY DAMAGE PREVENTION ACT)	

INITIATING ORDER FOR ALLEGED 811 VIOLATION OF THE KENTUCKY
UNDERGROUND FACILITY DAMAGE PREVENTION ACT

Hosler Excavating, Inc (Hosler Excavating) has been named as a party to an investigation before the Kentucky Public Service Commission (Commission) for allegedly violating the Kentucky Underground Facility Damage Prevention Act (Act).¹ A hearing in this case shall take place on July 29, 2022.

Pursuant to KRS 278.495(2), the Commission has jurisdiction to regulate the safety of natural gas facilities in Kentucky and to enforce minimum federal pipeline safety standards. Under the Act, the Commission has authority to investigate and assess civil penalties for any violation of the Act that results in excavation damage to an underground facility used to transport natural gas or hazardous liquid subject to federal pipeline safety laws, 49 U.S.C. § 60101, *et seq.* Any person who violates any provision of the Act is subject to assessment of a civil penalty in the amount of \$250 for the first offense, no more than \$1,000 for the second offense within one year, and no more than \$3,000 for the third and any subsequent offense. Additionally, any person whose violation of the Act

¹ KRS 367.4901 through KRS 367.4917.

results in damage to an underground facility containing any flammable, toxic, corrosive, or hazardous material or results in the release of any flammable, toxic, corrosive, or hazardous material is subject to an additional penalty of up to \$1,000.

Following receipt of a report of excavation damage to its underground gas pipeline from an operator, Commission Staff (Staff) conducted an investigation and prepared an Incident Report, a copy of which is attached to this Order as Appendix A. In its Incident Report, Staff cites Hosler Excavating for violation of the following provision of the Act:

KRS 367.4911(1)(a) – Each excavator, or person responsible for an excavation, planning excavation or demolition work shall, not less than two (2) full working days nor more than ten (10) full working days prior to commencing work, notify each affected operator of the excavator's intended work and work schedule. Contacting the applicable protection notification centers shall satisfy this requirement.

Based on its review of the Incident Report and being otherwise sufficiently advised, the Commission finds prima facie evidence that Hosler Excavating violated the Underground Facility Damage Prevention Act. The Commission further finds that a formal investigation into the excavation damage incident shall be conducted.

IT IS THEREFORE ORDERED that:

1. Hosler Excavating shall submit to the Commission, via email sent to PSCED@ky.gov with the case number of this proceeding in the subject line of the message, a written response to the allegations contained in the Staff Incident Report within 20 days of receipt of this Order.

2. Hosler Excavating shall appear on July 29, 2022, at 9 a.m. Eastern Daylight Time, in the Richard Raff Hearing Room of the Commission's offices at 211 Sower Boulevard in Frankfort, Kentucky, for the purpose of presenting evidence concerning the alleged violation of the Underground Facility Damage Prevention Act.


3. The July 29, 2022 hearing shall be conducted via video conferencing.
4. Hosler Excavating shall attend the hearing by using the following link: <https://global.gotomeeting.com/join/308551245>; information and instructions are attached to this Order as Appendix B.
5. Hosler Excavating shall notify the Commission at least ten days prior to the hearing if Hosler Excavating is unable to appear by video conferencing and will therefore appear in person.
6. **Any partnership, corporation, or business entity (including a limited liability company) must be represented by an attorney licensed to practice law in Kentucky, and such representation includes the filing of papers with and appearances at hearings before the Commission.**
7. An individual may submit a response to the allegations contained in the Staff Incident Report without the representation of an attorney.
8. The Staff Incident Report 43465, attached to this Order as Appendix A, is made a part of the record in this case.
9. The July 29, 2022 hearing shall be recorded by video only.
10. **Please note that notice of a hearing to be held in this matter will be mailed to Hosler Excavating once proof of service is received by the Commission. Parties who fail to appear after service will be subject to entry of a default judgment against them.**

PUBLIC SERVICE COMMISSION


Chairman

Vice Chairman

Commissioner



ATTEST:


Executive Director

APPENDIX A

APPENDIX TO AN ORDER OF THE KENTUCKY PUBLIC SERVICE
COMMISSION IN CASE NO. 2022-00171 DATED JUN 17 2022

FIFTY-ONE PAGES TO FOLLOW

PIPELINE DAMAGE INVESTIGATION REPORT

Investigation Information

Investigator Eric Tout **Incident ID** 43465 **Investigation** 8424
Incident Date 3/4/2021 10:17:00 AM **Report Submitted** 3/29/2021

Operator Information

Operator Louisville Gas and Electric Company
Phone (502) 364-8281 **Reported By** Mike Jones
Email Mike.Jones@lge-KU.com

Incident Location 1224 Ava Pearls Way
Louisville KY 40245 **Locate Ticket Number** NA

County Jefferson

Excavator Information

Excavator Randy Hosler **Organization ID** 0439475
Hosler Excavating, Inc.
Phone 502-639-9268 **Email**
Address 8201 Todds Point Rd **Locate Ticket Number** NA
Crestwood KY 40014

Damage Report (DR) Summary

Excavation Within 18" (Tolerance Zone)	Gas Or Hazardous Liquids		Type Of Equipment Used	Cost of Damage	Amount Billed
	Contained	Released			
No call to 811	Yes	Yes	Mechanized/Bulldozer	\$503.00	\$0.00

The Operator reports the Excavator damaged a one-inch gas service with a bulldozer while grading a lot and failed to contact the KY Contact Center (811).

The DR is included as Attachment 1.

INVESTIGATION

On 02/15/22 the Excavator, Hosler Excavating's Randy Hosler, stated that no call was made to 811. Mr. Hosler was receptive to attending the Damage Prevention Course and paying the reduced penalty of \$250.00.

VIOLATIONS¹

KRS 367.4911(1)(a) Each excavator, or person responsible for an excavation, planning excavation or demolition work shall, not less than two (2) full working days nor more than ten (10) full working days prior to commencing work, notify each affected operator of the excavator's intended work and work schedule. Contacting the applicable protection notification centers shall satisfy this requirement.

¹ A revision of the Underground Facility Damage Prevention Act took effect on January 1, 2022. All incidents of damage dated prior to January 1, 2022 will be reviewed under the former version of the Act

PIPELINE DAMAGE INVESTIGATION REPORT

of Offences Within 365 Days

(Including this incident)

Excavator	Last Offence Incident #	Last Offence Incident Date	Revert to 1st Offence Date (Last Offence Date +366 Days)
1 st	N/A	N/A	N/A

Attachment 1

Gas Excavation Damage Report

Louisville Gas and Electric Company

Submitted 3/29/2021 Incident ID: 43465

[Set back to Edit](#)[Staff Edit](#)[Print \(PDFForm.aspx?Rpt=GasInvestigation&IG=43465\)](#)

Reported By:

Name: Mike Jones
Phone: (502) 364-8281
Email: Mike.Jones@lge-KU.com

Gas Line Incident Occured:

Date: 3/4/2021
Time: 10:17 AM

Details:

Reported Date: 3/29/2021 1:43 PM

Incident Location Address:

Location:

Address: 1224 Ava Pearls Way
City: Louisville
State: KY
County: Jefferson
Zip: 40245
Confirm Code: Y

Number of Customers out: 1

Was gas or hazardous liquids contained in the underground facility?

Was gas or hazardous liquids released into the atmosphere? *

Locate Request Ticket No.: NA

Excavator: Contractor

Excavator Address:

First Name: Randy
Last Name: Hosler
Organization ID:
Company: Hosler Excavating
Phone: 502-639-9268
Email:

Address: 8205 Todds Point Rd
City: Crestwood
State: KY
Zip: 40014
Confirm Code: Y
Excavation Damage: No notification made to the One Call Center

Description of Incident ?Excavator grading without locate requests damaged service.

Summary Information

3/29/2021

Full details such as the cause Hosler Excavating was contracted by the builder to grade the property at the newly built home, which is currently under construction at 1224 Ava Pearls Way. Hosler Excavating was operating a large bulldozer to grade the aforementioned lot when they damaged a 1" plastic gas service. The line (#428281) was damaged on the customer side of the gas service, at a approximate depth of 12". The depth was difficult to determine because Hosler had already graded large portions of the lot and the land itself slopes from left to right, then drops off a large embankment on the right hand side of the lot. NO BUD ticket. **locate paint marks seen in the damage photos were painted for the LG&E locate request, called into 811 after the gas line was damaged.

Extent of the damage Broken 1" plastic service

Cost of the damage \$503.00

Steps taken to prevent re-occurrence Randy Hosler, on-site contact for excavator involved, stated he was unaware he needed to call in 811 tickets when doing grading work. Mr. Hosler stated he has called in locate tickets in the past, but only when he was going to do what he considered "digging". I showed Mr. Hosler the Kentucky 811 "Safe Digging Guide", specifically page 3, which states among other things that grading is considered excavation. I told Mr. Hosler that he needs to call 811 anytime he is doing grading, as well as other forms of what KY811 deems excavation. I gave my contact info, an excavator 811 booklet and a LG&E/Kentucky811 "Safe Digging" brochure to Mr. Hosler

Amount billed to excavator \$0.00

SUPPLEMENTAL PIPELINE DAMAGE INVESTIGATION REPORT

Investigation Information

Investigator Eric Tout **Incident ID** 43465 **Investigation** 8424
Incident Date 3/4/2021 10:17:00 AM **Report Submitted** 3/29/2021

Operator Information

Operator Louisville Gas and Electric Company **Reported By** Mike Jones
Phone (502) 364-8281 **Email** Mike.Jones@lge-KU.com

Incident Location 1224 Ava Pearls Way **Locate Ticket Number** NA
Louisville KY 40245

County Jefferson

Excavator Information

Excavator Randy Hosler **Organization ID** 0439475
Hosler Excavating, Inc.
Phone 502-639-9268 **Email**
Address 8201 Todds Point Rd **Locate Ticket Number** NA
Crestwood KY 40014

SUPPLEMENTAL INVESTIGATION

On 03/01/22 a Demand letter was sent to the Excavator.
The Demand letter is included as Attachment 2.

On 04/05/22 a 30 Days Past Due & No Attendance Remedial Measure/Training letter was sent and on 04/02/22 delivered.

The Past Due Letter is included as Attachment 3.

On 04/14/22 the Operator, LG&E's Mike Jones, provided the following documents:

- Facts-Based Investigation & Incident Field Investigation Report: Which are outlined in the DR Summary and Attachment 1.
- Photographs-28: Depicting the incident location. The Facts-Based Investigation indicate that the yellow markings on the ground were placed after the damage occurred.
- Invoice: Billing the Excavator \$503.03 for the damage repair. Mr. Jones stated that the Excavator was billed, but has not paid for the repair.

LG&E's documents are included as Attachment 4.

Attachment 2



Andy Beshear
Governor

Rebecca W. Goodman
Secretary
Energy and Environment Cabinet

Commonwealth of Kentucky
Public Service Commission
211 Sower Blvd.
P.O. Box 615
Frankfort, Kentucky 40602-0615
Telephone: (502) 564-3940
Fax: (502) 564-3460
psc.ky.gov

Kent A. Chandler
Chairman

Amy D. Cabbage
Vice Chairman

Marianne Butler
Commissioner

March 1, 2022

Randy Hosler
Hosler Excavating, Inc.
8201 Todds Point Rd.,
Crestwood KY 40014

Re: Violation of Kentucky Underground Facility Damage Prevention Act
Incident Number: **43465**

DEMAND FOR PENALTY ASSESSMENT AND REMEDIAL MEASURES

Dear Mr. Hosler:

The Kentucky Public Service Commission (Commission) received a report on March 29, 2021, regarding damage to a natural gas or hazardous liquid facility owned and/or operated by the Louisville Gas and Electric Company. Under the Kentucky Underground Facility Damage Prevention Act (Act), KRS 367.4901 through KRS 367.4917, the Commission has jurisdiction to investigate and assess civil penalties for any violation of the Act that results in excavation damage to underground facilities used to transport gas or hazardous liquid subject to federal pipeline safety laws, 49 U.S.C. secs. 60101 et seq. The Commission regulates the safety of jurisdictional natural gas pipelines in the Commonwealth pursuant to KRS 278.495 and 49 CFR Parts 190, 191, 192 and 195.

Following receipt of the damage notification, Commission Staff (Staff) performed an investigation of the incident and prepared the attached incident report. Based on its investigation of the incident, Staff has determined that Hosler Excavating committed the following violation(s) of the Act:

KRS 367.4911(1)(a) Each excavator, or person responsible for an excavation, planning excavation or demolition work shall, not less than two (2) full working days nor more than ten (10) full working days prior to commencing work, notify each affected operator of the excavator's intended work and work schedule. Contacting the applicable protection notification centers shall satisfy this requirement.

CIVIL PENALTY

Based on its investigation of this matter, Staff has determined that Hosler Excavating **should be assessed a penalty in the total amount of \$1,250, first offense, but that \$1,000 of the penalty should be suspended contingent upon Hosler Excavating's completion of Damage Prevention training:**

REMEDIAL MEASURE/TRAINING

A representative of Hosler Excavating shall participate in a Damage Prevention training course. The Kentucky Public Service Commission will hold these classes online. Class dates have a limited capacity available on a first come-first served basis. To sign up for the class, go to <https://psc.ky.gov/classSignUp>. You will need your incident number: **43465** and assigned key:

8424 to sign-up for one of the available training dates. Please understand that this training will be required as a contingency for the reduced penalty amount.

Within **30 days** of the date of this letter Hosler Excavating should mail or deliver a cashier's check or money order **made payable to** the:

“Kentucky State Treasurer”

The check should be in the amount of \$250.00 mailed to: 211 Sower Boulevard, Frankfort, Kentucky 40602.

Please include the Incident Number 43465 on the cashier's check or money order submitted for payment.

KRS 367.4917 provides that a person who commits a violation of the Act shall be subject to a civil penalty not to exceed \$250 for the first violation, \$1,000 for the second violation within one year, and \$3,000 for the third and any subsequent violation. If the violation results in damage to an underground pipeline used to transport gas or hazardous liquid, the violator is subject to an additional civil penalty not to exceed \$1,000 per violation.

Payment of the proposed civil penalty and completion of the remedial measure will satisfy and resolve any and all claims against Hosler Excavating for any violation of the Act arising out of the March 4, 2021 incident. Hosler Excavating's payment of the proposed civil penalty will not be considered an admission by Hosler Excavating that it willfully violated any provision of the Act.

If Hosler Excavating does not pay the proposed civil penalty within 30 days of the date of this letter, the Commission will institute an administrative proceeding against Hosler Excavating and hold a formal hearing during which Hosler Excavating will have an opportunity to present evidence.

If you have any questions regarding this demand for remedial measures and penalty assessment, please contact Ashley Rhodes, Division of Inspections at 502-782-2578.

Sincerely,

Nancy J. Vinsel

Nancy J. Vinsel
General Counsel

Attachment

Attachment 3



Andy Beshear
Governor

Kent A. Chandler
Chairman

Rebecca W. Goodman
Secretary
Energy and Environment Cabinet

Commonwealth of Kentucky
Public Service Commission
211 Sower Blvd.
P.O. Box 615
Frankfort, Kentucky 40602-0615
Telephone: (502) 564-3940
Fax: (502) 564-3460
psc.ky.gov

April 5, 2022

Randy Hosler
Hosler Excavating, Inc.
8201 Todds Point Rd.,
Crestwood KY 40014

Re: Violation of Kentucky Underground Facility Damage Prevention Act
Incident Number: 43465

30 Days Past Due & No Attendance Remedial Measure/Training

Dear Mr. Hosler:

Attached is the demand letter and investigation report for the above Incident. Our records indicate that a reduced penalty of \$250.00 **has not been paid** and **no representative** has attended the Remedial Measure/Training to receive this reduced penalty. Attendance is required for the penalty reduction to apply.

REMEDIAL MEASURE/TRAINING

A representative of Hosler Excavating shall participate in a Damage Prevention training course. The Kentucky Public Service Commission will hold these classes online. Class dates have a limited capacity available on a first come-first served basis. To sign up for the class, go to **<https://psc.ky.gov/classSignUp>**. You will need your incident number, **43465** and this key **8424** to sign-up for one of the available training dates. **Please understand that this training will be required as a contingency for the reduced penalty amount.**

If we do not hear from you within 10 days from the date of this letter this matter will be referred to the Commission for an Administrative Hearing to be held at the Commission's offices.

Once a referral to the Commission is made, any partnership, corporation, or business entity (including a limited liability company) must be represented by an attorney licensed to practice law in Kentucky. Thank you for your prompt attention to this matter.

If you have any questions regarding this notice or if you find that these requirements have been met, please contact Ashley Rhodes, Division of Inspections at 502-782-2578.

Sincerely,

Nancy J. Vinsel
General Counsel



Mailer: Kentucky Public Service Commission

Date Produced: 04/04/2022

ConnectSuite Inc.:

The following is the delivery information for Certified Mail™/RRE item number 9214 8901 9403 8371 2515 08. Our records indicate that this item was delivered on 04/02/2022 at 02:38 p.m. in CRESTWOOD, KY 40014. The scanned image of the recipient information is provided below.

Signature of Recipient :

R HOSLER
DS RT 3 C19

Address of Recipient :

**8201 TODDS POINT RD
CRESTWOOD, KY 40014**

Thank you for selecting the Postal Service for your mailing needs. If you require additional assistance, please contact your local post office or Postal Service representative.

Sincerely,
United States Postal Service

The customer reference number shown below is not validated or endorsed by the United States Postal Service. It is solely for customer use.

This USPS proof of delivery is linked to the customers mail piece information on file as shown below:

RANDY HOSLER
HOSLER EXCAVATING INC
8201 TODDS POINT RD
CRESTWOOD KY 40014-9128

Customer Reference Number: C3326719.19420070

Return Reference Number Incident 43465 30PD



Return address:


KENTUCKY PUBLIC SERVICE COMMISSION
211 SOWER BLVD
FRANKFORT KY 40602

Recipient address:

RANDY HOSLER
HOSLER EXCAVATING INC
8201 TODDS POINT RD
CRESTWOOD KY 40014-9128

MAILING DATE: 03/30/2022
DELIVERY DATE: 04/02/2022

USPS CERTIFIED MAIL



9214 8901 9403 8371 2515 08

USPS Tracking Label Number: 9214 8901 9403 8371 2515 08

USPS Tracking History	Location	Date / Time
PRE-SHIPMENT INFO SENT USPS AWAITS ITEM	FRANKFORT,KY 40602	03/30/2022 12:27
ORIGIN ACCEPTANCE	FRANKFORT,KY 40602	03/31/2022 20:38
PROCESSED THROUGH USPS FACILITY	LEXINGTON KY DISTRIBUTION CENTE 40511	03/31/2022 21:53
PROCESSED THROUGH USPS FACILITY	LOUISVILLE,KY 40221	04/01/2022 12:47
ARRIVAL AT UNIT	CRESTWOOD,KY 40014	04/02/2022 08:09
OUT FOR DELIVERY	CRESTWOOD,KY 40014	04/02/2022 08:20
NO AUTHORIZED RECIPIENT AVAILABLE	CRESTWOOD,KY 40014	04/02/2022 14:37
DELIVERED LEFT WITH INDIVIDUAL	CRESTWOOD,KY 40014	04/02/2022 14:38

CUSTOM 1:

Attachment 4

Tout, Eric V (PSC)

From: Jones, Mike (Auburndale) <Mike.Jones@lge-ku.com>
Sent: Thursday, April 14, 2022 10:39 AM
To: Tout, Eric V (PSC)
Subject: RE: 43465, 3/4/2021, 1224 Ava Pearls Way, Louisville, Hosler Excavating
Attachments: digitix_attachments_1649946512.zip; DigTix_Incident_Report (1).pdf; Yellow Report.pdf

****CAUTION** PDF attachments may contain links to malicious sites. Please contact the COT Service Desk ServiceCorrespondence@ky.gov for any assistance.**

This was billed but not paid. It has been sent to collections.

From: Tout, Eric V (PSC) <ericv.tout@ky.gov>
Sent: Thursday, April 14, 2022 6:10 AM
To: Jones, Mike (Auburndale) <Mike.Jones@lge-ku.com>
Subject: 43465, 3/4/2021, 1224 Ava Pearls Way, Louisville, Hosler Excavating

EXTERNAL email. STOP and THINK before responding, clicking on links, or opening attachments.

Hello Mike,

Please send repots, photos, invoices and payment info (copy of check) if paid.

Thanks,
Eric V. Tout
Kentucky Public Services Commission
Division of Inspections / Damage Prevention
211 Sower Blvd., Frankfort, KY 40601
Office: 502-782-2622
Fax: 502-564-1582

----- The information contained in this transmission is intended only for the person or entity to which it is directly addressed or copied. It may contain material of confidential and/or private nature. Any review, retransmission, dissemination or other use of, or taking of any action in reliance upon, this information by persons or entities other than the intended recipient is not allowed. If you received this message and the information contained therein by error, please contact the sender and delete the material from your/any storage medium.



Facts-Based Investigation

Internal Claim ID: INC-20210304-002 Customer Claim ID: _____
Site Investigator: Steve Delap Notified At: 03/04/21 10:23:00
Notified By: Gas operations dispatch 5025891444
Damage Location: 1224 AVA PEARLS WAY LOUISVILLE KY 40245
Incident Time: 03/04/21 10:15:00

Original Locate Request: None found Assigned Locator: _____
Locate Request Due: _____ Locate Request Completed: _____
Photos Taken Before Damage? N
Photos Taken of Damage Site? Y

Type and Size of Damaged Utility: Natural Gas Service/Drop 1
Depth: < 18" (0.5m) Below Grade
Description and Extent of Damage: Hosler Excavating was contracted by the builder to grade the property at the newly built home, which is in currently under construction at 1224 Ava Pearls Way. Hosler Excavating was operating a large bulldozer to grade the aforementioned lot when they damaged a 1" plastic gas service. The line (#428281) was damaged on the customer side of the gas service, at a approximate depth of 12". The depth was difficult to determine because Hosler has already graded large portions of the lot and the land itself slopes from left to right, then drops off a large embankment on the right hand side of the lot. NO BUD ticket.
**locate paint marks seen in the damage photos were painted for the LG&E locate request, called into 811 after the gas line was damaged.

Equipment Used: Bulldozer
Excavation Company Name: HOSLER EXCAVATING
Company Address: PO BOX 573, Crestwood, KY 40014
Phone: 5022417562 Contact Name: RANDY HOSLER
Working For: _____
Repair Company: LG&E
Personal Injury: N 3rd Party Property Damage: N Evacuations: N Other: N

Impact Comments: _____
Was Locate requested?: N Locate Request Completed?: N
Locate Accurate (Within Tolerance Zone): N/A If No, Distance Markings Off: N/A
Marks Visible at Time of Damage: _____ Damage Within Scope of Ticket: N



Facts-Based Investigation

Repair Contact Name: EOC- gas department **Phone:** 5025891444

Repair Comments: Repaired tracer wire, replaced approximately 16" of 1/2" PL IPS pipe, dropped a 3m marker ball at the damage spot

Witness: _____ **Phone:** _____

Comments: _____

Witness: _____ **Phone:** _____

Comments: _____

Root Cause Explanation: _____

Responsible Party: Hosler Excavating

Responsible Party Comments: Owner & on-site contact is Randy Hosler, 502-639-9268

Date of Investigation: 03/04/21 **Investigation Time (Hours):** _____

Site Investigator's Name: Steve Delap **Phone:** 5029911135

Site Investigator's Signature: Steve Delap **Date:** 03/04/2021

Damage Status: One Call Notification Issue

Cause Code: No notification made to One-Call Center / 811

Damage Claims Manager: _____





NOTE: Only 12 most recent photos shown. To view all 28 attachments, please view the ticket within DigTix.

503.03

Incident Field Investigation Report — Gas



a PPL company

Damage report # 2021030602 JPB

Is this related to a capital project? Yes No

Project/task OTPD419/ Maint

G# 6001012377 + 6001012384 JPB

Resp. ctr. _____

Damage to company facilities

Date of incident 3-4-2021 Time 10:17 a.m. p.m. Police report # _____

Address/location of damage 1224 Ave Pearls way Louisville Ky ZIP code 40245

Subdivision name _____

Time dispatched 10:17 a.m. p.m. Time of completion 2:00 a.m. p.m.

Who caused damage? Hostler Excavating
(Name of contractor, utility, individual, etc.)

Address of party causing damage 8205 Todds Point Rd Crestwood Ky 40014
(Street) (City) (State) (ZIP)

Phone number of party causing damage (502) 639-9268
(Area code) (Number)

Was party causing damage still on the job? Yes No If yes, who was in charge? Randy Hostler

If no, how did you obtain name of party causing damage? _____

What was damaged? Company main Customer service Company service Other _____

What type of work was being performed? Grading work on property

Party's explanation for damage Didn't know it was there and the service is very shallow

What repairs were made? Repair customer service

Any additional work to be performed? Yes No If yes, by whom? _____ Number of customers out 1

Possible damage to others

Date of incident _____ Time _____ a.m. p.m.

What was damaged? _____

What was LG&E doing at this location? _____

Description of damage _____

Owner of property _____ Phone (_____) _____
(Area code) (Number)

Owner's address _____
(Street) (City) (State) (ZIP)

To whom was damage reported? _____

Was an LG&E contractor notified? Yes No If yes, name of contractor _____

Is the LG&E contractor responsible for the damage? Yes No

Were photos taken? Yes No If yes, from whom can the photos be obtained? _____

Were there any injuries? Yes No If yes, name of injured party _____

Were there any witnesses to the incident? Yes No

Name	Address	Phone

BUD/KY 811/VA 811 information

BUD number and requesting party's name No Bud number / No active locates

Were facilities marked? Yes No Did excavator agree? Yes No

If yes, were facilities properly marked? Yes No Did excavator agree? Yes No

If no, how were they mismarked? (be specific) _____

Was line locating contractor on the job? Yes No

3-4-2021
(Date of report)

John Taylor
(Signature of employee)
Approved _____

E029135
(Employee number)

Date 03-05-2021


Put any additional comments on back

Comments

Excavating company was out having dump truck loads of dirt dumped in front yard and pushing to the backyard.

Crew Personnel	Employee #	ST Hours	OT Hours	DT Hours	Unit #	Equipment
Dustin Hartlage	F28315	1.5			8372	<input checked="" type="checkbox"/> Backhoe <input type="checkbox"/> Kubota
John Marlett	E029135	2.5			4923	<input type="checkbox"/> Backhoe <input checked="" type="checkbox"/> Kubota
Jake Emberton	E029133	2.5				<input type="checkbox"/> Backhoe <input type="checkbox"/> Kubota
						<input type="checkbox"/> Backhoe <input type="checkbox"/> Kubota
						<input type="checkbox"/> Backhoe <input type="checkbox"/> Kubota
						<input type="checkbox"/> Backhoe <input type="checkbox"/> Kubota
						<input type="checkbox"/> Backhoe <input type="checkbox"/> Kubota
						<input type="checkbox"/> Backhoe <input type="checkbox"/> Kubota
						<input type="checkbox"/> Backhoe <input type="checkbox"/> Kubota
						<input type="checkbox"/> Backhoe <input type="checkbox"/> Kubota
						<input type="checkbox"/> Backhoe <input type="checkbox"/> Kubota
						<input type="checkbox"/> Backhoe <input type="checkbox"/> Kubota

Please provide a sketch of the damage location, including any locate markings.



Material Used		
Qty.	Material	IIN#
	ft. Pipe PE 2406: 1/2" IPS	1170051
4	ft. Pipe PE 2406: 1" CTS	1170078
	ft. Pipe PE 2406: 1-1/4" IPS	0434843
	ft. Pipe PE 2406: 2" IPS	0459060
	ft. Pipe PE 2406: 4" IPS	0395160
	ea. 1/2" IPS Permasert coupling	0394943
2	ea. 1" CTS Permasert coupling	0394935
	ea. 2" IPS Electrofusion CPL	0394894
	ea. 4" IPS Electrofusion CPL	0394901
	ea. 1" Prefab Meterloop w/reg.	0532951
	ea. Flex Riser 1" male by 1/2" IPS	0530927
	ea. Flex Riser 1" male by 1" CTS	0530935
	ea. Farm tap (w/o regulator)	ARM WR 5695012
	ea. Farm tap regulator (Fischer 627 with 1/8" diameter orifice)	



2021-03-04 11:40:35
38.2565830,-85.4272316





2021-03-04 11:40:45
38.2564197,-85.4273010



2021-03-04 11:40:53
30,2567402,-85,4273996



2021-03-04 11:40:57
36,2567402,-95,4273996



2021-03-04 11:41:02
38.2566788,-85.4271529



2021-03-04 11:41:14

38.2566973,-85.4273030





2021-03-04 11:41:25
38.2566973,-85.4273030



2021-03-04 11:41:38
38.2566973,-85.4273038



2021-03-04 11:41:42
38.2569454,-85.4214042



2021-03-04 11:42:05
38.2566450,-85.4274851



2021-05-04 11:42:19
88.2565613,-85.4273438



2021-03-04 11:42:13
38.2565613,-85.4273433



2021-03-04 11:42:28
38.2566614,-85.4273445



2021-09-04 11:42:39
38.2566614; -85.4273445



2021-03-04 11:42:42
38.2566614,-85.4273445



2021-03-04 11:42:49
38.2566003,-85.4271901



2021-03-04 11:42:52
38.2566002,-85.4273313



2021-03-04 11:42:57
36.2567264, 105.4273452



2021-03-04 11:43:03
38.2564267,-85.4272254



2021-03-04 11:43:07
38.2564287,-85.4272254



2021-03-04 11:43:11
38.2567206, -85.4273766

Select Homes LLC

Lot # [REDACTED]-19
Address: 1224
AVA PEARL



Select Homes LLC

SOLD

www.SchulerBauer.com

**Schuler
Bauer**

Real Estate Services
(502) 426-3600



Staci O'Sullivan
502-817-7722







2021-03-04 12:14:38
38.2564686,-85.4273731



Invoice
Louisville Gas and Electric Company
 820 West Broadway
 Louisville, KY 40202
 Attn: Remittance and Collection
 800-928-1340

INVOICE DATE: 03/26/2021

REFERENCE: OTPD419
 NO.:
 DTS INVOICE: 2021030602
 NO.:

AMOUNT DUE: **\$503.03**
 DUE DATE: **04/25/2021**

HOSLER EXCAVATING
 8205 TODDS POINT ROAD
 CRESTWOOD KY 40014

PLEASE RETURN TOP PORTION WITH YOUR PAYMENT
PLEASE INCLUDE INVOICE NUMBER ON ALL REMITTANCES

COST TO REPAIR: Damaged Customer Gas Service
 DAMAGE DATE: 03/04/2021
 DAMAGE LOCATION: 1224 Ava Pearls Way
 Louisville, KY 40245

LABOR HOURS: 6.50

LABOR COST: \$437.89

MATERIAL COST: \$21.88

TRANSPORTATION/EQUIPMENT COST: \$43.26

CONTRACTOR COST: \$0.00

OTHER DAMAGE COSTS: \$0.00

TOTAL DUE: \$503.03

APPENDIX B

APPENDIX TO AN ORDER OF THE KENTUCKY PUBLIC SERVICE
COMMISSION IN CASE NO. 2022-00171 DATED JUN 17 2022

TWO PAGES TO FOLLOW

Information and Instructions for Hearing

You are required to attend a formal hearing with the Kentucky Public Service Commission. Please note the hearing is scheduled in the **Eastern Time Zone**, and the hearing date and time are on the Order that accompanied these instructions.

You are **strongly encouraged** to download the GoToMeeting app now and be ready for your hearing. If you cannot appear via video using this app, at least ten days prior to your scheduled hearing you must call the Commission's offices at the number provided below. You will receive instructions on appearing in person in the Richard Raff Hearing Room of the Commission's offices at 211 Sower Boulevard in Frankfort, Kentucky at the time and date of your scheduled hearing.

Please direct any questions to Ashley Rhodes, Commission Division of Inspections. AshleyB.Rhodes@ky.gov or 502-782-2578.

To download the GoToMeeting app go to:

<https://global.gotomeeting.com/install/258846301>

On the day of your hearing using your computer, tablet, or video enabled smartphone. **Access the proceeding at:**

<https://global.gotomeeting.com/join/308551245>

More information about using GoToMeeting can be found at:

GoToMeeting - Attendee Quick Start

<https://www.youtube.com/embed/8VaHHVP0FCU?autoplay=1&showinfo=0&controls=0&rel=0>

GoToMeeting - How to Join a Meeting

https://www.youtube.com/embed/Ojl1q_sPrP0?autoplay=1&showinfo=0&controls=0&rel=0

Technical Requirements for Using GoToMeeting

Operating System:

Windows 7 – Windows 10

Mac OS X 10.9 (Mavericks) – mac OS Big Sur (11)

Linux/Ubuntu (Web App only)

Google Chrome OS (Web App only)

iOS 11 – iOS 13

Android OS 5 (Lollipop) – Android 10

Web Browser: (Applies to Web App only)

Google Chrome v72 or newer

Microsoft Edge v77 or newer

Internet Connection:

Computer: 1 Mbps or better (broadband recommended)

Mobile device and Chromebook: 3G or better (WiFi recommended for VoIP)

Software:

GoToMeeting desktop app (JavaScript enabled)

GoToMeeting app from the Apple Store, Google Play Store, or Windows Store

Hardware:

2GB of RAM (minimum), 4GB or more of RAM (recommended)

Webcam device*

Microphone and speakers** (USB headset recommended)

Mobile Device:

iPhone 5 or newer

iPad 3rd gen or newer

Note: * You MUST have a camera on your device or connected to your device to appear at the hearing.

** Most devices have built-in speakers, but you will get better audio quality while connected via VoIP if you use a headset

Hosler Excavating, Inc.
8201 Todds Point Rd.
Crestwood, KENTUCKY 40014