VERIFICATION

COMMONWEALTH OF KENTUCKY)) COUNTY OF JEFFERSON)

The undersigned, John K. Wolfe, being duly sworn, deposes and says that he is Vice President, Electric Distribution for Kentucky Utilities Company and Louisville Gas and Electric Company and an employee of LG&E and KU Services Company, and that he has personal knowledge of the matters set forth in the responses for which he is identified as the witness, and the answers contained therein are true and correct to the best of his information, knowledge and belief.

heach John K./Wolfe

Subscribed and sworn to before me, a Notary Public in and before said County and State, this <u>Sta</u>day of <u>Monember</u> 2018.

udyscholor

Notary Public

My Commission Expires: Judy Schooler Notary Public, ID No. 603967 State at Large, Kentucky Commission Expires 7/11/2022

KENTUCKY UTILITIES COMPANY AND LOUISVILLE GAS AND ELECTRIC COMPANY

November 12, 2018 Supplemental Response to Commission Staff's First Request for Information Dated September 27, 2018

Case No. 2018-00304

Question No. 2

Responding Witness: John K. Wolfe

- Q-2. Refer to the application, paragraph 18, which states that 1,200 wires were downed and 200 poles were damaged.
 - a. Provide the capital costs incurred by KU/LG&E as a result of restoration efforts due to the July 2018 Storm, as defined in the application.
 - b. Provide a list of the number of damaged poles by size.

A-2. Original Response:

- a. LG&E capital costs through September 30, 2018 related to the July 20th, 2018 storm are \$1,016,257 for Distribution and \$115,539 for Transmission. KU (KY only) capital costs through September 30, 2018 related to the July 20th, 2018 storm are \$4,494,427 for Distribution and \$314,703 for Transmission.
- b. The following table provides a breakout of damaged poles by size.

Size (in feet)	Quantity
30	28
35	9
40	64
45	60
50	59
55	22
60	1
65	1
70	12
Total	256

Response to Question No. 2 Page 2 of 2 Wolfe

November 12, 2018 Supplemental Response for Question No. 2(b):

b. The following table provides a breakout of damaged poles by size through October 29, 2018.

Size (in feet)	Quantity
30	28
35	9
40	64
45	60
50	59
55	22
60	1
65	4
70	9
Total	256