

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 2/28/23 Ended 2/28/23

Areas Covered: DITCH @ 431 S / OLD DOLLAR STORE

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system: _____

Follow-up (repairs, maintenance or test resulting from this inspection): LINE IS PROTECTED WITH P.V.C ENCASE / RIP RAP / CONCRETE

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: [Signature]

Date: 2/28/23

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 2/28/23 Ended 2/28/23

Areas Covered: DITCH LINE @ W&R HEAT/COC

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):
NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system: _____

Follow-up (repairs, maintenance or test resulting from this inspection): LINE IS MIL WRAPPED FOR PROTECTION

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: By Alled

Date: 2/28/23

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 2/28/23 Ended 2/28/23

Areas Covered: HAZEL CREEK RD

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):
NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system: _____

Follow-up (repairs, maintenance or test resulting from this inspection): SERVICE TAP EXPOSED @ DITCH LINE. PROTECTED BY RIP RAP

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: B. Almad

Date: 2/28/23

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 2/28/23 Ended 2/28/23

Areas Covered: DITCH LINE @ 431 / FARRIS TRAILER

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):
NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system: _____

Follow-up (repairs, maintenance or test resulting from this inspection): LINE HAS BEEN CLAMPED AND IS MONITORED 2x WEEK

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: B. Almad

Date: 2/28/23

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 2/28/23

Ended 2/28/23

Areas Covered: 314 HWY 176

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:

Follow-up (repairs, maintenance or test resulting from this inspection): RISER WAS REPAIRED WITH COUPLING AND IS MONITORED 1x WEEK

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: R. Alled

Date: 2/28/23

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 2/28/23 Ended 2/28/23

Areas Covered: 404 BEECH CREEK RD.

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system: _____

Follow-up (repairs, maintenance or test resulting from this inspection): RISER HAS BEEN REPAIRED WITH COUPLING AND IS CHECKED 1X WEEK

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: [Signature]

Date: 2/28/23

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 2/28/23

Ended 2/28/23

Areas Covered: 3740 4315

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:

Follow-up (repairs, maintenance or test resulting from this inspection): _____

Comments: SITE IS REGULATOR STATION WITH 2" STEEL PRESSURE RELIEF. SITE IS CHECKED 2 X MONTH

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: Ry Wood

Date: 2/28/23