

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBURG

Period Covered: Began 4/6/23 Ended 4/6/23

Areas Covered: 3740 4315 (REGULATOR STATION)

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):
NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system: _____

Follow-up (repairs, maintenance or test resulting from this inspection): _____

Comments: SITE IS MONITORED 2x MONTH WITH C.G.I

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: Bj Alford

Date: 4/6/23

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 4/6/23 Ended 4/6/23

Areas Covered: DITCH LINE @ 431/OLD DOLLAR STORE
BEECHMONT

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):
NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:

Follow-up (repairs, maintenance or test resulting from this inspection): GAS LINE IS
PROTECTED WITH P.V.C ENCASED / RIP RAP / CONCRETE

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: By Alled

Date: 4/6/23

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 4/6/23 Ended 4/6/23

Areas Covered: DITCH LINE @ WBR HEAT/COOL

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):
NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system: _____

Follow-up (repairs, maintenance or test resulting from this inspection): LINE IS PROTECTED WITH MIL WRAP

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: B. Alled

Date: 4/6/23

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 4/6/23 Ended 4/6/23

Areas Covered: 315 HAZEL CREEK RD

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):
NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system: _____

Follow-up (repairs, maintenance or test resulting from this inspection): SERVICE TAP IS EXPOSED. PROTECTED WITH RIP RAP

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: By Alled

Date: 4/6/23

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DAYESBORO

Period Covered: Began 4/4/23 Ended 4/6/23

Areas Covered: DITCH @ 4316 / FARRIS TRAILERS

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system: _____

Follow-up (repairs, maintenance or test resulting from this inspection): LINE HAS BEEN REPAIRED WITH CLAMP / LINE IS MONITORED 2X WEEK

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: B. Almed

Date: 4/6/23

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 4/6/23 Ended 4/6/23

Areas Covered: 314 HWY 176

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system: _____

Follow-up (repairs, maintenance or test resulting from this inspection): RISER HAS BEEN REPAIRED WITH COUPLING AND IS CHECKED 2X WEEK

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: By Alced

Date: 4/6/23

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 4/6/23 Ended 4/6/23

Areas Covered: 404 BEECH CREEK RD.

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:

Follow-up (repairs, maintenance or test resulting from this inspection): RISEK WAS REPAIRED WITH COUPLING AND IS CHECKED 2X WEEK

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: B. Allen

Date: 4/6/23