## PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: DRAKESBORO UTILITIES
Period Covered: Began 2/25/22 Ended 2/25/22
Areas Covered: DITCH LINE & OLD DOLLAR STORE REECHNICHT
Map References:
Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):
Describe any unusual conditions at highway and railroad crossings:
Other Factors noted which could affect present or future safety or operations of the gas system:  LINE IS PROTECTED WITH PVC PIPE ARCUM  BAND RIFE RAFF WER TOP
Follow-up (repairs, maintenance or test resulting from this inspection):
Comments:
Number of Persons in Patrol Party:  Signature of Person in Charge of Patrol Party:   AllCol
Date: 2/25/27

## PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: DRIKESKORO UTILITIES
Period Covered: Began 2/25/22 Ended 2/25/22
Areas Covered: DITCH CROSSING @ 43/ /WESTER ST.
Map References:
Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):
Describe any unusual conditions at highway and railroad crossings:  Line 15 Mile WEAPEN
Other Factors noted which could affect present or future safety or operations of the gas system:
Follow-up (repairs, maintenance or test resulting from this inspection):
Comments:
Number of Persons in Patrol Party:
Signature of Person in Charge of Patrol Party: Butter
Date: 2/25/23

## PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: DEAVESRORO UTILITIES
Period Covered: Began 2/25/27 Ended 2/25/22
Areas Covered: DITCH UNE NEXT TO WAR HUAC
· · · · · · · · · · · · · · · · · · ·
Map References:
Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):
Describe any unusual conditions at highway and railroad crossings:
Other Factors noted which could affect present or future safety or operations of the gas system:
Follow-up (repairs, maintenance or test resulting from this inspection):
Comments:
Number of Persons in Patrol Party:
Signature of Person in Charge of Patrol Party:
Date: 2/25/22