

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 5/13/22 Ended 5/13/22

Areas Covered: DITCH LINE @ 431 / WESTER

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):
NO LEAKS FOUND.

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:
2" STEEL LINE FEEDING WESTER DRI

Follow-up (repairs, maintenance or test resulting from this inspection): _____

Comments: AREA IS MONITORED WITH C.G.I DAILY

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: Ryland

Date: 5/13/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 5/13/22 Ended 5/13/22

Areas Covered: DITCH LINE @ 431 / W & R HEATING / COOLING

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:

2' STEEL GAS LINE SLIGHTLY EXPOSED

Follow-up (repairs, maintenance or test resulting from this inspection): _____

LINE IS WRAPPED WITH MILL TAPE

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: By Alled

Date: 5/13/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 5/13/22 Ended 5/13/22

Areas Covered: DITCH LINE NEXT TO OLD DOLLAR STORE
IN BEECHMONT

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:

4" GAS MAIN CROSSING DITCH

Follow-up (repairs, maintenance or test resulting from this inspection): _____

Comments: PIPE IS PROTECTED WITH P.V.C. /RIP RAP
CONCRETE OVER

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: By Alled

Date: 5/13/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 5/13/22 Ended 5/13/22

Areas Covered: 322 HWY 176

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):
NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:
LINE IS CHECKED DAILY W/ C.G.F

Follow-up (repairs, maintenance or test resulting from this inspection): _____

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: Bj Alled

Date: 5/13/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 5/13/22 Ended 5/13/22

Areas Covered: 315 HAZEL CREEK

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):
NO LEAKS DETECTED

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:
SERVICE TAP EXPOSED IN DITCH LINE

Follow-up (repairs, maintenance or test resulting from this inspection): _____

Comments: MAKING PLANS TO REROUTE LINE

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: By Alled

Date: 5/13/22