

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 12/30/22 Ended 12/30/22

Areas Covered: DITCH LINE NEXT TO OLD DOLLAR STORE
IN BEECHMONT

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):
NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system: _____

Follow-up (repairs, maintenance or test resulting from this inspection): STEEL LINE IS
ENCASED IN P.V.C AND COVERED WITH RIP RAP/CONC.

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: By Alled

Date: 12/30/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 12/30/22 Ended 12/30/22

Areas Covered: DITCH LINE @ W3R HVAC

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:

NO LEAKS

Follow-up (repairs, maintenance or test resulting from this inspection): LINE IS MIL WRAPPED

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: [Signature]

Date: 12/30/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 12/30/22 Ended 12/30/22

Areas Covered: HAZEL CREEK RD

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:

Follow-up (repairs, maintenance or test resulting from this inspection): SERVICE TAP

EXPOSED IN DITCH LINE HAS BEEN COVERED
WITH RIP RAP

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: B. Allen

Date: 12/30/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 12/30/22 Ended 12/30/22

Areas Covered: DITCH NEXT TO FARRIS TRAILER SALES
ON 431(S)

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):
NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system: _____

Follow-up (repairs, maintenance or test resulting from this inspection): LINE HAS BEEN
CLAMPED AND IS MONITORED 2X WEEK

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: Bj Allard

Date: 12/30/22