

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 12/7/21 Ended 12/7/21

Areas Covered: DITCH LINE @ 431 S / WESTER ST.

Map References: \_\_\_\_\_

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):  
NO LEAKS

Describe any unusual conditions at highway and railroad crossings: LINE IS MILL WRAPPED TRYING TO DETERMINE WHAT TO DO TO PROTECT LINE.

Other Factors noted which could affect present or future safety or operations of the gas system:

Follow-up (repairs, maintenance or test resulting from this inspection): \_\_\_\_\_

Comments: \_\_\_\_\_

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: R. Alled

Date: 12/7/21

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 12/7/21 Ended 12/7/21

Areas Covered: DITCH LINE @ OLD DOLLAR STORE IN BEECHMONT

Map References: \_\_\_\_\_

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):  
NO LEAKS FOUND

Describe any unusual conditions at highway and railroad crossings: \_\_\_\_\_

Other Factors noted which could affect present or future safety or operations of the gas system:  
LINE IS SECURED BY SECONDARY PVC FOR PROTECTION AND COVERED WITH ROCK/CONCRETE

Follow-up (repairs, maintenance or test resulting from this inspection): \_\_\_\_\_

Comments: \_\_\_\_\_

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: R. Alford

Date: 12/7/21

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 12/7/21 Ended 12/7/21

Areas Covered: DITCH LINE NEXT TO W&R HEATING @  
431.5

Map References: \_\_\_\_\_

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):  
NO LEAKS

Describe any unusual conditions at highway and railroad crossings: \_\_\_\_\_

Other Factors noted which could affect present or future safety or operations of the gas system:  
LINE IS EXPOSED @ DITCH CROSSING, TRYING TO  
DETERMINE BEST WAY TO PROTECT

Follow-up (repairs, maintenance or test resulting from this inspection): \_\_\_\_\_

Comments: \_\_\_\_\_

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: B. Ahmed

Date: 12/7/21