

Last Name/First Name	Company Name	Test Date	P/F	Instructor	Test Name	Skill
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/19/2019	P	TAYLOR	F02.1.0701 Joining of Pipe: Bottom-Out Compression Couplings	F02.1.0701 SIM
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/20/2019	P	TAYLOR	G02.0861 Installation of Steel Pipe in a Ditch	NO SKILLS RETURNED
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/20/2019	P	TAYLOR	G02.0881 Installation of Steel Pipe by Plowing/Pull-In	NO SKILLS RETURNED
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/20/2019	P	TAYLOR	G02.0891 Field Bending of Steel Pipe	NO SKILLS RETURNED
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/20/2019	P	TAYLOR	G02.0931 Installation of Plastic Pipe by Plowing/Planting	NO SKILLS RETURNED
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/20/2019	P	TAYLOR	G02.0941 Install Tracer Wire	G02.0941 SIM
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/20/2019	P	TAYLOR	G02.0971 Installation and Maintenance of Casing Spacers, Vents and Seals	NO SKILLS RETURNED
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/20/2019	P	TAYLOR	H06.5701 Install Excess Flow Valves	H06.5701 SIM
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/21/2019	P	TAYLOR	I13.5541 Pipe Surface Preparation for Coating Application	I13.5541 SIM
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/19/2019	P	TAYLOR	F02.1.0691 Joining of Pipe: Nonbottom-Out Compression Couplings	F02.1.0691 SIM
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/19/2019	P	TAYLOR	F02.2.0681 Joining of Plastic Pipe: Stab Fittings	F02.2.0681 SIM
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/19/2019	P	TAYLOR	F02.3.0711 Joining of Pipe: Compression Couplings	F02.3.0711 SIM
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/19/2019	P	TAYLOR	F08.5821 Joining of Plastic Pipe: Bolt-On Tapping Tee	F08.5821 SIM
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/20/2019	P	TAYLOR	G02.0641 Visually Inspect Pipe and Components Prior to Installation	G02.0641 SIM
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/20/2019	P	TAYLOR	G02.0901 Installation of Plastic Pipe in a Ditch	G02.0901 SIM
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/20/2019	P	TAYLOR	G02.0921 Installation of Plastic Pipe by Plowing/Pull-In	G02.0921 SIM
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/20/2019	P	TAYLOR	H02.5861 Install Steel Service Lines	NO SKILLS RETURNED
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/20/2019	P	TAYLOR	H02.5901 Install Plastic Service Lines	H02.5901 SIM
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/21/2019	P	TAYLOR	H05.1191 Maintenance of Service Valves Upstream of Customer Meter	H05.1191 SIM
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/21/2019	P	TAYLOR	I01.0001 Measure Structure to Electrolyte Potential	I01.0001 SIM
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/21/2019	P	TAYLOR	I13.0991 Coating Application and Repair: Brushed or Rolled	NO SKILLS RETURNED
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/21/2019	P	TAYLOR	I13.1001 Coating Application and Repair: Sprayed	I13.1001 SIM
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/21/2019	P	TAYLOR	I13.1011 External Coating Application and Repair: Wrapped	I13.1011 SIM
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/19/2019	P	TAYLOR	L01.a.1101 Tapping a Pipeline With a Built-In Cutter	L01.a.1101 SIM
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/22/2019	P	TAYLOR	L02.1651 Purge-Flammable or Inert Gas	L02.1651 SIM
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/22/2019	P	TAYLOR	L02.1661 Purge - Hazardous Liquids.	L02.1661 SIM
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/13/2019	P	TAYLOR	L03.a.1211 Odorization: Periodic Sampling	L03.a.1211 SIM
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/22/2019	P	TAYLOR	M01.1261 Walking Gas Leakage Survey	M01.1261 SIM
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/22/2019	P	TAYLOR	M01.1271 Mobile Gas Leakage Survey: Flame Ionization	NO SKILLS RETURNED
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/22/2019	P	TAYLOR	M01.1281 Mobile Gas Leakage Survey: Optical Methane	NO SKILLS RETURNED
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/21/2019	P	TAYLOR	M05.0301 Manually Opening and Closing Valves	M05.0301 SIM
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/21/2019	P	TAYLOR	M05.0311 Adjust and Monitor Flow or Pressure-Manual Valve Operation	M05.0311 SIM
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/21/2019	P	TAYLOR	M05.0331 Valve - Visual Inspection and Partial Operation	M05.0331 SIM
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/21/2019	P	TAYLOR	M05.0341 Valve-Preventive Maintenance	M05.0341 SIM
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/22/2019	F	TAYLOR	M08.0201 Visual Inspection of Installed Pipe and Components for Mechanical Damage	M08.0201 SIM
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/22/2019	P	TAYLOR	M08.0211 Measure and Characterize Mechanical Damage on Installed Pipe and Components	M08.0211 SIM
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/22/2019	P	TAYLOR	M08.1041 Install Mechanical Clamps or Sleeves: Bolted	M08.1041 SIM
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/22/2019	P	TAYLOR	M08.1051 Fit-Up of Weld Type Repair: Sleeves	NO SKILLS RETURNED
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/22/2019	F	TAYLOR	M08.1061 Install Composite Sleeves	NO SKILLS RETURNED
SHAW JORDON	DRAKESBORO GAS DEPARTMENT	02/22/2019	P	TAYLOR	M08.1071 Repair of Steel Pipe by Grinding	NO SKILLS RETURNED

SHAW	JORDON	DRAKESBORO GAS DEPARTMENT	02/21/2019	P	TAYLOR	M08.1141 Squeeze Off Plastic Pipe	M08.1141 SIM
SHAW	JORDON	DRAKESBORO GAS DEPARTMENT	02/22/2019	P	TAYLOR	M10.5081 Abandon/Deactivate Mains	M10.5081 SIM
SHAW	JORDON	DRAKESBORO GAS DEPARTMENT	02/22/2019	P	TAYLOR	M10.5091 Abandon/deactivate Service Lines	M10.5091 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/19/2019	P	TAYLOR	F02.1.0701 Joining of Pipe: Bottom-Out Compression Couplings	F02.1.0701 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/20/2019	P	TAYLOR	G02.0861 Installation of Steel Pipe in a Ditch	NO SKILLS RETURNED
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/20/2019	P	TAYLOR	G02.0881 Installation of Steel Pipe by Plowing/Pull-In	NO SKILLS RETURNED
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/20/2019	P	TAYLOR	G02.0891 Field Bending of Steel Pipe	NO SKILLS RETURNED
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/20/2019	P	TAYLOR	G02.0931 Installation of Plastic Pipe by Plowing/Planting	NO SKILLS RETURNED
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/20/2019	P	TAYLOR	G02.0941 Install Tracer Wire	G02.0941 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/20/2019	P	TAYLOR	G02.0971 Installation and Maintenance of Casing Spacers, Vents and Seals	NO SKILLS RETURNED
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/20/2019	P	TAYLOR	H06.5701 Install Excess Flow Valves	H06.5701 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/21/2019	P	TAYLOR	I13.5541 Pipe Surface Preparation for Coating Application	I13.5541 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/19/2019	P	TAYLOR	F02.1.0691 Joining of Pipe: Nonbottom-Out Compression Couplings	F02.1.0691 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/19/2019	P	TAYLOR	F02.2.0681 Joining of Plastic Pipe: Stub Fittings	F02.2.0681 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/19/2019	P	TAYLOR	F02.3.0711 Joining of Pipe: Compression Couplings	F02.3.0711 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/19/2019	P	TAYLOR	F08.5821 Joining of Plastic Pipe: Bolt-On Tapping Tee	F08.5821 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/20/2019	P	TAYLOR	G02.0641 Visually Inspect Pipe and Components Prior to Installation	G02.0641 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/20/2019	P	TAYLOR	G02.0901 Installation of Plastic Pipe in a Ditch	G02.0901 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/20/2019	P	TAYLOR	G02.0921 Installation of Plastic Pipe by Plowing/Pull-In	G02.0921 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/20/2019	P	TAYLOR	H02.5861 Install Steel Service Lines	NO SKILLS RETURNED
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/20/2019	P	TAYLOR	H02.5901 Install Plastic Service Lines	H02.5901 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/21/2019	P	TAYLOR	H05.1191 Maintenance of Service Valves Upstream of Customer Meter	H05.1191 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/21/2019	P	TAYLOR	I01.0001 Measure Structure to Electrolyte Potential	I01.0001 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/21/2019	P	TAYLOR	I13.0991 Coating Application and Repair: Brushed or Rolled	NO SKILLS RETURNED
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/21/2019	P	TAYLOR	I13.1001 Coating Application and Repair: Sprayed	I13.1001 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/21/2019	P	TAYLOR	I13.1011 External Coating Application and Repair: Wrapped	I13.1011 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/19/2019	P	TAYLOR	L01.a.1101 Tapping a Pipeline With a Built-In Cutter	L01.a.1101 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/22/2019	P	TAYLOR	L02.1651 Purge-Flammable or Inert Gas	L02.1651 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/22/2019	P	TAYLOR	L02.1661 Purge – Hazardous Liquids.	L02.1661 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/13/2019	P	TAYLOR	L03.a.1211 Odorization: Periodic Sampling	L03.a.1211 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/22/2019	P	TAYLOR	M01.1261 Walking Gas Leakage Survey	M01.1261 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/22/2019	P	TAYLOR	M01.1271 Mobile Gas Leakage Survey: Flame Ionization	NO SKILLS RETURNED
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/22/2019	P	TAYLOR	M01.1281 Mobile Gas Leakage Survey: Optical Methane	NO SKILLS RETURNED
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/21/2019	P	TAYLOR	M05.0301 Manually Opening and Closing Valves	M05.0301 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/21/2019	P	TAYLOR	M05.0311 Adjust and Monitor Flow or Pressure-Manual Valve Operation	M05.0311 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/21/2019	P	TAYLOR	M05.0331 Valve - Visual Inspection and Partial Operation	M05.0331 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/21/2019	P	TAYLOR	M05.0341 Valve-Preventive Maintenance	M05.0341 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/22/2019	F	TAYLOR	M08.0201 Visual Inspection of Installed Pipe and Components for Mechanical Damage	M08.0201 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/22/2019	P	TAYLOR	M08.0211 Measure and Characterize Mechanical Damage on Installed Pipe and Components	M08.0211 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/22/2019	P	TAYLOR	M08.1041 Install Mechanical Clamps or Sleeves: Bolted	M08.1041 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/22/2019	P	TAYLOR	M08.1051 Fit-Up of Weld Type Repair: Sleeves	NO SKILLS RETURNED

SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/22/2019	P	TAYLOR M08.1061 Install Composite Sleeves	NO SKILLS RETURNED
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/22/2019	P	TAYLOR M08.1071 Repair of Steel Pipe by Grinding	NO SKILLS RETURNED
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/21/2019	P	TAYLOR M08.1141 Squeeze Off Plastic Pipe	M08.1141 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/22/2019	P	TAYLOR M10.5081 Abandon/Deactivate Mains	M10.5081 SIM
SIMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/22/2019	P	TAYLOR M10.5091 Abandon/deactivate Service Lines	M10.5091 SIM

Last Name	First Name	Company Name	Test Date	P/F	Instructor	Test Name	Skill
SHAW	JORDON	DRAKESBORO GAS DEPARTMENT	02/14/2019	P	TAYLOR	G01.0981 Backfilling	G01.0981 ALL-SIM
SHAW	JORDON	DRAKESBORO GAS DEPARTMENT	02/14/2019	P	TAYLOR	301.5051 Verified the Correct Marking of Permanently Marked Underground Pipeline Facilities	G01.5051 ALL-SIM
SHAW	JORDON	DRAKESBORO GAS DEPARTMENT	02/12/2019	P	TAYLOR	H01.1161 Installation of Customer Meters and Regulators: Residential and Small Commercial	H01.1161 ALL-SIM
SHAW	JORDON	DRAKESBORO GAS DEPARTMENT	02/14/2019	P	TAYLOR	G01.1321 Damage Prevention During Excavation Activities by or on Behalf of the Operator	G01.1321 ALL-SIM
SHAW	JORDON	DRAKESBORO GAS DEPARTMENT	02/14/2019	P	TAYLOR	G01.1331 Damage Prevention Inspection During Third-Party Excavation or Encroachment Activities as Determined Necessary by the Operator	G01.1331 ALL-SIM
SHAW	JORDON	DRAKESBORO GAS DEPARTMENT	02/14/2019	P	TAYLOR	G01.1341 Provide or Ensure Adequate Pipeline Support During Operator-Initiated Excavation Activities	G01.1341 ALL-SIM
SHAW	JORDON	DRAKESBORO GAS DEPARTMENT	02/14/2019	P	TAYLOR	G01.5061 Verified the Correct Marking of Temporarily Marked Underground Pipeline Facilities	G01.5061 ALL-SIM
SHAW	JORDON	DRAKESBORO GAS DEPARTMENT	02/12/2019	P	TAYLOR	H01.0721 Joining of Pipe: Threaded Joints	H01.0721 ALL-SIM
SHAW	JORDON	DRAKESBORO GAS DEPARTMENT	02/12/2019	P	TAYLOR	H01.1171 Installing Customer Meters: Large Commercial and Industrial	H01.1171 ALL-SIM
SHAW	JORDON	DRAKESBORO GAS DEPARTMENT	02/13/2019	P	TAYLOR	H03.1201 Temporary Isolation of Service Lines and Service Discontinuance	H03.1201 ALL-SIM
SHAW	JORDON	DRAKESBORO GAS DEPARTMENT	02/13/2019	P	TAYLOR	H04.5251 Install Service Line Valves Upstream of Customer Meter	H04.5251 ALL-SIM
SHAW	JORDON	DRAKESBORO GAS DEPARTMENT	02/12/2019	P	TAYLOR	H07.5781 Check for Irregularities In the Condition of Meter Installations	H07.5781 ALL-SIM
SHAW	JORDON	DRAKESBORO GAS DEPARTMENT	02/14/2019	P	TAYLOR	H08.5791 Restore Service	H08.5791 ALL-SIM
SHAW	JORDON	DRAKESBORO GAS DEPARTMENT	02/13/2019	P	TAYLOR	I10.0141 Visual Inspection For Atmospheric Corrosion	I10.0141 ALL-SIM
SHAW	JORDON	DRAKESBORO GAS DEPARTMENT	02/12/2019	P	TAYLOR	M01.1241 Outside Gas Leak Investigation	M01.1241 ALL-POJ
SHAW	JORDON	DRAKESBORO GAS DEPARTMENT	02/12/2019	P	TAYLOR	M02.1291 Locate Underground Pipelines	M02.1291 ALL-POJ
SHAW	JORDON	DRAKESBORO GAS DEPARTMENT	02/12/2019	P	TAYLOR	M02.1301 Install and Maintain Pipeline Markers	M02.1301 ALL-SIM
SHAW	JORDON	DRAKESBORO GAS DEPARTMENT	02/12/2019	P	TAYLOR	M02.5101 Temporarily Mark Underground Pipeline Facilities	M02.5101 ALL-POJ
SHAW	JORDON	DRAKESBORO GAS DEPARTMENT	02/13/2019	P	TAYLOR	M03.0561 Pressure Test: Nonliquid Medium – MAOP Less Than 100 psi	M03.0561 ALL-SIM
SHAW	JORDON	DRAKESBORO GAS DEPARTMENT	02/13/2019	P	TAYLOR	M03.0571 Pressure Test: Nonliquid Medium – MAOP Greater Than or Equal to 100 psi	M03.0571 ALL-SIM
SHAW	JORDON	DRAKESBORO GAS DEPARTMENT	02/13/2019	P	TAYLOR	M03.0591 Leak Test at Operating Pressure	M03.0591 ALL-SIM
SHAW	JORDON	DRAKESBORO GAS DEPARTMENT	02/11/2019	P	TAYLOR	M07.5741 Prevent Accidental Ignition	M07.5741 ALL-SIM
SHAW	JORDON	DRAKESBORO GAS DEPARTMENT	02/11/2019	P	TAYLOR	M11.5751 Recognize and React to Generic Abnormal Operating Conditions	M11.5751 ALL-SIM

SIMMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/14/2019 P	TAYLOR	G01.0981 Backfilling 301.5051 Verified the Correct Marking of Permanently Marked Underground Pipeline Facilities	G01.0981 ALL-SIM
SIMMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/14/2019 P	TAYLOR	401.1161 Installation of Customer Meters and Regulators: Residential and Small Commercial	G01.5051 ALL-SIM
SIMMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/14/2019 P	TAYLOR	G01.1321 Damage Prevention During Excavation Activities by or on Behalf of the Operator	H01.1161 ALL-SIM
SIMMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/14/2019 P	TAYLOR	G01.1331 Damage Prevention Inspection During Third-Party Excavation or Encroachment Activities as Determined Necessary by the Operator	G01.1321 ALL-SIM
SIMMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/14/2019 P	TAYLOR	G01.1341 Provide or Ensure Adequate Pipeline Support During Operator-Initiated Excavation Activities	G01.1331 ALL-SIM
SIMMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/14/2019 P	TAYLOR	G01.5061 Verified the Correct Marking of Temporarily Marked Underground Pipeline Facilities	G01.1341 ALL-SIM
SIMMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/14/2019 P	TAYLOR	H01.0721 Joining of Pipe: Threaded Joints	G01.5061 ALL-SIM
SIMMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/12/2019 P	TAYLOR	H01.1171 Installing Customer Meters: Large Commercial and Industrial	H01.0721 ALL-SIM
SIMMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/13/2019 P	TAYLOR	H03.1201 Temporary Isolation of Service Lines and Service Discontinuance	H01.1171 ALL-SIM
SIMMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/13/2019 P	TAYLOR	H04.5251 Install Service Line Valves Upstream of Customer Meter	H03.1201 ALL-SIM
SIMMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/12/2019 P	TAYLOR	H07.5781 Check for Irregularities In the Condition of Meter Installations	H04.5251 ALL-SIM
SIMMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/14/2019 P	TAYLOR	H08.5791 Restore Service	H07.5781 ALL-SIM
SIMMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/13/2019 P	TAYLOR	I10.0141 Visual Inspection For Atmospheric Corrosion	H08.5791 ALL-SIM
SIMMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/12/2019 P	TAYLOR	M01.1241 Outside Gas Leak Investigation	I10.0141 ALL-SIM
SIMMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/12/2019 P	TAYLOR	M02.1291 Locate Underground Pipelines	M01.1241 ALL-POJ
SIMMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/12/2019 P	TAYLOR	M02.1301 Install and Maintain Pipeline Markers	M02.1291 ALL-POJ
SIMMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/12/2019 P	TAYLOR	M02.5101 Temporarily Mark Underground Pipeline Facilities	M02.1301 ALL-SIM
SIMMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/13/2019 P	TAYLOR	M03.0561 Pressure Test: Nonliquid Medium – MAOP Less Than 100 psi	M02.5101 ALL-POJ
SIMMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/13/2019 P	TAYLOR	M03.0571 Pressure Test: Nonliquid Medium – MAOP Greater Than or Equal to 100 psi	M03.0561 ALL-SIM
SIMMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/13/2019 P	TAYLOR	M03.0591 Leak Test at Operating Pressure	M03.0571 ALL-SIM
SIMMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/11/2019 P	TAYLOR	M07.5741 Prevent Accidental Ignition	M03.0591 ALL-SIM
SIMMS	DONALD	DRAKESBORO GAS DEPARTMENT	02/11/2019 P	TAYLOR		M07.5741 ALL-SIM

