

Incident Number: 2019086618 Incident Type: NORMAL Priority:

IC Number: 19-0000009646

Details

Received By

Received Date

Dispatched

Complaint:

GAS LEAK

Comment

THIS IS A TEST....THIS IS A TEST....

Disposition

CALL COMPLETED

DBORO GAS ADVISED "....."

Location

Call ESN: 233

ALI Address:

Location Address: 305 CHRISTIAN ST, DRAKESBORO

GIS Address:

Latitude: 37.217955735529

Landmark:

Longitude: -87.0515270825658

Caller

ALI Caller:

Location Caller: BARBARA PIPER

Raw ALI Feed

Dispatched Units

Case Number:

Status

Set Date/Time

Odometer Comments

Set By

Incident Narrative

DMOORE 3/25/2019 15:07:16 CONTACT MADE W/DBORO GAS

DMOORE 3/25/2019 15:07:23 DBORO GAS 10-97

DMOORE 3/25/2019 15:07:28 DBORO GAS 10-98

Complainants

Vehicles

Make:

Model:

Style:

Color:

Year:

Tag Number:

Tag State:

Model:

Comments:

Wreckers

Wrecker Company

Service Area

Caller Requested Responded

Call Date/Time

Radio Communications

Incident Status Log

ACTIVE

DMOORE

3/25/2019 15:06:18

1

TEST EXAMPLE SYSTEM

LEGAL NOTICES

LEGAL NOTICES

LEGAL NOTICES

LEGAL NOTICES

pliance with the rules and regulations of various agencies having jurisdiction over the District.

The flushing will begin Friday, March 1, 2019 and will continue through Sunday, March 31, 2019. Due to unforeseen problems, dates may vary.



ONLINE
WWW.KY-LEADERNEWS.COM

READ THE ENTIRE
NEWSPAPER ONLINE AS
A PDF OF EACH PAGE.

<https://www.kyschoolreportcard.com>

Kentucky continues to offer tools stand and celebrate the performance raisethebar.education.ky.gov for more suite of School Report Card tools available to schools, parents and communities. KRS 158.64 requires that the School Report Card annually be published so stakeholders can have a clear view of how the school is performing. If you need help with your school's report card, please contact...

Customer Notification

City of Drakesboro is committed to ensuring that the Natural gas lines to your home or business remain safe and reliable.

City of Drakesboro Gas owns, operates and maintains the Natural gas pipeline and facilities leading up to and including the meter of all residential and commercial customers. This maintenance includes regular inspections to ensure no leaks are present and the lines are in good condition.

You own and are responsible for all buried and above ground natural gas piping on your property that runs from the meter to the structure and other outside gas appliances as well as all piping within the structure. This is referred to as "customer piping" and must be maintained by you, the customer. If the customer piping is not properly maintained, corrosion and leaks can occur creating a hazardous condition.

To keep your home or business safe, you should monitor and properly maintain the natural gas lines that you own. Your customer piping should periodically be inspected for leaks. If the piping is metallic, it should also be inspected for corrosion. A licensed plumber or qualified technician can assist you with the inspection and maintenance of your customer piping. Any unsafe condition that is discovered should be repaired immediately.

If excavation is required, remember to call 811, the national call-before-you-dig number, to ensure that buried lines are located and marked prior to digging. When excavation is near a buried pipeline, the excavator is required to hand dig to avoid damage to the underground piping.

City of Drakesboro Gas is committed to the safe and reliable delivery of natural gas to your home or business. Please feel free to call City of Drakesboro Gas if you have any questions or need any additional information concerning your customer piping.

Contact: City of Drakesboro Gas 270-476-8986

City Drakesboro



at the request of the adjoining property owner. The noxious weeds named in this law are Johnson grass, giant foxtail, Canada thistle, nodding thistle, common teasel, multiflora rose, amur honeysuckle, poison hemlock, marehail, Japanese knotweed, and kudzu.

Property owners actively treating noxious weeds on private property may submit an application to request the eradication of nuisance weeds found on adjacent state-owned right of way. Contact your local district highway office to request an application. Visit transportation.ky.gov/contactus.

Superior, State and Juvenile
Courts
3-5pd

LEGAL NOTICES

NOTICE

Raben Tire Co. LLC,
1724 West Everly Brothers
Blvd., Central City,
Kentucky 42330, 270-754-
5100 will have for sale
April 2, 2019 the following
vehicle:

2001 Ford Windstar, Vin#
2FMZA5143&BC173390.

Owner - Hurdy
Seawright, lean holder - 231
Auto Mart, LLC. 3-19c

Notice is hereby given that the Muhlenberg County Water District #1 will be flushing hydrants in all areas of the District.

This flushing is for the benefit of the system in cleaning out the water lines, but it may cause a temporary discoloration of water. The District apologizes for any inconvenience, but does this to provide the best possible distribution system for water it can, and also to be in compliance with the rules and regulations of various agencies having jurisdiction over the District.

The flushing will begin Friday, March 1, 2019 and will continue through Sunday, March 31, 2019. Due to unforeseen problems, dates may vary.

SUBSCRIBE

ONLINE

WWW.KY-LEADERNEWS.

COM

**READ THE ENTIRE
NEWSPAPER ONLINE AS
A PDF OF EACH PAGE.**

Customer Notification

City of Drakesboro is committed to ensuring that the Natural gas lines to your home or business remain safe and reliable.

City of Drakesboro Gas owns, operates and maintains the Natural gas pipeline and facilities leading up to and including the meter of all residential and commercial customers. This maintenance includes regular inspections to ensure no leaks are present and the lines are in good condition.

You own and are responsible for all buried and above ground natural gas piping on your property that runs from the meter to the structure and other outside gas appliances as well as all piping within the structure. This is referred to as "customer piping" and must be maintained by you, the customer. If the customer piping is not properly maintained, corrosion and leaks can occur creating a hazardous condition.

To keep your home or business safe, you should monitor and properly maintain the natural gas lines that you own. Your customer piping should periodically be inspected for leaks. If the piping is metallic, it should also be inspected for corrosion. A licensed plumber or qualified technician can assist you with the inspection and maintenance of your customer piping. Any unsafe condition that is discovered should be repaired immediately.

If excavation is required, remember to call 811, the national call-before-you-dig number, to ensure that buried lines are located and marked prior to digging. When excavation is near a buried pipeline, the excavator is required to hand dig to avoid damage to the underground piping.

City of Drakesboro Gas is committed to the safe and reliable delivery of natural gas to your home or business. Please feel free to call City of Drakesboro Gas if you have any questions or need any additional information concerning your customer piping.

Contact: City of Drakesboro Gas 270-476-8986

LEADER-NEWS
P.O. BOX 471
CENTRAL CITY, KY 42330
UNITED STATES
(270)-754-3000

PAGE 1

INVOICE DATE 3/5/2019
INVOICE NO 1247461

S
O
L
D
T
O
CIT002
CITY OF DRAKESBORO
P.O. BOX 129
212 MOSE RAGER BLVD.
DRAKESBORO, KY 42337

S
H
I
P
T
O
CIT002
CITY OF DRAKESBORO
P.O. BOX 129
212 MOSE RAGER BLVD.
DRAKESBORO, KY 42337

TOTAL DUE 108.75

SLS1	SLS2	DUE DATE	DISC DUE DATE	ORDER NO	ORDER DATE	SHIP NO
		4/10/2019	4/10/2019	00150648	3/5/2019	

TERMS DESCRIPTION	CUSTOMER PO NO	SHIP VIA	SHIP DATE
10th EOM Prox			3/5/2019

ITEM ID	TX CL	UNITS	ORDERED	SHIPPED	UNIT PRICE	EXTENSION
3/5/19-CUSTOMER NOTIFICATION	0	IN	15.00	15.00	7.25	108.75

Customer

We appreciate your business.

TAXABLE	NONTAXABLE	FREIGHT	SALES TAX	MISC	TOTAL
0.00	108.75	0.00	0.00	0.00	108.75
TOTAL DUE					108.75

STATEMENT

LEADER-NEWS
 P.O. BOX 471
 CENTRAL CITY, KY 42330
 UNITED STATES
 (270)-754-3000

PAGE 1
DATE 3/31/2019
ACCOUNT NO CIT002

ATTN: CITY OF DRAKESBORO
 P.O. BOX 129
 212 MOSE RAGER BLVD.
 DRAKESBORO, KY 42337

AMOUNT DUE 108.75
TERMS 10th EOM Prox

Payment accepted by cash, check, VISA or Mastercard.
 All collection fees, attorney fees, and/or court costs of unresolved
 accounts is the customer's responsibility.

INVOICE DATE	INVOICE NO	TYPE	PO/CHECK NO	CHARGES	CREDITS	BALANCE
3/5/2019	1247461	Inv		108.75	0.00	108.75

WE APPRECIATE YOUR BUSINESS!

Activity after 3/31/2019 will be reflected on your next statement.

YTD Finance Charges added to your account		New Finance Charges				0.00
CURRENT	31 - 60 DAYS	61 - 90 DAYS	OVER 90 DAYS	FINANCE CHARGE	AMOUNT DUE	
108.75	0.00	0.00	0.00	0.00	108.75	

To avoid additional charges pay by Closing Date 4/10/2019

DRAKESBORO WORK ORDER

Work Order #: _____

DATE: 2/21/19 Time: 1:29 Gas Water WW Acct #: _____

NAME: Kaitlyn Knight Meter Number: _____

ADDRESS: 100 Harpers Circle D'boro

WORK TO BE DONE:

270-820-3052

NEW METER # _____ NEW READING _____

TURN ON & READ _____ OLD READING _____

READ and LOCK _____ SET METER and LOCK _____

READING ONLY _____ LOCATE LINE _____ (SEE BELOW)

READ and LOCK (NON PAYMENT) _____ GET METER NUMBER _____

CHECK PRESSURE _____ FLUSH LINE _____ CHECK f. LEAK _____

UNLOCK ONLY and READ (DO NOT TURN ON) _____

SPECIAL INSTRUCTIONS: Meter has been installed but

Still smelling gas

Called Bart

(outside underground leak BCL)

2-21-19

WORK DONE:

FLUSHED: Yes No GPM: _____ How Long: _____ Water Loss: _____

WATER LEAK: Yes No GPM: _____ How Long: _____ Water Loss: _____

PARTS USED TO COMPLETE JOB:

COMMENTS: Gas Leak is under road. Going to have to dig up road. Going to try to fix weekend of 23rd, 24th. Jason + Eddie to dig up on Sat 23rd.

WORK COMPLETED BY: _____ DATE COMPLETED: _____

TIME STARTED: _____ TIME FINISHED: _____

DRAKESBORO WORK ORDER

Work Order #: _____

DATE: 3-18-19

Time: _____

Gas

Water

WW .. Acct #: _____

NAME: Katlyn Knight

Meter Number: _____

ADDRESS: Harper Circle.

WORK TO BE DONE:

NEW METER # _____ NEW READING _____

TURN ON & READ _____ OLD READING _____

READ and LOCK _____ SET METER and LOCK _____

READING ONLY _____ LOCATE LINE (SEE BELOW)

READ and LOCK (NON PAYMENT) _____ GET METER NUMBER _____

CHECK PRESSURE _____ FLUSH LINE _____ CHECK f. LEAK _____

UNLOCK ONLY and READ (DO NOT TURN ON) _____

SPECIAL INSTRUCTIONS: Previous Crew found leak on Harper Circle and vented it. Went back to dig it back up and fix.

WORK DONE:

FLUSHED: Yes No GPM: _____ How Long: _____ Water Loss: _____

WATER LEAK: Yes No GPM: _____ How Long: _____ Water Loss: _____

PARTS USED TO COMPLETE JOB:

Bolts for Clamp

COMMENTS: Upon digging previous dig back out, previous crew never found the leak. Dug up more blacktop and found leaking clamp. Replaced all the bolts and repaired the leak.

WORK COMPLETED BY: Bill D DATE COMPLETED: 3-18-19


TIME STARTED: 12:00 pm TIME FINISHED: 3:45 pm

VISUAL INSPECTION OF MAINS AND SERVICE PIPELINES

Address: 100 Harper Circle Location: Front of Property/End of driveway

PIPE TYPE	CONDITION	COMPOSITION	COATING/TREATMENT
Steel	✓ Excellent	✓ Localized	✓ Millwrap
PE	Good	General	Enamel
Cast Iron	Slight Pitting	Other	Roskote
CSST	Extreme Pitting	Pitting Depth	Oxidemp
Main	Hole/Voids		Xtrucoat
Service	Graphitization		Mastic
Other	Bent		Cold Roll
	Broken		Hot Wrap
	Other		Heat Shrink
COATING CONDITION	SOIL TYPE	SOIL COMPOSITION	COATING TYPE
Good	✓ Rock	✓ Dry	✓ Main Extension
Poor	Cinder	Wet/Swampy	Service Tap
Damaged	Clay	Normal	Leak Repair
Other	Loam	✓ Moisture Range (3-5)	Re-routing
	Sand	Moisture Range (5-8)	Third Party
	Alluvion		Abandonment
	Other		Deactivation
			Utility Theft
			Other

Description/Comments:



Name: Donald Sims Date: 3-18-19

DRAKESBORO WORK ORDER

Work Order #: _____

DATE: 2-2-2019 Time: 9:30am Gas Water WW Acct #: _____

NAME: Jerrold Henderson reported Meter Number: _____

ADDRESS: @ 3190 431 Beechmont Ky

WORK TO BE DONE:

NEW METER # _____ NEW READING _____

TURN ON & READ _____ OLD READING _____

READ and LOCK _____ SET METER and LOCK _____

READING ONLY _____ LOCATE LINE (SEE BELOW) _____

READ and LOCK (NON PAYMENT) _____ GET METER NUMBER _____

CHECK PRESSURE _____ FLUSH LINE _____ CHECK f. LEAK _____

UNLOCK ONLY and READ (DO NOT TURN ON) _____

SPECIAL INSTRUCTIONS:

Jerrold Henderson - make no water
Smells a gas leak

WORK DONE:

FLUSHED: Yes No GPM: _____ How Long: _____ Water Loss: _____

WATER LEAK: Yes No GPM: _____ How Long: _____ Water Loss: _____

PARTS USED TO COMPLETE JOB:

COMMENTS:

Gas leak has been found, dug up, and
ph 270-225-0712 vented weeks ago. Preparations for
grade of leak outside contractor to cap at main have
been made. Re-Satisfied still grade 2. No property damage

WORK COMPLETED BY: Jordan & Joe DATE COMPLETED: 3-2-19


TIME STARTED: 9:30am 3-2-2019 TIME FINISHED: 9:50 am

Del S

VISUAL INSPECTION OF MAINS AND SERVICE PIPELINES

Address	3190 US 431 S		Location	Left/Front Yard	
TYPE	CONDITION	CORROSION	COATING TYPE		
Steel ✓	✓ Excellent	Localized	✓	Millwrap	✓
PE	Good	✓ General		Enamel	
Cast Iron	Slight Pitting	✓ Other		Roskote	
CSST	Extreme Pitting	Pitting Depth		Oxidemp	
Main	✓ Hole/Voids			Xtrucoat	
Service	Graphitization			Mastic	
Other	Bent			Cold Roll	
	Broken			Hot Wrap	
	Other			Heat Shrink	

COATING CONDITION	SOIL TYPE	SOIL RESISTANCE	OTHER FACTORS		
Good	✓ Rock	Dry	✓	Main Extension	
Poor	Cinder	Wet/Swampy		Service Tap	
Damaged	Clay	✓ Normal	✓	Leak Repair	✓
Other	Loam	✓ Moisture Range (3-5)		Re-routing	
	Sand	Moisture Range (5-8)		Third Party	
	Alluvion			Abandonment	
	Other			Deactivation	
				Utility Theft	
				Other	



Name: **Donald Sims** Date: **4-1-19**

DRAKESBORO WORK ORDER

Work Order #: _____

DATE: 3-18-19 Time: _____ Gas Water WW .. Acct #: _____

NAME: _____ Meter Number: _____

ADDRESS: 3190 US 431 S. Beechmont Ky.

WORK TO BE DONE:

NEW METER # _____ NEW READING _____
TURN ON & READ _____ OLD READING _____
READ and LOCK _____ SET METER and LOCK _____
READING ONLY _____ LOCATE LINE (SEE BELOW) _____
READ and LOCK (NON PAYMENT) _____ GET METER NUMBER _____
CHECK PRESSURE _____ FLUSH LINE _____ CHECK f. LEAK _____
UNLOCK ONLY and READ (DO NOT TURN ON) _____

SPECIAL INSTRUCTIONS: Previous crew dug up but did not locate leak. Today we dug up the main and tap for service. Found a pin hole leak on service line. Used a clamp and stoped leak. Then wrapped pipe in pipe tape.

WORK DONE:


FLUSHED: Yes No GPM: _____ How Long: _____ Water Loss: _____
WATER LEAK: Yes No GPM: _____ How Long: _____ Water Loss: _____

PARTS USED TO COMPLETE JOB:

1" x 6" clamp.
Pipe Tape.

COMMENTS: _____

WORK COMPLETED BY: [Signature] DATE COMPLETED: 3-18-19
TIME STARTED: 12:30 PM TIME FINISHED: 3:00 PM



U.S. 431 South

Drive way

Ditch

30ft.

Main

Tap 4 1/2" deep service

Leak clamp

16 inches from tap to where leak was

Tree

Tree


15 ft from corner

House

3190

US 431 S.

Drakesboro's Five Year Survey Plan



Section 1 of Leak Survey completed
 Section 2 of Leak Survey completed
 Section 3 of Leak Survey completed

Copyright © and (P) 1988-2008 Microsoft Corporation and/or its suppliers. All rights reserved. <http://www.microsoft.com/street/>
 Certain mapping and direction data © 2008 NAVTEQ. All rights reserved. The Data for areas of Canada includes information taken with permission from Canadian authorities, including: © Her Majesty the Queen in Right of Canada © Queen's Printer for Ontario, NAVTEQ and NAVTEQ ON BOARD are trademarks of NAVTEQ. © 2008 Tele Atlas North America, Inc. All rights reserved. Tele Atlas and Tele Atlas North America are trademarks of Tele Atlas, Inc. © 2008 by Applied Geographic Systems. All rights reserved.