

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: Dralesboro Utilities

Period Covered: Began 4-22-21 Ended 4-22-21

Areas Covered: Ditch on 431 Behind W & B HVAC

Map References: N/A

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):  
No Leaks Found

Describe any unusual conditions at highway and railroad crossings: N/A

Other Factors noted which could affect present or future safety or operations of the gas system:  
2" Steel Low Pressure Main Crossing a ditch  
Main is exposed for about 44' at 23" inches deep -

Follow-up (repairs, maintenance or test resulting from this inspection):  
Main has been cleaned & wrapped to prevent  
any corrosion. Section is checked often.

Comments: \_\_\_\_\_

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: [Signature]

Date: 4-22-21