

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 6/7/21 Ended 6/7/21

Areas Covered: DITCH NEXT TO OLD DOLLAR STORE

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):
NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:
4" STEEL MAIN EXPOSED IN DITCH, DID ATTEMPT TO COVER WITH ROCK/CONCRETE. PART HAS BEEN WASHED AWAY DUE TO FLOOD

Follow-up (repairs, maintenance or test resulting from this inspection): _____

Comments: TRYING TO SCHEDULE PROPER REPAIR TO STOP WATER REMOVING COVER

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: B. Allen

Date: 6/7/21