

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 6/27/22 Ended 6/27/22

Areas Covered: DITCH LINE @ 431/WESTER ST.

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:

2" STEEL LINE

Follow-up (repairs, maintenance or test resulting from this inspection): _____

Comments: AREA IS MONITORED W/ C.G.I

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: By Alced

Date: 6/27/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 6/27/22 Ended 6/27/22

Areas Covered: DITCH @ W/R HVAC/431

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:

2" STEEL LINE

Follow-up (repairs, maintenance or test resulting from this inspection):

LINE IS WRAPPED WITH MILL TAPE

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: B. Alled

Date: 6/27/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 6/27/22 Ended 6/27/22

Areas Covered: DITCH NEXT TO OLD DOLLAR STORE
431

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:
4" GAS MAIN CROSSING DITCH LINE

Follow-up (repairs, maintenance or test resulting from this inspection): _____

Comments: PIPE IS PROTECTED W/ P.V.C AND RIP RAP

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: By Allied

Date: 6/27/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 6/27/22 Ended 6/27/22

Areas Covered: 322 Hwy 176

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):
NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:
LINE IS MONITORED DAILY WITH C.G.I

Follow-up (repairs, maintenance or test resulting from this inspection): _____

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: B. Alford

Date: 6/27/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 6/27/22 Ended 6/27/22

Areas Covered: 315 HAZEL CREEK

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):
NO LEAKS FOUND

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:
SERVICE TAP SLIGHTLY EXPOSED

Follow-up (repairs, maintenance or test resulting from this inspection): _____

Comments: HAS BEEN COVERED WITH RIP RAP WITH PLANS BEING MADE TO REROUTE LINE

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: B. Alled

Date: 6/27/22