

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: DZAKESBORO UTILITIES

Period Covered: Began 7/8/21 Ended 7/8/21

Areas Covered: DITCH @ 431 S. NEXT TO OLD DOLLAR STORE

Map References: \_\_\_\_\_

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):  
NO LEAKS FOUND

Describe any unusual conditions at highway and railroad crossings: \_\_\_\_\_

Other Factors noted which could affect present or future safety or operations of the gas system:  
4" STEEL GAS LINE EXPOSED @ DITCH  
COVERED WITH ROCK/CONCRETE

Follow-up (repairs, maintenance or test resulting from this inspection): \_\_\_\_\_

Comments: LOOKING FOR BEST WAY TO REPAIR AND KEEP  
FROM WASHING OUT DUE TO FLOOD WATER

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: B. Alford

Date: 7/9/21