

PATROLLING OF PIPELINE SYSTEM

FORM

COMPANY: City of Drakesboro

Period Covered: Began 7-11-19 1:20 pm Ended 2:00 pm

Areas Covered: Wyatt's Chapel Cemetery Rd.

Map References: N/A

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):  
No Leak Found

Describe any unusual conditions at highway and railroad crossings: None

Other Factors noted which could affect present or future safety or operations of the gas system:  
1/2" PE Pipe/service line, exposed in ditch line  
~~at~~ 3 spots, close to each other, about 10' in  
each spot exposed.

Follow-up (repairs, maintenance or test resulting from this inspection):  
Plans have been made for covering exposed  
pipe.

Comments: \_\_\_\_\_

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: Dawn [Signature]

Date: 7-11-19

PATROLLING OF PIPELINE SYSTEM

FOR

COMPANY: City of Drakesboro

Period Covered: Began 7-11-19 1:00pm Ended 7-11-19 1:20pm

Areas Covered: Wyatt's Chapel Cemetery Rd.

Map References: N/A

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation)  
No Leak Found

Describe any unusual conditions at highway and railroad crossings: None

Other Factors noted which could affect present or future safety or operations of the gas system:  
2" PE Pipe exposed in ditch line. 18" section. 32" Deep.

Follow-up (repairs, maintenance or test resulting from this inspection):

Comments: Plans have been made to cover exposed pipe.

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: Dawn Soto

Date: 7-11-19

PATROLLING OF PIPELINE SYSTEM

FORM

COMPANY: City of Drakesboro

Period Covered: Began 2:15 pm Ended 2:25 pm

Areas Covered: Union Ridge Rd Expose #1

Map References: N/A

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):  
NO Leak Found

Describe any unusual conditions at highway and railroad crossings: None

Other Factors noted which could affect present or future safety or operations of the gas system:  
1 1/4 Poly pipe exposed in ditch line. Approximately 27 inches exposed. 37 inches down.

Follow-up (repairs, maintenance or test resulting from this inspection):

Comments:

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: Dave So

Date: 7-11-19

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: City of Drakeboro

Period Covered: Began \_\_\_\_\_ Ended \_\_\_\_\_

Areas Covered: Union Ridge Road Exposure #2

Map References: N/A

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

No Leaks Detected

Describe any unusual conditions at highway and railroad crossings: None

Other Factors noted which could affect present or future safety or operations of the gas system:

1/4 poly pipe exposed in ditch here. About 3 1/2 foot exposed. And about 4/9 inches down. This is caused by water flow through a tile wash out.

Follow-up (repairs, maintenance or test resulting from this inspection):

Comments:

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: [Signature]

Date: 7-11-19

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: City of Drakeboro

Period Covered: Began \_\_\_\_\_ Ended \_\_\_\_\_

Areas Covered: US. 431 S, Drakeboro, Ky

Map References: N/A

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):  
No Leaks found.

Describe any unusual conditions at highway and railroad crossings: None

Other Factors noted which could affect present or future safety or operations of the gas system:

2" steel main exposed in a ditch, 2 in steel comes out of one bank, crossed the ditch, and into the bank on the other side. Main should have been buried deeper. 23 inches deep.

Follow-up (repairs, maintenance or test resulting from this inspection):

Main has been wrapped and is constantly being checked, and repairs are being drawn up to perform the task.

Comments: \_\_\_\_\_

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: [Signature]

Date: 7-11-19