

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 7/15/22 Ended 7/15/22

Areas Covered: DITCH LINE AT 431 S WESTER ST

Map References: \_\_\_\_\_

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS

Describe any unusual conditions at highway and railroad crossings: \_\_\_\_\_

Other Factors noted which could affect present or future safety or operations of the gas system:

2" STEEL LINE CROSSING DITCH

Follow-up (repairs, maintenance or test resulting from this inspection): \_\_\_\_\_

Comments: AREA IS MONITORED 2X A WEEK

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: By Alled

Date: 7/15/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 7/15/22 Ended 7/15/22

Areas Covered: DITCH @ 431 S/W 3R HVAC

Map References: \_\_\_\_\_

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS

Describe any unusual conditions at highway and railroad crossings: \_\_\_\_\_

Other Factors noted which could affect present or future safety or operations of the gas system:

2" STEEL LINE

Follow-up (repairs, maintenance or test resulting from this inspection): \_\_\_\_\_

LINE IS MIL WRAPPED

Comments: \_\_\_\_\_

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: By Alled

Date: 7/15/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBURG

Period Covered: Began 7/15/22 Ended 7/15/22

Areas Covered: DITCH NEXT TO OLD DOLLAR STORE  
431/ARNOLD ST

Map References: \_\_\_\_\_

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Describe any unusual conditions at highway and railroad crossings: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Other Factors noted which could affect present or future safety or operations of the gas system:

4" GAS MAIN CROSSING DITCH LINE

Follow-up (repairs, maintenance or test resulting from this inspection): \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Comments: PIPE IS PROTECTED w/ P.V.C. & RIP RAP

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: [Signature]

Date: 7/15/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 7/15/22

Ended 7/15/22

Areas Covered: 322 Hwy 176

Map References: \_\_\_\_\_

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS

Describe any unusual conditions at highway and railroad crossings: \_\_\_\_\_

Other Factors noted which could affect present or future safety or operations of the gas system:

LINE IS MONITORED 2X WEEK WITH C.G.I

Follow-up (repairs, maintenance or test resulting from this inspection): \_\_\_\_\_

Comments: \_\_\_\_\_

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: Bj Alced

Date: 7/15/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 7/15/22 Ended 7/15/22

Areas Covered: 315 HAZEL CREEK

Map References: \_\_\_\_\_

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS DETECTED

Describe any unusual conditions at highway and railroad crossings: \_\_\_\_\_

Other Factors noted which could affect present or future safety or operations of the gas system:

SERVICE TAP SLIGHTLY EXPOSED @ DITCH SIDE

Follow-up (repairs, maintenance or test resulting from this inspection): \_\_\_\_\_

Comments: COVERED WITH RIP RAP FOR PROTECTION

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: By Almad

Date: 7/15/22