

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBOIZO

Period Covered: Began 7/26/21 Ended 7/26/21

Areas Covered: DITCH LINE ON 431 NEXT TO OLD DOLLAR STORE

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAK DETECTED

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:

4" EXPOSED GAS LINE CROSSING DITCH
COVERED WITH ROCK/CONCRETE

Follow-up (repairs, maintenance or test resulting from this inspection): _____

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: By Alced

Date: 7/26/21

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBURG

Period Covered: Began 7/26/21 Ended 7/26/21

Areas Covered: DITCH LINE ACROSS FROM DOLLAR STORE
NEXT TO FARRIS TRAILER SALES

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS FOUND

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:

2" EXPOSED GAS LINE (STEEL) CROSSING DITCH LINE
18" OFF GROUND LEVEL

Follow-up (repairs, maintenance or test resulting from this inspection): _____

TRYING TO DETERMINE BEST WAY TO PROTECT
PIPE

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: B. Alled

Date: 7/26/21

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 7/26/21 Ended 7/26/21

Areas Covered: 431 SOUTH NEXT TO W/R HEATING & COOLING

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS FOUND

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:

2" STEEL MAIN CROSSING DITCH

Follow-up (repairs, maintenance or test resulting from this inspection): _____

LINE IS WRAPPED WITH WAX TAPE

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: Bj Alled

Date: 7/26/21