

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 8/26/21 Ended 8/26/21

Areas Covered: DITCH LINE ON 431 NEXT TO OLD DOLLAR STORE

Map References: \_\_\_\_\_

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):  
NO LEAKS FOUND

Describe any unusual conditions at highway and railroad crossings: \_\_\_\_\_

Other Factors noted which could affect present or future safety or operations of the gas system:  
4" GAS MAIN CROSSES DITCH. LINE HAS BEEN SECURED WITH RIFF RAF / CONCRETE.

Follow-up (repairs, maintenance or test resulting from this inspection): \_\_\_\_\_

Comments: \_\_\_\_\_

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: By Alled

Date: 8/26/21

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 8/26/21 Ended 8/26/21

Areas Covered: DITCH ACROSS FROM DOLLAR STORE ON  
431

Map References: \_\_\_\_\_

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):  
NO LEAKS

Describe any unusual conditions at highway and railroad crossings: \_\_\_\_\_

Other Factors noted which could affect present or future safety or operations of the gas system:  
2" GAS LINE (STEEL) CROSSING DITCH  
18" OFF GROUND

Follow-up (repairs, maintenance or test resulting from this inspection): TRYING TO  
FIND BEST WAY TO PROTECT LINE

Comments: \_\_\_\_\_

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: Bj Alled

Date: 8/26/21

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 8/26/21 Ended 8/26/21

Areas Covered: 431 SOUTH DITCH LINE NEXT TO  
W/R HEATING / COOLING

Map References: \_\_\_\_\_

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):  
NO LEAKS

Describe any unusual conditions at highway and railroad crossings: \_\_\_\_\_

Other Factors noted which could affect present or future safety or operations of the gas system:  
2" STEEL LINE CROSSING DITCH

Follow-up (repairs, maintenance or test resulting from this inspection): LINE IS  
PROTECTED WITH WAX WRAP

Comments: \_\_\_\_\_

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: B. Allen

Date: 8/26/21