

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 8/11/22

Ended 8/11/22

Areas Covered: DITCH @ 431/WESTER

Map References: \_\_\_\_\_

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS

Describe any unusual conditions at highway and railroad crossings: \_\_\_\_\_

Other Factors noted which could affect present or future safety or operations of the gas system:

2" STEEL LINE CROSSING DITCH

Follow-up (repairs, maintenance or test resulting from this inspection): \_\_\_\_\_

Comments: MONITORED 2x WEEK WITH C.G.I

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: By Alled

Date: 8/11/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 8/11/22 Ended 8/11/22

Areas Covered: DITCH @ 431 / W&R HEAT COOL

Map References: \_\_\_\_\_

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS

Describe any unusual conditions at highway and railroad crossings: \_\_\_\_\_

Other Factors noted which could affect present or future safety or operations of the gas system:

2" STEEL MAIN

Follow-up (repairs, maintenance or test resulting from this inspection): \_\_\_\_\_

LINE IS MIL WRAPPED

Comments: \_\_\_\_\_

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: R. Allen

Date: 8/11/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 8/11/22 Ended 8/11/22

Areas Covered: DITCH @ OLD DOLLAR STORE / 431 / ARNOLD

Map References: \_\_\_\_\_

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Describe any unusual conditions at highway and railroad crossings: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Other Factors noted which could affect present or future safety or operations of the gas system:  
4" GAS MAIN (STEEL)  
\_\_\_\_\_  
\_\_\_\_\_

Follow-up (repairs, maintenance or test resulting from this inspection): \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Comments: PIPE IS P.V.C. ENCASED AND RIP RAP / CONCRETE  
\_\_\_\_\_  
\_\_\_\_\_

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: [Signature]

Date: 8/22/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 8/11/22 Ended 8/11/22

Areas Covered: 322 Hwy 170

Map References: \_\_\_\_\_

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):  
NO LEAKS

Describe any unusual conditions at highway and railroad crossings: \_\_\_\_\_

Other Factors noted which could affect present or future safety or operations of the gas system:  
OLD SERVICE RISER HAD LEAK. FOUND LEAK AND HAS BEEN CAPPED

Follow-up (repairs, maintenance or test resulting from this inspection):  
REPAIR IS MONITORED DAILY WITH C.G.I

Comments: \_\_\_\_\_

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: By Alled

Date: 8/11/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 8/11/22 Ended 8/11/22

Areas Covered: 315 HAZEL CREEK RD.

Map References: \_\_\_\_\_

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

Describe any unusual conditions at highway and railroad crossings: \_\_\_\_\_

NO LEAKS

Other Factors noted which could affect present or future safety or operations of the gas system:

SEWICE TAP SLIGHTLY EXPOSED IN DITCH

Follow-up (repairs, maintenance or test resulting from this inspection):

TAP IS COVERED WITH RIP RAP FOR PROTECTION  
UNTIL PERMANENT FIX IS MADE

Comments: \_\_\_\_\_

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: B. Almad

Date: 8/11/22