

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 9/8/22 Ended 9/8/22

Areas Covered: DITCH @ 4315/WESTER DR.

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:

2" STEEL LINE CROSSING DITCH

Follow-up (repairs, maintenance or test resulting from this inspection): _____

Comments: LINE IS MONITORED 2X A WEEK

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: By Alled

Date: 9/8/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 9/8/22 Ended 9/8/22

Areas Covered: _____

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS DETECTED

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:

2" STEEL MAIN

Follow-up (repairs, maintenance or test resulting from this inspection): _____

LINE IS MIL WRAPPED

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: By Allied

Date: 9/8/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 9/8/22 Ended 9/8/22

Areas Covered: DITCH NEXT TO OLD DOLLARS STORE
4315 / ARNOLD RD.

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):
NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:
4" GAS MAIN

Follow-up (repairs, maintenance or test resulting from this inspection): _____

Comments: PIPE IS PROTECTED WITH P.V.C AND Rip Rap

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: By Alsed

Date: 9/8/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 9/8/22 Ended 9/8/22

Areas Covered: 322 HWY 176

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:

OLD SERVICE LINE LEAKING. HAS BEEN REPAIRED

Follow-up (repairs, maintenance or test resulting from this inspection):

LINE IS MONITORED 1X MONTH

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: R. Almad

Date: 9/8/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 9/8/22 Ended 9/8/22

Areas Covered: 315 HAZEL CREEK RD.

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:

EXPOSED SERVICE TAP

Follow-up (repairs, maintenance or test resulting from this inspection):

TAP HAS BEEN COVERED.

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: Bj Allen

Date: 9/8/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 9/8/22 Ended 9/8/22

Areas Covered: 404 BEECH CREEK RD.

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:

SERVICE LINE HIT

Follow-up (repairs, maintenance or test resulting from this inspection): LINE HAS BEEN CAPPED

Comments: AREA MONITORED 2x MONTH WITH C.G.I

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: Bj Alled

Date: 9/8/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 9/8/22 Ended 9/8/22

Areas Covered: COUNTY DUMP SITE 431'S/22 TO BEECHMON'S

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:

OLD SERVICE LINE WAS FOUND WITH SMALL LEAK

Follow-up (repairs, maintenance or test resulting from this inspection):

LINE HAS BEEN REPAIRED UNTIL PERMEMENT FIX IS MADE

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: B. Alled

Date: 9/8/22