



City of Drakesboro

Natural Gas Reports

Weekly Sniff Tests

<u>Date</u>	<u>Location</u>	<u>Reading</u>	<u>Operator Signature</u>
10/7/22	5499 HWY 176 DRORO	.361.25	B. Alled
10/7/22	3388 MERLE TRAVIS	.31/.25	
10/7/22	925 UNION RIDGE	.32/.25	
10/7/22	2 RIVERS 7158 HWY 70	.38/.25	
10/31/22	5499 HWY 176 DRORO	.34/.25	
10/31/22	3388 MERLE TRAVIS	.39/.25	
10/31/22	925 UNION RIDGE	.30/.25	
10/31/22	2 RIVERS 7158 HWY 70	.40/.33	

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 10/14/22 Ended 10/14/22

Areas Covered: DITCH LINE @ 431 / OLD DOLLAR STORE

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:

4" STEEL GAS MAIN ENCASED IN P.V.C / RIP RAP FOR PROTECTION

Follow-up (repairs, maintenance or test resulting from this inspection): _____

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: B. Alled

Date: 10/14/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 10/14/22 Ended 10/14/22

Areas Covered: DITCH @ WESTER ST./431

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:

2" STEEL LINE

Follow-up (repairs, maintenance or test resulting from this inspection): _____

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: [Signature]

Date: 10/14/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 10/14/22 Ended 10/14/22

Areas Covered: DITCH @ 431 NEXT TO W&R HEAT

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:

2" STEEL LINE @ DITCH LINE

Follow-up (repairs, maintenance or test resulting from this inspection): _____

Comments: LINE IS MIL WRAPPED

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: B. Alford

Date: 10/14/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 10/14/22 Ended 10/14/22

Areas Covered: HAZEL CREEK RD

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system:

SERVICE TAP IN DITCH SIDE COVERED WITH
KIP RAP FOR PROTECTION

Follow-up (repairs, maintenance or test resulting from this inspection): _____

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: By Alled

Date: 10/14/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 10/14/22 Ended 10/14/22

Areas Covered: 1760 DRAKESBORO

Map References: _____

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS

Describe any unusual conditions at highway and railroad crossings: _____

Other Factors noted which could affect present or future safety or operations of the gas system: _____

Follow-up (repairs, maintenance or test resulting from this inspection):

LINE WAS REPAIRED AND IS MONITORED 2x MONTH

Comments: _____

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: [Signature]

Date: 10/14/22