

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 11/30/22 Ended 11/30/22

Areas Covered: 318 MOSE DAGER

Map References: \_\_\_\_\_

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS

Describe any unusual conditions at highway and railroad crossings: \_\_\_\_\_

Other Factors noted which could affect present or future safety or operations of the gas system:

LINE WAS STRUCK AND HAS BEEN CAPPED

Follow-up (repairs, maintenance or test resulting from this inspection): \_\_\_\_\_

REPAIR IS CHECKED 2X MONTH

Comments: \_\_\_\_\_

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: [Signature]

Date: 11/30/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 11/30/22

Ended 11/30/22

Areas Covered: HAZEL CREEK RD

Map References: \_\_\_\_\_

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS

Describe any unusual conditions at highway and railroad crossings: \_\_\_\_\_

Other Factors noted which could affect present or future safety or operations of the gas system:

SERVICE TAP SLIGHTLY EXPOSED

Follow-up (repairs, maintenance or test resulting from this inspection):

TAP IS COVERED WITH RIP RIP FOR PROTECTION

Comments: \_\_\_\_\_

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: By Almad

Date: 11/30/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 11/30/22 Ended 11/30/22

Areas Covered: DITCH LINE @ 431 / OLD DOLLARS STORE

Map References: \_\_\_\_\_

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):

NO LEAKS

Describe any unusual conditions at highway and railroad crossings: \_\_\_\_\_

Other Factors noted which could affect present or future safety or operations of the gas system:

4" GAS MAIN CROSSES DITCH LINE  
MAIN LINE IS ENCASED IN P.V.C. AND COVERED WITH  
RIP RAP / CONCRETE

Follow-up (repairs, maintenance or test resulting from this inspection): \_\_\_\_\_

Comments: \_\_\_\_\_

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: Bj Alled

Date: 11/30/22

PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 11/30/22 Ended 11/30/22

Areas Covered: DITCH LINE @ 431 / WESTER ST.

Map References: \_\_\_\_\_

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):  
NO LEAKS

Describe any unusual conditions at highway and railroad crossings: \_\_\_\_\_

Other Factors noted which could affect present or future safety or operations of the gas system:  
2" STEEL LINE CROSSING DITCH

Follow-up (repairs, maintenance or test resulting from this inspection): \_\_\_\_\_

Comments: \_\_\_\_\_

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: B. Alled

Date: 11/30/22



PATROLLING OF PIPELINE SYSTEM

FORM 4

COMPANY: CITY OF DRAKESBORO

Period Covered: Began 11/30/22 Ended 11/30/22

Areas Covered: DITCH LINE @ 431 / W3R HEATING

Map References: \_\_\_\_\_

Leakage Indications Discovered (describe locations and indications, such as a condition of vegetation):  
NO LEAKS

Describe any unusual conditions at highway and railroad crossings: \_\_\_\_\_

Other Factors noted which could affect present or future safety or operations of the gas system:  
2" STEEL LINE CROSSING

Follow-up (repairs, maintenance or test resulting from this inspection):  
LINE IS MIL WRAPPED

Comments: \_\_\_\_\_

Number of Persons in Patrol Party: 2

Signature of Person in Charge of Patrol Party: [Signature]

Date: 11/30/22