

GCLWA Feb 2020

ITEM	QTY	ITEM	QTY	DATE
<b>DRESSERS</b>		<b>SADDLES BRASS TAPPING</b>		
3/4 X 3/4 CTS X CTS		2" X 3/4"		
3/4 CTS X 1 CTS		2" X 1"		
3/4 X 3/4 PVC		3" X 1"		<b>DISTRICT</b>
3/4 CTS X 1" PVC		3" X 3/4"		
1" X 1" CTS		4" X 3/4"		
1" X 1" PVC		4" X 1"		
3/4 MALE		4" X 2"		<b>OTHER MATERIAL USED</b>
3/4 FEMALE		6" X 3/4"		
<b>ADAPTERS 90 FOR STOPS</b>		6" X 1"		#2 UN: Flange - GAC
3/4"		6" X 2"		6' DI Pipe
1"		8" X 3/4"		1540x6 = 9240
<b>CLAMPS</b>		8" X 1"		March
2"		8" X 2"		
3"		<b>SADDLE CAST IRON TAPPING</b>		
4"		3" X 3/4"		22 hrs
6"		3" X 1"		Repair + Zach
8"		3" X 2"		62 miles
10"		4" X 3/4"		
CORP STOPS 3/4		4" X 1"		
CORP STOPS 1"		4" X 2"		
CORP STOPS 2"		6" X 3/4"		
<b>HYMAX COUPLINGS</b>		6" X 1"		
2"		6" X 2"		
3"		8" X 3/4"		
4"		8" X 1"		
6"	11	10" X 3/4"		
8"		10" X 1"		
10"		<b>SADDLES COPPER TAPPING</b>		
COUPLINGS 2 BOLT		SLEEVES 4" CL		
CURVE VALVES 3/4		SLEEVES 6" CL		
CURVE VALVES 1"		SLEEVES 8" CL		
CURVE VALVES 2"		SLEEVES 10 & 12"		
FIRE HYDRANTS		TEES 2", 4", 6", 8"		
FIRE HYDRANTS FLUSH		VALVE BOX COMPLETE		
METER TOPS/LIDS		VALVES 2"		
CAST IRON		VALVES 4"		
PLASTIC		VALVES 6"		
METER ELLS		VALVES 8"		
3/4"		VALVES 10"		
1"				
<b>METER YOKE SWIVEL NUTS</b>				
PVC MTR NUTS				
CTS MTR NUTS				
<b>METER YOKE</b>				
3/4"				
1"				
METER RIM & COVER				
<b>METER WELLS</b>				
PLASTIC	1			
CONCRETE				
METER TOKE TAIL PCS CTS				
METER YOKE TAIL PCS PVC				

System: 3/11/2020 2:17:25 PM  
 User Date: 3/11/2020

Mayfield EWS  
 TRANSACTION POSTING JOURNAL  
 Inventory Control

Page: 1  
 User ID: kmcadoo

Batch ID: WM0311200710216 Comment: WORKS Item Activity 3/11/2020 2:16 PM  
 Frequency: Single Use GL Posting Date: 3/11/2020  
 Trx Total- Actual: 1 Control: 0  
 Qty Total- Actual: 3.00000 Control: 0.00000

Audit Trail Code: IVADJ00000533

Document Number	Document Date	GL Posting Date	Document Type			
Item Number	U of M	Quantity	Site	Unit Cost	Extended Cost	
Description	Reason Code	Inventory Account	Offset Account			
Serial/Lot Number	Quantity					
IC031120071021619	3/11/2020	3/11/2020	Adjustment			
000430	EA	-2 01		\$211.27000	\$422.54	
COUPLINGS HYMAX - 8IN				1332-WT -131000-1000	1332-915-502789-9000	
000745	EA	-1 01		\$45.00000	\$45.00	
PLASTIC MTR WELLS				1332-WT -131000-1000	1332-915-502789-9000	

Total Items: 2

Total Documents: 1

WATER DISTRICT JOB FORM

GCWLD

Date 2-13-2020

Water District Hickory

Address or location of problem St Rt 945

Description of problem Leak Detection

Materials used to fix problem #56

25 miles

Time spent on job including travel time 4hr 1 man

WATER DISTRICT JOB FORM

GCWID

Date 2-14-2020

Water District HK

Address or location of problem \_\_\_\_\_

Description of problem Leak detection

Materials used to fix problem truck 56

Time spent on job including travel time 2hr 20 miles Eddy, Arizon

WATER DISTRICT JOB FORM

GCWLD

Date 2-11-2020

Water District Hickory

Address or location of problem St Rt 945

Description of problem Leak Detection

Materials used to fix problem # 56

35 miles

Time spent on job including travel time 8hr 1man

WATER DISTRICT JOB FORM

Gcwid

Date 2-6-20

Water District HK

Address or location of problem \_\_\_\_\_

Description of problem Leak detection

Materials used to fix problem truck 56

Time spent on job including travel time 30 miles Eddy, Aaron 4 hr

WATER DISTRICT JOB FORM

CCWLD

Date 2-6-2020

Water District Hickory

Address or location of problem 408 w a 945

Description of problem Leak detection

Materials used to fix problem # 56

30 miles

Time spent on job including travel time 4hr 1m 9s

WATER DISTRICT JOB FORM

GCWID

Date 2-5-20

Water District HK

Address or location of problem 408W

Description of problem Leak detection

Materials used to fix problem truck 56

Time spent on job including travel time 30 miles 4hr Eddy, Aaron



WATER DISTRICT JOB FORM **GCWLD**

Date 2-3-2020

Water District Hickory

Address or location of problem 408 W

Description of problem Leak detecting

Materials used to fix problem # 56

35 miles

Time spent on job including travel time 6hr 1man 2hr 1man

WATER DISTRICT JOB FORM

Gcwld

Date 2-27-2020

Water District HD

Address or location of problem \_\_\_\_\_

Description of problem Leak detection

Materials used to fix problem truck 56

Time spent on job including travel time 8hr 40mils Eddy, Aaron

WATER DISTRICT JOB FORM

GCWLD

Date 2-13-2020

Water District Hardeman

Address or location of problem St Rt 131

Description of problem Leak Detection

Materials used to fix problem #56

30 miles

Time spent on job including travel time 4hr 1man

WATER DISTRICT JOB FORM

GCWld

Date 2-25-2020

Water District HD

Address or location of problem \_\_\_\_\_

Description of problem Leak detection

Materials used to fix problem truck 56

Time spent on job including travel time 4 hr 20 miles Eddy, Aaron

WATER DISTRICT JOB FORM

GCWLD

Date 2-21-2020

Water District Hardeman

Address or location of problem 131

Description of problem Leak Detection

Materials used to fix problem #56

35 miles

Time spent on job including travel time 8hr 2mca

WATER DISTRICT JOB FORM

Date 2-20-2020

Water District HD

Address or location of problem Past arrowhead camper sales on left on 58E

Description of problem Set Master meter

Materials used to fix problem 2- 6" uni flange 6" ductile iron pipe  
6" Hymax-2 plastic meter well 4' tall Mini excavator

Mack dump truck truck 4

Time spent on job including travel time 8hr Avon, Rox 20 miles

WATER DISTRICT JOB FORM

GCWLD

Date 2-12-2020

Water District Hardeman

Address or location of problem \_\_\_\_\_

Description of problem Maintenance

Materials used to fix problem # 56

Time spent on job including travel time 4hr 1man

WATER DISTRICT JOB FORM

Date 2-7-20

Water District Hasdeman

Address or location of problem Clapp Rd, KY Rt 131, KY Rt 58

Description of problem marking out where to set master meters

Materials used to fix problem \_\_\_\_\_

Time spent on job including travel time 2 hrs Eric, Aron

12 miles



WATER DISTRICT JOB FORM

GCWLD

Date 2-26-2020

Water District HD

Address or location of problem \_\_\_\_\_

Description of problem Leak detection

Materials used to fix problem truck 56

Time spent on job including travel time 2hr 40miles Eddy, Aaron

WATER DISTRICT JOB FORM

Gcwld

Date 2-27-2020

Water District HD

Address or location of problem \_\_\_\_\_

Description of problem Leak detection

Materials used to fix problem truck 56

Time spent on job including travel time 8hr 40miles Eddy, Aaron

WATER DISTRICT JOB FORM

Gcwld

Date 2-28-2020

Water District HD

Address or location of problem \_\_\_\_\_

Description of problem leak detection

Materials used to fix problem truck 56

Time spent on job including travel time 2hr, 45 miles, Eddy, Aaron

GWD  
Leak

WATER DISTRICT JOB FORM	
Date	2-28-20
Water District	Hardman
Address or location of problem	858 Hopwell Rd.
Description of problem	CMW leak
Materials used to fix problem	#44#55# 8 ft hose, Jactank, 3/4" pipe, 3/4" c/s pipe rest, 3/4" PVC pipe rest, 4' 3/8" poly, 3 Small Blocks, Sand
Time spent on job including travel time	3 men 1 man
	2 HRT 1 HRT

Leak Dist

WATER DISTRICT JOB FORM	
Date	2-28-20
Water District	Hardman
Address or location of problem	810 Hopewell Rd.
Description of problem	Crew leak
Materials used to fix problem	#44, #55, Vac Truck, #8 Trencher 3/4" pipe, 3/4" cast pipe nut, 3/4" PVC pipe, 6' 3/4" poly, 4 small blocks, sand
Time spent on job including travel time	4 hr 2 hr

WATER DISTRICT JOB FORM

Date 2-28-20

Water District Hardeman

Address or location of problem 623 Hope well Rd.

Description of problem CMU leak

Materials used to fix problem Truck #49, vac Truck #5, #8 / Truck #66  
3/4" cts washer, 3/4" cts nut, 6' 3/4" polly 2 small blocks

Time spent on job including travel time 4 men : 2HR

Leak  
Detect