

0165 00015 KUPIa 08/16/2019 15:57:53 1908161398-00A EMER NEW GRID

EMERGENCY SEE REMARKS

Ticket : 1908161398 Date: 08/16/2019 Time: 15:47 Oper: JGUTERMUTH Chan:000

State: KY Cnty: GREENUP City: RACELAND

Subdivision:

Address :

Street : BELLEFONTE RD

Cross 1 : OAKLAND CT

Location: THIS IS AT A DUPLEX APARTMENT BUILDING THIS WILL BE AT 48 B BELLFONTE ROAD - WHEN VIEWING FROM THE ROAD LOCATE THE FRONT AND LEFT SIDES OF THE PROPERTY

:

Boundary: n 38.526745 s 38.524457 w -82.731925 e -82.729791

Work type : REPAIR WATER LINE

Done for : RICHARD BURKS

Start date: 08/16/2019 Time: 15:50 Hours notice: 0/0 Priority: EMER

Ug/Oh/Both: U Blasting: NO Emergency: Y

Duration : N/A Depth: 3 FEET

Company : BONZO EXCAVATING Type: HOME

Co addr : 107 WILDLIFE TRAIL

City : GREENUP State: KY Zip: 41144

Caller : RICHARD BURKS Phone: (606)923-1274

Contact : BONZO EXCAVATING Phone:

Mobile : (606)923-1274

Remarks : CREW IN ROUTE

:

Submitted date: 08/16/2019 Time: 15:47

Members: 0023 0165 0367 WINKY

Audit History:

8/16/2019 3:57:53 PM: Received

DETAILS: Ticket received for registration code 0165

8/16/2019 3:57:53 PM: Ticket Score Calculated

DETAILS: Risk Percentile calculated. Score value: 0

8/16/2019 3:57:53 PM: Auto Process

DETAILS: Ticket Folder Recommended: CKY BLASTING

8/16/2019 3:57:53 PM: Ticket Queued

DETAILS: Ticket queued for delivery

8/16/2019 3:58:03 PM: Ticket Delivered

DETAILS: Ticket successfully sent to a web request device at <https://integrator-ns.optimainxdr.com/ticket>

8/16/2019 3:58:06 PM: Smart Score Saved

DETAILS: Risk Percentile saved. Score value: 79

8/16/2019 4:18:53 PM: Put in Folder

DETAILS: Put in **Ashland- In House Locates by Elaine Teague

NOTE: 2631 -- Emergency KUPI#1908161398 -- Bellefonte Rd -- Raceland Ky sent to ic assigner emaurice

8/16/2019 4:18:53 PM: Ticket Queued

DETAILS: Ticket queued for delivery

8/16/2019 4:18:56 PM: Ticket Delivered

DETAILS: Ticket successfully sent to a web request device at <https://integrator-ns.optimainxdr.com/ticket>

8/16/2019 5:14:11 PM: Responded

DETAILS: CKY (1) MARKED: added by Brandon Meek, Locate Time: 8/16/2019 5:10:56 PM, Units of Work: 1.00

NOTE: marked CKY GAS in scope of the dig ticket with paint. Owner was on site and he said they would stay on the house next doors property as to avoid crossing CKY GAS service.

8/16/2019 5:14:11 PM: Ticket Queued

DETAILS: Ticket queued for delivery

8/16/2019 5:14:15 PM: Ticket Delivered

DETAILS: Ticket successfully sent to a web request device at <https://integrator-ns.optimainxdr.com/ticket>