

East Logan Water District  
WORK ORDER 14884

Account # \_\_\_\_\_ Order Date 9/3/2019  
Name BLACKBURN, HOMER L Status MEDIUM  
Address \_\_\_\_\_ Scheduled 09/03/19 12:47 PM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 78786042	73607028	2545	B14166275	

Description \_\_\_\_\_  
Comment RT WH/HS R/DR T/LF  
Requested By customer Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_  
Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_ Completed Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes check for leak on our side of meter at the meter box

Inventory Item And Description	Quantity Ordered	Quantity Used

*305 Turner Rd*  
*Repaired*

Signature \_\_\_\_\_



East Logan Water District  
WORK ORDER 14835

Account #  
Name VACANT  
Address  
Telephone

Order Date 8/9/2019  
Status MEDIUM  
Scheduled 08/09/19 04:06 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 36140570      ERT/INTERNAL ID# 09938306      READING 1870      LOCATOR TAG LF,WH HSE,LF CN      READING IN / OUT

Description  
Comment LF,WH HSE,LF CNR

Requested By Jerry Taylor      Assigned To MAINTENANCE CREW      Completed By  
Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_:\_\_\_\_      Completed Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_:\_\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes GO TO THE END OF KEETON RD, BY A GATE JERRY SAYS THERE WAS A LOT OF WATER THERE LAST WEEK, PRETTY MUCH AT THE END OF THE LINE

*high at see no water. The end of line is up in front of house # 250 must just been rain*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Water</i>		

Signature 

East Logan Water District  
WORK ORDER 14831

Account #: \_\_\_\_\_ Order Date: 8/9/2019  
 Name: MCCUE, ROBERT A Status: MEDIUM  
 Address: \_\_\_\_\_ Scheduled: 08/09/19 01:19 PM  
 Telephone: \_\_\_\_\_ Job #: \_\_\_\_\_ Order Type: CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 46202615	72841848	14912	B15450954	

Description: \_\_\_\_\_  
 Comment: BY RED GATE, 12" INSIDE FENCE  
 Requested By: \_\_\_\_\_ Assigned To: MAINTENANCE CREW Completed By: \_\_\_\_\_  
 Start Date: \_\_\_/\_\_\_/\_\_\_ Time: \_\_\_\_\_ Completed Date: \_\_\_/\_\_\_/\_\_\_ Time: \_\_\_\_\_

Make: \_\_\_\_\_ Size/Type: \_\_\_\_\_ Multiplier: \_\_\_\_\_

Notes: says that the meter is not turning, but the volume of water is coming through the meter, and when the meter was turned off before being unlocked that there was water flowing. I have no clue what she's talking about will someone just check the meter plz

Inventory Item And Description	Quantity Ordered	Quantity Used

14942  
 No sign of leaks -  
 ditches dug. bay dug

Signature: 



East Logan Water District  
WORK ORDER 14440

Account #  
Name RUST, BILL R  
Address  
Telephone Job #

Order Date 4/23/2019  
Status MEDIUM  
Scheduled 04/23/19 08 10 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 69361463      ERT/INTERNAL ID# 63066075      READING 2761      LOCATOR TAG B14162149      READING IN / OUT

Description  
Comment RT BLUE HS R/DR

Requested By sharon rust      Assigned To MAINTENANCE CREW      Completed By *MH*  
Start Date 4/23/19 Time 11:30      Completed Date 4/23/19 Time 11:30

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes from meter to the rd, meter box is full of water as well  
check pressure states that has low pressure as well      *no sound*

*Reading 2770 did Chlorine Test (negative) 35 lbs @  
Took Fluoride Sample      PRESSURE*

Inventory Item And Description	Quantity Ordered	Quantity Used

*no fluoride per lab 4.24.19*

*MH*

Signature

East Logan Water District  
**WORK ORDER 15170**

Account # \_\_\_\_\_ Order Date 11/27/2019  
 Name MURPHY DONALD Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 11/27/19 02:33 PM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE  
 METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
 WT 63869493 56502002 6191 B13478542  
 Description \_\_\_\_\_  
 Comment LF, LOG HSE, LF DR 2ND METER  
 Requested By ms murphy Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_  
 Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_:\_\_\_ Completed Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_:\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
 Notes some meter is full of water, but water  
is not moving.

Inventory Item And Description	Quantity Ordered	Quantity Used
<u>groundwater</u>		
<u>from Mountain run off</u>		
<u>test &amp; resid.</u>		

Signature \_\_\_\_\_

East Logan Water District  
WORK ORDER 15160

Account # \_\_\_\_\_ Order Date 11/19/2019  
Name TVA Status HIGH  
Address \_\_\_\_\_ Scheduled 11/19/19 12:58 PM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 52473718	61287514	1616	B14169888	

Description  
Comment LF,POWER SUB STA,LF GR DR

Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_  
Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_ Completed Date 11/19/19 Time 5:10

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes Very close to this meter is water coming up See if you can find it and determine how bad

Inventory Item And Description	Quantity Ordered	Quantity Used
was the sample box.		
stopped it.		

Signature EH



East Logan Water District  
**WORK ORDER 15184**

Account # \_\_\_\_\_ Order Date 12/5/2019  
Name STRATTON, JOSHUA D Status MEDIUM  
Address \_\_\_\_\_ Scheduled 12/05/19 03 33 PM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 69361578 63066190 2870 B14167062 2907

Description \_\_\_\_\_

Comment LF, PINK HSE. LF. CNR

Requested By MR STRATTON

Assigned To MAINTENANCE CREW

Completed By *EH*

Start Date   /  /   Time   :  :  

Completed Date 12/5/19 Time 10:07

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes: WHEN TURN METER OFF IN BOX WATER IS STILL FULL PRESSURE IN THE HOUSE. THEY ARE TRYING TO CHECK FOR A LEAK.

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>WT 69361578</i>		
<i>LF, PINK HSE. LF. CNR</i>		

Signature \_\_\_\_\_

East Logan Water District  
WORK ORDER 15182

Account #  
Name GOREE, SOPHIA M  
Address  
Telephone

Order Date 12/5/2019  
Status MEDIUM  
Scheduled 12/05/19 08:10 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 69361393	63066005	1680	B14166779	

Description  
Comment LT, WH/HSE LT/YD

Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_  
Start Date 12/5/19 Time 8:10 Completed Date 12/5/19 Time 8:10

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes

*Says meter is vibrating like a helicopter*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>meter was off. turned on and continued to spin waited 2 minutes + cut back off. no leak at house. Or any house leak.</i>		

Signature



East Logan Water District  
WORK ORDER 15155

Account # \_\_\_\_\_ Order Date 11/18/2019  
 Name HARRIS ROBERT N Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 11/18/19 10:42 AM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE  
 METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
 WT 9135919 9135919 415  
 Description \_\_\_\_\_  
 Comment RT.BLUE/DBL WIDE LYD  
 Requested By MR HARRIS Assigned To MAINTENANCE CREW Completed By EH  
 Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_ Completed Date 11/18/19 Time 10:42

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
 Notes CUSTOMER CALLED IN STATED THAT LOGAN TELE HAS RAN OVER AND DEMOLISHED THE BOX

Inventory Item And Description	Quantity Ordered	Quantity Used
No leaks		

X Joe Beauchamp

Both Sides

Nov 20 @ 11:00

1911180980

ELWD  
LTC  
wreck

EH

Signature

East Logan Water District  
WORK ORDER 14406

Account # \_\_\_\_\_ Name MCLEAN, RHONDA L Order Date 4/10/2019  
 Address \_\_\_\_\_ Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Status MEDIUM  
 Description \_\_\_\_\_ Scheduled 04/10/19 08:19 AM  
 Comment LT, BRK, LT DR Order Type CHECK FOR LEAK ON OUR SIDE  
 Requested By gary price Assigned To MAINTENANCE CREW Completed By CP/MH  
 Start Date 1/1/19 Time \_\_\_\_\_ Completed Date 4/10/19 Time 4:00  
 Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
 Notes \_\_\_\_\_

Inventory Item And Description	Quantity Ordered	Quantity Used
tucker Price		
Geopon <del>Pressure</del>		
Two 6in Knocks and 1 piece of 6in pipe 5ft long	6in knock 6in pipe	2 1
20 to 30 gpm for years!!		
Exp - May 1st		

ELWD, LTC, WRECC

1904 100 729

Signature 

East Logan Water District  
**WORK ORDER 14968**

Account # --  
Name BOBBETT, CLIFFORD G  
Address  
Telephone Job #

Order Date 9/18/2019  
Status MEDIUM  
Scheduled 09/18/19 12:32 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 67242274 60912207 4565 B14167366

Description  
Comment LF, WH TRLR, 15' LF 1ST DRIVE

Requested By Clifford Bobbett Assigned To MAINTENANCE CREW Completed By *GP*

Start Date   /  /   Time   :   Completed Date 9/18/19 Time 2:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes Intersection of Cooperiown & Dallam Creek has water in ditch BUD CALL

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>was a Basement shower drain!</i>		
<i>NO LEAK GP</i>		

*100' ft section both sides  
ELWD  
LTC  
# 1909181433*

*NO LEAK*

Signature *Paul*

East Logan Water District  
WORK ORDER 14784

Account #  
Name ARNOLD, DAVID J  
Address  
Telephone

Order Date 8/6/2019  
Status MEDIUM  
Scheduled 08/06/19 09:10 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 51780745      ERT/INTERNAL ID# 61950536      READING 5228      LOCATOR TAG B14168037      READING IN / OUT

Description  
Comment LF WH/HS L/DR

Requested By djarnold      Assigned To MAINTENANCE CREW      Completed By GP  
Start Date 8/1/19      Time :      Completed Date 8/17/19      Time 12:10

Make      Size/Type      Multiplier

Notes cust called in stated that if standing in drive way, walk across rd to the other side. in front of barn there is water standing, possible leak, can you please test for chlorine as well -thx

*This is a leak at coop Repair Leaks*

Inventory Item And Description	Quantity Ordered	Quantity Used
2 per Berbed fittings		
4 per Bands		
1 3/4" in pipe of pipe 2 to 3 gpm		
X - Amerson Stone Rd		

ELWD  
LTC  
WRECC

1874

Signature



East Logan Water District  
**WORK ORDER 14875**

Account # \_\_\_\_\_ Order Date 8/30/2019  
 Name HALEY, MELVIN LEWIS Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 08/30/19 08:49 AM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 51780750 ERT/INTERNAL ID# 09623816 READING 1665 LOCATOR TAG B15451271 READING IN / OUT \_\_\_\_\_

Description \_\_\_\_\_  
 Comment LT, WH/HSE OFF RD, LT/DR  
 Requested By Melvin Assigned To MAINTENANCE CREW Completed By *GP*  
 Start Date   1  /  1  /   Time   :   Completed Date   9  /  30  /  19   Time   3  :  30  

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes 270-772-3809 Melvin Haley  
 Water in box, hears water running

*Repaired Line*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>four Compression Rings</i>		
<i>Two barbed Fittings</i>		
<i>1 piece of 3/4" barb + 6" long</i>		
<i>5 to 10 gpm</i>		

Signature 

East Logan Water District  
WORK ORDER 14755

Account #  
Name LACK, EUGENIA  
Address  
Telephone

Order Date 7/29/2019  
Status MEDIUM  
Scheduled 07/29/19 10:19 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 69361391 63066003 3438 B14169135

Description  
Comment LT, 2nd MTR


Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By *GP*

Start Date 7/29 Time 10:00 Completed Date 7/29/19 Time 2:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes \_\_\_\_\_

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Replaced all the way to main</i>		
<i>four feet of blue pex</i>		<i>4 feet</i>
<i>1 Shark bite 3/4</i>		<i>1</i>
<i>1 to 2 gpm</i>		

Signature





East Logan Water District  
WORK ORDER 14621

Account # \_\_\_\_\_ Order Date 6/13/2019  
Name WHITE, BARRY Status MEDIUM  
Address \_\_\_\_\_ Scheduled 06/13/19 12 26 PM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE  
METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 81271678 74600750 340 B15261688  
Description \_\_\_\_\_  
Comment L TRL M/YD  
Requested By BARRY WHITE Assigned To MAINTENANCE CREW Completed By GP  
Start Date 6/13/19 Time \_\_\_\_\_ Completed Date 7/15/19 Time 4:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes LEAK IS DIRECTLY ACCROSS FROM DALADA LN, ROCK TRUCK PULLED OUT OF DALADA INTO GRASS ON MUD RIVER VALLEY, AND RAN OVER THE LINE. IS NOT LEAKING MUCH BUT DID TEST POSITIVE FOR CHLORINE, AND WATER IS STANDING-CS/CB

Inventory Item And Description	Quantity Ordered	Quantity Used
1 $\frac{3}{4}$ Cone packing		
<del>1 WATER</del>		
1 Muller Nut		
25 foot of pipe $\frac{3}{4}$ PEX		
2 $\frac{3}{4}$ Inserts		
June 28 @ 9		
exp July 17		

1.5 gpm

drip in meter box <sup>air side</sup> <sub>road</sub> where  
we've already repaired a leak

50' Radius

Att, ELWD -

cleared

190 6226 0587

Call Bud

Both sides of road

July 11  
exp 30th

190 7090901

Signature

CB WA Peni

East Logan Water District  
WORK ORDER 14882

Account # \_\_\_\_\_ Order Date 9/3/2019  
Name WRIGHT, JACK Status MEDIUM  
Address \_\_\_\_\_ Scheduled 09/03/19 11:29 AM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 000063869512	56502021	2127	B14166269	

Description \_\_\_\_\_  
Comment RT, BLUE HSE, 100' BEFORE HSE.  
Requested By Linda Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_  
Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_ Completed Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes A Customer called to say there is a leak here. If it is this service leaking, we can turn off at corp as this acct has been inactive for 6 years LA

Inventory Item And Description	Quantity Ordered	Quantity Used

Sigs by Lisa # 190903 1119  
ATT - 1-800-728-9140  
ELWD  
LTKWC  
TX Gas -  
3 GPM

Signature \_\_\_\_\_

East Logan Water District  
WORK ORDER 14837

Account #  
Name OGLE, LISA  
Address  
Telephone

Order Date 8/12/2019  
Status MEDIUM  
Scheduled 08/12/19 02:12 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 69361583      ERT/INTERNAL ID# 63066195      READING 4737      LOCATOR TAG B14167939      READING IN / OUT 4752

Description  
Comment LT, TAN TRLR, MYD

Requested By LISA      Assigned To MAINTENANCE CREW      Completed By

Start Date 8/12/19      Time : :      Completed Date 8/23/19      Time : :  
8/26/19

Make      Size/Type      Multiplier

Notes SAYS AROUND METER AREA IS SOGGY PLEASE SEE IF THERE IS A LEAK

*There leaks prob 3+05 GPM Replaced Line all the way to main*


Inventory Item And Description	Quantity Ordered	Quantity Used
<i>making AT the coast</i>		

X J.R. Williams  
X Dalada

Aug 16 @ 10:00  
exp Sept 4

Att, ELWD  
1908140633

*Nichos Polu  
High Beach*

Signature 

East Logan Water District  
WORK ORDER 14874

Account #  
Name GOODALL--TP, MALEAH G  
Address  
Telephone Job #

Order Date 8/29/2019  
Status MEDIUM  
Scheduled 08/29/19 08:46 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 83545707 89536819 546 B14167491 00564

Description  
Comment LF, WOOD HSE LF/CNR

Requested By Assigned To MAINTENANCE CREW Completed By CP  
Start Date 8/29/19 Time 8:00 Completed Date 8/29/19 Time 3:00

Make Size/Type Multiplier

Notes LEAK ON OUR SIDE OF METER IN WOODED AREA, CALLED BUD 1908290487, LTC & ELWD

*Repaired tree root rub a hole in service line. tree wood to be removed setting right on line*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Two barbed Fittings 3/4</i>		
<i>Four Bands 3/4</i>		
<i>1 piece of Pipe 3/4 about 6 in Long</i>		

Signature 

East Logan Water District  
**WORK ORDER 14584**

Account # \_\_\_\_\_ Name BILYEU, CLAY E Order Date 6/5/2019  
Address \_\_\_\_\_ Telephone \_\_\_\_\_ Status MEDIUM  
Scheduled 06/05/19 02:40 PM Order Type CHECK FOR LEAK ON OUR SIDE

METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
WT 9434302 9434302 176 \_\_\_\_\_ 0602/6/19

Description \_\_\_\_\_ Comment RT,BLUE HSE, MDL YD Requested By debbie Assigned To MAINTENANCE CREW Completed By GP/MH  
Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_ Completed Date 6/1/2019 Time 02:15

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes check for water in ditch near meter  
Small Leak on our side

Inventory Item And Description	Quantity Ordered	Quantity Used
<u>X - melody Ridge Rd</u>		

MARKED in white PAINT  
Both sides OF Rd.

3 gpm

June 10 @ 4pm

lyp 27 @ 4pm

2" gas line  
over main  
line

Att  
Atmos  
ELWD

Bud #

190 6016 18344

Signature



East Logan Water District  
WORK ORDER 14634

Account #  
Name MONTGOMERY, MATT T  
Address  
Telephone Job #

Order Date 6/17/2019  
Status MEDIUM  
Scheduled 06/17/19 03:30 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 43605867      ERT/INTERNAL ID# 09486240      READING 566      LOCATOR TAG B14168828      READING IN / OUT

Description  
Comment RT, TAN TRLR, M/YD  
Requested By Mrs. Lowery Neighbor      Assigned To MAINTENANCE CREW      Completed By GI FH  
Start Date 6/17 Time 4:00      Completed Date 6/20/19 Time 4:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes It was a curb that had been Retired that was Leaking

Inventory Item And Description	Quantity Ordered	Quantity Used
<u>6" Blue pipe</u>		
<u>1 3/4 cap</u>		
<u>1 3/4 Cone Nut</u>		

ATT  
Atmos  
LTC  
by 6-19-19  
1906772145

Remember the meters are back tapped on this road - (at least the ones in front are

*[Handwritten Signature]*

Signature \_\_\_\_\_

East Logan Water District  
WORK ORDER 14627

Account #  
Name THOMAS, LEWIS  
Address  
Telephone

Order Date 6/17/2019  
Status MEDIUM  
Scheduled 06/17/19 08 47 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 52473717 07314929 4290 B14172382

Description  
Comment LF TAN HS LYARD

Requested By Mrs. Thomas Assigned To MAINTENANCE CREW Completed By EH-6P  
Start Date 6/17/19 Time 3:15 Completed Date 6/18/19 Time 3:15

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes next to 2144 Plainview Church Rd driveway, water is filling up to the 2154 Plainview Church Rd yard

Inventory Item And Description	Quantity Ordered	Quantity Used
<u>Trapped water possibly</u>		

5 gpm Leak  
testing <sup>at W/O</sup> for fluoride  
shut off at corp. stop  
7-9-19  
MAA  
This is a leak  
ELWD LTC

Happy follow  
Proctorville  
190 619 1832

Signature EH





East Logan Water District  
**WORK ORDER 14630**

Account # \_\_\_\_\_  
Name ANDERSON CHARLES B  
Address \_\_\_\_\_  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_

Order Date 6/17/2019  
Status MEDIUM  
Scheduled 06/17/19 01:02 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 40548989    ERT/INTERNAL ID# 63249657    READING 6058    LOCATOR TAG B14169961    READING IN / OUT \_\_\_\_\_

Description \_\_\_\_\_  
Comment RT, 1/2 BRK HSE, LF CNR

Requested By charles anderson    Assigned To MAINTENANCE CREW

Completed By *EH-6P*

Start Date   1  /  1  /   Time   :  

Completed Date   7  /  15  /  19   Time   12  :  00  

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes 270-847-0706-foot behind meter there is water behind the meter box.

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>pinhole leak</i>		
<i>Replaced</i>		
<i>2 3/4 Shark bites</i>		
<i>2 3/4 Shark bite inserts</i>		
<i>3 feet of blue pex</i>		

*10-15 gpm*

*X Echo Valley  
K cleared  
LTC, ELWD  
LTC, LTWC  
Texas gas  
WRECC*

*← cleared*

*1906191834*

*July 11  
exp July 30  
1907090917*

Signature *EH P... [Signature]*

East Logan Water District  
**WORK ORDER 14657**

Account #  
Name MCELFRISH, STEVE & EMILY  
Address  
Telephone Job #

Order Date 6/26/2019  
Status MEDIUM  
Scheduled 06/26/19 02:49 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 48979857      ERT/INTERNAL ID# 10055365      READING 846      LOCATOR TAG B14169809      READING IN / OUT

Description

Comment LF, GREEN 2 STRY HSE, RT GR DR

Requested By CUSTOMER      Assigned To MAINTENANCE CREW      Completed By

Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_      Completed Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes

*- Pull service line under rd -*

Inventory Item And Description	Quantity Ordered	Quantity Used

*BUD call 6-28-19 LTC, ELWD #1904281097  
20-25 9pm Definito*

*leak*

*4395  
2960*

*✓ Checking for  
leak on 6-26-19  
positive results*

*July 11  
exp 30 x 00  
1907090904*

Signature \_\_\_\_\_

East Logan Water District  
WORK ORDER 14672

Account #  
Name WOODARD, WILLIAM  
Address  
Telephone

Order Date 7/1/2019  
Status MEDIUM  
Scheduled 07/01/19 09:36 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 44812547      ERT/INTERNAL ID# 09720083      READING 8059      LOCATOR TAG B14167270      READING IN / OUT

Description  
Comment RT, BRK HSE, MYD  
Requested By Bill Woodard      Assigned To MAINTENANCE CREW      Completed By *6P/MW/E-H*

Start Date 7/1/19 Time   :        Completed Date 7/11/19 Time 02:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes  
*X Franklin Rd -*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>1 3/4" Sharkbite</i>		
<i>2 3/4" PEX WATERLINE</i>		
<i>1 3/4" insert</i>		
<i>1 3/4" manhole mat</i>		

*5 gpm leak*

*July 11  
exp July 30*

*Att. ← Cleared  
ELWD,  
LTC  
LTRWC  
Riville Sewers*

*190 709 1035*

*Pennyrite  
720-2479*

Signature



East Logan Water District  
**WORK ORDER 15159**

Account # \_\_\_\_\_ Order Date 11/19/2019  
Name CHILES, ALLEN Status MEDIUM  
Address \_\_\_\_\_ Scheduled 11/19/19 12:51 PM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

---

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 9434425	9434425	2669		

---

Description \_\_\_\_\_  
Comment RT/B4 H2O TROUGH/BTW 2441/2370  
Requested By Ben Weaver Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW  
Start Date 11/20/19 08 42 AM Completed Date 11/20/19 08 42 AM

Notes Leak in box, meter is turning  
assuming busted meter bottom changed meter to kam 9434425-eh-2697  
Ben Weaver

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 15146**

Account #  
Name PIERCY, ERIC L  
Address  
Telephone Job #  
Order Date 11/14/2019  
Status MEDIUM  
Scheduled 11/14/19 08.04 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

---

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 9434417	9434417	1231		

---

Description  
Comment LF, TAN DBL WIDE, M/YD  
Requested By Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW

---

Start Date 11/14/19 10:48 AM Completed Date 11/14/19 10:48 AM

Notes check for busted meter bottom  
CHANGED METER OUT, BECAUSE METER AND METER BOX IS BUSTED, NEW METER. KAM  
9434417-1246-BW

East Logan Water District  
**WORK ORDER 15145**

Account # \_\_\_\_\_  
Name HALL, GLADYS  
Address \_\_\_\_\_  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_  
Order Date 11/13/2019  
Status MEDIUM  
Scheduled 11/13/19 10:36 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

---

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 9434412	9434412	7008		

---

Description  
Comment LF,TAN HSE 40' RT DR 2ND  
Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW

---

Start Date 11/14/19 11:57 AM Completed Date 11/14/19 11:57 AM

Notes 2707926680-check for busted meter bottom, says can hear water, and that lid is off the meter  
BUSTED METER BOTTOM, CHANGED OUT METER TO KAM: 9434412-7028-EH

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 15134**

Account #		Order Date	11/8/2019		
Name	COLES, BOYCE	Status	MEDIUM		
Address		Scheduled	11/08/19 09:24 AM		
Telephone	Job #	Order Type	CHECK FOR LEAK ON OUR SIDE		
METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT	
WT 9434406	9434406	3474			
Description					
Comment					
Requested By	MR COLES	Assigned To	MAINTENANCE CREW	Completed By	MAINTENANCE CREW
Start Date	11/15/19 10:08 AM			Completed Date	11/15/19 10:08 AM

Notes WILL NEED TO REPLACE LID TO METER WHEN THERE, SOMEONE HAS A LEAK INSIDE OF METER BOX AREA. BUT NOT SURE WHOS LEAK IT IS-3485-eh, changed meter to kam: 9434406-0

Signature \_\_\_\_\_



East Logan Water District  
WORK ORDER 14260

Account# 22 000000  
Name THOMAS, GARY R  
Address  
Telephone

Order Date 3/11/2019  
Status MEDIUM  
Scheduled 03/11/19 08:42 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 21581296      ERT/INTERNAL ID# 53315722      READING 4780      LOCATOR TAG B14969370      READING IN / OUT

Description

Comment LF, HSE OFF RD, RT GR DR

Requested By Linda

Assigned To MAINTENANCE CREW

Completed By *E.P.T.*

Start Date 3/11 Time

Completed Date 3/11/19 Time 8:30

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Gary called water bubbling up in box but can't tell from where Please check if our leak or his 270-893-2401

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Threaded PVC coupling 3/4</i>		<i>1</i>
<i>Threaded Brass barbed Fitting 1/4</i>		<i>1</i>
<i>Threaded Shark bite 3/4</i>		<i>1</i>
<i>3/4 Blue pex 8 in long</i>		<i>1</i>
<i>*LEAK WAS ON HIS SIDE*</i>		

Signature *P. [Signature]*

East Logan Water District  
WORK ORDER 14264

Account #  
Name GOODALL, JAYME  
Address  
Telephone

Order Date 3/12/2019  
Status MEDIUM  
Scheduled 03/12/19 08:45 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 84304846  
ERT/INTERNAL ID# 89866172  
READING 263  
LOCATOR TAG B14170205  
READING IN / OUT 292

Description  
Comment LF, WH HSE OFF RD. LF DR. AT H

Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By *CP RHE ET*  
Start Date   /  /   Time \_\_\_\_\_ Completed Date 3/12/19 Time 2:05

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes cust stated that looks like valve is teaking in the box. just check out whenever you get a free moment no rush

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Cust tighten it fixed</i>		

Signature \_\_\_\_\_

East Logan Water District  
WORK ORDER 14271

Account #  
Name HAFNER, DENNIS  
Address  
Telephone Job #

Order Date 3/13/2019  
Status MEDIUM  
Scheduled 03/13/19 10 21 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 51780757	09806144	1966	B14169723	

Description

Comment LF,TAN HSE,12' LF DR

Requested By dennis

Assigned To MAINTENANCE CREW

Completed By MAINTENANCE CREW

Start Date 03/14/19 08 21 AM

Completed Date 03/14/19 08 21 AM

Notes 2707257730  
replaced washer-gp

GP / M H 9:30 AM  
3-14-19

shut off leaking Tightened

Signature



East Logan Water District  
**WORK ORDER 14115**

Account # \_\_\_\_\_ Order Date 2/11/2019  
 Name PERRY, DANNY W Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 02/11/19 11:51 AM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
 WT 9135901 9135901

Description \_\_\_\_\_  
 Comment R, 1/2 BRK HSE RT NEIGHBOR DR

Requested By \_\_\_\_\_ Assigned to MAINTENANCE CREW Completed By \_\_\_\_\_

Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_:\_\_\_\_ Completed Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_:\_\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
 Notes cust stated that meter box is full of water and clasp that connects to meter is broken

Inventory Item And Description	Quantity Ordered	Quantity Used

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 13999**

Account #  
Name COLE PAULA  
Address  
Telephone

Order Date 1/14/2019  
Status MEDIUM  
Scheduled 01/14/19 10:40 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 52473849 69461096 5291 B14168937

Description

Comment LF.WH HSE.LF CNR

Requested By Assigned To MAINTENANCE CREW Completed By *MH*  
Start Date 1/14 Time \_\_\_\_\_ Completed Date 1/14/19 Time 6:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes customer stated that meter box is covered in water and extremely soupy

*No leak on either side*

Inventory Item And Description	Quantity Ordered	Quantity Used

Signature *[Handwritten Signature]*

East Logan Water District  
**WORK ORDER 14723**

Account #  
Name COX, RAYMOND T  
Address  
Telephone

Order Date 7/16/2019  
Status MEDIUM  
Scheduled 07/16/19 11.41 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 45221796      ERT/INTERNAL ID# 71971533      READING 2142      LOCATOR TAG B14167089      READING IN / OUT

Description  
Comment LF,WH/HSE MYD

Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW      Completed By \_\_\_\_\_  
Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_      Completed Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes  
LEAK OF CORP  
EXP. AUG 6  
BUD. 1907161068  
ELWD, LTC

Inventory Item And Description	Quantity Ordered	Quantity Used
1 1/4 Shark Bite couplings		
5 x 10 gpm		

EPP  
Option 1

Dennyville Electric

Signature \_\_\_\_\_

East Logan Water District  
WORK ORDER 14752

Account #  
Name DANKS, MICHAEL H  
Address  
Telephone Job #

Order Date 7/26/2019  
Status MEDIUM  
Scheduled 07/26/19 04.11 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 50180728	63183753	1148	B14168879	11.55

Description  
Comment LF, BRK HSE, RT DR

Requested By Michael Danks Assigned To MAINTENANCE CREW Completed By *(Signature)*  
Start Date 7/26/19 Time 9:00 Completed Date 7/29/19 Time 11:54

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes 1/2" stream of water around meter box coming up Please check for leak.

Inventory Item And Description	Quantity Ordered	Quantity Used
Repaired Leak		
Two 3/4 short pipes		2
1 3/4 pipe 12 in Long		1
5 gpm		

Leak on our side 3ft. in front of meter  
MARKED in white PAINT

*(Signature)*  
Signature Michael Danks

East Logan Water District  
WORK ORDER 14768

Account # \_\_\_\_\_ Order Date 8/1/2019  
Name BRAY, OTIS Status MEDIUM  
Address \_\_\_\_\_ Scheduled 08/01/19 03:24 PM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE


METER# WT 21337408 ERT/INTERNAL ID# 63814709 READING 2995 LOCATOR TAG B13480791 READING IN / OUT \_\_\_\_\_

Description \_\_\_\_\_  
Comment LT 1/2 BRICK RT 2ND DR

Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By *GP*  
Start Date 8/1 Time \_\_\_\_\_ Completed Date 8/1/19 Time 6:30

Make *Otis Bray* Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes *Reported*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>3/4 Shark blue</i>		<i>2</i>
<i>3/4 blue pex</i>		<i>3 feet</i>
<i>Repaired service line Next time if Leaks Replace <del>all</del> All the Service</i>		

Signature 



East Logan Water District  
WORK ORDER 14724

Account # \_\_\_\_\_ Order Date 7/16/2019  
 Name MCPHERSON MICHAEL V Status HIGH  
 Address \_\_\_\_\_ Scheduled 07/16/19 11:47 AM  
 Telephone \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE  
 METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
 WT 48431525 09403754 7843 B14170249  
 Description \_\_\_\_\_  
 Comment RT, GREEN HSE. 20' RT DR  
 Requested By BEN BROWN Assigned To MAINTENANCE CREW Completed By *G.P. [unclear]*  
 Start Date *7/16/19* Time \_\_\_\_\_ Completed Date *7/16/19* Time *12:00*


Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
 Notes BEN BROWN CALLED SAID THAT WATER IS SHOOTING UP OUT OF GROUND

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Two 6 in knock ons</i>		
<i>1 6 in pipe 90"</i>		

*25 ft*      *W Valley Wildcat*      *Exp. Aug 6.*

*Att, ATMOS, ELWD, LTC,  
by gas.*

*190 716 1094*



Signature



East Logan Water District  
WORK ORDER 15073

Account #  
Name EANS, STEPHEN L.  
Address  
Telephone Job #

Order Date 10/15/2019  
Status MEDIUM  
Scheduled 10/15/19 02:55 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 81271753	74600825	190	B14169859	00191

Description  
Comment RT, BRK HSE, 20' RT DRIVE

Requested By Stephen Eans Assigned To MAINTENANCE CREW Completed By EH  
Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_ Completed Date 10/16/19 Time 2:30

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes Customer said water coming up in box, but leak is not in box; maybe coming from under road customer thinks

Inventory Item And Description	Quantity Ordered	Quantity Used
Brass nipple		
2 3/4 Rings		
1 foot of pipe		

# 1910151717

Atmos  
ELWD  
LTC  
WRECC

Signature EH

East Logan Water District  
WORK ORDER 15088

Account #  
Name PHELPS, ALLEN  
Address  
Telephone

Order Date 10/23/2019  
Status MEDIUM  
Scheduled 10/23/19 09 13 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 43605836 63717596 5853 B14167370

Description

Comment RT WH/HS R/CNR HS

Requested By allen phelps

Assigned To MAINTENANCE CREW

Completed By *MH/EH*

Start Date   /  /   Time   :  

Completed Date 10/23/19 Time 3:50

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes cust believes that the meter bottom is busted water is spewing out water after shutting water off

Inventory Item And Description	Quantity Ordered	Quantity Used

*Leak in Service Tube our Side  
83 gpm.*

*Mike Hines*

Signature

WORK ORDER 14606

Account #		Order Date	6/7/2019
Name	HEAD, GERALD W	Status	MEDIUM
Address		Scheduled	06/07/19 08:00 AM
Telephone	Job #	Order Type	CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 47418228	73543855	2431	B14170212	

Description

Comment RT, BRK HSE, RT DR

Requested By Heard Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW

Start Date 06/07/19 11:30 AM Completed Date 06/07/19 11:30 AM

Notes Leak in service line

Mike, Gary, Ethan repaired. Estimated 20-25 gpm leak, possibly as much as 1,080,000 lost. Used 2ea 3/4 couplings, 4 ea 3/4 inserts and 2' pex line

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 15023**

Account #  
Name PRUNTY, MARY JANE  
Address  
Telephone

Order Date 10/3/2019  
Status MEDIUM  
Scheduled 10/03/19 08 44 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 36635914	58943335	3902	B14169661	2.1

Description

Comment LF TRLR MYD T/A T/RT MONTGOME

Requested By Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW

Start Date 10/03/19 09 25 AM Completed Date 10/03/19 09 25 AM

Notes leak on cust side around their shut off, guys spoke with customer, water is rolling out on their side of meter-gp/bw  
CUST CALLED BACK THINKING THAT WE ALSO HAVE A LEAK ON OUR SIDE OF THE METER, PLEASE  
CHECK OUT AND MAKE SURE-THX

10-10-19 4:00  
MH/EH

1 gpm  
6 days  
Loss 8,640

DT Arnold  
think our leak is at  
bottom of the settler.  
I've thought about 1/4" stream

*[Handwritten signature]*

*[Handwritten signature]*

Signature

East Logan Water District  
**WORK ORDER 15024**

Account # \_\_\_\_\_ Order Date 10/3/2019  
 Name JOHNSON, BOBBY R Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 10/03/19 09:31 AM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE  
 METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
 WT 49829038 63097829 1538 B14166614 \_\_\_\_\_ 1549  
 Description \_\_\_\_\_  
 Comment RT GRAY HS OFF RD R/DR  
 Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By GP  
 Start Date 10/1/19 Time \_\_\_\_\_ Completed Date 10/1/19 Time \_\_\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes service tube leak  
*Repaired service under Road pulled new line under Road 3 to 5 gpm*

Inventory Item And Description	Quantity Ordered	Quantity Used

Signature *GP*

East Logan Water District  
WORK ORDER 15189

Account #  
Name FYNBOE, RYAN C  
Address  
Telephone

Order Date 12/9/2019  
Status MEDIUM  
Scheduled 12/09/19 08:05 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 30275514      ERT/INTERNAL ID# 39220341      READING 6850      LOCATOR TAG B14167455      READING IN / OUT

Description  
Comment RT,WH HSE. BACK YD AT TREE

Requested By Ryan      Assigned To MAINTENANCE CREW      Completed By  
Start Date 1/1/      Time :      Completed Date 12/19/19      Time :

Make      Size/Type      Multiplier  
Notes Customer called to notify of leak before Hope Way on Bucksville Rd CB states its a service line leak

BUD # 1912090482  
LTC, WRECC  
both sides of road west of Bucksville

Inventory Item And Description	Quantity Ordered	Quantity Used
2 Feet 3/4 Poly		
2 meters		

*None*

*[Handwritten Signature]*

Signature



East Logan Water District  
WORK ORDER 15218

Account #  
Name HENDRICKS, JOE W  
Address  
Telephone Job #

Order Date 12/18/2019  
Status MEDIUM  
Scheduled 12/18/19 12 00 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 33085267 61287384 8678 B14169959 8.706

Description  
Comment RT BRK HSE RT YD  
Requested By JOE

Assigned to MAINTENANCE CREW Completed By *EAH*  
Completed Date 12/18/19 Time 1:05

Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes Plumbers said we have a leak inside the meter box Please check

Inventory Item And Description	Quantity Ordered	Quantity Used
Nothing major		
Leak in front of the		
box on our side		
Fixed - 2 valves 3/4 inch 1 brass nipple.		
56pm.		

*EAH*

Signature \_\_\_\_\_

East Logan Water District  
WORK ORDER 14957

Account # \_\_\_\_\_ Order Date 9/16/2019  
Name INSCOE, JEFF Status MEDIUM  
Address \_\_\_\_\_ Scheduled 09/16/19 09:24 AM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 43605859 63183747 6066 B14168816 6102

Description  
Comment LF, TAN HSE, ACROSS RD AT INTE

Requested By Linda Assigned To MAINTENANCE CREW Completed By CP  
Start Date 9/16/19 Time 9:30 Completed Date 9/16/19 Time 1:30

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes Intersection of Union Grove and Cedar Graveyard on left close to valve marker

Inventory Item And Description	Quantity Ordered	Quantity Used
Pulled new service under Road		
Service was leaking under Road about 1 to 2 gpm		
about 60 feet of 3/4 blue Pipe		60 feet
2 Barbed Fittings		2
4 Pipe Rings		4

Coupe  
Int + Low on  
Warren Lick Rd  
N 36.95784  
H086.87260

Signature 

East Logan Water District  
WORK ORDER 14486

Account #  
Name CELSOR, REBA LOWERY  
Address  
Telephone Job #

Order Date: 5/6/2019  
Status: MEDIUM  
Scheduled: 05/06/19 04:21 PM  
Order Type: CHECK FOR LEAK ON OUR SIDE

METER# WT 51780804      ERT/INTERNAL ID# 64887905      READING 4418      LOCATOR TAG B14168334      READING IN / OUT 4925

Description  
Comment RT BLUE HS L/DR


Requested By James Celsor      Assigned To MAINTENANCE CREW      Completed By G.P. / M.H.  
Start Date 5/1/19      Time :      Completed Date 5/7/19      Time 11:57

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes maybe 2 pinholes our side of connection at meter  
*Replaced S bar two pin holes 2 gpm*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>S bar</i>		<i>1</i>
<i>4 3/4 washers</i>		<i>4</i>
<i>and yes meter is working!! 😊</i>		

Leak Loss 2,880 gallons

Signature 

East Logan Water District  
**WORK ORDER 14505**

Account #  
Name LEACH, DAVID  
Address  
Telephone

Order Date 5/15/2019  
Status MEDIUM  
Scheduled 05/15/19 11:58 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 48979843	61287447	5582	B14167709	

Description

Comment RT, WH/HSE, LF/DR

Requested By Mike

Assigned To MAINTENANCE CREW

Completed By *G.P/MH*

Start Date *5/15/19*

Time

Completed Date *5/15/19*

Time *1:35*

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Mike says its a leak, will call BUD to fix

Inventory Item And Description	Quantity Ordered	Quantity Used

*Friday Bud - ELWD LTC Est. Leak 100,800  
1905151290*

*[Handwritten Signature]*

Signature

East Logan Water District  
WORK ORDER 14271

Account #  
Name HAFNER, DENNIS  
Address  
Telephone

Order Date 3/13/2019  
Status MEDIUM  
Scheduled 03/13/19 10:21 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 51780757  
ERT/INTERNAL ID# 09806144  
READING 1966  
LOCATOR TAG B14169723  
READING IN / OUT

Description  
Comment LF, TAN HSE, 12' LF DR

Requested By dennis  
Assigned To MAINTENANCE CREW  
Completed By *MA*  
Start Date    /    /    Time    :     
Completed Date 3/13/19 Time 10:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes 2707257730

*Water flowing out of meter box*

Inventory Item And Description	Quantity Ordered	Quantity Used
Replaced Rubber WASHER		

Signature *[Handwritten Signature]*



East Logan Water District  
WORK ORDER 14054

Account #  
Name GREGORY, FERRELL R  
Address  
Telephone Job #

Order Date 1/29/2019  
Status MEDIUM  
Scheduled 01/29/19 11:40 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 31464629	09111994	4287	B14169715	

Description  
Comment LF BRK HS R/DR

Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By *MH*  
Start Date 1/29/19 Time \_\_\_\_\_ Completed Date 1/29/19 Time 5:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes leak at meter box

Inventory Item And Description	Quantity Ordered	Quantity Used
1 foot $\frac{3}{4}$ Line		
$\frac{3}{4}$ Coupling		
$\frac{3}{4}$ Nut		

Signature *M. H.*

East Logan Water District  
WORK ORDER 14962

Account #  
Name THOMAS, JEFFREY C.  
Address  
Telephone

Order Date 9/17/2019  
Status MEDIUM  
Scheduled 09/17/19 10:01 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 76352428	72434038	726	B14169093	

Description  
Comment RT W/HSE RT CNR OF YD

Requested By Mike Assigned To MAINTENANCE CREW Completed By MAH  
Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_ Completed Date 9/17/19 Time 12:56

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes \_\_\_\_\_

Inventory Item And Description	Quantity Ordered	Quantity Used

Reading 773  
Leak on customer  
Already notified customer

Mike H

Signature



East Logan Water District  
**WORK ORDER 14325**

Account # \_\_\_\_\_ Order Date 3/29/2019  
Name SCRUGGS, ADAM RAY Status MEDIUM  
Address \_\_\_\_\_ Scheduled 03/29/19 09:00 AM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 9434304	9434304			

Description \_\_\_\_\_  
Comment LF, HSE ON TURNER RD, 2ND METE  
Requested By Mrs. Scruggs Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW

Start Date 04/01/19 10:00 AM Completed Date 04/01/19 10:00 AM

Notes Water boiling out of box  
KAM 9434304-5294-MH  
Mike found a busted meter bottom. Changed out meter. 3/28/19  
Reading was 5294

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 14275**

Account #		Order Date	3/13/2019	
Name	WOODALL, JIMMY	Status	MEDIUM	
Address		Scheduled	03/13/19 11.11 AM	
Telephone	Job #	Order Type	CHECK FOR LEAK ON OUR SIDE	
METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 000019569162	55166361	3452	B14168053	
Description				
Comment	LF STONE HS L/DR 2 MTRS			
Requested By	Assigned To	MAINTENANCE CREW	Completed By	MAINTENANCE CREW
Start Date	03/13/19 11 11 AM	Completed Date	03/13/19 11 11 AM	
Notes	SHUT OFF BROKEN, FIXED-3489-GP			

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 14186**

Account # \_\_\_\_\_ Order Date 2/27/2019  
Name CUNDIFF, PAUL Status MEDIUM  
Address \_\_\_\_\_ Scheduled 02/27/19 07:58 AM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 9135893	9135893	5835		

Description \_\_\_\_\_  
Comment RT, ROCKHSE, RT CNR  
Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW  
Start Date 02/27/19 09 13 AM Completed Date 02/27/19 09 13 AM

Notes meter bottom busted, replaced with kam: 9135893-gp-5842

East Logan Water District  
**WORK ORDER 14064**

Account #  
Name SHIFFLETT, AMANDA P  
Address  
Telephone

Order Date 2/4/2019  
Status MEDIUM  
Scheduled 02/04/19 09 07 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 9135917	9135917	5650		

Description  
Comment LF/ BROWN TR/ RT OF DR  
Requested By Amanda Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW  
Start Date 02/11/19 09 57 AM Completed Date 02/11/19 09 57 AM

Notes Please check for leak at meter  
METER BOTTOM BUSTED, REPLACED METER WITH KAM: 9135917-GP

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 14063**

Account #		Order Date	2/4/2019
Name	HAMPTON, RICKEY L	Status	MEDIUM
Address		Scheduled	02/04/19 09:05 AM
Telephone	Job #	Order Type	CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 82460025	75071641	1125	B14892793	

Description

Comment LF,HSE IN FLD,LF BEFORE 68

Requested By Rickey Hampton      Assigned To MAINTENANCE CREW      Completed By MAINTENANCE CREW

Start Date 02/08/19 09 47 AM      Completed Date 02/08/19 09 47 AM

Notes Rickey called to say there is water leaking in box. Please check

The regulator was blown. Replaced regulator and 2 washers. Leaking about 10-12 gpm - GP

East Logan Water District  
**WORK ORDER 13964**

Account # \_\_\_\_\_ Order Date 1/8/2019  
Name MCCUE, ROBERT A Status MEDIUM  
Address \_\_\_\_\_ Scheduled 01/08/19 11:20 AM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 22053546	22053546	14827	B15450954	

Description \_\_\_\_\_  
Comment BY RED GATE, 12" INSIDE FENCE  
Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW  
Start Date 01/09/19 11:21 AM Completed Date 01/09/19 11:21 AM

Notes cust stated that water is running under the meter, where we set the new meter  
GP & MH SAY THAT IT IS GROUND WATER FROM WHERE WE HAD TO BOAR RD OUT

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 15239**

Account # \_\_\_\_\_ Order Date 12/27/2019  
 Name BROS. COLES Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 12/27/19 08 53 AM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE  
 METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
 WT 22201368 09118080 6831 B14169253  
 Description \_\_\_\_\_  
 Comment RT, BRK HSE ACROSS BYPASS. LF  
 Requested By MR COLES Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_  
 Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_ Completed Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
 Notes \_\_\_\_\_

Inventory Item And Description	Quantity Ordered	Quantity Used





East Logan Water District  
**WORK ORDER 15037**

Account # \_\_\_\_\_ Name HOLLOWAY, MATT Order Date 10/4/2019  
Address \_\_\_\_\_ Status MEDIUM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Scheduled 10/04/19 10:18 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
WT 37330401 10467071 706 B14165425

Description \_\_\_\_\_  
Comment LF L/LONG GR DR  
Requested By Kenneth Belcher Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_  
Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_ Completed Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Mike Hines says there is a small service leak. Maybe caused by bushhog. Another W/O says a repair made here in 2017.  
BUD #1910041146  
marked by 10-8-19 @ 11:00 am  
LTC  
WRECC  
ELWD

Inventory Item And Description	Quantity Ordered	Quantity Used

*Dipped*

Signature \_\_\_\_\_

East Logan Water District  
WORK ORDER 14628

Account #  
Name SOUTHERLAND MIKE & CONNIE  
Address  
Telephone

Order Date 6/17/2019  
Status MEDIUM  
Scheduled 06/17/19 12:54 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 50055733      ERT/INTERNAL ID# 63097889      READING 7586      LOCATOR TAG B14168640      READING IN / OUT

Description  
Comment RT.BRK/HSE RT/CNR

Requested By \_\_\_\_\_ Assigned To \_\_\_\_\_ Completed By \_\_\_\_\_  
Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_\_ Completed Date 6/17/19 Time \_\_\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes \_\_\_\_\_

Inventory Item And Description	Quantity Ordered	Quantity Used

Customer leak  
meter rapidly turning  
turned meter off & notified customer

Signature LA

East Logan Water District  
WORK ORDER 14527

Account # Name Address Telephone Job # Order Date Status Scheduled Order Type  
BALD KNOB CHURCH  
5/28/2019  
MEDIUM  
05/28/19 09 40 AM  
CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 69361410	63066022	150	B14166657	

Description  
Comment RT BLUE HS BEHIND CH R/DR 2 MT  
Requested By doug steenbergen Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW  
Start Date 05/29/19 08 33 AM Completed Date 05/29/19 08 33 AM

Notes water in meter box-0151-meter beside this one is turning. called and adv. the customer that they may have a small leak on their side of the meter

Signature \_\_\_\_\_

East Logan Water District  
WORK ORDER 14533

Account #  
Name BRADY, WAYNE  
Address  
Telephone

Order Date 5/30/2019  
Status MEDIUM  
Scheduled 05/30/19 09:19 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 33586746      ERT/INTERNAL ID# 10565493      READING 5193      LOCATOR TAG B14162144      READING IN / OUT

Description  
Comment RT.TAN DW. 40' RT DR

Requested By Loyd      Assigned To MAINTENANCE CREW      Completed By *MH*

Start Date   /  /   Time   :        Completed Date 6.1.5.17 Time 10:15

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes There is a leak around this meter or service line

*Reading 5196 Leaking from Right outside  
Customer Side of Box*

Inventory Item And Description	Quantity Ordered	Quantity Used

*click sound*

*if meter is turning*

*see if customer is using water*

*Call back. me & will try to call them*

Signature *[Handwritten Signature]*

East Logan Water District  
**WORK ORDER 14527**

Account # \_\_\_\_\_ Order Date 5/28/2019  
Name BALD KNOB CHURCH Status MEDIUM  
Address \_\_\_\_\_ Scheduled 05/28/19 09:40 AM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 69361410	63066022	150	B14166657	

Description \_\_\_\_\_  
Comment RT BLUE HS BEHIND CH R/DR 2 MT  
Requested By doug steenbergen Assigned To MAINTENANCE CREW Completed By *EH / MJD*  
Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_ Completed Date *5-28-19* Time *1:13*

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes water in meter box  
*Reading 0151*

Inventory Item And Description	Quantity Ordered	Quantity Used

*Meter beside this one is turning  
# 70978972 Reading 0836*

Signature *[Handwritten Signature]*

East Logan Water District  
WORK ORDER 14306

Account # \_\_\_\_\_ Order Date 3/22/2019  
Name ARNEY, ALTON Status MEDIUM  
Address \_\_\_\_\_ Scheduled 03/22/19 02:33 PM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
WT 34697007 09966405 8332 B14462994

Description \_\_\_\_\_  
Comment RT, HSE OFF RD, RT IN FIELD. B  
Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By MH  
Start Date 3/22/19 Time 5:30 Completed Date 3/22/19 Time 5:30

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes \_\_\_\_\_

Inventory Item And Description	Quantity Ordered	Quantity Used

meter is close to white concrete well house  
Mrs. Arney will place flag there.

She saw water & wants to make sure its not  
a leak, either our leak or hers.

Leak on  
her side of meter  
Remains of

8488.  
Mrs. Arney knows

M.H.

Signature \_\_\_\_\_









East Logan Water District  
WORK ORDER 14408

Account #  
Name WALPOLE, JOHN  
Address  
Telephone

Order Date 4/10/2019  
Status MEDIUM  
Scheduled 04/10/19 09:37 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 69361484	63066096	1599	B14166459	

Description  
Comment LF, WH/HS L/DR

Requested By John Assigned To MAINTENANCE CREW Completed By *C.P. / M.H.*  
Start Date 4/10 Time 9:36 Completed Date 4/10/19 Time 9:36

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Left of drive between mailbox and meter is wet Please check for leak  
Call him if you need to get in fence He will show you the route

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>No Leak</i>		

Signature *P. [Signature]*

East Logan Water District  
WORK ORDER 14398

Account # \_\_\_\_\_ Order Date 4/8/2019  
Name CORUM, MIKE Status MEDIUM  
Address \_\_\_\_\_ Scheduled 04/08/19 01 18 PM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 85798115 58647033 7278 B14168582

Description \_\_\_\_\_  
Comment LF, WH HSE, 30' RT DR IN FIELD  
Requested By ms corum Assigned To MAINTENANCE CREW Completed By *ms*  
Start Date   /  /   Time   :   Completed Date   /  /   Time   :  

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes customer says that middle of drive there is a continuous puddle, where we had fixed a leak there before  
*also lg. Spender & source plz*

Inventory Item And Description	Quantity Ordered	Quantity Used

*Track Florida Sample*

*.05 per Tanker  
no fluoride.  
no leak*

*ms*

Signature

East Logan Water District  
WORK ORDER 14431

Account #  
Name BRYANT, CODY W  
Address  
Telephone Job #

Order Date 4/19/2019  
Status MEDIUM  
Scheduled 04/19/19 04:00 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 69361526 ERT/INTERNAL ID# 63066138 READING 5045 LOCATOR TAG B14169106 READING IN / OUT

Description  
Comment LF, TAN HS R/YD

Requested By Cody Assigned to MAINTENANCE CREW Completed By *MH*  
Start Date   /  /   Time    Completed Date 4/23/19 Time 11:57

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes 2 or 3 meters in a row, and meter box in question is closest to this house Box is full of water, and other was not  
Please check for possible leak

*Reading 5080 Tested Negative for Chlorine no sound  
Box is lower than ground level*

Inventory Item And Description	Quantity Ordered	Quantity Used

Signature *Mike*



East Logan Water District  
**WORK ORDER 14429**

Account #  
Name ZIMMERMAN, DAVID  
Address  
Telephone

Order Date 4/19/2019  
Status MEDIUM  
Scheduled 04/19/19 08:35 AM  
Order Type CHECK METER

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 42033279 09159507 66 B15042982

Description

Comment LF, GRAY HSE, IN FIELD ON RT OF

Requested By Linda Assigned To MAINTENANCE CREW Completed By

Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_ Completed Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Between here and creek, someone noticed water running out of ground by fence. Please check.

Inventory Item And Description	Quantity Ordered	Quantity Used
no leak		

Signature \_\_\_\_\_

East Logan Water District  
WORK ORDER 13881

Account #  
Name CLAYPOOL, ROY  
Address  
Telephone

Order Date 1/2/2019  
Status MEDIUM  
Scheduled 01/02/19 09 25 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 51170349 72175797 1675 B14168789

Description  
Comment RT. WOOD SIDE HSE, 20' LF. LF

Requested By Mrs Claypool Assigned To MAINTENANCE CREW Completed By *MH*

Start Date *1/1* Time *9:49* Completed Date *1/1/19* Time *9:49*

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes *Need to Replace Regulator Looking*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Replace Reg 1675</i>		
<i>Reg was before the meter 70 psi</i>		

*Sofia*  
*MH*

Signature

East Logan Water District  
**WORK ORDER 14648**

Account # \_\_\_\_\_ Order Date 6/21/2019  
Name FULLER TONY & MARSHA Status MEDIUM  
Address \_\_\_\_\_ Scheduled 06/21/19 08 10 AM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
WT 47418212 63153564 882 B14169931

Description

Comment LF, ROCK HSE, LF CNR

Requested By tony fuller Assigned To MAINTENANCE CREW Completed By *EH-MH*  
Start Date   /  /   Time   :   Completed Date   /  /   Time   :  

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes around meter box, is wet and standing water

*2 readings - 9:11*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Meter is barely turning, possible leak on customers side.</i>		

Signature *EH*



East Logan Water District  
WORK ORDER 14644

Account #  
Name MCCLLOUD HAROLD D  
Address  
Telephone Job #

Order Date 6/20/2019  
Status MEDIUM  
Scheduled 06/20/19 11:57 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 50180691      ERT/INTERNAL ID# 10257121      READING 782      LOCATOR TAG B14169767      READING IN / OUT

Description

Comment RT, WH DBL W LF DR

Requested By

Assigned To MAINTENANCE CREW

Completed By *EA - Matt*

Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_

Completed Date *6/20/19* Time *11:57*

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes under driveway, believe there is a water leak, no sign of water visible, but driveway is rising and falling right over where they believe that the main water line is

*Reading 0833*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>main water line across road.</i>		
<i>Damage not caused by water company.</i>		

Signature *EA*

East Logan Water District  
WORK ORDER 14655

Account #  
Name BILYEU, CLAY E  
Address  
Telephone Job #

Order Date 6/26/2019  
Status MEDIUM  
Scheduled 06/26/19 08:38 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 9434302  
ERT/INTERNAL ID# 9434302  
READING 176  
LOCATOR TAG  
READING IN / OUT

Description  
Comment RT, BLUE HSE, MDL YD

Requested By tiffany sweeney

Assigned To MAINTENANCE CREW

Completed By *MHA/FAH*

Start Date    /    /    Time    :   

Completed Date 6/26/19 Time 11:01

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes lady called in stated that water standing in rd directly in front of this residence We just fixed a leak here last week

*2" gas line directly on top of main line*

Inventory Item And Description	Quantity Ordered	Quantity Used

*Reading 2785 L<sub>2</sub> O  
Small wet spot 50' up Rd from meter no chlorine*

*MHA/FAH*

Signature

East Logan Water District  
**WORK ORDER 14653**

Account #  
Name KROHN, CINDY S  
Address  
Telephone

Order Date 6/25/2019  
Status MEDIUM  
Scheduled 06/25/19 09:27 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 65798117      ERT/INTERNAL ID# 58647035      READING 1650      LOCATOR TAG B14168530      READING IN / OUT

Description  
Comment RT HSE LF OF YD

Requested By cindy krohn      Assigned To MAINTENANCE CREW      Completed By  
Start Date      /      /      Time      :      Completed Date      /      /      Time      :

Make      Size/Type      Multiplier  
Notes cust called stated that there was water coming out of meter box

Inventory Item And Description	Quantity Ordered	Quantity Used

*R-1492*

*no work in box*

Signature *CL LA*

East Logan Water District  
WORK ORDER 14654

Account # \_\_\_\_\_ Order Date 6/26/2019  
Name JACKSON, JAMES Status MEDIUM  
Address \_\_\_\_\_ Scheduled 06/26/19 08:09 AM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 31152888 09964879 2302 B14166435

Description \_\_\_\_\_  
Comment RT, WH HSE, LF CNR YD  
Requested By Mr. Jackson Assigned To MAINTENANCE CREW Completed By *[Signature]*  
Start Date *6/26/19* Time \_\_\_\_\_ Completed Date *6/26/19* Time \_\_\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes Mr. Jackson called to say he thinks we have a leak

Inventory Item And Description	Quantity Ordered	Quantity Used

\* Checked everywhere we fixed before found no sign of leak  
Leak on customer side

9,300 gal used this Mo.  
Left message on Ricky's phone,  
talked with calculator - told  
leak on their side.

93

Easi Logan Water District  
WORK ORDER 14719

Account #  
Name PARRISH, RANDY  
Address  
Telephone

Order Date 7/16/2019  
Status MEDIUM  
Scheduled 07/16/19 08 14 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 000063869481      ERT/INTERNAL ID# 56501990      READING 6472      LOCATOR TAG B14167311      READING IN / OUT

Description

Comment LF, BEIGE HSE, RT DR READ 2

Requested By Mrs. Parrish

Assigned To MAINTENANCE CREW

Completed By

Start Date / / Time

Completed Date 7/16/19 Time 10:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes She said she has low pressure. about a pencil stream

Inventory Item And Description	Quantity Ordered	Quantity Used
meter is moving. no visible weeps.		

Signature EH

East Logan Water District  
WORK ORDER 14672

Account #  
Name WOODARD, WILLIAM  
Address  
Telephone Job #

Order Date 7/1/2019  
Status MEDIUM  
Scheduled 07/01/19 09 36 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 44812547 09720083 8021 B14167270

Description  
Comment RT, BRK HSE, MYD

Requested By Bill Woodard

Assigned To MAINTENANCE CREW

Completed By *WJ*

Start Date   /  /   Time   :  

Completed Date 7/1/19 Time 10:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes

*Positive Chlorine Test  
may be A Service Tube OR Main Line Seeping*

Inventory Item And Description	Quantity Ordered	Quantity Used

Signature

*Michael*

East Logan Water District  
WORK ORDER 14725

Account #  
Name VICKERS, CHERYL A.  
Address  
Telephone Job #

Order Date 7/16/2019  
Status MEDIUM  
Scheduled 07/16/19 02:45 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 42602816	63184003	5131	B14167593	

Description  
Comment LF BRK HSE 20' LF DRIVE

Requested By MR VICKERS Assigned To MAINTENANCE CREW Completed By *MYH*  
Start Date   /  /   Time   :  :   Completed Date 7/16/19 Time 1:51

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes CUSTOMER STATES THAT IN/AROUND METER BOX IS WET, AND BELIEVES THAT IT'S A LEAK  
*NO SIGN OF LEAK NO WATER IN OR AROUND BOX*  
*Reading 5137*

Inventory Item And Description	Quantity Ordered	Quantity Used

*MYH*

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 14958**

Account # \_\_\_\_\_ Order Date 9/16/2019  
Name SHOCKLEY, KELLIE G Status MEDIUM  
Address \_\_\_\_\_ Scheduled 09/16/19 02:42 PM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATION TAG	READING IN / OUT
WT 51780733	72175806	3518	B14167684	

Description \_\_\_\_\_  
Comment \_\_\_\_\_  
Requested By LINDA Assigned To MAINTENANCE CREW Completed By *MH*  
Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_ Completed Date *9/16/19* Time *11:05*

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Customer states water is in box, and meter is slightly turning. Please make sure connections and meter bottom is good and this is not at our connection.

Inventory Item And Description	Quantity Ordered	Quantity Used

Reading 3557  
Leaking where customer hooks to our stub out  
Possibly at customer shut off.

Signature *Mike B*



East Logan Water District  
**WORK ORDER 14258**

Account #  
Name WATSON, DAVID  
Address  
Telephone Job #

Order Date 3/10/2019  
Status MEDIUM  
Scheduled 03/10/19 01:53 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 33973769      ERT/INTERNAL ID# 08840797      READING 2605      LOCATOR TAG B14167670      READING IN / OUT 2978

Description  
Comment LT. AT CNR OF NEXT FENCE

Requested By Linda      Assigned To MAINTENANCE CREW      Completed By  
Start Date 3/10/19 Time 11:36      Completed Date 3/10/19 Time 11:36

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes: Mike says its leaking at the nipple connection. Gary can fix this. Non-emerg BUD, if its only LTC, Call TLC and ask for locate dept. Tell them we phoned in a BUD and would like to fix today (Monday) if they can send someone to mark the phone line. Ask them to notify Gary when located.

Inventory Item And Description	Quantity Ordered	Quantity Used
Thread pvc cuppling 3/4		1
Threading Pass barbed Fittings 3/4		1
Threading Shark bite 3/4		1
3/4 blue pvc 8 in long		1

Signature 

East Logan Water District  
**WORK ORDER 13890**

Account #  
Name BOLSTER, SANDRA M  
Address  
Telephone Job #

Order Date 1/7/2019  
Status MEDIUM  
Scheduled 01/07/19 07:47 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 81271714	74600786	382	B14167213	478

Description  
Comment LF, GRAY HSE, R/CNR T/LF

Requested By Sandra Assigned To MAINTENANCE CREW Completed By *[Signature]*  
Start Date 1/7/19 Time 7:47 AM Completed Date 1/7/19 Time 9:15 AM

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Box full of water and running down ditch  
*1.5 hrs work on 2" pipe on side*

Inventory Item And Description	Quantity Ordered	Quantity Used

Signature *[Signature]*

EAST LOGAN WATER DISTRICT  
WORK ORDER 14717

Account # \_\_\_\_\_ Name KING BLAKE Address \_\_\_\_\_ Telephone \_\_\_\_\_ Job # \_\_\_\_\_

METER# WT 33973721 ERT/INTERNAL ID# 08845412 READING 9573 LOCATOR TAG B15306851 READING IN / OUT 0573

Description \_\_\_\_\_ Comment RT TRLR MYD

Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By EH

Start Date 7/17/19 Time \_\_\_\_\_ Completed Date 7/17/19 Time 11:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes \_\_\_\_\_

Inventory Item And Description	Quantity Ordered	Quantity Used
water is running in from their trap. possible leak inside house.		

Signature EH

East Logan Water District  
**WORK ORDER 14728**

Account #  
Name BORDERS, FRED & SHARON  
Address  
Telephone Job #

Order Date 7/17/2019  
Status HIGH  
Scheduled 07/17/19 08:32 AM  
Order Type CHECK METER

METER# WT 66579001    ERY/INTERNAL ID# 59497403    READING 2447    LOCATOR TAG B14169145    READING IN / OUT

**Description**

Comment HSE OFF RD RT OF DR

Requested By Mr. Border

Assigned to MAINTENANCE CREW

Completed By *MJA*

Start Date 7/17/19 Time

Completed Date 7/17/19 Time 8:30

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Customer states they have been in CA since end of June. They turned meter off when they left. They say there should be no usage. Please check to see if meter is off, and if it is, if the cutoff valve is working

*Reading 2502*

Inventory Item And Description	Quantity Ordered	Quantity Used

*Shut off WAS Sweet Spot  
Need to Replace*

*Meter is Turning  
Possible Leak*

*MJA*

Signature





Castrogon Water District  
WORK ORDER 14294

Account # \_\_\_\_\_  
Name HUNT DONNA M  
Address \_\_\_\_\_  
Telephone \_\_\_\_\_

Order Date 3/19/2019  
Status MEDIUM  
Scheduled 03/19/19 10:27 AM  
Order Type CHECK METER

METER# WT 000063869480      ERT/INTERNAL ID# 56501989      READING 4478      LOCATOR TAG B14168907      READING IN / OUT \_\_\_\_\_ 4483

Description \_\_\_\_\_  
Comment RT WH/HS L/DRIVE

Requested By MS HUNT      Assigned to MAINTENANCE CREW      Completed By *[Signature]*

Start Date 3/19 Time \_\_\_\_\_      Completed Date 3/19/19 Time 1:50

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes SHUT OFF IS NOT SHUTTING OFF, STILL LEAKING. CUST HAS PLUMBERS AT THIS LOCATION


Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Replaced shut off And washers All 4 of them</i>		

Signature *[Signature]*

WORK ORDER 15230

Account # \_\_\_\_\_ Order Date 12/23/2019  
 Name OFFUTT, WANDA Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 12/23/19 09:39 AM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type \_\_\_\_\_  
 METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
 WT 78785968 73606954 704 B14168021 \_\_\_\_\_  
 Description \_\_\_\_\_  
 Comment LF BRN HSE, RT YD AT F O  
 Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_  
 Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_ Completed Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_  
 Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
 Notes cust shut off is not workign needing to do some repairs inside

Inventory Item And Description	Quantity Ordered	Quantity Used

*Repaired*  


Signature \_\_\_\_\_



EAST Logan Water District  
WORK ORDER 15013

Account #  
Name OSMANOVIC MIRZA  
Address  
Telephone Job #

Order Date 9/30/2019  
Status MEDIUM  
Scheduled 09/30/19 12:57 PM  
Order Type ABNORMAL SMELL/COLOR

METER# WT 84708362  
ERT/INTERNAL ID# 90041859  
READING 6  
LOCATOR TAG B15450913  
READING IN / OUT

Description

Comment RT, LFT of DR by elec pole

Requested By

Assigned to MAINTENANCE CREW

Completed By *MH*

Start Date

*1 / 1*

Time

Completed Date

*10/15/19*

Time

*1:00*

Make

Size/Type

Multiplier

Notes

please flush lines so that water does not smell like sulfur

*Flushed 15,450 gal*

Inventory Item And Description	Quantity Ordered	Quantity Used

*end of line @ PEP*

*M. H.*

Signature

WORK ORDER 15025

Account #  
Name BELCHER, PATRICIA  
Address  
Telephone

Order Date 10/3/2019  
Status MEDIUM  
Scheduled 10/03/19 09:39 AM  
Order Type

METER# WT 84200084      ERT/INTERNAL ID# 89837147      READING 188      LOCATOR TAG B14170245      READING IN / OUT

Description

Comment LF, WOOD SIDE HSE, LF YD

Requested By linda brady

Assigned To MAINTENANCE CREW

Completed By MA

Start Date / / Time :

Completed Date 10/14/19 Time 9:02

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes 2707256302

see about putting a riser on the meter. per land has sank in and they are trying to fill in, but not sure what to do about around the meter box

Inventory Item And Description	Quantity Ordered	Quantity Used
meter is falling possible repair on customer's side.		

~~Added a Round Riser~~  
Added a Riser (USED SCRAP) Box

Signature *Y.M. Beth J*

WORK ORDER 14854

Account # \_\_\_\_\_ Order Date 8/19/2019  
 Name FULLER, CHAD D Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 08/19/19 08 25 AM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type \_\_\_\_\_

METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
 WT 81271681 74600753 26 B15447946

Description \_\_\_\_\_  
 Comment B4 PP. RT OF WATSON LN  
 Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_  
 Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_ Completed Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
 Notes meter bottom busted.

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>100 - meters OK - assigned 8/22</i>		
<i>100 - meters OK - assigned 8/22</i>		

East Logan Water District  
WORK ORDER 14829

Account #  
Name RANDOLPH, DARLENE  
Address  
Telephone Job #

Order Date 8/9/2019  
Status MEDIUM  
Scheduled 08/09/19 08:27 AM  
Order Type CHECK PRESSURE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 50180717	10266484	1242	B14169632	1327

Description  
Comment RT, GRAY DBL WIDE, LF LOT, FIE

Requested By Assigned To MAINTENANCE CREW Completed By

Start Date 8/9/19 Time 8:00 AM Completed Date 8/15/19 Time 1:00 PM


Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes check pressure, logan tele group hit line on customer side, and repaired it, since this time the customer has had no pressure

...ff  
will you please check outside hydrant that is in the front of the house as well, since we are already out there, that way they know if this is on our side

Inventory Item And Description	Quantity Ordered	Quantity Used
<del>AKU # 14116430</del>		
(5002)		
Someone has change MXU I think the Unmetered do not meter house was 80 PSI		
100 PSI		
36.82490		
- 86.71474		

Signature



Water Meter District  
**WORK ORDER 15156**

Account # \_\_\_\_\_ Order Date 11/18/2019  
 Name FULLER, DEANNA R Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 11/18/19 11 28 AM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type \_\_\_\_\_  
 METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
 WT 66684121 59596209 2460 B14168118  
 Description \_\_\_\_\_  
 Comment LT, GRAY HSE. EOL LT/DR, T/A.  
 Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_  
 Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_\_ Completed Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
 Notes MAN STATED THAT SHUT OFF VALVE IS NOT WORKING CORRECTLY. THAT WATER IS STILL FLOWING THROUGH THE METER

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Dug box up &amp; replaced shut off on meter.</i>		

*Completed  
12/12/19  
DB*

East Logan Water District  
**WORK ORDER 13887**

Account #  
Name MILLER, BRENDA K  
Address  
Telephone Job #

Order Date 1/4/2019  
Status MEDIUM  
Scheduled 01/04/19 10:23 AM  
Order Type MISCELLANEOUS

METER# WT 9135954      ERT/INTERNAL ID# 9135954      READING 69      LOCATOR TAG      READING IN / OUT

Description

Comment RT, TRLR. M/YD

Requested By customer      Assigned To MAINTENANCE CREW      Completed By *MJ*

Start Date *1/1* Time :      Completed Date *1/19/19* Time :

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Customer says water is still milky Will you see if you need to flush in this area

*Flushed 8,000 - 8,500 gals*

Inventory Item And Description	Quantity Ordered	Quantity Used

Signature *Mike H*

WATER DISTRICT  
WORK ORDER 14163

Account #  
Name GORMLEY, MILDRED  
Address  
Telephone Job #

Order Date 2/15/2019  
Status MEDIUM  
Scheduled 02/15/19 10:21 AM  
Order Type CHECK PRESSURE

METER# WT 50056603    ERT/INTERNAL ID# 08850106    READING 4012    LOCATOR TAG B14168860    READING IN / OUT 4057

Description  
Comment LF, BRK HSE, RT CNR

Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW    Completed By P/E.T.  
Start Date 1/1 Time \_\_\_\_\_    Completed Date 2/18/19 Time 2:58

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes pressure is extremely low, milky water, etc  
\* METER IS WORKING

Inventory Item And Description	Quantity Ordered	Quantity Used
* 35-40 PSI		
* FLUSHED FOR 2 HRS. FRIDAY	14,400	Flushed
ADD 4 HRS TUESDAY	28,000	Flushed

Signature P. Price

WORK ORDER 14158

Account #  
Name GOODHUF TRAVIS W  
Address  
Telephone Job #

Order Date 2/13/2019  
Status MEDIUM  
Scheduled 02/13/19 01 24 PM  
Order Type ABNORMAL SMELL/COLOR

METER# WT 52473703  
ERT/INTERNAL ID# 63803441  
READING 3741  
LOCATOR TAG B14169954  
READING IN / OUT

Description  
Comment BRK HSE. MYD DON'T DRIVE IN Y

Requested By Assigned To MAINTENANCE CREW Completed By GP/ET/RH  
Start Date 1/1/19 Time : Completed Date 2/13/19 Time 10:39

Make Size/Type Multiplier

Notes air in lines, milky color, clears up once settles for a while

Flushed 14,400 gals

Investigation Item	Description	Quantity Ordered	Quantity Used
12:39	about 6 in and a 3 in pipe		
	Flushed at blow off at 730 Old Quality Rd		
	across the road!! 14,400 gallons		

Signature 



WORK ORDER 14160

Account #  
Name STRATTON STEPHANIE J  
Address  
Telephone Job #

Order Date 2/14/2019  
Status MEDIUM  
Scheduled 02/14/19 08 29 AM  
Order Type

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 33973747 63524748 170 B14170230 17012.9

Description  
Comment LFT W/TRLR LFT OF DR

Requested By Assigned To MAINTENANCE CREW Completed By GP/MM/RH/ET

Start Date 1/1/19 Time Completed Date 2/15/19 Time 4:00

Make Size/Type Multiplier

Notes turn off at corp

*Turned off at corp Knocked a hole in Main but Repaired it!*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>17012.9</i>		
<i>2 3in Knock ons</i>		
<i>1 3in pipe 18 1/2 Long</i>		

Est. Leak 27,500  
Est Flush 12,600

Signature *[Signature]*

East Logan Water District  
WORK ORDER 14331

Account #  
Name : SPITZ, DENNIS W  
Address  
Telephone

Order Date 4/1/2019  
Status MEDIUM  
Scheduled 04/01/19 08:40 AM  
Order Type

Job #

METER# WT 52473854      ERT/INTERNAL ID# 07306283      READING 7701      LOCATOR TAG B14169259      READING IN / OUT 7729

Description

Comment LE TRLR, LF YD

Requested By *Gary Rupp*      Assigned To MAINTENANCE CREW      Completed By *GP*

Start Date *1/1/19* Time *1:15*      Completed Date *4/1/19* Time *3:15*

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes read out and lock, putting into suspension until october

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>clean Gravel pit.</i>		
<i>BOTH sides of pit.</i>		
<i>8:00 AM.</i>		

*ELWD  
LTC.  
Mid Valley Pipeline - cleaned  
WRECC  
190403 2000*

*26*

Signature

*[Handwritten Signature]*

East Logan Water District  
WORK ORDER 14732

Account #  
Name MAYES, LARRY B  
Address  
Telephone Job #

Order Date 7/18/2019  
Status MEDIUM  
Scheduled 07/18/19 08:09 AM  
Order Type CHECK METER

METER# WT 55507404      ERT/INTERNAL ID# 52650301      READING 6953      LOCATOR TAG B14170118      READING IN / OUT

Description  
Comment BLUE, RT, TRLR, RT OF YD

Requested By Linde      Assigned To MAINTENANCE CREW      Completed By *MJA*

Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_      Completed Date *7/18/19* Time *9:00*

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes Larry said fiber optic contractors hit his line, also busted meter lid. Check MXU, etc

Inventory Item And Description	Quantity Ordered	Quantity Used
Replaced <i>lid</i>		
Need Square Box		

*St. Hill 3*

*New Friendship Rd. - Tues July 23*  
*off Aug. 9*

*ELWD, LTC, WRECC*

*Bud # 190 719 0811*

Signature *[Handwritten Signature]*





East Logan Water District  
WORK ORDER 15333

Account #  
Name PEARSON, CONNIE L  
Address  
Telephone

Order Date 1/13/2020  
Status MEDIUM  
Scheduled 01/13/20 09:25 AM  
Order Type MISCELLANEOUS

METER# WT 41604137      ERT/INTERNAL ID# 09666925      READING 9798      LOCATOR TAG B14169009      READING IN / OUT

Description  
Comment CORNER OF 100 & WARREN RD

Requested By Linda      Assigned To MAINTENANCE CREW      Completed By

Start Date \_\_\_/\_\_\_/\_\_\_      Time \_\_\_:\_\_\_      Completed Date \_\_\_/\_\_\_/\_\_\_      Time \_\_\_:\_\_\_

Make \_\_\_\_\_      Size/Type \_\_\_\_\_      Multiplier \_\_\_\_\_

Notes Need to replace cutoff valve and customer will put in a cutoff valve behind the meter *and get reading*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Dug box up. changed shut-off valve</i>		
<i>Completed 1/16/20</i>		
<i>(Signature)</i>		

Call Connie

as you are heading out.

Show them where to install their cut-off valve.

*Lady is out of town.*

BUD <sup>by</sup> 1/15/20

*Pool 1005280*

ATT  
ATmos  
LTC

# 2001131256

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 14935**

Account #  
Name STEVENSON, JAMES  
Address  
Telephone Job #

Order Date 9/9/2019  
Status MEDIUM  
Scheduled 09/09/19 01:47 PM  
Order Type CHECK METER

METER# ERT/INTERNAL ID# READING LOCATOR TAG  
WT 47418197 09450611 1504 B14163736

READING IN / OUT  
1568 - 1766

Description  
Comment RT X FROM B.O T/A T/LF

Requested By Assigned To MAINTENANCE CREW Completed By  
Start Date / / Time : Completed Date 9/10/19 Time 5:50

Make Size/Type Multiplier  
Notes PLEASE CHANGE OUT THIS METER

Inventory Item And Description	Quantity Ordered	Quantity Used
Shutoff isn't working		
meter is working		
Done		

by Oct 2 @ 8:15

300-97990  
- 800-80112

ELWD  
LTC  
WRECC - crew

# 1909301825

EM

Signature

East Logan Water District  
**WORK ORDER 14923**

Account #  
Name TROYER JR, ROMAN  
Address  
Telephone Job #

Order Date 9/9/2019  
Status MEDIUM  
Scheduled 09/09/19 01 09 PM  
Order Type

METER# WT 41032035  
SERIAL ID# 10505695  
READING 2477  
LOCATOR TAG B14166440  
READING IN / OUT 2505 126117  
Description  
Comment RT, TRLR, 75' LF DR  
Requested By  
Assigned to MAINTENANCE CREW  
Completed By EH  
Start Date / / Time :  
Completed Date 9/12/19 Time 1:55

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes CHECK METER TO MAKE SURE WORKING AND READING

Inventory Item And Description	Quantity Ordered	Quantity Used
Tried to change and the		
shutoff wasn't working.		
New meter Q134443		
meter isn't counting.		
New Reading 0000		
<del>Replaced meter/shutoff</del>		

*X Quality Invoice number*  
*- Friday @ 12:00 -*  
*ELWD, LTC*  
*Both Sites*  
*Bud# 1909251320*  
*Completed 12/10/19*

EH

Signature





East Logan Water District  
**WORK ORDER 13882**

Account #		Order Date	1/2/2019
Name	ADCOCK, LISA	Status	MEDIUM
Address		Scheduled	01/02/19 09 48 AM
Telephone	Job #	Order Type	CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 82995123	89283332	1152	B14169890	

Description  
Comment RT, TRLR OFF RD. 20' RT DR  
Requested By Linda Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW  
Start Date 01/02/19 09 36 AM Completed Date 01/02/19 09 36 AM

Notes Lisa 270/847/1165 home after 2 today Show her how to check meter for leak, and see if leak is on us  
no visible sign of leak on our side

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 13890**

Account #  
Name BOLSTER, SANDRA M  
Address  
Telephone Job #  
Order Date 1/7/2019  
Status MEDIUM  
Scheduled 01/07/19 07.47 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 81271714	74600786	382	B14167213	

Description  
Comment LF, GRAY HSE, R/CNR T/LF  
Requested By Sandra Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW  
Start Date 01/07/19 12 39 PM Completed Date 01/07/19 12 39 PM

Notes Box full of water and running down ditch  
leak on cust side-478-gp

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 13925**

Account #  
Name CHURCH OF GOD PROPHECY %  
Address  
Telephone Job #

Order Date 1/8/2019  
Status MEDIUM  
Scheduled 01/08/19 09:56 AM  
Order Type ZERO USAGE/CHECK OUT

METER# WT 83545720      ERT/INTERNAL ID# 89536832      READING 4      LOCATOR TAG B14166156      READING IN / OUT

Description  
Comment RT, WHITE CHURCH, LF DRIVE  
Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW      Completed By MH GURH  
Start Date 1/1 Time \_\_\_\_\_      Completed Date 1/8/19 Time 3:46

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes Meter is Registering but its Turned off. Leak on our side 5 gpm

Inventory Item And Description	Quantity Ordered	Quantity Used
<u>1 3/4 compression coupling</u>		
<u>3 3/4 inserts</u>		
<u>1 3/4 pipe about 1ft Long</u>		
<u>0004 Reading</u>		
<u>Repaired</u>		

\* CROSS STREET = MORTON MILLER

APP. Feb 1st

AH City of Aub  
Logan Tele  
WRECC  
LTRWC

1901110259

Price  
MH

Signature

East Logan Water District  
**WORK ORDER 14956**

Account #		Order Date	9/16/2019		
Name	GASKEY ASHLEY N	Status	MEDIUM		
Address		Scheduled	09/16/19 07:27 AM		
Telephone	Job #	Order Type	CHECK FOR LEAK ON OUR SIDE		
METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT	
WT 9434396	9434396				
Description					
Comment	RT, TRLR, RT DR				
Requested By	Mrs. Gaskey	Assigned To	MAINTENANCE CREW	Completed By	MAINTENANCE CREW
Start Date	09/14/19 08 31 AM			Completed Date	09/14/19 08 31 AM

Notes Customer called to say they had determined water was spraying from underneath meter. Ethan fixed this Saturday  
REPLACED METER WITH KAM 97434396 PER METER BOTTOM BUSTED-0305-EH

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 14955**

Account # \_\_\_\_\_  
Name BELCHER WAYNE  
Address \_\_\_\_\_  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_  
Order Date 9/13/2019  
Status MEDIUM  
Scheduled 09/13/19 02 16 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

---

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 81568829	74698200	2156	B14168537	

---

Description \_\_\_\_\_  
Comment LF, BRK HSE, LF IN FIELD. O/FE  
Requested By Anna Goodwin Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW  
Start Date 10/04/19 09 08 AM Completed Date 10/04/19 09 08 AM

Notes same place as before, behind mailbox, dirt trucks are running over it we may need to reinforce it somehow  
TEMP REPAIRED LINE, WILL STILL NEED TO BE REINFORCED

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 14859**

Account #		Order Date	8/21/2019
Name	MARSHALL, MICHAEL	Status	MEDIUM
Address		Scheduled	08/21/19 11:09 AM
Telephone	Job #	Order Type	CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 27207869	09233928	8625	B14163171	

Description  
Comment RT, BRK M/YD  
Requested By  
Assigned To MAINTENANCE CREW  
Completed By MAINTENANCE CREW  
Start Date 07/03/19 11:09 AM  
Completed Date 07/30/19 11:09 AM

Notes repaired water line, two pin holes-gp

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 14761**

Account #  
Name KNIGHT PATTI K  
Address  
Telephone Job #  
Order Date 7/31/2019  
Status MEDIUM  
Scheduled 07/31/19 08:17 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 9434358	9434358	3944		

Description

Comment LF L'GR LN READ 2

Requested By wendell jenkins Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW

Start Date 08/08/19 10 16 AM Completed Date 08/08/19 10 16 AM

Notes 2-3 GPM LEAK. CHANGED OUT LMETER WITH KAM PER BOTTOM BUSTED, 3963-KAM 9434358

Signature \_\_\_\_\_



East Logan Water District  
**WORK ORDER 14769**

Account #		Order Date	8/1/2019		
Name	FARLEY, DONNA L	Status	MEDIUM		
Address		Scheduled	08/01/19 03:29 PM		
Telephone	lob #	Order Type	CHECK FOR LEAK ON OUR SIDE		
METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT	
WT 22370773	64952909	4655	B14250263		
Description					
Comment	LF HSE OFF RD @ B.O				
Requested By	gp	Assigned To	MAINTENANCE CREW	Completed By	MAINTENANCE CREW
Start Date	08/08/19 10:17 AM			Completed Date	08/08/19 10:17 AM
Notes	2-3 GPM LEAK, METER BOTTOM BUSTED, 4890-CHANGED OUT WITH KAM 9434270				

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 14615**

Account #  
Name BALD KNOB CHURCH  
Address  
Telephone ob #  
Order Date 6/12/2019  
Status MEDIUM  
Scheduled 06/12/19 08:49 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 69361410	63066022	151	B14166657	

Description  
Comment RT BLUE HS BEHIND CH R/DR 2 MT  
Requested By TINK WEBB Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW  
Start Date 06/21/19 03:05 PM Completed Date 06/21/19 03:05 PM

Notes  
CUST CALLED STATED THAT HE HAD CALLED 2-3 TIMES BEFORE ABOUT THE WATER STANDING AT THE METER, HE ADV. THAT IT'S STILL STANDING THERE WITH NO RAIN AND WANTS IT TO BE TESTED AGAIN,  
changed meter, Kam. 9434330-cs

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 14613**

Account #		Order Date	6/11/2019		
Name	PHILLIPS RICHARD W III	Status	MEDIUM		
Address		Scheduled	06/11/19 11:06 AM		
Telephone	Job #	Order Type	CHECK FOR LEAK ON OUR SIDE		
METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT	
WT 9434410	9434410	3806			
Description					
Comment	LF BRK L/YD BY POLE				
Requested By	MH	Assigned To	MAINTENANCE CREW	Completed By	MAINTENANCE CREW
Start Date	09/17/19 09 16 AM		Completed Date 09/17/19 09 16 AM		

Notes MIKE NOTED IN MAY, THAT THERE WAS A LEAK IN THE BOX, NOT SURE IF IT IS ON US OR ON CUSTOMER SIDE. PLEASE CHECK OUT

MH replaced meter, busted meter bottom

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 14513**

Account #		Order Date	5/20/2019
Name	PEARSON RANDALL L	Status	MEDIUM
Address		Scheduled	05/20/19 09:00 AM
Telephone	Job #	Order Type	CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 9434278	9434278	5644		

Description

Comment LF,WH/TRLR R/DR T/L GO TO 1215

Requested By randall pearson Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW

Start Date 05/21/19 10 12 AM Completed Date 05/21/19 10 12 AM

Notes cust stated that in the meter box the copper pipe is leaking. not sure who is responsible for this part setter had holes in it, water was running through the meter and making it go up so may have to do an adjustment. changed out meter to kam: 9434278-gp/mh, est leak, 43,200

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 14495**

Account #  
Name JOHNSON, BILLIE D  
Address  
Telephone Job #  
Order Date 5/13/2019  
Status MEDIUM  
Scheduled 05/13/19 07:58 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 21142689	21142689	49		

Description  
Comment LT, WH/HSE, M/YD  
Requested By Mrs Johnson Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW  
Start Date 05/13/19 09 30 AM Completed Date 05/13/19 01 30 PM

Notes Mike says its our leak in box

Mike and Gary found leaks in 3 places, all on us, and one was causing meter to turn, so we will adjust her bill  
Also, moved the meter box out of the natural water flow

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 14490**

Account # \_\_\_\_\_ Order Date 5/8/2019  
Name MORROW, JOELLA & JIM Status MEDIUM  
Address \_\_\_\_\_ Scheduled 05/08/19 08:58 AM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 21142674	21142674	6336		

Description

Comment LF,BRK HSE,LF CNR

Requested By Linda Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW

Start Date 05/10/19 09:16 AM Completed Date 05/10/19 09:16 AM

Notes Customer says box is full of water (within an inch of top) but looks like it had been running over. Probably ground water, but please check when you can, meter bottom was busted changed meter with kam 9434328-gp/mh, 6351-leaking 1-2 gpm

Signature \_\_\_\_\_



East Logan Water District  
WORK ORDER 14633

Account #  
Name NIELSEN, RANDAL E  
Address  
Telephone Job #

Order Date 6/17/2019  
Status MEDIUM  
Scheduled 06/17/19 02:58 PM  
Order Type CHECK PRESSURE

METER# WT 81568780      ERT/INTERNAL ID# 74698151      READING 1097      LOCATOR TAG B15415583      READING IN / OUT 1133

Description  
Comment 20' OFF RD. 50' RT OF DR

Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW      Completed By GPEM  
Start Date 6/17/19 Time \_\_\_\_\_      Completed Date 6/17/19 Time 10:30

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes

*open one of the pressure test valves*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Reg was Leaking at bottom a Little</i>		
<i>Replaced Reg Pressure 43 Pressure</i>		
<i>before 40.</i>		

Signature 



East Logan Water District  
WORK ORDER 15084

Account #  
Name ROBBINS KEN H  
Address  
Telephone

Order Date 10/21/2019  
Status MEDIUM  
Scheduled 10/21/19 11 37 AM  
Order Type

METER# WT 9434411      ERT/INTERNAL ID# 9434411      READING 1      LOCATOR TAG      READING IN / OUT 0000100

Description  
Comment RT. BRK HSE. LF OF 2ND DR

Requested By son      Assigned To MAINTENANCE CREW      Completed By E.H.  
Start Date 10/21/19      Time      Completed Date 10/21/19      Time 2:17

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes stating that the shut off valve is not working inside the meter box adv that they should have a shut off valve on their side of the meter and since they are going to be working on the water lines to go ahead and get a shut off on their side of meter installed

Inventory Item And Description	Quantity Ordered	Quantity Used
Shutoff is not working		

E.H.

Signature \_\_\_\_\_

East Logan Water District  
WORK ORDER 15149

Account #  
Name MOORE, ERIC L  
Address  
Telephone

Order Date 11/14/2019  
Status MEDIUM  
Scheduled 11/14/19 01:39 PM  
Order Type CHECK METER

METER# WT 46202698      ERT/INTERNAL ID# 09778345      READING 7564      LOCATOR TAG B14169384      READING IN / OUT

Description  
Comment RT TRLR L/CNR BARN R/DR

Requested By Linda      Assigned To MAINTENANCE CREW      Completed By *[Signature]*  
Start Date 1/1/      Time :      Completed Date 11/14/2019      Time 10:00

Make      Size/Type      Multiplier

Notes Customer had no water for about 18 hours during cold snap, then said it came back. Please make sure we don't have a busted meter bottom or other leak.

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Nothing was found</i>		

Signature *[Signature]*

East Logan Water District  
**WORK ORDER 13882**

Account #  
Name ADCOCK, LISA  
Address  
Telephone

Order Date 1/2/2019  
Status MEDIUM  
Scheduled 01/02/19 09:48 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 82995123	89283332	1152	B14169890	

Description

Comment RT, TRLR OFF RD, 20' RT DR

Requested By Linda

Assigned To MAINTENANCE CREW

Completed By *C P / M H*

Start Date *1 1* Time *1*

Completed Date *1 2 12 5* Time *2 00*

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Lisa 270/847/1165 home after 2 today. Show her how to check meter for leak, and see if leak is on us

*No visible signs of leak*

Inventory Item And Description	Quantity Ordered	Quantity Used

Signature *[Handwritten Signature]*

East Logan Water District  
**WORK ORDER 15045**

Account #		Order Date	10/11/2019		
Name	FARMER, MICHAEL	Status	MEDIUM		
Address		Scheduled	10/11/19 08:25 AM		
Telephone	Job #	Order Type	CHECK FOR LEAK ON OUR SIDE		
METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT	
WT 9434407	9434407	7146			
Description					
Comment	LF IN FIELD 100' PAST LAST MTR				
Requested By	customer	Assigned To	MAINTENANCE CREW	Completed By	MAINTENANCE CREW
Start Date	10/14/19 11 30 AM	Completed Date			10/14/19 11 30 AM

Notes

leaking in box, meter is turning.  
Mike Hines reports its a contractors box & can feel a split in pipe on our side of meter. Will replace box, setter, and check if leaking

Mike and Brandon repaired leak in service tube about 12" from meter on our side Reading of 7418 & meter is turning

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 14992**

Account #  
Name THURMAN, FRANK  
Address  
Telephone Job #  
Order Date 9/23/2019  
Status MEDIUM  
Scheduled 09/23/19 02:34 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

---

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 32895319	58346529	3386	B14168472	

---

Description  
Comment LFT. X FRAME WOOD HS ON RGT  
Requested By Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW

---

Start Date 09/23/19 02 34 PM Completed Date 09/23/19 02 34 PM

Notes 3433-1-3 gpm, erpaired service line

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 14919**

Account #  
Name LOGAN CO CAREER & TECH CENTER  
Address  
Telephone Job #

Order Date 9/9/2019  
Status MEDIUM  
Scheduled 09/09/19 11 11 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 83340187 89445234 2021 B15415646

Description  
Comment L corner of school

Requested By Assigned To MAINTENANCE CREW Completed By GP  
Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_ Completed Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_

Make Size/Type Multiplier  
Notes LEAKING AROUND THE FENCE AREA, BUD 1909091105-ATT, ELWD, LTRWC

*Att - all cleared*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Main leak about 5 feet of</i>		<i>5 feet</i>
<i>6 in pipe and two 6 in knockers</i>		<i>2</i>

Signature 



East Logan Water District  
**WORK ORDER 14493**

Account #  
Name BEACHY, KEITH L  
Address  
Telephone

Order Date 5/8/2019  
Status MEDIUM  
Scheduled 05/08/19 12:47 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 41110201      ERT/INTERNAL ID# 08885378      READING 1760      LOCATOR TAG B14169489      READING IN / OUT

Description  
Comment LF, OLD HSE, RT YD, 2ND

Requested By ANDREW GROFF      Assigned To MAINTENANCE CREW      Completed By *G.P./M.H.*

Start Date    /    /         Time    :         Completed Date *5/9/19*      Time *10:12*

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes go into drive, straight ahead, on right, before the meters. gravel is wet  
270-731-9466

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>1-3/4" Cone Style Compression Coupling</i>		
<i>2-3/4" INSERTS</i>		

*Leaking where it WAS REPAIRED About 1 year Ago  
2 GPM*

Signature *Mike A*





East Logan Water District  
**WORK ORDER 15019**

Account #  
Name CRAWFORD, DARRELL E  
Address  
Telephone Job #

Order Date 10/1/2019  
Status MEDIUM  
Scheduled 10/01/19 03:19 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 22951800 59536109 4591 B14166383

Description  
Comment LF, HSE OFF RD, LF DR

Requested By mr crawford Assigned to MAINTENANCE CREW Completed By

Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_ Completed Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes \_\_\_\_\_

Inventory Item And Description	Quantity Ordered	Quantity Used
- ELWD		
- L70		
- WRECC		
- 191 001 1745 -		

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 14994**

Account # ---  
Name RITTENBERRY, MAXIE  
Address  
Telephone Job #  
Order Date 9/25/2019  
Status MEDIUM  
Scheduled 09/25/19 08:01 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 86295608  
ERT/INTERNAL ID# 10412691  
READING 3325  
LOCATOR TAG B13302904  
READING IN / OUT

Description  
Comment OLD SHOP

Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By MHGP BW  
Start Date   /  /   Time   :   Completed Date 9/25/19 Time 12:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes \_\_\_\_\_

Inventory Item And Description	Quantity Ordered	Quantity Used

ATT - clear  
LTC  
LTRWC  
WRECC - elec  
  
Loss 14,000

*Mike H*

Signature

East Logan Water District  
**WORK ORDER 14012**

Account #  
Name MAHAN, DEBORAH K  
Address  
Telephone

Order Date 1/15/2019  
Status MEDIUM  
Scheduled 01/15/19 02:38 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 41032004      ERT/INTERNAL ID# 10325417      READING 605      LOCATOR TAG B14169972      READING IN / OUT 0605

Description  
Comment brown trailer mid yrd

Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW      Completed By CP/RH/ET  
Start Date 1/15/19 Time \_\_\_\_\_      Completed Date 2/13/19 Time 11:16

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes  
SHUT OFF LEAKING  
BUD: 1901151227  
JAN 17-EXP, LTC, WRECC

Inventory Item And Description	Quantity Ordered	Quantity Used
Replaced Box and Repaired Shut off!		
1 Shut off		
1 3/4 Cone type coupling		
1 PVC Threaded coupling 3/4		
1 PVC pipe coupling 3/4		
1 muller nut and packing		
3 3/4 inserts blue		
1 3/4 6 in pipe		

Signature



East Logan Water District  
WORK ORDER 14419

Account # \_\_\_\_\_ Order Date 4/16/2019  
 Name ROSS, JOSEPH E Status MEDIUM  
 Address \_\_\_\_\_ Job # 3 Scheduled 04/16/19 01:34 PM  
 Telephone \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
 WT 39340257 09822214 6141 B14162992 6161

Description \_\_\_\_\_  
 Comment LF GRAY & BRK HSE RT CNR CUL-D  
 Requested By AMY Assigned To MAINTENANCE CREW Completed By GP/MT  
 Start Date 4/16/19 Time 10:05 Completed Date 4/16/19 Time 10:05

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
 Notes DEAD END AREA  
 GEORGE OFFUTT - LAWNMOWER GUY THAT FOUND IT  
 AMY-2707914857 AND LET KNOW IF LEAK IS ON HER SIDE OR OUR SIDE

Inventory Item And Description	Quantity Ordered	Quantity Used
<u>Leak outside</u>		
<u>2 inserts 3/4</u>		
<u>1 Muller Nut 3/4</u>		
<u>1 Cone Nut 3/4</u>		
<u>1 ft Pex 3/4</u>		
<u>Replaced all the way to the main</u>		



Signature

East Logan Water District  
**WORK ORDER 14426**

Account # \_\_\_\_\_ Order Date 4/18/2019  
 Name JOHNSON, STEPHANIE A Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 04/18/19 08:43 AM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
 WT 9135965 9135965 334 \_\_\_\_\_

Description \_\_\_\_\_  
 Comment LF, GRAY/HSE M/YD  
 Requested By darla/stephanie Assigned To MAINTENANCE CREW Completed By *MH d GP*  
 Start Date   /  /   Time   :   Completed Date 4/22/19 Time 9:30

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
 Notes in meter box, water is leaking in the box-from the road to the meter. directly in front of that

*Be marked by GAMI tomorrow*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>2 to 3 gpm Leaking 2 weeks</i>		
<i>1 muller coupling and 2 inserts</i>		

*Est Leak 40,320*

*Pru*

Signature



East Logan Water District  
**WORK ORDER 14293**

Account #  
Name SLATON, JAY  
Address  
Telephone

Order Date 3/19/2019  
Status MEDIUM  
Scheduled 03/19/19 09 09 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 46202810      ERT/INTERNAL ID# 09801619      READING 6310      LOCATOR TAG B14170229      READING IN / OUT 6331

Description  
Comment LF, TAN HSE, LF CNR

Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW      Completed By GP/MJS  
Start Date 3/19 Time \_\_\_\_\_      Completed Date 3/19/19 Time 11:15

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes soft spot next to the meter, in front yard

Inventory Item And Description	Quantity Ordered	Quantity Used
Call in		
2 muller cuplings		
2 inserts		
3/4 blue pex. 1ft Long		
Leaking about 25 gpm		

Signature  User1



East Logan Water District  
**WORK ORDER 14438**

Account #  
Name BROWN, MICHAEL  
Address  
Telephone Job #

Order Date 4/22/2019  
Status MEDIUM  
Scheduled 04/22/19 02:01 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 52473770      ERT/INTERNAL ID# 70978961      READING 1837      LOCATOR TAG B14250481      READING IN / OUT

Description  
Comment RT BRK R/DR

Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By *Mike H*

Start Date   /  /   Time   :   Completed Date 4/23/19 Time 12:40

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes CUST STATED COMING FROM 103, RIGHT PAST HIS HOUSE THAT THE ROAD IS STAYING WET AND IT NORMALLY DON'T WANTS US TO CHECK FOR A LEAK-CS

Inventory Item And Description	Quantity Ordered	Quantity Used
80' 3/4" Pex water Line		
2 - 3/4" Nuts		
2 - 3/4" inserts		

7120 5570 The Service Line to this meter  
Reading 0920  
Sounds Like A  
SMALL LEAK

Need to Pull New Service Line under Road  
Est. Leak 72,000

*Bud H*  
*190 423 1912*

*Chancellor's Rd*  
*1 Dogwood ways.*

*ELWD*  
*WRCC*  
*LTC*

*2546*  
*4/24 May 14*

*Mike H*

Signature

East Logan Water District  
**WORK ORDER 14183**

Account #  
Name TOOLEY, JOEY W  
Address  
Telephone Job #

Order Date 2/25/2019  
Status MEDIUM  
Scheduled 02/25/19 08:15 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 57645150	13769522	4790	B14168323	

Description  
Comment RT,BRK HSE,RT CNR

Requested By \_\_\_\_\_ Assigned to MAINTENANCE CREW Completed By CP/MH  
Start Date 2/25/19 Time 8:00 Completed Date 2/24/19 Time 3:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes SERVICE LINE LEAK

Inventory Item And Description	Quantity Ordered	Quantity Used
2 3/4 coupling		
4 inserts		
2 feet 3/4 service Tube		

50 Gpm for 3 days = 216,000

Signature *Michael*

East Logan Water District  
**WORK ORDER 14727**

Account # \_\_\_\_\_ Order Date 7/17/2019  
 Name MC CLOUD, HAROLD D Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 07/17/19 08.15 AM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE


METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 50180691	10257121	842	B14169767	

Description \_\_\_\_\_  
 Comment RT, WH DBL W. LF DR  
 Requested By Mr. McCloud Assigned To MAINTENANCE CREW Completed By *C. P. ...*  
 Start Date   /  /   Time   :   Completed Date   /  /   Time   :  

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Customer states contractors for phone company have cut his service line He has very reduced pressure  
*The contractor Fixed it!!*

Inventory Item And Description	Quantity Ordered	Quantity Used



Signature

East Logan Water District  
**WORK ORDER 14963**

Account #  
Name MILES, CHARLES  
Address  
Telephone

Order Date 9/17/2019  
Status MEDIUM  
Scheduled 09/17/19 11 30 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 66684128 59596216 4315 B14167039

Description  
Comment LT, PINK HSE, MYD

Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By *CP*

Start Date   /  /   Time   :   Completed Date 9/24/19 Time   :  

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes across the rd from the mailbox, main line is across the rd, so sound like a service line

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>3/4 1 Barbed Fittings</i>		
<i>3/4 2 Rings</i>		
<i>3 + 0 4 gpm</i>		

*X Morgantown Rd*

*Sept 20 @ 2:45  
exp. Oct 9th*

*Att Bluegrass Gas - check per  
ELWD - call to Gary*

*1909181766*

Signature *P...is*

East Logan Water District  
WORK ORDER 14986

Account #  
Name SHOEMAKE, MIKE  
Address  
Telephone Job #

Order Date 9/23/2019  
Status MEDIUM  
Scheduled 09/23/19 09:48 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 66684115 59596203 8855 B14167697

Description  
Comment RT WH BRK HSE LF DR

Requested By Mike Assigned To MAINTENANCE CREW Completed By GP  
Start Date 1/1 Time : Completed Date 9/26/19 Time :

Make Size/Type Multiplier  
Notes 291

Inventory Item And Description	Quantity Ordered	Quantity Used
Fixed two service lines		
2 Barbed Fittings		
4 Rings		
2 Cone Nuts		
2 pieces of 6 in 3/4 Line		
1 to 2 gpm		

BUD # 1909232161

ATT - clear  
Bluegrass Gas - clear per call to Gary  
LTRWC  
ELWD

Lawren  
ATT - 502-  
398-1324  
Loren

Signature 

East Logan Water District  
**WORK ORDER 14456**

Account #  
Name BOYER, AMANDA J  
Address  
Telephone Job #

Order Date 4/29/2019  
Status MEDIUM  
Scheduled 04/29/19 01:53 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 9135943      ERT/INTERNAL ID# 9135943      READING      LOCATOR TAG      READING IN / OUT

Description  
Comment LF, WH HSE, 15' LF DR, 3 METER

Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW      Completed By *GP/MLH*  
Start Date   1  /  1  /   Time   :  :        Completed Date   5  /  1  /  19   Time   1  :  30  

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes repair service line leak, bud called in on 4/29/19  
ATT, ELWD  
BUD : 1904291885

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>1 Cone Coupling</i>		<i>1</i>
<i>2 3/4 inserts</i>		<i>2</i>
<i>20 gpm for 1 month</i>		

Signature  User1

East Logan Water District  
WORK ORDER 14887

Account #  
Name CAHOE, LESLIE M  
Address  
Telephone

Order Date 9/4/2019  
Status MEDIUM  
Scheduled 09/04/19 09:33 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 36583314      ERT/INTERNAL ID# 09789687      READING 8363      LOCATOR TAG B14168950      READING IN / OUT

Description  
Comment LFT.WT/HSE,R/YD R/GATE

Requested By Paul Lyon      Assigned To MAINTENANCE CREW      Completed By *GP*  
Start Date   1  /  1  /   Time   :        Completed Date   9/19/19   Time   1:30  

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes

*1 to 3 gpm Repaired Blue pipe*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Two 3/4 Rings</i>	<i>2</i>	
<i>2 3/4 Barbed Fittings</i>	<i>1</i>	
<i>1 3/4 1 belt Bend Aid</i>	<i>1</i>	

*marked in white - edge of road wet*  
*by Sept 6*  
*ELWD*  
*LTC*  
*WRECC*  
*# 1909041841*  
*X-woodward*

Signature *Paul*

East Logan Water District  
WORK ORDER 14884

Account # \_\_\_\_\_ Order Date 9/3/2019  
Name BLACKBURN, HOMER L Status MEDIUM  
Address \_\_\_\_\_ Scheduled 09/03/19 12:47 PM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 78786042	73607028	2588	B14166275	

Description  
Comment RT WH/HS R/DR T/LF  
Requested By customer Assigned To MAINTENANCE CREW Completed By *GP*  
Start Date   /  /   Time   :  :   Completed Date   /  /   Time   :  :  

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes check for leak on our side of meter at the meter box  
*1 to 3 gpm*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>1 Barbed Fittings 3/4</i>		
<i>2 Rings</i>		
<i>1 1/2" Bolt Bandalo</i>		

Signature 



East Logan Water District  
WORK ORDER 14389

Account #  
Name KROPF, BRENT L  
Address  
Telephone

Order Date 4/3/2019  
Status MEDIUM  
Scheduled 04/03/19 03:00 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 43605841	09158167	3491	B14170269	

Description  
Comment LFT GRAY HSE RT OF DR

Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By MH/GP  
Start Date 4/3/19 Time 9:30 Completed Date 4/3/19 Time 9:30

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes driveway

Inventory Item And Description	Quantity Ordered	Quantity Used
2 3" Knock ons		
34' 3" WATER LINE		

X ~~Dakota~~ Leak  
Head

Leak Loss 414,864 gallons  
Flushed 10,000 gallons

ATT  
Blue Cross (San Salva)  
LORWC  
R. Villa

1904031911



Signature

East Logan Water District  
WORK ORDER 14397

Account #  
Name YODER DOUGLAS  
Address  
Telephone

Order Date 4/8/2019  
Status MEDIUM  
Scheduled 04/08/19 08 18 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 50180704 61512608 7658 B14170090

Description  
Comment RT, BRK HSE, 2ND DR, RT OF DR

Requested By mr yoder Assigned To MAINTENANCE CREW Completed By GP/MAH

Start Date 1/1 Time : Completed Date 4/16/19 Time 2:00

Make Size/Type Multiplier  
Notes Repaired service line 25 gpm

Inventory Item And Description	Quantity Ordered	Quantity Used
2 3/4 cone type couplings		2
4 3/4 inserts		4
and two feet of pex		

Signature 

East Logan Water District  
WORK ORDER 14364

Account # \_\_\_\_\_ Order Date 4/1/2019  
 Name MCKINNEY, PHILIP Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 04/01/19 01:38 PM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 43451511 ERT/INTERNAL ID# 08892882 READING 4230 LOCATOR TAG B14167247 READING IN / OUT \_\_\_\_\_

Description \_\_\_\_\_  
 Comment LF TRLR R/DR  
 Requested By Phil McKinney Assigned To MAINTENANCE CREW Completed By CP/MH  
 Start Date 4/1/19 Time 2:30 Completed Date 4/1/19 Time 3:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
 Notes states that there appears to be a leak on the main line, close to the mailbox

Inventory Item And Description	Quantity Ordered	Quantity Used
3 gpm		
2 3/4 inserts		2
1 muller coupling		1

Old Greenville Rd. Leak Loss 60,480  
 Ashby Rd.

April 3rd @ 2:30

ELWD  
 Logan tele  
 WIRECC

1904011770

Signature Phil

East Logan Water District  
**WORK ORDER 14388**

Account #  
Name KELLY, RALPH E  
Address  
Telephone

Order Date 4/3/2019  
Status MEDIUM  
Scheduled 04/03/19 12:49 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 23431639      ERT/INTERNAL ID# 13208843      READING 1298      LOCATOR TAG B14169979      READING IN / OUT 1319

Description  
Comment LF, WH HSE, 20' LF DR

Requested By mr kelly      Assigned To MAINTENANCE CREW      Completed By GP/MH  
Start Date 4/1/19      Time 10:00      Completed Date 4/1/19      Time 10:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes 1/2 way between meter and the road, super sloppy, 1/2 way between water meter and utility pole

*Two cone type couplings and piece of pex 12' long  
3:05 pm.*

Inventory Item And Description	Quantity Ordered	Quantity Used
Both sides of rd.		
W. Valley Dr.		
Wildcat Ln.		
April 1st @ 12:00 Noon.		

Att Atmos LTC, Texas gas cleared  
- 190403 1729 - *W. Jackson*

Est. Leak  
60,480

Echo 484 Valley      James Jackson

*Peri*

Signature

East Logan Water District  
WORK ORDER 14983

Account #  
Name BROCK WILLIAMS  
Address  
Telephone

Order Date 9/23/2019  
Status MEDIUM  
Scheduled 09/23/19 08:14 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 69361408      ERT/INTERNAL ID# 63066020      READING 798      LOCATOR TAG B14167497      READING IN / OUT ~~02000~~ 0934  
Description  
Comment LF L/DR 200' BEFORE GATES READ  
Requested By Kelvin Brock      Assigned To MAINTENANCE CREW      Completed By EH  
Start Date \_\_\_/\_\_\_/\_\_\_      Time \_\_\_:\_\_\_      Completed Date 9/23/19 Time 2:05  
9/30/19

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Says box is filling with water, but meter not turning. He just replaced his service line. We replaced the shutoff valve 12/16

1 miller nut 1 Barbed Fitting 1 1/2 of 6 in pipe  
3 to 6 gpm

Inventory Item And Description	Quantity Ordered	Quantity Used
<del>1/2" x 1/2" x 1/2" x 1/2" x 1/2" x 1/2"</del>		
<del>1/2" x 1/2" x 1/2" x 1/2" x 1/2" x 1/2"</del>		
Leak in id the pipe right before it enters the settled		
pressure was good		

BUD # 190231951

21-5 - clear

LTC

W/pe - clear

FLWD

he let down gravel to both  
sides in pipe to the hole things.

Signature EH

East Logan Water District  
WORK ORDER 14978

Account #  
Name THOMAS, MARY C  
Address  
Telephone

Order Date 9/20/2019  
Status MEDIUM  
Scheduled 09/20/19 01:55 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 52473860  
ERT/INTERNAL ID# 59637876  
READING 4395  
LOCATOR TAG B14172346  
READING IN / OUT 4497

Description  
Comment RT TRLR L/CNR

Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_  
Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_ Completed Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes LEAK COMING INTO METER BOX. VERIFIED BY MIKE.

*Repaired Nut going in to setter*

Inventory Item And Description	Quantity Ordered	Quantity Used
1 Cone Nut		
1 3/4 pipe Gin		
1 Barbed Fitting		
2 clamping Rings		
1 to 3 gpm		

*Y. Boston*  
*both sides*

*Meter not turning  
when they  
were working*

*1909201361*

*ELWD  
LTC  
WREU*

Signature



East Logan Water District  
**WORK ORDER 14955**

Account # \_\_\_\_\_  
Name BELCHER, WAYNE  
Address \_\_\_\_\_  
Telephone \_\_\_\_\_

Order Date 9/13/2019  
Status MEDIUM  
Scheduled 09/13/19 02:16 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 81568829	74698200	2156	B14168537	

Description  
Comment LF, BRK HSE, LF IN FIELD, O/FE

Requested By Anna Goodwin Assigned To MAINTENANCE CREW Completed By GP

Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_ Completed Date 9/13/19 Time 10:11

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes same place as before, behind mailbox, dirt trucks are running over it we may need to reinforce it somehow

*Repair*

Inventory Item And Description	Quantity Ordered	Quantity Used
09233928 meter #		
8700 Reading		
Barbed Fittings		2
3/4 Pipe		3 feet
1 to 3 gpm		

X WM BROWN RAL

9-13-19

*Sept 17 @ 4:45  
- COT 4th*

*ELWD, CTC  
190 9/13/19 49*

*Price*

Signature





East Logan Water District  
**WORK CREW 15181**

Account #  
Name HOCHSTETLER, VERNON  
Address  
Telephone Job #

Order Date 12/4/2019  
Status MEDIUM  
Scheduled 12/04/19 03:11 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 43605918	10128228	1837	B14169912	

Description  
Comment RT D-WIDE M/YARD

Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_  
Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_ Completed Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes Ethan said leakings @ setter

Inventory Item And Description	Quantity Ordered	Quantity Used
<u>Repaired leak at setter.</u>		
<u>Removed box for repairs.</u>		
<u>3' Pe &amp; Setter w/ 3 gaskets.</u>		
<u>Both Sides</u>		

ELWD, LTC, # locate ticket. Dec 9 @ 3:30  
WRECC 1912051319  
PI 205 1319

Completed 12/9/18

6258  
Maintenance



Mud River Church Lot  
in parking lot @  
meter  
@ Mud River Church.

10/24/2019  
MEDIUM  
10/24/19 10:54 AM  
CHECK FOR LEAK ON OUR SIDE  
READING IN / OUT

Completed By \_\_\_\_\_  
Date 11/19/19 Time \_\_\_\_\_

Location \_\_\_\_\_  
to get to meter \_\_\_\_\_

Oct 28 @ ~~11~~  
exp. Nov. 4

Bud #  
191024095

Att, ELWD  
LTRWC, Texasgas  
Whecc

Quantity Ordered	Quantity Used

- Before Saturday Morning -

Repaired

✓  
Don

Ethan

East Logan Water District  
**WORK ORDER 14736**

Account # \_\_\_\_\_ Order Date 7/19/2019  
 Name BAER, LEONARD I Status MEDIUM  
 Address \_\_\_\_\_ 76-8466 Scheduled 07/19/19 09:38 AM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
 WT 36583308 09968839 5264 B14166807 \_\_\_\_\_ 1592.054

Description \_\_\_\_\_  
 Comment LF, WH/HSE/1ST DR  
 Requested By LEONARD BAER Assigned to MAINTENANCE CREW Completed By \_\_\_\_\_  
 Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_ Completed Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
 Notes CUST STATED THAT AROUND THE METER BOX IS EXTREMELY WET, BELIEVES THAT WE HAVE A LEAK THERE

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>X Deskins Rd</i>		
<i>Repaired Sewer Line</i>		
<i>up 6" band,</i>		
<i>- ELWD, LTC, Pennyrile</i>		
<i>0894</i>		

*Completed!*  
*12/11/19*  


East Logan Water District  
**WORK ORDER 15087**

Account # \_\_\_\_\_ Order Date 10/22/2019  
Name WIX LOGGING Status MEDIUM  
Address \_\_\_\_\_ Scheduled 10/22/19 01:50 PM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
WT 34116531 63524755 7542 B14169703

Description  
Comment RT,LUMBER YD,LF CNR OFFICE BLD

Requested By old man wix Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_  
Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_ Completed Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes water in meter box.

Inventory Item And Description	Quantity Ordered	Quantity Used
check on our side.		
fill meter w/5 turning.		
section serv. line, replace sstter net.		
dig box out for replace.		

- 5913 -  
check  
Back flow.

*Completed*  
*12/11/19*



Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 15161**

Account # \_\_\_\_\_ Order Date 11/19/2019  
Name DEARMOND, TOMMY Status MEDIUM  
Address \_\_\_\_\_ 3 Scheduled 11/19/19 01:16 PM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
WT 35691863 09789686 5503 B14169662

Description \_\_\_\_\_  
Comment LF. TAN AND BRK HSE. LF CNR  
Requested By mr dearmond Assigned to MAINTENANCE CREW Completed By EH  
Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_ Completed Date 11/19/19 Time 3:20

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes check for a leak on our side of the meter, says that meter box is full of water and that it's running down the yard possible busted meter bottom

Inventory Item And Description	Quantity Ordered	Quantity Used
Leak. Right before service enters		
box. It is marked.		
<del>FEED</del> / Boath		

Att  
ELWD  
LTC  
09/6/5

Signature EH BR

East Logan Water District  
WORK ORDER 14973

Account #  
Name WRIGHT BOYD  
Address  
Telephone

Order Date 9/19/2019  
Status MEDIUM  
Scheduled 09/19/19 02:36 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 50056602  
ERT/INTERNAL ID# 63184000  
READING 3729  
LOCATOR TAG B14166455  
READING IN / OUT

Description  
Comment RT YELL HS R/DR

Requested By Assigned To MAINTENANCE CREW Completed By *EH*  
Start Date    /    /    Time    :    :    Completed Date 12/12/19 Time 12:45

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes LEAK AT THIS ADDRESS/SUMMERS RD

*long side*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>It is a leak.</i>		
<i>200ft is mentioned</i>		
<i>Cut 6'x4' section from Summer rd @ Chandlers Rd. to reach leak. small hole from rock in line. section line off. Back-filled hole. Pick up trailer &amp; gravel to backfill hole to gravel level.</i>	<i>5 gal. per min x 93 days = 669 gal.</i>	<i>669 gal. Lost</i>
<i>W.P. 10/10</i>		

*completed  
12/12/19 (DR)*

*ELWD,  
LTC,  
WRECC*

*200ft radius  
Bud #  
190919 11680*

*EH*

Signature \_\_\_\_\_




East Logan Water District  
**WORK ORDER 14984**

Account #		Order Date	9/23/2019
Name	ORDER, WORK	Status	MEDIUM
Address		Scheduled	09/23/19 08:18 AM
Telephone	Job #	Order Type	CHECK FOR LEAK ON OUR SIDE
METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG
			READING IN / OUT

WT No Num \_\_\_\_\_  
Description \_\_\_\_\_  
Comment \_\_\_\_\_  
Requested By Robert Woodward Assigned To MAINTENANCE CREW Completed By *CP*  
Start Date 1/1 Time \_\_\_\_\_ Completed Date 9/23/19 Time 10:56


Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes He says on Taylor Barrow, about 1.7 miles on right by woods there could be a leak  
*Took a Fluid!!!*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>11ft Dig in both sides of inspected</i>		
<i>There was no leak found in both sides</i>		
<i>of inside casing was dry. <del>the</del></i>		
<i>Completed 1/13/20 </i>		

*Robert Woodward  
270-725-0950*

*1909241984  
LTC  
WRECC - c/col  
Mid Western Gas  
ELWD*

*100 yds before  
1012 Taylor Barrow  
Right (marked in white)*

Signature **





East Logan Water District  
**WORK ORDER 15041**

Account #  
Name BROOKS, MARTHA C  
Address  
Telephone Job #

Order Date 10/5/2019  
Status MEDIUM  
Scheduled 10/05/19 12:04 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 48979844	63097837	2892	B14169274	02 298

Description  
Comment LF, WH/HS MYD

Requested By Andy Assigned To MAINTENANCE CREW Completed By *MH*

Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_ Completed Date 10/11/19 Time 11:50

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes Thinks its leaking around regulator. If so, check pressure, and if a regulator is not needed, just remove it.

Inventory Item And Description	Quantity Ordered	Quantity Used
Cont Find A leak		
Reading <del>2892</del> 2970		
Tested for Chlor. meter is slightly turning but visual insp. of Red Regulator & meter show no leak in box. Leak will be on CX LINE. (need to contact CX.)		

Leak in Service Line  
MARKED Road in White Paint  
& Blue FLAG AT Leak

*Call 17@1.45  
NOV. 7 exp*

*1910141574*

*ELWD  
LTC  
WRECC*

*Completed  
12/12/10  
PR*

*Bili  
Marta*



East Logan Water District  
**WORK ORDER 15044**

Account #  
Name BRAY, JIMMY  
Address  
Telephone

Order Date 10/10/2019  
Status MEDIUM  
Scheduled 10/10/19 11 25 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 66707789 59616924 3438 B14167657

Description

Comment RT NEWHSE LF DR READ 2

Requested By mr bray

Assigned To MAINTENANCE CREW

Completed By

EH-12/14

Start Date / / Time :

Completed Date 10/11/19 Time 12:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes main line crosses rd at this meter, leak is across the rd in the ditch line.

Inventory Item And Description	Quantity Ordered	Quantity Used
This is a leak. Road was marked.		
59616924 is the meter the leak is coming from.		
Repaired leak in serv line, section 2' & changed reading.		
Loss 11,880 gal.		

MARKed white paint & Blue FLAG  
ACROSS FROM 1882 + 1884

Completed  
12/13/19. (DB) ST

Out 17 @ 145  
NOV. 4 MXP

Att 1  
Bluegrass gas  
ELWD  
LTC  
LTEWC  
1910141562

EH

Signature

East Logan Water District  
**WORK ORDER 15158**

Account # \_\_\_\_\_  
Name GIPSON, EARL  
Address \_\_\_\_\_  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_

Order Date 11/19/2019  
Status MEDIUM  
Scheduled 11/19/19 12:12 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 68434124      ERT/INTERNAL ID# 62202148      READING 1728      LOCATOR TAG B14169752      READING IN / OUT 173,706.0

Description  
Comment LT "S" CURVE WHSE LF OF DR BY

Requested By ms gipson      Assigned To MAINTENANCE CREW      Completed By \_\_\_\_\_  
Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_      Time \_\_\_\_:\_\_\_\_      Completed Date 11/20/19      Time 10:41

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes left of driveway, closer to rd, water is standing, thinks its close to the main line that runs on that side

Inventory Item And Description	Quantity Ordered	Quantity Used
YES this is a leak.		
Road is marked.		
Pretty small service tube		
leak. Flag put out water		
spot.		

*Completed*

\* Repair Serv line.  
Section 2' & Crimp.  
12/13/19 Time: 1:54p

Loss ~~34,500~~ gal.  
8,640

Completed  
12/13/19 @ TS  
@ GIPSON

\* Royce GIPSON  
Dec. 2 @ noon  
w.p. Dec. 17

Bath Streets

ELWD, LTC  
WRECC

191 law 0960

EH

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 15241**

Account #  
Name LOPEZ, ALBERTO R  
Address  
Telephone

Order Date 12/27/2019  
Status MEDIUM  
Scheduled 12/27/19 01 53 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 81568798 74698169 1701 B14168764

Description  
Comment RT NXT DR LFT OF DR

Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_  
Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_ Completed Date 1/2/20 Time \_\_\_:\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes check for leak inside of meter box, stated that there is full of water

Inventory Item And Description	Quantity Ordered	Quantity Used
Completed 1/2/20 (2)		
Section serv line 1ft. Crimp		

US Route 68 - Both sides of RA marked -  
 { 1/6  
 exp 1/21  
 - 1912310269 -  
 ELWD  
 LTC  
 LTRWC  
 Texas gas  
 WRECC

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 15122**

Account #  
Name LONG, BILL  
Address  
Telephone

Order Date 11/5/2019  
Status MEDIUM  
Scheduled 11/05/19 09.24 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 42033350      ERT/INTERNAL ID# 08647047      READING 4520      LOCATOR TAG B14167617      READING IN / OUT 4528

Description  
Comment LF, BRK/HSE RT/DR

Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW      Completed By \_\_\_\_\_  
Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_      Completed Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes linda called in bud

Inventory Item And Description	Quantity Ordered	Quantity Used
SECTION SERV LINE 2' W - PEX & Crimped.		

Completed  
12/27/19

Signature







East Logan Water District  
WORK ORDER 14928

Account #  
Name CHICK, WILLIAM  
Address  
Telephone

Order Date 9/9/2019  
Status MEDIUM  
Scheduled 09/09/19 01:34 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 84200079      ERT/INTERNAL ID# 89837142      READING 734      LOCATOR TAG B14167683      READING IN / OUT 00768

Description  
Comment RT,WH/HSE,LF DR

Requested By Mike Hines      Assigned To MAINTENANCE CREW      Completed By GF

Start Date 1/1/      Time :      Completed Date 9/19/19      Time 11:15

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes leaking in box on 12" stubout. Need to replace stubout with pex and re-attach their service

*Repair service line Replaced setter and back the  
Stub out was not worked on old setter He had water at the box*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Meter was still running. 2 to 3 gpm</i>		
<i>Round Box</i>		1
<i>Setter</i>		1
<i>3/4 blue insert</i>		1
<i>3/4 barbend Fittings and two crimping</i>		1
<i>Rings</i>		2
<i>New Rubber meter washers</i>		2

*front of property left of Dr  
behind mail box*

*Both sides -*

*X Stratton Rd.  
Morgantown.*

*Sept 11 @  
2:15  
Sept 30 app.*

*ELWD, LTC*

*Bud # 190 909 2081*

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 15014**

Account #  
Name ENGLER, PHILLIP R  
Address  
Telephone Job #

Order Date 9/30/2019  
Status MEDIUM  
Scheduled 09/30/19 03:11 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 52473820 64887912 6125 B14172310

Description

Comment RT, GRAY HSE, RT/YD

Requested By mr engler

Assigned To MAINTENANCE CREW

Completed By *GP MHB*

Start Date 1/1 Time : :

Completed Date 10/3/19 Time 3:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes says meter box is full of water,

*Don't it a Leaker NOT if is it a drip be hard to Find Right  
now keep eye on it !!*

Inventory Item And Description	Quantity Ordered	Quantity Used

*3.5 gpm*

Signature

*[Handwritten Signature]*



East Logan Water District  
**WORK ORDER 15166**

Account # \_\_\_\_\_ Order Date 11/25/2019  
Name CROPPER, CAROL J Status MEDIUM  
Address 5001 \_\_\_\_\_ Scheduled 11/25/19 03:40 PM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 66990240	60687669	2601	B14168829	

Description \_\_\_\_\_  
Comment RT, HSE OFF RD, LF YD  
Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By EH  
Start Date 11/26/19 Time \_\_\_\_\_ Completed Date 11/26/19 Time 1:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes meter box leaking in box

Inventory Item And Description	Quantity Ordered	Quantity Used
Job 14 needs a setter. meter was turning but water boiled like it was coming from us.		1 setter nut 1 Gasket. 1 Nipple. 3/4" / 9

Gasper River / Tucker Price

ELWD, LTC, WRECC



191 205 1323

Both sides marked

Dec. 9 @ 3:30

12/6/19.

purged water, replaced setter nut, gasket & nipple to  
cx line. Completed w/pics (ARC)

Signature EH

East Logan Water District  
WORK ORDER 15151

Account #  
Name HUDSON, LESLIE A  
Address  
Telephone

Order Date 11/18/2019  
Status MEDIUM  
Scheduled 11/18/19 08:02 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 78461134      ERT/INTERNAL ID# 73488030      READING 1341      LOCATOR TAG B15440827      READING IN / OUT 7386/825

Description  
Comment RT, TRLR, MYD

Requested By Leslie      Assigned To MAINTENANCE CREW      Completed By  
Start Date 11/18/19      Time 4:00      Completed Date 12/10/19      Time 1:33

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes Called with water coming up between meter and main

Inventory Item And Description	Quantity Ordered	Quantity Used
Repaired air hole in serv. line w/ 1 bolt band.		

called for locate (OR)  
 X cave springs  
 BOTH sides  
 Nov. 20 @ 11:00  
 exp. Dec 9<sup>th</sup>  
 ELWD  
 LTC  
 WRECC  
 CREWEL  
 ticket # 1911180958  
 Completed 12/10/19  
 Signature OR

East Logan Water District  
**WORK ORDER 14507**

Account # 100001  
Name NOFFSINGER, TERRELL  
Address  
Telephone Job #

Order Date 5/15/2019  
Status MEDIUM  
Scheduled 05/15/19 04:38 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 30318337	70153732	4049	B14169634	

Description  
Comment LF, TAN HSE, RT YD AT FENCE T/  
Requested By Mowing guy Assigned To MAINTENANCE CREW Completed By *MTH*  
Start Date    /    /    Time    :    Completed Date 5/15/19 Time 5:25

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Noticed wet lire on mower and water running in field. Please check (Andy fixed a leak last year with couplings and inserts)  
*Meter # 14167948 07/08 10008632 Reading 5508*  
*M520R-C1-TC-X-A1*

A MOWING

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Buel 190 5160495</i>		
<i>Att. ELWD LTC, ZTRW buy and WRECC</i>		

Inside fence tested positive for chlorine.  
Both sides of Road MARKED with white paint.  
Est Leak 72,000 gal

MOWING

*May 20<sup>th</sup> exp June 6<sup>th</sup>*

*go through neighbors 1<sup>st</sup> house on left. opening in flow yard. Paul Arnold 270-893-5895*

Signature *MTH*



East Logan Water District  
WORK ORDER 14519

Account #  
Name JACKSON, JAMES  
Address  
Telephone

Order Date 5/21/2019  
Status MEDIUM  
Scheduled 05/21/19 01:08 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 31152888 09964879 2273 B14166435

Description  
Comment RT, WH HSE, LF CNR YD

Requested By Assigned To MAINTENANCE CREW Completed By GP/MH

Start Date 1/1 Time : Completed Date 5/24/19 Time 11:00

Make Size/Type Multiplier

Notes 10 gpm Leak About 2 months old  
Total Leak Loss 432,000

Inventory Item And Description	Quantity Ordered	Quantity Used
5' 3/4" Pex waterline		
1 - 3/4" cone nut		
1 - 3/4" mueller nut		
Stevenson Mill - AI Bead - 68/80		
2 - 3/4" INSERTS		

May 23 2pm  
Exp June 11th  
Call back June 7th

AH, ELWD, LTC,  
LTRWC, Texas Gas  
WRECC

Bud 0 1905211629 -

Signature 



East Logan Water District  
**WORK ORDER 14518**

Account #  
Name KNIGHT, PHILLIP M  
Address  
Telephone Job #

Order Date 5/20/2019  
Status MEDIUM  
Scheduled 05/20/19 03:59 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 69361543    ERT/INTERNAL ID# 63066155    READING 3221    LOCATOR TAG B14167785    READING IN / OUT 3233

Description  
Comment RT, WHITE TRLR, RT/DR

Requested By PHILLIP KNIGHT    Assigned To MAINTENANCE CREW    Completed By *CP/MH*  
Start Date    /    /       Time    :       Completed Date 5/24/19    Time 3:37

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes BETWEEN METER AND THE ROAD  
*Q mud: River Valley Rd.*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>6 3/4 inserts</i>		
<i>1 3/4 T</i>		
<i>1 Cone Nut</i>		
<i>5 foot pipe</i>		
<i>1 3/4 coupling</i>		
<i>Repaired service Tube</i>		

*ATT # ELW  
# 1905202227  
3 gpm for 5 day  
TOTAL LEAK LOSS 21,600*

Signature



East Logan Water District  
WORK ORDER 14523

Account #  
Name POWELL, AMANDA L  
Address  
Telephone

Order Date 5/24/2019  
Status MEDIUM  
Scheduled 05/24/19 08:07 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 42228894      ERT/INTERNAL ID# 61287396      READING 7140      LOCATOR TAG B14169945      READING IN / OUT 7180

Description  
Comment LF, HSE OFF RD, LF DR @ Rd

Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW      Completed By *GPH/MLH*  
Start Date   /  /   Time   :  :        Completed Date 5/28/19 Time 12:19

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes could hear water spraying, near water meter

*Reading 7180*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>X-Dennis - Corinth Rd.</i>		
<i>1 3/4 cone Coupling</i>		
<i>1 3/4 Cone Nut</i>		
<i>1 3/4 white Bandaid</i>		
<i>1 3/4 pipe 6" Long</i>		
<i>7 to 2 gpm</i>		
<i>Att, ELWD</i>		

*\* 190 524 1444*

*1 gpm*

*TOTAL LEAK LOSS 5,760*

*POWELL*  
*M. L. H.*

Signature

East Logan Water District  
**WORK ORDER 15037**

Account # .....  
Name HOLLOWAY, MATT  
Address .....  
Telephone ..... Job # .....

Order Date 10/4/2019  
Status MEDIUM  
Scheduled 10/04/19 10:18 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 37330401	10467071	610	B14165425	

Description

Comment LF L/LONG GR DR

Requested By Kenneth Belcher

Assigned To MAINTENANCE CREW

Completed By

Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_

Completed Date 10/19/19 Time 5:45

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Mike Hines says there is a small service leak. Maybe caused by bushhog. Another W/O says a repair made here in 2017  
BUD #1910041146  
marked by 10-8-19 @ 11:00 am  
LTC  
WRECC  
ELWD

Inventory Item And Description	Quantity Ordered	Quantity Used
1 3/4" 2 bolt clamp		
1-10 gpm		

10 gpm

201,600

EH

Signature

East Logan Water District  
**WORK ORDER 15006**

Account #  
Name ORNDORFF JOHN H  
Address  
Telephone Job #

Order Date 9/27/2019  
Status MEDIUM  
Scheduled 09/27/19 03:38 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 48029229 61287391 4552 B14170029

Description  
Comment RT, BRK HSE, M/BIG YD

Requested By Assigned To MAINTENANCE CREW Completed By MA/EH

Start Date 1/1 Time : Completed Date 10/20/19 Time 2:00

Make Size/Type Multiplier  
Notes

Inventory Item And Description	Quantity Ordered	Quantity Used
2 BRASS Fittings 3/4		
1' 3/4 PEX		

Stop @ leak, white paint both sides of rd.  
where 3 services come together

By Oct 2 @ 1:30

Bud  
# 1909301780

25gpm  
2 days  
~~10500~~  
~~276,000~~  
2055  
432,000

ATT - Cleed  
Atmos  
ELWD  
LTC

Signature 

East Logan Water District  
WORK ORDER 14985

Account #  
Name ASHBY, ROGER L  
Address  
Telephone

Order Date 9/23/2019  
Status MEDIUM  
Scheduled 09/23/19 08:31 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

*23 days*

METER# WT 36140694      ERT/INTERNAL ID# 63524771      READING 1548      LOCATOR TAG B15451399      READING IN / OUT

Description  
Comment RT HSE LF CNR

Requested By Roger Ashby      Assigned To MAINTENANCE CREW      Completed By *EH*

Start Date   /  /        Time   :        Completed Date   /  /        Time   :  

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes Mushy at edge of road and green grass.

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>1 3/4 inch d bolt clamp.</i>		
<i>5 gpm</i>		

*X Shutdown by 9-25 @ 9:00 am*

*ATT  
ELWD*

*1909230574*

Signature *EH*

East Logan Water District  
**WORK ORDER 15211**

Account # \_\_\_\_\_ Order Date 12/13/2019  
 Name JOHNSON, CHARLES & AMANDA Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 12/13/19 02 13 PM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 65798130	58647048	4140	B14167995	

Description \_\_\_\_\_  
 Comment LT, TRLR, LT/CNR, T/L  
 Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_  
 Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_ Completed Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
 Notes \_\_\_\_\_

Inventory Item And Description	Quantity Ordered	Quantity Used

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 14982**

Account #  
Name STEENBERGEN, TONY  
Address  
Telephone Job #

Order Date 9/20/2019  
Status MEDIUM  
Scheduled 09/20/19 03:46 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 81271635      ERT/INTERNAL ID# 74600707      READING 2447      LOCATOR TAG B15395651      READING IN / OUT

Description  
Comment LF,BRK/OFF RD LF/DR T/LF

Requested By TONY      Assigned To MAINTENANCE CREW      Completed By  
Start Date 9/19/19      Time 1:00      Completed Date 9/20/19      Time 1:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes HE SAID WATER AROUND METER OR AT THE END OF THE DRIVE

Inventory Item And Description	Quantity Ordered	Quantity Used
<del>100' WATER</del> NO water coming		
from anywhere. Homeowner said it		
had dried up after they fixed the		
leak at the very start of home rd.		

Signature   E.H.

East Logan Water District  
**WORK ORDER 14999**

Account # \_\_\_\_\_ Order Date 9/26/2019  
 Name ANDERSON, CATHARINE L Status MEDIUM  
 Address \_\_\_\_\_ ; Scheduled 09/26/19 10:09 AM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
 WT 66964680 60661462 8513 B14168068 8573

Description \_\_\_\_\_  
 Comment LF,WH HSE,RT DR,2ND METER  
 Requested By JOHN ANDERSON Assigned To MAINTENANCE CREW Completed By *JP*  
 Start Date   /  /   Time   :   Completed Date 9/30/19 Time   :  

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes STATED THAT HIS METER BOX AND THE ONE NEXT TO IT HAS FRESH STANDING WATER IN THEM.  
 CHECK TO MAKE SURE THAT WE DON'T HAVE A LEAK ON OUR SIDE THAT IS FILLING THE METER  
 BOXES UP

*marked white point and blue flag*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>2 brass nipples 4 1/2" fittings</i>		
<i>1 foot of blue PEX</i>		
<i>5-76pm</i>		

*marked by 10-3-19 @ 9:30 am*

*# 1910010626*

*ATT marked clear*

*ELWD*

*LTC - good but ~~not~~ <sup>have something</sup> at bypass by fence*

*LTRWC*

*Atmos*

*2 Mid Valley Pipe line*

Signature *Paul*



East Logan Water District  
**WORK ORDER 14544**

Account # \_\_\_\_\_ Name HART, JASON G Address \_\_\_\_\_ Telephone \_\_\_\_\_ Job # \_\_\_\_\_  
Order Date 6/3/2019 Status MEDIUM Scheduled 06/03/19 12 05 PM Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 000063869532 ERT/INTERNAL ID# 56502041 READING 6683 LOCATOR TAG B14166578 READING IN / OUT 670/97.6

Description \_\_\_\_\_ Comment RT GRAY TRLR L/YD DOG! Requested By JASON HART Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_  
Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_:\_\_\_\_ Completed Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_:\_\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes CUST STATED THAT INFRONT OF METER BOX WATER IS STANDING, AND THAT CUSTOMER HAS BEEN PUMPING IT OUT OF THE BOX OVER THE WEEKEND

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Repairs have been made.</i>		
<i>Be agreed.</i>		

*Completed  
12/13/19  
DR ST.*

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 15165**

Account # \_\_\_\_\_ Order Date 11/25/2019  
Name PUGH, GARY Status MEDIUM  
Address \_\_\_\_\_ Scheduled 11/25/19 09 58 AM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
WT 78785964 73606950 3880 B14168092

Description \_\_\_\_\_  
Comment RT, WH/HSE, RT/DR  
Requested By MS PUGH Assigned To MAINTENANCE CREW Completed By EH  
Start Date 11/25/19 Time \_\_\_\_\_ Completed Date 11/25/19 Time 1:13

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes SAYS WHERE MAIN WAS FIXED THAT IT'S STILL LEAKING. CHECK, PLEASE TRY NOT TO MESS UP CUSTOMERS YARD OR RUN OVER METER-PER CUST REQUEST-

Inventory Item And Description	Quantity Ordered	Quantity Used
The main is seep, AG		
Probably the band.		

Signature EH

East Logan Water District  
**WORK ORDER 15023**

Account # \_\_\_\_\_ Order Date 10/3/2019  
 Name PRUNTY, MARY JANE Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 10/03/19 08 44 AM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
 WT 36635914 58943335 3878 B14169661

Description \_\_\_\_\_  
 Comment LF TRLR M/YD T/A T/RT MONTGOME

Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_  
 Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_ Completed Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes \_\_\_\_\_

*Leak on cust side - gp BW*

Inventory Item And Description	Quantity Ordered	Quantity Used

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 15014**

Account # \_\_\_\_\_  
Name ENGLER, PHILLIP R  
Address \_\_\_\_\_  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_

Order Date 9/30/2019  
Status MEDIUM  
Scheduled 09/30/19 03.11 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 52473820      ERT/INTERNAL ID# 64887912      READING 6125      LOCATOR TAG B14172310      READING IN / OUT \_\_\_\_\_

Description \_\_\_\_\_  
Comment RT, GRAY HSE, RT/YD

Requested By mr engler      Assigned To MAINTENANCE CREW      Completed By EH  
Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_      Completed Date 10/1/19 Time 3:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes says meter box is full of water.

Inventory Item And Description	Quantity Ordered	Quantity Used
2 1/4 inch coupling		

~~\_\_\_\_\_~~ ~~\_\_\_\_\_~~ ~~\_\_\_\_\_~~

Signature EH

East Logan Water District  
**WORK ORDER 15009**

Account # 1  
Name CHRIS COLLINS CONSTRUCTION  
Address  
Telephone Job #

Order Date 9/30/2019  
Status MEDIUM  
Scheduled 09/30/19 10:28 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 78785933	73606919	26	B15347422	00030

Description  
Comment

Requested By Chris Assigned To MAINTENANCE CREW Completed By MH/EH  
Start Date 1/1 Time : Completed Date 10/13/19 Time 1:04

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes Chris says its leaking at meter when water is being used

Inventory Item And Description	Quantity Ordered	Quantity Used

Loose nut on meter Tightned not Leaking now  
223-7904  
Already Notified Customer

*EH*

Signature

East Logan Water District  
**WORK ORDER 14961**

Account # \_\_\_\_\_ Order Date 9/17/2019  
 Name DUKES, EARL Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 09/17/19 10:00 AM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 66990238 ERT/INTERNAL ID# 60687667 READING 2290 LOCATOR TAG B14170142 READING IN / OUT \_\_\_\_\_

Description \_\_\_\_\_  
 Comment RT HSE RT CNR  
 Requested By Mike Hines Assigned To MAINTENANCE CREW Completed By *MH*  
 Start Date    /    /    Time    :    Completed Date 9/17/19 Time 12:53

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
 Notes \_\_\_\_\_

Inventory Item And Description	Quantity Ordered	Quantity Used

*Leak on Cust. Side*

Signature *Mike Hines*

East Logan Water District  
**WORK ORDER 14620**

Account #  
Name MADISON, MICHELE E  
Address  
Telephone Job #

Order Date 6/13/2019  
Status MEDIUM  
Scheduled 06/13/19 11:10 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 50055747      ERT/INTERNAL ID# 10277540      READING 7523      LOCATOR TAG B14167619      READING IN / OUT

Description  
Comment RT,TRLR LFYD

Requested By LINDA

Assigned To MAINTENANCE CREW

Completed By MH/EH

Start Date   /  /   Time   :  


Completed Date 6/13/19 Time 9:40

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes DRUNK DRIVER RAN OVER METER AREA PLEASE SEE IF THERE IS A LEAK, AND ON WHOSE SIDE

No ~~leak~~ sign of leak But meter is turning very slow  
Reading 7587

Inventory Item And Description	Quantity Ordered	Quantity Used

Signature 

East Logan Water District  
**WORK ORDER 14284**

Account # 0000  
Name YATES PICKY D  
Address 06-9111  
Telephone ob #

Order Date 3/18/2019  
Status MEDIUM  
Scheduled 03/18/19 12:16 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 46202673	72841832	960	B14167217	0969

Description RT,LF OF GR DR  
Comment

Requested By Assigned To MAINTENANCE CREW Completed By *[Signature]*  
Start Date   /  /   Time   :   Completed Date 3/21/19 Time 10:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes small leak on our side, pretty sure that it's the screw

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>NO LEAK</i>		

*Happy Hallow in  
S. Collins Rd.*

*March 22  
exp April 10*

*Logans Tell  
ELWD  
400 190 320 1139*

*[Signature]*

Signature



East Logan Water District  
**WORK ORDER 14004**

Account # \_\_\_\_\_ Order Date 1/15/2019  
 Name MOSIER, SEAN & STACY Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 01/15/19 08:17 AM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 57551131	71205611	3147	B14167192	

Description \_\_\_\_\_  
 Comment RT, BRK HSE, LF CNR IN FIELD  
 Requested By sean mosier Assigned To MAINTENANCE CREW Completed By CP / RHT  
 Start Date 1/15/19 Time 16:40 Completed Date 1/15/19 Time 16:40

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes  
exp. IRB S

Inventory Item And Description	Quantity Ordered	Quantity Used
Att, ELWD, LTRWC		
1901150350		
Leak on their side		

Signature *Paci*

East Logan Water District  
**WORK ORDER 14726**

Account #  
Name BELCHER, WAYNE  
Address  
Telephone

Order Date 7/16/2019  
Status MEDIUM  
Scheduled 07/16/19 02:46 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
VT 81568829	74698200	1966	B14168537	

Description  
Comment LF, BRK HSE, LF IN FIELD, O/FE

Requested By MR BELCHER Assigned To MAINTENANCE CREW Completed By GP  
Start Date 7/16/19 Time 3:00 Completed Date 7/16/19 Time 3:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes CUSTOMER CAME IN STATED THAT END OF THE RD. END OF THE LINE, THAT WHERE LEAK HAD BEEN REPAIRED BEFORE HE BELIEVES THAT ITS BEEN LEAKING AGAIN FOR THE PAST COUPLE OF MONTHS could this have anything to do with the pressure on slim collins??

Inventory Item And Description	Quantity Ordered	Quantity Used
Repaire water leak wat for this house!! House across the Road Meter ID 09233928 Reading 8625		
Two pin holes in service line (X 2) 1 to 2 gpm on each		
Two sherk bites 3/4 Pice of pipe four 1/2 feet Long		

*From Blown*

*7347 8839 meter ID*

*ELWD, LTC  
190726 1492*

*July 30  
Spn.*

*[Handwritten Signature]*

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 14738**

Account #  
Name MUELLER, BRIAN S  
Address  
Telephone Job #

Order Date 7/22/2019  
Status MEDIUM  
Scheduled 07/22/19 08:40 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 66684123      ERT/INTERNAL ID# 58647041      READING 4873      LOCATOR TAG B14167676      READING IN / OUT 4910

Description  
Comment RT, WOOD HSE, RT/1ST DR  
Requested By Brian      Assigned To MAINTENANCE CREW      Completed By *MAY/BW/EI*

Start Date   /  /   Time   :        Completed Date *7/22/19* Time *9:3*

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Mowing and found really wet spot around meter. Please check for leak

*Leak in Service Line Before Meter*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Repair Service Line</i>		
<i>1 3/4 shock bite pipe hole</i>		
<i>in line</i>		

*Road MARKed in white PAINT  
Blue FLAG AT LEAK*

*5-7 gpm*

*X Morgantown Rd*

*AH, Bluegrass Gas*

*ELWD, LTRWC*

*WPP Aug 14*

*190 727 0800*

Signature *[Handwritten Signature]*

East Logan Water District  
**WORK ORDER 14839**

Account #  
Name LATHAM, JENNIFER L  
Address  
Telephone Job #

Order Date 8/13/2019  
Status MEDIUM  
Scheduled 08/13/19 12:01 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 36140719	10347294	8745	B14168535	

Description  
Comment RT, WH/HS R/DR  
Requested By Phil Baker Assigned To MAINTENANCE CREW Completed By *GP*  
Start Date   /  /   Time   :   Completed Date 8/16/19 Time   :  

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Check around meter, water is flowing from there and then downhill

*Replace service line all the way to the house!*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>10.5 in of Blue Pet!</i>		
<i>2 3/4 insects</i>		
<i>Aug 16 @ 3:30</i>		

*- WM Brown Rd -*

ELWD, LTC

190814 1501

Signature

East Logan Water District  
WORK ORDER 14780

Account #  
Name HUTCHESON, HOWARD  
Address  
Telephone ( ) Job #

Order Date 8/6/2019  
Status MEDIUM  
Scheduled 08/06/19 08:08 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 37330397      ERT/INTERNAL ID# 10054771      READING 4415      LOCATOR TAG B14169712      READING IN / OUT

Description

Comment RT, WH/HS, R/DR

Requested By Wanda Hutcheson      Assigned To MAINTENANCE CREW      Completed By *mt*

Start Date   /  /   Time   :        Completed Date *8/6/19* Time *2:30*

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes to the right of her house, there used to be a trailer that was removed 15 yrs ago. She says there is a wet, soggy spot there. Please see if this is a leak. If its from the old meter, it can be removed and turned off at corp.

*Leaking prob at corp same side as main  
MARKED in white paint + blue flag*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Dug down and shut off corp!! 2 to 3 pm</i>		

Meter # 10086037

Reading 3097

*ELWD, LTC  
WRECC*

*Wanda H*

Signature

East Logan Water District  
**WORK ORDER 14756**

Account #  
Name LOWHORN, ASHLEY M  
Address  
Telephone Job #

Order Date 7/29/2019  
Status MEDIUM  
Scheduled 07/29/19 10 30 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN/OUT  
WT 52473815 59637883 4577 B14166345 4027

Description  
Comment RT BRK L/DR 2ND MTR

Requested By 2705429062 Assigned To MAINTENANCE CREW Completed By GP  
Start Date 7/29 Time 10:30 Completed Date 7/29/19 Time 2:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes check for water standing in yard around meter this area has been repaired before  
yes is to look head mark in white and blue  
Flag on leak!

Inventory Item And Description	Quantity Ordered	Quantity Used
<u>1 cone nut</u>		
<u>1 w/weller</u>		
<u>2 inserts</u>		
<u>8 foot of pipe</u>		
<u>Replaced service All the way Beck</u>		
<u>To main it had about 4 small</u>		
<u>leaks in old tube 2 to 3 gpm</u>		

ELWD, LTC WRECC

1879

Signature *Prui*

East Logan Water District  
**WORK ORDER 14542**

Account #  
Name STEWART, PATRICK H  
Address  
Telephone Job #

Order Date 6/3/2019  
Status MEDIUM  
Scheduled 06/03/19 08:37 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 36635913	64952914	2475	B14169593	

Description  
Comment RT, TRLR, LF YD AT P POLE  
Requested By Patrick

Assigned To MAINTENANCE CREW Completed By MH

Start Date    /    /    Time    :    :    Completed Date 6/3/19 Time 11:28  
6:40 11:40

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes Water around meter to road Small Leak on our side (MARKED in white)  
Meter is TURNED off Blue flag at meter

Inventory Item And Description	Quantity Ordered	Quantity Used
60' $\frac{3}{4}$ " Pex waterline		
2- $\frac{3}{4}$ " cone nuts		
2- $\frac{3}{4}$ " inserts		

10 gpm Leak

Still needs  
be repaired  
bud called 6-3-19  
LTC, WRECC

Signature



East Logan Water District  
**WORK ORDER 16033**

Account #  
Name POLACHECK, LISA  
Address  
Telephone

Order Date 8/3/2020  
Status MEDIUM  
Scheduled 08/03/20 02.43 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 9135967  
Description RT.BRK HSE.MDLYD  
Comment  
Requested By  
Job #  
ERT/INTERNAL ID# 9135967  
READING 1425  
LOCATOR TAG  
READING IN / OUT 155807.0  
8-7-20 2:27 PM  
Assigned To MAINTENANCE CREW  
Completed By  
Start Date 1/1 Time :  
Completed Date 8/18/20 Time 2:30

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes \_\_\_\_\_

Inventory Item And Description	Quantity Ordered	Quantity Used
Fixed leak in bat on <del>customer</del> <sup>customer</sup> Side		
3 gpm		
2' pipe 1 sharkbite 1 comp Nut 1 insert		
8-18-20 Palled New Service line 50' 3/4" CT's		
2 comp Nuts		
2 gpm X 21 days		

35,300 gal is on us - flushing  
from July reading - Aug. 2020

13,300 has gone thru meter since 8-7-20

Signature \_\_\_\_\_



East Logan Water District  
**WORK ORDER 16066**

Account # \_\_\_\_\_ Order Date 8/10/2020  
 Name KINSER, WILLARD Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 08/10/20 08.45 AM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
 WT 50514853 62351418 7202 B14167713

Description  
 Comment RT, FENCE CNR AT B O T/A T/L  
 Requested By Stephen Assigned To MAINTENANCE CREW Completed By *EA KH*  
 Start Date   /  /   Time   :   Completed Date 8/31/20 Time   :  

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
 Notes Hole in setter, setter will need to be changed per ST

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>New Sense 2'</i>		
<i>New Setter</i>		
<i>6 gpm X 14 days</i>		

*one side  
 & marker  
 painted*

locate by 8-12-20 11:00 Am  
 ELWD  
 LTC  
 # 2008100931

Signature EA KH

East Logan Water District  
**WORK ORDER 15994**

Account #  
Name SHOULDERS, BRIAN S  
Address  
Telephone Job #

Order Date 7/27/2020  
Status MEDIUM  
Scheduled 07/27/20 09:17 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 46202632  
 FRI/INTERNAL ID# 09204546  
 READING 6319  
 LOCATOR TAG B14250084  
 READING IN / OUT 6349

Description  
Comment RT BRN HSE, LF DR, READ 2

Requested By rodney werth  
Assigned To MAINTENANCE CREW  
Completed By *ST*  
Start Date    /    /    Time    :    :     
Completed Date 8/11/20 Time 11:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes says that trash truck has ran over the meter and crushed the pipe, that water is running out, not sure if it's on our side or the customer side

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>New Sewer Line + New box + lid</i>		
<i>10' pipe 2 comp Nuts 2 inserts</i>		
<i>3 gpm x 30 days</i>		

*Wetley Ridge*

Signature *ST*

East Logan Water District  
**WORK ORDER 16036**

BELCHER, KENNETH WAYNE

Order Date 8/4/2020  
Status HIGH  
Scheduled 08/04/20 09:45 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

Job #	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
A31576	59637880	3553	B14167597	

Description: RT BRK L/DR  
Requested By: Mr. Belcher  
Assigned To: MAINTENANCE CREW  
Completed By:  
Start Date: / / Time: :  
Completed Date: / / Time: :

Make: Size/Type: Multiplier:  
Notes: He says water is in the edge of his field; possibly where we tapped/set a meter is leaking.

*corp turned off*

Inventory Item And Description	Quantity Ordered	Quantity Used
not leaking here, but leaking about 150' past -		
Service was not activated - no meter in box not listed in computer - turned off at corp.		

*could be 12315*

*tapped to ST*

*marked / paint on one side L*

*Stephen says it is a leak - maybe at corp.*

*X Hamilton Lane or 103*

*ELWD locate by LTC WRECC*

*# 200810 0924*

East Logan Water District  
**WORK ORDER 16076**

Account #  
Name FARLEY, BRENDA  
Address  
Telephone

Order Date 8/4/2020  
Status MEDIUM  
Scheduled 08/12/20 10:57 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT No Num	00013882		LF L/GR DR	

Description  
Comment LF L/GR DR  
Requested By Kenneth Belcher Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW  
Start Date 08/11/20 12:00 AM Completed Date 08/11/20 12:00 PM

Notes Account has never been hooked up, so instead of pulling a new service line, we turned off the at corporation stop to prevent future leaks

*Completed  
8/11/20*

Signature

*8/11/20 KH, KdB*

East Logan Water District  
**WORK ORDER 16036**

Account # \_\_\_\_\_ Order Date 8/4/2020  
Name CARROLL, DOUG Status MEDIUM  
Address \_\_\_\_\_ Scheduled 08/04/20 08:14 AM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 69361564	63066176	3277	B14167499	

Description  
Comment LF, TAN HSE, M/YD  
Requested By BONNIE CARROLL Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_  
Start Date   /  /   Time   :   Completed Date 8/5/20 Time 7:40

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes WATER IS STANDING AROUND METER, HAS BEEN THIS WAY FOR COUPLE WEEKS, EVEN WHEN DRY  
IT'S EXTREMELY MUSHY AND WET

*There is probly is a leak, Dig up*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Fixed. pulled new service.</i>		
<i>α bpm, HQ 16</i>		
<i>Fixed 7-20-20</i>		

*uptul ST  
x 79*

*marked both side*

*locats by 8-12 @ 11:00 am*

*ATT  
ELWD*

*# 2008100921*

Signature     *ELWD*

East Logan Water District  
**WORK ORDER 16059**

Account #  
Name FISHER, SAM  
Address  
Telephone Job #

Order Date 8/7/2020  
Status MEDIUM  
Scheduled 08/07/20 08 23 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 24561704    ERT/INTERNAL ID# 55166351    READING 4476    LOCATOR TAG B14169380    READING IN / OUT 4504

Description  
Comment LF, WHSE LF DRIVE

Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW    Completed By EH  
Start Date 8/1/20 Time \_\_\_\_\_    Completed Date 8/10/20 Time 8:03

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes says that meter box is filled with water, and water is all around meter box  
I think there might be a leak in front of the box

Inventory Item And Description	Quantity Ordered	Quantity Used
<u>4551 (8-26-20)</u>		
<u>1 gpm - 30 days KH</u>		
<u><del>4567</del> KH</u>		
<u>(9-1-20) completed</u>		

- Fixed leak, pulled new service line. 10ft of pex used.

EH

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 16078**

Account #  
Name BILYEU, DAKODA C  
Address  
Telephone Job #

Order Date 8/13/2020  
Status MEDIUM  
Scheduled 08/13/20 10:54 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 9135930	9135930	442		

Description  
Comment RT, BRK HSE, RT DR

Requested By dakoda bilyeu Assigned To MAINTENANCE CREW Completed By  
Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_ Completed Date 8/17/20 Time 7:40

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes 10 ft from mailbox, looks like pigs have wallered :) Ethan and Stephen fixed a leak right outside of the meter box in february of this year

*There is a leak here at the CORP.*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Fixed. <del>2 gpm x 20 days</del></i>		
<i>2 gpm x 20 days</i>		

*7.25*

Signature *EH*

East Logan Water District  
**WORK ORDER 16091**

Account # \_\_\_\_\_ Order Date 8/19/2020  
Name LONG. BILL Status MEDIUM  
Address \_\_\_\_\_ Scheduled 08/19/20 08.17 AM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
WT 42033350 08647047 4550 B14167617 01553710

Description \_\_\_\_\_  
Comment LF.BRK/HSE RT/DR  
Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By *EH*  
Start Date   /  /   Time   :  :   Completed Date   /  /   Time   :  :  

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes \_\_\_\_\_  
*IS a 10016*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Replaced Service Line 65' 3/4 CT5</i>		
<i>2 comp Nuts</i>		
<i>15 gpm X 10 days</i>		

*ELWD  
LTC  
2008190412*

*4355 Homer RD  
ELWD  
LTC  
will  
2008190412*

*41000 gallon  
for flushing*

*EH*

www.eastloganwater.com  
270-542-6856

Signature \_\_\_\_\_





East Logan Water District  
**WORK ORDER 16018**

Account #  
Name BALDWIN, RONALD R  
Address  
Telephone Job #

Order Date 7/30/2020  
Status MEDIUM  
Scheduled 07/30/20 04:50 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 50056531      ERT/INTERNAL ID# 09720861      READING 2367      LOCATOR TAG B14167459      READING IN / OUT

Description  
Comment LF YELLOW HSE, LF DR

Requested By Mr. Baldwin      Assigned To MAINTENANCE CREW      Completed By  
Start Date   /  /        Time   :        Completed Date 7/31/20      Time 2:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Our 6" mains runs down the left of his house towards the house behind him that faces Franklin Rd. He thinks we have a leak on that line, close to where it T's behind his house. Call him and he can show you.

Inventory Item And Description	Quantity Ordered	Quantity Used
Test positive for Chlorine		
Leak in back yard		
300' from Road		
5gpm X 14 days		
- Leaking at the 90° <del>at the 90°</del>		
replaced the 90°		
8-13-20 completed		

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 16093**

Account #  
Name THOMPSON, ERNEST  
Address  
Telephone

Order Date 8/19/2020  
Status MEDIUM  
Scheduled 08/19/20 09:40 AM  
Order Type LEAK BY FIBER INSTALLATION

METER# WT 68553084      ERT/INTERNAL ID# 62326771      READING 585      LOCATOR TAG B14170181      READING IN / OUT

Description  
Comment LF BARN LF CNR

Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW      Completed By STPH HDEH

Start Date   /  /   Time   :  :        Completed Date 8/18/20 Time 9:00 PM

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes main line hit by fiber crews

Inventory Item And Description	Quantity Ordered	Quantity Used
<u>7' of 6" pipe</u>		
<u>2 knock ons</u>		
<u>tube</u>		
<u>5 hrs labor</u>		
<u>4 pm - 9 pm</u>		
<u>4000 gal leak</u>		
<u>8000 Flush</u>		

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 16022**

Account #  
Name SCHMITT, RACHEL L  
Address  
Telephone Job #

Order Date 8/3/2020  
Status MEDIUM  
Scheduled 08/03/20 09 17 AM  
Order Type LEAK BY FIBER INSTALLATION

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 68654618 73543857 3394 B15197421

Description  
Comment RT R/CNR THORTON RD

Requested By Assigned To MAINTENANCE CREW Completed By  
Start Date 8/1/20 Time : Completed Date 8/13/20 Time :

Make Size/Type Multiplier  
Notes

Inventory Item And Description	Quantity Ordered	Quantity Used
Repair Service Line 1"		
Replaced 4' pipe 2 couplers		
1.5 gpm 1 1/2 hr		
1 gpm X 3 days		

WCS Backfilling Pulled repair apart on 8-7-20 at 8:00pm. Temp repair made then that repair came apart on 8-8-20 at 7pm Ethan made temp repair until good Repair could be made  
Replaced 4' with 1" pex 2 Brass adapters  
2' glue on PVC

Signature \_\_\_\_\_

East Logan Water District  
WORK ORDER 16044

Account # \_\_\_\_\_ Order Date 8/5/2020  
 Name ORDER, WORK Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 08/05/20 03 10 PM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE  
 METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
 WT No Num \_\_\_\_\_  
 Description \_\_\_\_\_  
 Comment \_\_\_\_\_  
 Requested By ETHAN Assigned To MAINTENANCE CREW Completed By STEVE FOSTER  
 Start Date 8/1/20 Time \_\_\_\_\_ Completed Date 8/1/20 Time 2:00p

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
 Notes LEAK CORNER OF BUCKSVILLE RD AND HOPE WAY

Inventory Item And Description	Quantity Ordered	Quantity Used
Replaced 30' of 6" pipe 3 knock outs		
1.72 gpm leak x 3 days		

Signature 

East Logan Water District  
WORK ORDER 16013

Account # \_\_\_\_\_ Order Date 7/30/2020  
 Name ORDER, WORK Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 07/30/20 10.06 AM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE  
 METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
 WT No Num \_\_\_\_\_  
 Description \_\_\_\_\_  
 Comment \_\_\_\_\_  
 Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By *J. D. H.*  
 Start Date   /  /   Time   :  :   Completed Date   /  /   Time   :  :  

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
 Notes CORNER OF LOGAN MIDDLETON AND FRIENDSHIP RD

Inventory Item And Description	Quzntity Ordered	Quantity Used
<i>2 gainx 21 days</i>		
<del><i>[scribbled out text]</i></del>		
<del><i>[scribbled out text]</i></del>		
<del><i>[scribbled out text]</i></del>		
<del><i>[scribbled out text]</i></del>		
<del><i>[scribbled out text]</i></del>		
<del><i>[scribbled out text]</i></del>		
<del><i>[scribbled out text]</i></del>		
<i>Replace 6' of 4" pipe 2 knee caps</i>		

*WA*

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 16094**

Account #  
Name WATKINS, MAURICE  
Address  
Telephone Job #

Order Date 8/19/2020  
Status MEDIUM  
Scheduled 08/19/20 09:42 AM  
Order Type LEAK BY FIBER INSTALLATION

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 9434292 9434292 410

Description  
Comment RT, GRAY DBL WIDE, 10' RT DR T

Requested By Assigned To MAINTENANCE CREW Completed By *M. Watkins*

Start Date 8/19/20 Time 09:42 Completed Date 8/19/20 Time 11:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes line hit by fiber crews

Inventory Item And Description	Quantity Ordered	Quantity Used
8' section of 4" pipe		
2 Fittings		
Lube		
3 hrs labor		
5000 gal lost to leak		
10000 Flush		

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 16092**

Account # 1  
Name CRABTREE-HOUSE, DICK  
Address  
Telephone Job #

Order Date 8/19/2020  
Status MEDIUM  
Scheduled 08/19/20 09:39 AM  
Order Type LEAK BY FIBER INSTALLATION

METER# WT 65798097  
ERT/INTERNAL ID# 58647015  
READING 5091  
LOCATOR TAG B15431668  
READING IN / OUT

Description  
Comment RT, BRK HSE, RT CNR AT SIDE (D)

Requested By Assigned To MAINTENANCE CREW Completed By

Start Date   /  /   Time   :  :    
Completed Date 8/17/20 Time 9:30

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes main line hit by fiber crews

Inventory Item And Description	Quantity Ordered	Quantity Used
Replaced 7' of 4" line & fittings		
400 gpm x 2 hrs		
Flushed 35000 gal		

Signature \_\_\_\_\_



East Logan Water District  
**WORK ORDER 16064**

Account #  
Name CUMMINGS, MARTHA M  
Address  
Telephone Job #

Order Date 8/10/2020  
Status MEDIUM  
Scheduled 08/10/20 08 13 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 81271626	74600698	1990	B15396184	02058 KH

Description

Comment RT,TRLR,MYD

Requested By Martha Cummings

Assigned To MAINTENANCE CREW

Completed By

Start Date   /  /   Time   :  

Completed Date 8/12/20 Time 1:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Leak around meter and now a spot in the road

Inventory Item And Description	Quantity Ordered	Quantity Used
- Everything seems to still be dry. No signs of any leaks.		
3pm x 6 days		
1 belt		

Signature

East Logan Water District  
**WORK ORDER 16116**

Account #  
Name MAYHEW, PAMELA N  
Address  
Telephone Job #

Order Date 8/31/2020  
Status MEDIUM  
Scheduled 08/31/20 09 04 AM  
Order Type READ OUT, LOCK, FINAL OUT

METER# WT 000048979817    ERT/INTERNAL ID# 58447910    READING 6112    LOCATOR TAG B14169742    READING IN / OUT          /         

Description  
Comment RT, 2ND WH HSE. L IN YD BY FEN

Requested By pam mayhew    Assigned To MAINTENANCE CREW    Completed By  
Start Date   /  /      Time   :      Completed Date   /  /      Time   :  

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes \_\_\_\_\_

Inventory Item And Description	Quantity Ordered	Quantity Used
- Need to change meter bottom. Meter bottom was leaking. 8-31-20		
- Replaced meter bottom 1gpm 8-31-20		

*Customer contacted us on 8/31/20 about a leak.*

*KF*

East Logan Water District  
**WORK ORDER 16097**

Account #  
Name SHUBBUCK, STEPHEN R  
Address  
Telephone Job #

Order Date 8/20/2020  
Status MEDIUM  
Scheduled 08/20/20 09:27 AM  
Order Type MISCELLANEOUS

METER# WT 45221786      ERT/INTERNAL ID# 72175792      READING 2540      LOCATOR TAG B14169585      READING IN / OUT

Description  
Comment RT.BRK/HSE L/CNR

Requested By customer      Assigned To MAINTENANCE CREW      Completed By *ST*  
Start Date \_\_\_/\_\_\_/\_\_\_      Time \_\_\_:\_\_\_      Completed Date 8/20/20      Time 1:06

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes As of Thursday morning, they are still having milky water Can we flush there? LA

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Opened Valve in yard so water could be flushed past this house down line.</i>		
<i>Flushed for 80 minutes @ 170gpm est.</i>		
<i>Water was clear and good chlorine.</i>		

Signature *ST*

East Logan Water District  
**WORK ORDER 16006**

Account # \_\_\_\_\_ Order Date 7/29/2020  
Name FLIPPIN, STACY J Status MEDIUM  
Address \_\_\_\_\_ Job # 793 Scheduled 07/29/20 08:26 AM  
Telephone \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 50055705	71205589	2223	B14166564	2223

Description \_\_\_\_\_  
Comment LT, 150' PAST RD BARN  
Requested By Marcus Huffman/ST Assigned To MAINTENANCE CREW Completed By EH  
Start Date 7/29 Time \_\_\_\_\_ Completed Date 7/29/20 Time 8:51

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes could be leaking thru shutoff  
Box is OK

Inventory Item And Description	Quantity Ordered	Quantity Used
<u>Needs a cap in the meter</u>		
<u>Cap off at setter</u>		

Signature EH

East Logan Water District  
**WORK ORDER 15959**

Account # \_\_\_\_\_  
Name ORDER, WORK  
Address \_\_\_\_\_  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_  
Order Date 7/14/2020  
Status MEDIUM  
Scheduled 07/14/20 01:06 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_

WT No Num \_\_\_\_\_

Description \_\_\_\_\_

Comment \_\_\_\_\_

Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By *[Signature]*  
Start Date 7/14/20 Time 1:00 Completed Date 7/14/20 Time 1:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes CORNER OF LOGAN MIDDLETON & FRIENDSHIP CHECK FOR LEAK

*LH KH ST 1*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>1/15 a leak marked RD</i>		
<i>10 sprays x 14 days</i>		
<i>Replaced 3' pipe 2 inserts 2 rings</i>		
<i>Needs New Service when possible</i>		

*1307  
Old Greenville  
hillside  
water coming*

Signature *[Signature]*

East Logan Water District  
**WORK ORDER 15993**

Account #  
Name MOORE, JAMES D  
Address  
Telephone Job #

Order Date 7/27/2020  
Status MEDIUM  
Scheduled 07/27/20 09:00 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 52473742	07306174	5396	B14169473	

Description  
Comment LT, LT/GR LN, TURN AT METAL GA  
Requested By STEPHEN Assigned To MAINTENANCE CREW Completed By  
Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_ Completed Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes \_\_\_\_\_

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>1.00 1.00 1.00 1.00</i>		
<i>1.00 1.00 1.00 1.00</i>		
<i>1.00 1.00 1.00 1.00</i>		
<i>1.00 1.00 1.00 1.00</i>		
<i>1.00 1.00 1.00 1.00</i>		
<i>Turned off at corp + Capped</i>		

*7/27/2020*

East Logan Water District  
**WORK ORDER 15923**

Account #  
Name KEMP, MICHAEL OR VICKIE  
Address  
Telephone Job #

Order Date 7/2/2020  
Status MEDIUM  
Scheduled 07/02/20 10:30 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 00006860473	56501982	4326	B15451489	4335

Description  
Comment LF, HSE OFF RD, RT DR AT INTER

Requested By mr kemp Assigned To MAINTENANCE CREW Completed By

Start Date 7/1/20 Time 10:00 Completed Date 7/2/20 Time 9:30

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes 3 ft on our side from the customer meter box

*Dodson Rd*

Inventory Item And Description	Quantity Ordered	Quantity Used
80' pex		
1 male threaded X Male insert brass		
1 Female threaded X Male insert		
2 crimp Rings		
1 gpm x 14 days = 29,160		

*Kenny*

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 15962**

Account #  
Name GREGORY, LISA  
Address 400 C  
Telephone Job #

Order Date 7/14/2020  
Status MEDIUM  
Scheduled 07/14/20 03:02 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 43605877  
ERT/INTERNAL ID# 09528452  
READING 343  
LOCATOR TAG B14167085  
READING IN / OUT 359

Description  
Comment LF TRLR 25' L/DR

Requested By DAVID GREGORY  
Assigned To MAINTENANCE CREW  
Completed By *ST E/A PM*

Start Date 7/14 Time      
Completed Date 7/14/20 Time 4:45

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes WATER IS RUNNING DOWN THE DITCHLINE.  
DAVI:

*Leaves around meter are damp, but <sup>water</sup> on lot*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>and running down ditch lines</i>		
<i>Leak under Road Need New Service Line</i>		
<i>Replaced Service Line 75' per 3 comp Nuts</i>		
<i>2 inserts 1 brass Female thread X male insert</i>		
<i>1- 3/4 PVC glue Female X Male thread</i>		
<i>New Seater, 5-bar, + Regulator</i>		
<i>10 gpm for 7 days</i>		

*Called In 7-14-20 5:08 PM*

*Contractor II  
87105*

ELWD  
LTC  
WRECC

*Confirmation #  
2007142087*

*NEW mtr - 22053519  
Reading - 00002799.2*

*17 Jul Prop Notice*

Signature *ST*



East Logan Water District  
**WORK ORDER 15950**

Account #  
Name RUST, FRANK  
Address  
Telephone

Order Date 7/13/2020  
Status MEDIUM  
Scheduled 07/13/20 08:31 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 51170348	56488697	6896	B14168335	6899

Description  
Comment RT BRK LYARD

Requested By Ethan Assigned To MAINTENANCE CREW Completed By STEPHEN KID

Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_ Completed Date 7/15/20 Time 11:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Leak on our side per Ethan

Inventory Item And Description	Quantity Ordered	Quantity Used
New Service line 3/4 per 75'		
2 Compression nuts		
New Meter box + lid		
4 gpm 14 days		
July 15 @ 10:15		
EXP Aug 3		

ELWD  
LTC  
WRECC

2007130950

Signature ST

East Logan Water District  
WORK ORDER 15978

Account # \_\_\_\_\_ Order Date 7/20/2020  
Name SHOEMAKE, DANNY D Status MEDIUM  
Address \_\_\_\_\_ Scheduled 07/20/20 06:17 AM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 82995072	89283281	2033	B15440706	

Description \_\_\_\_\_  
Comment RT WH HSE LON GR DR M/FR YD  
Requested By Stephen Assigned To MAINTENANCE CREW Completed By SJ KH EH  
Start Date 7/20/20 Time 10:00 Completed Date 7/20/20 Time 10:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Stephen found the leak at this address. BUD call  
  
# 2007200195 locate front of property both side of road  
LTC  
WRECC  
ELWD

Inventory Item And Description	Quantity Ordered	Quantity Used
<u>1/2" crack X 7' long</u>		
<u>7' split in 4" Main</u>		
<u>350 gpm 1 1/2 Lr 22500 loss to leak</u>		
<u>Replaced 8' Section 2 knock ons</u>		

Signature SJ

East Logan Water District  
**WORK ORDER 15980**

Account # \_\_\_\_\_ Order Date 7/20/2020  
 Name PRICE, WELDON J Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 07/20/20 12:13 PM  
 Telephone \_\_\_\_\_ JOB # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 43518910	63153563	2948	B14169004	

Description \_\_\_\_\_  
 Comment \_\_\_\_\_  
 Requested By Ethan Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_  
 Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_ Completed Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Across from this address, at an old meter, Ethan thinks he hears a leak. Area is marked with flags and paint

BUD  
 locate the area marked with flags and paint, located by Wed. 7/22/20

ATT  
 ELWD  
 LTC  
 LTRWC  
 WRECC

2007201418

Inventory Item And Description	Quantity Ordered	Quantity Used
2 ppm X 30 days		
Turned off at Corp + Remanded		
Meter, box, and line		
Put Cap on Corp		

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 15982**

Account #  
Name TOOLEY, JOEY W  
Address  
Telephone Job #

Order Date 7/21/2020  
Status MEDIUM  
Scheduled 07/21/20 02:13 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 9434317      ERT/INTERNAL ID# 9434317      READING 325      LOCATOR TAG      READING IN / OUT

Description  
Comment RT, BRK HSE, RT CNR

Requested By lacey tooley      Assigned To MAINTENANCE CREW      Completed By  
Start Date \_\_\_/\_\_\_/\_\_\_      Time \_\_\_:\_\_\_      Completed Date \_\_\_/\_\_\_/\_\_\_      Time \_\_\_:\_\_\_

Make \_\_\_\_\_ Size/Type JOEY Multiplier \_\_\_\_\_  
Notes JS ci 100K. ROAD & MGR KEO  
LONG side leak

Inventory Item And Description	Quantity Ordered	Quantity Used
2 gpm 14 days		

AP 14/67991

Aug 11th Expire  
Aug 8th Dig by

61950542 METRI

ATT  
Atmos  
ELWD  
LTC

OOIT ready

54' new second line

2007211809

7 Nuts  
2 inserts

leaking at Corp

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 15956**

Account # \_\_\_\_\_  
Name MCCORMICK, JUDITH M  
Address \_\_\_\_\_  
Telephone \_\_\_\_\_

Order Date 7/14/2020  
Status MEDIUM  
Scheduled 07/14/20 11:28 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 9135968      ERT/INTERNAL ID# 9135968      READING 1143      LOCATOR TAG \_\_\_\_\_      READING IN / OUT 1280.57.4  
Description \_\_\_\_\_  
Comment LF, HSE OFF RD, LF GR DR AT GA  
Requested By MS MCCORMICK      Assigned To MAINTENANCE CREW      Completed By *EA ST FA*  
Start Date 7/14 Time \_\_\_\_\_      Completed Date 7-24-20 Time \_\_\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes  
*Sounded like a leak marked. call in bhd. Dig it in  
NO flow on the main. No customer call*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Don't know</i>		
<i>4 gpm x 14 days = New Service line 6' per 2 Nuts</i>		

*[Handwritten Signature]*

Signature

East Logan Water District  
WORK ORDER 15988

BELMARIE O

Order Date 7/24/2020  
Status MEDIUM  
Scheduled 07/24/20 09:43 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

JOB #

ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
59495724	428	B14169573	

RT,TRLR,RT GR DR O/FENCE T/LF

by mr walton Assigned To MAINTENANCE CREW Completed By *SJ*  
Time : : Completed Date 7/24/20 Time : :

Size/Type Multiplier  
as leaking on our side of the meter, was fixed 11/05/2018

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Hand dug &amp; fixed leak 7-24-20</i>		
<i>3 GPM</i>		
<i>11 days</i>		

1645

Signature *SJ*

East Logan Water District  
**WORK ORDER 16008**

Account # \_\_\_\_\_ Order Date 7/29/2020  
 Name ORDER WORK Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 07/29/20 10 30 AM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE  
 METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_

WT No Num \_\_\_\_\_  
 Description \_\_\_\_\_  
 Comment \_\_\_\_\_  
 Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By EB  
 Start Date 7/29/20 Time \_\_\_\_\_ Completed Date 7/29/20 Time \_\_\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
 Notes when shutting valve to fix leak on franklin rd. broke valve on Wildcat In

Inventory Item And Description	Quantity Ordered	Quantity Used
Replaced (Valve 2")		
1 coupling		
3 Comp Nuts		
70 gpm = 5 hrs		

Signature ST

East Logan Water District  
**WORK ORDER 16007**

Account # \_\_\_\_\_ Order Date 7/29/2020  
 Name REESE STEPHEN Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 07/29/20 10:29 AM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
 WT 78786041 73607027 2328 B15347985

Description \_\_\_\_\_  
 Comment RT, 25 yds to right of drive  
 Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_  
 Start Date 7/29/20 Time \_\_\_\_\_ Completed Date 7/29/20 Time \_\_\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
 Notes across rd

Inventory Item And Description	Quantity Ordered	Quantity Used
6" main break replaced 84" pipe		
2 knockouts		
400 gpm x 3 1/2 hrs		
Leak found 5:30 AM		
Leak fixed by 12:00 PM		

Signature \_\_\_\_\_



East Logan Water District  
WORK ORDER 16009

Account #         
Name APPLING, PHILIP E  
Address         
Telephone       

*work order*  
Job #       

Order Date 7/29/2020  
Status MEDIUM  
Scheduled 07/29/20 10:32 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 48979863    ERT/INTERNAL ID# 63097825    READING 2037    LOCATOR TAG B14167608    READING IN / OUT       

Description RT, YELLOW HS MYD

Requested By           Assigned To MAINTENANCE CREW    Completed By EB  
Start Date 7/29/20    Time           Completed Date 7/29/20    Time       

Make           Size/Type           Multiplier         
Notes       

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Service line pulled loose from corp 20 gpm - 1 hr</i>		
<i>New Service line 7' New Meter, Setter, Bad + Tap</i>		

*new Meter ID  
22053514*

*old Meter ID  
09266843*

*379*  
*1-48979863-1*  
*09266843-1*

Signature

East Logan Water District  
**WORK ORDER 15969**

Account #		Order Date	7/16/2020
Name	NAGY, CHRIS	Status	MEDIUM
Address		Scheduled	07/15/20 06:06 PM
Telephone		Order Type	CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 52473769	07306173	5849	B14161795	

Description  
Comment RT, WOOD HSE R/CNR  
Requested By Chris Nagy Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW  
Start Date 07/16/20 08:16 AM Completed Date 07/16/20 08:16 AM

Notes  
It was a busted meter bottom  
Crew replaced bottom, leak is fixed  
Ethan said it was the worse meter bottom leak he had seen

Signature \_\_\_\_\_

East Logan Water District  
WORK ORDER 15948

Account #  
Name DeARMOND, SANDRA A  
Address  
Telephone Job #

Order Date 7/10/2020  
Status MEDIUM  
Scheduled 07/10/20 09:06 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 48979839      ERT/INTERNAL ID# 63671858      READING 1033      LOCATOR TAG B14169406      READING IN / OUT 1036

Description  
Comment RT, YELLOW HSE, LF YD

Requested By Sandra      Assigned To MAINTENANCE CREW      Completed By E.H.  
Start Date 7/10/20      Time      Completed Date 7/10/20      Time 11:00

Make      Size/Type      Multiplier

Notes Water coming out of box meter bottom - Fixed by Big E

Inventory Item And Description	Quantity Ordered	Quantity Used

E.H.

Signature \_\_\_\_\_

East Logan Water District  
WORK ORDER 15932

Account # \_\_\_\_\_ Order Date 7/7/2020  
 Name YODER, TIMOTHY I Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 07/07/20 02:12 PM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type LEAK BY FIBER INSTALLATION

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
 WT 83545699 89536811 983 B14166593 99743

Description  
 Comment 1ft of pallet mill, 10ft up to  
 Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By ETHAN ST  
 Start Date 7/7/20 Time \_\_\_\_\_ Completed Date 7/7/20 Time 4:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
 Notes cust called in stated that it has been leaking all day long apparently stephen and ethan are aware and will fix when they are done repairing line they are currently on

Inventory Item And Description	Quantity Ordered	Quantity Used
Replaced 2' pipe 1 shark bite 1 knot		
Need to pull New service line		
Line hit By NCS		
@ 12gpm X 20 min = 2400		

Signature ST

East Logan Water District  
WORK ORDER 15863

Account # \_\_\_\_\_ Order Date 6/23/2020  
Name VICKERS, CHERYL A Status MEDIUM  
Address \_\_\_\_\_ Scheduled 06/23/20 12:33 PM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
WT 42602816 63184003 5391 B14167593 5438659

Description \_\_\_\_\_  
Comment LF BRK HSE, 20' LF DRIVE  
Requested By MR VICKERS Assigned To MAINTENANCE CREW Completed By E.H. ADST

Start Date 1/1/11 Time \_\_\_\_\_ Completed Date 01-14-20 Time 3:00  
7-7-20 3:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes THINKS THERES A WATER LEAK

Inventory Item And Description	Quantity Ordered	Quantity Used
1/2" CPVC pipe		
1/2" CPVC fittings		
2 1/2" CPVC pipe		
Pulled New Service line 40' pipe		
2 Nuts		
2 gpm 30 dys = 86,400		

X Melody Ridge by Friday 6-26

- ATT
- Atmos
- Tx Gas
- ELWA

#2004240881

Signature E.H. ADST

East Logan Water District  
**WORK ORDER 15880**

Account # \_\_\_\_\_ Order Date 6/27/2020  
Name WATKINS, HAROLD RAY Status MEDIUM  
Address \_\_\_\_\_ Scheduled 06/27/20 02:46 PM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 40735717	69468368	7002	B14163637	

Description \_\_\_\_\_  
Comment LF L/LONG GR DR BETWEEN CEDARS  
Requested By George Barrow Assigned To MAINTENANCE CREW Completed By *EH RD*  
Start Date   /  /   Time   :  :   Completed Date   /  /   Time   :  :  

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Ethan checked this Saturday 6/27/20 He believes it to be a leak at corp stop. He will keep an eye on it. On Monday, Korbin and Hunter should go hand dig the corp and try to stop leak. We can pull a new service line later. Will need to do emergency bud please first thing Monday morning.

Inventory Item And Description	Quantity Ordered	Quantity Used
Replaced Nut + 2' pipe		
<del>8 gpm x 14 days = 161,000</del>		
8 gpm x 14 days = 161,000		

most likely Emergency Bud for that address  
marked in paint - front of property - both sides

Have LTC use flags so rain  
doesn't wash away

ELWD  
WREC  
LTC

2006290396

July 1 @ 8:30 AM  
exp. July 10

Signature \_\_\_\_\_

East Logan Water District  
WORK ORDER 15983

Account #		Order Date	7/22/2020
Name	STANLEY TINA M	Status	MEDIUM
Address		Scheduled	07/22/20 08 03 AM
Telephone	-- Job #	Order Type	CHECK FOR LEAK ON OUR SIDE
METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG
WT 9434440	9434440	386	
Description			READING IN / OUT
Comment	RT TRLR M/CIRCLE DR READ 2		386
Requested By	Phil McKinney	Assigned To	MAINTENANCE CREW
Start Date	07/22/20 01 00 PM	Completed By	MAINTENANCE CREW
		Completed Date	07/22/20 01 00 PM

Notes cust stated that the box is filling up pretty good and that water is running down the road customer has a leak on their side of the meter, cust is aware-411-eh

1 brass insert  
 3 rings  
 4 pex  
 hose had pulled loose from setter on  
 our side

Signature

*SM, EH, KH*

East Logan Water District  
**WORK ORDER 15802**

Account #  
Name WERTH, RODNEY  
Address  
Telephone Job #

Order Date 6/1/2020  
Status MEDIUM  
Scheduled 06/01/20 07:49 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 45052673      ERT/INTERNAL ID# 10291101      READING 5888      LOCATOR TAG B14168814      READING IN / OUT 6055

Description  
Comment RT BRK HSE. LF DR. 2ND

Requested By clay bilyeu      Assigned To MAINTENANCE CREW      Completed By ST EH  
Start Date 1/1 Time :      Completed Date 6/1/20 Time 12:53

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes \_\_\_\_\_

Inventory Item And Description	Quantity Ordered	Quantity Used
3' of 1" Sch 40 - <del>⊗</del>		
1- 1" Male Threaded X 1" glue		
1- 1" glue coupling		
18 gpm		

Signature ST EH



East Logan Water District  
**WORK ORDER 15837**

Account #  
Name COURSEY, BOYD  
Address  
Telephone Job #

Order Date 6/9/2020  
Status MEDIUM  
Scheduled 06/09/20 08 14 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 43518908      ERT/INTERNAL ID# 09832370      READING 2944      LOCATOR TAG B14168581      READING IN / OUT 2948

Description  
Comment RT, BRK HSE RT CNR  
Requested By Terry milam      Assigned To MAINTENANCE CREW      Completed By JH  
Start Date 6/11/20      Time :      Completed Date 6/12/20      Time :

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes wet spot in the yard, meter is not turning

erry's number  
IS a leak

Inventory Item And Description	Quantity Ordered	Quantity Used

ELWD      6-12      2006100467  
ATT      7-1 CAP  
Atmos      8:10 AM called in  
LTC - called Clear

~~Replaced~~ Service 6'  
Replaced      1 gpm leak

Signature \_\_\_\_\_



East Logan Water District  
**WORK ORDER 15843**

Account # \_\_\_\_\_  
Name COX, RAYMOND T  
Address \_\_\_\_\_  
Telephone \_\_\_\_\_

Order Date 6/11/2020  
Status MEDIUM  
Scheduled 06/11/20 11:29 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 45221796	71971533	2454	B14167089	<u>Locked</u>

Description \_\_\_\_\_  
Comment LF,WH/HSE,M/YD  
Requested By Susan Stratton Assigned To MAINTENANCE CREW Completed By MO BW STEH  
Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_ Completed Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes marked in blue and flagged, both sides of read  
Pull new service line

Inventory Item And Description	Quantity Ordered	Quantity Used

X Fred Stratton Rd

Pulled new service  
6/12/20 50'

Monday 6-15-20 by 1:30 pm

5 gpm leak

LTC

#200411112

Signature \_\_\_\_\_

East Logan Water District  
WORK ORDER 15816

Account #  
Name FULGHAM, TONYA  
Address  
Telephone

Order Date 6/3/2020  
Status MEDIUM  
Scheduled 06/03/20 10:17 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 48979858  
ERTINTERNAL ID# 6309783  
READING 7664  
LOCATOR TAG B14166495  
READING IN / OUT 7693

Description  
Comment RT L/FULLER RD 2ND MTR

Requested By stephen taylor  
Assigned To MAINTENANCE CREW  
Completed By *HT, BT, ST*  
Start Date   /  /   Time   :  :    
Completed Date 6/18/20 Time 3:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes \_\_\_\_\_

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>5 gpm leak under rd 30 days</i>		
<i>pulled new service line from main across road about 50'. Did not replace from meter to this spot - could not get cable to pass under extensive landscaping about 100' from new line to meter.</i>		
<i>50' per 3/4" - 1 Comp. Nut 2 brass insert 6 crimp rings</i>		

*65 psi at meter*

Signature *ST*

East Logan Water District  
**WORK ORDER 15783**

Account #  
Name KELLY, RAI PH F  
Address  
Telephone Job #

Order Date 5/26/2020  
Status MEDIUM  
Scheduled 05/26/20 08:26 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 23431639 13208843 1918 B14169979 204

Description  
Comment LF, WH HSE, 20' LF DR

Requested By MR KELLY Assigned To MAINTENANCE CREW Completed By  
Start Date   /  /   Time   :   Completed Date 6/3/20 Time 2:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes BETWEEN METER AND THE RD IS WET, AND MUSHY  
*Customer is going to mark area.  
was fixed this time last year*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Road marked</i>		
<i>1/20th of a gallon</i>		

*cross-wildcat LN Both Sides*  
*2005270977*

*ATT ✓  
ELWD  
Atmos   
LTC  
TX Gas ✓*

*EH [Signature]*

87103

East Logan Water District  
WORK ORDER 15848

Account # \_\_\_\_\_ Order Date 6/12/2020  
Name CRAWFORD, FLOSSIE J Status MEDIUM  
Address \_\_\_\_\_ Scheduled 06/12/20 03:25 PM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 84200074	89837137	3	B14167424	5

Description \_\_\_\_\_  
Comment RT WH/HS L/YD T/LF LASHLEY RD  
Requested By Delmar Graber Assigned To MAINTENANCE CREW Completed By *HR*  
Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_:\_\_\_ Completed Date *6/15/20* Time \_\_\_:\_\_\_:\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes Mr. Graber said there is water in ditchline.

Inventory Item And Description	Quantity Ordered	Quantity Used
70' pipe		
2 Comp Nuts		

3-16 5:15 E  
7-3 EXP

2006121419

ELWD  
LTC  
WRECC

2 to 3 gal/min  
1 bolted on 6/12/20

Will put in new  
service

6-17 pulled new  
Service 70'  
Corp 36.89 335'  
OPS 86.73 120

Black pipe

Signature *HR*

East Logan Water District  
**WORK ORDER 15787**

Account # \_\_\_\_\_ Order Date 5/27/2020  
Name JOHNSON, CHARLIE Status MEDIUM  
Address \_\_\_\_\_ Scheduled 05/27/20 09 53 AM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

---

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 22796302 13024794 7768 B14168751

---

Description  
Comment RT BLUE HS R/DR 2ND MTR  
Requested By MR JOHNSON Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW  
Start Date 05/29/20 01 13 PM Completed Date 05/29/20 01 13 PM

Notes CUST SAYS THAT WE REPAIRED LEAK THERE LAST WEEK, AND SEEMS TO NOT HAVE FIXED THE WHOLE PROBLEM, HE SAYS THAT WATER IS STILL STANDING AND LEAKING, PLEASE CHECK OUT 4gpm leak, 7801 repaired, replaced service line-st/bw/hb

*6-4-20 completed*

Signature \_\_\_\_\_





East Logan Water District  
**WORK ORDER 15703**

Account #  
Name PROCTOR, RONNIE L.  
Address  
Telephone Job #

Order Date 5/5/2020  
Status MEDIUM  
Scheduled 05/05/20 12:22 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 83545774	89536886	494	B14169092	<u>SID</u>

Description  
Comment RT, WH TRLR, LF DR  
Requested By Ehtan Assigned To MAINTENANCE CREW Completed By RS BWD EK  
Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_ Completed Date 5/15/20 Time \_\_\_:\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes King side service leak  New Hope Rd

Inventory Item And Description	Quantity Ordered	Quantity Used

*Duplicate*  
*Pulled new service*

*2-3 gpa*

Signature \_\_\_\_\_



East Logan Water District  
**WORK ORDER 15770**

Account #  
Name MORGAN, ALVIN  
Address  
Telephone Job #

Order Date 5/19/2020  
Status MEDIUM  
Scheduled 05/19/20 12:50 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 39340876	71205562	2055	B14169348	2075 / 2077 5-19-20 / 5-21-20
Description				
Comment LF, BRK APT, LF DR 2 METERS				
Requested By Mr. Morgan's worker		Assigned To MAINTENANCE CREW		Completed By HBRWST
Start Date ___/___/___		Time ___:___		Completed Date 5/19/20 Time 4:10

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes He has the cutoff valve in the box turned off, and says water is boiling up in box. Please check for leak.  
(he is replacing or repairing water heater; says the valve did stop the flow into the house)

Inventory Item And Description	Quantity Ordered	Quantity Used
leak at setter on our side		
Pulled New Service Line 4' per. 2 inserts 2 Nuts		
Ashley		

4-19-20

BUD 2005191480

Cross 68/80

texted to S.T.

Blue Flags

5-21-20 5:45

EXP 6-9-20

ATT  
ELWD  
Tex Gas  
LTRW

Signature HBRWST



East Logan Water District  
**WORK ORDER 15757**

Account #  
Name CANLER, AMY B  
Address  
Telephone

Order Date 5/18/2020  
Status MEDIUM  
Scheduled 05/18/20 08:40 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 84200090	89837153	797	B14166268	<u>819</u>

Description  
Comment RT,BRK HSE, LF DR

Requested By Tim Canler Assigned To MAINTENANCE CREW Completed By JBWST  
Start Date 5/18/20 Time 12:00 Completed Date 5/18/2020 Time 12:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes Tim said we have a leak

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>This is a leak.</i>		
<i>Service called in.</i>		
<i>Pulled New Service Line 45'</i>		
<i>2 inserts 2 Nuts</i>		

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 15775**

Account #  
Name HELTSLEY, KEVIN  
Address  
Telephone

Order Date 5/20/2020  
Status MEDIUM  
Scheduled 05/20/20 02:20 PM  
Order Type CHECK METER

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 48979872	09778834	6507	B14169626	6522

Description  
Comment LT, GRAY HSE, RT YD  
Requested By Ethan  
Assigned To MAINTENANCE CREW  
Completed By *RB BERTS*  
Start Date   /  /   Time   :  :    
Completed Date 5/22/20 Time   :  :  

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes Busted meter bottom, and cutoff needs to be changed as its not working

Inventory Item And Description	Quantity Ordered	Quantity Used

*Replaced meter bottom*

East Logan Water District  
**WORK ORDER 15779**

Account #  
Name BALDWIN JERRY  
Address  
Telephone Job #

Order Date 5/21/2020  
Status MEDIUM  
Scheduled 05/21/20 01:52 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 46512388      ERT/INTERNAL ID# 09367758      READING 4358      LOCATOR TAG B14168077      READING IN / OUT No Meter

Description  
Comment LF, TRLR MYD 2ND

Requested By stephen      Assigned To MAINTENANCE CREW      Completed By HOBW EN

Start Date   /  /   Time   :        Completed Date 5/26/20 Time   :  

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes \_\_\_\_\_

Inventory Item And Description	Quantity Ordered	Quantity Used
4' Put in new section pipe		
2 Brass Nipple		
4 Rings		

CROSS Lee of WF Hall

ELWD  
WRELL  
LTC

2005211423

Bulbry @ 1498 Bucksville  
3693540  
- 86.75818







East Logan Water District  
WORK ORDER 15691

Account #  
Name MILES, CHARLES  
Address  
Telephone Job #

Order Date 5/1/2020  
Status MEDIUM  
Scheduled 05/01/20 11:08 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 66684128      ERT/INTERNAL ID# 59596216      READING 4478      LOCATOR TAG B14167039      READING IN / OUT 4989

Description  
Comment LT, PINK HSE, MYD

Requested By mr miles      Assigned To MAINTENANCE CREW      Completed By *HAB BU EH*

Start Date    /    /    Time    :         Completed Date 5/12/20 Time    :   

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes check for leak, 2-3ft on our side of the meter-

*Please pull whole new service line  
Barton & Gary Repaired Sept 2019*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>IS 9 1/2" Road marked.</i>		
<i>New Service 30pm</i>		

*Morgantown Rd  
Both Sides  
white paint*

*May 7 Noon*

*Bud# 2005051058*

*ELWD  
ATT  
BG gass  
LTRW*

*~~Leak Fixed 5/1/20~~  
~~was leaking in~~  
~~cess~~  
~~3 feet in~~  
EH*

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 15738**

Account # \_\_\_\_\_  
Name CLINARD, JONATHAN P  
Address \_\_\_\_\_  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_

Order Date 5/7/2020  
Status MEDIUM  
Scheduled 05/07/20 10:38 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 48431491	63097869	9341	B14167284	9.386

Description  
Comment RT YELLOW D-WIDE L/DR T/LF

Requested By ETHAN Assigned To MAINTENANCE CREW Completed By EH  
Start Date 1/1 Time \_\_\_\_\_ Completed Date 5/11/20 Time 10:30

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes \_\_\_\_\_

Inventory Item And Description	Quantity Ordered	Quantity Used

2005071006  
E1WD  
LTC  
WPECC

New service pulled  
5/18/20  
9386 Reading  
KB, BW, EH, KD, J;

EH

Signature \_\_\_\_\_



East Logan Water District  
**WORK ORDER 15698**

Account # \_\_\_\_\_ Order Date 5/1/2020  
 Name SANDLIN, CLIFFORD W Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 05/04/20 08:58 AM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 30318313	39220313	3891	B14167141	3895

Description \_\_\_\_\_  
 Comment RT WH/HS R/YD 5/8/20  
 Requested By David Mimbs Assigned To MAINTENANCE CREW Completed By SJ BW  
 Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_ Completed Date 5/1/20 Time 1:50

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
 Notes Stephen says it is a service line leaking

*leak at Saffer Mt*

Inventory Item And Description	Quantity Ordered	Quantity Used

corner of Morgantown Rd + Bill Woodward Rd  
white paint

May 7 12:00  
Exp 26

Fixed insert  
79PM 3' pipe

Bud # 2005051047

ELWD  
LTC  
WRECC

Signature *SJ*

East Logan Water District  
**WORK ORDER 15787**

Account # \_\_\_\_\_ Name JOHNSON CHARLIE Address \_\_\_\_\_ Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Date 5/27/2020 Status MEDIUM Scheduled 05/27/20 09:53 AM Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 22796302 INTERNAL ID# 13024794 READING 7768 LOCATOR TAG B14168751 READING IN / OUT 7.801

Description RT BLUE HS R/DR 2ND MTR  
Requested By MR JOHNSON Assigned To MAINTENANCE CREW Completed By ST BW AB  
Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_ Completed Date 5/29/20 Time 10:50

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes CUST SAYS THAT WE REPAIRED LEAK THERE LAST WEEK, AND SEEMS TO NOT HAVE FIXED THE WHOLE PROBLEM. HE SAYS THAT WATER IS STILL STANDING AND LEAKING, PLEASE CHECK OUT

Inventory Item And Description	Quantity Ordered	Quantity Used
New Service line		
2 comp. Nuts		
5 SH pins		
4 gpm		

East Logan Water District  
WORK ORDER 15733

Account # -----  
 Name COOPER, ELIZABETH  
 Address -----  
 Telephone ----- Job # -----  
 Order Date 5/6/2020  
 Status MEDIUM  
 Scheduled 05/06/20 02 38 PM  
 Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 60628213  
 ERT/INTERNAL ID# 63183735  
 READING 4373  
 LOCATOR TAG B14170082  
 READING IN / OUT 0000000 2.5 4373

Description  
 Comment RT, HSE OFF RD, RT GR DR. 2 ME

Requested By ethan hudson  
 Assigned To MAINTENANCE CREW  
 Completed By EH  
 Start Date / / Time : :  
 Completed Date 5/6/20 Time : :

Make ----- Size/Type ----- Multiplier -----  
 Notes meter bottom busted

Inventory Item And Description	Quantity Ordered	Quantity Used
22053545		
2 1/2 GPM LEAK		

Signature EH

East Logan Water District  
WORK ORDER 15358

Account # \_\_\_\_\_ Order Date 1/27/2020  
Name KNUCKLES, TRACY Status MEDIUM  
Address \_\_\_\_\_ Scheduled 01/27/20 08 03 AM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 22201563	09245276	1292	B14652678	

Description \_\_\_\_\_  
Comment RT, GRAY HS R/CNR  
Requested By Tracy Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW  
Start Date 01/25/20 08 05 AM Completed Date 01/27/20 08 05 AM

Notes Service line leaking on our side of meter  
SR repaired on 1/25/20 Replaced where split with 2 ft of pex REading of 1312

Signature \_\_\_\_\_





East Logan Water District  
**WORK ORDER 15412**

Account # \_\_\_\_\_ Order Date 2/13/2020  
Name RUST, BILL R Status MEDIUM  
Address \_\_\_\_\_ Scheduled 02/13/20 02:43 PM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 69361463	63066075	2914	B14162149	

Description

Comment RT BLUE HS R/DR

Requested By ethan Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW

Start Date 03/11/20 08:05 AM Completed Date 03/11/20 08:05 AM

Notes - check for water and see if it's a leak\*\*\*\*\*STEPHEN PLEASE CHECK THIS OUT MONDAY\*\*\*\*\*  
negative for chlorine-st2942

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 15442**

Account #		Order Date	3/2/2020		
Name	DAVIS, DENNIS	Status	HIGH		
Address		Scheduled	03/02/20 08:59 AM		
Telephone	Job #	Order Type	CHECK FOR LEAK ON OUR SIDE		
METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT	
WT 22053584	22053584	7295			
Description					
Comment	LF,WH HSE,FAR LF YD				
Requested By	Dennis	Assigned To	MAINTENANCE CREW	Completed By	MAINTENANCE CREW
Start Date	03/06/20 10:54 AM	Completed Date	03/06/20 10:54 AM		

Notes: Customer is frequently gone, and turns water off when he leaves. Home now, and when he turned the water on, it started gushing out of box. Thinks maybe meter froze. CUSTOMER WANTS WATER TURNED OFF AFTER REPAIRED. CHANGED METER TO KAM, 22053584-7834-BW

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 15474**

Account # \_\_\_\_\_ Order Date 3/9/2020  
Name BEACHY, MATTHEW F Status MEDIUM  
Address \_\_\_\_\_ Scheduled 03/09/20 03 43 PM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

---

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 65798109	58647027	5697	B14167950	

---

Description \_\_\_\_\_  
Comment RT HSE FAR RT YD  
Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW  
Start Date 03/18/20 09 44 AM Completed Date 03/18/20 09 44 AM

Notes CUSTOMER SAYS THAT WATER IS GROWING IN HIS YARD, PLEASE CHECK FOR CHLORINE AND FLORIDE-everything tested negative, no leak of ours

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 15508**

Account #		Order Date	3/11/2020
Name	ORDER, WORK	Status	MEDIUM
Address		Scheduled	03/11/20 02:55 PM
Telephone	Job #	Order Type	CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
--------	------------------	---------	-------------	------------------

WT No Num \_\_\_\_\_

Description \_\_\_\_\_

Comment \_\_\_\_\_

Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW

Start Date 03/18/20 09:42 AM Completed Date 03/18/20 09:42 AM

Notes fiber optic-intersection of Avers/Lashley  
caller phone  
no leak, they had hit customer service line that they repaired the next day

Signature \_\_\_\_\_

East Logan Water District  
WORK ORDER 15520

Account #		Order Date	3/16/2020		
Name	STUTZMAN, EDWARD R	Status	MEDIUM		
Address		Scheduled	03/16/20 09.14 AM		
Telephone	Job #	Order Type	CHECK FOR LEAK ON OUR SIDE		
METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT	
WT 22053588	22053588				
Description					
Comment	RIGHT OF DRIVE 10FT				
Requested By	mr stutzman	Assigned To	MAINTENANCE CREW	Completed By	MAINTENANCE CREW
Start Date	03/16/20 02 38 PM	Completed Date	03/16/20 02 38 PM		

Notes: \_\_\_\_\_ says that the top blew up off the meter and water started shooting out when hooked up to the meter and turned the meter on-please check out  
CHANGED METER OUT PER METER BUSTED- 4, KAM 22053588-ST

Signature \_\_\_\_\_

East Logan Water District  
WORK ORDER 15550

Account #  
Name HOCHSTETLER, VERNON  
Address  
Telephone Job #

Order Date 3/31/2020  
Status MEDIUM  
Scheduled 03/31/20 09 04 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 22053536	22053536	2786		

Description

Comment RT D-WIDE M/YARD

Requested By mr hochsteller Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW

Start Date 03/31/20 04 30 PM Completed Date 04/04/20 04 30 PM

Notes says he's been without water since around 6 this morning

Stephen and Ethan pulled a new service line under road and replaced the meter  
70' pex 3/4"  
2 compression nuts  
new box and lid

Signature \_\_\_\_\_

East Logan Water District  
WORK ORDER 15582

Account #  
Name JOHNSON, WAYNE  
Address  
Telephone

Order Date 4/6/2020  
Status MEDIUM  
Scheduled 04/06/20 02 52 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 22053533	22053533	8559		

Description  
Comment RT BRK HSE LF DR AT FENCE

Requested By  
Assigned To MAINTENANCE CREW  
Completed By MAINTENANCE CREW

Start Date 04/06/20 08 06 AM

Completed Date 04/06/20 08 06 AM

Notes meter botlom busted changed out with kam 22053533-8565-eh

Signature \_\_\_\_\_



East Logan Water District  
WORK ORDER 15649

Account #  
Name GLOSTER, DANA L  
Address  
Telephone

Order Date 4/20/2020  
Status MEDIUM  
Scheduled 04/20/20 07:50 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 35507373	63524772	2133	B15089779	

Description  
Comment RT HSE RT CNR

Requested By ethan Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW

Start Date 04/24/20 08:14 AM Completed Date 04/24/20 08:14 AM

Notes not a leak, negative for floride-eh

East Logan Water District  
**WORK ORDER 15746**

Account # \_\_\_\_\_ Order Date 5/11/2020  
Name STEARSMAN, RONNIE N Status MEDIUM  
Address \_\_\_\_\_ Scheduled 05/11/20 09:29 AM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 37668928	63097875	3070	B14169916	

Description \_\_\_\_\_  
Comment RT, WH 2 STORY HSE, 50' LF GR  
Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW  
Start Date 05/08/20 09 34 AM Completed Date 05/08/20 09 34 AM

Notes leak at corp, blue pex pipe, replaced 3ft section-2/3 gpm leak

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 15752**

Account #		Order Date	5/13/2020
Name	ROBISON, CURTIS	Status	MEDIUM
Address		Scheduled	05/13/20 08.09 AM
Telephone	Job #	Order Type	CHECK FOR LEAK ON OUR SIDE
METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG
WT 48431563	63097932	2504	B15260738
Description			READING IN / OUT
Comment	LF, WH HSE. LF near tele phone		
Requested By	Linda	Assigned To	MAINTENANCE CREW
Start Date	05/13/20 09 17 AM	Completed By	MAINTENANCE CREW
		Completed Date	05/13/20 09 17 AM

Notes Customer says meter is turning, he has turned off his shut off valve, and meter is still turning

EH says no sign of leak, no water in box or at the meter Meter is turning The leak must be between box and customer's shutoff valve which is about 50' from meter Curtis is having DJ Arnold come

Signature \_\_\_\_\_



East Logan Water District  
WORK ORDER 15786

Account #		Order Date	5/27/2020
Name	BILBREY TP, JAMES E	Status	MEDIUM
Address		Scheduled	05/27/20 07 58 AM
Telephone	Job #	Order Type	CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
--------	------------------	---------	-------------	------------------

WT

Description

Comment LF,RT/LEE RD READ 2

Requested By stephen Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW

Start Date 05/27/20 08 05 AM Completed Date 05/27/20 08 05 AM

Notes no meter in the box, 4' put in new section of pex, 2 brass nipples, 4 rings, -hb/bw/eh

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 15841**

Account # \_\_\_\_\_ Order Date 6/11/2020  
Name WILKINS, ERNIE Status MEDIUM  
Address \_\_\_\_\_ Scheduled 06/11/20 09:18 AM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

---

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 22053589 22053589 7336

---

Description  
Comment LT, TAN HSE, RT/YD, CNR 79  
Requested By Ernie Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW  
Start Date 06/11/20 02:42 PM Completed Date 06/11/20 02:42 PM

Notes Customer states meter is not turning but he has no water  
CHANGED METER TO KAM 22053589-EH-PRESENT READING ON NEW METER 632-7411 ON OLD  
METER-EH

Signature \_\_\_\_\_

East Logan Water District  
WORK ORDER 15925

Account # \_\_\_\_\_ Order Date 7/4/2020  
Name OVERHOLT, ARLAND RAY Status MEDIUM  
Address \_\_\_\_\_ Scheduled 07/04/20 08.42 AM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 84200091	89837154	3110	B14168526	

Description

Comment RT.WH/HSE L/DR

Requested By Arland Overholt Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW

Start Date 07/04/20 12 25 PM Completed Date 07/04/20 12 25 PM

Notes Arland called to say he had hit the main line on Bucksville Rd, around 1300 Emergency Bud  
Stephen and Korbin repaired the main

Signature \_\_\_\_\_

East Logan Water District  
WORK ORDER 15951

Account #		Order Date	7/13/2020
Name	SHAVER, DAVID JR	Status	MEDIUM
Address		Scheduled	07/13/20 02:05 PM
Telephone	Job #	Order Type	CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 51170303	00052159		LF R/GR LANE	

Description

Comment LF R/GR LANE

Requested By Ethan/Korbin Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW

Start Date 07/23/20 11:40 AM Completed Date 07/23/20 11:40 AM

Notes

Ethan hears leak  
2007201418  
PUT CAP ON CORP. 2GPMx30DAYS  
PULLED UP METER-EH/ST

Signature \_\_\_\_\_



East Logan Water District  
**WORK ORDER 15988**

Account # .....  
Name WALTON, BELMARIE O  
Address ..  
Telephone ..... Job # .....  
Order Date 7/24/2020  
Status MEDIUM  
Scheduled 07/24/20 09 43 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 25976047	59495724	428	B14169573	

Description  
Comment RT,TRLR,RT GR DR O/FENCE T/LF  
Requested By mr wallon Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW  
Start Date 08/14/20 03 27 PM Completed Date 08/14/20 03 27 PM

Notes leaking on our side of the meter. was fixed 11/05/2018  
3gpmX21 days. eh, st, kh

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 15989**

Account # \_\_\_\_\_ Order Date 7/24/2020  
 Name HUGHES, SANDRA A Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 07/24/20 10.01 AM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 000065798081	61950542	17	B14167991	

Description \_\_\_\_\_  
 Comment LF, BRK HSE, LF DR  
 Requested By lacey tooley Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_  
 Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_ Completed Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
 Notes replaced 54' service line, 1gpm X 14 days, leaking at the corp-kh,eh,st

Inventory Item And Description	Quantity Ordered	Quantity Used

East Logan Water District  
WORK ORDER 16031

Account #				Order Date	8/3/2020
Name	none, none			Status	MEDIUM
Address	000 000			Scheduled	07/29/20 01:52 PM
Telephone		Job #		Order Type	CHECK FOR LEAK ON OUR SIDE
METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT	
WT 22053514	09266843		RT,SAME TRLR R/		
Description					
Comment	RT,SAME TRLR R/DR 3RD MTR				
Requested By		Assigned To	MAINTENANCE CREW	Completed By	MAINTENANCE CREW
Start Date	08/03/20 01 53 PM			Completed Date	08/03/20 01 53 PM

Notes service line pulled loose from corp. 20gpmX1hr, new service line, 7'. new meter, setter, box and top replaced meter with kam. 22053514-st

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 16104**

Account #		Order Date	8/24/2020		
Name	HALL, MITCH	Status	MEDIUM		
Address		Scheduled	08/24/20 01 16 PM		
Telephone	Job #	Order Type	CHECK FOR LEAK ON OUR SIDE		
METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT	
WT 22585405	63524803	4736	B14162017		
Description					
Comment	LF WH/HS L/CNR T/A T/RT				
Requested By	Mitch	Assigned To	MAINTENANCE CREW	Completed By	MAINTENANCE CREW
Start Date	08/26/20 07 58 AM	Completed Date	08/26/20 07 58 AM		

Notes Mr. Hall says it is staying wet between the meter and the main for the last 2 months. Please check for a leak if you need to call him.  
pulled a new service line. 2gpmX30days. 2 nuts-4759

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 15368**

Account #  
Name SMITH, KRISTA S  
Address  
Telephone Job #

Order Date 1/30/2020  
Status MEDIUM  
Scheduled 01/30/20 02:33 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 52473833	61950532	8597	B14172330	

Description  
Comment LF WOOD HS L/YD 2 MTRS

Requested By Ethan Hudson Assigned To MAINTENANCE CREW Completed By

Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_ Completed Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Rectangular black meter box. Leaking in box.  
BUD - 2001301234  
LTC  
WRECC

Inventory Item And Description	Quantity Ordered	Quantity Used
Replace gutter mat & section line 3 ft.		
Completed 1/31/20 (Signature)		

LTC will mark by 8:30 in Friday morning

Signature \_\_\_\_\_



East Logan Water District  
**WORK ORDER 15623**

Account # \_\_\_\_\_ Order Date 4/13/2020  
Name SCHWILL, RACHEL L Status MEDIUM  
Address \_\_\_\_\_ Scheduled 04/13/20 04:59 PM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
WT 68654618 73543857 3368 B15197421

Description \_\_\_\_\_  
Comment RT R/CNR THORNTON RD  
Requested By Brandon Gates Assigned To MAINTENANCE CREW Completed By *ST*  
Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_ Completed Date *4/13/20* Time \_\_\_\_:\_\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes ON the right before you get to Thornton Rd. Brandon noticed water on side of road that would be unusual even with the rain we had. Please see if this is a leak.

*I don't have anything saying "NO leak" or anything saying "leak, so please check out. Thanks"*

Inventory Item And Description	Quantity Ordered	Quantity Used

*Not a leak no chlorine Dried up*

**REPRINT**

Signature *ST*





East Logan Water District  
**WORK ORDER 15537**

Account # \_\_\_\_\_ Order Date 3/24/2020  
Name BROWN, BEN Status MEDIUM  
Address \_\_\_\_\_ Scheduled 03/24/20 03:02 PM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
WT 29582236 61287395 1056 B14169910 1126

Description \_\_\_\_\_  
Comment RT, WH 2 STORY HSE, RT YD AT F

Requested By ben Assigned To MAINTENANCE CREW Completed By ST EHHB KD

Start Date 3/24/20 Time \_\_\_\_\_ Completed Date 3/24/20 Time (1:30)

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes meter is bubbling water in meter box

Inventory Item And Description	Quantity Ordered	Quantity Used
2 cone nuts 2 inserts 6' pex		
<b>BUD</b> Replaced entire Service Tube (Black pipe) with pex 4 hrs labor hit a natural spring hard to keep water pumped away		
LOOKS like leak at the setter		

Contractor #37105 3-24-2020  
LTC  
ATT  
TX Gas  
Electric  
2003241608

Signature ST EHHB KD

East Logan Water District  
**WORK ORDER 15324**

Account # \_\_\_\_\_ Name BEACHY, KEITH L Order Date 1/8/2020  
Address \_\_\_\_\_ Status MEDIUM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Scheduled 01/08/20 12:38 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
WT 41110201 08885378 2085 B14169489

Description \_\_\_\_\_  
Comment LF, OLD HSE, RT YD, 2ND  
Requested By Groff Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_  
Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_ Completed Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes BUD # 2001081480  
1/10/2020 Exp 1/29/2020  
ATT  
LTC  
LTRWD  
TX Gas  
WRECC

Inventory Item And Description	Quantity Ordered	Quantity Used
Section Saw 1 AM 3 ft. + Crimped		

*Completed  
1/10/20  
(DR)*

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 15341**

Account #  
Name ROBERSON, MARY  
Address  
Telephone

Order Date 1/15/2020  
Status MEDIUM  
Scheduled 01/15/20 10:39 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
WT 22053603 22053603 9

Description

Comment RT, BRK L/DR

Requested By customer Assigned To MAINTENANCE CREW Completed By  
Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_ Completed Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Appears to be a leak there. Meter has been changed and show no additional usage to indicate on her side

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Repaired serv. line leak</i>		

*Completed 1/27/20*

*Location  
by Jan 17 @ 10:30 am  
front of property  
ELWD  
LTC  
2001150937*

East Logan Water District  
**WORK ORDER 15377**

Account # \_\_\_\_\_  
Name WILSON, TERRY & JENNIFER  
Address \_\_\_\_\_  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_

Order Date 2/4/2020  
Status MEDIUM  
Scheduled 02/04/20 03:06 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 47418246	63183996	6880	B14169545	

Description  
Comment LF, WH HSE, RT YD

Requested By Stephen Taylor Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_

Start Date 2/1/20 Time 1:00 Completed Date 2/1/20 Time 2:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Stephen sees leak in box close to setter.

BUD 2002041306

X Elmwood

ATT *CLR*

LTRWC

LTC

WRECC

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Leak where line goes into setter</i>		
<i>Replaced cement used 3' pipe</i>		
<i>insert a fiberglass pipe</i>		

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 15414**

Account # \_\_\_\_\_  
Name HART RAY  
Address \_\_\_\_\_  
Telephone \_\_\_\_\_

Order Date 2/17/2020  
Status MEDIUM  
Scheduled 02/17/20 09:13 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 52473759      ERT/INTERNAL ID# 07330248      READING 1001      LOCATOR TAG B14169785      READING IN / OUT \_\_\_\_\_

Description \_\_\_\_\_  
Comment LF, WH HSE, M/YD

Requested By ray hart      Assigned To MAINTENANCE CREW      Completed By BW EH  
Start Date 1/1/ Time \_\_\_\_\_      Completed Date 2/19/20 Time 3:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes \_\_\_\_\_

Inventory Item And Description	Quantity Ordered	Quantity Used
1 Bolt		
4 BPM		

SAM 2/20  
exp. March 9

Both sides of Rd. ✓

Att, Atmos, ELWD, LTC, Texas Gas.

200 217 0686

Signature BW EH

East Logan Water District  
**WORK ORDER 15378**

Account # \_\_\_\_\_ Name BILYEU, DAKODA C Order Date 2/3/2020  
 Address \_\_\_\_\_ Status MEDIUM  
 Telephone \_\_\_\_\_ b# \_\_\_\_\_ Scheduled 02/03/20 08:38 AM  
 Order Type CHECK FOR LEAK ON OUR SIDE

METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
 WT 9135930 9135930 235

Description \_\_\_\_\_  
 Comment RT, BRK HSE, RT DR  
 Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By *ST EH*  
 Start Date   /  /   Time   :  :   Completed Date   /  /   Time   :  :  

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
 Notes \_\_\_\_\_

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>3/4" cone nut</i>		
<i>3/4" 2' pipe</i>		
<i>3/4" 1 insert</i>		
<i>3/4" nipple</i>		
<i>3/4" 2 crimp rings</i>		
<i>Repaired leak nut to bond</i>		

LTC ~~over~~ Marked

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 15349**

Account # \_\_\_\_\_ Order Date 1/21/2020  
 Name WHITE, LONNIE Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 01/21/20 01:37 PM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
 WT 37668904 09443850 9422 B14169853 \_\_\_\_\_

Description \_\_\_\_\_  
 Comment LF, OLD HSE, RT YD 3RD  
 Requested By Nikki Vitale Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_  
 Start Date 1/21/20 Time 1:37 Completed Date \_\_\_\_\_ Time \_\_\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
 Notes \*\*leaking same spot, we have got to get this incased!!!!!!!!!!!!!!!!!!!!!!!!!!!!\*\*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Cased &amp; sectioned lines, filled</i>		
<i>w/ 2 Tens.</i>		
<i>40' Pex</i>		
<i>Completed</i>		
<i>1/27/20</i>		

East Logan Water District  
**WORK ORDER 15343**

Account # \_\_\_\_\_ Order Date 1/16/2020  
Name PHILLIPS, MONTANA C Status MEDIUM  
Address \_\_\_\_\_ Scheduled 01/16/20 09:19 AM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
WT 81271633 74600705 966 B14969515

Description \_\_\_\_\_  
Comment LFT WHITE TRLR MID YD  
Requested By James Burns Assigned To MAINTENANCE CREW Completed By *EH*  
Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_\_ Completed Date *1/17/20* Time *1:00*

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Says water is coming up in several places on other side of mailbox

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Leak fixed</i>		
<i>2 brass nipples 3/4 inch</i>		
<i>4 brass flings 3/4 inch</i>		
<i>2 feet of pipe</i>		

*1-16-20*  
*1-21-20*  
*2-6-20 exp*  
  
*ELWD*  
*LTC*  
*WRELL*

*2001160769*

Signature *[Handwritten Signature]*



East Logan Water District  
**WORK ORDER 15324**

Account # \_\_\_\_\_  
Name BEACHY, KEITH I  
Address \_\_\_\_\_  
Telephone \_\_\_\_\_

Order Date 1/8/2020  
Status MEDIUM  
Scheduled 01/08/20 12:38 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 41110201	08885378	2085	B14169489	

Description  
Comment LF, OLD HSE, RT YD, 2ND

Requested By Groff Assigned To MAINTENANCE CREW Completed By *E.H.*  
Start Date 1/1/20 Time \_\_\_\_\_ Completed Date 1/9/20 Time 2:15

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes \_\_\_\_\_

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>This is a leak.</i>		
<i>It has been fixed before in the same spot.</i>		
<i>Road is marked.</i>		
<i><del>RT trailer</del> RT trailer white/yellow RT of YD</i>		

*Completed 1/10/20*  
*(DH)*

*E.H.*

East Logan Water District  
**WORK ORDER 16207**

Account #		Order Date	9/18/2020
Name	GANT THOMAS W	Status	HIGH
Address		Scheduled	09/17/20 06 58 PM
Telephone	Job #	Order Type	CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 45221828	10288411	3216	B14170058	

**Description**

Comment RT, HSE OFF RD RT GR DR

Requested By Mrs. Gant Assigned To MAINTENANCE CREW Completed By MAINTENANCE CREW

Start Date 09/17/20 07 00 PM Completed Date 09/17/20 07 30 PM

**Notes**

Mrs. Gant called right at dark to say she had no water. Stephen responded and found the fiber optic crew had hit her water line. No one told the customer, so she had called us. Fiber crew had moved on down the road, and were gathering parts to fix her line.

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 16113**

Account #  
Name COURSEY, BRENDA G  
Address  
Telephone Job #

Order Date 8/27/2020  
Status MEDIUM  
Scheduled 08/27/20 03:29 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 9135896      ERT/INTERNAL ID# 9135896      READING 542      LOCATOR TAG READING IN/OUT

Description  
Comment RT OF DRIVE NEXT TO POLE

Requested By ethan      Assigned To MAINTENANCE CREW      Completed By SY  
Start Date 8/27/20 Time 3:29      Completed Date 8/27/20 Time 3:29

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes \_\_\_\_\_

Inventory Item And Description	Quantity Ordered	Quantity Used
No sign of a leak -		

Signature SY

East Logan Water District  
WORK ORDER 15581

Account #  
Name HALEY PHILLIP B  
Address  
Telephone

Order Date 4/6/2020  
Status MEDIUM  
Scheduled 04/06/20 12:13 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 00000002794w ERT/INTERNAL ID# 64887908 READING 5557 LOCATOR TAG B14168869 READING IN / OUT 5564

Description

Comment RT TRLR L/CNR

Requested By Christina Blake

Assigned To MAINTENANCE CREW

Completed By EH ED

Start Date 1/1 Time :

Completed Date 4/17/20 Time 11:30 AM

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes wet around meter and ditch

Inventory Item And Description	Quantity Ordered	Quantity Used
1 - Bolt		
10 gal Min		

Cross  
Camber Rd

Leak

2004062378

9:39 PM

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 15500**

Account # \_\_\_\_\_ Order Date 3/10/2020  
Name JENKINS, PATRICIA G Status MEDIUM  
Address \_\_\_\_\_ Scheduled 03/10/20 10:58 AM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 43431498	12098876	2186	B14167859	2375

Description \_\_\_\_\_  
Comment LF, BRK-WOOD HS R/DR  
Requested By stephen Assigned To MAINTENANCE CREW Completed By *H.B. STEIN, ET AL*  
Start Date   /  /   Time   :  :   Completed Date   /  /   Time   :  :  

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier *1*  
Notes leak in box, regulator is leaking-contractors box-st

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Repland Regulator</i>		
<i>Small leak in regulator</i>		
<i>&lt; .5 gal/min</i>		

CONF # ~~000000~~  
2003110238

LTC

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 15511**


Account # \_\_\_\_\_ Order Date 3/12/2020  
Name WOODALL, JIMMY Status MEDIUM  
Address R.O. Scheduled 03/12/20 11:37 AM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 000019569162 ERT/INTERNAL ID# 55166361 READING 5108 LOCATOR TAG B14168053  
READING IN / OUT ~~5103~~ ~~5187~~

Description \_\_\_\_\_  
Comment LF STONE HS L/DR 2 MTRS  
Requested By Jimmy Assigned To MAINTENANCE CREW Completed By *[Signature]*  
Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_ Completed Date 3/12/2020 Time 3:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Is meter bottom busted or any of our connections leaking? He's had high bill, and says box is full of water. Just see if it is leaking and if it is on us by some chance

Inventory Item And Description	Quantity Ordered	Quantity Used
Regulator IS leaking		
Down up Damaged but replaced regulator and Meterbox		
		

u

To do list

- Needs new Box
- Needs new Regulator

*EH*

Signature \_\_\_\_\_

East Logan Water District  
WORK ORDER 15472

Account # \_\_\_\_\_ Order Date 3/9/2020  
Name CLINE DANNY A Status MEDIUM  
Address \_\_\_\_\_ Scheduled 03/09/20 12:15 PM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
WT 50055721 10163888 2688 B14168010 2703

Description \_\_\_\_\_  
Comment RT BRK HSE.M/YD  
Requested By MS CLINE Assigned To MAINTENANCE CREW Completed By *ST BU AB*  
Start Date   /  /   Time   :   Completed Date   /  /   Time   :  

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes BETWEEN THE ROAD AND THE METER-


*Small crack small service leak*

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Small crack in service line</i>		
<i>Repaired with 1 bolt</i>		

*CONF# 2003110232*

*LTC  
WRECC*

*Start Mar 13 - 900  
Exp Apr 1 -*

Signature 

East Logan Water District  
**WORK ORDER 16032**

Account # \_\_\_\_\_ Order Date 8/3/2020  
Name CRAWLEY, DIANE Status MEDIUM  
Address \_\_\_\_\_ Scheduled 08/03/20 02:37 PM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
WT 40966677 69468370 4155 B14167427 415749.1

Description \_\_\_\_\_  
Comment LF, WOOD SIDED HSE, MDDL YD  
Requested By mower man Assigned To MAINTENANCE CREW Completed By ST  
Start Date 8/3/20 Time \_\_\_\_\_ Completed Date 8/3/20 Time 3:06

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes Guy who mows Diane's yard said water coming from around meter box.

Inventory Item And Description	Quantity Ordered	Quantity Used
<del>CRACK SEAL</del>		
<del>CRACK SEAL</del>		
<del>CRACK SEAL</del>		
Leak on customer side Meter stops when turned off		

1700 month  
200 since Sat.

547-C1A7

Signature ST



East Logan Water District  
**WORK ORDER 15860**

Account #  
Name CHANDLERS METHODIST CHURCH  
Address  
Telephone Job #

Order Date 6/22/2020  
Status MEDIUM  
Scheduled 06/22/20 08:50 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 34116540	10403335	5755	B14167718	

Description

Comment RT R/2ND DR

Requested By EH/KD

Assigned To MAINTENANCE CREW

Completed By

Start Date \_\_\_/\_\_\_/\_\_\_ Time :\_\_\_

Completed Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Looks like meter could be backtapped according to Ethan. Leak is not causing meter to turn

Inventory Item And Description	Quantity Ordered	Quantity Used
Could Never get a positive chlorine or fluoride		

X Turner Rd  
both sides marked

Reading on 6-22 - 5757

checked by June 24 11 am

ELWD  
LTC  
WRELL

# 2006220862

Signature \_\_\_\_\_





East Logan Water District  
WORK ORDER 16005

Account # \_\_\_\_\_ Name MCMURRAY, DOUGLAS Address \_\_\_\_\_ Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Date 7/29/2020 Status MEDIUM Scheduled 07/29/20 08:11 AM Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 45221777 ERT/INTERNAL ID# 63097853 READING 5186 LOCATOR TAG B14170036 READING IN / OUT \_\_\_\_\_

Description \_\_\_\_\_ Comment LF, GRAY HSE, RT YD

Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_ Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_ Completed Date 7/29/2020 Time 11:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_ Notes check for leak, check regulator, reduced pressure for 24 hours

Inventory Item And Description	Quantity Ordered	Quantity Used

*Replace Regulator, around 70 PSI*

*Had no reader  
this is  
top of meter  
reading  
522825.6*

*270-790-8509  
C. H. H. H.*

*Eric Parker*

Signature

East Logan Water District  
**WORK ORDER 15983**

Account # \_\_\_\_\_ Order Date 7/22/2020  
 Name STANLEY, TINA M Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 07/22/20 08 03 AM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
 WT 9434440 9434440 386 000041130

Description \_\_\_\_\_  
 Comment RT TRLR M/CIRCLE DR READ 2  
 Requested By Phil McKinney Assigned To MAINTENANCE CREW Completed By EH  
 Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_ Completed Date 7/22/20 Time 10:21

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes cust stated that the box is filling up pretty good and that water is running down the road  
 customer had a leak.

Inventory Item And Description	Quantity Ordered	Quantity Used

EH

Signature \_\_\_\_\_







East Logan Water District  
**WORK ORDER 15619**

Account # \_\_\_\_\_ Order Date 4/10/2020  
 Name LONG, TIMOTHY E Status MEDIUM  
 Address \_\_\_\_\_ 997 Scheduled 04/10/20 08 40 AM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 45000751	09106733	2992	B14167496	3023


Description \_\_\_\_\_  
 Comment LF, TAN TRLR, 15' LF DR  
 Requested By samantha long (homeowner) Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_  
 Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_ Completed Date 4/10/20 Time 9:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes walking up hill toward this address on the left side of the road, there is water puddling, fiber crews were out there 3-4 weeks ago, please check to see if can find water puddling, check for chlorine and all  
 Called in by Samantha

Inventory Item And Description	Quantity Ordered	Quantity Used

*Fluoride Negative*

Signature 



East Logan Water District  
**WORK ORDER 15624**

Account # \_\_\_\_\_ Order Date 4/14/2020  
 Name NASH, QUENTIN A Status MEDIUM  
 Address \_\_\_\_\_ 44 Scheduled 04/14/20 08:31 AM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE  
 METER# ERT/INTERNAL ID# READING LOCATOR TAG READING IN / OUT  
 WT 35691864 09456731 9009 B14167266 9021  
 Description \_\_\_\_\_  
 Comment RT,BRK/DUP LF DR,2ND METER  
 Requested By Ethan Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_  
 Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_ Completed Date 4/14/20 Time 9:00

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
 Notes Ethan found a leak at the meter for one of the duplexes

Inventory Item And Description	Quantity Ordered	Quantity Used

East Logan Water District  
**WORK ORDER 15570**

Account # \_\_\_\_\_ Order Date 4/3/2020  
 Name ROGERS, CHAD E Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 03/28/20 02:00 PM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
 WT 51780765 09204416 1005 B14652638 1005

Description \_\_\_\_\_  
 Comment RT, LT, GRAVEL RD, 2ND METER

Requested By neighbor Assigned To MAINTENANCE CREW Completed By *ST*

Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_ Completed Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes called to say water was running down ditchline and meter was overflowing in yard  
 Stephen checked, turned off meter, notified Chad leak Meter is to stay off until leak is fixed

Inventory Item And Description	Quantity Ordered	Quantity Used

Signature *ST*

East Logan Water District  
**WORK ORDER 15513**

Account # \_\_\_\_\_ Order Date 3/12/2020  
 Name POOLE, THOMAS E Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 03/12/20 02:11 PM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
 WT 67242277 60912210 5350 B14167345 S415

Description \_\_\_\_\_  
 Comment RT GRAY HS LYD READ 2

Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_  
 Start Date 3/16/20 Time \_\_\_\_\_ Completed Date 3/16/20 Time \_\_\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
 Notes \_\_\_\_\_

Inventory Item And Description	Quantity Ordered	Quantity Used
15 ft on customer side there is a leak		

Signature MB + BW

East Logan Water District  
**WORK ORDER 15533**

Account # \_\_\_\_\_ Order Date 3/23/2020  
Name COLEMAN, SHANNA K Status MEDIUM  
Address \_\_\_\_\_ Scheduled 03/23/20 08:10 AM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
WT 50515018 09022352 8809 B14169309 886.2

Description \_\_\_\_\_  
Comment LF.BRK HSE OFF RD,RT GR DR

Requested By customer Assigned To MAINTENANCE CREW Completed By ST  
Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_ Completed Date 3/23/20 Time 1:54

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes says that the meter box is filling with water.

Inventory Item And Description	Quantity Ordered	Quantity Used
There was water in box but tested Negative for Chlorine		

Signature ST

East Logan Water District  
**WORK ORDER 15455**

Account #  
Name WIX LOGGING  
Address  
Telephone

Order Date 3/5/2020  
Status MEDIUM  
Scheduled 03/05/20 01:46 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 34116531      ERT/INTERNAL ID# 63524755      READING 8136      LOCATOR TAG B14169703      READING IN / OUT

Description  
Comment RT,LUMBER YD,LF CNR OFFICE BLD

Requested By Linda      Assigned To MAINTENANCE CREW      Completed By

Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_:\_\_\_      Completed Date 3-15-20 Time 3:45 PM

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes Leak is registering through the meter See if it could possibly be ours, ie busted meter bottom??

Inventory Item And Description	Quantity Ordered	Quantity Used
<i>Leak on Cust Side</i>		

Signature \_\_\_\_\_

East Logan Water District  
**WORK ORDER 15471**

Account # \_\_\_\_\_ Order Date 3/9/2020  
 Name CRAWFORD, DARRELL F Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 03/09/20 12:03 PM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
 WT 22951800 59536109 5147 B14166383

Description \_\_\_\_\_  
 Comment LF, HSE OFF RD, LF DR  
 Requested By MR CRAWFORD Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_  
 Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_ Completed Date 3/9/20 Time 1:50

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
 Notes JUST HAD A DELIVERY OF WINE DELIVERED AND THE LARGE TRUCK RAN OVER THE SHUT OFF VALVE/METER

Inventory Item And Description	Quantity Ordered	Quantity Used
NO LEAK		

Signature EH

East Logan Water District  
**WORK ORDER 15468**

Account # \_\_\_\_\_  
Name GIDCUMB RICKY  
Address \_\_\_\_\_  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_

Order Date 3/9/2020  
Status MEDIUM  
Scheduled 03/09/20 11:18 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 38168066      ERT/INTERNAL ID# 09890932      READING 8590      LOCATOR TAG B14167809      READING IN / OUT \_\_\_\_\_

Description  
Comment LF, BRK HSE, LF CNR

Requested By VENITA HALL      Assigned To MAINTENANCE CREW      Completed By \_\_\_\_\_  
Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_:\_\_\_\_      Completed Date 3/9/2020 Time \_\_\_\_:\_\_\_\_:\_\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes OPPOSITE SIDE OF ROAD THEN PARSONAGE/NURSURY-BETWEEN OLD SCHOOL AND NURSURY, SAYS THERE'S A STRIP OF WATER, AND DRY ON BOTH SIDES AROUND IT PLEASE CHECK OUT

Inventory Item And Description	Quantity Ordered	Quantity Used
might be any thing		

Signature \_\_\_\_\_





East Logan Water District  
**WORK ORDER 15331**

Account # \_\_\_\_\_ Order Date 1/10/2020  
Name THOMAS, GARY D Status MEDIUM  
Address \_\_\_\_\_ Scheduled 01/10/20 02:50 PM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 63869448	56501957	8805	B14169611	50202

Description \_\_\_\_\_  
Comment LF,HSE OFF RD, RT DR O/FENCE

Requested By Gary Thomas Assigned To MAINTENANCE CREW Completed By \_\_\_\_\_  
Start Date \_\_\_\_/\_\_\_\_/\_\_\_\_ Time \_\_\_\_:\_\_\_\_ Completed Date 1/12/20 Time \_\_\_\_:\_\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes walk North from his meter to fenceline and hay stacks. Keep walking north about halfway across field, down by road you can see the water and prob tire track where he ran through it

Inventory Item And Description	Quantity Ordered	Quantity Used
Team off out camp		
1/10/20 Mr Thomas Meter		
Dukes Meter - No Address		

1/10/20  
360  
172

Signature \_\_\_\_\_

East Logan Water District  
WORK ORDER 15332

Account # \_\_\_\_\_  
Name FERGUSON, CONNOR M  
Address \_\_\_\_\_  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_  
Order Date 1/13/2020  
Status MEDIUM  
Scheduled 01/13/20 09:06 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 51170365  
ERT/INTERNAL ID# 09755540  
READING 1096  
LOCATOR TAG B14169804  
READING IN / OUT 1113

Description \_\_\_\_\_  
Comment LFT, GRAY/DBL/WIDE R/1ST/DR

Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW  
Completed By E F I  
Start Date 1/13/20 Time \_\_\_\_\_  
Completed Date 1/13/20 Time 3:45

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes cust said that the meter box is full of water, please check ou

Inventory Item And Description	Quantity Ordered	Quantity Used
<del>1</del> Qty as a burst		
No leak		

Signature 



East Logan Water District  
WORK ORDER 15248

Account #  
Name MAST, MAHLON H  
Address  
Telephone

Order Date 1/2/2020  
Status MEDIUM  
Scheduled 01/02/20 11:37 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATION TAG	READING IN / OUT
WT 9434367	9434367	444		

Description  
Comment RT TRLR W/ BRK PORCH, LF DR T/

Requested By Mrs Mast Assigned To MAINTENANCE CREW Completed By  
Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_ Completed Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes Appears to be leaking inside box. she mentioned around the cutoff valve? But said it was inside the box.

Inventory Item And Description	Quantity Ordered	Quantity Used
<del>1/2 2020</del>		
NO leaks		
1/2/20 (Signature)		



East Logan Water District  
WORK ORDER 16202

Account #  
Name WHEELER, KIRK T  
Address  
Telephone

Order Date 9/17/2020  
Status MEDIUM  
Scheduled 09/17/20 10:43 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 81271632      ERT/INTERNAL ID# (74600704)      READING 2370      LOCATOR TAG (B14169999)      READING IN / OUT 2.116

Description  
Comment LT, TRLR, RT/YD

Requested By Kirk      Assigned To MAINTENANCE CREW      Completed By SJ CB  
Start Date 1/1/      Time      Completed Date 9/17/20      Time 2:15

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes \_\_\_\_\_

Inventory Item And Description	Quantity Ordered	Quantity Used
Water flowing through Meter		
No water in or around Box		

Signature 

East Logan Water District  
**WORK ORDER 16263**

Account # \_\_\_\_\_ Name STALEY, RICKY D Order Date 9/30/2020  
Address \_\_\_\_\_ Status MEDIUM  
Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Scheduled 09/30/20 11:55 AM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER# \_\_\_\_\_ ERT/INTERNAL ID# \_\_\_\_\_ READING \_\_\_\_\_ LOCATOR TAG \_\_\_\_\_ READING IN / OUT \_\_\_\_\_  
WT 37363854 39215147 4617 B15402190

Description \_\_\_\_\_  
Comment RT GREY/HSE LFT OF SAME DR NO  
Requested By \_\_\_\_\_ Assigned To MAINTENANCE CREW Completed By *EH*  
Start Date   /  /   Time \_\_\_\_\_ Completed Date 9/30/20 Time 2:01

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
Notes NO LEAK

Inventory Item And Description	Quantity Ordered	Quantity Used

Signature *EH*

WORK ORDER 16260

Account # \_\_\_\_\_ Order Date 9/29/2020  
 Name CARDWELL, JESSICA M Status MEDIUM  
 Address \_\_\_\_\_ Scheduled 09/29/20 12 05 PM  
 Telephone \_\_\_\_\_ Job # \_\_\_\_\_ Order Type CHECK FOR LEAK ON OUR SIDE

METER# WT 78786040 ERT/INTERNAL ID# 73607026 READING 1489 LOCATOR TAG B15347551 READING IN / OUT 01616

Description \_\_\_\_\_  
 Comment RT, GRAY TRLR, LF DR  
 Requested By Tracy/Billy Manning Assigned To MAINTENANCE CREW Completed By ST  
 Start Date 9/29/20 Time 12:05 Completed Date 9/29/20 Time 12:05

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_  
 Notes says water is coming up at the meter

Inventory Item And Description	Quantity Ordered	Quantity Used
Customer leak		
Turn off water to stop work		
Customer notified		

~~9/29/20 12:05~~

Signature ST



East Logan Water District  
WORK ORDER 16197

Account #  
Name GORRELL, MARTY T  
Address  
Telephone Job #

Order Date 9/16/2020  
Status MEDIUM  
Scheduled 09/15/20 06:14 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 54230309	63184010	13360	B14169903	
Description	LF, BRK HSE, RT DR			
Comment	LF, BRK HSE, RT DR			
Requested By	Gorrell's	Assigned To	MAINTENANCE CREW	Completed By MAINTENANCE CREW
Start Date	09/15/20 06:45 PM		Completed Date 09/15/20 06:45 PM	

Notes Said water was pouring from box.  
Stephen found a busted meter bottom. and replaced the bottom

CRANDAL

Please see if this is leaking  
Bottom was replaced

Signature



East Logan Water District  
**WORK ORDER 16095**

Account #  
Name MCDOWELL TP, TRAVIS & CAROL  
Address  
Telephone Job #

Order Date 8/19/2020  
Status MEDIUM  
Scheduled 08/19/20 12:59 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 61247091	54037704	1401	B15347916	

Description

Comment RT,TRLR,25' LF DR

Requested By Ethan/Crandal Assigned To MAINTENANCE CREW Completed By ST

Start Date \_\_\_/\_\_\_/\_\_\_ Time \_\_\_:\_\_\_:\_\_\_ Completed Date 8/23/20 Time \_\_\_:\_\_\_:\_\_\_

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Sounding, and found a leak BUD call to repair

Inventory Item And Description	Quantity Ordered	Quantity Used
Determined it was Customer leak		

✓ Homer  
area painted locate both sides of road

Aug 21 by ST

ELWD  
LTC

2008191454

Signature ST

WORK ORDER 15521

Account #		Order Date	3/14/2020		
Name	YODER, TIMOTHY J	Status	HIGH		
Address		Scheduled	03/14/20 11 55 AM		
Telephone	Job #	Order Type	LEAK BY FIBER INSTALLATION		
METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT	
WT 83545699	89536811	284	B14166593		
Description					
Comment	1ft of pallet mill, 10ft up to				
Requested By	Elmer Kuhs	Assigned To	MAINTENANCE CREW	Completed By	MAINTENANCE CREW
Start Date	03/14/20 12 00 PM	Completed Date	03/14/20 02 00 PM		

Notes Elmer called Saturday to say there was a leak at this address, water running down the ditch

Ethan and Stephen spent 2 hours hand digging to repair where it had blown apart  
1 compression nut, 1 insert, 1 brass nipple, 2 crimp rings  
Flushed

Signature \_\_\_\_\_

WORK ORDER 15515

Account #  
Name YODER, TIMOTHY J  
Address  
Telephone Job #  
Order Date 3/12/2020  
Status HIGH  
Scheduled 03/12/20 05 49 PM  
Order Type LEAK BY FIBER INSTALLATION

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 83545699	89536811	284	B14166593	

Description

Comment 1ft of pallet mill, 10ft up to

Requested By Fiber Crew

Assigned To MAINTENANCE CREW

Completed By MAINTENANCE CREW

Start Date 03/14/20 12 00 PM

Completed Date 03/14/20 12 00 PM

Notes

Fiber crews hit this service line after hours Service line to Pallet Co.  
3-12 6pm - 8pm employees Dug up leak, crimped off line temporarily  
3-13 3 employees, 1 hr; replace 6' of pex, 1 insert, 1 compression nut, 1 brass nipple, 2 crimp rings

Signature \_\_\_\_\_

WORK ORDER 15510

Account #	---	Order Date	3/12/2020		
Name	MILLER, JASON	Status	HIGH		
Address		Scheduled	03/12/20 09 33 AM		
Telephone	Job #	Order Type	LEAK BY FIBER INSTALLATION		
METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT	
WT 50441828	72175800	2670	B14167112		
Description	LF,WH DBL WIDE,LF DR				
Comment	LF,WH DBL WIDE,LF DR				
Requested By	Stephen	Assigned To	MAINTENANCE CREW	Completed By	MAINTENANCE CREW
Start Date	03/12/20 09 33 AM	Completed Date	03/12/20 04 30 PM		

Notes

- Fiber optic crew from MN called Stephen to report they had hit the main line on Ayers
- 3 separate leaks
- 20' pipe 3" diameter
- 6 ea 3" knock-ons
- 3 employees 9 30 - 4 30
- 1 employee 12 00 - 4 30
- 2 Bac-T samples taken
- flushed 3 times est 12600
- leaked est 8400



East Logan Water District  
**WORK ORDER 16104**

Account #  
Name HALL, MITCH  
Address  
Telephone

Order Date 8/24/2020  
Status MEDIUM  
Scheduled 08/24/20 01:16 PM  
Order Type CHECK FOR LEAK ON OUR SIDE

METER#	ERT/INTERNAL ID#	READING	LOCATOR TAG	READING IN / OUT
WT 22585405	63524803	4736	B14162017	4735

Description  
Comment LF WH/HS L/CNR T/A T/RT

Requested By Mitch Assigned To MAINTENANCE CREW Completed By  
Start Date 8/24/20 Time 1:16 PM Completed Date 8/25/20 Time 2:16 PM

Make \_\_\_\_\_ Size/Type \_\_\_\_\_ Multiplier \_\_\_\_\_

Notes Mr. Hall says it is staying wet between the meter and the main for the last 2 months. Please check for a leak. You need to call him.

Inventory Item And Description	Quantity Ordered	Quantity Used
- 04759 (8-26-20)		
- Pulled a new service		
2 gpm x 30 dys		
2 hrs + 5		
10-2-20		

Signature 