

February 5, 2021

National Grid Renewables 8400 Normandale Lake Boulevard Bloomington, Minnesota 55437

Attn: Mr. John Strom, P.E. E: jstrom@nationalgridrenewables.com

Re: Caldwell Solar Karst Survey and Assessment Caldwell Solar, LLC Princeton, Caldwell County, Kentucky Terracon Project No. 57205061

Dear Mr. Strom:

As requested, Terracon Consultants, Inc. (Terracon) is submitting this report summarizing the karst survey and assessment at the proposed Caldwell Solar site in northern Caldwell County, Kentucky.

1.0 PROJECT INFORMATION

The proposed Caldwell Solar site in Caldwell County, Kentucky was assessed for potential karst geohazards underlying the property. The objective of the desktop review was to identify, locate, and characterize existing karst features with particular emphasis on open throat and/or active sinkhole development which could impact the proposed solar arrays, roadways, and supporting infrastructure. The entire site, measuring approximately 1,500 acres, is underlain by soluble carbonate bedrock forming a regional karst terrain (i.e. a landscape characterized by the presence of sinkholes, caves, sinking and losing streams, and a highly irregular "pinnacled" overburden/bedrock interface).

2.0 SCOPE OF SERVICES

Our karst survey and assessment services were performed in two phases: 1) a desktop data review phase, and 2) a field reconnaissance phase. Terracon assessed the properties indicated on files provided to us (Caldwell Solar.kmz, 11/18/2020; Caldwell-Golden-PIDs.pdf, 11/19/2020), hereinafter referred to as the Area of Interest (AOI).

Specifically, Terracon provided the following services:

Terracon's karst geologists performed a desktop review of readily available resources to identify suspected or documented karst features (e.g., sinkholes and areas of soil subsidence, cave entrances, closed depressions, and sinking and

Terracon Consultants, Inc. 19955 Highland Vista Drive Ashburn, Virginia 20147 P [703] 726 8030 terracon.com

1[erracon

Karst Survey and Assessment

Caldwell Solar Karst Assessment Caldwell County, Kentucky February 5, 2021 Terracon Project No. 57205061

losing streams) within the AOI, and any features within 0.25 miles of the AOI that were inferred to receive drainage from the AOI.

- Based on the results of the data review, Terracon's karst geologists located and delineated visible surface karst features (e.g., sinkholes and subsidences, cave entrances, closed depressions, and sinking and losing streams) within the proposed AOI, with particular emphasis on features that were inferred to have direct communication with the phreatic zone such as "open-throat" sinkholes, karst windows, cave entrances, abandoned wells, and sinking streams; and areas of high karst activity that could indicate development of pinnacled bedrock. Field observations were made by walking the AOI. A detailed map showing the AOI we evaluated is included as Map 1, Appendix A.
- Terracon delineated zones of karst terrain based on the surface karst feature assessment.
- The findings and conclusions of the data review and field study have been summarized in this report. The report includes recommendations on the feasibility of the planned construction in karst areas, indicates higher or lower risk areas within the AOI, and provides recommendations regarding additional studies or investigations for site specific karst features identified during the survey.

2.1 Methods and Procedures

Desktop Data Review

Potential karst features were identified remotely, prior to being located and characterized in the field. This process is intended to significantly reduce the amount of time spent in actual field observation and survey tasks. The review of the existing feature locations within the AOI was accomplished by examining data from the following sources:

- 1. The Cave Database of the Kentucky Speleological Survey (KSS);
- Maps of selected karst features available from the United States Geological Survey (USGS) and the Kentucky Geological Survey GIS Sinkhole Database (https://www.uky.edu/KGS/gis/sinkpick.htm);
- Two-foot contour interval maps for the AOI and surrounding to within 0.25 miles, in order to determine the presence of surface features not included in the above listed databases based on the presence of closed, descending contours or other suspect karst "fingerprint" features;

Nerracon

Karst Survey and Assessment

Caldwell Solar Karst Assessment Caldwell County, Kentucky February 5, 2021 Terracon Project No. 57205061

- 4. Digital Elevation Models (DEMs) and LIDAR Data;¹
- 5. Aerial photographs (both recent and historical); and
- 6. USGS Topographic 7.5-minute topographic quadrangles.

In addition, Terracon reviewed readily available geological literature for bedrock and structural characteristics. We relied upon the closest resolution geological mapping that exists for the AOI. Each feature was assigned a unique identifier.

Field Survey

Upon completion of the data review, Terracon initiated the field reconnaissance and survey activities. Specifically, the field reconnaissance entailed:

- 1. Location and verification of potential surface features identified in the desktop review;
- 2. Location of uncatalogued or previously unidentified surface features, specifically sinkholes, cave entrances, dry runs, sinking streams or abandoned mine entrances.

Each survey area was delineated and then examined for features (both catalogued and previously nondescript) in the field. This entailed walking over the survey area in a systematic manner, to observe features that fit the criteria. The locations and outlines of all relevant features were recorded using a sub-meter accuracy GPS device. For this study, the outline (parapet) of a closed depression (sinkhole) was defined as either the last closed descending contour at a 2-foot mapping interval or by the presence of a visible parapet. Cave entrances were identified as single points, unless the entrance was located within a larger sinkhole structure, in which case the cave entrance was indicated as a point within the sinkhole's parapet. Sinking streams were located as points of entry into the subsurface; however, losing streams were identified as linear features. Springs were also identified as points.

Each feature was assigned a unique identifier using the same protocol as the data review. Features verified from the data review retained their original identifiers; however, any feature that could not be verified in the field was removed from the final data set. Any new features were assigned the next number after the last one assigned.

3.0 GEOLOGY AND TERRAIN

Physiography – The proposed Caldwell Solar site is situated within the western portion of the Interior Low Plateaus Physiographic Province of Ohio, Kentucky and Tennessee, which extends from the Greater Cincinnati metropolitan region in the Ohio River Valley southward to the Nashville Region of Tennessee. In general, the Interior Low Plateaus range from approximately 380 to 1,200 feet in elevation and predominantly comprise of rolling plains and eroded plateaus.

¹ KyFromAbove (https://kyfromabove.ky.gov/)



Caldwell Solar Karst Assessment Caldwell County, Kentucky February 5, 2021 Terracon Project No. 57205061

This region is almost completely composed of horizontal beds of sandstone, shale, and limestone from the Paleozoic Era (541 to 252 million years ago). The Interior Low Plateaus exist at the southeastern area of the Central Lowlands, the boundary occurring where the maximum extent of the Pleistocene glaciers reached.

Specifically, the subsection of the Low Plateaus Physiographic Province in Kentucky is referred to locally as the Mississippian Plateaus or the "Pennyrile" (named for the Pennyroyal plant, *Hedeoma puligiodes*). The Mississippian Plateaus wrap around the Western Kentucky Coalfield Province, in a crescent that opens towards the north. This Mississippian Plateaus in the site area is divided by the Dripping Springs Escarpment into an upland often called the Mammoth Cave Plateau, and a lowland area called the Pennyroyal Plateau. The Caldwell Site lies within the Pennyroyal Plateau of Caldwell County, KY.

Topography – The Caldwell Site is nearly level, with an average elevation (EL) of EL 450. The highest point within the site is at EL 550, in Parcels 9-2 and 16-25A. The site lies along the southwestern base of the Dripping Springs Escarpment.

There are a few areas of surface water at the site, primarily ponds, which are mostly flooded sinkholes. An unnamed stream that originates on the escarpment sinks into the subsurface at the eastern edge of Parcel 16-51 into a sinkhole. Otherwise, there are not open bodies of surface water at the site.

Geology – The Mississippian Plateau Province is named based on its geology, as it is underlain primarily by karst-prone carbonate units dated to the Mississippian Geologic Period. The following bedrock units are mapped within the survey area and are shown in Map 2, Appendix A and described below:

Rosiclare Sandstone and Fredonia Limestone Members of the Ste. Genevieve Limestone (Msrf) In general, the Ste. Genevieve Limestone is composed of medium gray to bluish gray limestone with minor clay-shale beds and interbedded oolitic limestone with coarsely crystalline limestone and fine to medium grained calcarenite and calcilutite.

The Rosiclare Sandstone Member of the Ste. Genevieve Limestone was deposited during the Mississippian Period and ranges from approximately 5 to 10 feet thick. This member predominantly consists of very fine grained, calcareous sandstone and limestone.

The Fredonia Limestone Member of the Ste. Genevieve Limestone was deposited during the Mississippian Period and ranges in thickness from approximately 200 to 250 feet thick. The limestone comprising of this member is broken into three major types, described in detail below.

1. Light-gray and oolitic, found in zones 10 to 30 feet thick;



Caldwell Solar Karst Assessment Caldwell County, Kentucky February 5, 2021 Terracon Project No. 57205061

- 2. Light-to medium-gray, finely crystalline, commonly dolomitic with rare chert modules (typically found in the lower 60 feet); and
- 3. Light-to medium-gray, medium-to coarsely crystalline, fossil fragments evident.

The base of this unit is typically cherty limestone as it transitions to the underlying unit, and weathers to a dark reddish-brown soil with dense or oolitic chert fragments.

St. Louis Limestone (Mslu)

The St. Genevieve Limestone is underlain by this formation which consequently underlies the entirety of the AOI. This formation is separated into an upper (Mslu) and lower (Msll) member and specifically the upper member is mapped within the AOI at the south-eastern most end of the project site. The upper unit is comprised of mainly thin beds of dark gray limestone with thin layers of shale and nodules of chert present near the top of the formation.

Normal faults surround the project area within Caldwell County running approximately westsouthwest to east-northeast, creating abnormal and discontinuous dips and outcrops; however, no faults are currently mapped within the survey area. West of the survey area, alluvial material consisting of glacial deposits can be found along the Ohio River and associated tributaries.

Karst Geology – The site is within the classic Pennyroyal Plateau region, an area characterized by tens of thousands of sinkholes, sinking streams, dry valleys, springs, and caverns. It is of note that the limestones of the Pennyroyal Lowland below the Dripping Springs Escarpment are not capped by the soft sandstone that is found on the Mammoth Cave Plateau to the east. For this reason, there is a much higher concentration of karst features located in this area, most of which have open throats that lead directly into the subsurface, and are not clogged with sandstone residual sediment as are often found within the Mammoth Cave upland area.

Based on topographic mapping the site is internally drained, with a complete absence of surface streams of any kind. Most of the drainage to the site sinkholes is composed of broad "sheet flow". Nevertheless, there are a few features with poorly defined drainage channels. It is of note that three streams originated from offsite terminate and sink into the subsurface either on, or near, the subject site. It is almost a certainty that the surface karst features at the site are interconnected in a complex network of subsurface conduits and caverns, however the actual groundwater flow in this area has never been fully characterized. It is likely however that the groundwater most likely eventually moves towards the south and west and emerges in springs that discharge their water to the Cumberland and Tennessee Rivers.



Caldwell Solar Karst Assessment Caldwell County, Kentucky February 5, 2021 Terracon Project No. 57205061

4.0 SURVEY RESULTS AND DISCUSSION

4.1 Data Review

Based on the methods and procedures for the data review as detailed previously in Section 2.1, the majority of identified suspect karst features (SKFs) were identified throughout the proposed site. Review of the existing high-resolution LiDAR datasets resulted in one hundred and ninety-seven (197) suspect karst features. These SKF areas are highlighted in Figure 1 and indicate areas of karst development that were verified during the field survey.



Figure 1. Map of the site showing the SKF zones identified during the data review prior to field exploration. Proposed workspace (outlined in red), SKF (blue points and blue areas), proposed solar arrays (yellow).

4.2 Field Survey

The field survey was performed from December 8, through December 12, 2020, by Sean Vanderhoff, Terracon Staff Geologist. The AOI was assessed for karst development in the parcels where the geological mapping suggested there was the possibility of the development of karst terrain and/or where the data review indicated the possible presence of existing surface karst features (e.g. closed depressions, sinkholes, caves, or karst springs). A total of one hundred and seventy-six (176) karst features were verified in the field. A summary of the karst feature inventory documented during the field survey is included in map format in Appendix B, photolog format in Appendix C, and data format in Appendix D.

Terracon

Karst Survey and Assessment

Caldwell Solar Karst Assessment Caldwell County, Kentucky February 5, 2021 Terracon Project No. 57205061

5.0 KARST RISK RANKINGS

5.1 Examples of Features Used to Develop Risk Ranking

A total of eight different types of karst features with varying characteristics impacting the risk ranking are shown below. The following exemplary karst feature "types" are representative of the various characteristics used to develop the risk ranking. In some cases, the following feature types may have more than one of the characters used in the risk ranking development, nevertheless they are included here as examples.

Type 1 – This type of karst feature is characterized by the presence of an open throat at the base and active erosion along the walls and parapet of the feature. These features are considered the highest risk since they are actively growing and may continue to collapse and widen during construction activities and post development. Two examples of such features are shown below in Image 1.



Image 1. Both sinkholes are undergoing erosion and expansion of the parapet limits as demonstrated by the rough, raveling, and incised surfaces. In addition, the open throats present in the base of the sinkholes readily receive surface runoff with little to no filtration.

Type 2 – This type of karst feature is characterized by the presence of an incised drainage channel leading to the karst feature indicating that focused drainage enters the structure, which commonly results in active erosion and growth of the sinkhole (Image 2). In addition, they nearly always contain an open throat. Additionally, these features can be problematic as potential construction activities within the drainage may result in the uncontrolled flow of water transporting sediment and contaminants into the subsurface via the open throat. Awareness of the drainage catchment extent and implementation of proper erosion and sediment controls (ESC) are crucial for these types of karst features.



Caldwell Solar Karst Assessment Caldwell County, Kentucky February 5, 2021 Terracon Project No. 57205061



Image 2. Two examples of drainage channels leading towards sinkholes with open throats.

Type 3 – This type of karst feature has an open throat and rough, irregular parapet edges, indicating active erosion, collapse, and growth. The features are typically small (<5 feet) yet indicate that the area around the soil piping is undergoing sinkhole development which may widen, deepen, and affect the surrounding area (Image 3). It is commonplace to observe multiple soil piping features which may all be feeding into a single open throat in the subsurface. These features pose a significant risk because the karst features are actively developing; therefore, official remediation or avoidance is necessary.



Image 3. Examples of soil piping structures and open throats which are newly developed and indicate that growth and widening of these features is likely.

Type 4 – This type of karst feature is a sinkhole with a cave entrance located at the base or within the sidewall of the structure (Image 4). Caves pose a significant risk since they are relatively large openings that can receive surface runoff, may contain significantly sized chambers and passages below the surface, and may host cave fauna and sensitive biological habitats. Aside from having certified spelunkers enter the caves and map out the passages, geophysical techniques are often utilized to determine the presence, extent, depth, and size of cave passages in relationship to planned construction.

lerracon

Karst Survey and Assessment

Caldwell Solar Karst Assessment Caldwell County, Kentucky February 5, 2021 Terracon Project No. 57205061



Image 4. Two cave entrances observed during the field survey, where the right entrance is located at the base of a sinkhole and the left image shows a cave entrance at the base of a drainage channel.

Type 5 – This type of karst feature has an open throat within the structure, yet the remainder of the sinkhole is overgrown with vegetation and the parapet appears to be stable² (Image 5). Although there is an opening present leading into the subsurface, the protection and stabilization of the feature by maintaining a vegetated buffer dramatically reduces the risk of impacting the subsurface habitat during construction activities.



Image 5. Examples of overgrown open throats located at the base of sinkholes. The presence of the plant life indicates that little to no recent erosion has occurred.

Type 6 – This type of karst feature is characterized by bedrock bound open throats and rock outcrops either located at the base of sinkholes or within generally flat laying bedrock benches (Image 6). Although the open throats clearly connect to the subsurface, the bedrock does not present much risk of collapse or change in architecture unless the bedrock layer is very thin above an open chamber.

² Circular or oval sinkhole parapets are assumed to have reached equilibrium.

Terracon

Karst Survey and Assessment

Caldwell Solar Karst Assessment Caldwell County, Kentucky February 5, 2021 Terracon Project No. 57205061



Image 6. Bedrock bound open throats located within a bedrock outcrop (left) or at the base of a depression (right).

Type 7 – This type of sinkhole has been used by farmers and landowners as a convenient place to deposit field rock, trees, trash, and a menagerie of various items and materials. This practice of depositing trash is highly discouraged since the contaminants originating from the infill material may quickly reach and may affect the subsurface aquifer. Nevertheless, these karst features were present within the AOI and most typically observed to be infilled with trash and occasional trees (Image 7). Since these may have been partially or completely filled, it is impossible to fully characterize these features for the presence or absence of an open throat. Therefore, we assume that there is an open throat at the base in order to be conservative for protection measures during construction activities.



Image 7. Examples of trash filled sinkholes observed during the field survey. The feature on the left is filled with presumably cow and deer carcasses and the feature on the right is filled with old vehicles.

Type 8 – This types of sinkhole is present as a broad and shallow depression, ranging in size from tens to hundreds of feet in diameter and commonly referred to as a "mature" or paleokarst sinkhole (Image 8). Mature sinkholes often have a roughly circular parapet outline, are bowl shaped, lacking any opening to the subsurface (i.e. "throat") or showing evidence of active soil raveling or tension cracks around the parapet. Thus, whatever conduit or opening into the



Caldwell Solar Karst Assessment Caldwell County, Kentucky February 5, 2021 Terracon Project No. 57205061

underlying karst aquifer that may have functioned to create the structure is probably now clogged with soil, which would act as a filter for water infiltrating from the surface.



Image 8. Examples of mature sinkholes. The feature on the left is a large closed depression which has a subsidiary collapse located at the center of the feature (pointed out by the yellow arrow). The newly formed collapse acting as a drain to the closed depression indicates that reactivation has occurred. The image on the right shows a closed depression which has presumably been repurposed into a pond.

5.1 Risk Character Analysis and Results

Karst risk was assessed per karst feature through the compilation of a data matrix comprising five karst feature variables. These variables were assessed per karst feature by analyzing the field notes, observing the photographs, and considering the overall context and resources from the desktop data review.

It is of note that this type of data analysis and reduction (i.e. character analysis) is designed to assist in minimizing subjectivity in assessment of karst features for overall risk. The tabulation of the data analysis is present in Appendix D, Table 2.

The variables (characters) embodied in creating the risk data matrix and resulting risk assessment summary are:

- 1. Presence of an open throat
- 2. Parapet characteristics
- 3. Degree of soil raveling
- 4. Drainage leading to the karst feature
- 5. Presence and quality of vegetation

Explanation of the Characters

Character 1 – The presence of an open throat (e.g. an opening into the subsurface, usually at the base of a sinkhole, an opening within a rock outcrop, or a cave entrance) in a karst feature is important since it may allow the unimpeded flow of surface runoff into the subsurface and



Caldwell Solar Karst Assessment Caldwell County, Kentucky February 5, 2021 Terracon Project No. 57205061

eventually the groundwater table. This is a serious environmental concern to the groundwater and proper erosion and sediment control and buffering must be utilized during construction around these types of karst features.

Coding: Absent = 0; Small/Unknown = 1; Large/Open = 2

Character 2 - The shape and conformation of the parapet of each karst feature is important because the smoothness of the edge indicates the degree of erosion, growth, and overall activity of the karst feature. Typically, the rougher the parapet edge the more active the karst feature, and hence higher risk for the surface to continue to change.

Coding: Parapet Stable/Circular = 0; Irregular/Unstable = 1

Character 3 - Coeval with parapet shape changes and erosion, soil raveling of the sinkhole walls, throat, and subsidiary channels is a good indicator for sinkhole activity and risk. We further distinguish soil raveling into "minor raveling" and "raveling" to differentiate between levels of erosion and growth inside the karst feature.

Coding: No raveling = 0; Minor raveling = 1; Major/severe raveling = 2

Character 4 - An important factor that we note when assessing karst features, is evidence for surface drainage focused into the karst feature. This is typically manifested as matted down grass/vegetation in the direction of the sinkhole in the case of surface runoff (sheet flow) or distinct erosion and channel development where water commonly drains into the karst features. If the channel leading to the karst feature exhibits signs of erosion and downcutting, then this further supports the notion that the karst feature base level is decreasing and typically growing. **Coding: No evidence of drainage = 0; Sheet flow = 1; Drainage channel = 2**

Character 5 - The presence, type, and state of vegetative cover surrounding and within the karst feature is an indicator for sinkhole development and the existence of a natural buffer. If little to no vegetative cover is present within the sinkhole then this indicates that it is changing fast enough to inhibit plant growth and that it is vulnerable to surface runoff. If the sinkhole is overgrown, then this signifies that the sinkhole is more stable and that a natural vegetated buffer is present, which functions to filter out suspended soil/contamination in surface runoff.

Coding: Fully vegetated = 0; Partially vegetated = 1; Soil/rock = 2

Based on the character analysis, we have assigned a low, moderate or high-risk category of each of the confirmed karst features present, specifically to this site. If the defined characteristics sum was 0 it is our interpretation that the feature is very low risk to site development. If the sum was 1-2, we believe the feature is a low risk to site development. If the sum was 3-4, we believe the feature is a moderate risk to site development. If the sum was 5-6, we believe the feature is a high risk to site development. For features that their characteristics summed to 7-9, we believe present very high risk for continued karstification and site development and throughout the operation of the proposed facility.



Caldwell Solar Karst Assessment Caldwell County, Kentucky February 5, 2021 Terracon Project No. 57205061

The degree of risk we identify for these karst features indicates our professional opinion regarding the likelihood of the karst feature becoming unstable or accelerate its growth. The risk rankings should be used as a planning tool to aid in assessing the overall risk of developing the site. However, it should be clearly understood that even karst features designated as low risk can become unstable and negatively impact the proposed development. It is impossible to eliminate the risk of karst features, but measures can be taken to reduce the risk of karst issues.

6.0 KARST RISK RECOMMENDATIONS

The karst risk recommendations entail a suite of approaches for each karst risk level. These various solutions for karst features will depend upon the type and scope of the project, the amount of cut and fill planned for the AOI, the presence of karst dependent rare threatened and endangered species, and the hydrologic significance of the karst aquifer (e.g. municipal drinking water supply). For the specific development of remediation, alternative foundations, or detailed additional studies, it is recommended that a Terracon karst geologist monitor construction activities to ensure that proper protocol is applied and to be available for consultation in the event that new karst features develop during grading activities onsite. The karst avoidance and/or mitigation measures for each karst feature risk level are presented below. Please note that the recommendations from a higher risk category can always be applied to lower features.

Very High Risk

- Avoidance and buffering
- Additional investigations may lower risk ranking

Moderate to High Risk

- Avoidance and buffering
- Additional Investigations
- Remediation (If necessary)

Low Risk

• Span karst features

Very Low Risk

• Grade and monitor

The preferred option is to avoid all karst features if possible, since every feature does bring a variable amount of risk to both the project infrastructure and the karst aquifer. In addition, avoidance preserves the vegetated buffer, especially for features which have reached equilibrium naturally. For this avoidance scenario we recommend a minimum buffer of 25 feet which should remain in an undisturbed natural state³ through all periods of construction and subsequent facility operations. In addition, a 150-foot buffer should be established around each karst feature during

³The term "undisturbed natural state" means that the existing vegetation within the 25-foot buffer, and extending across the entire sinkhole, should not be cut, trimmed, thinned or disturbed in any way.

Terracon

Karst Survey and Assessment

Caldwell Solar Karst Assessment Caldwell County, Kentucky February 5, 2021 Terracon Project No. 57205061

construction where vehicles may not be refueled, and stockpiles of equipment or fuel should not be stored. The 150-foot buffer may need to be extended or modified if a significant drainage area has been delineated outside of an open throat feature. This does not mean construction is prohibited within this buffer, only that certain construction related activities primarily storage of fuel and equipment should not occur within this area.

In the case where avoidance is not possible then the next steps may include remediation of the karst features (e.g. reverse graded filter, pillow remediation, cap grouting, etc.) and conducting additional studies (Section 7.0) to shed light on the extent, characteristics, and impact that the karst feature may have on the surface. Remediation will vary for each karst feature based on characterization (e.g.: soil type, the architecture of the bedrock, and the local hydrology among many other factors). The type of remediation is typically determined upon subsurface exploration and excavation of the karst feature and identification and characterization of the bedrock bound throat if present at the soil bedrock interface.

Specifically, for solar field facilities it may be possible to span some of the karst features with the solar arrays, depending upon the length of the arrays and the spacing of the supporting piles. This option is limited to the low and very low risk karst features since their current characteristics do not suggest continued erosion and growth, and instead appear to have reached equilibrium naturally. It is important to note that periodic monitoring of these karst features post-construction is recommended.

It is permissible for the very low risk karst features to be graded per the construction plans, but it is imperative that the locations of these features be marked with survey grade GPS prior to grading activities. These areas should be monitored during construction in case the grading activities cause these features to reactivate.

Please note the risk rankings presented herein are based on the current condition of the site at the time of our study. Changes in the risks and changes in the karst features will occur over time. In addition, changes may occur due to changes in surface grades, surface hydrology, nearby construction activities such as blasting, installation of water supply wells, and other similar changes.

7.0 RECOMMENDATIONS REGARDING ADDITIONAL STUDIES

Prior to site development, additional studies are recommended. Non-invasive geophysical investigations should be used for any features other than very low risk. The preferred method would be electrical resistivity investigation (ERI), however other methods such as seismic and gravimetry may be utilized. The primary purpose of the ERI will be to reveal if there are any near-surface voids that could present a risk during construction or operation of the facility.



Caldwell Solar Karst Assessment Caldwell County, Kentucky February 5, 2021 Terracon Project No. 57205061

Other investigation methods including but not limited to drilling (hollow stem, air track probe, etc), test pits, direct push borings, or other appropriate methods may be utilized to investigate specific karst features. The actual investigation method to be used will be based on the site-specific conditions, access, and the type of the karst features.

8.0 CLOSURE

The information presented herein has been based on the review of both proprietary and publicly available geologic information. However, it should be noted that karst is a dynamic landform and significant changes can occur over time. We understand that a geotechnical investigation will be completed at this site which may reveal additional subsurface karst issues. As indicated herein, karst features may be present below the ground surface that were not identified by this study. These features may not be identified until during construction. Accordingly, Terracon should be engaged during the construction phase of this project to provide oversight of the karst management plan, and to address karst features encountered during construction.

As indicated in this report, the bedrock and overlying soil below the site are susceptible to sinkhole development, and there can be extensive areas of shallow bedrock and shallow groundwater that can pose a risk to the site development process. Risk associated with these factors can be minimized during development with proper planning, design, and the control of site hydrology. Nevertheless, the client must recognize that risk of sinkhole and hydrologic-related damage to foundations, site infrastructure, and pavements does exist



Karst Survey and Assessment Caldwell Solar Karst Assessment Caldwell County, Kentucky February 5, 2021 Terracon Project No. 57205061

Terracon has conducted these services in accordance with generally accepted geologic practices. No warranties, either expressed or implied, are made as to the professional services and recommendations presented herein.

Sincerely,

Terracon Consultants, Inc.

Jen Viltie

Joshua Valentino, PhD, PG Senior Staff Geologist



RK SS.

Robert K. Denton Jr., CPG, LPSS Karst SME

Appendices: Appendix A – Small Scale Maps Appendix B – Large Scale Maps Appendix C – Karst Feature Inventory Appendix D – Karst Feature Description Sheets

Responsive . Resourceful . Reliable

Filed per 3-30-2022 ESB Order Response to 2 ESB 01

APPENDIX A SMALL SCALE MAPS





Filed per 3-30-2022 ESB Order Response to 2 ESB 01

APPENDIX B LARGE SCALE MAPS



















