

WORK ORDERS BY TYPE

09:20:48

LIST/TY: RLID
 SCHEDULED DATE: 05/02/19 SCHEDULED TIME: PM:
 ACTIONS: REPLACE METER BOX LID

WORK ORDER NO : 50319

37.323048
 86.245937

LOCATION: RIGHT OF PHONE PEDESTAL

1332 07
 IN: 03/22/12



***** INFORMATION*****

***** OLD METER INFORMATION *****
 5/8 in. TY: G USE: 2 04/02 *
 MAKE SERIAL REMOTE MXUID CURRENT MAKE SERIAL REMOTE MXUID
 41940550 83432733 1650 A *
 *
 *

 HISTORY: DATE CURRENT PREVIOUS USAGE PRIOR W/O DATE TYPE
 04/02/19 1650 1648 2 A
 03/05/19 1648 1645 3 A 39919 07/14/16 RBOX
 02/04/19 1645 1644 1 A 39904 07/12/16 READ
 01/02/19 1644 1637 7 A 23288 03/13/12 AMR
 *****RLID

Start Date: 5-2-19 Arrival Time: 10:00

| Employee | Time | Rate | Cost |
|------------|-------|------|------|
| M | 3min | | |
| Dylan | 20min | | |
| P | 20min | | |
| Total Cost | | | |
| Vehicle | Time | Rate | Cost |
| 7 | 20min | | |
| Total Cost | | | |
| Equipment | Time | Rate | Cost |
| Total Cost | | | |

| Parts | | | |
|----------------------------|--------------|--------|-------|
| Part Description | Used / Ret # | GL # | Cost |
| Plastic meter box lid #449 | 1/5081 | 620.10 | 11.25 |
| Total Cost | | | |

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Completed Date: 5-2-19 Completed Time: 10:20 [Redacted] AP

WORK ORDERS BY TYPE

08:32:37


LIST/TYPE: MISC
 SCHEDULED DATE: 05/06/19 SCHEDULED TIME: AM:
 ACTIONS: REPLACE VALVE BOX

WORK ORDER NO : 50335

to Short

LOCATION:

IN:



METER INFORMATION*****

| MAKE | SERIAL | REMOTE | MXUID | CURRENT | * | MAKE | SERIAL | REMOTE | MXUID |
|------|--------|--------|-------|---------|---|------|--------|--------|-------|
| | | | | | * | | | | |
| | | | | | * | | | | |
| | | | | | * | | | | |

HISTORY: DATE CURRENT PREVIOUS USAGE PRIOR W/O DATE TYPE

*****MISC

Arrival Date: 5-1-19 Arrival Time: 1:30

| Labor Cost | | | | Parts | | | |
|------------|-------|------|------|---------------------|--------------|--------|-------|
| Employee | Time | Rate | Cost | Part Description | Used / Ret # | GL # | Cost |
| CC | 5 hrs | | | #471 | | | |
| Oylan | 1 hr | | | 24" x 36" Valve Box | used-1 | 620.10 | 39.18 |
| | | | | | | | |
| | | | | | | | |
| Total Cost | | | | | | | |

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____

Comments:
 Returned 18" x 24" valve box # 469 / 620.4

Completed Date: 5-1-19 Completed Time: 2:30 By _____

5/3410

WORK ORDERS BY TYPE

10:15:31

LIST/TYPE: LEAK

WORK ORDER NO : 50306

SCHEDULED DATE: 04/29/19 SCHEDULED TIME: AM:

ACTIONS: [REDACTED] - REPORTED AT THIS ADDRESS

THERE IS WATER STANDING EVERYWHERE AND RUNNING EVERYWHERE. FIXED LEAK THERE BEFORE, HE SAID IT'S ABOUT 50 FOOT UP FROM WHERE THE LAST BREAK WAS

37.362616
86.162060

LOCATION: RIGHT SIDE OF THE STEPS

IN: 11/11/10

*****OLD METER INFORMATION***** NEW METER INFORMATION*****

5/8 in. TY: G USE: 3 04/17 *
METER SERIAL REMOTE MXUID CURRENT MAKE SERIAL REMOTE MXUID
40356864 83006397 894 A *
*
*
*

| TORY: | DATE | CURRENT | PREVIOUS | USAGE | PRIOR W/O | DATE | TYPE |
|-------|----------|---------|----------|-------|-----------|----------|------|
| | 04/17/19 | 894 | 891 | 3 A | 48800 | 11/19/18 | MNLK |
| | 03/18/19 | 891 | 887 | 4 A | 49896 | 03/28/19 | SRLK |
| | 02/18/19 | 887 | 887 | 0 A | 49266 | 01/11/19 | SRLK |
| | 01/17/19 | 887 | 885 | 2 A | 48980 | 12/11/18 | SRLK |

*****LEAK

Call Date: 5/2/19 Arrival Time: 9:30

| Employee | Time | Rate | Cost |
|------------|------|------|------|
| C | 3min | | |
| JD | 2hrs | | |
| DB | 2hrs | | |
| Total Cost | | | |
| Vehicle | Time | Rate | Cost |
| X | 2hr | | |
| Le | 2hr | | |
| Total Cost | | | |
| Equipment | Time | Rate | Cost |
| TA | 2hr | | |
| Total Cost | | | |

| Parts | | | |
|-------------------------|--------------|--------|-------|
| Part Description | Used / Ret # | GL # | Cost |
| 3" x 12" PVC clamp #374 | Used 1 | 620.16 | 55.32 |
| Total Cost | | | |

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 41,500 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Completed Date: 5/2/19 Completed Time: 11:30 By: JD DB

WORK ORDERS BY TYPE

12:00:46

LIST/TY: MNLK
 SCHEDULED DATE: 05/13/19 SCHEDULED TIME: PM:
 ACTIONS: REPAIR MAIN LINE LEAK

WORK ORDER NO : 50405

37.269134
 86.328736

LOCATION: IN FRONT OF HOUSE 10' OF RD

7492 94
 IN: 03/06/12



NEW METER INFORMATION*****

5/8 in. TY: G USE: 27 05/03 *
 MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 41940231 83432903 4689 A *
 *
 *
 *

CATEGORY: DATE CURRENT PREVIOUS USAGE PRIOR W/O DATE TYPE
 05/03/19 4689 4662 27 A

*****MNLK

Date: 5/13/19 Arrival Time: 5:30

| Employee or Cost | | | | Parts | | | |
|------------------|------|------|------|-----------------------------|--------------|-------|-------|
| Employee | Time | Rate | Cost | Part Description | Used / Ret # | GL # | Cost |
| D. Lehrs | | | | 4" pvc repair coupling #391 | Used 2 | 620.6 | 22.00 |
| B. Lehrs | | | | 4" pvc pipe #497 | Used 4ft | 620.6 | 4.65 |
| Total Cost: | | | | Total Cost | | | |

| Employee | Time | Rate | Cost |
|-------------|------|------|------|
| Lohs | | | |
| Total Cost: | | | |
| ment | Time | Rate | Cost |
| Lohs | | | |
| Total Cost: | | | |

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 122,500 Gal. Flushed 25,000
 Cause Of Leak: rock Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Date: 5/13/19 Completed Time: 11:30 By: JDD DB

WORK ORDERS BY TYPE

08:41:19

KLIST/TYPE: HANG

WORK ORDER NO : 50570

SCHEDULED DATE: 05/30/19 SCHEDULED TIME: AM:

INSTRUCTIONS: PLEASE HANG METER FOR NEW OWNERS,

LEAVE ON AT METER UNLESS IT CONTINUES TO TURN!
METER STATUS: DRY BOX

LOCATION: ACROSS ROAD IN LINE WITH TRAILOR

IN:



METER INFORMATION*****

| MAKE | SERIAL | REMOTE | MXUID | CURRENT | MAKE | SERIAL | REMOTE | MXUID |
|------|--------|--------|-------|---------|----------|--------|----------|-------|
| | | | | 629 A | 49353463 | | 87244226 | |
| | | | | | | | | |
| | | | | | | | | |

552
334.4
R-422 HRE

| STORY: | DATE | CURRENT | PREVIOUS | USAGE | PRIOR W/O | DATE | TYPE |
|--------|----------|---------|----------|-------|-----------|------|------|
| | 10/18/05 | 629 | 629 | 0 | A | | |
| | 09/19/05 | 629 | 629 | 0 | A | | |
| | 08/18/05 | 629 | 629 | 0 | A | | |
| | 07/18/05 | 629 | 629 | 0 | A | | |

*****HANG

Arrival Date: 5-31-19 Arrival Time: 800

| Labor Cost | | | | Parts | | | |
|-------------|---------|------|------|--------------------------|--------------|-------|--------|
| Employee | Time | Rate | Cost | Part Description | Used / Ret # | GL # | Cost |
| C | 5min | | | #333 | | | |
| MT | 4hr 45m | | | 3/4 Service used SET | | 333.4 | 1.14 |
| J.C | 4hr 45m | | | 3/4 ss inserts #199 | U-3 | 333.4 | 3.54 |
| | | | | 3/4 X 5/8 metersetter #1 | U-1 | 334.5 | 142.77 |
| | | | | 3/4 PVC to 3/4 CST #107 | U-3 | 120.6 | 51.20 |
| | | | | Meter washer 255 | U-2 | 334.5 | .15 |
| | | | | plug 261 R-1+334 | | | |
| Total Cost: | | | | Total Cost | | | |

| Vehicle | Time | Rate | Cost |
|-------------|----------|------|------|
| 150 | 4hrs 45m | | |
| Total Cost: | | | |

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of interruption: _____

Comments: Left off meter kept turning
* Can not hang meter no way of
turning it on needs a setter

Completed Date: 5-31-19 Completed Time: 145 By: MT JI

WORK ORDERS BY TYPE

13:22:59

CKLIST/TY: MISC
SCHEDULED DATE: 05/31/19 SCHEDULED TIME: PM
INSTRUCTIONS: REPLACE 16' LINE

WORK ORDER NO : 50577

WORKER LOCATION: RIGHT OF GUIDE WIRE 6FT

IN: 03/26/10



***** INFORMATION*****

3/4 in. TY: G USE: 0 06/09 *
MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
36578363 A *
*
*
*

| STORY: | DATE | CURRENT | PREVIOUS | USAGE | PRIOR W/O | DATE | TYPE |
|--------|----------|---------|----------|-------|-----------|----------|-------|
| | 06/09/10 | 0 | 0 | 0 A | 46429 | 03/26/18 | RBOX |
| | 06/03/10 | 0 | 0 | 0 A | 42648 | 04/13/17 | MNLK |
| | 05/05/10 | 0 | 0 | 0 A | 10542 | 04/29/10 | PULL |
| | 04/07/10 | 0 | 0 | 0 A | 8905 | 03/25/10 | CHECK |

Arrival Date: 5-22-16 Arrival Time: 7:30

| Labor Cost | | | | Parts | | | |
|-------------|------|------|------|--------------------|--------------|-------|--------|
| Employee | Time | Rate | Cost | Part Description | Used / Ret # | GL # | Cost |
| V | 9hr | | | 16" Pipe #507 | Used 10ft | 620.6 | 204.18 |
| JH | 9hr | | | 16" sleeves #475 | Used 20 | 620.6 | 649.86 |
| JA | 9hr | | | locating wire #219 | Used 240ft | 620.6 | 18.05 |
| Total Cost: | | | | | | | |
| Vehicle | Time | Rate | Cost | Total Cost | | | |
| 150 | 9hr | | | | | | |

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Completed Date: 5-22-16 Completed Time: 4:30 By: JA DH TV

WORK ORDERS BY TYPE

13:07:18

LIST/TYPER: MNLK

WORK ORDER NO : 50426

SCHEDULED DATE: 05/16/19 SCHEDULED TIME: PM:

DESCRIPTION: MAIN LINE LEAK ACROSS THE STREET FROM [REDACTED] - CUSTOMER CALLED AND SAID WATER WAS GUSHING OUT - TOLD [REDACTED]

LOCATION:

IN:



METER INFORMATION*****

SERIAL REMOTE MXUID

*
*
*
*

PROPERTY: DATE CURRENT PREVIOUS USAGE PRIOR W/O DATE TYPE

*****MNLK

Arrival Date: 5-15-19 Arrival Time: 2:00

| Labor Cost | | | | Parts | | | |
|------------|--------|------|------|-------------------------|--------------|-------|-------|
| Employee | Time | Rate | Cost | Part Description | Used / Ret # | GL # | Cost |
| C | 5 min | | | 1 3/4 inch coupling #91 | #61 | 620.6 | 15.30 |
| F | 1 hour | | | 2 1/4 inserts #89 | 03 | 333.4 | 3.54 |
| C | 1 hour | | | 3/4 Tubing #333 | 6 3 Foot | 333.4 | 14.35 |
| Total Cost | | | | Total Cost | | | |

| Vehicle | Time | Rate | Cost |
|------------|--------|------|------|
| 8 | 1 hour | | |
| Total Cost | | | |

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Completed Date: 5-15-19 Completed Time: 3:30 By: AF JC

WORK ORDERS BY TYPE

Wrecc
WSKY

09:48:15


IST/TYPE: MISC

WORK ORDER NO : 50443

LED DATE: 05/20/19 SCHEDULED TIME: AM:

CTIONS: POSSIBLE LEAK, GO PAST THIS ADDRESS ABOUT TENTH OF A MILE ON THE RIGHT, NEW DRIVE WAY TO OLD

LOCATION:



R INFORMATION*****

E. SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
36577943 82614490 4975 A *

| ORY: | DATE | CURRENT | PREVIOUS | USAGE | PRIOR W/O | DATE | TYPE |
|------|----------|---------|----------|-------|-----------|----------|------|
| | 05/02/19 | 4975 | 4944 | 31 A | 8965 | 03/25/10 | AMR |
| | 04/02/19 | 4944 | 4917 | 27 A | 43359 | 06/19/17 | READ |
| | 03/04/19 | 4917 | 4891 | 26 A | 42231 | 03/03/17 | READ |
| | 02/04/19 | 4891 | 4851 | 40 A | 27780 | 12/06/12 | READ |

*****MISC

Call Date: 5/21/19 Arrival Time: 7:30

| Labor Cost | | | | Parts | | | |
|-------------|------|------|------|------------------------|-------------------|-------|-------|
| Employee | Time | Rate | Cost | Part Description | Used / Ret # | GL # | Cost |
| JD | 3hrs | | | 3/4" Comp Coupling #91 | used 4 | 620.6 | 61.18 |
| DB | 3hrs | | | 3/4" Inserts #89 | used 7 | 833.4 | 81.26 |
| | | | | 3/4" tubing #333 | used left + 333.4 | | 1.37 |
| Total Cost: | | | | Total Cost: | | | |

| Vehicle | Time | Rate | Cost |
|-------------|------|------|------|
| 0 | 3hrs | | |
| Total Cost: | | | |
| Equipment | Time | Rate | Cost |
| 7.5 | 3hrs | | |
| Total Cost: | | | |

Bud Called 5-21-19 Conf. # 1905210305
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 288,000 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of interruption: _____
 Comments: _____

Called Date: 5/21/19 Completed Time: 10:30 By: JD DB

WORK ORDERS BY TYPE

08:37:23

KLIST/TYPE: ANGL

WORK ORDER NO : 50420

SCHEDULED DATE: 05/15/19 SCHEDULED TIME: AM:

INSTRUCTIONS: POSSIBLE ANGLE VALVE, CUSTOMER CALLED AND WATER IS LEAKING INSIDE THE METER BOX BY THE METER. PLEASE CHECK THIS OUT

37.279514
86.210305

LOCATION: LEFT SIDE OF DRIVE

7968.04

IN: 10/13/10



| OLD METER INFORMATION | | | | NEW METER INFORMATION***** | | | |
|-----------------------|--------|----------|---------|----------------------------|--------|--------|-------|
| SIZE | TYPE | USE | DATE | MAKE | SERIAL | REMOTE | MXUID |
| 5/8 in. | G | | 04/17 | | | | |
| 40352564 | REMOTE | MXUID | CURRENT | MAKE | SERIAL | REMOTE | MXUID |
| | | 82885178 | 1225 A | | | | |

| STORY: | DATE | CURRENT | PREVIOUS | USAGE | PRIOR W/O | DATE | TYPE |
|--------|----------|---------|----------|-------|-----------|----------|-------|
| | 04/17/19 | 1225 | 1218 | 7 A | 39282 | 05/19/16 | MISC |
| | 03/18/19 | 1218 | 1209 | 9 A | 49605 | 02/28/19 | ANGLE |
| | 02/18/19 | 1209 | 1198 | 11 A | 49593 | 02/27/19 | MISC |
| | 01/18/19 | 1198 | 1189 | 9 A | 41706 | 01/03/17 | MNLK |

Arrival Date: 5-15-19 Arrival Time: 1:00

| Labor Cost | | | | Parts | | | |
|------------|------|------|------|------------------|--------------|-------|-------|
| Employee | Time | Rate | Cost | Part Description | Used / Ret # | GL # | Cost |
| MH | 30m | | | Angle valve #87 | U-1 | 020.6 | 29.19 |
| JL | 30m | | | | | | |
| AA | 30m | | | | | | |
| Total Cost | | | | Total Cost | | | |

| Vehicle | Time | Rate | Cost |
|------------|------|------|------|
| E-150 | 30m | | |
| Total Cost | | | |

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Completed Date: 5-15-19 Completed Time: 1:30 By: JL AA

WORK ORDERS BY TYPE

16:25:29

1ST/TYP: ANGLE
 LED DATE: 05/13/19 SCHEDULED TIME: PM:
 CTIONS: PER WO # 50394...ANGLE VALVE NEEDS REPLACED

WORK ORDER NO : 50412

37.305270
 86.286947

LOCATION: 1' RD 1ST DR 15' OF RD

IN: 05/10/19



***** OLD METER INFORMATION ***** NEW METER INFORMATION *****

5/8 in. TY: G USE: 0 05/06 *
 E SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 41940191 86859033 220 E *
 *
 *

ORY: DATE CURRENT PREVIOUS USAGE PRIOR W/O DATE TYPE

***** ANGL

Date: 5-14-19 Arrival Time: 1:00

| Labor or Cost | | | | Parts | | | |
|---------------|------|------|------|------------------|--------------|-------|-------|
| Employee | Time | Rate | Cost | Part Description | Used / Ret # | GL # | Cost |
| SH | 1m | | | Angle Valve #87 | 0-1 | W.D.P | 29.19 |
| JC | 30m | | | | | | |
| AF | 30m | | | | | | |
| Total Cost | | | | Total Cost | | | |
| hole | Time | Rate | Cost | | | | |
| 150 | 30m | | | | | | |
| Total Cost | | | | Total Cost | | | |

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

| Comment | Time | Rate | Cost |
|------------|------|------|------|
| | | | |
| Total Cost | | | |

ated Date: 5-14-19 Completed Time: 1:30 By: JC AF

WORK ORDERS BY TYPE


13:30:17

LIST/TY: SRLK
 SCHEDULED DATE: 05/09/19 SCHEDULED TIME: PM:
 ACTIONS: SERVICE LINE LEAK

WORK ORDER NO : 50387

LOCATION: RIGHT CORNER OF YARD

IN: 04/22/10



***** INFORMATION*****

| KEY SERIAL | REMOTE | MXUID | CURRENT | MAKE | SERIAL | REMOTE | MXUID |
|------------|--------|----------|---------|------|--------|--------|-------|
| 36599353 | | 82617612 | 5333 A | | | | |

| TORY: | DATE | CURRENT | PREVIOUS | USAGE | PRIOR W/O | DATE | TYPE |
|-------|----------|---------|----------|-------|-----------|----------|------|
| | 12/09/15 | 5333 | 5315 | 92 A | 42662 | 04/13/17 | PERD |
| | 12/02/15 | 5315 | 5223 | 92 A | 37682 | 12/08/15 | PULL |
| | 11/02/15 | 5223 | 5175 | 48 A | 9805 | 04/14/10 | AMR |
| | 10/02/15 | 5175 | 5094 | 81 A | | | |

Arrival Date: 5/13/19 Arrival Time: 1:00

| Employee | Time | Rate | Cost |
|------------|-------|------|------|
| | 5 min | | |
| | 1 hr | | |
| | 1 hr | | |
| Total Cost | | | |
| Vehicle | Time | Rate | Cost |
| | 1 hr | | |
| Total Cost | | | |
| Equipment | Time | Rate | Cost |
| | 1 hr | | |
| Total Cost | | | |

| Part Description | Used / Ret # | GL # | Cost |
|------------------------|--------------|-------|-------|
| 3/4" Comp Coupling #91 | Used 2 | 620.6 | 30.59 |
| 3/4" Inserts #89 | Used 4 | 333.4 | 4.72 |
| 3/4" Flow Coupling #93 | Used 1 | 620.6 | 4.45 |
| 3/4" tubing #33 | Used 5 | 333.4 | 1.14 |
| Total Cost | | | |

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 93/1000 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: Will need clean up

Completed Date: 5/13/19 Completed Time: 2:00 By: JD AR

WORK ORDERS BY TYPE

13:30:36

LIST/TY: ANGL

WORK ORDER NO : 50388

LED DATE: 05/09/19 SCHEDULED TIME: PM:

ACTIONS: ANGLE VALVE

37.122303

86.144095

LOCATION: LEFT SIDE OF DRIVE

2044.99

IN: 03/23/10

OLD METER INFORMATION** NEW METER INFORMATION*****

5/8 in. TY: G USE: 11 05/02 *
KE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
36578516 82612739 3073 A *

Table with columns: HISTORY, DATE, CURRENT, PREVIOUS, USAGE, PRIOR W/O, DATE, TYPE. Includes rows for 04/02/19, 03/04/19, 02/04/19, 01/02/19.

Arrival Date: 5-9-19 Arrival Time: 9:00

Table with columns: Labor Cost, Employee, Time, Rate, Cost. Includes entries for MH, D, and equipment.

Table with columns: Parts, Part Description, Used / Ret#, GL#, Cost. Includes entries for 3/4 Angle Valve #087 and Washers #255.

Form with fields: Bud Called, Conf. #, Bill Yes or No / Miles, Adj. Bill Yes or No / GPM, Est. loss, Gal. Flushed, Cause Of Leak, Time occurred, Length of interruption, Comments.

Completed Date: 5-9-19 Completed Time: 945 By: JD DB

WORK ORDERS BY TYPE

07:57:25

LIST/TY: MNLKV
 SCHEDULED DATE: 05/07/19 SCHEDULED TIME: AM:
 ACTIONS: MAIN LINE LEAK AND REPLACE VALVE

WORK ORDER NO : 50347

LOCATION: IN WOODS BEFORE DRIVE

IN: 04/12/18



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

5/8 in. TY: G USE: 68 05/02 *
 MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 41942729 83281961 656 A *
 *
 *

| CATEGORY: | DATE | CURRENT | PREVIOUS | USAGE | PRIOR W/O | DATE | TYPE |
|-----------|----------|---------|----------|-------|-----------|------|------|
| | 04/02/19 | 588 | 540 | 48 | A | | |
| | 03/04/19 | 540 | 491 | 49 | A | | |
| | 02/04/19 | 491 | 425 | 66 | A | | |
| | 01/02/19 | 425 | 365 | 60 | A | | |

*****MNLK

Arrival Date: 5-3-19 Arrival Time: 9:30

| Labor Cost | | | | Parts | | | |
|------------|-------|------|------|---|--------------|-------|--------|
| Employee | Time | Rate | Cost | Part Description | Used / Ret # | GL # | Cost |
| MH | 5 min | | | 8" Pipe #50' | Used 35' | 620.4 | 162.37 |
| TO | 7hr | | | 8" Couplings #401 | Used 3 | 620.6 | 269.97 |
| DH | 7hr | | | 8" RS Valve #426 | Used 1 | 620.4 | 701.52 |
| JA | 7hr | | | Value Box 24"x36" #271 | Used 1 | 620.4 | 39.19 |
| | | | | 3/4 Brass Coupling ⁰⁸⁴ 620.4 | Used 1 | 620.4 | 15.30 |
| | | | | 3/4 Inserts ⁰⁸⁴ used 3 | | | |
| Total Cost | | | | Total Cost | | | |
| Vehicle | Time | Rate | Cost | | | | |
| 150 | 7hr | | | | | | |
| Total Cost | | | | | | | |
| Equipment | Time | Rate | Cost | | | | |
| | 7hr | | | | | | |
| Total Cost | | | | | | | |

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ 3rd Adj. Bill Yes or No / GPM _____
 Est. loss 250,000 Gal. Flushed 300,000
 Cause Of Leak: Rock Time occurred: _____
 Length of Interruption: _____
 Comments: Will need Grant to Clean UP

#039 4
 used 1-8" saddle
 used 1-3/4" corp stop
 #083
 333.4
 27.94

Completed Date: 5-3-19 Completed Time: 4:30 By: TO DH JA

WORK ORDERS BY TYPE

09:05:41

✓
CHECKLIST/TYPER: PULL

WORK ORDER NO : 50329


SCHEDULED DATE: 05/03/19 SCHEDULED TIME: AM:

INSTRUCTIONS: PLEASE PULL METER AND REMOVE METER SERVICE PER CUSTOMERS REQUEST

37.286756
86.219305

WORKER LOCATION: BEFORE HYD

IN: 08/31/18



***** INFORMATION *****

| MAKE SERIAL | REMOTE | MXUID | CURRENT | * | MAKE SERIAL | REMOTE | MXUID |
|-------------|--------|----------|---------|---|-------------|--------|-------|
| 50003789 | | 87615862 | A | * | | | |
| 50003789 | | 87615862 | 10 | * | | | |
| | | | | * | | | |

| HISTORY: | DATE | CURRENT | PREVIOUS | USAGE | PRIOR W/O | DATE | TYPE |
|----------|----------|---------|----------|-------|-----------|----------|------|
| | 03/18/19 | 0 | 0 | 0 A | 48071 | 08/31/18 | HANG |
| | 02/18/19 | 0 | 0 | 0 A | 40560 | 09/06/16 | DISC |
| | 01/18/19 | 0 | 0 | 0 A | 38909 | 04/14/16 | HANG |
| | 12/18/18 | 0 | 0 | 0 A | | | |

Arrival Date: 5-7-19 Arrival Time: 7:30

| Labor Cost | | | |
|------------|------|------|------|
| Employee | Time | Rate | Cost |
| MH | 5hr | | |
| DB | 2hr | | |
| JD | 2hr | | |
| Total Cost | | | |
| Vehicle | | | |
| Vehicle | Time | Rate | Cost |
| 8 | 2hr | | |
| Total Cost | | | |
| Equipment | | | |
| Equipment | Time | Rate | Cost |
| TH | 2hr | | |
| Total Cost | | | |

| Parts | | | |
|-----------------------|--------------|-------|-------|
| Part Description | Used / Ret # | GL # | Cost |
| 3/4" Comp. Coupl. #91 | used-2 | 620.6 | 30.59 |
| 3/4" Flow #93 | used-1 | 620.6 | 4.45 |
| 3/4" Inserts #89 | used-4 | 333.4 | 4.72 |
| 3/4" Tubing #333 | used-4ft | 333.4 | .91 |
| Total Cost | | | |

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: put meter on to be tested

Completed Date: 5-7-19 Completed Time: 9:30 By: DB JD

WORK ORDERS BY TYPE

08:42:49

LIST/TYPE: SRLK
 SCHEDULED DATE: 04/29/19 SCHEDULED TIME: AM:
 ACTIONS: SERVICE LINE LEAK

WORK ORDER NO : 50302

*Ridge
 Chest*

37.355048
 86.160392

LOCATION: IN FRONT OF HOUSE

IN: 11/04/10



***** OLD METER INFORMATION ***** NEW METER INFORMATION *****

5/8 in. TY: G USE: 0 04/17 *
 MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 40356000 83005473 762 A *
 *
 *
 *

 HISTORY: DATE CURRENT PREVIOUS USAGE PRIOR W/O DATE TYPE
 04/17/19 762 762 0 A 6389 08/13/09 READ
 03/18/19 762 762 0 A 40139 07/21/16 SRLK
 02/18/19 762 762 0 A 31099 01/16/14 READ
 01/17/19 762 762 0 A 15110 10/21/10 AMR

 *****SRLK

Start Date: 5-3-19 Arrival Time: ~~5:00~~ 1:30

| Employee | Time | Rate | Cost |
|------------|-----------|------|------|
| AL | 5 min | | |
| DB | 1 1/2 hrs | | |
| JD | 1 1/2 hrs | | |
| Total Cost | | | |
| Vehicle | Time | Rate | Cost |
| 8 | 1 1/2 hrs | | |
| Total Cost | | | |
| Payment | Time | Rate | Cost |
| H | 1 1/2 hrs | | |
| Total Cost | | | |

| Parts | | | |
|------------------------|--------------|-------|-------|
| Part Description | Used / Ret # | GL # | Cost |
| #91 Compression Coupl. | Used-2 | 410.6 | 30.59 |
| 3/4" tubing #333 | Used-3 Ft | 333.4 | .68 |
| Total Cost | | | |

Bud Called 4-30-19 Conf. # 1904300310
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____

Comments: Service Line

Start Date: 5-3-19 Completed Time: 3:00 By: DB JD

WORK ORDERS BY TYPE

08:20:24

BOX

KLIST/TYPE: SRLK

WORK ORDER NO : 50080


SCHEDULED DATE: 04/18/19 SCHEDULED TIME: AM:

INSTRUCTIONS: SERVICE LINE LEAK CUSTOMER SENT E MAIL SAYING IT HAS BEEN WET ON THE OTHER SIDE OF HIS WATER MAIN REGARDLESS OF WEATHER WOULD LIKE IT CHECKED

37.273011
86.217060

LOCATION: BEHIND BUSH CENTER OF TRAILER

IN: 09/20/10



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

| | | | | | | | | |
|----------------------|-----------------|------------|-----------|---|------|--------|--------|-------|
| SIZE: 5/8 in. | TY: G | USE: 51 | 03/18 | * | | | | |
| MAKE SERIAL 40352988 | REMOTE 83010346 | MXUID 5539 | CURRENT A | * | MAKE | SERIAL | REMOTE | MXUID |

| STORY: | DATE | CURRENT | PREVIOUS | USAGE | PRIOR W/O | DATE | TYPE |
|--------|----------|---------|----------|-------|-----------|----------|------|
| | 03/18/19 | 5539 | 5488 | 51 A | 37691 | 12/08/15 | DISC |
| | 02/18/19 | 5488 | 5433 | 55 A | 40796 | 09/26/16 | SRLK |
| | 01/18/19 | 5433 | 5368 | 65 A | 49270 | 01/11/19 | SRLK |
| | 12/17/18 | 5368 | 5323 | 45 A | 37726 | 12/10/15 | REHA |

Call Date: 5-1-19 Arrival Time: 12:30

| Labor Cost | | | | Parts | | | |
|------------|------|------|------|------------------|--------------|-------|-------|
| Employee | Time | Rate | Cost | Part Description | Used / Ret # | GL# | Cost |
| M | 3min | | | 3/4 coupling #91 | used 2 | 620.6 | 30.59 |
| IF | 2h | | | 3/4 insert #89 | used 3 | 333.4 | 3.54 |
| IC | 2h | | | 3/4 Tubing #333 | used 5 Foot | 333.4 | 1.14 |
| DH | 2h | | | | | | |
| Total Cost | | | | Total Cost | | | |

Bud Called 4-30-19 Conf. # 190430.0301

Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____

Est. loss _____ Gal. Flushed _____

Cause Of Leak: _____ Time occurred: _____

Length of interruption: _____

Comments: Small service line leak edge of garage driveway Needs Clean UP

Completed Date: 5-1-19 Completed Time: 2:30 By: AF JC DH

Please prepare

LEC

WORK ORDERS BY TYPE

wycc wsty

13:32:56

SRLK ✓
04/23/19 SCHEDULED TIME: PM:
SERVICE LINE LEAK

WORK ORDER NO : 50216

POOR

37.113719
86.149605

LEFT CORNER OF [REDACTED]

2292-87
IN: 03/25/10



***** OLD METER INFORMATION ***** NEW METER INFORMATION *****

| | | | | | | | | |
|-------------|--------|----------|---------|---|------|--------|--------|-------|
| 5/8 in. | TY: G | USE: 12 | 04/02 | * | | | | |
| MAKE SERIAL | REMOTE | MXUID | CURRENT | * | MAKE | SERIAL | REMOTE | MXUID |
| 36577901 | | 82613485 | 2168 A | * | | | | |

***** HISTORY: *****

| DATE | CURRENT | PREVIOUS | USAGE | PRIOR W/O | DATE | TYPE |
|----------|---------|----------|-------|-----------|----------|------|
| 04/02/19 | 2168 | 2156 | 12 A | 8823 | 03/16/10 | AMR |
| 03/04/19 | 2156 | 2146 | 10 A | 32450 | 05/21/14 | SRLK |
| 02/04/19 | 2146 | 2132 | 14 A | 31225 | 01/27/14 | SRLK |
| 01/02/19 | 2132 | 2121 | 11 A | 15018 | 10/15/10 | SRLK |

Arrival Date: 5-1-19 Arrival Time: 8:30

| Employee | Time | Rate | Cost |
|-------------|------|------|------|
| NTT | 5m | | |
| JC | 1h | | |
| AP | 1h | | |
| OH | 2h | | |
| Total Cost: | | | |
| Vehicle | Time | Rate | Cost |
| -150 | 1h | | |
| Total Cost: | | | |
| Equipment | Time | Rate | Cost |
| H | 1h | | |
| Total Cost: | | | |

| Parts | | | |
|-------------------|--------------|-------|-------|
| Part Description | Used / Ret # | GL # | Cost |
| 3/4" coupling #91 | 0-2 | 620.4 | 30.59 |
| 3/4" inserts #89 | 0-4 | 333.4 | 4.72 |
| 3/4" Flow #93 | 0-1 | 620.4 | 4.45 |
| 3/4" tubing #333 | 0-2A | 333.4 | .46 |
| Total Cost: | | | |

Bud Called 4-30-19 Conf. # 1904300379

Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____

Est. loss _____ Gal. Flushed _____

Cause Of Leak: _____ Time occurred: _____

Length of Interruption: _____

Comments: need clean up

Completed Date: 5-1-19 Completed Time: 9:30 By: JC AH AF