

WORK ORDERS BY TYPE

13:39:51

LIST/TYPE: MISC
 SCHEDULED DATE: 07/25/19 SCHEDULED TIME: PM:
 INSTRUCTIONS: SET FILL HYDRANT RIDGECREST /FROM


WORK ORDER NO : 51131



PH cleared

LOCATION:

IN:



NEW METER INFORMATION

MAKE	SERIAL	REMOTE	MXUID	CURRENT	MAKE	SERIAL	REMOTE	MXUID
5/8 in.		TY: G	USE: 0	*				

 HISTORY: DATE CURRENT PREVIOUS USAGE PRIOR W/O DATE TYPE

***** MISC
 Date: 7-31-19 Arrival Time: 7:30

Time	Rate	Cost
5hr		
5hr		
Total Cost		
1hr		
Total Cost		
2hr		
Total Cost		

Part Description	Used / Ret #	GL #	Cost
3" #546 MJ Restraint	used-6	620.0	262.65
3" #277 Gate valve BS MJ	used-2	620.0	344.82
24"x36" #471 Valve Box	used-1	620.0	39.02
3" #405 GI-200 PVC	used-8	620.0	7.25
#539 Per T.S. #540 PH 2x4 3/4" BAY	used-1	305.4	715.00
3" Tee #303	used-1		

Parts made 715.00

Bud Called _____ Conf. # 1907231517
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

WORK ORDERS BY TYPE

15:10:28

ST/TY: MNLK

WORK ORDER NO : 51021

ED DATE: 07/19/19 SCHEDULED TIME: PM:

IONS: MAIN LINE LEAK

37.261893
86.370275

LOCATION: 20 FT RIGHT SIDE DRIVE

IN: 07/07/15



OLD METER INFORMATION***** NEW METER INFORMATION*****

5/8 in. TY: G USE: 33 07/02 *
SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
40355618 83005083 2644 A *
*
*
*

RY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	07/02/19	2644	2611	33 A	46088	02/22/18	READ
	06/03/19	2611	2568	43 A	49620	03/04/19	READ
	05/02/19	2568	2516	52 A	49099	12/18/18	VOID
	04/02/19	2516	2461	55 A	46088	02/22/18	READ

*****MNLK

Time	Rate	Cost
4 hrs		
4 hrs		
4 hrs		
4 hrs		
Total Cost		
4 hrs		
4 hrs		
Total Cost		
4 hrs		
Total Cost		

Parts		Used / Ret #	GL #	Cost
6" coupling #399	U-2	620.6	42.34	
6" pipe #499	U-12F+	620.6	40.44	
Total Cost				

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

7-19-19 Completed Time: 6:00 By: JC DB JD AF

WORK ORDERS BY TYPE

08:20:21

LEC

IST/TY: LEAK
 LED DATE: 07/09/19 SCHEDULED TIME: AM
 CTIONS: 8" LINE LEAK ACROSS RD FROM

WORK ORDER NO : 50936

LOCATION:

IN:

 [REDACTED LOCATION]

 OLD METER INFORMATION*** NEW METER INFORMATION*****
 5/8 in. TY: G USE: 0 *
 E SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 *
 *
 *

 MORY: DATE CURRENT PREVIOUS USAGE PRIOR W/O DATE TYPE

*****LEAK
 te: 7-5-19 Arrival Time: 3:30

Cost	Time	Rate	Cost
	3hrs		
	3hrs		
	3hrs		
	3hrs		
Total Cost			
	3hrs		
	3hrs		
Total Cost			
	3hrs		
Total Cost			

Parts		Used / Ret #	GL #	Cost
8" Repair	coupl #40	used-2	120.6	179.98
8" Pipe	#501	used-15ft	120.6	82.66
Total Cost				

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 323,000 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

WORK ORDERS BY TYPE

13:43:49

LIST TYPE: MNLK ✓
SCHEDULED DATE: 07/25/19
ACTIONS: MAIN LINE


WORK ORDER NO : 51132

SCHEDULED TIME: PM:



LOCATION:

IN:



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

5/8 in. TY: G USE: 0 *
SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
*
*
*
*

ISTORY: DATE CURRENT PREVIOUS USAGE PRIOR W/O DATE TYPE

*****7/24/19 Arrival Time: 7:30*****MNLK

Time	Rate	Cost
4hrs		
4hrs		
4hrs		
Total Cost		
Time	Rate	Cost
4hrs		
4hrs		
Total Cost		
Time	Rate	Cost
4hrs		
Total Cost		

Parts			
Part Description	Used / Ret #	GL#	Cost
8" pvc Coupling #401	Used 2	6204	179.97
8" pvc pipe # 501	Used 1	6204	33.06
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 345,600 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

WORK ORDERS BY TYPE

09:45:37

LIST/TYPER: RBOX

WORK ORDER NO : 51028


FILED DATE: 07/22/19 SCHEDULED TIME: AM:

ACTIONS: UNCOVER METER BOX /REPLACE METER BOX

37.353818
86.124261

LOCATION: LEFT SIDE OF THE DRIVEWAY

IN: 08/12/11



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

5/8 in. TY: G USE: 3 07/19 *
 MAKE SERIAL REMOTE MKUID CURRENT * MAKE SERIAL REMOTE MKUID
 41943478 83432661 1020 A *
 *
 *

STORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	06/18/19	1017	1012	5 A	20127	08/09/11	AMR
	05/21/19	1012	1007	5 A	30973	12/19/13	MISC
	04/18/19	1007	1001	6 A	30875	11/22/13	MISC
	03/20/19	1001	998	3 A	29962	08/22/13	MISC

*****RBOX

Date: 7/25/19 Arrival Time: 12:30

Time	Rate	Cost
5 min		
1 1/2 hrs		
1 1/2 hrs		
1 1/2 hrs		
Total Cost		
Time	Rate	Cost
1 1/2 hrs		
1 1/2 hrs		
Total Cost		
Time	Rate	Cost
1 1/2 hrs		
Total Cost		

Parts			
Part Description	Used / Ret #	GL #	Cost
#459 dual plastic box	used 1	620.6	86.36
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Date: 7/25/19 Completed Time: 2:00 By: JD DB AR

WORK ORDERS BY TYPE

15:33:08


IST/TYPE: MNLK
 LED DATE: 07/10/19 SCHEDULED TIME: PM:
 CTIONS: MAIN LINE LEAK

WORK ORDER NO : 50965

37.282478
 86.249352

LOCATION: 70' UP BANK 50' OF ROAD

8699 05
 IN: 04/05/12



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

5/8 in. TY: G USE: 37 07/02 *
 E SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 41940778 83431829 87 A *
 *
 *

DRY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	06/03/19	50	11	39 A	24035	04/11/12	RLID
	05/02/19	11	8	3 A	47398	07/09/18	SRLK
	04/02/19	8	8	0 A	44428	09/01/17	MISC
	03/04/19	8	8	0 A	31604	03/11/14	MISC

*****MNLK

7-9-19 Arrival Time: 2:30

Time	Rate	Cost
3hr		
3hr		
3hr		
3hr		
Total Cost		
3hr		
Total Cost		
3hr		
Total Cost		

Parts			
Part Description	Used / Ret #	GL #	Cost
4" x 12" Repair clamp # 375	used - 1	620.6	68.65
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 220,000 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Thurs June 13th 1000pm

WORK ORDERS BY TYPE

10:25:24

INST/TYPE: INSTA

WORK ORDER NO : 50694

SCHEDULED DATE: 06/20/19 SCHEDULED TIME: AM:

INSTRUCTIONS: PLEASE INSTALL 1 INCH METER FOR G OR

STAKED LINE SIZE (LONG OR SHORT DUAL OR REG) SETTING

LOCATION: 2" PVC IN:

***** [REDACTED] *****

5/8 in. TY: G USE: 0 SERIAL REMOTE MXUID CURRENT MA

RY: DATE CURRENT PREVIOUS USAGE PRIOR W/O DATE TYPE

***** ANGL

7/1/19 Arrival Time: 12:30

Parts			Part Description	Used / Ret #	GL #	Cost
Time	Rate	Cost				
1 hr	20.7551	20.7551				
3 hrs	25.1645	75.4935				
3 hrs	21.4317	64.2951				
Total Cost		110.5437				
Time	Rate	Cost				
3 hrs	10.00	30.00				
Total Cost		30.00				
Time	Rate	Cost				
3 hrs	35.00	105.00				
Total Cost		105.00				

(on back)

Bud Called 6/11/19 Conf. # 690661212
Bill Yes or No / Miles Adj. Bill Yes or No / GPM
Est. loss Gal. Flushed
Cause Of Leak: Time occurred:
Length of Interruption:

Total Cost \$945,0237

Time	Rate	Cost
3 hrs	35.00	105.00
Total Cost		105.00

7/1/19 Completed Time: 3:30 By: JD DB

Date: 6/14/19 (Time) 11:10 (Conf #) 1906111212 Meter Setting WPA downstream WPECC
Phone Located: Yes or No / Electric Located: Yes or No / Gas Located: Yes or No

Yes or No Yes Has property owner across road been notified: Yes or No

ng: Yes or No Yes

ame On Stake: Yes or no Yes

er Location: Right corner of property

ing: Read after ACC# 102-20500

er Information: _____

e: 6-14-19

Employee: _____



86931885

- 1 Meter: ID 48495927 Reading 10 #420 / 334.4 / 247.12
- 1 Meter Setter: Size 1" x 1" Type Reg #5 334.5 / 240.33
- 1 Service Saddle: Size 2" x 1" Type PVC #45 333.4 / 17.25
- 1 Corp. Stop: Size 1" #95 333.4 / 40.55
- 3 Inserts: Size 1" #101 333.4 / 2.89
- 8ft Tubing: Size 1" #331 333.4 / 2.45 Main Line distance from Center Line of Road: 21ft
- 1 Meter Box: Type Dual #459 420.4 / 59.03
- 3ft PVC Pipe: Size 1/2" #439 333.4 / 10.3ft PVC #493 - used 10ft 420.4 / 2.31
- Casing Pipe: Size _____ 2" PVC couplings - used 2 #393 420.4 / 18.15
- PRV: Size _____

WORK ORDERS BY TYPE

08:17:15

EST/TYPE: MNLK
 SCHEDULED DATE: 07/09/19
 ACTIONS: MAIN LINE LEAK

WORK ORDER NO : 50935

SCHEDULED TIME: AM: [REDACTED] 6" LINE LEAK

LOCATION: RIGHT OF GUIDE WIRE 6FT

IN: 03/26/10



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

3/4 in. TY: G USE: 0 06/09 *
 SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 36578363 A *
 *
 *

DRY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	06/09/10	0	0	0 A	50577	05/31/19	MISC
	06/03/10	0	0	0 A	46429	03/26/18	RBOX
	05/05/10	0	0	0 A	42648	04/13/17	MNLK
	04/07/10	0	0	0 A	10542	04/29/10	PULL

7-7-19 Arrival Time: 8:30

Time	Rate	Cost
5min		
8hrs		
8hrs		
8hrs		
8hrs		
Total Cost:		
8hrs		
8hrs		
8hrs		
Total Cost:		
8hrs		
Total Cost:		

Parts		Used / Ret #	GL #	Cost
16" PVC pipe #507	used - 25	1020.4		510.46
16" HD sleeve #475	used - 1	129.4		324.93
Total Cost:				

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 350,000 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

WORK ORDERS BY TYPE

09:31:07

EST/TYPE: MNLK
 SCHEDULED DATE: 07/30/19 SCHEDULED TIME: AM:
 WORK ORDER NO : 51158
 CONDITIONS: MAIN LINE LEAK - HIT A MAIN WATER LINE

LOCATION: FENCE

IN: 05/28/19

*****OLD METER INFORMATION***** NEW METER INFORMATION*****

5/8 in. TY: G USE: 10 07/17 *
 SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 40352658 82878627 2298 A *
 *
 *
 *

DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
07/17/19	2298	2288	10 A	50527	05/23/19	MISC
06/17/19	6008	6008	0 A	50867	06/27/19	MISC
06/17/19	2288	2288	0 A	50527	05/23/19	MISC

*****MNLK

7-30-19 Arrival Time: 10:30

Time / Rate / Cost			Parts			
Time	Rate	Cost	Part Description	Used / Ret #	GL#	Cost
5min			4" pvc pipe #497	used 5ft	620.6	5.81
1hr			4" Coupling pvc #397	used 2	620.6	53.07
1hr						
1hr						
Total Cost						
1hr			Total Cost			
1hr						
Total Cost						

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 24,000 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Completed Time: 11:30

WORK ORDERS BY TYPE

14:13:24

LIST/TY: MISC

WORK ORDER NO : 51065

FILED DATE: 07/23/19 SCHEDULED TIME: PM:

ACTIONS: NEIGHBOR CALLED IN AND WATER IS BUBBLING UP OUT OF THE METER BOX.

LOCATION: LEFT CORNER OF THE YARD

6489-13

IN: 06/07/13



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

5/8 in. TY: G USE: 1 10/07 *
 METER SERIAL REMOTE MKUID CURRENT * MAKE SERIAL REMOTE MKUID
 40352506 82883951 1074 A *
 *
 *

METER HISTORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	10/07/15	1074	1073	21 A	37098	10/06/15	DISC
	09/17/15	1073	1052	21 A	35563	05/06/15	REHA
	08/18/15	1052	1028	24 A	35545	05/05/15	DISC
	07/17/15	1028	1004	24 A	24193	04/12/12	MISC
	7-23-19						MISC

7-23-19 Arrival Time: 3:00

Time	Rate	Cost
30 min		
30 min		
Total Cost		
30 min		
Total Cost		
Time	Rate	Cost
Total Cost		

Parts			
Part Description	Used / Ret #	GL #	Cost
#147 cooling lock	01	620.6	15.93
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: Water Theft setter had jumper
That was leaking neighbor said on 7-19-19
The owner here pressure washed house all day and
water was leaking since

Date: 7-23-19 Completed Time: 3:30 By: AF JA

WORK ORDERS BY TYPE

13:35:58

LIST/TY: MISC

WORK ORDER NO : 50943

SCHEDULED DATE: 07/09/19 SCHEDULED TIME: PM:

INSTRUCTIONS: MISCELLANEOUS RAISE VALVE BOX IN DRIVEWAY

37.243413
86.279926

LOCATION: LEFT SIDE OF DRIVE BESIDE CORNER OF FENC 8231 04

IN: 08/24/10

***** OLD METER INFORMATION ***** NEW METER INFORMATION *****

5/8 in.	TY: G	USE: 26	07/02	*				
MAKE SERIAL	REMOTE	MXUID	CURRENT	*	MAKE	SERIAL	REMOTE	MXUID
40352796		83009731	4189 A	*				

DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
06/03/19	4163	4123	40 A	9500	03/31/10	SRLK
05/02/19	4123	4093	30 A	48011	08/24/18	SRLK
04/02/19	4093	4061	32 A	27472	10/25/12	MISC
03/04/19	4061	4033	28 A	12628	07/26/10	AMR

Date: 7-11-19 Arrival Time: 8:30

Time	Rate	Cost
3 min		
15		
15		
Total Cost		
30	15	
Total Cost		
Total Cost		

Part Description	Used / Ret #	GL #	Cost
Value Box Riser ²³¹	used 1	420.4	14.34
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Date: 7-11-19 Completed Time: 8:45 By: SD MT

WORK ORDERS BY TYPE

09:30:48

LIST/TYPE: MISC
 SCHEDULED DATE: 07/22/19 SCHEDULED TIME: AM:
 ACTIONS: REPLACE 3" VALVE AT

WORK ORDER NO : 51027

37.339166
 86.211545

LOCATION: RIGHT CORNER OF HOUSE

4699 01
 IN: 04/23/12

***** OLD METER INFORMATION ***** NEW METER INFORMATION *****

5/8 in. TY: G USE: 85 07/03 *
 SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 43603531 84429871 1623 A *

DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
07/03/19	1623	1538	85 A			
06/03/19	1538	1436	102 A	47769	08/14/18	VOID
05/03/19	1436	1349	87 A	47760	08/13/18	READ
04/03/19	1349	1268	81 A	24273	04/13/12	AMR

***** MISC

Arrival Time: 12:00

Time	Rate	Cost
5hrs		
5hrs		
5hrs		
Total Cost		
5hrs		
5hrs		
Total Cost		
5hrs		
Total Cost		

Part Description	Used / Ret #	GL #	Cost
3" gate valve m/j #277	used 1	620.4	344.82
3" m/j pul w/ flange #546	used 1	620.4	33.77
3" pul coupling #395	used 1	620.4	17.52
3" pul pipe #495	used 4ft	620.4	3.62
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 144,000 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Completed Time: 1:00 By: JDM AT AF

WORK ORDERS BY TYPE

14:13:31

IST/TYPE: SRLK

WORK ORDER NO : 51173

LED DATE: 07/31/19 SCHEDULED TIME: PM:

CTIONS: SERVICE LINE LEAK [REDACTED] CALLED SAID THERE IS WATER COMING UP ABOUT 50 FT FROM DRIVE NEXT TO RD

37.090319
86.076868

LOCATION: RIGHT CORNER YARD

IN: 03/23/10



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

5/8 in. TY: G USE: 54 07/02 *
E SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
36578491 82612726 8417 A *

MORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	07/02/19	8417	8363	54 A			
	06/03/19	8363	8295	68 A	36670	08/20/15	SRLK
	05/02/19	8295	8256	39 A	8744	03/16/10	AMR
	04/02/19	8256	8224	32 A			

*****Arrival Time***** SRLK

ist	Time	Rate	Cost	Parts	Used / Ret #	GL #	Cost
7-31-19	3min			#91			
	3hrs			3/4" Compression coupling	Used-2	620.6	30.60
	2hrs			3/4" Insert # 89	Used-4	333.4	4.72
	3hrs			3/4" Flow # 93	Used-1	620.6	4.45
	3hrs			3/4" Tubing # 333	Used-4	333.4	9.57
Total Cost				Total Cost			

Bud Called _____ Conf. # 1907312045

Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____

Est. loss 144,000 Gal. Flushed _____

Cause Of Leak: _____ Time occurred: _____

Length of Interruption: _____

Comments: _____

Time	Rate	Cost
3hrs		
Total Cost		

Date: 7-31-19 Completed Time: 6:30 By: Dylan

WORK ORDERS BY TYPE

08:30:24

ST/TYPE: SRLK
 ED DATE: 07/31/19 SCHEDULED TIME: AM:
 TIONS: SERVICE LINE LEAK

WORK ORDER NO : 51165

37.320595
 86.177348

LOCATION: BACK RANCH, 20' LEFT OF DRIVE

4116-89
 IN: 08/16/10



 *OLD METER INFORMATION***** NEW METER INFORMATION*****

5/8 in. TY: G USE: 5 07/17 *
 SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 40353876 83010815 4355 A *
 *
 *

RY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	07/17/19	4355	4350	5 A	36530	08/03/15	LEAK
	06/17/19	4350	4343	7 A	42634	04/11/17	MNLK
	05/20/19	4343	4335	8 A	39210	05/11/16	SRLK
	04/17/19	4335	4328	7 A	37623	11/25/15	MISC
							SRLK

Time	Rate	Cost
5 min		
1/2 hr		
1/2 hr		
Total Cost		
Time	Rate	Cost
1/2 hr		
Total Cost		

Part Description	Used / Ret #	GL #	Cost
3/4" Compression Coping #91	used-2	620.6	30.60
3/4" Insert #89	used-4	333.4	4.72
3/4" Tubing #333	used-3ft	333.4	.68
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 180,000 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Date: 7-30-19 Completed Time: 3:30 By: [Redacted] MT

WORK ORDERS BY TYPE

09:34:36


WT/TYPE: SRLK
 ND DATE: 07/29/19 SCHEDULED TIME: AM:
 IONS: SERVICE LINE LEAK AT [REDACTED]

WORK ORDER NO : 51148

37.240298
 86.275672

LOCATION: ACROSS FENCE IN LINE R CORNER HOUSE

2285-87
 IN: 08/20/10



07/29/19 BY: MARCIE COMPLETED:
 OLD METER INFORMATION***** NEW METER INFORMATION*****
 5/8 in. TY: G USE: 25 07/02 *
 SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 0352779 83010559 1955 A *
 *
 *

RY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	07/02/19	1955	1930	25 A	12585	07/26/10	AMR
	06/03/19	1930	1911	19 A	28126	01/28/13	SRLK
	05/02/19	1911	1892	19 A	28104	01/23/13	ANGL
	04/02/19	1892	1880	12 A	18682	04/25/11	SRLK

37-19 Arrival Time: 1:00

			Parts			
Time	Rate	Cost	Part Description	Used / Ret #	GL #	Cost
1hr 15m			3/4 Brass Comp. Coupling #91	4-2	620.6	30.16
1hr 15m			3/4 ss inserts #89	4-3	333.4	3.54
			3/4 service Tubing #333	4-1 FT	333.4	.29
Total Cost						
1hr 15m			Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Time	Rate	Cost
1hr 15m		

WORK ORDERS BY TYPE

Wrong
Part #

09:17:03

CKLIST/TY: MNLK
 E: 07/29/19 SCHEDULED TIME: AM:
 ISTRUCTIONS: REPAIR WATER MAIN 3" [REDACTED]

WORK ORDER NO : 51144

37.319910
 86.222857

ER LOCATION: BEHIND LIGHT POLE/ 20' OF RD

5941-90
 IN: 03/26/12

 [REDACTED]

*****OLD METER INFORMATION***** NEW METER INFORMATION*****
 E: 5/8 in. TY: G USE: 3 07/03 *
 MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 41940613 83282594 504 A *
 *
 *

HISTORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	07/03/19	504	501	3 A			
	06/04/19	501	500	1 A	48821	11/26/18	LEAK
	05/02/19	500	497	3 A	23391	03/16/12	AMR
	04/03/19	497	497	0 A			

Date: 7-28-19 Arrival Time: 4:00 *****MNLK

Cost	Time	Rate	Cost	Part Description	Used / Ret #	GL#	Cost
2H	7hr			#89 Inserts	03	333.4	3.54
	7hr			#91 coupling	02	420.6	30.60
	7hr			#333 tubing 3"	8ft	333.4	1.82
				#47 serv. saddle	01	333.4	18.47
Total Cost				#83 coup stop	01	333.4	28.29
Total Cost				Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 25,000 Gal. Flushed 20,000
 Cause Of Leak: Rock Time occurred: 2:00
 Length of Interruption: 8 1/2 hrs.
 Comments: LOOK ON BACK

95 Pipe 3" CL200 U 4ft 620.4/3.102

5 Repair coupling 3" U 2 620.4/35103

~~NO#~~
51144

WORK ORDERS BY TYPE

13:32:51

LIST/TYPE: SRLK

WORK ORDER NO : 51130

LED DATE: 07/25/19 SCHEDULED TIME: PM:

ACTIONS: SERVICE LINE LEAK CUSTOMER CALLED SAYS WATER IS BUBBLING UP BY MAIL BOX JUST BEFORE METER THINKS IT IS OUR LEAK

37.158918
86.225879

LOCATION: 10' LEFT SIDE GRAVEL ROAD

3470 88
IN: 10/05/18



***** OLD METER INFORMATION ***** NEW METER INFORMATION *****

5/8 in. TY: G USE: 45 07/02 *
SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
36597839 82615508 1384 A *
*
*
*

CATEGORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	07/02/19	1384	1339	45 A	1423	06/05/08	MISC
	06/03/19	1339	1292	47 A	47908	08/22/18	PERIO
	05/02/19	1292	1250	42 A	30946	12/12/13	BUST
	04/02/19	1250	1214	36 A	8458	03/16/10	AMR

7-31-19 Arrival Time: 8:00

ist	Time	Rate	Cost
	3min		
	1hr 15m		
	1hr 15m		
Total Cost			
ist	Time	Rate	Cost
	1hr 15m		
Total Cost			
ist	Time	Rate	Cost
	1hr 15m		
Total Cost			

Parts		Used / Ret #	GL #	Cost
3/4 Brass Lamp Coupling #91	U-2	1020.4		30.20
3/4 ss inserts #89	U-3	333.4		3.54
3/4 Service Tubing #333	U-1FT	333.4		.23
Total Cost				

Bud Called _____ Conf. # 190 725 2048
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM Called in non-emerg.
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: Small service line leak long service probably leaking under road.

WORK ORDERS BY TYPE

10:36:10

NGL

WORK ORDER NO : 51107

DATE: 07/24/19 SCHEDULED TIME: AM:
 ACTIONS: REPLACE ANGLE VALVE AT [REDACTED]

LOCATION: UNDER LOCUST TREE

IN:



***** OLD METER INFORMATION ***** NEW METER INFORMATION *****

5/8 in.	TY: G	USE: 0	02/25	*				
MAKE SERIAL	REMOTE	MXUID	CURRENT	*	MAKE	SERIAL	REMOTE	MXUID
NONE			71	*				
				*				
				*				

***** HISTORY: DATE CURRENT PREVIOUS USAGE PRIOR W/O DATE TYPE *****

***** ANGL *****
 7-25-19 Arrival Time: 8:00

Time	Rate	Cost
5:00		
1 hr 20 min		
1 hr 20 min		
Total Cost		
Time	Rate	Cost
1 hr 20 min		
Total Cost		
Time	Rate	Cost
Total Cost		

Parts		Used / Ret #	GL #	Cost
3/4 Brass angle valve	#87	4-1	620.6	29.19
24" PLASTIC Meter Box	#457	4-1	334.5	59.04
Total Cost				

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

7-25-19 Completed Time: 9:20 By: MT JB

WORK ORDERS BY TYPE

08:50:31

LIST/TYPE: SRLK ✓ WORK ORDER NO : 51102

SCHEDULED DATE: 07/24/19 SCHEDULED TIME: AM:

ACTIONS: POSSIBLE SERVICE LINE LEAK, CUSTOMER CALLED IN SAYING THEY TALKED TO THE ON CALL GUY AND WATER IS STILL LEAKING AND GOING DOWN THROUGH THE DITCH

37.093745
86.115138

LOCATION: LEFT SIDE OF DRIVE

7628 94
IN: 03/25/10



***** OLD METER INFORMATION ***** NEW METER INFORMATION *****

5/8 in. TY: G USE: 28 07/02 *
MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
36577813 82613185 3134 A *
*
*
*

TORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	07/02/19	3134	3106	28 A			
	06/03/19	3106	3041	65 A	8754	03/16/10	AMR
	05/02/19	3041	3009	32 A			
	04/02/19	3009	2975	34 A			

*****SRLK

7/25/19

Arrival Time: 7:30

Time	Rate	Cost	Part Description	Used / Ret #	GL #	Cost
4 hrs			3/4" Comp Coupling #91	used 2	620.6	30.60
4 hrs			3/4" Inserts #89	used 4	333.4	4.72
4 hrs			3/4" Flow Coupling #93	used 1	620.6	4.45
			3/4" tubing #333	used 48 ft	333.4	10.93
Total Cost						
4 hrs			Total Cost			
4 hrs						

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 360,000 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Will need clean up.

7/25/19 Completed Time: 11:30 By: JDOB AR

WORK ORDERS BY TYPE

09:29:00

TYPE: SRLK
 SCHEDULED DATE: 07/22/19 SCHEDULED TIME: AM:
 ACTIONS: SERVICE LINE LEAK AT [REDACTED]

WORK ORDER NO : 51026

37.338226
 86.208521

LOCATION: LEFT CORNER OF GARAGE

IN: 04/04/17



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

5/8 in. TY: G USE: 25 07/03 *
 MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 41940396 83283306 1058 A *
 *
 *

METER HISTORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	07/03/19	1058	1033	25 A	42533	04/03/17	HANG
	06/03/19	1033	1013	20 A	45570	12/29/17	HANG
	05/03/19	1013	1012	1 A	45230	11/20/17	DISC
	04/03/19	1012	1006	6 A	44650	09/19/17	VOID

Arrival Time: 11:40 *****SRCLK

Time	Rate	Cost
6hrs 20min		
6hrs 20min		
6hrs 20min		
Total Cost		
6hrs 20min		
6hrs 20min		
1ch/6hrs 20min		
Total Cost		
6hrs 20min		
Total Cost		

Part Description	Used / Ret #	GL #	Cost
3" X 3/4" service saddle #33	U-1	333.4	22.58
Comp. Coupling 3/4" #91	U-2	1020.6	30.60
SS insert 3/4" #89	U-3	333.4	3.54
3/4" service Tubing #333	1 FT	333.4	.23
3/4" Corp stop #83	U-1	333.4	28.28
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss \$2,100 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Completed Time: 06:00 By: MUTSD AF

WORK ORDERS BY TYPE

12:20:45

LIST/TY: MISC

WORK ORDER NO : 51030

PLD DATE: 07/22/19 SCHEDULED TIME: PM:

ACTIONS: CUSTOMER CALLED AND SAID THAT WATER IS STANDING IN THE METER BOX AND WATER HAS BEEN STANDING AROUND IT ON THE GROUND FOR TWO WEEKS PLEASE CHECK OUT

37.269915
86.280201

LOCATION: 4' LFT SIDE DRIVE 20' OF RD

IN: 02/27/12



***** OLD METER INFORMATION ***** NEW METER INFORMATION *****

5/8 in. TY: G USE: 33 07/02 *
 CE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 43423257 83650926 3750 A *
 *
 *
 *

FACTORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	07/02/19	3750	3717	33	A		
	06/03/19	3717	3615	102	A	22645 02/01/12	AMR
	05/02/19	3615	3586	29	A		
	04/02/19	3586	3555	31	A		

le: 7-20-19 Arrival Time: 1:00 *****MISC

Time	Rate	Cost
2 1/2 hrs		
Total Cost		
2 1/2 hrs		
Total Cost		
2 1/2 hrs		
Total Cost		

Parts		Used / Ret #	GL #	Cost
3/4" Tubing #333	used-35	333.4		7.97
3/4" Inserts #89	used-4	333.4		4.72
3/4" Comp Coupling #91	used-2	620.6		30.160
3/4" Flow Coupling #93	used-1	620.6		4.45
Total Cost				

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 350,000 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

ate: 7-20-19 Completed Time: 3:30 By: DB JD

WORK ORDERS BY TYPE

10:01:09

LIST/TYPE: SRLK


WORK ORDER NO : 51056

SCHEDULED DATE: 07/23/19 SCHEDULED TIME: AM:

ACTIONS: SERVICE LINE LEAK - PER [REDACTED]
CALLED IN BY A CUSTOMER

LOCATION:

IN:



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

5/8 in. TY: G USE: 0 *
 MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 *
 *
 *

METRY: DATE CURRENT PREVIOUS USAGE PRIOR W/O DATE TYPE

*****SRLK

7-22-19 Arrival Time: 12:30

Time	Rate	Cost
5min		
2hrs		
2hrs		
2hrs		
Total Cost		
Time	Rate	Cost
2hrs		
2hrs		
Total Cost		
Time	Rate	Cost
2hrs		
Total Cost		

Parts			
Part Description	Used / Ret #	GL#	Cost
3/4" Compressor coupling #91	used-4	620.6	61.20
3/4" Insert #89	used-6	333.4	7.08
3/4" Tubing #333	used-3A	333.4	.68
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 78,000 Gal. Flushed _____
 Cause Of Leak: rock Time occurred: _____
 Length of Interruption: _____
 Comments: _____

7-22-19 Completed Time: 2:30 JD. TA DB

WORK ORDERS BY TYPE

15:19 31

IST/TYPE: SRLK
 LED DATE: 07/17/19 SCHEDULED TIME: PM:
 CTIONS: SERVICE LINE LEAK

WORK ORDER NO : 51007

37.347448
 86.136843

LOCATION: LEFT OF BLACK TOP DRIVE

2423-19
 IN: 07/03/19



METER INFORMATION*****

5/8 in. TY: G USE: 0 07/03 *
 E SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 41943551 83432686 1968 A *

ORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	05/08/19	23	23	0 A	50892	07/02/19	HANG
	04/17/19	23	23	0 A	50360	05/07/19	DISC
	03/18/19	23	22	1 A	49408	02/01/19	HANG
	02/05/19	22	22	1 A	48989	12/11/18	DISC

***** SRLK

7/22/19 Arrival Time: 7:30

Time	Rate	Cost
2 1/2		
2 1/2		
2 1/2		
Total Cost		
Time	Rate	Cost
2 1/2		
2 1/2		
Total Cost		
Time	Rate	Cost
2 1/2		
Total Cost		

Parts			
Part Description	Used / Ret #	GL #	Cost
3/4" Comp Coupling #91	used 2	620.0	30.60
3/4" Inserts #89	used 3	333.4	3.54
3/4" Flow Coupling #93	used 1	620.0	4.45
3/4" tubing #333	used 3 ft	333.4	.68
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 31.680 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

ate: 7/22/19 Completed Time: 10:00 By: JD DB JA

WORK ORDERS BY TYPE

13:13:42

LIST/TY: SRLK

WORK ORDER NO : 51019

FILED DATE: 07/19/19 SCHEDULED TIME: PM:

ACTIONS: SERVICE LINE LEAK

37.283955
86.381650

LOCATION: IN LINE WITH FRONT DOOR

3247 87
IN: 07/29/16



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

5/8 in. TY: G USE: 6 07/02 *
 CE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 41941023 83431749 6093 A *
 *
 *
 *

FACTORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	07/02/19	6093	6087	6 A	39135	05/04/16	MISC
	06/03/19	6087	6078	9 A	48951	12/05/18	MISC
	05/02/19	6078	6072	6 A	48541	10/23/18	MISC
	04/02/19	6072	6067	5 A	40179	07/27/16	MISC

te: 7-19-19 Arrival Time: 1:00 *****SRK

Time	Rate	Cost
1 hr		
1 hr		
Total Cost		
Time	Rate	Cost
1 hr		
Total Cost		
Time	Rate	Cost
1 hr		
Total Cost		

Part Description	Used / Ret #	GL #	Cost
3/4" Repair Coupling #91	used-1		
3/4" Flow #93	used-1		
3/4" Repair Coupling #91	used-1	420.6	18.30
3/4" Flow #93	used-1	420.6	4.45
3/4" Inserts #89	used-2	333.4	2.36
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 500,000 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

WORK ORDERS BY TYPE

11:21:31

LIST/TY: ANGL

WORK ORDER NO : 50997

SCHEDULED DATE: 07/16/19 SCHEDULED TIME: AM:

ACTIONS: ANGLE VALVE CUSTOMER CALLED SAYS ANGLE VALVE IS BAD WILL NOT STOP WATER FLOW

37.294788
86.239362

LOCATION: 8' OF RD LFT CRNR OF BLDG

IN: 04/02/12



***** OLD METER INFORMATION ***** NEW METER INFORMATION *****

5/8 in.	TY: G	USE: 131	07/02	*					
MAKE SERIAL	REMOTE	MXUID	CURRENT	*	MAKE	SERIAL	REMOTE	MXUID	
41941166		83432855	3775 A	*					

HISTORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	07/02/19	3775	3644	131 A	23626	03/21/12	AMR
	06/04/19	3644	3546	98 A	46776	05/03/18	HANG
	05/02/19	3546	3546	0 A	46727	04/27/18	PULL
	04/02/19	3546	3546	0 A	33422	08/26/14	MNLK

Date: 7-22-19 Arrival Time: 8:50

Time	Rate	Cost
3min		
50min		
50min		
Total Cost		
Time	Rate	Cost
50min		
Total Cost		
Time	Rate	Cost
Total Cost		

Part Description	Used / Ret #	GL #	Cost
3/4 Angel Valve #87	U-1	020.0	29.19
Washer #259	U-2	334.5	.15
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

was off left aff

Date: 7-22-19 Completed Time: 9:40 By: MT SM

WORK ORDERS BY TYPE

12:36:18


SRLK

WORK ORDER NO : 50987

07/15/19 SCHEDULED TIME: PM:
SERVICE LINE LEAK AT [REDACTED]

LOCATION:

IN:



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

5/8 in. TY: G USE: 0
MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID

HISTORY: DATE CURRENT PREVIOUS USAGE PRIOR W/O DATE TYPE

Date: 7/14/19 Arrival Time: 12:30 *****SRLK

Cost	Time	Rate	Cost
7#	1 1/2 hr		
Total Cost:			
e	1 1/2 hr		
Total Cost:			
ent	1 1/2 hrs		
Total Cost:			

Parts		Used / Ret #	GL #	Cost
3/4" Comp. Coupling #91	used 1	620.6	15.30	
3/4" Inserts #89	used 2	333.4	2.36	
Total Cost				

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 43,200 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Wsn need clean up

Date: 7/14/19 Completed Time: 2:00 By: JD

WORK ORDERS BY TYPE

12:33:40

LIST/TYPE: SRLK ✓
SCHEDULED DATE: 07/15/19 SCHEDULED TIME: PM
ACTIONS: REPAIR SERVICE LINE LEAK AT

WORK ORDER NO : 50986

37.252915
86.165732

LOCATION: RIGHT SIDE WALKWAY AT HOUSE

3281-87
IN: 09/02/10



OLD METER INFORMATION NEW METER INFORMATION*****
5/8 in. TY: G USE: 22 06/17 *
MAKE SERIAL REMOTE MKUID CURRENT * MAKE SERIAL REMOTE MKUID
40352856 83010564 3004 A *
*
*
*

TORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	06/17/19	3004	2982	22 A			
	05/20/19	2982	2954	28 A	26846	08/31/12	SRLK
	04/17/19	2954	2934	20 A	13691	09/01/10	AMR
	03/18/19	2934	2918	16 A			

***** SRLK
Date: 7/16/19 Arrival Time: 12:30

Time	Rate	Cost
2hrs		
2hrs		
Total Cost		
2hrs		
Total Cost		
2hrs		
Total Cost		

Part Description	Used / Ret #	GL #	Cost
3/4" Comp Couplings #91	used 1	620.6	15.30
3/4" flow Coupling #93	used 1	620.6	4.45
3/4" Inserts #89	used 1	883.4	1.18
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 69,120 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Date: 7/16/19 Completed Time: 2:30 By: JDDB

Conf- 190 7160573

WORK ORDERS BY TYPE

09:19:32

KLIST/TY: LEAK ✓

WORK ORDER NO : 50982


SCHEDULED DATE: 07/15/19 SCHEDULED TIME: AM:

INSTRUCTIONS: CUSTOMER CALLED AND SAID THERE IS WATER ALL AROUND HER METER, AND THE BOX IS FULL OF WATER

37.225395
86.269686

LOCATION: IN LINE LEFT CORNER OF HOUSE

IN: 07/26/10



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE: 5/8 in. TY: G USE: 108 07/02 *
MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
40353196 83009749 4404 A *

STORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	07/02/19	4404	4296	108 A	43476	06/26/17	READ
	06/03/19	4296	4210	86 A	49535	02/20/19	REHA
	05/02/19	4210	4138	72 A	49517	02/19/19	DISC
	04/02/19	4138	4071	67 A	44780	10/02/17	RLID

Date: 7-16-19 Arrival Time: 9:30

Employee	Time	Rate	Cost	Part Description	Used / Ret #	GL #	Cost
	5min			3/4 Inserts #89	used-4	333.4	4.72
	2hrs			3/4 Comp Coupling #91	used-2	620.6	30.59
	2hrs			3/4" Flow Coupling #93	used-1	620.6	4.45
				3/4" Tubing #333	used-2ft	333.4	1.46
Total Cost				Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 650,000 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: Service line

Completed Date: 7-16-19 Completed Time: 11:30 By: DB JD

WORK ORDERS BY TYPE

15:44:02

MISC

WORK ORDER NO : 50972

WORK ORDER DATE: 07/11/19 SCHEDULED TIME: PM:
 ACTIONS: MOVE METER AT [REDACTED]
 PER [REDACTED]

LOCATION:

211-2605D-D

IN:

*****OLD METER INFORMATION***** NEW METER *****
 5/8 in. TY: G USE: 0 *
 MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 *
 *
 *

 HISTORY: DATE CURRENT PREVIOUS USAGE PRIOR W/O DATE TYPE

*****MISC
 Date: 7-29-19 Arrival Time: 1210

Employee	Time	Rate	Cost
DH	2 hrs	20.750	41.500
F	2 hrs	21.140	42.280
J	2 hrs	23.718	47.436
Total Cost			131.216
Vehicle	Time	Rate	Cost
	1 hr	10.00	10.00
Total Cost			10.00
Material	Time	Rate	Cost
	1 hr	35.00	35.00
Total Cost			35.00

Parts		Used / Ret #	GL #	Cost
5/8 x 3/4 setter #1	U-1	334.5	146.25	
3/4 ss insert #89	U-3	333.4	3.54	
3/4 Compression Coupling #91	U-1	620.6	15.30	
3/4 service tubing 333	U-18FT	333.4	2.28	
Total Cost				

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: New location 6FT Right of Porch steps

Total cost \$ 157.57

Do not Bill for setter ✓

Work Order Date: 7-29-19 Completed Time: 210 By: DH MT

WORK ORDERS BY TYPE

11:12:20

LIST/TY: ANGLE

WORK ORDER NO : 50969

SCHEDULED DATE: 07/11/19 SCHEDULED TIME: PM:

INSTRUCTIONS: ANGLE VALVE
PLEASE REPLACE ANGLE VALVE... IT IS LEAKING PER WO # 50948

37.358480
86.172340

LOCATION: RIGHT OF HOUSE

5125 02
IN: 01/05/11



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

5/8 in. TY: G USE: 11 06/18 *
MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
40356145 83010052 665 A *
*
*
*

STORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	06/18/19	665	654	11 A			
	05/20/19	654	643	11 A	50948	07/09/19	DISC
	04/18/19	643	643	0 A	28859	04/29/13	READ
	03/19/19	643	643	0 A	15776	11/08/10	AMR

Date: 7/12/19 Arrival Time: 9:00

Employee	Time	Rate	Cost
AF	1m		
	1hr		
	1hr		
Total Cost			
Vehicle	Time	Rate	Cost
	1hr		
Total Cost			
Material	Time	Rate	Cost
Total Cost			

Part Description	Used / Ret #	GL #	Cost
Angle Valve # 87	01	42010	29.19
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Completed Date: 7/12/19 Completed Time: 10:00 By: AF mt

WORK ORDERS BY TYPE

13:16:05

LIST/TYPE: LEAK

WORK ORDER NO : 50942


SCHEDULED DATE: 07/09/19 SCHEDULED TIME: PM:

ACTIONS: IN BETWEEN LOT #1 AND #2 RUNNING DOWN THE ROAD BELIEVES WE HAVE A LEAK, IF WE GET OUT THERE AND ITS NOT OURS CAN WE LOCATE OUR WATER LINES. SAYS LEAK IS MORE VISIBLE EARLY AM AND LATE PM

37.338052
86.195945

LOCATION: UNDER FRONT DECK

IN: 06/04/12



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

5/8 in. TY: G USE: 4 06/18 *
SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
41942775 83283455 191 A *

CATEGORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	06/18/19	191	187	4 A	25792	05/30/12	AMR
	05/21/19	187	186	1 A	43986	07/31/17	READ
	04/18/19	186	185	1 A	33004	07/18/14	READ
	03/19/19	185	185	0 A	29818	08/09/13	SRLK

Date: 7/12/19 Arrival Time: 7:30

Time	Rate	Cost
3 1/2		
3 1/2		
3 1/2		
Total Cost		
Time	Rate	Cost
3 1/2		
3 1/2		
Total Cost		
Time	Rate	Cost
3 1/2		
Total Cost		

Part Description	Used / Ret #	GL #	Cost
3/4" Comp Coupling #91	Used 2	620.6	30.59
3/4" Inserts #89	Used 3	333.4	3.54
3/4" Tubing #333	Used 3	433.4	.68
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 103,680 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: Service line
need to dig main out here. marked the spot

Date: 7/12/19 Completed Time: 11:00 By: JD DB JC

WORK ORDERS BY TYPE

08:15:14

LIST/TY: SRLK

WORK ORDER NO : 50934

SCHEDULED DATE: 07/09/19 SCHEDULED TIME: AM:

ACTIONS: SERVICE LINE LEAK

37.199926
86.382942

LOCATION: 2' IN FRONT OF HYDRANT 70' OF RD

210 85

IN: 07/19/10



***** OLD METER INFORMATION ***** NEW METER INFORMATION *****

5/8 in. TY: G USE: 68 07/03 *
 MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 40353675 83010782 5770 A *
 *
 *
 *

FACTORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	06/04/19	5702	5615	87 A	12013	06/30/10	AMR
	05/03/19	5615	5550	65 A	39047	04/22/16	SRLK
	04/03/19	5550	5478	72 A	19397	06/13/11	MNLK
	03/05/19	5478	5404	74 A	14288	09/20/10	MNLK
							SRLK

Date: 7-8-19 Arrival Time: 3:30

Time	Rate	Cost
3min		
2hrs		
2hrs		
1hr		
Total Cost		
Time	Rate	Cost
2hrs		
Total Cost		
Time	Rate	Cost
2hrs		
Total Cost		

Part Description	Used / Ret #	GL #	Cost
3/4" #91 Compression Capling	used-2	620.6	30.59
3/4" Flow #93	used-1	620.6	4.45
3/4" Inserts #89	used-4	833.4	4.72
3/4" Tubing #333	used-6	833.4	1.37
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 230400 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____
 Service line leak

Date: 7-8-19 Completed Time: 5:30 By: Dylan JA JC

WORK ORDERS BY TYPE

08:32:04


LIST/TYPE: SRLK
 SCHEDULED DATE: 07/08/19 SCHEDULED TIME: AM:
 INSTRUCTIONS: SERVICE LINE LEAK AT [REDACTED]

WORK ORDER NO ; 50915

37.157818
 86.260341

LOCATION: ACCRD FROM JAMES METER 15' OF RD

IN: 05/28/10



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

5/8 in.	TY: G	USE: 24	07/02	*					
MAKE SERIAL	REMOTE	MXUID	CURRENT	*	MAKE	SERIAL	REMOTE	MXUID	
36598507		82617296	5312 A	*					
				*					
				*					

TORY: DATE CURRENT PREVIOUS USAGE PRIOR W/O DATE TYPE

*****SRLK

Date: 7/10/19 Arrival Time: 7:30

Time	Rate	Cost
5 1/2		
5 1/2		
5		
5		
Total Cost		
5 1/2		
5		
5 1/2		
Total Cost		
5 1/2		
Total Cost		

Part Description	Used / Ret #	GL #	Cost
3/4" Comp Coupling #91	Used 1	620.6	15.29
3/4" Inserts #89	Used 2	333.4	2.36
3/4" Flow Coupling #93	Used 1	620.6	4.45
3/4" Stub on #85	Used 1	620.4	11.41
3/4" Tubing #333	Used 32	333.4	7.29
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 34,200 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____
 Service line leak

Date: 7/10/19 Completed Time: 2:00 By: TD DB

WORK ORDERS BY TYPE

15:37:55

LIST/TY: SRLK

WORK ORDER NO : 50907


SCHEDULED DATE: 07/03/19 SCHEDULED TIME: PM:

INSTRUCTIONS: SERVICE LINE LEAK AT [REDACTED]

37.283669
86.213616

LOCATION: BEFORE WATER HYD

IN: 05/24/19



OLD METER INFORMATION** NEW METER INFORMATION*****

5/8 in.	TY: G	USE: 4	06/17	*				
MAKE SERIAL	REMOTE	MXUID	CURRENT	*	MAKE	SERIAL	REMOTE	MXUID
43423833		84030571	2369 A	*				
				*				
				*				
				*				

HISTORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	06/17/19	2369	2365	4	A		

*****SRLK

Date: 7/9/19 Arrival Time: 9:30

Cost	Time	Rate	Cost
4	5min		
	2 hrs		
	2 hrs		
Total Cost			
Cost	Time	Rate	Cost
	1 hr		
Total Cost			
Cost	Time	Rate	Cost
	1 hr		
Total Cost			

Parts		Used / Ret #	GL #	Cost
3/4" Comp. Coupling	#91	Used 2	620.4	30.59
3/4" Inserts	#83	Used 4	333.4	4.72
3/4" tubing	#333	Used 1 ft	333.4	.23
Total Cost				

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 38,880 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: Will need clean up Service line back

Date: 7/9/19 Completed Time: 10:30 By: JD DB

WORK ORDERS BY TYPE

09:14:01

LIST/TYPE: SRLK
 SCHEDULED DATE: 07/02/19
 INSTRUCTIONS:


WORK ORDER NO : 50891

SCHEDULED TIME: AM: 01
 SERVICE LINE LEAK WILL NEED BACKHOE TRACHOE

37.274828
 86.173230

LOCATION: LEFT SIDE OF THE DRIVE

7160 04
 IN: 08/17/10



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

5/8 in. TY: G USE: 23 06/17 *
 MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 40353357 83009799 3772 A *
 *
 *

DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
06/17/19	3772	3749	23 A			
05/20/19	3749	3719	30 A	37039	09/29/15	READ
04/17/19	3719	3689	30 A	13140	08/04/10	AMR
03/18/19	3689	3659	30 A			

*****SRLK

date: 7/9/19 Arrival Time: 7:30

Time	Rate	Cost
2hrs		
2hrs		
Total Cost		
2hrs		
Total Cost		
2hrs		
Total Cost		

Part Description	Used / Ret #	GL #	Cost
3/4" Comp. Coupling #91	Used 2	1020.6	30.59
3/4" Flow Coupling #93	Used 1	1020.6	4.45
3/4" Inserts #89	Used 4	333.4	4.72
3/4" tubing #333	Used 84	333.4	1.82
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 48,960 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Will need clean up

Completed Date: 7/9/19 Completed Time: 9:30 By: JDD

WORK ORDERS BY TYPE

09:12:40

KLIST/TYPE: MISC

WORK ORDER NO : 50890

SCHEDULED DATE: 07/02/19 SCHEDULED TIME: AM:

INSTRUCTIONS: MISCELLANEOUS PLEASE MOVE METER FOR

37.287542

86.018180

LOCATION: LFT SDE WINE SAP RD NEXT TO SIGN

5343 89

IN: 04/21/11

***** OLD METER INFORMATION ***** NEW METER INFORMATION *****

Size: 5/8 in. TY: G USE: 0 06/17 *
 MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 41941004 83432639 528 A *

STORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	06/17/19	528	528	0 A			
	05/20/19	528	519	9 A	18259	04/15/11	AMR
	04/17/19	519	517	2 A	4370	03/09/09	PERD
	03/19/19	517	517	0 A			

***** MISC

Date: 7/2/19 Arrival Time: 7:30

Year	Time	Rate	Cost	Part Description	Used / Ret #	GL #	Cost
m	5m			3/4" Comp Coupling #91	used 1	620.4	15.30
	9hrs			3/4" Insert #89	used 1	333.4	1.18
	9hrs			3/4" tubing #333	used 68ft	333.4	15.49
				1 1/2 casing pipe #439	used 21ft	333.4	71.43
				3" pvc saddle #33	used 1	333.4	22.58
				3/4" corp stop #83	used 1	333.4	
Total Cost				Total Cost			
Year	Time	Rate	Cost				
	1hr						
	1hr						
Total Cost							
Year	Time	Rate	Cost				
	2hrs						
	2hrs						
Total Cost							

Bud Called: _____ Conf: _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: USE Time occurred: _____
 Length of Interruption: _____
 Comments: Move meter

Date: 7/2/19 Completed Time: 5:30 By: JD DB

LEC

WORK ORDERS BY TYPE

08:21:01


LIST/TY: SRLK
SCHEDULED DATE: 07/01/19 SCHEDULED TIME: AM:
DESCRIPTIONS: SERVICE LINE LEAK

WORK ORDER NO : 50879

LOCATION:

110-10100-A

IN:



***** INFORMATION *****

5/8 in. TY: G USE: 0
SERIAL REMOTE MXUID CURRENT MAKE SERIAL REMOTE MXUID
423808 84030119

READ 107840
CORY: DATE CURRENT PREVIOUS USAGE PRIOR W/O DATE TYPE

***** SRLK
Date: 7-1-19 Arrival Time: 2:30

Time	Rate	Cost
SM		
25 min		
25 min		
Total Cost		
Time	Rate	Cost
25 min		
Total Cost		
Time	Rate	Cost
Total Cost		

Parts			
Part Description	Used / Ret #	GL #	Cost
#089 Inserts	U 2	333.4	2.34
#091 Compression	U 1	620.6	15.29
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill (Yes) or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____
 (Signature) PLS JAL

WORK ORDERS BY TYPE

15:45:00

WPC

LIST/TY: SRLK
 SCHEDULED DATE: 06/11/19 SCHEDULED TIME: PM:
 ACTIONS: SERVICE LINE LEAK

WORK ORDER NO : 50703

37.149010
 86.227161

LOCATION: ACR FENCE IN LINE LEFT CRN HOUSE 0249 06
 IN: 05/26/10



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

5/8 in. TY: G USE: 34 06/03 *
 SERIAL REMOTE MXUID CURRENT MAKE SERIAL REMOTE MXUID
 36598454 82617571 3957 A *
 *
 *

DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
06/03/19	3957	3923	34 A	46856	05/11/18	SRLK
05/02/19	3923	3895	28 A	47744	08/10/18	MISC
04/02/19	3895	3870	25 A	47145	06/08/18	MNLK
03/04/19	3870	3843	27 A	47089	06/06/18	SRLK

Date: 7/9/19 Arrival Time: 12:30

Time	Rate	Cost
2 hrs		
2 hrs		
Total Cost		
2 hrs		
Total Cost		
2 hrs		
Total Cost		

Part Description	Used / Ret #	GL #	Cost
3/4" Comp. Coupling #91	Used 3	620.0	45.89
3/4" Inserts #89	Used 6	333.4	7.08
3/4" Flow Coupling #93	Used 2	620.0	8.90
3/4" Tubing #333	W/O	333.4	2.18
Total Cost			

Bud Called _____ Conf. # 1906130472
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 65,690 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Will need clean up Service line test

Date: 7/19/19 Completed Time: 2:30 By: JDB

Customer said may be 1 FT Deep

WORK ORDERS BY TYPE

13:29:23

LIST/TYP: HANG


WORK ORDER NO : 50566

SCHEDULED DATE: 05/29/19 SCHEDULED TIME: PM:

ACTIONS: PLEASE HANG METER FOR OWNERS DALE OR CORINNE
MAY BE INSTALLED ELSEWHERE LEAVE OFF AT METER

LOCATION: RIGHT OF ELECTRIC POLE

IN: 03/24/11



5/8 in. TY: G USE: 0 05/15 *

KEY SERIAL REMOTE MXUID CURRENT * MAKE
41939898 83433414 A * ID#

38990023

MXUID

* 50592016 R-10 HRE ME
*
*

*****HANG

TORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	05/15/14	0	0	0 A	39938	07/15/16	PULL
	04/17/14	0	0	0 A	32355	05/14/14	PULL
	03/17/14	0	0	0 A	17464	03/16/11	AMR
	02/18/14	0	0	0 A			

Arrival Date: 7/12/19 Arrival Time: 11:00

Employee	Time	Rate	Cost
AM	3m A	20.5101	1.0254
JD	3 1/2	24.8029	86.8101
DB	3 1/2	21.4312	75.0109
Total Cost:			162.8464

Part Description	Used / Ret #	GL #	Cost
#19 12" resetter w/o check	used 1	620.6	80.81
#492 1/2" pvc pipe	used 3	333.4	.75
#457 Reg plastic box	used 1	334.5	59.04
Total Cost			330.05

Vehicle	Time	Rate	Cost
8	3 1/2	10.00	35.00
9	3 1/2	5.00	17.50
Total Cost:			52.50

15.00 = 20.00
 Bill Called = 10.00
 Conf. # total cost = \$ 667.8964
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: total charged \$ 378.45
 Length of Interruption: _____
 Comments: Need Metal Detector
Need To Send Guy A Bill

Completed Date: 7/12/19 Completed Time: 3:30 By: JD DB

WORK ORDERS BY TYPE

09:10:12

CHECKLIST/TYPE: MNLK

WORK ORDER NO : 51144

SCHEDULED DATE: 07/29/19 SCHEDULED TIME: AM:

INSTRUCTIONS: REPAIR WATER MAIN 3" AT [REDACTED]

37.319910

86.222857

METER LOCATION: BEHIND LIGHT POLE/ 20' OF RD

5941-90

IN: 03/26/12

[REDACTED]

ISSUED: 07/29/19 BY: MARCIE COMPLETED: 07/29/19

*****OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE:	5/8 in.	TY:	G	USE:	0	03/02	*	
MAKE	SERIAL	REMOTE	MXUID	CURRENT	MAKE	SERIAL	REMOTE	MXUID
1:	41940613		83282594	550 A	*			
2:					*			
3:					*			
4:					*			

HISTORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	03/02/21	550	550	0 A			
	02/02/21	550	550	0 A	48821	11/26/18	LEAK
	01/04/21	550	550	0 A	23391	03/16/12	AMR
	12/02/20	550	550	0 A			

*****MNLK

Arrival Date: 7-30-19 Arrival Time:

Labor Cost				Parts			
Employee	Time	Rate	Cost	Part Description	Used / Ret #	GL #	Cost
				3/4 st. inserts ^{DB9}	U 3	333.4	3.54
				091 Br. Comp. Comp.	U 2	620.6	30.60
				333 5/8 tubing	U 8	33.4	1.82
				047 3x1 serv. saddle	U 1	333.4	18.47
				083 ^{Long Stop}	U 1	333.4	28.29
Total Cost				Total Cost			
Vehicle	Time	Rate	Cost	495/300 3" SL 200 PVC/30.0			
				3" Rep. Comp. ^{620.6}			35.03
Total Cost				Total Cost			
Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____				Est. loss _____ Gal. Flushed _____			
Cause Of Leak: _____ Time occurred: _____				Length of Interruption: _____			
Equipment				Comments: _____			
Total Cost							

WORK ORDERS BY TYPE

10:57:32

LIST/TYP: LEAK

WORK ORDER NO : 50859

SCHEDULED DATE: 06/25/19 SCHEDULED TIME: PM:

ACTIONS: CALLED IN BY [REDACTED] CUSTOMER CALLED HIM AND SAID HE HAD AN EXCESSIVE AMOUNT OF WATER AROUND HIS METER AND BELIEVES THERE IS A LEAK.

37.324553
86.162154

LOCATION: 15' RT OF HYDRANT

IN: 05/19/16

***** [REDACTED] *****

DATE: 06/25/19 BY: CASARA COMPLETED:

*****OLD METER INFORMATION***** NEW METER INFORMATION*****

5/8 in. TY: G USE: 5 06/17 *
SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
41942893 83283509 95 A *
*
*
*

MORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	05/20/19	90	88	2 A	29773	08/06/13	DISC
	04/17/19	88	88	0 A	39229	05/16/16	HANG
	03/18/19	88	88	0 A	34583	01/09/15	DISC
	02/18/19	88	88	0 A	32505	05/27/14	HANG

*****LEAK*****

date: 7-2-19 Arrival Time: 2:00

Cost	Time	Rate	Cost
	5min		
	2 1/2 hrs		
	3 hrs		
Total Cost			

Parts		Used / Ret #	GL #	Cost
3/4" tubing	#333	U-254	333.4	5.70
3/4" inserts	#89	U-3	333.4	3.54
3/4" coupling	#91	U-2	620.6	30.59
Total Cost				

Cost	Time	Rate	Cost
	2 1/2 hrs		
Total Cost			
Cost	Time	Rate	Cost
	3 hrs		
Total Cost			

Bud Called 6/25 3:10 PM. Conf. # 1906251760
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

WORK ORDERS BY TYPE

10:56:19

TYPE: MISC
 SCHEDULED DATE: 06/06/19 SCHEDULED TIME: AM:
 ACTIONS: MOVE METER BOX

WORK ORDER NO : 50651

LOCATION: PAST BLOW OFF ON LFT OF ROAD

IN: 12/12/14



METER INFORMATION*****
 5/8 in. TY: G USE: 0 03/12 *
 METER SERIAL REMOTE MXUID CURRENT MAKE SERIAL REMOTE MXUID
 43423147 84014918 367 A *
 *
 *

ORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	03/12/15	367	367	0 A	35030	03/11/15	DISC
	02/24/15	367	367	0 A	34459	12/12/14	REHA
	01/19/15	367	367	0 A	34114	11/11/14	DISC
	12/12/14	367	367	0 A	29601	07/22/13	MISC

*****MISC

6/11/19 Arrival Time: 2:30

Time	Rate	Cost
1 1/2 hr		
1 1/2 hr		
Total Cost		
Time	Rate	Cost
1 1/2 hr		
Total Cost		
Time	Rate	Cost
1 1/2 hrs		
Total Cost		

Parts			
Part Description	Used / Ret #	GL #	Cost
3/4" Comp. Coupling #91	used 1	620.0	15.29
3/4" Flow #93	used 1	620.0	4.45
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____
used inv. date of 11-1-19 because wasn't turned in during June
BT

WORK ORDERS BY TYPE

16:17:08

CHECKLIST/TYPE: MISC

WORK ORDER NO : 50826

SCHEDULED DATE: 06/19/19 SCHEDULED TIME: PM:

INSTRUCTIONS: PLEASE CHECK SHUT OFF AND METER AT [REDACTED], LOOKS LIKE IT HAS BROKE LOOSE ON THEIR SIDE POSSIBLY, PLEASE CHECK AND REPAIR PER [REDACTED]

METER LOCATION: ACROSS PLANK FENCE BESIDE SATELL 5881 03 IN:



Didn't have in. To pull 397

*****OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE: 2 in.	TY: G	USE: 143	06/18	*		
MAKE SERIAL	REMOTE	MXUID	CURRENT	*	MAKE SERIAL	
1: 37837618			43275 A	*	50592294	
2: 37837518			4321600	*		
3:				*		
4:				*		



R-16 #418

*****HISTORY*****

HISTORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	06/20/17	43132	43127	5 A	47271	06/20/18	MISC
	07/10/13	43507	43056	29 A	44675	09/20/17	MISC
	06/18/13	43056	43027	29 A	42741	04/19/17	MISC
	05/17/13	43027	43008	19 A	39675	06/22/16	MISC

Arrival Date: 7-30-19 Arrival Time: 7:30

Labor Cost				Parts			
Employee	Time	Rate	Cost	Part Description	Used / Ret #	GL #	Cost
MT	3hrs			2" Resetter 27	U-1	620.10	915.35
DH	3hrs			2x16 PVC nipple 165	U-2	300.9	11.55
				2" meter Flange 117	U-2	420.10	73.78
Total Cost				Total Cost			
Vehicle	Time	Rate	Cost	7-16			
F150	3hrs			Bud Called <u>6-20-19</u> Conf. # <u>1906201187</u>			
8	3hrs			Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM <u>1907161722 us ky</u>			
Total Cost				Est. loss _____ Gal. Flushed _____			
Equipment	Time	Rate	Cost	Cause Of Leak: _____ Time occurred: _____			
TH	3hrs			Length of Interruption: _____			
Total Cost				Comments: _____			

Completed Date: 7-30-19 Completed Time: 10:30 By: DH MT