

WORK OF

10:06:21

TYPE: MISC

WORK ORDER NO : 51453

ED DATE: 08/29/19 SCHEDULED TIME: AM.

IONS: MOVE METER AT

37.24390:

86.43272:

LOCATION: ACROSS FENCE AT FLUSH HYD

IN: 12/16/15



***** NEW METER INFORMATION*****

SIZE	TY:	G	USE:	50	08/02	*
SERIAL	REMOTE		MXUID		CURRENT	* MAKE SERIAL REMOTE MXUII
1940596			83432919		2565 A	*
1940596			83432919		265380	*

Y:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	08/02/19	2565	2515	50 A	17137	03/08/11	HANG
	07/02/19	2515	2493	22 A	45796	01/24/18	REHA
	06/04/19	2493	2447	46 A	45738	01/23/18	DISC
	05/02/19	2447	2421	26 A	37786	12/14/15	MREG

9/9/19 Arrival Time: 7:30

Time	Rate	Cost	Part Description	Used / Ret #	GL #	Cost
5m	20.7851	1.7196	3/4" Comp. Coupling #91	used 1	620.6	14.42
3m	25.1645	75.4935	3/4" inserts #89	used 3	333.4	3.63
3m	24.4317	74.2951	3/4" tubing #333	used 6	4633.4	1.25
Total Cost		141.5182				

Time	Rate	Cost
3m	10.00	30.00
Total Cost		30.00

Total Cost 19.35

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM total cost \$ 295.8682
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Time	Rate	Cost
hrs	35.00	105.00
Total Cost		105.00

WORK ORDERS BY TYPE

08:39:52

LIST/TYPE: SRLK

WORK ORDER NO : 51872

SCHEDULED DATE: 09/30/19 SCHEDULED TIME: PM:

ACTIONS: [REDACTED] SERVICE LINE LEAK

Taken off W.O. # 51875

37.208051
86.288585

756-86

IN: 06/29/10

Adj. W.O.

LOCATION: 8' LEFT SIDE DRIVEWAY



OLD METER INFORMATION***** NEW METER INFORMATION*****

5/8 in.	TY: G	USE: 26	09/04	*				
SERIAL	REMOTE	MXUID	CURRENT	*	MAKE	SERIAL	REMOTE	MXUID
36599175		82618612	2661 A	*				

CATEGORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	09/04/19	2661	2635	26 A			
	08/05/19	2635	2611	24 A	45670	01/11/18	MISC
	07/03/19	2611	2599	12 A	45290	11/28/17	READ
	06/04/19	2599	2580	19 A	11683	06/28/10	AMR

9-27-19 Arrival Time: 10:30

st	Time	Rate	Cost
	2hrs		
	2hrs		
	2hrs		
	2hrs		
Total Cost			
	2hrs		
	2hrs		
	2hrs		
Total Cost			
	2hrs		
Total Cost			

Parts	Part Description	Used / Ret #	GL #	Cost
	3/4" Compressor Coupling #91	Used-1	020.6	13.93
	3/4" Inserts #89	Used-2	333.4	2.42
	3/4" Tubing #333	Used-48ft	333.4	10.02
Total Cost				

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 102,000 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

WORK ORDERS BY TYPE


08:20:13

WKLST/TY: MISC
 SCHEDULED DATE: 09/19/19 SCHEDULED TIME: AM:
 INSTRUCTIONS: REPLACE 2 VALVE BOXES

WORK ORDER NO : 51751

WORK LOCATION: BEHIND MAILBOX

9260 05
 IN: 03/22/10



NEW METER INFORMATION*****

DATE	MAKE	SERIAL	REMOTE	MXUID	USAGE	PRIOR W/O	DATE	TYPE
04/24					50 A	31003	12/27/13	HANG
	36577770	82613731			50 A	24684	04/23/12	DISC
	36577770	82613731			34 A	16116	12/01/10	REHA
					39 A	16051	11/30/10	DISC

 HISTORY: DATE CURRENT PREVIOUS USAGE PRIOR W/O DATE TYPE
 04/24/12 843 836 50 A 31003 12/27/13 HANG
 04/02/12 836 786 50 A 24684 04/23/12 DISC
 03/02/12 786 752 34 A 16116 12/01/10 REHA
 02/02/12 752 713 39 A 16051 11/30/10 DISC
 *****MISC

Date: 9-23-19 Arrival Time: 12:40

Time	Rate	Cost
30m		
30m		
30m		
Total Cost		
30m		
Total Cost		
30m		
Total Cost		

Part Description	Used / Ret #	GL #	Cost
#469 18" VALVE BOX	02	620.6	49.00
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Date: 9-23-19 Completed Time: 1:10 By: JAJC

WORK ORDERS BY TYPE

15:20:29

MISC

WORK ORDER NO : 51815

09/23/19 SCHEDULED TIME: PM:
REPLACE VALVE BOX AT FIRE HYDRANT


37.303134

86.061007

40FT RIGHT SIDE BLACKTOP DRIVE.

6171-90

IN: 10/07/13



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

2 in.	TY: G	USE: 484	09/17	*				
MAKE SERIAL	REMOTE	MXUID	CURRENT	*	MAKE	SERIAL	REMOTE	MXUID
45281882		85476546	21721 A	*				

*****STORY:*****

DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
08/19/19	21237	20990	247 A			
07/17/19	20990	20876	114 A	17811	03/28/11	AMR
06/17/19	20876	20750	126 A	6188	07/28/09	MISC
05/20/19	20750	20342	408 A	2221	08/14/08	PERD

ate: 9-24-19 Arrival Time: 1000

Time	Rate	Cost
5 min		
40 min		
40 min		
Total Cost		

Parts			
Part Description	Used / Ret #	GL #	Cost
Value Box 24" x 36"	4-1	1020.00	39.02
Total Cost			

Time	Rate	Cost
50 40 min		
Total Cost		

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

WORK ORDERS BY TYPE

08:01:07

LIST/TYPE: SRLK *rec*

WORK ORDER NO : 51635

SCHEDULED DATE: 09/17/19 SCHEDULED TIME: AM:

ACTIONS: SERVICE LINE LEAK

37.151624
86.204272

LOCATION:

5220-89
IN: 05/06/19



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE	TY	G USE	DATE	MAKE	SERIAL	REMOTE	MXUID
5/8 in.			21 09/03				
49952458			87600197	72 A			

CATEGORY	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	09/03/19	72	51	21			A
	08/02/19	51	29	22	50105	04/18/19	PERIO
	07/02/19	29	17	12	8513	03/16/10	AMR
	06/03/19	4201	4200	1			A

*****SRLK

9/17/19 Arrival Time: 7:30

Time	Rate	Cost
3 min		
1 1/2		
1 1/2		
8 1/2		
Total Cost		
Time	Rate	Cost
1 1/2		
8 1/2		
Total Cost		
Time	Rate	Cost
1 1/2		
Total Cost		

Parts	Part Description	Used / Ret #	GL #	Cost
	tapping sleeve 8" x 1/2" #293	used 1	331.4	195.00
	tapping valve 4" #323	used 1	331.4	407.36
	4" Mj restraint w/ flange #548	used 1	620.6	29.24
	4" flange gasket #351	used 1	620.6	2.79
	8" pvc pipe #551	used 15ft	620.6	82.66
	3" pvc pipe #495	used 6ft		
Total Cost				

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 74,550 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: main line

8" pvc coupling #401 - used 2
8" pvc pipe - used 3ft #497
620.6 x 15 = 9309.0
620.6 x 6 = 3723.6
620.6 x 1 = 620.6
9309.0 + 3723.6 + 620.6 = 13653.2

9/17/19 8:10 AM TO MR DA

Deen LN

wire
WSKY

WORK ORDERS BY TYPE

08:09:29

LIST/TYPE: SRLK
SCHEDULED DATE: 09/03/19 SCHEDULED TIME: AM:

WORK ORDER NO : 51464

INSTRUCTIONS: POSSIBLE LEAK, LOT NEXT TO THIS ADDRESS.

PUT A STICK IN THE GROUND WITH A CARDBOARD SIGN THAT SAYS LEAK HERE...HE SAYS ITS REALLY WET AND MUDDY

37.362616
86.162060

LOCATION: RIGHT SIDE OF THE STEPS

IN: 11/11/10

*****OLD METER INFORMATION***** NEW METER INFORMATION*****

5/8 in. TY: G USE: 20 08/19 *
MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
40356864 83006397 946 A *

DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
08/19/19	946	926	20 A	48980	12/11/18	SRLK
07/17/19	926	913	13 A	50306	04/29/19	LEAK
06/17/19	913	905	8 A	49896	03/28/19	SRLK
05/20/19	905	894	11 A	49266	01/11/19	SRLK

Date: 9/13/19 Arrival Time: 7:30

Employee	Time	Rate	Cost
	5 min		
	1 1/2 hrs		
	1 1/2 hrs		
Total Cost			
Employee	Time	Rate	Cost
3	1 1/2 hrs		
	1 1/2 hrs		
Total Cost			
Employee	Time	Rate	Cost
	1/2		
Total Cost			

Part Description	Used / Ret #	GL #	Cost
3" x 12" PVC clamp #374	Used 1	620.6	55.92
Total Cost			

Bud Called 9-9-19 Conf. # 1909090958
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 37,440 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: leak on main line

ed Date: 9/13/19 Completed Time: 9:00 By: JD DB

307 BASHU

WALACE
USKY

WORK ORDERS BY TYPE

10:46:13

KLIST/TYPE: MISC

WORK ORDER NO : 51440

SCHEDULED DATE: 08/26/19 SCHEDULED TIME: AM:

DESCRIPTIONS: CUSTOMER ON THAT RD CAME IN AND SAID THERE WAS A LEAK BETWEEN A COUPLE CUSTOMERS ON THAT RD, HE NOTICED IT WHILE HE WAS WALKING. SEE THE PAPER ATTACHED

LOCATION:

IN:



METER INFORMATION*****

MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID

*
*
*
*

HISTORY: DATE CURRENT PREVIOUS USAGE PRIOR W/O DATE TYPE

*****MISC

Date: 9/4/19 Arrival Time: 7:30

Cost				Parts			
Code	Time	Rate	Cost	Part Description	Used / Ret #	GL #	Cost
BH	8hrs			3" PVC pipe #495	Used 4 ft	620.6	3.62
B	8hrs			3" Repair Couplings #395	Used 2	620.6	35.03
Total Cost				Total Cost			

Code	Time	Rate	Cost
83	8hrs		
Total Cost			
Code	Time	Rate	Cost
A	8hrs		
Total Cost			

Bud Called 8-27-19 Conf. # 1908270618
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 57,600 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____

Comments: main line

Completed Date: 9/4/19 Completed Time: 4:30 By: JD DB

WORK ORDERS BY TYPE

13:36:26

LIST/TYPE: HANG

WORK ORDER NO. 50906

SCHEDULED DATE: 07/03/19 SCHEDULED TIME: PM:
 INSTRUCTIONS: PLEASE HANG METER FOR NEW OWNER.

@ [REDACTED] LOT 15
 LEAVE OFF AT METER!
 METER STATUS: DRY BOX

LOCATION: OVER BLOCK WALL

IN:



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

3/4 in. TY: G USE: 0 12/11 *
 MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 2093 A *
 * **JD** R-10 ME
 * **#50592087** 552 334.4
 * **DD2.62**

STORY:	DATE	CURRENT	PREVIOUS	USAGE	PRICE W/O	DATE	TYPE
	12/11/07	2093	2093	0	A		
	11/19/07	2093	2093	0	A		
	10/18/07	2093	2093	0	A		
	09/18/07	2093	2093	0	A		



date: **9/10/19** Arrival Time: **7:30** meter setter 5/8 x 3/4 #1 - used 1 **334.5**
 curb stop 3/4" #135 - used 1 **620.6**

Time	Rate	Cost
5 min	21.2450	1.1704
2 hrs	25.1645	50.329
2 hrs	21.4317	42.8634
Total Cost		94.9628

Part Description	Used / Ret #	GL #	Cost
3/4" Inserts #89	used 3	333.4	3.63
3/4" tubing #333	used 8ft	333.4	1.67
3/4" Corp Stop #83	used 1	333.4	26.95
3" x 3/4" saddle #33	used 1	333.4	22.89
Reg Plastic meter #457	used 1	334.5	64.10
box			
Total Cost			544.95

Time	Rate	Cost
1 hr	10.00	10.00
Total Cost		10.00
1 hr	35.00	35.00
Total Cost		35.00

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM total \$ **64.9128**
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: ***Zweek***

Box pulled out meter
 on ground in front of house
 move meter 3ft to side of house standing in rd looking at house

Date: **9/10/19** Completed Time: **11:30** by: **JD DB**
 * **TV** When He Calls Back

Give to Tony

WORK ORDERS BY TYPE

13:54:54


CKLIST/TYPE: SRLK
 SCHEDULED DATE: 09/03/19 SCHEDULED TIME: PM:
 INSTRUCTIONS: SERVICE LINE LEAK

WORK ORDER NO : 51468

37.226448
 86.337468

WORKER LOCATION: 100FT PAST HSE ACR FENCE 15' OF RD

7186 91
 IN: 07/08/10



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE: 5/8 in. TYPE: G USE: 23 08/05 *
 MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 36597751 82615582 3582 A *
 *
 *

HISTORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	08/05/19	3582	3559	23 A			
	07/03/19	3559	3519	40 A	44109	08/14/17	MISC
	06/04/19	3519	3499	20 A	28181	02/08/13	MISC
	05/03/19	3499	3484	15 A	11896	06/30/10	AMR

*****SRLK

Start Date: 9/6/19 Arrival Time: 7:30

Employee	Time	Rate	Cost
JD	3 min		
DB	4 hrs		
JA	4 hrs		
AE	4 hrs		
Total Cost:			
Vehicle	Time	Rate	Cost
	4 hrs		
	4 hrs		
	4 hrs		
Total Cost:			
Equipment	Time	Rate	Cost
	4 hrs		
	4 hrs		
Total Cost:			

Parts	Part Description	Used / Ret #	GL #	Cost
	3/4" tubing #333	used 4004	333.4	8.35
	3/4" Comp Coupling #91	used 3	620.6	43.42
	3/4" flow Coupling #93	used 1	620.6	4.45
	3/4" Inserts #89	used 6	333.4	7.26
	1 1/4" HDPE pipe #1095	used 4004	354.0	16.00
Total Cost				

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 86,400 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____
 Service line

Completed Date: 9/6/19 Completed Time: 11:30 By: JD DB JA AE

center point RD

Precc
SRTC

WORK ORDERS BY TYPE

10:33:10

WJ

KLIST/TYPE: SRLK ✓ WORK ORDER NO : 51439

SCHEDULED DATE: 08/26/19 SCHEDULED TIME: AM:
INSTRUCTIONS: POSSIBLE SR OR MN LEAK PER CUSTOMER WATER IS
COMING UP AROUND THE METER BOX.
PLEASE CHECK THIS OUT THANK YOU

37.265972
86.023041

LOCATION: BESIDE FLUSH HYDRANT

7053-94
IN: 04/21/11

OLD METER INFORMATION** NEW METER INFORMATION*****

SIZE: 5/8 in. TY: G USE: 138 08/19 *
MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
41941057 83433252 20199 A *

STORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	07/17/19	20061	19919	142 A	28043	01/16/13	REHA
	06/17/19	19919	19805	114 A	31569	03/10/14	REHAN
	05/20/19	19805	19658	147 A	31549	03/07/14	DISC
	04/17/19	19658	19503	155 A	30931	12/09/13	READ

date: 9/9/19 Arrival Time: 1:00

Employee	Time	Rate	Cost
57	2hrs		
53	2hrs		
Total Cost			
Employee	Time	Rate	Cost
7	2hrs		
Total Cost			

Parts			
Part Description	Used / Ret #	GL #	Cost
3/4" Comp. Couplings #91	used 2	620.6	28.95
3/4" Inserts #89	used 3	333.4	3.63
3/4" tubing #333	used 5ft	333.4	1.04
Total Cost			

Bud Called 8-27-19 Conf. # 1908271478
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 38,880 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: Service line

Completed Date: 9/9/19 Completed Time: 3:00 By: JD DB

WORK ORDERS BY TYPE

13:57 54

LIST/TYPE: MNLK ✓
 SCHEDULED DATE: 09/03/19 SCHEDULED TIME: PM:
 INSTRUCTIONS: MAIN LINE LEAK

WORK ORDER NO : 51469

37.229662
 86.257856

LOCATION: THROUGH GATE UNDER SHEET METAL

IN: 08/21/13



OLD METER INFORMATION** NEW METER INFORMATION*****

2 in. TY: G USE: 4 08/02 *
 MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 45281875 85477257 1383 A *
 *
 *

TORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	08/02/19	1383	1379	4 A	31640	03/18/14	LEAK
	07/02/19	1379	1377	2 A	43948	07/26/17	REHAN
	06/03/19	1377	1377	0 A	43850	07/18/17	DISC
	05/02/19	1377	1377	0 A	41192	11/04/16	MISC

*****MNLK

date: 9-3-19 Arrival Time: 12:30

Cost	Time	Rate	Cost
	3hr		
	3hr		
	3hr		
	3hr		
Total Cost			
Cost	Time	Rate	Cost
	3hr		
	3hr		
Total Cost			
Cost	Time	Rate	Cost
	3hr		
Total Cost			

Part Description	Used / Ret #	GL #	Cost
2" meter gaskets #29	Used - 2	620.4	3.78
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 204,000 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

ed Date: 9-3-19 Completed Time: 3:30 By: Dylan

WORK ORDERS BY TYPE

13:59:36

LIST/TY: SRLK

WORK ORDER NO : 51470

FILED DATE: 09/03/19 SCHEDULED TIME: PM:

ACTIONS: SERVICE LINE LEAK

LOCATION: END OF ROAD LEFT SIDE DRIVEWAY

IN: 07/27/10

*****OLD METER INFORMATION***** NEW METER INFORMATION*****

5/8 in.	TY: G	USE: 2	09/04	*					
KE SERIAL	REMOTE	MXUID	CURRENT	*	MAKE	SERIAL	REMOTE	MXUID	
40353264		83011290	208 A	*					

DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
09/04/12	208	206	2 A	12458	07/22/10	AMR
08/02/12	206	203	3 A	7978	02/09/10	MREG
07/02/12	203	184	19 A	4688	04/13/09	MISC
06/04/12	184	181	3 A			

*****SRLK

Date: 9/6/19 Arrival Time: 9:30

Rate	Time	Rate	Cost
	1hr.		
	1hr.		
Total Cost			
	3 hr.		
Total Cost			
	1hr.		
Total Cost			

Part Description	Used / Ret #	GL #	Cost
3/4" Comp Coupling #91	Used 2	620.6	28.95
3/4" Flow Coupling #93	Used 1	620.6	4.45
3/4" Inserts #89	Used 4	333.4	4.84
3/4" Tubing #333	Used 4	333.4	1.83
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 28,500 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Date: 9/6/19 Completed Time: 10:30 By: JODB

WORK ORDERS BY TYPE

14:02:50

LIST/TY: SRLK
 SCHEDULED DATE: 09/03/19
 ACTIONS: SERVICE LINE LEAK

WORK ORDER NO : 51471

37.296905
 86.237027

LOCATION: 10' OF RD RIGHT CORNER OF THE YARD

IN: 04/04/12



ED: 09/03/19
 *****OLD METER INFORMATION***** NEW METER INFORMATION*****
 : 5/8 in. TY: G USE: 8 08/02 *
 MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 41940670 83432575 454 A *
 *
 *

 STORY: DATE CURRENT PREVIOUS USAGE PRIOR W/O DATE TYPE
 08/02/19 454 446 8 A
 07/02/19 446 441 5 A 36859 09/14/15 ANGLE
 06/04/19 441 425 16 A 23640 03/21/12 AMR
 05/02/19 425 420 5 A 2208 08/14/08 MREG
 *****SRLK

Date: 9/10/19 Arrival Time: 7:30

Employee	Time	Rate	Cost
1	3min		
2	2hrs		
3	2hrs		
Total Cost			
Vehicle	Time	Rate	Cost
83	2hrs		
Total Cost			
Comment	Time	Rate	Cost
A	2hrs		
Total Cost			

Parts		Used / Ret #	GL #	Cost
3/4" Comp Caping #91	Used 1	620.6	14.47	
3/4" Flow Caping #93	Used 1	620.6	9.45	
3/4" Inserts #89	Used 2	333.4	2.42	
Total Cost				

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 34,560 Gal Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: Service line

0130

17-101

LU

WORK ORDERS BY TYPE

USK/V
W/lee

09:23:46

LIST/TY: SRLK

SCHEDULED DATE: 09/06/19 SCHEDULED TIME: AM:

WORK ORDER NO : 51565


INSTRUCTIONS: SERVICE LINE LEAK CUSTOMER CALLED SAID METER IS LEAKING AT THE METER FURNING DOWN DITCH

37.155982
86.216381

LOCATION: RD

6314 03

IN: 05/06/19



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE: 5/8 in.	TY: G	USE: 56	09/03	*				
MAKE SERIAL: 50003860	REMOTE: 87616280	MXUID: 214	CURRENT: A	*	MAKE	SERIAL	REMOTE	MXUID

STORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	08/02/19	158	104	54 A	38377	02/10/16	SRLK
	07/02/19	104	55	49 A	50086	04/18/19	PERIO
	06/03/19	7131	7124	7 A	41623	12/14/16	SRLK
	06/03/19	55	0	55 A	39442	06/01/16	MISC

date: 8-10-19 Arrival Time: 12:30

Time	Rate	Cost
3min		
1 1/2 hrs		
1 1/2 hrs		
Total Cost		

Part Description	Used / Ret #	GL #	Cost
3/4" Inserts #89	used-3	333.4	3.63
3/4" Comp Coupling #91	used-2	620.6	20.94
3/4" Tubing #333	used-2A	333.4	.42
Total Cost			

Time	Rate	Cost
3min		
1 1/2 hrs		
Total Cost		

Bud Called 9-9-19 Conf. # 190909 0983

Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____

Est. loss 30,000 Gal. Flushed _____

Cause Of Leak: _____ Time occurred: _____

Length of Interruption: _____

Comments: Small Service Line Leak
Will Need Clean UP

Date: 8-10-19 Completed Time: 2:00 By: DB JD

WORK ORDERS BY TYPE

12:39:50

KLIST/TYPE: SRLK ^{LEL} WORK ORDER NO : 51570

SCHEDULED DATE: 09/06/19 SCHEDULED TIME: PM:

INSTRUCTIONS: SERVICE LINE LEAK CUSTOMER CALLED SAYS NABORS WATER METER STIILL LEAKING FLOODING YARD 3 METERS TOGETHER COPY OF OLD WORK ORDER ATT.

37.311621
86.278838

LOCATION: 60' BEHIND HOUSE RIGHT CORNER

5184-89
IN: 05/14/15



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE: 5/8 in.	TY: G	USE: 54	09/04	*				
MAKE SERIAL 36578320	REMOTE 82614912	MXUID 1130	CURRENT A	*	MAKE	SERIAL	REMOTE	MXUID

STORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	08/02/19	1076	1044	32 A	47998	08/23/18	RAHAN
	07/02/19	1044	1033	11 A	51192	08/05/19	CHECK
	06/03/19	1033	1022	11 A	51187	08/05/19	SRLK
	05/02/19	1022	1013	9 A	49805	03/19/19	VOID

*****SRLK*****

Date: 9/11/19 Arrival Time: 1:00

Time	Rate	Cost
3min		
2 1/2 hrs		
2 1/2 hrs		
Total Cost		
Time	Rate	Cost
2 1/2 hrs		
Total Cost		
Time	Rate	Cost
2 1/2 hrs		
Total Cost		

Part Description	Used / Ret #	GL #	Cost
3/4" Comp. Coupling #91	Used 2	420.6	28.95
3/4" Inserts #89	Used 4	333.4	4.84
3/4" tubing #333	Used 5 ft	333.4	1.04
Total Cost			

Bud Called 9-9-19 Conf. # 190900987
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 63,360 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: Service line leak

Date: 9/11/19 Completed Time: 3:30 By: JDDB

Leak at setter on Pigtail

WORK ORDERS BY TYPE

08:01:19

LIST/TYPE: SRLK
 ULED DATE: 09/09/19 SCHEDULED TIME: AM:
 UCTIONS: SERVICE LINE LEAK WATER LINE BUSTED AT METER
 CUSTOMER SAYS LEAK IS ON OUR SIDE

37.238694
 86.288526

LOCATION: BESIDE HOUSE LEFT SIDE

IN: 07/29/10



OLD METER INFORMATION** NEW METER INFORMATION*****

MAKE	SERIAL	REMOTE	MXUID	CURRENT	MAKE	SERIAL	REMOTE	MXUID
	40353023		83011098	2466 A				
	40353023		83011098	248570				

STORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	08/02/19	2383	2341	42 A			
	07/02/19	2341	2302	39 A	50654	06/06/19	READ
	06/06/19	2302	2261	41 A	12529	07/26/10	AMR
	05/02/19	2261	2237	24 A			

***** SRLK

te: 9-9-19 Arrival Time: 2:30

Time	Rate	Cost
37min		
45min		
45min		
Total Cost		
Time	Rate	Cost
50 45min		
Total Cost		
Time	Rate	Cost
Total Cost		

Part Description	Used / Ret #	GL #	Cost
# 89 Inserts	03	333.4	3.63
# 333 Tubing	3ft	333.4	.63
# 91 Coupling	02	620.6	28.94
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj, Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____
 Service line

...

WORK ORDERS BY TYPE

14:04:25

TYPE: MNLK ✓

DATE: 09/09/19 SCHEDULED TIME: PM:

WORK ORDER NO : 51584

DESCRIPTION: MAIN LINE LEAK AT NOLIN ESTATES

LOCATION:

IN:



OLD METER INFORMATION*****

NEW METER INFORMATION*****

5/8 in. TY: G USE: 0 *
 SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID *
 *
 *
 *

 Y: DATE CURRENT PREVIOUS USAGE PRIOR W/O DATE TYPE

*****MNLK
 9/13/19 Arrival Time: 9:00

Time	Rate	Cost
5m		
2 1/2		
2 1/2		
Total Cost		
Time	Rate	Cost
2 1/2		
2 1/2		
Total Cost		
Time	Rate	Cost
2 1/2		
Total Cost		

Parts			
Part Description	Used / Ret #	GL #	Cost
3/4" Comp Coupling #91	Used 2	620.6	28.94
3/4" Inserts #89	Used 4	333.4	4.84
3/4" tubing #333	Used 5	333.4	1.04
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 44,590 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____
 Service line

9/13/19 Completed Time: 11:30 By: JDDB

WORK ORDERS BY TYPE

14:55:03

LIST/TYPE: MISC

WORK ORDER NO : 51587

SCHEDULED DATE: 09/09/19 SCHEDULED TIME: PM:

ACTIONS: CUSTOMER CALLING IN SAYING WATER IS GOING ACROSS THE ROAD OUT OF HIS METER BOX.

37.241699
86.286112

LOCATION: AT LEFT CORNER OF HOUSE

8742 05
IN: 08/23/10



210

*****OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE	TY	G	USE	DATE	MAKE	SERIAL	REMOTE	MXUID
5/8 in.				190 09/03				
40352595				82886809				
40352595				82886809				
				12502 A				
				1254470				

*****MISC*****

DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
08/02/19	12312	12221	91 A			
07/02/19	12221	12079	142 A	40899	10/06/16	MISC
06/03/19	12079	11847	232 A	12545	07/26/10	AMR
05/02/19	11847	11775	72 A			

Date: 9-10-19 Arrival Time: 9:50

Time	Rate	Cost
1h.10m		
1h.10m		
Total Cost		
Time	Rate	Cost
1h.10m		
Total Cost		
Time	Rate	Cost
Total Cost		

Parts			
Part Description	Used / Ret #	GL#	Cost
#89 Insects Coupling	U2	833.4	2.42
#91 Compression	U1	620.6	14.47
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred _____
 Length of Interruption: _____
 Comments: Adjust Bill
 Service line

Date: 9-10-19 Completed Time: 11:00 By: JAA AF

WORK ORDERS BY TYPE

15:59:01

ISC


WORK ORDER NO : 51588

SCHEDULED DATE: 09/09/19 SCHEDULED TIME: PM:
 ACTIONS: NEEDS A RESETER PER [REDACTED]

37.336565
 86.142662

LOCATION: BEFORE HYDRANT

IN: 03/23/11



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

5/8 in. TY: G USE: 0 08/19 *
 KE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 41940900 83432867 154 A *
 41940900 83432867 *
 *
 *

TORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	08/19/19	154	154	0 A			
	07/17/19	154	154	0 A	51274	08/09/19	MISC
	06/17/19	154	154	0 A	17425	03/16/11	AMR
	05/20/19	154	154	0 A	5764	07/09/09	READ

*****MISC

9-10-19 Arrival Time: 2:35

st	Time	Rate	Cost
500m			
25min			
25min			
Total Cost			
nt	Time	Rate	Cost
25min			
Total Cost			
nt	Time	Rate	Cost
Total Cost			

Parts			
Part Description	Used / Ret #	GL #	Cost
RESETTER	01	620.6	76.60
#255 washers	04	334.5	30
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Van... 2:35 = 1 AM

WORK ORDERS BY TYPE

16:01:55

LIST/TY: MISC


WORK ORDER NO : 51590

SCHEDULED DATE: 09/09/19 SCHEDULED TIME: PM:

ACTIONS: NEEDS RESETTER

LOCATION: IN FRONT OF WATER HYD

IN: 07/17/18



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

5/8 in. TY: G USE: 0 08/20 *
 MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 49952391 87550480 A *
 49952391 87550480 *
 *

STORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	07/18/19	0	0	0 A	51567	09/06/19	PULL
	06/18/19	0	0	0 A	47495	07/18/18	RBOX
	05/21/19	0	0	0 A	47485	07/16/18	HANG
	04/18/19	0	0	0 A			

*****MISC

Date: 9-10-19 Arrival Time: 12:50

Time	Rate	Cost
35 min		
35 min		
Total Cost		
Time	Rate	Cost
35 min		
Total Cost		
Time	Rate	Cost
Total Cost		

Parts		Used / Ret #	GL #	Cost
#01	Resetter 9"	U1	620.4	76.60
#255	Washers	U4	334.5	.30
Total Cost				

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Date: 9-11-19 Completed Time: 1:25 By: JDAF

WORK ORDERS BY TYPE

09:51:10

WJ

KLIST/TYPE: LEAK WORK ORDER NO : 51592


SCHEDULED DATE: 09/10/19 SCHEDULED TIME: AM:

INSTRUCTIONS: CUSTOMER CALLED THE PERSON ON CALL LAST NIGHT 9-9-10 AND SAID THEY BELIEVE WE HAVE A LEAK, TOLD HIM SOMEONE WOULD BE OUT TODAY?

37.319597
86.224555

LOCATION: RIGHT SIDE OF DRIVE 4' OF RD

8057 04
IN: 03/26/12



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

MAKE	5/8 in.	TY:	G	USE:	6	09/04	*	MAKE	SERIAL	REMOTE	MXUID
41940607		REMOTE		MXUID		470	A				
				83432630							

STORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	08/05/19	464	446	18 A	23434	03/20/12	HANG
	07/03/19	446	440	6 A	39468	06/06/16	LEAK
	06/04/19	440	432	8 A	38748	03/24/16	MISC
	05/02/19	432	430	2 A	23855	03/27/12	AMR

Arrival Time: 9:30

Time	Rate	Cost
5 min		
2 hrs		
2 hrs		
Total Cost		
2 hrs		
Total Cost		
2 hrs		
Total Cost		

Part Description	Used / Ret #	GL #	Cost
3/4" Comp. Coupling #91	Used 2	620.6	28.95
3/4" Flow Coupling #93	Used 1	620.6	4.45
3/4" Inserts #89	Used 4	333.4	4.84
3/4" Tubing #333	Used 4	333.4	.83
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 34,560 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: Service line leak
 1909120325

11:30 TO DR

WORK ORDERS BY TYPE

07:46:37

LIST/TYPE: SRLK *✓LEC*

WORK ORDER NO : 51612

SCHEDULED DATE: 09/13/19 SCHEDULED TIME: AM:

ACTIONS: SERVICE LINE LEAK

37.116349

86.213336

LOCATION: LEFT CORNER OF THE YARD/8' OF RD

IN: 01/16/15



***** OLD METER INFORMATION ***** NEW METER INFORMATION *****

5/8 in. TY: G USE: 21 09/03 *
 MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 41943188 83432458 1011 A *
 *
 *

CATEGORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	09/03/19	1011	990	21 A	20959	09/14/11	PULL
	08/02/19	990	969	21 A	41616	12/13/16	READ
	07/02/19	969	935	34 A	27253	10/05/12	MISC
	06/03/19	935	914	21 A	34633	01/16/15	HANG

***** SRLK

9-16-19 Arrival Time: *7:30*

Time	Rate	Cost
<i>3min</i>		
<i>4hrs</i>		
<i>4hrs</i>		
Total Cost		
<i>4hrs</i>		
Total Cost		
<i>4hrs</i>		
Total Cost		

Parts			
Part Description	Used / Ret #	GL #	Cost
<i>3/4" Compression #91</i>	<i>used-2</i>	<i>620.6</i>	<i>28.95</i>
<i>3/4" Insert #89</i>	<i>used-4</i>	<i>333.4</i>	<i>4.84</i>
<i>3/4" Flow #93</i>	<i>used-1</i>	<i>620.6</i>	<i>4.45</i>
<i>3/4" Service tubing #333</i>	<i>used-4</i>	<i>333.4</i>	<i>8.77</i>
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss *204,000* Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: *long service line leak under road*

Date: *9-16-19* Completed Time: *11:30* By: *Dylan J*

WORK ORDERS BY TYPE

10:45:58

CHECKLIST/TYPE: ANGLE
 SCHEDULED DATE: 09/13/19 SCHEDULED TIME: AM: WORK ORDER NO : 51613
 INSTRUCTIONS: PLEASE REPLACE ANGLE VALVE PLUMBER SAYS IT IS BAD

37.092318
 86.090579

METER LOCATION: IN LINE RIGHT CORNER OF HOUSE

IN: 03/22/10



***** OLD METER INFORMATION ***** NEW METER INFORMATION *****

SIZE:	5/8 in.	TY:	G	USE:	12	09/03	*	MAKE	SERIAL	REMOTE	MXUID
1:	36578411				82614015	1474	A				
2:	36578411				82614015	1474	A				
3:											
4:											

HISTORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	09/03/19	1474	1462	12			A
	08/02/19	1462	1445	17	8709	03/16/10	AMR
	07/02/19	1445	1428	17			A
	06/03/19	1428	1410	18			A

***** ANGL

Arrival Date: 9-16-19 Arrival Time: 10:10

Labor Cost			
Employee	Time	Rate	Cost
MM	3mi A		
AF	1hr		
JA	1hr		
MT	1hr		
JA	1hr		
Total Cost			
Vehicle			
Vehicle	Time	Rate	Cost
F150	1hr		
2	1hr		
Total Cost			
Equipment			
Equipment	Time	Rate	Cost
Total Cost			

Parts			
Part Description	Used / Ret #	GL #	Cost
#255 washers	02	334.6	.15
#87 Angle valve	01	110.4	29.19
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: Checked angle valve it is leaking through.

9-11-19 Completed Time: 11:10 By: AF JA JB MT

Will locate by Wednesday 18 at 1:15 PM

WORK ORDERS BY TYPE

09:12:40

CHECKLIST/TYPE: LEAK

WORK ORDER NO : 51623

SCHEDULED DATE: 09/16/19 SCHEDULED TIME: PM:

INSTRUCTIONS: PLEASE REPAIR LEAK AT [REDACTED]

37.157989
86.260966

METER LOCATION: IN LINE W/RGT CORNER HOU 25' OF RD

3967-01

IN: 05/28/10



OLD METER INFORMATION

NEW METER INFORMATION*****

SIZE:	5/8 in.	TY:	G	USE:	40	09/03	*	MAKE	SERIAL	REMOTE	MXUID
1:	36598506			82617829		3760	A				
2:											
3:											
4:											

HISTORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	09/03/19	3760	3720	40	A		
	08/02/19	3720	3684	36	A	10397 04/20/10	AMR
	07/02/19	3684	3603	81	A		
	06/04/19	3603	3555	48	A		

*****LEAK

Arrival Date: 9/18/19 Arrival Time: 11:00

Labor Cost			
Employee	Time	Rate	Cost
JH	3hrs		
DB	3hrs		
Total Cost			
Vehicle			
Vehicle	Time	Rate	Cost
968's	3hrs		
	3hrs		
Total Cost			
Equipment			
Equipment	Time	Rate	Cost
JH	3hrs		
Total Cost			

Parts			
Part Description	Used / Ret #	GL #	Cost
3/4" Comp. Coupling #91	used 2	620.4	28.94
3/4" Inserts #89	used 4	333.4	4.84
3/4" tubing #333	used 3	333.4	.63
Total Cost			

Bud Called 9-16-19 Conf. # 1909161493
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 81,250 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____

Comments: Will need clean up ✓
 Service line

Completed Date: 9/18/19 Completed Time: 3:00 By: JH DB

WORK ORDERS BY TYPE

10:13:31

CHECKLIST/TYPE: SRLK


WORK ORDER NO : 51624

SCHEDULED DATE: 09/16/19 SCHEDULED TIME: PM:

INSTRUCTIONS: SERVICE LINE LEAK... CALLED IN A LEAK BETWEEN AND THE HOUSE ON THE CORNER OF

37.117094 86.258898

METER LOCATION: LEFT SIDE OF HOUSE 9' T ROW TREE 9103 05 IN: 05/19/10



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE: 5/8 in. TY: G USE: 25 09/03 * MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID 1: 36598337 82616716 2922 A * 2: * 3: * 4: *

Table with columns: HISTORY, DATE, CURRENT, PREVIOUS, USAGE, PRIOR W/O, DATE, TYPE. Rows include dates from 06/03/19 to 09/03/19 and usage values.

*****SRLK

Arrival Date: 09-16-19 Arrival Time: 10:30

Tables for Labor Cost, Vehicle, and Equipment. Labor Cost includes employees LM, Dylan, and JC. Vehicle is F-150. Equipment is BA.

Table for Parts with columns: Part Description, Used / Ret #, GL #, Cost. Items include 3/4" Compressor Coupling, 3/4" Insert #89, and 3/4" Flare #93.

Bud Called Conf. # Bill Yes or No / Miles Adj. Bill Yes or No / GPM Est. loss 230,400 Gal. Flushed Cause Of Leak: Time occurred: Length of Interruption: Comments:

Service line

Completed Date: 09-16-19 Completed Time: 2:30 By: Dylan JC

Diploma + Shores

Don't Drive

WORK ORDERS BY TYPE

11:32:28

CHECKLIST/TYPE: SRLK

WORK ORDER NO : 51625

SCHEDULED DATE: 09/16/19 SCHEDULED TIME: AM:

INSTRUCTIONS: SERVICE LINE LEAK CUSTOMER CALLED SAYS WATER IS RUNNING DOWN DITCH ON OTHER SIDE OF THE RD IN FRONT OF HIS PROPERTY OUR LEAK

Wine CC

37.327513
86.214376

METER LOCATION: LEFT CORNER OF YARD

4423-89
IN: 04/25/12



***** OLD METER INFORMATION ***** NEW METER INFORMATION *****

SIZE:	5/8 in.	TY:	G	USE:	19	09/04	*	
MAKE SERIAL	REMOTE	MXUID	CURRENT	*	MAKE	SERIAL	REMOTE	MXUID
1:	43423799		84030759		2507	A	*	
2:							*	
3:							*	
4:							*	

HISTORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	09/04/19	2507	2488	19	A		
	08/05/19	2488	2469	19	A	24334	04/16/12 AMR
	07/03/19	2469	2451	18	A		
	06/03/19	2451	2424	27	A		

***** SRLK

Arrival Date: 9/19/19 Arrival Time: 9:30

Labor Cost				Parts			
Employee	Time	Rate	Cost	Part Description	Used / Ret #	GL #	Cost
LD	4 min			3/4" Comp. Coupling #91	used 2	620.6	28.95
DB	3 hrs			3/4" flow Coupling #93	used 1	620.6	4.45
				3/4" Inserts #89	used 4	333.4	4.84
				3/4" tubing #333	used 25 ft	333.4	5.22
Total Cost:				Total Cost:			
Vehicle	Time	Rate	Cost				
9683	3 hrs						
Total Cost:							

Bud Called 1909172078 Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 46,250 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Service line leak could be under rd (TV)

Completed Date: 9/19/19 Completed Time: 12:30 By: JD DB

Old Bee Spring RD

WORK ORDERS BY TYPE


Wrec wsky 14:44:12

CHECKLIST/TYPER: SRLK
SCHEDULED DATE: 09/16/19 SCHEDULED TIME: PM:
INSTRUCTIONS: SERVICE LINE LEAK CUSTOMER CALLED SAID WATER IS LEAKING IN DITCH LINE BY MAIL BOX BEHIND IT

37.302537
86.285815

METER LOCATION: 15' RIGHT SIDE DRIVE/ 30' OF RD

IN: 02/24/12



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE: 5/8 in. TY: G USE: 51 09/03 *
MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
1: 43423336 83651157 3206 A *
2: *
3: *
4: *

HISTORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	09/03/19	3206	3155	51 A			
	08/02/19	3155	3116	39 A	29594	07/19/13	MISC
	07/02/19	3116	3080	36 A	22534	01/26/12	AMR
	06/03/19	3080	2977	103 A			

*****SRLK

Arrival Date: 9/19/19 Arrival Time: 3:00

Labor Cost			
Employee	Time	Rate	Cost
mm	3min		
JD	2 1/2		
DB	2 1/2		
Total Cost			
Vehicle			
Vehicle	Time	Rate	Cost
9683	2 1/2		
Total Cost			
Equipment			
Equipment	Time	Rate	Cost
TH	2 1/2		
Total Cost			

Parts			
Part Description	Used / Ret #	GL #	Cost
3/4" Comp. Coupling #91	used 2	620.6	28.94
3/4" flow coupling #93	used 1	620.6	4.45
3/4" inserts #89	used 2	333.4	2.42
3/4" tubing #333	used 28ft	333.4	5.84
1 1/2" casing pipe #439	used 2ft	333.4	71.43
Total Cost			

Bud Called 1909172066 Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: 115,560 Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Service line leak could be under rd
 not sure. JD - Will need clean up

Completed Date: 9/19/19 Completed Time: 5:30 By: JD DB

WORK ORDERS BY TYPE

08:02:47

CHECKLIST/TYPE: SRLK

WORK ORDER NO : 51636

SCHEDULED DATE: 09/17/19 SCHEDULED TIME: AM:

INSTRUCTIONS: SERVICE LINE LEAK REPAIR S [REDACTED]

37.292123
86.025116

METER LOCATION: LEFT CORNER OF HOUSE

IN: 11/29/17



ISSUED: 09/17/19 BY: [REDACTED]
*****OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE:	MAKE	SERIAL	REMOTE	MXUID	TY:	G USE:	CURRENT	MAKE	SERIAL	REMOTE	MXUID
5/8 in.							0 08/19				
1:	40356815			83004754			3012 A				
2:											
3:											
4:											

HISTORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	08/19/19	3012	3012	0 A	34522	01/02/15	HANG
	07/18/19	3012	3012	0 A	45300	11/29/17	HANG
	06/17/19	3012	3012	0 A	44060	08/08/17	DISC
	05/20/19	3012	3012	0 A	43659	07/03/17	VOID

Arrival Date: 9/19/19 Arrival Time: 7:30

Labor Cost			
Employee	Time	Rate	Cost
mm	3 min		
JD	2hr		
DB	2hr		
Total Cost			

Parts			
Part Description	Used / Ret #	GL #	Cost
3/4" Comp. Coupling #91	Used 2	620.6	28.95
3/4" Inserts #89	Used 4	333.4	4.84
3/4" tubing #333	Used 4 ft	333.4	.83
Total Cost			

Vehicle			
Vehicle	Time	Rate	Cost
91683	2hr		
Total Cost			
Equipment			
Equipment	Time	Rate	Cost
TTT	2hr		
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 109,440 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

used out of stock meter box

9/19/19 Completed Time: 9:30 By: JD DB


WORK ORDERS BY TYPE

08:23:21

VLCC
 /18/19 SCHEDULED TIME: PM: WORK ORDER NO : 51726
 MISCELLANEOUS REPLACE SERVICE LINE SRLK

METER LOCATION:

IN:



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE: 5/8 in. TY: G USE: 0 *
 MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 1: *
 2: *
 3: *
 4: *

HISTORY: DATE CURRENT PREVIOUS USAGE PRIOR W/O DATE TYPE

*****SRLK

Arrival Date: 9-19-19 Arrival Time: 1:30

Labor Cost				Parts			
Employee	Time	Rate	Cost	Part Description	Used / Ret #	GL #	Cost
DB	1 1/2 hrs			3/4" Comp Coupling #91	used-1	620.0	14.42
JD	1 1/2 hrs			3/4" Inserts #89	used-2	333.9	2.42
				3/4" Flow Coupling #93	used-1	620.0	4.45
Total Cost							
Vehicle	Time	Rate	Cost	Total Cost			
9683	1 1/2 hrs						

Bud Called _____ Conf. # _____

Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____

Est. loss 106,230 Gal. Flushed _____

Cause Of Leak: _____ Time occurred: _____

Length of Interruption: _____

Comments: _____

Service line

Equipment	Time	Rate	Cost
TH	1 1/2 hrs		
Total Cost			

WORK ORDERS BY TYPE

08:22:01

✓ Lec
CHECKLIST/TYPE: SRLK

WORK ORDER NO : 51727

SCHEDULED DATE: 09/18/19 SCHEDULED TIME: AM:

INSTRUCTIONS: MISCELLANEOUS REPLACE SERVICE LINE SRLK

PER LOCATION:

IN:

METER INFORMATION*****

SERIAL REMOTE MXUID

HISTORY: DATE CURRENT PREVIOUS USAGE PRIOR W/O DATE TYPE

SRLK

Date: 9/18/19 Arrival Time: 8:30

Cost				Parts			
Fee	Time	Rate	Cost	Part Description	Used / Ret #	GL #	Cost
	3 min			3/4" Comp. Coupling #91	used 4	620.6	57.88
	2 1/2			3/4" Inserts #89	used 8	333.4	9.67
	2 1/2			3/4" Flow Coupling #93	used 2	620.6	8.90
				3/4" tubing #333	used 8ft	333.4	1.67
Total Cost				Total Cost			
	Time	Rate	Cost				
	2 1/2						
	2 1/2						
Total Cost							
	Time	Rate	Cost				
	2 1/2						
Total Cost							

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 129,600 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____

Comments: Service line

WORK ORDERS BY TYPE

09:19:09

CHECKLIST/TYPE: SRLK

WORK ORDER NO : 51753


SCHEDULED DATE: 09/19/19 SCHEDULED TIME: AM:

INSTRUCTIONS: SERVICE LINE LEAK [REDACTED] CALLED SAYS THERE IS A LEAK IN DITCH 50 FT PAST DRIVEWAY ON THE RIGHT HAND SIDE

37.113225
86.156430

METER LOCATION: LEFT SIDE DRIVE BESIDE HOUSE

3983-89
IN: 03/25/10



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE:	5/8 in.	TY:	G	USE:	20	09/03	*
MAKE SERIAL	REMOTE	MXUID	CURRENT	MAKE	SERIAL	REMOTE	MXUID
1:	36577882	82613488	2185	A	*		
2:					*		
3:					*		
4:					*		

HISTORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	09/03/19	2185	2165	20	A		
	08/02/19	2165	2142	23	A	8818 03/16/10	AMR
	07/02/19	2142	2124	18	A		
	06/03/19	2124	2102	22	A		

*****SRLK

Arrival Date: 9-24-19 Arrival Time: 7:30

Labor Cost			
Employee	Time	Rate	Cost
MM	30 min		
Oylan	3 hrs		
DB	3 hrs		
Total Cost			
Vehicle	Time	Rate	Cost
9683	3 hrs		
Total Cost			
Equipment	Time	Rate	Cost
JH	3 hrs		
Total Cost			

Parts			
Part Description	Used / Ret #	GL #	Cost
3/4" Flx # 93	used-2	620.6	4.45
# 91			
3/4" compressor coupling	used-2	620.6	28.94
3/4" Insert # 89	used-4	333.4	4.84
3/4" Tubing # 333	used-22	333.4	5.64

Bud Called _____ Conf. # 190 9231897

Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____

Est. loss 103,680 Gal. Flushed _____

Cause Of Leak: _____ Time occurred: _____

Length of Interruption: _____

Comments: Marked in blue paint service line leak

Under road

Completed Date: 9-24-19 Completed Time: 10:30 By: Dylan DB


WORK ORDERS BY TYPE

10:48:08

CHECKLIST/TY: ANGLE WORK ORDER NO : 51757
 SCHEDULED DATE: 09/19/19 SCHEDULED TIME: AM:
 INSTRUCTIONS: ANGLE VALVE CUSTOMER CALL SAID ANGLE VALVE IS
 BAD WOULD LIKE IT OT BE REPLACED

37.327513
 86.214376

METER LOCATION: LEFT CORNER OF YARD 4423-89
 IN: 04/25/12



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE: 5/8 in. TY: G USE: 19 09/04 *
 MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 1: 43423799 84030759 2507 A *
 2: *
 3: *
 4: *

HISTORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	09/04/19	2507	2488	19 A			
	08/05/19	2488	2469	19 A	51625	09/16/19	SRLK
	07/03/19	2469	2451	18 A	24334	04/16/12	AMR
	06/03/19	2451	2424	27 A			

*****ANGL

Arrival Date: 9-20-19 Arrival Time: 845

Labor Cost				Parts			
Employee	Time	Rate	Cost	Part Description	Used / Ret #	GL #	Cost
MT	55m			3/4 Angel Valve #87	U-1	620.6	29.19
JA	55m			Washer 255	U-2	334.5	.15
Total Cost				Total Cost			
Vehicle	Time	Rate	Cost				
2	55m						
Total Cost							
Equipment	Time	Rate	Cost				
Total Cost							

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

9-20-19 9:40 MT JA

WORK ORDERS BY TYPE

07:49:54

CHECKLIST/TYPER: ^{✓sc} SRLK
 SCHEDULED DATE: 09/23/19 SCHEDULED TIME: PM:
 INSTRUCTIONS: SERVICE LINE LEAK LEAK AT PIGTAIL

WORK ORDER NO : 51804

37.371584
 86.215977

METER LOCATION: 15 FT LEFT OF LIGHT POLE

4830-89
 IN: 05/11/12



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE: 5/8 in.	TY: G	USE: 6	09/18	*					
MAKE SERIAL	REMOTE	MXUID	CURRENT	*	MAKE	SERIAL	REMOTE	MXUID	
1: 43423497		84030888	156 A	*					
2: 43423497		84030888	18520	*					
3:				*					
4:				*					

HISTORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	08/20/19	150	150	0 A			
	07/18/19	150	149	1 A	25512	05/22/12	MISC
	06/18/19	149	148	1 A	25202	05/09/12	AMR
	05/21/19	148	148	0 A			

*****SRLK

Arrival Date: 9-23-19 Arrival Time: 8:30

Labor Cost			
Employee	Time	Rate	Cost
Dylan	1 1/2 hr		
MT	1 1/2 hr		
Total Cost			
Vehicle	Time	Rate	Cost
F-150	1 1/2 hr		
Total Cost			
Equipment	Time	Rate	Cost
Total Cost			

Parts			
Part Description	Used / Ret#	GL#	Cost
3/4" Compressor Capling #91	used-1	600.6	14.49
3/4" Insert #89	used-2	333.4	2.42
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM Yes Y TIE
 Est. Joss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: We had leak on pig tail

9-23-19

Completed Time: 10:00

By: Dylan MT

CHECKLIST/TYPE: SRLK

WORK ORDER NO : 51805

SCHEDULED DATE: 09/23/19 SCHEDULED TIME: AM:

INSTRUCTIONS: SERVICE LINE LEAK CUSTOMER CALLED SAYS THERE IS A WATER LEAK WHERE HIS LINE GOES UNDER THE RD IN [REDACTED]

37.284838
86.013764

METER LOCATION: LEFT SIDE DRIVE

5278-89
IN: 04/21/11



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE:	5/8 in.	TY:	G	USE:	33	09/17	*		
MAKE	SERIAL	REMOTE	MXUID	CURRENT	*	MAKE	SERIAL	REMOTE	MXUID
1:	41940981		83431740	1390	A	*			
2:						*			
3:						*			
4:						*			

HISTORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	08/19/19	1357	1335	22	A		
	07/17/19	1335	1317	18	A	18264	04/15/11 AMR
	06/17/19	1317	1299	18	A		
	05/20/19	1299	1265	34	A		

*****SRLK

Arrival Date: 9-24-19 Arrival Time: 10:30

Labor Cost			
Employee	Time	Rate	Cost
M/M	3min		
Dylan	2hrs		
OB	2hrs		
Total Cost			
Vehicle	Time	Rate	Cost
9683	2hrs		
Total Cost			
Equipment	Time	Rate	Cost
TH	2hrs		
Total Cost			

Parts			
Part Description	Used / Ret #	GL #	Cost
3/4" compressor coupling #91	used-2	620.6	28.94
3/4" insert #89	used-3	333.4	3.63
3/4" service tubing #333	used-4	333.4	1.83
Total Cost			

Bud Called 9-23-19 2:35pm Conf. # 1909231912
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 122,800 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: Small service line leak across road from
9442

Completed Date: 9-24-19 Completed Time: 1:30 By: [REDACTED] OB

CHECKLIST/TYPE: MISC *VCC*

WORK ORDER NO : 51807

SCHEDULED DATE: 09/23/19 SCHEDULED TIME: AM:


INSTRUCTIONS: CUSTOMER SAID THAT THE METER BOX IS STANDING FULL OF WATER AND WOULD LIKE SOMEONE TO CHECK IT OUT FOR THEM.

37.284337

86.211620

METER LOCATION: BEHIND ELECTRIC POLE ANCHOR

IN: 10/06/10



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE:	5/8 in.	TY:	G	USE:	2	09/17	*		
MAKE	SERIAL	REMOTE	MXUID	CURRENT	*	MAKE	SERIAL	REMOTE	MXUID
1:	36547651		82576353	681 A	*				
2:					*				
3:					*				
4:					*				

HISTORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	08/19/19	679	675	4 A	2606	09/02/08	READ
	07/17/19	675	665	10 A	26900	09/10/12	ANGL
	06/17/19	665	659	6 A	15003	10/14/10	READ
	05/20/19	659	655	4 A	14576	09/27/10	AMR

*****MISC

Arrival Date: 9-25-19 Arrival Time: 12:30

Labor Cost			
Employee	Time	Rate	Cost
MH	3min		
Dylan	2hrs		
DB	2hrs		
MI	2hrs		
Total Cost			
Vehicle	Time	Rate	Cost
F-150	2hrs		
9683	2hrs		
Total Cost			
Equipment	Time	Rate	Cost
IT	2hrs		
Total Cost			

Parts			
Part Description	Used / Ret #	GL #	Cost
3/4" <i>#91</i> compression coupling	used-2	620.6	12.94
3/4" Insert <i>#89</i>	used-3	333.4	3.63
3/4" Tubing <i>#383</i>	used-2A	333.4	.42
Total Cost			

Bud Called 9-24-19 Conf. # 1909740844
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 108,000 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Main Service Line Leak

Completed Date: 9-25-19 Completed Time: 2:30 By: _____

WORK ORDERS BY TYPE

15:18:52

LIST/TYPE: MISC
 SCHEDULED DATE: 09/23/19 SCHEDULED TIME: PM:
 INSTRUCTIONS: MOVE METER
 WORK ORDER NO: 51814

METER LOCATION: UNDELEC FENCE LEFT SIDE GRAVE YD

37.070261
 86.131214
 2674 99
 IN: 04/14/10



*****OLD METER INFORMATION***** NEW METER INFORMATION*****
 SIZE: 5/8 in. TY: G USE: 185 09/03 *
 MAKE SERIAL REMOTE MXUID CURRENT MAKE SERIAL REMOTE MXUID
 1: 36578218 82614051 2564 A *
 2: 36578218 82614051 275370 *
 3:
 4:

HISTORY:

DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
09/03/19	2564	2379	185 A	46002	02/20/18	DISC
08/02/19	2379	2248	131 A	46708	04/25/18	REHA
07/02/19	2248	2172	76 A	46662	04/24/18	DISC
06/03/19	2172	2084	88 A	46052	02/21/18	REHA

Arrival Date: 9-27-19 Arrival Time: 7:30

Employee	Time	Rate	Cost
JH	5pm		
JD	5 1/2		
DB	5 1/2		
DH	2 1/2		
Total Cost			
Vehicle	Time	Rate	Cost
9683	1 1/2		
F-350	1 1/2		
Total Cost			
Equipment	Time	Rate	Cost
JH	2hrs		
BR	1 1/2		
Total Cost			

Part Description	Used / Ret #	GL #	Cost
Service Tubing 3/4" x 3/4" #333	used-654	333.4	13.57
HDPE Pipe 1 1/4" #1095	used-584	554.D	28.20
Reg meter box #457	used-1	334.5	64.10
Service Saddle 3" x 3/4" #33	used-1	333.4	22.58
Corp Stop 3/4" #83	used-1	333.4	26.95
Brass Comp Coupling 3/4" used #91	used-1		
Total Cost			

3 1/4" SS inserts #83 - used 2 each

Completed Date: 9-27-19 Completed Time: 2:00 By: JD DB

✓LEC

CHECKLIST/TYPE: SRLK

WORK ORDER NO : 51819


SCHEDULED DATE: 09/24/19 SCHEDULED TIME: AM:

INSTRUCTIONS: CUSTOMER SAID HE CALLED 3 WEEKS TO A PERSON ON CALL AT 4 AM ABOUT A LEAK. HE CAME OUT AND MARKED IT AND SAID IT WAS A ~~SERVICE~~ LINE LEAK AND WE WOULD BE BACK OUT. HE SAID ITS LEAKING PRETTY BAD

37.275724
86.378620

METER LOCATION: LINE LEFT CORNER OF HOUSE

IN: 02/18/11



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE: 5/8 in. TY: G USE: 60 09/03 *
MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
1: 40355443 83010009 4122 A *
2: *
3: *
4: *

HISTORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	09/03/19	4122	4062	60 A	16994	02/25/11	MISC
	08/02/19	4062	4034	28 A	40190	07/29/16	MISC
	07/02/19	4034	4001	33 A	36067	06/17/15	MISC
	06/03/19	4001	3964	37 A	31249	01/29/14	MNLK

*****SRLK*****

Arrival Date: 9-25-19 Arrival Time: 2:30

Labor Cost			
Employee	Time	Rate	Cost
Dylan	1 1/2 hr		
DB	1 1/2 hr		
MI	1 1/2 hr		
Total Cost			

Parts			
Part Description	Used / Ret #	GL #	Cost
3/4" Compressor coupling #91	used-2	620.6	28.94
3/4" Insert #89	used-3	333.4	3.63
3/4" Tubing #333	used-2ft	333.4	.42
Total Cost			

Vehicle	Time	Rate	Cost
R-150	1/2 hr		
9683	1/2 hr		
Total Cost			

Equipment	Time	Rate	Cost
FH	1 1/2 hr		
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 180,000 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____

Comments: Phone line is located
 Service line

WORK ORDERS BY TYPE

04/19/12 dr 9410


12:55:23

VLEC

CHECKLIST/TYPER: SRLK WORK ORDER NO : 51820
SCHEDULED DATE: 09/24/19 SCHEDULED TIME: PM:
INSTRUCTIONS: SERVICE LINE LEAK NEW OWNER CALLED SAID
THERE IS A SERVICE LINE LEAK BETWEEN HIS HOUSE AND
THE NABORS IN DITCH LINE

37.319362
86.222877

METER LOCATION: LEFT SIDE OF LIGHT POLE 4808 01
IN: 03/26/12



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE: 5/8 in. TY: G USE: 0 09/04 *
MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
1: 41940598 83433067 1216 A *
2: *
3: *
4: *

***** HISTORY: DATE CURRENT PREVIOUS USAGE PRIOR W/O DATE TYPE *****

Table with columns: DATE, CURRENT, PREVIOUS, USAGE, PRIOR W/O, DATE, TYPE. Rows include dates from 06/04/19 to 09/04/19 and meter readings like 1216, 1208, 1196, 0 A, 33166, 47814, 44930, 35244.

***** SRLK *****

Arrival Date: 9-25-19 Arrival Time: 9:00

Tables for Labor Cost and Equipment. Labor Cost table includes Employee (MM, Dylan, MT, OB), Time, Rate, Cost. Equipment table includes Equipment (IF), Time, Rate, Cost.

Parts table with columns: Part Description, Used / Ret #, GL #, Cost. Rows include 3/4" compression coupling #91, 3/4" Insert #89, 3/4" fl on #93.

Bud Called 9-24-19 Conf. # 1909241910
Bill Yes or No / Miles Adj. Bill Yes or No / GPM
Est. loss 22,000 Gal. Flushed
Cause Of Leak: Time occurred:
Length of Interruption:
Comments: Service leak

Completed Date: 9-25-19 Completed Time: 11:00 By: Dylan

WORK ORDERS BY TYPE

LU
unrec
wsky 08:30:51

CHECKLIST/TYPER: MISC ^{✓LEC}
 SCHEDULED DATE: 09/26/19 SCHEDULED TIME: AM:
 INSTRUCTIONS: WE DISCONNECTED CUSTOMER, AND REHUNG THE METER
 AND NOW SHES SAYS THE METER IS LEAKING?
 WORK ORDER NO : 51827

37.154733
86.225177

METER LOCATION: LEFT SIDE OF DR LEFT CORNER OF HOUSE

IN: 11/29/16

*****OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE:	5/8 in.	TY:	G	USE:	42	09/03	*						
MAKE	SERIAL	REMOTE		MXUID		CURRENT	*	MAKE	SERIAL	REMOTE	MXUID		
1:	36599030			82617761		8801 A	*						
2:	36599030			82617761		891020	*						
3:							*						
4:							*						

HISTORY:	DATE	CURRENT	PREVIOUS	USAGE		PRIOR W/O	DATE	TYPE
	09/03/19	8801	8759	42	A	41478	11/29/16	HANG
	08/02/19	8759	8638	121	A	51740	09/18/19	REHAN
	07/02/19	8638	8505	133	A	51667	09/17/19	DISC
	06/03/19	8505	8356	149	A	41776	01/16/17	MISC

*****MISC

Arrival Date: 9-30-19 Arrival Time: 3:30

Labor Cost				Parts			
Employee	Time	Rate	Cost	Part Description	Used / Ret #	GL #	Cost
CIO	3 min			3/4" Coupling # 91	U-1	620.6	13.73
JC	2h			3/4" Inserts # 89	U-2	333.4	2.42
DH	2h						
Total Cost							
Vehicle	Time	Rate	Cost				
F-150	2h						
Total Cost							
				Bud Called <u>9-27-19</u> Conf. # <u>1909270855</u> Bill Yes or No / Miles _____ Adj Bill Yes or No / GPM _____ Est. loss _____ Gal. Flushed _____ Cause Of Leak: _____ Time occurred: _____ Length of Interruption: _____ Comments: <u>Pigtail leak need to snake out</u> *It was our leak*			
				Total Cost			
Equipment	Time	Rate	Cost				
BH	2h						
Total Cost							

Completed Date: 9-30-19 Completed Time: 5:30 By: RC DH

WORK ORDERS BY TYPE

Wmeco
u sky 11:09:10


SRLK
09/26/19 SCHEDULED TIME: AM:
SERVICE LINE LEAK

WORK ORDER NO : 51832

METER LOCATION: ACR FENCE RT SIDE P O BUILDING

0991 07
IN: 10/22/15

37.250459
86.182464



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE:	5/8 in.	TY:	G	USE:	72	09/17	*	MAKE	SERIAL	REMOTE	MXUID
1:	47762883	86446499	3425	A							
2:											
3:											
4:											

HISTORY:

DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
09/17/19	3425	3353	72 A			
08/19/19	3353	3170	183 A	37263	10/21/15	MISC
07/17/19	3170	3030	140 A	13705	09/01/10	AMR
06/17/19	3030	2822	208 A			

Arrival Date: 9-30-19 Arrival Time: 8:00

Labor Cost			
Employee	Time	Rate	Cost
MH Sm			
JK	1h		
DH	1h		
Total Cost			
Vehicle			
Vehicle	Time	Rate	Cost
F-150	1h		
Total Cost			
Equipment			
Equipment	Time	Rate	Cost
BH	1h		
Total Cost			

Parts			
Part Description	Used / Ret #	GL #	Cost
3/4" couplings #91	U-2	620.6	27.44
3/4" inserts #89	U-3	333.4	5.63
3/4" tubing #233	U-3ft	333.4	.63
Total Cost			

Bud Called 9-27-19 Conf. # 1909270364

Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____

Est. loss _____ Gal. Flushed _____

Cause Of Leak: _____ Time occurred: _____

Length of Interruption: _____

Comments: SERVICE LINE

Completed Date: 9-30-19 Completed Time: 9:00 By: JK DH

WORK ORDERS BY TYPE

08:41:15

CHECKLIST/TY: SRLK

SCHEDULED DATE: 09/27/19 SCHEDULED TIME: PM:

WORK ORDER NO : 51841

INSTRUCTIONS: SERVICE LINE LEAK [REDACTED] CALL SAYS THERE IS A WATER LEAK ON LEFT HAND SIDE OF RD ACROSS [REDACTED]

37.197362
86.255635

METER LOCATION: LEFT SIDE DRIVE

6498-91
IN: 03/26/10



SIZE: 5/8 in. TY: G USE: 46 09/03 *
 MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 1: 36578337 82614243 4171 A *
 2: *
 3: *
 4: *

NEW METER INFORMATION*****

HISTORY: DATE CURRENT PREVIOUS USAGE PRIOR W/O DATE TYPE

09/03/19	4171	4125	46 A			
08/02/19	4125	4087	38 A	48908	11/29/18	RBOX
07/02/19	4087	4060	27 A	8902	03/25/10	CHECK
06/03/19	4060	4018	42 A			

*****SRLK

Arrival Date: 9-27-19 Arrival Time: 2:30

Labor Cost				Parts			
Employee	Time	Rate	Cost	Part Description	Used / Ret #	GL #	Cost
MM	3min			3/4" compressor coupling #91	used-2	620.6	27.46
Dylan	2hrs			3/4" Insert #89	used-4	333.4	4.84
MT	2hrs			3/4" Flow #93	used-1	620.6	4.46
JC	2hrs			3/4" Tubing #333	used-2 off	333.4	4.19
Total Cost				Total Cost			

Vehicle	Time	Rate	Cost
F-150	2hrs		
F-150	2hrs		
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 100,800 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____

Equipment	Time	Rate	Cost
TH	2hrs		
Total Cost			

Comments: Service line

Completed Date: 9-27-19 Completed Time: 4:30 By: Dylan

WORK ORDERS BY TYPE

11:34:39

CHECKLIST/TY: MISC

WORK ORDER NO : 51844

SCHEDULED DATE: 09/27/19 SCHEDULED TIME: AM:

INSTRUCTIONS: CUSTOMER CALLED IN AND WATER IS BUBBLING OUT OF METER BOX AT THERE METER OR THE METER OF THE NEIGHBOR NEXT DOOR NOT SURE WHICH IS THERES PLEASE CHECK OUT.

37.069552
86.137954

METER LOCATION: RIGHT SIDE OF POST OFFICE

IN: 04/14/10

*****OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE:	5/8 in.	TY:	G	USE:	2	09/03	*				
MAKE	SERIAL	REMOTE		MXUID		CURRENT	*	MAKE	SERIAL	REMOTE	MXUID
1:	36578201			82614613		926 A	*				
2:							*				
3:							*				
4:							*				

*****HISTORY*****

HISTORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	09/03/19	926	924	2 A	39744	06/29/16	RBOX
	08/02/19	924	922	2 A	46491	04/03/18	SRLK
	07/02/19	922	919	3 A	45646	01/08/18	MISC
	06/03/19	919	917	2 A	42100	02/21/17	VOID

Arrival Date: 9/27/19 Arrival Time: 3:00

Labor Cost				Parts			
Employee	Time	Rate	Cost	Part Description	Used / Ret #	GL #	Cost
MH	5 min			3/4" Comp Coupling #91	used 2	620.6	27.46
JD	1 hr			3/4" Flow Coupling #93	used 1	420.6	4.45
DB	1 hr			3/4" Inserts #89	used 4	333.4	4.84
				3/4" Tubing #333	used 4 ft	333.4	1.83
Total Cost							
Vehicle	Time	Rate	Cost				
91683	1 hr			Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 194,400 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Service line

Completed Date: 9/27/19 Completed Time: 4:00 By: JD DB