

WORK ORDERS BY TYPE

08:05:05

E: MISC
 E: 10/30/19 SCHEDULED TIME: AM:
 REPLACE VALVE BOX AT FIRE HYDRANT

WORK ORDER NO : 52169

37.379 30
 86.002 98

METER LOCATION: LEFT OF [REDACTED]

IN: 03/30/18



***** NEW METER INFORMATION*****

SIZE:	5/8 in.	TY:	G	USE:	113	07/12	*
MAKE SERIAL	REMOTE	MXUID	CURRENT	MAKE	SERIAL	REMOTE	MXUID
1:	40356580		83004787	1986 A			
2:							
3:							
4:							

HISTORY:

DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
07/12/18	1986	1873	113 A	52168	10/30/19	RBOX
06/19/18	1873	1689	184 A	47410	07/10/18	PULL
05/18/18	1689	1484	205 A	46537	04/10/18	RBOX
03/30/18	1484	1484	0	46472	03/30/18	HANG

MISC

Arrival Date: 11-6-19 Arrival Time: 9:45

Labor Cost			
Employee	Time	Rate	Cost
Dylan	20min		
JK	20min		
Total Cost			
Vehicle			
Vehicle	Time	Rate	Cost
F-150	20min		
Total Cost			
Equipment			
Equipment	Time	Rate	Cost
Total Cost			

Parts			
Part Description	Used / Ret #	GL #	Cost
24" x 36" # 471 valve box	used-1	6206	39.02
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

WORK ORDERS BY TYPE

08:08:32

CHECKLIST/TYPE: RLID

WORK ORDER NO

52397


SCHEDULED DATE: 11/13/19 SCHEDULED TIME: AM:

INSTRUCTIONS: REPLACE METER BOX LID - STATE BROKE COVER WHILE MOWING. CAUSING CUSTOMER METER TO FREEZE UP

37.345311
86.047306

METER LOCATION: LFT SIDE MTR 41943278/RT OF DRWAY 75'

IN: 11/06/14



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE:	5/8 in.	TY:	G	USE:	40	10/18	*
MAKE SERIAL	REMOTE	MXUID	CURRENT	MAKE	SERIAL	REMOTE	MXUID
1:	40356188	83010164	2274	A			
2:	40356188	83010164					
3:							
4:							

HISTORY:

DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
10/18/19	2274	2234	40 A			
09/18/19	2234	2195	39 A			
08/19/19	2195	2147	48 A	39114	05/02/16	MISC
07/18/19	2147	2106	41 A			

Arrival Date: 11-14-19 Arrival Time: 9:00 *****RLID

Labor Cost				Parts			
Employee	Time	Rate	Cost	Part Description	Used / Ret #	GL #	Cost
CC	5 min			#459	002/00X 01	6204	86.34
JA	1 hr.						
AF	1 hr.						
Total Cost:							
Vehicle	Time	Rate	Cost	Total Cost			
?	1 hr.						
Total Cost:							

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: 36577744

Equipment	Time	Rate	Cost
Total Cost:			

Completed Date: 11-14-19 Completed Time: 10:00 By: JA AF

WORK ORDERS BY TYPE

08:22:23

CHECKLIST/TYPE: RBOX
 SCHEDULED DATE: 11/15/19 SCHEDULED TIME: AM:
 INSTRUCTIONS: REPLACE DUAL METER BOX #459 - COMPLETED

WORK ORDER NO : 52413

37.345311
 86.047306

METER LOCATION: LFT SIDE MTR 41943278/RT OF DRWAY 75'

IN: 11/06/14



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE:	5/8 in.	TY:	G	USE:	40	10/18	*						
MAKE	SERIAL	REMOTE		MXUID		CURRENT	*	MAKE	SERIAL	REMOTE	MXUID		
1:	40356188			83010164		2274 A	*						
2:							*						
3:							*						
4:							*						

HISTORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	10/18/19	2274	2234	40 A			
	09/18/19	2234	2195	39 A	52397	11/13/19	RLID
	08/19/19	2195	2147	48 A	39114	05/02/16	MISC
	07/18/19	2147	2106	41 A			

*****RBOX

Arrival Date: 11-25-19 Arrival Time: 12:00

Labor Cost				Parts			
Employee	Time	Rate	Cost	Part Description	Used / Ret #	GL #	Cost
CC	5min			#459 Dual Box	U1	620.61	86.36
JA	1hr						
Total Cost							
Vehicle	Time	Rate	Cost	Total Cost			
4	1hr						
Total Cost							
Equipment	Time	Rate	Cost	Bud Called _____ Conf. # _____			
Total Cost				Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____			
				Est. Joss _____ Gal. Flushed _____			
				Cause Of Leak: _____ Time occurred: _____			
				Length of Interruption: _____			
				Comments: _____			

Completed Date: 11-25-19 Completed Time: 1:00 By: JA

WORK ORDERS BY TYPE

15:14:57

CHECKLIST/TYPE: HANG


SCHEDULED DATE: 11/01/19 SCHEDULED TIME: 10:00 AM

WORK ORDER NO : 52308

INSTRUCTIONS: PLEASE HANG METER BACK FOR OWNER
INSTALLED ELSEWHERE LEAVE OFF AT METER

METER LOCATION: LEFT CORNER OF YARD

2194 99
IN: 10/25/10



552 334-4 168-57

*****OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE: 5/8 in. TY: G USE: 10 08/24 *
MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
1: 40356616 83004718 3733 A * 50745649
2: * R-10
3: * ME
4: *



HISTORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	08/24/16	3733	3723	20 A	51863	09/30/19	SRLK
	08/03/16	3723	3703	20 A	40440	08/23/16	DISC
	07/06/16	3703	3668	35 A	38234	01/19/16	VOID
	06/03/16	3668	3644	24 A	34087	11/07/14	MISC

Arrival Date: 11-4-19 Arrival Time: 1:00 100 *****HANG

Labor Cost			
Employee	Time	Rate	Cost
MM	3mm		
Sm	3:00 hr		
MT	3:00 hr		
Total Cost			
Vehicle			
Vehicle	Time	Rate	Cost
F150	3:00 hr		
Total Cost			
Equipment			
Equipment	Time	Rate	Cost
Total Cost			

Parts			
Part Description	Used / Ret #	GL #	Cost
Plug #261	R-1	334.5	
meter Coupling #147 lock	R-1	620.6	
Pad Lock #266	R-1	334.5	
washer #255	U-2	334.5	.15
1/2 PVC pipe #492	U-1FT	333.4	.25
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Left on @ Customer Req

11-4-19

WORK ORDERS BY TYPE

12:07:33

CHECKLIST/TY: ANGL

SCHEDULED DATE: 10/28/19 SCHEDULED TIME: PM:


WORK ORDER NO : 52158

INSTRUCTIONS: ANGLE VALVE CUSTOMER CALL SAYS ANGLE VALVE IS BAD NEEDS REPALCEING

37.319362
86.222877

METER LOCATION: IN LINE W/RIGHT SD LOG HOUSE/5' RD

5764 93
IN: 03/26/12



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE:	5/8 in.	TY:	G	USE:	18	10/03	*	MAKE	SERIAL	REMOTE	MXUID
1:	41940612			83432384		262 A	*				
2:							*				
3:							*				
4:							*				

*****HISTORY*****

HISTORY:	DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
	10/03/19	262	244	18 A			
	09/04/19	244	226	18 A	23389	03/16/12	AMR
	08/05/19	226	226	0 A			
	07/03/19	226	226	0 A			

*****ANGL

Arrival Date: 11-4-19 Arrival Time: 10:30

Labor Cost			
Employee	Time	Rate	Cost
MM	3min		
SM	60min		
MT	60min		
Total Cost			
Vehicle			
Vehicle	Time	Rate	Cost
F-150	60min		
Total Cost			
Equipment			
Equipment	Time	Rate	Cost
Total Cost			

Parts			
Part Description	Used / Ret#	GL#	Cost
7" 3/4 X 3/4 Resetter #21	U-1	620.6	83.88
Meter Washers #255	Used-4	334.5	.31
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: Have to change line in gravel driveway, possibly use short resetter.

Completed Date: 11-4-19

Completed Time: 11:30 By: SM & MT

WORK ORDERS BY TYPE

14:59:22

CHECKLIST/TYPE: ANGL

WORK ORDER NO : 52319

SCHEDULED DATE: 11/04/19 SCHEDULED TIME: PM:

INSTRUCTIONS: ANGLE VALVE... WAS TRYING TO CLOSE UP FOR WINTER. THE VALVE WILL NOT SHUT OFF BY ROAD. EXP L WE WILL CHECK AND REPAIR. POSSIBLE CHARGE.

37.323649
86.221974

METER LOCATION: LEFT SIDE CONCRETE DRIVE 15FT RD

IN: 05/30/19



OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE:	5/8 in.	TY:	G	USE:	0	10/02	*	MAKE	SERIAL	REMOTE	MXUID
1:	50003875			87616601		33	A				
2:											
3:											
4:											

HISTORY:

DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
10/02/19	33	33	0 A	40089	07/19/16	DISC
09/04/19	33	25	8 A	50553	05/29/19	HANG
08/05/19	25	16	9 A	48995	12/11/18	SRLK
07/03/19	16	0	16 A	40089	07/19/16	DISC

*****ANGL

Arrival Date: 11-8-19 Arrival Time: 1:30

Labor Cost			
Employee	Time	Rate	Cost
8m	3m:n		
JA	30m		
AF	30m		
Total Cost			
Vehicle			
Vehicle	Time	Rate	Cost
F15L	30m		
Total Cost			
Equipment			
Equipment	Time	Rate	Cost
Total Cost			

Parts			
Part Description	Used / Ret#	GL#	Cost
#255 washers	02	334.5	.15
#187 Angle valve	01	620.6	30.98
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: ~~Notes changed~~ left off

Completed Date: 11-8-19 Completed Time: 2:00 By: JA AF

LEC ✓
 W mccc
 usky

WORK ORDERS BY TYPE

13:19:07

CHECKLIST/TYPER: MNLK

WORK ORDER NO : 52061


SCHEDULED DATE: 11/06/19 SCHEDULED TIME: PM:

INSTRUCTIONS: MAIN LINE LEAK CUSTOMER CALLED SAYS THERE IS A LEAK RIGHT BEFORE DRIVEWAY RUNNING DOWN FIELD

37.139936
 86.162593

METER LOCATION: 30' RIGHT SIDE OF DRIVE 30' OF RD

N: 03/24/10



***** NEW METER INFORMATION*****

SIZE:	5/8 in.	TY:	G	USE:	45	11/04	*
MAKE SERIAL	REMOTE	MXUID	CURRENT	MAKE	SERIAL	REMOTE	MXUID
1:	36578297	82614125	4569 A				
2:							
3:							
4:							

HISTORY:

DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
10/02/19	4524	4479	45 A	12275	07/20/10	DISC
09/03/19	4479	4435	44 A	50162	04/19/19	PERIO
08/02/19	4435	4398	37 A	36540	08/04/15	LEAK
07/02/19	4398	4358	40 A	12728	07/29/10	REHA

Arrival Date: 11-6-19 Arrival Time: 2:30

Labor Cost	Employee	Time	Rate	Cost
	MM	3min		
	DM	3hrs		
	AA	3hrs		
	JA	3hrs		

Parts	Part Description	Used / Ret#	GL#	Cost
	3/4" #91 compressor coupling	used-2	620.6	32.46
	3/4" Insert #89	used-4	333.4	5.03
	3/4" Tubing #333	used-2+	333.4	.46

Total Cost

Vehicle	Time	Rate	Cost
P-150	3hrs		
F-150	3hrs		

Bud Called 11-6-19 Conf. # 1911061392
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 104,000 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Total Cost

Equipment	Time	Rate	Cost
5H	3hrs		

Completed Date: 11-6-19 Completed Time: 5:30 By: Dylan

Service line

WORK ORDERS BY TYPE

08:27:41

CHECKLIST/TYPE: SRLK

WORK ORDER NO : 52414


SCHEDULED DATE: 11/15/19 SCHEDULED TIME: AM:

INSTRUCTIONS: SERVICE LINE LEAK FOR [REDACTED]

LEAK

METER LOCATION:

IN:



*****OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE:	5/8 in.	TY:	G	USE:	0	*	NEW METER INFORMATION*****	
MAKE SERIAL	REMOTE	MXUID	CURRENT	*	MAKE	SERIAL	REMOTE	MXUID
1:								
2:								
3:								
4:								

HISTORY: DATE CURRENT PREVIOUS USAGE PRIOR W/O DATE TYPE

*****SRLK

Arrival Date: 11-18-19 Arrival Time: 9:00

Labor Cost				Parts			
Employee	Time	Rate	Cost	Part Description	Used / Ret #	GL #	Cost
CC	5min			3/4" coupling #91	U-2	620.6	32.46
JC	2h			3/4" inserts #89	U-3	333.4	3.77
DH	2h			3/4" tubing #333	U-3+	333.4	0.68
Total Cost				Total Cost			
Vehicle	Time	Rate	Cost				
F-150	2h						
6	2h						
Total Cost							

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 250,000 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of interruption: _____
 Comments: _____

Service line leak

Completed Date: 11-18-19 Completed Time: 11:00 By: JC DH

WORK ORDERS BY TYPE

09:02:45

CHECKLIST/TY: MNLK
 SCHEDULED DATE: 12/02/19
 INSTRUCTIONS:

SCHEDULED TIME: AM:

WORK ORDER NO : 52575

LEC

METER LOCATION:

IN: *****



SIZE: 5/8 in. TY: G USE: 0
 MAKE SERIAL REMOTE MXUID CURRENT MAKE SERIAL REMOTE MXUID
 1:
 2:
 3:
 4:

***** REFER INFORMATION *****

HISTORY: DATE CURRENT PREVIOUS USAGE PRIOR W/O DATE TYPE

*****MNLK

Arrival Date: 11-21-19 Arrival Time: 7:30

Labor Cost				Parts			
Employee	Time	Rate	Cost	Part Description	Used / Ret#	GL#	Cost
MM	3min			3/4 Inserts #89	Used 5	333.4	6.29
DH	1hr			3/4 Comp Coupling #91	Used 2	620.6	32.46
TV	1hr			Tubing 3/4 #333	Used 12ft	333.4	4.22
JD	1hr			Repair Clamp #379 6x12" pvc	Used 1	320.6	111.02
AF	1hr						
JC	1hr						
Total Cost				Total Cost			

Vehicle	Time	Rate	Cost
ADA			
6	1hr		
ASD	1hr		
8	1hr		
4	1hr		
Total Cost			

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss 1,080,000 Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Equipment	Time	Rate	Cost
DH	1hr		
TRH	1hr		
Total Cost			

Will need Blacktop to be paved

Completed Date: 11-21-19 Completed Time: 4:30 By: JD DH JC AF

WORK ORDERS BY TYPE

16:03:29

CHECKLIST/TY: MISC
 SCHEDULED DATE: 10/03/19 SCHEDULED TIME: PM:
 INSTRUCTIONS: MOVE METER

WORK ORDER NO : 51892

METER LOCATION: 11' RIGHT OF TELEPHONE POLE 12' OF RD 3576 00

37.377139
 86.168671

IN: 12/03/10

*****OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE: 5/8 in. TY: G USE: 3 09/17 *
 MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
 1: 40356081 83011433 1279 A *
 2: *
 3: *
 4: *

***** HISTORY: *****

DATE	CURRENT	PREVIOUS	USAGE	PRIOR W/O	DATE	TYPE
09/17/19	1279	1276	3 A			
08/19/19	1276	1268	8 A			
07/17/19	1268	1255	13 A	26305	07/17/12	READ
06/17/19	1255	1251	4 A	15646	11/08/10	AMR
				13407	08/11/10	MISC

***** MISC *****

Arrival Date: 11/8/19 Arrival Time: 7:30

Labor Cost				Parts			
Employee	Time	Rate	Cost	Part Description	Used / Ret #	GL #	Cost
MFT	5mn	20.155	1.00775	3/4" tubing #333	used 116ft	333.4	26.39
JD	5hrs	25.1645	125.8225	3/4" Comp. Coupling #91	used 2	620.6	32.46
DB	5hrs	21.4317	107.1675	3/4" Flow Coupling #93	used 1	620.6	4.48
JC	2hrs	23.4147	46.8294	1 1/2 Casing pipe #439	used 21ft	333.4	71.43
				3/4" Inserts #89	used 2	333.4	2.52
Total Cost			297.31	Total Cost			137.28

Vehicle	Time	Rate	Cost
9683	1 1/2 hr	10.00	15.00
6	1 1/2 hr	10.00	15.00
Total Cost			30.00

Bud Called _____ Conf. # _____
 All Yes/No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____

total 604.59

Equipment	Time	Rate	Cost
TH	4hrs	35.00	140.00
Total Cost			140.00

Length of Interruption: _____
 Comments: Will need clean up

Completed Date: 11/8/19 Completed Time: 12:30 By: JD DB JC

WORK ORDERS BY TYPE

15:59:07

CHECKLIST/TYPE: MISC
SCHEDULED DATE: 05/27/16 SCHEDULED TIME: PM:
INSTRUCTIONS: REPLACE STEM IN HYDRANT

WORK ORDER NO : 39418
CANNON

METER LOCATION:

IN:

[Redacted] 2409
[Redacted]

OWNER : OWNER
O/ADDR :

COMPLETED:

*****OLD METER INFORMATION***** NEW METER INFORMATION*****

SIZE: 5/8 in. TY: G USE: 0 *
MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
1: *
2: *
3: *
4: *

HISTORY: DATE CURRENT PREVIOUS USAGE PRIOR W/O DATE TYPE

Arrival Date: 11-4-19 Arrival Time: 8:00
*****MISC
542-335-1 85114

Labor Cost			
Employee	Time	Rate	Cost
CH	3min		
JC	7hrs		
DH	7hrs		
Total Cost			

Parts				
Part Description	Used / Ret #	GL #	Cost	
Restrainer MJ4" PVC #257	U-6	6206	152.40	
4" pipe #497	U-12ft	6206	13.94	
4" coupling #397	U-1	6206	27.41	
tee Tee MJ4" #311	U-1	6206	56.31	
Valve Box lid #175	U-1	6206	5.66	
Total Cost				

Vehicle			
Vehicle	Time	Rate	Cost
F-150	7hrs		
Total Cost			

PH 2 1/4" x 3" Bury 4" MS Shoe - used - 1
 Bud Called 10-25-19 6206 Conf. # 1910250710
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

Equipment			
Equipment	Time	Rate	Cost
BH	7hrs		
Total Cost			

Got New Hydrant

Completed Date: 11-4-19 Completed Time: 4:00 By: JC DH

CHECKLIST/TYPE: ADJ
SCHEDULED DATE: 12/02/19 SCHEDULED TIME: PM:
INSTRUCTIONS: ADJUSTING CHANGE W/O FOR NOV. 2019

WORK ORDER NO : 52578

METER LOCATION:

IN:



***** NEW METER INFORMATION*****

SIZE: 5/8 in. TY: G USE: 0 *
MAKE SERIAL REMOTE MXUID CURRENT * MAKE SERIAL REMOTE MXUID
1: *
2: *
3: *
4: *

HISTORY: DATE CURRENT PREVIOUS USAGE PRIOR W/O DATE TYPE

***** ANGL

Arrival Date: _____ Arrival Time: _____

Labor Cost				Parts			
Employee	Time	Rate	Cost	Part Description	Used / Ret #	GL #	Cost
Total Cost				Total Cost			
Vehicle	Time	Rate	Cost				
Total Cost							
Equipment	Time	Rate	Cost				
Total Cost							

Bud Called _____ Conf. # _____
 Bill Yes or No / Miles _____ Adj. Bill Yes or No / GPM _____
 Est. loss _____ Gal. Flushed _____
 Cause Of Leak: _____ Time occurred: _____
 Length of Interruption: _____
 Comments: _____

① w/o failed to be made

[Redacted] [Redacted] [Redacted] [Redacted] [Redacted] [Redacted] [Redacted] [Redacted] [Redacted]

Rd Disburse 2

pt# 091

BRASS COMP 3/4" ✓

1

093

3/4" flow Coupler ✓

4

089

3/4" Stank's Insert ✓

② Failed to make w/o for [Redacted] [Redacted] [Redacted] [Redacted] ✓

make w/o
Nelson Sanders

218-00750-02

(318-00830-01)
~~218-00830-02~~

Waters and Sons see

[Redacted]

10 ✓

③ Failed to take 524 14 w/o ✓

(1) 093 #

3/4" in flow Coupler ✓

④ w/o 52561

Disburse wrong part ✓

Disburse # 441 cast iron lid (R) ✓

should have disburse 255 3/4 washer ✓

⑤ w/o 52174

Disburse

Part # 035

4" Saddle ✓

should have Disburse ✓

⑥ w/o 39148

033 3" saddle ✓

Disburse wrong part ⑤ 257 Restraint 4" R ✓

⑦ w/o 51840

⑤ 548 4" Restraint ✓

Disbursed 354 1 1/4 HDPE pipe # 1095 ✓

should of Disburse 75 ft 1 1/4 HDPE pipe 1095 ✓