

# Pole Attachment Violations

Nolin RECC System

# NESC Violation – Communication Above Neutral





# Ground Clearance Violation





# Pole is overloaded above NESC design limits



# Pending NJUNS ticket



Transfer considered complete by CATV.

Transfer not complete – Open NJUNS ticket



I-65 Crossing – New cable attached to existing midspan because of ground clearance issue




Transfer Needed – Pending NJUNS ticket





# I-65 Crossing – Missing down guy



Missing guy attachment and down guy

# NESC Violation

40" needed between communications and utility tpx. →



# Pole is overloaded above NESC design limits



Pole bowed at attachment



# Ground Clearance Violation







# Anchor Guy Issue



# Driveway Clearance



# Driveway Crossing





# Driveway Crossing











# Telecommunications Low





# Guying



# Property owner raised telecommunications





# Unlashed across crop field

